

Solid IT Networks
DIR-CPO-5404
Extreme Networks
Confidential Pricing for DIR Members

Note : Solid IT Networks cannot control external factors such as market conditions or unforeseen events (e.g., tariffs, trade disputes, pandemics, natural disasters, or force majeure) that may impact product pricing, lead times, and availability. All quoted prices are subject to change without prior notice. Additionally, stock availability is not guaranteed at the time of order placement.

For assistance with design, configuration, pricing, or inventory confirmation, please contact your Solid IT Networks sales representative or email us at sales@soliditnetworks.com.

| PRODUCT DESCRIPTION | PART NUMBER | MSRP | DISCOUNT % OFF MSRP | DIR CUSTOMER PRICE* |
|--|-------------|---------|---------------------|---------------------|
| PWR CORDEUR10ACEE7/7C13ST | 10033 | \$20.00 | 10% | \$18.14 |
| PWR CORDGBR10ABS1363C13ST | 10034 | \$21.00 | 10% | \$19.04 |
| PWR CORDZAF10ASANS164-1C13ST | 10035 | \$27.00 | 10% | \$24.48 |
| PWR CORDAUS10AAS 3112 3C13ST | 10036 | \$21.00 | 10% | \$19.04 |
| PWR CORDCHE10ASEV 1011C13ST | 10037 | \$18.00 | 10% | \$16.32 |
| PWR CORDITA10ACEI 23-50C13ST | 10038 | \$18.00 | 10% | \$16.32 |
| PWR CORDCHN10AGB2099C13ST | 10039 | \$18.00 | 10% | \$16.32 |
| PWR CORDNEMA10ANEMA 5-15PC13RA | 10041 | \$17.00 | 10% | \$15.41 |
| PWR CORDJPN12AJIS C 8303C13RA | 10042 | \$15.00 | 10% | \$13.60 |
| PWR CORDEUR10ACEE7/7C13RA | 10043 | \$17.00 | 10% | \$15.41 |
| PWR CORDGBR10ABS1363C13RA | 10044 | \$15.00 | 10% | \$13.60 |
| PWR CORDZAF10ASANS 164-1C13Right Angle | 10045 | \$15.00 | 10% | \$13.60 |

| | | | | |
|---|-------|----------|-----|-----------------|
| PWR CORDAUS10AAS/NZS4417C1 3RA | 10046 | \$15.00 | 10% | <i>\$13.60</i> |
| PWR CORDCHE10ASEV 1011C13RA | 10047 | \$15.00 | 10% | <i>\$13.60</i> |
| PWR CORDITA10ACEI 23- 50C13RA | 10048 | \$15.00 | 10% | <i>\$13.60</i> |
| PWR CORDCHN10AGB2099C13RA | 10049 | \$15.00 | 10% | <i>\$13.60</i> |
| PWR CORDNEMA10ANEMA 5-15PC13ST | 10061 | \$18.00 | 10% | <i>\$16.32</i> |
| PWR CORDJPN12AJIS C 8303C13ST | 10062 | \$26.00 | 10% | <i>\$23.58</i> |
| Mini-GBIC SFP 100FX MMF LC connector | 10063 | \$406.00 | 48% | <i>\$212.70</i> |
| 10/100/1000BASE-T SFP module CAT5 cable 100m link RJ45-connector for Giga Bit Ethernet SFP Port. | 10065 | \$543.00 | 48% | <i>\$284.48</i> |
| 100BASE-LX10 SFP module SMF 10km link LC-connector for Fast Ethernet SFP Port. | 10066 | \$406.00 | 48% | <i>\$212.70</i> |
| 100BASE-FX SFP module MMF 2km link LC-connector for Fast Ethernet SFP Port. I-temp | 10067 | \$206.00 | 48% | <i>\$107.92</i> |
| PWR CORDNEMA16ANEMA 6-20PC19ST | 10080 | \$25.00 | 10% | <i>\$22.67</i> |
| PWR CORDEUR16ACEE7/7C19ST | 10081 | \$17.00 | 10% | <i>\$15.41</i> |
| PWR CORDAUS15AAS 3112 3C19ST | 10084 | \$17.00 | 10% | <i>\$15.41</i> |
| PWR CORDGBR13ABS1363C19ST | 10087 | \$17.00 | 10% | <i>\$15.41</i> |
| PWR CORDNEMA10ANEMA L6-15PC13RA | 10088 | \$32.00 | 10% | <i>\$29.02</i> |
| PWR CORDAUS10AAS 3112 3C15ST | 10089 | \$38.00 | 10% | <i>\$34.46</i> |
| PWR CORDCHN10AGB2099C15ST | 10090 | \$30.00 | 10% | <i>\$27.20</i> |
| PWR CORDZAF10ASANS164- 1C15ST | 10092 | \$38.00 | 10% | <i>\$34.46</i> |

| | | | | |
|---------------------------------------|-------|----------|-----|----------|
| PWR CORDDNK10AAFSNIT 107-2-D1C15ST | 10093 | \$30.00 | 10% | \$27.20 |
| PWR CORDEUR10ACEE7/7C15ST | 10094 | \$35.00 | 10% | \$31.74 |
| PWR CORDBRA10ANBR14136C15S T | 10095 | \$38.00 | 10% | \$34.46 |
| PWR CORDGBR10ABS1363C15ST | 10096 | \$38.00 | 10% | \$34.46 |
| PWR CORDCHE10ASEV 1011C15ST | 10097 | \$38.00 | 10% | \$34.46 |
| PWR CORDJPN12AJIS C 8303C15ST | 10098 | \$38.00 | 10% | \$34.46 |
| PWR CORDNEMA15ANEMA 5-15PC15ST | 10099 | \$38.00 | 10% | \$34.46 |
| PWR CORDNEMA15AC14C15ST | 10100 | \$38.00 | 10% | \$34.46 |
| PWR CORDBRA10ANBR14136C13S T | 10102 | \$32.00 | 10% | \$29.02 |
| PWR CORDIND10AIS1293C13ST | 10103 | \$45.00 | 10% | \$40.80 |
| PWR CORDIND10AIS1293C15ST | 10104 | \$75.00 | 10% | \$68.01 |
| PWR CORDITA10ACEI 23- 50C15ST | 10105 | \$55.00 | 10% | \$49.87 |
| PWR CORDNEMA10AC14C13ST | 10106 | \$55.00 | 10% | \$49.87 |
| PWR CORDNEMA15ANEMA 6-15PC15ST | 10109 | \$60.00 | 10% | \$54.41 |
| PWR CORDNEMA15ANEMA 6-15PC19ST | 10117 | \$60.00 | 10% | \$54.41 |
| PWR CORDNEMA15ANEMA L6-15PC15ST | 10118 | \$125.00 | 10% | \$113.34 |
| PWR CORDCHN16AGB2099C19ST | 10119 | \$75.00 | 10% | \$68.01 |
| PWR CORDISR16ASI- 32C19ST | 10120 | \$150.00 | 10% | \$136.01 |
| PWR CORDITA16ACEI 23- 50C19ST | 10126 | \$60.00 | 10% | \$54.41 |
| PWR CORDZAF16ASANS164- 1C19ST | 10127 | \$75.00 | 10% | \$68.01 |

| | | | | |
|--|-------|------------|-----|------------|
| PWR CORDBRA16ANBR14136C19S T | 10128 | \$75.00 | 10% | \$68.01 |
| PWR CORDINTL16AC20C19ST | 10129 | \$125.00 | 10% | \$113.34 |
| PWR CORDNEMA20ANEMA 5-20PC19ST | 10134 | \$75.00 | 10% | \$68.01 |
| Power Cord 12A/250V 2.5M Jumper (International) IEC-60320- C13 to IEC-60320-C14 Right Angle | 10136 | \$60.00 | 10% | \$54.41 |
| PWR CORDNEMA15ANEMA 6-15PC13ST | 10137 | \$55.00 | 10% | \$49.87 |
| PWR CORDNEMA13ANEMA 5-15PC13ST | 10138 | \$25.00 | 10% | \$22.67 |
| PWR CORDNEMA20ANEMA L6-20PC19ST | 10139 | \$125.00 | 10% | \$113.34 |
| PWR CORDISR10ASI- 32C15ST | 10140 | \$150.00 | 10% | \$136.01 |
| PWR CORDARG10AIRAM 2073C15ST | 10141 | \$32.00 | 10% | \$29.02 |
| PWR CORDNEMA15ANEMA 5-15PC13RA | 10142 | \$55.00 | 10% | \$49.87 |
| 10 Gigabit Ethernet SFP+ module 850nm MMF 26-300m link LC connector | 10301 | \$1,642.00 | 48% | \$860.24 |
| 10 Gigabit Ethernet SFP+ module 1310nm SMF 10km link LC connector | 10302 | \$2,739.00 | 48% | \$1,434.96 |
| LRM SFP+ Module0 Gigabit Ethernet SFP+ module 1310nm MMF 220m link LC connector | 10303 | \$2,405.00 | 48% | \$1,259.98 |
| 10 Gigabit Ethernet SFP+ passive cable assembly 1m length. | 10304 | \$182.00 | 48% | \$95.35 |
| 10 Gigabit Ethernet SFP+ passive cable assembly 3m length. | 10305 | \$250.00 | 48% | \$130.98 |
| 10 Gigabit Ethernet SFP+ passive cable assembly 5m length. | 10306 | \$302.00 | 48% | \$158.22 |

| | | | | |
|---|-------|-------------|-----|-------------|
| 10 Gigabit Ethernet SFP+ passive cable assembly 10m length. | 10307 | \$363.00 | 48% | \$190.18 |
| 10 Gigabit Ethernet SFP+ module 1550nm SMF 40km link LC connector | 10309 | \$8,234.00 | 48% | \$4,313.79 |
| 10 Gigabit Ethernet SFP+ module 1550nm SMF 80km LC connector | 10310 | \$17,846.00 | 48% | \$9,349.52 |
| 40 Gigabit Ethernet QSFP+ passive copper cable assembly 0.5m length. | 10311 | \$382.00 | 48% | \$200.13 |
| QSFP+ (4X10GBASE) breakout optical module MPO connector 10km SMF link length | 10326 | \$9,372.00 | 48% | \$4,909.99 |
| MPO to 4 x LC breakout patch cable Single-Mode 10m | 10327 | \$2,870.00 | 48% | \$1,503.59 |
| ExtremeXOS 3rd Party Optics (40ExtremeXOS 3rd Party Optics (40G and 100G) Feature-Pack for X460-G2 X480 | 10328 | \$2,275.00 | 48% | \$1,191.87 |
| 40Gb Bidirectional MMF 100m OM3 QSFP+ LC | 10329 | \$3,611.00 | 48% | \$1,891.80 |
| MPO to 4xLC breakout patch cable OM4 MMF 5m | 10332 | \$1,957.00 | 10% | \$1,774.51 |
| 40Gb LM4 140m OM3 MMF 1Km SMF QSFP+ LC | 10334 | \$7,095.00 | 48% | \$3,717.07 |
| 40Gb ER4 40Km SMF QSFP+ LC | 10335 | \$40,188.00 | 48% | \$21,054.49 |
| 10Gb SFP+ 10GBASE-T RJ45 30m with Cat6a | 10338 | \$2,059.00 | 48% | \$1,078.71 |
| MPO to MPO Patch cable 12 fiber pinless MPO/MTP connectors OM3 MMF Type B 3m | 10345 | \$719.00 | 10% | \$651.95 |
| MPO to MPO Patch cable 12 fiber pinless MPO/MTP connectors OM3 MMF Type B 100m | 10346 | \$3,777.00 | 10% | \$3,424.79 |
| 100Gb PSM4 2km SMF QSFP28 MPO | 10405 | \$4,013.00 | 48% | \$2,102.41 |
| 100Gb QSFP28-QSFP28 Active optical cable 5m | 10434 | \$6,030.00 | 48% | \$3,159.12 |

| | | | | |
|--|-------|-------------|-----|------------|
| 100Gb QSFP28-QSFP28 Active optical cable 20m | 10437 | \$7,368.00 | 48% | \$3,860.10 |
| 100Gb QSFP28- 4xSFP28 (4x25Gb) Active optical breakout cable 10m | 10443 | \$15,408.00 | 48% | \$8,072.25 |
| 100Gb QSFP28- 4xSFP28 (4x25Gb) Active optical breakout cable 20m | 10444 | \$16,747.00 | 48% | \$8,773.75 |
| 25Gb SFP28 25GBASE-SR 70m OM3 / 100m OM4 MMF LC | 10501 | \$1,246.00 | 48% | \$652.78 |
| 25Gb SR Lite-FEC 50m OM3 / 70m OM4 RS-FEC 70m OM3 / 100m OM4 MMF LC | 10502 | \$1,940.00 | 10% | \$1,759.10 |
| 25Gb SFP28 ESR extended range 200m OM3 / 300m OM4 MMF LC | 10503 | \$2,498.00 | 48% | \$1,308.70 |
| QSFP28 - SFP28 Slot Adapter | 10506 | \$820.00 | 48% | \$429.60 |
| 25Gb SFP28-SFP28 Passive Copper Direct Attach Cable 5m | 10522 | \$620.00 | 10% | \$562.19 |
| External PoE+ Redundant Power Supply Unit 500 Watts with cable Power cord ordered separately | 10923 | \$1,526.00 | 48% | \$799.47 |
| 550W AC Power Supply module for Summit switches Front-to-Back airflow for X670 X670-V2 | 10925 | \$932.00 | 48% | \$488.27 |
| 550W DC Power Supply module for Summit switches Front-to-Back airflow for X670 X670-V2 | 10926 | \$1,246.00 | 48% | \$652.78 |
| 550W AC Power Supply module for Summit switches Back-to-Front airflow for X670 X670-V2 | 10927 | \$932.00 | 48% | \$488.27 |
| 550W DC Power Supply module for Summit switches Back-to-Front airflow for X670 X670-V2 | 10928 | \$1,246.00 | 48% | \$652.78 |
| 750W PoE AC Power Supply Module | 10931 | \$1,487.00 | 48% | \$779.04 |

| | | | | |
|--|-------|------------|-----|-----------------|
| External Redundant Power Supply Unit 150 Watts with cable- Extended Temparture Range from 0 to +60 degrees Celsius Power cord ordered separately | 10932 | \$945.00 | 48% | <i>\$495.09</i> |
| 300W +24V / -48V DC Power Supply Module for the X460 and the E4G-400 platforms | 10933 | \$1,188.00 | 48% | <i>\$622.39</i> |
| External Power System Chassis 2. Accepts up to three Summit 750W AC PoE PSU 48V power supplies. Accepts up to 5 EPS-CBL-2x7 or up to 1 EPS-CBL-2x9 cables. | 10936 | \$1,504.00 | 48% | <i>\$787.95</i> |
| External Power System Cable (1M with 2x7 pin) that connects EPS to any Summit X440 or X450-G2 for providing redundant power | 10939 | \$152.00 | 48% | <i>\$79.63</i> |
| 1100 Watt AC PoE Power Supply module with Front-to-Back airflow for Summit X465 X450-G2 X460-G2 VSP4900 5520 | 10941 | \$1,695.00 | 48% | <i>\$888.01</i> |
| 1100W AC Power Supply Module - back to front airflow | 10942 | \$1,636.00 | 48% | <i>\$857.10</i> |
| 300W AC Power Supply Module- back to front airflow | 10943 | \$739.00 | 48% | <i>\$387.16</i> |
| 300W DC Power Supply Module- back to front airflow | 10944 | \$1,188.00 | 48% | <i>\$622.39</i> |
| Fan Module for Summit X460-G2/X450-G2 Series Switches - front to back airflow | 10945 | \$440.00 | 48% | <i>\$230.52</i> |
| FAN Module for Summit X460-G2 Series Switches - back to front airflow | 10946 | \$440.00 | 48% | <i>\$230.52</i> |
| Power dongle for converting an IEC C5 plug to IEC C14 plug | 10947 | \$16.00 | 48% | <i>\$8.38</i> |
| 715W AC PoE Power Supply Module with front to back airflow for Summit X465 X450-G2 X460-G2 VSP4900 5520 | 10951 | \$1,345.00 | 48% | <i>\$704.65</i> |

| | | | | |
|---|-------|------------|-----|-------------------|
| 715W AC Power Supply Module back to front airflow | 10952 | \$1,337.00 | 48% | <i>\$700.45</i> |
| 350W AC Power Supply Module front to back airflow for Summit X465 X450-G2 X460-G2 VSP4900 5520 | 10953 | \$995.00 | 48% | <i>\$521.28</i> |
| 350W AC Power Supply Module back to front airflow | 10954 | \$972.00 | 48% | <i>\$509.23</i> |
| External converter for the international market that can use a CEE 7/1 plug to connect up to 4 half duplex devices to 4 full duplex switch ports. Does NOT support PoE pass through. External power supply and cord with CEE 7/1 plug included. | 10958 | \$187.00 | 48% | <i>\$97.97</i> |
| External converter for the North American market to connect up to four half duplex devices to four full duplex switch ports. Does NOT support PoE pass through. External power supply and cord with NEMA 1 15P plug included. | 10959 | \$187.00 | 48% | <i>\$97.97</i> |
| 770W AC power supply Front-to-Back airflow for X590 X690 X870 | 10960 | \$785.00 | 48% | <i>\$411.26</i> |
| 770W AC power supply Back-to-Front airflow for X590 X690 X870 | 10961 | \$785.00 | 48% | <i>\$411.26</i> |
| 1100W DC power supply Front-to-Back airflow for X590 X690 X870 | 10962 | \$1,265.00 | 48% | <i>\$662.73</i> |
| 1100W DC power supply Back-to-Front airflow for X590 X690 X870 | 10963 | \$1,265.00 | 48% | <i>\$662.73</i> |
| ExtremeSwitching LRM/MACsec Adapter two SFP+ network ports (unpopulated) and two host cables with integrated SFP/SFP+ transceivers for host switch connection | 10965 | \$1,970.00 | 48% | <i>\$1,032.08</i> |

| | | | | |
|--|-------|------------|-----|------------|
| Direct Attach Feature Pack for Summit X450a/X460/X460-G2/X480 X650 X670/X670-G2 X770 and BlackDiamond 8800 X Series | 11011 | \$1,031.00 | 48% | \$540.14 |
| SummitStack Stacking cable 5.0M (not supported for UniStack) | 16105 | \$748.00 | 48% | \$391.88 |
| SummitStack/UniStack Stacking cable 0.5M | 16106 | \$295.00 | 48% | \$154.55 |
| SummitStack/UniStack Stacking cable 1.5M | 16107 | \$446.00 | 48% | \$233.66 |
| SummitStack/UniStack Stacking cable 3.0M | 16108 | \$599.00 | 48% | \$313.82 |
| ExtremeXOS Audio Video Bridging Feature Pack for Summit X450-G2 series switches | 16169 | \$513.00 | 48% | \$268.76 |
| Summit X450-G2 24 10/100/1000BASE-T 4 1000BASE-X unpopulated SFP two 21Gb stacking ports 1 Fixed AC PSU 1 RPS port fan module slot (unpopulated) ExtremeXOS Edge license | 16172 | \$4,473.00 | 48% | \$2,343.40 |
| Summit X450-G2 24 10/100/1000BASE-T POE+ 4 1000BASE-X unpopulated SFP two 21Gb stacking ports 2 unpopulated power supply slots fan module slot (unpopulated) ExtremeXOS Edge license | 16173 | \$4,324.00 | 48% | \$2,265.34 |
| Summit X450-G2 48 10/100/1000BASE-T 4 1000BASE-X unpopulated SFP two 21Gb stacking ports (QSFP) 1 Fixed AC PSU 1 RPS port fan module slot (unpopulated) ExtremeXOS Edge license w Policy | 16174 | \$7,312.00 | 48% | \$3,830.76 |

| | | | | |
|---|-------|------------|-----|-------------------|
| Summit X450-G2 48 10/100/1000BASE-T POE+ 4 1000BASE-X unpopulated SFP two 21Gb stacking ports 2 unpopulated power supply slots fan module slot (unpopulated) ExtremeXOS Edge license | 16175 | \$7,611.00 | 48% | <i>\$3,987.40</i> |
| Summit X450-G2 24 10/100/1000BASE-T 4 10GBASE-X unpopulated SFP+ two 21Gb stacking ports 1 Fixed AC PSU 1 RPS port fan module slot (unpopulated) ExtremeXOS Edge license | 16176 | \$6,714.00 | 48% | <i>\$3,517.46</i> |
| Summit X450-G2 24 10/100/1000BASE-T POE+ 4 10GBASE-X unpopulated SFP+ two 21Gb stacking ports) 2 unpopulated power supply slots fan module slot (unpopulated) ExtremeXOS Edge license | 16177 | \$5,817.00 | 48% | <i>\$3,047.53</i> |
| Summit X450-G2 48 10/100/1000BASE-T 4 10GBASE-X unpopulated SFP+ two 21Gb stacking ports 1 Fixed AC PSU 1 RPS port fan module slot (unpopulated) ExtremeXOS Edge license | 16178 | \$9,701.00 | 48% | <i>\$5,082.35</i> |
| Summit X450-G2 48 10/100/1000BASE-T POE+ 4 10GBASE-X unpopulated SFP+ two 21Gb stacking ports 2 unpopulated power supply slots fan module slot (unpopulated) ExtremeXOS Edge license | 16179 | \$9,851.00 | 48% | <i>\$5,160.94</i> |
| ExtremeXOS Advanced Edge License upgrade for Summit X450-G2 series switches | 16190 | \$1,031.00 | 48% | <i>\$540.14</i> |
| ExtremeXOS Advanced Core License upgrade from Edge License for ExtremeSwitching X450-G2 series switches | 16191 | \$2,587.00 | 48% | <i>\$1,355.33</i> |

| | | | | |
|---|-------|------------|-----|------------|
| ExtremeXOS Advanced Core License upgrade from Advanced Edge License for ExtremeSwitching X450-G2 series switches | 16192 | \$1,695.00 | 48% | \$888.01 |
| ExtremeXOS Advanced Edge License for Summit X460 X460-G2 Series Switches | 16421 | \$1,031.00 | 48% | \$540.14 |
| ExtremeXOS Advanced Core License upgrade from Edge License for Summit X460 X460-G2 Series Switches | 16422 | \$3,105.00 | 48% | \$1,626.71 |
| ExtremeXOS Advanced Core License upgrade from Advanced Edge License for Summit X460 X460-G2 series switches | 16423 | \$2,068.00 | 48% | \$1,083.43 |
| ExtremeXOS MPLS Feature Pack for Summit X460 X460-G2 Series Switches | 16424 | \$2,068.00 | 48% | \$1,083.43 |
| ExtremeXOS Audio Video Bridging Feature Pack for Summit X460 X460-G2 series switches | 16426 | \$1,031.00 | 48% | \$540.14 |
| ExtremeXOS Advanced Edge License for Summit X440 series switches | 16521 | \$995.00 | 48% | \$521.28 |
| ExtremeXOS Audio Video Bridging Feature Pack for Summit X440 series switches | 16523 | \$495.00 | 48% | \$259.33 |
| X440-G2 12 10/100/1000BASE-T 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license | 16530 | \$2,536.00 | 48% | \$1,328.61 |
| X440-G2 12 10/100/1000BASE-T POE+ 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license | 16531 | \$3,488.00 | 48% | \$1,827.36 |

| | | | | |
|---|-------|------------|-----|-------------------|
| X440-G2 24 10/100/1000BASE-T 4 SFP combo 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license | 16532 | \$3,488.00 | 48% | <i>\$1,827.36</i> |
| X440-G2 24 10/100/1000BASE-T POE+ 4 SFP combo 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license | 16533 | \$4,919.00 | 48% | <i>\$2,577.06</i> |
| X440-G2-48t-10GE4 long description X440-G2 48 10/100/1000BASE-T 4 SFP combo 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ (2 combo/2 non-combo) 2 1GbE copper combo upgradable to 10GbE 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license | 16534 | \$5,237.00 | 48% | <i>\$2,743.66</i> |
| X440-G2 48 10/100/1000BASE-T POE+ 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ (2 combo/2 non-combo) 2 1GbE copper combo upgradable to 10GbE 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license | 16535 | \$7,781.00 | 48% | <i>\$4,076.47</i> |
| X440-G2 24 10/100/1000BASE-T 4 SFP combo 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ 1 Fixed DC PSU 1 RPS port ExtremeXOS Edge license | 16536 | \$3,966.00 | 48% | <i>\$2,077.79</i> |
| X440-G2 48 10/100/1000BASE-T 4 SFP combo 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ (2 combo/2 non-combo) 2 1GbE copper combo upgradable to 10GbE 1 Fixed DC PSU 1 RPS port ExtremeXOS Edge license | 16537 | \$5,397.00 | 48% | <i>\$2,827.49</i> |

| | | | | |
|---|-------|------------|-----|-------------------|
| X440-G2 12 10/100/1000BASE-T plus 8 fixed 100BASE-FX LC connectors 4 1GBASE-X unpopulated SFP 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license 0C to 60C operation | 16540 | \$6,033.00 | 48% | <i>\$3,160.69</i> |
| License that converts the two non-stack 1GbE SFP ports to be 10GbE SFP+ | 16542 | \$777.00 | 48% | <i>\$407.07</i> |
| License that converts four 1GbE SFP ports to be 10GbE SFP+ | 16543 | \$1,555.00 | 48% | <i>\$814.66</i> |
| License that upgrades an already licensed Dual 10GbE switch to a Quad 10GbE switch | 16546 | \$777.00 | 48% | <i>\$407.07</i> |
| 220-Series 12 port 10/100/1000BASE-T PoE+ 2 10GbE unpopulated SFP+ ports 1 Fixed AC PSU L2 Switching with RIP and Static Routes 1 country-specific power cord | 16561 | \$1,560.00 | 48% | <i>\$817.28</i> |
| 220-Series 24 port 10/100/1000BASE-T 2 10GbE unpopulated SFP+ ports 1 Fixed AC PSU 1 RPS port L2 Switching with RIP and Static Routes 1 country-specific power cord | 16562 | \$1,958.00 | 48% | <i>\$1,025.80</i> |
| 220-Series 24 port 10/100/1000BASE-T PoE+ 2 10GbE unpopulated SFP+ ports 1 Fixed AC PSU 1 RPS port L2 Switching with RIP and Static Routes 1 country-specific power cord | 16563 | \$2,585.00 | 48% | <i>\$1,354.28</i> |
| 220-Series 48 port 10/100/1000BASE-T 4 10GbE unpopulated SFP+ ports (2 LRM Capable) 1 Fixed AC PSU 1 RPS port L2 Switching with RIP and Static Routes 1 country-specific power cord | 16564 | \$3,125.00 | 48% | <i>\$1,637.19</i> |

| | | | | |
|--|-------|------------|-----|-------------------|
| 220-Series 48 port 10/100/1000BASE-T PoE+ 4 10GbE unpopulated SFP+ ports (2 LRM Capable) 1 Fixed AC PSU 1 RPS port L2 Switching with RIP and Static Routes 1 country-specific power cord | 16565 | \$4,691.00 | 48% | <i>\$2,457.61</i> |
| 210-Series 12 port 10/100/1000BASE-T 2 1GbE unpopulated SFP ports 1 Fixed AC PSU L2 Switching with Static Routes 1 country-specific power cord | 16566 | \$775.00 | 48% | <i>\$406.02</i> |
| 210-Series 12 port 10/100/1000BASE-T PoE+ 2 1GbE unpopulated SFP ports 1 Fixed AC PSU L2 Switching with Static Routes 1 country- specific power cord | 16567 | \$1,324.00 | 48% | <i>\$693.64</i> |
| 210-Series 24 port 10/100/1000BASE-T 2 1GbE unpopulated SFP ports 1 Fixed AC PSU L2 Switching with Static Routes 1 country-specific power cord | 16568 | \$1,169.00 | 48% | <i>\$612.44</i> |
| 210-Series 24 port 10/100/1000BASE-T PoE+ 2 1GbE unpopulated SFP ports 1 Fixed AC PSU L2 Switching with Static Routes 1 country- specific power cord | 16569 | \$1,716.00 | 48% | <i>\$899.01</i> |
| 210-Series 48 port 10/100/1000BASE-T 4 1GbE unpopulated SFP ports 1 Fixed AC PSU L2 Switching with Static Routes 1 country-specific power cord | 16570 | \$1,872.00 | 48% | <i>\$980.74</i> |
| 210-Series 48 port 10/100/1000BASE-T PoE+ 4 1GbE unpopulated SFP ports 1 Fixed AC PSU L2 Switching with Static Routes 1 country- specific power cord | 16571 | \$2,969.00 | 48% | <i>\$1,555.46</i> |

| | | | | |
|--|-------|-------------|-----|-------------------|
| Rack Mount Kit to mount dual compact form factor device side-by-side in 1RU space. For use with X435-8P-2T-W RPS-150W-XT 12 port 200-Series switches (210 and/or 220) | 16572 | \$126.00 | 48% | <i>\$66.01</i> |
| Hardware kit for wall mounting 12 port 4220 series switch 12 port 200-Series switch (either 210 or 220) or an 8 port X435 series switch | 16573 | \$54.00 | 48% | <i>\$28.29</i> |
| Summit X460-G2 24 10/100/1000BASE-T 8 100/1000BASE-X unpop SFP (4 SFP ports shared) 4 1000/10GBaseX unpop SFP+ ports Rear VIM Slot Rear Timing Slot 2 PSU slots fan module slot ExtremeXOS Adv Edge lic with EXOS min Rel 22.1 | 16701 | \$7,767.00 | 48% | <i>\$4,069.13</i> |
| Summit X460-G2 48 10/100/1000BASE-T 4 1000/10GBaseX unpopd SFP+ ports Rear VIM Slot (unpopd) Rear Timing Slot (unpopd) 2 unpopd PSU slots fan module slot (unpopd) ExtremeXOS Advanced Edge license with EXOS Release 22.1 or greater | 16702 | \$11,502.00 | 48% | <i>\$6,025.90</i> |
| Summit X460-G2 24 10/100/1000BASE-T PoE+ 8 100/1000BASE-X unpop SFP (4 SFP ports shared) 4 1000/10GBaseX unpop SFP+ ports Rear VIM Slot Rear Timing Slot 2 PSU slots fan module slot ExtremeXOS Adv Edge lic with EXOS min Rel 22.1 | 16703 | \$8,216.00 | 48% | <i>\$4,304.36</i> |

| | | | | |
|---|-------|-------------|-----|------------|
| Summit X460-G2 48 10/100/1000BASE-T PoE+ 4 1000/10GBaseX unpopd SFP+ ports Rear VIM Slot (unpopd) Rear Timing Slot (unpopd) 2 unpopd PSU slots fan module slot (unpopd) ExtremeXOS Advanced Edge license with EXOS Release 22.1 or greater | 16704 | \$12,098.00 | 48% | \$6,338.14 |
| Summit X460-G2 48 100/1000BASE-X unpopd SFP 4 1000/10GBaseX unpopd SFP+ ports Rear VIM Slot (unpopd) Rear Timing Slot (unpopd) 2 unpopd PSU slots fan module slot (unpopd) ExtremeXOS Advanced Edge license with EXOS Release 22.1 or greater | 16706 | \$15,981.00 | 48% | \$8,372.45 |
| Optional Virtual Interface Module for the rear of the X460-G2 providing 2 40GBASE-X ports unpopulated QSFP+ | 16710 | \$3,727.00 | 48% | \$1,952.58 |
| Optional Virtual Interface Module for the rear of the X460-G2 providing 2 10GBASE-X ports unpopulated SFP+ | 16711 | \$1,487.00 | 48% | \$779.04 |
| Optional Virtual Interface Module for the rear of the X460-G2 providing 2 10GBASE-T ports | 16712 | \$2,085.00 | 48% | \$1,092.33 |
| Optional Virtual Interface Module for the rear of the X460-G2 providing 2 ports of Extremes SummitStack | 16713 | \$889.00 | 48% | \$465.75 |
| Modular Grounding Lug Card for the X460-G2 that utilizes the Timing Module slot (note that adding the grounding lug excludes use of the 16715 Timing Module) | 16714 | \$73.00 | 48% | \$38.24 |

| | | | | |
|--|-------|------------|-----|-------------------|
| Optional Timing Module for the rear of the X460-G2 providing the hardware for SyncE and 1588 PTP clocking with 2 ports of mini-BNC connectors for clocking outputs | 16715 | \$1,451.00 | 48% | <i>\$760.18</i> |
| Summit X460-G2 24 10/100/1000BASE-T 8 100/1000BASE-X unpop SFP (4 SFP ports shared) 4 1GBASE-X unpop SFP Rear VIM Slot Rear Timing Slot 2 PSU slots fan module slot ExtremeXOS Adv Edge license with EXOS min Release 22.1 | 16716 | \$5,535.00 | 48% | <i>\$2,899.79</i> |
| Summit X460-G2 48 10/100/1000BASE-T 4 1GBASE-X unpopd SFP Rear VIM Slot (unpopd) Rear Timing Slot (unpopd) 2 unpopd PSU slots fan module slot (unpopd) ExtremeXOS Advanced Edge license with EXOS Release 22.1 or greater | 16717 | \$9,269.00 | 48% | <i>\$4,856.03</i> |
| Summit X460-G2 48 10/100/1000BASE-T PoE+ 4 1GBASE-X unpopd SFP Rear VIM Slot (unpopd) Rear Timing Slot (unpopd) 2 unpopd PSU slots fan module slot (unpopd) ExtremeXOS Advanced Edge license with EXOS Release 22.1 or greater | 16719 | \$9,866.00 | 48% | <i>\$5,168.80</i> |
| ExtremeXOS Network Timing Feature Pack for Summit X460-G2 that enables 1588v2 PTP (Precision Time Protocol) Boundary Clock | 16755 | \$1,031.00 | 48% | <i>\$540.14</i> |

| | | | | |
|--|-------|-------------|-----|-------------------|
| X460-G2 24 10/100/1000BASE-T full duplex PoE+ 24 10/100/1000BASE-T full/half duplex PoE+ 4 1000/10GBaseX unpopd SFP+ ports Rear VIM Slot (unpopd) Rear Timing Slot (unpopd) 2 unpopd PSU slots fan module slot (unpopd) ExtremeXOS Advanced Edge | 16756 | \$13,176.00 | 48% | <i>\$6,902.91</i> |
| X460-G2 24 10/100/1000BASE-T full duplex 24 10/100/1000BASE-T full/half duplex 4 1000/10GBaseX unpopd SFP+ ports Rear VIM Slot (unpopd) Rear Timing Slot (unpopd) 2 unpopd PSU slots fan module slot (unpopd) ExtremeXOS Advanced Edge | 16757 | \$12,546.00 | 48% | <i>\$6,572.85</i> |
| Adapter kit for adding rear rails to enable four post mounting of X460-G2 and Summit 17 or deeper switches | 16776 | \$103.00 | 48% | <i>\$53.96</i> |
| Four Piece Rack Mount Kit - Spare. Compatible with X450-G2 X460-G2 X620 (16 port models) X670 X670V X670- G2 X690 X770 X870 | 16777 | \$160.00 | 48% | <i>\$83.82</i> |
| ExtremeSwitching X440-G2 EXOS MACsec Feature Pack. Enables MACsec for use with ExtremeSwitching LRM/MACsec Adapter | 16778 | \$513.00 | 48% | <i>\$268.76</i> |
| ExtremeSwitching X450-G2 EXOS MACsec Feature Pack. Enables MACsec for use with ExtremeSwitching LRM/MACsec Adapter | 16779 | \$513.00 | 48% | <i>\$268.76</i> |

| | | | | |
|--|-------|-------------|-----|-------------|
| ExtremeSwitching X460-G2 EXOS MACsec Feature Pack. Enables MACsec for use with X460-G2-24p-24hp-10GE4 X460-G2-24t-24ht-10GE4 models or ExtremeSwitching LRM/MACsec Adapter | 16780 | \$513.00 | 48% | \$268.76 |
| ExtremeSwitching X590 base unit with 24 1Gb/10Gb SFP+ ports 1 10Gb/40Gb QSFP+ port 2 10Gb/25Gb/40Gb/50Gb/100Gb capable QSFP28 ports 2 unpopulated power supplies slots 4 unpopulated fan module slots ExtremeXOS Advanced Edge License | 16790 | \$16,057.00 | 48% | \$8,412.26 |
| ExtremeSwitching X590 base unit with 24 100Mb/1Gb/10GBASE-T ports 1 10Gb/40Gb QSFP+ port 2 10Gb/25Gb/40Gb/50Gb/100Gb capable QSFP28 ports 2 unpopulated power supplies slots 4 unpopulated fan module slots ExtremeXOS Advanced Edge License | 16791 | \$21,147.00 | 48% | \$11,078.91 |
| ExtremeSwitching X590 ExtremeXOS Core license upgrade from Advanced Edge | 16795 | \$2,592.00 | 48% | \$1,357.95 |
| 4-port POE+ 10/100 2-Port 10/100 w/ 2-port SFP Operating Temperature -40C - +75C | 16801 | \$2,265.00 | 48% | \$1,186.63 |
| 8-port POE+ 10/100 w/ 4-port SFP Operating Temperature -40C +75C | 16802 | \$2,568.00 | 48% | \$1,345.38 |
| 4-port POE+ Gigabit 2-port Gigabit w/ 2-port SFP Operating Temperature -40C - +75C | 16803 | \$2,718.00 | 48% | \$1,423.96 |
| 8-port POE+ Gigabit w/ 4-port SFP Operating Temperature -40C +75C | 16804 | \$3,323.00 | 48% | \$1,740.92 |

| | | | | |
|--|-------|------------|-----|------------|
| 24VDC GbE PoE injector with 60/75W output Operating Temperature -40C - +75C | 16805 | \$696.00 | 48% | \$364.63 |
| 24VDC GbE PoE injector with 30W output Operating Temperature -40C - +75C | 16806 | \$754.00 | 48% | \$395.02 |
| IS AC-DC Power Supply 240W Output DIN Rail -25 - 70C | 16807 | \$680.00 | 48% | \$356.25 |
| IS AC-DC Power Supply 480W Output DIN Rail -25 - 70C | 16920 | \$1,295.00 | 48% | \$678.45 |
| Conversion cable for SummitStack256 and SummitStack128 1.0M | 17026 | \$870.00 | 48% | \$455.79 |
| SummitStack128 Stacking Cable 1.0M | 17030 | \$674.00 | 48% | \$353.11 |
| Conversion cable for SummitStack128 and SummitStack 1.0M | 17038 | \$674.00 | 48% | \$353.11 |
| Fan module for Summit X670 series switches Front-to-Back airflow spare for X670 X670-V2 | 17111 | \$775.00 | 48% | \$406.02 |
| Fan module for Summit X670 series switches Back-to-Front airflow spare for X670 X670-V2 | 17112 | \$775.00 | 48% | \$406.02 |
| X870 X690 X590 5520 Fan Module Front-to-back airflow | 17115 | \$373.00 | 48% | \$195.41 |
| X870 X690 X590 5520 Fan Module Back-to-Front airflow | 17116 | \$373.00 | 48% | \$195.41 |
| VIM3-40G4X 4 40GBASE-X QSFP+ ports module for Summit X650/X480 | 17121 | \$7,246.00 | 48% | \$3,796.18 |
| ExtremeXOS Core License Summit X670 Series | 17131 | \$6,216.00 | 48% | \$3,256.56 |
| ExtremeXOS MPLS Feature Pack License for X670/X670-G2/X690/X695 series switches | 17133 | \$4,142.00 | 48% | \$2,169.99 |
| ExtremeXOS Audio Video Bridging Feature Pack for Summit X670 series switches | 17135 | \$3,105.00 | 48% | \$1,626.71 |
| ExtremeXOS Network Timing Feature Pack for Summit X670-G2 - enables 1588v2 PTP (Precision Time Protocol) | 17136 | \$1,031.00 | 48% | \$540.14 |

| | | | | |
|--|-------|-------------|-----|--------------------|
| ExtremeSwitching X670-G2 EXOS MACsec Feature Pack. Enables MACsec for use with ExtremeSwitching LRM/MACsec Adapter | 17137 | \$1,031.00 | 48% | <i>\$540.14</i> |
| ExtremeSwitching X690 EXOS MACsec Feature Pack. Enables MACsec for use with ExtremeSwitching LRM/MACsec Adapter | 17138 | \$1,031.00 | 48% | <i>\$540.14</i> |
| ExtremeSwitching X590 EXOS MACsec Feature Pack. Enables MACsec for use with ExtremeSwitching LRM/MACsec Adapter | 17139 | \$1,031.00 | 48% | <i>\$540.14</i> |
| 72 10GBASE-X SFP+ ExtremeXOS Advanced Edge License unpopulated dual PSU power slot and 5 unpopulated fan airflow slots | 17300 | \$33,414.00 | 48% | <i>\$17,505.59</i> |
| 48 10GBASE-X SFP+ and 4 40GBASE-X QSFP+ ExtremeXOS Advanced Edge License unpopulated dual PSU power slot and 3 unpopulated fan airflow slots | 17310 | \$30,266.00 | 48% | <i>\$15,856.36</i> |
| X690 base unit with 48 1Gb/10Gb SFP+ ports 2 10Gb/40Gb QSFP+ ports 4 10Gb/25Gb/40Gb/50Gb/100Gb capable QSFP28 ports 2 unpopulated power supplies slots 6 unpopulated fan module slots ExtremeXOS Advanced Edge License | 17350 | \$30,988.00 | 48% | <i>\$16,234.61</i> |

| | | | | |
|--|-------|-------------|-----|--------------------|
| X690 base unit with 48 1Gb/10GBASE-T ports 2 10Gb/40Gb QSFP+ ports 4 10Gb/25Gb/40Gb/50Gb/100Gb capable QSFP28 ports 2 unpopulated power supplies slots 6 unpopulated fan module slots ExtremeXOS Advanced Edge License | 17360 | \$38,138.00 | 48% | <i>\$19,980.50</i> |
| X620 16 100Mb/1Gb/10GBASE- X SFP+ ports 2 unpopulated power supply slots 1 unpopulated Fan Module slot ExtremeXOS Edge license | 17401 | \$7,049.00 | 48% | <i>\$3,692.97</i> |
| X620 10 100Mb/1Gb/10GBASE- X SFP+ ports integrated power supply and fans ExtremeXOS Edge license | 17404 | \$5,170.00 | 48% | <i>\$2,708.56</i> |
| ExtremeXOS Advanced Edge License for X620 | 17431 | \$1,031.00 | 48% | <i>\$540.14</i> |
| ExtremeXOS AVB (Audio Video Bridging) Feature Pack for X620 | 17433 | \$513.00 | 48% | <i>\$268.76</i> |
| ExtremeSwitching X620 EXOS MACsec Feature Pack. Enables MACsec for use with ExtremeSwitching LRM/MACsec Adapter | 17435 | \$1,031.00 | 48% | <i>\$540.14</i> |
| ExtremeXOS X870 Series Core License | 17825 | \$6,216.00 | 48% | <i>\$3,256.56</i> |
| ExtremeXOS X870 MPLS License | 17828 | \$4,142.00 | 48% | <i>\$2,169.99</i> |
| ExtremeXOS X870-96x-8c Port Speed License upgrades 6 ports to 10Gb/25Gb/40Gb/50Gb/100Gb support | 17830 | \$3,105.00 | 48% | <i>\$1,626.71</i> |

| | | | | |
|--|-------|-------------|-----|-------------------|
| V400 Series 24 10/100/1000BASE-T 2 1000/10GBaseX unpopulated SFP+ ports fixed power supply and fan | 18101 | \$3,999.00 | 48% | <i>\$2,095.08</i> |
| V400 Series 24 10/100/1000BASE-T PoE+ 2 1000/10GBaseX unpopulated SFP+ ports fixed power supply and fans | 18102 | \$5,205.00 | 48% | <i>\$2,726.90</i> |
| V400 Series 48 10/100/1000BASE-T 4 1000/10GBaseX unpopulated SFP+ ports fixed power supply and fan | 18103 | \$5,658.00 | 48% | <i>\$2,964.23</i> |
| V400 Series 48 10/100/1000BASE-T PoE+ 4 1000/10GBaseX unpopulated SFP+ ports fixed power supply and fans | 18104 | \$8,076.00 | 48% | <i>\$4,231.02</i> |
| VX 3 Slot Redundant Power Supply Shelf | 18201 | \$379.00 | 48% | <i>\$198.56</i> |
| VX 1000W Redundant Power Supply | 18202 | \$3,015.00 | 48% | <i>\$1,579.56</i> |
| Extreme Campus Controller E1120 - expandable to 125 APs/Defenders and 50 Switches (Requires Separate Activation Key) | 30137 | \$14,444.00 | 48% | <i>\$7,567.21</i> |
| Multi region 12V Indoor External Power Supply | 30512 | \$99.00 | 48% | <i>\$51.87</i> |
| Wall mounting bracket extension for indoor and outdoor directional service antennas | 30515 | \$188.00 | 48% | <i>\$98.49</i> |
| Indoor wall mounting bracket for AP3916ic | 30516 | \$54.00 | 48% | <i>\$28.29</i> |
| Drop Ceiling Multi-T Rail Bracket. Accommodates 9/16 15/16 and 1.5 wide T-bars | 30518 | \$54.00 | 48% | <i>\$28.29</i> |
| Outdoor Pole mounting bracket for AP3917i/e or AP 7662 i/e | 30520 | \$157.00 | 48% | <i>\$82.25</i> |

| | | | | |
|---|-------|------------|-----|------------|
| Silicone Rubber Chamfer Gasket Kit for WS-EIO-01 AP Enclosure | 30524 | \$116.00 | 48% | \$60.77 |
| Indoor 2.3-2.7/4.9-6.1GHz 4-feed 5dBi 120 degree sector antenna with standard RPSMA-type plug connector | 30702 | \$1,570.00 | 48% | \$822.52 |
| Indoor 4.9-6.1GHz 4-feed 4dBi 60 degree sector antenna with standard RPSMA-type plug | 30703 | \$746.00 | 48% | \$390.83 |
| Indoor 2.3-2.7GHz 4-feed 5dBi 60 degree sector antenna with standard RPSMA-type plug connector | 30704 | \$746.00 | 48% | \$390.83 |
| Indoor 2.4GHz/5GHz eight feed 6.5/5.5dBi 25 degree sector antenna with standard RPSMA-type plug connector | 30705 | \$4,555.00 | 48% | \$2,386.36 |
| Indoor 5GHz four feed 5dBi 25 degree sector antenna with RPSMA-type plug connector | 30706 | \$1,759.00 | 48% | \$921.54 |
| Indoor 2.4GHz/5GHz eight feed 10/6dBi 55 degree sector antenna with standard RPSMA-type plug connector | 30707 | \$4,555.00 | 48% | \$2,386.36 |
| Outdoor 2.3-2.7/4.9-6.1GHz 4-feed 5dBi 120 degree sector antenna with standard N-type plug connector | 30711 | \$728.00 | 48% | \$381.40 |
| Outdoor 4.9-6.1GHz 4-feed 4dBi 60 degree sector antenna with standard N-type plug | 30712 | \$746.00 | 48% | \$390.83 |
| Outdoor 5GHz four feed 5dBi 25 degree sector antenna with standard N-type plug connector | 30716 | \$1,599.00 | 48% | \$837.72 |
| Outdoor 2.4-2.5/5.15-5.875GHz 4dBi Omni antenna with standard N-type plug connector | 30724 | \$1,098.00 | 48% | \$575.24 |
| Vehicle Mounted Modem Bracket | 32216 | \$435.00 | 48% | \$227.90 |
| Mounting Plate for Indoor APs | 37201 | \$26.00 | 48% | \$13.62 |
| Flat Metal Indoor Bracket | 37210 | \$47.00 | 48% | \$24.62 |

| | | | | |
|--|--------|--------------|-----|-------------|
| Drop Ceiling Flat Tile Tbar Bracket. Accommodates 9/16 15/16 and 1.5 wide T-bars | 37211 | \$54.00 | 48% | \$28.29 |
| PWR 12VDC 2A 2.5mm x 5.5mm connector. Global AC plugs included | 37215 | \$99.00 | 48% | \$51.87 |
| PWR 12VDC 3A 2.5mm x 5.5mm connector. Global AC plugs included | 37219 | \$114.00 | 48% | \$59.72 |
| Per Incident Support | 90110 | \$ 1,850.00 | 1% | \$1,845.24 |
| EW Per Incident Consulting | 90119 | \$ 250.00 | 1% | \$249.36 |
| EW Core Operational Software Update | 90120 | \$ 2,500.00 | 1% | \$2,493.56 |
| EW Edge Wireless Operational SW Update | 90121 | \$ 1,500.00 | 1% | \$1,496.14 |
| Lab Fee | 90672 | \$ 200.00 | 1% | \$199.49 |
| Sandbox | 90673 | \$ 65.00 | 1% | \$64.83 |
| EWP Premier XIQ Support Overlay | 90888 | \$ 1.00 | 6% | \$0.95 |
| Hardware Inspection Program | 96005 | \$ 1.00 | 1% | \$1.00 |
| 40 Hours of Mgd Svc Remote Changes | 96008 | \$ 7,800.00 | 10% | \$7,072.65 |
| 200 Hours of Mgd Svc Remote Changes | 96009 | \$ 39,000.00 | 10% | \$35,363.25 |
| VSP 8000 PLDS PREMIER LICENSE FOR 1 CHASSIS LICDS | 380176 | \$7,772.00 | 48% | \$4,071.75 |
| VSP 8000 PLDS PREMIER LICENSE W/MACSEC FOR 1 CHASSIS LICDS | 380177 | \$7,772.00 | 48% | \$4,071.75 |
| VIRTUAL SERVICES PLATFORM 9000 PLDS PREM LICENSE FOR 1 CHASSIS. LICDS | 380810 | \$16,650.00 | 48% | \$8,722.94 |
| VIRTUAL SERVICES PLATFORM 9000 PLDS PREMIER LICENSE W/MACSEC LICDS | 380811 | \$16,650.00 | 48% | \$8,722.94 |
| VSP 7200 PORT LICENSE FOR 1 SWITCH LICDS | 386914 | \$20,734.00 | 48% | \$10,862.54 |
| VSP8600 IOC BASE LICDS | 392259 | \$6,216.00 | 48% | \$3,256.56 |
| VSP8600 CHAS L3V LICDS | 392670 | \$9,995.00 | 48% | \$5,236.38 |

| | | | | |
|---|-----------|-------------|-----|------------|
| VSP8600 CHAS L3V+MACSEC LICDS | 392671 | \$10,364.00 | 48% | \$5,429.70 |
| POWER DISTRIBUTION UNIT POWER CORD IEC C | 700512240 | \$132.00 | 48% | \$69.15 |
| POWER DISTRIBUTION UNIT POWER CORD IEC C | 700512241 | \$68.00 | 48% | \$35.63 |
| POWER DISTRIBUTION UNIT POWER CORD IEC C | 700512242 | \$115.00 | 48% | \$60.25 |
| ERS3600 STACKING CABLE 0.5M | 700512588 | \$101.00 | 48% | \$52.91 |
| ERS3600 STACKING CABLE 1.0M | 700512589 | \$125.00 | 48% | \$65.49 |
| RACK MOUNT KIT TWO POST SUPPORTS ERS3600 ERS4900 ERS5900 | 700512595 | \$23.00 | 48% | \$12.05 |
| 1000BASE-SX SFP MMF 220 550 meters LC connector Industrial Temp | 10051H | \$680.00 | 48% | \$356.25 |
| 1000BASE-LX SFP MMF 220 550 meters SMF 10km LC connector Industrial Temp | 10052H | \$1,367.00 | 48% | \$716.17 |
| 1000BASE-ZX SFP SMF 70km LC connector Industrial Temp | 10053H | \$5,488.00 | 48% | \$2,875.16 |
| 1000BASE-BX-D SFP 1490-nm TX/1310-nm RX wavelength Industrial Temp | 10056H | \$1,510.00 | 48% | \$791.09 |
| 1000BASE-BX-U SFP 1310-nm TX/1490-nm RX wavelength Industrial Temp | 10057H | \$1,510.00 | 48% | \$791.09 |
| Dual-speed 100 LX / 1000 LX SFP LC connector Industrial Temp | 10060H | \$817.00 | 48% | \$428.03 |
| 10/100/1000BASE-T SFP module CAT5 cable 100m link RJ45-connector for Giga Bit Ethernet SFP Port Industrial Temp | 10070H | \$406.00 | 48% | \$212.70 |
| 1000BASE-SX SFP 10 Pack Industrial Temp | 10071H | \$4,052.00 | 48% | \$2,122.84 |
| 1000BASE-LX SFP 10 Pack Industrial Temp | 10072H | \$8,172.00 | 48% | \$4,281.31 |

| | | | | |
|---|----------------------|-------------|-----|--------------------|
| 100G 4WDM-10 QSFP28 10km LC connector Single-Mode MSA P/N EQPT1H4WM4LCL100. | 100G-4WDM-QSFP10KM | \$6,381.00 | 48% | <i>\$3,343.01</i> |
| 100G 4WDM-20 QSFP28 20km LC connector Single-Mode MSA P/N EQPT1H4WM4WCL100. | 100G-4WDM-QSFP20KM | \$19,505.00 | 48% | <i>\$10,218.67</i> |
| 100G 4WDM-40 QSFP28 40km LC connector Single-Mode MSA P/N EQPT1H4WM4ECL100. | 100G-4WDM-QSFP40KM | \$37,806.00 | 48% | <i>\$19,806.56</i> |
| 100G CFP2 to QSFP28 adapter MSA P/N ECPA1HCPQP0C0100. | 100G-ADPT-CFP2-QSFP | \$2,512.00 | 48% | <i>\$1,316.04</i> |
| 100G AOC QSFP28 10m TAA MSA P/N EQPC1HA0100C0100. | 100G-AOC-QSFP10M-TA | \$4,116.00 | 48% | <i>\$2,156.37</i> |
| 100G CWDM4 QSFP28 2km LC connector Single-Mode MSA P/N EQPT1H4CW4FCL100. | 100G-CWDM4-QSFP2KM | \$19,318.00 | 48% | <i>\$10,120.70</i> |
| 100G Passive DAC QSFP28 1m MSA P/N EQPC1HPC010C0100. | 100G-DACP-QSFP1M | \$419.00 | 48% | <i>\$219.51</i> |
| 100G Passive DAC QSFP28 3m MSA P/N EQPC1HPC030C0100. | 100G-DACP-QSFP3M | \$710.00 | 48% | <i>\$371.97</i> |
| 100G Passive DAC QSFP28 to 4xSFP28 Breakout 1m MSA P/N EQPC1HPC010C01X4. | 100G-DACP-QSFP4SFP1M | \$676.00 | 48% | <i>\$354.16</i> |
| 100G Passive DAC QSFP28 to 4xSFP28 Breakout 3m MSA P/N EQPC1HPC030C01X4. | 100G-DACP-QSFP4SFP3M | \$1,000.00 | 48% | <i>\$523.90</i> |
| 100G Passive DAC QSFP28 to 4xSFP28 Breakout 5m MSA P/N EQPC1HPC050C01X4. | 100G-DACP-QSFP4SFP5M | \$1,334.00 | 48% | <i>\$698.88</i> |
| 100G Passive DAC QSFP28 5m MSA P/N EQPC1HPC050C0100. | 100G-DACP-QSFP5M | \$895.00 | 48% | <i>\$468.89</i> |
| 100G PASSIVE DAC QSFP28 0.5M MSA EQPT1H8FR1FCL100 | 100G-DACP-QSFPZ5M | \$419.00 | 48% | <i>\$219.51</i> |

| | | | | |
|---|---------------------|-------------|-----|--------------------|
| 100G DR QSFP28 500M LC SINGLE MODE MSA EQPT1H8DR1DCL100 | 100G-DR-QSFP500M | \$3,495.00 | 48% | <i>\$1,831.03</i> |
| 100G ER4-lite QSFP28 30km (w/o FEC) 40km (w/ FEC) LC connector Single-Mode MSA P/N EQPT1H4ER4ECL1LT. | 100G-ER4LT-QSFP40KM | \$59,478.00 | 48% | <i>\$31,160.52</i> |
| 100G ESR4 QSFP28 300m MPO connector Multi-Mode MSA P/N EQPT1H4SR4SCM100. | 100G-ESR4-QSFP300M | \$8,368.00 | 48% | <i>\$4,384.00</i> |
| 100G FR QSFP28 2KM LC CONN SINGLE MODE MSA EQPT1H8FR1FCL100 | 100G-FR-QSFP2KM | \$5,795.00 | 48% | <i>\$3,036.00</i> |
| 100G LR QSFP 10KM LC CONN SINGLE MODE MSA P/N EQPT1H8LR1LCL100 | 100G-LR-QSFP10KM | \$10,495.00 | 48% | <i>\$5,498.33</i> |
| 100G LR4 QSFP28 10km LC connector Single-Mode MSA P/N EQPT1H4LR4LCL100. | 100G-LR4-QSFP10KM | \$32,201.00 | 48% | <i>\$16,870.10</i> |
| 100G LR4 QSFP28 2km LC connector Single-Mode MSA P/N EQPT1H4LR4FCL100. | 100G-LR4-QSFP2KM | \$25,759.00 | 48% | <i>\$13,495.14</i> |
| 100G SR4 QSFP28 100m MPO connector Multi-Mode MSA P/N EQPT1H4SR4UCM100. | 100G-SR4-QSFP100M | \$2,402.00 | 48% | <i>\$1,258.41</i> |
| 100G BiDi - SR QSFP28 100m LC connector Multi-Mode MSA P/N EQPT1H4BD2UCL100 | 100G-SR4BD-QSFP100M | \$2,495.00 | 48% | <i>\$1,307.13</i> |
| 100G SWDM4 QSFP28 100m LC connector Multi-Mode MSA P/N EQPT1H4SW4UCL100. | 100G-SWDM4-QSFP100M | \$4,810.00 | 48% | <i>\$2,519.96</i> |
| 100BASE-FX SFP module MMF 2km link LC-connector for Fast Ethernet SFP Port I-temp | 100M-FX-SFP2KM-I | \$159.00 | 48% | <i>\$83.30</i> |
| 300W AC Power Supply module for Summit X460 E4G-400 Series Switches - Extended Temparture Range from -10 to +50 degrees Celsius | 10930A | \$739.00 | 48% | <i>\$387.16</i> |
| 10G AOC SFP+ 10m | 10G-AOC-SFP10M | \$476.00 | 48% | <i>\$249.38</i> |

| | | | | |
|---|----------------------|-------------|-----|------------|
| 10G AOC SFP+ 7m | 10G-AOC-SFP7M | \$476.00 | 48% | \$249.38 |
| 10G Active DAC SFP+ 1m | 10G-DACA-SFP1M | \$219.00 | 48% | \$114.73 |
| 10G Active DAC SFP+ 3m | 10G-DACA-SFP3M | \$306.00 | 48% | \$160.31 |
| 10G Active DAC SFP+ 5m | 10G-DACA-SFP5M | \$379.00 | 48% | \$198.56 |
| 10G PASSIVE DAC SFP+ 1M Industrial Temp | 10G-DACP-SFP1M-IT | \$218.00 | 48% | \$114.21 |
| 10G PASSIVE DAC SFP+ 0.5M | 10G-DACP-SFPZ5M | \$182.00 | 48% | \$95.35 |
| 10G PASSIVE DAC SFP+ 0.5M Industrial Temp | 10G-DACP-SFPZ5M-IT | \$218.00 | 48% | \$114.21 |
| 10G ER SFP+ 40km LC connector Single-Mode Ext.Temp | 10G-ER-SFP40KM-ET | \$13,198.00 | 48% | \$6,914.43 |
| 10G ER SFP+ 40km LC connector Single-Mode Industrial Temp | 10G-ER-SFP40KM-IT | \$15,178.00 | 48% | \$7,951.75 |
| 10G LR SFP+ 10km LC connector Single-Mode Ext.Temp | 10G-LR-SFP10KM-ET | \$3,255.00 | 48% | \$1,705.29 |
| 10G LR SFP+ 10km LC connector Single-Mode 8pack Ext.Temp | 10G-LR-SFP10KM-ET8PK | \$18,623.00 | 48% | \$9,756.59 |
| 10G LR SFP+ 10km LC connector Single-Mode Industrial Temp | 10G-LR-SFP10KM-IT | \$3,743.00 | 48% | \$1,960.96 |
| 10GBASE-SR SFP+ optic (LC) target range 300m over MMF | 10G-SFP-SR | \$1,276.00 | 48% | \$668.50 |
| 10G SR SFP+ 300m LC connector Multi-Mode Ext.Temp | 10G-SR-SFP300M-ET | \$1,217.00 | 48% | \$637.59 |
| 10G SR SFP+ 300m LC connector Multi-Mode 8pack Ext.Temp | 10G-SR-SFP300M-ET8PK | \$6,340.00 | 48% | \$3,321.53 |
| 10G SR SFP+ 300m LC connector Multi-Mode Industrial Temp | 10G-SR-SFP300M-IT | \$1,400.00 | 48% | \$733.46 |
| 10G USR SFP+ 100m Hight Rx Sens LC connector Multi-Mode | 10G-USR-SFP100M | \$990.00 | 48% | \$518.66 |
| 10 GB SINGLE FIBER SM -D 10 KM | 10GB-BX10-D | \$4,351.00 | 48% | \$2,279.49 |

| | | | | |
|--|------------------------------|-------------|-----|-------------|
| 10 GB SINGLE FIBER SM -U 10 KM | 10GB-BX10-U | \$4,351.00 | 48% | \$2,279.49 |
| 10 GB SINGLE FIBER SM -D 40 KM | 10GB-BX40-D | \$9,237.00 | 48% | \$4,839.26 |
| 10 GB SINGLE FIBER SM -U 40 KM | 10GB-BX40-U | \$9,237.00 | 48% | \$4,839.26 |
| Extreme Universal Compute Platform 1130C Appliance | 1130C | \$11,995.00 | 48% | \$6,284.18 |
| X440-G2 48 10/100/1000BASE- T POE+ 4 1GbE unpopulated SFP upgradable to 10GbE SFP+ (2 combo/2 non-combo) 2 1GbE copper combo upgradable to 10GbE 1 Fixed AC PSU 1 RPS port ExtremeXOS Edge license | 16535A | \$7,781.00 | 48% | \$4,076.47 |
| TAA Summit X670-G2-48x-4q 48 10GBASE-X SFP+ and 4 40GBASE-X QSFP+ ExtremeXOS Advanced Edge License 2 550W AC Power Supplies with Front-to-Back airflow and 3 Front-to-Back airflow fan modules | 17310T | \$41,983.00 | 48% | \$21,994.89 |
| X620 16 100Mb/1Gb/10GBASE- X SFP+ ports 2 BF 300W AC power supplies 1 BF Fan Module ExtremeXOS Edge license | 17401G | \$10,500.00 | 48% | \$5,500.95 |
| X620 16 100Mb/1Gb/10GBASE- X SFP+ ports 2 FB 300W AC power supplies 1 FB Fan Module ExtremeXOS Edge license | 17401T | \$10,888.00 | 48% | \$5,704.22 |
| Six Pack of - V400 Series 48 101001000BASE-T PoE 4 100010GBaseX unpopulated SFP ports fixed power supply and fans | 18104-6PK | \$32,303.00 | 48% | \$16,923.54 |
| 20G Passive DAC SFPDD 1m | 20G-DACP- SFPDD1M | \$490.00 | 48% | \$256.71 |
| 20G Passive DAC SFPDD to 2xSFP 1m breakout | 20G-DACP- SFPDD2SFP1 M | \$857.00 | 48% | \$448.98 |

| | | | | |
|--|----------------------|------------|-----|------------|
| 20G Passive DAC SFPDD to 2xSFP 3m breakout | 20G-DACP-SFPDD2SFP3M | \$957.00 | 48% | \$501.37 |
| 20G Passive DAC SFPDD to 2xSFP 5m breakout | 20G-DACP-SFPDD2SFP5M | \$1,443.00 | 48% | \$755.99 |
| 20G Passive DAC SFPDD 3m | 20G-DACP-SFPDD3M | \$745.00 | 48% | \$390.31 |
| 20G Passive DAC SFPDD 5m | 20G-DACP-SFPDD5M | \$1,048.00 | 48% | \$549.05 |
| SFPDD TO SFPDD 20G DAC 0.5M | 20G-DACP-SFPDDZ5M | \$444.00 | 48% | \$232.61 |
| CORD SET18AWG SVT 3COND 7.5FT | 23844-00-00R | \$15.00 | 48% | \$7.86 |
| RP-SMA (Male) To Type N (Female) Adapter | 25-85392-01R | \$69.00 | 48% | \$36.15 |
| RP-SMA-Female to N-Female adapter | 25-90262-01R | \$30.00 | 48% | \$15.72 |
| RP-SMA-Female to N-Male adapter | 25-90263-01R | \$30.00 | 48% | \$15.72 |
| N-MALE TO RP-SMA FEMALE ADAPTER | 25-90263-02R | \$30.00 | 48% | \$15.72 |
| N-Type Female to N-Type Female Adaptor | 25-99175-01R | \$15.00 | 48% | \$7.86 |
| 25G/10G SR DUAL RATE SFP28 100M LC MULTI MODE MSA ESPT251SR1UCL1DR | 25/10G-SR-SFP100M | \$1,806.00 | 48% | \$946.16 |
| 25G Passive DAC SFP28 1m MSA P/N ESPC25PC010C0100. | 25G-DACP-SFP1M | \$247.00 | 10% | \$223.97 |
| 25G Passive DAC SFP28 3m MSA P/N ESPC25PC030C0100. | 25G-DACP-SFP3M | \$342.00 | 10% | \$310.11 |
| 25G PASSIVE DAC SFP28 0.5M MSA ESPC25PCZ50C0100 | 25G-DACP-SFPZ5M | \$247.00 | 10% | \$223.97 |
| 25G ER SFP28 40km LC connector Single-Mode MSA P/N ESPT251ER1ECL100. | 25G-ER-SFP40KM | \$6,177.00 | 48% | \$3,236.13 |
| 25G LR SFP28 10km LC connector Single-Mode MSA P/N ESPT251LR1LCL100. | 25G-LR-SFP10KM | \$2,059.00 | 10% | \$1,867.00 |

| | | | | |
|--|---------------------|-------------|-----|-------------------|
| 25G SR SFP28 100m LC connector Multi-Mode MSA P/N ESPT251SR1UCL100. | 25G-SR-SFP100M | \$1,198.00 | 10% | <i>\$1,086.29</i> |
| 400G FR4 QSFPDD 2KM LC CONN SINGLE MODE MSA P/N EQDT4H8FR4FCL100 | 400G-FR4-QSFPDD2KM | \$18,125.00 | 48% | <i>\$9,495.69</i> |
| 40G AOC QSFP+ 100m MSA P/N EQPC40A01H0C0100. | 40G-AOC-QSFP100M | \$3,536.00 | 48% | <i>\$1,852.51</i> |
| 40G AOC QSFP+ 10m MSA P/N EQPC40A0100C0100. | 40G-AOC-QSFP10M | \$1,282.00 | 48% | <i>\$671.64</i> |
| 40G AOC QSFP+ 20m MSA P/N EQPC40A0200C0100. | 40G-AOC-QSFP20M | \$1,836.00 | 48% | <i>\$961.88</i> |
| 40G AOC QSFP+ 3m MSA P/N EQPC40A0030C0100. | 40G-AOC-QSFP3M | \$1,234.00 | 48% | <i>\$646.49</i> |
| 40G AOC QSFP+ to 4xSFP+ Breakout 10m MSA P/N EQPC40A0100C01X4. | 40G-AOC-QSFP4SFP10M | \$1,868.00 | 48% | <i>\$978.65</i> |
| 40G AOC QSFP+ 5m MSA P/N EQPC40A0050C0100. | 40G-AOC-QSFP5M | \$1,276.00 | 48% | <i>\$668.50</i> |
| 40G BiDi SR QSFP+ 150m LC connector Multi-Mode MSA P/N EQPT404BD2VCL100. | 40G-BDSR-QSFP150M | \$1,282.00 | 48% | <i>\$671.64</i> |
| 40G Active DAC QSFP+ 1m MSA P/N EQPC40AC010C0100. | 40G-DACA-QSFP1M | \$644.00 | 48% | <i>\$337.39</i> |
| 40G Active DAC QSFP+ 3m MSA P/N EQPC40AC030C0100. | 40G-DACA-QSFP3M | \$839.00 | 48% | <i>\$439.55</i> |
| 40G Active DAC QSFP+ to 4xSFP+ Breakout 1m MSA P/N EQPC40AC010C01X4. | 40G-DACA-QSFP4SFP1M | \$839.00 | 48% | <i>\$439.55</i> |
| 40G Active DAC QSFP+ to 4xSFP+ Breakout 3m MSA P/N EQPC40AC030C01X4. | 40G-DACA-QSFP4SFP3M | \$1,031.00 | 48% | <i>\$540.14</i> |
| 40G Active DAC QSFP+ to 4xSFP+ Breakout 5m MSA P/N EQPC40AC050C01X4. | 40G-DACA-QSFP4SFP5M | \$1,224.00 | 48% | <i>\$641.25</i> |
| 40G Active DAC QSFP+ 5m MSA P/N EQPC40AC050C0100. | 40G-DACA-QSFP5M | \$1,031.00 | 48% | <i>\$540.14</i> |
| 40G Passive DAC QSFP+ 1m MSA P/N EQPC40PC010C0100. | 40G-DACP-QSFP1M | \$372.00 | 48% | <i>\$194.89</i> |

| | | | | |
|---|----------------------|-------------|-----|-------------|
| 40G Passive DAC QSFP+ 3m MSA P/N EQPC40PC030C0100. | 40G-DACP-QSFP3M | \$702.00 | 48% | \$367.78 |
| 40G Passive DAC QSFP+ to 4xSFP+ Breakout 1m MSA P/N EQPC40PC010C01X4. | 40G-DACP-QSFP4SFP1M | \$839.00 | 48% | \$439.55 |
| 40G Passive DAC QSFP+ to 4xSFP+ Breakout 2m MSA P/N EQPC40PC020C01X4. | 40G-DACP-QSFP4SFP2M | \$1,694.00 | 48% | \$887.49 |
| 40G Passive DAC QSFP+ to 4xSFP+ Breakout 3m MSA P/N EQPC40PC030C01X4. | 40G-DACP-QSFP4SFP3M | \$934.00 | 48% | \$489.32 |
| 40G Passive DAC QSFP+ to 4xSFP+ Breakout 5m MSA P/N EQPC40PC050C01X4. | 40G-DACP-QSFP4SFP5M | \$1,408.00 | 48% | \$737.65 |
| 40G Passive DAC QSFP+ 5m MSA P/N EQPC40PC050C0100. | 40G-DACP-QSFP5M | \$766.00 | 48% | \$401.31 |
| 40G Passive DAC QSFP+ 0.5m MSA P/N EQPC40PCZ50C0100. | 40G-DACP-QSFPZ5M | \$355.00 | 48% | \$185.98 |
| 40G ESR4 QSFP+ 400m 10G-SR interoperable MPO connector Multi-Mode MSA P/N EQPT404SR4SCM1NT. | 40G-ESR4-QSFP400M-NT | \$4,503.00 | 48% | \$2,359.12 |
| 40G LM4 QSFP+ 160m 160m MMF. 1km SMF LC connector Multi-Mode MSA P/N EQPT404LM4VCL100. | 40G-LM4-QSFP160M | \$5,920.00 | 48% | \$3,101.49 |
| 40G LR4 QSFP+ 10km LC connector Single-Mode MSA P/N EQPT404LR4LCL100. | 40G-LR4-QSFP10KM | \$10,919.00 | 48% | \$5,720.46 |
| 40GBase-ER4 QSFP+ optic (LC) for up to 40km over SMF | 40G-QSFP-ER4-1 | \$47,667.00 | 48% | \$24,972.74 |
| 40G SR4 QSFP+ 150m 10G-SR interoperable MPO connector Multi-Mode MSA P/N MSA P/N EQPT404SR4VCM100 | 40G-SR4-QSFP150M | \$2,570.00 | 48% | \$1,346.42 |
| 40GB 40GBASE-LR4 SMF QSFP+ | 40GB-LR4-QSFP | \$11,356.00 | 48% | \$5,949.41 |

| | | | | |
|--|--------------|-------------|-----|--------------------|
| 4120 24 port stackable MultiGig switch with 24 10M/100M/1G/2.5GBaseT 90W POE ports 2x100G QSFP28 Universal/Stack ports 4x25G SFP28 ports fixed fans 1 internal fixed AC PSU 1 unpopulated modular PSU slot | 4120-24MW-4Y | \$8,995.00 | 48% | <i>\$4,712.48</i> |
| 4120 48 port stackable MultiGig switch with 48 10M/100M/1G/2.5GBaseT 90W POE ports 2x100G QSFP28 Universal/Stack ports 4x25G SFP28 ports fixed fans 1 internal fixed AC PSU 1 unpopulated modular PSU slot | 4120-48MW-4Y | \$11,995.00 | 48% | <i>\$6,284.18</i> |
| Extreme Universal Compute Platform 4120C Appliance | 4120C | \$55,093.00 | 48% | <i>\$28,863.22</i> |
| Extreme Universal Compute Platform 4120C Appliance (Larger capacity variant) | 4120C-1 | \$62,199.00 | 48% | <i>\$32,586.06</i> |
| 4220 12 port stackable switch (124W POE) with 12 10/100/1000BaseT 30W POE ports 4 1G/10G SFP+ ports. Includes Fans (Silent mode up to 35C) 1 Fixed AC PSU | 4220-12P-4X | \$2,995.00 | 48% | <i>\$1,569.08</i> |
| 4220 12 port stackable switch with 12 10/100/1000BaseT ports 4 1G/10G SFP+ ports. Includes Fans (Silent mode up to 35C) 1 Fixed AC PSU | 4220-12T-4X | \$2,195.00 | 48% | <i>\$1,149.96</i> |
| 4220 24 port stackable switch (195W POE) with 24 10/100/1000BaseT 30W POE ports 4 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU | 4220-24P-4X | \$3,995.00 | 48% | <i>\$2,092.98</i> |
| 4220 24 port stackable switch with 24 10/100/1000BaseT ports 4 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU | 4220-24T-4X | \$3,095.00 | 48% | <i>\$1,621.47</i> |

| | | | | |
|--|-------------------|------------|-----|------------|
| 4220 48 port stackable switch (370W POE) with 48 10/100/1000BaseT 30W POE ports 4 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU | 4220-48P-4X | \$5,995.00 | 48% | \$3,140.78 |
| 4220 48 port stackable switch with 48 10/100/1000BaseT ports 4 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU | 4220-48T-4X | \$4,495.00 | 48% | \$2,354.93 |
| 4220 24 port stackable MultiGig switch (370W POE) with 4 1G/2.5G/5GBaseT 90W POE ports 20 10/100/1000BaseT 30W POE ports 4 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU with option to add external redundant PSU | 4220-4MW-20P-4X | \$5,495.00 | 48% | \$2,878.83 |
| 4220 12 port stackable MultiGig switch (240W POE) with 4 1G/2.5G/5GBaseT 90W POE ports 8 10/100/1000BaseT 30W POE ports 4 1G/10G SFP+ ports. Includes Fans (Silent mode up to 35C) 1 Fixed AC PSU | 4220-4MW-8P-4X | \$3,895.00 | 48% | \$2,040.59 |
| 4220 48 port stackable MultiGig switch (740W POE) with 8 1G/2.5G/5GBaseT 90W POE ports 40 10/100/1000BaseT 30W POE ports 4 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU with option to add external redundant PSU | 4220-8MW-40P-4X | \$7,995.00 | 48% | \$4,188.58 |
| 4220 8 port stackable switch 8 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU | 4220-8X | \$4,195.00 | 48% | \$2,197.76 |
| AC Line Cord 1.8M ungrounded two wire NEMA 1-15P US for power supplies 50-14000-243R | 50-16000-182R | \$6.00 | 48% | \$3.14 |
| MACsec License for 5000 series switches | 5000-MACSEC-LIC-P | \$1,595.00 | 48% | \$835.62 |

| | | | | |
|---|----------------------|------------|-----|-------------------|
| Premier License for 5000 series switches | 5000-PRMR-LIC-P | \$2,495.00 | 48% | <i>\$1,307.13</i> |
| License that converts 4x1GbE SFP ports to 10GbE SFP+. Applicable with 16 24 and 48 port switches of 5320. | 5320-10GUPG-4X-LIC-P | \$795.00 | 48% | <i>\$416.50</i> |
| License that converts 8x1GbE SFP ports to 10GbE SFP+. Applicable with 24 and 48 port switches of 5320. | 5320-10GUPG-8X-LIC-P | \$1,195.00 | 48% | <i>\$626.06</i> |
| ExtremeSwitching 5320 16x10/100/1000BASET FDX/HDX PoE+ 4x10G unpopulated SFP+ MACSec capable 1x internal fixed PSU fans | 5320-16P-4XE | \$4,295.00 | 48% | <i>\$2,250.15</i> |
| ExtremeSwitching 5320 16x10/100/1000BASET FDX/HDX PoE+ 4x10G unpopulated SFP+ MACSec capable 1x internal fixed DC PSU fans | 5320-16P-4XE-DC | \$5,155.00 | 48% | <i>\$2,700.70</i> |
| ExtremeSwitching 5320 24x10/100/1000BASET FDX/HDX PoE+ 8x10G unpopulated SFP+ MACSec capable 1x internal fixed PSU fans | 5320-24P-8XE | \$5,525.00 | 48% | <i>\$2,894.55</i> |
| 5320 48 port stackable Extended Temperature (0-60C) switch with 24 10/10/1000BaseT ports 24 1G SFP ports 4 1G/10G SFP+ ports MACsec capable. Includes Fans 1 Fixed AC PSU with option to add external redundant PSU | 5320-24T-24S-4XE-XT | \$6,495.00 | 48% | <i>\$3,402.73</i> |
| 5320 24 port stackable Extended Temperature (0-60C) switch with 24 10/10/1000BaseT ports 4 1G/10G SFP+ ports. Includes Fans 1 Fixed AC PSU with option to add external redundant PSU | 5320-24T-4X-XT | \$3,495.00 | 48% | <i>\$1,831.03</i> |

| | | | | |
|--|------------------------|-------------|-----|------------|
| ExtremeSwitching 5320 24x10/100/1000BASET FDX/HDX 8x10G unpopulated SFP+ MACSec capable 1x internal fixed PSU fans | 5320-24T-8XE | \$4,149.00 | 48% | \$2,173.66 |
| ExtremeSwitching 5320 48x10/100/1000BASET FDX/HDX PoE+ 8x10G unpopulated SFP+ MACSec capable 1x internal fixed PSU fans | 5320-48P-8XE | \$8,726.00 | 48% | \$4,571.55 |
| ExtremeSwitching 5320 48x10/100/1000BASET FDX/HDX 8x10G unpopulated SFP+ MACSec capable 1x internal fixed PSU fans | 5320-48T-8XE | \$6,133.00 | 48% | \$3,213.08 |
| ExtremeSwitching 5420F 16 100Mb/1Gb/2.5Gb 802.3bt 90W PoE 32 10/100/1000BASET FDX/HDX PoE+ 2 stacking/SFP- DD 4 10G un-pop SFP+ MACsec capable internal fixed PSU fans 1 un-pop modular PSU slot. | 5420F-16MW- 32P-4XE | \$14,429.00 | 48% | \$7,559.35 |
| ExtremeSwitching 5420F 16 10/100/1000BASET FDX/HDX 802.3bt 90W PoE 32 10/100/1000BASET FDX/HDX PoE+ 2 stacking/SFP-DD 4 10G up-pop SFP+ MACsec internal fixed PSU fans 1 un-pop modular PSU slot. | 5420F-16W- 32P-4XE | \$11,096.00 | 48% | \$5,813.19 |
| ExtremeSwitching 5420F 24 10/100/1000BASET FDX/HDX PoE+ 2 stacking/SFP-DD 4 10G unpopulated SFP+ MACsec capable internal fixed PSU fans 1 unpopulated modular PSU slot. | 5420F-24P- 4XE | \$6,885.00 | 48% | \$3,607.05 |

| | | | | |
|---|----------------------|-------------|-----|-------------------|
| ExtremeSwitching 5420F 24 1000BASE-X SFP 2 stacking/SFP-DD 4 10G unpopulated SFP+ MACsec capable internal fixed PSU fans 1 unpopulated modular PSU slot. | 5420F-24S- 4XE | \$7,013.00 | 48% | <i>\$3,674.11</i> |
| ExtremeSwitching 5420F 24 10/100/1000BASET FDX/HDX 2 stacking/SFP-DD 4 10G unpopulated SFP+ MACsec capable internal fixed PSU fans 1 unpopulated modular PSU slot. | 5420F-24T- 4XE | \$5,737.00 | 48% | <i>\$3,005.61</i> |
| ExtremeSwitching 5420F 48 10/100/1000BASET FDX/HDX PoE+ 2 stacking/SFP-DD 4 10G unpopulated SFP+ MACsec capable internal fixed PSU fans 1 unpopulated modular PSU slots. | 5420F-48P- 4XE | \$10,586.00 | 48% | <i>\$5,546.01</i> |
| ExtremeSwitching 5420F 48 10/100/1000BASET FDX/HDX PoE+ 2 stacking/SFP-DD 4 10G unpopulated SFP+ w/ LRM MACsec capable internal fixed PSU fans 1 unpopulated modular PSU slot. | 5420F-48P- 4XL | \$11,096.00 | 48% | <i>\$5,813.19</i> |
| ExtremeSwitching 5420F 48 10/100/1000BASET FDX/HDX 2 stacking/SFP-DD 4 10G unpopulated SFP+ MACsec capable internal fixed PSU fans 1 unpopulated modular PSU slot. | 5420F-48T- 4XE | \$7,644.00 | 48% | <i>\$4,004.69</i> |
| ExtremeSwitching 5420F 8 10/100/1000BASET FDX/HDX 802.3bt 90W PoE 16 10/100/1000BASET FDX/HDX PoE+ 2 stacking/SFP-DD 4 10G un-pop SFP+ MACsec internal fixed PSU fans 1 un-pop modular PSU slot. | 5420F-8W-16P- 4XE | \$7,274.00 | 48% | <i>\$3,810.85</i> |

| | | | | |
|---|------------------------|-------------|-----|-------------------|
| ExtremeSwitching 5420M 16 100Mb/1Gb/2.5Gb 802.3bt 90W PoE 32 10/100/1000BASET FDX/HDX PoE+ 2 stacking/SFP- DD 4 10/25G un-pop SFP28 MACsec capable includes fan module 2 un-pop modular PSU slots. | 5420M-16MW- 32P-4YE | \$14,156.00 | 48% | <i>\$7,416.33</i> |
| ExtremeSwitching 5420M 24 10/100/1000BASET FDX/HDX 2 stacking/SFP-DD 4 10/25G unpopulated SFP28 MACsec capable includes fan module 2 unpopulated modular PSU slots. | 5420M-24T- 4YE | \$7,134.00 | 48% | <i>\$3,737.50</i> |
| ExtremeSwitching 5420M 24 10/100/1000BASET FDX/HDX 802.3bt 90W PoE 2 stacking/SFP- DD 4 10/25G unpopulated SFP28 MACsec capable includes fan module 2 unpopulated modular PSU slots. | 5420M-24W- 4YE | \$7,159.00 | 48% | <i>\$3,750.60</i> |
| ExtremeSwitching 5420M 48 10/100/1000BASET FDX/HDX 2 stacking/SFP-DD 4 10/25G unpopulated SFP28 MACsec capable includes fan module 2 unpopulated modular PSU slots. | 5420M-48T- 4YE | \$9,646.00 | 48% | <i>\$5,053.54</i> |
| ExtremeSwitching 5420M 48 10/100/1000BASET FDX/HDX 802.3bt 90W PoE 2 stacking/SFP- DD 4 10/25G unpopulated SFP28 MACsec capable includes fan module 2 unpopulated modular PSU slots. | 5420M-48W- 4YE | \$11,380.00 | 48% | <i>\$5,961.98</i> |
| ExtremeSwitch5520 12 100Mb/1Gb/2.5Gb/5Gb 802.3bt 90W PoE 36 10/100/1000BASET FDX/HDX 802.3bt 90W PoE 2 stacking/QSFP28 1 un-pop VIM slot MACsec capable 3 fan modules 2 un-pop modular PSU slots. | 5520-12MW- 36W | \$13,569.00 | 48% | <i>\$7,108.80</i> |

| | | | | |
|--|------------------------|-------------|-----|-------------------|
| ExtremeSwitching 5520 24 10/100/1000BASET FDX/HDX 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes 2 fan modules 2 unpopulated modular PSU slots. | 5520-24T | \$6,014.00 | 48% | <i>\$3,150.73</i> |
| 5520 24 10/100/1000BASET FDX/HDX MACsec capable ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 3 unpopulated modular fan slots 2 unpopulated modular PSU slots AC or DC PSU capable. | 5520-24T- ACDC-BASE | \$5,450.00 | 48% | <i>\$2,855.26</i> |
| 5520 24 10/100/1000BASET FDX/HDX MACsec capable ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 2 unpopulated modular fan slots 2 unpopulated modular PSU slots. | 5520-24T- BASE | \$5,268.00 | 48% | <i>\$2,759.91</i> |
| ExtremeSwitching 5520 24 10/100/1000BASET FDX/HDX 802.3bt 90W PoE 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes 3 fan modules 2 unpopulated modular PSU slots. | 5520-24W | \$6,736.00 | 48% | <i>\$3,528.99</i> |
| ExtremeSwitching 5520 24 1Gb/10Gb SFP+ ports 2 stacking/QSFP28 1 unpopulated VIM slot includes 2 fan modules 2 unpopulated modular PSU slots. | 5520-24X | \$16,585.00 | 48% | <i>\$8,688.88</i> |
| 5520 24 1Gb/10Gb SFP+ ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 3 unpopulated modular fan slots 2 unpopulated modular PSU slots AC or DC PSU capable. | 5520-24X- ACDC-BASE | \$15,839.00 | 48% | <i>\$8,298.05</i> |
| 5520 24 1Gb/10Gb SFP+ ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 2 unpopulated modular fan slots 2 unpopulated modular PSU slots. | 5520-24X- BASE | \$15,839.00 | 48% | <i>\$8,298.05</i> |

| | | | | |
|--|-------------------------|-------------|-----|------------|
| ExtremeSwitching 5520 48 1000BASE-X SFP 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes 3 fan modules 2 unpopulated modular PSU slots. | 5520-48SE | \$14,032.00 | 48% | \$7,351.36 |
| 5520 48 1000BASE-X SFP MACsec capable ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 3 unpopulated modular fan slots 2 unpopulated modular PSU slots AC or DC PSU capable. | 5520-48SE- ACDC-BASE | \$12,913.00 | 48% | \$6,765.12 |
| 5520 48 1000BASE-X SFP MACsec capable ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 3 unpopulated modular fan slots 2 unpopulated modular PSU slots. | 5520-48SE- BASE | \$12,913.00 | 48% | \$6,765.12 |
| ExtremeSwitching 5520 48 10/100/1000BASET FDX/HDX 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes 3 fan modules 2 unpopulated modular PSU slots. | 5520-48T | \$9,250.00 | 48% | \$4,846.08 |
| 5520 48 10/100/1000BASET FDX/HDX MACsec capable ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 3 unpopulated modular fan slots 2 unpopulated modular PSU slots AC or DC PSU capable. | 5520-48T- ACDC-BASE | \$8,131.00 | 48% | \$4,259.83 |
| 5520 48 10/100/1000BASET FDX/HDX MACsec capable ports 2 stacking/QSFP28 ports 1 unpopulated VIM slot 3 unpopulated modular fan slots 2 unpopulated modular PSU slots. | 5520-48T- BASE | \$8,131.00 | 48% | \$4,259.83 |

| | | | | |
|---|------------------|-------------|-----|-------------|
| ExtremeSwitching 5520 48 10/100/1000BASET FDX/HDX 802.3bt 90W PoE 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes 3 fan modules 2 unpopulated modular PSU slots. | 5520-48W | \$11,096.00 | 48% | \$5,813.19 |
| 5520 Versatile Interface Module with four 10GbE SFP+ ports supported on ExtremeSwitching 5520 | 5520-VIM-4X | \$1,598.00 | 48% | \$837.19 |
| 5520 Versatile Interface Module with four 10GbE SFP+ ports LRM MACsec capable supported on ExtremeSwitching 5520 | 5520-VIM- 4XE | \$2,338.00 | 48% | \$1,224.88 |
| 5520 Versatile Interface Module with four 25GbE SFP28 ports MACsec capable supported on ExtremeSwitching 5520 | 5520-VIM- 4YE | \$3,079.00 | 48% | \$1,613.09 |
| BRAZILCORDNBR 14136 10A C13 | 5601013-F | \$60.00 | 10% | \$54.41 |
| USACORDNEMA 6-15C13 208- 250V | 5601013-U2 | \$30.00 | 10% | \$27.20 |
| JUMPERCORDC14C13 | 5601313-J | \$38.00 | 10% | \$34.46 |
| USACORDNEMA 5-15C13 | 5601313-U1 | \$38.00 | 10% | \$34.46 |
| BRAZILCORD NBR 14136 20A C13 | 5601513-F | \$92.00 | 10% | \$83.42 |
| USACORDNEMA 5-15 C13 14 AWG | 5601513-U1 | \$38.00 | 10% | \$34.46 |
| ExtremeSwitching 5720 24 100Mb/1Gb/2.5Gb/5Gb 802.3bt 90W PoE 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes fan modules 2 unpopulated modular PSU slots. | 5720-24MW | \$16,995.00 | 48% | \$8,903.68 |
| ExtremeSwitching 5720 24 100Mb/1Gb/2.5Gb/5Gb/10Gb 802.3bt 90W PoE 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes fan modules 2 unpopulated modular PSU slots. | 5720-24MXW | \$22,995.00 | 48% | \$12,047.08 |

| | | | | |
|---|-------------------|-------------|-----|--------------------|
| ExtremeSwitching 5720 48 100Mb/1Gb/2.5Gb/5Gb 802.3bt 90W PoE 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes fan modules 2 unpopulated modular PSU slots. | 5720-48MW | \$19,995.00 | 48% | <i>\$10,475.38</i> |
| ExtremeSwitching 5720 48 100Mb/1Gb/2.5Gb/5Gb/10Gb 802.3bt 90W PoE 2 stacking/QSFP28 1 unpopulated VIM slot MACsec capable includes fan modules 2 unpopulated modular PSU slots. | 5720-48MXW | \$28,995.00 | 48% | <i>\$15,190.48</i> |
| 5720 Versatile Interface Module with 2 100GbE QSFP28 ports MACsec capable. | 5720-VIM-2CE | \$4,495.00 | 48% | <i>\$2,354.93</i> |
| 5720 Versatile Interface Module with 6 25GbE SFP28 ports MACsec capable. | 5720-VIM-6YE | \$4,495.00 | 48% | <i>\$2,354.93</i> |
| MACSec License for 7000 Series Switches | 7000-MACSEC-LIC-P | \$9,000.00 | 48% | <i>\$4,715.10</i> |
| Extreme 7000 Premier Feature License (Includes Integrated Application Hosting) | 7000-PRMR-LIC-P | \$9,000.00 | 48% | <i>\$4,715.10</i> |
| Extreme 7520-48XT Switch with two empty power supply slots six empty fan slots Ships with one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 7520-48XT-6C | \$33,300.00 | 48% | <i>\$17,445.87</i> |
| Extreme 7520-48XT Switch with front-back airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 7520-48XT-6C-AC-F | \$35,995.00 | 48% | <i>\$18,857.78</i> |
| Extreme 7520-48XT Switch with back-front airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 7520-48XT-6C-AC-R | \$35,995.00 | 48% | <i>\$18,857.78</i> |

| | | | | |
|---|--------------------|-------------|-----|--------------------|
| Extreme 7520-48Y Switch with two empty power supply slots six empty fan slots Ships with one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 7520-48Y-8C | \$31,300.00 | 48% | <i>\$16,398.07</i> |
| Extreme 7520-48Y Switch with front-back airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 7520-48Y-8C-AC-F | \$33,995.00 | 48% | <i>\$17,809.98</i> |
| Extreme 7520-48Y Switch with back-front airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 7520-48Y-8C-AC-R | \$33,995.00 | 48% | <i>\$17,809.98</i> |
| Extreme 7520-48YE Switch with two empty power supply slots six empty fan slots Ships with one 4-post rack mount kit Supports 48x25/10G with MACsec and 8x100/40G ports with MACsec | 7520-48YE-8CE | \$35,995.00 | 48% | <i>\$18,857.78</i> |
| Extreme 7520-48YE Switch with front-back airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x25/10G with MACsec and 8x100/40G ports with MACsec | 7520-48YE-8CE-AC-F | \$38,995.00 | 48% | <i>\$20,429.48</i> |
| Extreme 7520-48YE Switch with back-front airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x25/10G with MACsec and 8x100/40G ports with MACsec | 7520-48YE-8CE-AC-R | \$38,995.00 | 48% | <i>\$20,429.48</i> |

| | | | | |
|---|-------------------|-------------|-----|--------------------|
| Extreme 7720-32C Switch with two empty power supply slots six empty fan slots Ships with a 4-post rack mount kit Supports 32x100/40G | 7720-32C | \$37,995.00 | 48% | <i>\$19,905.58</i> |
| Extreme 7720-32C with Front to Back air flow. Supports 32x40/100G with dual AC power supplies six fans and a 4-post rack mount kit | 7720-32C-AC-F | \$40,850.00 | 48% | <i>\$21,401.32</i> |
| Extreme 7720-32C with Back to Front air flow. Supports 32x40/100G AC with dual power supplies six fans and a 4-post rack mount kit | 7720-32C-AC-R | \$40,850.00 | 48% | <i>\$21,401.32</i> |
| Extreme 8000 Premier Feature License (Includes Integrated Application Hosting) | 8000-PRMR-LIC-P | \$9,000.00 | 48% | <i>\$4,715.10</i> |
| Extreme 8520-48XT Switch with two empty power supply slots six empty fan slots Ships with one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 8520-48XT-6C | \$30,334.00 | 48% | <i>\$15,891.98</i> |
| Extreme 8520-48XT Switch with front-back airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 8520-48XT-6C-AC-F | \$32,863.00 | 48% | <i>\$17,216.93</i> |
| Extreme 8520-48XT Switch with back-front airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 8520-48XT-6C-AC-R | \$32,863.00 | 48% | <i>\$17,216.93</i> |
| Extreme 8520-48XT Switch with front-back airflow Ships with two DC power supplies six fans one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 8520-48XT-6C-DC-F | \$36,655.00 | 48% | <i>\$19,203.55</i> |

| | | | | |
|---|-------------------|-------------|-----|--------------------|
| Extreme 8520-48XT Switch with back-front airflow Ships with two DC power supplies six fans one 4-post rack mount kit Supports 48x10/1G copper ports and 6x100/40G fiber ports | 8520-48XT-6C-DC-R | \$36,655.00 | 48% | <i>\$19,203.55</i> |
| Extreme 8520-48Y Switch with two empty power supply slots six empty fan slots Ships with one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 8520-48Y-8C | \$30,814.00 | 48% | <i>\$16,143.45</i> |
| Extreme 8520-48Y Switch with front-back airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 8520-48Y-8C-AC-F | \$33,495.00 | 48% | <i>\$17,548.03</i> |
| Extreme 8520-48Y Switch with back-front airflow Ships with two AC power supplies six fans one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 8520-48Y-8C-AC-R | \$33,495.00 | 48% | <i>\$17,548.03</i> |
| Extreme 8520-48Y Switch with front-back airflow Ships with two DC power supplies six fans one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 8520-48Y-8C-DC-F | \$37,514.00 | 48% | <i>\$19,653.58</i> |
| Extreme 8520-48Y Switch with back-front airflow Ships with two DC power supplies six fans one 4-post rack mount kit Supports 48x25/10/1G and 8x100/40G ports | 8520-48Y-8C-DC-R | \$37,514.00 | 48% | <i>\$19,653.58</i> |
| Extreme 8720-32C Switch with two empty power supply slots six empty fan slots Supports 32x100/40G | 8720-32C | \$38,184.00 | 48% | <i>\$20,004.60</i> |

| | | | | |
|--|---------------|--------------|-----|--------------------|
| Extreme 8720-32C with Front to Back air flow. Supports 32x40/100G with dual AC power supplies six fans and a 4-post rack mount kit | 8720-32C-AC-F | \$40,195.00 | 48% | <i>\$21,058.16</i> |
| Extreme 8720-32C with Back to Front air flow. Supports 32x40/100G AC with dual power supplies six fans and a 4-post rack mount kit | 8720-32C-AC-R | \$40,195.00 | 48% | <i>\$21,058.16</i> |
| Extreme 8720-32C with Front to Back air flow. Supports 32x40/100G with dual DC power supplies six fans and a 4-post rack mount kit | 8720-32C-DC-F | \$44,215.00 | 48% | <i>\$23,164.24</i> |
| Extreme 8720-32C with Back to Front air flow. Supports 32x40/100G with dual DC power supplies six fans and a 4-post rack mount kit | 8720-32C-DC-R | \$44,215.00 | 48% | <i>\$23,164.24</i> |
| Extreme 8820-40C. Base unit with 40x100GE/40GE QSFP28 ports with 2 unpopulated power supply slots 6 unpopulated fan slots and a 4-post rack mount kit | 8820-40C | \$116,995.00 | 48% | <i>\$61,293.68</i> |
| Extreme 8820-40C with Front-Back airflow. Base unit with 40x100GE/40GE QSFP28 ports with 2 AC power supplies 6 fan modules and a 4-post rack mount kit | 8820-40C-AC-F | \$124,995.00 | 48% | <i>\$65,484.88</i> |
| Extreme 8820-40C with Back-Front airflow. Base unit with 40x100GE/40GE QSFP28 ports with 2 AC power supplies 6 fan modules and a 4-post rack mount kit | 8820-40C-AC-R | \$124,995.00 | 48% | <i>\$65,484.88</i> |
| Extreme 8820-40C with Front-Back airflow. Base unit with 40x100GE/40GE QSFP28 ports with 2 DC power supplies 6 fan modules and a 4-post rack mount kit | 8820-40C-DC-F | \$128,995.00 | 48% | <i>\$67,580.48</i> |

| | | | | |
|--|---------------|--------------|-----|---------------------|
| Extreme 8820-40C with Back-Front airflow. Base unit with 40x100GE/40GE QSFP28 ports with 2 DC power supplies 6 fan modules and a 4-post rack mount kit | 8820-40C-DC-R | \$128,995.00 | 48% | <i>\$67,580.48</i> |
| Extreme 8820-80C. Base unit with 80x100GE/40GE QSFP28 ports with 4 unpopulated power supply slots 4 unpopulated fan slots and a 4-post rack mount kit | 8820-80C | \$229,200.00 | 48% | <i>\$120,077.88</i> |
| Extreme 8820-80C with Front-Back airflow. Base unit with 80x100GE/40GE QSFP28 ports with 4 AC power supplies 4 fan modules and a 4-post rack mount kit | 8820-80C-AC-F | \$231,995.00 | 48% | <i>\$121,542.18</i> |
| Extreme 8820-80C with Back-Front airflow. Base unit with 80x100GE/40GE QSFP28 ports with 4 AC power supplies 4 fan modules and a 4-post rack mount kit | 8820-80C-AC-R | \$231,995.00 | 48% | <i>\$121,542.18</i> |
| Extreme 8820-80C with Front-Back airflow. Base unit with 80x100GE/40GE QSFP28 ports with 4 DC power supplies 4 fan modules and a 4-post rack mount kit | 8820-80C-DC-F | \$257,995.00 | 48% | <i>\$135,163.58</i> |
| Extreme 8820-80C with Back-Front airflow. Base unit with 80x100GE/40GE QSFP28 ports with 4 DC power supplies 4 fan modules and a 4-post rack mount kit | 8820-80C-DC-R | \$257,995.00 | 48% | <i>\$135,163.58</i> |
| CBL ASSY LC TO LC DPLX 10GB MM FBR 3M | 9380010-3M | \$219.00 | 10% | <i>\$198.58</i> |
| CBL MPO- 4 LC DPLXPLENUM10 GB MM 5M | 9380014-5M | \$1,882.00 | 10% | <i>\$1,706.50</i> |
| CBL ASSY LC TO SC DPLX 62.5 MM FBR 3M | 9380527-3M | \$219.00 | 10% | <i>\$198.58</i> |

| | | | | |
|--|--------------|-----------|-----|-----------------|
| CBL ASSY LC TO ST DPLX 62.5 MM FBR 3M | 9380528-3M | \$219.00 | 10% | <i>\$198.58</i> |
| CBL ASSY LC TO SC DPLX SM FBR 3M | 9380530-3M | \$219.00 | 10% | <i>\$198.58</i> |
| CBL ASSY LC TO ST DPLX SM FBR 3M | 9380531-3M | \$219.00 | 10% | <i>\$198.58</i> |
| CBL ASSY LC TO LC DPLX SM FBR 3M | 9380532-3M | \$219.00 | 10% | <i>\$198.58</i> |
| MSP NBD AHR RMA Only 16173 | 94304-16173 | \$ 86.00 | 6% | <i>\$81.45</i> |
| MSP NBD AHR RMA Only 16173T | 94304-16173T | \$ 179.00 | 6% | <i>\$169.52</i> |
| MSP NBD AHR RMA Only 16177 | 94304-16177 | \$ 116.00 | 6% | <i>\$109.86</i> |
| MSP NBD AHR RMA Only 16177T | 94304-16177T | \$ 215.00 | 6% | <i>\$203.62</i> |
| MSP NBD AHR RMA Only 16179 | 94304-16179 | \$ 197.00 | 6% | <i>\$186.57</i> |
| MSP NBD AHR RMA Only 16179T | 94304-16179T | \$ 325.00 | 6% | <i>\$307.79</i> |
| MSP NBD AHR RMA Only 16530 | 94304-16530 | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD AHR RMA Only 16531 | 94304-16531 | \$ 70.00 | 6% | <i>\$66.29</i> |
| MSP NBD AHR RMA Only 16531T | 94304-16531T | \$ 84.00 | 6% | <i>\$79.55</i> |
| MSP NBD AHR RMA Only 16532 | 94304-16532 | \$ 70.00 | 6% | <i>\$66.29</i> |
| MSP NBD AHR RMA Only 16532T | 94304-16532T | \$ 84.00 | 6% | <i>\$79.55</i> |
| MSP NBD AHR RMA Only 16533 | 94304-16533 | \$ 98.00 | 6% | <i>\$92.81</i> |
| MSP NBD AHR RMA Only 16533T | 94304-16533T | \$ 117.00 | 6% | <i>\$110.80</i> |
| MSP NBD AHR RMA Only 16534 | 94304-16534 | \$ 105.00 | 6% | <i>\$99.44</i> |
| MSP NBD AHR RMA Only 16535 | 94304-16535 | \$ 156.00 | 6% | <i>\$147.74</i> |
| MSP NBD AHR RMA Only 16535A | 94304-16535A | \$ 156.00 | 6% | <i>\$147.74</i> |
| MSP NBD AHR RMA Only 16535T | 94304-16535T | \$ 187.00 | 6% | <i>\$177.10</i> |

| | | | | |
|---|---------------------------|-----------|----|-----------------|
| MSP NBD AHR RMA Only 16703 | 94304-16703 | \$ 164.00 | 6% | <i>\$155.32</i> |
| MSP NBD AHR RMA Only 16703T | 94304-16703T | \$ 265.00 | 6% | <i>\$250.97</i> |
| MSP NBD AHR RMA Only 16704 | 94304-16704 | \$ 242.00 | 6% | <i>\$229.19</i> |
| MSP NBD AHR RMA Only 16704T | 94304-16704T | \$ 382.00 | 6% | <i>\$361.77</i> |
| MSP NBD AHR RMA Only 16790 | 94304-16790 | \$ 321.00 | 6% | <i>\$304.00</i> |
| MSP NBD AHR RMA Only 16791 | 94304-16791 | \$ 423.00 | 6% | <i>\$400.60</i> |
| MSP NBD AHR RMA Only 17300 | 94304-17300 | \$ 668.00 | 6% | <i>\$632.63</i> |
| MSP NBD AHR RMA Only 17310 | 94304-17310 | \$ 605.00 | 6% | <i>\$572.97</i> |
| MSP NBD AHR RMA Only 17310T | 94304-17310T | \$ 840.00 | 6% | <i>\$795.52</i> |
| MSP NBD AHR RMA Only 17350 | 94304-17350 | \$ 620.00 | 6% | <i>\$587.17</i> |
| MSP NBD AHR RMA Only 17360 | 94304-17360 | \$ 763.00 | 6% | <i>\$722.60</i> |
| MSP NBD AHR RMA Only 4120-24MW-4Y | 94304-4120- 24MW-4Y | \$ 180.00 | 6% | <i>\$170.47</i> |
| MSP NBD AHR RMA Only 4120-48MW-4Y | 94304-4120- 48MW-4Y | \$ 240.00 | 6% | <i>\$227.29</i> |
| MSP NBD AHR RMA Only 4220-12P-4X | 94304-4220- 12P-4X | \$ 60.00 | 6% | <i>\$56.82</i> |
| MSP NBD AHR RMA Only 4220-12T-4X | 94304-4220- 12T-4X | \$ 44.00 | 6% | <i>\$41.67</i> |
| MSP NBD AHR RMA Only 4220-24P-4X | 94304-4220- 24P-4X | \$ 80.00 | 6% | <i>\$75.76</i> |
| MSP NBD AHR RMA Only 4220-24T-4X | 94304-4220- 24T-4X | \$ 62.00 | 6% | <i>\$58.72</i> |
| MSP NBD AHR RMA Only 4220-48P-4X | 94304-4220- 48P-4X | \$ 120.00 | 6% | <i>\$113.65</i> |
| MSP NBD AHR RMA Only 4220-48T-4X | 94304-4220- 48T-4X | \$ 90.00 | 6% | <i>\$85.23</i> |
| MSP NBD AHR RMA Only 4220-4MW-20P-4X | 94304-4220- 4MW-20P-4X | \$ 110.00 | 6% | <i>\$104.18</i> |
| MSP NBD AHR RMA Only 4220-4MW-8P-4X | 94304-4220- 4MW-8P-4X | \$ 78.00 | 6% | <i>\$73.87</i> |

| | | | | |
|---|-----------------------------------|-----------|----|-----------------|
| MSP NBD AHR RMA Only 4220-8MW-40P-4X | 94304-4220- 8MW-40P-4X | \$ 160.00 | 6% | <i>\$151.53</i> |
| MSP NBD AHR RMA Only 4220-8X | 94304-4220-8X | \$ 84.00 | 6% | <i>\$79.55</i> |
| MSP NBD AHR RMA Only 5320-16P-4XE | 94304-5320- 16P-4XE | \$ 86.00 | 6% | <i>\$81.45</i> |
| MSP NBD AHR RMA Only 5320-16P-4XE-DC | 94304-5320- 16P-4XE-DC | \$ 103.00 | 6% | <i>\$97.55</i> |
| MSP NBD AHR RMA Only 5320-24P-8XE | 94304-5320- 24P-8XE | \$ 111.00 | 6% | <i>\$105.12</i> |
| MSP NBD AHR RMA Only 5320-24T-24S-4XE-XT | 94304-5320- 24T-24S-4XE- XT | \$ 130.00 | 6% | <i>\$123.12</i> |
| MSP NBD AHR RMA Only 5320-24T-4X-XT | 94304-5320- 24T-4X-XT | \$ 70.00 | 6% | <i>\$66.29</i> |
| MSP NBD AHR RMA Only 5320-24T-8XE | 94304-5320- 24T-8XE | \$ 83.00 | 6% | <i>\$78.61</i> |
| MSP NBD AHR RMA Only 5320-48P-8XE | 94304-5320- 48P-8XE | \$ 175.00 | 6% | <i>\$165.73</i> |
| MSP NBD AHR RMA Only 5320-48T-8XE | 94304-5320- 48T-8XE | \$ 123.00 | 6% | <i>\$116.49</i> |
| MSP NBD AHR RMA Only 5420F-16MW-32P-4XE | 94304-5420F- 16MW-32P- 4XE | \$ 289.00 | 6% | <i>\$273.70</i> |
| MSP NBD AHR RMA Only 5420F-16W-32P-4XE | 94304-5420F- 16W-32P-4XE | \$ 222.00 | 6% | <i>\$210.25</i> |
| MSP NBD AHR RMA Only 5420F-24P-4XE | 94304-5420F- 24P-4XE | \$ 138.00 | 6% | <i>\$130.69</i> |
| MSP NBD AHR RMA Only 5420F-24S-4XE | 94304-5420F- 24S-4XE | \$ 140.00 | 6% | <i>\$132.59</i> |
| MSP NBD AHR RMA Only 5420F-24T-4XE | 94304-5420F- 24T-4XE | \$ 115.00 | 6% | <i>\$108.91</i> |
| MSP NBD AHR RMA Only 5420F-48P-4XE | 94304-5420F- 48P-4XE | \$ 212.00 | 6% | <i>\$200.77</i> |
| MSP NBD AHR RMA Only 5420F-48P-4XL | 94304-5420F- 48P-4XL | \$ 222.00 | 6% | <i>\$210.25</i> |
| MSP NBD AHR RMA Only 5420F-48T-4XE | 94304-5420F- 48T-4XE | \$ 153.00 | 6% | <i>\$144.90</i> |
| MSP NBD AHR RMA Only 5420F-8W-16P-4XE | 94304-5420F- 8W-16P-4XE | \$ 145.00 | 6% | <i>\$137.32</i> |

| | | | | |
|---|-----------------------------------|-----------|----|----------|
| MSP NBD AHR RMA Only 5420M-16MW-32P-4YE | 94304-5420M- 16MW-32P- 4YE | \$ 283.00 | 6% | \$268.02 |
| MSP NBD AHR RMA Only 5420M-24T-4YE | 94304-5420M- 24T-4YE | \$ 143.00 | 6% | \$135.43 |
| MSP NBD AHR RMA Only 5420M-24W-4YE | 94304-5420M- 24W-4YE | \$ 143.00 | 6% | \$135.43 |
| MSP NBD AHR RMA Only 5420M-48T-4YE | 94304-5420M- 48T-4YE | \$ 193.00 | 6% | \$182.78 |
| MSP NBD AHR RMA Only 5420M-48W-4YE | 94304-5420M- 48W-4YE | \$ 228.00 | 6% | \$215.93 |
| MSP NBD AHR RMA Only 5520-12MW-36W | 94304-5520- 12MW-36W | \$ 271.00 | 6% | \$256.65 |
| MSP NBD AHR RMA Only 5520-24T | 94304-5520- 24T | \$ 120.00 | 6% | \$113.65 |
| MSP NBD AHR RMA Only 5520-24T-ACDC-BASE | 94304-5520- 24T-ACDC- BASE | \$ 120.00 | 6% | \$113.65 |
| MSP NBD AHR RMA Only 5520-24T-BASE | 94304-5520- 24T-BASE | \$ 120.00 | 6% | \$113.65 |
| MSP NBD AHR RMA Only 5520-24W | 94304-5520- 24W | \$ 135.00 | 6% | \$127.85 |
| MSP NBD AHR RMA Only 5520-24X | 94304-5520- 24X | \$ 332.00 | 6% | \$314.42 |
| MSP NBD AHR RMA Only 5520-24X-ACDC-BASE | 94304-5520- 24X-ACDC- BASE | \$ 332.00 | 6% | \$314.42 |
| MSP NBD AHR RMA Only 5520-24X-BASE | 94304-5520- 24X-BASE | \$ 332.00 | 6% | \$314.42 |
| MSP NBD AHR RMA Only 5520-48SE | 94304-5520- 48SE | \$ 281.00 | 6% | \$266.12 |
| MSP NBD AHR RMA Only 5520-48SE-ACDC-BASE | 94304-5520- 48SE-ACDC- BASE | \$ 281.00 | 6% | \$266.12 |
| MSP NBD AHR RMA Only 5520-48SE-BASE | 94304-5520- 48SE-BASE | \$ 281.00 | 6% | \$266.12 |
| MSP NBD AHR RMA Only 5520-48T | 94304-5520- 48T | \$ 185.00 | 6% | \$175.20 |
| MSP NBD AHR RMA Only 5520-48T-ACDC-BASE | 94304-5520- 48T-ACDC- BASE | \$ 185.00 | 6% | \$175.20 |
| MSP NBD AHR RMA Only 5520-48T-BASE | 94304-5520- 48T-BASE | \$ 185.00 | 6% | \$175.20 |

| | | | | |
|--|----------------------------------|-----------|----|-----------------|
| MSP NBD AHR RMA Only 5520-48W | 94304-5520- 48W | \$ 222.00 | 6% | <i>\$210.25</i> |
| MSP NBD AHR RMA Only 5720-24MW | 94304-5720- 24MW | \$ 340.00 | 6% | <i>\$322.00</i> |
| MSP NBD AHR RMA Only 5720-24MXW | 94304-5720- 24MXW | \$ 460.00 | 6% | <i>\$435.64</i> |
| MSP NBD AHR RMA Only 5720-48MW | 94304-5720- 48MW | \$ 400.00 | 6% | <i>\$378.82</i> |
| MSP NBD AHR RMA Only 5720-48MXW | 94304-5720- 48MXW | \$ 580.00 | 6% | <i>\$549.29</i> |
| MSP NBD AHR RMA Only 7520-48XT-6C | 94304-7520- 48XT-6C | \$ 666.00 | 6% | <i>\$630.74</i> |
| MSP NBD AHR RMA Only 7520-48XT-6C-AC-F | 94304-7520- 48XT-6C-AC- F | \$ 666.00 | 6% | <i>\$630.74</i> |
| MSP NBD AHR RMA Only 7520-48XT-6C-AC-R | 94304-7520- 48XT-6C-AC- R | \$ 666.00 | 6% | <i>\$630.74</i> |
| MSP NBD AHR RMA Only 7520-48Y-8C | 94304-7520- 48Y-8C | \$ 626.00 | 6% | <i>\$592.85</i> |
| MSP NBD AHR RMA ONLY 7520-48Y-8C-AC-F | 94304-7520- 48Y-8C-AC-F | \$ 626.00 | 6% | <i>\$592.85</i> |
| MSP NBD AHR RMA Only 7520-48Y-8C-AC-R | 94304-7520- 48Y-8C-AC-R | \$ 626.00 | 6% | <i>\$592.85</i> |
| MSP NBD AHR RMA ONLY 7520-48YE-8CE | 94304-7520- 48YE-8CE | \$ 720.00 | 6% | <i>\$681.88</i> |
| MSP NBD AHR RMA ONLY 7520-48YE-8CE-AC-F | 94304-7520- 48YE-8CE-AC- F | \$ 720.00 | 6% | <i>\$681.88</i> |
| MSP NBD AHR RMA ONLY 7520-48YE-8CE-AC-R | 94304-7520- 48YE-8CE-AC- R | \$ 720.00 | 6% | <i>\$681.88</i> |
| MSP NBD AHR RMA Only 7720-32C | 94304-7720- 32C | \$ 760.00 | 6% | <i>\$719.76</i> |
| MSP NBD AHR RMA Only 7720-32C-AC-F | 94304-7720- 32C-AC-F | \$ 760.00 | 6% | <i>\$719.76</i> |
| MSP NBD AHR RMA Only 7720-32C-AC-R | 94304-7720- 32C-AC-R | \$ 760.00 | 6% | <i>\$719.76</i> |
| MSP NBD AHR RMA Only AP3000-WW | 94304-AP3000- WW | \$ 10.50 | 6% | <i>\$9.94</i> |
| MSP NBD AHR RMA Only AP3000X-WW | 94304- AP3000X-WW | \$ 21.75 | 6% | <i>\$20.60</i> |

| | | | | |
|--------------------------------------|---------------------------|----------|----|----------------|
| MSP NBD AHR RMA Only AP302W-CAN | 94304- AP302W-CAN | \$ 15.00 | 6% | <i>\$14.21</i> |
| MSP NBD AHR RMA Only AP302W-EG | 94304- AP302W-EG | \$ 19.00 | 6% | <i>\$17.99</i> |
| MSP NBD AHR RMA Only AP302W-FCC | 94304- AP302W-FCC | \$ 15.00 | 6% | <i>\$14.21</i> |
| MSP NBD AHR RMA Only AP302W-WR | 94304- AP302W-WR | \$ 12.00 | 6% | <i>\$11.36</i> |
| MSP NBD AHR RMA Only AP305C-1-CAN | 94304-AP305C- 1-CAN | \$ 29.00 | 6% | <i>\$27.46</i> |
| MSP NBD AHR RMA Only AP305C-1-EG | 94304-AP305C- 1-EG | \$ 29.00 | 6% | <i>\$27.46</i> |
| MSP NBD AHR RMA Only AP305C-1-FCC | 94304-AP305C- 1-FCC | \$ 29.00 | 6% | <i>\$27.46</i> |
| MSP NBD AHR RMA Only AP305C-1-IL | 94304-AP305C- 1-IL | \$ 29.00 | 6% | <i>\$27.46</i> |
| MSP NBD AHR RMA Only AP305C-1-WR | 94304-AP305C- 1-WR | \$ 29.00 | 6% | <i>\$27.46</i> |
| MSP NBD AHR RMA Only AP305C-CAN | 94304-AP305C- CAN | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305C-EG | 94304-AP305C- EG | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305C-FCC | 94304-AP305C- FCC | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305C-IL | 94304-AP305C- IL | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305C-WR | 94304-AP305C- WR | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305CX-CAN | 94304- AP305CX- CAN | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305CX-FCC | 94304- AP305CX- FCC | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305CX-IL | 94304- AP305CX-IL | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP305CX-WR | 94304- AP305CX-WR | \$ 34.00 | 6% | <i>\$32.20</i> |
| MSP NBD AHR RMA Only AP4000-1-WW | 94304-AP4000- 1-WW | \$ 30.00 | 6% | <i>\$28.41</i> |

| | | | | |
|---------------------------------------|-----------------------------|----------|----|----------------|
| MSP NBD AHR RMA Only AP4000-WW | 94304-AP4000- WW | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP NBD AHR RMA Only AP410C-1-CAN | 94304-AP410C- 1-CAN | \$ 26.00 | 6% | <i>\$24.62</i> |
| MSP NBD AHR RMA Only AP410C-1-EG | 94304-AP410C- 1-EG | \$ 26.00 | 6% | <i>\$24.62</i> |
| MSP NBD AHR RMA Only AP410C-1-FCC | 94304-AP410C- 1-FCC | \$ 26.00 | 6% | <i>\$24.62</i> |
| MSP NBD AHR RMA Only AP410C-1-IL | 94304-AP410C- 1-IL | \$ 26.00 | 6% | <i>\$24.62</i> |
| MSP NBD AHR RMA Only AP410C-1-WR | 94304-AP410C- 1-WR | \$ 26.00 | 6% | <i>\$24.62</i> |
| MSP NBD AHR RMA Only AP410C-CAN | 94304-AP410C- CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP NBD AHR RMA Only AP410C-EG | 94304-AP410C- EG | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP NBD AHR RMA Only AP410C-FCC | 94304-AP410C- FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP NBD AHR RMA Only AP410C-IL | 94304-AP410C- IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP NBD AHR RMA Only AP410C-WR | 94304-AP410C- WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP NBD AHR RMA Only AP460C-CAN | 94304-AP460C- CAN | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460C-EG | 94304-AP460C- EG | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460C-FCC | 94304-AP460C- FCC | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460C-IL | 94304-AP460C- IL | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460C-WR | 94304-AP460C- WR | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460S12C-CAN | 94304- AP460S12C- CAN | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460S12C-FCC | 94304- AP460S12C- FCC | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460S12C-WR | 94304- AP460S12C- WR | \$ 32.00 | 6% | <i>\$30.31</i> |

| | | | | |
|--------------------------------------|----------------------------|-----------|----|-----------------|
| MSP NBD AHR RMA Only AP460S6C-CAN | 94304- AP460S6C- CAN | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460S6C-FCC | 94304- AP460S6C- FCC | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP460S6C-WR | 94304- AP460S6C- WR | \$ 32.00 | 6% | <i>\$30.31</i> |
| MSP NBD AHR RMA Only AP5010-WW | 94304-AP5010- WW | \$ 66.00 | 6% | <i>\$62.51</i> |
| MSP NBD AHR RMA Only AP5020-WW | 94304-AP5020- WW | \$ 107.96 | 6% | <i>\$102.24</i> |
| MSP NBD AHR RMA Only AP5050D-WW | 94304- AP5050D-WW | \$ 215.00 | 6% | <i>\$203.62</i> |
| MSP NBD AHR RMA Only AP5050U-WW | 94304- AP5050U-WW | \$ 161.00 | 6% | <i>\$152.48</i> |
| MSP NBD AHR RMA Only AP510C-CAN | 94304-AP510C- CAN | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD AHR RMA Only AP510C-CE | 94304-AP510C- CE | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD AHR RMA Only AP510C-FCC | 94304-AP510C- FCC | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD AHR RMA Only AP510C-W | 94304-AP510C- W | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD AHR RMA Only AP510C-WW | 94304-AP510C- WW | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP NBD AHR RMA Only AP510CX-CAN | 94304- AP510CX- CAN | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD AHR RMA Only AP510CX-CE | 94304- AP510CX- CE | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD AHR RMA Only AP510CX-FCC | 94304- AP510CX- FCC | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD AHR RMA Only AP510CX-W | 94304- AP510CX- W | \$ 21.00 | 6% | <i>\$19.89</i> |
| MSP NBD AHR RMA Only H35309 | 94304-H35309 | \$ 731.00 | 6% | <i>\$692.29</i> |
| MSP NBD AHR RMA Only H35310 | 94304-H35310 | \$ 731.00 | 6% | <i>\$692.29</i> |
| MSP NBD AHR RMA Only H35311 | 94304-H35311 | \$ 731.00 | 6% | <i>\$692.29</i> |

| | | | | |
|--|----------------------------------|-----------|----|----------|
| MSP NBD AHR RMA Only H35312 | 94304-H35312 | \$ 626.00 | 6% | \$592.85 |
| MSP NBD AHR RMA Only H35313 | 94304-H35313 | \$ 626.00 | 6% | \$592.85 |
| MSP NBD AHR RMA Only H35314 | 94304-H35314 | \$ 626.00 | 6% | \$592.85 |
| MSP NBD AHR RMA Only H35315 | 94304-H35315 | \$ 419.00 | 6% | \$396.81 |
| MSP NBD AHR RMA Only H35318 | 94304-H35318 | \$ 211.00 | 6% | \$199.83 |
| MSP NBD AHR RMA ONLY H35320 | 94304-H35320 | \$ 278.00 | 6% | \$263.28 |
| MSP NBD AHR RMA Only H35321 | 94304-H35321 | \$ 332.00 | 6% | \$314.42 |
| MSP NBD AHR RMA ONLY H35322 | 94304-H35322 | \$ 363.00 | 6% | \$343.78 |
| MSP NBD AHR RMA Only H35323 | 94304-H35323 | \$ 419.00 | 6% | \$396.81 |
| MSP NBD AHR RMA Only H35359 | 94304-H35359 | \$ 332.00 | 6% | \$314.42 |
| MSP NBD AHR RMA ONLY H35360 | 94304-H35360 | \$ 363.00 | 6% | \$343.78 |
| MSP NBD AHR RMA Only H35361 | 94304-H35361 | \$ 419.00 | 6% | \$396.81 |
| MSP NBD AHR RMA Only H35362 | 94304-H35362 | \$ 211.00 | 6% | \$199.83 |
| MSP NBD AHR RMA Only H35455 | 94304-H35455 | \$ 278.00 | 6% | \$263.28 |
| MSP NBD AHR RMA Only H35456 | 94304-H35456 | \$ 278.00 | 6% | \$263.28 |
| MSP NBD AHR RMA Only H35457 | 94304-H35457 | \$ 278.00 | 6% | \$263.28 |
| MSP NBD AHR RMA Only H35458 | 94304-H35458 | \$ 278.00 | 6% | \$263.28 |
| MSP NBD AHR RMA Only H35471 | 94304-H35471 | \$ 278.00 | 6% | \$263.28 |
| MSP NBD AHR RMA Only VSP49-12MXU-12XE | 94304- VSP4900- 12MXU-12XE | \$ 390.00 | 6% | \$369.35 |

| | | | | |
|--|---|-----------|----|----------|
| MSP NBD AHR RMA Only VSP49-12MXU-12XE-B | 94304- VSP4900- 12MXU-12XE- B1 | \$ 390.00 | 6% | \$369.35 |
| MSP NBD AHR RMA Only VSP4900-24S | 94304- VSP4900-24S | \$ 210.00 | 6% | \$198.88 |
| MSP NBD AHR RMA Only VSP4900-24S-B3 | 94304- VSP4900-24S- B3 | \$ 210.00 | 6% | \$198.88 |
| MSP NBD AHR RMA Only VSP4900-24XE | 94304- VSP4900- 24XE | \$ 404.00 | 6% | \$382.61 |
| MSP NBD AHR RMA Only VSP4900-24XE-B3 | 94304- VSP4900- 24XE-B3 | \$ 404.00 | 6% | \$382.61 |
| MSP NBD AHR RMA Only X435-24P-4S | 94304-X435- 24P-4S | \$ 51.00 | 6% | \$48.30 |
| MSP NBD AHR RMA Only X435-24T-4S | 94304-X435- 24T-4S | \$ 28.00 | 6% | \$26.52 |
| MSP NBD AHR RMA Only X435-8P-2T-W | 94304-X435- 8P-2T-W | \$ 28.00 | 6% | \$26.52 |
| MSP NBD AHR RMA Only X435-8P-4S | 94304-X435- 8P-4S | \$ 26.00 | 6% | \$24.62 |
| MSP NBD AHR RMA Only X435-8T-4S | 94304-X435- 8T-4S | \$ 20.00 | 6% | \$18.94 |
| MSP NBD AHR RMA ONLY X465-24MU | 94304-X465- 24MU | \$ 363.00 | 6% | \$343.78 |
| MSP NBD AHR RMA Only X465-24W | 94304-X465- 24W | \$ 211.00 | 6% | \$199.83 |
| MSP NBD AHR RMA ONLY X465-48P | 94304-X465- 48P | \$ 278.00 | 6% | \$263.28 |
| MSP NBD AHR RMA Only X465-48W | 94304-X465- 48W | \$ 332.00 | 6% | \$314.42 |
| MSP NBD AHR RMA Only X695-48Y-8C | 94304-X695- 48Y-8C | \$ 642.00 | 6% | \$608.01 |
| MSP NBD AHR RMA Only XR600 | 94304-XR600 | \$ 34.00 | 6% | \$32.20 |
| MSP NBD AHR RMA ONLY XSW-MSP-BR-M-A | 94304-XSW- MSP-BR-M-A | \$ 216.08 | 6% | \$204.64 |
| MSP NBD AHR RMA ONLY XSW-MSP-BR-S-A | 94304-XSW- MSP-BR-S-A | \$ 97.91 | 6% | \$92.73 |

| | | | | |
|---|-----------------------------------|-------------|----|-------------------|
| MSP NBD AHR RMA ONLY XSW-MSP-BR-XS-A | 94304-XSW- MSP-BR-XS- A | \$ 78.34 | 6% | <i>\$74.19</i> |
| MSP NBD AHR RMA ONLY XSW-MSP-DC-S-A | 94304-XSW- MSP-DC-S-A | \$ 495.32 | 6% | <i>\$469.09</i> |
| MSP NBD AHR RMA ONLY XSW-MSP-DCV2-LR-L-A | 94304-XSW- MSP-DCV2- LR-L-A | \$ 2,055.20 | 6% | <i>\$1,946.38</i> |
| MSP NBD AHR RMA ONLY XSW-MSP-DCV2-M-A | 94304-XSW- MSP-DCV2-M- A | \$ 1,507.01 | 6% | <i>\$1,427.21</i> |
| MSP NBD AHR RMA ONLY XSW-MSP-DCV2-SR-L-A | 94304-XSW- MSP-DCV2- SR-L-A | \$ 2,055.20 | 6% | <i>\$1,946.38</i> |
| MSP 4HR AHR RMA Only 16173 | 94307-16173 | \$ 238.00 | 6% | <i>\$225.40</i> |
| MSP 4HR AHR RMA Only 16173T | 94307-16173T | \$ 493.00 | 6% | <i>\$466.90</i> |
| MSP 4HR AHR RMA Only 16177 | 94307-16177 | \$ 320.00 | 6% | <i>\$303.06</i> |
| MSP 4HR AHR RMA Only 16177T | 94307-16177T | \$ 591.00 | 6% | <i>\$559.71</i> |
| MSP 4HR AHR RMA Only 16179 | 94307-16179 | \$ 542.00 | 6% | <i>\$513.30</i> |
| MSP 4HR AHR RMA Only 16179T | 94307-16179T | \$ 895.00 | 6% | <i>\$847.61</i> |
| MSP 4HR AHR RMA Only 16530 | 94307-16530 | \$ 139.00 | 6% | <i>\$131.64</i> |
| MSP 4HR AHR RMA Only 16531 | 94307-16531 | \$ 192.00 | 6% | <i>\$181.83</i> |
| MSP 4HR AHR RMA Only 16531T | 94307-16531T | \$ 231.00 | 6% | <i>\$218.77</i> |
| MSP 4HR AHR RMA Only 16532 | 94307-16532 | \$ 192.00 | 6% | <i>\$181.83</i> |
| MSP 4HR AHR RMA Only 16532T | 94307-16532T | \$ 231.00 | 6% | <i>\$218.77</i> |
| MSP 4HR AHR RMA Only 16533 | 94307-16533 | \$ 271.00 | 6% | <i>\$256.65</i> |
| MSP 4HR AHR RMA Only 16533T | 94307-16533T | \$ 323.00 | 6% | <i>\$305.90</i> |
| MSP 4HR AHR RMA Only 16534 | 94307-16534 | \$ 288.00 | 6% | <i>\$272.75</i> |

| | | | | |
|--------------------------------------|------------------------|-------------|----|-------------------|
| MSP 4HR AHR RMA Only 16535 | 94307-16535 | \$ 428.00 | 6% | <i>\$405.34</i> |
| MSP 4HR AHR RMA Only 16535A | 94307-16535A | \$ 428.00 | 6% | <i>\$405.34</i> |
| MSP 4HR AHR RMA Only 16535T | 94307-16535T | \$ 515.00 | 6% | <i>\$487.73</i> |
| MSP 4HR AHR RMA Only 16703 | 94307-16703 | \$ 452.00 | 6% | <i>\$428.07</i> |
| MSP 4HR AHR RMA Only 16703T | 94307-16703T | \$ 728.00 | 6% | <i>\$689.45</i> |
| MSP 4HR AHR RMA Only 16704 | 94307-16704 | \$ 665.00 | 6% | <i>\$629.79</i> |
| MSP 4HR AHR RMA Only 16704T | 94307-16704T | \$ 1,051.00 | 6% | <i>\$995.35</i> |
| MSP 4HR AHR RMA Only 16790 | 94307-16790 | \$ 883.00 | 6% | <i>\$836.25</i> |
| MSP 4HR AHR RMA Only 16791 | 94307-16791 | \$ 1,163.00 | 6% | <i>\$1,101.42</i> |
| MSP 4HR AHR RMA Only 17300 | 94307-17300 | \$ 1,838.00 | 6% | <i>\$1,740.68</i> |
| MSP 4HR AHR RMA Only 17310 | 94307-17310 | \$ 1,665.00 | 6% | <i>\$1,576.84</i> |
| MSP 4HR AHR RMA Only 17310T | 94307-17310T | \$ 2,309.00 | 6% | <i>\$2,186.74</i> |
| MSP 4HR AHR RMA Only 17350 | 94307-17350 | \$ 1,704.00 | 6% | <i>\$1,613.77</i> |
| MSP 4HR AHR RMA Only 17360 | 94307-17360 | \$ 2,098.00 | 6% | <i>\$1,986.91</i> |
| MSP 4HR AHR RMA Only 4120-24MW-4Y | 94307-4120- 24MW-4Y | \$ 495.00 | 6% | <i>\$468.79</i> |
| MSP 4HR AHR RMA Only 4120-24MW-4Y | 94307-4120- 48MW-4Y | \$ 660.00 | 6% | <i>\$625.05</i> |
| MSP 4HR AHR RMA Only 4220-12P-4X | 94307-4220- 12P-4X | \$ 165.00 | 6% | <i>\$156.26</i> |
| MSP 4HR AHR RMA Only 4220-12T-4X | 94307-4220- 12T-4X | \$ 121.00 | 6% | <i>\$114.59</i> |
| MSP 4HR AHR RMA Only 4220-24P-4X | 94307-4220- 24P-4X | \$ 220.00 | 6% | <i>\$208.35</i> |
| MSP 4HR AHR RMA Only 4220-24T-4X | 94307-4220- 24T-4X | \$ 170.00 | 6% | <i>\$161.00</i> |
| MSP 4HR AHR RMA Only 4220-48P-4X | 94307-4220- 48P-4X | \$ 330.00 | 6% | <i>\$312.53</i> |

| | | | | |
|---|-----------------------------------|-----------|----|----------|
| MSP 4HR AHR RMA Only 4220-48T-4X | 94307-4220- 48T-4X | \$ 247.00 | 6% | \$233.92 |
| MSP 4HR AHR RMA Only 4220-4MW-20P-4X | 94307-4220- 4MW-20P-4X | \$ 302.00 | 6% | \$286.01 |
| MSP 4HR AHR RMA Only 4220-4MW-8P-4X | 94307-4220- 4MW-8P-4X | \$ 214.00 | 6% | \$202.67 |
| MSP 4HR AHR RMA Only 4220-8MW-40P-4X | 94307-4220- 8MW-40P-4X | \$ 440.00 | 6% | \$416.70 |
| MSP 4HR AHR RMA Only 4220-8X | 94307-4220-8X | \$ 231.00 | 6% | \$218.77 |
| MSP 4HR AHR RMA Only 5320-16P-4XE | 94307-5320- 16P-4XE | \$ 236.00 | 6% | \$223.50 |
| MSP 4HR AHR RMA Only 5320-16P-4XE-DC | 94307-5320- 16P-4XE-DC | \$ 284.00 | 6% | \$268.96 |
| MSP 4HR AHR RMA Only 5320-24P-8XE | 94307-5320- 24P-8XE | \$ 304.00 | 6% | \$287.90 |
| MSP 4HR AHR RMA Only 5320-24T-24S-4XE-XT | 94307-5320- 24T-24S-4XE- XT | \$ 357.00 | 6% | \$338.10 |
| MSP 4HR AHR RMA Only 5320-24T-4X-XT | 94307-5320- 24T-4X-XT | \$ 192.00 | 6% | \$181.83 |
| MSP 4HR AHR RMA Only 5320-24T-8XE | 94307-5320- 24T-8XE | \$ 228.00 | 6% | \$215.93 |
| MSP 4HR AHR RMA Only 5320-48P-8XE | 94307-5320- 48P-8XE | \$ 480.00 | 6% | \$454.58 |
| MSP 4HR AHR RMA Only 5320-48T-8XE | 94307-5320- 48T-8XE | \$ 337.00 | 6% | \$319.16 |
| MSP 4HR AHR RMA Only 5420F-16MW-32P-4XE | 94307-5420F- 16MW-32P- 4XE | \$ 794.00 | 6% | \$751.96 |
| MSP 4HR AHR RMA Only 5420F-16W-32P-4XE | 94307-5420F- 16W-32P-4XE | \$ 610.00 | 6% | \$577.70 |
| MSP 4HR AHR RMA Only 5420F-24P-4XE | 94307-5420F- 24P-4XE | \$ 379.00 | 6% | \$358.93 |
| MSP 4HR AHR RMA Only 5420F-24S-4XE | 94307-5420F- 24S-4XE | \$ 386.00 | 6% | \$365.56 |
| MSP 4HR AHR RMA Only 5420F-24T-4XE | 94307-5420F- 24T-4XE | \$ 316.00 | 6% | \$299.27 |
| MSP 4HR AHR RMA Only 5420F-48P-4XE | 94307-5420F- 48P-4XE | \$ 582.00 | 6% | \$551.18 |
| MSP 4HR AHR RMA Only 5420F-48P-4XL | 94307-5420F- 48P-4XL | \$ 610.00 | 6% | \$577.70 |

| | | | | |
|---|-----------------------------------|-----------|----|----------|
| MSP 4HR AHR RMA Only 5420F-48T-4XE | 94307-5420F- 48T-4XE | \$ 420.00 | 6% | \$397.76 |
| MSP 4HR AHR RMA Only 5420F-8W-16P-4XE | 94307-5420F- 8W-16P-4XE | \$ 400.00 | 6% | \$378.82 |
| MSP 4HR AHR RMA Only 5420M-16MW-32P-4YE | 94307-5420M- 16MW-32P- 4YE | \$ 779.00 | 6% | \$737.75 |
| MSP 4HR AHR RMA Only 5420M-24T-4YE | 94307-5420M- 24T-4YE | \$ 392.00 | 6% | \$371.24 |
| MSP 4HR AHR RMA Only 5420M-24W-4YE | 94307-5420M- 24W-4YE | \$ 394.00 | 6% | \$373.14 |
| MSP 4HR AHR RMA Only 5420M-48T-4YE | 94307-5420M- 48T-4YE | \$ 531.00 | 6% | \$502.88 |
| MSP 4HR AHR RMA Only 5420M-48W-4YE | 94307-5420M- 48W-4YE | \$ 626.00 | 6% | \$592.85 |
| MSP 4HR AHR RMA Only 5520-12MW-36W | 94307-5520- 12MW-36W | \$ 746.00 | 6% | \$706.50 |
| MSP 4HR AHR RMA Only 5520-24T | 94307-5520- 24T | \$ 331.00 | 6% | \$313.47 |
| MSP 4HR AHR RMA Only 5520-24T-ACDC-BASE | 94307-5520- 24T-ACDC- BASE | \$ 331.00 | 6% | \$313.47 |
| MSP 4HR AHR RMA Only 5520-24T-BASE | 94307-5520- 24T-BASE | \$ 331.00 | 6% | \$313.47 |
| MSP 4HR AHR RMA Only 5520-24W | 94307-5520- 24W | \$ 370.00 | 6% | \$350.41 |
| MSP 4HR AHR RMA Only 5520-24X | 94307-5520- 24X | \$ 912.00 | 6% | \$863.71 |
| MSP 4HR AHR RMA Only 5520-24X-ACDC-BASE | 94307-5520- 24X-ACDC- BASE | \$ 912.00 | 6% | \$863.71 |
| MSP 4HR AHR RMA Only 5520-24X-BASE | 94307-5520- 24X-BASE | \$ 912.00 | 6% | \$863.71 |
| MSP 4HR AHR RMA Only 5520-48SE | 94307-5520- 48SE | \$ 772.00 | 6% | \$731.12 |
| MSP 4HR AHR RMA Only 5520-48SE-ACDC-BASE | 94307-5520- 48SE-ACDC- BASE | \$ 772.00 | 6% | \$731.12 |
| MSP 4HR AHR RMA Only 5520-48SE-BASE | 94307-5520- 48SE-BASE | \$ 772.00 | 6% | \$731.12 |
| MSP 4HR AHR RMA Only 5520-48T | 94307-5520- 48T | \$ 509.00 | 6% | \$482.05 |

| | | | | |
|--|----------------------------------|-------------|----|------------|
| MSP 4HR AHR RMA Only 5520-48T-ACDC-BASE | 94307-5520- 48T-ACDC- BASE | \$ 509.00 | 6% | \$482.05 |
| MSP 4HR AHR RMA Only 5520-48T-BASE | 94307-5520- 48T-BASE | \$ 509.00 | 6% | \$482.05 |
| MSP 4HR AHR RMA Only 5520-48W | 94307-5520- 48W | \$ 610.00 | 6% | \$577.70 |
| MSP 4HR AHR RMA Only 5720-24MW | 94307-5720- 24MW | \$ 935.00 | 6% | \$885.49 |
| MSP 4HR AHR RMA Only 5720-24MXW | 94307-5720- 24MXW | \$ 1,265.00 | 6% | \$1,198.02 |
| MSP 4HR AHR RMA Only 5720-48MW | 94307-5720- 48MW | \$ 1,100.00 | 6% | \$1,041.76 |
| MSP 4HR AHR RMA Only 5720-48MXW | 94307-5720- 48MXW | \$ 1,595.00 | 6% | \$1,510.54 |
| MSP 4HR AHR RMA Only 7520-48XT-6C | 94307-7520- 48XT-6C | \$ 1,832.00 | 6% | \$1,735.00 |
| MSP 4HR AHR RMA Only 7520-48XT-6C-AC-F | 94307-7520- 48XT-6C-AC- F | \$ 1,832.00 | 6% | \$1,735.00 |
| MSP 4HR AHR RMA Only 7520-48XT-6C-AC-R | 94307-7520- 48XT-6C-AC- R | \$ 1,832.00 | 6% | \$1,735.00 |
| MSP 4HR AHR RMA Only 7520-48Y-8C | 94307-7520- 48Y-8C | \$ 1,722.00 | 6% | \$1,630.82 |
| MSP 4HR AHR RMA ONLY 7520-48Y-8C-AC-F | 94307-7520- 48Y-8C-AC-F | \$ 1,722.00 | 6% | \$1,630.82 |
| MSP 4HR AHR RMA Only 7520-48Y-8C-AC-R | 94307-7520- 48Y-8C-AC-R | \$ 1,722.00 | 6% | \$1,630.82 |
| MSP 4HR AHR RMA ONLY 7520-48YE-8CE | 94307-7520- 48YE-8CE | \$ 1,980.00 | 6% | \$1,875.16 |
| MSP 4HR AHR RMA ONLY 7520-48YE-8CE-AC-F | 94307-7520- 48YE-8CE-AC- F | \$ 1,980.00 | 6% | \$1,875.16 |
| MSP 4HR AHR RMA ONLY 7520-48YE-8CE-AC-R | 94307-7520- 48YE-8CE-AC- R | \$ 1,980.00 | 6% | \$1,875.16 |
| MSP 4HR AHR RMA Only 7720-32C | 94307-7720- 32C | \$ 2,090.00 | 6% | \$1,979.33 |
| MSP 4HR AHR RMA Only 7720-32C-AC-F | 94307-7720- 32C-AC-F | \$ 2,090.00 | 6% | \$1,979.33 |
| MSP 4HR AHR RMA Only 7720-32C-AC-R | 94307-7720- 32C-AC-R | \$ 2,090.00 | 6% | \$1,979.33 |

| | | | | |
|--------------------------------------|---------------------------|----------|----|----------------|
| MSP 4HR AHR RMA Only AP3000-WW | 94307-AP3000- WW | \$ 33.00 | 6% | <i>\$31.25</i> |
| MSP 4HR AHR RMA Only AP3000X-WW | 94307- AP3000X-WW | \$ 50.50 | 6% | <i>\$47.83</i> |
| MSP 4HR AHR RMA Only AP302W-CAN | 94307- AP302W-CAN | \$ 33.00 | 6% | <i>\$31.25</i> |
| MSP 4HR AHR RMA Only AP302W-EG | 94307- AP302W-EG | \$ 39.00 | 6% | <i>\$36.93</i> |
| MSP 4HR AHR RMA Only AP302W-FCC | 94307- AP302W-FCC | \$ 33.00 | 6% | <i>\$31.25</i> |
| MSP 4HR AHR RMA Only AP302W-WR | 94307- AP302W-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| MSP 4HR AHR RMA Only AP305C-1-CAN | 94307-AP305C- 1-CAN | \$ 53.00 | 6% | <i>\$50.19</i> |
| MSP 4HR AHR RMA Only AP305C-1-EG | 94307-AP305C- 1-EG | \$ 53.00 | 6% | <i>\$50.19</i> |
| MSP 4HR AHR RMA Only AP305C-1-FCC | 94307-AP305C- 1-FCC | \$ 53.00 | 6% | <i>\$50.19</i> |
| MSP 4HR AHR RMA Only AP305C-1-IL | 94307-AP305C- 1-IL | \$ 53.00 | 6% | <i>\$50.19</i> |
| MSP 4HR AHR RMA Only AP305C-1-WR | 94307-AP305C- 1-WR | \$ 53.00 | 6% | <i>\$50.19</i> |
| MSP 4HR AHR RMA Only AP305C-CAN | 94307-AP305C- CAN | \$ 59.00 | 6% | <i>\$55.88</i> |
| MSP 4HR AHR RMA Only AP305C-EG | 94307-AP305C- EG | \$ 59.00 | 6% | <i>\$55.88</i> |
| MSP 4HR AHR RMA Only AP305C-FCC | 94307-AP305C- FCC | \$ 59.00 | 6% | <i>\$55.88</i> |
| MSP 4HR AHR RMA Only AP305C-IL | 94307-AP305C- IL | \$ 59.00 | 6% | <i>\$55.88</i> |
| MSP 4HR AHR RMA Only AP305C-WR | 94307-AP305C- WR | \$ 59.00 | 6% | <i>\$55.88</i> |
| MSP 4HR AHR RMA Only AP305CX-CAN | 94307- AP305CX- CAN | \$ 59.00 | 6% | <i>\$55.88</i> |
| MSP 4HR AHR RMA Only AP305CX-FCC | 94307- AP305CX- FCC | \$ 59.00 | 6% | <i>\$55.88</i> |
| MSP 4HR AHR RMA Only AP305CX-IL | 94307- AP305CX-IL | \$ 59.00 | 6% | <i>\$55.88</i> |

| | | | | |
|---------------------------------------|-----------------------------|----------|----|---------|
| MSP 4HR AHR RMA Only AP305CX-WR | 94307- AP305CX-WR | \$ 59.00 | 6% | \$55.88 |
| MSP 4HR AHR RMA Only AP4000-1-WW | 94307-AP4000- 1-WW | \$ 66.00 | 6% | \$62.51 |
| MSP 4HR AHR RMA Only AP4000-WW | 94307-AP4000- WW | \$ 66.00 | 6% | \$62.51 |
| MSP 4HR AHR RMA Only AP410C-1-CAN | 94307-AP410C- 1-CAN | \$ 64.00 | 6% | \$60.61 |
| MSP 4HR AHR RMA Only AP410C-1-EG | 94307-AP410C- 1-EG | \$ 64.00 | 6% | \$60.61 |
| MSP 4HR AHR RMA Only AP410C-1-FCC | 94307-AP410C- 1-FCC | \$ 64.00 | 6% | \$60.61 |
| MSP 4HR AHR RMA Only AP410C-1-IL | 94307-AP410C- 1-IL | \$ 64.00 | 6% | \$60.61 |
| MSP 4HR AHR RMA Only AP410C-1-WR | 94307-AP410C- 1-WR | \$ 64.00 | 6% | \$60.61 |
| MSP 4HR AHR RMA Only AP410C-CAN | 94307-AP410C- CAN | \$ 71.00 | 6% | \$67.24 |
| MSP 4HR AHR RMA Only AP410C-EG | 94307-AP410C- EG | \$ 71.00 | 6% | \$67.24 |
| MSP 4HR AHR RMA Only AP410C-FCC | 94307-AP410C- FCC | \$ 71.00 | 6% | \$67.24 |
| MSP 4HR AHR RMA Only AP410C-IL | 94307-AP410C- IL | \$ 71.00 | 6% | \$67.24 |
| MSP 4HR AHR RMA Only AP410C-WR | 94307-AP410C- WR | \$ 71.00 | 6% | \$67.24 |
| MSP 4HR AHR RMA Only AP460C-CAN | 94307-AP460C- CAN | \$ 94.00 | 6% | \$89.02 |
| MSP 4HR AHR RMA Only AP460C-EG | 94307-AP460C- EG | \$ 94.00 | 6% | \$89.02 |
| MSP 4HR AHR RMA Only AP460C-FCC | 94307-AP460C- FCC | \$ 94.00 | 6% | \$89.02 |
| MSP 4HR AHR RMA Only AP460C-IL | 94307-AP460C- IL | \$ 94.00 | 6% | \$89.02 |
| MSP 4HR AHR RMA Only AP460C-WR | 94307-AP460C- WR | \$ 94.00 | 6% | \$89.02 |
| MSP 4HR AHR RMA Only AP460S12C-CAN | 94307- AP460S12C- CAN | \$ 94.00 | 6% | \$89.02 |

| | | | | |
|---------------------------------------|-----------------------------|-----------|----|-----------------|
| MSP 4HR AHR RMA Only AP460S12C-FCC | 94307- AP460S12C- FCC | \$ 94.00 | 6% | <i>\$89.02</i> |
| MSP 4HR AHR RMA Only AP460S12C-WR | 94307- AP460S12C- WR | \$ 94.00 | 6% | <i>\$89.02</i> |
| MSP 4HR AHR RMA Only AP460S6C-CAN | 94307- AP460S6C- CAN | \$ 94.00 | 6% | <i>\$89.02</i> |
| MSP 4HR AHR RMA Only AP460S6C-FCC | 94307- AP460S6C- FCC | \$ 94.00 | 6% | <i>\$89.02</i> |
| MSP 4HR AHR RMA Only AP460S6C-WR | 94307- AP460S6C- WR | \$ 94.00 | 6% | <i>\$89.02</i> |
| MSP 4HR AHR RMA Only AP5010-WW | 94307-AP5010- WW | \$ 124.00 | 6% | <i>\$117.43</i> |
| MSP 4HR AHR RMA Only AP5020-WW | 94307-AP5020- WW | \$ 167.93 | 6% | <i>\$159.04</i> |
| MSP 4HR AHR RMA Only AP5050D-WW | 94307- AP5050D-WW | \$ 315.00 | 6% | <i>\$298.32</i> |
| MSP 4HR AHR RMA Only AP5050U-WW | 94307- AP5050U-WW | \$ 239.00 | 6% | <i>\$226.34</i> |
| MSP 4HR AHR RMA Only AP510C-CAN | 94307-AP510C- CAN | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP 4HR AHR RMA Only AP510C-CE | 94307-AP510C- CE | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP 4HR AHR RMA Only AP510C-FCC | 94307-AP510C- FCC | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP 4HR AHR RMA Only AP510C-W | 94307-AP510C- W | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP 4HR AHR RMA Only AP510C-WW | 94307-AP510C- WW | \$ 112.00 | 6% | <i>\$106.07</i> |
| MSP 4HR AHR RMA Only AP510CX-CAN | 94307- AP510CX- CAN | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP 4HR AHR RMA Only AP510CX-CE | 94307- AP510CX-CE | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP 4HR AHR RMA Only AP510CX-FCC | 94307- AP510CX- FCC | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP 4HR AHR RMA Only AP510CX-W | 94307- AP510CX-W | \$ 92.00 | 6% | <i>\$87.13</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| MSP 4HR AHR RMA Only H35309 | 94307-H35309 | \$ 2,011.00 | 6% | <i>\$1,904.52</i> |
| MSP 4HR AHR RMA Only H35310 | 94307-H35310 | \$ 2,011.00 | 6% | <i>\$1,904.52</i> |
| MSP 4HR AHR RMA Only H35311 | 94307-H35311 | \$ 2,011.00 | 6% | <i>\$1,904.52</i> |
| MSP 4HR AHR RMA Only H35312 | 94307-H35312 | \$ 1,721.00 | 6% | <i>\$1,629.87</i> |
| MSP 4HR AHR RMA Only H35313 | 94307-H35313 | \$ 1,721.00 | 6% | <i>\$1,629.87</i> |
| MSP 4HR AHR RMA Only H35314 | 94307-H35314 | \$ 1,721.00 | 6% | <i>\$1,629.87</i> |
| MSP 4HR AHR RMA Only H35315 | 94307-H35315 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| MSP 4HR AHR RMA Only H35318 | 94307-H35318 | \$ 581.00 | 6% | <i>\$550.24</i> |
| MSP 4HR AHR RMA ONLY H35320 | 94307-H35320 | \$ 764.00 | 6% | <i>\$723.55</i> |
| MSP 4HR AHR RMA Only H35321 | 94307-H35321 | \$ 914.00 | 6% | <i>\$865.60</i> |
| MSP 4HR AHR RMA ONLY H35322 | 94307-H35322 | \$ 997.00 | 6% | <i>\$944.21</i> |
| MSP 4HR AHR RMA Only H35323 | 94307-H35323 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| MSP 4HR AHR RMA Only H35359 | 94307-H35359 | \$ 914.00 | 6% | <i>\$865.60</i> |
| MSP 4HR AHR RMA ONLY H35360 | 94307-H35360 | \$ 997.00 | 6% | <i>\$944.21</i> |
| MSP 4HR AHR RMA Only H35361 | 94307-H35361 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| MSP 4HR AHR RMA Only H35362 | 94307-H35362 | \$ 581.00 | 6% | <i>\$550.24</i> |
| MSP 4HR AHR RMA Only H35455 | 94307-H35455 | \$ 764.00 | 6% | <i>\$723.55</i> |
| MSP 4HR AHR RMA Only H35456 | 94307-H35456 | \$ 764.00 | 6% | <i>\$723.55</i> |
| MSP 4HR AHR RMA Only H35457 | 94307-H35457 | \$ 764.00 | 6% | <i>\$723.55</i> |
| MSP 4HR AHR RMA Only H35458 | 94307-H35458 | \$ 764.00 | 6% | <i>\$723.55</i> |
| MSP 4HR AHR RMA Only H35471 | 94307-H35471 | \$ 764.00 | 6% | <i>\$723.55</i> |

| | | | | |
|--|---|-------------|----|-------------------|
| MSP 4HR AHR RMA Only VSP49-12MXU-12XE | 94307- VSP4900- 12MXU-12XE | \$ 1,073.00 | 6% | <i>\$1,016.18</i> |
| MSP 4HR AHR RMA Only VSP49-12MXU-12XE-B | 94307- VSP4900- 12MXU-12XE- B1 | \$ 1,073.00 | 6% | <i>\$1,016.18</i> |
| MSP 4HR AHR RMA Only VSP4900-24S | 94307- VSP4900-24S | \$ 577.00 | 6% | <i>\$546.45</i> |
| MSP 4HR AHR RMA Only VSP4900-24S-B3 | 94307- VSP4900-24S- B3 | \$ 577.00 | 6% | <i>\$546.45</i> |
| MSP 4HR AHR RMA Only VSP4900-24XE | 94307- VSP4900- 24XE | \$ 1,110.00 | 6% | <i>\$1,051.23</i> |
| MSP 4HR AHR RMA Only VSP4900-24XE-B3 | 94307- VSP4900- 24XE-B3 | \$ 1,110.00 | 6% | <i>\$1,051.23</i> |
| MSP 4HR AHR RMA Only X435-24P-4S | 94307-X435- 24P-4S | \$ 141.00 | 6% | <i>\$133.53</i> |
| MSP 4HR AHR RMA Only X435-24T-4S | 94307-X435- 24T-4S | \$ 77.00 | 6% | <i>\$72.92</i> |
| MSP 4HR AHR RMA Only X435-8P-2T-W | 94307-X435- 8P-2T-W | \$ 77.00 | 6% | <i>\$72.92</i> |
| MSP 4HR AHR RMA Only X435-8P-4S | 94307-X435- 8P-4S | \$ 70.00 | 6% | <i>\$66.29</i> |
| MSP 4HR AHR RMA Only X435-8T-4S | 94307-X435- 8T-4S | \$ 56.00 | 6% | <i>\$53.03</i> |
| MSP 4HR AHR RMA ONLY X465-24MU | 94307-X465- 24MU | \$ 997.00 | 6% | <i>\$944.21</i> |
| MSP 4HR AHR RMA Only X465-24W | 94307-X465- 24W | \$ 581.00 | 6% | <i>\$550.24</i> |
| MSP 4HR AHR RMA ONLY X465-48P | 94307-X465- 48P | \$ 764.00 | 6% | <i>\$723.55</i> |
| MSP 4HR AHR RMA Only X465-48W | 94307-X465- 48W | \$ 914.00 | 6% | <i>\$865.60</i> |
| MSP 4HR AHR RMA Only X695-48Y-8C | 94307-X695- 48Y-8C | \$ 1,764.00 | 6% | <i>\$1,670.60</i> |
| MSP 4HR AHR RMA Only XR600 | 94307-XR600 | \$ 68.00 | 6% | <i>\$64.40</i> |
| MSP 4HR Onsite RMA Only 16173 | 94308-16173 | \$ 324.00 | 6% | <i>\$306.84</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| MSP 4HR Onsite RMA Only 16173T | 94308-16173T | \$ 672.00 | 6% | \$636.42 |
| MSP 4HR Onsite RMA Only 16177 | 94308-16177 | \$ 436.00 | 6% | \$412.91 |
| MSP 4HR Onsite RMA Only 16177T | 94308-16177T | \$ 806.00 | 6% | \$763.32 |
| MSP 4HR Onsite RMA Only 16179 | 94308-16179 | \$ 739.00 | 6% | \$699.87 |
| MSP 4HR Onsite RMA Only 16179T | 94308-16179T | \$ 1,221.00 | 6% | \$1,156.35 |
| MSP 4HR Onsite RMA Only 16530 | 94308-16530 | \$ 190.00 | 6% | \$179.94 |
| MSP 4HR Onsite RMA Only 16531 | 94308-16531 | \$ 262.00 | 6% | \$248.13 |
| MSP 4HR Onsite RMA Only 16531T | 94308-16531T | \$ 315.00 | 6% | \$298.32 |
| MSP 4HR Onsite RMA Only 16532 | 94308-16532 | \$ 262.00 | 6% | \$248.13 |
| MSP 4HR Onsite RMA Only 16532T | 94308-16532T | \$ 315.00 | 6% | \$298.32 |
| MSP 4HR Onsite RMA Only 16533 | 94308-16533 | \$ 369.00 | 6% | \$349.46 |
| MSP 4HR Onsite RMA Only 16533T | 94308-16533T | \$ 440.00 | 6% | \$416.70 |
| MSP 4HR Onsite RMA Only 16534 | 94308-16534 | \$ 393.00 | 6% | \$372.19 |
| MSP 4HR Onsite RMA Only 16535 | 94308-16535 | \$ 584.00 | 6% | \$553.08 |
| MSP 4HR Onsite RMA Only 16535A | 94308-16535A | \$ 584.00 | 6% | \$553.08 |
| MSP 4HR Onsite RMA Only 16535T | 94308-16535T | \$ 703.00 | 6% | \$665.78 |
| MSP 4HR Onsite RMA Only 16703 | 94308-16703 | \$ 616.00 | 6% | \$583.38 |
| MSP 4HR Onsite RMA Only 16703T | 94308-16703T | \$ 993.00 | 6% | \$940.42 |
| MSP 4HR Onsite RMA Only 16704 | 94308-16704 | \$ 907.00 | 6% | \$858.97 |
| MSP 4HR Onsite RMA Only 16704T | 94308-16704T | \$ 1,433.00 | 6% | \$1,357.12 |
| MSP 4HR Onsite RMA Only 16790 | 94308-16790 | \$ 1,204.00 | 6% | \$1,140.25 |

| | | | | |
|--|---------------------------|-------------|----|-------------------|
| MSP 4HR Onsite RMA Only 16791 | 94308-16791 | \$ 1,586.00 | 6% | <i>\$1,502.02</i> |
| MSP 4HR Onsite RMA Only 17300 | 94308-17300 | \$ 2,506.00 | 6% | <i>\$2,373.31</i> |
| MSP 4HR Onsite RMA Only 17310 | 94308-17310 | \$ 2,270.00 | 6% | <i>\$2,149.80</i> |
| MSP 4HR Onsite RMA Only 17310T | 94308-17310T | \$ 3,149.00 | 6% | <i>\$2,982.26</i> |
| MSP 4HR Onsite RMA Only 17350 | 94308-17350 | \$ 2,324.00 | 6% | <i>\$2,200.94</i> |
| MSP 4HR Onsite RMA Only 17360 | 94308-17360 | \$ 2,860.00 | 6% | <i>\$2,708.56</i> |
| MSP 4HR Onsite RMA Only 4120-24MW-4Y | 94308-4120- 24MW-4Y | \$ 675.00 | 6% | <i>\$639.26</i> |
| MSP 4HR Onsite RMA Only 4120-48MW-4Y | 94308-4120- 48MW-4Y | \$ 900.00 | 6% | <i>\$852.35</i> |
| MSP 4HR Onsite RMA Only 4220-12P-4X | 94308-4220- 12P-4X | \$ 225.00 | 6% | <i>\$213.09</i> |
| MSP 4HR Onsite RMA Only 4220-12T-4X | 94308-4220- 12T-4X | \$ 165.00 | 6% | <i>\$156.26</i> |
| MSP 4HR Onsite RMA Only 4220-24P-4X | 94308-4220- 24P-4X | \$ 300.00 | 6% | <i>\$284.12</i> |
| MSP 4HR Onsite RMA Only 4220-24T-4X | 94308-4220- 24T-4X | \$ 232.00 | 6% | <i>\$219.72</i> |
| MSP 4HR Onsite RMA Only 4220-48P-4X | 94308-4220- 48P-4X | \$ 450.00 | 6% | <i>\$426.17</i> |
| MSP 4HR Onsite RMA Only 4220-48T-4X | 94308-4220- 48T-4X | \$ 337.00 | 6% | <i>\$319.16</i> |
| MSP 4HR Onsite RMA Only 4220-4MW-20P-4X | 94308-4220- 4MW-20P-4X | \$ 412.00 | 6% | <i>\$390.18</i> |
| MSP 4HR Onsite RMA Only 4220-4MW-8P-4X | 94308-4220- 4MW-8P-4X | \$ 292.00 | 6% | <i>\$276.54</i> |
| MSP 4HR Onsite RMA Only 4220-8MW-40P-4X | 94308-4220- 8MW-40P-4X | \$ 600.00 | 6% | <i>\$568.23</i> |
| MSP 4HR Onsite RMA Only 4220-8X | 94308-4220-8X | \$ 315.00 | 6% | <i>\$298.32</i> |
| MSP 4HR Onsite RMA Only 5320-16P-4XE | 94308-5320- 16P-4XE | \$ 322.00 | 6% | <i>\$304.95</i> |
| MSP 4HR Onsite RMA Only 5320-16P-4XE-DC | 94308-5320- 16P-4XE-DC | \$ 387.00 | 6% | <i>\$366.51</i> |
| MSP 4HR Onsite RMA Only 5320-24P-8XE | 94308-5320- 24P-8XE | \$ 414.00 | 6% | <i>\$392.08</i> |

| | | | | |
|--|---------------------------|-------------|----|-------------------|
| MSP 4HR Ons RMA Only 5320-24T-24S-4XE-XT | 94308-5320-24T-24S-4XE-XT | \$ 487.00 | 6% | <i>\$461.21</i> |
| MSP 4HR Onsite RMA Only 5320-24T-4X-XT | 94308-5320-24T-4X-XT | \$ 262.00 | 6% | <i>\$248.13</i> |
| MSP 4HR Onsite RMA Only 5320-24T-8XE | 94308-5320-24T-8XE | \$ 311.00 | 6% | <i>\$294.53</i> |
| MSP 4HR Onsite RMA Only 5320-48P-8XE | 94308-5320-48P-8XE | \$ 654.00 | 6% | <i>\$619.37</i> |
| MSP 4HR Onsite RMA Only 5320-48T-8XE | 94308-5320-48T-8XE | \$ 460.00 | 6% | <i>\$435.64</i> |
| MSP 4HR Onsi RMA Only 5420F-16MW-32P-4XE | 94308-5420F-16MW-32P-4XE | \$ 1,082.00 | 6% | <i>\$1,024.71</i> |
| MSP 4HR Onsit RMA Only 5420F-16W-32P-4XE | 94308-5420F-16W-32P-4XE | \$ 832.00 | 6% | <i>\$787.95</i> |
| MSP 4HR Onsite RMA Only 5420F-24P-4XE | 94308-5420F-24P-4XE | \$ 516.00 | 6% | <i>\$488.68</i> |
| MSP 4HR Onsite RMA Only 5420F-24S-4XE | 94308-5420F-24S-4XE | \$ 526.00 | 6% | <i>\$498.15</i> |
| MSP 4HR Onsite RMA Only 5420F-24T-4XE | 94308-5420F-24T-4XE | \$ 430.00 | 6% | <i>\$407.23</i> |
| MSP 4HR Onsite RMA Only 5420F-48P-4XE | 94308-5420F-48P-4XE | \$ 794.00 | 6% | <i>\$751.96</i> |
| MSP 4HR Onsite RMA Only 5420F-48P-4XL | 94308-5420F-48P-4XL | \$ 832.00 | 6% | <i>\$787.95</i> |
| MSP 4HR Onsite RMA Only 5420F-48T-4XE | 94308-5420F-48T-4XE | \$ 573.00 | 6% | <i>\$542.66</i> |
| MSP 4HR Onsite RMA Only 5420F-8W-16P-4XE | 94308-5420F-8W-16P-4XE | \$ 546.00 | 6% | <i>\$517.09</i> |
| MSP 4HR Onsi RMA Only 5420M-16MW-32P-4YE | 94308-5420M-16MW-32P-4YE | \$ 1,062.00 | 6% | <i>\$1,005.77</i> |
| MSP 4HR Onsite RMA Only 5420M-24T-4YE | 94308-5420M-24T-4YE | \$ 535.00 | 6% | <i>\$506.67</i> |
| MSP 4HR Onsite RMA Only 5420M-24W-4YE | 94308-5420M-24W-4YE | \$ 537.00 | 6% | <i>\$508.57</i> |
| MSP 4HR Onsite RMA Only 5420M-48T-4YE | 94308-5420M-48T-4YE | \$ 723.00 | 6% | <i>\$684.72</i> |
| MSP 4HR Onsite RMA Only 5420M-48W-4YE | 94308-5420M-48W-4YE | \$ 854.00 | 6% | <i>\$808.78</i> |

| | | | | |
|--|-----------------------------------|-------------|----|-------------------|
| MSP 4HR Onsite RMA Only 5520-12MW-36W | 94308-5520- 12MW-36W | \$ 1,018.00 | 6% | <i>\$964.10</i> |
| MSP 4HR Onsite RMA Only 5520-24T | 94308-5520- 24T | \$ 451.00 | 6% | <i>\$427.12</i> |
| MSP 4HR Onsi RMA Only 5520- 24T-ACDC-BASE | 94308-5520- 24T-ACDC- BASE | \$ 409.00 | 6% | <i>\$387.34</i> |
| MSP 4HR Onsite RMA Only 5520-24T-BASE | 94308-5520- 24T-BASE | \$ 395.00 | 6% | <i>\$374.08</i> |
| MSP 4HR Onsite RMA Only 5520-24W | 94308-5520- 24W | \$ 505.00 | 6% | <i>\$478.26</i> |
| MSP 4HR Onsite RMA Only 5520-24X | 94308-5520- 24X | \$ 1,244.00 | 6% | <i>\$1,178.13</i> |
| MSP 4HR Ons RMA Only 5520- 24X-ACDC-BASE | 94308-5520- 24X-ACDC- BASE | \$ 1,244.00 | 6% | <i>\$1,178.13</i> |
| MSP 4HR Onsite RMA Only 5520-24X-BASE | 94308-5520- 24X-BASE | \$ 1,244.00 | 6% | <i>\$1,178.13</i> |
| MSP 4HR Onsite RMA Only 5520-48SE | 94308-5520- 48SE | \$ 1,052.00 | 6% | <i>\$996.30</i> |
| MSP 4HR Ons RMA Only 5520- 48SE-ACDC-BASE | 94308-5520- 48SE-ACDC- BASE | \$ 1,052.00 | 6% | <i>\$996.30</i> |
| MSP 4HR Onsite RMA Only 5520-48SE-BASE | 94308-5520- 48SE-BASE | \$ 1,052.00 | 6% | <i>\$996.30</i> |
| MSP 4HR Onsite RMA Only 5520-48T | 94308-5520- 48T | \$ 694.00 | 6% | <i>\$657.25</i> |
| MSP 4HR Ons RMA Only 5520- 48T-ACDC-BASE | 94308-5520- 48T-ACDC- BASE | \$ 694.00 | 6% | <i>\$657.25</i> |
| MSP 4HR Onsite RMA Only 5520-48T-BASE | 94308-5520- 48T-BASE | \$ 694.00 | 6% | <i>\$657.25</i> |
| MSP 4HR Onsite RMA Only 5520-48W | 94308-5520- 48W | \$ 832.00 | 6% | <i>\$787.95</i> |
| MSP 4HR Onsite RMA Only 5720-24MW | 94308-5720- 24MW | \$ 1,275.00 | 6% | <i>\$1,207.49</i> |
| MSP 4HR Onsite RMA Only 5720-24MXW | 94308-5720- 24MXW | \$ 1,725.00 | 6% | <i>\$1,633.66</i> |
| MSP 4HR Onsite RMA Only 5720-48MW | 94308-5720- 48MW | \$ 1,500.00 | 6% | <i>\$1,420.58</i> |
| MSP 4HR Onsite RMA Only 5720-48MXW | 94308-5720- 48MXW | \$ 2,175.00 | 6% | <i>\$2,059.83</i> |

| | | | | |
|---|----------------------------------|-------------|----|------------|
| MSP 4HR Onsite RMA Only 7520-48XT-6C | 94308-7520- 48XT-6C | \$ 2,498.00 | 6% | \$2,365.73 |
| MSP 4HR Onsit RMA Only 7520-48XT-6C-AC-F | 94308-7520- 48XT-6C-AC- F | \$ 2,498.00 | 6% | \$2,365.73 |
| MSP 4HR Onsit RMA Only 7520-48XT-6C-AC-R | 94308-7520- 48XT-6C-AC- R | \$ 2,498.00 | 6% | \$2,365.73 |
| MSP 4HR Onsite RMA Only 7520-48Y-8C | 94308-7520- 48Y-8C | \$ 2,348.00 | 6% | \$2,223.67 |
| MSP 4HR Onsite RMA ONLY 7520-48Y-8C-AC-F | 94308-7520- 48Y-8C-AC-F | \$ 2,348.00 | 6% | \$2,223.67 |
| MSP 4HR Onsite RMA Only 7520-48Y-8C-AC-R | 94308-7520- 48Y-8C-AC-R | \$ 2,348.00 | 6% | \$2,223.67 |
| MSP 4HR Onsite RMA ONLY 7520-48YE-8CE | 94308-7520- 48YE-8CE | \$ 2,700.00 | 6% | \$2,557.04 |
| MSP 4HR Onsi RMA ONLY 7520-48YE-8CE-AC-F | 94308-7520- 48YE-8CE-AC- F | \$ 2,700.00 | 6% | \$2,557.04 |
| MSP 4HR Onsi RMA ONLY 7520-48YE-8CE-AC-R | 94308-7520- 48YE-8CE-AC- R | \$ 2,700.00 | 6% | \$2,557.04 |
| MSP 4HR Onsite RMA Only 7720-32C | 94308-7720- 32C | \$ 2,850.00 | 6% | \$2,699.09 |
| MSP 4HR Onsite RMA Only 7720-32C-AC-F | 94308-7720- 32C-AC-F | \$ 2,850.00 | 6% | \$2,699.09 |
| MSP 4HR Onsite RMA Only 7720-32C-AC-R | 94308-7720- 32C-AC-R | \$ 2,850.00 | 6% | \$2,699.09 |
| MSP 4HR Onsite RMA Only AP3000-WW | 94308-AP3000- WW | \$ 60.00 | 6% | \$56.82 |
| MSP 4HR Onsite RMA Only AP3000X-WW | 94308- AP3000X-WW | \$ 85.00 | 6% | \$80.50 |
| MSP 4HR Onsite RMA Only AP302W-CAN | 94308- AP302W-CAN | \$ 48.00 | 6% | \$45.46 |
| MSP 4HR Onsite RMA Only AP302W-EG | 94308- AP302W-EG | \$ 56.00 | 6% | \$53.03 |
| MSP 4HR Onsite RMA Only AP302W-FCC | 94308- AP302W-FCC | \$ 48.00 | 6% | \$45.46 |
| MSP 4HR Onsite RMA Only AP302W-WR | 94308- AP302W-WR | \$ 45.00 | 6% | \$42.62 |
| MSP 4HR Onsite RMA Only AP305C-1-CAN | 94308-AP305C- 1-CAN | \$ 75.00 | 6% | \$71.03 |

| | | | | |
|---|---------------------------|----------|----|----------------|
| MSP 4HR Onsite RMA Only AP305C-1-EG | 94308-AP305C- 1-EG | \$ 75.00 | 6% | <i>\$71.03</i> |
| MSP 4HR Onsite RMA Only AP305C-1-FCC | 94308-AP305C- 1-FCC | \$ 75.00 | 6% | <i>\$71.03</i> |
| MSP 4HR Onsite RMA Only AP305C-1-IL | 94308-AP305C- 1-IL | \$ 75.00 | 6% | <i>\$71.03</i> |
| MSP 4HR Onsite RMA Only AP305C-1-WR | 94308-AP305C- 1-WR | \$ 75.00 | 6% | <i>\$71.03</i> |
| MSP 4HR Onsite RMA Only AP305C-CAN | 94308-AP305C- CAN | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305C-EG | 94308-AP305C- EG | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305C-FCC | 94308-AP305C- FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305C-IL | 94308-AP305C- IL | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305C-WR | 94308-AP305C- WR | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305CX-CAN | 94308- AP305CX- CAN | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305CX-FCC | 94308- AP305CX- FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305CX-IL | 94308- AP305CX-IL | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP305CX-WR | 94308- AP305CX-WR | \$ 82.00 | 6% | <i>\$77.66</i> |
| MSP 4HR Onsite RMA Only AP4000-1-WW | 94308-AP4000- 1-WW | \$ 95.00 | 6% | <i>\$89.97</i> |
| MSP 4HR Onsite RMA Only AP4000-WW | 94308-AP4000- WW | \$ 95.00 | 6% | <i>\$89.97</i> |
| MSP 4HR Onsite RMA Only AP410C-1-CAN | 94308-AP410C- 1-CAN | \$ 88.00 | 6% | <i>\$83.34</i> |
| MSP 4HR Onsite RMA Only AP410C-1-EG | 94308-AP410C- 1-EG | \$ 88.00 | 6% | <i>\$83.34</i> |
| MSP 4HR Onsite RMA Only AP410C-1-FCC | 94308-AP410C- 1-FCC | \$ 88.00 | 6% | <i>\$83.34</i> |
| MSP 4HR Onsite RMA Only AP410C-1-IL | 94308-AP410C- 1-IL | \$ 88.00 | 6% | <i>\$83.34</i> |

| | | | | |
|---------------------------------------|---------------------|-----------|----|-----------------|
| MSP 4HR Onsite RMA Only AP410C-1-WR | 94308-AP410C-1-WR | \$ 88.00 | 6% | <i>\$83.34</i> |
| MSP 4HR Onsite RMA Only AP410C-CAN | 94308-AP410C-CAN | \$ 97.00 | 6% | <i>\$91.86</i> |
| MSP 4HR Onsite RMA Only AP410C-EG | 94308-AP410C-EG | \$ 97.00 | 6% | <i>\$91.86</i> |
| MSP 4HR Onsite RMA Only AP410C-FCC | 94308-AP410C-FCC | \$ 97.00 | 6% | <i>\$91.86</i> |
| MSP 4HR Onsite RMA Only AP410C-IL | 94308-AP410C-IL | \$ 97.00 | 6% | <i>\$91.86</i> |
| MSP 4HR Onsite RMA Only AP410C-WR | 94308-AP410C-WR | \$ 97.00 | 6% | <i>\$91.86</i> |
| MSP 4HR Onsite RMA Only AP460C-CAN | 94308-AP460C-CAN | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460C-EG | 94308-AP460C-EG | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460C-FCC | 94308-AP460C-FCC | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460C-IL | 94308-AP460C-IL | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460C-WR | 94308-AP460C-WR | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460S12C-CAN | 94308-AP460S12C-CAN | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460S12C-FCC | 94308-AP460S12C-FCC | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460S12C-WR | 94308-AP460S12C-WR | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460S6C-CAN | 94308-AP460S6C-CAN | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460S6C-FCC | 94308-AP460S6C-FCC | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP460S6C-WR | 94308-AP460S6C-WR | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP 4HR Onsite RMA Only AP5010-WW | 94308-AP5010-WW | \$ 170.00 | 6% | <i>\$161.00</i> |

| | | | | |
|--|---------------------------|-------------|----|------------|
| MSP 4HR Onsite RMA Only AP5050D-WW | 94308- AP5050D-WW | \$ 420.00 | 6% | \$397.76 |
| MSP 4HR Onsite RMA Only AP5050U-WW | 94308- AP5050U-WW | \$ 321.00 | 6% | \$304.00 |
| MSP 4HR Onsite RMA Only AP510C-CAN | 94308-AP510C- CAN | \$ 123.00 | 6% | \$116.49 |
| MSP 4HR Onsite RMA Only AP510C-CE | 94308-AP510C- CE | \$ 123.00 | 6% | \$116.49 |
| MSP 4HR Onsite RMA Only AP510C-FCC | 94308-AP510C- FCC | \$ 123.00 | 6% | \$116.49 |
| MSP 4HR Onsite RMA Only AP510C-W | 94308-AP510C- W | \$ 123.00 | 6% | \$116.49 |
| MSP 4HR Onsite RMA Only AP510C-WW | 94308-AP510C- WW | \$ 147.00 | 6% | \$139.22 |
| MSP 4HR Onsite RMA Only AP510CX-CAN | 94308- AP510CX- CAN | \$ 123.00 | 6% | \$116.49 |
| MSP 4HR Onsite RMA Only AP510CX-CE | 94308- AP510CX-CE | \$ 123.00 | 6% | \$116.49 |
| MSP 4HR Onsite RMA Only AP510CX-FCC | 94308- AP510CX- FCC | \$ 123.00 | 6% | \$116.49 |
| MSP 4HR Onsite RMA Only AP510CX-W | 94308- AP510CX-W | \$ 122.00 | 6% | \$115.54 |
| MSP 4HR Onsite RMA Only H35309 | 94308-H35309 | \$ 2,743.00 | 6% | \$2,597.76 |
| MSP 4HR Onsite RMA Only H35310 | 94308-H35310 | \$ 2,743.00 | 6% | \$2,597.76 |
| MSP 4HR Onsite RMA Only H35311 | 94308-H35311 | \$ 2,743.00 | 6% | \$2,597.76 |
| MSP 4HR Onsite RMA Only H35312 | 94308-H35312 | \$ 2,347.00 | 6% | \$2,222.73 |
| MSP 4HR Onsite RMA Only H35313 | 94308-H35313 | \$ 2,347.00 | 6% | \$2,222.73 |
| MSP 4HR Onsite RMA Only H35314 | 94308-H35314 | \$ 2,347.00 | 6% | \$2,222.73 |
| MSP 4HR Onsite RMA Only H35315 | 94308-H35315 | \$ 1,572.00 | 6% | \$1,488.76 |
| MSP 4HR Onsite RMA Only X465-24W-B2 | 94308-H35318 | \$ 792.00 | 6% | \$750.06 |
| MSP 4HR Onsite RMA ONLY H35320 | 94308-H35320 | \$ 1,042.00 | 6% | \$986.83 |

| | | | | |
|--|-----------------------------|-------------|----|-------------------|
| MSP 4HR Onsite RMA Only H353212 | 94308-H35321 | \$ 1,246.00 | 6% | <i>\$1,180.02</i> |
| MSP 4HR Onsite RMA ONLY H35322 | 94308-H35322 | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |
| MSP 4HR Onsite RMA Only H35323 | 94308-H35323 | \$ 1,572.00 | 6% | <i>\$1,488.76</i> |
| MSP 4HR Onsite RMA Only H35359 | 94308-H35359 | \$ 1,246.00 | 6% | <i>\$1,180.02</i> |
| MSP 4HR Onsite RMA ONLY H35360 | 94308-H35360 | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |
| MSP 4HR Onsite RMA Only H35361 | 94308-H35361 | \$ 1,572.00 | 6% | <i>\$1,488.76</i> |
| MSP 4HR Onsite RMA Only H35362 | 94308-H35362 | \$ 792.00 | 6% | <i>\$750.06</i> |
| MSP 4HR Onsite RMA Only H35455 | 94308-H35455 | \$ 1,042.00 | 6% | <i>\$986.83</i> |
| MSP 4HR Onsite RMA Only H35456 | 94308-H35456 | \$ 1,042.00 | 6% | <i>\$986.83</i> |
| MSP 4HR Onsite RMA Only H35457 | 94308-H35457 | \$ 1,042.00 | 6% | <i>\$986.83</i> |
| MSP 4HR Onsite RMA Only H35458 | 94308-H35458 | \$ 1,042.00 | 6% | <i>\$986.83</i> |
| MSP 4HR Onsite RMA Only H35471 | 94308-H35471 | \$ 1,042.00 | 6% | <i>\$986.83</i> |
| MSP 4HR Onsite RMA Only VSP49-12MXU-12XE | 94308-VSP4900-12MXU-12XE | \$ 1,464.00 | 6% | <i>\$1,386.48</i> |
| MSP 4HR Onsi RMA Only VSP49-12MXU-12XE-B | 94308-VSP4900-12MXU-12XE-B1 | \$ 1,464.00 | 6% | <i>\$1,386.48</i> |
| MSP 4HR Onsite RMA Only VSP4900-24S | 94308-VSP4900-24S | \$ 787.00 | 6% | <i>\$745.33</i> |
| MSP 4HR Onsite RMA Only VSP4900-24S-B3 | 94308-VSP4900-24S-B3 | \$ 787.00 | 6% | <i>\$745.33</i> |
| MSP 4HR Onsite RMA Only VSP4900-24XE | 94308-VSP4900-24XE | \$ 1,514.00 | 6% | <i>\$1,433.83</i> |
| MSP 4HR Onsite RMA Only VSP4900-24XE-B3 | 94308-VSP4900-24XE-B3 | \$ 1,514.00 | 6% | <i>\$1,433.83</i> |

| | | | | |
|--------------------------------------|--------------------|-------------|----|-------------------|
| MSP 4HR Onsite RMA Only X435-24P-4S | 94308-X435-24P-4S | \$ 192.00 | 6% | <i>\$181.83</i> |
| MSP 4HR Onsite RMA Only X435-24T-4S | 94308-X435-24T-4S | \$ 105.00 | 6% | <i>\$99.44</i> |
| MSP 4HR Onsite RMA Only X435-8P-2T-W | 94308-X435-8P-2T-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| MSP 4HR Onsite RMA Only X435-8P-4S | 94308-X435-8P-4S | \$ 96.00 | 6% | <i>\$90.92</i> |
| MSP 4HR Onsite RMA Only X435-8T-4S | 94308-X435-8T-4S | \$ 77.00 | 6% | <i>\$72.92</i> |
| MSP 4HR Onsite RMA ONLY X465-24MU | 94308-X465-24MU | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |
| MSP 4HR Onsite RMA Only X465-24W | 94308-X465-24W | \$ 792.00 | 6% | <i>\$750.06</i> |
| MSP 4HR Onsite RMA ONLY X465-48P | 94308-X465-48P | \$ 1,042.00 | 6% | <i>\$986.83</i> |
| MSP 4HR Onsite RMA Only X465-48W | 94308-X465-48W | \$ 1,246.00 | 6% | <i>\$1,180.02</i> |
| MSP 4HR Onsite RMA Only X695-48Y-8C | 94308-X695-48Y-8C | \$ 2,406.00 | 6% | <i>\$2,278.60</i> |
| MSP 4HR Onsite RMA Only XR600 | 94308-XR600 | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP NBD Onsite RMA Only 16173 | 94311-16173 | \$ 130.00 | 6% | <i>\$123.12</i> |
| MSP NBD Onsite RMA Only 16173T | 94311-16173T | \$ 269.00 | 6% | <i>\$254.76</i> |
| MSP NBD Onsite RMA Only 16177 | 94311-16177 | \$ 175.00 | 6% | <i>\$165.73</i> |
| MSP NBD Onsite RMA Only 16177T | 94311-16177T | \$ 322.00 | 6% | <i>\$304.95</i> |
| MSP NBD Onsite RMA Only 16179 | 94311-16179 | \$ 296.00 | 6% | <i>\$280.33</i> |
| MSP NBD Onsite RMA Only 16179T | 94311-16179T | \$ 488.00 | 6% | <i>\$462.16</i> |
| MSP NBD Onsite RMA Only 16530 | 94311-16530 | \$ 76.00 | 6% | <i>\$71.98</i> |
| MSP NBD Onsite RMA Only 16531 | 94311-16531 | \$ 105.00 | 6% | <i>\$99.44</i> |
| MSP NBD Onsite RMA Only 16531T | 94311-16531T | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP NBD Onsite RMA Only 16532 | 94311-16532 | \$ 105.00 | 6% | <i>\$99.44</i> |

| | | | | |
|---|------------------------|-------------|----|-------------------|
| MSP NBD Onsite RMA Only 16532T | 94311-16532T | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP NBD Onsite RMA Only 16533 | 94311-16533 | \$ 148.00 | 6% | <i>\$140.16</i> |
| MSP NBD Onsite RMA Only 16533T | 94311-16533T | \$ 176.00 | 6% | <i>\$166.68</i> |
| MSP NBD Onsite RMA Only 16534 | 94311-16534 | \$ 157.00 | 6% | <i>\$148.69</i> |
| MSP NBD Onsite RMA Only 16535 | 94311-16535 | \$ 233.00 | 6% | <i>\$220.66</i> |
| MSP NBD Onsite RMA Only 16535A | 94311-16535A | \$ 233.00 | 6% | <i>\$220.66</i> |
| MSP NBD Onsite RMA Only 16535T | 94311-16535T | \$ 281.00 | 6% | <i>\$266.12</i> |
| MSP NBD Onsite RMA Only 16703 | 94311-16703 | \$ 246.00 | 6% | <i>\$232.97</i> |
| MSP NBD Onsite RMA Only 16703T | 94311-16703T | \$ 397.00 | 6% | <i>\$375.98</i> |
| MSP NBD Onsite RMA Only 16704 | 94311-16704 | \$ 363.00 | 6% | <i>\$343.78</i> |
| MSP NBD Onsite RMA Only 16704T | 94311-16704T | \$ 573.00 | 6% | <i>\$542.66</i> |
| MSP NBD Onsite RMA Only 16790 | 94311-16790 | \$ 482.00 | 6% | <i>\$456.48</i> |
| MSP NBD Onsite RMA Only 16791 | 94311-16791 | \$ 634.00 | 6% | <i>\$600.43</i> |
| MSP NBD Onsite RMA Only 17300 | 94311-17300 | \$ 1,002.00 | 6% | <i>\$948.94</i> |
| MSP NBD Onsite RMA Only 17310 | 94311-17310 | \$ 908.00 | 6% | <i>\$859.92</i> |
| MSP NBD Onsite RMA Only 17310T | 94311-17310T | \$ 1,259.00 | 6% | <i>\$1,192.34</i> |
| MSP NBD Onsite RMA Only 17350 | 94311-17350 | \$ 930.00 | 6% | <i>\$880.76</i> |
| MSP NBD Onsite RMA Only 17360 | 94311-17360 | \$ 1,144.00 | 6% | <i>\$1,083.43</i> |
| MSP NBD Onsite RMA Only 4120-24MW-4Y | 94311-4120- 24MW-4Y | \$ 270.00 | 6% | <i>\$255.70</i> |
| MSP NBD Onsite RMA Only 4120-48MW-4Y | 94311-4120- 48MW-4Y | \$ 360.00 | 6% | <i>\$340.94</i> |
| MSP NBD Onsite RMA Only 4220-12P-4X | 94311-4220- 12P-4X | \$ 90.00 | 6% | <i>\$85.23</i> |

| | | | | |
|--|-----------------------------------|-----------|----|-----------------|
| MSP NBD Onsite RMA Only 4220-12T-4X | 94311-4220- 12T-4X | \$ 66.00 | 6% | <i>\$62.51</i> |
| MSP NBD Onsite RMA Only 4220-24P-4X | 94311-4220- 24P-4X | \$ 120.00 | 6% | <i>\$113.65</i> |
| MSP NBD Onsite RMA Only 4220-24T-4X | 94311-4220- 24T-4X | \$ 93.00 | 6% | <i>\$88.08</i> |
| MSP NBD Onsite RMA Only 4220-48P-4X | 94311-4220- 48P-4X | \$ 180.00 | 6% | <i>\$170.47</i> |
| MSP NBD Onsite RMA Only 4220-48T-4X | 94311-4220- 48T-4X | \$ 135.00 | 6% | <i>\$127.85</i> |
| MSP NBD Onsite RMA Only 4220-4MW-20P-4X | 94311-4220- 4MW-20P-4X | \$ 165.00 | 6% | <i>\$156.26</i> |
| MSP NBD Onsite RMA Only 4220-4MW-8P-4X | 94311-4220- 4MW-8P-4X | \$ 117.00 | 6% | <i>\$110.80</i> |
| MSP NBD Onsite RMA Only 4220-8MW-40P-4X | 94311-4220- 8MW-40P-4X | \$ 240.00 | 6% | <i>\$227.29</i> |
| MSP NBD Onsite RMA Only 4220-8X | 94311-4220-8X | \$ 126.00 | 6% | <i>\$119.33</i> |
| MSP NBD Onsite RMA Only 5320-16P-4XE | 94311-5320- 16P-4XE | \$ 129.00 | 6% | <i>\$122.17</i> |
| MSP NBD Onsite RMA Only 5320-16P-4XE-DC | 94311-5320- 16P-4XE-DC | \$ 155.00 | 6% | <i>\$146.79</i> |
| MSP NBD Onsite RMA Only 5320-24P-8XE | 94311-5320- 24P-8XE | \$ 166.00 | 6% | <i>\$157.21</i> |
| MSP NBD Onsite RMA Only 5320-24T-24S-4XE-XT | 94311-5320- 24T-24S-4XE- XT | \$ 195.00 | 6% | <i>\$184.67</i> |
| MSP NBD Onsite RMA Only 5320-24T-4X-XT | 94311-5320- 24T-4X-XT | \$ 105.00 | 6% | <i>\$99.44</i> |
| MSP NBD Onsite RMA Only 5320-24T-8XE | 94311-5320- 24T-8XE | \$ 124.00 | 6% | <i>\$117.43</i> |
| MSP NBD Onsite RMA Only 5320-48P-8XE | 94311-5320- 48P-8XE | \$ 262.00 | 6% | <i>\$248.13</i> |
| MSP NBD Onsite RMA Only 5320-48T-8XE | 94311-5320- 48T-8XE | \$ 184.00 | 6% | <i>\$174.26</i> |
| MSP NBD Onsite RMA Only 5420F-16MW-32P-4XE | 94311-5420F- 16MW-32P- 4XE | \$ 433.00 | 6% | <i>\$410.07</i> |
| MSP NBD Onsite RMA Only 5420F-16W-32P-4XE | 94311-5420F- 16W-32P-4XE | \$ 333.00 | 6% | <i>\$315.37</i> |
| MSP NBD Onsite RMA Only 5420F-24P-4XE | 94311-5420F- 24P-4XE | \$ 207.00 | 6% | <i>\$196.04</i> |

| | | | | |
|---|----------------------------------|-----------|----|-----------------|
| MSP NBD Onsite RMA Only 5420F-24S-4XE | 94311-5420F- 24S-4XE | \$ 210.00 | 6% | <i>\$198.88</i> |
| MSP NBD Onsite RMA Only 5420F-24T-4XE | 94311-5420F- 24T-4XE | \$ 172.00 | 6% | <i>\$162.89</i> |
| MSP NBD Onsite RMA Only 5420F-48P-4XE | 94311-5420F- 48P-4XE | \$ 318.00 | 6% | <i>\$301.16</i> |
| MSP NBD Onsite RMA Only 5420F-48P-4XL | 94311-5420F- 48P-4XL | \$ 333.00 | 6% | <i>\$315.37</i> |
| MSP NBD Onsite RMA Only 5420F-48T-4XE | 94311-5420F- 48T-4XE | \$ 229.00 | 6% | <i>\$216.87</i> |
| MSP NBD Onsite RMA Only 5420F-8W-16P-4XE | 94311-5420F- 8W-16P-4XE | \$ 218.00 | 6% | <i>\$206.46</i> |
| MSP NBD Onsi RMA Only 5420M-16MW-32P-4YE | 94311-5420M- 16MW-32P- 4YE | \$ 425.00 | 6% | <i>\$402.50</i> |
| MSP NBD Onsite RMA Only 5420M-24T-4YE | 94311-5420M- 24T-4YE | \$ 214.00 | 6% | <i>\$202.67</i> |
| MSP NBD Onsite RMA Only 5420M-24W-4YE | 94311-5420M- 24W-4YE | \$ 215.00 | 6% | <i>\$203.62</i> |
| MSP NBD Onsite RMA Only 5420M-48T-4YE | 94311-5420M- 48T-4YE | \$ 289.00 | 6% | <i>\$273.70</i> |
| MSP NBD Onsite RMA Only 5420M-48W-4YE | 94311-5420M- 48W-4YE | \$ 341.00 | 6% | <i>\$322.94</i> |
| MSP NBD Onsite RMA Only 5520-12MW-36W | 94311-5520- 12MW-36W | \$ 407.00 | 6% | <i>\$385.45</i> |
| MSP NBD Onsite RMA Only 5520-24T | 94311-5520- 24T | \$ 180.00 | 6% | <i>\$170.47</i> |
| MSP NBD Onsi RMA Only 5520-24T-ACDC-BASE | 94311-5520- 24T-ACDC- BASE | \$ 180.00 | 6% | <i>\$170.47</i> |
| MSP NBD Onsite RMA Only 5520-24T-BASE | 94311-5520- 24T-BASE | \$ 180.00 | 6% | <i>\$170.47</i> |
| MSP NBD Onsite RMA Only 5520-24W | 94311-5520- 24W | \$ 202.00 | 6% | <i>\$191.30</i> |
| MSP NBD Onsite RMA Only 5520-24X | 94311-5520- 24X | \$ 498.00 | 6% | <i>\$471.63</i> |
| MSP NBD Onsi RMA Only 5520-24X-ACDC-BASE | 94311-5520- 24X-ACDC- BASE | \$ 498.00 | 6% | <i>\$471.63</i> |
| MSP NBD Onsite RMA Only 5520-24X-BASE | 94311-5520- 24X-BASE | \$ 498.00 | 6% | <i>\$471.63</i> |

| | | | | |
|--|-----------------------------------|-------------|----|-------------------|
| MSP NBD Onsite RMA Only 5520-48SE | 94311-5520- 48SE | \$ 421.00 | 6% | <i>\$398.71</i> |
| MSP NBD Ons RMA Only 5520- 48SE-ACDC-BASE | 94311-5520- 48SE-ACDC- BASE | \$ 421.00 | 6% | <i>\$398.71</i> |
| MSP NBD Onsite RMA Only 5520-48SE-BASE | 94311-5520- 48SE-BASE | \$ 421.00 | 6% | <i>\$398.71</i> |
| MSP NBD Onsite RMA Only 5520-48T | 94311-5520- 48T | \$ 278.00 | 6% | <i>\$263.28</i> |
| MSP NBD Onsi RMA Only 5520-48T-ACDC-BASE | 94311-5520- 48T-ACDC- BASE | \$ 278.00 | 6% | <i>\$263.28</i> |
| MSP NBD Onsite RMA Only 5520-48T-BASE | 94311-5520- 48T-BASE | \$ 278.00 | 6% | <i>\$263.28</i> |
| MSP NBD Onsite RMA Only 5520-48W | 94311-5520- 48W | \$ 333.00 | 6% | <i>\$315.37</i> |
| MSP NBD Onsite RMA Only 5720-24MW | 94311-5720- 24MW | \$ 510.00 | 6% | <i>\$483.00</i> |
| MSP NBD Onsite RMA Only 5720-24MXW | 94311-5720- 24MXW | \$ 690.00 | 6% | <i>\$653.46</i> |
| MSP NBD Onsite RMA Only 5720-48MW | 94311-5720- 48MW | \$ 600.00 | 6% | <i>\$568.23</i> |
| MSP NBD Onsite RMA Only 5720-48MXW | 94311-5720- 48MXW | \$ 870.00 | 6% | <i>\$823.93</i> |
| MSP NBD Onsite RMA Only 7520-48XT-6C | 94311-7520- 48XT-6C | \$ 999.00 | 6% | <i>\$946.10</i> |
| MSP NBD Onsit RMA Only 7520-48XT-6C-AC-F | 94311-7520- 48XT-6C-AC- F | \$ 999.00 | 6% | <i>\$946.10</i> |
| MSP NBD Onsit RMA Only 7520-48XT-6C-AC-R | 94311-7520- 48XT-6C-AC- R | \$ 999.00 | 6% | <i>\$946.10</i> |
| MSP NBD Onsite RMA Only 7520-48Y-8C | 94311-7520- 48Y-8C | \$ 939.00 | 6% | <i>\$889.28</i> |
| MSP NBD Onsite RMA ONLY 7520-48Y-8C-AC-F | 94311-7520- 48Y-8C-AC-F | \$ 939.00 | 6% | <i>\$889.28</i> |
| MSP NBD Onsite RMA Only 7520-48Y-8C-AC-R | 94311-7520- 48Y-8C-AC-R | \$ 939.00 | 6% | <i>\$889.28</i> |
| MSP NBD Onsite RMA ONLY 7520-48YE-8CE | 94311-7520- 48YE-8CE | \$ 1,080.00 | 6% | <i>\$1,022.81</i> |
| MSP NBD Onsi RMA ONLY 7520-48YE-8CE-AC-F | 94311-7520- 48YE-8CE-AC- F | \$ 1,080.00 | 6% | <i>\$1,022.81</i> |

| | | | | |
|---|----------------------------------|-------------|----|-------------------|
| MSP NBD Onsi RMA ONLY 7520-48YE-8CE-AC-R | 94311-7520- 48YE-8CE-AC- R | \$ 1,080.00 | 6% | <i>\$1,022.81</i> |
| MSP NBD Onsite RMA Only 7720-32C | 94311-7720- 32C | \$ 1,140.00 | 6% | <i>\$1,079.64</i> |
| MSP NBD Onsite RMA Only 7720-32C-AC-F | 94311-7720- 32C-AC-F | \$ 1,140.00 | 6% | <i>\$1,079.64</i> |
| MSP NBD Onsite RMA Only 7720-32C-AC-R | 94311-7720- 32C-AC-R | \$ 1,140.00 | 6% | <i>\$1,079.64</i> |
| MSP NBD Onsite RMA Only AP3000-WW | 94311-AP3000- WW | \$ 28.50 | 6% | <i>\$26.99</i> |
| MSP NBD Onsite RMA Only AP3000X-WW | 94311- AP3000X-WW | \$ 44.75 | 6% | <i>\$42.38</i> |
| MSP NBD Onsite RMA Only AP302W-CAN | 94311- AP302W-CAN | \$ 24.00 | 6% | <i>\$22.73</i> |
| MSP NBD Onsite RMA Only AP302W-EG | 94311- AP302W-EG | \$ 29.00 | 6% | <i>\$27.46</i> |
| MSP NBD Onsite RMA Only AP302W-FCC | 94311- AP302W-FCC | \$ 24.00 | 6% | <i>\$22.73</i> |
| MSP NBD Onsite RMA Only AP302W-WR | 94311- AP302W-WR | \$ 22.00 | 6% | <i>\$20.84</i> |
| MSP NBD Onsite RMA Only AP305C-1-CAN | 94311-AP305C- 1-CAN | \$ 41.00 | 6% | <i>\$38.83</i> |
| MSP NBD Onsite RMA Only AP305C-1-EG | 94311-AP305C- 1-EG | \$ 41.00 | 6% | <i>\$38.83</i> |
| MSP NBD Onsite RMA Only AP305C-1-FCC | 94311-AP305C- 1-FCC | \$ 41.00 | 6% | <i>\$38.83</i> |
| MSP NBD Onsite RMA Only AP305C-1-IL | 94311-AP305C- 1-IL | \$ 41.00 | 6% | <i>\$38.83</i> |
| MSP NBD Onsite RMA Only AP305C-1-WR | 94311-AP305C- 1-WR | \$ 41.00 | 6% | <i>\$38.83</i> |
| MSP NBD Onsite RMA Only AP305C-CAN | 94311-AP305C- CAN | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP305C-EG | 94311-AP305C- EG | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP305C-FCC | 94311-AP305C- FCC | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP305C-IL | 94311-AP305C- IL | \$ 46.00 | 6% | <i>\$43.56</i> |

| | | | | |
|---|---------------------------|----------|----|----------------|
| MSP NBD Onsite RMA Only AP305C-WR | 94311-AP305C- WR | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP305CX-CAN | 94311- AP305CX- CAN | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP305CX-FCC | 94311- AP305CX- FCC | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP305CX-IL | 94311- AP305CX-IL | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP305CX-WR | 94311- AP305CX-WR | \$ 46.00 | 6% | <i>\$43.56</i> |
| MSP NBD Onsite RMA Only AP4000-1-WW | 94311-AP4000- 1-WW | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD Onsite RMA Only AP4000-WW | 94311-AP4000- WW | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD Onsite RMA Only AP410C-1-CAN | 94311-AP410C- 1-CAN | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD Onsite RMA Only AP410C-1-EG | 94311-AP410C- 1-EG | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD Onsite RMA Only AP410C-1-FCC | 94311-AP410C- 1-FCC | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD Onsite RMA Only AP410C-1-IL | 94311-AP410C- 1-IL | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD Onsite RMA Only AP410C-1-WR | 94311-AP410C- 1-WR | \$ 51.00 | 6% | <i>\$48.30</i> |
| MSP NBD Onsite RMA Only AP410C-CAN | 94311-AP410C- CAN | \$ 57.00 | 6% | <i>\$53.98</i> |
| MSP NBD Onsite RMA Only AP410C-EG | 94311-AP410C- EG | \$ 57.00 | 6% | <i>\$53.98</i> |
| MSP NBD Onsite RMA Only AP410C-FCC | 94311-AP410C- FCC | \$ 57.00 | 6% | <i>\$53.98</i> |
| MSP NBD Onsite RMA Only AP410C-IL | 94311-AP410C- IL | \$ 57.00 | 6% | <i>\$53.98</i> |
| MSP NBD Onsite RMA Only AP410C-WR | 94311-AP410C- WR | \$ 57.00 | 6% | <i>\$53.98</i> |
| MSP NBD Onsite RMA Only AP460C-CAN | 94311-AP460C- CAN | \$ 77.00 | 6% | <i>\$72.92</i> |
| MSP NBD Onsite RMA Only AP460C-EG | 94311-AP460C- EG | \$ 77.00 | 6% | <i>\$72.92</i> |

| | | | | |
|--|-----------------------------|-----------|----|----------|
| MSP NBD Onsite RMA Only AP460C-FCC | 94311-AP460C- FCC | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460C-IL | 94311-AP460C- IL | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460C-WR | 94311-AP460C- WR | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460S12C-CAN | 94311- AP460S12C- CAN | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460S12C-FCC | 94311- AP460S12C- FCC | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460S12C-WR | 94311- AP460S12C- WR | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460S6C-CAN | 94311- AP460S6C- CAN | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460S6C-FCC | 94311- AP460S6C- FCC | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP460S6C-WR | 94311- AP460S6C- WR | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only AP5010-WW | 94311-AP5010- WW | \$ 100.00 | 6% | \$94.71 |
| MSP NBD Onsite RMA Only AP5020-WW | 94311-AP5020- WW | \$ 155.94 | 6% | \$147.68 |
| MSP NBD Onsite RMA Only AP5050D-WW | 94311- AP5050D-WW | \$ 280.00 | 6% | \$265.17 |
| MSP NBD Onsite RMA Only AP5050U-WW | 94311- AP5050U-WW | \$ 212.00 | 6% | \$200.77 |
| MSP NBD Onsite RMA Only AP510C-CAN | 94311-AP510C- CAN | \$ 75.00 | 6% | \$71.03 |
| MSP NBD Onsite RMA Only AP510C-CE | 94311-AP510C- CE | \$ 75.00 | 6% | \$71.03 |
| MSP NBD Onsite RMA Only AP510C-FCC | 94311-AP510C- FCC | \$ 75.00 | 6% | \$71.03 |
| MSP NBD Onsite RMA Only AP510C-W | 94311-AP510C- W | \$ 75.00 | 6% | \$71.03 |
| MSP NBD Onsite RMA Only AP510C-WW | 94311-AP510C- WW | \$ 91.00 | 6% | \$86.18 |

| | | | | |
|--|---------------------------|-------------|----|-------------------|
| MSP NBD Onsite RMA Only AP510CX-CAN | 94311- AP510CX- CAN | \$ 75.00 | 6% | <i>\$71.03</i> |
| MSP NBD Onsite RMA Only AP510CX-CE | 94311- AP510CX-CE | \$ 75.00 | 6% | <i>\$71.03</i> |
| MSP NBD Onsite RMA Only AP510CX-FCC | 94311- AP510CX- FCC | \$ 75.00 | 6% | <i>\$71.03</i> |
| MSP NBD Onsite RMA Only AP510CX-W | 94311- AP510CX-W | \$ 74.00 | 6% | <i>\$70.08</i> |
| MSP NBD Onsite RMA Only H35309 | 94311-H35309 | \$ 1,097.00 | 6% | <i>\$1,038.91</i> |
| MSP NBD Onsite RMA Only H35310 | 94311-H35310 | \$ 1,097.00 | 6% | <i>\$1,038.91</i> |
| MSP NBD Onsite RMA Only H35311 | 94311-H35311 | \$ 1,097.00 | 6% | <i>\$1,038.91</i> |
| MSP NBD Onsite RMA Only H35312 | 94311-H35312 | \$ 939.00 | 6% | <i>\$889.28</i> |
| MSP NBD Onsite RMA Only H35313 | 94311-H35313 | \$ 939.00 | 6% | <i>\$889.28</i> |
| MSP NBD Onsite RMA Only H35314 | 94311-H35314 | \$ 939.00 | 6% | <i>\$889.28</i> |
| MSP NBD Onsite RMA Only H35315 | 94311-H35315 | \$ 629.00 | 6% | <i>\$595.69</i> |
| MSP NBD Onsite RMA Only H35318 | 94311-H35318 | \$ 317.00 | 6% | <i>\$300.21</i> |
| MSP NBD Onsite RMA ONLY H35320 | 94311-H35320 | \$ 417.00 | 6% | <i>\$394.92</i> |
| MSP NBD Onsite RMA ONLY H35321 | 94311-H35321 | \$ 499.00 | 6% | <i>\$472.58</i> |
| MSP NBD Onsite RMA ONLY H35322 | 94311-H35322 | \$ 544.00 | 6% | <i>\$515.20</i> |
| MSP NBD Onsite RMA Only H35323 | 94311-H35323 | \$ 629.00 | 6% | <i>\$595.69</i> |
| MSP NBD Onsite RMA Only H35359 | 94311-H35359 | \$ 499.00 | 6% | <i>\$472.58</i> |
| MSP NBD Onsite RMA ONLY H35360 | 94311-H35360 | \$ 544.00 | 6% | <i>\$515.20</i> |
| MSP NBD Onsite RMA Only H35361 | 94311-H35361 | \$ 629.00 | 6% | <i>\$595.69</i> |
| MSP NBD Onsite RMA Only H35362 | 94311-H35362 | \$ 317.00 | 6% | <i>\$300.21</i> |

| | | | | |
|--|-----------------------------|-----------|----|----------|
| MSP NBD Onsite RMA Only H35455 | 94311-H35455 | \$ 417.00 | 6% | \$394.92 |
| MSP NBD Onsite RMA Only H35456 | 94311-H35456 | \$ 417.00 | 6% | \$394.92 |
| MSP NBD Onsite RMA Only H35457 | 94311-H35457 | \$ 417.00 | 6% | \$394.92 |
| MSP NBD Onsite RMA Only H35458 | 94311-H35458 | \$ 417.00 | 6% | \$394.92 |
| MSP NBD Onsite RMA Only H35471 | 94311-H35471 | \$ 417.00 | 6% | \$394.92 |
| MSP NBD Onsite RMA Only VSP49-12MXU-12XE | 94311-VSP4900-12MXU-12XE | \$ 585.00 | 6% | \$554.02 |
| MSP NBD Onsite RMA Only VSP49-12MXU-12XE-B | 94311-VSP4900-12MXU-12XE-B1 | \$ 585.00 | 6% | \$554.02 |
| MSP NBD Onsite RMA Only VSP4900-24S | 94311-VSP4900-24S | \$ 315.00 | 6% | \$298.32 |
| MSP NBD Onsite RMA Only VSP4900-24S-B3 | 94311-VSP4900-24S-B3 | \$ 315.00 | 6% | \$298.32 |
| MSP NBD Onsite RMA Only VSP4900-24XE | 94311-VSP4900-24XE | \$ 606.00 | 6% | \$573.91 |
| MSP NBD Onsite RMA Only VSP4900-24XE-B3 | 94311-VSP4900-24XE-B3 | \$ 606.00 | 6% | \$573.91 |
| MSP NBD Onsite RMA Only X435-24P-4S | 94311-X435-24P-4S | \$ 77.00 | 6% | \$72.92 |
| MSP NBD Onsite RMA Only X435-24T-4S | 94311-X435-24T-4S | \$ 42.00 | 6% | \$39.78 |
| MSP NBD Onsite RMA Only X435-8P-2T-W | 94311-X435-8P-2T-W | \$ 42.00 | 6% | \$39.78 |
| MSP NBD Onsite RMA Only X435-8P-4S | 94311-X435-8P-4S | \$ 38.00 | 6% | \$35.99 |
| MSP NBD Onsite RMA Only X435-8T-4S | 94311-X435-8T-4S | \$ 31.00 | 6% | \$29.36 |
| MSP NBD Onsite RMA ONLY X465-24MU | 94311-X465-24MU | \$ 544.00 | 6% | \$515.20 |
| MSP NBD Onsite RMA Only X465-24W | 94311-X465-24W | \$ 317.00 | 6% | \$300.21 |

| | | | | |
|--|---------------------------|-------------|----|------------|
| MSP NBD Onsite RMA ONLY X465-48P | 94311-X465-48P | \$ 417.00 | 6% | \$394.92 |
| MSP NBD Onsite RMA Only X465-48W | 94311-X465-48W | \$ 499.00 | 6% | \$472.58 |
| MSP NBD Onsite RMA Only X695-48Y-8C | 94311-X695-48Y-8C | \$ 962.00 | 6% | \$911.06 |
| MSP NBD Onsite RMA Only XR600 | 94311-XR600 | \$ 54.00 | 6% | \$51.14 |
| MSP NBD Onsite RMA ONLY XSW-MSP-BR-M-A | 94311-XSW-MSP-BR-M-A | \$ 270.00 | 6% | \$255.70 |
| MSP NBD Onsite RMA ONLY XSW-MSP-BR-S-A | 94311-XSW-MSP-BR-S-A | \$ 123.00 | 6% | \$116.49 |
| MSP NBD Onsite RMA ONLY XSW-MSP-BR-XS-A | 94311-XSW-MSP-BR-XS-A | \$ 98.00 | 6% | \$92.81 |
| MSP NBD Onsite RMA ONLY XSW-MSP-DC-S-A | 94311-XSW-MSP-DC-S-A | \$ 619.00 | 6% | \$586.22 |
| MSP NBD Ons RMA ONLY XSW-MSP-DCV2-LR-L-A | 94311-XSW-MSP-DCV2-LR-L-A | \$ 2,569.00 | 6% | \$2,432.97 |
| MSP NBD Onsite RMA ONLY XSW-MSP-DCV2-M-A | 94311-XSW-MSP-DCV2-M-A | \$ 1,884.00 | 6% | \$1,784.24 |
| MSP NBD Ons RMA ONLY XSW-MSP-DCV2-SR-L-A | 94311-XSW-MSP-DCV2-SR-L-A | \$ 2,569.00 | 6% | \$2,432.97 |
| PW NBD AHR Optics 10200 | 95504-10200 | \$ 1,802.00 | 6% | \$1,706.58 |
| PW NBD AHR Optics 10320 | 95504-10320 | \$ 1,977.00 | 6% | \$1,872.32 |
| PW NBD AHR 10330 | 95504-10330 | \$ 4,848.00 | 6% | \$4,591.30 |
| PW NBD AHR 10331 | 95504-10331 | \$ 2,237.00 | 6% | \$2,118.55 |
| PW NBD AHR 10335 | 95504-10335 | \$ 3,414.00 | 6% | \$3,233.23 |
| PW NBD AHR 10403 | 95504-10403 | \$ 4,235.00 | 6% | \$4,010.76 |
| PW NBD AHR 10404 | 95504-10404 | \$ 2,083.00 | 6% | \$1,972.71 |
| PW NBD AHR 10441 | 95504-10441 | \$ 1,395.00 | 6% | \$1,321.13 |
| PW NBD AHR 10442 | 95504-10442 | \$ 1,484.00 | 6% | \$1,405.42 |
| PW NBD AHR 1130C | 95504-1130C | \$ 960.00 | 6% | \$909.17 |
| PW NBD AHR E4G 16119 | 95504-16119 | \$ 257.00 | 6% | \$243.39 |
| PW NBD AHR E4G 16120 | 95504-16120 | \$ 316.00 | 6% | \$299.27 |
| PW NBD AHR E4G 16126 | 95504-16126 | \$ 257.00 | 6% | \$243.39 |
| PW NBD AHR E4G 16127 | 95504-16127 | \$ 270.00 | 6% | \$255.70 |
| PW NBD AHR 16172 | 95504-16172 | \$ 267.00 | 6% | \$252.86 |
| PW NBD AHR -16172T | 95504-16172T | \$ 317.00 | 6% | \$300.21 |

| | | | | |
|-------------------------|--------------|-------------|----|------------|
| PW NBD AHR 16173 | 95504-16173 | \$ 275.00 | 6% | \$260.44 |
| PW NBD AHR -16173T | 95504-16173T | \$ 326.00 | 6% | \$308.74 |
| PW NBD AHR 16174 | 95504-16174 | \$ 422.00 | 6% | \$399.66 |
| PW NBD AHR 16175 | 95504-16175 | \$ 450.00 | 6% | \$426.17 |
| PW NBD AHR 16176 | 95504-16176 | \$ 392.00 | 6% | \$371.24 |
| PW NBD AHR 16177 | 95504-16177 | \$ 385.00 | 6% | \$364.61 |
| PW NBD AHR -16177T | 95504-16177T | \$ 488.00 | 6% | \$462.16 |
| PW NBD AHR 16178 | 95504-16178 | \$ 569.00 | 6% | \$538.87 |
| PW NBD AHR 16179 | 95504-16179 | \$ 584.00 | 6% | \$553.08 |
| PW NBD AHR -16179T | 95504-16179T | \$ 702.00 | 6% | \$664.83 |
| PW NBD AHR 16301T | 95504-16301T | \$ 1,521.00 | 6% | \$1,440.46 |
| PW NBD AHR 16303T | 95504-16303T | \$ 1,521.00 | 6% | \$1,440.46 |
| PW NBD AHR 16304T | 95504-16304T | \$ 2,027.00 | 6% | \$1,919.67 |
| PW NBD AHR 16401T | 95504-16401T | \$ 721.00 | 6% | \$682.82 |
| PW NBD AHR 16402T | 95504-16402T | \$ 1,087.00 | 6% | \$1,029.44 |
| PW NBD AHR 16403T | 95504-16403T | \$ 963.00 | 6% | \$912.01 |
| PW NBD AHR 16404T | 95504-16404T | \$ 963.00 | 6% | \$912.01 |
| PW NBD AHR 16405T | 95504-16405T | \$ 1,269.00 | 6% | \$1,201.81 |
| PW NBD AHR 16406T | 95504-16406T | \$ 1,695.00 | 6% | \$1,605.25 |
| PW NBD AHR E4G 16431 | 95504-16431 | \$ 1,071.00 | 6% | \$1,014.29 |
| PW NBD AHR E4G 16432 | 95504-16432 | \$ 1,162.00 | 6% | \$1,100.47 |
| PW NBD AHR E4G 16440 | 95504-16440 | \$ 674.00 | 6% | \$638.31 |
| PW NBD AHR E4G 16441 | 95504-16441 | \$ 606.00 | 6% | \$573.91 |
| PW NBD AHR E4G 16442 | 95504-16442 | \$ 270.00 | 6% | \$255.70 |
| PW NBD AHR E4G 16444 | 95504-16444 | \$ 136.00 | 6% | \$128.80 |
| PW NBD AHR Summit 16501 | 95504-16501 | \$ 145.00 | 6% | \$137.32 |
| PW NBD AHR 16501T | 95504-16501T | \$ 184.00 | 6% | \$174.26 |
| PW NBD AHR Summit 16502 | 95504-16502 | \$ 213.00 | 6% | \$201.72 |
| PW NBD AHR 16502T | 95504-16502T | \$ 257.00 | 6% | \$243.39 |
| PW NBD AHR Summit 16503 | 95504-16503 | \$ 177.00 | 6% | \$167.63 |
| PW NBD AHR 16503T | 95504-16503T | \$ 229.00 | 6% | \$216.87 |
| PW NBD AHR Summit 16504 | 95504-16504 | \$ 288.00 | 6% | \$272.75 |
| PW NBD AHR 16504T | 95504-16504T | \$ 340.00 | 6% | \$322.00 |
| PW NBD AHR Summit 16505 | 95504-16505 | \$ 318.00 | 6% | \$301.16 |
| PW NBD AHR 16505T | 95504-16505T | \$ 388.00 | 6% | \$367.46 |
| PW NBD AHR Summit 16506 | 95504-16506 | \$ 491.00 | 6% | \$465.00 |
| PW NBD AHR 16506T | 95504-16506T | \$ 388.00 | 6% | \$367.46 |
| PW NBD AHR Summit 16507 | 95504-16507 | \$ 448.00 | 6% | \$424.28 |
| PW NBD AHR 16507T | 95504-16507T | \$ 529.00 | 6% | \$500.99 |
| PW NBD AHR Summit 16508 | 95504-16508 | \$ 558.00 | 6% | \$528.45 |
| PW NBD AHR 16508T | 95504-16508T | \$ 668.00 | 6% | \$632.63 |
| PW NBD AHR Summit 16509 | 95504-16509 | \$ 558.00 | 6% | \$528.45 |

| | | | | |
|-------------------------|--------------|-----------|----|----------|
| PW NBD AHR 16509T | 95504-16509T | \$ 668.00 | 6% | \$632.63 |
| PW NBD AHR Summit 16510 | 95504-16510 | \$ 668.00 | 6% | \$632.63 |
| PW NBD AHR 16510T | 95504-16510T | \$ 800.00 | 6% | \$757.64 |
| PW NBD AHR-16513 | 95504-16513 | \$ 404.00 | 6% | \$382.61 |
| PW NBD AHR-16514 | 95504-16514 | \$ 656.00 | 6% | \$621.26 |
| PW NBD AHR 16515 | 95504-16515 | \$ 113.00 | 6% | \$107.02 |
| PW NBD AHR-16516 | 95504-16516 | \$ 121.00 | 6% | \$114.59 |
| PW NBD AHR 16517 | 95504-16517 | \$ 241.00 | 6% | \$228.24 |
| PW NBD AHR-16518 | 95504-16518 | \$ 215.00 | 6% | \$203.62 |
| PW-NBD AHR 16519 | 95504-16519 | \$ 221.00 | 6% | \$209.30 |
| PW-NBD AHR 16520 | 95504-16520 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR 16530 | 95504-16530 | \$ 135.00 | 6% | \$127.85 |
| PW NBD AHR 16531 | 95504-16531 | \$ 183.00 | 6% | \$173.31 |
| PW NBD AHR 16531T | 95504-16531T | \$ 199.00 | 6% | \$188.46 |
| PW NBD AHR 16532 | 95504-16532 | \$ 183.00 | 6% | \$173.31 |
| PW NBD AHR 16532T | 95504-16532T | \$ 199.00 | 6% | \$188.46 |
| PW NBD AHR 16533 | 95504-16533 | \$ 260.00 | 6% | \$246.23 |
| PW NBD AHR 16533T | 95504-16533T | \$ 283.00 | 6% | \$268.02 |
| PW NBD AHR 16534 | 95504-16534 | \$ 275.00 | 6% | \$260.44 |
| PW NBD AHR 16535 | 95504-16535 | \$ 404.00 | 6% | \$382.61 |
| PW NBD AHR 16535A | 95504-16535A | \$ 404.00 | 6% | \$382.61 |
| PW NBD AHR 16535T | 95504-16535T | \$ 450.00 | 6% | \$426.17 |
| PW NBD AHR 16536 | 95504-16536 | \$ 188.00 | 6% | \$178.05 |
| PW NBD AHR 16537 | 95504-16537 | \$ 257.00 | 6% | \$243.39 |
| PW NBD AHR 16538 | 95504-16538 | \$ 304.00 | 6% | \$287.90 |
| PW NBD AHR 16538T | 95504-16538T | \$ 372.00 | 6% | \$352.30 |
| PW NBD AHR 16539 | 95504-16539 | \$ 400.00 | 6% | \$378.82 |
| PW NBD AHR 16540 | 95504-16540 | \$ 284.00 | 6% | \$268.96 |
| PW NBD AHR 16541 | 95504-16541 | \$ 106.00 | 6% | \$100.39 |
| PW NBD AHR 16560 | 95504-16560 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR 16561 | 95504-16561 | \$ 90.00 | 6% | \$85.23 |
| PW NBD AHR 16562 | 95504-16562 | \$ 109.00 | 6% | \$103.23 |
| PW NBD AHR 16563 | 95504-16563 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR 16564 | 95504-16564 | \$ 178.00 | 6% | \$168.57 |
| PW NBD AHR 16565 | 95504-16565 | \$ 267.00 | 6% | \$252.86 |
| PW NBD AHR 16566 | 95504-16566 | \$ 41.00 | 6% | \$38.83 |
| PW NBD AHR 16567 | 95504-16567 | \$ 75.00 | 6% | \$71.03 |
| PW NBD AHR 16568 | 95504-16568 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR 16569 | 95504-16569 | \$ 96.00 | 6% | \$90.92 |
| PW NBD AHR 16570 | 95504-16570 | \$ 109.00 | 6% | \$103.23 |
| PW NBD AHR 16571 | 95504-16571 | \$ 178.00 | 6% | \$168.57 |
| PW NBD AHR 16701 | 95504-16701 | \$ 395.00 | 6% | \$374.08 |

| | | | | |
|-------------------------|--------------|-------------|----|------------|
| PW NBD AHR 16702 | 95504-16702 | \$ 573.00 | 6% | \$542.66 |
| PW NBD AHR 16703 | 95504-16703 | \$ 458.00 | 6% | \$433.75 |
| PW NBD AHR -16703T | 95504-16703T | \$ 545.00 | 6% | \$516.14 |
| PW NBD AHR 16704 | 95504-16704 | \$ 669.00 | 6% | \$633.58 |
| PW NBD AHR -16704T | 95504-16704T | \$ 802.00 | 6% | \$759.53 |
| PW NBD AHR 16705 | 95504-16705 | \$ 573.00 | 6% | \$542.66 |
| PW NBD AHR -16705T | 95504-16705T | \$ 695.00 | 6% | \$658.20 |
| PW NBD AHR 16706 | 95504-16706 | \$ 873.00 | 6% | \$826.77 |
| PW NBD AHR -16706T | 95504-16706T | \$ 1,054.00 | 6% | \$998.19 |
| PW NBD AHR 16710 | 95504-16710 | \$ 175.00 | 6% | \$165.73 |
| PW NBD AHR 16710T | 95504-16710T | \$ 215.00 | 6% | \$203.62 |
| PW NBD AHR 16711 | 95504-16711 | \$ 75.00 | 6% | \$71.03 |
| PW NBD AHR 16711T | 95504-16711T | \$ 88.00 | 6% | \$83.34 |
| PW NBD AHR 16712 | 95504-16712 | \$ 99.00 | 6% | \$93.76 |
| PW NBD AHR 16712T | 95504-16712T | \$ 118.00 | 6% | \$111.75 |
| PW NBD AHR 16713 | 95504-16713 | \$ 47.00 | 6% | \$44.51 |
| PW NBD AHR 16713T | 95504-16713T | \$ 54.00 | 6% | \$51.14 |
| PW NBD AHR 16715 | 95504-16715 | \$ 73.00 | 6% | \$69.13 |
| PW NBD AHR 16715T | 95504-16715T | \$ 88.00 | 6% | \$83.34 |
| PW NBD AHR 16716 | 95504-16716 | \$ 305.00 | 6% | \$288.85 |
| PW NBD AHR -16716T | 95504-16716T | \$ 362.00 | 6% | \$342.83 |
| PW NBD AHR 16717 | 95504-16717 | \$ 463.00 | 6% | \$438.48 |
| PW NBD AHR 16718 | 95504-16718 | \$ 329.00 | 6% | \$311.58 |
| PW NBD AHR -16718T | 95504-16718T | \$ 400.00 | 6% | \$378.82 |
| PW NBD AHR 16719 | 95504-16719 | \$ 491.00 | 6% | \$465.00 |
| PW NBD AHR -16719T | 95504-16719T | \$ 589.00 | 6% | \$557.81 |
| PW NBD AHR 16720 | 95504-16720 | \$ 740.00 | 6% | \$700.82 |
| PW NBD AHR 16720T | 95504-16720T | \$ 860.00 | 6% | \$814.46 |
| PW NBD AHR 16756 | 95504-16756 | \$ 540.00 | 6% | \$511.41 |
| PW NBD AHR 16756T | 95504-16756T | \$ 642.00 | 6% | \$608.01 |
| PW NBD AHR 16757 | 95504-16757 | \$ 509.00 | 6% | \$482.05 |
| PW NBD AHR 16757T | 95504-16757T | \$ 603.00 | 6% | \$571.07 |
| PW NBD AHR 16790 | 95504-16790 | \$ 1,189.00 | 6% | \$1,126.04 |
| PW NBD AHR 16791 | 95504-16791 | \$ 1,532.00 | 6% | \$1,450.88 |
| PW NBD AHR 16801 | 95504-16801 | \$ 136.00 | 6% | \$128.80 |
| PW NBD AHR 16802 | 95504-16802 | \$ 170.00 | 6% | \$161.00 |
| PW NBD AHR 16803 | 95504-16803 | \$ 177.00 | 6% | \$167.63 |
| PW NBD AHR 16804 | 95504-16804 | \$ 217.00 | 6% | \$205.51 |
| PW NBD AHR 16805 | 95504-16805 | \$ 48.00 | 6% | \$45.46 |
| PW NBD AHR 16806 | 95504-16806 | \$ 48.00 | 6% | \$45.46 |
| PW NBD AHR Summit 17101 | 95504-17101 | \$ 2,255.00 | 6% | \$2,135.60 |
| PW NBD AHR 17101T | 95504-17101T | \$ 2,877.00 | 6% | \$2,724.66 |

| | | | | |
|--------------------------|--------------|-------------|----|------------|
| PW NBD AHR Summit 17102 | 95504-17102 | \$ 2,255.00 | 6% | \$2,135.60 |
| PW NBD AHR 17102T | 95504-17102T | \$ 2,877.00 | 6% | \$2,724.66 |
| PW NBD AHR Summit 17103 | 95504-17103 | \$ 1,572.00 | 6% | \$1,488.76 |
| PW NBD AHR Summit 17103C | 95504-17103C | \$ 1,525.00 | 6% | \$1,444.25 |
| PW NBD AHR 17103T | 95504-17103T | \$ 2,011.00 | 6% | \$1,904.52 |
| PW NBD AHR Summit 17104 | 95504-17104 | \$ 1,572.00 | 6% | \$1,488.76 |
| PW NBD AHR 17104T | 95504-17104T | \$ 2,011.00 | 6% | \$1,904.52 |
| PW NBD AHR Summit 17121 | 95504-17121 | \$ 449.00 | 6% | \$425.23 |
| PW NBD AHR Summit 17122 | 95504-17122 | \$ 278.00 | 6% | \$263.28 |
| PW NBD AHR -17200 | 95504-17200 | \$ 3,546.00 | 6% | \$3,358.24 |
| PW NBD AHR 17200T | 95504-17200T | \$ 4,060.00 | 6% | \$3,845.02 |
| PW NBD AHR Summit 17201 | 95504-17201 | \$ 3,546.00 | 6% | \$3,358.24 |
| PW NBD AHR 17201T | 95504-17201T | \$ 4,060.00 | 6% | \$3,845.02 |
| PW NBD AHR Summit 17202 | 95504-17202 | \$ 3,546.00 | 6% | \$3,358.24 |
| PW NBD AHR 17202T | 95504-17202T | \$ 4,060.00 | 6% | \$3,845.02 |
| PW NBD AHR Summit 17203 | 95504-17203 | \$ 3,605.00 | 6% | \$3,414.12 |
| PW NBD AHR 17203T | 95504-17203T | \$ 4,118.00 | 6% | \$3,899.95 |
| PW NBD AHR Summit 17204 | 95504-17204 | \$ 3,605.00 | 6% | \$3,414.12 |
| PW NBD AHR 17204T | 95504-17204T | \$ 4,118.00 | 6% | \$3,899.95 |
| PW NBD AHR Summit 17205 | 95504-17205 | \$ 3,578.00 | 6% | \$3,388.54 |
| PW NBD AHR 17205T | 95504-17205T | \$ 4,087.00 | 6% | \$3,870.59 |
| PW NBD AHR Summit 17206 | 95504-17206 | \$ 3,578.00 | 6% | \$3,388.54 |
| PW NBD AHR 17206T | 95504-17206T | \$ 4,087.00 | 6% | \$3,870.59 |
| PW NBD AHR 17300 | 95504-17300 | \$ 2,347.00 | 6% | \$2,222.73 |
| PW NBD AHR 17310 | 95504-17310 | \$ 2,130.00 | 6% | \$2,017.22 |
| PW NBD AHR -17310T | 95504-17310T | \$ 2,560.00 | 6% | \$2,424.45 |
| PW NBD AHR 17350 | 95504-17350 | \$ 2,148.00 | 6% | \$2,034.26 |
| PW NBD AHR 17360 | 95504-17360 | \$ 2,643.00 | 6% | \$2,503.05 |
| PW NBD AHR 17401 | 95504-17401 | \$ 326.00 | 6% | \$308.74 |
| PW NBD AHR 17401G | 95504-17401G | \$ 388.00 | 6% | \$367.46 |
| PW NBD AHR 17401T | 95504-17401T | \$ 368.00 | 6% | \$348.51 |
| PW NBD AHR 17402 | 95504-17402 | \$ 467.00 | 6% | \$442.27 |
| PW NBD AHR 17402G | 95504-17402G | \$ 519.00 | 6% | \$491.52 |
| PW NBD AHR 17402T | 95504-17402T | \$ 496.00 | 6% | \$469.74 |
| PW NBD AHR 17403 | 95504-17403 | \$ 506.00 | 6% | \$479.21 |
| PW NBD AHR 17404 | 95504-17404 | \$ 245.00 | 6% | \$232.03 |
| PW NBD AHR 17405 | 95504-17405 | \$ 303.00 | 6% | \$286.96 |
| PW NBD AHR 17700 | 95504-17700 | \$ 4,159.00 | 6% | \$3,938.78 |
| PW NBD AHR 17701 | 95504-17701 | \$ 3,657.00 | 6% | \$3,463.36 |
| PW NBD AHR 17702 | 95504-17702 | \$ 3,657.00 | 6% | \$3,463.36 |
| PW NBD AHR 17703 | 95504-17703 | \$ 4,002.00 | 6% | \$3,790.09 |
| PW NBD AHR 17704 | 95504-17704 | \$ 4,002.00 | 6% | \$3,790.09 |

| | | | | |
|----------------------|-----------------|-------------|----|------------|
| PW NBD AHR 17705 | 95504-17705 | \$ 3,688.00 | 6% | \$3,492.72 |
| PW NBD AHR 17706 | 95504-17706 | \$ 3,688.00 | 6% | \$3,492.72 |
| PW NBD AHR 17800 | 95504-17800 | \$ 4,163.00 | 6% | \$3,942.57 |
| PW NBD AHR 17810 | 95504-17810 | \$ 3,329.00 | 6% | \$3,152.73 |
| PW NBD AHR 18101 | 95504-18101 | \$ 212.00 | 6% | \$200.77 |
| PW NBD AHR 18102 | 95504-18102 | \$ 271.00 | 6% | \$256.65 |
| PW NBD AHR 18103 | 95504-18103 | \$ 297.00 | 6% | \$281.27 |
| PW NBD AHR 18104 | 95504-18104 | \$ 423.00 | 6% | \$400.60 |
| PW NBD AHR 18104-6PK | 95504-18104-6PK | \$ 2,465.00 | 6% | \$2,334.48 |
| PW NBD AHR 18202 | 95504-18202 | \$ 158.00 | 6% | \$149.63 |
| PW NBD AHR 30135 | 95504-30135 | \$ 433.00 | 6% | \$410.07 |
| PW NBD AHR 30136 | 95504-30136 | \$ 3,268.00 | 6% | \$3,094.96 |
| PW NBD AHR 30137 | 95504-30137 | \$ 818.00 | 6% | \$774.69 |
| PW NBD AHR 30138 | 95504-30138 | \$ 3,775.00 | 6% | \$3,575.11 |
| PW NBD AHR 30139 | 95504-30139 | \$ 6,901.00 | 6% | \$6,535.59 |
| PW NBD AHR 30912 | 95504-30912 | \$ 44.00 | 6% | \$41.67 |
| PW NBD AHR 30913 | 95504-30913 | \$ 44.00 | 6% | \$41.67 |
| PW NBD AHR 31012 | 95504-31012 | \$ 74.00 | 6% | \$70.08 |
| PW NBD AHR 31013 | 95504-31013 | \$ 74.00 | 6% | \$70.08 |
| PW NBD AHR 31014 | 95504-31014 | \$ 74.00 | 6% | \$70.08 |
| PW NBD AHR 31015 | 95504-31015 | \$ 74.00 | 6% | \$70.08 |
| PW NBD AHR 31016 | 95504-31016 | \$ 239.00 | 6% | \$226.34 |
| PW NBD AHR 31017 | 95504-31017 | \$ 239.00 | 6% | \$226.34 |
| PW NBD AHR 31018 | 95504-31018 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR 31019 | 95504-31019 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR 31025 | 95504-31025 | \$ 46.00 | 6% | \$43.56 |
| PW NBD AHR 31026 | 95504-31026 | \$ 46.00 | 6% | \$43.56 |
| PW NBD AHR 31028 | 95504-31028 | \$ 47.00 | 6% | \$44.51 |
| PW NBD AHR 31029 | 95504-31029 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR 31031 | 95504-31031 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR 31032 | 95504-31032 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR 31034 | 95504-31034 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR 31035 | 95504-31035 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR 31050 | 95504-31050 | \$ 96.00 | 6% | \$90.92 |
| PW NBD AHR 31051 | 95504-31051 | \$ 96.00 | 6% | \$90.92 |
| PW NBD AHR 31055 | 95504-31055 | \$ 96.00 | 6% | \$90.92 |
| PW NBD AHR 31056 | 95504-31056 | \$ 96.00 | 6% | \$90.92 |
| PW NBD AHR 37101 | 95504-37101 | \$ 44.00 | 6% | \$41.67 |
| PW NBD AHR 37102 | 95504-37102 | \$ 44.00 | 6% | \$41.67 |
| PW NBD AHR 37103 | 95504-37103 | \$ 44.00 | 6% | \$41.67 |
| PW NBD AHR 37111 | 95504-37111 | \$ 48.00 | 6% | \$45.46 |

| | | | | |
|-------------------------|--------------------|-------------|----|-------------------|
| PW NBD AHR 37112 | 95504-37112 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PW NBD AHR 37113 | 95504-37113 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW NBD AHR 37114 | 95504-37114 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW NBD AHR 37115 | 95504-37115 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PW NBD AHR 37116 | 95504-37116 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW NBD AHR 37117 | 95504-37117 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PW NBD AHR 37121 | 95504-37121 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 37122 | 95504-37122 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 37123 | 95504-37123 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 37124 | 95504-37124 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 37125 | 95504-37125 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 37126 | 95504-37126 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 37129 | 95504-37129 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 37130 | 95504-37130 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW NBD AHR 39031 | 95504-39031 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD AHR 39032 | 95504-39032 | \$ 111.00 | 6% | <i>\$105.12</i> |
| PW NBD AHR 39033 | 95504-39033 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD AHR 39034 | 95504-39034 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD AHR 39035 | 95504-39035 | \$ 495.00 | 6% | <i>\$468.79</i> |
| PW NBD AHR 39036 | 95504-39036 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PW NBD AHR 39037 | 95504-39037 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PW NBD AHR 39038 | 95504-39038 | \$ 132.00 | 6% | <i>\$125.01</i> |
| PW NBD AHR 39039 | 95504-39039 | \$ 132.00 | 6% | <i>\$125.01</i> |
| PW NBD AHR 39505 | 95504-39505 | \$ 46.00 | 6% | <i>\$43.56</i> |
| PW NBD AHR 4120-24MW-4Y | 95504-4120-24MW-4Y | \$ 531.00 | 6% | <i>\$502.88</i> |
| PW NBD AHR 4120-48MW-4Y | 95504-4120-48MW-4Y | \$ 708.00 | 6% | <i>\$670.51</i> |
| PW NBD AHR 4120C | 95504-4120C | \$ 4,628.00 | 6% | <i>\$4,382.95</i> |
| PW NBD AHR 4120C-1 | 95504-4120C-1 | \$ 5,225.00 | 6% | <i>\$4,948.34</i> |
| PW NBD AHR 41216 | 95504-41216 | \$ 1,430.00 | 6% | <i>\$1,354.28</i> |
| PW NBD AHR 4220-12P-4X | 95504-4220-12P-4X | \$ 162.00 | 6% | <i>\$153.42</i> |
| PW NBD AHR 4220-12T-4X | 95504-4220-12T-4X | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW NBD AHR 4220-24P-4X | 95504-4220-24P-4X | \$ 216.00 | 6% | <i>\$204.56</i> |
| PW NBD AHR 4220-24T-4X | 95504-4220-24T-4X | \$ 167.00 | 6% | <i>\$158.16</i> |
| PW NBD AHR 4220-48P-4X | 95504-4220-48P-4X | \$ 324.00 | 6% | <i>\$306.84</i> |

| | | | | |
|--------------------------------|---------------------------|--------------|----|--------------------|
| PW NBD AHR 4220-48T-4X | 95504-4220-48T-4X | \$ 243.00 | 6% | <i>\$230.13</i> |
| PW NBD AHR 4220-4MW-20P-4X | 95504-4220-4MW-20P-4X | \$ 297.00 | 6% | <i>\$281.27</i> |
| PW NBD AHR 4220-4MW-8P-4X | 95504-4220-4MW-8P-4X | \$ 210.00 | 6% | <i>\$198.88</i> |
| PW NBD AHR 4220-8MW-40P-4X | 95504-4220-8MW-40P-4X | \$ 432.00 | 6% | <i>\$409.13</i> |
| PW NBD AHR 4220-8X | 95504-4220-8X | \$ 227.00 | 6% | <i>\$214.98</i> |
| PW NBD AHR BD X 48001 | 95504-48001 | \$ 5,936.00 | 6% | <i>\$5,621.69</i> |
| PW NBD AHR 48038 | 95504-48038 | \$ 2,378.00 | 6% | <i>\$2,252.08</i> |
| PW NBD AHR 48039 | 95504-48039 | \$ 2,378.00 | 6% | <i>\$2,252.08</i> |
| PW NBD AHR-48040 | 95504-48040 | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PW NBD AHR BD X 48041 | 95504-48041 | \$ 2,378.00 | 6% | <i>\$2,252.08</i> |
| PW NBD AHR BD X 48046 | 95504-48046 | \$ 3,121.00 | 6% | <i>\$2,955.74</i> |
| PW NBD AHR 48047 | 95504-48047 | \$ 8,320.00 | 6% | <i>\$7,879.46</i> |
| PW NBD AHR BD X 48051 | 95504-48051 | \$ 5,723.00 | 6% | <i>\$5,419.97</i> |
| PW NBD AHR 48061 | 95504-48061 | \$ 6,685.00 | 6% | <i>\$6,331.03</i> |
| PW NBD AHR 48062 | 95504-48062 | \$ 10,696.00 | 6% | <i>\$10,129.65</i> |
| PW NBD AHR 5320-16P-4XE | 95504-5320-16P-4XE | \$ 228.00 | 6% | <i>\$215.93</i> |
| PW NBD AHR 5320-16P-4XE-DC | 95504-5320-16P-4XE-DC | \$ 273.00 | 6% | <i>\$258.54</i> |
| PW NBD AHR 5320-24P-8XE | 95504-5320-24P-8XE | \$ 251.00 | 6% | <i>\$237.71</i> |
| PW NBD AHR 5320-24T-24S-4XE-XT | 95504-5320-24T-24S-4XE-XT | \$ 344.00 | 6% | <i>\$325.79</i> |
| PW NBD AHR 5320-24T-4X-XT | 95504-5320-24T-4X-XT | \$ 185.00 | 6% | <i>\$175.20</i> |
| PW NBD AHR 5320-24T-8XE | 95504-5320-24T-8XE | \$ 178.00 | 6% | <i>\$168.57</i> |
| PW NBD AHR 5320-48P-8XE | 95504-5320-48P-8XE | \$ 420.00 | 6% | <i>\$397.76</i> |
| PW NBD AHR 5320-48T-8XE | 95504-5320-48T-8XE | \$ 283.00 | 6% | <i>\$268.02</i> |
| PW NBD AHR 5420F-16MW-32P-4XE | 95504-5420F-16MW-32P-4XE | \$ 813.00 | 6% | <i>\$769.95</i> |
| PW NBD AHR 5420F-16W-32P-4XE | 95504-5420F-16W-32P-4XE | \$ 688.00 | 6% | <i>\$651.57</i> |

| | | | | |
|-------------------------------|--------------------------|-----------|----|----------|
| PW NBD AHR 5420F-24P-4XE | 95504-5420F-24P-4XE | \$ 343.00 | 6% | \$324.84 |
| PW NBD AHR 5420F-24S-4XE | 95504-5420F-24S-4XE | \$ 388.00 | 6% | \$367.46 |
| PW NBD AHR 5420F-24T-4XE | 95504-5420F-24T-4XE | \$ 282.00 | 6% | \$267.07 |
| PW NBD AHR 5420F-48P-4XE | 95504-5420F-48P-4XE | \$ 534.00 | 6% | \$505.72 |
| PW NBD AHR 5420F-48P-4XL | 95504-5420F-48P-4XL | \$ 623.00 | 6% | \$590.01 |
| PW NBD AHR 5420F-48T-4XE | 95504-5420F-48T-4XE | \$ 382.00 | 6% | \$361.77 |
| PW NBD AHR 5420F-8W-16P-4XE | 95504-5420F-8W-16P-4XE | \$ 404.00 | 6% | \$382.61 |
| PW NBD AHR 5420M-16MW-32P-4YE | 95504-5420M-16MW-32P-4YE | \$ 881.00 | 6% | \$834.35 |
| PW NBD AHR 5420M-24T-4YE | 95504-5420M-24T-4YE | \$ 375.00 | 6% | \$355.14 |
| PW NBD AHR 5420M-24W-4YE | 95504-5420M-24W-4YE | \$ 351.00 | 6% | \$332.41 |
| PW NBD AHR 5420M-48T-4YE | 95504-5420M-48T-4YE | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR 5420M-48W-4YE | 95504-5420M-48W-4YE | \$ 577.00 | 6% | \$546.45 |
| PW NBD AHR 5520-12MW-36W | 95504-5520-12MW-36W | \$ 802.00 | 6% | \$759.53 |
| PW NBD AHR 5520-24T | 95504-5520-24T | \$ 332.00 | 6% | \$314.42 |
| PW NBD AHR 5520-24T-ACDC-BASE | 95504-5520-24T-ACDC-BASE | \$ 332.00 | 6% | \$314.42 |
| PW NBD AHR 5520-24T-BASE | 95504-5520-24T-BASE | \$ 332.00 | 6% | \$314.42 |
| PW NBD AHR 5520-24W | 95504-5520-24W | \$ 505.00 | 6% | \$478.26 |
| PW NBD AHR 5520-24X | 95504-5520-24X | \$ 955.00 | 6% | \$904.43 |
| PW NBD AHR 5520-24X-ACDC-BASE | 95504-5520-24X-ACDC-BASE | \$ 955.00 | 6% | \$904.43 |

| | | | | |
|--------------------------------|---------------------------|-------------|----|-------------------|
| PW NBD AHR 5520-24X-BASE | 95504-5520-24X-BASE | \$ 955.00 | 6% | <i>\$904.43</i> |
| PW NBD AHR 5520-48SE | 95504-5520-48SE | \$ 983.00 | 6% | <i>\$930.95</i> |
| PW NBD AHR 5520-48SE-ACDC-BASE | 95504-5520-48SE-ACDC-BASE | \$ 983.00 | 6% | <i>\$930.95</i> |
| PW NBD AHR 5520-48SE-BASE | 95504-5520-48SE-BASE | \$ 983.00 | 6% | <i>\$930.95</i> |
| PW NBD AHR 5520-48T | 95504-5520-48T | \$ 546.00 | 6% | <i>\$517.09</i> |
| PW NBD AHR 5520-48T-ACDC-BASE | 95504-5520-48T-ACDC-BASE | \$ 546.00 | 6% | <i>\$517.09</i> |
| PW NBD AHR 5520-48T-BASE | 95504-5520-48T-BASE | \$ 546.00 | 6% | <i>\$517.09</i> |
| PW NBD AHR 5520-48W | 95504-5520-48W | \$ 655.00 | 6% | <i>\$620.32</i> |
| PW NBD AHR 5720-24MW | 95504-5720-24MW | \$ 1,003.00 | 6% | <i>\$949.89</i> |
| PW NBD AHR 5720-24MXW | 95504-5720-24MXW | \$ 1,357.00 | 6% | <i>\$1,285.15</i> |
| PW NBD AHR 5720-48MW | 95504-5720-48MW | \$ 1,186.00 | 6% | <i>\$1,123.20</i> |
| PW NBD AHR 5720-48MXW | 95504-5720-48MXW | \$ 1,711.00 | 6% | <i>\$1,620.40</i> |
| PW NBD AHR 7520-48XT-6C | 95504-7520-48XT-6C | \$ 1,837.00 | 6% | <i>\$1,739.73</i> |
| PW NBD AHR 7520-48XT-6C-AC-F | 95504-7520-48XT-6C-AC-F | \$ 1,837.00 | 6% | <i>\$1,739.73</i> |
| PW NBD AHR 7520-48XT-6C-AC-R | 95504-7520-48XT-6C-AC-R | \$ 1,837.00 | 6% | <i>\$1,739.73</i> |
| PW NBD AHR 7520-48Y-8C | 95504-7520-48Y-8C | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |
| PW NBD AHR 7520-48Y-8C-AC-F | 95504-7520-48Y-8C-AC-F | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |
| PW NBD AHR 7520-48Y-8C-AC-R | 95504-7520-48Y-8C-AC-R | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |
| PW NBD AHR 7520-48YE-8CE | 95504-7520-48YE-8CE | \$ 1,993.00 | 6% | <i>\$1,887.47</i> |

| | | | | |
|-------------------------------|--------------------------|-------------|----|-------------------|
| PW NBD AHR 7520-48YE-8CE-AC-F | 95504-7520-48YE-8CE-AC-F | \$ 1,993.00 | 6% | <i>\$1,887.47</i> |
| PW NBD AHR 7520-48YE-8CE-AC-R | 95504-7520-48YE-8CE-AC-R | \$ 1,993.00 | 6% | <i>\$1,887.47</i> |
| PW NBD AHR 7720-32C | 95504-7720-32C | \$ 2,146.00 | 6% | <i>\$2,032.37</i> |
| PW NBD AHR 7720-32C-AC-F | 95504-7720-32C-AC-F | \$ 2,146.00 | 6% | <i>\$2,032.37</i> |
| PW NBD AHR 7720-32C-AC-R | 95504-7720-32C-AC-R | \$ 2,146.00 | 6% | <i>\$2,032.37</i> |
| PW NBD AHR 8520-48XT-6C | 95504-8520-48XT-6C | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PW NBD AHR 8520-48XT-6C-AC-F | 95504-8520-48XT-6C-AC-F | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PW NBD AHR 8520-48XT-6C-AC-R | 95504-8520-48XT-6C-AC-R | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PW NBD AHR 8520-48XT-6C-DC-F | 95504-8520-48XT-6C-DC-F | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PW NBD AHR 8520-48XT-6C-DC-R | 95504-8520-48XT-6C-DC-R | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PW NBD AHR 8520-48Y-8C | 95504-8520-48Y-8C | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PW NBD AHR 8520-48Y-8C-AC-F | 95504-8520-48Y-8C-AC-F | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PW NBD AHR 8520-48Y-8C-AC-R | 95504-8520-48Y-8C-AC-R | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PW NBD AHR 8520-48Y-8C-DC-F | 95504-8520-48Y-8C-DC-F | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PW NBD AHR 8520-48Y-8C-DC-R | 95504-8520-48Y-8C-DC-R | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PW NBD AHR 86100 | 95504-86100 | \$ 4,770.00 | 6% | <i>\$4,517.43</i> |
| PW NBD AHR 86101 | 95504-86101 | \$ 6,557.00 | 6% | <i>\$6,209.81</i> |
| PW NBD AHR 87100 | 95504-87100 | \$ 2,960.00 | 6% | <i>\$2,803.27</i> |
| PW NBD AHR 87101 | 95504-87101 | \$ 4,556.00 | 6% | <i>\$4,314.76</i> |
| PW NBD AHR 8720-32C | 95504-8720-32C | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |

| | | | | |
|--------------------------|---------------------|--------------|----|--------------------|
| PW NBD AHR 8720-32C-AC-F | 95504-8720-32C-AC-F | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PW NBD AHR 8720-32C-AC-R | 95504-8720-32C-AC-R | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PW NBD AHR 8720-32C-DC-F | 95504-8720-32C-DC-F | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PW NBD AHR 8720-32C-DC-R | 95504-8720-32C-DC-R | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PW NBD AHR BD 8806 | 95504-8806 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| PW NBD AHR BD 8810 | 95504-8810 | \$ 3,862.00 | 6% | <i>\$3,657.51</i> |
| PW NBD AHR 88100 | 95504-88100 | \$ 5,389.00 | 6% | <i>\$5,103.65</i> |
| PW NBD AHR 8820-40C | 95504-8820-40C | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PW NBD AHR 8820-40C-AC-F | 95504-8820-40C-AC-F | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PW NBD AHR 8820-40C-AC-R | 95504-8820-40C-AC-R | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PW NBD AHR 8820-40C-DC-F | 95504-8820-40C-DC-F | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PW NBD AHR 8820-40C-DC-R | 95504-8820-40C-DC-R | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PW NBD AHR 8820-80C | 95504-8820-80C | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PW NBD AHR 8820-80C-AC-F | 95504-8820-80C-AC-F | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PW NBD AHR 8820-80C-AC-R | 95504-8820-80C-AC-R | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PW NBD AHR 8820-80C-DC-F | 95504-8820-80C-DC-F | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PW NBD AHR 8820-80C-DC-R | 95504-8820-80C-DC-R | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PW NBD AHR 9920-16C | 95504-9920-16C | \$ 7,541.00 | 6% | <i>\$7,141.70</i> |
| PW NBD AHR 9920-4D | 95504-9920-4D | \$ 7,541.00 | 6% | <i>\$7,141.70</i> |
| PW NBD AHR 9920-NPB-8 | 95504-9920-NPB-8 | \$ 13,716.00 | 6% | <i>\$12,989.74</i> |
| PW NBD AHR | 95504-A10148 | \$ 2,681.00 | 6% | <i>\$2,539.04</i> |
| PW NBD AHR | 95504-A10149 | \$ 5,112.00 | 6% | <i>\$4,841.32</i> |
| PW NBD AHR | 95504-A10152 | \$ 5,112.00 | 6% | <i>\$4,841.32</i> |
| PW NBD AHR | 95504-A10154 | \$ 15,587.00 | 6% | <i>\$14,761.67</i> |
| PW NBD AHR | 95504-A10155 | \$ 5,511.00 | 6% | <i>\$5,219.19</i> |

| | | | | |
|------------------------------|-------------------------|-------------|----|------------|
| PW NBD AHR | 95504-A10157 | \$ 9,739.00 | 6% | \$9,223.32 |
| PW NBD AHR 10175 | 95504-A10175 | \$ 5,459.00 | 6% | \$5,169.95 |
| PW NBD AHR A10176 | 95504-A10176 | \$ 8,192.00 | 6% | \$7,758.23 |
| PW NBD AHR AH-AP-1130-AC-CE | 95504-AH-AP-1130-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-1130-AC-FCC | 95504-AH-AP-1130-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-1130-AC-W | 95504-AH-AP-1130-AC-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-122-AC-CAN | 95504-AH-AP-122-AC-CAN | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-122-AC-CE | 95504-AH-AP-122-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-122-AC-FCC | 95504-AH-AP-122-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-122-AC-W | 95504-AH-AP-122-AC-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-130-AC-CE | 95504-AH-AP-130-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-130-AC-FCC | 95504-AH-AP-130-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-130-AC-W | 95504-AH-AP-130-AC-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-150W-AC-CAN | 95504-AH-AP-150W-AC-CAN | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-150W-AC-CE | 95504-AH-AP-150W-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-150W-AC-FCC | 95504-AH-AP-150W-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-150W-AC-W | 95504-AH-AP-150W-AC-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-230-AC-CE | 95504-AH-AP-230-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-230-AC-FCC | 95504-AH-AP-230-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-230-AC-W | 95504-AH-AP-230-AC-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-250-AC-CAN | 95504-AH-AP-250-AC-CAN | \$ 60.00 | 6% | \$56.82 |

| | | | | |
|------------------------------|-------------------------|----------|----|---------|
| PW NBD AHR AH-AP-250-AC-CE | 95504-AH-AP-250-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-250-AC-FCC | 95504-AH-AP-250-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-250-AC-W | 95504-AH-AP-250-AC-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-630-AX-CAN | 95504-AH-AP-630-AX-CAN | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-630-AX-CE | 95504-AH-AP-630-AX-CE | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-630-AX-FCC | 95504-AH-AP-630-AX-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-630-AX-W | 95504-AH-AP-630-AX-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-AP-650-AX-CAN | 95504-AH-AP-650-AX-CAN | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-AP-650-AX-CE | 95504-AH-AP-650-AX-CE | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-AP-650-AX-FCC | 95504-AH-AP-650-AX-FCC | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-AP-650-AX-W | 95504-AH-AP-650-AX-W | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-AP-650X-AX-CAN | 95504-AH-AP-650X-AX-CAN | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-AP-650X-AX-CE | 95504-AH-AP-650X-AX-CE | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-AP-650X-AX-FCC | 95504-AH-AP-650X-AX-FCC | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-AP-650X-AX-W | 95504-AH-AP-650X-AX-W | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR AH-ATOM-CAN | 95504-AH-ATOM-CAN | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-ATOM-CE-EU | 95504-AH-ATOM-CE-EU | \$ 63.00 | 6% | \$59.66 |
| PW NBD AHR AH-ATOM-CE-UK | 95504-AH-ATOM-CE-UK | \$ 63.00 | 6% | \$59.66 |
| PW NBD AHR AH-ATOM-FCC | 95504-AH-ATOM-FCC | \$ 60.00 | 6% | \$56.82 |

| | | | | |
|---------------------------|----------------------|----------|----|---------|
| PW NBD AHR AH-ATOM-W | 95504-AH-ATOM-W | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-ATOM-W-EU | 95504-AH-ATOM-W-EU | \$ 63.00 | 6% | \$59.66 |
| PW NBD AHR AH-ATOM-W-UK | 95504-AH-ATOM-W-UK | \$ 63.00 | 6% | \$59.66 |
| PW NBD AHR AH-SR-2208P-AU | 95504-AH-SR-2208P-AU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2208P-EU | 95504-AH-SR-2208P-EU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2208P-NA | 95504-AH-SR-2208P-NA | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2208P-UK | 95504-AH-SR-2208P-UK | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2224P-AU | 95504-AH-SR-2224P-AU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2224P-EU | 95504-AH-SR-2224P-EU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2224P-NA | 95504-AH-SR-2224P-NA | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2224P-UK | 95504-AH-SR-2224P-UK | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2324P-AU | 95504-AH-SR-2324P-AU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2324P-EU | 95504-AH-SR-2324P-EU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2324P-NA | 95504-AH-SR-2324P-NA | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2324P-UK | 95504-AH-SR-2324P-UK | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-SR-2348P-AU | 95504-AH-SR-2348P-AU | \$ 55.00 | 6% | \$52.09 |
| PW NBD AHR AH-SR-2348P-EU | 95504-AH-SR-2348P-EU | \$ 55.00 | 6% | \$52.09 |
| PW NBD AHR AH-SR-2348P-NA | 95504-AH-SR-2348P-NA | \$ 55.00 | 6% | \$52.09 |
| PW NBD AHR AH-SR-2348P-UK | 95504-AH-SR-2348P-UK | \$ 55.00 | 6% | \$52.09 |
| PW NBD AHR AH-XR200P-AU | 95504-AH-XR200P-AU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR200P-EU | 95504-AH-XR200P-EU | \$ 60.00 | 6% | \$56.82 |

| | | | | |
|------------------------------|-------------------------|-----------|----|----------|
| PW NBD AHR AH-XR200P-UK | 95504-AH-XR200P-UK | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR200P-US | 95504-AH-XR200P-US | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR600P | 95504-AH-XR600P | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR600P-AU | 95504-AH-XR600P-AU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR600P-EU | 95504-AH-XR600P-EU | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR600P-KR | 95504-AH-XR600P-KR | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR600P-UK | 95504-AH-XR600P-UK | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AH-XR600P-US | 95504-AH-XR600P-US | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP-8533-68SB30-IL | 95504-AP-8533-68SB30-IL | \$ 110.00 | 6% | \$104.18 |
| PW NBD AHR AP3000-IL | 95504-AP3000-IL | \$ 40.50 | 6% | \$38.36 |
| PW NBD AHR AP3000-TN | 95504-AP3000-TN | \$ 40.50 | 6% | \$38.36 |
| PW NBD AHR AP3000-WW | 95504-AP3000-WW | \$ 40.50 | 6% | \$38.36 |
| PW NBD AHR AP3000X-WW | 95504-AP3000X-WW | \$ 51.75 | 6% | \$49.01 |
| PW NBD AHR AP302W-CAN | 95504-AP302W-CAN | \$ 45.00 | 6% | \$42.62 |
| PW NBD AHR AP302W-EG | 95504-AP302W-EG | \$ 49.00 | 6% | \$46.41 |
| PW NBD AHR AP302W-FCC | 95504-AP302W-FCC | \$ 45.00 | 6% | \$42.62 |
| PW NBD AHR AP302W-WR | 95504-AP302W-WR | \$ 42.00 | 6% | \$39.78 |
| PW NBD AHR AP305C-1-CAN | 95504-AP305C-1-CAN | \$ 59.00 | 6% | \$55.88 |
| PW NBD AHR AP305C-1-EG | 95504-AP305C-1-EG | \$ 59.00 | 6% | \$55.88 |

| | | | | |
|-------------------------|--------------------|----------|----|---------|
| PW NBD AHR AP305C-1-FCC | 95504-AP305C-1-FCC | \$ 59.00 | 6% | \$55.88 |
| PW NBD AHR AP305C-1-IL | 95504-AP305C-1-IL | \$ 59.00 | 6% | \$55.88 |
| PW NBD AHR AP305C-1-WR | 95504-AP305C-1-WR | \$ 59.00 | 6% | \$55.88 |
| PW NBD AHR AP305C-CAN | 95504-AP305C-CAN | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305C-EG | 95504-AP305C-EG | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305C-FCC | 95504-AP305C-FCC | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305C-IL | 95504-AP305C-IL | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305C-WR | 95504-AP305C-WR | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305CX-CAN | 95504-AP305CX-CAN | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305CX-FCC | 95504-AP305CX-FCC | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305CX-IL | 95504-AP305CX-IL | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP305CX-WR | 95504-AP305CX-WR | \$ 64.00 | 6% | \$60.61 |
| PW NBD AHR AP310e-1-WR | 95504-AP310e-1-WR | \$ 38.00 | 6% | \$35.99 |
| PW NBD AHR AP310e-CAN | 95504-AP310e-CAN | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR AP310e-FCC | 95504-AP310e-FCC | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR AP310e-IL | 95504-AP310e-IL | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR AP310e-WR | 95504-AP310e-WR | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR AP310i-1-WR | 95504-AP310i-1-WR | \$ 38.00 | 6% | \$35.99 |
| PW NBD AHR AP310i-CAN | 95504-AP310i-CAN | \$ 40.00 | 6% | \$37.88 |

| | | | | |
|-------------------------|--------------------|----------|----|---------|
| PW NBD AHR AP310i-FCC | 95504-AP310i-FCC | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR AP310i-IL | 95504-AP310i-IL | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR AP310i-WR | 95504-AP310i-WR | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR AP360e-CAN | 95504-AP360e-CAN | \$ 57.00 | 6% | \$53.98 |
| PW NBD AHR AP360e-FCC | 95504-AP360e-FCC | \$ 57.00 | 6% | \$53.98 |
| PW NBD AHR AP360e-IL | 95504-AP360e-IL | \$ 57.00 | 6% | \$53.98 |
| PW NBD AHR AP360e-WR | 95504-AP360e-WR | \$ 57.00 | 6% | \$53.98 |
| PW NBD AHR AP360i-CAN | 95504-AP360i-CAN | \$ 57.00 | 6% | \$53.98 |
| PW NBD AHR AP360i-FCC | 95504-AP360i-FCC | \$ 57.00 | 6% | \$53.98 |
| PW NBD AHR AP360i-WR | 95504-AP360i-WR | \$ 57.00 | 6% | \$53.98 |
| PW NBD AHR AP4000-WW | 95504-AP4000-1-WW | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP4000-IL | 95504-AP4000-IL | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP4000-WW | 95504-AP4000-WW | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP410C-1-CAN | 95504-AP410C-1-CAN | \$ 56.00 | 6% | \$53.03 |
| PW NBD AHR AP410C-1-EG | 95504-AP410C-1-EG | \$ 56.00 | 6% | \$53.03 |
| PW NBD AHR AP410C-1-FCC | 95504-AP410C-1-FCC | \$ 56.00 | 6% | \$53.03 |
| PW NBD AHR AP410C-1-IL | 95504-AP410C-1-IL | \$ 56.00 | 6% | \$53.03 |
| PW NBD AHR AP410C-1-WR | 95504-AP410C-1-WR | \$ 56.00 | 6% | \$53.03 |
| PW NBD AHR AP410C-CAN | 95504-AP410C-CAN | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP410C-EG | 95504-AP410C-EG | \$ 60.00 | 6% | \$56.82 |

| | | | | |
|-------------------------|--------------------|----------|----|---------|
| PW NBD AHR AP410C-FCC | 95504-AP410C-FCC | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP410C-IL | 95504-AP410C-IL | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP410C-WR | 95504-AP410C-WR | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR AP410e-CAN | 95504-AP410e-CAN | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR AP410e-FCC | 95504-AP410e-FCC | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR AP410e-WR | 95504-AP410e-WR | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR AP410i-1-FCC | 95504-AP410i-1-FCC | \$ 67.00 | 6% | \$63.45 |
| PW NBD AHR AP410i-1-WR | 95504-AP410i-1-WR | \$ 67.00 | 6% | \$63.45 |
| PW NBD AHR AP410i-CAN | 95504-AP410i-CAN | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR AP410i-FCC | 95504-AP410i-FCC | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR AP410i-IL | 95504-AP410i-IL | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR AP410i-WR | 95504-AP410i-WR | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR AP460C-CAN | 95504-AP460C-CAN | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR AP460C-EG | 95504-AP460C-EG | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR AP460C-FCC | 95504-AP460C-FCC | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR AP460C-IL | 95504-AP460C-IL | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR AP460C-WR | 95504-AP460C-WR | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR AP460e-CAN | 95504-AP460e-CAN | \$ 82.00 | 6% | \$77.66 |
| PW NBD AHR AP460e-FCC | 95504-AP460e-FCC | \$ 82.00 | 6% | \$77.66 |
| PW NBD AHR AP460e-WR | 95504-AP460e-WR | \$ 78.00 | 6% | \$73.87 |
| PW NBD AHR AP460i-CAN | 95504-AP460i-CAN | \$ 78.00 | 6% | \$73.87 |

| | | | | |
|---------------------------|----------------------|-----------|----|-----------------|
| PW NBD AHR AP460i-FCC | 95504-AP460i-FCC | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD AHR AP460i-IL | 95504-AP460i-IL | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD AHR AP460i-WR | 95504-AP460i-WR | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD AHR AP460S12C-CAN | 95504-AP460S12C-CAN | \$ 62.00 | 6% | <i>\$58.72</i> |
| PW NBD AHR AP460S12C-FCC | 95504-AP460S12C-FCC | \$ 62.00 | 6% | <i>\$58.72</i> |
| PW NBD AHR AP460S12C-WR | 95504-AP460S12C-WR | \$ 62.00 | 6% | <i>\$58.72</i> |
| PW NBD AHR AP460S6C-CAN | 95504-AP460S6C-CAN | \$ 62.00 | 6% | <i>\$58.72</i> |
| PW NBD AHR AP460S6C-FCC | 95504-AP460S6C-FCC | \$ 62.00 | 6% | <i>\$58.72</i> |
| PW NBD AHR AP460S6C-WR | 95504-AP460S6C-WR | \$ 62.00 | 6% | <i>\$58.72</i> |
| PW NBD AHR AP5010-IL | 95504-AP5010-IL | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW NBD AHR AP5010-WW | 95504-AP5010-WW | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW NBD AHR AP5020-WW | 95504-AP5020-WW | \$ 107.96 | 6% | <i>\$102.24</i> |
| PW NBD AHR AP5050D-WW | 95504-AP5050D-WW | \$ 245.00 | 6% | <i>\$232.03</i> |
| PW NBD AHR AP5050U-WW | 95504-AP5050U-WW | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR AP505i-FCC | 95504-AP505i-FCC | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD AHR AP505i-FCC-TAA | 95504-AP505i-FCC-TAA | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD AHR AP505i-WR | 95504-AP505i-WR | \$ 90.00 | 6% | <i>\$85.23</i> |
| PW NBD AHR AP510C-CAN | 95504-AP510C-CAN | \$ 52.00 | 6% | <i>\$49.25</i> |

| | | | | |
|---------------------------|----------------------|-----------|----|-----------------|
| PW NBD AHR AP510C-CE | 95504-AP510C-CE | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD AHR AP510C-FCC | 95504-AP510C-FCC | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD AHR AP510C-W | 95504-AP510C-W | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD AHR AP510C-WW | 95504-AP510C-WW | \$ 60.00 | 6% | <i>\$56.82</i> |
| PW NBD AHR AP510CX-CAN | 95504-AP510CX-CAN | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD AHR AP510CX-CE | 95504-AP510CX-CE | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD AHR AP510CX-FCC | 95504-AP510CX-FCC | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD AHR AP510CX-W | 95504-AP510CX-W | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD AHR AP510CX-WW | 95504-AP510CX-WW | \$ 60.00 | 6% | <i>\$56.82</i> |
| PW NBD AHR AP510e-FCC | 95504-AP510e-FCC | \$ 113.00 | 6% | <i>\$107.02</i> |
| PW NBD AHR AP510e-FCC-TAA | 95504-AP510e-FCC-TAA | \$ 113.00 | 6% | <i>\$107.02</i> |
| PW NBD AHR AP510e-WR | 95504-AP510e-WR | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD AHR AP510i-1-FCC | 95504-AP510i-1-FCC | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW NBD AHR AP510i-1-WR | 95504-AP510i-1-WR | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW NBD AHR AP510i-FCC | 95504-AP510i-FCC | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW NBD AHR AP510i-FCC-TAA | 95504-AP510i-FCC-TAA | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW NBD AHR AP510i-WR | 95504-AP510i-WR | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW NBD AHR AP560h-FCC | 95504-AP560h-FCC | \$ 250.00 | 6% | <i>\$236.76</i> |
| PW NBD AHR AP560h-WR | 95504-AP560h-WR | \$ 250.00 | 6% | <i>\$236.76</i> |

| | | | | |
|-----------------------|------------------|-------------|----|------------|
| PW NBD AHR AP560i-FCC | 95504-AP560i-FCC | \$ 182.00 | 6% | \$172.36 |
| PW NBD AHR AP560i-WR | 95504-AP560i-WR | \$ 173.00 | 6% | \$163.84 |
| PW NBD AHR AP560m-FCC | 95504-AP560m-FCC | \$ 182.00 | 6% | \$172.36 |
| PW NBD AHR AP560t-FCC | 95504-AP560t-FCC | \$ 250.00 | 6% | \$236.76 |
| PW NBD AHR AP560u-FCC | 95504-AP560u-FCC | \$ 169.00 | 6% | \$160.05 |
| PW NBD AHR E2122 | 95504-E2122 | \$ 4,219.00 | 6% | \$3,995.60 |
| PW NBD AHR E2122-1 | 95504-E2122-1 | \$ 3,999.00 | 6% | \$3,787.25 |
| PW NBD AHR E3120-1 | 95504-E3120-1 | \$ 6,541.00 | 6% | \$6,194.65 |
| PW NBD AHR E3125 | 95504-E3125 | \$ 7,060.00 | 6% | \$6,686.17 |
| PW NBD AHR | 95504-H30003 | \$ 36.00 | 6% | \$34.09 |
| PW NBD AHR | 95504-H30004 | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR | 95504-H30005 | \$ 44.00 | 6% | \$41.67 |
| PW NBD AHR | 95504-H30006 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR | 95504-H30007 | \$ 78.00 | 6% | \$73.87 |
| PW NBD AHR | 95504-H30008 | \$ 152.00 | 6% | \$143.95 |
| PW NBD AHR | 95504-H30009 | \$ 36.00 | 6% | \$34.09 |
| PW NBD AHR | 95504-H30010 | \$ 73.00 | 6% | \$69.13 |
| PW NBD AHR | 95504-H30011 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR | 95504-H30012 | \$ 100.00 | 6% | \$94.71 |
| PW NBD AHR | 95504-H30078 | \$ 1,709.00 | 6% | \$1,618.51 |
| PW NBD AHR | 95504-H30104 | \$ 1,578.00 | 6% | \$1,494.44 |
| PW NBD AHR | 95504-H30105 | \$ 1,559.00 | 6% | \$1,476.45 |
| PW NBD AHR | 95504-H30131 | \$ 893.00 | 6% | \$845.72 |
| PW NBD AHR | 95504-H30132 | \$ 875.00 | 6% | \$828.67 |
| PW NBD AHR | 95504-H30133 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30134 | \$ 2,921.00 | 6% | \$2,766.33 |
| PW NBD AHR | 95504-H30135 | \$ 2,355.00 | 6% | \$2,230.30 |
| PW NBD AHR | 95504-H30136 | \$ 2,921.00 | 6% | \$2,766.33 |
| PW NBD AHR | 95504-H30184 | \$ 42.00 | 6% | \$39.78 |
| PW NBD AHR | 95504-H30185 | \$ 207.00 | 6% | \$196.04 |
| PW NBD AHR | 95504-H30186 | \$ 108.00 | 6% | \$102.28 |
| PW NBD AHR | 95504-H30187 | \$ 47.00 | 6% | \$44.51 |
| PW NBD AHR | 95504-H30188 | \$ 108.00 | 6% | \$102.28 |
| PW NBD AHR | 95504-H30189 | \$ 108.00 | 6% | \$102.28 |
| PW NBD AHR | 95504-H30190 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30214 | \$ 116.00 | 6% | \$109.86 |
| PW NBD AHR | 95504-H30215 | \$ 116.00 | 6% | \$109.86 |

| | | | | |
|------------|--------------|-------------|----|------------|
| PW NBD AHR | 95504-H30216 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30217 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30218 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30219 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30220 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30221 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30222 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30223 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30224 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30225 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30226 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30227 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30228 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30229 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30267 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30268 | \$ 221.00 | 6% | \$209.30 |
| PW NBD AHR | 95504-H30269 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30270 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30271 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30272 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30273 | \$ 486.00 | 6% | \$460.27 |
| PW NBD AHR | 95504-H30274 | \$ 486.00 | 6% | \$460.27 |
| PW NBD AHR | 95504-H30275 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30276 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30277 | \$ 486.00 | 6% | \$460.27 |
| PW NBD AHR | 95504-H30278 | \$ 529.00 | 6% | \$500.99 |
| PW NBD AHR | 95504-H30279 | \$ 486.00 | 6% | \$460.27 |
| PW NBD AHR | 95504-H30280 | \$ 486.00 | 6% | \$460.27 |
| PW NBD AHR | 95504-H30281 | \$ 564.00 | 6% | \$534.14 |
| PW NBD AHR | 95504-H30282 | \$ 486.00 | 6% | \$460.27 |
| PW NBD AHR | 95504-H30283 | \$ 321.00 | 6% | \$304.00 |
| PW NBD AHR | 95504-H30284 | \$ 353.00 | 6% | \$334.31 |
| PW NBD AHR | 95504-H30293 | \$ 1,925.00 | 6% | \$1,823.07 |
| PW NBD AHR | 95504-H30296 | \$ 116.00 | 6% | \$109.86 |
| PW NBD AHR | 95504-H30297 | \$ 106.00 | 6% | \$100.39 |
| PW NBD AHR | 95504-H30298 | \$ 116.00 | 6% | \$109.86 |
| PW NBD AHR | 95504-H30299 | \$ 106.00 | 6% | \$100.39 |
| PW NBD AHR | 95504-H30380 | \$ 3,136.00 | 6% | \$2,969.95 |
| PW NBD AHR | 95504-H30381 | \$ 316.00 | 6% | \$299.27 |
| PW NBD AHR | 95504-H30383 | \$ 4,460.00 | 6% | \$4,223.84 |
| PW NBD AHR | 95504-H30384 | \$ 257.00 | 6% | \$243.39 |
| PW NBD AHR | 95504-H30391 | \$ 605.00 | 6% | \$572.97 |

| | | | | |
|------------|--------------|-------------|----|------------|
| PW NBD AHR | 95504-H30392 | \$ 605.00 | 6% | \$572.97 |
| PW NBD AHR | 95504-H30393 | \$ 271.00 | 6% | \$256.65 |
| PW NBD AHR | 95504-H30394 | \$ 1,164.00 | 6% | \$1,102.37 |
| PW NBD AHR | 95504-H30395 | \$ 1,391.00 | 6% | \$1,317.35 |
| PW NBD AHR | 95504-H30396 | \$ 1,268.00 | 6% | \$1,200.86 |
| PW NBD AHR | 95504-H30397 | \$ 1,510.00 | 6% | \$1,430.05 |
| PW NBD AHR | 95504-H30398 | \$ 277.00 | 6% | \$262.33 |
| PW NBD AHR | 95504-H30400 | \$ 155.00 | 6% | \$146.79 |
| PW NBD AHR | 95504-H30401 | \$ 216.00 | 6% | \$204.56 |
| PW NBD AHR | 95504-H30402 | \$ 232.00 | 6% | \$219.72 |
| PW NBD AHR | 95504-H30403 | \$ 341.00 | 6% | \$322.94 |
| PW NBD AHR | 95504-H30434 | \$ 93.00 | 6% | \$88.08 |
| PW NBD AHR | 95504-H30480 | \$ 399.00 | 6% | \$377.87 |
| PW NBD AHR | 95504-H30495 | \$ 893.00 | 6% | \$845.72 |
| PW NBD AHR | 95504-H30496 | \$ 875.00 | 6% | \$828.67 |
| PW NBD AHR | 95504-H30497 | \$ 1,293.00 | 6% | \$1,224.54 |
| PW NBD AHR | 95504-H30498 | \$ 1,268.00 | 6% | \$1,200.86 |
| PW NBD AHR | 95504-H30499 | \$ 435.00 | 6% | \$411.97 |
| PW NBD AHR | 95504-H30501 | \$ 1,268.00 | 6% | \$1,200.86 |
| PW NBD AHR | 95504-H30502 | \$ 1,949.00 | 6% | \$1,845.80 |
| PW NBD AHR | 95504-H30503 | \$ 435.00 | 6% | \$411.97 |
| PW NBD AHR | 95504-H30505 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30506 | \$ 3,140.00 | 6% | \$2,973.74 |
| PW NBD AHR | 95504-H30509 | \$ 1,949.00 | 6% | \$1,845.80 |
| PW NBD AHR | 95504-H30510 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30511 | \$ 3,140.00 | 6% | \$2,973.74 |
| PW NBD AHR | 95504-H30512 | \$ 435.00 | 6% | \$411.97 |
| PW NBD AHR | 95504-H30513 | \$ 729.00 | 6% | \$690.40 |
| PW NBD AHR | 95504-H30525 | \$ 3,140.00 | 6% | \$2,973.74 |
| PW NBD AHR | 95504-H30526 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30528 | \$ 3,636.00 | 6% | \$3,443.47 |
| PW NBD AHR | 95504-H30531 | \$ 5,180.00 | 6% | \$4,905.72 |
| PW NBD AHR | 95504-H30532 | \$ 5,180.00 | 6% | \$4,905.72 |
| PW NBD AHR | 95504-H30534 | \$ 5,279.00 | 6% | \$4,999.48 |
| PW NBD AHR | 95504-H30535 | \$ 5,643.00 | 6% | \$5,344.20 |
| PW NBD AHR | 95504-H30536 | \$ 5,180.00 | 6% | \$4,905.72 |
| PW NBD AHR | 95504-H30537 | \$ 5,643.00 | 6% | \$5,344.20 |
| PW NBD AHR | 95504-H30538 | \$ 3,140.00 | 6% | \$2,973.74 |
| PW NBD AHR | 95504-H30539 | \$ 5,911.00 | 6% | \$5,598.01 |
| PW NBD AHR | 95504-H30540 | \$ 6,232.00 | 6% | \$5,902.02 |
| PW NBD AHR | 95504-H30543 | \$ 425.00 | 6% | \$402.50 |
| PW NBD AHR | 95504-H30544 | \$ 754.00 | 6% | \$714.08 |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| PW NBD AHR | 95504-H30548 | \$ 425.00 | 6% | \$402.50 |
| PW NBD AHR | 95504-H30549 | \$ 715.00 | 6% | \$677.14 |
| PW NBD AHR | 95504-H30550 | \$ 715.00 | 6% | \$677.14 |
| PW NBD AHR | 95504-H30552 | \$ 425.00 | 6% | \$402.50 |
| PW NBD AHR | 95504-H30553 | \$ 677.00 | 6% | \$641.15 |
| PW NBD AHR | 95504-H30567 | \$ 2,614.00 | 6% | \$2,475.59 |
| PW NBD AHR | 95504-H30569 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30570 | \$ 2,769.00 | 6% | \$2,622.38 |
| PW NBD AHR | 95504-H30571 | \$ 2,769.00 | 6% | \$2,622.38 |
| PW NBD AHR | 95504-H30573 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30574 | \$ 2,553.00 | 6% | \$2,417.82 |
| PW NBD AHR | 95504-H30575 | \$ 1,590.00 | 6% | \$1,505.81 |
| PW NBD AHR | 95504-H30576 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30577 | \$ 2,769.00 | 6% | \$2,622.38 |
| PW NBD AHR | 95504-H30578 | \$ 2,769.00 | 6% | \$2,622.38 |
| PW NBD AHR | 95504-H30587 | \$ 2,355.00 | 6% | \$2,230.30 |
| PW NBD AHR | 95504-H30588 | \$ 1,620.00 | 6% | \$1,534.22 |
| PW NBD AHR | 95504-H30589 | \$ 2,517.00 | 6% | \$2,383.72 |
| PW NBD AHR | 95504-H30591 | \$ 4,308.00 | 6% | \$4,079.89 |
| PW NBD AHR | 95504-H30632 | \$ 65.00 | 6% | \$61.56 |
| PW NBD AHR | 95504-H30633 | \$ 65.00 | 6% | \$61.56 |
| PW NBD AHR | 95504-H30643 | \$ 3,959.00 | 6% | \$3,749.37 |
| PW NBD AHR | 95504-H30706 | \$ 3,707.00 | 6% | \$3,510.71 |
| PW NBD AHR | 95504-H30707 | \$ 2,310.00 | 6% | \$2,187.69 |
| PW NBD AHR | 95504-H30724 | \$ 257.00 | 6% | \$243.39 |
| PW NBD AHR | 95504-H30725 | \$ 875.00 | 6% | \$828.67 |
| PW NBD AHR | 95504-H30726 | \$ 5,753.00 | 6% | \$5,448.38 |
| PW NBD AHR | 95504-H30727 | \$ 6,113.00 | 6% | \$5,789.32 |
| PW NBD AHR | 95504-H30730 | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR | 95504-H30731 | \$ 50.00 | 6% | \$47.35 |
| PW NBD AHR 30732 | 95504-H30732 | \$ 1,527.00 | 6% | \$1,446.15 |
| PW NBD AHR SKL8008-0810-F8 | 95504-H30733 | \$ 6,381.00 | 6% | \$6,043.13 |
| PW NBD AHR STL2006-0850 | 95504-H30734 | \$ 4,870.00 | 6% | \$4,612.13 |
| PW NBD AHR SGL2001-0850 | 95504-H30735 | \$ 5,392.00 | 6% | \$5,106.49 |
| PW NBD AHR SOK2209-0204 | 95504-H30736 | \$ 863.00 | 6% | \$817.30 |
| PW NBD AHR H30738 | 95504-H30738 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR -H30739 | 95504-H30739 | \$ 807.00 | 6% | \$764.27 |
| PW NBD AHR -H30740 | 95504-H30740 | \$ 464.00 | 6% | \$439.43 |
| PW NBD AHR -H30741 | 95504-H30741 | \$ 855.00 | 6% | \$809.73 |
| PW NBD AHR -H30742 | 95504-H30742 | \$ 756.00 | 6% | \$715.97 |
| PW NBD AHR -H30743 | 95504-H30743 | \$ 807.00 | 6% | \$764.27 |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PW NBD AHR -H30744 | 95504-H30744 | \$ 464.00 | 6% | \$439.43 |
| PW NBD AHR -H30745 | 95504-H30745 | \$ 473.00 | 6% | \$447.95 |
| PW NBD AHR -H30746 | 95504-H30746 | \$ 965.00 | 6% | \$913.90 |
| PW NBD AHR -H30747 | 95504-H30747 | \$ 1,673.00 | 6% | \$1,584.41 |
| PW NBD AHR -H30748 | 95504-H30748 | \$ 2,473.00 | 6% | \$2,342.05 |
| PW NBD AHR -H30749 | 95504-H30749 | \$ 5,550.00 | 6% | \$5,256.13 |
| PW NBD AHR -H30750 | 95504-H30750 | \$ 5,550.00 | 6% | \$5,256.13 |
| PW NBD AHR -H30751 | 95504-H30751 | \$ 3,302.00 | 6% | \$3,127.16 |
| PW NBD AHR -H30754 | 95504-H30754 | \$ 5,550.00 | 6% | \$5,256.13 |
| PW NBD AHR -H30755 | 95504-H30755 | \$ 6,041.00 | 6% | \$5,721.13 |
| PW NBD AHR -H30756 | 95504-H30756 | \$ 5,550.00 | 6% | \$5,256.13 |
| PW NBD AHR -H30757 | 95504-H30757 | \$ 2,473.00 | 6% | \$2,342.05 |
| PW NBD AHR -H30758 | 95504-H30758 | \$ 5,214.00 | 6% | \$4,937.92 |
| PW NBD AHR -H30759 | 95504-H30759 | \$ 5,661.00 | 6% | \$5,361.25 |
| PW NBD AHR -H30760 | 95504-H30760 | \$ 6,704.00 | 6% | \$6,349.02 |
| PW NBD AHR -H30761 | 95504-H30761 | \$ 2,473.00 | 6% | \$2,342.05 |
| PW NBD AHR -H30762 | 95504-H30762 | \$ 6,041.00 | 6% | \$5,721.13 |
| PW NBD AHR -H30763 | 95504-H30763 | \$ 6,041.00 | 6% | \$5,721.13 |
| PW NBD AHR -H30764 | 95504-H30764 | \$ 3,816.00 | 6% | \$3,613.94 |
| PW NBD AHR -H30765 | 95504-H30765 | \$ 3,364.00 | 6% | \$3,185.88 |
| PW NBD AHR -H30766 | 95504-H30766 | \$ 6,538.00 | 6% | \$6,191.81 |
| PW NBD AHR -H30767 | 95504-H30767 | \$ 3,816.00 | 6% | \$3,613.94 |
| PW NBD AHR H30769 | 95504-H30769 | \$ 1,970.00 | 6% | \$1,865.69 |
| PW NBD AHR H30773 | 95504-H30773 | \$ 122.00 | 6% | \$115.54 |
| PW NBD AHR H30774 | 95504-H30774 | \$ 131.00 | 6% | \$124.06 |
| PW NBD AHR H30775 | 95504-H30775 | \$ 131.00 | 6% | \$124.06 |
| PW NBD AHR H30776 | 95504-H30776 | \$ 122.00 | 6% | \$115.54 |
| PW NBD AHR H30777 | 95504-H30777 | \$ 131.00 | 6% | \$124.06 |
| PW NBD AHR H30778 | 95504-H30778 | \$ 131.00 | 6% | \$124.06 |
| PW NBD AHR H30779 | 95504-H30779 | \$ 71.00 | 6% | \$67.24 |
| PW NBD AHR H30780 | 95504-H30780 | \$ 72.00 | 6% | \$68.19 |
| PW NBD AHR H30781 | 95504-H30781 | \$ 72.00 | 6% | \$68.19 |
| PW NBD AHR H30782 | 95504-H30782 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30783 | 95504-H30783 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H30784 | 95504-H30784 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H30785 | 95504-H30785 | \$ 71.00 | 6% | \$67.24 |
| PW NBD AHR H30786 | 95504-H30786 | \$ 72.00 | 6% | \$68.19 |
| PW NBD AHR H30787 | 95504-H30787 | \$ 71.00 | 6% | \$67.24 |
| PW NBD AHR H30788 | 95504-H30788 | \$ 72.00 | 6% | \$68.19 |
| PW NBD AHR H30789 | 95504-H30789 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H30790 | 95504-H30790 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30791 | 95504-H30791 | \$ 62.00 | 6% | \$58.72 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H30793 | 95504-H30793 | \$ 55.00 | 6% | \$52.09 |
| PW NBD AHR H30794 | 95504-H30794 | \$ 69.00 | 6% | \$65.35 |
| PW NBD AHR H30795 | 95504-H30795 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30796 | 95504-H30796 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30797 | 95504-H30797 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30798 | 95504-H30798 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30799 | 95504-H30799 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30800 | 95504-H30800 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30801 | 95504-H30801 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30802 | 95504-H30802 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30803 | 95504-H30803 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30804 | 95504-H30804 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30805 | 95504-H30805 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30806 | 95504-H30806 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30807 | 95504-H30807 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30808 | 95504-H30808 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30809 | 95504-H30809 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30810 | 95504-H30810 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30811 | 95504-H30811 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30812 | 95504-H30812 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30813 | 95504-H30813 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30814 | 95504-H30814 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30815 | 95504-H30815 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30816 | 95504-H30816 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30817 | 95504-H30817 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30818 | 95504-H30818 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30819 | 95504-H30819 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30820 | 95504-H30820 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30821 | 95504-H30821 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30822 | 95504-H30822 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30823 | 95504-H30823 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30824 | 95504-H30824 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30825 | 95504-H30825 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30826 | 95504-H30826 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30827 | 95504-H30827 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30828 | 95504-H30828 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30829 | 95504-H30829 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H30830 | 95504-H30830 | \$ 86.00 | 6% | \$81.45 |
| PW NBD AHR H30831 | 95504-H30831 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H30832 | 95504-H30832 | \$ 1,093.00 | 6% | \$1,035.13 |
| PW NBD AHR H30833 | 95504-H30833 | \$ 290.00 | 6% | \$274.64 |
| PW NBD AHR H30834 | 95504-H30834 | \$ 290.00 | 6% | \$274.64 |

| | | | | |
|-------------------|--------------|-------------|----|-------------------|
| PW NBD AHR H30836 | 95504-H30836 | \$ 1,093.00 | 6% | <i>\$1,035.13</i> |
| PW NBD AHR H30838 | 95504-H30838 | \$ 41.00 | 6% | <i>\$38.83</i> |
| PW NBD AHR H30839 | 95504-H30839 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD AHR H30840 | 95504-H30840 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD AHR H30841 | 95504-H30841 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD AHR H30842 | 95504-H30842 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD AHR H30843 | 95504-H30843 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD AHR H30844 | 95504-H30844 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD AHR H30845 | 95504-H30845 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD AHR H30846 | 95504-H30846 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30847 | 95504-H30847 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30848 | 95504-H30848 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30849 | 95504-H30849 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30850 | 95504-H30850 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30851 | 95504-H30851 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30852 | 95504-H30852 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30853 | 95504-H30853 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30854 | 95504-H30854 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30855 | 95504-H30855 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30856 | 95504-H30856 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30857 | 95504-H30857 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30858 | 95504-H30858 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30859 | 95504-H30859 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30860 | 95504-H30860 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD AHR H30866 | 95504-H30866 | \$ 118.00 | 6% | <i>\$111.75</i> |
| PW NBD AHR H30867 | 95504-H30867 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30868 | 95504-H30868 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H30869 | 95504-H30869 | \$ 207.00 | 6% | <i>\$196.04</i> |
| PW NBD AHR H30870 | 95504-H30870 | \$ 207.00 | 6% | <i>\$196.04</i> |
| PW NBD AHR H30871 | 95504-H30871 | \$ 190.00 | 6% | <i>\$179.94</i> |
| PW NBD AHR H30872 | 95504-H30872 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD AHR H30873 | 95504-H30873 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD AHR H30874 | 95504-H30874 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD AHR H30875 | 95504-H30875 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PW NBD AHR H30876 | 95504-H30876 | \$ 36.00 | 6% | <i>\$34.09</i> |
| PW NBD AHR H30877 | 95504-H30877 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PW NBD AHR H30878 | 95504-H30878 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PW NBD AHR H30891 | 95504-H30891 | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD AHR H30892 | 95504-H30892 | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD AHR H30893 | 95504-H30893 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW NBD AHR H30894 | 95504-H30894 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PW NBD AHR H30895 | 95504-H30895 | \$ 131.00 | 6% | <i>\$124.06</i> |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H30896 | 95504-H30896 | \$ 309.00 | 6% | \$292.64 |
| PW NBD AHR H30897 | 95504-H30897 | \$ 543.00 | 6% | \$514.25 |
| PW NBD AHR H30898 | 95504-H30898 | \$ 608.00 | 6% | \$575.81 |
| PW NBD AHR H30900 | 95504-H30900 | \$ 1,839.00 | 6% | \$1,741.62 |
| PW NBD AHR H30901 | 95504-H30901 | \$ 2,448.00 | 6% | \$2,318.38 |
| PW NBD AHR H30902 | 95504-H30902 | \$ 2,567.00 | 6% | \$2,431.08 |
| PW NBD AHR H30904 | 95504-H30904 | \$ 3,781.00 | 6% | \$3,580.80 |
| PW NBD AHR H30905 | 95504-H30905 | \$ 5,403.00 | 6% | \$5,116.91 |
| PW NBD AHR H30906 | 95504-H30906 | \$ 146.00 | 6% | \$138.27 |
| PW NBD AHR H30912 | 95504-H30912 | \$ 406.00 | 6% | \$384.50 |
| PW NBD AHR H30913 | 95504-H30913 | \$ 43.00 | 6% | \$40.72 |
| PW NBD AHR H30914 | 95504-H30914 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H30915 | 95504-H30915 | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR H30916 | 95504-H30916 | \$ 40.00 | 6% | \$37.88 |
| PW NBD AHR H30917 | 95504-H30917 | \$ 43.00 | 6% | \$40.72 |
| PW NBD AHR H30918 | 95504-H30918 | \$ 43.00 | 6% | \$40.72 |
| PW NBD AHR H30946 | 95504-H30946 | \$ 77.00 | 6% | \$72.92 |
| PW NBD AHR H30948 | 95504-H30948 | \$ 77.00 | 6% | \$72.92 |
| PW NBD AHR H30950 | 95504-H30950 | \$ 85.00 | 6% | \$80.50 |
| PW NBD AHR H30951 | 95504-H30951 | \$ 77.00 | 6% | \$72.92 |
| PW NBD AHR H30952 | 95504-H30952 | \$ 77.00 | 6% | \$72.92 |
| PW NBD AHR H30966 | 95504-H30966 | \$ 131.00 | 6% | \$124.06 |
| PW NBD AHR H30967 | 95504-H30967 | \$ 122.00 | 6% | \$115.54 |
| PW NBD AHR H30968 | 95504-H30968 | \$ 131.00 | 6% | \$124.06 |
| PW NBD AHR H30969 | 95504-H30969 | \$ 69.00 | 6% | \$65.35 |
| PW NBD AHR H30970 | 95504-H30970 | \$ 96.00 | 6% | \$90.92 |
| PW NBD AHR H30971 | 95504-H30971 | \$ 83.00 | 6% | \$78.61 |
| PW NBD AHR H30972 | 95504-H30972 | \$ 96.00 | 6% | \$90.92 |
| PW NBD AHR H30973 | 95504-H30973 | \$ 136.00 | 6% | \$128.80 |
| PW NBD AHR H30974 | 95504-H30974 | \$ 118.00 | 6% | \$111.75 |
| PW NBD AHR H30975 | 95504-H30975 | \$ 136.00 | 6% | \$128.80 |
| PW NBD AHR H30976 | 95504-H30976 | \$ 136.00 | 6% | \$128.80 |
| PW NBD AHR H30977 | 95504-H30977 | \$ 118.00 | 6% | \$111.75 |
| PW NBD AHR H30978 | 95504-H30978 | \$ 136.00 | 6% | \$128.80 |
| PW NBD AHR H30995 | 95504-H30995 | \$ 1,478.00 | 6% | \$1,399.74 |
| PW NBD AHR H31030 | 95504-H31030 | \$ 4,773.00 | 6% | \$4,520.27 |
| PW NBD AHR H31031 | 95504-H31031 | \$ 380.00 | 6% | \$359.88 |
| PW NBD AHR H31033 | 95504-H31033 | \$ 2,892.00 | 6% | \$2,738.87 |
| PW NBD AHR H31034 | 95504-H31034 | \$ 1,608.00 | 6% | \$1,522.86 |
| PW NBD AHR H31035 | 95504-H31035 | \$ 1,682.00 | 6% | \$1,592.94 |
| PW NBD AHR H31036 | 95504-H31036 | \$ 3,368.00 | 6% | \$3,189.66 |
| PW NBD AHR H31040 | 95504-H31040 | \$ 125.00 | 6% | \$118.38 |

| | | | | |
|-------------------|--------------|-------------|----|-------------------|
| PW NBD AHR H31041 | 95504-H31041 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW NBD AHR H31042 | 95504-H31042 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H31043 | 95504-H31043 | \$ 134.00 | 6% | <i>\$126.90</i> |
| PW NBD AHR H31047 | 95504-H31047 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW NBD AHR H31049 | 95504-H31049 | \$ 1,344.00 | 6% | <i>\$1,272.84</i> |
| PW NBD AHR H31060 | 95504-H31060 | \$ 35.00 | 6% | <i>\$33.15</i> |
| PW NBD AHR H31062 | 95504-H31062 | \$ 37.00 | 6% | <i>\$35.04</i> |
| PW NBD AHR H31066 | 95504-H31066 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PW NBD AHR H31068 | 95504-H31068 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PW NBD AHR H31076 | 95504-H31076 | \$ 183.00 | 6% | <i>\$173.31</i> |
| PW NBD AHR H31077 | 95504-H31077 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H31078 | 95504-H31078 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H31103 | 95504-H31103 | \$ 3,083.00 | 6% | <i>\$2,919.76</i> |
| PW NBD AHR H31119 | 95504-H31119 | \$ 70.00 | 6% | <i>\$66.29</i> |
| PW NBD AHR H31124 | 95504-H31124 | \$ 74.00 | 6% | <i>\$70.08</i> |
| PW NBD AHR H31127 | 95504-H31127 | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW NBD AHR H31132 | 95504-H31132 | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW NBD AHR H31134 | 95504-H31134 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PW NBD AHR H31135 | 95504-H31135 | \$ 44.00 | 6% | <i>\$41.67</i> |
| PW NBD AHR H31136 | 95504-H31136 | \$ 64.00 | 6% | <i>\$60.61</i> |
| PW NBD AHR H31137 | 95504-H31137 | \$ 59.00 | 6% | <i>\$55.88</i> |
| PW NBD AHR H31197 | 95504-H31197 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H31198 | 95504-H31198 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H31199 | 95504-H31199 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H31200 | 95504-H31200 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H31201 | 95504-H31201 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H31202 | 95504-H31202 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD AHR H31203 | 95504-H31203 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD AHR H31204 | 95504-H31204 | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD AHR H31205 | 95504-H31205 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD AHR H31206 | 95504-H31206 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD AHR H31207 | 95504-H31207 | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD AHR H31208 | 95504-H31208 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD AHR H31210 | 95504-H31210 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW NBD AHR H31335 | 95504-H31335 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW NBD AHR H31337 | 95504-H31337 | \$ 6,362.00 | 6% | <i>\$6,025.13</i> |
| PW NBD AHR H31338 | 95504-H31338 | \$ 6,362.00 | 6% | <i>\$6,025.13</i> |
| PW NBD AHR H31339 | 95504-H31339 | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| PW NBD AHR H31340 | 95504-H31340 | \$ 2,210.00 | 6% | <i>\$2,092.98</i> |
| PW NBD AHR H31341 | 95504-H31341 | \$ 3,275.00 | 6% | <i>\$3,101.59</i> |
| PW NBD AHR H31342 | 95504-H31342 | \$ 1,030.00 | 6% | <i>\$975.46</i> |
| PW NBD AHR H31343 | 95504-H31343 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PW NBD AHR H31344 | 95504-H31344 | \$ 1,524.00 | 6% | \$1,443.30 |
| PW NBD AHR H31345 | 95504-H31345 | \$ 1,524.00 | 6% | \$1,443.30 |
| PW NBD AHR H31346 | 95504-H31346 | \$ 1,524.00 | 6% | \$1,443.30 |
| PW NBD AHR H31348 | 95504-H31348 | \$ 118.00 | 6% | \$111.75 |
| PW NBD AHR H31349 | 95504-H31349 | \$ 118.00 | 6% | \$111.75 |
| PW NBD AHR H31350 | 95504-H31350 | \$ 190.00 | 6% | \$179.94 |
| PW NBD AHR H31351 | 95504-H31351 | \$ 71.00 | 6% | \$67.24 |
| PW NBD AHR H31352 | 95504-H31352 | \$ 71.00 | 6% | \$67.24 |
| PW NBD AHR H31353 | 95504-H31353 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H31354 | 95504-H31354 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H31355 | 95504-H31355 | \$ 122.00 | 6% | \$115.54 |
| PW NBD AHR H31356 | 95504-H31356 | \$ 122.00 | 6% | \$115.54 |
| PW NBD AHR H31357 | 95504-H31357 | \$ 122.00 | 6% | \$115.54 |
| PW NBD AHR H31358 | 95504-H31358 | \$ 46.00 | 6% | \$43.56 |
| PW NBD AHR H31359 | 95504-H31359 | \$ 48.00 | 6% | \$45.46 |
| PW NBD AHR H31360 | 95504-H31360 | \$ 43.00 | 6% | \$40.72 |
| PW NBD AHR H31361 | 95504-H31361 | \$ 2,083.00 | 6% | \$1,972.71 |
| PW NBD AHR H31362 | 95504-H31362 | \$ 12,892.00 | 6% | \$12,209.37 |
| PW NBD AHR H31363 | 95504-H31363 | \$ 12,892.00 | 6% | \$12,209.37 |
| PW NBD AHR H31364 | 95504-H31364 | \$ 4,510.00 | 6% | \$4,271.20 |
| PW NBD AHR H31365 | 95504-H31365 | \$ 4,510.00 | 6% | \$4,271.20 |
| PW NBD AHR H31366 | 95504-H31366 | \$ 6,245.00 | 6% | \$5,914.33 |
| PW NBD AHR H31367 | 95504-H31367 | \$ 6,245.00 | 6% | \$5,914.33 |
| PW NBD AHR H31369 | 95504-H31369 | \$ 71.00 | 6% | \$67.24 |
| PW NBD AHR H31370 | 95504-H31370 | \$ 71.00 | 6% | \$67.24 |
| PW NBD AHR H31393 | 95504-H31393 | \$ 43.00 | 6% | \$40.72 |
| PW NBD AHR H32010 | 95504-H32010 | \$ 194.00 | 6% | \$183.73 |
| PW NBD AHR H32011 | 95504-H32011 | \$ 194.00 | 6% | \$183.73 |
| PW NBD AHR H32012 | 95504-H32012 | \$ 1,658.00 | 6% | \$1,570.21 |
| PW NBD AHR H32013 | 95504-H32013 | \$ 1,658.00 | 6% | \$1,570.21 |
| PW NBD AHR H32014 | 95504-H32014 | \$ 1,658.00 | 6% | \$1,570.21 |
| PW NBD AHR H32015 | 95504-H32015 | \$ 1,658.00 | 6% | \$1,570.21 |
| PW NBD AHR H32016 | 95504-H32016 | \$ 1,449.00 | 6% | \$1,372.28 |
| PW NBD AHR H32017 | 95504-H32017 | \$ 1,449.00 | 6% | \$1,372.28 |
| PW NBD AHR H32018 | 95504-H32018 | \$ 1,449.00 | 6% | \$1,372.28 |
| PW NBD AHR H32019 | 95504-H32019 | \$ 1,449.00 | 6% | \$1,372.28 |
| PW NBD AHR H32020 | 95504-H32020 | \$ 14,483.00 | 6% | \$13,716.13 |
| PW NBD AHR H32021 | 95504-H32021 | \$ 14,483.00 | 6% | \$13,716.13 |
| PW NBD AHR H32022 | 95504-H32022 | \$ 14,483.00 | 6% | \$13,716.13 |
| PW NBD AHR H32023 | 95504-H32023 | \$ 14,483.00 | 6% | \$13,716.13 |
| PW NBD AHR H32028 | 95504-H32028 | \$ 27,918.00 | 6% | \$26,439.74 |
| PW NBD AHR H32029 | 95504-H32029 | \$ 27,918.00 | 6% | \$26,439.74 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PW NBD AHR H32030 | 95504-H32030 | \$ 29,279.00 | 6% | \$27,728.68 |
| PW NBD AHR H32031 | 95504-H32031 | \$ 29,279.00 | 6% | \$27,728.68 |
| PW NBD AHR H32032 | 95504-H32032 | \$ 29,279.00 | 6% | \$27,728.68 |
| PW NBD AHR H32033 | 95504-H32033 | \$ 29,279.00 | 6% | \$27,728.68 |
| PW NBD AHR H32038 | 95504-H32038 | \$ 5,063.00 | 6% | \$4,794.91 |
| PW NBD AHR H32039 | 95504-H32039 | \$ 5,063.00 | 6% | \$4,794.91 |
| PW NBD AHR H32040 | 95504-H32040 | \$ 5,063.00 | 6% | \$4,794.91 |
| PW NBD AHR H32041 | 95504-H32041 | \$ 5,063.00 | 6% | \$4,794.91 |
| PW NBD AHR H32046 | 95504-H32046 | \$ 7,016.00 | 6% | \$6,644.50 |
| PW NBD AHR H32047 | 95504-H32047 | \$ 7,016.00 | 6% | \$6,644.50 |
| PW NBD AHR H32048 | 95504-H32048 | \$ 7,016.00 | 6% | \$6,644.50 |
| PW NBD AHR H32049 | 95504-H32049 | \$ 7,016.00 | 6% | \$6,644.50 |
| PW NBD AHR H32054 | 95504-H32054 | \$ 5,063.00 | 6% | \$4,794.91 |
| PW NBD AHR H32055 | 95504-H32055 | \$ 7,016.00 | 6% | \$6,644.50 |
| PW NBD AHR H32056 | 95504-H32056 | \$ 1,573.00 | 6% | \$1,489.71 |
| PW NBD AHR H32057 | 95504-H32057 | \$ 1,573.00 | 6% | \$1,489.71 |
| PW NBD AHR H32058 | 95504-H32058 | \$ 1,573.00 | 6% | \$1,489.71 |
| PW NBD AHR H32059 | 95504-H32059 | \$ 1,573.00 | 6% | \$1,489.71 |
| PW NBD AHR H32060 | 95504-H32060 | \$ 1,961.00 | 6% | \$1,857.17 |
| PW NBD AHR H32061 | 95504-H32061 | \$ 2,059.00 | 6% | \$1,949.98 |
| PW NBD AHR H32062 | 95504-H32062 | \$ 1,980.00 | 6% | \$1,875.16 |
| PW NBD AHR H32063 | 95504-H32063 | \$ 1,964.00 | 6% | \$1,860.01 |
| PW NBD AHR H32064 | 95504-H32064 | \$ 1,980.00 | 6% | \$1,875.16 |
| PW NBD AHR H32065 | 95504-H32065 | \$ 2,239.00 | 6% | \$2,120.44 |
| PW NBD AHR H32066 | 95504-H32066 | \$ 2,239.00 | 6% | \$2,120.44 |
| PW NBD AHR H32067 | 95504-H32067 | \$ 2,239.00 | 6% | \$2,120.44 |
| PW NBD AHR H32068 | 95504-H32068 | \$ 2,239.00 | 6% | \$2,120.44 |
| PW NBD AHR H32069 | 95504-H32069 | \$ 2,784.00 | 6% | \$2,636.59 |
| PW NBD AHR H32070 | 95504-H32070 | \$ 2,784.00 | 6% | \$2,636.59 |
| PW NBD AHR H32071 | 95504-H32071 | \$ 2,784.00 | 6% | \$2,636.59 |
| PW NBD AHR H32072 | 95504-H32072 | \$ 2,784.00 | 6% | \$2,636.59 |
| PW NBD AHR H32073 | 95504-H32073 | \$ 20,567.00 | 6% | \$19,477.98 |
| PW NBD AHR H32074 | 95504-H32074 | \$ 20,567.00 | 6% | \$19,477.98 |
| PW NBD AHR H32075 | 95504-H32075 | \$ 27,956.00 | 6% | \$26,475.73 |
| PW NBD AHR H32076 | 95504-H32076 | \$ 27,956.00 | 6% | \$26,475.73 |
| PW NBD AHR H32101 | 95504-H32101 | \$ 900.00 | 6% | \$852.35 |
| PW NBD AHR H32102 | 95504-H32102 | \$ 908.00 | 6% | \$859.92 |
| PW NBD AHR H32103 | 95504-H32103 | \$ 908.00 | 6% | \$859.92 |
| PW NBD AHR H32104 | 95504-H32104 | \$ 908.00 | 6% | \$859.92 |
| PW NBD AHR H32105 | 95504-H32105 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32106 | 95504-H32106 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32107 | 95504-H32107 | \$ 4,912.00 | 6% | \$4,651.91 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H32108 | 95504-H32108 | \$ 4,912.00 | 6% | \$4,651.91 |
| PW NBD AHR H32109 | 95504-H32109 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32110 | 95504-H32110 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32111 | 95504-H32111 | \$ 908.00 | 6% | \$859.92 |
| PW NBD AHR H32112 | 95504-H32112 | \$ 908.00 | 6% | \$859.92 |
| PW NBD AHR H32113 | 95504-H32113 | \$ 908.00 | 6% | \$859.92 |
| PW NBD AHR H32114 | 95504-H32114 | \$ 908.00 | 6% | \$859.92 |
| PW NBD AHR H32115 | 95504-H32115 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32116 | 95504-H32116 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32117 | 95504-H32117 | \$ 857.00 | 6% | \$811.62 |
| PW NBD AHR H32118 | 95504-H32118 | \$ 857.00 | 6% | \$811.62 |
| PW NBD AHR H32119 | 95504-H32119 | \$ 857.00 | 6% | \$811.62 |
| PW NBD AHR H32120 | 95504-H32120 | \$ 857.00 | 6% | \$811.62 |
| PW NBD AHR H32121 | 95504-H32121 | \$ 4,912.00 | 6% | \$4,651.91 |
| PW NBD AHR H32122 | 95504-H32122 | \$ 4,912.00 | 6% | \$4,651.91 |
| PW NBD AHR H32123 | 95504-H32123 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32124 | 95504-H32124 | \$ 1,813.00 | 6% | \$1,717.00 |
| PW NBD AHR H32125 | 95504-H32125 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32126 | 95504-H32126 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32127 | 95504-H32127 | \$ 2,106.00 | 6% | \$1,994.49 |
| PW NBD AHR H32128 | 95504-H32128 | \$ 2,106.00 | 6% | \$1,994.49 |
| PW NBD AHR H32129 | 95504-H32129 | \$ 2,106.00 | 6% | \$1,994.49 |
| PW NBD AHR H32130 | 95504-H32130 | \$ 2,106.00 | 6% | \$1,994.49 |
| PW NBD AHR H32131 | 95504-H32131 | \$ 2,106.00 | 6% | \$1,994.49 |
| PW NBD AHR H32132 | 95504-H32132 | \$ 2,106.00 | 6% | \$1,994.49 |
| PW NBD AHR H32133 | 95504-H32133 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32134 | 95504-H32134 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32135 | 95504-H32135 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32136 | 95504-H32136 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32137 | 95504-H32137 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32138 | 95504-H32138 | \$ 1,788.00 | 6% | \$1,693.33 |
| PW NBD AHR H32139 | 95504-H32139 | \$ 7,584.00 | 6% | \$7,182.43 |
| PW NBD AHR H32140 | 95504-H32140 | \$ 7,584.00 | 6% | \$7,182.43 |
| PW NBD AHR H32141 | 95504-H32141 | \$ 8,745.00 | 6% | \$8,281.95 |
| PW NBD AHR H32142 | 95504-H32142 | \$ 8,745.00 | 6% | \$8,281.95 |
| PW NBD AHR H32143 | 95504-H32143 | \$ 338.00 | 6% | \$320.10 |
| PW NBD AHR H32144 | 95504-H32144 | \$ 373.00 | 6% | \$353.25 |
| PW NBD AHR H32146 | 95504-H32146 | \$ 773.00 | 6% | \$732.07 |
| PW NBD AHR H32147 | 95504-H32147 | \$ 773.00 | 6% | \$732.07 |
| PW NBD AHR H32148 | 95504-H32148 | \$ 1,594.00 | 6% | \$1,509.60 |
| PW NBD AHR H32149 | 95504-H32149 | \$ 1,594.00 | 6% | \$1,509.60 |
| PW NBD AHR H32150 | 95504-H32150 | \$ 818.00 | 6% | \$774.69 |

| | | | | |
|-------------------|--------------|--------------|----|------------|
| PW NBD AHR H32151 | 95504-H32151 | \$ 361.00 | 6% | \$341.89 |
| PW NBD AHR H32152 | 95504-H32152 | \$ 373.00 | 6% | \$353.25 |
| PW NBD AHR H32169 | 95504-H32169 | \$ 917.00 | 6% | \$868.44 |
| PW NBD AHR H32170 | 95504-H32170 | \$ 917.00 | 6% | \$868.44 |
| PW NBD AHR H32171 | 95504-H32171 | \$ 867.00 | 6% | \$821.09 |
| PW NBD AHR H32172 | 95504-H32172 | \$ 867.00 | 6% | \$821.09 |
| PW NBD AHR H32173 | 95504-H32173 | \$ 2,289.00 | 6% | \$2,167.80 |
| PW NBD AHR H32174 | 95504-H32174 | \$ 2,289.00 | 6% | \$2,167.80 |
| PW NBD AHR H32175 | 95504-H32175 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW NBD AHR H32176 | 95504-H32176 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW NBD AHR H32177 | 95504-H32177 | \$ 8,939.00 | 6% | \$8,465.68 |
| PW NBD AHR H32178 | 95504-H32178 | \$ 10,309.00 | 6% | \$9,763.14 |
| PW NBD AHR H34008 | 95504-H34008 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34009 | 95504-H34009 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34010 | 95504-H34010 | \$ 25.00 | 6% | \$23.68 |
| PW NBD AHR H34011 | 95504-H34011 | \$ 54.00 | 6% | \$51.14 |
| PW NBD AHR H34012 | 95504-H34012 | \$ 98.00 | 6% | \$92.81 |
| PW NBD AHR H34013 | 95504-H34013 | \$ 37.00 | 6% | \$35.04 |
| PW NBD AHR H34014 | 95504-H34014 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34015 | 95504-H34015 | \$ 32.00 | 6% | \$30.31 |
| PW NBD AHR H34016 | 95504-H34016 | \$ 66.00 | 6% | \$62.51 |
| PW NBD AHR H34017 | 95504-H34017 | \$ 114.00 | 6% | \$107.96 |
| PW NBD AHR H34018 | 95504-H34018 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H34019 | 95504-H34019 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H34020 | 95504-H34020 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H34021 | 95504-H34021 | \$ 61.00 | 6% | \$57.77 |
| PW NBD AHR H34048 | 95504-H34048 | \$ 162.00 | 6% | \$153.42 |
| PW NBD AHR H34049 | 95504-H34049 | \$ 162.00 | 6% | \$153.42 |
| PW NBD AHR H34050 | 95504-H34050 | \$ 116.00 | 6% | \$109.86 |
| PW NBD AHR H34051 | 95504-H34051 | \$ 116.00 | 6% | \$109.86 |
| PW NBD AHR H34052 | 95504-H34052 | \$ 183.00 | 6% | \$173.31 |
| PW NBD AHR H34053 | 95504-H34053 | \$ 183.00 | 6% | \$173.31 |
| PW NBD AHR H34054 | 95504-H34054 | \$ 139.00 | 6% | \$131.64 |
| PW NBD AHR H34055 | 95504-H34055 | \$ 139.00 | 6% | \$131.64 |
| PW NBD AHR H34056 | 95504-H34056 | \$ 200.00 | 6% | \$189.41 |
| PW NBD AHR H34057 | 95504-H34057 | \$ 200.00 | 6% | \$189.41 |
| PW NBD AHR H34058 | 95504-H34058 | \$ 176.00 | 6% | \$166.68 |
| PW NBD AHR H34059 | 95504-H34059 | \$ 176.00 | 6% | \$166.68 |
| PW NBD AHR H34062 | 95504-H34062 | \$ 200.00 | 6% | \$189.41 |
| PW NBD AHR H34063 | 95504-H34063 | \$ 200.00 | 6% | \$189.41 |
| PW NBD AHR H34064 | 95504-H34064 | \$ 191.00 | 6% | \$180.89 |
| PW NBD AHR H34065 | 95504-H34065 | \$ 191.00 | 6% | \$180.89 |

| | | | | |
|-------------------|--------------|-------------|----|-------------------|
| PW NBD AHR H34066 | 95504-H34066 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H34067 | 95504-H34067 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H34068 | 95504-H34068 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H34069 | 95504-H34069 | \$ 186.00 | 6% | <i>\$176.15</i> |
| PW NBD AHR H34070 | 95504-H34070 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H34071 | 95504-H34071 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD AHR H34072 | 95504-H34072 | \$ 1,322.00 | 6% | <i>\$1,252.00</i> |
| PW NBD AHR H34073 | 95504-H34073 | \$ 1,427.00 | 6% | <i>\$1,351.44</i> |
| PW NBD AHR H34074 | 95504-H34074 | \$ 1,816.00 | 6% | <i>\$1,719.84</i> |
| PW NBD AHR H34075 | 95504-H34075 | \$ 1,740.00 | 6% | <i>\$1,647.87</i> |
| PW NBD AHR H34076 | 95504-H34076 | \$ 1,322.00 | 6% | <i>\$1,252.00</i> |
| PW NBD AHR H34077 | 95504-H34077 | \$ 1,427.00 | 6% | <i>\$1,351.44</i> |
| PW NBD AHR H34078 | 95504-H34078 | \$ 1,322.00 | 6% | <i>\$1,252.00</i> |
| PW NBD AHR H34079 | 95504-H34079 | \$ 1,427.00 | 6% | <i>\$1,351.44</i> |
| PW NBD AHR H34080 | 95504-H34080 | \$ 1,816.00 | 6% | <i>\$1,719.84</i> |
| PW NBD AHR H34081 | 95504-H34081 | \$ 1,740.00 | 6% | <i>\$1,647.87</i> |
| PW NBD AHR H34082 | 95504-H34082 | \$ 1,742.00 | 6% | <i>\$1,649.76</i> |
| PW NBD AHR H34083 | 95504-H34083 | \$ 1,668.00 | 6% | <i>\$1,579.68</i> |
| PW NBD AHR H34084 | 95504-H34084 | \$ 1,545.00 | 6% | <i>\$1,463.19</i> |
| PW NBD AHR H34085 | 95504-H34085 | \$ 1,545.00 | 6% | <i>\$1,463.19</i> |
| PW NBD AHR H34086 | 95504-H34086 | \$ 1,585.00 | 6% | <i>\$1,501.07</i> |
| PW NBD AHR H34087 | 95504-H34087 | \$ 1,520.00 | 6% | <i>\$1,439.52</i> |
| PW NBD AHR H34088 | 95504-H34088 | \$ 2,838.00 | 6% | <i>\$2,687.73</i> |
| PW NBD AHR H34089 | 95504-H34089 | \$ 2,838.00 | 6% | <i>\$2,687.73</i> |
| PW NBD AHR H34090 | 95504-H34090 | \$ 3,268.00 | 6% | <i>\$3,094.96</i> |
| PW NBD AHR H34091 | 95504-H34091 | \$ 1,847.00 | 6% | <i>\$1,749.20</i> |
| PW NBD AHR H34092 | 95504-H34092 | \$ 1,847.00 | 6% | <i>\$1,749.20</i> |
| PW NBD AHR H34093 | 95504-H34093 | \$ 1,847.00 | 6% | <i>\$1,749.20</i> |
| PW NBD AHR H34094 | 95504-H34094 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34095 | 95504-H34095 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34096 | 95504-H34096 | \$ 246.00 | 6% | <i>\$232.97</i> |
| PW NBD AHR H34097 | 95504-H34097 | \$ 246.00 | 6% | <i>\$232.97</i> |
| PW NBD AHR H34098 | 95504-H34098 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34099 | 95504-H34099 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34100 | 95504-H34100 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34101 | 95504-H34101 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34102 | 95504-H34102 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34103 | 95504-H34103 | \$ 211.00 | 6% | <i>\$199.83</i> |
| PW NBD AHR H34104 | 95504-H34104 | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW NBD AHR H34105 | 95504-H34105 | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW NBD AHR H34106 | 95504-H34106 | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW NBD AHR H34107 | 95504-H34107 | \$ 94.00 | 6% | <i>\$89.02</i> |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H34108 | 95504-H34108 | \$ 94.00 | 6% | \$89.02 |
| PW NBD AHR H34109 | 95504-H34109 | \$ 94.00 | 6% | \$89.02 |
| PW NBD AHR H34110 | 95504-H34110 | \$ 1,779.00 | 6% | \$1,684.80 |
| PW NBD AHR H34111 | 95504-H34111 | \$ 1,779.00 | 6% | \$1,684.80 |
| PW NBD AHR H34112 | 95504-H34112 | \$ 1,779.00 | 6% | \$1,684.80 |
| PW NBD AHR H34114 | 95504-H34114 | \$ 2,335.00 | 6% | \$2,211.36 |
| PW NBD AHR H34115 | 95504-H34115 | \$ 2,335.00 | 6% | \$2,211.36 |
| PW NBD AHR H34116 | 95504-H34116 | \$ 2,335.00 | 6% | \$2,211.36 |
| PW NBD AHR H34117 | 95504-H34117 | \$ 2,335.00 | 6% | \$2,211.36 |
| PW NBD AHR H34118 | 95504-H34118 | \$ 586.00 | 6% | \$554.97 |
| PW NBD AHR H34119 | 95504-H34119 | \$ 586.00 | 6% | \$554.97 |
| PW NBD AHR H34120 | 95504-H34120 | \$ 405.00 | 6% | \$383.56 |
| PW NBD AHR H34121 | 95504-H34121 | \$ 405.00 | 6% | \$383.56 |
| PW NBD AHR H34122 | 95504-H34122 | \$ 431.00 | 6% | \$408.18 |
| PW NBD AHR H34123 | 95504-H34123 | \$ 431.00 | 6% | \$408.18 |
| PW NBD AHR H34124 | 95504-H34124 | \$ 633.00 | 6% | \$599.48 |
| PW NBD AHR H34125 | 95504-H34125 | \$ 633.00 | 6% | \$599.48 |
| PW NBD AHR H34126 | 95504-H34126 | \$ 633.00 | 6% | \$599.48 |
| PW NBD AHR H34127 | 95504-H34127 | \$ 633.00 | 6% | \$599.48 |
| PW NBD AHR H34128 | 95504-H34128 | \$ 91.00 | 6% | \$86.18 |
| PW NBD AHR H34129 | 95504-H34129 | \$ 170.00 | 6% | \$161.00 |
| PW NBD AHR H34130 | 95504-H34130 | \$ 179.00 | 6% | \$169.52 |
| PW NBD AHR H34131 | 95504-H34131 | \$ 177.00 | 6% | \$167.63 |
| PW NBD AHR H34132 | 95504-H34132 | \$ 179.00 | 6% | \$169.52 |
| PW NBD AHR H34151 | 95504-H34151 | \$ 1,118.00 | 6% | \$1,058.80 |
| PW NBD AHR H34172 | 95504-H34172 | \$ 523.00 | 6% | \$495.31 |
| PW NBD AHR H34174 | 95504-H34174 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34175 | 95504-H34175 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34176 | 95504-H34176 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34177 | 95504-H34177 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34178 | 95504-H34178 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34179 | 95504-H34179 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34180 | 95504-H34180 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34181 | 95504-H34181 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34182 | 95504-H34182 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34183 | 95504-H34183 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34184 | 95504-H34184 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34185 | 95504-H34185 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34186 | 95504-H34186 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34187 | 95504-H34187 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34188 | 95504-H34188 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34189 | 95504-H34189 | \$ 35.00 | 6% | \$33.15 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34190 | 95504-H34190 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34191 | 95504-H34191 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34192 | 95504-H34192 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34193 | 95504-H34193 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34194 | 95504-H34194 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34195 | 95504-H34195 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34196 | 95504-H34196 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34197 | 95504-H34197 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34198 | 95504-H34198 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34199 | 95504-H34199 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34200 | 95504-H34200 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34201 | 95504-H34201 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34202 | 95504-H34202 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34203 | 95504-H34203 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34204 | 95504-H34204 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34205 | 95504-H34205 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34206 | 95504-H34206 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34207 | 95504-H34207 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34208 | 95504-H34208 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34209 | 95504-H34209 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34210 | 95504-H34210 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34211 | 95504-H34211 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34212 | 95504-H34212 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34213 | 95504-H34213 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34214 | 95504-H34214 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34215 | 95504-H34215 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34216 | 95504-H34216 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34217 | 95504-H34217 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34218 | 95504-H34218 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34219 | 95504-H34219 | \$ 35.00 | 6% | \$33.15 |
| PW NBD AHR H34220 | 95504-H34220 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34221 | 95504-H34221 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34222 | 95504-H34222 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34223 | 95504-H34223 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34224 | 95504-H34224 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34225 | 95504-H34225 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34226 | 95504-H34226 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34227 | 95504-H34227 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34228 | 95504-H34228 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34229 | 95504-H34229 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34230 | 95504-H34230 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34231 | 95504-H34231 | \$ 52.00 | 6% | \$49.25 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34232 | 95504-H34232 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34233 | 95504-H34233 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34234 | 95504-H34234 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34235 | 95504-H34235 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34236 | 95504-H34236 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34237 | 95504-H34237 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34238 | 95504-H34238 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34239 | 95504-H34239 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34240 | 95504-H34240 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34241 | 95504-H34241 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34242 | 95504-H34242 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34243 | 95504-H34243 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34244 | 95504-H34244 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34245 | 95504-H34245 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34246 | 95504-H34246 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34247 | 95504-H34247 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34248 | 95504-H34248 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34249 | 95504-H34249 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34250 | 95504-H34250 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34251 | 95504-H34251 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34252 | 95504-H34252 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34253 | 95504-H34253 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34254 | 95504-H34254 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34255 | 95504-H34255 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34256 | 95504-H34256 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34257 | 95504-H34257 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34258 | 95504-H34258 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34259 | 95504-H34259 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34260 | 95504-H34260 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34261 | 95504-H34261 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34262 | 95504-H34262 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34263 | 95504-H34263 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34264 | 95504-H34264 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34265 | 95504-H34265 | \$ 52.00 | 6% | \$49.25 |
| PW NBD AHR H34266 | 95504-H34266 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34267 | 95504-H34267 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34268 | 95504-H34268 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34269 | 95504-H34269 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34270 | 95504-H34270 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34271 | 95504-H34271 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34272 | 95504-H34272 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34273 | 95504-H34273 | \$ 39.00 | 6% | \$36.93 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34274 | 95504-H34274 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34275 | 95504-H34275 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34276 | 95504-H34276 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34277 | 95504-H34277 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34278 | 95504-H34278 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34279 | 95504-H34279 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34280 | 95504-H34280 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34281 | 95504-H34281 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34282 | 95504-H34282 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34283 | 95504-H34283 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34284 | 95504-H34284 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34285 | 95504-H34285 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34286 | 95504-H34286 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34287 | 95504-H34287 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34288 | 95504-H34288 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34289 | 95504-H34289 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34290 | 95504-H34290 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34291 | 95504-H34291 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34292 | 95504-H34292 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34293 | 95504-H34293 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34294 | 95504-H34294 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34295 | 95504-H34295 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34296 | 95504-H34296 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34297 | 95504-H34297 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34298 | 95504-H34298 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34299 | 95504-H34299 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34300 | 95504-H34300 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34301 | 95504-H34301 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34302 | 95504-H34302 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34303 | 95504-H34303 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34304 | 95504-H34304 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34305 | 95504-H34305 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H34306 | 95504-H34306 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34307 | 95504-H34307 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34308 | 95504-H34308 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34309 | 95504-H34309 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34310 | 95504-H34310 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34311 | 95504-H34311 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34312 | 95504-H34312 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34313 | 95504-H34313 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34314 | 95504-H34314 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34315 | 95504-H34315 | \$ 62.00 | 6% | \$58.72 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34316 | 95504-H34316 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34317 | 95504-H34317 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34318 | 95504-H34318 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34319 | 95504-H34319 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34320 | 95504-H34320 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34321 | 95504-H34321 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34322 | 95504-H34322 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34323 | 95504-H34323 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34324 | 95504-H34324 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34325 | 95504-H34325 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34326 | 95504-H34326 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34327 | 95504-H34327 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34328 | 95504-H34328 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34329 | 95504-H34329 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34330 | 95504-H34330 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34331 | 95504-H34331 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34332 | 95504-H34332 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34333 | 95504-H34333 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34334 | 95504-H34334 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34335 | 95504-H34335 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34336 | 95504-H34336 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34337 | 95504-H34337 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34338 | 95504-H34338 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34339 | 95504-H34339 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34340 | 95504-H34340 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34341 | 95504-H34341 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34342 | 95504-H34342 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34343 | 95504-H34343 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34344 | 95504-H34344 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34345 | 95504-H34345 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34346 | 95504-H34346 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34347 | 95504-H34347 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34348 | 95504-H34348 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34349 | 95504-H34349 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34350 | 95504-H34350 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34351 | 95504-H34351 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34352 | 95504-H34352 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34353 | 95504-H34353 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34354 | 95504-H34354 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34355 | 95504-H34355 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34356 | 95504-H34356 | \$ 90.00 | 6% | \$85.23 |
| PW NBD AHR H34357 | 95504-H34357 | \$ 90.00 | 6% | \$85.23 |

| | | | | | |
|-------------------|--------------|----|-------|----|---------|
| PW NBD AHR H34358 | 95504-H34358 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34359 | 95504-H34359 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34360 | 95504-H34360 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34361 | 95504-H34361 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34362 | 95504-H34362 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34363 | 95504-H34363 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34364 | 95504-H34364 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34365 | 95504-H34365 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34366 | 95504-H34366 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34367 | 95504-H34367 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34368 | 95504-H34368 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34369 | 95504-H34369 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34370 | 95504-H34370 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34371 | 95504-H34371 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34372 | 95504-H34372 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34373 | 95504-H34373 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34374 | 95504-H34374 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34375 | 95504-H34375 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34376 | 95504-H34376 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34377 | 95504-H34377 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34378 | 95504-H34378 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34379 | 95504-H34379 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34380 | 95504-H34380 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34381 | 95504-H34381 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34382 | 95504-H34382 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34383 | 95504-H34383 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34384 | 95504-H34384 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34385 | 95504-H34385 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34386 | 95504-H34386 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34387 | 95504-H34387 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34388 | 95504-H34388 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34389 | 95504-H34389 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34390 | 95504-H34390 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34391 | 95504-H34391 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34392 | 95504-H34392 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34393 | 95504-H34393 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34394 | 95504-H34394 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34395 | 95504-H34395 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34396 | 95504-H34396 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34397 | 95504-H34397 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34398 | 95504-H34398 | \$ | 90.00 | 6% | \$85.23 |
| PW NBD AHR H34399 | 95504-H34399 | \$ | 90.00 | 6% | \$85.23 |

| | | | | |
|-------------------|--------------|-----------|----|----------|
| PW NBD AHR H34400 | 95504-H34400 | \$ 90.00 | 6% | \$85.23 |
| PW NBD AHR H34401 | 95504-H34401 | \$ 90.00 | 6% | \$85.23 |
| PW NBD AHR H34402 | 95504-H34402 | \$ 90.00 | 6% | \$85.23 |
| PW NBD AHR H34403 | 95504-H34403 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34404 | 95504-H34404 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34405 | 95504-H34405 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34406 | 95504-H34406 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34407 | 95504-H34407 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34408 | 95504-H34408 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34409 | 95504-H34409 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34410 | 95504-H34410 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34411 | 95504-H34411 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34412 | 95504-H34412 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34413 | 95504-H34413 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34414 | 95504-H34414 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34415 | 95504-H34415 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34416 | 95504-H34416 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34417 | 95504-H34417 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34418 | 95504-H34418 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34419 | 95504-H34419 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34420 | 95504-H34420 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34421 | 95504-H34421 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34422 | 95504-H34422 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34423 | 95504-H34423 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34424 | 95504-H34424 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34425 | 95504-H34425 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34426 | 95504-H34426 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34427 | 95504-H34427 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34428 | 95504-H34428 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34429 | 95504-H34429 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34430 | 95504-H34430 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34431 | 95504-H34431 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34432 | 95504-H34432 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34433 | 95504-H34433 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34434 | 95504-H34434 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34435 | 95504-H34435 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34436 | 95504-H34436 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34437 | 95504-H34437 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34438 | 95504-H34438 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34439 | 95504-H34439 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34440 | 95504-H34440 | \$ 144.00 | 6% | \$136.38 |
| PW NBD AHR H34441 | 95504-H34441 | \$ 144.00 | 6% | \$136.38 |

| | | | | |
|-------------------|--------------|-----------|----|-----------------|
| PW NBD AHR H34442 | 95504-H34442 | \$ 144.00 | 6% | <i>\$136.38</i> |
| PW NBD AHR H34443 | 95504-H34443 | \$ 144.00 | 6% | <i>\$136.38</i> |
| PW NBD AHR H34444 | 95504-H34444 | \$ 144.00 | 6% | <i>\$136.38</i> |
| PW NBD AHR H34445 | 95504-H34445 | \$ 144.00 | 6% | <i>\$136.38</i> |
| PW NBD AHR H34446 | 95504-H34446 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34447 | 95504-H34447 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34448 | 95504-H34448 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34449 | 95504-H34449 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34450 | 95504-H34450 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34451 | 95504-H34451 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34452 | 95504-H34452 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34453 | 95504-H34453 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34454 | 95504-H34454 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34455 | 95504-H34455 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34456 | 95504-H34456 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34457 | 95504-H34457 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34458 | 95504-H34458 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34459 | 95504-H34459 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34460 | 95504-H34460 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34461 | 95504-H34461 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34462 | 95504-H34462 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34463 | 95504-H34463 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34464 | 95504-H34464 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34465 | 95504-H34465 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34466 | 95504-H34466 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34467 | 95504-H34467 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34468 | 95504-H34468 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34469 | 95504-H34469 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34470 | 95504-H34470 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34471 | 95504-H34471 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34472 | 95504-H34472 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34473 | 95504-H34473 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34474 | 95504-H34474 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34475 | 95504-H34475 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34476 | 95504-H34476 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34477 | 95504-H34477 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34478 | 95504-H34478 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34479 | 95504-H34479 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34480 | 95504-H34480 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34481 | 95504-H34481 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34482 | 95504-H34482 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD AHR H34483 | 95504-H34483 | \$ 165.00 | 6% | <i>\$156.26</i> |

| | | | | |
|-------------------|--------------|-----------|----|----------|
| PW NBD AHR H34484 | 95504-H34484 | \$ 165.00 | 6% | \$156.26 |
| PW NBD AHR H34485 | 95504-H34485 | \$ 165.00 | 6% | \$156.26 |
| PW NBD AHR H34486 | 95504-H34486 | \$ 165.00 | 6% | \$156.26 |
| PW NBD AHR H34487 | 95504-H34487 | \$ 165.00 | 6% | \$156.26 |
| PW NBD AHR H34488 | 95504-H34488 | \$ 165.00 | 6% | \$156.26 |
| PW NBD AHR H34489 | 95504-H34489 | \$ 165.00 | 6% | \$156.26 |
| PW NBD AHR H34490 | 95504-H34490 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34491 | 95504-H34491 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34492 | 95504-H34492 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34493 | 95504-H34493 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34494 | 95504-H34494 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34495 | 95504-H34495 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34496 | 95504-H34496 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34497 | 95504-H34497 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34498 | 95504-H34498 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34499 | 95504-H34499 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34500 | 95504-H34500 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34501 | 95504-H34501 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34502 | 95504-H34502 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34503 | 95504-H34503 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34504 | 95504-H34504 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34505 | 95504-H34505 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34506 | 95504-H34506 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34507 | 95504-H34507 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34508 | 95504-H34508 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34509 | 95504-H34509 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34510 | 95504-H34510 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34511 | 95504-H34511 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34512 | 95504-H34512 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34513 | 95504-H34513 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34514 | 95504-H34514 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34515 | 95504-H34515 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34516 | 95504-H34516 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34517 | 95504-H34517 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34518 | 95504-H34518 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34519 | 95504-H34519 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34520 | 95504-H34520 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34521 | 95504-H34521 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34522 | 95504-H34522 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34523 | 95504-H34523 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34524 | 95504-H34524 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34525 | 95504-H34525 | \$ 23.00 | 6% | \$21.78 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34526 | 95504-H34526 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34527 | 95504-H34527 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34528 | 95504-H34528 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34529 | 95504-H34529 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34530 | 95504-H34530 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34531 | 95504-H34531 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34532 | 95504-H34532 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34533 | 95504-H34533 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34534 | 95504-H34534 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34535 | 95504-H34535 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34536 | 95504-H34536 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34537 | 95504-H34537 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34538 | 95504-H34538 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34539 | 95504-H34539 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34540 | 95504-H34540 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34541 | 95504-H34541 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34542 | 95504-H34542 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34543 | 95504-H34543 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34544 | 95504-H34544 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34545 | 95504-H34545 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34546 | 95504-H34546 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34547 | 95504-H34547 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34548 | 95504-H34548 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34549 | 95504-H34549 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34550 | 95504-H34550 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34551 | 95504-H34551 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34552 | 95504-H34552 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34553 | 95504-H34553 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34554 | 95504-H34554 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34555 | 95504-H34555 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34556 | 95504-H34556 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34557 | 95504-H34557 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34558 | 95504-H34558 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34559 | 95504-H34559 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34560 | 95504-H34560 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34561 | 95504-H34561 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34562 | 95504-H34562 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34563 | 95504-H34563 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34564 | 95504-H34564 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34565 | 95504-H34565 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34566 | 95504-H34566 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34567 | 95504-H34567 | \$ 23.00 | 6% | \$21.78 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34568 | 95504-H34568 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34569 | 95504-H34569 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34570 | 95504-H34570 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34571 | 95504-H34571 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34572 | 95504-H34572 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34573 | 95504-H34573 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34574 | 95504-H34574 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34575 | 95504-H34575 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34576 | 95504-H34576 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34577 | 95504-H34577 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34578 | 95504-H34578 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34579 | 95504-H34579 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34580 | 95504-H34580 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34581 | 95504-H34581 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34582 | 95504-H34582 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34583 | 95504-H34583 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34584 | 95504-H34584 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34585 | 95504-H34585 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34586 | 95504-H34586 | \$ 23.00 | 6% | \$21.78 |
| PW NBD AHR H34587 | 95504-H34587 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34588 | 95504-H34588 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34589 | 95504-H34589 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34590 | 95504-H34590 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34591 | 95504-H34591 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34592 | 95504-H34592 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34593 | 95504-H34593 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34594 | 95504-H34594 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34595 | 95504-H34595 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34596 | 95504-H34596 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34597 | 95504-H34597 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34598 | 95504-H34598 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34599 | 95504-H34599 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34600 | 95504-H34600 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34601 | 95504-H34601 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34602 | 95504-H34602 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34603 | 95504-H34603 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34604 | 95504-H34604 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34605 | 95504-H34605 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34606 | 95504-H34606 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34607 | 95504-H34607 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34608 | 95504-H34608 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34609 | 95504-H34609 | \$ 58.00 | 6% | \$54.93 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34610 | 95504-H34610 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34611 | 95504-H34611 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34612 | 95504-H34612 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34613 | 95504-H34613 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34614 | 95504-H34614 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34615 | 95504-H34615 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34616 | 95504-H34616 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34617 | 95504-H34617 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34618 | 95504-H34618 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34619 | 95504-H34619 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34620 | 95504-H34620 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34621 | 95504-H34621 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34622 | 95504-H34622 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34623 | 95504-H34623 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34624 | 95504-H34624 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34625 | 95504-H34625 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34626 | 95504-H34626 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34627 | 95504-H34627 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34628 | 95504-H34628 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34629 | 95504-H34629 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34630 | 95504-H34630 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34631 | 95504-H34631 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H34632 | 95504-H34632 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34633 | 95504-H34633 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34634 | 95504-H34634 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34635 | 95504-H34635 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34636 | 95504-H34636 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34637 | 95504-H34637 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34638 | 95504-H34638 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34639 | 95504-H34639 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34640 | 95504-H34640 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34641 | 95504-H34641 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34642 | 95504-H34642 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34643 | 95504-H34643 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34644 | 95504-H34644 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34645 | 95504-H34645 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34646 | 95504-H34646 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34647 | 95504-H34647 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34648 | 95504-H34648 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34649 | 95504-H34649 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34650 | 95504-H34650 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34651 | 95504-H34651 | \$ 62.00 | 6% | \$58.72 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PW NBD AHR H34652 | 95504-H34652 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34653 | 95504-H34653 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34654 | 95504-H34654 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34655 | 95504-H34655 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34656 | 95504-H34656 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34657 | 95504-H34657 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34658 | 95504-H34658 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34659 | 95504-H34659 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34660 | 95504-H34660 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34661 | 95504-H34661 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34662 | 95504-H34662 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34663 | 95504-H34663 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34664 | 95504-H34664 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34665 | 95504-H34665 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34666 | 95504-H34666 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34667 | 95504-H34667 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34668 | 95504-H34668 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34669 | 95504-H34669 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34670 | 95504-H34670 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34671 | 95504-H34671 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34672 | 95504-H34672 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34673 | 95504-H34673 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34674 | 95504-H34674 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34675 | 95504-H34675 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34676 | 95504-H34676 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34677 | 95504-H34677 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34678 | 95504-H34678 | \$ 62.00 | 6% | \$58.72 |
| PW NBD AHR H34679 | 95504-H34679 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34680 | 95504-H34680 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34681 | 95504-H34681 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34682 | 95504-H34682 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34683 | 95504-H34683 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34684 | 95504-H34684 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34685 | 95504-H34685 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34686 | 95504-H34686 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34687 | 95504-H34687 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34688 | 95504-H34688 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34689 | 95504-H34689 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34690 | 95504-H34690 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34691 | 95504-H34691 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34692 | 95504-H34692 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34693 | 95504-H34693 | \$ 70.00 | 6% | \$66.29 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H34694 | 95504-H34694 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34695 | 95504-H34695 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34696 | 95504-H34696 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34697 | 95504-H34697 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34698 | 95504-H34698 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34699 | 95504-H34699 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34700 | 95504-H34700 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34701 | 95504-H34701 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34702 | 95504-H34702 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34703 | 95504-H34703 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34704 | 95504-H34704 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34705 | 95504-H34705 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34706 | 95504-H34706 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34707 | 95504-H34707 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34708 | 95504-H34708 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34709 | 95504-H34709 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34710 | 95504-H34710 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34711 | 95504-H34711 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34712 | 95504-H34712 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34713 | 95504-H34713 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34714 | 95504-H34714 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34715 | 95504-H34715 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34716 | 95504-H34716 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34717 | 95504-H34717 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34718 | 95504-H34718 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34719 | 95504-H34719 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34720 | 95504-H34720 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34721 | 95504-H34721 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34722 | 95504-H34722 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34723 | 95504-H34723 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34724 | 95504-H34724 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34725 | 95504-H34725 | \$ 70.00 | 6% | \$66.29 |
| PW NBD AHR H34726 | 95504-H34726 | \$ 1,373.00 | 6% | \$1,300.30 |
| PW NBD AHR H34727 | 95504-H34727 | \$ 1,373.00 | 6% | \$1,300.30 |
| PW NBD AHR H34728 | 95504-H34728 | \$ 1,373.00 | 6% | \$1,300.30 |
| PW NBD AHR H34729 | 95504-H34729 | \$ 1,373.00 | 6% | \$1,300.30 |
| PW NBD AHR H34730 | 95504-H34730 | \$ 1,469.00 | 6% | \$1,391.22 |
| PW NBD AHR H34731 | 95504-H34731 | \$ 1,469.00 | 6% | \$1,391.22 |
| PW NBD AHR H34732 | 95504-H34732 | \$ 1,469.00 | 6% | \$1,391.22 |
| PW NBD AHR H34733 | 95504-H34733 | \$ 1,469.00 | 6% | \$1,391.22 |
| PW NBD AHR H34734 | 95504-H34734 | \$ 212.00 | 6% | \$200.77 |
| PW NBD AHR H34735 | 95504-H34735 | \$ 212.00 | 6% | \$200.77 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H34736 | 95504-H34736 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H34737 | 95504-H34737 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H34738 | 95504-H34738 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34739 | 95504-H34739 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34740 | 95504-H34740 | \$ 212.00 | 6% | \$200.77 |
| PW NBD AHR H34741 | 95504-H34741 | \$ 212.00 | 6% | \$200.77 |
| PW NBD AHR H34742 | 95504-H34742 | \$ 213.00 | 6% | \$201.72 |
| PW NBD AHR H34743 | 95504-H34743 | \$ 213.00 | 6% | \$201.72 |
| PW NBD AHR H34744 | 95504-H34744 | \$ 270.00 | 6% | \$255.70 |
| PW NBD AHR H34745 | 95504-H34745 | \$ 270.00 | 6% | \$255.70 |
| PW NBD AHR H34746 | 95504-H34746 | \$ 303.00 | 6% | \$286.96 |
| PW NBD AHR H34747 | 95504-H34747 | \$ 303.00 | 6% | \$286.96 |
| PW NBD AHR H34748 | 95504-H34748 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34749 | 95504-H34749 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34750 | 95504-H34750 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34751 | 95504-H34751 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34752 | 95504-H34752 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34753 | 95504-H34753 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34754 | 95504-H34754 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34755 | 95504-H34755 | \$ 512.00 | 6% | \$484.89 |
| PW NBD AHR H34756 | 95504-H34756 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H34757 | 95504-H34757 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H34758 | 95504-H34758 | \$ 270.00 | 6% | \$255.70 |
| PW NBD AHR H34759 | 95504-H34759 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H34760 | 95504-H34760 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H34761 | 95504-H34761 | \$ 270.00 | 6% | \$255.70 |
| PW NBD AHR H34839 | 95504-H34839 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34840 | 95504-H34840 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34841 | 95504-H34841 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34842 | 95504-H34842 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34843 | 95504-H34843 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34844 | 95504-H34844 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34845 | 95504-H34845 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34846 | 95504-H34846 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H34993 | 95504-H34993 | \$ 7,187.00 | 6% | \$6,806.45 |
| PW NBD AHR H34994 | 95504-H34994 | \$ 7,187.00 | 6% | \$6,806.45 |
| PW NBD AHR H34996 | 95504-H34996 | \$ 7,187.00 | 6% | \$6,806.45 |
| PW NBD AHR H34997 | 95504-H34997 | \$ 7,187.00 | 6% | \$6,806.45 |
| PW NBD AHR H35005 | 95504-H35005 | \$ 5,244.00 | 6% | \$4,966.33 |
| PW NBD AHR H35006 | 95504-H35006 | \$ 5,244.00 | 6% | \$4,966.33 |
| PW NBD AHR H35012 | 95504-H35012 | \$ 3,148.00 | 6% | \$2,981.31 |
| PW NBD AHR H35070 | 95504-H35070 | \$ 39.00 | 6% | \$36.93 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H35071 | 95504-H35071 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35072 | 95504-H35072 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35073 | 95504-H35073 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35074 | 95504-H35074 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35075 | 95504-H35075 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35076 | 95504-H35076 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35077 | 95504-H35077 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35078 | 95504-H35078 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35079 | 95504-H35079 | \$ 39.00 | 6% | \$36.93 |
| PW NBD AHR H35080 | 95504-H35080 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H35081 | 95504-H35081 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H35082 | 95504-H35082 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H35083 | 95504-H35083 | \$ 58.00 | 6% | \$54.93 |
| PW NBD AHR H35090 | 95504-H35090 | \$ 451.00 | 6% | \$427.12 |
| PW NBD AHR H35091 | 95504-H35091 | \$ 2,252.00 | 6% | \$2,132.76 |
| PW NBD AHR H35262 | 95504-H35262 | \$ 2,079.00 | 6% | \$1,968.92 |
| PW NBD AHR H35270 | 95504-H35270 | \$ 183.00 | 6% | \$173.31 |
| PW NBD AHR H35271 | 95504-H35271 | \$ 139.00 | 6% | \$131.64 |
| PW NBD AHR H35272 | 95504-H35272 | \$ 180.00 | 6% | \$170.47 |
| PW NBD AHR H35273 | 95504-H35273 | \$ 180.00 | 6% | \$170.47 |
| PW NBD AHR H35274 | 95504-H35274 | \$ 305.00 | 6% | \$288.85 |
| PW NBD AHR H35275 | 95504-H35275 | \$ 200.00 | 6% | \$189.41 |
| PW NBD AHR H35276 | 95504-H35276 | \$ 1,322.00 | 6% | \$1,252.00 |
| PW NBD AHR H35277 | 95504-H35277 | \$ 1,742.00 | 6% | \$1,649.76 |
| PW NBD AHR H35278 | 95504-H35278 | \$ 1,545.00 | 6% | \$1,463.19 |
| PW NBD AHR H35279 | 95504-H35279 | \$ 1,520.00 | 6% | \$1,439.52 |
| PW NBD AHR H35280 | 95504-H35280 | \$ 1,744.00 | 6% | \$1,651.66 |
| PW NBD AHR H35281 | 95504-H35281 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35282 | 95504-H35282 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35283 | 95504-H35283 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35284 | 95504-H35284 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35285 | 95504-H35285 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35286 | 95504-H35286 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35287 | 95504-H35287 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35288 | 95504-H35288 | \$ 1,019.00 | 6% | \$965.04 |
| PW NBD AHR H35289 | 95504-H35289 | \$ 2,543.00 | 6% | \$2,408.35 |
| PW NBD AHR H35291 | 95504-H35291 | \$ 1,924.00 | 6% | \$1,822.12 |
| PW NBD AHR H35292 | 95504-H35292 | \$ 1,545.00 | 6% | \$1,463.19 |
| PW NBD AHR H35293 | 95504-H35293 | \$ 1,520.00 | 6% | \$1,439.52 |
| PW NBD AHR H35295 | 95504-H35295 | \$ 163.00 | 6% | \$154.37 |
| PW NBD AHR H35296 | 95504-H35296 | \$ 5,309.00 | 6% | \$5,027.89 |
| PW NBD AHR H35297 | 95504-H35297 | \$ 5,309.00 | 6% | \$5,027.89 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW NBD AHR H35298 | 95504-H35298 | \$ 8,531.00 | 6% | \$8,079.28 |
| PW NBD AHR H35299 | 95504-H35299 | \$ 8,531.00 | 6% | \$8,079.28 |
| PW NBD AHR H35302 | 95504-H35302 | \$ 2,059.00 | 6% | \$1,949.98 |
| PW NBD AHR H35303 | 95504-H35303 | \$ 2,059.00 | 6% | \$1,949.98 |
| PW NBD AHR H35304 | 95504-H35304 | \$ 1,947.00 | 6% | \$1,843.91 |
| PW NBD AHR H35305 | 95504-H35305 | \$ 2,157.00 | 6% | \$2,042.79 |
| PW NBD AHR H35306 | 95504-H35306 | \$ 2,157.00 | 6% | \$2,042.79 |
| PW NBD AHR H35307 | 95504-H35307 | \$ 2,157.00 | 6% | \$2,042.79 |
| PW NBD AHR H35309 | 95504-H35309 | \$ 2,554.00 | 6% | \$2,418.77 |
| PW NBD AHR H35310 | 95504-H35310 | \$ 2,554.00 | 6% | \$2,418.77 |
| PW NBD AHR H35311 | 95504-H35311 | \$ 2,554.00 | 6% | \$2,418.77 |
| PW NBD AHR H35312 | 95504-H35312 | \$ 2,113.00 | 6% | \$2,001.12 |
| PW NBD AHR H35313 | 95504-H35313 | \$ 2,113.00 | 6% | \$2,001.12 |
| PW NBD AHR H35314 | 95504-H35314 | \$ 2,113.00 | 6% | \$2,001.12 |
| PW NBD AHR H35315 | 95504-H35315 | \$ 915.00 | 6% | \$866.55 |
| PW NBD AHR H35318 | 95504-H35318 | \$ 431.00 | 6% | \$408.18 |
| PW NBD AHR H35319 | 95504-H35319 | \$ 582.00 | 6% | \$551.18 |
| PW NBD AHR H35320 | 95504-H35320 | \$ 604.00 | 6% | \$572.02 |
| PW NBD AHR H35321 | 95504-H35321 | \$ 769.00 | 6% | \$728.28 |
| PW NBD AHR H35322 | 95504-H35322 | \$ 934.00 | 6% | \$884.54 |
| PW NBD AHR H35323 | 95504-H35323 | \$ 915.00 | 6% | \$866.55 |
| PW NBD AHR H35328 | 95504-H35328 | \$ 78.00 | 6% | \$73.87 |
| PW NBD AHR H35330 | 95504-H35330 | \$ 55.00 | 6% | \$52.09 |
| PW NBD AHR H35340 | 95504-H35340 | \$ 2,223.00 | 6% | \$2,105.29 |
| PW NBD AHR H35341 | 95504-H35341 | \$ 2,223.00 | 6% | \$2,105.29 |
| PW NBD AHR H35342 | 95504-H35342 | \$ 1,966.00 | 6% | \$1,861.90 |
| PW NBD AHR H35343 | 95504-H35343 | \$ 2,223.00 | 6% | \$2,105.29 |
| PW NBD AHR H35344 | 95504-H35344 | \$ 2,319.00 | 6% | \$2,196.21 |
| PW NBD AHR H35345 | 95504-H35345 | \$ 2,319.00 | 6% | \$2,196.21 |
| PW NBD AHR H35346 | 95504-H35346 | \$ 2,038.00 | 6% | \$1,930.09 |
| PW NBD AHR H35347 | 95504-H35347 | \$ 2,319.00 | 6% | \$2,196.21 |
| PW NBD AHR H35349 | 95504-H35349 | \$ 2,562.00 | 6% | \$2,426.34 |
| PW NBD AHR H35350 | 95504-H35350 | \$ 2,562.00 | 6% | \$2,426.34 |
| PW NBD AHR H35351 | 95504-H35351 | \$ 2,231.00 | 6% | \$2,112.87 |
| PW NBD AHR H35352 | 95504-H35352 | \$ 2,562.00 | 6% | \$2,426.34 |
| PW NBD AHR H35359 | 95504-H35359 | \$ 769.00 | 6% | \$728.28 |
| PW NBD AHR H35360 | 95504-H35360 | \$ 934.00 | 6% | \$884.54 |
| PW NBD AHR H35361 | 95504-H35361 | \$ 915.00 | 6% | \$866.55 |
| PW NBD AHR H35362 | 95504-H35362 | \$ 431.00 | 6% | \$408.18 |
| PW NBD AHR H35366 | 95504-H35366 | \$ 1,118.00 | 6% | \$1,058.80 |
| PW NBD AHR H35367 | 95504-H35367 | \$ 1,304.00 | 6% | \$1,234.95 |
| PW NBD AHR H35368 | 95504-H35368 | \$ 1,988.00 | 6% | \$1,882.74 |

| | | | | |
|-------------------|--------------|-----------|----|----------|
| PW NBD AHR H35369 | 95504-H35369 | \$ 649.00 | 6% | \$614.64 |
| PW NBD AHR H35370 | 95504-H35370 | \$ 910.00 | 6% | \$861.82 |
| PW NBD AHR H35375 | 95504-H35375 | \$ 547.00 | 6% | \$518.04 |
| PW NBD AHR H35376 | 95504-H35376 | \$ 820.00 | 6% | \$776.58 |
| PW NBD AHR H35377 | 95504-H35377 | \$ 344.00 | 6% | \$325.79 |
| PW NBD AHR H35378 | 95504-H35378 | \$ 547.00 | 6% | \$518.04 |
| PW NBD AHR H35379 | 95504-H35379 | \$ 344.00 | 6% | \$325.79 |
| PW NBD AHR H35380 | 95504-H35380 | \$ 616.00 | 6% | \$583.38 |
| PW NBD AHR H35381 | 95504-H35381 | \$ 751.00 | 6% | \$711.23 |
| PW NBD AHR H35384 | 95504-H35384 | \$ 249.00 | 6% | \$235.82 |
| PW NBD AHR H35385 | 95504-H35385 | \$ 331.00 | 6% | \$313.47 |
| PW NBD AHR H35386 | 95504-H35386 | \$ 547.00 | 6% | \$518.04 |
| PW NBD AHR H35387 | 95504-H35387 | \$ 511.00 | 6% | \$483.94 |
| PW NBD AHR H35388 | 95504-H35388 | \$ 375.00 | 6% | \$355.14 |
| PW NBD AHR H35389 | 95504-H35389 | \$ 214.00 | 6% | \$202.67 |
| PW NBD AHR H35390 | 95504-H35390 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H35391 | 95504-H35391 | \$ 404.00 | 6% | \$382.61 |
| PW NBD AHR H35392 | 95504-H35392 | \$ 616.00 | 6% | \$583.38 |
| PW NBD AHR H35393 | 95504-H35393 | \$ 820.00 | 6% | \$776.58 |
| PW NBD AHR H35394 | 95504-H35394 | \$ 147.00 | 6% | \$139.22 |
| PW NBD AHR H35395 | 95504-H35395 | \$ 128.00 | 6% | \$121.22 |
| PW NBD AHR H35396 | 95504-H35396 | \$ 147.00 | 6% | \$139.22 |
| PW NBD AHR H35397 | 95504-H35397 | \$ 128.00 | 6% | \$121.22 |
| PW NBD AHR H35398 | 95504-H35398 | \$ 382.00 | 6% | \$361.77 |
| PW NBD AHR H35399 | 95504-H35399 | \$ 464.00 | 6% | \$439.43 |
| PW NBD AHR H35400 | 95504-H35400 | \$ 515.00 | 6% | \$487.73 |
| PW NBD AHR H35401 | 95504-H35401 | \$ 274.00 | 6% | \$259.49 |
| PW NBD AHR H35415 | 95504-H35415 | \$ 186.00 | 6% | \$176.15 |
| PW NBD AHR H35416 | 95504-H35416 | \$ 186.00 | 6% | \$176.15 |
| PW NBD AHR H35426 | 95504-H35426 | \$ 214.00 | 6% | \$202.67 |
| PW NBD AHR H35427 | 95504-H35427 | \$ 511.00 | 6% | \$483.94 |
| PW NBD AHR H35428 | 95504-H35428 | \$ 185.00 | 6% | \$175.20 |
| PW NBD AHR H35429 | 95504-H35429 | \$ 404.00 | 6% | \$382.61 |
| PW NBD AHR H35430 | 95504-H35430 | \$ 206.00 | 6% | \$195.09 |
| PW NBD AHR H35431 | 95504-H35431 | \$ 206.00 | 6% | \$195.09 |
| PW NBD AHR H35432 | 95504-H35432 | \$ 213.00 | 6% | \$201.72 |
| PW NBD AHR H35433 | 95504-H35433 | \$ 264.00 | 6% | \$250.02 |
| PW NBD AHR H35434 | 95504-H35434 | \$ 296.00 | 6% | \$280.33 |
| PW NBD AHR H35435 | 95504-H35435 | \$ 296.00 | 6% | \$280.33 |
| PW NBD AHR H35436 | 95504-H35436 | \$ 498.00 | 6% | \$471.63 |
| PW NBD AHR H35437 | 95504-H35437 | \$ 498.00 | 6% | \$471.63 |
| PW NBD AHR H35438 | 95504-H35438 | \$ 498.00 | 6% | \$471.63 |

| | | | | |
|------------------------------|-------------------------|-------------|----|------------|
| PW NBD AHR H35439 | 95504-H35439 | \$ 498.00 | 6% | \$471.63 |
| PW NBD AHR H35440 | 95504-H35440 | \$ 264.00 | 6% | \$250.02 |
| PW NBD AHR H35441 | 95504-H35441 | \$ 264.00 | 6% | \$250.02 |
| PW NBD AHR H35442 | 95504-H35442 | \$ 264.00 | 6% | \$250.02 |
| PW NBD AHR H35443 | 95504-H35443 | \$ 1,373.00 | 6% | \$1,300.30 |
| PW NBD AHR H35444 | 95504-H35444 | \$ 1,469.00 | 6% | \$1,391.22 |
| PW NBD AHR H35445 | 95504-H35445 | \$ 1,322.00 | 6% | \$1,252.00 |
| PW NBD AHR H35446 | 95504-H35446 | \$ 1,427.00 | 6% | \$1,351.44 |
| PW NBD AHR H35447 | 95504-H35447 | \$ 1,651.00 | 6% | \$1,563.58 |
| PW NBD AHR H35448 | 95504-H35448 | \$ 1,582.00 | 6% | \$1,498.23 |
| PW NBD AHR H35449 | 95504-H35449 | \$ 1,545.00 | 6% | \$1,463.19 |
| PW NBD AHR H35450 | 95504-H35450 | \$ 1,441.00 | 6% | \$1,364.70 |
| PW NBD AHR H35451 | 95504-H35451 | \$ 1,847.00 | 6% | \$1,749.20 |
| PW NBD AHR H35452 | 95504-H35452 | \$ 1,847.00 | 6% | \$1,749.20 |
| PW NBD AHR H35453 | 95504-H35453 | \$ 1,469.00 | 6% | \$1,391.22 |
| PW NBD AHR H35454 | 95504-H35454 | \$ 1,373.00 | 6% | \$1,300.30 |
| PW NBD AHR H35455 | 95504-H35455 | \$ 604.00 | 6% | \$572.02 |
| PW NBD AHR H35456 | 95504-H35456 | \$ 758.00 | 6% | \$717.86 |
| PW NBD AHR H35457 | 95504-H35457 | \$ 680.00 | 6% | \$643.99 |
| PW NBD AHR H35458 | 95504-H35458 | \$ 744.00 | 6% | \$704.61 |
| PW NBD AHR H35471 | 95504-H35471 | \$ 604.00 | 6% | \$572.02 |
| PW NBD AHR H35600 | 95504-H35600 | \$ 180.00 | 6% | \$170.47 |
| PW NBD AHR H35601 | 95504-H35601 | \$ 180.00 | 6% | \$170.47 |
| PW NBD AHR H35602 | 95504-H35602 | \$ 212.00 | 6% | \$200.77 |
| PW NBD AHR H35603 | 95504-H35603 | \$ 212.00 | 6% | \$200.77 |
| PW NBD AHR H35604 | 95504-H35604 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H35605 | 95504-H35605 | \$ 272.00 | 6% | \$257.60 |
| PW NBD AHR H35606 | 95504-H35606 | \$ 305.00 | 6% | \$288.85 |
| PW NBD AHR H35607 | 95504-H35607 | \$ 303.00 | 6% | \$286.96 |
| PW NBD AHR ISW-24W-4X | 95504-ISW-24W-4X | \$ 636.00 | 6% | \$602.32 |
| PW NBD AHR ISW-4W-4WS-4X | 95504-ISW-4W-4WS-4X | \$ 403.00 | 6% | \$381.66 |
| PW NBD AHR BD MSM128 | 95504-MSM128 | \$ 2,378.00 | 6% | \$2,252.08 |
| PW NBD AHR BD MSM48C | 95504-MSM48C | \$ 1,444.00 | 6% | \$1,367.54 |
| PW NBD AHR | 95504-R100-8T | \$ 60.00 | 6% | \$56.82 |
| PW NBD AHR SLX9150-48XT-DC-F | 95504-SLX9150-48XT-DC-F | \$ 2,023.00 | 6% | \$1,915.88 |

| | | | | |
|------------------------------|-------------------------|--------------|----|--------------------|
| PW NBD AHR SLX9150-48XT-DC-R | 95504-SLX9150-48XT-DC-R | \$ 2,209.00 | 6% | <i>\$2,092.03</i> |
| PW NBD AHR SLX9150-48Y-DC-F | 95504-SLX9150-48Y-DC-F | \$ 1,938.00 | 6% | <i>\$1,835.38</i> |
| PW NBD AHR SLX9150-48Y-DC-R | 95504-SLX9150-48Y-DC-R | \$ 2,117.00 | 6% | <i>\$2,004.90</i> |
| PW NBD AHR SLX9740-40C | 95504-SLX9740-40C | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PW NBD AHR SLX9740-40C-AC-F | 95504-SLX9740-40C-AC-F | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PW NBD AHR SLX9740-40C-AC-R | 95504-SLX9740-40C-AC-R | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PW NBD AHR SLX9740-40C-DC-F | 95504-SLX9740-40C-DC-F | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PW NBD AHR SLX9740-80C | 95504-SLX9740-80C | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PW NBD AHR SLX9740-80C-AC-F | 95504-SLX9740-80C-AC-F | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PW NBD AHR SLX9740-80C-AC-R | 95504-SLX9740-80C-AC-R | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PW NBD AHR SLX9740-80C-DC-F | 95504-SLX9740-80C-DC-F | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PW NBD AHR V300-8P-2X | 95504-V300-8P-2X | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW NBD AHR V300-8T-2X | 95504-V300-8T-2X | \$ 70.00 | 6% | <i>\$66.29</i> |
| PW NBD AHR V300HT-8P-2X | 95504-V300HT-8P-2X | \$ 231.00 | 6% | <i>\$218.77</i> |
| PW NBD AHR V300HT-8T-2X | 95504-V300HT-8T-2X | \$ 137.00 | 6% | <i>\$129.75</i> |
| PW NBD AHR Summit VIM-SS | 95504-VIM-SS | \$ 121.00 | 6% | <i>\$114.59</i> |

| | | | | |
|----------------------------------|-----------------------------|-----------|----|-----------------|
| PW NBD AHR Summit VIM-SSV80 | 95504-VIM-SSV80 | \$ 227.00 | 6% | <i>\$214.98</i> |
| PW NBD AHR Summit VIM2-SS | 95504-VIM2-SS | \$ 142.00 | 6% | <i>\$134.48</i> |
| PW NBD AHR Summit VIM2-SS128 | 95504-VIM2-SS128 | \$ 489.00 | 6% | <i>\$463.11</i> |
| PW NBD AHR Summit VIM2-V80 | 95504-VIM2-V80 | \$ 523.00 | 6% | <i>\$495.31</i> |
| PW NBD AHR Summit VIM210G4X | 95504-VIM210G4X | \$ 907.00 | 6% | <i>\$858.97</i> |
| PW NBD AHR VIM5-2Q | 95504-VIM5-2Q | \$ 145.00 | 6% | <i>\$137.32</i> |
| PW NBD AHR VIM5-2Y | 95504-VIM5-2Y | \$ 171.00 | 6% | <i>\$161.95</i> |
| PW NBD AHR VIM5-4X | 95504-VIM5-4X | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD AHR VIM5-4XE | 95504-VIM5-4XE | \$ 140.00 | 6% | <i>\$132.59</i> |
| PW NBD AHR VIM5-4Y | 95504-VIM5-4Y | \$ 218.00 | 6% | <i>\$206.46</i> |
| PW NBD AHR VIM5-4YE | 95504-VIM5-4YE | \$ 282.00 | 6% | <i>\$267.07</i> |
| PW NBD AHR VSP4900-12MXU-12XE | 95504-VSP4900-12MXU-12XE | \$ 807.00 | 6% | <i>\$764.27</i> |
| PW NBD AHR VSP4900-12MXU-12XE-B1 | 95504-VSP4900-12MXU-12XE-B1 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PW NBD AHR VSP4900-24S | 95504-VSP4900-24S | \$ 431.00 | 6% | <i>\$408.18</i> |
| PW NBD AHR VSP4900-24S-B3 | 95504-VSP4900-24S-B3 | \$ 431.00 | 6% | <i>\$408.18</i> |
| PW NBD AHR VSP4900-24XE | 95504-VSP4900-24XE | \$ 807.00 | 6% | <i>\$764.27</i> |
| PW NBD AHR VSP4900-24XE-B3 | 95504-VSP4900-24XE-B3 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PW NBD AHR X435-24P-4S | 95504-X435-24P-4S | \$ 173.00 | 6% | <i>\$163.84</i> |

| | | | | |
|------------------------------|--------------------|-------------|----|-------------------|
| PW NBD AHR X435-24T-4S | 95504-X435-24T-4S | \$ 99.00 | 6% | <i>\$93.76</i> |
| PW NBD AHR X435-8P-2T-W | 95504-X435-8P-2T-W | \$ 99.00 | 6% | <i>\$93.76</i> |
| PW NBD AHR X435-8P-4S | 95504-X435-8P-4S | \$ 90.00 | 6% | <i>\$85.23</i> |
| PW NBD AHR X435-8T-4S | 95504-X435-8T-4S | \$ 72.00 | 6% | <i>\$68.19</i> |
| PW NBD AHR Summit X460-24P | 95504-X460-24P | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW NBD AHR Summit X460-24T | 95504-X460-24T | \$ 595.00 | 6% | <i>\$563.49</i> |
| PW NBD AHR Summit X460-24TDC | 95504-X460-24TDC | \$ 875.00 | 6% | <i>\$828.67</i> |
| PW NBD AHR Summit X460-24X | 95504-X460-24X | \$ 1,102.00 | 6% | <i>\$1,043.65</i> |
| PW NBD AHR Summit X460-24XDC | 95504-X460-24XDC | \$ 1,234.00 | 6% | <i>\$1,168.66</i> |
| PW NBD AHR Summit X460-48P | 95504-X460-48P | \$ 1,102.00 | 6% | <i>\$1,043.65</i> |
| PW NBD AHR Summit X460-48T | 95504-X460-48T | \$ 946.00 | 6% | <i>\$895.91</i> |
| PW NBD AHR Summit X460-48TDC | 95504-X460-48TDC | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| PW NBD AHR Summit X460-48X | 95504-X460-48X | \$ 1,467.00 | 6% | <i>\$1,389.32</i> |
| PW NBD AHR Summit X460-48XDC | 95504-X460-48XDC | \$ 1,432.00 | 6% | <i>\$1,356.18</i> |
| PW NBD AHR X465-24MU | 95504-X465-24MU | \$ 934.00 | 6% | <i>\$884.54</i> |
| PW NBD AHR X465-24S | 95504-X465-24S | \$ 431.00 | 6% | <i>\$408.18</i> |
| PW NBD AHR X465-24S-B3 | 95504-X465-24S-B3 | \$ 431.00 | 6% | <i>\$408.18</i> |
| PW NBD AHR X465-24W | 95504-X465-24W | \$ 431.00 | 6% | <i>\$408.18</i> |
| PW NBD AHR X465-24XE | 95504-X465-24XE | \$ 807.00 | 6% | <i>\$764.27</i> |
| PW NBD AHR X465-24XE-B3 | 95504-X465-24XE-B3 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PW NBD AHR X465-48P | 95504-X465-48P | \$ 604.00 | 6% | <i>\$572.02</i> |

| | | | | |
|----------------------------|-----------------------|-------------|----|-------------------|
| PW NBD AHR X465-48T | 95504-X465-48T | \$ 582.00 | 6% | <i>\$551.18</i> |
| PW NBD AHR X465-48W | 95504-X465-48W | \$ 769.00 | 6% | <i>\$728.28</i> |
| PW NBD AHR X465i-48W | 95504-X465i-48W | \$ 915.00 | 6% | <i>\$866.55</i> |
| PW NBD AHR X465i-48W-B1-S1 | 95504-X465i-48W-B1-S1 | \$ 915.00 | 6% | <i>\$866.55</i> |
| PW NBD AHR X465i-48W-B2-S1 | 95504-X465i-48W-B2-S1 | \$ 915.00 | 6% | <i>\$866.55</i> |
| PW NBD AHR Summit X480-24X | 95504-X480-24X | \$ 1,359.00 | 6% | <i>\$1,287.04</i> |
| PW NBD AHR Summit X480-48T | 95504-X480-48T | \$ 1,359.00 | 6% | <i>\$1,287.04</i> |
| PW NBD AHR Summit X480-48X | 95504-X480-48X | \$ 1,808.00 | 6% | <i>\$1,712.27</i> |
| PW NBD AHR X695-48Y-8C | 95504-X695-48Y-8C | \$ 2,112.00 | 6% | <i>\$2,000.17</i> |
| PW NBD AHR XA1440 | 95504-XA1440 | \$ 220.00 | 6% | <i>\$208.35</i> |
| PW NBD AHR XA1480 | 95504-XA1480 | \$ 295.00 | 6% | <i>\$279.38</i> |
| PW NBD AHR Summit XGM3-2SF | 95504-XGM3-2SF | \$ 227.00 | 6% | <i>\$214.98</i> |
| PW NBD AHR XR600 | 95504-XR600 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW NBD AHR -ZR-XFP | 95504-ZR-XFP | \$ 1,371.00 | 6% | <i>\$1,298.41</i> |
| PW 4HR AHR Optics 10200 | 95507-10200 | \$ 2,519.00 | 6% | <i>\$2,385.62</i> |
| PW 4HR AHR Optics 10320 | 95507-10320 | \$ 2,772.00 | 6% | <i>\$2,625.22</i> |
| PW 4HR AHR 10330 | 95507-10330 | \$ 6,790.00 | 6% | <i>\$6,430.47</i> |
| PW 4HR AHR 10331 | 95507-10331 | \$ 3,137.00 | 6% | <i>\$2,970.90</i> |
| PW 4HR AHR 10335 | 95507-10335 | \$ 4,783.00 | 6% | <i>\$4,529.74</i> |
| PW 4HR AHR 10403 | 95507-10403 | \$ 5,938.00 | 6% | <i>\$5,623.58</i> |
| PW 4HR AHR 10404 | 95507-10404 | \$ 2,916.00 | 6% | <i>\$2,761.60</i> |
| PW 4HR AHR 10441 | 95507-10441 | \$ 1,957.00 | 6% | <i>\$1,853.38</i> |
| PW 4HR AHR 10442 | 95507-10442 | \$ 2,083.00 | 6% | <i>\$1,972.71</i> |
| PW 4HR AHR 1130C | 95507-1130C | \$ 1,200.00 | 6% | <i>\$1,136.46</i> |
| PW 4HR AHR E4G 16119 | 95507-16119 | \$ 361.00 | 6% | <i>\$341.89</i> |
| PW 4HR AHR E4G 16120 | 95507-16120 | \$ 446.00 | 6% | <i>\$422.38</i> |
| PW 4HR AHR E4G 16126 | 95507-16126 | \$ 361.00 | 6% | <i>\$341.89</i> |
| PW 4HR AHR E4G 16127 | 95507-16127 | \$ 378.00 | 6% | <i>\$357.98</i> |
| PW 4HR AHR 16172 | 95507-16172 | \$ 362.00 | 6% | <i>\$342.83</i> |

| | | | | |
|-------------------------|--------------|-------------|----|------------|
| PW 4HR AHR -16172T | 95507-16172T | \$ 444.00 | 6% | \$420.49 |
| PW 4HR AHR 16173 | 95507-16173 | \$ 386.00 | 6% | \$365.56 |
| PW 4HR AHR -16173T | 95507-16173T | \$ 465.00 | 6% | \$440.38 |
| PW 4HR AHR 16174 | 95507-16174 | \$ 585.00 | 6% | \$554.02 |
| PW 4HR AHR 16175 | 95507-16175 | \$ 628.00 | 6% | \$594.75 |
| PW 4HR AHR 16176 | 95507-16176 | \$ 547.00 | 6% | \$518.04 |
| PW 4HR AHR 16177 | 95507-16177 | \$ 539.00 | 6% | \$510.46 |
| PW 4HR AHR -16177T | 95507-16177T | \$ 688.00 | 6% | \$651.57 |
| PW 4HR AHR 16178 | 95507-16178 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR 16179 | 95507-16179 | \$ 814.00 | 6% | \$770.90 |
| PW 4HR AHR -16179T | 95507-16179T | \$ 975.00 | 6% | \$923.37 |
| PW 4HR AHR 16301T | 95507-16301T | \$ 2,126.00 | 6% | \$2,013.43 |
| PW 4HR AHR 16303T | 95507-16303T | \$ 2,126.00 | 6% | \$2,013.43 |
| PW 4HR AHR 16304T | 95507-16304T | \$ 2,840.00 | 6% | \$2,689.62 |
| PW 4HR AHR 16401T | 95507-16401T | \$ 999.00 | 6% | \$946.10 |
| PW 4HR AHR 16402T | 95507-16402T | \$ 1,527.00 | 6% | \$1,446.15 |
| PW 4HR AHR 16403T | 95507-16403T | \$ 1,335.00 | 6% | \$1,264.31 |
| PW 4HR AHR 16404T | 95507-16404T | \$ 1,335.00 | 6% | \$1,264.31 |
| PW 4HR AHR 16405T | 95507-16405T | \$ 1,778.00 | 6% | \$1,683.85 |
| PW 4HR AHR 16406T | 95507-16406T | \$ 2,364.00 | 6% | \$2,238.83 |
| PW 4HR AHR E4G 16431 | 95507-16431 | \$ 1,491.00 | 6% | \$1,412.05 |
| PW 4HR AHR E4G 16432 | 95507-16432 | \$ 1,621.00 | 6% | \$1,535.17 |
| PW 4HR AHR E4G 16440 | 95507-16440 | \$ 935.00 | 6% | \$885.49 |
| PW 4HR AHR E4G 16441 | 95507-16441 | \$ 846.00 | 6% | \$801.20 |
| PW 4HR AHR E4G 16442 | 95507-16442 | \$ 378.00 | 6% | \$357.98 |
| PW 4HR AHR E4G 16444 | 95507-16444 | \$ 187.00 | 6% | \$177.10 |
| PW 4HR AHR Summit 16501 | 95507-16501 | \$ 200.00 | 6% | \$189.41 |
| PW 4HR AHR 16501T | 95507-16501T | \$ 265.00 | 6% | \$250.97 |
| PW 4HR AHR Summit 16502 | 95507-16502 | \$ 301.00 | 6% | \$285.06 |
| PW 4HR AHR 16502T | 95507-16502T | \$ 360.00 | 6% | \$340.94 |
| PW 4HR AHR Summit 16503 | 95507-16503 | \$ 251.00 | 6% | \$237.71 |
| PW 4HR AHR 16503T | 95507-16503T | \$ 317.00 | 6% | \$300.21 |
| PW 4HR AHR Summit 16504 | 95507-16504 | \$ 404.00 | 6% | \$382.61 |
| PW 4HR AHR 16504T | 95507-16504T | \$ 479.00 | 6% | \$453.64 |
| PW 4HR AHR Summit 16505 | 95507-16505 | \$ 447.00 | 6% | \$423.33 |
| PW 4HR AHR 16505T | 95507-16505T | \$ 536.00 | 6% | \$507.62 |
| PW 4HR AHR Summit 16506 | 95507-16506 | \$ 684.00 | 6% | \$647.78 |
| PW 4HR AHR 16506T | 95507-16506T | \$ 536.00 | 6% | \$507.62 |
| PW 4HR AHR Summit 16507 | 95507-16507 | \$ 617.00 | 6% | \$584.33 |
| PW 4HR AHR 16507T | 95507-16507T | \$ 749.00 | 6% | \$709.34 |
| PW 4HR AHR Summit 16508 | 95507-16508 | \$ 779.00 | 6% | \$737.75 |
| PW 4HR AHR 16508T | 95507-16508T | \$ 941.00 | 6% | \$891.17 |

| | | | | |
|-------------------------|--------------|-------------|----|------------|
| PW 4HR AHR Summit 16509 | 95507-16509 | \$ 779.00 | 6% | \$737.75 |
| PW 4HR AHR 16509T | 95507-16509T | \$ 941.00 | 6% | \$891.17 |
| PW 4HR AHR Summit 16510 | 95507-16510 | \$ 941.00 | 6% | \$891.17 |
| PW 4HR AHR 16510T | 95507-16510T | \$ 1,123.00 | 6% | \$1,063.54 |
| PW 4hr AHR-16513 | 95507-16513 | \$ 558.00 | 6% | \$528.45 |
| PW 4hr AHR-16514 | 95507-16514 | \$ 921.00 | 6% | \$872.23 |
| PW 4HR AHR 16515 | 95507-16515 | \$ 160.00 | 6% | \$151.53 |
| PW 4hr AHR-16516 | 95507-16516 | \$ 173.00 | 6% | \$163.84 |
| PW 4HR AHR 16517 | 95507-16517 | \$ 331.00 | 6% | \$313.47 |
| PW 4hr AHR-16518 | 95507-16518 | \$ 303.00 | 6% | \$286.96 |
| PW-4HR AHR 16519 | 95507-16519 | \$ 317.00 | 6% | \$300.21 |
| PW-4HR AHR 16520 | 95507-16520 | \$ 499.00 | 6% | \$472.58 |
| PW 4HR AHR 16530 | 95507-16530 | \$ 183.00 | 6% | \$173.31 |
| PW 4HR AHR 16531 | 95507-16531 | \$ 260.00 | 6% | \$246.23 |
| PW 4HR AHR 16531T | 95507-16531T | \$ 283.00 | 6% | \$268.02 |
| PW 4HR AHR 16532 | 95507-16532 | \$ 260.00 | 6% | \$246.23 |
| PW 4HR AHR 16532T | 95507-16532T | \$ 283.00 | 6% | \$268.02 |
| PW 4HR AHR 16533 | 95507-16533 | \$ 351.00 | 6% | \$332.41 |
| PW 4HR AHR 16533T | 95507-16533T | \$ 397.00 | 6% | \$375.98 |
| PW 4HR AHR 16534 | 95507-16534 | \$ 372.00 | 6% | \$352.30 |
| PW 4HR AHR 16535 | 95507-16535 | \$ 563.00 | 6% | \$533.19 |
| PW 4HR AHR 16535A | 95507-16535A | \$ 563.00 | 6% | \$533.19 |
| PW 4HR AHR 16535T | 95507-16535T | \$ 631.00 | 6% | \$597.59 |
| PW 4HR AHR 16536 | 95507-16536 | \$ 263.00 | 6% | \$249.07 |
| PW 4HR AHR 16537 | 95507-16537 | \$ 361.00 | 6% | \$341.89 |
| PW 4HR AHR 16538 | 95507-16538 | \$ 428.00 | 6% | \$405.34 |
| PW 4HR AHR 16538T | 95507-16538T | \$ 516.00 | 6% | \$488.68 |
| PW 4HR AHR 16539 | 95507-16539 | \$ 553.00 | 6% | \$523.72 |
| PW 4HR AHR 16540 | 95507-16540 | \$ 400.00 | 6% | \$378.82 |
| PW 4HR AHR 16541 | 95507-16541 | \$ 153.00 | 6% | \$144.90 |
| PW 4HR AHR 16560 | 95507-16560 | \$ 90.00 | 6% | \$85.23 |
| PW 4HR AHR 16561 | 95507-16561 | \$ 123.00 | 6% | \$116.49 |
| PW 4HR AHR 16562 | 95507-16562 | \$ 151.00 | 6% | \$143.00 |
| PW 4HR AHR 16563 | 95507-16563 | \$ 197.00 | 6% | \$186.57 |
| PW 4HR AHR 16564 | 95507-16564 | \$ 246.00 | 6% | \$232.97 |
| PW 4HR AHR 16565 | 95507-16565 | \$ 374.00 | 6% | \$354.20 |
| PW 4HR AHR 16566 | 95507-16566 | \$ 55.00 | 6% | \$52.09 |
| PW 4HR AHR 16567 | 95507-16567 | \$ 103.00 | 6% | \$97.55 |
| PW 4HR AHR 16568 | 95507-16568 | \$ 90.00 | 6% | \$85.23 |
| PW 4HR AHR 16569 | 95507-16569 | \$ 136.00 | 6% | \$128.80 |
| PW 4HR AHR 16570 | 95507-16570 | \$ 151.00 | 6% | \$143.00 |
| PW 4HR AHR 16571 | 95507-16571 | \$ 246.00 | 6% | \$232.97 |

| | | | | |
|-------------------------|--------------|-------------|----|------------|
| PW 4HR AHR 16701 | 95507-16701 | \$ 546.00 | 6% | \$517.09 |
| PW 4HR AHR 16702 | 95507-16702 | \$ 801.00 | 6% | \$758.59 |
| PW 4HR AHR 16703 | 95507-16703 | \$ 634.00 | 6% | \$600.43 |
| PW 4HR AHR -16703T | 95507-16703T | \$ 768.00 | 6% | \$727.33 |
| PW 4HR AHR 16704 | 95507-16704 | \$ 935.00 | 6% | \$885.49 |
| PW 4HR AHR -16704T | 95507-16704T | \$ 1,121.00 | 6% | \$1,061.64 |
| PW 4HR AHR 16705 | 95507-16705 | \$ 801.00 | 6% | \$758.59 |
| PW 4HR AHR -16705T | 95507-16705T | \$ 978.00 | 6% | \$926.21 |
| PW 4HR AHR 16706 | 95507-16706 | \$ 1,238.00 | 6% | \$1,172.45 |
| PW 4HR AHR -16706T | 95507-16706T | \$ 1,487.00 | 6% | \$1,408.26 |
| PW 4HR AHR 16710 | 95507-16710 | \$ 246.00 | 6% | \$232.97 |
| PW 4HR AHR 16710T | 95507-16710T | \$ 293.00 | 6% | \$277.49 |
| PW 4HR AHR 16711 | 95507-16711 | \$ 99.00 | 6% | \$93.76 |
| PW 4HR AHR 16711T | 95507-16711T | \$ 121.00 | 6% | \$114.59 |
| PW 4HR AHR 16712 | 95507-16712 | \$ 142.00 | 6% | \$134.48 |
| PW 4HR AHR 16712T | 95507-16712T | \$ 166.00 | 6% | \$157.21 |
| PW 4HR AHR 16713 | 95507-16713 | \$ 59.00 | 6% | \$55.88 |
| PW 4HR AHR 16713T | 95507-16713T | \$ 75.00 | 6% | \$71.03 |
| PW 4HR AHR 16715 | 95507-16715 | \$ 97.00 | 6% | \$91.86 |
| PW 4HR AHR 16715T | 95507-16715T | \$ 121.00 | 6% | \$114.59 |
| PW 4HR AHR 16716 | 95507-16716 | \$ 435.00 | 6% | \$411.97 |
| PW 4HR AHR -16716T | 95507-16716T | \$ 514.00 | 6% | \$486.78 |
| PW 4HR AHR 16717 | 95507-16717 | \$ 649.00 | 6% | \$614.64 |
| PW 4HR AHR 16718 | 95507-16718 | \$ 465.00 | 6% | \$440.38 |
| PW 4HR AHR -16718T | 95507-16718T | \$ 553.00 | 6% | \$523.72 |
| PW 4HR AHR 16719 | 95507-16719 | \$ 691.00 | 6% | \$654.41 |
| PW 4HR AHR -16719T | 95507-16719T | \$ 826.00 | 6% | \$782.26 |
| PW 4HR AHR 16720 | 95507-16720 | \$ 1,037.00 | 6% | \$982.09 |
| PW 4HR AHR 16720T | 95507-16720T | \$ 1,206.00 | 6% | \$1,142.14 |
| PW 4HR AHR 16756 | 95507-16756 | \$ 752.00 | 6% | \$712.18 |
| PW 4HR AHR 16756T | 95507-16756T | \$ 884.00 | 6% | \$837.19 |
| PW 4HR AHR 16757 | 95507-16757 | \$ 714.00 | 6% | \$676.19 |
| PW 4HR AHR 16757T | 95507-16757T | \$ 848.00 | 6% | \$803.10 |
| PW 4HR AHR 16790 | 95507-16790 | \$ 1,663.00 | 6% | \$1,574.94 |
| PW 4HR AHR 16791 | 95507-16791 | \$ 2,146.00 | 6% | \$2,032.37 |
| PW 4HR AHR 16801 | 95507-16801 | \$ 210.00 | 6% | \$198.88 |
| PW 4HR AHR 16802 | 95507-16802 | \$ 238.00 | 6% | \$225.40 |
| PW 4HR AHR 16803 | 95507-16803 | \$ 258.00 | 6% | \$244.34 |
| PW 4HR AHR 16804 | 95507-16804 | \$ 313.00 | 6% | \$296.43 |
| PW 4HR AHR 16805 | 95507-16805 | \$ 68.00 | 6% | \$64.40 |
| PW 4HR AHR 16806 | 95507-16806 | \$ 54.00 | 6% | \$51.14 |
| PW 4HR AHR Summit 17101 | 95507-17101 | \$ 3,156.00 | 6% | \$2,988.89 |

| | | | | |
|--------------------------|--------------|-------------|----|------------|
| PW 4HR AHR 17101T | 95507-17101T | \$ 4,029.00 | 6% | \$3,815.66 |
| PW 4HR AHR Summit 17102 | 95507-17102 | \$ 3,156.00 | 6% | \$2,988.89 |
| PW 4HR AHR 17102T | 95507-17102T | \$ 4,029.00 | 6% | \$3,815.66 |
| PW 4HR AHR Summit 17103 | 95507-17103 | \$ 2,197.00 | 6% | \$2,080.67 |
| PW 4HR AHR Summit 17103C | 95507-17103C | \$ 2,132.00 | 6% | \$2,019.11 |
| PW 4HR AHR 17103T | 95507-17103T | \$ 2,811.00 | 6% | \$2,662.16 |
| PW 4HR AHR Summit 17104 | 95507-17104 | \$ 2,197.00 | 6% | \$2,080.67 |
| PW 4HR AHR 17104T | 95507-17104T | \$ 2,811.00 | 6% | \$2,662.16 |
| PW 4HR AHR Summit 17121 | 95507-17121 | \$ 625.00 | 6% | \$591.91 |
| PW 4HR AHR Summit 17122 | 95507-17122 | \$ 392.00 | 6% | \$371.24 |
| PW 4HR AHR -17200 | 95507-17200 | \$ 4,968.00 | 6% | \$4,704.94 |
| PW 4HR AHR 17200T | 95507-17200T | \$ 5,682.00 | 6% | \$5,381.14 |
| PW 4HR AHR Summit 17201 | 95507-17201 | \$ 4,968.00 | 6% | \$4,704.94 |
| PW 4HR AHR 17201T | 95507-17201T | \$ 5,682.00 | 6% | \$5,381.14 |
| PW 4HR AHR Summit 17202 | 95507-17202 | \$ 4,968.00 | 6% | \$4,704.94 |
| PW 4HR AHR 17202T | 95507-17202T | \$ 5,682.00 | 6% | \$5,381.14 |
| PW 4HR AHR Summit 17203 | 95507-17203 | \$ 5,043.00 | 6% | \$4,775.97 |
| PW 4HR AHR 17203T | 95507-17203T | \$ 5,771.00 | 6% | \$5,465.43 |
| PW 4HR AHR Summit 17204 | 95507-17204 | \$ 5,043.00 | 6% | \$4,775.97 |
| PW 4HR AHR 17204T | 95507-17204T | \$ 5,771.00 | 6% | \$5,465.43 |
| PW 4HR AHR Summit 17205 | 95507-17205 | \$ 5,011.00 | 6% | \$4,745.67 |
| PW 4HR AHR 17205T | 95507-17205T | \$ 5,719.00 | 6% | \$5,416.18 |
| PW 4HR AHR Summit 17206 | 95507-17206 | \$ 5,011.00 | 6% | \$4,745.67 |
| PW 4HR AHR 17206T | 95507-17206T | \$ 5,719.00 | 6% | \$5,416.18 |
| PW 4HR AHR 17300 | 95507-17300 | \$ 3,282.00 | 6% | \$3,108.22 |
| PW 4HR AHR 17310 | 95507-17310 | \$ 2,978.00 | 6% | \$2,820.31 |
| PW 4HR AHR -17310T | 95507-17310T | \$ 3,582.00 | 6% | \$3,392.33 |
| PW 4HR AHR 17350 | 95507-17350 | \$ 3,008.00 | 6% | \$2,848.73 |
| PW 4HR AHR 17360 | 95507-17360 | \$ 3,702.00 | 6% | \$3,505.98 |
| PW 4HR AHR 17401 | 95507-17401 | \$ 461.00 | 6% | \$436.59 |
| PW 4HR AHR 17401G | 95507-17401G | \$ 545.00 | 6% | \$516.14 |
| PW 4HR AHR 17401T | 95507-17401T | \$ 517.00 | 6% | \$489.62 |
| PW 4HR AHR 17402 | 95507-17402 | \$ 664.00 | 6% | \$628.84 |
| PW 4HR AHR 17402G | 95507-17402G | \$ 728.00 | 6% | \$689.45 |
| PW 4HR AHR 17402T | 95507-17402T | \$ 692.00 | 6% | \$655.36 |
| PW 4HR AHR 17403 | 95507-17403 | \$ 709.00 | 6% | \$671.46 |
| PW 4HR AHR 17404 | 95507-17404 | \$ 333.00 | 6% | \$315.37 |
| PW 4HR AHR 17405 | 95507-17405 | \$ 429.00 | 6% | \$406.28 |
| PW 4HR AHR 17700 | 95507-17700 | \$ 5,825.00 | 6% | \$5,516.57 |
| PW 4HR AHR 17701 | 95507-17701 | \$ 5,149.00 | 6% | \$4,876.36 |
| PW 4HR AHR 17702 | 95507-17702 | \$ 5,149.00 | 6% | \$4,876.36 |
| PW 4HR AHR 17703 | 95507-17703 | \$ 5,643.00 | 6% | \$5,344.20 |

| | | | | |
|----------------------|-----------------|-------------|----|------------|
| PW 4HR AHR 17704 | 95507-17704 | \$ 5,643.00 | 6% | \$5,344.20 |
| PW 4HR AHR 17705 | 95507-17705 | \$ 5,185.00 | 6% | \$4,910.45 |
| PW 4HR AHR 17706 | 95507-17706 | \$ 5,185.00 | 6% | \$4,910.45 |
| PW 4HR AHR 17800 | 95507-17800 | \$ 5,828.00 | 6% | \$5,519.41 |
| PW 4HR AHR 17810 | 95507-17810 | \$ 4,661.00 | 6% | \$4,414.20 |
| PW 4HR AHR 18101 | 95507-18101 | \$ 297.00 | 6% | \$281.27 |
| PW 4HR AHR 18102 | 95507-18102 | \$ 378.00 | 6% | \$357.98 |
| PW 4HR AHR 18103 | 95507-18103 | \$ 417.00 | 6% | \$394.92 |
| PW 4HR AHR 18104 | 95507-18104 | \$ 597.00 | 6% | \$565.39 |
| PW 4HR AHR 18104-6PK | 95507-18104-6PK | \$ 3,466.00 | 6% | \$3,282.48 |
| PW 4HR AHR 18202 | 95507-18202 | \$ 223.00 | 6% | \$211.19 |
| PW 4HR AHR 30135 | 95507-30135 | \$ 921.00 | 6% | \$872.23 |
| PW 4HR AHR 30136 | 95507-30136 | \$ 6,995.00 | 6% | \$6,624.61 |
| PW 4HR AHR 30137 | 95507-30137 | \$ 1,148.00 | 6% | \$1,087.21 |
| PW 4HR AHR 30138 | 95507-30138 | \$ 5,283.00 | 6% | \$5,003.27 |
| PW 4HR AHR 30139 | 95507-30139 | \$ 9,661.00 | 6% | \$9,149.45 |
| PW 4HR AHR 30912 | 95507-30912 | \$ 59.00 | 6% | \$55.88 |
| PW 4HR AHR 30913 | 95507-30913 | \$ 59.00 | 6% | \$55.88 |
| PW 4HR AHR 31012 | 95507-31012 | \$ 149.00 | 6% | \$141.11 |
| PW 4HR AHR 31013 | 95507-31013 | \$ 149.00 | 6% | \$141.11 |
| PW 4HR AHR 31014 | 95507-31014 | \$ 149.00 | 6% | \$141.11 |
| PW 4HR AHR 31015 | 95507-31015 | \$ 149.00 | 6% | \$141.11 |
| PW 4HR AHR 31016 | 95507-31016 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR 31017 | 95507-31017 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR 31018 | 95507-31018 | \$ 387.00 | 6% | \$366.51 |
| PW 4HR AHR 31019 | 95507-31019 | \$ 387.00 | 6% | \$366.51 |
| PW 4HR AHR 31025 | 95507-31025 | \$ 64.00 | 6% | \$60.61 |
| PW 4HR AHR 31026 | 95507-31026 | \$ 64.00 | 6% | \$60.61 |
| PW 4HR AHR 31028 | 95507-31028 | \$ 66.00 | 6% | \$62.51 |
| PW 4HR AHR 31029 | 95507-31029 | \$ 75.00 | 6% | \$71.03 |
| PW 4HR AHR 31031 | 95507-31031 | \$ 86.00 | 6% | \$81.45 |
| PW 4HR AHR 31032 | 95507-31032 | \$ 86.00 | 6% | \$81.45 |
| PW 4HR AHR 31034 | 95507-31034 | \$ 141.00 | 6% | \$133.53 |
| PW 4HR AHR 31035 | 95507-31035 | \$ 141.00 | 6% | \$133.53 |
| PW 4HR AHR 31050 | 95507-31050 | \$ 133.00 | 6% | \$125.96 |
| PW 4HR AHR 31051 | 95507-31051 | \$ 133.00 | 6% | \$125.96 |
| PW 4HR AHR 31055 | 95507-31055 | \$ 133.00 | 6% | \$125.96 |
| PW 4HR AHR 31056 | 95507-31056 | \$ 133.00 | 6% | \$125.96 |
| PW 4HR AHR 37101 | 95507-37101 | \$ 58.00 | 6% | \$54.93 |
| PW 4HR AHR 37102 | 95507-37102 | \$ 58.00 | 6% | \$54.93 |
| PW 4HR AHR 37103 | 95507-37103 | \$ 58.00 | 6% | \$54.93 |

| | | | | |
|-------------------------|--------------------|-------------|----|------------|
| PW 4HR AHR 37111 | 95507-37111 | \$ 68.00 | 6% | \$64.40 |
| PW 4HR AHR 37112 | 95507-37112 | \$ 68.00 | 6% | \$64.40 |
| PW 4HR AHR 37113 | 95507-37113 | \$ 89.00 | 6% | \$84.29 |
| PW 4HR AHR 37114 | 95507-37114 | \$ 89.00 | 6% | \$84.29 |
| PW 4HR AHR 37115 | 95507-37115 | \$ 68.00 | 6% | \$64.40 |
| PW 4HR AHR 37116 | 95507-37116 | \$ 89.00 | 6% | \$84.29 |
| PW 4HR AHR 37117 | 95507-37117 | \$ 68.00 | 6% | \$64.40 |
| PW 4HR AHR 37121 | 95507-37121 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 37122 | 95507-37122 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 37123 | 95507-37123 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 37124 | 95507-37124 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 37125 | 95507-37125 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 37126 | 95507-37126 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 37129 | 95507-37129 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 37130 | 95507-37130 | \$ 134.00 | 6% | \$126.90 |
| PW 4HR AHR 39031 | 95507-39031 | \$ 111.00 | 6% | \$105.12 |
| PW 4HR AHR 39032 | 95507-39032 | \$ 238.00 | 6% | \$225.40 |
| PW 4HR AHR 39033 | 95507-39033 | \$ 111.00 | 6% | \$105.12 |
| PW 4HR AHR 39034 | 95507-39034 | \$ 111.00 | 6% | \$105.12 |
| PW 4HR AHR 39035 | 95507-39035 | \$ 1,052.00 | 6% | \$996.30 |
| PW 4HR AHR 39036 | 95507-39036 | \$ 132.00 | 6% | \$125.01 |
| PW 4HR AHR 39037 | 95507-39037 | \$ 132.00 | 6% | \$125.01 |
| PW 4HR AHR 39038 | 95507-39038 | \$ 277.00 | 6% | \$262.33 |
| PW 4HR AHR 39039 | 95507-39039 | \$ 277.00 | 6% | \$262.33 |
| PW 4HR AHR 39505 | 95507-39505 | \$ 65.00 | 6% | \$61.56 |
| PW 4HR AHR 4120-24MW-4Y | 95507-4120-24MW-4Y | \$ 877.00 | 6% | \$830.56 |
| PW 4HR AHR 4120-48MW-4Y | 95507-4120-48MW-4Y | \$ 1,170.00 | 6% | \$1,108.05 |
| PW 4HR AHR 4120C | 95507-4120C | \$ 6,502.00 | 6% | \$6,157.72 |
| PW 4HR AHR 4120C-1 | 95507-4120C-1 | \$ 7,339.00 | 6% | \$6,950.40 |
| PW 4HR AHR 41216 | 95507-41216 | \$ 1,994.00 | 6% | \$1,888.42 |
| PW 4HR AHR 4220-12P-4X | 95507-4220-12P-4X | \$ 255.00 | 6% | \$241.50 |
| PW 4HR AHR 4220-12T-4X | 95507-4220-12T-4X | \$ 187.00 | 6% | \$177.10 |
| PW 4HR AHR 4220-24P-4X | 95507-4220-24P-4X | \$ 340.00 | 6% | \$322.00 |
| PW 4HR AHR 4220-24T-4X | 95507-4220-24T-4X | \$ 263.00 | 6% | \$249.07 |

| | | | | |
|--------------------------------|---------------------------|--------------|----|--------------------|
| PW 4HR AHR 4220-48P-4X | 95507-4220-48P-4X | \$ 510.00 | 6% | <i>\$483.00</i> |
| PW 4HR AHR 4220-48T-4X | 95507-4220-48T-4X | \$ 382.00 | 6% | <i>\$361.77</i> |
| PW 4HR AHR 4220-4MW-20P-4X | 95507-4220-4MW-20P-4X | \$ 467.00 | 6% | <i>\$442.27</i> |
| PW 4HR AHR 4220-4MW-8P-4X | 95507-4220-4MW-8P-4X | \$ 331.00 | 6% | <i>\$313.47</i> |
| PW 4HR AHR 4220-8MW-40P-4X | 95507-4220-8MW-40P-4X | \$ 680.00 | 6% | <i>\$643.99</i> |
| PW 4HR AHR 4220-8X | 95507-4220-8X | \$ 357.00 | 6% | <i>\$338.10</i> |
| PW 4HR AHR BD X 48001 | 95507-48001 | \$ 8,314.00 | 6% | <i>\$7,873.77</i> |
| PW 4HR AHR 48038 | 95507-48038 | \$ 3,326.00 | 6% | <i>\$3,149.89</i> |
| PW 4HR AHR 48039 | 95507-48039 | \$ 3,326.00 | 6% | <i>\$3,149.89</i> |
| PW 4hr Parts only-48040 | 95507-48040 | \$ 3,203.00 | 6% | <i>\$3,033.40</i> |
| PW 4HR AHR BD X 48041 | 95507-48041 | \$ 3,326.00 | 6% | <i>\$3,149.89</i> |
| PW 4HR AHR BD X 48046 | 95507-48046 | \$ 4,370.00 | 6% | <i>\$4,138.61</i> |
| PW 4HR AHR 48047 | 95507-48047 | \$ 11,645.00 | 6% | <i>\$11,028.40</i> |
| PW 4HR AHR BD X 48051 | 95507-48051 | \$ 8,012.00 | 6% | <i>\$7,587.76</i> |
| PW 4HR AHR 48061 | 95507-48061 | \$ 9,364.00 | 6% | <i>\$8,868.18</i> |
| PW 4HR AHR 48062 | 95507-48062 | \$ 14,984.00 | 6% | <i>\$14,190.60</i> |
| PW 4HR AHR 5320-16P-4XE | 95507-5320-16P-4XE | \$ 335.00 | 6% | <i>\$317.26</i> |
| PW 4HR AHR 5320-16P-4XE-DC | 95507-5320-16P-4XE-DC | \$ 403.00 | 6% | <i>\$381.66</i> |
| PW 4HR AHR 5320-24P-8XE | 95507-5320-24P-8XE | \$ 369.00 | 6% | <i>\$349.46</i> |
| PW 4HR AHR 5320-24T-24S-4XE-XT | 95507-5320-24T-24S-4XE-XT | \$ 552.00 | 6% | <i>\$522.77</i> |
| PW 4HR AHR 5320-24T-4X-XT | 95507-5320-24T-4X-XT | \$ 297.00 | 6% | <i>\$281.27</i> |
| PW 4HR AHR 5320-24T-8XE | 95507-5320-24T-8XE | \$ 262.00 | 6% | <i>\$248.13</i> |
| PW 4HR AHR 5320-48P-8XE | 95507-5320-48P-8XE | \$ 619.00 | 6% | <i>\$586.22</i> |
| PW 4HR AHR 5320-48T-8XE | 95507-5320-48T-8XE | \$ 417.00 | 6% | <i>\$394.92</i> |
| PW 4HR AHR 5420F-16MW-32P-4XE | 95507-5420F-16MW-32P-4XE | \$ 1,078.00 | 6% | <i>\$1,020.92</i> |

| | | | | |
|-------------------------------|--------------------------|-------------|----|-------------------|
| PW 4HR AHR 5420F-16W-32P-4XE | 95507-5420F-16W-32P-4XE | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| PW 4HR AHR 5420F-24P-4XE | 95507-5420F-24P-4XE | \$ 455.00 | 6% | <i>\$430.91</i> |
| PW 4HR AHR 5420F-24S-4XE | 95507-5420F-24S-4XE | \$ 513.00 | 6% | <i>\$485.84</i> |
| PW 4HR AHR 5420F-24T-4XE | 95507-5420F-24T-4XE | \$ 415.00 | 6% | <i>\$393.03</i> |
| PW 4HR AHR 5420F-48P-4XE | 95507-5420F-48P-4XE | \$ 682.00 | 6% | <i>\$645.89</i> |
| PW 4HR AHR 5420F-48P-4XL | 95507-5420F-48P-4XL | \$ 825.00 | 6% | <i>\$781.32</i> |
| PW 4HR AHR 5420F-48T-4XE | 95507-5420F-48T-4XE | \$ 509.00 | 6% | <i>\$482.05</i> |
| PW 4HR AHR 5420F-8W-16P-4XE | 95507-5420F-8W-16P-4XE | \$ 534.00 | 6% | <i>\$505.72</i> |
| PW 4HR AHR 5420M-16MW-32P-4YE | 95507-5420M-16MW-32P-4YE | \$ 1,223.00 | 6% | <i>\$1,158.24</i> |
| PW 4HR AHR 5420M-24T-4YE | 95507-5420M-24T-4YE | \$ 528.00 | 6% | <i>\$500.04</i> |
| PW 4HR AHR 5420M-24W-4YE | 95507-5420M-24W-4YE | \$ 493.00 | 6% | <i>\$466.90</i> |
| PW 4HR AHR 5420M-48T-4YE | 95507-5420M-48T-4YE | \$ 721.00 | 6% | <i>\$682.82</i> |
| PW 4HR AHR 5420M-48W-4YE | 95507-5420M-48W-4YE | \$ 831.00 | 6% | <i>\$787.00</i> |
| PW 4HR AHR 5520-12MW-36W | 95507-5520-12MW-36W | \$ 1,289.00 | 6% | <i>\$1,220.75</i> |
| PW 4HR AHR 5520-24T | 95507-5520-24T | \$ 465.00 | 6% | <i>\$440.38</i> |
| PW 4HR AHR 5520-24T-ACDC-BASE | 95507-5520-24T-ACDC-BASE | \$ 465.00 | 6% | <i>\$440.38</i> |
| PW 4HR AHR 5520-24T-BASE | 95507-5520-24T-BASE | \$ 465.00 | 6% | <i>\$440.38</i> |
| PW 4HR AHR 5520-24W | 95507-5520-24W | \$ 708.00 | 6% | <i>\$670.51</i> |
| PW 4HR AHR 5520-24X | 95507-5520-24X | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |

| | | | | |
|--------------------------------|---------------------------|-------------|----|-------------------|
| PW 4HR AHR 5520-24X-ACDC-BASE | 95507-5520-24X-ACDC-BASE | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| PW 4HR AHR 5520-24X-BASE | 95507-5520-24X-BASE | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| PW 4HR AHR 5520-48SE | 95507-5520-48SE | \$ 1,376.00 | 6% | <i>\$1,303.14</i> |
| PW 4HR AHR 5520-48SE-ACDC-BASE | 95507-5520-48SE-ACDC-BASE | \$ 1,376.00 | 6% | <i>\$1,303.14</i> |
| PW 4HR AHR 5520-48SE-BASE | 95507-5520-48SE-BASE | \$ 1,376.00 | 6% | <i>\$1,303.14</i> |
| PW 4HR AHR 5520-48T | 95507-5520-48T | \$ 796.00 | 6% | <i>\$753.85</i> |
| PW 4HR AHR 5520-48T-ACDC-BASE | 95507-5520-48T-ACDC-BASE | \$ 796.00 | 6% | <i>\$753.85</i> |
| PW 4HR AHR 5520-48T-BASE | 95507-5520-48T-BASE | \$ 796.00 | 6% | <i>\$753.85</i> |
| PW 4HR AHR 5520-48W | 95507-5520-48W | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| PW 4HR AHR 5720-24MW | 95507-5720-24MW | \$ 1,615.00 | 6% | <i>\$1,529.49</i> |
| PW 4HR AHR 5720-24MXW | 95507-5720-24MXW | \$ 2,185.00 | 6% | <i>\$2,069.30</i> |
| PW 4HR AHR 5720-48MW | 95507-5720-48MW | \$ 1,900.00 | 6% | <i>\$1,799.40</i> |
| PW 4HR AHR 5720-48MXW | 95507-5720-48MXW | \$ 2,755.00 | 6% | <i>\$2,609.12</i> |
| PW 4HR AHR 7520-48XT-6C | 95507-7520-48XT-6C | \$ 3,142.00 | 6% | <i>\$2,975.63</i> |
| PW 4HR AHR 7520-48XT-6C-AC-F | 95507-7520-48XT-6C-AC-F | \$ 3,142.00 | 6% | <i>\$2,975.63</i> |
| PW 4HR AHR 7520-48XT-6C-AC-R | 95507-7520-48XT-6C-AC-R | \$ 3,142.00 | 6% | <i>\$2,975.63</i> |
| PW 4HR AHR 7520-48Y-8C | 95507-7520-48Y-8C | \$ 2,932.00 | 6% | <i>\$2,776.75</i> |
| PW 4HR AHR 7520-48Y-8C-AC-F | 95507-7520-48Y-8C-AC-F | \$ 2,932.00 | 6% | <i>\$2,776.75</i> |
| PW 4HR AHR 7520-48Y-8C-AC-R | 95507-7520-48Y-8C-AC-R | \$ 2,932.00 | 6% | <i>\$2,776.75</i> |

| | | | | |
|-------------------------------|--------------------------|-------------|----|------------|
| PW 4HR AHR 7520-48YE-8CE | 95507-7520-48YE-8CE | \$ 3,404.00 | 6% | \$3,223.76 |
| PW 4HR AHR 7520-48YE-8CE-AC-F | 95507-7520-48YE-8CE-AC-F | \$ 3,404.00 | 6% | \$3,223.76 |
| PW 4HR AHR 7520-48YE-8CE-AC-R | 95507-7520-48YE-8CE-AC-R | \$ 3,404.00 | 6% | \$3,223.76 |
| PW 4HR AHR 7720-32C | 95507-7720-32C | \$ 3,635.00 | 6% | \$3,442.53 |
| PW 4HR AHR 7720-32C-AC-F | 95507-7720-32C-AC-F | \$ 3,635.00 | 6% | \$3,442.53 |
| PW 4HR AHR 7720-32C-AC-R | 95507-7720-32C-AC-R | \$ 3,635.00 | 6% | \$3,442.53 |
| PW 4HR AHR 8520-48XT-6C | 95507-8520-48XT-6C | \$ 2,978.00 | 6% | \$2,820.31 |
| PW 4HR AHR 8520-48XT-6C-AC-F | 95507-8520-48XT-6C-AC-F | \$ 2,978.00 | 6% | \$2,820.31 |
| PW 4HR AHR 8520-48XT-6C-AC-R | 95507-8520-48XT-6C-AC-R | \$ 2,978.00 | 6% | \$2,820.31 |
| PW 4HR AHR 8520-48XT-6C-DC-F | 95507-8520-48XT-6C-DC-F | \$ 2,978.00 | 6% | \$2,820.31 |
| PW 4HR AHR 8520-48XT-6C-DC-R | 95507-8520-48XT-6C-DC-R | \$ 2,978.00 | 6% | \$2,820.31 |
| PW 4HR AHR 8520-48Y-8C | 95507-8520-48Y-8C | \$ 3,022.00 | 6% | \$2,861.99 |
| PW 4HR AHR 8520-48Y-8C-AC-F | 95507-8520-48Y-8C-AC-F | \$ 3,022.00 | 6% | \$2,861.99 |
| PW 4HR AHR 8520-48Y-8C-AC-R | 95507-8520-48Y-8C-AC-R | \$ 3,022.00 | 6% | \$2,861.99 |
| PW 4HR AHR 8520-48Y-8C-DC-F | 95507-8520-48Y-8C-DC-F | \$ 3,022.00 | 6% | \$2,861.99 |
| PW 4HR AHR 8520-48Y-8C-DC-R | 95507-8520-48Y-8C-DC-R | \$ 3,022.00 | 6% | \$2,861.99 |
| PW 4HR AHR 86100 | 95507-86100 | \$ 5,624.00 | 6% | \$5,326.21 |
| PW 4HR AHR 86101 | 95507-86101 | \$ 7,725.00 | 6% | \$7,315.96 |
| PW 4HR AHR 87100 | 95507-87100 | \$ 3,490.00 | 6% | \$3,305.20 |
| PW 4HR AHR 87101 | 95507-87101 | \$ 5,372.00 | 6% | \$5,087.55 |

| | | | | |
|--------------------------|---------------------|--------------|----|-------------|
| PW 4HR AHR 8720-32C | 95507-8720-32C | \$ 3,478.00 | 6% | \$3,293.84 |
| PW 4HR AHR 8720-32C-AC-F | 95507-8720-32C-AC-F | \$ 3,478.00 | 6% | \$3,293.84 |
| PW 4HR AHR 8720-32C-AC-R | 95507-8720-32C-AC-R | \$ 3,478.00 | 6% | \$3,293.84 |
| PW 4HR AHR 8720-32C-DC-F | 95507-8720-32C-DC-F | \$ 3,478.00 | 6% | \$3,293.84 |
| PW 4HR AHR 8720-32C-DC-R | 95507-8720-32C-DC-R | \$ 3,478.00 | 6% | \$3,293.84 |
| PW 24X7X4 AHR 8806 | 95507-8806 | \$ 2,082.00 | 6% | \$1,971.76 |
| PW 24X7X4 AHR ASPEN | 95507-8810 | \$ 5,408.00 | 6% | \$5,121.65 |
| PW 4HR AHR 88100 | 95507-88100 | \$ 6,343.00 | 6% | \$6,007.14 |
| PW 4HR AHR 8820-40C | 95507-8820-40C | \$ 13,050.00 | 6% | \$12,359.00 |
| PW 4HR AHR 8820-40C-AC-F | 95507-8820-40C-AC-F | \$ 13,050.00 | 6% | \$12,359.00 |
| PW 4HR AHR 8820-40C-AC-R | 95507-8820-40C-AC-R | \$ 13,050.00 | 6% | \$12,359.00 |
| PW 4HR AHR 8820-40C-DC-F | 95507-8820-40C-DC-F | \$ 13,050.00 | 6% | \$12,359.00 |
| PW 4HR AHR 8820-40C-DC-R | 95507-8820-40C-DC-R | \$ 13,050.00 | 6% | \$12,359.00 |
| PW 4HR AHR 8820-80C | 95507-8820-80C | \$ 23,794.00 | 6% | \$22,534.11 |
| PW 4HR AHR 8820-80C-AC-F | 95507-8820-80C-AC-F | \$ 23,794.00 | 6% | \$22,534.11 |
| PW 4HR AHR 8820-80C-AC-R | 95507-8820-80C-AC-R | \$ 23,794.00 | 6% | \$22,534.11 |
| PW 4HR AHR 8820-80C-DC-F | 95507-8820-80C-DC-F | \$ 23,794.00 | 6% | \$22,534.11 |
| PW 4HR AHR 8820-80C-DC-R | 95507-8820-80C-DC-R | \$ 23,794.00 | 6% | \$22,534.11 |
| PW 4HR AHR 9920-16C | 95507-9920-16C | \$ 10,222.00 | 6% | \$9,680.75 |
| PW 4HR AHR 9920-4D | 95507-9920-4D | \$ 10,222.00 | 6% | \$9,680.75 |
| PW 4HR AHR 9920-NPB-8 | 95507-9920-NPB-8 | \$ 16,328.00 | 6% | \$15,463.43 |
| PW 4hr AHR | 95507-A10148 | \$ 3,155.00 | 6% | \$2,987.94 |
| PW 4hr AHR | 95507-A10149 | \$ 6,027.00 | 6% | \$5,707.87 |
| PW 4hr AHR | 95507-A10152 | \$ 6,027.00 | 6% | \$5,707.87 |

| | | | | |
|------------------------------|-------------------------|--------------|----|--------------------|
| PW 4hr AHR | 95507-A10154 | \$ 18,356.00 | 6% | <i>\$17,384.05</i> |
| PW 4hr AHR | 95507-A10155 | \$ 6,501.00 | 6% | <i>\$6,156.77</i> |
| PW 4hr AHR | 95507-A10157 | \$ 11,464.00 | 6% | <i>\$10,856.98</i> |
| PW 4HR AHR 10175 | 95507-A10175 | \$ 7,644.00 | 6% | <i>\$7,239.25</i> |
| PW 4HR AHR A10176 | 95507-A10176 | \$ 11,467.00 | 6% | <i>\$10,859.82</i> |
| PW 4HR AHR AH-AP-1130-AC-CE | 95507-AH-AP-1130-AC-CE | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR AHR AH-AP-1130-AC-FCC | 95507-AH-AP-1130-AC-FCC | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR AHR AH-AP-1130-AC-W | 95507-AH-AP-1130-AC-W | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR AHR AH-AP-122-AC-CAN | 95507-AH-AP-122-AC-CAN | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-122-AC-CE | 95507-AH-AP-122-AC-CE | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-122-AC-FCC | 95507-AH-AP-122-AC-FCC | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-122-AC-W | 95507-AH-AP-122-AC-W | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-130-AC-CE | 95507-AH-AP-130-AC-CE | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-130-AC-FCC | 95507-AH-AP-130-AC-FCC | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-130-AC-W | 95507-AH-AP-130-AC-W | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-150W-AC-CAN | 95507-AH-AP-150W-AC-CAN | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-150W-AC-CE | 95507-AH-AP-150W-AC-CE | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-150W-AC-FCC | 95507-AH-AP-150W-AC-FCC | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-150W-AC-W | 95507-AH-AP-150W-AC-W | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-230-AC-CE | 95507-AH-AP-230-AC-CE | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-230-AC-FCC | 95507-AH-AP-230-AC-FCC | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-230-AC-W | 95507-AH-AP-230-AC-W | \$ 83.00 | 6% | <i>\$78.61</i> |

| | | | | |
|------------------------------|-------------------------|-----------|----|-----------------|
| PW 4HR AHR AH-AP-250-AC-CAN | 95507-AH-AP-250-AC-CAN | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-250-AC-CE | 95507-AH-AP-250-AC-CE | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-250-AC-FCC | 95507-AH-AP-250-AC-FCC | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-250-AC-W | 95507-AH-AP-250-AC-W | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-AP-630-AX-CAN | 95507-AH-AP-630-AX-CAN | \$ 129.00 | 6% | <i>\$122.17</i> |
| PW 4HR AHR AH-AP-630-AX-CE | 95507-AH-AP-630-AX-CE | \$ 129.00 | 6% | <i>\$122.17</i> |
| PW 4HR AHR AH-AP-630-AX-FCC | 95507-AH-AP-630-AX-FCC | \$ 129.00 | 6% | <i>\$122.17</i> |
| PW 4HR AHR AH-AP-630-AX-W | 95507-AH-AP-630-AX-W | \$ 129.00 | 6% | <i>\$122.17</i> |
| PW 4HR AHR AH-AP-650-AX-CAN | 95507-AH-AP-650-AX-CAN | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-AP-650-AX-CE | 95507-AH-AP-650-AX-CE | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-AP-650-AX-FCC | 95507-AH-AP-650-AX-FCC | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-AP-650-AX-W | 95507-AH-AP-650-AX-W | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-AP-650X-AX-CAN | 95507-AH-AP-650X-AX-CAN | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-AP-650X-AX-CE | 95507-AH-AP-650X-AX-CE | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-AP-650X-AX-FCC | 95507-AH-AP-650X-AX-FCC | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-AP-650X-AX-W | 95507-AH-AP-650X-AX-W | \$ 126.00 | 6% | <i>\$119.33</i> |
| PW 4HR AHR AH-ATOM-CAN | 95507-AH-ATOM-CAN | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW 4HR AHR AH-ATOM-CE-EU | 95507-AH-ATOM-CE-EU | \$ 88.00 | 6% | <i>\$83.34</i> |
| PW 4HR AHR AH-ATOM-CE-UK | 95507-AH-ATOM-CE-UK | \$ 88.00 | 6% | <i>\$83.34</i> |

| | | | | |
|---------------------------|----------------------|-----------|----|-----------------|
| PW 4HR AHR AH-ATOM-FCC | 95507-AH-ATOM-FCC | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW 4HR AHR AH-ATOM-W | 95507-AH-ATOM-W | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW 4HR AHR AH-ATOM-W-EU | 95507-AH-ATOM-W-EU | \$ 88.00 | 6% | <i>\$83.34</i> |
| PW 4HR AHR AH-ATOM-W-UK | 95507-AH-ATOM-W-UK | \$ 88.00 | 6% | <i>\$83.34</i> |
| PW 4HR AHR AH-SR-2208P-AU | 95507-AH-SR-2208P-AU | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-SR-2208P-EU | 95507-AH-SR-2208P-EU | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-SR-2208P-NA | 95507-AH-SR-2208P-NA | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-SR-2208P-UK | 95507-AH-SR-2208P-UK | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-SR-2224P-AU | 95507-AH-SR-2224P-AU | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR AHR AH-SR-2224P-EU | 95507-AH-SR-2224P-EU | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR AHR AH-SR-2224P-NA | 95507-AH-SR-2224P-NA | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR AHR AH-SR-2224P-UK | 95507-AH-SR-2224P-UK | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR AHR AH-SR-2324P-AU | 95507-AH-SR-2324P-AU | \$ 173.00 | 6% | <i>\$163.84</i> |
| PW 4HR AHR AH-SR-2324P-EU | 95507-AH-SR-2324P-EU | \$ 173.00 | 6% | <i>\$163.84</i> |
| PW 4HR AHR AH-SR-2324P-NA | 95507-AH-SR-2324P-NA | \$ 173.00 | 6% | <i>\$163.84</i> |
| PW 4HR AHR AH-SR-2324P-UK | 95507-AH-SR-2324P-UK | \$ 173.00 | 6% | <i>\$163.84</i> |
| PW 4HR AHR AH-SR-2348P-AU | 95507-AH-SR-2348P-AU | \$ 301.00 | 6% | <i>\$285.06</i> |
| PW 4HR AHR AH-SR-2348P-EU | 95507-AH-SR-2348P-EU | \$ 301.00 | 6% | <i>\$285.06</i> |
| PW 4HR AHR AH-SR-2348P-NA | 95507-AH-SR-2348P-NA | \$ 301.00 | 6% | <i>\$285.06</i> |
| PW 4HR AHR AH-SR-2348P-UK | 95507-AH-SR-2348P-UK | \$ 301.00 | 6% | <i>\$285.06</i> |
| PW 4HR AHR AH-XR200P-AU | 95507-AH-XR200P-AU | \$ 83.00 | 6% | <i>\$78.61</i> |

| | | | | |
|------------------------------|-------------------------|-----------|----|-----------------|
| PW 4HR AHR AH-XR200P-EU | 95507-AH-XR200P-EU | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-XR200P-UK | 95507-AH-XR200P-UK | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-XR200P-US | 95507-AH-XR200P-US | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AH-XR600P | 95507-AH-XR600P | \$ 91.00 | 6% | <i>\$86.18</i> |
| PW 4HR AHR AH-XR600P-AU | 95507-AH-XR600P-AU | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AH-XR600P-EU | 95507-AH-XR600P-EU | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AH-XR600P-KR | 95507-AH-XR600P-KR | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AH-XR600P-UK | 95507-AH-XR600P-UK | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AH-XR600P-US | 95507-AH-XR600P-US | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AP-8533-68SB30-IL | 95507-AP-8533-68SB30-IL | \$ 151.00 | 6% | <i>\$143.00</i> |
| PW 4HR AHR AP3000-IL | 95507-AP3000-IL | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW 4HR AHR AP3000-TN | 95507-AP3000-TN | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW 4HR AHR AP3000-WW | 95507-AP3000-WW | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW 4HR AHR AP3000X-WW | 95507-AP3000X-WW | \$ 80.50 | 6% | <i>\$76.24</i> |
| PW 4HR AHR AP302W-CAN | 95507-AP302W-CAN | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW 4HR AHR AP302W-EG | 95507-AP302W-EG | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW 4HR AHR AP302W-FCC | 95507-AP302W-FCC | \$ 63.00 | 6% | <i>\$59.66</i> |
| PW 4HR AHR AP302W-WR | 95507-AP302W-WR | \$ 60.00 | 6% | <i>\$56.82</i> |
| PW 4HR AHR AP305C-1-CAN | 95507-AP305C-1-CAN | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AP305C-1-EG | 95507-AP305C-1-EG | \$ 83.00 | 6% | <i>\$78.61</i> |

| | | | | |
|-------------------------|--------------------|----------|----|----------------|
| PW 4HR AHR AP305C-1-FCC | 95507-AP305C-1-FCC | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AP305C-1-IL | 95507-AP305C-1-IL | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AP305C-1-WR | 95507-AP305C-1-WR | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR AP305C-CAN | 95507-AP305C-CAN | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305C-EG | 95507-AP305C-EG | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305C-FCC | 95507-AP305C-FCC | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305C-IL | 95507-AP305C-IL | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305C-WR | 95507-AP305C-WR | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305CX-CAN | 95507-AP305CX-CAN | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305CX-FCC | 95507-AP305CX-FCC | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305CX-IL | 95507-AP305CX-IL | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP305CX-WR | 95507-AP305CX-WR | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR AP310e-1-WR | 95507-AP310e-1-WR | \$ 53.00 | 6% | <i>\$50.19</i> |
| PW 4HR AHR AP310e-CAN | 95507-AP310e-CAN | \$ 56.00 | 6% | <i>\$53.03</i> |
| PW 4HR AHR AP310e-FCC | 95507-AP310e-FCC | \$ 56.00 | 6% | <i>\$53.03</i> |
| PW 4HR AHR AP310e-IL | 95507-AP310e-IL | \$ 56.00 | 6% | <i>\$53.03</i> |
| PW 4HR AHR AP310e-WR | 95507-AP310e-WR | \$ 56.00 | 6% | <i>\$53.03</i> |
| PW 4HR AHR AP310i-1-WR | 95507-AP310i-1-WR | \$ 53.00 | 6% | <i>\$50.19</i> |
| PW 4HR AHR AP310i-CAN | 95507-AP310i-CAN | \$ 56.00 | 6% | <i>\$53.03</i> |

| | | | | |
|-------------------------|--------------------|-----------|----|----------------|
| PW 4HR AHR AP310i-FCC | 95507-AP310i-FCC | \$ 56.00 | 6% | <i>\$53.03</i> |
| PW 4HR AHR AP310i-IL | 95507-AP310i-IL | \$ 56.00 | 6% | <i>\$53.03</i> |
| PW 4HR AHR AP310i-WR | 95507-AP310i-WR | \$ 56.00 | 6% | <i>\$53.03</i> |
| PW 4HR AHR AP360e-CAN | 95507-AP360e-CAN | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR AHR AP360e-FCC | 95507-AP360e-FCC | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR AHR AP360e-IL | 95507-AP360e-IL | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR AHR AP360e-WR | 95507-AP360e-WR | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR AHR AP360i-CAN | 95507-AP360i-CAN | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR AHR AP360i-FCC | 95507-AP360i-FCC | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR AHR AP360i-WR | 95507-AP360i-WR | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR AHR AP4000-WW | 95507-AP4000-1-WW | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AP4000-IL | 95507-AP4000-IL | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AP4000-WW | 95507-AP4000-WW | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW 4HR AHR AP410C-1-CAN | 95507-AP410C-1-CAN | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW 4HR AHR AP410C-1-EG | 95507-AP410C-1-EG | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW 4HR AHR AP410C-1-FCC | 95507-AP410C-1-FCC | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW 4HR AHR AP410C-1-IL | 95507-AP410C-1-IL | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW 4HR AHR AP410C-1-WR | 95507-AP410C-1-WR | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW 4HR AHR AP410C-CAN | 95507-AP410C-CAN | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR AHR AP410C-EG | 95507-AP410C-EG | \$ 101.00 | 6% | <i>\$95.65</i> |

| | | | | |
|-------------------------|--------------------|-----------|----|-----------------|
| PW 4HR AHR AP410C-FCC | 95507-AP410C-FCC | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR AHR AP410C-IL | 95507-AP410C-IL | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR AHR AP410C-WR | 95507-AP410C-WR | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR AHR AP410e-CAN | 95507-AP410e-CAN | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR AP410e-FCC | 95507-AP410e-FCC | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR AP410e-WR | 95507-AP410e-WR | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR AP410i-1-FCC | 95507-AP410i-1-FCC | \$ 92.00 | 6% | <i>\$87.13</i> |
| PW 4HR AHR AP410i-1-WR | 95507-AP410i-1-WR | \$ 92.00 | 6% | <i>\$87.13</i> |
| PW 4HR AHR AP410i-CAN | 95507-AP410i-CAN | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR AP410i-FCC | 95507-AP410i-FCC | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR AP410i-IL | 95507-AP410i-IL | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR AP410i-WR | 95507-AP410i-WR | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR AP460C-CAN | 95507-AP460C-CAN | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460C-EG | 95507-AP460C-EG | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460C-FCC | 95507-AP460C-FCC | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460C-IL | 95507-AP460C-IL | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460C-WR | 95507-AP460C-WR | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460e-CAN | 95507-AP460e-CAN | \$ 115.00 | 6% | <i>\$108.91</i> |
| PW 4HR AHR AP460e-FCC | 95507-AP460e-FCC | \$ 115.00 | 6% | <i>\$108.91</i> |
| PW 4HR AHR AP460e-WR | 95507-AP460e-WR | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR AHR AP460i-CAN | 95507-AP460i-CAN | \$ 110.00 | 6% | <i>\$104.18</i> |

| | | | | |
|---------------------------|----------------------|-----------|----|-----------------|
| PW 4HR AHR AP460i-FCC | 95507-AP460i-FCC | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR AHR AP460i-IL | 95507-AP460i-IL | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR AHR AP460i-WR | 95507-AP460i-WR | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR AHR AP460S12C-CAN | 95507-AP460S12C-CAN | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460S12C-FCC | 95507-AP460S12C-FCC | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460S12C-WR | 95507-AP460S12C-WR | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460S6C-CAN | 95507-AP460S6C-CAN | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460S6C-FCC | 95507-AP460S6C-FCC | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP460S6C-WR | 95507-AP460S6C-WR | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR AHR AP5010-IL | 95507-AP5010-IL | \$ 154.00 | 6% | <i>\$145.85</i> |
| PW 4HR AHR AP5010-WW | 95507-AP5010-WW | \$ 154.00 | 6% | <i>\$145.85</i> |
| PW 4HR AHR AP5020-WW | 95507-AP5020-WW | \$ 167.93 | 6% | <i>\$159.04</i> |
| PW 4HR AHR AP5050D-WW | 95507-AP5050D-WW | \$ 345.00 | 6% | <i>\$326.73</i> |
| PW 4HR AHR AP5050U-WW | 95507-AP5050U-WW | \$ 269.00 | 6% | <i>\$254.76</i> |
| PW 4HR AHR AP505i-FCC | 95507-AP505i-FCC | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW 4HR AHR AP505i-FCC-TAA | 95507-AP505i-FCC-TAA | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW 4HR AHR AP505i-WR | 95507-AP505i-WR | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR AHR AP510C-CAN | 95507-AP510C-CAN | \$ 123.00 | 6% | <i>\$116.49</i> |

| | | | | |
|---------------------------|----------------------|-----------|----|-----------------|
| PW 4HR AHR AP510C-CE | 95507-AP510C-CE | \$ 123.00 | 6% | <i>\$116.49</i> |
| PW 4HR AHR AP510C-FCC | 95507-AP510C-FCC | \$ 123.00 | 6% | <i>\$116.49</i> |
| PW 4HR AHR AP510C-W | 95507-AP510C-W | \$ 123.00 | 6% | <i>\$116.49</i> |
| PW 4HR AHR AP510C-WW | 95507-AP510C-WW | \$ 142.00 | 6% | <i>\$134.48</i> |
| PW 4HR AHR AP510CX-CAN | 95507-AP510CX-CAN | \$ 123.00 | 6% | <i>\$116.49</i> |
| PW 4HR AHR AP510CX-CE | 95507-AP510CX-CE | \$ 123.00 | 6% | <i>\$116.49</i> |
| PW 4HR AHR AP510CX-FCC | 95507-AP510CX-FCC | \$ 123.00 | 6% | <i>\$116.49</i> |
| PW 4HR AHR AP510CX-W | 95507-AP510CX-W | \$ 123.00 | 6% | <i>\$116.49</i> |
| PW 4HR AHR AP510CX-WW | 95507-AP510CX-WW | \$ 142.00 | 6% | <i>\$134.48</i> |
| PW 4HR AHR AP510e-FCC | 95507-AP510e-FCC | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR AHR AP510e-FCC-TAA | 95507-AP510e-FCC-TAA | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR AHR AP510e-WR | 95507-AP510e-WR | \$ 150.00 | 6% | <i>\$142.06</i> |
| PW 4HR AHR AP510i-1-FCC | 95507-AP510i-1-FCC | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR AHR AP510i-1-WR | 95507-AP510i-1-WR | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR AHR AP510i-FCC | 95507-AP510i-FCC | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR AHR AP510i-FCC-TAA | 95507-AP510i-FCC-TAA | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR AHR AP510i-WR | 95507-AP510i-WR | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR AHR AP560h-FCC | 95507-AP560h-FCC | \$ 350.00 | 6% | <i>\$331.47</i> |
| PW 4HR AHR AP560h-WR | 95507-AP560h-WR | \$ 350.00 | 6% | <i>\$331.47</i> |

| | | | | |
|-----------------------|------------------|-------------|----|------------|
| PW 4HR AHR AP560i-FCC | 95507-AP560i-FCC | \$ 257.00 | 6% | \$243.39 |
| PW 4HR AHR AP560i-WR | 95507-AP560i-WR | \$ 245.00 | 6% | \$232.03 |
| PW 4HR AHR AP560m-FCC | 95507-AP560m-FCC | \$ 257.00 | 6% | \$243.39 |
| PW 4HR AHR AP560t-FCC | 95507-AP560t-FCC | \$ 350.00 | 6% | \$331.47 |
| PW 4HR AHR AP560u-FCC | 95507-AP560u-FCC | \$ 239.00 | 6% | \$226.34 |
| PW 4HR AHR E2122 | 95507-E2122 | \$ 5,906.00 | 6% | \$5,593.28 |
| PW 4HR AHR E2122-1 | 95507-E2122-1 | \$ 5,598.00 | 6% | \$5,301.59 |
| PW 4HR AHR E3120-1 | 95507-E3120-1 | \$ 9,156.00 | 6% | \$8,671.19 |
| PW 4HR AHR E3125 | 95507-E3125 | \$ 9,884.00 | 6% | \$9,360.64 |
| PW 4hr AHR | 95507-H30078 | \$ 3,665.00 | 6% | \$3,470.94 |
| PW 4hr AHR | 95507-H30104 | \$ 3,385.00 | 6% | \$3,205.76 |
| PW 4hr AHR | 95507-H30105 | \$ 3,345.00 | 6% | \$3,167.88 |
| PW 4hr AHR | 95507-H30131 | \$ 1,922.00 | 6% | \$1,820.23 |
| PW 4hr AHR | 95507-H30132 | \$ 1,886.00 | 6% | \$1,786.14 |
| PW 4hr AHR | 95507-H30133 | \$ 4,940.00 | 6% | \$4,678.43 |
| PW 4hr AHR | 95507-H30134 | \$ 6,254.00 | 6% | \$5,922.85 |
| PW 4hr AHR | 95507-H30135 | \$ 5,037.00 | 6% | \$4,770.29 |
| PW 4hr AHR | 95507-H30136 | \$ 6,254.00 | 6% | \$5,922.85 |
| PW 4hr AHR | 95507-H30184 | \$ 84.00 | 6% | \$79.55 |
| PW 4hr AHR | 95507-H30185 | \$ 448.00 | 6% | \$424.28 |
| PW 4hr AHR | 95507-H30186 | \$ 227.00 | 6% | \$214.98 |
| PW 4hr AHR | 95507-H30187 | \$ 91.00 | 6% | \$86.18 |
| PW 4hr AHR | 95507-H30188 | \$ 227.00 | 6% | \$214.98 |
| PW 4hr AHR | 95507-H30189 | \$ 227.00 | 6% | \$214.98 |
| PW 4hr AHR | 95507-H30190 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30214 | \$ 242.00 | 6% | \$229.19 |
| PW 4hr AHR | 95507-H30215 | \$ 242.00 | 6% | \$229.19 |
| PW 4hr AHR | 95507-H30216 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30217 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30218 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30219 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30220 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30221 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30222 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30223 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30224 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30225 | \$ 479.00 | 6% | \$453.64 |

| | | | | |
|------------|--------------|-------------|----|------------|
| PW 4hr AHR | 95507-H30226 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30227 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30228 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30229 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30267 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30268 | \$ 479.00 | 6% | \$453.64 |
| PW 4hr AHR | 95507-H30269 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30270 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30271 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30272 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30273 | \$ 1,035.00 | 6% | \$980.20 |
| PW 4hr AHR | 95507-H30274 | \$ 1,035.00 | 6% | \$980.20 |
| PW 4hr AHR | 95507-H30275 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30276 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30277 | \$ 1,035.00 | 6% | \$980.20 |
| PW 4hr AHR | 95507-H30278 | \$ 1,139.00 | 6% | \$1,078.69 |
| PW 4hr AHR | 95507-H30279 | \$ 1,035.00 | 6% | \$980.20 |
| PW 4hr AHR | 95507-H30280 | \$ 1,035.00 | 6% | \$980.20 |
| PW 4hr AHR | 95507-H30281 | \$ 1,208.00 | 6% | \$1,144.04 |
| PW 4hr AHR | 95507-H30282 | \$ 1,035.00 | 6% | \$980.20 |
| PW 4hr AHR | 95507-H30283 | \$ 689.00 | 6% | \$652.52 |
| PW 4hr AHR | 95507-H30284 | \$ 758.00 | 6% | \$717.86 |
| PW 4hr AHR | 95507-H30293 | \$ 4,124.00 | 6% | \$3,905.63 |
| PW 4hr AHR | 95507-H30296 | \$ 242.00 | 6% | \$229.19 |
| PW 4hr AHR | 95507-H30297 | \$ 226.00 | 6% | \$214.03 |
| PW 4hr AHR | 95507-H30298 | \$ 242.00 | 6% | \$229.19 |
| PW 4hr AHR | 95507-H30299 | \$ 226.00 | 6% | \$214.03 |
| PW 4hr AHR | 95507-H30381 | \$ 677.00 | 6% | \$641.15 |
| PW 4hr AHR | 95507-H30384 | \$ 539.00 | 6% | \$510.46 |
| PW 4hr AHR | 95507-H30391 | \$ 1,286.00 | 6% | \$1,217.91 |
| PW 4hr AHR | 95507-H30392 | \$ 1,286.00 | 6% | \$1,217.91 |
| PW 4hr AHR | 95507-H30393 | \$ 581.00 | 6% | \$550.24 |
| PW 4hr AHR | 95507-H30394 | \$ 2,502.00 | 6% | \$2,369.52 |
| PW 4hr AHR | 95507-H30395 | \$ 2,979.00 | 6% | \$2,821.26 |
| PW 4hr AHR | 95507-H30396 | \$ 2,714.00 | 6% | \$2,570.29 |
| PW 4hr AHR | 95507-H30397 | \$ 3,214.00 | 6% | \$3,043.82 |
| PW 4hr AHR | 95507-H30398 | \$ 591.00 | 6% | \$559.71 |
| PW 4hr AHR | 95507-H30400 | \$ 335.00 | 6% | \$317.26 |
| PW 4hr AHR | 95507-H30401 | \$ 454.00 | 6% | \$429.96 |
| PW 4hr AHR | 95507-H30402 | \$ 489.00 | 6% | \$463.11 |
| PW 4hr AHR | 95507-H30403 | \$ 721.00 | 6% | \$682.82 |
| PW 4hr AHR | 95507-H30434 | \$ 193.00 | 6% | \$182.78 |

| | | | | |
|------------|--------------|--------------|----|-------------|
| PW 4hr AHR | 95507-H30480 | \$ 843.00 | 6% | \$798.36 |
| PW 4hr AHR | 95507-H30495 | \$ 1,922.00 | 6% | \$1,820.23 |
| PW 4hr AHR | 95507-H30496 | \$ 1,886.00 | 6% | \$1,786.14 |
| PW 4hr AHR | 95507-H30497 | \$ 2,769.00 | 6% | \$2,622.38 |
| PW 4hr AHR | 95507-H30498 | \$ 2,714.00 | 6% | \$2,570.29 |
| PW 4hr AHR | 95507-H30499 | \$ 925.00 | 6% | \$876.02 |
| PW 4hr AHR | 95507-H30501 | \$ 2,714.00 | 6% | \$2,570.29 |
| PW 4hr AHR | 95507-H30502 | \$ 4,176.00 | 6% | \$3,954.88 |
| PW 4hr AHR | 95507-H30503 | \$ 925.00 | 6% | \$876.02 |
| PW 4hr AHR | 95507-H30505 | \$ 4,940.00 | 6% | \$4,678.43 |
| PW 4hr AHR | 95507-H30506 | \$ 6,710.00 | 6% | \$6,354.71 |
| PW 4hr AHR | 95507-H30509 | \$ 4,176.00 | 6% | \$3,954.88 |
| PW 4hr AHR | 95507-H30510 | \$ 4,940.00 | 6% | \$4,678.43 |
| PW 4hr AHR | 95507-H30511 | \$ 6,710.00 | 6% | \$6,354.71 |
| PW 4hr AHR | 95507-H30512 | \$ 925.00 | 6% | \$876.02 |
| PW 4hr AHR | 95507-H30513 | \$ 1,561.00 | 6% | \$1,478.35 |
| PW 4hr AHR | 95507-H30525 | \$ 6,710.00 | 6% | \$6,354.71 |
| PW 4hr AHR | 95507-H30526 | \$ 4,940.00 | 6% | \$4,678.43 |
| PW 4hr AHR | 95507-H30528 | \$ 7,791.00 | 6% | \$7,378.47 |
| PW 4hr AHR | 95507-H30531 | \$ 11,099.00 | 6% | \$10,511.31 |
| PW 4hr AHR | 95507-H30532 | \$ 11,099.00 | 6% | \$10,511.31 |
| PW 4hr AHR | 95507-H30534 | \$ 11,313.00 | 6% | \$10,713.98 |
| PW 4hr AHR | 95507-H30535 | \$ 12,070.00 | 6% | \$11,430.89 |
| PW 4hr AHR | 95507-H30536 | \$ 11,099.00 | 6% | \$10,511.31 |
| PW 4hr AHR | 95507-H30537 | \$ 12,070.00 | 6% | \$11,430.89 |
| PW 4hr AHR | 95507-H30538 | \$ 6,710.00 | 6% | \$6,354.71 |
| PW 4hr AHR | 95507-H30539 | \$ 12,645.00 | 6% | \$11,975.45 |
| PW 4hr AHR | 95507-H30540 | \$ 13,333.00 | 6% | \$12,627.02 |
| PW 4hr AHR | 95507-H30543 | \$ 907.00 | 6% | \$858.97 |
| PW 4hr AHR | 95507-H30544 | \$ 1,621.00 | 6% | \$1,535.17 |
| PW 4hr AHR | 95507-H30548 | \$ 907.00 | 6% | \$858.97 |
| PW 4hr AHR | 95507-H30549 | \$ 1,533.00 | 6% | \$1,451.83 |
| PW 4hr AHR | 95507-H30550 | \$ 1,533.00 | 6% | \$1,451.83 |
| PW 4hr AHR | 95507-H30552 | \$ 907.00 | 6% | \$858.97 |
| PW 4hr AHR | 95507-H30553 | \$ 1,448.00 | 6% | \$1,371.33 |
| PW 4hr AHR | 95507-H30569 | \$ 4,940.00 | 6% | \$4,678.43 |
| PW 4hr AHR | 95507-H30570 | \$ 5,916.00 | 6% | \$5,602.75 |
| PW 4hr AHR | 95507-H30571 | \$ 5,916.00 | 6% | \$5,602.75 |
| PW 4hr AHR | 95507-H30573 | \$ 4,940.00 | 6% | \$4,678.43 |
| PW 4hr AHR | 95507-H30574 | \$ 5,463.00 | 6% | \$5,173.73 |
| PW 4hr AHR | 95507-H30575 | \$ 3,411.00 | 6% | \$3,230.39 |
| PW 4hr AHR | 95507-H30576 | \$ 4,940.00 | 6% | \$4,678.43 |

| | | | | |
|----------------------------|--------------|--------------|----|-------------|
| PW 4hr AHR | 95507-H30577 | \$ 5,916.00 | 6% | \$5,602.75 |
| PW 4hr AHR | 95507-H30578 | \$ 5,916.00 | 6% | \$5,602.75 |
| PW 4hr AHR | 95507-H30587 | \$ 5,037.00 | 6% | \$4,770.29 |
| PW 4hr AHR | 95507-H30588 | \$ 3,477.00 | 6% | \$3,292.89 |
| PW 4hr AHR | 95507-H30589 | \$ 5,380.00 | 6% | \$5,095.13 |
| PW 4hr AHR | 95507-H30632 | \$ 129.00 | 6% | \$122.17 |
| PW 4hr AHR | 95507-H30633 | \$ 129.00 | 6% | \$122.17 |
| PW 4hr AHR | 95507-H30643 | \$ 8,487.00 | 6% | \$8,037.61 |
| PW 4hr AHR | 95507-H30706 | \$ 7,942.00 | 6% | \$7,521.47 |
| PW 4hr AHR | 95507-H30707 | \$ 4,940.00 | 6% | \$4,678.43 |
| PW 4hr AHR | 95507-H30724 | \$ 539.00 | 6% | \$510.46 |
| PW 4hr AHR | 95507-H30725 | \$ 1,886.00 | 6% | \$1,786.14 |
| PW 4hr AHR | 95507-H30726 | \$ 12,303.00 | 6% | \$11,651.56 |
| PW 4hr AHR | 95507-H30727 | \$ 13,079.00 | 6% | \$12,386.47 |
| PW 4hr AHR | 95507-H30730 | \$ 65.00 | 6% | \$61.56 |
| PW 4hr AHR | 95507-H30731 | \$ 65.00 | 6% | \$61.56 |
| PW 4HR AHR 30732 | 95507-H30732 | \$ 2,146.00 | 6% | \$2,032.37 |
| PW 4HR AHR SKL8008-0810-F8 | 95507-H30733 | \$ 11,515.00 | 6% | \$10,905.28 |
| PW 4HR AHR STL2006-0850 | 95507-H30734 | \$ 8,789.00 | 6% | \$8,323.62 |
| PW 4HR AHR SGL2001-0850 | 95507-H30735 | \$ 10,238.00 | 6% | \$9,695.90 |
| PW 4HR AHR SOK2209-0204 | 95507-H30736 | \$ 1,602.00 | 6% | \$1,517.17 |
| PW 4HR AHR H30738 | 95507-H30738 | \$ 50.00 | 6% | \$47.35 |
| PW 4HR AHR -H30739 | 95507-H30739 | \$ 1,720.00 | 6% | \$1,628.93 |
| PW 4HR AHR -H30740 | 95507-H30740 | \$ 998.00 | 6% | \$945.16 |
| PW 4HR AHR -H30741 | 95507-H30741 | \$ 1,817.00 | 6% | \$1,720.79 |
| PW 4HR AHR -H30742 | 95507-H30742 | \$ 1,615.00 | 6% | \$1,529.49 |
| PW 4HR AHR -H30743 | 95507-H30743 | \$ 1,720.00 | 6% | \$1,628.93 |
| PW 4HR AHR -H30744 | 95507-H30744 | \$ 998.00 | 6% | \$945.16 |
| PW 4HR AHR -H30745 | 95507-H30745 | \$ 1,017.00 | 6% | \$963.15 |
| PW 4HR AHR -H30746 | 95507-H30746 | \$ 1,798.00 | 6% | \$1,702.80 |
| PW 4HR AHR -H30747 | 95507-H30747 | \$ 3,584.00 | 6% | \$3,394.23 |
| PW 4HR AHR -H30748 | 95507-H30748 | \$ 5,287.00 | 6% | \$5,007.05 |
| PW 4HR AHR -H30749 | 95507-H30749 | \$ 11,884.00 | 6% | \$11,254.74 |
| PW 4HR AHR -H30750 | 95507-H30750 | \$ 11,884.00 | 6% | \$11,254.74 |
| PW 4HR AHR -H30751 | 95507-H30751 | \$ 7,052.00 | 6% | \$6,678.60 |
| PW 4HR AHR -H30754 | 95507-H30754 | \$ 11,884.00 | 6% | \$11,254.74 |
| PW 4HR AHR -H30755 | 95507-H30755 | \$ 12,912.00 | 6% | \$12,228.31 |
| PW 4HR AHR -H30756 | 95507-H30756 | \$ 11,884.00 | 6% | \$11,254.74 |
| PW 4HR AHR -H30757 | 95507-H30757 | \$ 5,287.00 | 6% | \$5,007.05 |
| PW 4HR AHR -H30758 | 95507-H30758 | \$ 9,406.00 | 6% | \$8,907.95 |
| PW 4HR AHR -H30759 | 95507-H30759 | \$ 10,755.00 | 6% | \$10,185.52 |

| | | | | |
|--------------------|--------------|--------------|----|--------------------|
| PW 4HR AHR -H30760 | 95507-H30760 | \$ 12,094.00 | 6% | <i>\$11,453.62</i> |
| PW 4HR AHR -H30761 | 95507-H30761 | \$ 5,287.00 | 6% | <i>\$5,007.05</i> |
| PW 4HR AHR -H30762 | 95507-H30762 | \$ 12,912.00 | 6% | <i>\$12,228.31</i> |
| PW 4HR AHR -H30763 | 95507-H30763 | \$ 12,912.00 | 6% | <i>\$12,228.31</i> |
| PW 4HR AHR -H30764 | 95507-H30764 | \$ 8,184.00 | 6% | <i>\$7,750.66</i> |
| PW 4HR AHR -H30765 | 95507-H30765 | \$ 7,187.00 | 6% | <i>\$6,806.45</i> |
| PW 4HR AHR -H30766 | 95507-H30766 | \$ 14,002.00 | 6% | <i>\$13,260.59</i> |
| PW 4HR AHR -H30767 | 95507-H30767 | \$ 8,184.00 | 6% | <i>\$7,750.66</i> |
| PW 4HR AHR H30769 | 95507-H30769 | \$ 2,768.00 | 6% | <i>\$2,621.43</i> |
| PW 4HR AHR H30773 | 95507-H30773 | \$ 175.00 | 6% | <i>\$165.73</i> |
| PW 4HR AHR H30774 | 95507-H30774 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30775 | 95507-H30775 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30776 | 95507-H30776 | \$ 175.00 | 6% | <i>\$165.73</i> |
| PW 4HR AHR H30777 | 95507-H30777 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30778 | 95507-H30778 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30779 | 95507-H30779 | \$ 99.00 | 6% | <i>\$93.76</i> |
| PW 4HR AHR H30780 | 95507-H30780 | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW 4HR AHR H30781 | 95507-H30781 | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW 4HR AHR H30782 | 95507-H30782 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR H30783 | 95507-H30783 | \$ 85.00 | 6% | <i>\$80.50</i> |
| PW 4HR AHR H30784 | 95507-H30784 | \$ 85.00 | 6% | <i>\$80.50</i> |
| PW 4HR AHR H30785 | 95507-H30785 | \$ 99.00 | 6% | <i>\$93.76</i> |
| PW 4HR AHR H30786 | 95507-H30786 | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW 4HR AHR H30787 | 95507-H30787 | \$ 99.00 | 6% | <i>\$93.76</i> |
| PW 4HR AHR H30788 | 95507-H30788 | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW 4HR AHR H30789 | 95507-H30789 | \$ 85.00 | 6% | <i>\$80.50</i> |
| PW 4HR AHR H30790 | 95507-H30790 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW 4HR AHR H30791 | 95507-H30791 | \$ 85.00 | 6% | <i>\$80.50</i> |
| PW 4HR AHR H30793 | 95507-H30793 | \$ 79.00 | 6% | <i>\$74.82</i> |
| PW 4HR AHR H30794 | 95507-H30794 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR H30795 | 95507-H30795 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR AHR H30796 | 95507-H30796 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PW 4HR AHR H30797 | 95507-H30797 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR AHR H30798 | 95507-H30798 | \$ 72.00 | 6% | <i>\$68.19</i> |
| PW 4HR AHR H30799 | 95507-H30799 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR AHR H30800 | 95507-H30800 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW 4HR AHR H30801 | 95507-H30801 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PW 4HR AHR H30802 | 95507-H30802 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW 4HR AHR H30803 | 95507-H30803 | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW 4HR AHR H30804 | 95507-H30804 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR AHR H30805 | 95507-H30805 | \$ 72.00 | 6% | <i>\$68.19</i> |
| PW 4HR AHR H30806 | 95507-H30806 | \$ 119.00 | 6% | <i>\$112.70</i> |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW 4HR AHR H30807 | 95507-H30807 | \$ 75.00 | 6% | \$71.03 |
| PW 4HR AHR H30808 | 95507-H30808 | \$ 50.00 | 6% | \$47.35 |
| PW 4HR AHR H30809 | 95507-H30809 | \$ 72.00 | 6% | \$68.19 |
| PW 4HR AHR H30810 | 95507-H30810 | \$ 50.00 | 6% | \$47.35 |
| PW 4HR AHR H30811 | 95507-H30811 | \$ 119.00 | 6% | \$112.70 |
| PW 4HR AHR H30812 | 95507-H30812 | \$ 72.00 | 6% | \$68.19 |
| PW 4HR AHR H30813 | 95507-H30813 | \$ 84.00 | 6% | \$79.55 |
| PW 4HR AHR H30814 | 95507-H30814 | \$ 119.00 | 6% | \$112.70 |
| PW 4HR AHR H30815 | 95507-H30815 | \$ 50.00 | 6% | \$47.35 |
| PW 4HR AHR H30816 | 95507-H30816 | \$ 50.00 | 6% | \$47.35 |
| PW 4HR AHR H30817 | 95507-H30817 | \$ 119.00 | 6% | \$112.70 |
| PW 4HR AHR H30818 | 95507-H30818 | \$ 72.00 | 6% | \$68.19 |
| PW 4HR AHR H30819 | 95507-H30819 | \$ 119.00 | 6% | \$112.70 |
| PW 4HR AHR H30820 | 95507-H30820 | \$ 50.00 | 6% | \$47.35 |
| PW 4HR AHR H30821 | 95507-H30821 | \$ 84.00 | 6% | \$79.55 |
| PW 4HR AHR H30822 | 95507-H30822 | \$ 75.00 | 6% | \$71.03 |
| PW 4HR AHR H30823 | 95507-H30823 | \$ 84.00 | 6% | \$79.55 |
| PW 4HR AHR H30824 | 95507-H30824 | \$ 72.00 | 6% | \$68.19 |
| PW 4HR AHR H30825 | 95507-H30825 | \$ 84.00 | 6% | \$79.55 |
| PW 4HR AHR H30826 | 95507-H30826 | \$ 119.00 | 6% | \$112.70 |
| PW 4HR AHR H30827 | 95507-H30827 | \$ 75.00 | 6% | \$71.03 |
| PW 4HR AHR H30828 | 95507-H30828 | \$ 75.00 | 6% | \$71.03 |
| PW 4HR AHR H30829 | 95507-H30829 | \$ 84.00 | 6% | \$79.55 |
| PW 4HR AHR H30830 | 95507-H30830 | \$ 119.00 | 6% | \$112.70 |
| PW 4HR AHR H30831 | 95507-H30831 | \$ 72.00 | 6% | \$68.19 |
| PW 4HR AHR H30832 | 95507-H30832 | \$ 1,533.00 | 6% | \$1,451.83 |
| PW 4HR AHR H30833 | 95507-H30833 | \$ 413.00 | 6% | \$391.13 |
| PW 4HR AHR H30834 | 95507-H30834 | \$ 413.00 | 6% | \$391.13 |
| PW 4HR AHR H30836 | 95507-H30836 | \$ 1,533.00 | 6% | \$1,451.83 |
| PW 4HR AHR H30838 | 95507-H30838 | \$ 55.00 | 6% | \$52.09 |
| PW 4HR AHR H30839 | 95507-H30839 | \$ 79.00 | 6% | \$74.82 |
| PW 4HR AHR H30840 | 95507-H30840 | \$ 79.00 | 6% | \$74.82 |
| PW 4HR AHR H30841 | 95507-H30841 | \$ 79.00 | 6% | \$74.82 |
| PW 4HR AHR H30842 | 95507-H30842 | \$ 79.00 | 6% | \$74.82 |
| PW 4HR AHR H30843 | 95507-H30843 | \$ 79.00 | 6% | \$74.82 |
| PW 4HR AHR H30844 | 95507-H30844 | \$ 79.00 | 6% | \$74.82 |
| PW 4HR AHR H30845 | 95507-H30845 | \$ 79.00 | 6% | \$74.82 |
| PW 4HR AHR H30846 | 95507-H30846 | \$ 97.00 | 6% | \$91.86 |
| PW 4HR AHR H30847 | 95507-H30847 | \$ 97.00 | 6% | \$91.86 |
| PW 4HR AHR H30848 | 95507-H30848 | \$ 97.00 | 6% | \$91.86 |
| PW 4HR AHR H30849 | 95507-H30849 | \$ 97.00 | 6% | \$91.86 |
| PW 4HR AHR H30850 | 95507-H30850 | \$ 97.00 | 6% | \$91.86 |

| | | | | |
|-------------------|--------------|-------------|----|-------------------|
| PW 4HR AHR H30851 | 95507-H30851 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR H30852 | 95507-H30852 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR AHR H30853 | 95507-H30853 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30854 | 95507-H30854 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30855 | 95507-H30855 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30856 | 95507-H30856 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30857 | 95507-H30857 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30858 | 95507-H30858 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30859 | 95507-H30859 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30860 | 95507-H30860 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4HR AHR H30866 | 95507-H30866 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PW 4HR AHR H30867 | 95507-H30867 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW 4HR AHR H30868 | 95507-H30868 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW 4HR AHR H30869 | 95507-H30869 | \$ 290.00 | 6% | <i>\$274.64</i> |
| PW 4HR AHR H30870 | 95507-H30870 | \$ 290.00 | 6% | <i>\$274.64</i> |
| PW 4HR AHR H30871 | 95507-H30871 | \$ 266.00 | 6% | <i>\$251.92</i> |
| PW 4HR AHR H30872 | 95507-H30872 | \$ 147.00 | 6% | <i>\$139.22</i> |
| PW 4HR AHR H30873 | 95507-H30873 | \$ 147.00 | 6% | <i>\$139.22</i> |
| PW 4HR AHR H30874 | 95507-H30874 | \$ 147.00 | 6% | <i>\$139.22</i> |
| PW 4HR AHR H30875 | 95507-H30875 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PW 4HR AHR H30876 | 95507-H30876 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PW 4HR AHR H30877 | 95507-H30877 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PW 4HR AHR H30878 | 95507-H30878 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PW 4HR AHR H30891 | 95507-H30891 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR AHR H30892 | 95507-H30892 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR AHR H30893 | 95507-H30893 | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR H30894 | 95507-H30894 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PW 4HR AHR H30895 | 95507-H30895 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30896 | 95507-H30896 | \$ 433.00 | 6% | <i>\$410.07</i> |
| PW 4HR AHR H30897 | 95507-H30897 | \$ 757.00 | 6% | <i>\$716.92</i> |
| PW 4HR AHR H30898 | 95507-H30898 | \$ 852.00 | 6% | <i>\$806.89</i> |
| PW 4HR AHR H30900 | 95507-H30900 | \$ 2,574.00 | 6% | <i>\$2,437.71</i> |
| PW 4HR AHR H30901 | 95507-H30901 | \$ 3,426.00 | 6% | <i>\$3,244.59</i> |
| PW 4HR AHR H30902 | 95507-H30902 | \$ 3,597.00 | 6% | <i>\$3,406.54</i> |
| PW 4HR AHR H30904 | 95507-H30904 | \$ 5,290.00 | 6% | <i>\$5,009.89</i> |
| PW 4HR AHR H30905 | 95507-H30905 | \$ 7,562.00 | 6% | <i>\$7,161.59</i> |
| PW 4HR AHR H30906 | 95507-H30906 | \$ 207.00 | 6% | <i>\$196.04</i> |
| PW 4HR AHR H30912 | 95507-H30912 | \$ 568.00 | 6% | <i>\$537.92</i> |
| PW 4HR AHR H30913 | 95507-H30913 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW 4HR AHR H30914 | 95507-H30914 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PW 4HR AHR H30915 | 95507-H30915 | \$ 54.00 | 6% | <i>\$51.14</i> |
| PW 4HR AHR H30916 | 95507-H30916 | \$ 54.00 | 6% | <i>\$51.14</i> |

| | | | | |
|-------------------|--------------|-------------|----|-------------------|
| PW 4HR AHR H30917 | 95507-H30917 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW 4HR AHR H30918 | 95507-H30918 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW 4HR AHR H30946 | 95507-H30946 | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW 4HR AHR H30948 | 95507-H30948 | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW 4HR AHR H30950 | 95507-H30950 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW 4HR AHR H30951 | 95507-H30951 | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW 4HR AHR H30952 | 95507-H30952 | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW 4HR AHR H30966 | 95507-H30966 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30967 | 95507-H30967 | \$ 175.00 | 6% | <i>\$165.73</i> |
| PW 4HR AHR H30968 | 95507-H30968 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30969 | 95507-H30969 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PW 4HR AHR H30970 | 95507-H30970 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR AHR H30971 | 95507-H30971 | \$ 113.00 | 6% | <i>\$107.02</i> |
| PW 4HR AHR H30972 | 95507-H30972 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR AHR H30973 | 95507-H30973 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30974 | 95507-H30974 | \$ 164.00 | 6% | <i>\$155.32</i> |
| PW 4HR AHR H30975 | 95507-H30975 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30976 | 95507-H30976 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30977 | 95507-H30977 | \$ 164.00 | 6% | <i>\$155.32</i> |
| PW 4HR AHR H30978 | 95507-H30978 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PW 4HR AHR H30995 | 95507-H30995 | \$ 2,069.00 | 6% | <i>\$1,959.45</i> |
| PW 4HR AHR H31030 | 95507-H31030 | \$ 6,678.00 | 6% | <i>\$6,324.40</i> |
| PW 4HR AHR H31031 | 95507-H31031 | \$ 530.00 | 6% | <i>\$501.94</i> |
| PW 4HR AHR H31033 | 95507-H31033 | \$ 4,044.00 | 6% | <i>\$3,829.87</i> |
| PW 4HR AHR H31034 | 95507-H31034 | \$ 2,247.00 | 6% | <i>\$2,128.02</i> |
| PW 4HR AHR H31035 | 95507-H31035 | \$ 2,357.00 | 6% | <i>\$2,232.20</i> |
| PW 4HR AHR H31036 | 95507-H31036 | \$ 4,711.00 | 6% | <i>\$4,461.55</i> |
| PW 4HR AHR H31040 | 95507-H31040 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR AHR H31041 | 95507-H31041 | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW 4HR AHR H31042 | 95507-H31042 | \$ 263.00 | 6% | <i>\$249.07</i> |
| PW 4HR AHR H31043 | 95507-H31043 | \$ 190.00 | 6% | <i>\$179.94</i> |
| PW 4HR AHR H31047 | 95507-H31047 | \$ 175.00 | 6% | <i>\$165.73</i> |
| PW 4HR AHR H31049 | 95507-H31049 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |
| PW 4HR AHR H31060 | 95507-H31060 | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW 4HR AHR H31062 | 95507-H31062 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PW 4HR AHR H31066 | 95507-H31066 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW 4HR AHR H31068 | 95507-H31068 | \$ 74.00 | 6% | <i>\$70.08</i> |
| PW 4HR AHR H31076 | 95507-H31076 | \$ 256.00 | 6% | <i>\$242.44</i> |
| PW 4HR AHR H31077 | 95507-H31077 | \$ 263.00 | 6% | <i>\$249.07</i> |
| PW 4HR AHR H31078 | 95507-H31078 | \$ 268.00 | 6% | <i>\$253.81</i> |
| PW 4HR AHR H31103 | 95507-H31103 | \$ 4,315.00 | 6% | <i>\$4,086.52</i> |
| PW 4HR AHR H31119 | 95507-H31119 | \$ 98.00 | 6% | <i>\$92.81</i> |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW 4HR AHR H31124 | 95507-H31124 | \$ 103.00 | 6% | \$97.55 |
| PW 4HR AHR H31127 | 95507-H31127 | \$ 175.00 | 6% | \$165.73 |
| PW 4HR AHR H31132 | 95507-H31132 | \$ 165.00 | 6% | \$156.26 |
| PW 4HR AHR H31134 | 95507-H31134 | \$ 51.00 | 6% | \$48.30 |
| PW 4HR AHR H31135 | 95507-H31135 | \$ 59.00 | 6% | \$55.88 |
| PW 4HR AHR H31136 | 95507-H31136 | \$ 88.00 | 6% | \$83.34 |
| PW 4HR AHR H31137 | 95507-H31137 | \$ 80.00 | 6% | \$75.76 |
| PW 4HR AHR H31197 | 95507-H31197 | \$ 96.00 | 6% | \$90.92 |
| PW 4HR AHR H31198 | 95507-H31198 | \$ 96.00 | 6% | \$90.92 |
| PW 4HR AHR H31199 | 95507-H31199 | \$ 96.00 | 6% | \$90.92 |
| PW 4HR AHR H31200 | 95507-H31200 | \$ 96.00 | 6% | \$90.92 |
| PW 4HR AHR H31201 | 95507-H31201 | \$ 96.00 | 6% | \$90.92 |
| PW 4HR AHR H31202 | 95507-H31202 | \$ 96.00 | 6% | \$90.92 |
| PW 4HR AHR H31203 | 95507-H31203 | \$ 111.00 | 6% | \$105.12 |
| PW 4HR AHR H31204 | 95507-H31204 | \$ 99.00 | 6% | \$93.76 |
| PW 4HR AHR H31205 | 95507-H31205 | \$ 111.00 | 6% | \$105.12 |
| PW 4HR AHR H31206 | 95507-H31206 | \$ 111.00 | 6% | \$105.12 |
| PW 4HR AHR H31207 | 95507-H31207 | \$ 99.00 | 6% | \$93.76 |
| PW 4HR AHR H31208 | 95507-H31208 | \$ 111.00 | 6% | \$105.12 |
| PW 4HR AHR H31210 | 95507-H31210 | \$ 207.00 | 6% | \$196.04 |
| PW 4HR AHR H31335 | 95507-H31335 | \$ 113.00 | 6% | \$107.02 |
| PW 4HR AHR H31337 | 95507-H31337 | \$ 8,915.00 | 6% | \$8,442.95 |
| PW 4HR AHR H31338 | 95507-H31338 | \$ 8,915.00 | 6% | \$8,442.95 |
| PW 4HR AHR H31339 | 95507-H31339 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H31340 | 95507-H31340 | \$ 3,093.00 | 6% | \$2,929.23 |
| PW 4HR AHR H31341 | 95507-H31341 | \$ 4,584.00 | 6% | \$4,341.28 |
| PW 4HR AHR H31342 | 95507-H31342 | \$ 1,444.00 | 6% | \$1,367.54 |
| PW 4HR AHR H31343 | 95507-H31343 | \$ 2,133.00 | 6% | \$2,020.06 |
| PW 4HR AHR H31344 | 95507-H31344 | \$ 2,133.00 | 6% | \$2,020.06 |
| PW 4HR AHR H31345 | 95507-H31345 | \$ 2,133.00 | 6% | \$2,020.06 |
| PW 4HR AHR H31346 | 95507-H31346 | \$ 2,133.00 | 6% | \$2,020.06 |
| PW 4HR AHR H31348 | 95507-H31348 | \$ 164.00 | 6% | \$155.32 |
| PW 4HR AHR H31349 | 95507-H31349 | \$ 164.00 | 6% | \$155.32 |
| PW 4HR AHR H31350 | 95507-H31350 | \$ 266.00 | 6% | \$251.92 |
| PW 4HR AHR H31351 | 95507-H31351 | \$ 99.00 | 6% | \$93.76 |
| PW 4HR AHR H31352 | 95507-H31352 | \$ 99.00 | 6% | \$93.76 |
| PW 4HR AHR H31353 | 95507-H31353 | \$ 83.00 | 6% | \$78.61 |
| PW 4HR AHR H31354 | 95507-H31354 | \$ 83.00 | 6% | \$78.61 |
| PW 4HR AHR H31355 | 95507-H31355 | \$ 175.00 | 6% | \$165.73 |
| PW 4HR AHR H31356 | 95507-H31356 | \$ 175.00 | 6% | \$165.73 |
| PW 4HR AHR H31357 | 95507-H31357 | \$ 175.00 | 6% | \$165.73 |
| PW 4HR AHR H31358 | 95507-H31358 | \$ 61.00 | 6% | \$57.77 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PW 4HR AHR H31359 | 95507-H31359 | \$ 69.00 | 6% | \$65.35 |
| PW 4HR AHR H31360 | 95507-H31360 | \$ 58.00 | 6% | \$54.93 |
| PW 4HR AHR H31361 | 95507-H31361 | \$ 2,917.00 | 6% | \$2,762.54 |
| PW 4HR AHR H31362 | 95507-H31362 | \$ 22,092.00 | 6% | \$20,922.23 |
| PW 4HR AHR H31363 | 95507-H31363 | \$ 22,092.00 | 6% | \$20,922.23 |
| PW 4HR AHR H31364 | 95507-H31364 | \$ 7,720.00 | 6% | \$7,311.23 |
| PW 4HR AHR H31365 | 95507-H31365 | \$ 7,720.00 | 6% | \$7,311.23 |
| PW 4HR AHR H31366 | 95507-H31366 | \$ 10,706.00 | 6% | \$10,139.12 |
| PW 4HR AHR H31367 | 95507-H31367 | \$ 10,706.00 | 6% | \$10,139.12 |
| PW 4HR AHR H31369 | 95507-H31369 | \$ 99.00 | 6% | \$93.76 |
| PW 4HR AHR H31370 | 95507-H31370 | \$ 99.00 | 6% | \$93.76 |
| PW 4HR AHR H31393 | 95507-H31393 | \$ 57.00 | 6% | \$53.98 |
| PW 4HR AHR H32010 | 95507-H32010 | \$ 318.00 | 6% | \$301.16 |
| PW 4HR AHR H32011 | 95507-H32011 | \$ 318.00 | 6% | \$301.16 |
| PW 4HR AHR H32012 | 95507-H32012 | \$ 2,653.00 | 6% | \$2,512.52 |
| PW 4HR AHR H32013 | 95507-H32013 | \$ 2,653.00 | 6% | \$2,512.52 |
| PW 4HR AHR H32014 | 95507-H32014 | \$ 2,653.00 | 6% | \$2,512.52 |
| PW 4HR AHR H32015 | 95507-H32015 | \$ 2,653.00 | 6% | \$2,512.52 |
| PW 4HR AHR H32016 | 95507-H32016 | \$ 2,309.00 | 6% | \$2,186.74 |
| PW 4HR AHR H32017 | 95507-H32017 | \$ 2,309.00 | 6% | \$2,186.74 |
| PW 4HR AHR H32018 | 95507-H32018 | \$ 2,309.00 | 6% | \$2,186.74 |
| PW 4HR AHR H32019 | 95507-H32019 | \$ 2,309.00 | 6% | \$2,186.74 |
| PW 4HR AHR H32020 | 95507-H32020 | \$ 23,168.00 | 6% | \$21,941.25 |
| PW 4HR AHR H32021 | 95507-H32021 | \$ 23,168.00 | 6% | \$21,941.25 |
| PW 4HR AHR H32022 | 95507-H32022 | \$ 23,168.00 | 6% | \$21,941.25 |
| PW 4HR AHR H32023 | 95507-H32023 | \$ 23,168.00 | 6% | \$21,941.25 |
| PW 4HR AHR H32028 | 95507-H32028 | \$ 44,675.00 | 6% | \$42,309.46 |
| PW 4HR AHR H32029 | 95507-H32029 | \$ 44,675.00 | 6% | \$42,309.46 |
| PW 4HR AHR H32030 | 95507-H32030 | \$ 46,853.00 | 6% | \$44,372.13 |
| PW 4HR AHR H32031 | 95507-H32031 | \$ 46,853.00 | 6% | \$44,372.13 |
| PW 4HR AHR H32032 | 95507-H32032 | \$ 46,853.00 | 6% | \$44,372.13 |
| PW 4HR AHR H32033 | 95507-H32033 | \$ 46,853.00 | 6% | \$44,372.13 |
| PW 4HR AHR H32038 | 95507-H32038 | \$ 8,097.00 | 6% | \$7,668.26 |
| PW 4HR AHR H32039 | 95507-H32039 | \$ 8,097.00 | 6% | \$7,668.26 |
| PW 4HR AHR H32040 | 95507-H32040 | \$ 8,097.00 | 6% | \$7,668.26 |
| PW 4HR AHR H32041 | 95507-H32041 | \$ 8,097.00 | 6% | \$7,668.26 |
| PW 4HR AHR H32046 | 95507-H32046 | \$ 11,227.00 | 6% | \$10,632.53 |
| PW 4HR AHR H32047 | 95507-H32047 | \$ 11,227.00 | 6% | \$10,632.53 |
| PW 4HR AHR H32048 | 95507-H32048 | \$ 11,227.00 | 6% | \$10,632.53 |
| PW 4HR AHR H32049 | 95507-H32049 | \$ 11,227.00 | 6% | \$10,632.53 |
| PW 4HR AHR H32054 | 95507-H32054 | \$ 8,097.00 | 6% | \$7,668.26 |
| PW 4HR AHR H32055 | 95507-H32055 | \$ 11,227.00 | 6% | \$10,632.53 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PW 4HR AHR H32056 | 95507-H32056 | \$ 3,146.00 | 6% | \$2,979.42 |
| PW 4HR AHR H32057 | 95507-H32057 | \$ 3,146.00 | 6% | \$2,979.42 |
| PW 4HR AHR H32058 | 95507-H32058 | \$ 3,146.00 | 6% | \$2,979.42 |
| PW 4HR AHR H32059 | 95507-H32059 | \$ 3,146.00 | 6% | \$2,979.42 |
| PW 4HR AHR H32060 | 95507-H32060 | \$ 3,140.00 | 6% | \$2,973.74 |
| PW 4HR AHR H32061 | 95507-H32061 | \$ 3,297.00 | 6% | \$3,122.42 |
| PW 4HR AHR H32062 | 95507-H32062 | \$ 3,170.00 | 6% | \$3,002.15 |
| PW 4HR AHR H32063 | 95507-H32063 | \$ 3,143.00 | 6% | \$2,976.58 |
| PW 4HR AHR H32064 | 95507-H32064 | \$ 3,170.00 | 6% | \$3,002.15 |
| PW 4HR AHR H32065 | 95507-H32065 | \$ 3,572.00 | 6% | \$3,382.86 |
| PW 4HR AHR H32066 | 95507-H32066 | \$ 3,572.00 | 6% | \$3,382.86 |
| PW 4HR AHR H32067 | 95507-H32067 | \$ 3,572.00 | 6% | \$3,382.86 |
| PW 4HR AHR H32068 | 95507-H32068 | \$ 3,572.00 | 6% | \$3,382.86 |
| PW 4HR AHR H32069 | 95507-H32069 | \$ 4,444.00 | 6% | \$4,208.69 |
| PW 4HR AHR H32070 | 95507-H32070 | \$ 4,444.00 | 6% | \$4,208.69 |
| PW 4HR AHR H32071 | 95507-H32071 | \$ 4,444.00 | 6% | \$4,208.69 |
| PW 4HR AHR H32072 | 95507-H32072 | \$ 4,444.00 | 6% | \$4,208.69 |
| PW 4HR AHR H32073 | 95507-H32073 | \$ 32,912.00 | 6% | \$31,169.31 |
| PW 4HR AHR H32074 | 95507-H32074 | \$ 32,912.00 | 6% | \$31,169.31 |
| PW 4HR AHR H32075 | 95507-H32075 | \$ 44,721.00 | 6% | \$42,353.02 |
| PW 4HR AHR H32076 | 95507-H32076 | \$ 44,721.00 | 6% | \$42,353.02 |
| PW 4HR AHR H32101 | 95507-H32101 | \$ 1,436.00 | 6% | \$1,359.96 |
| PW 4HR AHR H32102 | 95507-H32102 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H32103 | 95507-H32103 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H32104 | 95507-H32104 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H32105 | 95507-H32105 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32106 | 95507-H32106 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32107 | 95507-H32107 | \$ 7,855.00 | 6% | \$7,439.08 |
| PW 4HR AHR H32108 | 95507-H32108 | \$ 7,855.00 | 6% | \$7,439.08 |
| PW 4HR AHR H32109 | 95507-H32109 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32110 | 95507-H32110 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32111 | 95507-H32111 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H32112 | 95507-H32112 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H32113 | 95507-H32113 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H32114 | 95507-H32114 | \$ 1,451.00 | 6% | \$1,374.17 |
| PW 4HR AHR H32115 | 95507-H32115 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32116 | 95507-H32116 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32117 | 95507-H32117 | \$ 1,358.00 | 6% | \$1,286.09 |
| PW 4HR AHR H32118 | 95507-H32118 | \$ 1,358.00 | 6% | \$1,286.09 |
| PW 4HR AHR H32119 | 95507-H32119 | \$ 1,358.00 | 6% | \$1,286.09 |
| PW 4HR AHR H32120 | 95507-H32120 | \$ 1,358.00 | 6% | \$1,286.09 |
| PW 4HR AHR H32121 | 95507-H32121 | \$ 7,855.00 | 6% | \$7,439.08 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PW 4HR AHR H32122 | 95507-H32122 | \$ 7,855.00 | 6% | \$7,439.08 |
| PW 4HR AHR H32123 | 95507-H32123 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32124 | 95507-H32124 | \$ 2,900.00 | 6% | \$2,746.45 |
| PW 4HR AHR H32125 | 95507-H32125 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32126 | 95507-H32126 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32127 | 95507-H32127 | \$ 3,375.00 | 6% | \$3,196.29 |
| PW 4HR AHR H32128 | 95507-H32128 | \$ 3,375.00 | 6% | \$3,196.29 |
| PW 4HR AHR H32129 | 95507-H32129 | \$ 3,375.00 | 6% | \$3,196.29 |
| PW 4HR AHR H32130 | 95507-H32130 | \$ 3,375.00 | 6% | \$3,196.29 |
| PW 4HR AHR H32131 | 95507-H32131 | \$ 3,375.00 | 6% | \$3,196.29 |
| PW 4HR AHR H32132 | 95507-H32132 | \$ 3,375.00 | 6% | \$3,196.29 |
| PW 4HR AHR H32133 | 95507-H32133 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32134 | 95507-H32134 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32135 | 95507-H32135 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32136 | 95507-H32136 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32137 | 95507-H32137 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32138 | 95507-H32138 | \$ 2,869.00 | 6% | \$2,717.09 |
| PW 4HR AHR H32139 | 95507-H32139 | \$ 12,132.00 | 6% | \$11,489.61 |
| PW 4HR AHR H32140 | 95507-H32140 | \$ 12,132.00 | 6% | \$11,489.61 |
| PW 4HR AHR H32141 | 95507-H32141 | \$ 13,998.00 | 6% | \$13,256.81 |
| PW 4HR AHR H32142 | 95507-H32142 | \$ 13,998.00 | 6% | \$13,256.81 |
| PW 4HR AHR H32146 | 95507-H32146 | \$ 1,238.00 | 6% | \$1,172.45 |
| PW 4HR AHR H32147 | 95507-H32147 | \$ 1,238.00 | 6% | \$1,172.45 |
| PW 4HR AHR H32148 | 95507-H32148 | \$ 2,550.00 | 6% | \$2,414.98 |
| PW 4HR AHR H32149 | 95507-H32149 | \$ 2,550.00 | 6% | \$2,414.98 |
| PW 4HR AHR H32150 | 95507-H32150 | \$ 1,309.00 | 6% | \$1,239.69 |
| PW 4HR AHR H32152 | 95507-H32152 | \$ 593.00 | 6% | \$561.60 |
| PW 4HR AHR H32169 | 95507-H32169 | \$ 1,467.00 | 6% | \$1,389.32 |
| PW 4HR AHR H32170 | 95507-H32170 | \$ 1,467.00 | 6% | \$1,389.32 |
| PW 4HR AHR H32171 | 95507-H32171 | \$ 1,374.00 | 6% | \$1,301.25 |
| PW 4HR AHR H32172 | 95507-H32172 | \$ 1,374.00 | 6% | \$1,301.25 |
| PW 4HR AHR H32173 | 95507-H32173 | \$ 3,670.00 | 6% | \$3,475.67 |
| PW 4HR AHR H32174 | 95507-H32174 | \$ 3,670.00 | 6% | \$3,475.67 |
| PW 4HR AHR H32175 | 95507-H32175 | \$ 3,119.00 | 6% | \$2,953.85 |
| PW 4HR AHR H32176 | 95507-H32176 | \$ 3,119.00 | 6% | \$2,953.85 |
| PW 4HR AHR H32177 | 95507-H32177 | \$ 14,300.00 | 6% | \$13,542.82 |
| PW 4HR AHR H32178 | 95507-H32178 | \$ 16,502.00 | 6% | \$15,628.22 |
| PW 4HR AHR H34008 | 95507-H34008 | \$ 62.00 | 6% | \$58.72 |
| PW 4HR AHR H34009 | 95507-H34009 | \$ 171.00 | 6% | \$161.95 |
| PW 4HR AHR H34010 | 95507-H34010 | \$ 70.00 | 6% | \$66.29 |
| PW 4HR AHR H34011 | 95507-H34011 | \$ 154.00 | 6% | \$145.85 |
| PW 4HR AHR H34012 | 95507-H34012 | \$ 277.00 | 6% | \$262.33 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW 4HR AHR H34013 | 95507-H34013 | \$ 109.00 | 6% | \$103.23 |
| PW 4HR AHR H34014 | 95507-H34014 | \$ 171.00 | 6% | \$161.95 |
| PW 4HR AHR H34015 | 95507-H34015 | \$ 87.00 | 6% | \$82.39 |
| PW 4HR AHR H34016 | 95507-H34016 | \$ 195.00 | 6% | \$184.67 |
| PW 4HR AHR H34017 | 95507-H34017 | \$ 326.00 | 6% | \$308.74 |
| PW 4HR AHR H34018 | 95507-H34018 | \$ 136.00 | 6% | \$128.80 |
| PW 4HR AHR H34019 | 95507-H34019 | \$ 136.00 | 6% | \$128.80 |
| PW 4HR AHR H34020 | 95507-H34020 | \$ 136.00 | 6% | \$128.80 |
| PW 4HR AHR H34021 | 95507-H34021 | \$ 136.00 | 6% | \$128.80 |
| PW 4HR AHR H34048 | 95507-H34048 | \$ 546.00 | 6% | \$517.09 |
| PW 4HR AHR H34049 | 95507-H34049 | \$ 546.00 | 6% | \$517.09 |
| PW 4HR AHR H34050 | 95507-H34050 | \$ 400.00 | 6% | \$378.82 |
| PW 4HR AHR H34051 | 95507-H34051 | \$ 400.00 | 6% | \$378.82 |
| PW 4HR AHR H34052 | 95507-H34052 | \$ 640.00 | 6% | \$606.11 |
| PW 4HR AHR H34053 | 95507-H34053 | \$ 640.00 | 6% | \$606.11 |
| PW 4HR AHR H34054 | 95507-H34054 | \$ 483.00 | 6% | \$457.43 |
| PW 4HR AHR H34055 | 95507-H34055 | \$ 483.00 | 6% | \$457.43 |
| PW 4HR AHR H34056 | 95507-H34056 | \$ 699.00 | 6% | \$661.99 |
| PW 4HR AHR H34057 | 95507-H34057 | \$ 699.00 | 6% | \$661.99 |
| PW 4HR AHR H34058 | 95507-H34058 | \$ 596.00 | 6% | \$564.44 |
| PW 4HR AHR H34059 | 95507-H34059 | \$ 596.00 | 6% | \$564.44 |
| PW 4HR AHR H34062 | 95507-H34062 | \$ 699.00 | 6% | \$661.99 |
| PW 4HR AHR H34063 | 95507-H34063 | \$ 699.00 | 6% | \$661.99 |
| PW 4HR AHR H34064 | 95507-H34064 | \$ 512.00 | 6% | \$484.89 |
| PW 4HR AHR H34065 | 95507-H34065 | \$ 512.00 | 6% | \$484.89 |
| PW 4HR AHR H34066 | 95507-H34066 | \$ 512.00 | 6% | \$484.89 |
| PW 4HR AHR H34067 | 95507-H34067 | \$ 512.00 | 6% | \$484.89 |
| PW 4HR AHR H34068 | 95507-H34068 | \$ 512.00 | 6% | \$484.89 |
| PW 4HR AHR H34069 | 95507-H34069 | \$ 498.00 | 6% | \$471.63 |
| PW 4HR AHR H34070 | 95507-H34070 | \$ 512.00 | 6% | \$484.89 |
| PW 4HR AHR H34071 | 95507-H34071 | \$ 512.00 | 6% | \$484.89 |
| PW 4HR AHR H34072 | 95507-H34072 | \$ 3,843.00 | 6% | \$3,639.51 |
| PW 4HR AHR H34073 | 95507-H34073 | \$ 3,771.00 | 6% | \$3,571.33 |
| PW 4HR AHR H34074 | 95507-H34074 | \$ 4,798.00 | 6% | \$4,543.95 |
| PW 4HR AHR H34075 | 95507-H34075 | \$ 4,595.00 | 6% | \$4,351.69 |
| PW 4HR AHR H34076 | 95507-H34076 | \$ 3,843.00 | 6% | \$3,639.51 |
| PW 4HR AHR H34077 | 95507-H34077 | \$ 3,771.00 | 6% | \$3,571.33 |
| PW 4HR AHR H34078 | 95507-H34078 | \$ 3,843.00 | 6% | \$3,639.51 |
| PW 4HR AHR H34079 | 95507-H34079 | \$ 3,771.00 | 6% | \$3,571.33 |
| PW 4HR AHR H34080 | 95507-H34080 | \$ 4,798.00 | 6% | \$4,543.95 |
| PW 4HR AHR H34081 | 95507-H34081 | \$ 4,595.00 | 6% | \$4,351.69 |
| PW 4HR AHR H34082 | 95507-H34082 | \$ 4,603.00 | 6% | \$4,359.27 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW 4HR AHR H34083 | 95507-H34083 | \$ 4,407.00 | 6% | \$4,173.65 |
| PW 4HR AHR H34084 | 95507-H34084 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR AHR H34085 | 95507-H34085 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR AHR H34086 | 95507-H34086 | \$ 4,039.00 | 6% | \$3,825.13 |
| PW 4HR AHR H34087 | 95507-H34087 | \$ 3,873.00 | 6% | \$3,667.92 |
| PW 4HR AHR H34088 | 95507-H34088 | \$ 8,250.00 | 6% | \$7,813.16 |
| PW 4HR AHR H34089 | 95507-H34089 | \$ 8,250.00 | 6% | \$7,813.16 |
| PW 4HR AHR H34090 | 95507-H34090 | \$ 9,501.00 | 6% | \$8,997.92 |
| PW 4HR AHR H34091 | 95507-H34091 | \$ 6,714.00 | 6% | \$6,358.49 |
| PW 4HR AHR H34092 | 95507-H34092 | \$ 6,714.00 | 6% | \$6,358.49 |
| PW 4HR AHR H34093 | 95507-H34093 | \$ 6,714.00 | 6% | \$6,358.49 |
| PW 4HR AHR H34094 | 95507-H34094 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34095 | 95507-H34095 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34096 | 95507-H34096 | \$ 875.00 | 6% | \$828.67 |
| PW 4HR AHR H34097 | 95507-H34097 | \$ 875.00 | 6% | \$828.67 |
| PW 4HR AHR H34098 | 95507-H34098 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34099 | 95507-H34099 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34100 | 95507-H34100 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34101 | 95507-H34101 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34102 | 95507-H34102 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34103 | 95507-H34103 | \$ 773.00 | 6% | \$732.07 |
| PW 4HR AHR H34104 | 95507-H34104 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR H34105 | 95507-H34105 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR H34106 | 95507-H34106 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR H34107 | 95507-H34107 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR H34108 | 95507-H34108 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR H34109 | 95507-H34109 | \$ 335.00 | 6% | \$317.26 |
| PW 4HR AHR H34110 | 95507-H34110 | \$ 6,467.00 | 6% | \$6,124.57 |
| PW 4HR AHR H34111 | 95507-H34111 | \$ 6,467.00 | 6% | \$6,124.57 |
| PW 4HR AHR H34112 | 95507-H34112 | \$ 6,467.00 | 6% | \$6,124.57 |
| PW 4HR AHR H34114 | 95507-H34114 | \$ 8,495.00 | 6% | \$8,045.19 |
| PW 4HR AHR H34115 | 95507-H34115 | \$ 8,495.00 | 6% | \$8,045.19 |
| PW 4HR AHR H34116 | 95507-H34116 | \$ 8,495.00 | 6% | \$8,045.19 |
| PW 4HR AHR H34117 | 95507-H34117 | \$ 8,495.00 | 6% | \$8,045.19 |
| PW 4HR AHR H34118 | 95507-H34118 | \$ 2,144.00 | 6% | \$2,030.48 |
| PW 4HR AHR H34119 | 95507-H34119 | \$ 2,144.00 | 6% | \$2,030.48 |
| PW 4HR AHR H34120 | 95507-H34120 | \$ 1,476.00 | 6% | \$1,397.85 |
| PW 4HR AHR H34121 | 95507-H34121 | \$ 1,476.00 | 6% | \$1,397.85 |
| PW 4HR AHR H34122 | 95507-H34122 | \$ 1,542.00 | 6% | \$1,460.35 |
| PW 4HR AHR H34123 | 95507-H34123 | \$ 1,542.00 | 6% | \$1,460.35 |
| PW 4HR AHR H34124 | 95507-H34124 | \$ 2,297.00 | 6% | \$2,175.37 |
| PW 4HR AHR H34125 | 95507-H34125 | \$ 2,297.00 | 6% | \$2,175.37 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW 4HR AHR H34126 | 95507-H34126 | \$ 2,297.00 | 6% | \$2,175.37 |
| PW 4HR AHR H34127 | 95507-H34127 | \$ 2,297.00 | 6% | \$2,175.37 |
| PW 4HR AHR H34128 | 95507-H34128 | \$ 277.00 | 6% | \$262.33 |
| PW 4HR AHR H34129 | 95507-H34129 | \$ 600.00 | 6% | \$568.23 |
| PW 4HR AHR H34130 | 95507-H34130 | \$ 624.00 | 6% | \$590.96 |
| PW 4HR AHR H34131 | 95507-H34131 | \$ 621.00 | 6% | \$588.12 |
| PW 4HR AHR H34132 | 95507-H34132 | \$ 624.00 | 6% | \$590.96 |
| PW 4HR AHR H34172 | 95507-H34172 | \$ 2,255.00 | 6% | \$2,135.60 |
| PW 4HR AHR H34726 | 95507-H34726 | \$ 3,991.00 | 6% | \$3,779.68 |
| PW 4HR AHR H34727 | 95507-H34727 | \$ 3,991.00 | 6% | \$3,779.68 |
| PW 4HR AHR H34728 | 95507-H34728 | \$ 3,991.00 | 6% | \$3,779.68 |
| PW 4HR AHR H34729 | 95507-H34729 | \$ 3,991.00 | 6% | \$3,779.68 |
| PW 4HR AHR H34730 | 95507-H34730 | \$ 4,281.00 | 6% | \$4,054.32 |
| PW 4HR AHR H34731 | 95507-H34731 | \$ 4,281.00 | 6% | \$4,054.32 |
| PW 4HR AHR H34732 | 95507-H34732 | \$ 4,281.00 | 6% | \$4,054.32 |
| PW 4HR AHR H34733 | 95507-H34733 | \$ 4,281.00 | 6% | \$4,054.32 |
| PW 4HR AHR H34734 | 95507-H34734 | \$ 622.00 | 6% | \$589.07 |
| PW 4HR AHR H34735 | 95507-H34735 | \$ 622.00 | 6% | \$589.07 |
| PW 4HR AHR H34736 | 95507-H34736 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR H34737 | 95507-H34737 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR H34738 | 95507-H34738 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34739 | 95507-H34739 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34740 | 95507-H34740 | \$ 622.00 | 6% | \$589.07 |
| PW 4HR AHR H34741 | 95507-H34741 | \$ 622.00 | 6% | \$589.07 |
| PW 4HR AHR H34742 | 95507-H34742 | \$ 627.00 | 6% | \$593.80 |
| PW 4HR AHR H34743 | 95507-H34743 | \$ 627.00 | 6% | \$593.80 |
| PW 4HR AHR H34744 | 95507-H34744 | \$ 788.00 | 6% | \$746.28 |
| PW 4HR AHR H34745 | 95507-H34745 | \$ 788.00 | 6% | \$746.28 |
| PW 4HR AHR H34746 | 95507-H34746 | \$ 887.00 | 6% | \$840.03 |
| PW 4HR AHR H34747 | 95507-H34747 | \$ 887.00 | 6% | \$840.03 |
| PW 4HR AHR H34748 | 95507-H34748 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34749 | 95507-H34749 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34750 | 95507-H34750 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34751 | 95507-H34751 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34752 | 95507-H34752 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34753 | 95507-H34753 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34754 | 95507-H34754 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34755 | 95507-H34755 | \$ 1,497.00 | 6% | \$1,417.73 |
| PW 4HR AHR H34756 | 95507-H34756 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR H34757 | 95507-H34757 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR H34758 | 95507-H34758 | \$ 788.00 | 6% | \$746.28 |
| PW 4HR AHR H34759 | 95507-H34759 | \$ 792.00 | 6% | \$750.06 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PW 4HR AHR H34760 | 95507-H34760 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR H34761 | 95507-H34761 | \$ 788.00 | 6% | \$746.28 |
| PW 4HR AHR H34839 | 95507-H34839 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34840 | 95507-H34840 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34841 | 95507-H34841 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34842 | 95507-H34842 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34843 | 95507-H34843 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34844 | 95507-H34844 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34845 | 95507-H34845 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34846 | 95507-H34846 | \$ 800.00 | 6% | \$757.64 |
| PW 4HR AHR H34993 | 95507-H34993 | \$ 16,737.00 | 6% | \$15,850.78 |
| PW 4HR AHR H34994 | 95507-H34994 | \$ 16,737.00 | 6% | \$15,850.78 |
| PW 4HR AHR H34996 | 95507-H34996 | \$ 16,737.00 | 6% | \$15,850.78 |
| PW 4HR AHR H34997 | 95507-H34997 | \$ 16,737.00 | 6% | \$15,850.78 |
| PW 4HR AHR H35005 | 95507-H35005 | \$ 12,209.00 | 6% | \$11,562.53 |
| PW 4HR AHR H35006 | 95507-H35006 | \$ 12,209.00 | 6% | \$11,562.53 |
| PW 4HR AHR H35012 | 95507-H35012 | \$ 7,338.00 | 6% | \$6,949.45 |
| PW 4HR AHR H35262 | 95507-H35262 | \$ 2,805.00 | 6% | \$2,656.48 |
| PW 4HR AHR H35270 | 95507-H35270 | \$ 640.00 | 6% | \$606.11 |
| PW 4HR AHR H35271 | 95507-H35271 | \$ 483.00 | 6% | \$457.43 |
| PW 4HR AHR H35272 | 95507-H35272 | \$ 479.00 | 6% | \$453.64 |
| PW 4HR AHR H35273 | 95507-H35273 | \$ 479.00 | 6% | \$453.64 |
| PW 4HR AHR H35274 | 95507-H35274 | \$ 891.00 | 6% | \$843.82 |
| PW 4HR AHR H35275 | 95507-H35275 | \$ 699.00 | 6% | \$661.99 |
| PW 4HR AHR H35276 | 95507-H35276 | \$ 3,843.00 | 6% | \$3,639.51 |
| PW 4HR AHR H35277 | 95507-H35277 | \$ 4,603.00 | 6% | \$4,359.27 |
| PW 4HR AHR H35278 | 95507-H35278 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR AHR H35279 | 95507-H35279 | \$ 3,873.00 | 6% | \$3,667.92 |
| PW 4HR AHR H35280 | 95507-H35280 | \$ 6,343.00 | 6% | \$6,007.14 |
| PW 4HR AHR H35281 | 95507-H35281 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35282 | 95507-H35282 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35283 | 95507-H35283 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35284 | 95507-H35284 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35285 | 95507-H35285 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35286 | 95507-H35286 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35287 | 95507-H35287 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35288 | 95507-H35288 | \$ 2,221.00 | 6% | \$2,103.40 |
| PW 4HR AHR H35289 | 95507-H35289 | \$ 5,913.00 | 6% | \$5,599.91 |
| PW 4HR AHR H35291 | 95507-H35291 | \$ 4,468.00 | 6% | \$4,231.42 |
| PW 4HR AHR H35292 | 95507-H35292 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR AHR H35293 | 95507-H35293 | \$ 3,873.00 | 6% | \$3,667.92 |
| PW 4HR AHR H35295 | 95507-H35295 | \$ 571.00 | 6% | \$540.77 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PW 4hr AHR H35296 | 95507-H35296 | \$ 7,436.00 | 6% | \$7,042.26 |
| PW 4hr AHR H35297 | 95507-H35297 | \$ 7,436.00 | 6% | \$7,042.26 |
| PW 4hr AHR H35298 | 95507-H35298 | \$ 11,944.00 | 6% | \$11,311.57 |
| PW 4hr AHR H35299 | 95507-H35299 | \$ 11,944.00 | 6% | \$11,311.57 |
| PW 4hr AHR H35302 | 95507-H35302 | \$ 2,880.00 | 6% | \$2,727.50 |
| PW 4hr AHR H35303 | 95507-H35303 | \$ 2,880.00 | 6% | \$2,727.50 |
| PW 4hr AHR H35304 | 95507-H35304 | \$ 2,880.00 | 6% | \$2,727.50 |
| PW 4hr AHR H35305 | 95507-H35305 | \$ 3,021.00 | 6% | \$2,861.04 |
| PW 4hr AHR H35306 | 95507-H35306 | \$ 3,021.00 | 6% | \$2,861.04 |
| PW 4hr AHR H35307 | 95507-H35307 | \$ 3,021.00 | 6% | \$2,861.04 |
| PW 4HR AHR H35309 | 95507-H35309 | \$ 4,043.00 | 6% | \$3,828.92 |
| PW 4HR AHR H35310 | 95507-H35310 | \$ 4,043.00 | 6% | \$3,828.92 |
| PW 4HR AHR H35311 | 95507-H35311 | \$ 4,043.00 | 6% | \$3,828.92 |
| PW 4HR AHR H35312 | 95507-H35312 | \$ 3,340.00 | 6% | \$3,163.15 |
| PW 4HR AHR H35313 | 95507-H35313 | \$ 3,340.00 | 6% | \$3,163.15 |
| PW 4HR AHR H35314 | 95507-H35314 | \$ 3,340.00 | 6% | \$3,163.15 |
| PW 4HR AHR H35315 | 95507-H35315 | \$ 1,464.00 | 6% | \$1,386.48 |
| PW 4HR AHR H35318 | 95507-H35318 | \$ 705.00 | 6% | \$667.67 |
| PW 4HR AHR H35319 | 95507-H35319 | \$ 932.00 | 6% | \$882.65 |
| PW 4HR AHR H35320 | 95507-H35320 | \$ 967.00 | 6% | \$915.80 |
| PW 4HR AHR H35321 | 95507-H35321 | \$ 1,231.00 | 6% | \$1,165.82 |
| PW 4HR AHR H35322 | 95507-H35322 | \$ 1,493.00 | 6% | \$1,413.95 |
| PW 4HR AHR H35323 | 95507-H35323 | \$ 1,464.00 | 6% | \$1,386.48 |
| PW 4HR AHR H35328 | 95507-H35328 | \$ 125.00 | 6% | \$118.38 |
| PW 4HR AHR H35330 | 95507-H35330 | \$ 120.00 | 6% | \$113.65 |
| PW 4HR AHR H35340 | 95507-H35340 | \$ 3,113.00 | 6% | \$2,948.17 |
| PW 4HR AHR H35341 | 95507-H35341 | \$ 3,113.00 | 6% | \$2,948.17 |
| PW 4HR AHR H35342 | 95507-H35342 | \$ 2,756.00 | 6% | \$2,610.07 |
| PW 4HR AHR H35343 | 95507-H35343 | \$ 3,113.00 | 6% | \$2,948.17 |
| PW 4HR AHR H35344 | 95507-H35344 | \$ 3,252.00 | 6% | \$3,079.81 |
| PW 4HR AHR H35345 | 95507-H35345 | \$ 3,252.00 | 6% | \$3,079.81 |
| PW 4HR AHR H35346 | 95507-H35346 | \$ 2,855.00 | 6% | \$2,703.83 |
| PW 4HR AHR H35347 | 95507-H35347 | \$ 3,252.00 | 6% | \$3,079.81 |
| PW 4HR AHR H35349 | 95507-H35349 | \$ 3,583.00 | 6% | \$3,393.28 |
| PW 4HR AHR H35350 | 95507-H35350 | \$ 3,583.00 | 6% | \$3,393.28 |
| PW 4HR AHR H35351 | 95507-H35351 | \$ 3,125.00 | 6% | \$2,959.53 |
| PW 4HR AHR H35352 | 95507-H35352 | \$ 3,583.00 | 6% | \$3,393.28 |
| PW 4HR AHR H35359 | 95507-H35359 | \$ 1,231.00 | 6% | \$1,165.82 |
| PW 4HR AHR H35360 | 95507-H35360 | \$ 1,493.00 | 6% | \$1,413.95 |
| PW 4HR AHR H35361 | 95507-H35361 | \$ 1,464.00 | 6% | \$1,386.48 |
| PW 4HR AHR H35362 | 95507-H35362 | \$ 705.00 | 6% | \$667.67 |
| PW 4HR AHR H35366 | 95507-H35366 | \$ 1,567.00 | 6% | \$1,484.03 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PW 4HR AHR H35367 | 95507-H35367 | \$ 1,829.00 | 6% | \$1,732.15 |
| PW 4HR AHR H35368 | 95507-H35368 | \$ 2,789.00 | 6% | \$2,641.32 |
| PW 4HR AHR H35369 | 95507-H35369 | \$ 910.00 | 6% | \$861.82 |
| PW 4HR AHR H35370 | 95507-H35370 | \$ 1,271.00 | 6% | \$1,203.70 |
| PW 4HR AHR H35375 | 95507-H35375 | \$ 763.00 | 6% | \$722.60 |
| PW 4HR AHR H35376 | 95507-H35376 | \$ 1,145.00 | 6% | \$1,084.37 |
| PW 4HR AHR H35377 | 95507-H35377 | \$ 477.00 | 6% | \$451.74 |
| PW 4HR AHR H35378 | 95507-H35378 | \$ 763.00 | 6% | \$722.60 |
| PW 4HR AHR H35379 | 95507-H35379 | \$ 477.00 | 6% | \$451.74 |
| PW 4HR AHR H35380 | 95507-H35380 | \$ 859.00 | 6% | \$813.52 |
| PW 4HR AHR H35381 | 95507-H35381 | \$ 1,049.00 | 6% | \$993.46 |
| PW 4HR AHR H35384 | 95507-H35384 | \$ 344.00 | 6% | \$325.79 |
| PW 4HR AHR H35385 | 95507-H35385 | \$ 458.00 | 6% | \$433.75 |
| PW 4HR AHR H35386 | 95507-H35386 | \$ 763.00 | 6% | \$722.60 |
| PW 4HR AHR H35387 | 95507-H35387 | \$ 714.00 | 6% | \$676.19 |
| PW 4HR AHR H35388 | 95507-H35388 | \$ 528.00 | 6% | \$500.04 |
| PW 4HR AHR H35389 | 95507-H35389 | \$ 297.00 | 6% | \$281.27 |
| PW 4HR AHR H35390 | 95507-H35390 | \$ 256.00 | 6% | \$242.44 |
| PW 4HR AHR H35391 | 95507-H35391 | \$ 566.00 | 6% | \$536.03 |
| PW 4HR AHR H35392 | 95507-H35392 | \$ 859.00 | 6% | \$813.52 |
| PW 4HR AHR H35393 | 95507-H35393 | \$ 1,145.00 | 6% | \$1,084.37 |
| PW 4HR AHR H35394 | 95507-H35394 | \$ 210.00 | 6% | \$198.88 |
| PW 4HR AHR H35395 | 95507-H35395 | \$ 172.00 | 6% | \$162.89 |
| PW 4HR AHR H35396 | 95507-H35396 | \$ 210.00 | 6% | \$198.88 |
| PW 4HR AHR H35397 | 95507-H35397 | \$ 172.00 | 6% | \$162.89 |
| PW 4HR AHR H35398 | 95507-H35398 | \$ 534.00 | 6% | \$505.72 |
| PW 4HR AHR H35399 | 95507-H35399 | \$ 649.00 | 6% | \$614.64 |
| PW 4HR AHR H35400 | 95507-H35400 | \$ 718.00 | 6% | \$679.98 |
| PW 4HR AHR H35401 | 95507-H35401 | \$ 382.00 | 6% | \$361.77 |
| PW 4HR AHR H35415 | 95507-H35415 | \$ 266.00 | 6% | \$251.92 |
| PW 4HR AHR H35416 | 95507-H35416 | \$ 266.00 | 6% | \$251.92 |
| PW 4HR AHR H35426 | 95507-H35426 | \$ 297.00 | 6% | \$281.27 |
| PW 4HR AHR H35427 | 95507-H35427 | \$ 714.00 | 6% | \$676.19 |
| PW 4HR AHR H35428 | 95507-H35428 | \$ 256.00 | 6% | \$242.44 |
| PW 4HR AHR H35429 | 95507-H35429 | \$ 566.00 | 6% | \$536.03 |
| PW 4HR AHR H35430 | 95507-H35430 | \$ 604.00 | 6% | \$572.02 |
| PW 4HR AHR H35431 | 95507-H35431 | \$ 604.00 | 6% | \$572.02 |
| PW 4HR AHR H35432 | 95507-H35432 | \$ 627.00 | 6% | \$593.80 |
| PW 4HR AHR H35433 | 95507-H35433 | \$ 769.00 | 6% | \$728.28 |
| PW 4HR AHR H35434 | 95507-H35434 | \$ 865.00 | 6% | \$819.20 |
| PW 4HR AHR H35435 | 95507-H35435 | \$ 865.00 | 6% | \$819.20 |
| PW 4HR AHR H35436 | 95507-H35436 | \$ 1,453.00 | 6% | \$1,376.06 |

| | | | | |
|------------------------------|-------------------------|-------------|----|------------|
| PW 4HR AHR H35437 | 95507-H35437 | \$ 1,453.00 | 6% | \$1,376.06 |
| PW 4HR AHR H35438 | 95507-H35438 | \$ 1,453.00 | 6% | \$1,376.06 |
| PW 4HR AHR H35439 | 95507-H35439 | \$ 1,453.00 | 6% | \$1,376.06 |
| PW 4HR AHR H35440 | 95507-H35440 | \$ 769.00 | 6% | \$728.28 |
| PW 4HR AHR H35441 | 95507-H35441 | \$ 769.00 | 6% | \$728.28 |
| PW 4HR AHR H35442 | 95507-H35442 | \$ 769.00 | 6% | \$728.28 |
| PW 4HR AHR H35443 | 95507-H35443 | \$ 3,991.00 | 6% | \$3,779.68 |
| PW 4HR AHR H35444 | 95507-H35444 | \$ 4,281.00 | 6% | \$4,054.32 |
| PW 4HR AHR H35445 | 95507-H35445 | \$ 3,843.00 | 6% | \$3,639.51 |
| PW 4HR AHR H35446 | 95507-H35446 | \$ 3,771.00 | 6% | \$3,571.33 |
| PW 4HR AHR H35447 | 95507-H35447 | \$ 4,362.00 | 6% | \$4,131.03 |
| PW 4HR AHR H35448 | 95507-H35448 | \$ 4,177.00 | 6% | \$3,955.83 |
| PW 4HR AHR H35449 | 95507-H35449 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR AHR H35450 | 95507-H35450 | \$ 3,672.00 | 6% | \$3,477.57 |
| PW 4HR AHR H35451 | 95507-H35451 | \$ 6,714.00 | 6% | \$6,358.49 |
| PW 4HR AHR H35452 | 95507-H35452 | \$ 6,714.00 | 6% | \$6,358.49 |
| PW 4HR AHR H35453 | 95507-H35453 | \$ 4,281.00 | 6% | \$4,054.32 |
| PW 4HR AHR H35454 | 95507-H35454 | \$ 3,991.00 | 6% | \$3,779.68 |
| PW 4HR AHR H35455 | 95507-H35455 | \$ 967.00 | 6% | \$915.80 |
| PW 4HR AHR H35456 | 95507-H35456 | \$ 1,193.00 | 6% | \$1,129.83 |
| PW 4HR AHR H35457 | 95507-H35457 | \$ 1,075.00 | 6% | \$1,018.08 |
| PW 4HR AHR H35458 | 95507-H35458 | \$ 1,175.00 | 6% | \$1,112.78 |
| PW 4HR AHR H35471 | 95507-H35471 | \$ 967.00 | 6% | \$915.80 |
| PW 4HR AHR H35600 | 95507-H35600 | \$ 479.00 | 6% | \$453.64 |
| PW 4HR AHR H35601 | 95507-H35601 | \$ 479.00 | 6% | \$453.64 |
| PW 4HR AHR H35602 | 95507-H35602 | \$ 622.00 | 6% | \$589.07 |
| PW 4HR AHR H35603 | 95507-H35603 | \$ 622.00 | 6% | \$589.07 |
| PW 4HR AHR H35604 | 95507-H35604 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR H35605 | 95507-H35605 | \$ 792.00 | 6% | \$750.06 |
| PW 4HR AHR H35606 | 95507-H35606 | \$ 891.00 | 6% | \$843.82 |
| PW 4HR AHR H35607 | 95507-H35607 | \$ 887.00 | 6% | \$840.03 |
| PW 4HR AHR ISW-24W-4X | 95507-ISW-24W-4X | \$ 1,017.00 | 6% | \$963.15 |
| PW 4HR AHR ISW-4W-4WS-4X | 95507-ISW-4W-4WS-4X | \$ 645.00 | 6% | \$610.85 |
| PW 4HR AHR BD MSM128 | 95507-MSM128 | \$ 3,326.00 | 6% | \$3,149.89 |
| PW 4HR AHR BD MSM48C | 95507-MSM48C | \$ 2,013.00 | 6% | \$1,906.41 |
| PW 4HR AHR SLX9150-48XT-DC-F | 95507-SLX9150-48XT-DC-F | \$ 2,836.00 | 6% | \$2,685.83 |

| | | | | |
|------------------------------|-------------------------|--------------|----|-------------|
| PW 4HR AHR SLX9150-48XT-DC-R | 95507-SLX9150-48XT-DC-R | \$ 3,096.00 | 6% | \$2,932.07 |
| PW 4HR AHR SLX9150-48Y-DC-F | 95507-SLX9150-48Y-DC-F | \$ 2,715.00 | 6% | \$2,571.24 |
| PW 4HR AHR SLX9150-48Y-DC-R | 95507-SLX9150-48Y-DC-R | \$ 2,965.00 | 6% | \$2,808.00 |
| PW 4HR AHR SLX9740-40C | 95507-SLX9740-40C | \$ 12,202.00 | 6% | \$11,555.90 |
| PW 4HR AHR SLX9740-40C-AC-F | 95507-SLX9740-40C-AC-F | \$ 12,202.00 | 6% | \$11,555.90 |
| PW 4HR AHR SLX9740-40C-AC-R | 95507-SLX9740-40C-AC-R | \$ 12,202.00 | 6% | \$11,555.90 |
| PW 4HR AHR SLX9740-40C-DC-F | 95507-SLX9740-40C-DC-F | \$ 12,202.00 | 6% | \$11,555.90 |
| PW 4HR AHR SLX9740-80C | 95507-SLX9740-80C | \$ 22,946.00 | 6% | \$21,731.01 |
| PW 4HR AHR SLX9740-80C-AC-F | 95507-SLX9740-80C-AC-F | \$ 22,946.00 | 6% | \$21,731.01 |
| PW 4HR AHR SLX9740-80C-AC-R | 95507-SLX9740-80C-AC-R | \$ 22,946.00 | 6% | \$21,731.01 |
| PW 4HR AHR SLX9740-80C-DC-F | 95507-SLX9740-80C-DC-F | \$ 22,946.00 | 6% | \$21,731.01 |
| PW 4HR AHR V300-8P-2X | 95507-V300-8P-2X | \$ 162.00 | 6% | \$153.42 |
| PW 4HR AHR V300-8T-2X | 95507-V300-8T-2X | \$ 112.00 | 6% | \$106.07 |
| PW 4HR AHR V300HT-8P-2X | 95507-V300HT-8P-2X | \$ 370.00 | 6% | \$350.41 |
| PW 4HR AHR V300HT-8T-2X | 95507-V300HT-8T-2X | \$ 220.00 | 6% | \$208.35 |
| PW 4HR AHR Summit VIM-SS | 95507-VIM-SS | \$ 165.00 | 6% | \$156.26 |

| | | | | |
|----------------------------------|-----------------------------|-------------|----|------------|
| PW 4HR AHR Summit VIM-SSV80 | 95507-VIM-SSV80 | \$ 309.00 | 6% | \$292.64 |
| PW 4HR AHR Summit VIM2-SS | 95507-VIM2-SS | \$ 193.00 | 6% | \$182.78 |
| PW 4HR AHR Summit VIM2-SS128 | 95507-VIM2-SS128 | \$ 683.00 | 6% | \$646.84 |
| PW 4HR AHR Summit VIM2-V80 | 95507-VIM2-V80 | \$ 729.00 | 6% | \$690.40 |
| PW 4HR AHR Summit VIM210G4X | 95507-VIM210G4X | \$ 1,268.00 | 6% | \$1,200.86 |
| PW 4HR AHR VIM5-2Q | 95507-VIM5-2Q | \$ 215.00 | 6% | \$203.62 |
| PW 4HR AHR VIM5-2Y | 95507-VIM5-2Y | \$ 254.00 | 6% | \$240.55 |
| PW 4HR AHR VIM5-4X | 95507-VIM5-4X | \$ 110.00 | 6% | \$104.18 |
| PW 4HR AHR VIM5-4XE | 95507-VIM5-4XE | \$ 209.00 | 6% | \$197.93 |
| PW 4HR AHR VIM5-4Y | 95507-VIM5-4Y | \$ 326.00 | 6% | \$308.74 |
| PW 4HR AHR VIM5-4YE | 95507-VIM5-4YE | \$ 419.00 | 6% | \$396.81 |
| PW 4HR AHR VSP4900-12MXU-12XE | 95507-VSP4900-12MXU-12XE | \$ 1,292.00 | 6% | \$1,223.59 |
| PW 4HR AHR VSP4900-12MXU-12XE-B1 | 95507-VSP4900-12MXU-12XE-B1 | \$ 1,292.00 | 6% | \$1,223.59 |
| PW 4HR AHR VSP4900-24S | 95507-VSP4900-24S | \$ 705.00 | 6% | \$667.67 |
| PW 4HR AHR VSP4900-24S-B3 | 95507-VSP4900-24S-B3 | \$ 705.00 | 6% | \$667.67 |
| PW 4HR AHR VSP4900-24XE | 95507-VSP4900-24XE | \$ 1,292.00 | 6% | \$1,223.59 |
| PW 4HR AHR VSP4900-24XE-B3 | 95507-VSP4900-24XE-B3 | \$ 1,292.00 | 6% | \$1,223.59 |
| PW 4HR AHR X435-24P-4S | 95507-X435-24P-4S | \$ 286.00 | 6% | \$270.86 |

| | | | | |
|------------------------------|--------------------|-------------|----|-------------------|
| PW 4HR AHR X435-24T-4S | 95507-X435-24T-4S | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR AHR X435-8P-2T-W | 95507-X435-8P-2T-W | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR AHR X435-8P-4S | 95507-X435-8P-4S | \$ 142.00 | 6% | <i>\$134.48</i> |
| PW 4HR AHR X435-8T-4S | 95507-X435-8T-4S | \$ 115.00 | 6% | <i>\$108.91</i> |
| PW 4HR AHR Summit X460-24P | 95507-X460-24P | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| PW 4HR AHR Summit X460-24T | 95507-X460-24T | \$ 829.00 | 6% | <i>\$785.10</i> |
| PW 4HR AHR Summit X460-24TDC | 95507-X460-24TDC | \$ 1,225.00 | 6% | <i>\$1,160.14</i> |
| PW 4HR AHR Summit X460-24X | 95507-X460-24X | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| PW 4HR AHR Summit X460-24XDC | 95507-X460-24XDC | \$ 1,726.00 | 6% | <i>\$1,634.61</i> |
| PW 4HR AHR Summit X460-48P | 95507-X460-48P | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| PW 4HR AHR Summit X460-48T | 95507-X460-48T | \$ 1,321.00 | 6% | <i>\$1,251.05</i> |
| PW 4HR AHR Summit X460-48TDC | 95507-X460-48TDC | \$ 1,673.00 | 6% | <i>\$1,584.41</i> |
| PW 4HR AHR Summit X460-48X | 95507-X460-48X | \$ 2,055.00 | 6% | <i>\$1,946.19</i> |
| PW 4HR AHR Summit X460-48XDC | 95507-X460-48XDC | \$ 2,004.00 | 6% | <i>\$1,897.89</i> |
| PW 4HR AHR X465-24MU | 95507-X465-24MU | \$ 1,493.00 | 6% | <i>\$1,413.95</i> |
| PW 4HR AHR X465-24S | 95507-X465-24S | \$ 705.00 | 6% | <i>\$667.67</i> |
| PW 4HR AHR X465-24S-B3 | 95507-X465-24S-B3 | \$ 705.00 | 6% | <i>\$667.67</i> |
| PW 4HR AHR X465-24W | 95507-X465-24W | \$ 705.00 | 6% | <i>\$667.67</i> |
| PW 4HR AHR X465-24XE | 95507-X465-24XE | \$ 1,292.00 | 6% | <i>\$1,223.59</i> |
| PW 4HR AHR X465-24XE-B3 | 95507-X465-24XE-B3 | \$ 1,292.00 | 6% | <i>\$1,223.59</i> |
| PW 4HR AHR X465-48P | 95507-X465-48P | \$ 967.00 | 6% | <i>\$915.80</i> |

| | | | | |
|----------------------------|-----------------------|-------------|----|------------|
| PW 4HR AHR X465-48T | 95507-X465-48T | \$ 932.00 | 6% | \$882.65 |
| PW 4HR AHR X465-48W | 95507-X465-48W | \$ 1,231.00 | 6% | \$1,165.82 |
| PW 4HR AHR X465i-48W | 95507-X465i-48W | \$ 1,464.00 | 6% | \$1,386.48 |
| PW 4HR AHR X465i-48W-B1-S1 | 95507-X465i-48W-B1-S1 | \$ 1,464.00 | 6% | \$1,386.48 |
| PW 4HR AHR X465i-48W-B2-S1 | 95507-X465i-48W-B2-S1 | \$ 1,464.00 | 6% | \$1,386.48 |
| PW 4HR AHR Summit X480-24X | 95507-X480-24X | \$ 1,905.00 | 6% | \$1,804.13 |
| PW 4HR AHR Summit X480-48T | 95507-X480-48T | \$ 1,905.00 | 6% | \$1,804.13 |
| PW 4HR AHR Summit X480-48X | 95507-X480-48X | \$ 2,529.00 | 6% | \$2,395.09 |
| PW 4HR AHR X695-48Y-8C | 95507-X695-48Y-8C | \$ 3,369.00 | 6% | \$3,190.61 |
| PW 4HR AHR XA1440 | 95507-XA1440 | \$ 353.00 | 6% | \$334.31 |
| PW 4HR AHR XA1480 | 95507-XA1480 | \$ 472.00 | 6% | \$447.01 |
| PW 4HR AHR Summit XGM3-2SF | 95507-XGM3-2SF | \$ 309.00 | 6% | \$292.64 |
| PW 4HR AHR XR600 | 95507-XR600 | \$ 97.00 | 6% | \$91.86 |
| PW 4HR AHR -ZR-XFP | 95507-ZR-XFP | \$ 1,916.00 | 6% | \$1,814.55 |
| PW 4HR ONSITE Optics 10200 | 95508-10200 | \$ 3,149.00 | 6% | \$2,982.26 |
| PW 4HR ONSITE Optics 10320 | 95508-10320 | \$ 3,459.00 | 6% | \$3,275.85 |
| PW 4HR ONSITE 10330 | 95508-10330 | \$ 8,488.00 | 6% | \$8,038.56 |
| PW 4HR ONSITE 10331 | 95508-10331 | \$ 3,915.00 | 6% | \$3,707.70 |
| PW 4HR ONSITE 10335 | 95508-10335 | \$ 5,974.00 | 6% | \$5,657.68 |
| PW 4HR ONSITE 10403 | 95508-10403 | \$ 7,410.00 | 6% | \$7,017.64 |
| PW 4HR ONSITE 10404 | 95508-10404 | \$ 3,635.00 | 6% | \$3,442.53 |
| PW 4HR ONSITE 10441 | 95508-10441 | \$ 2,437.00 | 6% | \$2,307.96 |
| PW 4HR ONSITE 10442 | 95508-10442 | \$ 2,595.00 | 6% | \$2,457.59 |
| PW 4HR ONSITE 1130C | 95508-1130C | \$ 1,679.00 | 6% | \$1,590.10 |
| PW 4HR ONSITE E4G 16119 | 95508-16119 | \$ 446.00 | 6% | \$422.38 |
| PW 4HR ONSITE E4G 16120 | 95508-16120 | \$ 558.00 | 6% | \$528.45 |
| PW 4HR ONSITE E4G 16126 | 95508-16126 | \$ 446.00 | 6% | \$422.38 |
| PW 4HR ONSITE E4G 16127 | 95508-16127 | \$ 468.00 | 6% | \$443.22 |
| PW 4HR ONSITE 16172 | 95508-16172 | \$ 465.00 | 6% | \$440.38 |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| PW 4HR ONSITE -16172T | 95508-16172T | \$ 561.00 | 6% | \$531.30 |
| PW 4HR ONSITE 16173 | 95508-16173 | \$ 482.00 | 6% | \$456.48 |
| PW 4HR ONSITE -16173T | 95508-16173T | \$ 579.00 | 6% | \$548.34 |
| PW 4HR ONSITE 16174 | 95508-16174 | \$ 735.00 | 6% | \$696.08 |
| PW 4HR ONSITE 16175 | 95508-16175 | \$ 783.00 | 6% | \$741.54 |
| PW 4HR ONSITE 16176 | 95508-16176 | \$ 688.00 | 6% | \$651.57 |
| PW 4HR ONSITE 16177 | 95508-16177 | \$ 675.00 | 6% | \$639.26 |
| PW 4HR ONSITE -16177T | 95508-16177T | \$ 857.00 | 6% | \$811.62 |
| PW 4HR ONSITE 16178 | 95508-16178 | \$ 997.00 | 6% | \$944.21 |
| PW 4HR ONSITE 16179 | 95508-16179 | \$ 1,019.00 | 6% | \$965.04 |
| PW 4HR ONSITE -16179T | 95508-16179T | \$ 1,233.00 | 6% | \$1,167.71 |
| PW 4HR ONSITE 16301T | 95508-16301T | \$ 2,664.00 | 6% | \$2,522.94 |
| PW 4HR ONSITE 16303T | 95508-16303T | \$ 2,664.00 | 6% | \$2,522.94 |
| PW 4HR ONSITE 16304T | 95508-16304T | \$ 3,556.00 | 6% | \$3,367.71 |
| PW 4HR ONSITE 16401T | 95508-16401T | \$ 1,249.00 | 6% | \$1,182.87 |
| PW 4HR ONSITE 16402T | 95508-16402T | \$ 1,901.00 | 6% | \$1,800.34 |
| PW 4HR ONSITE 16403T | 95508-16403T | \$ 1,690.00 | 6% | \$1,600.51 |
| PW 4HR ONSITE 16404T | 95508-16404T | \$ 1,690.00 | 6% | \$1,600.51 |
| PW 4HR ONSITE 16405T | 95508-16405T | \$ 2,218.00 | 6% | \$2,100.56 |
| PW 4HR ONSITE 16406T | 95508-16406T | \$ 2,966.00 | 6% | \$2,808.95 |
| PW 4HR ONSITE E4G 16431 | 95508-16431 | \$ 1,877.00 | 6% | \$1,777.61 |
| PW 4HR ONSITE E4G 16432 | 95508-16432 | \$ 2,028.00 | 6% | \$1,920.62 |
| PW 4HR ONSITE E4G 16440 | 95508-16440 | \$ 1,169.00 | 6% | \$1,107.10 |
| PW 4HR ONSITE E4G 16441 | 95508-16441 | \$ 1,052.00 | 6% | \$996.30 |
| PW 4HR ONSITE E4G 16442 | 95508-16442 | \$ 468.00 | 6% | \$443.22 |
| PW 4HR ONSITE E4G 16444 | 95508-16444 | \$ 234.00 | 6% | \$221.61 |
| PW 4HR ONSITE Summit 16501 | 95508-16501 | \$ 257.00 | 6% | \$243.39 |
| PW 4HR ONSITE 16501T | 95508-16501T | \$ 330.00 | 6% | \$312.53 |
| PW 4HR ONSITE Summit 16502 | 95508-16502 | \$ 370.00 | 6% | \$350.41 |
| PW 4HR ONSITE 16502T | 95508-16502T | \$ 448.00 | 6% | \$424.28 |
| PW 4HR ONSITE Summit 16503 | 95508-16503 | \$ 310.00 | 6% | \$293.59 |
| PW 4HR ONSITE 16503T | 95508-16503T | \$ 411.00 | 6% | \$389.24 |
| PW 4HR ONSITE Summit 16504 | 95508-16504 | \$ 499.00 | 6% | \$472.58 |
| PW 4HR ONSITE 16504T | 95508-16504T | \$ 603.00 | 6% | \$571.07 |
| PW 4HR ONSITE Summit 16505 | 95508-16505 | \$ 563.00 | 6% | \$533.19 |
| PW 4HR ONSITE 16505T | 95508-16505T | \$ 682.00 | 6% | \$645.89 |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| PW 4HR ONSITE Summit 16506 | 95508-16506 | \$ 857.00 | 6% | <i>\$811.62</i> |
| PW 4HR ONSITE 16506T | 95508-16506T | \$ 383.00 | 6% | <i>\$362.72</i> |
| PW 4HR ONSITE Summit 16507 | 95508-16507 | \$ 779.00 | 6% | <i>\$737.75</i> |
| PW 4HR ONSITE 16507T | 95508-16507T | \$ 941.00 | 6% | <i>\$891.17</i> |
| PW 4HR ONSITE Summit 16508 | 95508-16508 | \$ 976.00 | 6% | <i>\$924.32</i> |
| PW 4HR ONSITE 16508T | 95508-16508T | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4HR ONSITE Summit 16509 | 95508-16509 | \$ 976.00 | 6% | <i>\$924.32</i> |
| PW 4HR ONSITE 16509T | 95508-16509T | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4HR ONSITE Summit 16510 | 95508-16510 | \$ 1,168.00 | 6% | <i>\$1,106.15</i> |
| PW 4HR ONSITE 16510T | 95508-16510T | \$ 1,403.00 | 6% | <i>\$1,328.71</i> |
| PW 4hr On-site-16513 | 95508-16513 | \$ 779.00 | 6% | <i>\$737.75</i> |
| PW 4hr On-site-16514 | 95508-16514 | \$ 1,145.00 | 6% | <i>\$1,084.37</i> |
| PW 4HR ONSITE 16515 | 95508-16515 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4hr On-site-16516 | 95508-16516 | \$ 215.00 | 6% | <i>\$203.62</i> |
| PW 4HR ONSITE 16517 | 95508-16517 | \$ 419.00 | 6% | <i>\$396.81</i> |
| PW 4hr On-site-16518 | 95508-16518 | \$ 385.00 | 6% | <i>\$364.61</i> |
| PW-4HR On-SITE 16519 | 95508-16519 | \$ 388.00 | 6% | <i>\$367.46</i> |
| PW-4HR On-SITE 16520 | 95508-16520 | \$ 639.00 | 6% | <i>\$605.16</i> |
| PW 4HR ONSITE 16530 | 95508-16530 | \$ 229.00 | 6% | <i>\$216.87</i> |
| PW 4HR ONSITE 16531 | 95508-16531 | \$ 320.00 | 6% | <i>\$303.06</i> |
| PW 4HR ONSITE 16531T | 95508-16531T | \$ 359.00 | 6% | <i>\$339.99</i> |
| PW 4HR ONSITE 16532 | 95508-16532 | \$ 320.00 | 6% | <i>\$303.06</i> |
| PW 4HR ONSITE 16532T | 95508-16532T | \$ 359.00 | 6% | <i>\$339.99</i> |
| PW 4HR ONSITE 16533 | 95508-16533 | \$ 450.00 | 6% | <i>\$426.17</i> |
| PW 4HR ONSITE 16533T | 95508-16533T | \$ 495.00 | 6% | <i>\$468.79</i> |
| PW 4HR ONSITE 16534 | 95508-16534 | \$ 479.00 | 6% | <i>\$453.64</i> |
| PW 4HR ONSITE 16535 | 95508-16535 | \$ 708.00 | 6% | <i>\$670.51</i> |
| PW 4HR ONSITE 16535A | 95508-16535A | \$ 708.00 | 6% | <i>\$670.51</i> |
| PW 4HR ONSITE 16535T | 95508-16535T | \$ 782.00 | 6% | <i>\$740.59</i> |
| PW 4HR ONSITE 16536 | 95508-16536 | \$ 326.00 | 6% | <i>\$308.74</i> |
| PW 4HR ONSITE 16537 | 95508-16537 | \$ 450.00 | 6% | <i>\$426.17</i> |
| PW 4HR ONSITE 16538 | 95508-16538 | \$ 541.00 | 6% | <i>\$512.35</i> |
| PW 4HR ONSITE 16538T | 95508-16538T | \$ 655.00 | 6% | <i>\$620.32</i> |
| PW 4HR ONSITE 16539 | 95508-16539 | \$ 698.00 | 6% | <i>\$661.04</i> |
| PW 4HR ONSITE 16540 | 95508-16540 | \$ 498.00 | 6% | <i>\$471.63</i> |
| PW 4HR ONSITE 16541 | 95508-16541 | \$ 188.00 | 6% | <i>\$178.05</i> |
| PW 4HR ONSITE 16560 | 95508-16560 | \$ 109.00 | 6% | <i>\$103.23</i> |

| | | | | |
|-----------------------|--------------|-------------|----|-------------------|
| PW 4HR ONSITE 16561 | 95508-16561 | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR ONSITE 16562 | 95508-16562 | \$ 192.00 | 6% | <i>\$181.83</i> |
| PW 4HR ONSITE 16563 | 95508-16563 | \$ 253.00 | 6% | <i>\$239.60</i> |
| PW 4HR ONSITE 16564 | 95508-16564 | \$ 315.00 | 6% | <i>\$298.32</i> |
| PW 4HR ONSITE 16565 | 95508-16565 | \$ 462.00 | 6% | <i>\$437.54</i> |
| PW 4HR ONSITE 16566 | 95508-16566 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR ONSITE 16567 | 95508-16567 | \$ 130.00 | 6% | <i>\$123.12</i> |
| PW 4HR ONSITE 16568 | 95508-16568 | \$ 109.00 | 6% | <i>\$103.23</i> |
| PW 4HR ONSITE 16569 | 95508-16569 | \$ 171.00 | 6% | <i>\$161.95</i> |
| PW 4HR ONSITE 16570 | 95508-16570 | \$ 192.00 | 6% | <i>\$181.83</i> |
| PW 4HR ONSITE 16571 | 95508-16571 | \$ 315.00 | 6% | <i>\$298.32</i> |
| PW 4HR ONSITE 16701 | 95508-16701 | \$ 684.00 | 6% | <i>\$647.78</i> |
| PW 4HR ONSITE 16702 | 95508-16702 | \$ 1,009.00 | 6% | <i>\$955.57</i> |
| PW 4HR ONSITE 16703 | 95508-16703 | \$ 794.00 | 6% | <i>\$751.96</i> |
| PW 4HR ONSITE -16703T | 95508-16703T | \$ 958.00 | 6% | <i>\$907.27</i> |
| PW 4HR ONSITE 16704 | 95508-16704 | \$ 1,163.00 | 6% | <i>\$1,101.42</i> |
| PW 4HR ONSITE -16704T | 95508-16704T | \$ 1,404.00 | 6% | <i>\$1,329.66</i> |
| PW 4HR ONSITE 16705 | 95508-16705 | \$ 1,009.00 | 6% | <i>\$955.57</i> |
| PW 4HR ONSITE -16705T | 95508-16705T | \$ 1,215.00 | 6% | <i>\$1,150.67</i> |
| PW 4HR ONSITE 16706 | 95508-16706 | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| PW 4HR ONSITE -16706T | 95508-16706T | \$ 1,846.00 | 6% | <i>\$1,748.25</i> |
| PW 4HR ONSITE 16710 | 95508-16710 | \$ 304.00 | 6% | <i>\$287.90</i> |
| PW 4HR ONSITE 16710T | 95508-16710T | \$ 376.00 | 6% | <i>\$356.09</i> |
| PW 4HR ONSITE 16711 | 95508-16711 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW 4HR ONSITE 16711T | 95508-16711T | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR ONSITE 16712 | 95508-16712 | \$ 175.00 | 6% | <i>\$165.73</i> |
| PW 4HR ONSITE 16712T | 95508-16712T | \$ 210.00 | 6% | <i>\$198.88</i> |
| PW 4HR ONSITE 16713 | 95508-16713 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW 4HR ONSITE 16713T | 95508-16713T | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW 4HR ONSITE 16715 | 95508-16715 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR ONSITE 16715T | 95508-16715T | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR ONSITE 16716 | 95508-16716 | \$ 535.00 | 6% | <i>\$506.67</i> |
| PW 4HR ONSITE -16716T | 95508-16716T | \$ 646.00 | 6% | <i>\$611.79</i> |
| PW 4HR ONSITE 16717 | 95508-16717 | \$ 809.00 | 6% | <i>\$766.16</i> |
| PW 4HR ONSITE 16718 | 95508-16718 | \$ 580.00 | 6% | <i>\$549.29</i> |
| PW 4HR ONSITE -16718T | 95508-16718T | \$ 697.00 | 6% | <i>\$660.09</i> |
| PW 4HR ONSITE 16719 | 95508-16719 | \$ 870.00 | 6% | <i>\$823.93</i> |
| PW 4HR ONSITE -16719T | 95508-16719T | \$ 1,041.00 | 6% | <i>\$985.88</i> |
| PW 4HR ONSITE 16720 | 95508-16720 | \$ 1,293.00 | 6% | <i>\$1,224.54</i> |
| PW 4HR ONSITE 16720T | 95508-16720T | \$ 1,505.00 | 6% | <i>\$1,425.31</i> |
| PW 4HR ONSITE 16756 | 95508-16756 | \$ 942.00 | 6% | <i>\$892.12</i> |
| PW 4HR ONSITE 16756T | 95508-16756T | \$ 1,114.00 | 6% | <i>\$1,055.01</i> |

| | | | | |
|-----------------------------|--------------|-------------|----|------------|
| PW 4HR ONSITE 16757 | 95508-16757 | \$ 890.00 | 6% | \$842.87 |
| PW 4HR ONSITE 16757T | 95508-16757T | \$ 1,054.00 | 6% | \$998.19 |
| PW 4HR ONSITE 16790 | 95508-16790 | \$ 2,075.00 | 6% | \$1,965.13 |
| PW 4HR ONSITE 16791 | 95508-16791 | \$ 2,676.00 | 6% | \$2,534.31 |
| PW 4HR ONSITE 16801 | 95508-16801 | \$ 265.00 | 6% | \$250.97 |
| PW 4HR ONSITE 16802 | 95508-16802 | \$ 298.00 | 6% | \$282.22 |
| PW 4HR ONSITE 16803 | 95508-16803 | \$ 320.00 | 6% | \$303.06 |
| PW 4HR ONSITE 16804 | 95508-16804 | \$ 394.00 | 6% | \$373.14 |
| PW 4HR ONSITE 16805 | 95508-16805 | \$ 80.00 | 6% | \$75.76 |
| PW 4HR ONSITE 16806 | 95508-16806 | \$ 68.00 | 6% | \$64.40 |
| PW 4HR ONSITE Summit 17101 | 95508-17101 | \$ 3,945.00 | 6% | \$3,736.11 |
| PW 4HR ONSITE 17101T | 95508-17101T | \$ 5,048.00 | 6% | \$4,780.71 |
| PW 4HR ONSITE Summit 17102 | 95508-17102 | \$ 3,945.00 | 6% | \$3,736.11 |
| PW 4HR ONSITE 17102T | 95508-17102T | \$ 5,048.00 | 6% | \$4,780.71 |
| PW 4HR ONSITE Summit 17103 | 95508-17103 | \$ 2,751.00 | 6% | \$2,605.33 |
| PW 4HR ONSITE Summit 17103C | 95508-17103C | \$ 2,671.00 | 6% | \$2,529.57 |
| PW 4HR ONSITE 17103T | 95508-17103T | \$ 3,516.00 | 6% | \$3,329.83 |
| PW 4HR ONSITE Summit 17104 | 95508-17104 | \$ 2,751.00 | 6% | \$2,605.33 |
| PW 4HR ONSITE 17104T | 95508-17104T | \$ 3,516.00 | 6% | \$3,329.83 |
| PW 4HR ONSITE Summit 17121 | 95508-17121 | \$ 780.00 | 6% | \$738.70 |
| PW 4HR ONSITE Summit 17122 | 95508-17122 | \$ 495.00 | 6% | \$468.79 |
| PW 4HR ONSITE -17200 | 95508-17200 | \$ 6,217.00 | 6% | \$5,887.81 |
| PW 4HR ONSITE 17200T | 95508-17200T | \$ 7,103.00 | 6% | \$6,726.90 |
| PW 4HR ONSITE Summit 17201 | 95508-17201 | \$ 6,217.00 | 6% | \$5,887.81 |
| PW 4HR ONSITE 17201T | 95508-17201T | \$ 7,103.00 | 6% | \$6,726.90 |
| PW 4HR ONSITE Summit 17202 | 95508-17202 | \$ 6,217.00 | 6% | \$5,887.81 |
| PW 4HR ONSITE 17202T | 95508-17202T | \$ 7,103.00 | 6% | \$6,726.90 |
| PW 4HR ONSITE Summit 17203 | 95508-17203 | \$ 6,305.00 | 6% | \$5,971.15 |
| PW 4HR ONSITE 17203T | 95508-17203T | \$ 7,208.00 | 6% | \$6,826.34 |
| PW 4HR ONSITE Summit 17204 | 95508-17204 | \$ 6,305.00 | 6% | \$5,971.15 |
| PW 4HR ONSITE 17204T | 95508-17204T | \$ 7,208.00 | 6% | \$6,826.34 |

| | | | | |
|----------------------------|-----------------|--------------|----|-------------|
| PW 4HR ONSITE Summit 17205 | 95508-17205 | \$ 6,261.00 | 6% | \$5,929.48 |
| PW 4HR ONSITE 17205T | 95508-17205T | \$ 7,157.00 | 6% | \$6,778.04 |
| PW 4HR ONSITE Summit 17206 | 95508-17206 | \$ 6,261.00 | 6% | \$5,929.48 |
| PW 4HR ONSITE 17206T | 95508-17206T | \$ 7,157.00 | 6% | \$6,778.04 |
| PW 4HR ONSITE 17300 | 95508-17300 | \$ 4,109.00 | 6% | \$3,891.43 |
| PW 4HR ONSITE 17310 | 95508-17310 | \$ 3,722.00 | 6% | \$3,524.92 |
| PW 4HR ONSITE -17310T | 95508-17310T | \$ 4,494.00 | 6% | \$4,256.04 |
| PW 4HR ONSITE 17350 | 95508-17350 | \$ 3,758.00 | 6% | \$3,559.01 |
| PW 4HR ONSITE 17360 | 95508-17360 | \$ 4,623.00 | 6% | \$4,378.21 |
| PW 4HR ONSITE 17401 | 95508-17401 | \$ 577.00 | 6% | \$546.45 |
| PW 4HR ONSITE 17401G | 95508-17401G | \$ 681.00 | 6% | \$644.94 |
| PW 4HR ONSITE 17401T | 95508-17401T | \$ 647.00 | 6% | \$612.74 |
| PW 4HR ONSITE 17402 | 95508-17402 | \$ 828.00 | 6% | \$784.16 |
| PW 4HR ONSITE 17402G | 95508-17402G | \$ 907.00 | 6% | \$858.97 |
| PW 4HR ONSITE 17402T | 95508-17402T | \$ 866.00 | 6% | \$820.15 |
| PW 4HR ONSITE 17403 | 95508-17403 | \$ 884.00 | 6% | \$837.19 |
| PW 4HR ONSITE 17404 | 95508-17404 | \$ 426.00 | 6% | \$403.44 |
| PW 4HR ONSITE 17405 | 95508-17405 | \$ 538.00 | 6% | \$509.51 |
| PW 4HR ONSITE 17700 | 95508-17700 | \$ 7,283.00 | 6% | \$6,897.37 |
| PW 4HR ONSITE 17701 | 95508-17701 | \$ 6,427.00 | 6% | \$6,086.69 |
| PW 4HR ONSITE 17702 | 95508-17702 | \$ 6,427.00 | 6% | \$6,086.69 |
| PW 4HR ONSITE 17703 | 95508-17703 | \$ 7,038.00 | 6% | \$6,665.34 |
| PW 4HR ONSITE 17704 | 95508-17704 | \$ 7,038.00 | 6% | \$6,665.34 |
| PW 4HR ONSITE 17705 | 95508-17705 | \$ 6,474.00 | 6% | \$6,131.20 |
| PW 4HR ONSITE 17706 | 95508-17706 | \$ 6,474.00 | 6% | \$6,131.20 |
| PW 4HR ONSITE 17800 | 95508-17800 | \$ 7,285.00 | 6% | \$6,899.26 |
| PW 4HR ONSITE 17810 | 95508-17810 | \$ 5,829.00 | 6% | \$5,520.35 |
| PW 4HR ONSITE 18101 | 95508-18101 | \$ 371.00 | 6% | \$351.36 |
| PW 4HR ONSITE 18102 | 95508-18102 | \$ 476.00 | 6% | \$450.80 |
| PW 4HR ONSITE 18103 | 95508-18103 | \$ 523.00 | 6% | \$495.31 |
| PW 4HR ONSITE 18104 | 95508-18104 | \$ 740.00 | 6% | \$700.82 |
| PW 4HR ONSITE 18104-6PK | 95508-18104-6PK | \$ 4,312.00 | 6% | \$4,083.68 |
| PW 4HR ONSITE 18202 | 95508-18202 | \$ 276.00 | 6% | \$261.39 |
| PW 4HR ONSITE 30135 | 95508-30135 | \$ 1,049.00 | 6% | \$993.46 |
| PW 4HR ONSITE 30136 | 95508-30136 | \$ 7,933.00 | 6% | \$7,512.95 |
| PW 4HR ONSITE 30137 | 95508-30137 | \$ 1,433.00 | 6% | \$1,357.12 |
| PW 4HR ONSITE 30138 | 95508-30138 | \$ 6,605.00 | 6% | \$6,255.27 |
| PW 4HR ONSITE 30139 | 95508-30139 | \$ 12,077.00 | 6% | \$11,437.52 |
| PW 4HR ONSITE 30912 | 95508-30912 | \$ 108.00 | 6% | \$102.28 |

| | | | | |
|---------------------|-------------|-----------|----|-----------------|
| PW 4HR ONSITE 30913 | 95508-30913 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE 31012 | 95508-31012 | \$ 163.00 | 6% | <i>\$154.37</i> |
| PW 4HR ONSITE 31013 | 95508-31013 | \$ 163.00 | 6% | <i>\$154.37</i> |
| PW 4HR ONSITE 31014 | 95508-31014 | \$ 163.00 | 6% | <i>\$154.37</i> |
| PW 4HR ONSITE 31015 | 95508-31015 | \$ 163.00 | 6% | <i>\$154.37</i> |
| PW 4HR ONSITE 31016 | 95508-31016 | \$ 419.00 | 6% | <i>\$396.81</i> |
| PW 4HR ONSITE 31017 | 95508-31017 | \$ 419.00 | 6% | <i>\$396.81</i> |
| PW 4HR ONSITE 31018 | 95508-31018 | \$ 470.00 | 6% | <i>\$445.11</i> |
| PW 4HR ONSITE 31019 | 95508-31019 | \$ 470.00 | 6% | <i>\$445.11</i> |
| PW 4HR ONSITE 31025 | 95508-31025 | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW 4HR ONSITE 31026 | 95508-31026 | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW 4HR ONSITE 31028 | 95508-31028 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW 4HR ONSITE 31029 | 95508-31029 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE 31031 | 95508-31031 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR ONSITE 31032 | 95508-31032 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR ONSITE 31034 | 95508-31034 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE 31035 | 95508-31035 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE 31050 | 95508-31050 | \$ 171.00 | 6% | <i>\$161.95</i> |
| PW 4HR ONSITE 31051 | 95508-31051 | \$ 171.00 | 6% | <i>\$161.95</i> |
| PW 4HR ONSITE 31055 | 95508-31055 | \$ 171.00 | 6% | <i>\$161.95</i> |
| PW 4HR ONSITE 31056 | 95508-31056 | \$ 171.00 | 6% | <i>\$161.95</i> |
| PW 4HR ONSITE 37101 | 95508-37101 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW 4HR ONSITE 37102 | 95508-37102 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW 4HR ONSITE 37103 | 95508-37103 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW 4HR ONSITE 37111 | 95508-37111 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW 4HR ONSITE 37112 | 95508-37112 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW 4HR ONSITE 37113 | 95508-37113 | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW 4HR ONSITE 37114 | 95508-37114 | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW 4HR ONSITE 37115 | 95508-37115 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW 4HR ONSITE 37116 | 95508-37116 | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW 4HR ONSITE 37117 | 95508-37117 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW 4HR ONSITE 37121 | 95508-37121 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 37122 | 95508-37122 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 37123 | 95508-37123 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 37124 | 95508-37124 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 37125 | 95508-37125 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 37126 | 95508-37126 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 37129 | 95508-37129 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 37130 | 95508-37130 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW 4HR ONSITE 39031 | 95508-39031 | \$ 207.00 | 6% | <i>\$196.04</i> |
| PW 4HR ONSITE 39032 | 95508-39032 | \$ 268.00 | 6% | <i>\$253.81</i> |
| PW 4HR ONSITE 39033 | 95508-39033 | \$ 207.00 | 6% | <i>\$196.04</i> |

| | | | | |
|-------------------------------|-----------------------|--------------|----|--------------------|
| PW 4HR ONSITE 39034 | 95508-39034 | \$ 207.00 | 6% | <i>\$196.04</i> |
| PW 4HR ONSITE 39035 | 95508-39035 | \$ 1,195.00 | 6% | <i>\$1,131.72</i> |
| PW 4HR ONSITE 39036 | 95508-39036 | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE 39037 | 95508-39037 | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE 39038 | 95508-39038 | \$ 303.00 | 6% | <i>\$286.96</i> |
| PW 4HR ONSITE 39039 | 95508-39039 | \$ 303.00 | 6% | <i>\$286.96</i> |
| PW 4HR ONSITE 39505 | 95508-39505 | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW 4HR ONSITE 4120-24MW-4Y | 95508-4120-24MW-4Y | \$ 1,124.00 | 6% | <i>\$1,064.48</i> |
| PW 4HR ONSITE 4120-48MW-4Y | 95508-4120-48MW-4Y | \$ 1,499.00 | 6% | <i>\$1,419.63</i> |
| PW 4HR ONSITE 4120C | 95508-4120C | \$ 8,099.00 | 6% | <i>\$7,670.16</i> |
| PW 4HR ONSITE 4120C-1 | 95508-4120C-1 | \$ 9,143.00 | 6% | <i>\$8,658.88</i> |
| PW 4HR ONSITE 41216 | 95508-41216 | \$ 2,501.00 | 6% | <i>\$2,368.57</i> |
| PW 4HR ONSITE 4220-12P-4X | 95508-4220-12P-4X | \$ 326.00 | 6% | <i>\$308.74</i> |
| PW 4HR ONSITE 4220-12T-4X | 95508-4220-12T-4X | \$ 239.00 | 6% | <i>\$226.34</i> |
| PW 4HR ONSITE 4220-24P-4X | 95508-4220-24P-4X | \$ 435.00 | 6% | <i>\$411.97</i> |
| PW 4HR ONSITE 4220-24T-4X | 95508-4220-24T-4X | \$ 337.00 | 6% | <i>\$319.16</i> |
| PW 4HR ONSITE 4220-48P-4X | 95508-4220-48P-4X | \$ 653.00 | 6% | <i>\$618.42</i> |
| PW 4HR ONSITE 4220-48T-4X | 95508-4220-48T-4X | \$ 490.00 | 6% | <i>\$464.05</i> |
| PW 4HR ONSITE 4220-4MW-20P-4X | 95508-4220-4MW-20P-4X | \$ 599.00 | 6% | <i>\$567.28</i> |
| PW 4HR ONSITE 4220-4MW-8P-4X | 95508-4220-4MW-8P-4X | \$ 425.00 | 6% | <i>\$402.50</i> |
| PW 4HR ONSITE 4220-8MW-40P-4X | 95508-4220-8MW-40P-4X | \$ 871.00 | 6% | <i>\$824.88</i> |
| PW 4HR ONSITE 4220-8X | 95508-4220-8X | \$ 457.00 | 6% | <i>\$432.80</i> |
| PW 4HR ONSITE BD X 48001 | 95508-48001 | \$ 10,388.00 | 6% | <i>\$9,837.96</i> |
| PW 4HR ONSITE 48038 | 95508-48038 | \$ 4,165.00 | 6% | <i>\$3,944.46</i> |
| PW 4HR ONSITE 48039 | 95508-48039 | \$ 4,165.00 | 6% | <i>\$3,944.46</i> |
| PW 4hr On-site-48040 | 95508-48040 | \$ 3,945.00 | 6% | <i>\$3,736.11</i> |
| PW 4HR ONSITE BD X 48041 | 95508-48041 | \$ 4,165.00 | 6% | <i>\$3,944.46</i> |
| PW 4HR ONSITE BD X 48046 | 95508-48046 | \$ 5,463.00 | 6% | <i>\$5,173.73</i> |
| PW 4HR ONSITE 48047 | 95508-48047 | \$ 14,566.00 | 6% | <i>\$13,794.73</i> |

| | | | | |
|-----------------------------------|---------------------------|--------------|----|--------------------|
| PW 4HR ONSITE BD X 48051 | 95508-48051 | \$ 10,010.00 | 6% | <i>\$9,479.97</i> |
| PW 4HR ONSITE 48061 | 95508-48061 | \$ 11,707.00 | 6% | <i>\$11,087.11</i> |
| PW 4HR ONSITE 48062 | 95508-48062 | \$ 18,722.00 | 6% | <i>\$17,730.67</i> |
| PW 4HR ONSITE 5320-16P-4XE | 95508-5320-16P-4XE | \$ 416.00 | 6% | <i>\$393.97</i> |
| PW 4HR ONSITE 5320-16P-4XE-DC | 95508-5320-16P-4XE-DC | \$ 500.00 | 6% | <i>\$473.53</i> |
| PW 4HR ONSITE 5320-24P-8XE | 95508-5320-24P-8XE | \$ 459.00 | 6% | <i>\$434.70</i> |
| PW 4HR ONSITE 5320-24T-24S-4XE-XT | 95508-5320-24T-24S-4XE-XT | \$ 708.00 | 6% | <i>\$670.51</i> |
| PW 4HR ONSITE 5320-24T-4X-XT | 95508-5320-24T-4X-XT | \$ 381.00 | 6% | <i>\$360.83</i> |
| PW 4HR ONSITE 5320-24T-8XE | 95508-5320-24T-8XE | \$ 325.00 | 6% | <i>\$307.79</i> |
| PW 4HR ONSITE 5320-48P-8XE | 95508-5320-48P-8XE | \$ 769.00 | 6% | <i>\$728.28</i> |
| PW 4HR ONSITE 5320-48T-8XE | 95508-5320-48T-8XE | \$ 519.00 | 6% | <i>\$491.52</i> |
| PW 4HR ONSITE 5420F-16MW-32P-4XE | 95508-5420F-16MW-32P-4XE | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| PW 4HR ONSITE 5420F-16W-32P-4XE | 95508-5420F-16W-32P-4XE | \$ 1,318.00 | 6% | <i>\$1,248.21</i> |
| PW 4HR ONSITE 5420F-24P-4XE | 95508-5420F-24P-4XE | \$ 589.00 | 6% | <i>\$557.81</i> |
| PW 4HR ONSITE 5420F-24S-4XE | 95508-5420F-24S-4XE | \$ 645.00 | 6% | <i>\$610.85</i> |
| PW 4HR ONSITE 5420F-24T-4XE | 95508-5420F-24T-4XE | \$ 486.00 | 6% | <i>\$460.27</i> |
| PW 4HR ONSITE 5420F-48P-4XE | 95508-5420F-48P-4XE | \$ 919.00 | 6% | <i>\$870.34</i> |
| PW 4HR ONSITE 5420F-48P-4XL | 95508-5420F-48P-4XL | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| PW 4HR ONSITE 5420F-48T-4XE | 95508-5420F-48T-4XE | \$ 658.00 | 6% | <i>\$623.16</i> |
| PW 4HR ONSITE 5420F-8W-16P-4XE | 95508-5420F-8W-16P-4XE | \$ 672.00 | 6% | <i>\$636.42</i> |
| PW 4HR ONSITE 5420M-16MW-32P-4YE | 95508-5420M-16MW-32P-4YE | \$ 1,494.00 | 6% | <i>\$1,414.89</i> |

| | | | | |
|-----------------------------------|---------------------------|-------------|----|-------------------|
| PW 4HR ONSITE 5420M-24T-4YE | 95508-5420M-24T-4YE | \$ 649.00 | 6% | <i>\$614.64</i> |
| PW 4HR ONSITE 5420M-24W-4YE | 95508-5420M-24W-4YE | \$ 607.00 | 6% | <i>\$574.86</i> |
| PW 4HR ONSITE 5420M-48T-4YE | 95508-5420M-48T-4YE | \$ 888.00 | 6% | <i>\$840.98</i> |
| PW 4HR ONSITE 5420M-48W-4YE | 95508-5420M-48W-4YE | \$ 1,051.00 | 6% | <i>\$995.35</i> |
| PW 4HR ONSITE 5520-12MW-36W | 95508-5520-12MW-36W | \$ 1,611.00 | 6% | <i>\$1,525.70</i> |
| PW 4HR ONSITE 5520-24T | 95508-5520-24T | \$ 581.00 | 6% | <i>\$550.24</i> |
| PW 4HR ONSITE 5520-24T-ACDC-BASE | 95508-5520-24T-ACDC-BASE | \$ 581.00 | 6% | <i>\$550.24</i> |
| PW 4HR ONSITE 5520-24T-BASE | 95508-5520-24T-BASE | \$ 581.00 | 6% | <i>\$550.24</i> |
| PW 4HR ONSITE 5520-24W | 95508-5520-24W | \$ 885.00 | 6% | <i>\$838.14</i> |
| PW 4HR ONSITE 5520-24X | 95508-5520-24X | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| PW 4HR ONSITE 5520-24X-ACDC-BASE | 95508-5520-24X-ACDC-BASE | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| PW 4HR ONSITE 5520-24X-BASE | 95508-5520-24X-BASE | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| PW 4HR ONSITE 5520-48SE | 95508-5520-48SE | \$ 1,720.00 | 6% | <i>\$1,628.93</i> |
| PW 4HR ONSITE 5520-48SE-ACDC-BASE | 95508-5520-48SE-ACDC-BASE | \$ 1,720.00 | 6% | <i>\$1,628.93</i> |
| PW 4HR ONSITE 5520-48SE-BASE | 95508-5520-48SE-BASE | \$ 1,720.00 | 6% | <i>\$1,628.93</i> |
| PW 4HR ONSITE 5520-48T | 95508-5520-48T | \$ 996.00 | 6% | <i>\$943.26</i> |
| PW 4HR ONSITE 5520-48T-ACDC-BASE | 95508-5520-48T-ACDC-BASE | \$ 996.00 | 6% | <i>\$943.26</i> |
| PW 4HR ONSITE 5520-48T-BASE | 95508-5520-48T-BASE | \$ 996.00 | 6% | <i>\$943.26</i> |
| PW 4HR ONSITE 5520-48W | 95508-5520-48W | \$ 1,295.00 | 6% | <i>\$1,226.43</i> |

| | | | | |
|----------------------------------|--------------------------|-------------|----|-------------------|
| PW 4HR ONSITE 5720-24MW | 95508-5720-24MW | \$ 2,039.00 | 6% | <i>\$1,931.03</i> |
| PW 4HR ONSITE 5720-24MXW | 95508-5720-24MXW | \$ 2,759.00 | 6% | <i>\$2,612.91</i> |
| PW 4HR ONSITE 5720-48MW | 95508-5720-48MW | \$ 2,399.00 | 6% | <i>\$2,271.97</i> |
| PW 4HR ONSITE 5720-48MXW | 95508-5720-48MXW | \$ 3,479.00 | 6% | <i>\$3,294.79</i> |
| PW 4HR ONSITE 7520-48XT-6C | 95508-7520-48XT-6C | \$ 4,021.00 | 6% | <i>\$3,808.09</i> |
| PW 4HR ONSITE 7520-48XT-6C-AC-F | 95508-7520-48XT-6C-AC-F | \$ 4,021.00 | 6% | <i>\$3,808.09</i> |
| PW 4HR ONSITE 7520-48XT-6C-AC-R | 95508-7520-48XT-6C-AC-R | \$ 4,021.00 | 6% | <i>\$3,808.09</i> |
| PW 4HR ONSITE 7520-48Y-8C | 95508-7520-48Y-8C | \$ 3,758.00 | 6% | <i>\$3,559.01</i> |
| PW 4HR ONSITE 7520-48Y-8C-AC-F | 95508-7520-48Y-8C-AC-F | \$ 3,758.00 | 6% | <i>\$3,559.01</i> |
| PW 4HR ONSITE 7520-48Y-8C-AC-R | 95508-7520-48Y-8C-AC-R | \$ 3,758.00 | 6% | <i>\$3,559.01</i> |
| PW 4HR ONSITE 7520-48YE-8CE | 95508-7520-48YE-8CE | \$ 4,354.00 | 6% | <i>\$4,123.46</i> |
| PW 4HR ONSITE 7520-48YE-8CE-AC-F | 95508-7520-48YE-8CE-AC-F | \$ 4,354.00 | 6% | <i>\$4,123.46</i> |
| PW 4HR ONSITE 7520-48YE-8CE-AC-R | 95508-7520-48YE-8CE-AC-R | \$ 4,354.00 | 6% | <i>\$4,123.46</i> |
| PW 4HR ONSITE 7720-32C | 95508-7720-32C | \$ 4,638.00 | 6% | <i>\$4,392.42</i> |
| PW 4HR ONSITE 7720-32C-AC-F | 95508-7720-32C-AC-F | \$ 4,638.00 | 6% | <i>\$4,392.42</i> |
| PW 4HR ONSITE 7720-32C-AC-R | 95508-7720-32C-AC-R | \$ 4,638.00 | 6% | <i>\$4,392.42</i> |
| PW 4HR ONSITE 8520-48XT-6C | 95508-8520-48XT-6C | \$ 3,186.00 | 6% | <i>\$3,017.30</i> |
| PW 4HR ONSITE 8520-48XT-6C-AC-F | 95508-8520-48XT-6C-AC-F | \$ 3,186.00 | 6% | <i>\$3,017.30</i> |

| | | | | |
|---------------------------------|-------------------------|--------------|----|-------------|
| PW 4HR ONSITE 8520-48XT-6C-AC-R | 95508-8520-48XT-6C-AC-R | \$ 3,186.00 | 6% | \$3,017.30 |
| PW 4HR ONSITE 8520-48XT-6C-DC-F | 95508-8520-48XT-6C-DC-F | \$ 3,186.00 | 6% | \$3,017.30 |
| PW 4HR ONSITE 8520-48XT-6C-DC-R | 95508-8520-48XT-6C-DC-R | \$ 3,186.00 | 6% | \$3,017.30 |
| PW 4HR ONSITE 8520-48Y-8C | 95508-8520-48Y-8C | \$ 3,236.00 | 6% | \$3,064.65 |
| PW 4HR ONSITE 8520-48Y-8C-AC-F | 95508-8520-48Y-8C-AC-F | \$ 3,236.00 | 6% | \$3,064.65 |
| PW 4HR ONSITE 8520-48Y-8C-AC-R | 95508-8520-48Y-8C-AC-R | \$ 3,236.00 | 6% | \$3,064.65 |
| PW 4HR ONSITE 8520-48Y-8C-DC-F | 95508-8520-48Y-8C-DC-F | \$ 3,236.00 | 6% | \$3,064.65 |
| PW 4HR ONSITE 8520-48Y-8C-DC-R | 95508-8520-48Y-8C-DC-R | \$ 3,236.00 | 6% | \$3,064.65 |
| PW 4HR ONSITE 86100 | 95508-86100 | \$ 5,832.00 | 6% | \$5,523.20 |
| PW 4HR ONSITE 86101 | 95508-86101 | \$ 8,016.00 | 6% | \$7,591.55 |
| PW 4HR ONSITE 87100 | 95508-87100 | \$ 3,624.00 | 6% | \$3,432.11 |
| PW 4HR ONSITE 87101 | 95508-87101 | \$ 5,566.00 | 6% | \$5,271.28 |
| PW 4HR ONSITE 8720-32C | 95508-8720-32C | \$ 3,725.00 | 6% | \$3,527.76 |
| PW 4HR ONSITE 8720-32C-AC-F | 95508-8720-32C-AC-F | \$ 3,725.00 | 6% | \$3,527.76 |
| PW 4HR ONSITE 8720-32C-AC-R | 95508-8720-32C-AC-R | \$ 3,725.00 | 6% | \$3,527.76 |
| PW 4HR ONSITE 8720-32C-DC-F | 95508-8720-32C-DC-F | \$ 3,725.00 | 6% | \$3,527.76 |
| PW 4HR ONSITE 8720-32C-DC-R | 95508-8720-32C-DC-R | \$ 3,725.00 | 6% | \$3,527.76 |
| PW 24X7X4 Onsite 8806 | 95508-8806 | \$ 2,605.00 | 6% | \$2,467.07 |
| PW 24X7X4 Onsite ASPEN | 95508-8810 | \$ 6,899.00 | 6% | \$6,533.70 |
| PW 4HR ONSITE 88100 | 95508-88100 | \$ 6,582.00 | 6% | \$6,233.48 |
| PW 4HR ONSITE 8820-40C | 95508-8820-40C | \$ 13,922.00 | 6% | \$13,184.83 |
| PW 4HR ONSITE 8820-40C-AC-F | 95508-8820-40C-AC-F | \$ 13,922.00 | 6% | \$13,184.83 |
| PW 4HR ONSITE 8820-40C-AC-R | 95508-8820-40C-AC-R | \$ 13,922.00 | 6% | \$13,184.83 |

| | | | | |
|---------------------------------|-------------------------|--------------|----|--------------------|
| PW 4HR ONSITE 8820-40C-DC-F | 95508-8820-40C-DC-F | \$ 13,922.00 | 6% | <i>\$13,184.83</i> |
| PW 4HR ONSITE 8820-40C-DC-R | 95508-8820-40C-DC-R | \$ 13,922.00 | 6% | <i>\$13,184.83</i> |
| PW 4HR ONSITE 8820-80C | 95508-8820-80C | \$ 25,433.00 | 6% | <i>\$24,086.32</i> |
| PW 4HR ONSITE 8820-80C-AC-F | 95508-8820-80C-AC-F | \$ 25,433.00 | 6% | <i>\$24,086.32</i> |
| PW 4HR ONSITE 8820-80C-AC-R | 95508-8820-80C-AC-R | \$ 25,433.00 | 6% | <i>\$24,086.32</i> |
| PW 4HR ONSITE 8820-80C-DC-F | 95508-8820-80C-DC-F | \$ 25,433.00 | 6% | <i>\$24,086.32</i> |
| PW 4HR ONSITE 8820-80C-DC-R | 95508-8820-80C-DC-R | \$ 25,433.00 | 6% | <i>\$24,086.32</i> |
| PW 4HR ONSITE 9920-16C | 95508-9920-16C | \$ 12,231.00 | 6% | <i>\$11,583.37</i> |
| PW 4HR ONSITE 9920-4D | 95508-9920-4D | \$ 12,231.00 | 6% | <i>\$11,583.37</i> |
| PW 4HR ONSITE 9920-NPB-8 | 95508-9920-NPB-8 | \$ 18,287.00 | 6% | <i>\$17,318.70</i> |
| PW 4hr On-Site | 95508-A10148 | \$ 3,278.00 | 6% | <i>\$3,104.43</i> |
| PW 4hr On-Site | 95508-A10149 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| PW 4hr On-Site | 95508-A10152 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| PW 4hr On-Site | 95508-A10154 | \$ 19,050.00 | 6% | <i>\$18,041.30</i> |
| PW 4hr On-Site | 95508-A10155 | \$ 6,740.00 | 6% | <i>\$6,383.12</i> |
| PW 4hr On-Site | 95508-A10157 | \$ 11,898.00 | 6% | <i>\$11,268.00</i> |
| PW 4HR ONSITE 10175 | 95508-A10175 | \$ 9,554.00 | 6% | <i>\$9,048.12</i> |
| PW 4HR ONSITE A10176 | 95508-A10176 | \$ 14,333.00 | 6% | <i>\$13,574.07</i> |
| PW 4HR ONSITE AH-AP-1130-AC-CE | 95508-AH-AP-1130-AC-CE | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE AH-AP-1130-AC-FCC | 95508-AH-AP-1130-AC-FCC | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE AH-AP-1130-AC-W | 95508-AH-AP-1130-AC-W | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE AH-AP-122-AC-CAN | 95508-AH-AP-122-AC-CAN | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-122-AC-CE | 95508-AH-AP-122-AC-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-122-AC-FCC | 95508-AH-AP-122-AC-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-122-AC-W | 95508-AH-AP-122-AC-W | \$ 105.00 | 6% | <i>\$99.44</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|----|-----------------|
| PW 4HR ONSITE AH-AP-130-AC-CE | 95508-AH-AP-130-AC-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-130-AC-FCC | 95508-AH-AP-130-AC-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-130-AC-W | 95508-AH-AP-130-AC-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-150W-AC-CAN | 95508-AH-AP-150W-AC-CAN | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-150W-AC-CE | 95508-AH-AP-150W-AC-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-150W-AC-FCC | 95508-AH-AP-150W-AC-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-150W-AC-W | 95508-AH-AP-150W-AC-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-230-AC-CE | 95508-AH-AP-230-AC-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-230-AC-FCC | 95508-AH-AP-230-AC-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-230-AC-W | 95508-AH-AP-230-AC-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-250-AC-CAN | 95508-AH-AP-250-AC-CAN | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-250-AC-CE | 95508-AH-AP-250-AC-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-250-AC-FCC | 95508-AH-AP-250-AC-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-250-AC-W | 95508-AH-AP-250-AC-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-AP-630-AX-CAN | 95508-AH-AP-630-AX-CAN | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW 4HR ONSITE AH-AP-630-AX-CE | 95508-AH-AP-630-AX-CE | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW 4HR ONSITE AH-AP-630-AX-FCC | 95508-AH-AP-630-AX-FCC | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW 4HR ONSITE AH-AP-630-AX-W | 95508-AH-AP-630-AX-W | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW 4HR ONSITE AH-AP-650-AX-CAN | 95508-AH-AP-650-AX-CAN | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE AH-AP-650-AX-CE | 95508-AH-AP-650-AX-CE | \$ 158.00 | 6% | <i>\$149.63</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|----|-----------------|
| PW 4HR ONSITE AH-AP-650-AX-FCC | 95508-AH-AP-650-AX-FCC | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE AH-AP-650-AX-W | 95508-AH-AP-650-AX-W | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE AH-AP-650X-AX-CAN | 95508-AH-AP-650X-AX-CAN | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE AH-AP-650X-AX-CE | 95508-AH-AP-650X-AX-CE | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE AH-AP-650X-AX-FCC | 95508-AH-AP-650X-AX-FCC | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE AH-AP-650X-AX-W | 95508-AH-AP-650X-AX-W | \$ 158.00 | 6% | <i>\$149.63</i> |
| PW 4HR ONSITE AH-ATOM-CAN | 95508-AH-ATOM-CAN | \$ 106.00 | 6% | <i>\$100.39</i> |
| PW 4HR ONSITE AH-ATOM-CE-EU | 95508-AH-ATOM-CE-EU | \$ 111.00 | 6% | <i>\$105.12</i> |
| PW 4HR ONSITE AH-ATOM-CE-UK | 95508-AH-ATOM-CE-UK | \$ 111.00 | 6% | <i>\$105.12</i> |
| PW 4HR ONSITE AH-ATOM-FCC | 95508-AH-ATOM-FCC | \$ 106.00 | 6% | <i>\$100.39</i> |
| PW 4HR ONSITE AH-ATOM-W | 95508-AH-ATOM-W | \$ 106.00 | 6% | <i>\$100.39</i> |
| PW 4HR ONSITE AH-ATOM-W-EU | 95508-AH-ATOM-W-EU | \$ 111.00 | 6% | <i>\$105.12</i> |
| PW 4HR ONSITE AH-ATOM-W-UK | 95508-AH-ATOM-W-UK | \$ 111.00 | 6% | <i>\$105.12</i> |
| PW 4HR ONSITE AH-SR-2208P-AU | 95508-AH-SR-2208P-AU | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-SR-2208P-EU | 95508-AH-SR-2208P-EU | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-SR-2208P-NA | 95508-AH-SR-2208P-NA | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-SR-2208P-UK | 95508-AH-SR-2208P-UK | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-SR-2224P-AU | 95508-AH-SR-2224P-AU | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AH-SR-2224P-EU | 95508-AH-SR-2224P-EU | \$ 156.00 | 6% | <i>\$147.74</i> |

| | | | | |
|------------------------------|----------------------|-----------|----|-----------------|
| PW 4HR ONSITE AH-SR-2224P-NA | 95508-AH-SR-2224P-NA | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AH-SR-2224P-UK | 95508-AH-SR-2224P-UK | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AH-SR-2324P-AU | 95508-AH-SR-2324P-AU | \$ 215.00 | 6% | <i>\$203.62</i> |
| PW 4HR ONSITE AH-SR-2324P-EU | 95508-AH-SR-2324P-EU | \$ 215.00 | 6% | <i>\$203.62</i> |
| PW 4HR ONSITE AH-SR-2324P-NA | 95508-AH-SR-2324P-NA | \$ 215.00 | 6% | <i>\$203.62</i> |
| PW 4HR ONSITE AH-SR-2324P-UK | 95508-AH-SR-2324P-UK | \$ 215.00 | 6% | <i>\$203.62</i> |
| PW 4HR ONSITE AH-SR-2348P-AU | 95508-AH-SR-2348P-AU | \$ 377.00 | 6% | <i>\$357.04</i> |
| PW 4HR ONSITE AH-SR-2348P-EU | 95508-AH-SR-2348P-EU | \$ 377.00 | 6% | <i>\$357.04</i> |
| PW 4HR ONSITE AH-SR-2348P-NA | 95508-AH-SR-2348P-NA | \$ 377.00 | 6% | <i>\$357.04</i> |
| PW 4HR ONSITE AH-SR-2348P-UK | 95508-AH-SR-2348P-UK | \$ 377.00 | 6% | <i>\$357.04</i> |
| PW 4HR ONSITE AH-XR200P-AU | 95508-AH-XR200P-AU | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-XR200P-EU | 95508-AH-XR200P-EU | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-XR200P-UK | 95508-AH-XR200P-UK | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-XR200P-US | 95508-AH-XR200P-US | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AH-XR600P | 95508-AH-XR600P | \$ 113.00 | 6% | <i>\$107.02</i> |
| PW 4HR ONSITE AH-XR600P-AU | 95508-AH-XR600P-AU | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW 4HR ONSITE AH-XR600P-EU | 95508-AH-XR600P-EU | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW 4HR ONSITE AH-XR600P-KR | 95508-AH-XR600P-KR | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW 4HR ONSITE AH-XR600P-UK | 95508-AH-XR600P-UK | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW 4HR ONSITE AH-XR600P-US | 95508-AH-XR600P-US | \$ 119.00 | 6% | <i>\$112.70</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|----|-----------------|
| PW 4HR ONSITE AP-8533-68SB30-IL | 95508-AP-8533-68SB30-IL | \$ 196.00 | 6% | <i>\$185.62</i> |
| PW 4HR ONSITE AP3000-IL | 95508-AP3000-IL | \$ 90.00 | 6% | <i>\$85.23</i> |
| PW 4HR ONSITE AP3000-TN | 95508-AP3000-TN | \$ 90.00 | 6% | <i>\$85.23</i> |
| PW 4HR ONSITE AP3000-WW | 95508-AP3000-WW | \$ 90.00 | 6% | <i>\$85.23</i> |
| PW 4HR ONSITE AP3000X-WW | 95508-AP3000X-WW | \$ 115.00 | 6% | <i>\$108.91</i> |
| PW 4HR ONSITE AP302W-CAN | 95508-AP302W-CAN | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW 4HR ONSITE AP302W-EG | 95508-AP302W-EG | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW 4HR ONSITE AP302W-FCC | 95508-AP302W-FCC | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW 4HR ONSITE AP302W-WR | 95508-AP302W-WR | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR ONSITE AP305C-1-CAN | 95508-AP305C-1-CAN | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AP305C-1-EG | 95508-AP305C-1-EG | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AP305C-1-FCC | 95508-AP305C-1-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AP305C-1-IL | 95508-AP305C-1-IL | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AP305C-1-WR | 95508-AP305C-1-WR | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW 4HR ONSITE AP305C-CAN | 95508-AP305C-CAN | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP305C-EG | 95508-AP305C-EG | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP305C-FCC | 95508-AP305C-FCC | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP305C-IL | 95508-AP305C-IL | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP305C-WR | 95508-AP305C-WR | \$ 112.00 | 6% | <i>\$106.07</i> |

| | | | | |
|---------------------------|-------------------|-----------|----|-----------------|
| PW 4HR ONSITE AP305CX-CAN | 95508-AP305CX-CAN | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP305CX-FCC | 95508-AP305CX-FCC | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP305CX-IL | 95508-AP305CX-IL | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP305CX-WR | 95508-AP305CX-WR | \$ 112.00 | 6% | <i>\$106.07</i> |
| PW 4HR ONSITE AP310e-1-WR | 95508-AP310e-1-WR | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW 4HR ONSITE AP310e-CAN | 95508-AP310e-CAN | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP310e-FCC | 95508-AP310e-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP310e-IL | 95508-AP310e-IL | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP310e-WR | 95508-AP310e-WR | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP310i-1-WR | 95508-AP310i-1-WR | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW 4HR ONSITE AP310i-CAN | 95508-AP310i-CAN | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP310i-FCC | 95508-AP310i-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP310i-IL | 95508-AP310i-IL | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP310i-WR | 95508-AP310i-WR | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW 4HR ONSITE AP360e-CAN | 95508-AP360e-CAN | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE AP360e-FCC | 95508-AP360e-FCC | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE AP360e-IL | 95508-AP360e-IL | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE AP360e-WR | 95508-AP360e-WR | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE AP360i-CAN | 95508-AP360i-CAN | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE AP360i-FCC | 95508-AP360i-FCC | \$ 101.00 | 6% | <i>\$95.65</i> |

| | | | | |
|----------------------------|--------------------|-----------|----|-----------------|
| PW 4HR ONSITE AP360i-WR | 95508-AP360i-WR | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE AP4000-WW | 95508-AP4000-1-WW | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR ONSITE AP4000-IL | 95508-AP4000-IL | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR ONSITE AP4000-WW | 95508-AP4000-WW | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW 4HR ONSITE AP410C-1-CAN | 95508-AP410C-1-CAN | \$ 118.00 | 6% | <i>\$111.75</i> |
| PW 4HR ONSITE AP410C-1-EG | 95508-AP410C-1-EG | \$ 118.00 | 6% | <i>\$111.75</i> |
| PW 4HR ONSITE AP410C-1-FCC | 95508-AP410C-1-FCC | \$ 118.00 | 6% | <i>\$111.75</i> |
| PW 4HR ONSITE AP410C-1-IL | 95508-AP410C-1-IL | \$ 118.00 | 6% | <i>\$111.75</i> |
| PW 4HR ONSITE AP410C-1-WR | 95508-AP410C-1-WR | \$ 118.00 | 6% | <i>\$111.75</i> |
| PW 4HR ONSITE AP410C-CAN | 95508-AP410C-CAN | \$ 127.00 | 6% | <i>\$120.28</i> |
| PW 4HR ONSITE AP410C-EG | 95508-AP410C-EG | \$ 127.00 | 6% | <i>\$120.28</i> |
| PW 4HR ONSITE AP410C-FCC | 95508-AP410C-FCC | \$ 127.00 | 6% | <i>\$120.28</i> |
| PW 4HR ONSITE AP410C-IL | 95508-AP410C-IL | \$ 127.00 | 6% | <i>\$120.28</i> |
| PW 4HR ONSITE AP410C-WR | 95508-AP410C-WR | \$ 127.00 | 6% | <i>\$120.28</i> |
| PW 4HR ONSITE AP410e-CAN | 95508-AP410e-CAN | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR ONSITE AP410e-FCC | 95508-AP410e-FCC | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR ONSITE AP410e-WR | 95508-AP410e-WR | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR ONSITE AP410i-1-FCC | 95508-AP410i-1-FCC | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW 4HR ONSITE AP410i-1-WR | 95508-AP410i-1-WR | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW 4HR ONSITE AP410i-CAN | 95508-AP410i-CAN | \$ 122.00 | 6% | <i>\$115.54</i> |

| | | | | |
|-----------------------------|---------------------|-----------|----|-----------------|
| PW 4HR ONSITE AP410i-FCC | 95508-AP410i-FCC | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR ONSITE AP410i-IL | 95508-AP410i-IL | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR ONSITE AP410i-WR | 95508-AP410i-WR | \$ 122.00 | 6% | <i>\$115.54</i> |
| PW 4HR ONSITE AP460C-CAN | 95508-AP460C-CAN | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460C-EG | 95508-AP460C-EG | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460C-FCC | 95508-AP460C-FCC | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460C-IL | 95508-AP460C-IL | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460C-WR | 95508-AP460C-WR | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460e-CAN | 95508-AP460e-CAN | \$ 142.00 | 6% | <i>\$134.48</i> |
| PW 4HR ONSITE AP460e-FCC | 95508-AP460e-FCC | \$ 142.00 | 6% | <i>\$134.48</i> |
| PW 4HR ONSITE AP460e-WR | 95508-AP460e-WR | \$ 135.00 | 6% | <i>\$127.85</i> |
| PW 4HR ONSITE AP460i-CAN | 95508-AP460i-CAN | \$ 135.00 | 6% | <i>\$127.85</i> |
| PW 4HR ONSITE AP460i-FCC | 95508-AP460i-FCC | \$ 135.00 | 6% | <i>\$127.85</i> |
| PW 4HR ONSITE AP460i-IL | 95508-AP460i-IL | \$ 135.00 | 6% | <i>\$127.85</i> |
| PW 4HR ONSITE AP460i-WR | 95508-AP460i-WR | \$ 135.00 | 6% | <i>\$127.85</i> |
| PW 4HR ONSITE AP460S12C-CAN | 95508-AP460S12C-CAN | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460S12C-FCC | 95508-AP460S12C-FCC | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460S12C-WR | 95508-AP460S12C-WR | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460S6C-CAN | 95508-AP460S6C-CAN | \$ 156.00 | 6% | <i>\$147.74</i> |

| | | | | |
|------------------------------|----------------------|-----------|----|-----------------|
| PW 4HR ONSITE AP460S6C-FCC | 95508-AP460S6C-FCC | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP460S6C-WR | 95508-AP460S6C-WR | \$ 156.00 | 6% | <i>\$147.74</i> |
| PW 4HR ONSITE AP5010-IL | 95508-AP5010-IL | \$ 200.00 | 6% | <i>\$189.41</i> |
| PW 4HR ONSITE AP5010-WW | 95508-AP5010-WW | \$ 200.00 | 6% | <i>\$189.41</i> |
| PW 4HR ONSITE AP5020-WW | 95508-AP5020-WW | \$ 239.90 | 6% | <i>\$227.20</i> |
| PW 4HR ONSITE AP5050D-WW | 95508-AP5050D-WW | \$ 450.00 | 6% | <i>\$426.17</i> |
| PW 4HR ONSITE AP5050U-WW | 95508-AP5050U-WW | \$ 351.00 | 6% | <i>\$332.41</i> |
| PW 4HR ONSITE AP505i-FCC | 95508-AP505i-FCC | \$ 150.00 | 6% | <i>\$142.06</i> |
| PW 4HR ONSITE AP505i-FCC-TAA | 95508-AP505i-FCC-TAA | \$ 150.00 | 6% | <i>\$142.06</i> |
| PW 4HR ONSITE AP505i-WR | 95508-AP505i-WR | \$ 157.00 | 6% | <i>\$148.69</i> |
| PW 4HR ONSITE AP510C-CAN | 95508-AP510C-CAN | \$ 153.00 | 6% | <i>\$144.90</i> |
| PW 4HR ONSITE AP510C-CE | 95508-AP510C-CE | \$ 153.00 | 6% | <i>\$144.90</i> |
| PW 4HR ONSITE AP510C-FCC | 95508-AP510C-FCC | \$ 153.00 | 6% | <i>\$144.90</i> |
| PW 4HR ONSITE AP510C-W | 95508-AP510C-W | \$ 153.00 | 6% | <i>\$144.90</i> |
| PW 4HR ONSITE AP510C-WW | 95508-AP510C-WW | \$ 177.00 | 6% | <i>\$167.63</i> |
| PW 4HR ONSITE AP510CX-CAN | 95508-AP510CX-CAN | \$ 153.00 | 6% | <i>\$144.90</i> |
| PW 4HR ONSITE AP510CX-CE | 95508-AP510CX-CE | \$ 153.00 | 6% | <i>\$144.90</i> |
| PW 4HR ONSITE AP510CX-FCC | 95508-AP510CX-FCC | \$ 153.00 | 6% | <i>\$144.90</i> |
| PW 4HR ONSITE AP510CX-W | 95508-AP510CX-W | \$ 153.00 | 6% | <i>\$144.90</i> |

| | | | | |
|------------------------------|----------------------|--------------|----|--------------------|
| PW 4HR ONSITE AP510CX-WW | 95508-AP510CX-WW | \$ 177.00 | 6% | <i>\$167.63</i> |
| PW 4HR ONSITE AP510e-FCC | 95508-AP510e-FCC | \$ 200.00 | 6% | <i>\$189.41</i> |
| PW 4HR ONSITE AP510e-FCC-TAA | 95508-AP510e-FCC-TAA | \$ 200.00 | 6% | <i>\$189.41</i> |
| PW 4HR ONSITE AP510e-WR | 95508-AP510e-WR | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW 4HR ONSITE AP510i-1-FCC | 95508-AP510i-1-FCC | \$ 168.00 | 6% | <i>\$159.10</i> |
| PW 4HR ONSITE AP510i-1-WR | 95508-AP510i-1-WR | \$ 168.00 | 6% | <i>\$159.10</i> |
| PW 4HR ONSITE AP510i-FCC | 95508-AP510i-FCC | \$ 176.00 | 6% | <i>\$166.68</i> |
| PW 4HR ONSITE AP510i-FCC-TAA | 95508-AP510i-FCC-TAA | \$ 176.00 | 6% | <i>\$166.68</i> |
| PW 4HR ONSITE AP510i-WR | 95508-AP510i-WR | \$ 176.00 | 6% | <i>\$166.68</i> |
| PW 4HR ONSITE AP560h-FCC | 95508-AP560h-FCC | \$ 439.00 | 6% | <i>\$415.75</i> |
| PW 4HR ONSITE AP560h-WR | 95508-AP560h-WR | \$ 439.00 | 6% | <i>\$415.75</i> |
| PW 4HR ONSITE AP560i-FCC | 95508-AP560i-FCC | \$ 319.00 | 6% | <i>\$302.11</i> |
| PW 4HR ONSITE AP560i-WR | 95508-AP560i-WR | \$ 304.00 | 6% | <i>\$287.90</i> |
| PW 4HR ONSITE AP560m-FCC | 95508-AP560m-FCC | \$ 319.00 | 6% | <i>\$302.11</i> |
| PW 4HR ONSITE AP560t-FCC | 95508-AP560t-FCC | \$ 439.00 | 6% | <i>\$415.75</i> |
| PW 4HR ONSITE AP560u-FCC | 95508-AP560u-FCC | \$ 297.00 | 6% | <i>\$281.27</i> |
| PW 4HR ONSITE E2122 | 95508-E2122 | \$ 7,383.00 | 6% | <i>\$6,992.07</i> |
| PW 4HR ONSITE E2122-1 | 95508-E2122-1 | \$ 6,997.00 | 6% | <i>\$6,626.51</i> |
| PW 4HR ONSITE E3120-1 | 95508-E3120-1 | \$ 11,446.00 | 6% | <i>\$10,839.93</i> |
| PW 4HR ONSITE E3125 | 95508-E3125 | \$ 12,356.00 | 6% | <i>\$11,701.75</i> |
| PW 4hr On-Site | 95508-H30078 | \$ 4,151.00 | 6% | <i>\$3,931.20</i> |
| PW 4hr On-Site | 95508-H30104 | \$ 3,844.00 | 6% | <i>\$3,640.46</i> |
| PW 4hr On-Site | 95508-H30105 | \$ 3,798.00 | 6% | <i>\$3,596.90</i> |
| PW 4hr On-Site | 95508-H30131 | \$ 2,171.00 | 6% | <i>\$2,056.05</i> |
| PW 4hr On-Site | 95508-H30132 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |

| | | | | |
|----------------|--------------|-------------|----|-------------------|
| PW 4hr On-Site | 95508-H30133 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30134 | \$ 7,090.00 | 6% | <i>\$6,714.58</i> |
| PW 4hr On-Site | 95508-H30135 | \$ 5,707.00 | 6% | <i>\$5,404.81</i> |
| PW 4hr On-Site | 95508-H30136 | \$ 7,090.00 | 6% | <i>\$6,714.58</i> |
| PW 4hr On-Site | 95508-H30184 | \$ 91.00 | 6% | <i>\$86.18</i> |
| PW 4hr On-Site | 95508-H30185 | \$ 502.00 | 6% | <i>\$475.42</i> |
| PW 4hr On-Site | 95508-H30186 | \$ 254.00 | 6% | <i>\$240.55</i> |
| PW 4hr On-Site | 95508-H30187 | \$ 100.00 | 6% | <i>\$94.71</i> |
| PW 4hr On-Site | 95508-H30188 | \$ 254.00 | 6% | <i>\$240.55</i> |
| PW 4hr On-Site | 95508-H30189 | \$ 254.00 | 6% | <i>\$240.55</i> |
| PW 4hr On-Site | 95508-H30190 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30214 | \$ 271.00 | 6% | <i>\$256.65</i> |
| PW 4hr On-Site | 95508-H30215 | \$ 271.00 | 6% | <i>\$256.65</i> |
| PW 4hr On-Site | 95508-H30216 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30217 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30218 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30219 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30220 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30221 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30222 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30223 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30224 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30225 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30226 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30227 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30228 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30229 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30267 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30268 | \$ 536.00 | 6% | <i>\$507.62</i> |
| PW 4hr On-Site | 95508-H30269 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30270 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30271 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30272 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30273 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4hr On-Site | 95508-H30274 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4hr On-Site | 95508-H30275 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30276 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30277 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4hr On-Site | 95508-H30278 | \$ 1,293.00 | 6% | <i>\$1,224.54</i> |
| PW 4hr On-Site | 95508-H30279 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4hr On-Site | 95508-H30280 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4hr On-Site | 95508-H30281 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |

| | | | | |
|----------------|--------------|-------------|----|-------------------|
| PW 4hr On-Site | 95508-H30282 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| PW 4hr On-Site | 95508-H30283 | \$ 774.00 | 6% | <i>\$733.02</i> |
| PW 4hr On-Site | 95508-H30284 | \$ 851.00 | 6% | <i>\$805.94</i> |
| PW 4hr On-Site | 95508-H30293 | \$ 4,670.00 | 6% | <i>\$4,422.72</i> |
| PW 4hr On-Site | 95508-H30296 | \$ 271.00 | 6% | <i>\$256.65</i> |
| PW 4hr On-Site | 95508-H30297 | \$ 252.00 | 6% | <i>\$238.66</i> |
| PW 4hr On-Site | 95508-H30298 | \$ 271.00 | 6% | <i>\$256.65</i> |
| PW 4hr On-Site | 95508-H30299 | \$ 252.00 | 6% | <i>\$238.66</i> |
| PW 4hr On-Site | 95508-H30381 | \$ 761.00 | 6% | <i>\$720.71</i> |
| PW 4hr On-Site | 95508-H30384 | \$ 617.00 | 6% | <i>\$584.33</i> |
| PW 4hr On-Site | 95508-H30391 | \$ 1,470.00 | 6% | <i>\$1,392.16</i> |
| PW 4hr On-Site | 95508-H30392 | \$ 1,470.00 | 6% | <i>\$1,392.16</i> |
| PW 4hr On-Site | 95508-H30393 | \$ 650.00 | 6% | <i>\$615.58</i> |
| PW 4hr On-Site | 95508-H30394 | \$ 2,838.00 | 6% | <i>\$2,687.73</i> |
| PW 4hr On-Site | 95508-H30395 | \$ 3,379.00 | 6% | <i>\$3,200.08</i> |
| PW 4hr On-Site | 95508-H30396 | \$ 3,077.00 | 6% | <i>\$2,914.07</i> |
| PW 4hr On-Site | 95508-H30397 | \$ 3,653.00 | 6% | <i>\$3,459.57</i> |
| PW 4hr On-Site | 95508-H30398 | \$ 663.00 | 6% | <i>\$627.89</i> |
| PW 4hr On-Site | 95508-H30400 | \$ 373.00 | 6% | <i>\$353.25</i> |
| PW 4hr On-Site | 95508-H30401 | \$ 512.00 | 6% | <i>\$484.89</i> |
| PW 4hr On-Site | 95508-H30402 | \$ 561.00 | 6% | <i>\$531.30</i> |
| PW 4hr On-Site | 95508-H30403 | \$ 823.00 | 6% | <i>\$779.42</i> |
| PW 4hr On-Site | 95508-H30434 | \$ 218.00 | 6% | <i>\$206.46</i> |
| PW 4hr On-Site | 95508-H30480 | \$ 960.00 | 6% | <i>\$909.17</i> |
| PW 4hr On-Site | 95508-H30495 | \$ 2,171.00 | 6% | <i>\$2,056.05</i> |
| PW 4hr On-Site | 95508-H30496 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| PW 4hr On-Site | 95508-H30497 | \$ 3,136.00 | 6% | <i>\$2,969.95</i> |
| PW 4hr On-Site | 95508-H30498 | \$ 3,077.00 | 6% | <i>\$2,914.07</i> |
| PW 4hr On-Site | 95508-H30499 | \$ 1,049.00 | 6% | <i>\$993.46</i> |
| PW 4hr On-Site | 95508-H30501 | \$ 3,077.00 | 6% | <i>\$2,914.07</i> |
| PW 4hr On-Site | 95508-H30502 | \$ 4,729.00 | 6% | <i>\$4,478.60</i> |
| PW 4hr On-Site | 95508-H30503 | \$ 1,049.00 | 6% | <i>\$993.46</i> |
| PW 4hr On-Site | 95508-H30505 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30506 | \$ 7,610.00 | 6% | <i>\$7,207.05</i> |
| PW 4hr On-Site | 95508-H30509 | \$ 4,729.00 | 6% | <i>\$4,478.60</i> |
| PW 4hr On-Site | 95508-H30510 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30511 | \$ 7,610.00 | 6% | <i>\$7,207.05</i> |
| PW 4hr On-Site | 95508-H30512 | \$ 1,049.00 | 6% | <i>\$993.46</i> |
| PW 4hr On-Site | 95508-H30513 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| PW 4hr On-Site | 95508-H30525 | \$ 7,610.00 | 6% | <i>\$7,207.05</i> |
| PW 4hr On-Site | 95508-H30526 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30528 | \$ 8,839.00 | 6% | <i>\$8,370.97</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| PW 4hr On-Site | 95508-H30531 | \$ 12,577.00 | 6% | <i>\$11,911.05</i> |
| PW 4hr On-Site | 95508-H30532 | \$ 12,577.00 | 6% | <i>\$11,911.05</i> |
| PW 4hr On-Site | 95508-H30534 | \$ 12,823.00 | 6% | <i>\$12,144.02</i> |
| PW 4hr On-Site | 95508-H30535 | \$ 13,677.00 | 6% | <i>\$12,952.80</i> |
| PW 4hr On-Site | 95508-H30536 | \$ 12,577.00 | 6% | <i>\$11,911.05</i> |
| PW 4hr On-Site | 95508-H30537 | \$ 13,677.00 | 6% | <i>\$12,952.80</i> |
| PW 4hr On-Site | 95508-H30538 | \$ 7,610.00 | 6% | <i>\$7,207.05</i> |
| PW 4hr On-Site | 95508-H30539 | \$ 14,329.00 | 6% | <i>\$13,570.28</i> |
| PW 4hr On-Site | 95508-H30540 | \$ 15,117.00 | 6% | <i>\$14,316.55</i> |
| PW 4hr On-Site | 95508-H30543 | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| PW 4hr On-Site | 95508-H30544 | \$ 1,841.00 | 6% | <i>\$1,743.52</i> |
| PW 4hr On-Site | 95508-H30548 | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| PW 4hr On-Site | 95508-H30549 | \$ 1,744.00 | 6% | <i>\$1,651.66</i> |
| PW 4hr On-Site | 95508-H30550 | \$ 1,744.00 | 6% | <i>\$1,651.66</i> |
| PW 4hr On-Site | 95508-H30552 | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| PW 4hr On-Site | 95508-H30553 | \$ 1,634.00 | 6% | <i>\$1,547.48</i> |
| PW 4hr On-Site | 95508-H30569 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30570 | \$ 6,710.00 | 6% | <i>\$6,354.71</i> |
| PW 4hr On-Site | 95508-H30571 | \$ 6,710.00 | 6% | <i>\$6,354.71</i> |
| PW 4hr On-Site | 95508-H30573 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30574 | \$ 6,198.00 | 6% | <i>\$5,869.82</i> |
| PW 4hr On-Site | 95508-H30575 | \$ 3,872.00 | 6% | <i>\$3,666.98</i> |
| PW 4hr On-Site | 95508-H30576 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30577 | \$ 6,710.00 | 6% | <i>\$6,354.71</i> |
| PW 4hr On-Site | 95508-H30578 | \$ 6,710.00 | 6% | <i>\$6,354.71</i> |
| PW 4hr On-Site | 95508-H30587 | \$ 5,707.00 | 6% | <i>\$5,404.81</i> |
| PW 4hr On-Site | 95508-H30588 | \$ 3,950.00 | 6% | <i>\$3,740.85</i> |
| PW 4hr On-Site | 95508-H30589 | \$ 6,094.00 | 6% | <i>\$5,771.32</i> |
| PW 4hr On-Site | 95508-H30632 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4hr On-Site | 95508-H30633 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PW 4hr On-Site | 95508-H30643 | \$ 9,626.00 | 6% | <i>\$9,116.30</i> |
| PW 4hr On-Site | 95508-H30706 | \$ 9,012.00 | 6% | <i>\$8,534.81</i> |
| PW 4hr On-Site | 95508-H30707 | \$ 5,599.00 | 6% | <i>\$5,302.53</i> |
| PW 4hr On-Site | 95508-H30724 | \$ 617.00 | 6% | <i>\$584.33</i> |
| PW 4hr On-Site | 95508-H30725 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| PW 4hr On-Site | 95508-H30726 | \$ 13,944.00 | 6% | <i>\$13,205.67</i> |
| PW 4hr On-Site | 95508-H30727 | \$ 14,829.00 | 6% | <i>\$14,043.80</i> |
| PW 4hr On-Site | 95508-H30730 | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW 4hr On-Site | 95508-H30731 | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW 4HR ONSITE 30732 | 95508-H30732 | \$ 2,676.00 | 6% | <i>\$2,534.31</i> |
| PW 4HR ONSITE SKL8008-0810-F8 | 95508-H30733 | \$ 13,078.00 | 6% | <i>\$12,385.52</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| PW 4HR ONSITE STL2006-0850 | 95508-H30734 | \$ 9,979.00 | 6% | <i>\$9,450.61</i> |
| PW 4HR ONSITE SGL2001-0850 | 95508-H30735 | \$ 11,635.00 | 6% | <i>\$11,018.93</i> |
| PW 4HR ONSITE SOK2209-0204 | 95508-H30736 | \$ 1,808.00 | 6% | <i>\$1,712.27</i> |
| PW 4HR ONSITE H30738 | 95508-H30738 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE -H30739 | 95508-H30739 | \$ 1,955.00 | 6% | <i>\$1,851.48</i> |
| PW 4HR ONSITE -H30740 | 95508-H30740 | \$ 1,132.00 | 6% | <i>\$1,072.06</i> |
| PW 4HR ONSITE -H30741 | 95508-H30741 | \$ 2,066.00 | 6% | <i>\$1,956.61</i> |
| PW 4HR ONSITE -H30742 | 95508-H30742 | \$ 1,836.00 | 6% | <i>\$1,738.78</i> |
| PW 4HR ONSITE -H30743 | 95508-H30743 | \$ 1,955.00 | 6% | <i>\$1,851.48</i> |
| PW 4HR ONSITE -H30744 | 95508-H30744 | \$ 1,132.00 | 6% | <i>\$1,072.06</i> |
| PW 4HR ONSITE -H30745 | 95508-H30745 | \$ 1,155.00 | 6% | <i>\$1,093.84</i> |
| PW 4HR ONSITE -H30746 | 95508-H30746 | \$ 2,027.00 | 6% | <i>\$1,919.67</i> |
| PW 4HR ONSITE -H30747 | 95508-H30747 | \$ 4,060.00 | 6% | <i>\$3,845.02</i> |
| PW 4HR ONSITE -H30748 | 95508-H30748 | \$ 5,994.00 | 6% | <i>\$5,676.62</i> |
| PW 4HR ONSITE -H30749 | 95508-H30749 | \$ 13,463.00 | 6% | <i>\$12,750.13</i> |
| PW 4HR ONSITE -H30750 | 95508-H30750 | \$ 13,463.00 | 6% | <i>\$12,750.13</i> |
| PW 4HR ONSITE -H30751 | 95508-H30751 | \$ 7,991.00 | 6% | <i>\$7,567.88</i> |
| PW 4HR ONSITE -H30754 | 95508-H30754 | \$ 13,463.00 | 6% | <i>\$12,750.13</i> |
| PW 4HR ONSITE -H30755 | 95508-H30755 | \$ 14,637.00 | 6% | <i>\$13,861.97</i> |
| PW 4HR ONSITE -H30756 | 95508-H30756 | \$ 13,463.00 | 6% | <i>\$12,750.13</i> |
| PW 4HR ONSITE -H30757 | 95508-H30757 | \$ 5,994.00 | 6% | <i>\$5,676.62</i> |
| PW 4HR ONSITE -H30758 | 95508-H30758 | \$ 10,677.00 | 6% | <i>\$10,111.65</i> |
| PW 4HR ONSITE -H30759 | 95508-H30759 | \$ 12,213.00 | 6% | <i>\$11,566.32</i> |
| PW 4HR ONSITE -H30760 | 95508-H30760 | \$ 13,733.00 | 6% | <i>\$13,005.84</i> |
| PW 4HR ONSITE -H30761 | 95508-H30761 | \$ 5,994.00 | 6% | <i>\$5,676.62</i> |
| PW 4HR ONSITE -H30762 | 95508-H30762 | \$ 14,637.00 | 6% | <i>\$13,861.97</i> |
| PW 4HR ONSITE -H30763 | 95508-H30763 | \$ 14,637.00 | 6% | <i>\$13,861.97</i> |
| PW 4HR ONSITE -H30764 | 95508-H30764 | \$ 9,282.00 | 6% | <i>\$8,790.52</i> |
| PW 4HR ONSITE -H30765 | 95508-H30765 | \$ 8,147.00 | 6% | <i>\$7,715.62</i> |
| PW 4HR ONSITE -H30766 | 95508-H30766 | \$ 15,877.00 | 6% | <i>\$15,036.31</i> |
| PW 4HR ONSITE -H30767 | 95508-H30767 | \$ 9,282.00 | 6% | <i>\$8,790.52</i> |
| PW 4HR ONSITE H30769 | 95508-H30769 | \$ 3,457.00 | 6% | <i>\$3,273.95</i> |
| PW 4HR ONSITE H30773 | 95508-H30773 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PW 4HR ONSITE H30774 | 95508-H30774 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW 4HR ONSITE H30775 | 95508-H30775 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW 4HR ONSITE H30776 | 95508-H30776 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PW 4HR ONSITE H30777 | 95508-H30777 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW 4HR ONSITE H30778 | 95508-H30778 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW 4HR ONSITE H30779 | 95508-H30779 | \$ 129.00 | 6% | <i>\$122.17</i> |

| | | | | |
|----------------------|--------------|-----------|----|-----------------|
| PW 4HR ONSITE H30780 | 95508-H30780 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR ONSITE H30781 | 95508-H30781 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR ONSITE H30782 | 95508-H30782 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30783 | 95508-H30783 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR ONSITE H30784 | 95508-H30784 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR ONSITE H30785 | 95508-H30785 | \$ 129.00 | 6% | <i>\$122.17</i> |
| PW 4HR ONSITE H30786 | 95508-H30786 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR ONSITE H30787 | 95508-H30787 | \$ 129.00 | 6% | <i>\$122.17</i> |
| PW 4HR ONSITE H30788 | 95508-H30788 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW 4HR ONSITE H30789 | 95508-H30789 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR ONSITE H30790 | 95508-H30790 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30791 | 95508-H30791 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW 4HR ONSITE H30793 | 95508-H30793 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30794 | 95508-H30794 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30795 | 95508-H30795 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR ONSITE H30796 | 95508-H30796 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE H30797 | 95508-H30797 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR ONSITE H30798 | 95508-H30798 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE H30799 | 95508-H30799 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR ONSITE H30800 | 95508-H30800 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30801 | 95508-H30801 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE H30802 | 95508-H30802 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30803 | 95508-H30803 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30804 | 95508-H30804 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR ONSITE H30805 | 95508-H30805 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE H30806 | 95508-H30806 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30807 | 95508-H30807 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR ONSITE H30808 | 95508-H30808 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE H30809 | 95508-H30809 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE H30810 | 95508-H30810 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE H30811 | 95508-H30811 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30812 | 95508-H30812 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE H30813 | 95508-H30813 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30814 | 95508-H30814 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30815 | 95508-H30815 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE H30816 | 95508-H30816 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE H30817 | 95508-H30817 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30818 | 95508-H30818 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE H30819 | 95508-H30819 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30820 | 95508-H30820 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW 4HR ONSITE H30821 | 95508-H30821 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30822 | 95508-H30822 | \$ 97.00 | 6% | <i>\$91.86</i> |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PW 4HR ONSITE H30823 | 95508-H30823 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30824 | 95508-H30824 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE H30825 | 95508-H30825 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30826 | 95508-H30826 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30827 | 95508-H30827 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR ONSITE H30828 | 95508-H30828 | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW 4HR ONSITE H30829 | 95508-H30829 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW 4HR ONSITE H30830 | 95508-H30830 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30831 | 95508-H30831 | \$ 95.00 | 6% | <i>\$89.97</i> |
| PW 4HR ONSITE H30832 | 95508-H30832 | \$ 1,987.00 | 6% | <i>\$1,881.79</i> |
| PW 4HR ONSITE H30833 | 95508-H30833 | \$ 531.00 | 6% | <i>\$502.88</i> |
| PW 4HR ONSITE H30834 | 95508-H30834 | \$ 531.00 | 6% | <i>\$502.88</i> |
| PW 4HR ONSITE H30836 | 95508-H30836 | \$ 1,987.00 | 6% | <i>\$1,881.79</i> |
| PW 4HR ONSITE H30838 | 95508-H30838 | \$ 70.00 | 6% | <i>\$66.29</i> |
| PW 4HR ONSITE H30839 | 95508-H30839 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30840 | 95508-H30840 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30841 | 95508-H30841 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30842 | 95508-H30842 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30843 | 95508-H30843 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30844 | 95508-H30844 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30845 | 95508-H30845 | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW 4HR ONSITE H30846 | 95508-H30846 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30847 | 95508-H30847 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30848 | 95508-H30848 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30849 | 95508-H30849 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30850 | 95508-H30850 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30851 | 95508-H30851 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30852 | 95508-H30852 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30853 | 95508-H30853 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30854 | 95508-H30854 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30855 | 95508-H30855 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30856 | 95508-H30856 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30857 | 95508-H30857 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30858 | 95508-H30858 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30859 | 95508-H30859 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30860 | 95508-H30860 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PW 4HR ONSITE H30866 | 95508-H30866 | \$ 215.00 | 6% | <i>\$203.62</i> |
| PW 4HR ONSITE H30867 | 95508-H30867 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30868 | 95508-H30868 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30869 | 95508-H30869 | \$ 373.00 | 6% | <i>\$353.25</i> |
| PW 4HR ONSITE H30870 | 95508-H30870 | \$ 373.00 | 6% | <i>\$353.25</i> |
| PW 4HR ONSITE H30871 | 95508-H30871 | \$ 343.00 | 6% | <i>\$324.84</i> |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PW 4HR ONSITE H30872 | 95508-H30872 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW 4HR ONSITE H30873 | 95508-H30873 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW 4HR ONSITE H30874 | 95508-H30874 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW 4HR ONSITE H30875 | 95508-H30875 | \$ 66.00 | 6% | <i>\$62.51</i> |
| PW 4HR ONSITE H30876 | 95508-H30876 | \$ 62.00 | 6% | <i>\$58.72</i> |
| PW 4HR ONSITE H30877 | 95508-H30877 | \$ 66.00 | 6% | <i>\$62.51</i> |
| PW 4HR ONSITE H30878 | 95508-H30878 | \$ 66.00 | 6% | <i>\$62.51</i> |
| PW 4HR ONSITE H30891 | 95508-H30891 | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR ONSITE H30892 | 95508-H30892 | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR ONSITE H30893 | 95508-H30893 | \$ 116.00 | 6% | <i>\$109.86</i> |
| PW 4HR ONSITE H30894 | 95508-H30894 | \$ 66.00 | 6% | <i>\$62.51</i> |
| PW 4HR ONSITE H30895 | 95508-H30895 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW 4HR ONSITE H30896 | 95508-H30896 | \$ 558.00 | 6% | <i>\$528.45</i> |
| PW 4HR ONSITE H30897 | 95508-H30897 | \$ 983.00 | 6% | <i>\$930.95</i> |
| PW 4HR ONSITE H30898 | 95508-H30898 | \$ 1,103.00 | 6% | <i>\$1,044.60</i> |
| PW 4HR ONSITE H30900 | 95508-H30900 | \$ 3,332.00 | 6% | <i>\$3,155.57</i> |
| PW 4HR ONSITE H30901 | 95508-H30901 | \$ 4,426.00 | 6% | <i>\$4,191.64</i> |
| PW 4HR ONSITE H30902 | 95508-H30902 | \$ 4,647.00 | 6% | <i>\$4,400.94</i> |
| PW 4HR ONSITE H30904 | 95508-H30904 | \$ 6,842.00 | 6% | <i>\$6,479.72</i> |
| PW 4HR ONSITE H30905 | 95508-H30905 | \$ 9,777.00 | 6% | <i>\$9,259.31</i> |
| PW 4HR ONSITE H30906 | 95508-H30906 | \$ 270.00 | 6% | <i>\$255.70</i> |
| PW 4HR ONSITE H30912 | 95508-H30912 | \$ 735.00 | 6% | <i>\$696.08</i> |
| PW 4HR ONSITE H30913 | 95508-H30913 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR ONSITE H30914 | 95508-H30914 | \$ 66.00 | 6% | <i>\$62.51</i> |
| PW 4HR ONSITE H30915 | 95508-H30915 | \$ 70.00 | 6% | <i>\$66.29</i> |
| PW 4HR ONSITE H30916 | 95508-H30916 | \$ 70.00 | 6% | <i>\$66.29</i> |
| PW 4HR ONSITE H30917 | 95508-H30917 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR ONSITE H30918 | 95508-H30918 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW 4HR ONSITE H30946 | 95508-H30946 | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR ONSITE H30948 | 95508-H30948 | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR ONSITE H30950 | 95508-H30950 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PW 4HR ONSITE H30951 | 95508-H30951 | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR ONSITE H30952 | 95508-H30952 | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW 4HR ONSITE H30966 | 95508-H30966 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW 4HR ONSITE H30967 | 95508-H30967 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PW 4HR ONSITE H30968 | 95508-H30968 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW 4HR ONSITE H30969 | 95508-H30969 | \$ 124.00 | 6% | <i>\$117.43</i> |
| PW 4HR ONSITE H30970 | 95508-H30970 | \$ 174.00 | 6% | <i>\$164.79</i> |
| PW 4HR ONSITE H30971 | 95508-H30971 | \$ 149.00 | 6% | <i>\$141.11</i> |
| PW 4HR ONSITE H30972 | 95508-H30972 | \$ 174.00 | 6% | <i>\$164.79</i> |
| PW 4HR ONSITE H30973 | 95508-H30973 | \$ 241.00 | 6% | <i>\$228.24</i> |
| PW 4HR ONSITE H30974 | 95508-H30974 | \$ 210.00 | 6% | <i>\$198.88</i> |

| | | | | |
|----------------------|--------------|-------------|----|------------|
| PW 4HR ONSITE H30975 | 95508-H30975 | \$ 241.00 | 6% | \$228.24 |
| PW 4HR ONSITE H30976 | 95508-H30976 | \$ 241.00 | 6% | \$228.24 |
| PW 4HR ONSITE H30977 | 95508-H30977 | \$ 210.00 | 6% | \$198.88 |
| PW 4HR ONSITE H30978 | 95508-H30978 | \$ 241.00 | 6% | \$228.24 |
| PW 4HR ONSITE H30995 | 95508-H30995 | \$ 2,671.00 | 6% | \$2,529.57 |
| PW 4HR ONSITE H31030 | 95508-H31030 | \$ 8,633.00 | 6% | \$8,175.88 |
| PW 4HR ONSITE H31031 | 95508-H31031 | \$ 686.00 | 6% | \$649.68 |
| PW 4HR ONSITE H31033 | 95508-H31033 | \$ 5,234.00 | 6% | \$4,956.86 |
| PW 4HR ONSITE H31034 | 95508-H31034 | \$ 2,905.00 | 6% | \$2,751.18 |
| PW 4HR ONSITE H31035 | 95508-H31035 | \$ 3,046.00 | 6% | \$2,884.71 |
| PW 4HR ONSITE H31036 | 95508-H31036 | \$ 6,091.00 | 6% | \$5,768.48 |
| PW 4HR ONSITE H31040 | 95508-H31040 | \$ 224.00 | 6% | \$212.14 |
| PW 4HR ONSITE H31041 | 95508-H31041 | \$ 116.00 | 6% | \$109.86 |
| PW 4HR ONSITE H31042 | 95508-H31042 | \$ 341.00 | 6% | \$322.94 |
| PW 4HR ONSITE H31043 | 95508-H31043 | \$ 248.00 | 6% | \$234.87 |
| PW 4HR ONSITE H31047 | 95508-H31047 | \$ 227.00 | 6% | \$214.98 |
| PW 4HR ONSITE H31049 | 95508-H31049 | \$ 2,437.00 | 6% | \$2,307.96 |
| PW 4HR ONSITE H31060 | 95508-H31060 | \$ 61.00 | 6% | \$57.77 |
| PW 4HR ONSITE H31062 | 95508-H31062 | \$ 65.00 | 6% | \$61.56 |
| PW 4HR ONSITE H31066 | 95508-H31066 | \$ 89.00 | 6% | \$84.29 |
| PW 4HR ONSITE H31068 | 95508-H31068 | \$ 96.00 | 6% | \$90.92 |
| PW 4HR ONSITE H31076 | 95508-H31076 | \$ 330.00 | 6% | \$312.53 |
| PW 4HR ONSITE H31077 | 95508-H31077 | \$ 341.00 | 6% | \$322.94 |
| PW 4HR ONSITE H31078 | 95508-H31078 | \$ 345.00 | 6% | \$326.73 |
| PW 4HR ONSITE H31103 | 95508-H31103 | \$ 5,577.00 | 6% | \$5,281.70 |
| PW 4HR ONSITE H31119 | 95508-H31119 | \$ 125.00 | 6% | \$118.38 |
| PW 4HR ONSITE H31124 | 95508-H31124 | \$ 133.00 | 6% | \$125.96 |
| PW 4HR ONSITE H31127 | 95508-H31127 | \$ 221.00 | 6% | \$209.30 |
| PW 4HR ONSITE H31132 | 95508-H31132 | \$ 215.00 | 6% | \$203.62 |
| PW 4HR ONSITE H31134 | 95508-H31134 | \$ 66.00 | 6% | \$62.51 |
| PW 4HR ONSITE H31135 | 95508-H31135 | \$ 70.00 | 6% | \$66.29 |
| PW 4HR ONSITE H31136 | 95508-H31136 | \$ 113.00 | 6% | \$107.02 |
| PW 4HR ONSITE H31137 | 95508-H31137 | \$ 104.00 | 6% | \$98.49 |
| PW 4HR ONSITE H31197 | 95508-H31197 | \$ 123.00 | 6% | \$116.49 |
| PW 4HR ONSITE H31198 | 95508-H31198 | \$ 123.00 | 6% | \$116.49 |
| PW 4HR ONSITE H31199 | 95508-H31199 | \$ 123.00 | 6% | \$116.49 |
| PW 4HR ONSITE H31200 | 95508-H31200 | \$ 123.00 | 6% | \$116.49 |
| PW 4HR ONSITE H31201 | 95508-H31201 | \$ 123.00 | 6% | \$116.49 |
| PW 4HR ONSITE H31202 | 95508-H31202 | \$ 123.00 | 6% | \$116.49 |
| PW 4HR ONSITE H31203 | 95508-H31203 | \$ 146.00 | 6% | \$138.27 |
| PW 4HR ONSITE H31204 | 95508-H31204 | \$ 129.00 | 6% | \$122.17 |
| PW 4HR ONSITE H31205 | 95508-H31205 | \$ 146.00 | 6% | \$138.27 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW 4HR ONSITE H31206 | 95508-H31206 | \$ 146.00 | 6% | \$138.27 |
| PW 4HR ONSITE H31207 | 95508-H31207 | \$ 129.00 | 6% | \$122.17 |
| PW 4HR ONSITE H31208 | 95508-H31208 | \$ 146.00 | 6% | \$138.27 |
| PW 4HR ONSITE H31210 | 95508-H31210 | \$ 270.00 | 6% | \$255.70 |
| PW 4HR ONSITE H31335 | 95508-H31335 | \$ 149.00 | 6% | \$141.11 |
| PW 4HR ONSITE H31337 | 95508-H31337 | \$ 11,146.00 | 6% | \$10,555.82 |
| PW 4HR ONSITE H31338 | 95508-H31338 | \$ 11,146.00 | 6% | \$10,555.82 |
| PW 4HR ONSITE H31339 | 95508-H31339 | \$ 1,812.00 | 6% | \$1,716.05 |
| PW 4HR ONSITE H31340 | 95508-H31340 | \$ 3,868.00 | 6% | \$3,663.19 |
| PW 4HR ONSITE H31341 | 95508-H31341 | \$ 5,734.00 | 6% | \$5,430.38 |
| PW 4HR ONSITE H31342 | 95508-H31342 | \$ 1,805.00 | 6% | \$1,709.43 |
| PW 4HR ONSITE H31343 | 95508-H31343 | \$ 2,667.00 | 6% | \$2,525.78 |
| PW 4HR ONSITE H31344 | 95508-H31344 | \$ 2,667.00 | 6% | \$2,525.78 |
| PW 4HR ONSITE H31345 | 95508-H31345 | \$ 2,667.00 | 6% | \$2,525.78 |
| PW 4HR ONSITE H31346 | 95508-H31346 | \$ 2,667.00 | 6% | \$2,525.78 |
| PW 4HR ONSITE H31348 | 95508-H31348 | \$ 210.00 | 6% | \$198.88 |
| PW 4HR ONSITE H31349 | 95508-H31349 | \$ 210.00 | 6% | \$198.88 |
| PW 4HR ONSITE H31350 | 95508-H31350 | \$ 343.00 | 6% | \$324.84 |
| PW 4HR ONSITE H31351 | 95508-H31351 | \$ 129.00 | 6% | \$122.17 |
| PW 4HR ONSITE H31352 | 95508-H31352 | \$ 129.00 | 6% | \$122.17 |
| PW 4HR ONSITE H31353 | 95508-H31353 | \$ 108.00 | 6% | \$102.28 |
| PW 4HR ONSITE H31354 | 95508-H31354 | \$ 108.00 | 6% | \$102.28 |
| PW 4HR ONSITE H31355 | 95508-H31355 | \$ 221.00 | 6% | \$209.30 |
| PW 4HR ONSITE H31356 | 95508-H31356 | \$ 221.00 | 6% | \$209.30 |
| PW 4HR ONSITE H31357 | 95508-H31357 | \$ 221.00 | 6% | \$209.30 |
| PW 4HR ONSITE H31358 | 95508-H31358 | \$ 75.00 | 6% | \$71.03 |
| PW 4HR ONSITE H31359 | 95508-H31359 | \$ 89.00 | 6% | \$84.29 |
| PW 4HR ONSITE H31360 | 95508-H31360 | \$ 69.00 | 6% | \$65.35 |
| PW 4HR ONSITE H31361 | 95508-H31361 | \$ 3,770.00 | 6% | \$3,570.38 |
| PW 4HR ONSITE H31362 | 95508-H31362 | \$ 33,134.00 | 6% | \$31,379.55 |
| PW 4HR ONSITE H31363 | 95508-H31363 | \$ 33,134.00 | 6% | \$31,379.55 |
| PW 4HR ONSITE H31364 | 95508-H31364 | \$ 11,579.00 | 6% | \$10,965.89 |
| PW 4HR ONSITE H31365 | 95508-H31365 | \$ 11,579.00 | 6% | \$10,965.89 |
| PW 4HR ONSITE H31366 | 95508-H31366 | \$ 16,058.00 | 6% | \$15,207.73 |
| PW 4HR ONSITE H31367 | 95508-H31367 | \$ 16,058.00 | 6% | \$15,207.73 |
| PW 4HR ONSITE H31369 | 95508-H31369 | \$ 129.00 | 6% | \$122.17 |
| PW 4HR ONSITE H31370 | 95508-H31370 | \$ 129.00 | 6% | \$122.17 |
| PW 4HR ONSITE H31393 | 95508-H31393 | \$ 68.00 | 6% | \$64.40 |
| PW 4HR ONSITE H32010 | 95508-H32010 | \$ 461.00 | 6% | \$436.59 |
| PW 4HR ONSITE H32011 | 95508-H32011 | \$ 461.00 | 6% | \$436.59 |
| PW 4HR ONSITE H32012 | 95508-H32012 | \$ 3,976.00 | 6% | \$3,765.47 |
| PW 4HR ONSITE H32013 | 95508-H32013 | \$ 3,976.00 | 6% | \$3,765.47 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW 4HR ONSITE H32014 | 95508-H32014 | \$ 3,976.00 | 6% | \$3,765.47 |
| PW 4HR ONSITE H32015 | 95508-H32015 | \$ 3,976.00 | 6% | \$3,765.47 |
| PW 4HR ONSITE H32016 | 95508-H32016 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR ONSITE H32017 | 95508-H32017 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR ONSITE H32018 | 95508-H32018 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR ONSITE H32019 | 95508-H32019 | \$ 3,469.00 | 6% | \$3,285.32 |
| PW 4HR ONSITE H32020 | 95508-H32020 | \$ 34,748.00 | 6% | \$32,908.09 |
| PW 4HR ONSITE H32021 | 95508-H32021 | \$ 34,748.00 | 6% | \$32,908.09 |
| PW 4HR ONSITE H32022 | 95508-H32022 | \$ 34,748.00 | 6% | \$32,908.09 |
| PW 4HR ONSITE H32023 | 95508-H32023 | \$ 34,748.00 | 6% | \$32,908.09 |
| PW 4HR ONSITE H32028 | 95508-H32028 | \$ 67,011.00 | 6% | \$63,462.77 |
| PW 4HR ONSITE H32029 | 95508-H32029 | \$ 67,011.00 | 6% | \$63,462.77 |
| PW 4HR ONSITE H32030 | 95508-H32030 | \$ 70,275.00 | 6% | \$66,553.94 |
| PW 4HR ONSITE H32031 | 95508-H32031 | \$ 70,275.00 | 6% | \$66,553.94 |
| PW 4HR ONSITE H32032 | 95508-H32032 | \$ 70,275.00 | 6% | \$66,553.94 |
| PW 4HR ONSITE H32033 | 95508-H32033 | \$ 70,275.00 | 6% | \$66,553.94 |
| PW 4HR ONSITE H32038 | 95508-H32038 | \$ 12,144.00 | 6% | \$11,500.98 |
| PW 4HR ONSITE H32039 | 95508-H32039 | \$ 12,144.00 | 6% | \$11,500.98 |
| PW 4HR ONSITE H32040 | 95508-H32040 | \$ 12,144.00 | 6% | \$11,500.98 |
| PW 4HR ONSITE H32041 | 95508-H32041 | \$ 12,144.00 | 6% | \$11,500.98 |
| PW 4HR ONSITE H32046 | 95508-H32046 | \$ 16,840.00 | 6% | \$15,948.32 |
| PW 4HR ONSITE H32047 | 95508-H32047 | \$ 16,840.00 | 6% | \$15,948.32 |
| PW 4HR ONSITE H32048 | 95508-H32048 | \$ 16,840.00 | 6% | \$15,948.32 |
| PW 4HR ONSITE H32049 | 95508-H32049 | \$ 16,840.00 | 6% | \$15,948.32 |
| PW 4HR ONSITE H32054 | 95508-H32054 | \$ 12,144.00 | 6% | \$11,500.98 |
| PW 4HR ONSITE H32055 | 95508-H32055 | \$ 16,840.00 | 6% | \$15,948.32 |
| PW 4HR ONSITE H32056 | 95508-H32056 | \$ 4,475.00 | 6% | \$4,238.05 |
| PW 4HR ONSITE H32057 | 95508-H32057 | \$ 4,610.00 | 6% | \$4,365.90 |
| PW 4HR ONSITE H32058 | 95508-H32058 | \$ 4,610.00 | 6% | \$4,365.90 |
| PW 4HR ONSITE H32059 | 95508-H32059 | \$ 4,610.00 | 6% | \$4,365.90 |
| PW 4HR ONSITE H32060 | 95508-H32060 | \$ 5,749.00 | 6% | \$5,444.59 |
| PW 4HR ONSITE H32061 | 95508-H32061 | \$ 6,036.00 | 6% | \$5,716.39 |
| PW 4HR ONSITE H32062 | 95508-H32062 | \$ 5,804.00 | 6% | \$5,496.68 |
| PW 4HR ONSITE H32063 | 95508-H32063 | \$ 5,756.00 | 6% | \$5,451.22 |
| PW 4HR ONSITE H32064 | 95508-H32064 | \$ 5,804.00 | 6% | \$5,496.68 |
| PW 4HR ONSITE H32065 | 95508-H32065 | \$ 6,550.00 | 6% | \$6,203.18 |
| PW 4HR ONSITE H32066 | 95508-H32066 | \$ 6,550.00 | 6% | \$6,203.18 |
| PW 4HR ONSITE H32067 | 95508-H32067 | \$ 6,550.00 | 6% | \$6,203.18 |
| PW 4HR ONSITE H32068 | 95508-H32068 | \$ 6,550.00 | 6% | \$6,203.18 |
| PW 4HR ONSITE H32069 | 95508-H32069 | \$ 8,147.00 | 6% | \$7,715.62 |
| PW 4HR ONSITE H32070 | 95508-H32070 | \$ 8,147.00 | 6% | \$7,715.62 |
| PW 4HR ONSITE H32071 | 95508-H32071 | \$ 8,147.00 | 6% | \$7,715.62 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW 4HR ONSITE H32072 | 95508-H32072 | \$ 8,147.00 | 6% | \$7,715.62 |
| PW 4HR ONSITE H32073 | 95508-H32073 | \$ 49,363.00 | 6% | \$46,749.23 |
| PW 4HR ONSITE H32074 | 95508-H32074 | \$ 49,363.00 | 6% | \$46,749.23 |
| PW 4HR ONSITE H32075 | 95508-H32075 | \$ 67,081.00 | 6% | \$63,529.06 |
| PW 4HR ONSITE H32076 | 95508-H32076 | \$ 67,081.00 | 6% | \$63,529.06 |
| PW 4HR ONSITE H32101 | 95508-H32101 | \$ 2,157.00 | 6% | \$2,042.79 |
| PW 4HR ONSITE H32102 | 95508-H32102 | \$ 2,177.00 | 6% | \$2,061.73 |
| PW 4HR ONSITE H32103 | 95508-H32103 | \$ 2,177.00 | 6% | \$2,061.73 |
| PW 4HR ONSITE H32104 | 95508-H32104 | \$ 2,177.00 | 6% | \$2,061.73 |
| PW 4HR ONSITE H32105 | 95508-H32105 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32106 | 95508-H32106 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32107 | 95508-H32107 | \$ 11,769.00 | 6% | \$11,145.83 |
| PW 4HR ONSITE H32108 | 95508-H32108 | \$ 11,769.00 | 6% | \$11,145.83 |
| PW 4HR ONSITE H32109 | 95508-H32109 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32110 | 95508-H32110 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32111 | 95508-H32111 | \$ 2,177.00 | 6% | \$2,061.73 |
| PW 4HR ONSITE H32112 | 95508-H32112 | \$ 2,177.00 | 6% | \$2,061.73 |
| PW 4HR ONSITE H32113 | 95508-H32113 | \$ 2,178.00 | 6% | \$2,062.67 |
| PW 4HR ONSITE H32114 | 95508-H32114 | \$ 2,178.00 | 6% | \$2,062.67 |
| PW 4HR ONSITE H32115 | 95508-H32115 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32116 | 95508-H32116 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32117 | 95508-H32117 | \$ 2,040.00 | 6% | \$1,931.98 |
| PW 4HR ONSITE H32118 | 95508-H32118 | \$ 2,040.00 | 6% | \$1,931.98 |
| PW 4HR ONSITE H32119 | 95508-H32119 | \$ 2,040.00 | 6% | \$1,931.98 |
| PW 4HR ONSITE H32120 | 95508-H32120 | \$ 2,040.00 | 6% | \$1,931.98 |
| PW 4HR ONSITE H32121 | 95508-H32121 | \$ 11,769.00 | 6% | \$11,145.83 |
| PW 4HR ONSITE H32122 | 95508-H32122 | \$ 11,769.00 | 6% | \$11,145.83 |
| PW 4HR ONSITE H32123 | 95508-H32123 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32124 | 95508-H32124 | \$ 4,352.00 | 6% | \$4,121.56 |
| PW 4HR ONSITE H32125 | 95508-H32125 | \$ 4,299.00 | 6% | \$4,071.37 |
| PW 4HR ONSITE H32126 | 95508-H32126 | \$ 4,299.00 | 6% | \$4,071.37 |
| PW 4HR ONSITE H32127 | 95508-H32127 | \$ 5,060.00 | 6% | \$4,792.07 |
| PW 4HR ONSITE H32128 | 95508-H32128 | \$ 5,060.00 | 6% | \$4,792.07 |
| PW 4HR ONSITE H32129 | 95508-H32129 | \$ 5,060.00 | 6% | \$4,792.07 |
| PW 4HR ONSITE H32130 | 95508-H32130 | \$ 5,060.00 | 6% | \$4,792.07 |
| PW 4HR ONSITE H32131 | 95508-H32131 | \$ 5,060.00 | 6% | \$4,792.07 |
| PW 4HR ONSITE H32132 | 95508-H32132 | \$ 5,060.00 | 6% | \$4,792.07 |
| PW 4HR ONSITE H32133 | 95508-H32133 | \$ 4,299.00 | 6% | \$4,071.37 |
| PW 4HR ONSITE H32134 | 95508-H32134 | \$ 4,299.00 | 6% | \$4,071.37 |
| PW 4HR ONSITE H32135 | 95508-H32135 | \$ 4,299.00 | 6% | \$4,071.37 |
| PW 4HR ONSITE H32136 | 95508-H32136 | \$ 4,299.00 | 6% | \$4,071.37 |
| PW 4HR ONSITE H32137 | 95508-H32137 | \$ 4,299.00 | 6% | \$4,071.37 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW 4HR ONSITE H32138 | 95508-H32138 | \$ 4,299.00 | 6% | \$4,071.37 |
| PW 4HR ONSITE H32139 | 95508-H32139 | \$ 18,190.00 | 6% | \$17,226.84 |
| PW 4HR ONSITE H32140 | 95508-H32140 | \$ 18,190.00 | 6% | \$17,226.84 |
| PW 4HR ONSITE H32141 | 95508-H32141 | \$ 20,993.00 | 6% | \$19,881.42 |
| PW 4HR ONSITE H32142 | 95508-H32142 | \$ 20,993.00 | 6% | \$19,881.42 |
| PW 4HR ONSITE H32143 | 95508-H32143 | \$ 845.00 | 6% | \$800.26 |
| PW 4HR ONSITE H32144 | 95508-H32144 | \$ 805.00 | 6% | \$762.38 |
| PW 4HR ONSITE H32146 | 95508-H32146 | \$ 1,857.00 | 6% | \$1,758.67 |
| PW 4HR ONSITE H32147 | 95508-H32147 | \$ 1,857.00 | 6% | \$1,758.67 |
| PW 4HR ONSITE H32148 | 95508-H32148 | \$ 3,824.00 | 6% | \$3,621.52 |
| PW 4HR ONSITE H32149 | 95508-H32149 | \$ 3,824.00 | 6% | \$3,621.52 |
| PW 4HR ONSITE H32150 | 95508-H32150 | \$ 1,964.00 | 6% | \$1,860.01 |
| PW 4HR ONSITE H32151 | 95508-H32151 | \$ 858.00 | 6% | \$812.57 |
| PW 4HR ONSITE H32169 | 95508-H32169 | \$ 2,201.00 | 6% | \$2,084.46 |
| PW 4HR ONSITE H32170 | 95508-H32170 | \$ 2,201.00 | 6% | \$2,084.46 |
| PW 4HR ONSITE H32171 | 95508-H32171 | \$ 2,061.00 | 6% | \$1,951.87 |
| PW 4HR ONSITE H32172 | 95508-H32172 | \$ 2,061.00 | 6% | \$1,951.87 |
| PW 4HR ONSITE H32173 | 95508-H32173 | \$ 5,504.00 | 6% | \$5,212.56 |
| PW 4HR ONSITE H32174 | 95508-H32174 | \$ 5,504.00 | 6% | \$5,212.56 |
| PW 4HR ONSITE H32175 | 95508-H32175 | \$ 4,674.00 | 6% | \$4,426.51 |
| PW 4HR ONSITE H32176 | 95508-H32176 | \$ 4,674.00 | 6% | \$4,426.51 |
| PW 4HR ONSITE H32177 | 95508-H32177 | \$ 21,448.00 | 6% | \$20,312.33 |
| PW 4HR ONSITE H32178 | 95508-H32178 | \$ 24,748.00 | 6% | \$23,437.59 |
| PW 4HR ONSITE H34008 | 95508-H34008 | \$ 78.00 | 6% | \$73.87 |
| PW 4HR ONSITE H34009 | 95508-H34009 | \$ 226.00 | 6% | \$214.03 |
| PW 4HR ONSITE H34010 | 95508-H34010 | \$ 93.00 | 6% | \$88.08 |
| PW 4HR ONSITE H34011 | 95508-H34011 | \$ 199.00 | 6% | \$188.46 |
| PW 4HR ONSITE H34012 | 95508-H34012 | \$ 364.00 | 6% | \$344.73 |
| PW 4HR ONSITE H34013 | 95508-H34013 | \$ 136.00 | 6% | \$128.80 |
| PW 4HR ONSITE H34014 | 95508-H34014 | \$ 226.00 | 6% | \$214.03 |
| PW 4HR ONSITE H34015 | 95508-H34015 | \$ 116.00 | 6% | \$109.86 |
| PW 4HR ONSITE H34016 | 95508-H34016 | \$ 250.00 | 6% | \$236.76 |
| PW 4HR ONSITE H34017 | 95508-H34017 | \$ 425.00 | 6% | \$402.50 |
| PW 4HR ONSITE H34018 | 95508-H34018 | \$ 166.00 | 6% | \$157.21 |
| PW 4HR ONSITE H34019 | 95508-H34019 | \$ 166.00 | 6% | \$157.21 |
| PW 4HR ONSITE H34020 | 95508-H34020 | \$ 166.00 | 6% | \$157.21 |
| PW 4HR ONSITE H34021 | 95508-H34021 | \$ 166.00 | 6% | \$157.21 |
| PW 4HR ONSITE H34048 | 95508-H34048 | \$ 706.00 | 6% | \$668.62 |
| PW 4HR ONSITE H34049 | 95508-H34049 | \$ 706.00 | 6% | \$668.62 |
| PW 4HR ONSITE H34050 | 95508-H34050 | \$ 524.00 | 6% | \$496.25 |
| PW 4HR ONSITE H34051 | 95508-H34051 | \$ 524.00 | 6% | \$496.25 |
| PW 4HR ONSITE H34052 | 95508-H34052 | \$ 835.00 | 6% | \$790.79 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW 4HR ONSITE H34053 | 95508-H34053 | \$ 835.00 | 6% | \$790.79 |
| PW 4HR ONSITE H34054 | 95508-H34054 | \$ 625.00 | 6% | \$591.91 |
| PW 4HR ONSITE H34055 | 95508-H34055 | \$ 625.00 | 6% | \$591.91 |
| PW 4HR ONSITE H34056 | 95508-H34056 | \$ 912.00 | 6% | \$863.71 |
| PW 4HR ONSITE H34057 | 95508-H34057 | \$ 912.00 | 6% | \$863.71 |
| PW 4HR ONSITE H34058 | 95508-H34058 | \$ 770.00 | 6% | \$729.23 |
| PW 4HR ONSITE H34059 | 95508-H34059 | \$ 770.00 | 6% | \$729.23 |
| PW 4HR ONSITE H34062 | 95508-H34062 | \$ 912.00 | 6% | \$863.71 |
| PW 4HR ONSITE H34063 | 95508-H34063 | \$ 912.00 | 6% | \$863.71 |
| PW 4HR ONSITE H34064 | 95508-H34064 | \$ 611.00 | 6% | \$578.65 |
| PW 4HR ONSITE H34065 | 95508-H34065 | \$ 611.00 | 6% | \$578.65 |
| PW 4HR ONSITE H34066 | 95508-H34066 | \$ 611.00 | 6% | \$578.65 |
| PW 4HR ONSITE H34067 | 95508-H34067 | \$ 611.00 | 6% | \$578.65 |
| PW 4HR ONSITE H34068 | 95508-H34068 | \$ 611.00 | 6% | \$578.65 |
| PW 4HR ONSITE H34069 | 95508-H34069 | \$ 593.00 | 6% | \$561.60 |
| PW 4HR ONSITE H34070 | 95508-H34070 | \$ 611.00 | 6% | \$578.65 |
| PW 4HR ONSITE H34071 | 95508-H34071 | \$ 611.00 | 6% | \$578.65 |
| PW 4HR ONSITE H34072 | 95508-H34072 | \$ 4,994.00 | 6% | \$4,729.57 |
| PW 4HR ONSITE H34073 | 95508-H34073 | \$ 4,898.00 | 6% | \$4,638.65 |
| PW 4HR ONSITE H34074 | 95508-H34074 | \$ 6,237.00 | 6% | \$5,906.75 |
| PW 4HR ONSITE H34075 | 95508-H34075 | \$ 5,987.00 | 6% | \$5,669.99 |
| PW 4HR ONSITE H34076 | 95508-H34076 | \$ 4,994.00 | 6% | \$4,729.57 |
| PW 4HR ONSITE H34077 | 95508-H34077 | \$ 4,898.00 | 6% | \$4,638.65 |
| PW 4HR ONSITE H34078 | 95508-H34078 | \$ 4,994.00 | 6% | \$4,729.57 |
| PW 4HR ONSITE H34079 | 95508-H34079 | \$ 4,898.00 | 6% | \$4,638.65 |
| PW 4HR ONSITE H34080 | 95508-H34080 | \$ 6,237.00 | 6% | \$5,906.75 |
| PW 4HR ONSITE H34081 | 95508-H34081 | \$ 5,987.00 | 6% | \$5,669.99 |
| PW 4HR ONSITE H34082 | 95508-H34082 | \$ 5,983.00 | 6% | \$5,666.20 |
| PW 4HR ONSITE H34083 | 95508-H34083 | \$ 5,742.00 | 6% | \$5,437.96 |
| PW 4HR ONSITE H34084 | 95508-H34084 | \$ 4,251.00 | 6% | \$4,025.91 |
| PW 4HR ONSITE H34085 | 95508-H34085 | \$ 4,251.00 | 6% | \$4,025.91 |
| PW 4HR ONSITE H34086 | 95508-H34086 | \$ 4,950.00 | 6% | \$4,687.90 |
| PW 4HR ONSITE H34087 | 95508-H34087 | \$ 4,748.00 | 6% | \$4,496.59 |
| PW 4HR ONSITE H34088 | 95508-H34088 | \$ 10,744.00 | 6% | \$10,175.11 |
| PW 4HR ONSITE H34089 | 95508-H34089 | \$ 10,744.00 | 6% | \$10,175.11 |
| PW 4HR ONSITE H34090 | 95508-H34090 | \$ 12,372.00 | 6% | \$11,716.90 |
| PW 4HR ONSITE H34091 | 95508-H34091 | \$ 9,986.00 | 6% | \$9,457.24 |
| PW 4HR ONSITE H34092 | 95508-H34092 | \$ 9,986.00 | 6% | \$9,457.24 |
| PW 4HR ONSITE H34093 | 95508-H34093 | \$ 9,986.00 | 6% | \$9,457.24 |
| PW 4HR ONSITE H34094 | 95508-H34094 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34095 | 95508-H34095 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34096 | 95508-H34096 | \$ 1,306.00 | 6% | \$1,236.85 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW 4HR ONSITE H34097 | 95508-H34097 | \$ 1,306.00 | 6% | \$1,236.85 |
| PW 4HR ONSITE H34098 | 95508-H34098 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34099 | 95508-H34099 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34100 | 95508-H34100 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34101 | 95508-H34101 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34102 | 95508-H34102 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34103 | 95508-H34103 | \$ 1,154.00 | 6% | \$1,092.90 |
| PW 4HR ONSITE H34104 | 95508-H34104 | \$ 507.00 | 6% | \$480.15 |
| PW 4HR ONSITE H34105 | 95508-H34105 | \$ 506.00 | 6% | \$479.21 |
| PW 4HR ONSITE H34106 | 95508-H34106 | \$ 507.00 | 6% | \$480.15 |
| PW 4HR ONSITE H34107 | 95508-H34107 | \$ 506.00 | 6% | \$479.21 |
| PW 4HR ONSITE H34108 | 95508-H34108 | \$ 507.00 | 6% | \$480.15 |
| PW 4HR ONSITE H34109 | 95508-H34109 | \$ 506.00 | 6% | \$479.21 |
| PW 4HR ONSITE H34110 | 95508-H34110 | \$ 9,619.00 | 6% | \$9,109.67 |
| PW 4HR ONSITE H34111 | 95508-H34111 | \$ 9,619.00 | 6% | \$9,109.67 |
| PW 4HR ONSITE H34112 | 95508-H34112 | \$ 9,619.00 | 6% | \$9,109.67 |
| PW 4HR ONSITE H34114 | 95508-H34114 | \$ 12,639.00 | 6% | \$11,969.76 |
| PW 4HR ONSITE H34115 | 95508-H34115 | \$ 12,639.00 | 6% | \$11,969.76 |
| PW 4HR ONSITE H34116 | 95508-H34116 | \$ 12,639.00 | 6% | \$11,969.76 |
| PW 4HR ONSITE H34117 | 95508-H34117 | \$ 12,639.00 | 6% | \$11,969.76 |
| PW 4HR ONSITE H34118 | 95508-H34118 | \$ 3,195.00 | 6% | \$3,025.82 |
| PW 4HR ONSITE H34119 | 95508-H34119 | \$ 3,195.00 | 6% | \$3,025.82 |
| PW 4HR ONSITE H34120 | 95508-H34120 | \$ 2,199.00 | 6% | \$2,082.56 |
| PW 4HR ONSITE H34121 | 95508-H34121 | \$ 2,199.00 | 6% | \$2,082.56 |
| PW 4HR ONSITE H34122 | 95508-H34122 | \$ 2,293.00 | 6% | \$2,171.59 |
| PW 4HR ONSITE H34123 | 95508-H34123 | \$ 2,293.00 | 6% | \$2,171.59 |
| PW 4HR ONSITE H34124 | 95508-H34124 | \$ 3,417.00 | 6% | \$3,236.07 |
| PW 4HR ONSITE H34125 | 95508-H34125 | \$ 3,417.00 | 6% | \$3,236.07 |
| PW 4HR ONSITE H34126 | 95508-H34126 | \$ 3,417.00 | 6% | \$3,236.07 |
| PW 4HR ONSITE H34127 | 95508-H34127 | \$ 3,417.00 | 6% | \$3,236.07 |
| PW 4HR ONSITE H34128 | 95508-H34128 | \$ 355.00 | 6% | \$336.20 |
| PW 4HR ONSITE H34129 | 95508-H34129 | \$ 783.00 | 6% | \$741.54 |
| PW 4HR ONSITE H34130 | 95508-H34130 | \$ 814.00 | 6% | \$770.90 |
| PW 4HR ONSITE H34131 | 95508-H34131 | \$ 810.00 | 6% | \$767.11 |
| PW 4HR ONSITE H34132 | 95508-H34132 | \$ 814.00 | 6% | \$770.90 |
| PW 4HR ONSITE H34172 | 95508-H34172 | \$ 3,270.00 | 6% | \$3,096.85 |
| PW 4HR ONSITE H34726 | 95508-H34726 | \$ 5,199.00 | 6% | \$4,923.71 |
| PW 4HR ONSITE H34727 | 95508-H34727 | \$ 5,199.00 | 6% | \$4,923.71 |
| PW 4HR ONSITE H34728 | 95508-H34728 | \$ 5,199.00 | 6% | \$4,923.71 |
| PW 4HR ONSITE H34729 | 95508-H34729 | \$ 5,199.00 | 6% | \$4,923.71 |
| PW 4HR ONSITE H34730 | 95508-H34730 | \$ 5,572.00 | 6% | \$5,276.96 |
| PW 4HR ONSITE H34731 | 95508-H34731 | \$ 5,572.00 | 6% | \$5,276.96 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW 4HR ONSITE H34732 | 95508-H34732 | \$ 5,572.00 | 6% | \$5,276.96 |
| PW 4HR ONSITE H34733 | 95508-H34733 | \$ 5,572.00 | 6% | \$5,276.96 |
| PW 4HR ONSITE H34734 | 95508-H34734 | \$ 806.00 | 6% | \$763.32 |
| PW 4HR ONSITE H34735 | 95508-H34735 | \$ 806.00 | 6% | \$763.32 |
| PW 4HR ONSITE H34736 | 95508-H34736 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H34737 | 95508-H34737 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H34738 | 95508-H34738 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34739 | 95508-H34739 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34740 | 95508-H34740 | \$ 806.00 | 6% | \$763.32 |
| PW 4HR ONSITE H34741 | 95508-H34741 | \$ 806.00 | 6% | \$763.32 |
| PW 4HR ONSITE H34742 | 95508-H34742 | \$ 813.00 | 6% | \$769.95 |
| PW 4HR ONSITE H34743 | 95508-H34743 | \$ 813.00 | 6% | \$769.95 |
| PW 4HR ONSITE H34744 | 95508-H34744 | \$ 1,026.00 | 6% | \$971.67 |
| PW 4HR ONSITE H34745 | 95508-H34745 | \$ 1,026.00 | 6% | \$971.67 |
| PW 4HR ONSITE H34746 | 95508-H34746 | \$ 1,158.00 | 6% | \$1,096.68 |
| PW 4HR ONSITE H34747 | 95508-H34747 | \$ 1,158.00 | 6% | \$1,096.68 |
| PW 4HR ONSITE H34748 | 95508-H34748 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34749 | 95508-H34749 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34750 | 95508-H34750 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34751 | 95508-H34751 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34752 | 95508-H34752 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34753 | 95508-H34753 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34754 | 95508-H34754 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34755 | 95508-H34755 | \$ 1,945.00 | 6% | \$1,842.01 |
| PW 4HR ONSITE H34756 | 95508-H34756 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H34757 | 95508-H34757 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H34758 | 95508-H34758 | \$ 1,026.00 | 6% | \$971.67 |
| PW 4HR ONSITE H34759 | 95508-H34759 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H34760 | 95508-H34760 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H34761 | 95508-H34761 | \$ 1,026.00 | 6% | \$971.67 |
| PW 4HR ONSITE H34839 | 95508-H34839 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34840 | 95508-H34840 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34841 | 95508-H34841 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34842 | 95508-H34842 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34843 | 95508-H34843 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34844 | 95508-H34844 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34845 | 95508-H34845 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34846 | 95508-H34846 | \$ 847.00 | 6% | \$802.15 |
| PW 4HR ONSITE H34993 | 95508-H34993 | \$ 20,550.00 | 6% | \$19,461.88 |
| PW 4HR ONSITE H34994 | 95508-H34994 | \$ 20,550.00 | 6% | \$19,461.88 |
| PW 4HR ONSITE H34996 | 95508-H34996 | \$ 20,550.00 | 6% | \$19,461.88 |
| PW 4HR ONSITE H34997 | 95508-H34997 | \$ 20,550.00 | 6% | \$19,461.88 |

| | | | | |
|-----------------------|--------------|--------------|----|--------------------|
| PW 4HR ONSITE H35005 | 95508-H35005 | \$ 16,214.00 | 6% | <i>\$15,355.47</i> |
| PW 4HR ONSITE H35006 | 95508-H35006 | \$ 16,214.00 | 6% | <i>\$15,355.47</i> |
| PW 4HR ONSITE H35012 | 95508-H35012 | \$ 9,730.00 | 6% | <i>\$9,214.80</i> |
| PW 4HR ONSITE H35092 | 95508-H35092 | \$ 809.00 | 6% | <i>\$766.16</i> |
| PW 4HR ONSITE H35093 | 95508-H35093 | \$ 13,138.00 | 6% | <i>\$12,442.34</i> |
| PW 4HR ONSITE H35094 | 95508-H35094 | \$ 7,289.00 | 6% | <i>\$6,903.05</i> |
| PW 4HR ONSITE H35262 | 95508-H35262 | \$ 3,858.00 | 6% | <i>\$3,653.72</i> |
| PW 4HR ONSITE H35270 | 95508-H35270 | \$ 835.00 | 6% | <i>\$790.79</i> |
| PW 4HR ONSITE H35271 | 95508-H35271 | \$ 625.00 | 6% | <i>\$591.91</i> |
| PW 4HR ONSITE H35272 | 95508-H35272 | \$ 571.00 | 6% | <i>\$540.77</i> |
| PW 4HR ONSITE H35273 | 95508-H35273 | \$ 571.00 | 6% | <i>\$540.77</i> |
| PW 4HR ONSITE H35274 | 95508-H35274 | \$ 1,163.00 | 6% | <i>\$1,101.42</i> |
| PW 4HR ONSITE H35275 | 95508-H35275 | \$ 912.00 | 6% | <i>\$863.71</i> |
| PW 4HR ONSITE H35276 | 95508-H35276 | \$ 4,994.00 | 6% | <i>\$4,729.57</i> |
| PW 4HR ONSITE H35277 | 95508-H35277 | \$ 5,983.00 | 6% | <i>\$5,666.20</i> |
| PW 4HR ONSITE H35278 | 95508-H35278 | \$ 4,251.00 | 6% | <i>\$4,025.91</i> |
| PW 4HR ONSITE H35279 | 95508-H35279 | \$ 4,748.00 | 6% | <i>\$4,496.59</i> |
| PW 4HR ONSITE H35280 | 95508-H35280 | \$ 9,435.00 | 6% | <i>\$8,935.42</i> |
| PW 4HR ONSITE H35281 | 95508-H35281 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35282 | 95508-H35282 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35283 | 95508-H35283 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35284 | 95508-H35284 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35285 | 95508-H35285 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35286 | 95508-H35286 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35287 | 95508-H35287 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35288 | 95508-H35288 | \$ 2,673.00 | 6% | <i>\$2,531.46</i> |
| PW 4HR ONSITE H35289 | 95508-H35289 | \$ 7,068.00 | 6% | <i>\$6,693.75</i> |
| PW 4HR ONSITE H35291 | 95508-H35291 | \$ 5,343.00 | 6% | <i>\$5,060.09</i> |
| PW 4HR ONSITE H35292 | 95508-H35292 | \$ 4,251.00 | 6% | <i>\$4,025.91</i> |
| PW 4HR ONSITE H35293 | 95508-H35293 | \$ 4,748.00 | 6% | <i>\$4,496.59</i> |
| PW 4HR ONSITE H35295 | 95508-H35295 | \$ 746.00 | 6% | <i>\$706.50</i> |
| PW 4hr On-Site H35296 | 95508-H35296 | \$ 9,289.00 | 6% | <i>\$8,797.15</i> |
| PW 4hr On-Site H35297 | 95508-H35297 | \$ 9,289.00 | 6% | <i>\$8,797.15</i> |
| PW 4hr On-Site H35298 | 95508-H35298 | \$ 14,931.00 | 6% | <i>\$14,140.40</i> |
| PW 4hr On-Site H35299 | 95508-H35299 | \$ 14,931.00 | 6% | <i>\$14,140.40</i> |
| PW 4hr On-Site H35302 | 95508-H35302 | \$ 3,604.00 | 6% | <i>\$3,413.17</i> |
| PW 4hr On-Site H35303 | 95508-H35303 | \$ 3,604.00 | 6% | <i>\$3,413.17</i> |
| PW 4hr On-Site H35304 | 95508-H35304 | \$ 3,604.00 | 6% | <i>\$3,413.17</i> |
| PW 4hr On-Site H35305 | 95508-H35305 | \$ 3,775.00 | 6% | <i>\$3,575.11</i> |
| PW 4hr On-Site H35306 | 95508-H35306 | \$ 3,775.00 | 6% | <i>\$3,575.11</i> |
| PW 4hr On-Site H35307 | 95508-H35307 | \$ 3,775.00 | 6% | <i>\$3,575.11</i> |
| PW 4HR ONSITE H35309 | 95508-H35309 | \$ 5,046.00 | 6% | <i>\$4,778.81</i> |

| | | | | |
|----------------------|--------------|-------------|----|------------|
| PW 4HR ONSITE H35310 | 95508-H35310 | \$ 5,046.00 | 6% | \$4,778.81 |
| PW 4HR ONSITE H35311 | 95508-H35311 | \$ 5,046.00 | 6% | \$4,778.81 |
| PW 4HR ONSITE H35312 | 95508-H35312 | \$ 4,166.00 | 6% | \$3,945.41 |
| PW 4HR ONSITE H35313 | 95508-H35313 | \$ 4,166.00 | 6% | \$3,945.41 |
| PW 4HR ONSITE H35314 | 95508-H35314 | \$ 4,166.00 | 6% | \$3,945.41 |
| PW 4HR ONSITE H35315 | 95508-H35315 | \$ 1,806.00 | 6% | \$1,710.37 |
| PW 4HR ONSITE H35318 | 95508-H35318 | \$ 865.00 | 6% | \$819.20 |
| PW 4HR ONSITE H35319 | 95508-H35319 | \$ 1,165.00 | 6% | \$1,103.31 |
| PW 4HR ONSITE H35320 | 95508-H35320 | \$ 1,207.00 | 6% | \$1,143.09 |
| PW 4HR ONSITE H35321 | 95508-H35321 | \$ 1,509.00 | 6% | \$1,429.10 |
| PW 4HR ONSITE H35322 | 95508-H35322 | \$ 1,841.00 | 6% | \$1,743.52 |
| PW 4HR ONSITE H35323 | 95508-H35323 | \$ 1,806.00 | 6% | \$1,710.37 |
| PW 4HR ONSITE H35328 | 95508-H35328 | \$ 156.00 | 6% | \$147.74 |
| PW 4HR ONSITE H35330 | 95508-H35330 | \$ 147.00 | 6% | \$139.22 |
| PW 4HR ONSITE H35340 | 95508-H35340 | \$ 3,334.00 | 6% | \$3,157.46 |
| PW 4HR ONSITE H35341 | 95508-H35341 | \$ 3,334.00 | 6% | \$3,157.46 |
| PW 4HR ONSITE H35342 | 95508-H35342 | \$ 2,948.00 | 6% | \$2,791.90 |
| PW 4HR ONSITE H35343 | 95508-H35343 | \$ 3,334.00 | 6% | \$3,157.46 |
| PW 4HR ONSITE H35344 | 95508-H35344 | \$ 3,479.00 | 6% | \$3,294.79 |
| PW 4HR ONSITE H35345 | 95508-H35345 | \$ 3,479.00 | 6% | \$3,294.79 |
| PW 4HR ONSITE H35346 | 95508-H35346 | \$ 3,058.00 | 6% | \$2,896.08 |
| PW 4HR ONSITE H35347 | 95508-H35347 | \$ 3,479.00 | 6% | \$3,294.79 |
| PW 4HR ONSITE H35349 | 95508-H35349 | \$ 3,838.00 | 6% | \$3,634.78 |
| PW 4HR ONSITE H35350 | 95508-H35350 | \$ 3,838.00 | 6% | \$3,634.78 |
| PW 4HR ONSITE H35351 | 95508-H35351 | \$ 3,349.00 | 6% | \$3,171.67 |
| PW 4HR ONSITE H35352 | 95508-H35352 | \$ 3,838.00 | 6% | \$3,634.78 |
| PW 4HR ONSITE H35359 | 95508-H35359 | \$ 1,509.00 | 6% | \$1,429.10 |
| PW 4HR ONSITE H35360 | 95508-H35360 | \$ 1,841.00 | 6% | \$1,743.52 |
| PW 4HR ONSITE H35361 | 95508-H35361 | \$ 1,806.00 | 6% | \$1,710.37 |
| PW 4HR ONSITE H35362 | 95508-H35362 | \$ 865.00 | 6% | \$819.20 |
| PW 4HR ONSITE H35366 | 95508-H35366 | \$ 1,960.00 | 6% | \$1,856.22 |
| PW 4HR ONSITE H35367 | 95508-H35367 | \$ 2,286.00 | 6% | \$2,164.96 |
| PW 4HR ONSITE H35368 | 95508-H35368 | \$ 3,479.00 | 6% | \$3,294.79 |
| PW 4HR ONSITE H35369 | 95508-H35369 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW 4HR ONSITE H35370 | 95508-H35370 | \$ 1,588.00 | 6% | \$1,503.92 |
| PW 4HR ONSITE H35375 | 95508-H35375 | \$ 954.00 | 6% | \$903.49 |
| PW 4HR ONSITE H35376 | 95508-H35376 | \$ 1,431.00 | 6% | \$1,355.23 |
| PW 4HR ONSITE H35377 | 95508-H35377 | \$ 599.00 | 6% | \$567.28 |
| PW 4HR ONSITE H35378 | 95508-H35378 | \$ 954.00 | 6% | \$903.49 |
| PW 4HR ONSITE H35379 | 95508-H35379 | \$ 599.00 | 6% | \$567.28 |
| PW 4HR ONSITE H35380 | 95508-H35380 | \$ 1,074.00 | 6% | \$1,017.13 |
| PW 4HR ONSITE H35381 | 95508-H35381 | \$ 1,310.00 | 6% | \$1,240.64 |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PW 4HR ONSITE H35384 | 95508-H35384 | \$ 433.00 | 6% | <i>\$410.07</i> |
| PW 4HR ONSITE H35385 | 95508-H35385 | \$ 573.00 | 6% | <i>\$542.66</i> |
| PW 4HR ONSITE H35386 | 95508-H35386 | \$ 954.00 | 6% | <i>\$903.49</i> |
| PW 4HR ONSITE H35387 | 95508-H35387 | \$ 893.00 | 6% | <i>\$845.72</i> |
| PW 4HR ONSITE H35388 | 95508-H35388 | \$ 655.00 | 6% | <i>\$620.32</i> |
| PW 4HR ONSITE H35389 | 95508-H35389 | \$ 369.00 | 6% | <i>\$349.46</i> |
| PW 4HR ONSITE H35390 | 95508-H35390 | \$ 321.00 | 6% | <i>\$304.00</i> |
| PW 4HR ONSITE H35391 | 95508-H35391 | \$ 701.00 | 6% | <i>\$663.88</i> |
| PW 4HR ONSITE H35392 | 95508-H35392 | \$ 1,074.00 | 6% | <i>\$1,017.13</i> |
| PW 4HR ONSITE H35393 | 95508-H35393 | \$ 1,431.00 | 6% | <i>\$1,355.23</i> |
| PW 4HR ONSITE H35394 | 95508-H35394 | \$ 260.00 | 6% | <i>\$246.23</i> |
| PW 4HR ONSITE H35395 | 95508-H35395 | \$ 216.00 | 6% | <i>\$204.56</i> |
| PW 4HR ONSITE H35396 | 95508-H35396 | \$ 260.00 | 6% | <i>\$246.23</i> |
| PW 4HR ONSITE H35397 | 95508-H35397 | \$ 216.00 | 6% | <i>\$204.56</i> |
| PW 4HR ONSITE H35398 | 95508-H35398 | \$ 668.00 | 6% | <i>\$632.63</i> |
| PW 4HR ONSITE H35399 | 95508-H35399 | \$ 815.00 | 6% | <i>\$771.85</i> |
| PW 4HR ONSITE H35400 | 95508-H35400 | \$ 897.00 | 6% | <i>\$849.50</i> |
| PW 4HR ONSITE H35401 | 95508-H35401 | \$ 477.00 | 6% | <i>\$451.74</i> |
| PW 4HR ONSITE H35415 | 95508-H35415 | \$ 327.00 | 6% | <i>\$309.69</i> |
| PW 4HR ONSITE H35416 | 95508-H35416 | \$ 327.00 | 6% | <i>\$309.69</i> |
| PW 4HR ONSITE H35426 | 95508-H35426 | \$ 369.00 | 6% | <i>\$349.46</i> |
| PW 4HR ONSITE H35427 | 95508-H35427 | \$ 893.00 | 6% | <i>\$845.72</i> |
| PW 4HR ONSITE H35428 | 95508-H35428 | \$ 321.00 | 6% | <i>\$304.00</i> |
| PW 4HR ONSITE H35429 | 95508-H35429 | \$ 701.00 | 6% | <i>\$663.88</i> |
| PW 4HR ONSITE H35430 | 95508-H35430 | \$ 783.00 | 6% | <i>\$741.54</i> |
| PW 4HR ONSITE H35431 | 95508-H35431 | \$ 783.00 | 6% | <i>\$741.54</i> |
| PW 4HR ONSITE H35432 | 95508-H35432 | \$ 813.00 | 6% | <i>\$769.95</i> |
| PW 4HR ONSITE H35433 | 95508-H35433 | \$ 1,001.00 | 6% | <i>\$948.00</i> |
| PW 4HR ONSITE H35434 | 95508-H35434 | \$ 1,130.00 | 6% | <i>\$1,070.17</i> |
| PW 4HR ONSITE H35435 | 95508-H35435 | \$ 1,130.00 | 6% | <i>\$1,070.17</i> |
| PW 4HR ONSITE H35436 | 95508-H35436 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |
| PW 4HR ONSITE H35437 | 95508-H35437 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |
| PW 4HR ONSITE H35438 | 95508-H35438 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |
| PW 4HR ONSITE H35439 | 95508-H35439 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |
| PW 4HR ONSITE H35440 | 95508-H35440 | \$ 1,001.00 | 6% | <i>\$948.00</i> |
| PW 4HR ONSITE H35441 | 95508-H35441 | \$ 1,001.00 | 6% | <i>\$948.00</i> |
| PW 4HR ONSITE H35442 | 95508-H35442 | \$ 1,001.00 | 6% | <i>\$948.00</i> |
| PW 4HR ONSITE H35443 | 95508-H35443 | \$ 5,199.00 | 6% | <i>\$4,923.71</i> |
| PW 4HR ONSITE H35444 | 95508-H35444 | \$ 5,572.00 | 6% | <i>\$5,276.96</i> |
| PW 4HR ONSITE H35445 | 95508-H35445 | \$ 4,994.00 | 6% | <i>\$4,729.57</i> |
| PW 4HR ONSITE H35446 | 95508-H35446 | \$ 4,898.00 | 6% | <i>\$4,638.65</i> |
| PW 4HR ONSITE H35447 | 95508-H35447 | \$ 5,670.00 | 6% | <i>\$5,369.77</i> |

| | | | | |
|---------------------------------|-------------------------|--------------|----|-------------|
| PW 4HR ONSITE H35448 | 95508-H35448 | \$ 5,443.00 | 6% | \$5,154.79 |
| PW 4HR ONSITE H35449 | 95508-H35449 | \$ 4,251.00 | 6% | \$4,025.91 |
| PW 4HR ONSITE H35450 | 95508-H35450 | \$ 4,500.00 | 6% | \$4,261.73 |
| PW 4HR ONSITE H35451 | 95508-H35451 | \$ 9,986.00 | 6% | \$9,457.24 |
| PW 4HR ONSITE H35452 | 95508-H35452 | \$ 9,986.00 | 6% | \$9,457.24 |
| PW 4HR ONSITE H35453 | 95508-H35453 | \$ 5,572.00 | 6% | \$5,276.96 |
| PW 4HR ONSITE H35454 | 95508-H35454 | \$ 5,199.00 | 6% | \$4,923.71 |
| PW 4HR ONSITE H35455 | 95508-H35455 | \$ 1,207.00 | 6% | \$1,143.09 |
| PW 4HR ONSITE H35456 | 95508-H35456 | \$ 1,499.00 | 6% | \$1,419.63 |
| PW 4HR ONSITE H35457 | 95508-H35457 | \$ 1,343.00 | 6% | \$1,271.89 |
| PW 4HR ONSITE H35458 | 95508-H35458 | \$ 1,475.00 | 6% | \$1,396.90 |
| PW 4HR ONSITE H35471 | 95508-H35471 | \$ 1,207.00 | 6% | \$1,143.09 |
| PW 4HR ONSITE H35600 | 95508-H35600 | \$ 571.00 | 6% | \$540.77 |
| PW 4HR ONSITE H35601 | 95508-H35601 | \$ 571.00 | 6% | \$540.77 |
| PW 4HR ONSITE H35602 | 95508-H35602 | \$ 806.00 | 6% | \$763.32 |
| PW 4HR ONSITE H35603 | 95508-H35603 | \$ 806.00 | 6% | \$763.32 |
| PW 4HR ONSITE H35604 | 95508-H35604 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H35605 | 95508-H35605 | \$ 1,031.00 | 6% | \$976.41 |
| PW 4HR ONSITE H35606 | 95508-H35606 | \$ 1,163.00 | 6% | \$1,101.42 |
| PW 4HR ONSITE H35607 | 95508-H35607 | \$ 1,158.00 | 6% | \$1,096.68 |
| PW 4HR ONSITE ISW-24W-4X | 95508-ISW-24W-4X | \$ 1,269.00 | 6% | \$1,201.81 |
| PW 4HR ONSITE ISW-4W-4WS-4X | 95508-ISW-4W-4WS-4X | \$ 806.00 | 6% | \$763.32 |
| PW 4HR ONSITE BD MSM128 | 95508-MSM128 | \$ 4,238.00 | 6% | \$4,013.60 |
| PW 4HR ONSITE BD MSM48C | 95508-MSM48C | \$ 2,529.00 | 6% | \$2,395.09 |
| PW 4HR ONSITE SLX9150-48XT-DC-F | 95508-SLX9150-48XT-DC-F | \$ 3,034.00 | 6% | \$2,873.35 |
| PW 4HR ONSITE SLX9150-48XT-DC-R | 95508-SLX9150-48XT-DC-R | \$ 3,313.00 | 6% | \$3,137.58 |
| PW 4HR ONSITE SLX9150-48Y-DC-F | 95508-SLX9150-48Y-DC-F | \$ 2,908.00 | 6% | \$2,754.02 |
| PW 4HR ONSITE SLX9150-48Y-DC-R | 95508-SLX9150-48Y-DC-R | \$ 3,175.00 | 6% | \$3,006.88 |
| PW 4HR ONSITE SLX9740-40C | 95508-SLX9740-40C | \$ 13,074.00 | 6% | \$12,381.73 |

| | | | | |
|---------------------------------|------------------------|--------------|----|--------------------|
| PW 4HR ONSITE SLX9740-40C-AC-F | 95508-SLX9740-40C-AC-F | \$ 13,074.00 | 6% | <i>\$12,381.73</i> |
| PW 4HR ONSITE SLX9740-40C-AC-R | 95508-SLX9740-40C-AC-R | \$ 13,074.00 | 6% | <i>\$12,381.73</i> |
| PW 4HR ONSITE SLX9740-40C-DC-F | 95508-SLX9740-40C-DC-F | \$ 13,074.00 | 6% | <i>\$12,381.73</i> |
| PW 4HR ONSITE SLX9740-80C | 95508-SLX9740-80C | \$ 24,585.00 | 6% | <i>\$23,283.22</i> |
| PW 4HR ONSITE SLX9740-80C-AC-F | 95508-SLX9740-80C-AC-F | \$ 24,585.00 | 6% | <i>\$23,283.22</i> |
| PW 4HR ONSITE SLX9740-80C-AC-R | 95508-SLX9740-80C-AC-R | \$ 24,585.00 | 6% | <i>\$23,283.22</i> |
| PW 4HR ONSITE SLX9740-80C-DC-F | 95508-SLX9740-80C-DC-F | \$ 24,585.00 | 6% | <i>\$23,283.22</i> |
| PW 4HR ONSITE V300-8P-2X | 95508-V300-8P-2X | \$ 203.00 | 6% | <i>\$192.25</i> |
| PW 4HR ONSITE V300-8T-2X | 95508-V300-8T-2X | \$ 139.00 | 6% | <i>\$131.64</i> |
| PW 4HR ONSITE V300HT-8P-2X | 95508-V300HT-8P-2X | \$ 461.00 | 6% | <i>\$436.59</i> |
| PW 4HR ONSITE V300HT-8T-2X | 95508-V300HT-8T-2X | \$ 278.00 | 6% | <i>\$263.28</i> |
| PW 4HR ONSITE Summit VIM-SS | 95508-VIM-SS | \$ 207.00 | 6% | <i>\$196.04</i> |
| PW 4HR ONSITE Summit VIM-SSV80 | 95508-VIM-SSV80 | \$ 400.00 | 6% | <i>\$378.82</i> |
| PW 4HR ONSITE Summit VIM2-SS | 95508-VIM2-SS | \$ 246.00 | 6% | <i>\$232.97</i> |
| PW 4HR ONSITE Summit VIM2-SS128 | 95508-VIM2-SS128 | \$ 857.00 | 6% | <i>\$811.62</i> |
| PW 4HR ONSITE Summit VIM2-V80 | 95508-VIM2-V80 | \$ 913.00 | 6% | <i>\$864.66</i> |
| PW 4HR ONSITE Summit VIM210G4X | 95508-VIM210G4X | \$ 1,583.00 | 6% | <i>\$1,499.18</i> |

| | | | | |
|-------------------------------------|-----------------------------|-------------|----|------------|
| PW 4HR ONSITE VIM5-2Q | 95508-VIM5-2Q | \$ 277.00 | 6% | \$262.33 |
| PW 4HR ONSITE VIM5-2Y | 95508-VIM5-2Y | \$ 324.00 | 6% | \$306.84 |
| PW 4HR ONSITE VIM5-4X | 95508-VIM5-4X | \$ 134.00 | 6% | \$126.90 |
| PW 4HR ONSITE VIM5-4XE | 95508-VIM5-4XE | \$ 268.00 | 6% | \$253.81 |
| PW 4HR ONSITE VIM5-4Y | 95508-VIM5-4Y | \$ 417.00 | 6% | \$394.92 |
| PW 4HR ONSITE VIM5-4YE | 95508-VIM5-4YE | \$ 534.00 | 6% | \$505.72 |
| PW 4HR ONSITE VSP4900-12MXU-12XE | 95508-VSP4900-12MXU-12XE | \$ 1,583.00 | 6% | \$1,499.18 |
| PW 4HR ONSITE VSP4900-12MXU-12XE-B1 | 95508-VSP4900-12MXU-12XE-B1 | \$ 1,583.00 | 6% | \$1,499.18 |
| PW 4HR ONSITE VSP4900-24S | 95508-VSP4900-24S | \$ 865.00 | 6% | \$819.20 |
| PW 4HR ONSITE VSP4900-24S-B3 | 95508-VSP4900-24S-B3 | \$ 865.00 | 6% | \$819.20 |
| PW 4HR ONSITE VSP4900-24XE | 95508-VSP4900-24XE | \$ 1,583.00 | 6% | \$1,499.18 |
| PW 4HR ONSITE VSP4900-24XE-B3 | 95508-VSP4900-24XE-B3 | \$ 1,583.00 | 6% | \$1,499.18 |
| PW 4HR ONSITE X435-24P-4S | 95508-X435-24P-4S | \$ 362.00 | 6% | \$342.83 |
| PW 4HR ONSITE X435-24T-4S | 95508-X435-24T-4S | \$ 199.00 | 6% | \$188.46 |
| PW 4HR ONSITE X435-8P-2T-W | 95508-X435-8P-2T-W | \$ 199.00 | 6% | \$188.46 |
| PW 4HR ONSITE X435-8P-4S | 95508-X435-8P-4S | \$ 180.00 | 6% | \$170.47 |
| PW 4HR ONSITE X435-8T-4S | 95508-X435-8T-4S | \$ 144.00 | 6% | \$136.38 |
| PW 4HR ONSITE Summit X460-24P | 95508-X460-24P | \$ 1,491.00 | 6% | \$1,412.05 |

| | | | | |
|---------------------------------|-----------------------|-------------|----|-------------------|
| PW 4HR ONSITE Summit X460-24T | 95508-X460-24T | \$ 1,043.00 | 6% | <i>\$987.77</i> |
| PW 4HR ONSITE Summit X460-24TDC | 95508-X460-24TDC | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| PW 4HR ONSITE Summit X460-24X | 95508-X460-24X | \$ 1,932.00 | 6% | <i>\$1,829.70</i> |
| PW 4HR ONSITE Summit X460-24XDC | 95508-X460-24XDC | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PW 4HR ONSITE Summit X460-48P | 95508-X460-48P | \$ 1,932.00 | 6% | <i>\$1,829.70</i> |
| PW 4HR ONSITE Summit X460-48T | 95508-X460-48T | \$ 1,652.00 | 6% | <i>\$1,564.53</i> |
| PW 4HR ONSITE Summit X460-48TDC | 95508-X460-48TDC | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| PW 4HR ONSITE Summit X460-48X | 95508-X460-48X | \$ 2,569.00 | 6% | <i>\$2,432.97</i> |
| PW 4HR ONSITE Summit X460-48XDC | 95508-X460-48XDC | \$ 2,503.00 | 6% | <i>\$2,370.47</i> |
| PW 4HR ONSITE X465-24MU | 95508-X465-24MU | \$ 1,841.00 | 6% | <i>\$1,743.52</i> |
| PW 4HR ONSITE X465-24S | 95508-X465-24S | \$ 865.00 | 6% | <i>\$819.20</i> |
| PW 4HR ONSITE X465-24S-B3 | 95508-X465-24S-B3 | \$ 865.00 | 6% | <i>\$819.20</i> |
| PW 4HR ONSITE X465-24W | 95508-X465-24W | \$ 865.00 | 6% | <i>\$819.20</i> |
| PW 4HR ONSITE X465-24XE | 95508-X465-24XE | \$ 1,583.00 | 6% | <i>\$1,499.18</i> |
| PW 4HR ONSITE X465-24XE-B3 | 95508-X465-24XE-B3 | \$ 1,583.00 | 6% | <i>\$1,499.18</i> |
| PW 4HR ONSITE X465-48P | 95508-X465-48P | \$ 1,207.00 | 6% | <i>\$1,143.09</i> |
| PW 4HR ONSITE X465-48T | 95508-X465-48T | \$ 1,165.00 | 6% | <i>\$1,103.31</i> |
| PW 4HR ONSITE X465-48W | 95508-X465-48W | \$ 1,509.00 | 6% | <i>\$1,429.10</i> |
| PW 4HR ONSITE X465i-48W | 95508-X465i-48W | \$ 1,806.00 | 6% | <i>\$1,710.37</i> |
| PW 4HR ONSITE X465i-48W-B1-S1 | 95508-X465i-48W-B1-S1 | \$ 1,806.00 | 6% | <i>\$1,710.37</i> |
| PW 4HR ONSITE X465i-48W-B2-S1 | 95508-X465i-48W-B2-S1 | \$ 1,806.00 | 6% | <i>\$1,710.37</i> |

| | | | | |
|-------------------------------|-------------------|-------------|----|------------|
| PW 4HR ONSITE Summit X480-24X | 95508-X480-24X | \$ 2,374.00 | 6% | \$2,248.30 |
| PW 4HR ONSITE Summit X480-48T | 95508-X480-48T | \$ 2,374.00 | 6% | \$2,248.30 |
| PW 4HR ONSITE Summit X480-48X | 95508-X480-48X | \$ 3,166.00 | 6% | \$2,998.36 |
| PW 4HR ONSITE X695-48Y-8C | 95508-X695-48Y-8C | \$ 4,216.00 | 6% | \$3,992.76 |
| PW 4HR ONSITE XA1440 | 95508-XA1440 | \$ 442.00 | 6% | \$418.60 |
| PW 4HR ONSITE XA1480 | 95508-XA1480 | \$ 589.00 | 6% | \$557.81 |
| PW 4HR ONSITE Summit XGM3-2SF | 95508-XGM3-2SF | \$ 400.00 | 6% | \$378.82 |
| PW 4HR ONSITE XR600 | 95508-XR600 | \$ 122.00 | 6% | \$115.54 |
| PW 4HR ON-SITE -ZR-XFP | 95508-ZR-XFP | \$ 2,393.00 | 6% | \$2,266.29 |
| PW NBD ONSITE Optics 10200 | 95511-10200 | \$ 2,158.00 | 6% | \$2,043.73 |
| PW NBD ONSITE Optics 10320 | 95511-10320 | \$ 2,374.00 | 6% | \$2,248.30 |
| PW NBD ONSITE 10335 | 95511-10335 | \$ 4,099.00 | 6% | \$3,881.96 |
| PW NBD ONSITE 10403 | 95511-10403 | \$ 5,089.00 | 6% | \$4,819.54 |
| PW NBD ONSITE 10404 | 95511-10404 | \$ 2,499.00 | 6% | \$2,366.68 |
| PW NBD ONSITE 10441 | 95511-10441 | \$ 1,680.00 | 6% | \$1,591.04 |
| PW NBD ONSITE 10442 | 95511-10442 | \$ 1,780.00 | 6% | \$1,685.75 |
| PW NBD ONSITE 1130C | 95511-1130C | \$ 1,080.00 | 6% | \$1,022.81 |
| PW NBD ONSITE E4G 16119 | 95511-16119 | \$ 303.00 | 6% | \$286.96 |
| PW NBD ONSITE E4G 16120 | 95511-16120 | \$ 389.00 | 6% | \$368.40 |
| PW NBD ONSITE E4G 16126 | 95511-16126 | \$ 303.00 | 6% | \$286.96 |
| PW NBD ONSITE E4G 16127 | 95511-16127 | \$ 318.00 | 6% | \$301.16 |
| PW NBD ONSITE 16172 | 95511-16172 | \$ 317.00 | 6% | \$300.21 |
| PW NBD ONSITE -16172T | 95511-16172T | \$ 386.00 | 6% | \$365.56 |
| PW NBD ONSITE 16173 | 95511-16173 | \$ 326.00 | 6% | \$308.74 |
| PW NBD ONSITE -16173T | 95511-16173T | \$ 392.00 | 6% | \$371.24 |
| PW NBD ONSITE 16174 | 95511-16174 | \$ 501.00 | 6% | \$474.47 |
| PW NBD ONSITE 16175 | 95511-16175 | \$ 532.00 | 6% | \$503.83 |
| PW NBD ONSITE 16176 | 95511-16176 | \$ 473.00 | 6% | \$447.95 |
| PW NBD ONSITE 16177 | 95511-16177 | \$ 455.00 | 6% | \$430.91 |
| PW NBD ONSITE -16177T | 95511-16177T | \$ 584.00 | 6% | \$553.08 |
| PW NBD ONSITE 16178 | 95511-16178 | \$ 681.00 | 6% | \$644.94 |
| PW NBD ONSITE 16179 | 95511-16179 | \$ 694.00 | 6% | \$657.25 |

| | | | | |
|-------------------------------|--------------|-------------|----|------------|
| PW NBD ONSITE -16179T | 95511-16179T | \$ 828.00 | 6% | \$784.16 |
| PW NBD ONSITE 16301T | 95511-16301T | \$ 1,824.00 | 6% | \$1,727.42 |
| PW NBD ONSITE 16303T | 95511-16303T | \$ 1,824.00 | 6% | \$1,727.42 |
| PW NBD ONSITE 16304T | 95511-16304T | \$ 2,435.00 | 6% | \$2,306.07 |
| PW NBD ONSITE 16401T | 95511-16401T | \$ 851.00 | 6% | \$805.94 |
| PW NBD ONSITE 16402T | 95511-16402T | \$ 1,299.00 | 6% | \$1,230.22 |
| PW NBD ONSITE 16403T | 95511-16403T | \$ 1,153.00 | 6% | \$1,091.95 |
| PW NBD ONSITE 16404T | 95511-16404T | \$ 1,153.00 | 6% | \$1,091.95 |
| PW NBD ONSITE 16405T | 95511-16405T | \$ 1,527.00 | 6% | \$1,446.15 |
| PW NBD ONSITE 16406T | 95511-16406T | \$ 2,025.00 | 6% | \$1,917.78 |
| PW NBD ONSITE E4G 16431 | 95511-16431 | \$ 1,286.00 | 6% | \$1,217.91 |
| PW NBD ONSITE E4G 16432 | 95511-16432 | \$ 1,390.00 | 6% | \$1,316.40 |
| PW NBD ONSITE E4G 16440 | 95511-16440 | \$ 798.00 | 6% | \$755.75 |
| PW NBD ONSITE E4G 16441 | 95511-16441 | \$ 722.00 | 6% | \$683.77 |
| PW NBD ONSITE E4G 16442 | 95511-16442 | \$ 318.00 | 6% | \$301.16 |
| PW NBD ONSITE E4G 16444 | 95511-16444 | \$ 160.00 | 6% | \$151.53 |
| PW NBD ONSITE Summit 16501 | 95511-16501 | \$ 177.00 | 6% | \$167.63 |
| PW NBD ONSITE 16501T | 95511-16501T | \$ 229.00 | 6% | \$216.87 |
| PW NBD ONSITE Summit 16502 | 95511-16502 | \$ 257.00 | 6% | \$243.39 |
| PW NBD ONSITE 16502T | 95511-16502T | \$ 301.00 | 6% | \$285.06 |
| PW NBD ONSITE Summit 16503 | 95511-16503 | \$ 207.00 | 6% | \$196.04 |
| PW NBD ONSITE 16503T | 95511-16503T | \$ 271.00 | 6% | \$256.65 |
| PW NBD ONSITE Summit 16504 | 95511-16504 | \$ 340.00 | 6% | \$322.00 |
| PW NBD ONSITE 16504T | 95511-16504T | \$ 418.00 | 6% | \$395.87 |
| PW NBD ONSITE Summit 16505 | 95511-16505 | \$ 383.00 | 6% | \$362.72 |
| PW NBD ONSITE 16505T | 95511-16505T | \$ 470.00 | 6% | \$445.11 |
| PW NBD ONSITE Summit 16506 | 95511-16506 | \$ 483.00 | 6% | \$457.43 |
| PW NBD ONSITE 16506T | 95511-16506T | \$ 603.00 | 6% | \$571.07 |
| PW NBD ONSITE Summit 16507 | 95511-16507 | \$ 529.00 | 6% | \$500.99 |
| PW NBD ONSITE 16507T | 95511-16507T | \$ 639.00 | 6% | \$605.16 |
| PW NBD ONSITE Summit 16508 | 95511-16508 | \$ 668.00 | 6% | \$632.63 |
| PW NBD ONSITE 16508T | 95511-16508T | \$ 800.00 | 6% | \$757.64 |
| PW NBD ONSITE Summit 16509 | 95511-16509 | \$ 668.00 | 6% | \$632.63 |

| | | | | |
|----------------------------|--------------|-----------|----|----------|
| PW NBD ONSITE 16509T | 95511-16509T | \$ 800.00 | 6% | \$757.64 |
| PW NBD ONSITE Summit 16510 | 95511-16510 | \$ 800.00 | 6% | \$757.64 |
| PW NBD ONSITE 16510T | 95511-16510T | \$ 963.00 | 6% | \$912.01 |
| PW NBD On-site-16513 | 95511-16513 | \$ 521.00 | 6% | \$493.41 |
| PW NBD On-site-16514 | 95511-16514 | \$ 785.00 | 6% | \$743.43 |
| PW NBD ONSITE 16515 | 95511-16515 | \$ 136.00 | 6% | \$128.80 |
| PW NBD Onsite-16516 | 95511-16516 | \$ 152.00 | 6% | \$143.95 |
| PW NBD ONSITE 16517 | 95511-16517 | \$ 282.00 | 6% | \$267.07 |
| PW NBD Onsite-16518 | 95511-16518 | \$ 254.00 | 6% | \$240.55 |
| PW-NBD On-SITE 16519 | 95511-16519 | \$ 271.00 | 6% | \$256.65 |
| PW-NBD On-SITE 16520 | 95511-16520 | \$ 440.00 | 6% | \$416.70 |
| PW NBD ONSITE 16530 | 95511-16530 | \$ 161.00 | 6% | \$152.48 |
| PW NBD ONSITE 16531 | 95511-16531 | \$ 213.00 | 6% | \$201.72 |
| PW NBD ONSITE 16531T | 95511-16531T | \$ 237.00 | 6% | \$224.45 |
| PW NBD ONSITE 16532 | 95511-16532 | \$ 213.00 | 6% | \$201.72 |
| PW NBD ONSITE 16532T | 95511-16532T | \$ 237.00 | 6% | \$224.45 |
| PW NBD ONSITE 16533 | 95511-16533 | \$ 307.00 | 6% | \$290.74 |
| PW NBD ONSITE 16533T | 95511-16533T | \$ 334.00 | 6% | \$316.31 |
| PW NBD ONSITE 16534 | 95511-16534 | \$ 326.00 | 6% | \$308.74 |
| PW NBD ONSITE 16535 | 95511-16535 | \$ 487.00 | 6% | \$461.21 |
| PW NBD ONSITE 16535A | 95511-16535A | \$ 487.00 | 6% | \$461.21 |
| PW NBD ONSITE 16535T | 95511-16535T | \$ 540.00 | 6% | \$511.41 |
| PW NBD ONSITE 16536 | 95511-16536 | \$ 229.00 | 6% | \$216.87 |
| PW NBD ONSITE 16537 | 95511-16537 | \$ 304.00 | 6% | \$287.90 |
| PW NBD ONSITE 16538 | 95511-16538 | \$ 367.00 | 6% | \$347.57 |
| PW NBD ONSITE 16538T | 95511-16538T | \$ 450.00 | 6% | \$426.17 |
| PW NBD ONSITE 16539 | 95511-16539 | \$ 477.00 | 6% | \$451.74 |
| PW NBD ONSITE 16540 | 95511-16540 | \$ 338.00 | 6% | \$320.10 |
| PW NBD ONSITE 16541 | 95511-16541 | \$ 129.00 | 6% | \$122.17 |
| PW NBD ONSITE 16560 | 95511-16560 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE 16561 | 95511-16561 | \$ 109.00 | 6% | \$103.23 |
| PW NBD ONSITE 16562 | 95511-16562 | \$ 130.00 | 6% | \$123.12 |
| PW NBD ONSITE 16563 | 95511-16563 | \$ 171.00 | 6% | \$161.95 |
| PW NBD ONSITE 16564 | 95511-16564 | \$ 212.00 | 6% | \$200.77 |
| PW NBD ONSITE 16565 | 95511-16565 | \$ 321.00 | 6% | \$304.00 |
| PW NBD ONSITE 16566 | 95511-16566 | \$ 49.00 | 6% | \$46.41 |
| PW NBD ONSITE 16567 | 95511-16567 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE 16568 | 95511-16568 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE 16569 | 95511-16569 | \$ 117.00 | 6% | \$110.80 |
| PW NBD ONSITE 16570 | 95511-16570 | \$ 130.00 | 6% | \$123.12 |
| PW NBD ONSITE 16571 | 95511-16571 | \$ 212.00 | 6% | \$200.77 |

| | | | | |
|-----------------------|--------------|-------------|----|------------|
| PW NBD ONSITE 16701 | 95511-16701 | \$ 463.00 | 6% | \$438.48 |
| PW NBD ONSITE 16702 | 95511-16702 | \$ 691.00 | 6% | \$654.41 |
| PW NBD ONSITE 16703 | 95511-16703 | \$ 542.00 | 6% | \$513.30 |
| PW NBD ONSITE -16703T | 95511-16703T | \$ 651.00 | 6% | \$616.53 |
| PW NBD ONSITE 16704 | 95511-16704 | \$ 799.00 | 6% | \$756.69 |
| PW NBD ONSITE -16704T | 95511-16704T | \$ 961.00 | 6% | \$910.12 |
| PW NBD ONSITE 16705 | 95511-16705 | \$ 691.00 | 6% | \$654.41 |
| PW NBD ONSITE -16705T | 95511-16705T | \$ 826.00 | 6% | \$782.26 |
| PW NBD ONSITE 16706 | 95511-16706 | \$ 1,049.00 | 6% | \$993.46 |
| PW NBD ONSITE -16706T | 95511-16706T | \$ 1,274.00 | 6% | \$1,206.54 |
| PW NBD ONSITE 16710 | 95511-16710 | \$ 214.00 | 6% | \$202.67 |
| PW NBD ONSITE 16710T | 95511-16710T | \$ 254.00 | 6% | \$240.55 |
| PW NBD ONSITE 16711 | 95511-16711 | \$ 88.00 | 6% | \$83.34 |
| PW NBD ONSITE 16711T | 95511-16711T | \$ 99.00 | 6% | \$93.76 |
| PW NBD ONSITE 16712 | 95511-16712 | \$ 121.00 | 6% | \$114.59 |
| PW NBD ONSITE 16712T | 95511-16712T | \$ 140.00 | 6% | \$132.59 |
| PW NBD ONSITE 16713 | 95511-16713 | \$ 53.00 | 6% | \$50.19 |
| PW NBD ONSITE 16713T | 95511-16713T | \$ 59.00 | 6% | \$55.88 |
| PW NBD ONSITE 16715 | 95511-16715 | \$ 86.00 | 6% | \$81.45 |
| PW NBD ONSITE 16715T | 95511-16715T | \$ 99.00 | 6% | \$93.76 |
| PW NBD ONSITE 16716 | 95511-16716 | \$ 359.00 | 6% | \$339.99 |
| PW NBD ONSITE -16716T | 95511-16716T | \$ 446.00 | 6% | \$422.38 |
| PW NBD ONSITE 16717 | 95511-16717 | \$ 554.00 | 6% | \$524.67 |
| PW NBD ONSITE 16718 | 95511-16718 | \$ 398.00 | 6% | \$376.93 |
| PW NBD ONSITE -16718T | 95511-16718T | \$ 483.00 | 6% | \$457.43 |
| PW NBD ONSITE 16719 | 95511-16719 | \$ 587.00 | 6% | \$555.92 |
| PW NBD ONSITE -16719T | 95511-16719T | \$ 713.00 | 6% | \$675.25 |
| PW NBD ONSITE 16720 | 95511-16720 | \$ 884.00 | 6% | \$837.19 |
| PW NBD ONSITE 16720T | 95511-16720T | \$ 1,027.00 | 6% | \$972.62 |
| PW NBD ONSITE 16756 | 95511-16756 | \$ 646.00 | 6% | \$611.79 |
| PW NBD ONSITE 16756T | 95511-16756T | \$ 765.00 | 6% | \$724.49 |
| PW NBD ONSITE 16757 | 95511-16757 | \$ 609.00 | 6% | \$576.75 |
| PW NBD ONSITE 16757T | 95511-16757T | \$ 716.00 | 6% | \$678.09 |
| PW NBD ONSITE 16790 | 95511-16790 | \$ 1,427.00 | 6% | \$1,351.44 |
| PW NBD ONSITE 16791 | 95511-16791 | \$ 1,839.00 | 6% | \$1,741.62 |
| PW NBD ONSITE 16801 | 95511-16801 | \$ 177.00 | 6% | \$167.63 |
| PW NBD ONSITE 16802 | 95511-16802 | \$ 205.00 | 6% | \$194.15 |
| PW NBD ONSITE 16803 | 95511-16803 | \$ 217.00 | 6% | \$205.51 |
| PW NBD ONSITE 16804 | 95511-16804 | \$ 273.00 | 6% | \$258.54 |
| PW NBD ONSITE 16805 | 95511-16805 | \$ 54.00 | 6% | \$51.14 |
| PW NBD ONSITE 16806 | 95511-16806 | \$ 40.00 | 6% | \$37.88 |

| | | | | |
|-----------------------------|--------------|-------------|----|------------|
| PW NBD ONSITE Summit 17101 | 95511-17101 | \$ 2,702.00 | 6% | \$2,558.93 |
| PW NBD ONSITE 17101T | 95511-17101T | \$ 3,463.00 | 6% | \$3,279.63 |
| PW NBD ONSITE Summit 17102 | 95511-17102 | \$ 2,702.00 | 6% | \$2,558.93 |
| PW NBD ONSITE 17102T | 95511-17102T | \$ 3,463.00 | 6% | \$3,279.63 |
| PW NBD ONSITE Summit 17103 | 95511-17103 | \$ 1,888.00 | 6% | \$1,788.03 |
| PW NBD ONSITE Summit 17103C | 95511-17103C | \$ 1,832.00 | 6% | \$1,735.00 |
| PW NBD ONSITE 17103T | 95511-17103T | \$ 2,415.00 | 6% | \$2,287.13 |
| PW NBD ONSITE Summit 17104 | 95511-17104 | \$ 1,888.00 | 6% | \$1,788.03 |
| PW NBD ONSITE 17104T | 95511-17104T | \$ 2,415.00 | 6% | \$2,287.13 |
| PW NBD ONSITE Summit 17121 | 95511-17121 | \$ 537.00 | 6% | \$508.57 |
| PW NBD ONSITE Summit 17122 | 95511-17122 | \$ 335.00 | 6% | \$317.26 |
| PW NBD ONSITE -17200 | 95511-17200 | \$ 4,260.00 | 6% | \$4,034.43 |
| PW NBD ONSITE 17200T | 95511-17200T | \$ 4,867.00 | 6% | \$4,609.29 |
| PW NBD ONSITE Summit 17201 | 95511-17201 | \$ 4,260.00 | 6% | \$4,034.43 |
| PW NBD ONSITE 17201T | 95511-17201T | \$ 4,867.00 | 6% | \$4,609.29 |
| PW NBD ONSITE Summit 17202 | 95511-17202 | \$ 4,260.00 | 6% | \$4,034.43 |
| PW NBD ONSITE 17202T | 95511-17202T | \$ 4,867.00 | 6% | \$4,609.29 |
| PW NBD ONSITE Summit 17203 | 95511-17203 | \$ 4,329.00 | 6% | \$4,099.78 |
| PW NBD ONSITE 17203T | 95511-17203T | \$ 4,946.00 | 6% | \$4,684.11 |
| PW NBD ONSITE Summit 17204 | 95511-17204 | \$ 4,329.00 | 6% | \$4,099.78 |
| PW NBD ONSITE 17204T | 95511-17204T | \$ 4,946.00 | 6% | \$4,684.11 |
| PW NBD ONSITE Summit 17205 | 95511-17205 | \$ 4,292.00 | 6% | \$4,064.74 |
| PW NBD ONSITE 17205T | 95511-17205T | \$ 4,912.00 | 6% | \$4,651.91 |
| PW NBD ONSITE Summit 17206 | 95511-17206 | \$ 4,292.00 | 6% | \$4,064.74 |
| PW NBD ONSITE 17206T | 95511-17206T | \$ 4,912.00 | 6% | \$4,651.91 |
| PW NBD ONSITE 17300 | 95511-17300 | \$ 2,815.00 | 6% | \$2,665.95 |
| PW NBD ONSITE 17310 | 95511-17310 | \$ 2,550.00 | 6% | \$2,414.98 |
| PW NBD ONSITE -17310T | 95511-17310T | \$ 3,078.00 | 6% | \$2,915.02 |
| PW NBD ONSITE 17350 | 95511-17350 | \$ 2,573.00 | 6% | \$2,436.76 |

| | | | | |
|-------------------------|-----------------|-------------|----|------------|
| PW NBD ONSITE 17360 | 95511-17360 | \$ 3,172.00 | 6% | \$3,004.04 |
| PW NBD ONSITE 17401 | 95511-17401 | \$ 401.00 | 6% | \$379.77 |
| PW NBD ONSITE 17401G | 95511-17401G | \$ 463.00 | 6% | \$438.48 |
| PW NBD ONSITE 17401T | 95511-17401T | \$ 444.00 | 6% | \$420.49 |
| PW NBD ONSITE 17402 | 95511-17402 | \$ 569.00 | 6% | \$538.87 |
| PW NBD ONSITE 17402G | 95511-17402G | \$ 627.00 | 6% | \$593.80 |
| PW NBD ONSITE 17402T | 95511-17402T | \$ 597.00 | 6% | \$565.39 |
| PW NBD ONSITE 17403 | 95511-17403 | \$ 606.00 | 6% | \$573.91 |
| PW NBD ONSITE 17404 | 95511-17404 | \$ 291.00 | 6% | \$275.59 |
| PW NBD ONSITE 17405 | 95511-17405 | \$ 373.00 | 6% | \$353.25 |
| PW NBD ONSITE 17700 | 95511-17700 | \$ 4,994.00 | 6% | \$4,729.57 |
| PW NBD ONSITE 17701 | 95511-17701 | \$ 4,374.00 | 6% | \$4,142.40 |
| PW NBD ONSITE 17702 | 95511-17702 | \$ 4,374.00 | 6% | \$4,142.40 |
| PW NBD ONSITE 17703 | 95511-17703 | \$ 4,793.00 | 6% | \$4,539.21 |
| PW NBD ONSITE 17704 | 95511-17704 | \$ 4,793.00 | 6% | \$4,539.21 |
| PW NBD ONSITE 17705 | 95511-17705 | \$ 4,410.00 | 6% | \$4,176.49 |
| PW NBD ONSITE 17706 | 95511-17706 | \$ 4,410.00 | 6% | \$4,176.49 |
| PW NBD ONSITE 17800 | 95511-17800 | \$ 5,001.00 | 6% | \$4,736.20 |
| PW NBD ONSITE 17810 | 95511-17810 | \$ 4,002.00 | 6% | \$3,790.09 |
| PW NBD ONSITE 18101 | 95511-18101 | \$ 251.00 | 6% | \$237.71 |
| PW NBD ONSITE 18102 | 95511-18102 | \$ 325.00 | 6% | \$307.79 |
| PW NBD ONSITE 18103 | 95511-18103 | \$ 358.00 | 6% | \$339.04 |
| PW NBD ONSITE 18104 | 95511-18104 | \$ 510.00 | 6% | \$483.00 |
| PW NBD ONSITE 18104-6PK | 95511-18104-6PK | \$ 2,964.00 | 6% | \$2,807.06 |
| PW NBD ONSITE 18202 | 95511-18202 | \$ 190.00 | 6% | \$179.94 |
| PW NBD ONSITE 30135 | 95511-30135 | \$ 683.00 | 6% | \$646.84 |
| PW NBD ONSITE 30136 | 95511-30136 | \$ 5,135.00 | 6% | \$4,863.10 |
| PW NBD ONSITE 30137 | 95511-30137 | \$ 981.00 | 6% | \$929.06 |
| PW NBD ONSITE 30138 | 95511-30138 | \$ 4,529.00 | 6% | \$4,289.19 |
| PW NBD ONSITE 30139 | 95511-30139 | \$ 8,281.00 | 6% | \$7,842.52 |
| PW NBD ONSITE 30912 | 95511-30912 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE 30913 | 95511-30913 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE 31012 | 95511-31012 | \$ 107.00 | 6% | \$101.33 |
| PW NBD ONSITE 31013 | 95511-31013 | \$ 107.00 | 6% | \$101.33 |
| PW NBD ONSITE 31014 | 95511-31014 | \$ 107.00 | 6% | \$101.33 |
| PW NBD ONSITE 31015 | 95511-31015 | \$ 107.00 | 6% | \$101.33 |
| PW NBD ONSITE 31016 | 95511-31016 | \$ 285.00 | 6% | \$269.91 |
| PW NBD ONSITE 31017 | 95511-31017 | \$ 285.00 | 6% | \$269.91 |
| PW NBD ONSITE 31018 | 95511-31018 | \$ 322.00 | 6% | \$304.95 |
| PW NBD ONSITE 31019 | 95511-31019 | \$ 322.00 | 6% | \$304.95 |
| PW NBD ONSITE 31025 | 95511-31025 | \$ 51.00 | 6% | \$48.30 |

| | | | | |
|----------------------------|--------------------|-----------|----|-----------------|
| PW NBD ONSITE 31026 | 95511-31026 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PW NBD ONSITE 31028 | 95511-31028 | \$ 59.00 | 6% | <i>\$55.88</i> |
| PW NBD ONSITE 31029 | 95511-31029 | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE 31031 | 95511-31031 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE 31032 | 95511-31032 | \$ 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE 31034 | 95511-31034 | \$ 103.00 | 6% | <i>\$97.55</i> |
| PW NBD ONSITE 31035 | 95511-31035 | \$ 103.00 | 6% | <i>\$97.55</i> |
| PW NBD ONSITE 31050 | 95511-31050 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW NBD ONSITE 31051 | 95511-31051 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW NBD ONSITE 31055 | 95511-31055 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW NBD ONSITE 31056 | 95511-31056 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW NBD ONSITE 37101 | 95511-37101 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PW NBD ONSITE 37102 | 95511-37102 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PW NBD ONSITE 37103 | 95511-37103 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PW NBD ONSITE 37111 | 95511-37111 | \$ 60.00 | 6% | <i>\$56.82</i> |
| PW NBD ONSITE 37112 | 95511-37112 | \$ 60.00 | 6% | <i>\$56.82</i> |
| PW NBD ONSITE 37113 | 95511-37113 | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD ONSITE 37114 | 95511-37114 | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD ONSITE 37115 | 95511-37115 | \$ 60.00 | 6% | <i>\$56.82</i> |
| PW NBD ONSITE 37116 | 95511-37116 | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD ONSITE 37117 | 95511-37117 | \$ 60.00 | 6% | <i>\$56.82</i> |
| PW NBD ONSITE 37121 | 95511-37121 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 37122 | 95511-37122 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 37123 | 95511-37123 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 37124 | 95511-37124 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 37125 | 95511-37125 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 37126 | 95511-37126 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 37129 | 95511-37129 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 37130 | 95511-37130 | \$ 120.00 | 6% | <i>\$113.65</i> |
| PW NBD ONSITE 39031 | 95511-39031 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD ONSITE 39032 | 95511-39032 | \$ 175.00 | 6% | <i>\$165.73</i> |
| PW NBD ONSITE 39033 | 95511-39033 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD ONSITE 39034 | 95511-39034 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD ONSITE 39035 | 95511-39035 | \$ 773.00 | 6% | <i>\$732.07</i> |
| PW NBD ONSITE 39036 | 95511-39036 | \$ 106.00 | 6% | <i>\$100.39</i> |
| PW NBD ONSITE 39037 | 95511-39037 | \$ 106.00 | 6% | <i>\$100.39</i> |
| PW NBD ONSITE 39038 | 95511-39038 | \$ 197.00 | 6% | <i>\$186.57</i> |
| PW NBD ONSITE 39039 | 95511-39039 | \$ 197.00 | 6% | <i>\$186.57</i> |
| PW NBD ONSITE 39505 | 95511-39505 | \$ 54.00 | 6% | <i>\$51.14</i> |
| PW NBD ONSITE 4120-24MW-4Y | 95511-4120-24MW-4Y | \$ 666.00 | 6% | <i>\$630.74</i> |

| | | | | |
|-------------------------------|-----------------------|--------------|----|--------------------|
| PW NBD ONSITE 4120-48MW-4Y | 95511-4120-48MW-4Y | \$ 888.00 | 6% | <i>\$840.98</i> |
| PW NBD ONSITE 4120C | 95511-4120C | \$ 5,565.00 | 6% | <i>\$5,270.33</i> |
| PW NBD ONSITE 4120C-1 | 95511-4120C-1 | \$ 6,282.00 | 6% | <i>\$5,949.37</i> |
| PW NBD ONSITE 41216 | 95511-41216 | \$ 1,711.00 | 6% | <i>\$1,620.40</i> |
| PW NBD ONSITE 4220-12P-4X | 95511-4220-12P-4X | \$ 202.00 | 6% | <i>\$191.30</i> |
| PW NBD ONSITE 4220-12T-4X | 95511-4220-12T-4X | \$ 148.00 | 6% | <i>\$140.16</i> |
| PW NBD ONSITE 4220-24P-4X | 95511-4220-24P-4X | \$ 270.00 | 6% | <i>\$255.70</i> |
| PW NBD ONSITE 4220-24T-4X | 95511-4220-24T-4X | \$ 209.00 | 6% | <i>\$197.93</i> |
| PW NBD ONSITE 4220-48P-4X | 95511-4220-48P-4X | \$ 405.00 | 6% | <i>\$383.56</i> |
| PW NBD ONSITE 4220-48T-4X | 95511-4220-48T-4X | \$ 303.00 | 6% | <i>\$286.96</i> |
| PW NBD ONSITE 4220-4MW-20P-4X | 95511-4220-4MW-20P-4X | \$ 371.00 | 6% | <i>\$351.36</i> |
| PW NBD ONSITE 4220-4MW-8P-4X | 95511-4220-4MW-8P-4X | \$ 263.00 | 6% | <i>\$249.07</i> |
| PW NBD ONSITE 4220-8MW-40P-4X | 95511-4220-8MW-40P-4X | \$ 540.00 | 6% | <i>\$511.41</i> |
| PW NBD ONSITE 4220-8X | 95511-4220-8X | \$ 283.00 | 6% | <i>\$268.02</i> |
| PW NBD ONSITE BD X 48001 | 95511-48001 | \$ 7,126.00 | 6% | <i>\$6,748.68</i> |
| PW NBD ONSITE 48038 | 95511-48038 | \$ 2,852.00 | 6% | <i>\$2,700.99</i> |
| PW NBD ONSITE 48039 | 95511-48039 | \$ 2,852.00 | 6% | <i>\$2,700.99</i> |
| PW NBD On-site-48040 | 95511-48040 | \$ 2,756.00 | 6% | <i>\$2,610.07</i> |
| PW NBD ONSITE BD X 48041 | 95511-48041 | \$ 2,852.00 | 6% | <i>\$2,700.99</i> |
| PW NBD ONSITE BD X 48046 | 95511-48046 | \$ 3,746.00 | 6% | <i>\$3,547.65</i> |
| PW NBD ONSITE 48047 | 95511-48047 | \$ 9,983.00 | 6% | <i>\$9,454.40</i> |
| PW NBD ONSITE BD X 48051 | 95511-48051 | \$ 6,865.00 | 6% | <i>\$6,501.50</i> |
| PW NBD ONSITE 48061 | 95511-48061 | \$ 8,025.00 | 6% | <i>\$7,600.08</i> |
| PW NBD ONSITE 48062 | 95511-48062 | \$ 12,835.00 | 6% | <i>\$12,155.39</i> |
| PW NBD ONSITE 5320-16P-4XE | 95511-5320-16P-4XE | \$ 288.00 | 6% | <i>\$272.75</i> |
| PW NBD ONSITE 5320-16P-4XE-DC | 95511-5320-16P-4XE-DC | \$ 346.00 | 6% | <i>\$327.68</i> |
| PW NBD ONSITE 5320-24P-8XE | 95511-5320-24P-8XE | \$ 317.00 | 6% | <i>\$300.21</i> |

| | | | | |
|-----------------------------------|---------------------------|-----------|----|-----------------|
| PW NBD ONSITE 5320-24T-24S-4XE-XT | 95511-5320-24T-24S-4XE-XT | \$ 438.00 | 6% | <i>\$414.81</i> |
| PW NBD ONSITE 5320-24T-4X-XT | 95511-5320-24T-4X-XT | \$ 236.00 | 6% | <i>\$223.50</i> |
| PW NBD ONSITE 5320-24T-8XE | 95511-5320-24T-8XE | \$ 225.00 | 6% | <i>\$213.09</i> |
| PW NBD ONSITE 5320-48P-8XE | 95511-5320-48P-8XE | \$ 531.00 | 6% | <i>\$502.88</i> |
| PW NBD ONSITE 5320-48T-8XE | 95511-5320-48T-8XE | \$ 360.00 | 6% | <i>\$340.94</i> |
| PW NBD ONSITE 5420F-16MW-32P-4XE | 95511-5420F-16MW-32P-4XE | \$ 921.00 | 6% | <i>\$872.23</i> |
| PW NBD ONSITE 5420F-16W-32P-4XE | 95511-5420F-16W-32P-4XE | \$ 832.00 | 6% | <i>\$787.95</i> |
| PW NBD ONSITE 5420F-24P-4XE | 95511-5420F-24P-4XE | \$ 381.00 | 6% | <i>\$360.83</i> |
| PW NBD ONSITE 5420F-24S-4XE | 95511-5420F-24S-4XE | \$ 439.00 | 6% | <i>\$415.75</i> |
| PW NBD ONSITE 5420F-24T-4XE | 95511-5420F-24T-4XE | \$ 314.00 | 6% | <i>\$297.37</i> |
| PW NBD ONSITE 5420F-48P-4XE | 95511-5420F-48P-4XE | \$ 592.00 | 6% | <i>\$560.65</i> |
| PW NBD ONSITE 5420F-48P-4XL | 95511-5420F-48P-4XL | \$ 706.00 | 6% | <i>\$668.62</i> |
| PW NBD ONSITE 5420F-48T-4XE | 95511-5420F-48T-4XE | \$ 424.00 | 6% | <i>\$401.55</i> |
| PW NBD ONSITE 5420F-8W-16P-4XE | 95511-5420F-8W-16P-4XE | \$ 458.00 | 6% | <i>\$433.75</i> |
| PW NBD ONSITE 5420M-16MW-32P-4YE | 95511-5420M-16MW-32P-4YE | \$ 965.00 | 6% | <i>\$913.90</i> |
| PW NBD ONSITE 5420M-24T-4YE | 95511-5420M-24T-4YE | \$ 459.00 | 6% | <i>\$434.70</i> |
| PW NBD ONSITE 5420M-24W-4YE | 95511-5420M-24W-4YE | \$ 429.00 | 6% | <i>\$406.28</i> |
| PW NBD ONSITE 5420M-48T-4YE | 95511-5420M-48T-4YE | \$ 627.00 | 6% | <i>\$593.80</i> |
| PW NBD ONSITE 5420M-48W-4YE | 95511-5420M-48W-4YE | \$ 744.00 | 6% | <i>\$704.61</i> |

| | | | | |
|-----------------------------------|---------------------------|-------------|----|-------------------|
| PW NBD ONSITE 5520-12MW-36W | 95511-5520-12MW-36W | \$ 1,018.00 | 6% | <i>\$964.10</i> |
| PW NBD ONSITE 5520-24T | 95511-5520-24T | \$ 399.00 | 6% | <i>\$377.87</i> |
| PW NBD ONSITE 5520-24T-ACDC-BASE | 95511-5520-24T-ACDC-BASE | \$ 399.00 | 6% | <i>\$377.87</i> |
| PW NBD ONSITE 5520-24T-BASE | 95511-5520-24T-BASE | \$ 399.00 | 6% | <i>\$377.87</i> |
| PW NBD ONSITE 5520-24W | 95511-5520-24W | \$ 606.00 | 6% | <i>\$573.91</i> |
| PW NBD ONSITE 5520-24X | 95511-5520-24X | \$ 1,145.00 | 6% | <i>\$1,084.37</i> |
| PW NBD ONSITE 5520-24X-ACDC-BASE | 95511-5520-24X-ACDC-BASE | \$ 1,145.00 | 6% | <i>\$1,084.37</i> |
| PW NBD ONSITE 5520-24X-BASE | 95511-5520-24X-BASE | \$ 1,145.00 | 6% | <i>\$1,084.37</i> |
| PW NBD ONSITE 5520-48SE | 95511-5520-48SE | \$ 1,180.00 | 6% | <i>\$1,117.52</i> |
| PW NBD ONSITE 5520-48SE-ACDC-BASE | 95511-5520-48SE-ACDC-BASE | \$ 1,180.00 | 6% | <i>\$1,117.52</i> |
| PW NBD ONSITE 5520-48SE-BASE | 95511-5520-48SE-BASE | \$ 1,180.00 | 6% | <i>\$1,117.52</i> |
| PW NBD ONSITE 5520-48T | 95511-5520-48T | \$ 682.00 | 6% | <i>\$645.89</i> |
| PW NBD ONSITE 5520-48T-ACDC-BASE | 95511-5520-48T-ACDC-BASE | \$ 682.00 | 6% | <i>\$645.89</i> |
| PW NBD ONSITE 5520-48T-BASE | 95511-5520-48T-BASE | \$ 682.00 | 6% | <i>\$645.89</i> |
| PW NBD ONSITE 5520-48W | 95511-5520-48W | \$ 832.00 | 6% | <i>\$787.95</i> |
| PW NBD ONSITE 5720-24MW | 95511-5720-24MW | \$ 1,275.00 | 6% | <i>\$1,207.49</i> |
| PW NBD ONSITE 5720-24MXW | 95511-5720-24MXW | \$ 1,725.00 | 6% | <i>\$1,633.66</i> |
| PW NBD ONSITE 5720-48MW | 95511-5720-48MW | \$ 1,500.00 | 6% | <i>\$1,420.58</i> |
| PW NBD ONSITE 5720-48MXW | 95511-5720-48MXW | \$ 2,175.00 | 6% | <i>\$2,059.83</i> |

| | | | | |
|----------------------------------|--------------------------|-------------|----|------------|
| PW NBD ONSITE 7520-48XT-6C | 95511-7520-48XT-6C | \$ 2,383.00 | 6% | \$2,256.82 |
| PW NBD ONSITE 7520-48XT-6C-AC-F | 95511-7520-48XT-6C-AC-F | \$ 2,383.00 | 6% | \$2,256.82 |
| PW NBD ONSITE 7520-48XT-6C-AC-R | 95511-7520-48XT-6C-AC-R | \$ 2,383.00 | 6% | \$2,256.82 |
| PW NBD ONSITE 7520-48Y-8C | 95511-7520-48Y-8C | \$ 2,218.00 | 6% | \$2,100.56 |
| PW NBD ONSITE 7520-48Y-8C-AC-F | 95511-7520-48Y-8C-AC-F | \$ 2,218.00 | 6% | \$2,100.56 |
| PW NBD ONSITE 7520-48Y-8C-AC-R | 95511-7520-48Y-8C-AC-R | \$ 2,218.00 | 6% | \$2,100.56 |
| PW NBD ONSITE 7520-48YE-8CE | 95511-7520-48YE-8CE | \$ 2,583.00 | 6% | \$2,446.23 |
| PW NBD ONSITE 7520-48YE-8CE-AC-F | 95511-7520-48YE-8CE-AC-F | \$ 2,583.00 | 6% | \$2,446.23 |
| PW NBD ONSITE 7520-48YE-8CE-AC-R | 95511-7520-48YE-8CE-AC-R | \$ 2,583.00 | 6% | \$2,446.23 |
| PW NBD ONSITE 7720-32C | 95511-7720-32C | \$ 2,769.00 | 6% | \$2,622.38 |
| PW NBD ONSITE 7720-32C-AC-F | 95511-7720-32C-AC-F | \$ 2,769.00 | 6% | \$2,622.38 |
| PW NBD ONSITE 7720-32C-AC-R | 95511-7720-32C-AC-R | \$ 2,769.00 | 6% | \$2,622.38 |
| PW NBD ONSITE 8520-48XT-6C | 95511-8520-48XT-6C | \$ 2,554.00 | 6% | \$2,418.77 |
| PW NBD ONSITE 8520-48XT-6C-AC-F | 95511-8520-48XT-6C-AC-F | \$ 2,554.00 | 6% | \$2,418.77 |
| PW NBD ONSITE 8520-48XT-6C-AC-R | 95511-8520-48XT-6C-AC-R | \$ 2,554.00 | 6% | \$2,418.77 |
| PW NBD ONSITE 8520-48XT-6C-DC-F | 95511-8520-48XT-6C-DC-F | \$ 2,554.00 | 6% | \$2,418.77 |
| PW NBD ONSITE 8520-48XT-6C-DC-R | 95511-8520-48XT-6C-DC-R | \$ 2,554.00 | 6% | \$2,418.77 |

| | | | | |
|--------------------------------|------------------------|--------------|----|-------------|
| PW NBD ONSITE 8520-48Y-8C | 95511-8520-48Y-8C | \$ 2,594.00 | 6% | \$2,456.65 |
| PW NBD ONSITE 8520-48Y-8C-AC-F | 95511-8520-48Y-8C-AC-F | \$ 2,594.00 | 6% | \$2,456.65 |
| PW NBD ONSITE 8520-48Y-8C-AC-R | 95511-8520-48Y-8C-AC-R | \$ 2,594.00 | 6% | \$2,456.65 |
| PW NBD ONSITE 8520-48Y-8C-DC-F | 95511-8520-48Y-8C-DC-F | \$ 2,594.00 | 6% | \$2,456.65 |
| PW NBD ONSITE 8520-48Y-8C-DC-R | 95511-8520-48Y-8C-DC-R | \$ 2,594.00 | 6% | \$2,456.65 |
| PW NBD ONSITE 86100 | 95511-86100 | \$ 5,201.00 | 6% | \$4,925.61 |
| PW NBD ONSITE 86101 | 95511-86101 | \$ 7,144.00 | 6% | \$6,765.73 |
| PW NBD ONSITE 87100 | 95511-87100 | \$ 3,225.00 | 6% | \$3,054.24 |
| PW NBD ONSITE 87101 | 95511-87101 | \$ 4,961.00 | 6% | \$4,698.32 |
| PW NBD ONSITE 8720-32C | 95511-8720-32C | \$ 2,981.00 | 6% | \$2,823.16 |
| PW NBD ONSITE 8720-32C-AC-F | 95511-8720-32C-AC-F | \$ 2,981.00 | 6% | \$2,823.16 |
| PW NBD ONSITE 8720-32C-AC-R | 95511-8720-32C-AC-R | \$ 2,981.00 | 6% | \$2,823.16 |
| PW NBD ONSITE 8720-32C-DC-F | 95511-8720-32C-DC-F | \$ 2,981.00 | 6% | \$2,823.16 |
| PW NBD ONSITE 8720-32C-DC-R | 95511-8720-32C-DC-R | \$ 2,981.00 | 6% | \$2,823.16 |
| PW NBD Onsite 8806 | 95511-8806 | \$ 1,786.00 | 6% | \$1,691.43 |
| PW NBD Onsite ASPEN | 95511-8810 | \$ 4,727.00 | 6% | \$4,476.71 |
| PW NBD ONSITE 88100 | 95511-88100 | \$ 5,863.00 | 6% | \$5,552.55 |
| PW NBD ONSITE 8820-40C | 95511-8820-40C | \$ 11,306.00 | 6% | \$10,707.35 |
| PW NBD ONSITE 8820-40C-AC-F | 95511-8820-40C-AC-F | \$ 11,306.00 | 6% | \$10,707.35 |
| PW NBD ONSITE 8820-40C-AC-R | 95511-8820-40C-AC-R | \$ 11,306.00 | 6% | \$10,707.35 |
| PW NBD ONSITE 8820-40C-DC-F | 95511-8820-40C-DC-F | \$ 11,306.00 | 6% | \$10,707.35 |
| PW NBD ONSITE 8820-40C-DC-R | 95511-8820-40C-DC-R | \$ 11,306.00 | 6% | \$10,707.35 |
| PW NBD ONSITE 8820-80C | 95511-8820-80C | \$ 20,515.00 | 6% | \$19,428.73 |
| PW NBD ONSITE 8820-80C-AC-F | 95511-8820-80C-AC-F | \$ 20,515.00 | 6% | \$19,428.73 |

| | | | | |
|---------------------------------|-------------------------|--------------|----|--------------------|
| PW NBD ONSITE 8820-80C-AC-R | 95511-8820-80C-AC-R | \$ 20,515.00 | 6% | <i>\$19,428.73</i> |
| PW NBD ONSITE 8820-80C-DC-F | 95511-8820-80C-DC-F | \$ 20,515.00 | 6% | <i>\$19,428.73</i> |
| PW NBD ONSITE 8820-80C-DC-R | 95511-8820-80C-DC-R | \$ 20,515.00 | 6% | <i>\$19,428.73</i> |
| PW NBD ONSITE 9920-16C | 95511-9920-16C | \$ 9,217.00 | 6% | <i>\$8,728.96</i> |
| PW NBD ONSITE 9920-4D | 95511-9920-4D | \$ 9,217.00 | 6% | <i>\$8,728.96</i> |
| PW NBD ONSITE 9920-NPB-8 | 95511-9920-NPB-8 | \$ 15,349.00 | 6% | <i>\$14,536.27</i> |
| PW NBD ONSITE | 95511-A10148 | \$ 2,919.00 | 6% | <i>\$2,764.44</i> |
| PW NBD ONSITE | 95511-A10149 | \$ 5,566.00 | 6% | <i>\$5,271.28</i> |
| PW NBD ONSITE | 95511-A10152 | \$ 5,566.00 | 6% | <i>\$5,271.28</i> |
| PW NBD ONSITE | 95511-A10154 | \$ 16,973.00 | 6% | <i>\$16,074.28</i> |
| PW NBD ONSITE | 95511-A10155 | \$ 6,006.00 | 6% | <i>\$5,687.98</i> |
| PW NBD ONSITE | 95511-A10157 | \$ 10,599.00 | 6% | <i>\$10,037.78</i> |
| PW NBD ONSITE 10175 | 95511-A10175 | \$ 6,552.00 | 6% | <i>\$6,205.07</i> |
| PW NBD ONSITE A10176 | 95511-A10176 | \$ 9,827.00 | 6% | <i>\$9,306.66</i> |
| PW NBD ONSITE AH-AP-1130-AC-CE | 95511-AH-AP-1130-AC-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AH-AP-1130-AC-FCC | 95511-AH-AP-1130-AC-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AH-AP-1130-AC-W | 95511-AH-AP-1130-AC-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AH-AP-122-AC-CAN | 95511-AH-AP-122-AC-CAN | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-122-AC-CE | 95511-AH-AP-122-AC-CE | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-122-AC-FCC | 95511-AH-AP-122-AC-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-122-AC-W | 95511-AH-AP-122-AC-W | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-130-AC-CE | 95511-AH-AP-130-AC-CE | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-130-AC-FCC | 95511-AH-AP-130-AC-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-130-AC-W | 95511-AH-AP-130-AC-W | \$ 71.00 | 6% | <i>\$67.24</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|----|-----------------|
| PW NBD ONSITE AH-AP-150W-AC-CAN | 95511-AH-AP-150W-AC-CAN | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-150W-AC-CE | 95511-AH-AP-150W-AC-CE | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-150W-AC-FCC | 95511-AH-AP-150W-AC-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-150W-AC-W | 95511-AH-AP-150W-AC-W | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-230-AC-CE | 95511-AH-AP-230-AC-CE | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-230-AC-FCC | 95511-AH-AP-230-AC-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-230-AC-W | 95511-AH-AP-230-AC-W | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-250-AC-CAN | 95511-AH-AP-250-AC-CAN | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-250-AC-CE | 95511-AH-AP-250-AC-CE | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-250-AC-FCC | 95511-AH-AP-250-AC-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-250-AC-W | 95511-AH-AP-250-AC-W | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-AP-630-AX-CAN | 95511-AH-AP-630-AX-CAN | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW NBD ONSITE AH-AP-630-AX-CE | 95511-AH-AP-630-AX-CE | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW NBD ONSITE AH-AP-630-AX-FCC | 95511-AH-AP-630-AX-FCC | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW NBD ONSITE AH-AP-630-AX-W | 95511-AH-AP-630-AX-W | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW NBD ONSITE AH-AP-650-AX-CAN | 95511-AH-AP-650-AX-CAN | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE AH-AP-650-AX-CE | 95511-AH-AP-650-AX-CE | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE AH-AP-650-AX-FCC | 95511-AH-AP-650-AX-FCC | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE AH-AP-650-AX-W | 95511-AH-AP-650-AX-W | \$ 108.00 | 6% | <i>\$102.28</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|----|-----------------|
| PW NBD ONSITE AH-AP-650X-AX-CAN | 95511-AH-AP-650X-AX-CAN | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE AH-AP-650X-AX-CE | 95511-AH-AP-650X-AX-CE | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE AH-AP-650X-AX-FCC | 95511-AH-AP-650X-AX-FCC | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE AH-AP-650X-AX-W | 95511-AH-AP-650X-AX-W | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE AH-ATOM-CAN | 95511-AH-ATOM-CAN | \$ 72.00 | 6% | <i>\$68.19</i> |
| PW NBD ONSITE AH-ATOM-CE-EU | 95511-AH-ATOM-CE-EU | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AH-ATOM-CE-UK | 95511-AH-ATOM-CE-UK | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AH-ATOM-FCC | 95511-AH-ATOM-FCC | \$ 72.00 | 6% | <i>\$68.19</i> |
| PW NBD ONSITE AH-ATOM-W | 95511-AH-ATOM-W | \$ 72.00 | 6% | <i>\$68.19</i> |
| PW NBD ONSITE AH-ATOM-W-EU | 95511-AH-ATOM-W-EU | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AH-ATOM-W-UK | 95511-AH-ATOM-W-UK | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AH-SR-2208P-AU | 95511-AH-SR-2208P-AU | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-SR-2208P-EU | 95511-AH-SR-2208P-EU | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-SR-2208P-NA | 95511-AH-SR-2208P-NA | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-SR-2208P-UK | 95511-AH-SR-2208P-UK | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-SR-2224P-AU | 95511-AH-SR-2224P-AU | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AH-SR-2224P-EU | 95511-AH-SR-2224P-EU | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AH-SR-2224P-NA | 95511-AH-SR-2224P-NA | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AH-SR-2224P-UK | 95511-AH-SR-2224P-UK | \$ 107.00 | 6% | <i>\$101.33</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|----|-----------------|
| PW NBD ONSITE AH-SR-2324P-AU | 95511-AH-SR-2324P-AU | \$ 147.00 | 6% | <i>\$139.22</i> |
| PW NBD ONSITE AH-SR-2324P-EU | 95511-AH-SR-2324P-EU | \$ 147.00 | 6% | <i>\$139.22</i> |
| PW NBD ONSITE AH-SR-2324P-NA | 95511-AH-SR-2324P-NA | \$ 147.00 | 6% | <i>\$139.22</i> |
| PW NBD ONSITE AH-SR-2324P-UK | 95511-AH-SR-2324P-UK | \$ 147.00 | 6% | <i>\$139.22</i> |
| PW NBD ONSITE AH-SR-2348P-AU | 95511-AH-SR-2348P-AU | \$ 258.00 | 6% | <i>\$244.34</i> |
| PW NBD ONSITE AH-SR-2348P-EU | 95511-AH-SR-2348P-EU | \$ 258.00 | 6% | <i>\$244.34</i> |
| PW NBD ONSITE AH-SR-2348P-NA | 95511-AH-SR-2348P-NA | \$ 258.00 | 6% | <i>\$244.34</i> |
| PW NBD ONSITE AH-SR-2348P-UK | 95511-AH-SR-2348P-UK | \$ 258.00 | 6% | <i>\$244.34</i> |
| PW NBD ONSITE AH-XR200P-AU | 95511-AH-XR200P-AU | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-XR200P-EU | 95511-AH-XR200P-EU | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-XR200P-UK | 95511-AH-XR200P-UK | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-XR200P-US | 95511-AH-XR200P-US | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AH-XR600P | 95511-AH-XR600P | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD ONSITE AH-XR600P-AU | 95511-AH-XR600P-AU | \$ 82.00 | 6% | <i>\$77.66</i> |
| PW NBD ONSITE AH-XR600P-EU | 95511-AH-XR600P-EU | \$ 82.00 | 6% | <i>\$77.66</i> |
| PW NBD ONSITE AH-XR600P-KR | 95511-AH-XR600P-KR | \$ 82.00 | 6% | <i>\$77.66</i> |
| PW NBD ONSITE AH-XR600P-UK | 95511-AH-XR600P-UK | \$ 82.00 | 6% | <i>\$77.66</i> |
| PW NBD ONSITE AH-XR600P-US | 95511-AH-XR600P-US | \$ 82.00 | 6% | <i>\$77.66</i> |
| PW NBD ONSITE AP-8533-68SB30-IL | 95511-AP-8533-68SB30-IL | \$ 135.00 | 6% | <i>\$127.85</i> |
| PW NBD ONSITE AP3000-IL | 95511-AP3000-IL | \$ 58.50 | 6% | <i>\$55.40</i> |

| | | | | |
|----------------------------|--------------------|----------|----|----------------|
| PW NBD ONSITE AP3000-TN | 95511-AP3000-TN | \$ 58.50 | 6% | <i>\$55.40</i> |
| PW NBD ONSITE AP3000-WW | 95511-AP3000-WW | \$ 58.50 | 6% | <i>\$55.40</i> |
| PW NBD ONSITE AP3000X-WW | 95511-AP3000X-WW | \$ 74.75 | 6% | <i>\$70.79</i> |
| PW NBD ONSITE AP302W-CAN | 95511-AP302W-CAN | \$ 54.00 | 6% | <i>\$51.14</i> |
| PW NBD ONSITE AP302W-EG | 95511-AP302W-EG | \$ 59.00 | 6% | <i>\$55.88</i> |
| PW NBD ONSITE AP302W-FCC | 95511-AP302W-FCC | \$ 54.00 | 6% | <i>\$51.14</i> |
| PW NBD ONSITE AP302W-WR | 95511-AP302W-WR | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD ONSITE AP305C-1-CAN | 95511-AP305C-1-CAN | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AP305C-1-EG | 95511-AP305C-1-EG | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AP305C-1-FCC | 95511-AP305C-1-FCC | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AP305C-1-IL | 95511-AP305C-1-IL | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AP305C-1-WR | 95511-AP305C-1-WR | \$ 71.00 | 6% | <i>\$67.24</i> |
| PW NBD ONSITE AP305C-CAN | 95511-AP305C-CAN | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP305C-EG | 95511-AP305C-EG | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP305C-FCC | 95511-AP305C-FCC | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP305C-IL | 95511-AP305C-IL | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP305C-WR | 95511-AP305C-WR | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP305CX-CAN | 95511-AP305CX-CAN | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP305CX-FCC | 95511-AP305CX-FCC | \$ 76.00 | 6% | <i>\$71.98</i> |

| | | | | |
|---------------------------|-------------------|----------|----|----------------|
| PW NBD ONSITE AP305CX-IL | 95511-AP305CX-IL | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP305CX-WR | 95511-AP305CX-WR | \$ 76.00 | 6% | <i>\$71.98</i> |
| PW NBD ONSITE AP310e-1-WR | 95511-AP310e-1-WR | \$ 45.00 | 6% | <i>\$42.62</i> |
| PW NBD ONSITE AP310e-CAN | 95511-AP310e-CAN | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP310e-FCC | 95511-AP310e-FCC | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP310e-IL | 95511-AP310e-IL | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP310e-WR | 95511-AP310e-WR | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP310i-1-WR | 95511-AP310i-1-WR | \$ 45.00 | 6% | <i>\$42.62</i> |
| PW NBD ONSITE AP310i-CAN | 95511-AP310i-CAN | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP310i-FCC | 95511-AP310i-FCC | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP310i-IL | 95511-AP310i-IL | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP310i-WR | 95511-AP310i-WR | \$ 47.00 | 6% | <i>\$44.51</i> |
| PW NBD ONSITE AP360e-CAN | 95511-AP360e-CAN | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE AP360e-FCC | 95511-AP360e-FCC | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE AP360e-IL | 95511-AP360e-IL | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE AP360e-WR | 95511-AP360e-WR | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE AP360i-CAN | 95511-AP360i-CAN | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE AP360i-FCC | 95511-AP360i-FCC | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE AP360i-WR | 95511-AP360i-WR | \$ 68.00 | 6% | <i>\$64.40</i> |
| PW NBD ONSITE AP4000-WW | 95511-AP4000-1-WW | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD ONSITE AP4000-IL | 95511-AP4000-IL | \$ 81.00 | 6% | <i>\$76.71</i> |

| | | | | |
|----------------------------|--------------------|----------|----|----------------|
| PW NBD ONSITE AP4000-WW | 95511-AP4000-WW | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD ONSITE AP410C-1-CAN | 95511-AP410C-1-CAN | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD ONSITE AP410C-1-EG | 95511-AP410C-1-EG | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD ONSITE AP410C-1-FCC | 95511-AP410C-1-FCC | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD ONSITE AP410C-1-IL | 95511-AP410C-1-IL | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD ONSITE AP410C-1-WR | 95511-AP410C-1-WR | \$ 81.00 | 6% | <i>\$76.71</i> |
| PW NBD ONSITE AP410C-CAN | 95511-AP410C-CAN | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE AP410C-EG | 95511-AP410C-EG | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE AP410C-FCC | 95511-AP410C-FCC | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE AP410C-IL | 95511-AP410C-IL | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE AP410C-WR | 95511-AP410C-WR | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE AP410e-CAN | 95511-AP410e-CAN | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD ONSITE AP410e-FCC | 95511-AP410e-FCC | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD ONSITE AP410e-WR | 95511-AP410e-WR | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD ONSITE AP410i-1-FCC | 95511-AP410i-1-FCC | \$ 80.00 | 6% | <i>\$75.76</i> |
| PW NBD ONSITE AP410i-1-WR | 95511-AP410i-1-WR | \$ 80.00 | 6% | <i>\$75.76</i> |
| PW NBD ONSITE AP410i-CAN | 95511-AP410i-CAN | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD ONSITE AP410i-FCC | 95511-AP410i-FCC | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD ONSITE AP410i-IL | 95511-AP410i-IL | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD ONSITE AP410i-WR | 95511-AP410i-WR | \$ 84.00 | 6% | <i>\$79.55</i> |

| | | | | |
|-----------------------------|---------------------|-----------|----|-----------------|
| PW NBD ONSITE AP460C-CAN | 95511-AP460C-CAN | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460C-EG | 95511-AP460C-EG | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460C-FCC | 95511-AP460C-FCC | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460C-IL | 95511-AP460C-IL | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460C-WR | 95511-AP460C-WR | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460e-CAN | 95511-AP460e-CAN | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW NBD ONSITE AP460e-FCC | 95511-AP460e-FCC | \$ 97.00 | 6% | <i>\$91.86</i> |
| PW NBD ONSITE AP460e-WR | 95511-AP460e-WR | \$ 92.00 | 6% | <i>\$87.13</i> |
| PW NBD ONSITE AP460i-CAN | 95511-AP460i-CAN | \$ 92.00 | 6% | <i>\$87.13</i> |
| PW NBD ONSITE AP460i-FCC | 95511-AP460i-FCC | \$ 92.00 | 6% | <i>\$87.13</i> |
| PW NBD ONSITE AP460i-IL | 95511-AP460i-IL | \$ 92.00 | 6% | <i>\$87.13</i> |
| PW NBD ONSITE AP460i-WR | 95511-AP460i-WR | \$ 92.00 | 6% | <i>\$87.13</i> |
| PW NBD ONSITE AP460S12C-CAN | 95511-AP460S12C-CAN | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460S12C-FCC | 95511-AP460S12C-FCC | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460S12C-WR | 95511-AP460S12C-WR | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460S6C-CAN | 95511-AP460S6C-CAN | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460S6C-FCC | 95511-AP460S6C-FCC | \$ 107.00 | 6% | <i>\$101.33</i> |
| PW NBD ONSITE AP460S6C-WR | 95511-AP460S6C-WR | \$ 107.00 | 6% | <i>\$101.33</i> |

| | | | | |
|------------------------------|----------------------|-----------|----|-----------------|
| PW NBD ONSITE AP5010-IL | 95511-AP5010-IL | \$ 130.00 | 6% | <i>\$123.12</i> |
| PW NBD ONSITE AP5010-WW | 95511-AP5010-WW | \$ 130.00 | 6% | <i>\$123.12</i> |
| PW NBD ONSITE AP5020-WW | 95511-AP5020-WW | \$ 155.94 | 6% | <i>\$147.68</i> |
| PW NBD ONSITE AP5050D-WW | 95511-AP5050D-WW | \$ 310.00 | 6% | <i>\$293.59</i> |
| PW NBD ONSITE AP5050U-WW | 95511-AP5050U-WW | \$ 242.00 | 6% | <i>\$229.19</i> |
| PW NBD ONSITE AP505i-FCC | 95511-AP505i-FCC | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW NBD ONSITE AP505i-FCC-TAA | 95511-AP505i-FCC-TAA | \$ 101.00 | 6% | <i>\$95.65</i> |
| PW NBD ONSITE AP505i-WR | 95511-AP505i-WR | \$ 106.00 | 6% | <i>\$100.39</i> |
| PW NBD ONSITE AP510C-CAN | 95511-AP510C-CAN | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510C-CE | 95511-AP510C-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510C-FCC | 95511-AP510C-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510C-W | 95511-AP510C-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510C-WW | 95511-AP510C-WW | \$ 121.00 | 6% | <i>\$114.59</i> |
| PW NBD ONSITE AP510CX-CAN | 95511-AP510CX-CAN | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510CX-CE | 95511-AP510CX-CE | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510CX-FCC | 95511-AP510CX-FCC | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510CX-W | 95511-AP510CX-W | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE AP510CX-WW | 95511-AP510CX-WW | \$ 121.00 | 6% | <i>\$114.59</i> |
| PW NBD ONSITE AP510e-FCC | 95511-AP510e-FCC | \$ 138.00 | 6% | <i>\$130.69</i> |

| | | | | |
|------------------------------|----------------------|-------------|----|-------------------|
| PW NBD ONSITE AP510e-FCC-TAA | 95511-AP510e-FCC-TAA | \$ 138.00 | 6% | <i>\$130.69</i> |
| PW NBD ONSITE AP510e-WR | 95511-AP510e-WR | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE AP510i-1-FCC | 95511-AP510i-1-FCC | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW NBD ONSITE AP510i-1-WR | 95511-AP510i-1-WR | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW NBD ONSITE AP510i-FCC | 95511-AP510i-FCC | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW NBD ONSITE AP510i-FCC-TAA | 95511-AP510i-FCC-TAA | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW NBD ONSITE AP510i-WR | 95511-AP510i-WR | \$ 119.00 | 6% | <i>\$112.70</i> |
| PW NBD ONSITE AP560h-FCC | 95511-AP560h-FCC | \$ 301.00 | 6% | <i>\$285.06</i> |
| PW NBD ONSITE AP560h-WR | 95511-AP560h-WR | \$ 301.00 | 6% | <i>\$285.06</i> |
| PW NBD ONSITE AP560i-FCC | 95511-AP560i-FCC | \$ 219.00 | 6% | <i>\$207.40</i> |
| PW NBD ONSITE AP560i-WR | 95511-AP560i-WR | \$ 209.00 | 6% | <i>\$197.93</i> |
| PW NBD ONSITE AP560m-FCC | 95511-AP560m-FCC | \$ 219.00 | 6% | <i>\$207.40</i> |
| PW NBD ONSITE AP560t-FCC | 95511-AP560t-FCC | \$ 301.00 | 6% | <i>\$285.06</i> |
| PW NBD ONSITE AP560u-FCC | 95511-AP560u-FCC | \$ 204.00 | 6% | <i>\$193.20</i> |
| PW NBD ONSITE E2122 | 95511-E2122 | \$ 5,063.00 | 6% | <i>\$4,794.91</i> |
| PW NBD ONSITE E2122-1 | 95511-E2122-1 | \$ 4,799.00 | 6% | <i>\$4,544.89</i> |
| PW NBD ONSITE E3120-1 | 95511-E3120-1 | \$ 7,848.00 | 6% | <i>\$7,432.45</i> |
| PW NBD ONSITE E3125 | 95511-E3125 | \$ 8,472.00 | 6% | <i>\$8,023.41</i> |
| PW NBD ONSITE | 95511-H30078 | \$ 2,687.00 | 6% | <i>\$2,544.72</i> |
| PW NBD ONSITE | 95511-H30104 | \$ 2,485.00 | 6% | <i>\$2,353.42</i> |
| PW NBD ONSITE | 95511-H30105 | \$ 2,455.00 | 6% | <i>\$2,325.01</i> |
| PW NBD ONSITE | 95511-H30131 | \$ 1,405.00 | 6% | <i>\$1,330.61</i> |
| PW NBD ONSITE | 95511-H30132 | \$ 1,378.00 | 6% | <i>\$1,305.03</i> |
| PW NBD ONSITE | 95511-H30133 | \$ 3,620.00 | 6% | <i>\$3,428.32</i> |
| PW NBD ONSITE | 95511-H30134 | \$ 4,587.00 | 6% | <i>\$4,344.12</i> |
| PW NBD ONSITE | 95511-H30135 | \$ 3,692.00 | 6% | <i>\$3,496.51</i> |
| PW NBD ONSITE | 95511-H30136 | \$ 4,587.00 | 6% | <i>\$4,344.12</i> |
| PW NBD ONSITE | 95511-H30184 | \$ 62.00 | 6% | <i>\$58.72</i> |

| | | | | |
|---------------|--------------|-------------|----|------------|
| PW NBD ONSITE | 95511-H30185 | \$ 325.00 | 6% | \$307.79 |
| PW NBD ONSITE | 95511-H30186 | \$ 165.00 | 6% | \$156.26 |
| PW NBD ONSITE | 95511-H30187 | \$ 67.00 | 6% | \$63.45 |
| PW NBD ONSITE | 95511-H30188 | \$ 165.00 | 6% | \$156.26 |
| PW NBD ONSITE | 95511-H30189 | \$ 165.00 | 6% | \$156.26 |
| PW NBD ONSITE | 95511-H30190 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30214 | \$ 177.00 | 6% | \$167.63 |
| PW NBD ONSITE | 95511-H30215 | \$ 177.00 | 6% | \$167.63 |
| PW NBD ONSITE | 95511-H30216 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30217 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30218 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30219 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30220 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30221 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30222 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30223 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30224 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30225 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30226 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30227 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30228 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30229 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30267 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30268 | \$ 347.00 | 6% | \$328.63 |
| PW NBD ONSITE | 95511-H30269 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30270 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30271 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30272 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30273 | \$ 763.00 | 6% | \$722.60 |
| PW NBD ONSITE | 95511-H30274 | \$ 763.00 | 6% | \$722.60 |
| PW NBD ONSITE | 95511-H30275 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30276 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30277 | \$ 763.00 | 6% | \$722.60 |
| PW NBD ONSITE | 95511-H30278 | \$ 837.00 | 6% | \$792.68 |
| PW NBD ONSITE | 95511-H30279 | \$ 763.00 | 6% | \$722.60 |
| PW NBD ONSITE | 95511-H30280 | \$ 763.00 | 6% | \$722.60 |
| PW NBD ONSITE | 95511-H30281 | \$ 763.00 | 6% | \$722.60 |
| PW NBD ONSITE | 95511-H30282 | \$ 763.00 | 6% | \$722.60 |
| PW NBD ONSITE | 95511-H30283 | \$ 507.00 | 6% | \$480.15 |
| PW NBD ONSITE | 95511-H30284 | \$ 558.00 | 6% | \$528.45 |
| PW NBD ONSITE | 95511-H30293 | \$ 3,024.00 | 6% | \$2,863.88 |
| PW NBD ONSITE | 95511-H30296 | \$ 177.00 | 6% | \$167.63 |

| | | | | |
|---------------|--------------|-------------|----|------------|
| PW NBD ONSITE | 95511-H30297 | \$ 164.00 | 6% | \$155.32 |
| PW NBD ONSITE | 95511-H30298 | \$ 177.00 | 6% | \$167.63 |
| PW NBD ONSITE | 95511-H30299 | \$ 164.00 | 6% | \$155.32 |
| PW NBD ONSITE | 95511-H30381 | \$ 499.00 | 6% | \$472.58 |
| PW NBD ONSITE | 95511-H30384 | \$ 400.00 | 6% | \$378.82 |
| PW NBD ONSITE | 95511-H30391 | \$ 944.00 | 6% | \$894.02 |
| PW NBD ONSITE | 95511-H30392 | \$ 944.00 | 6% | \$894.02 |
| PW NBD ONSITE | 95511-H30393 | \$ 425.00 | 6% | \$402.50 |
| PW NBD ONSITE | 95511-H30394 | \$ 1,834.00 | 6% | \$1,736.89 |
| PW NBD ONSITE | 95511-H30395 | \$ 2,185.00 | 6% | \$2,069.30 |
| PW NBD ONSITE | 95511-H30396 | \$ 1,988.00 | 6% | \$1,882.74 |
| PW NBD ONSITE | 95511-H30397 | \$ 2,368.00 | 6% | \$2,242.61 |
| PW NBD ONSITE | 95511-H30398 | \$ 435.00 | 6% | \$411.97 |
| PW NBD ONSITE | 95511-H30400 | \$ 239.00 | 6% | \$226.34 |
| PW NBD ONSITE | 95511-H30401 | \$ 330.00 | 6% | \$312.53 |
| PW NBD ONSITE | 95511-H30402 | \$ 360.00 | 6% | \$340.94 |
| PW NBD ONSITE | 95511-H30403 | \$ 528.00 | 6% | \$500.04 |
| PW NBD ONSITE | 95511-H30434 | \$ 142.00 | 6% | \$134.48 |
| PW NBD ONSITE | 95511-H30480 | \$ 625.00 | 6% | \$591.91 |
| PW NBD ONSITE | 95511-H30495 | \$ 1,405.00 | 6% | \$1,330.61 |
| PW NBD ONSITE | 95511-H30496 | \$ 1,378.00 | 6% | \$1,305.03 |
| PW NBD ONSITE | 95511-H30497 | \$ 2,027.00 | 6% | \$1,919.67 |
| PW NBD ONSITE | 95511-H30498 | \$ 1,988.00 | 6% | \$1,882.74 |
| PW NBD ONSITE | 95511-H30499 | \$ 683.00 | 6% | \$646.84 |
| PW NBD ONSITE | 95511-H30501 | \$ 1,988.00 | 6% | \$1,882.74 |
| PW NBD ONSITE | 95511-H30502 | \$ 3,062.00 | 6% | \$2,899.87 |
| PW NBD ONSITE | 95511-H30503 | \$ 683.00 | 6% | \$646.84 |
| PW NBD ONSITE | 95511-H30505 | \$ 3,620.00 | 6% | \$3,428.32 |
| PW NBD ONSITE | 95511-H30506 | \$ 4,922.00 | 6% | \$4,661.38 |
| PW NBD ONSITE | 95511-H30509 | \$ 3,062.00 | 6% | \$2,899.87 |
| PW NBD ONSITE | 95511-H30510 | \$ 3,620.00 | 6% | \$3,428.32 |
| PW NBD ONSITE | 95511-H30511 | \$ 4,922.00 | 6% | \$4,661.38 |
| PW NBD ONSITE | 95511-H30512 | \$ 683.00 | 6% | \$646.84 |
| PW NBD ONSITE | 95511-H30513 | \$ 1,149.00 | 6% | \$1,088.16 |
| PW NBD ONSITE | 95511-H30525 | \$ 4,922.00 | 6% | \$4,661.38 |
| PW NBD ONSITE | 95511-H30526 | \$ 3,620.00 | 6% | \$3,428.32 |
| PW NBD ONSITE | 95511-H30528 | \$ 5,719.00 | 6% | \$5,416.18 |
| PW NBD ONSITE | 95511-H30531 | \$ 8,145.00 | 6% | \$7,713.72 |
| PW NBD ONSITE | 95511-H30532 | \$ 8,145.00 | 6% | \$7,713.72 |
| PW NBD ONSITE | 95511-H30534 | \$ 8,303.00 | 6% | \$7,863.36 |
| PW NBD ONSITE | 95511-H30535 | \$ 8,853.00 | 6% | \$8,384.23 |
| PW NBD ONSITE | 95511-H30536 | \$ 8,145.00 | 6% | \$7,713.72 |

| | | | | |
|-------------------------------|--------------|-------------|----|------------|
| PW NBD ONSITE | 95511-H30537 | \$ 8,853.00 | 6% | \$8,384.23 |
| PW NBD ONSITE | 95511-H30538 | \$ 4,922.00 | 6% | \$4,661.38 |
| PW NBD ONSITE | 95511-H30539 | \$ 9,274.00 | 6% | \$8,782.94 |
| PW NBD ONSITE | 95511-H30540 | \$ 9,779.00 | 6% | \$9,261.20 |
| PW NBD ONSITE | 95511-H30543 | \$ 670.00 | 6% | \$634.52 |
| PW NBD ONSITE | 95511-H30544 | \$ 1,191.00 | 6% | \$1,127.94 |
| PW NBD ONSITE | 95511-H30548 | \$ 670.00 | 6% | \$634.52 |
| PW NBD ONSITE | 95511-H30549 | \$ 1,127.00 | 6% | \$1,067.33 |
| PW NBD ONSITE | 95511-H30550 | \$ 1,127.00 | 6% | \$1,067.33 |
| PW NBD ONSITE | 95511-H30552 | \$ 670.00 | 6% | \$634.52 |
| PW NBD ONSITE | 95511-H30553 | \$ 1,062.00 | 6% | \$1,005.77 |
| PW NBD ONSITE | 95511-H30569 | \$ 3,620.00 | 6% | \$3,428.32 |
| PW NBD ONSITE | 95511-H30570 | \$ 4,342.00 | 6% | \$4,112.09 |
| PW NBD ONSITE | 95511-H30571 | \$ 4,342.00 | 6% | \$4,112.09 |
| PW NBD ONSITE | 95511-H30573 | \$ 3,620.00 | 6% | \$3,428.32 |
| PW NBD ONSITE | 95511-H30574 | \$ 4,008.00 | 6% | \$3,795.78 |
| PW NBD ONSITE | 95511-H30575 | \$ 2,502.00 | 6% | \$2,369.52 |
| PW NBD ONSITE | 95511-H30576 | \$ 3,620.00 | 6% | \$3,428.32 |
| PW NBD ONSITE | 95511-H30577 | \$ 4,342.00 | 6% | \$4,112.09 |
| PW NBD ONSITE | 95511-H30578 | \$ 4,342.00 | 6% | \$4,112.09 |
| PW NBD ONSITE | 95511-H30587 | \$ 3,692.00 | 6% | \$3,496.51 |
| PW NBD ONSITE | 95511-H30588 | \$ 2,553.00 | 6% | \$2,417.82 |
| PW NBD ONSITE | 95511-H30589 | \$ 3,945.00 | 6% | \$3,736.11 |
| PW NBD ONSITE | 95511-H30632 | \$ 98.00 | 6% | \$92.81 |
| PW NBD ONSITE | 95511-H30633 | \$ 98.00 | 6% | \$92.81 |
| PW NBD ONSITE | 95511-H30643 | \$ 6,226.00 | 6% | \$5,896.33 |
| PW NBD ONSITE | 95511-H30706 | \$ 5,831.00 | 6% | \$5,522.25 |
| PW NBD ONSITE | 95511-H30707 | \$ 3,620.00 | 6% | \$3,428.32 |
| PW NBD ONSITE | 95511-H30724 | \$ 402.00 | 6% | \$380.71 |
| PW NBD ONSITE | 95511-H30725 | \$ 1,378.00 | 6% | \$1,305.03 |
| PW NBD ONSITE | 95511-H30726 | \$ 9,025.00 | 6% | \$8,547.13 |
| PW NBD ONSITE | 95511-H30727 | \$ 9,592.00 | 6% | \$9,084.10 |
| PW NBD ONSITE | 95511-H30730 | \$ 94.00 | 6% | \$89.02 |
| PW NBD ONSITE | 95511-H30731 | \$ 94.00 | 6% | \$89.02 |
| PW NBD ONSITE 30732 | 95511-H30732 | \$ 1,831.00 | 6% | \$1,734.05 |
| PW NBD ONSITE SKL8008-0810-F8 | 95511-H30733 | \$ 8,480.00 | 6% | \$8,030.98 |
| PW NBD ONSITE STL2006-0850 | 95511-H30734 | \$ 6,460.00 | 6% | \$6,117.94 |
| PW NBD ONSITE SGL2001-0850 | 95511-H30735 | \$ 7,517.00 | 6% | \$7,118.97 |

| | | | | |
|----------------------------|--------------|--------------|----|-------------------|
| PW NBD ONSITE SOK2209-0204 | 95511-H30736 | \$ 1,185.00 | 6% | <i>\$1,122.25</i> |
| PW NBD ONSITE H30738 | 95511-H30738 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW NBD ONSITE -H30739 | 95511-H30739 | \$ 1,265.00 | 6% | <i>\$1,198.02</i> |
| PW NBD ONSITE -H30740 | 95511-H30740 | \$ 734.00 | 6% | <i>\$695.13</i> |
| PW NBD ONSITE -H30741 | 95511-H30741 | \$ 1,339.00 | 6% | <i>\$1,268.10</i> |
| PW NBD ONSITE -H30742 | 95511-H30742 | \$ 1,188.00 | 6% | <i>\$1,125.10</i> |
| PW NBD ONSITE -H30743 | 95511-H30743 | \$ 1,265.00 | 6% | <i>\$1,198.02</i> |
| PW NBD ONSITE -H30744 | 95511-H30744 | \$ 734.00 | 6% | <i>\$695.13</i> |
| PW NBD ONSITE -H30745 | 95511-H30745 | \$ 749.00 | 6% | <i>\$709.34</i> |
| PW NBD ONSITE -H30746 | 95511-H30746 | \$ 1,327.00 | 6% | <i>\$1,256.74</i> |
| PW NBD ONSITE -H30747 | 95511-H30747 | \$ 2,631.00 | 6% | <i>\$2,491.69</i> |
| PW NBD ONSITE -H30748 | 95511-H30748 | \$ 3,878.00 | 6% | <i>\$3,672.66</i> |
| PW NBD ONSITE -H30749 | 95511-H30749 | \$ 8,716.00 | 6% | <i>\$8,254.49</i> |
| PW NBD ONSITE -H30750 | 95511-H30750 | \$ 8,716.00 | 6% | <i>\$8,254.49</i> |
| PW NBD ONSITE -H30751 | 95511-H30751 | \$ 5,165.00 | 6% | <i>\$4,891.51</i> |
| PW NBD ONSITE -H30754 | 95511-H30754 | \$ 8,716.00 | 6% | <i>\$8,254.49</i> |
| PW NBD ONSITE -H30755 | 95511-H30755 | \$ 9,477.00 | 6% | <i>\$8,975.19</i> |
| PW NBD ONSITE -H30756 | 95511-H30756 | \$ 8,716.00 | 6% | <i>\$8,254.49</i> |
| PW NBD ONSITE -H30757 | 95511-H30757 | \$ 3,878.00 | 6% | <i>\$3,672.66</i> |
| PW NBD ONSITE -H30758 | 95511-H30758 | \$ 6,920.00 | 6% | <i>\$6,553.59</i> |
| PW NBD ONSITE -H30759 | 95511-H30759 | \$ 7,897.00 | 6% | <i>\$7,478.85</i> |
| PW NBD ONSITE -H30760 | 95511-H30760 | \$ 8,907.00 | 6% | <i>\$8,435.37</i> |
| PW NBD ONSITE -H30761 | 95511-H30761 | \$ 3,878.00 | 6% | <i>\$3,672.66</i> |
| PW NBD ONSITE -H30762 | 95511-H30762 | \$ 9,477.00 | 6% | <i>\$8,975.19</i> |
| PW NBD ONSITE -H30763 | 95511-H30763 | \$ 9,477.00 | 6% | <i>\$8,975.19</i> |
| PW NBD ONSITE -H30764 | 95511-H30764 | \$ 6,004.00 | 6% | <i>\$5,686.09</i> |
| PW NBD ONSITE -H30765 | 95511-H30765 | \$ 5,267.00 | 6% | <i>\$4,988.11</i> |
| PW NBD ONSITE -H30766 | 95511-H30766 | \$ 10,271.00 | 6% | <i>\$9,727.15</i> |
| PW NBD ONSITE -H30767 | 95511-H30767 | \$ 6,004.00 | 6% | <i>\$5,686.09</i> |
| PW NBD ONSITE H30769 | 95511-H30769 | \$ 2,368.00 | 6% | <i>\$2,242.61</i> |
| PW NBD ONSITE H30773 | 95511-H30773 | \$ 149.00 | 6% | <i>\$141.11</i> |
| PW NBD ONSITE H30774 | 95511-H30774 | \$ 160.00 | 6% | <i>\$151.53</i> |
| PW NBD ONSITE H30775 | 95511-H30775 | \$ 160.00 | 6% | <i>\$151.53</i> |
| PW NBD ONSITE H30776 | 95511-H30776 | \$ 149.00 | 6% | <i>\$141.11</i> |
| PW NBD ONSITE H30777 | 95511-H30777 | \$ 160.00 | 6% | <i>\$151.53</i> |
| PW NBD ONSITE H30778 | 95511-H30778 | \$ 160.00 | 6% | <i>\$151.53</i> |
| PW NBD ONSITE H30779 | 95511-H30779 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE H30780 | 95511-H30780 | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW NBD ONSITE H30781 | 95511-H30781 | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW NBD ONSITE H30782 | 95511-H30782 | \$ 74.00 | 6% | <i>\$70.08</i> |
| PW NBD ONSITE H30783 | 95511-H30783 | \$ 75.00 | 6% | <i>\$71.03</i> |

| | | | | |
|----------------------|--------------|-----------|----|---------|
| PW NBD ONSITE H30784 | 95511-H30784 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H30785 | 95511-H30785 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H30786 | 95511-H30786 | \$ 89.00 | 6% | \$84.29 |
| PW NBD ONSITE H30787 | 95511-H30787 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H30788 | 95511-H30788 | \$ 89.00 | 6% | \$84.29 |
| PW NBD ONSITE H30789 | 95511-H30789 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H30790 | 95511-H30790 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H30791 | 95511-H30791 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H30793 | 95511-H30793 | \$ 69.00 | 6% | \$65.35 |
| PW NBD ONSITE H30794 | 95511-H30794 | \$ 86.00 | 6% | \$81.45 |
| PW NBD ONSITE H30795 | 95511-H30795 | \$ 66.00 | 6% | \$62.51 |
| PW NBD ONSITE H30796 | 95511-H30796 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H30797 | 95511-H30797 | \$ 66.00 | 6% | \$62.51 |
| PW NBD ONSITE H30798 | 95511-H30798 | \$ 65.00 | 6% | \$61.56 |
| PW NBD ONSITE H30799 | 95511-H30799 | \$ 66.00 | 6% | \$62.51 |
| PW NBD ONSITE H30800 | 95511-H30800 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H30801 | 95511-H30801 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H30802 | 95511-H30802 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H30803 | 95511-H30803 | \$ 103.00 | 6% | \$97.55 |
| PW NBD ONSITE H30804 | 95511-H30804 | \$ 66.00 | 6% | \$62.51 |
| PW NBD ONSITE H30805 | 95511-H30805 | \$ 65.00 | 6% | \$61.56 |
| PW NBD ONSITE H30806 | 95511-H30806 | \$ 103.00 | 6% | \$97.55 |
| PW NBD ONSITE H30807 | 95511-H30807 | \$ 66.00 | 6% | \$62.51 |
| PW NBD ONSITE H30808 | 95511-H30808 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H30809 | 95511-H30809 | \$ 65.00 | 6% | \$61.56 |
| PW NBD ONSITE H30810 | 95511-H30810 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H30811 | 95511-H30811 | \$ 103.00 | 6% | \$97.55 |
| PW NBD ONSITE H30812 | 95511-H30812 | \$ 65.00 | 6% | \$61.56 |
| PW NBD ONSITE H30813 | 95511-H30813 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H30814 | 95511-H30814 | \$ 103.00 | 6% | \$97.55 |
| PW NBD ONSITE H30815 | 95511-H30815 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H30816 | 95511-H30816 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H30817 | 95511-H30817 | \$ 103.00 | 6% | \$97.55 |
| PW NBD ONSITE H30818 | 95511-H30818 | \$ 65.00 | 6% | \$61.56 |
| PW NBD ONSITE H30819 | 95511-H30819 | \$ 103.00 | 6% | \$97.55 |
| PW NBD ONSITE H30820 | 95511-H30820 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H30821 | 95511-H30821 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H30822 | 95511-H30822 | \$ 66.00 | 6% | \$62.51 |
| PW NBD ONSITE H30823 | 95511-H30823 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H30824 | 95511-H30824 | \$ 65.00 | 6% | \$61.56 |
| PW NBD ONSITE H30825 | 95511-H30825 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H30826 | 95511-H30826 | \$ 103.00 | 6% | \$97.55 |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PW NBD ONSITE H30827 | 95511-H30827 | \$ 66.00 | 6% | <i>\$62.51</i> |
| PW NBD ONSITE H30828 | 95511-H30828 | \$ 66.00 | 6% | <i>\$62.51</i> |
| PW NBD ONSITE H30829 | 95511-H30829 | \$ 74.00 | 6% | <i>\$70.08</i> |
| PW NBD ONSITE H30830 | 95511-H30830 | \$ 103.00 | 6% | <i>\$97.55</i> |
| PW NBD ONSITE H30831 | 95511-H30831 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW NBD ONSITE H30832 | 95511-H30832 | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| PW NBD ONSITE H30833 | 95511-H30833 | \$ 365.00 | 6% | <i>\$345.67</i> |
| PW NBD ONSITE H30834 | 95511-H30834 | \$ 365.00 | 6% | <i>\$345.67</i> |
| PW NBD ONSITE H30836 | 95511-H30836 | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| PW NBD ONSITE H30838 | 95511-H30838 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PW NBD ONSITE H30839 | 95511-H30839 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD ONSITE H30840 | 95511-H30840 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD ONSITE H30841 | 95511-H30841 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD ONSITE H30842 | 95511-H30842 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD ONSITE H30843 | 95511-H30843 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD ONSITE H30844 | 95511-H30844 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD ONSITE H30845 | 95511-H30845 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PW NBD ONSITE H30846 | 95511-H30846 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD ONSITE H30847 | 95511-H30847 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD ONSITE H30848 | 95511-H30848 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD ONSITE H30849 | 95511-H30849 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD ONSITE H30850 | 95511-H30850 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD ONSITE H30851 | 95511-H30851 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD ONSITE H30852 | 95511-H30852 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PW NBD ONSITE H30853 | 95511-H30853 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30854 | 95511-H30854 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30855 | 95511-H30855 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30856 | 95511-H30856 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30857 | 95511-H30857 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30858 | 95511-H30858 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30859 | 95511-H30859 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30860 | 95511-H30860 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PW NBD ONSITE H30866 | 95511-H30866 | \$ 145.00 | 6% | <i>\$137.32</i> |
| PW NBD ONSITE H30867 | 95511-H30867 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE H30868 | 95511-H30868 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE H30869 | 95511-H30869 | \$ 256.00 | 6% | <i>\$242.44</i> |
| PW NBD ONSITE H30870 | 95511-H30870 | \$ 256.00 | 6% | <i>\$242.44</i> |
| PW NBD ONSITE H30871 | 95511-H30871 | \$ 235.00 | 6% | <i>\$222.56</i> |
| PW NBD ONSITE H30872 | 95511-H30872 | \$ 134.00 | 6% | <i>\$126.90</i> |
| PW NBD ONSITE H30873 | 95511-H30873 | \$ 134.00 | 6% | <i>\$126.90</i> |
| PW NBD ONSITE H30874 | 95511-H30874 | \$ 134.00 | 6% | <i>\$126.90</i> |
| PW NBD ONSITE H30875 | 95511-H30875 | \$ 46.00 | 6% | <i>\$43.56</i> |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PW NBD ONSITE H30876 | 95511-H30876 | \$ 43.00 | 6% | <i>\$40.72</i> |
| PW NBD ONSITE H30877 | 95511-H30877 | \$ 46.00 | 6% | <i>\$43.56</i> |
| PW NBD ONSITE H30878 | 95511-H30878 | \$ 46.00 | 6% | <i>\$43.56</i> |
| PW NBD ONSITE H30891 | 95511-H30891 | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW NBD ONSITE H30892 | 95511-H30892 | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW NBD ONSITE H30893 | 95511-H30893 | \$ 78.00 | 6% | <i>\$73.87</i> |
| PW NBD ONSITE H30894 | 95511-H30894 | \$ 46.00 | 6% | <i>\$43.56</i> |
| PW NBD ONSITE H30895 | 95511-H30895 | \$ 160.00 | 6% | <i>\$151.53</i> |
| PW NBD ONSITE H30896 | 95511-H30896 | \$ 378.00 | 6% | <i>\$357.98</i> |
| PW NBD ONSITE H30897 | 95511-H30897 | \$ 669.00 | 6% | <i>\$633.58</i> |
| PW NBD ONSITE H30898 | 95511-H30898 | \$ 752.00 | 6% | <i>\$712.18</i> |
| PW NBD ONSITE H30900 | 95511-H30900 | \$ 2,276.00 | 6% | <i>\$2,155.49</i> |
| PW NBD ONSITE H30901 | 95511-H30901 | \$ 3,025.00 | 6% | <i>\$2,864.83</i> |
| PW NBD ONSITE H30902 | 95511-H30902 | \$ 3,175.00 | 6% | <i>\$3,006.88</i> |
| PW NBD ONSITE H30904 | 95511-H30904 | \$ 4,671.00 | 6% | <i>\$4,423.67</i> |
| PW NBD ONSITE H30905 | 95511-H30905 | \$ 6,672.00 | 6% | <i>\$6,318.72</i> |
| PW NBD ONSITE H30906 | 95511-H30906 | \$ 179.00 | 6% | <i>\$169.52</i> |
| PW NBD ONSITE H30912 | 95511-H30912 | \$ 503.00 | 6% | <i>\$476.37</i> |
| PW NBD ONSITE H30913 | 95511-H30913 | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD ONSITE H30914 | 95511-H30914 | \$ 46.00 | 6% | <i>\$43.56</i> |
| PW NBD ONSITE H30915 | 95511-H30915 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PW NBD ONSITE H30916 | 95511-H30916 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PW NBD ONSITE H30917 | 95511-H30917 | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD ONSITE H30918 | 95511-H30918 | \$ 52.00 | 6% | <i>\$49.25</i> |
| PW NBD ONSITE H30946 | 95511-H30946 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW NBD ONSITE H30948 | 95511-H30948 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW NBD ONSITE H30950 | 95511-H30950 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE H30951 | 95511-H30951 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW NBD ONSITE H30952 | 95511-H30952 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PW NBD ONSITE H30966 | 95511-H30966 | \$ 160.00 | 6% | <i>\$151.53</i> |
| PW NBD ONSITE H30967 | 95511-H30967 | \$ 149.00 | 6% | <i>\$141.11</i> |
| PW NBD ONSITE H30968 | 95511-H30968 | \$ 160.00 | 6% | <i>\$151.53</i> |
| PW NBD ONSITE H30969 | 95511-H30969 | \$ 87.00 | 6% | <i>\$82.39</i> |
| PW NBD ONSITE H30970 | 95511-H30970 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW NBD ONSITE H30971 | 95511-H30971 | \$ 102.00 | 6% | <i>\$96.60</i> |
| PW NBD ONSITE H30972 | 95511-H30972 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PW NBD ONSITE H30973 | 95511-H30973 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD ONSITE H30974 | 95511-H30974 | \$ 144.00 | 6% | <i>\$136.38</i> |
| PW NBD ONSITE H30975 | 95511-H30975 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD ONSITE H30976 | 95511-H30976 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD ONSITE H30977 | 95511-H30977 | \$ 144.00 | 6% | <i>\$136.38</i> |
| PW NBD ONSITE H30978 | 95511-H30978 | \$ 165.00 | 6% | <i>\$156.26</i> |

| | | | | |
|----------------------|--------------|-------------|----|------------|
| PW NBD ONSITE H30995 | 95511-H30995 | \$ 1,826.00 | 6% | \$1,729.31 |
| PW NBD ONSITE H31030 | 95511-H31030 | \$ 5,893.00 | 6% | \$5,580.97 |
| PW NBD ONSITE H31031 | 95511-H31031 | \$ 468.00 | 6% | \$443.22 |
| PW NBD ONSITE H31033 | 95511-H31033 | \$ 3,567.00 | 6% | \$3,378.13 |
| PW NBD ONSITE H31034 | 95511-H31034 | \$ 1,982.00 | 6% | \$1,877.05 |
| PW NBD ONSITE H31035 | 95511-H31035 | \$ 2,078.00 | 6% | \$1,967.97 |
| PW NBD ONSITE H31036 | 95511-H31036 | \$ 4,161.00 | 6% | \$3,940.68 |
| PW NBD ONSITE H31040 | 95511-H31040 | \$ 152.00 | 6% | \$143.95 |
| PW NBD ONSITE H31041 | 95511-H31041 | \$ 78.00 | 6% | \$73.87 |
| PW NBD ONSITE H31042 | 95511-H31042 | \$ 230.00 | 6% | \$217.82 |
| PW NBD ONSITE H31043 | 95511-H31043 | \$ 166.00 | 6% | \$157.21 |
| PW NBD ONSITE H31047 | 95511-H31047 | \$ 155.00 | 6% | \$146.79 |
| PW NBD ONSITE H31049 | 95511-H31049 | \$ 1,660.00 | 6% | \$1,572.10 |
| PW NBD ONSITE H31060 | 95511-H31060 | \$ 42.00 | 6% | \$39.78 |
| PW NBD ONSITE H31062 | 95511-H31062 | \$ 45.00 | 6% | \$42.62 |
| PW NBD ONSITE H31066 | 95511-H31066 | \$ 61.00 | 6% | \$57.77 |
| PW NBD ONSITE H31068 | 95511-H31068 | \$ 65.00 | 6% | \$61.56 |
| PW NBD ONSITE H31076 | 95511-H31076 | \$ 225.00 | 6% | \$213.09 |
| PW NBD ONSITE H31077 | 95511-H31077 | \$ 230.00 | 6% | \$217.82 |
| PW NBD ONSITE H31078 | 95511-H31078 | \$ 235.00 | 6% | \$222.56 |
| PW NBD ONSITE H31103 | 95511-H31103 | \$ 3,809.00 | 6% | \$3,607.31 |
| PW NBD ONSITE H31119 | 95511-H31119 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H31124 | 95511-H31124 | \$ 92.00 | 6% | \$87.13 |
| PW NBD ONSITE H31127 | 95511-H31127 | \$ 149.00 | 6% | \$141.11 |
| PW NBD ONSITE H31132 | 95511-H31132 | \$ 146.00 | 6% | \$138.27 |
| PW NBD ONSITE H31134 | 95511-H31134 | \$ 46.00 | 6% | \$43.56 |
| PW NBD ONSITE H31135 | 95511-H31135 | \$ 51.00 | 6% | \$48.30 |
| PW NBD ONSITE H31136 | 95511-H31136 | \$ 77.00 | 6% | \$72.92 |
| PW NBD ONSITE H31137 | 95511-H31137 | \$ 71.00 | 6% | \$67.24 |
| PW NBD ONSITE H31197 | 95511-H31197 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H31198 | 95511-H31198 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H31199 | 95511-H31199 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H31200 | 95511-H31200 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H31201 | 95511-H31201 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H31202 | 95511-H31202 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H31203 | 95511-H31203 | \$ 100.00 | 6% | \$94.71 |
| PW NBD ONSITE H31204 | 95511-H31204 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H31205 | 95511-H31205 | \$ 100.00 | 6% | \$94.71 |
| PW NBD ONSITE H31206 | 95511-H31206 | \$ 100.00 | 6% | \$94.71 |
| PW NBD ONSITE H31207 | 95511-H31207 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H31208 | 95511-H31208 | \$ 100.00 | 6% | \$94.71 |
| PW NBD ONSITE H31210 | 95511-H31210 | \$ 179.00 | 6% | \$169.52 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW NBD ONSITE H31335 | 95511-H31335 | \$ 102.00 | 6% | \$96.60 |
| PW NBD ONSITE H31337 | 95511-H31337 | \$ 7,639.00 | 6% | \$7,234.51 |
| PW NBD ONSITE H31338 | 95511-H31338 | \$ 7,639.00 | 6% | \$7,234.51 |
| PW NBD ONSITE H31339 | 95511-H31339 | \$ 1,242.00 | 6% | \$1,176.24 |
| PW NBD ONSITE H31340 | 95511-H31340 | \$ 2,651.00 | 6% | \$2,510.63 |
| PW NBD ONSITE H31341 | 95511-H31341 | \$ 3,929.00 | 6% | \$3,720.96 |
| PW NBD ONSITE H31342 | 95511-H31342 | \$ 1,237.00 | 6% | \$1,171.50 |
| PW NBD ONSITE H31343 | 95511-H31343 | \$ 1,831.00 | 6% | \$1,734.05 |
| PW NBD ONSITE H31344 | 95511-H31344 | \$ 1,831.00 | 6% | \$1,734.05 |
| PW NBD ONSITE H31345 | 95511-H31345 | \$ 1,831.00 | 6% | \$1,734.05 |
| PW NBD ONSITE H31346 | 95511-H31346 | \$ 1,831.00 | 6% | \$1,734.05 |
| PW NBD ONSITE H31348 | 95511-H31348 | \$ 144.00 | 6% | \$136.38 |
| PW NBD ONSITE H31349 | 95511-H31349 | \$ 144.00 | 6% | \$136.38 |
| PW NBD ONSITE H31350 | 95511-H31350 | \$ 235.00 | 6% | \$222.56 |
| PW NBD ONSITE H31351 | 95511-H31351 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H31352 | 95511-H31352 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H31353 | 95511-H31353 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H31354 | 95511-H31354 | \$ 74.00 | 6% | \$70.08 |
| PW NBD ONSITE H31355 | 95511-H31355 | \$ 149.00 | 6% | \$141.11 |
| PW NBD ONSITE H31356 | 95511-H31356 | \$ 149.00 | 6% | \$141.11 |
| PW NBD ONSITE H31357 | 95511-H31357 | \$ 149.00 | 6% | \$141.11 |
| PW NBD ONSITE H31358 | 95511-H31358 | \$ 57.00 | 6% | \$53.98 |
| PW NBD ONSITE H31359 | 95511-H31359 | \$ 61.00 | 6% | \$57.77 |
| PW NBD ONSITE H31360 | 95511-H31360 | \$ 49.00 | 6% | \$46.41 |
| PW NBD ONSITE H31361 | 95511-H31361 | \$ 2,573.00 | 6% | \$2,436.76 |
| PW NBD ONSITE H31362 | 95511-H31362 | \$ 17,258.00 | 6% | \$16,344.19 |
| PW NBD ONSITE H31363 | 95511-H31363 | \$ 17,258.00 | 6% | \$16,344.19 |
| PW NBD ONSITE H31364 | 95511-H31364 | \$ 6,033.00 | 6% | \$5,713.55 |
| PW NBD ONSITE H31365 | 95511-H31365 | \$ 6,033.00 | 6% | \$5,713.55 |
| PW NBD ONSITE H31366 | 95511-H31366 | \$ 8,363.00 | 6% | \$7,920.18 |
| PW NBD ONSITE H31367 | 95511-H31367 | \$ 8,363.00 | 6% | \$7,920.18 |
| PW NBD ONSITE H31369 | 95511-H31369 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H31370 | 95511-H31370 | \$ 87.00 | 6% | \$82.39 |
| PW NBD ONSITE H31393 | 95511-H31393 | \$ 49.00 | 6% | \$46.41 |
| PW NBD ONSITE H32010 | 95511-H32010 | \$ 241.00 | 6% | \$228.24 |
| PW NBD ONSITE H32011 | 95511-H32011 | \$ 241.00 | 6% | \$228.24 |
| PW NBD ONSITE H32012 | 95511-H32012 | \$ 2,070.00 | 6% | \$1,960.39 |
| PW NBD ONSITE H32013 | 95511-H32013 | \$ 2,070.00 | 6% | \$1,960.39 |
| PW NBD ONSITE H32014 | 95511-H32014 | \$ 2,070.00 | 6% | \$1,960.39 |
| PW NBD ONSITE H32015 | 95511-H32015 | \$ 2,070.00 | 6% | \$1,960.39 |
| PW NBD ONSITE H32016 | 95511-H32016 | \$ 1,810.00 | 6% | \$1,714.16 |
| PW NBD ONSITE H32017 | 95511-H32017 | \$ 1,810.00 | 6% | \$1,714.16 |

| | | | | |
|----------------------|--------------|--------------|----|--------------------|
| PW NBD ONSITE H32018 | 95511-H32018 | \$ 1,810.00 | 6% | <i>\$1,714.16</i> |
| PW NBD ONSITE H32019 | 95511-H32019 | \$ 1,810.00 | 6% | <i>\$1,714.16</i> |
| PW NBD ONSITE H32020 | 95511-H32020 | \$ 18,105.00 | 6% | <i>\$17,146.34</i> |
| PW NBD ONSITE H32021 | 95511-H32021 | \$ 18,105.00 | 6% | <i>\$17,146.34</i> |
| PW NBD ONSITE H32022 | 95511-H32022 | \$ 18,105.00 | 6% | <i>\$17,146.34</i> |
| PW NBD ONSITE H32023 | 95511-H32023 | \$ 18,105.00 | 6% | <i>\$17,146.34</i> |
| PW NBD ONSITE H32028 | 95511-H32028 | \$ 34,907.00 | 6% | <i>\$33,058.67</i> |
| PW NBD ONSITE H32029 | 95511-H32029 | \$ 34,907.00 | 6% | <i>\$33,058.67</i> |
| PW NBD ONSITE H32030 | 95511-H32030 | \$ 36,609.00 | 6% | <i>\$34,670.55</i> |
| PW NBD ONSITE H32031 | 95511-H32031 | \$ 36,609.00 | 6% | <i>\$34,670.55</i> |
| PW NBD ONSITE H32032 | 95511-H32032 | \$ 36,609.00 | 6% | <i>\$34,670.55</i> |
| PW NBD ONSITE H32033 | 95511-H32033 | \$ 36,609.00 | 6% | <i>\$34,670.55</i> |
| PW NBD ONSITE H32038 | 95511-H32038 | \$ 6,328.00 | 6% | <i>\$5,992.93</i> |
| PW NBD ONSITE H32039 | 95511-H32039 | \$ 6,328.00 | 6% | <i>\$5,992.93</i> |
| PW NBD ONSITE H32040 | 95511-H32040 | \$ 6,328.00 | 6% | <i>\$5,992.93</i> |
| PW NBD ONSITE H32041 | 95511-H32041 | \$ 6,328.00 | 6% | <i>\$5,992.93</i> |
| PW NBD ONSITE H32046 | 95511-H32046 | \$ 8,777.00 | 6% | <i>\$8,312.26</i> |
| PW NBD ONSITE H32047 | 95511-H32047 | \$ 8,777.00 | 6% | <i>\$8,312.26</i> |
| PW NBD ONSITE H32048 | 95511-H32048 | \$ 8,777.00 | 6% | <i>\$8,312.26</i> |
| PW NBD ONSITE H32049 | 95511-H32049 | \$ 8,777.00 | 6% | <i>\$8,312.26</i> |
| PW NBD ONSITE H32054 | 95511-H32054 | \$ 6,328.00 | 6% | <i>\$5,992.93</i> |
| PW NBD ONSITE H32055 | 95511-H32055 | \$ 8,777.00 | 6% | <i>\$8,312.26</i> |
| PW NBD ONSITE H32056 | 95511-H32056 | \$ 2,518.00 | 6% | <i>\$2,384.67</i> |
| PW NBD ONSITE H32057 | 95511-H32057 | \$ 2,518.00 | 6% | <i>\$2,384.67</i> |
| PW NBD ONSITE H32058 | 95511-H32058 | \$ 2,518.00 | 6% | <i>\$2,384.67</i> |
| PW NBD ONSITE H32059 | 95511-H32059 | \$ 2,518.00 | 6% | <i>\$2,384.67</i> |
| PW NBD ONSITE H32060 | 95511-H32060 | \$ 2,455.00 | 6% | <i>\$2,325.01</i> |
| PW NBD ONSITE H32061 | 95511-H32061 | \$ 2,578.00 | 6% | <i>\$2,441.49</i> |
| PW NBD ONSITE H32062 | 95511-H32062 | \$ 2,479.00 | 6% | <i>\$2,347.74</i> |
| PW NBD ONSITE H32063 | 95511-H32063 | \$ 2,458.00 | 6% | <i>\$2,327.85</i> |
| PW NBD ONSITE H32064 | 95511-H32064 | \$ 2,479.00 | 6% | <i>\$2,347.74</i> |
| PW NBD ONSITE H32065 | 95511-H32065 | \$ 2,797.00 | 6% | <i>\$2,648.90</i> |
| PW NBD ONSITE H32066 | 95511-H32066 | \$ 2,797.00 | 6% | <i>\$2,648.90</i> |
| PW NBD ONSITE H32067 | 95511-H32067 | \$ 2,797.00 | 6% | <i>\$2,648.90</i> |
| PW NBD ONSITE H32068 | 95511-H32068 | \$ 2,797.00 | 6% | <i>\$2,648.90</i> |
| PW NBD ONSITE H32069 | 95511-H32069 | \$ 3,482.00 | 6% | <i>\$3,297.63</i> |
| PW NBD ONSITE H32070 | 95511-H32070 | \$ 3,482.00 | 6% | <i>\$3,297.63</i> |
| PW NBD ONSITE H32071 | 95511-H32071 | \$ 3,482.00 | 6% | <i>\$3,297.63</i> |
| PW NBD ONSITE H32072 | 95511-H32072 | \$ 3,482.00 | 6% | <i>\$3,297.63</i> |
| PW NBD ONSITE H32073 | 95511-H32073 | \$ 25,709.00 | 6% | <i>\$24,347.71</i> |
| PW NBD ONSITE H32074 | 95511-H32074 | \$ 25,708.00 | 6% | <i>\$24,346.76</i> |
| PW NBD ONSITE H32075 | 95511-H32075 | \$ 34,945.00 | 6% | <i>\$33,094.66</i> |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW NBD ONSITE H32076 | 95511-H32076 | \$ 34,945.00 | 6% | \$33,094.66 |
| PW NBD ONSITE H32101 | 95511-H32101 | \$ 1,120.00 | 6% | \$1,060.70 |
| PW NBD ONSITE H32102 | 95511-H32102 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW NBD ONSITE H32103 | 95511-H32103 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW NBD ONSITE H32104 | 95511-H32104 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW NBD ONSITE H32105 | 95511-H32105 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32106 | 95511-H32106 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32107 | 95511-H32107 | \$ 6,129.00 | 6% | \$5,804.47 |
| PW NBD ONSITE H32108 | 95511-H32108 | \$ 6,129.00 | 6% | \$5,804.47 |
| PW NBD ONSITE H32109 | 95511-H32109 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32110 | 95511-H32110 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32111 | 95511-H32111 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW NBD ONSITE H32112 | 95511-H32112 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW NBD ONSITE H32113 | 95511-H32113 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW NBD ONSITE H32114 | 95511-H32114 | \$ 1,131.00 | 6% | \$1,071.11 |
| PW NBD ONSITE H32115 | 95511-H32115 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32116 | 95511-H32116 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32117 | 95511-H32117 | \$ 1,067.00 | 6% | \$1,010.50 |
| PW NBD ONSITE H32118 | 95511-H32118 | \$ 1,067.00 | 6% | \$1,010.50 |
| PW NBD ONSITE H32119 | 95511-H32119 | \$ 1,067.00 | 6% | \$1,010.50 |
| PW NBD ONSITE H32120 | 95511-H32120 | \$ 1,067.00 | 6% | \$1,010.50 |
| PW NBD ONSITE H32121 | 95511-H32121 | \$ 6,129.00 | 6% | \$5,804.47 |
| PW NBD ONSITE H32122 | 95511-H32122 | \$ 6,129.00 | 6% | \$5,804.47 |
| PW NBD ONSITE H32123 | 95511-H32123 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32124 | 95511-H32124 | \$ 2,265.00 | 6% | \$2,145.07 |
| PW NBD ONSITE H32125 | 95511-H32125 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32126 | 95511-H32126 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32127 | 95511-H32127 | \$ 2,633.00 | 6% | \$2,493.58 |
| PW NBD ONSITE H32128 | 95511-H32128 | \$ 2,633.00 | 6% | \$2,493.58 |
| PW NBD ONSITE H32129 | 95511-H32129 | \$ 2,633.00 | 6% | \$2,493.58 |
| PW NBD ONSITE H32130 | 95511-H32130 | \$ 2,633.00 | 6% | \$2,493.58 |
| PW NBD ONSITE H32131 | 95511-H32131 | \$ 2,633.00 | 6% | \$2,493.58 |
| PW NBD ONSITE H32132 | 95511-H32132 | \$ 2,633.00 | 6% | \$2,493.58 |
| PW NBD ONSITE H32133 | 95511-H32133 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32134 | 95511-H32134 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32135 | 95511-H32135 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32136 | 95511-H32136 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32137 | 95511-H32137 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32138 | 95511-H32138 | \$ 2,241.00 | 6% | \$2,122.34 |
| PW NBD ONSITE H32139 | 95511-H32139 | \$ 9,479.00 | 6% | \$8,977.09 |
| PW NBD ONSITE H32140 | 95511-H32140 | \$ 9,479.00 | 6% | \$8,977.09 |
| PW NBD ONSITE H32141 | 95511-H32141 | \$ 10,939.00 | 6% | \$10,359.78 |

| | | | | |
|----------------------|--------------|--------------|----|--------------------|
| PW NBD ONSITE H32142 | 95511-H32142 | \$ 10,939.00 | 6% | <i>\$10,359.78</i> |
| PW NBD ONSITE H32146 | 95511-H32146 | \$ 966.00 | 6% | <i>\$914.85</i> |
| PW NBD ONSITE H32147 | 95511-H32147 | \$ 966.00 | 6% | <i>\$914.85</i> |
| PW NBD ONSITE H32148 | 95511-H32148 | \$ 1,990.00 | 6% | <i>\$1,884.63</i> |
| PW NBD ONSITE H32149 | 95511-H32149 | \$ 1,990.00 | 6% | <i>\$1,884.63</i> |
| PW NBD ONSITE H32150 | 95511-H32150 | \$ 1,021.00 | 6% | <i>\$966.94</i> |
| PW NBD ONSITE H32169 | 95511-H32169 | \$ 1,145.00 | 6% | <i>\$1,084.37</i> |
| PW NBD ONSITE H32170 | 95511-H32170 | \$ 1,145.00 | 6% | <i>\$1,084.37</i> |
| PW NBD ONSITE H32171 | 95511-H32171 | \$ 1,079.00 | 6% | <i>\$1,021.87</i> |
| PW NBD ONSITE H32172 | 95511-H32172 | \$ 1,079.00 | 6% | <i>\$1,021.87</i> |
| PW NBD ONSITE H32173 | 95511-H32173 | \$ 2,863.00 | 6% | <i>\$2,711.40</i> |
| PW NBD ONSITE H32174 | 95511-H32174 | \$ 2,863.00 | 6% | <i>\$2,711.40</i> |
| PW NBD ONSITE H32175 | 95511-H32175 | \$ 2,437.00 | 6% | <i>\$2,307.96</i> |
| PW NBD ONSITE H32176 | 95511-H32176 | \$ 2,437.00 | 6% | <i>\$2,307.96</i> |
| PW NBD ONSITE H32177 | 95511-H32177 | \$ 11,176.00 | 6% | <i>\$10,584.23</i> |
| PW NBD ONSITE H32178 | 95511-H32178 | \$ 12,893.00 | 6% | <i>\$12,210.32</i> |
| PW NBD ONSITE H34008 | 95511-H34008 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PW NBD ONSITE H34009 | 95511-H34009 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE H34010 | 95511-H34010 | \$ 43.00 | 6% | <i>\$40.72</i> |
| PW NBD ONSITE H34011 | 95511-H34011 | \$ 89.00 | 6% | <i>\$84.29</i> |
| PW NBD ONSITE H34012 | 95511-H34012 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PW NBD ONSITE H34013 | 95511-H34013 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PW NBD ONSITE H34014 | 95511-H34014 | \$ 105.00 | 6% | <i>\$99.44</i> |
| PW NBD ONSITE H34015 | 95511-H34015 | \$ 55.00 | 6% | <i>\$52.09</i> |
| PW NBD ONSITE H34016 | 95511-H34016 | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW NBD ONSITE H34017 | 95511-H34017 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PW NBD ONSITE H34018 | 95511-H34018 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE H34019 | 95511-H34019 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE H34020 | 95511-H34020 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE H34021 | 95511-H34021 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PW NBD ONSITE H34048 | 95511-H34048 | \$ 322.00 | 6% | <i>\$304.95</i> |
| PW NBD ONSITE H34049 | 95511-H34049 | \$ 322.00 | 6% | <i>\$304.95</i> |
| PW NBD ONSITE H34050 | 95511-H34050 | \$ 239.00 | 6% | <i>\$226.34</i> |
| PW NBD ONSITE H34051 | 95511-H34051 | \$ 239.00 | 6% | <i>\$226.34</i> |
| PW NBD ONSITE H34052 | 95511-H34052 | \$ 374.00 | 6% | <i>\$354.20</i> |
| PW NBD ONSITE H34053 | 95511-H34053 | \$ 374.00 | 6% | <i>\$354.20</i> |
| PW NBD ONSITE H34054 | 95511-H34054 | \$ 282.00 | 6% | <i>\$267.07</i> |
| PW NBD ONSITE H34055 | 95511-H34055 | \$ 282.00 | 6% | <i>\$267.07</i> |
| PW NBD ONSITE H34056 | 95511-H34056 | \$ 406.00 | 6% | <i>\$384.50</i> |
| PW NBD ONSITE H34057 | 95511-H34057 | \$ 406.00 | 6% | <i>\$384.50</i> |
| PW NBD ONSITE H34058 | 95511-H34058 | \$ 350.00 | 6% | <i>\$331.47</i> |
| PW NBD ONSITE H34059 | 95511-H34059 | \$ 350.00 | 6% | <i>\$331.47</i> |

| | | | | |
|----------------------|--------------|-------------|----|------------|
| PW NBD ONSITE H34062 | 95511-H34062 | \$ 406.00 | 6% | \$384.50 |
| PW NBD ONSITE H34063 | 95511-H34063 | \$ 406.00 | 6% | \$384.50 |
| PW NBD ONSITE H34064 | 95511-H34064 | \$ 342.00 | 6% | \$323.89 |
| PW NBD ONSITE H34065 | 95511-H34065 | \$ 342.00 | 6% | \$323.89 |
| PW NBD ONSITE H34066 | 95511-H34066 | \$ 342.00 | 6% | \$323.89 |
| PW NBD ONSITE H34067 | 95511-H34067 | \$ 342.00 | 6% | \$323.89 |
| PW NBD ONSITE H34068 | 95511-H34068 | \$ 342.00 | 6% | \$323.89 |
| PW NBD ONSITE H34069 | 95511-H34069 | \$ 333.00 | 6% | \$315.37 |
| PW NBD ONSITE H34070 | 95511-H34070 | \$ 342.00 | 6% | \$323.89 |
| PW NBD ONSITE H34071 | 95511-H34071 | \$ 342.00 | 6% | \$323.89 |
| PW NBD ONSITE H34072 | 95511-H34072 | \$ 2,248.00 | 6% | \$2,128.97 |
| PW NBD ONSITE H34073 | 95511-H34073 | \$ 2,205.00 | 6% | \$2,088.25 |
| PW NBD ONSITE H34074 | 95511-H34074 | \$ 2,812.00 | 6% | \$2,663.10 |
| PW NBD ONSITE H34075 | 95511-H34075 | \$ 2,695.00 | 6% | \$2,552.30 |
| PW NBD ONSITE H34076 | 95511-H34076 | \$ 2,248.00 | 6% | \$2,128.97 |
| PW NBD ONSITE H34077 | 95511-H34077 | \$ 2,205.00 | 6% | \$2,088.25 |
| PW NBD ONSITE H34078 | 95511-H34078 | \$ 2,248.00 | 6% | \$2,128.97 |
| PW NBD ONSITE H34079 | 95511-H34079 | \$ 2,205.00 | 6% | \$2,088.25 |
| PW NBD ONSITE H34080 | 95511-H34080 | \$ 2,812.00 | 6% | \$2,663.10 |
| PW NBD ONSITE H34081 | 95511-H34081 | \$ 2,695.00 | 6% | \$2,552.30 |
| PW NBD ONSITE H34082 | 95511-H34082 | \$ 2,697.00 | 6% | \$2,554.19 |
| PW NBD ONSITE H34083 | 95511-H34083 | \$ 2,585.00 | 6% | \$2,448.12 |
| PW NBD ONSITE H34084 | 95511-H34084 | \$ 2,780.00 | 6% | \$2,632.80 |
| PW NBD ONSITE H34085 | 95511-H34085 | \$ 2,780.00 | 6% | \$2,632.80 |
| PW NBD ONSITE H34086 | 95511-H34086 | \$ 3,236.00 | 6% | \$3,064.65 |
| PW NBD ONSITE H34087 | 95511-H34087 | \$ 3,104.00 | 6% | \$2,939.64 |
| PW NBD ONSITE H34088 | 95511-H34088 | \$ 4,835.00 | 6% | \$4,578.99 |
| PW NBD ONSITE H34089 | 95511-H34089 | \$ 4,835.00 | 6% | \$4,578.99 |
| PW NBD ONSITE H34090 | 95511-H34090 | \$ 5,567.00 | 6% | \$5,272.23 |
| PW NBD ONSITE H34091 | 95511-H34091 | \$ 3,133.00 | 6% | \$2,967.11 |
| PW NBD ONSITE H34092 | 95511-H34092 | \$ 3,133.00 | 6% | \$2,967.11 |
| PW NBD ONSITE H34093 | 95511-H34093 | \$ 3,133.00 | 6% | \$2,967.11 |
| PW NBD ONSITE H34094 | 95511-H34094 | \$ 362.00 | 6% | \$342.83 |
| PW NBD ONSITE H34095 | 95511-H34095 | \$ 362.00 | 6% | \$342.83 |
| PW NBD ONSITE H34096 | 95511-H34096 | \$ 405.00 | 6% | \$383.56 |
| PW NBD ONSITE H34097 | 95511-H34097 | \$ 405.00 | 6% | \$383.56 |
| PW NBD ONSITE H34098 | 95511-H34098 | \$ 362.00 | 6% | \$342.83 |
| PW NBD ONSITE H34099 | 95511-H34099 | \$ 362.00 | 6% | \$342.83 |
| PW NBD ONSITE H34100 | 95511-H34100 | \$ 362.00 | 6% | \$342.83 |
| PW NBD ONSITE H34101 | 95511-H34101 | \$ 362.00 | 6% | \$342.83 |
| PW NBD ONSITE H34102 | 95511-H34102 | \$ 362.00 | 6% | \$342.83 |
| PW NBD ONSITE H34103 | 95511-H34103 | \$ 362.00 | 6% | \$342.83 |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PW NBD ONSITE H34104 | 95511-H34104 | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW NBD ONSITE H34105 | 95511-H34105 | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW NBD ONSITE H34106 | 95511-H34106 | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW NBD ONSITE H34107 | 95511-H34107 | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW NBD ONSITE H34108 | 95511-H34108 | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW NBD ONSITE H34109 | 95511-H34109 | \$ 161.00 | 6% | <i>\$152.48</i> |
| PW NBD ONSITE H34110 | 95511-H34110 | \$ 3,018.00 | 6% | <i>\$2,858.20</i> |
| PW NBD ONSITE H34111 | 95511-H34111 | \$ 3,018.00 | 6% | <i>\$2,858.20</i> |
| PW NBD ONSITE H34112 | 95511-H34112 | \$ 3,018.00 | 6% | <i>\$2,858.20</i> |
| PW NBD ONSITE H34114 | 95511-H34114 | \$ 3,956.00 | 6% | <i>\$3,746.53</i> |
| PW NBD ONSITE H34115 | 95511-H34115 | \$ 3,956.00 | 6% | <i>\$3,746.53</i> |
| PW NBD ONSITE H34116 | 95511-H34116 | \$ 3,956.00 | 6% | <i>\$3,746.53</i> |
| PW NBD ONSITE H34117 | 95511-H34117 | \$ 3,956.00 | 6% | <i>\$3,746.53</i> |
| PW NBD ONSITE H34118 | 95511-H34118 | \$ 1,000.00 | 6% | <i>\$947.05</i> |
| PW NBD ONSITE H34119 | 95511-H34119 | \$ 1,000.00 | 6% | <i>\$947.05</i> |
| PW NBD ONSITE H34120 | 95511-H34120 | \$ 690.00 | 6% | <i>\$653.46</i> |
| PW NBD ONSITE H34121 | 95511-H34121 | \$ 690.00 | 6% | <i>\$653.46</i> |
| PW NBD ONSITE H34122 | 95511-H34122 | \$ 715.00 | 6% | <i>\$677.14</i> |
| PW NBD ONSITE H34123 | 95511-H34123 | \$ 715.00 | 6% | <i>\$677.14</i> |
| PW NBD ONSITE H34124 | 95511-H34124 | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| PW NBD ONSITE H34125 | 95511-H34125 | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| PW NBD ONSITE H34126 | 95511-H34126 | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| PW NBD ONSITE H34127 | 95511-H34127 | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| PW NBD ONSITE H34128 | 95511-H34128 | \$ 174.00 | 6% | <i>\$164.79</i> |
| PW NBD ONSITE H34129 | 95511-H34129 | \$ 349.00 | 6% | <i>\$330.52</i> |
| PW NBD ONSITE H34130 | 95511-H34130 | \$ 363.00 | 6% | <i>\$343.78</i> |
| PW NBD ONSITE H34131 | 95511-H34131 | \$ 361.00 | 6% | <i>\$341.89</i> |
| PW NBD ONSITE H34132 | 95511-H34132 | \$ 363.00 | 6% | <i>\$343.78</i> |
| PW NBD ONSITE H34172 | 95511-H34172 | \$ 1,870.00 | 6% | <i>\$1,770.98</i> |
| PW NBD ONSITE H34174 | 95511-H34174 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34175 | 95511-H34175 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34176 | 95511-H34176 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34177 | 95511-H34177 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34178 | 95511-H34178 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34179 | 95511-H34179 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34180 | 95511-H34180 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34181 | 95511-H34181 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34182 | 95511-H34182 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34183 | 95511-H34183 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34184 | 95511-H34184 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34185 | 95511-H34185 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34186 | 95511-H34186 | \$ 58.00 | 6% | <i>\$54.93</i> |

| | | | | | |
|----------------------|--------------|----|-------|----|----------------|
| PW NBD ONSITE H34187 | 95511-H34187 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34188 | 95511-H34188 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34189 | 95511-H34189 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34190 | 95511-H34190 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34191 | 95511-H34191 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34192 | 95511-H34192 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34193 | 95511-H34193 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34194 | 95511-H34194 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34195 | 95511-H34195 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34196 | 95511-H34196 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34197 | 95511-H34197 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34198 | 95511-H34198 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34199 | 95511-H34199 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34200 | 95511-H34200 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34201 | 95511-H34201 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34202 | 95511-H34202 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34203 | 95511-H34203 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34204 | 95511-H34204 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34205 | 95511-H34205 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34206 | 95511-H34206 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34207 | 95511-H34207 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34208 | 95511-H34208 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34209 | 95511-H34209 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34210 | 95511-H34210 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34211 | 95511-H34211 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34212 | 95511-H34212 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34213 | 95511-H34213 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34214 | 95511-H34214 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34215 | 95511-H34215 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34216 | 95511-H34216 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34217 | 95511-H34217 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34218 | 95511-H34218 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34219 | 95511-H34219 | \$ | 58.00 | 6% | <i>\$54.93</i> |
| PW NBD ONSITE H34220 | 95511-H34220 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34221 | 95511-H34221 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34222 | 95511-H34222 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34223 | 95511-H34223 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34224 | 95511-H34224 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34225 | 95511-H34225 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34226 | 95511-H34226 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34227 | 95511-H34227 | \$ | 75.00 | 6% | <i>\$71.03</i> |
| PW NBD ONSITE H34228 | 95511-H34228 | \$ | 75.00 | 6% | <i>\$71.03</i> |

| | | | | |
|----------------------|--------------|----------|----|---------|
| PW NBD ONSITE H34229 | 95511-H34229 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34230 | 95511-H34230 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34231 | 95511-H34231 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34232 | 95511-H34232 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34233 | 95511-H34233 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34234 | 95511-H34234 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34235 | 95511-H34235 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34236 | 95511-H34236 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34237 | 95511-H34237 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34238 | 95511-H34238 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34239 | 95511-H34239 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34240 | 95511-H34240 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34241 | 95511-H34241 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34242 | 95511-H34242 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34243 | 95511-H34243 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34244 | 95511-H34244 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34245 | 95511-H34245 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34246 | 95511-H34246 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34247 | 95511-H34247 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34248 | 95511-H34248 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34249 | 95511-H34249 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34250 | 95511-H34250 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34251 | 95511-H34251 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34252 | 95511-H34252 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34253 | 95511-H34253 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34254 | 95511-H34254 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34255 | 95511-H34255 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34256 | 95511-H34256 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34257 | 95511-H34257 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34258 | 95511-H34258 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34259 | 95511-H34259 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34260 | 95511-H34260 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34261 | 95511-H34261 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34262 | 95511-H34262 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34263 | 95511-H34263 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34264 | 95511-H34264 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34265 | 95511-H34265 | \$ 75.00 | 6% | \$71.03 |
| PW NBD ONSITE H34266 | 95511-H34266 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34267 | 95511-H34267 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34268 | 95511-H34268 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34269 | 95511-H34269 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34270 | 95511-H34270 | \$ 52.00 | 6% | \$49.25 |

| | | | | |
|----------------------|--------------|----------|----|---------|
| PW NBD ONSITE H34271 | 95511-H34271 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34272 | 95511-H34272 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34273 | 95511-H34273 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34274 | 95511-H34274 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34275 | 95511-H34275 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34276 | 95511-H34276 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34277 | 95511-H34277 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34278 | 95511-H34278 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34279 | 95511-H34279 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34280 | 95511-H34280 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34281 | 95511-H34281 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34282 | 95511-H34282 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34283 | 95511-H34283 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34284 | 95511-H34284 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34285 | 95511-H34285 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34286 | 95511-H34286 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34287 | 95511-H34287 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34288 | 95511-H34288 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34289 | 95511-H34289 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34290 | 95511-H34290 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34291 | 95511-H34291 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34292 | 95511-H34292 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34293 | 95511-H34293 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34294 | 95511-H34294 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34295 | 95511-H34295 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34296 | 95511-H34296 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34297 | 95511-H34297 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34298 | 95511-H34298 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34299 | 95511-H34299 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34300 | 95511-H34300 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34301 | 95511-H34301 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34302 | 95511-H34302 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34303 | 95511-H34303 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34304 | 95511-H34304 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34305 | 95511-H34305 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H34306 | 95511-H34306 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34307 | 95511-H34307 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34308 | 95511-H34308 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34309 | 95511-H34309 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34310 | 95511-H34310 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34311 | 95511-H34311 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34312 | 95511-H34312 | \$ 84.00 | 6% | \$79.55 |

| | | | | |
|----------------------|--------------|----------|----|---------|
| PW NBD ONSITE H34313 | 95511-H34313 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34314 | 95511-H34314 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34315 | 95511-H34315 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34316 | 95511-H34316 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34317 | 95511-H34317 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34318 | 95511-H34318 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34319 | 95511-H34319 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34320 | 95511-H34320 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34321 | 95511-H34321 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34322 | 95511-H34322 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34323 | 95511-H34323 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34324 | 95511-H34324 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34325 | 95511-H34325 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34326 | 95511-H34326 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34327 | 95511-H34327 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34328 | 95511-H34328 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34329 | 95511-H34329 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34330 | 95511-H34330 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34331 | 95511-H34331 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34332 | 95511-H34332 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34333 | 95511-H34333 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34334 | 95511-H34334 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34335 | 95511-H34335 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34336 | 95511-H34336 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34337 | 95511-H34337 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34338 | 95511-H34338 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34339 | 95511-H34339 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34340 | 95511-H34340 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34341 | 95511-H34341 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34342 | 95511-H34342 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34343 | 95511-H34343 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34344 | 95511-H34344 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34345 | 95511-H34345 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34346 | 95511-H34346 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34347 | 95511-H34347 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34348 | 95511-H34348 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34349 | 95511-H34349 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34350 | 95511-H34350 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34351 | 95511-H34351 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34352 | 95511-H34352 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34353 | 95511-H34353 | \$ 84.00 | 6% | \$79.55 |
| PW NBD ONSITE H34354 | 95511-H34354 | \$ 84.00 | 6% | \$79.55 |

| | | | | |
|----------------------|--------------|-----------|----|-----------------|
| PW NBD ONSITE H34355 | 95511-H34355 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PW NBD ONSITE H34403 | 95511-H34403 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34404 | 95511-H34404 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34405 | 95511-H34405 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34406 | 95511-H34406 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34407 | 95511-H34407 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34408 | 95511-H34408 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34409 | 95511-H34409 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34410 | 95511-H34410 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34411 | 95511-H34411 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34412 | 95511-H34412 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34413 | 95511-H34413 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34414 | 95511-H34414 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34415 | 95511-H34415 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34416 | 95511-H34416 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34417 | 95511-H34417 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34418 | 95511-H34418 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34419 | 95511-H34419 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34420 | 95511-H34420 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34421 | 95511-H34421 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34422 | 95511-H34422 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34423 | 95511-H34423 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34424 | 95511-H34424 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34425 | 95511-H34425 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34426 | 95511-H34426 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34427 | 95511-H34427 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34428 | 95511-H34428 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34429 | 95511-H34429 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34430 | 95511-H34430 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34431 | 95511-H34431 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34432 | 95511-H34432 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34433 | 95511-H34433 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34434 | 95511-H34434 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34435 | 95511-H34435 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34436 | 95511-H34436 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34437 | 95511-H34437 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34438 | 95511-H34438 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34439 | 95511-H34439 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34440 | 95511-H34440 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34441 | 95511-H34441 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34442 | 95511-H34442 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34443 | 95511-H34443 | \$ 199.00 | 6% | <i>\$188.46</i> |

| | | | | |
|----------------------|--------------|-----------|----|-----------------|
| PW NBD ONSITE H34444 | 95511-H34444 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34445 | 95511-H34445 | \$ 199.00 | 6% | <i>\$188.46</i> |
| PW NBD ONSITE H34446 | 95511-H34446 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34447 | 95511-H34447 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34448 | 95511-H34448 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34449 | 95511-H34449 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34450 | 95511-H34450 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34451 | 95511-H34451 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34452 | 95511-H34452 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34453 | 95511-H34453 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34454 | 95511-H34454 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34455 | 95511-H34455 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34456 | 95511-H34456 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34457 | 95511-H34457 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34458 | 95511-H34458 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34459 | 95511-H34459 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34460 | 95511-H34460 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34461 | 95511-H34461 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34462 | 95511-H34462 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34463 | 95511-H34463 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34464 | 95511-H34464 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34465 | 95511-H34465 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34466 | 95511-H34466 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34467 | 95511-H34467 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34468 | 95511-H34468 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34469 | 95511-H34469 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34470 | 95511-H34470 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34471 | 95511-H34471 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34472 | 95511-H34472 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34473 | 95511-H34473 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34474 | 95511-H34474 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34475 | 95511-H34475 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34476 | 95511-H34476 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34477 | 95511-H34477 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34478 | 95511-H34478 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34479 | 95511-H34479 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34480 | 95511-H34480 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34481 | 95511-H34481 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34482 | 95511-H34482 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34483 | 95511-H34483 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34484 | 95511-H34484 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34485 | 95511-H34485 | \$ 234.00 | 6% | <i>\$221.61</i> |

| | | | | |
|----------------------|--------------|-----------|----|-----------------|
| PW NBD ONSITE H34486 | 95511-H34486 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34487 | 95511-H34487 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34488 | 95511-H34488 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34489 | 95511-H34489 | \$ 234.00 | 6% | <i>\$221.61</i> |
| PW NBD ONSITE H34490 | 95511-H34490 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34491 | 95511-H34491 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34492 | 95511-H34492 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34493 | 95511-H34493 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34494 | 95511-H34494 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34495 | 95511-H34495 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34496 | 95511-H34496 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34497 | 95511-H34497 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34498 | 95511-H34498 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34499 | 95511-H34499 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34500 | 95511-H34500 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34501 | 95511-H34501 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34502 | 95511-H34502 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34503 | 95511-H34503 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34504 | 95511-H34504 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34505 | 95511-H34505 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34506 | 95511-H34506 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34507 | 95511-H34507 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34508 | 95511-H34508 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34509 | 95511-H34509 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34510 | 95511-H34510 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34511 | 95511-H34511 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34512 | 95511-H34512 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34513 | 95511-H34513 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34514 | 95511-H34514 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34515 | 95511-H34515 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34516 | 95511-H34516 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34517 | 95511-H34517 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34518 | 95511-H34518 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34519 | 95511-H34519 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34520 | 95511-H34520 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34521 | 95511-H34521 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34522 | 95511-H34522 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34523 | 95511-H34523 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34524 | 95511-H34524 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34525 | 95511-H34525 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34526 | 95511-H34526 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PW NBD ONSITE H34527 | 95511-H34527 | \$ 32.00 | 6% | <i>\$30.31</i> |

| | | | | |
|----------------------|--------------|----------|----|---------|
| PW NBD ONSITE H34528 | 95511-H34528 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34529 | 95511-H34529 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34530 | 95511-H34530 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34531 | 95511-H34531 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34532 | 95511-H34532 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34533 | 95511-H34533 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34534 | 95511-H34534 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34535 | 95511-H34535 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34536 | 95511-H34536 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34537 | 95511-H34537 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34538 | 95511-H34538 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34539 | 95511-H34539 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34540 | 95511-H34540 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34541 | 95511-H34541 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34542 | 95511-H34542 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34543 | 95511-H34543 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34544 | 95511-H34544 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34545 | 95511-H34545 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34546 | 95511-H34546 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34547 | 95511-H34547 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34548 | 95511-H34548 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34549 | 95511-H34549 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34550 | 95511-H34550 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34551 | 95511-H34551 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34552 | 95511-H34552 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34553 | 95511-H34553 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34554 | 95511-H34554 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34555 | 95511-H34555 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34556 | 95511-H34556 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34557 | 95511-H34557 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34558 | 95511-H34558 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34559 | 95511-H34559 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34560 | 95511-H34560 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34561 | 95511-H34561 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34562 | 95511-H34562 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34563 | 95511-H34563 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34564 | 95511-H34564 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34565 | 95511-H34565 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34566 | 95511-H34566 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34567 | 95511-H34567 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34568 | 95511-H34568 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34569 | 95511-H34569 | \$ 32.00 | 6% | \$30.31 |

| | | | | |
|----------------------|--------------|----------|----|---------|
| PW NBD ONSITE H34570 | 95511-H34570 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34571 | 95511-H34571 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34572 | 95511-H34572 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34573 | 95511-H34573 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34574 | 95511-H34574 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34575 | 95511-H34575 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34576 | 95511-H34576 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34577 | 95511-H34577 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34578 | 95511-H34578 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34579 | 95511-H34579 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34580 | 95511-H34580 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34581 | 95511-H34581 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34582 | 95511-H34582 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34583 | 95511-H34583 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34584 | 95511-H34584 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34585 | 95511-H34585 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34586 | 95511-H34586 | \$ 32.00 | 6% | \$30.31 |
| PW NBD ONSITE H34587 | 95511-H34587 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34588 | 95511-H34588 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34589 | 95511-H34589 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34590 | 95511-H34590 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34591 | 95511-H34591 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34592 | 95511-H34592 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34593 | 95511-H34593 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34594 | 95511-H34594 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34595 | 95511-H34595 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34596 | 95511-H34596 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34597 | 95511-H34597 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34598 | 95511-H34598 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34599 | 95511-H34599 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34600 | 95511-H34600 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34601 | 95511-H34601 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34602 | 95511-H34602 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34603 | 95511-H34603 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34604 | 95511-H34604 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34605 | 95511-H34605 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34606 | 95511-H34606 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34607 | 95511-H34607 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34608 | 95511-H34608 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34609 | 95511-H34609 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34610 | 95511-H34610 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34611 | 95511-H34611 | \$ 90.00 | 6% | \$85.23 |

| | | | | |
|----------------------|--------------|----------|----|---------|
| PW NBD ONSITE H34612 | 95511-H34612 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34613 | 95511-H34613 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34614 | 95511-H34614 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34615 | 95511-H34615 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34616 | 95511-H34616 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34617 | 95511-H34617 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34618 | 95511-H34618 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34619 | 95511-H34619 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34620 | 95511-H34620 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34621 | 95511-H34621 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34622 | 95511-H34622 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34623 | 95511-H34623 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34624 | 95511-H34624 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34625 | 95511-H34625 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34626 | 95511-H34626 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34627 | 95511-H34627 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34628 | 95511-H34628 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34629 | 95511-H34629 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34630 | 95511-H34630 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34631 | 95511-H34631 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H34632 | 95511-H34632 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34633 | 95511-H34633 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34634 | 95511-H34634 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34635 | 95511-H34635 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34636 | 95511-H34636 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34637 | 95511-H34637 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34638 | 95511-H34638 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34639 | 95511-H34639 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34640 | 95511-H34640 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34641 | 95511-H34641 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34642 | 95511-H34642 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34643 | 95511-H34643 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34644 | 95511-H34644 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34645 | 95511-H34645 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34646 | 95511-H34646 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34647 | 95511-H34647 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34648 | 95511-H34648 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34649 | 95511-H34649 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34650 | 95511-H34650 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34651 | 95511-H34651 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34652 | 95511-H34652 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34653 | 95511-H34653 | \$ 96.00 | 6% | \$90.92 |

| | | | | |
|----------------------|--------------|-------------|----|------------|
| PW NBD ONSITE H34654 | 95511-H34654 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34655 | 95511-H34655 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34656 | 95511-H34656 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34657 | 95511-H34657 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34658 | 95511-H34658 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34659 | 95511-H34659 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34660 | 95511-H34660 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34661 | 95511-H34661 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34662 | 95511-H34662 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34663 | 95511-H34663 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34664 | 95511-H34664 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34665 | 95511-H34665 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34666 | 95511-H34666 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34667 | 95511-H34667 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34668 | 95511-H34668 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34669 | 95511-H34669 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34670 | 95511-H34670 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34671 | 95511-H34671 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34672 | 95511-H34672 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34673 | 95511-H34673 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34674 | 95511-H34674 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34675 | 95511-H34675 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34676 | 95511-H34676 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34677 | 95511-H34677 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34678 | 95511-H34678 | \$ 96.00 | 6% | \$90.92 |
| PW NBD ONSITE H34726 | 95511-H34726 | \$ 2,339.00 | 6% | \$2,215.15 |
| PW NBD ONSITE H34727 | 95511-H34727 | \$ 2,339.00 | 6% | \$2,215.15 |
| PW NBD ONSITE H34728 | 95511-H34728 | \$ 2,339.00 | 6% | \$2,215.15 |
| PW NBD ONSITE H34729 | 95511-H34729 | \$ 2,339.00 | 6% | \$2,215.15 |
| PW NBD ONSITE H34730 | 95511-H34730 | \$ 2,517.00 | 6% | \$2,383.72 |
| PW NBD ONSITE H34731 | 95511-H34731 | \$ 2,517.00 | 6% | \$2,383.72 |
| PW NBD ONSITE H34732 | 95511-H34732 | \$ 2,517.00 | 6% | \$2,383.72 |
| PW NBD ONSITE H34733 | 95511-H34733 | \$ 2,517.00 | 6% | \$2,383.72 |
| PW NBD ONSITE H34734 | 95511-H34734 | \$ 365.00 | 6% | \$345.67 |
| PW NBD ONSITE H34735 | 95511-H34735 | \$ 365.00 | 6% | \$345.67 |
| PW NBD ONSITE H34736 | 95511-H34736 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H34737 | 95511-H34737 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H34738 | 95511-H34738 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34739 | 95511-H34739 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34740 | 95511-H34740 | \$ 365.00 | 6% | \$345.67 |
| PW NBD ONSITE H34741 | 95511-H34741 | \$ 365.00 | 6% | \$345.67 |
| PW NBD ONSITE H34742 | 95511-H34742 | \$ 369.00 | 6% | \$349.46 |

| | | | | |
|----------------------|--------------|--------------|----|-------------|
| PW NBD ONSITE H34743 | 95511-H34743 | \$ 369.00 | 6% | \$349.46 |
| PW NBD ONSITE H34744 | 95511-H34744 | \$ 462.00 | 6% | \$437.54 |
| PW NBD ONSITE H34745 | 95511-H34745 | \$ 462.00 | 6% | \$437.54 |
| PW NBD ONSITE H34746 | 95511-H34746 | \$ 524.00 | 6% | \$496.25 |
| PW NBD ONSITE H34747 | 95511-H34747 | \$ 524.00 | 6% | \$496.25 |
| PW NBD ONSITE H34748 | 95511-H34748 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34749 | 95511-H34749 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34750 | 95511-H34750 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34751 | 95511-H34751 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34752 | 95511-H34752 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34753 | 95511-H34753 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34754 | 95511-H34754 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34755 | 95511-H34755 | \$ 872.00 | 6% | \$825.83 |
| PW NBD ONSITE H34756 | 95511-H34756 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H34757 | 95511-H34757 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H34758 | 95511-H34758 | \$ 462.00 | 6% | \$437.54 |
| PW NBD ONSITE H34759 | 95511-H34759 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H34760 | 95511-H34760 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H34761 | 95511-H34761 | \$ 462.00 | 6% | \$437.54 |
| PW NBD ONSITE H34839 | 95511-H34839 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34840 | 95511-H34840 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34841 | 95511-H34841 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34842 | 95511-H34842 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34843 | 95511-H34843 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34844 | 95511-H34844 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34845 | 95511-H34845 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34846 | 95511-H34846 | \$ 233.00 | 6% | \$220.66 |
| PW NBD ONSITE H34993 | 95511-H34993 | \$ 11,186.00 | 6% | \$10,593.70 |
| PW NBD ONSITE H34994 | 95511-H34994 | \$ 11,186.00 | 6% | \$10,593.70 |
| PW NBD ONSITE H34996 | 95511-H34996 | \$ 11,186.00 | 6% | \$10,593.70 |
| PW NBD ONSITE H34997 | 95511-H34997 | \$ 11,186.00 | 6% | \$10,593.70 |
| PW NBD ONSITE H35005 | 95511-H35005 | \$ 8,341.00 | 6% | \$7,899.34 |
| PW NBD ONSITE H35006 | 95511-H35006 | \$ 8,341.00 | 6% | \$7,899.34 |
| PW NBD ONSITE H35012 | 95511-H35012 | \$ 5,023.00 | 6% | \$4,757.03 |
| PW NBD ONSITE H35070 | 95511-H35070 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35071 | 95511-H35071 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35072 | 95511-H35072 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35073 | 95511-H35073 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35074 | 95511-H35074 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35075 | 95511-H35075 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35076 | 95511-H35076 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35077 | 95511-H35077 | \$ 52.00 | 6% | \$49.25 |

| | | | | |
|----------------------|--------------|--------------|----|------------|
| PW NBD ONSITE H35078 | 95511-H35078 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35079 | 95511-H35079 | \$ 52.00 | 6% | \$49.25 |
| PW NBD ONSITE H35080 | 95511-H35080 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H35081 | 95511-H35081 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H35082 | 95511-H35082 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H35083 | 95511-H35083 | \$ 90.00 | 6% | \$85.23 |
| PW NBD ONSITE H35092 | 95511-H35092 | \$ 547.00 | 6% | \$518.04 |
| PW NBD ONSITE H35093 | 95511-H35093 | \$ 8,570.00 | 6% | \$8,116.22 |
| PW NBD ONSITE H35094 | 95511-H35094 | \$ 4,753.00 | 6% | \$4,501.33 |
| PW NBD ONSITE H35270 | 95511-H35270 | \$ 374.00 | 6% | \$354.20 |
| PW NBD ONSITE H35271 | 95511-H35271 | \$ 282.00 | 6% | \$267.07 |
| PW NBD ONSITE H35272 | 95511-H35272 | \$ 320.00 | 6% | \$303.06 |
| PW NBD ONSITE H35273 | 95511-H35273 | \$ 320.00 | 6% | \$303.06 |
| PW NBD ONSITE H35274 | 95511-H35274 | \$ 527.00 | 6% | \$499.10 |
| PW NBD ONSITE H35275 | 95511-H35275 | \$ 406.00 | 6% | \$384.50 |
| PW NBD ONSITE H35276 | 95511-H35276 | \$ 2,248.00 | 6% | \$2,128.97 |
| PW NBD ONSITE H35277 | 95511-H35277 | \$ 2,697.00 | 6% | \$2,554.19 |
| PW NBD ONSITE H35278 | 95511-H35278 | \$ 2,780.00 | 6% | \$2,632.80 |
| PW NBD ONSITE H35279 | 95511-H35279 | \$ 3,104.00 | 6% | \$2,939.64 |
| PW NBD ONSITE H35280 | 95511-H35280 | \$ 2,960.00 | 6% | \$2,803.27 |
| PW NBD ONSITE H35281 | 95511-H35281 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35282 | 95511-H35282 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35283 | 95511-H35283 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35284 | 95511-H35284 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35285 | 95511-H35285 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35286 | 95511-H35286 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35287 | 95511-H35287 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35288 | 95511-H35288 | \$ 1,553.00 | 6% | \$1,470.77 |
| PW NBD ONSITE H35289 | 95511-H35289 | \$ 3,879.00 | 6% | \$3,673.61 |
| PW NBD ONSITE H35291 | 95511-H35291 | \$ 2,936.00 | 6% | \$2,780.54 |
| PW NBD ONSITE H35292 | 95511-H35292 | \$ 2,780.00 | 6% | \$2,632.80 |
| PW NBD ONSITE H35293 | 95511-H35293 | \$ 3,104.00 | 6% | \$2,939.64 |
| PW NBD ONSITE H35295 | 95511-H35295 | \$ 332.00 | 6% | \$314.42 |
| PW NBD ONSITE H35296 | 95511-H35296 | \$ 6,373.00 | 6% | \$6,035.55 |
| PW NBD ONSITE H35297 | 95511-H35297 | \$ 6,372.00 | 6% | \$6,034.60 |
| PW NBD ONSITE H35298 | 95511-H35298 | \$ 10,238.00 | 6% | \$9,695.90 |
| PW NBD ONSITE H35299 | 95511-H35299 | \$ 10,238.00 | 6% | \$9,695.90 |
| PW NBD ONSITE H35302 | 95511-H35302 | \$ 2,471.00 | 6% | \$2,340.16 |
| PW NBD ONSITE H35303 | 95511-H35303 | \$ 2,471.00 | 6% | \$2,340.16 |
| PW NBD ONSITE H35304 | 95511-H35304 | \$ 2,471.00 | 6% | \$2,340.16 |
| PW NBD ONSITE H35305 | 95511-H35305 | \$ 2,586.00 | 6% | \$2,449.07 |
| PW NBD ONSITE H35306 | 95511-H35306 | \$ 2,586.00 | 6% | \$2,449.07 |

| | | | | |
|----------------------|--------------|-------------|----|------------|
| PW NBD ONSITE H35307 | 95511-H35307 | \$ 2,586.00 | 6% | \$2,449.07 |
| PW NBD ONSITE H35309 | 95511-H35309 | \$ 3,177.00 | 6% | \$3,008.78 |
| PW NBD ONSITE H35310 | 95511-H35310 | \$ 3,177.00 | 6% | \$3,008.78 |
| PW NBD ONSITE H35311 | 95511-H35311 | \$ 3,177.00 | 6% | \$3,008.78 |
| PW NBD ONSITE H35312 | 95511-H35312 | \$ 2,626.00 | 6% | \$2,486.95 |
| PW NBD ONSITE H35313 | 95511-H35313 | \$ 2,625.00 | 6% | \$2,486.01 |
| PW NBD ONSITE H35314 | 95511-H35314 | \$ 2,625.00 | 6% | \$2,486.01 |
| PW NBD ONSITE H35315 | 95511-H35315 | \$ 1,120.00 | 6% | \$1,060.70 |
| PW NBD ONSITE H35318 | 95511-H35318 | \$ 541.00 | 6% | \$512.35 |
| PW NBD ONSITE H35319 | 95511-H35319 | \$ 713.00 | 6% | \$675.25 |
| PW NBD ONSITE H35320 | 95511-H35320 | \$ 755.00 | 6% | \$715.02 |
| PW NBD ONSITE H35321 | 95511-H35321 | \$ 942.00 | 6% | \$892.12 |
| PW NBD ONSITE H35322 | 95511-H35322 | \$ 1,144.00 | 6% | \$1,083.43 |
| PW NBD ONSITE H35323 | 95511-H35323 | \$ 1,120.00 | 6% | \$1,060.70 |
| PW NBD ONSITE H35328 | 95511-H35328 | \$ 97.00 | 6% | \$91.86 |
| PW NBD ONSITE H35330 | 95511-H35330 | \$ 97.00 | 6% | \$91.86 |
| PW NBD ONSITE H35340 | 95511-H35340 | \$ 2,672.00 | 6% | \$2,530.52 |
| PW NBD ONSITE H35341 | 95511-H35341 | \$ 2,672.00 | 6% | \$2,530.52 |
| PW NBD ONSITE H35342 | 95511-H35342 | \$ 2,361.00 | 6% | \$2,235.99 |
| PW NBD ONSITE H35343 | 95511-H35343 | \$ 2,672.00 | 6% | \$2,530.52 |
| PW NBD ONSITE H35344 | 95511-H35344 | \$ 2,789.00 | 6% | \$2,641.32 |
| PW NBD ONSITE H35345 | 95511-H35345 | \$ 2,789.00 | 6% | \$2,641.32 |
| PW NBD ONSITE H35346 | 95511-H35346 | \$ 2,449.00 | 6% | \$2,319.33 |
| PW NBD ONSITE H35347 | 95511-H35347 | \$ 2,789.00 | 6% | \$2,641.32 |
| PW NBD ONSITE H35349 | 95511-H35349 | \$ 3,070.00 | 6% | \$2,907.44 |
| PW NBD ONSITE H35350 | 95511-H35350 | \$ 3,070.00 | 6% | \$2,907.44 |
| PW NBD ONSITE H35351 | 95511-H35351 | \$ 2,678.00 | 6% | \$2,536.20 |
| PW NBD ONSITE H35352 | 95511-H35352 | \$ 3,070.00 | 6% | \$2,907.44 |
| PW NBD ONSITE H35359 | 95511-H35359 | \$ 942.00 | 6% | \$892.12 |
| PW NBD ONSITE H35360 | 95511-H35360 | \$ 1,144.00 | 6% | \$1,083.43 |
| PW NBD ONSITE H35361 | 95511-H35361 | \$ 1,120.00 | 6% | \$1,060.70 |
| PW NBD ONSITE H35362 | 95511-H35362 | \$ 541.00 | 6% | \$512.35 |
| PW NBD ONSITE H35366 | 95511-H35366 | \$ 1,346.00 | 6% | \$1,274.73 |
| PW NBD ONSITE H35367 | 95511-H35367 | \$ 1,567.00 | 6% | \$1,484.03 |
| PW NBD ONSITE H35368 | 95511-H35368 | \$ 2,390.00 | 6% | \$2,263.45 |
| PW NBD ONSITE H35369 | 95511-H35369 | \$ 780.00 | 6% | \$738.70 |
| PW NBD ONSITE H35370 | 95511-H35370 | \$ 1,092.00 | 6% | \$1,034.18 |
| PW NBD ONSITE H35375 | 95511-H35375 | \$ 655.00 | 6% | \$620.32 |
| PW NBD ONSITE H35376 | 95511-H35376 | \$ 986.00 | 6% | \$933.79 |
| PW NBD ONSITE H35377 | 95511-H35377 | \$ 413.00 | 6% | \$391.13 |
| PW NBD ONSITE H35378 | 95511-H35378 | \$ 655.00 | 6% | \$620.32 |
| PW NBD ONSITE H35379 | 95511-H35379 | \$ 413.00 | 6% | \$391.13 |

| | | | | |
|----------------------|--------------|-------------|----|------------|
| PW NBD ONSITE H35380 | 95511-H35380 | \$ 737.00 | 6% | \$697.98 |
| PW NBD ONSITE H35381 | 95511-H35381 | \$ 904.00 | 6% | \$856.13 |
| PW NBD ONSITE H35384 | 95511-H35384 | \$ 299.00 | 6% | \$283.17 |
| PW NBD ONSITE H35385 | 95511-H35385 | \$ 395.00 | 6% | \$374.08 |
| PW NBD ONSITE H35386 | 95511-H35386 | \$ 655.00 | 6% | \$620.32 |
| PW NBD ONSITE H35387 | 95511-H35387 | \$ 613.00 | 6% | \$580.54 |
| PW NBD ONSITE H35388 | 95511-H35388 | \$ 453.00 | 6% | \$429.01 |
| PW NBD ONSITE H35389 | 95511-H35389 | \$ 256.00 | 6% | \$242.44 |
| PW NBD ONSITE H35390 | 95511-H35390 | \$ 221.00 | 6% | \$209.30 |
| PW NBD ONSITE H35391 | 95511-H35391 | \$ 482.00 | 6% | \$456.48 |
| PW NBD ONSITE H35392 | 95511-H35392 | \$ 737.00 | 6% | \$697.98 |
| PW NBD ONSITE H35393 | 95511-H35393 | \$ 986.00 | 6% | \$933.79 |
| PW NBD ONSITE H35394 | 95511-H35394 | \$ 179.00 | 6% | \$169.52 |
| PW NBD ONSITE H35395 | 95511-H35395 | \$ 152.00 | 6% | \$143.95 |
| PW NBD ONSITE H35396 | 95511-H35396 | \$ 179.00 | 6% | \$169.52 |
| PW NBD ONSITE H35397 | 95511-H35397 | \$ 152.00 | 6% | \$143.95 |
| PW NBD ONSITE H35398 | 95511-H35398 | \$ 458.00 | 6% | \$433.75 |
| PW NBD ONSITE H35399 | 95511-H35399 | \$ 560.00 | 6% | \$530.35 |
| PW NBD ONSITE H35400 | 95511-H35400 | \$ 616.00 | 6% | \$583.38 |
| PW NBD ONSITE H35401 | 95511-H35401 | \$ 331.00 | 6% | \$313.47 |
| PW NBD ONSITE H35415 | 95511-H35415 | \$ 227.00 | 6% | \$214.98 |
| PW NBD ONSITE H35416 | 95511-H35416 | \$ 227.00 | 6% | \$214.98 |
| PW NBD ONSITE H35426 | 95511-H35426 | \$ 256.00 | 6% | \$242.44 |
| PW NBD ONSITE H35427 | 95511-H35427 | \$ 613.00 | 6% | \$580.54 |
| PW NBD ONSITE H35428 | 95511-H35428 | \$ 221.00 | 6% | \$209.30 |
| PW NBD ONSITE H35429 | 95511-H35429 | \$ 482.00 | 6% | \$456.48 |
| PW NBD ONSITE H35430 | 95511-H35430 | \$ 355.00 | 6% | \$336.20 |
| PW NBD ONSITE H35431 | 95511-H35431 | \$ 355.00 | 6% | \$336.20 |
| PW NBD ONSITE H35432 | 95511-H35432 | \$ 369.00 | 6% | \$349.46 |
| PW NBD ONSITE H35433 | 95511-H35433 | \$ 450.00 | 6% | \$426.17 |
| PW NBD ONSITE H35434 | 95511-H35434 | \$ 511.00 | 6% | \$483.94 |
| PW NBD ONSITE H35435 | 95511-H35435 | \$ 511.00 | 6% | \$483.94 |
| PW NBD ONSITE H35436 | 95511-H35436 | \$ 846.00 | 6% | \$801.20 |
| PW NBD ONSITE H35437 | 95511-H35437 | \$ 846.00 | 6% | \$801.20 |
| PW NBD ONSITE H35438 | 95511-H35438 | \$ 846.00 | 6% | \$801.20 |
| PW NBD ONSITE H35439 | 95511-H35439 | \$ 846.00 | 6% | \$801.20 |
| PW NBD ONSITE H35440 | 95511-H35440 | \$ 450.00 | 6% | \$426.17 |
| PW NBD ONSITE H35441 | 95511-H35441 | \$ 450.00 | 6% | \$426.17 |
| PW NBD ONSITE H35442 | 95511-H35442 | \$ 450.00 | 6% | \$426.17 |
| PW NBD ONSITE H35443 | 95511-H35443 | \$ 2,339.00 | 6% | \$2,215.15 |
| PW NBD ONSITE H35444 | 95511-H35444 | \$ 2,517.00 | 6% | \$2,383.72 |
| PW NBD ONSITE H35445 | 95511-H35445 | \$ 2,248.00 | 6% | \$2,128.97 |

| | | | | |
|---------------------------------|-------------------------|-------------|----|------------|
| PW NBD ONSITE H35446 | 95511-H35446 | \$ 2,205.00 | 6% | \$2,088.25 |
| PW NBD ONSITE H35447 | 95511-H35447 | \$ 2,556.00 | 6% | \$2,420.66 |
| PW NBD ONSITE H35448 | 95511-H35448 | \$ 2,450.00 | 6% | \$2,320.27 |
| PW NBD ONSITE H35449 | 95511-H35449 | \$ 2,780.00 | 6% | \$2,632.80 |
| PW NBD ONSITE H35450 | 95511-H35450 | \$ 2,942.00 | 6% | \$2,786.22 |
| PW NBD ONSITE H35451 | 95511-H35451 | \$ 3,133.00 | 6% | \$2,967.11 |
| PW NBD ONSITE H35452 | 95511-H35452 | \$ 3,133.00 | 6% | \$2,967.11 |
| PW NBD ONSITE H35453 | 95511-H35453 | \$ 2,517.00 | 6% | \$2,383.72 |
| PW NBD ONSITE H35454 | 95511-H35454 | \$ 2,339.00 | 6% | \$2,215.15 |
| PW NBD ONSITE H35455 | 95511-H35455 | \$ 755.00 | 6% | \$715.02 |
| PW NBD ONSITE H35456 | 95511-H35456 | \$ 950.00 | 6% | \$899.70 |
| PW NBD ONSITE H35457 | 95511-H35457 | \$ 850.00 | 6% | \$804.99 |
| PW NBD ONSITE H35458 | 95511-H35458 | \$ 932.00 | 6% | \$882.65 |
| PW NBD ONSITE H35471 | 95511-H35471 | \$ 755.00 | 6% | \$715.02 |
| PW NBD ONSITE H35600 | 95511-H35600 | \$ 320.00 | 6% | \$303.06 |
| PW NBD ONSITE H35601 | 95511-H35601 | \$ 320.00 | 6% | \$303.06 |
| PW NBD ONSITE H35602 | 95511-H35602 | \$ 365.00 | 6% | \$345.67 |
| PW NBD ONSITE H35603 | 95511-H35603 | \$ 365.00 | 6% | \$345.67 |
| PW NBD ONSITE H35604 | 95511-H35604 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H35605 | 95511-H35605 | \$ 464.00 | 6% | \$439.43 |
| PW NBD ONSITE H35606 | 95511-H35606 | \$ 527.00 | 6% | \$499.10 |
| PW NBD ONSITE H35607 | 95511-H35607 | \$ 524.00 | 6% | \$496.25 |
| PW NBD ONSITE ISW-24W-4X | 95511-ISW-24W-4X | \$ 794.00 | 6% | \$751.96 |
| PW NBD ONSITE ISW-4W-4WS-4X | 95511-ISW-4W-4WS-4X | \$ 504.00 | 6% | \$477.31 |
| PW NBD ONSITE BD MSM128 | 95511-MSM128 | \$ 2,907.00 | 6% | \$2,753.07 |
| PW NBD ONSITE BD MSM48C | 95511-MSM48C | \$ 1,725.00 | 6% | \$1,633.66 |
| PW NBD ONSITE SLX9150-48XT-DC-F | 95511-SLX9150-48XT-DC-F | \$ 2,432.00 | 6% | \$2,303.23 |
| PW NBD ONSITE SLX9150-48XT-DC-R | 95511-SLX9150-48XT-DC-R | \$ 2,655.00 | 6% | \$2,514.42 |
| PW NBD ONSITE SLX9150-48Y-DC-F | 95511-SLX9150-48Y-DC-F | \$ 2,330.00 | 6% | \$2,206.63 |
| PW NBD ONSITE SLX9150-48Y-DC-R | 95511-SLX9150-48Y-DC-R | \$ 2,544.00 | 6% | \$2,409.30 |

| | | | | |
|---------------------------------|------------------------|--------------|----|--------------------|
| PW NBD ONSITE SLX9740-40C | 95511-SLX9740-40C | \$ 10,458.00 | 6% | <i>\$9,904.25</i> |
| PW NBD ONSITE SLX9740-40C-AC-F | 95511-SLX9740-40C-AC-F | \$ 10,458.00 | 6% | <i>\$9,904.25</i> |
| PW NBD ONSITE SLX9740-40C-AC-R | 95511-SLX9740-40C-AC-R | \$ 10,458.00 | 6% | <i>\$9,904.25</i> |
| PW NBD ONSITE SLX9740-40C-DC-F | 95511-SLX9740-40C-DC-F | \$ 10,458.00 | 6% | <i>\$9,904.25</i> |
| PW NBD ONSITE SLX9740-80C | 95511-SLX9740-80C | \$ 19,667.00 | 6% | <i>\$18,625.63</i> |
| PW NBD ONSITE SLX9740-80C-AC-F | 95511-SLX9740-80C-AC-F | \$ 19,667.00 | 6% | <i>\$18,625.63</i> |
| PW NBD ONSITE SLX9740-80C-AC-R | 95511-SLX9740-80C-AC-R | \$ 19,667.00 | 6% | <i>\$18,625.63</i> |
| PW NBD ONSITE SLX9740-80C-DC-F | 95511-SLX9740-80C-DC-F | \$ 19,667.00 | 6% | <i>\$18,625.63</i> |
| PW NBD ONSITE V300-8P-2X | 95511-V300-8P-2X | \$ 127.00 | 6% | <i>\$120.28</i> |
| PW NBD ONSITE V300-8T-2X | 95511-V300-8T-2X | \$ 88.00 | 6% | <i>\$83.34</i> |
| PW NBD ONSITE V300HT-8P-2X | 95511-V300HT-8P-2X | \$ 420.00 | 6% | <i>\$397.76</i> |
| PW NBD ONSITE V300HT-8T-2X | 95511-V300HT-8T-2X | \$ 251.00 | 6% | <i>\$237.71</i> |
| PW NBD ONSITE Summit VIM-SS | 95511-VIM-SS | \$ 145.00 | 6% | <i>\$137.32</i> |
| PW NBD ONSITE Summit VIM-SSV80 | 95511-VIM-SSV80 | \$ 270.00 | 6% | <i>\$255.70</i> |
| PW NBD ONSITE Summit VIM2-SS | 95511-VIM2-SS | \$ 168.00 | 6% | <i>\$159.10</i> |
| PW NBD ONSITE Summit VIM2-SS128 | 95511-VIM2-SS128 | \$ 586.00 | 6% | <i>\$554.97</i> |
| PW NBD ONSITE Summit VIM2-V80 | 95511-VIM2-V80 | \$ 626.00 | 6% | <i>\$592.85</i> |

| | | | | |
|---|---|-------------|----|-------------------|
| PW NBD ONSITE Summit VIM210G4X | 95511- VIM210G4X | \$ 1,087.00 | 6% | <i>\$1,029.44</i> |
| PW NBD ONSITE VIM5-2Q | 95511-VIM5- 2Q | \$ 182.00 | 6% | <i>\$172.36</i> |
| PW NBD ONSITE VIM5-2Y | 95511-VIM5- 2Y | \$ 216.00 | 6% | <i>\$204.56</i> |
| PW NBD ONSITE VIM5-4X | 95511-VIM5- 4X | \$ 94.00 | 6% | <i>\$89.02</i> |
| PW NBD ONSITE HVIM5-4XE | 95511-VIM5- 4XE | \$ 177.00 | 6% | <i>\$167.63</i> |
| PW NBD ONSITE VIM5-4Y | 95511-VIM5- 4Y | \$ 276.00 | 6% | <i>\$261.39</i> |
| PW NBD ONSITE VIM5-4YE | 95511-VIM5- 4YE | \$ 356.00 | 6% | <i>\$337.15</i> |
| PW NBD ONSITE VSP4900- 12MXU-12XE | 95511- VSP4900- 12MXU-12XE | \$ 988.00 | 6% | <i>\$935.69</i> |
| PW NBD ONSITE VSP4900- 12MXU-12XE-B1 | 95511- VSP4900- 12MXU-12XE- B1 | \$ 988.00 | 6% | <i>\$935.69</i> |
| PW NBD ONSITE VSP4900- 24S | 95511- VSP4900-24S | \$ 541.00 | 6% | <i>\$512.35</i> |
| PW NBD ONSITE VSP4900- 24S-B3 | 95511- VSP4900-24S- B3 | \$ 541.00 | 6% | <i>\$512.35</i> |
| PW NBD ONSITE VSP4900- 24XE | 95511- VSP4900- 24XE | \$ 988.00 | 6% | <i>\$935.69</i> |
| PW NBD ONSITE VSP4900- 24XE-B3 | 95511- VSP4900- 24XE-B3 | \$ 988.00 | 6% | <i>\$935.69</i> |
| PW NBD ONSITE X435-24P-4S | 95511-X435- 24P-4S | \$ 227.00 | 6% | <i>\$214.98</i> |
| PW NBD ONSITE X435-24T-4S | 95511-X435- 24T-4S | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW NBD ONSITE X435-8P-2T- W | 95511-X435- 8P-2T-W | \$ 125.00 | 6% | <i>\$118.38</i> |
| PW NBD ONSITE X435-8P-4S | 95511-X435- 8P-4S | \$ 114.00 | 6% | <i>\$107.96</i> |
| PW NBD ONSITE X435-8T-4S | 95511-X435- 8T-4S | \$ 91.00 | 6% | <i>\$86.18</i> |

| | | | | |
|---------------------------------|-----------------------|-------------|----|------------|
| PW NBD ONSITE Summit X460-24P | 95511-X460-24P | \$ 1,021.00 | 6% | \$966.94 |
| PW NBD ONSITE Summit X460-24T | 95511-X460-24T | \$ 721.00 | 6% | \$682.82 |
| PW NBD ONSITE Summit X460-24TDC | 95511-X460-24TDC | \$ 1,051.00 | 6% | \$995.35 |
| PW NBD ONSITE Summit X460-24X | 95511-X460-24X | \$ 1,321.00 | 6% | \$1,251.05 |
| PW NBD ONSITE Summit X460-24XDC | 95511-X460-24XDC | \$ 1,475.00 | 6% | \$1,396.90 |
| PW NBD ONSITE Summit X460-48P | 95511-X460-48P | \$ 1,321.00 | 6% | \$1,251.05 |
| PW NBD ONSITE Summit X460-48T | 95511-X460-48T | \$ 1,139.00 | 6% | \$1,078.69 |
| PW NBD ONSITE Summit X460-48TDC | 95511-X460-48TDC | \$ 1,432.00 | 6% | \$1,356.18 |
| PW NBD ONSITE Summit X460-48X | 95511-X460-48X | \$ 1,761.00 | 6% | \$1,667.76 |
| PW NBD ONSITE Summit X460-48XDC | 95511-X460-48XDC | \$ 1,718.00 | 6% | \$1,627.03 |
| PW NBD ONSITE X465-24MU | 95511-X465-24MU | \$ 1,144.00 | 6% | \$1,083.43 |
| PW NBD ONSITE X465-24S | 95511-X465-24S | \$ 541.00 | 6% | \$512.35 |
| PW NBD ONSITE X465-24S-B3 | 95511-X465-24S-B3 | \$ 541.00 | 6% | \$512.35 |
| PW NBD ONSITE X465-24W | 95511-X465-24W | \$ 541.00 | 6% | \$512.35 |
| PW NBD ONSITE X465-24XE | 95511-X465-24XE | \$ 988.00 | 6% | \$935.69 |
| PW NBD ONSITE X465-24XE-B3 | 95511-X465-24XE-B3 | \$ 988.00 | 6% | \$935.69 |
| PW NBD ONSITE X465-48P | 95511-X465-48P | \$ 755.00 | 6% | \$715.02 |
| PW NBD ONSITE X465-48T | 95511-X465-48T | \$ 713.00 | 6% | \$675.25 |
| PW NBD ONSITE X465-48W | 95511-X465-48W | \$ 942.00 | 6% | \$892.12 |
| PW NBD ONSITE X465i-48W | 95511-X465i-48W | \$ 1,120.00 | 6% | \$1,060.70 |
| PW NBD ONSITE X465i-48W-B1-S1 | 95511-X465i-48W-B1-S1 | \$ 1,120.00 | 6% | \$1,060.70 |

| | | | | |
|-------------------------------|-----------------------|-------------|----|-------------------|
| PW NBD ONSITE X465i-48W-B2-S1 | 95511-X465i-48W-B2-S1 | \$ 1,120.00 | 6% | <i>\$1,060.70</i> |
| PW NBD ONSITE Summit X480-24X | 95511-X480-24X | \$ 1,629.00 | 6% | <i>\$1,542.74</i> |
| PW NBD ONSITE Summit X480-48T | 95511-X480-48T | \$ 1,629.00 | 6% | <i>\$1,542.74</i> |
| PW NBD ONSITE Summit X480-48X | 95511-X480-48X | \$ 2,176.00 | 6% | <i>\$2,060.78</i> |
| PW NBD ONSITE X695-48Y-8C | 95511-X695-48Y-8C | \$ 2,637.00 | 6% | <i>\$2,497.37</i> |
| PW NBD ONSITE XA1440 | 95511-XA1440 | \$ 277.00 | 6% | <i>\$262.33</i> |
| PW NBD ONSITE XA1480 | 95511-XA1480 | \$ 369.00 | 6% | <i>\$349.46</i> |
| PW NBD ONSITE Summit XGM3-2SF | 95511-XGM3-2SF | \$ 270.00 | 6% | <i>\$255.70</i> |
| PW NBD ONSITE XR600 | 95511-XR600 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW NBD ON-SITE -ZR-XFP | 95511-ZR-XFP | \$ 1,642.00 | 6% | <i>\$1,555.06</i> |
| PW Managed Cloud WiFi 30912 | 95524-30912 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW Managed Cloud WiFi 30913 | 95524-30913 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW Managed Cloud WiFi 31012 | 95524-31012 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW Managed Cloud WiFi 31013 | 95524-31013 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW Managed Cloud WiFi 31014 | 95524-31014 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW Managed Cloud WiFi 31015 | 95524-31015 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PW Managed Cloud WiFi 31016 | 95524-31016 | \$ 419.00 | 6% | <i>\$396.81</i> |
| PW Managed Cloud WiFi 31017 | 95524-31017 | \$ 419.00 | 6% | <i>\$396.81</i> |
| PW Managed Cloud WiFi 31018 | 95524-31018 | \$ 490.00 | 6% | <i>\$464.05</i> |
| PW Managed Cloud WiFi 31019 | 95524-31019 | \$ 490.00 | 6% | <i>\$464.05</i> |
| PW Managed Cloud WiFi 31025 | 95524-31025 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW Managed Cloud WiFi 31026 | 95524-31026 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PW Managed Cloud WiFi 31028 | 95524-31028 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW Managed Cloud WiFi 31029 | 95524-31029 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PW Managed Cloud WiFi 31034 | 95524-31034 | \$ 273.00 | 6% | <i>\$258.54</i> |
| PW Managed Cloud WiFi 31035 | 95524-31035 | \$ 273.00 | 6% | <i>\$258.54</i> |
| PW Managed Cloud WiFi 39031 | 95524-39031 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PW Managed Cloud WiFi 39032 | 95524-39032 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PW Managed Cloud WiFi 39033 | 95524-39033 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PW Managed Cloud WiFi 39034 | 95524-39034 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PW Managed Cloud WiFi 39035 | 95524-39035 | \$ 427.00 | 6% | <i>\$404.39</i> |
| PW Managed Cloud WiFi 39036 | 95524-39036 | \$ 171.00 | 6% | <i>\$161.95</i> |
| PW Managed Cloud WiFi 39037 | 95524-39037 | \$ 171.00 | 6% | <i>\$161.95</i> |

| | | | | |
|---------------------------------|--------------|-------------|----|------------|
| PW Managed Cloud WiFi 39038 | 95524-39038 | \$ 237.00 | 6% | \$224.45 |
| PW Managed Cloud WiFi 39039 | 95524-39039 | \$ 237.00 | 6% | \$224.45 |
| PW Managed Cloud WiFi | 95524-H30632 | \$ 136.00 | 6% | \$128.80 |
| PW Managed Cloud WiFi | 95524-H30633 | \$ 136.00 | 6% | \$128.80 |
| PW Managed Cloud WiFi | 95524-H30724 | \$ 224.00 | 6% | \$212.14 |
| PW Managed Cloud WiFi | 95524-H30730 | \$ 136.00 | 6% | \$128.80 |
| PW Managed Cloud WiFi | 95524-H30731 | \$ 136.00 | 6% | \$128.80 |
| PW Managed Cloud WiFi H30738 | 95524-H30738 | \$ 94.00 | 6% | \$89.02 |
| PWP TAC OS Optics 10200 | 95600-10200 | \$ 1,181.00 | 6% | \$1,118.47 |
| PWP TAC OS Optics 10320 | 95600-10320 | \$ 1,291.00 | 6% | \$1,222.64 |
| PWP TAC OS 10330 | 95600-10330 | \$ 3,172.00 | 6% | \$3,004.04 |
| PWP TAC OS 10331 | 95600-10331 | \$ 1,461.00 | 6% | \$1,383.64 |
| PWP TAC OS 10335 | 95600-10335 | \$ 2,234.00 | 6% | \$2,115.71 |
| PWP TAC OS 10403 | 95600-10403 | \$ 2,765.00 | 6% | \$2,618.59 |
| PWP TAC OS 10404 | 95600-10404 | \$ 1,321.00 | 6% | \$1,251.05 |
| PWP TAC OS 10441 | 95600-10441 | \$ 888.00 | 6% | \$840.98 |
| PWP TAC OS 10442 | 95600-10442 | \$ 938.00 | 6% | \$888.33 |
| PWP TAC OS Summit 11011 | 95600-11011 | \$ 159.00 | 6% | \$150.58 |
| PWP TAC OS 1130C | 95600-1130C | \$ 480.00 | 6% | \$454.58 |
| PWP TAC OS E4G 16119 | 95600-16119 | \$ 164.00 | 6% | \$155.32 |
| PWP TAC OS E4G 16120 | 95600-16120 | \$ 196.00 | 6% | \$185.62 |
| PWP TAC OS E4G 16126 | 95600-16126 | \$ 164.00 | 6% | \$155.32 |
| PWP TAC OS E4G 16127 | 95600-16127 | \$ 172.00 | 6% | \$162.89 |
| PWP TAC OS 16169 | 95600-16169 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS 16172 | 95600-16172 | \$ 176.00 | 6% | \$166.68 |
| PWP TAC OS -16172T | 95600-16172T | \$ 207.00 | 6% | \$196.04 |
| PWP TAC OS 16173 | 95600-16173 | \$ 176.00 | 6% | \$166.68 |
| PWP TAC OS -16173T | 95600-16173T | \$ 207.00 | 6% | \$196.04 |
| PWP TAC OS 16174 | 95600-16174 | \$ 275.00 | 6% | \$260.44 |
| PWP TAC OS 16175 | 95600-16175 | \$ 292.00 | 6% | \$276.54 |
| PWP TAC OS 16176 | 95600-16176 | \$ 260.00 | 6% | \$246.23 |
| PWP TAC OS 16177 | 95600-16177 | \$ 250.00 | 6% | \$236.76 |
| PWP TAC OS -16177T | 95600-16177T | \$ 314.00 | 6% | \$297.37 |
| PWP TAC OS 16178 | 95600-16178 | \$ 367.00 | 6% | \$347.57 |
| PWP TAC OS 16179 | 95600-16179 | \$ 374.00 | 6% | \$354.20 |
| PWP TAC OS -16179T | 95600-16179T | \$ 460.00 | 6% | \$435.64 |
| PWP TAC OS 16190 | 95600-16190 | \$ 117.00 | 6% | \$110.80 |
| PWP TAC OS 16191 | 95600-16191 | \$ 225.00 | 6% | \$213.09 |
| PWP TAC OS 16192 | 95600-16192 | \$ 225.00 | 6% | \$213.09 |
| PWP TAC OS 16200 | 95600-16200 | \$ 128.00 | 6% | \$121.22 |
| PWP TAC OS 16301T | 95600-16301T | \$ 949.00 | 6% | \$898.75 |

| | | | | |
|-------------------------|--------------|-------------|----|------------|
| PWP TAC OS 16303T | 95600-16303T | \$ 949.00 | 6% | \$898.75 |
| PWP TAC OS 16304T | 95600-16304T | \$ 1,268.00 | 6% | \$1,200.86 |
| PWP TAC OS 16323 | 95600-16323 | \$ 128.00 | 6% | \$121.22 |
| PWP TAC OS 16401T | 95600-16401T | \$ 444.00 | 6% | \$420.49 |
| PWP TAC OS 16402T | 95600-16402T | \$ 678.00 | 6% | \$642.10 |
| PWP TAC OS 16403T | 95600-16403T | \$ 597.00 | 6% | \$565.39 |
| PWP TAC OS 16404T | 95600-16404T | \$ 597.00 | 6% | \$565.39 |
| PWP TAC OS 16405T | 95600-16405T | \$ 794.00 | 6% | \$751.96 |
| PWP TAC OS 16406T | 95600-16406T | \$ 1,063.00 | 6% | \$1,006.71 |
| PWP TAC OS 16423 | 95600-16423 | \$ 242.00 | 6% | \$229.19 |
| PWP TAC OS 16425 | 95600-16425 | \$ 128.00 | 6% | \$121.22 |
| PWP TAC OS 16426 | 95600-16426 | \$ 105.00 | 6% | \$99.44 |
| PWP TAC OS E4G 16431 | 95600-16431 | \$ 675.00 | 6% | \$639.26 |
| PWP TAC OS E4G 16432 | 95600-16432 | \$ 723.00 | 6% | \$684.72 |
| PWP TAC OS E4G 16440 | 95600-16440 | \$ 422.00 | 6% | \$399.66 |
| PWP TAC OS E4G 16441 | 95600-16441 | \$ 382.00 | 6% | \$361.77 |
| PWP TAC OS E4G 16442 | 95600-16442 | \$ 172.00 | 6% | \$162.89 |
| PWP TAC OS E4G 16444 | 95600-16444 | \$ 85.00 | 6% | \$80.50 |
| PWP TAC OS E4G 16490 | 95600-16490 | \$ 85.00 | 6% | \$80.50 |
| PWP TAC OS E4G 16491 | 95600-16491 | \$ 185.00 | 6% | \$175.20 |
| PWP TAC OS E4G 16492 | 95600-16492 | \$ 279.00 | 6% | \$264.23 |
| PWP TAC OS E4G 16493 | 95600-16493 | \$ 279.00 | 6% | \$264.23 |
| PWP TAC OS E4G 16495 | 95600-16495 | \$ 85.00 | 6% | \$80.50 |
| PWP TAC OS E4G 16496 | 95600-16496 | \$ 261.00 | 6% | \$247.18 |
| PWP TAC OS Summit 16501 | 95600-16501 | \$ 91.00 | 6% | \$86.18 |
| PWP TAC OS 16501T | 95600-16501T | \$ 144.00 | 6% | \$136.38 |
| PWP TAC OS Summit 16502 | 95600-16502 | \$ 135.00 | 6% | \$127.85 |
| PWP TAC OS 16502T | 95600-16502T | \$ 162.00 | 6% | \$153.42 |
| PWP TAC OS Summit 16503 | 95600-16503 | \$ 112.00 | 6% | \$106.07 |
| PWP TAC OS 16503T | 95600-16503T | \$ 144.00 | 6% | \$136.38 |
| PWP TAC OS Summit 16504 | 95600-16504 | \$ 183.00 | 6% | \$173.31 |
| PWP TAC OS 16504T | 95600-16504T | \$ 220.00 | 6% | \$208.35 |
| PWP TAC OS Summit 16505 | 95600-16505 | \$ 201.00 | 6% | \$190.36 |
| PWP TAC OS 16505T | 95600-16505T | \$ 249.00 | 6% | \$235.82 |
| PWP TAC OS Summit 16506 | 95600-16506 | \$ 307.00 | 6% | \$290.74 |
| PWP TAC OS 16506T | 95600-16506T | \$ 380.00 | 6% | \$359.88 |
| PWP TAC OS Summit 16507 | 95600-16507 | \$ 277.00 | 6% | \$262.33 |
| PWP TAC OS 16507T | 95600-16507T | \$ 328.00 | 6% | \$310.63 |
| PWP TAC OS Summit 16508 | 95600-16508 | \$ 343.00 | 6% | \$324.84 |
| PWP TAC OS 16508T | 95600-16508T | \$ 424.00 | 6% | \$401.55 |
| PWP TAC OS Summit 16509 | 95600-16509 | \$ 343.00 | 6% | \$324.84 |
| PWP TAC OS 16509T | 95600-16509T | \$ 424.00 | 6% | \$401.55 |

| | | | | |
|----------------------------|--------------|-----------|----|----------|
| PWP TAC OS Summit 16510 | 95600-16510 | \$ 424.00 | 6% | \$401.55 |
| PWP TAC OS 16510T | 95600-16510T | \$ 503.00 | 6% | \$476.37 |
| PWP Software and TAC-16513 | 95600-16513 | \$ 249.00 | 6% | \$235.82 |
| PWP Software and TAC-16514 | 95600-16514 | \$ 414.00 | 6% | \$392.08 |
| PWP TAC OS 16515 | 95600-16515 | \$ 72.00 | 6% | \$68.19 |
| PWP Software TAC-16516 | 95600-16516 | \$ 79.00 | 6% | \$74.82 |
| PWP TAC OS 16517 | 95600-16517 | \$ 152.00 | 6% | \$143.95 |
| PWP Software TAC-16518 | 95600-16518 | \$ 135.00 | 6% | \$127.85 |
| PWP-Software and TAC 16519 | 95600-16519 | \$ 144.00 | 6% | \$136.38 |
| PWP-Software and TAC 16520 | 95600-16520 | \$ 241.00 | 6% | \$228.24 |
| PWP TAC OS Summit 16521 | 95600-16521 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS 16522 | 95600-16522 | \$ 105.00 | 6% | \$99.44 |
| PWP TAC OS 16523 | 95600-16523 | \$ 55.00 | 6% | \$52.09 |
| PWP Software and TAC 16524 | 95600-16524 | \$ 64.00 | 6% | \$60.61 |
| PWP TAC OS 16530 | 95600-16530 | \$ 91.00 | 6% | \$86.18 |
| PWP TAC OS 16531 | 95600-16531 | \$ 121.00 | 6% | \$114.59 |
| PWP TAC OS 16531T | 95600-16531T | \$ 135.00 | 6% | \$127.85 |
| PWP TAC OS 16532 | 95600-16532 | \$ 121.00 | 6% | \$114.59 |
| PWP TAC OS 16532T | 95600-16532T | \$ 135.00 | 6% | \$127.85 |
| PWP TAC OS 16533 | 95600-16533 | \$ 173.00 | 6% | \$163.84 |
| PWP TAC OS 16533T | 95600-16533T | \$ 190.00 | 6% | \$179.94 |
| PWP TAC OS 16534 | 95600-16534 | \$ 180.00 | 6% | \$170.47 |
| PWP TAC OS 16535 | 95600-16535 | \$ 267.00 | 6% | \$252.86 |
| PWP TAC OS 16535A | 95600-16535A | \$ 267.00 | 6% | \$252.86 |
| PWP TAC OS 16535T | 95600-16535T | \$ 293.00 | 6% | \$277.49 |
| PWP TAC OS 16536 | 95600-16536 | \$ 128.00 | 6% | \$121.22 |
| PWP TAC OS 16537 | 95600-16537 | \$ 164.00 | 6% | \$155.32 |
| PWP TAC OS 16538 | 95600-16538 | \$ 202.00 | 6% | \$191.30 |
| PWP TAC OS 16538T | 95600-16538T | \$ 246.00 | 6% | \$232.97 |
| PWP TAC OS 16539 | 95600-16539 | \$ 257.00 | 6% | \$243.39 |
| PWP TAC OS 16540 | 95600-16540 | \$ 187.00 | 6% | \$177.10 |
| PWP TAC OS 16541 | 95600-16541 | \$ 75.00 | 6% | \$71.03 |
| PWP TAC OS 16560 | 95600-16560 | \$ 43.00 | 6% | \$40.72 |
| PWP TAC OS 16561 | 95600-16561 | \$ 56.00 | 6% | \$53.03 |
| PWP TAC OS 16562 | 95600-16562 | \$ 72.00 | 6% | \$68.19 |
| PWP TAC OS 16563 | 95600-16563 | \$ 92.00 | 6% | \$87.13 |
| PWP TAC OS 16564 | 95600-16564 | \$ 113.00 | 6% | \$107.02 |
| PWP TAC OS 16565 | 95600-16565 | \$ 177.00 | 6% | \$167.63 |
| PWP TAC OS 16566 | 95600-16566 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 16567 | 95600-16567 | \$ 49.00 | 6% | \$46.41 |
| PWP TAC OS 16568 | 95600-16568 | \$ 43.00 | 6% | \$40.72 |
| PWP TAC OS 16569 | 95600-16569 | \$ 64.00 | 6% | \$60.61 |

| | | | | |
|--------------------|--------------|-------------|----|----------|
| PWP TAC OS 16570 | 95600-16570 | \$ 72.00 | 6% | \$68.19 |
| PWP TAC OS 16571 | 95600-16571 | \$ 113.00 | 6% | \$107.02 |
| PWP TAC OS 16701 | 95600-16701 | \$ 249.00 | 6% | \$235.82 |
| PWP TAC OS 16702 | 95600-16702 | \$ 367.00 | 6% | \$347.57 |
| PWP TAC OS 16703 | 95600-16703 | \$ 292.00 | 6% | \$276.54 |
| PWP TAC OS -16703T | 95600-16703T | \$ 344.00 | 6% | \$325.79 |
| PWP TAC OS 16704 | 95600-16704 | \$ 425.00 | 6% | \$402.50 |
| PWP TAC OS -16704T | 95600-16704T | \$ 502.00 | 6% | \$475.42 |
| PWP TAC OS 16705 | 95600-16705 | \$ 367.00 | 6% | \$347.57 |
| PWP TAC OS -16705T | 95600-16705T | \$ 443.00 | 6% | \$419.54 |
| PWP TAC OS 16706 | 95600-16706 | \$ 548.00 | 6% | \$518.98 |
| PWP TAC OS -16706T | 95600-16706T | \$ 661.00 | 6% | \$626.00 |
| PWP TAC OS 16710 | 95600-16710 | \$ 120.00 | 6% | \$113.65 |
| PWP TAC OS 16710T | 95600-16710T | \$ 141.00 | 6% | \$133.53 |
| PWP TAC OS 16711 | 95600-16711 | \$ 48.00 | 6% | \$45.46 |
| PWP TAC OS 16711T | 95600-16711T | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS 16712 | 95600-16712 | \$ 71.00 | 6% | \$67.24 |
| PWP TAC OS 16712T | 95600-16712T | \$ 82.00 | 6% | \$77.66 |
| PWP TAC OS 16713 | 95600-16713 | \$ 36.00 | 6% | \$34.09 |
| PWP TAC OS 16713T | 95600-16713T | \$ 43.00 | 6% | \$40.72 |
| PWP TAC OS 16715 | 95600-16715 | \$ 47.00 | 6% | \$44.51 |
| PWP TAC OS 16715T | 95600-16715T | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS 16716 | 95600-16716 | \$ 190.00 | 6% | \$179.94 |
| PWP TAC OS -16716T | 95600-16716T | \$ 230.00 | 6% | \$217.82 |
| PWP TAC OS 16717 | 95600-16717 | \$ 290.00 | 6% | \$274.64 |
| PWP TAC OS 16718 | 95600-16718 | \$ 205.00 | 6% | \$194.15 |
| PWP TAC OS -16718T | 95600-16718T | \$ 252.00 | 6% | \$238.66 |
| PWP TAC OS 16719 | 95600-16719 | \$ 312.00 | 6% | \$295.48 |
| PWP TAC OS -16719T | 95600-16719T | \$ 380.00 | 6% | \$359.88 |
| PWP TAC OS 16720 | 95600-16720 | \$ 463.00 | 6% | \$438.48 |
| PWP TAC OS 16720T | 95600-16720T | \$ 540.00 | 6% | \$511.41 |
| PWP TAC OS 16755 | 95600-16755 | \$ 44.00 | 6% | \$41.67 |
| PWP TAC OS 16756 | 95600-16756 | \$ 343.00 | 6% | \$324.84 |
| PWP TAC OS 16756T | 95600-16756T | \$ 404.00 | 6% | \$382.61 |
| PWP TAC OS 16757 | 95600-16757 | \$ 319.00 | 6% | \$302.11 |
| PWP TAC OS 16757T | 95600-16757T | \$ 372.00 | 6% | \$352.30 |
| PWP TAC OS 16778 | 95600-16778 | \$ 39.00 | 6% | \$36.93 |
| PWP TAC OS 16779 | 95600-16779 | \$ 39.00 | 6% | \$36.93 |
| PWP TAC OS 16780 | 95600-16780 | \$ 39.00 | 6% | \$36.93 |
| PWP TAC OS 16790 | 95600-16790 | \$ 777.00 | 6% | \$735.86 |
| PWP TAC OS 16791 | 95600-16791 | \$ 1,001.00 | 6% | \$948.00 |
| PWP TAC OS 16795 | 95600-16795 | \$ 163.00 | 6% | \$154.37 |

| | | | | |
|--------------------------|--------------|-------------|----|------------|
| PWP TAC OS 16801 | 95600-16801 | \$ 99.00 | 6% | \$93.76 |
| PWP TAC OS 16802 | 95600-16802 | \$ 113.00 | 6% | \$107.02 |
| PWP TAC OS 16803 | 95600-16803 | \$ 121.00 | 6% | \$114.59 |
| PWP TAC OS 16804 | 95600-16804 | \$ 149.00 | 6% | \$141.11 |
| PWP TAC OS 16805 | 95600-16805 | \$ 29.00 | 6% | \$27.46 |
| PWP TAC OS 16806 | 95600-16806 | \$ 23.00 | 6% | \$21.78 |
| PWP TAC OS Summit 17101 | 95600-17101 | \$ 1,476.00 | 6% | \$1,397.85 |
| PWP TAC OS 17101T | 95600-17101T | \$ 1,063.00 | 6% | \$1,006.71 |
| PWP TAC OS Summit 17102 | 95600-17102 | \$ 1,476.00 | 6% | \$1,397.85 |
| PWP TAC OS 17102T | 95600-17102T | \$ 1,063.00 | 6% | \$1,006.71 |
| PWP TAC OS Summit 17103 | 95600-17103 | \$ 1,031.00 | 6% | \$976.41 |
| PWP TAC OS Summit 17103C | 95600-17103C | \$ 937.00 | 6% | \$887.39 |
| PWP TAC OS 17103T | 95600-17103T | \$ 1,258.00 | 6% | \$1,191.39 |
| PWP TAC OS Summit 17104 | 95600-17104 | \$ 1,031.00 | 6% | \$976.41 |
| PWP TAC OS 17104T | 95600-17104T | \$ 1,258.00 | 6% | \$1,191.39 |
| PWP TAC OS Summit 17121 | 95600-17121 | \$ 289.00 | 6% | \$273.70 |
| PWP TAC OS Summit 17122 | 95600-17122 | \$ 185.00 | 6% | \$175.20 |
| PWP TAC OS Summit 17131 | 95600-17131 | \$ 407.00 | 6% | \$385.45 |
| PWP TAC OS Summit 17133 | 95600-17133 | \$ 249.00 | 6% | \$235.82 |
| PWP TAC OS 17134 | 95600-17134 | \$ 383.00 | 6% | \$362.72 |
| PWP TAC OS 17135 | 95600-17135 | \$ 316.00 | 6% | \$299.27 |
| PWP TAC OS 17136 | 95600-17136 | \$ 64.00 | 6% | \$60.61 |
| PWP TAC OS 17137 | 95600-17137 | \$ 72.00 | 6% | \$68.19 |
| PWP TAC OS 17138 | 95600-17138 | \$ 72.00 | 6% | \$68.19 |
| PWP TAC OS 17139 | 95600-17139 | \$ 72.00 | 6% | \$68.19 |
| PWP TAC OS -17200 | 95600-17200 | \$ 2,321.00 | 6% | \$2,198.10 |
| PWP TAC OS 17200T | 95600-17200T | \$ 2,536.00 | 6% | \$2,401.72 |
| PWP TAC OS Summit 17201 | 95600-17201 | \$ 2,321.00 | 6% | \$2,198.10 |
| PWP TAC OS 17201T | 95600-17201T | \$ 2,536.00 | 6% | \$2,401.72 |
| PWP TAC OS Summit 17202 | 95600-17202 | \$ 2,321.00 | 6% | \$2,198.10 |
| PWP TAC OS 17202T | 95600-17202T | \$ 2,536.00 | 6% | \$2,401.72 |
| PWP TAC OS Summit 17203 | 95600-17203 | \$ 2,368.00 | 6% | \$2,242.61 |
| PWP TAC OS 17203T | 95600-17203T | \$ 2,575.00 | 6% | \$2,438.65 |
| PWP TAC OS Summit 17204 | 95600-17204 | \$ 2,368.00 | 6% | \$2,242.61 |
| PWP TAC OS 17204T | 95600-17204T | \$ 2,575.00 | 6% | \$2,438.65 |
| PWP TAC OS Summit 17205 | 95600-17205 | \$ 2,342.00 | 6% | \$2,217.99 |
| PWP TAC OS 17205T | 95600-17205T | \$ 2,549.00 | 6% | \$2,414.03 |
| PWP TAC OS Summit 17206 | 95600-17206 | \$ 2,342.00 | 6% | \$2,217.99 |
| PWP TAC OS 17206T | 95600-17206T | \$ 2,549.00 | 6% | \$2,414.03 |
| PWP TAC OS 17300 | 95600-17300 | \$ 1,536.00 | 6% | \$1,454.67 |
| PWP TAC OS 17310 | 95600-17310 | \$ 1,396.00 | 6% | \$1,322.08 |
| PWP TAC OS -17310T | 95600-17310T | \$ 1,677.00 | 6% | \$1,588.20 |

| | | | | |
|----------------------|-----------------|-------------|----|------------|
| PWP TAC OS 17350 | 95600-17350 | \$ 1,410.00 | 6% | \$1,335.34 |
| PWP TAC OS 17360 | 95600-17360 | \$ 1,730.00 | 6% | \$1,638.40 |
| PWP TAC OS 17401 | 95600-17401 | \$ 212.00 | 6% | \$200.77 |
| PWP TAC OS 17401G | 95600-17401G | \$ 253.00 | 6% | \$239.60 |
| PWP TAC OS 17401T | 95600-17401T | \$ 240.00 | 6% | \$227.29 |
| PWP TAC OS 17402 | 95600-17402 | \$ 301.00 | 6% | \$285.06 |
| PWP TAC OS 17402G | 95600-17402G | \$ 340.00 | 6% | \$322.00 |
| PWP TAC OS 17402T | 95600-17402T | \$ 322.00 | 6% | \$304.95 |
| PWP TAC OS 17403 | 95600-17403 | \$ 330.00 | 6% | \$312.53 |
| PWP TAC OS 17404 | 95600-17404 | \$ 162.00 | 6% | \$153.42 |
| PWP TAC OS 17405 | 95600-17405 | \$ 197.00 | 6% | \$186.57 |
| PWP TAC OS 17431 | 95600-17431 | \$ 44.00 | 6% | \$41.67 |
| PWP TAC OS 17433 | 95600-17433 | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS 17434 | 95600-17434 | \$ 53.00 | 6% | \$50.19 |
| PWP TAC OS 17435 | 95600-17435 | \$ 74.00 | 6% | \$70.08 |
| PWP TAC OS 17438 | 95600-17438 | \$ 65.00 | 6% | \$61.56 |
| PWP TAC OS 17700 | 95600-17700 | \$ 2,721.00 | 6% | \$2,576.92 |
| PWP TAC OS 17701 | 95600-17701 | \$ 2,418.00 | 6% | \$2,289.97 |
| PWP TAC OS 17702 | 95600-17702 | \$ 2,418.00 | 6% | \$2,289.97 |
| PWP TAC OS 17703 | 95600-17703 | \$ 2,596.00 | 6% | \$2,458.54 |
| PWP TAC OS 17704 | 95600-17704 | \$ 2,596.00 | 6% | \$2,458.54 |
| PWP TAC OS 17705 | 95600-17705 | \$ 2,430.00 | 6% | \$2,301.33 |
| PWP TAC OS 17706 | 95600-17706 | \$ 2,430.00 | 6% | \$2,301.33 |
| PWP TAC OS 17725 | 95600-17725 | \$ 510.00 | 6% | \$483.00 |
| PWP TAC OS 17726 | 95600-17726 | \$ 224.00 | 6% | \$212.14 |
| PWP TAC OS 17727 | 95600-17727 | \$ 464.00 | 6% | \$439.43 |
| PWP TAC OS 17728 | 95600-17728 | \$ 211.00 | 6% | \$199.83 |
| PWP TAC OS 17729 | 95600-17729 | \$ 140.00 | 6% | \$132.59 |
| PWP TAC OS 17800 | 95600-17800 | \$ 2,718.00 | 6% | \$2,574.08 |
| PWP TAC OS 17810 | 95600-17810 | \$ 2,168.00 | 6% | \$2,053.20 |
| PWP TAC OS 17825 | 95600-17825 | \$ 382.00 | 6% | \$361.77 |
| PWP TAC OS 17826 | 95600-17826 | \$ 449.00 | 6% | \$425.23 |
| PWP TAC OS 17828 | 95600-17828 | \$ 268.00 | 6% | \$253.81 |
| PWP TAC OS 18101 | 95600-18101 | \$ 136.00 | 6% | \$128.80 |
| PWP TAC OS 18102 | 95600-18102 | \$ 178.00 | 6% | \$168.57 |
| PWP TAC OS 18103 | 95600-18103 | \$ 192.00 | 6% | \$181.83 |
| PWP TAC OS 18104 | 95600-18104 | \$ 274.00 | 6% | \$259.49 |
| PWP TAC OS 18104-6PK | 95600-18104-6PK | \$ 1,533.00 | 6% | \$1,451.83 |
| PWP TAC OS 18202 | 95600-18202 | \$ 103.00 | 6% | \$97.55 |
| PWP TAC OS 30135 | 95600-30135 | \$ 294.00 | 6% | \$278.43 |
| PWP TAC OS 30136 | 95600-30136 | \$ 2,268.00 | 6% | \$2,147.91 |

| | | | | |
|------------------|-------------|-------------|----|------------|
| PWP TAC OS 30137 | 95600-30137 | \$ 482.00 | 6% | \$456.48 |
| PWP TAC OS 30138 | 95600-30138 | \$ 2,402.00 | 6% | \$2,274.81 |
| PWP TAC OS 30139 | 95600-30139 | \$ 3,884.00 | 6% | \$3,678.34 |
| PWP TAC OS 30912 | 95600-30912 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 30913 | 95600-30913 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31012 | 95600-31012 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31013 | 95600-31013 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31014 | 95600-31014 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31015 | 95600-31015 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31016 | 95600-31016 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31017 | 95600-31017 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31018 | 95600-31018 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31019 | 95600-31019 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31025 | 95600-31025 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31026 | 95600-31026 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31028 | 95600-31028 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31029 | 95600-31029 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31031 | 95600-31031 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31032 | 95600-31032 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31034 | 95600-31034 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31035 | 95600-31035 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31050 | 95600-31050 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31051 | 95600-31051 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31055 | 95600-31055 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 31056 | 95600-31056 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37101 | 95600-37101 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37102 | 95600-37102 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37103 | 95600-37103 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37111 | 95600-37111 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37112 | 95600-37112 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37113 | 95600-37113 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37114 | 95600-37114 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37115 | 95600-37115 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37116 | 95600-37116 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37117 | 95600-37117 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37121 | 95600-37121 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37122 | 95600-37122 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37123 | 95600-37123 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37124 | 95600-37124 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37125 | 95600-37125 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37126 | 95600-37126 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 37129 | 95600-37129 | \$ 30.00 | 6% | \$28.41 |

| | | | | |
|----------------------------|-----------------------|-------------|----|-------------------|
| PWP TAC OS 37130 | 95600-37130 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39031 | 95600-39031 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39032 | 95600-39032 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39033 | 95600-39033 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39034 | 95600-39034 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39035 | 95600-39035 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39036 | 95600-39036 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39038 | 95600-39038 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39039 | 95600-39039 | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS 39505 | 95600-39505 | \$ 29.00 | 6% | <i>\$27.46</i> |
| PWP TAC OS 4120-24MW-4Y | 95600-4120-24MW-4Y | \$ 396.00 | 6% | <i>\$375.03</i> |
| PWP TAC OS 4120-48MW-4Y | 95600-4120-48MW-4Y | \$ 528.00 | 6% | <i>\$500.04</i> |
| PWP TAC OS 4120C | 95600-4120C | \$ 2,589.00 | 6% | <i>\$2,451.91</i> |
| PWP TAC OS 4120C-1 | 95600-4120C-1 | \$ 2,923.00 | 6% | <i>\$2,768.23</i> |
| PWP TAC OS 41216 | 95600-41216 | \$ 894.00 | 6% | <i>\$846.66</i> |
| PWP TAC OS BD 41312 | 95600-41312 | \$ 735.00 | 6% | <i>\$696.08</i> |
| PWP TAC OS 41314 | 95600-41314 | \$ 2,207.00 | 6% | <i>\$2,090.14</i> |
| PWP TAC OS 4220-12P-4X | 95600-4220-12P-4X | \$ 117.00 | 6% | <i>\$110.80</i> |
| PWP TAC OS 4220-12T-4X | 95600-4220-12T-4X | \$ 86.00 | 6% | <i>\$81.45</i> |
| PWP TAC OS 4220-24P-4X | 95600-4220-24P-4X | \$ 156.00 | 6% | <i>\$147.74</i> |
| PWP TAC OS 4220-24T-4X | 95600-4220-24T-4X | \$ 121.00 | 6% | <i>\$114.59</i> |
| PWP TAC OS 4220-48P-4X | 95600-4220-48P-4X | \$ 234.00 | 6% | <i>\$221.61</i> |
| PWP TAC OS 4220-48T-4X | 95600-4220-48T-4X | \$ 175.00 | 6% | <i>\$165.73</i> |
| PWP TAC OS 4220-4MW-20P-4X | 95600-4220-4MW-20P-4X | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS 4220-4MW-8P-4X | 95600-4220-4MW-8P-4X | \$ 152.00 | 6% | <i>\$143.95</i> |
| PWP TAC OS 4220-8MW-40P-4X | 95600-4220-8MW-40P-4X | \$ 312.00 | 6% | <i>\$295.48</i> |
| PWP TAC OS 4220-8X | 95600-4220-8X | \$ 164.00 | 6% | <i>\$155.32</i> |
| PWP TAC OS BD X 48001 | 95600-48001 | \$ 3,705.00 | 6% | <i>\$3,508.82</i> |
| PWP TAC OS 48038 | 95600-48038 | \$ 1,486.00 | 6% | <i>\$1,407.32</i> |

| | | | | |
|--------------------------------|---------------------------|-------------|----|-------------------|
| PWP TAC OS 48039 | 95600-48039 | \$ 1,486.00 | 6% | <i>\$1,407.32</i> |
| PWP Software and TAC-48040 | 95600-48040 | \$ 1,404.00 | 6% | <i>\$1,329.66</i> |
| PWP TAC OS BD X 48041 | 95600-48041 | \$ 1,486.00 | 6% | <i>\$1,407.32</i> |
| PWP TAC OS BD X 48046 | 95600-48046 | \$ 1,950.00 | 6% | <i>\$1,846.75</i> |
| PWP TAC OS 48047 | 95600-48047 | \$ 5,198.00 | 6% | <i>\$4,922.77</i> |
| PWP TAC OS BD X 48051 | 95600-48051 | \$ 3,570.00 | 6% | <i>\$3,380.97</i> |
| PWP TAC OS 48061 | 95600-48061 | \$ 4,176.00 | 6% | <i>\$3,954.88</i> |
| PWP TAC OS 48062 | 95600-48062 | \$ 6,681.00 | 6% | <i>\$6,327.24</i> |
| PWP TAC OS BD X 48091 | 95600-48091 | \$ 1,389.00 | 6% | <i>\$1,315.45</i> |
| PWP TAC OS BD X 48093 | 95600-48093 | \$ 926.00 | 6% | <i>\$876.97</i> |
| PWP TAC OS 48094 | 95600-48094 | \$ 1,389.00 | 6% | <i>\$1,315.45</i> |
| PWP TAC OS 5000-MACSEC-LIC | 95600-5000-MACSEC-LIC | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP TAC OS 5000-PRMR-LIC | 95600-5000-PRMR-LIC | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP TAC OS 5320-16P-4XE | 95600-5320-16P-4XE | \$ 166.00 | 6% | <i>\$157.21</i> |
| PWP TAC OS 5320-16P-4XE-DC | 95600-5320-16P-4XE-DC | \$ 199.00 | 6% | <i>\$188.46</i> |
| PWP TAC OS 5320-24P-8XE | 95600-5320-24P-8XE | \$ 182.00 | 6% | <i>\$172.36</i> |
| PWP TAC OS 5320-24T-24S-4XE-XT | 95600-5320-24T-24S-4XE-XT | \$ 253.00 | 6% | <i>\$239.60</i> |
| PWP TAC OS 5320-24T-4X-XT | 95600-5320-24T-4X-XT | \$ 136.00 | 6% | <i>\$128.80</i> |
| PWP TAC OS 5320-24T-8XE | 95600-5320-24T-8XE | \$ 130.00 | 6% | <i>\$123.12</i> |
| PWP TAC OS 5320-48P-8XE | 95600-5320-48P-8XE | \$ 305.00 | 6% | <i>\$288.85</i> |
| PWP TAC OS 5320-48T-8XE | 95600-5320-48T-8XE | \$ 206.00 | 6% | <i>\$195.09</i> |
| PWP TAC OS 5420F-16MW-32P-4XE | 95600-5420F-16MW-32P-4XE | \$ 569.00 | 6% | <i>\$538.87</i> |
| PWP TAC OS 5420F-16W-32P-4XE | 95600-5420F-16W-32P-4XE | \$ 481.00 | 6% | <i>\$455.53</i> |
| PWP TAC OS 5420F-24P-4XE | 95600-5420F-24P-4XE | \$ 296.00 | 6% | <i>\$280.33</i> |
| PWP TAC OS 5420F-24S-4XE | 95600-5420F-24S-4XE | \$ 271.00 | 6% | <i>\$256.65</i> |

| | | | | |
|-------------------------------|--------------------------|-----------|----|----------|
| PWP TAC OS 5420F-24T-4XE | 95600-5420F-24T-4XE | \$ 251.00 | 6% | \$237.71 |
| PWP TAC OS 5420F-48P-4XE | 95600-5420F-48P-4XE | \$ 455.00 | 6% | \$430.91 |
| PWP TAC OS 5420F-48P-4XL | 95600-5420F-48P-4XL | \$ 436.00 | 6% | \$412.91 |
| PWP TAC OS 5420F-48T-4XE | 95600-5420F-48T-4XE | \$ 329.00 | 6% | \$311.58 |
| PWP TAC OS 5420F-8W-16P-4XE | 95600-5420F-8W-16P-4XE | \$ 283.00 | 6% | \$268.02 |
| PWP TAC OS 5420M-16MW-32P-4YE | 95600-5420M-16MW-32P-4YE | \$ 691.00 | 6% | \$654.41 |
| PWP TAC OS 5420M-24T-4YE | 95600-5420M-24T-4YE | \$ 279.00 | 6% | \$264.23 |
| PWP TAC OS 5420M-24W-4YE | 95600-5420M-24W-4YE | \$ 280.00 | 6% | \$265.17 |
| PWP TAC OS 5420M-48T-4YE | 95600-5420M-48T-4YE | \$ 395.00 | 6% | \$374.08 |
| PWP TAC OS 5420M-48W-4YE | 95600-5420M-48W-4YE | \$ 445.00 | 6% | \$421.44 |
| PWP TAC OS 5520-12MW-36W | 95600-5520-12MW-36W | \$ 583.00 | 6% | \$552.13 |
| PWP TAC OS 5520-24T | 95600-5520-24T | \$ 263.00 | 6% | \$249.07 |
| PWP TAC OS 5520-24T-ACDC-BASE | 95600-5520-24T-ACDC-BASE | \$ 263.00 | 6% | \$249.07 |
| PWP TAC OS 5520-24T-BASE | 95600-5520-24T-BASE | \$ 263.00 | 6% | \$249.07 |
| PWP TAC OS 5520-24W | 95600-5520-24W | \$ 338.00 | 6% | \$320.10 |
| PWP TAC OS 5520-24X | 95600-5520-24X | \$ 713.00 | 6% | \$675.25 |
| PWP TAC OS 5520-24X-ACDC-BASE | 95600-5520-24X-ACDC-BASE | \$ 713.00 | 6% | \$675.25 |
| PWP TAC OS 5520-24X-BASE | 95600-5520-24X-BASE | \$ 713.00 | 6% | \$675.25 |
| PWP TAC OS 5520-48SE | 95600-5520-48SE | \$ 603.00 | 6% | \$571.07 |

| | | | | |
|--------------------------------|---------------------------|-------------|----|------------|
| PWP TAC OS 5520-48SE-ACDC-BASE | 95600-5520-48SE-ACDC-BASE | \$ 603.00 | 6% | \$571.07 |
| PWP TAC OS 5520-48SE-BASE | 95600-5520-48SE-BASE | \$ 603.00 | 6% | \$571.07 |
| PWP TAC OS 5520-48T | 95600-5520-48T | \$ 398.00 | 6% | \$376.93 |
| PWP TAC OS 5520-48T-ACDC-BASE | 95600-5520-48T-ACDC-BASE | \$ 398.00 | 6% | \$376.93 |
| PWP TAC OS 5520-48T-BASE | 95600-5520-48T-BASE | \$ 398.00 | 6% | \$376.93 |
| PWP TAC OS 5520-48W | 95600-5520-48W | \$ 477.00 | 6% | \$451.74 |
| PWP TAC OS 5720-24MW | 95600-5720-24MW | \$ 750.00 | 6% | \$710.29 |
| PWP TAC OS 5720-24MXW | 95600-5720-24MXW | \$ 1,015.00 | 6% | \$961.26 |
| PWP TAC OS 5720-48MW | 95600-5720-48MW | \$ 923.00 | 6% | \$874.13 |
| PWP TAC OS 5720-48MXW | 95600-5720-48MXW | \$ 1,319.00 | 6% | \$1,249.16 |
| PWP TAC OS 7000-MACSEC-LIC-P | 95600-7000-MACSEC-LIC-P | \$ 408.00 | 6% | \$386.40 |
| PWP TAC OS 7000-PRMR-LIC-P | 95600-7000-PRMR-LIC-P | \$ 408.00 | 6% | \$386.40 |
| PWP TAC OS 7520-48XT-6C | 95600-7520-48XT-6C | \$ 1,343.00 | 6% | \$1,271.89 |
| PWP TAC OS 7520-48XT-6C-AC-F | 95600-7520-48XT-6C-AC-F | \$ 1,343.00 | 6% | \$1,271.89 |
| PWP TAC OS 7520-48XT-6C-AC-R | 95600-7520-48XT-6C-AC-R | \$ 1,343.00 | 6% | \$1,271.89 |
| PWP TAC OS 7520-48Y-8C | 95600-7520-48Y-8C | \$ 1,310.00 | 6% | \$1,240.64 |
| PWP TAC OS 7520-48Y-8C-AC-F | 95600-7520-48Y-8C-AC-F | \$ 1,310.00 | 6% | \$1,240.64 |
| PWP TAC OS 7520-48Y-8C-AC-R | 95600-7520-48Y-8C-AC-R | \$ 1,310.00 | 6% | \$1,240.64 |
| PWP TAC OS 7520-48YE-8CE | 95600-7520-48YE-8CE | \$ 1,504.00 | 6% | \$1,424.36 |

| | | | | |
|-------------------------------|--------------------------|-------------|----|-------------------|
| PWP TAC OS 7520-48YE-8CE-AC-F | 95600-7520-48YE-8CE-AC-F | \$ 1,504.00 | 6% | <i>\$1,424.36</i> |
| PWP TAC OS 7520-48YE-8CE-AC-R | 95600-7520-48YE-8CE-AC-R | \$ 1,504.00 | 6% | <i>\$1,424.36</i> |
| PWP TAC OS 7720-32C | 95600-7720-32C | \$ 1,640.00 | 6% | <i>\$1,553.16</i> |
| PWP TAC OS 7720-32C-AC-F | 95600-7720-32C-AC-F | \$ 1,640.00 | 6% | <i>\$1,553.16</i> |
| PWP TAC OS 7720-32C-AC-R | 95600-7720-32C-AC-R | \$ 1,640.00 | 6% | <i>\$1,553.16</i> |
| PWP TAC OS 8000-PRMR-LIC-P | 95600-8000-PRMR-LIC-P | \$ 404.00 | 6% | <i>\$382.61</i> |
| PWP TAC OS 8520-48XT-6C | 95600-8520-48XT-6C | \$ 1,341.00 | 6% | <i>\$1,269.99</i> |
| PWP TAC OS 8520-48XT-6C-AC-F | 95600-8520-48XT-6C-AC-F | \$ 1,341.00 | 6% | <i>\$1,269.99</i> |
| PWP TAC OS 8520-48XT-6C-AC-R | 95600-8520-48XT-6C-AC-R | \$ 1,341.00 | 6% | <i>\$1,269.99</i> |
| PWP TAC OS 8520-48XT-6C-DC-F | 95600-8520-48XT-6C-DC-F | \$ 1,341.00 | 6% | <i>\$1,269.99</i> |
| PWP TAC OS 8520-48XT-6C-DC-R | 95600-8520-48XT-6C-DC-R | \$ 1,341.00 | 6% | <i>\$1,269.99</i> |
| PWP TAC OS 8520-48Y-8C | 95600-8520-48Y-8C | \$ 1,361.00 | 6% | <i>\$1,288.94</i> |
| PWP TAC OS 8520-48Y-8C-AC-F | 95600-8520-48Y-8C-AC-F | \$ 1,361.00 | 6% | <i>\$1,288.94</i> |
| PWP TAC OS 8520-48Y-8C-AC-R | 95600-8520-48Y-8C-AC-R | \$ 1,361.00 | 6% | <i>\$1,288.94</i> |
| PWP TAC OS 8520-48Y-8C-DC-F | 95600-8520-48Y-8C-DC-F | \$ 1,361.00 | 6% | <i>\$1,288.94</i> |
| PWP TAC OS 8520-48Y-8C-DC-R | 95600-8520-48Y-8C-DC-R | \$ 1,361.00 | 6% | <i>\$1,288.94</i> |
| PWP TAC OS 86100 | 95600-86100 | \$ 3,355.00 | 6% | <i>\$3,177.35</i> |
| PWP TAC OS 86101 | 95600-86101 | \$ 4,266.00 | 6% | <i>\$4,040.12</i> |
| PWP TAC OS 87100 | 95600-87100 | \$ 1,985.00 | 6% | <i>\$1,879.89</i> |
| PWP TAC OS 87101 | 95600-87101 | \$ 3,195.00 | 6% | <i>\$3,025.82</i> |

| | | | | |
|--------------------------|---------------------|--------------|----|--------------------|
| PWP TAC OS 8720-32C | 95600-8720-32C | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| PWP TAC OS 8720-32C-AC-F | 95600-8720-32C-AC-F | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| PWP TAC OS 8720-32C-AC-R | 95600-8720-32C-AC-R | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| PWP TAC OS 8720-32C-DC-F | 95600-8720-32C-DC-F | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| PWP TAC OS 8720-32C-DC-R | 95600-8720-32C-DC-R | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| PWP TAC SW 8806 | 95600-8806 | \$ 926.00 | 6% | <i>\$876.97</i> |
| PWP TAC OS BD 8810 | 95600-8810 | \$ 2,412.00 | 6% | <i>\$2,284.28</i> |
| PWP TAC OS 88100 | 95600-88100 | \$ 3,508.00 | 6% | <i>\$3,322.25</i> |
| PWP TAC OS 8820-40C | 95600-8820-40C | \$ 7,755.00 | 6% | <i>\$7,344.37</i> |
| PWP TAC OS 8820-40C-AC-F | 95600-8820-40C-AC-F | \$ 7,755.00 | 6% | <i>\$7,344.37</i> |
| PWP TAC OS 8820-40C-AC-R | 95600-8820-40C-AC-R | \$ 7,755.00 | 6% | <i>\$7,344.37</i> |
| PWP TAC OS 8820-40C-DC-F | 95600-8820-40C-DC-F | \$ 7,755.00 | 6% | <i>\$7,344.37</i> |
| PWP TAC OS 8820-40C-DC-R | 95600-8820-40C-DC-R | \$ 7,755.00 | 6% | <i>\$7,344.37</i> |
| PWP TAC OS 8820-80C | 95600-8820-80C | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| PWP TAC OS 8820-80C-AC-F | 95600-8820-80C-AC-F | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| PWP TAC OS 8820-80C-AC-R | 95600-8820-80C-AC-R | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| PWP TAC OS 8820-80C-DC-F | 95600-8820-80C-DC-F | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| PWP TAC OS 8820-80C-DC-R | 95600-8820-80C-DC-R | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| PWP TAC SW 88XOS | 95600-88XOS | \$ 2,207.00 | 6% | <i>\$2,090.14</i> |
| PWP TAC OS 9920-16C | 95600-9920-16C | \$ 5,278.00 | 6% | <i>\$4,998.53</i> |
| PWP TAC OS 9920-4D | 95600-9920-4D | \$ 5,278.00 | 6% | <i>\$4,998.53</i> |
| PWP TAC OS 9920-NPB-8 | 95600-9920-NPB-8 | \$ 9,603.00 | 6% | <i>\$9,094.52</i> |
| PWP Software and TAC | 95600-A10148 | \$ 1,766.00 | 6% | <i>\$1,672.49</i> |

| | | | | |
|------------------------------|-------------------------|----------|----|----------------|
| PWP TAC OS AH-AP-1130-AC-CE | 95600-AH-AP-1130-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-1130-AC-FCC | 95600-AH-AP-1130-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-1130-AC-W | 95600-AH-AP-1130-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-121-N-CE | 95600-AH-AP-121-N-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-121-N-FCC | 95600-AH-AP-121-N-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-121-N-W | 95600-AH-AP-121-N-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-121-N-W-NEC | 95600-AH-AP-121-N-W-NEC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122-AC-CAN | 95600-AH-AP-122-AC-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122-AC-CE | 95600-AH-AP-122-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122-AC-FCC | 95600-AH-AP-122-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122-AC-W | 95600-AH-AP-122-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122X-AC-CAN | 95600-AH-AP-122X-AC-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122X-AC-CE | 95600-AH-AP-122X-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122X-AC-FCC | 95600-AH-AP-122X-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-122X-AC-W | 95600-AH-AP-122X-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-130-AC-CE | 95600-AH-AP-130-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-130-AC-FCC | 95600-AH-AP-130-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-130-AC-W | 95600-AH-AP-130-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-141-N-CE | 95600-AH-AP-141-N-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-141-N-FCC | 95600-AH-AP-141-N-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |

| | | | | |
|------------------------------|-------------------------|----------|----|----------------|
| PWP TAC OS AH-AP-141-N-W | 95600-AH-AP-141-N-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-150W-AC-CAN | 95600-AH-AP-150W-AC-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-150W-AC-CE | 95600-AH-AP-150W-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-150W-AC-FCC | 95600-AH-AP-150W-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-150W-AC-W | 95600-AH-AP-150W-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-170-N-W | 95600-AH-AP-170-N-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-230-AC-CE | 95600-AH-AP-230-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-230-AC-FCC | 95600-AH-AP-230-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-230-AC-W | 95600-AH-AP-230-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-245X-AC-CAN | 95600-AH-AP-245X-AC-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-245X-AC-CE | 95600-AH-AP-245X-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-245X-AC-FCC | 95600-AH-AP-245X-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-245X-AC-W | 95600-AH-AP-245X-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-250-AC-CAN | 95600-AH-AP-250-AC-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-250-AC-CE | 95600-AH-AP-250-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-250-AC-FCC | 95600-AH-AP-250-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-250-AC-W | 95600-AH-AP-250-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-330-N-FCC | 95600-AH-AP-330-N-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-330-N-W | 95600-AH-AP-330-N-W | \$ 30.00 | 6% | <i>\$28.41</i> |

| | | | | |
|------------------------------|-------------------------|----------|----|----------------|
| PWP TAC OS AH-AP-350-N-FCC | 95600-AH-AP-350-N-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-350-N-W | 95600-AH-AP-350-N-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-370-AC-W | 95600-AH-AP-370-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-390-AC-W | 95600-AH-AP-390-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-550-AC-CAN | 95600-AH-AP-550-AC-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-550-AC-CE | 95600-AH-AP-550-AC-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-550-AC-FCC | 95600-AH-AP-550-AC-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-550-AC-W | 95600-AH-AP-550-AC-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-630-AX-CAN | 95600-AH-AP-630-AX-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-630-AX-CE | 95600-AH-AP-630-AX-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-630-AX-FCC | 95600-AH-AP-630-AX-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-630-AX-W | 95600-AH-AP-630-AX-W | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AH-AP-650-AX-CAN | 95600-AH-AP-650-AX-CAN | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AH-AP-650-AX-CE | 95600-AH-AP-650-AX-CE | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AH-AP-650-AX-FCC | 95600-AH-AP-650-AX-FCC | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AH-AP-650-AX-W | 95600-AH-AP-650-AX-W | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AH-AP-650X-AX-CAN | 95600-AH-AP-650X-AX-CAN | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AH-AP-650X-AX-CE | 95600-AH-AP-650X-AX-CE | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AH-AP-650X-AX-FCC | 95600-AH-AP-650X-AX-FCC | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AH-AP-650X-AX-W | 95600-AH-AP-650X-AX-W | \$ 25.00 | 6% | <i>\$23.68</i> |

| | | | | |
|------------------------------|-------------------------|----------|----|----------------|
| PWP TAC OS AH-ATOM-CAN | 95600-AH-ATOM-CAN | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS AH-ATOM-CE-EU | 95600-AH-ATOM-CE-EU | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS AH-ATOM-CE-UK | 95600-AH-ATOM-CE-UK | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS AH-ATOM-FCC | 95600-AH-ATOM-FCC | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS AH-ATOM-W | 95600-AH-ATOM-W | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS AH-ATOM-W-EU | 95600-AH-ATOM-W-EU | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS AH-ATOM-W-UK | 95600-AH-ATOM-W-UK | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS AH-BR-100-N-FCC | 95600-AH-BR-100-N-FCC | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-100-N-W | 95600-AH-BR-100-N-W | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-100-N-W-AU | 95600-AH-BR-100-N-W-AU | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-100-N-W-EU | 95600-AH-BR-100-N-W-EU | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-100-N-W-UK | 95600-AH-BR-100-N-W-UK | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-100-N-W-US | 95600-AH-BR-100-N-W-US | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-200 | 95600-AH-BR-200 | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-200WP-N-CE | 95600-AH-BR-200WP-N-CE | \$ 29.00 | 6% | <i>\$27.46</i> |
| PWP TAC OS AH-BR-200WP-N-EU | 95600-AH-BR-200WP-N-EU | \$ 29.00 | 6% | <i>\$27.46</i> |
| PWP TAC OS AH-BR-200WP-N-FCC | 95600-AH-BR-200WP-N-FCC | \$ 28.00 | 6% | <i>\$26.52</i> |
| PWP TAC OS AH-BR-200WP-N-W | 95600-AH-BR-200WP-N-W | \$ 29.00 | 6% | <i>\$27.46</i> |
| PWP TAC OS AH-SR-2124P | 95600-AH-SR-2124P | \$ 27.00 | 6% | <i>\$25.57</i> |
| PWP TAC OS AH-SR-2148P | 95600-AH-SR-2148P | \$ 27.00 | 6% | <i>\$25.57</i> |

| | | | | |
|---------------------------|----------------------|----------|----|---------|
| PWP TAC OS AH-SR-2208P-AU | 95600-AH-SR-2208P-AU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2208P-EU | 95600-AH-SR-2208P-EU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2208P-NA | 95600-AH-SR-2208P-NA | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2208P-UK | 95600-AH-SR-2208P-UK | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2224P-AU | 95600-AH-SR-2224P-AU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2224P-EU | 95600-AH-SR-2224P-EU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2224P-NA | 95600-AH-SR-2224P-NA | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2224P-UK | 95600-AH-SR-2224P-UK | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2324P-AU | 95600-AH-SR-2324P-AU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2324P-EU | 95600-AH-SR-2324P-EU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2324P-NA | 95600-AH-SR-2324P-NA | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2324P-UK | 95600-AH-SR-2324P-UK | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2348P-AU | 95600-AH-SR-2348P-AU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2348P-EU | 95600-AH-SR-2348P-EU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2348P-NA | 95600-AH-SR-2348P-NA | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-SR-2348P-UK | 95600-AH-SR-2348P-UK | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR200P-AU | 95600-AH-XR200P-AU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR200P-EU | 95600-AH-XR200P-EU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR200P-UK | 95600-AH-XR200P-UK | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR200P-US | 95600-AH-XR200P-US | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR600P | 95600-AH-XR600P | \$ 27.00 | 6% | \$25.57 |

| | | | | |
|------------------------------|-------------------------|----------|----|---------|
| PWP TAC OS AH-XR600P-AU | 95600-AH-XR600P-AU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR600P-EU | 95600-AH-XR600P-EU | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR600P-KR | 95600-AH-XR600P-KR | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR600P-UK | 95600-AH-XR600P-UK | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AH-XR600P-US | 95600-AH-XR600P-US | \$ 27.00 | 6% | \$25.57 |
| PWP TAC OS AP-8533-68SB30-IL | 95600-AP-8533-68SB30-IL | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP3000-IL | 95600-AP3000-IL | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP3000-TN | 95600-AP3000-TN | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP3000-WW | 95600-AP3000-WW | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP3000X-WW | 95600-AP3000X-WW | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP302W-CAN | 95600-AP302W-CAN | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP302W-EG | 95600-AP302W-EG | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP302W-FCC | 95600-AP302W-FCC | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP302W-WR | 95600-AP302W-WR | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP305C-1-CAN | 95600-AP305C-1-CAN | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP305C-1-EG | 95600-AP305C-1-EG | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP305C-1-FCC | 95600-AP305C-1-FCC | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP305C-1-IL | 95600-AP305C-1-IL | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP305C-1-WR | 95600-AP305C-1-WR | \$ 30.00 | 6% | \$28.41 |

| | | | | |
|------------------------|-------------------|----------|----|----------------|
| PWP TAC OS AP305C-CAN | 95600-AP305C-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305C-EG | 95600-AP305C-EG | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305C-FCC | 95600-AP305C-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305C-IL | 95600-AP305C-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305C-WR | 95600-AP305C-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305CX-CAN | 95600-AP305CX-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305CX-FCC | 95600-AP305CX-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305CX-IL | 95600-AP305CX-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP305CX-WR | 95600-AP305CX-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310e-1-WR | 95600-AP310e-1-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310e-CAN | 95600-AP310e-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310e-FCC | 95600-AP310e-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310e-IL | 95600-AP310e-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310e-WR | 95600-AP310e-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310i-1-WR | 95600-AP310i-1-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310i-CAN | 95600-AP310i-CAN | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP TAC OS AP310i-FCC | 95600-AP310i-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310i-IL | 95600-AP310i-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP310i-WR | 95600-AP310i-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP360e-CAN | 95600-AP360e-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |

| | | | | |
|-------------------------|--------------------|----------|----|----------------|
| PWP TAC OS AP360e-FCC | 95600-AP360e-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP360e-IL | 95600-AP360e-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP360e-WR | 95600-AP360e-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP360i-CAN | 95600-AP360i-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP360i-FCC | 95600-AP360i-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP360i-WR | 95600-AP360i-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP4000-WW | 95600-AP4000-1-WW | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP4000-IL | 95600-AP4000-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP4000-WW | 95600-AP4000-WW | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-1-CAN | 95600-AP410C-1-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-1-EG | 95600-AP410C-1-EG | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-1-FCC | 95600-AP410C-1-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-1-IL | 95600-AP410C-1-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-1-WR | 95600-AP410C-1-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-CAN | 95600-AP410C-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-EG | 95600-AP410C-EG | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-FCC | 95600-AP410C-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-IL | 95600-AP410C-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410C-WR | 95600-AP410C-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410e-CAN | 95600-AP410e-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |

| | | | | |
|-------------------------|--------------------|----------|----|----------------|
| PWP TAC OS AP410e-FCC | 95600-AP410e-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410e-WR | 95600-AP410e-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410i-1-FCC | 95600-AP410i-1-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410i-1-WR | 95600-AP410i-1-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410i-CAN | 95600-AP410i-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410i-FCC | 95600-AP410i-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410i-IL | 95600-AP410i-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP410i-WR | 95600-AP410i-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460C-CAN | 95600-AP460C-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460C-EG | 95600-AP460C-EG | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460C-FCC | 95600-AP460C-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460C-IL | 95600-AP460C-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460C-WR | 95600-AP460C-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460e-CAN | 95600-AP460e-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460e-FCC | 95600-AP460e-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460e-WR | 95600-AP460e-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460i-CAN | 95600-AP460i-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460i-FCC | 95600-AP460i-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460i-IL | 95600-AP460i-IL | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP460i-WR | 95600-AP460i-WR | \$ 30.00 | 6% | <i>\$28.41</i> |

| | | | | |
|---------------------------|----------------------|----------|----|---------|
| PWP TAC OS AP460S12C-CAN | 95600-AP460S12C-CAN | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP460S12C-FCC | 95600-AP460S12C-FCC | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP460S12C-WR | 95600-AP460S12C-WR | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP460S6C-CAN | 95600-AP460S6C-CAN | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP460S6C-FCC | 95600-AP460S6C-FCC | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP460S6C-WR | 95600-AP460S6C-WR | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP5010-IL | 95600-AP5010-IL | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP5010-WW | 95600-AP5010-WW | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP5020-WW | 95600-AP5020-WW | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP5050D-WW | 95600-AP5050D-WW | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP5050U-WW | 95600-AP5050U-WW | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP505i-FCC | 95600-AP505i-FCC | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP505i-FCC-TAA | 95600-AP505i-FCC-TAA | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP505i-WR | 95600-AP505i-WR | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP510C-CAN | 95600-AP510C-CAN | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP510C-CE | 95600-AP510C-CE | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP510C-FCC | 95600-AP510C-FCC | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS AP510C-W | 95600-AP510C-W | \$ 30.00 | 6% | \$28.41 |

| | | | | |
|---------------------------|----------------------|----------|----|----------------|
| PWP TAC OS AP510C-WW | 95600-AP510C-WW | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510CX-CAN | 95600-AP510CX-CAN | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510CX-CE | 95600-AP510CX-CE | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510CX-FCC | 95600-AP510CX-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510CX-W | 95600-AP510CX-W | \$ 31.00 | 6% | <i>\$29.36</i> |
| PWP TAC OS AP510CX-WW | 95600-AP510CX-WW | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510e-FCC | 95600-AP510e-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510e-FCC-TAA | 95600-AP510e-FCC-TAA | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510e-WR | 95600-AP510e-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510i-1-FCC | 95600-AP510i-1-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510i-1-WR | 95600-AP510i-1-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510i-FCC | 95600-AP510i-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510i-FCC-TAA | 95600-AP510i-FCC-TAA | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP510i-WR | 95600-AP510i-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP560h-FCC | 95600-AP560h-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP560h-WR | 95600-AP560h-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP560i-FCC | 95600-AP560i-FCC | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP560i-WR | 95600-AP560i-WR | \$ 30.00 | 6% | <i>\$28.41</i> |
| PWP TAC OS AP560m-FCC | 95600-AP560m-FCC | \$ 25.00 | 6% | <i>\$23.68</i> |

| | | | | |
|--------------------------------|---------------------------|-------------|----|------------|
| PWP TAC OS AP560t-FCC | 95600-AP560t-FCC | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS AP560u-FCC | 95600-AP560u-FCC | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS E2122 | 95600-E2122 | \$ 2,374.00 | 6% | \$2,248.30 |
| PWP TAC OS E2122-1 | 95600-E2122-1 | \$ 2,250.00 | 6% | \$2,130.86 |
| PWP TAC OS E3120-1 | 95600-E3120-1 | \$ 3,681.00 | 6% | \$3,486.09 |
| PWP TAC OS E3125 | 95600-E3125 | \$ 3,973.00 | 6% | \$3,762.63 |
| PWP TAC OS EXOS-AVB-FP-X435 | 95600-EXOS-AVB-FP-X435 | \$ 49.00 | 6% | \$46.41 |
| PWP TAC OS EXOS-AVB-FP-X465 | 95600-EXOS-AVB-FP-X465 | \$ 90.00 | 6% | \$85.23 |
| PWP TAC OS EXOS-CORE-FP-X695 | 95600-EXOS-CORE-FP-X695 | \$ 494.00 | 6% | \$467.84 |
| PWP TAC OS EXOS-MACSEC-FP-X695 | 95600-EXOS-MACSEC-FP-X695 | \$ 106.00 | 6% | \$100.39 |
| PWP Software and TAC | 95600-H30003 | \$ 29.00 | 6% | \$27.46 |
| PWP Software and TAC | 95600-H30004 | \$ 36.00 | 6% | \$34.09 |
| PWP Software and TAC | 95600-H30005 | \$ 33.00 | 6% | \$31.25 |
| PWP Software and TAC | 95600-H30006 | \$ 63.00 | 6% | \$59.66 |
| PWP Software and TAC | 95600-H30007 | \$ 57.00 | 6% | \$53.98 |
| PWP Software and TAC | 95600-H30008 | \$ 106.00 | 6% | \$100.39 |
| PWP Software and TAC | 95600-H30009 | \$ 29.00 | 6% | \$27.46 |
| PWP Software and TAC | 95600-H30010 | \$ 52.00 | 6% | \$49.25 |
| PWP Software and TAC | 95600-H30011 | \$ 44.00 | 6% | \$41.67 |
| PWP Software and TAC | 95600-H30012 | \$ 73.00 | 6% | \$69.13 |
| PWP Software and TAC | 95600-H30078 | \$ 1,242.00 | 6% | \$1,176.24 |
| PWP Software and TAC | 95600-H30104 | \$ 1,148.00 | 6% | \$1,087.21 |
| PWP Software and TAC | 95600-H30105 | \$ 1,105.00 | 6% | \$1,046.49 |
| PWP Software and TAC | 95600-H30131 | \$ 625.00 | 6% | \$591.91 |
| PWP Software and TAC | 95600-H30132 | \$ 612.00 | 6% | \$579.59 |
| PWP Software and TAC | 95600-H30133 | \$ 1,601.00 | 6% | \$1,516.23 |
| PWP Software and TAC | 95600-H30134 | \$ 2,029.00 | 6% | \$1,921.56 |
| PWP Software and TAC | 95600-H30135 | \$ 1,633.00 | 6% | \$1,546.53 |
| PWP Software and TAC | 95600-H30136 | \$ 2,029.00 | 6% | \$1,921.56 |
| PWP Software and TAC | 95600-H30184 | \$ 33.00 | 6% | \$31.25 |
| PWP Software and TAC | 95600-H30185 | \$ 152.00 | 6% | \$143.95 |
| PWP Software and TAC | 95600-H30186 | \$ 77.00 | 6% | \$72.92 |
| PWP Software and TAC | 95600-H30187 | \$ 35.00 | 6% | \$33.15 |
| PWP Software and TAC | 95600-H30188 | \$ 77.00 | 6% | \$72.92 |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PWP Software and TAC | 95600-H30189 | \$ 77.00 | 6% | <i>\$72.92</i> |
| PWP Software and TAC | 95600-H30190 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30214 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP Software and TAC | 95600-H30215 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP Software and TAC | 95600-H30216 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30217 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30218 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30219 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30220 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30221 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30222 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30223 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30224 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30225 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30226 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30227 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30228 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30229 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30267 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30268 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP Software and TAC | 95600-H30269 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30270 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30271 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30272 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30273 | \$ 336.00 | 6% | <i>\$318.21</i> |
| PWP Software and TAC | 95600-H30274 | \$ 336.00 | 6% | <i>\$318.21</i> |
| PWP Software and TAC | 95600-H30275 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30276 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30277 | \$ 336.00 | 6% | <i>\$318.21</i> |
| PWP Software and TAC | 95600-H30278 | \$ 365.00 | 6% | <i>\$345.67</i> |
| PWP Software and TAC | 95600-H30279 | \$ 336.00 | 6% | <i>\$318.21</i> |
| PWP Software and TAC | 95600-H30280 | \$ 336.00 | 6% | <i>\$318.21</i> |
| PWP Software and TAC | 95600-H30281 | \$ 352.00 | 6% | <i>\$333.36</i> |
| PWP Software and TAC | 95600-H30282 | \$ 336.00 | 6% | <i>\$318.21</i> |
| PWP Software and TAC | 95600-H30283 | \$ 226.00 | 6% | <i>\$214.03</i> |
| PWP Software and TAC | 95600-H30284 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Software and TAC | 95600-H30293 | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| PWP Software and TAC | 95600-H30296 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP Software and TAC | 95600-H30297 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP Software and TAC | 95600-H30298 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP Software and TAC | 95600-H30299 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP Software and TAC | 95600-H30380 | \$ 2,179.00 | 6% | <i>\$2,063.62</i> |

| | | | | |
|----------------------|--------------|-------------|----|-------------------|
| PWP Software and TAC | 95600-H30381 | \$ 222.00 | 6% | <i>\$210.25</i> |
| PWP Software and TAC | 95600-H30383 | \$ 1,008.00 | 6% | <i>\$954.63</i> |
| PWP Software and TAC | 95600-H30384 | \$ 176.00 | 6% | <i>\$166.68</i> |
| PWP Software and TAC | 95600-H30391 | \$ 423.00 | 6% | <i>\$400.60</i> |
| PWP Software and TAC | 95600-H30392 | \$ 423.00 | 6% | <i>\$400.60</i> |
| PWP Software and TAC | 95600-H30393 | \$ 192.00 | 6% | <i>\$181.83</i> |
| PWP Software and TAC | 95600-H30394 | \$ 810.00 | 6% | <i>\$767.11</i> |
| PWP Software and TAC | 95600-H30395 | \$ 963.00 | 6% | <i>\$912.01</i> |
| PWP Software and TAC | 95600-H30396 | \$ 880.00 | 6% | <i>\$833.40</i> |
| PWP Software and TAC | 95600-H30397 | \$ 1,047.00 | 6% | <i>\$991.56</i> |
| PWP Software and TAC | 95600-H30398 | \$ 196.00 | 6% | <i>\$185.62</i> |
| PWP Software and TAC | 95600-H30400 | \$ 109.00 | 6% | <i>\$103.23</i> |
| PWP Software and TAC | 95600-H30401 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP Software and TAC | 95600-H30402 | \$ 161.00 | 6% | <i>\$152.48</i> |
| PWP Software and TAC | 95600-H30403 | \$ 237.00 | 6% | <i>\$224.45</i> |
| PWP Software and TAC | 95600-H30434 | \$ 68.00 | 6% | <i>\$64.40</i> |
| PWP Software and TAC | 95600-H30480 | \$ 275.00 | 6% | <i>\$260.44</i> |
| PWP Software and TAC | 95600-H30495 | \$ 625.00 | 6% | <i>\$591.91</i> |
| PWP Software and TAC | 95600-H30496 | \$ 612.00 | 6% | <i>\$579.59</i> |
| PWP Software and TAC | 95600-H30497 | \$ 898.00 | 6% | <i>\$850.45</i> |
| PWP Software and TAC | 95600-H30498 | \$ 880.00 | 6% | <i>\$833.40</i> |
| PWP Software and TAC | 95600-H30499 | \$ 299.00 | 6% | <i>\$283.17</i> |
| PWP Software and TAC | 95600-H30501 | \$ 880.00 | 6% | <i>\$833.40</i> |
| PWP Software and TAC | 95600-H30502 | \$ 1,353.00 | 6% | <i>\$1,281.36</i> |
| PWP Software and TAC | 95600-H30503 | \$ 299.00 | 6% | <i>\$283.17</i> |
| PWP Software and TAC | 95600-H30505 | \$ 1,601.00 | 6% | <i>\$1,516.23</i> |
| PWP Software and TAC | 95600-H30506 | \$ 2,182.00 | 6% | <i>\$2,066.46</i> |
| PWP Software and TAC | 95600-H30509 | \$ 1,353.00 | 6% | <i>\$1,281.36</i> |
| PWP Software and TAC | 95600-H30510 | \$ 1,601.00 | 6% | <i>\$1,516.23</i> |
| PWP Software and TAC | 95600-H30511 | \$ 2,182.00 | 6% | <i>\$2,066.46</i> |
| PWP Software and TAC | 95600-H30512 | \$ 299.00 | 6% | <i>\$283.17</i> |
| PWP Software and TAC | 95600-H30513 | \$ 508.00 | 6% | <i>\$481.10</i> |
| PWP Software and TAC | 95600-H30525 | \$ 2,182.00 | 6% | <i>\$2,066.46</i> |
| PWP Software and TAC | 95600-H30526 | \$ 1,601.00 | 6% | <i>\$1,516.23</i> |
| PWP Software and TAC | 95600-H30528 | \$ 2,533.00 | 6% | <i>\$2,398.88</i> |
| PWP Software and TAC | 95600-H30531 | \$ 3,598.00 | 6% | <i>\$3,407.49</i> |
| PWP Software and TAC | 95600-H30532 | \$ 3,598.00 | 6% | <i>\$3,407.49</i> |
| PWP Software and TAC | 95600-H30534 | \$ 3,668.00 | 6% | <i>\$3,473.78</i> |
| PWP Software and TAC | 95600-H30535 | \$ 3,908.00 | 6% | <i>\$3,701.07</i> |
| PWP Software and TAC | 95600-H30536 | \$ 3,598.00 | 6% | <i>\$3,407.49</i> |
| PWP Software and TAC | 95600-H30537 | \$ 3,908.00 | 6% | <i>\$3,701.07</i> |
| PWP Software and TAC | 95600-H30538 | \$ 2,182.00 | 6% | <i>\$2,066.46</i> |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| PWP Software and TAC | 95600-H30539 | \$ 4,176.00 | 6% | \$3,954.88 |
| PWP Software and TAC | 95600-H30540 | \$ 4,318.00 | 6% | \$4,089.36 |
| PWP Software and TAC | 95600-H30543 | \$ 294.00 | 6% | \$278.43 |
| PWP Software and TAC | 95600-H30544 | \$ 524.00 | 6% | \$496.25 |
| PWP Software and TAC | 95600-H30548 | \$ 294.00 | 6% | \$278.43 |
| PWP Software and TAC | 95600-H30549 | \$ 499.00 | 6% | \$472.58 |
| PWP Software and TAC | 95600-H30550 | \$ 499.00 | 6% | \$472.58 |
| PWP Software and TAC | 95600-H30552 | \$ 294.00 | 6% | \$278.43 |
| PWP Software and TAC | 95600-H30553 | \$ 466.00 | 6% | \$441.33 |
| PWP Software and TAC | 95600-H30569 | \$ 1,601.00 | 6% | \$1,516.23 |
| PWP Software and TAC | 95600-H30570 | \$ 1,924.00 | 6% | \$1,822.12 |
| PWP Software and TAC | 95600-H30571 | \$ 1,924.00 | 6% | \$1,822.12 |
| PWP Software and TAC | 95600-H30573 | \$ 1,601.00 | 6% | \$1,516.23 |
| PWP Software and TAC | 95600-H30574 | \$ 1,775.00 | 6% | \$1,681.01 |
| PWP Software and TAC | 95600-H30575 | \$ 1,105.00 | 6% | \$1,046.49 |
| PWP Software and TAC | 95600-H30576 | \$ 1,601.00 | 6% | \$1,516.23 |
| PWP Software and TAC | 95600-H30577 | \$ 1,924.00 | 6% | \$1,822.12 |
| PWP Software and TAC | 95600-H30578 | \$ 1,924.00 | 6% | \$1,822.12 |
| PWP Software and TAC | 95600-H30587 | \$ 1,633.00 | 6% | \$1,546.53 |
| PWP Software and TAC | 95600-H30588 | \$ 1,125.00 | 6% | \$1,065.43 |
| PWP Software and TAC | 95600-H30589 | \$ 1,745.00 | 6% | \$1,652.60 |
| PWP Software and TAC | 95600-H30591 | \$ 3,027.00 | 6% | \$2,866.72 |
| PWP Software and TAC | 95600-H30632 | \$ 30.00 | 6% | \$28.41 |
| PWP Software and TAC | 95600-H30633 | \$ 30.00 | 6% | \$28.41 |
| PWP Software and TAC | 95600-H30643 | \$ 2,752.00 | 6% | \$2,606.28 |
| PWP Software and TAC | 95600-H30706 | \$ 2,581.00 | 6% | \$2,444.34 |
| PWP Software and TAC | 95600-H30707 | \$ 1,601.00 | 6% | \$1,516.23 |
| PWP Software and TAC | 95600-H30724 | \$ 30.00 | 6% | \$28.41 |
| PWP Software and TAC | 95600-H30725 | \$ 612.00 | 6% | \$579.59 |
| PWP Software and TAC | 95600-H30726 | \$ 3,986.00 | 6% | \$3,774.94 |
| PWP Software and TAC | 95600-H30727 | \$ 4,235.00 | 6% | \$4,010.76 |
| PWP Software and TAC | 95600-H30730 | \$ 30.00 | 6% | \$28.41 |
| PWP Software and TAC | 95600-H30731 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS 30732 | 95600-H30732 | \$ 970.00 | 6% | \$918.64 |
| PWP TAC OS SKL8008-0810-F8 | 95600-H30733 | \$ 3,745.00 | 6% | \$3,546.70 |
| PWP TAC OS STL2006-0850 | 95600-H30734 | \$ 2,857.00 | 6% | \$2,705.72 |
| PWP TAC OS SGL2001-0850 | 95600-H30735 | \$ 3,329.00 | 6% | \$3,152.73 |
| PWP TAC OS SOK2209-0204 | 95600-H30736 | \$ 524.00 | 6% | \$496.25 |
| PWP TAC OS H30738 | 95600-H30738 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS -H30739 | 95600-H30739 | \$ 552.00 | 6% | \$522.77 |
| PWP TAC OS -H30740 | 95600-H30740 | \$ 320.00 | 6% | \$303.06 |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PWP TAC OS -H30741 | 95600-H30741 | \$ 592.00 | 6% | \$560.65 |
| PWP TAC OS -H30742 | 95600-H30742 | \$ 527.00 | 6% | \$499.10 |
| PWP TAC OS -H30743 | 95600-H30743 | \$ 552.00 | 6% | \$522.77 |
| PWP TAC OS -H30744 | 95600-H30744 | \$ 320.00 | 6% | \$303.06 |
| PWP TAC OS -H30745 | 95600-H30745 | \$ 327.00 | 6% | \$309.69 |
| PWP TAC OS -H30746 | 95600-H30746 | \$ 592.00 | 6% | \$560.65 |
| PWP TAC OS -H30747 | 95600-H30747 | \$ 1,155.00 | 6% | \$1,093.84 |
| PWP TAC OS -H30748 | 95600-H30748 | \$ 1,718.00 | 6% | \$1,627.03 |
| PWP TAC OS -H30749 | 95600-H30749 | \$ 3,849.00 | 6% | \$3,645.20 |
| PWP TAC OS -H30750 | 95600-H30750 | \$ 3,849.00 | 6% | \$3,645.20 |
| PWP TAC OS -H30751 | 95600-H30751 | \$ 2,291.00 | 6% | \$2,169.69 |
| PWP TAC OS -H30754 | 95600-H30754 | \$ 3,849.00 | 6% | \$3,645.20 |
| PWP TAC OS -H30755 | 95600-H30755 | \$ 4,186.00 | 6% | \$3,964.35 |
| PWP TAC OS -H30756 | 95600-H30756 | \$ 3,849.00 | 6% | \$3,645.20 |
| PWP TAC OS -H30757 | 95600-H30757 | \$ 1,718.00 | 6% | \$1,627.03 |
| PWP TAC OS -H30758 | 95600-H30758 | \$ 3,063.00 | 6% | \$2,900.81 |
| PWP TAC OS -H30759 | 95600-H30759 | \$ 3,499.00 | 6% | \$3,313.73 |
| PWP TAC OS -H30760 | 95600-H30760 | \$ 3,933.00 | 6% | \$3,724.75 |
| PWP TAC OS -H30761 | 95600-H30761 | \$ 1,718.00 | 6% | \$1,627.03 |
| PWP TAC OS -H30762 | 95600-H30762 | \$ 4,186.00 | 6% | \$3,964.35 |
| PWP TAC OS -H30763 | 95600-H30763 | \$ 4,186.00 | 6% | \$3,964.35 |
| PWP TAC OS -H30764 | 95600-H30764 | \$ 2,652.00 | 6% | \$2,511.58 |
| PWP TAC OS -H30765 | 95600-H30765 | \$ 2,334.00 | 6% | \$2,210.41 |
| PWP TAC OS -H30766 | 95600-H30766 | \$ 4,532.00 | 6% | \$4,292.03 |
| PWP TAC OS -H30767 | 95600-H30767 | \$ 2,652.00 | 6% | \$2,511.58 |
| PWP TAC OS H30769 | 95600-H30769 | \$ 1,231.00 | 6% | \$1,165.82 |
| PWP TAC OS H30773 | 95600-H30773 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30774 | 95600-H30774 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30775 | 95600-H30775 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30776 | 95600-H30776 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30777 | 95600-H30777 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30778 | 95600-H30778 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30779 | 95600-H30779 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30780 | 95600-H30780 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30781 | 95600-H30781 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30782 | 95600-H30782 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30783 | 95600-H30783 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30784 | 95600-H30784 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30785 | 95600-H30785 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30786 | 95600-H30786 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30787 | 95600-H30787 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30788 | 95600-H30788 | \$ 30.00 | 6% | \$28.41 |

| | | | | | |
|-------------------|--------------|----|-------|----|---------|
| PWP TAC OS H30789 | 95600-H30789 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30790 | 95600-H30790 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30791 | 95600-H30791 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30793 | 95600-H30793 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30794 | 95600-H30794 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30795 | 95600-H30795 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30796 | 95600-H30796 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30797 | 95600-H30797 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30798 | 95600-H30798 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30799 | 95600-H30799 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30800 | 95600-H30800 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30801 | 95600-H30801 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30802 | 95600-H30802 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30803 | 95600-H30803 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30804 | 95600-H30804 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30805 | 95600-H30805 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30806 | 95600-H30806 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30807 | 95600-H30807 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30808 | 95600-H30808 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30809 | 95600-H30809 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30810 | 95600-H30810 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30811 | 95600-H30811 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30812 | 95600-H30812 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30813 | 95600-H30813 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30814 | 95600-H30814 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30815 | 95600-H30815 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30816 | 95600-H30816 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30817 | 95600-H30817 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30818 | 95600-H30818 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30819 | 95600-H30819 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30820 | 95600-H30820 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30821 | 95600-H30821 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30822 | 95600-H30822 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30823 | 95600-H30823 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30824 | 95600-H30824 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30825 | 95600-H30825 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30826 | 95600-H30826 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30827 | 95600-H30827 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30828 | 95600-H30828 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30829 | 95600-H30829 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30830 | 95600-H30830 | \$ | 30.00 | 6% | \$28.41 |
| PWP TAC OS H30831 | 95600-H30831 | \$ | 30.00 | 6% | \$28.41 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H30838 | 95600-H30838 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30839 | 95600-H30839 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30840 | 95600-H30840 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30841 | 95600-H30841 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30842 | 95600-H30842 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30843 | 95600-H30843 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30844 | 95600-H30844 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30845 | 95600-H30845 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30846 | 95600-H30846 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30847 | 95600-H30847 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30848 | 95600-H30848 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30849 | 95600-H30849 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30850 | 95600-H30850 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30851 | 95600-H30851 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30852 | 95600-H30852 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30853 | 95600-H30853 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30854 | 95600-H30854 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30855 | 95600-H30855 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30856 | 95600-H30856 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30857 | 95600-H30857 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30858 | 95600-H30858 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30859 | 95600-H30859 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30860 | 95600-H30860 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30866 | 95600-H30866 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30867 | 95600-H30867 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30868 | 95600-H30868 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30869 | 95600-H30869 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30870 | 95600-H30870 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30871 | 95600-H30871 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30872 | 95600-H30872 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30873 | 95600-H30873 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30874 | 95600-H30874 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30875 | 95600-H30875 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30876 | 95600-H30876 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30877 | 95600-H30877 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30878 | 95600-H30878 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30891 | 95600-H30891 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30892 | 95600-H30892 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30893 | 95600-H30893 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30894 | 95600-H30894 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30895 | 95600-H30895 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30913 | 95600-H30913 | \$ 30.00 | 6% | \$28.41 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H30914 | 95600-H30914 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30915 | 95600-H30915 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30916 | 95600-H30916 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30917 | 95600-H30917 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30918 | 95600-H30918 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30946 | 95600-H30946 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30948 | 95600-H30948 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30950 | 95600-H30950 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30951 | 95600-H30951 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30952 | 95600-H30952 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30966 | 95600-H30966 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30967 | 95600-H30967 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30968 | 95600-H30968 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30969 | 95600-H30969 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30970 | 95600-H30970 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30971 | 95600-H30971 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30972 | 95600-H30972 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30973 | 95600-H30973 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30974 | 95600-H30974 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30975 | 95600-H30975 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30976 | 95600-H30976 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30977 | 95600-H30977 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H30978 | 95600-H30978 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31040 | 95600-H31040 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31041 | 95600-H31041 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31042 | 95600-H31042 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31047 | 95600-H31047 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31060 | 95600-H31060 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31062 | 95600-H31062 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31066 | 95600-H31066 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31068 | 95600-H31068 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31076 | 95600-H31076 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31077 | 95600-H31077 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31078 | 95600-H31078 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31119 | 95600-H31119 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31124 | 95600-H31124 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31127 | 95600-H31127 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31132 | 95600-H31132 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31134 | 95600-H31134 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31135 | 95600-H31135 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31136 | 95600-H31136 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31137 | 95600-H31137 | \$ 30.00 | 6% | \$28.41 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PWP TAC OS H31185 | 95600-H31185 | \$ 24.00 | 6% | \$22.73 |
| PWP TAC OS H31192 | 95600-H31192 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H31193 | 95600-H31193 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H31194 | 95600-H31194 | \$ 23.00 | 6% | \$21.78 |
| PWP TAC OS H31197 | 95600-H31197 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31198 | 95600-H31198 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31199 | 95600-H31199 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31200 | 95600-H31200 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31201 | 95600-H31201 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31202 | 95600-H31202 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31203 | 95600-H31203 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31204 | 95600-H31204 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31205 | 95600-H31205 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31206 | 95600-H31206 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31207 | 95600-H31207 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31208 | 95600-H31208 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31335 | 95600-H31335 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31337 | 95600-H31337 | \$ 4,149.00 | 6% | \$3,929.31 |
| PWP TAC OS H31338 | 95600-H31338 | \$ 4,149.00 | 6% | \$3,929.31 |
| PWP TAC OS H31339 | 95600-H31339 | \$ 655.00 | 6% | \$620.32 |
| PWP TAC OS H31340 | 95600-H31340 | \$ 1,409.00 | 6% | \$1,334.39 |
| PWP TAC OS H31341 | 95600-H31341 | \$ 2,136.00 | 6% | \$2,022.90 |
| PWP TAC OS H31342 | 95600-H31342 | \$ 672.00 | 6% | \$636.42 |
| PWP TAC OS H31343 | 95600-H31343 | \$ 996.00 | 6% | \$943.26 |
| PWP TAC OS H31344 | 95600-H31344 | \$ 996.00 | 6% | \$943.26 |
| PWP TAC OS H31345 | 95600-H31345 | \$ 996.00 | 6% | \$943.26 |
| PWP TAC OS H31346 | 95600-H31346 | \$ 996.00 | 6% | \$943.26 |
| PWP TAC OS H31348 | 95600-H31348 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31349 | 95600-H31349 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31350 | 95600-H31350 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31351 | 95600-H31351 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31352 | 95600-H31352 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31353 | 95600-H31353 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31354 | 95600-H31354 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31355 | 95600-H31355 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31356 | 95600-H31356 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31357 | 95600-H31357 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31358 | 95600-H31358 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31359 | 95600-H31359 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31360 | 95600-H31360 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31362 | 95600-H31362 | \$ 5,325.00 | 6% | \$5,043.04 |
| PWP TAC OS H31363 | 95600-H31363 | \$ 5,325.00 | 6% | \$5,043.04 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PWP TAC OS H31364 | 95600-H31364 | \$ 1,865.00 | 6% | \$1,766.25 |
| PWP TAC OS H31365 | 95600-H31365 | \$ 1,865.00 | 6% | \$1,766.25 |
| PWP TAC OS H31366 | 95600-H31366 | \$ 5,163.00 | 6% | \$4,889.62 |
| PWP TAC OS H31367 | 95600-H31367 | \$ 5,163.00 | 6% | \$4,889.62 |
| PWP TAC OS H31368 | 95600-H31368 | \$ 229.00 | 6% | \$216.87 |
| PWP TAC OS H31369 | 95600-H31369 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31370 | 95600-H31370 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H31393 | 95600-H31393 | \$ 30.00 | 6% | \$28.41 |
| PWP TAC OS H32010 | 95600-H32010 | \$ 152.00 | 6% | \$143.95 |
| PWP TAC OS H32011 | 95600-H32011 | \$ 152.00 | 6% | \$143.95 |
| PWP TAC OS H32012 | 95600-H32012 | \$ 665.00 | 6% | \$629.79 |
| PWP TAC OS H32013 | 95600-H32013 | \$ 665.00 | 6% | \$629.79 |
| PWP TAC OS H32014 | 95600-H32014 | \$ 665.00 | 6% | \$629.79 |
| PWP TAC OS H32015 | 95600-H32015 | \$ 665.00 | 6% | \$629.79 |
| PWP TAC OS H32016 | 95600-H32016 | \$ 561.00 | 6% | \$531.30 |
| PWP TAC OS H32017 | 95600-H32017 | \$ 561.00 | 6% | \$531.30 |
| PWP TAC OS H32018 | 95600-H32018 | \$ 561.00 | 6% | \$531.30 |
| PWP TAC OS H32019 | 95600-H32019 | \$ 561.00 | 6% | \$531.30 |
| PWP TAC OS H32020 | 95600-H32020 | \$ 5,821.00 | 6% | \$5,512.78 |
| PWP TAC OS H32021 | 95600-H32021 | \$ 5,821.00 | 6% | \$5,512.78 |
| PWP TAC OS H32022 | 95600-H32022 | \$ 5,821.00 | 6% | \$5,512.78 |
| PWP TAC OS H32023 | 95600-H32023 | \$ 5,821.00 | 6% | \$5,512.78 |
| PWP TAC OS H32028 | 95600-H32028 | \$ 10,767.00 | 6% | \$10,196.89 |
| PWP TAC OS H32029 | 95600-H32029 | \$ 10,767.00 | 6% | \$10,196.89 |
| PWP TAC OS H32030 | 95600-H32030 | \$ 11,774.00 | 6% | \$11,150.57 |
| PWP TAC OS H32031 | 95600-H32031 | \$ 11,774.00 | 6% | \$11,150.57 |
| PWP TAC OS H32032 | 95600-H32032 | \$ 11,774.00 | 6% | \$11,150.57 |
| PWP TAC OS H32033 | 95600-H32033 | \$ 11,774.00 | 6% | \$11,150.57 |
| PWP TAC OS H32038 | 95600-H32038 | \$ 2,039.00 | 6% | \$1,931.03 |
| PWP TAC OS H32039 | 95600-H32039 | \$ 2,039.00 | 6% | \$1,931.03 |
| PWP TAC OS H32040 | 95600-H32040 | \$ 2,039.00 | 6% | \$1,931.03 |
| PWP TAC OS H32041 | 95600-H32041 | \$ 2,039.00 | 6% | \$1,931.03 |
| PWP TAC OS H32046 | 95600-H32046 | \$ 2,822.00 | 6% | \$2,672.58 |
| PWP TAC OS H32047 | 95600-H32047 | \$ 2,822.00 | 6% | \$2,672.58 |
| PWP TAC OS H32048 | 95600-H32048 | \$ 2,822.00 | 6% | \$2,672.58 |
| PWP TAC OS H32049 | 95600-H32049 | \$ 2,822.00 | 6% | \$2,672.58 |
| PWP TAC OS H32054 | 95600-H32054 | \$ 2,039.00 | 6% | \$1,931.03 |
| PWP TAC OS H32055 | 95600-H32055 | \$ 2,822.00 | 6% | \$2,672.58 |
| PWP TAC OS H32056 | 95600-H32056 | \$ 609.00 | 6% | \$576.75 |
| PWP TAC OS H32057 | 95600-H32057 | \$ 609.00 | 6% | \$576.75 |
| PWP TAC OS H32058 | 95600-H32058 | \$ 609.00 | 6% | \$576.75 |
| PWP TAC OS H32059 | 95600-H32059 | \$ 609.00 | 6% | \$576.75 |

| | | | | |
|-------------------|--------------|--------------|----|-------------|
| PWP TAC OS H32060 | 95600-H32060 | \$ 786.00 | 6% | \$744.38 |
| PWP TAC OS H32061 | 95600-H32061 | \$ 825.00 | 6% | \$781.32 |
| PWP TAC OS H32062 | 95600-H32062 | \$ 794.00 | 6% | \$751.96 |
| PWP TAC OS H32063 | 95600-H32063 | \$ 788.00 | 6% | \$746.28 |
| PWP TAC OS H32064 | 95600-H32064 | \$ 794.00 | 6% | \$751.96 |
| PWP TAC OS H32065 | 95600-H32065 | \$ 1,882.00 | 6% | \$1,782.35 |
| PWP TAC OS H32066 | 95600-H32066 | \$ 1,882.00 | 6% | \$1,782.35 |
| PWP TAC OS H32067 | 95600-H32067 | \$ 1,882.00 | 6% | \$1,782.35 |
| PWP TAC OS H32068 | 95600-H32068 | \$ 1,882.00 | 6% | \$1,782.35 |
| PWP TAC OS H32069 | 95600-H32069 | \$ 2,344.00 | 6% | \$2,219.89 |
| PWP TAC OS H32070 | 95600-H32070 | \$ 2,344.00 | 6% | \$2,219.89 |
| PWP TAC OS H32071 | 95600-H32071 | \$ 2,344.00 | 6% | \$2,219.89 |
| PWP TAC OS H32072 | 95600-H32072 | \$ 2,344.00 | 6% | \$2,219.89 |
| PWP TAC OS H32073 | 95600-H32073 | \$ 8,267.00 | 6% | \$7,829.26 |
| PWP TAC OS H32074 | 95600-H32074 | \$ 8,267.00 | 6% | \$7,829.26 |
| PWP TAC OS H32075 | 95600-H32075 | \$ 11,237.00 | 6% | \$10,642.00 |
| PWP TAC OS H32076 | 95600-H32076 | \$ 11,237.00 | 6% | \$10,642.00 |
| PWP TAC OS H32090 | 95600-H32090 | \$ 1,074.00 | 6% | \$1,017.13 |
| PWP TAC OS H32097 | 95600-H32097 | \$ 2,545.00 | 6% | \$2,410.24 |
| PWP TAC OS H32101 | 95600-H32101 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32102 | 95600-H32102 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32103 | 95600-H32103 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32104 | 95600-H32104 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32105 | 95600-H32105 | \$ 728.00 | 6% | \$689.45 |
| PWP TAC OS H32106 | 95600-H32106 | \$ 728.00 | 6% | \$689.45 |
| PWP TAC OS H32107 | 95600-H32107 | \$ 1,981.00 | 6% | \$1,876.11 |
| PWP TAC OS H32108 | 95600-H32108 | \$ 1,981.00 | 6% | \$1,876.11 |
| PWP TAC OS H32109 | 95600-H32109 | \$ 728.00 | 6% | \$689.45 |
| PWP TAC OS H32110 | 95600-H32110 | \$ 728.00 | 6% | \$689.45 |
| PWP TAC OS H32111 | 95600-H32111 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32112 | 95600-H32112 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32113 | 95600-H32113 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32114 | 95600-H32114 | \$ 368.00 | 6% | \$348.51 |
| PWP TAC OS H32115 | 95600-H32115 | \$ 728.00 | 6% | \$689.45 |
| PWP TAC OS H32116 | 95600-H32116 | \$ 728.00 | 6% | \$689.45 |
| PWP TAC OS H32117 | 95600-H32117 | \$ 345.00 | 6% | \$326.73 |
| PWP TAC OS H32118 | 95600-H32118 | \$ 345.00 | 6% | \$326.73 |
| PWP TAC OS H32119 | 95600-H32119 | \$ 345.00 | 6% | \$326.73 |
| PWP TAC OS H32120 | 95600-H32120 | \$ 345.00 | 6% | \$326.73 |
| PWP TAC OS H32121 | 95600-H32121 | \$ 1,981.00 | 6% | \$1,876.11 |
| PWP TAC OS H32122 | 95600-H32122 | \$ 1,981.00 | 6% | \$1,876.11 |
| PWP TAC OS H32123 | 95600-H32123 | \$ 728.00 | 6% | \$689.45 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PWP TAC OS H32124 | 95600-H32124 | \$ 728.00 | 6% | \$689.45 |
| PWP TAC OS H32125 | 95600-H32125 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32126 | 95600-H32126 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32127 | 95600-H32127 | \$ 843.00 | 6% | \$798.36 |
| PWP TAC OS H32128 | 95600-H32128 | \$ 843.00 | 6% | \$798.36 |
| PWP TAC OS H32129 | 95600-H32129 | \$ 843.00 | 6% | \$798.36 |
| PWP TAC OS H32130 | 95600-H32130 | \$ 843.00 | 6% | \$798.36 |
| PWP TAC OS H32131 | 95600-H32131 | \$ 843.00 | 6% | \$798.36 |
| PWP TAC OS H32132 | 95600-H32132 | \$ 843.00 | 6% | \$798.36 |
| PWP TAC OS H32133 | 95600-H32133 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32134 | 95600-H32134 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32135 | 95600-H32135 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32136 | 95600-H32136 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32137 | 95600-H32137 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32138 | 95600-H32138 | \$ 719.00 | 6% | \$680.93 |
| PWP TAC OS H32139 | 95600-H32139 | \$ 3,053.00 | 6% | \$2,891.34 |
| PWP TAC OS H32140 | 95600-H32140 | \$ 3,053.00 | 6% | \$2,891.34 |
| PWP TAC OS H32141 | 95600-H32141 | \$ 3,521.00 | 6% | \$3,334.56 |
| PWP TAC OS H32142 | 95600-H32142 | \$ 3,521.00 | 6% | \$3,334.56 |
| PWP TAC OS H32143 | 95600-H32143 | \$ 177.00 | 6% | \$167.63 |
| PWP TAC OS H32144 | 95600-H32144 | \$ 183.00 | 6% | \$173.31 |
| PWP TAC OS H32146 | 95600-H32146 | \$ 323.00 | 6% | \$305.90 |
| PWP TAC OS H32147 | 95600-H32147 | \$ 323.00 | 6% | \$305.90 |
| PWP TAC OS H32148 | 95600-H32148 | \$ 660.00 | 6% | \$625.05 |
| PWP TAC OS H32149 | 95600-H32149 | \$ 660.00 | 6% | \$625.05 |
| PWP TAC OS H32150 | 95600-H32150 | \$ 323.00 | 6% | \$305.90 |
| PWP TAC OS H32151 | 95600-H32151 | \$ 183.00 | 6% | \$173.31 |
| PWP TAC OS H32152 | 95600-H32152 | \$ 191.00 | 6% | \$180.89 |
| PWP TAC OS H32154 | 95600-H32154 | \$ 306.00 | 6% | \$289.80 |
| PWP TAC OS H32169 | 95600-H32169 | \$ 355.00 | 6% | \$336.20 |
| PWP TAC OS H32170 | 95600-H32170 | \$ 355.00 | 6% | \$336.20 |
| PWP TAC OS H32171 | 95600-H32171 | \$ 336.00 | 6% | \$318.21 |
| PWP TAC OS H32172 | 95600-H32172 | \$ 336.00 | 6% | \$318.21 |
| PWP TAC OS H32173 | 95600-H32173 | \$ 881.00 | 6% | \$834.35 |
| PWP TAC OS H32174 | 95600-H32174 | \$ 881.00 | 6% | \$834.35 |
| PWP TAC OS H32175 | 95600-H32175 | \$ 750.00 | 6% | \$710.29 |
| PWP TAC OS H32176 | 95600-H32176 | \$ 750.00 | 6% | \$710.29 |
| PWP TAC OS H32177 | 95600-H32177 | \$ 3,449.00 | 6% | \$3,266.38 |
| PWP TAC OS H32178 | 95600-H32178 | \$ 3,980.00 | 6% | \$3,769.26 |
| PWP TAC OS H34008 | 95600-H34008 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34009 | 95600-H34009 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34010 | 95600-H34010 | \$ 27.00 | 6% | \$25.57 |

| | | | | |
|-------------------|--------------|-------------|----|-------------------|
| PWP TAC OS H34011 | 95600-H34011 | \$ 53.00 | 6% | <i>\$50.19</i> |
| PWP TAC OS H34012 | 95600-H34012 | \$ 100.00 | 6% | <i>\$94.71</i> |
| PWP TAC OS H34013 | 95600-H34013 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PWP TAC OS H34014 | 95600-H34014 | \$ 62.00 | 6% | <i>\$58.72</i> |
| PWP TAC OS H34015 | 95600-H34015 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP TAC OS H34016 | 95600-H34016 | \$ 70.00 | 6% | <i>\$66.29</i> |
| PWP TAC OS H34017 | 95600-H34017 | \$ 116.00 | 6% | <i>\$109.86</i> |
| PWP TAC OS H34018 | 95600-H34018 | \$ 56.00 | 6% | <i>\$53.03</i> |
| PWP TAC OS H34019 | 95600-H34019 | \$ 56.00 | 6% | <i>\$53.03</i> |
| PWP TAC OS H34020 | 95600-H34020 | \$ 56.00 | 6% | <i>\$53.03</i> |
| PWP TAC OS H34021 | 95600-H34021 | \$ 56.00 | 6% | <i>\$53.03</i> |
| PWP TAC OS H34048 | 95600-H34048 | \$ 163.00 | 6% | <i>\$154.37</i> |
| PWP TAC OS H34049 | 95600-H34049 | \$ 163.00 | 6% | <i>\$154.37</i> |
| PWP TAC OS H34050 | 95600-H34050 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PWP TAC OS H34051 | 95600-H34051 | \$ 117.00 | 6% | <i>\$110.80</i> |
| PWP TAC OS H34052 | 95600-H34052 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PWP TAC OS H34053 | 95600-H34053 | \$ 187.00 | 6% | <i>\$177.10</i> |
| PWP TAC OS H34054 | 95600-H34054 | \$ 141.00 | 6% | <i>\$133.53</i> |
| PWP TAC OS H34055 | 95600-H34055 | \$ 141.00 | 6% | <i>\$133.53</i> |
| PWP TAC OS H34056 | 95600-H34056 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP TAC OS H34057 | 95600-H34057 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP TAC OS H34058 | 95600-H34058 | \$ 184.00 | 6% | <i>\$174.26</i> |
| PWP TAC OS H34059 | 95600-H34059 | \$ 184.00 | 6% | <i>\$174.26</i> |
| PWP TAC OS H34062 | 95600-H34062 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP TAC OS H34063 | 95600-H34063 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP TAC OS H34064 | 95600-H34064 | \$ 193.00 | 6% | <i>\$182.78</i> |
| PWP TAC OS H34065 | 95600-H34065 | \$ 193.00 | 6% | <i>\$182.78</i> |
| PWP TAC OS H34066 | 95600-H34066 | \$ 193.00 | 6% | <i>\$182.78</i> |
| PWP TAC OS H34067 | 95600-H34067 | \$ 193.00 | 6% | <i>\$182.78</i> |
| PWP TAC OS H34068 | 95600-H34068 | \$ 193.00 | 6% | <i>\$182.78</i> |
| PWP TAC OS H34069 | 95600-H34069 | \$ 188.00 | 6% | <i>\$178.05</i> |
| PWP TAC OS H34070 | 95600-H34070 | \$ 193.00 | 6% | <i>\$182.78</i> |
| PWP TAC OS H34071 | 95600-H34071 | \$ 193.00 | 6% | <i>\$182.78</i> |
| PWP TAC OS H34072 | 95600-H34072 | \$ 1,326.00 | 6% | <i>\$1,255.79</i> |
| PWP TAC OS H34073 | 95600-H34073 | \$ 1,310.00 | 6% | <i>\$1,240.64</i> |
| PWP TAC OS H34074 | 95600-H34074 | \$ 1,708.00 | 6% | <i>\$1,617.56</i> |
| PWP TAC OS H34075 | 95600-H34075 | \$ 1,583.00 | 6% | <i>\$1,499.18</i> |
| PWP TAC OS H34076 | 95600-H34076 | \$ 1,326.00 | 6% | <i>\$1,255.79</i> |
| PWP TAC OS H34077 | 95600-H34077 | \$ 1,310.00 | 6% | <i>\$1,240.64</i> |
| PWP TAC OS H34078 | 95600-H34078 | \$ 1,326.00 | 6% | <i>\$1,255.79</i> |
| PWP TAC OS H34079 | 95600-H34079 | \$ 1,310.00 | 6% | <i>\$1,240.64</i> |
| PWP TAC OS H34080 | 95600-H34080 | \$ 1,708.00 | 6% | <i>\$1,617.56</i> |

| | | | | |
|-------------------|--------------|-------------|----|-------------------|
| PWP TAC OS H34081 | 95600-H34081 | \$ 1,639.00 | 6% | <i>\$1,552.21</i> |
| PWP TAC OS H34082 | 95600-H34082 | \$ 1,638.00 | 6% | <i>\$1,551.27</i> |
| PWP TAC OS H34083 | 95600-H34083 | \$ 1,573.00 | 6% | <i>\$1,489.71</i> |
| PWP TAC OS H34084 | 95600-H34084 | \$ 1,457.00 | 6% | <i>\$1,379.85</i> |
| PWP TAC OS H34085 | 95600-H34085 | \$ 1,457.00 | 6% | <i>\$1,379.85</i> |
| PWP TAC OS H34086 | 95600-H34086 | \$ 1,452.00 | 6% | <i>\$1,375.12</i> |
| PWP TAC OS H34087 | 95600-H34087 | \$ 1,393.00 | 6% | <i>\$1,319.24</i> |
| PWP TAC OS H34088 | 95600-H34088 | \$ 2,988.00 | 6% | <i>\$2,829.79</i> |
| PWP TAC OS H34089 | 95600-H34089 | \$ 2,988.00 | 6% | <i>\$2,829.79</i> |
| PWP TAC OS H34090 | 95600-H34090 | \$ 3,286.00 | 6% | <i>\$3,112.01</i> |
| PWP TAC OS H34091 | 95600-H34091 | \$ 1,889.00 | 6% | <i>\$1,788.98</i> |
| PWP TAC OS H34092 | 95600-H34092 | \$ 1,889.00 | 6% | <i>\$1,788.98</i> |
| PWP TAC OS H34093 | 95600-H34093 | \$ 1,889.00 | 6% | <i>\$1,788.98</i> |
| PWP TAC OS H34094 | 95600-H34094 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34095 | 95600-H34095 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34096 | 95600-H34096 | \$ 245.00 | 6% | <i>\$232.03</i> |
| PWP TAC OS H34097 | 95600-H34097 | \$ 245.00 | 6% | <i>\$232.03</i> |
| PWP TAC OS H34098 | 95600-H34098 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34099 | 95600-H34099 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34100 | 95600-H34100 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34101 | 95600-H34101 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34102 | 95600-H34102 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34103 | 95600-H34103 | \$ 214.00 | 6% | <i>\$202.67</i> |
| PWP TAC OS H34104 | 95600-H34104 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP TAC OS H34105 | 95600-H34105 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP TAC OS H34106 | 95600-H34106 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP TAC OS H34107 | 95600-H34107 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP TAC OS H34108 | 95600-H34108 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP TAC OS H34109 | 95600-H34109 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP TAC OS H34110 | 95600-H34110 | \$ 1,743.00 | 6% | <i>\$1,650.71</i> |
| PWP TAC OS H34111 | 95600-H34111 | \$ 1,743.00 | 6% | <i>\$1,650.71</i> |
| PWP TAC OS H34112 | 95600-H34112 | \$ 1,743.00 | 6% | <i>\$1,650.71</i> |
| PWP TAC OS H34114 | 95600-H34114 | \$ 2,288.00 | 6% | <i>\$2,166.85</i> |
| PWP TAC OS H34115 | 95600-H34115 | \$ 2,288.00 | 6% | <i>\$2,166.85</i> |
| PWP TAC OS H34116 | 95600-H34116 | \$ 2,288.00 | 6% | <i>\$2,166.85</i> |
| PWP TAC OS H34117 | 95600-H34117 | \$ 2,288.00 | 6% | <i>\$2,166.85</i> |
| PWP TAC OS H34118 | 95600-H34118 | \$ 575.00 | 6% | <i>\$544.55</i> |
| PWP TAC OS H34119 | 95600-H34119 | \$ 575.00 | 6% | <i>\$544.55</i> |
| PWP TAC OS H34120 | 95600-H34120 | \$ 397.00 | 6% | <i>\$375.98</i> |
| PWP TAC OS H34121 | 95600-H34121 | \$ 397.00 | 6% | <i>\$375.98</i> |
| PWP TAC OS H34122 | 95600-H34122 | \$ 421.00 | 6% | <i>\$398.71</i> |
| PWP TAC OS H34123 | 95600-H34123 | \$ 421.00 | 6% | <i>\$398.71</i> |

| | | | | |
|-------------------|--------------|-----------|----|----------|
| PWP TAC OS H34124 | 95600-H34124 | \$ 635.00 | 6% | \$601.38 |
| PWP TAC OS H34125 | 95600-H34125 | \$ 635.00 | 6% | \$601.38 |
| PWP TAC OS H34126 | 95600-H34126 | \$ 622.00 | 6% | \$589.07 |
| PWP TAC OS H34127 | 95600-H34127 | \$ 622.00 | 6% | \$589.07 |
| PWP TAC OS H34128 | 95600-H34128 | \$ 89.00 | 6% | \$84.29 |
| PWP TAC OS H34129 | 95600-H34129 | \$ 174.00 | 6% | \$164.79 |
| PWP TAC OS H34130 | 95600-H34130 | \$ 188.00 | 6% | \$178.05 |
| PWP TAC OS H34131 | 95600-H34131 | \$ 187.00 | 6% | \$177.10 |
| PWP TAC OS H34132 | 95600-H34132 | \$ 188.00 | 6% | \$178.05 |
| PWP TAC OS H34172 | 95600-H34172 | \$ 525.00 | 6% | \$497.20 |
| PWP TAC OS H34174 | 95600-H34174 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34175 | 95600-H34175 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34176 | 95600-H34176 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34177 | 95600-H34177 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34178 | 95600-H34178 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34179 | 95600-H34179 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34180 | 95600-H34180 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34181 | 95600-H34181 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34182 | 95600-H34182 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34183 | 95600-H34183 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34184 | 95600-H34184 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34185 | 95600-H34185 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34186 | 95600-H34186 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34187 | 95600-H34187 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34188 | 95600-H34188 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34189 | 95600-H34189 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34190 | 95600-H34190 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34191 | 95600-H34191 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34192 | 95600-H34192 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34193 | 95600-H34193 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34194 | 95600-H34194 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34195 | 95600-H34195 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34196 | 95600-H34196 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34197 | 95600-H34197 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34198 | 95600-H34198 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34199 | 95600-H34199 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34200 | 95600-H34200 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34201 | 95600-H34201 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34202 | 95600-H34202 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34203 | 95600-H34203 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34204 | 95600-H34204 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34205 | 95600-H34205 | \$ 25.00 | 6% | \$23.68 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34206 | 95600-H34206 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34207 | 95600-H34207 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34208 | 95600-H34208 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34209 | 95600-H34209 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34210 | 95600-H34210 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34211 | 95600-H34211 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34212 | 95600-H34212 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34213 | 95600-H34213 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34214 | 95600-H34214 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34215 | 95600-H34215 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34216 | 95600-H34216 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34217 | 95600-H34217 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34218 | 95600-H34218 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34219 | 95600-H34219 | \$ 25.00 | 6% | \$23.68 |
| PWP TAC OS H34220 | 95600-H34220 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34221 | 95600-H34221 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34222 | 95600-H34222 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34223 | 95600-H34223 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34224 | 95600-H34224 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34225 | 95600-H34225 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34226 | 95600-H34226 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34227 | 95600-H34227 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34228 | 95600-H34228 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34229 | 95600-H34229 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34230 | 95600-H34230 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34231 | 95600-H34231 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34232 | 95600-H34232 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34233 | 95600-H34233 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34234 | 95600-H34234 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34235 | 95600-H34235 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34236 | 95600-H34236 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34237 | 95600-H34237 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34238 | 95600-H34238 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34239 | 95600-H34239 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34240 | 95600-H34240 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34241 | 95600-H34241 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34242 | 95600-H34242 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34243 | 95600-H34243 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34244 | 95600-H34244 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34245 | 95600-H34245 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34246 | 95600-H34246 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34247 | 95600-H34247 | \$ 40.00 | 6% | \$37.88 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34248 | 95600-H34248 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34249 | 95600-H34249 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34250 | 95600-H34250 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34251 | 95600-H34251 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34252 | 95600-H34252 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34253 | 95600-H34253 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34254 | 95600-H34254 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34255 | 95600-H34255 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34256 | 95600-H34256 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34257 | 95600-H34257 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34258 | 95600-H34258 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34259 | 95600-H34259 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34260 | 95600-H34260 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34261 | 95600-H34261 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34262 | 95600-H34262 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34263 | 95600-H34263 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34264 | 95600-H34264 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34265 | 95600-H34265 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34266 | 95600-H34266 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34267 | 95600-H34267 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34268 | 95600-H34268 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34269 | 95600-H34269 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34270 | 95600-H34270 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34271 | 95600-H34271 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34272 | 95600-H34272 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34273 | 95600-H34273 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34274 | 95600-H34274 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34275 | 95600-H34275 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34276 | 95600-H34276 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34277 | 95600-H34277 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34278 | 95600-H34278 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34279 | 95600-H34279 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34280 | 95600-H34280 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34281 | 95600-H34281 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34282 | 95600-H34282 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34283 | 95600-H34283 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34284 | 95600-H34284 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34285 | 95600-H34285 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34286 | 95600-H34286 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34287 | 95600-H34287 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34288 | 95600-H34288 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34289 | 95600-H34289 | \$ 31.00 | 6% | \$29.36 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34290 | 95600-H34290 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34291 | 95600-H34291 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34292 | 95600-H34292 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34293 | 95600-H34293 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34294 | 95600-H34294 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34295 | 95600-H34295 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34296 | 95600-H34296 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34297 | 95600-H34297 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34298 | 95600-H34298 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34299 | 95600-H34299 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34300 | 95600-H34300 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34301 | 95600-H34301 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34302 | 95600-H34302 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34303 | 95600-H34303 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34304 | 95600-H34304 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34305 | 95600-H34305 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H34306 | 95600-H34306 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34307 | 95600-H34307 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34308 | 95600-H34308 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34309 | 95600-H34309 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34310 | 95600-H34310 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34311 | 95600-H34311 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34312 | 95600-H34312 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34313 | 95600-H34313 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34314 | 95600-H34314 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34315 | 95600-H34315 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34316 | 95600-H34316 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34317 | 95600-H34317 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34318 | 95600-H34318 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34319 | 95600-H34319 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34320 | 95600-H34320 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34321 | 95600-H34321 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34322 | 95600-H34322 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34323 | 95600-H34323 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34324 | 95600-H34324 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34325 | 95600-H34325 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34326 | 95600-H34326 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34327 | 95600-H34327 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34328 | 95600-H34328 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34329 | 95600-H34329 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34330 | 95600-H34330 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34331 | 95600-H34331 | \$ 40.00 | 6% | \$37.88 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34332 | 95600-H34332 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34333 | 95600-H34333 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34334 | 95600-H34334 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34335 | 95600-H34335 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34336 | 95600-H34336 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34337 | 95600-H34337 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34338 | 95600-H34338 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34339 | 95600-H34339 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34340 | 95600-H34340 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34341 | 95600-H34341 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34342 | 95600-H34342 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34343 | 95600-H34343 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34344 | 95600-H34344 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34345 | 95600-H34345 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34346 | 95600-H34346 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34347 | 95600-H34347 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34348 | 95600-H34348 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34349 | 95600-H34349 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34350 | 95600-H34350 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34351 | 95600-H34351 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34352 | 95600-H34352 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34353 | 95600-H34353 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34354 | 95600-H34354 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34355 | 95600-H34355 | \$ 40.00 | 6% | \$37.88 |
| PWP TAC OS H34356 | 95600-H34356 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34357 | 95600-H34357 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34358 | 95600-H34358 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34359 | 95600-H34359 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34360 | 95600-H34360 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34361 | 95600-H34361 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34362 | 95600-H34362 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34363 | 95600-H34363 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34364 | 95600-H34364 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34365 | 95600-H34365 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34366 | 95600-H34366 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34367 | 95600-H34367 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34368 | 95600-H34368 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34369 | 95600-H34369 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34370 | 95600-H34370 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34371 | 95600-H34371 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34372 | 95600-H34372 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34373 | 95600-H34373 | \$ 70.00 | 6% | \$66.29 |

| | | | | |
|-------------------|--------------|-----------|----|----------|
| PWP TAC OS H34374 | 95600-H34374 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34375 | 95600-H34375 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34376 | 95600-H34376 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34377 | 95600-H34377 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34378 | 95600-H34378 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34379 | 95600-H34379 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34380 | 95600-H34380 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34381 | 95600-H34381 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34382 | 95600-H34382 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34383 | 95600-H34383 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34384 | 95600-H34384 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34385 | 95600-H34385 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34386 | 95600-H34386 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34387 | 95600-H34387 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34388 | 95600-H34388 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34389 | 95600-H34389 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34390 | 95600-H34390 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34391 | 95600-H34391 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34392 | 95600-H34392 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34393 | 95600-H34393 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34394 | 95600-H34394 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34395 | 95600-H34395 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34396 | 95600-H34396 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34397 | 95600-H34397 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34398 | 95600-H34398 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34399 | 95600-H34399 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34400 | 95600-H34400 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34401 | 95600-H34401 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34402 | 95600-H34402 | \$ 70.00 | 6% | \$66.29 |
| PWP TAC OS H34403 | 95600-H34403 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34404 | 95600-H34404 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34405 | 95600-H34405 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34406 | 95600-H34406 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34407 | 95600-H34407 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34408 | 95600-H34408 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34409 | 95600-H34409 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34410 | 95600-H34410 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34411 | 95600-H34411 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34412 | 95600-H34412 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34413 | 95600-H34413 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34414 | 95600-H34414 | \$ 110.00 | 6% | \$104.18 |
| PWP TAC OS H34415 | 95600-H34415 | \$ 110.00 | 6% | \$104.18 |

| | | | | |
|-------------------|--------------|-----------|----|-----------------|
| PWP TAC OS H34416 | 95600-H34416 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34417 | 95600-H34417 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34418 | 95600-H34418 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34419 | 95600-H34419 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34420 | 95600-H34420 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34421 | 95600-H34421 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34422 | 95600-H34422 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34423 | 95600-H34423 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34424 | 95600-H34424 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34425 | 95600-H34425 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34426 | 95600-H34426 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34427 | 95600-H34427 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34428 | 95600-H34428 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34429 | 95600-H34429 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34430 | 95600-H34430 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34431 | 95600-H34431 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34432 | 95600-H34432 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34433 | 95600-H34433 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34434 | 95600-H34434 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34435 | 95600-H34435 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34436 | 95600-H34436 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34437 | 95600-H34437 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34438 | 95600-H34438 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34439 | 95600-H34439 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34440 | 95600-H34440 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34441 | 95600-H34441 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34442 | 95600-H34442 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34443 | 95600-H34443 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34444 | 95600-H34444 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34445 | 95600-H34445 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP TAC OS H34446 | 95600-H34446 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34447 | 95600-H34447 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34448 | 95600-H34448 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34449 | 95600-H34449 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34450 | 95600-H34450 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34451 | 95600-H34451 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34452 | 95600-H34452 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34453 | 95600-H34453 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34454 | 95600-H34454 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34455 | 95600-H34455 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34456 | 95600-H34456 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34457 | 95600-H34457 | \$ 125.00 | 6% | <i>\$118.38</i> |

| | | | | |
|-------------------|--------------|-----------|----|-----------------|
| PWP TAC OS H34458 | 95600-H34458 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34459 | 95600-H34459 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34460 | 95600-H34460 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34461 | 95600-H34461 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34462 | 95600-H34462 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34463 | 95600-H34463 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34464 | 95600-H34464 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34465 | 95600-H34465 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34466 | 95600-H34466 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34467 | 95600-H34467 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34468 | 95600-H34468 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34469 | 95600-H34469 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34470 | 95600-H34470 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34471 | 95600-H34471 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34472 | 95600-H34472 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34473 | 95600-H34473 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34474 | 95600-H34474 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34475 | 95600-H34475 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34476 | 95600-H34476 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34477 | 95600-H34477 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34478 | 95600-H34478 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34479 | 95600-H34479 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34480 | 95600-H34480 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34481 | 95600-H34481 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34482 | 95600-H34482 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34483 | 95600-H34483 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34484 | 95600-H34484 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34485 | 95600-H34485 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34486 | 95600-H34486 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34487 | 95600-H34487 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34488 | 95600-H34488 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34489 | 95600-H34489 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP TAC OS H34490 | 95600-H34490 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34491 | 95600-H34491 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34492 | 95600-H34492 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34493 | 95600-H34493 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34494 | 95600-H34494 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34495 | 95600-H34495 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34496 | 95600-H34496 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34497 | 95600-H34497 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34498 | 95600-H34498 | \$ 22.00 | 6% | <i>\$20.84</i> |
| PWP TAC OS H34499 | 95600-H34499 | \$ 22.00 | 6% | <i>\$20.84</i> |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34500 | 95600-H34500 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34501 | 95600-H34501 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34502 | 95600-H34502 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34503 | 95600-H34503 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34504 | 95600-H34504 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34505 | 95600-H34505 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34506 | 95600-H34506 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34507 | 95600-H34507 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34508 | 95600-H34508 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34509 | 95600-H34509 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34510 | 95600-H34510 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34511 | 95600-H34511 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34512 | 95600-H34512 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34513 | 95600-H34513 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34514 | 95600-H34514 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34515 | 95600-H34515 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34516 | 95600-H34516 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34517 | 95600-H34517 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34518 | 95600-H34518 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34519 | 95600-H34519 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34520 | 95600-H34520 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34521 | 95600-H34521 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34522 | 95600-H34522 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34523 | 95600-H34523 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34524 | 95600-H34524 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34525 | 95600-H34525 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34526 | 95600-H34526 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34527 | 95600-H34527 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34528 | 95600-H34528 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34529 | 95600-H34529 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34530 | 95600-H34530 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34531 | 95600-H34531 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34532 | 95600-H34532 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34533 | 95600-H34533 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34534 | 95600-H34534 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34535 | 95600-H34535 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34536 | 95600-H34536 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34537 | 95600-H34537 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34538 | 95600-H34538 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34539 | 95600-H34539 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34540 | 95600-H34540 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34541 | 95600-H34541 | \$ 22.00 | 6% | \$20.84 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34542 | 95600-H34542 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34543 | 95600-H34543 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34544 | 95600-H34544 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34545 | 95600-H34545 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34546 | 95600-H34546 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34547 | 95600-H34547 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34548 | 95600-H34548 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34549 | 95600-H34549 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34550 | 95600-H34550 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34551 | 95600-H34551 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34552 | 95600-H34552 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34553 | 95600-H34553 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34554 | 95600-H34554 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34555 | 95600-H34555 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34556 | 95600-H34556 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34557 | 95600-H34557 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34558 | 95600-H34558 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34559 | 95600-H34559 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34560 | 95600-H34560 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34561 | 95600-H34561 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34562 | 95600-H34562 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34563 | 95600-H34563 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34564 | 95600-H34564 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34565 | 95600-H34565 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34566 | 95600-H34566 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34567 | 95600-H34567 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34568 | 95600-H34568 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34569 | 95600-H34569 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34570 | 95600-H34570 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34571 | 95600-H34571 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34572 | 95600-H34572 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34573 | 95600-H34573 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34574 | 95600-H34574 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34575 | 95600-H34575 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34576 | 95600-H34576 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34577 | 95600-H34577 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34578 | 95600-H34578 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34579 | 95600-H34579 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34580 | 95600-H34580 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34581 | 95600-H34581 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34582 | 95600-H34582 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34583 | 95600-H34583 | \$ 22.00 | 6% | \$20.84 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34584 | 95600-H34584 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34585 | 95600-H34585 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34586 | 95600-H34586 | \$ 22.00 | 6% | \$20.84 |
| PWP TAC OS H34587 | 95600-H34587 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34588 | 95600-H34588 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34589 | 95600-H34589 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34590 | 95600-H34590 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34591 | 95600-H34591 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34592 | 95600-H34592 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34593 | 95600-H34593 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34594 | 95600-H34594 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34595 | 95600-H34595 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34596 | 95600-H34596 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34597 | 95600-H34597 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34598 | 95600-H34598 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34599 | 95600-H34599 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34600 | 95600-H34600 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34601 | 95600-H34601 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34602 | 95600-H34602 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34603 | 95600-H34603 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34604 | 95600-H34604 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34605 | 95600-H34605 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34606 | 95600-H34606 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34607 | 95600-H34607 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34608 | 95600-H34608 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34609 | 95600-H34609 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34610 | 95600-H34610 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34611 | 95600-H34611 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34612 | 95600-H34612 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34613 | 95600-H34613 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34614 | 95600-H34614 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34615 | 95600-H34615 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34616 | 95600-H34616 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34617 | 95600-H34617 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34618 | 95600-H34618 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34619 | 95600-H34619 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34620 | 95600-H34620 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34621 | 95600-H34621 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34622 | 95600-H34622 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34623 | 95600-H34623 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34624 | 95600-H34624 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34625 | 95600-H34625 | \$ 46.00 | 6% | \$43.56 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34626 | 95600-H34626 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34627 | 95600-H34627 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34628 | 95600-H34628 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34629 | 95600-H34629 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34630 | 95600-H34630 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34631 | 95600-H34631 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H34632 | 95600-H34632 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34633 | 95600-H34633 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34634 | 95600-H34634 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34635 | 95600-H34635 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34636 | 95600-H34636 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34637 | 95600-H34637 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34638 | 95600-H34638 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34639 | 95600-H34639 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34640 | 95600-H34640 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34641 | 95600-H34641 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34642 | 95600-H34642 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34643 | 95600-H34643 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34644 | 95600-H34644 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34645 | 95600-H34645 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34646 | 95600-H34646 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34647 | 95600-H34647 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34648 | 95600-H34648 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34649 | 95600-H34649 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34650 | 95600-H34650 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34651 | 95600-H34651 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34652 | 95600-H34652 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34653 | 95600-H34653 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34654 | 95600-H34654 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34655 | 95600-H34655 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34656 | 95600-H34656 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34657 | 95600-H34657 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34658 | 95600-H34658 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34659 | 95600-H34659 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34660 | 95600-H34660 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34661 | 95600-H34661 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34662 | 95600-H34662 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34663 | 95600-H34663 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34664 | 95600-H34664 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34665 | 95600-H34665 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34666 | 95600-H34666 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34667 | 95600-H34667 | \$ 54.00 | 6% | \$51.14 |

| | | | | |
|-------------------|--------------|----------|----|---------|
| PWP TAC OS H34668 | 95600-H34668 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34669 | 95600-H34669 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34670 | 95600-H34670 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34671 | 95600-H34671 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34672 | 95600-H34672 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34673 | 95600-H34673 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34674 | 95600-H34674 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34675 | 95600-H34675 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34676 | 95600-H34676 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34677 | 95600-H34677 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34678 | 95600-H34678 | \$ 54.00 | 6% | \$51.14 |
| PWP TAC OS H34679 | 95600-H34679 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34680 | 95600-H34680 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34681 | 95600-H34681 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34682 | 95600-H34682 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34683 | 95600-H34683 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34684 | 95600-H34684 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34685 | 95600-H34685 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34686 | 95600-H34686 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34687 | 95600-H34687 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34688 | 95600-H34688 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34689 | 95600-H34689 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34690 | 95600-H34690 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34691 | 95600-H34691 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34692 | 95600-H34692 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34693 | 95600-H34693 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34694 | 95600-H34694 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34695 | 95600-H34695 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34696 | 95600-H34696 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34697 | 95600-H34697 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34698 | 95600-H34698 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34699 | 95600-H34699 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34700 | 95600-H34700 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34701 | 95600-H34701 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34702 | 95600-H34702 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34703 | 95600-H34703 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34704 | 95600-H34704 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34705 | 95600-H34705 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34706 | 95600-H34706 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34707 | 95600-H34707 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34708 | 95600-H34708 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34709 | 95600-H34709 | \$ 62.00 | 6% | \$58.72 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PWP TAC OS H34710 | 95600-H34710 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34711 | 95600-H34711 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34712 | 95600-H34712 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34713 | 95600-H34713 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34714 | 95600-H34714 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34715 | 95600-H34715 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34716 | 95600-H34716 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34717 | 95600-H34717 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34718 | 95600-H34718 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34719 | 95600-H34719 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34720 | 95600-H34720 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34721 | 95600-H34721 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34722 | 95600-H34722 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34723 | 95600-H34723 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34724 | 95600-H34724 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34725 | 95600-H34725 | \$ 62.00 | 6% | \$58.72 |
| PWP TAC OS H34726 | 95600-H34726 | \$ 1,387.00 | 6% | \$1,313.56 |
| PWP TAC OS H34727 | 95600-H34727 | \$ 1,387.00 | 6% | \$1,313.56 |
| PWP TAC OS H34728 | 95600-H34728 | \$ 1,387.00 | 6% | \$1,313.56 |
| PWP TAC OS H34729 | 95600-H34729 | \$ 1,387.00 | 6% | \$1,313.56 |
| PWP TAC OS H34730 | 95600-H34730 | \$ 1,482.00 | 6% | \$1,403.53 |
| PWP TAC OS H34731 | 95600-H34731 | \$ 1,482.00 | 6% | \$1,403.53 |
| PWP TAC OS H34732 | 95600-H34732 | \$ 1,482.00 | 6% | \$1,403.53 |
| PWP TAC OS H34733 | 95600-H34733 | \$ 1,482.00 | 6% | \$1,403.53 |
| PWP TAC OS H34734 | 95600-H34734 | \$ 209.00 | 6% | \$197.93 |
| PWP TAC OS H34735 | 95600-H34735 | \$ 209.00 | 6% | \$197.93 |
| PWP TAC OS H34736 | 95600-H34736 | \$ 269.00 | 6% | \$254.76 |
| PWP TAC OS H34737 | 95600-H34737 | \$ 269.00 | 6% | \$254.76 |
| PWP TAC OS H34738 | 95600-H34738 | \$ 501.00 | 6% | \$474.47 |
| PWP TAC OS H34739 | 95600-H34739 | \$ 501.00 | 6% | \$474.47 |
| PWP TAC OS H34740 | 95600-H34740 | \$ 216.00 | 6% | \$204.56 |
| PWP TAC OS H34741 | 95600-H34741 | \$ 216.00 | 6% | \$204.56 |
| PWP TAC OS H34742 | 95600-H34742 | \$ 212.00 | 6% | \$200.77 |
| PWP TAC OS H34743 | 95600-H34743 | \$ 212.00 | 6% | \$200.77 |
| PWP TAC OS H34744 | 95600-H34744 | \$ 277.00 | 6% | \$262.33 |
| PWP TAC OS H34745 | 95600-H34745 | \$ 277.00 | 6% | \$262.33 |
| PWP TAC OS H34746 | 95600-H34746 | \$ 313.00 | 6% | \$296.43 |
| PWP TAC OS H34747 | 95600-H34747 | \$ 313.00 | 6% | \$296.43 |
| PWP TAC OS H34748 | 95600-H34748 | \$ 518.00 | 6% | \$490.57 |
| PWP TAC OS H34749 | 95600-H34749 | \$ 501.00 | 6% | \$474.47 |
| PWP TAC OS H34750 | 95600-H34750 | \$ 518.00 | 6% | \$490.57 |
| PWP TAC OS H34751 | 95600-H34751 | \$ 518.00 | 6% | \$490.57 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PWP TAC OS H34752 | 95600-H34752 | \$ 518.00 | 6% | \$490.57 |
| PWP TAC OS H34753 | 95600-H34753 | \$ 501.00 | 6% | \$474.47 |
| PWP TAC OS H34754 | 95600-H34754 | \$ 518.00 | 6% | \$490.57 |
| PWP TAC OS H34755 | 95600-H34755 | \$ 518.00 | 6% | \$490.57 |
| PWP TAC OS H34756 | 95600-H34756 | \$ 279.00 | 6% | \$264.23 |
| PWP TAC OS H34757 | 95600-H34757 | \$ 269.00 | 6% | \$254.76 |
| PWP TAC OS H34758 | 95600-H34758 | \$ 277.00 | 6% | \$262.33 |
| PWP TAC OS H34759 | 95600-H34759 | \$ 279.00 | 6% | \$264.23 |
| PWP TAC OS H34760 | 95600-H34760 | \$ 279.00 | 6% | \$264.23 |
| PWP TAC OS H34761 | 95600-H34761 | \$ 277.00 | 6% | \$262.33 |
| PWP TAC OS H34993 | 95600-H34993 | \$ 5,754.00 | 6% | \$5,449.33 |
| PWP TAC OS H34994 | 95600-H34994 | \$ 5,754.00 | 6% | \$5,449.33 |
| PWP TAC OS H34996 | 95600-H34996 | \$ 5,754.00 | 6% | \$5,449.33 |
| PWP TAC OS H34997 | 95600-H34997 | \$ 5,754.00 | 6% | \$5,449.33 |
| PWP TAC OS H35005 | 95600-H35005 | \$ 3,480.00 | 6% | \$3,295.73 |
| PWP TAC OS H35006 | 95600-H35006 | \$ 3,480.00 | 6% | \$3,295.73 |
| PWP TAC OS H35012 | 95600-H35012 | \$ 2,085.00 | 6% | \$1,974.60 |
| PWP TAC OS H35070 | 95600-H35070 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35071 | 95600-H35071 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35072 | 95600-H35072 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35073 | 95600-H35073 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35074 | 95600-H35074 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35075 | 95600-H35075 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35076 | 95600-H35076 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35077 | 95600-H35077 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35078 | 95600-H35078 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35079 | 95600-H35079 | \$ 31.00 | 6% | \$29.36 |
| PWP TAC OS H35080 | 95600-H35080 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H35081 | 95600-H35081 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H35082 | 95600-H35082 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H35083 | 95600-H35083 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H35270 | 95600-H35270 | \$ 187.00 | 6% | \$177.10 |
| PWP TAC OS H35271 | 95600-H35271 | \$ 141.00 | 6% | \$133.53 |
| PWP TAC OS H35273 | 95600-H35273 | \$ 174.00 | 6% | \$164.79 |
| PWP TAC OS H35274 | 95600-H35274 | \$ 303.00 | 6% | \$286.96 |
| PWP TAC OS H35275 | 95600-H35275 | \$ 209.00 | 6% | \$197.93 |
| PWP TAC OS H35276 | 95600-H35276 | \$ 1,326.00 | 6% | \$1,255.79 |
| PWP TAC OS H35277 | 95600-H35277 | \$ 1,638.00 | 6% | \$1,551.27 |
| PWP TAC OS H35278 | 95600-H35278 | \$ 1,457.00 | 6% | \$1,379.85 |
| PWP TAC OS H35279 | 95600-H35279 | \$ 1,345.00 | 6% | \$1,273.78 |
| PWP TAC OS H35280 | 95600-H35280 | \$ 1,709.00 | 6% | \$1,618.51 |
| PWP TAC OS H35292 | 95600-H35292 | \$ 1,457.00 | 6% | \$1,379.85 |

| | | | | |
|-----------------------------|--------------|-------------|----|-------------------|
| PWP TAC OS H35293 | 95600-H35293 | \$ 1,345.00 | 6% | <i>\$1,273.78</i> |
| PWP TAC OS H35295 | 95600-H35295 | \$ 163.00 | 6% | <i>\$154.37</i> |
| PWP Software and TAC H35296 | 95600-H35296 | \$ 3,457.00 | 6% | <i>\$3,273.95</i> |
| PWP Software and TAC H35297 | 95600-H35297 | \$ 3,457.00 | 6% | <i>\$3,273.95</i> |
| PWP Software and TAC H35298 | 95600-H35298 | \$ 5,557.00 | 6% | <i>\$5,262.76</i> |
| PWP Software and TAC H35299 | 95600-H35299 | \$ 5,557.00 | 6% | <i>\$5,262.76</i> |
| PWP Software and TAC H35300 | 95600-H35300 | \$ 1,008.00 | 6% | <i>\$954.63</i> |
| PWP Software and TAC H35301 | 95600-H35301 | \$ 453.00 | 6% | <i>\$429.01</i> |
| PWP Software and TAC H35302 | 95600-H35302 | \$ 1,313.00 | 6% | <i>\$1,243.48</i> |
| PWP Software and TAC H35303 | 95600-H35303 | \$ 1,313.00 | 6% | <i>\$1,243.48</i> |
| PWP Software and TAC H35304 | 95600-H35304 | \$ 1,313.00 | 6% | <i>\$1,243.48</i> |
| PWP Software and TAC H35305 | 95600-H35305 | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| PWP Software and TAC H35306 | 95600-H35306 | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| PWP Software and TAC H35307 | 95600-H35307 | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| PWP Software and TAC H35308 | 95600-H35308 | \$ 371.00 | 6% | <i>\$351.36</i> |
| PWP TAC OS H35309 | 95600-H35309 | \$ 2,048.00 | 6% | <i>\$1,939.56</i> |
| PWP TAC OS H35310 | 95600-H35310 | \$ 2,048.00 | 6% | <i>\$1,939.56</i> |
| PWP TAC OS H35311 | 95600-H35311 | \$ 2,048.00 | 6% | <i>\$1,939.56</i> |
| PWP TAC OS H35312 | 95600-H35312 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| PWP TAC OS H35313 | 95600-H35313 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| PWP TAC OS H35314 | 95600-H35314 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| PWP TAC OS H35315 | 95600-H35315 | \$ 755.00 | 6% | <i>\$715.02</i> |
| PWP TAC OS H35316 | 95600-H35316 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PWP TAC OS H35317 | 95600-H35317 | \$ 164.00 | 6% | <i>\$155.32</i> |
| PWP TAC OS H35318 | 95600-H35318 | \$ 350.00 | 6% | <i>\$331.47</i> |
| PWP TAC OS H35319 | 95600-H35319 | \$ 472.00 | 6% | <i>\$447.01</i> |
| PWP TAC OS H35320 | 95600-H35320 | \$ 489.00 | 6% | <i>\$463.11</i> |
| PWP TAC OS H35321 | 95600-H35321 | \$ 623.00 | 6% | <i>\$590.01</i> |
| PWP TAC OS H35322 | 95600-H35322 | \$ 755.00 | 6% | <i>\$715.02</i> |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PWP TAC OS H35323 | 95600-H35323 | \$ 755.00 | 6% | \$715.02 |
| PWP TAC OS H35328 | 95600-H35328 | \$ 63.00 | 6% | \$59.66 |
| PWP TAC OS H35330 | 95600-H35330 | \$ 46.00 | 6% | \$43.56 |
| PWP TAC OS H35340 | 95600-H35340 | \$ 1,394.00 | 6% | \$1,320.19 |
| PWP TAC OS H35341 | 95600-H35341 | \$ 1,394.00 | 6% | \$1,320.19 |
| PWP TAC OS H35342 | 95600-H35342 | \$ 1,279.00 | 6% | \$1,211.28 |
| PWP TAC OS H35343 | 95600-H35343 | \$ 1,394.00 | 6% | \$1,320.19 |
| PWP TAC OS H35344 | 95600-H35344 | \$ 1,455.00 | 6% | \$1,377.96 |
| PWP TAC OS H35345 | 95600-H35345 | \$ 1,455.00 | 6% | \$1,377.96 |
| PWP TAC OS H35346 | 95600-H35346 | \$ 1,321.00 | 6% | \$1,251.05 |
| PWP TAC OS H35347 | 95600-H35347 | \$ 1,455.00 | 6% | \$1,377.96 |
| PWP TAC OS H35348 | 95600-H35348 | \$ 399.00 | 6% | \$377.87 |
| PWP TAC OS H35349 | 95600-H35349 | \$ 1,608.00 | 6% | \$1,522.86 |
| PWP TAC OS H35350 | 95600-H35350 | \$ 1,608.00 | 6% | \$1,522.86 |
| PWP TAC OS H35351 | 95600-H35351 | \$ 1,450.00 | 6% | \$1,373.22 |
| PWP TAC OS H35352 | 95600-H35352 | \$ 1,608.00 | 6% | \$1,522.86 |
| PWP TAC OS H35353 | 95600-H35353 | \$ 399.00 | 6% | \$377.87 |
| PWP TAC OS H35357 | 95600-H35357 | \$ 178.00 | 6% | \$168.57 |
| PWP TAC OS H35358 | 95600-H35358 | \$ 164.00 | 6% | \$155.32 |
| PWP TAC OS H35359 | 95600-H35359 | \$ 623.00 | 6% | \$590.01 |
| PWP TAC OS H35360 | 95600-H35360 | \$ 755.00 | 6% | \$715.02 |
| PWP TAC OS H35361 | 95600-H35361 | \$ 755.00 | 6% | \$715.02 |
| PWP TAC OS H35362 | 95600-H35362 | \$ 350.00 | 6% | \$331.47 |
| PWP TAC OS H35366 | 95600-H35366 | \$ 708.00 | 6% | \$670.51 |
| PWP TAC OS H35367 | 95600-H35367 | \$ 824.00 | 6% | \$780.37 |
| PWP TAC OS H35368 | 95600-H35368 | \$ 1,251.00 | 6% | \$1,184.76 |
| PWP TAC OS H35369 | 95600-H35369 | \$ 405.00 | 6% | \$383.56 |
| PWP TAC OS H35370 | 95600-H35370 | \$ 570.00 | 6% | \$539.82 |
| PWP TAC OS H35371 | 95600-H35371 | \$ 166.00 | 6% | \$157.21 |
| PWP TAC OS H35374 | 95600-H35374 | \$ 185.00 | 6% | \$175.20 |
| PWP TAC OS H35375 | 95600-H35375 | \$ 341.00 | 6% | \$322.94 |
| PWP TAC OS H35376 | 95600-H35376 | \$ 512.00 | 6% | \$484.89 |
| PWP TAC OS H35377 | 95600-H35377 | \$ 215.00 | 6% | \$203.62 |
| PWP TAC OS H35378 | 95600-H35378 | \$ 341.00 | 6% | \$322.94 |
| PWP TAC OS H35379 | 95600-H35379 | \$ 215.00 | 6% | \$203.62 |
| PWP TAC OS H35380 | 95600-H35380 | \$ 386.00 | 6% | \$365.56 |
| PWP TAC OS H35381 | 95600-H35381 | \$ 475.00 | 6% | \$449.85 |
| PWP TAC OS H35384 | 95600-H35384 | \$ 158.00 | 6% | \$149.63 |
| PWP TAC OS H35385 | 95600-H35385 | \$ 209.00 | 6% | \$197.93 |
| PWP TAC OS H35386 | 95600-H35386 | \$ 341.00 | 6% | \$322.94 |
| PWP TAC OS H35387 | 95600-H35387 | \$ 313.00 | 6% | \$296.43 |
| PWP TAC OS H35388 | 95600-H35388 | \$ 240.00 | 6% | \$227.29 |

| | | | | |
|-------------------|--------------|-------------|----|------------|
| PWP TAC OS H35389 | 95600-H35389 | \$ 133.00 | 6% | \$125.96 |
| PWP TAC OS H35390 | 95600-H35390 | \$ 116.00 | 6% | \$109.86 |
| PWP TAC OS H35391 | 95600-H35391 | \$ 249.00 | 6% | \$235.82 |
| PWP TAC OS H35392 | 95600-H35392 | \$ 386.00 | 6% | \$365.56 |
| PWP TAC OS H35393 | 95600-H35393 | \$ 512.00 | 6% | \$484.89 |
| PWP TAC OS H35394 | 95600-H35394 | \$ 96.00 | 6% | \$90.92 |
| PWP TAC OS H35395 | 95600-H35395 | \$ 82.00 | 6% | \$77.66 |
| PWP TAC OS H35396 | 95600-H35396 | \$ 96.00 | 6% | \$90.92 |
| PWP TAC OS H35397 | 95600-H35397 | \$ 82.00 | 6% | \$77.66 |
| PWP TAC OS H35398 | 95600-H35398 | \$ 240.00 | 6% | \$227.29 |
| PWP TAC OS H35399 | 95600-H35399 | \$ 291.00 | 6% | \$275.59 |
| PWP TAC OS H35400 | 95600-H35400 | \$ 322.00 | 6% | \$304.95 |
| PWP TAC OS H35401 | 95600-H35401 | \$ 171.00 | 6% | \$161.95 |
| PWP TAC OS H35404 | 95600-H35404 | \$ 76.00 | 6% | \$71.98 |
| PWP TAC OS H35405 | 95600-H35405 | \$ 185.00 | 6% | \$175.20 |
| PWP TAC OS H35406 | 95600-H35406 | \$ 23.00 | 6% | \$21.78 |
| PWP TAC OS H35407 | 95600-H35407 | \$ 155.00 | 6% | \$146.79 |
| PWP TAC OS H35408 | 95600-H35408 | \$ 231.00 | 6% | \$218.77 |
| PWP TAC OS H35409 | 95600-H35409 | \$ 23.00 | 6% | \$21.78 |
| PWP TAC OS H35415 | 95600-H35415 | \$ 117.00 | 6% | \$110.80 |
| PWP TAC OS H35416 | 95600-H35416 | \$ 117.00 | 6% | \$110.80 |
| PWP TAC OS H35426 | 95600-H35426 | \$ 133.00 | 6% | \$125.96 |
| PWP TAC OS H35427 | 95600-H35427 | \$ 313.00 | 6% | \$296.43 |
| PWP TAC OS H35428 | 95600-H35428 | \$ 116.00 | 6% | \$109.86 |
| PWP TAC OS H35429 | 95600-H35429 | \$ 249.00 | 6% | \$235.82 |
| PWP TAC OS H35430 | 95600-H35430 | \$ 203.00 | 6% | \$192.25 |
| PWP TAC OS H35431 | 95600-H35431 | \$ 203.00 | 6% | \$192.25 |
| PWP TAC OS H35432 | 95600-H35432 | \$ 212.00 | 6% | \$200.77 |
| PWP TAC OS H35433 | 95600-H35433 | \$ 261.00 | 6% | \$247.18 |
| PWP TAC OS H35434 | 95600-H35434 | \$ 295.00 | 6% | \$279.38 |
| PWP TAC OS H35435 | 95600-H35435 | \$ 295.00 | 6% | \$279.38 |
| PWP TAC OS H35436 | 95600-H35436 | \$ 486.00 | 6% | \$460.27 |
| PWP TAC OS H35437 | 95600-H35437 | \$ 486.00 | 6% | \$460.27 |
| PWP TAC OS H35438 | 95600-H35438 | \$ 486.00 | 6% | \$460.27 |
| PWP TAC OS H35439 | 95600-H35439 | \$ 486.00 | 6% | \$460.27 |
| PWP TAC OS H35440 | 95600-H35440 | \$ 261.00 | 6% | \$247.18 |
| PWP TAC OS H35441 | 95600-H35441 | \$ 261.00 | 6% | \$247.18 |
| PWP TAC OS H35442 | 95600-H35442 | \$ 261.00 | 6% | \$247.18 |
| PWP TAC OS H34728 | 95600-H35443 | \$ 1,387.00 | 6% | \$1,313.56 |
| PWP TAC OS H35444 | 95600-H35444 | \$ 1,482.00 | 6% | \$1,403.53 |
| PWP TAC OS H35445 | 95600-H35445 | \$ 1,326.00 | 6% | \$1,255.79 |
| PWP TAC OS H35446 | 95600-H35446 | \$ 1,310.00 | 6% | \$1,240.64 |

| | | | | |
|--------------------------|---------------------|-------------|----|-------------------|
| PWP TAC OS H35447 | 95600-H35447 | \$ 1,553.00 | 6% | <i>\$1,470.77</i> |
| PWP TAC OS H35448 | 95600-H35448 | \$ 1,439.00 | 6% | <i>\$1,362.80</i> |
| PWP TAC OS H35449 | 95600-H35449 | \$ 1,457.00 | 6% | <i>\$1,379.85</i> |
| PWP TAC OS H35450 | 95600-H35450 | \$ 1,275.00 | 6% | <i>\$1,207.49</i> |
| PWP TAC OS H35451 | 95600-H35451 | \$ 1,889.00 | 6% | <i>\$1,788.98</i> |
| PWP TAC OS H35452 | 95600-H35452 | \$ 1,889.00 | 6% | <i>\$1,788.98</i> |
| PWP TAC OS H35453 | 95600-H35453 | \$ 1,482.00 | 6% | <i>\$1,403.53</i> |
| PWP TAC OS H35454 | 95600-H35454 | \$ 1,387.00 | 6% | <i>\$1,313.56</i> |
| PWP TAC OS H35455 | 95600-H35455 | \$ 489.00 | 6% | <i>\$463.11</i> |
| PWP TAC OS H35456 | 95600-H35456 | \$ 582.00 | 6% | <i>\$551.18</i> |
| PWP TAC OS H35457 | 95600-H35457 | \$ 539.00 | 6% | <i>\$510.46</i> |
| PWP TAC OS H35458 | 95600-H35458 | \$ 588.00 | 6% | <i>\$556.87</i> |
| PWP TAC OS H35471 | 95600-H35471 | \$ 489.00 | 6% | <i>\$463.11</i> |
| PWP TAC OS H35600 | 95600-H35600 | \$ 174.00 | 6% | <i>\$164.79</i> |
| PWP TAC OS H35601 | 95600-H35601 | \$ 174.00 | 6% | <i>\$164.79</i> |
| PWP TAC OS H35602 | 95600-H35602 | \$ 216.00 | 6% | <i>\$204.56</i> |
| PWP TAC OS H35603 | 95600-H35603 | \$ 216.00 | 6% | <i>\$204.56</i> |
| PWP TAC OS H35604 | 95600-H35604 | \$ 279.00 | 6% | <i>\$264.23</i> |
| PWP TAC OS H35605 | 95600-H35605 | \$ 279.00 | 6% | <i>\$264.23</i> |
| PWP TAC OS H35606 | 95600-H35606 | \$ 303.00 | 6% | <i>\$286.96</i> |
| PWP TAC OS H35607 | 95600-H35607 | \$ 313.00 | 6% | <i>\$296.43</i> |
| PWP TAC OS ISW-24W-4X | 95600-ISW-24W-4X | \$ 475.00 | 6% | <i>\$449.85</i> |
| PWP TAC OS ISW-4W-4WS-4X | 95600-ISW-4W-4WS-4X | \$ 303.00 | 6% | <i>\$286.96</i> |
| PWP TAC OS BD MSM128 | 95600-MSM128 | \$ 1,486.00 | 6% | <i>\$1,407.32</i> |
| PWP TAC OS BD MSM48C | 95600-MSM48C | \$ 900.00 | 6% | <i>\$852.35</i> |
| PWP software TAC S22027 | 95600-S22027 | \$ 542.00 | 6% | <i>\$513.30</i> |
| PWP software TAC S22028 | 95600-S22028 | \$ 507.00 | 6% | <i>\$480.15</i> |
| PWP software TAC S22030 | 95600-S22030 | \$ 304.00 | 6% | <i>\$287.90</i> |
| PWP software TAC S22031 | 95600-S22031 | \$ 607.00 | 6% | <i>\$574.86</i> |
| PWP software TAC S22032 | 95600-S22032 | \$ 304.00 | 6% | <i>\$287.90</i> |
| PWP software TAC S22035 | 95600-S22035 | \$ 311.00 | 6% | <i>\$294.53</i> |
| PWP software TAC S22036 | 95600-S22036 | \$ 292.00 | 6% | <i>\$276.54</i> |
| PWP software TAC S22037 | 95600-S22037 | \$ 447.00 | 6% | <i>\$423.33</i> |
| PWP software TAC S22038 | 95600-S22038 | \$ 447.00 | 6% | <i>\$423.33</i> |
| PWP software TAC S22039 | 95600-S22039 | \$ 447.00 | 6% | <i>\$423.33</i> |
| PWP software TAC S22040 | 95600-S22040 | \$ 433.00 | 6% | <i>\$410.07</i> |
| PWP software TAC S22041 | 95600-S22041 | \$ 406.00 | 6% | <i>\$384.50</i> |
| PWP software TAC S22042 | 95600-S22042 | \$ 659.00 | 6% | <i>\$624.11</i> |

| | | | | |
|------------------------------|-------------------------|--------------|----|--------------------|
| PWP software TAC S22044 | 95600-S22044 | \$ 173.00 | 6% | <i>\$163.84</i> |
| PWP software TAC S22045 | 95600-S22045 | \$ 162.00 | 6% | <i>\$153.42</i> |
| PWP software TAC S22046 | 95600-S22046 | \$ 391.00 | 6% | <i>\$370.30</i> |
| PWP software TAC S22047 | 95600-S22047 | \$ 366.00 | 6% | <i>\$346.62</i> |
| PWP software TAC S22055 | 95600-S22055 | \$ 521.00 | 6% | <i>\$493.41</i> |
| PWP software TAC S22057 | 95600-S22057 | \$ 1,451.00 | 6% | <i>\$1,374.17</i> |
| PWP software TAC S22072 | 95600-S22072 | \$ 612.00 | 6% | <i>\$579.59</i> |
| PWP software TAC S22073 | 95600-S22073 | \$ 612.00 | 6% | <i>\$579.59</i> |
| PWP software TAC S22074 | 95600-S22074 | \$ 89.00 | 6% | <i>\$84.29</i> |
| PWP software TAC S22075 | 95600-S22075 | \$ 528.00 | 6% | <i>\$500.04</i> |
| PWP software TAC S22117 | 95600-S22117 | \$ 408.00 | 6% | <i>\$386.40</i> |
| PWP software TAC S22119 | 95600-S22119 | \$ 1,025.00 | 6% | <i>\$970.73</i> |
| PWP software TAC S22123 | 95600-S22123 | \$ 57.00 | 6% | <i>\$53.98</i> |
| PWP software TAC S22124 | 95600-S22124 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PWP software TAC S22149 | 95600-S22149 | \$ 1,253.00 | 6% | <i>\$1,186.65</i> |
| PWP software TAC S22150 | 95600-S22150 | \$ 11.00 | 6% | <i>\$10.42</i> |
| PWP TAC OS S22181 | 95600-S22181 | \$ 48,000.00 | 6% | <i>\$45,458.40</i> |
| PWP TAC OS S22182 | 95600-S22182 | \$ 9,600.00 | 6% | <i>\$9,091.68</i> |
| PWP TAC OS SLX9150-48XT-DC-F | 95600-SLX9150-48XT-DC-F | \$ 1,276.00 | 6% | <i>\$1,208.44</i> |
| PWP TAC OS SLX9150-48XT-DC-R | 95600-SLX9150-48XT-DC-R | \$ 1,393.00 | 6% | <i>\$1,319.24</i> |
| PWP TAC OS SLX9150-48Y-DC-F | 95600-SLX9150-48Y-DC-F | \$ 1,222.00 | 6% | <i>\$1,157.30</i> |
| PWP TAC OS SLX9150-48Y-DC-R | 95600-SLX9150-48Y-DC-R | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| PWP TAC OS SLX9740-40C | 95600-SLX9740-40C | \$ 6,907.00 | 6% | <i>\$6,541.27</i> |
| PWP TAC OS SLX9740-40C-AC-F | 95600-SLX9740-40C-AC-F | \$ 6,907.00 | 6% | <i>\$6,541.27</i> |
| PWP TAC OS SLX9740-40C-AC-R | 95600-SLX9740-40C-AC-R | \$ 6,907.00 | 6% | <i>\$6,541.27</i> |
| PWP TAC OS SLX9740-40C-DC-F | 95600-SLX9740-40C-DC-F | \$ 6,907.00 | 6% | <i>\$6,541.27</i> |
| PWP TAC OS SLX9740-80C | 95600-SLX9740-80C | \$ 12,986.00 | 6% | <i>\$12,298.39</i> |

| | | | | |
|------------------------------|-------------------------|--------------|----|--------------------|
| PWP TAC OS SLX9740-80C-AC-F | 95600-SLX9740-80C-AC-F | \$ 12,986.00 | 6% | <i>\$12,298.39</i> |
| PWP TAC OS SLX9740-80C-AC-R | 95600-SLX9740-80C-AC-R | \$ 12,986.00 | 6% | <i>\$12,298.39</i> |
| PWP TAC OS SLX9740-80C-DC-F | 95600-SLX9740-80C-DC-F | \$ 12,986.00 | 6% | <i>\$12,298.39</i> |
| PWP TAC OS SLX9740-ADV-LIC-P | 95600-SLX9740-ADV-LIC-P | \$ 1,252.00 | 6% | <i>\$1,185.71</i> |
| PWP TAC OS V300-8P-2X | 95600-V300-8P-2X | \$ 82.00 | 6% | <i>\$77.66</i> |
| PWP TAC OS V300-8T-2X | 95600-V300-8T-2X | \$ 56.00 | 6% | <i>\$53.03</i> |
| PWP TAC OS V300HT-8P-2X | 95600-V300HT-8P-2X | \$ 194.00 | 6% | <i>\$183.73</i> |
| PWP TAC OS V300HT-8T-2X | 95600-V300HT-8T-2X | \$ 117.00 | 6% | <i>\$110.80</i> |
| PWP TAC OS Summit VIM-SS | 95600-VIM-SS | \$ 79.00 | 6% | <i>\$74.82</i> |
| PWP TAC OS Summit VIM-SSV80 | 95600-VIM-SSV80 | \$ 143.00 | 6% | <i>\$135.43</i> |
| PWP TAC OS Summit VIM2-SS | 95600-VIM2-SS | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP TAC OS Summit VIM2-SS128 | 95600-VIM2-SS128 | \$ 299.00 | 6% | <i>\$283.17</i> |
| PWP TAC OS Summit VIM2-V80 | 95600-VIM2-V80 | \$ 322.00 | 6% | <i>\$304.95</i> |
| PWP TAC OS Summit VIM210G4X | 95600-VIM210G4X | \$ 568.00 | 6% | <i>\$537.92</i> |
| PWP TAC OS VIM5-2Q | 95600-VIM5-2Q | \$ 101.00 | 6% | <i>\$95.65</i> |
| PWP TAC OS VIM5-2Y | 95600-VIM5-2Y | \$ 118.00 | 6% | <i>\$111.75</i> |
| PWP TAC OS VIM5-4X | 95600-VIM5-4X | \$ 50.00 | 6% | <i>\$47.35</i> |
| PWP TAC OS VIM5-4XE | 95600-VIM5-4XE | \$ 99.00 | 6% | <i>\$93.76</i> |

| | | | | |
|----------------------------------|-----------------------------|-----------|----|-----------------|
| PWP TAC OS VIM5-4Y | 95600-VIM5-4Y | \$ 151.00 | 6% | <i>\$143.00</i> |
| PWP TAC OS VIM5-4YE | 95600-VIM5-4YE | \$ 199.00 | 6% | <i>\$188.46</i> |
| PWP TAC OS VSP4900-12MXU-12XE | 95600-VSP4900-12MXU-12XE | \$ 653.00 | 6% | <i>\$618.42</i> |
| PWP TAC OS VSP4900-12MXU-12XE-B1 | 95600-VSP4900-12MXU-12XE-B1 | \$ 653.00 | 6% | <i>\$618.42</i> |
| PWP TAC OS VSP4900-24S | 95600-VSP4900-24S | \$ 350.00 | 6% | <i>\$331.47</i> |
| PWP TAC OS VSP4900-24S-B3 | 95600-VSP4900-24S-B3 | \$ 350.00 | 6% | <i>\$331.47</i> |
| PWP TAC OS VSP4900-24XE | 95600-VSP4900-24XE | \$ 653.00 | 6% | <i>\$618.42</i> |
| PWP TAC OS VSP4900-24XE-B3 | 95600-VSP4900-24XE-B3 | \$ 653.00 | 6% | <i>\$618.42</i> |
| PWP TAC OS X435-24P-4S | 95600-X435-24P-4S | \$ 144.00 | 6% | <i>\$136.38</i> |
| PWP TAC OS X435-24T-4S | 95600-X435-24T-4S | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP TAC OS X435-8P-2T-W | 95600-X435-8P-2T-W | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP TAC OS X435-8P-4S | 95600-X435-8P-4S | \$ 72.00 | 6% | <i>\$68.19</i> |
| PWP TAC OS X435-8T-4S | 95600-X435-8T-4S | \$ 57.00 | 6% | <i>\$53.98</i> |
| PWP TAC OS Summit X460-24P | 95600-X460-24P | \$ 524.00 | 6% | <i>\$496.25</i> |
| PWP TAC OS Summit X460-24T | 95600-X460-24T | \$ 365.00 | 6% | <i>\$345.67</i> |
| PWP TAC OS Summit X460-24TDC | 95600-X460-24TDC | \$ 540.00 | 6% | <i>\$511.41</i> |
| PWP TAC OS Summit X460-24X | 95600-X460-24X | \$ 691.00 | 6% | <i>\$654.41</i> |
| PWP TAC OS Summit X460-24XDC | 95600-X460-24XDC | \$ 772.00 | 6% | <i>\$731.12</i> |

| | | | | |
|------------------------------|-----------------------|-----------|----|-----------------|
| PWP TAC OS Summit X460-48P | 95600-X460-48P | \$ 691.00 | 6% | <i>\$654.41</i> |
| PWP TAC OS Summit X460-48T | 95600-X460-48T | \$ 590.00 | 6% | <i>\$558.76</i> |
| PWP TAC OS Summit X460-48TDC | 95600-X460-48TDC | \$ 750.00 | 6% | <i>\$710.29</i> |
| PWP TAC OS Summit X460-48X | 95600-X460-48X | \$ 924.00 | 6% | <i>\$875.07</i> |
| PWP TAC OS Summit X460-48XDC | 95600-X460-48XDC | \$ 895.00 | 6% | <i>\$847.61</i> |
| PWP TAC OS Summit X460CORE | 95600-X460CORE | \$ 242.00 | 6% | <i>\$229.19</i> |
| PWP TAC OS Summit X460MPLS | 95600-X460MPLS | \$ 159.00 | 6% | <i>\$150.58</i> |
| PWP TAC OS Summit X460NS | 95600-X460NS | \$ 185.00 | 6% | <i>\$175.20</i> |
| PWP TAC OS X465-24MU | 95600-X465-24MU | \$ 755.00 | 6% | <i>\$715.02</i> |
| PWP TAC OS X465-24S | 95600-X465-24S | \$ 350.00 | 6% | <i>\$331.47</i> |
| PWP TAC OS X465-24S-B3 | 95600-X465-24S-B3 | \$ 350.00 | 6% | <i>\$331.47</i> |
| PWP TAC OS X465-24W | 95600-X465-24W | \$ 350.00 | 6% | <i>\$331.47</i> |
| PWP TAC OS X465-24XE | 95600-X465-24XE | \$ 653.00 | 6% | <i>\$618.42</i> |
| PWP TAC OS X465-24XE-B3 | 95600-X465-24XE-B3 | \$ 653.00 | 6% | <i>\$618.42</i> |
| PWP TAC OS X465-48P | 95600-X465-48P | \$ 489.00 | 6% | <i>\$463.11</i> |
| PWP TAC OS X465-48T | 95600-X465-48T | \$ 472.00 | 6% | <i>\$447.01</i> |
| PWP TAC OS X465-48W | 95600-X465-48W | \$ 623.00 | 6% | <i>\$590.01</i> |
| PWP TAC OS X465i-48W | 95600-X465i-48W | \$ 755.00 | 6% | <i>\$715.02</i> |
| PWP TAC OS X465i-48W-B1-S1 | 95600-X465i-48W-B1-S1 | \$ 755.00 | 6% | <i>\$715.02</i> |
| PWP TAC OS X465i-48W-B2-S1 | 95600-X465i-48W-B2-S1 | \$ 755.00 | 6% | <i>\$715.02</i> |
| PWP TAC OS Summit X480-24X | 95600-X480-24X | \$ 848.00 | 6% | <i>\$803.10</i> |

| | | | | |
|----------------------------|-------------------|---------------|----|---------------------|
| PWP TAC OS Summit X480-48T | 95600-X480-48T | \$ 848.00 | 6% | <i>\$803.10</i> |
| PWP TAC OS Summit X480-48X | 95600-X480-48X | \$ 1,129.00 | 6% | <i>\$1,069.22</i> |
| PWP TAC OS Summit X480CORE | 95600-X480CORE | \$ 434.00 | 6% | <i>\$411.02</i> |
| PWP TAC OS Summit X480MPLS | 95600-X480MPLS | \$ 224.00 | 6% | <i>\$212.14</i> |
| PWP TAC OS X695-48Y-8C | 95600-X695-48Y-8C | \$ 1,707.00 | 6% | <i>\$1,616.61</i> |
| PWP TAC OS Summit XGM3-2SF | 95600-XGM3-2SF | \$ 143.00 | 6% | <i>\$135.43</i> |
| PWP TAC OS XR600 | 95600-XR600 | \$ 29.00 | 6% | <i>\$27.46</i> |
| PWP TAC OS -ZR-XFP | 95600-ZR-XFP | \$ 901.00 | 6% | <i>\$853.29</i> |
| PWP SOFTWARE SUPPORT 30313 | 95603-30313 | \$ 558.00 | 6% | <i>\$528.45</i> |
| PWP SOFTWARE SUPPORT 30314 | 95603-30314 | \$ 575.00 | 6% | <i>\$544.55</i> |
| PWP SOFTWARE SUPPORT 30316 | 95603-30316 | \$ 575.00 | 6% | <i>\$544.55</i> |
| PWP SOFTWARE SUPPORT 30324 | 95603-30324 | \$ 539.00 | 6% | <i>\$510.46</i> |
| PWP SOFTWARE SUPPORT 30326 | 95603-30326 | \$ 539.00 | 6% | <i>\$510.46</i> |
| PWP SOFTWARE SUPPORT 30327 | 95603-30327 | \$ 413.00 | 6% | <i>\$391.13</i> |
| PWP SOFTWARE SUPPORT 30328 | 95603-30328 | \$ 2,057.00 | 6% | <i>\$1,948.08</i> |
| PWP SOFTWARE SUPPORT 30329 | 95603-30329 | \$ 8,226.00 | 6% | <i>\$7,790.43</i> |
| PWP SOFTWARE SUPPORT 30330 | 95603-30330 | \$ 41,128.00 | 6% | <i>\$38,950.27</i> |
| PWP SOFTWARE SUPPORT 30331 | 95603-30331 | \$ 164,512.00 | 6% | <i>\$155,801.09</i> |
| PWP SOFTWARE SUPPORT 39521 | 95603-39521 | \$ 585.00 | 6% | <i>\$554.02</i> |
| PWP SOFTWARE SUPPORT 39522 | 95603-39522 | \$ 5,840.00 | 6% | <i>\$5,530.77</i> |
| PWP SOFTWARE SUPPORT 39523 | 95603-39523 | \$ 58,401.00 | 6% | <i>\$55,308.67</i> |

| | | | | |
|-------------------------------|-------------|---------------|----|---------------------|
| PWP SOFTWARE SUPPORT 39524 | 95603-39524 | \$ 292,005.00 | 6% | <i>\$276,543.34</i> |
| PWP SOFTWARE SUPPORT 39525 | 95603-39525 | \$ 584,010.00 | 6% | <i>\$553,086.67</i> |
| PWP SOFTWARE SUPPORT 48101 | 95603-48101 | \$ 6,294.00 | 6% | <i>\$5,960.73</i> |
| PWP SOFTWARE SUPPORT 85108 | 95603-85108 | \$ 248.00 | 6% | <i>\$234.87</i> |
| PWP SOFTWARE SUPPORT 85109 | 95603-85109 | \$ 498.00 | 6% | <i>\$471.63</i> |
| PWP SOFTWARE SUPPORT 85110 | 95603-85110 | \$ 868.00 | 6% | <i>\$822.04</i> |
| PWP SOFTWARE SUPPORT 85111 | 95603-85111 | \$ 1,487.00 | 6% | <i>\$1,408.26</i> |
| PWP SOFTWARE SUPPORT 85112 | 95603-85112 | \$ 2,232.00 | 6% | <i>\$2,113.82</i> |
| PWP SOFTWARE SUPPORT 85113 | 95603-85113 | \$ 3,718.00 | 6% | <i>\$3,521.13</i> |
| PWP SOFTWARE SUPPORT 85114 | 95603-85114 | \$ 4,958.00 | 6% | <i>\$4,695.47</i> |
| PWP SOFTWARE SUPPORT 85115 | 95603-85115 | \$ 248.00 | 6% | <i>\$234.87</i> |
| PWP SOFTWARE SUPPORT 85116 | 95603-85116 | \$ 372.00 | 6% | <i>\$352.30</i> |
| PWP SOFTWARE SUPPORT 85117 | 95603-85117 | \$ 621.00 | 6% | <i>\$588.12</i> |
| PWP SOFTWARE SUPPORT 85118 | 95603-85118 | \$ 744.00 | 6% | <i>\$704.61</i> |
| PWP SOFTWARE SUPPORT 85119 | 95603-85119 | \$ 1,487.00 | 6% | <i>\$1,408.26</i> |
| PWP SOFTWARE SUPPORT 85120 | 95603-85120 | \$ 1,239.00 | 6% | <i>\$1,173.39</i> |
| PWP SOFTWARE SUPPORT 88201 | 95603-88201 | \$ 2,226.00 | 6% | <i>\$2,108.13</i> |
| PWP SOFTWARE SUPPORT 88202 | 95603-88202 | \$ 6,250.00 | 6% | <i>\$5,919.06</i> |
| PWP SOFTWARE SUPPORT 88203 | 95603-88203 | \$ 23,613.00 | 6% | <i>\$22,362.69</i> |
| PWP SOFTWARE SUPPORT 88211 | 95603-88211 | \$ 2,769.00 | 6% | <i>\$2,622.38</i> |
| PWP SOFTWARE SUPPORT 88212 | 95603-88212 | \$ 5,280.00 | 6% | <i>\$5,000.42</i> |

| | | | | |
|---------------------------------|----------------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT 88213 | 95603-88213 | \$ 2,440.00 | 6% | <i>\$2,310.80</i> |
| PWP SOFTWARE SUB EXTR- IQ-TC | 95603-EXTR- IQ-TC | \$ 330.00 | 6% | <i>\$312.53</i> |
| PWP SOFTWARE SUPPORT NACVX5 | 95603-NAC- VX-5 | \$ 1,321.00 | 6% | <i>\$1,251.05</i> |
| PWP SOFTWARE SUPPORT S20097 | 95603-S20097 | \$ 21,893.00 | 6% | <i>\$20,733.77</i> |
| PWP SOFTWARE SUPPORT S20098 | 95603-S20098 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| PWP SOFTWARE SUPPORT S20099 | 95603-S20099 | \$ 5,853.00 | 6% | <i>\$5,543.08</i> |
| PWP SOFTWARE SUPPORT S20100 | 95603-S20100 | \$ 10,004.00 | 6% | <i>\$9,474.29</i> |
| PWP SOFTWARE SUPPORT S20101 | 95603-S20101 | \$ 2,589.00 | 6% | <i>\$2,451.91</i> |
| PWP SOFTWARE SUPPORT S20112 | 95603-S20112 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| PWP SOFTWARE SUPPORT S20113 | 95603-S20113 | \$ 10,004.00 | 6% | <i>\$9,474.29</i> |
| PWP SOFTWARE SUPPORT S20114 | 95603-S20114 | \$ 3,932.00 | 6% | <i>\$3,723.80</i> |
| PWP SOFTWARE SUPPORT S20116 | 95603-S20116 | \$ 3,222.00 | 6% | <i>\$3,051.40</i> |
| PWP SOFTWARE SUPPORT S20117 | 95603-S20117 | \$ 1,163.00 | 6% | <i>\$1,101.42</i> |
| PWP SOFTWARE SUPPORT S20119 | 95603-S20119 | \$ 792.00 | 6% | <i>\$750.06</i> |
| PWP SOFTWARE SUPPORT S20120 | 95603-S20120 | \$ 4,710.00 | 6% | <i>\$4,460.61</i> |
| PWP SOFTWARE SUPPORT S20121 | 95603-S20121 | \$ 14,251.00 | 6% | <i>\$13,496.41</i> |
| PWP SOFTWARE SUPPORT S20122 | 95603-S20122 | \$ 4,785.00 | 6% | <i>\$4,531.63</i> |
| PWP SOFTWARE SUPPORT S20124 | 95603-S20124 | \$ 4,379.00 | 6% | <i>\$4,147.13</i> |
| PWP SOFTWARE SUPPORT S20125 | 95603-S20125 | \$ 1,955.00 | 6% | <i>\$1,851.48</i> |
| PWP SOFTWARE SUPPORT S20127 | 95603-S20127 | \$ 2,589.00 | 6% | <i>\$2,451.91</i> |
| PWP SOFTWARE SUPPORT S20128 | 95603-S20128 | \$ 1,274.00 | 6% | <i>\$1,206.54</i> |

| | | | | |
|-----------------------------|--------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT S20129 | 95603-S20129 | \$ 6,879.00 | 6% | <i>\$6,514.76</i> |
| PWP SOFTWARE SUPPORT S20130 | 95603-S20130 | \$ 20,013.00 | 6% | <i>\$18,953.31</i> |
| PWP SOFTWARE SUPPORT S20131 | 95603-S20131 | \$ 6,087.00 | 6% | <i>\$5,764.69</i> |
| PWP SOFTWARE SUPPORT S20133 | 95603-S20133 | \$ 5,853.00 | 6% | <i>\$5,543.08</i> |
| PWP SOFTWARE SUPPORT S20134 | 95603-S20134 | \$ 2,913.00 | 6% | <i>\$2,758.76</i> |
| PWP SOFTWARE SUPPORT S20134 | 95603-S20136 | \$ 2,239.00 | 6% | <i>\$2,120.44</i> |
| PWP SOFTWARE SUPPORT S20137 | 95603-S20137 | \$ 929.00 | 6% | <i>\$879.81</i> |
| PWP SOFTWARE SUPPORT S20139 | 95603-S20139 | \$ 4,152.00 | 6% | <i>\$3,932.15</i> |
| PWP SOFTWARE SUPPORT S20140 | 95603-S20140 | \$ 1,041.00 | 6% | <i>\$985.88</i> |
| PWP SOFTWARE SUPPORT S20140 | 95603-S20141 | \$ 5,102.00 | 6% | <i>\$4,831.85</i> |
| PWP SOFTWARE SUPPORT S20142 | 95603-S20142 | \$ 3,415.00 | 6% | <i>\$3,234.18</i> |
| PWP SOFTWARE SUPPORT S20143 | 95603-S20143 | \$ 7,058.00 | 6% | <i>\$6,684.28</i> |
| PWP SOFTWARE SUPPORT S20143 | 95603-S20144 | \$ 3,127.00 | 6% | <i>\$2,961.43</i> |
| PWP SOFTWARE SUPPORT S20145 | 95603-S20145 | \$ 3,250.00 | 6% | <i>\$3,077.91</i> |
| PWP SOFTWARE SUPPORT S20146 | 95603-S20146 | \$ 13,941.00 | 6% | <i>\$13,202.82</i> |
| PWP SOFTWARE SUPPORT S20149 | 95603-S20149 | \$ 6,664.00 | 6% | <i>\$6,311.14</i> |
| PWP SOFTWARE SUPPORT S20150 | 95603-S20150 | \$ 19,043.00 | 6% | <i>\$18,034.67</i> |
| PWP SOFTWARE SUPPORT S20153 | 95603-S20153 | \$ 2,204.00 | 6% | <i>\$2,087.30</i> |
| PWP SOFTWARE SUPPORT S20154 | 95603-S20154 | \$ 9,790.00 | 6% | <i>\$9,271.62</i> |
| PWP SOFTWARE SUPPORT S20155 | 95603-S20155 | \$ 26,093.00 | 6% | <i>\$24,711.38</i> |
| PWP SOFTWARE SUPPORT S20159 | 95603-S20159 | \$ 36,026.00 | 6% | <i>\$34,118.42</i> |

| | | | | |
|-----------------------------|--------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT S20161 | 95603-S20161 | \$ 9,934.00 | 6% | <i>\$9,407.99</i> |
| PWP SOFTWARE SUPPORT S20162 | 95603-S20162 | \$ 6,347.00 | 6% | <i>\$6,010.93</i> |
| PWP SOFTWARE SUPPORT S20163 | 95603-S20163 | \$ 1,624.00 | 6% | <i>\$1,538.01</i> |
| PWP SOFTWARE SUPPORT S20164 | 95603-S20164 | \$ 1,624.00 | 6% | <i>\$1,538.01</i> |
| PWP SOFTWARE SUPPORT S20165 | 95603-S20165 | \$ 8,619.00 | 6% | <i>\$8,162.62</i> |
| PWP SOFTWARE SUPPORT S20166 | 95603-S20166 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| PWP SOFTWARE SUPPORT S20167 | 95603-S20167 | \$ 3,485.00 | 6% | <i>\$3,300.47</i> |
| PWP SOFTWARE SUPPORT S20168 | 95603-S20168 | \$ 683.00 | 6% | <i>\$646.84</i> |
| PWP SOFTWARE SUPPORT S20169 | 95603-S20169 | \$ 11,805.00 | 6% | <i>\$11,179.93</i> |
| PWP SOFTWARE SUPPORT S20170 | 95603-S20170 | \$ 2,760.00 | 6% | <i>\$2,613.86</i> |
| PWP SOFTWARE SUPPORT S20170 | 95603-S20171 | \$ 4,710.00 | 6% | <i>\$4,460.61</i> |
| PWP SOFTWARE SUPPORT S20172 | 95603-S20172 | \$ 929.00 | 6% | <i>\$879.81</i> |
| PWP SOFTWARE SUPPORT S20173 | 95603-S20173 | \$ 462.00 | 6% | <i>\$437.54</i> |
| PWP SOFTWARE SUPPORT S20174 | 95603-S20174 | \$ 3,753.00 | 6% | <i>\$3,554.28</i> |
| PWP SOFTWARE SUPPORT S20177 | 95603-S20177 | \$ 1,163.00 | 6% | <i>\$1,101.42</i> |
| PWP SOFTWARE SUPPORT S20178 | 95603-S20178 | \$ 5,853.00 | 6% | <i>\$5,543.08</i> |
| PWP SOFTWARE SUPPORT S20181 | 95603-S20181 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| PWP SOFTWARE SUPPORT S20181 | 95603-S20182 | \$ 8,619.00 | 6% | <i>\$8,162.62</i> |
| PWP SOFTWARE SUPPORT S20182 | 95603-S20185 | \$ 11,805.00 | 6% | <i>\$11,179.93</i> |
| PWP SOFTWARE SUPPORT S20187 | 95603-S20187 | \$ 3,222.00 | 6% | <i>\$3,051.40</i> |
| PWP SOFTWARE SUPPORT S20188 | 95603-S20188 | \$ 16,798.00 | 6% | <i>\$15,908.55</i> |

| | | | | |
|-----------------------------|--------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT S20189 | 95603-S20189 | \$ 28,681.00 | 6% | <i>\$27,162.34</i> |
| PWP SOFTWARE SUPPORT S20190 | 95603-S20190 | \$ 7,346.00 | 6% | <i>\$6,957.03</i> |
| PWP SOFTWARE SUPPORT S20192 | 95603-S20192 | \$ 8,619.00 | 6% | <i>\$8,162.62</i> |
| PWP SOFTWARE SUPPORT S20213 | 95603-S20213 | \$ 2,164.00 | 6% | <i>\$2,049.42</i> |
| PWP SOFTWARE SUPPORT S20245 | 95603-S20245 | \$ 7,456.00 | 6% | <i>\$7,061.20</i> |
| PWP SOFTWARE SUPPORT S20246 | 95603-S20246 | \$ 44,802.00 | 6% | <i>\$42,429.73</i> |
| PWP SOFTWARE SUPPORT S20247 | 95603-S20247 | \$ 73,131.00 | 6% | <i>\$69,258.71</i> |
| PWP SOFTWARE SUPPORT S20248 | 95603-S20248 | \$ 28,681.00 | 6% | <i>\$27,162.34</i> |
| PWP SOFTWARE SUPPORT S20252 | 95603-S20252 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP SOFTWARE SUPPORT S20253 | 95603-S20253 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| PWP SOFTWARE SUPPORT S20254 | 95603-S20254 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| PWP SOFTWARE SUPPORT S20255 | 95603-S20255 | \$ 261.00 | 6% | <i>\$247.18</i> |
| PWP SOFTWARE SUPPORT S20256 | 95603-S20256 | \$ 261.00 | 6% | <i>\$247.18</i> |
| PWP SOFTWARE SUPPORT S20257 | 95603-S20257 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP SOFTWARE SUPPORT S20258 | 95603-S20258 | \$ 318.00 | 6% | <i>\$301.16</i> |
| PWP SOFTWARE SUPPORT S20259 | 95603-S20259 | \$ 318.00 | 6% | <i>\$301.16</i> |
| PWP SOFTWARE SUPPORT S20260 | 95603-S20260 | \$ 569.00 | 6% | <i>\$538.87</i> |
| PWP SOFTWARE SUPPORT S20261 | 95603-S20261 | \$ 303.00 | 6% | <i>\$286.96</i> |
| PWP SOFTWARE SUPPORT S20268 | 95603-S20268 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP SOFTWARE SUPPORT S20269 | 95603-S20269 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| PWP SOFTWARE SUPPORT S20270 | 95603-S20270 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |

| | | | | |
|-----------------------------|--------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT S20271 | 95603-S20271 | \$ 261.00 | 6% | <i>\$247.18</i> |
| PWP SOFTWARE SUPPORT S20272 | 95603-S20272 | \$ 261.00 | 6% | <i>\$247.18</i> |
| PWP SOFTWARE SUPPORT S20273 | 95603-S20273 | \$ 32.00 | 6% | <i>\$30.31</i> |
| PWP SOFTWARE SUPPORT S20274 | 95603-S20274 | \$ 318.00 | 6% | <i>\$301.16</i> |
| PWP SOFTWARE SUPPORT S20275 | 95603-S20275 | \$ 318.00 | 6% | <i>\$301.16</i> |
| PWP SOFTWARE SUPPORT S20281 | 95603-S20281 | \$ 558.00 | 6% | <i>\$528.45</i> |
| PWP SOFTWARE SUPPORT S20281 | 95603-S20282 | \$ 558.00 | 6% | <i>\$528.45</i> |
| PWP SOFTWARE SUPPORT S20283 | 95603-S20283 | \$ 575.00 | 6% | <i>\$544.55</i> |
| PWP SOFTWARE SUPPORT S20284 | 95603-S20284 | \$ 558.00 | 6% | <i>\$528.45</i> |
| PWP SOFTWARE SUPPORT 20293 | 95603-S20293 | \$ 1,481.00 | 6% | <i>\$1,402.58</i> |
| PWP SOFTWARE SUPPORT S20296 | 95603-S20296 | \$ 4,463.00 | 6% | <i>\$4,226.68</i> |
| PWP SOFTWARE SUPPORT S20298 | 95603-S20298 | \$ 2,126.00 | 6% | <i>\$2,013.43</i> |
| PWP SOFTWARE SUPPORT S20299 | 95603-S20299 | \$ 4,802.00 | 6% | <i>\$4,547.73</i> |
| PWP SOFTWARE SUPPORT S20300 | 95603-S20300 | \$ 7,013.00 | 6% | <i>\$6,641.66</i> |
| PWP SOFTWARE SUPPORT S20301 | 95603-S20301 | \$ 10,199.00 | 6% | <i>\$9,658.96</i> |
| PWP SOFTWARE SUPPORT S20302 | 95603-S20302 | \$ 14,529.00 | 6% | <i>\$13,759.69</i> |
| PWP SOFTWARE SUPPORT S20303 | 95603-S20303 | \$ 20,402.00 | 6% | <i>\$19,321.71</i> |
| PWP SOFTWARE SUPPORT S20304 | 95603-S20304 | \$ 29,237.00 | 6% | <i>\$27,688.90</i> |
| PWP SOFTWARE SUPPORT S20309 | 95603-S20309 | \$ 165.00 | 6% | <i>\$156.26</i> |
| PWP SOFTWARE SUPPORT S20310 | 95603-S20310 | \$ 70.00 | 6% | <i>\$66.29</i> |
| PWP SOFTWARE SUPPORT S20313 | 95603-S20313 | \$ 2,597.00 | 6% | <i>\$2,459.49</i> |

| | | | | |
|-----------------------------|--------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT S20314 | 95603-S20314 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP SOFTWARE SUPPORT S20330 | 95603-S20330 | \$ 25.00 | 6% | <i>\$23.68</i> |
| PWP SOFTWARE SUPPORT S20331 | 95603-S20331 | \$ 19.00 | 6% | <i>\$17.99</i> |
| PWP SOFTWARE SUPPORT S20343 | 95603-S20343 | \$ 237.00 | 6% | <i>\$224.45</i> |
| PWP SOFTWARE SUPPORT S20344 | 95603-S20344 | \$ 2,361.00 | 6% | <i>\$2,235.99</i> |
| PWP SOFTWARE SUPPORT S20345 | 95603-S20345 | \$ 25,957.00 | 6% | <i>\$24,582.58</i> |
| PWP SOFTWARE SUPPORT S20346 | 95603-S20346 | \$ 51,915.00 | 6% | <i>\$49,166.10</i> |
| PWP SOFTWARE SUPPORT S20353 | 95603-S20353 | \$ 6,738.00 | 6% | <i>\$6,381.22</i> |
| PWP SOFTWARE SUPPORT S20354 | 95603-S20354 | \$ 534.00 | 6% | <i>\$505.72</i> |
| PWP SOFTWARE SUPPORT S20358 | 95603-S20358 | \$ 168.00 | 6% | <i>\$159.10</i> |
| PWP SOFTWARE SUPPORT S20359 | 95603-S20359 | \$ 15.00 | 6% | <i>\$14.21</i> |
| PWP SOFTWARE SUPPORT S20360 | 95603-S20360 | \$ 208.00 | 6% | <i>\$196.99</i> |
| PWP SOFTWARE SUPPORT S20361 | 95603-S20361 | \$ 814.00 | 6% | <i>\$770.90</i> |
| PWP SOFTWARE SUPPORT S20362 | 95603-S20362 | \$ 3,266.00 | 6% | <i>\$3,093.07</i> |
| PWP SOFTWARE SUPPORT S20363 | 95603-S20363 | \$ 13,067.00 | 6% | <i>\$12,375.10</i> |
| PWP SOFTWARE SUPPORT S20364 | 95603-S20364 | \$ 26,140.00 | 6% | <i>\$24,755.89</i> |
| PWP SOFTWARE SUPPORT S20365 | 95603-S20365 | \$ 15.00 | 6% | <i>\$14.21</i> |
| PWP SOFTWARE SUPPORT S20366 | 95603-S20366 | \$ 208.00 | 6% | <i>\$196.99</i> |
| PWP SOFTWARE SUPPORT S20367 | 95603-S20367 | \$ 814.00 | 6% | <i>\$770.90</i> |
| PWP SOFTWARE SUPPORT S20368 | 95603-S20368 | \$ 3,266.00 | 6% | <i>\$3,093.07</i> |
| PWP SOFTWARE SUPPORT S20369 | 95603-S20369 | \$ 13,067.00 | 6% | <i>\$12,375.10</i> |

| | | | | |
|-----------------------------|--------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT S20370 | 95603-S20370 | \$ 26,140.00 | 6% | <i>\$24,755.89</i> |
| PWP SOFTWARE SUPPORT S20371 | 95603-S20371 | \$ 15.00 | 6% | <i>\$14.21</i> |
| PWP SOFTWARE SUPPORT S20372 | 95603-S20372 | \$ 72.00 | 6% | <i>\$68.19</i> |
| PWP SOFTWARE SUPPORT S20373 | 95603-S20373 | \$ 144.00 | 6% | <i>\$136.38</i> |
| PWP SOFTWARE SUPPORT S20374 | 95603-S20374 | \$ 701.00 | 6% | <i>\$663.88</i> |
| PWP SOFTWARE SUPPORT S20375 | 95603-S20375 | \$ 1,400.00 | 6% | <i>\$1,325.87</i> |
| PWP SOFTWARE SUPPORT S20376 | 95603-S20376 | \$ 7,003.00 | 6% | <i>\$6,632.19</i> |
| PWP SOFTWARE SUPPORT S20377 | 95603-S20377 | \$ 14,004.00 | 6% | <i>\$13,262.49</i> |
| PWP SOFTWARE SUPPORT S20378 | 95603-S20378 | \$ 28,008.00 | 6% | <i>\$26,524.98</i> |
| PWP SOFTWARE SUPPORT S20400 | 95603-S20400 | \$ 1,510.00 | 6% | <i>\$1,430.05</i> |
| PWP SOFTWARE SUPPORT S20401 | 95603-S20401 | \$ 585.00 | 6% | <i>\$554.02</i> |
| PWP SOFTWARE SUPPORT S20412 | 95603-S20412 | \$ 32,675.00 | 6% | <i>\$30,944.86</i> |
| PWP SOFTWARE SUPPORT S20414 | 95603-S20414 | \$ 32,675.00 | 6% | <i>\$30,944.86</i> |
| PWP SOFTWARE SUPPORT S20415 | 95603-S20415 | \$ 8,167.00 | 6% | <i>\$7,734.56</i> |
| PWP SOFTWARE SUPPORT S20416 | 95603-S20416 | \$ 8,167.00 | 6% | <i>\$7,734.56</i> |
| PWP SOFTWARE SUPPORT S20417 | 95603-S20417 | \$ 8,167.00 | 6% | <i>\$7,734.56</i> |
| PWP SOFTWARE SUPPORT S20418 | 95603-S20418 | \$ 8,167.00 | 6% | <i>\$7,734.56</i> |
| PWP SOFTWARE SUPPORT S20419 | 95603-S20419 | \$ 32,675.00 | 6% | <i>\$30,944.86</i> |
| PWP SOFTWARE SUPPORT S20420 | 95603-S20420 | \$ 12,254.00 | 6% | <i>\$11,605.15</i> |
| PWP SOFTWARE SUPPORT S20421 | 95603-S20421 | \$ 24,500.00 | 6% | <i>\$23,202.73</i> |
| PWP SOFTWARE SUPPORT S20422 | 95603-S20422 | \$ 12,254.00 | 6% | <i>\$11,605.15</i> |

| | | | | |
|-----------------------------|--------------|-------------|----|-------------------|
| PWP SOFTWARE SUPPORT S20423 | 95603-S20423 | \$ 3,266.00 | 6% | <i>\$3,093.07</i> |
| PWP SOFTWARE SUPPORT S20424 | 95603-S20424 | \$ 1,637.00 | 6% | <i>\$1,550.32</i> |
| PWP SOFTWARE SUPPORT S20425 | 95603-S20425 | \$ 3,266.00 | 6% | <i>\$3,093.07</i> |
| PWP SOFTWARE SUPPORT S20426 | 95603-S20426 | \$ 1,637.00 | 6% | <i>\$1,550.32</i> |
| PWP SOFTWARE SUPPORT S20428 | 95603-S20428 | \$ 1,539.00 | 6% | <i>\$1,457.51</i> |
| PWP SOFTWARE SUPPORT S20429 | 95603-S20429 | \$ 796.00 | 6% | <i>\$753.85</i> |
| PWP SOFTWARE SUPPORT S20430 | 95603-S20430 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |
| PWP SOFTWARE SUPPORT S20431 | 95603-S20431 | \$ 1,990.00 | 6% | <i>\$1,884.63</i> |
| PWP SOFTWARE SUPPORT S20434 | 95603-S20434 | \$ 1,818.00 | 6% | <i>\$1,721.74</i> |
| PWP SOFTWARE SUPPORT S20435 | 95603-S20435 | \$ 1,398.00 | 6% | <i>\$1,323.98</i> |
| PWP SOFTWARE SUPPORT S20437 | 95603-S20437 | \$ 942.00 | 6% | <i>\$892.12</i> |
| PWP SOFTWARE SUPPORT S20438 | 95603-S20438 | \$ 1,398.00 | 6% | <i>\$1,323.98</i> |
| PWP SOFTWARE SUPPORT S20439 | 95603-S20439 | \$ 3,360.00 | 6% | <i>\$3,182.09</i> |
| PWP SOFTWARE SUPPORT S20440 | 95603-S20440 | \$ 2,354.00 | 6% | <i>\$2,229.36</i> |
| PWP SOFTWARE SUPPORT S20441 | 95603-S20441 | \$ 945.00 | 6% | <i>\$894.96</i> |
| PWP SOFTWARE SUPPORT S20442 | 95603-S20442 | \$ 1,867.00 | 6% | <i>\$1,768.14</i> |
| PWP SOFTWARE SUPPORT S20443 | 95603-S20443 | \$ 1,179.00 | 6% | <i>\$1,116.57</i> |
| PWP SOFTWARE SUPPORT S20453 | 95603-S20453 | \$ 1,565.00 | 6% | <i>\$1,482.13</i> |
| PWP SOFTWARE SUPPORT S20463 | 95603-S20463 | \$ 157.00 | 6% | <i>\$148.69</i> |
| PWP SOFTWARE SUPPORT S20465 | 95603-S20465 | \$ 271.00 | 6% | <i>\$256.65</i> |
| PWP SOFTWARE SUPPORT S20477 | 95603-S20477 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |

| | | | | |
|-----------------------------|--------------|-------------|----|-------------------|
| PWP SOFTWARE SUPPORT S20478 | 95603-S20478 | \$ 960.00 | 6% | <i>\$909.17</i> |
| PWP SOFTWARE SUPPORT S20479 | 95603-S20479 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| PWP SOFTWARE SUPPORT S20480 | 95603-S20480 | \$ 2,738.00 | 6% | <i>\$2,593.02</i> |
| PWP SOFTWARE SUPPORT S20481 | 95603-S20481 | \$ 1,097.00 | 6% | <i>\$1,038.91</i> |
| PWP SOFTWARE SUPPORT S22014 | 95603-S22014 | \$ 2,298.00 | 6% | <i>\$2,176.32</i> |
| PWP SOFTWARE SUPPORT S22015 | 95603-S22015 | \$ 735.00 | 6% | <i>\$696.08</i> |
| PWP SOFTWARE SUPPORT S22016 | 95603-S22016 | \$ 2,026.00 | 6% | <i>\$1,918.72</i> |
| PWP SOFTWARE SUPPORT S22017 | 95603-S22017 | \$ 735.00 | 6% | <i>\$696.08</i> |
| PWP SOFTWARE SUPPORT S22018 | 95603-S22018 | \$ 2,298.00 | 6% | <i>\$2,176.32</i> |
| PWP SOFTWARE SUPPORT S22019 | 95603-S22019 | \$ 2,298.00 | 6% | <i>\$2,176.32</i> |
| PWP SOFTWARE SUPPORT S22020 | 95603-S22020 | \$ 2,298.00 | 6% | <i>\$2,176.32</i> |
| PWP SOFTWARE SUPPORT S22021 | 95603-S22021 | \$ 2,298.00 | 6% | <i>\$2,176.32</i> |
| PWP SOFTWARE SUPPORT S22022 | 95603-S22022 | \$ 2,026.00 | 6% | <i>\$1,918.72</i> |
| PWP SOFTWARE SUPPORT S22027 | 95603-S22027 | \$ 1,415.00 | 6% | <i>\$1,340.08</i> |
| PWP SOFTWARE SUPPORT S22028 | 95603-S22028 | \$ 1,324.00 | 6% | <i>\$1,253.89</i> |
| PWP SOFTWARE SUPPORT S22030 | 95603-S22030 | \$ 793.00 | 6% | <i>\$751.01</i> |
| PWP SOFTWARE SUPPORT S22031 | 95603-S22031 | \$ 1,591.00 | 6% | <i>\$1,506.76</i> |
| PWP SOFTWARE SUPPORT S22032 | 95603-S22032 | \$ 793.00 | 6% | <i>\$751.01</i> |
| PWP SOFTWARE SUPPORT S22035 | 95603-S22035 | \$ 761.00 | 6% | <i>\$720.71</i> |
| PWP SOFTWARE SUPPORT S22036 | 95603-S22036 | \$ 713.00 | 6% | <i>\$675.25</i> |
| PWP SOFTWARE SUPPORT S22037 | 95603-S22037 | \$ 1,101.00 | 6% | <i>\$1,042.70</i> |

| | | | | |
|-----------------------------|--------------|-------------|----|-------------------|
| PWP SOFTWARE SUPPORT S22038 | 95603-S22038 | \$ 1,101.00 | 6% | <i>\$1,042.70</i> |
| PWP SOFTWARE SUPPORT S22039 | 95603-S22039 | \$ 1,101.00 | 6% | <i>\$1,042.70</i> |
| PWP SOFTWARE SUPPORT S22040 | 95603-S22040 | \$ 1,134.00 | 6% | <i>\$1,073.95</i> |
| PWP SOFTWARE SUPPORT S22041 | 95603-S22041 | \$ 1,062.00 | 6% | <i>\$1,005.77</i> |
| PWP SOFTWARE SUPPORT S22042 | 95603-S22042 | \$ 1,726.00 | 6% | <i>\$1,634.61</i> |
| PWP SOFTWARE SUPPORT S22044 | 95603-S22044 | \$ 451.00 | 6% | <i>\$427.12</i> |
| PWP SOFTWARE SUPPORT S22045 | 95603-S22045 | \$ 422.00 | 6% | <i>\$399.66</i> |
| PWP SOFTWARE SUPPORT S22046 | 95603-S22046 | \$ 1,019.00 | 6% | <i>\$965.04</i> |
| PWP SOFTWARE SUPPORT S22047 | 95603-S22047 | \$ 954.00 | 6% | <i>\$903.49</i> |
| PWP SOFTWARE SUPPORT S22051 | 95603-S22051 | \$ 1,311.00 | 6% | <i>\$1,241.58</i> |
| PWP SOFTWARE SUPPORT S22055 | 95603-S22055 | \$ 1,656.00 | 6% | <i>\$1,568.31</i> |
| PWP SOFTWARE SUPPORT S22057 | 95603-S22057 | \$ 4,587.00 | 6% | <i>\$4,344.12</i> |
| PWP SOFTWARE SUPPORT S22063 | 95603-S22063 | \$ 2,265.00 | 6% | <i>\$2,145.07</i> |
| PWP SOFTWARE SUPPORT S22064 | 95603-S22064 | \$ 954.00 | 6% | <i>\$903.49</i> |
| PWP SOFTWARE SUPPORT S22065 | 95603-S22065 | \$ 3,220.00 | 6% | <i>\$3,049.50</i> |
| PWP SOFTWARE SUPPORT S22066 | 95603-S22066 | \$ 1,196.00 | 6% | <i>\$1,132.67</i> |
| PWP SOFTWARE SUPPORT S22067 | 95603-S22067 | \$ 5,488.00 | 6% | <i>\$5,197.41</i> |
| PWP SOFTWARE SUPPORT S22068 | 95603-S22068 | \$ 1,196.00 | 6% | <i>\$1,132.67</i> |
| PWP SOFTWARE SUPPORT S22069 | 95603-S22069 | \$ 2,027.00 | 6% | <i>\$1,919.67</i> |
| PWP SOFTWARE SUPPORT S22070 | 95603-S22070 | \$ 4,532.00 | 6% | <i>\$4,292.03</i> |
| PWP SOFTWARE SUPPORT S22072 | 95603-S22072 | \$ 1,936.00 | 6% | <i>\$1,833.49</i> |

| | | | | |
|-----------------------------|--------------|-------------|----|-------------------|
| PWP SOFTWARE SUPPORT S22073 | 95603-S22073 | \$ 1,936.00 | 6% | <i>\$1,833.49</i> |
| PWP SOFTWARE SUPPORT S22074 | 95603-S22074 | \$ 279.00 | 6% | <i>\$264.23</i> |
| PWP SOFTWARE SUPPORT S22075 | 95603-S22075 | \$ 1,678.00 | 6% | <i>\$1,589.15</i> |
| PWP SOFTWARE SUPPORT S22076 | 95603-S22076 | \$ 132.00 | 6% | <i>\$125.01</i> |
| PWP SOFTWARE SUPPORT S22077 | 95603-S22077 | \$ 563.00 | 6% | <i>\$533.19</i> |
| PWP SOFTWARE SUPPORT S22078 | 95603-S22078 | \$ 704.00 | 6% | <i>\$666.72</i> |
| PWP SOFTWARE SUPPORT S22079 | 95603-S22079 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PWP SOFTWARE SUPPORT S22080 | 95603-S22080 | \$ 35.00 | 6% | <i>\$33.15</i> |
| PWP SOFTWARE SUPPORT S22081 | 95603-S22081 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PWP SOFTWARE SUPPORT S22084 | 95603-S22084 | \$ 733.00 | 6% | <i>\$694.19</i> |
| PWP SOFTWARE SUPPORT S22085 | 95603-S22085 | \$ 924.00 | 6% | <i>\$875.07</i> |
| PWP SOFTWARE SUPPORT S22086 | 95603-S22086 | \$ 139.00 | 6% | <i>\$131.64</i> |
| PWP SOFTWARE SUPPORT S22087 | 95603-S22087 | \$ 592.00 | 6% | <i>\$560.65</i> |
| PWP SOFTWARE SUPPORT S22088 | 95603-S22088 | \$ 858.00 | 6% | <i>\$812.57</i> |
| PWP SOFTWARE SUPPORT S22089 | 95603-S22089 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PWP SOFTWARE SUPPORT S22090 | 95603-S22090 | \$ 388.00 | 6% | <i>\$367.46</i> |
| PWP SOFTWARE SUPPORT S22091 | 95603-S22091 | \$ 592.00 | 6% | <i>\$560.65</i> |
| PWP SOFTWARE SUPPORT S22092 | 95603-S22092 | \$ 388.00 | 6% | <i>\$367.46</i> |
| PWP SOFTWARE SUPPORT S22093 | 95603-S22093 | \$ 592.00 | 6% | <i>\$560.65</i> |
| PWP SOFTWARE SUPPORT S22094 | 95603-S22094 | \$ 582.00 | 6% | <i>\$551.18</i> |
| PWP SOFTWARE SUPPORT S22095 | 95603-S22095 | \$ 582.00 | 6% | <i>\$551.18</i> |

| | | | | |
|------------------------------|--------------|--------------|----|--------------------|
| PWP SOFTWARE SUPPORT S22117 | 95603-S22117 | \$ 1,294.00 | 6% | <i>\$1,225.48</i> |
| PWP SOFTWARE SUPPORT S22119 | 95603-S22119 | \$ 3,231.00 | 6% | <i>\$3,059.92</i> |
| PWP SOFTWARE SUPPORT S22123 | 95603-S22123 | \$ 175.00 | 6% | <i>\$165.73</i> |
| PWP SOFTWARE SUPPORT S22124 | 95603-S22124 | \$ 397.00 | 6% | <i>\$375.98</i> |
| PWP SOFTWARE SUPPORT S22139 | 95603-S22139 | \$ 492.00 | 6% | <i>\$465.95</i> |
| PWP SOFTWARE SUPPORTB S22140 | 95603-S22140 | \$ 798.00 | 6% | <i>\$755.75</i> |
| PWP SOFTWARE SUPPORT S22141 | 95603-S22141 | \$ 2,989.00 | 6% | <i>\$2,830.73</i> |
| PWP SOFTWARE SUPPORT S22142 | 95603-S22142 | \$ 4,333.00 | 6% | <i>\$4,103.57</i> |
| PWP SOFTWARE SUPPORT S22143 | 95603-S22143 | \$ 422.00 | 6% | <i>\$399.66</i> |
| PWP SOFTWARE SUPPORT S22152 | 95603-S22152 | \$ 6,811.00 | 6% | <i>\$6,450.36</i> |
| PWP SOFTWARE SUPPORT S22153 | 95603-S22153 | \$ 10,861.00 | 6% | <i>\$10,285.91</i> |
| PWP SOFTWARE SUPPORT S22154 | 95603-S22154 | \$ 18,992.00 | 6% | <i>\$17,986.37</i> |
| PWP SOFTWARE SUPPORT S22155 | 95603-S22155 | \$ 20,117.00 | 6% | <i>\$19,051.80</i> |
| PWP SOFTWARE SUPPORT S22156 | 95603-S22156 | \$ 6,811.00 | 6% | <i>\$6,450.36</i> |
| PWP SOFTWARE SUPPORT S22157 | 95603-S22157 | \$ 10,861.00 | 6% | <i>\$10,285.91</i> |
| PWP SOFTWARE SUPPORT S22158 | 95603-S22158 | \$ 6,811.00 | 6% | <i>\$6,450.36</i> |
| PWP SOFTWARE SUPPORT S22159 | 95603-S22159 | \$ 10,861.00 | 6% | <i>\$10,285.91</i> |
| PWP SOFTWARE SUPPORT S22160 | 95603-S22160 | \$ 6,811.00 | 6% | <i>\$6,450.36</i> |
| PWP SOFTWARE SUPPORT S22161 | 95603-S22161 | \$ 8,815.00 | 6% | <i>\$8,348.25</i> |
| PWP SOFTWARE SUPPORT S22162 | 95603-S22162 | \$ 15,415.00 | 6% | <i>\$14,598.78</i> |
| PWP SOFTWARE SUPPORT S22163 | 95603-S22163 | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |

| | | | | |
|--|-------------------------|--------------|----|-------------|
| PWP SOFTWARE SUPPORT S22164 | 95603-S22164 | \$ 2,996.00 | 6% | \$2,837.36 |
| PWP SOFTWARE SUPPORT S22165 | 95603-S22165 | \$ 5,617.00 | 6% | \$5,319.58 |
| PWP SOFTWARE SUPPORT S22166 | 95603-S22166 | \$ 4,124.00 | 6% | \$3,905.63 |
| PWP SOFTWARE SUPPORT S22167 | 95603-S22167 | \$ 5,350.00 | 6% | \$5,066.72 |
| PWP SOFTWARE SUPPORT S22173 | 95603-S22173 | \$ 729.00 | 6% | \$690.40 |
| PWP SOFTWARE SUPPORT S22174 | 95603-S22174 | \$ 1,457.00 | 6% | \$1,379.85 |
| PWP SOFTWARE SUPPORT S22175 | 95603-S22175 | \$ 2,915.00 | 6% | \$2,760.65 |
| PWP SOFTWARE SUPPORT XCC-ACT-V5-VT | 95603-XCC-ACT-V5-VT | \$ 454.00 | 6% | \$429.96 |
| PWP SOFTWARE SUPPORT XCC-ACT-V5-VT-EGY | 95603-XCC-ACT-V5-VT-EGY | \$ 454.00 | 6% | \$429.96 |
| PWP SOFTWARE SUPPORT XESNPLUSWPKG | 95603-XESN-PLUS-SW-PKG | \$ 11,998.00 | 6% | \$11,362.71 |
| PWP SOFTWARE SUB XIQ-CACT-APP | 95603-XIQ-CACT-APP | \$ 330.00 | 6% | \$312.53 |
| PWP SOFTWARE SUPPORT XIQ-CACT-VT | 95603-XIQ-CACT-VT | \$ 432.00 | 6% | \$409.13 |
| PWP SOFTWARE SUPPORT XIQ-CACT-VT-EGY | 95603-XIQ-CACT-VT-EGY | \$ 432.00 | 6% | \$409.13 |
| PWP SOFTWARE SUPPORT XIQ-PIL-P-OP | 95603-XIQ-PIL-P-OP | \$ 63.00 | 6% | \$59.66 |
| PWP SOFTWARE SUPPORT XVM-LIC-1 | 95603-XVM-LIC-1 | \$ 671.00 | 6% | \$635.47 |
| PWP NBD AHR Optics 10200 | 95604-10200 | \$ 1,802.00 | 6% | \$1,706.58 |
| PWP NBD AHR Optics 10320 | 95604-10320 | \$ 1,977.00 | 6% | \$1,872.32 |
| PWP NBD AHR 10330 | 95604-10330 | \$ 4,848.00 | 6% | \$4,591.30 |
| PWP NBD AHR 10331 | 95604-10331 | \$ 2,237.00 | 6% | \$2,118.55 |
| PWP NBD AHR 10335 | 95604-10335 | \$ 3,414.00 | 6% | \$3,233.23 |
| PWP NBD AHR 10403 | 95604-10403 | \$ 4,235.00 | 6% | \$4,010.76 |
| PWP NBD AHR 10404 | 95604-10404 | \$ 2,083.00 | 6% | \$1,972.71 |
| PWP NBD AHR 10441 | 95604-10441 | \$ 1,395.00 | 6% | \$1,321.13 |
| PWP NBD AHR 10442 | 95604-10442 | \$ 1,484.00 | 6% | \$1,405.42 |

| | | | | |
|--------------------------|--------------|-------------|----|------------|
| PWP NBD AHR 1130C | 95604-1130C | \$ 960.00 | 6% | \$909.17 |
| PWP NBD AHR E4G 16119 | 95604-16119 | \$ 257.00 | 6% | \$243.39 |
| PWP NBD AHR E4G 16120 | 95604-16120 | \$ 316.00 | 6% | \$299.27 |
| PWP NBD AHR E4G 16126 | 95604-16126 | \$ 257.00 | 6% | \$243.39 |
| PWP NBD AHR E4G 16127 | 95604-16127 | \$ 270.00 | 6% | \$255.70 |
| PWP NBD AHR 16172 | 95604-16172 | \$ 267.00 | 6% | \$252.86 |
| PWP NBD AHR -16172T | 95604-16172T | \$ 317.00 | 6% | \$300.21 |
| PWP NBD AHR 16173 | 95604-16173 | \$ 275.00 | 6% | \$260.44 |
| PWP NBD AHR -16173T | 95604-16173T | \$ 326.00 | 6% | \$308.74 |
| PWP NBD AHR 16174 | 95604-16174 | \$ 422.00 | 6% | \$399.66 |
| PWP NBD AHR 16175 | 95604-16175 | \$ 450.00 | 6% | \$426.17 |
| PWP NBD AHR 16176 | 95604-16176 | \$ 392.00 | 6% | \$371.24 |
| PWP NBD AHR 16177 | 95604-16177 | \$ 385.00 | 6% | \$364.61 |
| PWP NBD AHR -16177T | 95604-16177T | \$ 488.00 | 6% | \$462.16 |
| PWP NBD AHR 16178 | 95604-16178 | \$ 569.00 | 6% | \$538.87 |
| PWP NBD AHR 16179 | 95604-16179 | \$ 584.00 | 6% | \$553.08 |
| PWP NBD AHR -16179T | 95604-16179T | \$ 702.00 | 6% | \$664.83 |
| PWP NBD AHR 16301T | 95604-16301T | \$ 1,521.00 | 6% | \$1,440.46 |
| PWP NBD AHR 16303T | 95604-16303T | \$ 1,521.00 | 6% | \$1,440.46 |
| PWP NBD AHR 16304T | 95604-16304T | \$ 2,027.00 | 6% | \$1,919.67 |
| PWP NBD AHR 16401T | 95604-16401T | \$ 721.00 | 6% | \$682.82 |
| PWP NBD AHR 16402T | 95604-16402T | \$ 1,087.00 | 6% | \$1,029.44 |
| PWP NBD AHR 16403T | 95604-16403T | \$ 963.00 | 6% | \$912.01 |
| PWP NBD AHR 16404T | 95604-16404T | \$ 963.00 | 6% | \$912.01 |
| PWP NBD AHR 16405T | 95604-16405T | \$ 1,269.00 | 6% | \$1,201.81 |
| PWP NBD AHR 16406T | 95604-16406T | \$ 1,695.00 | 6% | \$1,605.25 |
| PWP NBD AHR E4G 16431 | 95604-16431 | \$ 1,071.00 | 6% | \$1,014.29 |
| PWP NBD AHR E4G 16432 | 95604-16432 | \$ 1,162.00 | 6% | \$1,100.47 |
| PWP NBD AHR E4G 16440 | 95604-16440 | \$ 674.00 | 6% | \$638.31 |
| PWP NBD AHR E4G 16441 | 95604-16441 | \$ 606.00 | 6% | \$573.91 |
| PWP NBD AHR E4G 16442 | 95604-16442 | \$ 270.00 | 6% | \$255.70 |
| PWP NBD AHR E4G 16444 | 95604-16444 | \$ 136.00 | 6% | \$128.80 |
| PWP NBD AHR Summit 16501 | 95604-16501 | \$ 145.00 | 6% | \$137.32 |
| PWP NBD AHR 16501T | 95604-16501T | \$ 184.00 | 6% | \$174.26 |
| PWP NBD AHR Summit 16502 | 95604-16502 | \$ 213.00 | 6% | \$201.72 |
| PWP NBD AHR 16502T | 95604-16502T | \$ 257.00 | 6% | \$243.39 |
| PWP NBD AHR Summit 16503 | 95604-16503 | \$ 177.00 | 6% | \$167.63 |
| PWP NBD AHR 16503T | 95604-16503T | \$ 229.00 | 6% | \$216.87 |
| PWP NBD AHR Summit 16504 | 95604-16504 | \$ 288.00 | 6% | \$272.75 |
| PWP NBD AHR 16504T | 95604-16504T | \$ 340.00 | 6% | \$322.00 |
| PWP NBD AHR Summit 16505 | 95604-16505 | \$ 318.00 | 6% | \$301.16 |
| PWP NBD AHR 16505T | 95604-16505T | \$ 388.00 | 6% | \$367.46 |

| | | | | |
|--------------------------|--------------|-----------|----|----------|
| PWP NBD AHR Summit 16506 | 95604-16506 | \$ 491.00 | 6% | \$465.00 |
| PWP NBD AHR 16506T | 95604-16506T | \$ 603.00 | 6% | \$571.07 |
| PWP NBD AHR Summit 16507 | 95604-16507 | \$ 448.00 | 6% | \$424.28 |
| PWP NBD AHR 16507T | 95604-16507T | \$ 529.00 | 6% | \$500.99 |
| PWP NBD AHR Summit 16508 | 95604-16508 | \$ 558.00 | 6% | \$528.45 |
| PWP NBD AHR 16508T | 95604-16508T | \$ 668.00 | 6% | \$632.63 |
| PWP NBD AHR Summit 16509 | 95604-16509 | \$ 558.00 | 6% | \$528.45 |
| PWP NBD AHR 16509T | 95604-16509T | \$ 668.00 | 6% | \$632.63 |
| PWP NBD AHR Summit 16510 | 95604-16510 | \$ 668.00 | 6% | \$632.63 |
| PWP NBD AHR 16510T | 95604-16510T | \$ 800.00 | 6% | \$757.64 |
| PWP NBD AHR-16513 | 95604-16513 | \$ 404.00 | 6% | \$382.61 |
| PWP NBD AHR-16514 | 95604-16514 | \$ 656.00 | 6% | \$621.26 |
| PWP NBD AHR 16515 | 95604-16515 | \$ 113.00 | 6% | \$107.02 |
| PWP NBD AHR-16516 | 95604-16516 | \$ 121.00 | 6% | \$114.59 |
| PWP NBD AHR 16517 | 95604-16517 | \$ 241.00 | 6% | \$228.24 |
| PWP NBD AHR-16518 | 95604-16518 | \$ 215.00 | 6% | \$203.62 |
| PWP-NBD AHR 16519 | 95604-16519 | \$ 221.00 | 6% | \$209.30 |
| PWP-NBD AHR 16520 | 95604-16520 | \$ 353.00 | 6% | \$334.31 |
| PWP NBD AHR 16530 | 95604-16530 | \$ 135.00 | 6% | \$127.85 |
| PWP NBD AHR 16531 | 95604-16531 | \$ 183.00 | 6% | \$173.31 |
| PWP NBD AHR 16531T | 95604-16531T | \$ 199.00 | 6% | \$188.46 |
| PWP NBD AHR 16532 | 95604-16532 | \$ 183.00 | 6% | \$173.31 |
| PWP NBD AHR 16532T | 95604-16532T | \$ 199.00 | 6% | \$188.46 |
| PWP NBD AHR 16533 | 95604-16533 | \$ 260.00 | 6% | \$246.23 |
| PWP NBD AHR 16533T | 95604-16533T | \$ 283.00 | 6% | \$268.02 |
| PWP NBD AHR 16534 | 95604-16534 | \$ 275.00 | 6% | \$260.44 |
| PWP NBD AHR 16535 | 95604-16535 | \$ 404.00 | 6% | \$382.61 |
| PWP NBD AHR 16535A | 95604-16535A | \$ 404.00 | 6% | \$382.61 |
| PWP NBD AHR 16535T | 95604-16535T | \$ 450.00 | 6% | \$426.17 |
| PWP NBD AHR 16536 | 95604-16536 | \$ 188.00 | 6% | \$178.05 |
| PWP NBD AHR 16537 | 95604-16537 | \$ 257.00 | 6% | \$243.39 |
| PWP NBD AHR 16538 | 95604-16538 | \$ 304.00 | 6% | \$287.90 |
| PWP NBD AHR 16538T | 95604-16538T | \$ 372.00 | 6% | \$352.30 |
| PWP NBD AHR 16539 | 95604-16539 | \$ 400.00 | 6% | \$378.82 |
| PWP NBD AHR 16540 | 95604-16540 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR 16541 | 95604-16541 | \$ 106.00 | 6% | \$100.39 |
| PWP NBD AHR 16560 | 95604-16560 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR 16561 | 95604-16561 | \$ 90.00 | 6% | \$85.23 |
| PWP NBD AHR 16562 | 95604-16562 | \$ 109.00 | 6% | \$103.23 |
| PWP NBD AHR 16563 | 95604-16563 | \$ 144.00 | 6% | \$136.38 |
| PWP NBD AHR 16564 | 95604-16564 | \$ 178.00 | 6% | \$168.57 |
| PWP NBD AHR 16565 | 95604-16565 | \$ 267.00 | 6% | \$252.86 |

| | | | | |
|---------------------|--------------|-------------|----|------------|
| PWP NBD AHR 16566 | 95604-16566 | \$ 41.00 | 6% | \$38.83 |
| PWP NBD AHR 16567 | 95604-16567 | \$ 75.00 | 6% | \$71.03 |
| PWP NBD AHR 16568 | 95604-16568 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR 16569 | 95604-16569 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR 16570 | 95604-16570 | \$ 109.00 | 6% | \$103.23 |
| PWP NBD AHR 16571 | 95604-16571 | \$ 178.00 | 6% | \$168.57 |
| PWP NBD AHR 16701 | 95604-16701 | \$ 395.00 | 6% | \$374.08 |
| PWP NBD AHR 16702 | 95604-16702 | \$ 573.00 | 6% | \$542.66 |
| PWP NBD AHR 16703 | 95604-16703 | \$ 458.00 | 6% | \$433.75 |
| PWP NBD AHR -16703T | 95604-16703T | \$ 545.00 | 6% | \$516.14 |
| PWP NBD AHR 16704 | 95604-16704 | \$ 669.00 | 6% | \$633.58 |
| PWP NBD AHR -16704T | 95604-16704T | \$ 802.00 | 6% | \$759.53 |
| PWP NBD AHR 16705 | 95604-16705 | \$ 573.00 | 6% | \$542.66 |
| PWP NBD AHR -16705T | 95604-16705T | \$ 695.00 | 6% | \$658.20 |
| PWP NBD AHR 16706 | 95604-16706 | \$ 873.00 | 6% | \$826.77 |
| PWP NBD AHR -16706T | 95604-16706T | \$ 1,054.00 | 6% | \$998.19 |
| PWP NBD AHR 16710 | 95604-16710 | \$ 175.00 | 6% | \$165.73 |
| PWP NBD AHR 16710T | 95604-16710T | \$ 215.00 | 6% | \$203.62 |
| PWP NBD AHR 16711 | 95604-16711 | \$ 75.00 | 6% | \$71.03 |
| PWP NBD AHR 16711T | 95604-16711T | \$ 88.00 | 6% | \$83.34 |
| PWP NBD AHR 16712 | 95604-16712 | \$ 99.00 | 6% | \$93.76 |
| PWP NBD AHR 16712T | 95604-16712T | \$ 118.00 | 6% | \$111.75 |
| PWP NBD AHR 16713 | 95604-16713 | \$ 47.00 | 6% | \$44.51 |
| PWP NBD AHR 16713T | 95604-16713T | \$ 54.00 | 6% | \$51.14 |
| PWP NBD AHR 16715 | 95604-16715 | \$ 73.00 | 6% | \$69.13 |
| PWP NBD AHR 16715T | 95604-16715T | \$ 88.00 | 6% | \$83.34 |
| PWP NBD AHR 16716 | 95604-16716 | \$ 305.00 | 6% | \$288.85 |
| PWP NBD AHR -16716T | 95604-16716T | \$ 362.00 | 6% | \$342.83 |
| PWP NBD AHR 16717 | 95604-16717 | \$ 463.00 | 6% | \$438.48 |
| PWP NBD AHR 16718 | 95604-16718 | \$ 329.00 | 6% | \$311.58 |
| PWP NBD AHR -16718T | 95604-16718T | \$ 400.00 | 6% | \$378.82 |
| PWP NBD AHR 16719 | 95604-16719 | \$ 491.00 | 6% | \$465.00 |
| PWP NBD AHR -16719T | 95604-16719T | \$ 589.00 | 6% | \$557.81 |
| PWP NBD AHR 16720 | 95604-16720 | \$ 740.00 | 6% | \$700.82 |
| PWP NBD AHR 16720T | 95604-16720T | \$ 860.00 | 6% | \$814.46 |
| PWP NBD AHR 16756 | 95604-16756 | \$ 540.00 | 6% | \$511.41 |
| PWP NBD AHR 16756T | 95604-16756T | \$ 642.00 | 6% | \$608.01 |
| PWP NBD AHR 16757 | 95604-16757 | \$ 509.00 | 6% | \$482.05 |
| PWP NBD AHR 16757T | 95604-16757T | \$ 603.00 | 6% | \$571.07 |
| PWP NBD AHR 16790 | 95604-16790 | \$ 1,189.00 | 6% | \$1,126.04 |
| PWP NBD AHR 16791 | 95604-16791 | \$ 1,532.00 | 6% | \$1,450.88 |
| PWP NBD AHR 16801 | 95604-16801 | \$ 136.00 | 6% | \$128.80 |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| PWP NBD AHR 16802 | 95604-16802 | \$ 170.00 | 6% | <i>\$161.00</i> |
| PWP NBD AHR 16803 | 95604-16803 | \$ 177.00 | 6% | <i>\$167.63</i> |
| PWP NBD AHR 16804 | 95604-16804 | \$ 217.00 | 6% | <i>\$205.51</i> |
| PWP NBD AHR 16805 | 95604-16805 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR 16806 | 95604-16806 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR Summit 17101 | 95604-17101 | \$ 2,255.00 | 6% | <i>\$2,135.60</i> |
| PWP NBD AHR 17101T | 95604-17101T | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| PWP NBD AHR Summit 17102 | 95604-17102 | \$ 2,255.00 | 6% | <i>\$2,135.60</i> |
| PWP NBD AHR 17102T | 95604-17102T | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| PWP NBD AHR Summit 17103 | 95604-17103 | \$ 1,572.00 | 6% | <i>\$1,488.76</i> |
| PWP NBD AHR Summit 17103C | 95604-17103C | \$ 1,525.00 | 6% | <i>\$1,444.25</i> |
| PWP NBD AHR 17103T | 95604-17103T | \$ 2,011.00 | 6% | <i>\$1,904.52</i> |
| PWP NBD AHR Summit 17104 | 95604-17104 | \$ 1,572.00 | 6% | <i>\$1,488.76</i> |
| PWP NBD AHR 17104T | 95604-17104T | \$ 2,011.00 | 6% | <i>\$1,904.52</i> |
| PWP NBD AHR Summit 17121 | 95604-17121 | \$ 449.00 | 6% | <i>\$425.23</i> |
| PWP NBD AHR Summit 17122 | 95604-17122 | \$ 278.00 | 6% | <i>\$263.28</i> |
| PWP NBD AHR -17200 | 95604-17200 | \$ 3,546.00 | 6% | <i>\$3,358.24</i> |
| PWP NBD AHR 17200T | 95604-17200T | \$ 4,060.00 | 6% | <i>\$3,845.02</i> |
| PWP NBD AHR Summit 17201 | 95604-17201 | \$ 3,546.00 | 6% | <i>\$3,358.24</i> |
| PWP NBD AHR 17201T | 95604-17201T | \$ 4,060.00 | 6% | <i>\$3,845.02</i> |
| PWP NBD AHR Summit 17202 | 95604-17202 | \$ 3,546.00 | 6% | <i>\$3,358.24</i> |
| PWP NBD AHR 17202T | 95604-17202T | \$ 4,060.00 | 6% | <i>\$3,845.02</i> |
| PWP NBD AHR Summit 17203 | 95604-17203 | \$ 3,605.00 | 6% | <i>\$3,414.12</i> |
| PWP NBD AHR 17203T | 95604-17203T | \$ 4,118.00 | 6% | <i>\$3,899.95</i> |
| PWP NBD AHR Summit 17204 | 95604-17204 | \$ 3,605.00 | 6% | <i>\$3,414.12</i> |
| PWP NBD AHR 17204T | 95604-17204T | \$ 4,118.00 | 6% | <i>\$3,899.95</i> |
| PWP NBD AHR Summit 17205 | 95604-17205 | \$ 3,578.00 | 6% | <i>\$3,388.54</i> |
| PWP NBD AHR 17205T | 95604-17205T | \$ 4,087.00 | 6% | <i>\$3,870.59</i> |
| PWP NBD AHR Summit 17206 | 95604-17206 | \$ 3,578.00 | 6% | <i>\$3,388.54</i> |
| PWP NBD AHR 17206T | 95604-17206T | \$ 4,087.00 | 6% | <i>\$3,870.59</i> |
| PWP NBD AHR 17300 | 95604-17300 | \$ 2,347.00 | 6% | <i>\$2,222.73</i> |
| PWP NBD AHR 17310 | 95604-17310 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| PWP NBD AHR -17310T | 95604-17310T | \$ 2,560.00 | 6% | <i>\$2,424.45</i> |
| PWP NBD AHR 17350 | 95604-17350 | \$ 2,148.00 | 6% | <i>\$2,034.26</i> |
| PWP NBD AHR 17360 | 95604-17360 | \$ 2,643.00 | 6% | <i>\$2,503.05</i> |
| PWP NBD AHR 17401 | 95604-17401 | \$ 326.00 | 6% | <i>\$308.74</i> |
| PWP NBD AHR 17401G | 95604-17401G | \$ 388.00 | 6% | <i>\$367.46</i> |
| PWP NBD AHR 17401T | 95604-17401T | \$ 368.00 | 6% | <i>\$348.51</i> |
| PWP NBD AHR 17402 | 95604-17402 | \$ 467.00 | 6% | <i>\$442.27</i> |
| PWP NBD AHR 17402G | 95604-17402G | \$ 519.00 | 6% | <i>\$491.52</i> |
| PWP NBD AHR 17402T | 95604-17402T | \$ 496.00 | 6% | <i>\$469.74</i> |

| | | | | |
|-----------------------|-----------------|-------------|----|------------|
| PWP NBD AHR 17403 | 95604-17403 | \$ 506.00 | 6% | \$479.21 |
| PWP NBD AHR 17404 | 95604-17404 | \$ 245.00 | 6% | \$232.03 |
| PWP NBD AHR 17405 | 95604-17405 | \$ 303.00 | 6% | \$286.96 |
| PWP NBD AHR 17700 | 95604-17700 | \$ 4,159.00 | 6% | \$3,938.78 |
| PWP NBD AHR 17701 | 95604-17701 | \$ 3,657.00 | 6% | \$3,463.36 |
| PWP NBD AHR 17702 | 95604-17702 | \$ 3,657.00 | 6% | \$3,463.36 |
| PWP NBD AHR 17703 | 95604-17703 | \$ 4,002.00 | 6% | \$3,790.09 |
| PWP NBD AHR 17704 | 95604-17704 | \$ 4,002.00 | 6% | \$3,790.09 |
| PWP NBD AHR 17705 | 95604-17705 | \$ 3,688.00 | 6% | \$3,492.72 |
| PWP NBD AHR 17706 | 95604-17706 | \$ 3,688.00 | 6% | \$3,492.72 |
| PWP NBD AHR 17800 | 95604-17800 | \$ 4,163.00 | 6% | \$3,942.57 |
| PWP NBD AHR 17810 | 95604-17810 | \$ 3,329.00 | 6% | \$3,152.73 |
| PWP NBD AHR 18101 | 95604-18101 | \$ 212.00 | 6% | \$200.77 |
| PWP NBD AHR 18102 | 95604-18102 | \$ 271.00 | 6% | \$256.65 |
| PWP NBD AHR 18103 | 95604-18103 | \$ 297.00 | 6% | \$281.27 |
| PWP NBD AHR 18104 | 95604-18104 | \$ 423.00 | 6% | \$400.60 |
| PWP NBD AHR 18104-6PK | 95604-18104-6PK | \$ 2,465.00 | 6% | \$2,334.48 |
| PWP NBD AHR 18202 | 95604-18202 | \$ 158.00 | 6% | \$149.63 |
| PWP NBD AHR 30135 | 95604-30135 | \$ 433.00 | 6% | \$410.07 |
| PWP NBD AHR 30136 | 95604-30136 | \$ 3,268.00 | 6% | \$3,094.96 |
| PWP NBD AHR 30137 | 95604-30137 | \$ 818.00 | 6% | \$774.69 |
| PWP NBD AHR 30138 | 95604-30138 | \$ 3,775.00 | 6% | \$3,575.11 |
| PWP NBD AHR 30139 | 95604-30139 | \$ 6,901.00 | 6% | \$6,535.59 |
| PWP NBD AHR 30912 | 95604-30912 | \$ 44.00 | 6% | \$41.67 |
| PWP NBD AHR 30913 | 95604-30913 | \$ 44.00 | 6% | \$41.67 |
| PWP NBD AHR 31012 | 95604-31012 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR 31013 | 95604-31013 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR 31014 | 95604-31014 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR 31015 | 95604-31015 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR 31016 | 95604-31016 | \$ 239.00 | 6% | \$226.34 |
| PWP NBD AHR 31017 | 95604-31017 | \$ 239.00 | 6% | \$226.34 |
| PWP NBD AHR 31018 | 95604-31018 | \$ 272.00 | 6% | \$257.60 |
| PWP NBD AHR 31019 | 95604-31019 | \$ 272.00 | 6% | \$257.60 |
| PWP NBD AHR 31025 | 95604-31025 | \$ 46.00 | 6% | \$43.56 |
| PWP NBD AHR 31026 | 95604-31026 | \$ 46.00 | 6% | \$43.56 |
| PWP NBD AHR 31028 | 95604-31028 | \$ 47.00 | 6% | \$44.51 |
| PWP NBD AHR 31029 | 95604-31029 | \$ 58.00 | 6% | \$54.93 |
| PWP NBD AHR 31031 | 95604-31031 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR 31032 | 95604-31032 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR 31034 | 95604-31034 | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR 31035 | 95604-31035 | \$ 70.00 | 6% | \$66.29 |

| | | | | |
|--------------------------|--------------------|-------------|----|-------------------|
| PWP NBD AHR 31050 | 95604-31050 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR 31051 | 95604-31051 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR 31055 | 95604-31055 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR 31056 | 95604-31056 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR 37101 | 95604-37101 | \$ 44.00 | 6% | <i>\$41.67</i> |
| PWP NBD AHR 37102 | 95604-37102 | \$ 44.00 | 6% | <i>\$41.67</i> |
| PWP NBD AHR 37103 | 95604-37103 | \$ 44.00 | 6% | <i>\$41.67</i> |
| PWP NBD AHR 37111 | 95604-37111 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR 37112 | 95604-37112 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR 37113 | 95604-37113 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR 37114 | 95604-37114 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR 37115 | 95604-37115 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR 37116 | 95604-37116 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR 37117 | 95604-37117 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR 37121 | 95604-37121 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 37122 | 95604-37122 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 37123 | 95604-37123 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 37124 | 95604-37124 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 37125 | 95604-37125 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 37126 | 95604-37126 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 37129 | 95604-37129 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 37130 | 95604-37130 | \$ 98.00 | 6% | <i>\$92.81</i> |
| PWP NBD AHR 39031 | 95604-39031 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PWP NBD AHR 39032 | 95604-39032 | \$ 111.00 | 6% | <i>\$105.12</i> |
| PWP NBD AHR 39033 | 95604-39033 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PWP NBD AHR 39034 | 95604-39034 | \$ 84.00 | 6% | <i>\$79.55</i> |
| PWP NBD AHR 39035 | 95604-39035 | \$ 495.00 | 6% | <i>\$468.79</i> |
| PWP NBD AHR 39036 | 95604-39036 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP NBD AHR 39037 | 95604-39037 | \$ 93.00 | 6% | <i>\$88.08</i> |
| PWP NBD AHR 39038 | 95604-39038 | \$ 132.00 | 6% | <i>\$125.01</i> |
| PWP NBD AHR 39039 | 95604-39039 | \$ 132.00 | 6% | <i>\$125.01</i> |
| PWP EXT WARR 39505 | 95604-39505 | \$ 46.00 | 6% | <i>\$43.56</i> |
| PWP NBD AHR 4120-24MW-4Y | 95604-4120-24MW-4Y | \$ 531.00 | 6% | <i>\$502.88</i> |
| PWP NBD AHR 4120-48MW-4Y | 95604-4120-48MW-4Y | \$ 708.00 | 6% | <i>\$670.51</i> |
| PWP NBD AHR 4120C | 95604-4120C | \$ 4,628.00 | 6% | <i>\$4,382.95</i> |
| PWP NBD AHR 4120C-1 | 95604-4120C-1 | \$ 5,225.00 | 6% | <i>\$4,948.34</i> |
| PWP NBD AHR 41216 | 95604-41216 | \$ 1,430.00 | 6% | <i>\$1,354.28</i> |
| PWP NBD AHR 4220-12P-4X | 95604-4220-12P-4X | \$ 162.00 | 6% | <i>\$153.42</i> |

| | | | | |
|---------------------------------|---------------------------|--------------|----|--------------------|
| PWP NBD AHR 4220-12T-4X | 95604-4220-12T-4X | \$ 119.00 | 6% | <i>\$112.70</i> |
| PWP NBD AHR 4220-24P-4X | 95604-4220-24P-4X | \$ 216.00 | 6% | <i>\$204.56</i> |
| PWP NBD AHR 4220-24T-4X | 95604-4220-24T-4X | \$ 167.00 | 6% | <i>\$158.16</i> |
| PWP NBD AHR 4220-48P-4X | 95604-4220-48P-4X | \$ 324.00 | 6% | <i>\$306.84</i> |
| PWP NBD AHR 4220-48T-4X | 95604-4220-48T-4X | \$ 243.00 | 6% | <i>\$230.13</i> |
| PWP NBD AHR 4220-4MW-20P-4X | 95604-4220-4MW-20P-4X | \$ 297.00 | 6% | <i>\$281.27</i> |
| PWP NBD AHR 4220-4MW-8P-4X | 95604-4220-4MW-8P-4X | \$ 210.00 | 6% | <i>\$198.88</i> |
| PWP NBD AHR 4220-8MW-40P-4X | 95604-4220-8MW-40P-4X | \$ 432.00 | 6% | <i>\$409.13</i> |
| PWP NBD AHR 4220-8X | 95604-4220-8X | \$ 227.00 | 6% | <i>\$214.98</i> |
| PWP NBD AHR BD X 48001 | 95604-48001 | \$ 5,936.00 | 6% | <i>\$5,621.69</i> |
| PWP NBD AHR 48038 | 95604-48038 | \$ 2,378.00 | 6% | <i>\$2,252.08</i> |
| PWP NBD AHR 48039 | 95604-48039 | \$ 2,378.00 | 6% | <i>\$2,252.08</i> |
| PWP NBD AHR-48040 | 95604-48040 | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PWP NBD AHR BD X 48041 | 95604-48041 | \$ 2,378.00 | 6% | <i>\$2,252.08</i> |
| PWP NBD AHR BD X 48046 | 95604-48046 | \$ 3,121.00 | 6% | <i>\$2,955.74</i> |
| PWP NBD AHR 48047 | 95604-48047 | \$ 8,320.00 | 6% | <i>\$7,879.46</i> |
| PWP NBD AHR BD X 48051 | 95604-48051 | \$ 5,723.00 | 6% | <i>\$5,419.97</i> |
| PWP NBD AHR 48061 | 95604-48061 | \$ 6,685.00 | 6% | <i>\$6,331.03</i> |
| PWP NBD AHR 48062 | 95604-48062 | \$ 10,696.00 | 6% | <i>\$10,129.65</i> |
| PWP NBD AHR 5320-16P-4XE | 95604-5320-16P-4XE | \$ 228.00 | 6% | <i>\$215.93</i> |
| PWP NBD AHR 5320-16P-4XE-DC | 95604-5320-16P-4XE-DC | \$ 273.00 | 6% | <i>\$258.54</i> |
| PWP NBD AHR 5320-24P-8XE | 95604-5320-24P-8XE | \$ 251.00 | 6% | <i>\$237.71</i> |
| PWP NBD AHR 5320-24T-24S-4XE-XT | 95604-5320-24T-24S-4XE-XT | \$ 344.00 | 6% | <i>\$325.79</i> |
| PWP NBD AHR 5320-24T-4X-XT | 95604-5320-24T-4X-XT | \$ 185.00 | 6% | <i>\$175.20</i> |
| PWP NBD AHR 5320-24T-8XE | 95604-5320-24T-8XE | \$ 178.00 | 6% | <i>\$168.57</i> |

| | | | | |
|--------------------------------|--------------------------|-----------|----|----------|
| PWP NBD AHR 5320-48P-8XE | 95604-5320-48P-8XE | \$ 420.00 | 6% | \$397.76 |
| PWP NBD AHR 5320-48T-8XE | 95604-5320-48T-8XE | \$ 283.00 | 6% | \$268.02 |
| PWP NBD AHR 5420F-16MW-32P-4XE | 95604-5420F-16MW-32P-4XE | \$ 813.00 | 6% | \$769.95 |
| PWP NBD AHR 5420F-16W-32P-4XE | 95604-5420F-16W-32P-4XE | \$ 688.00 | 6% | \$651.57 |
| PWP NBD AHR 5420F-24P-4XE | 95604-5420F-24P-4XE | \$ 343.00 | 6% | \$324.84 |
| PWP NBD AHR 5420F-24S-4XE | 95604-5420F-24S-4XE | \$ 388.00 | 6% | \$367.46 |
| PWP NBD AHR 5420F-24T-4XE | 95604-5420F-24T-4XE | \$ 282.00 | 6% | \$267.07 |
| PWP NBD AHR 5420F-48P-4XE | 95604-5420F-48P-4XE | \$ 534.00 | 6% | \$505.72 |
| PWP NBD AHR 5420F-48P-4XL | 95604-5420F-48P-4XL | \$ 623.00 | 6% | \$590.01 |
| PWP NBD AHR 5420F-48T-4XE | 95604-5420F-48T-4XE | \$ 382.00 | 6% | \$361.77 |
| PWP NBD AHR 5420F-8W-16P-4XE | 95604-5420F-8W-16P-4XE | \$ 404.00 | 6% | \$382.61 |
| PWP NBD AHR 5420M-16MW-32P-4YE | 95604-5420M-16MW-32P-4YE | \$ 881.00 | 6% | \$834.35 |
| PWP NBD AHR 5420M-24T-4YE | 95604-5420M-24T-4YE | \$ 375.00 | 6% | \$355.14 |
| PWP NBD AHR 5420M-24W-4YE | 95604-5420M-24W-4YE | \$ 351.00 | 6% | \$332.41 |
| PWP NBD AHR 5420M-48T-4YE | 95604-5420M-48T-4YE | \$ 512.00 | 6% | \$484.89 |
| PWP NBD AHR 5420M-48W-4YE | 95604-5420M-48W-4YE | \$ 577.00 | 6% | \$546.45 |
| PWP NBD AHR 5520-12MW-36W | 95604-5520-12MW-36W | \$ 802.00 | 6% | \$759.53 |
| PWP NBD AHR 5520-24T | 95604-5520-24T | \$ 332.00 | 6% | \$314.42 |
| PWP NBD AHR 5520-24T-ACDC-BASE | 95604-5520-24T-ACDC-BASE | \$ 332.00 | 6% | \$314.42 |

| | | | | |
|---------------------------------|---------------------------|-------------|----|-------------------|
| PWP NBD AHR 5520-24T-BASE | 95604-5520-24T-BASE | \$ 332.00 | 6% | <i>\$314.42</i> |
| PWP NBD AHR 5520-24W | 95604-5520-24W | \$ 505.00 | 6% | <i>\$478.26</i> |
| PWP NBD AHR 5520-24X | 95604-5520-24X | \$ 955.00 | 6% | <i>\$904.43</i> |
| PWP NBD AHR 5520-24X-ACDC-BASE | 95604-5520-24X-ACDC-BASE | \$ 955.00 | 6% | <i>\$904.43</i> |
| PWP NBD AHR 5520-24X-BASE | 95604-5520-24X-BASE | \$ 955.00 | 6% | <i>\$904.43</i> |
| PWP NBD AHR 5520-48SE | 95604-5520-48SE | \$ 983.00 | 6% | <i>\$930.95</i> |
| PWP NBD AHR 5520-48SE-ACDC-BASE | 95604-5520-48SE-ACDC-BASE | \$ 983.00 | 6% | <i>\$930.95</i> |
| PWP NBD AHR 5520-48SE-BASE | 95604-5520-48SE-BASE | \$ 983.00 | 6% | <i>\$930.95</i> |
| PWP NBD AHR 5520-48T | 95604-5520-48T | \$ 546.00 | 6% | <i>\$517.09</i> |
| PWP NBD AHR 5520-48T-ACDC-BASE | 95604-5520-48T-ACDC-BASE | \$ 546.00 | 6% | <i>\$517.09</i> |
| PWP NBD AHR 5520-48T-BASE | 95604-5520-48T-BASE | \$ 546.00 | 6% | <i>\$517.09</i> |
| PWP NBD AHR 5520-48W | 95604-5520-48W | \$ 655.00 | 6% | <i>\$620.32</i> |
| PWP NBD AHR 5720-24MW | 95604-5720-24MW | \$ 1,003.00 | 6% | <i>\$949.89</i> |
| PWP NBD AHR 5720-24MXW | 95604-5720-24MXW | \$ 1,357.00 | 6% | <i>\$1,285.15</i> |
| PWP NBD AHR 5720-48MW | 95604-5720-48MW | \$ 1,186.00 | 6% | <i>\$1,123.20</i> |
| PWP NBD AHR 5720-48MXW | 95604-5720-48MXW | \$ 1,711.00 | 6% | <i>\$1,620.40</i> |
| PWP NBD AHR 7520-48XT-6C | 95604-7520-48XT-6C | \$ 1,837.00 | 6% | <i>\$1,739.73</i> |
| PWP NBD AHR 7520-48XT-6C-AC-F | 95604-7520-48XT-6C-AC-F | \$ 1,837.00 | 6% | <i>\$1,739.73</i> |
| PWP NBD AHR 7520-48XT-6C-AC-R | 95604-7520-48XT-6C-AC-R | \$ 1,837.00 | 6% | <i>\$1,739.73</i> |

| | | | | |
|--------------------------------|--------------------------|-------------|----|-------------------|
| PWP NBD AHR 7520-48Y-8C | 95604-7520-48Y-8C | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |
| PWP NBD AHR 7520-48Y-8C-AC-F | 95604-7520-48Y-8C-AC-F | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |
| PWP NBD AHR 7520-48Y-8C-AC-R | 95604-7520-48Y-8C-AC-R | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |
| PWP NBD AHR 7520-48YE-8CE | 95604-7520-48YE-8CE | \$ 1,993.00 | 6% | <i>\$1,887.47</i> |
| PWP NBD AHR 7520-48YE-8CE-AC-F | 95604-7520-48YE-8CE-AC-F | \$ 1,993.00 | 6% | <i>\$1,887.47</i> |
| PWP NBD AHR 7520-48YE-8CE-AC-R | 95604-7520-48YE-8CE-AC-R | \$ 1,993.00 | 6% | <i>\$1,887.47</i> |
| PWP NBD AHR 7720-32C | 95604-7720-32C | \$ 2,146.00 | 6% | <i>\$2,032.37</i> |
| PWP NBD AHR 7720-32C-AC-F | 95604-7720-32C-AC-F | \$ 2,146.00 | 6% | <i>\$2,032.37</i> |
| PWP NBD AHR 7720-32C-AC-R | 95604-7720-32C-AC-R | \$ 2,146.00 | 6% | <i>\$2,032.37</i> |
| PWP NBD AHR 8520-48XT-6C | 95604-8520-48XT-6C | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PWP NBD AHR 8520-48XT-6C-AC-F | 95604-8520-48XT-6C-AC-F | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PWP NBD AHR 8520-48XT-6C-AC-R | 95604-8520-48XT-6C-AC-R | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PWP NBD AHR 8520-48XT-6C-DC-F | 95604-8520-48XT-6C-DC-F | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PWP NBD AHR 8520-48XT-6C-DC-R | 95604-8520-48XT-6C-DC-R | \$ 2,124.00 | 6% | <i>\$2,011.53</i> |
| PWP NBD AHR 8520-48Y-8C | 95604-8520-48Y-8C | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PWP NBD AHR 8520-48Y-8C-AC-F | 95604-8520-48Y-8C-AC-F | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PWP NBD AHR 8520-48Y-8C-AC-R | 95604-8520-48Y-8C-AC-R | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PWP NBD AHR 8520-48Y-8C-DC-F | 95604-8520-48Y-8C-DC-F | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |

| | | | | |
|------------------------------|------------------------|--------------|----|--------------------|
| PWP NBD AHR 8520-48Y-8C-DC-R | 95604-8520-48Y-8C-DC-R | \$ 2,158.00 | 6% | <i>\$2,043.73</i> |
| PWP NBD AHR 86100 | 95604-86100 | \$ 4,770.00 | 6% | <i>\$4,517.43</i> |
| PWP NBD AHR 86101 | 95604-86101 | \$ 6,557.00 | 6% | <i>\$6,209.81</i> |
| PWP NBD AHR 87100 | 95604-87100 | \$ 2,960.00 | 6% | <i>\$2,803.27</i> |
| PWP NBD AHR 87101 | 95604-87101 | \$ 4,556.00 | 6% | <i>\$4,314.76</i> |
| PWP NBD AHR 8720-32C | 95604-8720-32C | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PWP NBD AHR 8720-32C-AC-F | 95604-8720-32C-AC-F | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PWP NBD AHR 8720-32C-AC-R | 95604-8720-32C-AC-R | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PWP NBD AHR 8720-32C-DC-F | 95604-8720-32C-DC-F | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PWP NBD AHR 8720-32C-DC-R | 95604-8720-32C-DC-R | \$ 2,487.00 | 6% | <i>\$2,355.31</i> |
| PWP NBD AHR BD 8806 | 95604-8806 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| PWP NBD AHR BD 8810 | 95604-8810 | \$ 3,862.00 | 6% | <i>\$3,657.51</i> |
| PWP NBD AHR 88100 | 95604-88100 | \$ 5,389.00 | 6% | <i>\$5,103.65</i> |
| PWP NBD AHR 8820-40C | 95604-8820-40C | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PWP NBD AHR 8820-40C-AC-F | 95604-8820-40C-AC-F | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PWP NBD AHR 8820-40C-AC-R | 95604-8820-40C-AC-R | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PWP NBD AHR 8820-40C-DC-F | 95604-8820-40C-DC-F | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PWP NBD AHR 8820-40C-DC-R | 95604-8820-40C-DC-R | \$ 9,563.00 | 6% | <i>\$9,056.64</i> |
| PWP NBD AHR 8820-80C | 95604-8820-80C | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PWP NBD AHR 8820-80C-AC-F | 95604-8820-80C-AC-F | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PWP NBD AHR 8820-80C-AC-R | 95604-8820-80C-AC-R | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PWP NBD AHR 8820-80C-DC-F | 95604-8820-80C-DC-F | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PWP NBD AHR 8820-80C-DC-R | 95604-8820-80C-DC-R | \$ 17,237.00 | 6% | <i>\$16,324.30</i> |
| PWP NBD AHR 9920-16C | 95604-9920-16C | \$ 7,541.00 | 6% | <i>\$7,141.70</i> |

| | | | | |
|-------------------------------|-------------------------|--------------|----|-------------|
| PWP NBD AHR 9920-4D | 95604-9920-4D | \$ 7,541.00 | 6% | \$7,141.70 |
| PWP NBD AHR 9920-NPB-8 | 95604-9920-NPB-8 | \$ 13,716.00 | 6% | \$12,989.74 |
| PWP NBD AHR | 95604-A10148 | \$ 2,681.00 | 6% | \$2,539.04 |
| PWP NBD AHR | 95604-A10149 | \$ 5,112.00 | 6% | \$4,841.32 |
| PWP NBD AHR | 95604-A10152 | \$ 5,112.00 | 6% | \$4,841.32 |
| PWP NBD AHR | 95604-A10154 | \$ 15,587.00 | 6% | \$14,761.67 |
| PWP NBD AHR | 95604-A10155 | \$ 5,511.00 | 6% | \$5,219.19 |
| PWP NBD AHR | 95604-A10157 | \$ 9,739.00 | 6% | \$9,223.32 |
| PWP NBD AHR 10175 | 95604-A10175 | \$ 5,459.00 | 6% | \$5,169.95 |
| PWP NBD AHR A10176 | 95604-A10176 | \$ 8,192.00 | 6% | \$7,758.23 |
| PWP NBD AHR AH-AP-1130-AC-CE | 95604-AH-AP-1130-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-1130-AC-FCC | 95604-AH-AP-1130-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-1130-AC-W | 95604-AH-AP-1130-AC-W | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-122-AC-CAN | 95604-AH-AP-122-AC-CAN | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-122-AC-CE | 95604-AH-AP-122-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-122-AC-FCC | 95604-AH-AP-122-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-122-AC-W | 95604-AH-AP-122-AC-W | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-130-AC-CE | 95604-AH-AP-130-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-130-AC-FCC | 95604-AH-AP-130-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-130-AC-W | 95604-AH-AP-130-AC-W | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-150W-AC-CAN | 95604-AH-AP-150W-AC-CAN | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-150W-AC-CE | 95604-AH-AP-150W-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-150W-AC-FCC | 95604-AH-AP-150W-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-150W-AC-W | 95604-AH-AP-150W-AC-W | \$ 60.00 | 6% | \$56.82 |

| | | | | |
|-------------------------------|-------------------------|----------|----|---------|
| PWP NBD AHR AH-AP-230-AC-CE | 95604-AH-AP-230-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-230-AC-FCC | 95604-AH-AP-230-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-230-AC-W | 95604-AH-AP-230-AC-W | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-250-AC-CAN | 95604-AH-AP-250-AC-CAN | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-250-AC-CE | 95604-AH-AP-250-AC-CE | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-250-AC-FCC | 95604-AH-AP-250-AC-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-250-AC-W | 95604-AH-AP-250-AC-W | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-630-AX-CAN | 95604-AH-AP-630-AX-CAN | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-630-AX-CE | 95604-AH-AP-630-AX-CE | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-630-AX-FCC | 95604-AH-AP-630-AX-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-630-AX-W | 95604-AH-AP-630-AX-W | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AH-AP-650-AX-CAN | 95604-AH-AP-650-AX-CAN | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-AP-650-AX-CE | 95604-AH-AP-650-AX-CE | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-AP-650-AX-FCC | 95604-AH-AP-650-AX-FCC | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-AP-650-AX-W | 95604-AH-AP-650-AX-W | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-AP-650X-AX-CAN | 95604-AH-AP-650X-AX-CAN | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-AP-650X-AX-CE | 95604-AH-AP-650X-AX-CE | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-AP-650X-AX-FCC | 95604-AH-AP-650X-AX-FCC | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-AP-650X-AX-W | 95604-AH-AP-650X-AX-W | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR AH-ATOM-CAN | 95604-AH-ATOM-CAN | \$ 60.00 | 6% | \$56.82 |

| | | | | |
|----------------------------|----------------------|----------|----|----------------|
| PWP NBD AHR AH-ATOM-CE-EU | 95604-AH-ATOM-CE-EU | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR AH-ATOM-CE-UK | 95604-AH-ATOM-CE-UK | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR AH-ATOM-FCC | 95604-AH-ATOM-FCC | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-ATOM-W | 95604-AH-ATOM-W | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-ATOM-W-EU | 95604-AH-ATOM-W-EU | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR AH-ATOM-W-UK | 95604-AH-ATOM-W-UK | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR AH-SR-2208P-AU | 95604-AH-SR-2208P-AU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2208P-EU | 95604-AH-SR-2208P-EU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2208P-NA | 95604-AH-SR-2208P-NA | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2208P-UK | 95604-AH-SR-2208P-UK | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2224P-AU | 95604-AH-SR-2224P-AU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2224P-EU | 95604-AH-SR-2224P-EU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2224P-NA | 95604-AH-SR-2224P-NA | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2224P-UK | 95604-AH-SR-2224P-UK | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2324P-AU | 95604-AH-SR-2324P-AU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2324P-EU | 95604-AH-SR-2324P-EU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2324P-NA | 95604-AH-SR-2324P-NA | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2324P-UK | 95604-AH-SR-2324P-UK | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-SR-2348P-AU | 95604-AH-SR-2348P-AU | \$ 55.00 | 6% | <i>\$52.09</i> |
| PWP NBD AHR AH-SR-2348P-EU | 95604-AH-SR-2348P-EU | \$ 55.00 | 6% | <i>\$52.09</i> |

| | | | | |
|-------------------------------|-------------------------|-----------|----|-----------------|
| PWP NBD AHR AH-SR-2348P-NA | 95604-AH-SR-2348P-NA | \$ 55.00 | 6% | <i>\$52.09</i> |
| PWP NBD AHR AH-SR-2348P-UK | 95604-AH-SR-2348P-UK | \$ 55.00 | 6% | <i>\$52.09</i> |
| PWP NBD AHR AH-XR200P-AU | 95604-AH-XR200P-AU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR200P-EU | 95604-AH-XR200P-EU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR200P-UK | 95604-AH-XR200P-UK | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR200P-US | 95604-AH-XR200P-US | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR600P | 95604-AH-XR600P | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR600P-AU | 95604-AH-XR600P-AU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR600P-EU | 95604-AH-XR600P-EU | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR600P-KR | 95604-AH-XR600P-KR | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR600P-UK | 95604-AH-XR600P-UK | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AH-XR600P-US | 95604-AH-XR600P-US | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AP-8533-68SB30-IL | 95604-AP-8533-68SB30-IL | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP NBD AHR AP3000-IL | 95604-AP3000-IL | \$ 40.50 | 6% | <i>\$38.36</i> |
| PWP NBD AHR AP3000-TN | 95604-AP3000-TN | \$ 40.50 | 6% | <i>\$38.36</i> |
| PWP NBD AHR AP3000-WW | 95604-AP3000-WW | \$ 40.50 | 6% | <i>\$38.36</i> |
| PWP NBD AHR AP3000X-WW | 95604-AP3000X-WW | \$ 51.75 | 6% | <i>\$49.01</i> |
| PWP NBD AHR AP302W-CAN | 95604-AP302W-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| PWP NBD AHR AP302W-EG | 95604-AP302W-EG | \$ 49.00 | 6% | <i>\$46.41</i> |
| PWP NBD AHR AP302W-FCC | 95604-AP302W-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |

| | | | | |
|--------------------------|---------------------------|----------|----|---------|
| PWP NBD AHR AP302W-WR | 95604- AP302W-WR | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR AP305C-1-CAN | 95604-AP305C- 1-CAN | \$ 59.00 | 6% | \$55.88 |
| PWP NBD AHR AP305C-1-EG | 95604-AP305C- 1-EG | \$ 59.00 | 6% | \$55.88 |
| PWP NBD AHR AP305C-1-FCC | 95604-AP305C- 1-FCC | \$ 59.00 | 6% | \$55.88 |
| PWP NBD AHR AP305C-1-IL | 95604-AP305C- 1-IL | \$ 59.00 | 6% | \$55.88 |
| PWP NBD AHR AP305C-1-WR | 95604-AP305C- 1-WR | \$ 59.00 | 6% | \$55.88 |
| PWP NBD AHR AP305C-CAN | 95604-AP305C- CAN | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305C-EG | 95604-AP305C- EG | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305C-FCC | 95604-AP305C- FCC | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305C-IL | 95604-AP305C- IL | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305C-WR | 95604-AP305C- WR | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305CX-CAN | 95604- AP305CX- CAN | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305CX-FCC | 95604- AP305CX- FCC | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305CX-IL | 95604- AP305CX-IL | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP305CX-WR | 95604- AP305CX-WR | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR AP310e-1-WR | 95604-AP310e- 1-WR | \$ 38.00 | 6% | \$35.99 |
| PWP NBD AHR AP310e-CAN | 95604-AP310e- CAN | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR AP310e-FCC | 95604-AP310e- FCC | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR AP310e-IL | 95604-AP310e- IL | \$ 40.00 | 6% | \$37.88 |

| | | | | |
|--------------------------|--------------------|----------|----|---------|
| PWP NBD AHR AP310e-WR | 95604-AP310e-WR | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR AP310i-1-WR | 95604-AP310i-1-WR | \$ 38.00 | 6% | \$35.99 |
| PWP NBD AHR AP310i-CAN | 95604-AP310i-CAN | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR AP310i-FCC | 95604-AP310i-FCC | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR AP310i-IL | 95604-AP310i-IL | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR AP310i-WR | 95604-AP310i-WR | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR AP360e-CAN | 95604-AP360e-CAN | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR AP360e-FCC | 95604-AP360e-FCC | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR AP360e-IL | 95604-AP360e-IL | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR AP360e-WR | 95604-AP360e-WR | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR AP360i-CAN | 95604-AP360i-CAN | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR AP360i-FCC | 95604-AP360i-FCC | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR AP360i-WR | 95604-AP360i-WR | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR AP4000-WW | 95604-AP4000-1-WW | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP4000-IL | 95604-AP4000-IL | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP4000-WW | 95604-AP4000-WW | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP410C-1-CAN | 95604-AP410C-1-CAN | \$ 56.00 | 6% | \$53.03 |
| PWP NBD AHR AP410C-1-EG | 95604-AP410C-1-EG | \$ 56.00 | 6% | \$53.03 |
| PWP NBD AHR AP410C-1-FCC | 95604-AP410C-1-FCC | \$ 56.00 | 6% | \$53.03 |
| PWP NBD AHR AP410C-1-IL | 95604-AP410C-1-IL | \$ 56.00 | 6% | \$53.03 |

| | | | | |
|--------------------------|--------------------|----------|----|---------|
| PWP NBD AHR AP410C-1-WR | 95604-AP410C-1-WR | \$ 56.00 | 6% | \$53.03 |
| PWP NBD AHR AP410C-CAN | 95604-AP410C-CAN | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP410C-EG | 95604-AP410C-EG | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP410C-FCC | 95604-AP410C-FCC | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP410C-IL | 95604-AP410C-IL | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP410C-WR | 95604-AP410C-WR | \$ 60.00 | 6% | \$56.82 |
| PWP NBD AHR AP410e-CAN | 95604-AP410e-CAN | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR AP410e-FCC | 95604-AP410e-FCC | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR AP410e-WR | 95604-AP410e-WR | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR AP410i-1-FCC | 95604-AP410i-1-FCC | \$ 67.00 | 6% | \$63.45 |
| PWP NBD AHR AP410i-1-WR | 95604-AP410i-1-WR | \$ 67.00 | 6% | \$63.45 |
| PWP NBD AHR AP410i-CAN | 95604-AP410i-CAN | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR AP410i-FCC | 95604-AP410i-FCC | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR AP410i-IL | 95604-AP410i-IL | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR AP410i-WR | 95604-AP410i-WR | \$ 70.00 | 6% | \$66.29 |
| PWP NBD AHR AP460C-CAN | 95604-AP460C-CAN | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR AP460C-EG | 95604-AP460C-EG | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR AP460C-FCC | 95604-AP460C-FCC | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR AP460C-IL | 95604-AP460C-IL | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR AP460C-WR | 95604-AP460C-WR | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR AP460e-CAN | 95604-AP460e-CAN | \$ 82.00 | 6% | \$77.66 |

| | | | | |
|---------------------------|---------------------|-----------|----|-----------------|
| PWP NBD AHR AP460e-FCC | 95604-AP460e-FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| PWP NBD AHR AP460e-WR | 95604-AP460e-WR | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR AP460i-CAN | 95604-AP460i-CAN | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR AP460i-FCC | 95604-AP460i-FCC | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR AP460i-IL | 95604-AP460i-IL | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR AP460i-WR | 95604-AP460i-WR | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR AP460S12C-CAN | 95604-AP460S12C-CAN | \$ 62.00 | 6% | <i>\$58.72</i> |
| PWP NBD AHR AP460S12C-FCC | 95604-AP460S12C-FCC | \$ 62.00 | 6% | <i>\$58.72</i> |
| PWP NBD AHR AP460S12C-WR | 95604-AP460S12C-WR | \$ 62.00 | 6% | <i>\$58.72</i> |
| PWP NBD AHR AP460S6C-CAN | 95604-AP460S6C-CAN | \$ 62.00 | 6% | <i>\$58.72</i> |
| PWP NBD AHR AP460S6C-FCC | 95604-AP460S6C-FCC | \$ 62.00 | 6% | <i>\$58.72</i> |
| PWP NBD AHR AP460S6C-WR | 95604-AP460S6C-WR | \$ 62.00 | 6% | <i>\$58.72</i> |
| PWP NBD AHR AP5010-IL | 95604-AP5010-IL | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR AP5010-WW | 95604-AP5010-WW | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR AP5020-WW | 95604-AP5020-WW | \$ 107.96 | 6% | <i>\$102.24</i> |
| PWP NBD AHR AP5050D-WW | 95604-AP5050D-WW | \$ 245.00 | 6% | <i>\$232.03</i> |
| PWP NBD AHR AP5050U-WW | 95604-AP5050U-WW | \$ 191.00 | 6% | <i>\$180.89</i> |
| PWP NBD AHR AP505i-FCC | 95604-AP505i-FCC | \$ 86.00 | 6% | <i>\$81.45</i> |

| | | | | |
|----------------------------|----------------------|-----------|----|-----------------|
| PWP NBD AHR AP505i-FCC-TAA | 95604-AP505i-FCC-TAA | \$ 86.00 | 6% | <i>\$81.45</i> |
| PWP NBD AHR AP505i-WR | 95604-AP505i-WR | \$ 90.00 | 6% | <i>\$85.23</i> |
| PWP NBD AHR AP510C-CAN | 95604-AP510C-CAN | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510C-CE | 95604-AP510C-CE | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510C-FCC | 95604-AP510C-FCC | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510C-W | 95604-AP510C-W | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510C-WW | 95604-AP510C-WW | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AP510CX-CAN | 95604-AP510CX-CAN | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510CX-CE | 95604-AP510CX-CE | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510CX-FCC | 95604-AP510CX-FCC | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510CX-W | 95604-AP510CX-W | \$ 52.00 | 6% | <i>\$49.25</i> |
| PWP NBD AHR AP510CX-WW | 95604-AP510CX-WW | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR AP510e-FCC | 95604-AP510e-FCC | \$ 113.00 | 6% | <i>\$107.02</i> |
| PWP NBD AHR AP510e-FCC-TAA | 95604-AP510e-FCC-TAA | \$ 113.00 | 6% | <i>\$107.02</i> |
| PWP NBD AHR AP510e-WR | 95604-AP510e-WR | \$ 108.00 | 6% | <i>\$102.28</i> |
| PWP NBD AHR AP510i-1-FCC | 95604-AP510i-1-FCC | \$ 95.00 | 6% | <i>\$89.97</i> |
| PWP NBD AHR AP510i-1-WR | 95604-AP510i-1-WR | \$ 95.00 | 6% | <i>\$89.97</i> |
| PWP NBD AHR AP510i-FCC | 95604-AP510i-FCC | \$ 100.00 | 6% | <i>\$94.71</i> |
| PWP NBD AHR AP510i-FCC-TAA | 95604-AP510i-FCC-TAA | \$ 100.00 | 6% | <i>\$94.71</i> |

| | | | | |
|------------------------|------------------|-------------|----|-------------------|
| PWP NBD AHR AP510i-WR | 95604-AP510i-WR | \$ 100.00 | 6% | <i>\$94.71</i> |
| PWP NBD AHR AP560h-FCC | 95604-AP560h-FCC | \$ 250.00 | 6% | <i>\$236.76</i> |
| PWP NBD AHR AP560h-WR | 95604-AP560h-WR | \$ 250.00 | 6% | <i>\$236.76</i> |
| PWP NBD AHR AP560i-FCC | 95604-AP560i-FCC | \$ 182.00 | 6% | <i>\$172.36</i> |
| PWP NBD AHR AP560i-WR | 95604-AP560i-WR | \$ 173.00 | 6% | <i>\$163.84</i> |
| PWP NBD AHR AP560m-FCC | 95604-AP560m-FCC | \$ 182.00 | 6% | <i>\$172.36</i> |
| PWP NBD AHR AP560t-FCC | 95604-AP560t-FCC | \$ 250.00 | 6% | <i>\$236.76</i> |
| PWP NBD AHR AP560u-FCC | 95604-AP560u-FCC | \$ 169.00 | 6% | <i>\$160.05</i> |
| PWP NBD AHR E2122 | 95604-E2122 | \$ 4,219.00 | 6% | <i>\$3,995.60</i> |
| PWP NBD AHR E2122-1 | 95604-E2122-1 | \$ 3,999.00 | 6% | <i>\$3,787.25</i> |
| PWP NBD AHR E3120-1 | 95604-E3120-1 | \$ 6,541.00 | 6% | <i>\$6,194.65</i> |
| PWP NBD AHR E3125 | 95604-E3125 | \$ 7,060.00 | 6% | <i>\$6,686.17</i> |
| PWP NBD AHR | 95604-H30003 | \$ 36.00 | 6% | <i>\$34.09</i> |
| PWP NBD AHR | 95604-H30004 | \$ 50.00 | 6% | <i>\$47.35</i> |
| PWP NBD AHR | 95604-H30005 | \$ 44.00 | 6% | <i>\$41.67</i> |
| PWP NBD AHR | 95604-H30006 | \$ 86.00 | 6% | <i>\$81.45</i> |
| PWP NBD AHR | 95604-H30007 | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR | 95604-H30008 | \$ 152.00 | 6% | <i>\$143.95</i> |
| PWP NBD AHR | 95604-H30009 | \$ 36.00 | 6% | <i>\$34.09</i> |
| PWP NBD AHR | 95604-H30010 | \$ 73.00 | 6% | <i>\$69.13</i> |
| PWP NBD AHR | 95604-H30011 | \$ 58.00 | 6% | <i>\$54.93</i> |
| PWP NBD AHR | 95604-H30012 | \$ 100.00 | 6% | <i>\$94.71</i> |
| PWP NBD AHR | 95604-H30078 | \$ 1,709.00 | 6% | <i>\$1,618.51</i> |
| PWP NBD AHR | 95604-H30104 | \$ 1,578.00 | 6% | <i>\$1,494.44</i> |
| PWP NBD AHR | 95604-H30105 | \$ 1,559.00 | 6% | <i>\$1,476.45</i> |
| PWP NBD AHR | 95604-H30131 | \$ 893.00 | 6% | <i>\$845.72</i> |
| PWP NBD AHR | 95604-H30132 | \$ 875.00 | 6% | <i>\$828.67</i> |
| PWP NBD AHR | 95604-H30133 | \$ 2,310.00 | 6% | <i>\$2,187.69</i> |
| PWP NBD AHR | 95604-H30134 | \$ 2,921.00 | 6% | <i>\$2,766.33</i> |
| PWP NBD AHR | 95604-H30135 | \$ 2,355.00 | 6% | <i>\$2,230.30</i> |
| PWP NBD AHR | 95604-H30136 | \$ 2,921.00 | 6% | <i>\$2,766.33</i> |
| PWP NBD AHR | 95604-H30184 | \$ 42.00 | 6% | <i>\$39.78</i> |
| PWP NBD AHR | 95604-H30185 | \$ 207.00 | 6% | <i>\$196.04</i> |
| PWP NBD AHR | 95604-H30186 | \$ 108.00 | 6% | <i>\$102.28</i> |

| | | | | |
|-------------|--------------|-------------|----|-------------------|
| PWP NBD AHR | 95604-H30187 | \$ 47.00 | 6% | <i>\$44.51</i> |
| PWP NBD AHR | 95604-H30188 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PWP NBD AHR | 95604-H30189 | \$ 108.00 | 6% | <i>\$102.28</i> |
| PWP NBD AHR | 95604-H30190 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30214 | \$ 116.00 | 6% | <i>\$109.86</i> |
| PWP NBD AHR | 95604-H30215 | \$ 116.00 | 6% | <i>\$109.86</i> |
| PWP NBD AHR | 95604-H30216 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30217 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30218 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30219 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30220 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30221 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30222 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30223 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30224 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30225 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30226 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30227 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30228 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30229 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30267 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30268 | \$ 221.00 | 6% | <i>\$209.30</i> |
| PWP NBD AHR | 95604-H30269 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30270 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30271 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30272 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30273 | \$ 486.00 | 6% | <i>\$460.27</i> |
| PWP NBD AHR | 95604-H30274 | \$ 486.00 | 6% | <i>\$460.27</i> |
| PWP NBD AHR | 95604-H30275 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30276 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30277 | \$ 486.00 | 6% | <i>\$460.27</i> |
| PWP NBD AHR | 95604-H30278 | \$ 529.00 | 6% | <i>\$500.99</i> |
| PWP NBD AHR | 95604-H30279 | \$ 486.00 | 6% | <i>\$460.27</i> |
| PWP NBD AHR | 95604-H30280 | \$ 486.00 | 6% | <i>\$460.27</i> |
| PWP NBD AHR | 95604-H30281 | \$ 564.00 | 6% | <i>\$534.14</i> |
| PWP NBD AHR | 95604-H30282 | \$ 486.00 | 6% | <i>\$460.27</i> |
| PWP NBD AHR | 95604-H30283 | \$ 321.00 | 6% | <i>\$304.00</i> |
| PWP NBD AHR | 95604-H30284 | \$ 353.00 | 6% | <i>\$334.31</i> |
| PWP NBD AHR | 95604-H30293 | \$ 1,925.00 | 6% | <i>\$1,823.07</i> |
| PWP NBD AHR | 95604-H30296 | \$ 116.00 | 6% | <i>\$109.86</i> |
| PWP NBD AHR | 95604-H30297 | \$ 106.00 | 6% | <i>\$100.39</i> |
| PWP NBD AHR | 95604-H30298 | \$ 116.00 | 6% | <i>\$109.86</i> |

| | | | | |
|-------------|--------------|-------------|----|------------|
| PWP NBD AHR | 95604-H30299 | \$ 106.00 | 6% | \$100.39 |
| PWP NBD AHR | 95604-H30380 | \$ 3,136.00 | 6% | \$2,969.95 |
| PWP NBD AHR | 95604-H30381 | \$ 316.00 | 6% | \$299.27 |
| PWP NBD AHR | 95604-H30383 | \$ 4,460.00 | 6% | \$4,223.84 |
| PWP NBD AHR | 95604-H30384 | \$ 257.00 | 6% | \$243.39 |
| PWP NBD AHR | 95604-H30391 | \$ 605.00 | 6% | \$572.97 |
| PWP NBD AHR | 95604-H30392 | \$ 605.00 | 6% | \$572.97 |
| PWP NBD AHR | 95604-H30393 | \$ 271.00 | 6% | \$256.65 |
| PWP NBD AHR | 95604-H30394 | \$ 1,164.00 | 6% | \$1,102.37 |
| PWP NBD AHR | 95604-H30395 | \$ 1,391.00 | 6% | \$1,317.35 |
| PWP NBD AHR | 95604-H30396 | \$ 1,268.00 | 6% | \$1,200.86 |
| PWP NBD AHR | 95604-H30397 | \$ 1,510.00 | 6% | \$1,430.05 |
| PWP NBD AHR | 95604-H30398 | \$ 277.00 | 6% | \$262.33 |
| PWP NBD AHR | 95604-H30400 | \$ 155.00 | 6% | \$146.79 |
| PWP NBD AHR | 95604-H30401 | \$ 216.00 | 6% | \$204.56 |
| PWP NBD AHR | 95604-H30402 | \$ 232.00 | 6% | \$219.72 |
| PWP NBD AHR | 95604-H30403 | \$ 341.00 | 6% | \$322.94 |
| PWP NBD AHR | 95604-H30434 | \$ 93.00 | 6% | \$88.08 |
| PWP NBD AHR | 95604-H30480 | \$ 399.00 | 6% | \$377.87 |
| PWP NBD AHR | 95604-H30495 | \$ 893.00 | 6% | \$845.72 |
| PWP NBD AHR | 95604-H30496 | \$ 875.00 | 6% | \$828.67 |
| PWP NBD AHR | 95604-H30497 | \$ 1,293.00 | 6% | \$1,224.54 |
| PWP NBD AHR | 95604-H30498 | \$ 1,268.00 | 6% | \$1,200.86 |
| PWP NBD AHR | 95604-H30499 | \$ 435.00 | 6% | \$411.97 |
| PWP NBD AHR | 95604-H30501 | \$ 1,268.00 | 6% | \$1,200.86 |
| PWP NBD AHR | 95604-H30502 | \$ 1,949.00 | 6% | \$1,845.80 |
| PWP NBD AHR | 95604-H30503 | \$ 435.00 | 6% | \$411.97 |
| PWP NBD AHR | 95604-H30505 | \$ 2,310.00 | 6% | \$2,187.69 |
| PWP NBD AHR | 95604-H30506 | \$ 3,140.00 | 6% | \$2,973.74 |
| PWP NBD AHR | 95604-H30509 | \$ 1,949.00 | 6% | \$1,845.80 |
| PWP NBD AHR | 95604-H30510 | \$ 2,310.00 | 6% | \$2,187.69 |
| PWP NBD AHR | 95604-H30511 | \$ 3,140.00 | 6% | \$2,973.74 |
| PWP NBD AHR | 95604-H30512 | \$ 435.00 | 6% | \$411.97 |
| PWP NBD AHR | 95604-H30513 | \$ 729.00 | 6% | \$690.40 |
| PWP NBD AHR | 95604-H30524 | \$ 4,308.00 | 6% | \$4,079.89 |
| PWP NBD AHR | 95604-H30525 | \$ 3,140.00 | 6% | \$2,973.74 |
| PWP NBD AHR | 95604-H30526 | \$ 2,310.00 | 6% | \$2,187.69 |
| PWP NBD AHR | 95604-H30528 | \$ 3,636.00 | 6% | \$3,443.47 |
| PWP NBD AHR | 95604-H30531 | \$ 5,180.00 | 6% | \$4,905.72 |
| PWP NBD AHR | 95604-H30532 | \$ 5,180.00 | 6% | \$4,905.72 |
| PWP NBD AHR | 95604-H30534 | \$ 5,279.00 | 6% | \$4,999.48 |
| PWP NBD AHR | 95604-H30535 | \$ 5,643.00 | 6% | \$5,344.20 |

| | | | | |
|-----------------------------|--------------|-------------|----|------------|
| PWP NBD AHR | 95604-H30536 | \$ 5,180.00 | 6% | \$4,905.72 |
| PWP NBD AHR | 95604-H30537 | \$ 5,643.00 | 6% | \$5,344.20 |
| PWP NBD AHR | 95604-H30538 | \$ 3,140.00 | 6% | \$2,973.74 |
| PWP NBD AHR | 95604-H30539 | \$ 5,911.00 | 6% | \$5,598.01 |
| PWP NBD AHR | 95604-H30540 | \$ 6,232.00 | 6% | \$5,902.02 |
| PWP NBD AHR | 95604-H30542 | \$ 504.00 | 6% | \$477.31 |
| PWP NBD AHR | 95604-H30543 | \$ 425.00 | 6% | \$402.50 |
| PWP NBD AHR | 95604-H30544 | \$ 754.00 | 6% | \$714.08 |
| PWP NBD AHR | 95604-H30548 | \$ 425.00 | 6% | \$402.50 |
| PWP NBD AHR | 95604-H30549 | \$ 715.00 | 6% | \$677.14 |
| PWP NBD AHR | 95604-H30550 | \$ 715.00 | 6% | \$677.14 |
| PWP NBD AHR | 95604-H30552 | \$ 425.00 | 6% | \$402.50 |
| PWP NBD AHR | 95604-H30553 | \$ 677.00 | 6% | \$641.15 |
| PWP NBD AHR | 95604-H30567 | \$ 2,614.00 | 6% | \$2,475.59 |
| PWP NBD AHR | 95604-H30569 | \$ 2,310.00 | 6% | \$2,187.69 |
| PWP NBD AHR | 95604-H30570 | \$ 2,769.00 | 6% | \$2,622.38 |
| PWP NBD AHR | 95604-H30571 | \$ 2,769.00 | 6% | \$2,622.38 |
| PWP NBD AHR | 95604-H30573 | \$ 2,310.00 | 6% | \$2,187.69 |
| PWP NBD AHR | 95604-H30574 | \$ 2,553.00 | 6% | \$2,417.82 |
| PWP NBD AHR | 95604-H30575 | \$ 1,590.00 | 6% | \$1,505.81 |
| PWP NBD AHR | 95604-H30576 | \$ 2,310.00 | 6% | \$2,187.69 |
| PWP NBD AHR | 95604-H30577 | \$ 2,769.00 | 6% | \$2,622.38 |
| PWP NBD AHR | 95604-H30578 | \$ 2,769.00 | 6% | \$2,622.38 |
| PWP NBD AHR | 95604-H30586 | \$ 4,308.00 | 6% | \$4,079.89 |
| PWP NBD AHR | 95604-H30587 | \$ 2,355.00 | 6% | \$2,230.30 |
| PWP NBD AHR | 95604-H30588 | \$ 1,620.00 | 6% | \$1,534.22 |
| PWP NBD AHR | 95604-H30589 | \$ 2,517.00 | 6% | \$2,383.72 |
| PWP NBD AHR | 95604-H30632 | \$ 65.00 | 6% | \$61.56 |
| PWP NBD AHR | 95604-H30633 | \$ 65.00 | 6% | \$61.56 |
| PWP NBD AHR | 95604-H30643 | \$ 3,959.00 | 6% | \$3,749.37 |
| PWP NBD AHR | 95604-H30706 | \$ 3,779.00 | 6% | \$3,578.90 |
| PWP NBD AHR | 95604-H30707 | \$ 2,310.00 | 6% | \$2,187.69 |
| PWP NBD AHR | 95604-H30724 | \$ 257.00 | 6% | \$243.39 |
| PWP NBD AHR | 95604-H30725 | \$ 875.00 | 6% | \$828.67 |
| PWP NBD AHR | 95604-H30726 | \$ 5,753.00 | 6% | \$5,448.38 |
| PWP NBD AHR | 95604-H30727 | \$ 6,113.00 | 6% | \$5,789.32 |
| PWP NBD AHR | 95604-H30730 | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR | 95604-H30731 | \$ 50.00 | 6% | \$47.35 |
| PWP NBD AHR 30732 | 95604-H30732 | \$ 1,527.00 | 6% | \$1,446.15 |
| PWP NBD AHR SKL8008-0810-F8 | 95604-H30733 | \$ 6,381.00 | 6% | \$6,043.13 |

| | | | | |
|--------------------------|--------------|-------------|----|-------------------|
| PWP NBD AHR STL2006-0850 | 95604-H30734 | \$ 4,870.00 | 6% | <i>\$4,612.13</i> |
| PWP NBD AHR SGL2001-0850 | 95604-H30735 | \$ 5,392.00 | 6% | <i>\$5,106.49</i> |
| PWP NBD AHR SOK2209-0204 | 95604-H30736 | \$ 863.00 | 6% | <i>\$817.30</i> |
| PWP NBD AHR H30738 | 95604-H30738 | \$ 37.00 | 6% | <i>\$35.04</i> |
| PWP NBD AHR -H30739 | 95604-H30739 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR -H30740 | 95604-H30740 | \$ 464.00 | 6% | <i>\$439.43</i> |
| PWP NBD AHR -H30741 | 95604-H30741 | \$ 855.00 | 6% | <i>\$809.73</i> |
| PWP NBD AHR -H30742 | 95604-H30742 | \$ 756.00 | 6% | <i>\$715.97</i> |
| PWP NBD AHR -H30743 | 95604-H30743 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR -H30744 | 95604-H30744 | \$ 464.00 | 6% | <i>\$439.43</i> |
| PWP NBD AHR -H30745 | 95604-H30745 | \$ 473.00 | 6% | <i>\$447.95</i> |
| PWP NBD AHR -H30746 | 95604-H30746 | \$ 965.00 | 6% | <i>\$913.90</i> |
| PWP NBD AHR -H30747 | 95604-H30747 | \$ 1,673.00 | 6% | <i>\$1,584.41</i> |
| PWP NBD AHR -H30748 | 95604-H30748 | \$ 2,473.00 | 6% | <i>\$2,342.05</i> |
| PWP NBD AHR -H30749 | 95604-H30749 | \$ 5,550.00 | 6% | <i>\$5,256.13</i> |
| PWP NBD AHR -H30750 | 95604-H30750 | \$ 5,550.00 | 6% | <i>\$5,256.13</i> |
| PWP NBD AHR -H30751 | 95604-H30751 | \$ 3,302.00 | 6% | <i>\$3,127.16</i> |
| PWP NBD AHR -H30754 | 95604-H30754 | \$ 5,550.00 | 6% | <i>\$5,256.13</i> |
| PWP NBD AHR -H30755 | 95604-H30755 | \$ 6,041.00 | 6% | <i>\$5,721.13</i> |
| PWP NBD AHR -H30756 | 95604-H30756 | \$ 5,550.00 | 6% | <i>\$5,256.13</i> |
| PWP NBD AHR -H30757 | 95604-H30757 | \$ 2,473.00 | 6% | <i>\$2,342.05</i> |
| PWP NBD AHR -H30758 | 95604-H30758 | \$ 5,214.00 | 6% | <i>\$4,937.92</i> |
| PWP NBD AHR -H30759 | 95604-H30759 | \$ 5,661.00 | 6% | <i>\$5,361.25</i> |
| PWP NBD AHR -H30760 | 95604-H30760 | \$ 6,704.00 | 6% | <i>\$6,349.02</i> |
| PWP NBD AHR -H30761 | 95604-H30761 | \$ 2,473.00 | 6% | <i>\$2,342.05</i> |
| PWP NBD AHR -H30762 | 95604-H30762 | \$ 6,041.00 | 6% | <i>\$5,721.13</i> |
| PWP NBD AHR -H30763 | 95604-H30763 | \$ 6,041.00 | 6% | <i>\$5,721.13</i> |
| PWP NBD AHR -H30764 | 95604-H30764 | \$ 3,816.00 | 6% | <i>\$3,613.94</i> |
| PWP NBD AHR -H30765 | 95604-H30765 | \$ 3,364.00 | 6% | <i>\$3,185.88</i> |
| PWP NBD AHR -H30766 | 95604-H30766 | \$ 6,538.00 | 6% | <i>\$6,191.81</i> |
| PWP NBD AHR -H30767 | 95604-H30767 | \$ 3,816.00 | 6% | <i>\$3,613.94</i> |
| PWP NBD AHR H30769 | 95604-H30769 | \$ 1,970.00 | 6% | <i>\$1,865.69</i> |
| PWP NBD AHR H30773 | 95604-H30773 | \$ 122.00 | 6% | <i>\$115.54</i> |
| PWP NBD AHR H30774 | 95604-H30774 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PWP NBD AHR H30775 | 95604-H30775 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PWP NBD AHR H30776 | 95604-H30776 | \$ 122.00 | 6% | <i>\$115.54</i> |
| PWP NBD AHR H30777 | 95604-H30777 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PWP NBD AHR H30778 | 95604-H30778 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PWP NBD AHR H30779 | 95604-H30779 | \$ 71.00 | 6% | <i>\$67.24</i> |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H30780 | 95604-H30780 | \$ 72.00 | 6% | \$68.19 |
| PWP NBD AHR H30781 | 95604-H30781 | \$ 72.00 | 6% | \$68.19 |
| PWP NBD AHR H30782 | 95604-H30782 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30783 | 95604-H30783 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR H30784 | 95604-H30784 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR H30785 | 95604-H30785 | \$ 71.00 | 6% | \$67.24 |
| PWP NBD AHR H30786 | 95604-H30786 | \$ 72.00 | 6% | \$68.19 |
| PWP NBD AHR H30787 | 95604-H30787 | \$ 71.00 | 6% | \$67.24 |
| PWP NBD AHR H30788 | 95604-H30788 | \$ 72.00 | 6% | \$68.19 |
| PWP NBD AHR H30789 | 95604-H30789 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR H30790 | 95604-H30790 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30791 | 95604-H30791 | \$ 62.00 | 6% | \$58.72 |
| PWP NBD AHR H30793 | 95604-H30793 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30794 | 95604-H30794 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30795 | 95604-H30795 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30796 | 95604-H30796 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30797 | 95604-H30797 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30798 | 95604-H30798 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30799 | 95604-H30799 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30800 | 95604-H30800 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30801 | 95604-H30801 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30802 | 95604-H30802 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30803 | 95604-H30803 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30804 | 95604-H30804 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30805 | 95604-H30805 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30806 | 95604-H30806 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30807 | 95604-H30807 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30808 | 95604-H30808 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30809 | 95604-H30809 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30810 | 95604-H30810 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30811 | 95604-H30811 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30812 | 95604-H30812 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30813 | 95604-H30813 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30814 | 95604-H30814 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30815 | 95604-H30815 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30816 | 95604-H30816 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30817 | 95604-H30817 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30818 | 95604-H30818 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30819 | 95604-H30819 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30820 | 95604-H30820 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30821 | 95604-H30821 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30822 | 95604-H30822 | \$ 52.00 | 6% | \$49.25 |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PWP NBD AHR H30823 | 95604-H30823 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30824 | 95604-H30824 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30825 | 95604-H30825 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30826 | 95604-H30826 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30827 | 95604-H30827 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30828 | 95604-H30828 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30829 | 95604-H30829 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H30830 | 95604-H30830 | \$ 86.00 | 6% | \$81.45 |
| PWP NBD AHR H30831 | 95604-H30831 | \$ 52.00 | 6% | \$49.25 |
| PWP NBD AHR H30832 | 95604-H30832 | \$ 1,093.00 | 6% | \$1,035.13 |
| PWP NBD AHR H30833 | 95604-H30833 | \$ 290.00 | 6% | \$274.64 |
| PWP NBD AHR H30834 | 95604-H30834 | \$ 290.00 | 6% | \$274.64 |
| PWP NBD AHR H30836 | 95604-H30836 | \$ 1,093.00 | 6% | \$1,035.13 |
| PWP NBD AHR H30838 | 95604-H30838 | \$ 41.00 | 6% | \$38.83 |
| PWP NBD AHR H30839 | 95604-H30839 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30840 | 95604-H30840 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30841 | 95604-H30841 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30842 | 95604-H30842 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30843 | 95604-H30843 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30844 | 95604-H30844 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30845 | 95604-H30845 | \$ 55.00 | 6% | \$52.09 |
| PWP NBD AHR H30846 | 95604-H30846 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30847 | 95604-H30847 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30848 | 95604-H30848 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30849 | 95604-H30849 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30850 | 95604-H30850 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30851 | 95604-H30851 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30852 | 95604-H30852 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30853 | 95604-H30853 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30854 | 95604-H30854 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30855 | 95604-H30855 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30856 | 95604-H30856 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30857 | 95604-H30857 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30858 | 95604-H30858 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30859 | 95604-H30859 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30860 | 95604-H30860 | \$ 105.00 | 6% | \$99.44 |
| PWP NBD AHR H30866 | 95604-H30866 | \$ 118.00 | 6% | \$111.75 |
| PWP NBD AHR H30867 | 95604-H30867 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30868 | 95604-H30868 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30869 | 95604-H30869 | \$ 207.00 | 6% | \$196.04 |
| PWP NBD AHR H30870 | 95604-H30870 | \$ 207.00 | 6% | \$196.04 |
| PWP NBD AHR H30871 | 95604-H30871 | \$ 190.00 | 6% | \$179.94 |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PWP NBD AHR H30872 | 95604-H30872 | \$ 108.00 | 6% | \$102.28 |
| PWP NBD AHR H30873 | 95604-H30873 | \$ 108.00 | 6% | \$102.28 |
| PWP NBD AHR H30874 | 95604-H30874 | \$ 108.00 | 6% | \$102.28 |
| PWP NBD AHR H30875 | 95604-H30875 | \$ 39.00 | 6% | \$36.93 |
| PWP NBD AHR H30876 | 95604-H30876 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H30877 | 95604-H30877 | \$ 39.00 | 6% | \$36.93 |
| PWP NBD AHR H30878 | 95604-H30878 | \$ 39.00 | 6% | \$36.93 |
| PWP NBD AHR H30891 | 95604-H30891 | \$ 76.00 | 6% | \$71.98 |
| PWP NBD AHR H30892 | 95604-H30892 | \$ 76.00 | 6% | \$71.98 |
| PWP NBD AHR H30893 | 95604-H30893 | \$ 65.00 | 6% | \$61.56 |
| PWP NBD AHR H30894 | 95604-H30894 | \$ 39.00 | 6% | \$36.93 |
| PWP NBD AHR H30895 | 95604-H30895 | \$ 131.00 | 6% | \$124.06 |
| PWP NBD AHR H30896 | 95604-H30896 | \$ 309.00 | 6% | \$292.64 |
| PWP NBD AHR H30897 | 95604-H30897 | \$ 543.00 | 6% | \$514.25 |
| PWP NBD AHR H30898 | 95604-H30898 | \$ 608.00 | 6% | \$575.81 |
| PWP NBD AHR H30900 | 95604-H30900 | \$ 1,839.00 | 6% | \$1,741.62 |
| PWP NBD AHR H30901 | 95604-H30901 | \$ 2,448.00 | 6% | \$2,318.38 |
| PWP NBD AHR H30902 | 95604-H30902 | \$ 2,567.00 | 6% | \$2,431.08 |
| PWP NBD AHR H30904 | 95604-H30904 | \$ 3,781.00 | 6% | \$3,580.80 |
| PWP NBD AHR H30905 | 95604-H30905 | \$ 5,403.00 | 6% | \$5,116.91 |
| PWP NBD AHR H30906 | 95604-H30906 | \$ 146.00 | 6% | \$138.27 |
| PWP NBD AHR H30912 | 95604-H30912 | \$ 406.00 | 6% | \$384.50 |
| PWP NBD AHR H30913 | 95604-H30913 | \$ 43.00 | 6% | \$40.72 |
| PWP NBD AHR H30914 | 95604-H30914 | \$ 37.00 | 6% | \$35.04 |
| PWP NBD AHR H30915 | 95604-H30915 | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR H30916 | 95604-H30916 | \$ 40.00 | 6% | \$37.88 |
| PWP NBD AHR H30917 | 95604-H30917 | \$ 43.00 | 6% | \$40.72 |
| PWP NBD AHR H30918 | 95604-H30918 | \$ 43.00 | 6% | \$40.72 |
| PWP NBD AHR H30946 | 95604-H30946 | \$ 77.00 | 6% | \$72.92 |
| PWP NBD AHR H30948 | 95604-H30948 | \$ 77.00 | 6% | \$72.92 |
| PWP NBD AHR H30950 | 95604-H30950 | \$ 85.00 | 6% | \$80.50 |
| PWP NBD AHR H30951 | 95604-H30951 | \$ 77.00 | 6% | \$72.92 |
| PWP NBD AHR H30952 | 95604-H30952 | \$ 77.00 | 6% | \$72.92 |
| PWP NBD AHR H30966 | 95604-H30966 | \$ 131.00 | 6% | \$124.06 |
| PWP NBD AHR H30967 | 95604-H30967 | \$ 122.00 | 6% | \$115.54 |
| PWP NBD AHR H30968 | 95604-H30968 | \$ 131.00 | 6% | \$124.06 |
| PWP NBD AHR H30969 | 95604-H30969 | \$ 69.00 | 6% | \$65.35 |
| PWP NBD AHR H30970 | 95604-H30970 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H30971 | 95604-H30971 | \$ 83.00 | 6% | \$78.61 |
| PWP NBD AHR H30972 | 95604-H30972 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H30973 | 95604-H30973 | \$ 136.00 | 6% | \$128.80 |
| PWP NBD AHR H30974 | 95604-H30974 | \$ 118.00 | 6% | \$111.75 |

| | | | | |
|--------------------|--------------|-------------|----|-------------------|
| PWP NBD AHR H30975 | 95604-H30975 | \$ 136.00 | 6% | <i>\$128.80</i> |
| PWP NBD AHR H30976 | 95604-H30976 | \$ 136.00 | 6% | <i>\$128.80</i> |
| PWP NBD AHR H30977 | 95604-H30977 | \$ 118.00 | 6% | <i>\$111.75</i> |
| PWP NBD AHR H30978 | 95604-H30978 | \$ 136.00 | 6% | <i>\$128.80</i> |
| PWP NBD AHR H30995 | 95604-H30995 | \$ 1,478.00 | 6% | <i>\$1,399.74</i> |
| PWP NBD AHR H31030 | 95604-H31030 | \$ 4,773.00 | 6% | <i>\$4,520.27</i> |
| PWP NBD AHR H31031 | 95604-H31031 | \$ 380.00 | 6% | <i>\$359.88</i> |
| PWP NBD AHR H31033 | 95604-H31033 | \$ 2,892.00 | 6% | <i>\$2,738.87</i> |
| PWP NBD AHR H31034 | 95604-H31034 | \$ 1,608.00 | 6% | <i>\$1,522.86</i> |
| PWP NBD AHR H31035 | 95604-H31035 | \$ 1,682.00 | 6% | <i>\$1,592.94</i> |
| PWP NBD AHR H31036 | 95604-H31036 | \$ 3,368.00 | 6% | <i>\$3,189.66</i> |
| PWP NBD AHR H31040 | 95604-H31040 | \$ 125.00 | 6% | <i>\$118.38</i> |
| PWP NBD AHR H31041 | 95604-H31041 | \$ 65.00 | 6% | <i>\$61.56</i> |
| PWP NBD AHR H31042 | 95604-H31042 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PWP NBD AHR H31043 | 95604-H31043 | \$ 134.00 | 6% | <i>\$126.90</i> |
| PWP NBD AHR H31044 | 95604-H31044 | \$ 437.00 | 6% | <i>\$413.86</i> |
| PWP NBD AHR H31047 | 95604-H31047 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PWP NBD AHR H31049 | 95604-H31049 | \$ 1,344.00 | 6% | <i>\$1,272.84</i> |
| PWP NBD AHR H31060 | 95604-H31060 | \$ 35.00 | 6% | <i>\$33.15</i> |
| PWP NBD AHR H31062 | 95604-H31062 | \$ 37.00 | 6% | <i>\$35.04</i> |
| PWP NBD AHR H31066 | 95604-H31066 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR H31068 | 95604-H31068 | \$ 51.00 | 6% | <i>\$48.30</i> |
| PWP NBD AHR H31076 | 95604-H31076 | \$ 183.00 | 6% | <i>\$173.31</i> |
| PWP NBD AHR H31077 | 95604-H31077 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PWP NBD AHR H31078 | 95604-H31078 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PWP NBD AHR H31103 | 95604-H31103 | \$ 3,083.00 | 6% | <i>\$2,919.76</i> |
| PWP NBD AHR H31119 | 95604-H31119 | \$ 70.00 | 6% | <i>\$66.29</i> |
| PWP NBD AHR H31124 | 95604-H31124 | \$ 74.00 | 6% | <i>\$70.08</i> |
| PWP NBD AHR H31127 | 95604-H31127 | \$ 122.00 | 6% | <i>\$115.54</i> |
| PWP NBD AHR H31132 | 95604-H31132 | \$ 119.00 | 6% | <i>\$112.70</i> |
| PWP NBD AHR H31134 | 95604-H31134 | \$ 39.00 | 6% | <i>\$36.93</i> |
| PWP NBD AHR H31135 | 95604-H31135 | \$ 44.00 | 6% | <i>\$41.67</i> |
| PWP NBD AHR H31136 | 95604-H31136 | \$ 64.00 | 6% | <i>\$60.61</i> |
| PWP NBD AHR H31137 | 95604-H31137 | \$ 59.00 | 6% | <i>\$55.88</i> |
| PWP NBD AHR H31197 | 95604-H31197 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PWP NBD AHR H31198 | 95604-H31198 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PWP NBD AHR H31199 | 95604-H31199 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PWP NBD AHR H31200 | 95604-H31200 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PWP NBD AHR H31201 | 95604-H31201 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PWP NBD AHR H31202 | 95604-H31202 | \$ 69.00 | 6% | <i>\$65.35</i> |
| PWP NBD AHR H31203 | 95604-H31203 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PWP NBD AHR H31204 | 95604-H31204 | \$ 71.00 | 6% | <i>\$67.24</i> |

| | | | | |
|--------------------|--------------|--------------|----|--------------------|
| PWP NBD AHR H31205 | 95604-H31205 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PWP NBD AHR H31206 | 95604-H31206 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PWP NBD AHR H31207 | 95604-H31207 | \$ 71.00 | 6% | <i>\$67.24</i> |
| PWP NBD AHR H31208 | 95604-H31208 | \$ 81.00 | 6% | <i>\$76.71</i> |
| PWP NBD AHR H31210 | 95604-H31210 | \$ 146.00 | 6% | <i>\$138.27</i> |
| PWP NBD AHR H31335 | 95604-H31335 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP NBD AHR H31337 | 95604-H31337 | \$ 6,362.00 | 6% | <i>\$6,025.13</i> |
| PWP NBD AHR H31338 | 95604-H31338 | \$ 6,362.00 | 6% | <i>\$6,025.13</i> |
| PWP NBD AHR H31339 | 95604-H31339 | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| PWP NBD AHR H31340 | 95604-H31340 | \$ 2,210.00 | 6% | <i>\$2,092.98</i> |
| PWP NBD AHR H31341 | 95604-H31341 | \$ 3,275.00 | 6% | <i>\$3,101.59</i> |
| PWP NBD AHR H31342 | 95604-H31342 | \$ 1,030.00 | 6% | <i>\$975.46</i> |
| PWP NBD AHR H31343 | 95604-H31343 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |
| PWP NBD AHR H31344 | 95604-H31344 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |
| PWP NBD AHR H31345 | 95604-H31345 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |
| PWP NBD AHR H31346 | 95604-H31346 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |
| PWP NBD AHR H31348 | 95604-H31348 | \$ 118.00 | 6% | <i>\$111.75</i> |
| PWP NBD AHR H31349 | 95604-H31349 | \$ 118.00 | 6% | <i>\$111.75</i> |
| PWP NBD AHR H31350 | 95604-H31350 | \$ 190.00 | 6% | <i>\$179.94</i> |
| PWP NBD AHR H31351 | 95604-H31351 | \$ 71.00 | 6% | <i>\$67.24</i> |
| PWP NBD AHR H31352 | 95604-H31352 | \$ 71.00 | 6% | <i>\$67.24</i> |
| PWP NBD AHR H31353 | 95604-H31353 | \$ 61.00 | 6% | <i>\$57.77</i> |
| PWP NBD AHR H31354 | 95604-H31354 | \$ 61.00 | 6% | <i>\$57.77</i> |
| PWP NBD AHR H31355 | 95604-H31355 | \$ 122.00 | 6% | <i>\$115.54</i> |
| PWP NBD AHR H31356 | 95604-H31356 | \$ 122.00 | 6% | <i>\$115.54</i> |
| PWP NBD AHR H31357 | 95604-H31357 | \$ 122.00 | 6% | <i>\$115.54</i> |
| PWP NBD AHR H31358 | 95604-H31358 | \$ 46.00 | 6% | <i>\$43.56</i> |
| PWP NBD AHR H31359 | 95604-H31359 | \$ 48.00 | 6% | <i>\$45.46</i> |
| PWP NBD AHR H31360 | 95604-H31360 | \$ 43.00 | 6% | <i>\$40.72</i> |
| PWP NBD AHR H31361 | 95604-H31361 | \$ 2,083.00 | 6% | <i>\$1,972.71</i> |
| PWP NBD AHR H31362 | 95604-H31362 | \$ 12,892.00 | 6% | <i>\$12,209.37</i> |
| PWP NBD AHR H31363 | 95604-H31363 | \$ 12,892.00 | 6% | <i>\$12,209.37</i> |
| PWP NBD AHR H31364 | 95604-H31364 | \$ 4,510.00 | 6% | <i>\$4,271.20</i> |
| PWP NBD AHR H31365 | 95604-H31365 | \$ 4,510.00 | 6% | <i>\$4,271.20</i> |
| PWP NBD AHR H31366 | 95604-H31366 | \$ 6,245.00 | 6% | <i>\$5,914.33</i> |
| PWP NBD AHR H31367 | 95604-H31367 | \$ 6,245.00 | 6% | <i>\$5,914.33</i> |
| PWP NBD AHR H31369 | 95604-H31369 | \$ 71.00 | 6% | <i>\$67.24</i> |
| PWP NBD AHR H31370 | 95604-H31370 | \$ 71.00 | 6% | <i>\$67.24</i> |
| PWP NBD AHR H31393 | 95604-H31393 | \$ 43.00 | 6% | <i>\$40.72</i> |
| PWP NBD AHR H32010 | 95604-H32010 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PWP NBD AHR H32011 | 95604-H32011 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PWP NBD AHR H32012 | 95604-H32012 | \$ 1,658.00 | 6% | <i>\$1,570.21</i> |

| | | | | |
|--------------------|--------------|--------------|----|--------------------|
| PWP NBD AHR H32013 | 95604-H32013 | \$ 1,658.00 | 6% | <i>\$1,570.21</i> |
| PWP NBD AHR H32014 | 95604-H32014 | \$ 1,658.00 | 6% | <i>\$1,570.21</i> |
| PWP NBD AHR H32015 | 95604-H32015 | \$ 1,658.00 | 6% | <i>\$1,570.21</i> |
| PWP NBD AHR H32016 | 95604-H32016 | \$ 1,449.00 | 6% | <i>\$1,372.28</i> |
| PWP NBD AHR H32017 | 95604-H32017 | \$ 1,449.00 | 6% | <i>\$1,372.28</i> |
| PWP NBD AHR H32018 | 95604-H32018 | \$ 1,449.00 | 6% | <i>\$1,372.28</i> |
| PWP NBD AHR H32019 | 95604-H32019 | \$ 1,449.00 | 6% | <i>\$1,372.28</i> |
| PWP NBD AHR H32020 | 95604-H32020 | \$ 14,483.00 | 6% | <i>\$13,716.13</i> |
| PWP NBD AHR H32021 | 95604-H32021 | \$ 14,483.00 | 6% | <i>\$13,716.13</i> |
| PWP NBD AHR H32022 | 95604-H32022 | \$ 14,483.00 | 6% | <i>\$13,716.13</i> |
| PWP NBD AHR H32023 | 95604-H32023 | \$ 14,483.00 | 6% | <i>\$13,716.13</i> |
| PWP NBD AHR H32028 | 95604-H32028 | \$ 27,918.00 | 6% | <i>\$26,439.74</i> |
| PWP NBD AHR H32029 | 95604-H32029 | \$ 27,918.00 | 6% | <i>\$26,439.74</i> |
| PWP NBD AHR H32030 | 95604-H32030 | \$ 29,279.00 | 6% | <i>\$27,728.68</i> |
| PWP NBD AHR H32031 | 95604-H32031 | \$ 29,279.00 | 6% | <i>\$27,728.68</i> |
| PWP NBD AHR H32032 | 95604-H32032 | \$ 29,279.00 | 6% | <i>\$27,728.68</i> |
| PWP NBD AHR H32033 | 95604-H32033 | \$ 29,279.00 | 6% | <i>\$27,728.68</i> |
| PWP NBD AHR H32038 | 95604-H32038 | \$ 5,063.00 | 6% | <i>\$4,794.91</i> |
| PWP NBD AHR H32039 | 95604-H32039 | \$ 5,063.00 | 6% | <i>\$4,794.91</i> |
| PWP NBD AHR H32040 | 95604-H32040 | \$ 5,063.00 | 6% | <i>\$4,794.91</i> |
| PWP NBD AHR H32041 | 95604-H32041 | \$ 5,063.00 | 6% | <i>\$4,794.91</i> |
| PWP NBD AHR H32046 | 95604-H32046 | \$ 7,016.00 | 6% | <i>\$6,644.50</i> |
| PWP NBD AHR H32047 | 95604-H32047 | \$ 7,016.00 | 6% | <i>\$6,644.50</i> |
| PWP NBD AHR H32048 | 95604-H32048 | \$ 7,016.00 | 6% | <i>\$6,644.50</i> |
| PWP NBD AHR H32049 | 95604-H32049 | \$ 7,016.00 | 6% | <i>\$6,644.50</i> |
| PWP NBD AHR H32054 | 95604-H32054 | \$ 5,063.00 | 6% | <i>\$4,794.91</i> |
| PWP NBD AHR H32055 | 95604-H32055 | \$ 7,016.00 | 6% | <i>\$6,644.50</i> |
| PWP NBD AHR H32056 | 95604-H32056 | \$ 1,573.00 | 6% | <i>\$1,489.71</i> |
| PWP NBD AHR H32057 | 95604-H32057 | \$ 1,573.00 | 6% | <i>\$1,489.71</i> |
| PWP NBD AHR H32058 | 95604-H32058 | \$ 1,573.00 | 6% | <i>\$1,489.71</i> |
| PWP NBD AHR H32059 | 95604-H32059 | \$ 1,573.00 | 6% | <i>\$1,489.71</i> |
| PWP NBD AHR H32060 | 95604-H32060 | \$ 1,961.00 | 6% | <i>\$1,857.17</i> |
| PWP NBD AHR H32061 | 95604-H32061 | \$ 2,059.00 | 6% | <i>\$1,949.98</i> |
| PWP NBD AHR H32062 | 95604-H32062 | \$ 1,980.00 | 6% | <i>\$1,875.16</i> |
| PWP NBD AHR H32063 | 95604-H32063 | \$ 1,964.00 | 6% | <i>\$1,860.01</i> |
| PWP NBD AHR H32064 | 95604-H32064 | \$ 1,980.00 | 6% | <i>\$1,875.16</i> |
| PWP NBD AHR H32065 | 95604-H32065 | \$ 2,239.00 | 6% | <i>\$2,120.44</i> |
| PWP NBD AHR H32066 | 95604-H32066 | \$ 2,239.00 | 6% | <i>\$2,120.44</i> |
| PWP NBD AHR H32067 | 95604-H32067 | \$ 2,239.00 | 6% | <i>\$2,120.44</i> |
| PWP NBD AHR H32068 | 95604-H32068 | \$ 2,239.00 | 6% | <i>\$2,120.44</i> |
| PWP NBD AHR H32069 | 95604-H32069 | \$ 2,784.00 | 6% | <i>\$2,636.59</i> |
| PWP NBD AHR H32070 | 95604-H32070 | \$ 2,784.00 | 6% | <i>\$2,636.59</i> |

| | | | | |
|--------------------|--------------|--------------|----|-------------|
| PWP NBD AHR H32071 | 95604-H32071 | \$ 2,784.00 | 6% | \$2,636.59 |
| PWP NBD AHR H32072 | 95604-H32072 | \$ 2,784.00 | 6% | \$2,636.59 |
| PWP NBD AHR H32073 | 95604-H32073 | \$ 20,567.00 | 6% | \$19,477.98 |
| PWP NBD AHR H32074 | 95604-H32074 | \$ 20,567.00 | 6% | \$19,477.98 |
| PWP NBD AHR H32075 | 95604-H32075 | \$ 27,956.00 | 6% | \$26,475.73 |
| PWP NBD AHR H32076 | 95604-H32076 | \$ 27,956.00 | 6% | \$26,475.73 |
| PWP NBD AHR H32101 | 95604-H32101 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32102 | 95604-H32102 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32103 | 95604-H32103 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32104 | 95604-H32104 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32105 | 95604-H32105 | \$ 1,813.00 | 6% | \$1,717.00 |
| PWP NBD AHR H32106 | 95604-H32106 | \$ 1,813.00 | 6% | \$1,717.00 |
| PWP NBD AHR H32107 | 95604-H32107 | \$ 4,912.00 | 6% | \$4,651.91 |
| PWP NBD AHR H32108 | 95604-H32108 | \$ 4,912.00 | 6% | \$4,651.91 |
| PWP NBD AHR H32109 | 95604-H32109 | \$ 1,813.00 | 6% | \$1,717.00 |
| PWP NBD AHR H32110 | 95604-H32110 | \$ 1,798.00 | 6% | \$1,702.80 |
| PWP NBD AHR H32111 | 95604-H32111 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32112 | 95604-H32112 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32113 | 95604-H32113 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32114 | 95604-H32114 | \$ 908.00 | 6% | \$859.92 |
| PWP NBD AHR H32115 | 95604-H32115 | \$ 1,813.00 | 6% | \$1,717.00 |
| PWP NBD AHR H32116 | 95604-H32116 | \$ 1,813.00 | 6% | \$1,717.00 |
| PWP NBD AHR H32117 | 95604-H32117 | \$ 857.00 | 6% | \$811.62 |
| PWP NBD AHR H32118 | 95604-H32118 | \$ 857.00 | 6% | \$811.62 |
| PWP NBD AHR H32119 | 95604-H32119 | \$ 857.00 | 6% | \$811.62 |
| PWP NBD AHR H32120 | 95604-H32120 | \$ 857.00 | 6% | \$811.62 |
| PWP NBD AHR H32121 | 95604-H32121 | \$ 4,912.00 | 6% | \$4,651.91 |
| PWP NBD AHR H32122 | 95604-H32122 | \$ 4,912.00 | 6% | \$4,651.91 |
| PWP NBD AHR H32123 | 95604-H32123 | \$ 1,813.00 | 6% | \$1,717.00 |
| PWP NBD AHR H32124 | 95604-H32124 | \$ 1,813.00 | 6% | \$1,717.00 |
| PWP NBD AHR H32125 | 95604-H32125 | \$ 1,788.00 | 6% | \$1,693.33 |
| PWP NBD AHR H32126 | 95604-H32126 | \$ 1,788.00 | 6% | \$1,693.33 |
| PWP NBD AHR H32127 | 95604-H32127 | \$ 2,106.00 | 6% | \$1,994.49 |
| PWP NBD AHR H32128 | 95604-H32128 | \$ 2,106.00 | 6% | \$1,994.49 |
| PWP NBD AHR H32129 | 95604-H32129 | \$ 2,106.00 | 6% | \$1,994.49 |
| PWP NBD AHR H32130 | 95604-H32130 | \$ 2,106.00 | 6% | \$1,994.49 |
| PWP NBD AHR H32131 | 95604-H32131 | \$ 2,106.00 | 6% | \$1,994.49 |
| PWP NBD AHR H32132 | 95604-H32132 | \$ 2,106.00 | 6% | \$1,994.49 |
| PWP NBD AHR H32133 | 95604-H32133 | \$ 1,788.00 | 6% | \$1,693.33 |
| PWP NBD AHR H32134 | 95604-H32134 | \$ 1,788.00 | 6% | \$1,693.33 |
| PWP NBD AHR H32135 | 95604-H32135 | \$ 1,788.00 | 6% | \$1,693.33 |
| PWP NBD AHR H32136 | 95604-H32136 | \$ 1,788.00 | 6% | \$1,693.33 |

| | | | | |
|--------------------|--------------|--------------|----|------------|
| PWP NBD AHR H32137 | 95604-H32137 | \$ 1,788.00 | 6% | \$1,693.33 |
| PWP NBD AHR H32138 | 95604-H32138 | \$ 1,788.00 | 6% | \$1,693.33 |
| PWP NBD AHR H32139 | 95604-H32139 | \$ 7,584.00 | 6% | \$7,182.43 |
| PWP NBD AHR H32140 | 95604-H32140 | \$ 7,584.00 | 6% | \$7,182.43 |
| PWP NBD AHR H32141 | 95604-H32141 | \$ 8,745.00 | 6% | \$8,281.95 |
| PWP NBD AHR H32142 | 95604-H32142 | \$ 8,745.00 | 6% | \$8,281.95 |
| PWP NBD AHR H32143 | 95604-H32143 | \$ 353.00 | 6% | \$334.31 |
| PWP NBD AHR H32144 | 95604-H32144 | \$ 338.00 | 6% | \$320.10 |
| PWP NBD AHR H32146 | 95604-H32146 | \$ 773.00 | 6% | \$732.07 |
| PWP NBD AHR H32147 | 95604-H32147 | \$ 773.00 | 6% | \$732.07 |
| PWP NBD AHR H32148 | 95604-H32148 | \$ 1,594.00 | 6% | \$1,509.60 |
| PWP NBD AHR H32149 | 95604-H32149 | \$ 1,594.00 | 6% | \$1,509.60 |
| PWP NBD AHR H32150 | 95604-H32150 | \$ 818.00 | 6% | \$774.69 |
| PWP NBD AHR H32151 | 95604-H32151 | \$ 361.00 | 6% | \$341.89 |
| PWP NBD AHR H32152 | 95604-H32152 | \$ 353.00 | 6% | \$334.31 |
| PWP NBD AHR H32169 | 95604-H32169 | \$ 917.00 | 6% | \$868.44 |
| PWP NBD AHR H32170 | 95604-H32170 | \$ 917.00 | 6% | \$868.44 |
| PWP NBD AHR H32171 | 95604-H32171 | \$ 867.00 | 6% | \$821.09 |
| PWP NBD AHR H32172 | 95604-H32172 | \$ 867.00 | 6% | \$821.09 |
| PWP NBD AHR H32173 | 95604-H32173 | \$ 2,289.00 | 6% | \$2,167.80 |
| PWP NBD AHR H32174 | 95604-H32174 | \$ 2,289.00 | 6% | \$2,167.80 |
| PWP NBD AHR H32175 | 95604-H32175 | \$ 1,945.00 | 6% | \$1,842.01 |
| PWP NBD AHR H32176 | 95604-H32176 | \$ 1,945.00 | 6% | \$1,842.01 |
| PWP NBD AHR H32177 | 95604-H32177 | \$ 8,939.00 | 6% | \$8,465.68 |
| PWP NBD AHR H32178 | 95604-H32178 | \$ 10,309.00 | 6% | \$9,763.14 |
| PWP NBD AHR H34008 | 95604-H34008 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34009 | 95604-H34009 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34010 | 95604-H34010 | \$ 27.00 | 6% | \$25.57 |
| PWP NBD AHR H34011 | 95604-H34011 | \$ 58.00 | 6% | \$54.93 |
| PWP NBD AHR H34012 | 95604-H34012 | \$ 102.00 | 6% | \$96.60 |
| PWP NBD AHR H34013 | 95604-H34013 | \$ 39.00 | 6% | \$36.93 |
| PWP NBD AHR H34014 | 95604-H34014 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34015 | 95604-H34015 | \$ 33.00 | 6% | \$31.25 |
| PWP NBD AHR H34016 | 95604-H34016 | \$ 72.00 | 6% | \$68.19 |
| PWP NBD AHR H34017 | 95604-H34017 | \$ 120.00 | 6% | \$113.65 |
| PWP NBD AHR H34018 | 95604-H34018 | \$ 63.00 | 6% | \$59.66 |
| PWP NBD AHR H34019 | 95604-H34019 | \$ 63.00 | 6% | \$59.66 |
| PWP NBD AHR H34020 | 95604-H34020 | \$ 63.00 | 6% | \$59.66 |
| PWP NBD AHR H34021 | 95604-H34021 | \$ 63.00 | 6% | \$59.66 |
| PWP NBD AHR H34048 | 95604-H34048 | \$ 168.00 | 6% | \$159.10 |
| PWP NBD AHR H34049 | 95604-H34049 | \$ 168.00 | 6% | \$159.10 |
| PWP NBD AHR H34050 | 95604-H34050 | \$ 121.00 | 6% | \$114.59 |

| | | | | |
|--------------------|--------------|-------------|----|-------------------|
| PWP NBD AHR H34051 | 95604-H34051 | \$ 121.00 | 6% | <i>\$114.59</i> |
| PWP NBD AHR H34052 | 95604-H34052 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PWP NBD AHR H34053 | 95604-H34053 | \$ 191.00 | 6% | <i>\$180.89</i> |
| PWP NBD AHR H34054 | 95604-H34054 | \$ 145.00 | 6% | <i>\$137.32</i> |
| PWP NBD AHR H34055 | 95604-H34055 | \$ 145.00 | 6% | <i>\$137.32</i> |
| PWP NBD AHR H34056 | 95604-H34056 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP NBD AHR H34057 | 95604-H34057 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP NBD AHR H34058 | 95604-H34058 | \$ 183.00 | 6% | <i>\$173.31</i> |
| PWP NBD AHR H34059 | 95604-H34059 | \$ 183.00 | 6% | <i>\$173.31</i> |
| PWP NBD AHR H34062 | 95604-H34062 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP NBD AHR H34063 | 95604-H34063 | \$ 209.00 | 6% | <i>\$197.93</i> |
| PWP NBD AHR H34064 | 95604-H34064 | \$ 201.00 | 6% | <i>\$190.36</i> |
| PWP NBD AHR H34065 | 95604-H34065 | \$ 201.00 | 6% | <i>\$190.36</i> |
| PWP NBD AHR H34066 | 95604-H34066 | \$ 201.00 | 6% | <i>\$190.36</i> |
| PWP NBD AHR H34067 | 95604-H34067 | \$ 201.00 | 6% | <i>\$190.36</i> |
| PWP NBD AHR H34068 | 95604-H34068 | \$ 201.00 | 6% | <i>\$190.36</i> |
| PWP NBD AHR H34069 | 95604-H34069 | \$ 194.00 | 6% | <i>\$183.73</i> |
| PWP NBD AHR H34070 | 95604-H34070 | \$ 201.00 | 6% | <i>\$190.36</i> |
| PWP NBD AHR H34071 | 95604-H34071 | \$ 201.00 | 6% | <i>\$190.36</i> |
| PWP NBD AHR H34072 | 95604-H34072 | \$ 1,387.00 | 6% | <i>\$1,313.56</i> |
| PWP NBD AHR H34073 | 95604-H34073 | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| PWP NBD AHR H34074 | 95604-H34074 | \$ 1,909.00 | 6% | <i>\$1,807.92</i> |
| PWP NBD AHR H34075 | 95604-H34075 | \$ 1,828.00 | 6% | <i>\$1,731.21</i> |
| PWP NBD AHR H34076 | 95604-H34076 | \$ 1,387.00 | 6% | <i>\$1,313.56</i> |
| PWP NBD AHR H34077 | 95604-H34077 | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| PWP NBD AHR H34078 | 95604-H34078 | \$ 1,387.00 | 6% | <i>\$1,313.56</i> |
| PWP NBD AHR H34079 | 95604-H34079 | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| PWP NBD AHR H34080 | 95604-H34080 | \$ 1,909.00 | 6% | <i>\$1,807.92</i> |
| PWP NBD AHR H34081 | 95604-H34081 | \$ 1,828.00 | 6% | <i>\$1,731.21</i> |
| PWP NBD AHR H34082 | 95604-H34082 | \$ 1,831.00 | 6% | <i>\$1,734.05</i> |
| PWP NBD AHR H34083 | 95604-H34083 | \$ 1,754.00 | 6% | <i>\$1,661.13</i> |
| PWP NBD AHR H34084 | 95604-H34084 | \$ 1,621.00 | 6% | <i>\$1,535.17</i> |
| PWP NBD AHR H34085 | 95604-H34085 | \$ 1,621.00 | 6% | <i>\$1,535.17</i> |
| PWP NBD AHR H34086 | 95604-H34086 | \$ 1,652.00 | 6% | <i>\$1,564.53</i> |
| PWP NBD AHR H34087 | 95604-H34087 | \$ 1,584.00 | 6% | <i>\$1,500.13</i> |
| PWP NBD AHR H34088 | 95604-H34088 | \$ 2,981.00 | 6% | <i>\$2,823.16</i> |
| PWP NBD AHR H34089 | 95604-H34089 | \$ 2,981.00 | 6% | <i>\$2,823.16</i> |
| PWP NBD AHR H34090 | 95604-H34090 | \$ 3,432.00 | 6% | <i>\$3,250.28</i> |
| PWP NBD AHR H34091 | 95604-H34091 | \$ 1,936.00 | 6% | <i>\$1,833.49</i> |
| PWP NBD AHR H34092 | 95604-H34092 | \$ 1,936.00 | 6% | <i>\$1,833.49</i> |
| PWP NBD AHR H34093 | 95604-H34093 | \$ 1,936.00 | 6% | <i>\$1,833.49</i> |
| PWP NBD AHR H34094 | 95604-H34094 | \$ 222.00 | 6% | <i>\$210.25</i> |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PWP NBD AHR H34095 | 95604-H34095 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34096 | 95604-H34096 | \$ 258.00 | 6% | \$244.34 |
| PWP NBD AHR H34097 | 95604-H34097 | \$ 258.00 | 6% | \$244.34 |
| PWP NBD AHR H34098 | 95604-H34098 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34099 | 95604-H34099 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34100 | 95604-H34100 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34101 | 95604-H34101 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34102 | 95604-H34102 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34103 | 95604-H34103 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34104 | 95604-H34104 | \$ 100.00 | 6% | \$94.71 |
| PWP NBD AHR H34105 | 95604-H34105 | \$ 100.00 | 6% | \$94.71 |
| PWP NBD AHR H34106 | 95604-H34106 | \$ 100.00 | 6% | \$94.71 |
| PWP NBD AHR H34107 | 95604-H34107 | \$ 100.00 | 6% | \$94.71 |
| PWP NBD AHR H34108 | 95604-H34108 | \$ 100.00 | 6% | \$94.71 |
| PWP NBD AHR H34109 | 95604-H34109 | \$ 100.00 | 6% | \$94.71 |
| PWP NBD AHR H34110 | 95604-H34110 | \$ 1,866.00 | 6% | \$1,767.20 |
| PWP NBD AHR H34111 | 95604-H34111 | \$ 1,866.00 | 6% | \$1,767.20 |
| PWP NBD AHR H34112 | 95604-H34112 | \$ 1,866.00 | 6% | \$1,767.20 |
| PWP NBD AHR H34114 | 95604-H34114 | \$ 2,452.00 | 6% | \$2,322.17 |
| PWP NBD AHR H34115 | 95604-H34115 | \$ 2,452.00 | 6% | \$2,322.17 |
| PWP NBD AHR H34116 | 95604-H34116 | \$ 2,452.00 | 6% | \$2,322.17 |
| PWP NBD AHR H34117 | 95604-H34117 | \$ 2,452.00 | 6% | \$2,322.17 |
| PWP NBD AHR H34118 | 95604-H34118 | \$ 617.00 | 6% | \$584.33 |
| PWP NBD AHR H34119 | 95604-H34119 | \$ 617.00 | 6% | \$584.33 |
| PWP NBD AHR H34120 | 95604-H34120 | \$ 425.00 | 6% | \$402.50 |
| PWP NBD AHR H34121 | 95604-H34121 | \$ 425.00 | 6% | \$402.50 |
| PWP NBD AHR H34122 | 95604-H34122 | \$ 453.00 | 6% | \$429.01 |
| PWP NBD AHR H34123 | 95604-H34123 | \$ 453.00 | 6% | \$429.01 |
| PWP NBD AHR H34124 | 95604-H34124 | \$ 664.00 | 6% | \$628.84 |
| PWP NBD AHR H34125 | 95604-H34125 | \$ 664.00 | 6% | \$628.84 |
| PWP NBD AHR H34126 | 95604-H34126 | \$ 664.00 | 6% | \$628.84 |
| PWP NBD AHR H34127 | 95604-H34127 | \$ 664.00 | 6% | \$628.84 |
| PWP NBD AHR H34128 | 95604-H34128 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34129 | 95604-H34129 | \$ 180.00 | 6% | \$170.47 |
| PWP NBD AHR H34130 | 95604-H34130 | \$ 186.00 | 6% | \$176.15 |
| PWP NBD AHR H34131 | 95604-H34131 | \$ 185.00 | 6% | \$175.20 |
| PWP NBD AHR H34132 | 95604-H34132 | \$ 186.00 | 6% | \$176.15 |
| PWP NBD AHR H34172 | 95604-H34172 | \$ 550.00 | 6% | \$520.88 |
| PWP NBD AHR H34174 | 95604-H34174 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34175 | 95604-H34175 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34176 | 95604-H34176 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34177 | 95604-H34177 | \$ 36.00 | 6% | \$34.09 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34178 | 95604-H34178 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34179 | 95604-H34179 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34180 | 95604-H34180 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34181 | 95604-H34181 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34182 | 95604-H34182 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34183 | 95604-H34183 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34184 | 95604-H34184 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34185 | 95604-H34185 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34186 | 95604-H34186 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34187 | 95604-H34187 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34188 | 95604-H34188 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34189 | 95604-H34189 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34190 | 95604-H34190 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34191 | 95604-H34191 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34192 | 95604-H34192 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34193 | 95604-H34193 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34194 | 95604-H34194 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34195 | 95604-H34195 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34196 | 95604-H34196 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34197 | 95604-H34197 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34198 | 95604-H34198 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34199 | 95604-H34199 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34200 | 95604-H34200 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34201 | 95604-H34201 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34202 | 95604-H34202 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34203 | 95604-H34203 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34204 | 95604-H34204 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34205 | 95604-H34205 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34206 | 95604-H34206 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34207 | 95604-H34207 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34208 | 95604-H34208 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34209 | 95604-H34209 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34210 | 95604-H34210 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34211 | 95604-H34211 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34212 | 95604-H34212 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34213 | 95604-H34213 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34214 | 95604-H34214 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34215 | 95604-H34215 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34216 | 95604-H34216 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34217 | 95604-H34217 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34218 | 95604-H34218 | \$ 36.00 | 6% | \$34.09 |
| PWP NBD AHR H34219 | 95604-H34219 | \$ 36.00 | 6% | \$34.09 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34220 | 95604-H34220 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34221 | 95604-H34221 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34222 | 95604-H34222 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34223 | 95604-H34223 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34224 | 95604-H34224 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34225 | 95604-H34225 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34226 | 95604-H34226 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34227 | 95604-H34227 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34228 | 95604-H34228 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34229 | 95604-H34229 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34230 | 95604-H34230 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34231 | 95604-H34231 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34232 | 95604-H34232 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34233 | 95604-H34233 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34234 | 95604-H34234 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34235 | 95604-H34235 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34236 | 95604-H34236 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34237 | 95604-H34237 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34238 | 95604-H34238 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34239 | 95604-H34239 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34240 | 95604-H34240 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34241 | 95604-H34241 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34242 | 95604-H34242 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34243 | 95604-H34243 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34244 | 95604-H34244 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34245 | 95604-H34245 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34246 | 95604-H34246 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34247 | 95604-H34247 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34248 | 95604-H34248 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34249 | 95604-H34249 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34250 | 95604-H34250 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34251 | 95604-H34251 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34252 | 95604-H34252 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34253 | 95604-H34253 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34254 | 95604-H34254 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34255 | 95604-H34255 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34256 | 95604-H34256 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34257 | 95604-H34257 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34258 | 95604-H34258 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34259 | 95604-H34259 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34260 | 95604-H34260 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34261 | 95604-H34261 | \$ 57.00 | 6% | \$53.98 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34262 | 95604-H34262 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34263 | 95604-H34263 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34264 | 95604-H34264 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34265 | 95604-H34265 | \$ 57.00 | 6% | \$53.98 |
| PWP NBD AHR H34266 | 95604-H34266 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34267 | 95604-H34267 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34268 | 95604-H34268 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34269 | 95604-H34269 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34270 | 95604-H34270 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34271 | 95604-H34271 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34272 | 95604-H34272 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34273 | 95604-H34273 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34274 | 95604-H34274 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34275 | 95604-H34275 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34276 | 95604-H34276 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34277 | 95604-H34277 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34278 | 95604-H34278 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34279 | 95604-H34279 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34280 | 95604-H34280 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34281 | 95604-H34281 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34282 | 95604-H34282 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34283 | 95604-H34283 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34284 | 95604-H34284 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34285 | 95604-H34285 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34286 | 95604-H34286 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34287 | 95604-H34287 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34288 | 95604-H34288 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34289 | 95604-H34289 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34290 | 95604-H34290 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34291 | 95604-H34291 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34292 | 95604-H34292 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34293 | 95604-H34293 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34294 | 95604-H34294 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34295 | 95604-H34295 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34296 | 95604-H34296 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34297 | 95604-H34297 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34298 | 95604-H34298 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34299 | 95604-H34299 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34300 | 95604-H34300 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34301 | 95604-H34301 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34302 | 95604-H34302 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34303 | 95604-H34303 | \$ 42.00 | 6% | \$39.78 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34304 | 95604-H34304 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34305 | 95604-H34305 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H34306 | 95604-H34306 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34307 | 95604-H34307 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34308 | 95604-H34308 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34309 | 95604-H34309 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34310 | 95604-H34310 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34311 | 95604-H34311 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34312 | 95604-H34312 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34313 | 95604-H34313 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34314 | 95604-H34314 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34315 | 95604-H34315 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34316 | 95604-H34316 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34317 | 95604-H34317 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34318 | 95604-H34318 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34319 | 95604-H34319 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34320 | 95604-H34320 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34321 | 95604-H34321 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34322 | 95604-H34322 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34323 | 95604-H34323 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34324 | 95604-H34324 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34325 | 95604-H34325 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34326 | 95604-H34326 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34327 | 95604-H34327 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34328 | 95604-H34328 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34329 | 95604-H34329 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34330 | 95604-H34330 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34331 | 95604-H34331 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34332 | 95604-H34332 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34333 | 95604-H34333 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34334 | 95604-H34334 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34335 | 95604-H34335 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34336 | 95604-H34336 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34337 | 95604-H34337 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34338 | 95604-H34338 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34339 | 95604-H34339 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34340 | 95604-H34340 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34341 | 95604-H34341 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34342 | 95604-H34342 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34343 | 95604-H34343 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34344 | 95604-H34344 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34345 | 95604-H34345 | \$ 64.00 | 6% | \$60.61 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34346 | 95604-H34346 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34347 | 95604-H34347 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34348 | 95604-H34348 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34349 | 95604-H34349 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34350 | 95604-H34350 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34351 | 95604-H34351 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34352 | 95604-H34352 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34353 | 95604-H34353 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34354 | 95604-H34354 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34355 | 95604-H34355 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34356 | 95604-H34356 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34357 | 95604-H34357 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34358 | 95604-H34358 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34359 | 95604-H34359 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34360 | 95604-H34360 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34361 | 95604-H34361 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34362 | 95604-H34362 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34363 | 95604-H34363 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34364 | 95604-H34364 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34365 | 95604-H34365 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34366 | 95604-H34366 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34367 | 95604-H34367 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34368 | 95604-H34368 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34369 | 95604-H34369 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34370 | 95604-H34370 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34371 | 95604-H34371 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34372 | 95604-H34372 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34373 | 95604-H34373 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34374 | 95604-H34374 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34375 | 95604-H34375 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34376 | 95604-H34376 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34377 | 95604-H34377 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34378 | 95604-H34378 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34379 | 95604-H34379 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34380 | 95604-H34380 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34381 | 95604-H34381 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34382 | 95604-H34382 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34383 | 95604-H34383 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34384 | 95604-H34384 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34385 | 95604-H34385 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34386 | 95604-H34386 | \$ 96.00 | 6% | \$90.92 |
| PWP NBD AHR H34387 | 95604-H34387 | \$ 96.00 | 6% | \$90.92 |

| | | | | |
|--------------------|--------------|-----------|----|-----------------|
| PWP NBD AHR H34388 | 95604-H34388 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34389 | 95604-H34389 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34390 | 95604-H34390 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34391 | 95604-H34391 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34392 | 95604-H34392 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34393 | 95604-H34393 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34394 | 95604-H34394 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34395 | 95604-H34395 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34396 | 95604-H34396 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34397 | 95604-H34397 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34398 | 95604-H34398 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34399 | 95604-H34399 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34400 | 95604-H34400 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34401 | 95604-H34401 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34402 | 95604-H34402 | \$ 96.00 | 6% | <i>\$90.92</i> |
| PWP NBD AHR H34403 | 95604-H34403 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34404 | 95604-H34404 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34405 | 95604-H34405 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34406 | 95604-H34406 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34407 | 95604-H34407 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34408 | 95604-H34408 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34409 | 95604-H34409 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34410 | 95604-H34410 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34411 | 95604-H34411 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34412 | 95604-H34412 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34413 | 95604-H34413 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34414 | 95604-H34414 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34415 | 95604-H34415 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34416 | 95604-H34416 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34417 | 95604-H34417 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34418 | 95604-H34418 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34419 | 95604-H34419 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34420 | 95604-H34420 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34421 | 95604-H34421 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34422 | 95604-H34422 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34423 | 95604-H34423 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34424 | 95604-H34424 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34425 | 95604-H34425 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34426 | 95604-H34426 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34427 | 95604-H34427 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34428 | 95604-H34428 | \$ 150.00 | 6% | <i>\$142.06</i> |
| PWP NBD AHR H34429 | 95604-H34429 | \$ 150.00 | 6% | <i>\$142.06</i> |

| | | | | |
|--------------------|--------------|-----------|----|----------|
| PWP NBD AHR H34430 | 95604-H34430 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34431 | 95604-H34431 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34432 | 95604-H34432 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34433 | 95604-H34433 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34434 | 95604-H34434 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34435 | 95604-H34435 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34436 | 95604-H34436 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34437 | 95604-H34437 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34438 | 95604-H34438 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34439 | 95604-H34439 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34440 | 95604-H34440 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34441 | 95604-H34441 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34442 | 95604-H34442 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34443 | 95604-H34443 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34444 | 95604-H34444 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34445 | 95604-H34445 | \$ 150.00 | 6% | \$142.06 |
| PWP NBD AHR H34446 | 95604-H34446 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34447 | 95604-H34447 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34448 | 95604-H34448 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34449 | 95604-H34449 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34450 | 95604-H34450 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34451 | 95604-H34451 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34452 | 95604-H34452 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34453 | 95604-H34453 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34454 | 95604-H34454 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34455 | 95604-H34455 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34456 | 95604-H34456 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34457 | 95604-H34457 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34458 | 95604-H34458 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34459 | 95604-H34459 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34460 | 95604-H34460 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34461 | 95604-H34461 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34462 | 95604-H34462 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34463 | 95604-H34463 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34464 | 95604-H34464 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34465 | 95604-H34465 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34466 | 95604-H34466 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34467 | 95604-H34467 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34468 | 95604-H34468 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34469 | 95604-H34469 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34470 | 95604-H34470 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34471 | 95604-H34471 | \$ 174.00 | 6% | \$164.79 |

| | | | | |
|--------------------|--------------|-----------|----|----------|
| PWP NBD AHR H34472 | 95604-H34472 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34473 | 95604-H34473 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34474 | 95604-H34474 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34475 | 95604-H34475 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34476 | 95604-H34476 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34477 | 95604-H34477 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34478 | 95604-H34478 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34479 | 95604-H34479 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34480 | 95604-H34480 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34481 | 95604-H34481 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34482 | 95604-H34482 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34483 | 95604-H34483 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34484 | 95604-H34484 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34485 | 95604-H34485 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34486 | 95604-H34486 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34487 | 95604-H34487 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34488 | 95604-H34488 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34489 | 95604-H34489 | \$ 174.00 | 6% | \$164.79 |
| PWP NBD AHR H34490 | 95604-H34490 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34491 | 95604-H34491 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34492 | 95604-H34492 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34493 | 95604-H34493 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34494 | 95604-H34494 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34495 | 95604-H34495 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34496 | 95604-H34496 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34497 | 95604-H34497 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34498 | 95604-H34498 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34499 | 95604-H34499 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34500 | 95604-H34500 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34501 | 95604-H34501 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34502 | 95604-H34502 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34503 | 95604-H34503 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34504 | 95604-H34504 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34505 | 95604-H34505 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34506 | 95604-H34506 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34507 | 95604-H34507 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34508 | 95604-H34508 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34509 | 95604-H34509 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34510 | 95604-H34510 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34511 | 95604-H34511 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34512 | 95604-H34512 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34513 | 95604-H34513 | \$ 24.00 | 6% | \$22.73 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34514 | 95604-H34514 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34515 | 95604-H34515 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34516 | 95604-H34516 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34517 | 95604-H34517 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34518 | 95604-H34518 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34519 | 95604-H34519 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34520 | 95604-H34520 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34521 | 95604-H34521 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34522 | 95604-H34522 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34523 | 95604-H34523 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34524 | 95604-H34524 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34525 | 95604-H34525 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34526 | 95604-H34526 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34527 | 95604-H34527 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34528 | 95604-H34528 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34529 | 95604-H34529 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34530 | 95604-H34530 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34531 | 95604-H34531 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34532 | 95604-H34532 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34533 | 95604-H34533 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34534 | 95604-H34534 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34535 | 95604-H34535 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34536 | 95604-H34536 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34537 | 95604-H34537 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34538 | 95604-H34538 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34539 | 95604-H34539 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34540 | 95604-H34540 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34541 | 95604-H34541 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34542 | 95604-H34542 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34543 | 95604-H34543 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34544 | 95604-H34544 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34545 | 95604-H34545 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34546 | 95604-H34546 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34547 | 95604-H34547 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34548 | 95604-H34548 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34549 | 95604-H34549 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34550 | 95604-H34550 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34551 | 95604-H34551 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34552 | 95604-H34552 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34553 | 95604-H34553 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34554 | 95604-H34554 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34555 | 95604-H34555 | \$ 24.00 | 6% | \$22.73 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34556 | 95604-H34556 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34557 | 95604-H34557 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34558 | 95604-H34558 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34559 | 95604-H34559 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34560 | 95604-H34560 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34561 | 95604-H34561 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34562 | 95604-H34562 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34563 | 95604-H34563 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34564 | 95604-H34564 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34565 | 95604-H34565 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34566 | 95604-H34566 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34567 | 95604-H34567 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34568 | 95604-H34568 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34569 | 95604-H34569 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34570 | 95604-H34570 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34571 | 95604-H34571 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34572 | 95604-H34572 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34573 | 95604-H34573 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34574 | 95604-H34574 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34575 | 95604-H34575 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34576 | 95604-H34576 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34577 | 95604-H34577 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34578 | 95604-H34578 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34579 | 95604-H34579 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34580 | 95604-H34580 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34581 | 95604-H34581 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34582 | 95604-H34582 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34583 | 95604-H34583 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34584 | 95604-H34584 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34585 | 95604-H34585 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34586 | 95604-H34586 | \$ 24.00 | 6% | \$22.73 |
| PWP NBD AHR H34587 | 95604-H34587 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34588 | 95604-H34588 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34589 | 95604-H34589 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34590 | 95604-H34590 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34591 | 95604-H34591 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34592 | 95604-H34592 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34593 | 95604-H34593 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34594 | 95604-H34594 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34595 | 95604-H34595 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34596 | 95604-H34596 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34597 | 95604-H34597 | \$ 61.00 | 6% | \$57.77 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34598 | 95604-H34598 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34599 | 95604-H34599 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34600 | 95604-H34600 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34601 | 95604-H34601 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34602 | 95604-H34602 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34603 | 95604-H34603 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34604 | 95604-H34604 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34605 | 95604-H34605 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34606 | 95604-H34606 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34607 | 95604-H34607 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34608 | 95604-H34608 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34609 | 95604-H34609 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34610 | 95604-H34610 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34611 | 95604-H34611 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34612 | 95604-H34612 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34613 | 95604-H34613 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34614 | 95604-H34614 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34615 | 95604-H34615 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34616 | 95604-H34616 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34617 | 95604-H34617 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34618 | 95604-H34618 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34619 | 95604-H34619 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34620 | 95604-H34620 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34621 | 95604-H34621 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34622 | 95604-H34622 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34623 | 95604-H34623 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34624 | 95604-H34624 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34625 | 95604-H34625 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34626 | 95604-H34626 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34627 | 95604-H34627 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34628 | 95604-H34628 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34629 | 95604-H34629 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34630 | 95604-H34630 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34631 | 95604-H34631 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H34632 | 95604-H34632 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34633 | 95604-H34633 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34634 | 95604-H34634 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34635 | 95604-H34635 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34636 | 95604-H34636 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34637 | 95604-H34637 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34638 | 95604-H34638 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34639 | 95604-H34639 | \$ 64.00 | 6% | \$60.61 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34640 | 95604-H34640 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34641 | 95604-H34641 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34642 | 95604-H34642 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34643 | 95604-H34643 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34644 | 95604-H34644 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34645 | 95604-H34645 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34646 | 95604-H34646 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34647 | 95604-H34647 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34648 | 95604-H34648 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34649 | 95604-H34649 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34650 | 95604-H34650 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34651 | 95604-H34651 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34652 | 95604-H34652 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34653 | 95604-H34653 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34654 | 95604-H34654 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34655 | 95604-H34655 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34656 | 95604-H34656 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34657 | 95604-H34657 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34658 | 95604-H34658 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34659 | 95604-H34659 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34660 | 95604-H34660 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34661 | 95604-H34661 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34662 | 95604-H34662 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34663 | 95604-H34663 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34664 | 95604-H34664 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34665 | 95604-H34665 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34666 | 95604-H34666 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34667 | 95604-H34667 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34668 | 95604-H34668 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34669 | 95604-H34669 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34670 | 95604-H34670 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34671 | 95604-H34671 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34672 | 95604-H34672 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34673 | 95604-H34673 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34674 | 95604-H34674 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34675 | 95604-H34675 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34676 | 95604-H34676 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34677 | 95604-H34677 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34678 | 95604-H34678 | \$ 64.00 | 6% | \$60.61 |
| PWP NBD AHR H34679 | 95604-H34679 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34680 | 95604-H34680 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34681 | 95604-H34681 | \$ 74.00 | 6% | \$70.08 |

| | | | | |
|--------------------|--------------|----------|----|---------|
| PWP NBD AHR H34682 | 95604-H34682 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34683 | 95604-H34683 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34684 | 95604-H34684 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34685 | 95604-H34685 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34686 | 95604-H34686 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34687 | 95604-H34687 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34688 | 95604-H34688 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34689 | 95604-H34689 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34690 | 95604-H34690 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34691 | 95604-H34691 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34692 | 95604-H34692 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34693 | 95604-H34693 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34694 | 95604-H34694 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34695 | 95604-H34695 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34696 | 95604-H34696 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34697 | 95604-H34697 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34698 | 95604-H34698 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34699 | 95604-H34699 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34700 | 95604-H34700 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34701 | 95604-H34701 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34702 | 95604-H34702 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34703 | 95604-H34703 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34704 | 95604-H34704 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34705 | 95604-H34705 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34706 | 95604-H34706 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34707 | 95604-H34707 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34708 | 95604-H34708 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34709 | 95604-H34709 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34710 | 95604-H34710 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34711 | 95604-H34711 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34712 | 95604-H34712 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34713 | 95604-H34713 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34714 | 95604-H34714 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34715 | 95604-H34715 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34716 | 95604-H34716 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34717 | 95604-H34717 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34718 | 95604-H34718 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34719 | 95604-H34719 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34720 | 95604-H34720 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34721 | 95604-H34721 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34722 | 95604-H34722 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34723 | 95604-H34723 | \$ 74.00 | 6% | \$70.08 |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PWP NBD AHR H34724 | 95604-H34724 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34725 | 95604-H34725 | \$ 74.00 | 6% | \$70.08 |
| PWP NBD AHR H34726 | 95604-H34726 | \$ 1,440.00 | 6% | \$1,363.75 |
| PWP NBD AHR H34727 | 95604-H34727 | \$ 1,440.00 | 6% | \$1,363.75 |
| PWP NBD AHR H34728 | 95604-H34728 | \$ 1,440.00 | 6% | \$1,363.75 |
| PWP NBD AHR H34729 | 95604-H34729 | \$ 1,440.00 | 6% | \$1,363.75 |
| PWP NBD AHR H34730 | 95604-H34730 | \$ 1,541.00 | 6% | \$1,459.40 |
| PWP NBD AHR H34731 | 95604-H34731 | \$ 1,541.00 | 6% | \$1,459.40 |
| PWP NBD AHR H34732 | 95604-H34732 | \$ 1,541.00 | 6% | \$1,459.40 |
| PWP NBD AHR H34733 | 95604-H34733 | \$ 1,541.00 | 6% | \$1,459.40 |
| PWP NBD AHR H34734 | 95604-H34734 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34735 | 95604-H34735 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34736 | 95604-H34736 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H34737 | 95604-H34737 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H34738 | 95604-H34738 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34739 | 95604-H34739 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34740 | 95604-H34740 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34741 | 95604-H34741 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H34742 | 95604-H34742 | \$ 224.00 | 6% | \$212.14 |
| PWP NBD AHR H34743 | 95604-H34743 | \$ 224.00 | 6% | \$212.14 |
| PWP NBD AHR H34744 | 95604-H34744 | \$ 282.00 | 6% | \$267.07 |
| PWP NBD AHR H34745 | 95604-H34745 | \$ 282.00 | 6% | \$267.07 |
| PWP NBD AHR H34746 | 95604-H34746 | \$ 320.00 | 6% | \$303.06 |
| PWP NBD AHR H34747 | 95604-H34747 | \$ 320.00 | 6% | \$303.06 |
| PWP NBD AHR H34748 | 95604-H34748 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34749 | 95604-H34749 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34750 | 95604-H34750 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34751 | 95604-H34751 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34752 | 95604-H34752 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34753 | 95604-H34753 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34754 | 95604-H34754 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34755 | 95604-H34755 | \$ 538.00 | 6% | \$509.51 |
| PWP NBD AHR H34756 | 95604-H34756 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H34757 | 95604-H34757 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H34758 | 95604-H34758 | \$ 282.00 | 6% | \$267.07 |
| PWP NBD AHR H34759 | 95604-H34759 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H34760 | 95604-H34760 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H34761 | 95604-H34761 | \$ 282.00 | 6% | \$267.07 |
| PWP NBD AHR H34839 | 95604-H34839 | \$ 195.00 | 6% | \$184.67 |
| PWP NBD AHR H34840 | 95604-H34840 | \$ 195.00 | 6% | \$184.67 |
| PWP NBD AHR H34841 | 95604-H34841 | \$ 195.00 | 6% | \$184.67 |
| PWP NBD AHR H34842 | 95604-H34842 | \$ 195.00 | 6% | \$184.67 |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PWP NBD AHR H34843 | 95604-H34843 | \$ 195.00 | 6% | \$184.67 |
| PWP NBD AHR H34844 | 95604-H34844 | \$ 195.00 | 6% | \$184.67 |
| PWP NBD AHR H34845 | 95604-H34845 | \$ 195.00 | 6% | \$184.67 |
| PWP NBD AHR H34846 | 95604-H34846 | \$ 195.00 | 6% | \$184.67 |
| PWP NBD AHR H34993 | 95604-H34993 | \$ 7,545.00 | 6% | \$7,145.49 |
| PWP NBD AHR H34994 | 95604-H34994 | \$ 7,545.00 | 6% | \$7,145.49 |
| PWP NBD AHR H34996 | 95604-H34996 | \$ 7,545.00 | 6% | \$7,145.49 |
| PWP NBD AHR H34997 | 95604-H34997 | \$ 7,545.00 | 6% | \$7,145.49 |
| PWP NBD AHR H35005 | 95604-H35005 | \$ 5,511.00 | 6% | \$5,219.19 |
| PWP NBD AHR H35006 | 95604-H35006 | \$ 5,511.00 | 6% | \$5,219.19 |
| PWP NBD AHR H35012 | 95604-H35012 | \$ 3,306.00 | 6% | \$3,130.95 |
| PWP NBD AHR H35070 | 95604-H35070 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35071 | 95604-H35071 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35072 | 95604-H35072 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35073 | 95604-H35073 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35074 | 95604-H35074 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35075 | 95604-H35075 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35076 | 95604-H35076 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35077 | 95604-H35077 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35078 | 95604-H35078 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35079 | 95604-H35079 | \$ 42.00 | 6% | \$39.78 |
| PWP NBD AHR H35080 | 95604-H35080 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H35081 | 95604-H35081 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H35082 | 95604-H35082 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H35083 | 95604-H35083 | \$ 61.00 | 6% | \$57.77 |
| PWP NBD AHR H35270 | 95604-H35270 | \$ 191.00 | 6% | \$180.89 |
| PWP NBD AHR H35271 | 95604-H35271 | \$ 145.00 | 6% | \$137.32 |
| PWP NBD AHR H35273 | 95604-H35273 | \$ 188.00 | 6% | \$178.05 |
| PWP NBD AHR H35274 | 95604-H35274 | \$ 322.00 | 6% | \$304.95 |
| PWP NBD AHR H35275 | 95604-H35275 | \$ 209.00 | 6% | \$197.93 |
| PWP NBD AHR H35276 | 95604-H35276 | \$ 1,387.00 | 6% | \$1,313.56 |
| PWP NBD AHR H35277 | 95604-H35277 | \$ 1,831.00 | 6% | \$1,734.05 |
| PWP NBD AHR H35278 | 95604-H35278 | \$ 1,621.00 | 6% | \$1,535.17 |
| PWP NBD AHR H35279 | 95604-H35279 | \$ 1,584.00 | 6% | \$1,500.13 |
| PWP NBD AHR H35280 | 95604-H35280 | \$ 1,831.00 | 6% | \$1,734.05 |
| PWP NBD AHR H35281 | 95604-H35281 | \$ 1,068.00 | 6% | \$1,011.45 |
| PWP NBD AHR H35282 | 95604-H35282 | \$ 1,068.00 | 6% | \$1,011.45 |
| PWP NBD AHR H35283 | 95604-H35283 | \$ 1,068.00 | 6% | \$1,011.45 |
| PWP NBD AHR H35284 | 95604-H35284 | \$ 1,068.00 | 6% | \$1,011.45 |
| PWP NBD AHR H35285 | 95604-H35285 | \$ 1,068.00 | 6% | \$1,011.45 |
| PWP NBD AHR H35286 | 95604-H35286 | \$ 1,068.00 | 6% | \$1,011.45 |
| PWP NBD AHR H35287 | 95604-H35287 | \$ 1,068.00 | 6% | \$1,011.45 |

| | | | | |
|--------------------|--------------|-------------|----|-------------------|
| PWP NBD AHR H35288 | 95604-H35288 | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| PWP NBD AHR H35289 | 95604-H35289 | \$ 2,671.00 | 6% | <i>\$2,529.57</i> |
| PWP NBD AHR H35291 | 95604-H35291 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| PWP NBD AHR H35292 | 95604-H35292 | \$ 1,621.00 | 6% | <i>\$1,535.17</i> |
| PWP NBD AHR H35293 | 95604-H35293 | \$ 1,584.00 | 6% | <i>\$1,500.13</i> |
| PWP NBD AHR H35295 | 95604-H35295 | \$ 170.00 | 6% | <i>\$161.00</i> |
| PWP NBD AHR H35296 | 95604-H35296 | \$ 5,309.00 | 6% | <i>\$5,027.89</i> |
| PWP NBD AHR H35297 | 95604-H35297 | \$ 5,309.00 | 6% | <i>\$5,027.89</i> |
| PWP NBD AHR H35298 | 95604-H35298 | \$ 8,531.00 | 6% | <i>\$8,079.28</i> |
| PWP NBD AHR H35299 | 95604-H35299 | \$ 8,531.00 | 6% | <i>\$8,079.28</i> |
| PWP NBD AHR H35302 | 95604-H35302 | \$ 2,059.00 | 6% | <i>\$1,949.98</i> |
| PWP NBD AHR H35303 | 95604-H35303 | \$ 2,059.00 | 6% | <i>\$1,949.98</i> |
| PWP NBD AHR H35304 | 95604-H35304 | \$ 2,059.00 | 6% | <i>\$1,949.98</i> |
| PWP NBD AHR H35305 | 95604-H35305 | \$ 2,157.00 | 6% | <i>\$2,042.79</i> |
| PWP NBD AHR H35306 | 95604-H35306 | \$ 2,157.00 | 6% | <i>\$2,042.79</i> |
| PWP NBD AHR H35307 | 95604-H35307 | \$ 2,157.00 | 6% | <i>\$2,042.79</i> |
| PWP NBD AHR H35309 | 95604-H35309 | \$ 2,554.00 | 6% | <i>\$2,418.77</i> |
| PWP NBD AHR H35310 | 95604-H35310 | \$ 2,554.00 | 6% | <i>\$2,418.77</i> |
| PWP NBD AHR H35311 | 95604-H35311 | \$ 2,554.00 | 6% | <i>\$2,418.77</i> |
| PWP NBD AHR H35312 | 95604-H35312 | \$ 2,113.00 | 6% | <i>\$2,001.12</i> |
| PWP NBD AHR H35313 | 95604-H35313 | \$ 2,113.00 | 6% | <i>\$2,001.12</i> |
| PWP NBD AHR H35314 | 95604-H35314 | \$ 2,113.00 | 6% | <i>\$2,001.12</i> |
| PWP NBD AHR H35315 | 95604-H35315 | \$ 915.00 | 6% | <i>\$866.55</i> |
| PWP NBD AHR H35318 | 95604-H35318 | \$ 431.00 | 6% | <i>\$408.18</i> |
| PWP NBD AHR H35319 | 95604-H35319 | \$ 582.00 | 6% | <i>\$551.18</i> |
| PWP NBD AHR H35320 | 95604-H35320 | \$ 604.00 | 6% | <i>\$572.02</i> |
| PWP NBD AHR H35321 | 95604-H35321 | \$ 769.00 | 6% | <i>\$728.28</i> |
| PWP NBD AHR H35322 | 95604-H35322 | \$ 934.00 | 6% | <i>\$884.54</i> |
| PWP NBD AHR H35323 | 95604-H35323 | \$ 915.00 | 6% | <i>\$866.55</i> |
| PWP NBD AHR H35328 | 95604-H35328 | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR H35330 | 95604-H35330 | \$ 57.00 | 6% | <i>\$53.98</i> |
| PWP NBD AHR H35340 | 95604-H35340 | \$ 2,223.00 | 6% | <i>\$2,105.29</i> |
| PWP NBD AHR H35341 | 95604-H35341 | \$ 2,223.00 | 6% | <i>\$2,105.29</i> |
| PWP NBD AHR H35342 | 95604-H35342 | \$ 1,966.00 | 6% | <i>\$1,861.90</i> |
| PWP NBD AHR H35343 | 95604-H35343 | \$ 2,223.00 | 6% | <i>\$2,105.29</i> |
| PWP NBD AHR H35344 | 95604-H35344 | \$ 2,319.00 | 6% | <i>\$2,196.21</i> |
| PWP NBD AHR H35345 | 95604-H35345 | \$ 2,319.00 | 6% | <i>\$2,196.21</i> |
| PWP NBD AHR H35346 | 95604-H35346 | \$ 2,038.00 | 6% | <i>\$1,930.09</i> |
| PWP NBD AHR H35347 | 95604-H35347 | \$ 2,319.00 | 6% | <i>\$2,196.21</i> |
| PWP NBD AHR H35349 | 95604-H35349 | \$ 2,562.00 | 6% | <i>\$2,426.34</i> |
| PWP NBD AHR H35350 | 95604-H35350 | \$ 2,562.00 | 6% | <i>\$2,426.34</i> |
| PWP NBD AHR H35351 | 95604-H35351 | \$ 2,231.00 | 6% | <i>\$2,112.87</i> |

| | | | | |
|--------------------|--------------|-------------|----|------------|
| PWP NBD AHR H35352 | 95604-H35352 | \$ 2,562.00 | 6% | \$2,426.34 |
| PWP NBD AHR H35359 | 95604-H35359 | \$ 769.00 | 6% | \$728.28 |
| PWP NBD AHR H35360 | 95604-H35360 | \$ 934.00 | 6% | \$884.54 |
| PWP NBD AHR H35361 | 95604-H35361 | \$ 915.00 | 6% | \$866.55 |
| PWP NBD AHR H35362 | 95604-H35362 | \$ 431.00 | 6% | \$408.18 |
| PWP NBD AHR H35366 | 95604-H35366 | \$ 1,118.00 | 6% | \$1,058.80 |
| PWP NBD AHR H35367 | 95604-H35367 | \$ 1,299.00 | 6% | \$1,230.22 |
| PWP NBD AHR H35368 | 95604-H35368 | \$ 1,988.00 | 6% | \$1,882.74 |
| PWP NBD AHR H35369 | 95604-H35369 | \$ 649.00 | 6% | \$614.64 |
| PWP NBD AHR H35370 | 95604-H35370 | \$ 910.00 | 6% | \$861.82 |
| PWP NBD AHR H35375 | 95604-H35375 | \$ 547.00 | 6% | \$518.04 |
| PWP NBD AHR H35376 | 95604-H35376 | \$ 820.00 | 6% | \$776.58 |
| PWP NBD AHR H35377 | 95604-H35377 | \$ 344.00 | 6% | \$325.79 |
| PWP NBD AHR H35378 | 95604-H35378 | \$ 547.00 | 6% | \$518.04 |
| PWP NBD AHR H35379 | 95604-H35379 | \$ 344.00 | 6% | \$325.79 |
| PWP NBD AHR H35380 | 95604-H35380 | \$ 616.00 | 6% | \$583.38 |
| PWP NBD AHR H35381 | 95604-H35381 | \$ 751.00 | 6% | \$711.23 |
| PWP NBD AHR H35384 | 95604-H35384 | \$ 249.00 | 6% | \$235.82 |
| PWP NBD AHR H35385 | 95604-H35385 | \$ 331.00 | 6% | \$313.47 |
| PWP NBD AHR H35386 | 95604-H35386 | \$ 547.00 | 6% | \$518.04 |
| PWP NBD AHR H35387 | 95604-H35387 | \$ 511.00 | 6% | \$483.94 |
| PWP NBD AHR H35388 | 95604-H35388 | \$ 375.00 | 6% | \$355.14 |
| PWP NBD AHR H35389 | 95604-H35389 | \$ 214.00 | 6% | \$202.67 |
| PWP NBD AHR H35390 | 95604-H35390 | \$ 185.00 | 6% | \$175.20 |
| PWP NBD AHR H35391 | 95604-H35391 | \$ 404.00 | 6% | \$382.61 |
| PWP NBD AHR H35392 | 95604-H35392 | \$ 616.00 | 6% | \$583.38 |
| PWP NBD AHR H35393 | 95604-H35393 | \$ 820.00 | 6% | \$776.58 |
| PWP NBD AHR H35394 | 95604-H35394 | \$ 147.00 | 6% | \$139.22 |
| PWP NBD AHR H35395 | 95604-H35395 | \$ 128.00 | 6% | \$121.22 |
| PWP NBD AHR H35396 | 95604-H35396 | \$ 147.00 | 6% | \$139.22 |
| PWP NBD AHR H35397 | 95604-H35397 | \$ 128.00 | 6% | \$121.22 |
| PWP NBD AHR H35398 | 95604-H35398 | \$ 382.00 | 6% | \$361.77 |
| PWP NBD AHR H35399 | 95604-H35399 | \$ 464.00 | 6% | \$439.43 |
| PWP NBD AHR H35400 | 95604-H35400 | \$ 515.00 | 6% | \$487.73 |
| PWP NBD AHR H35401 | 95604-H35401 | \$ 274.00 | 6% | \$259.49 |
| PWP NBD AHR H35415 | 95604-H35415 | \$ 186.00 | 6% | \$176.15 |
| PWP NBD AHR H35416 | 95604-H35416 | \$ 186.00 | 6% | \$176.15 |
| PWP NBD AHR H35426 | 95604-H35426 | \$ 214.00 | 6% | \$202.67 |
| PWP NBD AHR H35427 | 95604-H35427 | \$ 511.00 | 6% | \$483.94 |
| PWP NBD AHR H35428 | 95604-H35428 | \$ 185.00 | 6% | \$175.20 |
| PWP NBD AHR H35429 | 95604-H35429 | \$ 404.00 | 6% | \$382.61 |
| PWP NBD AHR H35430 | 95604-H35430 | \$ 215.00 | 6% | \$203.62 |

| | | | | |
|---------------------------|---------------------|-------------|----|------------|
| PWP NBD AHR H35431 | 95604-H35431 | \$ 215.00 | 6% | \$203.62 |
| PWP NBD AHR H35432 | 95604-H35432 | \$ 224.00 | 6% | \$212.14 |
| PWP NBD AHR H35433 | 95604-H35433 | \$ 275.00 | 6% | \$260.44 |
| PWP NBD AHR H35434 | 95604-H35434 | \$ 313.00 | 6% | \$296.43 |
| PWP NBD AHR H35435 | 95604-H35435 | \$ 313.00 | 6% | \$296.43 |
| PWP NBD AHR H35436 | 95604-H35436 | \$ 522.00 | 6% | \$494.36 |
| PWP NBD AHR H35437 | 95604-H35437 | \$ 522.00 | 6% | \$494.36 |
| PWP NBD AHR H35438 | 95604-H35438 | \$ 522.00 | 6% | \$494.36 |
| PWP NBD AHR H35439 | 95604-H35439 | \$ 522.00 | 6% | \$494.36 |
| PWP NBD AHR H35440 | 95604-H35440 | \$ 275.00 | 6% | \$260.44 |
| PWP NBD AHR H35441 | 95604-H35441 | \$ 275.00 | 6% | \$260.44 |
| PWP NBD AHR H35442 | 95604-H35442 | \$ 275.00 | 6% | \$260.44 |
| PWP NBD AHR H35443 | 95604-H35443 | \$ 1,440.00 | 6% | \$1,363.75 |
| PWP NBD AHR H35444 | 95604-H35444 | \$ 1,541.00 | 6% | \$1,459.40 |
| PWP NBD AHR H35445 | 95604-H35445 | \$ 1,387.00 | 6% | \$1,313.56 |
| PWP NBD AHR H35446 | 95604-H35446 | \$ 1,498.00 | 6% | \$1,418.68 |
| PWP NBD AHR H35447 | 95604-H35447 | \$ 1,735.00 | 6% | \$1,643.13 |
| PWP NBD AHR H35448 | 95604-H35448 | \$ 1,662.00 | 6% | \$1,574.00 |
| PWP NBD AHR H35449 | 95604-H35449 | \$ 1,621.00 | 6% | \$1,535.17 |
| PWP NBD AHR H35450 | 95604-H35450 | \$ 1,502.00 | 6% | \$1,422.47 |
| PWP NBD AHR H35451 | 95604-H35451 | \$ 1,936.00 | 6% | \$1,833.49 |
| PWP NBD AHR H35452 | 95604-H35452 | \$ 1,936.00 | 6% | \$1,833.49 |
| PWP NBD AHR H35453 | 95604-H35453 | \$ 1,541.00 | 6% | \$1,459.40 |
| PWP NBD AHR H35454 | 95604-H35454 | \$ 1,440.00 | 6% | \$1,363.75 |
| PWP NBD AHR H35455 | 95604-H35455 | \$ 604.00 | 6% | \$572.02 |
| PWP NBD AHR H35456 | 95604-H35456 | \$ 758.00 | 6% | \$717.86 |
| PWP NBD AHR H35457 | 95604-H35457 | \$ 680.00 | 6% | \$643.99 |
| PWP NBD AHR H35458 | 95604-H35458 | \$ 744.00 | 6% | \$704.61 |
| PWP NBD AHR H35471 | 95604-H35471 | \$ 604.00 | 6% | \$572.02 |
| PWP NBD AHR H35600 | 95604-H35600 | \$ 188.00 | 6% | \$178.05 |
| PWP NBD AHR H35601 | 95604-H35601 | \$ 188.00 | 6% | \$178.05 |
| PWP NBD AHR H35602 | 95604-H35602 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H35603 | 95604-H35603 | \$ 222.00 | 6% | \$210.25 |
| PWP NBD AHR H35604 | 95604-H35604 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H35605 | 95604-H35605 | \$ 284.00 | 6% | \$268.96 |
| PWP NBD AHR H35606 | 95604-H35606 | \$ 322.00 | 6% | \$304.95 |
| PWP NBD AHR H35607 | 95604-H35607 | \$ 320.00 | 6% | \$303.06 |
| PWP NBD AHR ISW-24W-4X | 95604-ISW-24W-4X | \$ 636.00 | 6% | \$602.32 |
| PWP NBD AHR ISW-4W-4WS-4X | 95604-ISW-4W-4WS-4X | \$ 403.00 | 6% | \$381.66 |

| | | | | |
|-------------------------------|-------------------------|--------------|----|--------------------|
| PWP NBD AHR BD MSM128 | 95604-MSM128 | \$ 2,378.00 | 6% | <i>\$2,252.08</i> |
| PWP NBD AHR BD MSM48C | 95604-MSM48C | \$ 1,444.00 | 6% | <i>\$1,367.54</i> |
| PWP NBD AHR | 95604-R100-8T | \$ 60.00 | 6% | <i>\$56.82</i> |
| PWP NBD AHR SLX9150-48XT-DC-F | 95604-SLX9150-48XT-DC-F | \$ 2,023.00 | 6% | <i>\$1,915.88</i> |
| PWP NBD AHR SLX9150-48XT-DC-R | 95604-SLX9150-48XT-DC-R | \$ 2,209.00 | 6% | <i>\$2,092.03</i> |
| PWP NBD AHR SLX9150-48Y-DC-F | 95604-SLX9150-48Y-DC-F | \$ 1,938.00 | 6% | <i>\$1,835.38</i> |
| PWP NBD AHR SLX9150-48Y-DC-R | 95604-SLX9150-48Y-DC-R | \$ 2,117.00 | 6% | <i>\$2,004.90</i> |
| PWP NBD AHR SLX9740-40C | 95604-SLX9740-40C | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PWP NBD AHR SLX9740-40C-AC-F | 95604-SLX9740-40C-AC-F | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PWP NBD AHR SLX9740-40C-AC-R | 95604-SLX9740-40C-AC-R | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PWP NBD AHR SLX9740-40C-DC-F | 95604-SLX9740-40C-DC-F | \$ 8,715.00 | 6% | <i>\$8,253.54</i> |
| PWP NBD AHR SLX9740-80C | 95604-SLX9740-80C | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PWP NBD AHR SLX9740-80C-AC-F | 95604-SLX9740-80C-AC-F | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PWP NBD AHR SLX9740-80C-AC-R | 95604-SLX9740-80C-AC-R | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PWP NBD AHR SLX9740-80C-DC-F | 95604-SLX9740-80C-DC-F | \$ 16,389.00 | 6% | <i>\$15,521.20</i> |
| PWP NBD AHR V300-8P-2X | 95604-V300-8P-2X | \$ 101.00 | 6% | <i>\$95.65</i> |

| | | | | |
|-----------------------------------|-----------------------------|-----------|----|-----------------|
| PWP NBD AHR V300-8T-2X | 95604-V300-8T-2X | \$ 70.00 | 6% | <i>\$66.29</i> |
| PWP NBD AHR V300HT-8P-2X | 95604-V300HT-8P-2X | \$ 231.00 | 6% | <i>\$218.77</i> |
| PWP NBD AHR V300HT-8T-2X | 95604-V300HT-8T-2X | \$ 137.00 | 6% | <i>\$129.75</i> |
| PWP NBD AHR Summit VIM-SS | 95604-VIM-SS | \$ 121.00 | 6% | <i>\$114.59</i> |
| PWP NBD AHR Summit VIM-SSV80 | 95604-VIM-SSV80 | \$ 227.00 | 6% | <i>\$214.98</i> |
| PWP NBD AHR Summit VIM2-SS | 95604-VIM2-SS | \$ 142.00 | 6% | <i>\$134.48</i> |
| PWP NBD AHR Summit VIM2-SS128 | 95604-VIM2-SS128 | \$ 489.00 | 6% | <i>\$463.11</i> |
| PWP NBD AHR Summit VIM2-V80 | 95604-VIM2-V80 | \$ 523.00 | 6% | <i>\$495.31</i> |
| PWP NBD AHR Summit VIM210G4X | 95604-VIM210G4X | \$ 907.00 | 6% | <i>\$858.97</i> |
| PWP NBD AHR VIM5-2Q | 95604-VIM5-2Q | \$ 145.00 | 6% | <i>\$137.32</i> |
| PWP NBD AHR VIM5-2Y | 95604-VIM5-2Y | \$ 171.00 | 6% | <i>\$161.95</i> |
| PWP NBD AHR VIM5-4X | 95604-VIM5-4X | \$ 78.00 | 6% | <i>\$73.87</i> |
| PWP NBD AHR VIM5-4XE | 95604-VIM5-4XE | \$ 140.00 | 6% | <i>\$132.59</i> |
| PWP NBD AHR VIM5-4Y | 95604-VIM5-4Y | \$ 218.00 | 6% | <i>\$206.46</i> |
| PWP NBD AHR VIM5-4YE | 95604-VIM5-4YE | \$ 282.00 | 6% | <i>\$267.07</i> |
| PWP NBD AHR VSP4900-12MXU-12XE | 95604-VSP4900-12MXU-12XE | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR VSP4900-12MXU-12XE-B1 | 95604-VSP4900-12MXU-12XE-B1 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR VSP4900-24S | 95604-VSP4900-24S | \$ 431.00 | 6% | <i>\$408.18</i> |

| | | | | |
|-------------------------------|-----------------------|-------------|----|-------------------|
| PWP NBD AHR VSP4900-24S-B3 | 95604-VSP4900-24S-B3 | \$ 431.00 | 6% | <i>\$408.18</i> |
| PWP NBD AHR VSP4900-24XE | 95604-VSP4900-24XE | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR VSP4900-24XE-B3 | 95604-VSP4900-24XE-B3 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR X435-24P-4S | 95604-X435-24P-4S | \$ 180.00 | 6% | <i>\$170.47</i> |
| PWP NBD AHR X435-24T-4S | 95604-X435-24T-4S | \$ 99.00 | 6% | <i>\$93.76</i> |
| PWP NBD AHR X435-8P-2T-W | 95604-X435-8P-2T-W | \$ 99.00 | 6% | <i>\$93.76</i> |
| PWP NBD AHR X435-8P-4S | 95604-X435-8P-4S | \$ 90.00 | 6% | <i>\$85.23</i> |
| PWP NBD AHR X435-8T-4S | 95604-X435-8T-4S | \$ 72.00 | 6% | <i>\$68.19</i> |
| PWP NBD AHR Summit X460-24P | 95604-X460-24P | \$ 851.00 | 6% | <i>\$805.94</i> |
| PWP NBD AHR Summit X460-24T | 95604-X460-24T | \$ 595.00 | 6% | <i>\$563.49</i> |
| PWP NBD AHR Summit X460-24TDC | 95604-X460-24TDC | \$ 875.00 | 6% | <i>\$828.67</i> |
| PWP NBD AHR Summit X460-24X | 95604-X460-24X | \$ 1,102.00 | 6% | <i>\$1,043.65</i> |
| PWP NBD AHR Summit X460-24XDC | 95604-X460-24XDC | \$ 1,234.00 | 6% | <i>\$1,168.66</i> |
| PWP NBD AHR Summit X460-48P | 95604-X460-48P | \$ 1,102.00 | 6% | <i>\$1,043.65</i> |
| PWP NBD AHR Summit X460-48T | 95604-X460-48T | \$ 946.00 | 6% | <i>\$895.91</i> |
| PWP NBD AHR Summit X460-48TDC | 95604-X460-48TDC | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| PWP NBD AHR Summit X460-48X | 95604-X460-48X | \$ 1,467.00 | 6% | <i>\$1,389.32</i> |
| PWP NBD AHR Summit X460-48XDC | 95604-X460-48XDC | \$ 1,432.00 | 6% | <i>\$1,356.18</i> |
| PWP NBD AHR X465-24MU | 95604-X465-24MU | \$ 934.00 | 6% | <i>\$884.54</i> |

| | | | | |
|------------------------------|-----------------------|-------------|----|-------------------|
| PWP NBD AHR X465-24S | 95604-X465-24S | \$ 431.00 | 6% | <i>\$408.18</i> |
| PWP NBD AHR X465-24S-B3 | 95604-X465-24S-B3 | \$ 431.00 | 6% | <i>\$408.18</i> |
| PWP NBD AHR X465-24W | 95604-X465-24W | \$ 431.00 | 6% | <i>\$408.18</i> |
| PWP NBD AHR X465-24XE | 95604-X465-24XE | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR X465-24XE-B3 | 95604-X465-24XE-B3 | \$ 807.00 | 6% | <i>\$764.27</i> |
| PWP NBD AHR X465-48P | 95604-X465-48P | \$ 604.00 | 6% | <i>\$572.02</i> |
| PWP NBD AHR X465-48T | 95604-X465-48T | \$ 582.00 | 6% | <i>\$551.18</i> |
| PWP NBD AHR X465-48W | 95604-X465-48W | \$ 769.00 | 6% | <i>\$728.28</i> |
| PWP NBD AHR X465i-48W | 95604-X465i-48W | \$ 915.00 | 6% | <i>\$866.55</i> |
| PWP NBD AHR X465i-48W-B1-S1 | 95604-X465i-48W-B1-S1 | \$ 915.00 | 6% | <i>\$866.55</i> |
| PWP NBD AHR X465i-48W-B2-S1 | 95604-X465i-48W-B2-S1 | \$ 915.00 | 6% | <i>\$866.55</i> |
| PWP NBD AHR Summit X480-24X | 95604-X480-24X | \$ 1,359.00 | 6% | <i>\$1,287.04</i> |
| PWP NBD AHR Summit X480-48T | 95604-X480-48T | \$ 1,359.00 | 6% | <i>\$1,287.04</i> |
| PWP NBD AHR Summit X480-48X | 95604-X480-48X | \$ 1,808.00 | 6% | <i>\$1,712.27</i> |
| PWP NBD AHR X695-48Y-8C | 95604-X695-48Y-8C | \$ 2,112.00 | 6% | <i>\$2,000.17</i> |
| PWP NBD AHR XA1440 | 95604-XA1440 | \$ 220.00 | 6% | <i>\$208.35</i> |
| PWP NBD AHR XA1480 | 95604-XA1480 | \$ 295.00 | 6% | <i>\$279.38</i> |
| PWP NBD AHR Summit XGM3-2SF | 95604-XGM3-2SF | \$ 227.00 | 6% | <i>\$214.98</i> |
| PWP NBD AHR XR600 | 95604-XR600 | \$ 63.00 | 6% | <i>\$59.66</i> |
| PWP NBD AHR -ZR-XFP | 95604-ZR-XFP | \$ 1,371.00 | 6% | <i>\$1,298.41</i> |
| PWP Managed Cloud WiFi 30912 | 95624-30912 | \$ 128.00 | 6% | <i>\$121.22</i> |

| | | | | |
|---------------------------------|-------------|-----------|----|-----------------|
| PWP Managed Cloud WiFi 30913 | 95624-30913 | \$ 131.00 | 6% | <i>\$124.06</i> |
| PWP Managed Cloud WiFi 31012 | 95624-31012 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PWP Managed Cloud WiFi 31013 | 95624-31013 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PWP Managed Cloud WiFi 31014 | 95624-31014 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PWP Managed Cloud WiFi 31015 | 95624-31015 | \$ 128.00 | 6% | <i>\$121.22</i> |
| PWP Managed Cloud WiFi 31016 | 95624-31016 | \$ 419.00 | 6% | <i>\$396.81</i> |
| PWP Managed Cloud WiFi 31017 | 95624-31017 | \$ 419.00 | 6% | <i>\$396.81</i> |
| PWP Managed Cloud WiFi 31018 | 95624-31018 | \$ 490.00 | 6% | <i>\$464.05</i> |
| PWP Managed Cloud WiFi 31019 | 95624-31019 | \$ 490.00 | 6% | <i>\$464.05</i> |
| PWP Managed Cloud WiFi 31025 | 95624-31025 | \$ 83.00 | 6% | <i>\$78.61</i> |
| PWP Managed Cloud WiFi 31028 | 95624-31028 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP Managed Cloud WiFi 31029 | 95624-31029 | \$ 110.00 | 6% | <i>\$104.18</i> |
| PWP Managed Cloud WiFi 31034 | 95624-31034 | \$ 273.00 | 6% | <i>\$258.54</i> |
| PWP Managed Cloud WiFi 31035 | 95624-31035 | \$ 273.00 | 6% | <i>\$258.54</i> |
| PWP Managed Cloud WiFi 39031 | 95624-39031 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Managed Cloud WiFi 39032 | 95624-39032 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Managed Cloud WiFi 39033 | 95624-39033 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Managed Cloud WiFi 39034 | 95624-39034 | \$ 249.00 | 6% | <i>\$235.82</i> |
| PWP Managed Cloud WiFi 39035 | 95624-39035 | \$ 427.00 | 6% | <i>\$404.39</i> |
| PWP Managed Cloud WiFi 39036 | 95624-39036 | \$ 171.00 | 6% | <i>\$161.95</i> |
| PWP Managed Cloud WiFi 39038 | 95624-39038 | \$ 237.00 | 6% | <i>\$224.45</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|------------|
| PWP Managed Cloud WiFi 39039 | 95624-39039 | \$ 237.00 | 6% | \$224.45 |
| PWP Managed Cloud WiFi | 95624-H30632 | \$ 136.00 | 6% | \$128.80 |
| PWP Managed Cloud WiFi | 95624-H30633 | \$ 136.00 | 6% | \$128.80 |
| PWP Managed Cloud WiFi | 95624-H30724 | \$ 224.00 | 6% | \$212.14 |
| PWP Managed Cloud WiFi | 95624-H30730 | \$ 136.00 | 6% | \$128.80 |
| PWP Managed Cloud WiFi | 95624-H30731 | \$ 136.00 | 6% | \$128.80 |
| PWP Managed Cloud WiFi H30738 | 95624-H30738 | \$ 94.00 | 6% | \$89.02 |
| EW TAC OS Optics 10200 | 97000-10200 | \$ 1,181.00 | 10% | \$1,070.87 |
| EW TAC OS Optics 10320 | 97000-10320 | \$ 1,291.00 | 10% | \$1,170.61 |
| EW TAC OS 10330 | 97000-10330 | \$ 3,172.00 | 10% | \$2,876.21 |
| EW TAC OS 10331 | 97000-10331 | \$ 1,461.00 | 10% | \$1,324.76 |
| EW TAC OS 10335 | 97000-10335 | \$ 2,234.00 | 10% | \$2,025.68 |
| EW TAC OS 10403 | 97000-10403 | \$ 2,765.00 | 10% | \$2,507.16 |
| EW TAC OS 10404 | 97000-10404 | \$ 1,321.00 | 10% | \$1,197.82 |
| EW TAC OS 10441 | 97000-10441 | \$ 888.00 | 10% | \$805.19 |
| EW TAC OS 10442 | 97000-10442 | \$ 938.00 | 10% | \$850.53 |
| EW TAC OS Summit 11011 | 97000-11011 | \$ 159.00 | 10% | \$144.17 |
| EW TAC OS 1130C | 97000-1130C | \$ 480.00 | 6% | \$454.58 |
| EW TAC OS E4G 16119 | 97000-16119 | \$ 164.00 | 10% | \$148.71 |
| EW TAC OS E4G 16120 | 97000-16120 | \$ 196.00 | 10% | \$177.72 |
| EW TAC OS E4G 16126 | 97000-16126 | \$ 164.00 | 10% | \$148.71 |
| EW TAC OS E4G 16127 | 97000-16127 | \$ 172.00 | 10% | \$155.96 |
| EW TAC OS 16169 | 97000-16169 | \$ 62.00 | 10% | \$56.22 |
| EW TAC OS 16172 | 97000-16172 | \$ 176.00 | 10% | \$159.59 |
| EW TAC OS-16172T | 97000-16172T | \$ 207.00 | 10% | \$187.70 |
| EW TAC OS 16173 | 97000-16173 | \$ 176.00 | 10% | \$159.59 |
| EW TAC OS-16173T | 97000-16173T | \$ 207.00 | 10% | \$187.70 |
| EW TAC OS 16174 | 97000-16174 | \$ 275.00 | 10% | \$249.36 |
| EW TAC OS 16175 | 97000-16175 | \$ 292.00 | 10% | \$264.77 |
| EW TAC OS 16176 | 97000-16176 | \$ 260.00 | 10% | \$235.76 |
| EW TAC OS 16177 | 97000-16177 | \$ 250.00 | 10% | \$226.69 |
| EW TAC OS-16177T | 97000-16177T | \$ 314.00 | 10% | \$284.72 |
| EW TAC OS 16178 | 97000-16178 | \$ 367.00 | 10% | \$332.78 |
| EW TAC OS 16179 | 97000-16179 | \$ 374.00 | 10% | \$339.12 |
| EW TAC OS-16179T | 97000-16179T | \$ 460.00 | 10% | \$417.11 |
| EW TAC OS 16190 | 97000-16190 | \$ 117.00 | 10% | \$106.09 |
| EW TAC OS 16191 | 97000-16191 | \$ 225.00 | 10% | \$204.02 |
| EW TAC OS 16192 | 97000-16192 | \$ 225.00 | 10% | \$204.02 |
| EW TAC OS 16200 | 97000-16200 | \$ 128.00 | 10% | \$116.06 |
| EW TAC OS 16301T | 97000-16301T | \$ 949.00 | 10% | \$860.51 |

| | | | | |
|------------------------|--------------|-------------|-----|-------------------|
| EW TAC OS 16303T | 97000-16303T | \$ 949.00 | 10% | <i>\$860.51</i> |
| EW TAC OS 16304T | 97000-16304T | \$ 1,268.00 | 10% | <i>\$1,149.76</i> |
| EW TAC OS 16323 | 97000-16323 | \$ 128.00 | 10% | <i>\$116.06</i> |
| EW TAC OS 16401T | 97000-16401T | \$ 444.00 | 10% | <i>\$402.60</i> |
| EW TAC OS 16402T | 97000-16402T | \$ 678.00 | 10% | <i>\$614.78</i> |
| EW TAC OS 16403T | 97000-16403T | \$ 597.00 | 10% | <i>\$541.33</i> |
| EW TAC OS 16404T | 97000-16404T | \$ 597.00 | 10% | <i>\$541.33</i> |
| EW TAC OS 16405T | 97000-16405T | \$ 794.00 | 10% | <i>\$719.96</i> |
| EW TAC OS 16406T | 97000-16406T | \$ 1,063.00 | 10% | <i>\$963.88</i> |
| EW TAC OS 16423 | 97000-16423 | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW TAC OS 16425 | 97000-16425 | \$ 128.00 | 10% | <i>\$116.06</i> |
| EW TAC OS 16426 | 97000-16426 | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW TAC OS E4G 16431 | 97000-16431 | \$ 675.00 | 10% | <i>\$612.06</i> |
| EW TAC OS E4G 16432 | 97000-16432 | \$ 723.00 | 10% | <i>\$655.58</i> |
| EW TAC OS E4G 16440 | 97000-16440 | \$ 422.00 | 10% | <i>\$382.65</i> |
| EW TAC OS E4G 16441 | 97000-16441 | \$ 382.00 | 10% | <i>\$346.38</i> |
| EW TAC OS E4G 16442 | 97000-16442 | \$ 172.00 | 10% | <i>\$155.96</i> |
| EW TAC OS E4G 16444 | 97000-16444 | \$ 85.00 | 10% | <i>\$77.07</i> |
| EW TAC OS E4G 16490 | 97000-16490 | \$ 85.00 | 10% | <i>\$77.07</i> |
| EW TAC OS E4G 16491 | 97000-16491 | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW TAC OS E4G 16492 | 97000-16492 | \$ 279.00 | 10% | <i>\$252.98</i> |
| EW TAC OS E4G 16493 | 97000-16493 | \$ 279.00 | 10% | <i>\$252.98</i> |
| EW TAC OS E4G 16495 | 97000-16495 | \$ 85.00 | 10% | <i>\$77.07</i> |
| EW TAC OS E4G 16496 | 97000-16496 | \$ 261.00 | 10% | <i>\$236.66</i> |
| EW TAC OS Summit 16501 | 97000-16501 | \$ 91.00 | 10% | <i>\$82.51</i> |
| EW TAC OS 16501T | 97000-16501T | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW TAC OS Summit 16502 | 97000-16502 | \$ 135.00 | 10% | <i>\$122.41</i> |
| EW TAC OS 16502T | 97000-16502T | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW TAC OS Summit 16503 | 97000-16503 | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW TAC OS 16503T | 97000-16503T | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW TAC OS Summit 16504 | 97000-16504 | \$ 183.00 | 10% | <i>\$165.94</i> |
| EW TAC OS 16504T | 97000-16504T | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW TAC OS Summit 16505 | 97000-16505 | \$ 201.00 | 10% | <i>\$182.26</i> |
| EW TAC OS 16505T | 97000-16505T | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW TAC OS Summit 16506 | 97000-16506 | \$ 307.00 | 10% | <i>\$278.37</i> |
| EW TAC OS 16506T | 97000-16506T | \$ 380.00 | 10% | <i>\$344.57</i> |
| EW TAC OS Summit 16507 | 97000-16507 | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW TAC OS 16507T | 97000-16507T | \$ 328.00 | 10% | <i>\$297.41</i> |
| EW TAC OS Summit 16508 | 97000-16508 | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW TAC OS 16508T | 97000-16508T | \$ 424.00 | 10% | <i>\$384.46</i> |
| EW TAC OS Summit 16509 | 97000-16509 | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW TAC OS 16509T | 97000-16509T | \$ 424.00 | 10% | <i>\$384.46</i> |

| | | | | |
|---------------------------|--------------|-----------|-----|----------|
| EW TAC OS Summit 16510 | 97000-16510 | \$ 424.00 | 10% | \$384.46 |
| EW TAC OS 16510T | 97000-16510T | \$ 503.00 | 10% | \$456.10 |
| EW Software and TAC-16513 | 97000-16513 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC-16514 | 97000-16514 | \$ 414.00 | 10% | \$375.39 |
| EW TAC OS 16515 | 97000-16515 | \$ 72.00 | 10% | \$65.29 |
| EW Software TAC-16516 | 97000-16516 | \$ 79.00 | 10% | \$71.63 |
| EW TAC OS 16517 | 97000-16517 | \$ 152.00 | 10% | \$137.83 |
| EW Software TAC-16518 | 97000-16518 | \$ 135.00 | 10% | \$122.41 |
| EW-Software and TAC 16519 | 97000-16519 | \$ 144.00 | 10% | \$130.57 |
| EW-Software and TAC 16520 | 97000-16520 | \$ 241.00 | 10% | \$218.53 |
| EW TAC OS Summit 16521 | 97000-16521 | \$ 62.00 | 10% | \$56.22 |
| EW TAC OS 16522 | 97000-16522 | \$ 105.00 | 10% | \$95.21 |
| EW TAC OS 16523 | 97000-16523 | \$ 55.00 | 10% | \$49.87 |
| EW Software and TAC 16524 | 97000-16524 | \$ 64.00 | 10% | \$58.03 |
| EW TAC OS 16530 | 97000-16530 | \$ 91.00 | 10% | \$82.51 |
| EW TAC OS 16531 | 97000-16531 | \$ 121.00 | 10% | \$109.72 |
| EW TAC OS 16531T | 97000-16531T | \$ 135.00 | 10% | \$122.41 |
| EW TAC OS 16532 | 97000-16532 | \$ 121.00 | 10% | \$109.72 |
| EW TAC OS 16532T | 97000-16532T | \$ 135.00 | 10% | \$122.41 |
| EW TAC OS 16533 | 97000-16533 | \$ 173.00 | 10% | \$156.87 |
| EW TAC OS 16533T | 97000-16533T | \$ 190.00 | 10% | \$172.28 |
| EW TAC OS 16534 | 97000-16534 | \$ 180.00 | 10% | \$163.22 |
| EW TAC OS 16535 | 97000-16535 | \$ 267.00 | 10% | \$242.10 |
| EW TAC OS 16535A | 97000-16535A | \$ 267.00 | 10% | \$242.10 |
| EW TAC OS 16535T | 97000-16535T | \$ 293.00 | 10% | \$265.68 |
| EW TAC OS 16536 | 97000-16536 | \$ 128.00 | 10% | \$116.06 |
| EW TAC OS 16537 | 97000-16537 | \$ 164.00 | 10% | \$148.71 |
| EW TAC OS 16538 | 97000-16538 | \$ 202.00 | 10% | \$183.16 |
| EW TAC OS 16538T | 97000-16538T | \$ 246.00 | 10% | \$223.06 |
| EW TAC OS 16539 | 97000-16539 | \$ 257.00 | 10% | \$233.03 |
| EW TAC OS 16540 | 97000-16540 | \$ 187.00 | 10% | \$169.56 |
| EW TAC OS 16541 | 97000-16541 | \$ 75.00 | 10% | \$68.01 |
| EW TAC OS 16560 | 97000-16560 | \$ 43.00 | 10% | \$38.99 |
| EW TAC OS 16561 | 97000-16561 | \$ 56.00 | 10% | \$50.78 |
| EW TAC OS 16562 | 97000-16562 | \$ 72.00 | 10% | \$65.29 |
| EW TAC OS 16563 | 97000-16563 | \$ 92.00 | 10% | \$83.42 |
| EW TAC OS 16564 | 97000-16564 | \$ 113.00 | 10% | \$102.46 |
| EW TAC OS 16565 | 97000-16565 | \$ 177.00 | 10% | \$160.49 |
| EW TAC OS 16566 | 97000-16566 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 16567 | 97000-16567 | \$ 49.00 | 10% | \$44.43 |
| EW TAC OS 16568 | 97000-16568 | \$ 43.00 | 10% | \$38.99 |
| EW TAC OS 16569 | 97000-16569 | \$ 64.00 | 10% | \$58.03 |

| | | | | |
|------------------|--------------|-------------|-----|----------|
| EW TAC OS 16570 | 97000-16570 | \$ 72.00 | 10% | \$65.29 |
| EW TAC OS 16571 | 97000-16571 | \$ 113.00 | 10% | \$102.46 |
| EW TAC OS 16701 | 97000-16701 | \$ 249.00 | 10% | \$225.78 |
| EW TAC OS 16702 | 97000-16702 | \$ 367.00 | 10% | \$332.78 |
| EW TAC OS 16703 | 97000-16703 | \$ 292.00 | 10% | \$264.77 |
| EW TAC OS-16703T | 97000-16703T | \$ 344.00 | 10% | \$311.92 |
| EW TAC OS 16704 | 97000-16704 | \$ 425.00 | 10% | \$385.37 |
| EW TAC OS-16704T | 97000-16704T | \$ 502.00 | 10% | \$455.19 |
| EW TAC OS 16705 | 97000-16705 | \$ 367.00 | 10% | \$332.78 |
| EW TAC OS-16705T | 97000-16705T | \$ 443.00 | 10% | \$401.69 |
| EW TAC OS 16706 | 97000-16706 | \$ 548.00 | 10% | \$496.90 |
| EW TAC OS-16706T | 97000-16706T | \$ 661.00 | 10% | \$599.36 |
| EW TAC OS 16710 | 97000-16710 | \$ 120.00 | 10% | \$108.81 |
| EW TAC OS 16710T | 97000-16710T | \$ 141.00 | 10% | \$127.85 |
| EW TAC OS 16711 | 97000-16711 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS 16711T | 97000-16711T | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS 16712 | 97000-16712 | \$ 71.00 | 10% | \$64.38 |
| EW TAC OS 16712T | 97000-16712T | \$ 82.00 | 10% | \$74.35 |
| EW TAC OS 16713 | 97000-16713 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS 16713T | 97000-16713T | \$ 43.00 | 10% | \$38.99 |
| EW TAC OS 16715 | 97000-16715 | \$ 47.00 | 10% | \$42.62 |
| EW TAC OS 16715T | 97000-16715T | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS 16716 | 97000-16716 | \$ 190.00 | 10% | \$172.28 |
| EW TAC OS-16716T | 97000-16716T | \$ 230.00 | 10% | \$208.55 |
| EW TAC OS 16717 | 97000-16717 | \$ 290.00 | 10% | \$262.96 |
| EW TAC OS 16718 | 97000-16718 | \$ 205.00 | 10% | \$185.88 |
| EW TAC OS-16718T | 97000-16718T | \$ 252.00 | 10% | \$228.50 |
| EW TAC OS 16719 | 97000-16719 | \$ 312.00 | 10% | \$282.91 |
| EW TAC OS-16719T | 97000-16719T | \$ 380.00 | 10% | \$344.57 |
| EW TAC OS 16720 | 97000-16720 | \$ 463.00 | 10% | \$419.83 |
| EW TAC OS 16720T | 97000-16720T | \$ 540.00 | 10% | \$489.65 |
| EW TAC OS 16755 | 97000-16755 | \$ 44.00 | 10% | \$39.90 |
| EW TAC OS 16756 | 97000-16756 | \$ 343.00 | 10% | \$311.02 |
| EW TAC OS 16756T | 97000-16756T | \$ 404.00 | 10% | \$366.33 |
| EW TAC OS 16757 | 97000-16757 | \$ 319.00 | 10% | \$289.25 |
| EW TAC OS 16757T | 97000-16757T | \$ 372.00 | 10% | \$337.31 |
| EW TAC OS 16778 | 97000-16778 | \$ 39.00 | 10% | \$35.36 |
| EW TAC OS 16779 | 97000-16779 | \$ 39.00 | 10% | \$35.36 |
| EW TAC OS 16780 | 97000-16780 | \$ 39.00 | 10% | \$35.36 |
| EW TAC OS 16790 | 97000-16790 | \$ 777.00 | 10% | \$704.54 |
| EW TAC OS 16791 | 97000-16791 | \$ 1,001.00 | 10% | \$907.66 |
| EW TAC OS 16795 | 97000-16795 | \$ 163.00 | 10% | \$147.80 |

| | | | | |
|-------------------------|--------------|-------------|-----|-------------------|
| EW TAC OS 16801 | 97000-16801 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW TAC OS 16802 | 97000-16802 | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW TAC OS 16803 | 97000-16803 | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW TAC OS 16804 | 97000-16804 | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW TAC OS 16805 | 97000-16805 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 16806 | 97000-16806 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS Summit 17101 | 97000-17101 | \$ 1,476.00 | 10% | <i>\$1,338.36</i> |
| EW TAC OS 17101T | 97000-17101T | \$ 1,797.00 | 10% | <i>\$1,629.43</i> |
| EW TAC OS Summit 17102 | 97000-17102 | \$ 1,476.00 | 10% | <i>\$1,338.36</i> |
| EW TAC OS 17102T | 97000-17102T | \$ 1,797.00 | 10% | <i>\$1,629.43</i> |
| EW TAC OS Summit 17103 | 97000-17103 | \$ 1,031.00 | 10% | <i>\$934.86</i> |
| EW TAC OS Summit 17103C | 97000-17103C | \$ 937.00 | 10% | <i>\$849.62</i> |
| EW TAC OS 17103T | 97000-17103T | \$ 1,258.00 | 10% | <i>\$1,140.69</i> |
| EW TAC OS Summit 17104 | 97000-17104 | \$ 1,031.00 | 10% | <i>\$934.86</i> |
| EW TAC OS 17104T | 97000-17104T | \$ 1,258.00 | 10% | <i>\$1,140.69</i> |
| EW TAC OS Summit 17121 | 97000-17121 | \$ 289.00 | 10% | <i>\$262.05</i> |
| EW TAC OS Summit 17122 | 97000-17122 | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW TAC OS Summit 17131 | 97000-17131 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW TAC OS Summit 17133 | 97000-17133 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW TAC OS 17134 | 97000-17134 | \$ 383.00 | 10% | <i>\$347.29</i> |
| EW TAC OS 17135 | 97000-17135 | \$ 316.00 | 10% | <i>\$286.53</i> |
| EW TAC OS 17136 | 97000-17136 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW TAC OS 17137 | 97000-17137 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW TAC OS 17138 | 97000-17138 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW TAC OS 17139 | 97000-17139 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW TAC OS -17200 | 97000-17200 | \$ 2,321.00 | 10% | <i>\$2,104.57</i> |
| EW TAC OS 17200T | 97000-17200T | \$ 2,536.00 | 10% | <i>\$2,299.52</i> |
| EW TAC OS Summit 17201 | 97000-17201 | \$ 2,321.00 | 10% | <i>\$2,104.57</i> |
| EW TAC OS 17201T | 97000-17201T | \$ 2,536.00 | 10% | <i>\$2,299.52</i> |
| EW TAC OS Summit 17202 | 97000-17202 | \$ 2,321.00 | 10% | <i>\$2,104.57</i> |
| EW TAC OS 17202T | 97000-17202T | \$ 2,536.00 | 10% | <i>\$2,299.52</i> |
| EW TAC OS Summit 17203 | 97000-17203 | \$ 2,368.00 | 10% | <i>\$2,147.18</i> |
| EW TAC OS 17203T | 97000-17203T | \$ 2,575.00 | 10% | <i>\$2,334.88</i> |
| EW TAC OS Summit 17204 | 97000-17204 | \$ 2,368.00 | 10% | <i>\$2,147.18</i> |
| EW TAC OS 17204T | 97000-17204T | \$ 2,575.00 | 10% | <i>\$2,334.88</i> |
| EW TAC OS Summit 17205 | 97000-17205 | \$ 2,342.00 | 10% | <i>\$2,123.61</i> |
| EW TAC OS 17205T | 97000-17205T | \$ 2,549.00 | 10% | <i>\$2,311.31</i> |
| EW TAC OS Summit 17206 | 97000-17206 | \$ 2,342.00 | 10% | <i>\$2,123.61</i> |
| EW TAC OS 17206T | 97000-17206T | \$ 2,549.00 | 10% | <i>\$2,311.31</i> |
| EW TAC OS 17300 | 97000-17300 | \$ 1,536.00 | 10% | <i>\$1,392.77</i> |
| EW TAC OS 17310 | 97000-17310 | \$ 1,396.00 | 10% | <i>\$1,265.82</i> |
| EW TAC OS-17310T | 97000-17310T | \$ 1,677.00 | 10% | <i>\$1,520.62</i> |

| | | | | |
|---------------------|-----------------|-------------|-----|------------|
| EW TAC OS 17350 | 97000-17350 | \$ 1,410.00 | 10% | \$1,278.52 |
| EW TAC OS 17360 | 97000-17360 | \$ 1,730.00 | 10% | \$1,568.68 |
| EW TAC OS 17401 | 97000-17401 | \$ 212.00 | 10% | \$192.23 |
| EW TAC OS 17401G | 97000-17401G | \$ 253.00 | 10% | \$229.41 |
| EW TAC OS 17401T | 97000-17401T | \$ 240.00 | 10% | \$217.62 |
| EW TAC OS 17402 | 97000-17402 | \$ 301.00 | 10% | \$272.93 |
| EW TAC OS 17402G | 97000-17402G | \$ 340.00 | 10% | \$308.30 |
| EW TAC OS 17402T | 97000-17402T | \$ 322.00 | 10% | \$291.97 |
| EW TAC OS 17403 | 97000-17403 | \$ 330.00 | 10% | \$299.23 |
| EW TAC OS 17404 | 97000-17404 | \$ 162.00 | 10% | \$146.89 |
| EW TAC OS 17405 | 97000-17405 | \$ 197.00 | 10% | \$178.63 |
| EW TAC OS 17431 | 97000-17431 | \$ 44.00 | 10% | \$39.90 |
| EW TAC OS 17433 | 97000-17433 | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS 17434 | 97000-17434 | \$ 53.00 | 10% | \$48.06 |
| EW TAC OS 17435 | 97000-17435 | \$ 74.00 | 10% | \$67.10 |
| EW TAC OS 17700 | 97000-17700 | \$ 2,721.00 | 10% | \$2,467.27 |
| EW TAC OS 17701 | 97000-17701 | \$ 2,418.00 | 10% | \$2,192.52 |
| EW TAC OS 17702 | 97000-17702 | \$ 2,418.00 | 10% | \$2,192.52 |
| EW TAC OS 17703 | 97000-17703 | \$ 2,596.00 | 10% | \$2,353.92 |
| EW TAC OS 17704 | 97000-17704 | \$ 2,596.00 | 10% | \$2,353.92 |
| EW TAC OS 17705 | 97000-17705 | \$ 2,430.00 | 10% | \$2,203.40 |
| EW TAC OS 17706 | 97000-17706 | \$ 2,430.00 | 10% | \$2,203.40 |
| EW TAC OS 17725 | 97000-17725 | \$ 510.00 | 10% | \$462.44 |
| EW TAC OS 17726 | 97000-17726 | \$ 224.00 | 10% | \$203.11 |
| EW TAC OS 17727 | 97000-17727 | \$ 464.00 | 10% | \$420.73 |
| EW TAC OS 17728 | 97000-17728 | \$ 211.00 | 10% | \$191.32 |
| EW TAC OS 17729 | 97000-17729 | \$ 140.00 | 10% | \$126.95 |
| EW TAC OS 17800 | 97000-17800 | \$ 2,718.00 | 10% | \$2,464.55 |
| EW TAC OS 17810 | 97000-17810 | \$ 2,168.00 | 10% | \$1,965.83 |
| EW TAC OS 17825 | 97000-17825 | \$ 382.00 | 10% | \$346.38 |
| EW TAC OS 17826 | 97000-17826 | \$ 449.00 | 10% | \$407.13 |
| EW TAC OS 17828 | 97000-17828 | \$ 268.00 | 10% | \$243.01 |
| EW TAC OS 18101 | 97000-18101 | \$ 136.00 | 10% | \$123.32 |
| EW TAC OS 18102 | 97000-18102 | \$ 178.00 | 10% | \$161.40 |
| EW TAC OS 18103 | 97000-18103 | \$ 192.00 | 10% | \$174.10 |
| EW TAC OS 18104 | 97000-18104 | \$ 274.00 | 10% | \$248.45 |
| EW TAC OS 18104-6PK | 97000-18104-6PK | \$ 1,533.00 | 10% | \$1,390.05 |
| EW TAC OS 18202 | 97000-18202 | \$ 103.00 | 10% | \$93.40 |
| EW TAC OS 30135 | 97000-30135 | \$ 294.00 | 10% | \$266.58 |
| EW TAC OS 30136 | 97000-30136 | \$ 2,268.00 | 10% | \$2,056.51 |
| EW TAC OS 30137 | 97000-30137 | \$ 482.00 | 10% | \$437.05 |

| | | | | |
|-----------------|-------------|-------------|-----|-------------------|
| EW TAC OS 30138 | 97000-30138 | \$ 2,402.00 | 10% | <i>\$2,178.01</i> |
| EW TAC OS 30139 | 97000-30139 | \$ 3,884.00 | 10% | <i>\$3,521.82</i> |
| EW TAC OS 30912 | 97000-30912 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 30913 | 97000-30913 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31012 | 97000-31012 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31013 | 97000-31013 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31014 | 97000-31014 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31015 | 97000-31015 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31016 | 97000-31016 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31017 | 97000-31017 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31018 | 97000-31018 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31019 | 97000-31019 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31025 | 97000-31025 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31026 | 97000-31026 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31028 | 97000-31028 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31029 | 97000-31029 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31031 | 97000-31031 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31032 | 97000-31032 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31034 | 97000-31034 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31035 | 97000-31035 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31050 | 97000-31050 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31051 | 97000-31051 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31055 | 97000-31055 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 31056 | 97000-31056 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37101 | 97000-37101 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37102 | 97000-37102 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37103 | 97000-37103 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37111 | 97000-37111 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37112 | 97000-37112 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37113 | 97000-37113 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37114 | 97000-37114 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37115 | 97000-37115 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37116 | 97000-37116 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37117 | 97000-37117 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37121 | 97000-37121 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37122 | 97000-37122 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37123 | 97000-37123 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37124 | 97000-37124 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37125 | 97000-37125 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37126 | 97000-37126 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37129 | 97000-37129 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW TAC OS 37130 | 97000-37130 | \$ 30.00 | 10% | <i>\$27.20</i> |

| | | | | |
|---------------------------|-----------------------|-------------|-----|------------|
| EW TAC OS 39031 | 97000-39031 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39032 | 97000-39032 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39033 | 97000-39033 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39034 | 97000-39034 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39035 | 97000-39035 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39036 | 97000-39036 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39037 | 97000-39037 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39038 | 97000-39038 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39039 | 97000-39039 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS 39505 | 97000-39505 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS 4120-24MW-4Y | 97000-4120-24MW-4Y | \$ 396.00 | 10% | \$359.07 |
| EW TAC OS 4120-48MW-4Y | 97000-4120-48MW-4Y | \$ 528.00 | 10% | \$478.76 |
| EW TAC OS 4120C | 97000-4120C | \$ 2,589.00 | 10% | \$2,347.58 |
| EW TAC OS 4120C-1 | 97000-4120C-1 | \$ 2,923.00 | 10% | \$2,650.43 |
| EW TAC OS 41216 | 97000-41216 | \$ 894.00 | 10% | \$810.63 |
| EW TAC OS BD 41312 | 97000-41312 | \$ 735.00 | 10% | \$666.46 |
| EW TAC OS 41314 | 97000-41314 | \$ 2,207.00 | 10% | \$2,001.20 |
| EW TAC OS 4220-12P-4X | 97000-4220-12P-4X | \$ 117.00 | 10% | \$106.09 |
| EW TAC OS 4220-12T-4X | 97000-4220-12T-4X | \$ 86.00 | 10% | \$77.98 |
| EW TAC OS 4220-24P-4X | 97000-4220-24P-4X | \$ 156.00 | 10% | \$141.45 |
| EW TAC OS 4220-24T-4X | 97000-4220-24T-4X | \$ 121.00 | 10% | \$109.72 |
| EW TAC OS 4220-48P-4X | 97000-4220-48P-4X | \$ 234.00 | 10% | \$212.18 |
| EW TAC OS 4220-48T-4X | 97000-4220-48T-4X | \$ 175.00 | 10% | \$158.68 |
| EW TAC OS 4220-4MW-20P-4X | 97000-4220-4MW-20P-4X | \$ 214.00 | 10% | \$194.04 |
| EW TAC OS 4220-4MW-8P-4X | 97000-4220-4MW-8P-4X | \$ 152.00 | 10% | \$137.83 |
| EW TAC OS 4220-8MW-40P-4X | 97000-4220-8MW-40P-4X | \$ 312.00 | 10% | \$282.91 |
| EW TAC OS 4220-8X | 97000-4220-8X | \$ 164.00 | 10% | \$148.71 |
| EW TAC OS BD X 48001 | 97000-48001 | \$ 3,705.00 | 10% | \$3,359.51 |
| EW TAC OS 48038 | 97000-48038 | \$ 1,486.00 | 10% | \$1,347.43 |

| | | | | |
|-------------------------------|---------------------------|-------------|-----|-------------------|
| EW TAC OS 48039 | 97000-48039 | \$ 1,486.00 | 10% | <i>\$1,347.43</i> |
| EW Software and TAC-48040 | 97000-48040 | \$ 1,404.00 | 10% | <i>\$1,273.08</i> |
| EW TAC OS BD X 48041 | 97000-48041 | \$ 1,486.00 | 10% | <i>\$1,347.43</i> |
| EW TAC OS BD X 48046 | 97000-48046 | \$ 1,950.00 | 10% | <i>\$1,768.16</i> |
| EW TAC OS 48047 | 97000-48047 | \$ 5,198.00 | 10% | <i>\$4,713.29</i> |
| EW TAC OS BD X 48051 | 97000-48051 | \$ 3,570.00 | 10% | <i>\$3,237.10</i> |
| EW TAC OS 48061 | 97000-48061 | \$ 4,176.00 | 10% | <i>\$3,786.59</i> |
| EW TAC OS 48062 | 97000-48062 | \$ 6,681.00 | 10% | <i>\$6,058.00</i> |
| EW TAC OS BD X 48091 | 97000-48091 | \$ 1,389.00 | 10% | <i>\$1,259.48</i> |
| EW TAC OS BD X 48093 | 97000-48093 | \$ 926.00 | 10% | <i>\$839.65</i> |
| EW TAC OS 48094 | 97000-48094 | \$ 1,389.00 | 10% | <i>\$1,259.48</i> |
| TAC OS 5000-MACSEC-LIC | 97000-5000-MACSEC-LIC | \$ 96.00 | 10% | <i>\$87.05</i> |
| TAC OS 5000-PRMR-LIC | 97000-5000-PRMR-LIC | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW TAC OS 5320-16P-4XE | 97000-5320-16P-4XE | \$ 166.00 | 10% | <i>\$150.52</i> |
| EW TAC OS 5320-16P-4XE-DC | 97000-5320-16P-4XE-DC | \$ 199.00 | 10% | <i>\$180.44</i> |
| EW TAC OS 5320-24P-8XE | 97000-5320-24P-8XE | \$ 182.00 | 10% | <i>\$165.03</i> |
| EW TAC OS 5320-24T-24S-4XE-XT | 97000-5320-24T-24S-4XE-XT | \$ 253.00 | 10% | <i>\$229.41</i> |
| EW TAC OS 5320-24T-4X-XT | 97000-5320-24T-4X-XT | \$ 136.00 | 10% | <i>\$123.32</i> |
| EW TAC OS 5320-24T-8XE | 97000-5320-24T-8XE | \$ 130.00 | 10% | <i>\$117.88</i> |
| EW TAC OS 5320-48P-8XE | 97000-5320-48P-8XE | \$ 305.00 | 10% | <i>\$276.56</i> |
| EW TAC OS 5320-48T-8XE | 97000-5320-48T-8XE | \$ 206.00 | 10% | <i>\$186.79</i> |
| EW TAC OS 5420F-16MW-32P-4XE | 97000-5420F-16MW-32P-4XE | \$ 569.00 | 10% | <i>\$515.94</i> |
| EW TAC OS 5420F-16W-32P-4XE | 97000-5420F-16W-32P-4XE | \$ 481.00 | 10% | <i>\$436.15</i> |
| EW TAC OS 5420F-24P-4XE | 97000-5420F-24P-4XE | \$ 296.00 | 10% | <i>\$268.40</i> |
| EW TAC OS 5420F-24S-4XE | 97000-5420F-24S-4XE | \$ 271.00 | 10% | <i>\$245.73</i> |

| | | | | |
|------------------------------|--------------------------|-----------|-----|----------|
| EW TAC OS 5420F-24T-4XE | 97000-5420F-24T-4XE | \$ 251.00 | 10% | \$227.59 |
| EW TAC OS 5420F-48P-4XE | 97000-5420F-48P-4XE | \$ 455.00 | 10% | \$412.57 |
| EW TAC OS 5420F-48P-4XL | 97000-5420F-48P-4XL | \$ 436.00 | 10% | \$395.34 |
| EW TAC OS 5420F-48T-4XE | 97000-5420F-48T-4XE | \$ 329.00 | 10% | \$298.32 |
| EW TAC OS 5420F-8W-16P-4XE | 97000-5420F-8W-16P-4XE | \$ 283.00 | 10% | \$256.61 |
| EW TAC OS 5420M-16MW-32P-4YE | 97000-5420M-16MW-32P-4YE | \$ 691.00 | 10% | \$626.56 |
| EW TAC OS 5420M-24T-4YE | 97000-5420M-24T-4YE | \$ 279.00 | 10% | \$252.98 |
| EW TAC OS 5420M-24W-4YE | 97000-5420M-24W-4YE | \$ 280.00 | 10% | \$253.89 |
| EW TAC OS 5420M-48T-4YE | 97000-5420M-48T-4YE | \$ 395.00 | 10% | \$358.17 |
| EW TAC OS 5420M-48W-4YE | 97000-5420M-48W-4YE | \$ 445.00 | 10% | \$403.50 |
| EW TAC OS 5520-12MW-36W | 97000-5520-12MW-36W | \$ 583.00 | 10% | \$528.64 |
| EW TAC OS 5520-24T | 97000-5520-24T | \$ 263.00 | 10% | \$238.48 |
| EW TAC OS 5520-24T-ACDC-BASE | 97000-5520-24T-ACDC-BASE | \$ 263.00 | 10% | \$238.48 |
| EW TAC OS 5520-24T-BASE | 97000-5520-24T-BASE | \$ 263.00 | 10% | \$238.48 |
| EW TAC OS 5520-24W | 97000-5520-24W | \$ 338.00 | 10% | \$306.48 |
| EW TAC OS 5520-24X | 97000-5520-24X | \$ 713.00 | 10% | \$646.51 |
| EW TAC OS 5520-24X-ACDC-BASE | 97000-5520-24X-ACDC-BASE | \$ 713.00 | 10% | \$646.51 |
| EW TAC OS 5520-24X-BASE | 97000-5520-24X-BASE | \$ 713.00 | 10% | \$646.51 |
| EW TAC OS 5520-48SE | 97000-5520-48SE | \$ 603.00 | 10% | \$546.77 |

| | | | | |
|-------------------------------|---------------------------|-------------|-----|------------|
| EW TAC OS 5520-48SE-ACDC-BASE | 97000-5520-48SE-ACDC-BASE | \$ 603.00 | 10% | \$546.77 |
| EW TAC OS 5520-48SE-BASE | 97000-5520-48SE-BASE | \$ 603.00 | 10% | \$546.77 |
| EW TAC OS 5520-48T | 97000-5520-48T | \$ 398.00 | 10% | \$360.89 |
| EW TAC OS 5520-48T-ACDC-BASE | 97000-5520-48T-ACDC-BASE | \$ 398.00 | 10% | \$360.89 |
| EW TAC OS 5520-48T-BASE | 97000-5520-48T-BASE | \$ 398.00 | 10% | \$360.89 |
| EW TAC OS 5520-48W | 97000-5520-48W | \$ 477.00 | 10% | \$432.52 |
| EW TAC OS 5720-24MW | 97000-5720-24MW | \$ 750.00 | 10% | \$680.06 |
| EW TAC OS 5720-24MXW | 97000-5720-24MXW | \$ 1,015.00 | 10% | \$920.35 |
| EW TAC OS 5720-48MW | 97000-5720-48MW | \$ 923.00 | 10% | \$836.93 |
| EW TAC OS 5720-48MXW | 97000-5720-48MXW | \$ 1,319.00 | 10% | \$1,196.00 |
| EW TAC OS 7000-MACSEC-LIC-P | 97000-7000-MACSEC-LIC-P | \$ 408.00 | 10% | \$369.95 |
| EW TAC OS 7000-PRMR-LIC-P | 97000-7000-PRMR-LIC-P | \$ 408.00 | 10% | \$369.95 |
| EW TAC OS 7520-48XT-6C | 97000-7520-48XT-6C | \$ 1,343.00 | 10% | \$1,217.77 |
| EW TAC OS 7520-48XT-6C-AC-F | 97000-7520-48XT-6C-AC-F | \$ 1,343.00 | 10% | \$1,217.77 |
| EW TAC OS 7520-48XT-6C-AC-R | 97000-7520-48XT-6C-AC-R | \$ 1,343.00 | 10% | \$1,217.77 |
| EW TAC OS 7520-48Y-8C | 97000-7520-48Y-8C | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS 7520-48Y-8C-AC-F | 97000-7520-48Y-8C-AC-F | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS 7520-48Y-8C-AC-R | 97000-7520-48Y-8C-AC-R | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS 7520-48YE-8CE | 97000-7520-48YE-8CE | \$ 1,504.00 | 10% | \$1,363.75 |

| | | | | |
|------------------------------|--------------------------|-------------|-----|-------------------|
| EW TAC OS 7520-48YE-8CE-AC-F | 97000-7520-48YE-8CE-AC-F | \$ 1,504.00 | 10% | <i>\$1,363.75</i> |
| EW TAC OS 7520-48YE-8CE-AC-R | 97000-7520-48YE-8CE-AC-R | \$ 1,504.00 | 10% | <i>\$1,363.75</i> |
| EW TAC OS 7720-32C | 97000-7720-32C | \$ 1,640.00 | 10% | <i>\$1,487.07</i> |
| EW TAC OS 7720-32C-AC-F | 97000-7720-32C-AC-F | \$ 1,640.00 | 10% | <i>\$1,487.07</i> |
| EW TAC OS 7720-32C-AC-R | 97000-7720-32C-AC-R | \$ 1,640.00 | 10% | <i>\$1,487.07</i> |
| EW TAC OS 8000-PRMR-LIC-P | 97000-8000-PRMR-LIC-P | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW TAC OS 8520-48XT-6C | 97000-8520-48XT-6C | \$ 1,341.00 | 10% | <i>\$1,215.95</i> |
| EW TAC OS 8520-48XT-6C-AC-F | 97000-8520-48XT-6C-AC-F | \$ 1,341.00 | 10% | <i>\$1,215.95</i> |
| EW TAC OS 8520-48XT-6C-AC-R | 97000-8520-48XT-6C-AC-R | \$ 1,341.00 | 10% | <i>\$1,215.95</i> |
| EW TAC OS 8520-48XT-6C-DC-F | 97000-8520-48XT-6C-DC-F | \$ 1,341.00 | 10% | <i>\$1,215.95</i> |
| EW TAC OS 8520-48XT-6C-DC-R | 97000-8520-48XT-6C-DC-R | \$ 1,341.00 | 10% | <i>\$1,215.95</i> |
| EW TAC OS 8520-48Y-8C | 97000-8520-48Y-8C | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW TAC OS 8520-48Y-8C-AC-F | 97000-8520-48Y-8C-AC-F | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW TAC OS 8520-48Y-8C-AC-R | 97000-8520-48Y-8C-AC-R | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW TAC OS 8520-48Y-8C-DC-F | 97000-8520-48Y-8C-DC-F | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW TAC OS 8520-48Y-8C-DC-R | 97000-8520-48Y-8C-DC-R | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW TAC OS 86100 | 97000-86100 | \$ 3,355.00 | 10% | <i>\$3,042.15</i> |
| EW TAC OS 86101 | 97000-86101 | \$ 4,266.00 | 10% | <i>\$3,868.20</i> |
| EW TAC OS 87100 | 97000-87100 | \$ 1,985.00 | 10% | <i>\$1,799.90</i> |
| EW TAC OS 87101 | 97000-87101 | \$ 3,195.00 | 10% | <i>\$2,897.07</i> |

| | | | | |
|-------------------------|---------------------|--------------|-----|--------------------|
| EW TAC OS 8720-32C | 97000-8720-32C | \$ 1,568.00 | 10% | <i>\$1,421.78</i> |
| EW TAC OS 8720-32C-AC-F | 97000-8720-32C-AC-F | \$ 1,568.00 | 10% | <i>\$1,421.78</i> |
| EW TAC OS 8720-32C-AC-R | 97000-8720-32C-AC-R | \$ 1,568.00 | 10% | <i>\$1,421.78</i> |
| EW TAC OS 8720-32C-DC-F | 97000-8720-32C-DC-F | \$ 1,568.00 | 10% | <i>\$1,421.78</i> |
| EW TAC OS 8720-32C-DC-R | 97000-8720-32C-DC-R | \$ 1,568.00 | 10% | <i>\$1,421.78</i> |
| EW TAC SW 8806 | 97000-8806 | \$ 926.00 | 10% | <i>\$839.65</i> |
| EW TAC OS BD 8810 | 97000-8810 | \$ 2,412.00 | 10% | <i>\$2,187.08</i> |
| EW TAC OS 88100 | 97000-88100 | \$ 3,508.00 | 10% | <i>\$3,180.88</i> |
| EW TAC OS 8820-40C | 97000-8820-40C | \$ 7,755.00 | 10% | <i>\$7,031.85</i> |
| EW TAC OS 8820-40C-AC-F | 97000-8820-40C-AC-F | \$ 7,755.00 | 10% | <i>\$7,031.85</i> |
| EW TAC OS 8820-40C-AC-R | 97000-8820-40C-AC-R | \$ 7,755.00 | 10% | <i>\$7,031.85</i> |
| EW TAC OS 8820-40C-DC-F | 97000-8820-40C-DC-F | \$ 7,755.00 | 10% | <i>\$7,031.85</i> |
| EW TAC OS 8820-40C-DC-R | 97000-8820-40C-DC-R | \$ 7,755.00 | 10% | <i>\$7,031.85</i> |
| EW TAC OS 8820-80C | 97000-8820-80C | \$ 13,834.00 | 10% | <i>\$12,543.98</i> |
| EW TAC OS 8820-80C-AC-F | 97000-8820-80C-AC-F | \$ 13,834.00 | 10% | <i>\$12,543.98</i> |
| EW TAC OS 8820-80C-AC-R | 97000-8820-80C-AC-R | \$ 13,834.00 | 10% | <i>\$12,543.98</i> |
| EW TAC OS 8820-80C-DC-F | 97000-8820-80C-DC-F | \$ 13,834.00 | 10% | <i>\$12,543.98</i> |
| EW TAC OS 8820-80C-DC-R | 97000-8820-80C-DC-R | \$ 13,834.00 | 10% | <i>\$12,543.98</i> |
| EW TAC SW 88XOS | 97000-88XOS | \$ 2,207.00 | 10% | <i>\$2,001.20</i> |
| EW TAC OS 9920-16C | 97000-9920-16C | \$ 5,278.00 | 10% | <i>\$4,785.83</i> |
| EW TAC OS 9920-4D | 97000-9920-4D | \$ 5,278.00 | 10% | <i>\$4,785.83</i> |
| EW TAC OS 9920-NPB-8 | 97000-9920-NPB-8 | \$ 9,603.00 | 10% | <i>\$8,707.52</i> |
| EW Software and TAC | 97000-A10148 | \$ 1,766.00 | 10% | <i>\$1,601.32</i> |

| | | | | |
|-----------------------------|-------------------------|----------|-----|---------|
| EW TAC OS AH-AP-1130-AC-CE | 97000-AH-AP-1130-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-1130-AC-FCC | 97000-AH-AP-1130-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-1130-AC-W | 97000-AH-AP-1130-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-121-N-CE | 97000-AH-AP-121-N-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-121-N-FCC | 97000-AH-AP-121-N-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-121-N-W | 97000-AH-AP-121-N-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-121-N-W-NEC | 97000-AH-AP-121-N-W-NEC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122-AC-CAN | 97000-AH-AP-122-AC-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122-AC-CE | 97000-AH-AP-122-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122-AC-FCC | 97000-AH-AP-122-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122-AC-W | 97000-AH-AP-122-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122X-AC-CAN | 97000-AH-AP-122X-AC-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122X-AC-CE | 97000-AH-AP-122X-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122X-AC-FCC | 97000-AH-AP-122X-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-122X-AC-W | 97000-AH-AP-122X-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-130-AC-CE | 97000-AH-AP-130-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-130-AC-FCC | 97000-AH-AP-130-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-130-AC-W | 97000-AH-AP-130-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-141-N-CE | 97000-AH-AP-141-N-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-141-N-FCC | 97000-AH-AP-141-N-FCC | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|-----------------------------|-------------------------|----------|-----|---------|
| EW TAC OS AH-AP-141-N-W | 97000-AH-AP-141-N-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-141-N-W-NEC | 97000-AH-AP-141-N-W-NEC | \$ 37.00 | 10% | \$33.55 |
| EW TAC OS AH-AP-150W-AC-CAN | 97000-AH-AP-150W-AC-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-150W-AC-CE | 97000-AH-AP-150W-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-150W-AC-FCC | 97000-AH-AP-150W-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-150W-AC-W | 97000-AH-AP-150W-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-170-N-W | 97000-AH-AP-170-N-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-230-AC-CE | 97000-AH-AP-230-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-230-AC-FCC | 97000-AH-AP-230-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-230-AC-W | 97000-AH-AP-230-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-245X-AC-CAN | 97000-AH-AP-245X-AC-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-245X-AC-CE | 97000-AH-AP-245X-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-245X-AC-FCC | 97000-AH-AP-245X-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-245X-AC-W | 97000-AH-AP-245X-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-250-AC-CAN | 97000-AH-AP-250-AC-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-250-AC-CE | 97000-AH-AP-250-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-250-AC-FCC | 97000-AH-AP-250-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-250-AC-W | 97000-AH-AP-250-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-330-N-FCC | 97000-AH-AP-330-N-FCC | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|-----------------------------|-------------------------|----------|-----|---------|
| EW TAC OS AH-AP-330-N-W | 97000-AH-AP-330-N-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-350-N-FCC | 97000-AH-AP-350-N-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-350-N-W | 97000-AH-AP-350-N-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-370-AC-FCC | 97000-AH-AP-370-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-370-AC-W | 97000-AH-AP-370-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-390-AC-FCC | 97000-AH-AP-390-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-390-AC-W | 97000-AH-AP-390-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-550-AC-CAN | 97000-AH-AP-550-AC-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-550-AC-CE | 97000-AH-AP-550-AC-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-550-AC-FCC | 97000-AH-AP-550-AC-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-550-AC-W | 97000-AH-AP-550-AC-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-630-AX-CAN | 97000-AH-AP-630-AX-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-630-AX-CE | 97000-AH-AP-630-AX-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-630-AX-FCC | 97000-AH-AP-630-AX-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-630-AX-W | 97000-AH-AP-630-AX-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AH-AP-650-AX-CAN | 97000-AH-AP-650-AX-CAN | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AH-AP-650-AX-CE | 97000-AH-AP-650-AX-CE | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AH-AP-650-AX-FCC | 97000-AH-AP-650-AX-FCC | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AH-AP-650-AX-W | 97000-AH-AP-650-AX-W | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AH-AP-650X-AX-CAN | 97000-AH-AP-650X-AX-CAN | \$ 25.00 | 10% | \$22.67 |

| | | | | |
|-----------------------------|-------------------------|----------|-----|---------|
| EW TAC OS AH-AP-650X-AX-CE | 97000-AH-AP-650X-AX-CE | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AH-AP-650X-AX-FCC | 97000-AH-AP-650X-AX-FCC | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AH-AP-650X-AX-W | 97000-AH-AP-650X-AX-W | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AH-ATOM-CAN | 97000-AH-ATOM-CAN | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AH-ATOM-CE-EU | 97000-AH-ATOM-CE-EU | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AH-ATOM-CE-UK | 97000-AH-ATOM-CE-UK | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AH-ATOM-FCC | 97000-AH-ATOM-FCC | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AH-ATOM-W | 97000-AH-ATOM-W | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AH-ATOM-W-EU | 97000-AH-ATOM-W-EU | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AH-ATOM-W-UK | 97000-AH-ATOM-W-UK | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AH-BR-100-N-FCC | 97000-AH-BR-100-N-FCC | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-100-N-W | 97000-AH-BR-100-N-W | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-100-N-W-AU | 97000-AH-BR-100-N-W-AU | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-100-N-W-EU | 97000-AH-BR-100-N-W-EU | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-100-N-W-UK | 97000-AH-BR-100-N-W-UK | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-100-N-W-US | 97000-AH-BR-100-N-W-US | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-200 | 97000-AH-BR-200 | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-200WP-N-CE | 97000-AH-BR-200WP-N-CE | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-200WP-N-EU | 97000-AH-BR-200WP-N-EU | \$ 28.00 | 10% | \$25.39 |

| | | | | |
|-----------------------------|-------------------------|----------|-----|---------|
| EW TAC OS AH-BR-200WP-N-FCC | 97000-AH-BR-200WP-N-FCC | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-BR-200WP-N-W | 97000-AH-BR-200WP-N-W | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS AH-SR-2024P | 97000-AH-SR-2024P | \$ 26.00 | 10% | \$23.58 |
| EW TAC OS AH-SR-2124P | 97000-AH-SR-2124P | \$ 26.00 | 10% | \$23.58 |
| EW TAC OS AH-SR-2148P | 97000-AH-SR-2148P | \$ 26.00 | 10% | \$23.58 |
| EW TAC OS AH-SR-2208P-AU | 97000-AH-SR-2208P-AU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2208P-EU | 97000-AH-SR-2208P-EU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2208P-NA | 97000-AH-SR-2208P-NA | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2208P-UK | 97000-AH-SR-2208P-UK | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2224P-AU | 97000-AH-SR-2224P-AU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2224P-EU | 97000-AH-SR-2224P-EU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2224P-NA | 97000-AH-SR-2224P-NA | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2224P-UK | 97000-AH-SR-2224P-UK | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2324P-AU | 97000-AH-SR-2324P-AU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2324P-EU | 97000-AH-SR-2324P-EU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2324P-NA | 97000-AH-SR-2324P-NA | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2324P-UK | 97000-AH-SR-2324P-UK | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2348P-AU | 97000-AH-SR-2348P-AU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2348P-EU | 97000-AH-SR-2348P-EU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-SR-2348P-NA | 97000-AH-SR-2348P-NA | \$ 27.00 | 10% | \$24.48 |

| | | | | |
|-----------------------------|-------------------------|----------|-----|---------|
| EW TAC OS AH-SR-2348P-UK | 97000-AH-SR-2348P-UK | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR200P-AU | 97000-AH-XR200P-AU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR200P-EU | 97000-AH-XR200P-EU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR200P-UK | 97000-AH-XR200P-UK | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR200P-US | 97000-AH-XR200P-US | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR600P | 97000-AH-XR600P | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR600P-AU | 97000-AH-XR600P-AU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR600P-EU | 97000-AH-XR600P-EU | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR600P-KR | 97000-AH-XR600P-KR | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR600P-UK | 97000-AH-XR600P-UK | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AH-XR600P-US | 97000-AH-XR600P-US | \$ 27.00 | 10% | \$24.48 |
| EW TAC OS AP-8533-68SB30-IL | 97000-AP-8533-68SB30-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP3000-IL | 97000-AP3000-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP3000-TN | 97000-AP3000-TN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP3000-WW | 97000-AP3000-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP3000X-WW | 97000-AP3000X-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP302W-CAN | 97000-AP302W-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP302W-EG | 97000-AP302W-EG | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP302W-FCC | 97000-AP302W-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP302W-WR | 97000-AP302W-WR | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|------------------------|--------------------|----------|-----|---------|
| EW TAC OS AP305C-1-CAN | 97000-AP305C-1-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-1-EG | 97000-AP305C-1-EG | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-1-FCC | 97000-AP305C-1-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-1-IL | 97000-AP305C-1-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-1-WR | 97000-AP305C-1-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-CAN | 97000-AP305C-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-EG | 97000-AP305C-EG | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-FCC | 97000-AP305C-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-IL | 97000-AP305C-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305C-WR | 97000-AP305C-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305CX-CAN | 97000-AP305CX-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305CX-FCC | 97000-AP305CX-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305CX-IL | 97000-AP305CX-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP305CX-WR | 97000-AP305CX-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310e-1-WR | 97000-AP310e-1-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310e-CAN | 97000-AP310e-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310e-FCC | 97000-AP310e-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310e-IL | 97000-AP310e-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310e-WR | 97000-AP310e-WR | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|------------------------|--------------------|----------|-----|---------|
| EW TAC OS AP310i-1-WR | 97000-AP310i-1-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310i-CAN | 97000-AP310i-CAN | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AP310i-FCC | 97000-AP310i-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310i-IL | 97000-AP310i-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP310i-WR | 97000-AP310i-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP360e-CAN | 97000-AP360e-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP360e-FCC | 97000-AP360e-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP360e-IL | 97000-AP360e-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP360e-WR | 97000-AP360e-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP360i-CAN | 97000-AP360i-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP360i-FCC | 97000-AP360i-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP360i-WR | 97000-AP360i-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP4000-WW | 97000-AP4000-1-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP4000-IL | 97000-AP4000-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP4000-WW | 97000-AP4000-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-1-CAN | 97000-AP410C-1-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-1-EG | 97000-AP410C-1-EG | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-1-FCC | 97000-AP410C-1-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AAP410C-1-IL | 97000-AP410C-1-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-1-WR | 97000-AP410C-1-WR | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|------------------------|--------------------|----------|-----|---------|
| EW TAC OS AP410C-CAN | 97000-AP410C-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-EG | 97000-AP410C-EG | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-FCC | 97000-AP410C-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-IL | 97000-AP410C-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410C-WR | 97000-AP410C-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410e-CAN | 97000-AP410e-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410e-FCC | 97000-AP410e-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410e-WR | 97000-AP410e-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410i-1-FCC | 97000-AP410i-1-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410i-1-WR | 97000-AP410i-1-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410i-CAN | 97000-AP410i-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410i-FCC | 97000-AP410i-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410i-IL | 97000-AP410i-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP410i-WR | 97000-AP410i-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460C-CAN | 97000-AP460C-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460C-EG | 97000-AP460C-EG | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460C-FCC | 97000-AP460C-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460C-IL | 97000-AP460C-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460C-WR | 97000-AP460C-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460e-CAN | 97000-AP460e-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460e-FCC | 97000-AP460e-FCC | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|--------------------------|----------------------|----------|-----|---------|
| EW TAC OS AP460e-WR | 97000-AP460e-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460i-CAN | 97000-AP460i-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460i-FCC | 97000-AP460i-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460i-IL | 97000-AP460i-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460i-WR | 97000-AP460i-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460S12C-CAN | 97000-AP460S12C-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460S12C-FCC | 97000-AP460S12C-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460S12C-WR | 97000-AP460S12C-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460S6C-CAN | 97000-AP460S6C-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460S6C-FCC | 97000-AP460S6C-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP460S6C-WR | 97000-AP460S6C-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP5010-IL | 97000-AP5010-IL | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP5010-WW | 97000-AP5010-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP5020-WW | 97000-AP5020-WW | \$ 30.00 | 6% | \$28.41 |
| EW TAC OS AP5050D-WW | 97000-AP5050D-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP5050U-WW | 97000-AP5050U-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP505i-FCC | 97000-AP505i-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP505i-FCC-TAA | 97000-AP505i-FCC-TAA | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|--------------------------|----------------------|----------|-----|---------|
| EW TAC OS AP505i-WR | 97000-AP505i-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510C-CAN | 97000-AP510C-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510C-CE | 97000-AP510C-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510C-FCC | 97000-AP510C-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510C-W | 97000-AP510C-W | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510C-WW | 97000-AP510C-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510CX-CAN | 97000-AP510CX-CAN | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510CX-CE | 97000-AP510CX-CE | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510CX-FCC | 97000-AP510CX-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510CX-W | 97000-AP510CX-W | \$ 32.00 | 10% | \$29.02 |
| EW TAC OS AP510CX-WW | 97000-AP510CX-WW | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510e-FCC | 97000-AP510e-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510e-FCC-TAA | 97000-AP510e-FCC-TAA | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510e-WR | 97000-AP510e-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510i-1-FCC | 97000-AP510i-1-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510i-1-WR | 97000-AP510i-1-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510i-FCC | 97000-AP510i-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510i-FCC-TAA | 97000-AP510i-FCC-TAA | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP510i-WR | 97000-AP510i-WR | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|-------------------------------|---------------------------|-------------|-----|------------|
| EW TAC OS AP560h-FCC | 97000-AP560h-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP560h-WR | 97000-AP560h-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP560i-FCC | 97000-AP560i-FCC | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP560i-WR | 97000-AP560i-WR | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS AP560m-FCC | 97000-AP560m-FCC | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AP560t-FCC | 97000-AP560t-FCC | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS AP560u-FCC | 97000-AP560u-FCC | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS E2122 | 97000-E2122 | \$ 2,374.00 | 10% | \$2,152.62 |
| EW TAC OS E2122-1 | 97000-E2122-1 | \$ 2,250.00 | 10% | \$2,040.19 |
| EW TAC OS E3120-1 | 97000-E3120-1 | \$ 3,681.00 | 10% | \$3,337.75 |
| EW TAC OS E3125 | 97000-E3125 | \$ 3,973.00 | 10% | \$3,602.52 |
| EW TAC OS EXOS-AVB-FP-X435 | 97000-EXOS-AVB-FP-X435 | \$ 49.00 | 10% | \$44.43 |
| EW TAC OS EXOS-AVB-FP-X465 | 97000-EXOS-AVB-FP-X465 | \$ 90.00 | 10% | \$81.61 |
| EW TAC OS EXOS-CORE-FP-X695 | 97000-EXOS-CORE-FP-X695 | \$ 494.00 | 10% | \$447.93 |
| EW TAC OS EXOS-MACSEC-FP-X695 | 97000-EXOS-MACSEC-FP-X695 | \$ 106.00 | 10% | \$96.12 |
| EW Software and TAC | 97000-H30003 | \$ 29.00 | 10% | \$26.30 |
| EW Software and TAC | 97000-H30004 | \$ 36.00 | 10% | \$32.64 |
| EW Software and TAC | 97000-H30005 | \$ 33.00 | 10% | \$29.92 |
| EW Software and TAC | 97000-H30006 | \$ 63.00 | 10% | \$57.13 |
| EW Software and TAC | 97000-H30007 | \$ 57.00 | 10% | \$51.68 |
| EW Software and TAC | 97000-H30008 | \$ 106.00 | 10% | \$96.12 |
| EW Software and TAC | 97000-H30009 | \$ 29.00 | 10% | \$26.30 |
| EW Software and TAC | 97000-H30010 | \$ 52.00 | 10% | \$47.15 |
| EW Software and TAC | 97000-H30011 | \$ 44.00 | 10% | \$39.90 |
| EW Software and TAC | 97000-H30012 | \$ 73.00 | 10% | \$66.19 |
| EW Software and TAC | 97000-H30078 | \$ 1,242.00 | 10% | \$1,126.18 |
| EW Software and TAC | 97000-H30104 | \$ 1,148.00 | 10% | \$1,040.95 |
| EW Software and TAC | 97000-H30105 | \$ 1,105.00 | 10% | \$1,001.96 |
| EW Software and TAC | 97000-H30131 | \$ 625.00 | 10% | \$566.72 |

| | | | | |
|---------------------|--------------|-------------|-----|------------|
| EW Software and TAC | 97000-H30132 | \$ 612.00 | 10% | \$554.93 |
| EW Software and TAC | 97000-H30133 | \$ 1,601.00 | 10% | \$1,451.71 |
| EW Software and TAC | 97000-H30134 | \$ 2,029.00 | 10% | \$1,839.80 |
| EW Software and TAC | 97000-H30135 | \$ 1,633.00 | 10% | \$1,480.72 |
| EW Software and TAC | 97000-H30136 | \$ 2,029.00 | 10% | \$1,839.80 |
| EW Software and TAC | 97000-H30184 | \$ 33.00 | 10% | \$29.92 |
| EW Software and TAC | 97000-H30185 | \$ 152.00 | 10% | \$137.83 |
| EW Software and TAC | 97000-H30186 | \$ 77.00 | 10% | \$69.82 |
| EW Software and TAC | 97000-H30187 | \$ 35.00 | 10% | \$31.74 |
| EW Software and TAC | 97000-H30188 | \$ 77.00 | 10% | \$69.82 |
| EW Software and TAC | 97000-H30189 | \$ 77.00 | 10% | \$69.82 |
| EW Software and TAC | 97000-H30190 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30214 | \$ 83.00 | 10% | \$75.26 |
| EW Software and TAC | 97000-H30215 | \$ 83.00 | 10% | \$75.26 |
| EW Software and TAC | 97000-H30216 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30217 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30218 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30219 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30220 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30221 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30222 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30223 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30224 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30225 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30226 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30227 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30228 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30229 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30267 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30268 | \$ 162.00 | 10% | \$146.89 |
| EW Software and TAC | 97000-H30269 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30270 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30271 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30272 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30273 | \$ 336.00 | 10% | \$304.67 |
| EW Software and TAC | 97000-H30274 | \$ 336.00 | 10% | \$304.67 |
| EW Software and TAC | 97000-H30275 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30276 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30277 | \$ 336.00 | 10% | \$304.67 |
| EW Software and TAC | 97000-H30278 | \$ 365.00 | 10% | \$330.96 |
| EW Software and TAC | 97000-H30279 | \$ 336.00 | 10% | \$304.67 |
| EW Software and TAC | 97000-H30280 | \$ 336.00 | 10% | \$304.67 |

| | | | | |
|---------------------|--------------|-------------|-----|------------|
| EW Software and TAC | 97000-H30281 | \$ 336.00 | 10% | \$304.67 |
| EW Software and TAC | 97000-H30282 | \$ 336.00 | 10% | \$304.67 |
| EW Software and TAC | 97000-H30283 | \$ 226.00 | 10% | \$204.93 |
| EW Software and TAC | 97000-H30284 | \$ 249.00 | 10% | \$225.78 |
| EW Software and TAC | 97000-H30293 | \$ 1,335.00 | 10% | \$1,210.51 |
| EW Software and TAC | 97000-H30296 | \$ 83.00 | 10% | \$75.26 |
| EW Software and TAC | 97000-H30297 | \$ 83.00 | 10% | \$75.26 |
| EW Software and TAC | 97000-H30298 | \$ 83.00 | 10% | \$75.26 |
| EW Software and TAC | 97000-H30299 | \$ 83.00 | 10% | \$75.26 |
| EW Software and TAC | 97000-H30380 | \$ 2,179.00 | 10% | \$1,975.81 |
| EW Software and TAC | 97000-H30381 | \$ 222.00 | 10% | \$201.30 |
| EW Software and TAC | 97000-H30383 | \$ 1,008.00 | 10% | \$914.00 |
| EW Software and TAC | 97000-H30384 | \$ 176.00 | 10% | \$159.59 |
| EW Software and TAC | 97000-H30391 | \$ 423.00 | 10% | \$383.56 |
| EW Software and TAC | 97000-H30392 | \$ 423.00 | 10% | \$383.56 |
| EW Software and TAC | 97000-H30393 | \$ 192.00 | 10% | \$174.10 |
| EW Software and TAC | 97000-H30394 | \$ 810.00 | 10% | \$734.47 |
| EW Software and TAC | 97000-H30395 | \$ 963.00 | 10% | \$873.20 |
| EW Software and TAC | 97000-H30396 | \$ 880.00 | 10% | \$797.94 |
| EW Software and TAC | 97000-H30397 | \$ 1,047.00 | 10% | \$949.37 |
| EW Software and TAC | 97000-H30398 | \$ 196.00 | 10% | \$177.72 |
| EW Software and TAC | 97000-H30400 | \$ 109.00 | 10% | \$98.84 |
| EW Software and TAC | 97000-H30401 | \$ 150.00 | 10% | \$136.01 |
| EW Software and TAC | 97000-H30402 | \$ 161.00 | 10% | \$145.99 |
| EW Software and TAC | 97000-H30403 | \$ 237.00 | 10% | \$214.90 |
| EW Software and TAC | 97000-H30434 | \$ 68.00 | 10% | \$61.66 |
| EW Software and TAC | 97000-H30480 | \$ 275.00 | 10% | \$249.36 |
| EW Software and TAC | 97000-H30495 | \$ 625.00 | 10% | \$566.72 |
| EW Software and TAC | 97000-H30496 | \$ 612.00 | 10% | \$554.93 |
| EW Software and TAC | 97000-H30497 | \$ 898.00 | 10% | \$814.26 |
| EW Software and TAC | 97000-H30498 | \$ 880.00 | 10% | \$797.94 |
| EW Software and TAC | 97000-H30499 | \$ 299.00 | 10% | \$271.12 |
| EW Software and TAC | 97000-H30501 | \$ 880.00 | 10% | \$797.94 |
| EW Software and TAC | 97000-H30502 | \$ 1,353.00 | 10% | \$1,226.83 |
| EW Software and TAC | 97000-H30503 | \$ 299.00 | 10% | \$271.12 |
| EW Software and TAC | 97000-H30505 | \$ 1,601.00 | 10% | \$1,451.71 |
| EW Software and TAC | 97000-H30506 | \$ 2,182.00 | 10% | \$1,978.53 |
| EW Software and TAC | 97000-H30509 | \$ 1,353.00 | 10% | \$1,226.83 |
| EW Software and TAC | 97000-H30510 | \$ 1,601.00 | 10% | \$1,451.71 |
| EW Software and TAC | 97000-H30511 | \$ 2,182.00 | 10% | \$1,978.53 |
| EW Software and TAC | 97000-H30512 | \$ 299.00 | 10% | \$271.12 |
| EW Software and TAC | 97000-H30513 | \$ 508.00 | 10% | \$460.63 |

| | | | | |
|---------------------|--------------|-------------|-----|-------------------|
| EW Software and TAC | 97000-H30525 | \$ 2,182.00 | 10% | <i>\$1,978.53</i> |
| EW Software and TAC | 97000-H30526 | \$ 1,601.00 | 10% | <i>\$1,451.71</i> |
| EW Software and TAC | 97000-H30528 | \$ 2,533.00 | 10% | <i>\$2,296.80</i> |
| EW Software and TAC | 97000-H30531 | \$ 3,598.00 | 10% | <i>\$3,262.49</i> |
| EW Software and TAC | 97000-H30532 | \$ 3,598.00 | 10% | <i>\$3,262.49</i> |
| EW Software and TAC | 97000-H30534 | \$ 3,668.00 | 10% | <i>\$3,325.96</i> |
| EW Software and TAC | 97000-H30535 | \$ 3,908.00 | 10% | <i>\$3,543.58</i> |
| EW Software and TAC | 97000-H30536 | \$ 3,598.00 | 10% | <i>\$3,262.49</i> |
| EW Software and TAC | 97000-H30537 | \$ 3,908.00 | 10% | <i>\$3,543.58</i> |
| EW Software and TAC | 97000-H30538 | \$ 2,182.00 | 10% | <i>\$1,978.53</i> |
| EW Software and TAC | 97000-H30539 | \$ 4,176.00 | 10% | <i>\$3,786.59</i> |
| EW Software and TAC | 97000-H30540 | \$ 4,318.00 | 10% | <i>\$3,915.35</i> |
| EW Software and TAC | 97000-H30543 | \$ 294.00 | 10% | <i>\$266.58</i> |
| EW Software and TAC | 97000-H30544 | \$ 524.00 | 10% | <i>\$475.14</i> |
| EW Software and TAC | 97000-H30548 | \$ 294.00 | 10% | <i>\$266.58</i> |
| EW Software and TAC | 97000-H30549 | \$ 499.00 | 10% | <i>\$452.47</i> |
| EW Software and TAC | 97000-H30550 | \$ 499.00 | 10% | <i>\$452.47</i> |
| EW Software and TAC | 97000-H30552 | \$ 294.00 | 10% | <i>\$266.58</i> |
| EW Software and TAC | 97000-H30553 | \$ 466.00 | 10% | <i>\$422.55</i> |
| EW Software and TAC | 97000-H30569 | \$ 1,601.00 | 10% | <i>\$1,451.71</i> |
| EW Software and TAC | 97000-H30570 | \$ 1,924.00 | 10% | <i>\$1,744.59</i> |
| EW Software and TAC | 97000-H30571 | \$ 1,924.00 | 10% | <i>\$1,744.59</i> |
| EW Software and TAC | 97000-H30573 | \$ 1,601.00 | 10% | <i>\$1,451.71</i> |
| EW Software and TAC | 97000-H30574 | \$ 1,775.00 | 10% | <i>\$1,609.48</i> |
| EW Software and TAC | 97000-H30575 | \$ 1,105.00 | 10% | <i>\$1,001.96</i> |
| EW Software and TAC | 97000-H30576 | \$ 1,601.00 | 10% | <i>\$1,451.71</i> |
| EW Software and TAC | 97000-H30577 | \$ 1,924.00 | 10% | <i>\$1,744.59</i> |
| EW Software and TAC | 97000-H30578 | \$ 1,924.00 | 10% | <i>\$1,744.59</i> |
| EW Software and TAC | 97000-H30587 | \$ 1,633.00 | 10% | <i>\$1,480.72</i> |
| EW Software and TAC | 97000-H30588 | \$ 1,125.00 | 10% | <i>\$1,020.09</i> |
| EW Software and TAC | 97000-H30589 | \$ 1,745.00 | 10% | <i>\$1,582.28</i> |
| EW Software and TAC | 97000-H30632 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Software and TAC | 97000-H30633 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Software and TAC | 97000-H30643 | \$ 2,752.00 | 10% | <i>\$2,495.38</i> |
| EW Software and TAC | 97000-H30706 | \$ 2,581.00 | 10% | <i>\$2,340.32</i> |
| EW Software and TAC | 97000-H30707 | \$ 1,601.00 | 10% | <i>\$1,451.71</i> |
| EW Software and TAC | 97000-H30724 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Software and TAC | 97000-H30725 | \$ 612.00 | 10% | <i>\$554.93</i> |
| EW Software and TAC | 97000-H30726 | \$ 3,986.00 | 10% | <i>\$3,614.31</i> |
| EW Software and TAC | 97000-H30727 | \$ 4,235.00 | 10% | <i>\$3,840.09</i> |
| EW Software and TAC | 97000-H30730 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Software and TAC | 97000-H30731 | \$ 30.00 | 10% | <i>\$27.20</i> |

| | | | | |
|---------------------------|--------------|-------------|-----|------------|
| EW TAC OS 30732 | 97000-H30732 | \$ 970.00 | 10% | \$879.55 |
| EW TAC OS SKL8008-0810-F8 | 97000-H30733 | \$ 3,745.00 | 10% | \$3,395.78 |
| EW TAC OS STL2006-0850 | 97000-H30734 | \$ 2,857.00 | 10% | \$2,590.58 |
| EW TAC OS SGL2001-0850 | 97000-H30735 | \$ 3,329.00 | 10% | \$3,018.57 |
| EW TAC OS SOK2209-0204 | 97000-H30736 | \$ 524.00 | 10% | \$475.14 |
| EW TAC OS H30738 | 97000-H30738 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS-H30739 | 97000-H30739 | \$ 552.00 | 10% | \$500.53 |
| EW TAC OS-H30740 | 97000-H30740 | \$ 320.00 | 10% | \$290.16 |
| EW TAC OS-H30741 | 97000-H30741 | \$ 592.00 | 10% | \$536.80 |
| EW TAC OS-H30742 | 97000-H30742 | \$ 527.00 | 10% | \$477.86 |
| EW TAC OS-H30743 | 97000-H30743 | \$ 552.00 | 10% | \$500.53 |
| EW TAC OS-H30744 | 97000-H30744 | \$ 320.00 | 10% | \$290.16 |
| EW TAC OS-H30745 | 97000-H30745 | \$ 327.00 | 10% | \$296.51 |
| EW TAC OS-H30746 | 97000-H30746 | \$ 592.00 | 10% | \$536.80 |
| EW TAC OS-H30747 | 97000-H30747 | \$ 1,155.00 | 10% | \$1,047.30 |
| EW TAC OS-H30748 | 97000-H30748 | \$ 1,718.00 | 10% | \$1,557.80 |
| EW TAC OS-H30749 | 97000-H30749 | \$ 3,849.00 | 10% | \$3,490.08 |
| EW TAC OS-H30750 | 97000-H30750 | \$ 3,849.00 | 10% | \$3,490.08 |
| EW TAC OS-H30751 | 97000-H30751 | \$ 2,291.00 | 10% | \$2,077.36 |
| EW TAC OS-H30754 | 97000-H30754 | \$ 3,849.00 | 10% | \$3,490.08 |
| EW TAC OS-H30755 | 97000-H30755 | \$ 4,186.00 | 10% | \$3,795.66 |
| EW TAC OS-H30756 | 97000-H30756 | \$ 3,849.00 | 10% | \$3,490.08 |
| EW TAC OS-H30757 | 97000-H30757 | \$ 1,718.00 | 10% | \$1,557.80 |
| EW TAC OS-H30758 | 97000-H30758 | \$ 3,063.00 | 10% | \$2,777.38 |
| EW TAC OS-H30759 | 97000-H30759 | \$ 3,499.00 | 10% | \$3,172.72 |
| EW TAC OS-H30760 | 97000-H30760 | \$ 3,933.00 | 10% | \$3,566.25 |
| EW TAC OS-H30761 | 97000-H30761 | \$ 1,718.00 | 10% | \$1,557.80 |
| EW TAC OS-H30762 | 97000-H30762 | \$ 4,186.00 | 10% | \$3,795.66 |
| EW TAC OS-H30763 | 97000-H30763 | \$ 4,186.00 | 10% | \$3,795.66 |
| EW TAC OS-H30764 | 97000-H30764 | \$ 2,652.00 | 10% | \$2,404.70 |
| EW TAC OS-H30765 | 97000-H30765 | \$ 2,334.00 | 10% | \$2,116.35 |
| EW TAC OS-H30766 | 97000-H30766 | \$ 4,532.00 | 10% | \$4,109.39 |
| EW TAC OS-H30767 | 97000-H30767 | \$ 2,652.00 | 10% | \$2,404.70 |
| EW TAC OS H30769 | 97000-H30769 | \$ 1,231.00 | 10% | \$1,116.21 |
| EW TAC OS H30773 | 97000-H30773 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30774 | 97000-H30774 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30775 | 97000-H30775 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30776 | 97000-H30776 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30777 | 97000-H30777 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30778 | 97000-H30778 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30779 | 97000-H30779 | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H30780 | 97000-H30780 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30781 | 97000-H30781 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30782 | 97000-H30782 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30783 | 97000-H30783 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30784 | 97000-H30784 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30785 | 97000-H30785 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30786 | 97000-H30786 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30787 | 97000-H30787 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30788 | 97000-H30788 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30789 | 97000-H30789 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30790 | 97000-H30790 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30791 | 97000-H30791 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30793 | 97000-H30793 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30794 | 97000-H30794 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30795 | 97000-H30795 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30796 | 97000-H30796 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30797 | 97000-H30797 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30798 | 97000-H30798 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30799 | 97000-H30799 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30800 | 97000-H30800 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30801 | 97000-H30801 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30802 | 97000-H30802 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30803 | 97000-H30803 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30804 | 97000-H30804 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30805 | 97000-H30805 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30806 | 97000-H30806 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30807 | 97000-H30807 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30808 | 97000-H30808 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30809 | 97000-H30809 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30810 | 97000-H30810 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30811 | 97000-H30811 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30812 | 97000-H30812 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30813 | 97000-H30813 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30814 | 97000-H30814 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30815 | 97000-H30815 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30816 | 97000-H30816 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30817 | 97000-H30817 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30818 | 97000-H30818 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30819 | 97000-H30819 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30820 | 97000-H30820 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30821 | 97000-H30821 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30822 | 97000-H30822 | \$ 30.00 | 10% | \$27.20 |

| | | | | | |
|------------------|--------------|----|-------|-----|---------|
| EW TAC OS H30823 | 97000-H30823 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30824 | 97000-H30824 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30825 | 97000-H30825 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30826 | 97000-H30826 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30827 | 97000-H30827 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30828 | 97000-H30828 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30829 | 97000-H30829 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30830 | 97000-H30830 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30831 | 97000-H30831 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30838 | 97000-H30838 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30839 | 97000-H30839 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30840 | 97000-H30840 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30841 | 97000-H30841 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30842 | 97000-H30842 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30843 | 97000-H30843 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30844 | 97000-H30844 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30845 | 97000-H30845 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30846 | 97000-H30846 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30847 | 97000-H30847 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30848 | 97000-H30848 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30849 | 97000-H30849 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30850 | 97000-H30850 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30851 | 97000-H30851 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30852 | 97000-H30852 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30853 | 97000-H30853 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30854 | 97000-H30854 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30855 | 97000-H30855 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30856 | 97000-H30856 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30857 | 97000-H30857 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30858 | 97000-H30858 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30859 | 97000-H30859 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30860 | 97000-H30860 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30866 | 97000-H30866 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30867 | 97000-H30867 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30868 | 97000-H30868 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30869 | 97000-H30869 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30870 | 97000-H30870 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30871 | 97000-H30871 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30872 | 97000-H30872 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30873 | 97000-H30873 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30874 | 97000-H30874 | \$ | 30.00 | 10% | \$27.20 |
| EW TAC OS H30875 | 97000-H30875 | \$ | 30.00 | 10% | \$27.20 |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H30876 | 97000-H30876 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30877 | 97000-H30877 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30878 | 97000-H30878 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30891 | 97000-H30891 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30892 | 97000-H30892 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30893 | 97000-H30893 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30894 | 97000-H30894 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30895 | 97000-H30895 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30913 | 97000-H30913 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30914 | 97000-H30914 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30915 | 97000-H30915 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30916 | 97000-H30916 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30917 | 97000-H30917 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30918 | 97000-H30918 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30946 | 97000-H30946 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30948 | 97000-H30948 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30950 | 97000-H30950 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30951 | 97000-H30951 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30952 | 97000-H30952 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30956 | 97000-H30956 | \$ 33.00 | 10% | \$29.92 |
| EW TAC OS H30966 | 97000-H30966 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30967 | 97000-H30967 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30968 | 97000-H30968 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30969 | 97000-H30969 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30970 | 97000-H30970 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30971 | 97000-H30971 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30972 | 97000-H30972 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30973 | 97000-H30973 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30974 | 97000-H30974 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30975 | 97000-H30975 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30976 | 97000-H30976 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30977 | 97000-H30977 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H30978 | 97000-H30978 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31040 | 97000-H31040 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31041 | 97000-H31041 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31042 | 97000-H31042 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31047 | 97000-H31047 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31060 | 97000-H31060 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31062 | 97000-H31062 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31066 | 97000-H31066 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31068 | 97000-H31068 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31076 | 97000-H31076 | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|------------------|--------------|-------------|-----|------------|
| EW TAC OS H31077 | 97000-H31077 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31078 | 97000-H31078 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31119 | 97000-H31119 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31124 | 97000-H31124 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31127 | 97000-H31127 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31132 | 97000-H31132 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31134 | 97000-H31134 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31135 | 97000-H31135 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31136 | 97000-H31136 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31137 | 97000-H31137 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31185 | 97000-H31185 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H31192 | 97000-H31192 | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS H31193 | 97000-H31193 | \$ 25.00 | 10% | \$22.67 |
| EW TAC OS H31194 | 97000-H31194 | \$ 23.00 | 10% | \$20.86 |
| EW TAC OS H31197 | 97000-H31197 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31198 | 97000-H31198 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31199 | 97000-H31199 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31200 | 97000-H31200 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31201 | 97000-H31201 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31202 | 97000-H31202 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31203 | 97000-H31203 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31204 | 97000-H31204 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31205 | 97000-H31205 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31206 | 97000-H31206 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31207 | 97000-H31207 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31208 | 97000-H31208 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31335 | 97000-H31335 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31337 | 97000-H31337 | \$ 4,149.00 | 10% | \$3,762.11 |
| EW TAC OS H31338 | 97000-H31338 | \$ 4,149.00 | 10% | \$3,762.11 |
| EW TAC OS H31339 | 97000-H31339 | \$ 655.00 | 10% | \$593.92 |
| EW TAC OS H31340 | 97000-H31340 | \$ 1,409.00 | 10% | \$1,277.61 |
| EW TAC OS H31341 | 97000-H31341 | \$ 2,136.00 | 10% | \$1,936.82 |
| EW TAC OS H31342 | 97000-H31342 | \$ 672.00 | 10% | \$609.34 |
| EW TAC OS H31343 | 97000-H31343 | \$ 996.00 | 10% | \$903.12 |
| EW TAC OS H31344 | 97000-H31344 | \$ 996.00 | 10% | \$903.12 |
| EW TAC OS H31345 | 97000-H31345 | \$ 996.00 | 10% | \$903.12 |
| EW TAC OS H31346 | 97000-H31346 | \$ 996.00 | 10% | \$903.12 |
| EW TAC OS H31348 | 97000-H31348 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31349 | 97000-H31349 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31350 | 97000-H31350 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31351 | 97000-H31351 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31352 | 97000-H31352 | \$ 30.00 | 10% | \$27.20 |

| | | | | |
|------------------|--------------|--------------|-----|------------|
| EW TAC OS H31353 | 97000-H31353 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31354 | 97000-H31354 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31355 | 97000-H31355 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31356 | 97000-H31356 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31357 | 97000-H31357 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31358 | 97000-H31358 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31359 | 97000-H31359 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31360 | 97000-H31360 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31362 | 97000-H31362 | \$ 4,676.00 | 10% | \$4,239.96 |
| EW TAC OS H31363 | 97000-H31363 | \$ 4,676.00 | 10% | \$4,239.96 |
| EW TAC OS H31364 | 97000-H31364 | \$ 1,635.00 | 10% | \$1,482.54 |
| EW TAC OS H31365 | 97000-H31365 | \$ 1,635.00 | 10% | \$1,482.54 |
| EW TAC OS H31366 | 97000-H31366 | \$ 4,533.00 | 10% | \$4,110.30 |
| EW TAC OS H31367 | 97000-H31367 | \$ 4,533.00 | 10% | \$4,110.30 |
| EW TAC OS H31368 | 97000-H31368 | \$ 201.00 | 10% | \$182.26 |
| EW TAC OS H31369 | 97000-H31369 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31370 | 97000-H31370 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H31373 | 97000-H31373 | \$ 3,783.00 | 10% | \$3,430.24 |
| EW TAC OS H31393 | 97000-H31393 | \$ 30.00 | 10% | \$27.20 |
| EW TAC OS H32010 | 97000-H32010 | \$ 138.00 | 10% | \$125.13 |
| EW TAC OS H32011 | 97000-H32011 | \$ 138.00 | 10% | \$125.13 |
| EW TAC OS H32012 | 97000-H32012 | \$ 584.00 | 10% | \$529.54 |
| EW TAC OS H32013 | 97000-H32013 | \$ 584.00 | 10% | \$529.54 |
| EW TAC OS H32014 | 97000-H32014 | \$ 584.00 | 10% | \$529.54 |
| EW TAC OS H32015 | 97000-H32015 | \$ 584.00 | 10% | \$529.54 |
| EW TAC OS H32016 | 97000-H32016 | \$ 495.00 | 10% | \$448.84 |
| EW TAC OS H32017 | 97000-H32017 | \$ 495.00 | 10% | \$448.84 |
| EW TAC OS H32018 | 97000-H32018 | \$ 495.00 | 10% | \$448.84 |
| EW TAC OS H32019 | 97000-H32019 | \$ 495.00 | 10% | \$448.84 |
| EW TAC OS H32020 | 97000-H32020 | \$ 5,112.00 | 10% | \$4,635.31 |
| EW TAC OS H32021 | 97000-H32021 | \$ 5,112.00 | 10% | \$4,635.31 |
| EW TAC OS H32022 | 97000-H32022 | \$ 5,112.00 | 10% | \$4,635.31 |
| EW TAC OS H32023 | 97000-H32023 | \$ 5,112.00 | 10% | \$4,635.31 |
| EW TAC OS H32028 | 97000-H32028 | \$ 9,454.00 | 10% | \$8,572.41 |
| EW TAC OS H32029 | 97000-H32029 | \$ 9,454.00 | 10% | \$8,572.41 |
| EW TAC OS H32030 | 97000-H32030 | \$ 10,338.00 | 10% | \$9,373.98 |
| EW TAC OS H32031 | 97000-H32031 | \$ 10,338.00 | 10% | \$9,373.98 |
| EW TAC OS H32032 | 97000-H32032 | \$ 10,338.00 | 10% | \$9,373.98 |
| EW TAC OS H32033 | 97000-H32033 | \$ 10,338.00 | 10% | \$9,373.98 |
| EW TAC OS H32038 | 97000-H32038 | \$ 1,788.00 | 10% | \$1,621.27 |
| EW TAC OS H32039 | 97000-H32039 | \$ 1,788.00 | 10% | \$1,621.27 |
| EW TAC OS H32040 | 97000-H32040 | \$ 1,788.00 | 10% | \$1,621.27 |

| | | | | |
|------------------|--------------|-------------|-----|------------|
| EW TAC OS H32041 | 97000-H32041 | \$ 1,788.00 | 10% | \$1,621.27 |
| EW TAC OS H32042 | 97000-H32042 | \$ 2,213.00 | 10% | \$2,006.64 |
| EW TAC OS H32046 | 97000-H32046 | \$ 2,479.00 | 10% | \$2,247.83 |
| EW TAC OS H32047 | 97000-H32047 | \$ 2,479.00 | 10% | \$2,247.83 |
| EW TAC OS H32048 | 97000-H32048 | \$ 2,479.00 | 10% | \$2,247.83 |
| EW TAC OS H32049 | 97000-H32049 | \$ 2,479.00 | 10% | \$2,247.83 |
| EW TAC OS H32050 | 97000-H32050 | \$ 3,076.00 | 10% | \$2,789.16 |
| EW TAC OS H32051 | 97000-H32051 | \$ 3,076.00 | 10% | \$2,789.16 |
| EW TAC OS H32054 | 97000-H32054 | \$ 1,788.00 | 10% | \$1,621.27 |
| EW TAC OS H32055 | 97000-H32055 | \$ 2,479.00 | 10% | \$2,247.83 |
| EW TAC OS H32056 | 97000-H32056 | \$ 531.00 | 10% | \$481.48 |
| EW TAC OS H32057 | 97000-H32057 | \$ 531.00 | 10% | \$481.48 |
| EW TAC OS H32058 | 97000-H32058 | \$ 531.00 | 10% | \$481.48 |
| EW TAC OS H32059 | 97000-H32059 | \$ 531.00 | 10% | \$481.48 |
| EW TAC OS H32060 | 97000-H32060 | \$ 692.00 | 10% | \$627.47 |
| EW TAC OS H32061 | 97000-H32061 | \$ 727.00 | 10% | \$659.21 |
| EW TAC OS H32062 | 97000-H32062 | \$ 698.00 | 10% | \$632.91 |
| EW TAC OS H32063 | 97000-H32063 | \$ 692.00 | 10% | \$627.47 |
| EW TAC OS H32064 | 97000-H32064 | \$ 698.00 | 10% | \$632.91 |
| EW TAC OS H32065 | 97000-H32065 | \$ 1,652.00 | 10% | \$1,497.95 |
| EW TAC OS H32066 | 97000-H32066 | \$ 1,652.00 | 10% | \$1,497.95 |
| EW TAC OS H32067 | 97000-H32067 | \$ 1,652.00 | 10% | \$1,497.95 |
| EW TAC OS H32068 | 97000-H32068 | \$ 1,652.00 | 10% | \$1,497.95 |
| EW TAC OS H32069 | 97000-H32069 | \$ 2,062.00 | 10% | \$1,869.72 |
| EW TAC OS H32070 | 97000-H32070 | \$ 2,062.00 | 10% | \$1,869.72 |
| EW TAC OS H32071 | 97000-H32071 | \$ 2,062.00 | 10% | \$1,869.72 |
| EW TAC OS H32072 | 97000-H32072 | \$ 2,062.00 | 10% | \$1,869.72 |
| EW TAC OS H32073 | 97000-H32073 | \$ 7,261.00 | 10% | \$6,583.91 |
| EW TAC OS H32074 | 97000-H32074 | \$ 7,261.00 | 10% | \$6,583.91 |
| EW TAC OS H32075 | 97000-H32075 | \$ 9,871.00 | 10% | \$8,950.53 |
| EW TAC OS H32076 | 97000-H32076 | \$ 9,871.00 | 10% | \$8,950.53 |
| EW TAC OS H32090 | 97000-H32090 | \$ 941.00 | 10% | \$853.25 |
| EW TAC OS H32097 | 97000-H32097 | \$ 2,235.00 | 10% | \$2,026.59 |
| EW TAC OS H32101 | 97000-H32101 | \$ 322.00 | 10% | \$291.97 |
| EW TAC OS H32102 | 97000-H32102 | \$ 322.00 | 10% | \$291.97 |
| EW TAC OS H32103 | 97000-H32103 | \$ 322.00 | 10% | \$291.97 |
| EW TAC OS H32104 | 97000-H32104 | \$ 322.00 | 10% | \$291.97 |
| EW TAC OS H32105 | 97000-H32105 | \$ 638.00 | 10% | \$578.51 |
| EW TAC OS H32106 | 97000-H32106 | \$ 638.00 | 10% | \$578.51 |
| EW TAC OS H32107 | 97000-H32107 | \$ 1,734.00 | 10% | \$1,572.30 |
| EW TAC OS H32108 | 97000-H32108 | \$ 1,734.00 | 10% | \$1,572.30 |
| EW TAC OS H32109 | 97000-H32109 | \$ 638.00 | 10% | \$578.51 |

| | | | | |
|------------------|--------------|-------------|-----|-------------------|
| EW TAC OS H32110 | 97000-H32110 | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW TAC OS H32111 | 97000-H32111 | \$ 322.00 | 10% | <i>\$291.97</i> |
| EW TAC OS H32112 | 97000-H32112 | \$ 322.00 | 10% | <i>\$291.97</i> |
| EW TAC OS H32113 | 97000-H32113 | \$ 322.00 | 10% | <i>\$291.97</i> |
| EW TAC OS H32114 | 97000-H32114 | \$ 322.00 | 10% | <i>\$291.97</i> |
| EW TAC OS H32115 | 97000-H32115 | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW TAC OS H32116 | 97000-H32116 | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW TAC OS H32117 | 97000-H32117 | \$ 308.00 | 10% | <i>\$279.28</i> |
| EW TAC OS H32118 | 97000-H32118 | \$ 308.00 | 10% | <i>\$279.28</i> |
| EW TAC OS H32119 | 97000-H32119 | \$ 308.00 | 10% | <i>\$279.28</i> |
| EW TAC OS H32120 | 97000-H32120 | \$ 308.00 | 10% | <i>\$279.28</i> |
| EW TAC OS H32121 | 97000-H32121 | \$ 1,734.00 | 10% | <i>\$1,572.30</i> |
| EW TAC OS H32122 | 97000-H32122 | \$ 1,734.00 | 10% | <i>\$1,572.30</i> |
| EW TAC OS H32123 | 97000-H32123 | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW TAC OS H32124 | 97000-H32124 | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW TAC OS H32125 | 97000-H32125 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32126 | 97000-H32126 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32127 | 97000-H32127 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW TAC OS H32128 | 97000-H32128 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW TAC OS H32129 | 97000-H32129 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW TAC OS H32130 | 97000-H32130 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW TAC OS H32131 | 97000-H32131 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW TAC OS H32132 | 97000-H32132 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW TAC OS H32133 | 97000-H32133 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32134 | 97000-H32134 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32135 | 97000-H32135 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32136 | 97000-H32136 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32137 | 97000-H32137 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32138 | 97000-H32138 | \$ 635.00 | 10% | <i>\$575.79</i> |
| EW TAC OS H32139 | 97000-H32139 | \$ 2,681.00 | 10% | <i>\$2,431.00</i> |
| EW TAC OS H32140 | 97000-H32140 | \$ 2,681.00 | 10% | <i>\$2,431.00</i> |
| EW TAC OS H32141 | 97000-H32141 | \$ 3,088.00 | 10% | <i>\$2,800.04</i> |
| EW TAC OS H32142 | 97000-H32142 | \$ 3,088.00 | 10% | <i>\$2,800.04</i> |
| EW TAC OS H32143 | 97000-H32143 | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW TAC OS H32144 | 97000-H32144 | \$ 166.00 | 10% | <i>\$150.52</i> |
| EW TAC OS H32146 | 97000-H32146 | \$ 285.00 | 10% | <i>\$258.42</i> |
| EW TAC OS H32147 | 97000-H32147 | \$ 285.00 | 10% | <i>\$258.42</i> |
| EW TAC OS H32148 | 97000-H32148 | \$ 579.00 | 10% | <i>\$525.01</i> |
| EW TAC OS H32149 | 97000-H32149 | \$ 579.00 | 10% | <i>\$525.01</i> |
| EW TAC OS H32150 | 97000-H32150 | \$ 285.00 | 10% | <i>\$258.42</i> |
| EW TAC OS H32151 | 97000-H32151 | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW TAC OS H32152 | 97000-H32152 | \$ 172.00 | 10% | <i>\$155.96</i> |

| | | | | |
|------------------|--------------|-------------|-----|------------|
| EW TAC OS H32154 | 97000-H32154 | \$ 266.00 | 10% | \$241.20 |
| EW TAC OS H32169 | 97000-H32169 | \$ 314.00 | 10% | \$284.72 |
| EW TAC OS H32170 | 97000-H32170 | \$ 314.00 | 10% | \$284.72 |
| EW TAC OS H32171 | 97000-H32171 | \$ 299.00 | 10% | \$271.12 |
| EW TAC OS H32172 | 97000-H32172 | \$ 299.00 | 10% | \$271.12 |
| EW TAC OS H32173 | 97000-H32173 | \$ 779.00 | 10% | \$706.36 |
| EW TAC OS H32174 | 97000-H32174 | \$ 779.00 | 10% | \$706.36 |
| EW TAC OS H32175 | 97000-H32175 | \$ 663.00 | 10% | \$601.18 |
| EW TAC OS H32176 | 97000-H32176 | \$ 663.00 | 10% | \$601.18 |
| EW TAC OS H32177 | 97000-H32177 | \$ 3,026.00 | 10% | \$2,743.83 |
| EW TAC OS H32178 | 97000-H32178 | \$ 3,493.00 | 10% | \$3,167.28 |
| EW TAC OS H34008 | 97000-H34008 | \$ 28.00 | 10% | \$25.39 |
| EW TAC OS H34009 | 97000-H34009 | \$ 76.00 | 10% | \$68.91 |
| EW TAC OS H34010 | 97000-H34010 | \$ 33.00 | 10% | \$29.92 |
| EW TAC OS H34011 | 97000-H34011 | \$ 66.00 | 10% | \$59.85 |
| EW TAC OS H34012 | 97000-H34012 | \$ 119.00 | 10% | \$107.90 |
| EW TAC OS H34013 | 97000-H34013 | \$ 47.00 | 10% | \$42.62 |
| EW TAC OS H34014 | 97000-H34014 | \$ 76.00 | 10% | \$68.91 |
| EW TAC OS H34015 | 97000-H34015 | \$ 38.00 | 10% | \$34.46 |
| EW TAC OS H34016 | 97000-H34016 | \$ 86.00 | 10% | \$77.98 |
| EW TAC OS H34017 | 97000-H34017 | \$ 140.00 | 10% | \$126.95 |
| EW TAC OS H34018 | 97000-H34018 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34019 | 97000-H34019 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34020 | 97000-H34020 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34021 | 97000-H34021 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34048 | 97000-H34048 | \$ 198.00 | 10% | \$179.54 |
| EW TAC OS H34049 | 97000-H34049 | \$ 198.00 | 10% | \$179.54 |
| EW TAC OS H34050 | 97000-H34050 | \$ 142.00 | 10% | \$128.76 |
| EW TAC OS H34051 | 97000-H34051 | \$ 142.00 | 10% | \$128.76 |
| EW TAC OS H34052 | 97000-H34052 | \$ 227.00 | 10% | \$205.83 |
| EW TAC OS H34053 | 97000-H34053 | \$ 227.00 | 10% | \$205.83 |
| EW TAC OS H34054 | 97000-H34054 | \$ 171.00 | 10% | \$155.05 |
| EW TAC OS H34055 | 97000-H34055 | \$ 171.00 | 10% | \$155.05 |
| EW TAC OS H34056 | 97000-H34056 | \$ 254.00 | 10% | \$230.31 |
| EW TAC OS H34057 | 97000-H34057 | \$ 254.00 | 10% | \$230.31 |
| EW TAC OS H34058 | 97000-H34058 | \$ 225.00 | 10% | \$204.02 |
| EW TAC OS H34059 | 97000-H34059 | \$ 225.00 | 10% | \$204.02 |
| EW TAC OS H34062 | 97000-H34062 | \$ 254.00 | 10% | \$230.31 |
| EW TAC OS H34063 | 97000-H34063 | \$ 254.00 | 10% | \$230.31 |
| EW TAC OS H34064 | 97000-H34064 | \$ 174.00 | 10% | \$157.77 |
| EW TAC OS H34065 | 97000-H34065 | \$ 174.00 | 10% | \$157.77 |
| EW TAC OS H34066 | 97000-H34066 | \$ 174.00 | 10% | \$157.77 |

| | | | | |
|------------------|--------------|-------------|-----|------------|
| EW TAC OS H34067 | 97000-H34067 | \$ 174.00 | 10% | \$157.77 |
| EW TAC OS H34068 | 97000-H34068 | \$ 174.00 | 10% | \$157.77 |
| EW TAC OS H34069 | 97000-H34069 | \$ 170.00 | 10% | \$154.15 |
| EW TAC OS H34070 | 97000-H34070 | \$ 174.00 | 10% | \$157.77 |
| EW TAC OS H34071 | 97000-H34071 | \$ 174.00 | 10% | \$157.77 |
| EW TAC OS H34072 | 97000-H34072 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H34073 | 97000-H34073 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H34074 | 97000-H34074 | \$ 2,126.00 | 10% | \$1,927.75 |
| EW TAC OS H34075 | 97000-H34075 | \$ 1,968.00 | 10% | \$1,784.48 |
| EW TAC OS H34076 | 97000-H34076 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H34077 | 97000-H34077 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H34078 | 97000-H34078 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H34079 | 97000-H34079 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H34080 | 97000-H34080 | \$ 2,126.00 | 10% | \$1,927.75 |
| EW TAC OS H34081 | 97000-H34081 | \$ 2,037.00 | 10% | \$1,847.05 |
| EW TAC OS H34082 | 97000-H34082 | \$ 2,040.00 | 10% | \$1,849.77 |
| EW TAC OS H34083 | 97000-H34083 | \$ 1,954.00 | 10% | \$1,771.79 |
| EW TAC OS H34084 | 97000-H34084 | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS H34085 | 97000-H34085 | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS H34086 | 97000-H34086 | \$ 1,593.00 | 10% | \$1,444.45 |
| EW TAC OS H34087 | 97000-H34087 | \$ 1,528.00 | 10% | \$1,385.51 |
| EW TAC OS H34088 | 97000-H34088 | \$ 3,669.00 | 10% | \$3,326.87 |
| EW TAC OS H34089 | 97000-H34089 | \$ 3,669.00 | 10% | \$3,326.87 |
| EW TAC OS H34090 | 97000-H34090 | \$ 4,032.00 | 10% | \$3,656.02 |
| EW TAC OS H34091 | 97000-H34091 | \$ 2,325.00 | 10% | \$2,108.19 |
| EW TAC OS H34092 | 97000-H34092 | \$ 2,325.00 | 10% | \$2,108.19 |
| EW TAC OS H34093 | 97000-H34093 | \$ 2,325.00 | 10% | \$2,108.19 |
| EW TAC OS H34094 | 97000-H34094 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34095 | 97000-H34095 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34096 | 97000-H34096 | \$ 300.00 | 10% | \$272.03 |
| EW TAC OS H34097 | 97000-H34097 | \$ 300.00 | 10% | \$272.03 |
| EW TAC OS H34098 | 97000-H34098 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34099 | 97000-H34099 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34100 | 97000-H34100 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34101 | 97000-H34101 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34102 | 97000-H34102 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34103 | 97000-H34103 | \$ 270.00 | 10% | \$244.82 |
| EW TAC OS H34104 | 97000-H34104 | \$ 115.00 | 10% | \$104.28 |
| EW TAC OS H34105 | 97000-H34105 | \$ 115.00 | 10% | \$104.28 |
| EW TAC OS H34106 | 97000-H34106 | \$ 115.00 | 10% | \$104.28 |
| EW TAC OS H34107 | 97000-H34107 | \$ 115.00 | 10% | \$104.28 |
| EW TAC OS H34108 | 97000-H34108 | \$ 115.00 | 10% | \$104.28 |

| | | | | |
|------------------|--------------|-------------|-----|-------------------|
| EW TAC OS H34109 | 97000-H34109 | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW TAC OS H34110 | 97000-H34110 | \$ 2,147.00 | 10% | <i>\$1,946.79</i> |
| EW TAC OS H34111 | 97000-H34111 | \$ 2,147.00 | 10% | <i>\$1,946.79</i> |
| EW TAC OS H34112 | 97000-H34112 | \$ 2,147.00 | 10% | <i>\$1,946.79</i> |
| EW TAC OS H34114 | 97000-H34114 | \$ 2,810.00 | 10% | <i>\$2,547.97</i> |
| EW TAC OS H34115 | 97000-H34115 | \$ 2,810.00 | 10% | <i>\$2,547.97</i> |
| EW TAC OS H34116 | 97000-H34116 | \$ 2,810.00 | 10% | <i>\$2,547.97</i> |
| EW TAC OS H34117 | 97000-H34117 | \$ 2,810.00 | 10% | <i>\$2,547.97</i> |
| EW TAC OS H34118 | 97000-H34118 | \$ 708.00 | 10% | <i>\$641.98</i> |
| EW TAC OS H34119 | 97000-H34119 | \$ 708.00 | 10% | <i>\$641.98</i> |
| EW TAC OS H34120 | 97000-H34120 | \$ 490.00 | 10% | <i>\$444.31</i> |
| EW TAC OS H34121 | 97000-H34121 | \$ 490.00 | 10% | <i>\$444.31</i> |
| EW TAC OS H34122 | 97000-H34122 | \$ 509.00 | 10% | <i>\$461.54</i> |
| EW TAC OS H34123 | 97000-H34123 | \$ 509.00 | 10% | <i>\$461.54</i> |
| EW TAC OS H34124 | 97000-H34124 | \$ 759.00 | 10% | <i>\$688.22</i> |
| EW TAC OS H34125 | 97000-H34125 | \$ 759.00 | 10% | <i>\$688.22</i> |
| EW TAC OS H34126 | 97000-H34126 | \$ 759.00 | 10% | <i>\$688.22</i> |
| EW TAC OS H34127 | 97000-H34127 | \$ 759.00 | 10% | <i>\$688.22</i> |
| EW TAC OS H34128 | 97000-H34128 | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW TAC OS H34129 | 97000-H34129 | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW TAC OS H34130 | 97000-H34130 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW TAC OS H34131 | 97000-H34131 | \$ 228.00 | 10% | <i>\$206.74</i> |
| EW TAC OS H34132 | 97000-H34132 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW TAC OS H34138 | 97000-H34138 | \$ 898.00 | 10% | <i>\$814.26</i> |
| EW TAC OS H34172 | 97000-H34172 | \$ 505.00 | 10% | <i>\$457.91</i> |
| EW TAC OS H34174 | 97000-H34174 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34175 | 97000-H34175 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34176 | 97000-H34176 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34177 | 97000-H34177 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34178 | 97000-H34178 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34179 | 97000-H34179 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34180 | 97000-H34180 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34181 | 97000-H34181 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34182 | 97000-H34182 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34183 | 97000-H34183 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34184 | 97000-H34184 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34185 | 97000-H34185 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34186 | 97000-H34186 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34187 | 97000-H34187 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34188 | 97000-H34188 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34189 | 97000-H34189 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW TAC OS H34190 | 97000-H34190 | \$ 24.00 | 10% | <i>\$21.76</i> |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H34191 | 97000-H34191 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34192 | 97000-H34192 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34193 | 97000-H34193 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34194 | 97000-H34194 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34195 | 97000-H34195 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34196 | 97000-H34196 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34197 | 97000-H34197 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34198 | 97000-H34198 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34199 | 97000-H34199 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34200 | 97000-H34200 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34201 | 97000-H34201 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34202 | 97000-H34202 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34203 | 97000-H34203 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34204 | 97000-H34204 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34205 | 97000-H34205 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34206 | 97000-H34206 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34207 | 97000-H34207 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34208 | 97000-H34208 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34209 | 97000-H34209 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34210 | 97000-H34210 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34211 | 97000-H34211 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34212 | 97000-H34212 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34213 | 97000-H34213 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34214 | 97000-H34214 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34215 | 97000-H34215 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34216 | 97000-H34216 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34217 | 97000-H34217 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34218 | 97000-H34218 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34219 | 97000-H34219 | \$ 24.00 | 10% | \$21.76 |
| EW TAC OS H34220 | 97000-H34220 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34221 | 97000-H34221 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34222 | 97000-H34222 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34223 | 97000-H34223 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34224 | 97000-H34224 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34225 | 97000-H34225 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34226 | 97000-H34226 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34227 | 97000-H34227 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34228 | 97000-H34228 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34229 | 97000-H34229 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34230 | 97000-H34230 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34231 | 97000-H34231 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34232 | 97000-H34232 | \$ 34.00 | 10% | \$30.83 |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H34233 | 97000-H34233 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34234 | 97000-H34234 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34235 | 97000-H34235 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34236 | 97000-H34236 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34237 | 97000-H34237 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34238 | 97000-H34238 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34239 | 97000-H34239 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34240 | 97000-H34240 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34241 | 97000-H34241 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34242 | 97000-H34242 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34243 | 97000-H34243 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34244 | 97000-H34244 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34245 | 97000-H34245 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34246 | 97000-H34246 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34247 | 97000-H34247 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34248 | 97000-H34248 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34249 | 97000-H34249 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34250 | 97000-H34250 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34251 | 97000-H34251 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34252 | 97000-H34252 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34253 | 97000-H34253 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34254 | 97000-H34254 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34255 | 97000-H34255 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34256 | 97000-H34256 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34257 | 97000-H34257 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34258 | 97000-H34258 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34259 | 97000-H34259 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34260 | 97000-H34260 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34261 | 97000-H34261 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34262 | 97000-H34262 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34263 | 97000-H34263 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34264 | 97000-H34264 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34265 | 97000-H34265 | \$ 34.00 | 10% | \$30.83 |
| EW TAC OS H34266 | 97000-H34266 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34267 | 97000-H34267 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34268 | 97000-H34268 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34269 | 97000-H34269 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34270 | 97000-H34270 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34271 | 97000-H34271 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34272 | 97000-H34272 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34273 | 97000-H34273 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34274 | 97000-H34274 | \$ 29.00 | 10% | \$26.30 |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H34275 | 97000-H34275 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34276 | 97000-H34276 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34277 | 97000-H34277 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34278 | 97000-H34278 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34279 | 97000-H34279 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34280 | 97000-H34280 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34281 | 97000-H34281 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34282 | 97000-H34282 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34283 | 97000-H34283 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34284 | 97000-H34284 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34285 | 97000-H34285 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34286 | 97000-H34286 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34287 | 97000-H34287 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34288 | 97000-H34288 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34289 | 97000-H34289 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34290 | 97000-H34290 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34291 | 97000-H34291 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34292 | 97000-H34292 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34293 | 97000-H34293 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34294 | 97000-H34294 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34295 | 97000-H34295 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34296 | 97000-H34296 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34297 | 97000-H34297 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34298 | 97000-H34298 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34299 | 97000-H34299 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34300 | 97000-H34300 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34301 | 97000-H34301 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34302 | 97000-H34302 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34303 | 97000-H34303 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34304 | 97000-H34304 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34305 | 97000-H34305 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H34306 | 97000-H34306 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34307 | 97000-H34307 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34308 | 97000-H34308 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34309 | 97000-H34309 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34310 | 97000-H34310 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34311 | 97000-H34311 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34312 | 97000-H34312 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34313 | 97000-H34313 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34314 | 97000-H34314 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34315 | 97000-H34315 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34316 | 97000-H34316 | \$ 36.00 | 10% | \$32.64 |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H34317 | 97000-H34317 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34318 | 97000-H34318 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34319 | 97000-H34319 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34320 | 97000-H34320 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34321 | 97000-H34321 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34322 | 97000-H34322 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34323 | 97000-H34323 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34324 | 97000-H34324 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34325 | 97000-H34325 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34326 | 97000-H34326 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34327 | 97000-H34327 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34328 | 97000-H34328 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34329 | 97000-H34329 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34330 | 97000-H34330 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34331 | 97000-H34331 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34332 | 97000-H34332 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34333 | 97000-H34333 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34334 | 97000-H34334 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34335 | 97000-H34335 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34336 | 97000-H34336 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34337 | 97000-H34337 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34338 | 97000-H34338 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34339 | 97000-H34339 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34340 | 97000-H34340 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34341 | 97000-H34341 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34342 | 97000-H34342 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34343 | 97000-H34343 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34344 | 97000-H34344 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34345 | 97000-H34345 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34346 | 97000-H34346 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34347 | 97000-H34347 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34348 | 97000-H34348 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34349 | 97000-H34349 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34350 | 97000-H34350 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34351 | 97000-H34351 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34352 | 97000-H34352 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34353 | 97000-H34353 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34354 | 97000-H34354 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34355 | 97000-H34355 | \$ 36.00 | 10% | \$32.64 |
| EW TAC OS H34356 | 97000-H34356 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34357 | 97000-H34357 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34358 | 97000-H34358 | \$ 63.00 | 10% | \$57.13 |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H34359 | 97000-H34359 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34360 | 97000-H34360 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34361 | 97000-H34361 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34362 | 97000-H34362 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34363 | 97000-H34363 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34364 | 97000-H34364 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34365 | 97000-H34365 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34366 | 97000-H34366 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34367 | 97000-H34367 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34368 | 97000-H34368 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34369 | 97000-H34369 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34370 | 97000-H34370 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34371 | 97000-H34371 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34372 | 97000-H34372 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34373 | 97000-H34373 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34374 | 97000-H34374 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34375 | 97000-H34375 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34376 | 97000-H34376 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34377 | 97000-H34377 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34378 | 97000-H34378 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34379 | 97000-H34379 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34380 | 97000-H34380 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34381 | 97000-H34381 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34382 | 97000-H34382 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34383 | 97000-H34383 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34384 | 97000-H34384 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34385 | 97000-H34385 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34386 | 97000-H34386 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34387 | 97000-H34387 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34388 | 97000-H34388 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34389 | 97000-H34389 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34390 | 97000-H34390 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34391 | 97000-H34391 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34392 | 97000-H34392 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34393 | 97000-H34393 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34394 | 97000-H34394 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34395 | 97000-H34395 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34396 | 97000-H34396 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34397 | 97000-H34397 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34398 | 97000-H34398 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34399 | 97000-H34399 | \$ 63.00 | 10% | \$57.13 |
| EW TAC OS H34400 | 97000-H34400 | \$ 63.00 | 10% | \$57.13 |

| | | | | |
|------------------|--------------|-----------|-----|----------------|
| EW TAC OS H34401 | 97000-H34401 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW TAC OS H34402 | 97000-H34402 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW TAC OS H34403 | 97000-H34403 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34404 | 97000-H34404 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34405 | 97000-H34405 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34406 | 97000-H34406 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34407 | 97000-H34407 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34408 | 97000-H34408 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34409 | 97000-H34409 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34410 | 97000-H34410 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34411 | 97000-H34411 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34412 | 97000-H34412 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34413 | 97000-H34413 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34414 | 97000-H34414 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34415 | 97000-H34415 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34416 | 97000-H34416 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34417 | 97000-H34417 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34418 | 97000-H34418 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34419 | 97000-H34419 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34420 | 97000-H34420 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34421 | 97000-H34421 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34422 | 97000-H34422 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34423 | 97000-H34423 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34424 | 97000-H34424 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34425 | 97000-H34425 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34426 | 97000-H34426 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34427 | 97000-H34427 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34428 | 97000-H34428 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34429 | 97000-H34429 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34430 | 97000-H34430 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34431 | 97000-H34431 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34432 | 97000-H34432 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34433 | 97000-H34433 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34434 | 97000-H34434 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34435 | 97000-H34435 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34436 | 97000-H34436 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34437 | 97000-H34437 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34438 | 97000-H34438 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34439 | 97000-H34439 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34440 | 97000-H34440 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34441 | 97000-H34441 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34442 | 97000-H34442 | \$ 100.00 | 10% | <i>\$90.68</i> |

| | | | | |
|------------------|--------------|-----------|-----|-----------------|
| EW TAC OS H34443 | 97000-H34443 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34444 | 97000-H34444 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34445 | 97000-H34445 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW TAC OS H34446 | 97000-H34446 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34447 | 97000-H34447 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34448 | 97000-H34448 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34449 | 97000-H34449 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34450 | 97000-H34450 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34451 | 97000-H34451 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34452 | 97000-H34452 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34453 | 97000-H34453 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34454 | 97000-H34454 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34455 | 97000-H34455 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34456 | 97000-H34456 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34457 | 97000-H34457 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34458 | 97000-H34458 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34459 | 97000-H34459 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34460 | 97000-H34460 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34461 | 97000-H34461 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34462 | 97000-H34462 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34463 | 97000-H34463 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34464 | 97000-H34464 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34465 | 97000-H34465 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34466 | 97000-H34466 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34467 | 97000-H34467 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34468 | 97000-H34468 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34469 | 97000-H34469 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34470 | 97000-H34470 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34471 | 97000-H34471 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34472 | 97000-H34472 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34473 | 97000-H34473 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34474 | 97000-H34474 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34475 | 97000-H34475 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34476 | 97000-H34476 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34477 | 97000-H34477 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34478 | 97000-H34478 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34479 | 97000-H34479 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34480 | 97000-H34480 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34481 | 97000-H34481 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34482 | 97000-H34482 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34483 | 97000-H34483 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34484 | 97000-H34484 | \$ 113.00 | 10% | <i>\$102.46</i> |

| | | | | |
|------------------|--------------|-----------|-----|-----------------|
| EW TAC OS H34485 | 97000-H34485 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34486 | 97000-H34486 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34487 | 97000-H34487 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34488 | 97000-H34488 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34489 | 97000-H34489 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW TAC OS H34490 | 97000-H34490 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34491 | 97000-H34491 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34492 | 97000-H34492 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34493 | 97000-H34493 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34494 | 97000-H34494 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34495 | 97000-H34495 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34496 | 97000-H34496 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34497 | 97000-H34497 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34498 | 97000-H34498 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34499 | 97000-H34499 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34500 | 97000-H34500 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34501 | 97000-H34501 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34502 | 97000-H34502 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34503 | 97000-H34503 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34504 | 97000-H34504 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34505 | 97000-H34505 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34506 | 97000-H34506 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34507 | 97000-H34507 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34508 | 97000-H34508 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34509 | 97000-H34509 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34510 | 97000-H34510 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34511 | 97000-H34511 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34512 | 97000-H34512 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34513 | 97000-H34513 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34514 | 97000-H34514 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34515 | 97000-H34515 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34516 | 97000-H34516 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34517 | 97000-H34517 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34518 | 97000-H34518 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34519 | 97000-H34519 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34520 | 97000-H34520 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34521 | 97000-H34521 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34522 | 97000-H34522 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34523 | 97000-H34523 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34524 | 97000-H34524 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34525 | 97000-H34525 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34526 | 97000-H34526 | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | | |
|------------------|--------------|----|-------|-----|----------------|
| EW TAC OS H34527 | 97000-H34527 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34528 | 97000-H34528 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34529 | 97000-H34529 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34530 | 97000-H34530 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34531 | 97000-H34531 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34532 | 97000-H34532 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34533 | 97000-H34533 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34534 | 97000-H34534 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34535 | 97000-H34535 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34536 | 97000-H34536 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34537 | 97000-H34537 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34538 | 97000-H34538 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34539 | 97000-H34539 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34540 | 97000-H34540 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34541 | 97000-H34541 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34542 | 97000-H34542 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34543 | 97000-H34543 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34544 | 97000-H34544 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34545 | 97000-H34545 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34546 | 97000-H34546 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34547 | 97000-H34547 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34548 | 97000-H34548 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34549 | 97000-H34549 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34550 | 97000-H34550 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34551 | 97000-H34551 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34552 | 97000-H34552 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34553 | 97000-H34553 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34554 | 97000-H34554 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34555 | 97000-H34555 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34556 | 97000-H34556 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34557 | 97000-H34557 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34558 | 97000-H34558 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34559 | 97000-H34559 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34560 | 97000-H34560 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34561 | 97000-H34561 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34562 | 97000-H34562 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34563 | 97000-H34563 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34564 | 97000-H34564 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34565 | 97000-H34565 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34566 | 97000-H34566 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34567 | 97000-H34567 | \$ | 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34568 | 97000-H34568 | \$ | 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|------------------|--------------|----------|-----|----------------|
| EW TAC OS H34569 | 97000-H34569 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34570 | 97000-H34570 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34571 | 97000-H34571 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34572 | 97000-H34572 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34573 | 97000-H34573 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34574 | 97000-H34574 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34575 | 97000-H34575 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34576 | 97000-H34576 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34577 | 97000-H34577 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34578 | 97000-H34578 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34579 | 97000-H34579 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34580 | 97000-H34580 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34581 | 97000-H34581 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34582 | 97000-H34582 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34583 | 97000-H34583 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34584 | 97000-H34584 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34585 | 97000-H34585 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34586 | 97000-H34586 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW TAC OS H34587 | 97000-H34587 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34588 | 97000-H34588 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34589 | 97000-H34589 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34590 | 97000-H34590 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34591 | 97000-H34591 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34592 | 97000-H34592 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34593 | 97000-H34593 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34594 | 97000-H34594 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34595 | 97000-H34595 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34596 | 97000-H34596 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34597 | 97000-H34597 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34598 | 97000-H34598 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34599 | 97000-H34599 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34600 | 97000-H34600 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34601 | 97000-H34601 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34602 | 97000-H34602 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34603 | 97000-H34603 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34604 | 97000-H34604 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34605 | 97000-H34605 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34606 | 97000-H34606 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34607 | 97000-H34607 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34608 | 97000-H34608 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34609 | 97000-H34609 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW TAC OS H34610 | 97000-H34610 | \$ 42.00 | 10% | <i>\$38.08</i> |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H34611 | 97000-H34611 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34612 | 97000-H34612 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34613 | 97000-H34613 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34614 | 97000-H34614 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34615 | 97000-H34615 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34616 | 97000-H34616 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34617 | 97000-H34617 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34618 | 97000-H34618 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34619 | 97000-H34619 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34620 | 97000-H34620 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34621 | 97000-H34621 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34622 | 97000-H34622 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34623 | 97000-H34623 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34624 | 97000-H34624 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34625 | 97000-H34625 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34626 | 97000-H34626 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34627 | 97000-H34627 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34628 | 97000-H34628 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34629 | 97000-H34629 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34630 | 97000-H34630 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34631 | 97000-H34631 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H34632 | 97000-H34632 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34633 | 97000-H34633 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34634 | 97000-H34634 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34635 | 97000-H34635 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34636 | 97000-H34636 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34637 | 97000-H34637 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34638 | 97000-H34638 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34639 | 97000-H34639 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34640 | 97000-H34640 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34641 | 97000-H34641 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34642 | 97000-H34642 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34643 | 97000-H34643 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34644 | 97000-H34644 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34645 | 97000-H34645 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34646 | 97000-H34646 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34647 | 97000-H34647 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34648 | 97000-H34648 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34649 | 97000-H34649 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34650 | 97000-H34650 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34651 | 97000-H34651 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34652 | 97000-H34652 | \$ 48.00 | 10% | \$43.52 |

| | | | | |
|------------------|--------------|----------|-----|---------|
| EW TAC OS H34653 | 97000-H34653 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34654 | 97000-H34654 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34655 | 97000-H34655 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34656 | 97000-H34656 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34657 | 97000-H34657 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34658 | 97000-H34658 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34659 | 97000-H34659 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34660 | 97000-H34660 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34661 | 97000-H34661 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34662 | 97000-H34662 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34663 | 97000-H34663 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34664 | 97000-H34664 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34665 | 97000-H34665 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34666 | 97000-H34666 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34667 | 97000-H34667 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34668 | 97000-H34668 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34669 | 97000-H34669 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34670 | 97000-H34670 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34671 | 97000-H34671 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34672 | 97000-H34672 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34673 | 97000-H34673 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34674 | 97000-H34674 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34675 | 97000-H34675 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34676 | 97000-H34676 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34677 | 97000-H34677 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34678 | 97000-H34678 | \$ 48.00 | 10% | \$43.52 |
| EW TAC OS H34679 | 97000-H34679 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34680 | 97000-H34680 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34681 | 97000-H34681 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34682 | 97000-H34682 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34683 | 97000-H34683 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34684 | 97000-H34684 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34685 | 97000-H34685 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34686 | 97000-H34686 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34687 | 97000-H34687 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34688 | 97000-H34688 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34689 | 97000-H34689 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34690 | 97000-H34690 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34691 | 97000-H34691 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34692 | 97000-H34692 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34693 | 97000-H34693 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34694 | 97000-H34694 | \$ 54.00 | 10% | \$48.96 |

| | | | | |
|------------------|--------------|-------------|-----|------------|
| EW TAC OS H34695 | 97000-H34695 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34696 | 97000-H34696 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34697 | 97000-H34697 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34698 | 97000-H34698 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34699 | 97000-H34699 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34700 | 97000-H34700 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34701 | 97000-H34701 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34702 | 97000-H34702 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34703 | 97000-H34703 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34704 | 97000-H34704 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34705 | 97000-H34705 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34706 | 97000-H34706 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34707 | 97000-H34707 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34708 | 97000-H34708 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34709 | 97000-H34709 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34710 | 97000-H34710 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34711 | 97000-H34711 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34712 | 97000-H34712 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34713 | 97000-H34713 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34714 | 97000-H34714 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34715 | 97000-H34715 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34716 | 97000-H34716 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34717 | 97000-H34717 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34718 | 97000-H34718 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34719 | 97000-H34719 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34720 | 97000-H34720 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34721 | 97000-H34721 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34722 | 97000-H34722 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34723 | 97000-H34723 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34724 | 97000-H34724 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34725 | 97000-H34725 | \$ 54.00 | 10% | \$48.96 |
| EW TAC OS H34726 | 97000-H34726 | \$ 1,696.00 | 10% | \$1,537.85 |
| EW TAC OS H34727 | 97000-H34727 | \$ 1,696.00 | 10% | \$1,537.85 |
| EW TAC OS H34728 | 97000-H34728 | \$ 1,696.00 | 10% | \$1,537.85 |
| EW TAC OS H34729 | 97000-H34729 | \$ 1,696.00 | 10% | \$1,537.85 |
| EW TAC OS H34730 | 97000-H34730 | \$ 1,815.00 | 10% | \$1,645.75 |
| EW TAC OS H34731 | 97000-H34731 | \$ 1,815.00 | 10% | \$1,645.75 |
| EW TAC OS H34732 | 97000-H34732 | \$ 1,815.00 | 10% | \$1,645.75 |
| EW TAC OS H34733 | 97000-H34733 | \$ 1,815.00 | 10% | \$1,645.75 |
| EW TAC OS H34734 | 97000-H34734 | \$ 256.00 | 10% | \$232.13 |
| EW TAC OS H34735 | 97000-H34735 | \$ 256.00 | 10% | \$232.13 |
| EW TAC OS H34736 | 97000-H34736 | \$ 327.00 | 10% | \$296.51 |

| | | | | |
|------------------|--------------|-------------|-----|------------|
| EW TAC OS H34737 | 97000-H34737 | \$ 327.00 | 10% | \$296.51 |
| EW TAC OS H34738 | 97000-H34738 | \$ 613.00 | 10% | \$555.84 |
| EW TAC OS H34739 | 97000-H34739 | \$ 613.00 | 10% | \$555.84 |
| EW TAC OS H34740 | 97000-H34740 | \$ 266.00 | 10% | \$241.20 |
| EW TAC OS H34741 | 97000-H34741 | \$ 266.00 | 10% | \$241.20 |
| EW TAC OS H34742 | 97000-H34742 | \$ 143.00 | 10% | \$129.67 |
| EW TAC OS H34743 | 97000-H34743 | \$ 143.00 | 10% | \$129.67 |
| EW TAC OS H34744 | 97000-H34744 | \$ 337.00 | 10% | \$305.57 |
| EW TAC OS H34745 | 97000-H34745 | \$ 337.00 | 10% | \$305.57 |
| EW TAC OS H34746 | 97000-H34746 | \$ 380.00 | 10% | \$344.57 |
| EW TAC OS H34747 | 97000-H34747 | \$ 380.00 | 10% | \$344.57 |
| EW TAC OS H34748 | 97000-H34748 | \$ 635.00 | 10% | \$575.79 |
| EW TAC OS H34749 | 97000-H34749 | \$ 613.00 | 10% | \$555.84 |
| EW TAC OS H34750 | 97000-H34750 | \$ 635.00 | 10% | \$575.79 |
| EW TAC OS H34751 | 97000-H34751 | \$ 635.00 | 10% | \$575.79 |
| EW TAC OS H34752 | 97000-H34752 | \$ 635.00 | 10% | \$575.79 |
| EW TAC OS H34753 | 97000-H34753 | \$ 613.00 | 10% | \$555.84 |
| EW TAC OS H34754 | 97000-H34754 | \$ 635.00 | 10% | \$575.79 |
| EW TAC OS H34755 | 97000-H34755 | \$ 635.00 | 10% | \$575.79 |
| EW TAC OS H34756 | 97000-H34756 | \$ 338.00 | 10% | \$306.48 |
| EW TAC OS H34757 | 97000-H34757 | \$ 327.00 | 10% | \$296.51 |
| EW TAC OS H34758 | 97000-H34758 | \$ 337.00 | 10% | \$305.57 |
| EW TAC OS H34759 | 97000-H34759 | \$ 338.00 | 10% | \$306.48 |
| EW TAC OS H34760 | 97000-H34760 | \$ 338.00 | 10% | \$306.48 |
| EW TAC OS H34761 | 97000-H34761 | \$ 337.00 | 10% | \$305.57 |
| EW TAC OS H34993 | 97000-H34993 | \$ 7,063.00 | 10% | \$6,404.38 |
| EW TAC OS H34994 | 97000-H34994 | \$ 7,063.00 | 10% | \$6,404.38 |
| EW TAC OS H34996 | 97000-H34996 | \$ 7,063.00 | 10% | \$6,404.38 |
| EW TAC OS H34997 | 97000-H34997 | \$ 7,063.00 | 10% | \$6,404.38 |
| EW TAC OS H35005 | 97000-H35005 | \$ 4,271.00 | 10% | \$3,872.73 |
| EW TAC OS H35006 | 97000-H35006 | \$ 4,271.00 | 10% | \$3,872.73 |
| EW TAC OS H35012 | 97000-H35012 | \$ 2,562.00 | 10% | \$2,323.09 |
| EW TAC OS H35070 | 97000-H35070 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35071 | 97000-H35071 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35072 | 97000-H35072 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35073 | 97000-H35073 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35074 | 97000-H35074 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35075 | 97000-H35075 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35076 | 97000-H35076 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35077 | 97000-H35077 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35078 | 97000-H35078 | \$ 29.00 | 10% | \$26.30 |
| EW TAC OS H35079 | 97000-H35079 | \$ 29.00 | 10% | \$26.30 |

| | | | | |
|----------------------------|--------------|-------------|-----|------------|
| EW TAC OS H35080 | 97000-H35080 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H35081 | 97000-H35081 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H35082 | 97000-H35082 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H35083 | 97000-H35083 | \$ 42.00 | 10% | \$38.08 |
| EW TAC OS H35270 | 97000-H35270 | \$ 227.00 | 10% | \$205.83 |
| EW TAC OS H35271 | 97000-H35271 | \$ 171.00 | 10% | \$155.05 |
| EW TAC OS H35272 | 97000-H35272 | \$ 155.00 | 10% | \$140.55 |
| EW TAC OS H35273 | 97000-H35273 | \$ 155.00 | 10% | \$140.55 |
| EW TAC OS H35274 | 97000-H35274 | \$ 368.00 | 10% | \$333.68 |
| EW TAC OS H35275 | 97000-H35275 | \$ 254.00 | 10% | \$230.31 |
| EW TAC OS H35276 | 97000-H35276 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H35277 | 97000-H35277 | \$ 2,040.00 | 10% | \$1,849.77 |
| EW TAC OS H35278 | 97000-H35278 | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS H35279 | 97000-H35279 | \$ 1,475.00 | 10% | \$1,337.46 |
| EW TAC OS H35280 | 97000-H35280 | \$ 2,104.00 | 10% | \$1,907.80 |
| EW TAC OS H35281 | 97000-H35281 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35282 | 97000-H35282 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35283 | 97000-H35283 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35284 | 97000-H35284 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35285 | 97000-H35285 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35286 | 97000-H35286 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35287 | 97000-H35287 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35288 | 97000-H35288 | \$ 969.00 | 10% | \$878.64 |
| EW TAC OS H35289 | 97000-H35289 | \$ 2,428.00 | 10% | \$2,201.59 |
| EW TAC OS H35291 | 97000-H35291 | \$ 1,834.00 | 10% | \$1,662.98 |
| EW TAC OS H35292 | 97000-H35292 | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS H35293 | 97000-H35293 | \$ 1,475.00 | 10% | \$1,337.46 |
| EW TAC OS H35295 | 97000-H35295 | \$ 197.00 | 10% | \$178.63 |
| EW Software and TAC H35296 | 97000-H35296 | \$ 3,457.00 | 10% | \$3,134.63 |
| EW Software and TAC H35297 | 97000-H35297 | \$ 3,457.00 | 10% | \$3,134.63 |
| EW Software and TAC H35298 | 97000-H35298 | \$ 5,557.00 | 10% | \$5,038.81 |
| EW Software and TAC H35299 | 97000-H35299 | \$ 5,557.00 | 10% | \$5,038.81 |
| EW Software and TAC H35300 | 97000-H35300 | \$ 1,008.00 | 10% | \$914.00 |
| EW Software and TAC H35301 | 97000-H35301 | \$ 453.00 | 10% | \$410.76 |
| EW Software and TAC H35302 | 97000-H35302 | \$ 1,313.00 | 10% | \$1,190.56 |
| EW Software and TAC H35303 | 97000-H35303 | \$ 1,313.00 | 10% | \$1,190.56 |
| EW Software and TAC H35304 | 97000-H35304 | \$ 1,313.00 | 10% | \$1,190.56 |
| EW Software and TAC H35305 | 97000-H35305 | \$ 1,374.00 | 10% | \$1,245.87 |
| EW Software and TAC H35306 | 97000-H35306 | \$ 1,374.00 | 10% | \$1,245.87 |
| EW Software and TAC H35307 | 97000-H35307 | \$ 1,374.00 | 10% | \$1,245.87 |
| EW Software and TAC H35308 | 97000-H35308 | \$ 371.00 | 10% | \$336.40 |
| EW TAC OS H35309 | 97000-H35309 | \$ 2,048.00 | 10% | \$1,857.02 |

| | | | | |
|------------------|--------------|-------------|-----|-------------------|
| EW TAC OS H35310 | 97000-H35310 | \$ 2,048.00 | 10% | <i>\$1,857.02</i> |
| EW TAC OS H35311 | 97000-H35311 | \$ 2,048.00 | 10% | <i>\$1,857.02</i> |
| EW TAC OS H35312 | 97000-H35312 | \$ 1,718.00 | 10% | <i>\$1,557.80</i> |
| EW TAC OS H35313 | 97000-H35313 | \$ 1,718.00 | 10% | <i>\$1,557.80</i> |
| EW TAC OS H35314 | 97000-H35314 | \$ 1,718.00 | 10% | <i>\$1,557.80</i> |
| EW TAC OS H35315 | 97000-H35315 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS H35316 | 97000-H35316 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW TAC OS H35317 | 97000-H35317 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW TAC OS H35318 | 97000-H35318 | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW TAC OS H35319 | 97000-H35319 | \$ 472.00 | 10% | <i>\$427.99</i> |
| EW TAC OS H35320 | 97000-H35320 | \$ 489.00 | 10% | <i>\$443.40</i> |
| EW TAC OS H35321 | 97000-H35321 | \$ 623.00 | 10% | <i>\$564.91</i> |
| EW TAC OS H35322 | 97000-H35322 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS H35323 | 97000-H35323 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS H35328 | 97000-H35328 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW TAC OS H35330 | 97000-H35330 | \$ 44.00 | 10% | <i>\$39.90</i> |
| EW TAC OS H35340 | 97000-H35340 | \$ 1,394.00 | 10% | <i>\$1,264.01</i> |
| EW TAC OS H35341 | 97000-H35341 | \$ 1,394.00 | 10% | <i>\$1,264.01</i> |
| EW TAC OS H35342 | 97000-H35342 | \$ 1,279.00 | 10% | <i>\$1,159.73</i> |
| EW TAC OS H35343 | 97000-H35343 | \$ 1,394.00 | 10% | <i>\$1,264.01</i> |
| EW TAC OS H35344 | 97000-H35344 | \$ 1,455.00 | 10% | <i>\$1,319.32</i> |
| EW TAC OS H35345 | 97000-H35345 | \$ 1,455.00 | 10% | <i>\$1,319.32</i> |
| EW TAC OS H35346 | 97000-H35346 | \$ 1,321.00 | 10% | <i>\$1,197.82</i> |
| EW TAC OS H35347 | 97000-H35347 | \$ 1,455.00 | 10% | <i>\$1,319.32</i> |
| EW TAC OS H35348 | 97000-H35348 | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW TAC OS H35349 | 97000-H35349 | \$ 1,608.00 | 10% | <i>\$1,458.05</i> |
| EW TAC OS H35350 | 97000-H35350 | \$ 1,608.00 | 10% | <i>\$1,458.05</i> |
| EW TAC OS H35351 | 97000-H35351 | \$ 1,450.00 | 10% | <i>\$1,314.79</i> |
| EW TAC OS H35352 | 97000-H35352 | \$ 1,608.00 | 10% | <i>\$1,458.05</i> |
| EW TAC OS H35353 | 97000-H35353 | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW TAC OS H35357 | 97000-H35357 | \$ 178.00 | 10% | <i>\$161.40</i> |
| EW TAC OS H35358 | 97000-H35358 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW TAC OS H35359 | 97000-H35359 | \$ 623.00 | 10% | <i>\$564.91</i> |
| EW TAC OS H35360 | 97000-H35360 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS H35361 | 97000-H35361 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS H35362 | 97000-H35362 | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW TAC OS H35366 | 97000-H35366 | \$ 708.00 | 10% | <i>\$641.98</i> |
| EW TAC OS H35367 | 97000-H35367 | \$ 824.00 | 10% | <i>\$747.16</i> |
| EW TAC OS H35368 | 97000-H35368 | \$ 1,251.00 | 10% | <i>\$1,134.34</i> |
| EW TAC OS H35369 | 97000-H35369 | \$ 405.00 | 10% | <i>\$367.23</i> |
| EW TAC OS H35370 | 97000-H35370 | \$ 570.00 | 10% | <i>\$516.85</i> |
| EW TAC OS H35371 | 97000-H35371 | \$ 166.00 | 10% | <i>\$150.52</i> |

| | | | | |
|------------------|--------------|-----------|-----|-----------------|
| EW TAC OS H35374 | 97000-H35374 | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW TAC OS H35375 | 97000-H35375 | \$ 341.00 | 10% | <i>\$309.20</i> |
| EW TAC OS H35376 | 97000-H35376 | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW TAC OS H35377 | 97000-H35377 | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW TAC OS H35378 | 97000-H35378 | \$ 341.00 | 10% | <i>\$309.20</i> |
| EW TAC OS H35379 | 97000-H35379 | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW TAC OS H35380 | 97000-H35380 | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW TAC OS H35381 | 97000-H35381 | \$ 475.00 | 10% | <i>\$430.71</i> |
| EW TAC OS H35384 | 97000-H35384 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW TAC OS H35385 | 97000-H35385 | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW TAC OS H35386 | 97000-H35386 | \$ 341.00 | 10% | <i>\$309.20</i> |
| EW TAC OS H35387 | 97000-H35387 | \$ 313.00 | 10% | <i>\$283.81</i> |
| EW TAC OS H35388 | 97000-H35388 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW TAC OS H35389 | 97000-H35389 | \$ 133.00 | 10% | <i>\$120.60</i> |
| EW TAC OS H35390 | 97000-H35390 | \$ 116.00 | 10% | <i>\$105.18</i> |
| EW TAC OS H35391 | 97000-H35391 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW TAC OS H35392 | 97000-H35392 | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW TAC OS H35393 | 97000-H35393 | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW TAC OS H35394 | 97000-H35394 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW TAC OS H35395 | 97000-H35395 | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW TAC OS H35396 | 97000-H35396 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW TAC OS H35397 | 97000-H35397 | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW TAC OS H35398 | 97000-H35398 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW TAC OS H35399 | 97000-H35399 | \$ 291.00 | 10% | <i>\$263.86</i> |
| EW TAC OS H35400 | 97000-H35400 | \$ 322.00 | 10% | <i>\$291.97</i> |
| EW TAC OS H35401 | 97000-H35401 | \$ 171.00 | 10% | <i>\$155.05</i> |
| EW TAC OS H35404 | 97000-H35404 | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW TAC OS H35405 | 97000-H35405 | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW TAC OS H35406 | 97000-H35406 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW TAC OS H35407 | 97000-H35407 | \$ 155.00 | 10% | <i>\$140.55</i> |
| EW TAC OS H35408 | 97000-H35408 | \$ 231.00 | 10% | <i>\$209.46</i> |
| EW TAC OS H35409 | 97000-H35409 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW TAC OS H35415 | 97000-H35415 | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW TAC OS H35416 | 97000-H35416 | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW TAC OS H35426 | 97000-H35426 | \$ 133.00 | 10% | <i>\$120.60</i> |
| EW TAC OS H35427 | 97000-H35427 | \$ 313.00 | 10% | <i>\$283.81</i> |
| EW TAC OS H35428 | 97000-H35428 | \$ 116.00 | 10% | <i>\$105.18</i> |
| EW TAC OS H35429 | 97000-H35429 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW TAC OS H35430 | 97000-H35430 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW TAC OS H35431 | 97000-H35431 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW TAC OS H35432 | 97000-H35432 | \$ 143.00 | 10% | <i>\$129.67</i> |
| EW TAC OS H35433 | 97000-H35433 | \$ 317.00 | 10% | <i>\$287.44</i> |

| | | | | |
|--------------------------------|----------------------------|-------------|-----|------------|
| EW TAC OS H35434 | 97000-H35434 | \$ 357.00 | 10% | \$323.71 |
| EW TAC OS H35435 | 97000-H35435 | \$ 357.00 | 10% | \$323.71 |
| EW TAC OS H35436 | 97000-H35436 | \$ 595.00 | 10% | \$539.52 |
| EW TAC OS H35437 | 97000-H35437 | \$ 595.00 | 10% | \$539.52 |
| EW TAC OS H35438 | 97000-H35438 | \$ 595.00 | 10% | \$539.52 |
| EW TAC OS H35439 | 97000-H35439 | \$ 595.00 | 10% | \$539.52 |
| EW TAC OS H35440 | 97000-H35440 | \$ 317.00 | 10% | \$287.44 |
| EW TAC OS H35441 | 97000-H35441 | \$ 317.00 | 10% | \$287.44 |
| EW TAC OS H35442 | 97000-H35442 | \$ 317.00 | 10% | \$287.44 |
| EW TAC OS H35443 | 97000-H35443 | \$ 1,696.00 | 10% | \$1,537.85 |
| EW TAC OS H35444 | 97000-H35444 | \$ 1,815.00 | 10% | \$1,645.75 |
| EW TAC OS H35445 | 97000-H35445 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H35446 | 97000-H35446 | \$ 1,625.00 | 10% | \$1,473.47 |
| EW TAC OS H35447 | 97000-H35447 | \$ 1,933.00 | 10% | \$1,752.75 |
| EW TAC OS H35448 | 97000-H35448 | \$ 1,789.00 | 10% | \$1,622.18 |
| EW TAC OS H35449 | 97000-H35449 | \$ 1,310.00 | 10% | \$1,187.84 |
| EW TAC OS H35450 | 97000-H35450 | \$ 1,398.00 | 10% | \$1,267.64 |
| EW TAC OS H35451 | 97000-H35451 | \$ 2,325.00 | 10% | \$2,108.19 |
| EW TAC OS H35452 | 97000-H35452 | \$ 2,325.00 | 10% | \$2,108.19 |
| EW TAC OS H35453 | 97000-H35453 | \$ 1,815.00 | 10% | \$1,645.75 |
| EW TAC OS H35454 | 97000-H35454 | \$ 1,696.00 | 10% | \$1,537.85 |
| EW TAC OS H35455 | 97000-H35455 | \$ 489.00 | 10% | \$443.40 |
| EW TAC OS H35456 | 97000-H35456 | \$ 582.00 | 10% | \$527.73 |
| EW TAC OS H35457 | 97000-H35457 | \$ 539.00 | 10% | \$488.74 |
| EW TAC OS H35458 | 97000-H35458 | \$ 588.00 | 10% | \$533.17 |
| EW TAC OS H35471 | 97000-H35471 | \$ 489.00 | 10% | \$443.40 |
| EW TAC OS H35600 | 97000-H35600 | \$ 155.00 | 10% | \$140.55 |
| EW TAC OS H35601 | 97000-H35601 | \$ 155.00 | 10% | \$140.55 |
| EW TAC OS H35602 | 97000-H35602 | \$ 266.00 | 10% | \$241.20 |
| EW TAC OS H35603 | 97000-H35603 | \$ 266.00 | 10% | \$241.20 |
| EW TAC OS H35604 | 97000-H35604 | \$ 338.00 | 10% | \$306.48 |
| EW TAC OS H35605 | 97000-H35605 | \$ 338.00 | 10% | \$306.48 |
| EW TAC OS H35606 | 97000-H35606 | \$ 368.00 | 10% | \$333.68 |
| EW TAC OS H35607 | 97000-H35607 | \$ 380.00 | 10% | \$344.57 |
| EW TAC OS ipe-2000ax-LR-10G | 97000-ipe-2000ax-LR-10G | \$ 2,220.00 | 10% | \$2,012.99 |
| EW TAC OS ipe-2000ax-LR-10G-WP | 97000-ipe-2000ax-LR-10G-WP | \$ 2,220.00 | 10% | \$2,012.99 |
| EW TAC OS ipe-2000ax-Lx | 97000-ipe-2000ax-Lx | \$ 1,850.00 | 10% | \$1,677.49 |

| | | | | |
|--------------------------------|----------------------------|-------------|-----|-------------------|
| EW TAC OS ipe-2000ax-Lx-WP | 97000-ipe-2000ax-Lx-WP | \$ 1,850.00 | 10% | <i>\$1,677.49</i> |
| EW TAC OS ipe-2000ax-SR-10G | 97000-ipe-2000ax-SR-10G | \$ 2,220.00 | 10% | <i>\$2,012.99</i> |
| EW TAC OS ipe-2000ax-SR-10G-WP | 97000-ipe-2000ax-SR-10G-WP | \$ 2,220.00 | 10% | <i>\$2,012.99</i> |
| EW TAC OS ipe-2000ax-Sx | 97000-ipe-2000ax-Sx | \$ 1,850.00 | 10% | <i>\$1,677.49</i> |
| EW TAC OS ipe-2000ax-Sx-WP | 97000-ipe-2000ax-Sx-WP | \$ 1,850.00 | 10% | <i>\$1,677.49</i> |
| EW TAC OS ipe-2000ax-T | 97000-ipe-2000ax-T | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW TAC OS ipe-2000ax-T-WP | 97000-ipe-2000ax-T-WP | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW TAC OS ipe-30ax | 97000-ipe-30ax | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW TAC OS ipe-30ax-WP | 97000-ipe-30ax-WP | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW TAC OS ipe-30so | 97000-ipe-30so | \$ 57.00 | 10% | <i>\$51.68</i> |
| EW TAC OS ipe-30so-WP | 97000-ipe-30so-WP | \$ 57.00 | 10% | <i>\$51.68</i> |
| EW TAC OS ipe-4000ax-10Lr-10G | 97000-ipe-4000ax-10Lr-10G | \$ 7,325.00 | 10% | <i>\$6,641.94</i> |
| EW TAC OS ipe-4000ax-10Lr-3.5G | 97000-ipe-4000ax-10Lr-3.5G | \$ 4,130.00 | 10% | <i>\$3,744.88</i> |
| EW TAC OS ipe-4000ax-10Lr-7G | 97000-ipe-4000ax-10Lr-7G | \$ 5,919.00 | 10% | <i>\$5,367.05</i> |
| EW TAC OS ipe-4000ax-10Sr-10G | 97000-ipe-4000ax-10Sr-10G | \$ 7,251.00 | 10% | <i>\$6,574.84</i> |
| EW TAC OS ipe-4000ax-10Sr-3.5G | 97000-ipe-4000ax-10Sr-3.5G | \$ 4,060.00 | 10% | <i>\$3,681.41</i> |
| EW TAC OS ipe-4000ax-10Sr-7G | 97000-ipe-4000ax-10Sr-7G | \$ 5,845.00 | 10% | <i>\$5,299.95</i> |
| EW TAC OS ipe-4000ax-20Lr-10G | 97000-ipe-4000ax-20Lr-10G | \$ 8,805.00 | 10% | <i>\$7,983.93</i> |

| | | | | |
|-------------------------------|---------------------------|--------------|-----|--------------------|
| EW TAC OS ipe-4000ax-20Lr-14G | 97000-ipe-4000ax-20Lr-14G | \$ 10,285.00 | 10% | <i>\$9,325.92</i> |
| EW TAC OS ipe-4000ax-20Lr-20G | 97000-ipe-4000ax-20Lr-20G | \$ 13,170.00 | 10% | <i>\$11,941.90</i> |
| EW TAC OS ipe-4000ax-20Lr-7G | 97000-ipe-4000ax-20Lr-7G | \$ 7,325.00 | 10% | <i>\$6,641.94</i> |
| EW TAC OS ipe-4000ax-20Sr-10G | 97000-ipe-4000ax-20Sr-10G | \$ 8,731.00 | 10% | <i>\$7,916.83</i> |
| EW TAC OS ipe-4000ax-20Sr-14G | 97000-ipe-4000ax-20Sr-14G | \$ 10,210.00 | 10% | <i>\$9,257.92</i> |
| EW TAC OS ipe-4000ax-20Sr-20G | 97000-ipe-4000ax-20Sr-20G | \$ 13,097.00 | 10% | <i>\$11,875.70</i> |
| EW TAC OS ipe-4000ax-20Sr-7G | 97000-ipe-4000ax-20Sr-7G | \$ 7,251.00 | 10% | <i>\$6,574.84</i> |
| EW TAC OS ipe-4002ax | 97000-ipe-4002ax | \$ 1,406.00 | 10% | <i>\$1,274.89</i> |
| EW TAC OS ipe-400ax | 97000-ipe-400ax | \$ 359.00 | 10% | <i>\$325.52</i> |
| EW TAC OS ipe-400ax-WP | 97000-ipe-400ax-WP | \$ 359.00 | 10% | <i>\$325.52</i> |
| EW TAC OS ipe-40ax | 97000-ipe-40ax | \$ 138.00 | 10% | <i>\$125.13</i> |
| EW TAC OS ipe-40ax-V2 | 97000-ipe-40ax-V2 | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW TAC OS ipe-40ax-V2-WP | 97000-ipe-40ax-V2-WP | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW TAC OS ipe-40so | 97000-ipe-40so | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW TAC OS ipe-40so-V2 | 97000-ipe-40so-V2 | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW TAC OS ipe-40so-V2-WP | 97000-ipe-40so-V2-WP | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW TAC OS ipe-420ax | 97000-ipe-420ax | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW TAC OS ipe-420ax-WP | 97000-ipe-420ax-WP | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW TAC OS ipr-4108Lr | 97000-ipr-4108Lr | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |

| | | | | |
|---------------------------------|-----------------------------|-------------|-----|-------------------|
| EW TAC OS ipr-4108Sr | 97000-ipr-4108Sr | \$ 1,481.00 | 10% | <i>\$1,342.90</i> |
| EW TAC OS ISD-ipe-2000ax-LR-10G | 97000-ISD-ipe-2000ax-LR-10G | \$ 1,410.00 | 10% | <i>\$1,278.52</i> |
| EW TAC OS ISD-ipe-2000ax-Lx | 97000-ISD-ipe-2000ax-Lx | \$ 1,057.00 | 10% | <i>\$958.43</i> |
| EW TAC OS ISD-ipe-2000ax-SR-10G | 97000-ISD-ipe-2000ax-SR-10G | \$ 1,410.00 | 10% | <i>\$1,278.52</i> |
| EW TAC OS ISD-ipe-2000ax-Sx | 97000-ISD-ipe-2000ax-Sx | \$ 1,057.00 | 10% | <i>\$958.43</i> |
| EW TAC OS ISD-ipe-2000ax-T | 97000-ISD-ipe-2000ax-T | \$ 775.00 | 10% | <i>\$702.73</i> |
| EW TAC OS ISD-ipe-30ax | 97000-ISD-ipe-30ax | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW TAC OS ISD-ipe-30so | 97000-ISD-ipe-30so | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW TAC OS ISD-ipe-400ax | 97000-ISD-ipe-400ax | \$ 328.00 | 10% | <i>\$297.41</i> |
| EW TAC OS ISD-ipe-40ax-V2 | 97000-ISD-ipe-40ax-V2 | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW TAC OS ISD-ipe-40so-V2 | 97000-ISD-ipe-40so-V2 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW TAC OS ISD-ipe-420ax | 97000-ISD-ipe-420ax | \$ 331.00 | 10% | <i>\$300.13</i> |
| EW TAC OS ISW-24W-4X | 97000-ISW-24W-4X | \$ 475.00 | 10% | <i>\$430.71</i> |
| EW TAC OS ISW-4W-4WS-4X | 97000-ISW-4W-4WS-4X | \$ 303.00 | 10% | <i>\$274.75</i> |
| EW TAC OS BD MSM128 | 97000-MSM128 | \$ 1,486.00 | 10% | <i>\$1,347.43</i> |
| EW TAC OS BD MSM48C | 97000-MSM48C | \$ 900.00 | 10% | <i>\$816.08</i> |
| EW software TAC S22027 | 97000-S22027 | \$ 730.00 | 6% | <i>\$691.35</i> |
| EW software TAC S22028 | 97000-S22028 | \$ 684.00 | 6% | <i>\$647.78</i> |
| EW software TAC S22030 | 97000-S22030 | \$ 409.00 | 6% | <i>\$387.34</i> |
| EW software TAC S22031 | 97000-S22031 | \$ 824.00 | 6% | <i>\$780.37</i> |
| EW software TAC S22032 | 97000-S22032 | \$ 409.00 | 6% | <i>\$387.34</i> |
| EW software TAC S22035 | 97000-S22035 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EW software TAC S22036 | 97000-S22036 | \$ 393.00 | 6% | <i>\$372.19</i> |
| EW software TAC S22037 | 97000-S22037 | \$ 605.00 | 6% | <i>\$572.97</i> |

| | | | | |
|-----------------------------|-------------------------|--------------|-----|-------------|
| EW software TAC S22038 | 97000-S22038 | \$ 605.00 | 6% | \$572.97 |
| EW software TAC S22039 | 97000-S22039 | \$ 605.00 | 6% | \$572.97 |
| EW software TAC S22040 | 97000-S22040 | \$ 589.00 | 6% | \$557.81 |
| EW software TAC S22041 | 97000-S22041 | \$ 551.00 | 6% | \$521.82 |
| EW software TAC S22042 | 97000-S22042 | \$ 892.00 | 6% | \$844.77 |
| EW software TAC S22044 | 97000-S22044 | \$ 232.00 | 6% | \$219.72 |
| EW software TAC S22045 | 97000-S22045 | \$ 210.00 | 6% | \$198.88 |
| EW software TAC S22046 | 97000-S22046 | \$ 525.00 | 6% | \$497.20 |
| EW software TAC S22047 | 97000-S22047 | \$ 492.00 | 6% | \$465.95 |
| EW software TAC S22055 | 97000-S22055 | \$ 771.00 | 6% | \$730.18 |
| EW software TAC S22057 | 97000-S22057 | \$ 2,133.00 | 6% | \$2,020.06 |
| EW software TAC S22072 | 97000-S22072 | \$ 904.00 | 6% | \$856.13 |
| EW software TAC S22073 | 97000-S22073 | \$ 904.00 | 6% | \$856.13 |
| EW software TAC S22074 | 97000-S22074 | \$ 131.00 | 6% | \$124.06 |
| EW software TAC S22075 | 97000-S22075 | \$ 782.00 | 6% | \$740.59 |
| EW software TAC S22117 | 97000-S22117 | \$ 605.00 | 6% | \$572.97 |
| EW software TAC S22119 | 97000-S22119 | \$ 1,505.00 | 6% | \$1,425.31 |
| EW software TAC S22123 | 97000-S22123 | \$ 79.00 | 6% | \$74.82 |
| EW software TAC S22124 | 97000-S22124 | \$ 178.00 | 6% | \$168.57 |
| EW software TAC S22144 | 97000-S22144 | \$ 2,615.00 | 6% | \$2,476.54 |
| EW software TAC S22145 | 97000-S22145 | \$ 5,232.00 | 6% | \$4,954.97 |
| EW software TAC S22146 | 97000-S22146 | \$ 13,075.00 | 6% | \$12,382.68 |
| EW software TAC S22147 | 97000-S22147 | \$ 26,173.00 | 6% | \$24,787.14 |
| EW software TAC S22148 | 97000-S22148 | \$ 243.00 | 6% | \$230.13 |
| EW software TAC S22149 | 97000-S22149 | \$ 1,211.00 | 6% | \$1,146.88 |
| EW software TAC S22150 | 97000-S22150 | \$ 11.00 | 6% | \$10.42 |
| EW TAC OS S22181 | 97000-S22181 | \$ 48,000.00 | 6% | \$45,458.40 |
| EW TAC OS S22182 | 97000-S22182 | \$ 9,600.00 | 6% | \$9,091.68 |
| EW TAC OS SLX9150-48XT-DC-F | 97000-SLX9150-48XT-DC-F | \$ 1,276.00 | 10% | \$1,157.01 |
| EW TAC OS SLX9150-48XT-DC-R | 97000-SLX9150-48XT-DC-R | \$ 1,393.00 | 10% | \$1,263.10 |
| EW TAC OS SLX9150-48Y-DC-F | 97000-SLX9150-48Y-DC-F | \$ 1,222.00 | 10% | \$1,108.05 |
| EW TAC OS SLX9150-48Y-DC-R | 97000-SLX9150-48Y-DC-R | \$ 1,335.00 | 10% | \$1,210.51 |
| EW TAC OS SLX9740-40C | 97000-SLX9740-40C | \$ 6,907.00 | 10% | \$6,262.92 |

| | | | | |
|-----------------------------|-------------------------|--------------|-----|-------------|
| EW TAC OS SLX9740-40C-AC-F | 97000-SLX9740-40C-AC-F | \$ 6,907.00 | 10% | \$6,262.92 |
| EW TAC OS SLX9740-40C-AC-R | 97000-SLX9740-40C-AC-R | \$ 6,907.00 | 10% | \$6,262.92 |
| EW TAC OS SLX9740-40C-DC-F | 97000-SLX9740-40C-DC-F | \$ 6,907.00 | 10% | \$6,262.92 |
| EW TAC OS SLX9740-80C | 97000-SLX9740-80C | \$ 12,986.00 | 10% | \$11,775.06 |
| EW TAC OS SLX9740-80C-AC-F | 97000-SLX9740-80C-AC-F | \$ 12,986.00 | 10% | \$11,775.06 |
| EW TAC OS SLX9740-80C-AC-R | 97000-SLX9740-80C-AC-R | \$ 12,986.00 | 10% | \$11,775.06 |
| EW TAC OS SLX9740-80C-DC-F | 97000-SLX9740-80C-DC-F | \$ 12,986.00 | 10% | \$11,775.06 |
| EW TAC OS SLX9740-ADV-LIC-P | 97000-SLX9740-ADV-LIC-P | \$ 1,252.00 | 10% | \$1,135.25 |
| EW TAC OS V300-8P-2X | 97000-V300-8P-2X | \$ 82.00 | 10% | \$74.35 |
| EW TAC OS V300-8T-2X | 97000-V300-8T-2X | \$ 56.00 | 10% | \$50.78 |
| EW TAC OS V300HT-8P-2X | 97000-V300HT-8P-2X | \$ 194.00 | 10% | \$175.91 |
| EW TAC OS V300HT-8T-2X | 97000-V300HT-8T-2X | \$ 117.00 | 10% | \$106.09 |
| EW TAC OS Summit VIM-SS | 97000-VIM-SS | \$ 79.00 | 10% | \$71.63 |
| EW TAC OS Summit VIM-SSV80 | 97000-VIM-SSV80 | \$ 143.00 | 10% | \$129.67 |
| EW TAC OS Summit VIM2-SS | 97000-VIM2-SS | \$ 93.00 | 10% | \$84.33 |
| EW TAC OS Summit VIM2-SS128 | 97000-VIM2-SS128 | \$ 299.00 | 10% | \$271.12 |
| EW TAC OS Summit VIM2-V80 | 97000-VIM2-V80 | \$ 322.00 | 10% | \$291.97 |

| | | | | |
|-------------------------------------|---|-----------|-----|-----------------|
| EW TAC OS Summit VIM210G4X | 97000- VIM210G4X | \$ 568.00 | 10% | <i>\$515.03</i> |
| EW TAC OS VIM5-2Q | 97000-VIM5- 2Q | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW TAC OS VIM5-2Y | 97000-VIM5- 2Y | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW TAC OS VIM5-4X | 97000-VIM5- 4X | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW TAC OS VIM5-4XE | 97000-VIM5- 4XE | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW TAC OS VIM5-4Y | 97000-VIM5- 4Y | \$ 151.00 | 10% | <i>\$136.92</i> |
| EW TAC OS VIM5-4YE | 97000-VIM5- 4YE | \$ 199.00 | 10% | <i>\$180.44</i> |
| EW TAC OS VSP4900-12MXU- 12XE | 97000- VSP4900- 12MXU-12XE | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW TAC OS VSP4900-12MXU- 12XE-B1 | 97000- VSP4900- 12MXU-12XE- B1 | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW TAC OS VSP4900-24S | 97000- VSP4900-24S | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW TAC OS VSP4900-24S-B3 | 97000- VSP4900-24S- B3 | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW TAC OS VSP4900-24XE | 97000- VSP4900- 24XE | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW TAC OS VSP4900-24XE- B3 | 97000- VSP4900- 24XE-B3 | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW TAC OS X435-24P-4S | 97000-X435- 24P-4S | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW TAC OS X435-24T-4S | 97000-X435- 24T-4S | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW TAC OS X435-8P-2T-W | 97000-X435- 8P-2T-W | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW TAC OS X435-8P-4S | 97000-X435- 8P-4S | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW TAC OS X435-8T-4S | 97000-X435- 8T-4S | \$ 57.00 | 10% | <i>\$51.68</i> |

| | | | | |
|-----------------------------|--------------------|-----------|-----|-----------------|
| EW TAC OS Summit X460-24P | 97000-X460-24P | \$ 524.00 | 10% | <i>\$475.14</i> |
| EW TAC OS Summit X460-24T | 97000-X460-24T | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW TAC OS Summit X460-24TDC | 97000-X460-24TDC | \$ 540.00 | 10% | <i>\$489.65</i> |
| EW TAC OS Summit X460-24X | 97000-X460-24X | \$ 691.00 | 10% | <i>\$626.56</i> |
| EW TAC OS Summit X460-24XDC | 97000-X460-24XDC | \$ 772.00 | 10% | <i>\$700.01</i> |
| EW TAC OS Summit X460-48P | 97000-X460-48P | \$ 691.00 | 10% | <i>\$626.56</i> |
| EW TAC OS Summit X460-48T | 97000-X460-48T | \$ 590.00 | 10% | <i>\$534.98</i> |
| EW TAC OS Summit X460-48TDC | 97000-X460-48TDC | \$ 750.00 | 10% | <i>\$680.06</i> |
| EW TAC OS Summit X460-48X | 97000-X460-48X | \$ 924.00 | 10% | <i>\$837.84</i> |
| EW TAC OS Summit X460-48XDC | 97000-X460-48XDC | \$ 895.00 | 10% | <i>\$811.54</i> |
| EW TAC OS Summit X460CORE | 97000-X460CORE | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW TAC OS Summit X460MPLS | 97000-X460MPLS | \$ 159.00 | 10% | <i>\$144.17</i> |
| EW TAC OS Summit X460NS | 97000-X460NS | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW TAC OS X465-24MU | 97000-X465-24MU | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS X465-24S | 97000-X465-24S | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW TAC OS X465-24S-B3 | 97000-X465-24S-B3 | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW TAC OS X465-24W | 97000-X465-24W | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW TAC OS X465-24XE | 97000-X465-24XE | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW TAC OS X465-24XE-B3 | 97000-X465-24XE-B3 | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW TAC OS X465-48P | 97000-X465-48P | \$ 489.00 | 10% | <i>\$443.40</i> |
| EW TAC OS X465-48T | 97000-X465-48T | \$ 472.00 | 10% | <i>\$427.99</i> |

| | | | | |
|---------------------------|-----------------------|-------------|-----|-------------------|
| EW TAC OS X465-48W | 97000-X465-48W | \$ 623.00 | 10% | <i>\$564.91</i> |
| EW TAC OS X465i-48W | 97000-X465i-48W | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS X465i-48W-B1-S1 | 97000-X465i-48W-B1-S1 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS X465i-48W-B2-S1 | 97000-X465i-48W-B2-S1 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW TAC OS Summit X480-24X | 97000-X480-24X | \$ 848.00 | 10% | <i>\$768.92</i> |
| EW TAC OS Summit X480-48T | 97000-X480-48T | \$ 848.00 | 10% | <i>\$768.92</i> |
| EW TAC OS Summit X480-48X | 97000-X480-48X | \$ 1,129.00 | 10% | <i>\$1,023.72</i> |
| EW TAC OS Summit X480CORE | 97000-X480CORE | \$ 434.00 | 10% | <i>\$393.53</i> |
| EW TAC OS Summit X480MPLS | 97000-X480MPLS | \$ 224.00 | 10% | <i>\$203.11</i> |
| EW TAC OS X695-48Y-8C | 97000-X695-48Y-8C | \$ 1,707.00 | 10% | <i>\$1,547.82</i> |
| EW TAC OS Summit XGM3-2SF | 97000-XGM3-2SF | \$ 143.00 | 10% | <i>\$129.67</i> |
| EW TAC OS XR600 | 97000-XR600 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW TAC OS -ZR-XFP | 97000-ZR-XFP | \$ 901.00 | 10% | <i>\$816.98</i> |
| EW SOFTWARE SUPPORT 30313 | 97003-30313 | \$ 558.00 | 6% | <i>\$528.45</i> |
| EW SOFTWARE SUPPORT 30314 | 97003-30314 | \$ 575.00 | 6% | <i>\$544.55</i> |
| EW SOFTWARE SUPPORT 30316 | 97003-30316 | \$ 575.00 | 6% | <i>\$544.55</i> |
| EW SOFTWARE SUPPORT 30324 | 97003-30324 | \$ 539.00 | 6% | <i>\$510.46</i> |
| EW SOFTWARE SUPPORT 30326 | 97003-30326 | \$ 539.00 | 6% | <i>\$510.46</i> |
| EW SOFTWARE SUPPORT 30327 | 97003-30327 | \$ 413.00 | 6% | <i>\$391.13</i> |
| EW SOFTWARE SUPPORT 30328 | 97003-30328 | \$ 2,057.00 | 6% | <i>\$1,948.08</i> |
| EW SOFTWARE SUPPORT 30329 | 97003-30329 | \$ 8,226.00 | 6% | <i>\$7,790.43</i> |

| | | | | |
|------------------------------|-------------|---------------|----|---------------------|
| EW SOFTWARE SUPPORT 30330 | 97003-30330 | \$ 41,128.00 | 6% | <i>\$38,950.27</i> |
| EW SOFTWARE SUPPORT 30331 | 97003-30331 | \$ 164,512.00 | 6% | <i>\$155,801.09</i> |
| EW SOFTWARE SUPPORT 39521 | 97003-39521 | \$ 585.00 | 6% | <i>\$554.02</i> |
| EW SOFTWARE SUPPORT 39522 | 97003-39522 | \$ 5,840.00 | 6% | <i>\$5,530.77</i> |
| EW SOFTWARE SUPPORT 39523 | 97003-39523 | \$ 58,401.00 | 6% | <i>\$55,308.67</i> |
| EW SOFTWARE SUPPORT 39524 | 97003-39524 | \$ 292,005.00 | 6% | <i>\$276,543.34</i> |
| EW SOFTWARE SUPPORT 39525 | 97003-39525 | \$ 584,010.00 | 6% | <i>\$553,086.67</i> |
| EW SOFTWARE SUPPORT 48101 | 97003-48101 | \$ 6,294.00 | 6% | <i>\$5,960.73</i> |
| EW SOFTWARE SUPPORT 85108 | 97003-85108 | \$ 248.00 | 6% | <i>\$234.87</i> |
| EW SOFTWARE SUPPORT 85109 | 97003-85109 | \$ 498.00 | 6% | <i>\$471.63</i> |
| EW SOFTWARE SUPPORT 85110 | 97003-85110 | \$ 868.00 | 6% | <i>\$822.04</i> |
| EW SOFTWARE SUPPORT 85111 | 97003-85111 | \$ 1,487.00 | 6% | <i>\$1,408.26</i> |
| EW SOFTWARE SUPPORT 85112 | 97003-85112 | \$ 2,232.00 | 6% | <i>\$2,113.82</i> |
| EW SOFTWARE SUPPORT 85113 | 97003-85113 | \$ 3,718.00 | 6% | <i>\$3,521.13</i> |
| EW SOFTWARE SUPPORT 85114 | 97003-85114 | \$ 4,958.00 | 6% | <i>\$4,695.47</i> |
| EW SOFTWARE SUPPORT 85115 | 97003-85115 | \$ 248.00 | 6% | <i>\$234.87</i> |
| EW SOFTWARE SUPPORT 85116 | 97003-85116 | \$ 372.00 | 6% | <i>\$352.30</i> |
| EW SOFTWARE SUPPORT 85117 | 97003-85117 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EW SOFTWARE SUPPORT 85118 | 97003-85118 | \$ 744.00 | 6% | <i>\$704.61</i> |
| EW SOFTWARE SUPPORT 85119 | 97003-85119 | \$ 1,487.00 | 6% | <i>\$1,408.26</i> |
| EW SOFTWARE SUPPORT 85120 | 97003-85120 | \$ 1,239.00 | 6% | <i>\$1,173.39</i> |

| | | | | |
|--------------------------------|----------------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT 88201 | 97003-88201 | \$ 2,226.00 | 6% | <i>\$2,108.13</i> |
| EW SOFTWARE SUPPORT 88202 | 97003-88202 | \$ 6,250.00 | 6% | <i>\$5,919.06</i> |
| EW SOFTWARE SUPPORT 88203 | 97003-88203 | \$ 23,613.00 | 6% | <i>\$22,362.69</i> |
| EW SOFTWARE SUPPORT 88211 | 97003-88211 | \$ 2,769.00 | 6% | <i>\$2,622.38</i> |
| EW SOFTWARE SUPPORT 88212 | 97003-88212 | \$ 5,280.00 | 6% | <i>\$5,000.42</i> |
| EW SOFTWARE SUPPORT 88213 | 97003-88213 | \$ 2,440.00 | 6% | <i>\$2,310.80</i> |
| EW SOFTWARE SUB EXTR- IQ-TC | 97003-EXTR- IQ-TC | \$ 330.00 | 6% | <i>\$312.53</i> |
| EW SOFTWARE SUPPORT ISU-P | 97003-ISU-P | \$ 29.00 | 6% | <i>\$27.46</i> |
| EW SOFTWARE SUPPORT NACVX5 | 97003-NAC- VX-5 | \$ 1,321.00 | 6% | <i>\$1,251.05</i> |
| EW SOFTWARE SUPPORT S20097 | 97003-S20097 | \$ 21,893.00 | 6% | <i>\$20,733.77</i> |
| EW SOFTWARE SUPPORT S20098 | 97003-S20098 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EW SOFTWARE SUPPORT S20099 | 97003-S20099 | \$ 5,853.00 | 6% | <i>\$5,543.08</i> |
| EW SOFTWARE SUPPORT S20100 | 97003-S20100 | \$ 10,004.00 | 6% | <i>\$9,474.29</i> |
| EW SOFTWARE SUPPORT S20101 | 97003-S20101 | \$ 2,589.00 | 6% | <i>\$2,451.91</i> |
| EW SOFTWARE SUPPORT S20112 | 97003-S20112 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EW SOFTWARE SUPPORT S20113 | 97003-S20113 | \$ 10,004.00 | 6% | <i>\$9,474.29</i> |
| EW SOFTWARE SUPPORT S20114 | 97003-S20114 | \$ 3,932.00 | 6% | <i>\$3,723.80</i> |
| EW SOFTWARE SUPPORT S20116 | 97003-S20116 | \$ 3,222.00 | 6% | <i>\$3,051.40</i> |
| EW SOFTWARE SUPPORT S20117 | 97003-S20117 | \$ 1,163.00 | 6% | <i>\$1,101.42</i> |
| EW SOFTWARE SUPPORT S20119 | 97003-S20119 | \$ 792.00 | 6% | <i>\$750.06</i> |
| EW SOFTWARE SUPPORT S20120 | 97003-S20120 | \$ 4,710.00 | 6% | <i>\$4,460.61</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S20121 | 97003-S20121 | \$ 14,251.00 | 6% | <i>\$13,496.41</i> |
| EW SOFTWARE SUPPORT S20122 | 97003-S20122 | \$ 4,785.00 | 6% | <i>\$4,531.63</i> |
| EW SOFTWARE SUPPORT S20124 | 97003-S20124 | \$ 4,379.00 | 6% | <i>\$4,147.13</i> |
| EW SOFTWARE SUPPORT S20125 | 97003-S20125 | \$ 1,955.00 | 6% | <i>\$1,851.48</i> |
| EW SOFTWARE SUPPORT S20127 | 97003-S20127 | \$ 2,589.00 | 6% | <i>\$2,451.91</i> |
| EW SOFTWARE SUPPORT S20128 | 97003-S20128 | \$ 1,274.00 | 6% | <i>\$1,206.54</i> |
| EW SOFTWARE SUPPORT S20129 | 97003-S20129 | \$ 6,879.00 | 6% | <i>\$6,514.76</i> |
| EW SOFTWARE SUPPORT S20130 | 97003-S20130 | \$ 20,013.00 | 6% | <i>\$18,953.31</i> |
| EW SOFTWARE SUPPORT S20131 | 97003-S20131 | \$ 6,087.00 | 6% | <i>\$5,764.69</i> |
| EW SOFTWARE SUPPORT S20133 | 97003-S20133 | \$ 5,853.00 | 6% | <i>\$5,543.08</i> |
| EW SOFTWARE SUPPORT S20134 | 97003-S20134 | \$ 2,913.00 | 6% | <i>\$2,758.76</i> |
| EW SOFTWARE SUPPORT S20136 | 97003-S20136 | \$ 2,239.00 | 6% | <i>\$2,120.44</i> |
| EW SOFTWARE SUPPORT S20137 | 97003-S20137 | \$ 929.00 | 6% | <i>\$879.81</i> |
| EW SOFTWARE SUPPORT S20139 | 97003-S20139 | \$ 4,152.00 | 6% | <i>\$3,932.15</i> |
| EW SOFTWARE SUPPORT S20140 | 97003-S20140 | \$ 1,041.00 | 6% | <i>\$985.88</i> |
| EW SOFTWARE SUPPORT S20141 | 97003-S20141 | \$ 5,102.00 | 6% | <i>\$4,831.85</i> |
| EW SOFTWARE SUPPORT S20142 | 97003-S20142 | \$ 3,415.00 | 6% | <i>\$3,234.18</i> |
| EW SOFTWARE SUPPORT S20143 | 97003-S20143 | \$ 7,058.00 | 6% | <i>\$6,684.28</i> |
| EW SOFTWARE SUPPORT S20144 | 97003-S20144 | \$ 3,127.00 | 6% | <i>\$2,961.43</i> |
| EW SOFTWARE SUPPORT S20145 | 97003-S20145 | \$ 3,250.00 | 6% | <i>\$3,077.91</i> |
| EW SOFTWARE SUPPORT S20146 | 97003-S20146 | \$ 13,941.00 | 6% | <i>\$13,202.82</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S20149 | 97003-S20149 | \$ 6,664.00 | 6% | <i>\$6,311.14</i> |
| EW SOFTWARE SUPPORT S20150 | 97003-S20150 | \$ 19,043.00 | 6% | <i>\$18,034.67</i> |
| EW SOFTWARE SUPPORT S20153 | 97003-S20153 | \$ 2,204.00 | 6% | <i>\$2,087.30</i> |
| EW SOFTWARE SUPPORT S20154 | 97003-S20154 | \$ 9,790.00 | 6% | <i>\$9,271.62</i> |
| EW SOFTWARE SUPPORT S20155 | 97003-S20155 | \$ 26,093.00 | 6% | <i>\$24,711.38</i> |
| EW SOFTWARE SUPPORT S20159 | 97003-S20159 | \$ 36,026.00 | 6% | <i>\$34,118.42</i> |
| EW SOFTWARE SUPPORT S20161 | 97003-S20161 | \$ 9,934.00 | 6% | <i>\$9,407.99</i> |
| EW SOFTWARE SUPPORT S20162 | 97003-S20162 | \$ 6,347.00 | 6% | <i>\$6,010.93</i> |
| EW SOFTWARE SUPPORT S20163 | 97003-S20163 | \$ 1,624.00 | 6% | <i>\$1,538.01</i> |
| EW SOFTWARE SUPPORT S20164 | 97003-S20164 | \$ 1,624.00 | 6% | <i>\$1,538.01</i> |
| EW SOFTWARE SUPPORT S20165 | 97003-S20165 | \$ 8,619.00 | 6% | <i>\$8,162.62</i> |
| EW SOFTWARE SUPPORT S20166 | 97003-S20166 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EW SOFTWARE SUPPORT S20167 | 97003-S20167 | \$ 3,485.00 | 6% | <i>\$3,300.47</i> |
| EW SOFTWARE SUPPORT S20168 | 97003-S20168 | \$ 683.00 | 6% | <i>\$646.84</i> |
| EW SOFTWARE SUPPORT S20169 | 97003-S20169 | \$ 11,805.00 | 6% | <i>\$11,179.93</i> |
| EW SOFTWARE SUPPORT S20170 | 97003-S20170 | \$ 2,760.00 | 6% | <i>\$2,613.86</i> |
| EW SOFTWARE SUPPORT S20171 | 97003-S20171 | \$ 4,710.00 | 6% | <i>\$4,460.61</i> |
| EW SOFTWARE SUPPORT S20172 | 97003-S20172 | \$ 929.00 | 6% | <i>\$879.81</i> |
| EW SOFTWARE SUPPORT S20173 | 97003-S20173 | \$ 462.00 | 6% | <i>\$437.54</i> |
| EW SOFTWARE SUPPORT S20174 | 97003-S20174 | \$ 3,753.00 | 6% | <i>\$3,554.28</i> |
| EW SOFTWARE SUPPORT S20177 | 97003-S20177 | \$ 1,163.00 | 6% | <i>\$1,101.42</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S20178 | 97003-S20178 | \$ 5,853.00 | 6% | <i>\$5,543.08</i> |
| EW SOFTWARE SUPPORT S20181 | 97003-S20181 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EW SOFTWARE SUPPORT S20182 | 97003-S20182 | \$ 8,619.00 | 6% | <i>\$8,162.62</i> |
| EW SOFTWARE SUPPORT S20185 | 97003-S20185 | \$ 11,805.00 | 6% | <i>\$11,179.93</i> |
| EW SOFTWARE SUPPORT S20187 | 97003-S20187 | \$ 3,222.00 | 6% | <i>\$3,051.40</i> |
| EW SOFTWARE SUPPORT S20188 | 97003-S20188 | \$ 16,798.00 | 6% | <i>\$15,908.55</i> |
| EW SOFTWARE SUPPORT S20189 | 97003-S20189 | \$ 28,681.00 | 6% | <i>\$27,162.34</i> |
| EW SOFTWARE SUPPORT S20190 | 97003-S20190 | \$ 7,346.00 | 6% | <i>\$6,957.03</i> |
| EW SOFTWARE SUPPORT S20192 | 97003-S20192 | \$ 8,619.00 | 6% | <i>\$8,162.62</i> |
| EW SOFTWARE SUPPORT S20213 | 97003-S20213 | \$ 2,164.00 | 6% | <i>\$2,049.42</i> |
| EW SOFTWARE SUPPORT S20245 | 97003-S20245 | \$ 7,456.00 | 6% | <i>\$7,061.20</i> |
| EW SOFTWARE SUPPORT S20246 | 97003-S20246 | \$ 44,802.00 | 6% | <i>\$42,429.73</i> |
| EW SOFTWARE SUPPORT S20247 | 97003-S20247 | \$ 73,131.00 | 6% | <i>\$69,258.71</i> |
| EW SOFTWARE SUPPORT S20248 | 97003-S20248 | \$ 28,681.00 | 6% | <i>\$27,162.34</i> |
| EW SOFTWARE SUPPORT S20252 | 97003-S20252 | \$ 32.00 | 6% | <i>\$30.31</i> |
| EW SOFTWARE SUPPORT S20253 | 97003-S20253 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| EW SOFTWARE SUPPORT S20254 | 97003-S20254 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| EW SOFTWARE SUPPORT S20255 | 97003-S20255 | \$ 261.00 | 6% | <i>\$247.18</i> |
| EW SOFTWARE SUPPORT S20256 | 97003-S20256 | \$ 261.00 | 6% | <i>\$247.18</i> |
| EW SOFTWARE SUPPORT S20257 | 97003-S20257 | \$ 32.00 | 6% | <i>\$30.31</i> |
| EW SOFTWARE SUPPORT S20258 | 97003-S20258 | \$ 318.00 | 6% | <i>\$301.16</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EW SOFTWARE SUPPORT S20259 | 97003-S20259 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EW SOFTWARE SUPPORT S20260 | 97003-S20260 | \$ 569.00 | 6% | <i>\$538.87</i> |
| EW SOFTWARE SUPPORT S20261 | 97003-S20261 | \$ 303.00 | 6% | <i>\$286.96</i> |
| EW SOFTWARE SUPPORT S20268 | 97003-S20268 | \$ 32.00 | 6% | <i>\$30.31</i> |
| EW SOFTWARE SUPPORT S20269 | 97003-S20269 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| EW SOFTWARE SUPPORT S20270 | 97003-S20270 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| EW SOFTWARE SUPPORT S20271 | 97003-S20271 | \$ 261.00 | 6% | <i>\$247.18</i> |
| EW SOFTWARE SUPPORT S20272 | 97003-S20272 | \$ 261.00 | 6% | <i>\$247.18</i> |
| EW SOFTWARE SUPPORT S20273 | 97003-S20273 | \$ 32.00 | 6% | <i>\$30.31</i> |
| EW SOFTWARE SUPPORT S20274 | 97003-S20274 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EW SOFTWARE SUPPORT S20275 | 97003-S20275 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EW SOFTWARE SUPPORT S20279 | 97003-S20279 | \$ 569.00 | 6% | <i>\$538.87</i> |
| EW SOFTWARE SUPPORT S20281 | 97003-S20281 | \$ 558.00 | 6% | <i>\$528.45</i> |
| EW SOFTWARE SUPPORT S20182 | 97003-S20282 | \$ 558.00 | 6% | <i>\$528.45</i> |
| EW SOFTWARE SUPPORT S20283 | 97003-S20283 | \$ 575.00 | 6% | <i>\$544.55</i> |
| EW SOFTWARE SUPPORT S20284 | 97003-S20284 | \$ 558.00 | 6% | <i>\$528.45</i> |
| EW SOFTWARE SUPPORT 20293 | 97003-S20293 | \$ 1,481.00 | 6% | <i>\$1,402.58</i> |
| EW SOFTWARE SUPPORT S20296 | 97003-S20296 | \$ 4,463.00 | 6% | <i>\$4,226.68</i> |
| EW SOFTWARE SUPPORT S20298 | 97003-S20298 | \$ 2,126.00 | 6% | <i>\$2,013.43</i> |
| EW SOFTWARE SUPPORT S20299 | 97003-S20299 | \$ 4,802.00 | 6% | <i>\$4,547.73</i> |
| EW SOFTWARE SUPPORT S20300 | 97003-S20300 | \$ 7,013.00 | 6% | <i>\$6,641.66</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S20301 | 97003-S20301 | \$ 10,199.00 | 6% | <i>\$9,658.96</i> |
| EW SOFTWARE SUPPORT S20302 | 97003-S20302 | \$ 14,529.00 | 6% | <i>\$13,759.69</i> |
| EW SOFTWARE SUPPORT S20303 | 97003-S20303 | \$ 20,402.00 | 6% | <i>\$19,321.71</i> |
| EW SOFTWARE SUPPORT S20304 | 97003-S20304 | \$ 29,237.00 | 6% | <i>\$27,688.90</i> |
| EW SOFTWARE SUPPORT S20309 | 97003-S20309 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EW SOFTWARE SUPPORT S20310 | 97003-S20310 | \$ 70.00 | 6% | <i>\$66.29</i> |
| EW SOFTWARE SUPPORT S20313 | 97003-S20313 | \$ 2,597.00 | 6% | <i>\$2,459.49</i> |
| EW SOFTWARE SUPPORT S20314 | 97003-S20314 | \$ 48.00 | 6% | <i>\$45.46</i> |
| EW SOFTWARE SUPPORT S20330 | 97003-S20330 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EW SOFTWARE SUPPORT S20331 | 97003-S20331 | \$ 19.00 | 6% | <i>\$17.99</i> |
| EW SOFTWARE SUPPORT S20343 | 97003-S20343 | \$ 237.00 | 6% | <i>\$224.45</i> |
| EW SOFTWARE SUPPORT S20344 | 97003-S20344 | \$ 2,361.00 | 6% | <i>\$2,235.99</i> |
| EW SOFTWARE SUPPORT S20345 | 97003-S20345 | \$ 25,957.00 | 6% | <i>\$24,582.58</i> |
| EW SOFTWARE SUPPORT S20346 | 97003-S20346 | \$ 51,915.00 | 6% | <i>\$49,166.10</i> |
| EW SOFTWARE SUPPORT S20353 | 97003-S20353 | \$ 6,738.00 | 6% | <i>\$6,381.22</i> |
| EW SOFTWARE SUPPORT S20354 | 97003-S20354 | \$ 534.00 | 6% | <i>\$505.72</i> |
| EW SOFTWARE SUPPORT S20358 | 97003-S20358 | \$ 168.00 | 6% | <i>\$159.10</i> |
| EW SOFTWARE SUPPORT S20359 | 97003-S20359 | \$ 15.00 | 6% | <i>\$14.21</i> |
| EW SOFTWARE SUPPORT S20360 | 97003-S20360 | \$ 208.00 | 6% | <i>\$196.99</i> |
| EW SOFTWARE SUPPORT S20361 | 97003-S20361 | \$ 814.00 | 6% | <i>\$770.90</i> |
| EW SOFTWARE SUPPORT S20362 | 97003-S20362 | \$ 3,266.00 | 6% | <i>\$3,093.07</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S20363 | 97003-S20363 | \$ 13,067.00 | 6% | <i>\$12,375.10</i> |
| EW SOFTWARE SUPPORT S20364 | 97003-S20364 | \$ 26,140.00 | 6% | <i>\$24,755.89</i> |
| EW SOFTWARE SUPPORT S20365 | 97003-S20365 | \$ 15.00 | 6% | <i>\$14.21</i> |
| EW SOFTWARE SUPPORT S20366 | 97003-S20366 | \$ 208.00 | 6% | <i>\$196.99</i> |
| EW SOFTWARE SUPPORT S20367 | 97003-S20367 | \$ 814.00 | 6% | <i>\$770.90</i> |
| EW SOFTWARE SUPPORT S20368 | 97003-S20368 | \$ 3,266.00 | 6% | <i>\$3,093.07</i> |
| EW SOFTWARE SUPPORT S20369 | 97003-S20369 | \$ 13,067.00 | 6% | <i>\$12,375.10</i> |
| EW SOFTWARE SUPPORT S20370 | 97003-S20370 | \$ 26,140.00 | 6% | <i>\$24,755.89</i> |
| EW SOFTWARE SUPPORT S20371 | 97003-S20371 | \$ 15.00 | 6% | <i>\$14.21</i> |
| EW SOFTWARE SUPPORT S20372 | 97003-S20372 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EW SOFTWARE SUPPORT S20373 | 97003-S20373 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EW SOFTWARE SUPPORT S20374 | 97003-S20374 | \$ 701.00 | 6% | <i>\$663.88</i> |
| EW SOFTWARE SUPPORT S20375 | 97003-S20375 | \$ 1,400.00 | 6% | <i>\$1,325.87</i> |
| EW SOFTWARE SUPPORT S20376 | 97003-S20376 | \$ 7,003.00 | 6% | <i>\$6,632.19</i> |
| EW SOFTWARE SUPPORT S20377 | 97003-S20377 | \$ 14,004.00 | 6% | <i>\$13,262.49</i> |
| EW SOFTWARE SUPPORT S20378 | 97003-S20378 | \$ 28,008.00 | 6% | <i>\$26,524.98</i> |
| EW SOFTWARE SUPPORT S20400 | 97003-S20400 | \$ 2,556.00 | 6% | <i>\$2,420.66</i> |
| EW SOFTWARE SUPPORT S20401 | 97003-S20401 | \$ 986.00 | 6% | <i>\$933.79</i> |
| EW SOFTWARE SUPPORT S20412 | 97003-S20412 | \$ 55,201.00 | 6% | <i>\$52,278.11</i> |
| EW SOFTWARE SUPPORT S20414 | 97003-S20414 | \$ 55,201.00 | 6% | <i>\$52,278.11</i> |
| EW SOFTWARE SUPPORT S20415 | 97003-S20415 | \$ 13,800.00 | 6% | <i>\$13,069.29</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S20416 | 97003-S20416 | \$ 13,800.00 | 6% | <i>\$13,069.29</i> |
| EW SOFTWARE SUPPORT S20417 | 97003-S20417 | \$ 13,800.00 | 6% | <i>\$13,069.29</i> |
| EW SOFTWARE SUPPORT S20418 | 97003-S20418 | \$ 13,800.00 | 6% | <i>\$13,069.29</i> |
| EW SOFTWARE SUPPORT S20419 | 97003-S20419 | \$ 55,201.00 | 6% | <i>\$52,278.11</i> |
| EW SOFTWARE SUPPORT S20420 | 97003-S20420 | \$ 20,701.00 | 6% | <i>\$19,604.88</i> |
| EW SOFTWARE SUPPORT S20421 | 97003-S20421 | \$ 41,401.00 | 6% | <i>\$39,208.82</i> |
| EW SOFTWARE SUPPORT S20422 | 97003-S20422 | \$ 20,701.00 | 6% | <i>\$19,604.88</i> |
| EW SOFTWARE SUPPORT S20423 | 97003-S20423 | \$ 5,519.00 | 6% | <i>\$5,226.77</i> |
| EW SOFTWARE SUPPORT S20424 | 97003-S20424 | \$ 2,764.00 | 6% | <i>\$2,617.65</i> |
| EW SOFTWARE SUPPORT S20425 | 97003-S20425 | \$ 5,519.00 | 6% | <i>\$5,226.77</i> |
| EW SOFTWARE SUPPORT S20426 | 97003-S20426 | \$ 2,764.00 | 6% | <i>\$2,617.65</i> |
| EW SOFTWARE SUPPORT S20428 | 97003-S20428 | \$ 1,447.00 | 6% | <i>\$1,370.38</i> |
| EW SOFTWARE SUPPORT S20429 | 97003-S20429 | \$ 746.00 | 6% | <i>\$706.50</i> |
| EW SOFTWARE SUPPORT S20430 | 97003-S20430 | \$ 3,600.00 | 6% | <i>\$3,409.38</i> |
| EW SOFTWARE SUPPORT S20431 | 97003-S20431 | \$ 1,862.00 | 6% | <i>\$1,763.41</i> |
| EW SOFTWARE SUPPORT S20434 | 97003-S20434 | \$ 3,074.00 | 6% | <i>\$2,911.23</i> |
| EW SOFTWARE SUPPORT S20435 | 97003-S20435 | \$ 2,354.00 | 6% | <i>\$2,229.36</i> |
| EW SOFTWARE SUPPORT S20437 | 97003-S20437 | \$ 1,286.00 | 6% | <i>\$1,217.91</i> |
| EW SOFTWARE SUPPORT S20438 | 97003-S20438 | \$ 2,354.00 | 6% | <i>\$2,229.36</i> |
| EW SOFTWARE SUPPORT S20439 | 97003-S20439 | \$ 3,153.00 | 6% | <i>\$2,986.05</i> |
| EW SOFTWARE SUPPORT S20440 | 97003-S20440 | \$ 2,210.00 | 6% | <i>\$2,092.98</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EW SOFTWARE SUPPORT S20441 | 97003-S20441 | \$ 881.00 | 6% | <i>\$834.35</i> |
| EW SOFTWARE SUPPORT S20442 | 97003-S20442 | \$ 1,757.00 | 6% | <i>\$1,663.97</i> |
| EW SOFTWARE SUPPORT S20443 | 97003-S20443 | \$ 1,109.00 | 6% | <i>\$1,050.28</i> |
| EW SOFTWARE SUPPORT S20453 | 97003-S20453 | \$ 2,639.00 | 6% | <i>\$2,499.26</i> |
| EW SOFTWARE SUPPORT S20463 | 97003-S20463 | \$ 557.00 | 6% | <i>\$527.51</i> |
| EW SOFTWARE SUPPORT S20465 | 97003-S20465 | \$ 983.00 | 6% | <i>\$930.95</i> |
| EW SOFTWARE SUPPORT S20477 | 97003-S20477 | \$ 2,818.00 | 6% | <i>\$2,668.79</i> |
| EW SOFTWARE SUPPORT S20478 | 97003-S20478 | \$ 1,619.00 | 6% | <i>\$1,533.27</i> |
| EW SOFTWARE SUPPORT S20479 | 97003-S20479 | \$ 2,818.00 | 6% | <i>\$2,668.79</i> |
| EW SOFTWARE SUPPORT S20480 | 97003-S20480 | \$ 2,570.00 | 6% | <i>\$2,433.92</i> |
| EW SOFTWARE SUPPORT S20481 | 97003-S20481 | \$ 1,025.00 | 6% | <i>\$970.73</i> |
| EW SOFTWARE SUPPORT S22008 | 97003-S22008 | \$ 1,232.00 | 6% | <i>\$1,166.77</i> |
| EW SOFTWARE SUPPORT S22014 | 97003-S22014 | \$ 2,332.00 | 6% | <i>\$2,208.52</i> |
| EW SOFTWARE SUPPORT S22015 | 97003-S22015 | \$ 747.00 | 6% | <i>\$707.45</i> |
| EW SOFTWARE SUPPORT S22016 | 97003-S22016 | \$ 2,054.00 | 6% | <i>\$1,945.24</i> |
| EW SOFTWARE SUPPORT S22017 | 97003-S22017 | \$ 747.00 | 6% | <i>\$707.45</i> |
| EW SOFTWARE SUPPORT S22018 | 97003-S22018 | \$ 2,332.00 | 6% | <i>\$2,208.52</i> |
| EW SOFTWARE SUPPORT S22019 | 97003-S22019 | \$ 2,332.00 | 6% | <i>\$2,208.52</i> |
| EW SOFTWARE SUPPORT S22020 | 97003-S22020 | \$ 2,332.00 | 6% | <i>\$2,208.52</i> |
| EW SOFTWARE SUPPORT S22021 | 97003-S22021 | \$ 2,332.00 | 6% | <i>\$2,208.52</i> |
| EW SOFTWARE SUPPORT S22022 | 97003-S22022 | \$ 2,054.00 | 6% | <i>\$1,945.24</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EW SOFTWARE SUPPORT S22027 | 97003-S22027 | \$ 1,438.00 | 6% | <i>\$1,361.86</i> |
| EW SOFTWARE SUPPORT S22028 | 97003-S22028 | \$ 1,346.00 | 6% | <i>\$1,274.73</i> |
| EW SOFTWARE SUPPORT S22030 | 97003-S22030 | \$ 806.00 | 6% | <i>\$763.32</i> |
| EW SOFTWARE SUPPORT S22031 | 97003-S22031 | \$ 1,614.00 | 6% | <i>\$1,528.54</i> |
| EW SOFTWARE SUPPORT S22032 | 97003-S22032 | \$ 806.00 | 6% | <i>\$763.32</i> |
| EW SOFTWARE SUPPORT S22035 | 97003-S22035 | \$ 782.00 | 6% | <i>\$740.59</i> |
| EW SOFTWARE SUPPORT S22036 | 97003-S22036 | \$ 732.00 | 6% | <i>\$693.24</i> |
| EW SOFTWARE SUPPORT S22037 | 97003-S22037 | \$ 1,130.00 | 6% | <i>\$1,070.17</i> |
| EW SOFTWARE SUPPORT S22038 | 97003-S22038 | \$ 1,130.00 | 6% | <i>\$1,070.17</i> |
| EW SOFTWARE SUPPORT S22039 | 97003-S22039 | \$ 1,130.00 | 6% | <i>\$1,070.17</i> |
| EW SOFTWARE SUPPORT S22040 | 97003-S22040 | \$ 1,148.00 | 6% | <i>\$1,087.21</i> |
| EW SOFTWARE SUPPORT S22041 | 97003-S22041 | \$ 1,075.00 | 6% | <i>\$1,018.08</i> |
| EW SOFTWARE SUPPORT S22042 | 97003-S22042 | \$ 1,749.00 | 6% | <i>\$1,656.39</i> |
| EW SOFTWARE SUPPORT S22044 | 97003-S22044 | \$ 460.00 | 6% | <i>\$435.64</i> |
| EW SOFTWARE SUPPORT S22045 | 97003-S22045 | \$ 410.00 | 6% | <i>\$388.29</i> |
| EW SOFTWARE SUPPORT S22046 | 97003-S22046 | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| EW SOFTWARE SUPPORT S22047 | 97003-S22047 | \$ 970.00 | 6% | <i>\$918.64</i> |
| EW SOFTWARE SUPPORT S22051 | 97003-S22051 | \$ 1,330.00 | 6% | <i>\$1,259.58</i> |
| EW SOFTWARE SUPPORT S22055 | 97003-S22055 | \$ 1,678.00 | 6% | <i>\$1,589.15</i> |
| EW SOFTWARE SUPPORT S22057 | 97003-S22057 | \$ 4,654.00 | 6% | <i>\$4,407.57</i> |
| EW SOFTWARE SUPPORT S22063 | 97003-S22063 | \$ 2,300.00 | 6% | <i>\$2,178.22</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EW SOFTWARE SUPPORT S22064 | 97003-S22064 | \$ 970.00 | 6% | <i>\$918.64</i> |
| EW SOFTWARE SUPPORT S22065 | 97003-S22065 | \$ 3,270.00 | 6% | <i>\$3,096.85</i> |
| EW SOFTWARE SUPPORT S22066 | 97003-S22066 | \$ 1,211.00 | 6% | <i>\$1,146.88</i> |
| EW SOFTWARE SUPPORT S22067 | 97003-S22067 | \$ 5,569.00 | 6% | <i>\$5,274.12</i> |
| EW SOFTWARE SUPPORT S22068 | 97003-S22068 | \$ 776.00 | 6% | <i>\$734.91</i> |
| EW SOFTWARE SUPPORT S22069 | 97003-S22069 | \$ 2,060.00 | 6% | <i>\$1,950.92</i> |
| EW SOFTWARE SUPPORT S22070 | 97003-S22070 | \$ 4,600.00 | 6% | <i>\$4,356.43</i> |
| EW SOFTWARE SUPPORT S22072 | 97003-S22072 | \$ 1,967.00 | 6% | <i>\$1,862.85</i> |
| EW SOFTWARE SUPPORT S22073 | 97003-S22073 | \$ 1,967.00 | 6% | <i>\$1,862.85</i> |
| EW SOFTWARE SUPPORT S22074 | 97003-S22074 | \$ 284.00 | 6% | <i>\$268.96</i> |
| EW SOFTWARE SUPPORT S22075 | 97003-S22075 | \$ 1,702.00 | 6% | <i>\$1,611.88</i> |
| EW SOFTWARE SUPPORT S22076 | 97003-S22076 | \$ 141.00 | 6% | <i>\$133.53</i> |
| EW SOFTWARE SUPPORT S22077 | 97003-S22077 | \$ 607.00 | 6% | <i>\$574.86</i> |
| EW SOFTWARE SUPPORT S22078 | 97003-S22078 | \$ 760.00 | 6% | <i>\$719.76</i> |
| EW SOFTWARE SUPPORT S22079 | 97003-S22079 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EW SOFTWARE SUPPORT S22080 | 97003-S22080 | \$ 35.00 | 6% | <i>\$33.15</i> |
| EW SOFTWARE SUPPORT S22081 | 97003-S22081 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EW SOFTWARE SUPPORT S22084 | 97003-S22084 | \$ 791.00 | 6% | <i>\$749.12</i> |
| EW SOFTWARE SUPPORT S22085 | 97003-S22085 | \$ 1,001.00 | 6% | <i>\$948.00</i> |
| EW SOFTWARE SUPPORT S22086 | 97003-S22086 | \$ 149.00 | 6% | <i>\$141.11</i> |
| EW SOFTWARE SUPPORT S22087 | 97003-S22087 | \$ 638.00 | 6% | <i>\$604.22</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S22088 | 97003-S22088 | \$ 926.00 | 6% | <i>\$876.97</i> |
| EW SOFTWARE SUPPORT S22089 | 97003-S22089 | \$ 154.00 | 6% | <i>\$145.85</i> |
| EW SOFTWARE SUPPORT S22090 | 97003-S22090 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EW SOFTWARE SUPPORT S22091 | 97003-S22091 | \$ 638.00 | 6% | <i>\$604.22</i> |
| EW SOFTWARE SUPPORT S22092 | 97003-S22092 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EW SOFTWARE SUPPORT S22093 | 97003-S22093 | \$ 638.00 | 6% | <i>\$604.22</i> |
| EW SOFTWARE SUPPORT S22094 | 97003-S22094 | \$ 631.00 | 6% | <i>\$597.59</i> |
| EW SOFTWARE SUPPORT S22095 | 97003-S22095 | \$ 631.00 | 6% | <i>\$597.59</i> |
| EW SOFTWARE SUPPORT S22117 | 97003-S22117 | \$ 1,313.00 | 6% | <i>\$1,243.48</i> |
| EW SOFTWARE SUPPORT S22119 | 97003-S22119 | \$ 3,279.00 | 6% | <i>\$3,105.38</i> |
| EW SOFTWARE SUPPORT S22123 | 97003-S22123 | \$ 171.00 | 6% | <i>\$161.95</i> |
| EW SOFTWARE SUPPORT S22124 | 97003-S22124 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EW SOFTWARE SUPPORT S22139 | 97003-S22139 | \$ 475.00 | 6% | <i>\$449.85</i> |
| EW SOFTWARE SUPPORT S22140 | 97003-S22140 | \$ 770.00 | 6% | <i>\$729.23</i> |
| EW SOFTWARE SUPPORT S22141 | 97003-S22141 | \$ 2,891.00 | 6% | <i>\$2,737.92</i> |
| EW SOFTWARE SUPPORT S22142 | 97003-S22142 | \$ 4,188.00 | 6% | <i>\$3,966.25</i> |
| EW SOFTWARE SUPPORT S22143 | 97003-S22143 | \$ 410.00 | 6% | <i>\$388.29</i> |
| EW SOFTWARE SUPPORT S22152 | 97003-S22152 | \$ 6,914.00 | 6% | <i>\$6,547.90</i> |
| EW SOFTWARE SUPPORT S22153 | 97003-S22153 | \$ 11,021.00 | 6% | <i>\$10,437.44</i> |
| EW SOFTWARE SUPPORT S22154 | 97003-S22154 | \$ 19,270.00 | 6% | <i>\$18,249.65</i> |
| EW SOFTWARE SUPPORT S22155 | 97003-S22155 | \$ 20,414.00 | 6% | <i>\$19,333.08</i> |

| | | | | |
|---|------------------------------------|--------------|----|--------------------|
| EW SOFTWARE SUPPORT S22156 | 97003-S22156 | \$ 6,914.00 | 6% | <i>\$6,547.90</i> |
| EW SOFTWARE SUPPORT S22157 | 97003-S22157 | \$ 11,021.00 | 6% | <i>\$10,437.44</i> |
| EW SOFTWARE SUPPORT S22158 | 97003-S22158 | \$ 6,582.00 | 6% | <i>\$6,233.48</i> |
| EW SOFTWARE SUPPORT S22159 | 97003-S22159 | \$ 10,496.00 | 6% | <i>\$9,940.24</i> |
| EW SOFTWARE SUPPORT S22160 | 97003-S22160 | \$ 8,515.00 | 6% | <i>\$8,064.13</i> |
| EW SOFTWARE SUPPORT S22161 | 97003-S22161 | \$ 13,576.00 | 6% | <i>\$12,857.15</i> |
| EW SOFTWARE SUPPORT S22162 | 97003-S22162 | \$ 23,739.00 | 6% | <i>\$22,482.02</i> |
| EW SOFTWARE SUPPORT S22163 | 97003-S22163 | \$ 2,307.00 | 6% | <i>\$2,184.84</i> |
| EW SOFTWARE SUPPORT S22164 | 97003-S22164 | \$ 4,613.00 | 6% | <i>\$4,368.74</i> |
| EW SOFTWARE SUPPORT S22165 | 97003-S22165 | \$ 8,647.00 | 6% | <i>\$8,189.14</i> |
| EW SOFTWARE SUPPORT S22166 | 97003-S22166 | \$ 6,348.00 | 6% | <i>\$6,011.87</i> |
| EW SOFTWARE SUPPORT S22167 | 97003-S22167 | \$ 8,647.00 | 6% | <i>\$8,189.14</i> |
| EW SOFTWARE SUPPORT S22173 | 97003-S22173 | \$ 729.00 | 6% | <i>\$690.40</i> |
| EW SOFTWARE SUPPORT S22174 | 97003-S22174 | \$ 1,457.00 | 6% | <i>\$1,379.85</i> |
| EW SOFTWARE SUPPORT S22175 | 97003-S22175 | \$ 2,915.00 | 6% | <i>\$2,760.65</i> |
| EW SOFTWARE SUPPORT SALSA-Ent-edition-P | 97003-SALSA- Ent-edition-P | \$ 6,176.00 | 6% | <i>\$5,848.98</i> |
| EW SOFTWARE SUPPORT SALSA-Ent-edition-XL | 97003-SALSA- Ent-edition-XL | \$ 8,618.00 | 6% | <i>\$8,161.68</i> |
| EW SOFTWARE SUPPORT SALSA-Ent-export-P | 97003-SALSA- Ent-export-P | \$ 2,873.00 | 6% | <i>\$2,720.87</i> |
| EW SOFTWARE SUPPORT SALSA-Ent-XL-upgrade | 97003-SALSA- Ent-XL- upgrade | \$ 2,442.00 | 6% | <i>\$2,312.70</i> |
| EW SOFTWARE SUPPORT SALSA-IVS-8K-upgrade | 97003-SALSA- IVS-8K- upgrade | \$ 431.00 | 6% | <i>\$408.18</i> |

| | | | | |
|--|---------------------------------|--------------|-----|--------------------|
| EW SOFTWARE SUPPORT SALSA-MSP-edition-P | 97003-SALSA- MSP-edition-P | \$ 34,474.00 | 6% | <i>\$32,648.60</i> |
| EW SOFTWARE SUPPORT SALSA-MSP-export-P | 97003-SALSA- MSP-export-P | \$ 11,491.00 | 6% | <i>\$10,882.55</i> |
| EW SOFTWARE SUPPORT VINFP | 97003-VINF-P | \$ 29.00 | 6% | <i>\$27.46</i> |
| EW SOFTWARE SUPPORT XCC-ACT-V5-VT | 97003-XCC- ACT-V5-VT | \$ 454.00 | 6% | <i>\$429.96</i> |
| EW SOFTWARE SUPPORT XCC-ACT-V5-VT-EGY | 97003-XCC- ACT-V5-VT- EGY | \$ 454.00 | 6% | <i>\$429.96</i> |
| EW SOFTWARE SUPPORT XESNPLUSWPKG | 97003-XESN- PLUS-SW- PKG | \$ 12,360.00 | 6% | <i>\$11,705.54</i> |
| EW SOFTWARE SUB XIQ- CACT-APP | 97003-XIQ- CACT-APP | \$ 330.00 | 6% | <i>\$312.53</i> |
| EW SOFTWARE SUPPORT XIQ-CACT-VT | 97003-XIQ- CACT-VT | \$ 432.00 | 6% | <i>\$409.13</i> |
| EW SOFTWARE SUPPORT XIQ-CACT-VT-EGY | 97003-XIQ- CACT-VT- EGY | \$ 432.00 | 6% | <i>\$409.13</i> |
| EW SOFTWARE SUPPORT XIQ-PIL-P-OP | 97003-XIQ- PIL-P-OP | \$ 63.00 | 6% | <i>\$59.66</i> |
| EW SOFTWARE SUPPORT XVM-LIC-1 | 97003-XVM- LIC-1 | \$ 556.00 | 6% | <i>\$526.56</i> |
| EW NBD AHR 100G-LR4- QSFP10KM | 97004-100G- LR4- QSFP10KM | \$ 2,190.00 | 10% | <i>\$1,985.78</i> |
| EW NBD AHR Optics 10200 | 97004-10200 | \$ 1,802.00 | 10% | <i>\$1,633.96</i> |
| EW NBD AHR Optics 10320 | 97004-10320 | \$ 1,977.00 | 10% | <i>\$1,792.64</i> |
| EW NBD AHR 10330 | 97004-10330 | \$ 4,848.00 | 10% | <i>\$4,395.92</i> |
| EW NBD AHR 10331 | 97004-10331 | \$ 2,237.00 | 10% | <i>\$2,028.40</i> |
| EW NBD AHR 10335 | 97004-10335 | \$ 3,414.00 | 10% | <i>\$3,095.64</i> |
| EW NBD AHR 10403 | 97004-10403 | \$ 4,235.00 | 10% | <i>\$3,840.09</i> |
| EW NBD AHR 10404 | 97004-10404 | \$ 2,083.00 | 10% | <i>\$1,888.76</i> |
| EW NBD AHR 10441 | 97004-10441 | \$ 1,395.00 | 10% | <i>\$1,264.92</i> |
| EW NBD AHR 10442 | 97004-10442 | \$ 1,484.00 | 10% | <i>\$1,345.62</i> |
| EW NBD AHR 1130C | 97004-1130C | \$ 960.00 | 6% | <i>\$909.17</i> |
| EW NBD AHR E4G 16119 | 97004-16119 | \$ 257.00 | 10% | <i>\$233.03</i> |
| EW NBD AHR E4G 16120 | 97004-16120 | \$ 316.00 | 10% | <i>\$286.53</i> |
| EW NBD AHR E4G 16126 | 97004-16126 | \$ 257.00 | 10% | <i>\$233.03</i> |
| EW NBD AHR E4G 16127 | 97004-16127 | \$ 270.00 | 10% | <i>\$244.82</i> |

| | | | | |
|-------------------------|--------------|-------------|-----|------------|
| EW NBD AHR 16172 | 97004-16172 | \$ 267.00 | 10% | \$242.10 |
| EW NBD AHR -16172T | 97004-16172T | \$ 317.00 | 10% | \$287.44 |
| EW NBD AHR 16173 | 97004-16173 | \$ 275.00 | 10% | \$249.36 |
| EW NBD AHR -16173T | 97004-16173T | \$ 326.00 | 10% | \$295.60 |
| EW NBD AHR 16174 | 97004-16174 | \$ 422.00 | 10% | \$382.65 |
| EW NBD AHR 16175 | 97004-16175 | \$ 450.00 | 10% | \$408.04 |
| EW NBD AHR 16176 | 97004-16176 | \$ 392.00 | 10% | \$355.45 |
| EW NBD AHR 16177 | 97004-16177 | \$ 385.00 | 10% | \$349.10 |
| EW NBD AHR -16177T | 97004-16177T | \$ 488.00 | 10% | \$442.49 |
| EW NBD AHR 16178 | 97004-16178 | \$ 569.00 | 10% | \$515.94 |
| EW NBD AHR 16179 | 97004-16179 | \$ 584.00 | 10% | \$529.54 |
| EW NBD AHR -16179T | 97004-16179T | \$ 702.00 | 10% | \$636.54 |
| EW NBD AHR 16301T | 97004-16301T | \$ 1,521.00 | 10% | \$1,379.17 |
| EW NBD AHR 16303T | 97004-16303T | \$ 1,521.00 | 10% | \$1,379.17 |
| EW NBD AHR 16304T | 97004-16304T | \$ 2,027.00 | 10% | \$1,837.98 |
| EW NBD AHR 16401T | 97004-16401T | \$ 721.00 | 10% | \$653.77 |
| EW NBD AHR 16402T | 97004-16402T | \$ 1,087.00 | 10% | \$985.64 |
| EW NBD AHR 16403T | 97004-16403T | \$ 963.00 | 10% | \$873.20 |
| EW NBD AHR 16404T | 97004-16404T | \$ 963.00 | 10% | \$873.20 |
| EW NBD AHR 16405T | 97004-16405T | \$ 1,269.00 | 10% | \$1,150.67 |
| EW NBD AHR 16406T | 97004-16406T | \$ 1,695.00 | 10% | \$1,536.94 |
| EW NBD AHR E4G 16431 | 97004-16431 | \$ 1,071.00 | 10% | \$971.13 |
| EW NBD AHR E4G 16432 | 97004-16432 | \$ 1,162.00 | 10% | \$1,053.64 |
| EW NBD AHR E4G 16440 | 97004-16440 | \$ 674.00 | 10% | \$611.15 |
| EW NBD AHR E4G 16441 | 97004-16441 | \$ 606.00 | 10% | \$549.49 |
| EW NBD AHR E4G 16442 | 97004-16442 | \$ 270.00 | 10% | \$244.82 |
| EW NBD AHR E4G 16444 | 97004-16444 | \$ 136.00 | 10% | \$123.32 |
| EW NBD AHR Summit 16501 | 97004-16501 | \$ 145.00 | 10% | \$131.48 |
| EW NBD AHR 16501T | 97004-16501T | \$ 184.00 | 10% | \$166.84 |
| EW NBD AHR Summit 16502 | 97004-16502 | \$ 213.00 | 10% | \$193.14 |
| EW NBD AHR 16502T | 97004-16502T | \$ 257.00 | 10% | \$233.03 |
| EW NBD AHR Summit 16503 | 97004-16503 | \$ 177.00 | 10% | \$160.49 |
| EW NBD AHR 16503T | 97004-16503T | \$ 229.00 | 10% | \$207.65 |
| EW NBD AHR Summit 16504 | 97004-16504 | \$ 288.00 | 10% | \$261.14 |
| EW NBD AHR 16504T | 97004-16504T | \$ 340.00 | 10% | \$308.30 |
| EW NBD AHR Summit 16505 | 97004-16505 | \$ 318.00 | 10% | \$288.35 |
| EW NBD AHR 16505T | 97004-16505T | \$ 388.00 | 10% | \$351.82 |
| EW NBD AHR Summit 16506 | 97004-16506 | \$ 491.00 | 10% | \$445.21 |
| EW NBD AHR 16506T | 97004-16506T | \$ 603.00 | 10% | \$546.77 |
| EW NBD AHR Summit 16507 | 97004-16507 | \$ 448.00 | 10% | \$406.22 |
| EW NBD AHR 16507T | 97004-16507T | \$ 529.00 | 10% | \$479.67 |
| EW NBD AHR Summit 16508 | 97004-16508 | \$ 558.00 | 10% | \$505.97 |

| | | | | |
|-------------------------|--------------|-----------|-----|----------|
| EW NBD AHR 16508T | 97004-16508T | \$ 668.00 | 10% | \$605.71 |
| EW NBD AHR Summit 16509 | 97004-16509 | \$ 558.00 | 10% | \$505.97 |
| EW NBD AHR 16509T | 97004-16509T | \$ 668.00 | 10% | \$605.71 |
| EW NBD AHR Summit 16510 | 97004-16510 | \$ 668.00 | 10% | \$605.71 |
| EW NBD AHR 16510T | 97004-16510T | \$ 800.00 | 10% | \$725.40 |
| EW NBD AHR-16513 | 97004-16513 | \$ 404.00 | 10% | \$366.33 |
| EW NBD AHR-48081-16514 | 97004-16514 | \$ 656.00 | 10% | \$594.83 |
| EW NBD AHR 16515 | 97004-16515 | \$ 113.00 | 10% | \$102.46 |
| EW NBD AHR-16516 | 97004-16516 | \$ 121.00 | 10% | \$109.72 |
| EW NBD AHR 16517 | 97004-16517 | \$ 241.00 | 10% | \$218.53 |
| EW NBD AHR-16518 | 97004-16518 | \$ 215.00 | 10% | \$194.95 |
| EW-NBD AHR 16519 | 97004-16519 | \$ 221.00 | 10% | \$200.39 |
| EW-NBD AHR 16520 | 97004-16520 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR 16530 | 97004-16530 | \$ 135.00 | 10% | \$122.41 |
| EW NBD AHR 16531 | 97004-16531 | \$ 183.00 | 10% | \$165.94 |
| EW NBD AHR 16531T | 97004-16531T | \$ 199.00 | 10% | \$180.44 |
| EW NBD AHR 16532 | 97004-16532 | \$ 183.00 | 10% | \$165.94 |
| EW NBD AHR 16532T | 97004-16532T | \$ 199.00 | 10% | \$180.44 |
| EW NBD AHR 16533 | 97004-16533 | \$ 260.00 | 10% | \$235.76 |
| EW NBD AHR 16533T | 97004-16533T | \$ 283.00 | 10% | \$256.61 |
| EW NBD AHR 16534 | 97004-16534 | \$ 275.00 | 10% | \$249.36 |
| EW NBD AHR 16535 | 97004-16535 | \$ 404.00 | 10% | \$366.33 |
| EW NBD AHR 16535A | 97004-16535A | \$ 404.00 | 10% | \$366.33 |
| EW NBD AHR 16535T | 97004-16535T | \$ 450.00 | 10% | \$408.04 |
| EW NBD AHR 16536 | 97004-16536 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR 16537 | 97004-16537 | \$ 257.00 | 10% | \$233.03 |
| EW NBD AHR 16538 | 97004-16538 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR 16538T | 97004-16538T | \$ 372.00 | 10% | \$337.31 |
| EW NBD AHR 16539 | 97004-16539 | \$ 400.00 | 10% | \$362.70 |
| EW NBD AHR 16540 | 97004-16540 | \$ 284.00 | 10% | \$257.52 |
| EW NBD AHR 16541 | 97004-16541 | \$ 106.00 | 10% | \$96.12 |
| EW NBD AHR 16560 | 97004-16560 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR 16561 | 97004-16561 | \$ 90.00 | 10% | \$81.61 |
| EW NBD AHR 16562 | 97004-16562 | \$ 109.00 | 10% | \$98.84 |
| EW NBD AHR 16563 | 97004-16563 | \$ 144.00 | 10% | \$130.57 |
| EW NBD AHR 16564 | 97004-16564 | \$ 178.00 | 10% | \$161.40 |
| EW NBD AHR 16565 | 97004-16565 | \$ 267.00 | 10% | \$242.10 |
| EW NBD AHR 16566 | 97004-16566 | \$ 41.00 | 10% | \$37.18 |
| EW NBD AHR 16567 | 97004-16567 | \$ 75.00 | 10% | \$68.01 |
| EW NBD AHR 16568 | 97004-16568 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR 16569 | 97004-16569 | \$ 96.00 | 10% | \$87.05 |
| EW NBD AHR 16570 | 97004-16570 | \$ 109.00 | 10% | \$98.84 |

| | | | | |
|--------------------|--------------|-------------|-----|-------------------|
| EW NBD AHR 16571 | 97004-16571 | \$ 178.00 | 10% | <i>\$161.40</i> |
| EW NBD AHR 16701 | 97004-16701 | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW NBD AHR 16702 | 97004-16702 | \$ 573.00 | 10% | <i>\$519.57</i> |
| EW NBD AHR 16703 | 97004-16703 | \$ 458.00 | 10% | <i>\$415.29</i> |
| EW NBD AHR -16703T | 97004-16703T | \$ 545.00 | 10% | <i>\$494.18</i> |
| EW NBD AHR 16704 | 97004-16704 | \$ 669.00 | 10% | <i>\$606.62</i> |
| EW NBD AHR -16704T | 97004-16704T | \$ 802.00 | 10% | <i>\$727.21</i> |
| EW NBD AHR 16705 | 97004-16705 | \$ 573.00 | 10% | <i>\$519.57</i> |
| EW NBD AHR -16705T | 97004-16705T | \$ 695.00 | 10% | <i>\$630.19</i> |
| EW NBD AHR 16706 | 97004-16706 | \$ 873.00 | 10% | <i>\$791.59</i> |
| EW NBD AHR -16706T | 97004-16706T | \$ 1,054.00 | 10% | <i>\$955.71</i> |
| EW NBD AHR 16710 | 97004-16710 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD AHR 16710T | 97004-16710T | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW NBD AHR 16711 | 97004-16711 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW NBD AHR 16711T | 97004-16711T | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW NBD AHR 16712 | 97004-16712 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW NBD AHR 16712T | 97004-16712T | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW NBD AHR 16713 | 97004-16713 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD AHR 16713T | 97004-16713T | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW NBD AHR 16715 | 97004-16715 | \$ 73.00 | 10% | <i>\$66.19</i> |
| EW NBD AHR 16715T | 97004-16715T | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW NBD AHR 16716 | 97004-16716 | \$ 305.00 | 10% | <i>\$276.56</i> |
| EW NBD AHR -16716T | 97004-16716T | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW NBD AHR 16717 | 97004-16717 | \$ 463.00 | 10% | <i>\$419.83</i> |
| EW NBD AHR 16718 | 97004-16718 | \$ 329.00 | 10% | <i>\$298.32</i> |
| EW NBD AHR -16718T | 97004-16718T | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW NBD AHR 16719 | 97004-16719 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW NBD AHR -16719T | 97004-16719T | \$ 589.00 | 10% | <i>\$534.08</i> |
| EW NBD AHR 16720 | 97004-16720 | \$ 740.00 | 10% | <i>\$671.00</i> |
| EW NBD AHR 16720T | 97004-16720T | \$ 860.00 | 10% | <i>\$779.81</i> |
| EW NBD AHR 16756 | 97004-16756 | \$ 540.00 | 10% | <i>\$489.65</i> |
| EW NBD AHR 16756T | 97004-16756T | \$ 642.00 | 10% | <i>\$582.13</i> |
| EW NBD AHR 16757 | 97004-16757 | \$ 509.00 | 10% | <i>\$461.54</i> |
| EW NBD AHR 16757T | 97004-16757T | \$ 603.00 | 10% | <i>\$546.77</i> |
| EW NBD AHR 16790 | 97004-16790 | \$ 1,189.00 | 10% | <i>\$1,078.13</i> |
| EW NBD AHR 16791 | 97004-16791 | \$ 1,532.00 | 10% | <i>\$1,389.14</i> |
| EW NBD AHR 16801 | 97004-16801 | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW NBD AHR 16802 | 97004-16802 | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW NBD AHR 16803 | 97004-16803 | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW NBD AHR 16804 | 97004-16804 | \$ 224.00 | 10% | <i>\$203.11</i> |
| EW NBD AHR 16805 | 97004-16805 | \$ 49.00 | 10% | <i>\$44.43</i> |
| EW NBD AHR 16806 | 97004-16806 | \$ 49.00 | 10% | <i>\$44.43</i> |

| | | | | |
|--------------------------|--------------|-------------|-----|------------|
| EW NBD AHR Summit 17101 | 97004-17101 | \$ 2,255.00 | 10% | \$2,044.72 |
| EW NBD AHR 17101T | 97004-17101T | \$ 2,877.00 | 10% | \$2,608.72 |
| EW NBD AHR Summit 17102 | 97004-17102 | \$ 2,255.00 | 10% | \$2,044.72 |
| EW NBD AHR 17102T | 97004-17102T | \$ 2,877.00 | 10% | \$2,608.72 |
| EW NBD AHR Summit 17103 | 97004-17103 | \$ 1,572.00 | 10% | \$1,425.41 |
| EW NBD AHR Summit 17103C | 97004-17103C | \$ 1,525.00 | 10% | \$1,382.79 |
| EW NBD AHR 17103T | 97004-17103T | \$ 2,011.00 | 10% | \$1,823.47 |
| EW NBD AHR Summit 17104 | 97004-17104 | \$ 1,572.00 | 10% | \$1,425.41 |
| EW NBD AHR 17104T | 97004-17104T | \$ 2,011.00 | 10% | \$1,823.47 |
| EW NBD AHR Summit 17121 | 97004-17121 | \$ 449.00 | 10% | \$407.13 |
| EW NBD AHR Summit 17122 | 97004-17122 | \$ 278.00 | 10% | \$252.08 |
| EW NBD AHR -17200 | 97004-17200 | \$ 3,546.00 | 10% | \$3,215.34 |
| EW NBD AHR 17200T | 97004-17200T | \$ 4,060.00 | 10% | \$3,681.41 |
| EW NBD AHR Summit 17201 | 97004-17201 | \$ 3,546.00 | 10% | \$3,215.34 |
| EW NBD AHR 17201T | 97004-17201T | \$ 4,060.00 | 10% | \$3,681.41 |
| EW NBD AHR Summit 17202 | 97004-17202 | \$ 3,546.00 | 10% | \$3,215.34 |
| EW NBD AHR 17202T | 97004-17202T | \$ 4,060.00 | 10% | \$3,681.41 |
| EW NBD AHR Summit 17203 | 97004-17203 | \$ 3,605.00 | 10% | \$3,268.83 |
| EW NBD AHR 17203T | 97004-17203T | \$ 4,118.00 | 10% | \$3,734.00 |
| EW NBD AHR Summit 17204 | 97004-17204 | \$ 3,605.00 | 10% | \$3,268.83 |
| EW NBD AHR 17204T | 97004-17204T | \$ 4,118.00 | 10% | \$3,734.00 |
| EW NBD AHR Summit 17205 | 97004-17205 | \$ 3,578.00 | 10% | \$3,244.35 |
| EW NBD AHR 17205T | 97004-17205T | \$ 4,087.00 | 10% | \$3,705.89 |
| EW NBD AHR Summit 17206 | 97004-17206 | \$ 3,578.00 | 10% | \$3,244.35 |
| EW NBD AHR 17206T | 97004-17206T | \$ 4,087.00 | 10% | \$3,705.89 |
| EW NBD AHR 17300 | 97004-17300 | \$ 2,347.00 | 10% | \$2,128.14 |
| EW NBD AHR 17310 | 97004-17310 | \$ 2,130.00 | 10% | \$1,931.38 |
| EW NBD AHR -17310T | 97004-17310T | \$ 2,560.00 | 10% | \$2,321.28 |
| EW NBD AHR 17350 | 97004-17350 | \$ 2,148.00 | 10% | \$1,947.70 |
| EW NBD AHR 17360 | 97004-17360 | \$ 2,643.00 | 10% | \$2,396.54 |
| EW NBD AHR 17401 | 97004-17401 | \$ 326.00 | 10% | \$295.60 |
| EW NBD AHR 17401G | 97004-17401G | \$ 388.00 | 10% | \$351.82 |
| EW NBD AHR 17401T | 97004-17401T | \$ 368.00 | 10% | \$333.68 |
| EW NBD AHR 17402 | 97004-17402 | \$ 467.00 | 10% | \$423.45 |
| EW NBD AHR 17402G | 97004-17402G | \$ 519.00 | 10% | \$470.60 |
| EW NBD AHR 17402T | 97004-17402T | \$ 496.00 | 10% | \$449.75 |
| EW NBD AHR 17403 | 97004-17403 | \$ 506.00 | 10% | \$458.82 |
| EW NBD AHR 17404 | 97004-17404 | \$ 245.00 | 10% | \$222.15 |
| EW NBD AHR 17405 | 97004-17405 | \$ 303.00 | 10% | \$274.75 |
| EW NBD AHR 17700 | 97004-17700 | \$ 4,159.00 | 10% | \$3,771.17 |
| EW NBD AHR 17701 | 97004-17701 | \$ 3,657.00 | 10% | \$3,315.98 |
| EW NBD AHR 17702 | 97004-17702 | \$ 3,657.00 | 10% | \$3,315.98 |

| | | | | |
|----------------------|-----------------|-------------|-----|------------|
| EW NBD AHR 17703 | 97004-17703 | \$ 4,002.00 | 10% | \$3,628.81 |
| EW NBD AHR 17704 | 97004-17704 | \$ 4,002.00 | 10% | \$3,628.81 |
| EW NBD AHR 17705 | 97004-17705 | \$ 3,688.00 | 10% | \$3,344.09 |
| EW NBD AHR 17706 | 97004-17706 | \$ 3,688.00 | 10% | \$3,344.09 |
| EW NBD AHR 17800 | 97004-17800 | \$ 4,163.00 | 10% | \$3,774.80 |
| EW NBD AHR 17810 | 97004-17810 | \$ 3,329.00 | 10% | \$3,018.57 |
| EW NBD AHR 18101 | 97004-18101 | \$ 212.00 | 10% | \$192.23 |
| EW NBD AHR 18102 | 97004-18102 | \$ 271.00 | 10% | \$245.73 |
| EW NBD AHR 18103 | 97004-18103 | \$ 297.00 | 10% | \$269.30 |
| EW NBD AHR 18104 | 97004-18104 | \$ 423.00 | 10% | \$383.56 |
| EW NBD AHR 18104-6PK | 97004-18104-6PK | \$ 2,465.00 | 10% | \$2,235.14 |
| EW NBD AHR 18202 | 97004-18202 | \$ 158.00 | 10% | \$143.27 |
| EW NBD AHR 30135 | 97004-30135 | \$ 433.00 | 10% | \$392.62 |
| EW NBD AHR 30136 | 97004-30136 | \$ 3,268.00 | 10% | \$2,963.26 |
| EW NBD AHR 30137 | 97004-30137 | \$ 818.00 | 10% | \$741.72 |
| EW NBD AHR 30138 | 97004-30138 | \$ 3,775.00 | 10% | \$3,422.98 |
| EW NBD AHR 30139 | 97004-30139 | \$ 6,901.00 | 10% | \$6,257.48 |
| EW NBD AHR 30912 | 97004-30912 | \$ 44.00 | 10% | \$39.90 |
| EW NBD AHR 30913 | 97004-30913 | \$ 44.00 | 10% | \$39.90 |
| EW NBD AHR 31012 | 97004-31012 | \$ 74.00 | 10% | \$67.10 |
| EW NBD AHR 31013 | 97004-31013 | \$ 74.00 | 10% | \$67.10 |
| EW NBD AHR 31014 | 97004-31014 | \$ 74.00 | 10% | \$67.10 |
| EW NBD AHR 31015 | 97004-31015 | \$ 74.00 | 10% | \$67.10 |
| EW NBD AHR 31016 | 97004-31016 | \$ 239.00 | 10% | \$216.71 |
| EW NBD AHR 31017 | 97004-31017 | \$ 239.00 | 10% | \$216.71 |
| EW NBD AHR 31018 | 97004-31018 | \$ 272.00 | 10% | \$246.64 |
| EW NBD AHR 31019 | 97004-31019 | \$ 272.00 | 10% | \$246.64 |
| EW NBD AHR 31025 | 97004-31025 | \$ 46.00 | 10% | \$41.71 |
| EW NBD AHR 31026 | 97004-31026 | \$ 46.00 | 10% | \$41.71 |
| EW NBD AHR 31028 | 97004-31028 | \$ 47.00 | 10% | \$42.62 |
| EW NBD AHR 31029 | 97004-31029 | \$ 58.00 | 10% | \$52.59 |
| EW NBD AHR 31031 | 97004-31031 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR 31032 | 97004-31032 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR 31034 | 97004-31034 | \$ 70.00 | 10% | \$63.47 |
| EW NBD AHR 31035 | 97004-31035 | \$ 70.00 | 10% | \$63.47 |
| EW NBD AHR 31050 | 97004-31050 | \$ 96.00 | 10% | \$87.05 |
| EW NBD AHR 31051 | 97004-31051 | \$ 96.00 | 10% | \$87.05 |
| EW NBD AHR 31055 | 97004-31055 | \$ 96.00 | 10% | \$87.05 |
| EW NBD AHR 31056 | 97004-31056 | \$ 96.00 | 10% | \$87.05 |
| EW NBD AHR 37101 | 97004-37101 | \$ 44.00 | 10% | \$39.90 |
| EW NBD AHR 37102 | 97004-37102 | \$ 44.00 | 10% | \$39.90 |

| | | | | |
|-------------------------|--------------------|-------------|-----|-------------------|
| EW NBD AHR 37103 | 97004-37103 | \$ 44.00 | 10% | <i>\$39.90</i> |
| EW NBD AHR 37111 | 97004-37111 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW NBD AHR 37112 | 97004-37112 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW NBD AHR 37113 | 97004-37113 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR 37114 | 97004-37114 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR 37115 | 97004-37115 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW NBD AHR 37116 | 97004-37116 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR 37117 | 97004-37117 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW NBD AHR 37121 | 97004-37121 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 37122 | 97004-37122 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 37123 | 97004-37123 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 37124 | 97004-37124 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 37125 | 97004-37125 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 37126 | 97004-37126 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 37129 | 97004-37129 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 37130 | 97004-37130 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW NBD AHR 39031 | 97004-39031 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD AHR 39032 | 97004-39032 | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW NBD AHR 39033 | 97004-39033 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD AHR 39034 | 97004-39034 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD AHR 39035 | 97004-39035 | \$ 495.00 | 10% | <i>\$448.84</i> |
| EW NBD AHR 39036 | 97004-39036 | \$ 93.00 | 10% | <i>\$84.33</i> |
| EW NBD AHR 39037 | 97004-39037 | \$ 93.00 | 10% | <i>\$84.33</i> |
| EW NBD AHR 39038 | 97004-39038 | \$ 132.00 | 10% | <i>\$119.69</i> |
| EW NBD AHR 39039 | 97004-39039 | \$ 132.00 | 10% | <i>\$119.69</i> |
| EW NBD AHR 39505 | 97004-39505 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW NBD AHR 4120-24MW-4Y | 97004-4120-24MW-4Y | \$ 531.00 | 10% | <i>\$481.48</i> |
| EW NBD AHR 4120-48MW-4Y | 97004-4120-48MW-4Y | \$ 708.00 | 10% | <i>\$641.98</i> |
| EW NBD AHR 4120C | 97004-4120C | \$ 4,628.00 | 10% | <i>\$4,196.44</i> |
| EW NBD AHR 4120C-1 | 97004-4120C-1 | \$ 5,225.00 | 10% | <i>\$4,737.77</i> |
| EW NBD AHR 41216 | 97004-41216 | \$ 1,430.00 | 10% | <i>\$1,296.65</i> |
| EW NBD AHR 4220-12P-4X | 97004-4220-12P-4X | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW NBD AHR 4220-12T-4X | 97004-4220-12T-4X | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW NBD AHR 4220-24P-4X | 97004-4220-24P-4X | \$ 216.00 | 10% | <i>\$195.86</i> |
| EW NBD AHR 4220-24T-4X | 97004-4220-24T-4X | \$ 167.00 | 10% | <i>\$151.43</i> |

| | | | | |
|--------------------------------|---------------------------|--------------|-----|------------|
| EW NBD AHR 4220-48P-4X | 97004-4220-48P-4X | \$ 324.00 | 10% | \$293.79 |
| EW NBD AHR 4220-48T-4X | 97004-4220-48T-4X | \$ 243.00 | 10% | \$220.34 |
| EW NBD AHR 4220-4MW-20P-4X | 97004-4220-4MW-20P-4X | \$ 297.00 | 10% | \$269.30 |
| EW NBD AHR 4220-4MW-8P-4X | 97004-4220-4MW-8P-4X | \$ 210.00 | 10% | \$190.42 |
| EW NBD AHR 4220-8MW-40P-4X | 97004-4220-8MW-40P-4X | \$ 432.00 | 10% | \$391.72 |
| EW NBD AHR 4220-8X | 97004-4220-8X | \$ 227.00 | 10% | \$205.83 |
| EW NBD AHR BD X 48001 | 97004-48001 | \$ 5,936.00 | 10% | \$5,382.47 |
| EW NBD AHR 48038 | 97004-48038 | \$ 2,378.00 | 10% | \$2,156.25 |
| EW NBD AHR 48039 | 97004-48039 | \$ 2,378.00 | 10% | \$2,156.25 |
| EW NBD AHR-48040 | 97004-48040 | \$ 2,158.00 | 10% | \$1,956.77 |
| EW NBD AHR BD X 48041 | 97004-48041 | \$ 2,378.00 | 10% | \$2,156.25 |
| EW NBD AHR BD X 48046 | 97004-48046 | \$ 3,121.00 | 10% | \$2,829.97 |
| EW NBD AHR 48047 | 97004-48047 | \$ 8,320.00 | 10% | \$7,544.16 |
| EW NBD AHR BD X 48051 | 97004-48051 | \$ 5,723.00 | 10% | \$5,189.33 |
| EW NBD AHR 48061 | 97004-48061 | \$ 6,685.00 | 10% | \$6,061.62 |
| EW NBD AHR 48062 | 97004-48062 | \$ 10,696.00 | 10% | \$9,698.60 |
| EW NBD AHR 5320-16P-4XE | 97004-5320-16P-4XE | \$ 228.00 | 10% | \$206.74 |
| EW NBD AHR 5320-16P-4XE-DC | 97004-5320-16P-4XE-DC | \$ 273.00 | 10% | \$247.54 |
| EW NBD AHR 5320-24P-8XE | 97004-5320-24P-8XE | \$ 251.00 | 10% | \$227.59 |
| EW NBD AHR 5320-24T-24S-4XE-XT | 97004-5320-24T-24S-4XE-XT | \$ 344.00 | 10% | \$311.92 |
| EW NBD AHR 5320-24T-4X-XT | 97004-5320-24T-4X-XT | \$ 185.00 | 10% | \$167.75 |
| EW NBD AHR 5320-24T-8XE | 97004-5320-24T-8XE | \$ 178.00 | 10% | \$161.40 |
| EW NBD AHR 5320-48P-8XE | 97004-5320-48P-8XE | \$ 420.00 | 10% | \$380.84 |
| EW NBD AHR 5320-48T-8XE | 97004-5320-48T-8XE | \$ 283.00 | 10% | \$256.61 |
| EW NBD AHR 5420F-16MW-32P-4XE | 97004-5420F-16MW-32P-4XE | \$ 813.00 | 10% | \$737.19 |

| | | | | |
|-------------------------------|--------------------------|-----------|-----|-----------------|
| EW NBD AHR 5420F-16W-32P-4XE | 97004-5420F-16W-32P-4XE | \$ 688.00 | 10% | <i>\$623.84</i> |
| EW NBD AHR 5420F-24P-4XE | 97004-5420F-24P-4XE | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW NBD AHR 5420F-24S-4XE | 97004-5420F-24S-4XE | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW NBD AHR 5420F-24T-4XE | 97004-5420F-24T-4XE | \$ 282.00 | 10% | <i>\$255.70</i> |
| EW NBD AHR 5420F-48P-4XE | 97004-5420F-48P-4XE | \$ 534.00 | 10% | <i>\$484.20</i> |
| EW NBD AHR 5420F-48P-4XL | 97004-5420F-48P-4XL | \$ 623.00 | 10% | <i>\$564.91</i> |
| EW NBD AHR 5420F-48T-4XE | 97004-5420F-48T-4XE | \$ 382.00 | 10% | <i>\$346.38</i> |
| EW NBD AHR 5420F-8W-16P-4XE | 97004-5420F-8W-16P-4XE | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW NBD AHR 5420M-16MW-32P-4YE | 97004-5420M-16MW-32P-4YE | \$ 881.00 | 10% | <i>\$798.85</i> |
| EW NBD AHR 5420M-24T-4YE | 97004-5420M-24T-4YE | \$ 375.00 | 10% | <i>\$340.03</i> |
| EW NBD AHR 5420M-24W-4YE | 97004-5420M-24W-4YE | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW NBD AHR 5420M-48T-4YE | 97004-5420M-48T-4YE | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW NBD AHR 5420M-48W-4YE | 97004-5420M-48W-4YE | \$ 577.00 | 10% | <i>\$523.19</i> |
| EW NBD AHR 5520-12MW-36W | 97004-5520-12MW-36W | \$ 802.00 | 10% | <i>\$727.21</i> |
| EW NBD AHR 5520-24T | 97004-5520-24T | \$ 332.00 | 10% | <i>\$301.04</i> |
| EW NBD AHR 5520-24T-ACDC-BASE | 97004-5520-24T-ACDC-BASE | \$ 332.00 | 10% | <i>\$301.04</i> |
| EW NBD AHR 5520-24T-BASE | 97004-5520-24T-BASE | \$ 332.00 | 10% | <i>\$301.04</i> |
| EW NBD AHR 5520-24W | 97004-5520-24W | \$ 505.00 | 10% | <i>\$457.91</i> |
| EW NBD AHR 5520-24X | 97004-5520-24X | \$ 955.00 | 10% | <i>\$865.95</i> |

| | | | | |
|--------------------------------|---------------------------|-------------|-----|------------|
| EW NBD AHR 5520-24X-ACDC-BASE | 97004-5520-24X-ACDC-BASE | \$ 955.00 | 10% | \$865.95 |
| EW NBD AHR 5520-24X-BASE | 97004-5520-24X-BASE | \$ 955.00 | 10% | \$865.95 |
| EW NBD AHR 5520-48SE | 97004-5520-48SE | \$ 983.00 | 10% | \$891.34 |
| EW NBD AHR 5520-48SE-ACDC-BASE | 97004-5520-48SE-ACDC-BASE | \$ 983.00 | 10% | \$891.34 |
| EW NBD AHR 5520-48SE-BASE | 97004-5520-48SE-BASE | \$ 983.00 | 10% | \$891.34 |
| EW NBD AHR 5520-48T | 97004-5520-48T | \$ 546.00 | 10% | \$495.09 |
| EW NBD AHR 5520-48T-ACDC-BASE | 97004-5520-48T-ACDC-BASE | \$ 546.00 | 10% | \$495.09 |
| EW NBD AHR 5520-48T-BASE | 97004-5520-48T-BASE | \$ 546.00 | 10% | \$495.09 |
| EW NBD AHR 5520-48W | 97004-5520-48W | \$ 655.00 | 10% | \$593.92 |
| EW NBD AHR 5720-24MW | 97004-5720-24MW | \$ 1,003.00 | 10% | \$909.47 |
| EW NBD AHR 5720-24MXW | 97004-5720-24MXW | \$ 1,357.00 | 10% | \$1,230.46 |
| EW NBD AHR 5720-48MW | 97004-5720-48MW | \$ 1,186.00 | 10% | \$1,075.41 |
| EW NBD AHR 5720-48MXW | 97004-5720-48MXW | \$ 1,711.00 | 10% | \$1,551.45 |
| EW NBD AHR 7520-48XT-6C | 97004-7520-48XT-6C | \$ 1,837.00 | 10% | \$1,665.70 |
| EW NBD AHR 7520-48XT-6C-AC-F | 97004-7520-48XT-6C-AC-F | \$ 1,837.00 | 10% | \$1,665.70 |
| EW NBD AHR 7520-48XT-6C-AC-R | 97004-7520-48XT-6C-AC-R | \$ 1,837.00 | 10% | \$1,665.70 |
| EW NBD AHR 7520-48Y-8C | 97004-7520-48Y-8C | \$ 1,705.00 | 10% | \$1,546.01 |
| EW NBD AHR 7520-48Y-8C-AC-F | 97004-7520-48Y-8C-AC-F | \$ 1,705.00 | 10% | \$1,546.01 |
| EW NBD AHR 7520-48Y-8C-AC-R | 97004-7520-48Y-8C-AC-R | \$ 1,705.00 | 10% | \$1,546.01 |

| | | | | |
|-------------------------------|--------------------------|-------------|-----|-------------------|
| EW NBD AHR 7520-48YE-8CE | 97004-7520-48YE-8CE | \$ 1,993.00 | 10% | <i>\$1,807.15</i> |
| EW NBD AHR 7520-48YE-8CE-AC-F | 97004-7520-48YE-8CE-AC-F | \$ 1,993.00 | 10% | <i>\$1,807.15</i> |
| EW NBD AHR 7520-48YE-8CE-AC-R | 97004-7520-48YE-8CE-AC-R | \$ 1,993.00 | 10% | <i>\$1,807.15</i> |
| EW NBD AHR 7720-32C | 97004-7720-32C | \$ 2,146.00 | 10% | <i>\$1,945.89</i> |
| EW NBD AHR 7720-32C-AC-F | 97004-7720-32C-AC-F | \$ 2,146.00 | 10% | <i>\$1,945.89</i> |
| EW NBD AHR 7720-32C-AC-R | 97004-7720-32C-AC-R | \$ 2,146.00 | 10% | <i>\$1,945.89</i> |
| EW NBD AHR 8520-48XT-6C | 97004-8520-48XT-6C | \$ 2,124.00 | 10% | <i>\$1,925.94</i> |
| EW NBD AHR 8520-48XT-6C-AC-F | 97004-8520-48XT-6C-AC-F | \$ 2,124.00 | 10% | <i>\$1,925.94</i> |
| EW NBD AHR 8520-48XT-6C-AC-R | 97004-8520-48XT-6C-AC-R | \$ 2,124.00 | 10% | <i>\$1,925.94</i> |
| EW NBD AHR 8520-48XT-6C-DC-F | 97004-8520-48XT-6C-DC-F | \$ 2,124.00 | 10% | <i>\$1,925.94</i> |
| EW NBD AHR 8520-48XT-6C-DC-R | 97004-8520-48XT-6C-DC-R | \$ 2,124.00 | 10% | <i>\$1,925.94</i> |
| EW NBD AHR 8520-48Y-8C | 97004-8520-48Y-8C | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW NBD AHR 8520-48Y-8C-AC-F | 97004-8520-48Y-8C-AC-F | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW NBD AHR 8520-48Y-8C-AC-R | 97004-8520-48Y-8C-AC-R | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW NBD AHR 8520-48Y-8C-DC-F | 97004-8520-48Y-8C-DC-F | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW NBD AHR 8520-48Y-8C-DC-R | 97004-8520-48Y-8C-DC-R | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW NBD AHR 86100 | 97004-86100 | \$ 4,770.00 | 10% | <i>\$4,325.20</i> |
| EW NBD AHR 86101 | 97004-86101 | \$ 6,557.00 | 10% | <i>\$5,945.56</i> |
| EW NBD AHR 87100 | 97004-87100 | \$ 2,960.00 | 10% | <i>\$2,683.98</i> |
| EW NBD AHR 87101 | 97004-87101 | \$ 4,556.00 | 10% | <i>\$4,131.15</i> |

| | | | | |
|--------------------------|---------------------|--------------|-----|-------------|
| EW NBD AHR 8720-32C | 97004-8720-32C | \$ 2,487.00 | 10% | \$2,255.09 |
| EW NBD AHR 8720-32C-AC-F | 97004-8720-32C-AC-F | \$ 2,487.00 | 10% | \$2,255.09 |
| EW NBD AHR 8720-32C-AC-R | 97004-8720-32C-AC-R | \$ 2,487.00 | 10% | \$2,255.09 |
| EW NBD AHR 8720-32C-DC-F | 97004-8720-32C-DC-F | \$ 2,487.00 | 10% | \$2,255.09 |
| EW NBD AHR 8720-32C-DC-R | 97004-8720-32C-DC-R | \$ 2,487.00 | 10% | \$2,255.09 |
| EW NBD AHR BD 8806 | 97004-8806 | \$ 1,484.00 | 10% | \$1,345.62 |
| EW NBD AHR BD 8810 | 97004-8810 | \$ 3,862.00 | 10% | \$3,501.87 |
| EW NBD AHR 88100 | 97004-88100 | \$ 5,389.00 | 10% | \$4,886.48 |
| EW NBD AHR 8820-40C | 97004-8820-40C | \$ 9,563.00 | 10% | \$8,671.25 |
| EW NBD AHR 8820-40C-AC-F | 97004-8820-40C-AC-F | \$ 9,563.00 | 10% | \$8,671.25 |
| EW NBD AHR 8820-40C-AC-R | 97004-8820-40C-AC-R | \$ 9,563.00 | 10% | \$8,671.25 |
| EW NBD AHR 8820-40C-DC-F | 97004-8820-40C-DC-F | \$ 9,563.00 | 10% | \$8,671.25 |
| EW NBD AHR 8820-40C-DC-R | 97004-8820-40C-DC-R | \$ 9,563.00 | 10% | \$8,671.25 |
| EW NBD AHR 8820-80C | 97004-8820-80C | \$ 17,237.00 | 10% | \$15,629.65 |
| EW NBD AHR 8820-80C-AC-F | 97004-8820-80C-AC-F | \$ 17,237.00 | 10% | \$15,629.65 |
| EW NBD AHR 8820-80C-AC-R | 97004-8820-80C-AC-R | \$ 17,237.00 | 10% | \$15,629.65 |
| EW NBD AHR 8820-80C-DC-F | 97004-8820-80C-DC-F | \$ 17,237.00 | 10% | \$15,629.65 |
| EW NBD AHR 8820-80C-DC-R | 97004-8820-80C-DC-R | \$ 17,237.00 | 10% | \$15,629.65 |
| EW NBD AHR 9920-16C | 97004-9920-16C | \$ 7,541.00 | 10% | \$6,837.80 |
| EW NBD AHR 9920-4D | 97004-9920-4D | \$ 7,541.00 | 10% | \$6,837.80 |
| EW NBD AHR 9920-NPB-8 | 97004-9920-NPB-8 | \$ 13,716.00 | 10% | \$12,436.98 |
| EW NBD AHR | 97004-A10148 | \$ 2,681.00 | 10% | \$2,431.00 |
| EW NBD AHR | 97004-A10149 | \$ 5,112.00 | 10% | \$4,635.31 |
| EW NBD AHR | 97004-A10152 | \$ 5,112.00 | 10% | \$4,635.31 |

| | | | | |
|------------------------------|-------------------------|--------------|-----|--------------------|
| EW NBD AHR | 97004-A10154 | \$ 15,587.00 | 10% | <i>\$14,133.51</i> |
| EW NBD AHR | 97004-A10155 | \$ 5,511.00 | 10% | <i>\$4,997.10</i> |
| EW NBD AHR | 97004-A10157 | \$ 9,739.00 | 10% | <i>\$8,830.84</i> |
| EW NBD AHR 10175 | 97004-A10175 | \$ 5,459.00 | 10% | <i>\$4,949.95</i> |
| EW NBD AHR A10176 | 97004-A10176 | \$ 8,192.00 | 10% | <i>\$7,428.10</i> |
| EW NBD AHR AH-AP-1130-AC-CE | 97004-AH-AP-1130-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-1130-AC-FCC | 97004-AH-AP-1130-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-1130-AC-W | 97004-AH-AP-1130-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-121-N-CE | 97004-AH-AP-121-N-CE | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-121-N-FCC | 97004-AH-AP-121-N-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-121-N-W | 97004-AH-AP-121-N-W | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-121-N-W-NEC | 97004-AH-AP-121-N-W-NEC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-122-AC-CAN | 97004-AH-AP-122-AC-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-122-AC-CE | 97004-AH-AP-122-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-122-AC-FCC | 97004-AH-AP-122-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-122-AC-W | 97004-AH-AP-122-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-122X-AC-CAN | 97004-AH-AP-122X-AC-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-122X-AC-CE | 97004-AH-AP-122X-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-122X-AC-FCC | 97004-AH-AP-122X-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-122X-AC-W | 97004-AH-AP-122X-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-130-AC-CE | 97004-AH-AP-130-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-130-AC-FCC | 97004-AH-AP-130-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-130-AC-W | 97004-AH-AP-130-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |

| | | | | |
|------------------------------|-------------------------|----------|-----|----------------|
| EW NBD AHR AH-AP-141-N-CE | 97004-AH-AP-141-N-CE | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-141-N-FCC | 97004-AH-AP-141-N-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-141-N-W | 97004-AH-AP-141-N-W | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-150W-AC-CAN | 97004-AH-AP-150W-AC-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-150W-AC-CE | 97004-AH-AP-150W-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-150W-AC-FCC | 97004-AH-AP-150W-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-150W-AC-W | 97004-AH-AP-150W-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-230-AC-CE | 97004-AH-AP-230-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-230-AC-FCC | 97004-AH-AP-230-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-230-AC-W | 97004-AH-AP-230-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-245X-AC-CAN | 97004-AH-AP-245X-AC-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-245X-AC-CE | 97004-AH-AP-245X-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-245X-AC-FCC | 97004-AH-AP-245X-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-245X-AC-W | 97004-AH-AP-245X-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-250-AC-CAN | 97004-AH-AP-250-AC-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-250-AC-CE | 97004-AH-AP-250-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-250-AC-FCC | 97004-AH-AP-250-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-250-AC-W | 97004-AH-AP-250-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-330-N-FCC | 97004-AH-AP-330-N-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |

| | | | | |
|------------------------------|-------------------------|----------|-----|----------------|
| EW NBD AHR AH-AP-330-N-W | 97004-AH-AP-330-N-W | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-350-N-FCC | 97004-AH-AP-350-N-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-350-N-W | 97004-AH-AP-350-N-W | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-370-AC-FCC | 97004-AH-AP-370-AC-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-390-AC-FCC | 97004-AH-AP-390-AC-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-AP-550-AC-CAN | 97004-AH-AP-550-AC-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-550-AC-CE | 97004-AH-AP-550-AC-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-550-AC-FCC | 97004-AH-AP-550-AC-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-550-AC-W | 97004-AH-AP-550-AC-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-630-AX-CAN | 97004-AH-AP-630-AX-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-630-AX-CE | 97004-AH-AP-630-AX-CE | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-630-AX-FCC | 97004-AH-AP-630-AX-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-630-AX-W | 97004-AH-AP-630-AX-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-AP-650-AX-CAN | 97004-AH-AP-650-AX-CAN | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR AH-AP-650-AX-CE | 97004-AH-AP-650-AX-CE | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR AH-AP-650-AX-FCC | 97004-AH-AP-650-AX-FCC | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR AH-AP-650-AX-W | 97004-AH-AP-650-AX-W | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR AH-AP-650X-AX-CAN | 97004-AH-AP-650X-AX-CAN | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR AH-AP-650X-AX-CE | 97004-AH-AP-650X-AX-CE | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR AH-AP-650X-AX-FCC | 97004-AH-AP-650X-AX-FCC | \$ 50.00 | 10% | <i>\$45.34</i> |

| | | | | |
|------------------------------|-------------------------|----------|-----|----------------|
| EW NBD AHR AH-AP-650X-AX-W | 97004-AH-AP-650X-AX-W | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR AH-ATOM-1PK-FCC | 97004-AH-ATOM-1PK-FCC | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-ATOM-CAN | 97004-AH-ATOM-CAN | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-ATOM-CE-EU | 97004-AH-ATOM-CE-EU | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-ATOM-CE-UK | 97004-AH-ATOM-CE-UK | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-ATOM-FCC | 97004-AH-ATOM-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-ATOM-W | 97004-AH-ATOM-W | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-ATOM-W-EU | 97004-AH-ATOM-W-EU | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-ATOM-W-UK | 97004-AH-ATOM-W-UK | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-BR-100-N-FCC | 97004-AH-BR-100-N-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-BR-100-N-W | 97004-AH-BR-100-N-W | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-BR-100-N-W-AU | 97004-AH-BR-100-N-W-AU | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-BR-100-N-W-EU | 97004-AH-BR-100-N-W-EU | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-BR-100-N-W-UK | 97004-AH-BR-100-N-W-UK | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-BR-100-N-W-US | 97004-AH-BR-100-N-W-US | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AH-BR-200 | 97004-AH-BR-200 | \$ 61.00 | 10% | <i>\$55.31</i> |
| EW NBD AHR AH-BR-200WP-N-CE | 97004-AH-BR-200WP-N-CE | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-BR-200WP-N-EU | 97004-AH-BR-200WP-N-EU | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-BR-200WP-N-FCC | 97004-AH-BR-200WP-N-FCC | \$ 61.00 | 10% | <i>\$55.31</i> |

| | | | | |
|----------------------------|-----------------------|----------|-----|----------------|
| EW NBD AHR AH-BR-200WP-N-W | 97004-AH-BR-200WP-N-W | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW NBD AHR AH-SR-2024P | 97004-AH-SR-2024P | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW NBD AHR AH-SR-2124P | 97004-AH-SR-2124P | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2148P | 97004-AH-SR-2148P | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2208P-AU | 97004-AH-SR-2208P-AU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2208P-EU | 97004-AH-SR-2208P-EU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2208P-NA | 97004-AH-SR-2208P-NA | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2208P-UK | 97004-AH-SR-2208P-UK | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2224P-AU | 97004-AH-SR-2224P-AU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2224P-EU | 97004-AH-SR-2224P-EU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2224P-NA | 97004-AH-SR-2224P-NA | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2224P-UK | 97004-AH-SR-2224P-UK | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2324P-AU | 97004-AH-SR-2324P-AU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2324P-EU | 97004-AH-SR-2324P-EU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2324P-NA | 97004-AH-SR-2324P-NA | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2324P-UK | 97004-AH-SR-2324P-UK | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-SR-2348P-AU | 97004-AH-SR-2348P-AU | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW NBD AHR AH-SR-2348P-EU | 97004-AH-SR-2348P-EU | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW NBD AHR AH-SR-2348P-NA | 97004-AH-SR-2348P-NA | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW NBD AHR AH-SR-2348P-UK | 97004-AH-SR-2348P-UK | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW NBD AHR AH-XR200P-AU | 97004-AH-XR200P-AU | \$ 60.00 | 10% | <i>\$54.41</i> |

| | | | | |
|------------------------------|-------------------------|-----------|-----|----------------|
| EW NBD AHR AH-XR200P-EU | 97004-AH-XR200P-EU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR200P-UK | 97004-AH-XR200P-UK | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR200P-US | 97004-AH-XR200P-US | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR600P | 97004-AH-XR600P | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR600P-AU | 97004-AH-XR600P-AU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR600P-EU | 97004-AH-XR600P-EU | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR600P-KR | 97004-AH-XR600P-KR | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR600P-UK | 97004-AH-XR600P-UK | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AH-XR600P-US | 97004-AH-XR600P-US | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AP-8533-68SB30-IL | 97004-AP-8533-68SB30-IL | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW NBD AHR AP3000-IL | 97004-AP3000-IL | \$ 40.50 | 10% | <i>\$36.72</i> |
| EW NBD AHR AP3000-TN | 97004-AP3000-TN | \$ 40.50 | 10% | <i>\$36.72</i> |
| EW NBD AHR AP3000-WW | 97004-AP3000-WW | \$ 40.50 | 10% | <i>\$36.72</i> |
| EW NBD AHR AP3000X-WW | 97004-AP3000X-WW | \$ 51.75 | 10% | <i>\$46.92</i> |
| EW NBD AHR AP302W-CAN | 97004-AP302W-CAN | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD AHR AP302W-EG | 97004-AP302W-EG | \$ 49.00 | 10% | <i>\$44.43</i> |
| EW NBD AHR AP302W-FCC | 97004-AP302W-FCC | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD AHR AP302W-WR | 97004-AP302W-WR | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW NBD AHR AP305C-1-CAN | 97004-AP305C-1-CAN | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR AP305C-1-EG | 97004-AP305C-1-EG | \$ 59.00 | 10% | <i>\$53.50</i> |

| | | | | |
|-------------------------|--------------------|----------|-----|----------------|
| EW NBD AHR AP305C-1-FCC | 97004-AP305C-1-FCC | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR AP305C-1-IL | 97004-AP305C-1-IL | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR AP305C-1-WR | 97004-AP305C-1-WR | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR AP305C-CAN | 97004-AP305C-CAN | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305C-EG | 97004-AP305C-EG | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305C-FCC | 97004-AP305C-FCC | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305C-IL | 97004-AP305C-IL | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305C-WR | 97004-AP305C-WR | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305CX-CAN | 97004-AP305CX-CAN | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305CX-FCC | 97004-AP305CX-FCC | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305CX-IL | 97004-AP305CX-IL | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP305CX-WR | 97004-AP305CX-WR | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR AP310e-1-WR | 97004-AP310e-1-WR | \$ 38.00 | 10% | <i>\$34.46</i> |
| EW NBD AHR AP310e-CAN | 97004-AP310e-CAN | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW NBD AHR AP310e-FCC | 97004-AP310e-FCC | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW NBD AHR AP310e-IL | 97004-AP310e-IL | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW NBD AHR AP310e-WR | 97004-AP310e-WR | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW NBD AHR AP310i-1-WR | 97004-AP310i-1-WR | \$ 38.00 | 10% | <i>\$34.46</i> |
| EW NBD AHR AP310i-CAN | 97004-AP310i-CAN | \$ 40.00 | 10% | <i>\$36.27</i> |

| | | | | |
|-------------------------|--------------------|----------|-----|---------|
| EW NBD AHR AP310i-FCC | 97004-AP310i-FCC | \$ 40.00 | 10% | \$36.27 |
| EW NBD AHR AP310i-IL | 97004-AP310i-IL | \$ 40.00 | 10% | \$36.27 |
| EW NBD AHR AP310i-WR | 97004-AP310i-WR | \$ 40.00 | 10% | \$36.27 |
| EW NBD AHR AP360e-CAN | 97004-AP360e-CAN | \$ 57.00 | 10% | \$51.68 |
| EW NBD AHR AP360e-FCC | 97004-AP360e-FCC | \$ 57.00 | 10% | \$51.68 |
| EW NBD AHR AP360e-IL | 97004-AP360e-IL | \$ 57.00 | 10% | \$51.68 |
| EW NBD AHR AP360e-WR | 97004-AP360e-WR | \$ 57.00 | 10% | \$51.68 |
| EW NBD AHR AP360i-CAN | 97004-AP360i-CAN | \$ 57.00 | 10% | \$51.68 |
| EW NBD AHR AP360i-FCC | 97004-AP360i-FCC | \$ 57.00 | 10% | \$51.68 |
| EW NBD AHR AP360i-WR | 97004-AP360i-WR | \$ 57.00 | 10% | \$51.68 |
| EW NBD AHR AP4000-WW | 97004-AP4000-1-WW | \$ 60.00 | 10% | \$54.41 |
| EW NBD AHR AP4000-IL | 97004-AP4000-IL | \$ 60.00 | 10% | \$54.41 |
| EW NBD AHR AP4000-WW | 97004-AP4000-WW | \$ 60.00 | 10% | \$54.41 |
| EW NBD AHR AP410C-1-CAN | 97004-AP410C-1-CAN | \$ 56.00 | 10% | \$50.78 |
| EW NBD AHR AP410C-1-EG | 97004-AP410C-1-EG | \$ 56.00 | 10% | \$50.78 |
| EW NBD AHR AP410C-1-FCC | 97004-AP410C-1-FCC | \$ 56.00 | 10% | \$50.78 |
| EW NBD AHR AP410C-1-IL | 97004-AP410C-1-IL | \$ 56.00 | 10% | \$50.78 |
| EW NBD AHR AP410C-1-WR | 97004-AP410C-1-WR | \$ 56.00 | 10% | \$50.78 |
| EW NBD AHR AP410C-CAN | 97004-AP410C-CAN | \$ 60.00 | 10% | \$54.41 |
| EW NBD AHR AP410C-EG | 97004-AP410C-EG | \$ 60.00 | 10% | \$54.41 |

| | | | | |
|-------------------------|--------------------|----------|-----|----------------|
| EW NBD AHR AP410C-FCC | 97004-AP410C-FCC | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AP410C-IL | 97004-AP410C-IL | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AP410C-WR | 97004-AP410C-WR | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AP410e-CAN | 97004-AP410e-CAN | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR AP410e-FCC | 97004-AP410e-FCC | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR AP410e-WR | 97004-AP410e-WR | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR AP410i-1-FCC | 97004-AP410i-1-FCC | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AP410i-1-WR | 97004-AP410i-1-WR | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW NBD AHR AP410i-CAN | 97004-AP410i-CAN | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR AP410i-FCC | 97004-AP410i-FCC | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR AP410i-IL | 97004-AP410i-IL | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR AP410i-WR | 97004-AP410i-WR | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR AP460C-CAN | 97004-AP460C-CAN | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460C-EG | 97004-AP460C-EG | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460C-FCC | 97004-AP460C-FCC | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460C-IL | 97004-AP460C-IL | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460C-WR | 97004-AP460C-WR | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460e-CAN | 97004-AP460e-CAN | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW NBD AHR AP460e-FCC | 97004-AP460e-FCC | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW NBD AHR AP460e-WR | 97004-AP460e-WR | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD AHR AP460i-CAN | 97004-AP460i-CAN | \$ 78.00 | 10% | <i>\$70.73</i> |

| | | | | |
|---------------------------|----------------------|-----------|-----|-----------------|
| EW NBD AHR AP460i-FCC | 97004-AP460i-FCC | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD AHR AP460i-IL | 97004-AP460i-IL | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD AHR AP460i-WR | 97004-AP460i-WR | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD AHR AP460S12C-CAN | 97004-AP460S12C-CAN | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460S12C-FCC | 97004-AP460S12C-FCC | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460S12C-WR | 97004-AP460S12C-WR | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460S6C-CAN | 97004-AP460S6C-CAN | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460S6C-FCC | 97004-AP460S6C-FCC | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP460S6C-WR | 97004-AP460S6C-WR | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW NBD AHR AP5010-IL | 97004-AP5010-IL | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW NBD AHR AP5010-WW | 97004-AP5010-WW | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW NBD AHR AP5020-WW | 97004-AP5020-WW | \$ 107.96 | 6% | <i>\$102.24</i> |
| EW NBD AHR AP5050D-WW | 97004-AP5050D-WW | \$ 245.00 | 10% | <i>\$222.15</i> |
| EW NBD AHR AP5050U-WW | 97004-AP5050U-WW | \$ 191.00 | 10% | <i>\$173.19</i> |
| EW NBD AHR AP505i-FCC | 97004-AP505i-FCC | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD AHR AP505i-FCC-TAA | 97004-AP505i-FCC-TAA | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD AHR AP505i-WR | 97004-AP505i-WR | \$ 90.00 | 10% | <i>\$81.61</i> |
| EW NBD AHR AP510C-CAN | 97004-AP510C-CAN | \$ 52.00 | 10% | <i>\$47.15</i> |

| | | | | |
|---------------------------|----------------------|-----------|-----|-----------------|
| EW NBD AHR AP510C-CE | 97004-AP510C-CE | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR AP510C-FCC | 97004-AP510C-FCC | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR AP510C-W | 97004-AP510C-W | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR AP510C-WW | 97004-AP510C-WW | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AP510CX-CAN | 97004-AP510CX-CAN | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR AP510CX-CE | 97004-AP510CX-CE | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR AP510CX-FCC | 97004-AP510CX-FCC | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR AP510CX-W | 97004-AP510CX-W | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR AP510CX-WW | 97004-AP510CX-WW | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW NBD AHR AP510e-FCC | 97004-AP510e-FCC | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW NBD AHR AP510e-FCC-TAA | 97004-AP510e-FCC-TAA | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW NBD AHR AP510e-WR | 97004-AP510e-WR | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD AHR AP510i-1-FCC | 97004-AP510i-1-FCC | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW NBD AHR AP510i-1-WR | 97004-AP510i-1-WR | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW NBD AHR AP510i-FCC | 97004-AP510i-FCC | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW NBD AHR AP510i-FCC-TAA | 97004-AP510i-FCC-TAA | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW NBD AHR AP510i-WR | 97004-AP510i-WR | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW NBD AHR AP560h-FCC | 97004-AP560h-FCC | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW NBD AHR AP560h-WR | 97004-AP560h-WR | \$ 250.00 | 10% | <i>\$226.69</i> |

| | | | | |
|-----------------------|------------------|-------------|-----|-------------------|
| EW NBD AHR AP560i-FCC | 97004-AP560i-FCC | \$ 182.00 | 10% | <i>\$165.03</i> |
| EW NBD AHR AP560i-WR | 97004-AP560i-WR | \$ 173.00 | 10% | <i>\$156.87</i> |
| EW NBD AHR AP560m-FCC | 97004-AP560m-FCC | \$ 182.00 | 10% | <i>\$165.03</i> |
| EW NBD AHR AP560t-FCC | 97004-AP560t-FCC | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW NBD AHR AP560u-FCC | 97004-AP560u-FCC | \$ 169.00 | 10% | <i>\$153.24</i> |
| EW NBD AHR E2122 | 97004-E2122 | \$ 4,219.00 | 10% | <i>\$3,825.58</i> |
| EW NBD AHR E2122-1 | 97004-E2122-1 | \$ 3,999.00 | 10% | <i>\$3,626.09</i> |
| EW NBD AHR E3120-1 | 97004-E3120-1 | \$ 6,541.00 | 10% | <i>\$5,931.05</i> |
| EW NBD AHR E3125 | 97004-E3125 | \$ 7,064.00 | 10% | <i>\$6,405.28</i> |
| EW NBD AHR | 97004-H30003 | \$ 36.00 | 10% | <i>\$32.64</i> |
| EW NBD AHR | 97004-H30004 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD AHR | 97004-H30005 | \$ 44.00 | 10% | <i>\$39.90</i> |
| EW NBD AHR | 97004-H30006 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD AHR | 97004-H30007 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD AHR | 97004-H30008 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW NBD AHR | 97004-H30009 | \$ 36.00 | 10% | <i>\$32.64</i> |
| EW NBD AHR | 97004-H30010 | \$ 73.00 | 10% | <i>\$66.19</i> |
| EW NBD AHR | 97004-H30011 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW NBD AHR | 97004-H30012 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW NBD AHR | 97004-H30078 | \$ 1,709.00 | 10% | <i>\$1,549.64</i> |
| EW NBD AHR | 97004-H30104 | \$ 1,578.00 | 10% | <i>\$1,430.85</i> |
| EW NBD AHR | 97004-H30105 | \$ 1,559.00 | 10% | <i>\$1,413.62</i> |
| EW NBD AHR | 97004-H30131 | \$ 893.00 | 10% | <i>\$809.73</i> |
| EW NBD AHR | 97004-H30132 | \$ 875.00 | 10% | <i>\$793.41</i> |
| EW NBD AHR | 97004-H30133 | \$ 2,310.00 | 10% | <i>\$2,094.59</i> |
| EW NBD AHR | 97004-H30134 | \$ 2,921.00 | 10% | <i>\$2,648.62</i> |
| EW NBD AHR | 97004-H30135 | \$ 2,355.00 | 10% | <i>\$2,135.40</i> |
| EW NBD AHR | 97004-H30136 | \$ 2,921.00 | 10% | <i>\$2,648.62</i> |
| EW NBD AHR | 97004-H30184 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW NBD AHR | 97004-H30185 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW NBD AHR | 97004-H30186 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD AHR | 97004-H30187 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD AHR | 97004-H30188 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD AHR | 97004-H30189 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD AHR | 97004-H30190 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW NBD AHR | 97004-H30214 | \$ 116.00 | 10% | <i>\$105.18</i> |
| EW NBD AHR | 97004-H30215 | \$ 116.00 | 10% | <i>\$105.18</i> |

| | | | | |
|------------|--------------|-------------|-----|------------|
| EW NBD AHR | 97004-H30216 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30217 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30218 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30219 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30220 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30221 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30222 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30223 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30224 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30225 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30226 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30227 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30228 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30229 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30267 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30268 | \$ 221.00 | 10% | \$200.39 |
| EW NBD AHR | 97004-H30269 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30270 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30271 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30272 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30273 | \$ 486.00 | 10% | \$440.68 |
| EW NBD AHR | 97004-H30274 | \$ 486.00 | 10% | \$440.68 |
| EW NBD AHR | 97004-H30275 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30276 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30277 | \$ 486.00 | 10% | \$440.68 |
| EW NBD AHR | 97004-H30278 | \$ 529.00 | 10% | \$479.67 |
| EW NBD AHR | 97004-H30279 | \$ 486.00 | 10% | \$440.68 |
| EW NBD AHR | 97004-H30280 | \$ 486.00 | 10% | \$440.68 |
| EW NBD AHR | 97004-H30281 | \$ 486.00 | 10% | \$440.68 |
| EW NBD AHR | 97004-H30282 | \$ 486.00 | 10% | \$440.68 |
| EW NBD AHR | 97004-H30283 | \$ 321.00 | 10% | \$291.07 |
| EW NBD AHR | 97004-H30284 | \$ 353.00 | 10% | \$320.08 |
| EW NBD AHR | 97004-H30293 | \$ 1,925.00 | 10% | \$1,745.49 |
| EW NBD AHR | 97004-H30296 | \$ 116.00 | 10% | \$105.18 |
| EW NBD AHR | 97004-H30297 | \$ 106.00 | 10% | \$96.12 |
| EW NBD AHR | 97004-H30298 | \$ 116.00 | 10% | \$105.18 |
| EW NBD AHR | 97004-H30299 | \$ 106.00 | 10% | \$96.12 |
| EW NBD AHR | 97004-H30380 | \$ 3,136.00 | 10% | \$2,843.57 |
| EW NBD AHR | 97004-H30381 | \$ 316.00 | 10% | \$286.53 |
| EW NBD AHR | 97004-H30383 | \$ 4,460.00 | 10% | \$4,044.11 |
| EW NBD AHR | 97004-H30384 | \$ 257.00 | 10% | \$233.03 |
| EW NBD AHR | 97004-H30391 | \$ 605.00 | 10% | \$548.58 |

| | | | | |
|------------|--------------|-------------|-----|------------|
| EW NBD AHR | 97004-H30392 | \$ 605.00 | 10% | \$548.58 |
| EW NBD AHR | 97004-H30393 | \$ 271.00 | 10% | \$245.73 |
| EW NBD AHR | 97004-H30394 | \$ 1,164.00 | 10% | \$1,055.46 |
| EW NBD AHR | 97004-H30395 | \$ 1,391.00 | 10% | \$1,261.29 |
| EW NBD AHR | 97004-H30396 | \$ 1,268.00 | 10% | \$1,149.76 |
| EW NBD AHR | 97004-H30397 | \$ 1,510.00 | 10% | \$1,369.19 |
| EW NBD AHR | 97004-H30398 | \$ 277.00 | 10% | \$251.17 |
| EW NBD AHR | 97004-H30400 | \$ 155.00 | 10% | \$140.55 |
| EW NBD AHR | 97004-H30401 | \$ 216.00 | 10% | \$195.86 |
| EW NBD AHR | 97004-H30402 | \$ 232.00 | 10% | \$210.37 |
| EW NBD AHR | 97004-H30403 | \$ 341.00 | 10% | \$309.20 |
| EW NBD AHR | 97004-H30434 | \$ 93.00 | 10% | \$84.33 |
| EW NBD AHR | 97004-H30480 | \$ 399.00 | 10% | \$361.79 |
| EW NBD AHR | 97004-H30495 | \$ 893.00 | 10% | \$809.73 |
| EW NBD AHR | 97004-H30496 | \$ 875.00 | 10% | \$793.41 |
| EW NBD AHR | 97004-H30497 | \$ 1,293.00 | 10% | \$1,172.43 |
| EW NBD AHR | 97004-H30498 | \$ 1,268.00 | 10% | \$1,149.76 |
| EW NBD AHR | 97004-H30499 | \$ 435.00 | 10% | \$394.44 |
| EW NBD AHR | 97004-H30501 | \$ 1,268.00 | 10% | \$1,149.76 |
| EW NBD AHR | 97004-H30502 | \$ 1,949.00 | 10% | \$1,767.26 |
| EW NBD AHR | 97004-H30503 | \$ 435.00 | 10% | \$394.44 |
| EW NBD AHR | 97004-H30505 | \$ 2,310.00 | 10% | \$2,094.59 |
| EW NBD AHR | 97004-H30506 | \$ 3,140.00 | 10% | \$2,847.20 |
| EW NBD AHR | 97004-H30509 | \$ 1,949.00 | 10% | \$1,767.26 |
| EW NBD AHR | 97004-H30510 | \$ 2,310.00 | 10% | \$2,094.59 |
| EW NBD AHR | 97004-H30511 | \$ 3,140.00 | 10% | \$2,847.20 |
| EW NBD AHR | 97004-H30512 | \$ 435.00 | 10% | \$394.44 |
| EW NBD AHR | 97004-H30513 | \$ 729.00 | 10% | \$661.02 |
| EW NBD AHR | 97004-H30525 | \$ 3,140.00 | 10% | \$2,847.20 |
| EW NBD AHR | 97004-H30526 | \$ 2,310.00 | 10% | \$2,094.59 |
| EW NBD AHR | 97004-H30528 | \$ 3,636.00 | 10% | \$3,296.94 |
| EW NBD AHR | 97004-H30529 | \$ 6,137.00 | 10% | \$5,564.72 |
| EW NBD AHR | 97004-H30530 | \$ 3,721.00 | 10% | \$3,374.02 |
| EW NBD AHR | 97004-H30531 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW NBD AHR | 97004-H30532 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW NBD AHR | 97004-H30533 | \$ 3,721.00 | 10% | \$3,374.02 |
| EW NBD AHR | 97004-H30534 | \$ 5,279.00 | 10% | \$4,786.73 |
| EW NBD AHR | 97004-H30535 | \$ 5,643.00 | 10% | \$5,116.79 |
| EW NBD AHR | 97004-H30536 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW NBD AHR | 97004-H30537 | \$ 5,643.00 | 10% | \$5,116.79 |
| EW NBD AHR | 97004-H30538 | \$ 3,140.00 | 10% | \$2,847.20 |
| EW NBD AHR | 97004-H30539 | \$ 5,911.00 | 10% | \$5,359.80 |

| | | | | |
|----------------------------|--------------|-------------|-----|------------|
| EW NBD AHR | 97004-H30540 | \$ 6,232.00 | 10% | \$5,650.87 |
| EW NBD AHR | 97004-H30542 | \$ 504.00 | 10% | \$457.00 |
| EW NBD AHR | 97004-H30543 | \$ 425.00 | 10% | \$385.37 |
| EW NBD AHR | 97004-H30544 | \$ 754.00 | 10% | \$683.69 |
| EW NBD AHR | 97004-H30547 | \$ 847.00 | 10% | \$768.02 |
| EW NBD AHR | 97004-H30548 | \$ 425.00 | 10% | \$385.37 |
| EW NBD AHR | 97004-H30549 | \$ 715.00 | 10% | \$648.33 |
| EW NBD AHR | 97004-H30550 | \$ 715.00 | 10% | \$648.33 |
| EW NBD AHR | 97004-H30551 | \$ 504.00 | 10% | \$457.00 |
| EW NBD AHR | 97004-H30552 | \$ 425.00 | 10% | \$385.37 |
| EW NBD AHR | 97004-H30553 | \$ 677.00 | 10% | \$613.87 |
| EW NBD AHR | 97004-H30567 | \$ 2,614.00 | 10% | \$2,370.24 |
| EW NBD AHR | 97004-H30569 | \$ 2,310.00 | 10% | \$2,094.59 |
| EW NBD AHR | 97004-H30570 | \$ 2,769.00 | 10% | \$2,510.79 |
| EW NBD AHR | 97004-H30571 | \$ 2,769.00 | 10% | \$2,510.79 |
| EW NBD AHR | 97004-H30573 | \$ 2,310.00 | 10% | \$2,094.59 |
| EW NBD AHR | 97004-H30574 | \$ 2,553.00 | 10% | \$2,314.93 |
| EW NBD AHR | 97004-H30575 | \$ 1,590.00 | 10% | \$1,441.73 |
| EW NBD AHR | 97004-H30576 | \$ 2,310.00 | 10% | \$2,094.59 |
| EW NBD AHR | 97004-H30577 | \$ 2,769.00 | 10% | \$2,510.79 |
| EW NBD AHR | 97004-H30578 | \$ 2,769.00 | 10% | \$2,510.79 |
| EW NBD AHR | 97004-H30585 | \$ 2,738.00 | 10% | \$2,482.68 |
| EW NBD AHR | 97004-H30586 | \$ 4,308.00 | 10% | \$3,906.28 |
| EW NBD AHR | 97004-H30587 | \$ 2,355.00 | 10% | \$2,135.40 |
| EW NBD AHR | 97004-H30588 | \$ 1,620.00 | 10% | \$1,468.94 |
| EW NBD AHR | 97004-H30589 | \$ 2,517.00 | 10% | \$2,282.29 |
| EW NBD AHR | 97004-H30591 | \$ 4,308.00 | 10% | \$3,906.28 |
| EW NBD AHR | 97004-H30632 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR | 97004-H30633 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR | 97004-H30638 | \$ 1,216.00 | 10% | \$1,102.61 |
| EW NBD AHR | 97004-H30643 | \$ 3,959.00 | 10% | \$3,589.82 |
| EW NBD AHR | 97004-H30706 | \$ 3,707.00 | 10% | \$3,361.32 |
| EW NBD AHR | 97004-H30707 | \$ 2,310.00 | 10% | \$2,094.59 |
| EW NBD AHR | 97004-H30724 | \$ 257.00 | 10% | \$233.03 |
| EW NBD AHR | 97004-H30725 | \$ 875.00 | 10% | \$793.41 |
| EW NBD AHR | 97004-H30726 | \$ 5,753.00 | 10% | \$5,216.53 |
| EW NBD AHR | 97004-H30727 | \$ 6,113.00 | 10% | \$5,542.96 |
| EW NBD AHR | 97004-H30730 | \$ 50.00 | 10% | \$45.34 |
| EW NBD AHR | 97004-H30731 | \$ 50.00 | 10% | \$45.34 |
| EW NBD AHR 30732 | 97004-H30732 | \$ 1,527.00 | 10% | \$1,384.61 |
| EW NBD AHR SKL8008-0810-F8 | 97004-H30733 | \$ 6,381.00 | 10% | \$5,785.97 |

| | | | | |
|-------------------------|--------------|-------------|-----|------------|
| EW NBD AHR STL2006-0850 | 97004-H30734 | \$ 4,870.00 | 10% | \$4,415.87 |
| EW NBD AHR SGL2001-0850 | 97004-H30735 | \$ 5,392.00 | 10% | \$4,889.20 |
| EW NBD AHR SOK2209-0204 | 97004-H30736 | \$ 863.00 | 10% | \$782.53 |
| EW NBD AHR H30738 | 97004-H30738 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR -H30739 | 97004-H30739 | \$ 807.00 | 10% | \$731.75 |
| EW NBD AHR -H30740 | 97004-H30740 | \$ 464.00 | 10% | \$420.73 |
| EW NBD AHR -H30741 | 97004-H30741 | \$ 855.00 | 10% | \$775.27 |
| EW NBD AHR -H30742 | 97004-H30742 | \$ 756.00 | 10% | \$685.50 |
| EW NBD AHR -H30743 | 97004-H30743 | \$ 807.00 | 10% | \$731.75 |
| EW NBD AHR -H30744 | 97004-H30744 | \$ 464.00 | 10% | \$420.73 |
| EW NBD AHR -H30745 | 97004-H30745 | \$ 473.00 | 10% | \$428.89 |
| EW NBD AHR -H30746 | 97004-H30746 | \$ 965.00 | 10% | \$875.01 |
| EW NBD AHR -H30747 | 97004-H30747 | \$ 1,673.00 | 10% | \$1,516.99 |
| EW NBD AHR -H30748 | 97004-H30748 | \$ 2,473.00 | 10% | \$2,242.39 |
| EW NBD AHR -H30749 | 97004-H30749 | \$ 5,550.00 | 10% | \$5,032.46 |
| EW NBD AHR -H30750 | 97004-H30750 | \$ 5,550.00 | 10% | \$5,032.46 |
| EW NBD AHR -H30751 | 97004-H30751 | \$ 3,302.00 | 10% | \$2,994.09 |
| EW NBD AHR -H30754 | 97004-H30754 | \$ 5,550.00 | 10% | \$5,032.46 |
| EW NBD AHR -H30755 | 97004-H30755 | \$ 6,041.00 | 10% | \$5,477.68 |
| EW NBD AHR -H30756 | 97004-H30756 | \$ 5,550.00 | 10% | \$5,032.46 |
| EW NBD AHR -H30757 | 97004-H30757 | \$ 2,473.00 | 10% | \$2,242.39 |
| EW NBD AHR -H30758 | 97004-H30758 | \$ 5,214.00 | 10% | \$4,727.79 |
| EW NBD AHR -H30759 | 97004-H30759 | \$ 5,661.00 | 10% | \$5,133.11 |
| EW NBD AHR -H30760 | 97004-H30760 | \$ 6,704.00 | 10% | \$6,078.85 |
| EW NBD AHR -H30761 | 97004-H30761 | \$ 2,473.00 | 10% | \$2,242.39 |
| EW NBD AHR -H30762 | 97004-H30762 | \$ 6,041.00 | 10% | \$5,477.68 |
| EW NBD AHR -H30763 | 97004-H30763 | \$ 6,041.00 | 10% | \$5,477.68 |
| EW NBD AHR -H30764 | 97004-H30764 | \$ 3,816.00 | 10% | \$3,460.16 |
| EW NBD AHR -H30765 | 97004-H30765 | \$ 3,364.00 | 10% | \$3,050.31 |
| EW NBD AHR -H30766 | 97004-H30766 | \$ 6,538.00 | 10% | \$5,928.33 |
| EW NBD AHR -H30767 | 97004-H30767 | \$ 3,816.00 | 10% | \$3,460.16 |
| EW NBD AHR H30769 | 97004-H30769 | \$ 1,970.00 | 10% | \$1,786.30 |
| EW NBD AHR H30773 | 97004-H30773 | \$ 122.00 | 10% | \$110.62 |
| EW NBD AHR H30774 | 97004-H30774 | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR H30775 | 97004-H30775 | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR H30776 | 97004-H30776 | \$ 122.00 | 10% | \$110.62 |
| EW NBD AHR H30777 | 97004-H30777 | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR H30778 | 97004-H30778 | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR H30779 | 97004-H30779 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H30780 | 97004-H30780 | \$ 72.00 | 10% | \$65.29 |
| EW NBD AHR H30781 | 97004-H30781 | \$ 72.00 | 10% | \$65.29 |
| EW NBD AHR H30782 | 97004-H30782 | \$ 61.00 | 10% | \$55.31 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H30783 | 97004-H30783 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR H30784 | 97004-H30784 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR H30785 | 97004-H30785 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H30786 | 97004-H30786 | \$ 72.00 | 10% | \$65.29 |
| EW NBD AHR H30787 | 97004-H30787 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H30788 | 97004-H30788 | \$ 72.00 | 10% | \$65.29 |
| EW NBD AHR H30789 | 97004-H30789 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR H30790 | 97004-H30790 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H30791 | 97004-H30791 | \$ 62.00 | 10% | \$56.22 |
| EW NBD AHR H30793 | 97004-H30793 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30794 | 97004-H30794 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30795 | 97004-H30795 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30796 | 97004-H30796 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30797 | 97004-H30797 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30798 | 97004-H30798 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30799 | 97004-H30799 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30800 | 97004-H30800 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H30801 | 97004-H30801 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30802 | 97004-H30802 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H30803 | 97004-H30803 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30804 | 97004-H30804 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30805 | 97004-H30805 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30806 | 97004-H30806 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30807 | 97004-H30807 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30808 | 97004-H30808 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30809 | 97004-H30809 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30810 | 97004-H30810 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30811 | 97004-H30811 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30812 | 97004-H30812 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30813 | 97004-H30813 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H30814 | 97004-H30814 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30815 | 97004-H30815 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30816 | 97004-H30816 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30817 | 97004-H30817 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30818 | 97004-H30818 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30819 | 97004-H30819 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30820 | 97004-H30820 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30821 | 97004-H30821 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H30822 | 97004-H30822 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30823 | 97004-H30823 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H30824 | 97004-H30824 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30825 | 97004-H30825 | \$ 61.00 | 10% | \$55.31 |

| | | | | |
|-------------------|--------------|-------------|-----|----------|
| EW NBD AHR H30826 | 97004-H30826 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30827 | 97004-H30827 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30828 | 97004-H30828 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30829 | 97004-H30829 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H30830 | 97004-H30830 | \$ 86.00 | 10% | \$77.98 |
| EW NBD AHR H30831 | 97004-H30831 | \$ 52.00 | 10% | \$47.15 |
| EW NBD AHR H30832 | 97004-H30832 | \$ 1,093.00 | 10% | \$991.08 |
| EW NBD AHR H30833 | 97004-H30833 | \$ 290.00 | 10% | \$262.96 |
| EW NBD AHR H30834 | 97004-H30834 | \$ 290.00 | 10% | \$262.96 |
| EW NBD AHR H30836 | 97004-H30836 | \$ 1,093.00 | 10% | \$991.08 |
| EW NBD AHR H30838 | 97004-H30838 | \$ 41.00 | 10% | \$37.18 |
| EW NBD AHR H30839 | 97004-H30839 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30840 | 97004-H30840 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30841 | 97004-H30841 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30842 | 97004-H30842 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30843 | 97004-H30843 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30844 | 97004-H30844 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30845 | 97004-H30845 | \$ 55.00 | 10% | \$49.87 |
| EW NBD AHR H30846 | 97004-H30846 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30847 | 97004-H30847 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30848 | 97004-H30848 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30849 | 97004-H30849 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30850 | 97004-H30850 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30851 | 97004-H30851 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30852 | 97004-H30852 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30853 | 97004-H30853 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30854 | 97004-H30854 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30855 | 97004-H30855 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30856 | 97004-H30856 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30857 | 97004-H30857 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30858 | 97004-H30858 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30859 | 97004-H30859 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30860 | 97004-H30860 | \$ 105.00 | 10% | \$95.21 |
| EW NBD AHR H30866 | 97004-H30866 | \$ 118.00 | 10% | \$107.00 |
| EW NBD AHR H30867 | 97004-H30867 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30868 | 97004-H30868 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30869 | 97004-H30869 | \$ 207.00 | 10% | \$187.70 |
| EW NBD AHR H30870 | 97004-H30870 | \$ 207.00 | 10% | \$187.70 |
| EW NBD AHR H30871 | 97004-H30871 | \$ 190.00 | 10% | \$172.28 |
| EW NBD AHR H30872 | 97004-H30872 | \$ 108.00 | 10% | \$97.93 |
| EW NBD AHR H30873 | 97004-H30873 | \$ 108.00 | 10% | \$97.93 |
| EW NBD AHR H30874 | 97004-H30874 | \$ 108.00 | 10% | \$97.93 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW NBD AHR H30875 | 97004-H30875 | \$ 39.00 | 10% | \$35.36 |
| EW NBD AHR H30876 | 97004-H30876 | \$ 36.00 | 10% | \$32.64 |
| EW NBD AHR H30877 | 97004-H30877 | \$ 39.00 | 10% | \$35.36 |
| EW NBD AHR H30878 | 97004-H30878 | \$ 39.00 | 10% | \$35.36 |
| EW NBD AHR H30891 | 97004-H30891 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H30892 | 97004-H30892 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H30893 | 97004-H30893 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H30894 | 97004-H30894 | \$ 39.00 | 10% | \$35.36 |
| EW NBD AHR H30895 | 97004-H30895 | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR H30896 | 97004-H30896 | \$ 309.00 | 10% | \$280.19 |
| EW NBD AHR H30897 | 97004-H30897 | \$ 543.00 | 10% | \$492.37 |
| EW NBD AHR H30898 | 97004-H30898 | \$ 608.00 | 10% | \$551.30 |
| EW NBD AHR H30900 | 97004-H30900 | \$ 1,839.00 | 10% | \$1,667.51 |
| EW NBD AHR H30901 | 97004-H30901 | \$ 2,448.00 | 10% | \$2,219.72 |
| EW NBD AHR H30902 | 97004-H30902 | \$ 2,567.00 | 10% | \$2,327.63 |
| EW NBD AHR H30904 | 97004-H30904 | \$ 3,781.00 | 10% | \$3,428.42 |
| EW NBD AHR H30905 | 97004-H30905 | \$ 5,403.00 | 10% | \$4,899.17 |
| EW NBD AHR H30906 | 97004-H30906 | \$ 146.00 | 10% | \$132.39 |
| EW NBD AHR H30912 | 97004-H30912 | \$ 406.00 | 10% | \$368.14 |
| EW NBD AHR H30913 | 97004-H30913 | \$ 43.00 | 10% | \$38.99 |
| EW NBD AHR H30914 | 97004-H30914 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H30915 | 97004-H30915 | \$ 40.00 | 10% | \$36.27 |
| EW NBD AHR H30916 | 97004-H30916 | \$ 40.00 | 10% | \$36.27 |
| EW NBD AHR H30917 | 97004-H30917 | \$ 43.00 | 10% | \$38.99 |
| EW NBD AHR H30918 | 97004-H30918 | \$ 43.00 | 10% | \$38.99 |
| EW NBD AHR H30946 | 97004-H30946 | \$ 77.00 | 10% | \$69.82 |
| EW NBD AHR H30948 | 97004-H30948 | \$ 77.00 | 10% | \$69.82 |
| EW NBD AHR H30950 | 97004-H30950 | \$ 85.00 | 10% | \$77.07 |
| EW NBD AHR H30951 | 97004-H30951 | \$ 77.00 | 10% | \$69.82 |
| EW NBD AHR H30952 | 97004-H30952 | \$ 77.00 | 10% | \$69.82 |
| EW NBD AHR H30965 | 97004-H30965 | \$ 212.00 | 10% | \$192.23 |
| EW NBD AHR H30966 | 97004-H30966 | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR H30967 | 97004-H30967 | \$ 122.00 | 10% | \$110.62 |
| EW NBD AHR H30968 | 97004-H30968 | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR H30969 | 97004-H30969 | \$ 69.00 | 10% | \$62.57 |
| EW NBD AHR H30970 | 97004-H30970 | \$ 96.00 | 10% | \$87.05 |
| EW NBD AHR H30971 | 97004-H30971 | \$ 83.00 | 10% | \$75.26 |
| EW NBD AHR H30972 | 97004-H30972 | \$ 96.00 | 10% | \$87.05 |
| EW NBD AHR H30973 | 97004-H30973 | \$ 136.00 | 10% | \$123.32 |
| EW NBD AHR H30974 | 97004-H30974 | \$ 118.00 | 10% | \$107.00 |
| EW NBD AHR H30975 | 97004-H30975 | \$ 136.00 | 10% | \$123.32 |
| EW NBD AHR H30976 | 97004-H30976 | \$ 136.00 | 10% | \$123.32 |

| | | | | |
|-------------------|--------------|-------------|-----|-------------------|
| EW NBD AHR H30977 | 97004-H30977 | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW NBD AHR H30978 | 97004-H30978 | \$ 136.00 | 10% | <i>\$123.32</i> |
| EW NBD AHR H30995 | 97004-H30995 | \$ 1,478.00 | 10% | <i>\$1,340.18</i> |
| EW NBD AHR H30996 | 97004-H30996 | \$ 3,372.00 | 10% | <i>\$3,057.56</i> |
| EW NBD AHR H30997 | 97004-H30997 | \$ 5,183.00 | 10% | <i>\$4,699.69</i> |
| EW NBD AHR H31030 | 97004-H31030 | \$ 4,773.00 | 10% | <i>\$4,327.92</i> |
| EW NBD AHR H31031 | 97004-H31031 | \$ 380.00 | 10% | <i>\$344.57</i> |
| EW NBD AHR H31033 | 97004-H31033 | \$ 2,892.00 | 10% | <i>\$2,622.32</i> |
| EW NBD AHR H31034 | 97004-H31034 | \$ 1,608.00 | 10% | <i>\$1,458.05</i> |
| EW NBD AHR H31035 | 97004-H31035 | \$ 1,682.00 | 10% | <i>\$1,525.15</i> |
| EW NBD AHR H31036 | 97004-H31036 | \$ 3,368.00 | 10% | <i>\$3,053.93</i> |
| EW NBD AHR H31040 | 97004-H31040 | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW NBD AHR H31041 | 97004-H31041 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW NBD AHR H31042 | 97004-H31042 | \$ 191.00 | 10% | <i>\$173.19</i> |
| EW NBD AHR H31043 | 97004-H31043 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW NBD AHR H31044 | 97004-H31044 | \$ 437.00 | 10% | <i>\$396.25</i> |
| EW NBD AHR H31047 | 97004-H31047 | \$ 128.00 | 10% | <i>\$116.06</i> |
| EW NBD AHR H31049 | 97004-H31049 | \$ 1,344.00 | 10% | <i>\$1,218.67</i> |
| EW NBD AHR H31060 | 97004-H31060 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW NBD AHR H31062 | 97004-H31062 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW NBD AHR H31066 | 97004-H31066 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW NBD AHR H31068 | 97004-H31068 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW NBD AHR H31076 | 97004-H31076 | \$ 183.00 | 10% | <i>\$165.94</i> |
| EW NBD AHR H31077 | 97004-H31077 | \$ 191.00 | 10% | <i>\$173.19</i> |
| EW NBD AHR H31078 | 97004-H31078 | \$ 191.00 | 10% | <i>\$173.19</i> |
| EW NBD AHR H31103 | 97004-H31103 | \$ 3,083.00 | 10% | <i>\$2,795.51</i> |
| EW NBD AHR H31119 | 97004-H31119 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR H31124 | 97004-H31124 | \$ 74.00 | 10% | <i>\$67.10</i> |
| EW NBD AHR H31127 | 97004-H31127 | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW NBD AHR H31132 | 97004-H31132 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW NBD AHR H31134 | 97004-H31134 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW NBD AHR H31135 | 97004-H31135 | \$ 44.00 | 10% | <i>\$39.90</i> |
| EW NBD AHR H31136 | 97004-H31136 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW NBD AHR H31137 | 97004-H31137 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR H31197 | 97004-H31197 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD AHR H31198 | 97004-H31198 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD AHR H31199 | 97004-H31199 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD AHR H31200 | 97004-H31200 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD AHR H31201 | 97004-H31201 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD AHR H31202 | 97004-H31202 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD AHR H31203 | 97004-H31203 | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD AHR H31204 | 97004-H31204 | \$ 71.00 | 10% | <i>\$64.38</i> |

| | | | | |
|-------------------|--------------|--------------|-----|-------------|
| EW NBD AHR H31205 | 97004-H31205 | \$ 81.00 | 10% | \$73.45 |
| EW NBD AHR H31206 | 97004-H31206 | \$ 81.00 | 10% | \$73.45 |
| EW NBD AHR H31207 | 97004-H31207 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H31208 | 97004-H31208 | \$ 81.00 | 10% | \$73.45 |
| EW NBD AHR H31210 | 97004-H31210 | \$ 146.00 | 10% | \$132.39 |
| EW NBD AHR H31335 | 97004-H31335 | \$ 83.00 | 10% | \$75.26 |
| EW NBD AHR H31337 | 97004-H31337 | \$ 6,362.00 | 10% | \$5,768.74 |
| EW NBD AHR H31338 | 97004-H31338 | \$ 6,362.00 | 10% | \$5,768.74 |
| EW NBD AHR H31339 | 97004-H31339 | \$ 1,036.00 | 10% | \$939.39 |
| EW NBD AHR H31340 | 97004-H31340 | \$ 2,210.00 | 10% | \$2,003.92 |
| EW NBD AHR H31341 | 97004-H31341 | \$ 3,275.00 | 10% | \$2,969.61 |
| EW NBD AHR H31342 | 97004-H31342 | \$ 1,030.00 | 10% | \$933.95 |
| EW NBD AHR H31343 | 97004-H31343 | \$ 1,524.00 | 10% | \$1,381.89 |
| EW NBD AHR H31344 | 97004-H31344 | \$ 1,524.00 | 10% | \$1,381.89 |
| EW NBD AHR H31345 | 97004-H31345 | \$ 1,524.00 | 10% | \$1,381.89 |
| EW NBD AHR H31346 | 97004-H31346 | \$ 1,524.00 | 10% | \$1,381.89 |
| EW NBD AHR H31348 | 97004-H31348 | \$ 118.00 | 10% | \$107.00 |
| EW NBD AHR H31349 | 97004-H31349 | \$ 118.00 | 10% | \$107.00 |
| EW NBD AHR H31350 | 97004-H31350 | \$ 190.00 | 10% | \$172.28 |
| EW NBD AHR H31351 | 97004-H31351 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H31352 | 97004-H31352 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H31353 | 97004-H31353 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H31354 | 97004-H31354 | \$ 61.00 | 10% | \$55.31 |
| EW NBD AHR H31355 | 97004-H31355 | \$ 122.00 | 10% | \$110.62 |
| EW NBD AHR H31356 | 97004-H31356 | \$ 122.00 | 10% | \$110.62 |
| EW NBD AHR H31357 | 97004-H31357 | \$ 122.00 | 10% | \$110.62 |
| EW NBD AHR H31358 | 97004-H31358 | \$ 46.00 | 10% | \$41.71 |
| EW NBD AHR H31359 | 97004-H31359 | \$ 48.00 | 10% | \$43.52 |
| EW NBD AHR H31360 | 97004-H31360 | \$ 43.00 | 10% | \$38.99 |
| EW NBD AHR H31361 | 97004-H31361 | \$ 2,083.00 | 10% | \$1,888.76 |
| EW NBD AHR H31362 | 97004-H31362 | \$ 15,083.00 | 10% | \$13,676.51 |
| EW NBD AHR H31363 | 97004-H31363 | \$ 15,083.00 | 10% | \$13,676.51 |
| EW NBD AHR H31364 | 97004-H31364 | \$ 5,271.00 | 10% | \$4,779.48 |
| EW NBD AHR H31365 | 97004-H31365 | \$ 5,271.00 | 10% | \$4,779.48 |
| EW NBD AHR H31366 | 97004-H31366 | \$ 7,314.00 | 10% | \$6,631.97 |
| EW NBD AHR H31367 | 97004-H31367 | \$ 7,314.00 | 10% | \$6,631.97 |
| EW NBD AHR H31369 | 97004-H31369 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H31370 | 97004-H31370 | \$ 71.00 | 10% | \$64.38 |
| EW NBD AHR H31393 | 97004-H31393 | \$ 43.00 | 10% | \$38.99 |
| EW NBD AHR H32010 | 97004-H32010 | \$ 215.00 | 10% | \$194.95 |
| EW NBD AHR H32011 | 97004-H32011 | \$ 215.00 | 10% | \$194.95 |
| EW NBD AHR H32012 | 97004-H32012 | \$ 1,807.00 | 10% | \$1,638.50 |

| | | | | |
|-------------------|--------------|--------------|-----|--------------------|
| EW NBD AHR H32013 | 97004-H32013 | \$ 1,807.00 | 10% | <i>\$1,638.50</i> |
| EW NBD AHR H32014 | 97004-H32014 | \$ 1,807.00 | 10% | <i>\$1,638.50</i> |
| EW NBD AHR H32015 | 97004-H32015 | \$ 1,807.00 | 10% | <i>\$1,638.50</i> |
| EW NBD AHR H32016 | 97004-H32016 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW NBD AHR H32017 | 97004-H32017 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW NBD AHR H32018 | 97004-H32018 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW NBD AHR H32019 | 97004-H32019 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW NBD AHR H32020 | 97004-H32020 | \$ 15,819.00 | 10% | <i>\$14,343.88</i> |
| EW NBD AHR H32021 | 97004-H32021 | \$ 15,819.00 | 10% | <i>\$14,343.88</i> |
| EW NBD AHR H32022 | 97004-H32022 | \$ 15,819.00 | 10% | <i>\$14,343.88</i> |
| EW NBD AHR H32023 | 97004-H32023 | \$ 15,819.00 | 10% | <i>\$14,343.88</i> |
| EW NBD AHR H32028 | 97004-H32028 | \$ 30,511.00 | 10% | <i>\$27,665.85</i> |
| EW NBD AHR H32029 | 97004-H32029 | \$ 30,511.00 | 10% | <i>\$27,665.85</i> |
| EW NBD AHR H32030 | 97004-H32030 | \$ 31,998.00 | 10% | <i>\$29,014.19</i> |
| EW NBD AHR H32031 | 97004-H32031 | \$ 31,998.00 | 10% | <i>\$29,014.19</i> |
| EW NBD AHR H32032 | 97004-H32032 | \$ 31,998.00 | 10% | <i>\$29,014.19</i> |
| EW NBD AHR H32033 | 97004-H32033 | \$ 31,998.00 | 10% | <i>\$29,014.19</i> |
| EW NBD AHR H32038 | 97004-H32038 | \$ 5,528.00 | 10% | <i>\$5,012.51</i> |
| EW NBD AHR H32039 | 97004-H32039 | \$ 5,528.00 | 10% | <i>\$5,012.51</i> |
| EW NBD AHR H32040 | 97004-H32040 | \$ 5,528.00 | 10% | <i>\$5,012.51</i> |
| EW NBD AHR H32041 | 97004-H32041 | \$ 5,528.00 | 10% | <i>\$5,012.51</i> |
| EW NBD AHR H32046 | 97004-H32046 | \$ 7,671.00 | 10% | <i>\$6,955.68</i> |
| EW NBD AHR H32047 | 97004-H32047 | \$ 7,671.00 | 10% | <i>\$6,955.68</i> |
| EW NBD AHR H32048 | 97004-H32048 | \$ 7,671.00 | 10% | <i>\$6,955.68</i> |
| EW NBD AHR H32049 | 97004-H32049 | \$ 7,671.00 | 10% | <i>\$6,955.68</i> |
| EW NBD AHR H32054 | 97004-H32054 | \$ 5,528.00 | 10% | <i>\$5,012.51</i> |
| EW NBD AHR H32055 | 97004-H32055 | \$ 7,671.00 | 10% | <i>\$6,955.68</i> |
| EW NBD AHR H32056 | 97004-H32056 | \$ 1,721.00 | 10% | <i>\$1,560.52</i> |
| EW NBD AHR H32057 | 97004-H32057 | \$ 1,721.00 | 10% | <i>\$1,560.52</i> |
| EW NBD AHR H32058 | 97004-H32058 | \$ 1,721.00 | 10% | <i>\$1,560.52</i> |
| EW NBD AHR H32059 | 97004-H32059 | \$ 1,721.00 | 10% | <i>\$1,560.52</i> |
| EW NBD AHR H32060 | 97004-H32060 | \$ 2,141.00 | 10% | <i>\$1,941.35</i> |
| EW NBD AHR H32061 | 97004-H32061 | \$ 2,248.00 | 10% | <i>\$2,038.37</i> |
| EW NBD AHR H32062 | 97004-H32062 | \$ 2,162.00 | 10% | <i>\$1,960.39</i> |
| EW NBD AHR H32063 | 97004-H32063 | \$ 2,144.00 | 10% | <i>\$1,944.07</i> |
| EW NBD AHR H32064 | 97004-H32064 | \$ 2,162.00 | 10% | <i>\$1,960.39</i> |
| EW NBD AHR H32065 | 97004-H32065 | \$ 2,443.00 | 10% | <i>\$2,215.19</i> |
| EW NBD AHR H32066 | 97004-H32066 | \$ 2,443.00 | 10% | <i>\$2,215.19</i> |
| EW NBD AHR H32067 | 97004-H32067 | \$ 2,443.00 | 10% | <i>\$2,215.19</i> |
| EW NBD AHR H32068 | 97004-H32068 | \$ 2,443.00 | 10% | <i>\$2,215.19</i> |
| EW NBD AHR H32069 | 97004-H32069 | \$ 3,035.00 | 10% | <i>\$2,751.99</i> |
| EW NBD AHR H32070 | 97004-H32070 | \$ 3,035.00 | 10% | <i>\$2,751.99</i> |

| | | | | |
|-------------------|--------------|--------------|-----|-------------|
| EW NBD AHR H32071 | 97004-H32071 | \$ 3,035.00 | 10% | \$2,751.99 |
| EW NBD AHR H32072 | 97004-H32072 | \$ 3,035.00 | 10% | \$2,751.99 |
| EW NBD AHR H32073 | 97004-H32073 | \$ 22,474.00 | 10% | \$20,378.30 |
| EW NBD AHR H32074 | 97004-H32074 | \$ 22,474.00 | 10% | \$20,378.30 |
| EW NBD AHR H32075 | 97004-H32075 | \$ 30,543.00 | 10% | \$27,694.87 |
| EW NBD AHR H32076 | 97004-H32076 | \$ 30,543.00 | 10% | \$27,694.87 |
| EW NBD AHR H32101 | 97004-H32101 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32102 | 97004-H32102 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32103 | 97004-H32103 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32104 | 97004-H32104 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32105 | 97004-H32105 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32106 | 97004-H32106 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32107 | 97004-H32107 | \$ 5,361.00 | 10% | \$4,861.09 |
| EW NBD AHR H32108 | 97004-H32108 | \$ 5,361.00 | 10% | \$4,861.09 |
| EW NBD AHR H32109 | 97004-H32109 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32110 | 97004-H32110 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32111 | 97004-H32111 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32112 | 97004-H32112 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32113 | 97004-H32113 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32114 | 97004-H32114 | \$ 995.00 | 10% | \$902.22 |
| EW NBD AHR H32115 | 97004-H32115 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32116 | 97004-H32116 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32117 | 97004-H32117 | \$ 929.00 | 10% | \$842.37 |
| EW NBD AHR H32118 | 97004-H32118 | \$ 929.00 | 10% | \$842.37 |
| EW NBD AHR H32119 | 97004-H32119 | \$ 929.00 | 10% | \$842.37 |
| EW NBD AHR H32120 | 97004-H32120 | \$ 929.00 | 10% | \$842.37 |
| EW NBD AHR H32121 | 97004-H32121 | \$ 5,361.00 | 10% | \$4,861.09 |
| EW NBD AHR H32122 | 97004-H32122 | \$ 5,361.00 | 10% | \$4,861.09 |
| EW NBD AHR H32123 | 97004-H32123 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32124 | 97004-H32124 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW NBD AHR H32125 | 97004-H32125 | \$ 1,957.00 | 10% | \$1,774.51 |
| EW NBD AHR H32126 | 97004-H32126 | \$ 1,957.00 | 10% | \$1,774.51 |
| EW NBD AHR H32127 | 97004-H32127 | \$ 2,301.00 | 10% | \$2,086.43 |
| EW NBD AHR H32128 | 97004-H32128 | \$ 2,301.00 | 10% | \$2,086.43 |
| EW NBD AHR H32129 | 97004-H32129 | \$ 2,301.00 | 10% | \$2,086.43 |
| EW NBD AHR H32130 | 97004-H32130 | \$ 2,301.00 | 10% | \$2,086.43 |
| EW NBD AHR H32131 | 97004-H32131 | \$ 2,301.00 | 10% | \$2,086.43 |
| EW NBD AHR H32132 | 97004-H32132 | \$ 2,301.00 | 10% | \$2,086.43 |
| EW NBD AHR H32133 | 97004-H32133 | \$ 1,957.00 | 10% | \$1,774.51 |
| EW NBD AHR H32134 | 97004-H32134 | \$ 1,957.00 | 10% | \$1,774.51 |
| EW NBD AHR H32135 | 97004-H32135 | \$ 1,957.00 | 10% | \$1,774.51 |
| EW NBD AHR H32136 | 97004-H32136 | \$ 1,957.00 | 10% | \$1,774.51 |

| | | | | |
|-------------------|--------------|--------------|-----|--------------------|
| EW NBD AHR H32137 | 97004-H32137 | \$ 1,957.00 | 10% | <i>\$1,774.51</i> |
| EW NBD AHR H32138 | 97004-H32138 | \$ 1,957.00 | 10% | <i>\$1,774.51</i> |
| EW NBD AHR H32139 | 97004-H32139 | \$ 8,287.00 | 10% | <i>\$7,514.24</i> |
| EW NBD AHR H32140 | 97004-H32140 | \$ 8,287.00 | 10% | <i>\$7,514.24</i> |
| EW NBD AHR H32141 | 97004-H32141 | \$ 9,562.00 | 10% | <i>\$8,670.34</i> |
| EW NBD AHR H32142 | 97004-H32142 | \$ 9,562.00 | 10% | <i>\$8,670.34</i> |
| EW NBD AHR H32143 | 97004-H32143 | \$ 275.00 | 10% | <i>\$249.36</i> |
| EW NBD AHR H32144 | 97004-H32144 | \$ 288.00 | 10% | <i>\$261.14</i> |
| EW NBD AHR H32146 | 97004-H32146 | \$ 848.00 | 10% | <i>\$768.92</i> |
| EW NBD AHR H32147 | 97004-H32147 | \$ 848.00 | 10% | <i>\$768.92</i> |
| EW NBD AHR H32148 | 97004-H32148 | \$ 1,739.00 | 10% | <i>\$1,576.84</i> |
| EW NBD AHR H32149 | 97004-H32149 | \$ 1,739.00 | 10% | <i>\$1,576.84</i> |
| EW NBD AHR H32150 | 97004-H32150 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW NBD AHR H32151 | 97004-H32151 | \$ 296.00 | 10% | <i>\$268.40</i> |
| EW NBD AHR H32152 | 97004-H32152 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW NBD AHR H32169 | 97004-H32169 | \$ 1,005.00 | 10% | <i>\$911.28</i> |
| EW NBD AHR H32170 | 97004-H32170 | \$ 1,005.00 | 10% | <i>\$911.28</i> |
| EW NBD AHR H32171 | 97004-H32171 | \$ 941.00 | 10% | <i>\$853.25</i> |
| EW NBD AHR H32172 | 97004-H32172 | \$ 941.00 | 10% | <i>\$853.25</i> |
| EW NBD AHR H32173 | 97004-H32173 | \$ 2,503.00 | 10% | <i>\$2,269.60</i> |
| EW NBD AHR H32174 | 97004-H32174 | \$ 2,503.00 | 10% | <i>\$2,269.60</i> |
| EW NBD AHR H32175 | 97004-H32175 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW NBD AHR H32176 | 97004-H32176 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW NBD AHR H32177 | 97004-H32177 | \$ 9,767.00 | 10% | <i>\$8,856.23</i> |
| EW NBD AHR H32178 | 97004-H32178 | \$ 11,272.00 | 10% | <i>\$10,220.89</i> |
| EW NBD AHR H34008 | 97004-H34008 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW NBD AHR H34009 | 97004-H34009 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD AHR H34010 | 97004-H34010 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW NBD AHR H34011 | 97004-H34011 | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD AHR H34012 | 97004-H34012 | \$ 138.00 | 10% | <i>\$125.13</i> |
| EW NBD AHR H34013 | 97004-H34013 | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD AHR H34014 | 97004-H34014 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD AHR H34015 | 97004-H34015 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW NBD AHR H34016 | 97004-H34016 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW NBD AHR H34017 | 97004-H34017 | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW NBD AHR H34018 | 97004-H34018 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR H34019 | 97004-H34019 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR H34020 | 97004-H34020 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR H34021 | 97004-H34021 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD AHR H34028 | 97004-H34028 | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW NBD AHR H34030 | 97004-H34030 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW NBD AHR H34031 | 97004-H34031 | \$ 108.00 | 10% | <i>\$97.93</i> |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW NBD AHR H34048 | 97004-H34048 | \$ 228.00 | 10% | \$206.74 |
| EW NBD AHR H34049 | 97004-H34049 | \$ 228.00 | 10% | \$206.74 |
| EW NBD AHR H34050 | 97004-H34050 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34051 | 97004-H34051 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34052 | 97004-H34052 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34053 | 97004-H34053 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34054 | 97004-H34054 | \$ 198.00 | 10% | \$179.54 |
| EW NBD AHR H34055 | 97004-H34055 | \$ 198.00 | 10% | \$179.54 |
| EW NBD AHR H34056 | 97004-H34056 | \$ 287.00 | 10% | \$260.24 |
| EW NBD AHR H34057 | 97004-H34057 | \$ 287.00 | 10% | \$260.24 |
| EW NBD AHR H34058 | 97004-H34058 | \$ 251.00 | 10% | \$227.59 |
| EW NBD AHR H34059 | 97004-H34059 | \$ 251.00 | 10% | \$227.59 |
| EW NBD AHR H34062 | 97004-H34062 | \$ 287.00 | 10% | \$260.24 |
| EW NBD AHR H34063 | 97004-H34063 | \$ 287.00 | 10% | \$260.24 |
| EW NBD AHR H34064 | 97004-H34064 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR H34065 | 97004-H34065 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR H34066 | 97004-H34066 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR H34067 | 97004-H34067 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR H34068 | 97004-H34068 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR H34069 | 97004-H34069 | \$ 183.00 | 10% | \$165.94 |
| EW NBD AHR H34070 | 97004-H34070 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR H34071 | 97004-H34071 | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR H34072 | 97004-H34072 | \$ 1,890.00 | 10% | \$1,713.76 |
| EW NBD AHR H34073 | 97004-H34073 | \$ 1,854.00 | 10% | \$1,681.11 |
| EW NBD AHR H34074 | 97004-H34074 | \$ 2,360.00 | 10% | \$2,139.93 |
| EW NBD AHR H34075 | 97004-H34075 | \$ 2,263.00 | 10% | \$2,051.98 |
| EW NBD AHR H34076 | 97004-H34076 | \$ 1,890.00 | 10% | \$1,713.76 |
| EW NBD AHR H34077 | 97004-H34077 | \$ 1,854.00 | 10% | \$1,681.11 |
| EW NBD AHR H34078 | 97004-H34078 | \$ 1,890.00 | 10% | \$1,713.76 |
| EW NBD AHR H34079 | 97004-H34079 | \$ 1,854.00 | 10% | \$1,681.11 |
| EW NBD AHR H34080 | 97004-H34080 | \$ 2,360.00 | 10% | \$2,139.93 |
| EW NBD AHR H34081 | 97004-H34081 | \$ 2,263.00 | 10% | \$2,051.98 |
| EW NBD AHR H34082 | 97004-H34082 | \$ 2,264.00 | 10% | \$2,052.88 |
| EW NBD AHR H34083 | 97004-H34083 | \$ 2,170.00 | 10% | \$1,967.65 |
| EW NBD AHR H34084 | 97004-H34084 | \$ 1,515.00 | 10% | \$1,373.73 |
| EW NBD AHR H34085 | 97004-H34085 | \$ 1,515.00 | 10% | \$1,373.73 |
| EW NBD AHR H34086 | 97004-H34086 | \$ 1,764.00 | 10% | \$1,599.51 |
| EW NBD AHR H34087 | 97004-H34087 | \$ 1,693.00 | 10% | \$1,535.13 |
| EW NBD AHR H34088 | 97004-H34088 | \$ 4,061.00 | 10% | \$3,682.31 |
| EW NBD AHR H34089 | 97004-H34089 | \$ 4,061.00 | 10% | \$3,682.31 |
| EW NBD AHR H34090 | 97004-H34090 | \$ 4,676.00 | 10% | \$4,239.96 |
| EW NBD AHR H34091 | 97004-H34091 | \$ 2,643.00 | 10% | \$2,396.54 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW NBD AHR H34092 | 97004-H34092 | \$ 2,643.00 | 10% | \$2,396.54 |
| EW NBD AHR H34093 | 97004-H34093 | \$ 2,643.00 | 10% | \$2,396.54 |
| EW NBD AHR H34094 | 97004-H34094 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34095 | 97004-H34095 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34096 | 97004-H34096 | \$ 346.00 | 10% | \$313.74 |
| EW NBD AHR H34097 | 97004-H34097 | \$ 346.00 | 10% | \$313.74 |
| EW NBD AHR H34098 | 97004-H34098 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34099 | 97004-H34099 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34100 | 97004-H34100 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34101 | 97004-H34101 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34102 | 97004-H34102 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34103 | 97004-H34103 | \$ 304.00 | 10% | \$275.65 |
| EW NBD AHR H34104 | 97004-H34104 | \$ 132.00 | 10% | \$119.69 |
| EW NBD AHR H34105 | 97004-H34105 | \$ 132.00 | 10% | \$119.69 |
| EW NBD AHR H34106 | 97004-H34106 | \$ 132.00 | 10% | \$119.69 |
| EW NBD AHR H34107 | 97004-H34107 | \$ 132.00 | 10% | \$119.69 |
| EW NBD AHR H34108 | 97004-H34108 | \$ 132.00 | 10% | \$119.69 |
| EW NBD AHR H34109 | 97004-H34109 | \$ 132.00 | 10% | \$119.69 |
| EW NBD AHR H34110 | 97004-H34110 | \$ 2,547.00 | 10% | \$2,309.49 |
| EW NBD AHR H34111 | 97004-H34111 | \$ 2,547.00 | 10% | \$2,309.49 |
| EW NBD AHR H34112 | 97004-H34112 | \$ 2,547.00 | 10% | \$2,309.49 |
| EW NBD AHR H34113 | 97004-H34113 | \$ 3,711.00 | 10% | \$3,364.95 |
| EW NBD AHR H34114 | 97004-H34114 | \$ 3,345.00 | 10% | \$3,033.08 |
| EW NBD AHR H34115 | 97004-H34115 | \$ 3,345.00 | 10% | \$3,033.08 |
| EW NBD AHR H34116 | 97004-H34116 | \$ 3,345.00 | 10% | \$3,033.08 |
| EW NBD AHR H34117 | 97004-H34117 | \$ 3,345.00 | 10% | \$3,033.08 |
| EW NBD AHR H34118 | 97004-H34118 | \$ 842.00 | 10% | \$763.48 |
| EW NBD AHR H34119 | 97004-H34119 | \$ 842.00 | 10% | \$763.48 |
| EW NBD AHR H34120 | 97004-H34120 | \$ 583.00 | 10% | \$528.64 |
| EW NBD AHR H34121 | 97004-H34121 | \$ 583.00 | 10% | \$528.64 |
| EW NBD AHR H34122 | 97004-H34122 | \$ 606.00 | 10% | \$549.49 |
| EW NBD AHR H34123 | 97004-H34123 | \$ 606.00 | 10% | \$549.49 |
| EW NBD AHR H34124 | 97004-H34124 | \$ 906.00 | 10% | \$821.52 |
| EW NBD AHR H34125 | 97004-H34125 | \$ 906.00 | 10% | \$821.52 |
| EW NBD AHR H34126 | 97004-H34126 | \$ 906.00 | 10% | \$821.52 |
| EW NBD AHR H34127 | 97004-H34127 | \$ 906.00 | 10% | \$821.52 |
| EW NBD AHR H34128 | 97004-H34128 | \$ 138.00 | 10% | \$125.13 |
| EW NBD AHR H34129 | 97004-H34129 | \$ 247.00 | 10% | \$223.97 |
| EW NBD AHR H34130 | 97004-H34130 | \$ 255.00 | 10% | \$231.22 |
| EW NBD AHR H34131 | 97004-H34131 | \$ 254.00 | 10% | \$230.31 |
| EW NBD AHR H34132 | 97004-H34132 | \$ 255.00 | 10% | \$231.22 |
| EW NBD AHR H34168 | 97004-H34168 | \$ 219.00 | 10% | \$198.58 |

| | | | | |
|-------------------|--------------|-----------|-----|----------|
| EW NBD AHR H34172 | 97004-H34172 | \$ 584.00 | 10% | \$529.54 |
| EW NBD AHR H34174 | 97004-H34174 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34175 | 97004-H34175 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34176 | 97004-H34176 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34177 | 97004-H34177 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34178 | 97004-H34178 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34179 | 97004-H34179 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34180 | 97004-H34180 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34181 | 97004-H34181 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34182 | 97004-H34182 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34183 | 97004-H34183 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34184 | 97004-H34184 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34185 | 97004-H34185 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34186 | 97004-H34186 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34187 | 97004-H34187 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34188 | 97004-H34188 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34189 | 97004-H34189 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34190 | 97004-H34190 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34191 | 97004-H34191 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34192 | 97004-H34192 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34193 | 97004-H34193 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34194 | 97004-H34194 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34195 | 97004-H34195 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34196 | 97004-H34196 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34197 | 97004-H34197 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34198 | 97004-H34198 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34199 | 97004-H34199 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34200 | 97004-H34200 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34201 | 97004-H34201 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34202 | 97004-H34202 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34203 | 97004-H34203 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34204 | 97004-H34204 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34205 | 97004-H34205 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34206 | 97004-H34206 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34207 | 97004-H34207 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34208 | 97004-H34208 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34209 | 97004-H34209 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34210 | 97004-H34210 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34211 | 97004-H34211 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34212 | 97004-H34212 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34213 | 97004-H34213 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34214 | 97004-H34214 | \$ 35.00 | 10% | \$31.74 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34215 | 97004-H34215 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34216 | 97004-H34216 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34217 | 97004-H34217 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34218 | 97004-H34218 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34219 | 97004-H34219 | \$ 35.00 | 10% | \$31.74 |
| EW NBD AHR H34220 | 97004-H34220 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34221 | 97004-H34221 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34222 | 97004-H34222 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34223 | 97004-H34223 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34224 | 97004-H34224 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34225 | 97004-H34225 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34226 | 97004-H34226 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34227 | 97004-H34227 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34228 | 97004-H34228 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34229 | 97004-H34229 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34230 | 97004-H34230 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34231 | 97004-H34231 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34232 | 97004-H34232 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34233 | 97004-H34233 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34234 | 97004-H34234 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34235 | 97004-H34235 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34236 | 97004-H34236 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34237 | 97004-H34237 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34238 | 97004-H34238 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34239 | 97004-H34239 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34240 | 97004-H34240 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34241 | 97004-H34241 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34242 | 97004-H34242 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34243 | 97004-H34243 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34244 | 97004-H34244 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34245 | 97004-H34245 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34246 | 97004-H34246 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34247 | 97004-H34247 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34248 | 97004-H34248 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34249 | 97004-H34249 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34250 | 97004-H34250 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34251 | 97004-H34251 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34252 | 97004-H34252 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34253 | 97004-H34253 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34254 | 97004-H34254 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34255 | 97004-H34255 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34256 | 97004-H34256 | \$ 51.00 | 10% | \$46.24 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34257 | 97004-H34257 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34258 | 97004-H34258 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34259 | 97004-H34259 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34260 | 97004-H34260 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34261 | 97004-H34261 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34262 | 97004-H34262 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34263 | 97004-H34263 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34264 | 97004-H34264 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34265 | 97004-H34265 | \$ 51.00 | 10% | \$46.24 |
| EW NBD AHR H34266 | 97004-H34266 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34267 | 97004-H34267 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34268 | 97004-H34268 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34269 | 97004-H34269 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34270 | 97004-H34270 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34271 | 97004-H34271 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34272 | 97004-H34272 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34273 | 97004-H34273 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34274 | 97004-H34274 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34275 | 97004-H34275 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34276 | 97004-H34276 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34277 | 97004-H34277 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34278 | 97004-H34278 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34279 | 97004-H34279 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34280 | 97004-H34280 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34281 | 97004-H34281 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34282 | 97004-H34282 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34283 | 97004-H34283 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34284 | 97004-H34284 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34285 | 97004-H34285 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34286 | 97004-H34286 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34287 | 97004-H34287 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34288 | 97004-H34288 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34289 | 97004-H34289 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34290 | 97004-H34290 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34291 | 97004-H34291 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34292 | 97004-H34292 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34293 | 97004-H34293 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34294 | 97004-H34294 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34295 | 97004-H34295 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34296 | 97004-H34296 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34297 | 97004-H34297 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34298 | 97004-H34298 | \$ 37.00 | 10% | \$33.55 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34299 | 97004-H34299 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34300 | 97004-H34300 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34301 | 97004-H34301 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34302 | 97004-H34302 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34303 | 97004-H34303 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34304 | 97004-H34304 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34305 | 97004-H34305 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H34306 | 97004-H34306 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34307 | 97004-H34307 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34308 | 97004-H34308 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34309 | 97004-H34309 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34310 | 97004-H34310 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34311 | 97004-H34311 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34312 | 97004-H34312 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34313 | 97004-H34313 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34314 | 97004-H34314 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34315 | 97004-H34315 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34316 | 97004-H34316 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34317 | 97004-H34317 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34318 | 97004-H34318 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34319 | 97004-H34319 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34320 | 97004-H34320 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34321 | 97004-H34321 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34322 | 97004-H34322 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34323 | 97004-H34323 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34324 | 97004-H34324 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34325 | 97004-H34325 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34326 | 97004-H34326 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34327 | 97004-H34327 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34328 | 97004-H34328 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34329 | 97004-H34329 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34330 | 97004-H34330 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34331 | 97004-H34331 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34332 | 97004-H34332 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34333 | 97004-H34333 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34334 | 97004-H34334 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34335 | 97004-H34335 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34336 | 97004-H34336 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34337 | 97004-H34337 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34338 | 97004-H34338 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34339 | 97004-H34339 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34340 | 97004-H34340 | \$ 59.00 | 10% | \$53.50 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34341 | 97004-H34341 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34342 | 97004-H34342 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34343 | 97004-H34343 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34344 | 97004-H34344 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34345 | 97004-H34345 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34346 | 97004-H34346 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34347 | 97004-H34347 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34348 | 97004-H34348 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34349 | 97004-H34349 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34350 | 97004-H34350 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34351 | 97004-H34351 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34352 | 97004-H34352 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34353 | 97004-H34353 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34354 | 97004-H34354 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34355 | 97004-H34355 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34356 | 97004-H34356 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34357 | 97004-H34357 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34358 | 97004-H34358 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34359 | 97004-H34359 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34360 | 97004-H34360 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34361 | 97004-H34361 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34362 | 97004-H34362 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34363 | 97004-H34363 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34364 | 97004-H34364 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34365 | 97004-H34365 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34366 | 97004-H34366 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34367 | 97004-H34367 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34368 | 97004-H34368 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34369 | 97004-H34369 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34370 | 97004-H34370 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34371 | 97004-H34371 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34372 | 97004-H34372 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34373 | 97004-H34373 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34374 | 97004-H34374 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34375 | 97004-H34375 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34376 | 97004-H34376 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34377 | 97004-H34377 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34378 | 97004-H34378 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34379 | 97004-H34379 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34380 | 97004-H34380 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34381 | 97004-H34381 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34382 | 97004-H34382 | \$ 88.00 | 10% | \$79.79 |

| | | | | |
|-------------------|--------------|-----------|-----|----------|
| EW NBD AHR H34383 | 97004-H34383 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34384 | 97004-H34384 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34385 | 97004-H34385 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34386 | 97004-H34386 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34387 | 97004-H34387 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34388 | 97004-H34388 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34389 | 97004-H34389 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34390 | 97004-H34390 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34391 | 97004-H34391 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34392 | 97004-H34392 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34393 | 97004-H34393 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34394 | 97004-H34394 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34395 | 97004-H34395 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34396 | 97004-H34396 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34397 | 97004-H34397 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34398 | 97004-H34398 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34399 | 97004-H34399 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34400 | 97004-H34400 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34401 | 97004-H34401 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34402 | 97004-H34402 | \$ 88.00 | 10% | \$79.79 |
| EW NBD AHR H34403 | 97004-H34403 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34404 | 97004-H34404 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34405 | 97004-H34405 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34406 | 97004-H34406 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34407 | 97004-H34407 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34408 | 97004-H34408 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34409 | 97004-H34409 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34410 | 97004-H34410 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34411 | 97004-H34411 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34412 | 97004-H34412 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34413 | 97004-H34413 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34414 | 97004-H34414 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34415 | 97004-H34415 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34416 | 97004-H34416 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34417 | 97004-H34417 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34418 | 97004-H34418 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34419 | 97004-H34419 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34420 | 97004-H34420 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34421 | 97004-H34421 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34422 | 97004-H34422 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34423 | 97004-H34423 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34424 | 97004-H34424 | \$ 141.00 | 10% | \$127.85 |

| | | | | |
|-------------------|--------------|-----------|-----|----------|
| EW NBD AHR H34425 | 97004-H34425 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34426 | 97004-H34426 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34427 | 97004-H34427 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34428 | 97004-H34428 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34429 | 97004-H34429 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34430 | 97004-H34430 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34431 | 97004-H34431 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34432 | 97004-H34432 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34433 | 97004-H34433 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34434 | 97004-H34434 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34435 | 97004-H34435 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34436 | 97004-H34436 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34437 | 97004-H34437 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34438 | 97004-H34438 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34439 | 97004-H34439 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34440 | 97004-H34440 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34441 | 97004-H34441 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34442 | 97004-H34442 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34443 | 97004-H34443 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34444 | 97004-H34444 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34445 | 97004-H34445 | \$ 141.00 | 10% | \$127.85 |
| EW NBD AHR H34446 | 97004-H34446 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34447 | 97004-H34447 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34448 | 97004-H34448 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34449 | 97004-H34449 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34450 | 97004-H34450 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34451 | 97004-H34451 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34452 | 97004-H34452 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34453 | 97004-H34453 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34454 | 97004-H34454 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34455 | 97004-H34455 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34456 | 97004-H34456 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34457 | 97004-H34457 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34458 | 97004-H34458 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34459 | 97004-H34459 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34460 | 97004-H34460 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34461 | 97004-H34461 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34462 | 97004-H34462 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34463 | 97004-H34463 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34464 | 97004-H34464 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34465 | 97004-H34465 | \$ 164.00 | 10% | \$148.71 |
| EW NBD AHR H34466 | 97004-H34466 | \$ 164.00 | 10% | \$148.71 |

| | | | | |
|-------------------|--------------|-----------|-----|-----------------|
| EW NBD AHR H34467 | 97004-H34467 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34468 | 97004-H34468 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34469 | 97004-H34469 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34470 | 97004-H34470 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34471 | 97004-H34471 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34472 | 97004-H34472 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34473 | 97004-H34473 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34474 | 97004-H34474 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34475 | 97004-H34475 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34476 | 97004-H34476 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34477 | 97004-H34477 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34478 | 97004-H34478 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34479 | 97004-H34479 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34480 | 97004-H34480 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34481 | 97004-H34481 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34482 | 97004-H34482 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34483 | 97004-H34483 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34484 | 97004-H34484 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34485 | 97004-H34485 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34486 | 97004-H34486 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34487 | 97004-H34487 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34488 | 97004-H34488 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34489 | 97004-H34489 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW NBD AHR H34490 | 97004-H34490 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34491 | 97004-H34491 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34492 | 97004-H34492 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34493 | 97004-H34493 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34494 | 97004-H34494 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34495 | 97004-H34495 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34496 | 97004-H34496 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34497 | 97004-H34497 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34498 | 97004-H34498 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34499 | 97004-H34499 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34500 | 97004-H34500 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34501 | 97004-H34501 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34502 | 97004-H34502 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34503 | 97004-H34503 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34504 | 97004-H34504 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34505 | 97004-H34505 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34506 | 97004-H34506 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34507 | 97004-H34507 | \$ 24.00 | 10% | <i>\$21.76</i> |
| EW NBD AHR H34508 | 97004-H34508 | \$ 24.00 | 10% | <i>\$21.76</i> |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34509 | 97004-H34509 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34510 | 97004-H34510 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34511 | 97004-H34511 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34512 | 97004-H34512 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34513 | 97004-H34513 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34514 | 97004-H34514 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34515 | 97004-H34515 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34516 | 97004-H34516 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34517 | 97004-H34517 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34518 | 97004-H34518 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34519 | 97004-H34519 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34520 | 97004-H34520 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34521 | 97004-H34521 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34522 | 97004-H34522 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34523 | 97004-H34523 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34524 | 97004-H34524 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34525 | 97004-H34525 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34526 | 97004-H34526 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34527 | 97004-H34527 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34528 | 97004-H34528 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34529 | 97004-H34529 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34530 | 97004-H34530 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34531 | 97004-H34531 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34532 | 97004-H34532 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34533 | 97004-H34533 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34534 | 97004-H34534 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34535 | 97004-H34535 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34536 | 97004-H34536 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34537 | 97004-H34537 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34538 | 97004-H34538 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34539 | 97004-H34539 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34540 | 97004-H34540 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34541 | 97004-H34541 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34542 | 97004-H34542 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34543 | 97004-H34543 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34544 | 97004-H34544 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34545 | 97004-H34545 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34546 | 97004-H34546 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34547 | 97004-H34547 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34548 | 97004-H34548 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34549 | 97004-H34549 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34550 | 97004-H34550 | \$ 24.00 | 10% | \$21.76 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34551 | 97004-H34551 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34552 | 97004-H34552 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34553 | 97004-H34553 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34554 | 97004-H34554 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34555 | 97004-H34555 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34556 | 97004-H34556 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34557 | 97004-H34557 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34558 | 97004-H34558 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34559 | 97004-H34559 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34560 | 97004-H34560 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34561 | 97004-H34561 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34562 | 97004-H34562 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34563 | 97004-H34563 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34564 | 97004-H34564 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34565 | 97004-H34565 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34566 | 97004-H34566 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34567 | 97004-H34567 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34568 | 97004-H34568 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34569 | 97004-H34569 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34570 | 97004-H34570 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34571 | 97004-H34571 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34572 | 97004-H34572 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34573 | 97004-H34573 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34574 | 97004-H34574 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34575 | 97004-H34575 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34576 | 97004-H34576 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34577 | 97004-H34577 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34578 | 97004-H34578 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34579 | 97004-H34579 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34580 | 97004-H34580 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34581 | 97004-H34581 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34582 | 97004-H34582 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34583 | 97004-H34583 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34584 | 97004-H34584 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34585 | 97004-H34585 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34586 | 97004-H34586 | \$ 24.00 | 10% | \$21.76 |
| EW NBD AHR H34587 | 97004-H34587 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34588 | 97004-H34588 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34589 | 97004-H34589 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34590 | 97004-H34590 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34591 | 97004-H34591 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34592 | 97004-H34592 | \$ 59.00 | 10% | \$53.50 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34593 | 97004-H34593 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34594 | 97004-H34594 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34595 | 97004-H34595 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34596 | 97004-H34596 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34597 | 97004-H34597 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34598 | 97004-H34598 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34599 | 97004-H34599 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34600 | 97004-H34600 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34601 | 97004-H34601 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34602 | 97004-H34602 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34603 | 97004-H34603 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34604 | 97004-H34604 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34605 | 97004-H34605 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34606 | 97004-H34606 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34607 | 97004-H34607 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34608 | 97004-H34608 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34609 | 97004-H34609 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34610 | 97004-H34610 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34611 | 97004-H34611 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34612 | 97004-H34612 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34613 | 97004-H34613 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34614 | 97004-H34614 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34615 | 97004-H34615 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34616 | 97004-H34616 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34617 | 97004-H34617 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34618 | 97004-H34618 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34619 | 97004-H34619 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34620 | 97004-H34620 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34621 | 97004-H34621 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34622 | 97004-H34622 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34623 | 97004-H34623 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34624 | 97004-H34624 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34625 | 97004-H34625 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34626 | 97004-H34626 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34627 | 97004-H34627 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34628 | 97004-H34628 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34629 | 97004-H34629 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34630 | 97004-H34630 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34631 | 97004-H34631 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H34632 | 97004-H34632 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34633 | 97004-H34633 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34634 | 97004-H34634 | \$ 65.00 | 10% | \$58.94 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34635 | 97004-H34635 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34636 | 97004-H34636 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34637 | 97004-H34637 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34638 | 97004-H34638 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34639 | 97004-H34639 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34640 | 97004-H34640 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34641 | 97004-H34641 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34642 | 97004-H34642 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34643 | 97004-H34643 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34644 | 97004-H34644 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34645 | 97004-H34645 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34646 | 97004-H34646 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34647 | 97004-H34647 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34648 | 97004-H34648 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34649 | 97004-H34649 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34650 | 97004-H34650 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34651 | 97004-H34651 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34652 | 97004-H34652 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34653 | 97004-H34653 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34654 | 97004-H34654 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34655 | 97004-H34655 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34656 | 97004-H34656 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34657 | 97004-H34657 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34658 | 97004-H34658 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34659 | 97004-H34659 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34660 | 97004-H34660 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34661 | 97004-H34661 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34662 | 97004-H34662 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34663 | 97004-H34663 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34664 | 97004-H34664 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34665 | 97004-H34665 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34666 | 97004-H34666 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34667 | 97004-H34667 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34668 | 97004-H34668 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34669 | 97004-H34669 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34670 | 97004-H34670 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34671 | 97004-H34671 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34672 | 97004-H34672 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34673 | 97004-H34673 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34674 | 97004-H34674 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34675 | 97004-H34675 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34676 | 97004-H34676 | \$ 65.00 | 10% | \$58.94 |

| | | | | |
|-------------------|--------------|----------|-----|---------|
| EW NBD AHR H34677 | 97004-H34677 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34678 | 97004-H34678 | \$ 65.00 | 10% | \$58.94 |
| EW NBD AHR H34679 | 97004-H34679 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34680 | 97004-H34680 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34681 | 97004-H34681 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34682 | 97004-H34682 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34683 | 97004-H34683 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34684 | 97004-H34684 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34685 | 97004-H34685 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34686 | 97004-H34686 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34687 | 97004-H34687 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34688 | 97004-H34688 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34689 | 97004-H34689 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34690 | 97004-H34690 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34691 | 97004-H34691 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34692 | 97004-H34692 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34693 | 97004-H34693 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34694 | 97004-H34694 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34695 | 97004-H34695 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34696 | 97004-H34696 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34697 | 97004-H34697 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34698 | 97004-H34698 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34699 | 97004-H34699 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34700 | 97004-H34700 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34701 | 97004-H34701 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34702 | 97004-H34702 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34703 | 97004-H34703 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34704 | 97004-H34704 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34705 | 97004-H34705 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34706 | 97004-H34706 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34707 | 97004-H34707 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34708 | 97004-H34708 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34709 | 97004-H34709 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34710 | 97004-H34710 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34711 | 97004-H34711 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34712 | 97004-H34712 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34713 | 97004-H34713 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34714 | 97004-H34714 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34715 | 97004-H34715 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34716 | 97004-H34716 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34717 | 97004-H34717 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34718 | 97004-H34718 | \$ 76.00 | 10% | \$68.91 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW NBD AHR H34719 | 97004-H34719 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34720 | 97004-H34720 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34721 | 97004-H34721 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34722 | 97004-H34722 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34723 | 97004-H34723 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34724 | 97004-H34724 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34725 | 97004-H34725 | \$ 76.00 | 10% | \$68.91 |
| EW NBD AHR H34726 | 97004-H34726 | \$ 1,968.00 | 10% | \$1,784.48 |
| EW NBD AHR H34727 | 97004-H34727 | \$ 1,968.00 | 10% | \$1,784.48 |
| EW NBD AHR H34728 | 97004-H34728 | \$ 1,968.00 | 10% | \$1,784.48 |
| EW NBD AHR H34729 | 97004-H34729 | \$ 1,968.00 | 10% | \$1,784.48 |
| EW NBD AHR H34730 | 97004-H34730 | \$ 2,108.00 | 10% | \$1,911.43 |
| EW NBD AHR H34731 | 97004-H34731 | \$ 2,108.00 | 10% | \$1,911.43 |
| EW NBD AHR H34732 | 97004-H34732 | \$ 2,108.00 | 10% | \$1,911.43 |
| EW NBD AHR H34733 | 97004-H34733 | \$ 2,108.00 | 10% | \$1,911.43 |
| EW NBD AHR H34734 | 97004-H34734 | \$ 303.00 | 10% | \$274.75 |
| EW NBD AHR H34735 | 97004-H34735 | \$ 303.00 | 10% | \$274.75 |
| EW NBD AHR H34736 | 97004-H34736 | \$ 385.00 | 10% | \$349.10 |
| EW NBD AHR H34737 | 97004-H34737 | \$ 385.00 | 10% | \$349.10 |
| EW NBD AHR H34738 | 97004-H34738 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34739 | 97004-H34739 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34740 | 97004-H34740 | \$ 303.00 | 10% | \$274.75 |
| EW NBD AHR H34741 | 97004-H34741 | \$ 303.00 | 10% | \$274.75 |
| EW NBD AHR H34742 | 97004-H34742 | \$ 171.00 | 10% | \$155.05 |
| EW NBD AHR H34743 | 97004-H34743 | \$ 171.00 | 10% | \$155.05 |
| EW NBD AHR H34744 | 97004-H34744 | \$ 383.00 | 10% | \$347.29 |
| EW NBD AHR H34745 | 97004-H34745 | \$ 383.00 | 10% | \$347.29 |
| EW NBD AHR H34746 | 97004-H34746 | \$ 438.00 | 10% | \$397.16 |
| EW NBD AHR H34747 | 97004-H34747 | \$ 438.00 | 10% | \$397.16 |
| EW NBD AHR H34748 | 97004-H34748 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34749 | 97004-H34749 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34750 | 97004-H34750 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34751 | 97004-H34751 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34752 | 97004-H34752 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34753 | 97004-H34753 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34754 | 97004-H34754 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34755 | 97004-H34755 | \$ 736.00 | 10% | \$667.37 |
| EW NBD AHR H34756 | 97004-H34756 | \$ 385.00 | 10% | \$349.10 |
| EW NBD AHR H34757 | 97004-H34757 | \$ 385.00 | 10% | \$349.10 |
| EW NBD AHR H34758 | 97004-H34758 | \$ 383.00 | 10% | \$347.29 |
| EW NBD AHR H34759 | 97004-H34759 | \$ 385.00 | 10% | \$349.10 |
| EW NBD AHR H34760 | 97004-H34760 | \$ 385.00 | 10% | \$349.10 |

| | | | | |
|-------------------|--------------|--------------|-----|------------|
| EW NBD AHR H34761 | 97004-H34761 | \$ 383.00 | 10% | \$347.29 |
| EW NBD AHR H34839 | 97004-H34839 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34840 | 97004-H34840 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34841 | 97004-H34841 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34842 | 97004-H34842 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34843 | 97004-H34843 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34844 | 97004-H34844 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34845 | 97004-H34845 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34846 | 97004-H34846 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H34993 | 97004-H34993 | \$ 10,284.00 | 10% | \$9,325.02 |
| EW NBD AHR H34994 | 97004-H34994 | \$ 10,284.00 | 10% | \$9,325.02 |
| EW NBD AHR H34996 | 97004-H34996 | \$ 10,284.00 | 10% | \$9,325.02 |
| EW NBD AHR H34997 | 97004-H34997 | \$ 10,284.00 | 10% | \$9,325.02 |
| EW NBD AHR H35005 | 97004-H35005 | \$ 7,510.00 | 10% | \$6,809.69 |
| EW NBD AHR H35006 | 97004-H35006 | \$ 7,510.00 | 10% | \$6,809.69 |
| EW NBD AHR H35012 | 97004-H35012 | \$ 4,508.00 | 10% | \$4,087.63 |
| EW NBD AHR H35070 | 97004-H35070 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35071 | 97004-H35071 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35072 | 97004-H35072 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35073 | 97004-H35073 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35074 | 97004-H35074 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35075 | 97004-H35075 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35076 | 97004-H35076 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35077 | 97004-H35077 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35078 | 97004-H35078 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35079 | 97004-H35079 | \$ 37.00 | 10% | \$33.55 |
| EW NBD AHR H35080 | 97004-H35080 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H35081 | 97004-H35081 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H35082 | 97004-H35082 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H35083 | 97004-H35083 | \$ 59.00 | 10% | \$53.50 |
| EW NBD AHR H35090 | 97004-H35090 | \$ 422.00 | 10% | \$382.65 |
| EW NBD AHR H35091 | 97004-H35091 | \$ 2,111.00 | 10% | \$1,914.15 |
| EW NBD AHR H35262 | 97004-H35262 | \$ 2,045.00 | 10% | \$1,854.30 |
| EW NBD AHR H35270 | 97004-H35270 | \$ 264.00 | 10% | \$239.38 |
| EW NBD AHR H35271 | 97004-H35271 | \$ 198.00 | 10% | \$179.54 |
| EW NBD AHR H35273 | 97004-H35273 | \$ 175.00 | 10% | \$158.68 |
| EW NBD AHR H35274 | 97004-H35274 | \$ 440.00 | 10% | \$398.97 |
| EW NBD AHR H35275 | 97004-H35275 | \$ 287.00 | 10% | \$260.24 |
| EW NBD AHR H35276 | 97004-H35276 | \$ 1,890.00 | 10% | \$1,713.76 |
| EW NBD AHR H35277 | 97004-H35277 | \$ 2,264.00 | 10% | \$2,052.88 |
| EW NBD AHR H35278 | 97004-H35278 | \$ 1,515.00 | 10% | \$1,373.73 |
| EW NBD AHR H35279 | 97004-H35279 | \$ 1,693.00 | 10% | \$1,535.13 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW NBD AHR H35280 | 97004-H35280 | \$ 2,498.00 | 10% | \$2,265.06 |
| EW NBD AHR H35281 | 97004-H35281 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35282 | 97004-H35282 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35283 | 97004-H35283 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35284 | 97004-H35284 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35285 | 97004-H35285 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35286 | 97004-H35286 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35287 | 97004-H35287 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35288 | 97004-H35288 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW NBD AHR H35289 | 97004-H35289 | \$ 3,638.00 | 10% | \$3,298.76 |
| EW NBD AHR H35291 | 97004-H35291 | \$ 2,753.00 | 10% | \$2,496.28 |
| EW NBD AHR H35292 | 97004-H35292 | \$ 1,515.00 | 10% | \$1,373.73 |
| EW NBD AHR H35293 | 97004-H35293 | \$ 1,693.00 | 10% | \$1,535.13 |
| EW NBD AHR H35295 | 97004-H35295 | \$ 235.00 | 10% | \$213.09 |
| EW NBD AHR H35296 | 97004-H35296 | \$ 5,309.00 | 10% | \$4,813.94 |
| EW NBD AHR H35297 | 97004-H35297 | \$ 5,309.00 | 10% | \$4,813.94 |
| EW NBD AHR H35298 | 97004-H35298 | \$ 8,531.00 | 10% | \$7,735.48 |
| EW NBD AHR H35299 | 97004-H35299 | \$ 8,531.00 | 10% | \$7,735.48 |
| EW NBD AHR H35302 | 97004-H35302 | \$ 2,059.00 | 10% | \$1,867.00 |
| EW NBD AHR H35303 | 97004-H35303 | \$ 2,059.00 | 10% | \$1,867.00 |
| EW NBD AHR H35304 | 97004-H35304 | \$ 2,059.00 | 10% | \$1,867.00 |
| EW NBD AHR H35305 | 97004-H35305 | \$ 2,157.00 | 10% | \$1,955.86 |
| EW NBD AHR H35306 | 97004-H35306 | \$ 2,157.00 | 10% | \$1,955.86 |
| EW NBD AHR H35307 | 97004-H35307 | \$ 2,157.00 | 10% | \$1,955.86 |
| EW NBD AHR H35309 | 97004-H35309 | \$ 2,554.00 | 10% | \$2,315.84 |
| EW NBD AHR H35310 | 97004-H35310 | \$ 2,554.00 | 10% | \$2,315.84 |
| EW NBD AHR H35311 | 97004-H35311 | \$ 2,554.00 | 10% | \$2,315.84 |
| EW NBD AHR H35312 | 97004-H35312 | \$ 2,113.00 | 10% | \$1,915.96 |
| EW NBD AHR H35313 | 97004-H35313 | \$ 2,113.00 | 10% | \$1,915.96 |
| EW NBD AHR H35314 | 97004-H35314 | \$ 2,113.00 | 10% | \$1,915.96 |
| EW NBD AHR H35315 | 97004-H35315 | \$ 915.00 | 10% | \$829.68 |
| EW NBD AHR H35318 | 97004-H35318 | \$ 431.00 | 10% | \$390.81 |
| EW NBD AHR H35319 | 97004-H35319 | \$ 582.00 | 10% | \$527.73 |
| EW NBD AHR H35320 | 97004-H35320 | \$ 604.00 | 10% | \$547.68 |
| EW NBD AHR H35321 | 97004-H35321 | \$ 769.00 | 10% | \$697.29 |
| EW NBD AHR H35322 | 97004-H35322 | \$ 934.00 | 10% | \$846.90 |
| EW NBD AHR H35323 | 97004-H35323 | \$ 915.00 | 10% | \$829.68 |
| EW NBD AHR H35328 | 97004-H35328 | \$ 78.00 | 10% | \$70.73 |
| EW NBD AHR H35330 | 97004-H35330 | \$ 50.00 | 10% | \$45.34 |
| EW NBD AHR H35340 | 97004-H35340 | \$ 2,223.00 | 10% | \$2,015.71 |
| EW NBD AHR H35341 | 97004-H35341 | \$ 2,223.00 | 10% | \$2,015.71 |
| EW NBD AHR H35342 | 97004-H35342 | \$ 1,966.00 | 10% | \$1,782.67 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW NBD AHR H35343 | 97004-H35343 | \$ 2,223.00 | 10% | \$2,015.71 |
| EW NBD AHR H35344 | 97004-H35344 | \$ 2,319.00 | 10% | \$2,102.75 |
| EW NBD AHR H35345 | 97004-H35345 | \$ 2,319.00 | 10% | \$2,102.75 |
| EW NBD AHR H35346 | 97004-H35346 | \$ 2,038.00 | 10% | \$1,847.96 |
| EW NBD AHR H35347 | 97004-H35347 | \$ 2,319.00 | 10% | \$2,102.75 |
| EW NBD AHR H35349 | 97004-H35349 | \$ 2,562.00 | 10% | \$2,323.09 |
| EW NBD AHR H35350 | 97004-H35350 | \$ 2,562.00 | 10% | \$2,323.09 |
| EW NBD AHR H35351 | 97004-H35351 | \$ 2,231.00 | 10% | \$2,022.96 |
| EW NBD AHR H35352 | 97004-H35352 | \$ 2,562.00 | 10% | \$2,323.09 |
| EW NBD AHR H35359 | 97004-H35359 | \$ 769.00 | 10% | \$697.29 |
| EW NBD AHR H35360 | 97004-H35360 | \$ 934.00 | 10% | \$846.90 |
| EW NBD AHR H35361 | 97004-H35361 | \$ 915.00 | 10% | \$829.68 |
| EW NBD AHR H35362 | 97004-H35362 | \$ 431.00 | 10% | \$390.81 |
| EW NBD AHR H35366 | 97004-H35366 | \$ 1,118.00 | 10% | \$1,013.75 |
| EW NBD AHR H35367 | 97004-H35367 | \$ 1,304.00 | 10% | \$1,182.40 |
| EW NBD AHR H35368 | 97004-H35368 | \$ 1,988.00 | 10% | \$1,802.62 |
| EW NBD AHR H35369 | 97004-H35369 | \$ 649.00 | 10% | \$588.48 |
| EW NBD AHR H35370 | 97004-H35370 | \$ 910.00 | 10% | \$825.14 |
| EW NBD AHR H35375 | 97004-H35375 | \$ 542.00 | 10% | \$491.46 |
| EW NBD AHR H35376 | 97004-H35376 | \$ 820.00 | 10% | \$743.54 |
| EW NBD AHR H35377 | 97004-H35377 | \$ 344.00 | 10% | \$311.92 |
| EW NBD AHR H35378 | 97004-H35378 | \$ 547.00 | 10% | \$495.99 |
| EW NBD AHR H35379 | 97004-H35379 | \$ 344.00 | 10% | \$311.92 |
| EW NBD AHR H35380 | 97004-H35380 | \$ 616.00 | 10% | \$558.56 |
| EW NBD AHR H35381 | 97004-H35381 | \$ 751.00 | 10% | \$680.97 |
| EW NBD AHR H35384 | 97004-H35384 | \$ 249.00 | 10% | \$225.78 |
| EW NBD AHR H35385 | 97004-H35385 | \$ 331.00 | 10% | \$300.13 |
| EW NBD AHR H35386 | 97004-H35386 | \$ 547.00 | 10% | \$495.99 |
| EW NBD AHR H35387 | 97004-H35387 | \$ 511.00 | 10% | \$463.35 |
| EW NBD AHR H35388 | 97004-H35388 | \$ 375.00 | 10% | \$340.03 |
| EW NBD AHR H35389 | 97004-H35389 | \$ 214.00 | 10% | \$194.04 |
| EW NBD AHR H35390 | 97004-H35390 | \$ 185.00 | 10% | \$167.75 |
| EW NBD AHR H35391 | 97004-H35391 | \$ 404.00 | 10% | \$366.33 |
| EW NBD AHR H35392 | 97004-H35392 | \$ 616.00 | 10% | \$558.56 |
| EW NBD AHR H35393 | 97004-H35393 | \$ 820.00 | 10% | \$743.54 |
| EW NBD AHR H35394 | 97004-H35394 | \$ 147.00 | 10% | \$133.29 |
| EW NBD AHR H35395 | 97004-H35395 | \$ 128.00 | 10% | \$116.06 |
| EW NBD AHR H35396 | 97004-H35396 | \$ 147.00 | 10% | \$133.29 |
| EW NBD AHR H35397 | 97004-H35397 | \$ 128.00 | 10% | \$116.06 |
| EW NBD AHR H35398 | 97004-H35398 | \$ 382.00 | 10% | \$346.38 |
| EW NBD AHR H35399 | 97004-H35399 | \$ 464.00 | 10% | \$420.73 |
| EW NBD AHR H35400 | 97004-H35400 | \$ 515.00 | 10% | \$466.98 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW NBD AHR H35401 | 97004-H35401 | \$ 274.00 | 10% | \$248.45 |
| EW NBD AHR H35415 | 97004-H35415 | \$ 186.00 | 10% | \$168.66 |
| EW NBD AHR H35416 | 97004-H35416 | \$ 186.00 | 10% | \$168.66 |
| EW NBD AHR H35426 | 97004-H35426 | \$ 214.00 | 10% | \$194.04 |
| EW NBD AHR H35427 | 97004-H35427 | \$ 511.00 | 10% | \$463.35 |
| EW NBD AHR H35428 | 97004-H35428 | \$ 185.00 | 10% | \$167.75 |
| EW NBD AHR H35429 | 97004-H35429 | \$ 404.00 | 10% | \$366.33 |
| EW NBD AHR H35430 | 97004-H35430 | \$ 295.00 | 10% | \$267.49 |
| EW NBD AHR H35431 | 97004-H35431 | \$ 295.00 | 10% | \$267.49 |
| EW NBD AHR H35432 | 97004-H35432 | \$ 171.00 | 10% | \$155.05 |
| EW NBD AHR H35433 | 97004-H35433 | \$ 374.00 | 10% | \$339.12 |
| EW NBD AHR H35434 | 97004-H35434 | \$ 427.00 | 10% | \$387.18 |
| EW NBD AHR H35435 | 97004-H35435 | \$ 427.00 | 10% | \$387.18 |
| EW NBD AHR H35436 | 97004-H35436 | \$ 715.00 | 10% | \$648.33 |
| EW NBD AHR H35437 | 97004-H35437 | \$ 715.00 | 10% | \$648.33 |
| EW NBD AHR H35438 | 97004-H35438 | \$ 715.00 | 10% | \$648.33 |
| EW NBD AHR H35439 | 97004-H35439 | \$ 715.00 | 10% | \$648.33 |
| EW NBD AHR H35440 | 97004-H35440 | \$ 374.00 | 10% | \$339.12 |
| EW NBD AHR H35441 | 97004-H35441 | \$ 374.00 | 10% | \$339.12 |
| EW NBD AHR H35442 | 97004-H35442 | \$ 374.00 | 10% | \$339.12 |
| EW NBD AHR H35443 | 97004-H35443 | \$ 1,968.00 | 10% | \$1,784.48 |
| EW NBD AHR H35444 | 97004-H35444 | \$ 2,108.00 | 10% | \$1,911.43 |
| EW NBD AHR H35445 | 97004-H35445 | \$ 1,890.00 | 10% | \$1,713.76 |
| EW NBD AHR H35446 | 97004-H35446 | \$ 1,854.00 | 10% | \$1,681.11 |
| EW NBD AHR H35447 | 97004-H35447 | \$ 2,145.00 | 10% | \$1,944.98 |
| EW NBD AHR H35448 | 97004-H35448 | \$ 2,057.00 | 10% | \$1,865.18 |
| EW NBD AHR H35449 | 97004-H35449 | \$ 1,515.00 | 10% | \$1,373.73 |
| EW NBD AHR H35450 | 97004-H35450 | \$ 1,604.00 | 10% | \$1,454.43 |
| EW NBD AHR H35451 | 97004-H35451 | \$ 2,643.00 | 10% | \$2,396.54 |
| EW NBD AHR H35452 | 97004-H35452 | \$ 2,643.00 | 10% | \$2,396.54 |
| EW NBD AHR H35453 | 97004-H35453 | \$ 2,108.00 | 10% | \$1,911.43 |
| EW NBD AHR H35454 | 97004-H35454 | \$ 1,968.00 | 10% | \$1,784.48 |
| EW NBD AHR H35455 | 97004-H35455 | \$ 604.00 | 10% | \$547.68 |
| EW NBD AHR H35456 | 97004-H35456 | \$ 758.00 | 10% | \$687.32 |
| EW NBD AHR H35457 | 97004-H35457 | \$ 680.00 | 10% | \$616.59 |
| EW NBD AHR H35458 | 97004-H35458 | \$ 744.00 | 10% | \$674.62 |
| EW NBD AHR H35471 | 97004-H35471 | \$ 604.00 | 10% | \$547.68 |
| EW NBD AHR H35600 | 97004-H35600 | \$ 175.00 | 10% | \$158.68 |
| EW NBD AHR H35601 | 97004-H35601 | \$ 175.00 | 10% | \$158.68 |
| EW NBD AHR H35602 | 97004-H35602 | \$ 303.00 | 10% | \$274.75 |
| EW NBD AHR H35603 | 97004-H35603 | \$ 303.00 | 10% | \$274.75 |
| EW NBD AHR H35604 | 97004-H35604 | \$ 385.00 | 10% | \$349.10 |

| | | | | |
|---------------------------------|----------------------------|--------------|-----|--------------------|
| EW NBD AHR H35605 | 97004-H35605 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW NBD AHR H35606 | 97004-H35606 | \$ 440.00 | 10% | <i>\$398.97</i> |
| EW NBD AHR H35607 | 97004-H35607 | \$ 438.00 | 10% | <i>\$397.16</i> |
| EW NBD AHR ipe-2000ax-LR-10G | 97004-ipe-2000ax-LR-10G | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |
| EW NBD AHR ipe-2000ax-LR-10G-WP | 97004-ipe-2000ax-LR-10G-WP | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |
| EW NBD AHR ipe-2000ax-Lx | 97004-ipe-2000ax-Lx | \$ 3,700.00 | 10% | <i>\$3,354.98</i> |
| EW NBD AHR ipe-2000ax-Lx-WP | 97004-ipe-2000ax-Lx-WP | \$ 3,700.00 | 10% | <i>\$3,354.98</i> |
| EW NBD AHR ipe-2000ax-SR-10G | 97004-ipe-2000ax-SR-10G | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |
| EW NBD AHR ipe-2000ax-SR-10G-WP | 97004-ipe-2000ax-SR-10G-WP | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |
| EW NBD AHR ipe-2000ax-Sx | 97004-ipe-2000ax-Sx | \$ 3,700.00 | 10% | <i>\$3,354.98</i> |
| EW NBD AHR ipe-2000ax-Sx-WP | 97004-ipe-2000ax-Sx-WP | \$ 3,700.00 | 10% | <i>\$3,354.98</i> |
| EW NBD AHR ipe-2000ax-T | 97004-ipe-2000ax-T | \$ 3,255.00 | 10% | <i>\$2,951.47</i> |
| EW NBD AHR ipe-2000ax-T-WP | 97004-ipe-2000ax-T-WP | \$ 3,255.00 | 10% | <i>\$2,951.47</i> |
| EW NBD AHR ipe-30ax | 97004-ipe-30ax | \$ 139.00 | 10% | <i>\$126.04</i> |
| EW NBD AHR ipe-30ax-WP | 97004-ipe-30ax-WP | \$ 139.00 | 10% | <i>\$126.04</i> |
| EW NBD AHR ipe-30so | 97004-ipe-30so | \$ 116.00 | 10% | <i>\$105.18</i> |
| EW NBD AHR ipe-30so-WP | 97004-ipe-30so-WP | \$ 116.00 | 10% | <i>\$105.18</i> |
| EW NBD AHR ipe-4000ax-10Lr-10G | 97004-ipe-4000ax-10Lr-10G | \$ 14,651.00 | 10% | <i>\$13,284.79</i> |
| EW NBD AHR ipe-4000ax-10Lr-3.5G | 97004-ipe-4000ax-10Lr-3.5G | \$ 8,259.00 | 10% | <i>\$7,488.85</i> |
| EW NBD AHR ipe-4000ax-10Lr-7G | 97004-ipe-4000ax-10Lr-7G | \$ 11,839.00 | 10% | <i>\$10,735.01</i> |

| | | | | |
|---------------------------------|----------------------------|--------------|-----|--------------------|
| EW NBD AHR ipe-4000ax-10Sr-10G | 97004-ipe-4000ax-10Sr-10G | \$ 14,503.00 | 10% | <i>\$13,150.60</i> |
| EW NBD AHR ipe-4000ax-10Sr-3.5G | 97004-ipe-4000ax-10Sr-3.5G | \$ 8,122.00 | 10% | <i>\$7,364.62</i> |
| EW NBD AHR ipe-4000ax-10Sr-7G | 97004-ipe-4000ax-10Sr-7G | \$ 11,691.00 | 10% | <i>\$10,600.81</i> |
| EW NBD AHR ipe-4000ax-20Lr-10G | 97004-ipe-4000ax-20Lr-10G | \$ 17,611.00 | 10% | <i>\$15,968.77</i> |
| EW NBD AHR ipe-4000ax-20Lr-14G | 97004-ipe-4000ax-20Lr-14G | \$ 20,570.00 | 10% | <i>\$18,651.85</i> |
| EW NBD AHR ipe-4000ax-20Lr-20G | 97004-ipe-4000ax-20Lr-20G | \$ 26,340.00 | 10% | <i>\$23,883.80</i> |
| EW NBD AHR ipe-4000ax-20Lr-7G | 97004-ipe-4000ax-20Lr-7G | \$ 14,651.00 | 10% | <i>\$13,284.79</i> |
| EW NBD AHR ipe-4000ax-20Sr-10G | 97004-ipe-4000ax-20Sr-10G | \$ 17,462.00 | 10% | <i>\$15,833.67</i> |
| EW NBD AHR ipe-4000ax-20Sr-14G | 97004-ipe-4000ax-20Sr-14G | \$ 20,488.00 | 10% | <i>\$18,577.49</i> |
| EW NBD AHR ipe-4000ax-20Sr-20G | 97004-ipe-4000ax-20Sr-20G | \$ 26,192.00 | 10% | <i>\$23,749.60</i> |
| EW NBD AHR ipe-4000ax-20Sr-7G | 97004-ipe-4000ax-20Sr-7G | \$ 14,503.00 | 10% | <i>\$13,150.60</i> |
| EW NBD AHR ipe-4002ax | 97004-ipe-4002ax | \$ 2,812.00 | 10% | <i>\$2,549.78</i> |
| EW NBD AHR ipe-400ax | 97004-ipe-400ax | \$ 718.00 | 10% | <i>\$651.05</i> |
| EW NBD AHR ipe-400ax-WP | 97004-ipe-400ax-WP | \$ 718.00 | 10% | <i>\$651.05</i> |
| EW NBD AHR ipe-40ax | 97004-ipe-40ax | \$ 276.00 | 10% | <i>\$250.26</i> |
| EW NBD AHR ipe-40ax-V2 | 97004-ipe-40ax-V2 | \$ 327.00 | 10% | <i>\$296.51</i> |

| | | | | |
|----------------------------------|-----------------------------|-------------|-----|------------|
| EW NBD AHR ipe-40ax-V2-WP | 97004-ipe-40ax-V2-WP | \$ 327.00 | 10% | \$296.51 |
| EW NBD AHR ipe-40so | 97004-ipe-40so | \$ 188.00 | 10% | \$170.47 |
| EW NBD AHR ipe-40so-V2 | 97004-ipe-40so-V2 | \$ 223.00 | 10% | \$202.21 |
| EW NBD AHR ipe-40so-V2-WP | 97004-ipe-40so-V2-WP | \$ 223.00 | 10% | \$202.21 |
| EW NBD AHR ipe-420ax | 97004-ipe-420ax | \$ 799.00 | 10% | \$724.49 |
| EW NBD AHR ipe-420ax-WP | 97004-ipe-420ax-WP | \$ 799.00 | 10% | \$724.49 |
| EW NBD AHR ipr-4108Lr | 97004-ipr-4108Lr | \$ 3,108.00 | 10% | \$2,818.18 |
| EW NBD AHR ipr-4108Sr | 97004-ipr-4108Sr | \$ 2,960.00 | 10% | \$2,683.98 |
| EW NBD AHR ISD-ipe-2000ax-LR-10G | 97004-ISD-ipe-2000ax-LR-10G | \$ 2,819.00 | 10% | \$2,556.13 |
| EW NBD AHR ISD-ipe-2000ax-Lx | 97004-ISD-ipe-2000ax-Lx | \$ 2,114.00 | 10% | \$1,916.87 |
| EW NBD AHR ISD-ipe-2000ax-SR-10G | 97004-ISD-ipe-2000ax-SR-10G | \$ 2,819.00 | 10% | \$2,556.13 |
| EW NBD AHR ISD-ipe-2000ax-Sx | 97004-ISD-ipe-2000ax-Sx | \$ 2,114.00 | 10% | \$1,916.87 |
| EW NBD AHR ISD-ipe-2000ax-T | 97004-ISD-ipe-2000ax-T | \$ 1,550.00 | 10% | \$1,405.46 |
| EW NBD AHR ISD-IPE-2200AX-LR-10G | 97004-ISD-IPE-2200AX-LR-10G | \$ 2,819.00 | 10% | \$2,556.13 |
| EW NBD AHR ISD-IPE-2200AX-SR-10G | 97004-ISD-IPE-2200AX-SR-10G | \$ 2,819.00 | 10% | \$2,556.13 |
| EW NBD AHR ISD-IPE-2200AX-T | 97004-ISD-IPE-2200AX-T | \$ 1,550.00 | 10% | \$1,405.46 |
| EW NBD AHR ISD-ipe-30ax | 97004-ISD-ipe-30ax | \$ 131.00 | 10% | \$118.78 |
| EW NBD AHR ISD-ipe-30so | 97004-ISD-ipe-30so | \$ 104.00 | 10% | \$94.30 |
| EW NBD AHR ISD-ipe-400ax | 97004-ISD-ipe-400ax | \$ 656.00 | 10% | \$594.83 |

| | | | | |
|------------------------------|-------------------------|--------------|-----|-------------|
| EW NBD AHR ISD-ipe-40ax-V2 | 97004-ISD-ipe-40ax-V2 | \$ 290.00 | 10% | \$262.96 |
| EW NBD AHR ISD-ipe-40so-V2 | 97004-ISD-ipe-40so-V2 | \$ 198.00 | 10% | \$179.54 |
| EW NBD AHR ISD-ipe-420ax | 97004-ISD-ipe-420ax | \$ 662.00 | 10% | \$600.27 |
| EW NBD AHR ISW-24W-4X | 97004-ISW-24W-4X | \$ 636.00 | 10% | \$576.69 |
| EW NBD AHR ISW-4W-4WS-4X | 97004-ISW-4W-4WS-4X | \$ 403.00 | 10% | \$365.42 |
| EW NBD AHR BD MSM128 | 97004-MSM128 | \$ 2,378.00 | 10% | \$2,156.25 |
| EW NBD AHR BD MSM48C | 97004-MSM48C | \$ 1,444.00 | 10% | \$1,309.35 |
| ExtremeWorks NBD AHR | 97004-R100-8T | \$ 60.00 | 10% | \$54.41 |
| EW NBD AHR SLX9150-48XT-DC-F | 97004-SLX9150-48XT-DC-F | \$ 2,023.00 | 10% | \$1,834.36 |
| EW NBD AHR SLX9150-48XT-DC-R | 97004-SLX9150-48XT-DC-R | \$ 2,209.00 | 10% | \$2,003.01 |
| EW NBD AHR SLX9150-48Y-DC-F | 97004-SLX9150-48Y-DC-F | \$ 1,938.00 | 10% | \$1,757.28 |
| EW NBD AHR SLX9150-48Y-DC-R | 97004-SLX9150-48Y-DC-R | \$ 2,117.00 | 10% | \$1,919.59 |
| EW NBD AHR SLX9740-40C | 97004-SLX9740-40C | \$ 8,715.00 | 10% | \$7,902.33 |
| EW NBD AHR SLX9740-40C-AC-F | 97004-SLX9740-40C-AC-F | \$ 8,715.00 | 10% | \$7,902.33 |
| EW NBD AHR SLX9740-40C-AC-R | 97004-SLX9740-40C-AC-R | \$ 8,715.00 | 10% | \$7,902.33 |
| EW NBD AHR SLX9740-40C-DC-F | 97004-SLX9740-40C-DC-F | \$ 8,715.00 | 10% | \$7,902.33 |
| EW NBD AHR SLX9740-80C | 97004-SLX9740-80C | \$ 16,389.00 | 10% | \$14,860.73 |

| | | | | |
|------------------------------|------------------------|--------------|-----|--------------------|
| EW NBD AHR SLX9740-80C-AC-F | 97004-SLX9740-80C-AC-F | \$ 16,389.00 | 10% | <i>\$14,860.73</i> |
| EW NBD AHR SLX9740-80C-AC-R | 97004-SLX9740-80C-AC-R | \$ 16,389.00 | 10% | <i>\$14,860.73</i> |
| EW NBD AHR SLX9740-80C-DC-F | 97004-SLX9740-80C-DC-F | \$ 16,389.00 | 10% | <i>\$14,860.73</i> |
| EW NBD AHR V300-8P-2X | 97004-V300-8P-2X | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW NBD AHR V300-8T-2X | 97004-V300-8T-2X | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD AHR V300HT-8P-2X | 97004-V300HT-8P-2X | \$ 231.00 | 10% | <i>\$209.46</i> |
| EW NBD AHR V300HT-8T-2X | 97004-V300HT-8T-2X | \$ 137.00 | 10% | <i>\$124.22</i> |
| EW NBD AHR Summit VIM-SS | 97004-VIM-SS | \$ 121.00 | 10% | <i>\$109.72</i> |
| EW NBD AHR Summit VIM-SSV80 | 97004-VIM-SSV80 | \$ 227.00 | 10% | <i>\$205.83</i> |
| EW NBD AHR Summit VIM2-SS | 97004-VIM2-SS | \$ 142.00 | 10% | <i>\$128.76</i> |
| EW NBD AHR Summit VIM2-SS128 | 97004-VIM2-SS128 | \$ 489.00 | 10% | <i>\$443.40</i> |
| EW NBD AHR Summit VIM2-V80 | 97004-VIM2-V80 | \$ 523.00 | 10% | <i>\$474.23</i> |
| EW NBD AHR Summit VIM210G4X | 97004-VIM210G4X | \$ 907.00 | 10% | <i>\$822.42</i> |
| EW NBD AHR VIM5-2Q | 97004-VIM5-2Q | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW NBD AHR VIM5-2Y | 97004-VIM5-2Y | \$ 171.00 | 10% | <i>\$155.05</i> |
| EW NBD AHR VIM5-4X | 97004-VIM5-4X | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD AHR VIM5-4XE | 97004-VIM5-4XE | \$ 140.00 | 10% | <i>\$126.95</i> |
| EW NBD AHR VIM5-4Y | 97004-VIM5-4Y | \$ 218.00 | 10% | <i>\$197.67</i> |
| EW NBD AHR VIM5-4YE | 97004-VIM5-4YE | \$ 282.00 | 10% | <i>\$255.70</i> |

| | | | | |
|----------------------------------|-----------------------------|-------------|-----|-------------------|
| EW NBD AHR VSP4900-12MXU-12XE | 97004-VSP4900-12MXU-12XE | \$ 807.00 | 10% | <i>\$731.75</i> |
| EW NBD AHR VSP4900-12MXU-12XE-B1 | 97004-VSP4900-12MXU-12XE-B1 | \$ 807.00 | 10% | <i>\$731.75</i> |
| EW NBD AHR VSP4900-24S | 97004-VSP4900-24S | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW NBD AHR VSP4900-24S-B3 | 97004-VSP4900-24S-B3 | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW NBD AHR VSP4900-24XE | 97004-VSP4900-24XE | \$ 807.00 | 10% | <i>\$731.75</i> |
| EW NBD AHR VSP4900-24XE-B3 | 97004-VSP4900-24XE-B3 | \$ 807.00 | 10% | <i>\$731.75</i> |
| EW NBD AHR X435-24P-4S | 97004-X435-24P-4S | \$ 180.00 | 10% | <i>\$163.22</i> |
| EW NBD AHR X435-24T-4S | 97004-X435-24T-4S | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW NBD AHR X435-8P-2T-W | 97004-X435-8P-2T-W | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW NBD AHR X435-8P-4S | 97004-X435-8P-4S | \$ 90.00 | 10% | <i>\$81.61</i> |
| EW NBD AHR X435-8T-4S | 97004-X435-8T-4S | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW NBD AHR Summit X460-24P | 97004-X460-24P | \$ 851.00 | 10% | <i>\$771.64</i> |
| EW NBD AHR Summit X460-24T | 97004-X460-24T | \$ 595.00 | 10% | <i>\$539.52</i> |
| EW NBD AHR Summit X460-24TDC | 97004-X460-24TDC | \$ 875.00 | 10% | <i>\$793.41</i> |
| EW NBD AHR Summit X460-24X | 97004-X460-24X | \$ 1,102.00 | 10% | <i>\$999.24</i> |
| EW NBD AHR Summit X460-24XDC | 97004-X460-24XDC | \$ 1,234.00 | 10% | <i>\$1,118.93</i> |
| EW NBD AHR Summit X460-48P | 97004-X460-48P | \$ 1,102.00 | 10% | <i>\$999.24</i> |
| EW NBD AHR Summit X460-48T | 97004-X460-48T | \$ 946.00 | 10% | <i>\$857.79</i> |

| | | | | |
|------------------------------|-----------------------|-------------|-----|-------------------|
| EW NBD AHR Summit X460-48TDC | 97004-X460-48TDC | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW NBD AHR Summit X460-48X | 97004-X460-48X | \$ 1,467.00 | 10% | <i>\$1,330.20</i> |
| EW NBD AHR Summit X460-48XDC | 97004-X460-48XDC | \$ 1,432.00 | 10% | <i>\$1,298.47</i> |
| EW NBD AHR X465-24MU | 97004-X465-24MU | \$ 934.00 | 10% | <i>\$846.90</i> |
| EW NBD AHR X465-24S | 97004-X465-24S | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW NBD AHR X465-24S-B3 | 97004-X465-24S-B3 | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW NBD AHR X465-24W | 97004-X465-24W | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW NBD AHR X465-24XE | 97004-X465-24XE | \$ 807.00 | 10% | <i>\$731.75</i> |
| EW NBD AHR X465-24XE-B3 | 97004-X465-24XE-B3 | \$ 807.00 | 10% | <i>\$731.75</i> |
| EW NBD AHR X465-48P | 97004-X465-48P | \$ 604.00 | 10% | <i>\$547.68</i> |
| EW NBD AHR X465-48T | 97004-X465-48T | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW NBD AHR X465-48W | 97004-X465-48W | \$ 769.00 | 10% | <i>\$697.29</i> |
| EW NBD AHR X465i-48W | 97004-X465i-48W | \$ 915.00 | 10% | <i>\$829.68</i> |
| EW NBD AHR X465i-48W-B1-S1 | 97004-X465i-48W-B1-S1 | \$ 915.00 | 10% | <i>\$829.68</i> |
| EW NBD AHR X465i-48W-B2-S1 | 97004-X465i-48W-B2-S1 | \$ 915.00 | 10% | <i>\$829.68</i> |
| EW NBD AHR Summit X480-24X | 97004-X480-24X | \$ 1,359.00 | 10% | <i>\$1,232.27</i> |
| EW NBD AHR Summit X480-48T | 97004-X480-48T | \$ 1,359.00 | 10% | <i>\$1,232.27</i> |
| EW NBD AHR Summit X480-48X | 97004-X480-48X | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |
| EW NBD AHR X695-48Y-8C | 97004-X695-48Y-8C | \$ 2,112.00 | 10% | <i>\$1,915.06</i> |
| EW NBD AHR XA1440 | 97004-XA1440 | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW NBD AHR XA1480 | 97004-XA1480 | \$ 295.00 | 10% | <i>\$267.49</i> |

| | | | | |
|---------------------------------|----------------------------|-------------|-----|------------|
| EW NBD AHR Summit XGM3-2SF | 97004-XGM3-2SF | \$ 227.00 | 10% | \$205.83 |
| EW NBD AHR XR600 | 97004-XR600 | \$ 63.00 | 10% | \$57.13 |
| EW NBD AHR XSW-BR-M-A-D-NR | 97004-XSW-BR-M-A-D-NR | \$ 270.00 | 10% | \$244.82 |
| EW NBD AHR XSW-BR-S-A-D-NR | 97004-XSW-BR-S-A-D-NR | \$ 122.00 | 10% | \$110.62 |
| EW NBD AHR XSW-BR-XS-A-D-NR | 97004-XSW-BR-XS-A-D-NR | \$ 98.00 | 10% | \$88.86 |
| EW NBD AHR XSW-DC-S-A-D-NR | 97004-XSW-DC-S-A-D-NR | \$ 619.00 | 10% | \$561.28 |
| EW NBD AHR XSW-DCV2-LR-L-A-D-NR | 97004-XSW-DCV2-LR-L-A-D-NR | \$ 2,569.00 | 10% | \$2,329.44 |
| EW NBD AHR XSW-DCV2-M-A-D-NR | 97004-XSW-DCV2-M-A-D-NR | \$ 1,884.00 | 10% | \$1,708.32 |
| EW NBD AHR XSW-DCV2-SR-L-A-D-NR | 97004-XSW-DCV2-SR-L-A-D-NR | \$ 2,569.00 | 10% | \$2,329.44 |
| EW NBD AHR -ZR-XFP | 97004-ZR-XFP | \$ 1,371.00 | 10% | \$1,243.15 |
| EW 4HR AHR Optics 10200 | 97007-10200 | \$ 2,519.00 | 10% | \$2,284.10 |
| EW 4HR AHR Optics 10320 | 97007-10320 | \$ 2,772.00 | 10% | \$2,513.51 |
| EW 4HR AHR 10330 | 97007-10330 | \$ 6,790.00 | 10% | \$6,156.83 |
| EW 4HR AHR 10331 | 97007-10331 | \$ 3,137.00 | 10% | \$2,844.47 |
| EW 4HR AHR 10335 | 97007-10335 | \$ 4,783.00 | 10% | \$4,336.99 |
| EW 4HR AHR 10403 | 97007-10403 | \$ 5,938.00 | 10% | \$5,384.28 |
| EW 4HR AHR 10404 | 97007-10404 | \$ 2,916.00 | 10% | \$2,644.08 |
| EW 4HR AHR 10441 | 97007-10441 | \$ 1,957.00 | 10% | \$1,774.51 |
| EW 4HR AHR 10442 | 97007-10442 | \$ 2,083.00 | 10% | \$1,888.76 |
| EW 4HR AHR 1130C | 97007-1130C | \$ 1,200.00 | 6% | \$1,136.46 |
| EW 4HR AHR E4G 16119 | 97007-16119 | \$ 361.00 | 10% | \$327.34 |
| EW 4HR AHR E4G 16120 | 97007-16120 | \$ 446.00 | 10% | \$404.41 |
| EW 4HR AHR E4G 16126 | 97007-16126 | \$ 361.00 | 10% | \$327.34 |
| EW 4HR AHR E4G 16127 | 97007-16127 | \$ 378.00 | 10% | \$342.75 |
| EW 4HR AHR 16172 | 97007-16172 | \$ 362.00 | 10% | \$328.24 |
| EW 4HR AHR -16172T | 97007-16172T | \$ 444.00 | 10% | \$402.60 |
| EW 4HR AHR 16173 | 97007-16173 | \$ 386.00 | 10% | \$350.01 |
| EW 4HR AHR -16173T | 97007-16173T | \$ 465.00 | 10% | \$421.64 |
| EW 4HR AHR 16174 | 97007-16174 | \$ 585.00 | 10% | \$530.45 |

| | | | | |
|-------------------------|--------------|-------------|-----|------------|
| EW 4HR AHR 16175 | 97007-16175 | \$ 628.00 | 10% | \$569.44 |
| EW 4HR AHR 16176 | 97007-16176 | \$ 547.00 | 10% | \$495.99 |
| EW 4HR AHR 16177 | 97007-16177 | \$ 539.00 | 10% | \$488.74 |
| EW 4HR AHR -16177T | 97007-16177T | \$ 688.00 | 10% | \$623.84 |
| EW 4HR AHR 16178 | 97007-16178 | \$ 792.00 | 10% | \$718.15 |
| EW 4HR AHR 16179 | 97007-16179 | \$ 814.00 | 10% | \$738.09 |
| EW 4HR AHR -16179T | 97007-16179T | \$ 975.00 | 10% | \$884.08 |
| EW 4HR AHR 16301T | 97007-16301T | \$ 2,126.00 | 10% | \$1,927.75 |
| EW 4HR AHR 16303T | 97007-16303T | \$ 2,126.00 | 10% | \$1,927.75 |
| EW 4HR AHR 16304T | 97007-16304T | \$ 2,840.00 | 10% | \$2,575.17 |
| EW 4HR AHR 16401T | 97007-16401T | \$ 999.00 | 10% | \$905.84 |
| EW 4HR AHR 16402T | 97007-16402T | \$ 1,527.00 | 10% | \$1,384.61 |
| EW 4HR AHR 16403T | 97007-16403T | \$ 1,335.00 | 10% | \$1,210.51 |
| EW 4HR AHR 16404T | 97007-16404T | \$ 1,335.00 | 10% | \$1,210.51 |
| EW 4HR AHR 16405T | 97007-16405T | \$ 1,778.00 | 10% | \$1,612.20 |
| EW 4HR AHR 16406T | 97007-16406T | \$ 2,364.00 | 10% | \$2,143.56 |
| EW 4HR AHR E4G 16431 | 97007-16431 | \$ 1,491.00 | 10% | \$1,351.96 |
| EW 4HR AHR E4G 16432 | 97007-16432 | \$ 1,621.00 | 10% | \$1,469.84 |
| EW 4HR AHR E4G 16440 | 97007-16440 | \$ 935.00 | 10% | \$847.81 |
| EW 4HR AHR E4G 16441 | 97007-16441 | \$ 846.00 | 10% | \$767.11 |
| EW 4HR AHR E4G 16442 | 97007-16442 | \$ 378.00 | 10% | \$342.75 |
| EW 4HR AHR E4G 16444 | 97007-16444 | \$ 187.00 | 10% | \$169.56 |
| EW 4HR AHR Summit 16501 | 97007-16501 | \$ 200.00 | 10% | \$181.35 |
| EW 4HR AHR 16501T | 97007-16501T | \$ 265.00 | 10% | \$240.29 |
| EW 4HR AHR Summit 16502 | 97007-16502 | \$ 301.00 | 10% | \$272.93 |
| EW 4HR AHR 16502T | 97007-16502T | \$ 360.00 | 10% | \$326.43 |
| EW 4HR AHR Summit 16503 | 97007-16503 | \$ 251.00 | 10% | \$227.59 |
| EW 4HR AHR 16503T | 97007-16503T | \$ 317.00 | 10% | \$287.44 |
| EW 4HR AHR Summit 16504 | 97007-16504 | \$ 404.00 | 10% | \$366.33 |
| EW 4HR AHR 16504T | 97007-16504T | \$ 479.00 | 10% | \$434.33 |
| EW 4HR AHR Summit 16505 | 97007-16505 | \$ 447.00 | 10% | \$405.32 |
| EW 4HR AHR 16505T | 97007-16505T | \$ 536.00 | 10% | \$486.02 |
| EW 4HR AHR Summit 16506 | 97007-16506 | \$ 684.00 | 10% | \$620.22 |
| EW 4HR AHR 16506T | 97007-16506T | \$ 837.00 | 10% | \$758.95 |
| EW 4HR AHR Summit 16507 | 97007-16507 | \$ 617.00 | 10% | \$559.46 |
| EW 4HR AHR 16507T | 97007-16507T | \$ 749.00 | 10% | \$679.16 |
| EW 4HR AHR Summit 16508 | 97007-16508 | \$ 779.00 | 10% | \$706.36 |
| EW 4HR AHR 16508T | 97007-16508T | \$ 941.00 | 10% | \$853.25 |
| EW 4HR AHR Summit 16509 | 97007-16509 | \$ 779.00 | 10% | \$706.36 |
| EW 4HR AHR 16509T | 97007-16509T | \$ 941.00 | 10% | \$853.25 |
| EW 4HR AHR Summit 16510 | 97007-16510 | \$ 941.00 | 10% | \$853.25 |
| EW 4HR AHR 16510T | 97007-16510T | \$ 1,123.00 | 10% | \$1,018.28 |

| | | | | |
|--------------------|--------------|-----------|-----|----------|
| EW 4hr AHR-16513 | 97007-16513 | \$ 558.00 | 10% | \$505.97 |
| EW 4hr AHR-16514 | 97007-16514 | \$ 921.00 | 10% | \$835.12 |
| EW 4HR AHR 16515 | 97007-16515 | \$ 160.00 | 10% | \$145.08 |
| EW 4hr AHR-16516 | 97007-16516 | \$ 173.00 | 10% | \$156.87 |
| EW 4HR AHR 16517 | 97007-16517 | \$ 331.00 | 10% | \$300.13 |
| EW 4hr AHR-16518 | 97007-16518 | \$ 297.00 | 10% | \$269.30 |
| EW-4HR AHR 16519 | 97007-16519 | \$ 317.00 | 10% | \$287.44 |
| EW-4HR AHR 16520 | 97007-16520 | \$ 499.00 | 10% | \$452.47 |
| EW 4HR AHR 16530 | 97007-16530 | \$ 183.00 | 10% | \$165.94 |
| EW 4HR AHR 16531 | 97007-16531 | \$ 260.00 | 10% | \$235.76 |
| EW 4HR AHR 16531T | 97007-16531T | \$ 283.00 | 10% | \$256.61 |
| EW 4HR AHR 16532 | 97007-16532 | \$ 260.00 | 10% | \$235.76 |
| EW 4HR AHR 16532T | 97007-16532T | \$ 283.00 | 10% | \$256.61 |
| EW 4HR AHR 16533 | 97007-16533 | \$ 351.00 | 10% | \$318.27 |
| EW 4HR AHR 16533T | 97007-16533T | \$ 397.00 | 10% | \$359.98 |
| EW 4HR AHR 16534 | 97007-16534 | \$ 372.00 | 10% | \$337.31 |
| EW 4HR AHR 16535 | 97007-16535 | \$ 563.00 | 10% | \$510.50 |
| EW 4HR AHR 16535A | 97007-16535A | \$ 563.00 | 10% | \$510.50 |
| EW 4HR AHR 16535T | 97007-16535T | \$ 631.00 | 10% | \$572.16 |
| EW 4HR AHR 16536 | 97007-16536 | \$ 263.00 | 10% | \$238.48 |
| EW 4HR AHR 16537 | 97007-16537 | \$ 361.00 | 10% | \$327.34 |
| EW 4HR AHR 16538 | 97007-16538 | \$ 428.00 | 10% | \$388.09 |
| EW 4HR AHR 16538T | 97007-16538T | \$ 516.00 | 10% | \$467.88 |
| EW 4HR AHR 16539 | 97007-16539 | \$ 553.00 | 10% | \$501.43 |
| EW 4HR AHR 16540 | 97007-16540 | \$ 400.00 | 10% | \$362.70 |
| EW 4HR AHR 16541 | 97007-16541 | \$ 153.00 | 10% | \$138.73 |
| EW 4HR AHR 16560 | 97007-16560 | \$ 90.00 | 10% | \$81.61 |
| EW 4HR AHR 16561 | 97007-16561 | \$ 123.00 | 10% | \$111.53 |
| EW 4HR AHR 16562 | 97007-16562 | \$ 151.00 | 10% | \$136.92 |
| EW 4HR AHR 16563 | 97007-16563 | \$ 197.00 | 10% | \$178.63 |
| EW 4HR AHR 16564 | 97007-16564 | \$ 246.00 | 10% | \$223.06 |
| EW 4HR AHR 16565 | 97007-16565 | \$ 374.00 | 10% | \$339.12 |
| EW 4HR AHR 16566 | 97007-16566 | \$ 55.00 | 10% | \$49.87 |
| EW 4HR AHR 16567 | 97007-16567 | \$ 103.00 | 10% | \$93.40 |
| EW 4HR AHR 16568 | 97007-16568 | \$ 90.00 | 10% | \$81.61 |
| EW 4HR AHR 16569 | 97007-16569 | \$ 136.00 | 10% | \$123.32 |
| EW 4HR AHR 16570 | 97007-16570 | \$ 151.00 | 10% | \$136.92 |
| EW 4HR AHR 16571 | 97007-16571 | \$ 246.00 | 10% | \$223.06 |
| EW 4HR AHR 16701 | 97007-16701 | \$ 546.00 | 10% | \$495.09 |
| EW 4HR AHR 16702 | 97007-16702 | \$ 801.00 | 10% | \$726.31 |
| EW 4HR AHR 16703 | 97007-16703 | \$ 634.00 | 10% | \$574.88 |
| EW 4HR AHR -16703T | 97007-16703T | \$ 768.00 | 10% | \$696.38 |

| | | | | |
|-------------------------|--------------|-------------|-----|------------|
| EW 4HR AHR 16704 | 97007-16704 | \$ 935.00 | 10% | \$847.81 |
| EW 4HR AHR -16704T | 97007-16704T | \$ 1,121.00 | 10% | \$1,016.47 |
| EW 4HR AHR 16705 | 97007-16705 | \$ 801.00 | 10% | \$726.31 |
| EW 4HR AHR -16705T | 97007-16705T | \$ 978.00 | 10% | \$886.80 |
| EW 4HR AHR 16706 | 97007-16706 | \$ 1,238.00 | 10% | \$1,122.56 |
| EW 4HR AHR -16706T | 97007-16706T | \$ 1,487.00 | 10% | \$1,348.34 |
| EW 4HR AHR 16710 | 97007-16710 | \$ 246.00 | 10% | \$223.06 |
| EW 4HR AHR 16710T | 97007-16710T | \$ 293.00 | 10% | \$265.68 |
| EW 4HR AHR 16711 | 97007-16711 | \$ 99.00 | 10% | \$89.77 |
| EW 4HR AHR 16711T | 97007-16711T | \$ 121.00 | 10% | \$109.72 |
| EW 4HR AHR 16712 | 97007-16712 | \$ 142.00 | 10% | \$128.76 |
| EW 4HR AHR 16712T | 97007-16712T | \$ 166.00 | 10% | \$150.52 |
| EW 4HR AHR 16713 | 97007-16713 | \$ 59.00 | 10% | \$53.50 |
| EW 4HR AHR 16713T | 97007-16713T | \$ 75.00 | 10% | \$68.01 |
| EW 4HR AHR 16715 | 97007-16715 | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR 16715T | 97007-16715T | \$ 121.00 | 10% | \$109.72 |
| EW 4HR AHR 16716 | 97007-16716 | \$ 435.00 | 10% | \$394.44 |
| EW 4HR AHR -16716T | 97007-16716T | \$ 514.00 | 10% | \$466.07 |
| EW 4HR AHR 16717 | 97007-16717 | \$ 649.00 | 10% | \$588.48 |
| EW 4HR AHR 16718 | 97007-16718 | \$ 465.00 | 10% | \$421.64 |
| EW 4HR AHR -16718T | 97007-16718T | \$ 553.00 | 10% | \$501.43 |
| EW 4HR AHR 16719 | 97007-16719 | \$ 691.00 | 10% | \$626.56 |
| EW 4HR AHR -16719T | 97007-16719T | \$ 826.00 | 10% | \$748.98 |
| EW 4HR AHR 16720 | 97007-16720 | \$ 1,037.00 | 10% | \$940.30 |
| EW 4HR AHR 16720T | 97007-16720T | \$ 1,206.00 | 10% | \$1,093.54 |
| EW 4HR AHR 16756 | 97007-16756 | \$ 752.00 | 10% | \$681.88 |
| EW 4HR AHR 16756T | 97007-16756T | \$ 884.00 | 10% | \$801.57 |
| EW 4HR AHR 16757 | 97007-16757 | \$ 714.00 | 10% | \$647.42 |
| EW 4HR AHR 16757T | 97007-16757T | \$ 848.00 | 10% | \$768.92 |
| EW 4HR AHR 16790 | 97007-16790 | \$ 1,663.00 | 10% | \$1,507.93 |
| EW 4HR AHR 16791 | 97007-16791 | \$ 2,146.00 | 10% | \$1,945.89 |
| EW 4HR AHR 16801 | 97007-16801 | \$ 217.00 | 10% | \$196.76 |
| EW 4HR AHR 16802 | 97007-16802 | \$ 245.00 | 10% | \$222.15 |
| EW 4HR AHR 16803 | 97007-16803 | \$ 265.00 | 10% | \$240.29 |
| EW 4HR AHR 16804 | 97007-16804 | \$ 320.00 | 10% | \$290.16 |
| EW 4HR AHR 16805 | 97007-16805 | \$ 70.00 | 10% | \$63.47 |
| EW 4HR AHR 16806 | 97007-16806 | \$ 55.00 | 10% | \$49.87 |
| EW 4HR AHR Summit 17101 | 97007-17101 | \$ 3,156.00 | 10% | \$2,861.70 |
| EW 4HR AHR 17101T | 97007-17101T | \$ 4,029.00 | 10% | \$3,653.30 |
| EW 4HR AHR Summit 17102 | 97007-17102 | \$ 3,156.00 | 10% | \$2,861.70 |
| EW 4HR AHR 17102T | 97007-17102T | \$ 4,029.00 | 10% | \$3,653.30 |
| EW 4HR AHR Summit 17103 | 97007-17103 | \$ 2,197.00 | 10% | \$1,992.13 |

| | | | | |
|--------------------------|--------------|-------------|-----|------------|
| EW 4HR AHR Summit 17103C | 97007-17103C | \$ 2,132.00 | 10% | \$1,933.19 |
| EW 4HR AHR 17103T | 97007-17103T | \$ 2,811.00 | 10% | \$2,548.87 |
| EW 4HR AHR Summit 17104 | 97007-17104 | \$ 2,197.00 | 10% | \$1,992.13 |
| EW 4HR AHR 17104T | 97007-17104T | \$ 2,811.00 | 10% | \$2,548.87 |
| EW 4HR AHR Summit 17121 | 97007-17121 | \$ 625.00 | 10% | \$566.72 |
| EW 4HR AHR Summit 17122 | 97007-17122 | \$ 392.00 | 10% | \$355.45 |
| EW 4HR AHR -17200 | 97007-17200 | \$ 4,968.00 | 10% | \$4,504.73 |
| EW 4HR AHR 17200T | 97007-17200T | \$ 5,682.00 | 10% | \$5,152.15 |
| EW 4HR AHR Summit 17201 | 97007-17201 | \$ 4,968.00 | 10% | \$4,504.73 |
| EW 4HR AHR 17201T | 97007-17201T | \$ 5,682.00 | 10% | \$5,152.15 |
| EW 4HR AHR Summit 17202 | 97007-17202 | \$ 4,968.00 | 10% | \$4,504.73 |
| EW 4HR AHR 17202T | 97007-17202T | \$ 5,682.00 | 10% | \$5,152.15 |
| EW 4HR AHR Summit 17203 | 97007-17203 | \$ 5,043.00 | 10% | \$4,572.74 |
| EW 4HR AHR 17203T | 97007-17203T | \$ 5,771.00 | 10% | \$5,232.85 |
| EW 4HR AHR Summit 17204 | 97007-17204 | \$ 5,043.00 | 10% | \$4,572.74 |
| EW 4HR AHR 17204T | 97007-17204T | \$ 5,771.00 | 10% | \$5,232.85 |
| EW 4HR AHR Summit 17205 | 97007-17205 | \$ 5,011.00 | 10% | \$4,543.72 |
| EW 4HR AHR 17205T | 97007-17205T | \$ 5,719.00 | 10% | \$5,185.70 |
| EW 4HR AHR Summit 17206 | 97007-17206 | \$ 5,011.00 | 10% | \$4,543.72 |
| EW 4HR AHR 17206T | 97007-17206T | \$ 5,719.00 | 10% | \$5,185.70 |
| EW 4HR AHR 17300 | 97007-17300 | \$ 3,282.00 | 10% | \$2,975.95 |
| EW 4HR AHR 17310 | 97007-17310 | \$ 2,978.00 | 10% | \$2,700.30 |
| EW 4HR AHR -17310T | 97007-17310T | \$ 3,582.00 | 10% | \$3,247.98 |
| EW 4HR AHR 17350 | 97007-17350 | \$ 3,008.00 | 10% | \$2,727.50 |
| EW 4HR AHR 17360 | 97007-17360 | \$ 3,702.00 | 10% | \$3,356.79 |
| EW 4HR AHR 17401 | 97007-17401 | \$ 461.00 | 10% | \$418.01 |
| EW 4HR AHR 17401G | 97007-17401G | \$ 545.00 | 10% | \$494.18 |
| EW 4HR AHR 17401T | 97007-17401T | \$ 517.00 | 10% | \$468.79 |
| EW 4HR AHR 17402 | 97007-17402 | \$ 664.00 | 10% | \$602.08 |
| EW 4HR AHR 17402G | 97007-17402G | \$ 728.00 | 10% | \$660.11 |
| EW 4HR AHR 17402T | 97007-17402T | \$ 692.00 | 10% | \$627.47 |
| EW 4HR AHR 17403 | 97007-17403 | \$ 709.00 | 10% | \$642.89 |
| EW 4HR AHR 17404 | 97007-17404 | \$ 333.00 | 10% | \$301.95 |
| EW 4HR AHR 17405 | 97007-17405 | \$ 429.00 | 10% | \$389.00 |
| EW 4HR AHR 17700 | 97007-17700 | \$ 5,825.00 | 10% | \$5,281.82 |
| EW 4HR AHR 17701 | 97007-17701 | \$ 5,149.00 | 10% | \$4,668.86 |
| EW 4HR AHR 17702 | 97007-17702 | \$ 5,149.00 | 10% | \$4,668.86 |
| EW 4HR AHR 17703 | 97007-17703 | \$ 5,643.00 | 10% | \$5,116.79 |
| EW 4HR AHR 17704 | 97007-17704 | \$ 5,643.00 | 10% | \$5,116.79 |
| EW 4HR AHR 17705 | 97007-17705 | \$ 5,185.00 | 10% | \$4,701.50 |
| EW 4HR AHR 17706 | 97007-17706 | \$ 5,185.00 | 10% | \$4,701.50 |
| EW 4HR AHR 17800 | 97007-17800 | \$ 5,828.00 | 10% | \$5,284.54 |

| | | | | |
|----------------------|-----------------|-------------|-----|------------|
| EW 4HR AHR 17810 | 97007-17810 | \$ 4,661.00 | 10% | \$4,226.36 |
| EW 4HR AHR 18101 | 97007-18101 | \$ 297.00 | 10% | \$269.30 |
| EW 4HR AHR 18102 | 97007-18102 | \$ 378.00 | 10% | \$342.75 |
| EW 4HR AHR 18103 | 97007-18103 | \$ 417.00 | 10% | \$378.11 |
| EW 4HR AHR 18104 | 97007-18104 | \$ 597.00 | 10% | \$541.33 |
| EW 4HR AHR 18104-6PK | 97007-18104-6PK | \$ 3,466.00 | 10% | \$3,142.80 |
| EW 4HR AHR 18202 | 97007-18202 | \$ 223.00 | 10% | \$202.21 |
| EW 4HR AHR 30135 | 97007-30135 | \$ 921.00 | 10% | \$835.12 |
| EW 4HR AHR 30136 | 97007-30136 | \$ 6,995.00 | 10% | \$6,342.72 |
| EW 4HR AHR 30137 | 97007-30137 | \$ 1,148.00 | 10% | \$1,040.95 |
| EW 4HR AHR 30138 | 97007-30138 | \$ 5,283.00 | 10% | \$4,790.36 |
| EW 4HR AHR 30139 | 97007-30139 | \$ 9,661.00 | 10% | \$8,760.11 |
| EW 4HR AHR 30912 | 97007-30912 | \$ 59.00 | 10% | \$53.50 |
| EW 4HR AHR 30913 | 97007-30913 | \$ 59.00 | 10% | \$53.50 |
| EW 4HR AHR 31012 | 97007-31012 | \$ 149.00 | 10% | \$135.11 |
| EW 4HR AHR 31013 | 97007-31013 | \$ 149.00 | 10% | \$135.11 |
| EW 4HR AHR 31014 | 97007-31014 | \$ 149.00 | 10% | \$135.11 |
| EW 4HR AHR 31015 | 97007-31015 | \$ 149.00 | 10% | \$135.11 |
| EW 4HR AHR 31016 | 97007-31016 | \$ 335.00 | 10% | \$303.76 |
| EW 4HR AHR 31017 | 97007-31017 | \$ 335.00 | 10% | \$303.76 |
| EW 4HR AHR 31018 | 97007-31018 | \$ 387.00 | 10% | \$350.91 |
| EW 4HR AHR 31019 | 97007-31019 | \$ 387.00 | 10% | \$350.91 |
| EW 4HR AHR 31025 | 97007-31025 | \$ 64.00 | 10% | \$58.03 |
| EW 4HR AHR 31026 | 97007-31026 | \$ 64.00 | 10% | \$58.03 |
| EW 4HR AHR 31028 | 97007-31028 | \$ 66.00 | 10% | \$59.85 |
| EW 4HR AHR 31029 | 97007-31029 | \$ 75.00 | 10% | \$68.01 |
| EW 4HR AHR 31031 | 97007-31031 | \$ 86.00 | 10% | \$77.98 |
| EW 4HR AHR 31032 | 97007-31032 | \$ 86.00 | 10% | \$77.98 |
| EW 4HR AHR 31034 | 97007-31034 | \$ 141.00 | 10% | \$127.85 |
| EW 4HR AHR 31035 | 97007-31035 | \$ 141.00 | 10% | \$127.85 |
| EW 4HR AHR 31050 | 97007-31050 | \$ 133.00 | 10% | \$120.60 |
| EW 4HR AHR 31051 | 97007-31051 | \$ 133.00 | 10% | \$120.60 |
| EW 4HR AHR 31055 | 97007-31055 | \$ 133.00 | 10% | \$120.60 |
| EW 4HR AHR 31056 | 97007-31056 | \$ 133.00 | 10% | \$120.60 |
| EW 4HR AHR 37101 | 97007-37101 | \$ 58.00 | 10% | \$52.59 |
| EW 4HR AHR 37102 | 97007-37102 | \$ 58.00 | 10% | \$52.59 |
| EW 4HR AHR 37103 | 97007-37103 | \$ 58.00 | 10% | \$52.59 |
| EW 4HR AHR 37111 | 97007-37111 | \$ 68.00 | 10% | \$61.66 |
| EW 4HR AHR 37112 | 97007-37112 | \$ 68.00 | 10% | \$61.66 |
| EW 4HR AHR 37113 | 97007-37113 | \$ 89.00 | 10% | \$80.70 |
| EW 4HR AHR 37114 | 97007-37114 | \$ 89.00 | 10% | \$80.70 |

| | | | | |
|-------------------------|--------------------|-------------|-----|-------------------|
| EW 4HR AHR 37115 | 97007-37115 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW 4HR AHR 37116 | 97007-37116 | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR 37117 | 97007-37117 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW 4HR AHR 37121 | 97007-37121 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 37122 | 97007-37122 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 37123 | 97007-37123 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 37124 | 97007-37124 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 37125 | 97007-37125 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 37126 | 97007-37126 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 37129 | 97007-37129 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 37130 | 97007-37130 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR AHR 39031 | 97007-39031 | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW 4HR AHR 39032 | 97007-39032 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW 4HR AHR 39033 | 97007-39033 | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW 4HR AHR 39034 | 97007-39034 | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW 4HR AHR 39035 | 97007-39035 | \$ 1,052.00 | 10% | <i>\$953.90</i> |
| EW 4HR AHR 39036 | 97007-39036 | \$ 132.00 | 10% | <i>\$119.69</i> |
| EW 4HR AHR 39037 | 97007-39037 | \$ 132.00 | 10% | <i>\$119.69</i> |
| EW 4HR AHR 39038 | 97007-39038 | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW 4HR AHR 39039 | 97007-39039 | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW 4HR AHR 39505 | 97007-39505 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR AHR 4120-24MW-4Y | 97007-4120-24MW-4Y | \$ 877.00 | 10% | <i>\$795.22</i> |
| EW 4HR AHR 4120-48MW-4Y | 97007-4120-48MW-4Y | \$ 1,170.00 | 10% | <i>\$1,060.90</i> |
| EW 4HR AHR 4120C | 97007-4120C | \$ 6,502.00 | 10% | <i>\$5,895.69</i> |
| EW 4HR AHR 4120C-1 | 97007-4120C-1 | \$ 7,339.00 | 10% | <i>\$6,654.64</i> |
| EW 4HR AHR 41216 | 97007-41216 | \$ 1,994.00 | 10% | <i>\$1,808.06</i> |
| EW 4HR AHR 4220-12P-4X | 97007-4220-12P-4X | \$ 255.00 | 10% | <i>\$231.22</i> |
| EW 4HR AHR 4220-12T-4X | 97007-4220-12T-4X | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR 4220-24P-4X | 97007-4220-24P-4X | \$ 340.00 | 10% | <i>\$308.30</i> |
| EW 4HR AHR 4220-24T-4X | 97007-4220-24T-4X | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW 4HR AHR 4220-48P-4X | 97007-4220-48P-4X | \$ 510.00 | 10% | <i>\$462.44</i> |
| EW 4HR AHR 4220-48T-4X | 97007-4220-48T-4X | \$ 382.00 | 10% | <i>\$346.38</i> |

| | | | | |
|--------------------------------|---------------------------|--------------|-----|-------------|
| EW 4HR AHR 4220-4MW-20P-4X | 97007-4220-4MW-20P-4X | \$ 467.00 | 10% | \$423.45 |
| EW 4HR AHR 4220-4MW-8P-4X | 97007-4220-4MW-8P-4X | \$ 331.00 | 10% | \$300.13 |
| EW 4HR AHR 4220-8MW-40P-4X | 97007-4220-8MW-40P-4X | \$ 680.00 | 10% | \$616.59 |
| EW 4HR AHR 4220-8X | 97007-4220-8X | \$ 357.00 | 10% | \$323.71 |
| EW 4HR AHR BD X 48001 | 97007-48001 | \$ 8,314.00 | 10% | \$7,538.72 |
| EW 4HR AHR 48038 | 97007-48038 | \$ 3,326.00 | 10% | \$3,015.85 |
| EW 4HR AHR 48039 | 97007-48039 | \$ 3,326.00 | 10% | \$3,015.85 |
| EW 4hr Parts only-48040 | 97007-48040 | \$ 3,203.00 | 10% | \$2,904.32 |
| EW 4HR AHR BD X 48041 | 97007-48041 | \$ 3,326.00 | 10% | \$3,015.85 |
| EW 4HR AHR BD X 48046 | 97007-48046 | \$ 4,370.00 | 10% | \$3,962.50 |
| EW 4HR AHR 48047 | 97007-48047 | \$ 11,645.00 | 10% | \$10,559.10 |
| EW 4HR AHR BD X 48051 | 97007-48051 | \$ 8,012.00 | 10% | \$7,264.88 |
| EW 4HR AHR 48061 | 97007-48061 | \$ 9,364.00 | 10% | \$8,490.81 |
| EW 4HR AHR 48062 | 97007-48062 | \$ 14,984.00 | 10% | \$13,586.74 |
| EW 4HR AHR 5320-16P-4XE | 97007-5320-16P-4XE | \$ 335.00 | 10% | \$303.76 |
| EW 4HR AHR 5320-16P-4XE-DC | 97007-5320-16P-4XE-DC | \$ 403.00 | 10% | \$365.42 |
| EW 4HR AHR 5320-24P-8XE | 97007-5320-24P-8XE | \$ 369.00 | 10% | \$334.59 |
| EW 4HR AHR 5320-24T-24S-4XE-XT | 97007-5320-24T-24S-4XE-XT | \$ 552.00 | 10% | \$500.53 |
| EW 4HR AHR 5320-24T-4X-XT | 97007-5320-24T-4X-XT | \$ 297.00 | 10% | \$269.30 |
| EW 4HR AHR 5320-24T-8XE | 97007-5320-24T-8XE | \$ 262.00 | 10% | \$237.57 |
| EW 4HR AHR 5320-48P-8XE | 97007-5320-48P-8XE | \$ 619.00 | 10% | \$561.28 |
| EW 4HR AHR 5320-48T-8XE | 97007-5320-48T-8XE | \$ 417.00 | 10% | \$378.11 |
| EW 4HR AHR 5420F-16MW-32P-4XE | 97007-5420F-16MW-32P-4XE | \$ 1,078.00 | 10% | \$977.48 |
| EW 4HR AHR 5420F-16W-32P-4XE | 97007-5420F-16W-32P-4XE | \$ 1,054.00 | 10% | \$955.71 |
| EW 4HR AHR 5420F-24P-4XE | 97007-5420F-24P-4XE | \$ 455.00 | 10% | \$412.57 |

| | | | | |
|-------------------------------|--------------------------|-------------|-----|-------------------|
| EW 4HR AHR 5420F-24S-4XE | 97007-5420F-24S-4XE | \$ 513.00 | 10% | <i>\$465.16</i> |
| EW 4HR AHR 5420F-24T-4XE | 97007-5420F-24T-4XE | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW 4HR AHR 5420F-48P-4XE | 97007-5420F-48P-4XE | \$ 682.00 | 10% | <i>\$618.40</i> |
| EW 4HR AHR 5420F-48P-4XL | 97007-5420F-48P-4XL | \$ 825.00 | 10% | <i>\$748.07</i> |
| EW 4HR AHR 5420F-48T-4XE | 97007-5420F-48T-4XE | \$ 509.00 | 10% | <i>\$461.54</i> |
| EW 4HR AHR 5420F-8W-16P-4XE | 97007-5420F-8W-16P-4XE | \$ 534.00 | 10% | <i>\$484.20</i> |
| EW 4HR AHR 5420M-16MW-32P-4YE | 97007-5420M-16MW-32P-4YE | \$ 1,223.00 | 10% | <i>\$1,108.96</i> |
| EW 4HR AHR 5420M-24T-4YE | 97007-5420M-24T-4YE | \$ 528.00 | 10% | <i>\$478.76</i> |
| EW 4HR AHR 5420M-24W-4YE | 97007-5420M-24W-4YE | \$ 493.00 | 10% | <i>\$447.03</i> |
| EW 4HR AHR 5420M-48T-4YE | 97007-5420M-48T-4YE | \$ 721.00 | 10% | <i>\$653.77</i> |
| EW 4HR AHR 5420M-48W-4YE | 97007-5420M-48W-4YE | \$ 831.00 | 10% | <i>\$753.51</i> |
| EW 4HR AHR 5520-12MW-36W | 97007-5520-12MW-36W | \$ 1,289.00 | 10% | <i>\$1,168.80</i> |
| EW 4HR AHR 5520-24T | 97007-5520-24T | \$ 465.00 | 10% | <i>\$421.64</i> |
| EW 4HR AHR 5520-24T-ACDC-BASE | 97007-5520-24T-ACDC-BASE | \$ 465.00 | 10% | <i>\$421.64</i> |
| EW 4HR AHR 5520-24T-BASE | 97007-5520-24T-BASE | \$ 465.00 | 10% | <i>\$421.64</i> |
| EW 4HR AHR 5520-24W | 97007-5520-24W | \$ 708.00 | 10% | <i>\$641.98</i> |
| EW 4HR AHR 5520-24X | 97007-5520-24X | \$ 1,335.00 | 10% | <i>\$1,210.51</i> |
| EW 4HR AHR 5520-24X-ACDC-BASE | 97007-5520-24X-ACDC-BASE | \$ 1,335.00 | 10% | <i>\$1,210.51</i> |
| EW 4HR AHR 5520-24X-BASE | 97007-5520-24X-BASE | \$ 1,335.00 | 10% | <i>\$1,210.51</i> |

| | | | | |
|--------------------------------|---------------------------|-------------|-----|-------------------|
| EW 4HR AHR 5520-48SE | 97007-5520-48SE | \$ 1,376.00 | 10% | <i>\$1,247.69</i> |
| EW 4HR AHR 5520-48SE-ACDC-BASE | 97007-5520-48SE-ACDC-BASE | \$ 1,376.00 | 10% | <i>\$1,247.69</i> |
| EW 4HR AHR 5520-48SE-BASE | 97007-5520-48SE-BASE | \$ 1,376.00 | 10% | <i>\$1,247.69</i> |
| EW 4HR AHR 5520-48T | 97007-5520-48T | \$ 796.00 | 10% | <i>\$721.77</i> |
| EW 4HR AHR 5520-48T-ACDC-BASE | 97007-5520-48T-ACDC-BASE | \$ 796.00 | 10% | <i>\$721.77</i> |
| EW 4HR AHR 5520-48T-BASE | 97007-5520-48T-BASE | \$ 796.00 | 10% | <i>\$721.77</i> |
| EW 4HR AHR 5520-48W | 97007-5520-48W | \$ 1,036.00 | 10% | <i>\$939.39</i> |
| EW 4HR AHR 5720-24MW | 97007-5720-24MW | \$ 1,615.00 | 10% | <i>\$1,464.40</i> |
| EW 4HR AHR 5720-24MXW | 97007-5720-24MXW | \$ 2,185.00 | 10% | <i>\$1,981.25</i> |
| EW 4HR AHR 5720-48MW | 97007-5720-48MW | \$ 1,900.00 | 10% | <i>\$1,722.83</i> |
| EW 4HR AHR 5720-48MXW | 97007-5720-48MXW | \$ 2,755.00 | 10% | <i>\$2,498.10</i> |
| EW 4HR AHR 7520-48XT-6C | 97007-7520-48XT-6C | \$ 3,142.00 | 10% | <i>\$2,849.01</i> |
| EW 4HR AHR 7520-48XT-6C-AC-F | 97007-7520-48XT-6C-AC-F | \$ 3,142.00 | 10% | <i>\$2,849.01</i> |
| EW 4HR AHR 7520-48XT-6C-AC-R | 97007-7520-48XT-6C-AC-R | \$ 3,142.00 | 10% | <i>\$2,849.01</i> |
| EW 4HR AHR 7520-48Y-8C | 97007-7520-48Y-8C | \$ 2,932.00 | 10% | <i>\$2,658.59</i> |
| EW 4HR AHR 7520-48Y-8C-AC-F | 97007-7520-48Y-8C-AC-F | \$ 2,932.00 | 10% | <i>\$2,658.59</i> |
| EW 4HR AHR 7520-48Y-8C-AC-R | 97007-7520-48Y-8C-AC-R | \$ 2,932.00 | 10% | <i>\$2,658.59</i> |
| EW 4HR AHR 7520-48YE-8CE | 97007-7520-48YE-8CE | \$ 3,404.00 | 10% | <i>\$3,086.58</i> |
| EW 4HR AHR 7520-48YE-8CE-AC-F | 97007-7520-48YE-8CE-AC-F | \$ 3,404.00 | 10% | <i>\$3,086.58</i> |

| | | | | |
|-------------------------------|--------------------------|-------------|-----|------------|
| EW 4HR AHR 7520-48YE-8CE-AC-R | 97007-7520-48YE-8CE-AC-R | \$ 3,404.00 | 10% | \$3,086.58 |
| EW 4HR AHR 7720-32C | 97007-7720-32C | \$ 3,635.00 | 10% | \$3,296.04 |
| EW 4HR AHR 7720-32C-AC-F | 97007-7720-32C-AC-F | \$ 3,635.00 | 10% | \$3,296.04 |
| EW 4HR AHR 7720-32C-AC-R | 97007-7720-32C-AC-R | \$ 3,635.00 | 10% | \$3,296.04 |
| EW 4HR AHR 8520-48XT-6C | 97007-8520-48XT-6C | \$ 2,978.00 | 10% | \$2,700.30 |
| EW 4HR AHR 8520-48XT-6C-AC-F | 97007-8520-48XT-6C-AC-F | \$ 2,978.00 | 10% | \$2,700.30 |
| EW 4HR AHR 8520-48XT-6C-AC-R | 97007-8520-48XT-6C-AC-R | \$ 2,978.00 | 10% | \$2,700.30 |
| EW 4HR AHR 8520-48XT-6C-DC-F | 97007-8520-48XT-6C-DC-F | \$ 2,978.00 | 10% | \$2,700.30 |
| EW 4HR AHR 8520-48XT-6C-DC-R | 97007-8520-48XT-6C-DC-R | \$ 2,978.00 | 10% | \$2,700.30 |
| EW 4HR AHR 8520-48Y-8C | 97007-8520-48Y-8C | \$ 3,022.00 | 10% | \$2,740.20 |
| EW 4HR AHR 8520-48Y-8C-AC-F | 97007-8520-48Y-8C-AC-F | \$ 3,022.00 | 10% | \$2,740.20 |
| EW 4HR AHR 8520-48Y-8C-AC-R | 97007-8520-48Y-8C-AC-R | \$ 3,022.00 | 10% | \$2,740.20 |
| EW 4HR AHR 8520-48Y-8C-DC-F | 97007-8520-48Y-8C-DC-F | \$ 3,022.00 | 10% | \$2,740.20 |
| EW 4HR AHR 8520-48Y-8C-DC-R | 97007-8520-48Y-8C-DC-R | \$ 3,022.00 | 10% | \$2,740.20 |
| EW 4HR AHR 86100 | 97007-86100 | \$ 5,624.00 | 10% | \$5,099.56 |
| EW 4HR AHR 86101 | 97007-86101 | \$ 7,725.00 | 10% | \$7,004.64 |
| EW 4HR AHR 87100 | 97007-87100 | \$ 3,490.00 | 10% | \$3,164.56 |
| EW 4HR AHR 87101 | 97007-87101 | \$ 5,372.00 | 10% | \$4,871.06 |
| EW 4HR AHR 8720-32C | 97007-8720-32C | \$ 3,478.00 | 10% | \$3,153.68 |
| EW 4HR AHR 8720-32C-AC-F | 97007-8720-32C-AC-F | \$ 3,478.00 | 10% | \$3,153.68 |
| EW 4HR AHR 8720-32C-AC-R | 97007-8720-32C-AC-R | \$ 3,478.00 | 10% | \$3,153.68 |

| | | | | |
|--------------------------|---------------------|--------------|-----|--------------------|
| EW 4HR AHR 8720-32C-DC-F | 97007-8720-32C-DC-F | \$ 3,478.00 | 10% | <i>\$3,153.68</i> |
| EW 4HR AHR 8720-32C-DC-R | 97007-8720-32C-DC-R | \$ 3,478.00 | 10% | <i>\$3,153.68</i> |
| EW 4HR AHR 8806 | 97007-8806 | \$ 2,082.00 | 10% | <i>\$1,887.85</i> |
| EW 4HR AHR ASPEN | 97007-8810 | \$ 5,408.00 | 10% | <i>\$4,903.70</i> |
| EW 4HR AHR 88100 | 97007-88100 | \$ 6,343.00 | 10% | <i>\$5,751.52</i> |
| EW 4HR AHR 8820-40C | 97007-8820-40C | \$ 13,050.00 | 10% | <i>\$11,833.09</i> |
| EW 4HR AHR 8820-40C-AC-F | 97007-8820-40C-AC-F | \$ 13,050.00 | 10% | <i>\$11,833.09</i> |
| EW 4HR AHR 8820-40C-AC-R | 97007-8820-40C-AC-R | \$ 13,050.00 | 10% | <i>\$11,833.09</i> |
| EW 4HR AHR 8820-40C-DC-F | 97007-8820-40C-DC-F | \$ 13,050.00 | 10% | <i>\$11,833.09</i> |
| EW 4HR AHR 8820-40C-DC-R | 97007-8820-40C-DC-R | \$ 13,050.00 | 10% | <i>\$11,833.09</i> |
| EW 4HR AHR 8820-80C | 97007-8820-80C | \$ 23,794.00 | 10% | <i>\$21,575.21</i> |
| EW 4HR AHR 8820-80C-AC-F | 97007-8820-80C-AC-F | \$ 23,794.00 | 10% | <i>\$21,575.21</i> |
| EW 4HR AHR 8820-80C-AC-R | 97007-8820-80C-AC-R | \$ 23,794.00 | 10% | <i>\$21,575.21</i> |
| EW 4HR AHR 8820-80C-DC-F | 97007-8820-80C-DC-F | \$ 23,794.00 | 10% | <i>\$21,575.21</i> |
| EW 4HR AHR 8820-80C-DC-R | 97007-8820-80C-DC-R | \$ 23,794.00 | 10% | <i>\$21,575.21</i> |
| EW 4HR AHR 9920-16C | 97007-9920-16C | \$ 10,222.00 | 10% | <i>\$9,268.80</i> |
| EW 4HR AHR 9920-4D | 97007-9920-4D | \$ 10,222.00 | 10% | <i>\$9,268.80</i> |
| EW 4HR AHR 9920-NPB-8 | 97007-9920-NPB-8 | \$ 16,328.00 | 10% | <i>\$14,805.41</i> |
| EW 4hr AHR | 97007-A10148 | \$ 3,155.00 | 10% | <i>\$2,860.80</i> |
| EW 4hr AHR | 97007-A10149 | \$ 6,027.00 | 10% | <i>\$5,464.98</i> |
| EW 4hr AHR | 97007-A10152 | \$ 6,027.00 | 10% | <i>\$5,464.98</i> |
| EW 4hr AHR | 97007-A10154 | \$ 18,356.00 | 10% | <i>\$16,644.30</i> |
| EW 4hr AHR | 97007-A10155 | \$ 6,501.00 | 10% | <i>\$5,894.78</i> |
| EW 4hr AHR | 97007-A10157 | \$ 11,464.00 | 10% | <i>\$10,394.98</i> |
| EW 4HR AHR 10175 | 97007-A10175 | \$ 7,644.00 | 10% | <i>\$6,931.20</i> |
| EW 4HR AHR A10176 | 97007-A10176 | \$ 11,467.00 | 10% | <i>\$10,397.70</i> |

| | | | | |
|------------------------------|-------------------------|-----------|-----|-----------------|
| EW 4HR AHR AH-AP-1130-AC-CE | 97007-AH-AP-1130-AC-CE | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR AHR AH-AP-1130-AC-FCC | 97007-AH-AP-1130-AC-FCC | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR AHR AH-AP-1130-AC-W | 97007-AH-AP-1130-AC-W | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR AHR AH-AP-122-AC-CAN | 97007-AH-AP-122-AC-CAN | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-122-AC-CE | 97007-AH-AP-122-AC-CE | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-122-AC-FCC | 97007-AH-AP-122-AC-FCC | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-122-AC-W | 97007-AH-AP-122-AC-W | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-130-AC-CE | 97007-AH-AP-130-AC-CE | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-130-AC-FCC | 97007-AH-AP-130-AC-FCC | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-130-AC-W | 97007-AH-AP-130-AC-W | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-150W-AC-CAN | 97007-AH-AP-150W-AC-CAN | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-150W-AC-CE | 97007-AH-AP-150W-AC-CE | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-150W-AC-FCC | 97007-AH-AP-150W-AC-FCC | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-150W-AC-W | 97007-AH-AP-150W-AC-W | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-230-AC-CE | 97007-AH-AP-230-AC-CE | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-230-AC-FCC | 97007-AH-AP-230-AC-FCC | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-230-AC-W | 97007-AH-AP-230-AC-W | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-250-AC-CAN | 97007-AH-AP-250-AC-CAN | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-250-AC-CE | 97007-AH-AP-250-AC-CE | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-250-AC-FCC | 97007-AH-AP-250-AC-FCC | \$ 83.00 | 10% | <i>\$75.26</i> |

| | | | | |
|------------------------------|-------------------------|-----------|-----|-----------------|
| EW 4HR AHR AH-AP-250-AC-W | 97007-AH-AP-250-AC-W | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-AP-630-AX-CAN | 97007-AH-AP-630-AX-CAN | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR AHR AH-AP-630-AX-CE | 97007-AH-AP-630-AX-CE | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR AHR AH-AP-630-AX-FCC | 97007-AH-AP-630-AX-FCC | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR AHR AH-AP-630-AX-W | 97007-AH-AP-630-AX-W | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR AHR AH-AP-650-AX-CAN | 97007-AH-AP-650-AX-CAN | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-AP-650-AX-CE | 97007-AH-AP-650-AX-CE | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-AP-650-AX-FCC | 97007-AH-AP-650-AX-FCC | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-AP-650-AX-W | 97007-AH-AP-650-AX-W | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-AP-650X-AX-CAN | 97007-AH-AP-650X-AX-CAN | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-AP-650X-AX-CE | 97007-AH-AP-650X-AX-CE | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-AP-650X-AX-FCC | 97007-AH-AP-650X-AX-FCC | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-AP-650X-AX-W | 97007-AH-AP-650X-AX-W | \$ 126.00 | 10% | <i>\$114.25</i> |
| EW 4HR AHR AH-ATOM-CAN | 97007-AH-ATOM-CAN | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR AH-ATOM-CE-EU | 97007-AH-ATOM-CE-EU | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW 4HR AHR AH-ATOM-CE-UK | 97007-AH-ATOM-CE-UK | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW 4HR AHR AH-ATOM-FCC | 97007-AH-ATOM-FCC | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR AH-ATOM-W | 97007-AH-ATOM-W | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR AH-ATOM-W-EU | 97007-AH-ATOM-W-EU | \$ 88.00 | 10% | <i>\$79.79</i> |

| | | | | |
|---------------------------|----------------------|-----------|-----|-----------------|
| EW 4HR AHR AH-ATOM-W-UK | 97007-AH-ATOM-W-UK | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW 4HR AHR AH-SR-2208P-AU | 97007-AH-SR-2208P-AU | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-SR-2208P-EU | 97007-AH-SR-2208P-EU | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-SR-2208P-NA | 97007-AH-SR-2208P-NA | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-SR-2208P-UK | 97007-AH-SR-2208P-UK | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-SR-2224P-AU | 97007-AH-SR-2224P-AU | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR AHR AH-SR-2224P-EU | 97007-AH-SR-2224P-EU | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR AHR AH-SR-2224P-NA | 97007-AH-SR-2224P-NA | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR AHR AH-SR-2224P-UK | 97007-AH-SR-2224P-UK | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR AHR AH-SR-2324P-AU | 97007-AH-SR-2324P-AU | \$ 173.00 | 10% | <i>\$156.87</i> |
| EW 4HR AHR AH-SR-2324P-EU | 97007-AH-SR-2324P-EU | \$ 173.00 | 10% | <i>\$156.87</i> |
| EW 4HR AHR AH-SR-2324P-NA | 97007-AH-SR-2324P-NA | \$ 173.00 | 10% | <i>\$156.87</i> |
| EW 4HR AHR AH-SR-2324P-UK | 97007-AH-SR-2324P-UK | \$ 173.00 | 10% | <i>\$156.87</i> |
| EW 4HR AHR AH-SR-2348P-AU | 97007-AH-SR-2348P-AU | \$ 301.00 | 10% | <i>\$272.93</i> |
| EW 4HR AHR AH-SR-2348P-EU | 97007-AH-SR-2348P-EU | \$ 301.00 | 10% | <i>\$272.93</i> |
| EW 4HR AHR AH-SR-2348P-NA | 97007-AH-SR-2348P-NA | \$ 301.00 | 10% | <i>\$272.93</i> |
| EW 4HR AHR AH-SR-2348P-UK | 97007-AH-SR-2348P-UK | \$ 301.00 | 10% | <i>\$272.93</i> |
| EW 4HR AHR AH-XR200P-AU | 97007-AH-XR200P-AU | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-XR200P-EU | 97007-AH-XR200P-EU | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-XR200P-UK | 97007-AH-XR200P-UK | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AH-XR200P-US | 97007-AH-XR200P-US | \$ 83.00 | 10% | <i>\$75.26</i> |

| | | | | |
|------------------------------|-------------------------|-----------|-----|-----------------|
| EW 4HR AHR AH-XR600P | 97007-AH-XR600P | \$ 91.00 | 10% | <i>\$82.51</i> |
| EW 4HR AHR AH-XR600P-AU | 97007-AH-XR600P-AU | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AH-XR600P-EU | 97007-AH-XR600P-EU | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AH-XR600P-KR | 97007-AH-XR600P-KR | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AH-XR600P-UK | 97007-AH-XR600P-UK | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AH-XR600P-US | 97007-AH-XR600P-US | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AP-8533-68SB30-IL | 97007-AP-8533-68SB30-IL | \$ 151.00 | 10% | <i>\$136.92</i> |
| EW 4HR AHR AP3000-IL | 97007-AP3000-IL | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW 4HR AHR AP3000-TN | 97007-AP3000-TN | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW 4HR AHR AP3000-WW | 97007-AP3000-WW | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW 4HR AHR AP3000X-WW | 97007-AP3000X-WW | \$ 80.50 | 10% | <i>\$72.99</i> |
| EW 4HR AHR AP302W-CAN | 97007-AP302W-CAN | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW 4HR AHR AP302W-EG | 97007-AP302W-EG | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW 4HR AHR AP302W-FCC | 97007-AP302W-FCC | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW 4HR AHR AP302W-WR | 97007-AP302W-WR | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW 4HR AHR AP305C-1-CAN | 97007-AP305C-1-CAN | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AP305C-1-EG | 97007-AP305C-1-EG | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AP305C-1-FCC | 97007-AP305C-1-FCC | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AP305C-1-IL | 97007-AP305C-1-IL | \$ 83.00 | 10% | <i>\$75.26</i> |

| | | | | |
|------------------------|-------------------|----------|-----|----------------|
| EW 4HR AHR AP305C-1-WR | 97007-AP305C-1-WR | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR AP305C-CAN | 97007-AP305C-CAN | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305C-EG | 97007-AP305C-EG | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305C-FCC | 97007-AP305C-FCC | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305C-IL | 97007-AP305C-IL | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305C-WR | 97007-AP305C-WR | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305CX-CAN | 97007-AP305CX-CAN | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305CX-FCC | 97007-AP305CX-FCC | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305CX-IL | 97007-AP305CX-IL | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP305CX-WR | 97007-AP305CX-WR | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR AP310e-1-WR | 97007-AP310e-1-WR | \$ 53.00 | 10% | <i>\$48.06</i> |
| EW 4HR AHR AP310e-CAN | 97007-AP310e-CAN | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW 4HR AHR AP310e-FCC | 97007-AP310e-FCC | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW 4HR AHR AP310e-IL | 97007-AP310e-IL | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW 4HR AHR AP310e-WR | 97007-AP310e-WR | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW 4HR AHR AP310i-1-WR | 97007-AP310i-1-WR | \$ 53.00 | 10% | <i>\$48.06</i> |
| EW 4HR AHR AP310i-CAN | 97007-AP310i-CAN | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW 4HR AHR AP310i-FCC | 97007-AP310i-FCC | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW 4HR AHR AP310i-IL | 97007-AP310i-IL | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW 4HR AHR AP310i-WR | 97007-AP310i-WR | \$ 56.00 | 10% | <i>\$50.78</i> |

| | | | | |
|-------------------------|--------------------|-----------|-----|----------------|
| EW 4HR AHR AP360e-CAN | 97007-AP360e-CAN | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR AHR AP360e-FCC | 97007-AP360e-FCC | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR AHR AP360e-IL | 97007-AP360e-IL | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR AHR AP360e-WR | 97007-AP360e-WR | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR AHR AP360i-CAN | 97007-AP360i-CAN | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR AHR AP360i-FCC | 97007-AP360i-FCC | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR AHR AP360i-WR | 97007-AP360i-WR | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR AHR AP4000-WW | 97007-AP4000-1-WW | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AP4000-IL | 97007-AP4000-IL | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AP4000-WW | 97007-AP4000-WW | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW 4HR AHR AP410C-1-CAN | 97007-AP410C-1-CAN | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW 4HR AHR AP410C-1-EG | 97007-AP410C-1-EG | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW 4HR AHR AP410C-1-FCC | 97007-AP410C-1-FCC | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW 4HR AHR AP410C-1-IL | 97007-AP410C-1-IL | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW 4HR AHR AP410C-1-WR | 97007-AP410C-1-WR | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW 4HR AHR AP410C-CAN | 97007-AP410C-CAN | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR AHR AP410C-EG | 97007-AP410C-EG | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR AHR AP410C-FCC | 97007-AP410C-FCC | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR AHR AP410C-IL | 97007-AP410C-IL | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR AHR AP410C-WR | 97007-AP410C-WR | \$ 101.00 | 10% | <i>\$91.58</i> |

| | | | | |
|-------------------------|--------------------|-----------|-----|----------|
| EW 4HR AHR AP410e-CAN | 97007-AP410e-CAN | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR AP410e-FCC | 97007-AP410e-FCC | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR AP410e-WR | 97007-AP410e-WR | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR AP410i-1-FCC | 97007-AP410i-1-FCC | \$ 92.00 | 10% | \$83.42 |
| EW 4HR AHR AP410i-1-WR | 97007-AP410i-1-WR | \$ 92.00 | 10% | \$83.42 |
| EW 4HR AHR AP410i-CAN | 97007-AP410i-CAN | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR AP410i-FCC | 97007-AP410i-FCC | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR AP410i-IL | 97007-AP410i-IL | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR AP410i-WR | 97007-AP410i-WR | \$ 97.00 | 10% | \$87.95 |
| EW 4HR AHR AP460C-CAN | 97007-AP460C-CAN | \$ 124.00 | 10% | \$112.44 |
| EW 4HR AHR AP460C-EG | 97007-AP460C-EG | \$ 124.00 | 10% | \$112.44 |
| EW 4HR AHR AP460C-FCC | 97007-AP460C-FCC | \$ 124.00 | 10% | \$112.44 |
| EW 4HR AHR AP460C-IL | 97007-AP460C-IL | \$ 124.00 | 10% | \$112.44 |
| EW 4HR AHR AP460C-WR | 97007-AP460C-WR | \$ 124.00 | 10% | \$112.44 |
| EW 4HR AHR AP460e-CAN | 97007-AP460e-CAN | \$ 115.00 | 10% | \$104.28 |
| EW 4HR AHR AP460e-FCC | 97007-AP460e-FCC | \$ 115.00 | 10% | \$104.28 |
| EW 4HR AHR AP460e-WR | 97007-AP460e-WR | \$ 110.00 | 10% | \$99.74 |
| EW 4HR AHR AP460i-CAN | 97007-AP460i-CAN | \$ 110.00 | 10% | \$99.74 |
| EW 4HR AHR AP460i-FCC | 97007-AP460i-FCC | \$ 110.00 | 10% | \$99.74 |
| EW 4HR AHR AP460i-IL | 97007-AP460i-IL | \$ 110.00 | 10% | \$99.74 |
| EW 4HR AHR AP460i-WR | 97007-AP460i-WR | \$ 110.00 | 10% | \$99.74 |

| | | | | |
|---------------------------|----------------------|-----------|-----|-----------------|
| EW 4HR AHR AP460S12C-CAN | 97007-AP460S12C-CAN | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW 4HR AHR AP460S12C-FCC | 97007-AP460S12C-FCC | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW 4HR AHR AP460S12C-WR | 97007-AP460S12C-WR | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW 4HR AHR AP460S6C-CAN | 97007-AP460S6C-CAN | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW 4HR AHR AP460S6C-FCC | 97007-AP460S6C-FCC | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW 4HR AHR AP460S6C-WR | 97007-AP460S6C-WR | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW 4HR AHR AP5010-IL | 97007-AP5010-IL | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW 4HR AHR AP5010-WW | 97007-AP5010-WW | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW 4HR AHR AP5020-WW | 97007-AP5020-WW | \$ 167.93 | 6% | <i>\$159.04</i> |
| EW 4HR AHR AP5050D-WW | 97007-AP5050D-WW | \$ 345.00 | 10% | <i>\$312.83</i> |
| EW 4HR AHR AP5050U-WW | 97007-AP5050U-WW | \$ 269.00 | 10% | <i>\$243.92</i> |
| EW 4HR AHR AP505i-FCC | 97007-AP505i-FCC | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR AP505i-FCC-TAA | 97007-AP505i-FCC-TAA | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR AP505i-WR | 97007-AP505i-WR | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR AHR AP510C-CAN | 97007-AP510C-CAN | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW 4HR AHR AP510C-CE | 97007-AP510C-CE | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW 4HR AHR AP510C-FCC | 97007-AP510C-FCC | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW 4HR AHR AP510C-W | 97007-AP510C-W | \$ 123.00 | 10% | <i>\$111.53</i> |

| | | | | |
|---------------------------|----------------------|-----------|-----|-----------------|
| EW 4HR AHR AP510C-WW | 97007-AP510C-WW | \$ 142.00 | 10% | <i>\$128.76</i> |
| EW 4HR AHR AP510CX-CAN | 97007-AP510CX-CAN | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW 4HR AHR AP510CX-CE | 97007-AP510CX-CE | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW 4HR AHR AP510CX-FCC | 97007-AP510CX-FCC | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW 4HR AHR AP510CX-W | 97007-AP510CX-W | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW 4HR AHR AP510CX-WW | 97007-AP510CX-WW | \$ 142.00 | 10% | <i>\$128.76</i> |
| EW 4HR AHR AP510e-FCC | 97007-AP510e-FCC | \$ 157.00 | 10% | <i>\$142.36</i> |
| EW 4HR AHR AP510e-FCC-TAA | 97007-AP510e-FCC-TAA | \$ 157.00 | 10% | <i>\$142.36</i> |
| EW 4HR AHR AP510e-WR | 97007-AP510e-WR | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW 4HR AHR AP510i-1-FCC | 97007-AP510i-1-FCC | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR AHR AP510i-1-WR | 97007-AP510i-1-WR | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR AHR AP510i-FCC | 97007-AP510i-FCC | \$ 138.00 | 10% | <i>\$125.13</i> |
| EW 4HR AHR AP510i-FCC-TAA | 97007-AP510i-FCC-TAA | \$ 138.00 | 10% | <i>\$125.13</i> |
| EW 4HR AHR AP510i-WR | 97007-AP510i-WR | \$ 138.00 | 10% | <i>\$125.13</i> |
| EW 4HR AHR AP560h-FCC | 97007-AP560h-FCC | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW 4HR AHR AP560h-WR | 97007-AP560h-WR | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW 4HR AHR AP560i-FCC | 97007-AP560i-FCC | \$ 257.00 | 10% | <i>\$233.03</i> |
| EW 4HR AHR AP560i-WR | 97007-AP560i-WR | \$ 245.00 | 10% | <i>\$222.15</i> |
| EW 4HR AHR AP560m-FCC | 97007-AP560m-FCC | \$ 257.00 | 10% | <i>\$233.03</i> |

| | | | | |
|-----------------------|------------------|-------------|-----|------------|
| EW 4HR AHR AP560t-FCC | 97007-AP560t-FCC | \$ 350.00 | 10% | \$317.36 |
| EW 4HR AHR AP560u-FCC | 97007-AP560u-FCC | \$ 239.00 | 10% | \$216.71 |
| EW 4HR AHR E2122 | 97007-E2122 | \$ 5,906.00 | 10% | \$5,355.27 |
| EW 4HR AHR E2122-1 | 97007-E2122-1 | \$ 5,598.00 | 10% | \$5,075.99 |
| EW 4HR AHR E3120-1 | 97007-E3120-1 | \$ 9,156.00 | 10% | \$8,302.20 |
| EW 4HR AHR E3125 | 97007-E3125 | \$ 9,884.00 | 10% | \$8,962.32 |
| EW 4hr AHR | 97007-H30078 | \$ 3,665.00 | 10% | \$3,323.24 |
| EW 4hr AHR | 97007-H30104 | \$ 3,385.00 | 10% | \$3,069.35 |
| EW 4hr AHR | 97007-H30105 | \$ 3,345.00 | 10% | \$3,033.08 |
| EW 4hr AHR | 97007-H30131 | \$ 1,922.00 | 10% | \$1,742.77 |
| EW 4hr AHR | 97007-H30132 | \$ 1,886.00 | 10% | \$1,710.13 |
| EW 4hr AHR | 97007-H30133 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30134 | \$ 6,254.00 | 10% | \$5,670.81 |
| EW 4hr AHR | 97007-H30135 | \$ 5,037.00 | 10% | \$4,567.30 |
| EW 4hr AHR | 97007-H30136 | \$ 6,254.00 | 10% | \$5,670.81 |
| EW 4hr AHR | 97007-H30184 | \$ 84.00 | 10% | \$76.17 |
| EW 4hr AHR | 97007-H30185 | \$ 448.00 | 10% | \$406.22 |
| EW 4hr AHR | 97007-H30186 | \$ 227.00 | 10% | \$205.83 |
| EW 4hr AHR | 97007-H30187 | \$ 91.00 | 10% | \$82.51 |
| EW 4hr AHR | 97007-H30188 | \$ 227.00 | 10% | \$205.83 |
| EW 4hr AHR | 97007-H30189 | \$ 227.00 | 10% | \$205.83 |
| EW 4hr AHR | 97007-H30190 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30214 | \$ 242.00 | 10% | \$219.43 |
| EW 4hr AHR | 97007-H30215 | \$ 242.00 | 10% | \$219.43 |
| EW 4hr AHR | 97007-H30216 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30217 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30218 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30219 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30220 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30221 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30222 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30223 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30224 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30225 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30226 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30227 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30228 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30229 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30267 | \$ 479.00 | 10% | \$434.33 |
| EW 4hr AHR | 97007-H30268 | \$ 479.00 | 10% | \$434.33 |

| | | | | |
|------------|--------------|-------------|-----|------------|
| EW 4hr AHR | 97007-H30269 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30270 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30271 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30272 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30273 | \$ 1,035.00 | 10% | \$938.49 |
| EW 4hr AHR | 97007-H30274 | \$ 1,035.00 | 10% | \$938.49 |
| EW 4hr AHR | 97007-H30275 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30276 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30277 | \$ 1,035.00 | 10% | \$938.49 |
| EW 4hr AHR | 97007-H30278 | \$ 1,139.00 | 10% | \$1,032.79 |
| EW 4hr AHR | 97007-H30279 | \$ 1,035.00 | 10% | \$938.49 |
| EW 4hr AHR | 97007-H30280 | \$ 1,035.00 | 10% | \$938.49 |
| EW 4hr AHR | 97007-H30281 | \$ 1,035.00 | 10% | \$938.49 |
| EW 4hr AHR | 97007-H30282 | \$ 1,035.00 | 10% | \$938.49 |
| EW 4hr AHR | 97007-H30283 | \$ 689.00 | 10% | \$624.75 |
| EW 4hr AHR | 97007-H30284 | \$ 758.00 | 10% | \$687.32 |
| EW 4hr AHR | 97007-H30293 | \$ 4,124.00 | 10% | \$3,739.44 |
| EW 4hr AHR | 97007-H30296 | \$ 242.00 | 10% | \$219.43 |
| EW 4hr AHR | 97007-H30297 | \$ 226.00 | 10% | \$204.93 |
| EW 4hr AHR | 97007-H30298 | \$ 242.00 | 10% | \$219.43 |
| EW 4hr AHR | 97007-H30299 | \$ 226.00 | 10% | \$204.93 |
| EW 4hr AHR | 97007-H30381 | \$ 677.00 | 10% | \$613.87 |
| EW 4hr AHR | 97007-H30384 | \$ 539.00 | 10% | \$488.74 |
| EW 4hr AHR | 97007-H30391 | \$ 1,286.00 | 10% | \$1,166.08 |
| EW 4hr AHR | 97007-H30392 | \$ 1,286.00 | 10% | \$1,166.08 |
| EW 4hr AHR | 97007-H30393 | \$ 581.00 | 10% | \$526.82 |
| EW 4hr AHR | 97007-H30394 | \$ 2,502.00 | 10% | \$2,268.69 |
| EW 4hr AHR | 97007-H30395 | \$ 2,979.00 | 10% | \$2,701.21 |
| EW 4hr AHR | 97007-H30396 | \$ 2,714.00 | 10% | \$2,460.92 |
| EW 4hr AHR | 97007-H30397 | \$ 3,214.00 | 10% | \$2,914.29 |
| EW 4hr AHR | 97007-H30398 | \$ 591.00 | 10% | \$535.89 |
| EW 4hr AHR | 97007-H30400 | \$ 335.00 | 10% | \$303.76 |
| EW 4hr AHR | 97007-H30401 | \$ 454.00 | 10% | \$411.66 |
| EW 4hr AHR | 97007-H30402 | \$ 489.00 | 10% | \$443.40 |
| EW 4hr AHR | 97007-H30403 | \$ 721.00 | 10% | \$653.77 |
| EW 4hr AHR | 97007-H30434 | \$ 193.00 | 10% | \$175.00 |
| EW 4hr AHR | 97007-H30480 | \$ 843.00 | 10% | \$764.39 |
| EW 4hr AHR | 97007-H30495 | \$ 1,922.00 | 10% | \$1,742.77 |
| EW 4hr AHR | 97007-H30496 | \$ 1,886.00 | 10% | \$1,710.13 |
| EW 4hr AHR | 97007-H30497 | \$ 2,769.00 | 10% | \$2,510.79 |
| EW 4hr AHR | 97007-H30498 | \$ 2,714.00 | 10% | \$2,460.92 |
| EW 4hr AHR | 97007-H30499 | \$ 925.00 | 10% | \$838.74 |

| | | | | |
|------------|--------------|--------------|-----|-------------|
| EW 4hr AHR | 97007-H30501 | \$ 2,714.00 | 10% | \$2,460.92 |
| EW 4hr AHR | 97007-H30502 | \$ 4,176.00 | 10% | \$3,786.59 |
| EW 4hr AHR | 97007-H30503 | \$ 925.00 | 10% | \$838.74 |
| EW 4hr AHR | 97007-H30505 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30506 | \$ 6,710.00 | 10% | \$6,084.29 |
| EW 4hr AHR | 97007-H30509 | \$ 4,176.00 | 10% | \$3,786.59 |
| EW 4hr AHR | 97007-H30510 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30511 | \$ 6,710.00 | 10% | \$6,084.29 |
| EW 4hr AHR | 97007-H30512 | \$ 925.00 | 10% | \$838.74 |
| EW 4hr AHR | 97007-H30513 | \$ 1,561.00 | 10% | \$1,415.44 |
| EW 4hr AHR | 97007-H30525 | \$ 6,710.00 | 10% | \$6,084.29 |
| EW 4hr AHR | 97007-H30526 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30528 | \$ 7,791.00 | 10% | \$7,064.49 |
| EW 4hr AHR | 97007-H30531 | \$ 11,099.00 | 10% | \$10,064.02 |
| EW 4hr AHR | 97007-H30532 | \$ 11,099.00 | 10% | \$10,064.02 |
| EW 4hr AHR | 97007-H30534 | \$ 11,313.00 | 10% | \$10,258.06 |
| EW 4hr AHR | 97007-H30535 | \$ 12,070.00 | 10% | \$10,944.47 |
| EW 4hr AHR | 97007-H30536 | \$ 11,099.00 | 10% | \$10,064.02 |
| EW 4hr AHR | 97007-H30537 | \$ 12,070.00 | 10% | \$10,944.47 |
| EW 4hr AHR | 97007-H30538 | \$ 6,710.00 | 10% | \$6,084.29 |
| EW 4hr AHR | 97007-H30539 | \$ 12,645.00 | 10% | \$11,465.85 |
| EW 4hr AHR | 97007-H30540 | \$ 13,333.00 | 10% | \$12,089.70 |
| EW 4hr AHR | 97007-H30543 | \$ 907.00 | 10% | \$822.42 |
| EW 4hr AHR | 97007-H30544 | \$ 1,621.00 | 10% | \$1,469.84 |
| EW 4hr AHR | 97007-H30548 | \$ 907.00 | 10% | \$822.42 |
| EW 4hr AHR | 97007-H30549 | \$ 1,533.00 | 10% | \$1,390.05 |
| EW 4hr AHR | 97007-H30550 | \$ 1,533.00 | 10% | \$1,390.05 |
| EW 4hr AHR | 97007-H30552 | \$ 907.00 | 10% | \$822.42 |
| EW 4hr AHR | 97007-H30553 | \$ 1,448.00 | 10% | \$1,312.97 |
| EW 4hr AHR | 97007-H30569 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30570 | \$ 5,916.00 | 10% | \$5,364.33 |
| EW 4hr AHR | 97007-H30571 | \$ 5,916.00 | 10% | \$5,364.33 |
| EW 4hr AHR | 97007-H30573 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30574 | \$ 5,463.00 | 10% | \$4,953.58 |
| EW 4hr AHR | 97007-H30575 | \$ 3,411.00 | 10% | \$3,092.92 |
| EW 4hr AHR | 97007-H30576 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30577 | \$ 5,916.00 | 10% | \$5,364.33 |
| EW 4hr AHR | 97007-H30578 | \$ 5,916.00 | 10% | \$5,364.33 |
| EW 4hr AHR | 97007-H30587 | \$ 5,037.00 | 10% | \$4,567.30 |
| EW 4hr AHR | 97007-H30588 | \$ 3,477.00 | 10% | \$3,152.77 |
| EW 4hr AHR | 97007-H30589 | \$ 5,380.00 | 10% | \$4,878.32 |
| EW 4hr AHR | 97007-H30632 | \$ 129.00 | 10% | \$116.97 |

| | | | | |
|----------------------------|--------------|--------------|-----|-------------|
| EW 4hr AHR | 97007-H30633 | \$ 129.00 | 10% | \$116.97 |
| EW 4hr AHR | 97007-H30643 | \$ 8,487.00 | 10% | \$7,695.59 |
| EW 4hr AHR | 97007-H30706 | \$ 7,942.00 | 10% | \$7,201.41 |
| EW 4hr AHR | 97007-H30707 | \$ 4,940.00 | 10% | \$4,479.35 |
| EW 4hr AHR | 97007-H30724 | \$ 539.00 | 10% | \$488.74 |
| EW 4hr AHR | 97007-H30725 | \$ 1,886.00 | 10% | \$1,710.13 |
| EW 4hr AHR | 97007-H30726 | \$ 12,303.00 | 10% | \$11,155.75 |
| EW 4hr AHR | 97007-H30727 | \$ 13,079.00 | 10% | \$11,859.38 |
| EW 4hr AHR | 97007-H30730 | \$ 65.00 | 10% | \$58.94 |
| EW 4hr AHR | 97007-H30731 | \$ 65.00 | 10% | \$58.94 |
| EW 4HR AHR 30732 | 97007-H30732 | \$ 2,146.00 | 10% | \$1,945.89 |
| EW 4HR AHR SKL8008-0810-F8 | 97007-H30733 | \$ 11,515.00 | 10% | \$10,441.23 |
| EW 4HR AHR STL2006-0850 | 97007-H30734 | \$ 8,789.00 | 10% | \$7,969.43 |
| EW 4HR AHR SGL2001-0850 | 97007-H30735 | \$ 10,238.00 | 10% | \$9,283.31 |
| EW 4HR AHR SOK2209-0204 | 97007-H30736 | \$ 1,602.00 | 10% | \$1,452.61 |
| EW 4HR AHR H30738 | 97007-H30738 | \$ 50.00 | 10% | \$45.34 |
| EW 4HR AHR -H30739 | 97007-H30739 | \$ 1,720.00 | 10% | \$1,559.61 |
| EW 4HR AHR -H30740 | 97007-H30740 | \$ 998.00 | 10% | \$904.94 |
| EW 4HR AHR -H30741 | 97007-H30741 | \$ 1,817.00 | 10% | \$1,647.56 |
| EW 4HR AHR -H30742 | 97007-H30742 | \$ 1,615.00 | 10% | \$1,464.40 |
| EW 4HR AHR -H30743 | 97007-H30743 | \$ 1,720.00 | 10% | \$1,559.61 |
| EW 4HR AHR -H30744 | 97007-H30744 | \$ 998.00 | 10% | \$904.94 |
| EW 4HR AHR -H30745 | 97007-H30745 | \$ 1,017.00 | 10% | \$922.16 |
| EW 4HR AHR -H30746 | 97007-H30746 | \$ 1,798.00 | 10% | \$1,630.34 |
| EW 4HR AHR -H30747 | 97007-H30747 | \$ 3,584.00 | 10% | \$3,249.79 |
| EW 4HR AHR -H30748 | 97007-H30748 | \$ 5,287.00 | 10% | \$4,793.99 |
| EW 4HR AHR -H30749 | 97007-H30749 | \$ 11,884.00 | 10% | \$10,775.82 |
| EW 4HR AHR -H30750 | 97007-H30750 | \$ 11,884.00 | 10% | \$10,775.82 |
| EW 4HR AHR -H30751 | 97007-H30751 | \$ 7,052.00 | 10% | \$6,394.40 |
| EW 4HR AHR -H30754 | 97007-H30754 | \$ 11,884.00 | 10% | \$10,775.82 |
| EW 4HR AHR -H30755 | 97007-H30755 | \$ 12,912.00 | 10% | \$11,707.96 |
| EW 4HR AHR -H30756 | 97007-H30756 | \$ 11,884.00 | 10% | \$10,775.82 |
| EW 4HR AHR -H30757 | 97007-H30757 | \$ 5,287.00 | 10% | \$4,793.99 |
| EW 4HR AHR -H30758 | 97007-H30758 | \$ 9,406.00 | 10% | \$8,528.89 |
| EW 4HR AHR -H30759 | 97007-H30759 | \$ 10,755.00 | 10% | \$9,752.10 |
| EW 4HR AHR -H30760 | 97007-H30760 | \$ 12,094.00 | 10% | \$10,966.23 |
| EW 4HR AHR -H30761 | 97007-H30761 | \$ 5,287.00 | 10% | \$4,793.99 |
| EW 4HR AHR -H30762 | 97007-H30762 | \$ 12,912.00 | 10% | \$11,707.96 |
| EW 4HR AHR -H30763 | 97007-H30763 | \$ 12,912.00 | 10% | \$11,707.96 |
| EW 4HR AHR -H30764 | 97007-H30764 | \$ 8,184.00 | 10% | \$7,420.84 |
| EW 4HR AHR -H30765 | 97007-H30765 | \$ 7,187.00 | 10% | \$6,516.81 |

| | | | | |
|--------------------|--------------|--------------|-----|--------------------|
| EW 4HR AHR -H30766 | 97007-H30766 | \$ 14,002.00 | 10% | <i>\$12,696.31</i> |
| EW 4HR AHR -H30767 | 97007-H30767 | \$ 8,184.00 | 10% | <i>\$7,420.84</i> |
| EW 4HR AHR H30769 | 97007-H30769 | \$ 2,768.00 | 10% | <i>\$2,509.88</i> |
| EW 4HR AHR H30773 | 97007-H30773 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW 4HR AHR H30774 | 97007-H30774 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30775 | 97007-H30775 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30776 | 97007-H30776 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW 4HR AHR H30777 | 97007-H30777 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30778 | 97007-H30778 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30779 | 97007-H30779 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW 4HR AHR H30780 | 97007-H30780 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW 4HR AHR H30781 | 97007-H30781 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW 4HR AHR H30782 | 97007-H30782 | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR H30783 | 97007-H30783 | \$ 85.00 | 10% | <i>\$77.07</i> |
| EW 4HR AHR H30784 | 97007-H30784 | \$ 85.00 | 10% | <i>\$77.07</i> |
| EW 4HR AHR H30785 | 97007-H30785 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW 4HR AHR H30786 | 97007-H30786 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW 4HR AHR H30787 | 97007-H30787 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW 4HR AHR H30788 | 97007-H30788 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW 4HR AHR H30789 | 97007-H30789 | \$ 85.00 | 10% | <i>\$77.07</i> |
| EW 4HR AHR H30790 | 97007-H30790 | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW 4HR AHR H30791 | 97007-H30791 | \$ 85.00 | 10% | <i>\$77.07</i> |
| EW 4HR AHR H30793 | 97007-H30793 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30794 | 97007-H30794 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30795 | 97007-H30795 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30796 | 97007-H30796 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H30797 | 97007-H30797 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30798 | 97007-H30798 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW 4HR AHR H30799 | 97007-H30799 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30800 | 97007-H30800 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR H30801 | 97007-H30801 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H30802 | 97007-H30802 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR H30803 | 97007-H30803 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30804 | 97007-H30804 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30805 | 97007-H30805 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW 4HR AHR H30806 | 97007-H30806 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30807 | 97007-H30807 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30808 | 97007-H30808 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H30809 | 97007-H30809 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW 4HR AHR H30810 | 97007-H30810 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H30811 | 97007-H30811 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30812 | 97007-H30812 | \$ 72.00 | 10% | <i>\$65.29</i> |

| | | | | |
|-------------------|--------------|-------------|-----|-------------------|
| EW 4HR AHR H30813 | 97007-H30813 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR H30814 | 97007-H30814 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30815 | 97007-H30815 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H30816 | 97007-H30816 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H30817 | 97007-H30817 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30818 | 97007-H30818 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW 4HR AHR H30819 | 97007-H30819 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30820 | 97007-H30820 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H30821 | 97007-H30821 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR H30822 | 97007-H30822 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30823 | 97007-H30823 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR H30824 | 97007-H30824 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW 4HR AHR H30825 | 97007-H30825 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR H30826 | 97007-H30826 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30827 | 97007-H30827 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30828 | 97007-H30828 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR AHR H30829 | 97007-H30829 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW 4HR AHR H30830 | 97007-H30830 | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR AHR H30831 | 97007-H30831 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW 4HR AHR H30832 | 97007-H30832 | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW 4HR AHR H30833 | 97007-H30833 | \$ 413.00 | 10% | <i>\$374.49</i> |
| EW 4HR AHR H30834 | 97007-H30834 | \$ 413.00 | 10% | <i>\$374.49</i> |
| EW 4HR AHR H30836 | 97007-H30836 | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW 4HR AHR H30838 | 97007-H30838 | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW 4HR AHR H30839 | 97007-H30839 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30840 | 97007-H30840 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30841 | 97007-H30841 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30842 | 97007-H30842 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30843 | 97007-H30843 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30844 | 97007-H30844 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30845 | 97007-H30845 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW 4HR AHR H30846 | 97007-H30846 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30847 | 97007-H30847 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30848 | 97007-H30848 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30849 | 97007-H30849 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30850 | 97007-H30850 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30851 | 97007-H30851 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30852 | 97007-H30852 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR H30853 | 97007-H30853 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4HR AHR H30854 | 97007-H30854 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4HR AHR H30855 | 97007-H30855 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4HR AHR H30856 | 97007-H30856 | \$ 146.00 | 10% | <i>\$132.39</i> |

| | | | | |
|-------------------|--------------|-------------|-----|-------------------|
| EW 4HR AHR H30857 | 97007-H30857 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4HR AHR H30858 | 97007-H30858 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4HR AHR H30859 | 97007-H30859 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4HR AHR H30860 | 97007-H30860 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4HR AHR H30866 | 97007-H30866 | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW 4HR AHR H30867 | 97007-H30867 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW 4HR AHR H30868 | 97007-H30868 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW 4HR AHR H30869 | 97007-H30869 | \$ 290.00 | 10% | <i>\$262.96</i> |
| EW 4HR AHR H30870 | 97007-H30870 | \$ 290.00 | 10% | <i>\$262.96</i> |
| EW 4HR AHR H30871 | 97007-H30871 | \$ 266.00 | 10% | <i>\$241.20</i> |
| EW 4HR AHR H30872 | 97007-H30872 | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW 4HR AHR H30873 | 97007-H30873 | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW 4HR AHR H30874 | 97007-H30874 | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW 4HR AHR H30875 | 97007-H30875 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW 4HR AHR H30876 | 97007-H30876 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW 4HR AHR H30877 | 97007-H30877 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW 4HR AHR H30878 | 97007-H30878 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW 4HR AHR H30891 | 97007-H30891 | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR AHR H30892 | 97007-H30892 | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR AHR H30893 | 97007-H30893 | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR H30894 | 97007-H30894 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW 4HR AHR H30895 | 97007-H30895 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30896 | 97007-H30896 | \$ 433.00 | 10% | <i>\$392.62</i> |
| EW 4HR AHR H30897 | 97007-H30897 | \$ 757.00 | 10% | <i>\$686.41</i> |
| EW 4HR AHR H30898 | 97007-H30898 | \$ 852.00 | 10% | <i>\$772.55</i> |
| EW 4HR AHR H30900 | 97007-H30900 | \$ 2,574.00 | 10% | <i>\$2,333.97</i> |
| EW 4HR AHR H30901 | 97007-H30901 | \$ 3,426.00 | 10% | <i>\$3,106.53</i> |
| EW 4HR AHR H30902 | 97007-H30902 | \$ 3,597.00 | 10% | <i>\$3,261.58</i> |
| EW 4HR AHR H30904 | 97007-H30904 | \$ 5,290.00 | 10% | <i>\$4,796.71</i> |
| EW 4HR AHR H30905 | 97007-H30905 | \$ 7,562.00 | 10% | <i>\$6,856.84</i> |
| EW 4HR AHR H30906 | 97007-H30906 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW 4HR AHR H30912 | 97007-H30912 | \$ 568.00 | 10% | <i>\$515.03</i> |
| EW 4HR AHR H30913 | 97007-H30913 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW 4HR AHR H30914 | 97007-H30914 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW 4HR AHR H30915 | 97007-H30915 | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW 4HR AHR H30916 | 97007-H30916 | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW 4HR AHR H30917 | 97007-H30917 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW 4HR AHR H30918 | 97007-H30918 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW 4HR AHR H30946 | 97007-H30946 | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW 4HR AHR H30948 | 97007-H30948 | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW 4HR AHR H30950 | 97007-H30950 | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW 4HR AHR H30951 | 97007-H30951 | \$ 107.00 | 10% | <i>\$97.02</i> |

| | | | | |
|-------------------|--------------|-------------|-----|-------------------|
| EW 4HR AHR H30952 | 97007-H30952 | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW 4HR AHR H30966 | 97007-H30966 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30967 | 97007-H30967 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW 4HR AHR H30968 | 97007-H30968 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30969 | 97007-H30969 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW 4HR AHR H30970 | 97007-H30970 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR AHR H30971 | 97007-H30971 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW 4HR AHR H30972 | 97007-H30972 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR AHR H30973 | 97007-H30973 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30974 | 97007-H30974 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW 4HR AHR H30975 | 97007-H30975 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30976 | 97007-H30976 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30977 | 97007-H30977 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW 4HR AHR H30978 | 97007-H30978 | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW 4HR AHR H30995 | 97007-H30995 | \$ 2,069.00 | 10% | <i>\$1,876.07</i> |
| EW 4HR AHR H31030 | 97007-H31030 | \$ 6,678.00 | 10% | <i>\$6,055.28</i> |
| EW 4HR AHR H31031 | 97007-H31031 | \$ 530.00 | 10% | <i>\$480.58</i> |
| EW 4HR AHR H31033 | 97007-H31033 | \$ 4,044.00 | 10% | <i>\$3,666.90</i> |
| EW 4HR AHR H31034 | 97007-H31034 | \$ 2,247.00 | 10% | <i>\$2,037.47</i> |
| EW 4HR AHR H31035 | 97007-H31035 | \$ 2,357.00 | 10% | <i>\$2,137.21</i> |
| EW 4HR AHR H31036 | 97007-H31036 | \$ 4,711.00 | 10% | <i>\$4,271.70</i> |
| EW 4HR AHR H31040 | 97007-H31040 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW 4HR AHR H31041 | 97007-H31041 | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR AHR H31042 | 97007-H31042 | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW 4HR AHR H31043 | 97007-H31043 | \$ 190.00 | 10% | <i>\$172.28</i> |
| EW 4HR AHR H31047 | 97007-H31047 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW 4HR AHR H31049 | 97007-H31049 | \$ 1,888.00 | 10% | <i>\$1,711.94</i> |
| EW 4HR AHR H31060 | 97007-H31060 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW 4HR AHR H31062 | 97007-H31062 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW 4HR AHR H31066 | 97007-H31066 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW 4HR AHR H31068 | 97007-H31068 | \$ 74.00 | 10% | <i>\$67.10</i> |
| EW 4HR AHR H31076 | 97007-H31076 | \$ 256.00 | 10% | <i>\$232.13</i> |
| EW 4HR AHR H31077 | 97007-H31077 | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW 4HR AHR H31078 | 97007-H31078 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW 4HR AHR H31103 | 97007-H31103 | \$ 4,315.00 | 10% | <i>\$3,912.63</i> |
| EW 4HR AHR H31119 | 97007-H31119 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW 4HR AHR H31124 | 97007-H31124 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW 4HR AHR H31127 | 97007-H31127 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW 4HR AHR H31132 | 97007-H31132 | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW 4HR AHR H31134 | 97007-H31134 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW 4HR AHR H31135 | 97007-H31135 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW 4HR AHR H31136 | 97007-H31136 | \$ 88.00 | 10% | <i>\$79.79</i> |

| | | | | |
|-------------------|--------------|--------------|-----|-------------|
| EW 4HR AHR H31137 | 97007-H31137 | \$ 80.00 | 10% | \$72.54 |
| EW 4HR AHR H31197 | 97007-H31197 | \$ 96.00 | 10% | \$87.05 |
| EW 4HR AHR H31198 | 97007-H31198 | \$ 96.00 | 10% | \$87.05 |
| EW 4HR AHR H31199 | 97007-H31199 | \$ 96.00 | 10% | \$87.05 |
| EW 4HR AHR H31200 | 97007-H31200 | \$ 96.00 | 10% | \$87.05 |
| EW 4HR AHR H31201 | 97007-H31201 | \$ 96.00 | 10% | \$87.05 |
| EW 4HR AHR H31202 | 97007-H31202 | \$ 96.00 | 10% | \$87.05 |
| EW 4HR AHR H31203 | 97007-H31203 | \$ 111.00 | 10% | \$100.65 |
| EW 4HR AHR H31204 | 97007-H31204 | \$ 99.00 | 10% | \$89.77 |
| EW 4HR AHR H31205 | 97007-H31205 | \$ 111.00 | 10% | \$100.65 |
| EW 4HR AHR H31206 | 97007-H31206 | \$ 111.00 | 10% | \$100.65 |
| EW 4HR AHR H31207 | 97007-H31207 | \$ 99.00 | 10% | \$89.77 |
| EW 4HR AHR H31208 | 97007-H31208 | \$ 111.00 | 10% | \$100.65 |
| EW 4HR AHR H31210 | 97007-H31210 | \$ 207.00 | 10% | \$187.70 |
| EW 4HR AHR H31335 | 97007-H31335 | \$ 113.00 | 10% | \$102.46 |
| EW 4HR AHR H31337 | 97007-H31337 | \$ 8,915.00 | 10% | \$8,083.68 |
| EW 4HR AHR H31338 | 97007-H31338 | \$ 8,915.00 | 10% | \$8,083.68 |
| EW 4HR AHR H31339 | 97007-H31339 | \$ 1,451.00 | 10% | \$1,315.69 |
| EW 4HR AHR H31340 | 97007-H31340 | \$ 3,093.00 | 10% | \$2,804.58 |
| EW 4HR AHR H31341 | 97007-H31341 | \$ 4,584.00 | 10% | \$4,156.54 |
| EW 4HR AHR H31342 | 97007-H31342 | \$ 1,444.00 | 10% | \$1,309.35 |
| EW 4HR AHR H31343 | 97007-H31343 | \$ 2,133.00 | 10% | \$1,934.10 |
| EW 4HR AHR H31344 | 97007-H31344 | \$ 2,133.00 | 10% | \$1,934.10 |
| EW 4HR AHR H31345 | 97007-H31345 | \$ 2,133.00 | 10% | \$1,934.10 |
| EW 4HR AHR H31346 | 97007-H31346 | \$ 2,133.00 | 10% | \$1,934.10 |
| EW 4HR AHR H31348 | 97007-H31348 | \$ 164.00 | 10% | \$148.71 |
| EW 4HR AHR H31349 | 97007-H31349 | \$ 164.00 | 10% | \$148.71 |
| EW 4HR AHR H31350 | 97007-H31350 | \$ 266.00 | 10% | \$241.20 |
| EW 4HR AHR H31351 | 97007-H31351 | \$ 99.00 | 10% | \$89.77 |
| EW 4HR AHR H31352 | 97007-H31352 | \$ 99.00 | 10% | \$89.77 |
| EW 4HR AHR H31353 | 97007-H31353 | \$ 83.00 | 10% | \$75.26 |
| EW 4HR AHR H31354 | 97007-H31354 | \$ 83.00 | 10% | \$75.26 |
| EW 4HR AHR H31355 | 97007-H31355 | \$ 175.00 | 10% | \$158.68 |
| EW 4HR AHR H31356 | 97007-H31356 | \$ 175.00 | 10% | \$158.68 |
| EW 4HR AHR H31357 | 97007-H31357 | \$ 175.00 | 10% | \$158.68 |
| EW 4HR AHR H31358 | 97007-H31358 | \$ 61.00 | 10% | \$55.31 |
| EW 4HR AHR H31359 | 97007-H31359 | \$ 69.00 | 10% | \$62.57 |
| EW 4HR AHR H31360 | 97007-H31360 | \$ 58.00 | 10% | \$52.59 |
| EW 4HR AHR H31361 | 97007-H31361 | \$ 2,917.00 | 10% | \$2,644.99 |
| EW 4HR AHR H31362 | 97007-H31362 | \$ 24,141.00 | 10% | \$21,889.85 |
| EW 4HR AHR H31363 | 97007-H31363 | \$ 24,141.00 | 10% | \$21,889.85 |
| EW 4HR AHR H31364 | 97007-H31364 | \$ 8,433.00 | 10% | \$7,646.62 |

| | | | | |
|-------------------|--------------|--------------|-----|-------------|
| EW 4HR AHR H31365 | 97007-H31365 | \$ 8,433.00 | 10% | \$7,646.62 |
| EW 4HR AHR H31366 | 97007-H31366 | \$ 11,699.00 | 10% | \$10,608.07 |
| EW 4HR AHR H31367 | 97007-H31367 | \$ 11,699.00 | 10% | \$10,608.07 |
| EW 4HR AHR H31369 | 97007-H31369 | \$ 99.00 | 10% | \$89.77 |
| EW 4HR AHR H31370 | 97007-H31370 | \$ 99.00 | 10% | \$89.77 |
| EW 4HR AHR H31393 | 97007-H31393 | \$ 57.00 | 10% | \$51.68 |
| EW 4HR AHR H32010 | 97007-H32010 | \$ 337.00 | 10% | \$305.57 |
| EW 4HR AHR H32011 | 97007-H32011 | \$ 337.00 | 10% | \$305.57 |
| EW 4HR AHR H32012 | 97007-H32012 | \$ 2,895.00 | 10% | \$2,625.04 |
| EW 4HR AHR H32013 | 97007-H32013 | \$ 2,895.00 | 10% | \$2,625.04 |
| EW 4HR AHR H32014 | 97007-H32014 | \$ 2,895.00 | 10% | \$2,625.04 |
| EW 4HR AHR H32015 | 97007-H32015 | \$ 2,895.00 | 10% | \$2,625.04 |
| EW 4HR AHR H32016 | 97007-H32016 | \$ 2,525.00 | 10% | \$2,289.54 |
| EW 4HR AHR H32017 | 97007-H32017 | \$ 2,525.00 | 10% | \$2,289.54 |
| EW 4HR AHR H32018 | 97007-H32018 | \$ 2,525.00 | 10% | \$2,289.54 |
| EW 4HR AHR H32019 | 97007-H32019 | \$ 2,525.00 | 10% | \$2,289.54 |
| EW 4HR AHR H32020 | 97007-H32020 | \$ 25,316.00 | 10% | \$22,955.28 |
| EW 4HR AHR H32021 | 97007-H32021 | \$ 25,316.00 | 10% | \$22,955.28 |
| EW 4HR AHR H32022 | 97007-H32022 | \$ 25,316.00 | 10% | \$22,955.28 |
| EW 4HR AHR H32023 | 97007-H32023 | \$ 25,316.00 | 10% | \$22,955.28 |
| EW 4HR AHR H32028 | 97007-H32028 | \$ 48,816.00 | 10% | \$44,263.91 |
| EW 4HR AHR H32029 | 97007-H32029 | \$ 48,816.00 | 10% | \$44,263.91 |
| EW 4HR AHR H32030 | 97007-H32030 | \$ 51,196.00 | 10% | \$46,421.97 |
| EW 4HR AHR H32031 | 97007-H32031 | \$ 51,196.00 | 10% | \$46,421.97 |
| EW 4HR AHR H32032 | 97007-H32032 | \$ 51,196.00 | 10% | \$46,421.97 |
| EW 4HR AHR H32033 | 97007-H32033 | \$ 51,196.00 | 10% | \$46,421.97 |
| EW 4HR AHR H32038 | 97007-H32038 | \$ 8,843.00 | 10% | \$8,018.39 |
| EW 4HR AHR H32039 | 97007-H32039 | \$ 8,843.00 | 10% | \$8,018.39 |
| EW 4HR AHR H32040 | 97007-H32040 | \$ 8,843.00 | 10% | \$8,018.39 |
| EW 4HR AHR H32041 | 97007-H32041 | \$ 8,843.00 | 10% | \$8,018.39 |
| EW 4HR AHR H32046 | 97007-H32046 | \$ 12,267.00 | 10% | \$11,123.10 |
| EW 4HR AHR H32047 | 97007-H32047 | \$ 12,267.00 | 10% | \$11,123.10 |
| EW 4HR AHR H32048 | 97007-H32048 | \$ 12,267.00 | 10% | \$11,123.10 |
| EW 4HR AHR H32049 | 97007-H32049 | \$ 12,267.00 | 10% | \$11,123.10 |
| EW 4HR AHR H32054 | 97007-H32054 | \$ 8,843.00 | 10% | \$8,018.39 |
| EW 4HR AHR H32055 | 97007-H32055 | \$ 12,267.00 | 10% | \$11,123.10 |
| EW 4HR AHR H32056 | 97007-H32056 | \$ 3,440.00 | 10% | \$3,119.22 |
| EW 4HR AHR H32057 | 97007-H32057 | \$ 3,440.00 | 10% | \$3,119.22 |
| EW 4HR AHR H32058 | 97007-H32058 | \$ 3,440.00 | 10% | \$3,119.22 |
| EW 4HR AHR H32059 | 97007-H32059 | \$ 3,440.00 | 10% | \$3,119.22 |
| EW 4HR AHR H32060 | 97007-H32060 | \$ 3,425.00 | 10% | \$3,105.62 |
| EW 4HR AHR H32061 | 97007-H32061 | \$ 3,596.00 | 10% | \$3,260.67 |

| | | | | |
|-------------------|--------------|--------------|-----|-------------|
| EW 4HR AHR H32062 | 97007-H32062 | \$ 3,458.00 | 10% | \$3,135.54 |
| EW 4HR AHR H32063 | 97007-H32063 | \$ 3,429.00 | 10% | \$3,109.25 |
| EW 4HR AHR H32064 | 97007-H32064 | \$ 3,458.00 | 10% | \$3,135.54 |
| EW 4HR AHR H32065 | 97007-H32065 | \$ 3,906.00 | 10% | \$3,541.77 |
| EW 4HR AHR H32066 | 97007-H32066 | \$ 3,906.00 | 10% | \$3,541.77 |
| EW 4HR AHR H32067 | 97007-H32067 | \$ 3,906.00 | 10% | \$3,541.77 |
| EW 4HR AHR H32068 | 97007-H32068 | \$ 3,906.00 | 10% | \$3,541.77 |
| EW 4HR AHR H32069 | 97007-H32069 | \$ 4,855.00 | 10% | \$4,402.27 |
| EW 4HR AHR H32070 | 97007-H32070 | \$ 4,855.00 | 10% | \$4,402.27 |
| EW 4HR AHR H32071 | 97007-H32071 | \$ 4,855.00 | 10% | \$4,402.27 |
| EW 4HR AHR H32072 | 97007-H32072 | \$ 4,855.00 | 10% | \$4,402.27 |
| EW 4HR AHR H32073 | 97007-H32073 | \$ 35,959.00 | 10% | \$32,605.82 |
| EW 4HR AHR H32074 | 97007-H32074 | \$ 35,959.00 | 10% | \$32,605.82 |
| EW 4HR AHR H32075 | 97007-H32075 | \$ 48,872.00 | 10% | \$44,314.69 |
| EW 4HR AHR H32076 | 97007-H32076 | \$ 48,873.00 | 10% | \$44,315.59 |
| EW 4HR AHR H32101 | 97007-H32101 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32102 | 97007-H32102 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32103 | 97007-H32103 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32104 | 97007-H32104 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32105 | 97007-H32105 | \$ 3,170.00 | 10% | \$2,874.40 |
| EW 4HR AHR H32106 | 97007-H32106 | \$ 3,170.00 | 10% | \$2,874.40 |
| EW 4HR AHR H32107 | 97007-H32107 | \$ 8,573.00 | 10% | \$7,773.57 |
| EW 4HR AHR H32108 | 97007-H32108 | \$ 8,573.00 | 10% | \$7,773.57 |
| EW 4HR AHR H32109 | 97007-H32109 | \$ 3,171.00 | 10% | \$2,875.30 |
| EW 4HR AHR H32110 | 97007-H32110 | \$ 3,171.00 | 10% | \$2,875.30 |
| EW 4HR AHR H32111 | 97007-H32111 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32112 | 97007-H32112 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32113 | 97007-H32113 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32114 | 97007-H32114 | \$ 1,582.00 | 10% | \$1,434.48 |
| EW 4HR AHR H32115 | 97007-H32115 | \$ 3,171.00 | 10% | \$2,875.30 |
| EW 4HR AHR H32116 | 97007-H32116 | \$ 3,171.00 | 10% | \$2,875.30 |
| EW 4HR AHR H32117 | 97007-H32117 | \$ 1,487.00 | 10% | \$1,348.34 |
| EW 4HR AHR H32118 | 97007-H32118 | \$ 1,487.00 | 10% | \$1,348.34 |
| EW 4HR AHR H32119 | 97007-H32119 | \$ 1,487.00 | 10% | \$1,348.34 |
| EW 4HR AHR H32120 | 97007-H32120 | \$ 1,487.00 | 10% | \$1,348.34 |
| EW 4HR AHR H32121 | 97007-H32121 | \$ 8,573.00 | 10% | \$7,773.57 |
| EW 4HR AHR H32122 | 97007-H32122 | \$ 8,573.00 | 10% | \$7,773.57 |
| EW 4HR AHR H32123 | 97007-H32123 | \$ 3,171.00 | 10% | \$2,875.30 |
| EW 4HR AHR H32124 | 97007-H32124 | \$ 3,171.00 | 10% | \$2,875.30 |
| EW 4HR AHR H32125 | 97007-H32125 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32126 | 97007-H32126 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32127 | 97007-H32127 | \$ 3,684.00 | 10% | \$3,340.47 |

| | | | | |
|-------------------|--------------|--------------|-----|-------------|
| EW 4HR AHR H32128 | 97007-H32128 | \$ 3,684.00 | 10% | \$3,340.47 |
| EW 4HR AHR H32129 | 97007-H32129 | \$ 3,684.00 | 10% | \$3,340.47 |
| EW 4HR AHR H32130 | 97007-H32130 | \$ 3,684.00 | 10% | \$3,340.47 |
| EW 4HR AHR H32131 | 97007-H32131 | \$ 3,684.00 | 10% | \$3,340.47 |
| EW 4HR AHR H32132 | 97007-H32132 | \$ 3,684.00 | 10% | \$3,340.47 |
| EW 4HR AHR H32133 | 97007-H32133 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32134 | 97007-H32134 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32135 | 97007-H32135 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32136 | 97007-H32136 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32137 | 97007-H32137 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32138 | 97007-H32138 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW 4HR AHR H32139 | 97007-H32139 | \$ 13,252.00 | 10% | \$12,016.25 |
| EW 4HR AHR H32140 | 97007-H32140 | \$ 13,252.00 | 10% | \$12,016.25 |
| EW 4HR AHR H32141 | 97007-H32141 | \$ 15,294.00 | 10% | \$13,867.83 |
| EW 4HR AHR H32142 | 97007-H32142 | \$ 15,294.00 | 10% | \$13,867.83 |
| EW 4HR AHR H32146 | 97007-H32146 | \$ 1,350.00 | 10% | \$1,224.11 |
| EW 4HR AHR H32147 | 97007-H32147 | \$ 1,350.00 | 10% | \$1,224.11 |
| EW 4HR AHR H32148 | 97007-H32148 | \$ 2,785.00 | 10% | \$2,525.30 |
| EW 4HR AHR H32149 | 97007-H32149 | \$ 2,785.00 | 10% | \$2,525.30 |
| EW 4HR AHR H32150 | 97007-H32150 | \$ 1,428.00 | 10% | \$1,294.84 |
| EW 4HR AHR H32152 | 97007-H32152 | \$ 647.00 | 10% | \$586.67 |
| EW 4HR AHR H32169 | 97007-H32169 | \$ 1,601.00 | 10% | \$1,451.71 |
| EW 4HR AHR H32170 | 97007-H32170 | \$ 1,601.00 | 10% | \$1,451.71 |
| EW 4HR AHR H32171 | 97007-H32171 | \$ 1,504.00 | 10% | \$1,363.75 |
| EW 4HR AHR H32172 | 97007-H32172 | \$ 1,504.00 | 10% | \$1,363.75 |
| EW 4HR AHR H32173 | 97007-H32173 | \$ 4,007.00 | 10% | \$3,633.35 |
| EW 4HR AHR H32174 | 97007-H32174 | \$ 4,007.00 | 10% | \$3,633.35 |
| EW 4HR AHR H32175 | 97007-H32175 | \$ 3,405.00 | 10% | \$3,087.48 |
| EW 4HR AHR H32176 | 97007-H32176 | \$ 3,405.00 | 10% | \$3,087.48 |
| EW 4HR AHR H32177 | 97007-H32177 | \$ 15,621.00 | 10% | \$14,164.34 |
| EW 4HR AHR H32178 | 97007-H32178 | \$ 18,027.00 | 10% | \$16,345.98 |
| EW 4HR AHR H34008 | 97007-H34008 | \$ 62.00 | 10% | \$56.22 |
| EW 4HR AHR H34009 | 97007-H34009 | \$ 168.00 | 10% | \$152.33 |
| EW 4HR AHR H34010 | 97007-H34010 | \$ 69.00 | 10% | \$62.57 |
| EW 4HR AHR H34011 | 97007-H34011 | \$ 152.00 | 10% | \$137.83 |
| EW 4HR AHR H34012 | 97007-H34012 | \$ 273.00 | 10% | \$247.54 |
| EW 4HR AHR H34013 | 97007-H34013 | \$ 105.00 | 10% | \$95.21 |
| EW 4HR AHR H34014 | 97007-H34014 | \$ 168.00 | 10% | \$152.33 |
| EW 4HR AHR H34015 | 97007-H34015 | \$ 86.00 | 10% | \$77.98 |
| EW 4HR AHR H34016 | 97007-H34016 | \$ 191.00 | 10% | \$173.19 |
| EW 4HR AHR H34017 | 97007-H34017 | \$ 322.00 | 10% | \$291.97 |
| EW 4HR AHR H34018 | 97007-H34018 | \$ 118.00 | 10% | \$107.00 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW 4HR AHR H34019 | 97007-H34019 | \$ 118.00 | 10% | \$107.00 |
| EW 4HR AHR H34020 | 97007-H34020 | \$ 118.00 | 10% | \$107.00 |
| EW 4HR AHR H34021 | 97007-H34021 | \$ 118.00 | 10% | \$107.00 |
| EW 4HR AHR H34048 | 97007-H34048 | \$ 539.00 | 10% | \$488.74 |
| EW 4HR AHR H34049 | 97007-H34049 | \$ 539.00 | 10% | \$488.74 |
| EW 4HR AHR H34050 | 97007-H34050 | \$ 391.00 | 10% | \$354.54 |
| EW 4HR AHR H34051 | 97007-H34051 | \$ 391.00 | 10% | \$354.54 |
| EW 4HR AHR H34052 | 97007-H34052 | \$ 627.00 | 10% | \$568.53 |
| EW 4HR AHR H34053 | 97007-H34053 | \$ 627.00 | 10% | \$568.53 |
| EW 4HR AHR H34054 | 97007-H34054 | \$ 470.00 | 10% | \$426.17 |
| EW 4HR AHR H34055 | 97007-H34055 | \$ 470.00 | 10% | \$426.17 |
| EW 4HR AHR H34056 | 97007-H34056 | \$ 686.00 | 10% | \$622.03 |
| EW 4HR AHR H34057 | 97007-H34057 | \$ 686.00 | 10% | \$622.03 |
| EW 4HR AHR H34058 | 97007-H34058 | \$ 588.00 | 10% | \$533.17 |
| EW 4HR AHR H34059 | 97007-H34059 | \$ 588.00 | 10% | \$533.17 |
| EW 4HR AHR H34062 | 97007-H34062 | \$ 686.00 | 10% | \$622.03 |
| EW 4HR AHR H34063 | 97007-H34063 | \$ 686.00 | 10% | \$622.03 |
| EW 4HR AHR H34064 | 97007-H34064 | \$ 448.00 | 10% | \$406.22 |
| EW 4HR AHR H34065 | 97007-H34065 | \$ 448.00 | 10% | \$406.22 |
| EW 4HR AHR H34066 | 97007-H34066 | \$ 448.00 | 10% | \$406.22 |
| EW 4HR AHR H34067 | 97007-H34067 | \$ 448.00 | 10% | \$406.22 |
| EW 4HR AHR H34068 | 97007-H34068 | \$ 448.00 | 10% | \$406.22 |
| EW 4HR AHR H34069 | 97007-H34069 | \$ 436.00 | 10% | \$395.34 |
| EW 4HR AHR H34070 | 97007-H34070 | \$ 448.00 | 10% | \$406.22 |
| EW 4HR AHR H34071 | 97007-H34071 | \$ 448.00 | 10% | \$406.22 |
| EW 4HR AHR H34072 | 97007-H34072 | \$ 3,783.00 | 10% | \$3,430.24 |
| EW 4HR AHR H34073 | 97007-H34073 | \$ 3,711.00 | 10% | \$3,364.95 |
| EW 4HR AHR H34074 | 97007-H34074 | \$ 4,725.00 | 10% | \$4,284.39 |
| EW 4HR AHR H34075 | 97007-H34075 | \$ 4,525.00 | 10% | \$4,103.04 |
| EW 4HR AHR H34076 | 97007-H34076 | \$ 3,783.00 | 10% | \$3,430.24 |
| EW 4HR AHR H34077 | 97007-H34077 | \$ 3,711.00 | 10% | \$3,364.95 |
| EW 4HR AHR H34078 | 97007-H34078 | \$ 3,783.00 | 10% | \$3,430.24 |
| EW 4HR AHR H34079 | 97007-H34079 | \$ 3,711.00 | 10% | \$3,364.95 |
| EW 4HR AHR H34080 | 97007-H34080 | \$ 4,725.00 | 10% | \$4,284.39 |
| EW 4HR AHR H34081 | 97007-H34081 | \$ 4,525.00 | 10% | \$4,103.04 |
| EW 4HR AHR H34082 | 97007-H34082 | \$ 4,532.00 | 10% | \$4,109.39 |
| EW 4HR AHR H34083 | 97007-H34083 | \$ 4,341.00 | 10% | \$3,936.20 |
| EW 4HR AHR H34084 | 97007-H34084 | \$ 3,036.00 | 10% | \$2,752.89 |
| EW 4HR AHR H34085 | 97007-H34085 | \$ 3,036.00 | 10% | \$2,752.89 |
| EW 4HR AHR H34086 | 97007-H34086 | \$ 3,533.00 | 10% | \$3,203.55 |
| EW 4HR AHR H34087 | 97007-H34087 | \$ 3,389.00 | 10% | \$3,072.98 |
| EW 4HR AHR H34088 | 97007-H34088 | \$ 8,123.00 | 10% | \$7,365.53 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW 4HR AHR H34089 | 97007-H34089 | \$ 8,123.00 | 10% | \$7,365.53 |
| EW 4HR AHR H34090 | 97007-H34090 | \$ 9,354.00 | 10% | \$8,481.74 |
| EW 4HR AHR H34091 | 97007-H34091 | \$ 6,614.00 | 10% | \$5,997.24 |
| EW 4HR AHR H34092 | 97007-H34092 | \$ 6,614.00 | 10% | \$5,997.24 |
| EW 4HR AHR H34093 | 97007-H34093 | \$ 6,614.00 | 10% | \$5,997.24 |
| EW 4HR AHR H34094 | 97007-H34094 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34095 | 97007-H34095 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34096 | 97007-H34096 | \$ 863.00 | 10% | \$782.53 |
| EW 4HR AHR H34097 | 97007-H34097 | \$ 863.00 | 10% | \$782.53 |
| EW 4HR AHR H34098 | 97007-H34098 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34099 | 97007-H34099 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34100 | 97007-H34100 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34101 | 97007-H34101 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34102 | 97007-H34102 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34103 | 97007-H34103 | \$ 765.00 | 10% | \$693.66 |
| EW 4HR AHR H34104 | 97007-H34104 | \$ 331.00 | 10% | \$300.13 |
| EW 4HR AHR H34105 | 97007-H34105 | \$ 330.00 | 10% | \$299.23 |
| EW 4HR AHR H34106 | 97007-H34106 | \$ 331.00 | 10% | \$300.13 |
| EW 4HR AHR H34107 | 97007-H34107 | \$ 330.00 | 10% | \$299.23 |
| EW 4HR AHR H34108 | 97007-H34108 | \$ 331.00 | 10% | \$300.13 |
| EW 4HR AHR H34109 | 97007-H34109 | \$ 330.00 | 10% | \$299.23 |
| EW 4HR AHR H34110 | 97007-H34110 | \$ 6,371.00 | 10% | \$5,776.90 |
| EW 4HR AHR H34111 | 97007-H34111 | \$ 6,371.00 | 10% | \$5,776.90 |
| EW 4HR AHR H34112 | 97007-H34112 | \$ 6,371.00 | 10% | \$5,776.90 |
| EW 4HR AHR H34114 | 97007-H34114 | \$ 8,365.00 | 10% | \$7,584.96 |
| EW 4HR AHR H34115 | 97007-H34115 | \$ 8,365.00 | 10% | \$7,584.96 |
| EW 4HR AHR H34116 | 97007-H34116 | \$ 8,365.00 | 10% | \$7,584.96 |
| EW 4HR AHR H34117 | 97007-H34117 | \$ 8,365.00 | 10% | \$7,584.96 |
| EW 4HR AHR H34118 | 97007-H34118 | \$ 2,107.00 | 10% | \$1,910.52 |
| EW 4HR AHR H34119 | 97007-H34119 | \$ 2,107.00 | 10% | \$1,910.52 |
| EW 4HR AHR H34120 | 97007-H34120 | \$ 1,458.00 | 10% | \$1,322.04 |
| EW 4HR AHR H34121 | 97007-H34121 | \$ 1,458.00 | 10% | \$1,322.04 |
| EW 4HR AHR H34122 | 97007-H34122 | \$ 1,519.00 | 10% | \$1,377.35 |
| EW 4HR AHR H34123 | 97007-H34123 | \$ 1,519.00 | 10% | \$1,377.35 |
| EW 4HR AHR H34124 | 97007-H34124 | \$ 2,260.00 | 10% | \$2,049.26 |
| EW 4HR AHR H34125 | 97007-H34125 | \$ 2,260.00 | 10% | \$2,049.26 |
| EW 4HR AHR H34126 | 97007-H34126 | \$ 2,260.00 | 10% | \$2,049.26 |
| EW 4HR AHR H34127 | 97007-H34127 | \$ 2,260.00 | 10% | \$2,049.26 |
| EW 4HR AHR H34128 | 97007-H34128 | \$ 269.00 | 10% | \$243.92 |
| EW 4HR AHR H34129 | 97007-H34129 | \$ 587.00 | 10% | \$532.26 |
| EW 4HR AHR H34130 | 97007-H34130 | \$ 610.00 | 10% | \$553.12 |
| EW 4HR AHR H34131 | 97007-H34131 | \$ 607.00 | 10% | \$550.40 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW 4HR AHR H34132 | 97007-H34132 | \$ 610.00 | 10% | \$553.12 |
| EW 4HR AHR H34172 | 97007-H34172 | \$ 1,994.00 | 10% | \$1,808.06 |
| EW 4HR AHR H34726 | 97007-H34726 | \$ 3,930.00 | 10% | \$3,563.53 |
| EW 4HR AHR H34727 | 97007-H34727 | \$ 3,930.00 | 10% | \$3,563.53 |
| EW 4HR AHR H34728 | 97007-H34728 | \$ 3,930.00 | 10% | \$3,563.53 |
| EW 4HR AHR H34729 | 97007-H34729 | \$ 3,930.00 | 10% | \$3,563.53 |
| EW 4HR AHR H34730 | 97007-H34730 | \$ 4,213.00 | 10% | \$3,820.14 |
| EW 4HR AHR H34731 | 97007-H34731 | \$ 4,213.00 | 10% | \$3,820.14 |
| EW 4HR AHR H34732 | 97007-H34732 | \$ 4,213.00 | 10% | \$3,820.14 |
| EW 4HR AHR H34733 | 97007-H34733 | \$ 4,213.00 | 10% | \$3,820.14 |
| EW 4HR AHR H34734 | 97007-H34734 | \$ 613.00 | 10% | \$555.84 |
| EW 4HR AHR H34735 | 97007-H34735 | \$ 613.00 | 10% | \$555.84 |
| EW 4HR AHR H34736 | 97007-H34736 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H34737 | 97007-H34737 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H34738 | 97007-H34738 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34739 | 97007-H34739 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34740 | 97007-H34740 | \$ 613.00 | 10% | \$555.84 |
| EW 4HR AHR H34741 | 97007-H34741 | \$ 613.00 | 10% | \$555.84 |
| EW 4HR AHR H34742 | 97007-H34742 | \$ 493.00 | 10% | \$447.03 |
| EW 4HR AHR H34743 | 97007-H34743 | \$ 493.00 | 10% | \$447.03 |
| EW 4HR AHR H34744 | 97007-H34744 | \$ 776.00 | 10% | \$703.64 |
| EW 4HR AHR H34745 | 97007-H34745 | \$ 776.00 | 10% | \$703.64 |
| EW 4HR AHR H34746 | 97007-H34746 | \$ 872.00 | 10% | \$790.69 |
| EW 4HR AHR H34747 | 97007-H34747 | \$ 872.00 | 10% | \$790.69 |
| EW 4HR AHR H34748 | 97007-H34748 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34749 | 97007-H34749 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34750 | 97007-H34750 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34751 | 97007-H34751 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34752 | 97007-H34752 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34753 | 97007-H34753 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34754 | 97007-H34754 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34755 | 97007-H34755 | \$ 1,474.00 | 10% | \$1,336.55 |
| EW 4HR AHR H34756 | 97007-H34756 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H34757 | 97007-H34757 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H34758 | 97007-H34758 | \$ 776.00 | 10% | \$703.64 |
| EW 4HR AHR H34759 | 97007-H34759 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H34760 | 97007-H34760 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H34761 | 97007-H34761 | \$ 776.00 | 10% | \$703.64 |
| EW 4HR AHR H34839 | 97007-H34839 | \$ 788.00 | 10% | \$714.52 |
| EW 4HR AHR H34840 | 97007-H34840 | \$ 788.00 | 10% | \$714.52 |
| EW 4HR AHR H34841 | 97007-H34841 | \$ 788.00 | 10% | \$714.52 |
| EW 4HR AHR H34842 | 97007-H34842 | \$ 788.00 | 10% | \$714.52 |

| | | | | |
|-------------------|--------------|--------------|-----|-------------|
| EW 4HR AHR H34843 | 97007-H34843 | \$ 788.00 | 10% | \$714.52 |
| EW 4HR AHR H34844 | 97007-H34844 | \$ 788.00 | 10% | \$714.52 |
| EW 4HR AHR H34845 | 97007-H34845 | \$ 788.00 | 10% | \$714.52 |
| EW 4HR AHR H34846 | 97007-H34846 | \$ 788.00 | 10% | \$714.52 |
| EW 4HR AHR H34993 | 97007-H34993 | \$ 16,468.00 | 10% | \$14,932.36 |
| EW 4HR AHR H34994 | 97007-H34994 | \$ 16,468.00 | 10% | \$14,932.36 |
| EW 4HR AHR H34996 | 97007-H34996 | \$ 16,468.00 | 10% | \$14,932.36 |
| EW 4HR AHR H34997 | 97007-H34997 | \$ 16,468.00 | 10% | \$14,932.36 |
| EW 4HR AHR H35005 | 97007-H35005 | \$ 12,016.00 | 10% | \$10,895.51 |
| EW 4HR AHR H35006 | 97007-H35006 | \$ 12,016.00 | 10% | \$10,895.51 |
| EW 4HR AHR H35012 | 97007-H35012 | \$ 7,228.00 | 10% | \$6,553.99 |
| EW 4HR AHR H35262 | 97007-H35262 | \$ 2,454.00 | 10% | \$2,225.16 |
| EW 4HR AHR H35270 | 97007-H35270 | \$ 627.00 | 10% | \$568.53 |
| EW 4HR AHR H35271 | 97007-H35271 | \$ 470.00 | 10% | \$426.17 |
| EW 4HR AHR H35273 | 97007-H35273 | \$ 419.00 | 10% | \$379.93 |
| EW 4HR AHR H35274 | 97007-H35274 | \$ 876.00 | 10% | \$794.31 |
| EW 4HR AHR H35275 | 97007-H35275 | \$ 686.00 | 10% | \$622.03 |
| EW 4HR AHR H35276 | 97007-H35276 | \$ 3,783.00 | 10% | \$3,430.24 |
| EW 4HR AHR H35277 | 97007-H35277 | \$ 4,532.00 | 10% | \$4,109.39 |
| EW 4HR AHR H35278 | 97007-H35278 | \$ 3,036.00 | 10% | \$2,752.89 |
| EW 4HR AHR H35279 | 97007-H35279 | \$ 3,389.00 | 10% | \$3,072.98 |
| EW 4HR AHR H35280 | 97007-H35280 | \$ 6,250.00 | 10% | \$5,667.19 |
| EW 4HR AHR H35281 | 97007-H35281 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35282 | 97007-H35282 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35283 | 97007-H35283 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35284 | 97007-H35284 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35285 | 97007-H35285 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35286 | 97007-H35286 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35287 | 97007-H35287 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35288 | 97007-H35288 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW 4HR AHR H35289 | 97007-H35289 | \$ 5,821.00 | 10% | \$5,278.19 |
| EW 4HR AHR H35291 | 97007-H35291 | \$ 4,403.00 | 10% | \$3,992.42 |
| EW 4HR AHR H35292 | 97007-H35292 | \$ 3,036.00 | 10% | \$2,752.89 |
| EW 4HR AHR H35293 | 97007-H35293 | \$ 3,389.00 | 10% | \$3,072.98 |
| EW 4HR AHR H35295 | 97007-H35295 | \$ 560.00 | 10% | \$507.78 |
| EW 4hr AHR H35296 | 97007-H35296 | \$ 7,436.00 | 10% | \$6,742.59 |
| EW 4hr AHR H35297 | 97007-H35297 | \$ 7,436.00 | 10% | \$6,742.59 |
| EW 4hr AHR H35298 | 97007-H35298 | \$ 11,944.00 | 10% | \$10,830.22 |
| EW 4hr AHR H35299 | 97007-H35299 | \$ 11,944.00 | 10% | \$10,830.22 |
| EW 4hr AHR H35302 | 97007-H35302 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW 4hr AHR H35303 | 97007-H35303 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW 4hr AHR H35304 | 97007-H35304 | \$ 2,880.00 | 10% | \$2,611.44 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW 4hr AHR H35305 | 97007-H35305 | \$ 3,021.00 | 10% | \$2,739.29 |
| EW 4hr AHR H35306 | 97007-H35306 | \$ 3,021.00 | 10% | \$2,739.29 |
| EW 4hr AHR H35307 | 97007-H35307 | \$ 3,021.00 | 10% | \$2,739.29 |
| EW 4HR AHR H35309 | 97007-H35309 | \$ 4,043.00 | 10% | \$3,665.99 |
| EW 4HR AHR H35310 | 97007-H35310 | \$ 4,043.00 | 10% | \$3,665.99 |
| EW 4HR AHR H35311 | 97007-H35311 | \$ 4,043.00 | 10% | \$3,665.99 |
| EW 4HR AHR H35312 | 97007-H35312 | \$ 3,340.00 | 10% | \$3,028.55 |
| EW 4HR AHR H35313 | 97007-H35313 | \$ 3,340.00 | 10% | \$3,028.55 |
| EW 4HR AHR H35314 | 97007-H35314 | \$ 3,340.00 | 10% | \$3,028.55 |
| EW 4HR AHR H35315 | 97007-H35315 | \$ 1,464.00 | 10% | \$1,327.48 |
| EW 4HR AHR H35318 | 97007-H35318 | \$ 705.00 | 10% | \$639.26 |
| EW 4HR AHR H35319 | 97007-H35319 | \$ 932.00 | 10% | \$845.09 |
| EW 4HR AHR H35320 | 97007-H35320 | \$ 967.00 | 10% | \$876.83 |
| EW 4HR AHR H35321 | 97007-H35321 | \$ 1,231.00 | 10% | \$1,116.21 |
| EW 4HR AHR H35322 | 97007-H35322 | \$ 1,493.00 | 10% | \$1,353.78 |
| EW 4HR AHR H35323 | 97007-H35323 | \$ 1,464.00 | 10% | \$1,327.48 |
| EW 4HR AHR H35328 | 97007-H35328 | \$ 125.00 | 10% | \$113.34 |
| EW 4HR AHR H35330 | 97007-H35330 | \$ 104.00 | 10% | \$94.30 |
| EW 4HR AHR H35340 | 97007-H35340 | \$ 3,113.00 | 10% | \$2,822.71 |
| EW 4HR AHR H35341 | 97007-H35341 | \$ 3,113.00 | 10% | \$2,822.71 |
| EW 4HR AHR H35342 | 97007-H35342 | \$ 2,756.00 | 10% | \$2,499.00 |
| EW 4HR AHR H35343 | 97007-H35343 | \$ 3,113.00 | 10% | \$2,822.71 |
| EW 4HR AHR H35344 | 97007-H35344 | \$ 3,252.00 | 10% | \$2,948.75 |
| EW 4HR AHR H35345 | 97007-H35345 | \$ 3,252.00 | 10% | \$2,948.75 |
| EW 4HR AHR H35346 | 97007-H35346 | \$ 2,855.00 | 10% | \$2,588.77 |
| EW 4HR AHR H35347 | 97007-H35347 | \$ 3,252.00 | 10% | \$2,948.75 |
| EW 4HR AHR H35349 | 97007-H35349 | \$ 3,583.00 | 10% | \$3,248.89 |
| EW 4HR AHR H35350 | 97007-H35350 | \$ 3,583.00 | 10% | \$3,248.89 |
| EW 4HR AHR H35351 | 97007-H35351 | \$ 3,125.00 | 10% | \$2,833.59 |
| EW 4HR AHR H35352 | 97007-H35352 | \$ 3,583.00 | 10% | \$3,248.89 |
| EW 4HR AHR H35359 | 97007-H35359 | \$ 1,231.00 | 10% | \$1,116.21 |
| EW 4HR AHR H35360 | 97007-H35360 | \$ 1,493.00 | 10% | \$1,353.78 |
| EW 4HR AHR H35361 | 97007-H35361 | \$ 1,464.00 | 10% | \$1,327.48 |
| EW 4HR AHR H35362 | 97007-H35362 | \$ 705.00 | 10% | \$639.26 |
| EW 4HR AHR H35366 | 97007-H35366 | \$ 1,567.00 | 10% | \$1,420.88 |
| EW 4HR AHR H35367 | 97007-H35367 | \$ 1,829.00 | 10% | \$1,658.45 |
| EW 4HR AHR H35368 | 97007-H35368 | \$ 2,789.00 | 10% | \$2,528.93 |
| EW 4HR AHR H35369 | 97007-H35369 | \$ 910.00 | 10% | \$825.14 |
| EW 4HR AHR H35370 | 97007-H35370 | \$ 1,271.00 | 10% | \$1,152.48 |
| EW 4HR AHR H35375 | 97007-H35375 | \$ 763.00 | 10% | \$691.85 |
| EW 4HR AHR H35376 | 97007-H35376 | \$ 1,145.00 | 10% | \$1,038.23 |
| EW 4HR AHR H35377 | 97007-H35377 | \$ 477.00 | 10% | \$432.52 |

| | | | | |
|-------------------|--------------|-------------|-----|------------|
| EW 4HR AHR H35378 | 97007-H35378 | \$ 763.00 | 10% | \$691.85 |
| EW 4HR AHR H35379 | 97007-H35379 | \$ 477.00 | 10% | \$432.52 |
| EW 4HR AHR H35380 | 97007-H35380 | \$ 859.00 | 10% | \$778.90 |
| EW 4HR AHR H35381 | 97007-H35381 | \$ 1,049.00 | 10% | \$951.18 |
| EW 4HR AHR H35384 | 97007-H35384 | \$ 344.00 | 10% | \$311.92 |
| EW 4HR AHR H35385 | 97007-H35385 | \$ 458.00 | 10% | \$415.29 |
| EW 4HR AHR H35386 | 97007-H35386 | \$ 763.00 | 10% | \$691.85 |
| EW 4HR AHR H35387 | 97007-H35387 | \$ 714.00 | 10% | \$647.42 |
| EW 4HR AHR H35388 | 97007-H35388 | \$ 528.00 | 10% | \$478.76 |
| EW 4HR AHR H35389 | 97007-H35389 | \$ 297.00 | 10% | \$269.30 |
| EW 4HR AHR H35390 | 97007-H35390 | \$ 256.00 | 10% | \$232.13 |
| EW 4HR AHR H35391 | 97007-H35391 | \$ 566.00 | 10% | \$513.22 |
| EW 4HR AHR H35392 | 97007-H35392 | \$ 859.00 | 10% | \$778.90 |
| EW 4HR AHR H35393 | 97007-H35393 | \$ 1,145.00 | 10% | \$1,038.23 |
| EW 4HR AHR H35394 | 97007-H35394 | \$ 210.00 | 10% | \$190.42 |
| EW 4HR AHR H35395 | 97007-H35395 | \$ 172.00 | 10% | \$155.96 |
| EW 4HR AHR H35396 | 97007-H35396 | \$ 210.00 | 10% | \$190.42 |
| EW 4HR AHR H35397 | 97007-H35397 | \$ 172.00 | 10% | \$155.96 |
| EW 4HR AHR H35398 | 97007-H35398 | \$ 534.00 | 10% | \$484.20 |
| EW 4HR AHR H35399 | 97007-H35399 | \$ 649.00 | 10% | \$588.48 |
| EW 4HR AHR H35400 | 97007-H35400 | \$ 718.00 | 10% | \$651.05 |
| EW 4HR AHR H35401 | 97007-H35401 | \$ 382.00 | 10% | \$346.38 |
| EW 4HR AHR H35415 | 97007-H35415 | \$ 266.00 | 10% | \$241.20 |
| EW 4HR AHR H35416 | 97007-H35416 | \$ 266.00 | 10% | \$241.20 |
| EW 4HR AHR H35426 | 97007-H35426 | \$ 297.00 | 10% | \$269.30 |
| EW 4HR AHR H35427 | 97007-H35427 | \$ 714.00 | 10% | \$647.42 |
| EW 4HR AHR H35428 | 97007-H35428 | \$ 256.00 | 10% | \$232.13 |
| EW 4HR AHR H35429 | 97007-H35429 | \$ 566.00 | 10% | \$513.22 |
| EW 4HR AHR H35430 | 97007-H35430 | \$ 595.00 | 10% | \$539.52 |
| EW 4HR AHR H35431 | 97007-H35431 | \$ 595.00 | 10% | \$539.52 |
| EW 4HR AHR H35432 | 97007-H35432 | \$ 493.00 | 10% | \$447.03 |
| EW 4HR AHR H35433 | 97007-H35433 | \$ 757.00 | 10% | \$686.41 |
| EW 4HR AHR H35434 | 97007-H35434 | \$ 851.00 | 10% | \$771.64 |
| EW 4HR AHR H35435 | 97007-H35435 | \$ 851.00 | 10% | \$771.64 |
| EW 4HR AHR H35436 | 97007-H35436 | \$ 1,431.00 | 10% | \$1,297.56 |
| EW 4HR AHR H35437 | 97007-H35437 | \$ 1,431.00 | 10% | \$1,297.56 |
| EW 4HR AHR H35438 | 97007-H35438 | \$ 1,431.00 | 10% | \$1,297.56 |
| EW 4HR AHR H35439 | 97007-H35439 | \$ 1,431.00 | 10% | \$1,297.56 |
| EW 4HR AHR H35440 | 97007-H35440 | \$ 757.00 | 10% | \$686.41 |
| EW 4HR AHR H35441 | 97007-H35441 | \$ 757.00 | 10% | \$686.41 |
| EW 4HR AHR H35442 | 97007-H35442 | \$ 757.00 | 10% | \$686.41 |
| EW 4HR AHR H35443 | 97007-H35443 | \$ 3,930.00 | 10% | \$3,563.53 |

| | | | | |
|------------------------------|-------------------------|-------------|-----|------------|
| EW 4HR AHR H35444 | 97007-H35444 | \$ 4,213.00 | 10% | \$3,820.14 |
| EW 4HR AHR H35445 | 97007-H35445 | \$ 3,783.00 | 10% | \$3,430.24 |
| EW 4HR AHR H35446 | 97007-H35446 | \$ 3,711.00 | 10% | \$3,364.95 |
| EW 4HR AHR H35447 | 97007-H35447 | \$ 4,295.00 | 10% | \$3,894.49 |
| EW 4HR AHR H35448 | 97007-H35448 | \$ 4,114.00 | 10% | \$3,730.37 |
| EW 4HR AHR H35449 | 97007-H35449 | \$ 3,036.00 | 10% | \$2,752.89 |
| EW 4HR AHR H35450 | 97007-H35450 | \$ 3,212.00 | 10% | \$2,912.48 |
| EW 4HR AHR H35451 | 97007-H35451 | \$ 6,614.00 | 10% | \$5,997.24 |
| EW 4HR AHR H35452 | 97007-H35452 | \$ 6,614.00 | 10% | \$5,997.24 |
| EW 4HR AHR H35453 | 97007-H35453 | \$ 4,213.00 | 10% | \$3,820.14 |
| EW 4HR AHR H35454 | 97007-H35454 | \$ 3,930.00 | 10% | \$3,563.53 |
| EW 4HR AHR H35455 | 97007-H35455 | \$ 967.00 | 10% | \$876.83 |
| EW 4HR AHR H35456 | 97007-H35456 | \$ 1,193.00 | 10% | \$1,081.75 |
| EW 4HR AHR H35457 | 97007-H35457 | \$ 1,075.00 | 10% | \$974.76 |
| EW 4HR AHR H35458 | 97007-H35458 | \$ 1,175.00 | 10% | \$1,065.43 |
| EW 4HR AHR H35471 | 97007-H35471 | \$ 967.00 | 10% | \$876.83 |
| EW 4HR AHR H35600 | 97007-H35600 | \$ 419.00 | 10% | \$379.93 |
| EW 4HR AHR H35601 | 97007-H35601 | \$ 419.00 | 10% | \$379.93 |
| EW 4HR AHR H35602 | 97007-H35602 | \$ 613.00 | 10% | \$555.84 |
| EW 4HR AHR H35603 | 97007-H35603 | \$ 613.00 | 10% | \$555.84 |
| EW 4HR AHR H35604 | 97007-H35604 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H35605 | 97007-H35605 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR AHR H35606 | 97007-H35606 | \$ 876.00 | 10% | \$794.31 |
| EW 4HR AHR H35607 | 97007-H35607 | \$ 872.00 | 10% | \$790.69 |
| EW 4HR AHR ISW-24W-4X | 97007-ISW-24W-4X | \$ 1,017.00 | 10% | \$922.16 |
| EW 4HR AHR ISW-4W-4WS-4X | 97007-ISW-4W-4WS-4X | \$ 645.00 | 10% | \$584.85 |
| EW 4HR AHR BD MSM128 | 97007-MSM128 | \$ 3,326.00 | 10% | \$3,015.85 |
| EW 4HR AHR BD MSM48C | 97007-MSM48C | \$ 2,013.00 | 10% | \$1,825.29 |
| EW 4HR AHR SLX9150-48XT-DC-F | 97007-SLX9150-48XT-DC-F | \$ 2,836.00 | 10% | \$2,571.54 |
| EW 4HR AHR SLX9150-48XT-DC-R | 97007-SLX9150-48XT-DC-R | \$ 3,096.00 | 10% | \$2,807.30 |
| EW 4HR AHR SLX9150-48Y-DC-F | 97007-SLX9150-48Y-DC-F | \$ 2,715.00 | 10% | \$2,461.83 |

| | | | | |
|------------------------------|------------------------|--------------|-----|--------------------|
| EW 4HR AHR SLX9150-48Y-DC-R | 97007-SLX9150-48Y-DC-R | \$ 2,965.00 | 10% | <i>\$2,688.51</i> |
| EW 4HR AHR SLX9740-40C | 97007-SLX9740-40C | \$ 12,202.00 | 10% | <i>\$11,064.16</i> |
| EW 4HR AHR SLX9740-40C-AC-F | 97007-SLX9740-40C-AC-F | \$ 12,202.00 | 10% | <i>\$11,064.16</i> |
| EW 4HR AHR SLX9740-40C-AC-R | 97007-SLX9740-40C-AC-R | \$ 12,202.00 | 10% | <i>\$11,064.16</i> |
| EW 4HR AHR SLX9740-40C-DC-F | 97007-SLX9740-40C-DC-F | \$ 12,202.00 | 10% | <i>\$11,064.16</i> |
| EW 4HR AHR SLX9740-80C | 97007-SLX9740-80C | \$ 22,946.00 | 10% | <i>\$20,806.29</i> |
| EW 4HR AHR SLX9740-80C-AC-F | 97007-SLX9740-80C-AC-F | \$ 22,946.00 | 10% | <i>\$20,806.29</i> |
| EW 4HR AHR SLX9740-80C-AC-R | 97007-SLX9740-80C-AC-R | \$ 22,946.00 | 10% | <i>\$20,806.29</i> |
| EW 4HR AHR SLX9740-80C-DC-F | 97007-SLX9740-80C-DC-F | \$ 22,946.00 | 10% | <i>\$20,806.29</i> |
| EW 4HR AHR V300-8P-2X | 97007-V300-8P-2X | \$ 162.00 | 10% | <i>\$146.89</i> |
| EW 4HR AHR V300-8T-2X | 97007-V300-8T-2X | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR AHR V300HT-8P-2X | 97007-V300HT-8P-2X | \$ 370.00 | 10% | <i>\$335.50</i> |
| EW 4HR AHR V300HT-8T-2X | 97007-V300HT-8T-2X | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW 4HR AHR Summit VIM-SS | 97007-VIM-SS | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW 4HR AHR Summit VIM-SSV80 | 97007-VIM-SSV80 | \$ 309.00 | 10% | <i>\$280.19</i> |
| EW 4HR AHR Summit VIM2-SS | 97007-VIM2-SS | \$ 193.00 | 10% | <i>\$175.00</i> |
| EW 4HR AHR Summit VIM2-SS128 | 97007-VIM2-SS128 | \$ 683.00 | 10% | <i>\$619.31</i> |

| | | | | |
|----------------------------------|-----------------------------|-------------|-----|-------------------|
| EW 4HR AHR Summit VIM2-V80 | 97007-VIM2-V80 | \$ 729.00 | 10% | <i>\$661.02</i> |
| EW 4HR AHR Summit VIM210G4X | 97007-VIM210G4X | \$ 1,268.00 | 10% | <i>\$1,149.76</i> |
| EW 4HR AHR VIM5-2Q | 97007-VIM5-2Q | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW 4HR AHR VIM5-2Y | 97007-VIM5-2Y | \$ 254.00 | 10% | <i>\$230.31</i> |
| EW 4HR AHR VIM5-4X | 97007-VIM5-4X | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW 4HR AHR VIM5-4XE | 97007-VIM5-4XE | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW 4HR AHR VIM5-4Y | 97007-VIM5-4Y | \$ 326.00 | 10% | <i>\$295.60</i> |
| EW 4HR AHR VIM5-4YE | 97007-VIM5-4YE | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW 4HR AHR VSP4900-12MXU-12XE | 97007-VSP4900-12MXU-12XE | \$ 1,292.00 | 10% | <i>\$1,171.52</i> |
| EW 4HR AHR VSP4900-12MXU-12XE-B1 | 97007-VSP4900-12MXU-12XE-B1 | \$ 1,292.00 | 10% | <i>\$1,171.52</i> |
| EW 4HR AHR VSP4900-24S | 97007-VSP4900-24S | \$ 705.00 | 10% | <i>\$639.26</i> |
| EW 4HR AHR VSP4900-24S-B3 | 97007-VSP4900-24S-B3 | \$ 705.00 | 10% | <i>\$639.26</i> |
| EW 4HR AHR VSP4900-24XE | 97007-VSP4900-24XE | \$ 1,292.00 | 10% | <i>\$1,171.52</i> |
| EW 4HR AHR VSP4900-24XE-B3 | 97007-VSP4900-24XE-B3 | \$ 1,292.00 | 10% | <i>\$1,171.52</i> |
| EW 4HR AHR X435-24P-4S | 97007-X435-24P-4S | \$ 286.00 | 10% | <i>\$259.33</i> |
| EW 4HR AHR X435-24T-4S | 97007-X435-24T-4S | \$ 157.00 | 10% | <i>\$142.36</i> |
| EW 4HR AHR X435-8P-2T-W | 97007-X435-8P-2T-W | \$ 157.00 | 10% | <i>\$142.36</i> |
| EW 4HR AHR X435-8P-4S | 97007-X435-8P-4S | \$ 142.00 | 10% | <i>\$128.76</i> |

| | | | | |
|------------------------------|--------------------|-------------|-----|-------------------|
| EW 4HR AHR X435-8T-4S | 97007-X435-8T-4S | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW 4HR AHR Summit X460-24P | 97007-X460-24P | \$ 1,189.00 | 10% | <i>\$1,078.13</i> |
| EW 4HR AHR Summit X460-24T | 97007-X460-24T | \$ 829.00 | 10% | <i>\$751.70</i> |
| EW 4HR AHR Summit X460-24TDC | 97007-X460-24TDC | \$ 1,225.00 | 10% | <i>\$1,110.77</i> |
| EW 4HR AHR Summit X460-24X | 97007-X460-24X | \$ 1,549.00 | 10% | <i>\$1,404.56</i> |
| EW 4HR AHR Summit X460-24XDC | 97007-X460-24XDC | \$ 1,726.00 | 10% | <i>\$1,565.05</i> |
| EW 4HR AHR Summit X460-48P | 97007-X460-48P | \$ 1,549.00 | 10% | <i>\$1,404.56</i> |
| EW 4HR AHR Summit X460-48T | 97007-X460-48T | \$ 1,321.00 | 10% | <i>\$1,197.82</i> |
| EW 4HR AHR Summit X460-48TDC | 97007-X460-48TDC | \$ 1,673.00 | 10% | <i>\$1,516.99</i> |
| EW 4HR AHR Summit X460-48X | 97007-X460-48X | \$ 2,055.00 | 10% | <i>\$1,863.37</i> |
| EW 4HR AHR Summit X460-48XDC | 97007-X460-48XDC | \$ 2,004.00 | 10% | <i>\$1,817.13</i> |
| EW 4HR AHR X465-24MU | 97007-X465-24MU | \$ 1,493.00 | 10% | <i>\$1,353.78</i> |
| EW 4HR AHR X465-24S | 97007-X465-24S | \$ 705.00 | 10% | <i>\$639.26</i> |
| EW 4HR AHR X465-24S-B3 | 97007-X465-24S-B3 | \$ 705.00 | 10% | <i>\$639.26</i> |
| EW 4HR AHR X465-24W | 97007-X465-24W | \$ 705.00 | 10% | <i>\$639.26</i> |
| EW 4HR AHR X465-24XE | 97007-X465-24XE | \$ 1,292.00 | 10% | <i>\$1,171.52</i> |
| EW 4HR AHR X465-24XE-B3 | 97007-X465-24XE-B3 | \$ 1,292.00 | 10% | <i>\$1,171.52</i> |
| EW 4HR AHR X465-48P | 97007-X465-48P | \$ 967.00 | 10% | <i>\$876.83</i> |
| EW 4HR AHR X465-48T | 97007-X465-48T | \$ 932.00 | 10% | <i>\$845.09</i> |
| EW 4HR AHR X465-48W | 97007-X465-48W | \$ 1,231.00 | 10% | <i>\$1,116.21</i> |
| EW 4HR AHR X465i-48W | 97007-X465i-48W | \$ 1,464.00 | 10% | <i>\$1,327.48</i> |

| | | | | |
|----------------------------|-----------------------|-------------|-----|-------------------|
| EW 4HR AHR X465i-48W-B1-S1 | 97007-X465i-48W-B1-S1 | \$ 1,464.00 | 10% | <i>\$1,327.48</i> |
| EW 4HR AHR X465i-48W-B2-S1 | 97007-X465i-48W-B2-S1 | \$ 1,464.00 | 10% | <i>\$1,327.48</i> |
| EW 4HR AHR Summit X480-24X | 97007-X480-24X | \$ 1,905.00 | 10% | <i>\$1,727.36</i> |
| EW 4HR AHR Summit X480-48T | 97007-X480-48T | \$ 1,905.00 | 10% | <i>\$1,727.36</i> |
| EW 4HR AHR Summit X480-48X | 97007-X480-48X | \$ 2,529.00 | 10% | <i>\$2,293.17</i> |
| EW 4HR AHR X695-48Y-8C | 97007-X695-48Y-8C | \$ 3,369.00 | 10% | <i>\$3,054.84</i> |
| EW 4HR AHR XA1440 | 97007-XA1440 | \$ 353.00 | 10% | <i>\$320.08</i> |
| EW 4HR AHR XA1480 | 97007-XA1480 | \$ 472.00 | 10% | <i>\$427.99</i> |
| EW 4HR AHR Summit XGM3-2SF | 97007-XGM3-2SF | \$ 309.00 | 10% | <i>\$280.19</i> |
| EW 4HR AHR XR600 | 97007-XR600 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR AHR -ZR-XFP | 97007-ZR-XFP | \$ 1,916.00 | 10% | <i>\$1,737.33</i> |
| EW 4HR ONSITE Optics 10200 | 97008-10200 | \$ 3,149.00 | 10% | <i>\$2,855.36</i> |
| EW 4HR ONSITE Optics 10320 | 97008-10320 | \$ 3,459.00 | 10% | <i>\$3,136.45</i> |
| EW 4HR ONSITE 10330 | 97008-10330 | \$ 8,488.00 | 10% | <i>\$7,696.49</i> |
| EW 4HR ONSITE 10331 | 97008-10331 | \$ 3,915.00 | 10% | <i>\$3,549.93</i> |
| EW 4HR ONSITE 10335 | 97008-10335 | \$ 5,974.00 | 10% | <i>\$5,416.92</i> |
| EW 4HR ONSITE 10403 | 97008-10403 | \$ 7,410.00 | 10% | <i>\$6,719.02</i> |
| EW 4HR ONSITE 10404 | 97008-10404 | \$ 3,635.00 | 10% | <i>\$3,296.04</i> |
| EW 4HR ONSITE 10441 | 97008-10441 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW 4HR ONSITE 10442 | 97008-10442 | \$ 2,595.00 | 10% | <i>\$2,353.02</i> |
| EW 4HR ONSITE 1130C | 97008-1130C | \$ 1,679.00 | 6% | <i>\$1,590.10</i> |
| EW 4HR ONSITE E4G 16119 | 97008-16119 | \$ 446.00 | 10% | <i>\$404.41</i> |
| EW 4HR ONSITE E4G 16120 | 97008-16120 | \$ 558.00 | 10% | <i>\$505.97</i> |
| EW 4HR ONSITE E4G 16126 | 97008-16126 | \$ 446.00 | 10% | <i>\$404.41</i> |
| EW 4HR ONSITE E4G 16127 | 97008-16127 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW 4HR ONSITE 16172 | 97008-16172 | \$ 465.00 | 10% | <i>\$421.64</i> |
| EW 4HR ONSITE -16172T | 97008-16172T | \$ 561.00 | 10% | <i>\$508.69</i> |
| EW 4HR ONSITE 16173 | 97008-16173 | \$ 482.00 | 10% | <i>\$437.05</i> |
| EW 4HR ONSITE -16173T | 97008-16173T | \$ 579.00 | 10% | <i>\$525.01</i> |
| EW 4HR ONSITE 16174 | 97008-16174 | \$ 735.00 | 10% | <i>\$666.46</i> |
| EW 4HR ONSITE 16175 | 97008-16175 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW 4HR ONSITE 16176 | 97008-16176 | \$ 688.00 | 10% | <i>\$623.84</i> |

| | | | | |
|----------------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE 16177 | 97008-16177 | \$ 675.00 | 10% | \$612.06 |
| EW 4HR ONSITE -16177T | 97008-16177T | \$ 857.00 | 10% | \$777.08 |
| EW 4HR ONSITE 16178 | 97008-16178 | \$ 997.00 | 10% | \$904.03 |
| EW 4HR ONSITE 16179 | 97008-16179 | \$ 1,019.00 | 10% | \$923.98 |
| EW 4HR ONSITE -16179T | 97008-16179T | \$ 1,233.00 | 10% | \$1,118.02 |
| EW 4HR ONSITE 16301T | 97008-16301T | \$ 2,664.00 | 10% | \$2,415.58 |
| EW 4HR ONSITE 16303T | 97008-16303T | \$ 2,664.00 | 10% | \$2,415.58 |
| EW 4HR ONSITE 16304T | 97008-16304T | \$ 3,556.00 | 10% | \$3,224.40 |
| EW 4HR ONSITE 16401T | 97008-16401T | \$ 1,249.00 | 10% | \$1,132.53 |
| EW 4HR ONSITE 16402T | 97008-16402T | \$ 1,901.00 | 10% | \$1,723.73 |
| EW 4HR ONSITE 16403T | 97008-16403T | \$ 1,690.00 | 10% | \$1,532.41 |
| EW 4HR ONSITE 16404T | 97008-16404T | \$ 1,690.00 | 10% | \$1,532.41 |
| EW 4HR ONSITE 16405T | 97008-16405T | \$ 2,218.00 | 10% | \$2,011.17 |
| EW 4HR ONSITE 16406T | 97008-16406T | \$ 2,966.00 | 10% | \$2,689.42 |
| EW 4HR ONSITE E4G 16431 | 97008-16431 | \$ 1,877.00 | 10% | \$1,701.97 |
| EW 4HR ONSITE E4G 16432 | 97008-16432 | \$ 2,028.00 | 10% | \$1,838.89 |
| EW 4HR ONSITE E4G 16440 | 97008-16440 | \$ 1,169.00 | 10% | \$1,059.99 |
| EW 4HR ONSITE E4G 16441 | 97008-16441 | \$ 1,052.00 | 10% | \$953.90 |
| EW 4HR ONSITE E4G 16442 | 97008-16442 | \$ 468.00 | 10% | \$424.36 |
| EW 4HR ONSITE E4G 16444 | 97008-16444 | \$ 234.00 | 10% | \$212.18 |
| EW 4HR ONSITE Summit 16501 | 97008-16501 | \$ 257.00 | 10% | \$233.03 |
| EW 4HR ONSITE 16501T | 97008-16501T | \$ 330.00 | 10% | \$299.23 |
| EW 4HR ONSITE Summit 16502 | 97008-16502 | \$ 370.00 | 10% | \$335.50 |
| EW 4HR ONSITE 16502T | 97008-16502T | \$ 448.00 | 10% | \$406.22 |
| EW 4HR ONSITE Summit 16503 | 97008-16503 | \$ 310.00 | 10% | \$281.09 |
| EW 4HR ONSITE 16503T | 97008-16503T | \$ 411.00 | 10% | \$372.67 |
| EW 4HR ONSITE Summit 16504 | 97008-16504 | \$ 499.00 | 10% | \$452.47 |
| EW 4HR ONSITE 16504T | 97008-16504T | \$ 603.00 | 10% | \$546.77 |
| EW 4HR ONSITE Summit 16505 | 97008-16505 | \$ 563.00 | 10% | \$510.50 |
| EW 4HR ONSITE 16505T | 97008-16505T | \$ 682.00 | 10% | \$618.40 |
| EW 4HR ONSITE Summit 16506 | 97008-16506 | \$ 857.00 | 10% | \$777.08 |
| EW 4HR ONSITE 16506T | 97008-16506T | \$ 1,051.00 | 10% | \$952.99 |
| EW 4HR ONSITE Summit 16507 | 97008-16507 | \$ 779.00 | 10% | \$706.36 |
| EW 4HR ONSITE 16507T | 97008-16507T | \$ 941.00 | 10% | \$853.25 |

| | | | | |
|----------------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE Summit 16508 | 97008-16508 | \$ 976.00 | 10% | \$884.99 |
| EW 4HR ONSITE 16508T | 97008-16508T | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4HR ONSITE Summit 16509 | 97008-16509 | \$ 976.00 | 10% | \$884.99 |
| EW 4HR ONSITE 16509T | 97008-16509T | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4HR ONSITE Summit 16510 | 97008-16510 | \$ 1,168.00 | 10% | \$1,059.08 |
| EW 4HR ONSITE 16510T | 97008-16510T | \$ 1,403.00 | 10% | \$1,272.17 |
| EW 4hr On-site-16513 | 97008-16513 | \$ 779.00 | 10% | \$706.36 |
| EW 4hr On-site-16514 | 97008-16514 | \$ 1,145.00 | 10% | \$1,038.23 |
| EW 4HR ONSITE 16515 | 97008-16515 | \$ 194.00 | 10% | \$175.91 |
| EW 4hr On-site-16516 | 97008-16516 | \$ 215.00 | 10% | \$194.95 |
| EW 4HR ONSITE 16517 | 97008-16517 | \$ 419.00 | 10% | \$379.93 |
| EW 4hr On-site-16518 | 97008-16518 | \$ 378.00 | 10% | \$342.75 |
| EW-4HR On-SITE 16519 | 97008-16519 | \$ 388.00 | 10% | \$351.82 |
| EW-4HR On-SITE 16520 | 97008-16520 | \$ 639.00 | 10% | \$579.41 |
| EW 4HR ONSITE 16530 | 97008-16530 | \$ 229.00 | 10% | \$207.65 |
| EW 4HR ONSITE 16531 | 97008-16531 | \$ 320.00 | 10% | \$290.16 |
| EW 4HR ONSITE 16531T | 97008-16531T | \$ 359.00 | 10% | \$325.52 |
| EW 4HR ONSITE 16532 | 97008-16532 | \$ 320.00 | 10% | \$290.16 |
| EW 4HR ONSITE 16532T | 97008-16532T | \$ 359.00 | 10% | \$325.52 |
| EW 4HR ONSITE 16533 | 97008-16533 | \$ 450.00 | 10% | \$408.04 |
| EW 4HR ONSITE 16533T | 97008-16533T | \$ 495.00 | 10% | \$448.84 |
| EW 4HR ONSITE 16534 | 97008-16534 | \$ 479.00 | 10% | \$434.33 |
| EW 4HR ONSITE 16535 | 97008-16535 | \$ 708.00 | 10% | \$641.98 |
| EW 4HR ONSITE 16535A | 97008-16535A | \$ 708.00 | 10% | \$641.98 |
| EW 4HR ONSITE 16535T | 97008-16535T | \$ 782.00 | 10% | \$709.08 |
| EW 4HR ONSITE 16536 | 97008-16536 | \$ 326.00 | 10% | \$295.60 |
| EW 4HR ONSITE 16537 | 97008-16537 | \$ 450.00 | 10% | \$408.04 |
| EW 4HR ONSITE 16538 | 97008-16538 | \$ 541.00 | 10% | \$490.55 |
| EW 4HR ONSITE 16538T | 97008-16538T | \$ 655.00 | 10% | \$593.92 |
| EW 4HR ONSITE 16539 | 97008-16539 | \$ 698.00 | 10% | \$632.91 |
| EW 4HR ONSITE 16540 | 97008-16540 | \$ 498.00 | 10% | \$451.56 |
| EW 4HR ONSITE 16541 | 97008-16541 | \$ 188.00 | 10% | \$170.47 |
| EW 4HR ONSITE 16560 | 97008-16560 | \$ 109.00 | 10% | \$98.84 |
| EW 4HR ONSITE 16561 | 97008-16561 | \$ 157.00 | 10% | \$142.36 |
| EW 4HR ONSITE 16562 | 97008-16562 | \$ 192.00 | 10% | \$174.10 |
| EW 4HR ONSITE 16563 | 97008-16563 | \$ 253.00 | 10% | \$229.41 |
| EW 4HR ONSITE 16564 | 97008-16564 | \$ 315.00 | 10% | \$285.63 |
| EW 4HR ONSITE 16565 | 97008-16565 | \$ 462.00 | 10% | \$418.92 |
| EW 4HR ONSITE 16566 | 97008-16566 | \$ 75.00 | 10% | \$68.01 |

| | | | | |
|-----------------------|--------------|-------------|-----|-------------------|
| EW 4HR ONSITE 16567 | 97008-16567 | \$ 130.00 | 10% | <i>\$117.88</i> |
| EW 4HR ONSITE 16568 | 97008-16568 | \$ 109.00 | 10% | <i>\$98.84</i> |
| EW 4HR ONSITE 16569 | 97008-16569 | \$ 171.00 | 10% | <i>\$155.05</i> |
| EW 4HR ONSITE 16570 | 97008-16570 | \$ 192.00 | 10% | <i>\$174.10</i> |
| EW 4HR ONSITE 16571 | 97008-16571 | \$ 315.00 | 10% | <i>\$285.63</i> |
| EW 4HR ONSITE 16701 | 97008-16701 | \$ 684.00 | 10% | <i>\$620.22</i> |
| EW 4HR ONSITE 16702 | 97008-16702 | \$ 1,009.00 | 10% | <i>\$914.91</i> |
| EW 4HR ONSITE 16703 | 97008-16703 | \$ 794.00 | 10% | <i>\$719.96</i> |
| EW 4HR ONSITE -16703T | 97008-16703T | \$ 958.00 | 10% | <i>\$868.67</i> |
| EW 4HR ONSITE 16704 | 97008-16704 | \$ 1,163.00 | 10% | <i>\$1,054.55</i> |
| EW 4HR ONSITE -16704T | 97008-16704T | \$ 1,404.00 | 10% | <i>\$1,273.08</i> |
| EW 4HR ONSITE 16705 | 97008-16705 | \$ 1,009.00 | 10% | <i>\$914.91</i> |
| EW 4HR ONSITE -16705T | 97008-16705T | \$ 1,215.00 | 10% | <i>\$1,101.70</i> |
| EW 4HR ONSITE 16706 | 97008-16706 | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW 4HR ONSITE -16706T | 97008-16706T | \$ 1,846.00 | 10% | <i>\$1,673.86</i> |
| EW 4HR ONSITE 16710 | 97008-16710 | \$ 304.00 | 10% | <i>\$275.65</i> |
| EW 4HR ONSITE 16710T | 97008-16710T | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW 4HR ONSITE 16711 | 97008-16711 | \$ 128.00 | 10% | <i>\$116.06</i> |
| EW 4HR ONSITE 16711T | 97008-16711T | \$ 157.00 | 10% | <i>\$142.36</i> |
| EW 4HR ONSITE 16712 | 97008-16712 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW 4HR ONSITE 16712T | 97008-16712T | \$ 210.00 | 10% | <i>\$190.42</i> |
| EW 4HR ONSITE 16713 | 97008-16713 | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW 4HR ONSITE 16713T | 97008-16713T | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW 4HR ONSITE 16715 | 97008-16715 | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR ONSITE 16715T | 97008-16715T | \$ 157.00 | 10% | <i>\$142.36</i> |
| EW 4HR ONSITE 16716 | 97008-16716 | \$ 535.00 | 10% | <i>\$485.11</i> |
| EW 4HR ONSITE -16716T | 97008-16716T | \$ 646.00 | 10% | <i>\$585.76</i> |
| EW 4HR ONSITE 16717 | 97008-16717 | \$ 809.00 | 10% | <i>\$733.56</i> |
| EW 4HR ONSITE 16718 | 97008-16718 | \$ 580.00 | 10% | <i>\$525.92</i> |
| EW 4HR ONSITE -16718T | 97008-16718T | \$ 697.00 | 10% | <i>\$632.00</i> |
| EW 4HR ONSITE 16719 | 97008-16719 | \$ 870.00 | 10% | <i>\$788.87</i> |
| EW 4HR ONSITE -16719T | 97008-16719T | \$ 1,041.00 | 10% | <i>\$943.93</i> |
| EW 4HR ONSITE 16720 | 97008-16720 | \$ 1,293.00 | 10% | <i>\$1,172.43</i> |
| EW 4HR ONSITE 16720T | 97008-16720T | \$ 1,505.00 | 10% | <i>\$1,364.66</i> |
| EW 4HR ONSITE 16756 | 97008-16756 | \$ 942.00 | 10% | <i>\$854.16</i> |
| EW 4HR ONSITE 16756T | 97008-16756T | \$ 1,114.00 | 10% | <i>\$1,010.12</i> |
| EW 4HR ONSITE 16757 | 97008-16757 | \$ 890.00 | 10% | <i>\$807.01</i> |
| EW 4HR ONSITE 16757T | 97008-16757T | \$ 1,054.00 | 10% | <i>\$955.71</i> |
| EW 4HR ONSITE 16790 | 97008-16790 | \$ 2,075.00 | 10% | <i>\$1,881.51</i> |
| EW 4HR ONSITE 16791 | 97008-16791 | \$ 2,676.00 | 10% | <i>\$2,426.46</i> |
| EW 4HR ONSITE 16801 | 97008-16801 | \$ 273.00 | 10% | <i>\$247.54</i> |
| EW 4HR ONSITE 16802 | 97008-16802 | \$ 305.00 | 10% | <i>\$276.56</i> |

| | | | | |
|-----------------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE 16803 | 97008-16803 | \$ 326.00 | 10% | \$295.60 |
| EW 4HR ONSITE 16804 | 97008-16804 | \$ 408.00 | 10% | \$369.95 |
| EW 4HR ONSITE 16805 | 97008-16805 | \$ 83.00 | 10% | \$75.26 |
| EW 4HR ONSITE 16806 | 97008-16806 | \$ 70.00 | 10% | \$63.47 |
| EW 4HR ONSITE Summit 17101 | 97008-17101 | \$ 3,945.00 | 10% | \$3,577.13 |
| EW 4HR ONSITE 17101T | 97008-17101T | \$ 5,048.00 | 10% | \$4,577.27 |
| EW 4HR ONSITE Summit 17102 | 97008-17102 | \$ 3,945.00 | 10% | \$3,577.13 |
| EW 4HR ONSITE 17102T | 97008-17102T | \$ 5,048.00 | 10% | \$4,577.27 |
| EW 4HR ONSITE Summit 17103 | 97008-17103 | \$ 2,751.00 | 10% | \$2,494.47 |
| EW 4HR ONSITE Summit 17103C | 97008-17103C | \$ 2,671.00 | 10% | \$2,421.93 |
| EW 4HR ONSITE 17103T | 97008-17103T | \$ 3,516.00 | 10% | \$3,188.13 |
| EW 4HR ONSITE Summit 17104 | 97008-17104 | \$ 2,751.00 | 10% | \$2,494.47 |
| EW 4HR ONSITE 17104T | 97008-17104T | \$ 3,516.00 | 10% | \$3,188.13 |
| EW 4HR ONSITE Summit 17121 | 97008-17121 | \$ 780.00 | 10% | \$707.27 |
| EW 4HR ONSITE Summit 17122 | 97008-17122 | \$ 495.00 | 10% | \$448.84 |
| EW 4HR ONSITE -17200 | 97008-17200 | \$ 6,217.00 | 10% | \$5,637.26 |
| EW 4HR ONSITE 17200T | 97008-17200T | \$ 7,103.00 | 10% | \$6,440.65 |
| EW 4HR ONSITE Summit 17201 | 97008-17201 | \$ 6,217.00 | 10% | \$5,637.26 |
| EW 4HR ONSITE 17201T | 97008-17201T | \$ 7,103.00 | 10% | \$6,440.65 |
| EW 4HR ONSITE Summit 17202 | 97008-17202 | \$ 6,217.00 | 10% | \$5,637.26 |
| EW 4HR ONSITE 17202T | 97008-17202T | \$ 7,103.00 | 10% | \$6,440.65 |
| EW 4HR ONSITE Summit 17203 | 97008-17203 | \$ 6,305.00 | 10% | \$5,717.06 |
| EW 4HR ONSITE 17203T | 97008-17203T | \$ 7,208.00 | 10% | \$6,535.85 |
| EW 4HR ONSITE Summit 17204 | 97008-17204 | \$ 6,305.00 | 10% | \$5,717.06 |
| EW 4HR ONSITE 17204T | 97008-17204T | \$ 7,208.00 | 10% | \$6,535.85 |
| EW 4HR ONSITE Summit 17205 | 97008-17205 | \$ 6,261.00 | 10% | \$5,677.16 |
| EW 4HR ONSITE 17205T | 97008-17205T | \$ 7,157.00 | 10% | \$6,489.61 |
| EW 4HR ONSITE Summit 17206 | 97008-17206 | \$ 6,261.00 | 10% | \$5,677.16 |
| EW 4HR ONSITE 17206T | 97008-17206T | \$ 7,157.00 | 10% | \$6,489.61 |

| | | | | |
|-------------------------|-----------------|--------------|-----|-------------|
| EW 4HR ONSITE 17300 | 97008-17300 | \$ 4,109.00 | 10% | \$3,725.84 |
| EW 4HR ONSITE 17310 | 97008-17310 | \$ 3,722.00 | 10% | \$3,374.92 |
| EW 4HR ONSITE -17310T | 97008-17310T | \$ 4,494.00 | 10% | \$4,074.93 |
| EW 4HR ONSITE 17350 | 97008-17350 | \$ 3,758.00 | 10% | \$3,407.57 |
| EW 4HR ONSITE 17360 | 97008-17360 | \$ 4,623.00 | 10% | \$4,191.91 |
| EW 4HR ONSITE 17401 | 97008-17401 | \$ 577.00 | 10% | \$523.19 |
| EW 4HR ONSITE 17401G | 97008-17401G | \$ 681.00 | 10% | \$617.50 |
| EW 4HR ONSITE 17401T | 97008-17401T | \$ 647.00 | 10% | \$586.67 |
| EW 4HR ONSITE 17402 | 97008-17402 | \$ 828.00 | 10% | \$750.79 |
| EW 4HR ONSITE 17402G | 97008-17402G | \$ 907.00 | 10% | \$822.42 |
| EW 4HR ONSITE 17402T | 97008-17402T | \$ 866.00 | 10% | \$785.25 |
| EW 4HR ONSITE 17403 | 97008-17403 | \$ 884.00 | 10% | \$801.57 |
| EW 4HR ONSITE 17404 | 97008-17404 | \$ 426.00 | 10% | \$386.28 |
| EW 4HR ONSITE 17405 | 97008-17405 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE 17700 | 97008-17700 | \$ 7,283.00 | 10% | \$6,603.86 |
| EW 4HR ONSITE 17701 | 97008-17701 | \$ 6,427.00 | 10% | \$5,827.68 |
| EW 4HR ONSITE 17702 | 97008-17702 | \$ 6,427.00 | 10% | \$5,827.68 |
| EW 4HR ONSITE 17703 | 97008-17703 | \$ 7,038.00 | 10% | \$6,381.71 |
| EW 4HR ONSITE 17704 | 97008-17704 | \$ 7,038.00 | 10% | \$6,381.71 |
| EW 4HR ONSITE 17705 | 97008-17705 | \$ 6,474.00 | 10% | \$5,870.30 |
| EW 4HR ONSITE 17706 | 97008-17706 | \$ 6,474.00 | 10% | \$5,870.30 |
| EW 4HR ONSITE 17800 | 97008-17800 | \$ 7,285.00 | 10% | \$6,605.67 |
| EW 4HR ONSITE 17810 | 97008-17810 | \$ 5,829.00 | 10% | \$5,285.45 |
| EW 4HR ONSITE 18101 | 97008-18101 | \$ 371.00 | 10% | \$336.40 |
| EW 4HR ONSITE 18102 | 97008-18102 | \$ 476.00 | 10% | \$431.61 |
| EW 4HR ONSITE 18103 | 97008-18103 | \$ 523.00 | 10% | \$474.23 |
| EW 4HR ONSITE 18104 | 97008-18104 | \$ 740.00 | 10% | \$671.00 |
| EW 4HR ONSITE 18104-6PK | 97008-18104-6PK | \$ 4,312.00 | 10% | \$3,909.91 |
| EW 4HR ONSITE 18202 | 97008-18202 | \$ 276.00 | 10% | \$250.26 |
| EW 4HR ONSITE 30135 | 97008-30135 | \$ 1,049.00 | 10% | \$951.18 |
| EW 4HR ONSITE 30136 | 97008-30136 | \$ 7,933.00 | 10% | \$7,193.25 |
| EW 4HR ONSITE 30137 | 97008-30137 | \$ 1,433.00 | 10% | \$1,299.37 |
| EW 4HR ONSITE 30138 | 97008-30138 | \$ 6,605.00 | 10% | \$5,989.08 |
| EW 4HR ONSITE 30139 | 97008-30139 | \$ 12,077.00 | 10% | \$10,950.82 |
| EW 4HR ONSITE 30912 | 97008-30912 | \$ 78.00 | 10% | \$70.73 |
| EW 4HR ONSITE 30913 | 97008-30913 | \$ 108.00 | 10% | \$97.93 |
| EW 4HR ONSITE 31012 | 97008-31012 | \$ 163.00 | 10% | \$147.80 |
| EW 4HR ONSITE 31013 | 97008-31013 | \$ 163.00 | 10% | \$147.80 |
| EW 4HR ONSITE 31014 | 97008-31014 | \$ 163.00 | 10% | \$147.80 |
| EW 4HR ONSITE 31015 | 97008-31015 | \$ 163.00 | 10% | \$147.80 |
| EW 4HR ONSITE 31016 | 97008-31016 | \$ 419.00 | 10% | \$379.93 |

| | | | | |
|---------------------|-------------|-------------|-----|------------|
| EW 4HR ONSITE 31017 | 97008-31017 | \$ 419.00 | 10% | \$379.93 |
| EW 4HR ONSITE 31018 | 97008-31018 | \$ 470.00 | 10% | \$426.17 |
| EW 4HR ONSITE 31019 | 97008-31019 | \$ 470.00 | 10% | \$426.17 |
| EW 4HR ONSITE 31025 | 97008-31025 | \$ 76.00 | 10% | \$68.91 |
| EW 4HR ONSITE 31026 | 97008-31026 | \$ 76.00 | 10% | \$68.91 |
| EW 4HR ONSITE 31028 | 97008-31028 | \$ 84.00 | 10% | \$76.17 |
| EW 4HR ONSITE 31029 | 97008-31029 | \$ 95.00 | 10% | \$86.14 |
| EW 4HR ONSITE 31031 | 97008-31031 | \$ 110.00 | 10% | \$99.74 |
| EW 4HR ONSITE 31032 | 97008-31032 | \$ 110.00 | 10% | \$99.74 |
| EW 4HR ONSITE 31034 | 97008-31034 | \$ 152.00 | 10% | \$137.83 |
| EW 4HR ONSITE 31035 | 97008-31035 | \$ 152.00 | 10% | \$137.83 |
| EW 4HR ONSITE 31050 | 97008-31050 | \$ 171.00 | 10% | \$155.05 |
| EW 4HR ONSITE 31051 | 97008-31051 | \$ 171.00 | 10% | \$155.05 |
| EW 4HR ONSITE 31055 | 97008-31055 | \$ 171.00 | 10% | \$155.05 |
| EW 4HR ONSITE 31056 | 97008-31056 | \$ 171.00 | 10% | \$155.05 |
| EW 4HR ONSITE 37101 | 97008-37101 | \$ 69.00 | 10% | \$62.57 |
| EW 4HR ONSITE 37102 | 97008-37102 | \$ 69.00 | 10% | \$62.57 |
| EW 4HR ONSITE 37103 | 97008-37103 | \$ 69.00 | 10% | \$62.57 |
| EW 4HR ONSITE 37111 | 97008-37111 | \$ 87.00 | 10% | \$78.89 |
| EW 4HR ONSITE 37112 | 97008-37112 | \$ 87.00 | 10% | \$78.89 |
| EW 4HR ONSITE 37113 | 97008-37113 | \$ 114.00 | 10% | \$103.37 |
| EW 4HR ONSITE 37114 | 97008-37114 | \$ 114.00 | 10% | \$103.37 |
| EW 4HR ONSITE 37115 | 97008-37115 | \$ 87.00 | 10% | \$78.89 |
| EW 4HR ONSITE 37116 | 97008-37116 | \$ 114.00 | 10% | \$103.37 |
| EW 4HR ONSITE 37117 | 97008-37117 | \$ 87.00 | 10% | \$78.89 |
| EW 4HR ONSITE 37121 | 97008-37121 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 37122 | 97008-37122 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 37123 | 97008-37123 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 37124 | 97008-37124 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 37125 | 97008-37125 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 37126 | 97008-37126 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 37129 | 97008-37129 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 37130 | 97008-37130 | \$ 179.00 | 10% | \$162.31 |
| EW 4HR ONSITE 39031 | 97008-39031 | \$ 152.00 | 10% | \$137.83 |
| EW 4HR ONSITE 39032 | 97008-39032 | \$ 268.00 | 10% | \$243.01 |
| EW 4HR ONSITE 39033 | 97008-39033 | \$ 152.00 | 10% | \$137.83 |
| EW 4HR ONSITE 39034 | 97008-39034 | \$ 207.00 | 10% | \$187.70 |
| EW 4HR ONSITE 39035 | 97008-39035 | \$ 1,195.00 | 10% | \$1,083.57 |
| EW 4HR ONSITE 39036 | 97008-39036 | \$ 158.00 | 10% | \$143.27 |
| EW 4HR ONSITE 39037 | 97008-39037 | \$ 158.00 | 10% | \$143.27 |
| EW 4HR ONSITE 39038 | 97008-39038 | \$ 303.00 | 10% | \$274.75 |
| EW 4HR ONSITE 39039 | 97008-39039 | \$ 303.00 | 10% | \$274.75 |

| | | | | |
|-------------------------------|-----------------------|--------------|-----|--------------------|
| EW 4HR ONSITE 39505 | 97008-39505 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW 4HR ONSITE 4120-24MW-4Y | 97008-4120-24MW-4Y | \$ 1,124.00 | 10% | <i>\$1,019.19</i> |
| EW 4HR ONSITE 4120-48MW-4Y | 97008-4120-48MW-4Y | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW 4HR ONSITE 4120C | 97008-4120C | \$ 8,099.00 | 10% | <i>\$7,343.77</i> |
| EW 4HR ONSITE 4120C-1 | 97008-4120C-1 | \$ 9,143.00 | 10% | <i>\$8,290.42</i> |
| EW 4HR ONSITE 41216 | 97008-41216 | \$ 2,501.00 | 10% | <i>\$2,267.78</i> |
| EW 4HR ONSITE 4220-12P-4X | 97008-4220-12P-4X | \$ 326.00 | 10% | <i>\$295.60</i> |
| EW 4HR ONSITE 4220-12T-4X | 97008-4220-12T-4X | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW 4HR ONSITE 4220-24P-4X | 97008-4220-24P-4X | \$ 435.00 | 10% | <i>\$394.44</i> |
| EW 4HR ONSITE 4220-24T-4X | 97008-4220-24T-4X | \$ 337.00 | 10% | <i>\$305.57</i> |
| EW 4HR ONSITE 4220-48P-4X | 97008-4220-48P-4X | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW 4HR ONSITE 4220-48T-4X | 97008-4220-48T-4X | \$ 490.00 | 10% | <i>\$444.31</i> |
| EW 4HR ONSITE 4220-4MW-20P-4X | 97008-4220-4MW-20P-4X | \$ 599.00 | 10% | <i>\$543.14</i> |
| EW 4HR ONSITE 4220-4MW-8P-4X | 97008-4220-4MW-8P-4X | \$ 425.00 | 10% | <i>\$385.37</i> |
| EW 4HR ONSITE 4220-8MW-40P-4X | 97008-4220-8MW-40P-4X | \$ 871.00 | 10% | <i>\$789.78</i> |
| EW 4HR ONSITE 4220-8X | 97008-4220-8X | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW 4HR ONSITE BD X 48001 | 97008-48001 | \$ 10,388.00 | 10% | <i>\$9,419.32</i> |
| EW 4HR ONSITE 48038 | 97008-48038 | \$ 4,165.00 | 10% | <i>\$3,776.61</i> |
| EW 4HR ONSITE 48039 | 97008-48039 | \$ 4,165.00 | 10% | <i>\$3,776.61</i> |
| EW 4hr On-site-48040 | 97008-48040 | \$ 3,945.00 | 10% | <i>\$3,577.13</i> |
| EW 4HR ONSITE BD X 48041 | 97008-48041 | \$ 4,165.00 | 10% | <i>\$3,776.61</i> |
| EW 4HR ONSITE BD X 48046 | 97008-48046 | \$ 5,463.00 | 10% | <i>\$4,953.58</i> |
| EW 4HR ONSITE 48047 | 97008-48047 | \$ 14,566.00 | 10% | <i>\$13,207.72</i> |
| EW 4HR ONSITE BD X 48051 | 97008-48051 | \$ 10,010.00 | 10% | <i>\$9,076.57</i> |
| EW 4HR ONSITE 48061 | 97008-48061 | \$ 11,707.00 | 10% | <i>\$10,615.32</i> |
| EW 4HR ONSITE 48062 | 97008-48062 | \$ 18,722.00 | 10% | <i>\$16,976.17</i> |
| EW 4HR ONSITE 5320-16P-4XE | 97008-5320-16P-4XE | \$ 416.00 | 10% | <i>\$377.21</i> |

| | | | | |
|-----------------------------------|---------------------------|-------------|-----|------------|
| EW 4HR ONSITE 5320-16P-4XE-DC | 97008-5320-16P-4XE-DC | \$ 500.00 | 10% | \$453.38 |
| EW 4HR ONSITE 5320-24P-8XE | 97008-5320-24P-8XE | \$ 459.00 | 10% | \$416.20 |
| EW 4HR ONSITE 5320-24T-24S-4XE-XT | 97008-5320-24T-24S-4XE-XT | \$ 708.00 | 10% | \$641.98 |
| EW 4HR ONSITE 5320-24T-4X-XT | 97008-5320-24T-4X-XT | \$ 381.00 | 10% | \$345.47 |
| EW 4HR ONSITE 5320-24T-8XE | 97008-5320-24T-8XE | \$ 325.00 | 10% | \$294.69 |
| EW 4HR ONSITE 5320-48P-8XE | 97008-5320-48P-8XE | \$ 769.00 | 10% | \$697.29 |
| EW 4HR ONSITE 5320-48T-8XE | 97008-5320-48T-8XE | \$ 519.00 | 10% | \$470.60 |
| EW 4HR ONSITE 5420F-16MW-32P-4XE | 97008-5420F-16MW-32P-4XE | \$ 1,355.00 | 10% | \$1,228.65 |
| EW 4HR ONSITE 5420F-16W-32P-4XE | 97008-5420F-16W-32P-4XE | \$ 1,318.00 | 10% | \$1,195.10 |
| EW 4HR ONSITE 5420F-24P-4XE | 97008-5420F-24P-4XE | \$ 589.00 | 10% | \$534.08 |
| EW 4HR ONSITE 5420F-24S-4XE | 97008-5420F-24S-4XE | \$ 645.00 | 10% | \$584.85 |
| EW 4HR ONSITE 5420F-24T-4XE | 97008-5420F-24T-4XE | \$ 486.00 | 10% | \$440.68 |
| EW 4HR ONSITE 5420F-48P-4XE | 97008-5420F-48P-4XE | \$ 919.00 | 10% | \$833.30 |
| EW 4HR ONSITE 5420F-48P-4XL | 97008-5420F-48P-4XL | \$ 1,036.00 | 10% | \$939.39 |
| EW 4HR ONSITE 5420F-48T-4XE | 97008-5420F-48T-4XE | \$ 658.00 | 10% | \$596.64 |
| EW 4HR ONSITE 5420F-8W-16P-4XE | 97008-5420F-8W-16P-4XE | \$ 672.00 | 10% | \$609.34 |
| EW 4HR ONSITE 5420M-16MW-32P-4YE | 97008-5420M-16MW-32P-4YE | \$ 1,494.00 | 10% | \$1,354.68 |
| EW 4HR ONSITE 5420M-24T-4YE | 97008-5420M-24T-4YE | \$ 649.00 | 10% | \$588.48 |
| EW 4HR ONSITE 5420M-24W-4YE | 97008-5420M-24W-4YE | \$ 607.00 | 10% | \$550.40 |

| | | | | |
|-----------------------------------|---------------------------|-------------|-----|-------------------|
| EW 4HR ONSITE 5420M-48T-4YE | 97008-5420M-48T-4YE | \$ 888.00 | 10% | <i>\$805.19</i> |
| EW 4HR ONSITE 5420M-48W-4YE | 97008-5420M-48W-4YE | \$ 1,051.00 | 10% | <i>\$952.99</i> |
| EW 4HR ONSITE 5520-12MW-36W | 97008-5520-12MW-36W | \$ 1,611.00 | 10% | <i>\$1,460.77</i> |
| EW 4HR ONSITE 5520-24T | 97008-5520-24T | \$ 581.00 | 10% | <i>\$526.82</i> |
| EW 4HR ONSITE 5520-24T-ACDC-BASE | 97008-5520-24T-ACDC-BASE | \$ 581.00 | 10% | <i>\$526.82</i> |
| EW 4HR ONSITE 5520-24T-BASE | 97008-5520-24T-BASE | \$ 581.00 | 10% | <i>\$526.82</i> |
| EW 4HR ONSITE 5520-24W | 97008-5520-24W | \$ 885.00 | 10% | <i>\$802.47</i> |
| EW 4HR ONSITE 5520-24X | 97008-5520-24X | \$ 1,671.00 | 10% | <i>\$1,515.18</i> |
| EW 4HR ONSITE 5520-24X-ACDC-BASE | 97008-5520-24X-ACDC-BASE | \$ 1,671.00 | 10% | <i>\$1,515.18</i> |
| EW 4HR ONSITE 5520-24X-BASE | 97008-5520-24X-BASE | \$ 1,671.00 | 10% | <i>\$1,515.18</i> |
| EW 4HR ONSITE 5520-48SE | 97008-5520-48SE | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW 4HR ONSITE 5520-48SE-ACDC-BASE | 97008-5520-48SE-ACDC-BASE | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW 4HR ONSITE 5520-48SE-BASE | 97008-5520-48SE-BASE | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW 4HR ONSITE 5520-48T | 97008-5520-48T | \$ 996.00 | 10% | <i>\$903.12</i> |
| EW 4HR ONSITE 5520-48T-ACDC-BASE | 97008-5520-48T-ACDC-BASE | \$ 996.00 | 10% | <i>\$903.12</i> |
| EW 4HR ONSITE 5520-48T-BASE | 97008-5520-48T-BASE | \$ 996.00 | 10% | <i>\$903.12</i> |
| EW 4HR ONSITE 5520-48W | 97008-5520-48W | \$ 1,295.00 | 10% | <i>\$1,174.24</i> |
| EW 4HR ONSITE 5720-24MW | 97008-5720-24MW | \$ 2,039.00 | 10% | <i>\$1,848.86</i> |
| EW 4HR ONSITE 5720-24MXW | 97008-5720-24MXW | \$ 2,759.00 | 10% | <i>\$2,501.72</i> |

| | | | | |
|----------------------------------|--------------------------|-------------|-----|------------|
| EW 4HR ONSITE 5720-48MW | 97008-5720-48MW | \$ 2,399.00 | 10% | \$2,175.29 |
| EW 4HR ONSITE 5720-48MXW | 97008-5720-48MXW | \$ 3,479.00 | 10% | \$3,154.58 |
| EW 4HR ONSITE 7520-48XT-6C | 97008-7520-48XT-6C | \$ 4,021.00 | 10% | \$3,646.04 |
| EW 4HR ONSITE 7520-48XT-6C-AC-F | 97008-7520-48XT-6C-AC-F | \$ 4,021.00 | 10% | \$3,646.04 |
| EW 4HR ONSITE 7520-48XT-6C-AC-R | 97008-7520-48XT-6C-AC-R | \$ 4,021.00 | 10% | \$3,646.04 |
| EW 4HR ONSITE 7520-48Y-8C | 97008-7520-48Y-8C | \$ 3,758.00 | 10% | \$3,407.57 |
| EW 4HR ONSITE 7520-48Y-8C-AC-F | 97008-7520-48Y-8C-AC-F | \$ 3,758.00 | 10% | \$3,407.57 |
| EW 4HR ONSITE 7520-48Y-8C-AC-R | 97008-7520-48Y-8C-AC-R | \$ 3,758.00 | 10% | \$3,407.57 |
| EW 4HR ONSITE 7520-48YE-8CE | 97008-7520-48YE-8CE | \$ 4,354.00 | 10% | \$3,947.99 |
| EW 4HR ONSITE 7520-48YE-8CE-AC-F | 97008-7520-48YE-8CE-AC-F | \$ 4,354.00 | 10% | \$3,947.99 |
| EW 4HR ONSITE 7520-48YE-8CE-AC-R | 97008-7520-48YE-8CE-AC-R | \$ 4,354.00 | 10% | \$3,947.99 |
| EW 4HR ONSITE 7720-32C | 97008-7720-32C | \$ 4,638.00 | 10% | \$4,205.51 |
| EW 4HR ONSITE 7720-32C-AC-F | 97008-7720-32C-AC-F | \$ 4,638.00 | 10% | \$4,205.51 |
| EW 4HR ONSITE 7720-32C-AC-R | 97008-7720-32C-AC-R | \$ 4,638.00 | 10% | \$4,205.51 |
| EW 4HR ONSITE 8520-48XT-6C | 97008-8520-48XT-6C | \$ 3,186.00 | 10% | \$2,888.91 |
| EW 4HR ONSITE 8520-48XT-6C-AC-F | 97008-8520-48XT-6C-AC-F | \$ 3,186.00 | 10% | \$2,888.91 |
| EW 4HR ONSITE 8520-48XT-6C-AC-R | 97008-8520-48XT-6C-AC-R | \$ 3,186.00 | 10% | \$2,888.91 |
| EW 4HR ONSITE 8520-48XT-6C-DC-F | 97008-8520-48XT-6C-DC-F | \$ 3,186.00 | 10% | \$2,888.91 |

| | | | | |
|---------------------------------|-------------------------|--------------|-----|-------------|
| EW 4HR ONSITE 8520-48XT-6C-DC-R | 97008-8520-48XT-6C-DC-R | \$ 3,186.00 | 10% | \$2,888.91 |
| EW 4HR ONSITE 8520-48Y-8C | 97008-8520-48Y-8C | \$ 3,779.00 | 10% | \$3,426.61 |
| EW 4HR ONSITE 8520-48Y-8C-AC-F | 97008-8520-48Y-8C-AC-F | \$ 3,779.00 | 10% | \$3,426.61 |
| EW 4HR ONSITE 8520-48Y-8C-AC-R | 97008-8520-48Y-8C-AC-R | \$ 3,779.00 | 10% | \$3,426.61 |
| EW 4HR ONSITE 8520-48Y-8C-DC-F | 97008-8520-48Y-8C-DC-F | \$ 3,779.00 | 10% | \$3,426.61 |
| EW 4HR ONSITE 8520-48Y-8C-DC-R | 97008-8520-48Y-8C-DC-R | \$ 3,779.00 | 10% | \$3,426.61 |
| EW 4HR ONSITE 86100 | 97008-86100 | \$ 5,832.00 | 10% | \$5,288.17 |
| EW 4HR ONSITE 86101 | 97008-86101 | \$ 8,016.00 | 10% | \$7,268.51 |
| EW 4HR ONSITE 87100 | 97008-87100 | \$ 3,624.00 | 10% | \$3,286.06 |
| EW 4HR ONSITE 87101 | 97008-87101 | \$ 5,566.00 | 10% | \$5,046.97 |
| EW 4HR ONSITE 8720-32C | 97008-8720-32C | \$ 4,348.00 | 10% | \$3,942.55 |
| EW 4HR ONSITE 8720-32C-AC-F | 97008-8720-32C-AC-F | \$ 4,348.00 | 10% | \$3,942.55 |
| EW 4HR ONSITE 8720-32C-AC-R | 97008-8720-32C-AC-R | \$ 4,348.00 | 10% | \$3,942.55 |
| EW 4HR ONSITE 8720-32C-DC-F | 97008-8720-32C-DC-F | \$ 4,348.00 | 10% | \$3,942.55 |
| EW 4HR ONSITE 8720-32C-DC-R | 97008-8720-32C-DC-R | \$ 4,348.00 | 10% | \$3,942.55 |
| EW 4HR ONSITE 8806 | 97008-8806 | \$ 2,605.00 | 10% | \$2,362.08 |
| EW 4HR ONSITE ASPEN | 97008-8810 | \$ 6,899.00 | 10% | \$6,255.67 |
| EW 4HR ONSITE 88100 | 97008-88100 | \$ 6,582.00 | 10% | \$5,968.23 |
| EW 4HR ONSITE 8820-40C | 97008-8820-40C | \$ 13,922.00 | 10% | \$12,623.77 |
| EW 4HR ONSITE 8820-40C-AC-F | 97008-8820-40C-AC-F | \$ 13,922.00 | 10% | \$12,623.77 |
| EW 4HR ONSITE 8820-40C-AC-R | 97008-8820-40C-AC-R | \$ 13,922.00 | 10% | \$12,623.77 |
| EW 4HR ONSITE 8820-40C-DC-F | 97008-8820-40C-DC-F | \$ 13,922.00 | 10% | \$12,623.77 |
| EW 4HR ONSITE 8820-40C-DC-R | 97008-8820-40C-DC-R | \$ 13,922.00 | 10% | \$12,623.77 |
| EW 4HR ONSITE 8820-80C | 97008-8820-80C | \$ 25,433.00 | 10% | \$23,061.37 |

| | | | | |
|---------------------------------|-------------------------|--------------|-----|--------------------|
| EW 4HR ONSITE 8820-80C-AC-F | 97008-8820-80C-AC-F | \$ 25,433.00 | 10% | <i>\$23,061.37</i> |
| EW 4HR ONSITE 8820-80C-AC-R | 97008-8820-80C-AC-R | \$ 25,433.00 | 10% | <i>\$23,061.37</i> |
| EW 4HR ONSITE 8820-80C-DC-F | 97008-8820-80C-DC-F | \$ 25,433.00 | 10% | <i>\$23,061.37</i> |
| EW 4HR ONSITE 8820-80C-DC-R | 97008-8820-80C-DC-R | \$ 25,433.00 | 10% | <i>\$23,061.37</i> |
| EW 4HR ONSITE 9920-16C | 97008-9920-16C | \$ 12,231.00 | 10% | <i>\$11,090.46</i> |
| EW 4HR ONSITE 9920-4D | 97008-9920-4D | \$ 12,231.00 | 10% | <i>\$11,090.46</i> |
| EW 4HR ONSITE 9920-NPB-8 | 97008-9920-NPB-8 | \$ 18,287.00 | 10% | <i>\$16,581.74</i> |
| EW 4hr On-Site | 97008-A10148 | \$ 3,278.00 | 10% | <i>\$2,972.33</i> |
| EW 4hr On-Site | 97008-A10149 | \$ 6,239.00 | 10% | <i>\$5,657.21</i> |
| EW 4hr On-Site | 97008-A10152 | \$ 6,239.00 | 10% | <i>\$5,657.21</i> |
| EW 4hr On-Site | 97008-A10154 | \$ 19,050.00 | 10% | <i>\$17,273.59</i> |
| EW 4hr On-Site | 97008-A10155 | \$ 6,740.00 | 10% | <i>\$6,111.50</i> |
| EW 4hr On-Site | 97008-A10157 | \$ 11,898.00 | 10% | <i>\$10,788.51</i> |
| EW 4HR ONSITE 10175 | 97008-A10175 | \$ 9,554.00 | 10% | <i>\$8,663.09</i> |
| EW 4HR ONSITE A10176 | 97008-A10176 | \$ 14,333.00 | 10% | <i>\$12,996.45</i> |
| EW 4HR ONSITE AH-AP-1130-AC-CE | 97008-AH-AP-1130-AC-CE | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE AH-AP-1130-AC-FCC | 97008-AH-AP-1130-AC-FCC | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE AH-AP-1130-AC-W | 97008-AH-AP-1130-AC-W | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE AH-AP-122-AC-CAN | 97008-AH-AP-122-AC-CAN | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-122-AC-CE | 97008-AH-AP-122-AC-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-122-AC-FCC | 97008-AH-AP-122-AC-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-122-AC-W | 97008-AH-AP-122-AC-W | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-130-AC-CE | 97008-AH-AP-130-AC-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-130-AC-FCC | 97008-AH-AP-130-AC-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-130-AC-W | 97008-AH-AP-130-AC-W | \$ 105.00 | 10% | <i>\$95.21</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AH-AP-150W-AC-CAN | 97008-AH-AP-150W-AC-CAN | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-150W-AC-CE | 97008-AH-AP-150W-AC-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-150W-AC-FCC | 97008-AH-AP-150W-AC-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-150W-AC-W | 97008-AH-AP-150W-AC-W | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-230-AC-CE | 97008-AH-AP-230-AC-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-230-AC-FCC | 97008-AH-AP-230-AC-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-230-AC-W | 97008-AH-AP-230-AC-W | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-250-AC-CAN | 97008-AH-AP-250-AC-CAN | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-250-AC-CE | 97008-AH-AP-250-AC-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-250-AC-FCC | 97008-AH-AP-250-AC-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-250-AC-W | 97008-AH-AP-250-AC-W | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-AP-630-AX-CAN | 97008-AH-AP-630-AX-CAN | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW 4HR ONSITE AH-AP-630-AX-CE | 97008-AH-AP-630-AX-CE | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW 4HR ONSITE AH-AP-630-AX-FCC | 97008-AH-AP-630-AX-FCC | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW 4HR ONSITE AH-AP-630-AX-W | 97008-AH-AP-630-AX-W | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW 4HR ONSITE AH-AP-650-AX-CAN | 97008-AH-AP-650-AX-CAN | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW 4HR ONSITE AH-AP-650-AX-CE | 97008-AH-AP-650-AX-CE | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW 4HR ONSITE AH-AP-650-AX-FCC | 97008-AH-AP-650-AX-FCC | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW 4HR ONSITE AH-AP-650-AX-W | 97008-AH-AP-650-AX-W | \$ 158.00 | 10% | <i>\$143.27</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AH-AP-650X-AX-CAN | 97008-AH-AP-650X-AX-CAN | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW 4HR ONSITE AH-AP-650X-AX-CE | 97008-AH-AP-650X-AX-CE | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW 4HR ONSITE AH-AP-650X-AX-FCC | 97008-AH-AP-650X-AX-FCC | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW 4HR ONSITE AH-AP-650X-AX-W | 97008-AH-AP-650X-AX-W | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW 4HR ONSITE AH-ATOM-CAN | 97008-AH-ATOM-CAN | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW 4HR ONSITE AH-ATOM-CE-EU | 97008-AH-ATOM-CE-EU | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW 4HR ONSITE AH-ATOM-CE-UK | 97008-AH-ATOM-CE-UK | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW 4HR ONSITE AH-ATOM-FCC | 97008-AH-ATOM-FCC | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW 4HR ONSITE AH-ATOM-W | 97008-AH-ATOM-W | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW 4HR ONSITE AH-ATOM-W-EU | 97008-AH-ATOM-W-EU | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW 4HR ONSITE AH-ATOM-W-UK | 97008-AH-ATOM-W-UK | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW 4HR ONSITE AH-SR-2208P-AU | 97008-AH-SR-2208P-AU | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-SR-2208P-EU | 97008-AH-SR-2208P-EU | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-SR-2208P-NA | 97008-AH-SR-2208P-NA | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-SR-2208P-UK | 97008-AH-SR-2208P-UK | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-SR-2224P-AU | 97008-AH-SR-2224P-AU | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AH-SR-2224P-EU | 97008-AH-SR-2224P-EU | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AH-SR-2224P-NA | 97008-AH-SR-2224P-NA | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AH-SR-2224P-UK | 97008-AH-SR-2224P-UK | \$ 156.00 | 10% | <i>\$141.45</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AH-SR-2324P-AU | 97008-AH-SR-2324P-AU | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW 4HR ONSITE AH-SR-2324P-EU | 97008-AH-SR-2324P-EU | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW 4HR ONSITE AH-SR-2324P-NA | 97008-AH-SR-2324P-NA | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW 4HR ONSITE AH-SR-2324P-UK | 97008-AH-SR-2324P-UK | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW 4HR ONSITE AH-SR-2348P-AU | 97008-AH-SR-2348P-AU | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW 4HR ONSITE AH-SR-2348P-EU | 97008-AH-SR-2348P-EU | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW 4HR ONSITE AH-SR-2348P-NA | 97008-AH-SR-2348P-NA | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW 4HR ONSITE AH-SR-2348P-UK | 97008-AH-SR-2348P-UK | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW 4HR ONSITE AH-XR200P-AU | 97008-AH-XR200P-AU | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-XR200P-EU | 97008-AH-XR200P-EU | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-XR200P-UK | 97008-AH-XR200P-UK | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-XR200P-US | 97008-AH-XR200P-US | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AH-XR600P | 97008-AH-XR600P | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW 4HR ONSITE AH-XR600P-AU | 97008-AH-XR600P-AU | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR ONSITE AH-XR600P-EU | 97008-AH-XR600P-EU | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR ONSITE AH-XR600P-KR | 97008-AH-XR600P-KR | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR ONSITE AH-XR600P-UK | 97008-AH-XR600P-UK | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR ONSITE AH-XR600P-US | 97008-AH-XR600P-US | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW 4HR ONSITE AP-8533-68SB30-IL | 97008-AP-8533-68SB30-IL | \$ 196.00 | 10% | <i>\$177.72</i> |
| EW 4HR ONSITE AP3000-IL | 97008-AP3000-IL | \$ 90.00 | 10% | <i>\$81.61</i> |

| | | | | |
|----------------------------|--------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AP3000-TN | 97008-AP3000-TN | \$ 90.00 | 10% | <i>\$81.61</i> |
| EW 4HR ONSITE AP3000-WW | 97008-AP3000-WW | \$ 90.00 | 10% | <i>\$81.61</i> |
| EW 4HR ONSITE AP3000X-WW | 97008-AP3000X-WW | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW 4HR ONSITE AP302W-CAN | 97008-AP302W-CAN | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW 4HR ONSITE AP302W-EG | 97008-AP302W-EG | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW 4HR ONSITE AP302W-FCC | 97008-AP302W-FCC | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW 4HR ONSITE AP302W-WR | 97008-AP302W-WR | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR ONSITE AP305C-1-CAN | 97008-AP305C-1-CAN | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AP305C-1-EG | 97008-AP305C-1-EG | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AP305C-1-FCC | 97008-AP305C-1-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AP305C-1-IL | 97008-AP305C-1-IL | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AP305C-1-WR | 97008-AP305C-1-WR | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW 4HR ONSITE AP305C-CAN | 97008-AP305C-CAN | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP305C-EG | 97008-AP305C-EG | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP305C-FCC | 97008-AP305C-FCC | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP305C-IL | 97008-AP305C-IL | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP305C-WR | 97008-AP305C-WR | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP305CX-CAN | 97008-AP305CX-CAN | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP305CX-FCC | 97008-AP305CX-FCC | \$ 112.00 | 10% | <i>\$101.56</i> |

| | | | | |
|---------------------------|-----------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AP305CX-IL | 97008- AP305CX-IL | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP305CX-WR | 97008- AP305CX-WR | \$ 112.00 | 10% | <i>\$101.56</i> |
| EW 4HR ONSITE AP310e-1-WR | 97008-AP310e- 1-WR | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW 4HR ONSITE AP310e-CAN | 97008-AP310e- CAN | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP310e-FCC | 97008-AP310e- FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP310e-IL | 97008-AP310e- IL | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP310e-WR | 97008-AP310e- WR | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP310i-1-WR | 97008-AP310i- 1-WR | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW 4HR ONSITE AP310i-CAN | 97008-AP310i- CAN | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP310i-FCC | 97008-AP310i- FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP310i-IL | 97008-AP310i- IL | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP310i-WR | 97008-AP310i- WR | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW 4HR ONSITE AP360e-CAN | 97008-AP360e- CAN | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE AP360e-FCC | 97008-AP360e- FCC | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE AP360e-IL | 97008-AP360e- IL | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE AP360e-WR | 97008-AP360e- WR | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE AP360i-CAN | 97008-AP360i- CAN | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE AP360i-FCC | 97008-AP360i- FCC | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE AP360i-WR | 97008-AP360i- WR | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE AP4000-WW | 97008-AP4000- 1-WW | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR ONSITE AP4000-IL | 97008-AP4000- IL | \$ 125.00 | 10% | <i>\$113.34</i> |

| | | | | |
|----------------------------|--------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AP4000-WW | 97008-AP4000-WW | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR ONSITE AP410C-1-CAN | 97008-AP410C-1-CAN | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW 4HR ONSITE AP410C-1-EG | 97008-AP410C-1-EG | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW 4HR ONSITE AP410C-1-FCC | 97008-AP410C-1-FCC | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW 4HR ONSITE AP410C-1-IL | 97008-AP410C-1-IL | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW 4HR ONSITE AP410C-1-WR | 97008-AP410C-1-WR | \$ 118.00 | 10% | <i>\$107.00</i> |
| EW 4HR ONSITE AP410C-CAN | 97008-AP410C-CAN | \$ 127.00 | 10% | <i>\$115.16</i> |
| EW 4HR ONSITE AP410C-EG | 97008-AP410C-EG | \$ 127.00 | 10% | <i>\$115.16</i> |
| EW 4HR ONSITE AP410C-FCC | 97008-AP410C-FCC | \$ 127.00 | 10% | <i>\$115.16</i> |
| EW 4HR ONSITE AP410C-IL | 97008-AP410C-IL | \$ 127.00 | 10% | <i>\$115.16</i> |
| EW 4HR ONSITE AP410C-WR | 97008-AP410C-WR | \$ 127.00 | 10% | <i>\$115.16</i> |
| EW 4HR ONSITE AP410e-CAN | 97008-AP410e-CAN | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR ONSITE AP410e-FCC | 97008-AP410e-FCC | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR ONSITE AP410e-WR | 97008-AP410e-WR | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR ONSITE AP410i-1-FCC | 97008-AP410i-1-FCC | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW 4HR ONSITE AP410i-1-WR | 97008-AP410i-1-WR | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW 4HR ONSITE AP410i-CAN | 97008-AP410i-CAN | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR ONSITE AP410i-FCC | 97008-AP410i-FCC | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR ONSITE AP410i-IL | 97008-AP410i-IL | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR ONSITE AP410i-WR | 97008-AP410i-WR | \$ 122.00 | 10% | <i>\$110.62</i> |

| | | | | |
|-----------------------------|---------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AP460C-CAN | 97008-AP460C-CAN | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460C-EG | 97008-AP460C-EG | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460C-FCC | 97008-AP460C-FCC | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460C-IL | 97008-AP460C-IL | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460C-WR | 97008-AP460C-WR | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460e-CAN | 97008-AP460e-CAN | \$ 142.00 | 10% | <i>\$128.76</i> |
| EW 4HR ONSITE AP460e-FCC | 97008-AP460e-FCC | \$ 142.00 | 10% | <i>\$128.76</i> |
| EW 4HR ONSITE AP460e-WR | 97008-AP460e-WR | \$ 135.00 | 10% | <i>\$122.41</i> |
| EW 4HR ONSITE AP460i-CAN | 97008-AP460i-CAN | \$ 135.00 | 10% | <i>\$122.41</i> |
| EW 4HR ONSITE AP460i-FCC | 97008-AP460i-FCC | \$ 135.00 | 10% | <i>\$122.41</i> |
| EW 4HR ONSITE AP460i-IL | 97008-AP460i-IL | \$ 135.00 | 10% | <i>\$122.41</i> |
| EW 4HR ONSITE AP460i-WR | 97008-AP460i-WR | \$ 135.00 | 10% | <i>\$122.41</i> |
| EW 4HR ONSITE AP460S12C-CAN | 97008-AP460S12C-CAN | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460S12C-FCC | 97008-AP460S12C-FCC | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460S12C-WR | 97008-AP460S12C-WR | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460S6C-CAN | 97008-AP460S6C-CAN | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460S6C-FCC | 97008-AP460S6C-FCC | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW 4HR ONSITE AP460S6C-WR | 97008-AP460S6C-WR | \$ 156.00 | 10% | <i>\$141.45</i> |

| | | | | |
|------------------------------|----------------------|-----------|-----|-----------------|
| EW 4HR ONSITE AP5010-IL | 97008-AP5010-IL | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW 4HR ONSITE AP5010-WW | 97008-AP5010-WW | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW 4HR ONSITE AP5020-WW | 97008-AP5020-WW | \$ 239.90 | 6% | <i>\$227.20</i> |
| EW 4HR ONSITE AP5050D-WW | 97008-AP5050D-WW | \$ 450.00 | 10% | <i>\$408.04</i> |
| EW 4HR ONSITE AP5050U-WW | 97008-AP5050U-WW | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW 4HR ONSITE AP505i-FCC | 97008-AP505i-FCC | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW 4HR ONSITE AP505i-FCC-TAA | 97008-AP505i-FCC-TAA | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW 4HR ONSITE AP505i-WR | 97008-AP505i-WR | \$ 157.00 | 10% | <i>\$142.36</i> |
| EW 4HR ONSITE AP510C-CAN | 97008-AP510C-CAN | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510C-CE | 97008-AP510C-CE | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510C-FCC | 97008-AP510C-FCC | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510C-W | 97008-AP510C-W | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510C-WW | 97008-AP510C-WW | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW 4HR ONSITE AP510CX-CAN | 97008-AP510CX-CAN | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510CX-CE | 97008-AP510CX-CE | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510CX-FCC | 97008-AP510CX-FCC | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510CX-W | 97008-AP510CX-W | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW 4HR ONSITE AP510CX-WW | 97008-AP510CX-WW | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW 4HR ONSITE AP510e-FCC | 97008-AP510e-FCC | \$ 200.00 | 10% | <i>\$181.35</i> |

| | | | | |
|------------------------------|----------------------|--------------|-----|--------------------|
| EW 4HR ONSITE AP510e-FCC-TAA | 97008-AP510e-FCC-TAA | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW 4HR ONSITE AP510e-WR | 97008-AP510e-WR | \$ 191.00 | 10% | <i>\$173.19</i> |
| EW 4HR ONSITE AP510i-1-FCC | 97008-AP510i-1-FCC | \$ 168.00 | 10% | <i>\$152.33</i> |
| EW 4HR ONSITE AP510i-1-WR | 97008-AP510i-1-WR | \$ 168.00 | 10% | <i>\$152.33</i> |
| EW 4HR ONSITE AP510i-FCC | 97008-AP510i-FCC | \$ 176.00 | 10% | <i>\$159.59</i> |
| EW 4HR ONSITE AP510i-FCC-TAA | 97008-AP510i-FCC-TAA | \$ 176.00 | 10% | <i>\$159.59</i> |
| EW 4HR ONSITE AP510i-WR | 97008-AP510i-WR | \$ 176.00 | 10% | <i>\$159.59</i> |
| EW 4HR ONSITE AP560h-FCC | 97008-AP560h-FCC | \$ 439.00 | 10% | <i>\$398.06</i> |
| EW 4HR ONSITE AP560h-WR | 97008-AP560h-WR | \$ 439.00 | 10% | <i>\$398.06</i> |
| EW 4HR ONSITE AP560i-FCC | 97008-AP560i-FCC | \$ 319.00 | 10% | <i>\$289.25</i> |
| EW 4HR ONSITE AP560i-WR | 97008-AP560i-WR | \$ 304.00 | 10% | <i>\$275.65</i> |
| EW 4HR ONSITE AP560m-FCC | 97008-AP560m-FCC | \$ 319.00 | 10% | <i>\$289.25</i> |
| EW 4HR ONSITE AP560t-FCC | 97008-AP560t-FCC | \$ 439.00 | 10% | <i>\$398.06</i> |
| EW 4HR ONSITE AP560u-FCC | 97008-AP560u-FCC | \$ 297.00 | 10% | <i>\$269.30</i> |
| EW 4HR ONSITE E2122 | 97008-E2122 | \$ 7,383.00 | 10% | <i>\$6,694.54</i> |
| EW 4HR ONSITE E2122-1 | 97008-E2122-1 | \$ 6,997.00 | 10% | <i>\$6,344.53</i> |
| EW 4HR ONSITE E3120-1 | 97008-E3120-1 | \$ 11,446.00 | 10% | <i>\$10,378.66</i> |
| EW 4HR ONSITE E3125 | 97008-E3125 | \$ 12,356.00 | 10% | <i>\$11,203.80</i> |
| EW 4hr On-Site | 97008-H30078 | \$ 4,151.00 | 10% | <i>\$3,763.92</i> |
| EW 4hr On-Site | 97008-H30104 | \$ 3,844.00 | 10% | <i>\$3,485.55</i> |
| EW 4hr On-Site | 97008-H30105 | \$ 3,798.00 | 10% | <i>\$3,443.84</i> |
| EW 4hr On-Site | 97008-H30131 | \$ 2,171.00 | 10% | <i>\$1,968.55</i> |
| EW 4hr On-Site | 97008-H30132 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW 4hr On-Site | 97008-H30133 | \$ 5,599.00 | 10% | <i>\$5,076.89</i> |
| EW 4hr On-Site | 97008-H30134 | \$ 7,090.00 | 10% | <i>\$6,428.86</i> |
| EW 4hr On-Site | 97008-H30135 | \$ 5,707.00 | 10% | <i>\$5,174.82</i> |
| EW 4hr On-Site | 97008-H30136 | \$ 7,090.00 | 10% | <i>\$6,428.86</i> |
| EW 4hr On-Site | 97008-H30184 | \$ 91.00 | 10% | <i>\$82.51</i> |

| | | | | |
|----------------|--------------|-------------|-----|------------|
| EW 4hr On-Site | 97008-H30185 | \$ 502.00 | 10% | \$455.19 |
| EW 4hr On-Site | 97008-H30186 | \$ 254.00 | 10% | \$230.31 |
| EW 4hr On-Site | 97008-H30187 | \$ 100.00 | 10% | \$90.68 |
| EW 4hr On-Site | 97008-H30188 | \$ 254.00 | 10% | \$230.31 |
| EW 4hr On-Site | 97008-H30189 | \$ 254.00 | 10% | \$230.31 |
| EW 4hr On-Site | 97008-H30190 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30214 | \$ 271.00 | 10% | \$245.73 |
| EW 4hr On-Site | 97008-H30215 | \$ 271.00 | 10% | \$245.73 |
| EW 4hr On-Site | 97008-H30216 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30217 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30218 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30219 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30220 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30221 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30222 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30223 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30224 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30225 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30226 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30227 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30228 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30229 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30267 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30268 | \$ 536.00 | 10% | \$486.02 |
| EW 4hr On-Site | 97008-H30269 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30270 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30271 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30272 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30273 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4hr On-Site | 97008-H30274 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4hr On-Site | 97008-H30275 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30276 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30277 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4hr On-Site | 97008-H30278 | \$ 1,293.00 | 10% | \$1,172.43 |
| EW 4hr On-Site | 97008-H30279 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4hr On-Site | 97008-H30280 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4hr On-Site | 97008-H30281 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4hr On-Site | 97008-H30282 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW 4hr On-Site | 97008-H30283 | \$ 774.00 | 10% | \$701.82 |
| EW 4hr On-Site | 97008-H30284 | \$ 851.00 | 10% | \$771.64 |
| EW 4hr On-Site | 97008-H30293 | \$ 4,670.00 | 10% | \$4,234.52 |
| EW 4hr On-Site | 97008-H30296 | \$ 271.00 | 10% | \$245.73 |

| | | | | |
|----------------|--------------|--------------|-----|-------------|
| EW 4hr On-Site | 97008-H30297 | \$ 252.00 | 10% | \$228.50 |
| EW 4hr On-Site | 97008-H30298 | \$ 271.00 | 10% | \$245.73 |
| EW 4hr On-Site | 97008-H30299 | \$ 252.00 | 10% | \$228.50 |
| EW 4hr On-Site | 97008-H30381 | \$ 761.00 | 10% | \$690.04 |
| EW 4hr On-Site | 97008-H30384 | \$ 617.00 | 10% | \$559.46 |
| EW 4hr On-Site | 97008-H30391 | \$ 1,470.00 | 10% | \$1,332.92 |
| EW 4hr On-Site | 97008-H30392 | \$ 1,470.00 | 10% | \$1,332.92 |
| EW 4hr On-Site | 97008-H30393 | \$ 650.00 | 10% | \$589.39 |
| EW 4hr On-Site | 97008-H30394 | \$ 2,838.00 | 10% | \$2,573.36 |
| EW 4hr On-Site | 97008-H30395 | \$ 3,379.00 | 10% | \$3,063.91 |
| EW 4hr On-Site | 97008-H30396 | \$ 3,077.00 | 10% | \$2,790.07 |
| EW 4hr On-Site | 97008-H30397 | \$ 3,653.00 | 10% | \$3,312.36 |
| EW 4hr On-Site | 97008-H30398 | \$ 663.00 | 10% | \$601.18 |
| EW 4hr On-Site | 97008-H30400 | \$ 373.00 | 10% | \$338.22 |
| EW 4hr On-Site | 97008-H30401 | \$ 512.00 | 10% | \$464.26 |
| EW 4hr On-Site | 97008-H30402 | \$ 561.00 | 10% | \$508.69 |
| EW 4hr On-Site | 97008-H30403 | \$ 823.00 | 10% | \$746.26 |
| EW 4hr On-Site | 97008-H30434 | \$ 218.00 | 10% | \$197.67 |
| EW 4hr On-Site | 97008-H30480 | \$ 960.00 | 10% | \$870.48 |
| EW 4hr On-Site | 97008-H30495 | \$ 2,171.00 | 10% | \$1,968.55 |
| EW 4hr On-Site | 97008-H30496 | \$ 2,130.00 | 10% | \$1,931.38 |
| EW 4hr On-Site | 97008-H30497 | \$ 3,136.00 | 10% | \$2,843.57 |
| EW 4hr On-Site | 97008-H30498 | \$ 3,077.00 | 10% | \$2,790.07 |
| EW 4hr On-Site | 97008-H30499 | \$ 1,049.00 | 10% | \$951.18 |
| EW 4hr On-Site | 97008-H30501 | \$ 3,077.00 | 10% | \$2,790.07 |
| EW 4hr On-Site | 97008-H30502 | \$ 4,729.00 | 10% | \$4,288.02 |
| EW 4hr On-Site | 97008-H30503 | \$ 1,049.00 | 10% | \$951.18 |
| EW 4hr On-Site | 97008-H30505 | \$ 5,599.00 | 10% | \$5,076.89 |
| EW 4hr On-Site | 97008-H30506 | \$ 7,610.00 | 10% | \$6,900.37 |
| EW 4hr On-Site | 97008-H30509 | \$ 4,729.00 | 10% | \$4,288.02 |
| EW 4hr On-Site | 97008-H30510 | \$ 5,599.00 | 10% | \$5,076.89 |
| EW 4hr On-Site | 97008-H30511 | \$ 7,610.00 | 10% | \$6,900.37 |
| EW 4hr On-Site | 97008-H30512 | \$ 1,049.00 | 10% | \$951.18 |
| EW 4hr On-Site | 97008-H30513 | \$ 1,779.00 | 10% | \$1,613.11 |
| EW 4hr On-Site | 97008-H30525 | \$ 7,610.00 | 10% | \$6,900.37 |
| EW 4hr On-Site | 97008-H30526 | \$ 5,599.00 | 10% | \$5,076.89 |
| EW 4hr On-Site | 97008-H30528 | \$ 8,839.00 | 10% | \$8,014.76 |
| EW 4hr On-Site | 97008-H30531 | \$ 12,577.00 | 10% | \$11,404.19 |
| EW 4hr On-Site | 97008-H30532 | \$ 12,577.00 | 10% | \$11,404.19 |
| EW 4hr On-Site | 97008-H30534 | \$ 12,823.00 | 10% | \$11,627.26 |
| EW 4hr On-Site | 97008-H30535 | \$ 13,677.00 | 10% | \$12,401.62 |
| EW 4hr On-Site | 97008-H30536 | \$ 12,577.00 | 10% | \$11,404.19 |

| | | | | |
|-------------------------------|--------------|--------------|-----|--------------------|
| EW 4hr On-Site | 97008-H30537 | \$ 13,677.00 | 10% | <i>\$12,401.62</i> |
| EW 4hr On-Site | 97008-H30538 | \$ 7,610.00 | 10% | <i>\$6,900.37</i> |
| EW 4hr On-Site | 97008-H30539 | \$ 14,329.00 | 10% | <i>\$12,992.82</i> |
| EW 4hr On-Site | 97008-H30540 | \$ 15,117.00 | 10% | <i>\$13,707.34</i> |
| EW 4hr On-Site | 97008-H30543 | \$ 1,031.00 | 10% | <i>\$934.86</i> |
| EW 4hr On-Site | 97008-H30544 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW 4hr On-Site | 97008-H30548 | \$ 1,031.00 | 10% | <i>\$934.86</i> |
| EW 4hr On-Site | 97008-H30549 | \$ 1,744.00 | 10% | <i>\$1,581.37</i> |
| EW 4hr On-Site | 97008-H30550 | \$ 1,744.00 | 10% | <i>\$1,581.37</i> |
| EW 4hr On-Site | 97008-H30552 | \$ 1,031.00 | 10% | <i>\$934.86</i> |
| EW 4hr On-Site | 97008-H30553 | \$ 1,634.00 | 10% | <i>\$1,481.63</i> |
| EW 4hr On-Site | 97008-H30569 | \$ 5,599.00 | 10% | <i>\$5,076.89</i> |
| EW 4hr On-Site | 97008-H30570 | \$ 6,710.00 | 10% | <i>\$6,084.29</i> |
| EW 4hr On-Site | 97008-H30571 | \$ 6,710.00 | 10% | <i>\$6,084.29</i> |
| EW 4hr On-Site | 97008-H30573 | \$ 5,599.00 | 10% | <i>\$5,076.89</i> |
| EW 4hr On-Site | 97008-H30574 | \$ 6,198.00 | 10% | <i>\$5,620.04</i> |
| EW 4hr On-Site | 97008-H30575 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW 4hr On-Site | 97008-H30576 | \$ 5,599.00 | 10% | <i>\$5,076.89</i> |
| EW 4hr On-Site | 97008-H30577 | \$ 6,710.00 | 10% | <i>\$6,084.29</i> |
| EW 4hr On-Site | 97008-H30578 | \$ 6,710.00 | 10% | <i>\$6,084.29</i> |
| EW 4hr On-Site | 97008-H30587 | \$ 5,707.00 | 10% | <i>\$5,174.82</i> |
| EW 4hr On-Site | 97008-H30588 | \$ 3,950.00 | 10% | <i>\$3,581.66</i> |
| EW 4hr On-Site | 97008-H30589 | \$ 6,094.00 | 10% | <i>\$5,525.73</i> |
| EW 4hr On-Site | 97008-H30632 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4hr On-Site | 97008-H30633 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW 4hr On-Site | 97008-H30643 | \$ 9,626.00 | 10% | <i>\$8,728.38</i> |
| EW 4hr On-Site | 97008-H30706 | \$ 9,012.00 | 10% | <i>\$8,171.63</i> |
| EW 4hr On-Site | 97008-H30707 | \$ 5,599.00 | 10% | <i>\$5,076.89</i> |
| EW 4hr On-Site | 97008-H30724 | \$ 617.00 | 10% | <i>\$559.46</i> |
| EW 4hr On-Site | 97008-H30725 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW 4hr On-Site | 97008-H30726 | \$ 13,944.00 | 10% | <i>\$12,643.72</i> |
| EW 4hr On-Site | 97008-H30727 | \$ 14,829.00 | 10% | <i>\$13,446.20</i> |
| EW 4hr On-Site | 97008-H30730 | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW 4hr On-Site | 97008-H30731 | \$ 114.00 | 10% | <i>\$103.37</i> |
| EW 4HR ONSITE 30732 | 97008-H30732 | \$ 2,676.00 | 10% | <i>\$2,426.46</i> |
| EW 4HR ONSITE SKL8008-0810-F8 | 97008-H30733 | \$ 13,078.00 | 10% | <i>\$11,858.48</i> |
| EW 4HR ONSITE STL2006-0850 | 97008-H30734 | \$ 9,979.00 | 10% | <i>\$9,048.46</i> |
| EW 4HR ONSITE SGL2001-0850 | 97008-H30735 | \$ 11,635.00 | 10% | <i>\$10,550.04</i> |

| | | | | |
|----------------------------|--------------|--------------|-----|--------------------|
| EW 4HR ONSITE SOK2209-0204 | 97008-H30736 | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |
| EW 4HR ONSITE H30738 | 97008-H30738 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE -H30739 | 97008-H30739 | \$ 1,955.00 | 10% | <i>\$1,772.70</i> |
| EW 4HR ONSITE -H30740 | 97008-H30740 | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW 4HR ONSITE -H30741 | 97008-H30741 | \$ 2,066.00 | 10% | <i>\$1,873.35</i> |
| EW 4HR ONSITE -H30742 | 97008-H30742 | \$ 1,836.00 | 10% | <i>\$1,664.79</i> |
| EW 4HR ONSITE -H30743 | 97008-H30743 | \$ 1,955.00 | 10% | <i>\$1,772.70</i> |
| EW 4HR ONSITE -H30744 | 97008-H30744 | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW 4HR ONSITE -H30745 | 97008-H30745 | \$ 1,155.00 | 10% | <i>\$1,047.30</i> |
| EW 4HR ONSITE -H30746 | 97008-H30746 | \$ 2,027.00 | 10% | <i>\$1,837.98</i> |
| EW 4HR ONSITE -H30747 | 97008-H30747 | \$ 4,060.00 | 10% | <i>\$3,681.41</i> |
| EW 4HR ONSITE -H30748 | 97008-H30748 | \$ 5,994.00 | 10% | <i>\$5,435.06</i> |
| EW 4HR ONSITE -H30749 | 97008-H30749 | \$ 13,463.00 | 10% | <i>\$12,207.58</i> |
| EW 4HR ONSITE -H30750 | 97008-H30750 | \$ 13,463.00 | 10% | <i>\$12,207.58</i> |
| EW 4HR ONSITE -H30751 | 97008-H30751 | \$ 7,991.00 | 10% | <i>\$7,245.84</i> |
| EW 4HR ONSITE -H30754 | 97008-H30754 | \$ 13,463.00 | 10% | <i>\$12,207.58</i> |
| EW 4HR ONSITE -H30755 | 97008-H30755 | \$ 14,637.00 | 10% | <i>\$13,272.10</i> |
| EW 4HR ONSITE -H30756 | 97008-H30756 | \$ 13,463.00 | 10% | <i>\$12,207.58</i> |
| EW 4HR ONSITE -H30757 | 97008-H30757 | \$ 5,994.00 | 10% | <i>\$5,435.06</i> |
| EW 4HR ONSITE -H30758 | 97008-H30758 | \$ 10,677.00 | 10% | <i>\$9,681.37</i> |
| EW 4HR ONSITE -H30759 | 97008-H30759 | \$ 12,213.00 | 10% | <i>\$11,074.14</i> |
| EW 4HR ONSITE -H30760 | 97008-H30760 | \$ 13,733.00 | 10% | <i>\$12,452.40</i> |
| EW 4HR ONSITE -H30761 | 97008-H30761 | \$ 5,994.00 | 10% | <i>\$5,435.06</i> |
| EW 4HR ONSITE -H30762 | 97008-H30762 | \$ 14,637.00 | 10% | <i>\$13,272.10</i> |
| EW 4HR ONSITE -H30763 | 97008-H30763 | \$ 14,637.00 | 10% | <i>\$13,272.10</i> |
| EW 4HR ONSITE -H30764 | 97008-H30764 | \$ 9,282.00 | 10% | <i>\$8,416.45</i> |
| EW 4HR ONSITE -H30765 | 97008-H30765 | \$ 8,147.00 | 10% | <i>\$7,387.29</i> |
| EW 4HR ONSITE -H30766 | 97008-H30766 | \$ 15,877.00 | 10% | <i>\$14,396.47</i> |
| EW 4HR ONSITE -H30767 | 97008-H30767 | \$ 9,282.00 | 10% | <i>\$8,416.45</i> |
| EW 4HR ONSITE H30769 | 97008-H30769 | \$ 3,457.00 | 10% | <i>\$3,134.63</i> |
| EW 4HR ONSITE H30773 | 97008-H30773 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW 4HR ONSITE H30774 | 97008-H30774 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW 4HR ONSITE H30775 | 97008-H30775 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW 4HR ONSITE H30776 | 97008-H30776 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW 4HR ONSITE H30777 | 97008-H30777 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW 4HR ONSITE H30778 | 97008-H30778 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW 4HR ONSITE H30779 | 97008-H30779 | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR ONSITE H30780 | 97008-H30780 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR ONSITE H30781 | 97008-H30781 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR ONSITE H30782 | 97008-H30782 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30783 | 97008-H30783 | \$ 110.00 | 10% | <i>\$99.74</i> |

| | | | | |
|----------------------|--------------|-----------|-----|-----------------|
| EW 4HR ONSITE H30784 | 97008-H30784 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW 4HR ONSITE H30785 | 97008-H30785 | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR ONSITE H30786 | 97008-H30786 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR ONSITE H30787 | 97008-H30787 | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR ONSITE H30788 | 97008-H30788 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW 4HR ONSITE H30789 | 97008-H30789 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW 4HR ONSITE H30790 | 97008-H30790 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30791 | 97008-H30791 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW 4HR ONSITE H30793 | 97008-H30793 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW 4HR ONSITE H30794 | 97008-H30794 | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW 4HR ONSITE H30795 | 97008-H30795 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR ONSITE H30796 | 97008-H30796 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE H30797 | 97008-H30797 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR ONSITE H30798 | 97008-H30798 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW 4HR ONSITE H30799 | 97008-H30799 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR ONSITE H30800 | 97008-H30800 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30801 | 97008-H30801 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE H30802 | 97008-H30802 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30803 | 97008-H30803 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE H30804 | 97008-H30804 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR ONSITE H30805 | 97008-H30805 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW 4HR ONSITE H30806 | 97008-H30806 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE H30807 | 97008-H30807 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR ONSITE H30808 | 97008-H30808 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE H30809 | 97008-H30809 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW 4HR ONSITE H30810 | 97008-H30810 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE H30811 | 97008-H30811 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE H30812 | 97008-H30812 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW 4HR ONSITE H30813 | 97008-H30813 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30814 | 97008-H30814 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE H30815 | 97008-H30815 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE H30816 | 97008-H30816 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE H30817 | 97008-H30817 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE H30818 | 97008-H30818 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW 4HR ONSITE H30819 | 97008-H30819 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW 4HR ONSITE H30820 | 97008-H30820 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW 4HR ONSITE H30821 | 97008-H30821 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30822 | 97008-H30822 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW 4HR ONSITE H30823 | 97008-H30823 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30824 | 97008-H30824 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW 4HR ONSITE H30825 | 97008-H30825 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H30826 | 97008-H30826 | \$ 152.00 | 10% | <i>\$137.83</i> |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE H30827 | 97008-H30827 | \$ 97.00 | 10% | \$87.95 |
| EW 4HR ONSITE H30828 | 97008-H30828 | \$ 97.00 | 10% | \$87.95 |
| EW 4HR ONSITE H30829 | 97008-H30829 | \$ 108.00 | 10% | \$97.93 |
| EW 4HR ONSITE H30830 | 97008-H30830 | \$ 152.00 | 10% | \$137.83 |
| EW 4HR ONSITE H30831 | 97008-H30831 | \$ 95.00 | 10% | \$86.14 |
| EW 4HR ONSITE H30832 | 97008-H30832 | \$ 1,987.00 | 10% | \$1,801.71 |
| EW 4HR ONSITE H30833 | 97008-H30833 | \$ 531.00 | 10% | \$481.48 |
| EW 4HR ONSITE H30834 | 97008-H30834 | \$ 531.00 | 10% | \$481.48 |
| EW 4HR ONSITE H30836 | 97008-H30836 | \$ 1,987.00 | 10% | \$1,801.71 |
| EW 4HR ONSITE H30838 | 97008-H30838 | \$ 70.00 | 10% | \$63.47 |
| EW 4HR ONSITE H30839 | 97008-H30839 | \$ 101.00 | 10% | \$91.58 |
| EW 4HR ONSITE H30840 | 97008-H30840 | \$ 101.00 | 10% | \$91.58 |
| EW 4HR ONSITE H30841 | 97008-H30841 | \$ 101.00 | 10% | \$91.58 |
| EW 4HR ONSITE H30842 | 97008-H30842 | \$ 101.00 | 10% | \$91.58 |
| EW 4HR ONSITE H30843 | 97008-H30843 | \$ 101.00 | 10% | \$91.58 |
| EW 4HR ONSITE H30844 | 97008-H30844 | \$ 101.00 | 10% | \$91.58 |
| EW 4HR ONSITE H30845 | 97008-H30845 | \$ 101.00 | 10% | \$91.58 |
| EW 4HR ONSITE H30846 | 97008-H30846 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30847 | 97008-H30847 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30848 | 97008-H30848 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30849 | 97008-H30849 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30850 | 97008-H30850 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30851 | 97008-H30851 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30852 | 97008-H30852 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30853 | 97008-H30853 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30854 | 97008-H30854 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30855 | 97008-H30855 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30856 | 97008-H30856 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30857 | 97008-H30857 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30858 | 97008-H30858 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30859 | 97008-H30859 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30860 | 97008-H30860 | \$ 194.00 | 10% | \$175.91 |
| EW 4HR ONSITE H30866 | 97008-H30866 | \$ 215.00 | 10% | \$194.95 |
| EW 4HR ONSITE H30867 | 97008-H30867 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30868 | 97008-H30868 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30869 | 97008-H30869 | \$ 373.00 | 10% | \$338.22 |
| EW 4HR ONSITE H30870 | 97008-H30870 | \$ 373.00 | 10% | \$338.22 |
| EW 4HR ONSITE H30871 | 97008-H30871 | \$ 343.00 | 10% | \$311.02 |
| EW 4HR ONSITE H30872 | 97008-H30872 | \$ 191.00 | 10% | \$173.19 |
| EW 4HR ONSITE H30873 | 97008-H30873 | \$ 191.00 | 10% | \$173.19 |
| EW 4HR ONSITE H30874 | 97008-H30874 | \$ 191.00 | 10% | \$173.19 |
| EW 4HR ONSITE H30875 | 97008-H30875 | \$ 66.00 | 10% | \$59.85 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE H30876 | 97008-H30876 | \$ 62.00 | 10% | \$56.22 |
| EW 4HR ONSITE H30877 | 97008-H30877 | \$ 66.00 | 10% | \$59.85 |
| EW 4HR ONSITE H30878 | 97008-H30878 | \$ 66.00 | 10% | \$59.85 |
| EW 4HR ONSITE H30891 | 97008-H30891 | \$ 138.00 | 10% | \$125.13 |
| EW 4HR ONSITE H30892 | 97008-H30892 | \$ 138.00 | 10% | \$125.13 |
| EW 4HR ONSITE H30893 | 97008-H30893 | \$ 116.00 | 10% | \$105.18 |
| EW 4HR ONSITE H30894 | 97008-H30894 | \$ 66.00 | 10% | \$59.85 |
| EW 4HR ONSITE H30895 | 97008-H30895 | \$ 234.00 | 10% | \$212.18 |
| EW 4HR ONSITE H30896 | 97008-H30896 | \$ 559.00 | 10% | \$506.87 |
| EW 4HR ONSITE H30897 | 97008-H30897 | \$ 983.00 | 10% | \$891.34 |
| EW 4HR ONSITE H30898 | 97008-H30898 | \$ 1,103.00 | 10% | \$1,000.15 |
| EW 4HR ONSITE H30900 | 97008-H30900 | \$ 3,332.00 | 10% | \$3,021.29 |
| EW 4HR ONSITE H30901 | 97008-H30901 | \$ 4,426.00 | 10% | \$4,013.28 |
| EW 4HR ONSITE H30902 | 97008-H30902 | \$ 4,647.00 | 10% | \$4,213.67 |
| EW 4HR ONSITE H30904 | 97008-H30904 | \$ 6,842.00 | 10% | \$6,203.98 |
| EW 4HR ONSITE H30905 | 97008-H30905 | \$ 9,777.00 | 10% | \$8,865.29 |
| EW 4HR ONSITE H30906 | 97008-H30906 | \$ 270.00 | 10% | \$244.82 |
| EW 4HR ONSITE H30912 | 97008-H30912 | \$ 735.00 | 10% | \$666.46 |
| EW 4HR ONSITE H30913 | 97008-H30913 | \$ 75.00 | 10% | \$68.01 |
| EW 4HR ONSITE H30914 | 97008-H30914 | \$ 66.00 | 10% | \$59.85 |
| EW 4HR ONSITE H30915 | 97008-H30915 | \$ 70.00 | 10% | \$63.47 |
| EW 4HR ONSITE H30916 | 97008-H30916 | \$ 70.00 | 10% | \$63.47 |
| EW 4HR ONSITE H30917 | 97008-H30917 | \$ 75.00 | 10% | \$68.01 |
| EW 4HR ONSITE H30918 | 97008-H30918 | \$ 75.00 | 10% | \$68.01 |
| EW 4HR ONSITE H30946 | 97008-H30946 | \$ 138.00 | 10% | \$125.13 |
| EW 4HR ONSITE H30948 | 97008-H30948 | \$ 138.00 | 10% | \$125.13 |
| EW 4HR ONSITE H30950 | 97008-H30950 | \$ 152.00 | 10% | \$137.83 |
| EW 4HR ONSITE H30951 | 97008-H30951 | \$ 138.00 | 10% | \$125.13 |
| EW 4HR ONSITE H30952 | 97008-H30952 | \$ 138.00 | 10% | \$125.13 |
| EW 4HR ONSITE H30966 | 97008-H30966 | \$ 234.00 | 10% | \$212.18 |
| EW 4HR ONSITE H30967 | 97008-H30967 | \$ 221.00 | 10% | \$200.39 |
| EW 4HR ONSITE H30968 | 97008-H30968 | \$ 234.00 | 10% | \$212.18 |
| EW 4HR ONSITE H30969 | 97008-H30969 | \$ 124.00 | 10% | \$112.44 |
| EW 4HR ONSITE H30970 | 97008-H30970 | \$ 174.00 | 10% | \$157.77 |
| EW 4HR ONSITE H30971 | 97008-H30971 | \$ 149.00 | 10% | \$135.11 |
| EW 4HR ONSITE H30972 | 97008-H30972 | \$ 174.00 | 10% | \$157.77 |
| EW 4HR ONSITE H30973 | 97008-H30973 | \$ 241.00 | 10% | \$218.53 |
| EW 4HR ONSITE H30974 | 97008-H30974 | \$ 210.00 | 10% | \$190.42 |
| EW 4HR ONSITE H30975 | 97008-H30975 | \$ 241.00 | 10% | \$218.53 |
| EW 4HR ONSITE H30976 | 97008-H30976 | \$ 241.00 | 10% | \$218.53 |
| EW 4HR ONSITE H30977 | 97008-H30977 | \$ 210.00 | 10% | \$190.42 |
| EW 4HR ONSITE H30978 | 97008-H30978 | \$ 241.00 | 10% | \$218.53 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE H30995 | 97008-H30995 | \$ 2,671.00 | 10% | \$2,421.93 |
| EW 4HR ONSITE H31030 | 97008-H31030 | \$ 8,633.00 | 10% | \$7,827.97 |
| EW 4HR ONSITE H31031 | 97008-H31031 | \$ 686.00 | 10% | \$622.03 |
| EW 4HR ONSITE H31033 | 97008-H31033 | \$ 5,234.00 | 10% | \$4,745.93 |
| EW 4HR ONSITE H31034 | 97008-H31034 | \$ 2,905.00 | 10% | \$2,634.11 |
| EW 4HR ONSITE H31035 | 97008-H31035 | \$ 3,046.00 | 10% | \$2,761.96 |
| EW 4HR ONSITE H31036 | 97008-H31036 | \$ 6,091.00 | 10% | \$5,523.01 |
| EW 4HR ONSITE H31040 | 97008-H31040 | \$ 224.00 | 10% | \$203.11 |
| EW 4HR ONSITE H31041 | 97008-H31041 | \$ 116.00 | 10% | \$105.18 |
| EW 4HR ONSITE H31042 | 97008-H31042 | \$ 341.00 | 10% | \$309.20 |
| EW 4HR ONSITE H31043 | 97008-H31043 | \$ 248.00 | 10% | \$224.87 |
| EW 4HR ONSITE H31047 | 97008-H31047 | \$ 227.00 | 10% | \$205.83 |
| EW 4HR ONSITE H31049 | 97008-H31049 | \$ 2,437.00 | 10% | \$2,209.75 |
| EW 4HR ONSITE H31060 | 97008-H31060 | \$ 61.00 | 10% | \$55.31 |
| EW 4HR ONSITE H31062 | 97008-H31062 | \$ 65.00 | 10% | \$58.94 |
| EW 4HR ONSITE H31066 | 97008-H31066 | \$ 89.00 | 10% | \$80.70 |
| EW 4HR ONSITE H31068 | 97008-H31068 | \$ 96.00 | 10% | \$87.05 |
| EW 4HR ONSITE H31076 | 97008-H31076 | \$ 330.00 | 10% | \$299.23 |
| EW 4HR ONSITE H31077 | 97008-H31077 | \$ 341.00 | 10% | \$309.20 |
| EW 4HR ONSITE H31078 | 97008-H31078 | \$ 345.00 | 10% | \$312.83 |
| EW 4HR ONSITE H31103 | 97008-H31103 | \$ 5,577.00 | 10% | \$5,056.94 |
| EW 4HR ONSITE H31119 | 97008-H31119 | \$ 125.00 | 10% | \$113.34 |
| EW 4HR ONSITE H31124 | 97008-H31124 | \$ 133.00 | 10% | \$120.60 |
| EW 4HR ONSITE H31127 | 97008-H31127 | \$ 221.00 | 10% | \$200.39 |
| EW 4HR ONSITE H31132 | 97008-H31132 | \$ 215.00 | 10% | \$194.95 |
| EW 4HR ONSITE H31134 | 97008-H31134 | \$ 66.00 | 10% | \$59.85 |
| EW 4HR ONSITE H31135 | 97008-H31135 | \$ 70.00 | 10% | \$63.47 |
| EW 4HR ONSITE H31136 | 97008-H31136 | \$ 113.00 | 10% | \$102.46 |
| EW 4HR ONSITE H31137 | 97008-H31137 | \$ 104.00 | 10% | \$94.30 |
| EW 4HR ONSITE H31197 | 97008-H31197 | \$ 123.00 | 10% | \$111.53 |
| EW 4HR ONSITE H31198 | 97008-H31198 | \$ 123.00 | 10% | \$111.53 |
| EW 4HR ONSITE H31199 | 97008-H31199 | \$ 123.00 | 10% | \$111.53 |
| EW 4HR ONSITE H31200 | 97008-H31200 | \$ 123.00 | 10% | \$111.53 |
| EW 4HR ONSITE H31201 | 97008-H31201 | \$ 123.00 | 10% | \$111.53 |
| EW 4HR ONSITE H31202 | 97008-H31202 | \$ 123.00 | 10% | \$111.53 |
| EW 4HR ONSITE H31203 | 97008-H31203 | \$ 146.00 | 10% | \$132.39 |
| EW 4HR ONSITE H31204 | 97008-H31204 | \$ 129.00 | 10% | \$116.97 |
| EW 4HR ONSITE H31205 | 97008-H31205 | \$ 146.00 | 10% | \$132.39 |
| EW 4HR ONSITE H31206 | 97008-H31206 | \$ 146.00 | 10% | \$132.39 |
| EW 4HR ONSITE H31207 | 97008-H31207 | \$ 129.00 | 10% | \$116.97 |
| EW 4HR ONSITE H31208 | 97008-H31208 | \$ 146.00 | 10% | \$132.39 |
| EW 4HR ONSITE H31210 | 97008-H31210 | \$ 270.00 | 10% | \$244.82 |

| | | | | |
|----------------------|--------------|--------------|-----|--------------------|
| EW 4HR ONSITE H31335 | 97008-H31335 | \$ 149.00 | 10% | <i>\$135.11</i> |
| EW 4HR ONSITE H31337 | 97008-H31337 | \$ 11,146.00 | 10% | <i>\$10,106.64</i> |
| EW 4HR ONSITE H31338 | 97008-H31338 | \$ 11,146.00 | 10% | <i>\$10,106.64</i> |
| EW 4HR ONSITE H31339 | 97008-H31339 | \$ 1,812.00 | 10% | <i>\$1,643.03</i> |
| EW 4HR ONSITE H31340 | 97008-H31340 | \$ 3,868.00 | 10% | <i>\$3,507.31</i> |
| EW 4HR ONSITE H31341 | 97008-H31341 | \$ 5,734.00 | 10% | <i>\$5,199.30</i> |
| EW 4HR ONSITE H31342 | 97008-H31342 | \$ 1,805.00 | 10% | <i>\$1,636.68</i> |
| EW 4HR ONSITE H31343 | 97008-H31343 | \$ 2,667.00 | 10% | <i>\$2,418.30</i> |
| EW 4HR ONSITE H31344 | 97008-H31344 | \$ 2,667.00 | 10% | <i>\$2,418.30</i> |
| EW 4HR ONSITE H31345 | 97008-H31345 | \$ 2,667.00 | 10% | <i>\$2,418.30</i> |
| EW 4HR ONSITE H31346 | 97008-H31346 | \$ 2,667.00 | 10% | <i>\$2,418.30</i> |
| EW 4HR ONSITE H31348 | 97008-H31348 | \$ 210.00 | 10% | <i>\$190.42</i> |
| EW 4HR ONSITE H31349 | 97008-H31349 | \$ 210.00 | 10% | <i>\$190.42</i> |
| EW 4HR ONSITE H31350 | 97008-H31350 | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW 4HR ONSITE H31351 | 97008-H31351 | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR ONSITE H31352 | 97008-H31352 | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR ONSITE H31353 | 97008-H31353 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H31354 | 97008-H31354 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW 4HR ONSITE H31355 | 97008-H31355 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW 4HR ONSITE H31356 | 97008-H31356 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW 4HR ONSITE H31357 | 97008-H31357 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW 4HR ONSITE H31358 | 97008-H31358 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW 4HR ONSITE H31359 | 97008-H31359 | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW 4HR ONSITE H31360 | 97008-H31360 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW 4HR ONSITE H31361 | 97008-H31361 | \$ 3,770.00 | 10% | <i>\$3,418.45</i> |
| EW 4HR ONSITE H31362 | 97008-H31362 | \$ 30,173.00 | 10% | <i>\$27,359.37</i> |
| EW 4HR ONSITE H31363 | 97008-H31363 | \$ 30,173.00 | 10% | <i>\$27,359.37</i> |
| EW 4HR ONSITE H31364 | 97008-H31364 | \$ 10,542.00 | 10% | <i>\$9,558.96</i> |
| EW 4HR ONSITE H31365 | 97008-H31365 | \$ 10,542.00 | 10% | <i>\$9,558.96</i> |
| EW 4HR ONSITE H31366 | 97008-H31366 | \$ 14,622.00 | 10% | <i>\$13,258.50</i> |
| EW 4HR ONSITE H31367 | 97008-H31367 | \$ 14,622.00 | 10% | <i>\$13,258.50</i> |
| EW 4HR ONSITE H31369 | 97008-H31369 | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR ONSITE H31370 | 97008-H31370 | \$ 129.00 | 10% | <i>\$116.97</i> |
| EW 4HR ONSITE H31393 | 97008-H31393 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW 4HR ONSITE H32010 | 97008-H32010 | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW 4HR ONSITE H32011 | 97008-H32011 | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW 4HR ONSITE H32012 | 97008-H32012 | \$ 3,624.00 | 10% | <i>\$3,286.06</i> |
| EW 4HR ONSITE H32013 | 97008-H32013 | \$ 3,624.00 | 10% | <i>\$3,286.06</i> |
| EW 4HR ONSITE H32014 | 97008-H32014 | \$ 3,624.00 | 10% | <i>\$3,286.06</i> |
| EW 4HR ONSITE H32015 | 97008-H32015 | \$ 3,624.00 | 10% | <i>\$3,286.06</i> |
| EW 4HR ONSITE H32016 | 97008-H32016 | \$ 3,155.00 | 10% | <i>\$2,860.80</i> |
| EW 4HR ONSITE H32017 | 97008-H32017 | \$ 3,155.00 | 10% | <i>\$2,860.80</i> |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW 4HR ONSITE H32018 | 97008-H32018 | \$ 3,155.00 | 10% | \$2,860.80 |
| EW 4HR ONSITE H32019 | 97008-H32019 | \$ 3,155.00 | 10% | \$2,860.80 |
| EW 4HR ONSITE H32020 | 97008-H32020 | \$ 31,644.00 | 10% | \$28,693.20 |
| EW 4HR ONSITE H32021 | 97008-H32021 | \$ 31,644.00 | 10% | \$28,693.20 |
| EW 4HR ONSITE H32022 | 97008-H32022 | \$ 31,644.00 | 10% | \$28,693.20 |
| EW 4HR ONSITE H32023 | 97008-H32023 | \$ 31,644.00 | 10% | \$28,693.20 |
| EW 4HR ONSITE H32028 | 97008-H32028 | \$ 61,021.00 | 10% | \$55,330.79 |
| EW 4HR ONSITE H32029 | 97008-H32029 | \$ 61,021.00 | 10% | \$55,330.79 |
| EW 4HR ONSITE H32030 | 97008-H32030 | \$ 63,994.00 | 10% | \$58,026.56 |
| EW 4HR ONSITE H32031 | 97008-H32031 | \$ 63,994.00 | 10% | \$58,026.56 |
| EW 4HR ONSITE H32032 | 97008-H32032 | \$ 63,994.00 | 10% | \$58,026.56 |
| EW 4HR ONSITE H32033 | 97008-H32033 | \$ 63,994.00 | 10% | \$58,026.56 |
| EW 4HR ONSITE H32038 | 97008-H32038 | \$ 11,058.00 | 10% | \$10,026.84 |
| EW 4HR ONSITE H32039 | 97008-H32039 | \$ 11,058.00 | 10% | \$10,026.84 |
| EW 4HR ONSITE H32040 | 97008-H32040 | \$ 11,058.00 | 10% | \$10,026.84 |
| EW 4HR ONSITE H32041 | 97008-H32041 | \$ 11,058.00 | 10% | \$10,026.84 |
| EW 4HR ONSITE H32046 | 97008-H32046 | \$ 15,334.00 | 10% | \$13,904.10 |
| EW 4HR ONSITE H32047 | 97008-H32047 | \$ 15,334.00 | 10% | \$13,904.10 |
| EW 4HR ONSITE H32048 | 97008-H32048 | \$ 15,334.00 | 10% | \$13,904.10 |
| EW 4HR ONSITE H32049 | 97008-H32049 | \$ 15,334.00 | 10% | \$13,904.10 |
| EW 4HR ONSITE H32054 | 97008-H32054 | \$ 11,058.00 | 10% | \$10,026.84 |
| EW 4HR ONSITE H32055 | 97008-H32055 | \$ 15,334.00 | 10% | \$13,904.10 |
| EW 4HR ONSITE H32056 | 97008-H32056 | \$ 4,298.00 | 10% | \$3,897.21 |
| EW 4HR ONSITE H32057 | 97008-H32057 | \$ 4,298.00 | 10% | \$3,897.21 |
| EW 4HR ONSITE H32058 | 97008-H32058 | \$ 4,298.00 | 10% | \$3,897.21 |
| EW 4HR ONSITE H32059 | 97008-H32059 | \$ 4,298.00 | 10% | \$3,897.21 |
| EW 4HR ONSITE H32060 | 97008-H32060 | \$ 5,356.00 | 10% | \$4,856.55 |
| EW 4HR ONSITE H32061 | 97008-H32061 | \$ 5,624.00 | 10% | \$5,099.56 |
| EW 4HR ONSITE H32062 | 97008-H32062 | \$ 5,408.00 | 10% | \$4,903.70 |
| EW 4HR ONSITE H32063 | 97008-H32063 | \$ 5,362.00 | 10% | \$4,861.99 |
| EW 4HR ONSITE H32064 | 97008-H32064 | \$ 5,408.00 | 10% | \$4,903.70 |
| EW 4HR ONSITE H32065 | 97008-H32065 | \$ 4,884.00 | 10% | \$4,428.57 |
| EW 4HR ONSITE H32066 | 97008-H32066 | \$ 4,884.00 | 10% | \$4,428.57 |
| EW 4HR ONSITE H32067 | 97008-H32067 | \$ 4,884.00 | 10% | \$4,428.57 |
| EW 4HR ONSITE H32068 | 97008-H32068 | \$ 4,884.00 | 10% | \$4,428.57 |
| EW 4HR ONSITE H32069 | 97008-H32069 | \$ 6,069.00 | 10% | \$5,503.07 |
| EW 4HR ONSITE H32070 | 97008-H32070 | \$ 6,069.00 | 10% | \$5,503.07 |
| EW 4HR ONSITE H32071 | 97008-H32071 | \$ 6,069.00 | 10% | \$5,503.07 |
| EW 4HR ONSITE H32072 | 97008-H32072 | \$ 6,069.00 | 10% | \$5,503.07 |
| EW 4HR ONSITE H32073 | 97008-H32073 | \$ 44,947.00 | 10% | \$40,755.69 |
| EW 4HR ONSITE H32074 | 97008-H32074 | \$ 44,947.00 | 10% | \$40,755.69 |
| EW 4HR ONSITE H32075 | 97008-H32075 | \$ 61,079.00 | 10% | \$55,383.38 |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW 4HR ONSITE H32076 | 97008-H32076 | \$ 61,079.00 | 10% | \$55,383.38 |
| EW 4HR ONSITE H32101 | 97008-H32101 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32102 | 97008-H32102 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32103 | 97008-H32103 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32104 | 97008-H32104 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32105 | 97008-H32105 | \$ 3,961.00 | 10% | \$3,591.64 |
| EW 4HR ONSITE H32106 | 97008-H32106 | \$ 3,961.00 | 10% | \$3,591.64 |
| EW 4HR ONSITE H32107 | 97008-H32107 | \$ 10,721.00 | 10% | \$9,721.27 |
| EW 4HR ONSITE H32108 | 97008-H32108 | \$ 10,721.00 | 10% | \$9,721.27 |
| EW 4HR ONSITE H32109 | 97008-H32109 | \$ 3,961.00 | 10% | \$3,591.64 |
| EW 4HR ONSITE H32110 | 97008-H32110 | \$ 3,961.00 | 10% | \$3,591.64 |
| EW 4HR ONSITE H32111 | 97008-H32111 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32112 | 97008-H32112 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32113 | 97008-H32113 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32114 | 97008-H32114 | \$ 1,981.00 | 10% | \$1,796.27 |
| EW 4HR ONSITE H32115 | 97008-H32115 | \$ 3,962.00 | 10% | \$3,592.54 |
| EW 4HR ONSITE H32116 | 97008-H32116 | \$ 3,962.00 | 10% | \$3,592.54 |
| EW 4HR ONSITE H32117 | 97008-H32117 | \$ 1,857.00 | 10% | \$1,683.83 |
| EW 4HR ONSITE H32118 | 97008-H32118 | \$ 1,857.00 | 10% | \$1,683.83 |
| EW 4HR ONSITE H32119 | 97008-H32119 | \$ 1,857.00 | 10% | \$1,683.83 |
| EW 4HR ONSITE H32120 | 97008-H32120 | \$ 1,857.00 | 10% | \$1,683.83 |
| EW 4HR ONSITE H32121 | 97008-H32121 | \$ 10,721.00 | 10% | \$9,721.27 |
| EW 4HR ONSITE H32122 | 97008-H32122 | \$ 10,721.00 | 10% | \$9,721.27 |
| EW 4HR ONSITE H32123 | 97008-H32123 | \$ 3,962.00 | 10% | \$3,592.54 |
| EW 4HR ONSITE H32124 | 97008-H32124 | \$ 3,962.00 | 10% | \$3,592.54 |
| EW 4HR ONSITE H32125 | 97008-H32125 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32126 | 97008-H32126 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32127 | 97008-H32127 | \$ 4,607.00 | 10% | \$4,177.40 |
| EW 4HR ONSITE H32128 | 97008-H32128 | \$ 4,607.00 | 10% | \$4,177.40 |
| EW 4HR ONSITE H32129 | 97008-H32129 | \$ 4,607.00 | 10% | \$4,177.40 |
| EW 4HR ONSITE H32130 | 97008-H32130 | \$ 4,607.00 | 10% | \$4,177.40 |
| EW 4HR ONSITE H32131 | 97008-H32131 | \$ 4,607.00 | 10% | \$4,177.40 |
| EW 4HR ONSITE H32132 | 97008-H32132 | \$ 4,607.00 | 10% | \$4,177.40 |
| EW 4HR ONSITE H32133 | 97008-H32133 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32134 | 97008-H32134 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32135 | 97008-H32135 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32136 | 97008-H32136 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32137 | 97008-H32137 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32138 | 97008-H32138 | \$ 3,914.00 | 10% | \$3,549.02 |
| EW 4HR ONSITE H32139 | 97008-H32139 | \$ 16,566.00 | 10% | \$15,021.22 |
| EW 4HR ONSITE H32140 | 97008-H32140 | \$ 16,566.00 | 10% | \$15,021.22 |
| EW 4HR ONSITE H32141 | 97008-H32141 | \$ 19,112.00 | 10% | \$17,329.81 |

| | | | | |
|----------------------|--------------|--------------|-----|--------------------|
| EW 4HR ONSITE H32142 | 97008-H32142 | \$ 19,112.00 | 10% | <i>\$17,329.81</i> |
| EW 4HR ONSITE H32146 | 97008-H32146 | \$ 1,689.00 | 10% | <i>\$1,531.50</i> |
| EW 4HR ONSITE H32147 | 97008-H32147 | \$ 1,689.00 | 10% | <i>\$1,531.50</i> |
| EW 4HR ONSITE H32148 | 97008-H32148 | \$ 3,480.00 | 10% | <i>\$3,155.49</i> |
| EW 4HR ONSITE H32149 | 97008-H32149 | \$ 3,480.00 | 10% | <i>\$3,155.49</i> |
| EW 4HR ONSITE H32150 | 97008-H32150 | \$ 1,786.00 | 10% | <i>\$1,619.46</i> |
| EW 4HR ONSITE H32169 | 97008-H32169 | \$ 2,004.00 | 10% | <i>\$1,817.13</i> |
| EW 4HR ONSITE H32170 | 97008-H32170 | \$ 2,004.00 | 10% | <i>\$1,817.13</i> |
| EW 4HR ONSITE H32171 | 97008-H32171 | \$ 1,879.00 | 10% | <i>\$1,703.78</i> |
| EW 4HR ONSITE H32172 | 97008-H32172 | \$ 1,879.00 | 10% | <i>\$1,703.78</i> |
| EW 4HR ONSITE H32173 | 97008-H32173 | \$ 5,013.00 | 10% | <i>\$4,545.54</i> |
| EW 4HR ONSITE H32174 | 97008-H32174 | \$ 5,013.00 | 10% | <i>\$4,545.54</i> |
| EW 4HR ONSITE H32175 | 97008-H32175 | \$ 4,257.00 | 10% | <i>\$3,860.03</i> |
| EW 4HR ONSITE H32176 | 97008-H32176 | \$ 4,257.00 | 10% | <i>\$3,860.03</i> |
| EW 4HR ONSITE H32177 | 97008-H32177 | \$ 19,533.00 | 10% | <i>\$17,711.55</i> |
| EW 4HR ONSITE H32178 | 97008-H32178 | \$ 22,534.00 | 10% | <i>\$20,432.70</i> |
| EW 4HR ONSITE H34008 | 97008-H34008 | \$ 74.00 | 10% | <i>\$67.10</i> |
| EW 4HR ONSITE H34009 | 97008-H34009 | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW 4HR ONSITE H34010 | 97008-H34010 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW 4HR ONSITE H34011 | 97008-H34011 | \$ 184.00 | 10% | <i>\$166.84</i> |
| EW 4HR ONSITE H34012 | 97008-H34012 | \$ 334.00 | 10% | <i>\$302.85</i> |
| EW 4HR ONSITE H34013 | 97008-H34013 | \$ 125.00 | 10% | <i>\$113.34</i> |
| EW 4HR ONSITE H34014 | 97008-H34014 | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW 4HR ONSITE H34015 | 97008-H34015 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW 4HR ONSITE H34016 | 97008-H34016 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW 4HR ONSITE H34017 | 97008-H34017 | \$ 397.00 | 10% | <i>\$359.98</i> |
| EW 4HR ONSITE H34018 | 97008-H34018 | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW 4HR ONSITE H34019 | 97008-H34019 | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW 4HR ONSITE H34020 | 97008-H34020 | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW 4HR ONSITE H34021 | 97008-H34021 | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW 4HR ONSITE H34048 | 97008-H34048 | \$ 655.00 | 10% | <i>\$593.92</i> |
| EW 4HR ONSITE H34049 | 97008-H34049 | \$ 655.00 | 10% | <i>\$593.92</i> |
| EW 4HR ONSITE H34050 | 97008-H34050 | \$ 485.00 | 10% | <i>\$439.77</i> |
| EW 4HR ONSITE H34051 | 97008-H34051 | \$ 485.00 | 10% | <i>\$439.77</i> |
| EW 4HR ONSITE H34052 | 97008-H34052 | \$ 773.00 | 10% | <i>\$700.92</i> |
| EW 4HR ONSITE H34053 | 97008-H34053 | \$ 773.00 | 10% | <i>\$700.92</i> |
| EW 4HR ONSITE H34054 | 97008-H34054 | \$ 575.00 | 10% | <i>\$521.38</i> |
| EW 4HR ONSITE H34055 | 97008-H34055 | \$ 575.00 | 10% | <i>\$521.38</i> |
| EW 4HR ONSITE H34056 | 97008-H34056 | \$ 843.00 | 10% | <i>\$764.39</i> |
| EW 4HR ONSITE H34057 | 97008-H34057 | \$ 843.00 | 10% | <i>\$764.39</i> |
| EW 4HR ONSITE H34058 | 97008-H34058 | \$ 715.00 | 10% | <i>\$648.33</i> |
| EW 4HR ONSITE H34059 | 97008-H34059 | \$ 715.00 | 10% | <i>\$648.33</i> |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW 4HR ONSITE H34062 | 97008-H34062 | \$ 843.00 | 10% | \$764.39 |
| EW 4HR ONSITE H34063 | 97008-H34063 | \$ 843.00 | 10% | \$764.39 |
| EW 4HR ONSITE H34064 | 97008-H34064 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE H34065 | 97008-H34065 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE H34066 | 97008-H34066 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE H34067 | 97008-H34067 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE H34068 | 97008-H34068 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE H34069 | 97008-H34069 | \$ 522.00 | 10% | \$473.32 |
| EW 4HR ONSITE H34070 | 97008-H34070 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE H34071 | 97008-H34071 | \$ 538.00 | 10% | \$487.83 |
| EW 4HR ONSITE H34072 | 97008-H34072 | \$ 4,628.00 | 10% | \$4,196.44 |
| EW 4HR ONSITE H34073 | 97008-H34073 | \$ 4,541.00 | 10% | \$4,117.55 |
| EW 4HR ONSITE H34074 | 97008-H34074 | \$ 5,783.00 | 10% | \$5,243.74 |
| EW 4HR ONSITE H34075 | 97008-H34075 | \$ 5,547.00 | 10% | \$5,029.74 |
| EW 4HR ONSITE H34076 | 97008-H34076 | \$ 4,628.00 | 10% | \$4,196.44 |
| EW 4HR ONSITE H34077 | 97008-H34077 | \$ 4,541.00 | 10% | \$4,117.55 |
| EW 4HR ONSITE H34078 | 97008-H34078 | \$ 4,628.00 | 10% | \$4,196.44 |
| EW 4HR ONSITE H34079 | 97008-H34079 | \$ 4,541.00 | 10% | \$4,117.55 |
| EW 4HR ONSITE H34080 | 97008-H34080 | \$ 5,783.00 | 10% | \$5,243.74 |
| EW 4HR ONSITE H34081 | 97008-H34081 | \$ 5,547.00 | 10% | \$5,029.74 |
| EW 4HR ONSITE H34082 | 97008-H34082 | \$ 5,547.00 | 10% | \$5,029.74 |
| EW 4HR ONSITE H34083 | 97008-H34083 | \$ 5,321.00 | 10% | \$4,824.82 |
| EW 4HR ONSITE H34084 | 97008-H34084 | \$ 3,719.00 | 10% | \$3,372.20 |
| EW 4HR ONSITE H34085 | 97008-H34085 | \$ 3,719.00 | 10% | \$3,372.20 |
| EW 4HR ONSITE H34086 | 97008-H34086 | \$ 4,331.00 | 10% | \$3,927.13 |
| EW 4HR ONSITE H34087 | 97008-H34087 | \$ 4,154.00 | 10% | \$3,766.64 |
| EW 4HR ONSITE H34088 | 97008-H34088 | \$ 9,952.00 | 10% | \$9,023.98 |
| EW 4HR ONSITE H34089 | 97008-H34089 | \$ 9,952.00 | 10% | \$9,023.98 |
| EW 4HR ONSITE H34090 | 97008-H34090 | \$ 11,460.00 | 10% | \$10,391.36 |
| EW 4HR ONSITE H34091 | 97008-H34091 | \$ 9,256.00 | 10% | \$8,392.88 |
| EW 4HR ONSITE H34092 | 97008-H34092 | \$ 9,256.00 | 10% | \$8,392.88 |
| EW 4HR ONSITE H34093 | 97008-H34093 | \$ 9,256.00 | 10% | \$8,392.88 |
| EW 4HR ONSITE H34094 | 97008-H34094 | \$ 1,069.00 | 10% | \$969.32 |
| EW 4HR ONSITE H34095 | 97008-H34095 | \$ 1,069.00 | 10% | \$969.32 |
| EW 4HR ONSITE H34096 | 97008-H34096 | \$ 1,207.00 | 10% | \$1,094.45 |
| EW 4HR ONSITE H34097 | 97008-H34097 | \$ 1,207.00 | 10% | \$1,094.45 |
| EW 4HR ONSITE H34098 | 97008-H34098 | \$ 1,069.00 | 10% | \$969.32 |
| EW 4HR ONSITE H34099 | 97008-H34099 | \$ 1,069.00 | 10% | \$969.32 |
| EW 4HR ONSITE H34100 | 97008-H34100 | \$ 1,069.00 | 10% | \$969.32 |
| EW 4HR ONSITE H34101 | 97008-H34101 | \$ 1,069.00 | 10% | \$969.32 |
| EW 4HR ONSITE H34102 | 97008-H34102 | \$ 1,069.00 | 10% | \$969.32 |
| EW 4HR ONSITE H34103 | 97008-H34103 | \$ 1,069.00 | 10% | \$969.32 |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW 4HR ONSITE H34104 | 97008-H34104 | \$ 463.00 | 10% | \$419.83 |
| EW 4HR ONSITE H34105 | 97008-H34105 | \$ 462.00 | 10% | \$418.92 |
| EW 4HR ONSITE H34106 | 97008-H34106 | \$ 463.00 | 10% | \$419.83 |
| EW 4HR ONSITE H34107 | 97008-H34107 | \$ 462.00 | 10% | \$418.92 |
| EW 4HR ONSITE H34108 | 97008-H34108 | \$ 463.00 | 10% | \$419.83 |
| EW 4HR ONSITE H34109 | 97008-H34109 | \$ 462.00 | 10% | \$418.92 |
| EW 4HR ONSITE H34110 | 97008-H34110 | \$ 8,915.00 | 10% | \$8,083.68 |
| EW 4HR ONSITE H34111 | 97008-H34111 | \$ 8,915.00 | 10% | \$8,083.68 |
| EW 4HR ONSITE H34112 | 97008-H34112 | \$ 8,915.00 | 10% | \$8,083.68 |
| EW 4HR ONSITE H34114 | 97008-H34114 | \$ 11,710.00 | 10% | \$10,618.04 |
| EW 4HR ONSITE H34115 | 97008-H34115 | \$ 11,710.00 | 10% | \$10,618.04 |
| EW 4HR ONSITE H34116 | 97008-H34116 | \$ 11,710.00 | 10% | \$10,618.04 |
| EW 4HR ONSITE H34117 | 97008-H34117 | \$ 11,710.00 | 10% | \$10,618.04 |
| EW 4HR ONSITE H34118 | 97008-H34118 | \$ 2,959.00 | 10% | \$2,683.07 |
| EW 4HR ONSITE H34119 | 97008-H34119 | \$ 2,959.00 | 10% | \$2,683.07 |
| EW 4HR ONSITE H34120 | 97008-H34120 | \$ 2,034.00 | 10% | \$1,844.33 |
| EW 4HR ONSITE H34121 | 97008-H34121 | \$ 2,034.00 | 10% | \$1,844.33 |
| EW 4HR ONSITE H34122 | 97008-H34122 | \$ 2,126.00 | 10% | \$1,927.75 |
| EW 4HR ONSITE H34123 | 97008-H34123 | \$ 2,126.00 | 10% | \$1,927.75 |
| EW 4HR ONSITE H34124 | 97008-H34124 | \$ 3,167.00 | 10% | \$2,871.68 |
| EW 4HR ONSITE H34125 | 97008-H34125 | \$ 3,167.00 | 10% | \$2,871.68 |
| EW 4HR ONSITE H34126 | 97008-H34126 | \$ 3,167.00 | 10% | \$2,871.68 |
| EW 4HR ONSITE H34127 | 97008-H34127 | \$ 3,167.00 | 10% | \$2,871.68 |
| EW 4HR ONSITE H34128 | 97008-H34128 | \$ 331.00 | 10% | \$300.13 |
| EW 4HR ONSITE H34129 | 97008-H34129 | \$ 725.00 | 10% | \$657.39 |
| EW 4HR ONSITE H34130 | 97008-H34130 | \$ 754.00 | 10% | \$683.69 |
| EW 4HR ONSITE H34131 | 97008-H34131 | \$ 750.00 | 10% | \$680.06 |
| EW 4HR ONSITE H34132 | 97008-H34132 | \$ 754.00 | 10% | \$683.69 |
| EW 4HR ONSITE H34172 | 97008-H34172 | \$ 2,720.00 | 10% | \$2,466.36 |
| EW 4HR ONSITE H34726 | 97008-H34726 | \$ 4,813.00 | 10% | \$4,364.19 |
| EW 4HR ONSITE H34727 | 97008-H34727 | \$ 4,813.00 | 10% | \$4,364.19 |
| EW 4HR ONSITE H34728 | 97008-H34728 | \$ 4,813.00 | 10% | \$4,364.19 |
| EW 4HR ONSITE H34729 | 97008-H34729 | \$ 4,813.00 | 10% | \$4,364.19 |
| EW 4HR ONSITE H34730 | 97008-H34730 | \$ 5,162.00 | 10% | \$4,680.64 |
| EW 4HR ONSITE H34731 | 97008-H34731 | \$ 5,162.00 | 10% | \$4,680.64 |
| EW 4HR ONSITE H34732 | 97008-H34732 | \$ 5,162.00 | 10% | \$4,680.64 |
| EW 4HR ONSITE H34733 | 97008-H34733 | \$ 5,162.00 | 10% | \$4,680.64 |
| EW 4HR ONSITE H34734 | 97008-H34734 | \$ 746.00 | 10% | \$676.44 |
| EW 4HR ONSITE H34735 | 97008-H34735 | \$ 746.00 | 10% | \$676.44 |
| EW 4HR ONSITE H34736 | 97008-H34736 | \$ 951.00 | 10% | \$862.32 |
| EW 4HR ONSITE H34737 | 97008-H34737 | \$ 951.00 | 10% | \$862.32 |
| EW 4HR ONSITE H34738 | 97008-H34738 | \$ 1,799.00 | 10% | \$1,631.24 |

| | | | | |
|----------------------|--------------|--------------|-----|--------------------|
| EW 4HR ONSITE H34739 | 97008-H34739 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34740 | 97008-H34740 | \$ 746.00 | 10% | <i>\$676.44</i> |
| EW 4HR ONSITE H34741 | 97008-H34741 | \$ 746.00 | 10% | <i>\$676.44</i> |
| EW 4HR ONSITE H34742 | 97008-H34742 | \$ 639.00 | 10% | <i>\$579.41</i> |
| EW 4HR ONSITE H34743 | 97008-H34743 | \$ 639.00 | 10% | <i>\$579.41</i> |
| EW 4HR ONSITE H34744 | 97008-H34744 | \$ 947.00 | 10% | <i>\$858.69</i> |
| EW 4HR ONSITE H34745 | 97008-H34745 | \$ 947.00 | 10% | <i>\$858.69</i> |
| EW 4HR ONSITE H34746 | 97008-H34746 | \$ 1,072.00 | 10% | <i>\$972.04</i> |
| EW 4HR ONSITE H34747 | 97008-H34747 | \$ 1,072.00 | 10% | <i>\$972.04</i> |
| EW 4HR ONSITE H34748 | 97008-H34748 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34749 | 97008-H34749 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34750 | 97008-H34750 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34751 | 97008-H34751 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34752 | 97008-H34752 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34753 | 97008-H34753 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34754 | 97008-H34754 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34755 | 97008-H34755 | \$ 1,799.00 | 10% | <i>\$1,631.24</i> |
| EW 4HR ONSITE H34756 | 97008-H34756 | \$ 951.00 | 10% | <i>\$862.32</i> |
| EW 4HR ONSITE H34757 | 97008-H34757 | \$ 951.00 | 10% | <i>\$862.32</i> |
| EW 4HR ONSITE H34758 | 97008-H34758 | \$ 947.00 | 10% | <i>\$858.69</i> |
| EW 4HR ONSITE H34759 | 97008-H34759 | \$ 951.00 | 10% | <i>\$862.32</i> |
| EW 4HR ONSITE H34760 | 97008-H34760 | \$ 951.00 | 10% | <i>\$862.32</i> |
| EW 4HR ONSITE H34761 | 97008-H34761 | \$ 947.00 | 10% | <i>\$858.69</i> |
| EW 4HR ONSITE H34839 | 97008-H34839 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34840 | 97008-H34840 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34841 | 97008-H34841 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34842 | 97008-H34842 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34843 | 97008-H34843 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34844 | 97008-H34844 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34845 | 97008-H34845 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34846 | 97008-H34846 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW 4HR ONSITE H34993 | 97008-H34993 | \$ 19,039.00 | 10% | <i>\$17,263.61</i> |
| EW 4HR ONSITE H34994 | 97008-H34994 | \$ 19,039.00 | 10% | <i>\$17,263.61</i> |
| EW 4HR ONSITE H34996 | 97008-H34996 | \$ 19,039.00 | 10% | <i>\$17,263.61</i> |
| EW 4HR ONSITE H34997 | 97008-H34997 | \$ 19,039.00 | 10% | <i>\$17,263.61</i> |
| EW 4HR ONSITE H35005 | 97008-H35005 | \$ 15,019.00 | 10% | <i>\$13,618.48</i> |
| EW 4HR ONSITE H35006 | 97008-H35006 | \$ 15,019.00 | 10% | <i>\$13,618.48</i> |
| EW 4HR ONSITE H35012 | 97008-H35012 | \$ 9,015.00 | 10% | <i>\$8,174.35</i> |
| EW 4HR ONSITE H35084 | 97008-H35084 | \$ 14,721.00 | 10% | <i>\$13,348.27</i> |
| EW 4HR ONSITE H35085 | 97008-H35085 | \$ 22,089.00 | 10% | <i>\$20,029.20</i> |
| EW 4HR ONSITE H35086 | 97008-H35086 | \$ 32,262.00 | 10% | <i>\$29,253.57</i> |
| EW 4HR ONSITE H35087 | 97008-H35087 | \$ 3,223.00 | 10% | <i>\$2,922.46</i> |

| | | | | |
|-----------------------|--------------|--------------|-----|-------------|
| EW 4HR ONSITE H35088 | 97008-H35088 | \$ 6,448.00 | 10% | \$5,846.72 |
| EW 4HR ONSITE H35089 | 97008-H35089 | \$ 32,262.00 | 10% | \$29,253.57 |
| EW 4HR ONSITE H35092 | 97008-H35092 | \$ 697.00 | 10% | \$632.00 |
| EW 4HR ONSITE H35093 | 97008-H35093 | \$ 10,951.00 | 10% | \$9,929.82 |
| EW 4HR ONSITE H35094 | 97008-H35094 | \$ 6,074.00 | 10% | \$5,507.60 |
| EW 4HR ONSITE H35262 | 97008-H35262 | \$ 3,375.00 | 10% | \$3,060.28 |
| EW 4HR ONSITE H35270 | 97008-H35270 | \$ 773.00 | 10% | \$700.92 |
| EW 4HR ONSITE H35271 | 97008-H35271 | \$ 575.00 | 10% | \$521.38 |
| EW 4HR ONSITE H35273 | 97008-H35273 | \$ 502.00 | 10% | \$455.19 |
| EW 4HR ONSITE H35274 | 97008-H35274 | \$ 1,077.00 | 10% | \$976.57 |
| EW 4HR ONSITE H35275 | 97008-H35275 | \$ 843.00 | 10% | \$764.39 |
| EW 4HR ONSITE H35276 | 97008-H35276 | \$ 4,628.00 | 10% | \$4,196.44 |
| EW 4HR ONSITE H35277 | 97008-H35277 | \$ 5,547.00 | 10% | \$5,029.74 |
| EW 4HR ONSITE H35278 | 97008-H35278 | \$ 3,719.00 | 10% | \$3,372.20 |
| EW 4HR ONSITE H35279 | 97008-H35279 | \$ 4,154.00 | 10% | \$3,766.64 |
| EW 4HR ONSITE H35280 | 97008-H35280 | \$ 8,747.00 | 10% | \$7,931.34 |
| EW 4HR ONSITE H35281 | 97008-H35281 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35282 | 97008-H35282 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35283 | 97008-H35283 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35284 | 97008-H35284 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35285 | 97008-H35285 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35286 | 97008-H35286 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35287 | 97008-H35287 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35288 | 97008-H35288 | \$ 2,476.00 | 10% | \$2,245.11 |
| EW 4HR ONSITE H35289 | 97008-H35289 | \$ 6,549.00 | 10% | \$5,938.31 |
| EW 4HR ONSITE H35291 | 97008-H35291 | \$ 4,953.00 | 10% | \$4,491.13 |
| EW 4HR ONSITE H35292 | 97008-H35292 | \$ 3,719.00 | 10% | \$3,372.20 |
| EW 4HR ONSITE H35293 | 97008-H35293 | \$ 4,154.00 | 10% | \$3,766.64 |
| EW 4HR ONSITE H35295 | 97008-H35295 | \$ 690.00 | 10% | \$625.66 |
| EW 4hr On-Site H35296 | 97008-H35296 | \$ 9,289.00 | 10% | \$8,422.80 |
| EW 4hr On-Site H35297 | 97008-H35297 | \$ 9,289.00 | 10% | \$8,422.80 |
| EW 4hr On-Site H35298 | 97008-H35298 | \$ 14,931.00 | 10% | \$13,538.68 |
| EW 4hr On-Site H35299 | 97008-H35299 | \$ 14,931.00 | 10% | \$13,538.68 |
| EW 4hr On-Site H35302 | 97008-H35302 | \$ 3,604.00 | 10% | \$3,267.93 |
| EW 4hr On-Site H35303 | 97008-H35303 | \$ 3,604.00 | 10% | \$3,267.93 |
| EW 4hr On-Site H35304 | 97008-H35304 | \$ 3,604.00 | 10% | \$3,267.93 |
| EW 4hr On-Site H35305 | 97008-H35305 | \$ 3,775.00 | 10% | \$3,422.98 |
| EW 4hr On-Site H35306 | 97008-H35306 | \$ 3,775.00 | 10% | \$3,422.98 |
| EW 4hr On-Site H35307 | 97008-H35307 | \$ 3,775.00 | 10% | \$3,422.98 |
| EW 4HR ONSITE H35309 | 97008-H35309 | \$ 5,046.00 | 10% | \$4,575.46 |
| EW 4HR ONSITE H35310 | 97008-H35310 | \$ 5,046.00 | 10% | \$4,575.46 |
| EW 4HR ONSITE H35311 | 97008-H35311 | \$ 5,046.00 | 10% | \$4,575.46 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE H35312 | 97008-H35312 | \$ 4,166.00 | 10% | \$3,777.52 |
| EW 4HR ONSITE H35313 | 97008-H35313 | \$ 4,166.00 | 10% | \$3,777.52 |
| EW 4HR ONSITE H35314 | 97008-H35314 | \$ 4,166.00 | 10% | \$3,777.52 |
| EW 4HR ONSITE H35315 | 97008-H35315 | \$ 1,806.00 | 10% | \$1,637.59 |
| EW 4HR ONSITE H35318 | 97008-H35318 | \$ 865.00 | 10% | \$784.34 |
| EW 4HR ONSITE H35319 | 97008-H35319 | \$ 1,165.00 | 10% | \$1,056.36 |
| EW 4HR ONSITE H35320 | 97008-H35320 | \$ 1,207.00 | 10% | \$1,094.45 |
| EW 4HR ONSITE H35321 | 97008-H35321 | \$ 1,509.00 | 10% | \$1,368.29 |
| EW 4HR ONSITE H35322 | 97008-H35322 | \$ 1,841.00 | 10% | \$1,669.33 |
| EW 4HR ONSITE H35323 | 97008-H35323 | \$ 1,806.00 | 10% | \$1,637.59 |
| EW 4HR ONSITE H35328 | 97008-H35328 | \$ 156.00 | 10% | \$141.45 |
| EW 4HR ONSITE H35330 | 97008-H35330 | \$ 128.00 | 10% | \$116.06 |
| EW 4HR ONSITE H35340 | 97008-H35340 | \$ 3,893.00 | 10% | \$3,529.98 |
| EW 4HR ONSITE H35341 | 97008-H35341 | \$ 3,893.00 | 10% | \$3,529.98 |
| EW 4HR ONSITE H35342 | 97008-H35342 | \$ 2,948.00 | 10% | \$2,673.10 |
| EW 4HR ONSITE H35343 | 97008-H35343 | \$ 3,893.00 | 10% | \$3,529.98 |
| EW 4HR ONSITE H35344 | 97008-H35344 | \$ 3,479.00 | 10% | \$3,154.58 |
| EW 4HR ONSITE H35345 | 97008-H35345 | \$ 3,479.00 | 10% | \$3,154.58 |
| EW 4HR ONSITE H35346 | 97008-H35346 | \$ 3,058.00 | 10% | \$2,772.84 |
| EW 4HR ONSITE H35347 | 97008-H35347 | \$ 3,479.00 | 10% | \$3,154.58 |
| EW 4HR ONSITE H35349 | 97008-H35349 | \$ 4,479.00 | 10% | \$4,061.33 |
| EW 4HR ONSITE H35350 | 97008-H35350 | \$ 4,479.00 | 10% | \$4,061.33 |
| EW 4HR ONSITE H35351 | 97008-H35351 | \$ 3,349.00 | 10% | \$3,036.71 |
| EW 4HR ONSITE H35352 | 97008-H35352 | \$ 4,479.00 | 10% | \$4,061.33 |
| EW 4HR ONSITE H35359 | 97008-H35359 | \$ 1,509.00 | 10% | \$1,368.29 |
| EW 4HR ONSITE H35360 | 97008-H35360 | \$ 1,841.00 | 10% | \$1,669.33 |
| EW 4HR ONSITE H35361 | 97008-H35361 | \$ 1,806.00 | 10% | \$1,637.59 |
| EW 4HR ONSITE H35362 | 97008-H35362 | \$ 865.00 | 10% | \$784.34 |
| EW 4HR ONSITE H35366 | 97008-H35366 | \$ 1,960.00 | 10% | \$1,777.23 |
| EW 4HR ONSITE H35367 | 97008-H35367 | \$ 2,286.00 | 10% | \$2,072.83 |
| EW 4HR ONSITE H35368 | 97008-H35368 | \$ 3,479.00 | 10% | \$3,154.58 |
| EW 4HR ONSITE H35369 | 97008-H35369 | \$ 1,131.00 | 10% | \$1,025.53 |
| EW 4HR ONSITE H35370 | 97008-H35370 | \$ 1,588.00 | 10% | \$1,439.92 |
| EW 4HR ONSITE H35375 | 97008-H35375 | \$ 954.00 | 10% | \$865.04 |
| EW 4HR ONSITE H35376 | 97008-H35376 | \$ 1,431.00 | 10% | \$1,297.56 |
| EW 4HR ONSITE H35377 | 97008-H35377 | \$ 599.00 | 10% | \$543.14 |
| EW 4HR ONSITE H35378 | 97008-H35378 | \$ 954.00 | 10% | \$865.04 |
| EW 4HR ONSITE H35379 | 97008-H35379 | \$ 599.00 | 10% | \$543.14 |
| EW 4HR ONSITE H35380 | 97008-H35380 | \$ 1,074.00 | 10% | \$973.85 |
| EW 4HR ONSITE H35381 | 97008-H35381 | \$ 1,310.00 | 10% | \$1,187.84 |
| EW 4HR ONSITE H35384 | 97008-H35384 | \$ 433.00 | 10% | \$392.62 |
| EW 4HR ONSITE H35385 | 97008-H35385 | \$ 573.00 | 10% | \$519.57 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW 4HR ONSITE H35386 | 97008-H35386 | \$ 954.00 | 10% | \$865.04 |
| EW 4HR ONSITE H35387 | 97008-H35387 | \$ 893.00 | 10% | \$809.73 |
| EW 4HR ONSITE H35388 | 97008-H35388 | \$ 655.00 | 10% | \$593.92 |
| EW 4HR ONSITE H35389 | 97008-H35389 | \$ 369.00 | 10% | \$334.59 |
| EW 4HR ONSITE H35390 | 97008-H35390 | \$ 321.00 | 10% | \$291.07 |
| EW 4HR ONSITE H35391 | 97008-H35391 | \$ 701.00 | 10% | \$635.63 |
| EW 4HR ONSITE H35392 | 97008-H35392 | \$ 1,074.00 | 10% | \$973.85 |
| EW 4HR ONSITE H35393 | 97008-H35393 | \$ 1,431.00 | 10% | \$1,297.56 |
| EW 4HR ONSITE H35394 | 97008-H35394 | \$ 260.00 | 10% | \$235.76 |
| EW 4HR ONSITE H35395 | 97008-H35395 | \$ 216.00 | 10% | \$195.86 |
| EW 4HR ONSITE H35396 | 97008-H35396 | \$ 260.00 | 10% | \$235.76 |
| EW 4HR ONSITE H35397 | 97008-H35397 | \$ 216.00 | 10% | \$195.86 |
| EW 4HR ONSITE H35398 | 97008-H35398 | \$ 668.00 | 10% | \$605.71 |
| EW 4HR ONSITE H35399 | 97008-H35399 | \$ 815.00 | 10% | \$739.00 |
| EW 4HR ONSITE H35400 | 97008-H35400 | \$ 897.00 | 10% | \$813.35 |
| EW 4HR ONSITE H35401 | 97008-H35401 | \$ 477.00 | 10% | \$432.52 |
| EW 4HR ONSITE H35415 | 97008-H35415 | \$ 327.00 | 10% | \$296.51 |
| EW 4HR ONSITE H35416 | 97008-H35416 | \$ 327.00 | 10% | \$296.51 |
| EW 4HR ONSITE H35426 | 97008-H35426 | \$ 369.00 | 10% | \$334.59 |
| EW 4HR ONSITE H35427 | 97008-H35427 | \$ 893.00 | 10% | \$809.73 |
| EW 4HR ONSITE H35428 | 97008-H35428 | \$ 321.00 | 10% | \$291.07 |
| EW 4HR ONSITE H35429 | 97008-H35429 | \$ 701.00 | 10% | \$635.63 |
| EW 4HR ONSITE H35430 | 97008-H35430 | \$ 723.00 | 10% | \$655.58 |
| EW 4HR ONSITE H35431 | 97008-H35431 | \$ 723.00 | 10% | \$655.58 |
| EW 4HR ONSITE H35432 | 97008-H35432 | \$ 639.00 | 10% | \$579.41 |
| EW 4HR ONSITE H35433 | 97008-H35433 | \$ 924.00 | 10% | \$837.84 |
| EW 4HR ONSITE H35434 | 97008-H35434 | \$ 1,046.00 | 10% | \$948.46 |
| EW 4HR ONSITE H35435 | 97008-H35435 | \$ 1,046.00 | 10% | \$948.46 |
| EW 4HR ONSITE H35436 | 97008-H35436 | \$ 1,746.00 | 10% | \$1,583.19 |
| EW 4HR ONSITE H35437 | 97008-H35437 | \$ 1,746.00 | 10% | \$1,583.19 |
| EW 4HR ONSITE H35438 | 97008-H35438 | \$ 1,746.00 | 10% | \$1,583.19 |
| EW 4HR ONSITE H35439 | 97008-H35439 | \$ 1,746.00 | 10% | \$1,583.19 |
| EW 4HR ONSITE H35440 | 97008-H35440 | \$ 924.00 | 10% | \$837.84 |
| EW 4HR ONSITE H35441 | 97008-H35441 | \$ 924.00 | 10% | \$837.84 |
| EW 4HR ONSITE H35442 | 97008-H35442 | \$ 924.00 | 10% | \$837.84 |
| EW 4HR ONSITE H35443 | 97008-H35443 | \$ 4,813.00 | 10% | \$4,364.19 |
| EW 4HR ONSITE H35444 | 97008-H35444 | \$ 5,162.00 | 10% | \$4,680.64 |
| EW 4HR ONSITE H35445 | 97008-H35445 | \$ 4,628.00 | 10% | \$4,196.44 |
| EW 4HR ONSITE H35446 | 97008-H35446 | \$ 4,541.00 | 10% | \$4,117.55 |
| EW 4HR ONSITE H35447 | 97008-H35447 | \$ 5,257.00 | 10% | \$4,766.78 |
| EW 4HR ONSITE H35448 | 97008-H35448 | \$ 5,043.00 | 10% | \$4,572.74 |
| EW 4HR ONSITE H35449 | 97008-H35449 | \$ 3,719.00 | 10% | \$3,372.20 |

| | | | | |
|---------------------------------|-------------------------|--------------|-----|-------------|
| EW 4HR ONSITE H35450 | 97008-H35450 | \$ 3,937.00 | 10% | \$3,569.87 |
| EW 4HR ONSITE H35451 | 97008-H35451 | \$ 9,256.00 | 10% | \$8,392.88 |
| EW 4HR ONSITE H35452 | 97008-H35452 | \$ 9,256.00 | 10% | \$8,392.88 |
| EW 4HR ONSITE H35453 | 97008-H35453 | \$ 5,162.00 | 10% | \$4,680.64 |
| EW 4HR ONSITE H35454 | 97008-H35454 | \$ 4,813.00 | 10% | \$4,364.19 |
| EW 4HR ONSITE H35455 | 97008-H35455 | \$ 1,207.00 | 10% | \$1,094.45 |
| EW 4HR ONSITE H35456 | 97008-H35456 | \$ 1,499.00 | 10% | \$1,359.22 |
| EW 4HR ONSITE H35457 | 97008-H35457 | \$ 1,343.00 | 10% | \$1,217.77 |
| EW 4HR ONSITE H35458 | 97008-H35458 | \$ 1,475.00 | 10% | \$1,337.46 |
| EW 4HR ONSITE H35471 | 97008-H35471 | \$ 1,207.00 | 10% | \$1,094.45 |
| EW 4HR ONSITE H35600 | 97008-H35600 | \$ 502.00 | 10% | \$455.19 |
| EW 4HR ONSITE H35601 | 97008-H35601 | \$ 502.00 | 10% | \$455.19 |
| EW 4HR ONSITE H35602 | 97008-H35602 | \$ 746.00 | 10% | \$676.44 |
| EW 4HR ONSITE H35603 | 97008-H35603 | \$ 746.00 | 10% | \$676.44 |
| EW 4HR ONSITE H35604 | 97008-H35604 | \$ 951.00 | 10% | \$862.32 |
| EW 4HR ONSITE H35605 | 97008-H35605 | \$ 951.00 | 10% | \$862.32 |
| EW 4HR ONSITE H35606 | 97008-H35606 | \$ 1,077.00 | 10% | \$976.57 |
| EW 4HR ONSITE H35607 | 97008-H35607 | \$ 1,072.00 | 10% | \$972.04 |
| EW 4HR ONSITE ISW-24W-4X | 97008-ISW-24W-4X | \$ 1,269.00 | 10% | \$1,150.67 |
| EW 4HR ONSITE ISW-4W-4WS-4X | 97008-ISW-4W-4WS-4X | \$ 806.00 | 10% | \$730.84 |
| EW 4HR ONSITE BD MSM128 | 97008-MSM128 | \$ 4,238.00 | 10% | \$3,842.81 |
| EW 4HR ONSITE BD MSM48C | 97008-MSM48C | \$ 2,529.00 | 10% | \$2,293.17 |
| EW 4HR ONSITE SLX9150-48XT-DC-F | 97008-SLX9150-48XT-DC-F | \$ 3,034.00 | 10% | \$2,751.08 |
| EW 4HR ONSITE SLX9150-48XT-DC-R | 97008-SLX9150-48XT-DC-R | \$ 3,313.00 | 10% | \$3,004.06 |
| EW 4HR ONSITE SLX9150-48Y-DC-F | 97008-SLX9150-48Y-DC-F | \$ 3,395.00 | 10% | \$3,078.42 |
| EW 4HR ONSITE SLX9150-48Y-DC-R | 97008-SLX9150-48Y-DC-R | \$ 3,708.00 | 10% | \$3,362.23 |
| EW 4HR ONSITE SLX9740-40C | 97008-SLX9740-40C | \$ 13,074.00 | 10% | \$11,854.85 |
| EW 4HR ONSITE SLX9740-40C-AC-F | 97008-SLX9740-40C-AC-F | \$ 13,074.00 | 10% | \$11,854.85 |

| | | | | |
|---------------------------------|------------------------|--------------|-----|--------------------|
| EW 4HR ONSITE SLX9740-40C-AC-R | 97008-SLX9740-40C-AC-R | \$ 13,074.00 | 10% | <i>\$11,854.85</i> |
| EW 4HR ONSITE SLX9740-40C-DC-F | 97008-SLX9740-40C-DC-F | \$ 13,074.00 | 10% | <i>\$11,854.85</i> |
| EW 4HR ONSITE SLX9740-80C | 97008-SLX9740-80C | \$ 24,585.00 | 10% | <i>\$22,292.45</i> |
| EW 4HR ONSITE SLX9740-80C-AC-F | 97008-SLX9740-80C-AC-F | \$ 24,585.00 | 10% | <i>\$22,292.45</i> |
| EW 4HR ONSITE SLX9740-80C-AC-R | 97008-SLX9740-80C-AC-R | \$ 24,585.00 | 10% | <i>\$22,292.45</i> |
| EW 4HR ONSITE SLX9740-80C-DC-F | 97008-SLX9740-80C-DC-F | \$ 24,585.00 | 10% | <i>\$22,292.45</i> |
| EW 4HR ONSITE V300-8P-2X | 97008-V300-8P-2X | \$ 203.00 | 10% | <i>\$184.07</i> |
| EW 4HR ONSITE V300-8T-2X | 97008-V300-8T-2X | \$ 139.00 | 10% | <i>\$126.04</i> |
| EW 4HR ONSITE V300HT-8P-2X | 97008-V300HT-8P-2X | \$ 461.00 | 10% | <i>\$418.01</i> |
| EW 4HR ONSITE V300HT-8T-2X | 97008-V300HT-8T-2X | \$ 278.00 | 10% | <i>\$252.08</i> |
| EW 4HR ONSITE Summit VIM-SS | 97008-VIM-SS | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW 4HR ONSITE Summit VIM-SSV80 | 97008-VIM-SSV80 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW 4HR ONSITE Summit VIM2-SS | 97008-VIM2-SS | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW 4HR ONSITE Summit VIM2-SS128 | 97008-VIM2-SS128 | \$ 857.00 | 10% | <i>\$777.08</i> |
| EW 4HR ONSITE Summit VIM2-V80 | 97008-VIM2-V80 | \$ 913.00 | 10% | <i>\$827.86</i> |
| EW 4HR ONSITE Summit VIM210G4X | 97008-VIM210G4X | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW 4HR ONSITE VIM5-2Q | 97008-VIM5-2Q | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW 4HR ONSITE VIM5-2Y | 97008-VIM5-2Y | \$ 324.00 | 10% | <i>\$293.79</i> |

| | | | | |
|-------------------------------------|-----------------------------|-------------|-----|-------------------|
| EW 4HR ONSITE VIM5-4X | 97008-VIM5-4X | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW 4HR ONSITE VIM5-4XE | 97008-VIM5-4XE | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW 4HR ONSITE VIM5-4Y | 97008-VIM5-4Y | \$ 417.00 | 10% | <i>\$378.11</i> |
| EW 4HR ONSITE VIM5-4YE | 97008-VIM5-4YE | \$ 534.00 | 10% | <i>\$484.20</i> |
| EW 4HR ONSITE VSP4900-12MXU-12XE | 97008-VSP4900-12MXU-12XE | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW 4HR ONSITE VSP4900-12MXU-12XE-B1 | 97008-VSP4900-12MXU-12XE-B1 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW 4HR ONSITE VSP4900-24S | 97008-VSP4900-24S | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW 4HR ONSITE VSP4900-24S-B3 | 97008-VSP4900-24S-B3 | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW 4HR ONSITE VSP4900-24XE | 97008-VSP4900-24XE | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW 4HR ONSITE VSP4900-24XE-B3 | 97008-VSP4900-24XE-B3 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW 4HR ONSITE X435-24P-4S | 97008-X435-24P-4S | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW 4HR ONSITE X435-24T-4S | 97008-X435-24T-4S | \$ 199.00 | 10% | <i>\$180.44</i> |
| EW 4HR ONSITE X435-8P-2T-W | 97008-X435-8P-2T-W | \$ 199.00 | 10% | <i>\$180.44</i> |
| EW 4HR ONSITE X435-8P-4S | 97008-X435-8P-4S | \$ 180.00 | 10% | <i>\$163.22</i> |
| EW 4HR ONSITE X435-8T-4S | 97008-X435-8T-4S | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW 4HR ONSITE Summit X460-24P | 97008-X460-24P | \$ 1,491.00 | 10% | <i>\$1,351.96</i> |
| EW 4HR ONSITE Summit X460-24T | 97008-X460-24T | \$ 1,043.00 | 10% | <i>\$945.74</i> |
| EW 4HR ONSITE Summit X460-24TDC | 97008-X460-24TDC | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |

| | | | | |
|---------------------------------|-----------------------|-------------|-----|-------------------|
| EW 4HR ONSITE Summit X460-24X | 97008-X460-24X | \$ 1,932.00 | 10% | <i>\$1,751.84</i> |
| EW 4HR ONSITE Summit X460-24XDC | 97008-X460-24XDC | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW 4HR ONSITE Summit X460-48P | 97008-X460-48P | \$ 1,932.00 | 10% | <i>\$1,751.84</i> |
| EW 4HR ONSITE Summit X460-48T | 97008-X460-48T | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW 4HR ONSITE Summit X460-48TDC | 97008-X460-48TDC | \$ 2,085.00 | 10% | <i>\$1,890.57</i> |
| EW 4HR ONSITE Summit X460-48X | 97008-X460-48X | \$ 2,569.00 | 10% | <i>\$2,329.44</i> |
| EW 4HR ONSITE Summit X460-48XDC | 97008-X460-48XDC | \$ 2,503.00 | 10% | <i>\$2,269.60</i> |
| EW 4HR ONSITE X465-24MU | 97008-X465-24MU | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW 4HR ONSITE X465-24S | 97008-X465-24S | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW 4HR ONSITE X465-24S-B3 | 97008-X465-24S-B3 | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW 4HR ONSITE X465-24W | 97008-X465-24W | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW 4HR ONSITE X465-24XE | 97008-X465-24XE | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW 4HR ONSITE X465-24XE-B3 | 97008-X465-24XE-B3 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW 4HR ONSITE X465-48P | 97008-X465-48P | \$ 1,207.00 | 10% | <i>\$1,094.45</i> |
| EW 4HR ONSITE X465-48T | 97008-X465-48T | \$ 1,165.00 | 10% | <i>\$1,056.36</i> |
| EW 4HR ONSITE X465-48W | 97008-X465-48W | \$ 1,509.00 | 10% | <i>\$1,368.29</i> |
| EW 4HR ONSITE X465i-48W | 97008-X465i-48W | \$ 1,806.00 | 10% | <i>\$1,637.59</i> |
| EW 4HR ONSITE X465i-48W-B1-S1 | 97008-X465i-48W-B1-S1 | \$ 1,806.00 | 10% | <i>\$1,637.59</i> |
| EW 4HR ONSITE X465i-48W-B2-S1 | 97008-X465i-48W-B2-S1 | \$ 1,806.00 | 10% | <i>\$1,637.59</i> |
| EW 4HR ONSITE Summit X480-24X | 97008-X480-24X | \$ 2,374.00 | 10% | <i>\$2,152.62</i> |
| EW 4HR ONSITE Summit X480-48T | 97008-X480-48T | \$ 2,374.00 | 10% | <i>\$2,152.62</i> |

| | | | | |
|---------------------------------|-------------------------|-------------|-----|-------------------|
| EW 4HR ONSITE Summit X480-48X | 97008-X480-48X | \$ 3,166.00 | 10% | <i>\$2,870.77</i> |
| EW 4HR ONSITE X695-48Y-8C | 97008-X695-48Y-8C | \$ 4,216.00 | 10% | <i>\$3,822.86</i> |
| EW 4HR ONSITE XA1440 | 97008-XA1440 | \$ 442.00 | 10% | <i>\$400.78</i> |
| EW 4HR ONSITE XA1480 | 97008-XA1480 | \$ 589.00 | 10% | <i>\$534.08</i> |
| EW 4HR ONSITE Summit XGM3-2SF | 97008-XGM3-2SF | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW 4HR ONSITE XR600 | 97008-XR600 | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW 4HR ONSITE XSW-BR-M-A-D | 97008-XSW-BR-M-A-D | \$ 201.00 | 10% | <i>\$182.26</i> |
| EW 4HR ONSITE 3YR XSW-BR-M-A-D | 97008-XSW-BR-M-A-D-3YR | \$ 603.00 | 10% | <i>\$546.77</i> |
| EW 4HR ONSITE 5YR XSW-BR-M-A-D | 97008-XSW-BR-M-A-D-5YR | \$ 1,005.00 | 10% | <i>\$911.28</i> |
| EW 4HR ONSITE XSW-BR-S-A-D | 97008-XSW-BR-S-A-D | \$ 91.00 | 10% | <i>\$82.51</i> |
| EW 4HR ONSITE 3YR XSW-BR-S-A-D | 97008-XSW-BR-S-A-D-3YR | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW 4HR ONSITE 5YR XSW-BR-S-A-D | 97008-XSW-BR-S-A-D-5YR | \$ 454.00 | 10% | <i>\$411.66</i> |
| EW 4HR ONSITE XSW-BR-XS-A-D | 97008-XSW-BR-XS-A-D | \$ 73.00 | 10% | <i>\$66.19</i> |
| EW 4HR ONSITE 3YR XSW-BR-XS-A-D | 97008-XSW-BR-XS-A-D-3YR | \$ 218.00 | 10% | <i>\$197.67</i> |
| EW 4HR ONSITE 5YR XSW-BR-XS-A-D | 97008-XSW-BR-XS-A-D-5YR | \$ 363.00 | 10% | <i>\$329.15</i> |
| EW 4HR ONSITE XSW-DC-S-A-D | 97008-XSW-DC-S-A-D | \$ 461.00 | 10% | <i>\$418.01</i> |
| EW 4HR ONSITE 3YR XSW-DC-S-A-D | 97008-XSW-DC-S-A-D-3YR | \$ 1,382.00 | 10% | <i>\$1,253.13</i> |
| EW 4HR ONSITE 5YR XSW-DC-S-A-D | 97008-XSW-DC-S-A-D-5YR | \$ 2,304.00 | 10% | <i>\$2,089.15</i> |

| | | | | |
|-------------------------------------|-----------------------------|-------------|-----|-------------------|
| EW 4HR ONSITE XSW-DCV2-LR-L-A-D | 97008-XSW-DCV2-LR-L-A-D | \$ 1,961.00 | 10% | <i>\$1,778.14</i> |
| EW 4HR ONSITE 3YR XSW-DCV2-LR-L-A-D | 97008-XSW-DCV2-LR-L-A-D-3YR | \$ 5,882.00 | 10% | <i>\$5,333.50</i> |
| EW 4HR ONSITE 5YR XSW-DCV2-LR-L-A-D | 97008-XSW-DCV2-LR-L-A-D-5YR | \$ 9,804.00 | 10% | <i>\$8,889.78</i> |
| EW 4HR ONSITE XSW-DCV2-M-A-D | 97008-XSW-DCV2-M-A-D | \$ 1,078.00 | 10% | <i>\$977.48</i> |
| EW 4HR ONSITE 3YR XSW-DCV2-M-A-D | 97008-XSW-DCV2-M-A-D-3YR | \$ 3,235.00 | 10% | <i>\$2,933.34</i> |
| EW 4HR ONSITE 5YR XSW-DCV2-M-A-D | 97008-XSW-DCV2-M-A-D-5YR | \$ 5,392.00 | 10% | <i>\$4,889.20</i> |
| EW 4HR ONSITE XSW-DCV2-SR-L-A-D | 97008-XSW-DCV2-SR-L-A-D | \$ 1,961.00 | 10% | <i>\$1,778.14</i> |
| EW 4HR ONSITE 3YR XSW-DCV2-SR-L-A-D | 97008-XSW-DCV2-SR-L-A-D-3YR | \$ 5,882.00 | 10% | <i>\$5,333.50</i> |
| EW 4HR ONSITE 5YR XSW-DCV2-SR-L-A-D | 97008-XSW-DCV2-SR-L-A-D-5YR | \$ 9,804.00 | 10% | <i>\$8,889.78</i> |
| EW 4HR ON-SITE -ZR-XFP | 97008-ZR-XFP | \$ 2,393.00 | 10% | <i>\$2,169.85</i> |
| EW NBD ONSITE Optics 10200 | 97011-10200 | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW NBD ONSITE Optics 10320 | 97011-10320 | \$ 2,374.00 | 10% | <i>\$2,152.62</i> |
| EW NBD ONSITE 10335 | 97011-10335 | \$ 4,099.00 | 10% | <i>\$3,716.77</i> |
| EW NBD ONSITE 10403 | 97011-10403 | \$ 5,089.00 | 10% | <i>\$4,614.45</i> |
| EW NBD ONSITE 10404 | 97011-10404 | \$ 2,499.00 | 10% | <i>\$2,265.97</i> |
| EW NBD ONSITE 10441 | 97011-10441 | \$ 1,680.00 | 10% | <i>\$1,523.34</i> |
| EW NBD ONSITE 10442 | 97011-10442 | \$ 1,780.00 | 10% | <i>\$1,614.02</i> |
| EW NBD ONSITE 1130C | 97011-1130C | \$ 1,080.00 | 6% | <i>\$1,022.81</i> |
| EW NBD ONSITE E4G 16119 | 97011-16119 | \$ 303.00 | 10% | <i>\$274.75</i> |
| EW NBD ONSITE E4G 16120 | 97011-16120 | \$ 389.00 | 10% | <i>\$352.73</i> |
| EW NBD ONSITE E4G 16126 | 97011-16126 | \$ 303.00 | 10% | <i>\$274.75</i> |
| EW NBD ONSITE E4G 16127 | 97011-16127 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW NBD ONSITE 16172 | 97011-16172 | \$ 317.00 | 10% | <i>\$287.44</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|------------|
| EW NBD ONSITE -16172T | 97011-16172T | \$ 386.00 | 10% | \$350.01 |
| EW NBD ONSITE 16173 | 97011-16173 | \$ 326.00 | 10% | \$295.60 |
| EW NBD ONSITE -16173T | 97011-16173T | \$ 392.00 | 10% | \$355.45 |
| EW NBD ONSITE 16174 | 97011-16174 | \$ 501.00 | 10% | \$454.28 |
| EW NBD ONSITE 16175 | 97011-16175 | \$ 532.00 | 10% | \$482.39 |
| EW NBD ONSITE 16176 | 97011-16176 | \$ 473.00 | 10% | \$428.89 |
| EW NBD ONSITE 16177 | 97011-16177 | \$ 455.00 | 10% | \$412.57 |
| EW NBD ONSITE -16177T | 97011-16177T | \$ 584.00 | 10% | \$529.54 |
| EW NBD ONSITE 16178 | 97011-16178 | \$ 681.00 | 10% | \$617.50 |
| EW NBD ONSITE 16179 | 97011-16179 | \$ 694.00 | 10% | \$629.28 |
| EW NBD ONSITE -16179T | 97011-16179T | \$ 828.00 | 10% | \$750.79 |
| EW NBD ONSITE 16301T | 97011-16301T | \$ 1,824.00 | 10% | \$1,653.91 |
| EW NBD ONSITE 16303T | 97011-16303T | \$ 1,824.00 | 10% | \$1,653.91 |
| EW NBD ONSITE 16304T | 97011-16304T | \$ 2,435.00 | 10% | \$2,207.94 |
| EW NBD ONSITE 16401T | 97011-16401T | \$ 851.00 | 10% | \$771.64 |
| EW NBD ONSITE 16402T | 97011-16402T | \$ 1,299.00 | 10% | \$1,177.87 |
| EW NBD ONSITE 16403T | 97011-16403T | \$ 1,153.00 | 10% | \$1,045.48 |
| EW NBD ONSITE 16404T | 97011-16404T | \$ 1,153.00 | 10% | \$1,045.48 |
| EW NBD ONSITE 16405T | 97011-16405T | \$ 1,527.00 | 10% | \$1,384.61 |
| EW NBD ONSITE 16406T | 97011-16406T | \$ 2,025.00 | 10% | \$1,836.17 |
| EW NBD ONSITE E4G 16431 | 97011-16431 | \$ 1,286.00 | 10% | \$1,166.08 |
| EW NBD ONSITE E4G 16432 | 97011-16432 | \$ 1,390.00 | 10% | \$1,260.38 |
| EW NBD ONSITE E4G 16440 | 97011-16440 | \$ 798.00 | 10% | \$723.59 |
| EW NBD ONSITE E4G 16441 | 97011-16441 | \$ 722.00 | 10% | \$654.67 |
| EW NBD ONSITE E4G 16442 | 97011-16442 | \$ 318.00 | 10% | \$288.35 |
| EW NBD ONSITE E4G 16444 | 97011-16444 | \$ 160.00 | 10% | \$145.08 |
| EW NBD ONSITE Summit 16501 | 97011-16501 | \$ 177.00 | 10% | \$160.49 |
| EW NBD ONSITE 16501T | 97011-16501T | \$ 229.00 | 10% | \$207.65 |
| EW NBD ONSITE Summit 16502 | 97011-16502 | \$ 257.00 | 10% | \$233.03 |
| EW NBD ONSITE 16502T | 97011-16502T | \$ 301.00 | 10% | \$272.93 |
| EW NBD ONSITE Summit 16503 | 97011-16503 | \$ 207.00 | 10% | \$187.70 |
| EW NBD ONSITE 16503T | 97011-16503T | \$ 271.00 | 10% | \$245.73 |
| EW NBD ONSITE Summit 16504 | 97011-16504 | \$ 340.00 | 10% | \$308.30 |
| EW NBD ONSITE 16504T | 97011-16504T | \$ 418.00 | 10% | \$379.02 |
| EW NBD ONSITE Summit 16505 | 97011-16505 | \$ 383.00 | 10% | \$347.29 |
| EW NBD ONSITE 16505T | 97011-16505T | \$ 470.00 | 10% | \$426.17 |

| | | | | |
|----------------------------|--------------|-----------|-----|----------|
| EW NBD ONSITE Summit 16506 | 97011-16506 | \$ 591.00 | 10% | \$535.89 |
| EW NBD ONSITE 16506T | 97011-16506T | \$ 727.00 | 10% | \$659.21 |
| EW NBD ONSITE Summit 16507 | 97011-16507 | \$ 529.00 | 10% | \$479.67 |
| EW NBD ONSITE 16507T | 97011-16507T | \$ 639.00 | 10% | \$579.41 |
| EW NBD ONSITE Summit 16508 | 97011-16508 | \$ 668.00 | 10% | \$605.71 |
| EW NBD ONSITE 16508T | 97011-16508T | \$ 800.00 | 10% | \$725.40 |
| EW NBD ONSITE Summit 16509 | 97011-16509 | \$ 668.00 | 10% | \$605.71 |
| EW NBD ONSITE 16509T | 97011-16509T | \$ 800.00 | 10% | \$725.40 |
| EW NBD ONSITE Summit 16510 | 97011-16510 | \$ 800.00 | 10% | \$725.40 |
| EW NBD ONSITE 16510T | 97011-16510T | \$ 963.00 | 10% | \$873.20 |
| EW NBD On-site-16513 | 97011-16513 | \$ 521.00 | 10% | \$472.42 |
| EW NBD On-site-16514 | 97011-16514 | \$ 785.00 | 10% | \$711.80 |
| EW NBD ONSITE 16515 | 97011-16515 | \$ 136.00 | 10% | \$123.32 |
| EW NBD Onsite-16516 | 97011-16516 | \$ 152.00 | 10% | \$137.83 |
| EW NBD ONSITE 16517 | 97011-16517 | \$ 282.00 | 10% | \$255.70 |
| EW NBD Onsite-16518 | 97011-16518 | \$ 254.00 | 10% | \$230.31 |
| EW-NBD On-SITE 16519 | 97011-16519 | \$ 271.00 | 10% | \$245.73 |
| EW-NBD On-SITE 16520 | 97011-16520 | \$ 440.00 | 10% | \$398.97 |
| EW NBD ONSITE 16530 | 97011-16530 | \$ 161.00 | 10% | \$145.99 |
| EW NBD ONSITE 16531 | 97011-16531 | \$ 213.00 | 10% | \$193.14 |
| EW NBD ONSITE 16531T | 97011-16531T | \$ 237.00 | 10% | \$214.90 |
| EW NBD ONSITE 16532 | 97011-16532 | \$ 213.00 | 10% | \$193.14 |
| EW NBD ONSITE 16532T | 97011-16532T | \$ 237.00 | 10% | \$214.90 |
| EW NBD ONSITE 16533 | 97011-16533 | \$ 307.00 | 10% | \$278.37 |
| EW NBD ONSITE 16533T | 97011-16533T | \$ 334.00 | 10% | \$302.85 |
| EW NBD ONSITE 16534 | 97011-16534 | \$ 326.00 | 10% | \$295.60 |
| EW NBD ONSITE 16535 | 97011-16535 | \$ 487.00 | 10% | \$441.59 |
| EW NBD ONSITE 16535A | 97011-16535A | \$ 487.00 | 10% | \$441.59 |
| EW NBD ONSITE 16535T | 97011-16535T | \$ 540.00 | 10% | \$489.65 |
| EW NBD ONSITE 16536 | 97011-16536 | \$ 229.00 | 10% | \$207.65 |
| EW NBD ONSITE 16537 | 97011-16537 | \$ 304.00 | 10% | \$275.65 |
| EW NBD ONSITE 16538 | 97011-16538 | \$ 367.00 | 10% | \$332.78 |
| EW NBD ONSITE 16538T | 97011-16538T | \$ 450.00 | 10% | \$408.04 |
| EW NBD ONSITE 16539 | 97011-16539 | \$ 477.00 | 10% | \$432.52 |
| EW NBD ONSITE 16540 | 97011-16540 | \$ 338.00 | 10% | \$306.48 |
| EW NBD ONSITE 16541 | 97011-16541 | \$ 129.00 | 10% | \$116.97 |
| EW NBD ONSITE 16560 | 97011-16560 | \$ 75.00 | 10% | \$68.01 |

| | | | | |
|-----------------------|--------------|-------------|-----|-------------------|
| EW NBD ONSITE 16561 | 97011-16561 | \$ 109.00 | 10% | <i>\$98.84</i> |
| EW NBD ONSITE 16562 | 97011-16562 | \$ 130.00 | 10% | <i>\$117.88</i> |
| EW NBD ONSITE 16563 | 97011-16563 | \$ 171.00 | 10% | <i>\$155.05</i> |
| EW NBD ONSITE 16564 | 97011-16564 | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW NBD ONSITE 16565 | 97011-16565 | \$ 321.00 | 10% | <i>\$291.07</i> |
| EW NBD ONSITE 16566 | 97011-16566 | \$ 49.00 | 10% | <i>\$44.43</i> |
| EW NBD ONSITE 16567 | 97011-16567 | \$ 90.00 | 10% | <i>\$81.61</i> |
| EW NBD ONSITE 16568 | 97011-16568 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW NBD ONSITE 16569 | 97011-16569 | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW NBD ONSITE 16570 | 97011-16570 | \$ 130.00 | 10% | <i>\$117.88</i> |
| EW NBD ONSITE 16571 | 97011-16571 | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW NBD ONSITE 16701 | 97011-16701 | \$ 463.00 | 10% | <i>\$419.83</i> |
| EW NBD ONSITE 16702 | 97011-16702 | \$ 691.00 | 10% | <i>\$626.56</i> |
| EW NBD ONSITE 16703 | 97011-16703 | \$ 542.00 | 10% | <i>\$491.46</i> |
| EW NBD ONSITE -16703T | 97011-16703T | \$ 651.00 | 10% | <i>\$590.29</i> |
| EW NBD ONSITE 16704 | 97011-16704 | \$ 799.00 | 10% | <i>\$724.49</i> |
| EW NBD ONSITE -16704T | 97011-16704T | \$ 961.00 | 10% | <i>\$871.39</i> |
| EW NBD ONSITE 16705 | 97011-16705 | \$ 691.00 | 10% | <i>\$626.56</i> |
| EW NBD ONSITE -16705T | 97011-16705T | \$ 826.00 | 10% | <i>\$748.98</i> |
| EW NBD ONSITE 16706 | 97011-16706 | \$ 1,049.00 | 10% | <i>\$951.18</i> |
| EW NBD ONSITE -16706T | 97011-16706T | \$ 1,274.00 | 10% | <i>\$1,155.20</i> |
| EW NBD ONSITE 16710 | 97011-16710 | \$ 214.00 | 10% | <i>\$194.04</i> |
| EW NBD ONSITE 16710T | 97011-16710T | \$ 254.00 | 10% | <i>\$230.31</i> |
| EW NBD ONSITE 16711 | 97011-16711 | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW NBD ONSITE 16711T | 97011-16711T | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW NBD ONSITE 16712 | 97011-16712 | \$ 121.00 | 10% | <i>\$109.72</i> |
| EW NBD ONSITE 16712T | 97011-16712T | \$ 140.00 | 10% | <i>\$126.95</i> |
| EW NBD ONSITE 16713 | 97011-16713 | \$ 53.00 | 10% | <i>\$48.06</i> |
| EW NBD ONSITE 16713T | 97011-16713T | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD ONSITE 16715 | 97011-16715 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE 16715T | 97011-16715T | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW NBD ONSITE 16716 | 97011-16716 | \$ 359.00 | 10% | <i>\$325.52</i> |
| EW NBD ONSITE -16716T | 97011-16716T | \$ 446.00 | 10% | <i>\$404.41</i> |
| EW NBD ONSITE 16717 | 97011-16717 | \$ 554.00 | 10% | <i>\$502.34</i> |
| EW NBD ONSITE 16718 | 97011-16718 | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW NBD ONSITE -16718T | 97011-16718T | \$ 483.00 | 10% | <i>\$437.96</i> |
| EW NBD ONSITE 16719 | 97011-16719 | \$ 587.00 | 10% | <i>\$532.26</i> |
| EW NBD ONSITE -16719T | 97011-16719T | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW NBD ONSITE 16720 | 97011-16720 | \$ 884.00 | 10% | <i>\$801.57</i> |
| EW NBD ONSITE 16720T | 97011-16720T | \$ 1,027.00 | 10% | <i>\$931.23</i> |
| EW NBD ONSITE 16756 | 97011-16756 | \$ 646.00 | 10% | <i>\$585.76</i> |
| EW NBD ONSITE 16756T | 97011-16756T | \$ 765.00 | 10% | <i>\$693.66</i> |

| | | | | |
|-----------------------------|--------------|-------------|-----|------------|
| EW NBD ONSITE 16757 | 97011-16757 | \$ 609.00 | 10% | \$552.21 |
| EW NBD ONSITE 16757T | 97011-16757T | \$ 716.00 | 10% | \$649.23 |
| EW NBD ONSITE 16790 | 97011-16790 | \$ 1,427.00 | 10% | \$1,293.93 |
| EW NBD ONSITE 16791 | 97011-16791 | \$ 1,839.00 | 10% | \$1,667.51 |
| EW NBD ONSITE 16801 | 97011-16801 | \$ 185.00 | 10% | \$167.75 |
| EW NBD ONSITE 16802 | 97011-16802 | \$ 210.00 | 10% | \$190.42 |
| EW NBD ONSITE 16803 | 97011-16803 | \$ 224.00 | 10% | \$203.11 |
| EW NBD ONSITE 16804 | 97011-16804 | \$ 279.00 | 10% | \$252.98 |
| EW NBD ONSITE 16805 | 97011-16805 | \$ 55.00 | 10% | \$49.87 |
| EW NBD ONSITE 16806 | 97011-16806 | \$ 41.00 | 10% | \$37.18 |
| EW NBD ONSITE Summit 17101 | 97011-17101 | \$ 2,702.00 | 10% | \$2,450.04 |
| EW NBD ONSITE 17101T | 97011-17101T | \$ 3,463.00 | 10% | \$3,140.08 |
| EW NBD ONSITE Summit 17102 | 97011-17102 | \$ 2,702.00 | 10% | \$2,450.04 |
| EW NBD ONSITE 17102T | 97011-17102T | \$ 3,463.00 | 10% | \$3,140.08 |
| EW NBD ONSITE Summit 17103 | 97011-17103 | \$ 1,888.00 | 10% | \$1,711.94 |
| EW NBD ONSITE Summit 17103C | 97011-17103C | \$ 1,832.00 | 10% | \$1,661.17 |
| EW NBD ONSITE 17103T | 97011-17103T | \$ 2,415.00 | 10% | \$2,189.80 |
| EW NBD ONSITE Summit 17104 | 97011-17104 | \$ 1,888.00 | 10% | \$1,711.94 |
| EW NBD ONSITE 17104T | 97011-17104T | \$ 2,415.00 | 10% | \$2,189.80 |
| EW NBD ONSITE Summit 17121 | 97011-17121 | \$ 537.00 | 10% | \$486.92 |
| EW NBD ONSITE Summit 17122 | 97011-17122 | \$ 335.00 | 10% | \$303.76 |
| EW NBD ONSITE -17200 | 97011-17200 | \$ 4,260.00 | 10% | \$3,862.76 |
| EW NBD ONSITE 17200T | 97011-17200T | \$ 4,867.00 | 10% | \$4,413.15 |
| EW NBD ONSITE Summit 17201 | 97011-17201 | \$ 4,260.00 | 10% | \$3,862.76 |
| EW NBD ONSITE 17201T | 97011-17201T | \$ 4,867.00 | 10% | \$4,413.15 |
| EW NBD ONSITE Summit 17202 | 97011-17202 | \$ 4,260.00 | 10% | \$3,862.76 |
| EW NBD ONSITE 17202T | 97011-17202T | \$ 4,867.00 | 10% | \$4,413.15 |
| EW NBD ONSITE Summit 17203 | 97011-17203 | \$ 4,329.00 | 10% | \$3,925.32 |
| EW NBD ONSITE 17203T | 97011-17203T | \$ 4,946.00 | 10% | \$4,484.79 |
| EW NBD ONSITE Summit 17204 | 97011-17204 | \$ 4,329.00 | 10% | \$3,925.32 |
| EW NBD ONSITE 17204T | 97011-17204T | \$ 4,946.00 | 10% | \$4,484.79 |

| | | | | |
|----------------------------|-----------------|-------------|-----|------------|
| EW NBD ONSITE Summit 17205 | 97011-17205 | \$ 4,292.00 | 10% | \$3,891.77 |
| EW NBD ONSITE 17205T | 97011-17205T | \$ 4,912.00 | 10% | \$4,453.96 |
| EW NBD ONSITE Summit 17206 | 97011-17206 | \$ 4,292.00 | 10% | \$3,891.77 |
| EW NBD ONSITE 17206T | 97011-17206T | \$ 4,912.00 | 10% | \$4,453.96 |
| EW NBD ONSITE 17300 | 97011-17300 | \$ 2,815.00 | 10% | \$2,552.50 |
| EW NBD ONSITE 17310 | 97011-17310 | \$ 2,550.00 | 10% | \$2,312.21 |
| EW NBD ONSITE -17310T | 97011-17310T | \$ 3,078.00 | 10% | \$2,790.98 |
| EW NBD ONSITE 17350 | 97011-17350 | \$ 2,573.00 | 10% | \$2,333.07 |
| EW NBD ONSITE 17360 | 97011-17360 | \$ 3,172.00 | 10% | \$2,876.21 |
| EW NBD ONSITE 17401 | 97011-17401 | \$ 401.00 | 10% | \$363.61 |
| EW NBD ONSITE 17401G | 97011-17401G | \$ 463.00 | 10% | \$419.83 |
| EW NBD ONSITE 17401T | 97011-17401T | \$ 444.00 | 10% | \$402.60 |
| EW NBD ONSITE 17402 | 97011-17402 | \$ 569.00 | 10% | \$515.94 |
| EW NBD ONSITE 17402G | 97011-17402G | \$ 627.00 | 10% | \$568.53 |
| EW NBD ONSITE 17402T | 97011-17402T | \$ 597.00 | 10% | \$541.33 |
| EW NBD ONSITE 17403 | 97011-17403 | \$ 606.00 | 10% | \$549.49 |
| EW NBD ONSITE 17404 | 97011-17404 | \$ 291.00 | 10% | \$263.86 |
| EW NBD ONSITE 17405 | 97011-17405 | \$ 373.00 | 10% | \$338.22 |
| EW NBD ONSITE 17700 | 97011-17700 | \$ 4,994.00 | 10% | \$4,528.31 |
| EW NBD ONSITE 17701 | 97011-17701 | \$ 4,374.00 | 10% | \$3,966.12 |
| EW NBD ONSITE 17702 | 97011-17702 | \$ 4,374.00 | 10% | \$3,966.12 |
| EW NBD ONSITE 17703 | 97011-17703 | \$ 4,793.00 | 10% | \$4,346.05 |
| EW NBD ONSITE 17704 | 97011-17704 | \$ 4,793.00 | 10% | \$4,346.05 |
| EW NBD ONSITE 17705 | 97011-17705 | \$ 4,410.00 | 10% | \$3,998.77 |
| EW NBD ONSITE 17706 | 97011-17706 | \$ 4,410.00 | 10% | \$3,998.77 |
| EW NBD ONSITE 17800 | 97011-17800 | \$ 5,001.00 | 10% | \$4,534.66 |
| EW NBD ONSITE 17810 | 97011-17810 | \$ 4,002.00 | 10% | \$3,628.81 |
| EW NBD ONSITE 18101 | 97011-18101 | \$ 251.00 | 10% | \$227.59 |
| EW NBD ONSITE 18102 | 97011-18102 | \$ 325.00 | 10% | \$294.69 |
| EW NBD ONSITE 18103 | 97011-18103 | \$ 358.00 | 10% | \$324.62 |
| EW NBD ONSITE 18104 | 97011-18104 | \$ 510.00 | 10% | \$462.44 |
| EW NBD ONSITE 18104-6PK | 97011-18104-6PK | \$ 2,964.00 | 10% | \$2,687.61 |
| EW NBD ONSITE 18202 | 97011-18202 | \$ 190.00 | 10% | \$172.28 |
| EW NBD ONSITE 30135 | 97011-30135 | \$ 683.00 | 10% | \$619.31 |
| EW NBD ONSITE 30136 | 97011-30136 | \$ 5,135.00 | 10% | \$4,656.16 |
| EW NBD ONSITE 30137 | 97011-30137 | \$ 981.00 | 10% | \$889.52 |
| EW NBD ONSITE 30138 | 97011-30138 | \$ 4,529.00 | 10% | \$4,106.67 |
| EW NBD ONSITE 30139 | 97011-30139 | \$ 8,281.00 | 10% | \$7,508.80 |
| EW NBD ONSITE 30912 | 97011-30912 | \$ 87.00 | 10% | \$78.89 |

| | | | | |
|---------------------|-------------|-----------|-----|----------|
| EW NBD ONSITE 30913 | 97011-30913 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE 31012 | 97011-31012 | \$ 107.00 | 10% | \$97.02 |
| EW NBD ONSITE 31013 | 97011-31013 | \$ 107.00 | 10% | \$97.02 |
| EW NBD ONSITE 31014 | 97011-31014 | \$ 107.00 | 10% | \$97.02 |
| EW NBD ONSITE 31015 | 97011-31015 | \$ 107.00 | 10% | \$97.02 |
| EW NBD ONSITE 31016 | 97011-31016 | \$ 285.00 | 10% | \$258.42 |
| EW NBD ONSITE 31017 | 97011-31017 | \$ 285.00 | 10% | \$258.42 |
| EW NBD ONSITE 31018 | 97011-31018 | \$ 322.00 | 10% | \$291.97 |
| EW NBD ONSITE 31019 | 97011-31019 | \$ 322.00 | 10% | \$291.97 |
| EW NBD ONSITE 31025 | 97011-31025 | \$ 51.00 | 10% | \$46.24 |
| EW NBD ONSITE 31026 | 97011-31026 | \$ 51.00 | 10% | \$46.24 |
| EW NBD ONSITE 31028 | 97011-31028 | \$ 59.00 | 10% | \$53.50 |
| EW NBD ONSITE 31029 | 97011-31029 | \$ 68.00 | 10% | \$61.66 |
| EW NBD ONSITE 31031 | 97011-31031 | \$ 75.00 | 10% | \$68.01 |
| EW NBD ONSITE 31032 | 97011-31032 | \$ 75.00 | 10% | \$68.01 |
| EW NBD ONSITE 31034 | 97011-31034 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE 31035 | 97011-31035 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE 31050 | 97011-31050 | \$ 117.00 | 10% | \$106.09 |
| EW NBD ONSITE 31051 | 97011-31051 | \$ 117.00 | 10% | \$106.09 |
| EW NBD ONSITE 31055 | 97011-31055 | \$ 117.00 | 10% | \$106.09 |
| EW NBD ONSITE 31056 | 97011-31056 | \$ 117.00 | 10% | \$106.09 |
| EW NBD ONSITE 37101 | 97011-37101 | \$ 50.00 | 10% | \$45.34 |
| EW NBD ONSITE 37102 | 97011-37102 | \$ 50.00 | 10% | \$45.34 |
| EW NBD ONSITE 37103 | 97011-37103 | \$ 50.00 | 10% | \$45.34 |
| EW NBD ONSITE 37111 | 97011-37111 | \$ 60.00 | 10% | \$54.41 |
| EW NBD ONSITE 37112 | 97011-37112 | \$ 60.00 | 10% | \$54.41 |
| EW NBD ONSITE 37113 | 97011-37113 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE 37114 | 97011-37114 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE 37115 | 97011-37115 | \$ 60.00 | 10% | \$54.41 |
| EW NBD ONSITE 37116 | 97011-37116 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE 37117 | 97011-37117 | \$ 60.00 | 10% | \$54.41 |
| EW NBD ONSITE 37121 | 97011-37121 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 37122 | 97011-37122 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 37123 | 97011-37123 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 37124 | 97011-37124 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 37125 | 97011-37125 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 37126 | 97011-37126 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 37129 | 97011-37129 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 37130 | 97011-37130 | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 39031 | 97011-39031 | \$ 165.00 | 10% | \$149.61 |
| EW NBD ONSITE 39032 | 97011-39032 | \$ 175.00 | 10% | \$158.68 |
| EW NBD ONSITE 39033 | 97011-39033 | \$ 165.00 | 10% | \$149.61 |

| | | | | |
|-------------------------------|-----------------------|-------------|-----|-------------------|
| EW NBD ONSITE 39034 | 97011-39034 | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW NBD ONSITE 39035 | 97011-39035 | \$ 773.00 | 10% | <i>\$700.92</i> |
| EW NBD ONSITE 39036 | 97011-39036 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW NBD ONSITE 39037 | 97011-39037 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW NBD ONSITE 39038 | 97011-39038 | \$ 197.00 | 10% | <i>\$178.63</i> |
| EW NBD ONSITE 39039 | 97011-39039 | \$ 197.00 | 10% | <i>\$178.63</i> |
| EW NBD ONSITE 39505 | 97011-39505 | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW NBD ONSITE 4120-24MW-4Y | 97011-4120-24MW-4Y | \$ 666.00 | 10% | <i>\$603.90</i> |
| EW NBD ONSITE 4120-48MW-4Y | 97011-4120-48MW-4Y | \$ 888.00 | 10% | <i>\$805.19</i> |
| EW NBD ONSITE 4120C-1 | 97011-4120C-1 | \$ 6,282.00 | 10% | <i>\$5,696.20</i> |
| EW NBD ONSITE 41216 | 97011-41216 | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW NBD ONSITE 4220-12P-4X | 97011-4220-12P-4X | \$ 202.00 | 10% | <i>\$183.16</i> |
| EW NBD ONSITE 4220-12T-4X | 97011-4220-12T-4X | \$ 148.00 | 10% | <i>\$134.20</i> |
| EW NBD ONSITE 4220-24P-4X | 97011-4220-24P-4X | \$ 270.00 | 10% | <i>\$244.82</i> |
| EW NBD ONSITE 4220-24T-4X | 97011-4220-24T-4X | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW NBD ONSITE 4220-48P-4X | 97011-4220-48P-4X | \$ 405.00 | 10% | <i>\$367.23</i> |
| EW NBD ONSITE 4220-48T-4X | 97011-4220-48T-4X | \$ 303.00 | 10% | <i>\$274.75</i> |
| EW NBD ONSITE 4220-4MW-20P-4X | 97011-4220-4MW-20P-4X | \$ 371.00 | 10% | <i>\$336.40</i> |
| EW NBD ONSITE 4220-4MW-8P-4X | 97011-4220-4MW-8P-4X | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW NBD ONSITE 4220-8MW-40P-4X | 97011-4220-8MW-40P-4X | \$ 540.00 | 10% | <i>\$489.65</i> |
| EW NBD ONSITE 4220-8X | 97011-4220-8X | \$ 283.00 | 10% | <i>\$256.61</i> |
| EW NBD ONSITE 48038 | 97011-48038 | \$ 2,852.00 | 10% | <i>\$2,586.05</i> |
| EW NBD ONSITE 48039 | 97011-48039 | \$ 2,852.00 | 10% | <i>\$2,586.05</i> |
| EW NBD On-site-48040 | 97011-48040 | \$ 2,756.00 | 10% | <i>\$2,499.00</i> |
| EW NBD ONSITE BD X 48041 | 97011-48041 | \$ 2,852.00 | 10% | <i>\$2,586.05</i> |
| EW NBD ONSITE BD X 48046 | 97011-48046 | \$ 3,746.00 | 10% | <i>\$3,396.69</i> |
| EW NBD ONSITE 48047 | 97011-48047 | \$ 9,983.00 | 10% | <i>\$9,052.09</i> |
| EW NBD ONSITE BD X 48051 | 97011-48051 | \$ 6,865.00 | 10% | <i>\$6,224.84</i> |
| EW NBD ONSITE 48061 | 97011-48061 | \$ 8,025.00 | 10% | <i>\$7,276.67</i> |

| | | | | |
|-----------------------------------|---------------------------|--------------|-----|--------------------|
| EW NBD ONSITE 48062 | 97011-48062 | \$ 12,835.00 | 10% | <i>\$11,638.14</i> |
| EW NBD ONSITE 5320-16P-4XE | 97011-5320-16P-4XE | \$ 288.00 | 10% | <i>\$261.14</i> |
| EW NBD ONSITE 5320-16P-4XE-DC | 97011-5320-16P-4XE-DC | \$ 346.00 | 10% | <i>\$313.74</i> |
| EW NBD ONSITE 5320-24P-8XE | 97011-5320-24P-8XE | \$ 317.00 | 10% | <i>\$287.44</i> |
| EW NBD ONSITE 5320-24T-24S-4XE-XT | 97011-5320-24T-24S-4XE-XT | \$ 438.00 | 10% | <i>\$397.16</i> |
| EW NBD ONSITE 5320-24T-4X-XT | 97011-5320-24T-4X-XT | \$ 236.00 | 10% | <i>\$213.99</i> |
| EW NBD ONSITE 5320-24T-8XE | 97011-5320-24T-8XE | \$ 225.00 | 10% | <i>\$204.02</i> |
| EW NBD ONSITE 5320-48P-8XE | 97011-5320-48P-8XE | \$ 531.00 | 10% | <i>\$481.48</i> |
| EW NBD ONSITE 5320-48T-8XE | 97011-5320-48T-8XE | \$ 360.00 | 10% | <i>\$326.43</i> |
| EW NBD ONSITE 5420F-16MW-32P-4XE | 97011-5420F-16MW-32P-4XE | \$ 921.00 | 10% | <i>\$835.12</i> |
| EW NBD ONSITE 5420F-16W-32P-4XE | 97011-5420F-16W-32P-4XE | \$ 832.00 | 10% | <i>\$754.42</i> |
| EW NBD ONSITE 5420F-24P-4XE | 97011-5420F-24P-4XE | \$ 381.00 | 10% | <i>\$345.47</i> |
| EW NBD ONSITE 5420F-24S-4XE | 97011-5420F-24S-4XE | \$ 439.00 | 10% | <i>\$398.06</i> |
| EW NBD ONSITE 5420F-24T-4XE | 97011-5420F-24T-4XE | \$ 314.00 | 10% | <i>\$284.72</i> |
| EW NBD ONSITE 5420F-48P-4XE | 97011-5420F-48P-4XE | \$ 592.00 | 10% | <i>\$536.80</i> |
| EW NBD ONSITE 5420F-48P-4XL | 97011-5420F-48P-4XL | \$ 706.00 | 10% | <i>\$640.17</i> |
| EW NBD ONSITE 5420F-48T-4XE | 97011-5420F-48T-4XE | \$ 424.00 | 10% | <i>\$384.46</i> |
| EW NBD ONSITE 5420F-8W-16P-4XE | 97011-5420F-8W-16P-4XE | \$ 458.00 | 10% | <i>\$415.29</i> |
| EW NBD ONSITE 5420M-16MW-32P-4YE | 97011-5420M-16MW-32P-4YE | \$ 965.00 | 10% | <i>\$875.01</i> |
| EW NBD ONSITE 5420M-24T-4YE | 97011-5420M-24T-4YE | \$ 459.00 | 10% | <i>\$416.20</i> |

| | | | | |
|-----------------------------------|---------------------------|-------------|-----|------------|
| EW NBD ONSITE 5420M-24W-4YE | 97011-5420M-24W-4YE | \$ 429.00 | 10% | \$389.00 |
| EW NBD ONSITE 5420M-48T-4YE | 97011-5420M-48T-4YE | \$ 627.00 | 10% | \$568.53 |
| EW NBD ONSITE 5420M-48W-4YE | 97011-5420M-48W-4YE | \$ 744.00 | 10% | \$674.62 |
| EW NBD ONSITE 5520-12MW-36W | 97011-5520-12MW-36W | \$ 1,018.00 | 10% | \$923.07 |
| EW NBD ONSITE 5520-24T | 97011-5520-24T | \$ 399.00 | 10% | \$361.79 |
| EW NBD ONSITE 5520-24T-ACDC-BASE | 97011-5520-24T-ACDC-BASE | \$ 399.00 | 10% | \$361.79 |
| EW NBD ONSITE 5520-24T-BASE | 97011-5520-24T-BASE | \$ 399.00 | 10% | \$361.79 |
| EW NBD ONSITE 5520-24W | 97011-5520-24W | \$ 606.00 | 10% | \$549.49 |
| EW NBD ONSITE 5520-24X | 97011-5520-24X | \$ 1,145.00 | 10% | \$1,038.23 |
| EW NBD ONSITE 5520-24X-ACDC-BASE | 97011-5520-24X-ACDC-BASE | \$ 1,145.00 | 10% | \$1,038.23 |
| EW NBD ONSITE 5520-24X-BASE | 97011-5520-24X-BASE | \$ 1,145.00 | 10% | \$1,038.23 |
| EW NBD ONSITE 5520-48SE | 97011-5520-48SE | \$ 1,180.00 | 10% | \$1,069.97 |
| EW NBD ONSITE 5520-48SE-ACDC-BASE | 97011-5520-48SE-ACDC-BASE | \$ 1,180.00 | 10% | \$1,069.97 |
| EW NBD ONSITE 5520-48SE-BASE | 97011-5520-48SE-BASE | \$ 1,180.00 | 10% | \$1,069.97 |
| EW NBD ONSITE 5520-48T | 97011-5520-48T | \$ 682.00 | 10% | \$618.40 |
| EW NBD ONSITE 5520-48T-ACDC-BASE | 97011-5520-48T-ACDC-BASE | \$ 682.00 | 10% | \$618.40 |
| EW NBD ONSITE 5520-48T-BASE | 97011-5520-48T-BASE | \$ 682.00 | 10% | \$618.40 |
| EW NBD ONSITE 5520-48W | 97011-5520-48W | \$ 832.00 | 10% | \$754.42 |
| EW NBD ONSITE 5720-24MW | 97011-5720-24MW | \$ 1,275.00 | 10% | \$1,156.11 |

| | | | | |
|----------------------------------|--------------------------|-------------|-----|-------------------|
| EW NBD ONSITE 5720-24MXW | 97011-5720-24MXW | \$ 1,725.00 | 10% | <i>\$1,564.14</i> |
| EW NBD ONSITE 5720-48MW | 97011-5720-48MW | \$ 1,500.00 | 10% | <i>\$1,360.13</i> |
| EW NBD ONSITE 5720-48MXW | 97011-5720-48MXW | \$ 2,175.00 | 10% | <i>\$1,972.18</i> |
| EW NBD ONSITE 7520-48XT-6C | 97011-7520-48XT-6C | \$ 2,383.00 | 10% | <i>\$2,160.79</i> |
| EW NBD ONSIT 7520-48XT-6C-AC-F | 97011-7520-48XT-6C-AC-F | \$ 2,383.00 | 10% | <i>\$2,160.79</i> |
| EW NBD ONSITE 7520-48XT-6C-AC-R | 97011-7520-48XT-6C-AC-R | \$ 2,383.00 | 10% | <i>\$2,160.79</i> |
| EW NBD ONSITE 7520-48Y-8C | 97011-7520-48Y-8C | \$ 2,218.00 | 10% | <i>\$2,011.17</i> |
| EW NBD ONSITE 7520-48Y-8C-AC-F | 97011-7520-48Y-8C-AC-F | \$ 2,218.00 | 10% | <i>\$2,011.17</i> |
| EW NBD ONSITE 7520-48Y-8C-AC-R | 97011-7520-48Y-8C-AC-R | \$ 2,218.00 | 10% | <i>\$2,011.17</i> |
| EW NBD ONSITE 7520-48YE-8CE | 97011-7520-48YE-8CE | \$ 2,583.00 | 10% | <i>\$2,342.14</i> |
| EW NBD ONSITE 7520-48YE-8CE-AC-F | 97011-7520-48YE-8CE-AC-F | \$ 2,583.00 | 10% | <i>\$2,342.14</i> |
| EW NBD ONSITE 7520-48YE-8CE-AC-R | 97011-7520-48YE-8CE-AC-R | \$ 2,583.00 | 10% | <i>\$2,342.14</i> |
| EW NBD ONSITE 7720-32C | 97011-7720-32C | \$ 2,769.00 | 10% | <i>\$2,510.79</i> |
| EW NBD ONSITE 7720-32C-AC-F | 97011-7720-32C-AC-F | \$ 2,769.00 | 10% | <i>\$2,510.79</i> |
| EW NBD ONSITE 7720-32C-AC-R | 97011-7720-32C-AC-R | \$ 2,769.00 | 10% | <i>\$2,510.79</i> |
| EW NBD ONSITE 8520-48XT-6C | 97011-8520-48XT-6C | \$ 2,554.00 | 10% | <i>\$2,315.84</i> |
| EW NBD ONSITE 8520-48XT-6C-AC-F | 97011-8520-48XT-6C-AC-F | \$ 2,554.00 | 10% | <i>\$2,315.84</i> |
| EW NBD ONSITE 8520-48XT-6C-AC-R | 97011-8520-48XT-6C-AC-R | \$ 2,554.00 | 10% | <i>\$2,315.84</i> |

| | | | | |
|---------------------------------|-------------------------|--------------|-----|-------------|
| EW NBD ONSITE 8520-48XT-6C-DC-F | 97011-8520-48XT-6C-DC-F | \$ 2,554.00 | 10% | \$2,315.84 |
| EW NBD ONSITE 8520-48XT-6C-DC-R | 97011-8520-48XT-6C-DC-R | \$ 2,554.00 | 10% | \$2,315.84 |
| EW NBD ONSITE 8520-48Y-8C | 97011-8520-48Y-8C | \$ 2,594.00 | 10% | \$2,352.11 |
| EW NBD ONSITE 8520-48Y-8C-AC-F | 97011-8520-48Y-8C-AC-F | \$ 2,594.00 | 10% | \$2,352.11 |
| EW NBD ONSITE 8520-48Y-8C-AC-R | 97011-8520-48Y-8C-AC-R | \$ 2,594.00 | 10% | \$2,352.11 |
| EW NBD ONSITE 8520-48Y-8C-DC-F | 97011-8520-48Y-8C-DC-F | \$ 2,594.00 | 10% | \$2,352.11 |
| EW NBD ONSITE 8520-48Y-8C-DC-R | 97011-8520-48Y-8C-DC-R | \$ 2,594.00 | 10% | \$2,352.11 |
| EW NBD ONSITE 86100 | 97011-86100 | \$ 5,201.00 | 10% | \$4,716.01 |
| EW NBD ONSITE 86101 | 97011-86101 | \$ 7,144.00 | 10% | \$6,477.82 |
| EW NBD ONSITE 87100 | 97011-87100 | \$ 3,225.00 | 10% | \$2,924.27 |
| EW NBD ONSITE 87101 | 97011-87101 | \$ 4,961.00 | 10% | \$4,498.39 |
| EW NBD ONSITE 8720-32C | 97011-8720-32C | \$ 2,981.00 | 10% | \$2,703.02 |
| EW NBD ONSITE 8720-32C-AC-F | 97011-8720-32C-AC-F | \$ 2,981.00 | 10% | \$2,703.02 |
| EW NBD ONSITE 8720-32C-AC-R | 97011-8720-32C-AC-R | \$ 2,981.00 | 10% | \$2,703.02 |
| EW NBD ONSITE 8720-32C-DC-F | 97011-8720-32C-DC-F | \$ 2,981.00 | 10% | \$2,703.02 |
| EW NBD ONSITE 8720-32C-DC-R | 97011-8720-32C-DC-R | \$ 2,981.00 | 10% | \$2,703.02 |
| EW NBD ONSITE 8806 | 97011-8806 | \$ 1,786.00 | 10% | \$1,619.46 |
| EW NBD ONSITE ASPEN | 97011-8810 | \$ 4,727.00 | 10% | \$4,286.21 |
| EW NBD ONSITE 88100 | 97011-88100 | \$ 5,863.00 | 10% | \$5,316.28 |
| EW NBD ONSITE 8820-40C | 97011-8820-40C | \$ 11,306.00 | 10% | \$10,251.72 |
| EW NBD ONSITE 8820-40C-AC-F | 97011-8820-40C-AC-F | \$ 11,306.00 | 10% | \$10,251.72 |
| EW NBD ONSITE 8820-40C-AC-R | 97011-8820-40C-AC-R | \$ 11,306.00 | 10% | \$10,251.72 |
| EW NBD ONSITE 8820-40C-DC-F | 97011-8820-40C-DC-F | \$ 11,306.00 | 10% | \$10,251.72 |

| | | | | |
|---------------------------------|-------------------------|--------------|-----|--------------------|
| EW NBD ONSITE 8820-40C-DC-R | 97011-8820-40C-DC-R | \$ 11,306.00 | 10% | <i>\$10,251.72</i> |
| EW NBD ONSITE 8820-80C | 97011-8820-80C | \$ 20,515.00 | 10% | <i>\$18,601.98</i> |
| EW NBD ONSITE 8820-80C-AC-F | 97011-8820-80C-AC-F | \$ 20,515.00 | 10% | <i>\$18,601.98</i> |
| EW NBD ONSITE 8820-80C-AC-R | 97011-8820-80C-AC-R | \$ 20,515.00 | 10% | <i>\$18,601.98</i> |
| EW NBD ONSITE 8820-80C-DC-F | 97011-8820-80C-DC-F | \$ 20,515.00 | 10% | <i>\$18,601.98</i> |
| EW NBD ONSITE 8820-80C-DC-R | 97011-8820-80C-DC-R | \$ 20,515.00 | 10% | <i>\$18,601.98</i> |
| EW NBD ONSITE 9920-16C | 97011-9920-16C | \$ 9,217.00 | 10% | <i>\$8,357.51</i> |
| EW NBD ONSITE 9920-4D | 97011-9920-4D | \$ 9,217.00 | 10% | <i>\$8,357.51</i> |
| EW NBD ONSITE 9920-NPB-8 | 97011-9920-NPB-8 | \$ 15,349.00 | 10% | <i>\$13,917.71</i> |
| EW NBD ONSITE | 97011-A10148 | \$ 2,919.00 | 10% | <i>\$2,646.80</i> |
| EW NBD ONSITE | 97011-A10149 | \$ 5,566.00 | 10% | <i>\$5,046.97</i> |
| EW NBD ONSITE | 97011-A10152 | \$ 5,566.00 | 10% | <i>\$5,046.97</i> |
| EW NBD ONSITE | 97011-A10154 | \$ 16,973.00 | 10% | <i>\$15,390.27</i> |
| EW NBD ONSITE | 97011-A10155 | \$ 6,006.00 | 10% | <i>\$5,445.94</i> |
| EW NBD ONSITE | 97011-A10157 | \$ 10,599.00 | 10% | <i>\$9,610.64</i> |
| EW NBD ONSITE 10175 | 97011-A10175 | \$ 6,552.00 | 10% | <i>\$5,941.03</i> |
| EW NBD ONSITE A10176 | 97011-A10176 | \$ 9,827.00 | 10% | <i>\$8,910.63</i> |
| EW NBD ONSITE AH-AP-1130-AC-CE | 97011-AH-AP-1130-AC-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AH-AP-1130-AC-FCC | 97011-AH-AP-1130-AC-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AH-AP-1130-AC-W | 97011-AH-AP-1130-AC-W | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AH-AP-122-AC-CAN | 97011-AH-AP-122-AC-CAN | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-122-AC-CE | 97011-AH-AP-122-AC-CE | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-122-AC-FCC | 97011-AH-AP-122-AC-FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-122-AC-W | 97011-AH-AP-122-AC-W | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-130-AC-CE | 97011-AH-AP-130-AC-CE | \$ 71.00 | 10% | <i>\$64.38</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|-----|----------------|
| EW NBD ONSITE AH-AP-130-AC-FCC | 97011-AH-AP-130-AC-FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-130-AC-W | 97011-AH-AP-130-AC-W | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-150W-AC-CAN | 97011-AH-AP-150W-AC-CAN | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-150W-AC-CE | 97011-AH-AP-150W-AC-CE | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-150W-AC-FCC | 97011-AH-AP-150W-AC-FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-150W-AC-W | 97011-AH-AP-150W-AC-W | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-230-AC-CE | 97011-AH-AP-230-AC-CE | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-230-AC-FCC | 97011-AH-AP-230-AC-FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-230-AC-W | 97011-AH-AP-230-AC-W | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-250-AC-CAN | 97011-AH-AP-250-AC-CAN | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-250-AC-CE | 97011-AH-AP-250-AC-CE | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-250-AC-FCC | 97011-AH-AP-250-AC-FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-250-AC-W | 97011-AH-AP-250-AC-W | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-AP-630-AX-CAN | 97011-AH-AP-630-AX-CAN | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW NBD ONSITE AH-AP-630-AX-CE | 97011-AH-AP-630-AX-CE | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW NBD ONSITE AH-AP-630-AX-FCC | 97011-AH-AP-630-AX-FCC | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW NBD ONSITE AH-AP-630-AX-W | 97011-AH-AP-630-AX-W | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW NBD ONSITE AH-AP-650-AX-CAN | 97011-AH-AP-650-AX-CAN | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD ONSITE AH-AP-650-AX-CE | 97011-AH-AP-650-AX-CE | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD ONSITE AH-AP-650-AX-FCC | 97011-AH-AP-650-AX-FCC | \$ 108.00 | 10% | <i>\$97.93</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|-----|----------------|
| EW NBD ONSITE AH-AP-650-AX-W | 97011-AH-AP-650-AX-W | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD ONSITE AH-AP-650X-AX-CAN | 97011-AH-AP-650X-AX-CAN | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD ONSITE AH-AP-650X-AX-CE | 97011-AH-AP-650X-AX-CE | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD ONSITE AH-AP-650X-AX-FCC | 97011-AH-AP-650X-AX-FCC | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD ONSITE AH-AP-650X-AX-W | 97011-AH-AP-650X-AX-W | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW NBD ONSITE AH-ATOM-CAN | 97011-AH-ATOM-CAN | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW NBD ONSITE AH-ATOM-CE-EU | 97011-AH-ATOM-CE-EU | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AH-ATOM-CE-UK | 97011-AH-ATOM-CE-UK | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AH-ATOM-FCC | 97011-AH-ATOM-FCC | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW NBD ONSITE AH-ATOM-W | 97011-AH-ATOM-W | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW NBD ONSITE AH-ATOM-W-EU | 97011-AH-ATOM-W-EU | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AH-ATOM-W-UK | 97011-AH-ATOM-W-UK | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AH-SR-2208P-AU | 97011-AH-SR-2208P-AU | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-SR-2208P-EU | 97011-AH-SR-2208P-EU | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-SR-2208P-NA | 97011-AH-SR-2208P-NA | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-SR-2208P-UK | 97011-AH-SR-2208P-UK | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-SR-2224P-AU | 97011-AH-SR-2224P-AU | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AH-SR-2224P-EU | 97011-AH-SR-2224P-EU | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AH-SR-2224P-NA | 97011-AH-SR-2224P-NA | \$ 107.00 | 10% | <i>\$97.02</i> |

| | | | | |
|---------------------------------|-------------------------|-----------|-----|-----------------|
| EW NBD ONSITE AH-SR-2224P-UK | 97011-AH-SR-2224P-UK | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AH-SR-2324P-AU | 97011-AH-SR-2324P-AU | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW NBD ONSITE AH-SR-2324P-EU | 97011-AH-SR-2324P-EU | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW NBD ONSITE AH-SR-2324P-NA | 97011-AH-SR-2324P-NA | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW NBD ONSITE AH-SR-2324P-UK | 97011-AH-SR-2324P-UK | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW NBD ONSITE AH-SR-2348P-AU | 97011-AH-SR-2348P-AU | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW NBD ONSITE AH-SR-2348P-EU | 97011-AH-SR-2348P-EU | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW NBD ONSITE AH-SR-2348P-NA | 97011-AH-SR-2348P-NA | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW NBD ONSITE AH-SR-2348P-UK | 97011-AH-SR-2348P-UK | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW NBD ONSITE AH-XR200P-AU | 97011-AH-XR200P-AU | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-XR200P-EU | 97011-AH-XR200P-EU | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-XR200P-UK | 97011-AH-XR200P-UK | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-XR200P-US | 97011-AH-XR200P-US | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AH-XR600P | 97011-AH-XR600P | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD ONSITE AH-XR600P-AU | 97011-AH-XR600P-AU | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW NBD ONSITE AH-XR600P-EU | 97011-AH-XR600P-EU | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW NBD ONSITE AH-XR600P-KR | 97011-AH-XR600P-KR | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW NBD ONSITE AH-XR600P-UK | 97011-AH-XR600P-UK | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW NBD ONSITE AH-XR600P-US | 97011-AH-XR600P-US | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW NBD ONSITE AP-8533-68SB30-IL | 97011-AP-8533-68SB30-IL | \$ 135.00 | 10% | <i>\$122.41</i> |

| | | | | |
|----------------------------|--------------------|----------|-----|----------------|
| EW NBD ONSITE AP3000-IL | 97011-AP3000-IL | \$ 58.50 | 10% | <i>\$53.04</i> |
| EW NBD ONSITE AP3000-TN | 97011-AP3000-TN | \$ 58.50 | 10% | <i>\$53.04</i> |
| EW NBD ONSITE AP3000-WW | 97011-AP3000-WW | \$ 58.50 | 10% | <i>\$53.04</i> |
| EW NBD ONSITE AP3000X-WW | 97011-AP3000X-WW | \$ 74.75 | 10% | <i>\$67.78</i> |
| EW NBD ONSITE AP302W-CAN | 97011-AP302W-CAN | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW NBD ONSITE AP302W-EG | 97011-AP302W-EG | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW NBD ONSITE AP302W-FCC | 97011-AP302W-FCC | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW NBD ONSITE AP302W-WR | 97011-AP302W-WR | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD ONSITE AP305C-1-CAN | 97011-AP305C-1-CAN | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AP305C-1-EG | 97011-AP305C-1-EG | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AP305C-1-FCC | 97011-AP305C-1-FCC | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AP305C-1-IL | 97011-AP305C-1-IL | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AP305C-1-WR | 97011-AP305C-1-WR | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE AP305C-CAN | 97011-AP305C-CAN | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP305C-EG | 97011-AP305C-EG | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP305C-FCC | 97011-AP305C-FCC | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP305C-IL | 97011-AP305C-IL | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP305C-WR | 97011-AP305C-WR | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP305CX-CAN | 97011-AP305CX-CAN | \$ 76.00 | 10% | <i>\$68.91</i> |

| | | | | |
|---------------------------|-------------------|----------|-----|----------------|
| EW NBD ONSITE AP305CX-FCC | 97011-AP305CX-FCC | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP305CX-IL | 97011-AP305CX-IL | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP305CX-WR | 97011-AP305CX-WR | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW NBD ONSITE AP310e-1-WR | 97011-AP310e-1-WR | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE AP310e-CAN | 97011-AP310e-CAN | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP310e-FCC | 97011-AP310e-FCC | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP310e-IL | 97011-AP310e-IL | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP310e-WR | 97011-AP310e-WR | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP310i-1-WR | 97011-AP310i-1-WR | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE AP310i-CAN | 97011-AP310i-CAN | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP310i-FCC | 97011-AP310i-FCC | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP310i-IL | 97011-AP310i-IL | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP310i-WR | 97011-AP310i-WR | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW NBD ONSITE AP360e-CAN | 97011-AP360e-CAN | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW NBD ONSITE AP360e-FCC | 97011-AP360e-FCC | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW NBD ONSITE AP360e-IL | 97011-AP360e-IL | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW NBD ONSITE AP360e-WR | 97011-AP360e-WR | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW NBD ONSITE AP360i-CAN | 97011-AP360i-CAN | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW NBD ONSITE AP360i-FCC | 97011-AP360i-FCC | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW NBD ONSITE AP360i-WR | 97011-AP360i-WR | \$ 68.00 | 10% | <i>\$61.66</i> |

| | | | | |
|----------------------------|--------------------|----------|-----|----------------|
| EW NBD ONSITE AP4000-WW | 97011-AP4000-1-WW | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP4000-IL | 97011-AP4000-IL | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP4000-WW | 97011-AP4000-WW | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP410C-1-CAN | 97011-AP410C-1-CAN | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP410C-1-EG | 97011-AP410C-1-EG | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP410C-1-FCC | 97011-AP410C-1-FCC | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP410C-1-IL | 97011-AP410C-1-IL | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP410C-1-WR | 97011-AP410C-1-WR | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW NBD ONSITE AP410C-CAN | 97011-AP410C-CAN | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE AP410C-EG | 97011-AP410C-EG | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE AP410C-FCC | 97011-AP410C-FCC | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE AP410C-IL | 97011-AP410C-IL | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE AP410C-WR | 97011-AP410C-WR | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE AP410e-CAN | 97011-AP410e-CAN | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE AP410e-FCC | 97011-AP410e-FCC | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE AP410e-WR | 97011-AP410e-WR | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE AP410i-1-FCC | 97011-AP410i-1-FCC | \$ 80.00 | 10% | <i>\$72.54</i> |
| EW NBD ONSITE AP410i-1-WR | 97011-AP410i-1-WR | \$ 80.00 | 10% | <i>\$72.54</i> |
| EW NBD ONSITE AP410i-CAN | 97011-AP410i-CAN | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE AP410i-FCC | 97011-AP410i-FCC | \$ 84.00 | 10% | <i>\$76.17</i> |

| | | | | |
|-----------------------------|---------------------|-----------|-----|----------------|
| EW NBD ONSITE AP410i-IL | 97011-AP410i-IL | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE AP410i-WR | 97011-AP410i-WR | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE AP460C-CAN | 97011-AP460C-CAN | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460C-EG | 97011-AP460C-EG | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460C-FCC | 97011-AP460C-FCC | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460C-IL | 97011-AP460C-IL | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460C-WR | 97011-AP460C-WR | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460e-CAN | 97011-AP460e-CAN | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW NBD ONSITE AP460e-FCC | 97011-AP460e-FCC | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW NBD ONSITE AP460e-WR | 97011-AP460e-WR | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW NBD ONSITE AP460i-CAN | 97011-AP460i-CAN | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW NBD ONSITE AP460i-FCC | 97011-AP460i-FCC | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW NBD ONSITE AP460i-IL | 97011-AP460i-IL | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW NBD ONSITE AP460i-WR | 97011-AP460i-WR | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW NBD ONSITE AP460S12C-CAN | 97011-AP460S12C-CAN | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460S12C-FCC | 97011-AP460S12C-FCC | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460S12C-WR | 97011-AP460S12C-WR | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460S6C-CAN | 97011-AP460S6C-CAN | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP460S6C-FCC | 97011-AP460S6C-FCC | \$ 107.00 | 10% | <i>\$97.02</i> |

| | | | | |
|------------------------------|----------------------|-----------|-----|-----------------|
| EW NBD ONSITE AP460S6C-WR | 97011-AP460S6C-WR | \$ 107.00 | 10% | <i>\$97.02</i> |
| EW NBD ONSITE AP5010-IL | 97011-AP5010-IL | \$ 130.00 | 10% | <i>\$117.88</i> |
| EW NBD ONSITE AP5010-WW | 97011-AP5010-WW | \$ 130.00 | 10% | <i>\$117.88</i> |
| EW NBD ONSITE AP5020-WW | 97011-AP5020-WW | \$ 155.94 | 6% | <i>\$147.68</i> |
| EW NBD ONSITE AP5050D-WW | 97011-AP5050D-WW | \$ 310.00 | 10% | <i>\$281.09</i> |
| EW NBD ONSITE AP5050U-WW | 97011-AP5050U-WW | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW NBD ONSITE AP505i-FCC | 97011-AP505i-FCC | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW NBD ONSITE AP505i-FCC-TAA | 97011-AP505i-FCC-TAA | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW NBD ONSITE AP505i-WR | 97011-AP505i-WR | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW NBD ONSITE AP510C-CAN | 97011-AP510C-CAN | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510C-CE | 97011-AP510C-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510C-FCC | 97011-AP510C-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510C-W | 97011-AP510C-W | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510C-WW | 97011-AP510C-WW | \$ 121.00 | 10% | <i>\$109.72</i> |
| EW NBD ONSITE AP510CX-CAN | 97011-AP510CX-CAN | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510CX-CE | 97011-AP510CX-CE | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510CX-FCC | 97011-AP510CX-FCC | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510CX-W | 97011-AP510CX-W | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE AP510CX-WW | 97011-AP510CX-WW | \$ 121.00 | 10% | <i>\$109.72</i> |

| | | | | |
|------------------------------|----------------------|-------------|-----|-------------------|
| EW NBD ONSITE AP510e-FCC | 97011-AP510e-FCC | \$ 138.00 | 10% | <i>\$125.13</i> |
| EW NBD ONSITE AP510e-FCC-TAA | 97011-AP510e-FCC-TAA | \$ 138.00 | 10% | <i>\$125.13</i> |
| EW NBD ONSITE AP510e-WR | 97011-AP510e-WR | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE AP510i-1-FCC | 97011-AP510i-1-FCC | \$ 114.00 | 10% | <i>\$103.37</i> |
| EW NBD ONSITE AP510i-1-WR | 97011-AP510i-1-WR | \$ 114.00 | 10% | <i>\$103.37</i> |
| EW NBD ONSITE AP510i-FCC | 97011-AP510i-FCC | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW NBD ONSITE AP510i-FCC-TAA | 97011-AP510i-FCC-TAA | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW NBD ONSITE AP510i-WR | 97011-AP510i-WR | \$ 119.00 | 10% | <i>\$107.90</i> |
| EW NBD ONSITE AP560h-FCC | 97011-AP560h-FCC | \$ 301.00 | 10% | <i>\$272.93</i> |
| EW NBD ONSITE AP560h-WR | 97011-AP560h-WR | \$ 301.00 | 10% | <i>\$272.93</i> |
| EW NBD ONSITE AP560i-FCC | 97011-AP560i-FCC | \$ 219.00 | 10% | <i>\$198.58</i> |
| EW NBD ONSITE AP560i-WR | 97011-AP560i-WR | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW NBD ONSITE AP560m-FCC | 97011-AP560m-FCC | \$ 219.00 | 10% | <i>\$198.58</i> |
| EW NBD ONSITE AP560t-FCC | 97011-AP560t-FCC | \$ 301.00 | 10% | <i>\$272.93</i> |
| EW NBD ONSITE AP560u-FCC | 97011-AP560u-FCC | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE E2122 | 97011-E2122 | \$ 5,063.00 | 10% | <i>\$4,590.88</i> |
| EW NBD ONSITE E2122-1 | 97011-E2122-1 | \$ 4,799.00 | 10% | <i>\$4,351.49</i> |
| EW NBD ONSITE E3120-1 | 97011-E3120-1 | \$ 7,848.00 | 10% | <i>\$7,116.17</i> |
| EW NBD ONSITE E3125 | 97011-E3125 | \$ 8,472.00 | 10% | <i>\$7,681.99</i> |
| EW NBD ONSITE | 97011-H30078 | \$ 2,687.00 | 10% | <i>\$2,436.44</i> |
| EW NBD ONSITE | 97011-H30104 | \$ 2,485.00 | 10% | <i>\$2,253.27</i> |
| EW NBD ONSITE | 97011-H30105 | \$ 2,455.00 | 10% | <i>\$2,226.07</i> |
| EW NBD ONSITE | 97011-H30131 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW NBD ONSITE | 97011-H30132 | \$ 1,378.00 | 10% | <i>\$1,249.50</i> |
| EW NBD ONSITE | 97011-H30133 | \$ 3,620.00 | 10% | <i>\$3,282.44</i> |
| EW NBD ONSITE | 97011-H30134 | \$ 4,587.00 | 10% | <i>\$4,159.26</i> |
| EW NBD ONSITE | 97011-H30135 | \$ 3,692.00 | 10% | <i>\$3,347.72</i> |

| | | | | |
|---------------|--------------|-------------|-----|------------|
| EW NBD ONSITE | 97011-H30136 | \$ 4,587.00 | 10% | \$4,159.26 |
| EW NBD ONSITE | 97011-H30184 | \$ 62.00 | 10% | \$56.22 |
| EW NBD ONSITE | 97011-H30185 | \$ 325.00 | 10% | \$294.69 |
| EW NBD ONSITE | 97011-H30186 | \$ 165.00 | 10% | \$149.61 |
| EW NBD ONSITE | 97011-H30187 | \$ 67.00 | 10% | \$60.75 |
| EW NBD ONSITE | 97011-H30188 | \$ 165.00 | 10% | \$149.61 |
| EW NBD ONSITE | 97011-H30189 | \$ 165.00 | 10% | \$149.61 |
| EW NBD ONSITE | 97011-H30190 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30214 | \$ 177.00 | 10% | \$160.49 |
| EW NBD ONSITE | 97011-H30215 | \$ 177.00 | 10% | \$160.49 |
| EW NBD ONSITE | 97011-H30216 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30217 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30218 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30219 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30220 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30221 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30222 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30223 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30224 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30225 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30226 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30227 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30228 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30229 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30267 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30268 | \$ 347.00 | 10% | \$314.64 |
| EW NBD ONSITE | 97011-H30269 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30270 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30271 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30272 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30273 | \$ 763.00 | 10% | \$691.85 |
| EW NBD ONSITE | 97011-H30274 | \$ 763.00 | 10% | \$691.85 |
| EW NBD ONSITE | 97011-H30275 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30276 | \$ 558.00 | 10% | \$505.97 |
| EW NBD ONSITE | 97011-H30277 | \$ 763.00 | 10% | \$691.85 |
| EW NBD ONSITE | 97011-H30278 | \$ 837.00 | 10% | \$758.95 |
| EW NBD ONSITE | 97011-H30279 | \$ 763.00 | 10% | \$691.85 |
| EW NBD ONSITE | 97011-H30280 | \$ 763.00 | 10% | \$691.85 |
| EW NBD ONSITE | 97011-H30281 | \$ 763.00 | 10% | \$691.85 |
| EW NBD ONSITE | 97011-H30282 | \$ 763.00 | 10% | \$691.85 |
| EW NBD ONSITE | 97011-H30283 | \$ 507.00 | 10% | \$459.72 |
| EW NBD ONSITE | 97011-H30284 | \$ 558.00 | 10% | \$505.97 |

| | | | | |
|---------------|--------------|-------------|-----|------------|
| EW NBD ONSITE | 97011-H30293 | \$ 3,024.00 | 10% | \$2,742.01 |
| EW NBD ONSITE | 97011-H30296 | \$ 177.00 | 10% | \$160.49 |
| EW NBD ONSITE | 97011-H30297 | \$ 164.00 | 10% | \$148.71 |
| EW NBD ONSITE | 97011-H30298 | \$ 177.00 | 10% | \$160.49 |
| EW NBD ONSITE | 97011-H30299 | \$ 164.00 | 10% | \$148.71 |
| EW NBD ONSITE | 97011-H30381 | \$ 499.00 | 10% | \$452.47 |
| EW NBD ONSITE | 97011-H30384 | \$ 400.00 | 10% | \$362.70 |
| EW NBD ONSITE | 97011-H30391 | \$ 944.00 | 10% | \$855.97 |
| EW NBD ONSITE | 97011-H30392 | \$ 944.00 | 10% | \$855.97 |
| EW NBD ONSITE | 97011-H30393 | \$ 425.00 | 10% | \$385.37 |
| EW NBD ONSITE | 97011-H30394 | \$ 1,834.00 | 10% | \$1,662.98 |
| EW NBD ONSITE | 97011-H30395 | \$ 2,185.00 | 10% | \$1,981.25 |
| EW NBD ONSITE | 97011-H30396 | \$ 1,988.00 | 10% | \$1,802.62 |
| EW NBD ONSITE | 97011-H30397 | \$ 2,368.00 | 10% | \$2,147.18 |
| EW NBD ONSITE | 97011-H30398 | \$ 435.00 | 10% | \$394.44 |
| EW NBD ONSITE | 97011-H30400 | \$ 239.00 | 10% | \$216.71 |
| EW NBD ONSITE | 97011-H30401 | \$ 330.00 | 10% | \$299.23 |
| EW NBD ONSITE | 97011-H30402 | \$ 360.00 | 10% | \$326.43 |
| EW NBD ONSITE | 97011-H30403 | \$ 528.00 | 10% | \$478.76 |
| EW NBD ONSITE | 97011-H30434 | \$ 142.00 | 10% | \$128.76 |
| EW NBD ONSITE | 97011-H30480 | \$ 625.00 | 10% | \$566.72 |
| EW NBD ONSITE | 97011-H30495 | \$ 1,405.00 | 10% | \$1,273.98 |
| EW NBD ONSITE | 97011-H30496 | \$ 1,378.00 | 10% | \$1,249.50 |
| EW NBD ONSITE | 97011-H30497 | \$ 2,027.00 | 10% | \$1,837.98 |
| EW NBD ONSITE | 97011-H30498 | \$ 1,988.00 | 10% | \$1,802.62 |
| EW NBD ONSITE | 97011-H30499 | \$ 683.00 | 10% | \$619.31 |
| EW NBD ONSITE | 97011-H30501 | \$ 1,988.00 | 10% | \$1,802.62 |
| EW NBD ONSITE | 97011-H30502 | \$ 3,062.00 | 10% | \$2,776.47 |
| EW NBD ONSITE | 97011-H30503 | \$ 683.00 | 10% | \$619.31 |
| EW NBD ONSITE | 97011-H30505 | \$ 3,620.00 | 10% | \$3,282.44 |
| EW NBD ONSITE | 97011-H30506 | \$ 4,922.00 | 10% | \$4,463.02 |
| EW NBD ONSITE | 97011-H30509 | \$ 3,062.00 | 10% | \$2,776.47 |
| EW NBD ONSITE | 97011-H30510 | \$ 3,620.00 | 10% | \$3,282.44 |
| EW NBD ONSITE | 97011-H30511 | \$ 4,922.00 | 10% | \$4,463.02 |
| EW NBD ONSITE | 97011-H30512 | \$ 683.00 | 10% | \$619.31 |
| EW NBD ONSITE | 97011-H30513 | \$ 1,149.00 | 10% | \$1,041.86 |
| EW NBD ONSITE | 97011-H30525 | \$ 4,922.00 | 10% | \$4,463.02 |
| EW NBD ONSITE | 97011-H30526 | \$ 3,620.00 | 10% | \$3,282.44 |
| EW NBD ONSITE | 97011-H30528 | \$ 5,719.00 | 10% | \$5,185.70 |
| EW NBD ONSITE | 97011-H30531 | \$ 8,145.00 | 10% | \$7,385.48 |
| EW NBD ONSITE | 97011-H30532 | \$ 8,145.00 | 10% | \$7,385.48 |
| EW NBD ONSITE | 97011-H30534 | \$ 8,303.00 | 10% | \$7,528.75 |

| | | | | |
|-------------------------------|--------------|-------------|-----|------------|
| EW NBD ONSITE | 97011-H30535 | \$ 8,853.00 | 10% | \$8,027.46 |
| EW NBD ONSITE | 97011-H30536 | \$ 8,145.00 | 10% | \$7,385.48 |
| EW NBD ONSITE | 97011-H30537 | \$ 8,853.00 | 10% | \$8,027.46 |
| EW NBD ONSITE | 97011-H30538 | \$ 4,922.00 | 10% | \$4,463.02 |
| EW NBD ONSITE | 97011-H30539 | \$ 9,274.00 | 10% | \$8,409.20 |
| EW NBD ONSITE | 97011-H30540 | \$ 9,779.00 | 10% | \$8,867.11 |
| EW NBD ONSITE | 97011-H30543 | \$ 670.00 | 10% | \$607.52 |
| EW NBD ONSITE | 97011-H30544 | \$ 1,191.00 | 10% | \$1,079.94 |
| EW NBD ONSITE | 97011-H30548 | \$ 670.00 | 10% | \$607.52 |
| EW NBD ONSITE | 97011-H30549 | \$ 1,127.00 | 10% | \$1,021.91 |
| EW NBD ONSITE | 97011-H30550 | \$ 1,127.00 | 10% | \$1,021.91 |
| EW NBD ONSITE | 97011-H30552 | \$ 670.00 | 10% | \$607.52 |
| EW NBD ONSITE | 97011-H30553 | \$ 1,062.00 | 10% | \$962.97 |
| EW NBD ONSITE | 97011-H30569 | \$ 3,620.00 | 10% | \$3,282.44 |
| EW NBD ONSITE | 97011-H30570 | \$ 4,342.00 | 10% | \$3,937.11 |
| EW NBD ONSITE | 97011-H30571 | \$ 4,342.00 | 10% | \$3,937.11 |
| EW NBD ONSITE | 97011-H30573 | \$ 3,620.00 | 10% | \$3,282.44 |
| EW NBD ONSITE | 97011-H30574 | \$ 4,008.00 | 10% | \$3,634.25 |
| EW NBD ONSITE | 97011-H30575 | \$ 2,502.00 | 10% | \$2,268.69 |
| EW NBD ONSITE | 97011-H30576 | \$ 3,620.00 | 10% | \$3,282.44 |
| EW NBD ONSITE | 97011-H30577 | \$ 4,342.00 | 10% | \$3,937.11 |
| EW NBD ONSITE | 97011-H30578 | \$ 4,342.00 | 10% | \$3,937.11 |
| EW NBD ONSITE | 97011-H30587 | \$ 3,692.00 | 10% | \$3,347.72 |
| EW NBD ONSITE | 97011-H30588 | \$ 2,553.00 | 10% | \$2,314.93 |
| EW NBD ONSITE | 97011-H30589 | \$ 3,945.00 | 10% | \$3,577.13 |
| EW NBD ONSITE | 97011-H30632 | \$ 98.00 | 10% | \$88.86 |
| EW NBD ONSITE | 97011-H30633 | \$ 98.00 | 10% | \$88.86 |
| EW NBD ONSITE | 97011-H30643 | \$ 6,226.00 | 10% | \$5,645.43 |
| EW NBD ONSITE | 97011-H30706 | \$ 5,831.00 | 10% | \$5,287.26 |
| EW NBD ONSITE | 97011-H30707 | \$ 3,620.00 | 10% | \$3,282.44 |
| EW NBD ONSITE | 97011-H30724 | \$ 402.00 | 10% | \$364.51 |
| EW NBD ONSITE | 97011-H30725 | \$ 1,378.00 | 10% | \$1,249.50 |
| EW NBD ONSITE | 97011-H30726 | \$ 9,025.00 | 10% | \$8,183.42 |
| EW NBD ONSITE | 97011-H30727 | \$ 9,592.00 | 10% | \$8,697.55 |
| EW NBD ONSITE | 97011-H30730 | \$ 94.00 | 10% | \$85.23 |
| EW NBD ONSITE | 97011-H30731 | \$ 94.00 | 10% | \$85.23 |
| EW NBD ONSITE 30732 | 97011-H30732 | \$ 1,831.00 | 10% | \$1,660.26 |
| EW NBD ONSITE SKL8008-0810-F8 | 97011-H30733 | \$ 8,480.00 | 10% | \$7,689.24 |
| EW NBD ONSITE STL2006-0850 | 97011-H30734 | \$ 6,460.00 | 10% | \$5,857.61 |

| | | | | |
|----------------------------|--------------|--------------|-----|-------------------|
| EW NBD ONSITE SGL2001-0850 | 97011-H30735 | \$ 7,517.00 | 10% | <i>\$6,816.04</i> |
| EW NBD ONSITE SOK2209-0204 | 97011-H30736 | \$ 1,185.00 | 10% | <i>\$1,074.50</i> |
| EW NBD ONSITE H30738 | 97011-H30738 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW NBD ONSITE -H30739 | 97011-H30739 | \$ 1,265.00 | 10% | <i>\$1,147.04</i> |
| EW NBD ONSITE -H30740 | 97011-H30740 | \$ 734.00 | 10% | <i>\$665.55</i> |
| EW NBD ONSITE -H30741 | 97011-H30741 | \$ 1,339.00 | 10% | <i>\$1,214.14</i> |
| EW NBD ONSITE -H30742 | 97011-H30742 | \$ 1,188.00 | 10% | <i>\$1,077.22</i> |
| EW NBD ONSITE -H30743 | 97011-H30743 | \$ 1,265.00 | 10% | <i>\$1,147.04</i> |
| EW NBD ONSITE -H30744 | 97011-H30744 | \$ 734.00 | 10% | <i>\$665.55</i> |
| EW NBD ONSITE -H30745 | 97011-H30745 | \$ 749.00 | 10% | <i>\$679.16</i> |
| EW NBD ONSITE -H30746 | 97011-H30746 | \$ 1,327.00 | 10% | <i>\$1,203.26</i> |
| EW NBD ONSITE -H30747 | 97011-H30747 | \$ 2,631.00 | 10% | <i>\$2,385.66</i> |
| EW NBD ONSITE -H30748 | 97011-H30748 | \$ 3,878.00 | 10% | <i>\$3,516.38</i> |
| EW NBD ONSITE -H30749 | 97011-H30749 | \$ 8,716.00 | 10% | <i>\$7,903.23</i> |
| EW NBD ONSITE -H30750 | 97011-H30750 | \$ 8,716.00 | 10% | <i>\$7,903.23</i> |
| EW NBD ONSITE -H30751 | 97011-H30751 | \$ 5,165.00 | 10% | <i>\$4,683.36</i> |
| EW NBD ONSITE -H30754 | 97011-H30754 | \$ 8,716.00 | 10% | <i>\$7,903.23</i> |
| EW NBD ONSITE -H30755 | 97011-H30755 | \$ 9,477.00 | 10% | <i>\$8,593.27</i> |
| EW NBD ONSITE -H30756 | 97011-H30756 | \$ 8,716.00 | 10% | <i>\$7,903.23</i> |
| EW NBD ONSITE -H30757 | 97011-H30757 | \$ 3,878.00 | 10% | <i>\$3,516.38</i> |
| EW NBD ONSITE -H30758 | 97011-H30758 | \$ 6,920.00 | 10% | <i>\$6,274.71</i> |
| EW NBD ONSITE -H30759 | 97011-H30759 | \$ 7,897.00 | 10% | <i>\$7,160.60</i> |
| EW NBD ONSITE -H30760 | 97011-H30760 | \$ 8,907.00 | 10% | <i>\$8,076.42</i> |
| EW NBD ONSITE -H30761 | 97011-H30761 | \$ 3,878.00 | 10% | <i>\$3,516.38</i> |
| EW NBD ONSITE -H30762 | 97011-H30762 | \$ 9,477.00 | 10% | <i>\$8,593.27</i> |
| EW NBD ONSITE -H30763 | 97011-H30763 | \$ 9,477.00 | 10% | <i>\$8,593.27</i> |
| EW NBD ONSITE -H30764 | 97011-H30764 | \$ 6,004.00 | 10% | <i>\$5,444.13</i> |
| EW NBD ONSITE -H30765 | 97011-H30765 | \$ 5,267.00 | 10% | <i>\$4,775.85</i> |
| EW NBD ONSITE -H30766 | 97011-H30766 | \$ 10,271.00 | 10% | <i>\$9,313.23</i> |
| EW NBD ONSITE -H30767 | 97011-H30767 | \$ 6,004.00 | 10% | <i>\$5,444.13</i> |
| EW NBD ONSITE H30769 | 97011-H30769 | \$ 2,368.00 | 10% | <i>\$2,147.18</i> |
| EW NBD ONSITE H30773 | 97011-H30773 | \$ 149.00 | 10% | <i>\$135.11</i> |
| EW NBD ONSITE H30774 | 97011-H30774 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW NBD ONSITE H30775 | 97011-H30775 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW NBD ONSITE H30776 | 97011-H30776 | \$ 149.00 | 10% | <i>\$135.11</i> |
| EW NBD ONSITE H30777 | 97011-H30777 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW NBD ONSITE H30778 | 97011-H30778 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW NBD ONSITE H30779 | 97011-H30779 | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE H30780 | 97011-H30780 | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW NBD ONSITE H30781 | 97011-H30781 | \$ 89.00 | 10% | <i>\$80.70</i> |

| | | | | |
|----------------------|--------------|-----------|-----|---------|
| EW NBD ONSITE H30782 | 97011-H30782 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H30783 | 97011-H30783 | \$ 75.00 | 10% | \$68.01 |
| EW NBD ONSITE H30784 | 97011-H30784 | \$ 75.00 | 10% | \$68.01 |
| EW NBD ONSITE H30785 | 97011-H30785 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE H30786 | 97011-H30786 | \$ 89.00 | 10% | \$80.70 |
| EW NBD ONSITE H30787 | 97011-H30787 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE H30788 | 97011-H30788 | \$ 89.00 | 10% | \$80.70 |
| EW NBD ONSITE H30789 | 97011-H30789 | \$ 75.00 | 10% | \$68.01 |
| EW NBD ONSITE H30790 | 97011-H30790 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H30791 | 97011-H30791 | \$ 75.00 | 10% | \$68.01 |
| EW NBD ONSITE H30793 | 97011-H30793 | \$ 69.00 | 10% | \$62.57 |
| EW NBD ONSITE H30794 | 97011-H30794 | \$ 86.00 | 10% | \$77.98 |
| EW NBD ONSITE H30795 | 97011-H30795 | \$ 66.00 | 10% | \$59.85 |
| EW NBD ONSITE H30796 | 97011-H30796 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H30797 | 97011-H30797 | \$ 66.00 | 10% | \$59.85 |
| EW NBD ONSITE H30798 | 97011-H30798 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H30799 | 97011-H30799 | \$ 66.00 | 10% | \$59.85 |
| EW NBD ONSITE H30800 | 97011-H30800 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H30801 | 97011-H30801 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H30802 | 97011-H30802 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H30803 | 97011-H30803 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE H30804 | 97011-H30804 | \$ 66.00 | 10% | \$59.85 |
| EW NBD ONSITE H30805 | 97011-H30805 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H30806 | 97011-H30806 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE H30807 | 97011-H30807 | \$ 66.00 | 10% | \$59.85 |
| EW NBD ONSITE H30808 | 97011-H30808 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H30809 | 97011-H30809 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H30810 | 97011-H30810 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H30811 | 97011-H30811 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE H30812 | 97011-H30812 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H30813 | 97011-H30813 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H30814 | 97011-H30814 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE H30815 | 97011-H30815 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H30816 | 97011-H30816 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H30817 | 97011-H30817 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE H30818 | 97011-H30818 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H30819 | 97011-H30819 | \$ 103.00 | 10% | \$93.40 |
| EW NBD ONSITE H30820 | 97011-H30820 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H30821 | 97011-H30821 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H30822 | 97011-H30822 | \$ 66.00 | 10% | \$59.85 |
| EW NBD ONSITE H30823 | 97011-H30823 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H30824 | 97011-H30824 | \$ 65.00 | 10% | \$58.94 |

| | | | | |
|----------------------|--------------|-------------|-----|-------------------|
| EW NBD ONSITE H30825 | 97011-H30825 | \$ 74.00 | 10% | <i>\$67.10</i> |
| EW NBD ONSITE H30826 | 97011-H30826 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW NBD ONSITE H30827 | 97011-H30827 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW NBD ONSITE H30828 | 97011-H30828 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW NBD ONSITE H30829 | 97011-H30829 | \$ 74.00 | 10% | <i>\$67.10</i> |
| EW NBD ONSITE H30830 | 97011-H30830 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW NBD ONSITE H30831 | 97011-H30831 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW NBD ONSITE H30832 | 97011-H30832 | \$ 1,355.00 | 10% | <i>\$1,228.65</i> |
| EW NBD ONSITE H30833 | 97011-H30833 | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW NBD ONSITE H30834 | 97011-H30834 | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW NBD ONSITE H30836 | 97011-H30836 | \$ 1,355.00 | 10% | <i>\$1,228.65</i> |
| EW NBD ONSITE H30838 | 97011-H30838 | \$ 50.00 | 10% | <i>\$45.34</i> |
| EW NBD ONSITE H30839 | 97011-H30839 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD ONSITE H30840 | 97011-H30840 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD ONSITE H30841 | 97011-H30841 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD ONSITE H30842 | 97011-H30842 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD ONSITE H30843 | 97011-H30843 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD ONSITE H30844 | 97011-H30844 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD ONSITE H30845 | 97011-H30845 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW NBD ONSITE H30846 | 97011-H30846 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE H30847 | 97011-H30847 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE H30848 | 97011-H30848 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE H30849 | 97011-H30849 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE H30850 | 97011-H30850 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE H30851 | 97011-H30851 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE H30852 | 97011-H30852 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW NBD ONSITE H30853 | 97011-H30853 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30854 | 97011-H30854 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30855 | 97011-H30855 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30856 | 97011-H30856 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30857 | 97011-H30857 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30858 | 97011-H30858 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30859 | 97011-H30859 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30860 | 97011-H30860 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW NBD ONSITE H30866 | 97011-H30866 | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW NBD ONSITE H30867 | 97011-H30867 | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE H30868 | 97011-H30868 | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE H30869 | 97011-H30869 | \$ 256.00 | 10% | <i>\$232.13</i> |
| EW NBD ONSITE H30870 | 97011-H30870 | \$ 256.00 | 10% | <i>\$232.13</i> |
| EW NBD ONSITE H30871 | 97011-H30871 | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW NBD ONSITE H30872 | 97011-H30872 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW NBD ONSITE H30873 | 97011-H30873 | \$ 134.00 | 10% | <i>\$121.50</i> |

| | | | | |
|----------------------|--------------|-------------|-----|-------------------|
| EW NBD ONSITE H30874 | 97011-H30874 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW NBD ONSITE H30875 | 97011-H30875 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW NBD ONSITE H30876 | 97011-H30876 | \$ 43.00 | 10% | <i>\$38.99</i> |
| EW NBD ONSITE H30877 | 97011-H30877 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW NBD ONSITE H30878 | 97011-H30878 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW NBD ONSITE H30891 | 97011-H30891 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW NBD ONSITE H30892 | 97011-H30892 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW NBD ONSITE H30893 | 97011-H30893 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD ONSITE H30894 | 97011-H30894 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW NBD ONSITE H30895 | 97011-H30895 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW NBD ONSITE H30896 | 97011-H30896 | \$ 378.00 | 10% | <i>\$342.75</i> |
| EW NBD ONSITE H30897 | 97011-H30897 | \$ 669.00 | 10% | <i>\$606.62</i> |
| EW NBD ONSITE H30898 | 97011-H30898 | \$ 752.00 | 10% | <i>\$681.88</i> |
| EW NBD ONSITE H30900 | 97011-H30900 | \$ 2,276.00 | 10% | <i>\$2,063.76</i> |
| EW NBD ONSITE H30901 | 97011-H30901 | \$ 3,025.00 | 10% | <i>\$2,742.92</i> |
| EW NBD ONSITE H30902 | 97011-H30902 | \$ 3,175.00 | 10% | <i>\$2,878.93</i> |
| EW NBD ONSITE H30904 | 97011-H30904 | \$ 4,671.00 | 10% | <i>\$4,235.43</i> |
| EW NBD ONSITE H30905 | 97011-H30905 | \$ 6,672.00 | 10% | <i>\$6,049.84</i> |
| EW NBD ONSITE H30906 | 97011-H30906 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW NBD ONSITE H30912 | 97011-H30912 | \$ 503.00 | 10% | <i>\$456.10</i> |
| EW NBD ONSITE H30913 | 97011-H30913 | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD ONSITE H30914 | 97011-H30914 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW NBD ONSITE H30915 | 97011-H30915 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW NBD ONSITE H30916 | 97011-H30916 | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW NBD ONSITE H30917 | 97011-H30917 | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD ONSITE H30918 | 97011-H30918 | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW NBD ONSITE H30946 | 97011-H30946 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW NBD ONSITE H30947 | 97011-H30947 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW NBD ONSITE H30948 | 97011-H30948 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW NBD ONSITE H30950 | 97011-H30950 | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW NBD ONSITE H30951 | 97011-H30951 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW NBD ONSITE H30952 | 97011-H30952 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW NBD ONSITE H30966 | 97011-H30966 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW NBD ONSITE H30967 | 97011-H30967 | \$ 149.00 | 10% | <i>\$135.11</i> |
| EW NBD ONSITE H30968 | 97011-H30968 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW NBD ONSITE H30969 | 97011-H30969 | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE H30970 | 97011-H30970 | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW NBD ONSITE H30971 | 97011-H30971 | \$ 102.00 | 10% | <i>\$92.49</i> |
| EW NBD ONSITE H30972 | 97011-H30972 | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW NBD ONSITE H30973 | 97011-H30973 | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW NBD ONSITE H30974 | 97011-H30974 | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW NBD ONSITE H30975 | 97011-H30975 | \$ 165.00 | 10% | <i>\$149.61</i> |

| | | | | |
|----------------------|--------------|-------------|-----|-------------------|
| EW NBD ONSITE H30976 | 97011-H30976 | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW NBD ONSITE H30977 | 97011-H30977 | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW NBD ONSITE H30978 | 97011-H30978 | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW NBD ONSITE H30995 | 97011-H30995 | \$ 1,826.00 | 10% | <i>\$1,655.73</i> |
| EW NBD ONSITE H31030 | 97011-H31030 | \$ 5,893.00 | 10% | <i>\$5,343.48</i> |
| EW NBD ONSITE H31031 | 97011-H31031 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW NBD ONSITE H31033 | 97011-H31033 | \$ 3,567.00 | 10% | <i>\$3,234.38</i> |
| EW NBD ONSITE H31034 | 97011-H31034 | \$ 1,982.00 | 10% | <i>\$1,797.18</i> |
| EW NBD ONSITE H31035 | 97011-H31035 | \$ 2,078.00 | 10% | <i>\$1,884.23</i> |
| EW NBD ONSITE H31036 | 97011-H31036 | \$ 4,161.00 | 10% | <i>\$3,772.99</i> |
| EW NBD ONSITE H31040 | 97011-H31040 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW NBD ONSITE H31041 | 97011-H31041 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD ONSITE H31042 | 97011-H31042 | \$ 230.00 | 10% | <i>\$208.55</i> |
| EW NBD ONSITE H31043 | 97011-H31043 | \$ 166.00 | 10% | <i>\$150.52</i> |
| EW NBD ONSITE H31047 | 97011-H31047 | \$ 155.00 | 10% | <i>\$140.55</i> |
| EW NBD ONSITE H31049 | 97011-H31049 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW NBD ONSITE H31060 | 97011-H31060 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW NBD ONSITE H31062 | 97011-H31062 | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE H31066 | 97011-H31066 | \$ 61.00 | 10% | <i>\$55.31</i> |
| EW NBD ONSITE H31068 | 97011-H31068 | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW NBD ONSITE H31076 | 97011-H31076 | \$ 225.00 | 10% | <i>\$204.02</i> |
| EW NBD ONSITE H31077 | 97011-H31077 | \$ 230.00 | 10% | <i>\$208.55</i> |
| EW NBD ONSITE H31078 | 97011-H31078 | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW NBD ONSITE H31103 | 97011-H31103 | \$ 3,809.00 | 10% | <i>\$3,453.81</i> |
| EW NBD ONSITE H31119 | 97011-H31119 | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE H31124 | 97011-H31124 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW NBD ONSITE H31127 | 97011-H31127 | \$ 149.00 | 10% | <i>\$135.11</i> |
| EW NBD ONSITE H31132 | 97011-H31132 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW NBD ONSITE H31134 | 97011-H31134 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW NBD ONSITE H31135 | 97011-H31135 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW NBD ONSITE H31136 | 97011-H31136 | \$ 77.00 | 10% | <i>\$69.82</i> |
| EW NBD ONSITE H31137 | 97011-H31137 | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW NBD ONSITE H31197 | 97011-H31197 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE H31198 | 97011-H31198 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE H31199 | 97011-H31199 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE H31200 | 97011-H31200 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE H31201 | 97011-H31201 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE H31202 | 97011-H31202 | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW NBD ONSITE H31203 | 97011-H31203 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW NBD ONSITE H31204 | 97011-H31204 | \$ 87.00 | 10% | <i>\$78.89</i> |
| EW NBD ONSITE H31205 | 97011-H31205 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW NBD ONSITE H31206 | 97011-H31206 | \$ 100.00 | 10% | <i>\$90.68</i> |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW NBD ONSITE H31207 | 97011-H31207 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE H31208 | 97011-H31208 | \$ 100.00 | 10% | \$90.68 |
| EW NBD ONSITE H31210 | 97011-H31210 | \$ 179.00 | 10% | \$162.31 |
| EW NBD ONSITE H31335 | 97011-H31335 | \$ 102.00 | 10% | \$92.49 |
| EW NBD ONSITE H31337 | 97011-H31337 | \$ 7,639.00 | 10% | \$6,926.66 |
| EW NBD ONSITE H31338 | 97011-H31338 | \$ 7,639.00 | 10% | \$6,926.66 |
| EW NBD ONSITE H31339 | 97011-H31339 | \$ 1,242.00 | 10% | \$1,126.18 |
| EW NBD ONSITE H31340 | 97011-H31340 | \$ 2,651.00 | 10% | \$2,403.79 |
| EW NBD ONSITE H31341 | 97011-H31341 | \$ 3,929.00 | 10% | \$3,562.62 |
| EW NBD ONSITE H31342 | 97011-H31342 | \$ 1,237.00 | 10% | \$1,121.65 |
| EW NBD ONSITE H31343 | 97011-H31343 | \$ 1,831.00 | 10% | \$1,660.26 |
| EW NBD ONSITE H31344 | 97011-H31344 | \$ 1,831.00 | 10% | \$1,660.26 |
| EW NBD ONSITE H31345 | 97011-H31345 | \$ 1,831.00 | 10% | \$1,660.26 |
| EW NBD ONSITE H31346 | 97011-H31346 | \$ 1,831.00 | 10% | \$1,660.26 |
| EW NBD ONSITE H31348 | 97011-H31348 | \$ 144.00 | 10% | \$130.57 |
| EW NBD ONSITE H31349 | 97011-H31349 | \$ 144.00 | 10% | \$130.57 |
| EW NBD ONSITE H31350 | 97011-H31350 | \$ 235.00 | 10% | \$213.09 |
| EW NBD ONSITE H31351 | 97011-H31351 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE H31352 | 97011-H31352 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE H31353 | 97011-H31353 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H31354 | 97011-H31354 | \$ 74.00 | 10% | \$67.10 |
| EW NBD ONSITE H31355 | 97011-H31355 | \$ 149.00 | 10% | \$135.11 |
| EW NBD ONSITE H31356 | 97011-H31356 | \$ 149.00 | 10% | \$135.11 |
| EW NBD ONSITE H31357 | 97011-H31357 | \$ 149.00 | 10% | \$135.11 |
| EW NBD ONSITE H31358 | 97011-H31358 | \$ 57.00 | 10% | \$51.68 |
| EW NBD ONSITE H31359 | 97011-H31359 | \$ 61.00 | 10% | \$55.31 |
| EW NBD ONSITE H31360 | 97011-H31360 | \$ 49.00 | 10% | \$44.43 |
| EW NBD ONSITE H31361 | 97011-H31361 | \$ 2,573.00 | 10% | \$2,333.07 |
| EW NBD ONSITE H31362 | 97011-H31362 | \$ 18,862.00 | 10% | \$17,103.12 |
| EW NBD ONSITE H31363 | 97011-H31363 | \$ 18,862.00 | 10% | \$17,103.12 |
| EW NBD ONSITE H31364 | 97011-H31364 | \$ 6,590.00 | 10% | \$5,975.48 |
| EW NBD ONSITE H31365 | 97011-H31365 | \$ 6,590.00 | 10% | \$5,975.48 |
| EW NBD ONSITE H31366 | 97011-H31366 | \$ 9,137.00 | 10% | \$8,284.97 |
| EW NBD ONSITE H31367 | 97011-H31367 | \$ 9,137.00 | 10% | \$8,284.97 |
| EW NBD ONSITE H31369 | 97011-H31369 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE H31370 | 97011-H31370 | \$ 87.00 | 10% | \$78.89 |
| EW NBD ONSITE H31393 | 97011-H31393 | \$ 49.00 | 10% | \$44.43 |
| EW NBD ONSITE H32010 | 97011-H32010 | \$ 262.00 | 10% | \$237.57 |
| EW NBD ONSITE H32011 | 97011-H32011 | \$ 262.00 | 10% | \$237.57 |
| EW NBD ONSITE H32012 | 97011-H32012 | \$ 2,267.00 | 10% | \$2,055.60 |
| EW NBD ONSITE H32013 | 97011-H32013 | \$ 2,267.00 | 10% | \$2,055.60 |
| EW NBD ONSITE H32014 | 97011-H32014 | \$ 2,267.00 | 10% | \$2,055.60 |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW NBD ONSITE H32015 | 97011-H32015 | \$ 2,267.00 | 10% | \$2,055.60 |
| EW NBD ONSITE H32016 | 97011-H32016 | \$ 1,974.00 | 10% | \$1,789.92 |
| EW NBD ONSITE H32017 | 97011-H32017 | \$ 1,974.00 | 10% | \$1,789.92 |
| EW NBD ONSITE H32018 | 97011-H32018 | \$ 1,974.00 | 10% | \$1,789.92 |
| EW NBD ONSITE H32019 | 97011-H32019 | \$ 1,974.00 | 10% | \$1,789.92 |
| EW NBD ONSITE H32020 | 97011-H32020 | \$ 19,782.00 | 10% | \$17,937.33 |
| EW NBD ONSITE H32021 | 97011-H32021 | \$ 19,782.00 | 10% | \$17,937.33 |
| EW NBD ONSITE H32022 | 97011-H32022 | \$ 19,782.00 | 10% | \$17,937.33 |
| EW NBD ONSITE H32023 | 97011-H32023 | \$ 19,782.00 | 10% | \$17,937.33 |
| EW NBD ONSITE H32028 | 97011-H32028 | \$ 38,137.00 | 10% | \$34,580.72 |
| EW NBD ONSITE H32029 | 97011-H32029 | \$ 38,137.00 | 10% | \$34,580.72 |
| EW NBD ONSITE H32030 | 97011-H32030 | \$ 39,993.00 | 10% | \$36,263.65 |
| EW NBD ONSITE H32031 | 97011-H32031 | \$ 39,993.00 | 10% | \$36,263.65 |
| EW NBD ONSITE H32032 | 97011-H32032 | \$ 39,993.00 | 10% | \$36,263.65 |
| EW NBD ONSITE H32033 | 97011-H32033 | \$ 39,993.00 | 10% | \$36,263.65 |
| EW NBD ONSITE H32038 | 97011-H32038 | \$ 6,912.00 | 10% | \$6,267.46 |
| EW NBD ONSITE H32039 | 97011-H32039 | \$ 6,912.00 | 10% | \$6,267.46 |
| EW NBD ONSITE H32040 | 97011-H32040 | \$ 6,912.00 | 10% | \$6,267.46 |
| EW NBD ONSITE H32041 | 97011-H32041 | \$ 6,912.00 | 10% | \$6,267.46 |
| EW NBD ONSITE H32046 | 97011-H32046 | \$ 9,583.00 | 10% | \$8,689.39 |
| EW NBD ONSITE H32047 | 97011-H32047 | \$ 9,583.00 | 10% | \$8,689.39 |
| EW NBD ONSITE H32048 | 97011-H32048 | \$ 9,583.00 | 10% | \$8,689.39 |
| EW NBD ONSITE H32049 | 97011-H32049 | \$ 9,583.00 | 10% | \$8,689.39 |
| EW NBD ONSITE H32054 | 97011-H32054 | \$ 6,912.00 | 10% | \$6,267.46 |
| EW NBD ONSITE H32055 | 97011-H32055 | \$ 9,583.00 | 10% | \$8,689.39 |
| EW NBD ONSITE H32056 | 97011-H32056 | \$ 2,749.00 | 10% | \$2,492.66 |
| EW NBD ONSITE H32057 | 97011-H32057 | \$ 2,749.00 | 10% | \$2,492.66 |
| EW NBD ONSITE H32058 | 97011-H32058 | \$ 2,749.00 | 10% | \$2,492.66 |
| EW NBD ONSITE H32059 | 97011-H32059 | \$ 2,749.00 | 10% | \$2,492.66 |
| EW NBD ONSITE H32060 | 97011-H32060 | \$ 2,680.00 | 10% | \$2,430.09 |
| EW NBD ONSITE H32061 | 97011-H32061 | \$ 2,814.00 | 10% | \$2,551.59 |
| EW NBD ONSITE H32062 | 97011-H32062 | \$ 2,706.00 | 10% | \$2,453.67 |
| EW NBD ONSITE H32063 | 97011-H32063 | \$ 2,683.00 | 10% | \$2,432.81 |
| EW NBD ONSITE H32064 | 97011-H32064 | \$ 2,706.00 | 10% | \$2,453.67 |
| EW NBD ONSITE H32065 | 97011-H32065 | \$ 3,056.00 | 10% | \$2,771.03 |
| EW NBD ONSITE H32066 | 97011-H32066 | \$ 3,056.00 | 10% | \$2,771.03 |
| EW NBD ONSITE H32067 | 97011-H32067 | \$ 3,056.00 | 10% | \$2,771.03 |
| EW NBD ONSITE H32068 | 97011-H32068 | \$ 3,056.00 | 10% | \$2,771.03 |
| EW NBD ONSITE H32069 | 97011-H32069 | \$ 3,796.00 | 10% | \$3,442.02 |
| EW NBD ONSITE H32070 | 97011-H32070 | \$ 3,796.00 | 10% | \$3,442.02 |
| EW NBD ONSITE H32071 | 97011-H32071 | \$ 3,796.00 | 10% | \$3,442.02 |
| EW NBD ONSITE H32072 | 97011-H32072 | \$ 3,796.00 | 10% | \$3,442.02 |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW NBD ONSITE H32073 | 97011-H32073 | \$ 28,098.00 | 10% | \$25,477.86 |
| EW NBD ONSITE H32074 | 97011-H32074 | \$ 28,098.00 | 10% | \$25,477.86 |
| EW NBD ONSITE H32075 | 97011-H32075 | \$ 38,180.00 | 10% | \$34,619.72 |
| EW NBD ONSITE H32076 | 97011-H32076 | \$ 38,180.00 | 10% | \$34,619.72 |
| EW NBD ONSITE H32101 | 97011-H32101 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32102 | 97011-H32102 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32103 | 97011-H32103 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32104 | 97011-H32104 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32105 | 97011-H32105 | \$ 2,473.00 | 10% | \$2,242.39 |
| EW NBD ONSITE H32106 | 97011-H32106 | \$ 2,473.00 | 10% | \$2,242.39 |
| EW NBD ONSITE H32107 | 97011-H32107 | \$ 6,702.00 | 10% | \$6,077.04 |
| EW NBD ONSITE H32108 | 97011-H32108 | \$ 6,702.00 | 10% | \$6,077.04 |
| EW NBD ONSITE H32109 | 97011-H32109 | \$ 2,474.00 | 10% | \$2,243.30 |
| EW NBD ONSITE H32110 | 97011-H32110 | \$ 2,474.00 | 10% | \$2,243.30 |
| EW NBD ONSITE H32111 | 97011-H32111 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32112 | 97011-H32112 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32113 | 97011-H32113 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32114 | 97011-H32114 | \$ 1,240.00 | 10% | \$1,124.37 |
| EW NBD ONSITE H32115 | 97011-H32115 | \$ 2,474.00 | 10% | \$2,243.30 |
| EW NBD ONSITE H32116 | 97011-H32116 | \$ 2,474.00 | 10% | \$2,243.30 |
| EW NBD ONSITE H32117 | 97011-H32117 | \$ 1,160.00 | 10% | \$1,051.83 |
| EW NBD ONSITE H32118 | 97011-H32118 | \$ 1,160.00 | 10% | \$1,051.83 |
| EW NBD ONSITE H32119 | 97011-H32119 | \$ 1,160.00 | 10% | \$1,051.83 |
| EW NBD ONSITE H32120 | 97011-H32120 | \$ 1,160.00 | 10% | \$1,051.83 |
| EW NBD ONSITE H32121 | 97011-H32121 | \$ 6,702.00 | 10% | \$6,077.04 |
| EW NBD ONSITE H32122 | 97011-H32122 | \$ 6,702.00 | 10% | \$6,077.04 |
| EW NBD ONSITE H32123 | 97011-H32123 | \$ 2,474.00 | 10% | \$2,243.30 |
| EW NBD ONSITE H32124 | 97011-H32124 | \$ 2,474.00 | 10% | \$2,243.30 |
| EW NBD ONSITE H32125 | 97011-H32125 | \$ 2,450.00 | 10% | \$2,221.54 |
| EW NBD ONSITE H32126 | 97011-H32126 | \$ 2,450.00 | 10% | \$2,221.54 |
| EW NBD ONSITE H32127 | 97011-H32127 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW NBD ONSITE H32128 | 97011-H32128 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW NBD ONSITE H32129 | 97011-H32129 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW NBD ONSITE H32130 | 97011-H32130 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW NBD ONSITE H32131 | 97011-H32131 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW NBD ONSITE H32132 | 97011-H32132 | \$ 2,880.00 | 10% | \$2,611.44 |
| EW NBD ONSITE H32133 | 97011-H32133 | \$ 2,450.00 | 10% | \$2,221.54 |
| EW NBD ONSITE H32134 | 97011-H32134 | \$ 2,450.00 | 10% | \$2,221.54 |
| EW NBD ONSITE H32135 | 97011-H32135 | \$ 2,450.00 | 10% | \$2,221.54 |
| EW NBD ONSITE H32136 | 97011-H32136 | \$ 2,450.00 | 10% | \$2,221.54 |
| EW NBD ONSITE H32137 | 97011-H32137 | \$ 2,450.00 | 10% | \$2,221.54 |
| EW NBD ONSITE H32138 | 97011-H32138 | \$ 2,450.00 | 10% | \$2,221.54 |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW NBD ONSITE H32139 | 97011-H32139 | \$ 10,356.00 | 10% | \$9,390.30 |
| EW NBD ONSITE H32140 | 97011-H32140 | \$ 10,356.00 | 10% | \$9,390.30 |
| EW NBD ONSITE H32141 | 97011-H32141 | \$ 11,948.00 | 10% | \$10,833.85 |
| EW NBD ONSITE H32142 | 97011-H32142 | \$ 11,948.00 | 10% | \$10,833.85 |
| EW NBD ONSITE H32146 | 97011-H32146 | \$ 1,058.00 | 10% | \$959.34 |
| EW NBD ONSITE H32147 | 97011-H32147 | \$ 1,058.00 | 10% | \$959.34 |
| EW NBD ONSITE H32148 | 97011-H32148 | \$ 2,174.00 | 10% | \$1,971.27 |
| EW NBD ONSITE H32149 | 97011-H32149 | \$ 2,174.00 | 10% | \$1,971.27 |
| EW NBD ONSITE H32150 | 97011-H32150 | \$ 1,120.00 | 10% | \$1,015.56 |
| EW NBD ONSITE H32169 | 97011-H32169 | \$ 1,255.00 | 10% | \$1,137.97 |
| EW NBD ONSITE H32170 | 97011-H32170 | \$ 1,255.00 | 10% | \$1,137.97 |
| EW NBD ONSITE H32171 | 97011-H32171 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW NBD ONSITE H32172 | 97011-H32172 | \$ 1,174.00 | 10% | \$1,064.52 |
| EW NBD ONSITE H32173 | 97011-H32173 | \$ 3,135.00 | 10% | \$2,842.66 |
| EW NBD ONSITE H32174 | 97011-H32174 | \$ 3,135.00 | 10% | \$2,842.66 |
| EW NBD ONSITE H32175 | 97011-H32175 | \$ 2,664.00 | 10% | \$2,415.58 |
| EW NBD ONSITE H32176 | 97011-H32176 | \$ 2,664.00 | 10% | \$2,415.58 |
| EW NBD ONSITE H32177 | 97011-H32177 | \$ 12,209.00 | 10% | \$11,070.51 |
| EW NBD ONSITE H32178 | 97011-H32178 | \$ 14,087.00 | 10% | \$12,773.39 |
| EW NBD ONSITE H34008 | 97011-H34008 | \$ 40.00 | 10% | \$36.27 |
| EW NBD ONSITE H34009 | 97011-H34009 | \$ 108.00 | 10% | \$97.93 |
| EW NBD ONSITE H34010 | 97011-H34010 | \$ 44.00 | 10% | \$39.90 |
| EW NBD ONSITE H34011 | 97011-H34011 | \$ 91.00 | 10% | \$82.51 |
| EW NBD ONSITE H34012 | 97011-H34012 | \$ 175.00 | 10% | \$158.68 |
| EW NBD ONSITE H34013 | 97011-H34013 | \$ 66.00 | 10% | \$59.85 |
| EW NBD ONSITE H34014 | 97011-H34014 | \$ 108.00 | 10% | \$97.93 |
| EW NBD ONSITE H34015 | 97011-H34015 | \$ 58.00 | 10% | \$52.59 |
| EW NBD ONSITE H34016 | 97011-H34016 | \$ 119.00 | 10% | \$107.90 |
| EW NBD ONSITE H34017 | 97011-H34017 | \$ 200.00 | 10% | \$181.35 |
| EW NBD ONSITE H34018 | 97011-H34018 | \$ 79.00 | 10% | \$71.63 |
| EW NBD ONSITE H34019 | 97011-H34019 | \$ 79.00 | 10% | \$71.63 |
| EW NBD ONSITE H34020 | 97011-H34020 | \$ 79.00 | 10% | \$71.63 |
| EW NBD ONSITE H34021 | 97011-H34021 | \$ 79.00 | 10% | \$71.63 |
| EW NBD ONSITE H34048 | 97011-H34048 | \$ 334.00 | 10% | \$302.85 |
| EW NBD ONSITE H34049 | 97011-H34049 | \$ 334.00 | 10% | \$302.85 |
| EW NBD ONSITE H34050 | 97011-H34050 | \$ 250.00 | 10% | \$226.69 |
| EW NBD ONSITE H34051 | 97011-H34051 | \$ 250.00 | 10% | \$226.69 |
| EW NBD ONSITE H34052 | 97011-H34052 | \$ 391.00 | 10% | \$354.54 |
| EW NBD ONSITE H34053 | 97011-H34053 | \$ 391.00 | 10% | \$354.54 |
| EW NBD ONSITE H34054 | 97011-H34054 | \$ 295.00 | 10% | \$267.49 |
| EW NBD ONSITE H34055 | 97011-H34055 | \$ 295.00 | 10% | \$267.49 |
| EW NBD ONSITE H34056 | 97011-H34056 | \$ 428.00 | 10% | \$388.09 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW NBD ONSITE H34057 | 97011-H34057 | \$ 428.00 | 10% | \$388.09 |
| EW NBD ONSITE H34058 | 97011-H34058 | \$ 364.00 | 10% | \$330.06 |
| EW NBD ONSITE H34059 | 97011-H34059 | \$ 364.00 | 10% | \$330.06 |
| EW NBD ONSITE H34062 | 97011-H34062 | \$ 428.00 | 10% | \$388.09 |
| EW NBD ONSITE H34063 | 97011-H34063 | \$ 428.00 | 10% | \$388.09 |
| EW NBD ONSITE H34064 | 97011-H34064 | \$ 254.00 | 10% | \$230.31 |
| EW NBD ONSITE H34065 | 97011-H34065 | \$ 254.00 | 10% | \$230.31 |
| EW NBD ONSITE H34066 | 97011-H34066 | \$ 254.00 | 10% | \$230.31 |
| EW NBD ONSITE H34067 | 97011-H34067 | \$ 254.00 | 10% | \$230.31 |
| EW NBD ONSITE H34068 | 97011-H34068 | \$ 254.00 | 10% | \$230.31 |
| EW NBD ONSITE H34069 | 97011-H34069 | \$ 247.00 | 10% | \$223.97 |
| EW NBD ONSITE H34070 | 97011-H34070 | \$ 254.00 | 10% | \$230.31 |
| EW NBD ONSITE H34071 | 97011-H34071 | \$ 254.00 | 10% | \$230.31 |
| EW NBD ONSITE H34072 | 97011-H34072 | \$ 2,364.00 | 10% | \$2,143.56 |
| EW NBD ONSITE H34073 | 97011-H34073 | \$ 2,317.00 | 10% | \$2,100.94 |
| EW NBD ONSITE H34074 | 97011-H34074 | \$ 2,951.00 | 10% | \$2,675.82 |
| EW NBD ONSITE H34075 | 97011-H34075 | \$ 2,829.00 | 10% | \$2,565.20 |
| EW NBD ONSITE H34076 | 97011-H34076 | \$ 2,364.00 | 10% | \$2,143.56 |
| EW NBD ONSITE H34077 | 97011-H34077 | \$ 2,317.00 | 10% | \$2,100.94 |
| EW NBD ONSITE H34078 | 97011-H34078 | \$ 2,364.00 | 10% | \$2,143.56 |
| EW NBD ONSITE H34079 | 97011-H34079 | \$ 2,317.00 | 10% | \$2,100.94 |
| EW NBD ONSITE H34080 | 97011-H34080 | \$ 2,951.00 | 10% | \$2,675.82 |
| EW NBD ONSITE H34081 | 97011-H34081 | \$ 2,829.00 | 10% | \$2,565.20 |
| EW NBD ONSITE H34082 | 97011-H34082 | \$ 2,832.00 | 10% | \$2,567.92 |
| EW NBD ONSITE H34083 | 97011-H34083 | \$ 2,713.00 | 10% | \$2,460.01 |
| EW NBD ONSITE H34084 | 97011-H34084 | \$ 2,048.00 | 10% | \$1,857.02 |
| EW NBD ONSITE H34085 | 97011-H34085 | \$ 2,048.00 | 10% | \$1,857.02 |
| EW NBD ONSITE H34086 | 97011-H34086 | \$ 2,386.00 | 10% | \$2,163.51 |
| EW NBD ONSITE H34087 | 97011-H34087 | \$ 2,288.00 | 10% | \$2,074.64 |
| EW NBD ONSITE H34088 | 97011-H34088 | \$ 5,075.00 | 10% | \$4,601.76 |
| EW NBD ONSITE H34089 | 97011-H34089 | \$ 5,075.00 | 10% | \$4,601.76 |
| EW NBD ONSITE H34090 | 97011-H34090 | \$ 5,844.00 | 10% | \$5,299.05 |
| EW NBD ONSITE H34091 | 97011-H34091 | \$ 3,521.00 | 10% | \$3,192.67 |
| EW NBD ONSITE H34092 | 97011-H34092 | \$ 3,521.00 | 10% | \$3,192.67 |
| EW NBD ONSITE H34093 | 97011-H34093 | \$ 3,521.00 | 10% | \$3,192.67 |
| EW NBD ONSITE H34094 | 97011-H34094 | \$ 408.00 | 10% | \$369.95 |
| EW NBD ONSITE H34095 | 97011-H34095 | \$ 408.00 | 10% | \$369.95 |
| EW NBD ONSITE H34096 | 97011-H34096 | \$ 456.00 | 10% | \$413.48 |
| EW NBD ONSITE H34097 | 97011-H34097 | \$ 456.00 | 10% | \$413.48 |
| EW NBD ONSITE H34098 | 97011-H34098 | \$ 408.00 | 10% | \$369.95 |
| EW NBD ONSITE H34099 | 97011-H34099 | \$ 408.00 | 10% | \$369.95 |
| EW NBD ONSITE H34100 | 97011-H34100 | \$ 408.00 | 10% | \$369.95 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW NBD ONSITE H34101 | 97011-H34101 | \$ 408.00 | 10% | \$369.95 |
| EW NBD ONSITE H34102 | 97011-H34102 | \$ 408.00 | 10% | \$369.95 |
| EW NBD ONSITE H34103 | 97011-H34103 | \$ 408.00 | 10% | \$369.95 |
| EW NBD ONSITE H34104 | 97011-H34104 | \$ 180.00 | 10% | \$163.22 |
| EW NBD ONSITE H34105 | 97011-H34105 | \$ 180.00 | 10% | \$163.22 |
| EW NBD ONSITE H34106 | 97011-H34106 | \$ 180.00 | 10% | \$163.22 |
| EW NBD ONSITE H34107 | 97011-H34107 | \$ 180.00 | 10% | \$163.22 |
| EW NBD ONSITE H34108 | 97011-H34108 | \$ 180.00 | 10% | \$163.22 |
| EW NBD ONSITE H34109 | 97011-H34109 | \$ 180.00 | 10% | \$163.22 |
| EW NBD ONSITE H34110 | 97011-H34110 | \$ 3,390.00 | 10% | \$3,073.88 |
| EW NBD ONSITE H34111 | 97011-H34111 | \$ 3,390.00 | 10% | \$3,073.88 |
| EW NBD ONSITE H34112 | 97011-H34112 | \$ 3,390.00 | 10% | \$3,073.88 |
| EW NBD ONSITE H34114 | 97011-H34114 | \$ 4,451.00 | 10% | \$4,035.94 |
| EW NBD ONSITE H34115 | 97011-H34115 | \$ 4,451.00 | 10% | \$4,035.94 |
| EW NBD ONSITE H34116 | 97011-H34116 | \$ 4,451.00 | 10% | \$4,035.94 |
| EW NBD ONSITE H34117 | 97011-H34117 | \$ 4,451.00 | 10% | \$4,035.94 |
| EW NBD ONSITE H34118 | 97011-H34118 | \$ 1,127.00 | 10% | \$1,021.91 |
| EW NBD ONSITE H34119 | 97011-H34119 | \$ 1,127.00 | 10% | \$1,021.91 |
| EW NBD ONSITE H34120 | 97011-H34120 | \$ 774.00 | 10% | \$701.82 |
| EW NBD ONSITE H34121 | 97011-H34121 | \$ 774.00 | 10% | \$701.82 |
| EW NBD ONSITE H34122 | 97011-H34122 | \$ 807.00 | 10% | \$731.75 |
| EW NBD ONSITE H34123 | 97011-H34123 | \$ 807.00 | 10% | \$731.75 |
| EW NBD ONSITE H34124 | 97011-H34124 | \$ 1,201.00 | 10% | \$1,089.01 |
| EW NBD ONSITE H34125 | 97011-H34125 | \$ 1,201.00 | 10% | \$1,089.01 |
| EW NBD ONSITE H34126 | 97011-H34126 | \$ 1,201.00 | 10% | \$1,089.01 |
| EW NBD ONSITE H34127 | 97011-H34127 | \$ 1,201.00 | 10% | \$1,089.01 |
| EW NBD ONSITE H34128 | 97011-H34128 | \$ 200.00 | 10% | \$181.35 |
| EW NBD ONSITE H34129 | 97011-H34129 | \$ 368.00 | 10% | \$333.68 |
| EW NBD ONSITE H34130 | 97011-H34130 | \$ 382.00 | 10% | \$346.38 |
| EW NBD ONSITE H34131 | 97011-H34131 | \$ 380.00 | 10% | \$344.57 |
| EW NBD ONSITE H34132 | 97011-H34132 | \$ 382.00 | 10% | \$346.38 |
| EW NBD ONSITE H34172 | 97011-H34172 | \$ 1,896.00 | 10% | \$1,719.20 |
| EW NBD ONSITE H34174 | 97011-H34174 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34175 | 97011-H34175 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34176 | 97011-H34176 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34177 | 97011-H34177 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34178 | 97011-H34178 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34179 | 97011-H34179 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34180 | 97011-H34180 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34181 | 97011-H34181 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34182 | 97011-H34182 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34183 | 97011-H34183 | \$ 48.00 | 10% | \$43.52 |

| | | | | |
|----------------------|--------------|----------|-----|---------|
| EW NBD ONSITE H34184 | 97011-H34184 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34185 | 97011-H34185 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34186 | 97011-H34186 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34187 | 97011-H34187 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34188 | 97011-H34188 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34189 | 97011-H34189 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34190 | 97011-H34190 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34191 | 97011-H34191 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34192 | 97011-H34192 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34193 | 97011-H34193 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34194 | 97011-H34194 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34195 | 97011-H34195 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34196 | 97011-H34196 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34197 | 97011-H34197 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34198 | 97011-H34198 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34199 | 97011-H34199 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34200 | 97011-H34200 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34201 | 97011-H34201 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34202 | 97011-H34202 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34203 | 97011-H34203 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34204 | 97011-H34204 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34205 | 97011-H34205 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34206 | 97011-H34206 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34207 | 97011-H34207 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34208 | 97011-H34208 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34209 | 97011-H34209 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34210 | 97011-H34210 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34211 | 97011-H34211 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34212 | 97011-H34212 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34213 | 97011-H34213 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34214 | 97011-H34214 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34215 | 97011-H34215 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34216 | 97011-H34216 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34217 | 97011-H34217 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34218 | 97011-H34218 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34219 | 97011-H34219 | \$ 48.00 | 10% | \$43.52 |
| EW NBD ONSITE H34220 | 97011-H34220 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34221 | 97011-H34221 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34222 | 97011-H34222 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34223 | 97011-H34223 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34224 | 97011-H34224 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34225 | 97011-H34225 | \$ 65.00 | 10% | \$58.94 |

| | | | | |
|----------------------|--------------|----------|-----|---------|
| EW NBD ONSITE H34226 | 97011-H34226 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34227 | 97011-H34227 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34228 | 97011-H34228 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34229 | 97011-H34229 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34230 | 97011-H34230 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34231 | 97011-H34231 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34232 | 97011-H34232 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34233 | 97011-H34233 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34234 | 97011-H34234 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34235 | 97011-H34235 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34236 | 97011-H34236 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34237 | 97011-H34237 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34238 | 97011-H34238 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34239 | 97011-H34239 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34240 | 97011-H34240 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34241 | 97011-H34241 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34242 | 97011-H34242 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34243 | 97011-H34243 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34244 | 97011-H34244 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34245 | 97011-H34245 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34246 | 97011-H34246 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34247 | 97011-H34247 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34248 | 97011-H34248 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34249 | 97011-H34249 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34250 | 97011-H34250 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34251 | 97011-H34251 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34252 | 97011-H34252 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34253 | 97011-H34253 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34254 | 97011-H34254 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34255 | 97011-H34255 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34256 | 97011-H34256 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34257 | 97011-H34257 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34258 | 97011-H34258 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34259 | 97011-H34259 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34260 | 97011-H34260 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34261 | 97011-H34261 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34262 | 97011-H34262 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34263 | 97011-H34263 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34264 | 97011-H34264 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34265 | 97011-H34265 | \$ 65.00 | 10% | \$58.94 |
| EW NBD ONSITE H34266 | 97011-H34266 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34267 | 97011-H34267 | \$ 45.00 | 10% | \$40.80 |

| | | | | |
|----------------------|--------------|----------|-----|---------|
| EW NBD ONSITE H34268 | 97011-H34268 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34269 | 97011-H34269 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34270 | 97011-H34270 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34271 | 97011-H34271 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34272 | 97011-H34272 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34273 | 97011-H34273 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34274 | 97011-H34274 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34275 | 97011-H34275 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34276 | 97011-H34276 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34277 | 97011-H34277 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34278 | 97011-H34278 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34279 | 97011-H34279 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34280 | 97011-H34280 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34281 | 97011-H34281 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34282 | 97011-H34282 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34283 | 97011-H34283 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34284 | 97011-H34284 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34285 | 97011-H34285 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34286 | 97011-H34286 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34287 | 97011-H34287 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34288 | 97011-H34288 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34289 | 97011-H34289 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34290 | 97011-H34290 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34291 | 97011-H34291 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34292 | 97011-H34292 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34293 | 97011-H34293 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34294 | 97011-H34294 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34295 | 97011-H34295 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34296 | 97011-H34296 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34297 | 97011-H34297 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34298 | 97011-H34298 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34299 | 97011-H34299 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34300 | 97011-H34300 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34301 | 97011-H34301 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34302 | 97011-H34302 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34303 | 97011-H34303 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34304 | 97011-H34304 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34305 | 97011-H34305 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H34306 | 97011-H34306 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34307 | 97011-H34307 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34308 | 97011-H34308 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34309 | 97011-H34309 | \$ 73.00 | 10% | \$66.19 |

| | | | | |
|----------------------|--------------|----------|-----|---------|
| EW NBD ONSITE H34310 | 97011-H34310 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34311 | 97011-H34311 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34312 | 97011-H34312 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34313 | 97011-H34313 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34314 | 97011-H34314 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34315 | 97011-H34315 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34316 | 97011-H34316 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34317 | 97011-H34317 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34318 | 97011-H34318 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34319 | 97011-H34319 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34320 | 97011-H34320 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34321 | 97011-H34321 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34322 | 97011-H34322 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34323 | 97011-H34323 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34324 | 97011-H34324 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34325 | 97011-H34325 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34326 | 97011-H34326 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34327 | 97011-H34327 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34328 | 97011-H34328 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34329 | 97011-H34329 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34330 | 97011-H34330 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34331 | 97011-H34331 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34332 | 97011-H34332 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34333 | 97011-H34333 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34334 | 97011-H34334 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34335 | 97011-H34335 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34336 | 97011-H34336 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34337 | 97011-H34337 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34338 | 97011-H34338 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34339 | 97011-H34339 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34340 | 97011-H34340 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34341 | 97011-H34341 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34342 | 97011-H34342 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34343 | 97011-H34343 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34344 | 97011-H34344 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34345 | 97011-H34345 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34346 | 97011-H34346 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34347 | 97011-H34347 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34348 | 97011-H34348 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34349 | 97011-H34349 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34350 | 97011-H34350 | \$ 73.00 | 10% | \$66.19 |
| EW NBD ONSITE H34351 | 97011-H34351 | \$ 73.00 | 10% | \$66.19 |

| | | | | |
|----------------------|--------------|-----------|-----|-----------------|
| EW NBD ONSITE H34352 | 97011-H34352 | \$ 73.00 | 10% | <i>\$66.19</i> |
| EW NBD ONSITE H34353 | 97011-H34353 | \$ 73.00 | 10% | <i>\$66.19</i> |
| EW NBD ONSITE H34354 | 97011-H34354 | \$ 73.00 | 10% | <i>\$66.19</i> |
| EW NBD ONSITE H34355 | 97011-H34355 | \$ 73.00 | 10% | <i>\$66.19</i> |
| EW NBD ONSITE H34403 | 97011-H34403 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34404 | 97011-H34404 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34405 | 97011-H34405 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34406 | 97011-H34406 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34407 | 97011-H34407 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34408 | 97011-H34408 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34409 | 97011-H34409 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34410 | 97011-H34410 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34411 | 97011-H34411 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34412 | 97011-H34412 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34413 | 97011-H34413 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34414 | 97011-H34414 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34415 | 97011-H34415 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34416 | 97011-H34416 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34417 | 97011-H34417 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34418 | 97011-H34418 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34419 | 97011-H34419 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34420 | 97011-H34420 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34421 | 97011-H34421 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34422 | 97011-H34422 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34423 | 97011-H34423 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34424 | 97011-H34424 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34425 | 97011-H34425 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34426 | 97011-H34426 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34427 | 97011-H34427 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34428 | 97011-H34428 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34429 | 97011-H34429 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34430 | 97011-H34430 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34431 | 97011-H34431 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34432 | 97011-H34432 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34433 | 97011-H34433 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34434 | 97011-H34434 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34435 | 97011-H34435 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34436 | 97011-H34436 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34437 | 97011-H34437 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34438 | 97011-H34438 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34439 | 97011-H34439 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34440 | 97011-H34440 | \$ 175.00 | 10% | <i>\$158.68</i> |

| | | | | |
|----------------------|--------------|-----------|-----|-----------------|
| EW NBD ONSITE H34441 | 97011-H34441 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34442 | 97011-H34442 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34443 | 97011-H34443 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34444 | 97011-H34444 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34445 | 97011-H34445 | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW NBD ONSITE H34446 | 97011-H34446 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34447 | 97011-H34447 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34448 | 97011-H34448 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34449 | 97011-H34449 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34450 | 97011-H34450 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34451 | 97011-H34451 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34452 | 97011-H34452 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34453 | 97011-H34453 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34454 | 97011-H34454 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34455 | 97011-H34455 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34456 | 97011-H34456 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34457 | 97011-H34457 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34458 | 97011-H34458 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34459 | 97011-H34459 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34460 | 97011-H34460 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34461 | 97011-H34461 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34462 | 97011-H34462 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34463 | 97011-H34463 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34464 | 97011-H34464 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34465 | 97011-H34465 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34466 | 97011-H34466 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34467 | 97011-H34467 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34468 | 97011-H34468 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34469 | 97011-H34469 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34470 | 97011-H34470 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34471 | 97011-H34471 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34472 | 97011-H34472 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34473 | 97011-H34473 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34474 | 97011-H34474 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34475 | 97011-H34475 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34476 | 97011-H34476 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34477 | 97011-H34477 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34478 | 97011-H34478 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34479 | 97011-H34479 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34480 | 97011-H34480 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34481 | 97011-H34481 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34482 | 97011-H34482 | \$ 204.00 | 10% | <i>\$184.98</i> |

| | | | | |
|----------------------|--------------|-----------|-----|-----------------|
| EW NBD ONSITE H34483 | 97011-H34483 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34484 | 97011-H34484 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34485 | 97011-H34485 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34486 | 97011-H34486 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34487 | 97011-H34487 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34488 | 97011-H34488 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34489 | 97011-H34489 | \$ 204.00 | 10% | <i>\$184.98</i> |
| EW NBD ONSITE H34490 | 97011-H34490 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34491 | 97011-H34491 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34492 | 97011-H34492 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34493 | 97011-H34493 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34494 | 97011-H34494 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34495 | 97011-H34495 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34496 | 97011-H34496 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34497 | 97011-H34497 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34498 | 97011-H34498 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34499 | 97011-H34499 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34500 | 97011-H34500 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34501 | 97011-H34501 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34502 | 97011-H34502 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34503 | 97011-H34503 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34504 | 97011-H34504 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34505 | 97011-H34505 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34506 | 97011-H34506 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34507 | 97011-H34507 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34508 | 97011-H34508 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34509 | 97011-H34509 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34510 | 97011-H34510 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34511 | 97011-H34511 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34512 | 97011-H34512 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34513 | 97011-H34513 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34514 | 97011-H34514 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34515 | 97011-H34515 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34516 | 97011-H34516 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34517 | 97011-H34517 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34518 | 97011-H34518 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34519 | 97011-H34519 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34520 | 97011-H34520 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34521 | 97011-H34521 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34522 | 97011-H34522 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34523 | 97011-H34523 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW NBD ONSITE H34524 | 97011-H34524 | \$ 29.00 | 10% | <i>\$26.30</i> |

| | | | | |
|----------------------|--------------|----------|-----|---------|
| EW NBD ONSITE H34525 | 97011-H34525 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34526 | 97011-H34526 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34527 | 97011-H34527 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34528 | 97011-H34528 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34529 | 97011-H34529 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34530 | 97011-H34530 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34531 | 97011-H34531 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34532 | 97011-H34532 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34533 | 97011-H34533 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34534 | 97011-H34534 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34535 | 97011-H34535 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34536 | 97011-H34536 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34537 | 97011-H34537 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34538 | 97011-H34538 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34539 | 97011-H34539 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34540 | 97011-H34540 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34541 | 97011-H34541 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34542 | 97011-H34542 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34543 | 97011-H34543 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34544 | 97011-H34544 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34545 | 97011-H34545 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34546 | 97011-H34546 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34547 | 97011-H34547 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34548 | 97011-H34548 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34549 | 97011-H34549 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34550 | 97011-H34550 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34551 | 97011-H34551 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34552 | 97011-H34552 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34553 | 97011-H34553 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34554 | 97011-H34554 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34555 | 97011-H34555 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34556 | 97011-H34556 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34557 | 97011-H34557 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34558 | 97011-H34558 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34559 | 97011-H34559 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34560 | 97011-H34560 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34561 | 97011-H34561 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34562 | 97011-H34562 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34563 | 97011-H34563 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34564 | 97011-H34564 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34565 | 97011-H34565 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34566 | 97011-H34566 | \$ 29.00 | 10% | \$26.30 |

| | | | | |
|----------------------|--------------|----------|-----|---------|
| EW NBD ONSITE H34567 | 97011-H34567 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34568 | 97011-H34568 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34569 | 97011-H34569 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34570 | 97011-H34570 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34571 | 97011-H34571 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34572 | 97011-H34572 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34573 | 97011-H34573 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34574 | 97011-H34574 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34575 | 97011-H34575 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34576 | 97011-H34576 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34577 | 97011-H34577 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34578 | 97011-H34578 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34579 | 97011-H34579 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34580 | 97011-H34580 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34581 | 97011-H34581 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34582 | 97011-H34582 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34583 | 97011-H34583 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34584 | 97011-H34584 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34585 | 97011-H34585 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34586 | 97011-H34586 | \$ 29.00 | 10% | \$26.30 |
| EW NBD ONSITE H34587 | 97011-H34587 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34588 | 97011-H34588 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34589 | 97011-H34589 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34590 | 97011-H34590 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34591 | 97011-H34591 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34592 | 97011-H34592 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34593 | 97011-H34593 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34594 | 97011-H34594 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34595 | 97011-H34595 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34596 | 97011-H34596 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34597 | 97011-H34597 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34598 | 97011-H34598 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34599 | 97011-H34599 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34600 | 97011-H34600 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34601 | 97011-H34601 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34602 | 97011-H34602 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34603 | 97011-H34603 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34604 | 97011-H34604 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34605 | 97011-H34605 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34606 | 97011-H34606 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34607 | 97011-H34607 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34608 | 97011-H34608 | \$ 78.00 | 10% | \$70.73 |

| | | | | |
|----------------------|--------------|----------|-----|---------|
| EW NBD ONSITE H34609 | 97011-H34609 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34610 | 97011-H34610 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34611 | 97011-H34611 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34612 | 97011-H34612 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34613 | 97011-H34613 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34614 | 97011-H34614 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34615 | 97011-H34615 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34616 | 97011-H34616 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34617 | 97011-H34617 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34618 | 97011-H34618 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34619 | 97011-H34619 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34620 | 97011-H34620 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34621 | 97011-H34621 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34622 | 97011-H34622 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34623 | 97011-H34623 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34624 | 97011-H34624 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34625 | 97011-H34625 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34626 | 97011-H34626 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34627 | 97011-H34627 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34628 | 97011-H34628 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34629 | 97011-H34629 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34630 | 97011-H34630 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34631 | 97011-H34631 | \$ 78.00 | 10% | \$70.73 |
| EW NBD ONSITE H34632 | 97011-H34632 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34633 | 97011-H34633 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34634 | 97011-H34634 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34635 | 97011-H34635 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34636 | 97011-H34636 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34637 | 97011-H34637 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34638 | 97011-H34638 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34639 | 97011-H34639 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34640 | 97011-H34640 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34641 | 97011-H34641 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34642 | 97011-H34642 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34643 | 97011-H34643 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34644 | 97011-H34644 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34645 | 97011-H34645 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34646 | 97011-H34646 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34647 | 97011-H34647 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34648 | 97011-H34648 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34649 | 97011-H34649 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34650 | 97011-H34650 | \$ 84.00 | 10% | \$76.17 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW NBD ONSITE H34651 | 97011-H34651 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34652 | 97011-H34652 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34653 | 97011-H34653 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34654 | 97011-H34654 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34655 | 97011-H34655 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34656 | 97011-H34656 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34657 | 97011-H34657 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34658 | 97011-H34658 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34659 | 97011-H34659 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34660 | 97011-H34660 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34661 | 97011-H34661 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34662 | 97011-H34662 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34663 | 97011-H34663 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34664 | 97011-H34664 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34665 | 97011-H34665 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34666 | 97011-H34666 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34667 | 97011-H34667 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34668 | 97011-H34668 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34669 | 97011-H34669 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34670 | 97011-H34670 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34671 | 97011-H34671 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34672 | 97011-H34672 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34673 | 97011-H34673 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34674 | 97011-H34674 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34675 | 97011-H34675 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34676 | 97011-H34676 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34677 | 97011-H34677 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34678 | 97011-H34678 | \$ 84.00 | 10% | \$76.17 |
| EW NBD ONSITE H34726 | 97011-H34726 | \$ 2,457.00 | 10% | \$2,227.88 |
| EW NBD ONSITE H34727 | 97011-H34727 | \$ 2,457.00 | 10% | \$2,227.88 |
| EW NBD ONSITE H34728 | 97011-H34728 | \$ 2,457.00 | 10% | \$2,227.88 |
| EW NBD ONSITE H34729 | 97011-H34729 | \$ 2,457.00 | 10% | \$2,227.88 |
| EW NBD ONSITE H34730 | 97011-H34730 | \$ 2,637.00 | 10% | \$2,391.10 |
| EW NBD ONSITE H34731 | 97011-H34731 | \$ 2,637.00 | 10% | \$2,391.10 |
| EW NBD ONSITE H34732 | 97011-H34732 | \$ 2,637.00 | 10% | \$2,391.10 |
| EW NBD ONSITE H34733 | 97011-H34733 | \$ 2,637.00 | 10% | \$2,391.10 |
| EW NBD ONSITE H34734 | 97011-H34734 | \$ 383.00 | 10% | \$347.29 |
| EW NBD ONSITE H34735 | 97011-H34735 | \$ 383.00 | 10% | \$347.29 |
| EW NBD ONSITE H34736 | 97011-H34736 | \$ 484.00 | 10% | \$438.87 |
| EW NBD ONSITE H34737 | 97011-H34737 | \$ 484.00 | 10% | \$438.87 |
| EW NBD ONSITE H34738 | 97011-H34738 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34739 | 97011-H34739 | \$ 917.00 | 10% | \$831.49 |

| | | | | |
|----------------------|--------------|--------------|-----|-------------|
| EW NBD ONSITE H34740 | 97011-H34740 | \$ 383.00 | 10% | \$347.29 |
| EW NBD ONSITE H34741 | 97011-H34741 | \$ 383.00 | 10% | \$347.29 |
| EW NBD ONSITE H34742 | 97011-H34742 | \$ 290.00 | 10% | \$262.96 |
| EW NBD ONSITE H34743 | 97011-H34743 | \$ 290.00 | 10% | \$262.96 |
| EW NBD ONSITE H34744 | 97011-H34744 | \$ 482.00 | 10% | \$437.05 |
| EW NBD ONSITE H34745 | 97011-H34745 | \$ 482.00 | 10% | \$437.05 |
| EW NBD ONSITE H34746 | 97011-H34746 | \$ 546.00 | 10% | \$495.09 |
| EW NBD ONSITE H34747 | 97011-H34747 | \$ 546.00 | 10% | \$495.09 |
| EW NBD ONSITE H34748 | 97011-H34748 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34749 | 97011-H34749 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34750 | 97011-H34750 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34751 | 97011-H34751 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34752 | 97011-H34752 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34753 | 97011-H34753 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34754 | 97011-H34754 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34755 | 97011-H34755 | \$ 917.00 | 10% | \$831.49 |
| EW NBD ONSITE H34756 | 97011-H34756 | \$ 484.00 | 10% | \$438.87 |
| EW NBD ONSITE H34757 | 97011-H34757 | \$ 484.00 | 10% | \$438.87 |
| EW NBD ONSITE H34758 | 97011-H34758 | \$ 482.00 | 10% | \$437.05 |
| EW NBD ONSITE H34759 | 97011-H34759 | \$ 484.00 | 10% | \$438.87 |
| EW NBD ONSITE H34760 | 97011-H34760 | \$ 484.00 | 10% | \$438.87 |
| EW NBD ONSITE H34761 | 97011-H34761 | \$ 482.00 | 10% | \$437.05 |
| EW NBD ONSITE H34839 | 97011-H34839 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34840 | 97011-H34840 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34841 | 97011-H34841 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34842 | 97011-H34842 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34843 | 97011-H34843 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34844 | 97011-H34844 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34845 | 97011-H34845 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34846 | 97011-H34846 | \$ 264.00 | 10% | \$239.38 |
| EW NBD ONSITE H34993 | 97011-H34993 | \$ 12,586.00 | 10% | \$11,412.36 |
| EW NBD ONSITE H34994 | 97011-H34994 | \$ 12,586.00 | 10% | \$11,412.36 |
| EW NBD ONSITE H34996 | 97011-H34996 | \$ 12,586.00 | 10% | \$11,412.36 |
| EW NBD ONSITE H34997 | 97011-H34997 | \$ 12,586.00 | 10% | \$11,412.36 |
| EW NBD ONSITE H35005 | 97011-H35005 | \$ 9,386.00 | 10% | \$8,510.76 |
| EW NBD ONSITE H35006 | 97011-H35006 | \$ 9,386.00 | 10% | \$8,510.76 |
| EW NBD ONSITE H35012 | 97011-H35012 | \$ 5,656.00 | 10% | \$5,128.58 |
| EW NBD ONSITE H35070 | 97011-H35070 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H35071 | 97011-H35071 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H35072 | 97011-H35072 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H35073 | 97011-H35073 | \$ 45.00 | 10% | \$40.80 |
| EW NBD ONSITE H35074 | 97011-H35074 | \$ 45.00 | 10% | \$40.80 |

| | | | | |
|----------------------|--------------|--------------|-----|--------------------|
| EW NBD ONSITE H35075 | 97011-H35075 | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE H35076 | 97011-H35076 | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE H35077 | 97011-H35077 | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE H35078 | 97011-H35078 | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE H35079 | 97011-H35079 | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW NBD ONSITE H35080 | 97011-H35080 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD ONSITE H35081 | 97011-H35081 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD ONSITE H35082 | 97011-H35082 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD ONSITE H35083 | 97011-H35083 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW NBD ONSITE H35084 | 97011-H35084 | \$ 9,600.00 | 10% | <i>\$8,704.80</i> |
| EW NBD ONSITE H35085 | 97011-H35085 | \$ 14,406.00 | 10% | <i>\$13,062.64</i> |
| EW NBD ONSITE H35086 | 97011-H35086 | \$ 21,041.00 | 10% | <i>\$19,078.93</i> |
| EW NBD ONSITE H35087 | 97011-H35087 | \$ 2,102.00 | 10% | <i>\$1,905.99</i> |
| EW NBD ONSITE H35088 | 97011-H35088 | \$ 4,204.00 | 10% | <i>\$3,811.98</i> |
| EW NBD ONSITE H35089 | 97011-H35089 | \$ 21,041.00 | 10% | <i>\$19,078.93</i> |
| EW NBD ONSITE H35092 | 97011-H35092 | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW NBD ONSITE H35093 | 97011-H35093 | \$ 7,141.00 | 10% | <i>\$6,475.10</i> |
| EW NBD ONSITE H35094 | 97011-H35094 | \$ 3,962.00 | 10% | <i>\$3,592.54</i> |
| EW NBD ONSITE H35270 | 97011-H35270 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW NBD ONSITE H35271 | 97011-H35271 | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW NBD ONSITE H35273 | 97011-H35273 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW NBD ONSITE H35274 | 97011-H35274 | \$ 548.00 | 10% | <i>\$496.90</i> |
| EW NBD ONSITE H35275 | 97011-H35275 | \$ 428.00 | 10% | <i>\$388.09</i> |
| EW NBD ONSITE H35276 | 97011-H35276 | \$ 2,364.00 | 10% | <i>\$2,143.56</i> |
| EW NBD ONSITE H35277 | 97011-H35277 | \$ 2,832.00 | 10% | <i>\$2,567.92</i> |
| EW NBD ONSITE H35278 | 97011-H35278 | \$ 2,048.00 | 10% | <i>\$1,857.02</i> |
| EW NBD ONSITE H35279 | 97011-H35279 | \$ 2,288.00 | 10% | <i>\$2,074.64</i> |
| EW NBD ONSITE H35280 | 97011-H35280 | \$ 3,327.00 | 10% | <i>\$3,016.76</i> |
| EW NBD ONSITE H35281 | 97011-H35281 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35282 | 97011-H35282 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35283 | 97011-H35283 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35284 | 97011-H35284 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35285 | 97011-H35285 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35286 | 97011-H35286 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35287 | 97011-H35287 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35288 | 97011-H35288 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW NBD ONSITE H35289 | 97011-H35289 | \$ 4,366.00 | 10% | <i>\$3,958.87</i> |
| EW NBD ONSITE H35291 | 97011-H35291 | \$ 3,303.00 | 10% | <i>\$2,995.00</i> |
| EW NBD ONSITE H35292 | 97011-H35292 | \$ 2,048.00 | 10% | <i>\$1,857.02</i> |
| EW NBD ONSITE H35293 | 97011-H35293 | \$ 2,288.00 | 10% | <i>\$2,074.64</i> |
| EW NBD ONSITE H35295 | 97011-H35295 | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW NBD ONSITE H35296 | 97011-H35296 | \$ 6,373.00 | 10% | <i>\$5,778.72</i> |

| | | | | |
|----------------------|--------------|--------------|-----|------------|
| EW NBD ONSITE H35297 | 97011-H35297 | \$ 6,372.00 | 10% | \$5,777.81 |
| EW NBD ONSITE H35298 | 97011-H35298 | \$ 10,238.00 | 10% | \$9,283.31 |
| EW NBD ONSITE H35299 | 97011-H35299 | \$ 10,238.00 | 10% | \$9,283.31 |
| EW NBD ONSITE H35302 | 97011-H35302 | \$ 2,471.00 | 10% | \$2,240.58 |
| EW NBD ONSITE H35303 | 97011-H35303 | \$ 2,471.00 | 10% | \$2,240.58 |
| EW NBD ONSITE H35304 | 97011-H35304 | \$ 2,471.00 | 10% | \$2,240.58 |
| EW NBD ONSITE H35305 | 97011-H35305 | \$ 2,586.00 | 10% | \$2,344.86 |
| EW NBD ONSITE H35306 | 97011-H35306 | \$ 2,586.00 | 10% | \$2,344.86 |
| EW NBD ONSITE H35307 | 97011-H35307 | \$ 2,586.00 | 10% | \$2,344.86 |
| EW NBD ONSITE H35309 | 97011-H35309 | \$ 3,177.00 | 10% | \$2,880.74 |
| EW NBD ONSITE H35310 | 97011-H35310 | \$ 3,177.00 | 10% | \$2,880.74 |
| EW NBD ONSITE H35311 | 97011-H35311 | \$ 3,177.00 | 10% | \$2,880.74 |
| EW NBD ONSITE H35312 | 97011-H35312 | \$ 2,626.00 | 10% | \$2,381.13 |
| EW NBD ONSITE H35313 | 97011-H35313 | \$ 2,625.00 | 10% | \$2,380.22 |
| EW NBD ONSITE H35314 | 97011-H35314 | \$ 2,625.00 | 10% | \$2,380.22 |
| EW NBD ONSITE H35315 | 97011-H35315 | \$ 1,120.00 | 10% | \$1,015.56 |
| EW NBD ONSITE H35318 | 97011-H35318 | \$ 541.00 | 10% | \$490.55 |
| EW NBD ONSITE H35319 | 97011-H35319 | \$ 713.00 | 10% | \$646.51 |
| EW NBD ONSITE H35320 | 97011-H35320 | \$ 755.00 | 10% | \$684.60 |
| EW NBD ONSITE H35321 | 97011-H35321 | \$ 942.00 | 10% | \$854.16 |
| EW NBD ONSITE H35322 | 97011-H35322 | \$ 1,144.00 | 10% | \$1,037.32 |
| EW NBD ONSITE H35323 | 97011-H35323 | \$ 1,120.00 | 10% | \$1,015.56 |
| EW NBD ONSITE H35328 | 97011-H35328 | \$ 97.00 | 10% | \$87.95 |
| EW NBD ONSITE H35330 | 97011-H35330 | \$ 70.00 | 10% | \$63.47 |
| EW NBD ONSITE H35340 | 97011-H35340 | \$ 2,672.00 | 10% | \$2,422.84 |
| EW NBD ONSITE H35341 | 97011-H35341 | \$ 2,672.00 | 10% | \$2,422.84 |
| EW NBD ONSITE H35342 | 97011-H35342 | \$ 2,361.00 | 10% | \$2,140.84 |
| EW NBD ONSITE H35343 | 97011-H35343 | \$ 2,672.00 | 10% | \$2,422.84 |
| EW NBD ONSITE H35344 | 97011-H35344 | \$ 2,789.00 | 10% | \$2,528.93 |
| EW NBD ONSITE H35345 | 97011-H35345 | \$ 2,789.00 | 10% | \$2,528.93 |
| EW NBD ONSITE H35346 | 97011-H35346 | \$ 2,449.00 | 10% | \$2,220.63 |
| EW NBD ONSITE H35347 | 97011-H35347 | \$ 2,789.00 | 10% | \$2,528.93 |
| EW NBD ONSITE H35349 | 97011-H35349 | \$ 3,070.00 | 10% | \$2,783.72 |
| EW NBD ONSITE H35350 | 97011-H35350 | \$ 3,070.00 | 10% | \$2,783.72 |
| EW NBD ONSITE H35351 | 97011-H35351 | \$ 2,678.00 | 10% | \$2,428.28 |
| EW NBD ONSITE H35352 | 97011-H35352 | \$ 3,070.00 | 10% | \$2,783.72 |
| EW NBD ONSITE H35359 | 97011-H35359 | \$ 942.00 | 10% | \$854.16 |
| EW NBD ONSITE H35360 | 97011-H35360 | \$ 1,144.00 | 10% | \$1,037.32 |
| EW NBD ONSITE H35361 | 97011-H35361 | \$ 1,120.00 | 10% | \$1,015.56 |
| EW NBD ONSITE H35362 | 97011-H35362 | \$ 541.00 | 10% | \$490.55 |
| EW NBD ONSITE H35366 | 97011-H35366 | \$ 1,346.00 | 10% | \$1,220.49 |
| EW NBD ONSITE H35367 | 97011-H35367 | \$ 1,567.00 | 10% | \$1,420.88 |

| | | | | |
|----------------------|--------------|-------------|-----|------------|
| EW NBD ONSITE H35368 | 97011-H35368 | \$ 2,390.00 | 10% | \$2,167.13 |
| EW NBD ONSITE H35369 | 97011-H35369 | \$ 780.00 | 10% | \$707.27 |
| EW NBD ONSITE H35370 | 97011-H35370 | \$ 1,092.00 | 10% | \$990.17 |
| EW NBD ONSITE H35375 | 97011-H35375 | \$ 655.00 | 10% | \$593.92 |
| EW NBD ONSITE H35376 | 97011-H35376 | \$ 986.00 | 10% | \$894.06 |
| EW NBD ONSITE H35377 | 97011-H35377 | \$ 413.00 | 10% | \$374.49 |
| EW NBD ONSITE H35378 | 97011-H35378 | \$ 655.00 | 10% | \$593.92 |
| EW NBD ONSITE H35379 | 97011-H35379 | \$ 413.00 | 10% | \$374.49 |
| EW NBD ONSITE H35380 | 97011-H35380 | \$ 737.00 | 10% | \$668.27 |
| EW NBD ONSITE H35381 | 97011-H35381 | \$ 904.00 | 10% | \$819.70 |
| EW NBD ONSITE H35384 | 97011-H35384 | \$ 299.00 | 10% | \$271.12 |
| EW NBD ONSITE H35385 | 97011-H35385 | \$ 395.00 | 10% | \$358.17 |
| EW NBD ONSITE H35386 | 97011-H35386 | \$ 655.00 | 10% | \$593.92 |
| EW NBD ONSITE H35387 | 97011-H35387 | \$ 613.00 | 10% | \$555.84 |
| EW NBD ONSITE H35388 | 97011-H35388 | \$ 453.00 | 10% | \$410.76 |
| EW NBD ONSITE H35389 | 97011-H35389 | \$ 256.00 | 10% | \$232.13 |
| EW NBD ONSITE H35390 | 97011-H35390 | \$ 221.00 | 10% | \$200.39 |
| EW NBD ONSITE H35391 | 97011-H35391 | \$ 482.00 | 10% | \$437.05 |
| EW NBD ONSITE H35392 | 97011-H35392 | \$ 737.00 | 10% | \$668.27 |
| EW NBD ONSITE H35393 | 97011-H35393 | \$ 986.00 | 10% | \$894.06 |
| EW NBD ONSITE H35394 | 97011-H35394 | \$ 179.00 | 10% | \$162.31 |
| EW NBD ONSITE H35395 | 97011-H35395 | \$ 152.00 | 10% | \$137.83 |
| EW NBD ONSITE H35396 | 97011-H35396 | \$ 179.00 | 10% | \$162.31 |
| EW NBD ONSITE H35397 | 97011-H35397 | \$ 152.00 | 10% | \$137.83 |
| EW NBD ONSITE H35398 | 97011-H35398 | \$ 458.00 | 10% | \$415.29 |
| EW NBD ONSITE H35399 | 97011-H35399 | \$ 560.00 | 10% | \$507.78 |
| EW NBD ONSITE H35400 | 97011-H35400 | \$ 616.00 | 10% | \$558.56 |
| EW NBD ONSITE H35401 | 97011-H35401 | \$ 331.00 | 10% | \$300.13 |
| EW NBD ONSITE H35415 | 97011-H35415 | \$ 227.00 | 10% | \$205.83 |
| EW NBD ONSITE H35416 | 97011-H35416 | \$ 227.00 | 10% | \$205.83 |
| EW NBD ONSITE H35426 | 97011-H35426 | \$ 256.00 | 10% | \$232.13 |
| EW NBD ONSITE H35427 | 97011-H35427 | \$ 613.00 | 10% | \$555.84 |
| EW NBD ONSITE H35428 | 97011-H35428 | \$ 221.00 | 10% | \$200.39 |
| EW NBD ONSITE H35429 | 97011-H35429 | \$ 482.00 | 10% | \$437.05 |
| EW NBD ONSITE H35430 | 97011-H35430 | \$ 372.00 | 10% | \$337.31 |
| EW NBD ONSITE H35431 | 97011-H35431 | \$ 372.00 | 10% | \$337.31 |
| EW NBD ONSITE H35432 | 97011-H35432 | \$ 290.00 | 10% | \$262.96 |
| EW NBD ONSITE H35433 | 97011-H35433 | \$ 470.00 | 10% | \$426.17 |
| EW NBD ONSITE H35434 | 97011-H35434 | \$ 532.00 | 10% | \$482.39 |
| EW NBD ONSITE H35435 | 97011-H35435 | \$ 532.00 | 10% | \$482.39 |
| EW NBD ONSITE H35436 | 97011-H35436 | \$ 890.00 | 10% | \$807.01 |
| EW NBD ONSITE H35437 | 97011-H35437 | \$ 890.00 | 10% | \$807.01 |

| | | | | |
|------------------------------------|----------------------------|-------------|-----|-------------------|
| EW NBD ONSITE H35438 | 97011-H35438 | \$ 890.00 | 10% | <i>\$807.01</i> |
| EW NBD ONSITE H35439 | 97011-H35439 | \$ 890.00 | 10% | <i>\$807.01</i> |
| EW NBD ONSITE H35440 | 97011-H35440 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW NBD ONSITE H35441 | 97011-H35441 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW NBD ONSITE H35442 | 97011-H35442 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW NBD ONSITE H35443 | 97011-H35443 | \$ 2,457.00 | 10% | <i>\$2,227.88</i> |
| EW NBD ONSITE H35444 | 97011-H35444 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW NBD ONSITE H35445 | 97011-H35445 | \$ 2,364.00 | 10% | <i>\$2,143.56</i> |
| EW NBD ONSITE H35446 | 97011-H35446 | \$ 2,317.00 | 10% | <i>\$2,100.94</i> |
| EW NBD ONSITE H35447 | 97011-H35447 | \$ 2,683.00 | 10% | <i>\$2,432.81</i> |
| EW NBD ONSITE H35448 | 97011-H35448 | \$ 2,572.00 | 10% | <i>\$2,332.16</i> |
| EW NBD ONSITE H35449 | 97011-H35449 | \$ 2,048.00 | 10% | <i>\$1,857.02</i> |
| EW NBD ONSITE H35450 | 97011-H35450 | \$ 2,169.00 | 10% | <i>\$1,966.74</i> |
| EW NBD ONSITE H35451 | 97011-H35451 | \$ 3,521.00 | 10% | <i>\$3,192.67</i> |
| EW NBD ONSITE H35452 | 97011-H35452 | \$ 3,521.00 | 10% | <i>\$3,192.67</i> |
| EW NBD ONSITE H35453 | 97011-H35453 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW NBD ONSITE H35454 | 97011-H35454 | \$ 2,457.00 | 10% | <i>\$2,227.88</i> |
| EW NBD ONSITE H35455 | 97011-H35455 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW NBD ONSITE H35456 | 97011-H35456 | \$ 950.00 | 10% | <i>\$861.41</i> |
| EW NBD ONSITE H35457 | 97011-H35457 | \$ 850.00 | 10% | <i>\$770.74</i> |
| EW NBD ONSITE H35458 | 97011-H35458 | \$ 932.00 | 10% | <i>\$845.09</i> |
| EW NBD ONSITE H35471 | 97011-H35471 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW NBD ONSITE H35600 | 97011-H35600 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW NBD ONSITE H35601 | 97011-H35601 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW NBD ONSITE H35602 | 97011-H35602 | \$ 383.00 | 10% | <i>\$347.29</i> |
| EW NBD ONSITE H35603 | 97011-H35603 | \$ 383.00 | 10% | <i>\$347.29</i> |
| EW NBD ONSITE H35604 | 97011-H35604 | \$ 484.00 | 10% | <i>\$438.87</i> |
| EW NBD ONSITE H35605 | 97011-H35605 | \$ 484.00 | 10% | <i>\$438.87</i> |
| EW NBD ONSITE H35606 | 97011-H35606 | \$ 548.00 | 10% | <i>\$496.90</i> |
| EW NBD ONSITE H35607 | 97011-H35607 | \$ 546.00 | 10% | <i>\$495.09</i> |
| EW NBD ONSITE ipe-2000ax-LR-10G | 97011-ipe-2000ax-LR-10G | \$ 5,328.00 | 10% | <i>\$4,831.16</i> |
| EW NBD ONSITE ipe-2000ax-LR-10G-WP | 97011-ipe-2000ax-LR-10G-WP | \$ 5,328.00 | 10% | <i>\$4,831.16</i> |
| EW NBD ONSITE ipe-2000ax-Lx | 97011-ipe-2000ax-Lx | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |
| EW NBD ONSITE ipe-2000ax-Lx-WP | 97011-ipe-2000ax-Lx-WP | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |

| | | | | |
|------------------------------------|----------------------------|--------------|-----|--------------------|
| EW NBD ONSITE ipe-2000ax-SR-10G | 97011-ipe-2000ax-SR-10G | \$ 5,328.00 | 10% | <i>\$4,831.16</i> |
| EW NBD ONSITE ipe-2000ax-SR-10G-WP | 97011-ipe-2000ax-SR-10G-WP | \$ 5,328.00 | 10% | <i>\$4,831.16</i> |
| EW NBD ONSITE ipe-2000ax-Sx | 97011-ipe-2000ax-Sx | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |
| EW NBD ONSITE ipe-2000ax-Sx-WP | 97011-ipe-2000ax-Sx-WP | \$ 4,440.00 | 10% | <i>\$4,025.97</i> |
| EW NBD ONSITE ipe-2000ax-T | 97011-ipe-2000ax-T | \$ 3,907.00 | 10% | <i>\$3,542.67</i> |
| EW NBD ONSITE ipe-2000ax-T-WP | 97011-ipe-2000ax-T-WP | \$ 3,907.00 | 10% | <i>\$3,542.67</i> |
| EW NBD ONSITE ipe-30ax | 97011-ipe-30ax | \$ 168.00 | 10% | <i>\$152.33</i> |
| EW NBD ONSITE ipe-30ax-WP | 97011-ipe-30ax-WP | \$ 168.00 | 10% | <i>\$152.33</i> |
| EW NBD ONSITE ipe-30so | 97011-ipe-30so | \$ 139.00 | 10% | <i>\$126.04</i> |
| EW NBD ONSITE ipe-30so-WP | 97011-ipe-30so-WP | \$ 139.00 | 10% | <i>\$126.04</i> |
| EW NBD ONSITE ipe-4000ax-10Lr-10G | 97011-ipe-4000ax-10Lr-10G | \$ 17,580.00 | 10% | <i>\$15,940.67</i> |
| EW NBD ONSITE ipe-4000ax-10Lr-3.5G | 97011-ipe-4000ax-10Lr-3.5G | \$ 9,911.00 | 10% | <i>\$8,986.80</i> |
| EW NBD ONSITE ipe-4000ax-10Lr-7G | 97011-ipe-4000ax-10Lr-7G | \$ 14,207.00 | 10% | <i>\$12,882.20</i> |
| EW NBD ONSITE ipe-4000ax-10Sr-10G | 97011-ipe-4000ax-10Sr-10G | \$ 17,402.00 | 10% | <i>\$15,779.26</i> |
| EW NBD ONSITE ipe-4000ax-10Sr-3.5G | 97011-ipe-4000ax-10Sr-3.5G | \$ 5,399.00 | 10% | <i>\$4,895.54</i> |
| EW NBD ONSITE ipe-4000ax-10Sr-7G | 97011-ipe-4000ax-10Sr-7G | \$ 14,029.00 | 10% | <i>\$12,720.80</i> |
| EW NBD ONSITE ipe-4000ax-20Lr-10G | 97011-ipe-4000ax-20Lr-10G | \$ 21,131.00 | 10% | <i>\$19,160.53</i> |

| | | | | |
|-----------------------------------|---------------------------|--------------|-----|-------------|
| EW NBD ONSITE ipe-4000ax-20Lr-14G | 97011-ipe-4000ax-20Lr-14G | \$ 24,682.00 | 10% | \$22,380.40 |
| EW NBD ONSITE ipe-4000ax-20Lr-20G | 97011-ipe-4000ax-20Lr-20G | \$ 31,607.00 | 10% | \$28,659.65 |
| EW NBD ONSITE ipe-4000ax-20Lr-7G | 97011-ipe-4000ax-20Lr-7G | \$ 17,580.00 | 10% | \$15,940.67 |
| EW NBD ONSITE ipe-4000ax-20Sr-10G | 97011-ipe-4000ax-20Sr-10G | \$ 20,954.00 | 10% | \$19,000.04 |
| EW NBD ONSITE ipe-4000ax-20Sr-14G | 97011-ipe-4000ax-20Sr-14G | \$ 24,505.00 | 10% | \$22,219.91 |
| EW NBD ONSITE ipe-4000ax-20Sr-20G | 97011-ipe-4000ax-20Sr-20G | \$ 31,432.00 | 10% | \$28,500.97 |
| EW NBD ONSITE ipe-4000ax-20Sr-7G | 97011-ipe-4000ax-20Sr-7G | \$ 17,402.00 | 10% | \$15,779.26 |
| EW NBD ONSITE ipe-4002ax | 97011-ipe-4002ax | \$ 3,374.00 | 10% | \$3,059.37 |
| EW NBD ONSITE ipe-400ax | 97011-ipe-400ax | \$ 862.00 | 10% | \$781.62 |
| EW NBD ONSITE ipe-400ax-WP | 97011-ipe-400ax-WP | \$ 862.00 | 10% | \$781.62 |
| EW NBD ONSITE ipe-40ax | 97011-ipe-40ax | \$ 331.00 | 10% | \$300.13 |
| EW NBD ONSITE ipe-40ax-V2 | 97011-ipe-40ax-V2 | \$ 392.00 | 10% | \$355.45 |
| EW NBD ONSITE ipe-40ax-V2-WP | 97011-ipe-40ax-V2-WP | \$ 39.00 | 10% | \$35.36 |
| EW NBD ONSITE ipe-40so | 97011-ipe-40so | \$ 226.00 | 10% | \$204.93 |
| EW NBD ONSITE ipe-40so-V2 | 97011-ipe-40so-V2 | \$ 266.00 | 10% | \$241.20 |
| EW NBD ONSITE ipe-40so-V2-WP | 97011-ipe-40so-V2-WP | \$ 266.00 | 10% | \$241.20 |
| EW NBD ONSITE ipe-420ax | 97011-ipe-420ax | \$ 959.00 | 10% | \$869.57 |
| EW NBD ONSITE ipe-420ax-WP | 97011-ipe-420ax-WP | \$ 959.00 | 10% | \$869.57 |
| EW NBD ONSITE ipr-4108Lr | 97011-ipr-4108Lr | \$ 3,730.00 | 10% | \$3,382.18 |

| | | | | |
|--------------------------------------|-----------------------------|-------------|-----|------------|
| EW NBD ONSITE ipr-4108Sr | 97011-ipr-4108Sr | \$ 3,551.00 | 10% | \$3,219.87 |
| EW NBD ONSITE ISD-ipe-2000ax-LR-10G | 97011-ISD-ipe-2000ax-LR-10G | \$ 3,382.00 | 10% | \$3,066.63 |
| EW NBD ONSITE ISD-ipe-2000ax-Lx | 97011-ISD-ipe-2000ax-Lx | \$ 2,537.00 | 10% | \$2,300.42 |
| EW NBD ONSITE ISD-ipe-2000ax-SR-10G | 97011-ISD-ipe-2000ax-SR-10G | \$ 3,382.00 | 10% | \$3,066.63 |
| EW NBD ONSITE ISD-ipe-2000ax-Sx | 97011-ISD-ipe-2000ax-Sx | \$ 2,537.00 | 10% | \$2,300.42 |
| EW NBD ONSITE ISD-ipe-2000ax-T | 97011-ISD-ipe-2000ax-T | \$ 1,861.00 | 10% | \$1,687.46 |
| EW NBD ONSITE XISD-IPE-2200AX-LR-10G | 97011-ISD-IPE-2200AX-LR-10G | \$ 3,382.00 | 10% | \$3,066.63 |
| EW NBD ONSITE ISD-IPE-2200AX-SR-10G | 97011-ISD-IPE-2200AX-SR-10G | \$ 3,382.00 | 10% | \$3,066.63 |
| EW NBD ONSITE ISD-IPE-2200AX-T | 97011-ISD-IPE-2200AX-T | \$ 1,861.00 | 10% | \$1,687.46 |
| EW NBD ONSITE ISD-ipe-30ax | 97011-ISD-ipe-30ax | \$ 158.00 | 10% | \$143.27 |
| EW NBD ONSITE ISD-ipe-30so | 97011-ISD-ipe-30so | \$ 125.00 | 10% | \$113.34 |
| EW NBD ONSITE ISD-ipe-400ax | 97011-ISD-ipe-400ax | \$ 787.00 | 10% | \$713.61 |
| EW NBD ONSITE ISD-ipe-40ax-V2 | 97011-ISD-ipe-40ax-V2 | \$ 346.00 | 10% | \$313.74 |
| EW NBD ONSITE ISD-ipe-40so-V2 | 97011-ISD-ipe-40so-V2 | \$ 237.00 | 10% | \$214.90 |
| EW NBD ONSITE ISD-ipe-420ax | 97011-ISD-ipe-420ax | \$ 795.00 | 10% | \$720.87 |
| EW NBD ONSITE ISW-24W-4X | 97011-ISW-24W-4X | \$ 794.00 | 10% | \$719.96 |
| EW NBD ONSITE ISW-4W-4WS-4X | 97011-ISW-4W-4WS-4X | \$ 504.00 | 10% | \$457.00 |
| EW NBD ONSITE BD MSM128 | 97011-MSM128 | \$ 2,907.00 | 10% | \$2,635.92 |
| EW NBD ONSITE BD MSM48C | 97011-MSM48C | \$ 1,725.00 | 10% | \$1,564.14 |

| | | | | |
|---------------------------------|-------------------------|--------------|-----|-------------|
| EW NBD ONSITE SLX9150-48XT-DC-F | 97011-SLX9150-48XT-DC-F | \$ 2,432.00 | 10% | \$2,205.22 |
| EW NBD ONSITE SLX9150-48XT-DC-R | 97011-SLX9150-48XT-DC-R | \$ 2,655.00 | 10% | \$2,407.42 |
| EW NBD ONSITE SLX9150-48Y-DC-F | 97011-SLX9150-48Y-DC-F | \$ 2,330.00 | 10% | \$2,112.73 |
| EW NBD ONSITE SLX9150-48Y-DC-R | 97011-SLX9150-48Y-DC-R | \$ 2,544.00 | 10% | \$2,306.77 |
| EW NBD ONSITE SLX9740-40C | 97011-SLX9740-40C | \$ 10,458.00 | 10% | \$9,482.79 |
| EW NBD ONSITE SLX9740-40C-AC-F | 97011-SLX9740-40C-AC-F | \$ 10,458.00 | 10% | \$9,482.79 |
| EW NBD ONSITE SLX9740-40C-AC-R | 97011-SLX9740-40C-AC-R | \$ 10,458.00 | 10% | \$9,482.79 |
| EW NBD ONSITE SLX9740-40C-DC-F | 97011-SLX9740-40C-DC-F | \$ 10,458.00 | 10% | \$9,482.79 |
| EW NBD ONSITE SLX9740-80C | 97011-SLX9740-80C | \$ 19,667.00 | 10% | \$17,833.05 |
| EW NBD ONSITE SLX9740-80C-AC-F | 97011-SLX9740-80C-AC-F | \$ 19,667.00 | 10% | \$17,833.05 |
| EW NBD ONSITE SLX9740-80C-AC-R | 97011-SLX9740-80C-AC-R | \$ 19,667.00 | 10% | \$17,833.05 |
| EW NBD ONSITE SLX9740-80C-DC-F | 97011-SLX9740-80C-DC-F | \$ 19,667.00 | 10% | \$17,833.05 |
| EW NBD ONSITE V300-8P-2X | 97011-V300-8P-2X | \$ 127.00 | 10% | \$115.16 |
| EW NBD ONSITE V300-8T-2X | 97011-V300-8T-2X | \$ 88.00 | 10% | \$79.79 |
| EW NBD ONSITE V300HT-8P-2X | 97011-V300HT-8P-2X | \$ 420.00 | 10% | \$380.84 |

| | | | | |
|-------------------------------------|-----------------------------|-------------|-----|----------|
| EW NBD ONSITE V300HT-8T-2X | 97011-V300HT-8T-2X | \$ 251.00 | 10% | \$227.59 |
| EW NBD ONSITE Summit VIM-SS | 97011-VIM-SS | \$ 145.00 | 10% | \$131.48 |
| EW NBD ONSITE Summit VIM-SSV80 | 97011-VIM-SSV80 | \$ 270.00 | 10% | \$244.82 |
| EW NBD ONSITE Summit VIM2-SS | 97011-VIM2-SS | \$ 168.00 | 10% | \$152.33 |
| EW NBD ONSITE Summit VIM2-SS128 | 97011-VIM2-SS128 | \$ 586.00 | 10% | \$531.36 |
| EW NBD ONSITE Summit VIM2-V80 | 97011-VIM2-V80 | \$ 626.00 | 10% | \$567.63 |
| EW NBD ONSITE Summit VIM210G4X | 97011-VIM210G4X | \$ 1,087.00 | 10% | \$985.64 |
| EW NBD ONSITE VIM5-2Q | 97011-VIM5-2Q | \$ 182.00 | 10% | \$165.03 |
| EW NBD ONSITE VIM5-2Y | 97011-VIM5-2Y | \$ 216.00 | 10% | \$195.86 |
| EW NBD ONSITE VIM5-4X | 97011-VIM5-4X | \$ 94.00 | 10% | \$85.23 |
| EW NBD ONSITE VIM5-4XE | 97011-VIM5-4XE | \$ 177.00 | 10% | \$160.49 |
| EW NBD ONSITE VIM5-4Y | 97011-VIM5-4Y | \$ 276.00 | 10% | \$250.26 |
| EW NBD ONSITE VIM5-4YE | 97011-VIM5-4YE | \$ 356.00 | 10% | \$322.80 |
| EW NBD ONSITE VSP4900-12MXU-12XE | 97011-VSP4900-12MXU-12XE | \$ 988.00 | 10% | \$895.87 |
| EW NBD ONSITE VSP4900-12MXU-12XE-B1 | 97011-VSP4900-12MXU-12XE-B1 | \$ 988.00 | 10% | \$895.87 |
| EW NBD ONSITE VSP4900-24S | 97011-VSP4900-24S | \$ 541.00 | 10% | \$490.55 |
| EW NBD ONSITE VSP4900-24S-B3 | 97011-VSP4900-24S-B3 | \$ 541.00 | 10% | \$490.55 |
| EW NBD ONSITE VSP4900-24XE | 97011-VSP4900-24XE | \$ 988.00 | 10% | \$895.87 |

| | | | | |
|---------------------------------|-----------------------|-------------|-----|------------|
| EW NBD ONSITE VSP4900-24XE-B3 | 97011-VSP4900-24XE-B3 | \$ 988.00 | 10% | \$895.87 |
| EW NBD ONSITE X435-24P-4S | 97011-X435-24P-4S | \$ 227.00 | 10% | \$205.83 |
| EW NBD ONSITE X435-24T-4S | 97011-X435-24T-4S | \$ 125.00 | 10% | \$113.34 |
| EW NBD ONSITE X435-8P-2T-W | 97011-X435-8P-2T-W | \$ 125.00 | 10% | \$113.34 |
| EW NBD ONSITE X435-8P-4S | 97011-X435-8P-4S | \$ 114.00 | 10% | \$103.37 |
| EW NBD ONSITE X435-8T-4S | 97011-X435-8T-4S | \$ 91.00 | 10% | \$82.51 |
| EW NBD ONSITE Summit X460-24P | 97011-X460-24P | \$ 1,021.00 | 10% | \$925.79 |
| EW NBD ONSITE Summit X460-24T | 97011-X460-24T | \$ 721.00 | 10% | \$653.77 |
| EW NBD ONSITE Summit X460-24TDC | 97011-X460-24TDC | \$ 1,051.00 | 10% | \$952.99 |
| EW NBD ONSITE Summit X460-24X | 97011-X460-24X | \$ 1,321.00 | 10% | \$1,197.82 |
| EW NBD ONSITE Summit X460-24XDC | 97011-X460-24XDC | \$ 1,475.00 | 10% | \$1,337.46 |
| EW NBD ONSITE Summit X460-48P | 97011-X460-48P | \$ 1,321.00 | 10% | \$1,197.82 |
| EW NBD ONSITE Summit X460-48T | 97011-X460-48T | \$ 1,139.00 | 10% | \$1,032.79 |
| EW NBD ONSITE Summit X460-48TDC | 97011-X460-48TDC | \$ 1,432.00 | 10% | \$1,298.47 |
| EW NBD ONSITE Summit X460-48X | 97011-X460-48X | \$ 1,761.00 | 10% | \$1,596.79 |
| EW NBD ONSITE Summit X460-48XDC | 97011-X460-48XDC | \$ 1,718.00 | 10% | \$1,557.80 |
| EW NBD ONSITE X465-24MU | 97011-X465-24MU | \$ 1,144.00 | 10% | \$1,037.32 |
| EW NBD ONSITE X465-24S | 97011-X465-24S | \$ 541.00 | 10% | \$490.55 |
| EW NBD ONSITE X465-24S-B3 | 97011-X465-24S-B3 | \$ 541.00 | 10% | \$490.55 |
| EW NBD ONSITE X465-24W | 97011-X465-24W | \$ 541.00 | 10% | \$490.55 |

| | | | | |
|--------------------------------|------------------------|-------------|-----|------------|
| EW NBD ONSITE X465-24XE | 97011-X465-24XE | \$ 988.00 | 10% | \$895.87 |
| EW NBD ONSITE X465-24XE-B3 | 97011-X465-24XE-B3 | \$ 988.00 | 10% | \$895.87 |
| EW NBD ONSITE X465-48P | 97011-X465-48P | \$ 755.00 | 10% | \$684.60 |
| EW NBD ONSITE X465-48T | 97011-X465-48T | \$ 713.00 | 10% | \$646.51 |
| EW NBD ONSITE X465-48W | 97011-X465-48W | \$ 942.00 | 10% | \$854.16 |
| EW NBD ONSITE X465i-48W | 97011-X465i-48W | \$ 1,120.00 | 10% | \$1,015.56 |
| EW NBD ONSITE X465i-48W-B1-S1 | 97011-X465i-48W-B1-S1 | \$ 1,120.00 | 10% | \$1,015.56 |
| EW NBD ONSITE X465i-48W-B2-S1 | 97011-X465i-48W-B2-S1 | \$ 1,120.00 | 10% | \$1,015.56 |
| EW NBD ONSITE Summit X480-24X | 97011-X480-24X | \$ 1,629.00 | 10% | \$1,477.10 |
| EW NBD ONSITE Summit X480-48T | 97011-X480-48T | \$ 1,629.00 | 10% | \$1,477.10 |
| EW NBD ONSITE Summit X480-48X | 97011-X480-48X | \$ 2,176.00 | 10% | \$1,973.09 |
| EW NBD ONSITE X695-48Y-8C | 97011-X695-48Y-8C | \$ 2,637.00 | 10% | \$2,391.10 |
| EW NBD ONSITE XA1440 | 97011-XA1440 | \$ 277.00 | 10% | \$251.17 |
| EW NBD ONSITE XA1480 | 97011-XA1480 | \$ 369.00 | 10% | \$334.59 |
| EW NBD ONSITE Summit XGM3-2SF | 97011-XGM3-2SF | \$ 270.00 | 10% | \$244.82 |
| EW NBD ONSITE XR600 | 97011-XR600 | \$ 83.00 | 10% | \$75.26 |
| EW NBD ONSITE XSW-BR-M-A-D | 97011-XSW-BR-M-A-D | \$ 40.00 | 10% | \$36.27 |
| EW NBD ONSITE 3YR XSW-BR-M-A-D | 97011-XSW-BR-M-A-D-3YR | \$ 120.00 | 10% | \$108.81 |
| EW NBD ONSITE 5YR XSW-BR-M-A-D | 97011-XSW-BR-M-A-D-5YR | \$ 200.00 | 10% | \$181.35 |
| EW NBD ONSITE XSW-BR-M-A-D-NR | 97011-XSW-BR-M-A-D-NR | \$ 324.00 | 10% | \$293.79 |

| | | | | |
|-----------------------------------|---------------------------|-------------|-----|-------------------|
| EW NBD ONSITE XSW-BR-S-A-D | 97011-XSW-BR-S-A-D | \$ 18.00 | 10% | <i>\$16.32</i> |
| EW NBD ONSITE 3YR XSW-BR-S-A-D | 97011-XSW-BR-S-A-D-3YR | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW NBD ONSITE 5YR XSW-BR-S-A-D | 97011-XSW-BR-S-A-D-5YR | \$ 90.00 | 10% | <i>\$81.61</i> |
| EW NBD ONSITE XSW-BR-S-A-D-NR | 97011-XSW-BR-S-A-D-NR | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW NBD ONSITE XSW-BR-XS-A-D | 97011-XSW-BR-XS-A-D | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW NBD ONSITE 3YR XSW-BR-XS-A-D | 97011-XSW-BR-XS-A-D-3YR | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW NBD ONSITE 5YR XSW-BR-XS-A-D | 97011-XSW-BR-XS-A-D-5YR | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW NBD ONSITE XSW-BR-XS-A-D-NR | 97011-XSW-BR-XS-A-D-NR | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW NBD ONSITE XSW-DC-LR-L-A-D | 97011-XSW-DC-LR-L-A-D | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW NBD ONSITE 3YR XSW-DC-LR-L-A-D | 97011-XSW-DC-LR-L-A-D-3YR | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |
| EW NBD ONSITE 5YR XSW-DC-LR-L-A-D | 97011-XSW-DC-LR-L-A-D-5YR | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW NBD ONSITE XSW-DC-M-A-D | 97011-XSW-DC-M-A-D | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW NBD ONSITE 3YR XSW-DC-M-A-D | 97011-XSW-DC-M-A-D-3YR | \$ 639.00 | 10% | <i>\$579.41</i> |
| EW NBD ONSITE 5YR XSW-DC-M-A-D | 97011-XSW-DC-M-A-D-5YR | \$ 1,065.00 | 10% | <i>\$965.69</i> |
| EW NBD ONSITE XSW-DC-S-A-D | 97011-XSW-DC-S-A-D | \$ 91.00 | 10% | <i>\$82.51</i> |
| EW NBD ONSITE 3YR XSW-DC-S-A-D | 97011-XSW-DC-S-A-D-3YR | \$ 273.00 | 10% | <i>\$247.54</i> |

| | | | | |
|-------------------------------------|-----------------------------|-------------|-----|-------------------|
| EW NBD ONSITE 5YR XSW-DC-S-A-D | 97011-XSW-DC-S-A-D-5YR | \$ 455.00 | 10% | <i>\$412.57</i> |
| EW NBD ONSITE XSW-DC-S-A-D-NR | 97011-XSW-DC-S-A-D-NR | \$ 743.00 | 10% | <i>\$673.72</i> |
| EW NBD ONSITE XSW-DC-SR-L-A-D | 97011-XSW-DC-SR-L-A-D | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW NBD ONSITE 3YR XSW-DC-SR-L-A-D | 97011-XSW-DC-SR-L-A-D-3YR | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |
| EW NBD ONSITE 5YR XSW-DC-SR-L-A-D | 97011-XSW-DC-SR-L-A-D-5YR | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW NBD ONSITE XSW-DCV2-LR-L-A-D | 97011-XSW-DCV2-LR-L-A-D | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW NBD ONSITE 3YR XSW-DCV2-LR-L-A-D | 97011-XSW-DCV2-LR-L-A-D-3YR | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |
| EW NBD ONSITE 5YR XSW-DCV2-LR-L-A-D | 97011-XSW-DCV2-LR-L-A-D-5YR | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW NBD ONSITE XSW-DCV2-LR-L-A-D-NR | 97011-XSW-DCV2-LR-L-A-D-NR | \$ 3,083.00 | 10% | <i>\$2,795.51</i> |
| EW NBD ONSITE XSW-DCV2-M-A-D | 97011-XSW-DCV2-M-A-D | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW NBD ONSITE 3YR XSW-DCV2-M-A-D | 97011-XSW-DCV2-M-A-D-3YR | \$ 639.00 | 10% | <i>\$579.41</i> |
| EW NBD ONSITE 5YR XSW-DCV2-M-A-D | 97011-XSW-DCV2-M-A-D-5YR | \$ 1,065.00 | 10% | <i>\$965.69</i> |
| EW NBD ONSITE XSW-DCV2-M-A-D-NR | 97011-XSW-DCV2-M-A-D-NR | \$ 2,261.00 | 10% | <i>\$2,050.16</i> |
| EW NBD ONSITE XSW-DCV2-SR-L-A-D | 97011-XSW-DCV2-SR-L-A-D | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW NBD ONSITE 3YR XSW-DCV2-SR-L-A-D | 97011-XSW-DCV2-SR-L-A-D-3YR | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |

| | | | | |
|-------------------------------------|-----------------------------|-------------|-----|------------|
| EW NBD ONSITE 5YR XSW-DCV2-SR-L-A-D | 97011-XSW-DCV2-SR-L-A-D-5YR | \$ 1,940.00 | 10% | \$1,759.10 |
| EW NBD ONSITE XSW-DCV2-SR-L-A-D-NR | 97011-XSW-DCV2-SR-L-A-D-NR | \$ 3,083.00 | 10% | \$2,795.51 |
| EW NBD ON-SITE -ZR-XFP | 97011-ZR-XFP | \$ 1,642.00 | 10% | \$1,488.88 |
| EW SWScript 9 PortAP-27001 | 97201-27001 | \$ 77.00 | 6% | \$72.92 |
| EW SWScript 9 to 35 Port-27001 | 97202-27001 | \$ 310.00 | 6% | \$293.59 |
| EW SWScript 35 Port-27001 | 97203-27001 | \$ 465.00 | 6% | \$440.38 |
| PER USER CONTROL | 97207-27001 | \$ 12.00 | 6% | \$11.36 |
| PER USER CONTROLANALYTICS | 97208-27001 | \$ 20.00 | 6% | \$18.94 |
| EW Edu NBD PartOnly-10200 | 97304-10200 | \$ 621.00 | 10% | \$563.09 |
| EW Edu NBD PartOnly-10320 | 97304-10320 | \$ 686.00 | 10% | \$622.03 |
| EW Edu NBD PartOnly-10330 | 97304-10330 | \$ 1,676.00 | 10% | \$1,519.71 |
| EW Edu NBD PartOnly-10331 | 97304-10331 | \$ 776.00 | 10% | \$703.64 |
| EW Edu NBD PartOnly 10335 | 97304-10335 | \$ 1,180.00 | 10% | \$1,069.97 |
| EW Edu NBD PartOnly 10403 | 97304-10403 | \$ 1,470.00 | 10% | \$1,332.92 |
| EW Edu NBD PartOnly 10404 | 97304-10404 | \$ 762.00 | 10% | \$690.94 |
| EW Edu NBD PartOnly 10441 | 97304-10441 | \$ 507.00 | 10% | \$459.72 |
| EW Edu NBD PartOnly 10442 | 97304-10442 | \$ 546.00 | 10% | \$495.09 |
| EW Edu NBD PartOnly 1130C | 97304-1130C | \$ 480.00 | 6% | \$454.58 |
| EW Edu NBD PartOnly-16119 | 97304-16119 | \$ 93.00 | 10% | \$84.33 |
| EW Edu NBD PartOnly-16120 | 97304-16120 | \$ 120.00 | 10% | \$108.81 |
| EW Edu NBD PartOnly-16126 | 97304-16126 | \$ 93.00 | 10% | \$84.33 |
| EW Edu NBD PartOnly-16127 | 97304-16127 | \$ 98.00 | 10% | \$88.86 |
| EW Edu NBD PartOnly 16172 | 97304-16172 | \$ 91.00 | 10% | \$82.51 |
| EW Edu NBD PartOnly -16172T | 97304-16172T | \$ 110.00 | 10% | \$99.74 |
| EW Edu NBD PartOnly 16173 | 97304-16173 | \$ 99.00 | 10% | \$89.77 |
| EW Edu NBD PartOnly -16173T | 97304-16173T | \$ 119.00 | 10% | \$107.90 |
| EW Edu NBD PartOnly 16174 | 97304-16174 | \$ 147.00 | 10% | \$133.29 |
| EW Edu NBD PartOnly 16175 | 97304-16175 | \$ 158.00 | 10% | \$143.27 |
| EW Edu NBD PartOnly 16176 | 97304-16176 | \$ 132.00 | 10% | \$119.69 |
| EW Edu NBD PartOnly 16177 | 97304-16177 | \$ 135.00 | 10% | \$122.41 |
| EW Edu NBD PartOnly -16177T | 97304-16177T | \$ 174.00 | 10% | \$157.77 |
| EW Edu NBD PartOnly 16178 | 97304-16178 | \$ 202.00 | 10% | \$183.16 |

| | | | | |
|-----------------------------|--------------|-----------|-----|----------|
| EW Edu NBD PartOnly 16179 | 97304-16179 | \$ 210.00 | 10% | \$190.42 |
| EW Edu NBD PartOnly -16179T | 97304-16179T | \$ 242.00 | 10% | \$219.43 |
| EW Edu NBD PartOnly-16301T | 97304-16301T | \$ 572.00 | 10% | \$518.66 |
| EW Edu NBD PartOnly-16303T | 97304-16303T | \$ 572.00 | 10% | \$518.66 |
| EW Edu NBD PartOnly-16304T | 97304-16304T | \$ 759.00 | 10% | \$688.22 |
| EW Edu NBD PartOnly-16401T | 97304-16401T | \$ 277.00 | 10% | \$251.17 |
| EW Edu NBD PartOnly-16402T | 97304-16402T | \$ 409.00 | 10% | \$370.86 |
| EW Edu NBD PartOnly-16403T | 97304-16403T | \$ 366.00 | 10% | \$331.87 |
| EW Edu NBD PartOnly-16404T | 97304-16404T | \$ 366.00 | 10% | \$331.87 |
| EW Edu NBD PartOnly-16405T | 97304-16405T | \$ 475.00 | 10% | \$430.71 |
| EW Edu NBD PartOnly-16406T | 97304-16406T | \$ 632.00 | 10% | \$573.07 |
| EW Edu NBD PartOnly-16431 | 97304-16431 | \$ 396.00 | 10% | \$359.07 |
| EW Edu NBD PartOnly-16432 | 97304-16432 | \$ 439.00 | 10% | \$398.06 |
| EW Edu NBD PartOnly-16440 | 97304-16440 | \$ 252.00 | 10% | \$228.50 |
| EW Edu NBD PartOnly-16441 | 97304-16441 | \$ 224.00 | 10% | \$203.11 |
| EW Edu NBD PartOnly-16442 | 97304-16442 | \$ 98.00 | 10% | \$88.86 |
| EW Edu NBD PartOnly-16444 | 97304-16444 | \$ 51.00 | 10% | \$46.24 |
| EW Edu NBD PartOnly-16501 | 97304-16501 | \$ 54.00 | 10% | \$48.96 |
| EW Edu NBD PartOnly-16501T | 97304-16501T | \$ 40.00 | 10% | \$36.27 |
| EW Edu NBD PartOnly-16502 | 97304-16502 | \$ 78.00 | 10% | \$70.73 |
| EW Edu NBD PartOnly-16502T | 97304-16502T | \$ 95.00 | 10% | \$86.14 |
| EW Edu NBD PartOnly-16503 | 97304-16503 | \$ 65.00 | 10% | \$58.94 |
| EW Edu NBD PartOnly-16503T | 97304-16503T | \$ 85.00 | 10% | \$77.07 |
| EW Edu NBD PartOnly-16504 | 97304-16504 | \$ 105.00 | 10% | \$95.21 |
| EW Edu NBD PartOnly-16504T | 97304-16504T | \$ 120.00 | 10% | \$108.81 |
| EW Edu NBD PartOnly-16505 | 97304-16505 | \$ 117.00 | 10% | \$106.09 |
| EW Edu NBD PartOnly-16505T | 97304-16505T | \$ 139.00 | 10% | \$126.04 |
| EW Edu NBD PartOnly-16506 | 97304-16506 | \$ 184.00 | 10% | \$166.84 |
| EW Edu NBD PartOnly-16506T | 97304-16506T | \$ 223.00 | 10% | \$202.21 |
| EW Edu NBD PartOnly-16507 | 97304-16507 | \$ 171.00 | 10% | \$155.05 |
| EW Edu NBD PartOnly-16507T | 97304-16507T | \$ 201.00 | 10% | \$182.26 |
| EW Edu NBD PartOnly-16508 | 97304-16508 | \$ 215.00 | 10% | \$194.95 |
| EW Edu NBD PartOnly-16508T | 97304-16508T | \$ 244.00 | 10% | \$221.25 |
| EW Edu NBD PartOnly-16509 | 97304-16509 | \$ 215.00 | 10% | \$194.95 |
| EW Edu NBD PartOnly-16509T | 97304-16509T | \$ 244.00 | 10% | \$221.25 |
| EW Edu NBD PartOnly-16510 | 97304-16510 | \$ 244.00 | 10% | \$221.25 |
| EW Edu NBD PartOnly-16510T | 97304-16510T | \$ 297.00 | 10% | \$269.30 |
| EW Edu NBD PartOnly-16513 | 97304-16513 | \$ 155.00 | 10% | \$140.55 |
| EW Edu NBD PartOnly-16514 | 97304-16514 | \$ 242.00 | 10% | \$219.43 |
| EW Edu NBD PartOnly-16515 | 97304-16515 | \$ 41.00 | 10% | \$37.18 |
| EW Edu NBD PartOnly-16516 | 97304-16516 | \$ 42.00 | 10% | \$38.08 |

| | | | | |
|-----------------------------|--------------|-----------|-----|----------|
| EW Edu NBD PartOnly-16517 | 97304-16517 | \$ 89.00 | 10% | \$80.70 |
| EW Edu NBD PartOnly-16518 | 97304-16518 | \$ 80.00 | 10% | \$72.54 |
| EW Edu NBD PartOnly-16519 | 97304-16519 | \$ 77.00 | 10% | \$69.82 |
| EW Edu NBD PartOnly-16520 | 97304-16520 | \$ 112.00 | 10% | \$101.56 |
| EW Edu NBD PartOnly-16530 | 97304-16530 | \$ 44.00 | 10% | \$39.90 |
| EW Edu NBD PartOnly-16531 | 97304-16531 | \$ 62.00 | 10% | \$56.22 |
| EW Edu NBD PartOnly 16531T | 97304-16531T | \$ 64.00 | 10% | \$58.03 |
| EW Edu NBD PartOnly-16532 | 97304-16532 | \$ 62.00 | 10% | \$56.22 |
| EW Edu NBD PartOnly 16532T | 97304-16532T | \$ 64.00 | 10% | \$58.03 |
| EW Edu NBD PartOnly-16533 | 97304-16533 | \$ 87.00 | 10% | \$78.89 |
| EW Edu NBD PartOnly 16533T | 97304-16533T | \$ 93.00 | 10% | \$84.33 |
| EW Edu NBD PartOnly-16534 | 97304-16534 | \$ 95.00 | 10% | \$86.14 |
| EW Edu NBD PartOnly-16535 | 97304-16535 | \$ 137.00 | 10% | \$124.22 |
| EW Edu NBD PartOnly-16535A | 97304-16535A | \$ 137.00 | 10% | \$124.22 |
| EW Edu NBD PartOnly 16535T | 97304-16535T | \$ 157.00 | 10% | \$142.36 |
| EW Edu NBD PartOnly-16536 | 97304-16536 | \$ 60.00 | 10% | \$54.41 |
| EW Edu NBD PartOnly-16537 | 97304-16537 | \$ 93.00 | 10% | \$84.33 |
| EW Edu NBD PartOnly-16538 | 97304-16538 | \$ 102.00 | 10% | \$92.49 |
| EW Edu NBD PartOnly 16538T | 97304-16538T | \$ 126.00 | 10% | \$114.25 |
| EW Edu NBD PartOnly-16539 | 97304-16539 | \$ 143.00 | 10% | \$129.67 |
| EW Edu NBD PartOnly-16540 | 97304-16540 | \$ 97.00 | 10% | \$87.95 |
| EW Edu NBD PartOnly-16541 | 97304-16541 | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly 16560 | 97304-16560 | \$ 19.00 | 10% | \$17.23 |
| EW Edu NBD PartOnly 16561 | 97304-16561 | \$ 34.00 | 10% | \$30.83 |
| EW Edu NBD PartOnly 16562 | 97304-16562 | \$ 37.00 | 10% | \$33.55 |
| EW Edu NBD PartOnly 16563 | 97304-16563 | \$ 52.00 | 10% | \$47.15 |
| EW Edu NBD PartOnly 16564 | 97304-16564 | \$ 65.00 | 10% | \$58.94 |
| EW Edu NBD PartOnly 16565 | 97304-16565 | \$ 90.00 | 10% | \$81.61 |
| EW Edu NBD PartOnly 16566 | 97304-16566 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly 16567 | 97304-16567 | \$ 26.00 | 10% | \$23.58 |
| EW Edu NBD PartOnly 16568 | 97304-16568 | \$ 19.00 | 10% | \$17.23 |
| EW Edu NBD PartOnly 16569 | 97304-16569 | \$ 33.00 | 10% | \$29.92 |
| EW Edu NBD PartOnly 16570 | 97304-16570 | \$ 37.00 | 10% | \$33.55 |
| EW Edu NBD PartOnly 16571 | 97304-16571 | \$ 65.00 | 10% | \$58.94 |
| EW Edu NBD PartOnly-16701 | 97304-16701 | \$ 146.00 | 10% | \$132.39 |
| EW Edu NBD PartOnly-16702 | 97304-16702 | \$ 206.00 | 10% | \$186.79 |
| EW Edu NBD PartOnly-16703 | 97304-16703 | \$ 166.00 | 10% | \$150.52 |
| EW Edu NBD PartOnly -16703T | 97304-16703T | \$ 201.00 | 10% | \$182.26 |
| EW Edu NBD PartOnly-16704 | 97304-16704 | \$ 244.00 | 10% | \$221.25 |
| EW Edu NBD PartOnly -16704T | 97304-16704T | \$ 300.00 | 10% | \$272.03 |

| | | | | |
|-----------------------------|--------------|-------------|-----|-----------------|
| EW Edu NBD PartOnly-16705 | 97304-16705 | \$ 206.00 | 10% | <i>\$186.79</i> |
| EW Edu NBD PartOnly -16705T | 97304-16705T | \$ 252.00 | 10% | <i>\$228.50</i> |
| EW Edu NBD PartOnly-16706 | 97304-16706 | \$ 325.00 | 10% | <i>\$294.69</i> |
| EW Edu NBD PartOnly -16706T | 97304-16706T | \$ 393.00 | 10% | <i>\$356.35</i> |
| EW Edu NBD PartOnly-16710 | 97304-16710 | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW Edu NBD PartOnly 16710T | 97304-16710T | \$ 74.00 | 10% | <i>\$67.10</i> |
| EW Edu NBD PartOnly-16711 | 97304-16711 | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly 16711T | 97304-16711T | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly-16712 | 97304-16712 | \$ 28.00 | 10% | <i>\$25.39</i> |
| EW Edu NBD PartOnly 16712T | 97304-16712T | \$ 36.00 | 10% | <i>\$32.64</i> |
| EW Edu NBD PartOnly-16713 | 97304-16713 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly 16713T | 97304-16713T | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly-16715 | 97304-16715 | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly 16715T | 97304-16715T | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly-16716 | 97304-16716 | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW Edu NBD PartOnly -16716T | 97304-16716T | \$ 132.00 | 10% | <i>\$119.69</i> |
| EW Edu NBD PartOnly-16717 | 97304-16717 | \$ 173.00 | 10% | <i>\$156.87</i> |
| EW Edu NBD PartOnly-16718 | 97304-16718 | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW Edu NBD PartOnly -16718T | 97304-16718T | \$ 148.00 | 10% | <i>\$134.20</i> |
| EW Edu NBD PartOnly-16719 | 97304-16719 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW Edu NBD PartOnly -16719T | 97304-16719T | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW Edu NBD PartOnly 16720 | 97304-16720 | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW Edu NBD PartOnly 16720T | 97304-16720T | \$ 320.00 | 10% | <i>\$290.16</i> |
| EW Edu NBD PartOnly 16756 | 97304-16756 | \$ 197.00 | 10% | <i>\$178.63</i> |
| EW Edu NBD PartOnly 16756T | 97304-16756T | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW Edu NBD PartOnly 16757 | 97304-16757 | \$ 190.00 | 10% | <i>\$172.28</i> |
| EW Edu NBD PartOnly 16757T | 97304-16757T | \$ 231.00 | 10% | <i>\$209.46</i> |
| EW Edu NBD PartOnly 16790 | 97304-16790 | \$ 412.00 | 10% | <i>\$373.58</i> |
| EW Edu NBD PartOnly 16791 | 97304-16791 | \$ 531.00 | 10% | <i>\$481.48</i> |
| EW Edu NBD PartOnly 16801 | 97304-16801 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly 16802 | 97304-16802 | \$ 62.00 | 10% | <i>\$56.22</i> |
| EW Edu NBD PartOnly 16803 | 97304-16803 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly 16804 | 97304-16804 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW Edu NBD PartOnly 16805 | 97304-16805 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Edu NBD PartOnly-17101 | 97304-17101 | \$ 779.00 | 10% | <i>\$706.36</i> |
| EW Edu NBD PartOnly-17101T | 97304-17101T | \$ 1,080.00 | 10% | <i>\$979.29</i> |
| EW Edu NBD PartOnly-17102 | 97304-17102 | \$ 779.00 | 10% | <i>\$706.36</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|------------|
| EW Edu NBD PartOnly-17102T | 97304-17102T | \$ 1,080.00 | 10% | \$979.29 |
| EW Edu NBD PartOnly-17103 | 97304-17103 | \$ 541.00 | 10% | \$490.55 |
| EW Edu NBD PartOnly-17103C | 97304-17103C | \$ 588.00 | 10% | \$533.17 |
| EW Edu NBD PartOnly-17103T | 97304-17103T | \$ 753.00 | 10% | \$682.78 |
| EW Edu NBD PartOnly-17104 | 97304-17104 | \$ 541.00 | 10% | \$490.55 |
| EW Edu NBD PartOnly-17104T | 97304-17104T | \$ 753.00 | 10% | \$682.78 |
| EW Edu NBD PartOnly-17121 | 97304-17121 | \$ 160.00 | 10% | \$145.08 |
| EW Edu NBD PartOnly-17122 | 97304-17122 | \$ 93.00 | 10% | \$84.33 |
| EW Edu NBD PartOnly 17200 | 97304-17200 | \$ 1,225.00 | 6% | \$1,160.14 |
| EW Edu NBD PartOnly-17200T | 97304-17200T | \$ 1,524.00 | 10% | \$1,381.89 |
| EW Edu NBD PartOnly-17201 | 97304-17201 | \$ 1,225.00 | 10% | \$1,110.77 |
| EW Edu NBD PartOnly-17201T | 97304-17201T | \$ 1,524.00 | 10% | \$1,381.89 |
| EW Edu NBD PartOnly-17202 | 97304-17202 | \$ 1,225.00 | 10% | \$1,110.77 |
| EW Edu NBD PartOnly-17202T | 97304-17202T | \$ 1,524.00 | 10% | \$1,381.89 |
| EW Edu NBD PartOnly-17203 | 97304-17203 | \$ 1,237.00 | 10% | \$1,121.65 |
| EW Edu NBD PartOnly-17203T | 97304-17203T | \$ 1,543.00 | 10% | \$1,399.12 |
| EW Edu NBD PartOnly-17204 | 97304-17204 | \$ 1,237.00 | 10% | \$1,121.65 |
| EW Edu NBD PartOnly-17204T | 97304-17204T | \$ 1,543.00 | 10% | \$1,399.12 |
| EW Edu NBD PartOnly-17205 | 97304-17205 | \$ 1,236.00 | 10% | \$1,120.74 |
| EW Edu NBD PartOnly-17205T | 97304-17205T | \$ 1,538.00 | 10% | \$1,394.58 |
| EW Edu NBD PartOnly-17206 | 97304-17206 | \$ 1,236.00 | 10% | \$1,120.74 |
| EW Edu NBD PartOnly-17206T | 97304-17206T | \$ 1,538.00 | 10% | \$1,394.58 |
| EW Edu NBD PartOnly-17300 | 97304-17300 | \$ 811.00 | 10% | \$735.37 |
| EW Edu NBD PartOnly-17310 | 97304-17310 | \$ 734.00 | 10% | \$665.55 |
| EW Edu NBD PartOnly -17310T | 97304-17310T | \$ 883.00 | 10% | \$800.66 |
| EW Edu NBD PartOnly 17350 | 97304-17350 | \$ 738.00 | 10% | \$669.18 |
| EW Edu NBD PartOnly 17360 | 97304-17360 | \$ 913.00 | 10% | \$827.86 |
| EW eRate NBD Part Only 17401 | 97304-17401 | \$ 114.00 | 10% | \$103.37 |
| EW Edu NBD PartOnly 17401G | 97304-17401G | \$ 135.00 | 10% | \$122.41 |
| EW Edu NBD PartOnly 17401T | 97304-17401T | \$ 128.00 | 10% | \$116.06 |
| EW eRate NBD Part Only 17402 | 97304-17402 | \$ 166.00 | 10% | \$150.52 |
| EW Edu NBD PartOnly 17402G | 97304-17402G | \$ 179.00 | 10% | \$162.31 |
| EW Edu NBD PartOnly 17402T | 97304-17402T | \$ 174.00 | 10% | \$157.77 |
| EW eRate NBD Part Only 17403 | 97304-17403 | \$ 176.00 | 10% | \$159.59 |
| EW eRate NBD Part Only 17404 | 97304-17404 | \$ 83.00 | 10% | \$75.26 |
| EW eRate NBD Part Only 17405 | 97304-17405 | \$ 106.00 | 10% | \$96.12 |
| EW Edu NBD PartOnly 17700 | 97304-17700 | \$ 1,438.00 | 6% | \$1,361.86 |
| EW Edu NBD PartOnly-17701 | 97304-17701 | \$ 1,239.00 | 10% | \$1,123.46 |
| EW Edu NBD PartOnly-17702 | 97304-17702 | \$ 1,239.00 | 10% | \$1,123.46 |
| EW Edu NBD PartOnly-17703 | 97304-17703 | \$ 1,406.00 | 10% | \$1,274.89 |
| EW Edu NBD PartOnly-17704 | 97304-17704 | \$ 1,406.00 | 10% | \$1,274.89 |

| | | | | |
|-------------------------------|-----------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly-17705 | 97304-17705 | \$ 1,258.00 | 10% | <i>\$1,140.69</i> |
| EW Edu NBD PartOnly-17706 | 97304-17706 | \$ 1,258.00 | 10% | <i>\$1,140.69</i> |
| EW Edu NBD PartOnly 17800 | 97304-17800 | \$ 1,445.00 | 10% | <i>\$1,310.25</i> |
| EW Edu NBD PartOnly 17810 | 97304-17810 | \$ 1,161.00 | 10% | <i>\$1,052.74</i> |
| EW Edu NBD PartOnly 18101 | 97304-18101 | \$ 76.00 | 10% | <i>\$68.91</i> |
| EW Edu NBD PartOnly 18102 | 97304-18102 | \$ 93.00 | 10% | <i>\$84.33</i> |
| EW Edu NBD PartOnly 18103 | 97304-18103 | \$ 105.00 | 10% | <i>\$95.21</i> |
| EW Edu NBD PartOnly 18104 | 97304-18104 | \$ 149.00 | 10% | <i>\$135.11</i> |
| EW Edu NBD PartOnly 18104-6PK | 97304-18104-6PK | \$ 932.00 | 10% | <i>\$845.09</i> |
| EW Edu NBD PartOnly 18202 | 97304-18202 | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW Edu NBD PartOnly 30135 | 97304-30135 | \$ 139.00 | 10% | <i>\$126.04</i> |
| EW Edu NBD PartOnly 30136 | 97304-30136 | \$ 1,000.00 | 10% | <i>\$906.75</i> |
| EW Edu NBD PartOnly 30137 | 97304-30137 | \$ 336.00 | 10% | <i>\$304.67</i> |
| EW Edu NBD PartOnly 30138 | 97304-30138 | \$ 1,373.00 | 10% | <i>\$1,244.97</i> |
| EW Edu NBD PartOnly 30139 | 97304-30139 | \$ 3,017.00 | 10% | <i>\$2,735.66</i> |
| EW Edu NBD PartOnly-30912 | 97304-30912 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly 30913 | 97304-30913 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly 31012 | 97304-31012 | \$ 44.00 | 10% | <i>\$39.90</i> |
| EW Edu NBD PartOnly 31014 | 97304-31014 | \$ 44.00 | 10% | <i>\$39.90</i> |
| EW Edu NBD PartOnly-31016 | 97304-31016 | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW Edu NBD PartOnly-31017 | 97304-31017 | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW Edu NBD PartOnly-31018 | 97304-31018 | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW Edu NBD PartOnly-31019 | 97304-31019 | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW Edu NBD PartOnly 31025 | 97304-31025 | \$ 16.00 | 10% | <i>\$14.51</i> |
| EW Edu NBD PartOnly 31026 | 97304-31026 | \$ 16.00 | 10% | <i>\$14.51</i> |
| EW Edu NBD PartOnly 31028 | 97304-31028 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly 31029 | 97304-31029 | \$ 28.00 | 10% | <i>\$25.39</i> |
| EW Edu NBD PartOnly 31031 | 97304-31031 | \$ 32.00 | 10% | <i>\$29.02</i> |
| EW Edu NBD PartOnly 31032 | 97304-31032 | \$ 32.00 | 10% | <i>\$29.02</i> |
| EW Edu NBD PartOnly 31034 | 97304-31034 | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly 31035 | 97304-31035 | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly 31050 | 97304-31050 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly 31051 | 97304-31051 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly 31055 | 97304-31055 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly 31056 | 97304-31056 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly 37101 | 97304-37101 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly 37102 | 97304-37102 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly 37103 | 97304-37103 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly 37111 | 97304-37111 | \$ 18.00 | 10% | <i>\$16.32</i> |
| EW Edu NBD PartOnly 37112 | 97304-37112 | \$ 16.00 | 10% | <i>\$14.51</i> |
| EW Edu NBD PartOnly 37113 | 97304-37113 | \$ 33.00 | 10% | <i>\$29.92</i> |

| | | | | |
|-------------------------------------|-----------------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly 37114 | 97304-37114 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly 37121 | 97304-37121 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Edu NBD PartOnly 37122 | 97304-37122 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Edu NBD PartOnly 37123 | 97304-37123 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Edu NBD PartOnly 37124 | 97304-37124 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Edu NBD PartOnly 37125 | 97304-37125 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Edu NBD PartOnly 37126 | 97304-37126 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Edu NBD PartOnly 39031 | 97304-39031 | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW Edu NBD PartOnly 39032 | 97304-39032 | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW Edu NBD PartOnly 39033 | 97304-39033 | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW Edu NBD PartOnly 39034 | 97304-39034 | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW Edu NBD PartOnly 39035 | 97304-39035 | \$ 465.00 | 10% | <i>\$421.64</i> |
| EW Edu NBD PartOnly 39036 | 97304-39036 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW Edu NBD PartOnly 39037 | 97304-39037 | \$ 63.00 | 10% | <i>\$57.13</i> |
| EW Edu NBD PartOnly 4120-24MW-4Y | 97304-4120-24MW-4Y | \$ 135.00 | 10% | <i>\$122.41</i> |
| EW Edu NBD PartOnly 4120-48MW-4Y | 97304-4120-48MW-4Y | \$ 180.00 | 10% | <i>\$163.22</i> |
| EW Edu NBD PartOnly 4120C | 97304-4120C | \$ 2,039.00 | 10% | <i>\$1,848.86</i> |
| EW Edu NBD PartOnly 4120C-1 | 97304-4120C-1 | \$ 2,302.00 | 10% | <i>\$2,087.34</i> |
| EW eRate NBD Part Only 41216 | 97304-41216 | \$ 536.00 | 10% | <i>\$486.02</i> |
| EW Edu NBD PartOnly 4220-12P-4X | 97304-4220-12P-4X | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW Edu NBD PartOnly 4220-12T-4X | 97304-4220-12T-4X | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly 4220-24P-4X | 97304-4220-24P-4X | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW Edu NBD PartOnly 4220-24T-4X | 97304-4220-24T-4X | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly 4220-48P-4X | 97304-4220-48P-4X | \$ 90.00 | 10% | <i>\$81.61</i> |
| EW Edu NBD PartOnly 4220-48T-4X | 97304-4220-48T-4X | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW Edu NBD PartOnly 4220-4MW-20P-4X | 97304-4220-4MW-20P-4X | \$ 82.00 | 10% | <i>\$74.35</i> |
| EW Edu NBD PartOnly 4220-4MW-8P-4X | 97304-4220-4MW-8P-4X | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Edu NBD PartOnly 4220-8MW-40P-4X | 97304-4220-8MW-40P-4X | \$ 120.00 | 10% | <i>\$108.81</i> |
| EW Edu NBD PartOnly 4220-8X | 97304-4220-8X | \$ 63.00 | 10% | <i>\$57.13</i> |

| | | | | |
|---|---------------------------|-------------|-----|------------|
| EW Edu NBD PartOnly-48001 | 97304-48001 | \$ 2,231.00 | 10% | \$2,022.96 |
| EW Edu NBD PartOnly-48038 | 97304-48038 | \$ 892.00 | 10% | \$808.82 |
| EW Edu NBD PartOnly-48039 | 97304-48039 | \$ 892.00 | 10% | \$808.82 |
| EW Edu NBD PartOnly-48040 | 97304-48040 | \$ 754.00 | 10% | \$683.69 |
| EW Edu NBD PartOnly-48041 | 97304-48041 | \$ 892.00 | 10% | \$808.82 |
| EW Edu NBD PartOnly-48046 | 97304-48046 | \$ 1,171.00 | 10% | \$1,061.80 |
| EW Edu NBD PartOnly-48051 | 97304-48051 | \$ 2,153.00 | 10% | \$1,952.23 |
| EW Edu NBD PartOnly-48061 | 97304-48061 | \$ 2,509.00 | 10% | \$2,275.04 |
| EW Edu NBD PartOnly 5320-16P-4XE | 97304-5320-16P-4XE | \$ 62.00 | 10% | \$56.22 |
| EW Edu NBD PartOnly 5320-16P-4XE-DC | 97304-5320-16P-4XE-DC | \$ 74.00 | 10% | \$67.10 |
| EW Edu NBD PartOnly 5320-24P-8XE | 97304-5320-24P-8XE | \$ 69.00 | 10% | \$62.57 |
| EW Edu NBD PartOnly 5320-24T-24S-4XE-XT | 97304-5320-24T-24S-4XE-XT | \$ 91.00 | 10% | \$82.51 |
| EW Edu NBD PartOnly 5320-24T-4X-XT | 97304-5320-24T-4X-XT | \$ 49.00 | 10% | \$44.43 |
| EW Edu NBD PartOnly 5320-24T-8XE | 97304-5320-24T-8XE | \$ 48.00 | 10% | \$43.52 |
| EW Edu NBD PartOnly 5320-48P-8XE | 97304-5320-48P-8XE | \$ 115.00 | 10% | \$104.28 |
| EW Edu NBD PartOnly 5320-48T-8XE | 97304-5320-48T-8XE | \$ 77.00 | 10% | \$69.82 |
| EW Edu NBD PartOnly 5420F-16MW-32P-4XE | 97304-5420F-16MW-32P-4XE | \$ 244.00 | 10% | \$221.25 |
| EW Edu NBD PartOnly 5420F-16W-32P-4XE | 97304-5420F-16W-32P-4XE | \$ 207.00 | 10% | \$187.70 |
| EW Edu NBD PartOnly 5420F-24P-4XE | 97304-5420F-24P-4XE | \$ 47.00 | 10% | \$42.62 |
| EW Edu NBD PartOnly 5420F-24S-4XE | 97304-5420F-24S-4XE | \$ 117.00 | 10% | \$106.09 |
| EW Edu NBD PartOnly 5420F-24T-4XE | 97304-5420F-24T-4XE | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly5420F-48P-4XE | 97304-5420F-48P-4XE | \$ 79.00 | 10% | \$71.63 |
| EW Edu NBD PartOnly 5420F-48P-4XL | 97304-5420F-48P-4XL | \$ 187.00 | 10% | \$169.56 |
| EW Edu NBD PartOnly 5420F-48T-4XE | 97304-5420F-48T-4XE | \$ 53.00 | 10% | \$48.06 |

| | | | | |
|---|---------------------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly 5420F-8W-16P-4XE | 97304-5420F-8W-16P-4XE | \$ 121.00 | 10% | <i>\$109.72</i> |
| EW Edu NBD PartOnly 5420M-16MW-32P-4YE | 97304-5420M-16MW-32P-4YE | \$ 190.00 | 10% | <i>\$172.28</i> |
| EW Edu NBD PartOnly 5420M-24T-4YE | 97304-5420M-24T-4YE | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW Edu NBD PartOnly 5420M-24W-4YE | 97304-5420M-24W-4YE | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW Edu NBD PartOnly 5420M-48T-4YE | 97304-5420M-48T-4YE | \$ 117.00 | 10% | <i>\$106.09</i> |
| EW Edu NBD PartOnly 5420M-48W-4YE | 97304-5420M-48W-4YE | \$ 132.00 | 10% | <i>\$119.69</i> |
| EW EDU NBD PARTONLY 5520-12MW-36W | 97304-5520-12MW-36W | \$ 219.00 | 10% | <i>\$198.58</i> |
| EW EDU NBD PARTONLY 5520-24T | 97304-5520-24T | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW EDU NBD PARTONLY 5520-24T-ACDC-BASE | 97304-5520-24T-ACDC-BASE | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW EDU NBD PARTONLY 5520-24T-BASE | 97304-5520-24T-BASE | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW EDU NBD PARTONLY 5520-24W | 97304-5520-24W | \$ 167.00 | 10% | <i>\$151.43</i> |
| EW EDU NBD PARTONLY 5520-24X | 97304-5520-24X | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW EDU NBD PARTONLY 5520-24X-ACDC-BASE | 97304-5520-24X-ACDC-BASE | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW EDU NBD PARTONLY 5520-24X-BASE | 97304-5520-24X-BASE | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW EDU NBD PARTONLY 5520-48SE | 97304-5520-48SE | \$ 380.00 | 10% | <i>\$344.57</i> |
| EW EDU NBD PARTONLY 5520-48SE-ACDC-BASE | 97304-5520-48SE-ACDC-BASE | \$ 380.00 | 10% | <i>\$344.57</i> |
| EW EDU NBD PARTONLY 5520-48SE-BASE | 97304-5520-48SE-BASE | \$ 380.00 | 10% | <i>\$344.57</i> |
| EW EDU NBD PARTONLY 5520-48T | 97304-5520-48T | \$ 148.00 | 10% | <i>\$134.20</i> |
| EW EDU NBD PARTONLY 5520-48T-ACDC-BASE | 97304-5520-48T-ACDC-BASE | \$ 148.00 | 10% | <i>\$134.20</i> |

| | | | | |
|---|----------------------------------|-----------|-----|-----------------|
| EW EDU NBD PARTONLY 5520-48T-BASE | 97304-5520- 48T-BASE | \$ 148.00 | 10% | <i>\$134.20</i> |
| EW EDU NBD PARTONLY 5520-48W | 97304-5520- 48W | \$ 178.00 | 10% | <i>\$161.40</i> |
| EW Edu NBD PartOnly 5720- 24MW | 97304-5720- 24MW | \$ 253.00 | 10% | <i>\$229.41</i> |
| EW Edu NBD PartOnly 5720- 24MXW | 97304-5720- 24MXW | \$ 342.00 | 10% | <i>\$310.11</i> |
| EW Edu NBD PartOnly 5720- 48MW | 97304-5720- 48MW | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW Edu NBD PartOnly 5720- 48MXW | 97304-5720- 48MXW | \$ 392.00 | 10% | <i>\$355.45</i> |
| EW Edu NBD PartOnly 7520- 48XT-6C | 97304-7520- 48XT-6C | \$ 494.00 | 10% | <i>\$447.93</i> |
| EW Edu NBD PartOnly 7520- 48XT-6C-AC-F | 97304-7520- 48XT-6C-AC- F | \$ 494.00 | 10% | <i>\$447.93</i> |
| EW Edu NBD PartOnly 7520- 48XT-6C-AC-R | 97304-7520- 48XT-6C-AC- R | \$ 494.00 | 10% | <i>\$447.93</i> |
| EW Edu NBD PartOnly 7520- 48Y-8C | 97304-7520- 48Y-8C | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW Edu NBD PartOnly 7520- 48Y-8C-AC-F | 97304-7520- 48Y-8C-AC-F | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW Edu NBD PartOnly 7520- 48Y-8C-AC-R | 97304-7520- 48Y-8C-AC-R | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW EDU NBD PARTONLY 7520-48YE-8CE | 97304-7520- 48YE-8CE | \$ 489.00 | 10% | <i>\$443.40</i> |
| EW EDU NBD PARTONLY 7520-48YE-8CE-AC-F | 97304-7520- 48YE-8CE-AC- F | \$ 489.00 | 10% | <i>\$443.40</i> |
| EW EDU NBD PARTONLY 7520-48YE-8CE-AC-R | 97304-7520- 48YE-8CE-AC- R | \$ 489.00 | 10% | <i>\$443.40</i> |
| EW Edu NBD PartOnly 7720- 32C | 97304-7720- 32C | \$ 506.00 | 10% | <i>\$458.82</i> |
| EW Edu NBD PartOnly 7720- 32C-AC-F | 97304-7720- 32C-AC-F | \$ 506.00 | 10% | <i>\$458.82</i> |
| EW Edu NBD PartOnly 7720- 32C-AC-R | 97304-7720- 32C-AC-R | \$ 506.00 | 10% | <i>\$458.82</i> |
| EW Edu NBD PartOnly 8520- 48XT-6C | 97304-8520- 48XT-6C | \$ 783.00 | 10% | <i>\$709.99</i> |

| | | | | |
|---------------------------------------|-------------------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly 8520-48XT-6C-AC-F | 97304-8520-48XT-6C-AC-F | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW Edu NBD PartOnly 8520-48XT-6C-AC-R | 97304-8520-48XT-6C-AC-R | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW Edu NBD PartOnly 8520-48XT-6C-DC-F | 97304-8520-48XT-6C-DC-F | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW Edu NBD PartOnly 8520-48XT-6C-DC-R | 97304-8520-48XT-6C-DC-R | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW Edu NBD PartOnly 8520-48Y-8C | 97304-8520-48Y-8C | \$ 797.00 | 10% | <i>\$722.68</i> |
| EW Edu NBD PartOnly 8520-48Y-8C-AC-F | 97304-8520-48Y-8C-AC-F | \$ 797.00 | 10% | <i>\$722.68</i> |
| EW Edu NBD PartOnly 8520-48Y-8C-AC-R | 97304-8520-48Y-8C-AC-R | \$ 797.00 | 10% | <i>\$722.68</i> |
| EW Edu NBD PartOnly 8520-48Y-8C-DC-F | 97304-8520-48Y-8C-DC-F | \$ 797.00 | 10% | <i>\$722.68</i> |
| EW Edu NBD PartOnly 8520-48Y-8C-DC-R | 97304-8520-48Y-8C-DC-R | \$ 797.00 | 10% | <i>\$722.68</i> |
| EW Edu NBD PartOnly 8720-32C | 97304-8720-32C | \$ 919.00 | 10% | <i>\$833.30</i> |
| EW Edu NBD PartOnly 8720-32C-AC-F | 97304-8720-32C-AC-F | \$ 919.00 | 10% | <i>\$833.30</i> |
| EW Edu NBD PartOnly 8720-32C-AC-R | 97304-8720-32C-AC-R | \$ 919.00 | 10% | <i>\$833.30</i> |
| EW Edu NBD PartOnly 8720-32C-DC-F | 97304-8720-32C-DC-F | \$ 919.00 | 10% | <i>\$833.30</i> |
| EW Edu NBD PartOnly 8720-32C-DC-R | 97304-8720-32C-DC-R | \$ 919.00 | 10% | <i>\$833.30</i> |
| EW Edu NBD PartOnly-8806 | 97304-8806 | \$ 558.00 | 10% | <i>\$505.97</i> |
| EW Edu NBD PartOnly-8810 | 97304-8810 | \$ 1,450.00 | 10% | <i>\$1,314.79</i> |
| EW Edu NBD PartOnly 8820-40C | 97304-8820-40C | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |
| EW Edu NBD PartOnly 8820-40C-AC-F | 97304-8820-40C-AC-F | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |
| EW Edu NBD PartOnly 8820-40C-AC-R | 97304-8820-40C-AC-R | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |
| EW Edu NBD PartOnly 8820-40C-DC-F | 97304-8820-40C-DC-F | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |

| | | | | |
|---------------------------------------|-------------------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly 8820-40C-DC-R | 97304-8820-40C-DC-R | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |
| EW Edu NBD PartOnly 8820-80C | 97304-8820-80C | \$ 3,403.00 | 10% | <i>\$3,085.67</i> |
| EW Edu NBD PartOnly 8820-80C-AC-F | 97304-8820-80C-AC-F | \$ 3,403.00 | 10% | <i>\$3,085.67</i> |
| EW Edu NBD PartOnly 8820-80C-AC-R | 97304-8820-80C-AC-R | \$ 3,403.00 | 10% | <i>\$3,085.67</i> |
| EW Edu NBD PartOnly 8820-80C-DC-F | 97304-8820-80C-DC-F | \$ 3,403.00 | 10% | <i>\$3,085.67</i> |
| EW Edu NBD PartOnly 8820-80C-DC-R | 97304-8820-80C-DC-R | \$ 3,403.00 | 10% | <i>\$3,085.67</i> |
| EW Edu NBD PartOnly 9920-16C | 97304-9920-16C | \$ 2,263.00 | 10% | <i>\$2,051.98</i> |
| EW Edu NBD PartOnly 9920-4D | 97304-9920-4D | \$ 2,263.00 | 10% | <i>\$2,051.98</i> |
| EW Edu NBD PartOnly 9920-NPB-8 | 97304-9920-NPB-8 | \$ 4,113.00 | 10% | <i>\$3,729.46</i> |
| EW Edu NBD PartOnly AH-AP-1130-AC-FCC | 97304-AH-AP-1130-AC-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AH-AP-122-AC-FCC | 97304-AH-AP-122-AC-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AH-AP-130-AC-FCC | 97304-AH-AP-130-AC-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AH-AP-150W-AC-FCC | 97304-AH-AP-150W-AC-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AH-AP-230-AC-FCC | 97304-AH-AP-230-AC-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AH-AP-250-AC-FCC | 97304-AH-AP-250-AC-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AH-AP-550-AC-FCC | 97304-AH-AP-550-AC-FCC | \$ 32.00 | 10% | <i>\$29.02</i> |
| EW Edu NBD PartOnly AH-AP-630-AX-FCC | 97304-AH-AP-630-AX-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AH-AP-650-AX-FCC | 97304-AH-AP-650-AX-FCC | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly AH-AP-650X-AX-FCC | 97304-AH-AP-650X-AX-FCC | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly AH-ATOM-FCC | 97304-AH-ATOM-FCC | \$ 28.00 | 10% | <i>\$25.39</i> |

| | | | | |
|---------------------------------------|-------------------------|----------|-----|----------------|
| EW Edu NBD PartOnly AH-SR-2148P | 97304-AH-SR-2148P | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly AH-SR-2208P-NA | 97304-AH-SR-2208P-NA | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly AH-SR-2224P-NA | 97304-AH-SR-2224P-NA | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly AH-SR-2324P-NA | 97304-AH-SR-2324P-NA | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly AH-SR-2348P-NA | 97304-AH-SR-2348P-NA | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly AH-XR200P-US | 97304-AH-XR200P-US | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly AH-XR600P-US | 97304-AH-XR600P-US | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly AP-8533-68SB30-IL | 97304-AP-8533-68SB30-IL | \$ 80.00 | 10% | <i>\$72.54</i> |
| EW Edu NBD PartOnly AP3000-IL | 97304-AP3000-IL | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly AP3000-TN | 97304-AP3000-TN | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly AP3000-WW | 97304-AP3000-WW | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly AP3000X-WW | 97304-AP3000X-WW | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly AP302W-CAN | 97304-AP302W-CAN | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Edu NBD PartOnly AP302W-FCC | 97304-AP302W-FCC | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Edu NBD PartOnly AP302W-WR | 97304-AP302W-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Edu NBD PartOnly AP305C-1-CAN | 97304-AP305C-1-CAN | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Edu NBD PartOnly AP305C-1-EG | 97304-AP305C-1-EG | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Edu NBD PartOnly AP305C-1-FCC | 97304-AP305C-1-FCC | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Edu NBD PartOnly AP305C-1-IL | 97304-AP305C-1-IL | \$ 29.00 | 10% | <i>\$26.30</i> |

| | | | | |
|---------------------------------|-------------------|----------|-----|----------------|
| EW Edu NBD PartOnly AP305C-1-WR | 97304-AP305C-1-WR | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Edu NBD PartOnly AP305C-FCC | 97304-AP305C-FCC | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly AP305C-WR | 97304-AP305C-WR | \$ 34.00 | 6% | <i>\$32.20</i> |
| EW Edu NBD PartOnly AP305CX-FCC | 97304-AP305CX-FCC | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly AP310e-1-WR | 97304-AP310e-1-WR | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly AP310e-CAN | 97304-AP310e-CAN | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly AP310e-FCC | 97304-AP310e-FCC | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly AP310e-IL | 97304-AP310e-IL | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly AP310e-WR | 97304-AP310e-WR | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly AP310i-1-WR | 97304-AP310i-1-WR | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly AP310i-CAN | 97304-AP310i-CAN | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Edu NBD PartOnly AP310i-FCC | 97304-AP310i-FCC | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly AP310i-IL | 97304-AP310i-IL | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly AP310i-WR | 97304-AP310i-WR | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly AP360e-CAN | 97304-AP360e-CAN | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly AP360e-FCC | 97304-AP360e-FCC | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly AP360e-IL | 97304-AP360e-IL | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly AP360e-WR | 97304-AP360e-WR | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly AP360i-CAN | 97304-AP360i-CAN | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly AP360i-FCC | 97304-AP360i-FCC | \$ 27.00 | 10% | <i>\$24.48</i> |

| | | | | |
|----------------------------------|--------------------|----------|-----|----------------|
| EW Edu NBD PartOnly AP360i-WR | 97304-AP360i-WR | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly AP4000-WW | 97304-AP4000-1-WW | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AP4000-IL | 97304-AP4000-IL | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AP4000-WW | 97304-AP4000-WW | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AP410C-1-CAN | 97304-AP410C-1-CAN | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly AP410C-1-EG | 97304-AP410C-1-EG | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly AP410C-1-FCC | 97304-AP410C-1-FCC | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly AP410C-1-IL | 97304-AP410C-1-IL | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly AP410C-1-WR | 97304-AP410C-1-WR | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly AP410C-FCC | 97304-AP410C-FCC | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AP410e-CAN | 97304-AP410e-CAN | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly AP410e-FCC | 97304-AP410e-FCC | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Edu NBD PartOnly AP410e-WR | 97304-AP410e-WR | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Edu NBD PartOnly AP410i-1-FCC | 97304-AP410i-1-FCC | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly AP410i-1-WR | 97304-AP410i-1-WR | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly AP410i-CAN | 97304-AP410i-CAN | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly AP410i-FCC | 97304-AP410i-FCC | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly AP410i-IL | 97304-AP410i-IL | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly AP410i-WR | 97304-AP410i-WR | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly AP460C-FCC | 97304-AP460C-FCC | \$ 32.00 | 10% | <i>\$29.02</i> |

| | | | | |
|------------------------------------|----------------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly AP460e-CAN | 97304-AP460e-CAN | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW Edu NBD PartOnly AP460e-FCC | 97304-AP460e-FCC | \$ 52.00 | 10% | <i>\$47.15</i> |
| EW Edu NBD PartOnly AP460e-WR | 97304-AP460e-WR | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW Edu NBD PartOnly AP460i-CAN | 97304-AP460i-CAN | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW Edu NBD PartOnly AP460i-FCC | 97304-AP460i-FCC | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW Edu NBD PartOnly AP460i-IL | 97304-AP460i-IL | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW Edu NBD PartOnly AP460i-WR | 97304-AP460i-WR | \$ 48.00 | 10% | <i>\$43.52</i> |
| EW Edu NBD PartOnly AP460S12C-FCC | 97304-AP460S12C-FCC | \$ 32.00 | 10% | <i>\$29.02</i> |
| EW Edu NBD PartOnly AP460S6C-FCC | 97304-AP460S6C-FCC | \$ 32.00 | 10% | <i>\$29.02</i> |
| EW Edu NBD PartOnly AP5010-IL | 97304-AP5010-IL | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly AP5010-WW | 97304-AP5010-WW | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly AP5020-WW | 97304-AP5020-WW | \$ 77.96 | 6% | <i>\$73.83</i> |
| EW Edu NBD PartOnly AP5050D-WW | 97304-AP5050D-WW | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW Edu NBD PartOnly AP5050U-WW | 97304-AP5050U-WW | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW Edu NBD PartOnly AP505i-FCC | 97304-AP505i-FCC | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW Edu NBD PartOnly AP505i-FCC-TAA | 97304-AP505i-FCC-TAA | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW Edu NBD PartOnly AP505i-WR | 97304-AP505i-WR | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW Edu NBD PartOnly AP510C-FCC | 97304-AP510C-FCC | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly AP510C-WW | 97304-AP510C-WW | \$ 30.00 | 10% | <i>\$27.20</i> |

| | | | | |
|------------------------------------|----------------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly AP510CX-FCC | 97304-AP510CX-FCC | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly AP510CX-WW | 97304-AP510CX-WW | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly AP510e-FCC | 97304-AP510e-FCC | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW Edu NBD PartOnly AP510e-FCC-TAA | 97304-AP510e-FCC-TAA | \$ 83.00 | 10% | <i>\$75.26</i> |
| EW Edu NBD PartOnly AP510e-WR | 97304-AP510e-WR | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW Edu NBD PartOnly AP510i-1-FCC | 97304-AP510i-1-FCC | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW Edu NBD PartOnly AP510i-1-WR | 97304-AP510i-1-WR | \$ 65.00 | 10% | <i>\$58.94</i> |
| EW Edu NBD PartOnly AP510i-FCC | 97304-AP510i-FCC | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW Edu NBD PartOnly AP510i-FCC-TAA | 97304-AP510i-FCC-TAA | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW Edu NBD PartOnly AP510i-WR | 97304-AP510i-WR | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW Edu NBD PartOnly AP560m-FCC | 97304-AP560m-FCC | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW Edu NBD PartOnly E2122 | 97304-E2122 | \$ 1,845.00 | 10% | <i>\$1,672.95</i> |
| EW Edu NBD PartOnly E2122-1 | 97304-E2122-1 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW Edu NBD PartOnly E3120-1 | 97304-E3120-1 | \$ 2,860.00 | 10% | <i>\$2,593.31</i> |
| EW Edu NBD PartOnly E3125 | 97304-E3125 | \$ 3,091.00 | 10% | <i>\$2,802.76</i> |
| EW Edu NBD PartOnly-H30003 | 97304-H30003 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly-H30004 | 97304-H30004 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly-H30005 | 97304-H30005 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly-H30006 | 97304-H30006 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly-H30007 | 97304-H30007 | \$ 21.00 | 10% | <i>\$19.04</i> |
| EW Edu NBD PartOnly-H30008 | 97304-H30008 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly-H30009 | 97304-H30009 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly-H30010 | 97304-H30010 | \$ 21.00 | 10% | <i>\$19.04</i> |
| EW Edu NBD PartOnly-H30011 | 97304-H30011 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly-H30012 | 97304-H30012 | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly-H30078 | 97304-H30078 | \$ 467.00 | 10% | <i>\$423.45</i> |
| EW Edu NBD PartOnly-H30104 | 97304-H30104 | \$ 430.00 | 10% | <i>\$389.90</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly-H30105 | 97304-H30105 | \$ 454.00 | 10% | <i>\$411.66</i> |
| EW Edu NBD PartOnly-H30131 | 97304-H30131 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW Edu NBD PartOnly-H30132 | 97304-H30132 | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW Edu NBD PartOnly-H30133 | 97304-H30133 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW Edu NBD PartOnly-H30134 | 97304-H30134 | \$ 892.00 | 10% | <i>\$808.82</i> |
| EW Edu NBD PartOnly-H30135 | 97304-H30135 | \$ 722.00 | 10% | <i>\$654.67</i> |
| EW Edu NBD PartOnly-H30136 | 97304-H30136 | \$ 892.00 | 10% | <i>\$808.82</i> |
| EW Edu NBD PartOnly-H30184 | 97304-H30184 | \$ 9.00 | 10% | <i>\$8.16</i> |
| EW Edu NBD PartOnly-H30185 | 97304-H30185 | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW Edu NBD PartOnly-H30186 | 97304-H30186 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly-H30188 | 97304-H30188 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly-H30189 | 97304-H30189 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly-H30190 | 97304-H30190 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30214 | 97304-H30214 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly-H30215 | 97304-H30215 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly-H30216 | 97304-H30216 | \$ 54.00 | 10% | <i>\$48.96</i> |
| EW Edu NBD PartOnly-H30217 | 97304-H30217 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30218 | 97304-H30218 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30219 | 97304-H30219 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30220 | 97304-H30220 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30221 | 97304-H30221 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30222 | 97304-H30222 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30223 | 97304-H30223 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30224 | 97304-H30224 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30225 | 97304-H30225 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30226 | 97304-H30226 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30227 | 97304-H30227 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30228 | 97304-H30228 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30229 | 97304-H30229 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30267 | 97304-H30267 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30268 | 97304-H30268 | \$ 59.00 | 10% | <i>\$53.50</i> |
| EW Edu NBD PartOnly-H30269 | 97304-H30269 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30270 | 97304-H30270 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30271 | 97304-H30271 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30272 | 97304-H30272 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30273 | 97304-H30273 | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW Edu NBD PartOnly-H30274 | 97304-H30274 | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW Edu NBD PartOnly-H30275 | 97304-H30275 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30276 | 97304-H30276 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30277 | 97304-H30277 | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW Edu NBD PartOnly-H30278 | 97304-H30278 | \$ 164.00 | 10% | <i>\$148.71</i> |
| EW Edu NBD PartOnly-H30279 | 97304-H30279 | \$ 150.00 | 10% | <i>\$136.01</i> |

| | | | | |
|-----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly-H30280 | 97304-H30280 | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW Edu NBD PartOnly-H30281 | 97304-H30281 | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW Edu NBD PartOnly-H30282 | 97304-H30282 | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW Edu NBD PartOnly-H30283 | 97304-H30283 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW Edu NBD PartOnly-H30284 | 97304-H30284 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30296 | 97304-H30296 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly-H30297 | 97304-H30297 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly-H30298 | 97304-H30298 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly-H30299 | 97304-H30299 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly-H30381 | 97304-H30381 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW Edu NBD PartOnly-H30384 | 97304-H30384 | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW Edu NBD PartOnly-H30391 | 97304-H30391 | \$ 182.00 | 10% | <i>\$165.03</i> |
| EW Edu NBD PartOnly-H30392 | 97304-H30392 | \$ 182.00 | 10% | <i>\$165.03</i> |
| EW Edu NBD PartOnly-H30393 | 97304-H30393 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW Edu NBD PartOnly-H30394 | 97304-H30394 | \$ 354.00 | 10% | <i>\$320.99</i> |
| EW Edu NBD PartOnly-H30395 | 97304-H30395 | \$ 428.00 | 10% | <i>\$388.09</i> |
| EW Edu NBD PartOnly-H30396 | 97304-H30396 | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW Edu NBD PartOnly-H30397 | 97304-H30397 | \$ 463.00 | 10% | <i>\$419.83</i> |
| EW Edu NBD PartOnly-H30398 | 97304-H30398 | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW Edu NBD PartOnly-H30400 | 97304-H30400 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly-H30401 | 97304-H30401 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly-H30402 | 97304-H30402 | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW Edu NBD PartOnly-H30403 | 97304-H30403 | \$ 104.00 | 10% | <i>\$94.30</i> |
| EW Edu NBD PartOnly-H30434 | 97304-H30434 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly-H30480 | 97304-H30480 | \$ 124.00 | 10% | <i>\$112.44</i> |
| EW Edu NBD PartOnly H305495 | 97304-H30495 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW Edu NBD PartOnly-H30496 | 97304-H30496 | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW Edu NBD PartOnly-H30498 | 97304-H30498 | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW Edu NBD PartOnly-H30499 | 97304-H30499 | \$ 136.00 | 10% | <i>\$123.32</i> |
| EW Edu NBD PartOnly-H30501 | 97304-H30501 | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW Edu NBD PartOnly-H30502 | 97304-H30502 | \$ 596.00 | 10% | <i>\$540.42</i> |
| EW Edu NBD PartOnly-H30503 | 97304-H30503 | \$ 136.00 | 10% | <i>\$123.32</i> |
| EW Edu NBD PartOnly-H30505 | 97304-H30505 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW Edu NBD PartOnly-H30506 | 97304-H30506 | \$ 958.00 | 10% | <i>\$868.67</i> |
| EW Edu NBD PartOnly-H30509 | 97304-H30509 | \$ 596.00 | 10% | <i>\$540.42</i> |
| EW Edu NBD PartOnly-H30510 | 97304-H30510 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW Edu NBD PartOnly-H30511 | 97304-H30511 | \$ 958.00 | 10% | <i>\$868.67</i> |
| EW Edu NBD PartOnly-H30512 | 97304-H30512 | \$ 136.00 | 10% | <i>\$123.32</i> |
| EW Edu NBD PartOnly-H30513 | 97304-H30513 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW Edu NBD PartOnly-H30525 | 97304-H30525 | \$ 958.00 | 10% | <i>\$868.67</i> |
| EW Edu NBD PartOnly-H30526 | 97304-H30526 | \$ 709.00 | 10% | <i>\$642.89</i> |

| | | | | |
|-------------------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly-H30528 | 97304-H30528 | \$ 1,103.00 | 10% | <i>\$1,000.15</i> |
| EW Edu NBD PartOnly-H30531 | 97304-H30531 | \$ 1,582.00 | 10% | <i>\$1,434.48</i> |
| EW Edu NBD PartOnly-H30532 | 97304-H30532 | \$ 1,582.00 | 10% | <i>\$1,434.48</i> |
| EW Edu NBD PartOnly-H30534 | 97304-H30534 | \$ 1,611.00 | 10% | <i>\$1,460.77</i> |
| EW Edu NBD PartOnly-H30535 | 97304-H30535 | \$ 1,735.00 | 10% | <i>\$1,573.21</i> |
| EW Edu NBD PartOnly-H30536 | 97304-H30536 | \$ 1,582.00 | 10% | <i>\$1,434.48</i> |
| EW Edu NBD PartOnly-H30537 | 97304-H30537 | \$ 1,735.00 | 10% | <i>\$1,573.21</i> |
| EW Edu NBD PartOnly-H30538 | 97304-H30538 | \$ 958.00 | 10% | <i>\$868.67</i> |
| EW Edu NBD PartOnly-H30539 | 97304-H30539 | \$ 1,735.00 | 10% | <i>\$1,573.21</i> |
| EW Edu NBD PartOnly-H30540 | 97304-H30540 | \$ 1,914.00 | 10% | <i>\$1,735.52</i> |
| EW Edu NBD PartOnly-H30543 | 97304-H30543 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW Edu NBD PartOnly-H30544 | 97304-H30544 | \$ 230.00 | 10% | <i>\$208.55</i> |
| EW Edu NBD PartOnly-H30548 | 97304-H30548 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW Edu NBD PartOnly-H30549 | 97304-H30549 | \$ 216.00 | 10% | <i>\$195.86</i> |
| EW Edu NBD PartOnly-H30550 | 97304-H30550 | \$ 216.00 | 10% | <i>\$195.86</i> |
| EW Edu NBD PartOnly-H30552 | 97304-H30552 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW Edu NBD PartOnly-H30553 | 97304-H30553 | \$ 211.00 | 10% | <i>\$191.32</i> |
| EW Edu NBD PartOnly-H30569 | 97304-H30569 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW Edu NBD PartOnly-H30570 | 97304-H30570 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW Edu NBD PartOnly-H30571 | 97304-H30571 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW Edu NBD PartOnly-H30573 | 97304-H30573 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW Edu NBD PartOnly-H30574 | 97304-H30574 | \$ 778.00 | 10% | <i>\$705.45</i> |
| EW Edu NBD PartOnly-H30575 | 97304-H30575 | \$ 485.00 | 10% | <i>\$439.77</i> |
| EW Edu NBD PartOnly-H30576 | 97304-H30576 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW Edu NBD PartOnly-H30577 | 97304-H30577 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW Edu NBD PartOnly-H30578 | 97304-H30578 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW Edu NBD PartOnly-H30587 | 97304-H30587 | \$ 722.00 | 10% | <i>\$654.67</i> |
| EW Edu NBD PartOnly-H30588 | 97304-H30588 | \$ 495.00 | 10% | <i>\$448.84</i> |
| EW Edu NBD PartOnly-H30589 | 97304-H30589 | \$ 772.00 | 10% | <i>\$700.01</i> |
| EW Edu NBD PartOnly-H30632 | 97304-H30632 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Edu NBD PartOnly-H30633 | 97304-H30633 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Edu NBD PartOnly-H30643 | 97304-H30643 | \$ 1,207.00 | 10% | <i>\$1,094.45</i> |
| EW Edu NBD PartOnly-H30706 | 97304-H30706 | \$ 1,126.00 | 10% | <i>\$1,021.00</i> |
| EW Edu NBD PartOnly-H30707 | 97304-H30707 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW Edu NBD PartOnly-H30724 | 97304-H30724 | \$ 227.00 | 10% | <i>\$205.83</i> |
| EW Edu NBD PartOnly-H30725 | 97304-H30725 | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW Edu NBD PartOnly-H30726 | 97304-H30726 | \$ 1,767.00 | 10% | <i>\$1,602.23</i> |
| EW Edu NBD PartOnly-H30727 | 97304-H30727 | \$ 1,878.00 | 10% | <i>\$1,702.88</i> |
| EW Edu NBD PartOnly-H30730 | 97304-H30730 | \$ 20.00 | 10% | <i>\$18.14</i> |
| EW Edu NBD PartOnly-H30731 | 97304-H30731 | \$ 20.00 | 10% | <i>\$18.14</i> |
| EW Edu NBD PartOnly SKL8008-0810 | 97304-H30733 | \$ 2,636.00 | 10% | <i>\$2,390.19</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly STL2006-0850 | 97304-H30734 | \$ 2,013.00 | 10% | <i>\$1,825.29</i> |
| EW Edu NBD PartOnly SGL2001-0850 | 97304-H30735 | \$ 2,063.00 | 10% | <i>\$1,870.63</i> |
| EW Edu NBD PartOnly SOK2209-0204 | 97304-H30736 | \$ 339.00 | 10% | <i>\$307.39</i> |
| EW Edu NBD PartOnly H30738 | 97304-H30738 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW eRate -H30739 | 97304-H30739 | \$ 255.00 | 10% | <i>\$231.22</i> |
| EW eRate -H30740 | 97304-H30740 | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW eRate -H30741 | 97304-H30741 | \$ 263.00 | 10% | <i>\$238.48</i> |
| EW eRate -H30742 | 97304-H30742 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW eRate -H30743 | 97304-H30743 | \$ 255.00 | 10% | <i>\$231.22</i> |
| EW eRate -H30744 | 97304-H30744 | \$ 144.00 | 10% | <i>\$130.57</i> |
| EW eRate -H30745 | 97304-H30745 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW eRate -H30746 | 97304-H30746 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW eRate -H30747 | 97304-H30747 | \$ 518.00 | 10% | <i>\$469.70</i> |
| EW eRate -H30748 | 97304-H30748 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW eRate -H30749 | 97304-H30749 | \$ 1,701.00 | 10% | <i>\$1,542.38</i> |
| EW eRate -H30750 | 97304-H30750 | \$ 1,701.00 | 10% | <i>\$1,542.38</i> |
| EW eRate -H30751 | 97304-H30751 | \$ 1,011.00 | 10% | <i>\$916.72</i> |
| EW eRate -H30754 | 97304-H30754 | \$ 1,701.00 | 10% | <i>\$1,542.38</i> |
| EW eRate -H30755 | 97304-H30755 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW eRate -H30756 | 97304-H30756 | \$ 1,701.00 | 10% | <i>\$1,542.38</i> |
| EW eRate -H30757 | 97304-H30757 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW eRate -H30758 | 97304-H30758 | \$ 2,151.00 | 10% | <i>\$1,950.42</i> |
| EW eRate -H30759 | 97304-H30759 | \$ 2,162.00 | 10% | <i>\$1,960.39</i> |
| EW eRate -H30760 | 97304-H30760 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW eRate -H30761 | 97304-H30761 | \$ 755.00 | 10% | <i>\$684.60</i> |
| EW eRate -H30762 | 97304-H30762 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW eRate -H30763 | 97304-H30763 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW eRate -H30764 | 97304-H30764 | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |
| EW eRate -H30765 | 97304-H30765 | \$ 1,030.00 | 10% | <i>\$933.95</i> |
| EW eRate -H30766 | 97304-H30766 | \$ 2,006.00 | 10% | <i>\$1,818.94</i> |
| EW eRate -H30767 | 97304-H30767 | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |
| EW eRate H30769 | 97304-H30769 | \$ 739.00 | 10% | <i>\$670.09</i> |
| EW Edu NBD PartOnly H30773 | 97304-H30773 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW Edu NBD PartOnly H30774 | 97304-H30774 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H30775 | 97304-H30775 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H30776 | 97304-H30776 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW Edu NBD PartOnly H30777 | 97304-H30777 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H30778 | 97304-H30778 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H30779 | 97304-H30779 | \$ 41.00 | 10% | <i>\$37.18</i> |

| | | | | |
|----------------------------|--------------|----------|-----|---------|
| EW Edu NBD PartOnly H30780 | 97304-H30780 | \$ 42.00 | 10% | \$38.08 |
| EW Edu NBD PartOnly H30781 | 97304-H30781 | \$ 42.00 | 10% | \$38.08 |
| EW Edu NBD PartOnly H30782 | 97304-H30782 | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly H30783 | 97304-H30783 | \$ 32.00 | 10% | \$29.02 |
| EW Edu NBD PartOnly H30784 | 97304-H30784 | \$ 32.00 | 10% | \$29.02 |
| EW Edu NBD PartOnly H30785 | 97304-H30785 | \$ 41.00 | 10% | \$37.18 |
| EW Edu NBD PartOnly H30786 | 97304-H30786 | \$ 42.00 | 10% | \$38.08 |
| EW Edu NBD PartOnly H30787 | 97304-H30787 | \$ 41.00 | 10% | \$37.18 |
| EW Edu NBD PartOnly H30788 | 97304-H30788 | \$ 42.00 | 10% | \$38.08 |
| EW Edu NBD PartOnly H30789 | 97304-H30789 | \$ 32.00 | 10% | \$29.02 |
| EW Edu NBD PartOnly H30790 | 97304-H30790 | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly H30791 | 97304-H30791 | \$ 32.00 | 10% | \$29.02 |
| EW Edu NBD PartOnly H30793 | 97304-H30793 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H30794 | 97304-H30794 | \$ 39.00 | 10% | \$35.36 |
| EW Edu NBD PartOnly H30795 | 97304-H30795 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30796 | 97304-H30796 | \$ 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H30797 | 97304-H30797 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30798 | 97304-H30798 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30799 | 97304-H30799 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30800 | 97304-H30800 | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly H30801 | 97304-H30801 | \$ 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H30802 | 97304-H30802 | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly H30803 | 97304-H30803 | \$ 56.00 | 10% | \$50.78 |
| EW Edu NBD PartOnly H30804 | 97304-H30804 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30805 | 97304-H30805 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30806 | 97304-H30806 | \$ 56.00 | 10% | \$50.78 |
| EW Edu NBD PartOnly H30807 | 97304-H30807 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30808 | 97304-H30808 | \$ 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H30809 | 97304-H30809 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30810 | 97304-H30810 | \$ 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H30811 | 97304-H30811 | \$ 56.00 | 10% | \$50.78 |
| EW Edu NBD PartOnly H30812 | 97304-H30812 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30813 | 97304-H30813 | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly H30814 | 97304-H30814 | \$ 56.00 | 10% | \$50.78 |
| EW Edu NBD PartOnly H30815 | 97304-H30815 | \$ 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H30816 | 97304-H30816 | \$ 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H30817 | 97304-H30817 | \$ 56.00 | 10% | \$50.78 |
| EW Edu NBD PartOnly H30818 | 97304-H30818 | \$ 22.00 | 10% | \$19.95 |
| EW Edu NBD PartOnly H30819 | 97304-H30819 | \$ 56.00 | 10% | \$50.78 |
| EW Edu NBD PartOnly H30820 | 97304-H30820 | \$ 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H30821 | 97304-H30821 | \$ 31.00 | 10% | \$28.11 |
| EW Edu NBD PartOnly H30822 | 97304-H30822 | \$ 22.00 | 10% | \$19.95 |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H30823 | 97304-H30823 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly H30824 | 97304-H30824 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H30825 | 97304-H30825 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly H30826 | 97304-H30826 | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW Edu NBD PartOnly H30827 | 97304-H30827 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H30828 | 97304-H30828 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H30829 | 97304-H30829 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly H30830 | 97304-H30830 | \$ 56.00 | 10% | <i>\$50.78</i> |
| EW Edu NBD PartOnly H30831 | 97304-H30831 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H30832 | 97304-H30832 | \$ 359.00 | 10% | <i>\$325.52</i> |
| EW Edu NBD PartOnly H30833 | 97304-H30833 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW Edu NBD PartOnly H30834 | 97304-H30834 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW Edu NBD PartOnly H30836 | 97304-H30836 | \$ 359.00 | 10% | <i>\$325.52</i> |
| EW Edu NBD PartOnly H30838 | 97304-H30838 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H30839 | 97304-H30839 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H30840 | 97304-H30840 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H30841 | 97304-H30841 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H30842 | 97304-H30842 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H30843 | 97304-H30843 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H30844 | 97304-H30844 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H30845 | 97304-H30845 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H30846 | 97304-H30846 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30847 | 97304-H30847 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30848 | 97304-H30848 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30849 | 97304-H30849 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30850 | 97304-H30850 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30851 | 97304-H30851 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30852 | 97304-H30852 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30853 | 97304-H30853 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30854 | 97304-H30854 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30855 | 97304-H30855 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30856 | 97304-H30856 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30857 | 97304-H30857 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30858 | 97304-H30858 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30859 | 97304-H30859 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30860 | 97304-H30860 | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW Edu NBD PartOnly H30866 | 97304-H30866 | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW Edu NBD PartOnly H30867 | 97304-H30867 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30868 | 97304-H30868 | \$ 42.00 | 10% | <i>\$38.08</i> |
| EW Edu NBD PartOnly H30869 | 97304-H30869 | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW Edu NBD PartOnly H30870 | 97304-H30870 | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW Edu NBD PartOnly H30871 | 97304-H30871 | \$ 160.00 | 10% | <i>\$145.08</i> |

| | | | | |
|----------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly H30872 | 97304-H30872 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW Edu NBD PartOnly H30873 | 97304-H30873 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW Edu NBD PartOnly H30874 | 97304-H30874 | \$ 78.00 | 10% | <i>\$70.73</i> |
| EW Edu NBD PartOnly H30875 | 97304-H30875 | \$ 9.00 | 10% | <i>\$8.16</i> |
| EW Edu NBD PartOnly H30876 | 97304-H30876 | \$ 6.00 | 10% | <i>\$5.44</i> |
| EW Edu NBD PartOnly H30877 | 97304-H30877 | \$ 9.00 | 10% | <i>\$8.16</i> |
| EW Edu NBD PartOnly H30878 | 97304-H30878 | \$ 9.00 | 10% | <i>\$8.16</i> |
| EW Edu NBD PartOnly H30891 | 97304-H30891 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H30892 | 97304-H30892 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H30893 | 97304-H30893 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Edu NBD PartOnly H30894 | 97304-H30894 | \$ 9.00 | 10% | <i>\$8.16</i> |
| EW Edu NBD PartOnly H30895 | 97304-H30895 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H30896 | 97304-H30896 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW Edu NBD PartOnly H30897 | 97304-H30897 | \$ 167.00 | 10% | <i>\$151.43</i> |
| EW Edu NBD PartOnly H30898 | 97304-H30898 | \$ 183.00 | 10% | <i>\$165.94</i> |
| EW Edu NBD PartOnly H30900 | 97304-H30900 | \$ 544.00 | 10% | <i>\$493.27</i> |
| EW Edu NBD PartOnly H30901 | 97304-H30901 | \$ 727.00 | 10% | <i>\$659.21</i> |
| EW Edu NBD PartOnly H30902 | 97304-H30902 | \$ 760.00 | 10% | <i>\$689.13</i> |
| EW Edu NBD PartOnly H30904 | 97304-H30904 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW Edu NBD PartOnly H30905 | 97304-H30905 | \$ 1,801.00 | 10% | <i>\$1,633.06</i> |
| EW Edu NBD PartOnly H30906 | 97304-H30906 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H30912 | 97304-H30912 | \$ 131.00 | 10% | <i>\$118.78</i> |
| EW Edu NBD PartOnly H30913 | 97304-H30913 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Edu NBD PartOnly H30914 | 97304-H30914 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H30915 | 97304-H30915 | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly H30916 | 97304-H30916 | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly H30917 | 97304-H30917 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Edu NBD PartOnly H30918 | 97304-H30918 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Edu NBD PartOnly H30946 | 97304-H30946 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H30948 | 97304-H30948 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H30950 | 97304-H30950 | \$ 55.00 | 10% | <i>\$49.87</i> |
| EW Edu NBD PartOnly H30951 | 97304-H30951 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H30952 | 97304-H30952 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H30966 | 97304-H30966 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H30967 | 97304-H30967 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW Edu NBD PartOnly H30968 | 97304-H30968 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H30969 | 97304-H30969 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H30970 | 97304-H30970 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly H30971 | 97304-H30971 | \$ 53.00 | 10% | <i>\$48.06</i> |
| EW Edu NBD PartOnly H30972 | 97304-H30972 | \$ 66.00 | 10% | <i>\$59.85</i> |
| EW Edu NBD PartOnly H30973 | 97304-H30973 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW Edu NBD PartOnly H30974 | 97304-H30974 | \$ 88.00 | 10% | <i>\$79.79</i> |

| | | | | |
|----------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly H30975 | 97304-H30975 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW Edu NBD PartOnly H30976 | 97304-H30976 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW Edu NBD PartOnly H30977 | 97304-H30977 | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW Edu NBD PartOnly H30978 | 97304-H30978 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW Edu NBD PartOnly H30995 | 97304-H30995 | \$ 508.00 | 10% | <i>\$460.63</i> |
| EW Edu NBD PartOnly H31030 | 97304-H31030 | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW Edu NBD PartOnly H31031 | 97304-H31031 | \$ 145.00 | 10% | <i>\$131.48</i> |
| EW Edu NBD PartOnly H31033 | 97304-H31033 | \$ 886.00 | 10% | <i>\$803.38</i> |
| EW Edu NBD PartOnly H31034 | 97304-H31034 | \$ 492.00 | 10% | <i>\$446.12</i> |
| EW Edu NBD PartOnly H31035 | 97304-H31035 | \$ 516.00 | 10% | <i>\$467.88</i> |
| EW Edu NBD PartOnly H31036 | 97304-H31036 | \$ 1,032.00 | 10% | <i>\$935.77</i> |
| EW Edu NBD PartOnly H31040 | 97304-H31040 | \$ 95.00 | 10% | <i>\$86.14</i> |
| EW Edu NBD PartOnly H31041 | 97304-H31041 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Edu NBD PartOnly H31042 | 97304-H31042 | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW Edu NBD PartOnly H31043 | 97304-H31043 | \$ 45.00 | 10% | <i>\$40.80</i> |
| EW Edu NBD PartOnly H31047 | 97304-H31047 | \$ 98.00 | 10% | <i>\$88.86</i> |
| EW Edu NBD PartOnly H31049 | 97304-H31049 | \$ 413.00 | 10% | <i>\$374.49</i> |
| EW Edu NBD PartOnly H31060 | 97304-H31060 | \$ 5.00 | 10% | <i>\$4.53</i> |
| EW Edu NBD PartOnly H31062 | 97304-H31062 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H31066 | 97304-H31066 | \$ 18.00 | 10% | <i>\$16.32</i> |
| EW Edu NBD PartOnly H31068 | 97304-H31068 | \$ 21.00 | 10% | <i>\$19.04</i> |
| EW Edu NBD PartOnly H31076 | 97304-H31076 | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW Edu NBD PartOnly H31077 | 97304-H31077 | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW Edu NBD PartOnly H31078 | 97304-H31078 | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW Edu NBD PartOnly H31103 | 97304-H31103 | \$ 941.00 | 10% | <i>\$853.25</i> |
| EW Edu NBD PartOnly H31119 | 97304-H31119 | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW Edu NBD PartOnly H31124 | 97304-H31124 | \$ 44.00 | 10% | <i>\$39.90</i> |
| EW Edu NBD PartOnly H31127 | 97304-H31127 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW Edu NBD PartOnly H31132 | 97304-H31132 | \$ 89.00 | 10% | <i>\$80.70</i> |
| EW Edu NBD PartOnly H31134 | 97304-H31134 | \$ 9.00 | 10% | <i>\$8.16</i> |
| EW Edu NBD PartOnly H31135 | 97304-H31135 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H31136 | 97304-H31136 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H31137 | 97304-H31137 | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Edu NBD PartOnly H31197 | 97304-H31197 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H31198 | 97304-H31198 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H31199 | 97304-H31199 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H31200 | 97304-H31200 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H31201 | 97304-H31201 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H31202 | 97304-H31202 | \$ 39.00 | 10% | <i>\$35.36</i> |
| EW Edu NBD PartOnly H31203 | 97304-H31203 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H31204 | 97304-H31204 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H31205 | 97304-H31205 | \$ 51.00 | 10% | <i>\$46.24</i> |

| | | | | |
|----------------------------|--------------|--------------|-----|-------------------|
| EW Edu NBD PartOnly H31206 | 97304-H31206 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H31207 | 97304-H31207 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H31208 | 97304-H31208 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H31210 | 97304-H31210 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H31335 | 97304-H31335 | \$ 53.00 | 10% | <i>\$48.06</i> |
| EW Edu NBD PartOnly H31337 | 97304-H31337 | \$ 2,213.00 | 10% | <i>\$2,006.64</i> |
| EW Edu NBD PartOnly H31338 | 97304-H31338 | \$ 2,213.00 | 10% | <i>\$2,006.64</i> |
| EW Edu NBD PartOnly H31339 | 97304-H31339 | \$ 381.00 | 10% | <i>\$345.47</i> |
| EW Edu NBD PartOnly H31340 | 97304-H31340 | \$ 801.00 | 10% | <i>\$726.31</i> |
| EW Edu NBD PartOnly H31341 | 97304-H31341 | \$ 1,139.00 | 10% | <i>\$1,032.79</i> |
| EW Edu NBD PartOnly H31342 | 97304-H31342 | \$ 358.00 | 10% | <i>\$324.62</i> |
| EW Edu NBD PartOnly H31343 | 97304-H31343 | \$ 528.00 | 10% | <i>\$478.76</i> |
| EW Edu NBD PartOnly H31344 | 97304-H31344 | \$ 528.00 | 10% | <i>\$478.76</i> |
| EW Edu NBD PartOnly H31345 | 97304-H31345 | \$ 528.00 | 10% | <i>\$478.76</i> |
| EW Edu NBD PartOnly H31346 | 97304-H31346 | \$ 528.00 | 10% | <i>\$478.76</i> |
| EW Edu NBD PartOnly H31348 | 97304-H31348 | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW Edu NBD PartOnly H31349 | 97304-H31349 | \$ 88.00 | 10% | <i>\$79.79</i> |
| EW Edu NBD PartOnly H31350 | 97304-H31350 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW Edu NBD PartOnly H31351 | 97304-H31351 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H31352 | 97304-H31352 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H31353 | 97304-H31353 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly H31354 | 97304-H31354 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW Edu NBD PartOnly H31355 | 97304-H31355 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW Edu NBD PartOnly H31356 | 97304-H31356 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW Edu NBD PartOnly H31357 | 97304-H31357 | \$ 92.00 | 10% | <i>\$83.42</i> |
| EW Edu NBD PartOnly H31358 | 97304-H31358 | \$ 16.00 | 10% | <i>\$14.51</i> |
| EW Edu NBD PartOnly H31359 | 97304-H31359 | \$ 18.00 | 10% | <i>\$16.32</i> |
| EW Edu NBD PartOnly H31360 | 97304-H31360 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H31361 | 97304-H31361 | \$ 695.00 | 10% | <i>\$630.19</i> |
| EW Edu NBD PartOnly H31362 | 97304-H31362 | \$ 10,407.00 | 10% | <i>\$9,436.55</i> |
| EW Edu NBD PartOnly H31363 | 97304-H31363 | \$ 10,407.00 | 10% | <i>\$9,436.55</i> |
| EW Edu NBD PartOnly H31364 | 97304-H31364 | \$ 3,636.00 | 10% | <i>\$3,296.94</i> |

| | | | | |
|----------------------------|--------------|--------------|-----|-------------|
| EW Edu NBD PartOnly H31365 | 97304-H31365 | \$ 3,636.00 | 10% | \$3,296.94 |
| EW Edu NBD PartOnly H31366 | 97304-H31366 | \$ 2,781.00 | 10% | \$2,521.67 |
| EW Edu NBD PartOnly H31367 | 97304-H31367 | \$ 2,781.00 | 10% | \$2,521.67 |
| EW Edu NBD PartOnly H31369 | 97304-H31369 | \$ 41.00 | 10% | \$37.18 |
| EW Edu NBD PartOnly H31370 | 97304-H31370 | \$ 41.00 | 10% | \$37.18 |
| EW Edu NBD PartOnly H32010 | 97304-H32010 | \$ 77.00 | 10% | \$69.82 |
| EW Edu NBD PartOnly H32011 | 97304-H32011 | \$ 77.00 | 10% | \$69.82 |
| EW Edu NBD PartOnly H32012 | 97304-H32012 | \$ 1,223.00 | 10% | \$1,108.96 |
| EW Edu NBD PartOnly H32013 | 97304-H32013 | \$ 1,223.00 | 10% | \$1,108.96 |
| EW Edu NBD PartOnly H32014 | 97304-H32014 | \$ 1,223.00 | 10% | \$1,108.96 |
| EW Edu NBD PartOnly H32015 | 97304-H32015 | \$ 1,223.00 | 10% | \$1,108.96 |
| EW Edu NBD PartOnly H32016 | 97304-H32016 | \$ 1,086.00 | 10% | \$984.73 |
| EW Edu NBD PartOnly H32017 | 97304-H32017 | \$ 1,086.00 | 10% | \$984.73 |
| EW Edu NBD PartOnly H32018 | 97304-H32018 | \$ 1,086.00 | 10% | \$984.73 |
| EW Edu NBD PartOnly H32019 | 97304-H32019 | \$ 1,086.00 | 10% | \$984.73 |
| EW Edu NBD PartOnly H32020 | 97304-H32020 | \$ 10,707.00 | 10% | \$9,708.57 |
| EW Edu NBD PartOnly H32021 | 97304-H32021 | \$ 10,707.00 | 10% | \$9,708.57 |
| EW Edu NBD PartOnly H32022 | 97304-H32022 | \$ 10,707.00 | 10% | \$9,708.57 |
| EW Edu NBD PartOnly H32023 | 97304-H32023 | \$ 10,707.00 | 10% | \$9,708.57 |
| EW Edu NBD PartOnly H32028 | 97304-H32028 | \$ 21,057.00 | 10% | \$19,093.43 |
| EW Edu NBD PartOnly H32029 | 97304-H32029 | \$ 21,057.00 | 10% | \$19,093.43 |
| EW Edu NBD PartOnly H32030 | 97304-H32030 | \$ 21,660.00 | 10% | \$19,640.21 |
| EW Edu NBD PartOnly H32031 | 97304-H32031 | \$ 21,660.00 | 10% | \$19,640.21 |
| EW Edu NBD PartOnly H32032 | 97304-H32032 | \$ 21,660.00 | 10% | \$19,640.21 |
| EW Edu NBD PartOnly H32033 | 97304-H32033 | \$ 21,660.00 | 10% | \$19,640.21 |
| EW Edu NBD PartOnly H32038 | 97304-H32038 | \$ 3,740.00 | 10% | \$3,391.25 |
| EW Edu NBD PartOnly H32039 | 97304-H32039 | \$ 3,740.00 | 10% | \$3,391.25 |
| EW Edu NBD PartOnly H32040 | 97304-H32040 | \$ 3,740.00 | 10% | \$3,391.25 |
| EW Edu NBD PartOnly H32041 | 97304-H32041 | \$ 3,740.00 | 10% | \$3,391.25 |
| EW Edu NBD PartOnly H32046 | 97304-H32046 | \$ 5,192.00 | 10% | \$4,707.85 |
| EW Edu NBD PartOnly H32047 | 97304-H32047 | \$ 5,192.00 | 10% | \$4,707.85 |
| EW Edu NBD PartOnly H32048 | 97304-H32048 | \$ 5,192.00 | 10% | \$4,707.85 |
| EW Edu NBD PartOnly H32049 | 97304-H32049 | \$ 5,192.00 | 10% | \$4,707.85 |
| EW Edu NBD PartOnly H32054 | 97304-H32054 | \$ 3,740.00 | 10% | \$3,391.25 |
| EW Edu NBD PartOnly H32055 | 97304-H32055 | \$ 5,192.00 | 10% | \$4,707.85 |
| EW Edu NBD PartOnly H32056 | 97304-H32056 | \$ 1,190.00 | 10% | \$1,079.03 |
| EW Edu NBD PartOnly H32057 | 97304-H32057 | \$ 1,190.00 | 10% | \$1,079.03 |
| EW Edu NBD PartOnly H32058 | 97304-H32058 | \$ 1,190.00 | 10% | \$1,079.03 |
| EW Edu NBD PartOnly H32059 | 97304-H32059 | \$ 1,190.00 | 10% | \$1,079.03 |
| EW Edu NBD PartOnly H32060 | 97304-H32060 | \$ 1,449.00 | 10% | \$1,313.88 |
| EW Edu NBD PartOnly H32061 | 97304-H32061 | \$ 1,521.00 | 10% | \$1,379.17 |
| EW Edu NBD PartOnly H32062 | 97304-H32062 | \$ 1,464.00 | 10% | \$1,327.48 |

| | | | | |
|----------------------------|--------------|--------------|-----|--------------------|
| EW Edu NBD PartOnly H32063 | 97304-H32063 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW Edu NBD PartOnly H32064 | 97304-H32064 | \$ 1,464.00 | 10% | <i>\$1,327.48</i> |
| EW Edu NBD PartOnly H32065 | 97304-H32065 | \$ 791.00 | 10% | <i>\$717.24</i> |
| EW Edu NBD PartOnly H32066 | 97304-H32066 | \$ 791.00 | 10% | <i>\$717.24</i> |
| EW Edu NBD PartOnly H32067 | 97304-H32067 | \$ 791.00 | 10% | <i>\$717.24</i> |
| EW Edu NBD PartOnly H32068 | 97304-H32068 | \$ 791.00 | 10% | <i>\$717.24</i> |
| EW Edu NBD PartOnly H32069 | 97304-H32069 | \$ 973.00 | 10% | <i>\$882.27</i> |
| EW Edu NBD PartOnly H32070 | 97304-H32070 | \$ 973.00 | 10% | <i>\$882.27</i> |
| EW Edu NBD PartOnly H32071 | 97304-H32071 | \$ 973.00 | 10% | <i>\$882.27</i> |
| EW Edu NBD PartOnly H32072 | 97304-H32072 | \$ 973.00 | 10% | <i>\$882.27</i> |
| EW Edu NBD PartOnly H32073 | 97304-H32073 | \$ 15,213.00 | 10% | <i>\$13,794.39</i> |
| EW Edu NBD PartOnly H32074 | 97304-H32074 | \$ 15,213.00 | 10% | <i>\$13,794.39</i> |
| EW Edu NBD PartOnly H32075 | 97304-H32075 | \$ 20,672.00 | 10% | <i>\$18,744.34</i> |
| EW Edu NBD PartOnly H32076 | 97304-H32076 | \$ 20,672.00 | 10% | <i>\$18,744.34</i> |
| EW Edu NBD PartOnly H32090 | 97304-H32090 | \$ 522.00 | 10% | <i>\$473.32</i> |
| EW Edu NBD PartOnly H32101 | 97304-H32101 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32102 | 97304-H32102 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32103 | 97304-H32103 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32104 | 97304-H32104 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32105 | 97304-H32105 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32106 | 97304-H32106 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32107 | 97304-H32107 | \$ 3,627.00 | 10% | <i>\$3,288.78</i> |
| EW Edu NBD PartOnly H32108 | 97304-H32108 | \$ 3,627.00 | 10% | <i>\$3,288.78</i> |
| EW Edu NBD PartOnly H32109 | 97304-H32109 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32110 | 97304-H32110 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32111 | 97304-H32111 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32112 | 97304-H32112 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32113 | 97304-H32113 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32114 | 97304-H32114 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW Edu NBD PartOnly H32115 | 97304-H32115 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32116 | 97304-H32116 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32117 | 97304-H32117 | \$ 621.00 | 10% | <i>\$563.09</i> |
| EW Edu NBD PartOnly H32118 | 97304-H32118 | \$ 621.00 | 10% | <i>\$563.09</i> |
| EW Edu NBD PartOnly H32119 | 97304-H32119 | \$ 621.00 | 10% | <i>\$563.09</i> |
| EW Edu NBD PartOnly H32120 | 97304-H32120 | \$ 621.00 | 10% | <i>\$563.09</i> |
| EW Edu NBD PartOnly H32121 | 97304-H32121 | \$ 3,627.00 | 10% | <i>\$3,288.78</i> |
| EW Edu NBD PartOnly H32122 | 97304-H32122 | \$ 3,627.00 | 10% | <i>\$3,288.78</i> |
| EW Edu NBD PartOnly H32123 | 97304-H32123 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32124 | 97304-H32124 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW Edu NBD PartOnly H32125 | 97304-H32125 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32126 | 97304-H32126 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32127 | 97304-H32127 | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |

| | | | | |
|----------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly H32128 | 97304-H32128 | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |
| EW Edu NBD PartOnly H32129 | 97304-H32129 | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |
| EW Edu NBD PartOnly H32130 | 97304-H32130 | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |
| EW Edu NBD PartOnly H32131 | 97304-H32131 | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |
| EW Edu NBD PartOnly H32132 | 97304-H32132 | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |
| EW Edu NBD PartOnly H32133 | 97304-H32133 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32134 | 97304-H32134 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32135 | 97304-H32135 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32136 | 97304-H32136 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32137 | 97304-H32137 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32138 | 97304-H32138 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW Edu NBD PartOnly H32139 | 97304-H32139 | \$ 5,606.00 | 10% | <i>\$5,083.24</i> |
| EW Edu NBD PartOnly H32140 | 97304-H32140 | \$ 5,606.00 | 10% | <i>\$5,083.24</i> |
| EW Edu NBD PartOnly H32141 | 97304-H32141 | \$ 6,474.00 | 10% | <i>\$5,870.30</i> |
| EW Edu NBD PartOnly H32142 | 97304-H32142 | \$ 6,474.00 | 10% | <i>\$5,870.30</i> |
| EW Edu NBD PartOnly H32143 | 97304-H32143 | \$ 113.00 | 10% | <i>\$102.46</i> |
| EW Edu NBD PartOnly H32144 | 97304-H32144 | \$ 122.00 | 10% | <i>\$110.62</i> |
| EW Edu NBD PartOnly H32146 | 97304-H32146 | \$ 563.00 | 10% | <i>\$510.50</i> |
| EW Edu NBD PartOnly H32147 | 97304-H32147 | \$ 563.00 | 10% | <i>\$510.50</i> |
| EW Edu NBD PartOnly H32148 | 97304-H32148 | \$ 1,160.00 | 10% | <i>\$1,051.83</i> |
| EW Edu NBD PartOnly H32149 | 97304-H32149 | \$ 1,160.00 | 10% | <i>\$1,051.83</i> |
| EW Edu NBD PartOnly H32150 | 97304-H32150 | \$ 612.00 | 10% | <i>\$554.93</i> |
| EW Edu NBD PartOnly H32151 | 97304-H32151 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW Edu NBD PartOnly H32152 | 97304-H32152 | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW Edu NBD PartOnly H32169 | 97304-H32169 | \$ 691.00 | 10% | <i>\$626.56</i> |
| EW Edu NBD PartOnly H32170 | 97304-H32170 | \$ 691.00 | 10% | <i>\$626.56</i> |
| EW Edu NBD PartOnly H32171 | 97304-H32171 | \$ 642.00 | 10% | <i>\$582.13</i> |
| EW Edu NBD PartOnly H32172 | 97304-H32172 | \$ 642.00 | 10% | <i>\$582.13</i> |
| EW Edu NBD PartOnly H32173 | 97304-H32173 | \$ 1,724.00 | 10% | <i>\$1,563.24</i> |
| EW Edu NBD PartOnly H32174 | 97304-H32174 | \$ 1,724.00 | 10% | <i>\$1,563.24</i> |
| EW Edu NBD PartOnly H32175 | 97304-H32175 | \$ 1,467.00 | 10% | <i>\$1,330.20</i> |
| EW Edu NBD PartOnly H32176 | 97304-H32176 | \$ 1,467.00 | 10% | <i>\$1,330.20</i> |
| EW Edu NBD PartOnly H32177 | 97304-H32177 | \$ 6,741.00 | 10% | <i>\$6,112.40</i> |
| EW Edu NBD PartOnly H32178 | 97304-H32178 | \$ 7,779.00 | 10% | <i>\$7,053.61</i> |
| EW Edu NBD PartOnly H34008 | 97304-H34008 | \$ 2.00 | 10% | <i>\$1.81</i> |
| EW Edu NBD PartOnly H34009 | 97304-H34009 | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly H34010 | 97304-H34010 | \$ 2.00 | 10% | <i>\$1.81</i> |
| EW Edu NBD PartOnly H34011 | 97304-H34011 | \$ 10.00 | 10% | <i>\$9.07</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34012 | 97304-H34012 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Edu NBD PartOnly H34013 | 97304-H34013 | \$ 5.00 | 10% | <i>\$4.53</i> |
| EW Edu NBD PartOnly H34014 | 97304-H34014 | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly H34015 | 97304-H34015 | \$ 4.00 | 10% | <i>\$3.63</i> |
| EW Edu NBD PartOnly H34016 | 97304-H34016 | \$ 10.00 | 10% | <i>\$9.07</i> |
| EW Edu NBD PartOnly H34017 | 97304-H34017 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34018 | 97304-H34018 | \$ 5.00 | 10% | <i>\$4.53</i> |
| EW Edu NBD PartOnly H34019 | 97304-H34019 | \$ 5.00 | 10% | <i>\$4.53</i> |
| EW Edu NBD PartOnly H34020 | 97304-H34020 | \$ 5.00 | 10% | <i>\$4.53</i> |
| EW Edu NBD PartOnly H34021 | 97304-H34021 | \$ 5.00 | 10% | <i>\$4.53</i> |
| EW Edu NBD PartOnly H34048 | 97304-H34048 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly H34049 | 97304-H34049 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Edu NBD PartOnly H34050 | 97304-H34050 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34051 | 97304-H34051 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34052 | 97304-H34052 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly H34053 | 97304-H34053 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly H34054 | 97304-H34054 | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly H34055 | 97304-H34055 | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly H34056 | 97304-H34056 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly H34057 | 97304-H34057 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly H34058 | 97304-H34058 | \$ 26.00 | 10% | <i>\$23.58</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H34059 | 97304-H34059 | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly H34062 | 97304-H34062 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly H34063 | 97304-H34063 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly H34064 | 97304-H34064 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H34065 | 97304-H34065 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H34066 | 97304-H34066 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H34067 | 97304-H34067 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H34068 | 97304-H34068 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H34069 | 97304-H34069 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Edu NBD PartOnly H34070 | 97304-H34070 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H34071 | 97304-H34071 | \$ 14.00 | 10% | <i>\$12.69</i> |
| EW Edu NBD PartOnly H34072 | 97304-H34072 | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW Edu NBD PartOnly H34073 | 97304-H34073 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW Edu NBD PartOnly H34074 | 97304-H34074 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW Edu NBD PartOnly H34075 | 97304-H34075 | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW Edu NBD PartOnly H34076 | 97304-H34076 | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW Edu NBD PartOnly H34077 | 97304-H34077 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW Edu NBD PartOnly H34078 | 97304-H34078 | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW Edu NBD PartOnly H34079 | 97304-H34079 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW Edu NBD PartOnly H34080 | 97304-H34080 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW Edu NBD PartOnly H34081 | 97304-H34081 | \$ 226.00 | 10% | <i>\$204.93</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H34082 | 97304-H34082 | \$ 224.00 | 10% | <i>\$203.11</i> |
| EW Edu NBD PartOnly H34083 | 97304-H34083 | \$ 216.00 | 10% | <i>\$195.86</i> |
| EW Edu NBD PartOnly H34084 | 97304-H34084 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW Edu NBD PartOnly H34085 | 97304-H34085 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW Edu NBD PartOnly H34086 | 97304-H34086 | \$ 171.00 | 10% | <i>\$155.05</i> |
| EW Edu NBD PartOnly H34087 | 97304-H34087 | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW Edu NBD PartOnly H34088 | 97304-H34088 | \$ 392.00 | 10% | <i>\$355.45</i> |
| EW Edu NBD PartOnly H34089 | 97304-H34089 | \$ 392.00 | 10% | <i>\$355.45</i> |
| EW Edu NBD PartOnly H34090 | 97304-H34090 | \$ 644.00 | 10% | <i>\$583.95</i> |
| EW Edu NBD PartOnly H34091 | 97304-H34091 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW Edu NBD PartOnly H34092 | 97304-H34092 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW Edu NBD PartOnly H34093 | 97304-H34093 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW Edu NBD PartOnly H34094 | 97304-H34094 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H34095 | 97304-H34095 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H34096 | 97304-H34096 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H34097 | 97304-H34097 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H34098 | 97304-H34098 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H34099 | 97304-H34099 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H34100 | 97304-H34100 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H34101 | 97304-H34101 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H34102 | 97304-H34102 | \$ 34.00 | 10% | <i>\$30.83</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H34103 | 97304-H34103 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly H34104 | 97304-H34104 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34105 | 97304-H34105 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34106 | 97304-H34106 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34107 | 97304-H34107 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34108 | 97304-H34108 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34109 | 97304-H34109 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34110 | 97304-H34110 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW Edu NBD PartOnly H34111 | 97304-H34111 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW Edu NBD PartOnly H34112 | 97304-H34112 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW Edu NBD PartOnly H34114 | 97304-H34114 | \$ 535.00 | 10% | <i>\$485.11</i> |
| EW Edu NBD PartOnly H34115 | 97304-H34115 | \$ 535.00 | 10% | <i>\$485.11</i> |
| EW Edu NBD PartOnly H34116 | 97304-H34116 | \$ 535.00 | 10% | <i>\$485.11</i> |
| EW Edu NBD PartOnly H34117 | 97304-H34117 | \$ 535.00 | 10% | <i>\$485.11</i> |
| EW Edu NBD PartOnly H34118 | 97304-H34118 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW Edu NBD PartOnly H34119 | 97304-H34119 | \$ 134.00 | 10% | <i>\$121.50</i> |
| EW Edu NBD PartOnly H34120 | 97304-H34120 | \$ 93.00 | 10% | <i>\$84.33</i> |
| EW Edu NBD PartOnly H34121 | 97304-H34121 | \$ 93.00 | 10% | <i>\$84.33</i> |
| EW Edu NBD PartOnly H34122 | 97304-H34122 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW Edu NBD PartOnly H34123 | 97304-H34123 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW Edu NBD PartOnly H34124 | 97304-H34124 | \$ 147.00 | 10% | <i>\$133.29</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H34125 | 97304-H34125 | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW Edu NBD PartOnly H34126 | 97304-H34126 | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW Edu NBD PartOnly H34127 | 97304-H34127 | \$ 147.00 | 10% | <i>\$133.29</i> |
| EW Edu NBD PartOnly H34128 | 97304-H34128 | \$ 21.00 | 10% | <i>\$19.04</i> |
| EW Edu NBD PartOnly H34129 | 97304-H34129 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Edu NBD PartOnly H34130 | 97304-H34130 | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly H34131 | 97304-H34131 | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly H34132 | 97304-H34132 | \$ 26.00 | 10% | <i>\$23.58</i> |
| EW Edu NBD PartOnly H34172 | 97304-H34172 | \$ 79.00 | 10% | <i>\$71.63</i> |
| EW Edu NBD PartOnly H34174 | 97304-H34174 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34175 | 97304-H34175 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34176 | 97304-H34176 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34177 | 97304-H34177 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34178 | 97304-H34178 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34179 | 97304-H34179 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34180 | 97304-H34180 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34181 | 97304-H34181 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34182 | 97304-H34182 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34183 | 97304-H34183 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34184 | 97304-H34184 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34185 | 97304-H34185 | \$ 11.00 | 10% | <i>\$9.97</i> |

| | | | | |
|----------------------------|--------------|----------|-----|--------|
| EW Edu NBD PartOnly H34186 | 97304-H34186 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34187 | 97304-H34187 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34188 | 97304-H34188 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34189 | 97304-H34189 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34190 | 97304-H34190 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34191 | 97304-H34191 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34192 | 97304-H34192 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34193 | 97304-H34193 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34194 | 97304-H34194 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34195 | 97304-H34195 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34196 | 97304-H34196 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34197 | 97304-H34197 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34198 | 97304-H34198 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34199 | 97304-H34199 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34200 | 97304-H34200 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34201 | 97304-H34201 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34202 | 97304-H34202 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34203 | 97304-H34203 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34204 | 97304-H34204 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34205 | 97304-H34205 | \$ 11.00 | 10% | \$9.97 |
| EW Edu NBD PartOnly H34206 | 97304-H34206 | \$ 11.00 | 10% | \$9.97 |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34207 | 97304-H34207 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34208 | 97304-H34208 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34209 | 97304-H34209 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34210 | 97304-H34210 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34211 | 97304-H34211 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34212 | 97304-H34212 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34213 | 97304-H34213 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34214 | 97304-H34214 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34215 | 97304-H34215 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34216 | 97304-H34216 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34217 | 97304-H34217 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34218 | 97304-H34218 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34219 | 97304-H34219 | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Edu NBD PartOnly H34220 | 97304-H34220 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34221 | 97304-H34221 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34222 | 97304-H34222 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34223 | 97304-H34223 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34224 | 97304-H34224 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34225 | 97304-H34225 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34226 | 97304-H34226 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34227 | 97304-H34227 | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34228 | 97304-H34228 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34229 | 97304-H34229 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34230 | 97304-H34230 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34231 | 97304-H34231 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34232 | 97304-H34232 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34233 | 97304-H34233 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34234 | 97304-H34234 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34235 | 97304-H34235 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34236 | 97304-H34236 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34237 | 97304-H34237 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34238 | 97304-H34238 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34239 | 97304-H34239 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34240 | 97304-H34240 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34241 | 97304-H34241 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34242 | 97304-H34242 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34243 | 97304-H34243 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34244 | 97304-H34244 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34245 | 97304-H34245 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34246 | 97304-H34246 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34247 | 97304-H34247 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34248 | 97304-H34248 | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34249 | 97304-H34249 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34250 | 97304-H34250 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34251 | 97304-H34251 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34252 | 97304-H34252 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34253 | 97304-H34253 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34254 | 97304-H34254 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34255 | 97304-H34255 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34256 | 97304-H34256 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34257 | 97304-H34257 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34258 | 97304-H34258 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34259 | 97304-H34259 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34260 | 97304-H34260 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34261 | 97304-H34261 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34262 | 97304-H34262 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34263 | 97304-H34263 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34264 | 97304-H34264 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34265 | 97304-H34265 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34266 | 97304-H34266 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H34267 | 97304-H34267 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H34268 | 97304-H34268 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H34269 | 97304-H34269 | \$ 8.00 | 10% | <i>\$7.25</i> |

| | | | | |
|----------------------------|--------------|---------|-----|--------|
| EW Edu NBD PartOnly H34270 | 97304-H34270 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34271 | 97304-H34271 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34272 | 97304-H34272 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34273 | 97304-H34273 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34274 | 97304-H34274 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34275 | 97304-H34275 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34276 | 97304-H34276 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34277 | 97304-H34277 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34278 | 97304-H34278 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34279 | 97304-H34279 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34280 | 97304-H34280 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34281 | 97304-H34281 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34282 | 97304-H34282 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34283 | 97304-H34283 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34284 | 97304-H34284 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34285 | 97304-H34285 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34286 | 97304-H34286 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34287 | 97304-H34287 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34288 | 97304-H34288 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34289 | 97304-H34289 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34290 | 97304-H34290 | \$ 8.00 | 10% | \$7.25 |

| | | | | |
|----------------------------|--------------|----------|-----|---------|
| EW Edu NBD PartOnly H34291 | 97304-H34291 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34292 | 97304-H34292 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34293 | 97304-H34293 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34294 | 97304-H34294 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34295 | 97304-H34295 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34296 | 97304-H34296 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34297 | 97304-H34297 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34298 | 97304-H34298 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34299 | 97304-H34299 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34300 | 97304-H34300 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34301 | 97304-H34301 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34302 | 97304-H34302 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34303 | 97304-H34303 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34304 | 97304-H34304 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34305 | 97304-H34305 | \$ 8.00 | 10% | \$7.25 |
| EW Edu NBD PartOnly H34306 | 97304-H34306 | \$ 23.00 | 10% | \$20.86 |
| EW Edu NBD PartOnly H34307 | 97304-H34307 | \$ 23.00 | 10% | \$20.86 |
| EW Edu NBD PartOnly H34308 | 97304-H34308 | \$ 23.00 | 10% | \$20.86 |
| EW Edu NBD PartOnly H34309 | 97304-H34309 | \$ 23.00 | 10% | \$20.86 |
| EW Edu NBD PartOnly H34310 | 97304-H34310 | \$ 23.00 | 10% | \$20.86 |
| EW Edu NBD PartOnly H34311 | 97304-H34311 | \$ 23.00 | 10% | \$20.86 |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34312 | 97304-H34312 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34313 | 97304-H34313 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34314 | 97304-H34314 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34315 | 97304-H34315 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34316 | 97304-H34316 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34317 | 97304-H34317 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34318 | 97304-H34318 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34319 | 97304-H34319 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34320 | 97304-H34320 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34321 | 97304-H34321 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34322 | 97304-H34322 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34323 | 97304-H34323 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34324 | 97304-H34324 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34325 | 97304-H34325 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34326 | 97304-H34326 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34327 | 97304-H34327 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34328 | 97304-H34328 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34329 | 97304-H34329 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34330 | 97304-H34330 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34331 | 97304-H34331 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34332 | 97304-H34332 | \$ 23.00 | 10% | <i>\$20.86</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34333 | 97304-H34333 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34334 | 97304-H34334 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34335 | 97304-H34335 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34336 | 97304-H34336 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34337 | 97304-H34337 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34338 | 97304-H34338 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34339 | 97304-H34339 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34340 | 97304-H34340 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34341 | 97304-H34341 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34342 | 97304-H34342 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34343 | 97304-H34343 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34344 | 97304-H34344 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34345 | 97304-H34345 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34346 | 97304-H34346 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34347 | 97304-H34347 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34348 | 97304-H34348 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34349 | 97304-H34349 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34350 | 97304-H34350 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34351 | 97304-H34351 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34352 | 97304-H34352 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34353 | 97304-H34353 | \$ 23.00 | 10% | <i>\$20.86</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34354 | 97304-H34354 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34355 | 97304-H34355 | \$ 23.00 | 10% | <i>\$20.86</i> |
| EW Edu NBD PartOnly H34356 | 97304-H34356 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34357 | 97304-H34357 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34358 | 97304-H34358 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34359 | 97304-H34359 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34360 | 97304-H34360 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34361 | 97304-H34361 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34362 | 97304-H34362 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34363 | 97304-H34363 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34364 | 97304-H34364 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34365 | 97304-H34365 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34366 | 97304-H34366 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34367 | 97304-H34367 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34368 | 97304-H34368 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34369 | 97304-H34369 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34370 | 97304-H34370 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34371 | 97304-H34371 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34372 | 97304-H34372 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34373 | 97304-H34373 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34374 | 97304-H34374 | \$ 25.00 | 10% | <i>\$22.67</i> |

| | | | | |
|----------------------------|--------------|----------|-----|---------|
| EW Edu NBD PartOnly H34375 | 97304-H34375 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34376 | 97304-H34376 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34377 | 97304-H34377 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34378 | 97304-H34378 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34379 | 97304-H34379 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34380 | 97304-H34380 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34381 | 97304-H34381 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34382 | 97304-H34382 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34383 | 97304-H34383 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34384 | 97304-H34384 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34385 | 97304-H34385 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34386 | 97304-H34386 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34387 | 97304-H34387 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34388 | 97304-H34388 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34389 | 97304-H34389 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34390 | 97304-H34390 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34391 | 97304-H34391 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34392 | 97304-H34392 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34393 | 97304-H34393 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34394 | 97304-H34394 | \$ 25.00 | 10% | \$22.67 |
| EW Edu NBD PartOnly H34395 | 97304-H34395 | \$ 25.00 | 10% | \$22.67 |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34396 | 97304-H34396 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34397 | 97304-H34397 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34398 | 97304-H34398 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34399 | 97304-H34399 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34400 | 97304-H34400 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34401 | 97304-H34401 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34402 | 97304-H34402 | \$ 25.00 | 10% | <i>\$22.67</i> |
| EW Edu NBD PartOnly H34403 | 97304-H34403 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34404 | 97304-H34404 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34405 | 97304-H34405 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34406 | 97304-H34406 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34407 | 97304-H34407 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34408 | 97304-H34408 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34409 | 97304-H34409 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34410 | 97304-H34410 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34411 | 97304-H34411 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34412 | 97304-H34412 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34413 | 97304-H34413 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34414 | 97304-H34414 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34415 | 97304-H34415 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34416 | 97304-H34416 | \$ 41.00 | 10% | <i>\$37.18</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34417 | 97304-H34417 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34418 | 97304-H34418 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34419 | 97304-H34419 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34420 | 97304-H34420 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34421 | 97304-H34421 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34422 | 97304-H34422 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34423 | 97304-H34423 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34424 | 97304-H34424 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34425 | 97304-H34425 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34426 | 97304-H34426 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34427 | 97304-H34427 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34428 | 97304-H34428 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34429 | 97304-H34429 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34430 | 97304-H34430 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34431 | 97304-H34431 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34432 | 97304-H34432 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34433 | 97304-H34433 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34434 | 97304-H34434 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34435 | 97304-H34435 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34436 | 97304-H34436 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34437 | 97304-H34437 | \$ 41.00 | 10% | <i>\$37.18</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34438 | 97304-H34438 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34439 | 97304-H34439 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34440 | 97304-H34440 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34441 | 97304-H34441 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34442 | 97304-H34442 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34443 | 97304-H34443 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34444 | 97304-H34444 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34445 | 97304-H34445 | \$ 41.00 | 10% | <i>\$37.18</i> |
| EW Edu NBD PartOnly H34446 | 97304-H34446 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34447 | 97304-H34447 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34448 | 97304-H34448 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34449 | 97304-H34449 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34450 | 97304-H34450 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34451 | 97304-H34451 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34452 | 97304-H34452 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34453 | 97304-H34453 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34454 | 97304-H34454 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34455 | 97304-H34455 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34456 | 97304-H34456 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34457 | 97304-H34457 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34458 | 97304-H34458 | \$ 51.00 | 10% | <i>\$46.24</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34459 | 97304-H34459 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34460 | 97304-H34460 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34461 | 97304-H34461 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34462 | 97304-H34462 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34463 | 97304-H34463 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34464 | 97304-H34464 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34465 | 97304-H34465 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34466 | 97304-H34466 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34467 | 97304-H34467 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34468 | 97304-H34468 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34469 | 97304-H34469 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34470 | 97304-H34470 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34471 | 97304-H34471 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34472 | 97304-H34472 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34473 | 97304-H34473 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34474 | 97304-H34474 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34475 | 97304-H34475 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34476 | 97304-H34476 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34477 | 97304-H34477 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34478 | 97304-H34478 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34479 | 97304-H34479 | \$ 51.00 | 10% | <i>\$46.24</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34480 | 97304-H34480 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34481 | 97304-H34481 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34482 | 97304-H34482 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34483 | 97304-H34483 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34484 | 97304-H34484 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34485 | 97304-H34485 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34486 | 97304-H34486 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34487 | 97304-H34487 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34488 | 97304-H34488 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34489 | 97304-H34489 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H34490 | 97304-H34490 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34491 | 97304-H34491 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34492 | 97304-H34492 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34493 | 97304-H34493 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34494 | 97304-H34494 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34495 | 97304-H34495 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34496 | 97304-H34496 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34497 | 97304-H34497 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34498 | 97304-H34498 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34499 | 97304-H34499 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34500 | 97304-H34500 | \$ 7.00 | 10% | <i>\$6.35</i> |

| | | | | | |
|----------------------------|--------------|----|------|-----|--------|
| EW Edu NBD PartOnly H34501 | 97304-H34501 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34502 | 97304-H34502 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34503 | 97304-H34503 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34504 | 97304-H34504 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34505 | 97304-H34505 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34506 | 97304-H34506 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34507 | 97304-H34507 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34508 | 97304-H34508 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34509 | 97304-H34509 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34510 | 97304-H34510 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34511 | 97304-H34511 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34512 | 97304-H34512 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34513 | 97304-H34513 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34514 | 97304-H34514 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34515 | 97304-H34515 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34516 | 97304-H34516 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34517 | 97304-H34517 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34518 | 97304-H34518 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34519 | 97304-H34519 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34520 | 97304-H34520 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34521 | 97304-H34521 | \$ | 7.00 | 10% | \$6.35 |

| | | | | | |
|----------------------------|--------------|----|------|-----|--------|
| EW Edu NBD PartOnly H34522 | 97304-H34522 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34523 | 97304-H34523 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34524 | 97304-H34524 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34525 | 97304-H34525 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34526 | 97304-H34526 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34527 | 97304-H34527 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34528 | 97304-H34528 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34529 | 97304-H34529 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34530 | 97304-H34530 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34531 | 97304-H34531 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34532 | 97304-H34532 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34533 | 97304-H34533 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34534 | 97304-H34534 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34535 | 97304-H34535 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34536 | 97304-H34536 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34537 | 97304-H34537 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34538 | 97304-H34538 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34539 | 97304-H34539 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34540 | 97304-H34540 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34541 | 97304-H34541 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34542 | 97304-H34542 | \$ | 7.00 | 10% | \$6.35 |

| | | | | | |
|----------------------------|--------------|----|------|-----|--------|
| EW Edu NBD PartOnly H34543 | 97304-H34543 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34544 | 97304-H34544 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34545 | 97304-H34545 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34546 | 97304-H34546 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34547 | 97304-H34547 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34548 | 97304-H34548 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34549 | 97304-H34549 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34550 | 97304-H34550 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34551 | 97304-H34551 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34552 | 97304-H34552 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34553 | 97304-H34553 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34554 | 97304-H34554 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34555 | 97304-H34555 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34556 | 97304-H34556 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34557 | 97304-H34557 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34558 | 97304-H34558 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34559 | 97304-H34559 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34560 | 97304-H34560 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34561 | 97304-H34561 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34562 | 97304-H34562 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34563 | 97304-H34563 | \$ | 7.00 | 10% | \$6.35 |

| | | | | | |
|----------------------------|--------------|----|------|-----|--------|
| EW Edu NBD PartOnly H34564 | 97304-H34564 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34565 | 97304-H34565 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34566 | 97304-H34566 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34567 | 97304-H34567 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34568 | 97304-H34568 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34569 | 97304-H34569 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34570 | 97304-H34570 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34571 | 97304-H34571 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34572 | 97304-H34572 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34573 | 97304-H34573 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34574 | 97304-H34574 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34575 | 97304-H34575 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34576 | 97304-H34576 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34577 | 97304-H34577 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34578 | 97304-H34578 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34579 | 97304-H34579 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34580 | 97304-H34580 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34581 | 97304-H34581 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34582 | 97304-H34582 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34583 | 97304-H34583 | \$ | 7.00 | 10% | \$6.35 |
| EW Edu NBD PartOnly H34584 | 97304-H34584 | \$ | 7.00 | 10% | \$6.35 |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34585 | 97304-H34585 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34586 | 97304-H34586 | \$ 7.00 | 10% | <i>\$6.35</i> |
| EW Edu NBD PartOnly H34587 | 97304-H34587 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34588 | 97304-H34588 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34589 | 97304-H34589 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34590 | 97304-H34590 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34591 | 97304-H34591 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34592 | 97304-H34592 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34593 | 97304-H34593 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34594 | 97304-H34594 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34595 | 97304-H34595 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34596 | 97304-H34596 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34597 | 97304-H34597 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34598 | 97304-H34598 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34599 | 97304-H34599 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34600 | 97304-H34600 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34601 | 97304-H34601 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34602 | 97304-H34602 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34603 | 97304-H34603 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34604 | 97304-H34604 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34605 | 97304-H34605 | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34606 | 97304-H34606 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34607 | 97304-H34607 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34608 | 97304-H34608 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34609 | 97304-H34609 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34610 | 97304-H34610 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34611 | 97304-H34611 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34612 | 97304-H34612 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34613 | 97304-H34613 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34614 | 97304-H34614 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34615 | 97304-H34615 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34616 | 97304-H34616 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34617 | 97304-H34617 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34618 | 97304-H34618 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34619 | 97304-H34619 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34620 | 97304-H34620 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34621 | 97304-H34621 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34622 | 97304-H34622 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34623 | 97304-H34623 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34624 | 97304-H34624 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34625 | 97304-H34625 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34626 | 97304-H34626 | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34627 | 97304-H34627 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34628 | 97304-H34628 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34629 | 97304-H34629 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34630 | 97304-H34630 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34631 | 97304-H34631 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34632 | 97304-H34632 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34633 | 97304-H34633 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34634 | 97304-H34634 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34635 | 97304-H34635 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34636 | 97304-H34636 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34637 | 97304-H34637 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34638 | 97304-H34638 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34639 | 97304-H34639 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34640 | 97304-H34640 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34641 | 97304-H34641 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34642 | 97304-H34642 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34643 | 97304-H34643 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34644 | 97304-H34644 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34645 | 97304-H34645 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34646 | 97304-H34646 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34647 | 97304-H34647 | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34648 | 97304-H34648 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34649 | 97304-H34649 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34650 | 97304-H34650 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34651 | 97304-H34651 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34652 | 97304-H34652 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34653 | 97304-H34653 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34654 | 97304-H34654 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34655 | 97304-H34655 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34656 | 97304-H34656 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34657 | 97304-H34657 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34658 | 97304-H34658 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34659 | 97304-H34659 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34660 | 97304-H34660 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34661 | 97304-H34661 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34662 | 97304-H34662 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34663 | 97304-H34663 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34664 | 97304-H34664 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34665 | 97304-H34665 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34666 | 97304-H34666 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34667 | 97304-H34667 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34668 | 97304-H34668 | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34669 | 97304-H34669 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34670 | 97304-H34670 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34671 | 97304-H34671 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34672 | 97304-H34672 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34673 | 97304-H34673 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34674 | 97304-H34674 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34675 | 97304-H34675 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34676 | 97304-H34676 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34677 | 97304-H34677 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34678 | 97304-H34678 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H34679 | 97304-H34679 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34680 | 97304-H34680 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34681 | 97304-H34681 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34682 | 97304-H34682 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34683 | 97304-H34683 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34684 | 97304-H34684 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34685 | 97304-H34685 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34686 | 97304-H34686 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34687 | 97304-H34687 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34688 | 97304-H34688 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34689 | 97304-H34689 | \$ 22.00 | 10% | <i>\$19.95</i> |

| | | | | |
|----------------------------|--------------|----------|-----|----------------|
| EW Edu NBD PartOnly H34690 | 97304-H34690 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34691 | 97304-H34691 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34692 | 97304-H34692 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34693 | 97304-H34693 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34694 | 97304-H34694 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34695 | 97304-H34695 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34696 | 97304-H34696 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34697 | 97304-H34697 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34698 | 97304-H34698 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34699 | 97304-H34699 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34700 | 97304-H34700 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34701 | 97304-H34701 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34702 | 97304-H34702 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34703 | 97304-H34703 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34704 | 97304-H34704 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34705 | 97304-H34705 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34706 | 97304-H34706 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34707 | 97304-H34707 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34708 | 97304-H34708 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34709 | 97304-H34709 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34710 | 97304-H34710 | \$ 22.00 | 10% | <i>\$19.95</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H34711 | 97304-H34711 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34712 | 97304-H34712 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34713 | 97304-H34713 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34714 | 97304-H34714 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34715 | 97304-H34715 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34716 | 97304-H34716 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34717 | 97304-H34717 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34718 | 97304-H34718 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34719 | 97304-H34719 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34720 | 97304-H34720 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34721 | 97304-H34721 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34722 | 97304-H34722 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34723 | 97304-H34723 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34724 | 97304-H34724 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34725 | 97304-H34725 | \$ 22.00 | 10% | <i>\$19.95</i> |
| EW Edu NBD PartOnly H34726 | 97304-H34726 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW Edu NBD PartOnly H34727 | 97304-H34727 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW Edu NBD PartOnly H34728 | 97304-H34728 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW Edu NBD PartOnly H34729 | 97304-H34729 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW Edu NBD PartOnly H34730 | 97304-H34730 | \$ 293.00 | 10% | <i>\$265.68</i> |
| EW Edu NBD PartOnly H34731 | 97304-H34731 | \$ 293.00 | 10% | <i>\$265.68</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H34732 | 97304-H34732 | \$ 293.00 | 10% | <i>\$265.68</i> |
| EW Edu NBD PartOnly H34733 | 97304-H34733 | \$ 293.00 | 10% | <i>\$265.68</i> |
| EW Edu NBD PartOnly H34734 | 97304-H34734 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H34735 | 97304-H34735 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H34736 | 97304-H34736 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Edu NBD PartOnly H34737 | 97304-H34737 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Edu NBD PartOnly H34738 | 97304-H34738 | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW Edu NBD PartOnly H34739 | 97304-H34739 | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW Edu NBD PartOnly H34740 | 97304-H34740 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly H34741 | 97304-H34741 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly H34742 | 97304-H34742 | \$ 28.00 | 10% | <i>\$25.39</i> |
| EW Edu NBD PartOnly H34743 | 97304-H34743 | \$ 28.00 | 10% | <i>\$25.39</i> |
| EW Edu NBD PartOnly H34744 | 97304-H34744 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H34745 | 97304-H34745 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H34746 | 97304-H34746 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Edu NBD PartOnly H34747 | 97304-H34747 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Edu NBD PartOnly H34748 | 97304-H34748 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H34749 | 97304-H34749 | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW Edu NBD PartOnly H34750 | 97304-H34750 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H34751 | 97304-H34751 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H34752 | 97304-H34752 | \$ 101.00 | 10% | <i>\$91.58</i> |

| | | | | |
|----------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly H34753 | 97304-H34753 | \$ 123.00 | 10% | <i>\$111.53</i> |
| EW Edu NBD PartOnly H34754 | 97304-H34754 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H34755 | 97304-H34755 | \$ 101.00 | 10% | <i>\$91.58</i> |
| EW Edu NBD PartOnly H34756 | 97304-H34756 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H34757 | 97304-H34757 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Edu NBD PartOnly H34758 | 97304-H34758 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H34759 | 97304-H34759 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H34760 | 97304-H34760 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H34761 | 97304-H34761 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H34839 | 97304-H34839 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34840 | 97304-H34840 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34841 | 97304-H34841 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34842 | 97304-H34842 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34843 | 97304-H34843 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34844 | 97304-H34844 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34845 | 97304-H34845 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34846 | 97304-H34846 | \$ 207.00 | 10% | <i>\$187.70</i> |
| EW Edu NBD PartOnly H34993 | 97304-H34993 | \$ 3,221.00 | 10% | <i>\$2,920.64</i> |
| EW Edu NBD PartOnly H34994 | 97304-H34994 | \$ 3,221.00 | 10% | <i>\$2,920.64</i> |
| EW Edu NBD PartOnly H34996 | 97304-H34996 | \$ 3,221.00 | 10% | <i>\$2,920.64</i> |
| EW Edu NBD PartOnly H34997 | 97304-H34997 | \$ 3,221.00 | 10% | <i>\$2,920.64</i> |

| | | | | |
|----------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly H35005 | 97304-H35005 | \$ 3,239.00 | 10% | <i>\$2,936.96</i> |
| EW Edu NBD PartOnly H35006 | 97304-H35006 | \$ 3,239.00 | 10% | <i>\$2,936.96</i> |
| EW Edu NBD PartOnly H35012 | 97304-H35012 | \$ 1,946.00 | 10% | <i>\$1,764.54</i> |
| EW Edu NBD PartOnly H35070 | 97304-H35070 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35071 | 97304-H35071 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35072 | 97304-H35072 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35073 | 97304-H35073 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35074 | 97304-H35074 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35075 | 97304-H35075 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35076 | 97304-H35076 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35077 | 97304-H35077 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35078 | 97304-H35078 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35079 | 97304-H35079 | \$ 8.00 | 10% | <i>\$7.25</i> |
| EW Edu NBD PartOnly H35080 | 97304-H35080 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H35081 | 97304-H35081 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H35082 | 97304-H35082 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H35083 | 97304-H35083 | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Edu NBD PartOnly H35270 | 97304-H35270 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly H35271 | 97304-H35271 | \$ 27.00 | 10% | <i>\$24.48</i> |
| EW Edu NBD PartOnly H35273 | 97304-H35273 | \$ 20.00 | 10% | <i>\$18.14</i> |
| EW Edu NBD PartOnly H35274 | 97304-H35274 | \$ 72.00 | 10% | <i>\$65.29</i> |

| | | | | |
|----------------------------|--------------|-------------|-----|-------------------|
| EW Edu NBD PartOnly H35275 | 97304-H35275 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Edu NBD PartOnly H35276 | 97304-H35276 | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW Edu NBD PartOnly H35277 | 97304-H35277 | \$ 224.00 | 10% | <i>\$203.11</i> |
| EW Edu NBD PartOnly H35278 | 97304-H35278 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW Edu NBD PartOnly H35279 | 97304-H35279 | \$ 218.00 | 10% | <i>\$197.67</i> |
| EW Edu NBD PartOnly H35280 | 97304-H35280 | \$ 394.00 | 10% | <i>\$357.26</i> |
| EW Edu NBD PartOnly H35292 | 97304-H35292 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW Edu NBD PartOnly H35293 | 97304-H35293 | \$ 218.00 | 10% | <i>\$197.67</i> |
| EW Edu NBD PartOnly H35295 | 97304-H35295 | \$ 38.00 | 10% | <i>\$34.46</i> |
| EW Edu NBD PartOnly H35296 | 97304-H35296 | \$ 1,852.00 | 10% | <i>\$1,679.30</i> |
| EW Edu NBD PartOnly H35297 | 97304-H35297 | \$ 1,852.00 | 10% | <i>\$1,679.30</i> |
| EW Edu NBD PartOnly H35298 | 97304-H35298 | \$ 2,974.00 | 10% | <i>\$2,696.67</i> |
| EW Edu NBD PartOnly H35299 | 97304-H35299 | \$ 2,974.00 | 10% | <i>\$2,696.67</i> |
| EW Edu NBD PartOnly H35302 | 97304-H35302 | \$ 746.00 | 10% | <i>\$676.44</i> |
| EW Edu NBD PartOnly H35303 | 97304-H35303 | \$ 746.00 | 10% | <i>\$676.44</i> |
| EW Edu NBD PartOnly H35304 | 97304-H35304 | \$ 746.00 | 10% | <i>\$676.44</i> |
| EW Edu NBD PartOnly H35305 | 97304-H35305 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW Edu NBD PartOnly H35306 | 97304-H35306 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW Edu NBD PartOnly H35307 | 97304-H35307 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW Edu NBD PartOnly H35309 | 97304-H35309 | \$ 1,128.00 | 10% | <i>\$1,022.81</i> |
| EW Edu NBD PartOnly H35310 | 97304-H35310 | \$ 1,128.00 | 10% | <i>\$1,022.81</i> |
| EW Edu NBD PartOnly H35311 | 97304-H35311 | \$ 1,128.00 | 10% | <i>\$1,022.81</i> |
| EW Edu NBD PartOnly H35312 | 97304-H35312 | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW Edu NBD PartOnly H35313 | 97304-H35313 | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW Edu NBD PartOnly H35314 | 97304-H35314 | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW Edu NBD PartOnly H35315 | 97304-H35315 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW Edu NBD PartOnly H35318 | 97304-H35318 | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW Edu NBD PartOnly H35319 | 97304-H35319 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW Edu NBD PartOnly H35320 | 97304-H35320 | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW Edu NBD PartOnly H35321 | 97304-H35321 | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW Edu NBD PartOnly H35322 | 97304-H35322 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW Edu NBD PartOnly H35323 | 97304-H35323 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW Edu NBD PartOnly H35328 | 97304-H35328 | \$ 15.00 | 10% | <i>\$13.60</i> |

| | | | | |
|----------------------------|--------------|-----------|-----|----------|
| EW Edu NBD PartOnly H35330 | 97304-H35330 | \$ 6.00 | 10% | \$5.44 |
| EW Edu NBD PartOnly H35340 | 97304-H35340 | \$ 829.00 | 10% | \$751.70 |
| EW Edu NBD PartOnly H35341 | 97304-H35341 | \$ 829.00 | 10% | \$751.70 |
| EW Edu NBD PartOnly H35342 | 97304-H35342 | \$ 687.00 | 10% | \$622.94 |
| EW Edu NBD PartOnly H35343 | 97304-H35343 | \$ 829.00 | 10% | \$751.70 |
| EW Edu NBD PartOnly H35344 | 97304-H35344 | \$ 864.00 | 10% | \$783.43 |
| EW Edu NBD PartOnly H35345 | 97304-H35345 | \$ 864.00 | 10% | \$783.43 |
| EW Edu NBD PartOnly H35346 | 97304-H35346 | \$ 717.00 | 10% | \$650.14 |
| EW Edu NBD PartOnly H35347 | 97304-H35347 | \$ 864.00 | 10% | \$783.43 |
| EW Edu NBD PartOnly H35349 | 97304-H35349 | \$ 954.00 | 10% | \$865.04 |
| EW Edu NBD PartOnly H35350 | 97304-H35350 | \$ 954.00 | 10% | \$865.04 |
| EW Edu NBD PartOnly H35351 | 97304-H35351 | \$ 781.00 | 10% | \$708.17 |
| EW Edu NBD PartOnly H35352 | 97304-H35352 | \$ 954.00 | 10% | \$865.04 |
| EW Edu NBD PartOnly H35359 | 97304-H35359 | \$ 146.00 | 10% | \$132.39 |
| EW Edu NBD PartOnly H35360 | 97304-H35360 | \$ 179.00 | 10% | \$162.31 |
| EW Edu NBD PartOnly H35361 | 97304-H35361 | \$ 160.00 | 10% | \$145.08 |
| EW Edu NBD PartOnly H35362 | 97304-H35362 | \$ 81.00 | 10% | \$73.45 |
| EW Edu NBD PartOnly H35366 | 97304-H35366 | \$ 410.00 | 10% | \$371.77 |
| EW Edu NBD PartOnly H35367 | 97304-H35367 | \$ 480.00 | 10% | \$435.24 |
| EW Edu NBD PartOnly H35368 | 97304-H35368 | \$ 737.00 | 10% | \$668.27 |
| EW Edu NBD PartOnly H35369 | 97304-H35369 | \$ 244.00 | 10% | \$221.25 |
| EW Edu NBD PartOnly H35370 | 97304-H35370 | \$ 340.00 | 10% | \$308.30 |
| EW Edu NBD PartOnly H35375 | 97304-H35375 | \$ 201.00 | 10% | \$182.26 |
| EW Edu NBD PartOnly H35376 | 97304-H35376 | \$ 308.00 | 10% | \$279.28 |
| EW Edu NBD PartOnly H35377 | 97304-H35377 | \$ 129.00 | 10% | \$116.97 |
| EW Edu NBD PartOnly H35378 | 97304-H35378 | \$ 206.00 | 10% | \$186.79 |
| EW Edu NBD PartOnly H35379 | 97304-H35379 | \$ 129.00 | 10% | \$116.97 |
| EW Edu NBD PartOnly H35380 | 97304-H35380 | \$ 230.00 | 10% | \$208.55 |
| EW Edu NBD PartOnly H35381 | 97304-H35381 | \$ 276.00 | 10% | \$250.26 |
| EW Edu NBD PartOnly H35384 | 97304-H35384 | \$ 91.00 | 10% | \$82.51 |
| EW Edu NBD PartOnly H35385 | 97304-H35385 | \$ 122.00 | 10% | \$110.62 |
| EW Edu NBD PartOnly H35386 | 97304-H35386 | \$ 206.00 | 10% | \$186.79 |
| EW Edu NBD PartOnly H35387 | 97304-H35387 | \$ 198.00 | 10% | \$179.54 |
| EW Edu NBD PartOnly H35388 | 97304-H35388 | \$ 135.00 | 10% | \$122.41 |
| EW Edu NBD PartOnly H35389 | 97304-H35389 | \$ 81.00 | 10% | \$73.45 |
| EW Edu NBD PartOnly H35390 | 97304-H35390 | \$ 69.00 | 10% | \$62.57 |
| EW Edu NBD PartOnly H35391 | 97304-H35391 | \$ 155.00 | 10% | \$140.55 |
| EW Edu NBD PartOnly H35392 | 97304-H35392 | \$ 230.00 | 10% | \$208.55 |
| EW Edu NBD PartOnly H35393 | 97304-H35393 | \$ 308.00 | 10% | \$279.28 |
| EW Edu NBD PartOnly H35394 | 97304-H35394 | \$ 51.00 | 10% | \$46.24 |
| EW Edu NBD PartOnly H35395 | 97304-H35395 | \$ 46.00 | 10% | \$41.71 |

| | | | | |
|-----------------------------------|---------------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly H35396 | 97304-H35396 | \$ 51.00 | 10% | <i>\$46.24</i> |
| EW Edu NBD PartOnly H35397 | 97304-H35397 | \$ 46.00 | 10% | <i>\$41.71</i> |
| EW Edu NBD PartOnly H35398 | 97304-H35398 | \$ 142.00 | 10% | <i>\$128.76</i> |
| EW Edu NBD PartOnly H35399 | 97304-H35399 | \$ 173.00 | 10% | <i>\$156.87</i> |
| EW Edu NBD PartOnly H35400 | 97304-H35400 | \$ 193.00 | 10% | <i>\$175.00</i> |
| EW Edu NBD PartOnly H35401 | 97304-H35401 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW Edu NBD PartOnly H35415 | 97304-H35415 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW Edu NBD PartOnly H35416 | 97304-H35416 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW Edu NBD PartOnly H35426 | 97304-H35426 | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW Edu NBD PartOnly H35427 | 97304-H35427 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW Edu NBD PartOnly H35428 | 97304-H35428 | \$ 69.00 | 10% | <i>\$62.57</i> |
| EW Edu NBD PartOnly H35429 | 97304-H35429 | \$ 155.00 | 10% | <i>\$140.55</i> |
| EW Edu NBD PartOnly H35445 | 97304-H35445 | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW Edu NBD PartOnly H35447 | 97304-H35447 | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW Edu NBD PartOnly H35449 | 97304-H35449 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW Edu NBD PartOnly H35450 | 97304-H35450 | \$ 206.00 | 10% | <i>\$186.79</i> |
| EW Edu NBD PartOnly H35455 | 97304-H35455 | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW Edu NBD PartOnly H35456 | 97304-H35456 | \$ 176.00 | 10% | <i>\$159.59</i> |
| EW Edu NBD PartOnly H35457 | 97304-H35457 | \$ 141.00 | 10% | <i>\$127.85</i> |
| EW Edu NBD PartOnly H35458 | 97304-H35458 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW Edu NBD PartOnly H35471 | 97304-H35471 | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW Edu NBD PartOnly H35600 | 97304-H35600 | \$ 20.00 | 10% | <i>\$18.14</i> |
| EW Edu NBD PartOnly H35601 | 97304-H35601 | \$ 20.00 | 10% | <i>\$18.14</i> |
| EW Edu NBD PartOnly H35602 | 97304-H35602 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly H35603 | 97304-H35603 | \$ 37.00 | 10% | <i>\$33.55</i> |
| EW Edu NBD PartOnly H35604 | 97304-H35604 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H35605 | 97304-H35605 | \$ 47.00 | 10% | <i>\$42.62</i> |
| EW Edu NBD PartOnly H35606 | 97304-H35606 | \$ 72.00 | 10% | <i>\$65.29</i> |
| EW Edu NBD PartOnly H35607 | 97304-H35607 | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Edu NBD PartOnly ISW-24W-4X | 97304-ISW-24W-4X | \$ 161.00 | 10% | <i>\$145.99</i> |
| EW Edu NBD PartOnly ISW-4W-4WS-4X | 97304-ISW-4W-4WS-4X | \$ 100.00 | 10% | <i>\$90.68</i> |

| | | | | |
|---------------------------------------|-------------------------|-------------|-----|------------|
| EW Edu NBD PartOnly-MSM128 | 97304-MSM128 | \$ 892.00 | 10% | \$808.82 |
| EW Edu NBD PartOnly-MSM48C | 97304-MSM48C | \$ 544.00 | 10% | \$493.27 |
| EW Edu NBD PartOnly SLX9150-48XT-DC-F | 97304-SLX9150-48XT-DC-F | \$ 747.00 | 10% | \$677.34 |
| EW Edu NBD PartOnly SLX9150-48XT-DC-R | 97304-SLX9150-48XT-DC-R | \$ 816.00 | 10% | \$739.91 |
| EW Edu NBD PartOnly SLX9150-48Y-DC-F | 97304-SLX9150-48Y-DC-F | \$ 716.00 | 10% | \$649.23 |
| EW Edu NBD PartOnly SLX9150-48Y-DC-R | 97304-SLX9150-48Y-DC-R | \$ 782.00 | 10% | \$709.08 |
| EW Edu NBD PartOnly SLX9740-40C | 97304-SLX9740-40C | \$ 1,808.00 | 10% | \$1,639.40 |
| EW Edu NBD PartOnly SLX9740-40C-AC-F | 97304-SLX9740-40C-AC-F | \$ 1,808.00 | 10% | \$1,639.40 |
| EW Edu NBD PartOnly SLX9740-40C-AC-R | 97304-SLX9740-40C-AC-R | \$ 1,808.00 | 10% | \$1,639.40 |
| EW Edu NBD PartOnly SLX9740-40C-DC-F | 97304-SLX9740-40C-DC-F | \$ 1,808.00 | 10% | \$1,639.40 |
| EW Edu NBD PartOnly SLX9740-80C | 97304-SLX9740-80C | \$ 3,403.00 | 10% | \$3,085.67 |
| EW Edu NBD PartOnly SLX9740-80C-AC-F | 97304-SLX9740-80C-AC-F | \$ 3,403.00 | 10% | \$3,085.67 |
| EW Edu NBD PartOnly SLX9740-80C-AC-R | 97304-SLX9740-80C-AC-R | \$ 3,403.00 | 10% | \$3,085.67 |
| EW Edu NBD PartOnly SLX9740-80C-DC-F | 97304-SLX9740-80C-DC-F | \$ 3,403.00 | 10% | \$3,085.67 |
| EW Edu NBD PartOnly V300-8P-2X | 97304-V300-8P-2X | \$ 19.00 | 10% | \$17.23 |
| EW Edu NBD PartOnly V300-8T-2X | 97304-V300-8T-2X | \$ 14.00 | 10% | \$12.69 |

| | | | | |
|---------------------------------------|-----------------------------|-----------|-----|----------|
| EW Edu NBD PartOnly V300HT-8P-2X | 97304-V300HT-8P-2X | \$ 37.00 | 10% | \$33.55 |
| EW Edu NBD PartOnly V300HT-8T-2X | 97304-V300HT-8T-2X | \$ 20.00 | 10% | \$18.14 |
| EW Edu NBD PartOnly-VIM-SS | 97304-VIM-SS | \$ 42.00 | 10% | \$38.08 |
| EW Edu NBD PartOnly-VIM-SSV80 | 97304-VIM-SSV80 | \$ 84.00 | 10% | \$76.17 |
| EW Edu NBD PartOnly-VIM2-SS | 97304-VIM2-SS | \$ 49.00 | 10% | \$44.43 |
| EW Edu NBD PartOnly-VIM2-SS128 | 97304-VIM2-SS128 | \$ 190.00 | 10% | \$172.28 |
| EW Edu NBD PartOnly-VIM2-V80 | 97304-VIM2-V80 | \$ 201.00 | 10% | \$182.26 |
| EW Edu NBD PartOnly-VIM210G4X | 97304-VIM210G4X | \$ 339.00 | 10% | \$307.39 |
| EW Edu NBD PartOnly VIM5-2Q | 97304-VIM5-2Q | \$ 44.00 | 10% | \$39.90 |
| EW Edu NBD PartOnly VIM5-2Y | 97304-VIM5-2Y | \$ 53.00 | 10% | \$48.06 |
| EW Edu NBD PartOnly VIM5-4X | 97304-VIM5-4X | \$ 28.00 | 10% | \$25.39 |
| EW Edu NBD PartOnly VIM5-4XE | 97304-VIM5-4XE | \$ 41.00 | 10% | \$37.18 |
| EW Edu NBD PartOnly VIM5-4Y | 97304-VIM5-4Y | \$ 67.00 | 10% | \$60.75 |
| EW Edu NBD PartOnly VIM5-4YE | 97304-VIM5-4YE | \$ 83.00 | 10% | \$75.26 |
| EW Edu NBD Part VSP4900-12MXU-12XE | 97304-VSP4900-12MXU-12XE | \$ 154.00 | 10% | \$139.64 |
| EW Edu NBD Part VSP4900-12MXU-12XE-B1 | 97304-VSP4900-12MXU-12XE-B1 | \$ 154.00 | 10% | \$139.64 |
| EW Edu NBD PartOnly VSP4900-24S | 97304-VSP4900-24S | \$ 81.00 | 10% | \$73.45 |
| EW Edu NBD PartOnly VSP4900-24S-B3 | 97304-VSP4900-24S-B3 | \$ 81.00 | 10% | \$73.45 |

| | | | | |
|--|-------------------------------|-----------|-----|-----------------|
| EW Edu NBD PartOnly VSP4900-24XE | 97304- VSP4900- 24XE | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW Edu NBD PartOnly VSP4900-24XE-B3 | 97304- VSP4900- 24XE-B3 | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW Edu NBD PartOnly X435- 24P-4S | 97304-X435- 24P-4S | \$ 36.00 | 10% | <i>\$32.64</i> |
| EW Edu NBD PartOnly X435- 24T-4S | 97304-X435- 24T-4S | \$ 21.00 | 10% | <i>\$19.04</i> |
| EW Edu NBD PartOnly X435-8P- 2T-W | 97304-X435- 8P-2T-W | \$ 21.00 | 10% | <i>\$19.04</i> |
| EW Edu NBD PartOnly X435-8P- 4S | 97304-X435- 8P-4S | \$ 18.00 | 10% | <i>\$16.32</i> |
| EW Edu NBD PartOnly X435-8T- 4S | 97304-X435- 8T-4S | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Edu NBD PartOnly-X460- 24P | 97304-X460- 24P | \$ 327.00 | 10% | <i>\$296.51</i> |
| EW Edu NBD PartOnly-X460- 24T | 97304-X460- 24T | \$ 230.00 | 10% | <i>\$208.55</i> |
| EW Edu NBD PartOnly-X460- 24TDC | 97304-X460- 24TDC | \$ 335.00 | 10% | <i>\$303.76</i> |
| EW Edu NBD PartOnly-X460- 24X | 97304-X460- 24X | \$ 411.00 | 10% | <i>\$372.67</i> |
| EW Edu NBD PartOnly-X460- 24XDC | 97304-X460- 24XDC | \$ 462.00 | 10% | <i>\$418.92</i> |
| EW Edu NBD PartOnly-X460- 48P | 97304-X460- 48P | \$ 411.00 | 10% | <i>\$372.67</i> |
| EW Edu NBD PartOnly-X460- 48T | 97304-X460- 48T | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW Edu NBD PartOnly-X460- 48TDC | 97304-X460- 48TDC | \$ 447.00 | 10% | <i>\$405.32</i> |
| EW Edu NBD PartOnly-X460- 48X | 97304-X460- 48X | \$ 543.00 | 10% | <i>\$492.37</i> |
| EW Edu NBD PartOnly-X460- 48XDC | 97304-X460- 48XDC | \$ 537.00 | 10% | <i>\$486.92</i> |
| EW Edu NBD PartOnly X465- 24MU | 97304-X465- 24MU | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW Edu NBD PartOnly X465- 24S | 97304-X465- 24S | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW Edu NBD PartOnly X465- 24S-B3 | 97304-X465- 24S-B3 | \$ 81.00 | 10% | <i>\$73.45</i> |

| | | | | |
|-------------------------------------|-----------------------|--------------|-----|--------------------|
| EW Edu NBD PartOnly X465-24W | 97304-X465-24W | \$ 81.00 | 10% | <i>\$73.45</i> |
| EW Edu NBD PartOnly X465-24XE | 97304-X465-24XE | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW Edu NBD PartOnly X465-24XE-B3 | 97304-X465-24XE-B3 | \$ 154.00 | 10% | <i>\$139.64</i> |
| EW Edu NBD PartOnly X465-48P | 97304-X465-48P | \$ 115.00 | 10% | <i>\$104.28</i> |
| EW Edu NBD PartOnly X465-48T | 97304-X465-48T | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW Edu NBD PartOnly X465-48W | 97304-X465-48W | \$ 146.00 | 10% | <i>\$132.39</i> |
| EW Edu NBD PartOnly X465i-48W | 97304-X465i-48W | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW Edu NBD PartOnly X465i-48W-B1-S1 | 97304-X465i-48W-B1-S1 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW Edu NBD PartOnly X465i-48W-B2-S1 | 97304-X465i-48W-B2-S1 | \$ 160.00 | 10% | <i>\$145.08</i> |
| EW Edu NBD PartOnly-X480-24X | 97304-X480-24X | \$ 511.00 | 10% | <i>\$463.35</i> |
| EW Edu NBD PartOnly-X480-48T | 97304-X480-48T | \$ 511.00 | 10% | <i>\$463.35</i> |
| EW Edu NBD PartOnly-X480-48X | 97304-X480-48X | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW Edu NBD PartOnly X695-48Y-8C | 97304-X695-48Y-8C | \$ 405.00 | 10% | <i>\$367.23</i> |
| EW Edu NBD PartOnly XA1440 | 97304-XA1440 | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW Edu NBD PartOnly XA1480 | 97304-XA1480 | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW Edu NBD PartOnly-XGM3-2SF | 97304-XGM3-2SF | \$ 84.00 | 10% | <i>\$76.17</i> |
| EW Edu NBD PartOnly XR600 | 97304-XR600 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW Edu NBD PartOnly-ZR-XFP | 97304-ZR-XFP | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW ANALYTICS 100K FLOW S20245 | 97403-S20245 | \$ 28,110.00 | 6% | <i>\$26,621.58</i> |
| EW ANALYTICS 1M FLOW S20246 | 97403-S20246 | \$ 58,400.00 | 6% | <i>\$55,307.72</i> |
| EW ANALYTICS 3M FLOW S20247 | 97403-S20247 | \$ 86,410.00 | 6% | <i>\$81,834.59</i> |

| | | | | |
|-------------------------------|--------------|--------------|-----|--------------------|
| EW ANALYTICS 500K FLOW S20248 | 97403-S20248 | \$ 49,460.00 | 6% | <i>\$46,841.09</i> |
| EW ANALYTICS 50K FLOW S20296 | 97403-S20296 | \$ 27,490.00 | 6% | <i>\$26,034.40</i> |
| EW MonitorPLS NBD AHR 1130C | 97404-1130C | \$ 1,804.00 | 6% | <i>\$1,708.48</i> |
| EW MonitorPLS NBD AHR-16119 | 97404-16119 | \$ 492.00 | 10% | <i>\$446.12</i> |
| EW MonitorPLS NBD AHR-16120 | 97404-16120 | \$ 551.00 | 10% | <i>\$499.62</i> |
| EW MonitorPLS NBD AHR-16126 | 97404-16126 | \$ 492.00 | 10% | <i>\$446.12</i> |
| EW MonitorPLS NBD AHR-16127 | 97404-16127 | \$ 516.00 | 10% | <i>\$467.88</i> |
| EW MonitorPLS NBD AHR-16172 | 97404-16172 | \$ 1,013.00 | 10% | <i>\$918.54</i> |
| EW MonitorPLS NBD AHR 16172T | 97404-16172T | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW MonitorPLS NBD AHR-16173 | 97404-16173 | \$ 1,019.00 | 10% | <i>\$923.98</i> |
| EW MonitorPLS NBD AHR 16173T | 97404-16173T | \$ 1,123.00 | 10% | <i>\$1,018.28</i> |
| EW MonitorPLS NBD AHR-16174 | 97404-16174 | \$ 1,136.00 | 10% | <i>\$1,030.07</i> |
| EW MonitorPLS NBD AHR-16175 | 97404-16175 | \$ 1,189.00 | 10% | <i>\$1,078.13</i> |
| EW MonitorPLS NBD AHR-16176 | 97404-16176 | \$ 1,130.00 | 10% | <i>\$1,024.63</i> |
| EW MonitorPLS NBD AHR-16177 | 97404-16177 | \$ 1,073.00 | 10% | <i>\$972.94</i> |
| EW MonitorPLS NBD AHR 16177T | 97404-16177T | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW MonitorPLS NBD AHR-16178 | 97404-16178 | \$ 1,300.00 | 10% | <i>\$1,178.78</i> |
| EW MonitorPLS NBD AHR-16179 | 97404-16179 | \$ 1,316.00 | 10% | <i>\$1,193.28</i> |
| EW MonitorPLS NBD AHR 16179T | 97404-16179T | \$ 1,449.00 | 10% | <i>\$1,313.88</i> |
| EW MonitorPLS NBD AHR-16301T | 97404-16301T | \$ 2,119.00 | 10% | <i>\$1,921.40</i> |
| EW MonitorPLS NBD AHR-16303T | 97404-16303T | \$ 2,119.00 | 10% | <i>\$1,921.40</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-16304T | 97404-16304T | \$ 2,611.00 | 10% | <i>\$2,367.52</i> |
| EW MonitorPLS NBD AHR-16401T | 97404-16401T | \$ 1,439.00 | 10% | <i>\$1,304.81</i> |
| EW MonitorPLS NBD AHR-16402T | 97404-16402T | \$ 1,792.00 | 10% | <i>\$1,624.90</i> |
| EW MonitorPLS NBD AHR-16403T | 97404-16403T | \$ 1,673.00 | 10% | <i>\$1,516.99</i> |
| EW MonitorPLS NBD AHR-16404T | 97404-16404T | \$ 1,673.00 | 10% | <i>\$1,516.99</i> |
| EW MonitorPLS NBD AHR-16405T | 97404-16405T | \$ 1,968.00 | 10% | <i>\$1,784.48</i> |
| EW MonitorPLS NBD AHR-16406T | 97404-16406T | \$ 2,364.00 | 10% | <i>\$2,143.56</i> |
| EW MonitorPLS NBD AHR-16431 | 97404-16431 | \$ 1,725.00 | 10% | <i>\$1,564.14</i> |
| EW MonitorPLS NBD AHR-16432 | 97404-16432 | \$ 1,828.00 | 10% | <i>\$1,657.54</i> |
| EW MonitorPLS NBD AHR-16440 | 97404-16440 | \$ 1,348.00 | 10% | <i>\$1,222.30</i> |
| EW MonitorPLS NBD AHR-16441 | 97404-16441 | \$ 1,279.00 | 10% | <i>\$1,159.73</i> |
| EW MonitorPLS NBD AHR-16442 | 97404-16442 | \$ 516.00 | 10% | <i>\$467.88</i> |
| EW MonitorPLS NBD AHR-16444 | 97404-16444 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW MonitorPLS NBD AHR-16501 | 97404-16501 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW MonitorPLS NBD AHR-16501T | 97404-16501T | \$ 933.00 | 10% | <i>\$846.00</i> |
| EW MonitorPLS NBD AHR-16502 | 97404-16502 | \$ 963.00 | 10% | <i>\$873.20</i> |
| EW MonitorPLS NBD AHR-16502T | 97404-16502T | \$ 999.00 | 10% | <i>\$905.84</i> |
| EW MonitorPLS NBD AHR-16503 | 97404-16503 | \$ 927.00 | 10% | <i>\$840.56</i> |
| EW MonitorPLS NBD AHR-16503T | 97404-16503T | \$ 976.00 | 10% | <i>\$884.99</i> |
| EW MonitorPLS NBD AHR-16504 | 97404-16504 | \$ 1,027.00 | 10% | <i>\$931.23</i> |
| EW MonitorPLS NBD AHR-16504T | 97404-16504T | \$ 1,079.00 | 10% | <i>\$978.38</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-16505 | 97404-16505 | \$ 1,045.00 | 10% | <i>\$947.55</i> |
| EW MonitorPLS NBD AHR-16505T | 97404-16505T | \$ 1,123.00 | 10% | <i>\$1,018.28</i> |
| EW MonitorPLS NBD AHR-16506 | 97404-16506 | \$ 1,210.00 | 10% | <i>\$1,097.17</i> |
| EW MonitorPLS NBD AHR-16506T | 97404-16506T | \$ 1,329.00 | 10% | <i>\$1,205.07</i> |
| EW MonitorPLS NBD AHR-16507 | 97404-16507 | \$ 1,183.00 | 10% | <i>\$1,072.69</i> |
| EW MonitorPLS NBD AHR-16507T | 97404-16507T | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW MonitorPLS NBD AHR-16508 | 97404-16508 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS NBD AHR-16508T | 97404-16508T | \$ 1,395.00 | 10% | <i>\$1,264.92</i> |
| EW MonitorPLS NBD AHR-16509 | 97404-16509 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS NBD AHR-16509T | 97404-16509T | \$ 1,395.00 | 10% | <i>\$1,264.92</i> |
| EW MonitorPLS NBD AHR-16510 | 97404-16510 | \$ 1,395.00 | 10% | <i>\$1,264.92</i> |
| EW MonitorPLS NBD AHR-16510T | 97404-16510T | \$ 1,520.00 | 10% | <i>\$1,378.26</i> |
| EW MonitorPLS NBD AHR-16513 | 97404-16513 | \$ 1,139.00 | 10% | <i>\$1,032.79</i> |
| EW MonitorPLS NBD AHR-16514 | 97404-16514 | \$ 1,368.00 | 10% | <i>\$1,240.43</i> |
| EW MonitorPLS NBD AHR-16515 | 97404-16515 | \$ 811.00 | 10% | <i>\$735.37</i> |
| EW MonitorPLS NBD AHR-16516 | 97404-16516 | \$ 820.00 | 10% | <i>\$743.54</i> |
| EW MonitorPLS NBD AHR-16517 | 97404-16517 | \$ 935.00 | 10% | <i>\$847.81</i> |
| EW MonitorPLS NBD AHR-16518 | 97404-16518 | \$ 913.00 | 10% | <i>\$827.86</i> |
| EW MonitorPLS NBD AHR-16519 | 97404-16519 | \$ 969.00 | 10% | <i>\$878.64</i> |
| EW MonitorPLS NBD AHR-16520 | 97404-16520 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLUS NBD AHR-16530 | 97404-16530 | \$ 905.00 | 10% | <i>\$820.61</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLUS NBD AHR-16531 | 97404-16531 | \$ 960.00 | 10% | <i>\$870.48</i> |
| EW MonitorPLUS NBD AHR-16531T | 97404-16531T | \$ 959.00 | 10% | <i>\$869.57</i> |
| EW MonitorPLUS NBD AHR-16532 | 97404-16532 | \$ 960.00 | 10% | <i>\$870.48</i> |
| EW MonitorPLUS NBD AHR-16532T | 97404-16532T | \$ 959.00 | 10% | <i>\$869.57</i> |
| EW MonitorPLUS NBD AHR-16533 | 97404-16533 | \$ 1,026.00 | 10% | <i>\$930.33</i> |
| EW MonitorPLUS NBD AHR-16533T | 97404-16533T | \$ 1,043.00 | 10% | <i>\$945.74</i> |
| EW MonitorPLUS NBD AHR-16534 | 97404-16534 | \$ 1,043.00 | 10% | <i>\$945.74</i> |
| EW MonitorPLUS NBD AHR-16535 | 97404-16535 | \$ 1,163.00 | 10% | <i>\$1,054.55</i> |
| EW MonitorPLUS NBD AHR-16535A | 97404-16535A | \$ 1,163.00 | 10% | <i>\$1,054.55</i> |
| EW MonitorPLUS NBD AHR-16535T | 97404-16535T | \$ 1,209.00 | 10% | <i>\$1,096.26</i> |
| EW MonitorPLUS NBD AHR-16536 | 97404-16536 | \$ 890.00 | 10% | <i>\$807.01</i> |
| EW MonitorPLUS NBD AHR-16537 | 97404-16537 | \$ 954.00 | 10% | <i>\$865.04</i> |
| EW MonitorPLUS NBD AHR-16538 | 97404-16538 | \$ 1,003.00 | 10% | <i>\$909.47</i> |
| EW MonitorPLUS NBD AHR-16538T | 97404-16538T | \$ 1,134.00 | 10% | <i>\$1,028.25</i> |
| EW MonitorPLUS NBD AHR-16539 | 97404-16539 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLUS NBD AHR-16540 | 97404-16540 | \$ 981.00 | 10% | <i>\$889.52</i> |
| EW MonitorPLUS NBD AHR-16541 | 97404-16541 | \$ 810.00 | 10% | <i>\$734.47</i> |
| EW MonitorPLS NBD AHR 16560 | 97404-16560 | \$ 525.00 | 10% | <i>\$476.04</i> |
| EW MonitorPLS NBD AHR 16561 | 97404-16561 | \$ 552.00 | 10% | <i>\$500.53</i> |
| EW MonitorPLS NBD AHR 16562 | 97404-16562 | \$ 782.00 | 10% | <i>\$709.08</i> |
| EW MonitorPLS NBD AHR 16563 | 97404-16563 | \$ 817.00 | 10% | <i>\$740.81</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR 16564 | 97404-16564 | \$ 853.00 | 10% | <i>\$773.46</i> |
| EW MonitorPLS NBD AHR 16565 | 97404-16565 | \$ 940.00 | 10% | <i>\$852.35</i> |
| EW MonitorPLS NBD AHR 16566 | 97404-16566 | \$ 505.00 | 10% | <i>\$457.91</i> |
| EW MonitorPLS NBD AHR 16567 | 97404-16567 | \$ 539.00 | 10% | <i>\$488.74</i> |
| EW MonitorPLS NBD AHR 16568 | 97404-16568 | \$ 736.00 | 10% | <i>\$667.37</i> |
| EW MonitorPLS NBD AHR 16569 | 97404-16569 | \$ 771.00 | 10% | <i>\$699.10</i> |
| EW MonitorPLS NBD AHR 16570 | 97404-16570 | \$ 782.00 | 10% | <i>\$709.08</i> |
| EW MonitorPLS NBD AHR 16571 | 97404-16571 | \$ 853.00 | 10% | <i>\$773.46</i> |
| EW MonitorPLS NBD AHR- 16701 | 97404-16701 | \$ 1,084.00 | 10% | <i>\$982.92</i> |
| EW MonitorPLS NBD AHR- 16702 | 97404-16702 | \$ 1,257.00 | 10% | <i>\$1,139.78</i> |
| EW MonitorPLS NBD AHR- 16703 | 97404-16703 | \$ 1,221.00 | 10% | <i>\$1,107.14</i> |
| EW MonitorPLS NBD AHR 16703T | 97404-16703T | \$ 1,349.00 | 10% | <i>\$1,223.21</i> |
| EW MonitorPLUS NBD AHR- 16704 | 97404-16704 | \$ 1,414.00 | 10% | <i>\$1,282.14</i> |
| EW MonitorPLS NBD AHR 16704T | 97404-16704T | \$ 1,564.00 | 10% | <i>\$1,418.16</i> |
| EW MonitorPLS NBD AHR- 16705 | 97404-16705 | \$ 1,257.00 | 10% | <i>\$1,139.78</i> |
| EW MonitorPLS NBD AHR 16705T | 97404-16705T | \$ 1,394.00 | 10% | <i>\$1,264.01</i> |
| EW MonitorPLS NBD AHR- 16706 | 97404-16706 | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW MonitorPLS NBD AHR 16706T | 97404-16706T | \$ 1,792.00 | 10% | <i>\$1,624.90</i> |
| EW MonitorPLS NBD AHR- 16710 | 97404-16710 | \$ 414.00 | 10% | <i>\$375.39</i> |
| EW MonitorPLS NBD AHR 16710T | 97404-16710T | \$ 455.00 | 10% | <i>\$412.57</i> |
| EW MonitorPLS NBD AHR- 16711 | 97404-16711 | \$ 311.00 | 10% | <i>\$282.00</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR 16711T | 97404-16711T | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW MonitorPLS NBD AHR- 16712 | 97404-16712 | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW MonitorPLS NBD AHR 16712T | 97404-16712T | \$ 367.00 | 10% | <i>\$332.78</i> |
| EW MonitorPLS NBD AHR- 16713 | 97404-16713 | \$ 285.00 | 10% | <i>\$258.42</i> |
| EW MonitorPLS NBD AHR 16713T | 97404-16713T | \$ 312.00 | 10% | <i>\$282.91</i> |
| EW MonitorPLS NBD AHR- 16715 | 97404-16715 | \$ 303.00 | 10% | <i>\$274.75</i> |
| EW MonitorPLS NBD AHR 16715T | 97404-16715T | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW MonitorPLS NBD AHR- 16716 | 97404-16716 | \$ 1,071.00 | 10% | <i>\$971.13</i> |
| EW MonitorPLS NBD AHR 16716T | 97404-16716T | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW MonitorPLS NBD AHR- 16717 | 97404-16717 | \$ 1,152.00 | 10% | <i>\$1,044.58</i> |
| EW MonitorPLS NBD AHR- 16718 | 97404-16718 | \$ 1,101.00 | 10% | <i>\$998.33</i> |
| EW MonitorPLS NBD AHR- 16719 | 97404-16719 | \$ 1,182.00 | 10% | <i>\$1,071.78</i> |
| EW MonitorPLS NBD AHR 16720 | 97404-16720 | \$ 1,430.00 | 10% | <i>\$1,296.65</i> |
| EW MonitorPLS NBD AHR 16720T | 97404-16720T | \$ 1,665.00 | 10% | <i>\$1,509.74</i> |
| EW MonitorPLS NBD AHR 16756 | 97404-16756 | \$ 1,300.00 | 10% | <i>\$1,178.78</i> |
| EW MonitorPLS NBD AHR 16756T | 97404-16756T | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW MonitorPLS NBD AHR 16757 | 97404-16757 | \$ 1,267.00 | 10% | <i>\$1,148.85</i> |
| EW MonitorPLS NBD AHR 16757T | 97404-16757T | \$ 1,493.00 | 10% | <i>\$1,353.78</i> |
| EW MonitorPLS NBD AHR 16790 | 97404-16790 | \$ 1,709.00 | 10% | <i>\$1,549.64</i> |
| EW MonitorPLS NBD AHR 16791 | 97404-16791 | \$ 2,206.00 | 10% | <i>\$2,000.29</i> |
| EW MonitorPLS NBD AHR- 17101 | 97404-17101 | \$ 2,796.00 | 10% | <i>\$2,535.27</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-17101T | 97404-17101T | \$ 3,500.00 | 10% | <i>\$3,173.63</i> |
| EW MonitorPLS NBD AHR-17102 | 97404-17102 | \$ 2,796.00 | 10% | <i>\$2,535.27</i> |
| EW MonitorPLS NBD AHR-17102T | 97404-17102T | \$ 3,500.00 | 10% | <i>\$3,173.63</i> |
| EW MonitorPLS NBD AHR-17103 | 97404-17103 | \$ 2,146.00 | 10% | <i>\$1,945.89</i> |
| EW MonitorPLS NBD AHR-17103C | 97404-17103C | \$ 2,083.00 | 10% | <i>\$1,888.76</i> |
| EW MonitorPLS NBD AHR-17103T | 97404-17103T | \$ 2,672.00 | 10% | <i>\$2,422.84</i> |
| EW MonitorPLS NBD AHR-17104 | 97404-17104 | \$ 2,146.00 | 10% | <i>\$1,945.89</i> |
| EW MonitorPLS NBD AHR-17104T | 97404-17104T | \$ 2,672.00 | 10% | <i>\$2,422.84</i> |
| EW MonitorPLS NBD AHR-17121 | 97404-17121 | \$ 686.00 | 10% | <i>\$622.03</i> |
| EW MonitorPLS NBD AHR-17122 | 97404-17122 | \$ 506.00 | 10% | <i>\$458.82</i> |
| EW MonitorPLS NBD AHR-17200 | 97404-17200 | \$ 4,033.00 | 10% | <i>\$3,656.92</i> |
| EW MonitorPLS NBD AHR-17200T | 97404-17200T | \$ 4,539.00 | 10% | <i>\$4,115.74</i> |
| EW MonitorPLS NBD AHR-17201 | 97404-17201 | \$ 4,033.00 | 10% | <i>\$3,656.92</i> |
| EW MonitorPLS NBD AHR-17201T | 97404-17201T | \$ 4,539.00 | 10% | <i>\$4,115.74</i> |
| EW MonitorPLS NBD AHR-17202 | 97404-17202 | \$ 4,033.00 | 10% | <i>\$3,656.92</i> |
| EW MonitorPLS NBD AHR-17202T | 97404-17202T | \$ 4,539.00 | 10% | <i>\$4,115.74</i> |
| EW MonitorPLS NBD AHR-17203 | 97404-17203 | \$ 4,082.00 | 10% | <i>\$3,701.35</i> |
| EW MonitorPLS NBD AHR-17203T | 97404-17203T | \$ 4,597.00 | 10% | <i>\$4,168.33</i> |
| EW MonitorPLS NBD AHR-17204 | 97404-17204 | \$ 4,082.00 | 10% | <i>\$3,701.35</i> |
| EW MonitorPLS NBD AHR-17204T | 97404-17204T | \$ 4,597.00 | 10% | <i>\$4,168.33</i> |
| EW MonitorPLS NBD AHR-17205 | 97404-17205 | \$ 4,058.00 | 10% | <i>\$3,679.59</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-17205T | 97404-17205T | \$ 4,565.00 | 10% | <i>\$4,139.31</i> |
| EW MonitorPLS NBD AHR-17206 | 97404-17206 | \$ 4,058.00 | 10% | <i>\$3,679.59</i> |
| EW MonitorPLS NBD AHR-17206T | 97404-17206T | \$ 4,565.00 | 10% | <i>\$4,139.31</i> |
| EW MonitorPLS NBD AHR-17300 | 97404-17300 | \$ 2,937.00 | 10% | <i>\$2,663.12</i> |
| EW MonitorPLS NBD AHR-17310 | 97404-17310 | \$ 2,727.00 | 10% | <i>\$2,472.71</i> |
| EW MonitorPLS NBD AHR 17350 | 97404-17350 | \$ 2,835.00 | 10% | <i>\$2,570.64</i> |
| EW MonitorPLS NBD AHR 17360 | 97404-17360 | \$ 3,330.00 | 10% | <i>\$3,019.48</i> |
| EW MonitorPLS NBD AHR 17401 | 97404-17401 | \$ 1,012.00 | 10% | <i>\$917.63</i> |
| EW MonitorPLS NBD AHR 17401G | 97404-17401G | \$ 1,049.00 | 10% | <i>\$951.18</i> |
| EW MonitorPLS NBD AHR 17401T | 97404-17401T | \$ 1,049.00 | 10% | <i>\$951.18</i> |
| EW MonitorPLS NBD AHR 17402 | 97404-17402 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR 17402G | 97404-17402G | \$ 1,087.00 | 10% | <i>\$985.64</i> |
| EW MonitorPLS NBD AHR 17402T | 97404-17402T | \$ 1,087.00 | 10% | <i>\$985.64</i> |
| EW MonitorPLS NBD AHR 17403 | 97404-17403 | \$ 1,137.00 | 10% | <i>\$1,030.97</i> |
| EW MonitorPLS NBD AHR 17404 | 97404-17404 | \$ 930.00 | 10% | <i>\$843.28</i> |
| EW MonitorPLS NBD AHR 17405 | 97404-17405 | \$ 941.00 | 10% | <i>\$853.25</i> |
| EW MonitorPLS NBD AHR 17700 | 97404-17700 | \$ 4,759.00 | 10% | <i>\$4,315.22</i> |
| EW MonitorPLS NBD AHR-17701 | 97404-17701 | \$ 4,100.00 | 10% | <i>\$3,717.68</i> |
| EW MonitorPLS NBD AHR-17702 | 97404-17702 | \$ 4,100.00 | 10% | <i>\$3,717.68</i> |
| EW MonitorPLS NBD AHR-17703 | 97404-17703 | \$ 4,471.00 | 10% | <i>\$4,054.08</i> |
| EW MonitorPLS NBD AHR-17704 | 97404-17704 | \$ 4,471.00 | 10% | <i>\$4,054.08</i> |

| | | | | |
|---------------------------------|-----------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR-17705 | 97404-17705 | \$ 4,123.00 | 10% | \$3,738.53 |
| EW MonitorPLS NBD AHR-17706 | 97404-17706 | \$ 4,123.00 | 10% | \$3,738.53 |
| EW MonitorPLS NBD AHR 17800 | 97404-17800 | \$ 4,873.00 | 10% | \$4,418.59 |
| EW MonitorPLS NBD AHR 17810 | 97404-17810 | \$ 4,039.00 | 10% | \$3,662.36 |
| EW MonitorPLS NBD AHR 18101 | 97404-18101 | \$ 423.00 | 10% | \$383.56 |
| EW MonitorPLS NBD AHR 18102 | 97404-18102 | \$ 482.00 | 10% | \$437.05 |
| EW MonitorPLS NBD AHR 18103 | 97404-18103 | \$ 506.00 | 10% | \$458.82 |
| EW MonitorPLS NBD AHR 18104 | 97404-18104 | \$ 629.00 | 10% | \$570.35 |
| EW MonitorPLS NBD AHR 18104-6PK | 97404-18104-6PK | \$ 3,774.00 | 10% | \$3,422.07 |
| EW MonitorPLS NBD AHR-30135 | 97404-30135 | \$ 1,738.00 | 10% | \$1,575.93 |
| EW MonitorPLS NBD AHR 30136 | 97404-30136 | \$ 4,516.00 | 10% | \$4,094.88 |
| EW MonitorPLS NBD AHR 30137 | 97404-30137 | \$ 1,550.00 | 10% | \$1,405.46 |
| EW MonitorPLS NBD AHR 30138 | 97404-30138 | \$ 4,388.00 | 10% | \$3,978.82 |
| EW MonitorPLS NBD AHR 30139 | 97404-30139 | \$ 7,552.00 | 10% | \$6,847.78 |
| EW MonitorPLS NBD AHR 30912 | 97404-30912 | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBD AHR 30913 | 97404-30913 | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBD AHR 31012 | 97404-31012 | \$ 246.00 | 10% | \$223.06 |
| EW MonitorPLS NBD AHR 31013 | 97404-31013 | \$ 246.00 | 10% | \$223.06 |
| EW MonitorPLS NBD AHR 31014 | 97404-31014 | \$ 246.00 | 10% | \$223.06 |
| EW MonitorPLS NBD AHR 31015 | 97404-31015 | \$ 246.00 | 10% | \$223.06 |
| EW MonitorPLS NBD AHR 31016 | 97404-31016 | \$ 406.00 | 10% | \$368.14 |

| | | | | |
|--------------------------------|-------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR 31017 | 97404-31017 | \$ 406.00 | 10% | <i>\$368.14</i> |
| EW MonitorPLS NBD AHR 31018 | 97404-31018 | \$ 439.00 | 10% | <i>\$398.06</i> |
| EW MonitorPLS NBD AHR 31019 | 97404-31019 | \$ 439.00 | 10% | <i>\$398.06</i> |
| EW MonitorPLS NBD AHR 31025 | 97404-31025 | \$ 216.00 | 10% | <i>\$195.86</i> |
| EW MonitorPLS NBD AHR 31026 | 97404-31026 | \$ 216.00 | 10% | <i>\$195.86</i> |
| EW MonitorPLS NBD AHR 31028 | 97404-31028 | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW MonitorPLS NBD AHR 31029 | 97404-31029 | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW MonitorPLS NBD AHR 31031 | 97404-31031 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR 31032 | 97404-31032 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR 31034 | 97404-31034 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR 31035 | 97404-31035 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR 31050 | 97404-31050 | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW MonitorPLS NBD AHR 31051 | 97404-31051 | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW MonitorPLS NBD AHR 31055 | 97404-31055 | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW MonitorPLS NBD AHR 31056 | 97404-31056 | \$ 258.00 | 10% | <i>\$233.94</i> |
| EW MonitorPLS NBD AHR 39031 | 97404-39031 | \$ 455.00 | 10% | <i>\$412.57</i> |
| EW MonitorPLS NBD AHR 39032 | 97404-39032 | \$ 483.00 | 10% | <i>\$437.96</i> |
| EW MonitorPLS NBD AHR 39033 | 97404-39033 | \$ 455.00 | 10% | <i>\$412.57</i> |
| EW MonitorPLS NBD AHR 39034 | 97404-39034 | \$ 455.00 | 10% | <i>\$412.57</i> |
| EW MonitorPLS NBD AHR 39035 | 97404-39035 | \$ 868.00 | 10% | <i>\$787.06</i> |
| EW MonitorPLS NBD AHR 39036 | 97404-39036 | \$ 446.00 | 10% | <i>\$404.41</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR 39037 | 97404-39037 | \$ 446.00 | 10% | <i>\$404.41</i> |
| EW MonitorPLS NBD AHR 39038 | 97404-39038 | \$ 487.00 | 10% | <i>\$441.59</i> |
| EW MonitorPLS NBD AHR 39039 | 97404-39039 | \$ 487.00 | 10% | <i>\$441.59</i> |
| EW MonitorPLS NBD AHR 4120-24MW-4Y | 97404-4120- 24MW-4Y | \$ 994.00 | 10% | <i>\$901.31</i> |
| EW MonitorPLS NBD AHR 4120-48MW-4Y | 97404-4120- 48MW-4Y | \$ 1,171.00 | 10% | <i>\$1,061.80</i> |
| EW MonitorPLS NBD AHR 4120C | 97404-4120C | \$ 5,069.00 | 10% | <i>\$4,596.32</i> |
| EW MonitorPLS NBD AHR 4120C-1 | 97404-4120C-1 | \$ 5,722.00 | 10% | <i>\$5,188.42</i> |
| EW MonitorPLS NBD AHR 41216 | 97404-41216 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW MonitorPLS NBD AHR 4220-12P-4X | 97404-4220- 12P-4X | \$ 625.00 | 10% | <i>\$566.72</i> |
| EW MonitorPLS NBD AHR 4220-12T-4X | 97404-4220- 12T-4X | \$ 581.00 | 10% | <i>\$526.82</i> |
| EW MonitorPLS NBD AHR 4220-24P-4X | 97404-4220- 24P-4X | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW MonitorPLS NBD AHR 4220-24T-4X | 97404-4220- 24T-4X | \$ 630.00 | 10% | <i>\$571.25</i> |
| EW MonitorPLS NBD AHR 4220-48P-4X | 97404-4220- 48P-4X | \$ 787.00 | 10% | <i>\$713.61</i> |
| EW MonitorPLS NBD AHR 4220-48T-4X | 97404-4220- 48T-4X | \$ 706.00 | 10% | <i>\$640.17</i> |
| EW MonitorPLS NBD AHR 4220-4MW-20P-4X | 97404-4220- 4MW-20P-4X | \$ 760.00 | 10% | <i>\$689.13</i> |
| EW MonitorPLS NBD AHR 4220-4MW-8P-4X | 97404-4220- 4MW-8P-4X | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW MonitorPLS NBD AHR 4220-8MW-40P-4X | 97404-4220- 8MW-40P-4X | \$ 895.00 | 10% | <i>\$811.54</i> |
| EW MonitorPLS NBD AHR 4220-8X | 97404-4220-8X | \$ 689.00 | 10% | <i>\$624.75</i> |
| EW MonitorPLS NBD AHR- 48001 | 97404-48001 | \$ 7,077.00 | 10% | <i>\$6,417.07</i> |
| EW MonitorPLS NBD AHR- 48038 | 97404-48038 | \$ 2,529.00 | 10% | <i>\$2,293.17</i> |
| EW MonitorPLS NBD AHR- 48039 | 97404-48039 | \$ 2,529.00 | 10% | <i>\$2,293.17</i> |

| | | | | |
|--|---------------------------|--------------|-----|------------|
| EW MonitorPLS NBD AHR-48040 | 97404-48040 | \$ 2,316.00 | 10% | \$2,100.03 |
| EW MonitorPLS NBD AHR-48041 | 97404-48041 | \$ 2,529.00 | 10% | \$2,293.17 |
| EW MonitorPLS NBD AHR-48046 | 97404-48046 | \$ 3,237.00 | 10% | \$2,935.15 |
| EW MonitorPLS NBD AHR-48047 | 97404-48047 | \$ 8,190.00 | 10% | \$7,426.28 |
| EW MonitorPLS NBD AHR-48051 | 97404-48051 | \$ 5,710.00 | 10% | \$5,177.54 |
| EW MonitorPLS NBD AHR-48061 | 97404-48061 | \$ 6,631.00 | 10% | \$6,012.66 |
| EW MonitorPLS NBD AHR-48062 | 97404-48062 | \$ 10,451.00 | 10% | \$9,476.44 |
| EW MonitorPLS NBD AHR 5320-16P-4XE | 97404-5320-16P-4XE | \$ 765.00 | 10% | \$693.66 |
| EW MonitorPLS NBD AHR 5320-16P-4XE-DC | 97404-5320-16P-4XE-DC | \$ 809.00 | 10% | \$733.56 |
| EW MonitorPLS NBD AHR 5320-24P-8XE | 97404-5320-24P-8XE | \$ 766.00 | 10% | \$694.57 |
| EW MonitorPLS NBD AHR5320-24T-24S-4XE-XT | 97404-5320-24T-24S-4XE-XT | \$ 807.00 | 10% | \$731.75 |
| EW MonitorPLS NBD AHR 5320-24T-4X-XT | 97404-5320-24T-4X-XT | \$ 648.00 | 10% | \$587.57 |
| EW MonitorPLS NBD AHR 5320-24T-8XE | 97404-5320-24T-8XE | \$ 719.00 | 10% | \$651.95 |
| EW MonitorPLS NBD AHR 5320-48P-8XE | 97404-5320-48P-8XE | \$ 989.00 | 10% | \$896.78 |
| EW MonitorPLS NBD AHR 5320-48T-8XE | 97404-5320-48T-8XE | \$ 852.00 | 10% | \$772.55 |
| EW MonitorPLS NBD AHR 5420F-16MW-32P-4XE | 97404-5420F-16MW-32P-4XE | \$ 1,512.00 | 10% | \$1,371.01 |
| EW MonitorPLS NBD AHR 5420F-16W-32P-4XE | 97404-5420F-16W-32P-4XE | \$ 1,278.00 | 10% | \$1,158.83 |
| EW MonitorPLS NBD AHR 5420F-24P-4XE | 97404-5420F-24P-4XE | \$ 1,022.00 | 10% | \$926.70 |
| EW MonitorPLS NBD AHR 5420F-24S-4XE | 97404-5420F-24S-4XE | \$ 1,068.00 | 10% | \$968.41 |
| EW MonitorPLS NBD AHR 5420F-24T-4XE | 97404-5420F-24T-4XE | \$ 962.00 | 10% | \$872.29 |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR 5420F-48P-4XE | 97404-5420F- 48P-4XE | \$ 1,213.00 | 10% | <i>\$1,099.89</i> |
| EW MonitorPLS NBD AHR 5420F-48P-4XL | 97404-5420F- 48P-4XL | \$ 1,300.00 | 10% | <i>\$1,178.78</i> |
| EW MonitorPLS NBD AHR 5420F-48T-4XE | 97404-5420F- 48T-4XE | \$ 1,039.00 | 10% | <i>\$942.11</i> |
| EW MonitorPLS NBD AHR 5420F-8W-16P-4XE | 97404-5420F- 8W-16P-4XE | \$ 1,062.00 | 10% | <i>\$962.97</i> |
| EW MonitorPLS NBD AHR 5420M-16MW-32P-4YE | 97404-5420M- 16MW-32P- 4YE | \$ 1,488.00 | 10% | <i>\$1,349.24</i> |
| EW MonitorPLS NBD AHR 5420M-24T-4YE | 97404-5420M- 24T-4YE | \$ 1,032.00 | 10% | <i>\$935.77</i> |
| EW MonitorPLS NBD AHR 5420M-24W-4YE | 97404-5420M- 24W-4YE | \$ 947.00 | 10% | <i>\$858.69</i> |
| EW MonitorPLS NBD AHR 5420M-48T-4YE | 97404-5420M- 48T-4YE | \$ 1,170.00 | 10% | <i>\$1,060.90</i> |
| EW MonitorPLS NBD AHR 5420M-48W-4YE | 97404-5420M- 48W-4YE | \$ 1,257.00 | 10% | <i>\$1,139.78</i> |
| EW MONITORPLUS NBD AHR 5520-12MW-36W | 97404-5520- 12MW-36W | \$ 1,416.00 | 10% | <i>\$1,283.96</i> |
| EW MONITORPLUS NBD AHR 5520-24T | 97404-5520- 24T | \$ 1,021.00 | 10% | <i>\$925.79</i> |
| EW MONITORPLUS NBD AH 5520-24T-ACDC-BASE | 97404-5520- 24T-ACDC- BASE | \$ 1,021.00 | 10% | <i>\$925.79</i> |
| EW MONITORPLUS NBD AHR 5520-24T-BASE | 97404-5520- 24T-BASE | \$ 1,021.00 | 10% | <i>\$925.79</i> |
| EW MONITORPLUS NBD AHR 5520-24W | 97404-5520- 24W | \$ 1,105.00 | 10% | <i>\$1,001.96</i> |
| EW MONITORPLUS NBD AHR 5520-24X | 97404-5520- 24X | \$ 1,686.00 | 10% | <i>\$1,528.78</i> |
| EW MONITORPLUS NBD AH 5520-24X-ACDC-BASE | 97404-5520- 24X-ACDC- BASE | \$ 1,686.00 | 10% | <i>\$1,528.78</i> |
| EW MONITORPLUS NBD AHR 5520-24X-BASE | 97404-5520- 24X-BASE | \$ 1,686.00 | 10% | <i>\$1,528.78</i> |
| EW MONITORPLUS NBD AHR 5520-48SE | 97404-5520- 48SE | \$ 1,619.00 | 10% | <i>\$1,468.03</i> |
| EW MONITORPL NBD AH 5520-48SE-ACDC-BASE | 97404-5520- 48SE-ACDC- BASE | \$ 1,619.00 | 10% | <i>\$1,468.03</i> |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EW MONITORPLUS NBD AHR 5520-48SE-BASE | 97404-5520- 48SE-BASE | \$ 1,619.00 | 10% | <i>\$1,468.03</i> |
| EW MONITORPLUS NBD AHR 5520-48T | 97404-5520- 48T | \$ 1,224.00 | 10% | <i>\$1,109.86</i> |
| EW MONITORPLUS NBD AH 5520-48T-ACDC-BASE | 97404-5520- 48T-ACDC- BASE | \$ 1,224.00 | 10% | <i>\$1,109.86</i> |
| EW MONITORPLUS NBD AHR 5520-48T-BASE | 97404-5520- 48T-BASE | \$ 1,224.00 | 10% | <i>\$1,109.86</i> |
| EW MONITORPLUS NBD AHR 5520-48W | 97404-5520- 48W | \$ 1,304.00 | 10% | <i>\$1,182.40</i> |
| EW MonitorPLS NBD AHR 5720-24MW | 97404-5720- 24MW | \$ 1,365.00 | 10% | <i>\$1,237.71</i> |
| EW MonitorPLS NBD AHR 5720-24MXW | 97404-5720- 24MXW | \$ 1,789.00 | 10% | <i>\$1,622.18</i> |
| EW MonitorPLS NBD AHR 5720-48MW | 97404-5720- 48MW | \$ 1,544.00 | 10% | <i>\$1,400.02</i> |
| EW MonitorPLS NBD AHR 5720-48MXW | 97404-5720- 48MXW | \$ 2,071.00 | 10% | <i>\$1,877.88</i> |
| EW MonitorPLS NBD AHR 7520-48XT-6C | 97404-7520- 48XT-6C | \$ 2,263.00 | 10% | <i>\$2,051.98</i> |
| EW MonitorPLS NBD AHR 7520-48XT-6C-AC-F | 97404-7520- 48XT-6C-AC- F | \$ 2,263.00 | 10% | <i>\$2,051.98</i> |
| EW MonitorPLS NBD AHR 7520-48XT-6C-AC-R | 97404-7520- 48XT-6C-AC- R | \$ 2,263.00 | 10% | <i>\$2,051.98</i> |
| EW MonitorPLS NBD AHR 7520-48Y-8C | 97404-7520- 48Y-8C | \$ 2,106.00 | 10% | <i>\$1,909.62</i> |
| EW MonitorPLS NBD AHR 7520-48Y-8C-AC-F | 97404-7520- 48Y-8C-AC-F | \$ 2,106.00 | 10% | <i>\$1,909.62</i> |
| EW MonitorPLS NBD AHR 7520-48Y-8C-AC-R | 97404-7520- 48Y-8C-AC-R | \$ 2,106.00 | 10% | <i>\$1,909.62</i> |
| EW MONITORPLUS NBD AHR 7520-48YE-8CE | 97404-7520- 48YE-8CE | \$ 2,456.00 | 10% | <i>\$2,226.98</i> |
| EW MONITORPLU NBD AHR 7520-48YE-8CE-AC-F | 97404-7520- 48YE-8CE-AC- F | \$ 2,456.00 | 10% | <i>\$2,226.98</i> |
| EW MONITORPLU NBD AHR 7520-48YE-8CE-AC-R | 97404-7520- 48YE-8CE-AC- R | \$ 2,456.00 | 10% | <i>\$2,226.98</i> |
| EW MonitorPLS NBD AHR 7720-32C | 97404-7720- 32C | \$ 2,633.00 | 10% | <i>\$2,387.47</i> |

| | | | | |
|--|---------------------------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR 7720-32C-AC-F | 97404-7720- 32C-AC-F | \$ 2,633.00 | 10% | \$2,387.47 |
| EW MonitorPLS NBD AHR 7720-32C-AC-R | 97404-7720- 32C-AC-R | \$ 2,633.00 | 10% | \$2,387.47 |
| EW MonitorPLS NBD AHR 8520-48XT-6C | 97404-8520- 48XT-6C | \$ 2,882.00 | 10% | \$2,613.25 |
| EW MonitorPLS NBD AHR 8520-48XT-6C-AC-F | 97404-8520- 48XT-6C-AC- F | \$ 2,882.00 | 10% | \$2,613.25 |
| EW MonitorPLS NBD AHR 8520-48XT-6C-AC-R | 97404-8520- 48XT-6C-AC- R | \$ 2,882.00 | 10% | \$2,613.25 |
| EW MonitorPLS NBD AHR 8520-48XT-6C-DC-F | 97404-8520- 48XT-6C-DC- F | \$ 2,882.00 | 10% | \$2,613.25 |
| EW MonitorPLS NBD AHR 8520-48XT-6C-DC-R | 97404-8520- 48XT-6C-DC- R | \$ 2,882.00 | 10% | \$2,613.25 |
| EW MonitorPLS NBD AHR 8520-48Y-8C | 97404-8520- 48Y-8C | \$ 2,963.00 | 10% | \$2,686.70 |
| EW MonitorPLS NBD AHR 8520-48Y-8C-AC-F | 97404-8520- 48Y-8C-AC-F | \$ 2,963.00 | 10% | \$2,686.70 |
| EW MonitorPLS NBD AHR 8520-48Y-8C-AC-R | 97404-8520- 48Y-8C-AC-R | \$ 2,963.00 | 10% | \$2,686.70 |
| EW MonitorPLS NBD AHR 8520-48Y-8C-DC-F | 97404-8520- 48Y-8C-DC-F | \$ 2,963.00 | 10% | \$2,686.70 |
| EW MonitorPLS NBD AHR 8520-48Y-8C-DC-R | 97404-8520- 48Y-8C-DC-R | \$ 2,963.00 | 10% | \$2,686.70 |
| EW MonitorPLS NBD AHR 8720-32C | 97404-8720- 32C | \$ 3,290.00 | 10% | \$2,983.21 |
| EW MonitorPLS NBD AHR 8720-32C-AC-F | 97404-8720- 32C-AC-F | \$ 3,290.00 | 10% | \$2,983.21 |
| EW MonitorPLS NBD AHR 8720-32C-AC-R | 97404-8720- 32C-AC-R | \$ 3,290.00 | 10% | \$2,983.21 |
| EW MonitorPLS NBD AHR 8720-32C-DC-F | 97404-8720- 32C-DC-F | \$ 3,290.00 | 10% | \$2,983.21 |
| EW MonitorPLS NBD AHR 8720-32C-DC-R | 97404-8720- 32C-DC-R | \$ 3,290.00 | 10% | \$2,983.21 |
| EW MonitorPLUS NBD AHR- 8806 | 97404-8806 | \$ 3,374.00 | 10% | \$3,059.37 |
| EW MonitorPLS NBD AHR- 8810 | 97404-8810 | \$ 5,979.00 | 10% | \$5,421.46 |

| | | | | |
|---|-----------------------------|--------------|-----|--------------------|
| EW MonitorPLS NBD AHR 8820-40C | 97404-8820- 40C | \$ 10,187.00 | 10% | <i>\$9,237.06</i> |
| EW MonitorPLS NBD AHR 8820-40C-AC-F | 97404-8820- 40C-AC-F | \$ 10,187.00 | 10% | <i>\$9,237.06</i> |
| EW MonitorPLS NBD AHR 8820-40C-AC-R | 97404-8820- 40C-AC-R | \$ 10,187.00 | 10% | <i>\$9,237.06</i> |
| EW MonitorPLS NBD AHR 8820-40C-DC-F | 97404-8820- 40C-DC-F | \$ 10,187.00 | 10% | <i>\$9,237.06</i> |
| EW MonitorPLS NBD AHR 8820-40C-DC-R | 97404-8820- 40C-DC-R | \$ 10,187.00 | 10% | <i>\$9,237.06</i> |
| EW MonitorPLS NBD AHR 8820-80C | 97404-8820- 80C | \$ 17,861.00 | 10% | <i>\$16,195.46</i> |
| EW MonitorPLS NBD AHR 8820-80C-AC-F | 97404-8820- 80C-AC-F | \$ 17,861.00 | 10% | <i>\$16,195.46</i> |
| EW MonitorPLS NBD AHR 8820-80C-AC-R | 97404-8820- 80C-AC-R | \$ 17,861.00 | 10% | <i>\$16,195.46</i> |
| EW MonitorPLS NBD AHR 8820-80C-DC-F | 97404-8820- 80C-DC-F | \$ 17,861.00 | 10% | <i>\$16,195.46</i> |
| EW MonitorPLS NBD AHR 8820-80C-DC-R | 97404-8820- 80C-DC-R | \$ 17,861.00 | 10% | <i>\$16,195.46</i> |
| EW MonitorPLS NBD AHR 9920-16C | 97404-9920- 16C | \$ 8,351.00 | 10% | <i>\$7,572.27</i> |
| EW MonitorPLS NBD AHR 9920-4D | 97404-9920-4D | \$ 8,351.00 | 10% | <i>\$7,572.27</i> |
| EW MonitorPLS NBD AHR 9920-NPB-8 | 97404-9920- NPB-8 | \$ 14,547.00 | 10% | <i>\$13,190.49</i> |
| EW MonitorPLS NBD AHR AH- AP-1130-AC-CE | 97404-AH-AP- 1130-AC-CE | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH- AP-1130-AC-FCC | 97404-AH-AP- 1130-AC-FCC | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH- AP-1130-AC-W | 97404-AH-AP- 1130-AC-W | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH- AP-121-N-CE | 97404-AH-AP- 121-N-CE | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW MonitorPLS NBD AHR AH- AP-121-N-FCC | 97404-AH-AP- 121-N-FCC | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW MonitorPLS NBD AHR AH- AP-121-N-W | 97404-AH-AP- 121-N-W | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW MonitorPLS NBD AHR AH- AP-121-N-W-NEC | 97404-AH-AP- 121-N-W-NEC | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW MonitorPLS NBD AHR AH- AP-122-AC-CAN | 97404-AH-AP- 122-AC-CAN | \$ 223.00 | 10% | <i>\$202.21</i> |

| | | | | |
|---|-------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AH-AP-122-AC-CE | 97404-AH-AP-122-AC-CE | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-122-AC-FCC | 97404-AH-AP-122-AC-FCC | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-122-AC-W | 97404-AH-AP-122-AC-W | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-122X-AC-CAN | 97404-AH-AP-122X-AC-CAN | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-122X-AC-CE | 97404-AH-AP-122X-AC-CE | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-122X-AC-FCC | 97404-AH-AP-122X-AC-FCC | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-122X-AC-W | 97404-AH-AP-122X-AC-W | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-130-AC-CE | 97404-AH-AP-130-AC-CE | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-130-AC-FCC | 97404-AH-AP-130-AC-FCC | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-130-AC-W | 97404-AH-AP-130-AC-W | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-141-N-CE | 97404-AH-AP-141-N-CE | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW MonitorPLS NBD AHR AH-AP-141-N-FCC | 97404-AH-AP-141-N-FCC | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW MonitorPLS NBD AHR AH-AP-141-N-W | 97404-AH-AP-141-N-W | \$ 250.00 | 10% | <i>\$226.69</i> |
| EW MonitorPLS NBD AHR AH-AP-150W-AC-CAN | 97404-AH-AP-150W-AC-CAN | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-150W-AC-CE | 97404-AH-AP-150W-AC-CE | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-150W-AC-FCC | 97404-AH-AP-150W-AC-FCC | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-150W-AC-W | 97404-AH-AP-150W-AC-W | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-230-AC-CE | 97404-AH-AP-230-AC-CE | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-230-AC-FCC | 97404-AH-AP-230-AC-FCC | \$ 223.00 | 10% | <i>\$202.21</i> |

| | | | | |
|---|-------------------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR AH-AP-230-AC-W | 97404-AH-AP-230-AC-W | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-245X-AC-CAN | 97404-AH-AP-245X-AC-CAN | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-245X-AC-CE | 97404-AH-AP-245X-AC-CE | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-245X-AC-FCC | 97404-AH-AP-245X-AC-FCC | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-245X-AC-W | 97404-AH-AP-245X-AC-W | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-250-AC-CAN | 97404-AH-AP-250-AC-CAN | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-250-AC-CE | 97404-AH-AP-250-AC-CE | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-250-AC-FCC | 97404-AH-AP-250-AC-FCC | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-250-AC-W | 97404-AH-AP-250-AC-W | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-330-N-FCC | 97404-AH-AP-330-N-FCC | \$ 250.00 | 10% | \$226.69 |
| EW MonitorPLS NBD AHR AH-AP-330-N-W | 97404-AH-AP-330-N-W | \$ 250.00 | 10% | \$226.69 |
| EW MonitorPLS NBD AHR AH-AP-350-N-FCC | 97404-AH-AP-350-N-FCC | \$ 250.00 | 10% | \$226.69 |
| EW MonitorPLS NBD AHR AH-AP-350-N-W | 97404-AH-AP-350-N-W | \$ 250.00 | 10% | \$226.69 |
| EW MonitorPLS NBD AHR AH-AP-550-AC-CAN | 97404-AH-AP-550-AC-CAN | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-550-AC-CE | 97404-AH-AP-550-AC-CE | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-550-AC-FCC | 97404-AH-AP-550-AC-FCC | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-550-AC-W | 97404-AH-AP-550-AC-W | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-630-AX-CAN | 97404-AH-AP-630-AX-CAN | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-630-AX-CE | 97404-AH-AP-630-AX-CE | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR AH-AP-630-AX-FCC | 97404-AH-AP-630-AX-FCC | \$ 223.00 | 10% | \$202.21 |

| | | | | |
|---|-------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AH-AP-630-AX-W | 97404-AH-AP-630-AX-W | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AH-AP-650-AX-CAN | 97404-AH-AP-650-AX-CAN | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-AP-650-AX-CE | 97404-AH-AP-650-AX-CE | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-AP-650-AX-FCC | 97404-AH-AP-650-AX-FCC | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-AP-650-AX-W | 97404-AH-AP-650-AX-W | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-AP-650X-AX-CAN | 97404-AH-AP-650X-AX-CAN | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-AP-650X-AX-CE | 97404-AH-AP-650X-AX-CE | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-AP-650X-AX-FCC | 97404-AH-AP-650X-AX-FCC | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-AP-650X-AX-W | 97404-AH-AP-650X-AX-W | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AH-ATOM-CAN | 97404-AH-ATOM-CAN | \$ 233.00 | 10% | <i>\$211.27</i> |
| EW MonitorPLS NBD AHR AH-ATOM-CE-EU | 97404-AH-ATOM-CE-EU | \$ 245.00 | 10% | <i>\$222.15</i> |
| EW MonitorPLS NBD AHR AH-ATOM-CE-UK | 97404-AH-ATOM-CE-UK | \$ 245.00 | 10% | <i>\$222.15</i> |
| EW MonitorPLS NBD AHR AH-ATOM-FCC | 97404-AH-ATOM-FCC | \$ 233.00 | 10% | <i>\$211.27</i> |
| EW MonitorPLS NBD AHR AH-ATOM-W | 97404-AH-ATOM-W | \$ 233.00 | 10% | <i>\$211.27</i> |
| EW MonitorPLS NBD AHR AH-ATOM-W-EU | 97404-AH-ATOM-W-EU | \$ 245.00 | 10% | <i>\$222.15</i> |
| EW MonitorPLS NBD AHR AH-ATOM-W-UK | 97404-AH-ATOM-W-UK | \$ 245.00 | 10% | <i>\$222.15</i> |
| EW MonitorPLS NBD AHR AH-BR-100-N-FCC | 97404-AH-BR-100-N-FCC | \$ 730.00 | 10% | <i>\$661.93</i> |
| EW MonitorPLS NBD AHR AH-BR-100-N-W | 97404-AH-BR-100-N-W | \$ 730.00 | 10% | <i>\$661.93</i> |
| EW MonitorPLS NBD AHR AH-BR-100-N-W-AU | 97404-AH-BR-100-N-W-AU | \$ 730.00 | 10% | <i>\$661.93</i> |

| | | | | |
|---|-------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AH-BR-100-N-W-EU | 97404-AH-BR-100-N-W-EU | \$ 730.00 | 10% | <i>\$661.93</i> |
| EW MonitorPLS NBD AHR AH-BR-100-N-W-UK | 97404-AH-BR-100-N-W-UK | \$ 730.00 | 10% | <i>\$661.93</i> |
| EW MonitorPLS NBD AHR AH-BR-100-N-W-US | 97404-AH-BR-100-N-W-US | \$ 730.00 | 10% | <i>\$661.93</i> |
| EW MonitorPLS NBD AHR AH-BR-200 | 97404-AH-BR-200 | \$ 664.00 | 10% | <i>\$602.08</i> |
| EW MonitorPLS NBD AHR AH-BR-200WP-N-CE | 97404-AH-BR-200WP-N-CE | \$ 684.00 | 10% | <i>\$620.22</i> |
| EW MonitorPLS NBD AHR AH-BR-200WP-N-EU | 97404-AH-BR-200WP-N-EU | \$ 684.00 | 10% | <i>\$620.22</i> |
| EW MonitorPLS NBD AHR AH-BR-200WP-N-FCC | 97404-AH-BR-200WP-N-FCC | \$ 664.00 | 10% | <i>\$602.08</i> |
| EW MonitorPLS NBD AHR AH-BR-200WP-N-W | 97404-AH-BR-200WP-N-W | \$ 684.00 | 10% | <i>\$620.22</i> |
| EW MonitorPLS NBD AHR AH-SR-2024P | 97404-AH-SR-2024P | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2124P | 97404-AH-SR-2124P | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2148P | 97404-AH-SR-2148P | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2208P-AU | 97404-AH-SR-2208P-AU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2208P-EU | 97404-AH-SR-2208P-EU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2208P-NA | 97404-AH-SR-2208P-NA | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2208P-UK | 97404-AH-SR-2208P-UK | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2224P-AU | 97404-AH-SR-2224P-AU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2224P-EU | 97404-AH-SR-2224P-EU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2224P-NA | 97404-AH-SR-2224P-NA | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2224P-UK | 97404-AH-SR-2224P-UK | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2324P-AU | 97404-AH-SR-2324P-AU | \$ 653.00 | 10% | <i>\$592.11</i> |

| | | | | |
|---|-------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AH-SR-2324P-EU | 97404-AH-SR-2324P-EU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2324P-NA | 97404-AH-SR-2324P-NA | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2324P-UK | 97404-AH-SR-2324P-UK | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2348P-AU | 97404-AH-SR-2348P-AU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2348P-EU | 97404-AH-SR-2348P-EU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2348P-NA | 97404-AH-SR-2348P-NA | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-SR-2348P-UK | 97404-AH-SR-2348P-UK | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR200P-AU | 97404-AH-XR200P-AU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR200P-EU | 97404-AH-XR200P-EU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR200P-UK | 97404-AH-XR200P-UK | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR200P-US | 97404-AH-XR200P-US | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR600P | 97404-AH-XR600P | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR600P-AU | 97404-AH-XR600P-AU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR600P-EU | 97404-AH-XR600P-EU | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR600P-KR | 97404-AH-XR600P-KR | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR600P-UK | 97404-AH-XR600P-UK | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AH-XR600P-US | 97404-AH-XR600P-US | \$ 653.00 | 10% | <i>\$592.11</i> |
| EW MonitorPLS NBD AHR AP-8533-68SB30-IL | 97404-AP-8533-68SB30-IL | \$ 264.00 | 10% | <i>\$239.38</i> |
| EW MonitorPLS NBD AHR AP3000-IL | 97404-AP3000-IL | \$ 155.94 | 10% | <i>\$141.40</i> |
| EW MonitorPLS NBD AHR AP3000-TN | 97404-AP3000-TN | \$ 155.94 | 10% | <i>\$141.40</i> |

| | | | | |
|---------------------------------------|---------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AP3000-WW | 97404-AP3000- WW | \$ 155.94 | 10% | <i>\$141.40</i> |
| EW MonitorPLS NBD AHR AP3000X-WW | 97404- AP3000X-WW | \$ 167.19 | 10% | <i>\$151.60</i> |
| EW MonitorPLS NBD AHR AP302W-CAN | 97404- AP302W-CAN | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW MonitorPLS NBD AHR AP302W-EG | 97404- AP302W-EG | \$ 165.00 | 10% | <i>\$149.61</i> |
| EW MonitorPLS NBD AHR AP302W-FCC | 97404- AP302W-FCC | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW MonitorPLS NBD AHR AP302W-WR | 97404- AP302W-WR | \$ 210.00 | 10% | <i>\$190.42</i> |
| EW MonitorPLS NBD AHR AP305C-1-CAN | 97404-AP305C- 1-CAN | \$ 222.00 | 10% | <i>\$201.30</i> |
| EW MonitorPLS NBD AHR AP305C-1-EG | 97404-AP305C- 1-EG | \$ 222.00 | 10% | <i>\$201.30</i> |
| EW MonitorPLS NBD AHR AP305C-1-FCC | 97404-AP305C- 1-FCC | \$ 222.00 | 10% | <i>\$201.30</i> |
| EW MonitorPLS NBD AHR AP305C-1-IL | 97404-AP305C- 1-IL | \$ 222.00 | 10% | <i>\$201.30</i> |
| EW MonitorPLS NBD AHR AP305C-1-WR | 97404-AP305C- 1-WR | \$ 222.00 | 10% | <i>\$201.30</i> |
| EW MonitorPLS NBD AHR AP305C-CAN | 97404-AP305C- CAN | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP305C-EG | 97404-AP305C- EG | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP305C-FCC | 97404-AP305C- FCC | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP305C-IL | 97404-AP305C- IL | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP305C-WR | 97404-AP305C- WR | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP305CX-CAN | 97404- AP305CX- CAN | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP305CX-FCC | 97404- AP305CX- FCC | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP305CX-IL | 97404- AP305CX-IL | \$ 239.00 | 10% | <i>\$216.71</i> |

| | | | | |
|--------------------------------------|-----------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AP305CX-WR | 97404- AP305CX-WR | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP310e-1-WR | 97404-AP310e- 1-WR | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW MonitorPLS NBD AHR AP310e-CAN | 97404-AP310e- CAN | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP310e-FCC | 97404-AP310e- FCC | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP310e-IL | 97404-AP310e- IL | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP310e-WR | 97404-AP310e- WR | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP310i-1-WR | 97404-AP310i- 1-WR | \$ 212.00 | 10% | <i>\$192.23</i> |
| EW MonitorPLS NBD AHR AP310i-CAN | 97404-AP310i- CAN | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP310i-FCC | 97404-AP310i- FCC | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP310i-IL | 97404-AP310i- IL | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP310i-WR | 97404-AP310i- WR | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR AP360e-CAN | 97404-AP360e- CAN | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP360e-FCC | 97404-AP360e- FCC | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP360e-IL | 97404-AP360e- IL | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP360e-WR | 97404-AP360e- WR | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP360i-CAN | 97404-AP360i- CAN | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP360i-FCC | 97404-AP360i- FCC | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP360i-WR | 97404-AP360i- WR | \$ 239.00 | 10% | <i>\$216.71</i> |
| EW MonitorPLS NBD AHR AP4000-WW | 97404-AP4000- 1-WW | \$ 202.00 | 10% | <i>\$183.16</i> |
| EW MonitorPLS NBD AHR AP4000-IL | 97404-AP4000- IL | \$ 202.00 | 10% | <i>\$183.16</i> |
| EW MonitorPLS NBD AHR AP4000-WW | 97404-AP4000- WW | \$ 202.00 | 10% | <i>\$183.16</i> |

| | | | | |
|---------------------------------------|------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AP410C-1-CAN | 97404-AP410C- 1-CAN | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW MonitorPLS NBD AHR AP410C-1-EG | 97404-AP410C- 1-EG | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW MonitorPLS NBD AHR AP410C-1-FCC | 97404-AP410C- 1-FCC | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW MonitorPLS NBD AHR AP410C-1-IL | 97404-AP410C- 1-IL | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW MonitorPLS NBD AHR AP410C-1-WR | 97404-AP410C- 1-WR | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW MonitorPLS NBD AHR AP410C-CAN | 97404-AP410C- CAN | \$ 225.00 | 10% | <i>\$204.02</i> |
| EW MonitorPLS NBD AHR AP410C-EG | 97404-AP410C- EG | \$ 225.00 | 10% | <i>\$204.02</i> |
| EW MonitorPLS NBD AHR AP410C-FCC | 97404-AP410C- FCC | \$ 225.00 | 10% | <i>\$204.02</i> |
| EW MonitorPLS NBD AHR AP410C-IL | 97404-AP410C- IL | \$ 225.00 | 10% | <i>\$204.02</i> |
| EW MonitorPLS NBD AHR AP410C-WR | 97404-AP410C- WR | \$ 225.00 | 10% | <i>\$204.02</i> |
| EW MonitorPLS NBD AHR AP410e-CAN | 97404-AP410e- CAN | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS NBD AHR AP410e-FCC | 97404-AP410e- FCC | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS NBD AHR AP410e-WR | 97404-AP410e- WR | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS NBD AHR AP410i-1-FCC | 97404-AP410i- 1-FCC | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS NBD AHR AP410i-1-WR | 97404-AP410i- 1-WR | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS NBD AHR AP410i-CAN | 97404-AP410i- CAN | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS NBD AHR AP410i-FCC | 97404-AP410i- FCC | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS NBD AHR AP410i-IL | 97404-AP410i- IL | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS NBD AHR AP410i-WR | 97404-AP410i- WR | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS NBD AHR AP460C-CAN | 97404-AP460C- CAN | \$ 231.00 | 10% | <i>\$209.46</i> |

| | | | | |
|--|-----------------------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR AP460C-EG | 97404-AP460C- EG | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460C-FCC | 97404-AP460C- FCC | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460C-IL | 97404-AP460C- IL | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460C-WR | 97404-AP460C- WR | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460e-CAN | 97404-AP460e- CAN | \$ 256.00 | 10% | \$232.13 |
| EW MonitorPLS NBD AHR AP460e-FCC | 97404-AP460e- FCC | \$ 256.00 | 10% | \$232.13 |
| EW MonitorPLS NBD AHR AP460e-WR | 97404-AP460e- WR | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBD AHR AP460i-CAN | 97404-AP460i- CAN | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBD AHR AP460i-FCC | 97404-AP460i- FCC | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBD AHR AP460i-IL | 97404-AP460i- IL | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBD AHR AP460i-WR | 97404-AP460i- WR | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBD AHR AP460S12C-CAN | 97404- AP460S12C- CAN | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460S12C-FCC | 97404- AP460S12C- FCC | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460S12C-WR | 97404- AP460S12C- WR | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460S6C-CAN | 97404- AP460S6C- CAN | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460S6C-FCC | 97404- AP460S6C- FCC | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP460S6C-WR | 97404- AP460S6C- WR | \$ 231.00 | 10% | \$209.46 |
| EW MonitorPLS NBD AHR AP5010-IL | 97404-AP5010- IL | \$ 224.00 | 10% | \$203.11 |

| | | | | |
|---|---------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR AP5010-WW | 97404-AP5010- WW | \$ 224.00 | 10% | <i>\$203.11</i> |
| EW MonitorPLS NBD AHR AP5020-WW | 97404-AP5020- WW | \$ 223.40 | 6% | <i>\$211.57</i> |
| EW MonitorPLS NBD AHR AP5050D-WW | 97404- AP5050D-WW | \$ 360.00 | 10% | <i>\$326.43</i> |
| EW MonitorPLS NBD AHR AP5050U-WW | 97404- AP5050U-WW | \$ 306.00 | 10% | <i>\$277.47</i> |
| EW MonitorPLS NBD AHR AP505i-FCC | 97404-AP505i- FCC | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW MonitorPLS NBD AHR AP505i-FCC-TAA | 97404-AP505i- FCC-TAA | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW MonitorPLS NBD AHR AP505i-WR | 97404-AP505i- WR | \$ 261.00 | 10% | <i>\$236.66</i> |
| EW MonitorPLS NBD AHR AP510C-CAN | 97404-AP510C- CAN | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510C-CE | 97404-AP510C- CE | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510C-FCC | 97404-AP510C- FCC | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510C-W | 97404-AP510C- W | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510C-WW | 97404-AP510C- WW | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR AP510CX-CAN | 97404- AP510CX- CAN | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510CX-CE | 97404- AP510CX-CE | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510CX-FCC | 97404- AP510CX- FCC | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510CX-W | 97404- AP510CX-W | \$ 187.00 | 10% | <i>\$169.56</i> |
| EW MonitorPLS NBD AHR AP510CX-WW | 97404- AP510CX-WW | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR AP510e-FCC | 97404-AP510e- FCC | \$ 284.00 | 10% | <i>\$257.52</i> |
| EW MonitorPLS NBD AHR AP510e-FCC-TAA | 97404-AP510e- FCC-TAA | \$ 284.00 | 10% | <i>\$257.52</i> |

| | | | | |
|---|--------------------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR AP510e-WR | 97404-AP510e- WR | \$ 271.00 | 10% | \$245.73 |
| EW MonitorPLS NBD AHR AP510i-1-FCC | 97404-AP510i- 1-FCC | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBD AHR AP510i-1-WR | 97404-AP510i- 1-WR | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBD AHR AP510i-FCC | 97404-AP510i- FCC | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBD AHR AP510i-FCC-TAA | 97404-AP510i- FCC-TAA | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBD AHR AP510i-WR | 97404-AP510i- WR | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBD AHR AP560h-FCC | 97404-AP560h- FCC | \$ 421.00 | 10% | \$381.74 |
| EW MonitorPLS NBD AHR AP560h-WR | 97404-AP560h- WR | \$ 421.00 | 10% | \$381.74 |
| EW MonitorPLS NBD AHR AP560i-FCC | 97404-AP560i- FCC | \$ 353.00 | 10% | \$320.08 |
| EW MonitorPLS NBD AHR AP560i-WR | 97404-AP560i- WR | \$ 336.00 | 10% | \$304.67 |
| EW MonitorPLS NBD AHR AP560m-FCC | 97404-AP560m- FCC | \$ 353.00 | 10% | \$320.08 |
| EW MonitorPLS NBD AHR AP560t-FCC | 97404-AP560t- FCC | \$ 421.00 | 10% | \$381.74 |
| EW MonitorPLS NBD AHR AP560u-FCC | 97404-AP560u- FCC | \$ 328.00 | 10% | \$297.41 |
| EW MonitorPLS NBD AHR E2122 | 97404-E2122 | \$ 4,870.00 | 10% | \$4,415.87 |
| EW MonitorPLS NBD AHR E2122-1 | 97404-E2122-1 | \$ 4,616.00 | 10% | \$4,185.56 |
| EW MonitorPLS NBD AHR E3120-1 | 97404-E3120-1 | \$ 7,158.00 | 10% | \$6,490.52 |
| EW MonitorPLS NBD AHR E3125 | 97404-E3125 | \$ 7,908.00 | 10% | \$7,170.58 |
| EW MonitorPLS NBD AHR- H30003 | 97404-H30003 | \$ 510.00 | 10% | \$462.44 |
| EW MonitorPLS NBD AHR- H30004 | 97404-H30004 | \$ 523.00 | 10% | \$474.23 |
| EW MonitorPLS NBD AHR- H30005 | 97404-H30005 | \$ 744.00 | 10% | \$674.62 |
| EW MonitorPLS NBD AHR- H30006 | 97404-H30006 | \$ 784.00 | 10% | \$710.89 |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-H30007 | 97404-H30007 | \$ 777.00 | 10% | <i>\$704.54</i> |
| EW MonitorPLS NBD AHR-H30008 | 97404-H30008 | \$ 853.00 | 10% | <i>\$773.46</i> |
| EW MonitorPLS NBD AHR-H30009 | 97404-H30009 | \$ 737.00 | 10% | <i>\$668.27</i> |
| EW MonitorPLS NBD AHR-H30010 | 97404-H30010 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW MonitorPLS NBD AHR-H30011 | 97404-H30011 | \$ 757.00 | 10% | <i>\$686.41</i> |
| EW MonitorPLS NBD AHR-H30012 | 97404-H30012 | \$ 798.00 | 10% | <i>\$723.59</i> |
| EW MonitorPLS NBD AHR-H30131 | 97404-H30131 | \$ 1,529.00 | 10% | <i>\$1,386.42</i> |
| EW MonitorPLS NBD AHR-H30132 | 97404-H30132 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW MonitorPLS NBD AHR-H30133 | 97404-H30133 | \$ 2,863.00 | 10% | <i>\$2,596.03</i> |
| EW MonitorPLS NBD AHR-H30134 | 97404-H30134 | \$ 3,448.00 | 10% | <i>\$3,126.47</i> |
| EW MonitorPLS NBD AHR-H30135 | 97404-H30135 | \$ 2,918.00 | 10% | <i>\$2,645.90</i> |
| EW MonitorPLS NBD AHR-H30136 | 97404-H30136 | \$ 3,448.00 | 10% | <i>\$3,126.47</i> |
| EW MonitorPLS NBD AHR-H30184 | 97404-H30184 | \$ 727.00 | 10% | <i>\$659.21</i> |
| EW MonitorPLS NBD AHR-H30185 | 97404-H30185 | \$ 908.00 | 10% | <i>\$823.33</i> |
| EW MonitorPLS NBD AHR-H30186 | 97404-H30186 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW MonitorPLS NBD AHR-H30187 | 97404-H30187 | \$ 794.00 | 10% | <i>\$719.96</i> |
| EW MonitorPLS NBD AHR-H30188 | 97404-H30188 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW MonitorPLS NBD AHR-H30189 | 97404-H30189 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW MonitorPLS NBD AHR-H30190 | 97404-H30190 | \$ 969.00 | 10% | <i>\$878.64</i> |
| EW MonitorPLS NBD AHR-H30214 | 97404-H30214 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS NBD AHR-H30215 | 97404-H30215 | \$ 859.00 | 10% | <i>\$778.90</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR-H30216 | 97404-H30216 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30217 | 97404-H30217 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30218 | 97404-H30218 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30219 | 97404-H30219 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30220 | 97404-H30220 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30221 | 97404-H30221 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30222 | 97404-H30222 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30223 | 97404-H30223 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30224 | 97404-H30224 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30225 | 97404-H30225 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30226 | 97404-H30226 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30227 | 97404-H30227 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30228 | 97404-H30228 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30229 | 97404-H30229 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30267 | 97404-H30267 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30268 | 97404-H30268 | \$ 969.00 | 10% | \$878.64 |
| EW MonitorPLS NBD AHR-H30269 | 97404-H30269 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30270 | 97404-H30270 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30271 | 97404-H30271 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30272 | 97404-H30272 | \$ 1,093.00 | 10% | \$991.08 |
| EW MonitorPLS NBD AHR-H30273 | 97404-H30273 | \$ 1,220.00 | 10% | \$1,106.24 |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-H30274 | 97404-H30274 | \$ 1,220.00 | 10% | <i>\$1,106.24</i> |
| EW MonitorPLS NBD AHR-H30275 | 97404-H30275 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLS NBD AHR-H30276 | 97404-H30276 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLS NBD AHR-H30277 | 97404-H30277 | \$ 1,220.00 | 10% | <i>\$1,106.24</i> |
| EW MonitorPLS NBD AHR-H30278 | 97404-H30278 | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW MonitorPLS NBD AHR-H30279 | 97404-H30279 | \$ 1,220.00 | 10% | <i>\$1,106.24</i> |
| EW MonitorPLS NBD AHR-H30280 | 97404-H30280 | \$ 1,220.00 | 10% | <i>\$1,106.24</i> |
| EW MonitorPLS NBD AHR-H30281 | 97404-H30281 | \$ 1,220.00 | 10% | <i>\$1,106.24</i> |
| EW MonitorPLS NBD AHR-H30282 | 97404-H30282 | \$ 1,220.00 | 10% | <i>\$1,106.24</i> |
| EW MonitorPLS NBD AHR-H30283 | 97404-H30283 | \$ 994.00 | 10% | <i>\$901.31</i> |
| EW MonitorPLS NBD AHR-H30284 | 97404-H30284 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLS NBD AHR-H30296 | 97404-H30296 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS NBD AHR-H30297 | 97404-H30297 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS NBD AHR-H30298 | 97404-H30298 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS NBD AHR-H30299 | 97404-H30299 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS NBD AHR-H30381 | 97404-H30381 | \$ 1,536.00 | 10% | <i>\$1,392.77</i> |
| EW MonitorPLS NBD AHR-H30384 | 97404-H30384 | \$ 1,476.00 | 10% | <i>\$1,338.36</i> |
| EW MonitorPLS NBD AHR-H30391 | 97404-H30391 | \$ 828.00 | 10% | <i>\$750.79</i> |
| EW MonitorPLS NBD AHR-H30392 | 97404-H30392 | \$ 828.00 | 10% | <i>\$750.79</i> |
| EW MonitorPLS NBD AHR-H30393 | 97404-H30393 | \$ 503.00 | 10% | <i>\$456.10</i> |
| EW MonitorPLS NBD AHR-H30394 | 97404-H30394 | \$ 1,359.00 | 10% | <i>\$1,232.27</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-H30395 | 97404-H30395 | \$ 1,574.00 | 10% | <i>\$1,427.22</i> |
| EW MonitorPLS NBD AHR-H30396 | 97404-H30396 | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW MonitorPLS NBD AHR-H30397 | 97404-H30397 | \$ 1,680.00 | 10% | <i>\$1,523.34</i> |
| EW MonitorPLS NBD AHR-H30398 | 97404-H30398 | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW MonitorPLS NBD AHR-H30400 | 97404-H30400 | \$ 393.00 | 10% | <i>\$356.35</i> |
| EW MonitorPLS NBD AHR-H30401 | 97404-H30401 | \$ 454.00 | 10% | <i>\$411.66</i> |
| EW MonitorPLS NBD AHR-H30402 | 97404-H30402 | \$ 464.00 | 10% | <i>\$420.73</i> |
| EW MonitorPLS NBD AHR-H30403 | 97404-H30403 | \$ 572.00 | 10% | <i>\$518.66</i> |
| EW MonitorPLS NBD AHR-H30480 | 97404-H30480 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW MonitorPLS NBD AHR-H30495 | 97404-H30495 | \$ 2,080.00 | 10% | <i>\$1,886.04</i> |
| EW MonitorPLS NBD AHR-H30496 | 97404-H30496 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW MonitorPLS NBD AHR-H30497 | 97404-H30497 | \$ 2,460.00 | 10% | <i>\$2,230.61</i> |
| EW MonitorPLS NBD AHR-H30498 | 97404-H30498 | \$ 2,413.00 | 10% | <i>\$2,187.99</i> |
| EW MonitorPLS NBD AHR-H30499 | 97404-H30499 | \$ 663.00 | 10% | <i>\$601.18</i> |
| EW MonitorPLS NBD AHR-H30501 | 97404-H30501 | \$ 2,413.00 | 10% | <i>\$2,187.99</i> |
| EW MonitorPLS NBD AHR-H30502 | 97404-H30502 | \$ 3,062.00 | 10% | <i>\$2,776.47</i> |
| EW MonitorPLS NBD AHR-H30503 | 97404-H30503 | \$ 663.00 | 10% | <i>\$601.18</i> |
| EW MonitorPLS NBD AHR-H30505 | 97404-H30505 | \$ 3,403.00 | 10% | <i>\$3,085.67</i> |
| EW MonitorPLS NBD AHR-H30506 | 97404-H30506 | \$ 4,195.00 | 10% | <i>\$3,803.82</i> |
| EW MonitorPLS NBD AHR-H30509 | 97404-H30509 | \$ 3,062.00 | 10% | <i>\$2,776.47</i> |
| EW MonitorPLS NBD AHR-H30510 | 97404-H30510 | \$ 3,403.00 | 10% | <i>\$3,085.67</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR-H30511 | 97404-H30511 | \$ 4,195.00 | 10% | \$3,803.82 |
| EW MonitorPLS NBD AHR-H30512 | 97404-H30512 | \$ 663.00 | 10% | \$601.18 |
| EW MonitorPLS NBD AHR-H30513 | 97404-H30513 | \$ 944.00 | 10% | \$855.97 |
| EW MonitorPLS NBD AHR-H30525 | 97404-H30525 | \$ 3,236.00 | 10% | \$2,934.24 |
| EW MonitorPLS NBD AHR-H30526 | 97404-H30526 | \$ 2,445.00 | 10% | \$2,217.00 |
| EW MonitorPLS NBD AHR-H30528 | 97404-H30528 | \$ 3,713.00 | 10% | \$3,366.76 |
| EW MonitorPLS NBD AHR-H30531 | 97404-H30531 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW MonitorPLS NBD AHR-H30532 | 97404-H30532 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW MonitorPLS NBD AHR-H30534 | 97404-H30534 | \$ 5,279.00 | 10% | \$4,786.73 |
| EW MonitorPLS NBD AHR-H30535 | 97404-H30535 | \$ 5,611.00 | 10% | \$5,087.77 |
| EW MonitorPLS NBD AHR-H30536 | 97404-H30536 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW MonitorPLS NBD AHR-H30537 | 97404-H30537 | \$ 5,611.00 | 10% | \$5,087.77 |
| EW MonitorPLS NBD AHR-H30538 | 97404-H30538 | \$ 3,236.00 | 10% | \$2,934.24 |
| EW MonitorPLS NBD AHR-H30539 | 97404-H30539 | \$ 5,992.00 | 10% | \$5,433.25 |
| EW MonitorPLS NBD AHR-H30540 | 97404-H30540 | \$ 6,178.00 | 10% | \$5,601.90 |
| EW MonitorPLS NBD AHR-H30543 | 97404-H30543 | \$ 650.00 | 10% | \$589.39 |
| EW MonitorPLS NBD AHR-H30544 | 97404-H30544 | \$ 966.00 | 10% | \$875.92 |
| EW MonitorPLS NBD AHR-H30548 | 97404-H30548 | \$ 650.00 | 10% | \$589.39 |
| EW MonitorPLS NBD AHR-H30549 | 97404-H30549 | \$ 928.00 | 10% | \$841.46 |
| EW MonitorPLS NBD AHR-H30550 | 97404-H30550 | \$ 928.00 | 10% | \$841.46 |
| EW MonitorPLS NBD AHR-H30552 | 97404-H30552 | \$ 650.00 | 10% | \$589.39 |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-H30553 | 97404-H30553 | \$ 889.00 | 10% | <i>\$806.10</i> |
| EW MonitorPLS NBD AHR-H30569 | 97404-H30569 | \$ 2,863.00 | 10% | <i>\$2,596.03</i> |
| EW MonitorPLS NBD AHR-H30570 | 97404-H30570 | \$ 3,312.00 | 10% | <i>\$3,003.16</i> |
| EW MonitorPLS NBD AHR-H30571 | 97404-H30571 | \$ 3,312.00 | 10% | <i>\$3,003.16</i> |
| EW MonitorPLS NBD AHR-H30573 | 97404-H30573 | \$ 2,863.00 | 10% | <i>\$2,596.03</i> |
| EW MonitorPLS NBD AHR-H30574 | 97404-H30574 | \$ 3,109.00 | 10% | <i>\$2,819.09</i> |
| EW MonitorPLS NBD AHR-H30575 | 97404-H30575 | \$ 2,182.00 | 10% | <i>\$1,978.53</i> |
| EW MonitorPLS NBD AHR-H30576 | 97404-H30576 | \$ 2,863.00 | 10% | <i>\$2,596.03</i> |
| EW MonitorPLS NBD AHR-H30577 | 97404-H30577 | \$ 3,250.00 | 10% | <i>\$2,946.94</i> |
| EW MonitorPLS NBD AHR-H30578 | 97404-H30578 | \$ 3,250.00 | 10% | <i>\$2,946.94</i> |
| EW MonitorPLS NBD AHR-H30587 | 97404-H30587 | \$ 2,493.00 | 10% | <i>\$2,260.53</i> |
| EW MonitorPLS NBD AHR-H30588 | 97404-H30588 | \$ 1,798.00 | 10% | <i>\$1,630.34</i> |
| EW MonitorPLS NBD AHR-H30589 | 97404-H30589 | \$ 2,659.00 | 10% | <i>\$2,411.05</i> |
| EW MonitorPLS NBD AHR-H30632 | 97404-H30632 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW MonitorPLS NBD AHR-H30633 | 97404-H30633 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW MonitorPLS NBD AHR-H30643 | 97404-H30643 | \$ 5,216.00 | 10% | <i>\$4,729.61</i> |
| EW MonitorPLS NBD AHR-H30706 | 97404-H30706 | \$ 3,784.00 | 10% | <i>\$3,431.14</i> |
| EW MonitorPLS NBD AHR-H30707 | 97404-H30707 | \$ 2,445.00 | 10% | <i>\$2,217.00</i> |
| EW MonitorPLS NBD AHR-H30724 | 97404-H30724 | \$ 428.00 | 10% | <i>\$388.09</i> |
| EW MonitorPLS NBD AHR-H30725 | 97404-H30725 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW MonitorPLS NBD AHR-H30726 | 97404-H30726 | \$ 5,719.00 | 10% | <i>\$5,185.70</i> |

| | | | | |
|------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS NBD AHR-H30727 | 97404-H30727 | \$ 6,060.00 | 10% | <i>\$5,494.91</i> |
| EW MonitorPLS NBD AHR-H30730 | 97404-H30730 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS NBD AHR-H30731 | 97404-H30731 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS NBD AHR-H30733 | 97404-H30733 | \$ 6,329.00 | 10% | <i>\$5,738.82</i> |
| EW MonitorPLS NBD AHR-H30734 | 97404-H30734 | \$ 4,884.00 | 10% | <i>\$4,428.57</i> |
| EW MonitorPLS NBD AHR-H30735 | 97404-H30735 | \$ 5,384.00 | 10% | <i>\$4,881.94</i> |
| EW MonitorPLS NBD AHR-H30736 | 97404-H30736 | \$ 1,069.00 | 10% | <i>\$969.32</i> |
| EW MonitorPLS NBD AHR-H30738 | 97404-H30738 | \$ 221.00 | 10% | <i>\$200.39</i> |
| EW MonitorPLS NBD AHR H31337 | 97404-H31337 | \$ 8,293.00 | 10% | <i>\$7,519.68</i> |
| EW MonitorPLS NBD AHR H31338 | 97404-H31338 | \$ 8,293.00 | 10% | <i>\$7,519.68</i> |
| EW MonitorPLS NBD AHR H31341 | 97404-H31341 | \$ 4,484.00 | 10% | <i>\$4,065.87</i> |
| EW MonitorPLS NBD AHR H31342 | 97404-H31342 | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |
| EW MonitorPLS NBD AHR H31343 | 97404-H31343 | \$ 1,765.00 | 10% | <i>\$1,600.41</i> |
| EW MonitorPLS NBD AHR H31344 | 97404-H31344 | \$ 1,765.00 | 10% | <i>\$1,600.41</i> |
| EW MonitorPLS NBD AHR H31345 | 97404-H31345 | \$ 1,765.00 | 10% | <i>\$1,600.41</i> |
| EW MonitorPLS NBD AHR H31346 | 97404-H31346 | \$ 1,765.00 | 10% | <i>\$1,600.41</i> |
| EW MonitorPLS NBD AHR H31362 | 97404-H31362 | \$ 19,749.00 | 10% | <i>\$17,907.41</i> |
| EW MonitorPLS NBD AHR H31363 | 97404-H31363 | \$ 19,749.00 | 10% | <i>\$17,907.41</i> |
| EW MonitorPLS NBD AHR H31364 | 97404-H31364 | \$ 7,364.00 | 10% | <i>\$6,677.31</i> |
| EW MonitorPLS NBD AHR H31365 | 97404-H31365 | \$ 7,364.00 | 10% | <i>\$6,677.31</i> |
| EW MonitorPLS NBD AHR H31366 | 97404-H31366 | \$ 10,200.00 | 10% | <i>\$9,248.85</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS NBD AHR H31367 | 97404-H31367 | \$ 10,200.00 | 10% | <i>\$9,248.85</i> |
| EW MonitorPLS NBD AHR H32010 | 97404-H32010 | \$ 1,037.00 | 10% | <i>\$940.30</i> |
| EW MonitorPLS NBD AHR H32011 | 97404-H32011 | \$ 1,037.00 | 10% | <i>\$940.30</i> |
| EW MonitorPLS NBD AHR H32012 | 97404-H32012 | \$ 2,595.00 | 10% | <i>\$2,353.02</i> |
| EW MonitorPLS NBD AHR H32013 | 97404-H32013 | \$ 2,595.00 | 10% | <i>\$2,353.02</i> |
| EW MonitorPLS NBD AHR H32014 | 97404-H32014 | \$ 2,595.00 | 10% | <i>\$2,353.02</i> |
| EW MonitorPLS NBD AHR H32015 | 97404-H32015 | \$ 2,595.00 | 10% | <i>\$2,353.02</i> |
| EW MonitorPLS NBD AHR H32016 | 97404-H32016 | \$ 2,368.00 | 10% | <i>\$2,147.18</i> |
| EW MonitorPLS NBD AHR H32017 | 97404-H32017 | \$ 2,368.00 | 10% | <i>\$2,147.18</i> |
| EW MonitorPLS NBD AHR H32018 | 97404-H32018 | \$ 2,368.00 | 10% | <i>\$2,147.18</i> |
| EW MonitorPLS NBD AHR H32019 | 97404-H32019 | \$ 2,368.00 | 10% | <i>\$2,147.18</i> |
| EW MonitorPLS NBD AHR H32020 | 97404-H32020 | \$ 20,215.00 | 10% | <i>\$18,329.95</i> |
| EW MonitorPLS NBD AHR H32021 | 97404-H32021 | \$ 20,215.00 | 10% | <i>\$18,329.95</i> |
| EW MonitorPLS NBD AHR H32022 | 97404-H32022 | \$ 20,215.00 | 10% | <i>\$18,329.95</i> |
| EW MonitorPLS NBD AHR H32023 | 97404-H32023 | \$ 20,215.00 | 10% | <i>\$18,329.95</i> |
| EW MonitorPLS NBD AHR H32028 | 97404-H32028 | \$ 37,918.00 | 10% | <i>\$34,382.15</i> |
| EW MonitorPLS NBD AHR H32029 | 97404-H32029 | \$ 37,918.00 | 10% | <i>\$34,382.15</i> |
| EW MonitorPLS NBD AHR H32030 | 97404-H32030 | \$ 39,765.00 | 10% | <i>\$36,056.91</i> |
| EW MonitorPLS NBD AHR H32031 | 97404-H32031 | \$ 39,765.00 | 10% | <i>\$36,056.91</i> |
| EW MonitorPLS NBD AHR H32032 | 97404-H32032 | \$ 39,765.00 | 10% | <i>\$36,056.91</i> |
| EW MonitorPLS NBD AHR H32033 | 97404-H32033 | \$ 39,765.00 | 10% | <i>\$36,056.91</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|------------|
| EW MonitorPLS NBD AHR H32038 | 97404-H32038 | \$ 7,494.00 | 10% | \$6,795.18 |
| EW MonitorPLS NBD AHR H32039 | 97404-H32039 | \$ 7,494.00 | 10% | \$6,795.18 |
| EW MonitorPLS NBD AHR H32040 | 97404-H32040 | \$ 7,494.00 | 10% | \$6,795.18 |
| EW MonitorPLS NBD AHR H32041 | 97404-H32041 | \$ 7,494.00 | 10% | \$6,795.18 |
| EW MonitorPLS NBD AHR H32046 | 97404-H32046 | \$ 10,376.00 | 10% | \$9,408.44 |
| EW MonitorPLS NBD AHR H32047 | 97404-H32047 | \$ 10,376.00 | 10% | \$9,408.44 |
| EW MonitorPLS NBD AHR H32048 | 97404-H32048 | \$ 10,376.00 | 10% | \$9,408.44 |
| EW MonitorPLS NBD AHR H32049 | 97404-H32049 | \$ 10,376.00 | 10% | \$9,408.44 |
| EW MonitorPLS NBD AHR H32054 | 97404-H32054 | \$ 7,494.00 | 10% | \$6,795.18 |
| EW MonitorPLS NBD AHR H32055 | 97404-H32055 | \$ 10,376.00 | 10% | \$9,408.44 |
| EW MonitorPLS NBD AHR H32056 | 97404-H32056 | \$ 2,571.00 | 10% | \$2,331.25 |
| EW MonitorPLS NBD AHR H32057 | 97404-H32057 | \$ 2,650.00 | 10% | \$2,402.89 |
| EW MonitorPLS NBD AHR H32058 | 97404-H32058 | \$ 2,650.00 | 10% | \$2,402.89 |
| EW MonitorPLS NBD AHR H32059 | 97404-H32059 | \$ 2,650.00 | 10% | \$2,402.89 |
| EW MonitorPLS NBD AHR H32060 | 97404-H32060 | \$ 2,978.00 | 10% | \$2,700.30 |
| EW MonitorPLS NBD AHR H32061 | 97404-H32061 | \$ 3,127.00 | 10% | \$2,835.41 |
| EW MonitorPLS NBD AHR H32062 | 97404-H32062 | \$ 3,006.00 | 10% | \$2,725.69 |
| EW MonitorPLS NBD AHR H32063 | 97404-H32063 | \$ 2,981.00 | 10% | \$2,703.02 |
| EW MonitorPLS NBD AHR H32064 | 97404-H32064 | \$ 3,006.00 | 10% | \$2,725.69 |
| EW MonitorPLS NBD AHR H32065 | 97404-H32065 | \$ 3,279.00 | 10% | \$2,973.23 |
| EW MonitorPLS NBD AHR H32066 | 97404-H32066 | \$ 3,279.00 | 10% | \$2,973.23 |

| | | | | |
|---------------------------------|--------------|--------------|-----|-------------|
| EW MonitorPLS NBD AHR H32067 | 97404-H32067 | \$ 3,279.00 | 10% | \$2,973.23 |
| EW MonitorPLS NBD AHR H32068 | 97404-H32068 | \$ 3,279.00 | 10% | \$2,973.23 |
| EW MonitorPLS NBD AHR H32069 | 97404-H32069 | \$ 3,871.00 | 10% | \$3,510.03 |
| EW MonitorPLS NBD AHR H32070 | 97404-H32070 | \$ 3,871.00 | 10% | \$3,510.03 |
| EW MonitorPLS NBD AHR H32071 | 97404-H32071 | \$ 3,871.00 | 10% | \$3,510.03 |
| EW MonitorPLS NBD AHR H32072 | 97404-H32072 | \$ 3,871.00 | 10% | \$3,510.03 |
| EW MonitorPLS NBD AHR H32073 | 97404-H32073 | \$ 24,203.00 | 10% | \$21,946.07 |
| EW MonitorPLS NBD AHR H32074 | 97404-H32074 | \$ 24,203.00 | 10% | \$21,946.07 |
| EW MonitorPLS NBD AHR H32075 | 97404-H32075 | \$ 32,926.00 | 10% | \$29,855.65 |
| EW MonitorPLS NBD AHR H32076 | 97404-H32076 | \$ 32,926.00 | 10% | \$29,855.65 |
| EW MonitorPLS NBD AHR H32101 | 97404-H32101 | \$ 1,865.00 | 10% | \$1,691.09 |
| EW MonitorPLS NBD AHR H32102 | 97404-H32102 | \$ 1,865.00 | 10% | \$1,691.09 |
| EW MonitorPLS NBD AHR H32103 | 97404-H32103 | \$ 1,865.00 | 10% | \$1,691.09 |
| EW MonitorPLS NBD AHR H32104 | 97404-H32104 | \$ 1,865.00 | 10% | \$1,691.09 |
| EW MonitorPLS NBD AHR H32105 | 97404-H32105 | \$ 2,851.00 | 10% | \$2,585.14 |
| EW MonitorPLS NBD AHR H32106 | 97404-H32106 | \$ 2,851.00 | 10% | \$2,585.14 |
| EW MonitorPLS NBD AHR H32107 | 97404-H32107 | \$ 6,231.00 | 10% | \$5,649.96 |
| EW MonitorPLS NBD AHR H32108 | 97404-H32108 | \$ 6,231.00 | 10% | \$5,649.96 |
| EW MonitorPLS NBD AHR H32109 | 97404-H32109 | \$ 2,851.00 | 10% | \$2,585.14 |
| EW MonitorPLS NBD AHR H32110 | 97404-H32110 | \$ 2,851.00 | 10% | \$2,585.14 |
| EW MonitorPLS NBD AHR H32111 | 97404-H32111 | \$ 1,865.00 | 10% | \$1,691.09 |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR H32112 | 97404-H32112 | \$ 1,865.00 | 10% | <i>\$1,691.09</i> |
| EW MonitorPLS NBD AHR H32113 | 97404-H32113 | \$ 1,865.00 | 10% | <i>\$1,691.09</i> |
| EW MonitorPLS NBD AHR H32114 | 97404-H32114 | \$ 1,865.00 | 10% | <i>\$1,691.09</i> |
| EW MonitorPLS NBD AHR H32115 | 97404-H32115 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS NBD AHR H32116 | 97404-H32116 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS NBD AHR H32117 | 97404-H32117 | \$ 1,800.00 | 10% | <i>\$1,632.15</i> |
| EW MonitorPLS NBD AHR H32118 | 97404-H32118 | \$ 1,800.00 | 10% | <i>\$1,632.15</i> |
| EW MonitorPLS NBD AHR H32119 | 97404-H32119 | \$ 1,800.00 | 10% | <i>\$1,632.15</i> |
| EW MonitorPLS NBD AHR H32120 | 97404-H32120 | \$ 1,800.00 | 10% | <i>\$1,632.15</i> |
| EW MonitorPLS NBD AHR H32121 | 97404-H32121 | \$ 6,231.00 | 10% | <i>\$5,649.96</i> |
| EW MonitorPLS NBD AHR H32122 | 97404-H32122 | \$ 6,231.00 | 10% | <i>\$5,649.96</i> |
| EW MonitorPLS NBD AHR H32123 | 97404-H32123 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS NBD AHR H32124 | 97404-H32124 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS NBD AHR H32125 | 97404-H32125 | \$ 2,768.00 | 10% | <i>\$2,509.88</i> |
| EW MonitorPLS NBD AHR H32126 | 97404-H32126 | \$ 2,768.00 | 10% | <i>\$2,509.88</i> |
| EW MonitorPLS NBD AHR H32127 | 97404-H32127 | \$ 3,110.00 | 10% | <i>\$2,819.99</i> |
| EW MonitorPLS NBD AHR H32128 | 97404-H32128 | \$ 3,110.00 | 10% | <i>\$2,819.99</i> |
| EW MonitorPLS NBD AHR H32129 | 97404-H32129 | \$ 3,110.00 | 10% | <i>\$2,819.99</i> |
| EW MonitorPLS NBD AHR H32130 | 97404-H32130 | \$ 3,110.00 | 10% | <i>\$2,819.99</i> |
| EW MonitorPLS NBD AHR H32131 | 97404-H32131 | \$ 3,110.00 | 10% | <i>\$2,819.99</i> |
| EW MonitorPLS NBD AHR H32132 | 97404-H32132 | \$ 3,110.00 | 10% | <i>\$2,819.99</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|-------------|
| EW MonitorPLS NBD AHR H32133 | 97404-H32133 | \$ 2,768.00 | 10% | \$2,509.88 |
| EW MonitorPLS NBD AHR H32134 | 97404-H32134 | \$ 2,768.00 | 10% | \$2,509.88 |
| EW MonitorPLS NBD AHR H32135 | 97404-H32135 | \$ 2,768.00 | 10% | \$2,509.88 |
| EW MonitorPLS NBD AHR H32136 | 97404-H32136 | \$ 2,768.00 | 10% | \$2,509.88 |
| EW MonitorPLS NBD AHR H32137 | 97404-H32137 | \$ 2,768.00 | 10% | \$2,509.88 |
| EW MonitorPLS NBD AHR H32138 | 97404-H32138 | \$ 2,768.00 | 10% | \$2,509.88 |
| EW MonitorPLS NBD AHR H32139 | 97404-H32139 | \$ 10,396.00 | 10% | \$9,426.57 |
| EW MonitorPLS NBD AHR H32140 | 97404-H32140 | \$ 10,396.00 | 10% | \$9,426.57 |
| EW MonitorPLS NBD AHR H32141 | 97404-H32141 | \$ 12,367.00 | 10% | \$11,213.78 |
| EW MonitorPLS NBD AHR H32142 | 97404-H32142 | \$ 12,367.00 | 10% | \$11,213.78 |
| EW MonitorPLS NBD AHR H32146 | 97404-H32146 | \$ 1,767.00 | 10% | \$1,602.23 |
| EW MonitorPLS NBD AHR H32147 | 97404-H32147 | \$ 1,767.00 | 10% | \$1,602.23 |
| EW MonitorPLS NBD AHR H32148 | 97404-H32148 | \$ 2,702.00 | 10% | \$2,450.04 |
| EW MonitorPLS NBD AHR H32149 | 97404-H32149 | \$ 2,702.00 | 10% | \$2,450.04 |
| EW MonitorPLS NBD AHR H32150 | 97404-H32150 | \$ 1,767.00 | 10% | \$1,602.23 |
| EW MonitorPLS NBD AHR H32152 | 97404-H32152 | \$ 1,231.00 | 10% | \$1,116.21 |
| EW MonitorPLS NBD AHR H32169 | 97404-H32169 | \$ 1,887.00 | 10% | \$1,711.04 |
| EW MonitorPLS NBD AHR H32170 | 97404-H32170 | \$ 1,887.00 | 10% | \$1,711.04 |
| EW MonitorPLS NBD AHR H32171 | 97404-H32171 | \$ 1,822.00 | 10% | \$1,652.10 |
| EW MonitorPLS NBD AHR H32172 | 97404-H32172 | \$ 1,822.00 | 10% | \$1,652.10 |
| EW MonitorPLS NBD AHR H32173 | 97404-H32173 | \$ 3,383.00 | 10% | \$3,067.54 |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS NBD AHR H32174 | 97404-H32174 | \$ 3,383.00 | 10% | <i>\$3,067.54</i> |
| EW MonitorPLS NBD AHR H32175 | 97404-H32175 | \$ 3,010.00 | 10% | <i>\$2,729.32</i> |
| EW MonitorPLS NBD AHR H32176 | 97404-H32176 | \$ 3,010.00 | 10% | <i>\$2,729.32</i> |
| EW MonitorPLS NBD AHR H32177 | 97404-H32177 | \$ 11,645.00 | 10% | <i>\$10,559.10</i> |
| EW MonitorPLS NBD AHR H32178 | 97404-H32178 | \$ 13,853.00 | 10% | <i>\$12,561.21</i> |
| EW MonitorPLS NBD AHR H34008 | 97404-H34008 | \$ 714.00 | 10% | <i>\$647.42</i> |
| EW MonitorPLS NBD AHR H34009 | 97404-H34009 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW MonitorPLS NBD AHR H34010 | 97404-H34010 | \$ 675.00 | 10% | <i>\$612.06</i> |
| EW MonitorPLS NBD AHR H34011 | 97404-H34011 | \$ 761.00 | 10% | <i>\$690.04</i> |
| EW MonitorPLS NBD AHR H34012 | 97404-H34012 | \$ 822.00 | 10% | <i>\$745.35</i> |
| EW MonitorPLS NBD AHR H34013 | 97404-H34013 | \$ 738.00 | 10% | <i>\$669.18</i> |
| EW MonitorPLS NBD AHR H34014 | 97404-H34014 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW MonitorPLS NBD AHR H34015 | 97404-H34015 | \$ 683.00 | 10% | <i>\$619.31</i> |
| EW MonitorPLS NBD AHR H34016 | 97404-H34016 | \$ 780.00 | 10% | <i>\$707.27</i> |
| EW MonitorPLS NBD AHR H34017 | 97404-H34017 | \$ 846.00 | 10% | <i>\$767.11</i> |
| EW MonitorPLS NBD AHR H34018 | 97404-H34018 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW MonitorPLS NBD AHR H34019 | 97404-H34019 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW MonitorPLS NBD AHR H34020 | 97404-H34020 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW MonitorPLS NBD AHR H34021 | 97404-H34021 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW MonitorPLS NBD AHR H34048 | 97404-H34048 | \$ 912.00 | 10% | <i>\$826.96</i> |
| EW MonitorPLS NBD AHR H34049 | 97404-H34049 | \$ 912.00 | 10% | <i>\$826.96</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR H34050 | 97404-H34050 | \$ 848.00 | 10% | \$768.92 |
| EW MonitorPLS NBD AHR H34051 | 97404-H34051 | \$ 848.00 | 10% | \$768.92 |
| EW MonitorPLS NBD AHR H34052 | 97404-H34052 | \$ 947.00 | 10% | \$858.69 |
| EW MonitorPLS NBD AHR H34053 | 97404-H34053 | \$ 947.00 | 10% | \$858.69 |
| EW MonitorPLS NBD AHR H34054 | 97404-H34054 | \$ 882.00 | 10% | \$799.75 |
| EW MonitorPLS NBD AHR H34055 | 97404-H34055 | \$ 882.00 | 10% | \$799.75 |
| EW MonitorPLS NBD AHR H34056 | 97404-H34056 | \$ 1,033.00 | 10% | \$936.67 |
| EW MonitorPLS NBD AHR H34057 | 97404-H34057 | \$ 1,033.00 | 10% | \$936.67 |
| EW MonitorPLS NBD AHR H34058 | 97404-H34058 | \$ 995.00 | 10% | \$902.22 |
| EW MonitorPLS NBD AHR H34059 | 97404-H34059 | \$ 995.00 | 10% | \$902.22 |
| EW MonitorPLS NBD AHR H34062 | 97404-H34062 | \$ 1,033.00 | 10% | \$936.67 |
| EW MonitorPLS NBD AHR H34063 | 97404-H34063 | \$ 1,033.00 | 10% | \$936.67 |
| EW MonitorPLS NBD AHR H34064 | 97404-H34064 | \$ 873.00 | 10% | \$791.59 |
| EW MonitorPLS NBD AHR H34065 | 97404-H34065 | \$ 873.00 | 10% | \$791.59 |
| EW MonitorPLS NBD AHR H34066 | 97404-H34066 | \$ 873.00 | 10% | \$791.59 |
| EW MonitorPLS NBD AHR H34067 | 97404-H34067 | \$ 873.00 | 10% | \$791.59 |
| EW MonitorPLS NBD AHR H34068 | 97404-H34068 | \$ 873.00 | 10% | \$791.59 |
| EW MonitorPLS NBD AHR H34069 | 97404-H34069 | \$ 848.00 | 10% | \$768.92 |
| EW MonitorPLS NBD AHR H34070 | 97404-H34070 | \$ 873.00 | 10% | \$791.59 |
| EW MonitorPLS NBD AHR H34071 | 97404-H34071 | \$ 873.00 | 10% | \$791.59 |
| EW MonitorPLS NBD AHR H34072 | 97404-H34072 | \$ 2,532.00 | 10% | \$2,295.89 |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR H34073 | 97404-H34073 | \$ 2,483.00 | 10% | \$2,251.46 |
| EW MonitorPLS NBD AHR H34074 | 97404-H34074 | \$ 3,106.00 | 10% | \$2,816.37 |
| EW MonitorPLS NBD AHR H34075 | 97404-H34075 | \$ 3,010.00 | 10% | \$2,729.32 |
| EW MonitorPLS NBD AHR H34076 | 97404-H34076 | \$ 2,532.00 | 10% | \$2,295.89 |
| EW MonitorPLS NBD AHR H34077 | 97404-H34077 | \$ 2,483.00 | 10% | \$2,251.46 |
| EW MonitorPLS NBD AHR H34078 | 97404-H34078 | \$ 2,532.00 | 10% | \$2,295.89 |
| EW MonitorPLS NBD AHR H34079 | 97404-H34079 | \$ 2,483.00 | 10% | \$2,251.46 |
| EW MonitorPLS NBD AHR H34080 | 97404-H34080 | \$ 3,106.00 | 10% | \$2,816.37 |
| EW MonitorPLS NBD AHR H34081 | 97404-H34081 | \$ 3,010.00 | 10% | \$2,729.32 |
| EW MonitorPLS NBD AHR H34082 | 97404-H34082 | \$ 2,980.00 | 10% | \$2,702.12 |
| EW MonitorPLS NBD AHR H34083 | 97404-H34083 | \$ 2,886.00 | 10% | \$2,616.88 |
| EW MonitorPLS NBD AHR H34084 | 97404-H34084 | \$ 2,157.00 | 10% | \$1,955.86 |
| EW MonitorPLS NBD AHR H34085 | 97404-H34085 | \$ 2,157.00 | 10% | \$1,955.86 |
| EW MonitorPLS NBD AHR H34086 | 97404-H34086 | \$ 2,510.00 | 10% | \$2,275.94 |
| EW MonitorPLS NBD AHR H34087 | 97404-H34087 | \$ 2,408.00 | 10% | \$2,183.45 |
| EW MonitorPLS NBD AHR H34088 | 97404-H34088 | \$ 4,876.00 | 10% | \$4,421.31 |
| EW MonitorPLS NBD AHR H34089 | 97404-H34089 | \$ 4,876.00 | 10% | \$4,421.31 |
| EW MonitorPLS NBD AHR H34090 | 97404-H34090 | \$ 5,616.00 | 10% | \$5,092.31 |
| EW MonitorPLS NBD AHR H34091 | 97404-H34091 | \$ 4,629.00 | 10% | \$4,197.35 |
| EW MonitorPLS NBD AHR H34092 | 97404-H34092 | \$ 4,629.00 | 10% | \$4,197.35 |
| EW MonitorPLS NBD AHR H34093 | 97404-H34093 | \$ 4,629.00 | 10% | \$4,197.35 |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR H34094 | 97404-H34094 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34095 | 97404-H34095 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34096 | 97404-H34096 | \$ 596.00 | 10% | \$540.42 |
| EW MonitorPLS NBD AHR H34097 | 97404-H34097 | \$ 595.00 | 10% | \$539.52 |
| EW MonitorPLS NBD AHR H34098 | 97404-H34098 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34099 | 97404-H34099 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34100 | 97404-H34100 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34101 | 97404-H34101 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34102 | 97404-H34102 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34103 | 97404-H34103 | \$ 554.00 | 10% | \$502.34 |
| EW MonitorPLS NBD AHR H34104 | 97404-H34104 | \$ 381.00 | 10% | \$345.47 |
| EW MonitorPLS NBD AHR H34105 | 97404-H34105 | \$ 381.00 | 10% | \$345.47 |
| EW MonitorPLS NBD AHR H34106 | 97404-H34106 | \$ 381.00 | 10% | \$345.47 |
| EW MonitorPLS NBD AHR H34107 | 97404-H34107 | \$ 381.00 | 10% | \$345.47 |
| EW MonitorPLS NBD AHR H34108 | 97404-H34108 | \$ 381.00 | 10% | \$345.47 |
| EW MonitorPLS NBD AHR H34109 | 97404-H34109 | \$ 381.00 | 10% | \$345.47 |
| EW MonitorPLS NBD AHR H34110 | 97404-H34110 | \$ 4,459.00 | 10% | \$4,043.20 |
| EW MonitorPLS NBD AHR H34111 | 97404-H34111 | \$ 4,459.00 | 10% | \$4,043.20 |
| EW MonitorPLS NBD AHR H34112 | 97404-H34112 | \$ 4,459.00 | 10% | \$4,043.20 |
| EW MonitorPLS NBD AHR H34114 | 97404-H34114 | \$ 6,694.00 | 10% | \$6,069.78 |
| EW MonitorPLS NBD AHR H34115 | 97404-H34115 | \$ 6,454.00 | 10% | \$5,852.16 |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR H34116 | 97404-H34116 | \$ 6,454.00 | 10% | <i>\$5,852.16</i> |
| EW MonitorPLS NBD AHR H34117 | 97404-H34117 | \$ 6,694.00 | 10% | <i>\$6,069.78</i> |
| EW MonitorPLS NBD AHR H34118 | 97404-H34118 | \$ 1,083.00 | 10% | <i>\$982.01</i> |
| EW MonitorPLS NBD AHR H34119 | 97404-H34119 | \$ 1,083.00 | 10% | <i>\$982.01</i> |
| EW MonitorPLS NBD AHR H34120 | 97404-H34120 | \$ 822.00 | 10% | <i>\$745.35</i> |
| EW MonitorPLS NBD AHR H34121 | 97404-H34121 | \$ 822.00 | 10% | <i>\$745.35</i> |
| EW MonitorPLS NBD AHR H34122 | 97404-H34122 | \$ 844.00 | 10% | <i>\$765.30</i> |
| EW MonitorPLS NBD AHR H34123 | 97404-H34123 | \$ 844.00 | 10% | <i>\$765.30</i> |
| EW MonitorPLS NBD AHR H34124 | 97404-H34124 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW MonitorPLS NBD AHR H34125 | 97404-H34125 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW MonitorPLS NBD AHR H34126 | 97404-H34126 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW MonitorPLS NBD AHR H34127 | 97404-H34127 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW MonitorPLS NBD AHR H34129 | 97404-H34129 | \$ 888.00 | 10% | <i>\$805.19</i> |
| EW MonitorPLS NBD AHR H34130 | 97404-H34130 | \$ 922.00 | 10% | <i>\$836.02</i> |
| EW MonitorPLS NBD AHR H34131 | 97404-H34131 | \$ 917.00 | 10% | <i>\$831.49</i> |
| EW MonitorPLS NBD AHR H34132 | 97404-H34132 | \$ 922.00 | 10% | <i>\$836.02</i> |
| EW MonitorPLS NBD AHR H34172 | 97404-H34172 | \$ 1,244.00 | 10% | <i>\$1,128.00</i> |
| EW MonitorPLS NBD AHR H34174 | 97404-H34174 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34175 | 97404-H34175 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34176 | 97404-H34176 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34177 | 97404-H34177 | \$ 223.00 | 10% | <i>\$202.21</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34178 | 97404-H34178 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34179 | 97404-H34179 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34180 | 97404-H34180 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34181 | 97404-H34181 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34182 | 97404-H34182 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34183 | 97404-H34183 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34184 | 97404-H34184 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34185 | 97404-H34185 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34186 | 97404-H34186 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34187 | 97404-H34187 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34188 | 97404-H34188 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34189 | 97404-H34189 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34190 | 97404-H34190 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34191 | 97404-H34191 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34192 | 97404-H34192 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34193 | 97404-H34193 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34194 | 97404-H34194 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34195 | 97404-H34195 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34196 | 97404-H34196 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34197 | 97404-H34197 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW MonitorPLS NBD AHR H34198 | 97404-H34198 | \$ 223.00 | 10% | <i>\$202.21</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34199 | 97404-H34199 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34200 | 97404-H34200 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34201 | 97404-H34201 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34202 | 97404-H34202 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34203 | 97404-H34203 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34204 | 97404-H34204 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34205 | 97404-H34205 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34206 | 97404-H34206 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34207 | 97404-H34207 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34208 | 97404-H34208 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34209 | 97404-H34209 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34210 | 97404-H34210 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34211 | 97404-H34211 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34212 | 97404-H34212 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34213 | 97404-H34213 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34214 | 97404-H34214 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34215 | 97404-H34215 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34216 | 97404-H34216 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34217 | 97404-H34217 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34218 | 97404-H34218 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBD AHR H34219 | 97404-H34219 | \$ 223.00 | 10% | \$202.21 |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34220 | 97404-H34220 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34221 | 97404-H34221 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34222 | 97404-H34222 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34223 | 97404-H34223 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34224 | 97404-H34224 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34225 | 97404-H34225 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34226 | 97404-H34226 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34227 | 97404-H34227 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34228 | 97404-H34228 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34229 | 97404-H34229 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34230 | 97404-H34230 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34231 | 97404-H34231 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34232 | 97404-H34232 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34233 | 97404-H34233 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34234 | 97404-H34234 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34235 | 97404-H34235 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34236 | 97404-H34236 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34237 | 97404-H34237 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34238 | 97404-H34238 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34239 | 97404-H34239 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34240 | 97404-H34240 | \$ 240.00 | 10% | <i>\$217.62</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34241 | 97404-H34241 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34242 | 97404-H34242 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34243 | 97404-H34243 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34244 | 97404-H34244 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34245 | 97404-H34245 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34246 | 97404-H34246 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34247 | 97404-H34247 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34248 | 97404-H34248 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34249 | 97404-H34249 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34250 | 97404-H34250 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34251 | 97404-H34251 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34252 | 97404-H34252 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34253 | 97404-H34253 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34254 | 97404-H34254 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34255 | 97404-H34255 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34256 | 97404-H34256 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34257 | 97404-H34257 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34258 | 97404-H34258 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34259 | 97404-H34259 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34260 | 97404-H34260 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34261 | 97404-H34261 | \$ 240.00 | 10% | <i>\$217.62</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34262 | 97404-H34262 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34263 | 97404-H34263 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34264 | 97404-H34264 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34265 | 97404-H34265 | \$ 240.00 | 10% | <i>\$217.62</i> |
| EW MonitorPLS NBD AHR H34266 | 97404-H34266 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34267 | 97404-H34267 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34268 | 97404-H34268 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34269 | 97404-H34269 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34270 | 97404-H34270 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34271 | 97404-H34271 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34272 | 97404-H34272 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34273 | 97404-H34273 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34274 | 97404-H34274 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34275 | 97404-H34275 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34276 | 97404-H34276 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34277 | 97404-H34277 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34278 | 97404-H34278 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34279 | 97404-H34279 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34280 | 97404-H34280 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34281 | 97404-H34281 | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS NBD AHR H34282 | 97404-H34282 | \$ 226.00 | 10% | <i>\$204.93</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34283 | 97404-H34283 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34284 | 97404-H34284 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34285 | 97404-H34285 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34286 | 97404-H34286 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34287 | 97404-H34287 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34288 | 97404-H34288 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34289 | 97404-H34289 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34290 | 97404-H34290 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34291 | 97404-H34291 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34292 | 97404-H34292 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34293 | 97404-H34293 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34294 | 97404-H34294 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34295 | 97404-H34295 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34296 | 97404-H34296 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34297 | 97404-H34297 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34298 | 97404-H34298 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34299 | 97404-H34299 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34300 | 97404-H34300 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34301 | 97404-H34301 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34302 | 97404-H34302 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34303 | 97404-H34303 | \$ 226.00 | 10% | \$204.93 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34304 | 97404-H34304 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34305 | 97404-H34305 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H34306 | 97404-H34306 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34307 | 97404-H34307 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34308 | 97404-H34308 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34309 | 97404-H34309 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34310 | 97404-H34310 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34311 | 97404-H34311 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34312 | 97404-H34312 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34313 | 97404-H34313 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34314 | 97404-H34314 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34315 | 97404-H34315 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34316 | 97404-H34316 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34317 | 97404-H34317 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34318 | 97404-H34318 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34319 | 97404-H34319 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34320 | 97404-H34320 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34321 | 97404-H34321 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34322 | 97404-H34322 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34323 | 97404-H34323 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34324 | 97404-H34324 | \$ 248.00 | 10% | \$224.87 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34325 | 97404-H34325 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34326 | 97404-H34326 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34327 | 97404-H34327 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34328 | 97404-H34328 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34329 | 97404-H34329 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34330 | 97404-H34330 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34331 | 97404-H34331 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34332 | 97404-H34332 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34333 | 97404-H34333 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34334 | 97404-H34334 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34335 | 97404-H34335 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34336 | 97404-H34336 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34337 | 97404-H34337 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34338 | 97404-H34338 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34339 | 97404-H34339 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34340 | 97404-H34340 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34341 | 97404-H34341 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34342 | 97404-H34342 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34343 | 97404-H34343 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34344 | 97404-H34344 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34345 | 97404-H34345 | \$ 248.00 | 10% | \$224.87 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34346 | 97404-H34346 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34347 | 97404-H34347 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34348 | 97404-H34348 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34349 | 97404-H34349 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34350 | 97404-H34350 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34351 | 97404-H34351 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34352 | 97404-H34352 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34353 | 97404-H34353 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34354 | 97404-H34354 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34355 | 97404-H34355 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34356 | 97404-H34356 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34357 | 97404-H34357 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34358 | 97404-H34358 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34359 | 97404-H34359 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34360 | 97404-H34360 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34361 | 97404-H34361 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34362 | 97404-H34362 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34363 | 97404-H34363 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34364 | 97404-H34364 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34365 | 97404-H34365 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34366 | 97404-H34366 | \$ 276.00 | 10% | \$250.26 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34367 | 97404-H34367 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34368 | 97404-H34368 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34369 | 97404-H34369 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34370 | 97404-H34370 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34371 | 97404-H34371 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34372 | 97404-H34372 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34373 | 97404-H34373 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34374 | 97404-H34374 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34375 | 97404-H34375 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34376 | 97404-H34376 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34377 | 97404-H34377 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34378 | 97404-H34378 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34379 | 97404-H34379 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34380 | 97404-H34380 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34381 | 97404-H34381 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34382 | 97404-H34382 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34383 | 97404-H34383 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34384 | 97404-H34384 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34385 | 97404-H34385 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34386 | 97404-H34386 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34387 | 97404-H34387 | \$ 276.00 | 10% | \$250.26 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34388 | 97404-H34388 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34389 | 97404-H34389 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34390 | 97404-H34390 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34391 | 97404-H34391 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34392 | 97404-H34392 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34393 | 97404-H34393 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34394 | 97404-H34394 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34395 | 97404-H34395 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34396 | 97404-H34396 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34397 | 97404-H34397 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34398 | 97404-H34398 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34399 | 97404-H34399 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34400 | 97404-H34400 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34401 | 97404-H34401 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34402 | 97404-H34402 | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS NBD AHR H34403 | 97404-H34403 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34404 | 97404-H34404 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34405 | 97404-H34405 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34406 | 97404-H34406 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34407 | 97404-H34407 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34408 | 97404-H34408 | \$ 329.00 | 10% | \$298.32 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34409 | 97404-H34409 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34410 | 97404-H34410 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34411 | 97404-H34411 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34412 | 97404-H34412 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34413 | 97404-H34413 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34414 | 97404-H34414 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34415 | 97404-H34415 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34416 | 97404-H34416 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34417 | 97404-H34417 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34418 | 97404-H34418 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34419 | 97404-H34419 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34420 | 97404-H34420 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34421 | 97404-H34421 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34422 | 97404-H34422 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34423 | 97404-H34423 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34424 | 97404-H34424 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34425 | 97404-H34425 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34426 | 97404-H34426 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34427 | 97404-H34427 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34428 | 97404-H34428 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34429 | 97404-H34429 | \$ 329.00 | 10% | \$298.32 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34430 | 97404-H34430 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34431 | 97404-H34431 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34432 | 97404-H34432 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34433 | 97404-H34433 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34434 | 97404-H34434 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34435 | 97404-H34435 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34436 | 97404-H34436 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34437 | 97404-H34437 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34438 | 97404-H34438 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34439 | 97404-H34439 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34440 | 97404-H34440 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34441 | 97404-H34441 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34442 | 97404-H34442 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34443 | 97404-H34443 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34444 | 97404-H34444 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34445 | 97404-H34445 | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS NBD AHR H34446 | 97404-H34446 | \$ 352.00 | 10% | \$319.18 |
| EW MonitorPLS NBD AHR H34447 | 97404-H34447 | \$ 352.00 | 10% | \$319.18 |
| EW MonitorPLS NBD AHR H34448 | 97404-H34448 | \$ 352.00 | 10% | \$319.18 |
| EW MonitorPLS NBD AHR H34449 | 97404-H34449 | \$ 352.00 | 10% | \$319.18 |
| EW MonitorPLS NBD AHR H34450 | 97404-H34450 | \$ 352.00 | 10% | \$319.18 |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34451 | 97404-H34451 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34452 | 97404-H34452 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34453 | 97404-H34453 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34454 | 97404-H34454 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34455 | 97404-H34455 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34456 | 97404-H34456 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34457 | 97404-H34457 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34458 | 97404-H34458 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34459 | 97404-H34459 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34460 | 97404-H34460 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34461 | 97404-H34461 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34462 | 97404-H34462 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34463 | 97404-H34463 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34464 | 97404-H34464 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34465 | 97404-H34465 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34466 | 97404-H34466 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34467 | 97404-H34467 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34468 | 97404-H34468 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34469 | 97404-H34469 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34470 | 97404-H34470 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34471 | 97404-H34471 | \$ 352.00 | 10% | <i>\$319.18</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34472 | 97404-H34472 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34473 | 97404-H34473 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34474 | 97404-H34474 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34475 | 97404-H34475 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34476 | 97404-H34476 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34477 | 97404-H34477 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34478 | 97404-H34478 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34479 | 97404-H34479 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34480 | 97404-H34480 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34481 | 97404-H34481 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34482 | 97404-H34482 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34483 | 97404-H34483 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34484 | 97404-H34484 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34485 | 97404-H34485 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34486 | 97404-H34486 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34487 | 97404-H34487 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34488 | 97404-H34488 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34489 | 97404-H34489 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW MonitorPLS NBD AHR H34490 | 97404-H34490 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34491 | 97404-H34491 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34492 | 97404-H34492 | \$ 213.00 | 10% | <i>\$193.14</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34493 | 97404-H34493 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34494 | 97404-H34494 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34495 | 97404-H34495 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34496 | 97404-H34496 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34497 | 97404-H34497 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34498 | 97404-H34498 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34499 | 97404-H34499 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34500 | 97404-H34500 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34501 | 97404-H34501 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34502 | 97404-H34502 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34503 | 97404-H34503 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34504 | 97404-H34504 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34505 | 97404-H34505 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34506 | 97404-H34506 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34507 | 97404-H34507 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34508 | 97404-H34508 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34509 | 97404-H34509 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34510 | 97404-H34510 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34511 | 97404-H34511 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34512 | 97404-H34512 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34513 | 97404-H34513 | \$ 213.00 | 10% | <i>\$193.14</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34514 | 97404-H34514 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34515 | 97404-H34515 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34516 | 97404-H34516 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34517 | 97404-H34517 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34518 | 97404-H34518 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34519 | 97404-H34519 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34520 | 97404-H34520 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34521 | 97404-H34521 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34522 | 97404-H34522 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34523 | 97404-H34523 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34524 | 97404-H34524 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34525 | 97404-H34525 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34526 | 97404-H34526 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34527 | 97404-H34527 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34528 | 97404-H34528 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34529 | 97404-H34529 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34530 | 97404-H34530 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34531 | 97404-H34531 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34532 | 97404-H34532 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34533 | 97404-H34533 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34534 | 97404-H34534 | \$ 213.00 | 10% | <i>\$193.14</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34535 | 97404-H34535 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34536 | 97404-H34536 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34537 | 97404-H34537 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34538 | 97404-H34538 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34539 | 97404-H34539 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34540 | 97404-H34540 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34541 | 97404-H34541 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34542 | 97404-H34542 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34543 | 97404-H34543 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34544 | 97404-H34544 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34545 | 97404-H34545 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34546 | 97404-H34546 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34547 | 97404-H34547 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34548 | 97404-H34548 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34549 | 97404-H34549 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34550 | 97404-H34550 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34551 | 97404-H34551 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34552 | 97404-H34552 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34553 | 97404-H34553 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34554 | 97404-H34554 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34555 | 97404-H34555 | \$ 213.00 | 10% | <i>\$193.14</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34556 | 97404-H34556 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34557 | 97404-H34557 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34558 | 97404-H34558 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34559 | 97404-H34559 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34560 | 97404-H34560 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34561 | 97404-H34561 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34562 | 97404-H34562 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34563 | 97404-H34563 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34564 | 97404-H34564 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34565 | 97404-H34565 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34566 | 97404-H34566 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34567 | 97404-H34567 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34568 | 97404-H34568 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34569 | 97404-H34569 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34570 | 97404-H34570 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34571 | 97404-H34571 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34572 | 97404-H34572 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34573 | 97404-H34573 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34574 | 97404-H34574 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34575 | 97404-H34575 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34576 | 97404-H34576 | \$ 213.00 | 10% | <i>\$193.14</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBD AHR H34577 | 97404-H34577 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34578 | 97404-H34578 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34579 | 97404-H34579 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34580 | 97404-H34580 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34581 | 97404-H34581 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34582 | 97404-H34582 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34583 | 97404-H34583 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34584 | 97404-H34584 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34585 | 97404-H34585 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34586 | 97404-H34586 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW MonitorPLS NBD AHR H34587 | 97404-H34587 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34588 | 97404-H34588 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34589 | 97404-H34589 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34590 | 97404-H34590 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34591 | 97404-H34591 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34592 | 97404-H34592 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34593 | 97404-H34593 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34594 | 97404-H34594 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34595 | 97404-H34595 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34596 | 97404-H34596 | \$ 248.00 | 10% | <i>\$224.87</i> |
| EW MonitorPLS NBD AHR H34597 | 97404-H34597 | \$ 248.00 | 10% | <i>\$224.87</i> |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34598 | 97404-H34598 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34599 | 97404-H34599 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34600 | 97404-H34600 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34601 | 97404-H34601 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34602 | 97404-H34602 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34603 | 97404-H34603 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34604 | 97404-H34604 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34605 | 97404-H34605 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34606 | 97404-H34606 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34607 | 97404-H34607 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34608 | 97404-H34608 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34609 | 97404-H34609 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34610 | 97404-H34610 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34611 | 97404-H34611 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34612 | 97404-H34612 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34613 | 97404-H34613 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34614 | 97404-H34614 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34615 | 97404-H34615 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34616 | 97404-H34616 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34617 | 97404-H34617 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34618 | 97404-H34618 | \$ 248.00 | 10% | \$224.87 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34619 | 97404-H34619 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34620 | 97404-H34620 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34621 | 97404-H34621 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34622 | 97404-H34622 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34623 | 97404-H34623 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34624 | 97404-H34624 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34625 | 97404-H34625 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34626 | 97404-H34626 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34627 | 97404-H34627 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34628 | 97404-H34628 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34629 | 97404-H34629 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34630 | 97404-H34630 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34631 | 97404-H34631 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H34632 | 97404-H34632 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34633 | 97404-H34633 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34634 | 97404-H34634 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34635 | 97404-H34635 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34636 | 97404-H34636 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34637 | 97404-H34637 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34638 | 97404-H34638 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34639 | 97404-H34639 | \$ 253.00 | 10% | \$229.41 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34640 | 97404-H34640 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34641 | 97404-H34641 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34642 | 97404-H34642 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34643 | 97404-H34643 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34644 | 97404-H34644 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34645 | 97404-H34645 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34646 | 97404-H34646 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34647 | 97404-H34647 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34648 | 97404-H34648 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34649 | 97404-H34649 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34650 | 97404-H34650 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34651 | 97404-H34651 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34652 | 97404-H34652 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34653 | 97404-H34653 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34654 | 97404-H34654 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34655 | 97404-H34655 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34656 | 97404-H34656 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34657 | 97404-H34657 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34658 | 97404-H34658 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34659 | 97404-H34659 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34660 | 97404-H34660 | \$ 253.00 | 10% | \$229.41 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34661 | 97404-H34661 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34662 | 97404-H34662 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34663 | 97404-H34663 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34664 | 97404-H34664 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34665 | 97404-H34665 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34666 | 97404-H34666 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34667 | 97404-H34667 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34668 | 97404-H34668 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34669 | 97404-H34669 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34670 | 97404-H34670 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34671 | 97404-H34671 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34672 | 97404-H34672 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34673 | 97404-H34673 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34674 | 97404-H34674 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34675 | 97404-H34675 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34676 | 97404-H34676 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34677 | 97404-H34677 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34678 | 97404-H34678 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBD AHR H34679 | 97404-H34679 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34680 | 97404-H34680 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34681 | 97404-H34681 | \$ 265.00 | 10% | \$240.29 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34682 | 97404-H34682 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34683 | 97404-H34683 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34684 | 97404-H34684 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34685 | 97404-H34685 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34686 | 97404-H34686 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34687 | 97404-H34687 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34688 | 97404-H34688 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34689 | 97404-H34689 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34690 | 97404-H34690 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34691 | 97404-H34691 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34692 | 97404-H34692 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34693 | 97404-H34693 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34694 | 97404-H34694 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34695 | 97404-H34695 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34696 | 97404-H34696 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34697 | 97404-H34697 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34698 | 97404-H34698 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34699 | 97404-H34699 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34700 | 97404-H34700 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34701 | 97404-H34701 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34702 | 97404-H34702 | \$ 265.00 | 10% | \$240.29 |

| | | | | |
|---------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBD AHR H34703 | 97404-H34703 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34704 | 97404-H34704 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34705 | 97404-H34705 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34706 | 97404-H34706 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34707 | 97404-H34707 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34708 | 97404-H34708 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34709 | 97404-H34709 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34710 | 97404-H34710 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34711 | 97404-H34711 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34712 | 97404-H34712 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34713 | 97404-H34713 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34714 | 97404-H34714 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34715 | 97404-H34715 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34716 | 97404-H34716 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34717 | 97404-H34717 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34718 | 97404-H34718 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34719 | 97404-H34719 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34720 | 97404-H34720 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34721 | 97404-H34721 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34722 | 97404-H34722 | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS NBD AHR H34723 | 97404-H34723 | \$ 265.00 | 10% | \$240.29 |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR H34724 | 97404-H34724 | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW MonitorPLS NBD AHR H34725 | 97404-H34725 | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW MonitorPLS NBD AHR H34726 | 97404-H34726 | \$ 2,651.00 | 10% | <i>\$2,403.79</i> |
| EW MonitorPLS NBD AHR H34727 | 97404-H34727 | \$ 2,651.00 | 10% | <i>\$2,403.79</i> |
| EW MonitorPLS NBD AHR H34728 | 97404-H34728 | \$ 2,651.00 | 10% | <i>\$2,403.79</i> |
| EW MonitorPLS NBD AHR H34729 | 97404-H34729 | \$ 2,651.00 | 10% | <i>\$2,403.79</i> |
| EW MonitorPLS NBD AHR H34730 | 97404-H34730 | \$ 2,792.00 | 10% | <i>\$2,531.65</i> |
| EW MonitorPLS NBD AHR H34731 | 97404-H34731 | \$ 2,792.00 | 10% | <i>\$2,531.65</i> |
| EW MonitorPLS NBD AHR H34732 | 97404-H34732 | \$ 2,792.00 | 10% | <i>\$2,531.65</i> |
| EW MonitorPLS NBD AHR H34733 | 97404-H34733 | \$ 2,792.00 | 10% | <i>\$2,531.65</i> |
| EW MonitorPLS NBD AHR H34734 | 97404-H34734 | \$ 1,015.00 | 10% | <i>\$920.35</i> |
| EW MonitorPLS NBD AHR H34735 | 97404-H34735 | \$ 1,015.00 | 10% | <i>\$920.35</i> |
| EW MonitorPLS NBD AHR H34736 | 97404-H34736 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H34737 | 97404-H34737 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H34738 | 97404-H34738 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34739 | 97404-H34739 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34740 | 97404-H34740 | \$ 1,015.00 | 10% | <i>\$920.35</i> |
| EW MonitorPLS NBD AHR H34741 | 97404-H34741 | \$ 1,015.00 | 10% | <i>\$920.35</i> |
| EW MonitorPLS NBD AHR H34742 | 97404-H34742 | \$ 886.00 | 10% | <i>\$803.38</i> |
| EW MonitorPLS NBD AHR H34743 | 97404-H34743 | \$ 886.00 | 10% | <i>\$803.38</i> |
| EW MonitorPLS NBD AHR H34744 | 97404-H34744 | \$ 1,092.00 | 10% | <i>\$990.17</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS NBD AHR H34745 | 97404-H34745 | \$ 1,092.00 | 10% | <i>\$990.17</i> |
| EW MonitorPLS NBD AHR H34746 | 97404-H34746 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW MonitorPLS NBD AHR H34747 | 97404-H34747 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW MonitorPLS NBD AHR H34748 | 97404-H34748 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34749 | 97404-H34749 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34750 | 97404-H34750 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34751 | 97404-H34751 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34752 | 97404-H34752 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34753 | 97404-H34753 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34754 | 97404-H34754 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34755 | 97404-H34755 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS NBD AHR H34756 | 97404-H34756 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H34757 | 97404-H34757 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H34758 | 97404-H34758 | \$ 1,092.00 | 10% | <i>\$990.17</i> |
| EW MonitorPLS NBD AHR H34759 | 97404-H34759 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H34760 | 97404-H34760 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H34761 | 97404-H34761 | \$ 1,092.00 | 10% | <i>\$990.17</i> |
| EW MonitorPLS NBD AHR H34993 | 97404-H34993 | \$ 13,053.00 | 10% | <i>\$11,835.81</i> |
| EW MonitorPLS NBD AHR H34994 | 97404-H34994 | \$ 13,053.00 | 10% | <i>\$11,835.81</i> |
| EW MonitorPLS NBD AHR H34996 | 97404-H34996 | \$ 13,053.00 | 10% | <i>\$11,835.81</i> |
| EW MonitorPLS NBD AHR H34997 | 97404-H34997 | \$ 13,053.00 | 10% | <i>\$11,835.81</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR H35005 | 97404-H35005 | \$ 9,404.00 | 10% | \$8,527.08 |
| EW MonitorPLS NBD AHR H35006 | 97404-H35006 | \$ 9,404.00 | 10% | \$8,527.08 |
| EW MonitorPLS NBD AHR H35012 | 97404-H35012 | \$ 6,042.00 | 10% | \$5,478.58 |
| EW MonitorPLS NBD AHR H35070 | 97404-H35070 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35071 | 97404-H35071 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35072 | 97404-H35072 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35073 | 97404-H35073 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35074 | 97404-H35074 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35075 | 97404-H35075 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35076 | 97404-H35076 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35077 | 97404-H35077 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35078 | 97404-H35078 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35079 | 97404-H35079 | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS NBD AHR H35080 | 97404-H35080 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H35081 | 97404-H35081 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H35082 | 97404-H35082 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H35083 | 97404-H35083 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBD AHR H35270 | 97404-H35270 | \$ 947.00 | 10% | \$858.69 |
| EW MonitorPLS NBD AHR H35271 | 97404-H35271 | \$ 882.00 | 10% | \$799.75 |
| EW MonitorPLS NBD AHR H35272 | 97404-H35272 | \$ 817.00 | 10% | \$740.81 |
| EW MonitorPLS NBD AHR H35273 | 97404-H35273 | \$ 817.00 | 10% | \$740.81 |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR H35274 | 97404-H35274 | \$ 1,151.00 | 10% | <i>\$1,043.67</i> |
| EW MonitorPLS NBD AHR H35275 | 97404-H35275 | \$ 1,033.00 | 10% | <i>\$936.67</i> |
| EW MonitorPLS NBD AHR H35276 | 97404-H35276 | \$ 2,532.00 | 10% | <i>\$2,295.89</i> |
| EW MonitorPLS NBD AHR H35277 | 97404-H35277 | \$ 2,980.00 | 10% | <i>\$2,702.12</i> |
| EW MonitorPLS NBD AHR H35278 | 97404-H35278 | \$ 2,157.00 | 10% | <i>\$1,955.86</i> |
| EW MonitorPLS NBD AHR H35279 | 97404-H35279 | \$ 2,408.00 | 10% | <i>\$2,183.45</i> |
| EW MonitorPLS NBD AHR H35280 | 97404-H35280 | \$ 4,374.00 | 10% | <i>\$3,966.12</i> |
| EW MonitorPLS NBD AHR H35292 | 97404-H35292 | \$ 2,157.00 | 10% | <i>\$1,955.86</i> |
| EW MonitorPLS NBD AHR H35293 | 97404-H35293 | \$ 2,408.00 | 10% | <i>\$2,183.45</i> |
| EW MonitorPLS NBD AHR H35295 | 97404-H35295 | \$ 844.00 | 10% | <i>\$765.30</i> |
| EW MonitorPLS NBD AHR H35302 | 97404-H35302 | \$ 2,712.00 | 10% | <i>\$2,459.11</i> |
| EW MonitorPLS NBD AHR H35303 | 97404-H35303 | \$ 2,712.00 | 10% | <i>\$2,459.11</i> |
| EW MonitorPLS NBD AHR H35304 | 97404-H35304 | \$ 2,712.00 | 10% | <i>\$2,459.11</i> |
| EW MonitorPLS NBD AHR H35305 | 97404-H35305 | \$ 2,808.00 | 10% | <i>\$2,546.15</i> |
| EW MonitorPLS NBD AHR H35306 | 97404-H35306 | \$ 2,808.00 | 10% | <i>\$2,546.15</i> |
| EW MonitorPLS NBD AHR H35307 | 97404-H35307 | \$ 2,808.00 | 10% | <i>\$2,546.15</i> |
| EW MonitorPLS NBD AHR H35309 | 97404-H35309 | \$ 3,041.00 | 10% | <i>\$2,757.43</i> |
| EW MonitorPLS NBD AHR H35310 | 97404-H35310 | \$ 3,041.00 | 10% | <i>\$2,757.43</i> |
| EW MonitorPLS NBD AHR H35311 | 97404-H35311 | \$ 3,041.00 | 10% | <i>\$2,757.43</i> |
| EW MonitorPLS NBD AHR H35312 | 97404-H35312 | \$ 2,514.00 | 10% | <i>\$2,279.57</i> |
| EW MonitorPLS NBD AHR H35313 | 97404-H35313 | \$ 2,514.00 | 10% | <i>\$2,279.57</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR H35314 | 97404-H35314 | \$ 2,514.00 | 10% | \$2,279.57 |
| EW MonitorPLS NBD AHR H35315 | 97404-H35315 | \$ 1,510.00 | 10% | \$1,369.19 |
| EW MonitorPLS NBD AHR H35318 | 97404-H35318 | \$ 998.00 | 10% | \$904.94 |
| EW MonitorPLS NBD AHR H35319 | 97404-H35319 | \$ 1,149.00 | 10% | \$1,041.86 |
| EW MonitorPLS NBD AHR H35320 | 97404-H35320 | \$ 1,170.00 | 10% | \$1,060.90 |
| EW MonitorPLS NBD AHR H35321 | 97404-H35321 | \$ 1,337.00 | 10% | \$1,212.32 |
| EW MonitorPLS NBD AHR H35322 | 97404-H35322 | \$ 1,528.00 | 10% | \$1,385.51 |
| EW MonitorPLS NBD AHR H35323 | 97404-H35323 | \$ 1,510.00 | 10% | \$1,369.19 |
| EW MonitorPLS NBD AHR H35328 | 97404-H35328 | \$ 481.00 | 10% | \$436.15 |
| EW MonitorPLS NBD AHR H35330 | 97404-H35330 | \$ 662.00 | 10% | \$600.27 |
| EW MonitorPLS NBD AHR H35340 | 97404-H35340 | \$ 3,052.00 | 10% | \$2,767.40 |
| EW MonitorPLS NBD AHR H35341 | 97404-H35341 | \$ 3,052.00 | 10% | \$2,767.40 |
| EW MonitorPLS NBD AHR H35342 | 97404-H35342 | \$ 2,590.00 | 10% | \$2,348.48 |
| EW MonitorPLS NBD AHR H35343 | 97404-H35343 | \$ 3,052.00 | 10% | \$2,767.40 |
| EW MonitorPLS NBD AHR H35344 | 97404-H35344 | \$ 3,147.00 | 10% | \$2,853.54 |
| EW MonitorPLS NBD AHR H35345 | 97404-H35345 | \$ 3,147.00 | 10% | \$2,853.54 |
| EW MonitorPLS NBD AHR H35346 | 97404-H35346 | \$ 2,662.00 | 10% | \$2,413.77 |
| EW MonitorPLS NBD AHR H35347 | 97404-H35347 | \$ 3,147.00 | 10% | \$2,853.54 |
| EW MonitorPLS NBD AHR H35349 | 97404-H35349 | \$ 3,389.00 | 10% | \$3,072.98 |
| EW MonitorPLS NBD AHR H35350 | 97404-H35350 | \$ 3,389.00 | 10% | \$3,072.98 |
| EW MonitorPLS NBD AHR H35351 | 97404-H35351 | \$ 2,855.00 | 10% | \$2,588.77 |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR H35352 | 97404-H35352 | \$ 3,389.00 | 10% | \$3,072.98 |
| EW MonitorPLS NBD AHR H35359 | 97404-H35359 | \$ 1,337.00 | 10% | \$1,212.32 |
| EW MonitorPLS NBD AHR H35360 | 97404-H35360 | \$ 1,528.00 | 10% | \$1,385.51 |
| EW MonitorPLS NBD AHR H35361 | 97404-H35361 | \$ 1,510.00 | 10% | \$1,369.19 |
| EW MonitorPLS NBD AHR H35362 | 97404-H35362 | \$ 998.00 | 10% | \$904.94 |
| EW MonitorPLS NBD AHR H35366 | 97404-H35366 | \$ 1,208.00 | 10% | \$1,095.35 |
| EW MonitorPLS NBD AHR H35367 | 97404-H35367 | \$ 1,409.00 | 10% | \$1,277.61 |
| EW MonitorPLS NBD AHR H35368 | 97404-H35368 | \$ 2,147.00 | 10% | \$1,946.79 |
| EW MonitorPLS NBD AHR H35369 | 97404-H35369 | \$ 698.00 | 10% | \$632.91 |
| EW MonitorPLS NBD AHR H35370 | 97404-H35370 | \$ 982.00 | 10% | \$890.43 |
| EW MonitorPLS NBD AHR H35375 | 97404-H35375 | \$ 789.00 | 10% | \$715.43 |
| EW MonitorPLS NBD AHR H35376 | 97404-H35376 | \$ 1,183.00 | 10% | \$1,072.69 |
| EW MonitorPLS NBD AHR H35377 | 97404-H35377 | \$ 497.00 | 10% | \$450.65 |
| EW MonitorPLS NBD AHR H35378 | 97404-H35378 | \$ 789.00 | 10% | \$715.43 |
| EW MonitorPLS NBD AHR H35379 | 97404-H35379 | \$ 497.00 | 10% | \$450.65 |
| EW MonitorPLS NBD AHR H35380 | 97404-H35380 | \$ 890.00 | 10% | \$807.01 |
| EW MonitorPLS NBD AHR H35381 | 97404-H35381 | \$ 1,088.00 | 10% | \$986.54 |
| EW MonitorPLS NBD AHR H35384 | 97404-H35384 | \$ 401.00 | 10% | \$363.61 |
| EW MonitorPLS NBD AHR H35385 | 97404-H35385 | \$ 534.00 | 10% | \$484.20 |
| EW MonitorPLS NBD AHR H35386 | 97404-H35386 | \$ 885.00 | 10% | \$802.47 |
| EW MonitorPLS NBD AHR H35387 | 97404-H35387 | \$ 827.00 | 10% | \$749.88 |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBD AHR H35388 | 97404-H35388 | \$ 610.00 | 10% | \$553.12 |
| EW MonitorPLS NBD AHR H35389 | 97404-H35389 | \$ 345.00 | 10% | \$312.83 |
| EW MonitorPLS NBD AHR H35390 | 97404-H35390 | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS NBD AHR H35391 | 97404-H35391 | \$ 649.00 | 10% | \$588.48 |
| EW MonitorPLS NBD AHR H35392 | 97404-H35392 | \$ 992.00 | 10% | \$899.50 |
| EW MonitorPLS NBD AHR H35393 | 97404-H35393 | \$ 1,323.00 | 10% | \$1,199.63 |
| EW MonitorPLS NBD AHR H35394 | 97404-H35394 | \$ 243.00 | 10% | \$220.34 |
| EW MonitorPLS NBD AHR H35395 | 97404-H35395 | \$ 204.00 | 10% | \$184.98 |
| EW MonitorPLS NBD AHR H35396 | 97404-H35396 | \$ 243.00 | 10% | \$220.34 |
| EW MonitorPLS NBD AHR H35397 | 97404-H35397 | \$ 204.00 | 10% | \$184.98 |
| EW MonitorPLS NBD AHR H35398 | 97404-H35398 | \$ 616.00 | 10% | \$558.56 |
| EW MonitorPLS NBD AHR H35399 | 97404-H35399 | \$ 751.00 | 10% | \$680.97 |
| EW MonitorPLS NBD AHR H35400 | 97404-H35400 | \$ 827.00 | 10% | \$749.88 |
| EW MonitorPLS NBD AHR H35401 | 97404-H35401 | \$ 445.00 | 10% | \$403.50 |
| EW MonitorPLS NBD AHR H35415 | 97404-H35415 | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS NBD AHR H35416 | 97404-H35416 | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS NBD AHR H35426 | 97404-H35426 | \$ 345.00 | 10% | \$312.83 |
| EW MonitorPLS NBD AHR H35427 | 97404-H35427 | \$ 827.00 | 10% | \$749.88 |
| EW MonitorPLS NBD AHR H35428 | 97404-H35428 | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS NBD AHR H35429 | 97404-H35429 | \$ 649.00 | 10% | \$588.48 |
| EW MonitorPLS NBD AHR H35430 | 97404-H35430 | \$ 986.00 | 10% | \$894.06 |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR H35431 | 97404-H35431 | \$ 986.00 | 10% | <i>\$894.06</i> |
| EW MonitorPLS NBD AHR H35432 | 97404-H35432 | \$ 886.00 | 10% | <i>\$803.38</i> |
| EW MonitorPLS NBD AHR H35433 | 97404-H35433 | \$ 1,066.00 | 10% | <i>\$966.60</i> |
| EW MonitorPLS NBD AHR H35434 | 97404-H35434 | \$ 1,117.00 | 10% | <i>\$1,012.84</i> |
| EW MonitorPLS NBD AHR H35435 | 97404-H35435 | \$ 1,117.00 | 10% | <i>\$1,012.84</i> |
| EW MonitorPLS NBD AHR H35436 | 97404-H35436 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW MonitorPLS NBD AHR H35437 | 97404-H35437 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW MonitorPLS NBD AHR H35438 | 97404-H35438 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW MonitorPLS NBD AHR H35439 | 97404-H35439 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW MonitorPLS NBD AHR H35440 | 97404-H35440 | \$ 1,066.00 | 10% | <i>\$966.60</i> |
| EW MonitorPLS NBD AHR H35441 | 97404-H35441 | \$ 1,066.00 | 10% | <i>\$966.60</i> |
| EW MonitorPLS NBD AHR H35442 | 97404-H35442 | \$ 1,066.00 | 10% | <i>\$966.60</i> |
| EW MonitorPLS NBD AHR H35443 | 97404-H35443 | \$ 2,651.00 | 10% | <i>\$2,403.79</i> |
| EW MonitorPLS NBD AHR H35444 | 97404-H35444 | \$ 2,792.00 | 10% | <i>\$2,531.65</i> |
| EW MonitorPLS NBD AHR H35445 | 97404-H35445 | \$ 2,532.00 | 10% | <i>\$2,295.89</i> |
| EW MonitorPLS NBD AHR H35446 | 97404-H35446 | \$ 2,483.00 | 10% | <i>\$2,251.46</i> |
| EW MonitorPLS NBD AHR H35447 | 97404-H35447 | \$ 2,824.00 | 10% | <i>\$2,560.66</i> |
| EW MonitorPLS NBD AHR H35448 | 97404-H35448 | \$ 2,736.00 | 10% | <i>\$2,480.87</i> |
| EW MonitorPLS NBD AHR H35449 | 97404-H35449 | \$ 2,157.00 | 10% | <i>\$1,955.86</i> |
| EW MonitorPLS NBD AHR H35450 | 97404-H35450 | \$ 2,282.00 | 10% | <i>\$2,069.20</i> |
| EW MonitorPLS NBD AHR H35451 | 97404-H35451 | \$ 4,629.00 | 10% | <i>\$4,197.35</i> |

| | | | | |
|--|-------------------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR H35452 | 97404-H35452 | \$ 4,629.00 | 10% | <i>\$4,197.35</i> |
| EW MonitorPLS NBD AHR H35453 | 97404-H35453 | \$ 2,792.00 | 10% | <i>\$2,531.65</i> |
| EW MonitorPLS NBD AHR H35454 | 97404-H35454 | \$ 2,651.00 | 10% | <i>\$2,403.79</i> |
| EW MonitorPLS NBD AHR H35455 | 97404-H35455 | \$ 1,170.00 | 10% | <i>\$1,060.90</i> |
| EW MonitorPLS NBD AHR H35456 | 97404-H35456 | \$ 1,308.00 | 10% | <i>\$1,186.03</i> |
| EW MonitorPLS NBD AHR H35457 | 97404-H35457 | \$ 1,247.00 | 10% | <i>\$1,130.72</i> |
| EW MonitorPLS NBD AHR H35458 | 97404-H35458 | \$ 1,311.00 | 10% | <i>\$1,188.75</i> |
| EW MonitorPLS NBD AHR H35471 | 97404-H35471 | \$ 1,170.00 | 10% | <i>\$1,060.90</i> |
| EW MonitorPLS NBD AHR H35600 | 97404-H35600 | \$ 817.00 | 10% | <i>\$740.81</i> |
| EW MonitorPLS NBD AHR H35601 | 97404-H35601 | \$ 817.00 | 10% | <i>\$740.81</i> |
| EW MonitorPLS NBD AHR H35602 | 97404-H35602 | \$ 1,015.00 | 10% | <i>\$920.35</i> |
| EW MonitorPLS NBD AHR H35603 | 97404-H35603 | \$ 1,015.00 | 10% | <i>\$920.35</i> |
| EW MonitorPLS NBD AHR H35604 | 97404-H35604 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H35605 | 97404-H35605 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLS NBD AHR H35606 | 97404-H35606 | \$ 1,151.00 | 10% | <i>\$1,043.67</i> |
| EW MonitorPLS NBD AHR H35607 | 97404-H35607 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW MonitorPLS NBD AHR ISW-24W-4X | 97404-ISW- 24W-4X | \$ 1,099.00 | 10% | <i>\$996.52</i> |
| EW MonitorPLS NBD AHR ISW-4W-4WS-4X | 97404-ISW-4W- 4WS-4X | \$ 866.00 | 10% | <i>\$785.25</i> |
| EW MonitorPLUS NBD AHR- MS128 | 97404- MSM128 | \$ 2,529.00 | 10% | <i>\$2,293.17</i> |
| EW MonitorPLS NBD AHR- MSM48C | 97404- MSM48C | \$ 1,636.00 | 10% | <i>\$1,483.44</i> |
| EW MonitorPLS NBD AHR- R100-8T | 97404-R100-8T | \$ 715.00 | 10% | <i>\$648.33</i> |

| | | | | |
|--|---------------------------------|--------------|-----|-------------|
| EW MonitorPLS NBD AHR SLX9150-48XT-DC-F | 97404- SLX9150- 48XT-DC-F | \$ 2,746.00 | 10% | \$2,489.94 |
| EW MonitorPLS NBD AHR SLX9150-48XT-DC-R | 97404- SLX9150- 48XT-DC-R | \$ 2,999.00 | 10% | \$2,719.34 |
| EW MonitorPLS NBD AHR SLX9150-48Y-DC-F | 97404- SLX9150-48Y- DC-F | \$ 2,661.00 | 10% | \$2,412.86 |
| EW MonitorPLS NBD AHR SLX9150-48Y-DC-R | 97404- SLX9150-48Y- DC-R | \$ 2,905.00 | 10% | \$2,634.11 |
| EW MonitorPLS NBD AHR SLX9740-40C | 97404- SLX9740-40C | \$ 9,339.00 | 10% | \$8,468.14 |
| EW MonitorPLS NBD AHR SLX9740-40C-AC-F | 97404- SLX9740-40C- AC-F | \$ 9,339.00 | 10% | \$8,468.14 |
| EW MonitorPLS NBD AHR SLX9740-40C-AC-R | 97404- SLX9740-40C- AC-R | \$ 9,339.00 | 10% | \$8,468.14 |
| EW MonitorPLS NBD AHR SLX9740-40C-DC-F | 97404- SLX9740-40C- DC-F | \$ 9,339.00 | 10% | \$8,468.14 |
| EW MonitorPLS NBD AHR SLX9740-80C | 97404- SLX9740-80C | \$ 17,013.00 | 10% | \$15,426.54 |
| EW MonitorPLS NBD AHR SLX9740-80C-AC-F | 97404- SLX9740-80C- AC-F | \$ 17,013.00 | 10% | \$15,426.54 |
| EW MonitorPLS NBD AHR SLX9740-80C-AC-R | 97404- SLX9740-80C- AC-R | \$ 17,013.00 | 10% | \$15,426.54 |
| EW MonitorPLS NBD AHR SLX9740-80C-DC-F | 97404- SLX9740-80C- DC-F | \$ 17,013.00 | 10% | \$15,426.54 |
| EW MonitorPLS NBD AHR V300-8P-2X | 97404-V300- 8P-2X | \$ 503.00 | 10% | \$456.10 |
| EW MonitorPLS NBD AHR V300-8T-2X | 97404-V300- 8T-2X | \$ 474.00 | 10% | \$429.80 |
| EW MonitorPLS NBD AHR V300HT-8P-2X | 97404-V300HT- 8P-2X | \$ 608.00 | 10% | \$551.30 |

| | | | | |
|--|---|-------------|-----|------------|
| EW MonitorPLS NBD AHR V300HT-8T-2X | 97404-V300HT- 8T-2X | \$ 527.00 | 10% | \$477.86 |
| EW MonitorPLS NBD AHR- VIM-SS | 97404-VIM-SS | \$ 378.00 | 10% | \$342.75 |
| EW MonitorPLS NBD AHRVIMSSV80 | 97404-VIM- SSV80 | \$ 475.00 | 10% | \$430.71 |
| EW MonitorPLS NBD AHR- VIM2-SS | 97404-VIM2- SS | \$ 381.00 | 10% | \$345.47 |
| EW MonitorPLS NBD AHRVIM2SS128 | 97404-VIM2- SS128 | \$ 710.00 | 10% | \$643.79 |
| EW MonitorPLS NBD AHR- VIM2-V80 | 97404-VIM2- V80 | \$ 757.00 | 10% | \$686.41 |
| EW MonitorPLS NBD AHRVIM210G4X | 97404- VIM210G4X | \$ 1,108.00 | 10% | \$1,004.68 |
| EW MonPLS NBD AHR VSP4900-12MXU-12XE | 97404- VSP4900- 12MXU-12XE | \$ 1,401.00 | 10% | \$1,270.36 |
| EW MonPLS NBD AHR VSP4900-12MXU-12XE-B1 | 97404- VSP4900- 12MXU-12XE- B1 | \$ 1,401.00 | 10% | \$1,270.36 |
| EW MonitorPLS NBD AHR VSP4900-24S | 97404- VSP4900-24S | \$ 998.00 | 10% | \$904.94 |
| EW MonitorPLS NBD AHR VSP4900-24S-B3 | 97404- VSP4900-24S- B3 | \$ 998.00 | 10% | \$904.94 |
| EW MonitorPLS NBD AHR VSP4900-24XE | 97404- VSP4900- 24XE | \$ 1,401.00 | 10% | \$1,270.36 |
| EW MonitorPLS NBD AHR VSP4900-24XE-B3 | 97404- VSP4900- 24XE-B3 | \$ 1,401.00 | 10% | \$1,270.36 |
| EW MonitorPLS NBD AHR X435-24P-4S | 97404-X435- 24P-4S | \$ 586.00 | 10% | \$531.36 |
| EW MonitorPLS NBD AHR X435-24T-4S | 97404-X435- 24T-4S | \$ 506.00 | 10% | \$458.82 |
| EW MonitorPLS NBD AHR X435-8P-2T-W | 97404-X435- 8P-2T-W | \$ 506.00 | 10% | \$458.82 |
| EW MonitorPLS NBD AHR X435-8P-4S | 97404-X435- 8P-4S | \$ 496.00 | 10% | \$449.75 |
| EW MonitorPLS NBD AHR X435-8T-4S | 97404-X435- 8T-4S | \$ 479.00 | 10% | \$434.33 |

| | | | | |
|---------------------------------------|-----------------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR-X460-24P | 97404-X460-24P | \$ 1,580.00 | 10% | <i>\$1,432.67</i> |
| EW MonitorPLS NBD AHR-X460-24T | 97404-X460-24T | \$ 1,321.00 | 10% | <i>\$1,197.82</i> |
| EW MonitorPLS NBD AHR-X460-24 | 97404-X460-24TDC | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW MonitorPLS NBD AHR-X460-24X | 97404-X460-24X | \$ 1,806.00 | 10% | <i>\$1,637.59</i> |
| EW MonitorPLS NBD AHR-X460-24 | 97404-X460-24XDC | \$ 1,968.00 | 10% | <i>\$1,784.48</i> |
| EW MonitorPLS NBD AHR-X460-48P | 97404-X460-48P | \$ 1,806.00 | 10% | <i>\$1,637.59</i> |
| EW MonitorPLS NBD AHR-X460-48T | 97404-X460-48T | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW MonitorPLS NBD AHR-X46048 | 97404-X460-48TDC | \$ 1,932.00 | 10% | <i>\$1,751.84</i> |
| EW MonitorPLS NBD AHR-X460-48X | 97404-X460-48X | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW MonitorPLS NBD AHR-X46048 | 97404-X460-48XDC | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW MonitorPLS NBD AHR X465-24MU | 97404-X465-24MU | \$ 1,528.00 | 10% | <i>\$1,385.51</i> |
| EW MonitorPLS NBD AHR X465-24S | 97404-X465-24S | \$ 998.00 | 10% | <i>\$904.94</i> |
| EW MonitorPLS NBD AHR X465-24S-B3 | 97404-X465-24S-B3 | \$ 998.00 | 10% | <i>\$904.94</i> |
| EW MonitorPLS NBD AHR X465-24W | 97404-X465-24W | \$ 998.00 | 10% | <i>\$904.94</i> |
| EW MonitorPLS NBD AHR X465-24XE | 97404-X465-24XE | \$ 1,401.00 | 10% | <i>\$1,270.36</i> |
| EW MonitorPLS NBD AHR X465-24XE-B3 | 97404-X465-24XE-B3 | \$ 1,401.00 | 10% | <i>\$1,270.36</i> |
| EW MonitorPLS NBD AHR X465-48P | 97404-X465-48P | \$ 1,170.00 | 10% | <i>\$1,060.90</i> |
| EW MonitorPLS NBD AHR X465-48T | 97404-X465-48T | \$ 1,149.00 | 10% | <i>\$1,041.86</i> |
| EW MonitorPLS NBD AHR X465-48W | 97404-X465-48W | \$ 1,337.00 | 10% | <i>\$1,212.32</i> |
| EW MonitorPLS NBD AHR X465i-48W | 97404-X465i-48W | \$ 1,510.00 | 10% | <i>\$1,369.19</i> |
| EW MonitorPLS NBD AHR X465i-48W-B1-S1 | 97404-X465i-48W-B1-S1 | \$ 1,510.00 | 10% | <i>\$1,369.19</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW MonitorPLS NBD AHR X465i-48W-B2-S1 | 97404-X465i- 48W-B2-S1 | \$ 1,510.00 | 10% | <i>\$1,369.19</i> |
| EW MonitorPLS NBD AHR- X480-24X | 97404-X480- 24X | \$ 1,957.00 | 10% | <i>\$1,774.51</i> |
| EW MonitorPLUS NBD AHR- X480T | 97404-X480- 48T | \$ 1,957.00 | 10% | <i>\$1,774.51</i> |
| EW MonitorPLS NBD AHR- X48048 | 97404-X480- 48X | \$ 2,388.00 | 10% | <i>\$2,165.32</i> |
| EW MonitorPLS NBD AHR X695-48Y-8C | 97404-X695- 48Y-8C | \$ 2,523.00 | 10% | <i>\$2,287.73</i> |
| EW MonitorPLS NBD AHR XA1440 | 97404-XA1440 | \$ 613.00 | 10% | <i>\$555.84</i> |
| EW MonitorPLS NBD AHR XA1480 | 97404-XA1480 | \$ 687.00 | 10% | <i>\$622.94</i> |
| EW MonitorPLS NBD AHR- XGM3-2SF | 97404-XGM3- 2SF | \$ 475.00 | 10% | <i>\$430.71</i> |
| EW MonitorPLS NBD AHR XR600 | 97404-XR600 | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HR AHR 1130C | 97407-1130C | \$ 2,043.00 | 6% | <i>\$1,934.82</i> |
| EW MonitorPLS 4HR AHR- 16119 | 97407-16119 | \$ 591.00 | 10% | <i>\$535.89</i> |
| EW MonitorPLS 4HR AHR- 16120 | 97407-16120 | \$ 677.00 | 10% | <i>\$613.87</i> |
| EW MonitorPLS 4HR AHR- 16126 | 97407-16126 | \$ 591.00 | 10% | <i>\$535.89</i> |
| EW MonitorPLS 4HR AHR- 16127 | 97407-16127 | \$ 619.00 | 10% | <i>\$561.28</i> |
| EW MonitorPLS 4HR AHR- 16172 | 97407-16172 | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW MonitorPLS 4HR AHR 16172T | 97407-16172T | \$ 1,227.00 | 10% | <i>\$1,112.58</i> |
| EW MonitorPLS 4HR AHR- 16173 | 97407-16173 | \$ 1,124.00 | 10% | <i>\$1,019.19</i> |
| EW MonitorPLS 4HR AHR 16173T | 97407-16173T | \$ 1,241.00 | 10% | <i>\$1,125.28</i> |
| EW MonitorPLS 4HR AHR- 16174 | 97407-16174 | \$ 1,293.00 | 10% | <i>\$1,172.43</i> |
| EW MonitorPLS 4HR AHR- 16175 | 97407-16175 | \$ 1,360.00 | 10% | <i>\$1,233.18</i> |
| EW MonitorPLS 4HR AHR- 16176 | 97407-16176 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-16177 | 97407-16177 | \$ 1,219.00 | 10% | <i>\$1,105.33</i> |
| EW MonitorPLS 4HR AHR 16177T | 97407-16177T | \$ 1,440.00 | 10% | <i>\$1,305.72</i> |
| EW MonitorPLS 4HR AHR-16178 | 97407-16178 | \$ 1,516.00 | 10% | <i>\$1,374.63</i> |
| EW MonitorPLS 4HR AHR-16179 | 97407-16179 | \$ 1,537.00 | 10% | <i>\$1,393.67</i> |
| EW MonitorPLS 4HR AHR 16179T | 97407-16179T | \$ 1,692.00 | 10% | <i>\$1,534.22</i> |
| EW MonitorPLS 4HR AHR-16301T | 97407-16301T | \$ 2,703.00 | 10% | <i>\$2,450.95</i> |
| EW MonitorPLS 4HR AHR-16303T | 97407-16303T | \$ 2,703.00 | 10% | <i>\$2,450.95</i> |
| EW MonitorPLS 4HR AHR-16304T | 97407-16304T | \$ 3,379.00 | 10% | <i>\$3,063.91</i> |
| EW MonitorPLS 4HR AHR-16401T | 97407-16401T | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW MonitorPLS 4HR AHR-16402T | 97407-16402T | \$ 2,209.00 | 10% | <i>\$2,003.01</i> |
| EW MonitorPLS 4HR AHR-16403T | 97407-16403T | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW MonitorPLS 4HR AHR-16404T | 97407-16404T | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW MonitorPLS 4HR AHR-16405T | 97407-16405T | \$ 2,452.00 | 10% | <i>\$2,223.35</i> |
| EW MonitorPLS 4HR AHR-16406T | 97407-16406T | \$ 3,010.00 | 10% | <i>\$2,729.32</i> |
| EW MonitorPLS 4HR AHR-16431 | 97407-16431 | \$ 2,131.00 | 10% | <i>\$1,932.28</i> |
| EW MonitorPLS 4HR AHR-16432 | 97407-16432 | \$ 2,268.00 | 10% | <i>\$2,056.51</i> |
| EW MonitorPLS 4HR AHR-16440 | 97407-16440 | \$ 1,602.00 | 10% | <i>\$1,452.61</i> |
| EW MonitorPLS 4HR AHR-16441 | 97407-16441 | \$ 1,506.00 | 10% | <i>\$1,365.57</i> |
| EW MonitorPLS 4HR AHR-16442 | 97407-16442 | \$ 619.00 | 10% | <i>\$561.28</i> |
| EW MonitorPLS 4HR AHR-16444 | 97407-16444 | \$ 440.00 | 10% | <i>\$398.97</i> |
| EW MonitorPLS 4HR AHR-16501 | 97407-16501 | \$ 946.00 | 10% | <i>\$857.79</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-16501T | 97407-16501T | \$ 1,005.00 | 10% | <i>\$911.28</i> |
| EW MonitorPLS 4HR AHR-16502 | 97407-16502 | \$ 1,043.00 | 10% | <i>\$945.74</i> |
| EW MonitorPLS 4HR AHR-16502T | 97407-16502T | \$ 1,102.00 | 10% | <i>\$999.24</i> |
| EW MonitorPLS 4HR AHR-16503 | 97407-16503 | \$ 992.00 | 10% | <i>\$899.50</i> |
| EW MonitorPLS 4HR AHR-16503T | 97407-16503T | \$ 1,056.00 | 10% | <i>\$957.53</i> |
| EW MonitorPLS 4HR AHR-16504 | 97407-16504 | \$ 1,139.00 | 10% | <i>\$1,032.79</i> |
| EW MonitorPLS 4HR AHR-16504T | 97407-16504T | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-16505 | 97407-16505 | \$ 1,166.00 | 10% | <i>\$1,057.27</i> |
| EW MonitorPLS 4HR AHR-16505T | 97407-16505T | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HR AHR-16506 | 97407-16506 | \$ 1,396.00 | 10% | <i>\$1,265.82</i> |
| EW MonitorPLS 4HR AHR-16506T | 97407-16506T | \$ 1,557.00 | 10% | <i>\$1,411.81</i> |
| EW MonitorPLS 4HR AHR-16507 | 97407-16507 | \$ 1,344.00 | 10% | <i>\$1,218.67</i> |
| EW MonitorPLS 4HR AHR-16507T | 97407-16507T | \$ 1,467.00 | 10% | <i>\$1,330.20</i> |
| EW MonitorPLS 4HR AHR-16508 | 97407-16508 | \$ 1,498.00 | 10% | <i>\$1,358.31</i> |
| EW MonitorPLS 4HR AHR-16508T | 97407-16508T | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW MonitorPLS 4HR AHR-16509 | 97407-16509 | \$ 1,498.00 | 10% | <i>\$1,358.31</i> |
| EW MonitorPLS 4HR AHR-16509T | 97407-16509T | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW MonitorPLS 4HR AHR-16510 | 97407-16510 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW MonitorPLS 4HR AHR-16510T | 97407-16510T | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW MonitorPLS 4HR AHR-16513 | 97407-16513 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS 4HR AHR-16514 | 97407-16514 | \$ 1,620.00 | 10% | <i>\$1,468.94</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-16515 | 97407-16515 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS 4HR AHR-16516 | 97407-16516 | \$ 873.00 | 10% | <i>\$791.59</i> |
| EW MonitorPLS 4HR AHR-16517 | 97407-16517 | \$ 1,024.00 | 10% | <i>\$928.51</i> |
| EW MonitorPLS 4HR AHR-16518 | 97407-16518 | \$ 989.00 | 10% | <i>\$896.78</i> |
| EW MonitorPLS 4HR AHR-16519 | 97407-16519 | \$ 1,056.00 | 10% | <i>\$957.53</i> |
| EW MonitorPLS 4HR AHR-16520 | 97407-16520 | \$ 1,234.00 | 10% | <i>\$1,118.93</i> |
| EW MonitorPLUS 4HR AHR-16530 | 97407-16530 | \$ 959.00 | 10% | <i>\$869.57</i> |
| EW MonitorPLUS 4HR AHR-16531 | 97407-16531 | \$ 1,026.00 | 10% | <i>\$930.33</i> |
| EW MonitorPLUS 4HR AHR-16531T | 97407-16531T | \$ 1,043.00 | 10% | <i>\$945.74</i> |
| EW MonitorPLUS 4HR AHR-16532 | 97407-16532 | \$ 1,026.00 | 10% | <i>\$930.33</i> |
| EW MonitorPLUS 4HR AHR-16532T | 97407-16532T | \$ 1,043.00 | 10% | <i>\$945.74</i> |
| EW MonitorPLUS 4HR AHR-16533 | 97407-16533 | \$ 1,117.00 | 10% | <i>\$1,012.84</i> |
| EW MonitorPLUS 4HR AHR-16533T | 97407-16533T | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW MonitorPLUS 4HR AHR-16534 | 97407-16534 | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW MonitorPLUS 4HR AHR-16535 | 97407-16535 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW MonitorPLUS 4HR AHR-16535A | 97407-16535A | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW MonitorPLUS 4HR AHR-16535T | 97407-16535T | \$ 1,392.00 | 10% | <i>\$1,262.20</i> |
| EW MonitorPLUS 4HR AHR-16536 | 97407-16536 | \$ 961.00 | 10% | <i>\$871.39</i> |
| EW MonitorPLUS 4HR AHR-16537 | 97407-16537 | \$ 1,050.00 | 10% | <i>\$952.09</i> |
| EW MonitorPLUS 4HR AHR-16538 | 97407-16538 | \$ 1,119.00 | 10% | <i>\$1,014.65</i> |
| EW MonitorPLUS 4HR AHR-16538T | 97407-16538T | \$ 1,277.00 | 10% | <i>\$1,157.92</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLUS 4HR AHR-16539 | 97407-16539 | \$ 1,238.00 | 10% | <i>\$1,122.56</i> |
| EW MonitorPLUS 4HR AHR-16540 | 97407-16540 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLUS 4HR AHR-16541 | 97407-16541 | \$ 858.00 | 10% | <i>\$777.99</i> |
| EW MonitorPLS 4HR AHR 16560 | 97407-16560 | \$ 764.00 | 10% | <i>\$692.76</i> |
| EW MonitorPLS 4HR AHR 16561 | 97407-16561 | \$ 798.00 | 10% | <i>\$723.59</i> |
| EW MonitorPLS 4HR AHR 16562 | 97407-16562 | \$ 824.00 | 10% | <i>\$747.16</i> |
| EW MonitorPLS 4HR AHR 16563 | 97407-16563 | \$ 871.00 | 10% | <i>\$789.78</i> |
| EW MonitorPLS 4HR AHR 16564 | 97407-16564 | \$ 919.00 | 10% | <i>\$833.30</i> |
| EW MonitorPLS 4HR AHR 16565 | 97407-16565 | \$ 1,049.00 | 10% | <i>\$951.18</i> |
| EW MonitorPLS 4HR AHR 16566 | 97407-16566 | \$ 730.00 | 10% | <i>\$661.93</i> |
| EW MonitorPLS 4HR AHR 16567 | 97407-16567 | \$ 776.00 | 10% | <i>\$703.64</i> |
| EW MonitorPLS 4HR AHR 16568 | 97407-16568 | \$ 764.00 | 10% | <i>\$692.76</i> |
| EW MonitorPLS 4HR AHR 16569 | 97407-16569 | \$ 811.00 | 10% | <i>\$735.37</i> |
| EW MonitorPLS 4HR AHR 16570 | 97407-16570 | \$ 824.00 | 10% | <i>\$747.16</i> |
| EW MonitorPLS 4HR AHR 16571 | 97407-16571 | \$ 919.00 | 10% | <i>\$833.30</i> |
| EW MonitorPLS 4HR AHR-16701 | 97407-16701 | \$ 1,229.00 | 10% | <i>\$1,114.40</i> |
| EW MonitorPLS 4HR AHR-16702 | 97407-16702 | \$ 1,478.00 | 10% | <i>\$1,340.18</i> |
| EW MonitorPLS 4HR AHR-16703 | 97407-16703 | \$ 1,389.00 | 10% | <i>\$1,259.48</i> |
| EW MonitorPLS 4HR AHR 16703T | 97407-16703T | \$ 1,541.00 | 10% | <i>\$1,397.30</i> |
| EW MonitorPLUS 4HR AHR-16704 | 97407-16704 | \$ 1,664.00 | 10% | <i>\$1,508.83</i> |
| EW MonitorPLS 4HR AHR 16704T | 97407-16704T | \$ 1,540.00 | 10% | <i>\$1,396.40</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-16705 | 97407-16705 | \$ 1,478.00 | 10% | <i>\$1,340.18</i> |
| EW MonitorPLS 4HR AHR 16705T | 97407-16705T | \$ 1,636.00 | 10% | <i>\$1,483.44</i> |
| EW MonitorPLS 4HR AHR-16706 | 97407-16706 | \$ 1,959.00 | 10% | <i>\$1,776.32</i> |
| EW MonitorPLS 4HR AHR 16706T | 97407-16706T | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW MonitorPLS 4HR AHR-16710 | 97407-16710 | \$ 479.00 | 10% | <i>\$434.33</i> |
| EW MonitorPLS 4HR AHR 16710T | 97407-16710T | \$ 527.00 | 10% | <i>\$477.86</i> |
| EW MonitorPLS 4HR AHR-16711 | 97407-16711 | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW MonitorPLS 4HR AHR 16711T | 97407-16711T | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW MonitorPLS 4HR AHR-16712 | 97407-16712 | \$ 382.00 | 10% | <i>\$346.38</i> |
| EW MonitorPLS 4HR AHR 16712T | 97407-16712T | \$ 413.00 | 10% | <i>\$374.49</i> |
| EW MonitorPLS 4HR AHR-16713 | 97407-16713 | \$ 298.00 | 10% | <i>\$270.21</i> |
| EW MonitorPLS 4HR AHR 16713T | 97407-16713T | \$ 339.00 | 10% | <i>\$307.39</i> |
| EW MonitorPLS 4HR AHR-16715 | 97407-16715 | \$ 335.00 | 10% | <i>\$303.76</i> |
| EW MonitorPLS 4HR AHR 16715T | 97407-16715T | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW MonitorPLS 4HR AHR-16716 | 97407-16716 | \$ 1,192.00 | 10% | <i>\$1,080.85</i> |
| EW MonitorPLS 4HR AHR 16716T | 97407-16716T | \$ 1,319.00 | 10% | <i>\$1,196.00</i> |
| EW MonitorPLS 4HR AHR-16717 | 97407-16717 | \$ 1,334.00 | 10% | <i>\$1,209.60</i> |
| EW MonitorPLS 4HR AHR-16718 | 97407-16718 | \$ 1,229.00 | 10% | <i>\$1,114.40</i> |
| EW MonitorPLS 4HR AHR-16719 | 97407-16719 | \$ 1,368.00 | 10% | <i>\$1,240.43</i> |
| EW MonitorPLS 4HR AHR 16720 | 97407-16720 | \$ 1,727.00 | 10% | <i>\$1,565.96</i> |
| EW MonitorPLS 4HR AHR 16720T | 97407-16720T | \$ 2,012.00 | 10% | <i>\$1,824.38</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR 16756 | 97407-16756 | \$ 1,513.00 | 10% | <i>\$1,371.91</i> |
| EW MonitorPLS 4HR AHR 16756T | 97407-16756T | \$ 1,785.00 | 10% | <i>\$1,618.55</i> |
| EW MonitorPLS 4HR AHR 16757 | 97407-16757 | \$ 1,474.00 | 10% | <i>\$1,336.55</i> |
| EW MonitorPLS 4HR AHR 16757T | 97407-16757T | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS 4HR AHR 16790 | 97407-16790 | \$ 1,958.00 | 10% | <i>\$1,775.42</i> |
| EW MonitorPLS 4HR AHR 16791 | 97407-16791 | \$ 2,527.00 | 10% | <i>\$2,291.36</i> |
| EW MonitorPLS 4HR AHR- 17101 | 97407-17101 | \$ 3,654.00 | 10% | <i>\$3,313.26</i> |
| EW MonitorPLS 4HR AHR- 17101T | 97407-17101T | \$ 4,595.00 | 10% | <i>\$4,166.52</i> |
| EW MonitorPLS 4HR AHR- 17102 | 97407-17102 | \$ 3,654.00 | 10% | <i>\$3,313.26</i> |
| EW MonitorPLS 4HR AHR- 17102T | 97407-17102T | \$ 4,595.00 | 10% | <i>\$4,166.52</i> |
| EW MonitorPLS 4HR AHR- 17103 | 97407-17103 | \$ 2,746.00 | 10% | <i>\$2,489.94</i> |
| EW MonitorPLS 4HR AHR- 17103C | 97407-17103C | \$ 2,665.00 | 10% | <i>\$2,416.49</i> |
| EW MonitorPLS 4HR AHR- 17103T | 97407-17103T | \$ 3,434.00 | 10% | <i>\$3,113.78</i> |
| EW MonitorPLS 4HR AHR- 17104 | 97407-17104 | \$ 2,746.00 | 10% | <i>\$2,489.94</i> |
| EW MonitorPLS 4HR AHR- 17104T | 97407-17104T | \$ 3,434.00 | 10% | <i>\$3,113.78</i> |
| EW MonitorPLS 4HR AHR- 17121 | 97407-17121 | \$ 855.00 | 10% | <i>\$775.27</i> |
| EW MonitorPLS 4HR AHR- 17122 | 97407-17122 | \$ 613.00 | 10% | <i>\$555.84</i> |
| EW MonitorPLS 4HR AHR- 17200 | 97407-17200 | \$ 5,383.00 | 10% | <i>\$4,881.04</i> |
| EW MonitorPLS 4HR AHR- 17200T | 97407-17200T | \$ 6,087.00 | 10% | <i>\$5,519.39</i> |
| EW MonitorPLS 4HR AHR- 17201 | 97407-17201 | \$ 5,383.00 | 10% | <i>\$4,881.04</i> |
| EW MonitorPLS 4HR AHR- 17201T | 97407-17201T | \$ 6,087.00 | 10% | <i>\$5,519.39</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-17202 | 97407-17202 | \$ 5,383.00 | 10% | <i>\$4,881.04</i> |
| EW MonitorPLS 4HR AHR-17202T | 97407-17202T | \$ 6,087.00 | 10% | <i>\$5,519.39</i> |
| EW MonitorPLS 4HR AHR-17203 | 97407-17203 | \$ 5,453.00 | 10% | <i>\$4,944.51</i> |
| EW MonitorPLS 4HR AHR-17203T | 97407-17203T | \$ 6,165.00 | 10% | <i>\$5,590.11</i> |
| EW MonitorPLS 4HR AHR-17204 | 97407-17204 | \$ 5,453.00 | 10% | <i>\$4,944.51</i> |
| EW MonitorPLS 4HR AHR-17204T | 97407-17204T | \$ 6,165.00 | 10% | <i>\$5,590.11</i> |
| EW MonitorPLS 4HR AHR-17205 | 97407-17205 | \$ 5,421.00 | 10% | <i>\$4,915.49</i> |
| EW MonitorPLS 4HR AHR-17205T | 97407-17205T | \$ 6,127.00 | 10% | <i>\$5,555.66</i> |
| EW MonitorPLS 4HR AHR-17206 | 97407-17206 | \$ 5,421.00 | 10% | <i>\$4,915.49</i> |
| EW MonitorPLS 4HR AHR-17206T | 97407-17206T | \$ 6,127.00 | 10% | <i>\$5,555.66</i> |
| EW MonitorPLS 4HR AHR-17300 | 97407-17300 | \$ 3,825.00 | 10% | <i>\$3,468.32</i> |
| EW MonitorPLS 4HR AHR-17310 | 97407-17310 | \$ 3,532.00 | 10% | <i>\$3,202.64</i> |
| EW MonitorPLS 4HR AHR 17350 | 97407-17350 | \$ 3,695.00 | 10% | <i>\$3,350.44</i> |
| EW MonitorPLS 4HR AHR 17360 | 97407-17360 | \$ 4,390.00 | 10% | <i>\$3,980.63</i> |
| EW MonitorPLS 4HR AHR 17401 | 97407-17401 | \$ 1,140.00 | 10% | <i>\$1,033.70</i> |
| EW MonitorPLS 4HR AHR 17401G | 97407-17401G | \$ 1,192.00 | 10% | <i>\$1,080.85</i> |
| EW MonitorPLS 4HR AHR 17401T | 97407-17401T | \$ 1,192.00 | 10% | <i>\$1,080.85</i> |
| EW MonitorPLS 4HR AHR 17402 | 97407-17402 | \$ 1,282.00 | 10% | <i>\$1,162.45</i> |
| EW MonitorPLS 4HR AHR 17402G | 97407-17402G | \$ 1,289.00 | 10% | <i>\$1,168.80</i> |
| EW MonitorPLS 4HR AHR 17402T | 97407-17402T | \$ 1,289.00 | 10% | <i>\$1,168.80</i> |
| EW MonitorPLS 4HR AHR 17403 | 97407-17403 | \$ 1,339.00 | 10% | <i>\$1,214.14</i> |

| | | | | |
|------------------------------------|---------------------|--------------|-----|------------|
| EW MonitorPLS 4HR AHR 17404 | 97407-17404 | \$ 1,019.00 | 10% | \$923.98 |
| EW MonitorPLS 4HR AHR 17405 | 97407-17405 | \$ 1,059.00 | 10% | \$960.25 |
| EW MonitorPLS 4HR AHR 17700 | 97407-17700 | \$ 6,475.00 | 10% | \$5,871.21 |
| EW MonitorPLS 4HR AHR- 17701 | 97407-17701 | \$ 5,519.00 | 10% | \$5,004.35 |
| EW MonitorPLS 4HR AHR- 17702 | 97407-17702 | \$ 5,519.00 | 10% | \$5,004.35 |
| EW MonitorPLS 4HR AHR- 17703 | 97407-17703 | \$ 6,029.00 | 10% | \$5,466.80 |
| EW MonitorPLS 4HR AHR- 17704 | 97407-17704 | \$ 6,029.00 | 10% | \$5,466.80 |
| EW MonitorPLS 4HR AHR- 17705 | 97407-17705 | \$ 5,556.00 | 10% | \$5,037.90 |
| EW MonitorPLS 4HR AHR- 17706 | 97407-17706 | \$ 5,556.00 | 10% | \$5,037.90 |
| EW MonitorPLS 4HR AHR 17800 | 97407-17800 | \$ 6,535.00 | 10% | \$5,925.61 |
| EW MonitorPLS 4HR AHR 17810 | 97407-17810 | \$ 5,368.00 | 10% | \$4,867.43 |
| EW MonitorPLS 4HR AHR 18101 | 97407-18101 | \$ 506.00 | 10% | \$458.82 |
| EW MonitorPLS 4HR AHR 18102 | 97407-18102 | \$ 584.00 | 10% | \$529.54 |
| EW MonitorPLS 4HR AHR 18103 | 97407-18103 | \$ 621.00 | 10% | \$563.09 |
| EW MonitorPLS 4HR AHR 18104 | 97407-18104 | \$ 795.00 | 10% | \$720.87 |
| EW MonitorPLS 4HR AHR 18104-6PK | 97407-18104- 6PK | \$ 4,774.00 | 10% | \$4,328.82 |
| EW MonitorPLS 4HR AHR- 30135 | 97407-30135 | \$ 2,202.00 | 10% | \$1,996.66 |
| EW MonitorPLS 4HR AHR 30136 | 97407-30136 | \$ 8,245.00 | 10% | \$7,476.15 |
| EW MonitorPLS 4HR AHR 30137 | 97407-30137 | \$ 1,879.00 | 10% | \$1,703.78 |
| EW MonitorPLS 4HR AHR 30138 | 97407-30138 | \$ 5,896.00 | 10% | \$5,346.20 |
| EW MonitorPLS 4HR AHR 30139 | 97407-30139 | \$ 10,312.00 | 10% | \$9,350.41 |

| | | | | |
|--------------------------------|-------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR 30912 | 97407-30912 | \$ 249.00 | 10% | \$225.78 |
| EW MonitorPLS 4HR AHR 30913 | 97407-30913 | \$ 249.00 | 10% | \$225.78 |
| EW MonitorPLS 4HR AHR 31012 | 97407-31012 | \$ 317.00 | 10% | \$287.44 |
| EW MonitorPLS 4HR AHR 31013 | 97407-31013 | \$ 317.00 | 10% | \$287.44 |
| EW MonitorPLS 4HR AHR 31014 | 97407-31014 | \$ 317.00 | 10% | \$287.44 |
| EW MonitorPLS 4HR AHR 31015 | 97407-31015 | \$ 317.00 | 10% | \$287.44 |
| EW MonitorPLS 4HR AHR 31016 | 97407-31016 | \$ 497.00 | 10% | \$450.65 |
| EW MonitorPLS 4HR AHR 31017 | 97407-31017 | \$ 497.00 | 10% | \$450.65 |
| EW MonitorPLS 4HR AHR 31018 | 97407-31018 | \$ 542.00 | 10% | \$491.46 |
| EW MonitorPLS 4HR AHR 31019 | 97407-31019 | \$ 542.00 | 10% | \$491.46 |
| EW MonitorPLS 4HR AHR 31025 | 97407-31025 | \$ 235.00 | 10% | \$213.09 |
| EW MonitorPLS 4HR AHR 31026 | 97407-31026 | \$ 235.00 | 10% | \$213.09 |
| EW MonitorPLS 4HR AHR 31028 | 97407-31028 | \$ 229.00 | 10% | \$207.65 |
| EW MonitorPLS 4HR AHR 31029 | 97407-31029 | \$ 229.00 | 10% | \$207.65 |
| EW MonitorPLS 4HR AHR 31031 | 97407-31031 | \$ 250.00 | 10% | \$226.69 |
| EW MonitorPLS 4HR AHR 31032 | 97407-31032 | \$ 250.00 | 10% | \$226.69 |
| EW MonitorPLS 4HR AHR 31034 | 97407-31034 | \$ 317.00 | 10% | \$287.44 |
| EW MonitorPLS 4HR AHR 31035 | 97407-31035 | \$ 317.00 | 10% | \$287.44 |
| EW MonitorPLS 4HR AHR 31050 | 97407-31050 | \$ 295.00 | 10% | \$267.49 |
| EW MonitorPLS 4HR AHR 31051 | 97407-31051 | \$ 295.00 | 10% | \$267.49 |
| EW MonitorPLS 4HR AHR 31055 | 97407-31055 | \$ 295.00 | 10% | \$267.49 |

| | | | | |
|--|------------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR 31056 | 97407-31056 | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HR AHR 39031 | 97407-39031 | \$ 483.00 | 10% | <i>\$437.96</i> |
| EW MonitorPLS 4HR AHR 39032 | 97407-39032 | \$ 619.00 | 10% | <i>\$561.28</i> |
| EW MonitorPLS 4HR AHR 39033 | 97407-39033 | \$ 483.00 | 10% | <i>\$437.96</i> |
| EW MonitorPLS 4HR AHR 39034 | 97407-39034 | \$ 483.00 | 10% | <i>\$437.96</i> |
| EW MonitorPLS 4HR AHR 39035 | 97407-39035 | \$ 1,430.00 | 10% | <i>\$1,296.65</i> |
| EW MonitorPLS 4HR AHR 39036 | 97407-39036 | \$ 487.00 | 10% | <i>\$441.59</i> |
| EW MonitorPLS 4HR AHR 39037 | 97407-39037 | \$ 487.00 | 10% | <i>\$441.59</i> |
| EW MonitorPLS 4HR AHR 39038 | 97407-39038 | \$ 630.00 | 10% | <i>\$571.25</i> |
| EW MonitorPLS 4HR AHR 39039 | 97407-39039 | \$ 630.00 | 10% | <i>\$571.25</i> |
| EW MonitorPLS 4HR AHR 4120- 24MW-4Y | 97407-4120- 24MW-4Y | \$ 1,340.00 | 10% | <i>\$1,215.05</i> |
| EW MonitorPLS 4HR AHR 4120- 48MW-4Y | 97407-4120- 48MW-4Y | \$ 1,632.00 | 10% | <i>\$1,479.82</i> |
| EW MonitorPLS 4HR AHR 4120C | 97407-4120C | \$ 6,942.00 | 10% | <i>\$6,294.66</i> |
| EW MonitorPLS 4HR AHR 4120C-1 | 97407-4120C-1 | \$ 7,837.00 | 10% | <i>\$7,106.20</i> |
| EW MonitorPLS 4HR AHR 41216 | 97407-41216 | \$ 2,165.00 | 10% | <i>\$1,963.11</i> |
| EW MonitorPLS 4HR AHR 4220- 12P-4X | 97407-4220- 12P-4X | \$ 717.00 | 10% | <i>\$650.14</i> |
| EW MonitorPLS 4HR AHR 4220- 12T-4X | 97407-4220- 12T-4X | \$ 649.00 | 10% | <i>\$588.48</i> |
| EW MonitorPLS 4HR AHR 4220- 24P-4X | 97407-4220- 24P-4X | \$ 802.00 | 10% | <i>\$727.21</i> |
| EW MonitorPLS 4HR AHR 4220- 24T-4X | 97407-4220- 24T-4X | \$ 726.00 | 10% | <i>\$658.30</i> |
| EW MonitorPLS 4HR AHR 4220- 48P-4X | 97407-4220- 48P-4X | \$ 972.00 | 10% | <i>\$881.36</i> |
| EW MonitorPLS 4HR AHR 4220- 48T-4X | 97407-4220- 48T-4X | \$ 845.00 | 10% | <i>\$766.20</i> |

| | | | | |
|--|---------------------------|--------------|-----|-------------|
| EW MonitorPLS 4HR AHR 4220-4MW-20P-4X | 97407-4220-4MW-20P-4X | \$ 930.00 | 10% | \$843.28 |
| EW MonitorPLS 4HR AHR 4220-4MW-8P-4X | 97407-4220-4MW-8P-4X | \$ 794.00 | 10% | \$719.96 |
| EW MonitorPLS 4HR AHR 4220-8MW-40P-4X | 97407-4220-8MW-40P-4X | \$ 1,142.00 | 10% | \$1,035.51 |
| EW MonitorPLS 4HR AHR 4220-8X | 97407-4220-8X | \$ 819.00 | 10% | \$742.63 |
| EW MonitorPLS 4HR AHR-48001 | 97407-48001 | \$ 9,386.00 | 10% | \$8,510.76 |
| EW MonitorPLS 4HR AHR-48038 | 97407-48038 | \$ 3,436.00 | 10% | \$3,115.59 |
| EW MonitorPLS 4HR AHR-48039 | 97407-48039 | \$ 3,436.00 | 10% | \$3,115.59 |
| EW MonitorPLS 4HR AHR-48040 | 97407-48040 | \$ 3,306.00 | 10% | \$2,997.72 |
| EW MonitorPLS 4HR AHR-48041 | 97407-48041 | \$ 3,436.00 | 10% | \$3,115.59 |
| EW MonitorPLS 4HR AHR-48046 | 97407-48046 | \$ 4,425.00 | 10% | \$4,012.37 |
| EW MonitorPLS 4HR AHR-48047 | 97407-48047 | \$ 11,356.00 | 10% | \$10,297.05 |
| EW MonitorPLS 4HR AHR-48051 | 97407-48051 | \$ 7,888.00 | 10% | \$7,152.44 |
| EW MonitorPLS 4HR AHR-48061 | 97407-48061 | \$ 9,180.00 | 10% | \$8,323.97 |
| EW MonitorPLS 4HR AHR-48062 | 97407-48062 | \$ 14,532.00 | 10% | \$13,176.89 |
| EW MonitorPLS 4HR AHR 5320-16P-4XE | 97407-5320-16P-4XE | \$ 908.00 | 10% | \$823.33 |
| EW MonitorPLS 4HR AHR 5320-16P-4XE-DC | 97407-5320-16P-4XE-DC | \$ 975.00 | 10% | \$884.08 |
| EW MonitorPLS 4HR AHR 5320-24P-8XE | 97407-5320-24P-8XE | \$ 941.00 | 10% | \$853.25 |
| EW MonitorPLS 4HR AHR5320-24T-24S-4XE-XT | 97407-5320-24T-24S-4XE-XT | \$ 1,015.00 | 10% | \$920.35 |
| EW MonitorPLS 4HR AHR 5320-24T-4X-XT | 97407-5320-24T-4X-XT | \$ 760.00 | 10% | \$689.13 |
| EW MonitorPLS 4HR AHR 5320-24T-8XE | 97407-5320-24T-8XE | \$ 834.00 | 10% | \$756.23 |

| | | | | |
|--|--------------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR 5320-48P-8XE | 97407-5320-48P-8XE | \$ 1,225.00 | 10% | <i>\$1,110.77</i> |
| EW MonitorPLS 4HR AHR 5320-48T-8XE | 97407-5320-48T-8XE | \$ 1,022.00 | 10% | <i>\$926.70</i> |
| EW MonitorPLS 4HR AHR 5420F-16MW-32P-4XE | 97407-5420F-16MW-32P-4XE | \$ 1,777.00 | 10% | <i>\$1,611.29</i> |
| EW MonitorPLS 4HR AHR 5420F-16W-32P-4XE | 97407-5420F-16W-32P-4XE | \$ 1,736.00 | 10% | <i>\$1,574.12</i> |
| EW MonitorPLS 4HR AHR 5420F-24P-4XE | 97407-5420F-24P-4XE | \$ 1,134.00 | 10% | <i>\$1,028.25</i> |
| EW MonitorPLS 4HR AHR 5420F-24S-4XE | 97407-5420F-24S-4XE | \$ 1,194.00 | 10% | <i>\$1,082.66</i> |
| EW MonitorPLS 4HR AHR 5420F-24T-4XE | 97407-5420F-24T-4XE | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW MonitorPLS 4HR AHR 5420F-48P-4XE | 97407-5420F-48P-4XE | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW MonitorPLS 4HR AHR 5420F-48P-4XL | 97407-5420F-48P-4XL | \$ 1,505.00 | 10% | <i>\$1,364.66</i> |
| EW MonitorPLS 4HR AHR 5420F-48T-4XE | 97407-5420F-48T-4XE | \$ 1,165.00 | 10% | <i>\$1,056.36</i> |
| EW MonitorPLS 4HR AHR 5420F-8W-16P-4XE | 97407-5420F-8W-16P-4XE | \$ 1,191.00 | 10% | <i>\$1,079.94</i> |
| EW MonitorPLS 4HR AHR 5420M-16MW-32P-4YE | 97407-5420M-16MW-32P-4YE | \$ 1,908.00 | 10% | <i>\$1,730.08</i> |
| EW MonitorPLS 4HR AHR 5420M-24T-4YE | 97407-5420M-24T-4YE | \$ 1,184.00 | 10% | <i>\$1,073.59</i> |
| EW MonitorPLS 4HR AHR 5420M-24W-4YE | 97407-5420M-24W-4YE | \$ 1,089.00 | 10% | <i>\$987.45</i> |
| EW MonitorPLS 4HR AHR 5420M-48T-4YE | 97407-5420M-48T-4YE | \$ 1,379.00 | 10% | <i>\$1,250.41</i> |
| EW MonitorPLS 4HR AHR 5420M-48W-4YE | 97407-5420M-48W-4YE | \$ 1,508.00 | 10% | <i>\$1,367.38</i> |
| EW MONITORPLUS 4HR AHR 5520-12MW-36W | 97407-5520-12MW-36W | \$ 1,996.00 | 10% | <i>\$1,809.87</i> |
| EW MONITORPLUS 4HR AHR 5520-24T | 97407-5520-24T | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW MONITORPLUS 4HR AH 5520-24T-ACDC-BASE | 97407-5520-24T-ACDC-BASE | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW MONITORPLUS 4HR AHR 5520-24T-BASE | 97407-5520-24T-BASE | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW MONITORPLUS 4HR AHR 5520-24W | 97407-5520-24W | \$ 1,307.00 | 10% | <i>\$1,185.12</i> |
| EW MONITORPLUS 4HR AHR 5520-24X | 97407-5520-24X | \$ 2,066.00 | 10% | <i>\$1,873.35</i> |
| EW MONITORPLUS 4HR AH 5520-24X-ACDC-BASE | 97407-5520-24X-ACDC-BASE | \$ 2,066.00 | 10% | <i>\$1,873.35</i> |
| EW MONITORPLUS 4HR AHR 5520-24X-BASE | 97407-5520-24X-BASE | \$ 2,066.00 | 10% | <i>\$1,873.35</i> |
| EW MONITORPLUS 4HR AHR 5520-48SE | 97407-5520-48SE | \$ 2,011.00 | 10% | <i>\$1,823.47</i> |
| EW MONITORPLU 4HR AH 5520-48SE-ACDC-BASE | 97407-5520-48SE-ACDC-BASE | \$ 2,011.00 | 10% | <i>\$1,823.47</i> |
| EW MONITORPLUS 4HR AHR 5520-48SE-BASE | 97407-5520-48SE-BASE | \$ 2,011.00 | 10% | <i>\$1,823.47</i> |
| EW MONITORPLUS 4HR AHR 5520-48T | 97407-5520-48T | \$ 1,505.00 | 10% | <i>\$1,364.66</i> |
| EW MONITORPLUS 4HR AH 5520-48T-ACDC-BASE | 97407-5520-48T-ACDC-BASE | \$ 1,505.00 | 10% | <i>\$1,364.66</i> |
| EW MONITORPLUS 4HR AHR 5520-48T-BASE | 97407-5520-48T-BASE | \$ 1,505.00 | 10% | <i>\$1,364.66</i> |
| EW MONITORPLUS 4HR AHR 5520-48W | 97407-5520-48W | \$ 1,766.00 | 10% | <i>\$1,601.32</i> |
| EW MonitorPLS 4HR AHR 5720-24MW | 97407-5720-24MW | \$ 1,979.00 | 10% | <i>\$1,794.46</i> |
| EW MonitorPLS 4HR AHR 5720-24MXW | 97407-5720-24MXW | \$ 2,620.00 | 10% | <i>\$2,375.69</i> |
| EW MonitorPLS 4HR AHR 5720-48MW | 97407-5720-48MW | \$ 2,257.00 | 10% | <i>\$2,046.53</i> |
| EW MonitorPLS 4HR AHR 5720-48MXW | 97407-5720-48MXW | \$ 3,117.00 | 10% | <i>\$2,826.34</i> |
| EW MonitorPLS 4HR AHR 7520-48XT-6C | 97407-7520-48XT-6C | \$ 3,575.00 | 10% | <i>\$3,241.63</i> |
| EW MonitorPLS 4HR AHR 7520-48XT-6C-AC-F | 97407-7520-48XT-6C-AC-F | \$ 3,575.00 | 10% | <i>\$3,241.63</i> |
| EW MonitorPLS 4HR AHR 7520-48XT-6C-AC-R | 97407-7520-48XT-6C-AC-R | \$ 3,575.00 | 10% | <i>\$3,241.63</i> |

| | | | | |
|--|--------------------------|-------------|-----|------------|
| EW MonitorPLS 4HR AHR 7520-48Y-8C | 97407-7520-48Y-8C | \$ 3,339.00 | 10% | \$3,027.64 |
| EW MonitorPLS 4HR AHR 7520-48Y-8C-AC-F | 97407-7520-48Y-8C-AC-F | \$ 3,339.00 | 10% | \$3,027.64 |
| EW MonitorPLS 4HR AHR 7520-48Y-8C-AC-R | 97407-7520-48Y-8C-AC-R | \$ 3,339.00 | 10% | \$3,027.64 |
| EW MONITORPLUS 4HR AHR 7520-48YE-8CE | 97407-7520-48YE-8CE | \$ 3,867.00 | 10% | \$3,506.40 |
| EW MONITORPLU 4HR AHR 7520-48YE-8CE-AC-F | 97407-7520-48YE-8CE-AC-F | \$ 3,867.00 | 10% | \$3,506.40 |
| EW MONITORPLU 4HR AHR 7520-48YE-8CE-AC-R | 97407-7520-48YE-8CE-AC-R | \$ 3,867.00 | 10% | \$3,506.40 |
| EW MonitorPLS 4HR AHR 7720-32C | 97407-7720-32C | \$ 4,129.00 | 10% | \$3,743.97 |
| EW MonitorPLS 4HR AHR 7720-32C-AC-F | 97407-7720-32C-AC-F | \$ 4,129.00 | 10% | \$3,743.97 |
| EW MonitorPLS 4HR AHR 7720-32C-AC-R | 97407-7720-32C-AC-R | \$ 4,129.00 | 10% | \$3,743.97 |
| EW MonitorPLS 4HR AHR 8520-48XT-6C | 97407-8520-48XT-6C | \$ 3,736.00 | 10% | \$3,387.62 |
| EW MonitorPLS 4HR AHR 8520-48XT-6C-AC-F | 97407-8520-48XT-6C-AC-F | \$ 3,736.00 | 10% | \$3,387.62 |
| EW MonitorPLS 4HR AHR 8520-48XT-6C-AC-R | 97407-8520-48XT-6C-AC-R | \$ 3,736.00 | 10% | \$3,387.62 |
| EW MonitorPLS 4HR AHR 8520-48XT-6C-DC-F | 97407-8520-48XT-6C-DC-F | \$ 3,736.00 | 10% | \$3,387.62 |
| EW MonitorPLS 4HR AHR 8520-48XT-6C-DC-R | 97407-8520-48XT-6C-DC-R | \$ 3,736.00 | 10% | \$3,387.62 |
| EW MonitorPLS 4HR AHR 8520-48Y-8C | 97407-8520-48Y-8C | \$ 3,827.00 | 10% | \$3,470.13 |
| EW MonitorPLS 4HR AHR 8520-48Y-8C-AC-F | 97407-8520-48Y-8C-AC-F | \$ 3,827.00 | 10% | \$3,470.13 |
| EW MonitorPLS 4HR AHR 8520-48Y-8C-AC-R | 97407-8520-48Y-8C-AC-R | \$ 3,827.00 | 10% | \$3,470.13 |
| EW MonitorPLS 4HR AHR 8520-48Y-8C-DC-F | 97407-8520-48Y-8C-DC-F | \$ 3,827.00 | 10% | \$3,470.13 |

| | | | | |
|--|------------------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR 8520-48Y-8C-DC-R | 97407-8520-48Y-8C-DC-R | \$ 3,827.00 | 10% | <i>\$3,470.13</i> |
| EW MonitorPLS 4HR AHR 8720-32C | 97407-8720-32C | \$ 4,282.00 | 10% | <i>\$3,882.70</i> |
| EW MonitorPLS 4HR AHR 8720-32C-AC-F | 97407-8720-32C-AC-F | \$ 4,282.00 | 10% | <i>\$3,882.70</i> |
| EW MonitorPLS 4HR AHR 8720-32C-AC-R | 97407-8720-32C-AC-R | \$ 4,282.00 | 10% | <i>\$3,882.70</i> |
| EW MonitorPLS 4HR AHR 8720-32C-DC-F | 97407-8720-32C-DC-F | \$ 4,282.00 | 10% | <i>\$3,882.70</i> |
| EW MonitorPLS 4HR AHR 8720-32C-DC-R | 97407-8720-32C-DC-R | \$ 4,282.00 | 10% | <i>\$3,882.70</i> |
| EW MonitorPLUS 4HR AHR-8806 | 97407-8806 | \$ 3,490.00 | 10% | <i>\$3,164.56</i> |
| EW MonitorPLS 4HR AHR-8810 | 97407-8810 | \$ 7,454.00 | 10% | <i>\$6,758.91</i> |
| EW MonitorPLS 4HR AHR 8820-40C | 97407-8820-40C | \$ 13,673.00 | 10% | <i>\$12,397.99</i> |
| EW MonitorPLS 4HR AHR 8820-40C-AC-F | 97407-8820-40C-AC-F | \$ 13,673.00 | 10% | <i>\$12,397.99</i> |
| EW MonitorPLS 4HR AHR 8820-40C-AC-R | 97407-8820-40C-AC-R | \$ 13,673.00 | 10% | <i>\$12,397.99</i> |
| EW MonitorPLS 4HR AHR 8820-40C-DC-F | 97407-8820-40C-DC-F | \$ 13,673.00 | 10% | <i>\$12,397.99</i> |
| EW MonitorPLS 4HR AHR 8820-40C-DC-R | 97407-8820-40C-DC-R | \$ 13,673.00 | 10% | <i>\$12,397.99</i> |
| EW MonitorPLS 4HR AHR 8820-80C | 97407-8820-80C | \$ 24,416.00 | 10% | <i>\$22,139.21</i> |
| EW MonitorPLS 4HR AHR 8820-80C-AC-F | 97407-8820-80C-AC-F | \$ 24,416.00 | 10% | <i>\$22,139.21</i> |
| EW MonitorPLS 4HR AHR 8820-80C-AC-R | 97407-8820-80C-AC-R | \$ 24,416.00 | 10% | <i>\$22,139.21</i> |
| EW MonitorPLS 4HR AHR 8820-80C-DC-F | 97407-8820-80C-DC-F | \$ 24,416.00 | 10% | <i>\$22,139.21</i> |
| EW MonitorPLS 4HR AHR 8820-80C-DC-R | 97407-8820-80C-DC-R | \$ 24,416.00 | 10% | <i>\$22,139.21</i> |
| EW MonitorPLS 4HR AHR 9920-16C | 97407-9920-16C | \$ 11,030.00 | 10% | <i>\$10,001.45</i> |
| EW MonitorPLS 4HR AHR 9920-4D | 97407-9920-4D | \$ 11,030.00 | 10% | <i>\$10,001.45</i> |
| EW MonitorPLS 4HR AHR 9920-NPB-8 | 97407-9920-NPB-8 | \$ 17,159.00 | 10% | <i>\$15,558.92</i> |

| | | | | |
|---|-------------------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR AH-AP-1130-AC-CE | 97407-AH-AP-1130-AC-CE | \$ 286.00 | 10% | \$259.33 |
| EW MonitorPLS 4HR AHR AH-AP-1130-AC-FCC | 97407-AH-AP-1130-AC-FCC | \$ 286.00 | 10% | \$259.33 |
| EW MonitorPLS 4HR AHR AH-AP-1130-AC-W | 97407-AH-AP-1130-AC-W | \$ 286.00 | 10% | \$259.33 |
| EW MonitorPLS 4HR AHR AH-AP-122-AC-CAN | 97407-AH-AP-122-AC-CAN | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-122-AC-CE | 97407-AH-AP-122-AC-CE | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-122-AC-FCC | 97407-AH-AP-122-AC-FCC | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-122-AC-W | 97407-AH-AP-122-AC-W | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-130-AC-CE | 97407-AH-AP-130-AC-CE | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-130-AC-FCC | 97407-AH-AP-130-AC-FCC | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-130-AC-W | 97407-AH-AP-130-AC-W | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-150W-AC-CAN | 97407-AH-AP-150W-AC-CAN | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-150W-AC-CE | 97407-AH-AP-150W-AC-CE | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-150W-AC-FCC | 97407-AH-AP-150W-AC-FCC | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-150W-AC-W | 97407-AH-AP-150W-AC-W | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-230-AC-CE | 97407-AH-AP-230-AC-CE | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-230-AC-FCC | 97407-AH-AP-230-AC-FCC | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-230-AC-W | 97407-AH-AP-230-AC-W | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-250-AC-CAN | 97407-AH-AP-250-AC-CAN | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-250-AC-CE | 97407-AH-AP-250-AC-CE | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-250-AC-FCC | 97407-AH-AP-250-AC-FCC | \$ 247.00 | 10% | \$223.97 |

| | | | | |
|---|-------------------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR AH-AP-250-AC-W | 97407-AH-AP-250-AC-W | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS 4HR AHR AH-AP-630-AX-CAN | 97407-AH-AP-630-AX-CAN | \$ 292.00 | 10% | \$264.77 |
| EW MonitorPLS 4HR AHR AH-AP-630-AX-CE | 97407-AH-AP-630-AX-CE | \$ 292.00 | 10% | \$264.77 |
| EW MonitorPLS 4HR AHR AH-AP-630-AX-FCC | 97407-AH-AP-630-AX-FCC | \$ 292.00 | 10% | \$264.77 |
| EW MonitorPLS 4HR AHR AH-AP-630-AX-W | 97407-AH-AP-630-AX-W | \$ 292.00 | 10% | \$264.77 |
| EW MonitorPLS 4HR AHR AH-AP-650-AX-CAN | 97407-AH-AP-650-AX-CAN | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-AP-650-AX-CE | 97407-AH-AP-650-AX-CE | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-AP-650-AX-FCC | 97407-AH-AP-650-AX-FCC | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-AP-650-AX-W | 97407-AH-AP-650-AX-W | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-AP-650X-AX-CAN | 97407-AH-AP-650X-AX-CAN | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-AP-650X-AX-CE | 97407-AH-AP-650X-AX-CE | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-AP-650X-AX-FCC | 97407-AH-AP-650X-AX-FCC | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-AP-650X-AX-W | 97407-AH-AP-650X-AX-W | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AH-ATOM-CAN | 97407-AH-ATOM-CAN | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS 4HR AHR AH-ATOM-CE-EU | 97407-AH-ATOM-CE-EU | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS 4HR AHR AH-ATOM-CE-UK | 97407-AH-ATOM-CE-UK | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS 4HR AHR AH-ATOM-FCC | 97407-AH-ATOM-FCC | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS 4HR AHR AH-ATOM-W | 97407-AH-ATOM-W | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS 4HR AHR AH-ATOM-W-EU | 97407-AH-ATOM-W-EU | \$ 272.00 | 10% | \$246.64 |

| | | | | |
|--------------------------------------|----------------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR AH-ATOM-W-UK | 97407-AH-ATOM-W-UK | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS 4HR AHR AH-SR-2208P-AU | 97407-AH-SR-2208P-AU | \$ 677.00 | 10% | \$613.87 |
| EW MonitorPLS 4HR AHR AH-SR-2208P-EU | 97407-AH-SR-2208P-EU | \$ 677.00 | 10% | \$613.87 |
| EW MonitorPLS 4HR AHR AH-SR-2208P-NA | 97407-AH-SR-2208P-NA | \$ 677.00 | 10% | \$613.87 |
| EW MonitorPLS 4HR AHR AH-SR-2208P-UK | 97407-AH-SR-2208P-UK | \$ 677.00 | 10% | \$613.87 |
| EW MonitorPLS 4HR AHR AH-SR-2224P-AU | 97407-AH-SR-2224P-AU | \$ 718.00 | 10% | \$651.05 |
| EW MonitorPLS 4HR AHR AH-SR-2224P-EU | 97407-AH-SR-2224P-EU | \$ 718.00 | 10% | \$651.05 |
| EW MonitorPLS 4HR AHR AH-SR-2224P-NA | 97407-AH-SR-2224P-NA | \$ 718.00 | 10% | \$651.05 |
| EW MonitorPLS 4HR AHR AH-SR-2224P-UK | 97407-AH-SR-2224P-UK | \$ 718.00 | 10% | \$651.05 |
| EW MonitorPLS 4HR AHR AH-SR-2324P-AU | 97407-AH-SR-2324P-AU | \$ 765.00 | 10% | \$693.66 |
| EW MonitorPLS 4HR AHR AH-SR-2324P-EU | 97407-AH-SR-2324P-EU | \$ 765.00 | 10% | \$693.66 |
| EW MonitorPLS 4HR AHR AH-SR-2324P-NA | 97407-AH-SR-2324P-NA | \$ 765.00 | 10% | \$693.66 |
| EW MonitorPLS 4HR AHR AH-SR-2324P-UK | 97407-AH-SR-2324P-UK | \$ 765.00 | 10% | \$693.66 |
| EW MonitorPLS 4HR AHR AH-SR-2348P-AU | 97407-AH-SR-2348P-AU | \$ 926.00 | 10% | \$839.65 |
| EW MonitorPLS 4HR AHR AH-SR-2348P-EU | 97407-AH-SR-2348P-EU | \$ 926.00 | 10% | \$839.65 |
| EW MonitorPLS 4HR AHR AH-SR-2348P-NA | 97407-AH-SR-2348P-NA | \$ 926.00 | 10% | \$839.65 |
| EW MonitorPLS 4HR AHR AH-SR-2348P-UK | 97407-AH-SR-2348P-UK | \$ 926.00 | 10% | \$839.65 |
| EW MonitorPLS 4HR AHR AH-XR200P-AU | 97407-AH-XR200P-AU | \$ 677.00 | 10% | \$613.87 |
| EW MonitorPLS 4HR AHR AH-XR200P-EU | 97407-AH-XR200P-EU | \$ 677.00 | 10% | \$613.87 |
| EW MonitorPLS 4HR AHR AH-XR200P-UK | 97407-AH-XR200P-UK | \$ 677.00 | 10% | \$613.87 |
| EW MonitorPLS 4HR AHR AH-XR200P-US | 97407-AH-XR200P-US | \$ 677.00 | 10% | \$613.87 |

| | | | | |
|---|---------------------------------|-----------|-----|-----------------|
| EW MonitorPLS 4HR AHR AH- XR600P | 97407-AH- XR600P | \$ 685.00 | 10% | <i>\$621.12</i> |
| EW MonitorPLS 4HR AHR AH- XR600P-AU | 97407-AH- XR600P-AU | \$ 689.00 | 10% | <i>\$624.75</i> |
| EW MonitorPLS 4HR AHR AH- XR600P-EU | 97407-AH- XR600P-EU | \$ 689.00 | 10% | <i>\$624.75</i> |
| EW MonitorPLS 4HR AHR AH- XR600P-KR | 97407-AH- XR600P-KR | \$ 689.00 | 10% | <i>\$624.75</i> |
| EW MonitorPLS 4HR AHR AH- XR600P-UK | 97407-AH- XR600P-UK | \$ 689.00 | 10% | <i>\$624.75</i> |
| EW MonitorPLS 4HR AHR AH- XR600P-US | 97407-AH- XR600P-US | \$ 689.00 | 10% | <i>\$624.75</i> |
| EW MonitorPLS 4HR AHR AP- 8533-68SB30-IL | 97407-AP- 8533-68SB30- IL | \$ 306.00 | 10% | <i>\$277.47</i> |
| EW MonitorPLS 4HR AHR AP3000-IL | 97407-AP3000- IL | \$ 178.44 | 10% | <i>\$161.80</i> |
| EW MonitorPLS 4HR AHR AP3000-TN | 97407-AP3000- TN | \$ 178.44 | 10% | <i>\$161.80</i> |
| EW MonitorPLS 4HR AHR AP3000-WW | 97407-AP3000- WW | \$ 178.44 | 10% | <i>\$161.80</i> |
| EW MonitorPLS 4HR AHR AP3000X-WW | 97407- AP3000X-WW | \$ 195.94 | 10% | <i>\$177.67</i> |
| EW MonitorPLS 4HR AHR AP302W-CAN | 97407- AP302W-CAN | \$ 237.00 | 10% | <i>\$214.90</i> |
| EW MonitorPLS 4HR AHR AP302W-EG | 97407- AP302W-EG | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW MonitorPLS 4HR AHR AP302W-FCC | 97407- AP302W-FCC | \$ 237.00 | 10% | <i>\$214.90</i> |
| EW MonitorPLS 4HR AHR AP302W-WR | 97407- AP302W-WR | \$ 226.00 | 10% | <i>\$204.93</i> |
| EW MonitorPLS 4HR AHR AP305C-1-CAN | 97407-AP305C- 1-CAN | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS 4HR AHR AP305C-1-EG | 97407-AP305C- 1-EG | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS 4HR AHR AP305C-1-FCC | 97407-AP305C- 1-FCC | \$ 246.00 | 10% | <i>\$223.06</i> |
| EW MonitorPLS 4HR AHR AP305C-1-IL | 97407-AP305C- 1-IL | \$ 246.00 | 10% | <i>\$223.06</i> |

| | | | | |
|--------------------------------------|---------------------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR AP305C-1-WR | 97407-AP305C- 1-WR | \$ 246.00 | 10% | \$223.06 |
| EW MonitorPLS 4HR AHR AP305C-CAN | 97407-AP305C- CAN | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305C-EG | 97407-AP305C- EG | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305C-FCC | 97407-AP305C- FCC | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305C-IL | 97407-AP305C- IL | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305C-WR | 97407-AP305C- WR | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305CX-CAN | 97407- AP305CX- CAN | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305CX-FCC | 97407- AP305CX- FCC | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305CX-IL | 97407- AP305CX-IL | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP305CX-WR | 97407- AP305CX-WR | \$ 265.00 | 10% | \$240.29 |
| EW MonitorPLS 4HR AHR AP310e-1-WR | 97407-AP310e- 1-WR | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS 4HR AHR AP310e-CAN | 97407-AP310e- CAN | \$ 237.00 | 10% | \$214.90 |
| EW MonitorPLS 4HR AHR AP310e-FCC | 97407-AP310e- FCC | \$ 237.00 | 10% | \$214.90 |
| EW MonitorPLS 4HR AHR AP310e-IL | 97407-AP310e- IL | \$ 237.00 | 10% | \$214.90 |
| EW MonitorPLS 4HR AHR AP310e-WR | 97407-AP310e- WR | \$ 237.00 | 10% | \$214.90 |
| EW MonitorPLS 4HR AHR AP310i-1-WR | 97407-AP310i- 1-WR | \$ 226.00 | 10% | \$204.93 |
| EW MonitorPLS 4HR AHR AP310i-CAN | 97407-AP310i- CAN | \$ 237.00 | 10% | \$214.90 |
| EW MonitorPLS 4HR AHR AP310i-FCC | 97407-AP310i- FCC | \$ 237.00 | 10% | \$214.90 |
| EW MonitorPLS 4HR AHR AP310i-IL | 97407-AP310i- IL | \$ 237.00 | 10% | \$214.90 |
| EW MonitorPLS 4HR AHR AP310i-WR | 97407-AP310i- WR | \$ 237.00 | 10% | \$214.90 |

| | | | | |
|---------------------------------------|------------------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR AP360e-CAN | 97407-AP360e- CAN | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AP360e-FCC | 97407-AP360e- FCC | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AP360e-IL | 97407-AP360e- IL | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AP360e-WR | 97407-AP360e- WR | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AP360i-CAN | 97407-AP360i- CAN | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AP360i-FCC | 97407-AP360i- FCC | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AP360i-WR | 97407-AP360i- WR | \$ 263.00 | 10% | \$238.48 |
| EW MonitorPLS 4HR AHR AP4000-WW | 97407-AP4000- 1-WW | \$ 239.00 | 10% | \$216.71 |
| EW MonitorPLS 4HR AHR AP4000-IL | 97407-AP4000- IL | \$ 239.00 | 10% | \$216.71 |
| EW MonitorPLS 4HR AHR AP4000-WW | 97407-AP4000- WW | \$ 239.00 | 10% | \$216.71 |
| EW MonitorPLS 4HR AHR AP410C-1-CAN | 97407-AP410C- 1-CAN | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS 4HR AHR AP410C-1-EG | 97407-AP410C- 1-EG | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS 4HR AHR AP410C-1-FCC | 97407-AP410C- 1-FCC | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS 4HR AHR AP410C-1-IL | 97407-AP410C- 1-IL | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS 4HR AHR AP410C-1-WR | 97407-AP410C- 1-WR | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS 4HR AHR AP410C-CAN | 97407-AP410C- CAN | \$ 267.00 | 10% | \$242.10 |
| EW MonitorPLS 4HR AHR AP410C-EG | 97407-AP410C- EG | \$ 267.00 | 10% | \$242.10 |
| EW MonitorPLS 4HR AHR AP410C-FCC | 97407-AP410C- FCC | \$ 267.00 | 10% | \$242.10 |
| EW MonitorPLS 4HR AHR AP410C-IL | 97407-AP410C- IL | \$ 267.00 | 10% | \$242.10 |
| EW MonitorPLS 4HR AHR AP410C-WR | 97407-AP410C- WR | \$ 267.00 | 10% | \$242.10 |

| | | | | |
|---------------------------------------|------------------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR AP410e-CAN | 97407-AP410e- CAN | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS 4HR AHR AP410e-FCC | 97407-AP410e- FCC | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS 4HR AHR AP410e-WR | 97407-AP410e- WR | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS 4HR AHR AP410i-1-FCC | 97407-AP410i- 1-FCC | \$ 261.00 | 10% | \$236.66 |
| EW MonitorPLS 4HR AHR AP410i-1-WR | 97407-AP410i- 1-WR | \$ 261.00 | 10% | \$236.66 |
| EW MonitorPLS 4HR AHR AP410i-CAN | 97407-AP410i- CAN | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS 4HR AHR AP410i-FCC | 97407-AP410i- FCC | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS 4HR AHR AP410i-IL | 97407-AP410i- IL | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS 4HR AHR AP410i-WR | 97407-AP410i- WR | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS 4HR AHR AP460C-CAN | 97407-AP460C- CAN | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460C-EG | 97407-AP460C- EG | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460C-FCC | 97407-AP460C- FCC | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460C-IL | 97407-AP460C- IL | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460C-WR | 97407-AP460C- WR | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460e-CAN | 97407-AP460e- CAN | \$ 290.00 | 10% | \$262.96 |
| EW MonitorPLS 4HR AHR AP460e-FCC | 97407-AP460e- FCC | \$ 290.00 | 10% | \$262.96 |
| EW MonitorPLS 4HR AHR AP460e-WR | 97407-AP460e- WR | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS 4HR AHR AP460i-CAN | 97407-AP460i- CAN | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS 4HR AHR AP460i-FCC | 97407-AP460i- FCC | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS 4HR AHR AP460i-IL | 97407-AP460i- IL | \$ 276.00 | 10% | \$250.26 |
| EW MonitorPLS 4HR AHR AP460i-WR | 97407-AP460i- WR | \$ 277.00 | 10% | \$251.17 |

| | | | | |
|---|-----------------------------|-----------|-----|----------|
| EW MonitorPLS 4HR AHR AP460S12C-CAN | 97407- AP460S12C- CAN | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460S12C-FCC | 97407- AP460S12C- FCC | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460S12C-WR | 97407- AP460S12C- WR | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460S6C-CAN | 97407- AP460S6C- CAN | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460S6C-FCC | 97407- AP460S6C- FCC | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP460S6C-WR | 97407- AP460S6C- WR | \$ 294.00 | 10% | \$266.58 |
| EW MonitorPLS 4HR AHR AP5010-IL | 97407-AP5010- IL | \$ 282.00 | 10% | \$255.70 |
| EW MonitorPLS 4HR AHR AP5010-WW | 97407-AP5010- WW | \$ 282.00 | 10% | \$255.70 |
| EW MonitorPLS 4HR AHR AP5020-WW | 97407-AP5020- WW | \$ 283.37 | 6% | \$268.37 |
| EW MonitorPLS 4HR AHR AP5050D-WW | 97407- AP5050D-WW | \$ 460.00 | 10% | \$417.11 |
| EW MonitorPLS 4HR AHR AP5050U-WW | 97407- AP5050U-WW | \$ 384.00 | 10% | \$348.19 |
| EW MonitorPLS 4HR AHR AP505i-FCC | 97407-AP505i- FCC | \$ 283.00 | 10% | \$256.61 |
| EW MonitorPLS 4HR AHR AP505i-FCC-TAA | 97407-AP505i- FCC-TAA | \$ 283.00 | 10% | \$256.61 |
| EW MonitorPLS 4HR AHR AP505i-WR | 97407-AP505i- WR | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HR AHR AP510C-CAN | 97407-AP510C- CAN | \$ 255.00 | 10% | \$231.22 |
| EW MonitorPLS 4HR AHR AP510C-CE | 97407-AP510C- CE | \$ 255.00 | 10% | \$231.22 |
| EW MonitorPLS 4HR AHR AP510C-FCC | 97407-AP510C- FCC | \$ 255.00 | 10% | \$231.22 |
| EW MonitorPLS 4HR AHR AP510C-W | 97407-AP510C- W | \$ 255.00 | 10% | \$231.22 |

| | | | | |
|---|---------------------------|-----------|-----|-----------------|
| EW MonitorPLS 4HR AHR AP510C-WW | 97407-AP510C- WW | \$ 339.00 | 10% | <i>\$307.39</i> |
| EW MonitorPLS 4HR AHR AP510CX-CAN | 97407- AP510CX- CAN | \$ 255.00 | 10% | <i>\$231.22</i> |
| EW MonitorPLS 4HR AHR AP510CX-CE | 97407- AP510CX-CE | \$ 255.00 | 10% | <i>\$231.22</i> |
| EW MonitorPLS 4HR AHR AP510CX-FCC | 97407- AP510CX- FCC | \$ 255.00 | 10% | <i>\$231.22</i> |
| EW MonitorPLS 4HR AHR AP510CX-W | 97407- AP510CX-W | \$ 255.00 | 10% | <i>\$231.22</i> |
| EW MonitorPLS 4HR AHR AP510CX-WW | 97407- AP510CX-WW | \$ 339.00 | 10% | <i>\$307.39</i> |
| EW MonitorPLS 4HR AHR AP510e-FCC | 97407-AP510e- FCC | \$ 328.00 | 10% | <i>\$297.41</i> |
| EW MonitorPLS 4HR AHR AP510e-FCC-TAA | 97407-AP510e- FCC-TAA | \$ 328.00 | 10% | <i>\$297.41</i> |
| EW MonitorPLS 4HR AHR AP510e-WR | 97407-AP510e- WR | \$ 313.00 | 10% | <i>\$283.81</i> |
| EW MonitorPLS 4HR AHR AP510i-1-FCC | 97407-AP510i- 1-FCC | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HR AHR AP510i-1-WR | 97407-AP510i- 1-WR | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HR AHR AP510i-FCC | 97407-AP510i- FCC | \$ 310.00 | 10% | <i>\$281.09</i> |
| EW MonitorPLS 4HR AHR AP510i-FCC-TAA | 97407-AP510i- FCC-TAA | \$ 310.00 | 10% | <i>\$281.09</i> |
| EW MonitorPLS 4HR AHR AP510i-WR | 97407-AP510i- WR | \$ 310.00 | 10% | <i>\$281.09</i> |
| EW MonitorPLS 4HR AHR AP560h-FCC | 97407-AP560h- FCC | \$ 522.00 | 10% | <i>\$473.32</i> |
| EW MonitorPLS 4HR AHR AP560h-WR | 97407-AP560h- WR | \$ 522.00 | 10% | <i>\$473.32</i> |
| EW MonitorPLS 4HR AHR AP560i-FCC | 97407-AP560i- FCC | \$ 429.00 | 10% | <i>\$389.00</i> |
| EW MonitorPLS 4HR AHR AP560i-WR | 97407-AP560i- WR | \$ 409.00 | 10% | <i>\$370.86</i> |
| EW MonitorPLS 4HR AHR AP560m-FCC | 97407-AP560m- FCC | \$ 429.00 | 10% | <i>\$389.00</i> |

| | | | | |
|-------------------------------------|----------------------|--------------|-----|-------------------|
| EW MonitorPLS 4HR AHR AP560t-FCC | 97407-AP560t- FCC | \$ 522.00 | 10% | <i>\$473.32</i> |
| EW MonitorPLS 4HR AHR AP560u-FCC | 97407-AP560u- FCC | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW MonitorPLS 4HR AHR E2122 | 97407-E2122 | \$ 6,557.00 | 10% | <i>\$5,945.56</i> |
| EW MonitorPLS 4HR AHR E2122-1 | 97407-E2122-1 | \$ 6,215.00 | 10% | <i>\$5,635.45</i> |
| EW MonitorPLS 4HR AHR E3120-1 | 97407-E3120-1 | \$ 9,773.00 | 10% | <i>\$8,861.67</i> |
| EW MonitorPLS 4HR AHR E3125 | 97407-E3125 | \$ 10,728.00 | 10% | <i>\$9,727.61</i> |
| EW MonitorPLS 4HR AHR- H30131 | 97407-H30131 | \$ 2,498.00 | 10% | <i>\$2,265.06</i> |
| EW MonitorPLS 4HR AHR- H30132 | 97407-H30132 | \$ 2,452.00 | 10% | <i>\$2,223.35</i> |
| EW MonitorPLS 4HR AHR- H30133 | 97407-H30133 | \$ 5,366.00 | 10% | <i>\$4,865.62</i> |
| EW MonitorPLS 4HR AHR- H30134 | 97407-H30134 | \$ 6,613.00 | 10% | <i>\$5,996.34</i> |
| EW MonitorPLS 4HR AHR- H30135 | 97407-H30135 | \$ 5,471.00 | 10% | <i>\$4,960.83</i> |
| EW MonitorPLS 4HR AHR- H30136 | 97407-H30136 | \$ 6,613.00 | 10% | <i>\$5,996.34</i> |
| EW MonitorPLS 4HR AHR- H30184 | 97407-H30184 | \$ 762.00 | 10% | <i>\$690.94</i> |
| EW MonitorPLS 4HR AHR- H30185 | 97407-H30185 | \$ 1,134.00 | 10% | <i>\$1,028.25</i> |
| EW MonitorPLS 4HR AHR- H30186 | 97407-H30186 | \$ 922.00 | 10% | <i>\$836.02</i> |
| EW MonitorPLS 4HR AHR- H30187 | 97407-H30187 | \$ 829.00 | 10% | <i>\$751.70</i> |
| EW MonitorPLS 4HR AHR- H30188 | 97407-H30188 | \$ 922.00 | 10% | <i>\$836.02</i> |
| EW MonitorPLS 4HR AHR- H30189 | 97407-H30189 | \$ 922.00 | 10% | <i>\$836.02</i> |
| EW MonitorPLS 4HR AHR- H30190 | 97407-H30190 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR- H30214 | 97407-H30214 | \$ 985.00 | 10% | <i>\$893.15</i> |
| EW MonitorPLS 4HR AHR- H30215 | 97407-H30215 | \$ 985.00 | 10% | <i>\$893.15</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-H30216 | 97407-H30216 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30217 | 97407-H30217 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30218 | 97407-H30218 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30219 | 97407-H30219 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30220 | 97407-H30220 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30221 | 97407-H30221 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30222 | 97407-H30222 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30223 | 97407-H30223 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30224 | 97407-H30224 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30225 | 97407-H30225 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30226 | 97407-H30226 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30227 | 97407-H30227 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30228 | 97407-H30228 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30229 | 97407-H30229 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30267 | 97407-H30267 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30268 | 97407-H30268 | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW MonitorPLS 4HR AHR-H30269 | 97407-H30269 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30270 | 97407-H30270 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30271 | 97407-H30271 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30272 | 97407-H30272 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30273 | 97407-H30273 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-H30274 | 97407-H30274 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS 4HR AHR-H30275 | 97407-H30275 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30276 | 97407-H30276 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30277 | 97407-H30277 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS 4HR AHR-H30278 | 97407-H30278 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW MonitorPLS 4HR AHR-H30279 | 97407-H30279 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS 4HR AHR-H30280 | 97407-H30280 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS 4HR AHR-H30281 | 97407-H30281 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS 4HR AHR-H30282 | 97407-H30282 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS 4HR AHR-H30283 | 97407-H30283 | \$ 1,341.00 | 10% | <i>\$1,215.95</i> |
| EW MonitorPLS 4HR AHR-H30284 | 97407-H30284 | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW MonitorPLS 4HR AHR-H30296 | 97407-H30296 | \$ 985.00 | 10% | <i>\$893.15</i> |
| EW MonitorPLS 4HR AHR-H30297 | 97407-H30297 | \$ 985.00 | 10% | <i>\$893.15</i> |
| EW MonitorPLS 4HR AHR-H30298 | 97407-H30298 | \$ 985.00 | 10% | <i>\$893.15</i> |
| EW MonitorPLS 4HR AHR-H30299 | 97407-H30299 | \$ 985.00 | 10% | <i>\$893.15</i> |
| EW MonitorPLS 4HR AHR-H30381 | 97407-H30381 | \$ 1,869.00 | 10% | <i>\$1,694.72</i> |
| EW MonitorPLS 4HR AHR-H30384 | 97407-H30384 | \$ 1,745.00 | 10% | <i>\$1,582.28</i> |
| EW MonitorPLS 4HR AHR-H30391 | 97407-H30391 | \$ 1,476.00 | 10% | <i>\$1,338.36</i> |
| EW MonitorPLS 4HR AHR-H30392 | 97407-H30392 | \$ 1,476.00 | 10% | <i>\$1,338.36</i> |
| EW MonitorPLS 4HR AHR-H30393 | 97407-H30393 | \$ 792.00 | 10% | <i>\$718.15</i> |
| EW MonitorPLS 4HR AHR-H30394 | 97407-H30394 | \$ 2,631.00 | 10% | <i>\$2,385.66</i> |

| | | | | |
|------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS 4HR AHR-H30395 | 97407-H30395 | \$ 3,084.00 | 10% | \$2,796.42 |
| EW MonitorPLS 4HR AHR-H30396 | 97407-H30396 | \$ 2,832.00 | 10% | \$2,567.92 |
| EW MonitorPLS 4HR AHR-H30397 | 97407-H30397 | \$ 3,312.00 | 10% | \$3,003.16 |
| EW MonitorPLS 4HR AHR-H30398 | 97407-H30398 | \$ 807.00 | 10% | \$731.75 |
| EW MonitorPLS 4HR AHR-H30400 | 97407-H30400 | \$ 561.00 | 10% | \$508.69 |
| EW MonitorPLS 4HR AHR-H30401 | 97407-H30401 | \$ 683.00 | 10% | \$619.31 |
| EW MonitorPLS 4HR AHR-H30402 | 97407-H30402 | \$ 710.00 | 10% | \$643.79 |
| EW MonitorPLS 4HR AHR-H30403 | 97407-H30403 | \$ 928.00 | 10% | \$841.46 |
| EW MonitorPLS 4HR AHR-H30480 | 97407-H30480 | \$ 2,009.00 | 10% | \$1,821.66 |
| EW MonitorPLS 4HR AHR-H30495 | 97407-H30495 | \$ 3,058.00 | 10% | \$2,772.84 |
| EW MonitorPLS 4HR AHR-H30496 | 97407-H30496 | \$ 2,998.00 | 10% | \$2,718.44 |
| EW MonitorPLS 4HR AHR-H30497 | 97407-H30497 | \$ 3,863.00 | 10% | \$3,502.78 |
| EW MonitorPLS 4HR AHR-H30498 | 97407-H30498 | \$ 3,789.00 | 10% | \$3,435.68 |
| EW MonitorPLS 4HR AHR-H30499 | 97407-H30499 | \$ 1,129.00 | 10% | \$1,023.72 |
| EW MonitorPLS 4HR AHR-H30501 | 97407-H30501 | \$ 3,789.00 | 10% | \$3,435.68 |
| EW MonitorPLS 4HR AHR-H30502 | 97407-H30502 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW MonitorPLS 4HR AHR-H30503 | 97407-H30503 | \$ 1,129.00 | 10% | \$1,023.72 |
| EW MonitorPLS 4HR AHR-H30505 | 97407-H30505 | \$ 5,913.00 | 10% | \$5,361.61 |
| EW MonitorPLS 4HR AHR-H30506 | 97407-H30506 | \$ 7,599.00 | 10% | \$6,890.39 |
| EW MonitorPLS 4HR AHR-H30509 | 97407-H30509 | \$ 5,180.00 | 10% | \$4,696.97 |
| EW MonitorPLS 4HR AHR-H30510 | 97407-H30510 | \$ 5,913.00 | 10% | \$5,361.61 |

| | | | | |
|------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR-H30511 | 97407-H30511 | \$ 7,599.00 | 10% | <i>\$6,890.39</i> |
| EW MonitorPLS 4HR AHR-H30512 | 97407-H30512 | \$ 1,129.00 | 10% | <i>\$1,023.72</i> |
| EW MonitorPLS 4HR AHR-H30513 | 97407-H30513 | \$ 1,738.00 | 10% | <i>\$1,575.93</i> |
| EW MonitorPLS 4HR AHR-H30525 | 97407-H30525 | \$ 6,639.00 | 10% | <i>\$6,019.91</i> |
| EW MonitorPLS 4HR AHR-H30526 | 97407-H30526 | \$ 4,947.00 | 10% | <i>\$4,485.69</i> |
| EW MonitorPLS 4HR AHR-H30528 | 97407-H30528 | \$ 7,669.00 | 10% | <i>\$6,953.87</i> |
| EW MonitorPLS 4HR AHR-H30531 | 97407-H30531 | \$ 10,814.00 | 10% | <i>\$9,805.59</i> |
| EW MonitorPLS 4HR AHR-H30532 | 97407-H30532 | \$ 10,814.00 | 10% | <i>\$9,805.59</i> |
| EW MonitorPLS 4HR AHR-H30534 | 97407-H30534 | \$ 11,025.00 | 10% | <i>\$9,996.92</i> |
| EW MonitorPLS 4HR AHR-H30535 | 97407-H30535 | \$ 11,735.00 | 10% | <i>\$10,640.71</i> |
| EW MonitorPLS 4HR AHR-H30536 | 97407-H30536 | \$ 10,814.00 | 10% | <i>\$9,805.59</i> |
| EW MonitorPLS 4HR AHR-H30537 | 97407-H30537 | \$ 11,735.00 | 10% | <i>\$10,640.71</i> |
| EW MonitorPLS 4HR AHR-H30538 | 97407-H30538 | \$ 6,639.00 | 10% | <i>\$6,019.91</i> |
| EW MonitorPLS 4HR AHR-H30539 | 97407-H30539 | \$ 12,532.00 | 10% | <i>\$11,363.39</i> |
| EW MonitorPLS 4HR AHR-H30540 | 97407-H30540 | \$ 12,953.00 | 10% | <i>\$11,745.13</i> |
| EW MonitorPLS 4HR AHR-H30543 | 97407-H30543 | \$ 1,108.00 | 10% | <i>\$1,004.68</i> |
| EW MonitorPLS 4HR AHR-H30544 | 97407-H30544 | \$ 1,789.00 | 10% | <i>\$1,622.18</i> |
| EW MonitorPLS 4HR AHR-H30548 | 97407-H30548 | \$ 1,108.00 | 10% | <i>\$1,004.68</i> |
| EW MonitorPLS 4HR AHR-H30549 | 97407-H30549 | \$ 1,705.00 | 10% | <i>\$1,546.01</i> |
| EW MonitorPLS 4HR AHR-H30550 | 97407-H30550 | \$ 1,705.00 | 10% | <i>\$1,546.01</i> |
| EW MonitorPLS 4HR AHR-H30552 | 97407-H30552 | \$ 1,108.00 | 10% | <i>\$1,004.68</i> |

| | | | | |
|------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR-H30553 | 97407-H30553 | \$ 1,616.00 | 10% | <i>\$1,465.31</i> |
| EW MonitorPLS 4HR AHR-H30569 | 97407-H30569 | \$ 5,366.00 | 10% | <i>\$4,865.62</i> |
| EW MonitorPLS 4HR AHR-H30570 | 97407-H30570 | \$ 6,309.00 | 10% | <i>\$5,720.69</i> |
| EW MonitorPLS 4HR AHR-H30571 | 97407-H30571 | \$ 6,309.00 | 10% | <i>\$5,720.69</i> |
| EW MonitorPLS 4HR AHR-H30573 | 97407-H30573 | \$ 5,366.00 | 10% | <i>\$4,865.62</i> |
| EW MonitorPLS 4HR AHR-H30574 | 97407-H30574 | \$ 5,877.00 | 10% | <i>\$5,328.97</i> |
| EW MonitorPLS 4HR AHR-H30575 | 97407-H30575 | \$ 3,912.00 | 10% | <i>\$3,547.21</i> |
| EW MonitorPLS 4HR AHR-H30576 | 97407-H30576 | \$ 5,366.00 | 10% | <i>\$4,865.62</i> |
| EW MonitorPLS 4HR AHR-H30577 | 97407-H30577 | \$ 6,189.00 | 10% | <i>\$5,611.88</i> |
| EW MonitorPLS 4HR AHR-H30578 | 97407-H30578 | \$ 6,189.00 | 10% | <i>\$5,611.88</i> |
| EW MonitorPLS 4HR AHR-H30587 | 97407-H30587 | \$ 5,043.00 | 10% | <i>\$4,572.74</i> |
| EW MonitorPLS 4HR AHR-H30588 | 97407-H30588 | \$ 3,562.00 | 10% | <i>\$3,229.84</i> |
| EW MonitorPLS 4HR AHR-H30589 | 97407-H30589 | \$ 5,387.00 | 10% | <i>\$4,884.66</i> |
| EW MonitorPLS 4HR AHR-H30632 | 97407-H30632 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW MonitorPLS 4HR AHR-H30633 | 97407-H30633 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW MonitorPLS 4HR AHR-H30643 | 97407-H30643 | \$ 9,523.00 | 10% | <i>\$8,634.98</i> |
| EW MonitorPLS 4HR AHR-H30706 | 97407-H30706 | \$ 7,817.00 | 10% | <i>\$7,088.06</i> |
| EW MonitorPLS 4HR AHR-H30707 | 97407-H30707 | \$ 4,947.00 | 10% | <i>\$4,485.69</i> |
| EW MonitorPLS 4HR AHR-H30724 | 97407-H30724 | \$ 704.00 | 10% | <i>\$638.35</i> |
| EW MonitorPLS 4HR AHR-H30725 | 97407-H30725 | \$ 2,452.00 | 10% | <i>\$2,223.35</i> |
| EW MonitorPLS 4HR AHR-H30726 | 97407-H30726 | \$ 11,963.00 | 10% | <i>\$10,847.45</i> |

| | | | | |
|------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR-H30727 | 97407-H30727 | \$ 12,705.00 | 10% | <i>\$11,520.26</i> |
| EW MonitorPLS 4HR AHR-H30730 | 97407-H30730 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW MonitorPLS 4HR AHR-H30731 | 97407-H30731 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW MonitorPLS 4HR AHR-H30733 | 97407-H30733 | \$ 11,221.00 | 10% | <i>\$10,174.64</i> |
| EW MonitorPLS 4HR AHR-H30734 | 97407-H30734 | \$ 8,614.00 | 10% | <i>\$7,810.74</i> |
| EW MonitorPLS 4HR AHR-H30735 | 97407-H30735 | \$ 10,001.00 | 10% | <i>\$9,068.41</i> |
| EW MonitorPLS 4HR AHR-H30736 | 97407-H30736 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW MonitorPLS 4HR AHR-H30738 | 97407-H30738 | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS 4HR AHR H31337 | 97407-H31337 | \$ 10,844.00 | 10% | <i>\$9,832.80</i> |
| EW MonitorPLS 4HR AHR H31338 | 97407-H31338 | \$ 10,844.00 | 10% | <i>\$9,832.80</i> |
| EW MonitorPLS 4HR AHR H31341 | 97407-H31341 | \$ 5,794.00 | 10% | <i>\$5,253.71</i> |
| EW MonitorPLS 4HR AHR H31342 | 97407-H31342 | \$ 1,684.00 | 10% | <i>\$1,526.97</i> |
| EW MonitorPLS 4HR AHR H31343 | 97407-H31343 | \$ 2,372.00 | 10% | <i>\$2,150.81</i> |
| EW MonitorPLS 4HR AHR H31344 | 97407-H31344 | \$ 2,372.00 | 10% | <i>\$2,150.81</i> |
| EW MonitorPLS 4HR AHR H31345 | 97407-H31345 | \$ 2,372.00 | 10% | <i>\$2,150.81</i> |
| EW MonitorPLS 4HR AHR H31346 | 97407-H31346 | \$ 2,372.00 | 10% | <i>\$2,150.81</i> |
| EW MonitorPLS 4HR AHR H31362 | 97407-H31362 | \$ 29,279.00 | 10% | <i>\$26,548.73</i> |
| EW MonitorPLS 4HR AHR H31363 | 97407-H31363 | \$ 29,279.00 | 10% | <i>\$26,548.73</i> |
| EW MonitorPLS 4HR AHR H31364 | 97407-H31364 | \$ 10,693.00 | 10% | <i>\$9,695.88</i> |
| EW MonitorPLS 4HR AHR H31365 | 97407-H31365 | \$ 10,693.00 | 10% | <i>\$9,695.88</i> |
| EW MonitorPLS 4HR AHR H31366 | 97407-H31366 | \$ 14,814.00 | 10% | <i>\$13,432.59</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H31367 | 97407-H31367 | \$ 14,814.00 | 10% | <i>\$13,432.59</i> |
| EW MonitorPLS 4HR AHR H32010 | 97407-H32010 | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW MonitorPLS 4HR AHR H32011 | 97407-H32011 | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW MonitorPLS 4HR AHR H32012 | 97407-H32012 | \$ 3,681.00 | 10% | <i>\$3,337.75</i> |
| EW MonitorPLS 4HR AHR H32013 | 97407-H32013 | \$ 3,681.00 | 10% | <i>\$3,337.75</i> |
| EW MonitorPLS 4HR AHR H32014 | 97407-H32014 | \$ 3,681.00 | 10% | <i>\$3,337.75</i> |
| EW MonitorPLS 4HR AHR H32015 | 97407-H32015 | \$ 3,681.00 | 10% | <i>\$3,337.75</i> |
| EW MonitorPLS 4HR AHR H32016 | 97407-H32016 | \$ 3,312.00 | 10% | <i>\$3,003.16</i> |
| EW MonitorPLS 4HR AHR H32017 | 97407-H32017 | \$ 3,312.00 | 10% | <i>\$3,003.16</i> |
| EW MonitorPLS 4HR AHR H32018 | 97407-H32018 | \$ 3,312.00 | 10% | <i>\$3,003.16</i> |
| EW MonitorPLS 4HR AHR H32019 | 97407-H32019 | \$ 3,312.00 | 10% | <i>\$3,003.16</i> |
| EW MonitorPLS 4HR AHR H32020 | 97407-H32020 | \$ 30,210.00 | 10% | <i>\$27,392.92</i> |
| EW MonitorPLS 4HR AHR H32021 | 97407-H32021 | \$ 30,210.00 | 10% | <i>\$27,392.92</i> |
| EW MonitorPLS 4HR AHR H32022 | 97407-H32022 | \$ 30,210.00 | 10% | <i>\$27,392.92</i> |
| EW MonitorPLS 4HR AHR H32023 | 97407-H32023 | \$ 30,210.00 | 10% | <i>\$27,392.92</i> |
| EW MonitorPLS 4HR AHR H32028 | 97407-H32028 | \$ 57,185.00 | 10% | <i>\$51,852.50</i> |
| EW MonitorPLS 4HR AHR H32029 | 97407-H32029 | \$ 57,185.00 | 10% | <i>\$51,852.50</i> |
| EW MonitorPLS 4HR AHR H32030 | 97407-H32030 | \$ 59,973.00 | 10% | <i>\$54,380.52</i> |
| EW MonitorPLS 4HR AHR H32031 | 97407-H32031 | \$ 59,973.00 | 10% | <i>\$54,380.52</i> |
| EW MonitorPLS 4HR AHR H32032 | 97407-H32032 | \$ 59,973.00 | 10% | <i>\$54,380.52</i> |
| EW MonitorPLS 4HR AHR H32033 | 97407-H32033 | \$ 59,973.00 | 10% | <i>\$54,380.52</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H32038 | 97407-H32038 | \$ 10,985.00 | 10% | <i>\$9,960.65</i> |
| EW MonitorPLS 4HR AHR H32039 | 97407-H32039 | \$ 10,985.00 | 10% | <i>\$9,960.65</i> |
| EW MonitorPLS 4HR AHR H32040 | 97407-H32040 | \$ 10,985.00 | 10% | <i>\$9,960.65</i> |
| EW MonitorPLS 4HR AHR H32041 | 97407-H32041 | \$ 10,985.00 | 10% | <i>\$9,960.65</i> |
| EW MonitorPLS 4HR AHR H32046 | 97407-H32046 | \$ 15,216.00 | 10% | <i>\$13,797.11</i> |
| EW MonitorPLS 4HR AHR H32047 | 97407-H32047 | \$ 15,216.00 | 10% | <i>\$13,797.11</i> |
| EW MonitorPLS 4HR AHR H32048 | 97407-H32048 | \$ 15,216.00 | 10% | <i>\$13,797.11</i> |
| EW MonitorPLS 4HR AHR H32049 | 97407-H32049 | \$ 15,216.00 | 10% | <i>\$13,797.11</i> |
| EW MonitorPLS 4HR AHR H32054 | 97407-H32054 | \$ 10,985.00 | 10% | <i>\$9,960.65</i> |
| EW MonitorPLS 4HR AHR H32055 | 97407-H32055 | \$ 15,216.00 | 10% | <i>\$13,797.11</i> |
| EW MonitorPLS 4HR AHR H32056 | 97407-H32056 | \$ 4,242.00 | 10% | <i>\$3,846.43</i> |
| EW MonitorPLS 4HR AHR H32057 | 97407-H32057 | \$ 4,370.00 | 10% | <i>\$3,962.50</i> |
| EW MonitorPLS 4HR AHR H32058 | 97407-H32058 | \$ 4,370.00 | 10% | <i>\$3,962.50</i> |
| EW MonitorPLS 4HR AHR H32059 | 97407-H32059 | \$ 4,370.00 | 10% | <i>\$3,962.50</i> |
| EW MonitorPLS 4HR AHR H32060 | 97407-H32060 | \$ 4,262.00 | 10% | <i>\$3,864.57</i> |
| EW MonitorPLS 4HR AHR H32061 | 97407-H32061 | \$ 4,475.00 | 10% | <i>\$4,057.71</i> |
| EW MonitorPLS 4HR AHR H32062 | 97407-H32062 | \$ 4,303.00 | 10% | <i>\$3,901.75</i> |
| EW MonitorPLS 4HR AHR H32063 | 97407-H32063 | \$ 4,266.00 | 10% | <i>\$3,868.20</i> |
| EW MonitorPLS 4HR AHR H32064 | 97407-H32064 | \$ 4,303.00 | 10% | <i>\$3,901.75</i> |
| EW MonitorPLS 4HR AHR H32065 | 97407-H32065 | \$ 4,743.00 | 10% | <i>\$4,300.72</i> |
| EW MonitorPLS 4HR AHR H32066 | 97407-H32066 | \$ 4,743.00 | 10% | <i>\$4,300.72</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H32067 | 97407-H32067 | \$ 4,743.00 | 10% | <i>\$4,300.72</i> |
| EW MonitorPLS 4HR AHR H32068 | 97407-H32068 | \$ 4,743.00 | 10% | <i>\$4,300.72</i> |
| EW MonitorPLS 4HR AHR H32069 | 97407-H32069 | \$ 5,691.00 | 10% | <i>\$5,160.31</i> |
| EW MonitorPLS 4HR AHR H32070 | 97407-H32070 | \$ 5,691.00 | 10% | <i>\$5,160.31</i> |
| EW MonitorPLS 4HR AHR H32071 | 97407-H32071 | \$ 5,691.00 | 10% | <i>\$5,160.31</i> |
| EW MonitorPLS 4HR AHR H32072 | 97407-H32072 | \$ 5,691.00 | 10% | <i>\$5,160.31</i> |
| EW MonitorPLS 4HR AHR H32073 | 97407-H32073 | \$ 37,690.00 | 10% | <i>\$34,175.41</i> |
| EW MonitorPLS 4HR AHR H32074 | 97407-H32074 | \$ 37,690.00 | 10% | <i>\$34,175.41</i> |
| EW MonitorPLS 4HR AHR H32075 | 97407-H32075 | \$ 51,246.00 | 10% | <i>\$46,467.31</i> |
| EW MonitorPLS 4HR AHR H32076 | 97407-H32076 | \$ 51,246.00 | 10% | <i>\$46,467.31</i> |
| EW MonitorPLS 4HR AHR H32101 | 97407-H32101 | \$ 2,453.00 | 10% | <i>\$2,224.26</i> |
| EW MonitorPLS 4HR AHR H32102 | 97407-H32102 | \$ 2,453.00 | 10% | <i>\$2,224.26</i> |
| EW MonitorPLS 4HR AHR H32103 | 97407-H32103 | \$ 2,453.00 | 10% | <i>\$2,224.26</i> |
| EW MonitorPLS 4HR AHR H32104 | 97407-H32104 | \$ 2,453.00 | 10% | <i>\$2,224.26</i> |
| EW MonitorPLS 4HR AHR H32105 | 97407-H32105 | \$ 4,041.00 | 10% | <i>\$3,664.18</i> |
| EW MonitorPLS 4HR AHR H32106 | 97407-H32106 | \$ 4,041.00 | 10% | <i>\$3,664.18</i> |
| EW MonitorPLS 4HR AHR H32107 | 97407-H32107 | \$ 9,443.00 | 10% | <i>\$8,562.44</i> |
| EW MonitorPLS 4HR AHR H32108 | 97407-H32108 | \$ 9,443.00 | 10% | <i>\$8,562.44</i> |
| EW MonitorPLS 4HR AHR H32109 | 97407-H32109 | \$ 4,041.00 | 10% | <i>\$3,664.18</i> |
| EW MonitorPLS 4HR AHR H32110 | 97407-H32110 | \$ 4,041.00 | 10% | <i>\$3,664.18</i> |
| EW MonitorPLS 4HR AHR H32111 | 97407-H32111 | \$ 2,453.00 | 10% | <i>\$2,224.26</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS 4HR AHR H32112 | 97407-H32112 | \$ 2,453.00 | 10% | \$2,224.26 |
| EW MonitorPLS 4HR AHR H32113 | 97407-H32113 | \$ 2,453.00 | 10% | \$2,224.26 |
| EW MonitorPLS 4HR AHR H32114 | 97407-H32114 | \$ 2,453.00 | 10% | \$2,224.26 |
| EW MonitorPLS 4HR AHR H32115 | 97407-H32115 | \$ 4,041.00 | 10% | \$3,664.18 |
| EW MonitorPLS 4HR AHR H32116 | 97407-H32116 | \$ 4,041.00 | 10% | \$3,664.18 |
| EW MonitorPLS 4HR AHR H32117 | 97407-H32117 | \$ 2,357.00 | 10% | \$2,137.21 |
| EW MonitorPLS 4HR AHR H32118 | 97407-H32118 | \$ 2,357.00 | 10% | \$2,137.21 |
| EW MonitorPLS 4HR AHR H32119 | 97407-H32119 | \$ 2,357.00 | 10% | \$2,137.21 |
| EW MonitorPLS 4HR AHR H32120 | 97407-H32120 | \$ 2,357.00 | 10% | \$2,137.21 |
| EW MonitorPLS 4HR AHR H32121 | 97407-H32121 | \$ 9,443.00 | 10% | \$8,562.44 |
| EW MonitorPLS 4HR AHR H32122 | 97407-H32122 | \$ 9,443.00 | 10% | \$8,562.44 |
| EW MonitorPLS 4HR AHR H32123 | 97407-H32123 | \$ 4,041.00 | 10% | \$3,664.18 |
| EW MonitorPLS 4HR AHR H32124 | 97407-H32124 | \$ 4,041.00 | 10% | \$3,664.18 |
| EW MonitorPLS 4HR AHR H32125 | 97407-H32125 | \$ 3,941.00 | 10% | \$3,573.50 |
| EW MonitorPLS 4HR AHR H32126 | 97407-H32126 | \$ 3,941.00 | 10% | \$3,573.50 |
| EW MonitorPLS 4HR AHR H32127 | 97407-H32127 | \$ 4,494.00 | 10% | \$4,074.93 |
| EW MonitorPLS 4HR AHR H32128 | 97407-H32128 | \$ 4,494.00 | 10% | \$4,074.93 |
| EW MonitorPLS 4HR AHR H32129 | 97407-H32129 | \$ 4,494.00 | 10% | \$4,074.93 |
| EW MonitorPLS 4HR AHR H32130 | 97407-H32130 | \$ 4,494.00 | 10% | \$4,074.93 |
| EW MonitorPLS 4HR AHR H32131 | 97407-H32131 | \$ 4,494.00 | 10% | \$4,074.93 |
| EW MonitorPLS 4HR AHR H32132 | 97407-H32132 | \$ 4,494.00 | 10% | \$4,074.93 |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H32133 | 97407-H32133 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HR AHR H32134 | 97407-H32134 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HR AHR H32135 | 97407-H32135 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HR AHR H32136 | 97407-H32136 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HR AHR H32137 | 97407-H32137 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HR AHR H32138 | 97407-H32138 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HR AHR H32139 | 97407-H32139 | \$ 15,622.00 | 10% | <i>\$14,165.25</i> |
| EW MonitorPLS 4HR AHR H32140 | 97407-H32140 | \$ 15,622.00 | 10% | <i>\$14,165.25</i> |
| EW MonitorPLS 4HR AHR H32141 | 97407-H32141 | \$ 18,399.00 | 10% | <i>\$16,683.29</i> |
| EW MonitorPLS 4HR AHR H32142 | 97407-H32142 | \$ 18,399.00 | 10% | <i>\$16,683.29</i> |
| EW MonitorPLS 4HR AHR H32146 | 97407-H32146 | \$ 2,323.00 | 10% | <i>\$2,106.38</i> |
| EW MonitorPLS 4HR AHR H32147 | 97407-H32147 | \$ 2,323.00 | 10% | <i>\$2,106.38</i> |
| EW MonitorPLS 4HR AHR H32148 | 97407-H32148 | \$ 3,827.00 | 10% | <i>\$3,470.13</i> |
| EW MonitorPLS 4HR AHR H32149 | 97407-H32149 | \$ 3,827.00 | 10% | <i>\$3,470.13</i> |
| EW MonitorPLS 4HR AHR H32150 | 97407-H32150 | \$ 2,323.00 | 10% | <i>\$2,106.38</i> |
| EW MonitorPLS 4HR AHR H32152 | 97407-H32152 | \$ 1,472.00 | 10% | <i>\$1,334.74</i> |
| EW MonitorPLS 4HR AHR H32169 | 97407-H32169 | \$ 2,481.00 | 10% | <i>\$2,249.65</i> |
| EW MonitorPLS 4HR AHR H32170 | 97407-H32170 | \$ 2,481.00 | 10% | <i>\$2,249.65</i> |
| EW MonitorPLS 4HR AHR H32171 | 97407-H32171 | \$ 2,385.00 | 10% | <i>\$2,162.60</i> |
| EW MonitorPLS 4HR AHR H32172 | 97407-H32172 | \$ 2,385.00 | 10% | <i>\$2,162.60</i> |
| EW MonitorPLS 4HR AHR H32173 | 97407-H32173 | \$ 4,887.00 | 10% | <i>\$4,431.29</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H32174 | 97407-H32174 | \$ 4,887.00 | 10% | <i>\$4,431.29</i> |
| EW MonitorPLS 4HR AHR H32175 | 97407-H32175 | \$ 4,286.00 | 10% | <i>\$3,886.33</i> |
| EW MonitorPLS 4HR AHR H32176 | 97407-H32176 | \$ 4,286.00 | 10% | <i>\$3,886.33</i> |
| EW MonitorPLS 4HR AHR H32177 | 97407-H32177 | \$ 17,500.00 | 10% | <i>\$15,868.13</i> |
| EW MonitorPLS 4HR AHR H32178 | 97407-H32178 | \$ 20,611.00 | 10% | <i>\$18,689.02</i> |
| EW MonitorPLS 4HR AHR H34008 | 97407-H34008 | \$ 746.00 | 10% | <i>\$676.44</i> |
| EW MonitorPLS 4HR AHR H34009 | 97407-H34009 | \$ 853.00 | 10% | <i>\$773.46</i> |
| EW MonitorPLS 4HR AHR H34010 | 97407-H34010 | \$ 711.00 | 10% | <i>\$644.70</i> |
| EW MonitorPLS 4HR AHR H34011 | 97407-H34011 | \$ 835.00 | 10% | <i>\$757.14</i> |
| EW MonitorPLS 4HR AHR H34012 | 97407-H34012 | \$ 957.00 | 10% | <i>\$867.76</i> |
| EW MonitorPLS 4HR AHR H34013 | 97407-H34013 | \$ 790.00 | 10% | <i>\$716.33</i> |
| EW MonitorPLS 4HR AHR H34014 | 97407-H34014 | \$ 853.00 | 10% | <i>\$773.46</i> |
| EW MonitorPLS 4HR AHR H34015 | 97407-H34015 | \$ 728.00 | 10% | <i>\$660.11</i> |
| EW MonitorPLS 4HR AHR H34016 | 97407-H34016 | \$ 876.00 | 10% | <i>\$794.31</i> |
| EW MonitorPLS 4HR AHR H34017 | 97407-H34017 | \$ 1,007.00 | 10% | <i>\$913.10</i> |
| EW MonitorPLS 4HR AHR H34018 | 97407-H34018 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW MonitorPLS 4HR AHR H34019 | 97407-H34019 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW MonitorPLS 4HR AHR H34020 | 97407-H34020 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW MonitorPLS 4HR AHR H34021 | 97407-H34021 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW MonitorPLS 4HR AHR H34048 | 97407-H34048 | \$ 1,223.00 | 10% | <i>\$1,108.96</i> |
| EW MonitorPLS 4HR AHR H34049 | 97407-H34049 | \$ 1,223.00 | 10% | <i>\$1,108.96</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS 4HR AHR H34050 | 97407-H34050 | \$ 1,077.00 | 10% | \$976.57 |
| EW MonitorPLS 4HR AHR H34051 | 97407-H34051 | \$ 1,077.00 | 10% | \$976.57 |
| EW MonitorPLS 4HR AHR H34052 | 97407-H34052 | \$ 1,312.00 | 10% | \$1,189.66 |
| EW MonitorPLS 4HR AHR H34053 | 97407-H34053 | \$ 1,312.00 | 10% | \$1,189.66 |
| EW MonitorPLS 4HR AHR H34054 | 97407-H34054 | \$ 1,156.00 | 10% | \$1,048.20 |
| EW MonitorPLS 4HR AHR H34055 | 97407-H34055 | \$ 1,156.00 | 10% | \$1,048.20 |
| EW MonitorPLS 4HR AHR H34056 | 97407-H34056 | \$ 1,430.00 | 10% | \$1,296.65 |
| EW MonitorPLS 4HR AHR H34057 | 97407-H34057 | \$ 1,430.00 | 10% | \$1,296.65 |
| EW MonitorPLS 4HR AHR H34058 | 97407-H34058 | \$ 1,335.00 | 10% | \$1,210.51 |
| EW MonitorPLS 4HR AHR H34059 | 97407-H34059 | \$ 1,335.00 | 10% | \$1,210.51 |
| EW MonitorPLS 4HR AHR H34062 | 97407-H34062 | \$ 1,430.00 | 10% | \$1,296.65 |
| EW MonitorPLS 4HR AHR H34063 | 97407-H34063 | \$ 1,430.00 | 10% | \$1,296.65 |
| EW MonitorPLS 4HR AHR H34064 | 97407-H34064 | \$ 1,133.00 | 10% | \$1,027.35 |
| EW MonitorPLS 4HR AHR H34065 | 97407-H34065 | \$ 1,133.00 | 10% | \$1,027.35 |
| EW MonitorPLS 4HR AHR H34066 | 97407-H34066 | \$ 1,133.00 | 10% | \$1,027.35 |
| EW MonitorPLS 4HR AHR H34067 | 97407-H34067 | \$ 1,133.00 | 10% | \$1,027.35 |
| EW MonitorPLS 4HR AHR H34068 | 97407-H34068 | \$ 1,133.00 | 10% | \$1,027.35 |
| EW MonitorPLS 4HR AHR H34069 | 97407-H34069 | \$ 1,101.00 | 10% | \$998.33 |
| EW MonitorPLS 4HR AHR H34070 | 97407-H34070 | \$ 1,133.00 | 10% | \$1,027.35 |
| EW MonitorPLS 4HR AHR H34071 | 97407-H34071 | \$ 1,133.00 | 10% | \$1,027.35 |
| EW MonitorPLS 4HR AHR H34072 | 97407-H34072 | \$ 4,425.00 | 10% | \$4,012.37 |

| | | | | |
|---------------------------------|--------------|--------------|-----|------------|
| EW MonitorPLS 4HR AHR H34073 | 97407-H34073 | \$ 4,340.00 | 10% | \$3,935.30 |
| EW MonitorPLS 4HR AHR H34074 | 97407-H34074 | \$ 5,468.00 | 10% | \$4,958.11 |
| EW MonitorPLS 4HR AHR H34075 | 97407-H34075 | \$ 5,271.00 | 10% | \$4,779.48 |
| EW MonitorPLS 4HR AHR H34076 | 97407-H34076 | \$ 4,425.00 | 10% | \$4,012.37 |
| EW MonitorPLS 4HR AHR H34077 | 97407-H34077 | \$ 4,340.00 | 10% | \$3,935.30 |
| EW MonitorPLS 4HR AHR H34078 | 97407-H34078 | \$ 4,425.00 | 10% | \$4,012.37 |
| EW MonitorPLS 4HR AHR H34079 | 97407-H34079 | \$ 4,340.00 | 10% | \$3,935.30 |
| EW MonitorPLS 4HR AHR H34080 | 97407-H34080 | \$ 5,468.00 | 10% | \$4,958.11 |
| EW MonitorPLS 4HR AHR H34081 | 97407-H34081 | \$ 5,271.00 | 10% | \$4,779.48 |
| EW MonitorPLS 4HR AHR H34082 | 97407-H34082 | \$ 5,246.00 | 10% | \$4,756.81 |
| EW MonitorPLS 4HR AHR H34083 | 97407-H34083 | \$ 5,056.00 | 10% | \$4,584.53 |
| EW MonitorPLS 4HR AHR H34084 | 97407-H34084 | \$ 3,677.00 | 10% | \$3,334.12 |
| EW MonitorPLS 4HR AHR H34085 | 97407-H34085 | \$ 3,677.00 | 10% | \$3,334.12 |
| EW MonitorPLS 4HR AHR H34086 | 97407-H34086 | \$ 4,280.00 | 10% | \$3,880.89 |
| EW MonitorPLS 4HR AHR H34087 | 97407-H34087 | \$ 4,106.00 | 10% | \$3,723.12 |
| EW MonitorPLS 4HR AHR H34088 | 97407-H34088 | \$ 8,939.00 | 10% | \$8,105.44 |
| EW MonitorPLS 4HR AHR H34089 | 97407-H34089 | \$ 8,939.00 | 10% | \$8,105.44 |
| EW MonitorPLS 4HR AHR H34090 | 97407-H34090 | \$ 10,294.00 | 10% | \$9,334.08 |
| EW MonitorPLS 4HR AHR H34091 | 97407-H34091 | \$ 8,598.00 | 10% | \$7,796.24 |
| EW MonitorPLS 4HR AHR H34092 | 97407-H34092 | \$ 8,598.00 | 10% | \$7,796.24 |
| EW MonitorPLS 4HR AHR H34093 | 97407-H34093 | \$ 8,598.00 | 10% | \$7,796.24 |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H34094 | 97407-H34094 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34095 | 97407-H34095 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34096 | 97407-H34096 | \$ 1,112.00 | 10% | <i>\$1,008.31</i> |
| EW MonitorPLS 4HR AHR H34097 | 97407-H34097 | \$ 1,112.00 | 10% | <i>\$1,008.31</i> |
| EW MonitorPLS 4HR AHR H34098 | 97407-H34098 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34099 | 97407-H34099 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34100 | 97407-H34100 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34101 | 97407-H34101 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34102 | 97407-H34102 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34103 | 97407-H34103 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HR AHR H34104 | 97407-H34104 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW MonitorPLS 4HR AHR H34105 | 97407-H34105 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW MonitorPLS 4HR AHR H34106 | 97407-H34106 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW MonitorPLS 4HR AHR H34107 | 97407-H34107 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW MonitorPLS 4HR AHR H34108 | 97407-H34108 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW MonitorPLS 4HR AHR H34109 | 97407-H34109 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW MonitorPLS 4HR AHR H34110 | 97407-H34110 | \$ 8,282.00 | 10% | <i>\$7,509.70</i> |
| EW MonitorPLS 4HR AHR H34111 | 97407-H34111 | \$ 8,282.00 | 10% | <i>\$7,509.70</i> |
| EW MonitorPLS 4HR AHR H34112 | 97407-H34112 | \$ 8,282.00 | 10% | <i>\$7,509.70</i> |
| EW MonitorPLS 4HR AHR H34114 | 97407-H34114 | \$ 11,715.00 | 10% | <i>\$10,622.58</i> |
| EW MonitorPLS 4HR AHR H34115 | 97407-H34115 | \$ 11,474.00 | 10% | <i>\$10,404.05</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H34116 | 97407-H34116 | \$ 11,474.00 | 10% | <i>\$10,404.05</i> |
| EW MonitorPLS 4HR AHR H34117 | 97407-H34117 | \$ 11,715.00 | 10% | <i>\$10,622.58</i> |
| EW MonitorPLS 4HR AHR H34118 | 97407-H34118 | \$ 2,348.00 | 10% | <i>\$2,129.05</i> |
| EW MonitorPLS 4HR AHR H34119 | 97407-H34119 | \$ 2,348.00 | 10% | <i>\$2,129.05</i> |
| EW MonitorPLS 4HR AHR H34120 | 97407-H34120 | \$ 1,698.00 | 10% | <i>\$1,539.66</i> |
| EW MonitorPLS 4HR AHR H34121 | 97407-H34121 | \$ 1,698.00 | 10% | <i>\$1,539.66</i> |
| EW MonitorPLS 4HR AHR H34122 | 97407-H34122 | \$ 1,760.00 | 10% | <i>\$1,595.88</i> |
| EW MonitorPLS 4HR AHR H34123 | 97407-H34123 | \$ 1,760.00 | 10% | <i>\$1,595.88</i> |
| EW MonitorPLS 4HR AHR H34124 | 97407-H34124 | \$ 2,498.00 | 10% | <i>\$2,265.06</i> |
| EW MonitorPLS 4HR AHR H34125 | 97407-H34125 | \$ 2,498.00 | 10% | <i>\$2,265.06</i> |
| EW MonitorPLS 4HR AHR H34126 | 97407-H34126 | \$ 2,498.00 | 10% | <i>\$2,265.06</i> |
| EW MonitorPLS 4HR AHR H34127 | 97407-H34127 | \$ 2,498.00 | 10% | <i>\$2,265.06</i> |
| EW MonitorPLS 4HR AHR H34129 | 97407-H34129 | \$ 1,229.00 | 10% | <i>\$1,114.40</i> |
| EW MonitorPLS 4HR AHR H34130 | 97407-H34130 | \$ 1,276.00 | 10% | <i>\$1,157.01</i> |
| EW MonitorPLS 4HR AHR H34131 | 97407-H34131 | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |
| EW MonitorPLS 4HR AHR H34132 | 97407-H34132 | \$ 1,276.00 | 10% | <i>\$1,157.01</i> |
| EW MonitorPLS 4HR AHR H34172 | 97407-H34172 | \$ 2,580.00 | 10% | <i>\$2,339.42</i> |
| EW MonitorPLS 4HR AHR H34726 | 97407-H34726 | \$ 4,615.00 | 10% | <i>\$4,184.65</i> |
| EW MonitorPLS 4HR AHR H34727 | 97407-H34727 | \$ 4,615.00 | 10% | <i>\$4,184.65</i> |
| EW MonitorPLS 4HR AHR H34728 | 97407-H34728 | \$ 4,615.00 | 10% | <i>\$4,184.65</i> |
| EW MonitorPLS 4HR AHR H34729 | 97407-H34729 | \$ 4,615.00 | 10% | <i>\$4,184.65</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR H34730 | 97407-H34730 | \$ 4,898.00 | 10% | <i>\$4,441.26</i> |
| EW MonitorPLS 4HR AHR H34731 | 97407-H34731 | \$ 4,898.00 | 10% | <i>\$4,441.26</i> |
| EW MonitorPLS 4HR AHR H34732 | 97407-H34732 | \$ 4,898.00 | 10% | <i>\$4,441.26</i> |
| EW MonitorPLS 4HR AHR H34733 | 97407-H34733 | \$ 4,898.00 | 10% | <i>\$4,441.26</i> |
| EW MonitorPLS 4HR AHR H34734 | 97407-H34734 | \$ 1,324.00 | 10% | <i>\$1,200.54</i> |
| EW MonitorPLS 4HR AHR H34735 | 97407-H34735 | \$ 1,324.00 | 10% | <i>\$1,200.54</i> |
| EW MonitorPLS 4HR AHR H34736 | 97407-H34736 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H34737 | 97407-H34737 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H34738 | 97407-H34738 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34739 | 97407-H34739 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34740 | 97407-H34740 | \$ 1,324.00 | 10% | <i>\$1,200.54</i> |
| EW MonitorPLS 4HR AHR H34741 | 97407-H34741 | \$ 1,324.00 | 10% | <i>\$1,200.54</i> |
| EW MonitorPLS 4HR AHR H34742 | 97407-H34742 | \$ 1,210.00 | 10% | <i>\$1,097.17</i> |
| EW MonitorPLS 4HR AHR H34743 | 97407-H34743 | \$ 1,210.00 | 10% | <i>\$1,097.17</i> |
| EW MonitorPLS 4HR AHR H34744 | 97407-H34744 | \$ 1,483.00 | 10% | <i>\$1,344.71</i> |
| EW MonitorPLS 4HR AHR H34745 | 97407-H34745 | \$ 1,483.00 | 10% | <i>\$1,344.71</i> |
| EW MonitorPLS 4HR AHR H34746 | 97407-H34746 | \$ 1,578.00 | 10% | <i>\$1,430.85</i> |
| EW MonitorPLS 4HR AHR H34747 | 97407-H34747 | \$ 1,578.00 | 10% | <i>\$1,430.85</i> |
| EW MonitorPLS 4HR AHR H34748 | 97407-H34748 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34749 | 97407-H34749 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34750 | 97407-H34750 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |

| | | | | |
|---------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HR AHR H34751 | 97407-H34751 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34752 | 97407-H34752 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34753 | 97407-H34753 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34754 | 97407-H34754 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34755 | 97407-H34755 | \$ 2,184.00 | 10% | <i>\$1,980.34</i> |
| EW MonitorPLS 4HR AHR H34756 | 97407-H34756 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H34757 | 97407-H34757 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H34758 | 97407-H34758 | \$ 1,483.00 | 10% | <i>\$1,344.71</i> |
| EW MonitorPLS 4HR AHR H34759 | 97407-H34759 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H34760 | 97407-H34760 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H34761 | 97407-H34761 | \$ 1,483.00 | 10% | <i>\$1,344.71</i> |
| EW MonitorPLS 4HR AHR H34993 | 97407-H34993 | \$ 18,943.00 | 10% | <i>\$17,176.57</i> |
| EW MonitorPLS 4HR AHR H34994 | 97407-H34994 | \$ 18,943.00 | 10% | <i>\$17,176.57</i> |
| EW MonitorPLS 4HR AHR H34996 | 97407-H34996 | \$ 18,943.00 | 10% | <i>\$17,176.57</i> |
| EW MonitorPLS 4HR AHR H34997 | 97407-H34997 | \$ 18,943.00 | 10% | <i>\$17,176.57</i> |
| EW MonitorPLS 4HR AHR H35005 | 97407-H35005 | \$ 13,698.00 | 10% | <i>\$12,420.66</i> |
| EW MonitorPLS 4HR AHR H35006 | 97407-H35006 | \$ 13,698.00 | 10% | <i>\$12,420.66</i> |
| EW MonitorPLS 4HR AHR H35012 | 97407-H35012 | \$ 8,633.00 | 10% | <i>\$7,827.97</i> |
| EW MonitorPLS 4HR AHR H35270 | 97407-H35270 | \$ 1,312.00 | 10% | <i>\$1,189.66</i> |
| EW MonitorPLS 4HR AHR H35271 | 97407-H35271 | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW MonitorPLS 4HR AHR H35272 | 97407-H35272 | \$ 1,059.00 | 10% | <i>\$960.25</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR H35273 | 97407-H35273 | \$ 1,059.00 | 10% | <i>\$960.25</i> |
| EW MonitorPLS 4HR AHR H35274 | 97407-H35274 | \$ 1,586.00 | 10% | <i>\$1,438.11</i> |
| EW MonitorPLS 4HR AHR H35275 | 97407-H35275 | \$ 1,430.00 | 10% | <i>\$1,296.65</i> |
| EW MonitorPLS 4HR AHR H35276 | 97407-H35276 | \$ 4,425.00 | 10% | <i>\$4,012.37</i> |
| EW MonitorPLS 4HR AHR H35277 | 97407-H35277 | \$ 5,246.00 | 10% | <i>\$4,756.81</i> |
| EW MonitorPLS 4HR AHR H35278 | 97407-H35278 | \$ 3,677.00 | 10% | <i>\$3,334.12</i> |
| EW MonitorPLS 4HR AHR H35279 | 97407-H35279 | \$ 4,106.00 | 10% | <i>\$3,723.12</i> |
| EW MonitorPLS 4HR AHR H35280 | 97407-H35280 | \$ 8,124.00 | 10% | <i>\$7,366.44</i> |
| EW MonitorPLS 4HR AHR H35292 | 97407-H35292 | \$ 3,677.00 | 10% | <i>\$3,334.12</i> |
| EW MonitorPLS 4HR AHR H35293 | 97407-H35293 | \$ 4,106.00 | 10% | <i>\$3,723.12</i> |
| EW MonitorPLS 4HR AHR H35295 | 97407-H35295 | \$ 1,169.00 | 10% | <i>\$1,059.99</i> |
| EW MonitorPLS 4HR AHR H35302 | 97407-H35302 | \$ 3,509.00 | 10% | <i>\$3,181.79</i> |
| EW MonitorPLS 4HR AHR H35303 | 97407-H35303 | \$ 3,509.00 | 10% | <i>\$3,181.79</i> |
| EW MonitorPLS 4HR AHR H35304 | 97407-H35304 | \$ 3,509.00 | 10% | <i>\$3,181.79</i> |
| EW MonitorPLS 4HR AHR H35305 | 97407-H35305 | \$ 3,647.00 | 10% | <i>\$3,306.92</i> |
| EW MonitorPLS 4HR AHR H35306 | 97407-H35306 | \$ 3,647.00 | 10% | <i>\$3,306.92</i> |
| EW MonitorPLS 4HR AHR H35307 | 97407-H35307 | \$ 3,647.00 | 10% | <i>\$3,306.92</i> |
| EW MonitorPLS 4HR AHR H35309 | 97407-H35309 | \$ 4,537.00 | 10% | <i>\$4,113.92</i> |
| EW MonitorPLS 4HR AHR H35310 | 97407-H35310 | \$ 4,537.00 | 10% | <i>\$4,113.92</i> |
| EW MonitorPLS 4HR AHR H35311 | 97407-H35311 | \$ 4,537.00 | 10% | <i>\$4,113.92</i> |
| EW MonitorPLS 4HR AHR H35312 | 97407-H35312 | \$ 3,747.00 | 10% | <i>\$3,397.59</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR H35313 | 97407-H35313 | \$ 3,747.00 | 10% | <i>\$3,397.59</i> |
| EW MonitorPLS 4HR AHR H35314 | 97407-H35314 | \$ 3,747.00 | 10% | <i>\$3,397.59</i> |
| EW MonitorPLS 4HR AHR H35315 | 97407-H35315 | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |
| EW MonitorPLS 4HR AHR H35318 | 97407-H35318 | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW MonitorPLS 4HR AHR H35319 | 97407-H35319 | \$ 1,500.00 | 10% | <i>\$1,360.13</i> |
| EW MonitorPLS 4HR AHR H35320 | 97407-H35320 | \$ 1,531.00 | 10% | <i>\$1,388.23</i> |
| EW MonitorPLS 4HR AHR H35321 | 97407-H35321 | \$ 1,798.00 | 10% | <i>\$1,630.34</i> |
| EW MonitorPLS 4HR AHR H35322 | 97407-H35322 | \$ 2,087.00 | 10% | <i>\$1,892.39</i> |
| EW MonitorPLS 4HR AHR H35323 | 97407-H35323 | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |
| EW MonitorPLS 4HR AHR H35328 | 97407-H35328 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW MonitorPLS 4HR AHR H35330 | 97407-H35330 | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HR AHR H35340 | 97407-H35340 | \$ 3,942.00 | 10% | <i>\$3,574.41</i> |
| EW MonitorPLS 4HR AHR H35341 | 97407-H35341 | \$ 3,942.00 | 10% | <i>\$3,574.41</i> |
| EW MonitorPLS 4HR AHR H35342 | 97407-H35342 | \$ 3,375.00 | 10% | <i>\$3,060.28</i> |
| EW MonitorPLS 4HR AHR H35343 | 97407-H35343 | \$ 3,942.00 | 10% | <i>\$3,574.41</i> |
| EW MonitorPLS 4HR AHR H35344 | 97407-H35344 | \$ 4,079.00 | 10% | <i>\$3,698.63</i> |
| EW MonitorPLS 4HR AHR H35345 | 97407-H35345 | \$ 4,079.00 | 10% | <i>\$3,698.63</i> |
| EW MonitorPLS 4HR AHR H35346 | 97407-H35346 | \$ 3,479.00 | 10% | <i>\$3,154.58</i> |
| EW MonitorPLS 4HR AHR H35347 | 97407-H35347 | \$ 4,079.00 | 10% | <i>\$3,698.63</i> |
| EW MonitorPLS 4HR AHR H35349 | 97407-H35349 | \$ 4,412.00 | 10% | <i>\$4,000.58</i> |
| EW MonitorPLS 4HR AHR H35350 | 97407-H35350 | \$ 4,412.00 | 10% | <i>\$4,000.58</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR H35351 | 97407-H35351 | \$ 3,749.00 | 10% | <i>\$3,399.41</i> |
| EW MonitorPLS 4HR AHR H35352 | 97407-H35352 | \$ 4,412.00 | 10% | <i>\$4,000.58</i> |
| EW MonitorPLS 4HR AHR H35359 | 97407-H35359 | \$ 1,798.00 | 10% | <i>\$1,630.34</i> |
| EW MonitorPLS 4HR AHR H35360 | 97407-H35360 | \$ 2,087.00 | 10% | <i>\$1,892.39</i> |
| EW MonitorPLS 4HR AHR H35361 | 97407-H35361 | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |
| EW MonitorPLS 4HR AHR H35362 | 97407-H35362 | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW MonitorPLS 4HR AHR H35366 | 97407-H35366 | \$ 1,643.00 | 10% | <i>\$1,489.79</i> |
| EW MonitorPLS 4HR AHR H35367 | 97407-H35367 | \$ 1,919.00 | 10% | <i>\$1,740.05</i> |
| EW MonitorPLS 4HR AHR H35368 | 97407-H35368 | \$ 2,921.00 | 10% | <i>\$2,648.62</i> |
| EW MonitorPLS 4HR AHR H35369 | 97407-H35369 | \$ 953.00 | 10% | <i>\$864.13</i> |
| EW MonitorPLS 4HR AHR H35370 | 97407-H35370 | \$ 1,332.00 | 10% | <i>\$1,207.79</i> |
| EW MonitorPLS 4HR AHR H35375 | 97407-H35375 | \$ 1,031.00 | 10% | <i>\$934.86</i> |
| EW MonitorPLS 4HR AHR H35376 | 97407-H35376 | \$ 1,540.00 | 10% | <i>\$1,396.40</i> |
| EW MonitorPLS 4HR AHR H35377 | 97407-H35377 | \$ 643.00 | 10% | <i>\$583.04</i> |
| EW MonitorPLS 4HR AHR H35378 | 97407-H35378 | \$ 1,031.00 | 10% | <i>\$934.86</i> |
| EW MonitorPLS 4HR AHR H35379 | 97407-H35379 | \$ 643.00 | 10% | <i>\$583.04</i> |
| EW MonitorPLS 4HR AHR H35380 | 97407-H35380 | \$ 1,158.00 | 10% | <i>\$1,050.02</i> |
| EW MonitorPLS 4HR AHR H35381 | 97407-H35381 | \$ 1,412.00 | 10% | <i>\$1,280.33</i> |
| EW MonitorPLS 4HR AHR H35384 | 97407-H35384 | \$ 522.00 | 10% | <i>\$473.32</i> |
| EW MonitorPLS 4HR AHR H35385 | 97407-H35385 | \$ 693.00 | 10% | <i>\$628.38</i> |
| EW MonitorPLS 4HR AHR H35386 | 97407-H35386 | \$ 1,151.00 | 10% | <i>\$1,043.67</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS 4HR AHR H35387 | 97407-H35387 | \$ 1,077.00 | 10% | \$976.57 |
| EW MonitorPLS 4HR AHR H35388 | 97407-H35388 | \$ 795.00 | 10% | \$720.87 |
| EW MonitorPLS 4HR AHR H35389 | 97407-H35389 | \$ 446.00 | 10% | \$404.41 |
| EW MonitorPLS 4HR AHR H35390 | 97407-H35390 | \$ 387.00 | 10% | \$350.91 |
| EW MonitorPLS 4HR AHR H35391 | 97407-H35391 | \$ 852.00 | 10% | \$772.55 |
| EW MonitorPLS 4HR AHR H35392 | 97407-H35392 | \$ 1,298.00 | 10% | \$1,176.96 |
| EW MonitorPLS 4HR AHR H35393 | 97407-H35393 | \$ 1,729.00 | 10% | \$1,567.77 |
| EW MonitorPLS 4HR AHR H35394 | 97407-H35394 | \$ 312.00 | 10% | \$282.91 |
| EW MonitorPLS 4HR AHR H35395 | 97407-H35395 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS 4HR AHR H35396 | 97407-H35396 | \$ 312.00 | 10% | \$282.91 |
| EW MonitorPLS 4HR AHR H35397 | 97407-H35397 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS 4HR AHR H35398 | 97407-H35398 | \$ 807.00 | 10% | \$731.75 |
| EW MonitorPLS 4HR AHR H35399 | 97407-H35399 | \$ 980.00 | 10% | \$888.62 |
| EW MonitorPLS 4HR AHR H35400 | 97407-H35400 | \$ 1,082.00 | 10% | \$981.10 |
| EW MonitorPLS 4HR AHR H35401 | 97407-H35401 | \$ 579.00 | 10% | \$525.01 |
| EW MonitorPLS 4HR AHR H35415 | 97407-H35415 | \$ 353.00 | 10% | \$320.08 |
| EW MonitorPLS 4HR AHR H35416 | 97407-H35416 | \$ 353.00 | 10% | \$320.08 |
| EW MonitorPLS 4HR AHR H35426 | 97407-H35426 | \$ 446.00 | 10% | \$404.41 |
| EW MonitorPLS 4HR AHR H35427 | 97407-H35427 | \$ 1,077.00 | 10% | \$976.57 |
| EW MonitorPLS 4HR AHR H35428 | 97407-H35428 | \$ 387.00 | 10% | \$350.91 |
| EW MonitorPLS 4HR AHR H35429 | 97407-H35429 | \$ 852.00 | 10% | \$772.55 |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR H35430 | 97407-H35430 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS 4HR AHR H35431 | 97407-H35431 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS 4HR AHR H35432 | 97407-H35432 | \$ 1,210.00 | 10% | <i>\$1,097.17</i> |
| EW MonitorPLS 4HR AHR H35433 | 97407-H35433 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS 4HR AHR H35434 | 97407-H35434 | \$ 1,539.00 | 10% | <i>\$1,395.49</i> |
| EW MonitorPLS 4HR AHR H35435 | 97407-H35435 | \$ 1,539.00 | 10% | <i>\$1,395.49</i> |
| EW MonitorPLS 4HR AHR H35436 | 97407-H35436 | \$ 2,120.00 | 10% | <i>\$1,922.31</i> |
| EW MonitorPLS 4HR AHR H35437 | 97407-H35437 | \$ 2,120.00 | 10% | <i>\$1,922.31</i> |
| EW MonitorPLS 4HR AHR H35438 | 97407-H35438 | \$ 2,120.00 | 10% | <i>\$1,922.31</i> |
| EW MonitorPLS 4HR AHR H35439 | 97407-H35439 | \$ 2,120.00 | 10% | <i>\$1,922.31</i> |
| EW MonitorPLS 4HR AHR H35440 | 97407-H35440 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS 4HR AHR H35441 | 97407-H35441 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS 4HR AHR H35442 | 97407-H35442 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW MonitorPLS 4HR AHR H35443 | 97407-H35443 | \$ 4,615.00 | 10% | <i>\$4,184.65</i> |
| EW MonitorPLS 4HR AHR H35444 | 97407-H35444 | \$ 4,898.00 | 10% | <i>\$4,441.26</i> |
| EW MonitorPLS 4HR AHR H35445 | 97407-H35445 | \$ 4,425.00 | 10% | <i>\$4,012.37</i> |
| EW MonitorPLS 4HR AHR H35446 | 97407-H35446 | \$ 4,340.00 | 10% | <i>\$3,935.30</i> |
| EW MonitorPLS 4HR AHR H35447 | 97407-H35447 | \$ 4,971.00 | 10% | <i>\$4,507.45</i> |
| EW MonitorPLS 4HR AHR H35448 | 97407-H35448 | \$ 4,792.00 | 10% | <i>\$4,345.15</i> |
| EW MonitorPLS 4HR AHR H35449 | 97407-H35449 | \$ 3,677.00 | 10% | <i>\$3,334.12</i> |
| EW MonitorPLS 4HR AHR H35450 | 97407-H35450 | \$ 3,891.00 | 10% | <i>\$3,528.16</i> |

| | | | | |
|---|-------------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR H35451 | 97407-H35451 | \$ 8,598.00 | 10% | <i>\$7,796.24</i> |
| EW MonitorPLS 4HR AHR H35452 | 97407-H35452 | \$ 8,598.00 | 10% | <i>\$7,796.24</i> |
| EW MonitorPLS 4HR AHR H35453 | 97407-H35453 | \$ 4,898.00 | 10% | <i>\$4,441.26</i> |
| EW MonitorPLS 4HR AHR H35454 | 97407-H35454 | \$ 4,615.00 | 10% | <i>\$4,184.65</i> |
| EW MonitorPLS 4HR AHR H35455 | 97407-H35455 | \$ 1,531.00 | 10% | <i>\$1,388.23</i> |
| EW MonitorPLS 4HR AHR H35456 | 97407-H35456 | \$ 1,744.00 | 10% | <i>\$1,581.37</i> |
| EW MonitorPLS 4HR AHR H35457 | 97407-H35457 | \$ 1,641.00 | 10% | <i>\$1,487.98</i> |
| EW MonitorPLS 4HR AHR H35458 | 97407-H35458 | \$ 1,741.00 | 10% | <i>\$1,578.65</i> |
| EW MonitorPLS 4HR AHR H35471 | 97407-H35471 | \$ 1,531.00 | 10% | <i>\$1,388.23</i> |
| EW MonitorPLS 4HR AHR H35600 | 97407-H35600 | \$ 1,059.00 | 10% | <i>\$960.25</i> |
| EW MonitorPLS 4HR AHR H35601 | 97407-H35601 | \$ 1,059.00 | 10% | <i>\$960.25</i> |
| EW MonitorPLS 4HR AHR H35602 | 97407-H35602 | \$ 1,324.00 | 10% | <i>\$1,200.54</i> |
| EW MonitorPLS 4HR AHR H35603 | 97407-H35603 | \$ 1,324.00 | 10% | <i>\$1,200.54</i> |
| EW MonitorPLS 4HR AHR H35604 | 97407-H35604 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H35605 | 97407-H35605 | \$ 1,490.00 | 10% | <i>\$1,351.06</i> |
| EW MonitorPLS 4HR AHR H35606 | 97407-H35606 | \$ 1,586.00 | 10% | <i>\$1,438.11</i> |
| EW MonitorPLS 4HR AHR H35607 | 97407-H35607 | \$ 1,578.00 | 10% | <i>\$1,430.85</i> |
| EW MonitorPLS 4HR AHR ISW- 24W-4X | 97407-ISW- 24W-4X | \$ 1,480.00 | 10% | <i>\$1,341.99</i> |
| EW MonitorPLS 4HR AHR ISW- 4W-4WS-4X | 97407-ISW-4W- 4WS-4X | \$ 1,108.00 | 10% | <i>\$1,004.68</i> |
| EW MonitorPLUS 4HR AHR- MS128 | 97407- MSM128 | \$ 3,340.00 | 10% | <i>\$3,028.55</i> |
| EW MonitorPLS 4HR AHR- MSM48C | 97407- MSM48C | \$ 2,186.00 | 10% | <i>\$1,982.16</i> |

| | | | | |
|--|---------------------------------|--------------|-----|-------------|
| EW MonitorPLS 4HR AHR SLX9150-48XT-DC-F | 97407- SLX9150- 48XT-DC-F | \$ 3,558.00 | 10% | \$3,226.22 |
| EW MonitorPLS 4HR AHR SLX9150-48XT-DC-R | 97407- SLX9150- 48XT-DC-R | \$ 3,885.00 | 10% | \$3,522.72 |
| EW MonitorPLS 4HR AHR SLX9150-48Y-DC-F | 97407- SLX9150-48Y- DC-F | \$ 3,438.00 | 10% | \$3,117.41 |
| EW MonitorPLS 4HR AHR SLX9150-48Y-DC-R | 97407- SLX9150-48Y- DC-R | \$ 3,755.00 | 10% | \$3,404.85 |
| EW MonitorPLS 4HR AHR SLX9740-40C | 97407- SLX9740-40C | \$ 12,825.00 | 10% | \$11,629.07 |
| EW MonitorPLS 4HR AHR SLX9740-40C-AC-F | 97407- SLX9740-40C- AC-F | \$ 12,825.00 | 10% | \$11,629.07 |
| EW MonitorPLS 4HR AHR SLX9740-40C-AC-R | 97407- SLX9740-40C- AC-R | \$ 12,825.00 | 10% | \$11,629.07 |
| EW MonitorPLS 4HR AHR SLX9740-40C-DC-F | 97407- SLX9740-40C- DC-F | \$ 12,825.00 | 10% | \$11,629.07 |
| EW MonitorPLS 4HR AHR SLX9740-80C | 97407- SLX9740-80C | \$ 23,568.00 | 10% | \$21,370.28 |
| EW MonitorPLS 4HR AHR SLX9740-80C-AC-F | 97407- SLX9740-80C- AC-F | \$ 23,568.00 | 10% | \$21,370.28 |
| EW MonitorPLS 4HR AHR SLX9740-80C-AC-R | 97407- SLX9740-80C- AC-R | \$ 23,568.00 | 10% | \$21,370.28 |
| EW MonitorPLS 4HR AHR SLX9740-80C-DC-F | 97407- SLX9740-80C- DC-F | \$ 23,568.00 | 10% | \$21,370.28 |
| EW MonitorPLS 4HR AHR V300-8P-2X | 97407-V300- 8P-2X | \$ 570.00 | 10% | \$516.85 |
| EW MonitorPLS 4HR AHR V300-8T-2X | 97407-V300- 8T-2X | \$ 520.00 | 10% | \$471.51 |
| EW MonitorPLS 4HR AHR V300HT-8P-2X | 97407-V300HT- 8P-2X | \$ 776.00 | 10% | \$703.64 |

| | | | | |
|--|---|-------------|-----|------------|
| EW MonitorPLS 4HR AHR V300HT-8T-2X | 97407-V300HT- 8T-2X | \$ 628.00 | 10% | \$569.44 |
| EW MonitorPLS 4HR AHR- VIM-SS | 97407-VIM-SS | \$ 419.00 | 10% | \$379.93 |
| EW MonitorPLS 4HR AHRVIMSSV80 | 97407-VIM- SSV80 | \$ 558.00 | 10% | \$505.97 |
| EW MonitorPLS 4HR AHR- VIM2-SS | 97407-VIM2- SS | \$ 432.00 | 10% | \$391.72 |
| EW MonitorPLS 4HR AHRVIM2SS128 | 97407-VIM2- SS128 | \$ 895.00 | 10% | \$811.54 |
| EW MonitorPLS 4HR AHR- VIM2-V80 | 97407-VIM2- V80 | \$ 956.00 | 10% | \$866.85 |
| EW MonitorPLS 4HR AHRVIM210G4X | 97407- VIM210G4X | \$ 1,454.00 | 10% | \$1,318.41 |
| EW MonPLS 4HR AHR VSP4900-12MXU-12XE | 97407- VSP4900- 12MXU-12XE | \$ 1,885.00 | 10% | \$1,709.22 |
| EW MonPLS 4HR AHR VSP4900-12MXU-12XE-B1 | 97407- VSP4900- 12MXU-12XE- B1 | \$ 1,885.00 | 10% | \$1,709.22 |
| EW MonitorPLS 4HR AHR VSP4900-24S | 97407- VSP4900-24S | \$ 1,272.00 | 10% | \$1,153.39 |
| EW MonitorPLS 4HR AHR VSP4900-24S-B3 | 97407- VSP4900-24S- B3 | \$ 1,272.00 | 10% | \$1,153.39 |
| EW MonitorPLS 4HR AHR VSP4900-24XE | 97407- VSP4900- 24XE | \$ 1,885.00 | 10% | \$1,709.22 |
| EW MonitorPLS 4HR AHR VSP4900-24XE-B3 | 97407- VSP4900- 24XE-B3 | \$ 1,885.00 | 10% | \$1,709.22 |
| EW MonitorPLS 4HR AHR X435-24P-4S | 97407-X435- 24P-4S | \$ 693.00 | 10% | \$628.38 |
| EW MonitorPLS 4HR AHR X435-24T-4S | 97407-X435- 24T-4S | \$ 565.00 | 10% | \$512.31 |
| EW MonitorPLS 4HR AHR X435-8P-2T-W | 97407-X435- 8P-2T-W | \$ 565.00 | 10% | \$512.31 |
| EW MonitorPLS 4HR AHR X435-8P-4S | 97407-X435- 8P-4S | \$ 548.00 | 10% | \$496.90 |
| EW MonitorPLS 4HR AHR X435-8T-4S | 97407-X435- 8T-4S | \$ 521.00 | 10% | \$472.42 |

| | | | | |
|---------------------------------------|-----------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR-X460-24P | 97407-X460-24P | \$ 1,901.00 | 10% | <i>\$1,723.73</i> |
| EW MonitorPLS 4HR AHR-X460-24T | 97407-X460-24T | \$ 1,549.00 | 10% | <i>\$1,404.56</i> |
| EW MonitorPLS 4HR AHR-X460-24 | 97407-X460-24TDC | \$ 1,960.00 | 10% | <i>\$1,777.23</i> |
| EW MonitorPLS 4HR AHR-X460-24X | 97407-X460-24X | \$ 2,231.00 | 10% | <i>\$2,022.96</i> |
| EW MonitorPLS 4HR AHR-X460-24 | 97407-X460-24XDC | \$ 2,444.00 | 10% | <i>\$2,216.10</i> |
| EW MonitorPLS 4HR AHR-X460-48P | 97407-X460-48P | \$ 2,231.00 | 10% | <i>\$2,022.96</i> |
| EW MonitorPLS 4HR AHR-X460-48T | 97407-X460-48T | \$ 2,020.00 | 10% | <i>\$1,831.64</i> |
| EW MonitorPLS 4HR AHR-X46048 | 97407-X460-48TDC | \$ 2,394.00 | 10% | <i>\$2,170.76</i> |
| EW MonitorPLS 4HR AHR-X460-48X | 97407-X460-48X | \$ 2,717.00 | 10% | <i>\$2,463.64</i> |
| EW MonitorPLS 4HR AHR-X46048 | 97407-X460-48XDC | \$ 2,717.00 | 10% | <i>\$2,463.64</i> |
| EW MonitorPLS 4HR AHR X465-24MU | 97407-X465-24MU | \$ 2,087.00 | 10% | <i>\$1,892.39</i> |
| EW MonitorPLS 4HR AHR X465-24S | 97407-X465-24S | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW MonitorPLS 4HR AHR X465-24S-B3 | 97407-X465-24S-B3 | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW MonitorPLS 4HR AHR X465-24W | 97407-X465-24W | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW MonitorPLS 4HR AHR X465-24XE | 97407-X465-24XE | \$ 1,885.00 | 10% | <i>\$1,709.22</i> |
| EW MonitorPLS 4HR AHR X465-24XE-B3 | 97407-X465-24XE-B3 | \$ 1,885.00 | 10% | <i>\$1,709.22</i> |
| EW MonitorPLS 4HR AHR X465-48P | 97407-X465-48P | \$ 1,531.00 | 10% | <i>\$1,388.23</i> |
| EW MonitorPLS 4HR AHR X465-48T | 97407-X465-48T | \$ 1,500.00 | 10% | <i>\$1,360.13</i> |
| EW MonitorPLS 4HR AHR X465-48W | 97407-X465-48W | \$ 1,798.00 | 10% | <i>\$1,630.34</i> |
| EW MonitorPLS 4HR AHR X465i-48W | 97407-X465i-48W | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |
| EW MonitorPLS 4HR AHR X465i-48W-B1-S1 | 97407-X465i-48W-B1-S1 | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HR AHR X465i-48W-B2-S1 | 97407-X465i- 48W-B2-S1 | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |
| EW MonitorPLS 4HR AHR- X480-24X | 97407-X480- 24X | \$ 2,472.00 | 10% | <i>\$2,241.49</i> |
| EW MonitorPLUS 4HR AHR- X480T | 97407-X480- 48T | \$ 2,239.00 | 10% | <i>\$2,030.21</i> |
| EW MonitorPLS 4HR AHR- X48048 | 97407-X480- 48X | \$ 3,077.00 | 10% | <i>\$2,790.07</i> |
| EW MonitorPLS 4HR AHR X695-48Y-8C | 97407-X695- 48Y-8C | \$ 3,786.00 | 10% | <i>\$3,432.96</i> |
| EW MonitorPLS 4HR AHR XA1440 | 97407-XA1440 | \$ 744.00 | 10% | <i>\$674.62</i> |
| EW MonitorPLS 4HR AHR XA1480 | 97407-XA1480 | \$ 863.00 | 10% | <i>\$782.53</i> |
| EW MonitorPLS 4HR AHR- XGM3-2SF | 97407-XGM3- 2SF | \$ 558.00 | 10% | <i>\$505.97</i> |
| EW MonitorPLS 4HR AHR XR600 | 97407-XR600 | \$ 733.00 | 10% | <i>\$664.65</i> |
| EW MonitorPLS 4HROnsite 1130C | 97408-1130C | \$ 2,523.00 | 6% | <i>\$2,389.41</i> |
| EW MonitorPLS 4HROnsite- 16119 | 97408-16119 | \$ 677.00 | 10% | <i>\$613.87</i> |
| EW MonitorPLS 4HROnsite- 16120 | 97408-16120 | \$ 782.00 | 10% | <i>\$709.08</i> |
| EW MonitorPLS 4HROnsite- 16126 | 97408-16126 | \$ 677.00 | 10% | <i>\$613.87</i> |
| EW MonitorPLS 4HROnsite- 16127 | 97408-16127 | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW MonitorPLS 4HROnsite- 16172 | 97408-16172 | \$ 1,205.00 | 10% | <i>\$1,092.63</i> |
| EW MonitorPLS 4HROnsite 16172T | 97408-16172T | \$ 1,323.00 | 10% | <i>\$1,199.63</i> |
| EW MonitorPLS 4HROnsite- 16173 | 97408-16173 | \$ 1,220.00 | 10% | <i>\$1,106.24</i> |
| EW MonitorPLS 4HROnsite 16173T | 97408-16173T | \$ 1,337.00 | 10% | <i>\$1,212.32</i> |
| EW MonitorPLS 4HROnsite- 16174 | 97408-16174 | \$ 1,437.00 | 10% | <i>\$1,303.00</i> |
| EW MonitorPLS 4HROnsite- 16175 | 97408-16175 | \$ 1,508.00 | 10% | <i>\$1,367.38</i> |
| EW MonitorPLS 4HROnsite- 16176 | 97408-16176 | \$ 1,419.00 | 10% | <i>\$1,286.68</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite-16177 | 97408-16177 | \$ 1,350.00 | 10% | <i>\$1,224.11</i> |
| EW MonitorPLS 4HROnsite 16177T | 97408-16177T | \$ 1,588.00 | 10% | <i>\$1,439.92</i> |
| EW MonitorPLS 4HROnsite-16178 | 97408-16178 | \$ 1,714.00 | 10% | <i>\$1,554.17</i> |
| EW MonitorPLS 4HROnsite-16179 | 97408-16179 | \$ 1,736.00 | 10% | <i>\$1,574.12</i> |
| EW MonitorPLS 4HROnsite 16179T | 97408-16179T | \$ 1,915.00 | 10% | <i>\$1,736.43</i> |
| EW MonitorPLS 4HROnsite-16301T | 97408-16301T | \$ 3,208.00 | 10% | <i>\$2,908.85</i> |
| EW MonitorPLS 4HROnsite-16303T | 97408-16303T | \$ 3,208.00 | 10% | <i>\$2,908.85</i> |
| EW MonitorPLS 4HROnsite-16304T | 97408-16304T | \$ 4,060.00 | 10% | <i>\$3,681.41</i> |
| EW MonitorPLS 4HROnsite-16401T | 97408-16401T | \$ 1,945.00 | 10% | <i>\$1,763.63</i> |
| EW MonitorPLS 4HROnsite-16402T | 97408-16402T | \$ 2,561.00 | 10% | <i>\$2,322.19</i> |
| EW MonitorPLS 4HROnsite-16403T | 97408-16403T | \$ 2,356.00 | 10% | <i>\$2,136.30</i> |
| EW MonitorPLS 4HROnsite-16404T | 97408-16404T | \$ 2,356.00 | 10% | <i>\$2,136.30</i> |
| EW MonitorPLS 4HROnsite-16405T | 97408-16405T | \$ 2,863.00 | 10% | <i>\$2,596.03</i> |
| EW MonitorPLS 4HROnsite-16406T | 97408-16406T | \$ 3,574.00 | 10% | <i>\$3,240.72</i> |
| EW MonitorPLS 4HROnsite-16431 | 97408-16431 | \$ 2,495.00 | 10% | <i>\$2,262.34</i> |
| EW MonitorPLS 4HROnsite-16432 | 97408-16432 | \$ 2,653.00 | 10% | <i>\$2,405.61</i> |
| EW MonitorPLS 4HROnsite-16440 | 97408-16440 | \$ 1,821.00 | 10% | <i>\$1,651.19</i> |
| EW MonitorPLS 4HROnsite-16441 | 97408-16441 | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW MonitorPLS 4HROnsite-16442 | 97408-16442 | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW MonitorPLS 4HROnsite-16444 | 97408-16444 | \$ 483.00 | 10% | <i>\$437.96</i> |
| EW MonitorPLS 4HROnsite-16501 | 97408-16501 | \$ 999.00 | 10% | <i>\$905.84</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite-16501T | 97408-16501T | \$ 1,074.00 | 10% | <i>\$973.85</i> |
| EW MonitorPLS 4HROnsite-16502 | 97408-16502 | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW MonitorPLS 4HROnsite-16502T | 97408-16502T | \$ 1,183.00 | 10% | <i>\$1,072.69</i> |
| EW MonitorPLS 4HROnsite-16503 | 97408-16503 | \$ 1,051.00 | 10% | <i>\$952.99</i> |
| EW MonitorPLS 4HROnsite-16503T | 97408-16503T | \$ 1,145.00 | 10% | <i>\$1,038.23</i> |
| EW MonitorPLS 4HROnsite-16504 | 97408-16504 | \$ 1,234.00 | 10% | <i>\$1,118.93</i> |
| EW MonitorPLS 4HROnsite-16504T | 97408-16504T | \$ 1,329.00 | 10% | <i>\$1,205.07</i> |
| EW MonitorPLS 4HROnsite-16505 | 97408-16505 | \$ 1,275.00 | 10% | <i>\$1,156.11</i> |
| EW MonitorPLS 4HROnsite-16505T | 97408-16505T | \$ 1,410.00 | 10% | <i>\$1,278.52</i> |
| EW MonitorPLS 4HROnsite-16506 | 97408-16506 | \$ 1,555.00 | 10% | <i>\$1,410.00</i> |
| EW MonitorPLS 4HROnsite-16506T | 97408-16506T | \$ 1,755.00 | 10% | <i>\$1,591.35</i> |
| EW MonitorPLS 4HROnsite-16507 | 97408-16507 | \$ 1,498.00 | 10% | <i>\$1,358.31</i> |
| EW MonitorPLS 4HROnsite-16507T | 97408-16507T | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW MonitorPLS 4HROnsite-16508 | 97408-16508 | \$ 1,690.00 | 10% | <i>\$1,532.41</i> |
| EW MonitorPLS 4HROnsite-16508T | 97408-16508T | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-16509 | 97408-16509 | \$ 1,690.00 | 10% | <i>\$1,532.41</i> |
| EW MonitorPLS 4HROnsite-16509T | 97408-16509T | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-16510 | 97408-16510 | \$ 1,865.00 | 10% | <i>\$1,691.09</i> |
| EW MonitorPLS 4HROnsite-16510T | 97408-16510T | \$ 2,085.00 | 10% | <i>\$1,890.57</i> |
| EW MonitorPLS 4HROnsite-16513 | 97408-16513 | \$ 1,498.00 | 10% | <i>\$1,358.31</i> |
| EW MonitorPLS 4HROnsite-16514 | 97408-16514 | \$ 1,828.00 | 10% | <i>\$1,657.54</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HRonsite-16515 | 97408-16515 | \$ 895.00 | 10% | <i>\$811.54</i> |
| EW MonitorPLS 4HRonsite-16516 | 97408-16516 | \$ 913.00 | 10% | <i>\$827.86</i> |
| EW MonitorPLS 4HRonsite-16517 | 97408-16517 | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |
| EW MonitorPLS 4HRonsite-16518 | 97408-16518 | \$ 1,066.00 | 10% | <i>\$966.60</i> |
| EW MonitorPLS 4HRonsite-16519 | 97408-16519 | \$ 1,123.00 | 10% | <i>\$1,018.28</i> |
| EW MonitorPLS 4HRonsite-16520 | 97408-16520 | \$ 1,357.00 | 10% | <i>\$1,230.46</i> |
| EW MonitorPLUS 4HRonsite-16530 | 97408-16530 | \$ 1,003.00 | 10% | <i>\$909.47</i> |
| EW MonitorPLUS 4HRonsite-16531 | 97408-16531 | \$ 1,087.00 | 10% | <i>\$985.64</i> |
| EW MonitorPLUS 4HRonsite16531T | 97408-16531T | \$ 1,117.00 | 10% | <i>\$1,012.84</i> |
| EW MonitorPLUS 4HRonsite-16532 | 97408-16532 | \$ 1,087.00 | 10% | <i>\$985.64</i> |
| EW MonitorPLUS 4HRonsite16532T | 97408-16532T | \$ 1,117.00 | 10% | <i>\$1,012.84</i> |
| EW MonitorPLUS 4HRonsite-16533 | 97408-16533 | \$ 1,209.00 | 10% | <i>\$1,096.26</i> |
| EW MonitorPLUS 4HRonsite16533T | 97408-16533T | \$ 1,255.00 | 10% | <i>\$1,137.97</i> |
| EW MonitorPLUS 4HRonsite-16534 | 97408-16534 | \$ 1,240.00 | 10% | <i>\$1,124.37</i> |
| EW MonitorPLUS 4HRonsite-16535 | 97408-16535 | \$ 1,460.00 | 10% | <i>\$1,323.86</i> |
| EW MonitorPLUS 4HRonsite-16535A | 97408-16535A | \$ 1,460.00 | 10% | <i>\$1,323.86</i> |
| EW MonitorPLUS 4HRonsite16535T | 97408-16535T | \$ 1,542.00 | 10% | <i>\$1,398.21</i> |
| EW MonitorPLUS 4HRonsite-16536 | 97408-16536 | \$ 1,022.00 | 10% | <i>\$926.70</i> |
| EW MonitorPLUS 4HRonsite-16537 | 97408-16537 | \$ 1,140.00 | 10% | <i>\$1,033.70</i> |
| EW MonitorPLUS 4HRonsite-16538 | 97408-16538 | \$ 1,224.00 | 10% | <i>\$1,109.86</i> |
| EW MonitorPLUS 4HRonsite16538T | 97408-16538T | \$ 1,412.00 | 10% | <i>\$1,280.33</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLUS 4HROnsite-16539 | 97408-16539 | \$ 1,375.00 | 10% | <i>\$1,246.78</i> |
| EW MonitorPLUS 4HROnsite-16540 | 97408-16540 | \$ 1,190.00 | 10% | <i>\$1,079.03</i> |
| EW MonitorPLUS 4HROnsite-16541 | 97408-16541 | \$ 890.00 | 10% | <i>\$807.01</i> |
| EW MonitorPLS 4HROnsite 16560 | 97408-16560 | \$ 782.00 | 10% | <i>\$709.08</i> |
| EW MonitorPLS 4HROnsite 16561 | 97408-16561 | \$ 830.00 | 10% | <i>\$752.60</i> |
| EW MonitorPLS 4HROnsite 16562 | 97408-16562 | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW MonitorPLS 4HROnsite 16563 | 97408-16563 | \$ 926.00 | 10% | <i>\$839.65</i> |
| EW MonitorPLS 4HROnsite 16564 | 97408-16564 | \$ 988.00 | 10% | <i>\$895.87</i> |
| EW MonitorPLS 4HROnsite 16565 | 97408-16565 | \$ 1,137.00 | 10% | <i>\$1,030.97</i> |
| EW MonitorPLS 4HROnsite 16566 | 97408-16566 | \$ 750.00 | 10% | <i>\$680.06</i> |
| EW MonitorPLS 4HROnsite 16567 | 97408-16567 | \$ 805.00 | 10% | <i>\$729.93</i> |
| EW MonitorPLS 4HROnsite 16568 | 97408-16568 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW MonitorPLS 4HROnsite 16569 | 97408-16569 | \$ 846.00 | 10% | <i>\$767.11</i> |
| EW MonitorPLS 4HROnsite 16570 | 97408-16570 | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW MonitorPLS 4HROnsite 16571 | 97408-16571 | \$ 988.00 | 10% | <i>\$895.87</i> |
| EW MonitorPLS 4HROnsite-16701 | 97408-16701 | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW MonitorPLS 4HROnsite-16702 | 97408-16702 | \$ 1,671.00 | 10% | <i>\$1,515.18</i> |
| EW MonitorPLS 4HROnsite-16703 | 97408-16703 | \$ 1,541.00 | 10% | <i>\$1,397.30</i> |
| EW MonitorPLS 4HROnsite 16703T | 97408-16703T | \$ 1,702.00 | 10% | <i>\$1,543.29</i> |
| EW MonitorPLUS 4HROnsite-16704 | 97408-16704 | \$ 1,892.00 | 10% | <i>\$1,715.57</i> |
| EW MonitorPLS 4HROnsite 16704T | 97408-16704T | \$ 1,792.00 | 10% | <i>\$1,624.90</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite-16705 | 97408-16705 | \$ 1,671.00 | 10% | <i>\$1,515.18</i> |
| EW MonitorPLS 4HROnsite 16705T | 97408-16705T | \$ 1,852.00 | 10% | <i>\$1,679.30</i> |
| EW MonitorPLS 4HROnsite-16706 | 97408-16706 | \$ 2,248.00 | 10% | <i>\$2,038.37</i> |
| EW MonitorPLS 4HROnsite 16706T | 97408-16706T | \$ 2,481.00 | 10% | <i>\$2,249.65</i> |
| EW MonitorPLS 4HROnsite-16710 | 97408-16710 | \$ 536.00 | 10% | <i>\$486.02</i> |
| EW MonitorPLS 4HROnsite 16710T | 97408-16710T | \$ 599.00 | 10% | <i>\$543.14</i> |
| EW MonitorPLS 4HROnsite-16711 | 97408-16711 | \$ 369.00 | 10% | <i>\$334.59</i> |
| EW MonitorPLS 4HROnsite 16711T | 97408-16711T | \$ 409.00 | 10% | <i>\$370.86</i> |
| EW MonitorPLS 4HROnsite-16712 | 97408-16712 | \$ 414.00 | 10% | <i>\$375.39</i> |
| EW MonitorPLS 4HROnsite 16712T | 97408-16712T | \$ 444.00 | 10% | <i>\$402.60</i> |
| EW MonitorPLS 4HROnsite-16713 | 97408-16713 | \$ 317.00 | 10% | <i>\$287.44</i> |
| EW MonitorPLS 4HROnsite 16713T | 97408-16713T | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW MonitorPLS 4HROnsite-16715 | 97408-16715 | \$ 360.00 | 10% | <i>\$326.43</i> |
| EW MonitorPLS 4HROnsite 16715T | 97408-16715T | \$ 409.00 | 10% | <i>\$370.86</i> |
| EW MonitorPLS 4HROnsite-16716 | 97408-16716 | \$ 1,293.00 | 10% | <i>\$1,172.43</i> |
| EW MonitorPLS 4HROnsite 16716T | 97408-16716T | \$ 1,433.00 | 10% | <i>\$1,299.37</i> |
| EW MonitorPLS 4HROnsite-16717 | 97408-16717 | \$ 1,484.00 | 10% | <i>\$1,345.62</i> |
| EW MonitorPLS 4HROnsite-16718 | 97408-16718 | \$ 1,337.00 | 10% | <i>\$1,212.32</i> |
| EW MonitorPLS 4HROnsite-16719 | 97408-16719 | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW MonitorPLS 4HROnsite 16720 | 97408-16720 | \$ 1,981.00 | 10% | <i>\$1,796.27</i> |
| EW MonitorPLS 4HROnsite 16720T | 97408-16720T | \$ 2,308.00 | 10% | <i>\$2,092.78</i> |

| | | | | |
|------------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite 16756 | 97408-16756 | \$ 1,703.00 | 10% | <i>\$1,544.20</i> |
| EW MonitorPLS 4HROnsite 16756T | 97408-16756T | \$ 2,015.00 | 10% | <i>\$1,827.10</i> |
| EW MonitorPLS 4HROnsite 16757 | 97408-16757 | \$ 1,650.00 | 10% | <i>\$1,496.14</i> |
| EW MonitorPLS 4HROnsite 16757T | 97408-16757T | \$ 1,945.00 | 10% | <i>\$1,763.63</i> |
| EW MonitorPLS 4HROnsite 16790 | 97408-16790 | \$ 2,353.00 | 10% | <i>\$2,133.58</i> |
| EW MonitorPLS 4HROnsite 16791 | 97408-16791 | \$ 3,036.00 | 10% | <i>\$2,752.89</i> |
| EW MonitorPLS 4HROnsite- 17101 | 97408-17101 | \$ 4,405.00 | 10% | <i>\$3,994.23</i> |
| EW MonitorPLS 4HROnsite- 17101T | 97408-17101T | \$ 5,563.00 | 10% | <i>\$5,044.25</i> |
| EW MonitorPLS 4HROnsite- 17102 | 97408-17102 | \$ 4,405.00 | 10% | <i>\$3,994.23</i> |
| EW MonitorPLS 4HROnsite- 17102T | 97408-17102T | \$ 5,563.00 | 10% | <i>\$5,044.25</i> |
| EW MonitorPLS 4HROnsite- 17103 | 97408-17103 | \$ 3,271.00 | 10% | <i>\$2,965.98</i> |
| EW MonitorPLS 4HROnsite- 17103C | 97408-17103C | \$ 3,174.00 | 10% | <i>\$2,878.02</i> |
| EW MonitorPLS 4HROnsite- 17103T | 97408-17103T | \$ 4,102.00 | 10% | <i>\$3,719.49</i> |
| EW MonitorPLS 4HROnsite- 17104 | 97408-17104 | \$ 3,271.00 | 10% | <i>\$2,965.98</i> |
| EW MonitorPLS 4HROnsite- 17104T | 97408-17104T | \$ 4,102.00 | 10% | <i>\$3,719.49</i> |
| EW MonitorPLS 4HROnsite- 17121 | 97408-17121 | \$ 1,003.00 | 10% | <i>\$909.47</i> |
| EW MonitorPLS 4HROnsite- 17122 | 97408-17122 | \$ 709.00 | 10% | <i>\$642.89</i> |
| EW MonitorPLS 4HROnsite- 17200 | 97408-17200 | \$ 6,564.00 | 10% | <i>\$5,951.91</i> |
| EW MonitorPLS 4HROnsite- 17200T | 97408-17200T | \$ 7,437.00 | 10% | <i>\$6,743.50</i> |
| EW MonitorPLS 4HROnsite- 17201 | 97408-17201 | \$ 6,564.00 | 10% | <i>\$5,951.91</i> |
| EW MonitorPLS 4HROnsite- 17201T | 97408-17201T | \$ 7,437.00 | 10% | <i>\$6,743.50</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite-17202 | 97408-17202 | \$ 6,564.00 | 10% | <i>\$5,951.91</i> |
| EW MonitorPLS 4HROnsite-17202T | 97408-17202T | \$ 7,437.00 | 10% | <i>\$6,743.50</i> |
| EW MonitorPLS 4HROnsite-17203 | 97408-17203 | \$ 6,658.00 | 10% | <i>\$6,037.14</i> |
| EW MonitorPLS 4HROnsite-17203T | 97408-17203T | \$ 7,535.00 | 10% | <i>\$6,832.36</i> |
| EW MonitorPLS 4HROnsite-17204 | 97408-17204 | \$ 6,658.00 | 10% | <i>\$6,037.14</i> |
| EW MonitorPLS 4HROnsite-17204T | 97408-17204T | \$ 7,535.00 | 10% | <i>\$6,832.36</i> |
| EW MonitorPLS 4HROnsite-17205 | 97408-17205 | \$ 6,613.00 | 10% | <i>\$5,996.34</i> |
| EW MonitorPLS 4HROnsite-17205T | 97408-17205T | \$ 7,491.00 | 10% | <i>\$6,792.46</i> |
| EW MonitorPLS 4HROnsite-17206 | 97408-17206 | \$ 6,613.00 | 10% | <i>\$5,996.34</i> |
| EW MonitorPLS 4HROnsite-17206T | 97408-17206T | \$ 7,491.00 | 10% | <i>\$6,792.46</i> |
| EW MonitorPLS 4HROnsite-17300 | 97408-17300 | \$ 4,611.00 | 10% | <i>\$4,181.02</i> |
| EW MonitorPLS 4HROnsite-17310 | 97408-17310 | \$ 4,245.00 | 10% | <i>\$3,849.15</i> |
| EW MonitorPLS 4HROnsite 17350 | 97408-17350 | \$ 4,444.00 | 10% | <i>\$4,029.60</i> |
| EW MonitorPLS 4HROnsite 17360 | 97408-17360 | \$ 5,311.00 | 10% | <i>\$4,815.75</i> |
| EW MonitorPLS 4HROnsite 17401 | 97408-17401 | \$ 1,248.00 | 10% | <i>\$1,131.62</i> |
| EW MonitorPLS 4HROnsite 17401G | 97408-17401G | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS 4HROnsite 17401T | 97408-17401T | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS 4HROnsite 17402 | 97408-17402 | \$ 1,440.00 | 10% | <i>\$1,305.72</i> |
| EW MonitorPLS 4HROnsite 17402G | 97408-17402G | \$ 1,463.00 | 10% | <i>\$1,326.58</i> |
| EW MonitorPLS 4HROnsite 17402T | 97408-17402T | \$ 1,463.00 | 10% | <i>\$1,326.58</i> |
| EW MonitorPLS 4HROnsite 17403 | 97408-17403 | \$ 1,515.00 | 10% | <i>\$1,373.73</i> |

| | | | | |
|--------------------------------------|---------------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite 17404 | 97408-17404 | \$ 1,105.00 | 10% | <i>\$1,001.96</i> |
| EW MonitorPLS 4HROnsite 17405 | 97408-17405 | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW MonitorPLS 4HROnsite 17700 | 97408-17700 | \$ 7,934.00 | 10% | <i>\$7,194.15</i> |
| EW MonitorPLS 4HROnsite- 17701 | 97408-17701 | \$ 6,737.00 | 10% | <i>\$6,108.77</i> |
| EW MonitorPLS 4HROnsite- 17702 | 97408-17702 | \$ 6,737.00 | 10% | <i>\$6,108.77</i> |
| EW MonitorPLS 4HROnsite- 17703 | 97408-17703 | \$ 7,361.00 | 10% | <i>\$6,674.59</i> |
| EW MonitorPLS 4HROnsite- 17704 | 97408-17704 | \$ 7,361.00 | 10% | <i>\$6,674.59</i> |
| EW MonitorPLS 4HROnsite- 17705 | 97408-17705 | \$ 6,778.00 | 10% | <i>\$6,145.95</i> |
| EW MonitorPLS 4HROnsite- 17706 | 97408-17706 | \$ 6,778.00 | 10% | <i>\$6,145.95</i> |
| EW MonitorPLS 4HROnsite 17800 | 97408-17800 | \$ 7,994.00 | 10% | <i>\$7,248.56</i> |
| EW MonitorPLS 4HROnsite 17810 | 97408-17810 | \$ 6,535.00 | 10% | <i>\$5,925.61</i> |
| EW MonitorPLS 4HROnsite 18101 | 97408-18101 | \$ 577.00 | 10% | <i>\$523.19</i> |
| EW MonitorPLS 4HROnsite 18102 | 97408-18102 | \$ 680.00 | 10% | <i>\$616.59</i> |
| EW MonitorPLS 4HROnsite 18103 | 97408-18103 | \$ 726.00 | 10% | <i>\$658.30</i> |
| EW MonitorPLS 4HROnsite 18104 | 97408-18104 | \$ 937.00 | 10% | <i>\$849.62</i> |
| EW MonitorPLS 4HROnsite 18104-6PK | 97408-18104- 6PK | \$ 5,622.00 | 10% | <i>\$5,097.75</i> |
| EW MonitorPLS 4HROnsite- 30135 | 97408-30135 | \$ 2,323.00 | 10% | <i>\$2,106.38</i> |
| EW MonitorPLS 4HROnsite 30136 | 97408-30136 | \$ 9,182.00 | 10% | <i>\$8,325.78</i> |
| EW MonitorPLS 4HROnsite 30137 | 97408-30137 | \$ 2,164.00 | 10% | <i>\$1,962.21</i> |
| EW MonitorPLS 4HROnsite 30138 | 97408-30138 | \$ 7,218.00 | 10% | <i>\$6,544.92</i> |
| EW MonitorPLS 4HROnsite 30139 | 97408-30139 | \$ 12,728.00 | 10% | <i>\$11,541.11</i> |

| | | | | |
|----------------------------------|-------------|-----------|-----|----------|
| EW MonitorPLS 4HROnsite 30912 | 97408-30912 | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite 30913 | 97408-30913 | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite 31012 | 97408-31012 | \$ 335.00 | 10% | \$303.76 |
| EW MonitorPLS 4HROnsite 31013 | 97408-31013 | \$ 335.00 | 10% | \$303.76 |
| EW MonitorPLS 4HROnsite 31014 | 97408-31014 | \$ 335.00 | 10% | \$303.76 |
| EW MonitorPLS 4HROnsite 31015 | 97408-31015 | \$ 335.00 | 10% | \$303.76 |
| EW MonitorPLS 4HROnsite 31016 | 97408-31016 | \$ 581.00 | 10% | \$526.82 |
| EW MonitorPLS 4HROnsite 31017 | 97408-31017 | \$ 581.00 | 10% | \$526.82 |
| EW MonitorPLS 4HROnsite 31018 | 97408-31018 | \$ 632.00 | 10% | \$573.07 |
| EW MonitorPLS 4HROnsite 31019 | 97408-31019 | \$ 632.00 | 10% | \$573.07 |
| EW MonitorPLS 4HROnsite 31025 | 97408-31025 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS 4HROnsite 31026 | 97408-31026 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS 4HROnsite 31028 | 97408-31028 | \$ 249.00 | 10% | \$225.78 |
| EW MonitorPLS 4HROnsite 31029 | 97408-31029 | \$ 249.00 | 10% | \$225.78 |
| EW MonitorPLS 4HROnsite 31031 | 97408-31031 | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS 4HROnsite 31032 | 97408-31032 | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS 4HROnsite 31034 | 97408-31034 | \$ 335.00 | 10% | \$303.76 |
| EW MonitorPLS 4HROnsite 31035 | 97408-31035 | \$ 335.00 | 10% | \$303.76 |
| EW MonitorPLS 4HROnsite 31050 | 97408-31050 | \$ 332.00 | 10% | \$301.04 |
| EW MonitorPLS 4HROnsite 31051 | 97408-31051 | \$ 332.00 | 10% | \$301.04 |
| EW MonitorPLS 4HROnsite 31055 | 97408-31055 | \$ 332.00 | 10% | \$301.04 |

| | | | | |
|---|------------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite 31056 | 97408-31056 | \$ 332.00 | 10% | <i>\$301.04</i> |
| EW MonitorPLS 4HROnsite 39031 | 97408-39031 | \$ 578.00 | 10% | <i>\$524.10</i> |
| EW MonitorPLS 4HROnsite 39032 | 97408-39032 | \$ 647.00 | 10% | <i>\$586.67</i> |
| EW MonitorPLS 4HROnsite 39033 | 97408-39033 | \$ 578.00 | 10% | <i>\$524.10</i> |
| EW MonitorPLS 4HROnsite 39034 | 97408-39034 | \$ 578.00 | 10% | <i>\$524.10</i> |
| EW MonitorPLS 4HROnsite 39035 | 97408-39035 | \$ 1,566.00 | 10% | <i>\$1,419.97</i> |
| EW MonitorPLS 4HROnsite 39036 | 97408-39036 | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW MonitorPLS 4HROnsite 39037 | 97408-39037 | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW MonitorPLS 4HROnsite 39038 | 97408-39038 | \$ 656.00 | 10% | <i>\$594.83</i> |
| EW MonitorPLS 4HROnsite 39039 | 97408-39039 | \$ 656.00 | 10% | <i>\$594.83</i> |
| EW MonitorPLS 4HROnsite 4120-24MW-4Y | 97408-4120- 24MW-4Y | \$ 1,587.00 | 10% | <i>\$1,439.01</i> |
| EW MonitorPLS 4HROnsite 4120-48MW-4Y | 97408-4120- 48MW-4Y | \$ 1,962.00 | 10% | <i>\$1,779.04</i> |
| EW MonitorPLS 4HROnsite 4120C | 97408-4120C | \$ 8,539.00 | 10% | <i>\$7,742.74</i> |
| EW MonitorPLS 4HROnsite 4120C-1 | 97408-4120C-1 | \$ 9,641.00 | 10% | <i>\$8,741.98</i> |
| EW MonitorPLS 4HROnsite 41216 | 97408-41216 | \$ 2,639.00 | 10% | <i>\$2,392.91</i> |
| EW MonitorPLS 4HROnsite 4220-12P-4X | 97408-4220- 12P-4X | \$ 789.00 | 10% | <i>\$715.43</i> |
| EW MonitorPLS 4HROnsite 4220-12T-4X | 97408-4220- 12T-4X | \$ 702.00 | 10% | <i>\$636.54</i> |
| EW MonitorPLS 4HROnsite 4220-24P-4X | 97408-4220- 24P-4X | \$ 898.00 | 10% | <i>\$814.26</i> |
| EW MonitorPLS 4HROnsite 4220-24T-4X | 97408-4220- 24T-4X | \$ 800.00 | 10% | <i>\$725.40</i> |
| EW MonitorPLS 4HROnsite 4220-48P-4X | 97408-4220- 48P-4X | \$ 1,116.00 | 10% | <i>\$1,011.93</i> |
| EW MonitorPLS 4HROnsite 4220-48T-4X | 97408-4220- 48T-4X | \$ 953.00 | 10% | <i>\$864.13</i> |

| | | | | |
|--|-----------------------------------|--------------|-----|-------------|
| EW MonitorPLS 4HROnsite 4220-4MW-20P-4X | 97408-4220- 4MW-20P-4X | \$ 1,062.00 | 10% | \$962.97 |
| EW MonitorPLS 4HROnsite 4220-4MW-8P-4X | 97408-4220- 4MW-8P-4X | \$ 887.00 | 10% | \$804.29 |
| EW MonitorPLS 4HROnsite 4220-8MW-40P-4X | 97408-4220- 8MW-40P-4X | \$ 1,334.00 | 10% | \$1,209.60 |
| EW MonitorPLS 4HROnsite 4220-8X | 97408-4220-8X | \$ 920.00 | 10% | \$834.21 |
| EW MonitorPLS 4HROnsite- 48001 | 97408-48001 | \$ 11,399.00 | 10% | \$10,336.04 |
| EW MonitorPLS 4HROnsite- 48038 | 97408-48038 | \$ 4,226.00 | 10% | \$3,831.93 |
| EW MonitorPLS 4HROnsite- 48039 | 97408-48039 | \$ 4,226.00 | 10% | \$3,831.93 |
| EW MonitorPLS 4HROnsite- 48040 | 97408-48040 | \$ 4,013.00 | 10% | \$3,638.79 |
| EW MonitorPLS 4HROnsite- 48041 | 97408-48041 | \$ 4,226.00 | 10% | \$3,831.93 |
| EW MonitorPLS 4HROnsite- 48046 | 97408-48046 | \$ 5,463.00 | 10% | \$4,953.58 |
| EW MonitorPLS 4HROnsite- 48047 | 97408-48047 | \$ 14,132.00 | 10% | \$12,814.19 |
| EW MonitorPLS 4HROnsite- 48051 | 97408-48051 | \$ 9,805.00 | 10% | \$8,890.68 |
| EW MonitorPLS 4HROnsite- 48061 | 97408-48061 | \$ 11,405.00 | 10% | \$10,341.48 |
| EW MonitorPLS 4HROnsite- 48062 | 97408-48062 | \$ 18,097.00 | 10% | \$16,409.45 |
| EW MonitorPLS 4HROnsite 5320-16P-4XE | 97408-5320- 16P-4XE | \$ 988.00 | 10% | \$895.87 |
| EW MonitorPLS 4HROnsite 5320-16P-4XE-DC | 97408-5320- 16P-4XE-DC | \$ 1,072.00 | 10% | \$972.04 |
| EW MonitorPLS 4HROnsite 5320-24P-8XE | 97408-5320- 24P-8XE | \$ 1,032.00 | 10% | \$935.77 |
| EW MonitorPLS 4HROns 5320- 24T-24S-4XE-XT | 97408-5320- 24T-24S-4XE- XT | \$ 1,171.00 | 10% | \$1,061.80 |
| EW MonitorPLS 4HROnsite 5320-24T-4X-XT | 97408-5320- 24T-4X-XT | \$ 844.00 | 10% | \$765.30 |
| EW MonitorPLS 4HROnsite 5320-24T-8XE | 97408-5320- 24T-8XE | \$ 896.00 | 10% | \$812.45 |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite 5320-48P-8XE | 97408-5320- 48P-8XE | \$ 1,376.00 | 10% | <i>\$1,247.69</i> |
| EW MonitorPLS 4HROnsite 5320-48T-8XE | 97408-5320- 48T-8XE | \$ 1,124.00 | 10% | <i>\$1,019.19</i> |
| EW MonitorPLS 4HROnsi 5420F-16MW-32P-4XE | 97408-5420F- 16MW-32P- 4XE | \$ 2,052.00 | 10% | <i>\$1,860.65</i> |
| EW MonitorPLS 4HROnsit 5420F-16W-32P-4XE | 97408-5420F- 16W-32P-4XE | \$ 1,995.00 | 10% | <i>\$1,808.97</i> |
| EW MonitorPLS 4HROnsite 5420F-24P-4XE | 97408-5420F- 24P-4XE | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HROnsite 5420F-24S-4XE | 97408-5420F- 24S-4XE | \$ 1,323.00 | 10% | <i>\$1,199.63</i> |
| EW MonitorPLS 4HROnsite 5420F-24T-4XE | 97408-5420F- 24T-4XE | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |
| EW MonitorPLS 4HROnsite 5420F-48P-4XE | 97408-5420F- 48P-4XE | \$ 1,600.00 | 10% | <i>\$1,450.80</i> |
| EW MonitorPLS 4HROnsite 5420F-48P-4XL | 97408-5420F- 48P-4XL | \$ 1,714.00 | 10% | <i>\$1,554.17</i> |
| EW MonitorPLS 4HROnsite 5420F-48T-4XE | 97408-5420F- 48T-4XE | \$ 1,315.00 | 10% | <i>\$1,192.38</i> |
| EW MonitorPLS 4HROnsite 5420F-8W-16P-4XE | 97408-5420F- 8W-16P-4XE | \$ 1,329.00 | 10% | <i>\$1,205.07</i> |
| EW MonitorPLS 4HROnsi 5420M-16MW-32P-4YE | 97408-5420M- 16MW-32P- 4YE | \$ 2,192.00 | 10% | <i>\$1,987.60</i> |
| EW MonitorPLS 4HROnsite 5420M-24T-4YE | 97408-5420M- 24T-4YE | \$ 1,306.00 | 10% | <i>\$1,184.22</i> |
| EW MonitorPLS 4HROnsite 5420M-24W-4YE | 97408-5420M- 24W-4YE | \$ 1,203.00 | 10% | <i>\$1,090.82</i> |
| EW MonitorPLS 4HROnsite 5420M-48T-4YE | 97408-5420M- 48T-4YE | \$ 1,545.00 | 10% | <i>\$1,400.93</i> |
| EW MonitorPLS 4HROnsite 5420M-48W-4YE | 97408-5420M- 48W-4YE | \$ 1,729.00 | 10% | <i>\$1,567.77</i> |
| EW MONITORPLUS 4HR ONSITE 5520-12MW-36W | 97408-5520- 12MW-36W | \$ 2,318.00 | 10% | <i>\$2,101.85</i> |
| EW MONITORPLUS 4HR ONSITE 5520-24T | 97408-5520- 24T | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |
| EW MONITORPLUS 4HR ON 5520-24T-ACDC-BASE | 97408-5520- 24T-ACDC- BASE | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |

| | | | | |
|--|-----------------------------------|-------------|-----|-------------------|
| EW MONITORPLUS 4HR ONSITE 5520-24T-BASE | 97408-5520- 24T-BASE | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |
| EW MONITORPLUS 4HR ONSITE 5520-24W | 97408-5520- 24W | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW MONITORPLUS 4HR ONSITE 5520-24X | 97408-5520- 24X | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MONITORPLUS 4HR ON 5520-24X-ACDC-BASE | 97408-5520- 24X-ACDC- BASE | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MONITORPLUS 4HR ONSITE 5520-24X-BASE | 97408-5520- 24X-BASE | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MONITORPLUS 4HR ONSITE 5520-48SE | 97408-5520- 48SE | \$ 2,356.00 | 10% | <i>\$2,136.30</i> |
| EW MONITORPLU 4HR ON 5520-48SE-ACDC-BASE | 97408-5520- 48SE-ACDC- BASE | \$ 2,356.00 | 10% | <i>\$2,136.30</i> |
| EW MONITORPLUS 4HR ONSITE 5520-48SE-BASE | 97408-5520- 48SE-BASE | \$ 2,356.00 | 10% | <i>\$2,136.30</i> |
| EW MONITORPLUS 4HR ONSITE 5520-48T | 97408-5520- 48T | \$ 1,703.00 | 10% | <i>\$1,544.20</i> |
| EW MONITORPLUS 4HR ON 5520-48T-ACDC-BASE | 97408-5520- 48T-ACDC- BASE | \$ 1,703.00 | 10% | <i>\$1,544.20</i> |
| EW MONITORPLUS 4HR ONSITE 5520-48T-BASE | 97408-5520- 48T-BASE | \$ 1,703.00 | 10% | <i>\$1,544.20</i> |
| EW MONITORPLUS 4HR ONSITE 5520-48W | 97408-5520- 48W | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |
| EW MonitorPLS 4HROnsite 5720-24MW | 97408-5720- 24MW | \$ 2,411.00 | 10% | <i>\$2,186.17</i> |
| EW MonitorPLS 4HROnsite 5720-24MXW | 97408-5720- 24MXW | \$ 3,205.00 | 10% | <i>\$2,906.13</i> |
| EW MonitorPLS 4HROnsite 5720-48MW | 97408-5720- 48MW | \$ 2,766.00 | 10% | <i>\$2,508.07</i> |
| EW MonitorPLS 4HROnsite 5720-48MXW | 97408-5720- 48MXW | \$ 3,849.00 | 10% | <i>\$3,490.08</i> |
| EW MonitorPLS 4HROnsite 7520-48XT-6C | 97408-7520- 48XT-6C | \$ 4,453.00 | 10% | <i>\$4,037.76</i> |
| EW MonitorPLS 4HROnsit 7520- 48XT-6C-AC-F | 97408-7520- 48XT-6C-AC- F | \$ 4,453.00 | 10% | <i>\$4,037.76</i> |
| EW MonitorPLS 4HROnsit 7520- 48XT-6C-AC-R | 97408-7520- 48XT-6C-AC- R | \$ 4,453.00 | 10% | <i>\$4,037.76</i> |

| | | | | |
|--|----------------------------------|-------------|-----|------------|
| EW MonitorPLS 4HROnsite 7520-48Y-8C | 97408-7520- 48Y-8C | \$ 4,164.00 | 10% | \$3,775.71 |
| EW MonitorPLS 4HROnsite 7520-48Y-8C-AC-F | 97408-7520- 48Y-8C-AC-F | \$ 4,164.00 | 10% | \$3,775.71 |
| EW MonitorPLS 4HROnsite 7520-48Y-8C-AC-R | 97408-7520- 48Y-8C-AC-R | \$ 4,164.00 | 10% | \$3,775.71 |
| EW MONITORPLUS 4HR ONSITE 7520-48YE-8CE | 97408-7520- 48YE-8CE | \$ 4,817.00 | 10% | \$4,367.81 |
| EW MONITORPLU 4HR ONS 7520-48YE-8CE-AC-F | 97408-7520- 48YE-8CE-AC- F | \$ 4,817.00 | 10% | \$4,367.81 |
| EW MONITORPLU 4HR ONS 7520-48YE-8CE-AC-R | 97408-7520- 48YE-8CE-AC- R | \$ 4,817.00 | 10% | \$4,367.81 |
| EW MonitorPLS 4HROnsite 7720-32C | 97408-7720- 32C | \$ 5,131.00 | 10% | \$4,652.53 |
| EW MonitorPLS 4HROnsite 7720-32C-AC-F | 97408-7720- 32C-AC-F | \$ 5,131.00 | 10% | \$4,652.53 |
| EW MonitorPLS 4HROnsite 7720-32C-AC-R | 97408-7720- 32C-AC-R | \$ 5,131.00 | 10% | \$4,652.53 |
| EW MonitorPLS 4HROnsite 8520-48XT-6C | 97408-8520- 48XT-6C | \$ 3,944.00 | 10% | \$3,576.22 |
| EW MonitorPLS4HROnsite 8520- 48XT-6C-AC-F | 97408-8520- 48XT-6C-AC- F | \$ 3,944.00 | 10% | \$3,576.22 |
| EW MonitorPLS4HROnsite 8520- 48XT-6C-AC-R | 97408-8520- 48XT-6C-AC- R | \$ 3,944.00 | 10% | \$3,576.22 |
| EW MonitorPLS4HROnsite 8520- 48XT-6C-DC-F | 97408-8520- 48XT-6C-DC- F | \$ 3,944.00 | 10% | \$3,576.22 |
| EW MonitorPLS4HROnsite 8520- 48XT-6C-DC-R | 97408-8520- 48XT-6C-DC- R | \$ 3,944.00 | 10% | \$3,576.22 |
| EW MonitorPLS 4HROnsite 8520-48Y-8C | 97408-8520- 48Y-8C | \$ 4,041.00 | 10% | \$3,664.18 |
| EW MonitorPLS 4HROnsite 8520-48Y-8C-AC-F | 97408-8520- 48Y-8C-AC-F | \$ 4,041.00 | 10% | \$3,664.18 |
| EW MonitorPLS 4HROnsite 8520-48Y-8C-AC-R | 97408-8520- 48Y-8C-AC-R | \$ 4,041.00 | 10% | \$3,664.18 |
| EW MonitorPLS 4HROnsite 8520-48Y-8C-DC-F | 97408-8520- 48Y-8C-DC-F | \$ 4,041.00 | 10% | \$3,664.18 |

| | | | | |
|---|----------------------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite 8520-48Y-8C-DC-R | 97408-8520- 48Y-8C-DC-R | \$ 4,041.00 | 10% | <i>\$3,664.18</i> |
| EW MonitorPLS 4HROnsite 8720-32C | 97408-8720- 32C | \$ 4,529.00 | 10% | <i>\$4,106.67</i> |
| EW MonitorPLS 4HROnsite 8720-32C-AC-F | 97408-8720- 32C-AC-F | \$ 4,529.00 | 10% | <i>\$4,106.67</i> |
| EW MonitorPLS 4HROnsite 8720-32C-AC-R | 97408-8720- 32C-AC-R | \$ 4,529.00 | 10% | <i>\$4,106.67</i> |
| EW MonitorPLS 4HROnsite 8720-32C-DC-F | 97408-8720- 32C-DC-F | \$ 4,529.00 | 10% | <i>\$4,106.67</i> |
| EW MonitorPLS 4HROnsite 8720-32C-DC-R | 97408-8720- 32C-DC-R | \$ 4,529.00 | 10% | <i>\$4,106.67</i> |
| EW MonitorPLUS 4HROnsite- 8806 | 97408-8806 | \$ 3,986.00 | 10% | <i>\$3,614.31</i> |
| EW MonitorPLS 4HROnsite- 8810 | 97408-8810 | \$ 8,738.00 | 10% | <i>\$7,923.18</i> |
| EW MonitorPLS 4HROnsite 8820-40C | 97408-8820- 40C | \$ 14,545.00 | 10% | <i>\$13,188.68</i> |
| EW MonitorPLS 4HROnsite 8820-40C-AC-F | 97408-8820- 40C-AC-F | \$ 14,545.00 | 10% | <i>\$13,188.68</i> |
| EW MonitorPLS 4HROnsite 8820-40C-AC-R | 97408-8820- 40C-AC-R | \$ 14,545.00 | 10% | <i>\$13,188.68</i> |
| EW MonitorPLS 4HROnsite 8820-40C-DC-F | 97408-8820- 40C-DC-F | \$ 14,545.00 | 10% | <i>\$13,188.68</i> |
| EW MonitorPLS 4HROnsite 8820-40C-DC-R | 97408-8820- 40C-DC-R | \$ 14,545.00 | 10% | <i>\$13,188.68</i> |
| EW MonitorPLS 4HROnsite 8820-80C | 97408-8820- 80C | \$ 26,056.00 | 10% | <i>\$23,626.28</i> |
| EW MonitorPLS 4HROnsite 8820-80C-AC-F | 97408-8820- 80C-AC-F | \$ 26,056.00 | 10% | <i>\$23,626.28</i> |
| EW MonitorPLS 4HROnsite 8820-80C-AC-R | 97408-8820- 80C-AC-R | \$ 26,056.00 | 10% | <i>\$23,626.28</i> |
| EW MonitorPLS 4HROnsite 8820-80C-DC-F | 97408-8820- 80C-DC-F | \$ 26,056.00 | 10% | <i>\$23,626.28</i> |
| EW MonitorPLS 4HROnsite 8820-80C-DC-R | 97408-8820- 80C-DC-R | \$ 26,056.00 | 10% | <i>\$23,626.28</i> |
| EW MonitorPLS 4HROnsite 9920-16C | 97408-9920- 16C | \$ 13,040.00 | 10% | <i>\$11,824.02</i> |
| EW MonitorPLS 4HROnsite 9920-4D | 97408-9920-4D | \$ 13,040.00 | 10% | <i>\$11,824.02</i> |
| EW MonitorPLS 4HROnsite 9920-NPB-8 | 97408-9920- NPB-8 | \$ 19,118.00 | 10% | <i>\$17,335.25</i> |

| | | | | |
|--|-------------------------|-----------|-----|----------|
| EW MonitorPLS 4HROnsite AH-AP-1130-AC-CE | 97408-AH-AP-1130-AC-CE | \$ 316.00 | 10% | \$286.53 |
| EW MonitorPLS 4HROnsite AH-AP-1130-AC-FC | 97408-AH-AP-1130-AC-FCC | \$ 316.00 | 10% | \$286.53 |
| EW MonitorPLS 4HROnsite AH-AP-1130-AC-W | 97408-AH-AP-1130-AC-W | \$ 316.00 | 10% | \$286.53 |
| EW MonitorPLS 4HROnsite AH-AP-122-AC-CAN | 97408-AH-AP-122-AC-CAN | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-122-AC-CE | 97408-AH-AP-122-AC-CE | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-122-AC-FCC | 97408-AH-AP-122-AC-FCC | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-122-AC-W | 97408-AH-AP-122-AC-W | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-130-AC-CE | 97408-AH-AP-130-AC-CE | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-130-AC-FCC | 97408-AH-AP-130-AC-FCC | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-130-AC-W | 97408-AH-AP-130-AC-W | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-150W-AC-CA | 97408-AH-AP-150W-AC-CAN | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-150W-AC-CE | 97408-AH-AP-150W-AC-CE | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-150W-AC-FC | 97408-AH-AP-150W-AC-FCC | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-150W-AC-W | 97408-AH-AP-150W-AC-W | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-230-AC-CE | 97408-AH-AP-230-AC-CE | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-230-AC-FCC | 97408-AH-AP-230-AC-FCC | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-230-AC-W | 97408-AH-AP-230-AC-W | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-250-AC-CAN | 97408-AH-AP-250-AC-CAN | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-250-AC-CE | 97408-AH-AP-250-AC-CE | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AH-AP-250-AC-FCC | 97408-AH-AP-250-AC-FCC | \$ 268.00 | 10% | \$243.01 |

| | | | | |
|--|-------------------------|-----------|-----|-----------------|
| EW MonitorPLS 4HROnsite AH-AP-250-AC-W | 97408-AH-AP-250-AC-W | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS 4HROnsite AH-AP-630-AX-CAN | 97408-AH-AP-630-AX-CAN | \$ 323.00 | 10% | <i>\$292.88</i> |
| EW MonitorPLS 4HROnsite AH-AP-630-AX-CE | 97408-AH-AP-630-AX-CE | \$ 323.00 | 10% | <i>\$292.88</i> |
| EW MonitorPLS 4HROnsite AH-AP-630-AX-FCC | 97408-AH-AP-630-AX-FCC | \$ 323.00 | 10% | <i>\$292.88</i> |
| EW MonitorPLS 4HROnsite AH-AP-630-AX-W | 97408-AH-AP-630-AX-W | \$ 323.00 | 10% | <i>\$292.88</i> |
| EW MonitorPLS 4HROnsite AH-AP-650-AX-CAN | 97408-AH-AP-650-AX-CAN | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-AP-650-AX-CE | 97408-AH-AP-650-AX-CE | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-AP-650-AX-FCC | 97408-AH-AP-650-AX-FCC | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-AP-650-AX-W | 97408-AH-AP-650-AX-W | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-AP-650X-AX-CA | 97408-AH-AP-650X-AX-CAN | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-AP-650X-AX-CE | 97408-AH-AP-650X-AX-CE | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-AP-650X-AX-FC | 97408-AH-AP-650X-AX-FCC | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-AP-650X-AX-W | 97408-AH-AP-650X-AX-W | \$ 295.00 | 10% | <i>\$267.49</i> |
| EW MonitorPLS 4HROnsite AH-ATOM-CAN | 97408-AH-ATOM-CAN | \$ 282.00 | 10% | <i>\$255.70</i> |
| EW MonitorPLS 4HROnsite AH-ATOM-CE-EU | 97408-AH-ATOM-CE-EU | \$ 296.00 | 10% | <i>\$268.40</i> |
| EW MonitorPLS 4HROnsite AH-ATOM-CE-UK | 97408-AH-ATOM-CE-UK | \$ 296.00 | 10% | <i>\$268.40</i> |
| EW MonitorPLS 4HROnsite AH-ATOM-FCC | 97408-AH-ATOM-FCC | \$ 281.00 | 10% | <i>\$254.80</i> |
| EW MonitorPLS 4HROnsite AH-ATOM-W | 97408-AH-ATOM-W | \$ 282.00 | 10% | <i>\$255.70</i> |
| EW MonitorPLS 4HROnsite AH-ATOM-W-EU | 97408-AH-ATOM-W-EU | \$ 296.00 | 10% | <i>\$268.40</i> |

| | | | | |
|--|----------------------|-------------|-----|-----------------|
| EW MonitorPLS 4HROnsite AH-ATOM-W-UK | 97408-AH-ATOM-W-UK | \$ 296.00 | 10% | <i>\$268.40</i> |
| EW MonitorPLS 4HROnsite AH-SR-2208P-AU | 97408-AH-SR-2208P-AU | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HROnsite AH-SR-2208P-EU | 97408-AH-SR-2208P-EU | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HROnsite AH-SR-2208P-NA | 97408-AH-SR-2208P-NA | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HROnsite AH-SR-2208P-UK | 97408-AH-SR-2208P-UK | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HROnsite AH-SR-2224P-AU | 97408-AH-SR-2224P-AU | \$ 751.00 | 10% | <i>\$680.97</i> |
| EW MonitorPLS 4HROnsite AH-SR-2224P-EU | 97408-AH-SR-2224P-EU | \$ 751.00 | 10% | <i>\$680.97</i> |
| EW MonitorPLS 4HROnsite AH-SR-2224P-NA | 97408-AH-SR-2224P-NA | \$ 751.00 | 10% | <i>\$680.97</i> |
| EW MonitorPLS 4HROnsite AH-SR-2224P-UK | 97408-AH-SR-2224P-UK | \$ 751.00 | 10% | <i>\$680.97</i> |
| EW MonitorPLS 4HROnsite AH-SR-2324P-AU | 97408-AH-SR-2324P-AU | \$ 809.00 | 10% | <i>\$733.56</i> |
| EW MonitorPLS 4HROnsite AH-SR-2324P-EU | 97408-AH-SR-2324P-EU | \$ 809.00 | 10% | <i>\$733.56</i> |
| EW MonitorPLS 4HROnsite AH-SR-2324P-NA | 97408-AH-SR-2324P-NA | \$ 809.00 | 10% | <i>\$733.56</i> |
| EW MonitorPLS 4HROnsite AH-SR-2324P-UK | 97408-AH-SR-2324P-UK | \$ 809.00 | 10% | <i>\$733.56</i> |
| EW MonitorPLS 4HROnsite AH-SR-2348P-AU | 97408-AH-SR-2348P-AU | \$ 1,009.00 | 10% | <i>\$914.91</i> |
| EW MonitorPLS 4HROnsite AH-SR-2348P-EU | 97408-AH-SR-2348P-EU | \$ 1,009.00 | 10% | <i>\$914.91</i> |
| EW MonitorPLS 4HROnsite AH-SR-2348P-NA | 97408-AH-SR-2348P-NA | \$ 1,009.00 | 10% | <i>\$914.91</i> |
| EW MonitorPLS 4HROnsite AH-SR-2348P-UK | 97408-AH-SR-2348P-UK | \$ 1,009.00 | 10% | <i>\$914.91</i> |
| EW MonitorPLS 4HROnsite AH-XR200P-AU | 97408-AH-XR200P-AU | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HROnsite AH-XR200P-EU | 97408-AH-XR200P-EU | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HROnsite AH-XR200P-UK | 97408-AH-XR200P-UK | \$ 698.00 | 10% | <i>\$632.91</i> |
| EW MonitorPLS 4HROnsite AH-XR200P-US | 97408-AH-XR200P-US | \$ 698.00 | 10% | <i>\$632.91</i> |

| | | | | |
|--------------------------------------|-------------------------|-----------|-----|-----------------|
| EW MonitorPLS 4HROnsite AH-XR600P | 97408-AH-XR600P | \$ 707.00 | 10% | <i>\$641.07</i> |
| EW MonitorPLS 4HROnsite AH-XR600P-AU | 97408-AH-XR600P-AU | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite AH-XR600P-EU | 97408-AH-XR600P-EU | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite AH-XR600P-KR | 97408-AH-XR600P-KR | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite AH-XR600P-UK | 97408-AH-XR600P-UK | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite AH-XR600P-US | 97408-AH-XR600P-US | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite AP-8533-IL | 97408-AP-8533-68SB30-IL | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW MonitorPLS 4HROnsite AP3000-IL | 97408-AP3000-IL | \$ 205.44 | 10% | <i>\$186.28</i> |
| EW MonitorPLS 4HROnsite AP3000-TN | 97408-AP3000-TN | \$ 205.44 | 10% | <i>\$186.28</i> |
| EW MonitorPLS 4HROnsite AP3000-WW | 97408-AP3000-WW | \$ 205.44 | 10% | <i>\$186.28</i> |
| EW MonitorPLS 4HROnsite AP3000X-WW | 97408-AP3000X-WW | \$ 230.44 | 10% | <i>\$208.95</i> |
| EW MonitorPLS 4HROnsite AP302W-CAN | 97408-AP302W-CAN | \$ 254.00 | 10% | <i>\$230.31</i> |
| EW MonitorPLS 4HROnsite AP302W-EG | 97408-AP302W-EG | \$ 201.00 | 10% | <i>\$182.26</i> |
| EW MonitorPLS 4HROnsite AP302W-FCC | 97408-AP302W-FCC | \$ 254.00 | 10% | <i>\$230.31</i> |
| EW MonitorPLS 4HROnsite AP302W-WR | 97408-AP302W-WR | \$ 242.00 | 10% | <i>\$219.43</i> |
| EW MonitorPLS 4HROnsite AP305C-1-CAN | 97408-AP305C-1-CAN | \$ 267.00 | 10% | <i>\$242.10</i> |
| EW MonitorPLS 4HROnsite AP305C-1-EG | 97408-AP305C-1-EG | \$ 267.00 | 10% | <i>\$242.10</i> |
| EW MonitorPLS 4HROnsite AP305C-1-FCC | 97408-AP305C-1-FCC | \$ 267.00 | 10% | <i>\$242.10</i> |
| EW MonitorPLS 4HROnsite AP305C-1-IL | 97408-AP305C-1-IL | \$ 267.00 | 10% | <i>\$242.10</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EW MonitorPLS 4HROnsite AP305C-1-WR | 97408-AP305C- 1-WR | \$ 267.00 | 10% | \$242.10 |
| EW MonitorPLS 4HROnsite AP305C-CAN | 97408-AP305C- CAN | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305C-EG | 97408-AP305C- EG | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305C-FCC | 97408-AP305C- FCC | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305C-IL | 97408-AP305C- IL | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305C-WR | 97408-AP305C- WR | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305CX-CAN | 97408- AP305CX- CAN | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305CX-FCC | 97408- AP305CX- FCC | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305CX-IL | 97408- AP305CX-IL | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP305CX-WR | 97408- AP305CX-WR | \$ 287.00 | 10% | \$260.24 |
| EW MonitorPLS 4HROnsite AP310e-1-WR | 97408-AP310e- 1-WR | \$ 241.00 | 10% | \$218.53 |
| EW MonitorPLS 4HROnsite AP310e-CAN | 97408-AP310e- CAN | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS 4HROnsite AP310e-FCC | 97408-AP310e- FCC | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS 4HROnsite AP310e-IL | 97408-AP310e- IL | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS 4HROnsite AP310e-WR | 97408-AP310e- WR | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS 4HROnsite AP310i-1-WR | 97408-AP310i- 1-WR | \$ 241.00 | 10% | \$218.53 |
| EW MonitorPLS 4HROnsite AP310i-CAN | 97408-AP310i- CAN | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS 4HROnsite AP310i-FCC | 97408-AP310i- FCC | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS 4HROnsite AP310i-IL | 97408-AP310i- IL | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS 4HROnsite AP310i-WR | 97408-AP310i- WR | \$ 253.00 | 10% | \$229.41 |

| | | | | |
|---|------------------------|-----------|-----|----------|
| EW MonitorPLS 4HROnsite AP360e-CAN | 97408-AP360e- CAN | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP360e-FCC | 97408-AP360e- FCC | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP360e-IL | 97408-AP360e- IL | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP360e-WR | 97408-AP360e- WR | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP360i-CAN | 97408-AP360i- CAN | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP360i-FCC | 97408-AP360i- FCC | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP360i-WR | 97408-AP360i- WR | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP4000-WW | 97408-AP4000- 1-WW | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsiteAP4000-IL | 97408-AP4000- IL | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AP4000-WW | 97408-AP4000- WW | \$ 268.00 | 10% | \$243.01 |
| EW MonitorPLS 4HROnsite AP410C-1-CAN | 97408-AP410C- 1-CAN | \$ 271.00 | 10% | \$245.73 |
| EW MonitorPLS 4HROnsite AP410C-1-EG | 97408-AP410C- 1-EG | \$ 271.00 | 10% | \$245.73 |
| EW MonitorPLS 4HROnsite AP410C-1-FCC | 97408-AP410C- 1-FCC | \$ 271.00 | 10% | \$245.73 |
| EW MonitorPLS 4HROnsite AP410C-1-IL | 97408-AP410C- 1-IL | \$ 271.00 | 10% | \$245.73 |
| EW MonitorPLS 4HROnsite AP410C-1-WR | 97408-AP410C- 1-WR | \$ 271.00 | 10% | \$245.73 |
| EW MonitorPLS 4HROnsite AP410C-CAN | 97408-AP410C- CAN | \$ 291.00 | 10% | \$263.86 |
| EW MonitorPLS 4HROnsite AP410C-EG | 97408-AP410C- EG | \$ 291.00 | 10% | \$263.86 |
| EW MonitorPLS 4HROnsite AP410C-FCC | 97408-AP410C- FCC | \$ 291.00 | 10% | \$263.86 |
| EW MonitorPLS 4HROnsite AP410C-IL | 97408-AP410C- IL | \$ 291.00 | 10% | \$263.86 |
| EW MonitorPLS 4HROnsite AP410C-WR | 97408-AP410C- WR | \$ 291.00 | 10% | \$263.86 |

| | | | | |
|---|------------------------|-----------|-----|----------|
| EW MonitorPLS 4HROnsite AP410e-CAN | 97408-AP410e- CAN | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite AP410e-FCC | 97408-AP410e- FCC | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite AP410e-WR | 97408-AP410e- WR | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite AP410i-1-FCC | 97408-AP410i- 1-FCC | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP410i-1-WR | 97408-AP410i- 1-WR | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP410i-CAN | 97408-AP410i- CAN | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite AP410i-FCC | 97408-AP410i- FCC | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite AP410i-IL | 97408-AP410i- IL | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite AP410i-WR | 97408-AP410i- WR | \$ 297.00 | 10% | \$269.30 |
| EW MonitorPLS 4HROnsite AP460C-CAN | 97408-AP460C- CAN | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460C-EG | 97408-AP460C- EG | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460C-FCC | 97408-AP460C- FCC | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460C-IL | 97408-AP460C- IL | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460C-WR | 97408-AP460C- WR | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460e-CAN | 97408-AP460e- CAN | \$ 319.00 | 10% | \$289.25 |
| EW MonitorPLS 4HROnsite AP460e-FCC | 97408-AP460e- FCC | \$ 319.00 | 10% | \$289.25 |
| EW MonitorPLS 4HROnsite AP460e-WR | 97408-AP460e- WR | \$ 303.00 | 10% | \$274.75 |
| EW MonitorPLS 4HROnsite AP460i-CAN | 97408-AP460i- CAN | \$ 303.00 | 10% | \$274.75 |
| EW MonitorPLS 4HROnsite AP460i-FCC | 97408-AP460i- FCC | \$ 303.00 | 10% | \$274.75 |
| EW MonitorPLS 4HROnsite AP460i-IL | 97408-AP460i- IL | \$ 303.00 | 10% | \$274.75 |
| EW MonitorPLS 4HROnsite AP460i-WR | 97408-AP460i- WR | \$ 303.00 | 10% | \$274.75 |

| | | | | |
|---|-----------------------------|-----------|-----|----------|
| EW MonitorPLS 4HROnsite AP460S12C-CAN | 97408- AP460S12C- CAN | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460S12C-FCC | 97408- AP460S12C- FCC | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460S12C-WR | 97408- AP460S12C- WR | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460S6C-CAN | 97408- AP460S6C- CAN | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460S6C-FCC | 97408- AP460S6C- FCC | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP460S6C-WR | 97408- AP460S6C- WR | \$ 325.00 | 10% | \$294.69 |
| EW MonitorPLS 4HROnsite AP5010-IL | 97408-AP5010- IL | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS 4HROnsite AP5010-WW | 97408-AP5010- WW | \$ 329.00 | 10% | \$298.32 |
| EW MonitorPLS 4HROnsite AP5020-WW | 97408-AP5020- WW | \$ 355.34 | 6% | \$336.52 |
| EW MonitorPLS 4HROnsite AP5050D-WW | 97408- AP5050D-WW | \$ 565.00 | 10% | \$512.31 |
| EW MonitorPLS 4HROnsite AP5050U-WW | 97408- AP5050U-WW | \$ 466.00 | 10% | \$422.55 |
| EW MonitorPLS 4HROnsite AP505i-FCC | 97408-AP505i- FCC | \$ 313.00 | 10% | \$283.81 |
| EW MonitorPLS 4HROnsite AP505i-FCC-TAA | 97408-AP505i- FCC-TAA | \$ 313.00 | 10% | \$283.81 |
| EW MonitorPLS 4HROnsite AP505i-WR | 97408-AP505i- WR | \$ 328.00 | 10% | \$297.41 |
| EW MonitorPLS 4HROnsite AP510C-CAN | 97408-AP510C- CAN | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP510C-CE | 97408-AP510C- CE | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP510C-FCC | 97408-AP510C- FCC | \$ 284.00 | 10% | \$257.52 |
| EW MonitorPLS 4HROnsite AP510C-W | 97408-AP510C- W | \$ 284.00 | 10% | \$257.52 |

| | | | | |
|---|---------------------------|-----------|-----|-----------------|
| EW MonitorPLS 4HROnsite AP510C-WW | 97408-AP510C- WW | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW MonitorPLS 4HROnsite AP510CX-CAN | 97408- AP510CX- CAN | \$ 284.00 | 10% | <i>\$257.52</i> |
| EW MonitorPLS 4HROnsite AP510CX-CE | 97408- AP510CX-CE | \$ 284.00 | 10% | <i>\$257.52</i> |
| EW MonitorPLS 4HROnsite AP510CX-FCC | 97408- AP510CX- FCC | \$ 284.00 | 10% | <i>\$257.52</i> |
| EW MonitorPLS 4HROnsite AP510CX-W | 97408- AP510CX-W | \$ 284.00 | 10% | <i>\$257.52</i> |
| EW MonitorPLS 4HROnsite AP510CX-WW | 97408- AP510CX-WW | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW MonitorPLS 4HROnsite AP510e-FCC | 97408-AP510e- FCC | \$ 372.00 | 10% | <i>\$337.31</i> |
| EW MonitorPLS 4HROnsite AP510e-FCC-TAA | 97408-AP510e- FCC-TAA | \$ 372.00 | 10% | <i>\$337.31</i> |
| EW MonitorPLS 4HROnsite AP510e-WR | 97408-AP510e- WR | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW MonitorPLS 4HROnsite AP510i-1-FCC | 97408-AP510i- 1-FCC | \$ 331.00 | 10% | <i>\$300.13</i> |
| EW MonitorPLS 4HROnsite AP510i-1-WR | 97408-AP510i- 1-WR | \$ 331.00 | 10% | <i>\$300.13</i> |
| EW MonitorPLS 4HROnsite AP510i-FCC | 97408-AP510i- FCC | \$ 347.00 | 10% | <i>\$314.64</i> |
| EW MonitorPLS 4HROnsite AP510i-FCC-TAA | 97408-AP510i- FCC-TAA | \$ 347.00 | 10% | <i>\$314.64</i> |
| EW MonitorPLS 4HROnsite AP510i-WR | 97408-AP510i- WR | \$ 347.00 | 10% | <i>\$314.64</i> |
| EW MonitorPLS 4HROnsite AP560h-FCC | 97408-AP560h- FCC | \$ 610.00 | 10% | <i>\$553.12</i> |
| EW MonitorPLS 4HROnsite AP560h-WR | 97408-AP560h- WR | \$ 610.00 | 10% | <i>\$553.12</i> |
| EW MonitorPLS 4HROnsite AP560i-FCC | 97408-AP560i- FCC | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW MonitorPLS 4HROnsite AP560i-WR | 97408-AP560i- WR | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW MonitorPLS 4HROnsite AP560m-FCC | 97408-AP560m- FCC | \$ 491.00 | 10% | <i>\$445.21</i> |

| | | | | |
|---------------------------------------|----------------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite AP560t-FCC | 97408-AP560t- FCC | \$ 610.00 | 10% | <i>\$553.12</i> |
| EW MonitorPLS 4HROnsite AP560u-FCC | 97408-AP560u- FCC | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW MonitorPLS 4HROnsite E2122 | 97408-E2122 | \$ 8,034.00 | 10% | <i>\$7,284.83</i> |
| EW MonitorPLS 4HROnsite E2122-1 | 97408-E2122-1 | \$ 7,614.00 | 10% | <i>\$6,903.99</i> |
| EW MonitorPLS 4HROnsite E3120-1 | 97408-E3120-1 | \$ 12,063.00 | 10% | <i>\$10,938.13</i> |
| EW MonitorPLS 4HROnsite E3125 | 97408-E3125 | \$ 13,200.00 | 10% | <i>\$11,969.10</i> |
| EW MonitorPLS 4HROnsite- H30131 | 97408-H30131 | \$ 2,743.00 | 10% | <i>\$2,487.22</i> |
| EW MonitorPLS 4HROnsite- H30132 | 97408-H30132 | \$ 2,690.00 | 10% | <i>\$2,439.16</i> |
| EW MonitorPLS 4HROnsite- H30133 | 97408-H30133 | \$ 5,996.00 | 10% | <i>\$5,436.87</i> |
| EW MonitorPLS 4HROnsite- H30134 | 97408-H30134 | \$ 7,412.00 | 10% | <i>\$6,720.83</i> |
| EW MonitorPLS 4HROnsite- H30135 | 97408-H30135 | \$ 6,113.00 | 10% | <i>\$5,542.96</i> |
| EW MonitorPLS 4HROnsite- H30136 | 97408-H30136 | \$ 7,412.00 | 10% | <i>\$6,720.83</i> |
| EW MonitorPLS 4HROnsite- H30184 | 97408-H30184 | \$ 776.00 | 10% | <i>\$703.64</i> |
| EW MonitorPLS 4HROnsite- H30185 | 97408-H30185 | \$ 1,188.00 | 10% | <i>\$1,077.22</i> |
| EW MonitorPLS 4HROnsite- H30186 | 97408-H30186 | \$ 949.00 | 10% | <i>\$860.51</i> |
| EW MonitorPLS 4HROnsite- H30187 | 97408-H30187 | \$ 846.00 | 10% | <i>\$767.11</i> |
| EW MonitorPLS 4HROnsite- H30188 | 97408-H30188 | \$ 949.00 | 10% | <i>\$860.51</i> |
| EW MonitorPLS 4HROnsite- H30189 | 97408-H30189 | \$ 949.00 | 10% | <i>\$860.51</i> |
| EW MonitorPLS 4HROnsite- H30190 | 97408-H30190 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HROnsite- H30214 | 97408-H30214 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HROnsite- H30215 | 97408-H30215 | \$ 1,014.00 | 10% | <i>\$919.44</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HRonsite-H30216 | 97408-H30216 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30217 | 97408-H30217 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30218 | 97408-H30218 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30219 | 97408-H30219 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30220 | 97408-H30220 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30221 | 97408-H30221 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30222 | 97408-H30222 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30223 | 97408-H30223 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30224 | 97408-H30224 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30225 | 97408-H30225 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30226 | 97408-H30226 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30227 | 97408-H30227 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30228 | 97408-H30228 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30229 | 97408-H30229 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30267 | 97408-H30267 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30268 | 97408-H30268 | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLS 4HRonsite-H30269 | 97408-H30269 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30270 | 97408-H30270 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30271 | 97408-H30271 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30272 | 97408-H30272 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HRonsite-H30273 | 97408-H30273 | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite-H30274 | 97408-H30274 | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-H30275 | 97408-H30275 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HROnsite-H30276 | 97408-H30276 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HROnsite-H30277 | 97408-H30277 | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-H30278 | 97408-H30278 | \$ 1,982.00 | 10% | <i>\$1,797.18</i> |
| EW MonitorPLS 4HROnsite-H30279 | 97408-H30279 | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-H30280 | 97408-H30280 | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-H30281 | 97408-H30281 | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-H30282 | 97408-H30282 | \$ 1,872.00 | 10% | <i>\$1,697.44</i> |
| EW MonitorPLS 4HROnsite-H30283 | 97408-H30283 | \$ 1,429.00 | 10% | <i>\$1,295.75</i> |
| EW MonitorPLS 4HROnsite-H30284 | 97408-H30284 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS 4HROnsite-H30296 | 97408-H30296 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HROnsite-H30297 | 97408-H30297 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HROnsite-H30298 | 97408-H30298 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HROnsite-H30299 | 97408-H30299 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS 4HROnsite-H30381 | 97408-H30381 | \$ 1,961.00 | 10% | <i>\$1,778.14</i> |
| EW MonitorPLS 4HROnsite-H30384 | 97408-H30384 | \$ 1,810.00 | 10% | <i>\$1,641.22</i> |
| EW MonitorPLS 4HROnsite-H30391 | 97408-H30391 | \$ 1,641.00 | 10% | <i>\$1,487.98</i> |
| EW MonitorPLS 4HROnsite-H30392 | 97408-H30392 | \$ 1,641.00 | 10% | <i>\$1,487.98</i> |
| EW MonitorPLS 4HROnsite-H30393 | 97408-H30393 | \$ 863.00 | 10% | <i>\$782.53</i> |
| EW MonitorPLS 4HROnsite-H30394 | 97408-H30394 | \$ 2,947.00 | 10% | <i>\$2,672.19</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS 4HROnsite-H30395 | 97408-H30395 | \$ 3,463.00 | 10% | \$3,140.08 |
| EW MonitorPLS 4HROnsite-H30396 | 97408-H30396 | \$ 3,172.00 | 10% | \$2,876.21 |
| EW MonitorPLS 4HROnsite-H30397 | 97408-H30397 | \$ 3,725.00 | 10% | \$3,377.64 |
| EW MonitorPLS 4HROnsite-H30398 | 97408-H30398 | \$ 880.00 | 10% | \$797.94 |
| EW MonitorPLS 4HROnsite-H30400 | 97408-H30400 | \$ 599.00 | 10% | \$543.14 |
| EW MonitorPLS 4HROnsite-H30401 | 97408-H30401 | \$ 735.00 | 10% | \$666.46 |
| EW MonitorPLS 4HROnsite-H30402 | 97408-H30402 | \$ 765.00 | 10% | \$693.66 |
| EW MonitorPLS 4HROnsite-H30403 | 97408-H30403 | \$ 1,031.00 | 10% | \$934.86 |
| EW MonitorPLS 4HROnsite-H30480 | 97408-H30480 | \$ 2,124.00 | 10% | \$1,925.94 |
| EW MonitorPLS 4HROnsite-H30495 | 97408-H30495 | \$ 3,300.00 | 10% | \$2,992.28 |
| EW MonitorPLS 4HROnsite-H30496 | 97408-H30496 | \$ 3,236.00 | 10% | \$2,934.24 |
| EW MonitorPLS 4HROnsite-H30497 | 97408-H30497 | \$ 4,218.00 | 10% | \$3,824.67 |
| EW MonitorPLS 4HROnsite-H30498 | 97408-H30498 | \$ 4,137.00 | 10% | \$3,751.22 |
| EW MonitorPLS 4HROnsite-H30499 | 97408-H30499 | \$ 1,254.00 | 10% | \$1,137.06 |
| EW MonitorPLS 4HROnsite-H30501 | 97408-H30501 | \$ 4,137.00 | 10% | \$3,751.22 |
| EW MonitorPLS 4HROnsite-H30502 | 97408-H30502 | \$ 5,712.00 | 10% | \$5,179.36 |
| EW MonitorPLS 4HROnsite-H30503 | 97408-H30503 | \$ 1,254.00 | 10% | \$1,137.06 |
| EW MonitorPLS 4HROnsite-H30505 | 97408-H30505 | \$ 6,544.00 | 10% | \$5,933.77 |
| EW MonitorPLS 4HROnsite-H30506 | 97408-H30506 | \$ 8,455.00 | 10% | \$7,666.57 |
| EW MonitorPLS 4HROnsite-H30509 | 97408-H30509 | \$ 5,712.00 | 10% | \$5,179.36 |
| EW MonitorPLS 4HROnsite-H30510 | 97408-H30510 | \$ 6,544.00 | 10% | \$5,933.77 |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite-H30511 | 97408-H30511 | \$ 8,455.00 | 10% | <i>\$7,666.57</i> |
| EW MonitorPLS 4HROnsite-H30512 | 97408-H30512 | \$ 1,254.00 | 10% | <i>\$1,137.06</i> |
| EW MonitorPLS 4HROnsite-H30513 | 97408-H30513 | \$ 1,941.00 | 10% | <i>\$1,760.00</i> |
| EW MonitorPLS 4HROnsite-H30525 | 97408-H30525 | \$ 7,495.00 | 10% | <i>\$6,796.09</i> |
| EW MonitorPLS 4HROnsite-H30526 | 97408-H30526 | \$ 5,579.00 | 10% | <i>\$5,058.76</i> |
| EW MonitorPLS 4HROnsite-H30528 | 97408-H30528 | \$ 8,659.00 | 10% | <i>\$7,851.55</i> |
| EW MonitorPLS 4HROnsite-H30531 | 97408-H30531 | \$ 12,224.00 | 10% | <i>\$11,084.11</i> |
| EW MonitorPLS 4HROnsite-H30532 | 97408-H30532 | \$ 12,224.00 | 10% | <i>\$11,084.11</i> |
| EW MonitorPLS 4HROnsite-H30534 | 97408-H30534 | \$ 12,460.00 | 10% | <i>\$11,298.11</i> |
| EW MonitorPLS 4HROnsite-H30535 | 97408-H30535 | \$ 13,265.00 | 10% | <i>\$12,028.04</i> |
| EW MonitorPLS 4HROnsite-H30536 | 97408-H30536 | \$ 12,224.00 | 10% | <i>\$11,084.11</i> |
| EW MonitorPLS 4HROnsite-H30537 | 97408-H30537 | \$ 13,265.00 | 10% | <i>\$12,028.04</i> |
| EW MonitorPLS 4HROnsite-H30538 | 97408-H30538 | \$ 7,495.00 | 10% | <i>\$6,796.09</i> |
| EW MonitorPLS 4HROnsite-H30539 | 97408-H30539 | \$ 14,168.00 | 10% | <i>\$12,846.83</i> |
| EW MonitorPLS 4HROnsite-H30540 | 97408-H30540 | \$ 14,644.00 | 10% | <i>\$13,278.45</i> |
| EW MonitorPLS 4HROnsite-H30543 | 97408-H30543 | \$ 1,230.00 | 10% | <i>\$1,115.30</i> |
| EW MonitorPLS 4HROnsite-H30544 | 97408-H30544 | \$ 1,995.00 | 10% | <i>\$1,808.97</i> |
| EW MonitorPLS 4HROnsite-H30548 | 97408-H30548 | \$ 1,230.00 | 10% | <i>\$1,115.30</i> |
| EW MonitorPLS 4HROnsite-H30549 | 97408-H30549 | \$ 1,905.00 | 10% | <i>\$1,727.36</i> |
| EW MonitorPLS 4HROnsite-H30550 | 97408-H30550 | \$ 1,905.00 | 10% | <i>\$1,727.36</i> |
| EW MonitorPLS 4HROnsite-H30552 | 97408-H30552 | \$ 1,230.00 | 10% | <i>\$1,115.30</i> |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite-H30553 | 97408-H30553 | \$ 1,803.00 | 10% | <i>\$1,634.87</i> |
| EW MonitorPLS 4HROnsite-H30569 | 97408-H30569 | \$ 5,996.00 | 10% | <i>\$5,436.87</i> |
| EW MonitorPLS 4HROnsite-H30570 | 97408-H30570 | \$ 7,057.00 | 10% | <i>\$6,398.93</i> |
| EW MonitorPLS 4HROnsite-H30571 | 97408-H30571 | \$ 7,057.00 | 10% | <i>\$6,398.93</i> |
| EW MonitorPLS 4HROnsite-H30573 | 97408-H30573 | \$ 5,996.00 | 10% | <i>\$5,436.87</i> |
| EW MonitorPLS 4HROnsite-H30574 | 97408-H30574 | \$ 6,573.00 | 10% | <i>\$5,960.07</i> |
| EW MonitorPLS 4HROnsite-H30575 | 97408-H30575 | \$ 4,350.00 | 10% | <i>\$3,944.36</i> |
| EW MonitorPLS 4HROnsite-H30576 | 97408-H30576 | \$ 5,996.00 | 10% | <i>\$5,436.87</i> |
| EW MonitorPLS 4HROnsite-H30577 | 97408-H30577 | \$ 6,923.00 | 10% | <i>\$6,277.43</i> |
| EW MonitorPLS 4HROnsite-H30578 | 97408-H30578 | \$ 6,923.00 | 10% | <i>\$6,277.43</i> |
| EW MonitorPLS 4HROnsite-H30587 | 97408-H30587 | \$ 5,687.00 | 10% | <i>\$5,156.69</i> |
| EW MonitorPLS 4HROnsite-H30588 | 97408-H30588 | \$ 4,008.00 | 10% | <i>\$3,634.25</i> |
| EW MonitorPLS 4HROnsite-H30589 | 97408-H30589 | \$ 6,074.00 | 10% | <i>\$5,507.60</i> |
| EW MonitorPLS 4HROnsite-H30632 | 97408-H30632 | \$ 331.00 | 10% | <i>\$300.13</i> |
| EW MonitorPLS 4HROnsite-H30633 | 97408-H30633 | \$ 331.00 | 10% | <i>\$300.13</i> |
| EW MonitorPLS 4HROnsite-H30643 | 97408-H30643 | \$ 10,608.00 | 10% | <i>\$9,618.80</i> |
| EW MonitorPLS 4HROnsite-H30706 | 97408-H30706 | \$ 8,828.00 | 10% | <i>\$8,004.79</i> |
| EW MonitorPLS 4HROnsite-H30707 | 97408-H30707 | \$ 5,579.00 | 10% | <i>\$5,058.76</i> |
| EW MonitorPLS 4HROnsite-H30724 | 97408-H30724 | \$ 769.00 | 10% | <i>\$697.29</i> |
| EW MonitorPLS 4HROnsite-H30725 | 97408-H30725 | \$ 2,690.00 | 10% | <i>\$2,439.16</i> |
| EW MonitorPLS 4HROnsite-H30726 | 97408-H30726 | \$ 13,524.00 | 10% | <i>\$12,262.89</i> |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite-H30727 | 97408-H30727 | \$ 14,365.00 | 10% | <i>\$13,025.46</i> |
| EW MonitorPLS 4HROnsite-H30730 | 97408-H30730 | \$ 297.00 | 10% | <i>\$269.30</i> |
| EW MonitorPLS 4HROnsite-H30731 | 97408-H30731 | \$ 297.00 | 10% | <i>\$269.30</i> |
| EW MonitorPLS 4HROnsite-H30733 | 97408-H30733 | \$ 12,703.00 | 10% | <i>\$11,518.45</i> |
| EW MonitorPLS 4HROnsite-H30734 | 97408-H30734 | \$ 9,746.00 | 10% | <i>\$8,837.19</i> |
| EW MonitorPLS 4HROnsite-H30735 | 97408-H30735 | \$ 11,326.00 | 10% | <i>\$10,269.85</i> |
| EW MonitorPLS 4HROnsite-H30736 | 97408-H30736 | \$ 1,970.00 | 10% | <i>\$1,786.30</i> |
| EW MonitorPLS 4HROnsite-H30738 | 97408-H30738 | \$ 249.00 | 10% | <i>\$225.78</i> |
| EW MonitorPLS 4HROnsite H31337 | 97408-H31337 | \$ 13,079.00 | 10% | <i>\$11,859.38</i> |
| EW MonitorPLS 4HROnsite H31338 | 97408-H31338 | \$ 13,079.00 | 10% | <i>\$11,859.38</i> |
| EW MonitorPLS 4HROnsite H31341 | 97408-H31341 | \$ 6,944.00 | 10% | <i>\$6,296.47</i> |
| EW MonitorPLS 4HROnsite H31342 | 97408-H31342 | \$ 2,046.00 | 10% | <i>\$1,855.21</i> |
| EW MonitorPLS 4HROnsite H31343 | 97408-H31343 | \$ 2,907.00 | 10% | <i>\$2,635.92</i> |
| EW MonitorPLS 4HROnsite H31344 | 97408-H31344 | \$ 2,907.00 | 10% | <i>\$2,635.92</i> |
| EW MonitorPLS 4HROnsite H31345 | 97408-H31345 | \$ 2,907.00 | 10% | <i>\$2,635.92</i> |
| EW MonitorPLS 4HROnsite H31346 | 97408-H31346 | \$ 2,907.00 | 10% | <i>\$2,635.92</i> |
| EW MonitorPLS 4HROnsite H31362 | 97408-H31362 | \$ 35,632.00 | 10% | <i>\$32,309.32</i> |
| EW MonitorPLS 4HROnsite H31363 | 97408-H31363 | \$ 35,632.00 | 10% | <i>\$32,309.32</i> |
| EW MonitorPLS 4HROnsite H31364 | 97408-H31364 | \$ 12,910.00 | 10% | <i>\$11,706.14</i> |
| EW MonitorPLS 4HROnsite H31365 | 97408-H31365 | \$ 12,910.00 | 10% | <i>\$11,706.14</i> |
| EW MonitorPLS 4HROnsite H31366 | 97408-H31366 | \$ 17,894.00 | 10% | <i>\$16,225.38</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H31367 | 97408-H31367 | \$ 17,894.00 | 10% | <i>\$16,225.38</i> |
| EW MonitorPLS 4HROnsite H32010 | 97408-H32010 | \$ 1,244.00 | 10% | <i>\$1,128.00</i> |
| EW MonitorPLS 4HROnsite H32011 | 97408-H32011 | \$ 1,244.00 | 10% | <i>\$1,128.00</i> |
| EW MonitorPLS 4HROnsite H32012 | 97408-H32012 | \$ 4,409.00 | 10% | <i>\$3,997.86</i> |
| EW MonitorPLS 4HROnsite H32013 | 97408-H32013 | \$ 4,409.00 | 10% | <i>\$3,997.86</i> |
| EW MonitorPLS 4HROnsite H32014 | 97408-H32014 | \$ 4,409.00 | 10% | <i>\$3,997.86</i> |
| EW MonitorPLS 4HROnsite H32015 | 97408-H32015 | \$ 4,409.00 | 10% | <i>\$3,997.86</i> |
| EW MonitorPLS 4HROnsite H32016 | 97408-H32016 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HROnsite H32017 | 97408-H32017 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HROnsite H32018 | 97408-H32018 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HROnsite H32019 | 97408-H32019 | \$ 3,941.00 | 10% | <i>\$3,573.50</i> |
| EW MonitorPLS 4HROnsite H32020 | 97408-H32020 | \$ 36,872.00 | 10% | <i>\$33,433.69</i> |
| EW MonitorPLS 4HROnsite H32021 | 97408-H32021 | \$ 36,872.00 | 10% | <i>\$33,433.69</i> |
| EW MonitorPLS 4HROnsite H32022 | 97408-H32022 | \$ 36,872.00 | 10% | <i>\$33,433.69</i> |
| EW MonitorPLS 4HROnsite H32023 | 97408-H32023 | \$ 36,872.00 | 10% | <i>\$33,433.69</i> |
| EW MonitorPLS 4HROnsite H32028 | 97408-H32028 | \$ 70,034.00 | 10% | <i>\$63,503.33</i> |
| EW MonitorPLS 4HROnsite H32029 | 97408-H32029 | \$ 70,034.00 | 10% | <i>\$63,503.33</i> |
| EW MonitorPLS 4HROnsite H32030 | 97408-H32030 | \$ 73,444.00 | 10% | <i>\$66,595.35</i> |
| EW MonitorPLS 4HROnsite H32031 | 97408-H32031 | \$ 73,444.00 | 10% | <i>\$66,595.35</i> |
| EW MonitorPLS 4HROnsite H32032 | 97408-H32032 | \$ 73,444.00 | 10% | <i>\$66,595.35</i> |
| EW MonitorPLS 4HROnsite H32033 | 97408-H32033 | \$ 73,444.00 | 10% | <i>\$66,595.35</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32038 | 97408-H32038 | \$ 13,310.00 | 10% | <i>\$12,068.84</i> |
| EW MonitorPLS 4HROnsite H32039 | 97408-H32039 | \$ 13,310.00 | 10% | <i>\$12,068.84</i> |
| EW MonitorPLS 4HROnsite H32040 | 97408-H32040 | \$ 13,310.00 | 10% | <i>\$12,068.84</i> |
| EW MonitorPLS 4HROnsite H32041 | 97408-H32041 | \$ 13,310.00 | 10% | <i>\$12,068.84</i> |
| EW MonitorPLS 4HROnsite H32046 | 97408-H32046 | \$ 18,445.00 | 10% | <i>\$16,725.00</i> |
| EW MonitorPLS 4HROnsite H32047 | 97408-H32047 | \$ 18,445.00 | 10% | <i>\$16,725.00</i> |
| EW MonitorPLS 4HROnsite H32048 | 97408-H32048 | \$ 18,445.00 | 10% | <i>\$16,725.00</i> |
| EW MonitorPLS 4HROnsite H32049 | 97408-H32049 | \$ 18,445.00 | 10% | <i>\$16,725.00</i> |
| EW MonitorPLS 4HROnsite H32054 | 97408-H32054 | \$ 13,310.00 | 10% | <i>\$12,068.84</i> |
| EW MonitorPLS 4HROnsite H32055 | 97408-H32055 | \$ 18,445.00 | 10% | <i>\$16,725.00</i> |
| EW MonitorPLS 4HROnsite H32056 | 97408-H32056 | \$ 5,077.00 | 10% | <i>\$4,603.57</i> |
| EW MonitorPLS 4HROnsite H32057 | 97408-H32057 | \$ 5,228.00 | 10% | <i>\$4,740.49</i> |
| EW MonitorPLS 4HROnsite H32058 | 97408-H32058 | \$ 5,228.00 | 10% | <i>\$4,740.49</i> |
| EW MonitorPLS 4HROnsite H32059 | 97408-H32059 | \$ 5,228.00 | 10% | <i>\$4,740.49</i> |
| EW MonitorPLS 4HROnsite H32060 | 97408-H32060 | \$ 6,195.00 | 10% | <i>\$5,617.32</i> |
| EW MonitorPLS 4HROnsite H32061 | 97408-H32061 | \$ 6,505.00 | 10% | <i>\$5,898.41</i> |
| EW MonitorPLS 4HROnsite H32062 | 97408-H32062 | \$ 6,255.00 | 10% | <i>\$5,671.72</i> |
| EW MonitorPLS 4HROnsite H32063 | 97408-H32063 | \$ 6,202.00 | 10% | <i>\$5,623.66</i> |
| EW MonitorPLS 4HROnsite H32064 | 97408-H32064 | \$ 6,255.00 | 10% | <i>\$5,671.72</i> |
| EW MonitorPLS 4HROnsite H32065 | 97408-H32065 | \$ 5,720.00 | 10% | <i>\$5,186.61</i> |
| EW MonitorPLS 4HROnsite H32066 | 97408-H32066 | \$ 5,720.00 | 10% | <i>\$5,186.61</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32067 | 97408-H32067 | \$ 5,720.00 | 10% | <i>\$5,186.61</i> |
| EW MonitorPLS 4HROnsite H32068 | 97408-H32068 | \$ 5,720.00 | 10% | <i>\$5,186.61</i> |
| EW MonitorPLS 4HROnsite H32069 | 97408-H32069 | \$ 6,906.00 | 10% | <i>\$6,262.02</i> |
| EW MonitorPLS 4HROnsite H32070 | 97408-H32070 | \$ 6,906.00 | 10% | <i>\$6,262.02</i> |
| EW MonitorPLS 4HROnsite H32071 | 97408-H32071 | \$ 6,906.00 | 10% | <i>\$6,262.02</i> |
| EW MonitorPLS 4HROnsite H32072 | 97408-H32072 | \$ 6,906.00 | 10% | <i>\$6,262.02</i> |
| EW MonitorPLS 4HROnsite H32073 | 97408-H32073 | \$ 46,676.00 | 10% | <i>\$42,323.46</i> |
| EW MonitorPLS 4HROnsite H32074 | 97408-H32074 | \$ 46,676.00 | 10% | <i>\$42,323.46</i> |
| EW MonitorPLS 4HROnsite H32075 | 97408-H32075 | \$ 63,460.00 | 10% | <i>\$57,542.36</i> |
| EW MonitorPLS 4HROnsite H32076 | 97408-H32076 | \$ 63,461.00 | 10% | <i>\$57,543.26</i> |
| EW MonitorPLS 4HROnsite H32101 | 97408-H32101 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS 4HROnsite H32102 | 97408-H32102 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS 4HROnsite H32103 | 97408-H32103 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS 4HROnsite H32104 | 97408-H32104 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS 4HROnsite H32105 | 97408-H32105 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32106 | 97408-H32106 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32107 | 97408-H32107 | \$ 11,591.00 | 10% | <i>\$10,510.14</i> |
| EW MonitorPLS 4HROnsite H32108 | 97408-H32108 | \$ 11,591.00 | 10% | <i>\$10,510.14</i> |
| EW MonitorPLS 4HROnsite H32109 | 97408-H32109 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32110 | 97408-H32110 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32111 | 97408-H32111 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32112 | 97408-H32112 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS 4HROnsite H32113 | 97408-H32113 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS 4HROnsite H32114 | 97408-H32114 | \$ 2,851.00 | 10% | <i>\$2,585.14</i> |
| EW MonitorPLS 4HROnsite H32115 | 97408-H32115 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32116 | 97408-H32116 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32117 | 97408-H32117 | \$ 2,728.00 | 10% | <i>\$2,473.61</i> |
| EW MonitorPLS 4HROnsite H32118 | 97408-H32118 | \$ 2,728.00 | 10% | <i>\$2,473.61</i> |
| EW MonitorPLS 4HROnsite H32119 | 97408-H32119 | \$ 2,728.00 | 10% | <i>\$2,473.61</i> |
| EW MonitorPLS 4HROnsite H32120 | 97408-H32120 | \$ 2,728.00 | 10% | <i>\$2,473.61</i> |
| EW MonitorPLS 4HROnsite H32121 | 97408-H32121 | \$ 11,591.00 | 10% | <i>\$10,510.14</i> |
| EW MonitorPLS 4HROnsite H32122 | 97408-H32122 | \$ 11,591.00 | 10% | <i>\$10,510.14</i> |
| EW MonitorPLS 4HROnsite H32123 | 97408-H32123 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32124 | 97408-H32124 | \$ 4,831.00 | 10% | <i>\$4,380.51</i> |
| EW MonitorPLS 4HROnsite H32125 | 97408-H32125 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32126 | 97408-H32126 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32127 | 97408-H32127 | \$ 5,418.00 | 10% | <i>\$4,912.77</i> |
| EW MonitorPLS 4HROnsite H32128 | 97408-H32128 | \$ 5,418.00 | 10% | <i>\$4,912.77</i> |
| EW MonitorPLS 4HROnsite H32129 | 97408-H32129 | \$ 5,418.00 | 10% | <i>\$4,912.77</i> |
| EW MonitorPLS 4HROnsite H32130 | 97408-H32130 | \$ 5,418.00 | 10% | <i>\$4,912.77</i> |
| EW MonitorPLS 4HROnsite H32131 | 97408-H32131 | \$ 5,418.00 | 10% | <i>\$4,912.77</i> |
| EW MonitorPLS 4HROnsite H32132 | 97408-H32132 | \$ 5,418.00 | 10% | <i>\$4,912.77</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32133 | 97408-H32133 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32134 | 97408-H32134 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32135 | 97408-H32135 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32136 | 97408-H32136 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32137 | 97408-H32137 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32138 | 97408-H32138 | \$ 4,724.00 | 10% | <i>\$4,283.49</i> |
| EW MonitorPLS 4HROnsite H32139 | 97408-H32139 | \$ 19,112.00 | 10% | <i>\$17,329.81</i> |
| EW MonitorPLS 4HROnsite H32140 | 97408-H32140 | \$ 19,112.00 | 10% | <i>\$17,329.81</i> |
| EW MonitorPLS 4HROnsite H32141 | 97408-H32141 | \$ 22,421.00 | 10% | <i>\$20,330.24</i> |
| EW MonitorPLS 4HROnsite H32142 | 97408-H32142 | \$ 22,421.00 | 10% | <i>\$20,330.24</i> |
| EW MonitorPLS 4HROnsite H32146 | 97408-H32146 | \$ 2,702.00 | 10% | <i>\$2,450.04</i> |
| EW MonitorPLS 4HROnsite H32147 | 97408-H32147 | \$ 2,702.00 | 10% | <i>\$2,450.04</i> |
| EW MonitorPLS 4HROnsite H32148 | 97408-H32148 | \$ 4,576.00 | 10% | <i>\$4,149.29</i> |
| EW MonitorPLS 4HROnsite H32149 | 97408-H32149 | \$ 4,576.00 | 10% | <i>\$4,149.29</i> |
| EW MonitorPLS 4HROnsite H32150 | 97408-H32150 | \$ 2,702.00 | 10% | <i>\$2,450.04</i> |
| EW MonitorPLS 4HROnsite H32169 | 97408-H32169 | \$ 2,884.00 | 10% | <i>\$2,615.07</i> |
| EW MonitorPLS 4HROnsite H32170 | 97408-H32170 | \$ 2,884.00 | 10% | <i>\$2,615.07</i> |
| EW MonitorPLS 4HROnsite H32171 | 97408-H32171 | \$ 2,759.00 | 10% | <i>\$2,501.72</i> |
| EW MonitorPLS 4HROnsite H32172 | 97408-H32172 | \$ 2,759.00 | 10% | <i>\$2,501.72</i> |
| EW MonitorPLS 4HROnsite H32173 | 97408-H32173 | \$ 5,893.00 | 10% | <i>\$5,343.48</i> |
| EW MonitorPLS 4HROnsite H32174 | 97408-H32174 | \$ 5,893.00 | 10% | <i>\$5,343.48</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32175 | 97408-H32175 | \$ 5,137.00 | 10% | <i>\$4,657.97</i> |
| EW MonitorPLS 4HROnsite H32176 | 97408-H32176 | \$ 5,137.00 | 10% | <i>\$4,657.97</i> |
| EW MonitorPLS 4HROnsite H32177 | 97408-H32177 | \$ 21,412.00 | 10% | <i>\$19,415.33</i> |
| EW MonitorPLS 4HROnsite H32178 | 97408-H32178 | \$ 25,116.00 | 10% | <i>\$22,773.93</i> |
| EW MonitorPLS 4HROnsite H34008 | 97408-H34008 | \$ 758.00 | 10% | <i>\$687.32</i> |
| EW MonitorPLS 4HROnsite H34009 | 97408-H34009 | \$ 893.00 | 10% | <i>\$809.73</i> |
| EW MonitorPLS 4HROnsite H34010 | 97408-H34010 | \$ 728.00 | 10% | <i>\$660.11</i> |
| EW MonitorPLS 4HROnsite H34011 | 97408-H34011 | \$ 869.00 | 10% | <i>\$787.97</i> |
| EW MonitorPLS 4HROnsite H34012 | 97408-H34012 | \$ 1,019.00 | 10% | <i>\$923.98</i> |
| EW MonitorPLS 4HROnsite H34013 | 97408-H34013 | \$ 809.00 | 10% | <i>\$733.56</i> |
| EW MonitorPLS 4HROnsite H34014 | 97408-H34014 | \$ 893.00 | 10% | <i>\$809.73</i> |
| EW MonitorPLS 4HROnsite H34015 | 97408-H34015 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW MonitorPLS 4HROnsite H34016 | 97408-H34016 | \$ 913.00 | 10% | <i>\$827.86</i> |
| EW MonitorPLS 4HROnsite H34017 | 97408-H34017 | \$ 1,081.00 | 10% | <i>\$980.20</i> |
| EW MonitorPLS 4HROnsite H34018 | 97408-H34018 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW MonitorPLS 4HROnsite H34019 | 97408-H34019 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW MonitorPLS 4HROnsite H34020 | 97408-H34020 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW MonitorPLS 4HROnsite H34021 | 97408-H34021 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW MonitorPLS 4HROnsite H34048 | 97408-H34048 | \$ 1,340.00 | 10% | <i>\$1,215.05</i> |
| EW MonitorPLS 4HROnsite H34049 | 97408-H34049 | \$ 1,340.00 | 10% | <i>\$1,215.05</i> |
| EW MonitorPLS 4HROnsite H34050 | 97408-H34050 | \$ 1,169.00 | 10% | <i>\$1,059.99</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite H34051 | 97408-H34051 | \$ 1,169.00 | 10% | <i>\$1,059.99</i> |
| EW MonitorPLS 4HROnsite H34052 | 97408-H34052 | \$ 1,459.00 | 10% | <i>\$1,322.95</i> |
| EW MonitorPLS 4HROnsite H34053 | 97408-H34053 | \$ 1,459.00 | 10% | <i>\$1,322.95</i> |
| EW MonitorPLS 4HROnsite H34054 | 97408-H34054 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW MonitorPLS 4HROnsite H34055 | 97408-H34055 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW MonitorPLS 4HROnsite H34056 | 97408-H34056 | \$ 1,591.00 | 10% | <i>\$1,442.64</i> |
| EW MonitorPLS 4HROnsite H34057 | 97408-H34057 | \$ 1,591.00 | 10% | <i>\$1,442.64</i> |
| EW MonitorPLS 4HROnsite H34058 | 97408-H34058 | \$ 1,461.00 | 10% | <i>\$1,324.76</i> |
| EW MonitorPLS 4HROnsite H34059 | 97408-H34059 | \$ 1,461.00 | 10% | <i>\$1,324.76</i> |
| EW MonitorPLS 4HROnsite H34062 | 97408-H34062 | \$ 1,591.00 | 10% | <i>\$1,442.64</i> |
| EW MonitorPLS 4HROnsite H34063 | 97408-H34063 | \$ 1,591.00 | 10% | <i>\$1,442.64</i> |
| EW MonitorPLS 4HROnsite H34064 | 97408-H34064 | \$ 1,222.00 | 10% | <i>\$1,108.05</i> |
| EW MonitorPLS 4HROnsite H34065 | 97408-H34065 | \$ 1,222.00 | 10% | <i>\$1,108.05</i> |
| EW MonitorPLS 4HROnsite H34066 | 97408-H34066 | \$ 1,222.00 | 10% | <i>\$1,108.05</i> |
| EW MonitorPLS 4HROnsite H34067 | 97408-H34067 | \$ 1,222.00 | 10% | <i>\$1,108.05</i> |
| EW MonitorPLS 4HROnsite H34068 | 97408-H34068 | \$ 1,222.00 | 10% | <i>\$1,108.05</i> |
| EW MonitorPLS 4HROnsite H34069 | 97408-H34069 | \$ 1,188.00 | 10% | <i>\$1,077.22</i> |
| EW MonitorPLS 4HROnsite H34070 | 97408-H34070 | \$ 1,222.00 | 10% | <i>\$1,108.05</i> |
| EW MonitorPLS 4HROnsite H34071 | 97408-H34071 | \$ 1,222.00 | 10% | <i>\$1,108.05</i> |
| EW MonitorPLS 4HROnsite H34072 | 97408-H34072 | \$ 5,269.00 | 10% | <i>\$4,777.67</i> |
| EW MonitorPLS 4HROnsite H34073 | 97408-H34073 | \$ 5,169.00 | 10% | <i>\$4,686.99</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H34074 | 97408-H34074 | \$ 6,529.00 | 10% | <i>\$5,920.17</i> |
| EW MonitorPLS 4HROnsite H34075 | 97408-H34075 | \$ 6,293.00 | 10% | <i>\$5,706.18</i> |
| EW MonitorPLS 4HROnsite H34076 | 97408-H34076 | \$ 5,269.00 | 10% | <i>\$4,777.67</i> |
| EW MonitorPLS 4HROnsite H34077 | 97408-H34077 | \$ 5,169.00 | 10% | <i>\$4,686.99</i> |
| EW MonitorPLS 4HROnsite H34078 | 97408-H34078 | \$ 5,269.00 | 10% | <i>\$4,777.67</i> |
| EW MonitorPLS 4HROnsite H34079 | 97408-H34079 | \$ 5,169.00 | 10% | <i>\$4,686.99</i> |
| EW MonitorPLS 4HROnsite H34080 | 97408-H34080 | \$ 6,529.00 | 10% | <i>\$5,920.17</i> |
| EW MonitorPLS 4HROnsite H34081 | 97408-H34081 | \$ 6,293.00 | 10% | <i>\$5,706.18</i> |
| EW MonitorPLS 4HROnsite H34082 | 97408-H34082 | \$ 6,262.00 | 10% | <i>\$5,678.07</i> |
| EW MonitorPLS 4HROnsite H34083 | 97408-H34083 | \$ 6,035.00 | 10% | <i>\$5,472.24</i> |
| EW MonitorPLS 4HROnsite H34084 | 97408-H34084 | \$ 4,361.00 | 10% | <i>\$3,954.34</i> |
| EW MonitorPLS 4HROnsite H34085 | 97408-H34085 | \$ 4,361.00 | 10% | <i>\$3,954.34</i> |
| EW MonitorPLS 4HROnsite H34086 | 97408-H34086 | \$ 5,077.00 | 10% | <i>\$4,603.57</i> |
| EW MonitorPLS 4HROnsite H34087 | 97408-H34087 | \$ 4,869.00 | 10% | <i>\$4,414.97</i> |
| EW MonitorPLS 4HROnsite H34088 | 97408-H34088 | \$ 10,768.00 | 10% | <i>\$9,763.88</i> |
| EW MonitorPLS 4HROnsite H34089 | 97408-H34089 | \$ 10,768.00 | 10% | <i>\$9,763.88</i> |
| EW MonitorPLS 4HROnsite H34090 | 97408-H34090 | \$ 12,398.00 | 10% | <i>\$11,241.89</i> |
| EW MonitorPLS 4HROnsite H34091 | 97408-H34091 | \$ 11,240.00 | 10% | <i>\$10,191.87</i> |
| EW MonitorPLS 4HROnsite H34092 | 97408-H34092 | \$ 11,240.00 | 10% | <i>\$10,191.87</i> |
| EW MonitorPLS 4HROnsite H34093 | 97408-H34093 | \$ 11,240.00 | 10% | <i>\$10,191.87</i> |
| EW MonitorPLS 4HROnsite H34094 | 97408-H34094 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H34095 | 97408-H34095 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW MonitorPLS 4HROnsite H34096 | 97408-H34096 | \$ 1,457.00 | 10% | <i>\$1,321.13</i> |
| EW MonitorPLS 4HROnsite H34097 | 97408-H34097 | \$ 1,457.00 | 10% | <i>\$1,321.13</i> |
| EW MonitorPLS 4HROnsite H34098 | 97408-H34098 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW MonitorPLS 4HROnsite H34099 | 97408-H34099 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW MonitorPLS 4HROnsite H34100 | 97408-H34100 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW MonitorPLS 4HROnsite H34101 | 97408-H34101 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW MonitorPLS 4HROnsite H34102 | 97408-H34102 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW MonitorPLS 4HROnsite H34103 | 97408-H34103 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW MonitorPLS 4HROnsite H34104 | 97408-H34104 | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite H34105 | 97408-H34105 | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite H34106 | 97408-H34106 | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite H34107 | 97408-H34107 | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite H34108 | 97408-H34108 | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite H34109 | 97408-H34109 | \$ 713.00 | 10% | <i>\$646.51</i> |
| EW MonitorPLS 4HROnsite H34110 | 97408-H34110 | \$ 10,827.00 | 10% | <i>\$9,817.38</i> |
| EW MonitorPLS 4HROnsite H34111 | 97408-H34111 | \$ 10,827.00 | 10% | <i>\$9,817.38</i> |
| EW MonitorPLS 4HROnsite H34112 | 97408-H34112 | \$ 10,827.00 | 10% | <i>\$9,817.38</i> |
| EW MonitorPLS 4HROnsite H34114 | 97408-H34114 | \$ 15,059.00 | 10% | <i>\$13,654.75</i> |
| EW MonitorPLS 4HROnsite H34115 | 97408-H34115 | \$ 14,820.00 | 10% | <i>\$13,438.04</i> |
| EW MonitorPLS 4HROnsite H34116 | 97408-H34116 | \$ 14,820.00 | 10% | <i>\$13,438.04</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H34117 | 97408-H34117 | \$ 15,059.00 | 10% | <i>\$13,654.75</i> |
| EW MonitorPLS 4HROnsite H34118 | 97408-H34118 | \$ 3,198.00 | 10% | <i>\$2,899.79</i> |
| EW MonitorPLS 4HROnsite H34119 | 97408-H34119 | \$ 3,198.00 | 10% | <i>\$2,899.79</i> |
| EW MonitorPLS 4HROnsite H34120 | 97408-H34120 | \$ 2,273.00 | 10% | <i>\$2,061.04</i> |
| EW MonitorPLS 4HROnsite H34121 | 97408-H34121 | \$ 2,273.00 | 10% | <i>\$2,061.04</i> |
| EW MonitorPLS 4HROnsite H34122 | 97408-H34122 | \$ 2,366.00 | 10% | <i>\$2,145.37</i> |
| EW MonitorPLS 4HROnsite H34123 | 97408-H34123 | \$ 2,366.00 | 10% | <i>\$2,145.37</i> |
| EW MonitorPLS 4HROnsite H34124 | 97408-H34124 | \$ 3,407.00 | 10% | <i>\$3,089.30</i> |
| EW MonitorPLS 4HROnsite H34125 | 97408-H34125 | \$ 3,407.00 | 10% | <i>\$3,089.30</i> |
| EW MonitorPLS 4HROnsite H34126 | 97408-H34126 | \$ 3,407.00 | 10% | <i>\$3,089.30</i> |
| EW MonitorPLS 4HROnsite H34127 | 97408-H34127 | \$ 3,407.00 | 10% | <i>\$3,089.30</i> |
| EW MonitorPLS 4HROnsite H34129 | 97408-H34129 | \$ 1,366.00 | 10% | <i>\$1,238.62</i> |
| EW MonitorPLS 4HROnsite H34130 | 97408-H34130 | \$ 1,419.00 | 10% | <i>\$1,286.68</i> |
| EW MonitorPLS 4HROnsite H34131 | 97408-H34131 | \$ 1,412.00 | 10% | <i>\$1,280.33</i> |
| EW MonitorPLS 4HROnsite H34132 | 97408-H34132 | \$ 1,419.00 | 10% | <i>\$1,286.68</i> |
| EW MonitorPLS 4HROnsite H34172 | 97408-H34172 | \$ 3,279.00 | 10% | <i>\$2,973.23</i> |
| EW MonitorPLS 4HROnsite H34726 | 97408-H34726 | \$ 5,499.00 | 10% | <i>\$4,986.22</i> |
| EW MonitorPLS 4HROnsite H34727 | 97408-H34727 | \$ 5,499.00 | 10% | <i>\$4,986.22</i> |
| EW MonitorPLS 4HROnsite H34728 | 97408-H34728 | \$ 5,499.00 | 10% | <i>\$4,986.22</i> |
| EW MonitorPLS 4HROnsite H34729 | 97408-H34729 | \$ 5,499.00 | 10% | <i>\$4,986.22</i> |
| EW MonitorPLS 4HROnsite H34730 | 97408-H34730 | \$ 5,847.00 | 10% | <i>\$5,301.77</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite H34731 | 97408-H34731 | \$ 5,847.00 | 10% | <i>\$5,301.77</i> |
| EW MonitorPLS 4HROnsite H34732 | 97408-H34732 | \$ 5,847.00 | 10% | <i>\$5,301.77</i> |
| EW MonitorPLS 4HROnsite H34733 | 97408-H34733 | \$ 5,847.00 | 10% | <i>\$5,301.77</i> |
| EW MonitorPLS 4HROnsite H34734 | 97408-H34734 | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW MonitorPLS 4HROnsite H34735 | 97408-H34735 | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW MonitorPLS 4HROnsite H34736 | 97408-H34736 | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW MonitorPLS 4HROnsite H34737 | 97408-H34737 | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW MonitorPLS 4HROnsite H34738 | 97408-H34738 | \$ 2,512.00 | 10% | <i>\$2,277.76</i> |
| EW MonitorPLS 4HROnsite H34739 | 97408-H34739 | \$ 2,512.00 | 10% | <i>\$2,277.76</i> |
| EW MonitorPLS 4HROnsite H34740 | 97408-H34740 | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW MonitorPLS 4HROnsite H34741 | 97408-H34741 | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW MonitorPLS 4HROnsite H34742 | 97408-H34742 | \$ 1,356.00 | 10% | <i>\$1,229.55</i> |
| EW MonitorPLS 4HROnsite H34743 | 97408-H34743 | \$ 1,356.00 | 10% | <i>\$1,229.55</i> |
| EW MonitorPLS 4HROnsite H34744 | 97408-H34744 | \$ 1,655.00 | 10% | <i>\$1,500.67</i> |
| EW MonitorPLS 4HROnsite H34745 | 97408-H34745 | \$ 1,655.00 | 10% | <i>\$1,500.67</i> |
| EW MonitorPLS 4HROnsite H34746 | 97408-H34746 | \$ 1,779.00 | 10% | <i>\$1,613.11</i> |
| EW MonitorPLS 4HROnsite H34747 | 97408-H34747 | \$ 1,779.00 | 10% | <i>\$1,613.11</i> |
| EW MonitorPLS 4HROnsite H34748 | 97408-H34748 | \$ 2,512.00 | 10% | <i>\$2,277.76</i> |
| EW MonitorPLS 4HROnsite H34749 | 97408-H34749 | \$ 2,512.00 | 10% | <i>\$2,277.76</i> |
| EW MonitorPLS 4HROnsite H34750 | 97408-H34750 | \$ 2,512.00 | 10% | <i>\$2,277.76</i> |
| EW MonitorPLS 4HROnsite H34751 | 97408-H34751 | \$ 2,512.00 | 10% | <i>\$2,277.76</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|-------------|
| EW MonitorPLS 4HROnsite H34752 | 97408-H34752 | \$ 2,512.00 | 10% | \$2,277.76 |
| EW MonitorPLS 4HROnsite H34753 | 97408-H34753 | \$ 2,512.00 | 10% | \$2,277.76 |
| EW MonitorPLS 4HROnsite H34754 | 97408-H34754 | \$ 2,512.00 | 10% | \$2,277.76 |
| EW MonitorPLS 4HROnsite H34755 | 97408-H34755 | \$ 2,512.00 | 10% | \$2,277.76 |
| EW MonitorPLS 4HROnsite H34756 | 97408-H34756 | \$ 1,663.00 | 10% | \$1,507.93 |
| EW MonitorPLS 4HROnsite H34757 | 97408-H34757 | \$ 1,663.00 | 10% | \$1,507.93 |
| EW MonitorPLS 4HROnsite H34758 | 97408-H34758 | \$ 1,655.00 | 10% | \$1,500.67 |
| EW MonitorPLS 4HROnsite H34759 | 97408-H34759 | \$ 1,663.00 | 10% | \$1,507.93 |
| EW MonitorPLS 4HROnsite H34760 | 97408-H34760 | \$ 1,663.00 | 10% | \$1,507.93 |
| EW MonitorPLS 4HROnsite H34761 | 97408-H34761 | \$ 1,655.00 | 10% | \$1,500.67 |
| EW MonitorPLS 4HROnsite H34993 | 97408-H34993 | \$ 21,390.00 | 10% | \$19,395.38 |
| EW MonitorPLS 4HROnsite H34994 | 97408-H34994 | \$ 21,390.00 | 10% | \$19,395.38 |
| EW MonitorPLS 4HROnsite H34996 | 97408-H34996 | \$ 21,390.00 | 10% | \$19,395.38 |
| EW MonitorPLS 4HROnsite H34997 | 97408-H34997 | \$ 21,390.00 | 10% | \$19,395.38 |
| EW MonitorPLS 4HROnsite H35005 | 97408-H35005 | \$ 16,558.00 | 10% | \$15,013.97 |
| EW MonitorPLS 4HROnsite H35006 | 97408-H35006 | \$ 16,558.00 | 10% | \$15,013.97 |
| EW MonitorPLS 4HROnsite H35012 | 97408-H35012 | \$ 10,333.00 | 10% | \$9,369.45 |
| EW MonitorPLS 4HROnsite H35270 | 97408-H35270 | \$ 1,459.00 | 10% | \$1,322.95 |
| EW MonitorPLS 4HROnsite H35271 | 97408-H35271 | \$ 1,261.00 | 10% | \$1,143.41 |
| EW MonitorPLS 4HROnsite H35272 | 97408-H35272 | \$ 1,142.00 | 10% | \$1,035.51 |
| EW MonitorPLS 4HROnsite H35273 | 97408-H35273 | \$ 1,142.00 | 10% | \$1,035.51 |

| | | | | |
|-----------------------------------|--------------|--------------|-----|-------------------|
| EW MonitorPLS 4HROnsite H35274 | 97408-H35274 | \$ 1,788.00 | 10% | <i>\$1,621.27</i> |
| EW MonitorPLS 4HROnsite H35275 | 97408-H35275 | \$ 1,591.00 | 10% | <i>\$1,442.64</i> |
| EW MonitorPLS 4HROnsite H35276 | 97408-H35276 | \$ 5,269.00 | 10% | <i>\$4,777.67</i> |
| EW MonitorPLS 4HROnsite H35277 | 97408-H35277 | \$ 6,262.00 | 10% | <i>\$5,678.07</i> |
| EW MonitorPLS 4HROnsite H35278 | 97408-H35278 | \$ 4,361.00 | 10% | <i>\$3,954.34</i> |
| EW MonitorPLS 4HROnsite H35279 | 97408-H35279 | \$ 4,869.00 | 10% | <i>\$4,414.97</i> |
| EW MonitorPLS 4HROnsite H35280 | 97408-H35280 | \$ 10,622.00 | 10% | <i>\$9,631.50</i> |
| EW MonitorPLS 4HROnsite H35292 | 97408-H35292 | \$ 4,361.00 | 10% | <i>\$3,954.34</i> |
| EW MonitorPLS 4HROnsite H35293 | 97408-H35293 | \$ 4,869.00 | 10% | <i>\$4,414.97</i> |
| EW MonitorPLS 4HROnsite H35295 | 97408-H35295 | \$ 1,300.00 | 10% | <i>\$1,178.78</i> |
| EW MonitorPLS 4HROnsite H35302 | 97408-H35302 | \$ 4,212.00 | 10% | <i>\$3,819.23</i> |
| EW MonitorPLS 4HROnsite H35303 | 97408-H35303 | \$ 4,212.00 | 10% | <i>\$3,819.23</i> |
| EW MonitorPLS 4HROnsite H35304 | 97408-H35304 | \$ 4,212.00 | 10% | <i>\$3,819.23</i> |
| EW MonitorPLS 4HROnsite H35305 | 97408-H35305 | \$ 4,377.00 | 10% | <i>\$3,968.84</i> |
| EW MonitorPLS 4HROnsite H35306 | 97408-H35306 | \$ 4,377.00 | 10% | <i>\$3,968.84</i> |
| EW MonitorPLS 4HROnsite H35307 | 97408-H35307 | \$ 4,377.00 | 10% | <i>\$3,968.84</i> |
| EW MonitorPLS 4HROnsite H35309 | 97408-H35309 | \$ 5,539.00 | 10% | <i>\$5,022.49</i> |
| EW MonitorPLS 4HROnsite H35310 | 97408-H35310 | \$ 5,539.00 | 10% | <i>\$5,022.49</i> |
| EW MonitorPLS 4HROnsite H35311 | 97408-H35311 | \$ 5,539.00 | 10% | <i>\$5,022.49</i> |
| EW MonitorPLS 4HROnsite H35312 | 97408-H35312 | \$ 4,572.00 | 10% | <i>\$4,145.66</i> |
| EW MonitorPLS 4HROnsite H35313 | 97408-H35313 | \$ 4,572.00 | 10% | <i>\$4,145.66</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite H35314 | 97408-H35314 | \$ 4,572.00 | 10% | <i>\$4,145.66</i> |
| EW MonitorPLS 4HROnsite H35315 | 97408-H35315 | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MonitorPLS 4HROnsite H35318 | 97408-H35318 | \$ 1,432.00 | 10% | <i>\$1,298.47</i> |
| EW MonitorPLS 4HROnsite H35319 | 97408-H35319 | \$ 1,732.00 | 10% | <i>\$1,570.49</i> |
| EW MonitorPLS 4HROnsite H35320 | 97408-H35320 | \$ 1,774.00 | 10% | <i>\$1,608.57</i> |
| EW MonitorPLS 4HROnsite H35321 | 97408-H35321 | \$ 2,076.00 | 10% | <i>\$1,882.41</i> |
| EW MonitorPLS 4HROnsite H35322 | 97408-H35322 | \$ 2,436.00 | 10% | <i>\$2,208.84</i> |
| EW MonitorPLS 4HROnsite H35323 | 97408-H35323 | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MonitorPLS 4HROnsite H35328 | 97408-H35328 | \$ 563.00 | 10% | <i>\$510.50</i> |
| EW MonitorPLS 4HROnsite H35330 | 97408-H35330 | \$ 737.00 | 10% | <i>\$668.27</i> |
| EW MonitorPLS 4HROnsite H35340 | 97408-H35340 | \$ 4,162.00 | 10% | <i>\$3,773.89</i> |
| EW MonitorPLS 4HROnsite H35341 | 97408-H35341 | \$ 4,162.00 | 10% | <i>\$3,773.89</i> |
| EW MonitorPLS 4HROnsite H35342 | 97408-H35342 | \$ 3,572.00 | 10% | <i>\$3,238.91</i> |
| EW MonitorPLS 4HROnsite H35343 | 97408-H35343 | \$ 4,162.00 | 10% | <i>\$3,773.89</i> |
| EW MonitorPLS 4HROnsite H35344 | 97408-H35344 | \$ 4,307.00 | 10% | <i>\$3,905.37</i> |
| EW MonitorPLS 4HROnsite H35345 | 97408-H35345 | \$ 4,307.00 | 10% | <i>\$3,905.37</i> |
| EW MonitorPLS 4HROnsite H35346 | 97408-H35346 | \$ 3,682.00 | 10% | <i>\$3,338.65</i> |
| EW MonitorPLS 4HROnsite H35347 | 97408-H35347 | \$ 4,307.00 | 10% | <i>\$3,905.37</i> |
| EW MonitorPLS 4HROnsite H35349 | 97408-H35349 | \$ 4,666.00 | 10% | <i>\$4,230.90</i> |
| EW MonitorPLS 4HROnsite H35350 | 97408-H35350 | \$ 4,666.00 | 10% | <i>\$4,230.90</i> |
| EW MonitorPLS 4HROnsite H35351 | 97408-H35351 | \$ 3,973.00 | 10% | <i>\$3,602.52</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite H35352 | 97408-H35352 | \$ 4,666.00 | 10% | <i>\$4,230.90</i> |
| EW MonitorPLS 4HROnsite H35359 | 97408-H35359 | \$ 2,076.00 | 10% | <i>\$1,882.41</i> |
| EW MonitorPLS 4HROnsite H35360 | 97408-H35360 | \$ 2,436.00 | 10% | <i>\$2,208.84</i> |
| EW MonitorPLS 4HROnsite H35361 | 97408-H35361 | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MonitorPLS 4HROnsite H35362 | 97408-H35362 | \$ 1,432.00 | 10% | <i>\$1,298.47</i> |
| EW MonitorPLS 4HROnsite H35366 | 97408-H35366 | \$ 2,037.00 | 10% | <i>\$1,847.05</i> |
| EW MonitorPLS 4HROnsite H35367 | 97408-H35367 | \$ 2,375.00 | 10% | <i>\$2,153.53</i> |
| EW MonitorPLS 4HROnsite H35368 | 97408-H35368 | \$ 3,616.00 | 10% | <i>\$3,278.81</i> |
| EW MonitorPLS 4HROnsite H35369 | 97408-H35369 | \$ 1,180.00 | 10% | <i>\$1,069.97</i> |
| EW MonitorPLS 4HROnsite H35370 | 97408-H35370 | \$ 1,650.00 | 10% | <i>\$1,496.14</i> |
| EW MonitorPLS 4HROnsite H35375 | 97408-H35375 | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW MonitorPLS 4HROnsite H35376 | 97408-H35376 | \$ 1,876.00 | 10% | <i>\$1,701.06</i> |
| EW MonitorPLS 4HROnsite H35377 | 97408-H35377 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW MonitorPLS 4HROnsite H35378 | 97408-H35378 | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW MonitorPLS 4HROnsite H35379 | 97408-H35379 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW MonitorPLS 4HROnsite H35380 | 97408-H35380 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW MonitorPLS 4HROnsite H35381 | 97408-H35381 | \$ 1,724.00 | 10% | <i>\$1,563.24</i> |
| EW MonitorPLS 4HROnsite H35384 | 97408-H35384 | \$ 636.00 | 10% | <i>\$576.69</i> |
| EW MonitorPLS 4HROnsite H35385 | 97408-H35385 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW MonitorPLS 4HROnsite H35386 | 97408-H35386 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW MonitorPLS 4HROnsite H35387 | 97408-H35387 | \$ 1,315.00 | 10% | <i>\$1,192.38</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS 4HROnsite H35388 | 97408-H35388 | \$ 967.00 | 10% | \$876.83 |
| EW MonitorPLS 4HROnsite H35389 | 97408-H35389 | \$ 547.00 | 10% | \$495.99 |
| EW MonitorPLS 4HROnsite H35390 | 97408-H35390 | \$ 470.00 | 10% | \$426.17 |
| EW MonitorPLS 4HROnsite H35391 | 97408-H35391 | \$ 1,035.00 | 10% | \$938.49 |
| EW MonitorPLS 4HROnsite H35392 | 97408-H35392 | \$ 1,583.00 | 10% | \$1,435.39 |
| EW MonitorPLS 4HROnsite H35393 | 97408-H35393 | \$ 2,112.00 | 10% | \$1,915.06 |
| EW MonitorPLS 4HROnsite H35394 | 97408-H35394 | \$ 382.00 | 10% | \$346.38 |
| EW MonitorPLS 4HROnsite H35395 | 97408-H35395 | \$ 319.00 | 10% | \$289.25 |
| EW MonitorPLS 4HROnsite H35396 | 97408-H35396 | \$ 382.00 | 10% | \$346.38 |
| EW MonitorPLS 4HROnsite H35397 | 97408-H35397 | \$ 319.00 | 10% | \$289.25 |
| EW MonitorPLS 4HROnsite H35398 | 97408-H35398 | \$ 986.00 | 10% | \$894.06 |
| EW MonitorPLS 4HROnsite H35399 | 97408-H35399 | \$ 1,195.00 | 10% | \$1,083.57 |
| EW MonitorPLS 4HROnsite H35400 | 97408-H35400 | \$ 1,323.00 | 10% | \$1,199.63 |
| EW MonitorPLS 4HROnsite H35401 | 97408-H35401 | \$ 707.00 | 10% | \$641.07 |
| EW MonitorPLS 4HROnsite H35415 | 97408-H35415 | \$ 433.00 | 10% | \$392.62 |
| EW MonitorPLS 4HROnsite H35416 | 97408-H35416 | \$ 433.00 | 10% | \$392.62 |
| EW MonitorPLS 4HROnsite H35426 | 97408-H35426 | \$ 547.00 | 10% | \$495.99 |
| EW MonitorPLS 4HROnsite H35427 | 97408-H35427 | \$ 1,315.00 | 10% | \$1,192.38 |
| EW MonitorPLS 4HROnsite H35428 | 97408-H35428 | \$ 470.00 | 10% | \$426.17 |
| EW MonitorPLS 4HROnsite H35429 | 97408-H35429 | \$ 1,035.00 | 10% | \$938.49 |
| EW MonitorPLS 4HROnsite H35430 | 97408-H35430 | \$ 1,412.00 | 10% | \$1,280.33 |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H35431 | 97408-H35431 | \$ 1,412.00 | 10% | <i>\$1,280.33</i> |
| EW MonitorPLS 4HROnsite H35432 | 97408-H35432 | \$ 1,356.00 | 10% | <i>\$1,229.55</i> |
| EW MonitorPLS 4HROnsite H35433 | 97408-H35433 | \$ 1,615.00 | 10% | <i>\$1,464.40</i> |
| EW MonitorPLS 4HROnsite H35434 | 97408-H35434 | \$ 1,736.00 | 10% | <i>\$1,574.12</i> |
| EW MonitorPLS 4HROnsite H35435 | 97408-H35435 | \$ 1,736.00 | 10% | <i>\$1,574.12</i> |
| EW MonitorPLS 4HROnsite H35436 | 97408-H35436 | \$ 2,438.00 | 10% | <i>\$2,210.66</i> |
| EW MonitorPLS 4HROnsite H35437 | 97408-H35437 | \$ 2,438.00 | 10% | <i>\$2,210.66</i> |
| EW MonitorPLS 4HROnsite H35438 | 97408-H35438 | \$ 2,438.00 | 10% | <i>\$2,210.66</i> |
| EW MonitorPLS 4HROnsite H35439 | 97408-H35439 | \$ 2,438.00 | 10% | <i>\$2,210.66</i> |
| EW MonitorPLS 4HROnsite H35440 | 97408-H35440 | \$ 1,615.00 | 10% | <i>\$1,464.40</i> |
| EW MonitorPLS 4HROnsite H35441 | 97408-H35441 | \$ 1,615.00 | 10% | <i>\$1,464.40</i> |
| EW MonitorPLS 4HROnsite H35442 | 97408-H35442 | \$ 1,615.00 | 10% | <i>\$1,464.40</i> |
| EW MonitorPLS 4HROnsite H35443 | 97408-H35443 | \$ 5,499.00 | 10% | <i>\$4,986.22</i> |
| EW MonitorPLS 4HROnsite H35444 | 97408-H35444 | \$ 5,847.00 | 10% | <i>\$5,301.77</i> |
| EW MonitorPLS 4HROnsite H35445 | 97408-H35445 | \$ 5,269.00 | 10% | <i>\$4,777.67</i> |
| EW MonitorPLS 4HROnsite H35446 | 97408-H35446 | \$ 5,169.00 | 10% | <i>\$4,686.99</i> |
| EW MonitorPLS 4HROnsite H35447 | 97408-H35447 | \$ 5,935.00 | 10% | <i>\$5,381.56</i> |
| EW MonitorPLS 4HROnsite H35448 | 97408-H35448 | \$ 5,721.00 | 10% | <i>\$5,187.52</i> |
| EW MonitorPLS 4HROnsite H35449 | 97408-H35449 | \$ 4,361.00 | 10% | <i>\$3,954.34</i> |
| EW MonitorPLS 4HROnsite H35450 | 97408-H35450 | \$ 4,615.00 | 10% | <i>\$4,184.65</i> |
| EW MonitorPLS 4HROnsite H35451 | 97408-H35451 | \$ 11,240.00 | 10% | <i>\$10,191.87</i> |

| | | | | |
|---|-------------------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H35452 | 97408-H35452 | \$ 11,240.00 | 10% | <i>\$10,191.87</i> |
| EW MonitorPLS 4HROnsite H35453 | 97408-H35453 | \$ 5,847.00 | 10% | <i>\$5,301.77</i> |
| EW MonitorPLS 4HROnsite H35454 | 97408-H35454 | \$ 5,499.00 | 10% | <i>\$4,986.22</i> |
| EW MonitorPLS 4HROnsite H35455 | 97408-H35455 | \$ 1,774.00 | 10% | <i>\$1,608.57</i> |
| EW MonitorPLS 4HROnsite H35456 | 97408-H35456 | \$ 2,050.00 | 10% | <i>\$1,858.84</i> |
| EW MonitorPLS 4HROnsite H35457 | 97408-H35457 | \$ 1,909.00 | 10% | <i>\$1,730.99</i> |
| EW MonitorPLS 4HROnsite H35458 | 97408-H35458 | \$ 2,043.00 | 10% | <i>\$1,852.49</i> |
| EW MonitorPLS 4HROnsite H35471 | 97408-H35471 | \$ 1,774.00 | 10% | <i>\$1,608.57</i> |
| EW MonitorPLS 4HROnsite H35600 | 97408-H35600 | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW MonitorPLS 4HROnsite H35601 | 97408-H35601 | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW MonitorPLS 4HROnsite H35602 | 97408-H35602 | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW MonitorPLS 4HROnsite H35603 | 97408-H35603 | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW MonitorPLS 4HROnsite H35604 | 97408-H35604 | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW MonitorPLS 4HROnsite H35605 | 97408-H35605 | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW MonitorPLS 4HROnsite H35606 | 97408-H35606 | \$ 1,788.00 | 10% | <i>\$1,621.27</i> |
| EW MonitorPLS 4HROnsite H35607 | 97408-H35607 | \$ 1,779.00 | 10% | <i>\$1,613.11</i> |
| EW MonitorPLS 4HROnsite ISW- 24W-4X | 97408-ISW- 24W-4X | \$ 1,732.00 | 10% | <i>\$1,570.49</i> |
| EW MonitorPLS 4HROnsite ISW- 4W-4WS-4X | 97408-ISW-4W- 4WS-4X | \$ 1,269.00 | 10% | <i>\$1,150.67</i> |
| EW MonitorPLUS 4HROnsite- MS128 | 97408- MSM128 | \$ 4,138.00 | 10% | <i>\$3,752.13</i> |
| EW MonitorPLS 4HROnsite- MSM48C | 97408- MSM48C | \$ 2,674.00 | 10% | <i>\$2,424.65</i> |

| | | | | |
|---|---------------------------------|--------------|-----|-------------|
| EW MonitorPLS 4HRonsit SLX9150-48XT-DC-F | 97408- SLX9150- 48XT-DC-F | \$ 3,756.00 | 10% | \$3,405.75 |
| EW MonitorPLS 4HRonsit SLX9150-48XT-DC-R | 97408- SLX9150- 48XT-DC-R | \$ 4,101.00 | 10% | \$3,718.58 |
| EW MonitorPLS 4HRonsite SLX9150-48Y-DC-F | 97408- SLX9150-48Y- DC-F | \$ 3,630.00 | 10% | \$3,291.50 |
| EW MonitorPLS 4HRonsite SLX9150-48Y-DC-R | 97408- SLX9150-48Y- DC-R | \$ 3,964.00 | 10% | \$3,594.36 |
| EW MonitorPLS 4HRonsite SLX9740-40C | 97408- SLX9740-40C | \$ 13,697.00 | 10% | \$12,419.75 |
| EW MonitorPLS 4HRonsite SLX9740-40C-AC-F | 97408- SLX9740-40C- AC-F | \$ 13,697.00 | 10% | \$12,419.75 |
| EW MonitorPLS 4HRonsite SLX9740-40C-AC-R | 97408- SLX9740-40C- AC-R | \$ 13,697.00 | 10% | \$12,419.75 |
| EW MonitorPLS 4HRonsite SLX9740-40C-DC-F | 97408- SLX9740-40C- DC-F | \$ 13,697.00 | 10% | \$12,419.75 |
| EW MonitorPLS 4HRonsite SLX9740-80C | 97408- SLX9740-80C | \$ 25,208.00 | 10% | \$22,857.35 |
| EW MonitorPLS 4HRonsite SLX9740-80C-AC-F | 97408- SLX9740-80C- AC-F | \$ 25,208.00 | 10% | \$22,857.35 |
| EW MonitorPLS 4HRonsite SLX9740-80C-AC-R | 97408- SLX9740-80C- AC-R | \$ 25,208.00 | 10% | \$22,857.35 |
| EW MonitorPLS 4HRonsite SLX9740-80C-DC-F | 97408- SLX9740-80C- DC-F | \$ 25,208.00 | 10% | \$22,857.35 |
| EW MonitorPLS 4HRonsite V300-8P-2X | 97408-V300- 8P-2X | \$ 609.00 | 10% | \$552.21 |
| EW MonitorPLS 4HRonsite V300-8T-2X | 97408-V300- 8T-2X | \$ 546.00 | 10% | \$495.09 |
| EW MonitorPLS 4HRonsite V300HT-8P-2X | 97408-V300HT- 8P-2X | \$ 870.00 | 10% | \$788.87 |

| | | | | |
|---|---|-------------|-----|------------|
| EW MonitorPLS 4HROnsite V300HT-8T-2X | 97408-V300HT- 8T-2X | \$ 684.00 | 10% | \$620.22 |
| EW MonitorPLS 4HROnsite- VIM-SS | 97408-VIM-SS | \$ 461.00 | 10% | \$418.01 |
| EW MonitorPLS 4HROnsiteVIMSSV8 | 97408-VIM- SSV80 | \$ 639.00 | 10% | \$579.41 |
| EW MonitorPLS 4HROnsiteVIM2SS | 97408-VIM2- SS | \$ 477.00 | 10% | \$432.52 |
| EW MonitorPLS 4HROnsiteVIM2SS | 97408-VIM2- SS128 | \$ 1,062.00 | 10% | \$962.97 |
| EW MonitorPLS 4HROnsiteVIM2V80 | 97408-VIM2- V80 | \$ 1,134.00 | 10% | \$1,028.25 |
| EW MonitorPLS 4HROnsiteVIM210 | 97408- VIM210G4X | \$ 1,758.00 | 10% | \$1,594.07 |
| EW MonPLS 4HROnsit VSP4900-12MXU-12XE | 97408- VSP4900- 12MXU-12XE | \$ 2,177.00 | 10% | \$1,973.99 |
| EW MonPLS 4HROnsit VSP4900-12MXU-12XE-B1 | 97408- VSP4900- 12MXU-12XE- B1 | \$ 2,177.00 | 10% | \$1,973.99 |
| EW MonitorPLS 4HROnsite VSP4900-24S | 97408- VSP4900-24S | \$ 1,432.00 | 10% | \$1,298.47 |
| EW MonitorPLS 4HROnsite VSP4900-24S-B3 | 97408- VSP4900-24S- B3 | \$ 1,432.00 | 10% | \$1,298.47 |
| EW MonitorPLS 4HROnsite VSP4900-24XE | 97408- VSP4900- 24XE | \$ 2,177.00 | 10% | \$1,973.99 |
| EW MonitorPLS 4HROnsite VSP4900-24XE-B3 | 97408- VSP4900- 24XE-B3 | \$ 2,177.00 | 10% | \$1,973.99 |
| EW MonitorPLS 4HROnsite X435-24P-4S | 97408-X435- 24P-4S | \$ 769.00 | 10% | \$697.29 |
| EW MonitorPLS 4HROnsite X435-24T-4S | 97408-X435- 24T-4S | \$ 606.00 | 10% | \$549.49 |
| EW MonitorPLS 4HROnsite X435-8P-2T-W | 97408-X435- 8P-2T-W | \$ 606.00 | 10% | \$549.49 |
| EW MonitorPLS 4HROnsite X435-8P-4S | 97408-X435- 8P-4S | \$ 586.00 | 10% | \$531.36 |
| EW MonitorPLS 4HROnsite X435-8T-4S | 97408-X435- 8T-4S | \$ 550.00 | 10% | \$498.71 |

| | | | | |
|---|-----------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite-X46024 | 97408-X460-24P | \$ 2,188.00 | 10% | <i>\$1,983.97</i> |
| EW MonitorPLS 4HROnsite-X46024 | 97408-X460-24T | \$ 1,747.00 | 10% | <i>\$1,584.09</i> |
| EW MonitorPLS 4HROnsite-X46024 | 97408-X460-24TDC | \$ 2,261.00 | 10% | <i>\$2,050.16</i> |
| EW MonitorPLS 4HROnsite-X46024 | 97408-X460-24X | \$ 2,591.00 | 10% | <i>\$2,349.39</i> |
| EW MonitorPLS 4HROnsite-X46024 | 97408-X460-24XDC | \$ 2,863.00 | 10% | <i>\$2,596.03</i> |
| EW MonitorPLS 4HROnsite-X46048 | 97408-X460-48P | \$ 2,591.00 | 10% | <i>\$2,349.39</i> |
| EW MonitorPLS 4HROnsite-X46048 | 97408-X460-48T | \$ 2,327.00 | 10% | <i>\$2,110.01</i> |
| EW MonitorPLS 4HROnsite-X46048 | 97408-X460-48TDC | \$ 2,795.00 | 10% | <i>\$2,534.37</i> |
| EW MonitorPLS 4HROnsite-X46048 | 97408-X460-48X | \$ 3,207.00 | 10% | <i>\$2,907.95</i> |
| EW MonitorPLS 4HROnsite-X46048 | 97408-X460-48XDC | \$ 3,199.00 | 10% | <i>\$2,900.69</i> |
| EW MonitorPLS 4HROnsite X465-24MU | 97408-X465-24MU | \$ 2,436.00 | 10% | <i>\$2,208.84</i> |
| EW MonitorPLS 4HROnsite X465-24S | 97408-X465-24S | \$ 1,432.00 | 10% | <i>\$1,298.47</i> |
| EW MonitorPLS 4HROnsite X465-24S-B3 | 97408-X465-24S-B3 | \$ 1,432.00 | 10% | <i>\$1,298.47</i> |
| EW MonitorPLS 4HROnsite X465-24W | 97408-X465-24W | \$ 1,432.00 | 10% | <i>\$1,298.47</i> |
| EW MonitorPLS 4HROnsite X465-24XE | 97408-X465-24XE | \$ 2,177.00 | 10% | <i>\$1,973.99</i> |
| EW MonitorPLS 4HROnsite X465-24XE-B3 | 97408-X465-24XE-B3 | \$ 2,177.00 | 10% | <i>\$1,973.99</i> |
| EW MonitorPLS 4HROnsite X465-48P | 97408-X465-48P | \$ 1,774.00 | 10% | <i>\$1,608.57</i> |
| EW MonitorPLS 4HROnsite X465-48T | 97408-X465-48T | \$ 1,732.00 | 10% | <i>\$1,570.49</i> |
| EW MonitorPLS 4HROnsite X465-48W | 97408-X465-48W | \$ 2,076.00 | 10% | <i>\$1,882.41</i> |
| EW MonitorPLS 4HROnsite X465i-48W | 97408-X465i-48W | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MonitorPLS 4HROnsite X465i-48W-B1-S1 | 97408-X465i-48W-B1-S1 | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite X465i-48W-B2-S1 | 97408-X465i- 48W-B2-S1 | \$ 2,400.00 | 10% | <i>\$2,176.20</i> |
| EW MonitorPLS 4HROnsite- X48024 | 97408-X480- 24X | \$ 2,921.00 | 10% | <i>\$2,648.62</i> |
| EW MonitorPLUS 4HROnsite- X480T | 97408-X480- 48T | \$ 2,690.00 | 10% | <i>\$2,439.16</i> |
| EW MonitorPLS 4HROnsite- X48048 | 97408-X480- 48X | \$ 3,680.00 | 10% | <i>\$3,336.84</i> |
| EW MonitorPLS 4HROnsite X695-48Y-8C | 97408-X695- 48Y-8C | \$ 4,632.00 | 10% | <i>\$4,200.07</i> |
| EW MonitorPLS 4HROnsite XA1440 | 97408-XA1440 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW MonitorPLS 4HROnsite XA1480 | 97408-XA1480 | \$ 981.00 | 10% | <i>\$889.52</i> |
| EW MonitorPLS 4HROnsiteXGM32SF | 97408-XGM3- 2SF | \$ 639.00 | 10% | <i>\$579.41</i> |
| EW MonitorPLS 4HROnsite XR600 | 97408-XR600 | \$ 756.00 | 10% | <i>\$685.50</i> |
| EW MonitorPLS NBDOnsite 1130C | 97411-1130C | \$ 1,924.00 | 6% | <i>\$1,822.12</i> |
| EW MonitorPLS NBDOnsite- 16119 | 97411-16119 | \$ 539.00 | 10% | <i>\$488.74</i> |
| EW MonitorPLS NBDOnsite- 16120 | 97411-16120 | \$ 617.00 | 10% | <i>\$559.46</i> |
| EW MonitorPLS NBDOnsite- 16126 | 97411-16126 | \$ 539.00 | 10% | <i>\$488.74</i> |
| EW MonitorPLS NBDOnsite- 16127 | 97411-16127 | \$ 564.00 | 10% | <i>\$511.41</i> |
| EW MonitorPLS NBDOnsite- 16172 | 97411-16172 | \$ 1,066.00 | 10% | <i>\$966.60</i> |
| EW MonitorPLS NBDOnsite 16172T | 97411-16172T | \$ 1,175.00 | 10% | <i>\$1,065.43</i> |
| EW MonitorPLS NBDOnsite- 16173 | 97411-16173 | \$ 1,071.00 | 10% | <i>\$971.13</i> |
| EW MonitorPLS NBDOnsite 16173T | 97411-16173T | \$ 1,183.00 | 10% | <i>\$1,072.69</i> |
| EW MonitorPLS NBDOnsite- 16174 | 97411-16174 | \$ 1,216.00 | 10% | <i>\$1,102.61</i> |
| EW MonitorPLS NBDOnsite- 16175 | 97411-16175 | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW MonitorPLS NBDOnsite- 16176 | 97411-16176 | \$ 1,212.00 | 10% | <i>\$1,098.98</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-16177 | 97411-16177 | \$ 1,143.00 | 10% | <i>\$1,036.42</i> |
| EW MonitorPLS NBDOnsite 16177T | 97411-16177T | \$ 1,345.00 | 10% | <i>\$1,219.58</i> |
| EW MonitorPLS NBDOnsite-16178 | 97411-16178 | \$ 1,414.00 | 10% | <i>\$1,282.14</i> |
| EW MonitorPLS NBDOnsite-16179 | 97411-16179 | \$ 1,426.00 | 10% | <i>\$1,293.03</i> |
| EW MonitorPLS NBDOnsite 16179T | 97411-16179T | \$ 1,566.00 | 10% | <i>\$1,419.97</i> |
| EW MonitorPLS NBDOnsite-16301T | 97411-16301T | \$ 2,414.00 | 10% | <i>\$2,188.89</i> |
| EW MonitorPLS NBDOnsite-16303T | 97411-16303T | \$ 2,414.00 | 10% | <i>\$2,188.89</i> |
| EW MonitorPLS NBDOnsite-16304T | 97411-16304T | \$ 2,990.00 | 10% | <i>\$2,711.18</i> |
| EW MonitorPLS NBDOnsite-16401T | 97411-16401T | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW MonitorPLS NBDOnsite-16402T | 97411-16402T | \$ 1,997.00 | 10% | <i>\$1,810.78</i> |
| EW MonitorPLS NBDOnsite-16403T | 97411-16403T | \$ 1,850.00 | 10% | <i>\$1,677.49</i> |
| EW MonitorPLS NBDOnsite-16404T | 97411-16404T | \$ 1,850.00 | 10% | <i>\$1,677.49</i> |
| EW MonitorPLS NBDOnsite-16405T | 97411-16405T | \$ 2,209.00 | 10% | <i>\$2,003.01</i> |
| EW MonitorPLS NBDOnsite-16406T | 97411-16406T | \$ 2,687.00 | 10% | <i>\$2,436.44</i> |
| EW MonitorPLS NBDOnsite-16431 | 97411-16431 | \$ 1,931.00 | 10% | <i>\$1,750.93</i> |
| EW MonitorPLS NBDOnsite-16432 | 97411-16432 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW MonitorPLS NBDOnsite-16440 | 97411-16440 | \$ 1,472.00 | 10% | <i>\$1,334.74</i> |
| EW MonitorPLS NBDOnsite-16441 | 97411-16441 | \$ 1,396.00 | 10% | <i>\$1,265.82</i> |
| EW MonitorPLS NBDOnsite-16442 | 97411-16442 | \$ 564.00 | 10% | <i>\$511.41</i> |
| EW MonitorPLS NBDOnsite-16444 | 97411-16444 | \$ 413.00 | 10% | <i>\$374.49</i> |
| EW MonitorPLS NBDOnsite-16501 | 97411-16501 | \$ 927.00 | 10% | <i>\$840.56</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite-16501T | 97411-16501T | \$ 976.00 | 10% | \$884.99 |
| EW MonitorPLS NBDOnsite-16502 | 97411-16502 | \$ 999.00 | 10% | \$905.84 |
| EW MonitorPLS NBDOnsite-16502T | 97411-16502T | \$ 1,043.00 | 10% | \$945.74 |
| EW MonitorPLS NBDOnsite-16503 | 97411-16503 | \$ 956.00 | 10% | \$866.85 |
| EW MonitorPLS NBDOnsite-16503T | 97411-16503T | \$ 1,014.00 | 10% | \$919.44 |
| EW MonitorPLS NBDOnsite-16504 | 97411-16504 | \$ 1,079.00 | 10% | \$978.38 |
| EW MonitorPLS NBDOnsite-16504T | 97411-16504T | \$ 1,153.00 | 10% | \$1,045.48 |
| EW MonitorPLS NBDOnsite-16505 | 97411-16505 | \$ 1,102.00 | 10% | \$999.24 |
| EW MonitorPLS NBDOnsite-16505T | 97411-16505T | \$ 1,206.00 | 10% | \$1,093.54 |
| EW MonitorPLS NBDOnsite-16506 | 97411-16506 | \$ 1,304.00 | 10% | \$1,182.40 |
| EW MonitorPLS NBDOnsite-16506T | 97411-16506T | \$ 1,447.00 | 10% | \$1,312.07 |
| EW MonitorPLS NBDOnsite-16507 | 97411-16507 | \$ 1,263.00 | 10% | \$1,145.23 |
| EW MonitorPLS NBDOnsite-16507T | 97411-16507T | \$ 1,357.00 | 10% | \$1,230.46 |
| EW MonitorPLS NBDOnsite-16508 | 97411-16508 | \$ 1,395.00 | 10% | \$1,264.92 |
| EW MonitorPLS NBDOnsite-16508T | 97411-16508T | \$ 1,520.00 | 10% | \$1,378.26 |
| EW MonitorPLS NBDOnsite-16509 | 97411-16509 | \$ 1,395.00 | 10% | \$1,264.92 |
| EW MonitorPLS NBDOnsite-16509T | 97411-16509T | \$ 1,520.00 | 10% | \$1,378.26 |
| EW MonitorPLS NBDOnsite-16510 | 97411-16510 | \$ 1,520.00 | 10% | \$1,378.26 |
| EW MonitorPLS NBDOnsite-16510T | 97411-16510T | \$ 1,673.00 | 10% | \$1,516.99 |
| EW MonitorPLS NBDOnsite-16513 | 97411-16513 | \$ 1,255.00 | 10% | \$1,137.97 |
| EW MonitorPLS NBDOnsite-16514 | 97411-16514 | \$ 1,491.00 | 10% | \$1,351.96 |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-16515 | 97411-16515 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW MonitorPLS NBDOnsite-16516 | 97411-16516 | \$ 853.00 | 10% | <i>\$773.46</i> |
| EW MonitorPLS NBDOnsite-16517 | 97411-16517 | \$ 977.00 | 10% | <i>\$885.89</i> |
| EW MonitorPLS NBDOnsite-16518 | 97411-16518 | \$ 949.00 | 10% | <i>\$860.51</i> |
| EW MonitorPLS NBDOnsite-16519 | 97411-16519 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS NBDOnsite-16520 | 97411-16520 | \$ 1,174.00 | 10% | <i>\$1,064.52</i> |
| EW MonitorPLUS NBDOnsite-16530 | 97411-16530 | \$ 934.00 | 10% | <i>\$846.90</i> |
| EW MonitorPLUS NBDOnsite-16531 | 97411-16531 | \$ 990.00 | 10% | <i>\$897.68</i> |
| EW MonitorPLUS NBDOnsite16531T | 97411-16531T | \$ 998.00 | 10% | <i>\$904.94</i> |
| EW MonitorPLUS NBDOnsite-16532 | 97411-16532 | \$ 990.00 | 10% | <i>\$897.68</i> |
| EW MonitorPLUS NBDOnsite16532T | 97411-16532T | \$ 998.00 | 10% | <i>\$904.94</i> |
| EW MonitorPLUS NBDOnsite-16533 | 97411-16533 | \$ 1,070.00 | 10% | <i>\$970.22</i> |
| EW MonitorPLUS NBDOnsite16533T | 97411-16533T | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLUS NBDOnsite-16534 | 97411-16534 | \$ 1,097.00 | 10% | <i>\$994.70</i> |
| EW MonitorPLUS NBDOnsite-16535 | 97411-16535 | \$ 1,249.00 | 10% | <i>\$1,132.53</i> |
| EW MonitorPLUS NBDOnsite-16535A | 97411-16535A | \$ 1,249.00 | 10% | <i>\$1,132.53</i> |
| EW MonitorPLUS NBDOnsite16535T | 97411-16535T | \$ 1,299.00 | 10% | <i>\$1,177.87</i> |
| EW MonitorPLUS NBDOnsite-16536 | 97411-16536 | \$ 926.00 | 10% | <i>\$839.65</i> |
| EW MonitorPLUS NBDOnsite-16537 | 97411-16537 | \$ 1,003.00 | 10% | <i>\$909.47</i> |
| EW MonitorPLUS NBDOnsite-16538 | 97411-16538 | \$ 1,057.00 | 10% | <i>\$958.43</i> |
| EW MonitorPLUS NBDOnsite16538T | 97411-16538T | \$ 1,209.00 | 10% | <i>\$1,096.26</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLUS NBDOnsite-16539 | 97411-16539 | \$ 1,168.00 | 10% | <i>\$1,059.08</i> |
| EW MonitorPLUS NBDOnsite-16540 | 97411-16540 | \$ 1,038.00 | 10% | <i>\$941.21</i> |
| EW MonitorPLUS NBDOnsite-16541 | 97411-16541 | \$ 836.00 | 10% | <i>\$758.04</i> |
| EW MonitorPLS NBDOnsite 16560 | 97411-16560 | \$ 750.00 | 10% | <i>\$680.06</i> |
| EW MonitorPLS NBDOnsite 16561 | 97411-16561 | \$ 782.00 | 10% | <i>\$709.08</i> |
| EW MonitorPLS NBDOnsite 16562 | 97411-16562 | \$ 805.00 | 10% | <i>\$729.93</i> |
| EW MonitorPLS NBDOnsite 16563 | 97411-16563 | \$ 846.00 | 10% | <i>\$767.11</i> |
| EW MonitorPLS NBDOnsite 16564 | 97411-16564 | \$ 887.00 | 10% | <i>\$804.29</i> |
| EW MonitorPLS NBDOnsite 16565 | 97411-16565 | \$ 995.00 | 10% | <i>\$902.22</i> |
| EW MonitorPLS NBDOnsite 16566 | 97411-16566 | \$ 723.00 | 10% | <i>\$655.58</i> |
| EW MonitorPLS NBDOnsite 16567 | 97411-16567 | \$ 764.00 | 10% | <i>\$692.76</i> |
| EW MonitorPLS NBDOnsite 16568 | 97411-16568 | \$ 750.00 | 10% | <i>\$680.06</i> |
| EW MonitorPLS NBDOnsite 16569 | 97411-16569 | \$ 790.00 | 10% | <i>\$716.33</i> |
| EW MonitorPLS NBDOnsite 16570 | 97411-16570 | \$ 805.00 | 10% | <i>\$729.93</i> |
| EW MonitorPLS NBDOnsite 16571 | 97411-16571 | \$ 887.00 | 10% | <i>\$804.29</i> |
| EW MonitorPLS NBDOnsite-16701 | 97411-16701 | \$ 1,152.00 | 10% | <i>\$1,044.58</i> |
| EW MonitorPLS NBDOnsite-16702 | 97411-16702 | \$ 1,368.00 | 10% | <i>\$1,240.43</i> |
| EW MonitorPLS NBDOnsite-16703 | 97411-16703 | \$ 1,307.00 | 10% | <i>\$1,185.12</i> |
| EW MonitorPLS NBDOnsite 16703T | 97411-16703T | \$ 1,441.00 | 10% | <i>\$1,306.63</i> |
| EW MonitorPLUS NBDOnsite-16704 | 97411-16704 | \$ 1,541.00 | 10% | <i>\$1,397.30</i> |
| EW MonitorPLS NBDOnsite 16704T | 97411-16704T | \$ 1,395.00 | 10% | <i>\$1,264.92</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-16705 | 97411-16705 | \$ 1,368.00 | 10% | <i>\$1,240.43</i> |
| EW MonitorPLS NBDOnsite 16705T | 97411-16705T | \$ 1,505.00 | 10% | <i>\$1,364.66</i> |
| EW MonitorPLS NBDOnsite-16706 | 97411-16706 | \$ 1,785.00 | 10% | <i>\$1,618.55</i> |
| EW MonitorPLS NBDOnsite 16706T | 97411-16706T | \$ 1,977.00 | 10% | <i>\$1,792.64</i> |
| EW MonitorPLS NBDOnsite-16710 | 97411-16710 | \$ 447.00 | 10% | <i>\$405.32</i> |
| EW MonitorPLS NBDOnsite 16710T | 97411-16710T | \$ 493.00 | 10% | <i>\$447.03</i> |
| EW MonitorPLS NBDOnsite-16711 | 97411-16711 | \$ 325.00 | 10% | <i>\$294.69</i> |
| EW MonitorPLS NBDOnsite 16711T | 97411-16711T | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW MonitorPLS NBDOnsite-16712 | 97411-16712 | \$ 363.00 | 10% | <i>\$329.15</i> |
| EW MonitorPLS NBDOnsite 16712T | 97411-16712T | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW MonitorPLS NBDOnsite-16713 | 97411-16713 | \$ 291.00 | 10% | <i>\$263.86</i> |
| EW MonitorPLS NBDOnsite 16713T | 97411-16713T | \$ 317.00 | 10% | <i>\$287.44</i> |
| EW MonitorPLS NBDOnsite-16715 | 97411-16715 | \$ 317.00 | 10% | <i>\$287.44</i> |
| EW MonitorPLS NBDOnsite 16715T | 97411-16715T | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW MonitorPLS NBDOnsite-16716 | 97411-16716 | \$ 1,124.00 | 10% | <i>\$1,019.19</i> |
| EW MonitorPLS NBDOnsite 16716T | 97411-16716T | \$ 1,257.00 | 10% | <i>\$1,139.78</i> |
| EW MonitorPLS NBDOnsite-16717 | 97411-16717 | \$ 1,236.00 | 10% | <i>\$1,120.74</i> |
| EW MonitorPLS NBDOnsite-16718 | 97411-16718 | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW MonitorPLS NBDOnsite-16719 | 97411-16719 | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |
| EW MonitorPLS NBDOnsite 16720 | 97411-16720 | \$ 1,574.00 | 10% | <i>\$1,427.22</i> |
| EW MonitorPLS NBDOnsite 16720T | 97411-16720T | \$ 1,832.00 | 10% | <i>\$1,661.17</i> |

| | | | | |
|------------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite 16756 | 97411-16756 | \$ 1,406.00 | 10% | <i>\$1,274.89</i> |
| EW MonitorPLS NBDOnsite 16756T | 97411-16756T | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW MonitorPLS NBDOnsite 16757 | 97411-16757 | \$ 1,367.00 | 10% | <i>\$1,239.53</i> |
| EW MonitorPLS NBDOnsite 16757T | 97411-16757T | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW MonitorPLS NBDOnsite 16790 | 97411-16790 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |
| EW MonitorPLS NBDOnsite 16791 | 97411-16791 | \$ 2,236.00 | 10% | <i>\$2,027.49</i> |
| EW MonitorPLS NBDOnsite- 17101 | 97411-17101 | \$ 3,225.00 | 10% | <i>\$2,924.27</i> |
| EW MonitorPLS NBDOnsite- 17101T | 97411-17101T | \$ 4,050.00 | 10% | <i>\$3,672.34</i> |
| EW MonitorPLS NBDOnsite- 17102 | 97411-17102 | \$ 3,225.00 | 10% | <i>\$2,924.27</i> |
| EW MonitorPLS NBDOnsite- 17102T | 97411-17102T | \$ 4,050.00 | 10% | <i>\$3,672.34</i> |
| EW MonitorPLS NBDOnsite- 17103 | 97411-17103 | \$ 2,442.00 | 10% | <i>\$2,214.28</i> |
| EW MonitorPLS NBDOnsite- 17103C | 97411-17103C | \$ 2,371.00 | 10% | <i>\$2,149.90</i> |
| EW MonitorPLS NBDOnsite- 17103T | 97411-17103T | \$ 3,053.00 | 10% | <i>\$2,768.31</i> |
| EW MonitorPLS NBDOnsite- 17104 | 97411-17104 | \$ 2,442.00 | 10% | <i>\$2,214.28</i> |
| EW MonitorPLS NBDOnsite- 17104T | 97411-17104T | \$ 3,053.00 | 10% | <i>\$2,768.31</i> |
| EW MonitorPLS NBDOnsite- 17121 | 97411-17121 | \$ 767.00 | 10% | <i>\$695.48</i> |
| EW MonitorPLS NBDOnsite- 17122 | 97411-17122 | \$ 562.00 | 10% | <i>\$509.59</i> |
| EW MonitorPLS NBDOnsite- 17200 | 97411-17200 | \$ 4,709.00 | 10% | <i>\$4,269.89</i> |
| EW MonitorPLS NBDOnsite- 17200T | 97411-17200T | \$ 5,313.00 | 10% | <i>\$4,817.56</i> |
| EW MonitorPLS NBDOnsite- 17201 | 97411-17201 | \$ 4,709.00 | 10% | <i>\$4,269.89</i> |
| EW MonitorPLS NBDOnsite- 17201T | 97411-17201T | \$ 5,313.00 | 10% | <i>\$4,817.56</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-17202 | 97411-17202 | \$ 4,709.00 | 10% | <i>\$4,269.89</i> |
| EW MonitorPLS NBDOnsite-17202T | 97411-17202T | \$ 5,313.00 | 10% | <i>\$4,817.56</i> |
| EW MonitorPLS NBDOnsite-17203 | 97411-17203 | \$ 4,770.00 | 10% | <i>\$4,325.20</i> |
| EW MonitorPLS NBDOnsite-17203T | 97411-17203T | \$ 5,384.00 | 10% | <i>\$4,881.94</i> |
| EW MonitorPLS NBDOnsite-17204 | 97411-17204 | \$ 4,770.00 | 10% | <i>\$4,325.20</i> |
| EW MonitorPLS NBDOnsite-17204T | 97411-17204T | \$ 5,384.00 | 10% | <i>\$4,881.94</i> |
| EW MonitorPLS NBDOnsite-17205 | 97411-17205 | \$ 4,742.00 | 10% | <i>\$4,299.81</i> |
| EW MonitorPLS NBDOnsite-17205T | 97411-17205T | \$ 5,352.00 | 10% | <i>\$4,852.93</i> |
| EW MonitorPLS NBDOnsite-17206 | 97411-17206 | \$ 4,742.00 | 10% | <i>\$4,299.81</i> |
| EW MonitorPLS NBDOnsite-17206T | 97411-17206T | \$ 5,352.00 | 10% | <i>\$4,852.93</i> |
| EW MonitorPLS NBDOnsite-17300 | 97411-17300 | \$ 3,385.00 | 10% | <i>\$3,069.35</i> |
| EW MonitorPLS NBDOnsite-17310 | 97411-17310 | \$ 3,126.00 | 10% | <i>\$2,834.50</i> |
| EW MonitorPLS NBDOnsite 17350 | 97411-17350 | \$ 3,261.00 | 10% | <i>\$2,956.91</i> |
| EW MonitorPLS NBDOnsite 17360 | 97411-17360 | \$ 3,859.00 | 10% | <i>\$3,499.15</i> |
| EW MonitorPLS NBDOnsite 17401 | 97411-17401 | \$ 1,078.00 | 10% | <i>\$977.48</i> |
| EW MonitorPLS NBDOnsite 17401G | 97411-17401G | \$ 1,118.00 | 10% | <i>\$1,013.75</i> |
| EW MonitorPLS NBDOnsite 17401T | 97411-17401T | \$ 1,118.00 | 10% | <i>\$1,013.75</i> |
| EW MonitorPLS NBDOnsite 17402 | 97411-17402 | \$ 1,188.00 | 10% | <i>\$1,077.22</i> |
| EW MonitorPLS NBDOnsite 17402G | 97411-17402G | \$ 1,188.00 | 10% | <i>\$1,077.22</i> |
| EW MonitorPLS NBDOnsite 17402T | 97411-17402T | \$ 1,188.00 | 10% | <i>\$1,077.22</i> |
| EW MonitorPLS NBDOnsite 17403 | 97411-17403 | \$ 1,237.00 | 10% | <i>\$1,121.65</i> |

| | | | | |
|--------------------------------------|---------------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite 17404 | 97411-17404 | \$ 978.00 | 10% | <i>\$886.80</i> |
| EW MonitorPLS NBDOnsite 17405 | 97411-17405 | \$ 1,004.00 | 10% | <i>\$910.38</i> |
| EW MonitorPLS NBDOnsite 17700 | 97411-17700 | \$ 5,643.00 | 10% | <i>\$5,116.79</i> |
| EW MonitorPLS NBDOnsite- 17701 | 97411-17701 | \$ 4,780.00 | 10% | <i>\$4,334.27</i> |
| EW MonitorPLS NBDOnsite- 17702 | 97411-17702 | \$ 4,780.00 | 10% | <i>\$4,334.27</i> |
| EW MonitorPLS NBDOnsite- 17703 | 97411-17703 | \$ 5,231.00 | 10% | <i>\$4,743.21</i> |
| EW MonitorPLS NBDOnsite- 17704 | 97411-17704 | \$ 5,231.00 | 10% | <i>\$4,743.21</i> |
| EW MonitorPLS NBDOnsite- 17705 | 97411-17705 | \$ 4,809.00 | 10% | <i>\$4,360.56</i> |
| EW MonitorPLS NBDOnsite- 17706 | 97411-17706 | \$ 4,809.00 | 10% | <i>\$4,360.56</i> |
| EW MonitorPLS NBDOnsite 17800 | 97411-17800 | \$ 5,708.00 | 10% | <i>\$5,175.73</i> |
| EW MonitorPLS NBDOnsite 17810 | 97411-17810 | \$ 4,709.00 | 10% | <i>\$4,269.89</i> |
| EW MonitorPLS NBDOnsite 18101 | 97411-18101 | \$ 461.00 | 10% | <i>\$418.01</i> |
| EW MonitorPLS NBDOnsite 18102 | 97411-18102 | \$ 533.00 | 10% | <i>\$483.30</i> |
| EW MonitorPLS NBDOnsite 18103 | 97411-18103 | \$ 565.00 | 10% | <i>\$512.31</i> |
| EW MonitorPLS NBDOnsite 18104 | 97411-18104 | \$ 711.00 | 10% | <i>\$644.70</i> |
| EW MonitorPLS NBDOnsite 18104-6PK | 97411-18104- 6PK | \$ 4,274.00 | 10% | <i>\$3,875.45</i> |
| EW MonitorPLS NBDOnsite- 30135 | 97411-30135 | \$ 1,977.00 | 10% | <i>\$1,792.64</i> |
| EW MonitorPLS NBDOnsite 30136 | 97411-30136 | \$ 6,384.00 | 10% | <i>\$5,788.69</i> |
| EW MonitorPLS NBDOnsite 30137 | 97411-30137 | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW MonitorPLS NBDOnsite 30138 | 97411-30138 | \$ 5,141.00 | 10% | <i>\$4,661.60</i> |
| EW MonitorPLS NBDOnsite 30139 | 97411-30139 | \$ 8,932.00 | 10% | <i>\$8,099.09</i> |

| | | | | |
|----------------------------------|-------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite 30912 | 97411-30912 | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS NBDOnsite 30913 | 97411-30913 | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS NBDOnsite 31012 | 97411-31012 | \$ 278.00 | 10% | \$252.08 |
| EW MonitorPLS NBDOnsite 31013 | 97411-31013 | \$ 278.00 | 10% | \$252.08 |
| EW MonitorPLS NBDOnsite 31014 | 97411-31014 | \$ 278.00 | 10% | \$252.08 |
| EW MonitorPLS NBDOnsite 31015 | 97411-31015 | \$ 278.00 | 10% | \$252.08 |
| EW MonitorPLS NBDOnsite 31016 | 97411-31016 | \$ 453.00 | 10% | \$410.76 |
| EW MonitorPLS NBDOnsite 31017 | 97411-31017 | \$ 453.00 | 10% | \$410.76 |
| EW MonitorPLS NBDOnsite 31018 | 97411-31018 | \$ 490.00 | 10% | \$444.31 |
| EW MonitorPLS NBDOnsite 31019 | 97411-31019 | \$ 490.00 | 10% | \$444.31 |
| EW MonitorPLS NBDOnsite 31025 | 97411-31025 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBDOnsite 31026 | 97411-31026 | \$ 248.00 | 10% | \$224.87 |
| EW MonitorPLS NBDOnsite 31028 | 97411-31028 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBDOnsite 31029 | 97411-31029 | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBDOnsite 31031 | 97411-31031 | \$ 239.00 | 10% | \$216.71 |
| EW MonitorPLS NBDOnsite 31032 | 97411-31032 | \$ 239.00 | 10% | \$216.71 |
| EW MonitorPLS NBDOnsite 31034 | 97411-31034 | \$ 278.00 | 10% | \$252.08 |
| EW MonitorPLS NBDOnsite 31035 | 97411-31035 | \$ 278.00 | 10% | \$252.08 |
| EW MonitorPLS NBDOnsite 31050 | 97411-31050 | \$ 280.00 | 10% | \$253.89 |
| EW MonitorPLS NBDOnsite 31051 | 97411-31051 | \$ 280.00 | 10% | \$253.89 |
| EW MonitorPLS NBDOnsite 31055 | 97411-31055 | \$ 280.00 | 10% | \$253.89 |

| | | | | |
|---|------------------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite 31056 | 97411-31056 | \$ 280.00 | 10% | \$253.89 |
| EW MonitorPLS NBDOnsite 39031 | 97411-39031 | \$ 537.00 | 10% | \$486.92 |
| EW MonitorPLS NBDOnsite 39032 | 97411-39032 | \$ 550.00 | 10% | \$498.71 |
| EW MonitorPLS NBDOnsite 39033 | 97411-39033 | \$ 537.00 | 10% | \$486.92 |
| EW MonitorPLS NBDOnsite 39034 | 97411-39034 | \$ 537.00 | 10% | \$486.92 |
| EW MonitorPLS NBDOnsite 39035 | 97411-39035 | \$ 1,156.00 | 10% | \$1,048.20 |
| EW MonitorPLS NBDOnsite 39036 | 97411-39036 | \$ 461.00 | 10% | \$418.01 |
| EW MonitorPLS NBDOnsite 39037 | 97411-39037 | \$ 512.00 | 10% | \$464.26 |
| EW MonitorPLS NBDOnsite 39038 | 97411-39038 | \$ 551.00 | 10% | \$499.62 |
| EW MonitorPLS NBDOnsite 39039 | 97411-39039 | \$ 551.00 | 10% | \$499.62 |
| EW MonitorPLS NBDOnsite 4120-24MW-4Y | 97411-4120- 24MW-4Y | \$ 1,128.00 | 10% | \$1,022.81 |
| EW MonitorPLS NBDOnsite 4120-48MW-4Y | 97411-4120- 48MW-4Y | \$ 1,350.00 | 10% | \$1,224.11 |
| EW MonitorPLS NBDOnsite 4120C | 97411-4120C | \$ 6,005.00 | 10% | \$5,445.03 |
| EW MonitorPLS NBDOnsite 4120C-1 | 97411-4120C-1 | \$ 6,780.00 | 10% | \$6,147.77 |
| EW MonitorPLS NBDOnsite 41216 | 97411-41216 | \$ 1,891.00 | 10% | \$1,714.66 |
| EW MonitorPLS NBDOnsite 4220-12P-4X | 97411-4220- 12P-4X | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite 4220-12T-4X | 97411-4220- 12T-4X | \$ 611.00 | 10% | \$554.02 |
| EW MonitorPLS NBDOnsite 4220-24P-4X | 97411-4220- 24P-4X | \$ 733.00 | 10% | \$664.65 |
| EW MonitorPLS NBDOnsite 4220-24T-4X | 97411-4220- 24T-4X | \$ 672.00 | 10% | \$609.34 |
| EW MonitorPLS NBDOnsite 4220-48P-4X | 97411-4220- 48P-4X | \$ 868.00 | 10% | \$787.06 |
| EW MonitorPLS NBDOnsite 4220-48T-4X | 97411-4220- 48T-4X | \$ 766.00 | 10% | \$694.57 |

| | | | | |
|--|-----------------------------------|--------------|-----|-------------|
| EW MonitorPLS NBDOnsite 4220-4MW-20P-4X | 97411-4220- 4MW-20P-4X | \$ 834.00 | 10% | \$756.23 |
| EW MonitorPLS NBDOnsite 4220-4MW-8P-4X | 97411-4220- 4MW-8P-4X | \$ 726.00 | 10% | \$658.30 |
| EW MonitorPLS NBDOnsite 4220-8MW-40P-4X | 97411-4220- 8MW-40P-4X | \$ 1,003.00 | 10% | \$909.47 |
| EW MonitorPLS NBDOnsite 4220-8X | 97411-4220-8X | \$ 746.00 | 10% | \$676.44 |
| EW MonitorPLS NBDOnsite- 48001 | 97411-48001 | \$ 8,232.00 | 10% | \$7,464.37 |
| EW MonitorPLS NBDOnsite- 48038 | 97411-48038 | \$ 2,982.00 | 10% | \$2,703.93 |
| EW MonitorPLS NBDOnsite- 48039 | 97411-48039 | \$ 2,982.00 | 10% | \$2,703.93 |
| EW MonitorPLS NBDOnsite- 48040 | 97411-48040 | \$ 2,879.00 | 10% | \$2,610.53 |
| EW MonitorPLS NBDOnsite- 48041 | 97411-48041 | \$ 2,982.00 | 10% | \$2,703.93 |
| EW MonitorPLS NBDOnsite- 48046 | 97411-48046 | \$ 3,827.00 | 10% | \$3,470.13 |
| EW MonitorPLS NBDOnsite- 48047 | 97411-48047 | \$ 9,771.00 | 10% | \$8,859.85 |
| EW MonitorPLS NBDOnsite- 48051 | 97411-48051 | \$ 6,802.00 | 10% | \$6,167.71 |
| EW MonitorPLS NBDOnsite- 48061 | 97411-48061 | \$ 7,909.00 | 10% | \$7,171.49 |
| EW MonitorPLS NBDOnsite- 48062 | 97411-48062 | \$ 12,492.00 | 10% | \$11,327.12 |
| EW MonitorPLS NBDOnsite 5320-16P-4XE | 97411-5320- 16P-4XE | \$ 862.00 | 10% | \$781.62 |
| EW MonitorPLS NBDOnsite 5320-16P-4XE-DC | 97411-5320- 16P-4XE-DC | \$ 918.00 | 10% | \$832.40 |
| EW MonitorPLS NBDOnsite 5320-24P-8XE | 97411-5320- 24P-8XE | \$ 889.00 | 10% | \$806.10 |
| EW MonitorPLS NBDOns 5320- 24T-24S-4XE-XT | 97411-5320- 24T-24S-4XE- XT | \$ 901.00 | 10% | \$816.98 |
| EW MonitorPLS NBDOnsite 5320-24T-4X-XT | 97411-5320- 24T-4X-XT | \$ 699.00 | 10% | \$633.82 |
| EW MonitorPLS NBDOnsite 5320-24T-8XE | 97411-5320- 24T-8XE | \$ 796.00 | 10% | \$721.77 |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite 5320-48P-8XE | 97411-5320- 48P-8XE | \$ 1,138.00 | 10% | <i>\$1,031.88</i> |
| EW MonitorPLS NBDOnsite 5320-48T-8XE | 97411-5320- 48T-8XE | \$ 964.00 | 10% | <i>\$874.11</i> |
| EW MonitorPLS NBDOnsi 5420F-16MW-32P-4XE | 97411-5420F- 16MW-32P- 4XE | \$ 1,620.00 | 10% | <i>\$1,468.94</i> |
| EW MonitorPLS NBDOnsit 5420F-16W-32P-4XE | 97411-5420F- 16W-32P-4XE | \$ 1,464.00 | 10% | <i>\$1,327.48</i> |
| EW MonitorPLS NBDOnsite 5420F-24P-4XE | 97411-5420F- 24P-4XE | \$ 1,061.00 | 10% | <i>\$962.06</i> |
| EW MonitorPLS NBDOnsite 5420F-24S-4XE | 97411-5420F- 24S-4XE | \$ 1,117.00 | 10% | <i>\$1,012.84</i> |
| EW MonitorPLS NBDOnsite 5420F-24T-4XE | 97411-5420F- 24T-4XE | \$ 994.00 | 10% | <i>\$901.31</i> |
| EW MonitorPLS NBDOnsite 5420F-48P-4XE | 97411-5420F- 48P-4XE | \$ 1,273.00 | 10% | <i>\$1,154.29</i> |
| EW MonitorPLS NBDOnsite 5420F-48P-4XL | 97411-5420F- 48P-4XL | \$ 1,383.00 | 10% | <i>\$1,254.04</i> |
| EW MonitorPLS NBDOnsite 5420F-48T-4XE | 97411-5420F- 48T-4XE | \$ 1,080.00 | 10% | <i>\$979.29</i> |
| EW MonitorPLS NBDOnsite 5420F-8W-16P-4XE | 97411-5420F- 8W-16P-4XE | \$ 1,115.00 | 10% | <i>\$1,011.03</i> |
| EW MonitorPLS NBDOnsi 5420M-16MW-32P-4YE | 97411-5420M- 16MW-32P- 4YE | \$ 1,573.00 | 10% | <i>\$1,426.32</i> |
| EW MonitorPLS NBDOnsite 5420M-24T-4YE | 97411-5420M- 24T-4YE | \$ 1,116.00 | 10% | <i>\$1,011.93</i> |
| EW MonitorPLS NBDOnsite 5420M-24W-4YE | 97411-5420M- 24W-4YE | \$ 1,026.00 | 10% | <i>\$930.33</i> |
| EW MonitorPLS NBDOnsite 5420M-48T-4YE | 97411-5420M- 48T-4YE | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS NBDOnsite 5420M-48W-4YE | 97411-5420M- 48W-4YE | \$ 1,421.00 | 10% | <i>\$1,288.49</i> |
| EW MONITORPLUS NBD ONSITE 5520-12MW-36W | 97411-5520- 12MW-36W | \$ 1,670.00 | 10% | <i>\$1,514.27</i> |
| EW MONITORPLUS NBD ONSITE 5520-24T | 97411-5520- 24T | \$ 1,088.00 | 10% | <i>\$986.54</i> |
| EW MONITORPLUS NBD ON 5520-24T-ACDC-BASE | 97411-5520- 24T-ACDC- BASE | \$ 1,088.00 | 10% | <i>\$986.54</i> |

| | | | | |
|--|-----------------------------------|-------------|-----|-------------------|
| EW MONITORPLUS NBD ONSITE 5520-24T-BASE | 97411-5520- 24T-BASE | \$ 1,088.00 | 10% | <i>\$986.54</i> |
| EW MONITORPLUS NBD ONSITE 5520-24W | 97411-5520- 24W | \$ 1,206.00 | 10% | <i>\$1,093.54</i> |
| EW MONITORPLUS NBD ONSITE 5520-24X | 97411-5520- 24X | \$ 1,874.00 | 10% | <i>\$1,699.25</i> |
| EW MONITORPLUS NBD ON 5520-24X-ACDC-BASE | 97411-5520- 24X-ACDC- BASE | \$ 1,874.00 | 10% | <i>\$1,699.25</i> |
| EW MONITORPLUS NBD ONSITE 5520-24X-BASE | 97411-5520- 24X-BASE | \$ 1,874.00 | 10% | <i>\$1,699.25</i> |
| EW MONITORPLUS NBD ONSITE 5520-48SE | 97411-5520- 48SE | \$ 1,816.00 | 10% | <i>\$1,646.66</i> |
| EW MONITORPLU NBD ON 5520-48SE-ACDC-BASE | 97411-5520- 48SE-ACDC- BASE | \$ 1,816.00 | 10% | <i>\$1,646.66</i> |
| EW MONITORPLUS NBD ONSITE 5520-48SE-BASE | 97411-5520- 48SE-BASE | \$ 1,816.00 | 10% | <i>\$1,646.66</i> |
| EW MONITORPLUS NBD ONSITE 5520-48T | 97411-5520- 48T | \$ 1,392.00 | 10% | <i>\$1,262.20</i> |
| EW MONITORPLUS NBD ON 5520-48T-ACDC-BASE | 97411-5520- 48T-ACDC- BASE | \$ 1,392.00 | 10% | <i>\$1,262.20</i> |
| EW MONITORPLUS NBD ONSITE 5520-48T-BASE | 97411-5520- 48T-BASE | \$ 1,392.00 | 10% | <i>\$1,262.20</i> |
| EW MONITORPLUS NBD ONSITE 5520-48W | 97411-5520- 48W | \$ 1,515.00 | 10% | <i>\$1,373.73</i> |
| EW MonitorPLS NBDOnsite 5720-24MW | 97411-5720- 24MW | \$ 1,649.00 | 10% | <i>\$1,495.23</i> |
| EW MonitorPLS NBDOnsite 5720-24MXW | 97411-5720- 24MXW | \$ 2,174.00 | 10% | <i>\$1,971.27</i> |
| EW MonitorPLS NBDOnsite 5720-48MW | 97411-5720- 48MW | \$ 1,868.00 | 10% | <i>\$1,693.81</i> |
| EW MonitorPLS NBDOnsite 5720-48MXW | 97411-5720- 48MXW | \$ 2,548.00 | 10% | <i>\$2,310.40</i> |
| EW MonitorPLS NBDOnsite 7520-48XT-6C | 97411-7520- 48XT-6C | \$ 2,808.00 | 10% | <i>\$2,546.15</i> |
| EW MonitorPLS NBDOnsit 7520- 48XT-6C-AC-F | 97411-7520- 48XT-6C-AC- F | \$ 2,808.00 | 10% | <i>\$2,546.15</i> |
| EW MonitorPLS NBDOnsit 7520- 48XT-6C-AC-R | 97411-7520- 48XT-6C-AC- R | \$ 2,808.00 | 10% | <i>\$2,546.15</i> |

| | | | | |
|---|----------------------------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite 7520-48Y-8C | 97411-7520- 48Y-8C | \$ 2,618.00 | 10% | \$2,373.87 |
| EW MonitorPLS NBDOnsite 7520-48Y-8C-AC-F | 97411-7520- 48Y-8C-AC-F | \$ 2,618.00 | 10% | \$2,373.87 |
| EW MonitorPLS NBDOnsite 7520-48Y-8C-AC-R | 97411-7520- 48Y-8C-AC-R | \$ 2,618.00 | 10% | \$2,373.87 |
| EW MONITORPLUS NBD ONSITE 7520-48YE-8CE | 97411-7520- 48YE-8CE | \$ 3,046.00 | 10% | \$2,761.96 |
| EW MONITORPLU NBD ONS 7520-48YE-8CE-AC-F | 97411-7520- 48YE-8CE-AC- F | \$ 3,046.00 | 10% | \$2,761.96 |
| EW MONITORPLU NBD ONS 7520-48YE-8CE-AC-R | 97411-7520- 48YE-8CE-AC- R | \$ 3,046.00 | 10% | \$2,761.96 |
| EW MonitorPLS NBDOnsite 7720-32C | 97411-7720- 32C | \$ 3,254.00 | 10% | \$2,950.56 |
| EW MonitorPLS NBDOnsite 7720-32C-AC-F | 97411-7720- 32C-AC-F | \$ 3,254.00 | 10% | \$2,950.56 |
| EW MonitorPLS NBDOnsite 7720-32C-AC-R | 97411-7720- 32C-AC-R | \$ 3,254.00 | 10% | \$2,950.56 |
| EW MonitorPLS NBDOnsite 8520-48XT-6C | 97411-8520- 48XT-6C | \$ 3,307.00 | 10% | \$2,998.62 |
| EW MonitorPLSNBDOnsite 8520-48XT-6C-AC-F | 97411-8520- 48XT-6C-AC- F | \$ 3,307.00 | 10% | \$2,998.62 |
| EW MonitorPLSNBDOnsite 8520-48XT-6C-AC-R | 97411-8520- 48XT-6C-AC- R | \$ 3,307.00 | 10% | \$2,998.62 |
| EW MonitorPLSNBDOnsite 8520-48XT-6C-DC-F | 97411-8520- 48XT-6C-DC- F | \$ 3,307.00 | 10% | \$2,998.62 |
| EW MonitorPLSNBDOnsite 8520-48XT-6C-DC-R | 97411-8520- 48XT-6C-DC- R | \$ 3,307.00 | 10% | \$2,998.62 |
| EW MonitorPLS NBDOnsite 8520-48Y-8C | 97411-8520- 48Y-8C | \$ 3,397.00 | 10% | \$3,080.23 |
| EW MonitorPLS NBDOnsite 8520-48Y-8C-AC-F | 97411-8520- 48Y-8C-AC-F | \$ 3,397.00 | 10% | \$3,080.23 |
| EW MonitorPLS NBDOnsite 8520-48Y-8C-AC-R | 97411-8520- 48Y-8C-AC-R | \$ 3,397.00 | 10% | \$3,080.23 |
| EW MonitorPLS NBDOnsite 8520-48Y-8C-DC-F | 97411-8520- 48Y-8C-DC-F | \$ 3,397.00 | 10% | \$3,080.23 |

| | | | | |
|---|----------------------------|--------------|-----|--------------------|
| EW MonitorPLS NBDOnsite 8520-48Y-8C-DC-R | 97411-8520- 48Y-8C-DC-R | \$ 3,397.00 | 10% | <i>\$3,080.23</i> |
| EW MonitorPLS NBDOnsite 8720-32C | 97411-8720- 32C | \$ 3,785.00 | 10% | <i>\$3,432.05</i> |
| EW MonitorPLS NBDOnsite 8720-32C-AC-F | 97411-8720- 32C-AC-F | \$ 3,785.00 | 10% | <i>\$3,432.05</i> |
| EW MonitorPLS NBDOnsite 8720-32C-AC-R | 97411-8720- 32C-AC-R | \$ 3,785.00 | 10% | <i>\$3,432.05</i> |
| EW MonitorPLS NBDOnsite 8720-32C-DC-F | 97411-8720- 32C-DC-F | \$ 3,785.00 | 10% | <i>\$3,432.05</i> |
| EW MonitorPLS NBDOnsite 8720-32C-DC-R | 97411-8720- 32C-DC-R | \$ 3,785.00 | 10% | <i>\$3,432.05</i> |
| EW MonitorPLUS NBDOnsite- 8806 | 97411-8806 | \$ 3,210.00 | 10% | <i>\$2,910.67</i> |
| EW MonitorPLS NBDOnsite- 8810 | 97411-8810 | \$ 6,713.00 | 10% | <i>\$6,087.01</i> |
| EW MonitorPLS NBDOnsite 8820-40C | 97411-8820- 40C | \$ 11,930.00 | 10% | <i>\$10,817.53</i> |
| EW MonitorPLS NBDOnsite 8820-40C-AC-F | 97411-8820- 40C-AC-F | \$ 11,930.00 | 10% | <i>\$10,817.53</i> |
| EW MonitorPLS NBDOnsite 8820-40C-AC-R | 97411-8820- 40C-AC-R | \$ 11,930.00 | 10% | <i>\$10,817.53</i> |
| EW MonitorPLS NBDOnsite 8820-40C-DC-F | 97411-8820- 40C-DC-F | \$ 11,930.00 | 10% | <i>\$10,817.53</i> |
| EW MonitorPLS NBDOnsite 8820-40C-DC-R | 97411-8820- 40C-DC-R | \$ 11,930.00 | 10% | <i>\$10,817.53</i> |
| EW MonitorPLS NBDOnsite 8820-80C | 97411-8820- 80C | \$ 21,138.00 | 10% | <i>\$19,166.88</i> |
| EW MonitorPLS NBDOnsite 8820-80C-AC-F | 97411-8820- 80C-AC-F | \$ 21,138.00 | 10% | <i>\$19,166.88</i> |
| EW MonitorPLS NBDOnsite 8820-80C-AC-R | 97411-8820- 80C-AC-R | \$ 21,138.00 | 10% | <i>\$19,166.88</i> |
| EW MonitorPLS NBDOnsite 8820-80C-DC-F | 97411-8820- 80C-DC-F | \$ 21,138.00 | 10% | <i>\$19,166.88</i> |
| EW MonitorPLS NBDOnsite 8820-80C-DC-R | 97411-8820- 80C-DC-R | \$ 21,138.00 | 10% | <i>\$19,166.88</i> |
| EW MonitorPLS NBDOnsite 9920-16C | 97411-9920- 16C | \$ 10,025.00 | 10% | <i>\$9,090.17</i> |
| EW MonitorPLS NBDOnsite 9920-4D | 97411-9920-4D | \$ 10,025.00 | 10% | <i>\$9,090.17</i> |
| EW MonitorPLS NBDOnsite 9920-NPB-8 | 97411-9920- NPB-8 | \$ 16,180.00 | 10% | <i>\$14,671.22</i> |

| | | | | |
|--|-------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite AH-AP-1130-AC-CE | 97411-AH-AP-1130-AC-CE | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite AH-AP-1130-AC-FC | 97411-AH-AP-1130-AC-FCC | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite AH-AP-1130-AC-W | 97411-AH-AP-1130-AC-W | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite AH-AP-122-AC-CAN | 97411-AH-AP-122-AC-CAN | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-122-AC-CE | 97411-AH-AP-122-AC-CE | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-122-AC-FCC | 97411-AH-AP-122-AC-FCC | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-122-AC-W | 97411-AH-AP-122-AC-W | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-130-AC-CE | 97411-AH-AP-130-AC-CE | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-130-AC-FCC | 97411-AH-AP-130-AC-FCC | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-130-AC-W | 97411-AH-AP-130-AC-W | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-150W-AC-CA | 97411-AH-AP-150W-AC-CAN | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-150W-AC-CE | 97411-AH-AP-150W-AC-CE | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-150W-AC-FC | 97411-AH-AP-150W-AC-FCC | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-150W-AC-W | 97411-AH-AP-150W-AC-W | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-230-AC-CE | 97411-AH-AP-230-AC-CE | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-230-AC-FCC | 97411-AH-AP-230-AC-FCC | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-230-AC-W | 97411-AH-AP-230-AC-W | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-250-AC-CAN | 97411-AH-AP-250-AC-CAN | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-250-AC-CE | 97411-AH-AP-250-AC-CE | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite AH-AP-250-AC-FCC | 97411-AH-AP-250-AC-FCC | \$ 235.00 | 10% | <i>\$213.09</i> |

| | | | | |
|--|-------------------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite AH-AP-250-AC-W | 97411-AH-AP-250-AC-W | \$ 235.00 | 10% | \$213.09 |
| EW MonitorPLS NBDOnsite AH-AP-630-AX-CAN | 97411-AH-AP-630-AX-CAN | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS NBDOnsite AH-AP-630-AX-CE | 97411-AH-AP-630-AX-CE | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS NBDOnsite AH-AP-630-AX-FCC | 97411-AH-AP-630-AX-FCC | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS NBDOnsite AH-AP-630-AX-W | 97411-AH-AP-630-AX-W | \$ 274.00 | 10% | \$248.45 |
| EW MonitorPLS NBDOnsite AH-AP-650-AX-CAN | 97411-AH-AP-650-AX-CAN | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-AP-650-AX-CE | 97411-AH-AP-650-AX-CE | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-AP-650-AX-FCC | 97411-AH-AP-650-AX-FCC | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-AP-650-AX-W | 97411-AH-AP-650-AX-W | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-AP-650X-AX-CA | 97411-AH-AP-650X-AX-CAN | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-AP-650X-AX-CE | 97411-AH-AP-650X-AX-CE | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-AP-650X-AX-FC | 97411-AH-AP-650X-AX-FCC | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-AP-650X-AX-W | 97411-AH-AP-650X-AX-W | \$ 245.00 | 10% | \$222.15 |
| EW MonitorPLS NBDOnsite AH-ATOM-CAN | 97411-AH-ATOM-CAN | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS NBDOnsite AH-ATOM-CE-EU | 97411-AH-ATOM-CE-EU | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AH-ATOM-CE-UK | 97411-AH-ATOM-CE-UK | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AH-ATOM-FCC | 97411-AH-ATOM-FCC | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS NBDOnsite AH-ATOM-W | 97411-AH-ATOM-W | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS NBDOnsite AH-ATOM-W-EU | 97411-AH-ATOM-W-EU | \$ 259.00 | 10% | \$234.85 |

| | | | | |
|--|----------------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite AH-ATOM-W-UK | 97411-AH-ATOM-W-UK | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AH-SR-2208P-AU | 97411-AH-SR-2208P-AU | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite AH-SR-2208P-EU | 97411-AH-SR-2208P-EU | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite AH-SR-2208P-NA | 97411-AH-SR-2208P-NA | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite AH-SR-2208P-UK | 97411-AH-SR-2208P-UK | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite AH-SR-2224P-AU | 97411-AH-SR-2224P-AU | \$ 700.00 | 10% | \$634.73 |
| EW MonitorPLS NBDOnsite AH-SR-2224P-EU | 97411-AH-SR-2224P-EU | \$ 700.00 | 10% | \$634.73 |
| EW MonitorPLS NBDOnsite AH-SR-2224P-NA | 97411-AH-SR-2224P-NA | \$ 700.00 | 10% | \$634.73 |
| EW MonitorPLS NBDOnsite AH-SR-2224P-UK | 97411-AH-SR-2224P-UK | \$ 700.00 | 10% | \$634.73 |
| EW MonitorPLS NBDOnsite AH-SR-2324P-AU | 97411-AH-SR-2324P-AU | \$ 741.00 | 10% | \$671.90 |
| EW MonitorPLS NBDOnsite AH-SR-2324P-EU | 97411-AH-SR-2324P-EU | \$ 741.00 | 10% | \$671.90 |
| EW MonitorPLS NBDOnsite AH-SR-2324P-NA | 97411-AH-SR-2324P-NA | \$ 741.00 | 10% | \$671.90 |
| EW MonitorPLS NBDOnsite AH-SR-2324P-UK | 97411-AH-SR-2324P-UK | \$ 741.00 | 10% | \$671.90 |
| EW MonitorPLS NBDOnsite AH-SR-2348P-AU | 97411-AH-SR-2348P-AU | \$ 878.00 | 10% | \$796.13 |
| EW MonitorPLS NBDOnsite AH-SR-2348P-EU | 97411-AH-SR-2348P-EU | \$ 878.00 | 10% | \$796.13 |
| EW MonitorPLS NBDOnsite AH-SR-2348P-NA | 97411-AH-SR-2348P-NA | \$ 878.00 | 10% | \$796.13 |
| EW MonitorPLS NBDOnsite AH-SR-2348P-UK | 97411-AH-SR-2348P-UK | \$ 878.00 | 10% | \$796.13 |
| EW MonitorPLS NBDOnsite AH-XR200P-AU | 97411-AH-XR200P-AU | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite AH-XR200P-EU | 97411-AH-XR200P-EU | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite AH-XR200P-UK | 97411-AH-XR200P-UK | \$ 665.00 | 10% | \$602.99 |
| EW MonitorPLS NBDOnsite AH-XR200P-US | 97411-AH-XR200P-US | \$ 665.00 | 10% | \$602.99 |

| | | | | |
|--|---------------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite AH- XR600P | 97411-AH- XR600P | \$ 671.00 | 10% | <i>\$608.43</i> |
| EW MonitorPLS NBDOnsite AH- XR600P-AU | 97411-AH- XR600P-AU | \$ 676.00 | 10% | <i>\$612.96</i> |
| EW MonitorPLS NBDOnsite AH- XR600P-EU | 97411-AH- XR600P-EU | \$ 676.00 | 10% | <i>\$612.96</i> |
| EW MonitorPLS NBDOnsite AH- XR600P-KR | 97411-AH- XR600P-KR | \$ 676.00 | 10% | <i>\$612.96</i> |
| EW MonitorPLS NBDOnsite AH- XR600P-UK | 97411-AH- XR600P-UK | \$ 676.00 | 10% | <i>\$612.96</i> |
| EW MonitorPLS NBDOnsite AH- XR600P-US | 97411-AH- XR600P-US | \$ 676.00 | 10% | <i>\$612.96</i> |
| EW MonitorPLS NBDOnsite AP- 8533-IL | 97411-AP- 8533-68SB30- IL | \$ 289.00 | 10% | <i>\$262.05</i> |
| EW MonitorPLS NBDOnsite AP3000-IL | 97411-AP3000- IL | \$ 173.94 | 10% | <i>\$157.72</i> |
| EW MonitorPLS NBDOnsite AP3000-TN | 97411-AP3000- TN | \$ 173.94 | 10% | <i>\$157.72</i> |
| EW MonitorPLS NBDOnsite AP3000-WW | 97411-AP3000- WW | \$ 173.94 | 10% | <i>\$157.72</i> |
| EW MonitorPLS NBDOnsite AP3000X-WW | 97411- AP3000X-WW | \$ 190.19 | 10% | <i>\$172.45</i> |
| EW MonitorPLS NBDOnsite AP302W-CAN | 97411- AP302W-CAN | \$ 228.00 | 10% | <i>\$206.74</i> |
| EW MonitorPLS NBDOnsite AP302W-EG | 97411- AP302W-EG | \$ 175.00 | 10% | <i>\$158.68</i> |
| EW MonitorPLS NBDOnsite AP302W-FCC | 97411- AP302W-FCC | \$ 228.00 | 10% | <i>\$206.74</i> |
| EW MonitorPLS NBDOnsite AP302W-WR | 97411- AP302W-WR | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite AP305C-1-CAN | 97411-AP305C- 1-CAN | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS NBDOnsite AP305C-1-EG | 97411-AP305C- 1-EG | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS NBDOnsite AP305C-1-FCC | 97411-AP305C- 1-FCC | \$ 234.00 | 10% | <i>\$212.18</i> |
| EW MonitorPLS NBDOnsite AP305C-1-IL | 97411-AP305C- 1-IL | \$ 234.00 | 10% | <i>\$212.18</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite AP305C-1-WR | 97411-AP305C- 1-WR | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBDOnsite AP305C-CAN | 97411-AP305C- CAN | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305C-EG | 97411-AP305C- EG | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305C-FCC | 97411-AP305C- FCC | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305C-IL | 97411-AP305C- IL | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305C-WR | 97411-AP305C- WR | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305CX-CAN | 97411- AP305CX- CAN | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305CX-FCC | 97411- AP305CX- FCC | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305CX-IL | 97411- AP305CX-IL | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP305CX-WR | 97411- AP305CX-WR | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP310e-1-WR | 97411-AP310e- 1-WR | \$ 219.00 | 10% | \$198.58 |
| EW MonitorPLS NBDOnsite AP310e-CAN | 97411-AP310e- CAN | \$ 230.00 | 10% | \$208.55 |
| EW MonitorPLS NBDOnsite AP310e-FCC | 97411-AP310e- FCC | \$ 230.00 | 10% | \$208.55 |
| EW MonitorPLS NBDOnsite AP310e-IL | 97411-AP310e- IL | \$ 230.00 | 10% | \$208.55 |
| EW MonitorPLS NBDOnsite AP310e-WR | 97411-AP310e- WR | \$ 230.00 | 10% | \$208.55 |
| EW MonitorPLS NBDOnsite AP310i-1-WR | 97411-AP310i- 1-WR | \$ 219.00 | 10% | \$198.58 |
| EW MonitorPLS NBDOnsite AP310i-CAN | 97411-AP310i- CAN | \$ 230.00 | 10% | \$208.55 |
| EW MonitorPLS NBDOnsite AP310i-FCC | 97411-AP310i- FCC | \$ 230.00 | 10% | \$208.55 |
| EW MonitorPLS NBDOnsite AP310i-IL | 97411-AP310i- IL | \$ 230.00 | 10% | \$208.55 |
| EW MonitorPLS NBDOnsite AP310i-WR | 97411-AP310i- WR | \$ 230.00 | 10% | \$208.55 |

| | | | | |
|---|------------------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite AP360e-CAN | 97411-AP360e- CAN | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP360e-FCC | 97411-AP360e- FCC | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP360e-IL | 97411-AP360e- IL | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP360e-WR | 97411-AP360e- WR | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP360i-CAN | 97411-AP360i- CAN | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP360i-FCC | 97411-AP360i- FCC | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP360i-WR | 97411-AP360i- WR | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP4000-WW | 97411-AP4000- 1-WW | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBDOnsite AP4000-IL | 97411-AP4000- IL | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBDOnsite AP4000-WW | 97411-AP4000- WW | \$ 223.00 | 10% | \$202.21 |
| EW MonitorPLS NBDOnsite AP410C-1-CAN | 97411-AP410C- 1-CAN | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBDOnsite AP410C-1-EG | 97411-AP410C- 1-EG | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBDOnsite AP410C-1-FCC | 97411-AP410C- 1-FCC | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBDOnsite AP410C-1-IL | 97411-AP410C- 1-IL | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBDOnsite AP410C-1-WR | 97411-AP410C- 1-WR | \$ 234.00 | 10% | \$212.18 |
| EW MonitorPLS NBDOnsite AP410C-CAN | 97411-AP410C- CAN | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP410C-EG | 97411-AP410C- EG | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP410C-FCC | 97411-AP410C- FCC | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP410C-IL | 97411-AP410C- IL | \$ 252.00 | 10% | \$228.50 |
| EW MonitorPLS NBDOnsite AP410C-WR | 97411-AP410C- WR | \$ 252.00 | 10% | \$228.50 |

| | | | | |
|---|------------------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite AP410e-CAN | 97411-AP410e- CAN | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AP410e-FCC | 97411-AP410e- FCC | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AP410e-WR | 97411-AP410e- WR | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AP410i-1-FCC | 97411-AP410i- 1-FCC | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS NBDOnsite AP410i-1-WR | 97411-AP410i- 1-WR | \$ 247.00 | 10% | \$223.97 |
| EW MonitorPLS NBDOnsite AP410i-CAN | 97411-AP410i- CAN | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AP410i-FCC | 97411-AP410i- FCC | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AP410i-IL | 97411-AP410i- IL | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AP410i-WR | 97411-AP410i- WR | \$ 259.00 | 10% | \$234.85 |
| EW MonitorPLS NBDOnsite AP460C-CAN | 97411-AP460C- CAN | \$ 277.00 | 10% | \$251.17 |
| EW MonitorPLS NBDOnsite AP460C-EG | 97411-AP460C- EG | \$ 277.00 | 10% | \$251.17 |
| EW MonitorPLS NBDOnsite AP460C-FCC | 97411-AP460C- FCC | \$ 277.00 | 10% | \$251.17 |
| EW MonitorPLS NBDOnsite AP460C-IL | 97411-AP460C- IL | \$ 277.00 | 10% | \$251.17 |
| EW MonitorPLS NBDOnsite AP460C-WR | 97411-AP460C- WR | \$ 277.00 | 10% | \$251.17 |
| EW MonitorPLS NBDOnsite AP460e-CAN | 97411-AP460e- CAN | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS NBDOnsite AP460e-FCC | 97411-AP460e- FCC | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS NBDOnsite AP460e-WR | 97411-AP460e- WR | \$ 261.00 | 10% | \$236.66 |
| EW MonitorPLS NBDOnsite AP460i-CAN | 97411-AP460i- CAN | \$ 261.00 | 10% | \$236.66 |
| EW MonitorPLS NBDOnsite AP460i-FCC | 97411-AP460i- FCC | \$ 261.00 | 10% | \$236.66 |
| EW MonitorPLS NBDOnsite AP460i-IL | 97411-AP460i- IL | \$ 261.00 | 10% | \$236.66 |
| EW MonitorPLS NBDOnsite AP460i-WR | 97411-AP460i- WR | \$ 261.00 | 10% | \$236.66 |

| | | | | |
|---|-----------------------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite AP460S12C-CAN | 97411- AP460S12C- CAN | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW MonitorPLS NBDOnsite AP460S12C-FCC | 97411- AP460S12C- FCC | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW MonitorPLS NBDOnsite AP460S12C-WR | 97411- AP460S12C- WR | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW MonitorPLS NBDOnsite AP460S6C-CAN | 97411- AP460S6C- CAN | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW MonitorPLS NBDOnsite AP460S6C-FCC | 97411- AP460S6C- FCC | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW MonitorPLS NBDOnsite AP460S6C-WR | 97411- AP460S6C- WR | \$ 277.00 | 10% | <i>\$251.17</i> |
| EW MonitorPLS NBDOnsite AP5010-IL | 97411-AP5010- IL | \$ 259.00 | 10% | <i>\$234.85</i> |
| EW MonitorPLS NBDOnsite AP5010-WW | 97411-AP5010- WW | \$ 259.00 | 10% | <i>\$234.85</i> |
| EW MonitorPLS NBDOnsite AP5020-WW | 97411-AP5020- WW | \$ 271.38 | 6% | <i>\$257.01</i> |
| EW MonitorPLS NBDOnsite AP5050D-WW | 97411- AP5050D-WW | \$ 425.00 | 10% | <i>\$385.37</i> |
| EW MonitorPLS NBDOnsite AP5050U-WW | 97411- AP5050U-WW | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW MonitorPLS NBDOnsite AP505i-FCC | 97411-AP505i- FCC | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW MonitorPLS NBDOnsite AP505i-FCC-TAA | 97411-AP505i- FCC-TAA | \$ 265.00 | 10% | <i>\$240.29</i> |
| EW MonitorPLS NBDOnsite AP505i-WR | 97411-AP505i- WR | \$ 279.00 | 10% | <i>\$252.98</i> |
| EW MonitorPLS NBDOnsite AP510C-CAN | 97411-AP510C- CAN | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite AP510C-CE | 97411-AP510C- CE | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite AP510C-FCC | 97411-AP510C- FCC | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite AP510C-W | 97411-AP510C- W | \$ 238.00 | 10% | <i>\$215.81</i> |

| | | | | |
|---|---------------------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite AP510C-WW | 97411-AP510C- WW | \$ 315.00 | 10% | \$285.63 |
| EW MonitorPLS NBDOnsite AP510CX-CAN | 97411- AP510CX- CAN | \$ 238.00 | 10% | \$215.81 |
| EW MonitorPLS NBDOnsite AP510CX-CE | 97411- AP510CX-CE | \$ 238.00 | 10% | \$215.81 |
| EW MonitorPLS NBDOnsite AP510CX-FCC | 97411- AP510CX- FCC | \$ 238.00 | 10% | \$215.81 |
| EW MonitorPLS NBDOnsite AP510CX-W | 97411- AP510CX-W | \$ 238.00 | 10% | \$215.81 |
| EW MonitorPLS NBDOnsite AP510CX-WW | 97411- AP510CX-WW | \$ 315.00 | 10% | \$285.63 |
| EW MonitorPLS NBDOnsite AP510e-FCC | 97411-AP510e- FCC | \$ 310.00 | 10% | \$281.09 |
| EW MonitorPLS NBDOnsite AP510e-FCC-TAA | 97411-AP510e- FCC-TAA | \$ 310.00 | 10% | \$281.09 |
| EW MonitorPLS NBDOnsite AP510e-WR | 97411-AP510e- WR | \$ 295.00 | 10% | \$267.49 |
| EW MonitorPLS NBDOnsite AP510i-1-FCC | 97411-AP510i- 1-FCC | \$ 277.00 | 10% | \$251.17 |
| EW MonitorPLS NBDOnsite AP510i-1-WR | 97411-AP510i- 1-WR | \$ 277.00 | 10% | \$251.17 |
| EW MonitorPLS NBDOnsite AP510i-FCC | 97411-AP510i- FCC | \$ 290.00 | 10% | \$262.96 |
| EW MonitorPLS NBDOnsite AP510i-FCC-TAA | 97411-AP510i- FCC-TAA | \$ 290.00 | 10% | \$262.96 |
| EW MonitorPLS NBDOnsite AP510i-WR | 97411-AP510i- WR | \$ 290.00 | 10% | \$262.96 |
| EW MonitorPLS NBDOnsite AP560h-FCC | 97411-AP560h- FCC | \$ 472.00 | 10% | \$427.99 |
| EW MonitorPLS NBDOnsite AP560h-WR | 97411-AP560h- WR | \$ 472.00 | 10% | \$427.99 |
| EW MonitorPLS NBDOnsite AP560i-FCC | 97411-AP560i- FCC | \$ 390.00 | 10% | \$353.63 |
| EW MonitorPLS NBDOnsite AP560i-WR | 97411-AP560i- WR | \$ 372.00 | 10% | \$337.31 |
| EW MonitorPLS NBDOnsite AP560m-FCC | 97411-AP560m- FCC | \$ 390.00 | 10% | \$353.63 |

| | | | | |
|---------------------------------------|----------------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite AP560t-FCC | 97411-AP560t- FCC | \$ 472.00 | 10% | <i>\$427.99</i> |
| EW MonitorPLS NBDOnsite AP560u-FCC | 97411-AP560u- FCC | \$ 363.00 | 10% | <i>\$329.15</i> |
| EW MonitorPLS NBDOnsite E2122 | 97411-E2122 | \$ 5,715.00 | 10% | <i>\$5,182.08</i> |
| EW MonitorPLS NBDOnsite E2122-1 | 97411-E2122-1 | \$ 5,416.00 | 10% | <i>\$4,910.96</i> |
| EW MonitorPLS NBDOnsite E3120-1 | 97411-E3120-1 | \$ 8,465.00 | 10% | <i>\$7,675.64</i> |
| EW MonitorPLS NBDOnsite E3125 | 97411-E3125 | \$ 9,316.00 | 10% | <i>\$8,447.28</i> |
| EW MonitorPLS NBDOnsite- H30131 | 97411-H30131 | \$ 2,014.00 | 10% | <i>\$1,826.19</i> |
| EW MonitorPLS NBDOnsite- H30132 | 97411-H30132 | \$ 1,976.00 | 10% | <i>\$1,791.74</i> |
| EW MonitorPLS NBDOnsite- H30133 | 97411-H30133 | \$ 4,117.00 | 10% | <i>\$3,733.09</i> |
| EW MonitorPLS NBDOnsite- H30134 | 97411-H30134 | \$ 5,032.00 | 10% | <i>\$4,562.77</i> |
| EW MonitorPLS NBDOnsite- H30135 | 97411-H30135 | \$ 4,197.00 | 10% | <i>\$3,805.63</i> |
| EW MonitorPLS NBDOnsite- H30136 | 97411-H30136 | \$ 5,032.00 | 10% | <i>\$4,562.77</i> |
| EW MonitorPLS NBDOnsite- H30184 | 97411-H30184 | \$ 744.00 | 10% | <i>\$674.62</i> |
| EW MonitorPLS NBDOnsite- H30185 | 97411-H30185 | \$ 1,018.00 | 10% | <i>\$923.07</i> |
| EW MonitorPLS NBDOnsite- H30186 | 97411-H30186 | \$ 868.00 | 10% | <i>\$787.06</i> |
| EW MonitorPLS NBDOnsite- H30187 | 97411-H30187 | \$ 809.00 | 10% | <i>\$733.56</i> |
| EW MonitorPLS NBDOnsite- H30188 | 97411-H30188 | \$ 868.00 | 10% | <i>\$787.06</i> |
| EW MonitorPLS NBDOnsite- H30189 | 97411-H30189 | \$ 868.00 | 10% | <i>\$787.06</i> |
| EW MonitorPLS NBDOnsite- H30190 | 97411-H30190 | \$ 1,087.00 | 10% | <i>\$985.64</i> |
| EW MonitorPLS NBDOnsite- H30214 | 97411-H30214 | \$ 927.00 | 10% | <i>\$840.56</i> |
| EW MonitorPLS NBDOnsite- H30215 | 97411-H30215 | \$ 927.00 | 10% | <i>\$840.56</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite-H30216 | 97411-H30216 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30217 | 97411-H30217 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30218 | 97411-H30218 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30219 | 97411-H30219 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30220 | 97411-H30220 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30221 | 97411-H30221 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30222 | 97411-H30222 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30223 | 97411-H30223 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30224 | 97411-H30224 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30225 | 97411-H30225 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30226 | 97411-H30226 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30227 | 97411-H30227 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30228 | 97411-H30228 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30229 | 97411-H30229 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30267 | 97411-H30267 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30268 | 97411-H30268 | \$ 1,087.00 | 10% | \$985.64 |
| EW MonitorPLS NBDOnsite-H30269 | 97411-H30269 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30270 | 97411-H30270 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30271 | 97411-H30271 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30272 | 97411-H30272 | \$ 1,285.00 | 10% | \$1,165.17 |
| EW MonitorPLS NBDOnsite-H30273 | 97411-H30273 | \$ 1,485.00 | 10% | \$1,346.52 |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-H30274 | 97411-H30274 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW MonitorPLS NBDOnsite-H30275 | 97411-H30275 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS NBDOnsite-H30276 | 97411-H30276 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS NBDOnsite-H30277 | 97411-H30277 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW MonitorPLS NBDOnsite-H30278 | 97411-H30278 | \$ 1,549.00 | 10% | <i>\$1,404.56</i> |
| EW MonitorPLS NBDOnsite-H30279 | 97411-H30279 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW MonitorPLS NBDOnsite-H30280 | 97411-H30280 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW MonitorPLS NBDOnsite-H30281 | 97411-H30281 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW MonitorPLS NBDOnsite-H30282 | 97411-H30282 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW MonitorPLS NBDOnsite-H30283 | 97411-H30283 | \$ 1,168.00 | 10% | <i>\$1,059.08</i> |
| EW MonitorPLS NBDOnsite-H30284 | 97411-H30284 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |
| EW MonitorPLS NBDOnsite-H30296 | 97411-H30296 | \$ 927.00 | 10% | <i>\$840.56</i> |
| EW MonitorPLS NBDOnsite-H30297 | 97411-H30297 | \$ 927.00 | 10% | <i>\$840.56</i> |
| EW MonitorPLS NBDOnsite-H30298 | 97411-H30298 | \$ 927.00 | 10% | <i>\$840.56</i> |
| EW MonitorPLS NBDOnsite-H30299 | 97411-H30299 | \$ 927.00 | 10% | <i>\$840.56</i> |
| EW MonitorPLS NBDOnsite-H30381 | 97411-H30381 | \$ 1,705.00 | 10% | <i>\$1,546.01</i> |
| EW MonitorPLS NBDOnsite-H30384 | 97411-H30384 | \$ 1,608.00 | 10% | <i>\$1,458.05</i> |
| EW MonitorPLS NBDOnsite-H30391 | 97411-H30391 | \$ 1,149.00 | 10% | <i>\$1,041.86</i> |
| EW MonitorPLS NBDOnsite-H30392 | 97411-H30392 | \$ 1,149.00 | 10% | <i>\$1,041.86</i> |
| EW MonitorPLS NBDOnsite-H30393 | 97411-H30393 | \$ 644.00 | 10% | <i>\$583.95</i> |
| EW MonitorPLS NBDOnsite-H30394 | 97411-H30394 | \$ 1,995.00 | 10% | <i>\$1,808.97</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-H30395 | 97411-H30395 | \$ 2,330.00 | 10% | <i>\$2,112.73</i> |
| EW MonitorPLS NBDOnsite-H30396 | 97411-H30396 | \$ 2,142.00 | 10% | <i>\$1,942.26</i> |
| EW MonitorPLS NBDOnsite-H30397 | 97411-H30397 | \$ 2,498.00 | 10% | <i>\$2,265.06</i> |
| EW MonitorPLS NBDOnsite-H30398 | 97411-H30398 | \$ 656.00 | 10% | <i>\$594.83</i> |
| EW MonitorPLS NBDOnsite-H30400 | 97411-H30400 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW MonitorPLS NBDOnsite-H30401 | 97411-H30401 | \$ 571.00 | 10% | <i>\$517.75</i> |
| EW MonitorPLS NBDOnsite-H30402 | 97411-H30402 | \$ 586.00 | 10% | <i>\$531.36</i> |
| EW MonitorPLS NBDOnsite-H30403 | 97411-H30403 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW MonitorPLS NBDOnsite-H30480 | 97411-H30480 | \$ 1,796.00 | 10% | <i>\$1,628.52</i> |
| EW MonitorPLS NBDOnsite-H30495 | 97411-H30495 | \$ 2,565.00 | 10% | <i>\$2,325.81</i> |
| EW MonitorPLS NBDOnsite-H30496 | 97411-H30496 | \$ 2,517.00 | 10% | <i>\$2,282.29</i> |
| EW MonitorPLS NBDOnsite-H30497 | 97411-H30497 | \$ 3,163.00 | 10% | <i>\$2,868.05</i> |
| EW MonitorPLS NBDOnsite-H30498 | 97411-H30498 | \$ 3,102.00 | 10% | <i>\$2,812.74</i> |
| EW MonitorPLS NBDOnsite-H30499 | 97411-H30499 | \$ 899.00 | 10% | <i>\$815.17</i> |
| EW MonitorPLS NBDOnsite-H30501 | 97411-H30501 | \$ 3,102.00 | 10% | <i>\$2,812.74</i> |
| EW MonitorPLS NBDOnsite-H30502 | 97411-H30502 | \$ 4,124.00 | 10% | <i>\$3,739.44</i> |
| EW MonitorPLS NBDOnsite-H30503 | 97411-H30503 | \$ 899.00 | 10% | <i>\$815.17</i> |
| EW MonitorPLS NBDOnsite-H30505 | 97411-H30505 | \$ 4,659.00 | 10% | <i>\$4,224.55</i> |
| EW MonitorPLS NBDOnsite-H30506 | 97411-H30506 | \$ 5,901.00 | 10% | <i>\$5,350.73</i> |
| EW MonitorPLS NBDOnsite-H30509 | 97411-H30509 | \$ 4,124.00 | 10% | <i>\$3,739.44</i> |
| EW MonitorPLS NBDOnsite-H30510 | 97411-H30510 | \$ 4,659.00 | 10% | <i>\$4,224.55</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-H30511 | 97411-H30511 | \$ 5,901.00 | 10% | <i>\$5,350.73</i> |
| EW MonitorPLS NBDOnsite-H30512 | 97411-H30512 | \$ 899.00 | 10% | <i>\$815.17</i> |
| EW MonitorPLS NBDOnsite-H30513 | 97411-H30513 | \$ 1,344.00 | 10% | <i>\$1,218.67</i> |
| EW MonitorPLS NBDOnsite-H30525 | 97411-H30525 | \$ 4,935.00 | 10% | <i>\$4,474.81</i> |
| EW MonitorPLS NBDOnsite-H30526 | 97411-H30526 | \$ 3,700.00 | 10% | <i>\$3,354.98</i> |
| EW MonitorPLS NBDOnsite-H30528 | 97411-H30528 | \$ 5,694.00 | 10% | <i>\$5,163.03</i> |
| EW MonitorPLS NBDOnsite-H30531 | 97411-H30531 | \$ 7,997.00 | 10% | <i>\$7,251.28</i> |
| EW MonitorPLS NBDOnsite-H30532 | 97411-H30532 | \$ 7,997.00 | 10% | <i>\$7,251.28</i> |
| EW MonitorPLS NBDOnsite-H30534 | 97411-H30534 | \$ 8,152.00 | 10% | <i>\$7,391.83</i> |
| EW MonitorPLS NBDOnsite-H30535 | 97411-H30535 | \$ 8,673.00 | 10% | <i>\$7,864.24</i> |
| EW MonitorPLS NBDOnsite-H30536 | 97411-H30536 | \$ 7,997.00 | 10% | <i>\$7,251.28</i> |
| EW MonitorPLS NBDOnsite-H30537 | 97411-H30537 | \$ 8,673.00 | 10% | <i>\$7,864.24</i> |
| EW MonitorPLS NBDOnsite-H30538 | 97411-H30538 | \$ 4,935.00 | 10% | <i>\$4,474.81</i> |
| EW MonitorPLS NBDOnsite-H30539 | 97411-H30539 | \$ 9,261.00 | 10% | <i>\$8,397.41</i> |
| EW MonitorPLS NBDOnsite-H30540 | 97411-H30540 | \$ 9,562.00 | 10% | <i>\$8,670.34</i> |
| EW MonitorPLS NBDOnsite-H30543 | 97411-H30543 | \$ 882.00 | 10% | <i>\$799.75</i> |
| EW MonitorPLS NBDOnsite-H30544 | 97411-H30544 | \$ 1,378.00 | 10% | <i>\$1,249.50</i> |
| EW MonitorPLS NBDOnsite-H30548 | 97411-H30548 | \$ 882.00 | 10% | <i>\$799.75</i> |
| EW MonitorPLS NBDOnsite-H30549 | 97411-H30549 | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS NBDOnsite-H30550 | 97411-H30550 | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS NBDOnsite-H30552 | 97411-H30552 | \$ 882.00 | 10% | <i>\$799.75</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite-H30553 | 97411-H30553 | \$ 1,256.00 | 10% | <i>\$1,138.88</i> |
| EW MonitorPLS NBDOnsite-H30569 | 97411-H30569 | \$ 4,117.00 | 10% | <i>\$3,733.09</i> |
| EW MonitorPLS NBDOnsite-H30570 | 97411-H30570 | \$ 4,807.00 | 10% | <i>\$4,358.75</i> |
| EW MonitorPLS NBDOnsite-H30571 | 97411-H30571 | \$ 4,807.00 | 10% | <i>\$4,358.75</i> |
| EW MonitorPLS NBDOnsite-H30573 | 97411-H30573 | \$ 4,117.00 | 10% | <i>\$3,733.09</i> |
| EW MonitorPLS NBDOnsite-H30574 | 97411-H30574 | \$ 4,493.00 | 10% | <i>\$4,074.03</i> |
| EW MonitorPLS NBDOnsite-H30575 | 97411-H30575 | \$ 3,050.00 | 10% | <i>\$2,765.59</i> |
| EW MonitorPLS NBDOnsite-H30576 | 97411-H30576 | \$ 4,117.00 | 10% | <i>\$3,733.09</i> |
| EW MonitorPLS NBDOnsite-H30577 | 97411-H30577 | \$ 4,716.00 | 10% | <i>\$4,276.23</i> |
| EW MonitorPLS NBDOnsite-H30578 | 97411-H30578 | \$ 4,716.00 | 10% | <i>\$4,276.23</i> |
| EW MonitorPLS NBDOnsite-H30587 | 97411-H30587 | \$ 3,772.00 | 10% | <i>\$3,420.26</i> |
| EW MonitorPLS NBDOnsite-H30588 | 97411-H30588 | \$ 2,683.00 | 10% | <i>\$2,432.81</i> |
| EW MonitorPLS NBDOnsite-H30589 | 97411-H30589 | \$ 4,027.00 | 10% | <i>\$3,651.48</i> |
| EW MonitorPLS NBDOnsite-H30632 | 97411-H30632 | \$ 284.00 | 10% | <i>\$257.52</i> |
| EW MonitorPLS NBDOnsite-H30633 | 97411-H30633 | \$ 284.00 | 10% | <i>\$257.52</i> |
| EW MonitorPLS NBDOnsite-H30643 | 97411-H30643 | \$ 7,373.00 | 10% | <i>\$6,685.47</i> |
| EW MonitorPLS NBDOnsite-H30706 | 97411-H30706 | \$ 5,804.00 | 10% | <i>\$5,262.78</i> |
| EW MonitorPLS NBDOnsite-H30707 | 97411-H30707 | \$ 3,700.00 | 10% | <i>\$3,354.98</i> |
| EW MonitorPLS NBDOnsite-H30724 | 97411-H30724 | \$ 571.00 | 10% | <i>\$517.75</i> |
| EW MonitorPLS NBDOnsite-H30725 | 97411-H30725 | \$ 1,976.00 | 10% | <i>\$1,791.74</i> |
| EW MonitorPLS NBDOnsite-H30726 | 97411-H30726 | \$ 8,840.00 | 10% | <i>\$8,015.67</i> |

| | | | | |
|--------------------------------|--------------|--------------|-----|-------------|
| EW MonitorPLS NBDOnsite-H30727 | 97411-H30727 | \$ 9,381.00 | 10% | \$8,506.22 |
| EW MonitorPLS NBDOnsite-H30730 | 97411-H30730 | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS NBDOnsite-H30731 | 97411-H30731 | \$ 275.00 | 10% | \$249.36 |
| EW MonitorPLS NBDOnsite-H30733 | 97411-H30733 | \$ 8,323.00 | 10% | \$7,546.88 |
| EW MonitorPLS NBDOnsite-H30734 | 97411-H30734 | \$ 6,402.00 | 10% | \$5,805.01 |
| EW MonitorPLS NBDOnsite-H30735 | 97411-H30735 | \$ 7,412.00 | 10% | \$6,720.83 |
| EW MonitorPLS NBDOnsite-H30736 | 97411-H30736 | \$ 1,370.00 | 10% | \$1,242.25 |
| EW MonitorPLS NBDOnsite-H30738 | 97411-H30738 | \$ 249.00 | 10% | \$225.78 |
| EW MonitorPLS NBDOnsite H31337 | 97411-H31337 | \$ 9,570.00 | 10% | \$8,677.60 |
| EW MonitorPLS NBDOnsite H31338 | 97411-H31338 | \$ 9,570.00 | 10% | \$8,677.60 |
| EW MonitorPLS NBDOnsite H31341 | 97411-H31341 | \$ 5,139.00 | 10% | \$4,659.79 |
| EW MonitorPLS NBDOnsite H31342 | 97411-H31342 | \$ 1,477.00 | 10% | \$1,339.27 |
| EW MonitorPLS NBDOnsite H31343 | 97411-H31343 | \$ 2,072.00 | 10% | \$1,878.79 |
| EW MonitorPLS NBDOnsite H31344 | 97411-H31344 | \$ 2,072.00 | 10% | \$1,878.79 |
| EW MonitorPLS NBDOnsite H31345 | 97411-H31345 | \$ 2,072.00 | 10% | \$1,878.79 |
| EW MonitorPLS NBDOnsite H31346 | 97411-H31346 | \$ 2,072.00 | 10% | \$1,878.79 |
| EW MonitorPLS NBDOnsite H31362 | 97411-H31362 | \$ 23,722.00 | 10% | \$21,509.92 |
| EW MonitorPLS NBDOnsite H31363 | 97411-H31363 | \$ 23,722.00 | 10% | \$21,509.92 |
| EW MonitorPLS NBDOnsite H31364 | 97411-H31364 | \$ 8,752.00 | 10% | \$7,935.88 |
| EW MonitorPLS NBDOnsite H31365 | 97411-H31365 | \$ 8,752.00 | 10% | \$7,935.88 |
| EW MonitorPLS NBDOnsite H31366 | 97411-H31366 | \$ 12,123.00 | 10% | \$10,992.53 |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS NBDOnsite H31367 | 97411-H31367 | \$ 12,123.00 | 10% | <i>\$10,992.53</i> |
| EW MonitorPLS 4HROnsite H32010 | 97411-H32010 | \$ 1,087.00 | 10% | <i>\$985.64</i> |
| EW MonitorPLS 4HROnsite H32011 | 97411-H32011 | \$ 1,087.00 | 10% | <i>\$985.64</i> |
| EW MonitorPLS 4HROnsite H32012 | 97411-H32012 | \$ 3,053.00 | 10% | <i>\$2,768.31</i> |
| EW MonitorPLS 4HROnsite H32013 | 97411-H32013 | \$ 3,053.00 | 10% | <i>\$2,768.31</i> |
| EW MonitorPLS 4HROnsite H32014 | 97411-H32014 | \$ 3,053.00 | 10% | <i>\$2,768.31</i> |
| EW MonitorPLS 4HROnsite H32015 | 97411-H32015 | \$ 3,053.00 | 10% | <i>\$2,768.31</i> |
| EW MonitorPLS 4HROnsite H32016 | 97411-H32016 | \$ 2,762.00 | 10% | <i>\$2,504.44</i> |
| EW MonitorPLS 4HROnsite H32017 | 97411-H32017 | \$ 2,762.00 | 10% | <i>\$2,504.44</i> |
| EW MonitorPLS 4HROnsite H32018 | 97411-H32018 | \$ 2,762.00 | 10% | <i>\$2,504.44</i> |
| EW MonitorPLS 4HROnsite H32019 | 97411-H32019 | \$ 2,762.00 | 10% | <i>\$2,504.44</i> |
| EW MonitorPLS 4HROnsite H32020 | 97411-H32020 | \$ 24,379.00 | 10% | <i>\$22,105.66</i> |
| EW MonitorPLS 4HROnsite H32021 | 97411-H32021 | \$ 24,379.00 | 10% | <i>\$22,105.66</i> |
| EW MonitorPLS 4HROnsite H32022 | 97411-H32022 | \$ 24,379.00 | 10% | <i>\$22,105.66</i> |
| EW MonitorPLS 4HROnsite H32023 | 97411-H32023 | \$ 24,379.00 | 10% | <i>\$22,105.66</i> |
| EW MonitorPLS 4HROnsite H32028 | 97411-H32028 | \$ 45,943.00 | 10% | <i>\$41,658.82</i> |
| EW MonitorPLS 4HROnsite H32029 | 97411-H32029 | \$ 45,943.00 | 10% | <i>\$41,658.82</i> |
| EW MonitorPLS 4HROnsite H32030 | 97411-H32030 | \$ 48,182.00 | 10% | <i>\$43,689.03</i> |
| EW MonitorPLS 4HROnsite H32031 | 97411-H32031 | \$ 48,182.00 | 10% | <i>\$43,689.03</i> |
| EW MonitorPLS 4HROnsite H32032 | 97411-H32032 | \$ 48,182.00 | 10% | <i>\$43,689.03</i> |
| EW MonitorPLS 4HROnsite H32033 | 97411-H32033 | \$ 48,182.00 | 10% | <i>\$43,689.03</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32038 | 97411-H32038 | \$ 8,947.00 | 10% | <i>\$8,112.69</i> |
| EW MonitorPLS 4HROnsite H32039 | 97411-H32039 | \$ 8,947.00 | 10% | <i>\$8,112.69</i> |
| EW MonitorPLS 4HROnsite H32040 | 97411-H32040 | \$ 8,947.00 | 10% | <i>\$8,112.69</i> |
| EW MonitorPLS 4HROnsite H32041 | 97411-H32041 | \$ 8,947.00 | 10% | <i>\$8,112.69</i> |
| EW MonitorPLS 4HROnsite H32046 | 97411-H32046 | \$ 12,393.00 | 10% | <i>\$11,237.35</i> |
| EW MonitorPLS 4HROnsite H32047 | 97411-H32047 | \$ 12,393.00 | 10% | <i>\$11,237.35</i> |
| EW MonitorPLS 4HROnsite H32048 | 97411-H32048 | \$ 12,393.00 | 10% | <i>\$11,237.35</i> |
| EW MonitorPLS 4HROnsite H32049 | 97411-H32049 | \$ 12,393.00 | 10% | <i>\$11,237.35</i> |
| EW MonitorPLS 4HROnsite H32054 | 97411-H32054 | \$ 8,947.00 | 10% | <i>\$8,112.69</i> |
| EW MonitorPLS 4HROnsite H32055 | 97411-H32055 | \$ 12,393.00 | 10% | <i>\$11,237.35</i> |
| EW MonitorPLS 4HROnsite H32056 | 97411-H32056 | \$ 3,572.00 | 10% | <i>\$3,238.91</i> |
| EW MonitorPLS 4HROnsite H32057 | 97411-H32057 | \$ 3,679.00 | 10% | <i>\$3,335.93</i> |
| EW MonitorPLS 4HROnsite H32058 | 97411-H32058 | \$ 3,679.00 | 10% | <i>\$3,335.93</i> |
| EW MonitorPLS 4HROnsite H32059 | 97411-H32059 | \$ 3,679.00 | 10% | <i>\$3,335.93</i> |
| EW MonitorPLS 4HROnsite H32060 | 97411-H32060 | \$ 3,516.00 | 10% | <i>\$3,188.13</i> |
| EW MonitorPLS 4HROnsite H32061 | 97411-H32061 | \$ 3,692.00 | 10% | <i>\$3,347.72</i> |
| EW MonitorPLS 4HROnsite H32062 | 97411-H32062 | \$ 3,550.00 | 10% | <i>\$3,218.96</i> |
| EW MonitorPLS 4HROnsite H32063 | 97411-H32063 | \$ 3,521.00 | 10% | <i>\$3,192.67</i> |
| EW MonitorPLS 4HROnsite H32064 | 97411-H32064 | \$ 3,550.00 | 10% | <i>\$3,218.96</i> |
| EW MonitorPLS 4HROnsite H32065 | 97411-H32065 | \$ 3,893.00 | 10% | <i>\$3,529.98</i> |
| EW MonitorPLS 4HROnsite H32066 | 97411-H32066 | \$ 3,893.00 | 10% | <i>\$3,529.98</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|-------------|
| EW MonitorPLS 4HROnsite H32067 | 97411-H32067 | \$ 3,893.00 | 10% | \$3,529.98 |
| EW MonitorPLS 4HROnsite H32068 | 97411-H32068 | \$ 3,893.00 | 10% | \$3,529.98 |
| EW MonitorPLS 4HROnsite H32069 | 97411-H32069 | \$ 4,632.00 | 10% | \$4,200.07 |
| EW MonitorPLS 4HROnsite H32070 | 97411-H32070 | \$ 4,632.00 | 10% | \$4,200.07 |
| EW MonitorPLS 4HROnsite H32071 | 97411-H32071 | \$ 4,632.00 | 10% | \$4,200.07 |
| EW MonitorPLS 4HROnsite H32072 | 97411-H32072 | \$ 4,632.00 | 10% | \$4,200.07 |
| EW MonitorPLS 4HROnsite H32073 | 97411-H32073 | \$ 29,826.00 | 10% | \$27,044.73 |
| EW MonitorPLS 4HROnsite H32074 | 97411-H32074 | \$ 29,824.00 | 10% | \$27,042.91 |
| EW MonitorPLS 4HROnsite H32075 | 97411-H32075 | \$ 40,553.00 | 10% | \$36,771.43 |
| EW MonitorPLS 4HROnsite H32076 | 97411-H32076 | \$ 40,553.00 | 10% | \$36,771.43 |
| EW MonitorPLS 4HROnsite H32101 | 97411-H32101 | \$ 2,112.00 | 10% | \$1,915.06 |
| EW MonitorPLS 4HROnsite H32102 | 97411-H32102 | \$ 2,112.00 | 10% | \$1,915.06 |
| EW MonitorPLS 4HROnsite H32103 | 97411-H32103 | \$ 2,112.00 | 10% | \$1,915.06 |
| EW MonitorPLS 4HROnsite H32104 | 97411-H32104 | \$ 2,112.00 | 10% | \$1,915.06 |
| EW MonitorPLS 4HROnsite H32105 | 97411-H32105 | \$ 3,344.00 | 10% | \$3,032.17 |
| EW MonitorPLS 4HROnsite H32106 | 97411-H32106 | \$ 3,344.00 | 10% | \$3,032.17 |
| EW MonitorPLS 4HROnsite H32107 | 97411-H32107 | \$ 7,574.00 | 10% | \$6,867.72 |
| EW MonitorPLS 4HROnsite H32108 | 97411-H32108 | \$ 7,574.00 | 10% | \$6,867.72 |
| EW MonitorPLS 4HROnsite H32109 | 97411-H32109 | \$ 3,344.00 | 10% | \$3,032.17 |
| EW MonitorPLS 4HROnsite H32110 | 97411-H32110 | \$ 3,344.00 | 10% | \$3,032.17 |
| EW MonitorPLS 4HROnsite H32111 | 97411-H32111 | \$ 2,112.00 | 10% | \$1,915.06 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS 4HROnsite H32112 | 97411-H32112 | \$ 2,112.00 | 10% | <i>\$1,915.06</i> |
| EW MonitorPLS 4HROnsite H32113 | 97411-H32113 | \$ 2,112.00 | 10% | <i>\$1,915.06</i> |
| EW MonitorPLS 4HROnsite H32114 | 97411-H32114 | \$ 2,112.00 | 10% | <i>\$1,915.06</i> |
| EW MonitorPLS 4HROnsite H32115 | 97411-H32115 | \$ 3,344.00 | 10% | <i>\$3,032.17</i> |
| EW MonitorPLS 4HROnsite H32116 | 97411-H32116 | \$ 3,344.00 | 10% | <i>\$3,032.17</i> |
| EW MonitorPLS 4HROnsite H32117 | 97411-H32117 | \$ 2,031.00 | 10% | <i>\$1,841.61</i> |
| EW MonitorPLS 4HROnsite H32118 | 97411-H32118 | \$ 2,031.00 | 10% | <i>\$1,841.61</i> |
| EW MonitorPLS 4HROnsite H32119 | 97411-H32119 | \$ 2,031.00 | 10% | <i>\$1,841.61</i> |
| EW MonitorPLS 4HROnsite H32120 | 97411-H32120 | \$ 2,031.00 | 10% | <i>\$1,841.61</i> |
| EW MonitorPLS 4HROnsite H32121 | 97411-H32121 | \$ 7,574.00 | 10% | <i>\$6,867.72</i> |
| EW MonitorPLS 4HROnsite H32122 | 97411-H32122 | \$ 7,574.00 | 10% | <i>\$6,867.72</i> |
| EW MonitorPLS 4HROnsite H32123 | 97411-H32123 | \$ 3,344.00 | 10% | <i>\$3,032.17</i> |
| EW MonitorPLS 4HROnsite H32124 | 97411-H32124 | \$ 3,344.00 | 10% | <i>\$3,032.17</i> |
| EW MonitorPLS 4HROnsite H32125 | 97411-H32125 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32126 | 97411-H32126 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32127 | 97411-H32127 | \$ 3,691.00 | 10% | <i>\$3,346.81</i> |
| EW MonitorPLS 4HROnsite H32128 | 97411-H32128 | \$ 3,691.00 | 10% | <i>\$3,346.81</i> |
| EW MonitorPLS 4HROnsite H32129 | 97411-H32129 | \$ 3,691.00 | 10% | <i>\$3,346.81</i> |
| EW MonitorPLS 4HROnsite H32130 | 97411-H32130 | \$ 3,691.00 | 10% | <i>\$3,346.81</i> |
| EW MonitorPLS 4HROnsite H32131 | 97411-H32131 | \$ 3,691.00 | 10% | <i>\$3,346.81</i> |
| EW MonitorPLS 4HROnsite H32132 | 97411-H32132 | \$ 3,691.00 | 10% | <i>\$3,346.81</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32133 | 97411-H32133 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32134 | 97411-H32134 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32135 | 97411-H32135 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32136 | 97411-H32136 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32137 | 97411-H32137 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32138 | 97411-H32138 | \$ 3,258.00 | 10% | <i>\$2,954.19</i> |
| EW MonitorPLS 4HROnsite H32139 | 97411-H32139 | \$ 12,576.00 | 10% | <i>\$11,403.29</i> |
| EW MonitorPLS 4HROnsite H32140 | 97411-H32140 | \$ 12,576.00 | 10% | <i>\$11,403.29</i> |
| EW MonitorPLS 4HROnsite H32141 | 97411-H32141 | \$ 14,882.00 | 10% | <i>\$13,494.25</i> |
| EW MonitorPLS 4HROnsite H32142 | 97411-H32142 | \$ 14,882.00 | 10% | <i>\$13,494.25</i> |
| EW MonitorPLS 4HROnsite H32146 | 97411-H32146 | \$ 2,001.00 | 10% | <i>\$1,814.41</i> |
| EW MonitorPLS 4HROnsite H32147 | 97411-H32147 | \$ 2,001.00 | 10% | <i>\$1,814.41</i> |
| EW MonitorPLS 4HROnsite H32148 | 97411-H32148 | \$ 3,167.00 | 10% | <i>\$2,871.68</i> |
| EW MonitorPLS 4HROnsite H32149 | 97411-H32149 | \$ 3,167.00 | 10% | <i>\$2,871.68</i> |
| EW MonitorPLS 4HROnsite H32150 | 97411-H32150 | \$ 2,001.00 | 10% | <i>\$1,814.41</i> |
| EW MonitorPLS 4HROnsite H32169 | 97411-H32169 | \$ 2,137.00 | 10% | <i>\$1,937.72</i> |
| EW MonitorPLS 4HROnsite H32170 | 97411-H32170 | \$ 2,137.00 | 10% | <i>\$1,937.72</i> |
| EW MonitorPLS 4HROnsite H32171 | 97411-H32171 | \$ 2,055.00 | 10% | <i>\$1,863.37</i> |
| EW MonitorPLS 4HROnsite H32172 | 97411-H32172 | \$ 2,055.00 | 10% | <i>\$1,863.37</i> |
| EW MonitorPLS 4HROnsite H32173 | 97411-H32173 | \$ 4,015.00 | 10% | <i>\$3,640.60</i> |
| EW MonitorPLS 4HROnsite H32174 | 97411-H32174 | \$ 4,015.00 | 10% | <i>\$3,640.60</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS 4HROnsite H32175 | 97411-H32175 | \$ 3,544.00 | 10% | <i>\$3,213.52</i> |
| EW MonitorPLS 4HROnsite H32176 | 97411-H32176 | \$ 3,544.00 | 10% | <i>\$3,213.52</i> |
| EW MonitorPLS 4HROnsite H32177 | 97411-H32177 | \$ 14,087.00 | 10% | <i>\$12,773.39</i> |
| EW MonitorPLS 4HROnsite H32178 | 97411-H32178 | \$ 16,672.00 | 10% | <i>\$15,117.34</i> |
| EW MonitorPLS NBDOnsite H34008 | 97411-H34008 | \$ 724.00 | 10% | <i>\$656.49</i> |
| EW MonitorPLS NBDOnsite H34009 | 97411-H34009 | \$ 792.00 | 10% | <i>\$718.15</i> |
| EW MonitorPLS NBDOnsite H34010 | 97411-H34010 | \$ 686.00 | 10% | <i>\$622.03</i> |
| EW MonitorPLS NBDOnsite H34011 | 97411-H34011 | \$ 777.00 | 10% | <i>\$704.54</i> |
| EW MonitorPLS NBDOnsite H34012 | 97411-H34012 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS NBDOnsite H34013 | 97411-H34013 | \$ 750.00 | 10% | <i>\$680.06</i> |
| EW MonitorPLS NBDOnsite H34014 | 97411-H34014 | \$ 792.00 | 10% | <i>\$718.15</i> |
| EW MonitorPLS NBDOnsite H34015 | 97411-H34015 | \$ 697.00 | 10% | <i>\$632.00</i> |
| EW MonitorPLS NBDOnsite H34016 | 97411-H34016 | \$ 802.00 | 10% | <i>\$727.21</i> |
| EW MonitorPLS NBDOnsite H34017 | 97411-H34017 | \$ 884.00 | 10% | <i>\$801.57</i> |
| EW MonitorPLS NBDOnsite H34018 | 97411-H34018 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW MonitorPLS NBDOnsite H34019 | 97411-H34019 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW MonitorPLS NBDOnsite H34020 | 97411-H34020 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW MonitorPLS NBDOnsite H34021 | 97411-H34021 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW MonitorPLS NBDOnsite H34048 | 97411-H34048 | \$ 1,019.00 | 10% | <i>\$923.98</i> |
| EW MonitorPLS NBDOnsite H34049 | 97411-H34049 | \$ 1,019.00 | 10% | <i>\$923.98</i> |
| EW MonitorPLS NBDOnsite H34050 | 97411-H34050 | \$ 934.00 | 10% | <i>\$846.90</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H34051 | 97411-H34051 | \$ 934.00 | 10% | <i>\$846.90</i> |
| EW MonitorPLS NBDOnsite H34052 | 97411-H34052 | \$ 1,077.00 | 10% | <i>\$976.57</i> |
| EW MonitorPLS NBDOnsite H34053 | 97411-H34053 | \$ 1,077.00 | 10% | <i>\$976.57</i> |
| EW MonitorPLS NBDOnsite H34054 | 97411-H34054 | \$ 979.00 | 10% | <i>\$887.71</i> |
| EW MonitorPLS NBDOnsite H34055 | 97411-H34055 | \$ 979.00 | 10% | <i>\$887.71</i> |
| EW MonitorPLS NBDOnsite H34056 | 97411-H34056 | \$ 1,175.00 | 10% | <i>\$1,065.43</i> |
| EW MonitorPLS NBDOnsite H34057 | 97411-H34057 | \$ 1,175.00 | 10% | <i>\$1,065.43</i> |
| EW MonitorPLS NBDOnsite H34058 | 97411-H34058 | \$ 1,111.00 | 10% | <i>\$1,007.40</i> |
| EW MonitorPLS NBDOnsite H34059 | 97411-H34059 | \$ 1,111.00 | 10% | <i>\$1,007.40</i> |
| EW MonitorPLS NBDOnsite H34062 | 97411-H34062 | \$ 1,175.00 | 10% | <i>\$1,065.43</i> |
| EW MonitorPLS NBDOnsite H34063 | 97411-H34063 | \$ 1,175.00 | 10% | <i>\$1,065.43</i> |
| EW MonitorPLS NBDOnsite H34064 | 97411-H34064 | \$ 939.00 | 10% | <i>\$851.44</i> |
| EW MonitorPLS NBDOnsite H34065 | 97411-H34065 | \$ 939.00 | 10% | <i>\$851.44</i> |
| EW MonitorPLS NBDOnsite H34066 | 97411-H34066 | \$ 939.00 | 10% | <i>\$851.44</i> |
| EW MonitorPLS NBDOnsite H34067 | 97411-H34067 | \$ 939.00 | 10% | <i>\$851.44</i> |
| EW MonitorPLS NBDOnsite H34068 | 97411-H34068 | \$ 939.00 | 10% | <i>\$851.44</i> |
| EW MonitorPLS NBDOnsite H34069 | 97411-H34069 | \$ 911.00 | 10% | <i>\$826.05</i> |
| EW MonitorPLS NBDOnsite H34070 | 97411-H34070 | \$ 939.00 | 10% | <i>\$851.44</i> |
| EW MonitorPLS NBDOnsite H34071 | 97411-H34071 | \$ 939.00 | 10% | <i>\$851.44</i> |
| EW MonitorPLS NBDOnsite H34072 | 97411-H34072 | \$ 3,004.00 | 10% | <i>\$2,723.88</i> |
| EW MonitorPLS NBDOnsite H34073 | 97411-H34073 | \$ 2,947.00 | 10% | <i>\$2,672.19</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite H34074 | 97411-H34074 | \$ 3,698.00 | 10% | \$3,353.16 |
| EW MonitorPLS NBDOnsite H34075 | 97411-H34075 | \$ 3,574.00 | 10% | \$3,240.72 |
| EW MonitorPLS NBDOnsite H34076 | 97411-H34076 | \$ 3,004.00 | 10% | \$2,723.88 |
| EW MonitorPLS NBDOnsite H34077 | 97411-H34077 | \$ 2,947.00 | 10% | \$2,672.19 |
| EW MonitorPLS NBDOnsite H34078 | 97411-H34078 | \$ 3,004.00 | 10% | \$2,723.88 |
| EW MonitorPLS NBDOnsite H34079 | 97411-H34079 | \$ 2,947.00 | 10% | \$2,672.19 |
| EW MonitorPLS NBDOnsite H34080 | 97411-H34080 | \$ 3,698.00 | 10% | \$3,353.16 |
| EW MonitorPLS NBDOnsite H34081 | 97411-H34081 | \$ 3,574.00 | 10% | \$3,240.72 |
| EW MonitorPLS NBDOnsite H34082 | 97411-H34082 | \$ 3,547.00 | 10% | \$3,216.24 |
| EW MonitorPLS NBDOnsite H34083 | 97411-H34083 | \$ 3,428.00 | 10% | \$3,108.34 |
| EW MonitorPLS NBDOnsite H34084 | 97411-H34084 | \$ 2,689.00 | 10% | \$2,438.25 |
| EW MonitorPLS NBDOnsite H34085 | 97411-H34085 | \$ 2,689.00 | 10% | \$2,438.25 |
| EW MonitorPLS NBDOnsite H34086 | 97411-H34086 | \$ 3,131.00 | 10% | \$2,839.03 |
| EW MonitorPLS NBDOnsite H34087 | 97411-H34087 | \$ 3,003.00 | 10% | \$2,722.97 |
| EW MonitorPLS NBDOnsite H34088 | 97411-H34088 | \$ 5,888.00 | 10% | \$5,338.94 |
| EW MonitorPLS NBDOnsite H34089 | 97411-H34089 | \$ 5,888.00 | 10% | \$5,338.94 |
| EW MonitorPLS NBDOnsite H34090 | 97411-H34090 | \$ 6,783.00 | 10% | \$6,150.49 |
| EW MonitorPLS NBDOnsite H34091 | 97411-H34091 | \$ 5,504.00 | 10% | \$4,990.75 |
| EW MonitorPLS NBDOnsite H34092 | 97411-H34092 | \$ 5,504.00 | 10% | \$4,990.75 |
| EW MonitorPLS NBDOnsite H34093 | 97411-H34093 | \$ 5,504.00 | 10% | \$4,990.75 |
| EW MonitorPLS NBDOnsite H34094 | 97411-H34094 | \$ 655.00 | 10% | \$593.92 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite H34095 | 97411-H34095 | \$ 655.00 | 10% | \$593.92 |
| EW MonitorPLS NBDOnsite H34096 | 97411-H34096 | \$ 707.00 | 10% | \$641.07 |
| EW MonitorPLS NBDOnsite H34097 | 97411-H34097 | \$ 707.00 | 10% | \$641.07 |
| EW MonitorPLS NBDOnsite H34098 | 97411-H34098 | \$ 655.00 | 10% | \$593.92 |
| EW MonitorPLS NBDOnsite H34099 | 97411-H34099 | \$ 655.00 | 10% | \$593.92 |
| EW MonitorPLS NBDOnsite H34100 | 97411-H34100 | \$ 655.00 | 10% | \$593.92 |
| EW MonitorPLS NBDOnsite H34101 | 97411-H34101 | \$ 655.00 | 10% | \$593.92 |
| EW MonitorPLS NBDOnsite H34102 | 97411-H34102 | \$ 655.00 | 10% | \$593.92 |
| EW MonitorPLS NBDOnsite H34103 | 97411-H34103 | \$ 655.00 | 10% | \$593.92 |
| EW MonitorPLS NBDOnsite H34104 | 97411-H34104 | \$ 427.00 | 10% | \$387.18 |
| EW MonitorPLS NBDOnsite H34105 | 97411-H34105 | \$ 427.00 | 10% | \$387.18 |
| EW MonitorPLS NBDOnsite H34106 | 97411-H34106 | \$ 427.00 | 10% | \$387.18 |
| EW MonitorPLS NBDOnsite H34107 | 97411-H34107 | \$ 427.00 | 10% | \$387.18 |
| EW MonitorPLS NBDOnsite H34108 | 97411-H34108 | \$ 427.00 | 10% | \$387.18 |
| EW MonitorPLS NBDOnsite H34109 | 97411-H34109 | \$ 427.00 | 10% | \$387.18 |
| EW MonitorPLS NBDOnsite H34110 | 97411-H34110 | \$ 5,303.00 | 10% | \$4,808.50 |
| EW MonitorPLS NBDOnsite H34111 | 97411-H34111 | \$ 5,303.00 | 10% | \$4,808.50 |
| EW MonitorPLS NBDOnsite H34112 | 97411-H34112 | \$ 5,303.00 | 10% | \$4,808.50 |
| EW MonitorPLS NBDOnsite H34114 | 97411-H34114 | \$ 7,799.00 | 10% | \$7,071.74 |
| EW MonitorPLS NBDOnsite H34115 | 97411-H34115 | \$ 7,559.00 | 10% | \$6,854.12 |
| EW MonitorPLS NBDOnsite H34116 | 97411-H34116 | \$ 7,559.00 | 10% | \$6,854.12 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H34117 | 97411-H34117 | \$ 7,799.00 | 10% | <i>\$7,071.74</i> |
| EW MonitorPLS NBDOnsite H34118 | 97411-H34118 | \$ 1,366.00 | 10% | <i>\$1,238.62</i> |
| EW MonitorPLS NBDOnsite H34119 | 97411-H34119 | \$ 1,366.00 | 10% | <i>\$1,238.62</i> |
| EW MonitorPLS NBDOnsite H34120 | 97411-H34120 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS NBDOnsite H34121 | 97411-H34121 | \$ 1,014.00 | 10% | <i>\$919.44</i> |
| EW MonitorPLS NBDOnsite H34122 | 97411-H34122 | \$ 1,047.00 | 10% | <i>\$949.37</i> |
| EW MonitorPLS NBDOnsite H34123 | 97411-H34123 | \$ 1,047.00 | 10% | <i>\$949.37</i> |
| EW MonitorPLS NBDOnsite H34124 | 97411-H34124 | \$ 1,441.00 | 10% | <i>\$1,306.63</i> |
| EW MonitorPLS NBDOnsite H34125 | 97411-H34125 | \$ 1,441.00 | 10% | <i>\$1,306.63</i> |
| EW MonitorPLS NBDOnsite H34126 | 97411-H34126 | \$ 1,441.00 | 10% | <i>\$1,306.63</i> |
| EW MonitorPLS NBDOnsite H34127 | 97411-H34127 | \$ 1,441.00 | 10% | <i>\$1,306.63</i> |
| EW MonitorPLS NBDOnsite H34129 | 97411-H34129 | \$ 1,008.00 | 10% | <i>\$914.00</i> |
| EW MonitorPLS NBDOnsite H34130 | 97411-H34130 | \$ 1,047.00 | 10% | <i>\$949.37</i> |
| EW MonitorPLS NBDOnsite H34131 | 97411-H34131 | \$ 1,042.00 | 10% | <i>\$944.83</i> |
| EW MonitorPLS NBDOnsite H34132 | 97411-H34132 | \$ 1,047.00 | 10% | <i>\$949.37</i> |
| EW MonitorPLS NBDOnsite H34172 | 97411-H34172 | \$ 2,489.00 | 10% | <i>\$2,256.90</i> |
| EW MonitorPLS NBDOnsite H34174 | 97411-H34174 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34175 | 97411-H34175 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34176 | 97411-H34176 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34177 | 97411-H34177 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34178 | 97411-H34178 | \$ 238.00 | 10% | <i>\$215.81</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34179 | 97411-H34179 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34180 | 97411-H34180 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34181 | 97411-H34181 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34182 | 97411-H34182 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34183 | 97411-H34183 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34184 | 97411-H34184 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34185 | 97411-H34185 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34186 | 97411-H34186 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34187 | 97411-H34187 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34188 | 97411-H34188 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34189 | 97411-H34189 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34190 | 97411-H34190 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34191 | 97411-H34191 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34192 | 97411-H34192 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34193 | 97411-H34193 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34194 | 97411-H34194 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34195 | 97411-H34195 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34196 | 97411-H34196 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34197 | 97411-H34197 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34198 | 97411-H34198 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34199 | 97411-H34199 | \$ 238.00 | 10% | <i>\$215.81</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34200 | 97411-H34200 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34201 | 97411-H34201 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34202 | 97411-H34202 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34203 | 97411-H34203 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34204 | 97411-H34204 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34205 | 97411-H34205 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34206 | 97411-H34206 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34207 | 97411-H34207 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34208 | 97411-H34208 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34209 | 97411-H34209 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34210 | 97411-H34210 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34211 | 97411-H34211 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34212 | 97411-H34212 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34213 | 97411-H34213 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34214 | 97411-H34214 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34215 | 97411-H34215 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34216 | 97411-H34216 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34217 | 97411-H34217 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34218 | 97411-H34218 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34219 | 97411-H34219 | \$ 238.00 | 10% | <i>\$215.81</i> |
| EW MonitorPLS NBDOnsite H34220 | 97411-H34220 | \$ 253.00 | 10% | <i>\$229.41</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34221 | 97411-H34221 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34222 | 97411-H34222 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34223 | 97411-H34223 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34224 | 97411-H34224 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34225 | 97411-H34225 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34226 | 97411-H34226 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34227 | 97411-H34227 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34228 | 97411-H34228 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34229 | 97411-H34229 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34230 | 97411-H34230 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34231 | 97411-H34231 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34232 | 97411-H34232 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34233 | 97411-H34233 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34234 | 97411-H34234 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34235 | 97411-H34235 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34236 | 97411-H34236 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34237 | 97411-H34237 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34238 | 97411-H34238 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34239 | 97411-H34239 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34240 | 97411-H34240 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34241 | 97411-H34241 | \$ 253.00 | 10% | \$229.41 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34242 | 97411-H34242 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34243 | 97411-H34243 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34244 | 97411-H34244 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34245 | 97411-H34245 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34246 | 97411-H34246 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34247 | 97411-H34247 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34248 | 97411-H34248 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34249 | 97411-H34249 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34250 | 97411-H34250 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34251 | 97411-H34251 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34252 | 97411-H34252 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34253 | 97411-H34253 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34254 | 97411-H34254 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34255 | 97411-H34255 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34256 | 97411-H34256 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34257 | 97411-H34257 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34258 | 97411-H34258 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34259 | 97411-H34259 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34260 | 97411-H34260 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34261 | 97411-H34261 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34262 | 97411-H34262 | \$ 253.00 | 10% | \$229.41 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34263 | 97411-H34263 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34264 | 97411-H34264 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34265 | 97411-H34265 | \$ 253.00 | 10% | \$229.41 |
| EW MonitorPLS NBDOnsite H34266 | 97411-H34266 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34267 | 97411-H34267 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34268 | 97411-H34268 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34269 | 97411-H34269 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34270 | 97411-H34270 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34271 | 97411-H34271 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34272 | 97411-H34272 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34273 | 97411-H34273 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34274 | 97411-H34274 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34275 | 97411-H34275 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34276 | 97411-H34276 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34277 | 97411-H34277 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34278 | 97411-H34278 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34279 | 97411-H34279 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34280 | 97411-H34280 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34281 | 97411-H34281 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34282 | 97411-H34282 | \$ 232.00 | 10% | \$210.37 |
| EW MonitorPLS NBDOnsite H34283 | 97411-H34283 | \$ 232.00 | 10% | \$210.37 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34284 | 97411-H34284 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34285 | 97411-H34285 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34286 | 97411-H34286 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34287 | 97411-H34287 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34288 | 97411-H34288 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34289 | 97411-H34289 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34290 | 97411-H34290 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34291 | 97411-H34291 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34292 | 97411-H34292 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34293 | 97411-H34293 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34294 | 97411-H34294 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34295 | 97411-H34295 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34296 | 97411-H34296 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34297 | 97411-H34297 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34298 | 97411-H34298 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34299 | 97411-H34299 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34300 | 97411-H34300 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34301 | 97411-H34301 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34302 | 97411-H34302 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34303 | 97411-H34303 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34304 | 97411-H34304 | \$ 232.00 | 10% | <i>\$210.37</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34305 | 97411-H34305 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H34306 | 97411-H34306 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34307 | 97411-H34307 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34308 | 97411-H34308 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34309 | 97411-H34309 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34310 | 97411-H34310 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34311 | 97411-H34311 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34312 | 97411-H34312 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34313 | 97411-H34313 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34314 | 97411-H34314 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34315 | 97411-H34315 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34316 | 97411-H34316 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34317 | 97411-H34317 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34318 | 97411-H34318 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34319 | 97411-H34319 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34320 | 97411-H34320 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34321 | 97411-H34321 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34322 | 97411-H34322 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34323 | 97411-H34323 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34324 | 97411-H34324 | \$ 260.00 | 10% | <i>\$235.76</i> |
| EW MonitorPLS NBDOnsite H34325 | 97411-H34325 | \$ 260.00 | 10% | <i>\$235.76</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34326 | 97411-H34326 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34327 | 97411-H34327 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34328 | 97411-H34328 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34329 | 97411-H34329 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34330 | 97411-H34330 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34331 | 97411-H34331 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34332 | 97411-H34332 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34333 | 97411-H34333 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34334 | 97411-H34334 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34335 | 97411-H34335 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34336 | 97411-H34336 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34337 | 97411-H34337 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34338 | 97411-H34338 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34339 | 97411-H34339 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34340 | 97411-H34340 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34341 | 97411-H34341 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34342 | 97411-H34342 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34343 | 97411-H34343 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34344 | 97411-H34344 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34345 | 97411-H34345 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34346 | 97411-H34346 | \$ 260.00 | 10% | \$235.76 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34347 | 97411-H34347 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34348 | 97411-H34348 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34349 | 97411-H34349 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34350 | 97411-H34350 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34351 | 97411-H34351 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34352 | 97411-H34352 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34353 | 97411-H34353 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34354 | 97411-H34354 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34355 | 97411-H34355 | \$ 260.00 | 10% | \$235.76 |
| EW MonitorPLS NBDOnsite H34403 | 97411-H34403 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34404 | 97411-H34404 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34405 | 97411-H34405 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34406 | 97411-H34406 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34407 | 97411-H34407 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34408 | 97411-H34408 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34409 | 97411-H34409 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34410 | 97411-H34410 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34411 | 97411-H34411 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34412 | 97411-H34412 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34413 | 97411-H34413 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34414 | 97411-H34414 | \$ 363.00 | 10% | \$329.15 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34415 | 97411-H34415 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34416 | 97411-H34416 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34417 | 97411-H34417 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34418 | 97411-H34418 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34419 | 97411-H34419 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34420 | 97411-H34420 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34421 | 97411-H34421 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34422 | 97411-H34422 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34423 | 97411-H34423 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34424 | 97411-H34424 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34425 | 97411-H34425 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34426 | 97411-H34426 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34427 | 97411-H34427 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34428 | 97411-H34428 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34429 | 97411-H34429 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34430 | 97411-H34430 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34431 | 97411-H34431 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34432 | 97411-H34432 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34433 | 97411-H34433 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34434 | 97411-H34434 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34435 | 97411-H34435 | \$ 363.00 | 10% | \$329.15 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34436 | 97411-H34436 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34437 | 97411-H34437 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34438 | 97411-H34438 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34439 | 97411-H34439 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34440 | 97411-H34440 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34441 | 97411-H34441 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34442 | 97411-H34442 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34443 | 97411-H34443 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34444 | 97411-H34444 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34445 | 97411-H34445 | \$ 363.00 | 10% | \$329.15 |
| EW MonitorPLS NBDOnsite H34446 | 97411-H34446 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34447 | 97411-H34447 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34448 | 97411-H34448 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34449 | 97411-H34449 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34450 | 97411-H34450 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34451 | 97411-H34451 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34452 | 97411-H34452 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34453 | 97411-H34453 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34454 | 97411-H34454 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34455 | 97411-H34455 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34456 | 97411-H34456 | \$ 393.00 | 10% | \$356.35 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34457 | 97411-H34457 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34458 | 97411-H34458 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34459 | 97411-H34459 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34460 | 97411-H34460 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34461 | 97411-H34461 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34462 | 97411-H34462 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34463 | 97411-H34463 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34464 | 97411-H34464 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34465 | 97411-H34465 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34466 | 97411-H34466 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34467 | 97411-H34467 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34468 | 97411-H34468 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34469 | 97411-H34469 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34470 | 97411-H34470 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34471 | 97411-H34471 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34472 | 97411-H34472 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34473 | 97411-H34473 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34474 | 97411-H34474 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34475 | 97411-H34475 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34476 | 97411-H34476 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34477 | 97411-H34477 | \$ 393.00 | 10% | \$356.35 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34478 | 97411-H34478 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34479 | 97411-H34479 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34480 | 97411-H34480 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34481 | 97411-H34481 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34482 | 97411-H34482 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34483 | 97411-H34483 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34484 | 97411-H34484 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34485 | 97411-H34485 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34486 | 97411-H34486 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34487 | 97411-H34487 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34488 | 97411-H34488 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34489 | 97411-H34489 | \$ 393.00 | 10% | \$356.35 |
| EW MonitorPLS NBDOnsite H34490 | 97411-H34490 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34491 | 97411-H34491 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34492 | 97411-H34492 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34493 | 97411-H34493 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34494 | 97411-H34494 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34495 | 97411-H34495 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34496 | 97411-H34496 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34497 | 97411-H34497 | \$ 217.00 | 10% | \$196.76 |
| EW MonitorPLS NBDOnsite H34498 | 97411-H34498 | \$ 217.00 | 10% | \$196.76 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34499 | 97411-H34499 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34500 | 97411-H34500 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34501 | 97411-H34501 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34502 | 97411-H34502 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34503 | 97411-H34503 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34504 | 97411-H34504 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34505 | 97411-H34505 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34506 | 97411-H34506 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34507 | 97411-H34507 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34508 | 97411-H34508 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34509 | 97411-H34509 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34510 | 97411-H34510 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34511 | 97411-H34511 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34512 | 97411-H34512 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34513 | 97411-H34513 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34514 | 97411-H34514 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34515 | 97411-H34515 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34516 | 97411-H34516 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34517 | 97411-H34517 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34518 | 97411-H34518 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34519 | 97411-H34519 | \$ 217.00 | 10% | <i>\$196.76</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34520 | 97411-H34520 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34521 | 97411-H34521 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34522 | 97411-H34522 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34523 | 97411-H34523 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34524 | 97411-H34524 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34525 | 97411-H34525 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34526 | 97411-H34526 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34527 | 97411-H34527 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34528 | 97411-H34528 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34529 | 97411-H34529 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34530 | 97411-H34530 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34531 | 97411-H34531 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34532 | 97411-H34532 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34533 | 97411-H34533 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34534 | 97411-H34534 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34535 | 97411-H34535 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34536 | 97411-H34536 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34537 | 97411-H34537 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34538 | 97411-H34538 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34539 | 97411-H34539 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34540 | 97411-H34540 | \$ 217.00 | 10% | <i>\$196.76</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34541 | 97411-H34541 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34542 | 97411-H34542 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34543 | 97411-H34543 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34544 | 97411-H34544 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34545 | 97411-H34545 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34546 | 97411-H34546 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34547 | 97411-H34547 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34548 | 97411-H34548 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34549 | 97411-H34549 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34550 | 97411-H34550 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34551 | 97411-H34551 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34552 | 97411-H34552 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34553 | 97411-H34553 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34554 | 97411-H34554 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34555 | 97411-H34555 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34556 | 97411-H34556 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34557 | 97411-H34557 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34558 | 97411-H34558 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34559 | 97411-H34559 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34560 | 97411-H34560 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34561 | 97411-H34561 | \$ 217.00 | 10% | <i>\$196.76</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34562 | 97411-H34562 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34563 | 97411-H34563 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34564 | 97411-H34564 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34565 | 97411-H34565 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34566 | 97411-H34566 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34567 | 97411-H34567 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34568 | 97411-H34568 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34569 | 97411-H34569 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34570 | 97411-H34570 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34571 | 97411-H34571 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34572 | 97411-H34572 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34573 | 97411-H34573 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34574 | 97411-H34574 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34575 | 97411-H34575 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34576 | 97411-H34576 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34577 | 97411-H34577 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34578 | 97411-H34578 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34579 | 97411-H34579 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34580 | 97411-H34580 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34581 | 97411-H34581 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34582 | 97411-H34582 | \$ 217.00 | 10% | <i>\$196.76</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34583 | 97411-H34583 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34584 | 97411-H34584 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34585 | 97411-H34585 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34586 | 97411-H34586 | \$ 217.00 | 10% | <i>\$196.76</i> |
| EW MonitorPLS NBDOnsite H34587 | 97411-H34587 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34588 | 97411-H34588 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34589 | 97411-H34589 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34590 | 97411-H34590 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34591 | 97411-H34591 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34592 | 97411-H34592 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34593 | 97411-H34593 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34594 | 97411-H34594 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34595 | 97411-H34595 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34596 | 97411-H34596 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34597 | 97411-H34597 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34598 | 97411-H34598 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34599 | 97411-H34599 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34600 | 97411-H34600 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34601 | 97411-H34601 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34602 | 97411-H34602 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34603 | 97411-H34603 | \$ 268.00 | 10% | <i>\$243.01</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34604 | 97411-H34604 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34605 | 97411-H34605 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34606 | 97411-H34606 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34607 | 97411-H34607 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34608 | 97411-H34608 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34609 | 97411-H34609 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34610 | 97411-H34610 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34611 | 97411-H34611 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34612 | 97411-H34612 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34613 | 97411-H34613 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34614 | 97411-H34614 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34615 | 97411-H34615 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34616 | 97411-H34616 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34617 | 97411-H34617 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34618 | 97411-H34618 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34619 | 97411-H34619 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34620 | 97411-H34620 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34621 | 97411-H34621 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34622 | 97411-H34622 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34623 | 97411-H34623 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34624 | 97411-H34624 | \$ 268.00 | 10% | <i>\$243.01</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW MonitorPLS NBDOnsite H34625 | 97411-H34625 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34626 | 97411-H34626 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34627 | 97411-H34627 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34628 | 97411-H34628 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34629 | 97411-H34629 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34630 | 97411-H34630 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34631 | 97411-H34631 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H34632 | 97411-H34632 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34633 | 97411-H34633 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34634 | 97411-H34634 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34635 | 97411-H34635 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34636 | 97411-H34636 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34637 | 97411-H34637 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34638 | 97411-H34638 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34639 | 97411-H34639 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34640 | 97411-H34640 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34641 | 97411-H34641 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34642 | 97411-H34642 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34643 | 97411-H34643 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34644 | 97411-H34644 | \$ 272.00 | 10% | <i>\$246.64</i> |
| EW MonitorPLS NBDOnsite H34645 | 97411-H34645 | \$ 272.00 | 10% | <i>\$246.64</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW MonitorPLS NBDOnsite H34646 | 97411-H34646 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34647 | 97411-H34647 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34648 | 97411-H34648 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34649 | 97411-H34649 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34650 | 97411-H34650 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34651 | 97411-H34651 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34652 | 97411-H34652 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34653 | 97411-H34653 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34654 | 97411-H34654 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34655 | 97411-H34655 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34656 | 97411-H34656 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34657 | 97411-H34657 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34658 | 97411-H34658 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34659 | 97411-H34659 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34660 | 97411-H34660 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34661 | 97411-H34661 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34662 | 97411-H34662 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34663 | 97411-H34663 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34664 | 97411-H34664 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34665 | 97411-H34665 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34666 | 97411-H34666 | \$ 272.00 | 10% | \$246.64 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite H34667 | 97411-H34667 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34668 | 97411-H34668 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34669 | 97411-H34669 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34670 | 97411-H34670 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34671 | 97411-H34671 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34672 | 97411-H34672 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34673 | 97411-H34673 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34674 | 97411-H34674 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34675 | 97411-H34675 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34676 | 97411-H34676 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34677 | 97411-H34677 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34678 | 97411-H34678 | \$ 272.00 | 10% | \$246.64 |
| EW MonitorPLS NBDOnsite H34726 | 97411-H34726 | \$ 3,143.00 | 10% | \$2,849.92 |
| EW MonitorPLS NBDOnsite H34727 | 97411-H34727 | \$ 3,143.00 | 10% | \$2,849.92 |
| EW MonitorPLS NBDOnsite H34728 | 97411-H34728 | \$ 3,143.00 | 10% | \$2,849.92 |
| EW MonitorPLS NBDOnsite H34729 | 97411-H34729 | \$ 3,143.00 | 10% | \$2,849.92 |
| EW MonitorPLS NBDOnsite H34730 | 97411-H34730 | \$ 3,320.00 | 10% | \$3,010.41 |
| EW MonitorPLS NBDOnsite H34731 | 97411-H34731 | \$ 3,320.00 | 10% | \$3,010.41 |
| EW MonitorPLS NBDOnsite H34732 | 97411-H34732 | \$ 3,320.00 | 10% | \$3,010.41 |
| EW MonitorPLS NBDOnsite H34733 | 97411-H34733 | \$ 3,320.00 | 10% | \$3,010.41 |
| EW MonitorPLS NBDOnsite H34734 | 97411-H34734 | \$ 1,093.00 | 10% | \$991.08 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H34735 | 97411-H34735 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLS NBDOnsite H34736 | 97411-H34736 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H34737 | 97411-H34737 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H34738 | 97411-H34738 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34739 | 97411-H34739 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34740 | 97411-H34740 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLS NBDOnsite H34741 | 97411-H34741 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLS NBDOnsite H34742 | 97411-H34742 | \$ 1,008.00 | 10% | <i>\$914.00</i> |
| EW MonitorPLS NBDOnsite H34743 | 97411-H34743 | \$ 1,008.00 | 10% | <i>\$914.00</i> |
| EW MonitorPLS NBDOnsite H34744 | 97411-H34744 | \$ 1,192.00 | 10% | <i>\$1,080.85</i> |
| EW MonitorPLS NBDOnsite H34745 | 97411-H34745 | \$ 1,192.00 | 10% | <i>\$1,080.85</i> |
| EW MonitorPLS NBDOnsite H34746 | 97411-H34746 | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW MonitorPLS NBDOnsite H34747 | 97411-H34747 | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW MonitorPLS NBDOnsite H34748 | 97411-H34748 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34749 | 97411-H34749 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34750 | 97411-H34750 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34751 | 97411-H34751 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34752 | 97411-H34752 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34753 | 97411-H34753 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34754 | 97411-H34754 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW MonitorPLS NBDOnsite H34755 | 97411-H34755 | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW MonitorPLS NBDOnsite H34756 | 97411-H34756 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H34757 | 97411-H34757 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H34758 | 97411-H34758 | \$ 1,192.00 | 10% | <i>\$1,080.85</i> |
| EW MonitorPLS NBDOnsite H34759 | 97411-H34759 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H34760 | 97411-H34760 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H34761 | 97411-H34761 | \$ 1,192.00 | 10% | <i>\$1,080.85</i> |
| EW MonitorPLS NBDOnsite H34993 | 97411-H34993 | \$ 15,243.00 | 10% | <i>\$13,821.59</i> |
| EW MonitorPLS NBDOnsite H34994 | 97411-H34994 | \$ 15,243.00 | 10% | <i>\$13,821.59</i> |
| EW MonitorPLS NBDOnsite H34996 | 97411-H34996 | \$ 15,243.00 | 10% | <i>\$13,821.59</i> |
| EW MonitorPLS NBDOnsite H34997 | 97411-H34997 | \$ 15,243.00 | 10% | <i>\$13,821.59</i> |
| EW MonitorPLS NBDOnsite H35005 | 97411-H35005 | \$ 11,193.00 | 10% | <i>\$10,149.25</i> |
| EW MonitorPLS NBDOnsite H35006 | 97411-H35006 | \$ 11,193.00 | 10% | <i>\$10,149.25</i> |
| EW MonitorPLS NBDOnsite H35012 | 97411-H35012 | \$ 7,134.00 | 10% | <i>\$6,468.75</i> |
| EW MonitorPLS NBDOnsite H35070 | 97411-H35070 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35071 | 97411-H35071 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35072 | 97411-H35072 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35073 | 97411-H35073 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35074 | 97411-H35074 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35075 | 97411-H35075 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35076 | 97411-H35076 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35077 | 97411-H35077 | \$ 232.00 | 10% | <i>\$210.37</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H35078 | 97411-H35078 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35079 | 97411-H35079 | \$ 232.00 | 10% | <i>\$210.37</i> |
| EW MonitorPLS NBDOnsite H35080 | 97411-H35080 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H35081 | 97411-H35081 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H35082 | 97411-H35082 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H35083 | 97411-H35083 | \$ 268.00 | 10% | <i>\$243.01</i> |
| EW MonitorPLS NBDOnsite H35270 | 97411-H35270 | \$ 1,077.00 | 10% | <i>\$976.57</i> |
| EW MonitorPLS NBDOnsite H35271 | 97411-H35271 | \$ 979.00 | 10% | <i>\$887.71</i> |
| EW MonitorPLS NBDOnsite H35272 | 97411-H35272 | \$ 878.00 | 10% | <i>\$796.13</i> |
| EW MonitorPLS NBDOnsite H35273 | 97411-H35273 | \$ 878.00 | 10% | <i>\$796.13</i> |
| EW MonitorPLS NBDOnsite H35274 | 97411-H35274 | \$ 1,259.00 | 10% | <i>\$1,141.60</i> |
| EW MonitorPLS NBDOnsite H35275 | 97411-H35275 | \$ 1,175.00 | 10% | <i>\$1,065.43</i> |
| EW MonitorPLS NBDOnsite H35276 | 97411-H35276 | \$ 3,004.00 | 10% | <i>\$2,723.88</i> |
| EW MonitorPLS NBDOnsite H3527 | 97411-H35277 | \$ 3,547.00 | 10% | <i>\$3,216.24</i> |
| EW MonitorPLS NBDOnsite H35278 | 97411-H35278 | \$ 2,689.00 | 10% | <i>\$2,438.25</i> |
| EW MonitorPLS NBDOnsite H35279 | 97411-H35279 | \$ 3,003.00 | 10% | <i>\$2,722.97</i> |
| EW MonitorPLS NBDOnsite H35280 | 97411-H35280 | \$ 5,201.00 | 10% | <i>\$4,716.01</i> |
| EW MonitorPLS NBDOnsite H35292 | 97411-H35292 | \$ 2,689.00 | 10% | <i>\$2,438.25</i> |
| EW MonitorPLS NBDOnsite H35293 | 97411-H35293 | \$ 3,003.00 | 10% | <i>\$2,722.97</i> |
| EW MonitorPLS NBDOnsite H35295 | 97411-H35295 | \$ 960.00 | 10% | <i>\$870.48</i> |
| EW MonitorPLS NBDOnsite H35302 | 97411-H35302 | \$ 3,111.00 | 10% | <i>\$2,820.90</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H35303 | 97411-H35303 | \$ 3,111.00 | 10% | <i>\$2,820.90</i> |
| EW MonitorPLS NBDOnsite H35304 | 97411-H35304 | \$ 3,111.00 | 10% | <i>\$2,820.90</i> |
| EW MonitorPLS NBDOnsite H35305 | 97411-H35305 | \$ 3,224.00 | 10% | <i>\$2,923.36</i> |
| EW MonitorPLS NBDOnsite H35306 | 97411-H35306 | \$ 3,224.00 | 10% | <i>\$2,923.36</i> |
| EW MonitorPLS NBDOnsite H35307 | 97411-H35307 | \$ 3,224.00 | 10% | <i>\$2,923.36</i> |
| EW MonitorPLS NBDOnsite H35309 | 97411-H35309 | \$ 3,662.00 | 10% | <i>\$3,320.52</i> |
| EW MonitorPLS NBDOnsite H35310 | 97411-H35310 | \$ 3,662.00 | 10% | <i>\$3,320.52</i> |
| EW MonitorPLS NBDOnsite H35311 | 97411-H35311 | \$ 3,662.00 | 10% | <i>\$3,320.52</i> |
| EW MonitorPLS NBDOnsite H35312 | 97411-H35312 | \$ 3,026.00 | 10% | <i>\$2,743.83</i> |
| EW MonitorPLS NBDOnsite H35313 | 97411-H35313 | \$ 3,026.00 | 10% | <i>\$2,743.83</i> |
| EW MonitorPLS NBDOnsite H35314 | 97411-H35314 | \$ 3,026.00 | 10% | <i>\$2,743.83</i> |
| EW MonitorPLS NBDOnsite H35315 | 97411-H35315 | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW MonitorPLS NBDOnsite H35318 | 97411-H35318 | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |
| EW MonitorPLS NBDOnsite H35319 | 97411-H35319 | \$ 1,280.00 | 10% | <i>\$1,160.64</i> |
| EW MonitorPLS NBDOnsite H35320 | 97411-H35320 | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS NBDOnsite H35321 | 97411-H35321 | \$ 1,509.00 | 10% | <i>\$1,368.29</i> |
| EW MonitorPLS NBDOnsite H35322 | 97411-H35322 | \$ 1,737.00 | 10% | <i>\$1,575.02</i> |
| EW MonitorPLS NBDOnsite H35323 | 97411-H35323 | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW MonitorPLS NBDOnsite H35328 | 97411-H35328 | \$ 504.00 | 10% | <i>\$457.00</i> |
| EW MonitorPLS NBDOnsite H35330 | 97411-H35330 | \$ 680.00 | 10% | <i>\$616.59</i> |
| EW MonitorPLS NBDOnsite H35340 | 97411-H35340 | \$ 3,500.00 | 10% | <i>\$3,173.63</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H35341 | 97411-H35341 | \$ 3,500.00 | 10% | <i>\$3,173.63</i> |
| EW MonitorPLS NBDOnsite H35342 | 97411-H35342 | \$ 2,985.00 | 10% | <i>\$2,706.65</i> |
| EW MonitorPLS NBDOnsite H35343 | 97411-H35343 | \$ 3,500.00 | 10% | <i>\$3,173.63</i> |
| EW MonitorPLS NBDOnsite H35344 | 97411-H35344 | \$ 3,611.00 | 10% | <i>\$3,274.27</i> |
| EW MonitorPLS NBDOnsite H35345 | 97411-H35345 | \$ 3,611.00 | 10% | <i>\$3,274.27</i> |
| EW MonitorPLS NBDOnsite H35346 | 97411-H35346 | \$ 3,073.00 | 10% | <i>\$2,786.44</i> |
| EW MonitorPLS NBDOnsite H35347 | 97411-H35347 | \$ 3,611.00 | 10% | <i>\$3,274.27</i> |
| EW MonitorPLS NBDOnsite H35349 | 97411-H35349 | \$ 3,900.00 | 10% | <i>\$3,536.33</i> |
| EW MonitorPLS NBDOnsite H35350 | 97411-H35350 | \$ 3,900.00 | 10% | <i>\$3,536.33</i> |
| EW MonitorPLS NBDOnsite H35351 | 97411-H35351 | \$ 3,302.00 | 10% | <i>\$2,994.09</i> |
| EW MonitorPLS NBDOnsite H35352 | 97411-H35352 | \$ 3,900.00 | 10% | <i>\$3,536.33</i> |
| EW MonitorPLS NBDOnsite H35359 | 97411-H35359 | \$ 1,509.00 | 10% | <i>\$1,368.29</i> |
| EW MonitorPLS NBDOnsite H35360 | 97411-H35360 | \$ 1,737.00 | 10% | <i>\$1,575.02</i> |
| EW MonitorPLS NBDOnsite H35361 | 97411-H35361 | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW MonitorPLS NBDOnsite H35362 | 97411-H35362 | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |
| EW MonitorPLS NBDOnsite H35366 | 97411-H35366 | \$ 1,428.00 | 10% | <i>\$1,294.84</i> |
| EW MonitorPLS NBDOnsite H35367 | 97411-H35367 | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW MonitorPLS NBDOnsite H35368 | 97411-H35368 | \$ 2,534.00 | 10% | <i>\$2,297.70</i> |
| EW MonitorPLS NBDOnsite H35369 | 97411-H35369 | \$ 828.00 | 10% | <i>\$750.79</i> |
| EW MonitorPLS NBDOnsite H35370 | 97411-H35370 | \$ 1,159.00 | 10% | <i>\$1,050.92</i> |
| EW MonitorPLS NBDOnsite H35375 | 97411-H35375 | \$ 916.00 | 10% | <i>\$830.58</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H35376 | 97411-H35376 | \$ 1,367.00 | 10% | <i>\$1,239.53</i> |
| EW MonitorPLS NBDOnsite H35377 | 97411-H35377 | \$ 573.00 | 10% | <i>\$519.57</i> |
| EW MonitorPLS NBDOnsite H35378 | 97411-H35378 | \$ 916.00 | 10% | <i>\$830.58</i> |
| EW MonitorPLS NBDOnsite H35379 | 97411-H35379 | \$ 573.00 | 10% | <i>\$519.57</i> |
| EW MonitorPLS NBDOnsite H35380 | 97411-H35380 | \$ 1,023.00 | 10% | <i>\$927.61</i> |
| EW MonitorPLS NBDOnsite H35381 | 97411-H35381 | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW MonitorPLS NBDOnsite H35384 | 97411-H35384 | \$ 464.00 | 10% | <i>\$420.73</i> |
| EW MonitorPLS NBDOnsite H35385 | 97411-H35385 | \$ 616.00 | 10% | <i>\$558.56</i> |
| EW MonitorPLS NBDOnsite H35386 | 97411-H35386 | \$ 1,023.00 | 10% | <i>\$927.61</i> |
| EW MonitorPLS NBDOnsite H35387 | 97411-H35387 | \$ 959.00 | 10% | <i>\$869.57</i> |
| EW MonitorPLS NBDOnsite H35388 | 97411-H35388 | \$ 707.00 | 10% | <i>\$641.07</i> |
| EW MonitorPLS NBDOnsite H35389 | 97411-H35389 | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW MonitorPLS NBDOnsite H35390 | 97411-H35390 | \$ 345.00 | 10% | <i>\$312.83</i> |
| EW MonitorPLS NBDOnsite H35391 | 97411-H35391 | \$ 756.00 | 10% | <i>\$685.50</i> |
| EW MonitorPLS NBDOnsite H35392 | 97411-H35392 | \$ 1,151.00 | 10% | <i>\$1,043.67</i> |
| EW MonitorPLS NBDOnsite H35393 | 97411-H35393 | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW MonitorPLS NBDOnsite H35394 | 97411-H35394 | \$ 280.00 | 10% | <i>\$253.89</i> |
| EW MonitorPLS NBDOnsite H35395 | 97411-H35395 | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite H35396 | 97411-H35396 | \$ 280.00 | 10% | <i>\$253.89</i> |
| EW MonitorPLS NBDOnsite H35397 | 97411-H35397 | \$ 235.00 | 10% | <i>\$213.09</i> |
| EW MonitorPLS NBDOnsite H35398 | 97411-H35398 | \$ 718.00 | 10% | <i>\$651.05</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|------------|
| EW MonitorPLS NBDOnsite H35399 | 97411-H35399 | \$ 870.00 | 10% | \$788.87 |
| EW MonitorPLS NBDOnsite H35400 | 97411-H35400 | \$ 961.00 | 10% | \$871.39 |
| EW MonitorPLS NBDOnsite H35401 | 97411-H35401 | \$ 515.00 | 10% | \$466.98 |
| EW MonitorPLS NBDOnsite H35415 | 97411-H35415 | \$ 314.00 | 10% | \$284.72 |
| EW MonitorPLS NBDOnsite H35416 | 97411-H35416 | \$ 314.00 | 10% | \$284.72 |
| EW MonitorPLS NBDOnsite H35426 | 97411-H35426 | \$ 399.00 | 10% | \$361.79 |
| EW MonitorPLS NBDOnsite H35427 | 97411-H35427 | \$ 959.00 | 10% | \$869.57 |
| EW MonitorPLS NBDOnsite H35428 | 97411-H35428 | \$ 345.00 | 10% | \$312.83 |
| EW MonitorPLS NBDOnsite H35429 | 97411-H35429 | \$ 756.00 | 10% | \$685.50 |
| EW MonitorPLS NBDOnsite H35430 | 97411-H35430 | \$ 1,062.00 | 10% | \$962.97 |
| EW MonitorPLS NBDOnsite H35431 | 97411-H35431 | \$ 1,062.00 | 10% | \$962.97 |
| EW MonitorPLS NBDOnsite H35432 | 97411-H35432 | \$ 1,008.00 | 10% | \$914.00 |
| EW MonitorPLS NBDOnsite H35433 | 97411-H35433 | \$ 1,162.00 | 10% | \$1,053.64 |
| EW MonitorPLS NBDOnsite H35434 | 97411-H35434 | \$ 1,222.00 | 10% | \$1,108.05 |
| EW MonitorPLS NBDOnsite H35435 | 97411-H35435 | \$ 1,222.00 | 10% | \$1,108.05 |
| EW MonitorPLS NBDOnsite H35436 | 97411-H35436 | \$ 1,580.00 | 10% | \$1,432.67 |
| EW MonitorPLS NBDOnsite H35437 | 97411-H35437 | \$ 1,580.00 | 10% | \$1,432.67 |
| EW MonitorPLS NBDOnsite H35438 | 97411-H35438 | \$ 1,580.00 | 10% | \$1,432.67 |
| EW MonitorPLS NBDOnsite H35439 | 97411-H35439 | \$ 1,580.00 | 10% | \$1,432.67 |
| EW MonitorPLS NBDOnsite H35440 | 97411-H35440 | \$ 1,162.00 | 10% | \$1,053.64 |
| EW MonitorPLS NBDOnsite H35441 | 97411-H35441 | \$ 1,162.00 | 10% | \$1,053.64 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite H35442 | 97411-H35442 | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW MonitorPLS NBDOnsite H35443 | 97411-H35443 | \$ 3,143.00 | 10% | <i>\$2,849.92</i> |
| EW MonitorPLS NBDOnsite H35444 | 97411-H35444 | \$ 3,320.00 | 10% | <i>\$3,010.41</i> |
| EW MonitorPLS NBDOnsite H35445 | 97411-H35445 | \$ 3,004.00 | 10% | <i>\$2,723.88</i> |
| EW MonitorPLS NBDOnsite H35446 | 97411-H35446 | \$ 2,947.00 | 10% | <i>\$2,672.19</i> |
| EW MonitorPLS NBDOnsite H35447 | 97411-H35447 | \$ 3,362.00 | 10% | <i>\$3,048.49</i> |
| EW MonitorPLS NBDOnsite H35448 | 97411-H35448 | \$ 3,249.00 | 10% | <i>\$2,946.03</i> |
| EW MonitorPLS NBDOnsite H35449 | 97411-H35449 | \$ 2,689.00 | 10% | <i>\$2,438.25</i> |
| EW MonitorPLS NBDOnsite H35450 | 97411-H35450 | \$ 2,846.00 | 10% | <i>\$2,580.61</i> |
| EW MonitorPLS NBDOnsite H35451 | 97411-H35451 | \$ 5,504.00 | 10% | <i>\$4,990.75</i> |
| EW MonitorPLS NBDOnsite H35452 | 97411-H35452 | \$ 5,504.00 | 10% | <i>\$4,990.75</i> |
| EW MonitorPLS NBDOnsite H35453 | 97411-H35453 | \$ 3,320.00 | 10% | <i>\$3,010.41</i> |
| EW MonitorPLS NBDOnsite H35454 | 97411-H35454 | \$ 3,143.00 | 10% | <i>\$2,849.92</i> |
| EW MonitorPLS NBDOnsite H35455 | 97411-H35455 | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS NBDOnsite H35456 | 97411-H35456 | \$ 1,500.00 | 10% | <i>\$1,360.13</i> |
| EW MonitorPLS NBDOnsite H35457 | 97411-H35457 | \$ 1,415.00 | 10% | <i>\$1,283.05</i> |
| EW MonitorPLS NBDOnsite H35458 | 97411-H35458 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW MonitorPLS NBDOnsite H35471 | 97411-H35471 | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS NBDOnsite H35600 | 97411-H35600 | \$ 878.00 | 10% | <i>\$796.13</i> |
| EW MonitorPLS NBDOnsite H35601 | 97411-H35601 | \$ 878.00 | 10% | <i>\$796.13</i> |
| EW MonitorPLS NBDOnsite H35602 | 97411-H35602 | \$ 1,093.00 | 10% | <i>\$991.08</i> |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EW MonitorPLS NBDOnsite H35603 | 97411-H35603 | \$ 1,093.00 | 10% | <i>\$991.08</i> |
| EW MonitorPLS NBDOnsite H35604 | 97411-H35604 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H35605 | 97411-H35605 | \$ 1,197.00 | 10% | <i>\$1,085.38</i> |
| EW MonitorPLS NBDOnsite H35606 | 97411-H35606 | \$ 1,259.00 | 10% | <i>\$1,141.60</i> |
| EW MonitorPLS NBDOnsite H35607 | 97411-H35607 | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW MonitorPLS NBDOnsite ISW-24W-4X | 97411-ISW- 24W-4X | \$ 1,257.00 | 10% | <i>\$1,139.78</i> |
| EW MonitorPLS NBDOnsite ISW-4W-4WS-4X | 97411-ISW-4W- 4WS-4X | \$ 967.00 | 10% | <i>\$876.83</i> |
| EW MonitorPLUS NBDOnsite- MS128 | 97411- MSM128 | \$ 2,886.00 | 10% | <i>\$2,616.88</i> |
| EW MonitorPLS NBDOnsite- MSM48C | 97411- MSM48C | \$ 1,911.00 | 10% | <i>\$1,732.80</i> |
| EW MonitorPLS NBDOnsit SLX9150-48XT-DC-F | 97411- SLX9150- 48XT-DC-F | \$ 3,149.00 | 10% | <i>\$2,855.36</i> |
| EW MonitorPLS NBDOnsit SLX9150-48XT-DC-R | 97411- SLX9150- 48XT-DC-R | \$ 3,439.00 | 10% | <i>\$3,118.31</i> |
| EW MonitorPLS NBDOnsite SLX9150-48Y-DC-F | 97411- SLX9150-48Y- DC-F | \$ 3,052.00 | 10% | <i>\$2,767.40</i> |
| EW MonitorPLS NBDOnsite SLX9150-48Y-DC-R | 97411- SLX9150-48Y- DC-R | \$ 3,333.00 | 10% | <i>\$3,022.20</i> |
| EW MonitorPLS NBDOnsite SLX9740-40C | 97411- SLX9740-40C | \$ 11,082.00 | 10% | <i>\$10,048.60</i> |
| EW MonitorPLS NBDOnsite SLX9740-40C-AC-F | 97411- SLX9740-40C- AC-F | \$ 11,082.00 | 10% | <i>\$10,048.60</i> |
| EW MonitorPLS NBDOnsite SLX9740-40C-AC-R | 97411- SLX9740-40C- AC-R | \$ 11,082.00 | 10% | <i>\$10,048.60</i> |
| EW MonitorPLS NBDOnsite SLX9740-40C-DC-F | 97411- SLX9740-40C- DC-F | \$ 11,082.00 | 10% | <i>\$10,048.60</i> |
| EW MonitorPLS NBDOnsite SLX9740-80C | 97411- SLX9740-80C | \$ 20,290.00 | 10% | <i>\$18,397.96</i> |

| | | | | |
|---|---|--------------|-----|--------------------|
| EW MonitorPLS NBDOnsite SLX9740-80C-AC-F | 97411- SLX9740-80C- AC-F | \$ 20,290.00 | 10% | <i>\$18,397.96</i> |
| EW MonitorPLS NBDOnsite SLX9740-80C-AC-R | 97411- SLX9740-80C- AC-R | \$ 20,290.00 | 10% | <i>\$18,397.96</i> |
| EW MonitorPLS NBDOnsite SLX9740-80C-DC-F | 97411- SLX9740-80C- DC-F | \$ 20,290.00 | 10% | <i>\$18,397.96</i> |
| EW MonitorPLS NBDOnsite V300-8P-2X | 97411-V300- 8P-2X | \$ 534.00 | 10% | <i>\$484.20</i> |
| EW MonitorPLS NBDOnsite V300-8T-2X | 97411-V300- 8T-2X | \$ 494.00 | 10% | <i>\$447.93</i> |
| EW MonitorPLS NBDOnsite V300HT-8P-2X | 97411-V300HT- 8P-2X | \$ 826.00 | 10% | <i>\$748.98</i> |
| EW MonitorPLS NBDOnsite V300HT-8T-2X | 97411-V300HT- 8T-2X | \$ 659.00 | 10% | <i>\$597.55</i> |
| EW MonitorPLS NBDOnsite- VIM-SS | 97411-VIM-SS | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW MonitorPLS NBDOnsiteVIMSSV8 | 97411-VIM- SSV80 | \$ 516.00 | 10% | <i>\$467.88</i> |
| EW MonitorPLS NBDOnsiteVIM2SS | 97411-VIM2- SS | \$ 405.00 | 10% | <i>\$367.23</i> |
| EW MonitorPLS NBDOnsiteVIM2SS | 97411-VIM2- SS128 | \$ 805.00 | 10% | <i>\$729.93</i> |
| EW MonitorPLS NBDOnsiteVIM2V80 | 97411-VIM2- V80 | \$ 859.00 | 10% | <i>\$778.90</i> |
| EW MonitorPLS NBDOnsiteVIM210 | 97411- VIM210G4X | \$ 1,282.00 | 10% | <i>\$1,162.45</i> |
| EW MonPLS NBDOnsit VSP4900-12MXU-12XE | 97411- VSP4900- 12MXU-12XE | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW MonPLS NBDOnsit VSP4900-12MXU-12XE-B1 | 97411- VSP4900- 12MXU-12XE- B1 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW MonitorPLS NBDOnsite VSP4900-24S | 97411- VSP4900-24S | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |
| EW MonitorPLS NBDOnsite VSP4900-24S-B3 | 97411- VSP4900-24S- B3 | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |

| | | | | |
|--|-------------------------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite VSP4900-24XE | 97411- VSP4900- 24XE | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW MonitorPLS NBDOnsite VSP4900-24XE-B3 | 97411- VSP4900- 24XE-B3 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW MonitorPLS NBDOnsite X435-24P-4S | 97411-X435- 24P-4S | \$ 634.00 | 10% | <i>\$574.88</i> |
| EW MonitorPLS NBDOnsite X435-24T-4S | 97411-X435- 24T-4S | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW MonitorPLS NBDOnsite X435-8P-2T-W | 97411-X435- 8P-2T-W | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW MonitorPLS NBDOnsite X435-8P-4S | 97411-X435- 8P-4S | \$ 520.00 | 10% | <i>\$471.51</i> |
| EW MonitorPLS NBDOnsite X435-8T-4S | 97411-X435- 8T-4S | \$ 498.00 | 10% | <i>\$451.56</i> |
| EW MonitorPLS NBDOnsite- X46024 | 97411-X460- 24P | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW MonitorPLS NBDOnsite- X46024 | 97411-X460- 24T | \$ 1,439.00 | 10% | <i>\$1,304.81</i> |
| EW MonitorPLS NBDOnsite- X46024 | 97411-X460- 24TDC | \$ 1,792.00 | 10% | <i>\$1,624.90</i> |
| EW MonitorPLS NBDOnsite- X46024 | 97411-X460- 24X | \$ 2,020.00 | 10% | <i>\$1,831.64</i> |
| EW MonitorPLS NBDOnsite- X46024 | 97411-X460- 24XDC | \$ 2,201.00 | 10% | <i>\$1,995.76</i> |
| EW MonitorPLS NBDOnsite- X46048 | 97411-X460- 48P | \$ 2,020.00 | 10% | <i>\$1,831.64</i> |
| EW MonitorPLS NBDOnsite- X46048 | 97411-X460- 48T | \$ 1,836.00 | 10% | <i>\$1,664.79</i> |
| EW MonitorPLS NBDOnsite- X46048 | 97411-X460- 48TDC | \$ 2,158.00 | 10% | <i>\$1,956.77</i> |
| EW MonitorPLS NBDOnsite- X46048 | 97411-X460- 48X | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW MonitorPLS NBDOnsite- X46048 | 97411-X460- 48XDC | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW MonitorPLS NBDOnsite X465-24MU | 97411-X465- 24MU | \$ 1,737.00 | 10% | <i>\$1,575.02</i> |
| EW MonitorPLS NBDOnsite X465-24S | 97411-X465- 24S | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |
| EW MonitorPLS NBDOnsite X465-24S-B3 | 97411-X465- 24S-B3 | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW MonitorPLS NBDOnsite X465-24W | 97411-X465- 24W | \$ 1,107.00 | 10% | <i>\$1,003.77</i> |
| EW MonitorPLS NBDOnsite X465-24XE | 97411-X465- 24XE | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW MonitorPLS NBDOnsite X465-24XE-B3 | 97411-X465- 24XE-B3 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW MonitorPLS NBDOnsite X465-48P | 97411-X465- 48P | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW MonitorPLS NBDOnsite X465-48T | 97411-X465- 48T | \$ 1,280.00 | 10% | <i>\$1,160.64</i> |
| EW MonitorPLS NBDOnsite X465-48W | 97411-X465- 48W | \$ 1,509.00 | 10% | <i>\$1,368.29</i> |
| EW MonitorPLS NBDOnsite X465i-48W | 97411-X465i- 48W | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW MonitorPLS NBDOnsite X465i-48W-B1-S1 | 97411-X465i- 48W-B1-S1 | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW MonitorPLS NBDOnsite X465i-48W-B2-S1 | 97411-X465i- 48W-B2-S1 | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW MonitorPLS NBDOnsite- X48024 | 97411-X480- 24X | \$ 2,213.00 | 10% | <i>\$2,006.64</i> |
| EW MonitorPLUS NBDOnsite- X480T | 97411-X480- 48T | \$ 1,982.00 | 10% | <i>\$1,797.18</i> |
| EW MonitorPLS NBDOnsite- X48048 | 97411-X480- 48X | \$ 2,729.00 | 10% | <i>\$2,474.52</i> |
| EW MonitorPLS NBDOnsite X695-48Y-8C | 97411-X695- 48Y-8C | \$ 3,047.00 | 10% | <i>\$2,762.87</i> |
| EW MonitorPLS NBDOnsite XA1440 | 97411-XA1440 | \$ 668.00 | 10% | <i>\$605.71</i> |
| EW MonitorPLS NBDOnsite XA1480 | 97411-XA1480 | \$ 761.00 | 10% | <i>\$690.04</i> |
| EW MonitorPLS NBDOnsiteXGM32SF | 97411-XGM3- 2SF | \$ 516.00 | 10% | <i>\$467.88</i> |
| EW MonitorPLS NBDOnsite XR600 | 97411-XR600 | \$ 718.00 | 10% | <i>\$651.05</i> |
| EW ResponsePLS NBD AHR 1130C | 97504-1130C | \$ 2,432.00 | 6% | <i>\$2,303.23</i> |
| EW ResponsePLS NBD AHR- 16119 | 97504-16119 | \$ 677.00 | 10% | <i>\$613.87</i> |
| EW ResponsePLS NBD AHR- 16120 | 97504-16120 | \$ 735.00 | 10% | <i>\$666.46</i> |
| EW ResponsePLS NBD AHR- 16126 | 97504-16126 | \$ 677.00 | 10% | <i>\$613.87</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-16127 | 97504-16127 | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW ResponsePLS NBD AHR-16172 | 97504-16172 | \$ 1,573.00 | 10% | <i>\$1,426.32</i> |
| EW ResponsePLS NBD AHR 16172T | 97504-16172T | \$ 1,676.00 | 10% | <i>\$1,519.71</i> |
| EW ResponsePLS NBD AHR-16173 | 97504-16173 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW ResponsePLS NBD AHR 16173T | 97504-16173T | \$ 1,692.00 | 10% | <i>\$1,534.22</i> |
| EW ResponsePLS NBD AHR-16174 | 97504-16174 | \$ 1,679.00 | 10% | <i>\$1,522.43</i> |
| EW ResponsePLS NBD AHR-16175 | 97504-16175 | \$ 1,751.00 | 10% | <i>\$1,587.72</i> |
| EW ResponsePLS NBD AHR-16176 | 97504-16176 | \$ 1,700.00 | 10% | <i>\$1,541.48</i> |
| EW ResponsePLS NBD AHR-16177 | 97504-16177 | \$ 1,597.00 | 10% | <i>\$1,448.08</i> |
| EW ResponsePLS NBD AHR 16177T | 97504-16177T | \$ 1,825.00 | 10% | <i>\$1,654.82</i> |
| EW ResponsePLS NBD AHR-16178 | 97504-16178 | \$ 1,861.00 | 10% | <i>\$1,687.46</i> |
| EW ResponsePLS NBD AHR-16179 | 97504-16179 | \$ 1,877.00 | 10% | <i>\$1,701.97</i> |
| EW ResponsePLS NBD AHR 16179T | 97504-16179T | \$ 2,003.00 | 10% | <i>\$1,816.22</i> |
| EW ResponsePLS NBD AHR-16301T | 97504-16301T | \$ 2,624.00 | 10% | <i>\$2,379.31</i> |
| EW ResponsePLS NBD AHR-16303T | 97504-16303T | \$ 2,624.00 | 10% | <i>\$2,379.31</i> |
| EW ResponsePLS NBD AHR-16304T | 97504-16304T | \$ 3,109.00 | 10% | <i>\$2,819.09</i> |
| EW ResponsePLS NBD AHR-16401T | 97504-16401T | \$ 1,997.00 | 10% | <i>\$1,810.78</i> |
| EW ResponsePLS NBD AHR-16402T | 97504-16402T | \$ 2,347.00 | 10% | <i>\$2,128.14</i> |
| EW ResponsePLS NBD AHR-16403T | 97504-16403T | \$ 2,231.00 | 10% | <i>\$2,022.96</i> |
| EW ResponsePLS NBD AHR-16404T | 97504-16404T | \$ 2,231.00 | 10% | <i>\$2,022.96</i> |
| EW ResponsePLS NBD AHR-16405T | 97504-16405T | \$ 2,526.00 | 10% | <i>\$2,290.45</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-16406T | 97504-16406T | \$ 2,928.00 | 10% | <i>\$2,654.96</i> |
| EW ResponsePLS NBD AHR-16431 | 97504-16431 | \$ 2,255.00 | 10% | <i>\$2,044.72</i> |
| EW ResponsePLS NBD AHR-16432 | 97504-16432 | \$ 2,357.00 | 10% | <i>\$2,137.21</i> |
| EW ResponsePLS NBD AHR-16440 | 97504-16440 | \$ 1,870.00 | 10% | <i>\$1,695.62</i> |
| EW ResponsePLS NBD AHR-16441 | 97504-16441 | \$ 1,808.00 | 10% | <i>\$1,639.40</i> |
| EW ResponsePLS NBD AHR-16442 | 97504-16442 | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW ResponsePLS NBD AHR-16444 | 97504-16444 | \$ 578.00 | 10% | <i>\$524.10</i> |
| EW ResponsePLS NBD AHR-16501 | 97504-16501 | \$ 1,453.00 | 10% | <i>\$1,317.51</i> |
| EW ResponsePLS NBD AHR-16501T | 97504-16501T | \$ 1,491.00 | 10% | <i>\$1,351.96</i> |
| EW ResponsePLS NBD AHR-16502 | 97504-16502 | \$ 1,520.00 | 10% | <i>\$1,378.26</i> |
| EW ResponsePLS NBD AHR-16502T | 97504-16502T | \$ 1,557.00 | 10% | <i>\$1,411.81</i> |
| EW ResponsePLS NBD AHR-16503 | 97504-16503 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsePLS NBD AHR-16503T | 97504-16503T | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW ResponsePLS NBD AHR-16504 | 97504-16504 | \$ 1,585.00 | 10% | <i>\$1,437.20</i> |
| EW ResponsePLS NBD AHR-16504T | 97504-16504T | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLS NBD AHR-16505 | 97504-16505 | \$ 1,592.00 | 10% | <i>\$1,443.55</i> |
| EW ResponsePLS NBD AHR-16505T | 97504-16505T | \$ 1,690.00 | 10% | <i>\$1,532.41</i> |
| EW ResponsePLS NBD AHR-16506 | 97504-16506 | \$ 1,757.00 | 10% | <i>\$1,593.16</i> |
| EW ResponsePLS NBD AHR-16506T | 97504-16506T | \$ 1,894.00 | 10% | <i>\$1,717.38</i> |
| EW ResponsePLS NBD AHR-16507 | 97504-16507 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW ResponsePLS NBD AHR-16507T | 97504-16507T | \$ 1,822.00 | 10% | <i>\$1,652.10</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-16508 | 97504-16508 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsePLS NBD AHR-16508T | 97504-16508T | \$ 1,953.00 | 10% | <i>\$1,770.88</i> |
| EW ResponsePLS NBD AHR-16509 | 97504-16509 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsePLS NBD AHR-16509T | 97504-16509T | \$ 1,953.00 | 10% | <i>\$1,770.88</i> |
| EW ResponsePLS NBD AHR-16510 | 97504-16510 | \$ 1,953.00 | 10% | <i>\$1,770.88</i> |
| EW ResponsePLS NBD AHR-16510T | 97504-16510T | \$ 2,078.00 | 10% | <i>\$1,884.23</i> |
| EW ResponsePLS NBD AHR-16513 | 97504-16513 | \$ 1,695.00 | 10% | <i>\$1,536.94</i> |
| EW ResponsePLS NBD AHR-16514 | 97504-16514 | \$ 1,915.00 | 10% | <i>\$1,736.43</i> |
| EW ResponsePLS NBD AHR-16515 | 97504-16515 | \$ 1,342.00 | 10% | <i>\$1,216.86</i> |
| EW ResponsePLS NBD AHR-16516 | 97504-16516 | \$ 1,348.00 | 10% | <i>\$1,222.30</i> |
| EW ResponsePLS NBD AHR-16517 | 97504-16517 | \$ 1,458.00 | 10% | <i>\$1,322.04</i> |
| EW ResponsePLS NBD AHR-16518 | 97504-16518 | \$ 1,436.00 | 10% | <i>\$1,302.09</i> |
| EW ResponsePLS NBD AHR-16519 | 97504-16519 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-16520 | 97504-16520 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLUS NBD AHR-16530 | 97504-16530 | \$ 1,491.00 | 10% | <i>\$1,351.96</i> |
| EW ResponsePLUS NBD AHR-16531 | 97504-16531 | \$ 1,537.00 | 10% | <i>\$1,393.67</i> |
| EW ResponsePLUS NBD AHR-16531T | 97504-16531T | \$ 1,519.00 | 10% | <i>\$1,377.35</i> |
| EW ResponsePLUS NBD AHR-16532 | 97504-16532 | \$ 1,537.00 | 10% | <i>\$1,393.67</i> |
| EW ResponsePLUS NBD AHR-16532T | 97504-16532T | \$ 1,519.00 | 10% | <i>\$1,377.35</i> |
| EW ResponsePLUS NBD AHR-16533 | 97504-16533 | \$ 1,605.00 | 10% | <i>\$1,455.33</i> |
| EW ResponsePLUS NBD AHR-16533T | 97504-16533T | \$ 1,605.00 | 10% | <i>\$1,455.33</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLUS NBD AHR-16534 | 97504-16534 | \$ 1,619.00 | 10% | <i>\$1,468.03</i> |
| EW ResponsePLUS NBD AHR-16535 | 97504-16535 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW ResponsePLUS NBD AHR-16535A | 97504-16535A | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW ResponsePLUS NBD AHR-16535T | 97504-16535T | \$ 1,770.00 | 10% | <i>\$1,604.95</i> |
| EW ResponsePLUS NBD AHR-16536 | 97504-16536 | \$ 1,418.00 | 10% | <i>\$1,285.77</i> |
| EW ResponsePLUS NBD AHR-16537 | 97504-16537 | \$ 1,479.00 | 10% | <i>\$1,341.08</i> |
| EW ResponsePLUS NBD AHR-16538 | 97504-16538 | \$ 1,528.00 | 10% | <i>\$1,385.51</i> |
| EW ResponsePLUS NBD AHR-16538T | 97504-16538T | \$ 1,694.00 | 10% | <i>\$1,536.03</i> |
| EW ResponsePLUS NBD AHR-16539 | 97504-16539 | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW ResponsePLUS NBD AHR-16540 | 97504-16540 | \$ 1,506.00 | 10% | <i>\$1,365.57</i> |
| EW ResponsePLUS NBD AHR-16541 | 97504-16541 | \$ 1,340.00 | 10% | <i>\$1,215.05</i> |
| EW ResponsePLS NBD AHR 16560 | 97504-16560 | \$ 1,246.00 | 10% | <i>\$1,129.81</i> |
| EW ResponsePLS NBD AHR 16561 | 97504-16561 | \$ 1,274.00 | 10% | <i>\$1,155.20</i> |
| EW ResponsePLS NBD AHR 16562 | 97504-16562 | \$ 1,295.00 | 10% | <i>\$1,174.24</i> |
| EW ResponsePLS NBD AHR 16563 | 97504-16563 | \$ 1,327.00 | 10% | <i>\$1,203.26</i> |
| EW ResponsePLS NBD AHR 16564 | 97504-16564 | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW ResponsePLS NBD AHR 16565 | 97504-16565 | \$ 1,450.00 | 10% | <i>\$1,314.79</i> |
| EW ResponsePLS NBD AHR 16566 | 97504-16566 | \$ 1,226.00 | 10% | <i>\$1,111.68</i> |
| EW ResponsePLS NBD AHR 16567 | 97504-16567 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW ResponsePLS NBD AHR 16568 | 97504-16568 | \$ 1,246.00 | 10% | <i>\$1,129.81</i> |
| EW ResponsePLS NBD AHR 16569 | 97504-16569 | \$ 1,281.00 | 10% | <i>\$1,161.55</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR 16570 | 97504-16570 | \$ 1,295.00 | 10% | <i>\$1,174.24</i> |
| EW ResponsePLS NBD AHR 16571 | 97504-16571 | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW ResponsePLS NBD AHR- 16701 | 97504-16701 | \$ 1,608.00 | 10% | <i>\$1,458.05</i> |
| EW ResponsePLS NBD AHR- 16702 | 97504-16702 | \$ 1,790.00 | 10% | <i>\$1,623.08</i> |
| EW ResponsePLS NBD AHR- 16703 | 97504-16703 | \$ 1,802.00 | 10% | <i>\$1,633.96</i> |
| EW ResponsePLS NBD AHR 16703T | 97504-16703T | \$ 1,925.00 | 10% | <i>\$1,745.49</i> |
| EW ResponsePLUS NBD AHR- 16704 | 97504-16704 | \$ 1,997.00 | 10% | <i>\$1,810.78</i> |
| EW ResponsePLS NBD AHR 16704T | 97504-16704T | \$ 1,625.00 | 10% | <i>\$1,473.47</i> |
| EW ResponsePLS NBD AHR- 16705 | 97504-16705 | \$ 1,790.00 | 10% | <i>\$1,623.08</i> |
| EW ResponsePLS NBD AHR 16705T | 97504-16705T | \$ 1,905.00 | 10% | <i>\$1,727.36</i> |
| EW ResponsePLS NBD AHR- 16706 | 97504-16706 | \$ 2,195.00 | 10% | <i>\$1,990.32</i> |
| EW ResponsePLS NBD AHR 16706T | 97504-16706T | \$ 2,350.00 | 10% | <i>\$2,130.86</i> |
| EW ResponsePLS NBD AHR- 16710 | 97504-16710 | \$ 596.00 | 10% | <i>\$540.42</i> |
| EW ResponsePLS NBD AHR 16710T | 97504-16710T | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW ResponsePLS NBD AHR- 16711 | 97504-16711 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR 16711T | 97504-16711T | \$ 526.00 | 10% | <i>\$476.95</i> |
| EW ResponsePLS NBD AHR- 16712 | 97504-16712 | \$ 518.00 | 10% | <i>\$469.70</i> |
| EW ResponsePLS NBD AHR 16712T | 97504-16712T | \$ 539.00 | 10% | <i>\$488.74</i> |
| EW ResponsePLS NBD AHR- 16713 | 97504-16713 | \$ 466.00 | 10% | <i>\$422.55</i> |
| EW ResponsePLS NBD AHR 16713T | 97504-16713T | \$ 500.00 | 10% | <i>\$453.38</i> |
| EW ResponsePLS NBD AHR- 16715 | 97504-16715 | \$ 479.00 | 10% | <i>\$434.33</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR 16715T | 97504-16715T | \$ 526.00 | 10% | <i>\$476.95</i> |
| EW ResponsePLS NBD AHR- 16716 | 97504-16716 | \$ 1,650.00 | 10% | <i>\$1,496.14</i> |
| EW ResponsePLS NBD AHR 16716T | 97504-16716T | \$ 1,779.00 | 10% | <i>\$1,613.11</i> |
| EW ResponsePLS NBD AHR- 16717 | 97504-16717 | \$ 1,678.00 | 10% | <i>\$1,521.53</i> |
| EW ResponsePLS NBD AHR- 16718 | 97504-16718 | \$ 1,680.00 | 10% | <i>\$1,523.34</i> |
| EW ResponsePLS NBD AHR- 16719 | 97504-16719 | \$ 1,707.00 | 10% | <i>\$1,547.82</i> |
| EW ResponsePLS NBD AHR 16720 | 97504-16720 | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW ResponsePLS NBD AHR 16720T | 97504-16720T | \$ 2,261.00 | 10% | <i>\$2,050.16</i> |
| EW ResponsePLS NBD AHR 16756 | 97504-16756 | \$ 1,861.00 | 10% | <i>\$1,687.46</i> |
| EW ResponsePLS NBD AHR 16756T | 97504-16756T | \$ 2,198.00 | 10% | <i>\$1,993.04</i> |
| EW ResponsePLS NBD AHR 16757 | 97504-16757 | \$ 1,833.00 | 10% | <i>\$1,662.07</i> |
| EW ResponsePLS NBD AHR 16757T | 97504-16757T | \$ 2,167.00 | 10% | <i>\$1,964.93</i> |
| EW ResponsePLS NBD AHR 16790 | 97504-16790 | \$ 1,784.00 | 10% | <i>\$1,617.64</i> |
| EW ResponsePLS NBD AHR 16791 | 97504-16791 | \$ 2,303.00 | 10% | <i>\$2,088.25</i> |
| EW ResponsePLS NBD AHR- 17101 | 97504-17101 | \$ 3,276.00 | 10% | <i>\$2,970.51</i> |
| EW ResponsePLS NBD AHR- 17101T | 97504-17101T | \$ 4,058.00 | 10% | <i>\$3,679.59</i> |
| EW ResponsePLS NBD AHR- 17102 | 97504-17102 | \$ 3,276.00 | 10% | <i>\$2,970.51</i> |
| EW ResponsePLS NBD AHR- 17102T | 97504-17102T | \$ 4,058.00 | 10% | <i>\$3,679.59</i> |
| EW ResponsePLS NBD AHR- 17103 | 97504-17103 | \$ 2,626.00 | 10% | <i>\$2,381.13</i> |
| EW ResponsePLS NBD AHR- 17103C | 97504-17103C | \$ 2,548.00 | 10% | <i>\$2,310.40</i> |
| EW ResponsePLS NBD AHR- 17103T | 97504-17103T | \$ 3,230.00 | 10% | <i>\$2,928.80</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|------------|
| EW ResponsePLS NBD AHR-17104 | 97504-17104 | \$ 2,626.00 | 10% | \$2,381.13 |
| EW ResponsePLS NBD AHR-17104T | 97504-17104T | \$ 3,230.00 | 10% | \$2,928.80 |
| EW ResponsePLS NBD AHR-17121 | 97504-17121 | \$ 873.00 | 10% | \$791.59 |
| EW ResponsePLS NBD AHR-17122 | 97504-17122 | \$ 681.00 | 10% | \$617.50 |
| EW ResponsePLS NBD AHR-17200 | 97504-17200 | \$ 4,512.00 | 10% | \$4,091.26 |
| EW ResponsePLS NBD AHR-17200T | 97504-17200T | \$ 5,037.00 | 10% | \$4,567.30 |
| EW ResponsePLS NBD AHR-17201 | 97504-17201 | \$ 4,512.00 | 10% | \$4,091.26 |
| EW ResponsePLS NBD AHR-17201T | 97504-17201T | \$ 5,037.00 | 10% | \$4,567.30 |
| EW ResponsePLS NBD AHR-17202 | 97504-17202 | \$ 4,512.00 | 10% | \$4,091.26 |
| EW ResponsePLS NBD AHR-17202T | 97504-17202T | \$ 5,037.00 | 10% | \$4,567.30 |
| EW ResponsePLS NBD AHR-17203 | 97504-17203 | \$ 4,563.00 | 10% | \$4,137.50 |
| EW ResponsePLS NBD AHR-17203T | 97504-17203T | \$ 5,104.00 | 10% | \$4,628.05 |
| EW ResponsePLS NBD AHR-17204 | 97504-17204 | \$ 4,563.00 | 10% | \$4,137.50 |
| EW ResponsePLS NBD AHR-17204T | 97504-17204T | \$ 5,104.00 | 10% | \$4,628.05 |
| EW ResponsePLS NBD AHR-17205 | 97504-17205 | \$ 4,539.00 | 10% | \$4,115.74 |
| EW ResponsePLS NBD AHR-17205T | 97504-17205T | \$ 5,069.00 | 10% | \$4,596.32 |
| EW ResponsePLS NBD AHR-17206 | 97504-17206 | \$ 4,539.00 | 10% | \$4,115.74 |
| EW ResponsePLS NBD AHR-17206T | 97504-17206T | \$ 5,069.00 | 10% | \$4,596.32 |
| EW ResponsePLS NBD AHR-17300 | 97504-17300 | \$ 3,451.00 | 10% | \$3,129.19 |
| EW ResponsePLS NBD AHR-17310 | 97504-17310 | \$ 3,242.00 | 10% | \$2,939.68 |
| EW ResponsePLS NBD AHR-17350 | 97504-17350 | \$ 3,345.00 | 10% | \$3,033.08 |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR 17360 | 97504-17360 | \$ 3,841.00 | 10% | <i>\$3,482.83</i> |
| EW ResponsePLS NBD AHR 17401 | 97504-17401 | \$ 1,532.00 | 10% | <i>\$1,389.14</i> |
| EW ResponsePLS NBD AHR 17401G | 97504-17401G | \$ 1,553.00 | 10% | <i>\$1,408.18</i> |
| EW ResponsePLS NBD AHR 17401T | 97504-17401T | \$ 1,553.00 | 10% | <i>\$1,408.18</i> |
| EW ResponsePLS NBD AHR 17402 | 97504-17402 | \$ 1,579.00 | 10% | <i>\$1,431.76</i> |
| EW ResponsePLS NBD AHR 17402G | 97504-17402G | \$ 1,535.00 | 10% | <i>\$1,391.86</i> |
| EW ResponsePLS NBD AHR 17402T | 97504-17402T | \$ 1,535.00 | 10% | <i>\$1,391.86</i> |
| EW ResponsePLS NBD AHR 17403 | 97504-17403 | \$ 1,603.00 | 10% | <i>\$1,453.52</i> |
| EW ResponsePLS NBD AHR 17404 | 97504-17404 | \$ 1,444.00 | 10% | <i>\$1,309.35</i> |
| EW ResponsePLS NBD AHR 17405 | 97504-17405 | \$ 1,427.00 | 10% | <i>\$1,293.93</i> |
| EW ResponsePLS NBD AHR 17700 | 97504-17700 | \$ 5,290.00 | 10% | <i>\$4,796.71</i> |
| EW ResponsePLS NBD AHR- 17701 | 97504-17701 | \$ 4,552.00 | 10% | <i>\$4,127.53</i> |
| EW ResponsePLS NBD AHR- 17702 | 97504-17702 | \$ 4,552.00 | 10% | <i>\$4,127.53</i> |
| EW ResponsePLS NBD AHR- 17703 | 97504-17703 | \$ 4,961.00 | 10% | <i>\$4,498.39</i> |
| EW ResponsePLS NBD AHR- 17704 | 97504-17704 | \$ 4,961.00 | 10% | <i>\$4,498.39</i> |
| EW ResponsePLS NBD AHR- 17705 | 97504-17705 | \$ 4,577.00 | 10% | <i>\$4,150.19</i> |
| EW ResponsePLS NBD AHR- 17706 | 97504-17706 | \$ 4,577.00 | 10% | <i>\$4,150.19</i> |
| EW ResponsePLS NBD AHR 17800 | 97504-17800 | \$ 5,395.00 | 10% | <i>\$4,891.92</i> |
| EW ResponsePLS NBD AHR 17810 | 97504-17810 | \$ 4,561.00 | 10% | <i>\$4,135.69</i> |
| EW ResponsePLS NBD AHR 18101 | 97504-18101 | \$ 584.00 | 10% | <i>\$529.54</i> |
| EW ResponsePLS NBD AHR 18102 | 97504-18102 | \$ 642.00 | 10% | <i>\$582.13</i> |

| | | | | |
|-------------------------------------|---------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR 18103 | 97504-18103 | \$ 667.00 | 10% | <i>\$604.80</i> |
| EW ResponsePLS NBD AHR 18104 | 97504-18104 | \$ 790.00 | 10% | <i>\$716.33</i> |
| EW ResponsePLS NBD AHR 18104-6PK | 97504-18104- 6PK | \$ 4,737.00 | 10% | <i>\$4,295.27</i> |
| EW ResponsePLS NBD AHR- 30135 | 97504-30135 | \$ 2,723.00 | 10% | <i>\$2,469.08</i> |
| EW ResponsePLS NBD AHR 30136 | 97504-30136 | \$ 5,446.00 | 10% | <i>\$4,938.16</i> |
| EW ResponsePLS NBD AHR 30137 | 97504-30137 | \$ 2,091.00 | 10% | <i>\$1,896.01</i> |
| EW ResponsePLS NBD AHR 30138 | 97504-30138 | \$ 4,841.00 | 10% | <i>\$4,389.58</i> |
| EW ResponsePLS NBD AHR 30139 | 97504-30139 | \$ 8,034.00 | 10% | <i>\$7,284.83</i> |
| EW ResponsePLS NBD AHR 30912 | 97504-30912 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR 30913 | 97504-30913 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR 31012 | 97504-31012 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR 31013 | 97504-31013 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR 31014 | 97504-31014 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR 31015 | 97504-31015 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR 31016 | 97504-31016 | \$ 542.00 | 10% | <i>\$491.46</i> |
| EW ResponsePLS NBD AHR 31017 | 97504-31017 | \$ 542.00 | 10% | <i>\$491.46</i> |
| EW ResponsePLS NBD AHR 31018 | 97504-31018 | \$ 581.00 | 10% | <i>\$526.82</i> |
| EW ResponsePLS NBD AHR 31019 | 97504-31019 | \$ 581.00 | 10% | <i>\$526.82</i> |
| EW ResponsePLS NBD AHR 31025 | 97504-31025 | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW ResponsePLS NBD AHR 31026 | 97504-31026 | \$ 343.00 | 10% | <i>\$311.02</i> |
| EW ResponsePLS NBD AHR 31028 | 97504-31028 | \$ 336.00 | 10% | <i>\$304.67</i> |

| | | | | |
|--|------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR 31029 | 97504-31029 | \$ 336.00 | 10% | <i>\$304.67</i> |
| EW ResponsePLS NBD AHR 31031 | 97504-31031 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW ResponsePLS NBD AHR 31032 | 97504-31032 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW ResponsePLS NBD AHR 31034 | 97504-31034 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR 31035 | 97504-31035 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR 31050 | 97504-31050 | \$ 383.00 | 10% | <i>\$347.29</i> |
| EW ResponsePLS NBD AHR 31051 | 97504-31051 | \$ 383.00 | 10% | <i>\$347.29</i> |
| EW ResponsePLS NBD AHR 31055 | 97504-31055 | \$ 383.00 | 10% | <i>\$347.29</i> |
| EW ResponsePLS NBD AHR 31056 | 97504-31056 | \$ 383.00 | 10% | <i>\$347.29</i> |
| EW ResponsePLS NBD AHR 39031 | 97504-39031 | \$ 744.00 | 10% | <i>\$674.62</i> |
| EW ResponsePLS NBD AHR 39032 | 97504-39032 | \$ 770.00 | 10% | <i>\$698.20</i> |
| EW ResponsePLS NBD AHR 39033 | 97504-39033 | \$ 744.00 | 10% | <i>\$674.62</i> |
| EW ResponsePLS NBD AHR 39034 | 97504-39034 | \$ 744.00 | 10% | <i>\$674.62</i> |
| EW ResponsePLS NBD AHR 39035 | 97504-39035 | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW ResponsePLS NBD AHR 39036 | 97504-39036 | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW ResponsePLS NBD AHR 39037 | 97504-39037 | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW ResponsePLS NBD AHR 39038 | 97504-39038 | \$ 761.00 | 10% | <i>\$690.04</i> |
| EW ResponsePLS NBD AHR 39039 | 97504-39039 | \$ 761.00 | 10% | <i>\$690.04</i> |
| EW ResponsePLS NBD AHR 4120-24MW-4Y | 97504-4120- 24MW-4Y | \$ 1,339.00 | 10% | <i>\$1,214.14</i> |
| EW ResponsePLS NBD AHR 4120-48MW-4Y | 97504-4120- 48MW-4Y | \$ 1,516.00 | 10% | <i>\$1,374.63</i> |
| EW ResponsePLS NBD AHR 4120C | 97504-4120C | \$ 5,400.00 | 10% | <i>\$4,896.45</i> |

| | | | | |
|---|---------------------------|-------------|-----|------------|
| EW ResponsePLS NBD AHR 4120C-1 | 97504-4120C-1 | \$ 6,096.00 | 10% | \$5,527.55 |
| EW ResponsePLS NBD AHR 41216 | 97504-41216 | \$ 1,815.00 | 10% | \$1,645.75 |
| EW ResponsePLS NBD AHR 4220-12P-4X | 97504-4220- 12P-4X | \$ 970.00 | 10% | \$879.55 |
| EW ResponsePLS NBD AHR 4220-12T-4X | 97504-4220- 12T-4X | \$ 927.00 | 10% | \$840.56 |
| EW ResponsePLS NBD AHR 4220-24P-4X | 97504-4220- 24P-4X | \$ 1,024.00 | 10% | \$928.51 |
| EW ResponsePLS NBD AHR 4220-24T-4X | 97504-4220- 24T-4X | \$ 976.00 | 10% | \$884.99 |
| EW ResponsePLS NBD AHR 4220-48P-4X | 97504-4220- 48P-4X | \$ 1,132.00 | 10% | \$1,026.44 |
| EW ResponsePLS NBD AHR 4220-48T-4X | 97504-4220- 48T-4X | \$ 1,051.00 | 10% | \$952.99 |
| EW ResponsePLS NBD AHR 4220-4MW-20P-4X | 97504-4220- 4MW-20P-4X | \$ 1,105.00 | 10% | \$1,001.96 |
| EW ResponsePLS NBD AHR 4220-4MW-8P-4X | 97504-4220- 4MW-8P-4X | \$ 1,019.00 | 10% | \$923.98 |
| EW ResponsePLS NBD AHR 4220-8MW-40P-4X | 97504-4220- 8MW-40P-4X | \$ 1,240.00 | 10% | \$1,124.37 |
| EW ResponsePLS NBD AHR 4220-8X | 97504-4220-8X | \$ 1,035.00 | 10% | \$938.49 |
| EW ResponsePLS NBD AHR- 48001 | 97504-48001 | \$ 8,052.00 | 10% | \$7,301.15 |
| EW ResponsePLS NBD AHR- 48038 | 97504-48038 | \$ 2,720.00 | 10% | \$2,466.36 |
| EW ResponsePLS NBD AHR- 48039 | 97504-48039 | \$ 2,720.00 | 10% | \$2,466.36 |
| EW ResponsePLS NBD AHR- 48040 | 97504-48040 | \$ 2,507.00 | 10% | \$2,273.22 |
| EW ResponsePLS NBD AHR- 48041 | 97504-48041 | \$ 2,720.00 | 10% | \$2,466.36 |
| EW ResponsePLS NBD AHR- 48046 | 97504-48046 | \$ 3,429.00 | 10% | \$3,109.25 |
| EW ResponsePLS NBD AHR- 48047 | 97504-48047 | \$ 8,383.00 | 10% | \$7,601.29 |
| EW ResponsePLS NBD AHR- 48051 | 97504-48051 | \$ 5,903.00 | 10% | \$5,352.55 |
| EW ResponsePLS NBD AHR- 48061 | 97504-48061 | \$ 6,822.00 | 10% | \$6,185.85 |

| | | | | |
|---|--------------------------|--------------|-----|-------------------|
| EW ResponsePLS NBD AHR-48062 | 97504-48062 | \$ 10,643.00 | 10% | <i>\$9,650.54</i> |
| EW ResponsePLS NBD AHR 5320-16P-4XE | 97504-5320-16P-4XE | \$ 1,166.00 | 10% | <i>\$1,057.27</i> |
| EW ResponsePLS NBD AHR 5320-16P-4XE-DC | 97504-5320-16P-4XE-DC | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW ResponsePLS NBD AHR 5320-24P-8XE | 97504-5320-24P-8XE | \$ 1,151.00 | 10% | <i>\$1,043.67</i> |
| EW ResponsePLS NBD AHR 5320-24T-8XE | 97504-5320-24T-8XE | \$ 1,121.00 | 10% | <i>\$1,016.47</i> |
| EW ResponsePLS NBD AHR 5320-48P-8XE | 97504-5320-48P-8XE | \$ 1,414.00 | 10% | <i>\$1,282.14</i> |
| EW ResponsePLS NBD AHR 5320-48T-8XE | 97504-5320-48T-8XE | \$ 1,278.00 | 10% | <i>\$1,158.83</i> |
| EW ResponsePLS NBD AHR 5420F-16MW-32P-4XE | 97504-5420F-16MW-32P-4XE | \$ 2,034.00 | 10% | <i>\$1,844.33</i> |
| EW ResponsePLS NBD AHR 5420F-16W-32P-4XE | 97504-5420F-16W-32P-4XE | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW ResponsePLS NBD AHR 5420F-24P-4XE | 97504-5420F-24P-4XE | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsePLS NBD AHR 5420F-24S-4XE | 97504-5420F-24S-4XE | \$ 1,577.00 | 10% | <i>\$1,429.94</i> |
| EW ResponsePLS NBD AHR 5420F-24T-4XE | 97504-5420F-24T-4XE | \$ 1,471.00 | 10% | <i>\$1,333.83</i> |
| EW ResponsePLS NBD AHR 5420F-48P-4XE | 97504-5420F-48P-4XE | \$ 1,724.00 | 10% | <i>\$1,563.24</i> |
| EW ResponsePLS NBD AHR 5420F-48P-4XL | 97504-5420F-48P-4XL | \$ 1,809.00 | 10% | <i>\$1,640.31</i> |
| EW ResponsePLS NBD AHR 5420F-48T-4XE | 97504-5420F-48T-4XE | \$ 1,529.00 | 10% | <i>\$1,386.42</i> |
| EW ResponsePLS NBD AHR 5420F-8W-16P-4XE | 97504-5420F-8W-16P-4XE | \$ 1,553.00 | 10% | <i>\$1,408.18</i> |
| EW ResponsePLS NBD AHR 5420M-16MW-32P-4YE | 97504-5420M-16MW-32P-4YE | \$ 1,942.00 | 10% | <i>\$1,760.91</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR 5420M-24T-4YE | 97504-5420M- 24T-4YE | \$ 1,523.00 | 10% | <i>\$1,380.98</i> |
| EW ResponsePLS NBD AHR 5420M-24W-4YE | 97504-5420M- 24W-4YE | \$ 1,394.00 | 10% | <i>\$1,264.01</i> |
| EW ResponsePLS NBD AHR 5420M-48T-4YE | 97504-5420M- 48T-4YE | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW ResponsePLS NBD AHR 5420M-48W-4YE | 97504-5420M- 48W-4YE | \$ 1,764.00 | 10% | <i>\$1,599.51</i> |
| EW RESPONSEPLUS NBD AHR 5520-12MW-36W | 97504-5520- 12MW-36W | \$ 1,876.00 | 10% | <i>\$1,701.06</i> |
| EW RESPONSEPLUS NBD AHR 5520-24T | 97504-5520- 24T | \$ 1,536.00 | 10% | <i>\$1,392.77</i> |
| EW RESPONSEPLU NBD AH 5520-24T-ACDC-BASE | 97504-5520- 24T-ACDC- BASE | \$ 1,536.00 | 10% | <i>\$1,392.77</i> |
| EW RESPONSEPLUS NBD AHR 5520-24T-BASE | 97504-5520- 24T-BASE | \$ 1,536.00 | 10% | <i>\$1,392.77</i> |
| EW RESPONSEPLUS NBD AHR 5520-24W | 97504-5520- 24W | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |
| EW RESPONSEPLUS NBD AHR 5520-24X | 97504-5520- 24X | \$ 2,234.00 | 10% | <i>\$2,025.68</i> |
| EW RESPONSEPLU NBD AH 5520-24X-ACDC-BASE | 97504-5520- 24X-ACDC- BASE | \$ 2,234.00 | 10% | <i>\$2,025.68</i> |
| EW RESPONSEPLUS NBD AHR 5520-24X-BASE | 97504-5520- 24X-BASE | \$ 2,234.00 | 10% | <i>\$2,025.68</i> |
| EW RESPONSEPLUS NBD AHR 5520-48SE | 97504-5520- 48SE | \$ 2,095.00 | 10% | <i>\$1,899.64</i> |
| EW RESPONSEPL NBD AH 5520-48SE-ACDC-BASE | 97504-5520- 48SE-ACDC- BASE | \$ 2,095.00 | 10% | <i>\$1,899.64</i> |
| EW RESPONSEPLUS NBD AHR 5520-48SE-BASE | 97504-5520- 48SE-BASE | \$ 2,095.00 | 10% | <i>\$1,899.64</i> |
| EW RESPONSEPLUS NBD AHR 5520-48T | 97504-5520- 48T | \$ 1,732.00 | 10% | <i>\$1,570.49</i> |
| EW RESPONSEPLU NBD AH 5520-48T-ACDC-BASE | 97504-5520- 48T-ACDC- BASE | \$ 1,732.00 | 10% | <i>\$1,570.49</i> |
| EW RESPONSEPLUS NBD AHR 5520-48T-BASE | 97504-5520- 48T-BASE | \$ 1,732.00 | 10% | <i>\$1,570.49</i> |
| EW RESPONSEPLUS NBD AHR 5520-48W | 97504-5520- 48W | \$ 1,790.00 | 10% | <i>\$1,623.08</i> |

| | | | | |
|--|----------------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR 5720-24MW | 97504-5720- 24MW | \$ 1,545.00 | 10% | <i>\$1,400.93</i> |
| EW ResponsePLS NBD AHR 5720-24MXW | 97504-5720- 24MXW | \$ 2,005.00 | 10% | <i>\$1,818.03</i> |
| EW ResponsePLS NBD AHR 5720-48MW | 97504-5720- 48MW | \$ 1,723.00 | 10% | <i>\$1,562.33</i> |
| EW ResponsePLS NBD AHR 5720-48MXW | 97504-5720- 48MXW | \$ 2,250.00 | 10% | <i>\$2,040.19</i> |
| EW ResponsePLS NBD AHR 7520-48XT-6C | 97504-7520- 48XT-6C | \$ 2,589.00 | 10% | <i>\$2,347.58</i> |
| EW ResponsePLS NBD AHR 7520-48XT-6C-AC-F | 97504-7520- 48XT-6C-AC- F | \$ 2,589.00 | 10% | <i>\$2,347.58</i> |
| EW ResponsePLS NBD AHR 7520-48XT-6C-AC-R | 97504-7520- 48XT-6C-AC- R | \$ 2,589.00 | 10% | <i>\$2,347.58</i> |
| EW ResponsePLS NBD AHR 7520-48Y-8C | 97504-7520- 48Y-8C | \$ 2,412.00 | 10% | <i>\$2,187.08</i> |
| EW ResponsePLS NBD AHR 7520-48Y-8C-AC-F | 97504-7520- 48Y-8C-AC-F | \$ 2,412.00 | 10% | <i>\$2,187.08</i> |
| EW ResponsePLS NBD AHR 7520-48Y-8C-AC-R | 97504-7520- 48Y-8C-AC-R | \$ 2,412.00 | 10% | <i>\$2,187.08</i> |
| EW RESPONSEPLUS NBD AHR 7520-48YE-8CE | 97504-7520- 48YE-8CE | \$ 2,802.00 | 10% | <i>\$2,540.71</i> |
| EW RESPONSEPLU NBD AHR 7520-48YE-8CE-AC-F | 97504-7520- 48YE-8CE-AC- F | \$ 2,802.00 | 10% | <i>\$2,540.71</i> |
| EW RESPONSEPLU NBD AHR 7520-48YE-8CE-AC-R | 97504-7520- 48YE-8CE-AC- R | \$ 2,802.00 | 10% | <i>\$2,540.71</i> |
| EW ResponsePLS NBD AHR 7720-32C | 97504-7720- 32C | \$ 3,004.00 | 10% | <i>\$2,723.88</i> |
| EW ResponsePLS NBD AHR 7720-32C-AC-F | 97504-7720- 32C-AC-F | \$ 3,004.00 | 10% | <i>\$2,723.88</i> |
| EW ResponsePLS NBD AHR 7720-32C-AC-R | 97504-7720- 32C-AC-R | \$ 3,004.00 | 10% | <i>\$2,723.88</i> |
| EW ResponsePLS NBD AHR 8520-48XT-6C | 97504-8520- 48XT-6C | \$ 3,458.00 | 10% | <i>\$3,135.54</i> |
| EW ResponsePLS NBD AHR 8520-48XT-6C-AC-F | 97504-8520- 48XT-6C-AC- F | \$ 3,458.00 | 10% | <i>\$3,135.54</i> |

| | | | | |
|---|---------------------------------|--------------|-----|-------------------|
| EW ResponsePLS NBD AHR 8520-48XT-6C-AC-R | 97504-8520- 48XT-6C-AC- R | \$ 3,458.00 | 10% | <i>\$3,135.54</i> |
| EW ResponsePLS NBD AHR 8520-48XT-6C-DC-F | 97504-8520- 48XT-6C-DC- F | \$ 3,458.00 | 10% | <i>\$3,135.54</i> |
| EW ResponsePLS NBD AHR 8520-48XT-6C-DC-R | 97504-8520- 48XT-6C-DC- R | \$ 3,458.00 | 10% | <i>\$3,135.54</i> |
| EW ResponsePLS NBD AHR 8520-48Y-8C | 97504-8520- 48Y-8C | \$ 3,571.00 | 10% | <i>\$3,238.00</i> |
| EW ResponsePLS NBD AHR 8520-48Y-8C-AC-F | 97504-8520- 48Y-8C-AC-F | \$ 3,571.00 | 10% | <i>\$3,238.00</i> |
| EW ResponsePLS NBD AHR 8520-48Y-8C-AC-R | 97504-8520- 48Y-8C-AC-R | \$ 3,571.00 | 10% | <i>\$3,238.00</i> |
| EW ResponsePLS NBD AHR 8520-48Y-8C-DC-F | 97504-8520- 48Y-8C-DC-F | \$ 3,571.00 | 10% | <i>\$3,238.00</i> |
| EW ResponsePLS NBD AHR 8520-48Y-8C-DC-R | 97504-8520- 48Y-8C-DC-R | \$ 3,571.00 | 10% | <i>\$3,238.00</i> |
| EW ResponsePLS NBD AHR 8720-32C | 97504-8720- 32C | \$ 3,901.00 | 10% | <i>\$3,537.23</i> |
| EW ResponsePLS NBD AHR 8720-32C-AC-F | 97504-8720- 32C-AC-F | \$ 3,901.00 | 10% | <i>\$3,537.23</i> |
| EW ResponsePLS NBD AHR 8720-32C-AC-R | 97504-8720- 32C-AC-R | \$ 3,901.00 | 10% | <i>\$3,537.23</i> |
| EW ResponsePLS NBD AHR 8720-32C-DC-F | 97504-8720- 32C-DC-F | \$ 3,901.00 | 10% | <i>\$3,537.23</i> |
| EW ResponsePLS NBD AHR 8720-32C-DC-R | 97504-8720- 32C-DC-R | \$ 3,901.00 | 10% | <i>\$3,537.23</i> |
| EW ResponsePLUS NBD AHR- 8806 | 97504-8806 | \$ 4,040.00 | 10% | <i>\$3,663.27</i> |
| EW ResponsePLS NBD AHR- 8810 | 97504-8810 | \$ 7,681.00 | 10% | <i>\$6,964.75</i> |
| EW ResponsePLS NBD AHR 8820-40C | 97504-8820- 40C | \$ 10,658.00 | 10% | <i>\$9,664.14</i> |
| EW ResponsePLS NBD AHR 8820-40C-AC-F | 97504-8820- 40C-AC-F | \$ 10,658.00 | 10% | <i>\$9,664.14</i> |
| EW ResponsePLS NBD AHR 8820-40C-AC-R | 97504-8820- 40C-AC-R | \$ 10,658.00 | 10% | <i>\$9,664.14</i> |
| EW ResponsePLS NBD AHR 8820-40C-DC-F | 97504-8820- 40C-DC-F | \$ 10,658.00 | 10% | <i>\$9,664.14</i> |

| | | | | |
|---|-----------------------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR 8820-40C-DC-R | 97504-8820- 40C-DC-R | \$ 10,658.00 | 10% | <i>\$9,664.14</i> |
| EW ResponsePLS NBD AHR 8820-80C | 97504-8820- 80C | \$ 18,332.00 | 10% | <i>\$16,622.54</i> |
| EW ResponsePLS NBD AHR 8820-80C-AC-F | 97504-8820- 80C-AC-F | \$ 18,332.00 | 10% | <i>\$16,622.54</i> |
| EW ResponsePLS NBD AHR 8820-80C-AC-R | 97504-8820- 80C-AC-R | \$ 18,332.00 | 10% | <i>\$16,622.54</i> |
| EW ResponsePLS NBD AHR 8820-80C-DC-F | 97504-8820- 80C-DC-F | \$ 18,332.00 | 10% | <i>\$16,622.54</i> |
| EW ResponsePLS NBD AHR 8820-80C-DC-R | 97504-8820- 80C-DC-R | \$ 18,332.00 | 10% | <i>\$16,622.54</i> |
| EW ResponsePLS NBD AHR 9920-16C | 97504-9920- 16C | \$ 8,963.00 | 10% | <i>\$8,127.20</i> |
| EW ResponsePLS NBD AHR 9920-4D | 97504-9920-4D | \$ 8,963.00 | 10% | <i>\$8,127.20</i> |
| EW ResponsePLS NBD AHR 9920-NPB-8 | 97504-9920- NPB-8 | \$ 15,173.00 | 10% | <i>\$13,758.12</i> |
| EW ResponsePLS NBD AHR AH-AP-1130-AC-CE | 97504-AH-AP- 1130-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-1130-AC-FCC | 97504-AH-AP- 1130-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-1130-AC-W | 97504-AH-AP- 1130-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-121-N-CE | 97504-AH-AP- 121-N-CE | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-121-N-FCC | 97504-AH-AP- 121-N-FCC | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-121-N-W | 97504-AH-AP- 121-N-W | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-121-N-W-NEC | 97504-AH-AP- 121-N-W-NEC | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-122-AC-CAN | 97504-AH-AP- 122-AC-CAN | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-122-AC-CE | 97504-AH-AP- 122-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-122-AC-FCC | 97504-AH-AP- 122-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-122-AC-W | 97504-AH-AP- 122-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |

| | | | | |
|---|---------------------------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR AH-AP-122X-AC-CAN | 97504-AH-AP- 122X-AC- CAN | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-122X-AC-CE | 97504-AH-AP- 122X-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-122X-AC-FCC | 97504-AH-AP- 122X-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-122X-AC-W | 97504-AH-AP- 122X-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-130-AC-CE | 97504-AH-AP- 130-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-130-AC-FCC | 97504-AH-AP- 130-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-130-AC-W | 97504-AH-AP- 130-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-141-N-CE | 97504-AH-AP- 141-N-CE | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-141-N-FCC | 97504-AH-AP- 141-N-FCC | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-141-N-W | 97504-AH-AP- 141-N-W | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-150W-AC-CAN | 97504-AH-AP- 150W-AC- CAN | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-150W-AC-CE | 97504-AH-AP- 150W-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-150W-AC-FCC | 97504-AH-AP- 150W-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-150W-AC-W | 97504-AH-AP- 150W-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-230-AC-CE | 97504-AH-AP- 230-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-230-AC-FCC | 97504-AH-AP- 230-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-230-AC-W | 97504-AH-AP- 230-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-245X-AC-CAN | 97504-AH-AP- 245X-AC- CAN | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-245X-AC-CE | 97504-AH-AP- 245X-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |

| | | | | |
|---|-----------------------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR AH-AP-245X-AC-FCC | 97504-AH-AP- 245X-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-245X-AC-W | 97504-AH-AP- 245X-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-250-AC-CAN | 97504-AH-AP- 250-AC-CAN | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-250-AC-CE | 97504-AH-AP- 250-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-250-AC-FCC | 97504-AH-AP- 250-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-250-AC-W | 97504-AH-AP- 250-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-330-N-FCC | 97504-AH-AP- 330-N-FCC | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-330-N-W | 97504-AH-AP- 330-N-W | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-350-N-FCC | 97504-AH-AP- 350-N-FCC | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-350-N-W | 97504-AH-AP- 350-N-W | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR AH-AP-550-AC-CAN | 97504-AH-AP- 550-AC-CAN | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-550-AC-CE | 97504-AH-AP- 550-AC-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-550-AC-FCC | 97504-AH-AP- 550-AC-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-550-AC-W | 97504-AH-AP- 550-AC-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-630-AX-CAN | 97504-AH-AP- 630-AX-CAN | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-630-AX-CE | 97504-AH-AP- 630-AX-CE | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-630-AX-FCC | 97504-AH-AP- 630-AX-FCC | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-630-AX-W | 97504-AH-AP- 630-AX-W | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsePLS NBD AHR AH-AP-650-AX-CAN | 97504-AH-AP- 650-AX-CAN | \$ 289.00 | 10% | <i>\$262.05</i> |
| EW ResponsePLS NBD AHR AH-AP-650-AX-CE | 97504-AH-AP- 650-AX-CE | \$ 289.00 | 10% | <i>\$262.05</i> |
| EW ResponsePLS NBD AHR AH-AP-650-AX-FCC | 97504-AH-AP- 650-AX-FCC | \$ 289.00 | 10% | <i>\$262.05</i> |

| | | | | |
|---|---------------------------------|-------------|-----|------------|
| EW ResponsePLS NBD AHR AH-AP-650-AX-W | 97504-AH-AP- 650-AX-W | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AH-AP-650X-AX-CAN | 97504-AH-AP- 650X-AX- CAN | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AH-AP-650X-AX-CE | 97504-AH-AP- 650X-AX-CE | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AH-AP-650X-AX-FCC | 97504-AH-AP- 650X-AX-FCC | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AH-AP-650X-AX-W | 97504-AH-AP- 650X-AX-W | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AH-ATOM-CAN | 97504-AH- ATOM-CAN | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR AH-ATOM-CE-EU | 97504-AH- ATOM-CE-EU | \$ 380.00 | 10% | \$344.57 |
| EW ResponsePLS NBD AHR AH-ATOM-CE-UK | 97504-AH- ATOM-CE-UK | \$ 380.00 | 10% | \$344.57 |
| EW ResponsePLS NBD AHR AH-ATOM-FCC | 97504-AH- ATOM-FCC | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR AH-ATOM-W | 97504-AH- ATOM-W | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR AH-ATOM-W-EU | 97504-AH- ATOM-W-EU | \$ 380.00 | 10% | \$344.57 |
| EW ResponsePLS NBD AHR AH-ATOM-W-UK | 97504-AH- ATOM-W-UK | \$ 380.00 | 10% | \$344.57 |
| EW ResponsePLS NBD AHR AH-BR-100-N-FCC | 97504-AH-BR- 100-N-FCC | \$ 1,227.00 | 10% | \$1,112.58 |
| EW ResponsePLS NBD AHR AH-BR-100-N-W | 97504-AH-BR- 100-N-W | \$ 1,227.00 | 10% | \$1,112.58 |
| EW ResponsePLS NBD AHR AH-BR-100-N-W-AU | 97504-AH-BR- 100-N-W-AU | \$ 1,227.00 | 10% | \$1,112.58 |
| EW ResponsePLS NBD AHR AH-BR-100-N-W-EU | 97504-AH-BR- 100-N-W-EU | \$ 1,227.00 | 10% | \$1,112.58 |
| EW ResponsePLS NBD AHR AH-BR-100-N-W-UK | 97504-AH-BR- 100-N-W-UK | \$ 1,227.00 | 10% | \$1,112.58 |
| EW ResponsePLS NBD AHR AH-BR-100-N-W-US | 97504-AH-BR- 100-N-W-US | \$ 1,227.00 | 10% | \$1,112.58 |
| EW ResponsePLS NBD AHR AH-BR-200 | 97504-AH-BR- 200 | \$ 1,115.00 | 10% | \$1,011.03 |

| | | | | |
|---|-----------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR AH-BR-200WP-N-CE | 97504-AH-BR- 200WP-N-CE | \$ 1,148.00 | 10% | <i>\$1,040.95</i> |
| EW ResponsePLS NBD AHR AH-BR-200WP-N-EU | 97504-AH-BR- 200WP-N-EU | \$ 1,148.00 | 10% | <i>\$1,040.95</i> |
| EW ResponsePLS NBD AHR AH-BR-200WP-N-FCC | 97504-AH-BR- 200WP-N-FCC | \$ 1,115.00 | 10% | <i>\$1,011.03</i> |
| EW ResponsePLS NBD AHR AH-BR-200WP-N-W | 97504-AH-BR- 200WP-N-W | \$ 1,148.00 | 10% | <i>\$1,040.95</i> |
| EW ResponsePLS NBD AHR AH-SR-2024P | 97504-AH-SR- 2024P | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2124P | 97504-AH-SR- 2124P | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2148P | 97504-AH-SR- 2148P | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2208P-AU | 97504-AH-SR- 2208P-AU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2208P-EU | 97504-AH-SR- 2208P-EU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2208P-NA | 97504-AH-SR- 2208P-NA | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2208P-UK | 97504-AH-SR- 2208P-UK | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2224P-AU | 97504-AH-SR- 2224P-AU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2224P-EU | 97504-AH-SR- 2224P-EU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2224P-NA | 97504-AH-SR- 2224P-NA | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2224P-UK | 97504-AH-SR- 2224P-UK | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2324P-AU | 97504-AH-SR- 2324P-AU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2324P-EU | 97504-AH-SR- 2324P-EU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2324P-NA | 97504-AH-SR- 2324P-NA | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2324P-UK | 97504-AH-SR- 2324P-UK | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2348P-AU | 97504-AH-SR- 2348P-AU | \$ 1,096.00 | 10% | <i>\$993.80</i> |

| | | | | |
|---|---------------------------------|-------------|-----|-----------------|
| EW ResponsePLS NBD AHR AH-SR-2348P-EU | 97504-AH-SR- 2348P-EU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2348P-NA | 97504-AH-SR- 2348P-NA | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-SR-2348P-UK | 97504-AH-SR- 2348P-UK | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR200P-AU | 97504-AH- XR200P-AU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR200P-EU | 97504-AH- XR200P-EU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR200P-UK | 97504-AH- XR200P-UK | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR200P-US | 97504-AH- XR200P-US | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR600P | 97504-AH- XR600P | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR600P-AU | 97504-AH- XR600P-AU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR600P-EU | 97504-AH- XR600P-EU | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR600P-KR | 97504-AH- XR600P-KR | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR600P-UK | 97504-AH- XR600P-UK | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AH-XR600P-US | 97504-AH- XR600P-US | \$ 1,096.00 | 10% | <i>\$993.80</i> |
| EW ResponsePLS NBD AHR AP-8533-68SB30-IL | 97504-AP- 8533-68SB30- IL | \$ 349.00 | 10% | <i>\$316.46</i> |
| EW ResponsePLS NBD AHR AP3000-IL | 97504-AP3000- IL | \$ 241.74 | 10% | <i>\$219.20</i> |
| EW ResponsePLS NBD AHR AP3000-TN | 97504-AP3000- TN | \$ 241.74 | 10% | <i>\$219.20</i> |
| EW ResponsePLS NBD AHR AP3000-WW | 97504-AP3000- WW | \$ 241.74 | 10% | <i>\$219.20</i> |
| EW ResponsePLS NBD AHR AP3000X-WW | 97504- AP3000X-WW | \$ 252.99 | 10% | <i>\$229.40</i> |
| EW ResponsePLS NBD AHR AP302W-CAN | 97504- AP302W-CAN | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW ResponsePLS NBD AHR AP302W-EG | 97504- AP302W-EG | \$ 251.00 | 10% | <i>\$227.59</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR AP302W-FCC | 97504- AP302W-FCC | \$ 350.00 | 10% | \$317.36 |
| EW ResponsePLS NBD AHR AP302W-WR | 97504- AP302W-WR | \$ 333.00 | 10% | \$301.95 |
| EW ResponsePLS NBD AHR AP305C-1-CAN | 97504-AP305C- 1-CAN | \$ 343.00 | 10% | \$311.02 |
| EW ResponsePLS NBD AHR AP305C-1-EG | 97504-AP305C- 1-EG | \$ 343.00 | 10% | \$311.02 |
| EW ResponsePLS NBD AHR AP305C-1-FCC | 97504-AP305C- 1-FCC | \$ 343.00 | 10% | \$311.02 |
| EW ResponsePLS NBD AHR AP305C-1-IL | 97504-AP305C- 1-IL | \$ 343.00 | 10% | \$311.02 |
| EW ResponsePLS NBD AHR AP305C-1-WR | 97504-AP305C- 1-WR | \$ 343.00 | 10% | \$311.02 |
| EW ResponsePLS NBD AHR AP305C-CAN | 97504-AP305C- CAN | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305C-EG | 97504-AP305C- EG | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305C-FCC | 97504-AP305C- FCC | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305C-IL | 97504-AP305C- IL | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305C-WR | 97504-AP305C- WR | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305CX-CAN | 97504- AP305CX- CAN | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305CX-FCC | 97504- AP305CX- FCC | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305CX-IL | 97504- AP305CX-IL | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP305CX-WR | 97504- AP305CX-WR | \$ 369.00 | 10% | \$334.59 |
| EW ResponsePLS NBD AHR AP310e-1-WR | 97504-AP310e- 1-WR | \$ 341.00 | 10% | \$309.20 |
| EW ResponsePLS NBD AHR AP310e-CAN | 97504-AP310e- CAN | \$ 358.00 | 10% | \$324.62 |
| EW ResponsePLS NBD AHR AP310e-FCC | 97504-AP310e- FCC | \$ 358.00 | 10% | \$324.62 |

| | | | | |
|--|------------------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR AP310e-IL | 97504-AP310e- IL | \$ 358.00 | 10% | \$324.62 |
| EW ResponsePLS NBD AHR AP310e-WR | 97504-AP310e- WR | \$ 358.00 | 10% | \$324.62 |
| EW ResponsePLS NBD AHR AP310i-1-WR | 97504-AP310i- 1-WR | \$ 341.00 | 10% | \$309.20 |
| EW ResponsePLS NBD AHR AP310i-CAN | 97504-AP310i- CAN | \$ 358.00 | 10% | \$324.62 |
| EW ResponsePLS NBD AHR AP310i-FCC | 97504-AP310i- FCC | \$ 358.00 | 10% | \$324.62 |
| EW ResponsePLS NBD AHR AP310i-IL | 97504-AP310i- IL | \$ 358.00 | 10% | \$324.62 |
| EW ResponsePLS NBD AHR AP310i-WR | 97504-AP310i- WR | \$ 358.00 | 10% | \$324.62 |
| EW ResponsePLS NBD AHR AP360e-CAN | 97504-AP360e- CAN | \$ 374.00 | 10% | \$339.12 |
| EW ResponsePLS NBD AHR AP360e-FCC | 97504-AP360e- FCC | \$ 374.00 | 10% | \$339.12 |
| EW ResponsePLS NBD AHR AP360e-IL | 97504-AP360e- IL | \$ 374.00 | 10% | \$339.12 |
| EW ResponsePLS NBD AHR AP360e-WR | 97504-AP360e- WR | \$ 374.00 | 10% | \$339.12 |
| EW ResponsePLS NBD AHR AP360i-CAN | 97504-AP360i- CAN | \$ 374.00 | 10% | \$339.12 |
| EW ResponsePLS NBD AHR AP360i-FCC | 97504-AP360i- FCC | \$ 374.00 | 10% | \$339.12 |
| EW ResponsePLS NBD AHR AP360i-WR | 97504-AP360i- WR | \$ 374.00 | 10% | \$339.12 |
| EW ResponsePLS NBD AHR AP4000-WW | 97504-AP4000- 1-WW | \$ 310.00 | 10% | \$281.09 |
| EW ResponsePLS NBD AHRAP4000-IL | 97504-AP4000- IL | \$ 310.00 | 10% | \$281.09 |
| EW ResponsePLS NBD AHR AP4000-WW | 97504-AP4000- WW | \$ 310.00 | 10% | \$281.09 |
| EW ResponsePLS NBD AHR AP410C-1-CAN | 97504-AP410C- 1-CAN | \$ 324.00 | 10% | \$293.79 |
| EW ResponsePLS NBD AHR AP410C-1-EG | 97504-AP410C- 1-EG | \$ 324.00 | 10% | \$293.79 |
| EW ResponsePLS NBD AHR AP410C-1-FCC | 97504-AP410C- 1-FCC | \$ 324.00 | 10% | \$293.79 |

| | | | | |
|--|------------------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR AP410C-1-IL | 97504-AP410C- 1-IL | \$ 324.00 | 10% | <i>\$293.79</i> |
| EW ResponsePLS NBD AHR AP410C-1-WR | 97504-AP410C- 1-WR | \$ 324.00 | 10% | <i>\$293.79</i> |
| EW ResponsePLS NBD AHR AP410C-CAN | 97504-AP410C- CAN | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBD AHR AP410C-EG | 97504-AP410C- EG | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBD AHR AP410C-FCC | 97504-AP410C- FCC | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBD AHR AP410C-IL | 97504-AP410C- IL | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBD AHR AP410C-WR | 97504-AP410C- WR | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBD AHR AP410e-CAN | 97504-AP410e- CAN | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS NBD AHR AP410e-FCC | 97504-AP410e- FCC | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS NBD AHR AP410e-WR | 97504-AP410e- WR | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS NBD AHR AP410i-1-FCC | 97504-AP410i- 1-FCC | \$ 359.00 | 10% | <i>\$325.52</i> |
| EW ResponsePLS NBD AHR AP410i-1-WR | 97504-AP410i- 1-WR | \$ 359.00 | 10% | <i>\$325.52</i> |
| EW ResponsePLS NBD AHR AP410i-CAN | 97504-AP410i- CAN | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS NBD AHR AP410i-FCC | 97504-AP410i- FCC | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS NBD AHR AP410i-IL | 97504-AP410i- IL | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS NBD AHR AP410i-WR | 97504-AP410i- WR | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS NBD AHR AP460C-CAN | 97504-AP460C- CAN | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460C-EG | 97504-AP460C- EG | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460C-FCC | 97504-AP460C- FCC | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460C-IL | 97504-AP460C- IL | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460C-WR | 97504-AP460C- WR | \$ 357.00 | 10% | <i>\$323.71</i> |

| | | | | |
|---|-----------------------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR AP460e-CAN | 97504-AP460e- CAN | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR AP460e-FCC | 97504-AP460e- FCC | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR AP460e-WR | 97504-AP460e- WR | \$ 370.00 | 10% | <i>\$335.50</i> |
| EW ResponsePLS NBD AHR AP460i-CAN | 97504-AP460i- CAN | \$ 370.00 | 10% | <i>\$335.50</i> |
| EW ResponsePLS NBD AHR AP460i-FCC | 97504-AP460i- FCC | \$ 370.00 | 10% | <i>\$335.50</i> |
| EW ResponsePLS NBD AHR AP460i-IL | 97504-AP460i- IL | \$ 370.00 | 10% | <i>\$335.50</i> |
| EW ResponsePLS NBD AHR AP460i-WR | 97504-AP460i- WR | \$ 370.00 | 10% | <i>\$335.50</i> |
| EW ResponsePLS NBD AHR AP460S12C-CAN | 97504- AP460S12C- CAN | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460S12C-FCC | 97504- AP460S12C- FCC | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460S12C-WR | 97504- AP460S12C- WR | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460S6C-CAN | 97504- AP460S6C- CAN | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460S6C-FCC | 97504- AP460S6C- FCC | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP460S6C-WR | 97504- AP460S6C- WR | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS NBD AHR AP5010-IL | 97504-AP5010- IL | \$ 320.00 | 10% | <i>\$290.16</i> |
| EW ResponsePLS NBD AHR AP5010-WW | 97504-AP5010- WW | \$ 320.00 | 10% | <i>\$290.16</i> |
| EW ResponsePLS NBD AHR AP5020-WW | 97504-AP5020- WW | \$ 309.20 | 6% | <i>\$292.83</i> |
| EW ResponsePLS NBD AHR AP5050D-WW | 97504- AP5050D-WW | \$ 446.00 | 10% | <i>\$404.41</i> |
| EW ResponsePLS NBD AHR AP5050U-WW | 97504- AP5050U-WW | \$ 392.00 | 10% | <i>\$355.45</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR AP505i-FCC | 97504-AP505i- FCC | \$ 370.00 | 10% | \$335.50 |
| EW ResponsePLS NBD AHR AP505i-FCC-TAA | 97504-AP505i- FCC-TAA | \$ 370.00 | 10% | \$335.50 |
| EW ResponsePLS NBD AHR AP505i-WR | 97504-AP505i- WR | \$ 388.00 | 10% | \$351.82 |
| EW ResponsePLS NBD AHR AP510C-CAN | 97504-AP510C- CAN | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510C-CE | 97504-AP510C- CE | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510C-FCC | 97504-AP510C- FCC | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510C-W | 97504-AP510C- W | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510C-WW | 97504-AP510C- WW | \$ 383.00 | 10% | \$347.29 |
| EW ResponsePLS NBD AHR AP510CX-CAN | 97504- AP510CX- CAN | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510CX-CE | 97504- AP510CX-CE | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510CX-FCC | 97504- AP510CX- FCC | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510CX-W | 97504- AP510CX-W | \$ 289.00 | 10% | \$262.05 |
| EW ResponsePLS NBD AHR AP510CX-WW | 97504- AP510CX-WW | \$ 383.00 | 10% | \$347.29 |
| EW ResponsePLS NBD AHR AP510e-FCC | 97504-AP510e- FCC | \$ 411.00 | 10% | \$372.67 |
| EW ResponsePLS NBD AHR AP510e-FCC-TAA | 97504-AP510e- FCC-TAA | \$ 411.00 | 10% | \$372.67 |
| EW ResponsePLS NBD AHR AP510e-WR | 97504-AP510e- WR | \$ 391.00 | 10% | \$354.54 |
| EW ResponsePLS NBD AHR AP510i-1-FCC | 97504-AP510i- 1-FCC | \$ 380.00 | 10% | \$344.57 |
| EW ResponsePLS NBD AHR AP510i-1-WR | 97504-AP510i- 1-WR | \$ 380.00 | 10% | \$344.57 |
| EW ResponsePLS NBD AHR AP510i-FCC | 97504-AP510i- FCC | \$ 399.00 | 10% | \$361.79 |

| | | | | |
|--|--------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR AP510i-FCC-TAA | 97504-AP510i- FCC-TAA | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW ResponsePLS NBD AHR AP510i-WR | 97504-AP510i- WR | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW ResponsePLS NBD AHR AP560h-FCC | 97504-AP560h- FCC | \$ 549.00 | 10% | <i>\$497.81</i> |
| EW ResponsePLS NBD AHR AP560h-WR | 97504-AP560h- WR | \$ 549.00 | 10% | <i>\$497.81</i> |
| EW ResponsePLS NBD AHR AP560i-FCC | 97504-AP560i- FCC | \$ 479.00 | 10% | <i>\$434.33</i> |
| EW ResponsePLS NBD AHR AP560i-WR | 97504-AP560i- WR | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW ResponsePLS NBD AHR AP560m-FCC | 97504-AP560m- FCC | \$ 479.00 | 10% | <i>\$434.33</i> |
| EW ResponsePLS NBD AHR AP560t-FCC | 97504-AP560t- FCC | \$ 549.00 | 10% | <i>\$497.81</i> |
| EW ResponsePLS NBD AHR AP560u-FCC | 97504-AP560u- FCC | \$ 446.00 | 10% | <i>\$404.41</i> |
| EW ResponsePLS NBD AHR E2122 | 97504-E2122 | \$ 5,351.00 | 10% | <i>\$4,852.02</i> |
| EW ResponsePLS NBD AHR E2122-1 | 97504-E2122-1 | \$ 5,072.00 | 10% | <i>\$4,599.04</i> |
| EW ResponsePLS NBD AHR E3120-1 | 97504-E3120-1 | \$ 7,614.00 | 10% | <i>\$6,903.99</i> |
| EW ResponsePLS NBD AHR E3125 | 97504-E3125 | \$ 8,537.00 | 10% | <i>\$7,740.92</i> |
| EW ResponsePLS NBD AHR- H30003 | 97504-H30003 | \$ 873.00 | 10% | <i>\$791.59</i> |
| EW ResponsePLS NBD AHR- H30004 | 97504-H30004 | \$ 886.00 | 10% | <i>\$803.38</i> |
| EW ResponsePLS NBD AHR- H30005 | 97504-H30005 | \$ 1,266.00 | 10% | <i>\$1,147.95</i> |
| EW ResponsePLS NBD AHR- H30006 | 97504-H30006 | \$ 1,313.00 | 10% | <i>\$1,190.56</i> |
| EW ResponsePLS NBD AHR- H30007 | 97504-H30007 | \$ 1,307.00 | 10% | <i>\$1,185.12</i> |
| EW ResponsePLS NBD AHR- H30008 | 97504-H30008 | \$ 1,374.00 | 10% | <i>\$1,245.87</i> |
| EW ResponsePLS NBD AHR- H30009 | 97504-H30009 | \$ 1,258.00 | 10% | <i>\$1,140.69</i> |
| EW ResponsePLS NBD AHR- H30010 | 97504-H30010 | \$ 1,293.00 | 10% | <i>\$1,172.43</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-H30011 | 97504-H30011 | \$ 1,279.00 | 10% | <i>\$1,159.73</i> |
| EW ResponsePLS NBD AHR-H30012 | 97504-H30012 | \$ 1,326.00 | 10% | <i>\$1,202.35</i> |
| EW ResponsePLS NBD AHR-H30131 | 97504-H30131 | \$ 2,027.00 | 10% | <i>\$1,837.98</i> |
| EW ResponsePLS NBD AHR-H30132 | 97504-H30132 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |
| EW ResponsePLS NBD AHR-H30133 | 97504-H30133 | \$ 3,353.00 | 10% | <i>\$3,040.33</i> |
| EW ResponsePLS NBD AHR-H30134 | 97504-H30134 | \$ 3,938.00 | 10% | <i>\$3,570.78</i> |
| EW ResponsePLS NBD AHR-H30135 | 97504-H30135 | \$ 3,417.00 | 10% | <i>\$3,098.36</i> |
| EW ResponsePLS NBD AHR-H30136 | 97504-H30136 | \$ 3,938.00 | 10% | <i>\$3,570.78</i> |
| EW ResponsePLS NBD AHR-H30184 | 97504-H30184 | \$ 1,242.00 | 10% | <i>\$1,126.18</i> |
| EW ResponsePLS NBD AHR-H30185 | 97504-H30185 | \$ 1,430.00 | 10% | <i>\$1,296.65</i> |
| EW ResponsePLS NBD AHR-H30186 | 97504-H30186 | \$ 1,333.00 | 10% | <i>\$1,208.70</i> |
| EW ResponsePLS NBD AHR-H30187 | 97504-H30187 | \$ 1,352.00 | 10% | <i>\$1,225.93</i> |
| EW ResponsePLS NBD AHR-H30188 | 97504-H30188 | \$ 1,333.00 | 10% | <i>\$1,208.70</i> |
| EW ResponsePLS NBD AHR-H30189 | 97504-H30189 | \$ 1,333.00 | 10% | <i>\$1,208.70</i> |
| EW ResponsePLS NBD AHR-H30190 | 97504-H30190 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30214 | 97504-H30214 | \$ 1,425.00 | 10% | <i>\$1,292.12</i> |
| EW ResponsePLS NBD AHR-H30215 | 97504-H30215 | \$ 1,425.00 | 10% | <i>\$1,292.12</i> |
| EW ResponsePLS NBD AHR-H30216 | 97504-H30216 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30217 | 97504-H30217 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30218 | 97504-H30218 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30219 | 97504-H30219 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-H30220 | 97504-H30220 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30221 | 97504-H30221 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30222 | 97504-H30222 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30223 | 97504-H30223 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30224 | 97504-H30224 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30225 | 97504-H30225 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30226 | 97504-H30226 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30227 | 97504-H30227 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30228 | 97504-H30228 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30229 | 97504-H30229 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30267 | 97504-H30267 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30268 | 97504-H30268 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsePLS NBD AHR-H30269 | 97504-H30269 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30270 | 97504-H30270 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30271 | 97504-H30271 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30272 | 97504-H30272 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30273 | 97504-H30273 | \$ 1,778.00 | 10% | <i>\$1,612.20</i> |
| EW ResponsePLS NBD AHR-H30274 | 97504-H30274 | \$ 1,778.00 | 10% | <i>\$1,612.20</i> |
| EW ResponsePLS NBD AHR-H30275 | 97504-H30275 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30276 | 97504-H30276 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30277 | 97504-H30277 | \$ 1,778.00 | 10% | <i>\$1,612.20</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-H30278 | 97504-H30278 | \$ 1,822.00 | 10% | <i>\$1,652.10</i> |
| EW ResponsePLS NBD AHR-H30279 | 97504-H30279 | \$ 1,778.00 | 10% | <i>\$1,612.20</i> |
| EW ResponsePLS NBD AHR-H30280 | 97504-H30280 | \$ 1,778.00 | 10% | <i>\$1,612.20</i> |
| EW ResponsePLS NBD AHR-H30281 | 97504-H30281 | \$ 1,778.00 | 10% | <i>\$1,612.20</i> |
| EW ResponsePLS NBD AHR-H30282 | 97504-H30282 | \$ 1,778.00 | 10% | <i>\$1,612.20</i> |
| EW ResponsePLS NBD AHR-H30283 | 97504-H30283 | \$ 1,509.00 | 10% | <i>\$1,368.29</i> |
| EW ResponsePLS NBD AHR-H30284 | 97504-H30284 | \$ 1,660.00 | 10% | <i>\$1,505.21</i> |
| EW ResponsePLS NBD AHR-H30296 | 97504-H30296 | \$ 1,425.00 | 10% | <i>\$1,292.12</i> |
| EW ResponsePLS NBD AHR-H30297 | 97504-H30297 | \$ 1,425.00 | 10% | <i>\$1,292.12</i> |
| EW ResponsePLS NBD AHR-H30298 | 97504-H30298 | \$ 1,425.00 | 10% | <i>\$1,292.12</i> |
| EW ResponsePLS NBD AHR-H30299 | 97504-H30299 | \$ 1,425.00 | 10% | <i>\$1,292.12</i> |
| EW ResponsePLS NBD AHR-H30381 | 97504-H30381 | \$ 2,447.00 | 10% | <i>\$2,218.82</i> |
| EW ResponsePLS NBD AHR-H30384 | 97504-H30384 | \$ 2,388.00 | 10% | <i>\$2,165.32</i> |
| EW ResponsePLS NBD AHR-H30391 | 97504-H30391 | \$ 1,004.00 | 10% | <i>\$910.38</i> |
| EW ResponsePLS NBD AHR-H30392 | 97504-H30392 | \$ 1,004.00 | 10% | <i>\$910.38</i> |
| EW ResponsePLS NBD AHR-H30393 | 97504-H30393 | \$ 683.00 | 10% | <i>\$619.31</i> |
| EW ResponsePLS NBD AHR-H30394 | 97504-H30394 | \$ 1,538.00 | 10% | <i>\$1,394.58</i> |
| EW ResponsePLS NBD AHR-H30395 | 97504-H30395 | \$ 1,759.00 | 10% | <i>\$1,594.97</i> |
| EW ResponsePLS NBD AHR-H30396 | 97504-H30396 | \$ 1,629.00 | 10% | <i>\$1,477.10</i> |
| EW ResponsePLS NBD AHR-H30397 | 97504-H30397 | \$ 1,864.00 | 10% | <i>\$1,690.18</i> |
| EW ResponsePLS NBD AHR-H30398 | 97504-H30398 | \$ 696.00 | 10% | <i>\$631.10</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-H30400 | 97504-H30400 | \$ 572.00 | 10% | <i>\$518.66</i> |
| EW ResponsePLS NBD AHR-H30401 | 97504-H30401 | \$ 637.00 | 10% | <i>\$577.60</i> |
| EW ResponsePLS NBD AHR-H30402 | 97504-H30402 | \$ 644.00 | 10% | <i>\$583.95</i> |
| EW ResponsePLS NBD AHR-H30403 | 97504-H30403 | \$ 747.00 | 10% | <i>\$677.34</i> |
| EW ResponsePLS NBD AHR-H30480 | 97504-H30480 | \$ 2,478.00 | 10% | <i>\$2,246.93</i> |
| EW ResponsePLS NBD AHR-H30495 | 97504-H30495 | \$ 2,990.00 | 10% | <i>\$2,711.18</i> |
| EW ResponsePLS NBD AHR-H30496 | 97504-H30496 | \$ 2,934.00 | 10% | <i>\$2,660.40</i> |
| EW ResponsePLS NBD AHR-H30497 | 97504-H30497 | \$ 3,372.00 | 10% | <i>\$3,057.56</i> |
| EW ResponsePLS NBD AHR-H30498 | 97504-H30498 | \$ 3,308.00 | 10% | <i>\$2,999.53</i> |
| EW ResponsePLS NBD AHR-H30499 | 97504-H30499 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW ResponsePLS NBD AHR-H30501 | 97504-H30501 | \$ 3,308.00 | 10% | <i>\$2,999.53</i> |
| EW ResponsePLS NBD AHR-H30502 | 97504-H30502 | \$ 3,957.00 | 10% | <i>\$3,588.01</i> |
| EW ResponsePLS NBD AHR-H30503 | 97504-H30503 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW ResponsePLS NBD AHR-H30505 | 97504-H30505 | \$ 4,297.00 | 10% | <i>\$3,896.30</i> |
| EW ResponsePLS NBD AHR-H30506 | 97504-H30506 | \$ 5,089.00 | 10% | <i>\$4,614.45</i> |
| EW ResponsePLS NBD AHR-H30509 | 97504-H30509 | \$ 3,957.00 | 10% | <i>\$3,588.01</i> |
| EW ResponsePLS NBD AHR-H30510 | 97504-H30510 | \$ 4,297.00 | 10% | <i>\$3,896.30</i> |
| EW ResponsePLS NBD AHR-H30511 | 97504-H30511 | \$ 5,089.00 | 10% | <i>\$4,614.45</i> |
| EW ResponsePLS NBD AHR-H30512 | 97504-H30512 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW ResponsePLS NBD AHR-H30513 | 97504-H30513 | \$ 1,129.00 | 10% | <i>\$1,023.72</i> |
| EW ResponsePLS NBD AHR-H30525 | 97504-H30525 | \$ 3,411.00 | 10% | <i>\$3,092.92</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-H30526 | 97504-H30526 | \$ 2,626.00 | 10% | <i>\$2,381.13</i> |
| EW ResponsePLS NBD AHR-H30528 | 97504-H30528 | \$ 3,892.00 | 10% | <i>\$3,529.07</i> |
| EW ResponsePLS NBD AHR-H30531 | 97504-H30531 | \$ 5,360.00 | 10% | <i>\$4,860.18</i> |
| EW ResponsePLS NBD AHR-H30532 | 97504-H30532 | \$ 5,360.00 | 10% | <i>\$4,860.18</i> |
| EW ResponsePLS NBD AHR-H30534 | 97504-H30534 | \$ 5,463.00 | 10% | <i>\$4,953.58</i> |
| EW ResponsePLS NBD AHR-H30535 | 97504-H30535 | \$ 5,791.00 | 10% | <i>\$5,250.99</i> |
| EW ResponsePLS NBD AHR-H30536 | 97504-H30536 | \$ 5,360.00 | 10% | <i>\$4,860.18</i> |
| EW ResponsePLS NBD AHR-H30537 | 97504-H30537 | \$ 5,791.00 | 10% | <i>\$5,250.99</i> |
| EW ResponsePLS NBD AHR-H30538 | 97504-H30538 | \$ 3,411.00 | 10% | <i>\$3,092.92</i> |
| EW ResponsePLS NBD AHR-H30539 | 97504-H30539 | \$ 6,184.00 | 10% | <i>\$5,607.34</i> |
| EW ResponsePLS NBD AHR-H30540 | 97504-H30540 | \$ 6,362.00 | 10% | <i>\$5,768.74</i> |
| EW ResponsePLS NBD AHR-H30543 | 97504-H30543 | \$ 831.00 | 10% | <i>\$753.51</i> |
| EW ResponsePLS NBD AHR-H30544 | 97504-H30544 | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW ResponsePLS NBD AHR-H30548 | 97504-H30548 | \$ 831.00 | 10% | <i>\$753.51</i> |
| EW ResponsePLS NBD AHR-H30549 | 97504-H30549 | \$ 1,108.00 | 10% | <i>\$1,004.68</i> |
| EW ResponsePLS NBD AHR-H30550 | 97504-H30550 | \$ 1,108.00 | 10% | <i>\$1,004.68</i> |
| EW ResponsePLS NBD AHR-H30552 | 97504-H30552 | \$ 831.00 | 10% | <i>\$753.51</i> |
| EW ResponsePLS NBD AHR-H30553 | 97504-H30553 | \$ 1,069.00 | 10% | <i>\$969.32</i> |
| EW ResponsePLS NBD AHR-H30569 | 97504-H30569 | \$ 3,353.00 | 10% | <i>\$3,040.33</i> |
| EW ResponsePLS NBD AHR-H30570 | 97504-H30570 | \$ 3,810.00 | 10% | <i>\$3,454.72</i> |
| EW ResponsePLS NBD AHR-H30571 | 97504-H30571 | \$ 3,810.00 | 10% | <i>\$3,454.72</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR-H30573 | 97504-H30573 | \$ 3,353.00 | 10% | <i>\$3,040.33</i> |
| EW ResponsePLS NBD AHR-H30574 | 97504-H30574 | \$ 3,608.00 | 10% | <i>\$3,271.55</i> |
| EW ResponsePLS NBD AHR-H30575 | 97504-H30575 | \$ 2,669.00 | 10% | <i>\$2,420.12</i> |
| EW ResponsePLS NBD AHR-H30576 | 97504-H30576 | \$ 3,353.00 | 10% | <i>\$3,040.33</i> |
| EW ResponsePLS NBD AHR-H30577 | 97504-H30577 | \$ 3,738.00 | 10% | <i>\$3,389.43</i> |
| EW ResponsePLS NBD AHR-H30578 | 97504-H30578 | \$ 3,738.00 | 10% | <i>\$3,389.43</i> |
| EW ResponsePLS NBD AHR-H30587 | 97504-H30587 | \$ 2,676.00 | 10% | <i>\$2,426.46</i> |
| EW ResponsePLS NBD AHR-H30588 | 97504-H30588 | \$ 1,982.00 | 10% | <i>\$1,797.18</i> |
| EW ResponsePLS NBD AHR-H30589 | 97504-H30589 | \$ 2,859.00 | 10% | <i>\$2,592.40</i> |
| EW ResponsePLS NBD AHR-H30632 | 97504-H30632 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsePLS NBD AHR-H30633 | 97504-H30633 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsePLS NBD AHR-H30643 | 97504-H30643 | \$ 6,294.00 | 10% | <i>\$5,707.08</i> |
| EW ResponsePLS NBD AHR-H30706 | 97504-H30706 | \$ 3,968.00 | 10% | <i>\$3,597.98</i> |
| EW ResponsePLS NBD AHR-H30707 | 97504-H30707 | \$ 2,626.00 | 10% | <i>\$2,381.13</i> |
| EW ResponsePLS NBD AHR-H30724 | 97504-H30724 | \$ 571.00 | 10% | <i>\$517.75</i> |
| EW ResponsePLS NBD AHR-H30725 | 97504-H30725 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |
| EW ResponsePLS NBD AHR-H30726 | 97504-H30726 | \$ 5,903.00 | 10% | <i>\$5,352.55</i> |
| EW ResponsePLS NBD AHR-H30727 | 97504-H30727 | \$ 6,241.00 | 10% | <i>\$5,659.03</i> |
| EW ResponsePLS NBD AHR-H30730 | 97504-H30730 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR-H30731 | 97504-H30731 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR-H30733 | 97504-H30733 | \$ 6,512.00 | 10% | <i>\$5,904.76</i> |

| | | | | |
|-------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR-H30734 | 97504-H30734 | \$ 5,063.00 | 10% | <i>\$4,590.88</i> |
| EW ResponsePLS NBD AHR-H30735 | 97504-H30735 | \$ 5,567.00 | 10% | <i>\$5,047.88</i> |
| EW ResponsePLS NBD AHR-H30736 | 97504-H30736 | \$ 1,248.00 | 10% | <i>\$1,131.62</i> |
| EW ResponsePLS NBD AHR-H30738 | 97504-H30738 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsePLS NBD AHR H30787 | 97504-H30787 | \$ 282.00 | 10% | <i>\$255.70</i> |
| EW ResponsePLS NBD AHR H30847 | 97504-H30847 | \$ 290.00 | 10% | <i>\$262.96</i> |
| EW ResponsePLS NBD AHR H30852 | 97504-H30852 | \$ 290.00 | 10% | <i>\$262.96</i> |
| EW ResponsePLS NBD AHR H30857 | 97504-H30857 | \$ 326.00 | 10% | <i>\$295.60</i> |
| EW ResponsePLS NBD AHR H31337 | 97504-H31337 | \$ 9,763.00 | 10% | <i>\$8,852.60</i> |
| EW ResponsePLS NBD AHR H31338 | 97504-H31338 | \$ 9,763.00 | 10% | <i>\$8,852.60</i> |
| EW ResponsePLS NBD AHR H31341 | 97504-H31341 | \$ 5,393.00 | 10% | <i>\$4,890.10</i> |
| EW ResponsePLS NBD AHR H31342 | 97504-H31342 | \$ 1,456.00 | 10% | <i>\$1,320.23</i> |
| EW ResponsePLS NBD AHR H31343 | 97504-H31343 | \$ 1,952.00 | 10% | <i>\$1,769.98</i> |
| EW ResponsePLS NBD AHR H31344 | 97504-H31344 | \$ 1,952.00 | 10% | <i>\$1,769.98</i> |
| EW ResponsePLS NBD AHR H31345 | 97504-H31345 | \$ 1,952.00 | 10% | <i>\$1,769.98</i> |
| EW ResponsePLS NBD AHR H31346 | 97504-H31346 | \$ 1,952.00 | 10% | <i>\$1,769.98</i> |
| EW ResponsePLS NBD AHR H31362 | 97504-H31362 | \$ 22,616.00 | 10% | <i>\$20,507.06</i> |
| EW ResponsePLS NBD AHR H31363 | 97504-H31363 | \$ 22,616.00 | 10% | <i>\$20,507.06</i> |
| EW ResponsePLS NBD AHR H31364 | 97504-H31364 | \$ 8,713.00 | 10% | <i>\$7,900.51</i> |
| EW ResponsePLS NBD AHR H31365 | 97504-H31365 | \$ 8,713.00 | 10% | <i>\$7,900.51</i> |
| EW ResponsePLS NBD AHR H31366 | 97504-H31366 | \$ 12,054.00 | 10% | <i>\$10,929.96</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR H31367 | 97504-H31367 | \$ 12,054.00 | 10% | <i>\$10,929.96</i> |
| EW ResponsePLS NBD AHR H32010 | 97504-H32010 | \$ 1,664.00 | 10% | <i>\$1,508.83</i> |
| EW ResponsePLS NBD AHR H32011 | 97504-H32011 | \$ 1,664.00 | 10% | <i>\$1,508.83</i> |
| EW ResponsePLS NBD AHR H32012 | 97504-H32012 | \$ 3,098.00 | 10% | <i>\$2,809.11</i> |
| EW ResponsePLS NBD AHR H32013 | 97504-H32013 | \$ 3,191.00 | 10% | <i>\$2,893.44</i> |
| EW ResponsePLS NBD AHR H32014 | 97504-H32014 | \$ 3,191.00 | 10% | <i>\$2,893.44</i> |
| EW ResponsePLS NBD AHR H32015 | 97504-H32015 | \$ 3,191.00 | 10% | <i>\$2,893.44</i> |
| EW ResponsePLS NBD AHR H32016 | 97504-H32016 | \$ 2,964.00 | 10% | <i>\$2,687.61</i> |
| EW ResponsePLS NBD AHR H32017 | 97504-H32017 | \$ 2,964.00 | 10% | <i>\$2,687.61</i> |
| EW ResponsePLS NBD AHR H32018 | 97504-H32018 | \$ 2,964.00 | 10% | <i>\$2,687.61</i> |
| EW ResponsePLS NBD AHR H32019 | 97504-H32019 | \$ 2,964.00 | 10% | <i>\$2,687.61</i> |
| EW ResponsePLS NBD AHR H32020 | 97504-H32020 | \$ 22,853.00 | 10% | <i>\$20,721.96</i> |
| EW ResponsePLS NBD AHR H32021 | 97504-H32021 | \$ 22,853.00 | 10% | <i>\$20,721.96</i> |
| EW ResponsePLS NBD AHR H32022 | 97504-H32022 | \$ 22,853.00 | 10% | <i>\$20,721.96</i> |
| EW ResponsePLS NBD AHR H32023 | 97504-H32023 | \$ 22,853.00 | 10% | <i>\$20,721.96</i> |
| EW ResponsePLS NBD AHR H32028 | 97504-H32028 | \$ 42,204.00 | 10% | <i>\$38,268.48</i> |
| EW ResponsePLS NBD AHR H32029 | 97504-H32029 | \$ 42,204.00 | 10% | <i>\$38,268.48</i> |
| EW ResponsePLS NBD AHR H32030 | 97504-H32030 | \$ 44,260.00 | 10% | <i>\$40,132.76</i> |
| EW ResponsePLS NBD AHR H32031 | 97504-H32031 | \$ 44,260.00 | 10% | <i>\$40,132.76</i> |
| EW ResponsePLS NBD AHR H32032 | 97504-H32032 | \$ 44,260.00 | 10% | <i>\$40,132.76</i> |
| EW ResponsePLS NBD AHR H32033 | 97504-H32033 | \$ 44,260.00 | 10% | <i>\$40,132.76</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR H32038 | 97504-H32038 | \$ 8,731.00 | 10% | <i>\$7,916.83</i> |
| EW ResponsePLS NBD AHR H32039 | 97504-H32039 | \$ 8,731.00 | 10% | <i>\$7,916.83</i> |
| EW ResponsePLS NBD AHR H32040 | 97504-H32040 | \$ 8,731.00 | 10% | <i>\$7,916.83</i> |
| EW ResponsePLS NBD AHR H32041 | 97504-H32041 | \$ 8,731.00 | 10% | <i>\$7,916.83</i> |
| EW ResponsePLS NBD AHR H32046 | 97504-H32046 | \$ 12,079.00 | 10% | <i>\$10,952.63</i> |
| EW ResponsePLS NBD AHR H32047 | 97504-H32047 | \$ 12,079.00 | 10% | <i>\$10,952.63</i> |
| EW ResponsePLS NBD AHR H32048 | 97504-H32048 | \$ 12,079.00 | 10% | <i>\$10,952.63</i> |
| EW ResponsePLS NBD AHR H32049 | 97504-H32049 | \$ 12,079.00 | 10% | <i>\$10,952.63</i> |
| EW ResponsePLS NBD AHR H32054 | 97504-H32054 | \$ 8,731.00 | 10% | <i>\$7,916.83</i> |
| EW ResponsePLS NBD AHR H32055 | 97504-H32055 | \$ 12,079.00 | 10% | <i>\$10,952.63</i> |
| EW ResponsePLS NBD AHR H32056 | 97504-H32056 | \$ 3,256.00 | 10% | <i>\$2,952.38</i> |
| EW ResponsePLS NBD AHR H32057 | 97504-H32057 | \$ 3,354.00 | 10% | <i>\$3,041.24</i> |
| EW ResponsePLS NBD AHR H32058 | 97504-H32058 | \$ 3,354.00 | 10% | <i>\$3,041.24</i> |
| EW ResponsePLS NBD AHR H32059 | 97504-H32059 | \$ 3,354.00 | 10% | <i>\$3,041.24</i> |
| EW ResponsePLS NBD AHR H32060 | 97504-H32060 | \$ 3,613.00 | 10% | <i>\$3,276.09</i> |
| EW ResponsePLS NBD AHR H32061 | 97504-H32061 | \$ 3,794.00 | 10% | <i>\$3,440.21</i> |
| EW ResponsePLS NBD AHR H32062 | 97504-H32062 | \$ 3,648.00 | 10% | <i>\$3,307.82</i> |
| EW ResponsePLS NBD AHR H32063 | 97504-H32063 | \$ 3,618.00 | 10% | <i>\$3,280.62</i> |
| EW ResponsePLS NBD AHR H32064 | 97504-H32064 | \$ 3,648.00 | 10% | <i>\$3,307.82</i> |
| EW ResponsePLS NBD AHR H32065 | 97504-H32065 | \$ 3,912.00 | 10% | <i>\$3,547.21</i> |
| EW ResponsePLS NBD AHR H32066 | 97504-H32066 | \$ 3,912.00 | 10% | <i>\$3,547.21</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR H32067 | 97504-H32067 | \$ 3,914.00 | 10% | <i>\$3,549.02</i> |
| EW ResponsePLS NBD AHR H32068 | 97504-H32068 | \$ 3,914.00 | 10% | <i>\$3,549.02</i> |
| EW ResponsePLS NBD AHR H32069 | 97504-H32069 | \$ 4,505.00 | 10% | <i>\$4,084.91</i> |
| EW ResponsePLS NBD AHR H32070 | 97504-H32070 | \$ 4,505.00 | 10% | <i>\$4,084.91</i> |
| EW ResponsePLS NBD AHR H32071 | 97504-H32071 | \$ 4,505.00 | 10% | <i>\$4,084.91</i> |
| EW ResponsePLS NBD AHR H32072 | 97504-H32072 | \$ 4,505.00 | 10% | <i>\$4,084.91</i> |
| EW ResponsePLS NBD AHR H32073 | 97504-H32073 | \$ 25,481.00 | 10% | <i>\$23,104.90</i> |
| EW ResponsePLS NBD AHR H32074 | 97504-H32074 | \$ 25,481.00 | 10% | <i>\$23,104.90</i> |
| EW ResponsePLS NBD AHR H32075 | 97504-H32075 | \$ 34,680.00 | 10% | <i>\$31,446.09</i> |
| EW ResponsePLS NBD AHR H32076 | 97504-H32076 | \$ 34,680.00 | 10% | <i>\$31,446.09</i> |
| EW ResponsePLS NBD AHR H32101 | 97504-H32101 | \$ 2,524.00 | 10% | <i>\$2,288.64</i> |
| EW ResponsePLS NBD AHR H32102 | 97504-H32102 | \$ 2,524.00 | 10% | <i>\$2,288.64</i> |
| EW ResponsePLS NBD AHR H32103 | 97504-H32103 | \$ 2,524.00 | 10% | <i>\$2,288.64</i> |
| EW ResponsePLS NBD AHR H32104 | 97504-H32104 | \$ 2,524.00 | 10% | <i>\$2,288.64</i> |
| EW ResponsePLS NBD AHR H32105 | 97504-H32105 | \$ 3,510.00 | 10% | <i>\$3,182.69</i> |
| EW ResponsePLS NBD AHR H32106 | 97504-H32106 | \$ 3,510.00 | 10% | <i>\$3,182.69</i> |
| EW ResponsePLS NBD AHR H32107 | 97504-H32107 | \$ 6,891.00 | 10% | <i>\$6,248.41</i> |
| EW ResponsePLS NBD AHR H32108 | 97504-H32108 | \$ 6,891.00 | 10% | <i>\$6,248.41</i> |
| EW ResponsePLS NBD AHR H32109 | 97504-H32109 | \$ 3,510.00 | 10% | <i>\$3,182.69</i> |
| EW ResponsePLS NBD AHR H32110 | 97504-H32110 | \$ 3,510.00 | 10% | <i>\$3,182.69</i> |
| EW ResponsePLS NBD AHR H32111 | 97504-H32111 | \$ 2,524.00 | 10% | <i>\$2,288.64</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|------------|
| EW ResponsePLS NBD AHR H32112 | 97504-H32112 | \$ 2,524.00 | 10% | \$2,288.64 |
| EW ResponsePLS NBD AHR H32113 | 97504-H32113 | \$ 2,524.00 | 10% | \$2,288.64 |
| EW ResponsePLS NBD AHR H32114 | 97504-H32114 | \$ 2,524.00 | 10% | \$2,288.64 |
| EW ResponsePLS NBD AHR H32115 | 97504-H32115 | \$ 3,510.00 | 10% | \$3,182.69 |
| EW ResponsePLS NBD AHR H32116 | 97504-H32116 | \$ 3,510.00 | 10% | \$3,182.69 |
| EW ResponsePLS NBD AHR H32117 | 97504-H32117 | \$ 2,460.00 | 10% | \$2,230.61 |
| EW ResponsePLS NBD AHR H32118 | 97504-H32118 | \$ 2,460.00 | 10% | \$2,230.61 |
| EW ResponsePLS NBD AHR H32119 | 97504-H32119 | \$ 2,460.00 | 10% | \$2,230.61 |
| EW ResponsePLS NBD AHR H32120 | 97504-H32120 | \$ 2,460.00 | 10% | \$2,230.61 |
| EW ResponsePLS NBD AHR H32121 | 97504-H32121 | \$ 6,891.00 | 10% | \$6,248.41 |
| EW ResponsePLS NBD AHR H32122 | 97504-H32122 | \$ 6,891.00 | 10% | \$6,248.41 |
| EW ResponsePLS NBD AHR H32123 | 97504-H32123 | \$ 3,511.00 | 10% | \$3,183.60 |
| EW ResponsePLS NBD AHR H32124 | 97504-H32124 | \$ 3,511.00 | 10% | \$3,183.60 |
| EW ResponsePLS NBD AHR H32125 | 97504-H32125 | \$ 3,381.00 | 10% | \$3,065.72 |
| EW ResponsePLS NBD AHR H32126 | 97504-H32126 | \$ 3,381.00 | 10% | \$3,065.72 |
| EW ResponsePLS NBD AHR H32127 | 97504-H32127 | \$ 3,724.00 | 10% | \$3,376.74 |
| EW ResponsePLS NBD AHR H32128 | 97504-H32128 | \$ 3,724.00 | 10% | \$3,376.74 |
| EW ResponsePLS NBD AHR H32129 | 97504-H32129 | \$ 3,724.00 | 10% | \$3,376.74 |
| EW ResponsePLS NBD AHR H32130 | 97504-H32130 | \$ 3,724.00 | 10% | \$3,376.74 |
| EW ResponsePLS NBD AHR H32131 | 97504-H32131 | \$ 3,724.00 | 10% | \$3,376.74 |
| EW ResponsePLS NBD AHR H32132 | 97504-H32132 | \$ 3,724.00 | 10% | \$3,376.74 |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR H32133 | 97504-H32133 | \$ 3,381.00 | 10% | <i>\$3,065.72</i> |
| EW ResponsePLS NBD AHR H32134 | 97504-H32134 | \$ 3,381.00 | 10% | <i>\$3,065.72</i> |
| EW ResponsePLS NBD AHR H32135 | 97504-H32135 | \$ 3,381.00 | 10% | <i>\$3,065.72</i> |
| EW ResponsePLS NBD AHR H32136 | 97504-H32136 | \$ 3,381.00 | 10% | <i>\$3,065.72</i> |
| EW ResponsePLS NBD AHR H32137 | 97504-H32137 | \$ 3,381.00 | 10% | <i>\$3,065.72</i> |
| EW ResponsePLS NBD AHR H32138 | 97504-H32138 | \$ 3,381.00 | 10% | <i>\$3,065.72</i> |
| EW ResponsePLS NBD AHR H32139 | 97504-H32139 | \$ 11,633.00 | 10% | <i>\$10,548.22</i> |
| EW ResponsePLS NBD AHR H32140 | 97504-H32140 | \$ 11,633.00 | 10% | <i>\$10,548.22</i> |
| EW ResponsePLS NBD AHR H32141 | 97504-H32141 | \$ 14,070.00 | 10% | <i>\$12,757.97</i> |
| EW ResponsePLS NBD AHR H32142 | 97504-H32142 | \$ 14,070.00 | 10% | <i>\$12,757.97</i> |
| EW ResponsePLS NBD AHR H32146 | 97504-H32146 | \$ 2,391.00 | 10% | <i>\$2,168.04</i> |
| EW ResponsePLS NBD AHR H32147 | 97504-H32147 | \$ 2,391.00 | 10% | <i>\$2,168.04</i> |
| EW ResponsePLS NBD AHR H32148 | 97504-H32148 | \$ 3,326.00 | 10% | <i>\$3,015.85</i> |
| EW ResponsePLS NBD AHR H32149 | 97504-H32149 | \$ 3,326.00 | 10% | <i>\$3,015.85</i> |
| EW ResponsePLS NBD AHR H32150 | 97504-H32150 | \$ 2,391.00 | 10% | <i>\$2,168.04</i> |
| EW ResponsePLS NBD AHR H32152 | 97504-H32152 | \$ 1,856.00 | 10% | <i>\$1,682.93</i> |
| EW ResponsePLS NBD AHR H32169 | 97504-H32169 | \$ 2,554.00 | 10% | <i>\$2,315.84</i> |
| EW ResponsePLS NBD AHR H32170 | 97504-H32170 | \$ 2,554.00 | 10% | <i>\$2,315.84</i> |
| EW ResponsePLS NBD AHR H32171 | 97504-H32171 | \$ 2,488.00 | 10% | <i>\$2,255.99</i> |
| EW ResponsePLS NBD AHR H32172 | 97504-H32172 | \$ 2,488.00 | 10% | <i>\$2,255.99</i> |
| EW ResponsePLS NBD AHR H32173 | 97504-H32173 | \$ 4,050.00 | 10% | <i>\$3,672.34</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR H32174 | 97504-H32174 | \$ 4,050.00 | 10% | <i>\$3,672.34</i> |
| EW ResponsePLS NBD AHR H32175 | 97504-H32175 | \$ 3,676.00 | 10% | <i>\$3,333.21</i> |
| EW ResponsePLS NBD AHR H32176 | 97504-H32176 | \$ 3,676.00 | 10% | <i>\$3,333.21</i> |
| EW ResponsePLS NBD AHR H32177 | 97504-H32177 | \$ 13,032.00 | 10% | <i>\$11,816.77</i> |
| EW ResponsePLS NBD AHR H32178 | 97504-H32178 | \$ 15,761.00 | 10% | <i>\$14,291.29</i> |
| EW ResponsePLS NBD AHR H34008 | 97504-H34008 | \$ 1,225.00 | 10% | <i>\$1,110.77</i> |
| EW ResponsePLS NBD AHR H34009 | 97504-H34009 | \$ 1,283.00 | 10% | <i>\$1,163.36</i> |
| EW ResponsePLS NBD AHR H34010 | 97504-H34010 | \$ 1,155.00 | 10% | <i>\$1,047.30</i> |
| EW ResponsePLS NBD AHR H34011 | 97504-H34011 | \$ 1,273.00 | 10% | <i>\$1,154.29</i> |
| EW ResponsePLS NBD AHR H34012 | 97504-H34012 | \$ 1,333.00 | 10% | <i>\$1,208.70</i> |
| EW ResponsePLS NBD AHR H34013 | 97504-H34013 | \$ 1,249.00 | 10% | <i>\$1,132.53</i> |
| EW ResponsePLS NBD AHR H34014 | 97504-H34014 | \$ 1,283.00 | 10% | <i>\$1,163.36</i> |
| EW ResponsePLS NBD AHR H34015 | 97504-H34015 | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW ResponsePLS NBD AHR H34016 | 97504-H34016 | \$ 1,293.00 | 10% | <i>\$1,172.43</i> |
| EW ResponsePLS NBD AHR H34017 | 97504-H34017 | \$ 1,357.00 | 10% | <i>\$1,230.46</i> |
| EW ResponsePLS NBD AHR H34018 | 97504-H34018 | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW ResponsePLS NBD AHR H34019 | 97504-H34019 | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW ResponsePLS NBD AHR H34020 | 97504-H34020 | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW ResponsePLS NBD AHR H34021 | 97504-H34021 | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW ResponsePLS NBD AHR H34048 | 97504-H34048 | \$ 1,426.00 | 10% | <i>\$1,293.03</i> |
| EW ResponsePLS NBD AHR H34049 | 97504-H34049 | \$ 1,426.00 | 10% | <i>\$1,293.03</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR H34050 | 97504-H34050 | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW ResponsePLS NBD AHR H34051 | 97504-H34051 | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW ResponsePLS NBD AHR H34052 | 97504-H34052 | \$ 1,460.00 | 10% | <i>\$1,323.86</i> |
| EW ResponsePLS NBD AHR H34053 | 97504-H34053 | \$ 1,460.00 | 10% | <i>\$1,323.86</i> |
| EW ResponsePLS NBD AHR H34054 | 97504-H34054 | \$ 1,396.00 | 10% | <i>\$1,265.82</i> |
| EW ResponsePLS NBD AHR H34055 | 97504-H34055 | \$ 1,396.00 | 10% | <i>\$1,265.82</i> |
| EW ResponsePLS NBD AHR H34056 | 97504-H34056 | \$ 1,592.00 | 10% | <i>\$1,443.55</i> |
| EW ResponsePLS NBD AHR H34057 | 97504-H34057 | \$ 1,592.00 | 10% | <i>\$1,443.55</i> |
| EW ResponsePLS NBD AHR H34058 | 97504-H34058 | \$ 1,556.00 | 10% | <i>\$1,410.90</i> |
| EW ResponsePLS NBD AHR H34059 | 97504-H34059 | \$ 1,556.00 | 10% | <i>\$1,410.90</i> |
| EW ResponsePLS NBD AHR H34062 | 97504-H34062 | \$ 1,592.00 | 10% | <i>\$1,443.55</i> |
| EW ResponsePLS NBD AHR H34063 | 97504-H34063 | \$ 1,592.00 | 10% | <i>\$1,443.55</i> |
| EW ResponsePLS NBD AHR H34064 | 97504-H34064 | \$ 1,386.00 | 10% | <i>\$1,256.76</i> |
| EW ResponsePLS NBD AHR H34065 | 97504-H34065 | \$ 1,386.00 | 10% | <i>\$1,256.76</i> |
| EW ResponsePLS NBD AHR H34066 | 97504-H34066 | \$ 1,386.00 | 10% | <i>\$1,256.76</i> |
| EW ResponsePLS NBD AHR H34067 | 97504-H34067 | \$ 1,386.00 | 10% | <i>\$1,256.76</i> |
| EW ResponsePLS NBD AHR H34068 | 97504-H34068 | \$ 1,386.00 | 10% | <i>\$1,256.76</i> |
| EW ResponsePLS NBD AHR H34069 | 97504-H34069 | \$ 1,346.00 | 10% | <i>\$1,220.49</i> |
| EW ResponsePLS NBD AHR H34070 | 97504-H34070 | \$ 1,386.00 | 10% | <i>\$1,256.76</i> |
| EW ResponsePLS NBD AHR H34071 | 97504-H34071 | \$ 1,386.00 | 10% | <i>\$1,256.76</i> |
| EW ResponsePLS NBD AHR H34072 | 97504-H34072 | \$ 3,011.00 | 10% | <i>\$2,730.22</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|------------|
| EW ResponsePLS NBD AHR H34073 | 97504-H34073 | \$ 2,954.00 | 10% | \$2,678.54 |
| EW ResponsePLS NBD AHR H34074 | 97504-H34074 | \$ 3,664.00 | 10% | \$3,322.33 |
| EW ResponsePLS NBD AHR H34075 | 97504-H34075 | \$ 3,567.00 | 10% | \$3,234.38 |
| EW ResponsePLS NBD AHR H34076 | 97504-H34076 | \$ 3,011.00 | 10% | \$2,730.22 |
| EW ResponsePLS NBD AHR H34077 | 97504-H34077 | \$ 2,954.00 | 10% | \$2,678.54 |
| EW ResponsePLS NBD AHR H34078 | 97504-H34078 | \$ 3,011.00 | 10% | \$2,730.22 |
| EW ResponsePLS NBD AHR H34079 | 97504-H34079 | \$ 2,954.00 | 10% | \$2,678.54 |
| EW ResponsePLS NBD AHR H34080 | 97504-H34080 | \$ 3,664.00 | 10% | \$3,322.33 |
| EW ResponsePLS NBD AHR H34081 | 97504-H34081 | \$ 3,567.00 | 10% | \$3,234.38 |
| EW ResponsePLS NBD AHR H34082 | 97504-H34082 | \$ 3,515.00 | 10% | \$3,187.23 |
| EW ResponsePLS NBD AHR H34083 | 97504-H34083 | \$ 3,422.00 | 10% | \$3,102.90 |
| EW ResponsePLS NBD AHR H34084 | 97504-H34084 | \$ 2,637.00 | 10% | \$2,391.10 |
| EW ResponsePLS NBD AHR H34085 | 97504-H34085 | \$ 2,637.00 | 10% | \$2,391.10 |
| EW ResponsePLS NBD AHR H34086 | 97504-H34086 | \$ 3,069.00 | 10% | \$2,782.82 |
| EW ResponsePLS NBD AHR H34087 | 97504-H34087 | \$ 2,944.00 | 10% | \$2,669.47 |
| EW ResponsePLS NBD AHR H34088 | 97504-H34088 | \$ 5,493.00 | 10% | \$4,980.78 |
| EW ResponsePLS NBD AHR H34089 | 97504-H34089 | \$ 5,493.00 | 10% | \$4,980.78 |
| EW ResponsePLS NBD AHR H34090 | 97504-H34090 | \$ 6,325.00 | 10% | \$5,735.19 |
| EW ResponsePLS NBD AHR H34091 | 97504-H34091 | \$ 6,099.00 | 10% | \$5,530.27 |
| EW ResponsePLS NBD AHR H34092 | 97504-H34092 | \$ 6,099.00 | 10% | \$5,530.27 |
| EW ResponsePLS NBD AHRH34093 | 97504-H34093 | \$ 6,099.00 | 10% | \$5,530.27 |

| | | | | |
|----------------------------------|--------------|-------------|-----|------------|
| EW ResponsePLS NBD AHR H34094 | 97504-H34094 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34095 | 97504-H34095 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34096 | 97504-H34096 | \$ 778.00 | 10% | \$705.45 |
| EW ResponsePLS NBD AHR H34097 | 97504-H34097 | \$ 778.00 | 10% | \$705.45 |
| EW ResponsePLS NBD AHR H34098 | 97504-H34098 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34099 | 97504-H34099 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34100 | 97504-H34100 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34101 | 97504-H34101 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34102 | 97504-H34102 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34103 | 97504-H34103 | \$ 737.00 | 10% | \$668.27 |
| EW ResponsePLS NBD AHR H34104 | 97504-H34104 | \$ 565.00 | 10% | \$512.31 |
| EW ResponsePLS NBD AHR H34105 | 97504-H34105 | \$ 565.00 | 10% | \$512.31 |
| EW ResponsePLS NBD AHR H34106 | 97504-H34106 | \$ 565.00 | 10% | \$512.31 |
| EW ResponsePLS NBD AHR H34107 | 97504-H34107 | \$ 565.00 | 10% | \$512.31 |
| EW ResponsePLS NBD AHR H34108 | 97504-H34108 | \$ 565.00 | 10% | \$512.31 |
| EW ResponsePLS NBD AHR H34109 | 97504-H34109 | \$ 565.00 | 10% | \$512.31 |
| EW ResponsePLS NBD AHR H34110 | 97504-H34110 | \$ 5,876.00 | 10% | \$5,328.06 |
| EW ResponsePLS NBD AHR H34111 | 97504-H34111 | \$ 5,876.00 | 10% | \$5,328.06 |
| EW ResponsePLS NBD AHR H34112 | 97504-H34112 | \$ 5,876.00 | 10% | \$5,328.06 |
| EW ResponsePLS NBD AHR H34114 | 97504-H34114 | \$ 9,172.00 | 10% | \$8,316.71 |
| EW ResponsePLS NBD AHR H34115 | 97504-H34115 | \$ 8,755.00 | 10% | \$7,938.60 |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR H34116 | 97504-H34116 | \$ 8,755.00 | 10% | <i>\$7,938.60</i> |
| EW ResponsePLS NBD AHR H34117 | 97504-H34117 | \$ 9,172.00 | 10% | <i>\$8,316.71</i> |
| EW ResponsePLS NBD AHR H34118 | 97504-H34118 | \$ 1,260.00 | 10% | <i>\$1,142.51</i> |
| EW ResponsePLS NBD AHR H34119 | 97504-H34119 | \$ 1,260.00 | 10% | <i>\$1,142.51</i> |
| EW ResponsePLS NBD AHR H34120 | 97504-H34120 | \$ 1,000.00 | 10% | <i>\$906.75</i> |
| EW ResponsePLS NBD AHR H34121 | 97504-H34121 | \$ 1,000.00 | 10% | <i>\$906.75</i> |
| EW ResponsePLS NBD AHR H34122 | 97504-H34122 | \$ 1,022.00 | 10% | <i>\$926.70</i> |
| EW ResponsePLS NBD AHR H34123 | 97504-H34123 | \$ 1,022.00 | 10% | <i>\$926.70</i> |
| EW ResponsePLS NBD AHR H34124 | 97504-H34124 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBD AHR H34125 | 97504-H34125 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBD AHR H34126 | 97504-H34126 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBD AHR H34127 | 97504-H34127 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBD AHR H34129 | 97504-H34129 | \$ 1,367.00 | 10% | <i>\$1,239.53</i> |
| EW ResponsePLS NBD AHRH34130 | 97504-H34130 | \$ 1,420.00 | 10% | <i>\$1,287.59</i> |
| EW ResponsePLS NBD AHRH34131 | 97504-H34131 | \$ 1,413.00 | 10% | <i>\$1,281.24</i> |
| EW ResponsePLS NBD AHR H34132 | 97504-H34132 | \$ 1,420.00 | 10% | <i>\$1,287.59</i> |
| EW ResponsePLS NBD AHR H34172 | 97504-H34172 | \$ 1,758.00 | 10% | <i>\$1,594.07</i> |
| EW ResponsePLS NBD AHR H34174 | 97504-H34174 | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS NBD AHR H34175 | 97504-H34175 | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS NBD AHR H34176 | 97504-H34176 | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS NBD AHR H34177 | 97504-H34177 | \$ 362.00 | 10% | <i>\$328.24</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34178 | 97504-H34178 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34179 | 97504-H34179 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34180 | 97504-H34180 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34181 | 97504-H34181 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34182 | 97504-H34182 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34183 | 97504-H34183 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34184 | 97504-H34184 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34185 | 97504-H34185 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34186 | 97504-H34186 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34187 | 97504-H34187 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34188 | 97504-H34188 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34189 | 97504-H34189 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34190 | 97504-H34190 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34191 | 97504-H34191 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34192 | 97504-H34192 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34193 | 97504-H34193 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34194 | 97504-H34194 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34195 | 97504-H34195 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34196 | 97504-H34196 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34197 | 97504-H34197 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34198 | 97504-H34198 | \$ 362.00 | 10% | \$328.24 |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34199 | 97504-H34199 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34200 | 97504-H34200 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34201 | 97504-H34201 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34202 | 97504-H34202 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34203 | 97504-H34203 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34204 | 97504-H34204 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34205 | 97504-H34205 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34206 | 97504-H34206 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34207 | 97504-H34207 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34208 | 97504-H34208 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34209 | 97504-H34209 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34210 | 97504-H34210 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34211 | 97504-H34211 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34212 | 97504-H34212 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34213 | 97504-H34213 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34214 | 97504-H34214 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34215 | 97504-H34215 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34216 | 97504-H34216 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34217 | 97504-H34217 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34218 | 97504-H34218 | \$ 362.00 | 10% | \$328.24 |
| EW ResponsePLS NBD AHR H34219 | 97504-H34219 | \$ 362.00 | 10% | \$328.24 |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34220 | 97504-H34220 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34221 | 97504-H34221 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34222 | 97504-H34222 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34223 | 97504-H34223 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34224 | 97504-H34224 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34225 | 97504-H34225 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34226 | 97504-H34226 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34227 | 97504-H34227 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34228 | 97504-H34228 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34229 | 97504-H34229 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34230 | 97504-H34230 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34231 | 97504-H34231 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34232 | 97504-H34232 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34233 | 97504-H34233 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34234 | 97504-H34234 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHRH 34235 | 97504-H34235 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34236 | 97504-H34236 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34237 | 97504-H34237 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34238 | 97504-H34238 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34239 | 97504-H34239 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34240 | 97504-H34240 | \$ 378.00 | 10% | \$342.75 |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34241 | 97504-H34241 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34242 | 97504-H34242 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34243 | 97504-H34243 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34244 | 97504-H34244 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34245 | 97504-H34245 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34246 | 97504-H34246 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34247 | 97504-H34247 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34248 | 97504-H34248 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34249 | 97504-H34249 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34250 | 97504-H34250 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34251 | 97504-H34251 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34252 | 97504-H34252 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34253 | 97504-H34253 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34254 | 97504-H34254 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34255 | 97504-H34255 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34256 | 97504-H34256 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34257 | 97504-H34257 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34258 | 97504-H34258 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34259 | 97504-H34259 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34260 | 97504-H34260 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34261 | 97504-H34261 | \$ 378.00 | 10% | \$342.75 |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHRH 34262 | 97504-H34262 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34263 | 97504-H34263 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34264 | 97504-H34264 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR H34265 | 97504-H34265 | \$ 378.00 | 10% | \$342.75 |
| EW ResponsePLS NBD AHR 34266 | 97504-H34266 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34267 | 97504-H34267 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34268 | 97504-H34268 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34269 | 97504-H34269 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34270 | 97504-H34270 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34271 | 97504-H34271 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34272 | 97504-H34272 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34273 | 97504-H34273 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34274 | 97504-H34274 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34275 | 97504-H34275 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34276 | 97504-H34276 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34277 | 97504-H34277 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34278 | 97504-H34278 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34279 | 97504-H34279 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34280 | 97504-H34280 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34281 | 97504-H34281 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34282 | 97504-H34282 | \$ 364.00 | 10% | \$330.06 |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34283 | 97504-H34283 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34284 | 97504-H34284 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34285 | 97504-H34285 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34286 | 97504-H34286 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34287 | 97504-H34287 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34288 | 97504-H34288 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34289 | 97504-H34289 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34290 | 97504-H34290 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34291 | 97504-H34291 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34292 | 97504-H34292 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34293 | 97504-H34293 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34294 | 97504-H34294 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34295 | 97504-H34295 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34296 | 97504-H34296 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34297 | 97504-H34297 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34298 | 97504-H34298 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34299 | 97504-H34299 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34300 | 97504-H34300 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34301 | 97504-H34301 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34302 | 97504-H34302 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H34303 | 97504-H34303 | \$ 364.00 | 10% | <i>\$330.06</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34304 | 97504-H34304 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34305 | 97504-H34305 | \$ 364.00 | 10% | \$330.06 |
| EW ResponsePLS NBD AHR H34306 | 97504-H34306 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34307 | 97504-H34307 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34308 | 97504-H34308 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34309 | 97504-H34309 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34310 | 97504-H34310 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34311 | 97504-H34311 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34312 | 97504-H34312 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34313 | 97504-H34313 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34314 | 97504-H34314 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34315 | 97504-H34315 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34316 | 97504-H34316 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34317 | 97504-H34317 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34318 | 97504-H34318 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34319 | 97504-H34319 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34320 | 97504-H34320 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34321 | 97504-H34321 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34322 | 97504-H34322 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34323 | 97504-H34323 | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS NBD AHR H34324 | 97504-H34324 | \$ 385.00 | 10% | \$349.10 |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34325 | 97504-H34325 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34326 | 97504-H34326 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34327 | 97504-H34327 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34328 | 97504-H34328 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34329 | 97504-H34329 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34330 | 97504-H34330 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34331 | 97504-H34331 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHRH 34332 | 97504-H34332 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34333 | 97504-H34333 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34334 | 97504-H34334 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34335 | 97504-H34335 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34336 | 97504-H34336 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34337 | 97504-H34337 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34338 | 97504-H34338 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34339 | 97504-H34339 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34340 | 97504-H34340 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34341 | 97504-H34341 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34342 | 97504-H34342 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34343 | 97504-H34343 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34344 | 97504-H34344 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34345 | 97504-H34345 | \$ 385.00 | 10% | <i>\$349.10</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34346 | 97504-H34346 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34347 | 97504-H34347 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34348 | 97504-H34348 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34349 | 97504-H34349 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34350 | 97504-H34350 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34351 | 97504-H34351 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34352 | 97504-H34352 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34353 | 97504-H34353 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34354 | 97504-H34354 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34355 | 97504-H34355 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34356 | 97504-H34356 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34357 | 97504-H34357 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34358 | 97504-H34358 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34359 | 97504-H34359 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHRH 34360 | 97504-H34360 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34361 | 97504-H34361 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34362 | 97504-H34362 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34363 | 97504-H34363 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34364 | 97504-H34364 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34365 | 97504-H34365 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34366 | 97504-H34366 | \$ 415.00 | 10% | <i>\$376.30</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34367 | 97504-H34367 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34368 | 97504-H34368 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34369 | 97504-H34369 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34370 | 97504-H34370 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34371 | 97504-H34371 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34372 | 97504-H34372 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34373 | 97504-H34373 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34374 | 97504-H34374 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34375 | 97504-H34375 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34376 | 97504-H34376 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34377 | 97504-H34377 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34378 | 97504-H34378 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34379 | 97504-H34379 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34380 | 97504-H34380 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34381 | 97504-H34381 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34382 | 97504-H34382 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34383 | 97504-H34383 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34384 | 97504-H34384 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34385 | 97504-H34385 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34386 | 97504-H34386 | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS NBD AHR H34387 | 97504-H34387 | \$ 415.00 | 10% | \$376.30 |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34388 | 97504-H34388 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34389 | 97504-H34389 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34390 | 97504-H34390 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34391 | 97504-H34391 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34392 | 97504-H34392 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34393 | 97504-H34393 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34394 | 97504-H34394 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34395 | 97504-H34395 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34396 | 97504-H34396 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34397 | 97504-H34397 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34398 | 97504-H34398 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34399 | 97504-H34399 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34400 | 97504-H34400 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34401 | 97504-H34401 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34402 | 97504-H34402 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsePLS NBD AHR H34403 | 97504-H34403 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34404 | 97504-H34404 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34405 | 97504-H34405 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34406 | 97504-H34406 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34407 | 97504-H34407 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34408 | 97504-H34408 | \$ 468.00 | 10% | <i>\$424.36</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34409 | 97504-H34409 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34410 | 97504-H34410 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34411 | 97504-H34411 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34412 | 97504-H34412 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34413 | 97504-H34413 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34414 | 97504-H34414 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34415 | 97504-H34415 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34416 | 97504-H34416 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34417 | 97504-H34417 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34418 | 97504-H34418 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34419 | 97504-H34419 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34420 | 97504-H34420 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34421 | 97504-H34421 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34422 | 97504-H34422 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34423 | 97504-H34423 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34424 | 97504-H34424 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34425 | 97504-H34425 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34426 | 97504-H34426 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34427 | 97504-H34427 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34428 | 97504-H34428 | \$ 468.00 | 10% | \$424.36 |
| EW ResponsePLS NBD AHR H34429 | 97504-H34429 | \$ 468.00 | 10% | \$424.36 |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34430 | 97504-H34430 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34431 | 97504-H34431 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34432 | 97504-H34432 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34433 | 97504-H34433 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34434 | 97504-H34434 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34435 | 97504-H34435 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34436 | 97504-H34436 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34437 | 97504-H34437 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34438 | 97504-H34438 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34439 | 97504-H34439 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34440 | 97504-H34440 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34441 | 97504-H34441 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34442 | 97504-H34442 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34443 | 97504-H34443 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34444 | 97504-H34444 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34445 | 97504-H34445 | \$ 468.00 | 10% | <i>\$424.36</i> |
| EW ResponsePLS NBD AHR H34446 | 97504-H34446 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34447 | 97504-H34447 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34448 | 97504-H34448 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34449 | 97504-H34449 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34450 | 97504-H34450 | \$ 491.00 | 10% | <i>\$445.21</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34451 | 97504-H34451 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34452 | 97504-H34452 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34453 | 97504-H34453 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34454 | 97504-H34454 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34455 | 97504-H34455 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34456 | 97504-H34456 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34457 | 97504-H34457 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34458 | 97504-H34458 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34459 | 97504-H34459 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34460 | 97504-H34460 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34461 | 97504-H34461 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34462 | 97504-H34462 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34463 | 97504-H34463 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34464 | 97504-H34464 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34465 | 97504-H34465 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHRH34466 | 97504-H34466 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34467 | 97504-H34467 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34468 | 97504-H34468 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34469 | 97504-H34469 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34470 | 97504-H34470 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34471 | 97504-H34471 | \$ 491.00 | 10% | <i>\$445.21</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34472 | 97504-H34472 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34473 | 97504-H34473 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34474 | 97504-H34474 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34475 | 97504-H34475 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34476 | 97504-H34476 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34477 | 97504-H34477 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34478 | 97504-H34478 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34479 | 97504-H34479 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34480 | 97504-H34480 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34481 | 97504-H34481 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34482 | 97504-H34482 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34483 | 97504-H34483 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34484 | 97504-H34484 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34485 | 97504-H34485 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34486 | 97504-H34486 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34487 | 97504-H34487 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34488 | 97504-H34488 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34489 | 97504-H34489 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EW ResponsePLS NBD AHR H34490 | 97504-H34490 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34491 | 97504-H34491 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34492 | 97504-H34492 | \$ 351.00 | 10% | <i>\$318.27</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34493 | 97504-H34493 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34494 | 97504-H34494 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34495 | 97504-H34495 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34496 | 97504-H34496 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34497 | 97504-H34497 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34498 | 97504-H34498 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34499 | 97504-H34499 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34500 | 97504-H34500 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34501 | 97504-H34501 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34502 | 97504-H34502 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34503 | 97504-H34503 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34504 | 97504-H34504 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34505 | 97504-H34505 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34506 | 97504-H34506 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34507 | 97504-H34507 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34508 | 97504-H34508 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34509 | 97504-H34509 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34510 | 97504-H34510 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34511 | 97504-H34511 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34512 | 97504-H34512 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34513 | 97504-H34513 | \$ 351.00 | 10% | <i>\$318.27</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34514 | 97504-H34514 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34515 | 97504-H34515 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34516 | 97504-H34516 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34517 | 97504-H34517 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34518 | 97504-H34518 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34519 | 97504-H34519 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34520 | 97504-H34520 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34521 | 97504-H34521 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34522 | 97504-H34522 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34523 | 97504-H34523 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34524 | 97504-H34524 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34525 | 97504-H34525 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34526 | 97504-H34526 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34527 | 97504-H34527 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34528 | 97504-H34528 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34529 | 97504-H34529 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34530 | 97504-H34530 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34531 | 97504-H34531 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34532 | 97504-H34532 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34533 | 97504-H34533 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34534 | 97504-H34534 | \$ 351.00 | 10% | <i>\$318.27</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34535 | 97504-H34535 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34536 | 97504-H34536 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34537 | 97504-H34537 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34538 | 97504-H34538 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34539 | 97504-H34539 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34540 | 97504-H34540 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34541 | 97504-H34541 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34542 | 97504-H34542 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34543 | 97504-H34543 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34544 | 97504-H34544 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34545 | 97504-H34545 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34546 | 97504-H34546 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34547 | 97504-H34547 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34548 | 97504-H34548 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34549 | 97504-H34549 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34550 | 97504-H34550 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34551 | 97504-H34551 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34552 | 97504-H34552 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34553 | 97504-H34553 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34554 | 97504-H34554 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34555 | 97504-H34555 | \$ 351.00 | 10% | <i>\$318.27</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34556 | 97504-H34556 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34557 | 97504-H34557 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34558 | 97504-H34558 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34559 | 97504-H34559 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34560 | 97504-H34560 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34561 | 97504-H34561 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34562 | 97504-H34562 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34563 | 97504-H34563 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34564 | 97504-H34564 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34565 | 97504-H34565 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34566 | 97504-H34566 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34567 | 97504-H34567 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34568 | 97504-H34568 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34569 | 97504-H34569 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34570 | 97504-H34570 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34571 | 97504-H34571 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34572 | 97504-H34572 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34573 | 97504-H34573 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34574 | 97504-H34574 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34575 | 97504-H34575 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34576 | 97504-H34576 | \$ 351.00 | 10% | <i>\$318.27</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34577 | 97504-H34577 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34578 | 97504-H34578 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34579 | 97504-H34579 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34580 | 97504-H34580 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34581 | 97504-H34581 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34582 | 97504-H34582 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34583 | 97504-H34583 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34584 | 97504-H34584 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34585 | 97504-H34585 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34586 | 97504-H34586 | \$ 351.00 | 10% | <i>\$318.27</i> |
| EW ResponsePLS NBD AHR H34587 | 97504-H34587 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34588 | 97504-H34588 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34589 | 97504-H34589 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34590 | 97504-H34590 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34591 | 97504-H34591 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34592 | 97504-H34592 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34593 | 97504-H34593 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34594 | 97504-H34594 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34595 | 97504-H34595 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34596 | 97504-H34596 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34597 | 97504-H34597 | \$ 385.00 | 10% | <i>\$349.10</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34598 | 97504-H34598 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34599 | 97504-H34599 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34600 | 97504-H34600 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34601 | 97504-H34601 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34602 | 97504-H34602 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34603 | 97504-H34603 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34604 | 97504-H34604 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34605 | 97504-H34605 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34606 | 97504-H34606 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34607 | 97504-H34607 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34608 | 97504-H34608 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34609 | 97504-H34609 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34610 | 97504-H34610 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34611 | 97504-H34611 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34612 | 97504-H34612 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34613 | 97504-H34613 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34614 | 97504-H34614 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34615 | 97504-H34615 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34616 | 97504-H34616 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34617 | 97504-H34617 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34618 | 97504-H34618 | \$ 385.00 | 10% | <i>\$349.10</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34619 | 97504-H34619 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34620 | 97504-H34620 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34621 | 97504-H34621 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34622 | 97504-H34622 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34623 | 97504-H34623 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34624 | 97504-H34624 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34625 | 97504-H34625 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34626 | 97504-H34626 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34627 | 97504-H34627 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34628 | 97504-H34628 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34629 | 97504-H34629 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34630 | 97504-H34630 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34631 | 97504-H34631 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H34632 | 97504-H34632 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34633 | 97504-H34633 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34634 | 97504-H34634 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34635 | 97504-H34635 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34636 | 97504-H34636 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34637 | 97504-H34637 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34638 | 97504-H34638 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34639 | 97504-H34639 | \$ 391.00 | 10% | <i>\$354.54</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34640 | 97504-H34640 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34641 | 97504-H34641 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34642 | 97504-H34642 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34643 | 97504-H34643 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34644 | 97504-H34644 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34645 | 97504-H34645 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34646 | 97504-H34646 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34647 | 97504-H34647 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34648 | 97504-H34648 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34649 | 97504-H34649 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34650 | 97504-H34650 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34651 | 97504-H34651 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34652 | 97504-H34652 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34653 | 97504-H34653 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34654 | 97504-H34654 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34655 | 97504-H34655 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34656 | 97504-H34656 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34657 | 97504-H34657 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34658 | 97504-H34658 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34659 | 97504-H34659 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34660 | 97504-H34660 | \$ 391.00 | 10% | <i>\$354.54</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsePLS NBD AHR H34661 | 97504-H34661 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34662 | 97504-H34662 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34663 | 97504-H34663 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34664 | 97504-H34664 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34665 | 97504-H34665 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34666 | 97504-H34666 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34667 | 97504-H34667 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34668 | 97504-H34668 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34669 | 97504-H34669 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34670 | 97504-H34670 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34671 | 97504-H34671 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34672 | 97504-H34672 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34673 | 97504-H34673 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34674 | 97504-H34674 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34675 | 97504-H34675 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34676 | 97504-H34676 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34677 | 97504-H34677 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34678 | 97504-H34678 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBD AHR H34679 | 97504-H34679 | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsePLS NBD AHR H34680 | 97504-H34680 | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsePLS NBD AHR H34681 | 97504-H34681 | \$ 404.00 | 10% | <i>\$366.33</i> |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34682 | 97504-H34682 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34683 | 97504-H34683 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34684 | 97504-H34684 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34685 | 97504-H34685 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34686 | 97504-H34686 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34687 | 97504-H34687 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34688 | 97504-H34688 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34689 | 97504-H34689 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34690 | 97504-H34690 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34691 | 97504-H34691 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34692 | 97504-H34692 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34693 | 97504-H34693 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34694 | 97504-H34694 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34695 | 97504-H34695 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34696 | 97504-H34696 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34697 | 97504-H34697 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34698 | 97504-H34698 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34699 | 97504-H34699 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34700 | 97504-H34700 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34701 | 97504-H34701 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34702 | 97504-H34702 | \$ 404.00 | 10% | \$366.33 |

| | | | | |
|----------------------------------|--------------|-----------|-----|----------|
| EW ResponsePLS NBD AHR H34703 | 97504-H34703 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34704 | 97504-H34704 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34705 | 97504-H34705 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34706 | 97504-H34706 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34707 | 97504-H34707 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34708 | 97504-H34708 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34709 | 97504-H34709 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34710 | 97504-H34710 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34711 | 97504-H34711 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34712 | 97504-H34712 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34713 | 97504-H34713 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34714 | 97504-H34714 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34715 | 97504-H34715 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34716 | 97504-H34716 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34717 | 97504-H34717 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34718 | 97504-H34718 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34719 | 97504-H34719 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34720 | 97504-H34720 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34721 | 97504-H34721 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34722 | 97504-H34722 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34723 | 97504-H34723 | \$ 404.00 | 10% | \$366.33 |

| | | | | |
|----------------------------------|--------------|-------------|-----|------------|
| EW ResponsePLS NBD AHR H34724 | 97504-H34724 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34725 | 97504-H34725 | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBD AHR H34726 | 97504-H34726 | \$ 3,164.00 | 10% | \$2,868.96 |
| EW ResponsePLS NBD AHR H34727 | 97504-H34727 | \$ 3,164.00 | 10% | \$2,868.96 |
| EW ResponsePLS NBD AHR H34728 | 97504-H34728 | \$ 3,164.00 | 10% | \$2,868.96 |
| EW ResponsePLS NBD AHR H34729 | 97504-H34729 | \$ 3,164.00 | 10% | \$2,868.96 |
| EW ResponsePLS NBD AHR H34730 | 97504-H34730 | \$ 3,303.00 | 10% | \$2,995.00 |
| EW ResponsePLS NBD AHR H34731 | 97504-H34731 | \$ 3,303.00 | 10% | \$2,995.00 |
| EW ResponsePLS NBD AHR H34732 | 97504-H34732 | \$ 3,303.00 | 10% | \$2,995.00 |
| EW ResponsePLS NBD AHR H34733 | 97504-H34733 | \$ 3,303.00 | 10% | \$2,995.00 |
| EW ResponsePLS NBD AHR H34734 | 97504-H34734 | \$ 1,548.00 | 10% | \$1,403.65 |
| EW ResponsePLS NBD AHR H34735 | 97504-H34735 | \$ 1,548.00 | 10% | \$1,403.65 |
| EW ResponsePLS NBD AHR H34736 | 97504-H34736 | \$ 1,629.00 | 10% | \$1,477.10 |
| EW ResponsePLS NBD AHR H34737 | 97504-H34737 | \$ 1,629.00 | 10% | \$1,477.10 |
| EW ResponsePLS NBD AHR H34738 | 97504-H34738 | \$ 1,980.00 | 10% | \$1,795.37 |
| EW ResponsePLS NBD AHR H34739 | 97504-H34739 | \$ 1,980.00 | 10% | \$1,795.37 |
| EW ResponsePLS NBD AHR H34740 | 97504-H34740 | \$ 1,548.00 | 10% | \$1,403.65 |
| EW ResponsePLS NBD AHR H34741 | 97504-H34741 | \$ 1,548.00 | 10% | \$1,403.65 |
| EW ResponsePLS NBD AHR H34742 | 97504-H34742 | \$ 1,422.00 | 10% | \$1,289.40 |
| EW ResponsePLS NBD AHR H34743 | 97504-H34743 | \$ 1,422.00 | 10% | \$1,289.40 |
| EW ResponsePLS NBD AHR H34744 | 97504-H34744 | \$ 1,621.00 | 10% | \$1,469.84 |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS NBD AHR H34745 | 97504-H34745 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsePLS NBD AHR H34746 | 97504-H34746 | \$ 1,675.00 | 10% | <i>\$1,518.81</i> |
| EW ResponsePLS NBD AHR H34747 | 97504-H34747 | \$ 1,675.00 | 10% | <i>\$1,518.81</i> |
| EW ResponsePLS NBD AHR H34748 | 97504-H34748 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34749 | 97504-H34749 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34750 | 97504-H34750 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34751 | 97504-H34751 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34752 | 97504-H34752 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34753 | 97504-H34753 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34754 | 97504-H34754 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34755 | 97504-H34755 | \$ 1,980.00 | 10% | <i>\$1,795.37</i> |
| EW ResponsePLS NBD AHR H34756 | 97504-H34756 | \$ 1,629.00 | 10% | <i>\$1,477.10</i> |
| EW ResponsePLS NBD AHR H34757 | 97504-H34757 | \$ 1,629.00 | 10% | <i>\$1,477.10</i> |
| EW ResponsePLS NBD AHR H34758 | 97504-H34758 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsePLS NBD AHR H34759 | 97504-H34759 | \$ 1,629.00 | 10% | <i>\$1,477.10</i> |
| EW ResponsePLS NBD AHR H34760 | 97504-H34760 | \$ 1,629.00 | 10% | <i>\$1,477.10</i> |
| EW ResponsePLS NBD AHR H34761 | 97504-H34761 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsePLS NBD AHR H34993 | 97504-H34993 | \$ 14,934.00 | 10% | <i>\$13,541.40</i> |
| EW ResponsePLS NBD AHR H34994 | 97504-H34994 | \$ 14,934.00 | 10% | <i>\$13,541.40</i> |
| EW ResponsePLS NBD AHR H34996 | 97504-H34996 | \$ 14,934.00 | 10% | <i>\$13,541.40</i> |
| EW ResponsePLS NBD AHR H34997 | 97504-H34997 | \$ 14,934.00 | 10% | <i>\$13,541.40</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|-------------------|
| EW ResponsePLS NBD AHR H35005 | 97504-H35005 | \$ 10,545.00 | 10% | <i>\$9,561.68</i> |
| EW ResponsePLS NBD AHR H35006 | 97504-H35006 | \$ 10,545.00 | 10% | <i>\$9,561.68</i> |
| EW ResponsePLS NBD AHR H35012 | 97504-H35012 | \$ 7,340.00 | 10% | <i>\$6,655.55</i> |
| EW ResponsePLS NBD AHR H35070 | 97504-H35070 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35071 | 97504-H35071 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35072 | 97504-H35072 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35073 | 97504-H35073 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35074 | 97504-H35074 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35075 | 97504-H35075 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35076 | 97504-H35076 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35077 | 97504-H35077 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35078 | 97504-H35078 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35079 | 97504-H35079 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsePLS NBD AHR H35080 | 97504-H35080 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H35081 | 97504-H35081 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H35082 | 97504-H35082 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H35083 | 97504-H35083 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBD AHR H35270 | 97504-H35270 | \$ 1,460.00 | 10% | <i>\$1,323.86</i> |
| EW ResponsePLS NBD AHR H35271 | 97504-H35271 | \$ 1,396.00 | 10% | <i>\$1,265.82</i> |
| EW ResponsePLS NBD AHR H35272 | 97504-H35272 | \$ 1,296.00 | 10% | <i>\$1,175.15</i> |
| EW ResponsePLS NBD AHR H35273 | 97504-H35273 | \$ 1,296.00 | 10% | <i>\$1,175.15</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR H35274 | 97504-H35274 | \$ 1,683.00 | 10% | <i>\$1,526.06</i> |
| EW ResponsePLS NBD AHR H35275 | 97504-H35275 | \$ 1,592.00 | 10% | <i>\$1,443.55</i> |
| EW ResponsePLS NBD AHR H35276 | 97504-H35276 | \$ 3,011.00 | 10% | <i>\$2,730.22</i> |
| EW ResponsePLS NBD AHR H35277 | 97504-H35277 | \$ 3,515.00 | 10% | <i>\$3,187.23</i> |
| EW ResponsePLS NBD AHR H35278 | 97504-H35278 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW ResponsePLS NBD AHR H35279 | 97504-H35279 | \$ 2,944.00 | 10% | <i>\$2,669.47</i> |
| EW ResponsePLS NBD AHR H35280 | 97504-H35280 | \$ 5,762.00 | 10% | <i>\$5,224.69</i> |
| EW ResponsePLS NBD AHR H35292 | 97504-H35292 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW ResponsePLS NBD AHR H35293 | 97504-H35293 | \$ 2,944.00 | 10% | <i>\$2,669.47</i> |
| EW ResponsePLS NBD AHRH35295 | 97504-H35295 | \$ 1,301.00 | 10% | <i>\$1,179.68</i> |
| EW ResponsePLS NBD AHR H35302 | 97504-H35302 | \$ 3,254.00 | 10% | <i>\$2,950.56</i> |
| EW ResponsePLS NBD AHR H35303 | 97504-H35303 | \$ 3,254.00 | 10% | <i>\$2,950.56</i> |
| EW ResponsePLS NBD AHR H35304 | 97504-H35304 | \$ 3,254.00 | 10% | <i>\$2,950.56</i> |
| EW ResponsePLS NBD AHR H35305 | 97504-H35305 | \$ 3,350.00 | 10% | <i>\$3,037.61</i> |
| EW ResponsePLS NBD AHR H35306 | 97504-H35306 | \$ 3,350.00 | 10% | <i>\$3,037.61</i> |
| EW ResponsePLS NBD AHR H35307 | 97504-H35307 | \$ 3,350.00 | 10% | <i>\$3,037.61</i> |
| EW ResponsePLS NBD AHR H35309 | 97504-H35309 | \$ 3,412.00 | 10% | <i>\$3,093.83</i> |
| EW ResponsePLS NBD AHR H35310 | 97504-H35310 | \$ 3,412.00 | 10% | <i>\$3,093.83</i> |
| EW ResponsePLS NBD AHR H35311 | 97504-H35311 | \$ 3,412.00 | 10% | <i>\$3,093.83</i> |
| EW ResponsePLS NBD AHR H35312 | 97504-H35312 | \$ 2,820.00 | 10% | <i>\$2,557.04</i> |
| EW ResponsePLS NBD AHR H35313 | 97504-H35313 | \$ 2,820.00 | 10% | <i>\$2,557.04</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR H35314 | 97504-H35314 | \$ 2,820.00 | 10% | <i>\$2,557.04</i> |
| EW ResponsePLS NBD AHR H35315 | 97504-H35315 | \$ 1,954.00 | 10% | <i>\$1,771.79</i> |
| EW ResponsePLS NBD AHR H35318 | 97504-H35318 | \$ 1,421.00 | 10% | <i>\$1,288.49</i> |
| EW ResponsePLS NBD AHR H35319 | 97504-H35319 | \$ 1,571.00 | 10% | <i>\$1,424.50</i> |
| EW ResponsePLS NBD AHR H35320 | 97504-H35320 | \$ 1,593.00 | 10% | <i>\$1,444.45</i> |
| EW ResponsePLS NBD AHR H35321 | 97504-H35321 | \$ 1,761.00 | 10% | <i>\$1,596.79</i> |
| EW ResponsePLS NBD AHR H35322 | 97504-H35322 | \$ 1,971.00 | 10% | <i>\$1,787.20</i> |
| EW ResponsePLS NBD AHR H35323 | 97504-H35323 | \$ 1,954.00 | 10% | <i>\$1,771.79</i> |
| EW ResponsePLS NBD AHR H35328 | 97504-H35328 | \$ 788.00 | 10% | <i>\$714.52</i> |
| EW ResponsePLS NBD AHR H35330 | 97504-H35330 | \$ 1,118.00 | 10% | <i>\$1,013.75</i> |
| EW ResponsePLS NBD AHR H35340 | 97504-H35340 | \$ 3,679.00 | 10% | <i>\$3,335.93</i> |
| EW ResponsePLS NBD AHR H35341 | 97504-H35341 | \$ 3,679.00 | 10% | <i>\$3,335.93</i> |
| EW ResponsePLS NBD AHR H35342 | 97504-H35342 | \$ 3,063.00 | 10% | <i>\$2,777.38</i> |
| EW ResponsePLS NBD AHR H35343 | 97504-H35343 | \$ 3,679.00 | 10% | <i>\$3,335.93</i> |
| EW ResponsePLS NBD AHR H35344 | 97504-H35344 | \$ 3,776.00 | 10% | <i>\$3,423.89</i> |
| EW ResponsePLS NBD AHR H35345 | 97504-H35345 | \$ 3,776.00 | 10% | <i>\$3,423.89</i> |
| EW ResponsePLS NBD AHR H35346 | 97504-H35346 | \$ 3,136.00 | 10% | <i>\$2,843.57</i> |
| EW ResponsePLS NBD AHR H35347 | 97504-H35347 | \$ 3,776.00 | 10% | <i>\$3,423.89</i> |
| EW ResponsePLS NBD AHR H35349 | 97504-H35349 | \$ 4,018.00 | 10% | <i>\$3,643.32</i> |
| EW ResponsePLS NBD AHR H35350 | 97504-H35350 | \$ 4,018.00 | 10% | <i>\$3,643.32</i> |
| EW ResponsePLS NBD AHR H35351 | 97504-H35351 | \$ 3,328.00 | 10% | <i>\$3,017.66</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR H35352 | 97504-H35352 | \$ 4,018.00 | 10% | <i>\$3,643.32</i> |
| EW ResponsePLS NBD AHR H35359 | 97504-H35359 | \$ 1,761.00 | 10% | <i>\$1,596.79</i> |
| EW ResponsePLS NBD AHR H35360 | 97504-H35360 | \$ 1,971.00 | 10% | <i>\$1,787.20</i> |
| EW ResponsePLS NBD AHR H35361 | 97504-H35361 | \$ 1,954.00 | 10% | <i>\$1,771.79</i> |
| EW ResponsePLS NBD AHR H35362 | 97504-H35362 | \$ 1,421.00 | 10% | <i>\$1,288.49</i> |
| EW ResponsePLS NBD AHR H35366 | 97504-H35366 | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |
| EW ResponsePLS NBD AHR H35367 | 97504-H35367 | \$ 1,484.00 | 10% | <i>\$1,345.62</i> |
| EW ResponsePLS NBD AHR H35368 | 97504-H35368 | \$ 2,258.00 | 10% | <i>\$2,047.44</i> |
| EW ResponsePLS NBD AHR H35369 | 97504-H35369 | \$ 738.00 | 10% | <i>\$669.18</i> |
| EW ResponsePLS NBD AHR H35370 | 97504-H35370 | \$ 1,029.00 | 10% | <i>\$933.05</i> |
| EW ResponsePLS NBD AHR H35375 | 97504-H35375 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW ResponsePLS NBD AHR H35376 | 97504-H35376 | \$ 1,348.00 | 10% | <i>\$1,222.30</i> |
| EW ResponsePLS NBD AHR H35377 | 97504-H35377 | \$ 566.00 | 10% | <i>\$513.22</i> |
| EW ResponsePLS NBD AHR H35378 | 97504-H35378 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW ResponsePLS NBD AHR H35379 | 97504-H35379 | \$ 566.00 | 10% | <i>\$513.22</i> |
| EW ResponsePLS NBD AHR H35380 | 97504-H35380 | \$ 1,011.00 | 10% | <i>\$916.72</i> |
| EW ResponsePLS NBD AHR H35381 | 97504-H35381 | \$ 1,234.00 | 10% | <i>\$1,118.93</i> |
| EW ResponsePLS NBD AHR H35384 | 97504-H35384 | \$ 453.00 | 10% | <i>\$410.76</i> |
| EW ResponsePLS NBD AHR H35385 | 97504-H35385 | \$ 599.00 | 10% | <i>\$543.14</i> |
| EW ResponsePLS NBD AHR H35386 | 97504-H35386 | \$ 999.00 | 10% | <i>\$905.84</i> |
| EW ResponsePLS NBD AHR H35387 | 97504-H35387 | \$ 935.00 | 10% | <i>\$847.81</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR H35388 | 97504-H35388 | \$ 687.00 | 10% | <i>\$622.94</i> |
| EW ResponsePLS NBD AHR H35389 | 97504-H35389 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR H35390 | 97504-H35390 | \$ 333.00 | 10% | <i>\$301.95</i> |
| EW ResponsePLS NBD AHR H35391 | 97504-H35391 | \$ 737.00 | 10% | <i>\$668.27</i> |
| EW ResponsePLS NBD AHR H35392 | 97504-H35392 | \$ 1,125.00 | 10% | <i>\$1,020.09</i> |
| EW ResponsePLS NBD AHR H35393 | 97504-H35393 | \$ 1,494.00 | 10% | <i>\$1,354.68</i> |
| EW ResponsePLS NBD AHR H35394 | 97504-H35394 | \$ 274.00 | 10% | <i>\$248.45</i> |
| EW ResponsePLS NBD AHR H35395 | 97504-H35395 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW ResponsePLS NBD AHR H35396 | 97504-H35396 | \$ 274.00 | 10% | <i>\$248.45</i> |
| EW ResponsePLS NBD AHR H35397 | 97504-H35397 | \$ 229.00 | 10% | <i>\$207.65</i> |
| EW ResponsePLS NBD AHR H35398 | 97504-H35398 | \$ 699.00 | 10% | <i>\$633.82</i> |
| EW ResponsePLS NBD AHR H35399 | 97504-H35399 | \$ 853.00 | 10% | <i>\$773.46</i> |
| EW ResponsePLS NBD AHR H35400 | 97504-H35400 | \$ 936.00 | 10% | <i>\$848.72</i> |
| EW ResponsePLS NBD AHR H35401 | 97504-H35401 | \$ 503.00 | 10% | <i>\$456.10</i> |
| EW ResponsePLS NBD AHR H35415 | 97504-H35415 | \$ 314.00 | 10% | <i>\$284.72</i> |
| EW ResponsePLS NBD AHR H35416 | 97504-H35416 | \$ 314.00 | 10% | <i>\$284.72</i> |
| EW ResponsePLS NBD AHR H35426 | 97504-H35426 | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsePLS NBD AHR H35427 | 97504-H35427 | \$ 935.00 | 10% | <i>\$847.81</i> |
| EW ResponsePLS NBD AHR H35428 | 97504-H35428 | \$ 333.00 | 10% | <i>\$301.95</i> |
| EW ResponsePLS NBD AHR H35429 | 97504-H35429 | \$ 737.00 | 10% | <i>\$668.27</i> |
| EW ResponsePLS NBD AHR H35430 | 97504-H35430 | \$ 1,503.00 | 10% | <i>\$1,362.85</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR H35431 | 97504-H35431 | \$ 1,503.00 | 10% | <i>\$1,362.85</i> |
| EW ResponsePLS NBD AHR H35432 | 97504-H35432 | \$ 1,422.00 | 10% | <i>\$1,289.40</i> |
| EW ResponsePLS NBD AHR H35433 | 97504-H35433 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW ResponsePLS NBD AHR H35434 | 97504-H35434 | \$ 1,634.00 | 10% | <i>\$1,481.63</i> |
| EW ResponsePLS NBD AHR H35435 | 97504-H35435 | \$ 1,634.00 | 10% | <i>\$1,481.63</i> |
| EW ResponsePLS NBD AHR H35436 | 97504-H35436 | \$ 1,923.00 | 10% | <i>\$1,743.68</i> |
| EW ResponsePLS NBD AHR H35437 | 97504-H35437 | \$ 1,923.00 | 10% | <i>\$1,743.68</i> |
| EW ResponsePLS NBD AHR H35438 | 97504-H35438 | \$ 1,923.00 | 10% | <i>\$1,743.68</i> |
| EW ResponsePLS NBD AHR H35439 | 97504-H35439 | \$ 1,923.00 | 10% | <i>\$1,743.68</i> |
| EW ResponsePLS NBD AHR H35440 | 97504-H35440 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW ResponsePLS NBD AHR H35441 | 97504-H35441 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW ResponsePLS NBD AHR H35442 | 97504-H35442 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW ResponsePLS NBD AHR H35443 | 97504-H35443 | \$ 3,164.00 | 10% | <i>\$2,868.96</i> |
| EW ResponsePLS NBD AHR H35444 | 97504-H35444 | \$ 3,303.00 | 10% | <i>\$2,995.00</i> |
| EW ResponsePLS NBD AHR H35445 | 97504-H35445 | \$ 3,011.00 | 10% | <i>\$2,730.22</i> |
| EW ResponsePLS NBD AHR H35446 | 97504-H35446 | \$ 2,954.00 | 10% | <i>\$2,678.54</i> |
| EW ResponsePLS NBD AHR H35447 | 97504-H35447 | \$ 3,331.00 | 10% | <i>\$3,020.38</i> |
| EW ResponsePLS NBD AHR H35448 | 97504-H35448 | \$ 3,243.00 | 10% | <i>\$2,940.59</i> |
| EW ResponsePLS NBD AHR H35449 | 97504-H35449 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW ResponsePLS NBD AHR H35450 | 97504-H35450 | \$ 2,790.00 | 10% | <i>\$2,529.83</i> |
| EW ResponsePLS NBD AHR H35451 | 97504-H35451 | \$ 6,099.00 | 10% | <i>\$5,530.27</i> |

| | | | | |
|---|-------------------------|-------------|-----|------------|
| EW ResponsePLS NBD AHRH35452 | 97504-H35452 | \$ 6,099.00 | 10% | \$5,530.27 |
| EW ResponsePLS NBD AHR H35453 | 97504-H35453 | \$ 3,303.00 | 10% | \$2,995.00 |
| EW ResponsePLS NBD AHR H35454 | 97504-H35454 | \$ 3,164.00 | 10% | \$2,868.96 |
| EW ResponsePLS NBD AHR H35455 | 97504-H35455 | \$ 1,593.00 | 10% | \$1,444.45 |
| EW ResponsePLS NBD AHR H35456 | 97504-H35456 | \$ 1,721.00 | 10% | \$1,560.52 |
| EW ResponsePLS NBD AHR H35457 | 97504-H35457 | \$ 1,671.00 | 10% | \$1,515.18 |
| EW ResponsePLS NBD AHR H35458 | 97504-H35458 | \$ 1,734.00 | 10% | \$1,572.30 |
| EW ResponsePLS NBD AHR H35471 | 97504-H35471 | \$ 1,593.00 | 10% | \$1,444.45 |
| EW ResponsePLS NBD AHR H35600 | 97504-H35600 | \$ 1,296.00 | 10% | \$1,175.15 |
| EW ResponsePLS NBD AHR H35601 | 97504-H35601 | \$ 1,296.00 | 10% | \$1,175.15 |
| EW ResponsePLS NBD AHR H35602 | 97504-H35602 | \$ 1,548.00 | 10% | \$1,403.65 |
| EW ResponsePLS NBD AHR H35603 | 97504-H35603 | \$ 1,548.00 | 10% | \$1,403.65 |
| EW ResponsePLS NBD AHR H35604 | 97504-H35604 | \$ 1,629.00 | 10% | \$1,477.10 |
| EW ResponsePLS NBD AHR H35605 | 97504-H35605 | \$ 1,629.00 | 10% | \$1,477.10 |
| EW ResponsePLS NBD AHR H35606 | 97504-H35606 | \$ 1,683.00 | 10% | \$1,526.06 |
| EW ResponsePLS NBD AHR H35607 | 97504-H35607 | \$ 1,675.00 | 10% | \$1,518.81 |
| EW ResponsePLS NBD AHR ISW-24W-4X | 97504-ISW- 24W-4X | \$ 1,445.00 | 10% | \$1,310.25 |
| EW ResponsePLS NBD AHR ISW-4W-4WS-4X | 97504-ISW-4W- 4WS-4X | \$ 1,212.00 | 10% | \$1,098.98 |
| EW ResponsePLUS NBD AHR- MS128 | 97504- MSM128 | \$ 2,556.00 | 10% | \$2,317.65 |
| EW ResponsePLS NBD AHR- MSM48C | 97504- MSM48C | \$ 1,836.00 | 10% | \$1,664.79 |
| EW ResponsePLS NBD AHR- R100-8T | 97504-R100-8T | \$ 1,203.00 | 10% | \$1,090.82 |

| | | | | |
|---|---------------------------------|--------------|-----|-------------|
| EW ResponsePLS NBD AHR SLX9150-48XT-DC-F | 97504- SLX9150- 48XT-DC-F | \$ 3,293.00 | 10% | \$2,985.93 |
| EW ResponsePLS NBD AHR SLX9150-48XT-DC-R | 97504- SLX9150- 48XT-DC-R | \$ 3,596.00 | 10% | \$3,260.67 |
| EW ResponsePLS NBD AHR SLX9150-48Y-DC-F | 97504- SLX9150-48Y- DC-F | \$ 3,209.00 | 10% | \$2,909.76 |
| EW ResponsePLS NBD AHR SLX9150-48Y-DC-R | 97504- SLX9150-48Y- DC-R | \$ 3,504.00 | 10% | \$3,177.25 |
| EW ResponsePLS NBD AHR SLX9740-40C | 97504- SLX9740-40C | \$ 9,810.00 | 10% | \$8,895.22 |
| EW ResponsePLS NBD AHR SLX9740-40C-AC-F | 97504- SLX9740-40C- AC-F | \$ 9,810.00 | 10% | \$8,895.22 |
| EW ResponsePLS NBD AHR SLX9740-40C-AC-R | 97504- SLX9740-40C- AC-R | \$ 9,810.00 | 10% | \$8,895.22 |
| EW ResponsePLS NBD AHR SLX9740-40C-DC-F | 97504- SLX9740-40C- DC-F | \$ 9,810.00 | 10% | \$8,895.22 |
| EW ResponsePLS NBD AHR SLX9740-80C | 97504- SLX9740-80C | \$ 17,484.00 | 10% | \$15,853.62 |
| EW ResponsePLS NBD AHR SLX9740-80C-AC-F | 97504- SLX9740-80C- AC-F | \$ 17,484.00 | 10% | \$15,853.62 |
| EW ResponsePLS NBD AHR SLX9740-80C-AC-R | 97504- SLX9740-80C- AC-R | \$ 17,484.00 | 10% | \$15,853.62 |
| EW ResponsePLS NBD AHR SLX9740-80C-DC-F | 97504- SLX9740-80C- DC-F | \$ 17,484.00 | 10% | \$15,853.62 |
| EW ResponsePLS NBD AHR V300-8P-2X | 97504-V300- 8P-2X | \$ 810.00 | 10% | \$734.47 |
| EW ResponsePLS NBD AHR V300-8T-2X | 97504-V300- 8T-2X | \$ 778.00 | 10% | \$705.45 |
| EW ResponsePLS NBD AHR V300HT-8P-2X | 97504-V300HT- 8P-2X | \$ 939.00 | 10% | \$851.44 |

| | | | | |
|---|---|-------------|-----|------------|
| EW ResponsePLS NBD AHR V300HT-8T-2X | 97504-V300HT- 8T-2X | \$ 847.00 | 10% | \$768.02 |
| EW ResponsePLS NBD AHR- VIM-SS | 97504-VIM-SS | \$ 564.00 | 10% | \$511.41 |
| EW ResponsePLS NBD AHRVIMSSV80 | 97504-VIM- SSV80 | \$ 668.00 | 10% | \$605.71 |
| EW ResponsePLS NBD AHR- VIM2-SS | 97504-VIM2- SS | \$ 561.00 | 10% | \$508.69 |
| EW ResponsePLS NBD AHRVIM2SS | 97504-VIM2- SS128 | \$ 889.00 | 10% | \$806.10 |
| EW ResponsePLS NBD AHRVIM2V80 | 97504-VIM2- V80 | \$ 949.00 | 10% | \$860.51 |
| EW ResponsePLS NBD AHRVIM | 97504- VIM210G4X | \$ 1,287.00 | 10% | \$1,166.99 |
| EW RespPLS NBD AHR VSP4900-12MXU-12XE | 97504- VSP4900- 12MXU-12XE | \$ 1,847.00 | 10% | \$1,674.77 |
| EW RespPLS NBD AHR VSP4900-12MXU-12XE-B1 | 97504- VSP4900- 12MXU-12XE- B1 | \$ 1,847.00 | 10% | \$1,674.77 |
| EW ResponsePLS NBD AHR VSP4900-24S | 97504- VSP4900-24S | \$ 1,421.00 | 10% | \$1,288.49 |
| EW ResponsePLS NBD AHR VSP4900-24S-B3 | 97504- VSP4900-24S- B3 | \$ 1,421.00 | 10% | \$1,288.49 |
| EW ResponsePLS NBD AHR VSP4900-24XE | 97504- VSP4900- 24XE | \$ 1,847.00 | 10% | \$1,674.77 |
| EW ResponsePLS NBD AHR VSP4900-24XE-B3 | 97504- VSP4900- 24XE-B3 | \$ 1,847.00 | 10% | \$1,674.77 |
| EW ResponsePLS NBD AHR X435-24P-4S | 97504-X435- 24P-4S | \$ 888.00 | 10% | \$805.19 |
| EW ResponsePLS NBD AHR X435-24T-4S | 97504-X435- 24T-4S | \$ 807.00 | 10% | \$731.75 |
| EW ResponsePLS NBD AHR X435-8P-2T-W | 97504-X435- 8P-2T-W | \$ 807.00 | 10% | \$731.75 |
| EW ResponsePLS NBD AHR X435-8P-4S | 97504-X435- 8P-4S | \$ 798.00 | 10% | \$723.59 |
| EW ResponsePLS NBD AHR X435-8T-4S | 97504-X435- 8T-4S | \$ 780.00 | 10% | \$707.27 |

| | | | | |
|---|---------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHRX46024P | 97504-X460- 24P | \$ 2,151.00 | 10% | <i>\$1,950.42</i> |
| EW ResponsePLS NBD AHRX46024T | 97504-X460- 24T | \$ 1,879.00 | 10% | <i>\$1,703.78</i> |
| EW ResponsePLS NBD AHRX46024T | 97504-X460- 24TDC | \$ 2,188.00 | 10% | <i>\$1,983.97</i> |
| EW ResponsePLS NBD AHRX46024X | 97504-X460- 24X | \$ 2,364.00 | 10% | <i>\$2,143.56</i> |
| EW ResponsePLS NBD AHRX46024X | 97504-X460- 24XDC | \$ 2,531.00 | 10% | <i>\$2,294.98</i> |
| EW ResponsePLS NBD AHRX46048P | 97504-X460- 48P | \$ 2,364.00 | 10% | <i>\$2,143.56</i> |
| EW ResponsePLS NBD AHRX46048T | 97504-X460- 48T | \$ 2,218.00 | 10% | <i>\$2,011.17</i> |
| EW ResponsePLS NBD AHRX46048T | 97504-X460- 48TDC | \$ 2,496.00 | 10% | <i>\$2,263.25</i> |
| EW ResponsePLS NBD AHRX46048X | 97504-X460- 48X | \$ 2,717.00 | 10% | <i>\$2,463.64</i> |
| EW ResponsePLS NBD AHRX46048X | 97504-X460- 48XDC | \$ 2,730.00 | 10% | <i>\$2,475.43</i> |
| EW ResponsePLS NBD AHR X465-24MU | 97504-X465- 24MU | \$ 1,971.00 | 10% | <i>\$1,787.20</i> |
| EW ResponsePLS NBD AHR X465-24S | 97504-X465- 24S | \$ 1,421.00 | 10% | <i>\$1,288.49</i> |
| EW ResponsePLS NBD AHR X465-24S-B3 | 97504-X465- 24S-B3 | \$ 1,421.00 | 10% | <i>\$1,288.49</i> |
| EW ResponsePLS NBD AHR X465-24W | 97504-X465- 24W | \$ 1,421.00 | 10% | <i>\$1,288.49</i> |
| EW ResponsePLS NBD AHR X465-24XE | 97504-X465- 24XE | \$ 1,847.00 | 10% | <i>\$1,674.77</i> |
| EW ResponsePLS NBD AHR X465-24XE-B3 | 97504-X465- 24XE-B3 | \$ 1,847.00 | 10% | <i>\$1,674.77</i> |
| EW ResponsePLS NBD AHR X465-48P | 97504-X465- 48P | \$ 1,593.00 | 10% | <i>\$1,444.45</i> |
| EW ResponsePLS NBD AHR X465-48T | 97504-X465- 48T | \$ 1,571.00 | 10% | <i>\$1,424.50</i> |
| EW ResponsePLS NBD AHRX465-48W | 97504-X465- 48W | \$ 1,761.00 | 10% | <i>\$1,596.79</i> |
| EW ResponsePLS NBD AHR X465i-48W | 97504-X465i- 48W | \$ 1,954.00 | 10% | <i>\$1,771.79</i> |
| EW ResponsePLS NBD AHR X465i-48W-B1-S1 | 97504-X465i- 48W-B1-S1 | \$ 1,954.00 | 10% | <i>\$1,771.79</i> |

| | | | | |
|---|---------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBD AHR X465i-48W-B2-S1 | 97504-X465i- 48W-B2-S1 | \$ 1,954.00 | 10% | <i>\$1,771.79</i> |
| EW ResponsePLS NBD AHRX48024X | 97504-X480- 24X | \$ 2,445.00 | 10% | <i>\$2,217.00</i> |
| EW ResponsePLUS NBD AHR- X480T | 97504-X480- 48T | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsePLS NBD AHR- X48048 | 97504-X480- 48X | \$ 2,877.00 | 10% | <i>\$2,608.72</i> |
| EW ResponsePLS NBD AHR X695-48Y-8C | 97504-X695- 48Y-8C | \$ 2,836.00 | 10% | <i>\$2,571.54</i> |
| EW ResponsePLS NBD AHR XA1440 | 97504-XA1440 | \$ 903.00 | 10% | <i>\$818.80</i> |
| EW ResponsePLS NBD AHR XA1480 | 97504-XA1480 | \$ 976.00 | 10% | <i>\$884.99</i> |
| EW ResponsePLS NBD AHRXGM32SF | 97504-XGM3- 2SF | \$ 668.00 | 10% | <i>\$605.71</i> |
| EW ResponsePLS NBD AHR XR600 | 97504-XR600 | \$ 1,173.00 | 10% | <i>\$1,063.62</i> |
| EW ResponsePLS 4HR AHR 1130C | 97507-1130C | \$ 2,672.00 | 6% | <i>\$2,530.52</i> |
| EW ResponsePLS 4HR AHR- 16119 | 97507-16119 | \$ 768.00 | 10% | <i>\$696.38</i> |
| EW ResponsePLS 4HR AHR- 16120 | 97507-16120 | \$ 860.00 | 10% | <i>\$779.81</i> |
| EW ResponsePLS 4HR AHR- 16126 | 97507-16126 | \$ 768.00 | 10% | <i>\$696.38</i> |
| EW ResponsePLS 4HR AHR- 16127 | 97507-16127 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW ResponsePLS 4HR AHR- 16172 | 97507-16172 | \$ 1,676.00 | 10% | <i>\$1,519.71</i> |
| EW ResponsePLS 4HR AHR 16172T | 97507-16172T | \$ 1,781.00 | 10% | <i>\$1,614.92</i> |
| EW ResponsePLS 4HR AHR- 16173 | 97507-16173 | \$ 1,692.00 | 10% | <i>\$1,534.22</i> |
| EW ResponsePLS 4HR AHR 16173T | 97507-16173T | \$ 1,795.00 | 10% | <i>\$1,627.62</i> |
| EW ResponsePLS 4HR AHR- 16174 | 97507-16174 | \$ 1,844.00 | 10% | <i>\$1,672.05</i> |
| EW ResponsePLS 4HR AHR- 16175 | 97507-16175 | \$ 1,927.00 | 10% | <i>\$1,747.31</i> |
| EW ResponsePLS 4HR AHR- 16176 | 97507-16176 | \$ 1,848.00 | 10% | <i>\$1,675.67</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR-16177 | 97507-16177 | \$ 1,743.00 | 10% | <i>\$1,580.47</i> |
| EW ResponsePLS 4HR AHR 16177T | 97507-16177T | \$ 1,995.00 | 10% | <i>\$1,808.97</i> |
| EW ResponsePLS 4HR AHR-16178 | 97507-16178 | \$ 2,076.00 | 10% | <i>\$1,882.41</i> |
| EW ResponsePLS 4HR AHR-16179 | 97507-16179 | \$ 2,098.00 | 10% | <i>\$1,902.36</i> |
| EW ResponsePLS 4HR AHR 16179T | 97507-16179T | \$ 2,237.00 | 10% | <i>\$2,028.40</i> |
| EW ResponsePLS 4HR AHR-16301T | 97507-16301T | \$ 3,201.00 | 10% | <i>\$2,902.51</i> |
| EW ResponsePLS 4HR AHR-16303T | 97507-16303T | \$ 3,201.00 | 10% | <i>\$2,902.51</i> |
| EW ResponsePLS 4HR AHR-16304T | 97507-16304T | \$ 3,878.00 | 10% | <i>\$3,516.38</i> |
| EW ResponsePLS 4HR AHR-16401T | 97507-16401T | \$ 2,267.00 | 10% | <i>\$2,055.60</i> |
| EW ResponsePLS 4HR AHR-16402T | 97507-16402T | \$ 2,767.00 | 10% | <i>\$2,508.98</i> |
| EW ResponsePLS 4HR AHR-16403T | 97507-16403T | \$ 2,591.00 | 10% | <i>\$2,349.39</i> |
| EW ResponsePLS 4HR AHR-16404T | 97507-16404T | \$ 2,591.00 | 10% | <i>\$2,349.39</i> |
| EW ResponsePLS 4HR AHR-16405T | 97507-16405T | \$ 3,010.00 | 10% | <i>\$2,729.32</i> |
| EW ResponsePLS 4HR AHR-16406T | 97507-16406T | \$ 3,567.00 | 10% | <i>\$3,234.38</i> |
| EW ResponsePLS 4HR AHR-16431 | 97507-16431 | \$ 2,653.00 | 10% | <i>\$2,405.61</i> |
| EW ResponsePLS 4HR AHR-16432 | 97507-16432 | \$ 2,796.00 | 10% | <i>\$2,535.27</i> |
| EW ResponsePLS 4HR AHR-16440 | 97507-16440 | \$ 2,123.00 | 10% | <i>\$1,925.03</i> |
| EW ResponsePLS 4HR AHR-16441 | 97507-16441 | \$ 2,034.00 | 10% | <i>\$1,844.33</i> |
| EW ResponsePLS 4HR AHR-16442 | 97507-16442 | \$ 804.00 | 10% | <i>\$729.03</i> |
| EW ResponsePLS 4HR AHR-16444 | 97507-16444 | \$ 634.00 | 10% | <i>\$574.88</i> |
| EW ResponsePLS 4HR AHR-16501 | 97507-16501 | \$ 1,504.00 | 10% | <i>\$1,363.75</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR-16501T | 97507-16501T | \$ 1,562.00 | 10% | <i>\$1,416.34</i> |
| EW ResponsePLS 4HR AHR-16502 | 97507-16502 | \$ 1,601.00 | 10% | <i>\$1,451.71</i> |
| EW ResponsePLS 4HR AHR-16502T | 97507-16502T | \$ 1,667.00 | 10% | <i>\$1,511.55</i> |
| EW ResponsePLS 4HR AHR-16503 | 97507-16503 | \$ 1,549.00 | 10% | <i>\$1,404.56</i> |
| EW ResponsePLS 4HR AHR-16503T | 97507-16503T | \$ 1,614.00 | 10% | <i>\$1,463.49</i> |
| EW ResponsePLS 4HR AHR-16504 | 97507-16504 | \$ 1,695.00 | 10% | <i>\$1,536.94</i> |
| EW ResponsePLS 4HR AHR-16504T | 97507-16504T | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-16505 | 97507-16505 | \$ 1,715.00 | 10% | <i>\$1,555.08</i> |
| EW ResponsePLS 4HR AHR-16505T | 97507-16505T | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsePLS 4HR AHR-16506 | 97507-16506 | \$ 1,945.00 | 10% | <i>\$1,763.63</i> |
| EW ResponsePLS 4HR AHR-16506T | 97507-16506T | \$ 2,114.00 | 10% | <i>\$1,916.87</i> |
| EW ResponsePLS 4HR AHR-16507 | 97507-16507 | \$ 1,909.00 | 10% | <i>\$1,730.99</i> |
| EW ResponsePLS 4HR AHR-16507T | 97507-16507T | \$ 2,025.00 | 10% | <i>\$1,836.17</i> |
| EW ResponsePLS 4HR AHR-16508 | 97507-16508 | \$ 2,055.00 | 10% | <i>\$1,863.37</i> |
| EW ResponsePLS 4HR AHR-16508T | 97507-16508T | \$ 2,209.00 | 10% | <i>\$2,003.01</i> |
| EW ResponsePLS 4HR AHR-16509 | 97507-16509 | \$ 2,055.00 | 10% | <i>\$1,863.37</i> |
| EW ResponsePLS 4HR AHR-16509T | 97507-16509T | \$ 2,209.00 | 10% | <i>\$2,003.01</i> |
| EW ResponsePLS 4HR AHR-16510 | 97507-16510 | \$ 2,209.00 | 10% | <i>\$2,003.01</i> |
| EW ResponsePLS 4HR AHR-16510T | 97507-16510T | \$ 2,385.00 | 10% | <i>\$2,162.60</i> |
| EW ResponsePLS 4HR AHR-16513 | 97507-16513 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsePLS 4HR AHR-16514 | 97507-16514 | \$ 2,167.00 | 10% | <i>\$1,964.93</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR-16515 | 97507-16515 | \$ 1,382.00 | 10% | <i>\$1,253.13</i> |
| EW ResponsePLS 4HR AHR-16516 | 97507-16516 | \$ 1,396.00 | 10% | <i>\$1,265.82</i> |
| EW ResponsePLS 4HR AHR-16517 | 97507-16517 | \$ 1,554.00 | 10% | <i>\$1,409.09</i> |
| EW ResponsePLS 4HR AHR-16518 | 97507-16518 | \$ 1,511.00 | 10% | <i>\$1,370.10</i> |
| EW ResponsePLS 4HR AHR-16519 | 97507-16519 | \$ 1,614.00 | 10% | <i>\$1,463.49</i> |
| EW ResponsePLS 4HR AHR-16520 | 97507-16520 | \$ 1,792.00 | 10% | <i>\$1,624.90</i> |
| EW ResponsePLUS 4HR AHR-16530 | 97507-16530 | \$ 1,537.00 | 10% | <i>\$1,393.67</i> |
| EW ResponsePLUS 4HR AHR-16531 | 97507-16531 | \$ 1,605.00 | 10% | <i>\$1,455.33</i> |
| EW ResponsePLUS 4HR AHR-16531T | 97507-16531T | \$ 1,605.00 | 10% | <i>\$1,455.33</i> |
| EW ResponsePLUS 4HR AHR-16532 | 97507-16532 | \$ 1,605.00 | 10% | <i>\$1,455.33</i> |
| EW ResponsePLUS 4HR AHR-16532T | 97507-16532T | \$ 1,605.00 | 10% | <i>\$1,455.33</i> |
| EW ResponsePLUS 4HR AHR-16533 | 97507-16533 | \$ 1,704.00 | 10% | <i>\$1,545.10</i> |
| EW ResponsePLUS 4HR AHR-16533T | 97507-16533T | \$ 1,718.00 | 10% | <i>\$1,557.80</i> |
| EW ResponsePLUS 4HR AHR-16534 | 97507-16534 | \$ 1,725.00 | 10% | <i>\$1,564.14</i> |
| EW ResponsePLUS 4HR AHR-16535 | 97507-16535 | \$ 1,901.00 | 10% | <i>\$1,723.73</i> |
| EW ResponsePLUS 4HR AHR-16535A | 97507-16535A | \$ 1,901.00 | 10% | <i>\$1,723.73</i> |
| EW ResponsePLUS 4HR AHR-16535T | 97507-16535T | \$ 1,954.00 | 10% | <i>\$1,771.79</i> |
| EW ResponsePLUS 4HR AHR-16536 | 97507-16536 | \$ 1,486.00 | 10% | <i>\$1,347.43</i> |
| EW ResponsePLUS 4HR AHR-16537 | 97507-16537 | \$ 1,583.00 | 10% | <i>\$1,435.39</i> |
| EW ResponsePLUS 4HR AHR-16538 | 97507-16538 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLUS 4HR AHR-16538T | 97507-16538T | \$ 1,838.00 | 10% | <i>\$1,666.61</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLUS 4HR AHR-16539 | 97507-16539 | \$ 1,762.00 | 10% | <i>\$1,597.69</i> |
| EW ResponsePLUS 4HR AHR-16540 | 97507-16540 | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW ResponsePLUS 4HR AHR-16541 | 97507-16541 | \$ 1,381.00 | 10% | <i>\$1,252.22</i> |
| EW ResponsePLS 4HR AHR 16560 | 97507-16560 | \$ 1,273.00 | 10% | <i>\$1,154.29</i> |
| EW ResponsePLS 4HR AHR 16561 | 97507-16561 | \$ 1,308.00 | 10% | <i>\$1,186.03</i> |
| EW ResponsePLS 4HR AHR 16562 | 97507-16562 | \$ 1,336.00 | 10% | <i>\$1,211.42</i> |
| EW ResponsePLS 4HR AHR 16563 | 97507-16563 | \$ 1,382.00 | 10% | <i>\$1,253.13</i> |
| EW ResponsePLS 4HR AHR 16564 | 97507-16564 | \$ 1,432.00 | 10% | <i>\$1,298.47</i> |
| EW ResponsePLS 4HR AHR 16565 | 97507-16565 | \$ 1,560.00 | 10% | <i>\$1,414.53</i> |
| EW ResponsePLS 4HR AHR 16566 | 97507-16566 | \$ 1,241.00 | 10% | <i>\$1,125.28</i> |
| EW ResponsePLS 4HR AHR 16567 | 97507-16567 | \$ 1,286.00 | 10% | <i>\$1,166.08</i> |
| EW ResponsePLS 4HR AHR 16568 | 97507-16568 | \$ 1,274.00 | 10% | <i>\$1,155.20</i> |
| EW ResponsePLS 4HR AHR 16569 | 97507-16569 | \$ 1,320.00 | 10% | <i>\$1,196.91</i> |
| EW ResponsePLS 4HR AHR 16570 | 97507-16570 | \$ 1,336.00 | 10% | <i>\$1,211.42</i> |
| EW ResponsePLS 4HR AHR 16571 | 97507-16571 | \$ 1,431.00 | 10% | <i>\$1,297.56</i> |
| EW ResponsePLS 4HR AHR-16701 | 97507-16701 | \$ 1,754.00 | 10% | <i>\$1,590.44</i> |
| EW ResponsePLS 4HR AHR-16702 | 97507-16702 | \$ 2,004.00 | 10% | <i>\$1,817.13</i> |
| EW ResponsePLS 4HR AHR-16703 | 97507-16703 | \$ 1,978.00 | 10% | <i>\$1,793.55</i> |
| EW ResponsePLS 4HR AHR 16703T | 97507-16703T | \$ 2,107.00 | 10% | <i>\$1,910.52</i> |
| EW ResponsePLUS 4HR AHR-16704 | 97507-16704 | \$ 2,248.00 | 10% | <i>\$2,038.37</i> |
| EW ResponsePLS 4HR AHR 16704T | 97507-16704T | \$ 1,891.00 | 10% | <i>\$1,714.66</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR-16705 | 97507-16705 | \$ 2,004.00 | 10% | <i>\$1,817.13</i> |
| EW ResponsePLS 4HR AHR 16705T | 97507-16705T | \$ 2,143.00 | 10% | <i>\$1,943.17</i> |
| EW ResponsePLS 4HR AHR-16706 | 97507-16706 | \$ 2,537.00 | 10% | <i>\$2,300.42</i> |
| EW ResponsePLS 4HR AHR 16706T | 97507-16706T | \$ 2,706.00 | 10% | <i>\$2,453.67</i> |
| EW ResponsePLS 4HR AHR-16710 | 97507-16710 | \$ 660.00 | 10% | <i>\$598.46</i> |
| EW ResponsePLS 4HR AHR 16710T | 97507-16710T | \$ 702.00 | 10% | <i>\$636.54</i> |
| EW ResponsePLS 4HR AHR-16711 | 97507-16711 | \$ 518.00 | 10% | <i>\$469.70</i> |
| EW ResponsePLS 4HR AHR 16711T | 97507-16711T | \$ 552.00 | 10% | <i>\$500.53</i> |
| EW ResponsePLS 4HR AHR-16712 | 97507-16712 | \$ 564.00 | 10% | <i>\$511.41</i> |
| EW ResponsePLS 4HR AHR 16712T | 97507-16712T | \$ 584.00 | 10% | <i>\$529.54</i> |
| EW ResponsePLS 4HR AHR-16713 | 97507-16713 | \$ 479.00 | 10% | <i>\$434.33</i> |
| EW ResponsePLS 4HR AHR 16713T | 97507-16713T | \$ 514.00 | 10% | <i>\$466.07</i> |
| EW ResponsePLS 4HR AHR-16715 | 97507-16715 | \$ 505.00 | 10% | <i>\$457.91</i> |
| EW ResponsePLS 4HR AHR 16715T | 97507-16715T | \$ 552.00 | 10% | <i>\$500.53</i> |
| EW ResponsePLS 4HR AHR-16716 | 97507-16716 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR 16716T | 97507-16716T | \$ 1,900.00 | 10% | <i>\$1,722.83</i> |
| EW ResponsePLS 4HR AHR-16717 | 97507-16717 | \$ 1,857.00 | 10% | <i>\$1,683.83</i> |
| EW ResponsePLS 4HR AHR-16718 | 97507-16718 | \$ 1,811.00 | 10% | <i>\$1,642.12</i> |
| EW ResponsePLS 4HR AHR-16719 | 97507-16719 | \$ 1,892.00 | 10% | <i>\$1,715.57</i> |
| EW ResponsePLS 4HR AHR 16720 | 97507-16720 | \$ 2,238.00 | 10% | <i>\$2,029.31</i> |
| EW ResponsePLS 4HR AHR 16720T | 97507-16720T | \$ 2,607.00 | 10% | <i>\$2,363.90</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR 16756 | 97507-16756 | \$ 2,075.00 | 10% | <i>\$1,881.51</i> |
| EW ResponsePLS 4HR AHR 16756T | 97507-16756T | \$ 2,449.00 | 10% | <i>\$2,220.63</i> |
| EW ResponsePLS 4HR AHR 16757 | 97507-16757 | \$ 2,035.00 | 10% | <i>\$1,845.24</i> |
| EW ResponsePLS 4HR AHR 16757T | 97507-16757T | \$ 2,402.00 | 10% | <i>\$2,178.01</i> |
| EW ResponsePLS 4HR AHR 16790 | 97507-16790 | \$ 2,237.00 | 10% | <i>\$2,028.40</i> |
| EW ResponsePLS 4HR AHR 16791 | 97507-16791 | \$ 2,885.00 | 10% | <i>\$2,615.97</i> |
| EW ResponsePLS 4HR AHR- 17101 | 97507-17101 | \$ 4,135.00 | 10% | <i>\$3,749.41</i> |
| EW ResponsePLS 4HR AHR- 17101T | 97507-17101T | \$ 5,152.00 | 10% | <i>\$4,671.58</i> |
| EW ResponsePLS 4HR AHR- 17102 | 97507-17102 | \$ 4,135.00 | 10% | <i>\$3,749.41</i> |
| EW ResponsePLS 4HR AHR- 17102T | 97507-17102T | \$ 5,152.00 | 10% | <i>\$4,671.58</i> |
| EW ResponsePLS 4HR AHR- 17103 | 97507-17103 | \$ 3,225.00 | 10% | <i>\$2,924.27</i> |
| EW ResponsePLS 4HR AHR- 17103C | 97507-17103C | \$ 3,131.00 | 10% | <i>\$2,839.03</i> |
| EW ResponsePLS 4HR AHR- 17103T | 97507-17103T | \$ 3,992.00 | 10% | <i>\$3,619.75</i> |
| EW ResponsePLS 4HR AHR- 17104 | 97507-17104 | \$ 3,225.00 | 10% | <i>\$2,924.27</i> |
| EW ResponsePLS 4HR AHR- 17104T | 97507-17104T | \$ 3,992.00 | 10% | <i>\$3,619.75</i> |
| EW ResponsePLS 4HR AHR- 17121 | 97507-17121 | \$ 1,038.00 | 10% | <i>\$941.21</i> |
| EW ResponsePLS 4HR AHR- 17122 | 97507-17122 | \$ 790.00 | 10% | <i>\$716.33</i> |
| EW ResponsePLS 4HR AHR- 17200 | 97507-17200 | \$ 5,863.00 | 10% | <i>\$5,316.28</i> |
| EW ResponsePLS 4HR AHR- 17200T | 97507-17200T | \$ 6,586.00 | 10% | <i>\$5,971.86</i> |
| EW ResponsePLS 4HR AHR- 17201 | 97507-17201 | \$ 5,863.00 | 10% | <i>\$5,316.28</i> |
| EW ResponsePLS 4HR AHR- 17201T | 97507-17201T | \$ 6,586.00 | 10% | <i>\$5,971.86</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|------------|
| EW ResponsePLS 4HR AHR-17202 | 97507-17202 | \$ 5,863.00 | 10% | \$5,316.28 |
| EW ResponsePLS 4HR AHR-17202T | 97507-17202T | \$ 6,586.00 | 10% | \$5,971.86 |
| EW ResponsePLS 4HR AHR-17203 | 97507-17203 | \$ 5,934.00 | 10% | \$5,380.65 |
| EW ResponsePLS 4HR AHR-17203T | 97507-17203T | \$ 6,670.00 | 10% | \$6,048.02 |
| EW ResponsePLS 4HR AHR-17204 | 97507-17204 | \$ 5,934.00 | 10% | \$5,380.65 |
| EW ResponsePLS 4HR AHR-17204T | 97507-17204T | \$ 6,670.00 | 10% | \$6,048.02 |
| EW ResponsePLS 4HR AHR-17205 | 97507-17205 | \$ 5,901.00 | 10% | \$5,350.73 |
| EW ResponsePLS 4HR AHR-17205T | 97507-17205T | \$ 6,626.00 | 10% | \$6,008.13 |
| EW ResponsePLS 4HR AHR-17206 | 97507-17206 | \$ 5,901.00 | 10% | \$5,350.73 |
| EW ResponsePLS 4HR AHR-17206T | 97507-17206T | \$ 6,626.00 | 10% | \$6,008.13 |
| EW ResponsePLS 4HR AHR-17300 | 97507-17300 | \$ 4,347.00 | 10% | \$3,941.64 |
| EW ResponsePLS 4HR AHR-17310 | 97507-17310 | \$ 4,050.00 | 10% | \$3,672.34 |
| EW ResponsePLS 4HR AHR 17350 | 97507-17350 | \$ 4,205.00 | 10% | \$3,812.88 |
| EW ResponsePLS 4HR AHR 17360 | 97507-17360 | \$ 4,899.00 | 10% | \$4,442.17 |
| EW ResponsePLS 4HR AHR 17401 | 97507-17401 | \$ 1,655.00 | 10% | \$1,500.67 |
| EW ResponsePLS 4HR AHR 17401G | 97507-17401G | \$ 1,704.00 | 10% | \$1,545.10 |
| EW ResponsePLS 4HR AHR 17401T | 97507-17401T | \$ 1,704.00 | 10% | \$1,545.10 |
| EW ResponsePLS 4HR AHR 17402 | 97507-17402 | \$ 1,762.00 | 10% | \$1,597.69 |
| EW ResponsePLS 4HR AHR 17402G | 97507-17402G | \$ 1,731.00 | 10% | \$1,569.58 |
| EW ResponsePLS 4HR AHR 17402T | 97507-17402T | \$ 1,731.00 | 10% | \$1,569.58 |
| EW ResponsePLS 4HR AHR 17403 | 97507-17403 | \$ 1,806.00 | 10% | \$1,637.59 |

| | | | | |
|-------------------------------------|---------------------|--------------|-----|-------------------|
| EW ResponsePLS 4HR AHR 17404 | 97507-17404 | \$ 1,541.00 | 10% | <i>\$1,397.30</i> |
| EW ResponsePLS 4HR AHR 17405 | 97507-17405 | \$ 1,541.00 | 10% | <i>\$1,397.30</i> |
| EW ResponsePLS 4HR AHR 17700 | 97507-17700 | \$ 6,955.00 | 10% | <i>\$6,306.45</i> |
| EW ResponsePLS 4HR AHR- 17701 | 97507-17701 | \$ 5,972.00 | 10% | <i>\$5,415.11</i> |
| EW ResponsePLS 4HR AHR- 17702 | 97507-17702 | \$ 5,972.00 | 10% | <i>\$5,415.11</i> |
| EW ResponsePLS 4HR AHR- 17703 | 97507-17703 | \$ 6,524.00 | 10% | <i>\$5,915.64</i> |
| EW ResponsePLS 4HR AHR- 17704 | 97507-17704 | \$ 6,524.00 | 10% | <i>\$5,915.64</i> |
| EW ResponsePLS 4HR AHR- 17705 | 97507-17705 | \$ 6,009.00 | 10% | <i>\$5,448.66</i> |
| EW ResponsePLS 4HR AHR- 17706 | 97507-17706 | \$ 6,009.00 | 10% | <i>\$5,448.66</i> |
| EW ResponsePLS 4HR AHR 17800 | 97507-17800 | \$ 7,061.00 | 10% | <i>\$6,402.56</i> |
| EW ResponsePLS 4HR AHR 17810 | 97507-17810 | \$ 5,893.00 | 10% | <i>\$5,343.48</i> |
| EW ResponsePLS 4HR AHR 18101 | 97507-18101 | \$ 667.00 | 10% | <i>\$604.80</i> |
| EW ResponsePLS 4HR AHR 18102 | 97507-18102 | \$ 744.00 | 10% | <i>\$674.62</i> |
| EW ResponsePLS 4HR AHR 18103 | 97507-18103 | \$ 782.00 | 10% | <i>\$709.08</i> |
| EW ResponsePLS 4HR AHR 18104 | 97507-18104 | \$ 956.00 | 10% | <i>\$866.85</i> |
| EW ResponsePLS 4HR AHR 18104-6PK | 97507-18104- 6PK | \$ 5,738.00 | 10% | <i>\$5,202.93</i> |
| EW ResponsePLS 4HR AHR- 30135 | 97507-30135 | \$ 3,186.00 | 10% | <i>\$2,888.91</i> |
| EW ResponsePLS 4HR AHR 30136 | 97507-30136 | \$ 9,176.00 | 10% | <i>\$8,320.34</i> |
| EW ResponsePLS 4HR AHR 30137 | 97507-30137 | \$ 2,420.00 | 10% | <i>\$2,194.34</i> |
| EW ResponsePLS 4HR AHR 30138 | 97507-30138 | \$ 6,348.00 | 10% | <i>\$5,756.05</i> |
| EW ResponsePLS 4HR AHR 30139 | 97507-30139 | \$ 10,794.00 | 10% | <i>\$9,787.46</i> |

| | | | | |
|---------------------------------|-------------|-----------|-----|-----------------|
| EW ResponsePLS 4HR AHR 30912 | 97507-30912 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsePLS 4HR AHR 30913 | 97507-30913 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsePLS 4HR AHR 31012 | 97507-31012 | \$ 459.00 | 10% | <i>\$416.20</i> |
| EW ResponsePLS 4HR AHR 31013 | 97507-31013 | \$ 459.00 | 10% | <i>\$416.20</i> |
| EW ResponsePLS 4HR AHR 31014 | 97507-31014 | \$ 459.00 | 10% | <i>\$416.20</i> |
| EW ResponsePLS 4HR AHR 31015 | 97507-31015 | \$ 459.00 | 10% | <i>\$416.20</i> |
| EW ResponsePLS 4HR AHR 31016 | 97507-31016 | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW ResponsePLS 4HR AHR 31017 | 97507-31017 | \$ 638.00 | 10% | <i>\$578.51</i> |
| EW ResponsePLS 4HR AHR 31018 | 97507-31018 | \$ 683.00 | 10% | <i>\$619.31</i> |
| EW ResponsePLS 4HR AHR 31019 | 97507-31019 | \$ 683.00 | 10% | <i>\$619.31</i> |
| EW ResponsePLS 4HR AHR 31025 | 97507-31025 | \$ 360.00 | 10% | <i>\$326.43</i> |
| EW ResponsePLS 4HR AHR 31026 | 97507-31026 | \$ 360.00 | 10% | <i>\$326.43</i> |
| EW ResponsePLS 4HR AHR 31028 | 97507-31028 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsePLS 4HR AHR 31029 | 97507-31029 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsePLS 4HR AHR 31031 | 97507-31031 | \$ 375.00 | 10% | <i>\$340.03</i> |
| EW ResponsePLS 4HR AHR 31032 | 97507-31032 | \$ 375.00 | 10% | <i>\$340.03</i> |
| EW ResponsePLS 4HR AHR 31034 | 97507-31034 | \$ 456.00 | 10% | <i>\$413.48</i> |
| EW ResponsePLS 4HR AHR 31035 | 97507-31035 | \$ 456.00 | 10% | <i>\$413.48</i> |
| EW ResponsePLS 4HR AHR 31050 | 97507-31050 | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR 31051 | 97507-31051 | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR 31055 | 97507-31055 | \$ 420.00 | 10% | <i>\$380.84</i> |

| | | | | |
|--|------------------------|-------------|-----|------------|
| EW ResponsePLS 4HR AHR 31056 | 97507-31056 | \$ 420.00 | 10% | \$380.84 |
| EW ResponsePLS 4HR AHR 39031 | 97507-39031 | \$ 770.00 | 10% | \$698.20 |
| EW ResponsePLS 4HR AHR 39032 | 97507-39032 | \$ 895.00 | 10% | \$811.54 |
| EW ResponsePLS 4HR AHR 39033 | 97507-39033 | \$ 770.00 | 10% | \$698.20 |
| EW ResponsePLS 4HR AHR 39034 | 97507-39034 | \$ 770.00 | 10% | \$698.20 |
| EW ResponsePLS 4HR AHR 39035 | 97507-39035 | \$ 1,705.00 | 10% | \$1,546.01 |
| EW ResponsePLS 4HR AHR 39036 | 97507-39036 | \$ 749.00 | 10% | \$679.16 |
| EW ResponsePLS 4HR AHR 39037 | 97507-39037 | \$ 749.00 | 10% | \$679.16 |
| EW ResponsePLS 4HR AHR 39038 | 97507-39038 | \$ 906.00 | 10% | \$821.52 |
| EW ResponsePLS 4HR AHR 39039 | 97507-39039 | \$ 906.00 | 10% | \$821.52 |
| EW ResponsePLS 4HR AHR 4120-24MW-4Y | 97507-4120- 24MW-4Y | \$ 1,686.00 | 10% | \$1,528.78 |
| EW ResponsePLS 4HR AHR 4120-48MW-4Y | 97507-4120- 48MW-4Y | \$ 1,978.00 | 10% | \$1,793.55 |
| EW ResponsePLS 4HR AHR 4120C | 97507-4120C | \$ 7,217.00 | 10% | \$6,544.01 |
| EW ResponsePLS 4HR AHR 4120C-1 | 97507-4120C-1 | \$ 8,148.00 | 10% | \$7,388.20 |
| EW ResponsePLS 4HR AHR 41216 | 97507-41216 | \$ 2,357.00 | 10% | \$2,137.21 |
| EW ResponsePLS 4HR AHR 4220-12P-4X | 97507-4220- 12P-4X | \$ 1,063.00 | 10% | \$963.88 |
| EW ResponsePLS 4HR AHR 4220-12T-4X | 97507-4220- 12T-4X | \$ 995.00 | 10% | \$902.22 |
| EW ResponsePLS 4HR AHR 4220-24P-4X | 97507-4220- 24P-4X | \$ 1,148.00 | 10% | \$1,040.95 |
| EW ResponsePLS 4HR AHR 4220-24T-4X | 97507-4220- 24T-4X | \$ 1,072.00 | 10% | \$972.04 |
| EW ResponsePLS 4HR AHR 4220-48P-4X | 97507-4220- 48P-4X | \$ 1,318.00 | 10% | \$1,195.10 |
| EW ResponsePLS 4HR AHR 4220-48T-4X | 97507-4220- 48T-4X | \$ 1,191.00 | 10% | \$1,079.94 |

| | | | | |
|--|-----------------------------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR 4220-4MW-20P-4X | 97507-4220- 4MW-20P-4X | \$ 1,276.00 | 10% | <i>\$1,157.01</i> |
| EW ResponsePLS 4HR AHR 4220-4MW-8P-4X | 97507-4220- 4MW-8P-4X | \$ 1,140.00 | 10% | <i>\$1,033.70</i> |
| EW ResponsePLS 4HR AHR 4220-8MW-40P-4X | 97507-4220- 8MW-40P-4X | \$ 1,488.00 | 10% | <i>\$1,349.24</i> |
| EW ResponsePLS 4HR AHR 4220-8X | 97507-4220-8X | \$ 1,165.00 | 10% | <i>\$1,056.36</i> |
| EW ResponsePLS 4HR AHR- 48001 | 97507-48001 | \$ 10,360.00 | 10% | <i>\$9,393.93</i> |
| EW ResponsePLS 4HR AHR- 48038 | 97507-48038 | \$ 3,622.00 | 10% | <i>\$3,284.25</i> |
| EW ResponsePLS 4HR AHR- 48039 | 97507-48039 | \$ 3,622.00 | 10% | <i>\$3,284.25</i> |
| EW ResponsePLS 4HR AHR- 48040 | 97507-48040 | \$ 3,498.00 | 10% | <i>\$3,171.81</i> |
| EW ResponsePLS 4HR AHR- 48041 | 97507-48041 | \$ 3,622.00 | 10% | <i>\$3,284.25</i> |
| EW ResponsePLS 4HR AHR- 48046 | 97507-48046 | \$ 4,618.00 | 10% | <i>\$4,187.37</i> |
| EW ResponsePLS 4HR AHR- 48047 | 97507-48047 | \$ 11,550.00 | 10% | <i>\$10,472.96</i> |
| EW ResponsePLS 4HR AHR- 48051 | 97507-48051 | \$ 8,080.00 | 10% | <i>\$7,326.54</i> |
| EW ResponsePLS 4HR AHR- 48061 | 97507-48061 | \$ 9,372.00 | 10% | <i>\$8,498.06</i> |
| EW ResponsePLS 4HR AHR- 48062 | 97507-48062 | \$ 14,718.00 | 10% | <i>\$13,345.55</i> |
| EW ResponsePLS 4HR AHR 5320-16P-4XE | 97507-5320- 16P-4XE | \$ 1,337.00 | 10% | <i>\$1,212.32</i> |
| EW ResponsePLS 4HR AHR 5320-16P-4XE-DC | 97507-5320- 16P-4XE-DC | \$ 1,404.00 | 10% | <i>\$1,273.08</i> |
| EW ResponsePLS 4HR AHR 5320-24P-8XE | 97507-5320- 24P-8XE | \$ 1,368.00 | 10% | <i>\$1,240.43</i> |
| EW ResponsePLS 4HRAH 5320- 24T-24S-4XE-XT | 97507-5320- 24T-24S-4XE- XT | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW ResponsePLS 4HR AHR 5320-24T-4X-XT | 97507-5320- 24T-4X-XT | \$ 1,106.00 | 10% | <i>\$1,002.87</i> |
| EW ResponsePLS 4HR AHR 5320-24T-8XE | 97507-5320- 24T-8XE | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR 5320-48P-8XE | 97507-5320- 48P-8XE | \$ 1,680.00 | 10% | <i>\$1,523.34</i> |
| EW ResponsePLS 4HR AHR 5320-48T-8XE | 97507-5320- 48T-8XE | \$ 1,475.00 | 10% | <i>\$1,337.46</i> |
| EW ResponsPLS 4HR AHR 5420F-16MW-32P-4XE | 97507-5420F- 16MW-32P- 4XE | \$ 2,301.00 | 10% | <i>\$2,086.43</i> |
| EW ResponsePLS 4HR AHR 5420F-16W-32P-4XE | 97507-5420F- 16W-32P-4XE | \$ 2,248.00 | 10% | <i>\$2,038.37</i> |
| EW ResponsePLS 4HR AHR 5420F-24P-4XE | 97507-5420F- 24P-4XE | \$ 1,642.00 | 10% | <i>\$1,488.88</i> |
| EW ResponsePLS 4HR AHR 5420F-24S-4XE | 97507-5420F- 24S-4XE | \$ 1,701.00 | 10% | <i>\$1,542.38</i> |
| EW ResponsePLS 4HR AHR 5420F-24T-4XE | 97507-5420F- 24T-4XE | \$ 1,604.00 | 10% | <i>\$1,454.43</i> |
| EW ResponsePLS 4HR AHR 5420F-48P-4XE | 97507-5420F- 48P-4XE | \$ 1,869.00 | 10% | <i>\$1,694.72</i> |
| EW ResponsePLS 4HR AHR 5420F-48P-4XL | 97507-5420F- 48P-4XL | \$ 2,014.00 | 10% | <i>\$1,826.19</i> |
| EW ResponsePLS 4HR AHR 5420F-48T-4XE | 97507-5420F- 48T-4XE | \$ 1,656.00 | 10% | <i>\$1,501.58</i> |
| EW ResponsePLS 4HR AHR 5420F-8W-16P-4XE | 97507-5420F- 8W-16P-4XE | \$ 1,683.00 | 10% | <i>\$1,526.06</i> |
| EW ResponsPLS 4HR AHR 5420M-16MW-32P-4YE | 97507-5420M- 16MW-32P- 4YE | \$ 2,419.00 | 10% | <i>\$2,193.43</i> |
| EW ResponsePLS 4HR AHR 5420M-24T-4YE | 97507-5420M- 24T-4YE | \$ 1,677.00 | 10% | <i>\$1,520.62</i> |
| EW ResponsePLS 4HR AHR 5420M-24W-4YE | 97507-5420M- 24W-4YE | \$ 1,534.00 | 10% | <i>\$1,390.95</i> |
| EW ResponsePLS 4HR AHR 5420M-48T-4YE | 97507-5420M- 48T-4YE | \$ 1,870.00 | 10% | <i>\$1,695.62</i> |
| EW ResponsePLS 4HR AHR 5420M-48W-4YE | 97507-5420M- 48W-4YE | \$ 2,017.00 | 10% | <i>\$1,828.91</i> |
| EW RESPONSEPLUS 4HR AHR 5520-12MW-36W | 97507-5520- 12MW-36W | \$ 2,527.00 | 10% | <i>\$2,291.36</i> |
| EW RESPONSEPLUS 4HR AHR 5520-24T | 97507-5520- 24T | \$ 1,674.00 | 10% | <i>\$1,517.90</i> |
| EW RESPONSEPLU 4HR AH 5520-24T-ACDC-BASE | 97507-5520- 24T-ACDC- BASE | \$ 1,674.00 | 10% | <i>\$1,517.90</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EW RESPONSEPLUS 4HR AHR 5520-24T-BASE | 97507-5520- 24T-BASE | \$ 1,674.00 | 10% | <i>\$1,517.90</i> |
| EW RESPONSEPLUS 4HR AHR 5520-24W | 97507-5520- 24W | \$ 1,757.00 | 10% | <i>\$1,593.16</i> |
| EW RESPONSEPLUS 4HR AHR 5520-24X | 97507-5520- 24X | \$ 2,615.00 | 10% | <i>\$2,371.15</i> |
| EW RESPONSEPLU 4HR AH 5520-24X-ACDC-BASE | 97507-5520- 24X-ACDC- BASE | \$ 2,615.00 | 10% | <i>\$2,371.15</i> |
| EW RESPONSEPLUS 4HR AHR 5520-24X-BASE | 97507-5520- 24X-BASE | \$ 2,615.00 | 10% | <i>\$2,371.15</i> |
| EW RESPONSEPLUS 4HR AHR 5520-48SE | 97507-5520- 48SE | \$ 2,488.00 | 10% | <i>\$2,255.99</i> |
| EW RESPONSEPL 4HR AH 5520-48SE-ACDC-BASE | 97507-5520- 48SE-ACDC- BASE | \$ 2,488.00 | 10% | <i>\$2,255.99</i> |
| EW RESPONSEPLUS 4HR AHR 5520-48SE-BASE | 97507-5520- 48SE-BASE | \$ 2,488.00 | 10% | <i>\$2,255.99</i> |
| EW RESPONSEPLUS 4HR AHR 5520-48T | 97507-5520- 48T | \$ 2,034.00 | 10% | <i>\$1,844.33</i> |
| EW RESPONSEPLU 4HR AH 5520-48T-ACDC-BASE | 97507-5520- 48T-ACDC- BASE | \$ 2,034.00 | 10% | <i>\$1,844.33</i> |
| EW RESPONSEPLUS 4HR AHR 5520-48T-BASE | 97507-5520- 48T-BASE | \$ 2,034.00 | 10% | <i>\$1,844.33</i> |
| EW RESPONSEPLUS 4HR AHR 5520-48W | 97507-5520- 48W | \$ 2,313.00 | 10% | <i>\$2,097.31</i> |
| EW ResponsePLS 4HR AHR 5720-24MW | 97507-5720- 24MW | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsePLS 4HR AHR 5720-24MXW | 97507-5720- 24MXW | \$ 2,837.00 | 10% | <i>\$2,572.45</i> |
| EW ResponsePLS 4HR AHR 5720-48MW | 97507-5720- 48MW | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsePLS 4HR AHR 5720-48MXW | 97507-5720- 48MXW | \$ 3,298.00 | 10% | <i>\$2,990.46</i> |
| EW ResponsePLS 4HR AHR 7520-48XT-6C | 97507-7520- 48XT-6C | \$ 3,902.00 | 10% | <i>\$3,538.14</i> |
| EW ResponsePLS 4HR AHR 7520-48XT-6C-AC-F | 97507-7520- 48XT-6C-AC- F | \$ 3,902.00 | 10% | <i>\$3,538.14</i> |
| EW ResponsePLS 4HR AH 7520- 48XT-6C-AC-R | 97507-7520- 48XT-6C-AC- R | \$ 3,902.00 | 10% | <i>\$3,538.14</i> |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR 7520-48Y-8C | 97507-7520- 48Y-8C | \$ 3,646.00 | 10% | <i>\$3,306.01</i> |
| EW ResponsePLS 4HR AHR 7520-48Y-8C-AC-F | 97507-7520- 48Y-8C-AC-F | \$ 3,646.00 | 10% | <i>\$3,306.01</i> |
| EW ResponsePLS 4HR AHR 7520-48Y-8C-AC-R | 97507-7520- 48Y-8C-AC-R | \$ 3,646.00 | 10% | <i>\$3,306.01</i> |
| EW RESPONSEPLUS 4HR AHR 7520-48YE-8CE | 97507-7520- 48YE-8CE | \$ 4,212.00 | 10% | <i>\$3,819.23</i> |
| EW RESPONSEPLU 4HRAHR 7520-48YE-8CE-AC-F | 97507-7520- 48YE-8CE-AC- F | \$ 4,212.00 | 10% | <i>\$3,819.23</i> |
| EW RESPONSEPLU 4HRAHR 7520-48YE-8CE-AC-R | 97507-7520- 48YE-8CE-AC- R | \$ 4,212.00 | 10% | <i>\$3,819.23</i> |
| EW ResponsePLS 4HR AHR 7720-32C | 97507-7720- 32C | \$ 4,502.00 | 10% | <i>\$4,082.19</i> |
| EW ResponsePLS 4HR AHR 7720-32C-AC-F | 97507-7720- 32C-AC-F | \$ 4,502.00 | 10% | <i>\$4,082.19</i> |
| EW ResponsePLS 4HR AHR 7720-32C-AC-R | 97507-7720- 32C-AC-R | \$ 4,502.00 | 10% | <i>\$4,082.19</i> |
| EW ResponsePLS 4HR AHR 8520-48XT-6C | 97507-8520- 48XT-6C | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsePLS 4HR AHR 8520-48XT-6C-AC-F | 97507-8520- 48XT-6C-AC- F | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsePLS 4HR AHR 8520-48XT-6C-AC-R | 97507-8520- 48XT-6C-AC- R | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsePLS 4HR AHR 8520-48XT-6C-DC-F | 97507-8520- 48XT-6C-DC- F | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsePLS 4HR AHR 8520-48XT-6C-DC-R | 97507-8520- 48XT-6C-DC- R | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsePLS 4HR AHR 8520-48Y-8C | 97507-8520- 48Y-8C | \$ 4,436.00 | 10% | <i>\$4,022.34</i> |
| EW ResponsePLS 4HR AHR 8520-48Y-8C-AC-F | 97507-8520- 48Y-8C-AC-F | \$ 4,436.00 | 10% | <i>\$4,022.34</i> |
| EW ResponsePLS 4HR AHR 8520-48Y-8C-AC-R | 97507-8520- 48Y-8C-AC-R | \$ 4,436.00 | 10% | <i>\$4,022.34</i> |
| EW ResponsePLS 4HR AHR 8520-48Y-8C-DC-F | 97507-8520- 48Y-8C-DC-F | \$ 4,436.00 | 10% | <i>\$4,022.34</i> |

| | | | | |
|--|----------------------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR 8520-48Y-8C-DC-R | 97507-8520- 48Y-8C-DC-R | \$ 4,436.00 | 10% | <i>\$4,022.34</i> |
| EW ResponsePLS 4HR AHR 8720-32C | 97507-8720- 32C | \$ 4,892.00 | 10% | <i>\$4,435.82</i> |
| EW ResponsePLS 4HR AHR 8720-32C-AC-F | 97507-8720- 32C-AC-F | \$ 4,892.00 | 10% | <i>\$4,435.82</i> |
| EW ResponsePLS 4HR AHR 8720-32C-AC-R | 97507-8720- 32C-AC-R | \$ 4,892.00 | 10% | <i>\$4,435.82</i> |
| EW ResponsePLS 4HR AHR 8720-32C-DC-F | 97507-8720- 32C-DC-F | \$ 4,892.00 | 10% | <i>\$4,435.82</i> |
| EW ResponsePLS 4HR AHR 8720-32C-DC-R | 97507-8720- 32C-DC-R | \$ 4,892.00 | 10% | <i>\$4,435.82</i> |
| EW ResponsePLUS 4HR AHR- 8806 | 97507-8806 | \$ 4,611.00 | 10% | <i>\$4,181.02</i> |
| EW ResponsePLS 4HR AHR- 8810 | 97507-8810 | \$ 9,151.00 | 10% | <i>\$8,297.67</i> |
| EW ResponsePLS 4HR AHR 8820-40C | 97507-8820- 40C | \$ 14,145.00 | 10% | <i>\$12,825.98</i> |
| EW ResponsePLS 4HR AHR 8820-40C-AC-F | 97507-8820- 40C-AC-F | \$ 14,145.00 | 10% | <i>\$12,825.98</i> |
| EW ResponsePLS 4HR AHR 8820-40C-AC-R | 97507-8820- 40C-AC-R | \$ 14,145.00 | 10% | <i>\$12,825.98</i> |
| EW ResponsePLS 4HR AHR 8820-40C-DC-F | 97507-8820- 40C-DC-F | \$ 14,145.00 | 10% | <i>\$12,825.98</i> |
| EW ResponsePLS 4HR AHR 8820-40C-DC-R | 97507-8820- 40C-DC-R | \$ 14,145.00 | 10% | <i>\$12,825.98</i> |
| EW ResponsePLS 4HR AHR 8820-80C | 97507-8820- 80C | \$ 24,889.00 | 10% | <i>\$22,568.10</i> |
| EW ResponsePLS 4HR AHR 8820-80C-AC-F | 97507-8820- 80C-AC-F | \$ 24,889.00 | 10% | <i>\$22,568.10</i> |
| EW ResponsePLS 4HR AHR 8820-80C-AC-R | 97507-8820- 80C-AC-R | \$ 24,889.00 | 10% | <i>\$22,568.10</i> |
| EW ResponsePLS 4HR AHR 8820-80C-DC-F | 97507-8820- 80C-DC-F | \$ 24,889.00 | 10% | <i>\$22,568.10</i> |
| EW ResponsePLS 4HR AHR 8820-80C-DC-R | 97507-8820- 80C-DC-R | \$ 24,889.00 | 10% | <i>\$22,568.10</i> |
| EW ResponsePLS 4HR AHR 9920-16C | 97507-9920- 16C | \$ 11,643.00 | 10% | <i>\$10,557.29</i> |
| EW ResponsePLS 4HR AHR 9920-4D | 97507-9920-4D | \$ 11,643.00 | 10% | <i>\$10,557.29</i> |
| EW ResponsePLS 4HR AHR 9920-NPB-8 | 97507-9920- NPB-8 | \$ 17,785.00 | 10% | <i>\$16,126.55</i> |

| | | | | |
|---|---------------------------------|-----------|-----|----------|
| EW ResponsePLS 4HR AHR AH-AP-1130-AC-CE | 97507-AH-AP- 1130-AC-CE | \$ 406.00 | 10% | \$368.14 |
| EW ResponsePLS 4HR AHR AH-AP-1130-AC-FCC | 97507-AH-AP- 1130-AC-FCC | \$ 406.00 | 10% | \$368.14 |
| EW ResponsePLS 4HR AHR AH-AP-1130-AC-W | 97507-AH-AP- 1130-AC-W | \$ 406.00 | 10% | \$368.14 |
| EW ResponsePLS 4HR AHR AH-AP-122-AC-CAN | 97507-AH-AP- 122-AC-CAN | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-122-AC-CE | 97507-AH-AP- 122-AC-CE | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-122-AC-FCC | 97507-AH-AP- 122-AC-FCC | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-122-AC-W | 97507-AH-AP- 122-AC-W | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-130-AC-CE | 97507-AH-AP- 130-AC-CE | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-130-AC-FCC | 97507-AH-AP- 130-AC-FCC | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-130-AC-W | 97507-AH-AP- 130-AC-W | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-150W-AC-CAN | 97507-AH-AP- 150W-AC- CAN | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-150W-AC-CE | 97507-AH-AP- 150W-AC-CE | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-150W-AC-FCC | 97507-AH-AP- 150W-AC-FCC | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-150W-AC-W | 97507-AH-AP- 150W-AC-W | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-230-AC-CE | 97507-AH-AP- 230-AC-CE | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-230-AC-FCC | 97507-AH-AP- 230-AC-FCC | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-230-AC-W | 97507-AH-AP- 230-AC-W | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-250-AC-CAN | 97507-AH-AP- 250-AC-CAN | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-250-AC-CE | 97507-AH-AP- 250-AC-CE | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-250-AC-FCC | 97507-AH-AP- 250-AC-FCC | \$ 368.00 | 10% | \$333.68 |

| | | | | |
|---|---------------------------------|-----------|-----|----------|
| EW ResponsePLS 4HR AHR AH-AP-250-AC-W | 97507-AH-AP- 250-AC-W | \$ 368.00 | 10% | \$333.68 |
| EW ResponsePLS 4HR AHR AH-AP-630-AX-CAN | 97507-AH-AP- 630-AX-CAN | \$ 413.00 | 10% | \$374.49 |
| EW ResponsePLS 4HR AHR AH-AP-630-AX-CE | 97507-AH-AP- 630-AX-CE | \$ 413.00 | 10% | \$374.49 |
| EW ResponsePLS 4HR AHR AH-AP-630-AX-FCC | 97507-AH-AP- 630-AX-FCC | \$ 413.00 | 10% | \$374.49 |
| EW ResponsePLS 4HR AHR AH-AP-630-AX-W | 97507-AH-AP- 630-AX-W | \$ 413.00 | 10% | \$374.49 |
| EW ResponsePLS 4HR AHR AH-AP-650-AX-CAN | 97507-AH-AP- 650-AX-CAN | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-AP-650-AX-CE | 97507-AH-AP- 650-AX-CE | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-AP-650-AX-FCC | 97507-AH-AP- 650-AX-FCC | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-AP-650-AX-W | 97507-AH-AP- 650-AX-W | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-AP-650X-AX-CAN | 97507-AH-AP- 650X-AX- CAN | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-AP-650X-AX-CE | 97507-AH-AP- 650X-AX-CE | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-AP-650X-AX-FCC | 97507-AH-AP- 650X-AX-FCC | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-AP-650X-AX-W | 97507-AH-AP- 650X-AX-W | \$ 365.00 | 10% | \$330.96 |
| EW ResponsePLS 4HR AHR AH-ATOM-CAN | 97507-AH- ATOM-CAN | \$ 387.00 | 10% | \$350.91 |
| EW ResponsePLS 4HR AHR AH-ATOM-CE-EU | 97507-AH- ATOM-CE-EU | \$ 406.00 | 10% | \$368.14 |
| EW ResponsePLS 4HR AHR AH-ATOM-CE-UK | 97507-AH- ATOM-CE-UK | \$ 406.00 | 10% | \$368.14 |
| EW ResponsePLS 4HR AHR AH-ATOM-FCC | 97507-AH- ATOM-FCC | \$ 386.00 | 10% | \$350.01 |
| EW ResponsePLS 4HR AHR AH-ATOM-W | 97507-AH- ATOM-W | \$ 387.00 | 10% | \$350.91 |
| EW ResponsePLS 4HR AHR AH-ATOM-W-EU | 97507-AH- ATOM-W-EU | \$ 406.00 | 10% | \$368.14 |

| | | | | |
|--|--------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR AH-ATOM-W-UK | 97507-AH- ATOM-W-UK | \$ 406.00 | 10% | <i>\$368.14</i> |
| EW ResponsePLS 4HR AHR AH-SR-2208P-AU | 97507-AH-SR- 2208P-AU | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |
| EW ResponsePLS 4HR AHR AH-SR-2208P-EU | 97507-AH-SR- 2208P-EU | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |
| EW ResponsePLS 4HR AHR AH-SR-2208P-NA | 97507-AH-SR- 2208P-NA | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |
| EW ResponsePLS 4HR AHR AH-SR-2208P-UK | 97507-AH-SR- 2208P-UK | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |
| EW ResponsePLS 4HR AHR AH-SR-2224P-AU | 97507-AH-SR- 2224P-AU | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW ResponsePLS 4HR AHR AH-SR-2224P-EU | 97507-AH-SR- 2224P-EU | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW ResponsePLS 4HR AHR AH-SR-2224P-NA | 97507-AH-SR- 2224P-NA | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW ResponsePLS 4HR AHR AH-SR-2224P-UK | 97507-AH-SR- 2224P-UK | \$ 1,162.00 | 10% | <i>\$1,053.64</i> |
| EW ResponsePLS 4HR AHR AH-SR-2324P-AU | 97507-AH-SR- 2324P-AU | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW ResponsePLS 4HR AHR AH-SR-2324P-EU | 97507-AH-SR- 2324P-EU | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW ResponsePLS 4HR AHR AH-SR-2324P-NA | 97507-AH-SR- 2324P-NA | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW ResponsePLS 4HR AHR AH-SR-2324P-UK | 97507-AH-SR- 2324P-UK | \$ 1,211.00 | 10% | <i>\$1,098.07</i> |
| EW ResponsePLS 4HR AHR AH-SR-2348P-AU | 97507-AH-SR- 2348P-AU | \$ 1,369.00 | 10% | <i>\$1,241.34</i> |
| EW ResponsePLS 4HR AHR AH-SR-2348P-EU | 97507-AH-SR- 2348P-EU | \$ 1,369.00 | 10% | <i>\$1,241.34</i> |
| EW ResponsePLS 4HR AHR AH-SR-2348P-NA | 97507-AH-SR- 2348P-NA | \$ 1,369.00 | 10% | <i>\$1,241.34</i> |
| EW ResponsePLS 4HR AHR AH-SR-2348P-UK | 97507-AH-SR- 2348P-UK | \$ 1,369.00 | 10% | <i>\$1,241.34</i> |
| EW ResponsePLS 4HR AHR AH-XR200P-AU | 97507-AH- XR200P-AU | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |
| EW ResponsePLS 4HR AHR AH-XR200P-EU | 97507-AH- XR200P-EU | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |
| EW ResponsePLS 4HR AHR AH-XR200P-UK | 97507-AH- XR200P-UK | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |
| EW ResponsePLS 4HR AHR AH-XR200P-US | 97507-AH- XR200P-US | \$ 1,120.00 | 10% | <i>\$1,015.56</i> |

| | | | | |
|--|-------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR AH-XR600P | 97507-AH-XR600P | \$ 1,128.00 | 10% | <i>\$1,022.81</i> |
| EW ResponsePLS 4HR AHR AH-XR600P-AU | 97507-AH-XR600P-AU | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW ResponsePLS 4HR AHR AH-XR600P-EU | 97507-AH-XR600P-EU | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW ResponsePLS 4HR AHR AH-XR600P-KR | 97507-AH-XR600P-KR | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW ResponsePLS 4HR AHR AH-XR600P-UK | 97507-AH-XR600P-UK | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW ResponsePLS 4HR AHR AH-XR600P-US | 97507-AH-XR600P-US | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW ResponsePLS 4HR AHR AP-8533-68SB30-IL | 97507-AP-8533-68SB30-IL | \$ 377.00 | 10% | <i>\$341.84</i> |
| EW ResponsePLS 4HR AHR AP3000-IL | 97507-AP3000-IL | \$ 264.24 | 10% | <i>\$239.60</i> |
| EW ResponsePLS 4HR AHR AP3000-TN | 97507-AP3000-TN | \$ 264.24 | 10% | <i>\$239.60</i> |
| EW ResponsePLS 4HR AHR AP3000-WW | 97507-AP3000-WW | \$ 264.24 | 10% | <i>\$239.60</i> |
| EW ResponsePLS 4HR AHR AP3000X-WW | 97507-AP3000X-WW | \$ 281.74 | 10% | <i>\$255.47</i> |
| EW ResponsePLS 4HR AHR AP302W-CAN | 97507-AP302W-CAN | \$ 368.00 | 10% | <i>\$333.68</i> |
| EW ResponsePLS 4HR AHR AP302W-EG | 97507-AP302W-EG | \$ 271.00 | 10% | <i>\$245.73</i> |
| EW ResponsePLS 4HR AHR AP302W-FCC | 97507-AP302W-FCC | \$ 368.00 | 10% | <i>\$333.68</i> |
| EW ResponsePLS 4HR AHR AP302W-WR | 97507-AP302W-WR | \$ 350.00 | 10% | <i>\$317.36</i> |
| EW ResponsePLS 4HR AHR AP305C-1-CAN | 97507-AP305C-1-CAN | \$ 367.00 | 10% | <i>\$332.78</i> |
| EW ResponsePLS 4HR AHR AP305C-1-EG | 97507-AP305C-1-EG | \$ 367.00 | 10% | <i>\$332.78</i> |
| EW ResponsePLS 4HR AHR AP305C-1-FCC | 97507-AP305C-1-FCC | \$ 367.00 | 10% | <i>\$332.78</i> |
| EW ResponsePLS 4HR AHR AP305C-1-IL | 97507-AP305C-1-IL | \$ 367.00 | 10% | <i>\$332.78</i> |

| | | | | |
|---------------------------------------|---------------------------|-----------|-----|----------|
| EW ResponsePLS 4HR AHR AP305C-1-WR | 97507-AP305C- 1-WR | \$ 367.00 | 10% | \$332.78 |
| EW ResponsePLS 4HR AHR AP305C-CAN | 97507-AP305C- CAN | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305C-EG | 97507-AP305C- EG | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305C-FCC | 97507-AP305C- FCC | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305C-IL | 97507-AP305C- IL | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305C-WR | 97507-AP305C- WR | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305CX-CAN | 97507- AP305CX- CAN | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305CX-FCC | 97507- AP305CX- FCC | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305CX-IL | 97507- AP305CX-IL | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP305CX-WR | 97507- AP305CX-WR | \$ 394.00 | 10% | \$357.26 |
| EW ResponsePLS 4HR AHR AP310e-1-WR | 97507-AP310e- 1-WR | \$ 355.00 | 10% | \$321.90 |
| EW ResponsePLS 4HR AHR AP310e-CAN | 97507-AP310e- CAN | \$ 373.00 | 10% | \$338.22 |
| EW ResponsePLS 4HR AHR AP310e-FCC | 97507-AP310e- FCC | \$ 373.00 | 10% | \$338.22 |
| EW ResponsePLS 4HR AHR AP310e-IL | 97507-AP310e- IL | \$ 373.00 | 10% | \$338.22 |
| EW ResponsePLS 4HR AHR AP310e-WR | 97507-AP310e- WR | \$ 373.00 | 10% | \$338.22 |
| EW ResponsePLS 4HR AHR AP310i-1-WR | 97507-AP310i- 1-WR | \$ 355.00 | 10% | \$321.90 |
| EW ResponsePLS 4HR AHR AP310i-CAN | 97507-AP310i- CAN | \$ 373.00 | 10% | \$338.22 |
| EW ResponsePLS 4HR AHR AP310i-FCC | 97507-AP310i- FCC | \$ 373.00 | 10% | \$338.22 |
| EW ResponsePLS 4HR AHR AP310i-IL | 97507-AP310i- IL | \$ 373.00 | 10% | \$338.22 |
| EW ResponsePLS 4HR AHR AP310i-WR | 97507-AP310i- WR | \$ 373.00 | 10% | \$338.22 |

| | | | | |
|--|------------------------|-----------|-----|-----------------|
| EW ResponsePLS 4HR AHR AP360e-CAN | 97507-AP360e- CAN | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsePLS 4HR AHR AP360e-FCC | 97507-AP360e- FCC | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsePLS 4HR AHR AP360e-IL | 97507-AP360e- IL | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsePLS 4HR AHR AP360e-WR | 97507-AP360e- WR | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsePLS 4HR AHR AP360i-CAN | 97507-AP360i- CAN | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsePLS 4HR AHR AP360i-FCC | 97507-AP360i- FCC | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsePLS 4HR AHR AP360i-WR | 97507-AP360i- WR | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsePLS 4HR AHR AP4000-WW | 97507-AP4000- 1-WW | \$ 346.00 | 10% | <i>\$313.74</i> |
| EW ResponsePLS 4HR AHR AP4000-IL | 97507-AP4000- IL | \$ 346.00 | 10% | <i>\$313.74</i> |
| EW ResponsePLS 4HR AHR AP4000-WW | 97507-AP4000- WW | \$ 346.00 | 10% | <i>\$313.74</i> |
| EW ResponsePLS 4HR AHR AP410C-1-CAN | 97507-AP410C- 1-CAN | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS 4HR AHR AP410C-1-EG | 97507-AP410C- 1-EG | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS 4HR AHR AP410C-1-FCC | 97507-AP410C- 1-FCC | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS 4HR AHR AP410C-1-IL | 97507-AP410C- 1-IL | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS 4HR AHR AP410C-1-WR | 97507-AP410C- 1-WR | \$ 362.00 | 10% | <i>\$328.24</i> |
| EW ResponsePLS 4HR AHR AP410C-CAN | 97507-AP410C- CAN | \$ 389.00 | 10% | <i>\$352.73</i> |
| EW ResponsePLS 4HR AHR AP410C-EG | 97507-AP410C- EG | \$ 389.00 | 10% | <i>\$352.73</i> |
| EW ResponsePLS 4HR AHR AP410C-FCC | 97507-AP410C- FCC | \$ 389.00 | 10% | <i>\$352.73</i> |
| EW ResponsePLS 4HR AHR AP410C-IL | 97507-AP410C- IL | \$ 389.00 | 10% | <i>\$352.73</i> |
| EW ResponsePLS 4HR AHR AP410C-WR | 97507-AP410C- WR | \$ 389.00 | 10% | <i>\$352.73</i> |

| | | | | |
|--|------------------------|-----------|-----|----------|
| EW ResponsePLS 4HR AHR AP410e-CAN | 97507-AP410e- CAN | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS 4HR AHR AP410e-FCC | 97507-AP410e- FCC | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS 4HR AHR AP410e-WR | 97507-AP410e- WR | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS 4HR AHR AP410i-1-FCC | 97507-AP410i- 1-FCC | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS 4HR AHR AP410i-1-WR | 97507-AP410i- 1-WR | \$ 385.00 | 10% | \$349.10 |
| EW ResponsePLS 4HR AHR AP410i-CAN | 97507-AP410i- CAN | \$ 405.00 | 10% | \$367.23 |
| EW ResponsePLS 4HR AHR AP410i-FCC | 97507-AP410i- FCC | \$ 405.00 | 10% | \$367.23 |
| EW ResponsePLS 4HR AHR AP410i-IL | 97507-AP410i- IL | \$ 405.00 | 10% | \$367.23 |
| EW ResponsePLS 4HR AHR AP410i-WR | 97507-AP410i- WR | \$ 405.00 | 10% | \$367.23 |
| EW ResponsePLS 4HR AHR AP460C-CAN | 97507-AP460C- CAN | \$ 420.00 | 10% | \$380.84 |
| EW ResponsePLS 4HR AHR AP460C-EG | 97507-AP460C- EG | \$ 420.00 | 10% | \$380.84 |
| EW ResponsePLS 4HR AHR AP460C-FCC | 97507-AP460C- FCC | \$ 420.00 | 10% | \$380.84 |
| EW ResponsePLS 4HR AHR AP460C-IL | 97507-AP460C- IL | \$ 420.00 | 10% | \$380.84 |
| EW ResponsePLS 4HR AHR AP460C-WR | 97507-AP460C- WR | \$ 420.00 | 10% | \$380.84 |
| EW ResponsePLS 4HR AHR AP460e-CAN | 97507-AP460e- CAN | \$ 421.00 | 10% | \$381.74 |
| EW ResponsePLS 4HR AHR AP460e-FCC | 97507-AP460e- FCC | \$ 421.00 | 10% | \$381.74 |
| EW ResponsePLS 4HR AHR AP460e-WR | 97507-AP460e- WR | \$ 401.00 | 10% | \$363.61 |
| EW ResponsePLS 4HR AHR AP460i-CAN | 97507-AP460i- CAN | \$ 401.00 | 10% | \$363.61 |
| EW ResponsePLS 4HR AHR AP460i-FCC | 97507-AP460i- FCC | \$ 401.00 | 10% | \$363.61 |
| EW ResponsePLS 4HR AHR AP460i-IL | 97507-AP460i- IL | \$ 401.00 | 10% | \$363.61 |
| EW ResponsePLS 4HR AHR AP460i-WR | 97507-AP460i- WR | \$ 401.00 | 10% | \$363.61 |

| | | | | |
|--|-----------------------------|-----------|-----|-----------------|
| EW ResponsePLS 4HR AHR AP460S12C-CAN | 97507- AP460S12C- CAN | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR AP460S12C-FCC | 97507- AP460S12C- FCC | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR AP460S12C-WR | 97507- AP460S12C- WR | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR AP460S6C-CAN | 97507- AP460S6C- CAN | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR AP460S6C-FCC | 97507- AP460S6C- FCC | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR AP460S6C-WR | 97507- AP460S6C- WR | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsePLS 4HR AHR AP5010-IL | 97507-AP5010- IL | \$ 378.00 | 10% | <i>\$342.75</i> |
| EW ResponsePLS 4HR AHR AP5010-WW | 97507-AP5010- WW | \$ 378.00 | 10% | <i>\$342.75</i> |
| EW ResponsePLS 4HR AHR AP5020-WW | 97507-AP5020- WW | \$ 369.17 | 6% | <i>\$349.62</i> |
| EW ResponsePLS 4HR AHR AP5050D-WW | 97507- AP5050D-WW | \$ 546.00 | 10% | <i>\$495.09</i> |
| EW ResponsePLS 4HR AHR AP5050U-WW | 97507- AP5050U-WW | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW ResponsePLS 4HR AHR AP505i-FCC | 97507-AP505i- FCC | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsePLS 4HR AHR AP505i-FCC-TAA | 97507-AP505i- FCC-TAA | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsePLS 4HR AHR AP505i-WR | 97507-AP505i- WR | \$ 424.00 | 10% | <i>\$384.46</i> |
| EW ResponsePLS 4HR AHR AP510C-CAN | 97507-AP510C- CAN | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS 4HR AHR AP510C-CE | 97507-AP510C- CE | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS 4HR AHR AP510C-FCC | 97507-AP510C- FCC | \$ 357.00 | 10% | <i>\$323.71</i> |
| EW ResponsePLS 4HR AHR AP510C-W | 97507-AP510C- W | \$ 357.00 | 10% | <i>\$323.71</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EW ResponsePLS 4HR AHR AP510C-WW | 97507-AP510C- WW | \$ 473.00 | 10% | \$428.89 |
| EW ResponsePLS 4HR AHR AP510CX-CAN | 97507- AP510CX- CAN | \$ 357.00 | 10% | \$323.71 |
| EW ResponsePLS 4HR AHR AP510CX-CE | 97507- AP510CX-CE | \$ 357.00 | 10% | \$323.71 |
| EW ResponsePLS 4HR AHR AP510CX-FCC | 97507- AP510CX- FCC | \$ 357.00 | 10% | \$323.71 |
| EW ResponsePLS 4HR AHR AP510CX-W | 97507- AP510CX-W | \$ 357.00 | 10% | \$323.71 |
| EW ResponsePLS 4HR AHR AP510CX-WW | 97507- AP510CX-WW | \$ 473.00 | 10% | \$428.89 |
| EW ResponsePLS 4HR AHR AP510e-FCC | 97507-AP510e- FCC | \$ 455.00 | 10% | \$412.57 |
| EW ResponsePLS 4HR AHR AP510e-FCC-TAA | 97507-AP510e- FCC-TAA | \$ 455.00 | 10% | \$412.57 |
| EW ResponsePLS 4HR AHR AP510e-WR | 97507-AP510e- WR | \$ 433.00 | 10% | \$392.62 |
| EW ResponsePLS 4HR AHR AP510i-1-FCC | 97507-AP510i- 1-FCC | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS 4HR AHR AP510i-1-WR | 97507-AP510i- 1-WR | \$ 415.00 | 10% | \$376.30 |
| EW ResponsePLS 4HR AHR AP510i-FCC | 97507-AP510i- FCC | \$ 435.00 | 10% | \$394.44 |
| EW ResponsePLS 4HR AHR AP510i-FCC-TAA | 97507-AP510i- FCC-TAA | \$ 435.00 | 10% | \$394.44 |
| EW ResponsePLS 4HR AHR AP510i-WR | 97507-AP510i- WR | \$ 435.00 | 10% | \$394.44 |
| EW ResponsePLS 4HR AHR AP560h-FCC | 97507-AP560h- FCC | \$ 649.00 | 10% | \$588.48 |
| EW ResponsePLS 4HR AHR AP560h-WR | 97507-AP560h- WR | \$ 649.00 | 10% | \$588.48 |
| EW ResponsePLS 4HR AHR AP560i-FCC | 97507-AP560i- FCC | \$ 555.00 | 10% | \$503.25 |
| EW ResponsePLS 4HR AHR AP560i-WR | 97507-AP560i- WR | \$ 529.00 | 10% | \$479.67 |
| EW ResponsePLS 4HR AHR AP560m-FCC | 97507-AP560m- FCC | \$ 555.00 | 10% | \$503.25 |

| | | | | |
|--------------------------------------|----------------------|--------------|-----|-------------|
| EW ResponsePLS 4HR AHR AP560t-FCC | 97507-AP560t- FCC | \$ 649.00 | 10% | \$588.48 |
| EW ResponsePLS 4HR AHR AP560u-FCC | 97507-AP560u- FCC | \$ 516.00 | 10% | \$467.88 |
| EW ResponsePLS 4HR AHR E2122 | 97507-E2122 | \$ 7,039.00 | 10% | \$6,382.61 |
| EW ResponsePLS 4HR AHR E2122-1 | 97507-E2122-1 | \$ 6,672.00 | 10% | \$6,049.84 |
| EW ResponsePLS 4HR AHR E3120-1 | 97507-E3120-1 | \$ 10,231.00 | 10% | \$9,276.96 |
| EW ResponsePLS 4HR AHR E3125 | 97507-E3125 | \$ 11,357.00 | 10% | \$10,297.96 |
| EW ResponsePLS 4HR AHR- H30131 | 97507-H30131 | \$ 2,997.00 | 10% | \$2,717.53 |
| EW ResponsePLS 4HR AHR- H30132 | 97507-H30132 | \$ 2,941.00 | 10% | \$2,666.75 |
| EW ResponsePLS 4HR AHR- H30133 | 97507-H30133 | \$ 5,862.00 | 10% | \$5,315.37 |
| EW ResponsePLS 4HR AHR- H30134 | 97507-H30134 | \$ 7,110.00 | 10% | \$6,446.99 |
| EW ResponsePLS 4HR AHR- H30135 | 97507-H30135 | \$ 5,976.00 | 10% | \$5,418.74 |
| EW ResponsePLS 4HR AHR- H30136 | 97507-H30136 | \$ 7,110.00 | 10% | \$6,446.99 |
| EW ResponsePLS 4HR AHR- H30184 | 97507-H30184 | \$ 1,288.00 | 10% | \$1,167.89 |
| EW ResponsePLS 4HR AHR- H30185 | 97507-H30185 | \$ 1,657.00 | 10% | \$1,502.48 |
| EW ResponsePLS 4HR AHR- H30186 | 97507-H30186 | \$ 1,444.00 | 10% | \$1,309.35 |
| EW ResponsePLS 4HR AHR- H30187 | 97507-H30187 | \$ 1,403.00 | 10% | \$1,272.17 |
| EW ResponsePLS 4HR AHR- H30188 | 97507-H30188 | \$ 1,444.00 | 10% | \$1,309.35 |
| EW ResponsePLS 4HR AHR- H30189 | 97507-H30189 | \$ 1,444.00 | 10% | \$1,309.35 |
| EW ResponsePLS 4HR AHR- H30190 | 97507-H30190 | \$ 1,769.00 | 10% | \$1,604.04 |
| EW ResponsePLS 4HR AHR- H30214 | 97507-H30214 | \$ 1,543.00 | 10% | \$1,399.12 |
| EW ResponsePLS 4HR AHR- H30215 | 97507-H30215 | \$ 1,543.00 | 10% | \$1,399.12 |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR-H30216 | 97507-H30216 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30217 | 97507-H30217 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30218 | 97507-H30218 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30219 | 97507-H30219 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30220 | 97507-H30220 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30221 | 97507-H30221 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30222 | 97507-H30222 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30223 | 97507-H30223 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30224 | 97507-H30224 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30225 | 97507-H30225 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30226 | 97507-H30226 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30227 | 97507-H30227 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30228 | 97507-H30228 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30229 | 97507-H30229 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30267 | 97507-H30267 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30268 | 97507-H30268 | \$ 1,769.00 | 10% | <i>\$1,604.04</i> |
| EW ResponsePLS 4HR AHR-H30269 | 97507-H30269 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30270 | 97507-H30270 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30271 | 97507-H30271 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30272 | 97507-H30272 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30273 | 97507-H30273 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR-H30274 | 97507-H30274 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |
| EW ResponsePLS 4HR AHR-H30275 | 97507-H30275 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30276 | 97507-H30276 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30277 | 97507-H30277 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |
| EW ResponsePLS 4HR AHR-H30278 | 97507-H30278 | \$ 2,399.00 | 10% | <i>\$2,175.29</i> |
| EW ResponsePLS 4HR AHR-H30279 | 97507-H30279 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |
| EW ResponsePLS 4HR AHR-H30280 | 97507-H30280 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |
| EW ResponsePLS 4HR AHR-H30281 | 97507-H30281 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |
| EW ResponsePLS 4HR AHR-H30282 | 97507-H30282 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |
| EW ResponsePLS 4HR AHR-H30283 | 97507-H30283 | \$ 1,848.00 | 10% | <i>\$1,675.67</i> |
| EW ResponsePLS 4HR AHR-H30284 | 97507-H30284 | \$ 2,033.00 | 10% | <i>\$1,843.42</i> |
| EW ResponsePLS 4HR AHR-H30296 | 97507-H30296 | \$ 1,543.00 | 10% | <i>\$1,399.12</i> |
| EW ResponsePLS 4HR AHR-H30297 | 97507-H30297 | \$ 1,543.00 | 10% | <i>\$1,399.12</i> |
| EW ResponsePLS 4HR AHR-H30298 | 97507-H30298 | \$ 1,543.00 | 10% | <i>\$1,399.12</i> |
| EW ResponsePLS 4HR AHR-H30299 | 97507-H30299 | \$ 1,543.00 | 10% | <i>\$1,399.12</i> |
| EW ResponsePLS 4HR AHR-H30381 | 97507-H30381 | \$ 2,781.00 | 10% | <i>\$2,521.67</i> |
| EW ResponsePLS 4HR AHR-H30384 | 97507-H30384 | \$ 2,657.00 | 10% | <i>\$2,409.23</i> |
| EW ResponsePLS 4HR AHR-H30391 | 97507-H30391 | \$ 1,654.00 | 10% | <i>\$1,499.76</i> |
| EW ResponsePLS 4HR AHR-H30392 | 97507-H30392 | \$ 1,654.00 | 10% | <i>\$1,499.76</i> |
| EW ResponsePLS 4HR AHR-H30393 | 97507-H30393 | \$ 966.00 | 10% | <i>\$875.92</i> |
| EW ResponsePLS 4HR AHR-H30394 | 97507-H30394 | \$ 2,812.00 | 10% | <i>\$2,549.78</i> |

| | | | | |
|-------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR-H30395 | 97507-H30395 | \$ 3,259.00 | 10% | <i>\$2,955.10</i> |
| EW ResponsePLS 4HR AHR-H30396 | 97507-H30396 | \$ 3,011.00 | 10% | <i>\$2,730.22</i> |
| EW ResponsePLS 4HR AHR-H30397 | 97507-H30397 | \$ 3,495.00 | 10% | <i>\$3,169.09</i> |
| EW ResponsePLS 4HR AHR-H30398 | 97507-H30398 | \$ 985.00 | 10% | <i>\$893.15</i> |
| EW ResponsePLS 4HR AHR-H30400 | 97507-H30400 | \$ 734.00 | 10% | <i>\$665.55</i> |
| EW ResponsePLS 4HR AHR-H30401 | 97507-H30401 | \$ 866.00 | 10% | <i>\$785.25</i> |
| EW ResponsePLS 4HR AHR-H30402 | 97507-H30402 | \$ 889.00 | 10% | <i>\$806.10</i> |
| EW ResponsePLS 4HR AHR-H30403 | 97507-H30403 | \$ 1,108.00 | 10% | <i>\$1,004.68</i> |
| EW ResponsePLS 4HR AHR-H30480 | 97507-H30480 | \$ 2,903.00 | 10% | <i>\$2,632.30</i> |
| EW ResponsePLS 4HR AHR-H30495 | 97507-H30495 | \$ 3,968.00 | 10% | <i>\$3,597.98</i> |
| EW ResponsePLS 4HR AHR-H30496 | 97507-H30496 | \$ 3,892.00 | 10% | <i>\$3,529.07</i> |
| EW ResponsePLS 4HR AHR-H30497 | 97507-H30497 | \$ 4,774.00 | 10% | <i>\$4,328.82</i> |
| EW ResponsePLS 4HR AHR-H30498 | 97507-H30498 | \$ 4,684.00 | 10% | <i>\$4,247.22</i> |
| EW ResponsePLS 4HR AHR-H30499 | 97507-H30499 | \$ 1,311.00 | 10% | <i>\$1,188.75</i> |
| EW ResponsePLS 4HR AHR-H30501 | 97507-H30501 | \$ 4,684.00 | 10% | <i>\$4,247.22</i> |
| EW ResponsePLS 4HR AHR-H30502 | 97507-H30502 | \$ 6,081.00 | 10% | <i>\$5,513.95</i> |
| EW ResponsePLS 4HR AHR-H30503 | 97507-H30503 | \$ 1,311.00 | 10% | <i>\$1,188.75</i> |
| EW ResponsePLS 4HR AHR-H30505 | 97507-H30505 | \$ 6,807.00 | 10% | <i>\$6,172.25</i> |
| EW ResponsePLS 4HR AHR-H30506 | 97507-H30506 | \$ 8,492.00 | 10% | <i>\$7,700.12</i> |
| EW ResponsePLS 4HR AHR-H30509 | 97507-H30509 | \$ 6,081.00 | 10% | <i>\$5,513.95</i> |
| EW ResponsePLS 4HR AHR-H30510 | 97507-H30510 | \$ 6,807.00 | 10% | <i>\$6,172.25</i> |

| | | | | |
|-------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR-H30511 | 97507-H30511 | \$ 8,492.00 | 10% | <i>\$7,700.12</i> |
| EW ResponsePLS 4HR AHR-H30512 | 97507-H30512 | \$ 1,311.00 | 10% | <i>\$1,188.75</i> |
| EW ResponsePLS 4HR AHR-H30513 | 97507-H30513 | \$ 1,922.00 | 10% | <i>\$1,742.77</i> |
| EW ResponsePLS 4HR AHR-H30525 | 97507-H30525 | \$ 6,819.00 | 10% | <i>\$6,183.13</i> |
| EW ResponsePLS 4HR AHR-H30526 | 97507-H30526 | \$ 5,128.00 | 10% | <i>\$4,649.81</i> |
| EW ResponsePLS 4HR AHR-H30528 | 97507-H30528 | \$ 7,850.00 | 10% | <i>\$7,117.99</i> |
| EW ResponsePLS 4HR AHR-H30531 | 97507-H30531 | \$ 10,995.00 | 10% | <i>\$9,969.72</i> |
| EW ResponsePLS 4HR AHR-H30532 | 97507-H30532 | \$ 10,995.00 | 10% | <i>\$9,969.72</i> |
| EW ResponsePLS 4HR AHR-H30534 | 97507-H30534 | \$ 11,208.00 | 10% | <i>\$10,162.85</i> |
| EW ResponsePLS 4HR AHR-H30535 | 97507-H30535 | \$ 11,915.00 | 10% | <i>\$10,803.93</i> |
| EW ResponsePLS 4HR AHR-H30536 | 97507-H30536 | \$ 10,995.00 | 10% | <i>\$9,969.72</i> |
| EW ResponsePLS 4HR AHR-H30537 | 97507-H30537 | \$ 11,915.00 | 10% | <i>\$10,803.93</i> |
| EW ResponsePLS 4HR AHR-H30538 | 97507-H30538 | \$ 6,819.00 | 10% | <i>\$6,183.13</i> |
| EW ResponsePLS 4HR AHR-H30539 | 97507-H30539 | \$ 12,725.00 | 10% | <i>\$11,538.39</i> |
| EW ResponsePLS 4HR AHR-H30540 | 97507-H30540 | \$ 13,130.00 | 10% | <i>\$11,905.63</i> |
| EW ResponsePLS 4HR AHR-H30543 | 97507-H30543 | \$ 1,287.00 | 10% | <i>\$1,166.99</i> |
| EW ResponsePLS 4HR AHR-H30544 | 97507-H30544 | \$ 1,970.00 | 10% | <i>\$1,786.30</i> |
| EW ResponsePLS 4HR AHR-H30548 | 97507-H30548 | \$ 1,287.00 | 10% | <i>\$1,166.99</i> |
| EW ResponsePLS 4HR AHR-H30549 | 97507-H30549 | \$ 1,886.00 | 10% | <i>\$1,710.13</i> |
| EW ResponsePLS 4HR AHR-H30550 | 97507-H30550 | \$ 1,886.00 | 10% | <i>\$1,710.13</i> |
| EW ResponsePLS 4HR AHR-H30552 | 97507-H30552 | \$ 1,287.00 | 10% | <i>\$1,166.99</i> |

| | | | | |
|-------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR-H30553 | 97507-H30553 | \$ 1,796.00 | 10% | <i>\$1,628.52</i> |
| EW ResponsePLS 4HR AHR-H30569 | 97507-H30569 | \$ 5,862.00 | 10% | <i>\$5,315.37</i> |
| EW ResponsePLS 4HR AHR-H30570 | 97507-H30570 | \$ 6,808.00 | 10% | <i>\$6,173.15</i> |
| EW ResponsePLS 4HR AHR-H30571 | 97507-H30571 | \$ 6,808.00 | 10% | <i>\$6,173.15</i> |
| EW ResponsePLS 4HR AHR-H30573 | 97507-H30573 | \$ 5,862.00 | 10% | <i>\$5,315.37</i> |
| EW ResponsePLS 4HR AHR-H30574 | 97507-H30574 | \$ 6,376.00 | 10% | <i>\$5,781.44</i> |
| EW ResponsePLS 4HR AHR-H30575 | 97507-H30575 | \$ 4,402.00 | 10% | <i>\$3,991.51</i> |
| EW ResponsePLS 4HR AHR-H30576 | 97507-H30576 | \$ 5,862.00 | 10% | <i>\$5,315.37</i> |
| EW ResponsePLS 4HR AHR-H30577 | 97507-H30577 | \$ 6,678.00 | 10% | <i>\$6,055.28</i> |
| EW ResponsePLS 4HR AHR-H30578 | 97507-H30578 | \$ 6,678.00 | 10% | <i>\$6,055.28</i> |
| EW ResponsePLS 4HR AHR-H30587 | 97507-H30587 | \$ 5,227.00 | 10% | <i>\$4,739.58</i> |
| EW ResponsePLS 4HR AHR-H30588 | 97507-H30588 | \$ 3,745.00 | 10% | <i>\$3,395.78</i> |
| EW ResponsePLS 4HR AHR-H30589 | 97507-H30589 | \$ 5,586.00 | 10% | <i>\$5,065.11</i> |
| EW ResponsePLS 4HR AHR-H30632 | 97507-H30632 | \$ 461.00 | 10% | <i>\$418.01</i> |
| EW ResponsePLS 4HR AHR-H30633 | 97507-H30633 | \$ 461.00 | 10% | <i>\$418.01</i> |
| EW ResponsePLS 4HR AHR-H30643 | 97507-H30643 | \$ 10,595.00 | 10% | <i>\$9,607.02</i> |
| EW ResponsePLS 4HR AHR-H30706 | 97507-H30706 | \$ 8,002.00 | 10% | <i>\$7,255.81</i> |
| EW ResponsePLS 4HR AHR-H30707 | 97507-H30707 | \$ 5,128.00 | 10% | <i>\$4,649.81</i> |
| EW ResponsePLS 4HR AHR-H30724 | 97507-H30724 | \$ 840.00 | 10% | <i>\$761.67</i> |
| EW ResponsePLS 4HR AHR-H30725 | 97507-H30725 | \$ 2,941.00 | 10% | <i>\$2,666.75</i> |
| EW ResponsePLS 4HR AHR-H30726 | 97507-H30726 | \$ 12,146.00 | 10% | <i>\$11,013.39</i> |

| | | | | |
|-------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR-H30727 | 97507-H30727 | \$ 12,879.00 | 10% | <i>\$11,678.03</i> |
| EW ResponsePLS 4HR AHR-H30730 | 97507-H30730 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsePLS 4HR AHR-H30731 | 97507-H30731 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsePLS 4HR AHR-H30733 | 97507-H30733 | \$ 11,405.00 | 10% | <i>\$10,341.48</i> |
| EW ResponsePLS 4HR AHR-H30734 | 97507-H30734 | \$ 8,794.00 | 10% | <i>\$7,973.96</i> |
| EW ResponsePLS 4HR AHR-H30735 | 97507-H30735 | \$ 10,185.00 | 10% | <i>\$9,235.25</i> |
| EW ResponsePLS 4HR AHR-H30736 | 97507-H30736 | \$ 1,949.00 | 10% | <i>\$1,767.26</i> |
| EW ResponsePLS 4HR AHR-H30738 | 97507-H30738 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS 4HR AHR H30787 | 97507-H30787 | \$ 310.00 | 10% | <i>\$281.09</i> |
| EW ResponsePLS 4HR AHR H30847 | 97507-H30847 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW ResponsePLS 4HR AHR H30852 | 97507-H30852 | \$ 318.00 | 10% | <i>\$288.35</i> |
| EW ResponsePLS 4HR AHR H30857 | 97507-H30857 | \$ 367.00 | 10% | <i>\$332.78</i> |
| EW ResponsePLS 4HR AHR H31337 | 97507-H31337 | \$ 12,315.00 | 10% | <i>\$11,166.63</i> |
| EW ResponsePLS 4HR AHR H31338 | 97507-H31338 | \$ 12,315.00 | 10% | <i>\$11,166.63</i> |
| EW ResponsePLS 4HR AHR H31341 | 97507-H31341 | \$ 6,702.00 | 10% | <i>\$6,077.04</i> |
| EW ResponsePLS 4HR AHR H31342 | 97507-H31342 | \$ 1,871.00 | 10% | <i>\$1,696.53</i> |
| EW ResponsePLS 4HR AHR H31343 | 97507-H31343 | \$ 2,560.00 | 10% | <i>\$2,321.28</i> |
| EW ResponsePLS 4HR AHR H31344 | 97507-H31344 | \$ 2,560.00 | 10% | <i>\$2,321.28</i> |
| EW ResponsePLS 4HR AHR H31345 | 97507-H31345 | \$ 2,560.00 | 10% | <i>\$2,321.28</i> |
| EW ResponsePLS 4HR AHR H31346 | 97507-H31346 | \$ 2,560.00 | 10% | <i>\$2,321.28</i> |
| EW ResponsePLS 4HR AHR H31362 | 97507-H31362 | \$ 32,147.00 | 10% | <i>\$29,149.29</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR H31363 | 97507-H31363 | \$ 32,147.00 | 10% | <i>\$29,149.29</i> |
| EW ResponsePLS 4HR AHR H31364 | 97507-H31364 | \$ 12,041.00 | 10% | <i>\$10,918.18</i> |
| EW ResponsePLS 4HR AHR H31365 | 97507-H31365 | \$ 12,041.00 | 10% | <i>\$10,918.18</i> |
| EW ResponsePLS 4HR AHR H31366 | 97507-H31366 | \$ 16,670.00 | 10% | <i>\$15,115.52</i> |
| EW ResponsePLS 4HR AHR H31367 | 97507-H31367 | \$ 16,670.00 | 10% | <i>\$15,115.52</i> |
| EW ResponsePLS 4HR AHR H32010 | 97507-H32010 | \$ 1,786.00 | 10% | <i>\$1,619.46</i> |
| EW ResponsePLS 4HR AHR H32011 | 97507-H32011 | \$ 1,786.00 | 10% | <i>\$1,619.46</i> |
| EW ResponsePLS 4HR AHR H32012 | 97507-H32012 | \$ 4,277.00 | 10% | <i>\$3,878.17</i> |
| EW ResponsePLS 4HR AHR H32013 | 97507-H32013 | \$ 4,277.00 | 10% | <i>\$3,878.17</i> |
| EW ResponsePLS 4HR AHR H32014 | 97507-H32014 | \$ 4,277.00 | 10% | <i>\$3,878.17</i> |
| EW ResponsePLS 4HR AHR H32015 | 97507-H32015 | \$ 4,277.00 | 10% | <i>\$3,878.17</i> |
| EW ResponsePLS 4HR AHR H32016 | 97507-H32016 | \$ 3,909.00 | 10% | <i>\$3,544.49</i> |
| EW ResponsePLS 4HR AHR H32017 | 97507-H32017 | \$ 3,909.00 | 10% | <i>\$3,544.49</i> |
| EW ResponsePLS 4HR AHR H32018 | 97507-H32018 | \$ 3,909.00 | 10% | <i>\$3,544.49</i> |
| EW ResponsePLS 4HR AHR H32019 | 97507-H32019 | \$ 3,909.00 | 10% | <i>\$3,544.49</i> |
| EW ResponsePLS 4HR AHR H32020 | 97507-H32020 | \$ 32,848.00 | 10% | <i>\$29,784.92</i> |
| EW ResponsePLS 4HR AHR H32021 | 97507-H32021 | \$ 32,848.00 | 10% | <i>\$29,784.92</i> |
| EW ResponsePLS 4HR AHR H32022 | 97507-H32022 | \$ 32,848.00 | 10% | <i>\$29,784.92</i> |
| EW ResponsePLS 4HR AHR H32023 | 97507-H32023 | \$ 32,848.00 | 10% | <i>\$29,784.92</i> |
| EW ResponsePLS 4HR AHR H32028 | 97507-H32028 | \$ 61,470.00 | 10% | <i>\$55,737.92</i> |
| EW ResponsePLS 4HR AHR H32029 | 97507-H32029 | \$ 61,470.00 | 10% | <i>\$55,737.92</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR H32030 | 97507-H32030 | \$ 64,466.00 | 10% | <i>\$58,454.55</i> |
| EW ResponsePLS 4HR AHR H32031 | 97507-H32031 | \$ 64,466.00 | 10% | <i>\$58,454.55</i> |
| EW ResponsePLS 4HR AHR H32032 | 97507-H32032 | \$ 64,466.00 | 10% | <i>\$58,454.55</i> |
| EW ResponsePLS 4HR AHR H32033 | 97507-H32033 | \$ 64,466.00 | 10% | <i>\$58,454.55</i> |
| EW ResponsePLS 4HR AHR H32038 | 97507-H32038 | \$ 12,223.00 | 10% | <i>\$11,083.21</i> |
| EW ResponsePLS 4HR AHR H32039 | 97507-H32039 | \$ 12,223.00 | 10% | <i>\$11,083.21</i> |
| EW ResponsePLS 4HR AHR H32040 | 97507-H32040 | \$ 12,223.00 | 10% | <i>\$11,083.21</i> |
| EW ResponsePLS 4HR AHR H32041 | 97507-H32041 | \$ 12,223.00 | 10% | <i>\$11,083.21</i> |
| EW ResponsePLS 4HR AHR H32046 | 97507-H32046 | \$ 16,919.00 | 10% | <i>\$15,341.30</i> |
| EW ResponsePLS 4HR AHR H32047 | 97507-H32047 | \$ 16,919.00 | 10% | <i>\$15,341.30</i> |
| EW ResponsePLS 4HR AHR H32048 | 97507-H32048 | \$ 16,919.00 | 10% | <i>\$15,341.30</i> |
| EW ResponsePLS 4HR AHR H32049 | 97507-H32049 | \$ 16,919.00 | 10% | <i>\$15,341.30</i> |
| EW ResponsePLS 4HR AHR H32054 | 97507-H32054 | \$ 12,223.00 | 10% | <i>\$11,083.21</i> |
| EW ResponsePLS 4HR AHR H32055 | 97507-H32055 | \$ 16,919.00 | 10% | <i>\$15,341.30</i> |
| EW ResponsePLS 4HR AHR H32056 | 97507-H32056 | \$ 4,927.00 | 10% | <i>\$4,467.56</i> |
| EW ResponsePLS 4HR AHR H32057 | 97507-H32057 | \$ 5,075.00 | 10% | <i>\$4,601.76</i> |
| EW ResponsePLS 4HR AHR H32058 | 97507-H32058 | \$ 5,075.00 | 10% | <i>\$4,601.76</i> |
| EW ResponsePLS 4HR AHR H32059 | 97507-H32059 | \$ 5,075.00 | 10% | <i>\$4,601.76</i> |
| EW ResponsePLS 4HR AHR H32060 | 97507-H32060 | \$ 4,895.00 | 10% | <i>\$4,438.54</i> |
| EW ResponsePLS 4HR AHR H32061 | 97507-H32061 | \$ 5,140.00 | 10% | <i>\$4,660.70</i> |
| EW ResponsePLS 4HR AHR H32062 | 97507-H32062 | \$ 4,942.00 | 10% | <i>\$4,481.16</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR H32063 | 97507-H32063 | \$ 4,901.00 | 10% | <i>\$4,443.98</i> |
| EW ResponsePLS 4HR AHR H32064 | 97507-H32064 | \$ 4,942.00 | 10% | <i>\$4,481.16</i> |
| EW ResponsePLS 4HR AHR H32065 | 97507-H32065 | \$ 5,380.00 | 10% | <i>\$4,878.32</i> |
| EW ResponsePLS 4HR AHR H32066 | 97507-H32066 | \$ 5,380.00 | 10% | <i>\$4,878.32</i> |
| EW ResponsePLS 4HR AHR H32067 | 97507-H32067 | \$ 5,380.00 | 10% | <i>\$4,878.32</i> |
| EW ResponsePLS 4HR AHR H32068 | 97507-H32068 | \$ 5,380.00 | 10% | <i>\$4,878.32</i> |
| EW ResponsePLS 4HR AHR H32069 | 97507-H32069 | \$ 6,326.00 | 10% | <i>\$5,736.10</i> |
| EW ResponsePLS 4HR AHR H32070 | 97507-H32070 | \$ 6,326.00 | 10% | <i>\$5,736.10</i> |
| EW ResponsePLS 4HR AHR H32071 | 97507-H32071 | \$ 6,326.00 | 10% | <i>\$5,736.10</i> |
| EW ResponsePLS 4HR AHR H32072 | 97507-H32072 | \$ 6,326.00 | 10% | <i>\$5,736.10</i> |
| EW ResponsePLS 4HR AHR H32073 | 97507-H32073 | \$ 38,969.00 | 10% | <i>\$35,335.14</i> |
| EW ResponsePLS 4HR AHR H32074 | 97507-H32074 | \$ 38,969.00 | 10% | <i>\$35,335.14</i> |
| EW ResponsePLS 4HR AHR H32075 | 97507-H32075 | \$ 53,004.00 | 10% | <i>\$48,061.38</i> |
| EW ResponsePLS 4HR AHR H32076 | 97507-H32076 | \$ 53,004.00 | 10% | <i>\$48,061.38</i> |
| EW ResponsePLS 4HR AHR H32101 | 97507-H32101 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32102 | 97507-H32102 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32103 | 97507-H32103 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32104 | 97507-H32104 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32105 | 97507-H32105 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32106 | 97507-H32106 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32107 | 97507-H32107 | \$ 10,104.00 | 10% | <i>\$9,161.80</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H32108 | 97507-H32108 | \$ 10,104.00 | 10% | <i>\$9,161.80</i> |
| EW ResponsePLS 4HR AHR H32109 | 97507-H32109 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32110 | 97507-H32110 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32111 | 97507-H32111 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32112 | 97507-H32112 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32113 | 97507-H32113 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32114 | 97507-H32114 | \$ 3,112.00 | 10% | <i>\$2,821.81</i> |
| EW ResponsePLS 4HR AHR H32115 | 97507-H32115 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32116 | 97507-H32116 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32117 | 97507-H32117 | \$ 3,018.00 | 10% | <i>\$2,736.57</i> |
| EW ResponsePLS 4HR AHR H32118 | 97507-H32118 | \$ 3,018.00 | 10% | <i>\$2,736.57</i> |
| EW ResponsePLS 4HR AHR H32119 | 97507-H32119 | \$ 3,018.00 | 10% | <i>\$2,736.57</i> |
| EW ResponsePLS 4HR AHR H32120 | 97507-H32120 | \$ 3,018.00 | 10% | <i>\$2,736.57</i> |
| EW ResponsePLS 4HR AHR H32121 | 97507-H32121 | \$ 10,104.00 | 10% | <i>\$9,161.80</i> |
| EW ResponsePLS 4HR AHR H32122 | 97507-H32122 | \$ 10,104.00 | 10% | <i>\$9,161.80</i> |
| EW ResponsePLS 4HR AHR H32123 | 97507-H32123 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32124 | 97507-H32124 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H32125 | 97507-H32125 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32126 | 97507-H32126 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32127 | 97507-H32127 | \$ 5,108.00 | 10% | <i>\$4,631.68</i> |
| EW ResponsePLS 4HR AHR H32128 | 97507-H32128 | \$ 5,108.00 | 10% | <i>\$4,631.68</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR H32129 | 97507-H32129 | \$ 5,108.00 | 10% | <i>\$4,631.68</i> |
| EW ResponsePLS 4HR AHR H32130 | 97507-H32130 | \$ 5,108.00 | 10% | <i>\$4,631.68</i> |
| EW ResponsePLS 4HR AHR H32131 | 97507-H32131 | \$ 5,108.00 | 10% | <i>\$4,631.68</i> |
| EW ResponsePLS 4HR AHR H32132 | 97507-H32132 | \$ 5,108.00 | 10% | <i>\$4,631.68</i> |
| EW ResponsePLS 4HR AHR H32133 | 97507-H32133 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32134 | 97507-H32134 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32135 | 97507-H32135 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32136 | 97507-H32136 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32137 | 97507-H32137 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32138 | 97507-H32138 | \$ 4,554.00 | 10% | <i>\$4,129.34</i> |
| EW ResponsePLS 4HR AHR H32139 | 97507-H32139 | \$ 16,861.00 | 10% | <i>\$15,288.71</i> |
| EW ResponsePLS 4HR AHR H32140 | 97507-H32140 | \$ 16,861.00 | 10% | <i>\$15,288.71</i> |
| EW ResponsePLS 4HR AHR H32141 | 97507-H32141 | \$ 20,103.00 | 10% | <i>\$18,228.40</i> |
| EW ResponsePLS 4HR AHR H32142 | 97507-H32142 | \$ 20,103.00 | 10% | <i>\$18,228.40</i> |
| EW ResponsePLS 4HR AHR H32146 | 97507-H32146 | \$ 2,948.00 | 10% | <i>\$2,673.10</i> |
| EW ResponsePLS 4HR AHR H32147 | 97507-H32147 | \$ 2,948.00 | 10% | <i>\$2,673.10</i> |
| EW ResponsePLS 4HR AHR H32148 | 97507-H32148 | \$ 4,453.00 | 10% | <i>\$4,037.76</i> |
| EW ResponsePLS 4HR AHR H32149 | 97507-H32149 | \$ 4,453.00 | 10% | <i>\$4,037.76</i> |
| EW ResponsePLS 4HR AHR H32150 | 97507-H32150 | \$ 2,948.00 | 10% | <i>\$2,673.10</i> |
| EW ResponsePLS 4HR AHR H32152 | 97507-H32152 | \$ 2,097.00 | 10% | <i>\$1,901.45</i> |
| EW ResponsePLS 4HR AHR H32169 | 97507-H32169 | \$ 3,148.00 | 10% | <i>\$2,854.45</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|-------------|
| EW ResponsePLS 4HR AHR H32170 | 97507-H32170 | \$ 3,148.00 | 10% | \$2,854.45 |
| EW ResponsePLS 4HR AHR H32171 | 97507-H32171 | \$ 3,053.00 | 10% | \$2,768.31 |
| EW ResponsePLS 4HR AHR H32172 | 97507-H32172 | \$ 3,053.00 | 10% | \$2,768.31 |
| EW ResponsePLS 4HR AHR H32173 | 97507-H32173 | \$ 5,554.00 | 10% | \$5,036.09 |
| EW ResponsePLS 4HR AHR H32174 | 97507-H32174 | \$ 5,554.00 | 10% | \$5,036.09 |
| EW ResponsePLS 4HR AHR H32175 | 97507-H32175 | \$ 4,953.00 | 10% | \$4,491.13 |
| EW ResponsePLS 4HR AHR H32176 | 97507-H32176 | \$ 4,953.00 | 10% | \$4,491.13 |
| EW ResponsePLS 4HR AHR H32177 | 97507-H32177 | \$ 18,887.00 | 10% | \$17,125.79 |
| EW ResponsePLS 4HR AHR H32178 | 97507-H32178 | \$ 22,518.00 | 10% | \$20,418.20 |
| EW ResponsePLS 4HR AHR H34008 | 97507-H34008 | \$ 1,258.00 | 10% | \$1,140.69 |
| EW ResponsePLS 4HR AHR H34009 | 97507-H34009 | \$ 1,366.00 | 10% | \$1,238.62 |
| EW ResponsePLS 4HR AHR H34010 | 97507-H34010 | \$ 1,190.00 | 10% | \$1,079.03 |
| EW ResponsePLS 4HR AHR H34011 | 97507-H34011 | \$ 1,349.00 | 10% | \$1,223.21 |
| EW ResponsePLS 4HR AHR H34012 | 97507-H34012 | \$ 1,470.00 | 10% | \$1,332.92 |
| EW ResponsePLS 4HR AHR H34013 | 97507-H34013 | \$ 1,300.00 | 10% | \$1,178.78 |
| EW ResponsePLS 4HR AHR H34014 | 97507-H34014 | \$ 1,366.00 | 10% | \$1,238.62 |
| EW ResponsePLS 4HR AHR H34015 | 97507-H34015 | \$ 1,209.00 | 10% | \$1,096.26 |
| EW ResponsePLS 4HR AHR H34016 | 97507-H34016 | \$ 1,390.00 | 10% | \$1,260.38 |
| EW ResponsePLS 4HR AHR H34017 | 97507-H34017 | \$ 1,517.00 | 10% | \$1,375.54 |
| EW ResponsePLS 4HR AHR H34018 | 97507-H34018 | \$ 1,322.00 | 10% | \$1,198.72 |
| EW ResponsePLS 4HR AHR H34019 | 97507-H34019 | \$ 1,322.00 | 10% | \$1,198.72 |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H34020 | 97507-H34020 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS 4HR AHR H34021 | 97507-H34021 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS 4HR AHR H34048 | 97507-H34048 | \$ 1,736.00 | 10% | <i>\$1,574.12</i> |
| EW ResponsePLS 4HR AHR H34049 | 97507-H34049 | \$ 1,736.00 | 10% | <i>\$1,574.12</i> |
| EW ResponsePLS 4HR AHR H34050 | 97507-H34050 | \$ 1,590.00 | 10% | <i>\$1,441.73</i> |
| EW ResponsePLS 4HR AHR H34051 | 97507-H34051 | \$ 1,590.00 | 10% | <i>\$1,441.73</i> |
| EW ResponsePLS 4HR AHR H34052 | 97507-H34052 | \$ 1,823.00 | 10% | <i>\$1,653.01</i> |
| EW ResponsePLS 4HR AHR H34053 | 97507-H34053 | \$ 1,823.00 | 10% | <i>\$1,653.01</i> |
| EW ResponsePLS 4HR AHR H34054 | 97507-H34054 | \$ 1,668.00 | 10% | <i>\$1,512.46</i> |
| EW ResponsePLS 4HR AHR H34055 | 97507-H34055 | \$ 1,668.00 | 10% | <i>\$1,512.46</i> |
| EW ResponsePLS 4HR AHR H34056 | 97507-H34056 | \$ 1,990.00 | 10% | <i>\$1,804.43</i> |
| EW ResponsePLS 4HR AHR H34057 | 97507-H34057 | \$ 1,990.00 | 10% | <i>\$1,804.43</i> |
| EW ResponsePLS 4HR AHR H34058 | 97507-H34058 | \$ 1,894.00 | 10% | <i>\$1,717.38</i> |
| EW ResponsePLS 4HR AHR H34059 | 97507-H34059 | \$ 1,894.00 | 10% | <i>\$1,717.38</i> |
| EW ResponsePLS 4HR AHR H34062 | 97507-H34062 | \$ 1,990.00 | 10% | <i>\$1,804.43</i> |
| EW ResponsePLS 4HR AHR H34063 | 97507-H34063 | \$ 1,990.00 | 10% | <i>\$1,804.43</i> |
| EW ResponsePLS 4HR AHR H34064 | 97507-H34064 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLS 4HR AHR H34065 | 97507-H34065 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLS 4HR AHR H34066 | 97507-H34066 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLS 4HR AHR H34067 | 97507-H34067 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLS 4HR AHR H34068 | 97507-H34068 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H34069 | 97507-H34069 | \$ 1,598.00 | 10% | <i>\$1,448.99</i> |
| EW ResponsePLS 4HR AHR H34070 | 97507-H34070 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLS 4HR AHR H34071 | 97507-H34071 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsePLS 4HR AHR H34072 | 97507-H34072 | \$ 4,904.00 | 10% | <i>\$4,446.70</i> |
| EW ResponsePLS 4HR AHR H34073 | 97507-H34073 | \$ 4,809.00 | 10% | <i>\$4,360.56</i> |
| EW ResponsePLS 4HR AHR H34074 | 97507-H34074 | \$ 6,029.00 | 10% | <i>\$5,466.80</i> |
| EW ResponsePLS 4HR AHR H34075 | 97507-H34075 | \$ 5,830.00 | 10% | <i>\$5,286.35</i> |
| EW ResponsePLS 4HR AHR H34076 | 97507-H34076 | \$ 4,904.00 | 10% | <i>\$4,446.70</i> |
| EW ResponsePLS 4HR AHR H34077 | 97507-H34077 | \$ 4,809.00 | 10% | <i>\$4,360.56</i> |
| EW ResponsePLS 4HR AHR H34078 | 97507-H34078 | \$ 4,904.00 | 10% | <i>\$4,446.70</i> |
| EW ResponsePLS 4HR AHR H34079 | 97507-H34079 | \$ 4,809.00 | 10% | <i>\$4,360.56</i> |
| EW ResponsePLS 4HR AHR H34080 | 97507-H34080 | \$ 6,029.00 | 10% | <i>\$5,466.80</i> |
| EW ResponsePLS 4HR AHR H34081 | 97507-H34081 | \$ 5,830.00 | 10% | <i>\$5,286.35</i> |
| EW ResponsePLS 4HR AHR H34082 | 97507-H34082 | \$ 5,782.00 | 10% | <i>\$5,242.83</i> |
| EW ResponsePLS 4HR AHR H34083 | 97507-H34083 | \$ 5,592.00 | 10% | <i>\$5,070.55</i> |
| EW ResponsePLS 4HR AHR H34084 | 97507-H34084 | \$ 4,156.00 | 10% | <i>\$3,768.45</i> |
| EW ResponsePLS 4HR AHR H34085 | 97507-H34085 | \$ 4,156.00 | 10% | <i>\$3,768.45</i> |
| EW ResponsePLS 4HR AHR H34086 | 97507-H34086 | \$ 4,838.00 | 10% | <i>\$4,386.86</i> |
| EW ResponsePLS 4HR AHR H34087 | 97507-H34087 | \$ 4,641.00 | 10% | <i>\$4,208.23</i> |
| EW ResponsePLS 4HR AHR H34088 | 97507-H34088 | \$ 9,555.00 | 10% | <i>\$8,664.00</i> |
| EW ResponsePLS 4HR AHR H34089 | 97507-H34089 | \$ 9,555.00 | 10% | <i>\$8,664.00</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H34090 | 97507-H34090 | \$ 11,002.00 | 10% | <i>\$9,976.06</i> |
| EW ResponsePLS 4HR AHR H34091 | 97507-H34091 | \$ 10,069.00 | 10% | <i>\$9,130.07</i> |
| EW ResponsePLS 4HR AHR H34092 | 97507-H34092 | \$ 10,069.00 | 10% | <i>\$9,130.07</i> |
| EW ResponsePLS 4HR AHR H34093 | 97507-H34093 | \$ 10,069.00 | 10% | <i>\$9,130.07</i> |
| EW ResponsePLS 4HR AHR H34094 | 97507-H34094 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34095 | 97507-H34095 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34096 | 97507-H34096 | \$ 1,296.00 | 10% | <i>\$1,175.15</i> |
| EW ResponsePLS 4HR AHR H34097 | 97507-H34097 | \$ 1,296.00 | 10% | <i>\$1,175.15</i> |
| EW ResponsePLS 4HR AHR H34098 | 97507-H34098 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34099 | 97507-H34099 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34100 | 97507-H34100 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34101 | 97507-H34101 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34102 | 97507-H34102 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34103 | 97507-H34103 | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EW ResponsePLS 4HR AHR H34104 | 97507-H34104 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsePLS 4HR AHR H34105 | 97507-H34105 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsePLS 4HR AHR H34106 | 97507-H34106 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsePLS 4HR AHR H34107 | 97507-H34107 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsePLS 4HR AHR H34108 | 97507-H34108 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsePLS 4HR AHR H34109 | 97507-H34109 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsePLS 4HR AHR H34110 | 97507-H34110 | \$ 9,699.00 | 10% | <i>\$8,794.57</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR H34111 | 97507-H34111 | \$ 9,699.00 | 10% | <i>\$8,794.57</i> |
| EW ResponsePLS 4HR AHR H34112 | 97507-H34112 | \$ 9,699.00 | 10% | <i>\$8,794.57</i> |
| EW ResponsePLS 4HR AHR H34114 | 97507-H34114 | \$ 14,193.00 | 10% | <i>\$12,869.50</i> |
| EW ResponsePLS 4HR AHR H34115 | 97507-H34115 | \$ 13,775.00 | 10% | <i>\$12,490.48</i> |
| EW ResponsePLS 4HR AHR H34116 | 97507-H34116 | \$ 13,775.00 | 10% | <i>\$12,490.48</i> |
| EW ResponsePLS 4HR AHR H34117 | 97507-H34117 | \$ 14,193.00 | 10% | <i>\$12,869.50</i> |
| EW ResponsePLS 4HR AHR H34118 | 97507-H34118 | \$ 2,525.00 | 10% | <i>\$2,289.54</i> |
| EW ResponsePLS 4HR AHR H34119 | 97507-H34119 | \$ 2,525.00 | 10% | <i>\$2,289.54</i> |
| EW ResponsePLS 4HR AHR H34120 | 97507-H34120 | \$ 1,874.00 | 10% | <i>\$1,699.25</i> |
| EW ResponsePLS 4HR AHR H34121 | 97507-H34121 | \$ 1,874.00 | 10% | <i>\$1,699.25</i> |
| EW ResponsePLS 4HR AHR H34122 | 97507-H34122 | \$ 1,937.00 | 10% | <i>\$1,756.37</i> |
| EW ResponsePLS 4HR AHR H34123 | 97507-H34123 | \$ 1,937.00 | 10% | <i>\$1,756.37</i> |
| EW ResponsePLS 4HR AHR H34124 | 97507-H34124 | \$ 2,676.00 | 10% | <i>\$2,426.46</i> |
| EW ResponsePLS 4HR AHR H34125 | 97507-H34125 | \$ 2,676.00 | 10% | <i>\$2,426.46</i> |
| EW ResponsePLS 4HR AHR H34126 | 97507-H34126 | \$ 2,676.00 | 10% | <i>\$2,426.46</i> |
| EW ResponsePLS 4HR AHR H34127 | 97507-H34127 | \$ 2,676.00 | 10% | <i>\$2,426.46</i> |
| EW ResponsePLS 4HR AHR H34129 | 97507-H34129 | \$ 1,708.00 | 10% | <i>\$1,548.73</i> |
| EW ResponsePLS 4HR AHR H34130 | 97507-H34130 | \$ 1,775.00 | 10% | <i>\$1,609.48</i> |
| EW ResponsePLS 4HR AHR H34131 | 97507-H34131 | \$ 1,766.00 | 10% | <i>\$1,601.32</i> |
| EW ResponsePLS 4HR AHR H34132 | 97507-H34132 | \$ 1,775.00 | 10% | <i>\$1,609.48</i> |
| EW ResponsePLS 4HR AHR H34172 | 97507-H34172 | \$ 3,093.00 | 10% | <i>\$2,804.58</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H34726 | 97507-H34726 | \$ 5,127.00 | 10% | <i>\$4,648.91</i> |
| EW ResponsePLS 4HR AHR H34727 | 97507-H34727 | \$ 5,127.00 | 10% | <i>\$4,648.91</i> |
| EW ResponsePLS 4HR AHR H34728 | 97507-H34728 | \$ 5,127.00 | 10% | <i>\$4,648.91</i> |
| EW ResponsePLS 4HR AHR H34729 | 97507-H34729 | \$ 5,127.00 | 10% | <i>\$4,648.91</i> |
| EW ResponsePLS 4HR AHR H34730 | 97507-H34730 | \$ 5,410.00 | 10% | <i>\$4,905.52</i> |
| EW ResponsePLS 4HR AHR H34731 | 97507-H34731 | \$ 5,410.00 | 10% | <i>\$4,905.52</i> |
| EW ResponsePLS 4HR AHR H34732 | 97507-H34732 | \$ 5,410.00 | 10% | <i>\$4,905.52</i> |
| EW ResponsePLS 4HR AHR H34733 | 97507-H34733 | \$ 5,410.00 | 10% | <i>\$4,905.52</i> |
| EW ResponsePLS 4HR AHR H34734 | 97507-H34734 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsePLS 4HR AHR H34735 | 97507-H34735 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsePLS 4HR AHR H34736 | 97507-H34736 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H34737 | 97507-H34737 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H34738 | 97507-H34738 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34739 | 97507-H34739 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34740 | 97507-H34740 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsePLS 4HR AHR H34741 | 97507-H34741 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsePLS 4HR AHR H34742 | 97507-H34742 | \$ 1,747.00 | 10% | <i>\$1,584.09</i> |
| EW ResponsePLS 4HR AHR H34743 | 97507-H34743 | \$ 1,747.00 | 10% | <i>\$1,584.09</i> |
| EW ResponsePLS 4HR AHR H34744 | 97507-H34744 | \$ 2,013.00 | 10% | <i>\$1,825.29</i> |
| EW ResponsePLS 4HR AHR H34745 | 97507-H34745 | \$ 2,013.00 | 10% | <i>\$1,825.29</i> |
| EW ResponsePLS 4HR AHR H34746 | 97507-H34746 | \$ 2,108.00 | 10% | <i>\$1,911.43</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR H34747 | 97507-H34747 | \$ 2,108.00 | 10% | <i>\$1,911.43</i> |
| EW ResponsePLS 4HR AHR H34748 | 97507-H34748 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34749 | 97507-H34749 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34750 | 97507-H34750 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34751 | 97507-H34751 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34752 | 97507-H34752 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34753 | 97507-H34753 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34754 | 97507-H34754 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34755 | 97507-H34755 | \$ 2,715.00 | 10% | <i>\$2,461.83</i> |
| EW ResponsePLS 4HR AHR H34756 | 97507-H34756 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H34757 | 97507-H34757 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H34758 | 97507-H34758 | \$ 2,013.00 | 10% | <i>\$1,825.29</i> |
| EW ResponsePLS 4HR AHR H34759 | 97507-H34759 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H34760 | 97507-H34760 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H34761 | 97507-H34761 | \$ 2,013.00 | 10% | <i>\$1,825.29</i> |
| EW ResponsePLS 4HR AHR H34993 | 97507-H34993 | \$ 20,825.00 | 10% | <i>\$18,883.07</i> |
| EW ResponsePLS 4HR AHR H34994 | 97507-H34994 | \$ 20,825.00 | 10% | <i>\$18,883.07</i> |
| EW ResponsePLS 4HR AHR H34996 | 97507-H34996 | \$ 20,825.00 | 10% | <i>\$18,883.07</i> |
| EW ResponsePLS 4HR AHR H34997 | 97507-H34997 | \$ 20,825.00 | 10% | <i>\$18,883.07</i> |
| EW ResponsePLS 4HR AHR H35005 | 97507-H35005 | \$ 14,840.00 | 10% | <i>\$13,456.17</i> |
| EW ResponsePLS 4HR AHR H35006 | 97507-H35006 | \$ 14,840.00 | 10% | <i>\$13,456.17</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H35012 | 97507-H35012 | \$ 9,931.00 | 10% | <i>\$9,004.93</i> |
| EW ResponsePLS 4HR AHR H35270 | 97507-H35270 | \$ 1,823.00 | 10% | <i>\$1,653.01</i> |
| EW ResponsePLS 4HR AHR H35271 | 97507-H35271 | \$ 1,668.00 | 10% | <i>\$1,512.46</i> |
| EW ResponsePLS 4HR AHR H35272 | 97507-H35272 | \$ 1,539.00 | 10% | <i>\$1,395.49</i> |
| EW ResponsePLS 4HR AHR H35273 | 97507-H35273 | \$ 1,539.00 | 10% | <i>\$1,395.49</i> |
| EW ResponsePLS 4HR AHR H35274 | 97507-H35274 | \$ 2,119.00 | 10% | <i>\$1,921.40</i> |
| EW ResponsePLS 4HR AHR H35275 | 97507-H35275 | \$ 1,990.00 | 10% | <i>\$1,804.43</i> |
| EW ResponsePLS 4HR AHR H35276 | 97507-H35276 | \$ 4,904.00 | 10% | <i>\$4,446.70</i> |
| EW ResponsePLS 4HR AHR H35277 | 97507-H35277 | \$ 5,782.00 | 10% | <i>\$5,242.83</i> |
| EW ResponsePLS 4HR AHR H35278 | 97507-H35278 | \$ 4,156.00 | 10% | <i>\$3,768.45</i> |
| EW ResponsePLS 4HR AHR H35279 | 97507-H35279 | \$ 4,641.00 | 10% | <i>\$4,208.23</i> |
| EW ResponsePLS 4HR AHR H35280 | 97507-H35280 | \$ 9,514.00 | 10% | <i>\$8,626.82</i> |
| EW ResponsePLS 4HR AHR H35292 | 97507-H35292 | \$ 4,156.00 | 10% | <i>\$3,768.45</i> |
| EW ResponsePLS 4HR AHR H35293 | 97507-H35293 | \$ 4,641.00 | 10% | <i>\$4,208.23</i> |
| EW ResponsePLS 4HR AHR H35295 | 97507-H35295 | \$ 1,626.00 | 10% | <i>\$1,474.38</i> |
| EW ResponsePLS 4HR AHR H35302 | 97507-H35302 | \$ 4,051.00 | 10% | <i>\$3,673.24</i> |
| EW ResponsePLS 4HR AHR H35303 | 97507-H35303 | \$ 4,051.00 | 10% | <i>\$3,673.24</i> |
| EW ResponsePLS 4HR AHR H35304 | 97507-H35304 | \$ 4,051.00 | 10% | <i>\$3,673.24</i> |
| EW ResponsePLS 4HR AHR H35305 | 97507-H35305 | \$ 4,187.00 | 10% | <i>\$3,796.56</i> |
| EW ResponsePLS 4HR AHR H35306 | 97507-H35306 | \$ 4,187.00 | 10% | <i>\$3,796.56</i> |
| EW ResponsePLS 4HR AHR H35307 | 97507-H35307 | \$ 4,187.00 | 10% | <i>\$3,796.56</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H35309 | 97507-H35309 | \$ 4,910.00 | 10% | <i>\$4,452.14</i> |
| EW ResponsePLS 4HR AHR H35310 | 97507-H35310 | \$ 4,910.00 | 10% | <i>\$4,452.14</i> |
| EW ResponsePLS 4HR AHR H35311 | 97507-H35311 | \$ 4,910.00 | 10% | <i>\$4,452.14</i> |
| EW ResponsePLS 4HR AHR H35312 | 97507-H35312 | \$ 4,054.00 | 10% | <i>\$3,675.96</i> |
| EW ResponsePLS 4HR AHR H35313 | 97507-H35313 | \$ 4,054.00 | 10% | <i>\$3,675.96</i> |
| EW ResponsePLS 4HR AHR H35314 | 97507-H35314 | \$ 4,054.00 | 10% | <i>\$3,675.96</i> |
| EW ResponsePLS 4HR AHR H35315 | 97507-H35315 | \$ 2,501.00 | 10% | <i>\$2,267.78</i> |
| EW ResponsePLS 4HR AHR H35318 | 97507-H35318 | \$ 1,694.00 | 10% | <i>\$1,536.03</i> |
| EW ResponsePLS 4HR AHR H35319 | 97507-H35319 | \$ 1,923.00 | 10% | <i>\$1,743.68</i> |
| EW ResponsePLS 4HR AHR H35320 | 97507-H35320 | \$ 1,955.00 | 10% | <i>\$1,772.70</i> |
| EW ResponsePLS 4HR AHR H35321 | 97507-H35321 | \$ 2,222.00 | 10% | <i>\$2,014.80</i> |
| EW ResponsePLS 4HR AHR H35322 | 97507-H35322 | \$ 2,531.00 | 10% | <i>\$2,294.98</i> |
| EW ResponsePLS 4HR AHR H35323 | 97507-H35323 | \$ 2,501.00 | 10% | <i>\$2,267.78</i> |
| EW ResponsePLS 4HR AHR H35328 | 97507-H35328 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW ResponsePLS 4HR AHR H35330 | 97507-H35330 | \$ 1,170.00 | 10% | <i>\$1,060.90</i> |
| EW ResponsePLS 4HR AHR H35340 | 97507-H35340 | \$ 4,570.00 | 10% | <i>\$4,143.85</i> |
| EW ResponsePLS 4HR AHR H35341 | 97507-H35341 | \$ 4,570.00 | 10% | <i>\$4,143.85</i> |
| EW ResponsePLS 4HR AHR H35342 | 97507-H35342 | \$ 3,848.00 | 10% | <i>\$3,489.17</i> |
| EW ResponsePLS 4HR AHR H35343 | 97507-H35343 | \$ 4,570.00 | 10% | <i>\$4,143.85</i> |
| EW ResponsePLS 4HR AHR H35344 | 97507-H35344 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsePLS 4HR AHR H35345 | 97507-H35345 | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|------------|
| EW ResponsePLS 4HR AHR H35346 | 97507-H35346 | \$ 3,952.00 | 10% | \$3,583.48 |
| EW ResponsePLS 4HR AHR H35347 | 97507-H35347 | \$ 4,700.00 | 10% | \$4,261.73 |
| EW ResponsePLS 4HR AHR H35349 | 97507-H35349 | \$ 5,040.00 | 10% | \$4,570.02 |
| EW ResponsePLS 4HR AHR H35350 | 97507-H35350 | \$ 5,040.00 | 10% | \$4,570.02 |
| EW ResponsePLS 4HR AHR H35351 | 97507-H35351 | \$ 4,222.00 | 10% | \$3,828.30 |
| EW ResponsePLS 4HR AHR H35352 | 97507-H35352 | \$ 5,040.00 | 10% | \$4,570.02 |
| EW ResponsePLS 4HR AHR H35359 | 97507-H35359 | \$ 2,222.00 | 10% | \$2,014.80 |
| EW ResponsePLS 4HR AHR H35360 | 97507-H35360 | \$ 2,531.00 | 10% | \$2,294.98 |
| EW ResponsePLS 4HR AHR H35361 | 97507-H35361 | \$ 2,501.00 | 10% | \$2,267.78 |
| EW ResponsePLS 4HR AHR H35362 | 97507-H35362 | \$ 1,694.00 | 10% | \$1,536.03 |
| EW ResponsePLS 4HR AHR H35366 | 97507-H35366 | \$ 1,699.00 | 10% | \$1,540.57 |
| EW ResponsePLS 4HR AHR H35367 | 97507-H35367 | \$ 1,982.00 | 10% | \$1,797.18 |
| EW ResponsePLS 4HR AHR H35368 | 97507-H35368 | \$ 3,016.00 | 10% | \$2,734.76 |
| EW ResponsePLS 4HR AHR H35369 | 97507-H35369 | \$ 982.00 | 10% | \$890.43 |
| EW ResponsePLS 4HR AHR H35370 | 97507-H35370 | \$ 1,381.00 | 10% | \$1,252.22 |
| EW ResponsePLS 4HR AHR H35375 | 97507-H35375 | \$ 1,125.00 | 10% | \$1,020.09 |
| EW ResponsePLS 4HR AHR H35376 | 97507-H35376 | \$ 1,685.00 | 10% | \$1,527.87 |
| EW ResponsePLS 4HR AHR H35377 | 97507-H35377 | \$ 707.00 | 10% | \$641.07 |
| EW ResponsePLS 4HR AHR H35378 | 97507-H35378 | \$ 1,125.00 | 10% | \$1,020.09 |
| EW ResponsePLS 4HR AHR H35379 | 97507-H35379 | \$ 707.00 | 10% | \$641.07 |
| EW ResponsePLS 4HR AHR H35380 | 97507-H35380 | \$ 1,265.00 | 10% | \$1,147.04 |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H35381 | 97507-H35381 | \$ 1,546.00 | 10% | <i>\$1,401.84</i> |
| EW ResponsePLS 4HR AHR H35384 | 97507-H35384 | \$ 566.00 | 10% | <i>\$513.22</i> |
| EW ResponsePLS 4HR AHR H35385 | 97507-H35385 | \$ 757.00 | 10% | <i>\$686.41</i> |
| EW ResponsePLS 4HR AHR H35386 | 97507-H35386 | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW ResponsePLS 4HR AHR H35387 | 97507-H35387 | \$ 1,173.00 | 10% | <i>\$1,063.62</i> |
| EW ResponsePLS 4HR AHR H35388 | 97507-H35388 | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW ResponsePLS 4HR AHR H35389 | 97507-H35389 | \$ 488.00 | 10% | <i>\$442.49</i> |
| EW ResponsePLS 4HR AHR H35390 | 97507-H35390 | \$ 423.00 | 10% | <i>\$383.56</i> |
| EW ResponsePLS 4HR AHR H35391 | 97507-H35391 | \$ 923.00 | 10% | <i>\$836.93</i> |
| EW ResponsePLS 4HR AHR H35392 | 97507-H35392 | \$ 1,412.00 | 10% | <i>\$1,280.33</i> |
| EW ResponsePLS 4HR AHR H35393 | 97507-H35393 | \$ 1,882.00 | 10% | <i>\$1,706.50</i> |
| EW ResponsePLS 4HR AHR H35394 | 97507-H35394 | \$ 336.00 | 10% | <i>\$304.67</i> |
| EW ResponsePLS 4HR AHR H35395 | 97507-H35395 | \$ 286.00 | 10% | <i>\$259.33</i> |
| EW ResponsePLS 4HR AHR H35396 | 97507-H35396 | \$ 336.00 | 10% | <i>\$304.67</i> |
| EW ResponsePLS 4HR AHR H35397 | 97507-H35397 | \$ 286.00 | 10% | <i>\$259.33</i> |
| EW ResponsePLS 4HR AHR H35398 | 97507-H35398 | \$ 878.00 | 10% | <i>\$796.13</i> |
| EW ResponsePLS 4HR AHR H35399 | 97507-H35399 | \$ 1,069.00 | 10% | <i>\$969.32</i> |
| EW ResponsePLS 4HR AHR H35400 | 97507-H35400 | \$ 1,177.00 | 10% | <i>\$1,067.24</i> |
| EW ResponsePLS 4HR AHR H35401 | 97507-H35401 | \$ 629.00 | 10% | <i>\$570.35</i> |
| EW ResponsePLS 4HR AHR H35415 | 97507-H35415 | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsePLS 4HR AHR H35416 | 97507-H35416 | \$ 386.00 | 10% | <i>\$350.01</i> |

| | | | | |
|----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H35426 | 97507-H35426 | \$ 488.00 | 10% | <i>\$442.49</i> |
| EW ResponsePLS 4HR AHR H35427 | 97507-H35427 | \$ 1,173.00 | 10% | <i>\$1,063.62</i> |
| EW ResponsePLS 4HR AHR H35428 | 97507-H35428 | \$ 423.00 | 10% | <i>\$383.56</i> |
| EW ResponsePLS 4HR AHR H35429 | 97507-H35429 | \$ 923.00 | 10% | <i>\$836.93</i> |
| EW ResponsePLS 4HR AHR H35430 | 97507-H35430 | \$ 1,802.00 | 10% | <i>\$1,633.96</i> |
| EW ResponsePLS 4HR AHR H35431 | 97507-H35431 | \$ 1,802.00 | 10% | <i>\$1,633.96</i> |
| EW ResponsePLS 4HR AHR H35432 | 97507-H35432 | \$ 1,747.00 | 10% | <i>\$1,584.09</i> |
| EW ResponsePLS 4HR AHR H35433 | 97507-H35433 | \$ 1,964.00 | 10% | <i>\$1,780.86</i> |
| EW ResponsePLS 4HR AHR H35434 | 97507-H35434 | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |
| EW ResponsePLS 4HR AHR H35435 | 97507-H35435 | \$ 2,057.00 | 10% | <i>\$1,865.18</i> |
| EW ResponsePLS 4HR AHR H35436 | 97507-H35436 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW ResponsePLS 4HR AHR H35437 | 97507-H35437 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW ResponsePLS 4HR AHR H35438 | 97507-H35438 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW ResponsePLS 4HR AHR H35439 | 97507-H35439 | \$ 2,637.00 | 10% | <i>\$2,391.10</i> |
| EW ResponsePLS 4HR AHR H35440 | 97507-H35440 | \$ 1,964.00 | 10% | <i>\$1,780.86</i> |
| EW ResponsePLS 4HR AHR H35441 | 97507-H35441 | \$ 1,964.00 | 10% | <i>\$1,780.86</i> |
| EW ResponsePLS 4HR AHR H35442 | 97507-H35442 | \$ 1,964.00 | 10% | <i>\$1,780.86</i> |
| EW ResponsePLS 4HR AHR H35443 | 97507-H35443 | \$ 5,127.00 | 10% | <i>\$4,648.91</i> |
| EW ResponsePLS 4HR AHR H35444 | 97507-H35444 | \$ 5,410.00 | 10% | <i>\$4,905.52</i> |
| EW ResponsePLS 4HR AHR H35445 | 97507-H35445 | \$ 4,904.00 | 10% | <i>\$4,446.70</i> |
| EW ResponsePLS 4HR AHR H35446 | 97507-H35446 | \$ 4,809.00 | 10% | <i>\$4,360.56</i> |

| | | | | |
|----------------------------------|--------------|--------------|-----|-------------------|
| EW ResponsePLS 4HR AHR H35447 | 97507-H35447 | \$ 5,481.00 | 10% | <i>\$4,969.90</i> |
| EW ResponsePLS 4HR AHR H35448 | 97507-H35448 | \$ 5,300.00 | 10% | <i>\$4,805.78</i> |
| EW ResponsePLS 4HR AHR H35449 | 97507-H35449 | \$ 4,156.00 | 10% | <i>\$3,768.45</i> |
| EW ResponsePLS 4HR AHR H35450 | 97507-H35450 | \$ 4,398.00 | 10% | <i>\$3,987.89</i> |
| EW ResponsePLS 4HR AHR H35451 | 97507-H35451 | \$ 10,069.00 | 10% | <i>\$9,130.07</i> |
| EW ResponsePLS 4HR AHR H35452 | 97507-H35452 | \$ 10,069.00 | 10% | <i>\$9,130.07</i> |
| EW ResponsePLS 4HR AHR H35453 | 97507-H35453 | \$ 5,410.00 | 10% | <i>\$4,905.52</i> |
| EW ResponsePLS 4HR AHR H35454 | 97507-H35454 | \$ 5,127.00 | 10% | <i>\$4,648.91</i> |
| EW ResponsePLS 4HR AHR H35455 | 97507-H35455 | \$ 1,955.00 | 10% | <i>\$1,772.70</i> |
| EW ResponsePLS 4HR AHR H35456 | 97507-H35456 | \$ 2,156.00 | 10% | <i>\$1,954.95</i> |
| EW ResponsePLS 4HR AHR H35457 | 97507-H35457 | \$ 2,063.00 | 10% | <i>\$1,870.63</i> |
| EW ResponsePLS 4HR AHR H35458 | 97507-H35458 | \$ 2,166.00 | 10% | <i>\$1,964.02</i> |
| EW ResponsePLS 4HR AHR H35471 | 97507-H35471 | \$ 1,956.00 | 10% | <i>\$1,773.60</i> |
| EW ResponsePLS 4HR AHR H35600 | 97507-H35600 | \$ 1,539.00 | 10% | <i>\$1,395.49</i> |
| EW ResponsePLS 4HR AHR H35601 | 97507-H35601 | \$ 1,539.00 | 10% | <i>\$1,395.49</i> |
| EW ResponsePLS 4HR AHR H35602 | 97507-H35602 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsePLS 4HR AHR H35603 | 97507-H35603 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsePLS 4HR AHR H35604 | 97507-H35604 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H35605 | 97507-H35605 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |
| EW ResponsePLS 4HR AHR H35606 | 97507-H35606 | \$ 2,119.00 | 10% | <i>\$1,921.40</i> |
| EW ResponsePLS 4HR AHR H35607 | 97507-H35607 | \$ 2,108.00 | 10% | <i>\$1,911.43</i> |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EW ResponsePLS 4HR AHR ISW-24W-4X | 97507-ISW- 24W-4X | \$ 1,826.00 | 10% | <i>\$1,655.73</i> |
| EW ResponsePLS 4HR AHR ISW-4W-4WS-4X | 97507-ISW-4W- 4WS-4X | \$ 1,454.00 | 10% | <i>\$1,318.41</i> |
| EW ResponsePLUS 4HR AHR- MS128 | 97507- MSM128 | \$ 3,464.00 | 10% | <i>\$3,140.98</i> |
| EW ResponsePLS 4HR AHR- MSM48C | 97507- MSM48C | \$ 2,385.00 | 10% | <i>\$2,162.60</i> |
| EW ResponsePLS 4HR AHR SLX9150-48XT-DC-F | 97507- SLX9150- 48XT-DC-F | \$ 4,100.00 | 10% | <i>\$3,717.68</i> |
| EW ResponsePLS 4HR AHR SLX9150-48XT-DC-R | 97507- SLX9150- 48XT-DC-R | \$ 4,477.00 | 10% | <i>\$4,059.52</i> |
| EW ResponsePLS 4HR AHR SLX9150-48Y-DC-F | 97507- SLX9150-48Y- DC-F | \$ 3,985.00 | 10% | <i>\$3,613.40</i> |
| EW ResponsePLS 4HR AHR SLX9150-48Y-DC-R | 97507- SLX9150-48Y- DC-R | \$ 4,351.00 | 10% | <i>\$3,945.27</i> |
| EW ResponsePLS 4HR AHR SLX9740-40C | 97507- SLX9740-40C | \$ 13,297.00 | 10% | <i>\$12,057.05</i> |
| EW ResponsePLS 4HR AHR SLX9740-40C-AC-F | 97507- SLX9740-40C- AC-F | \$ 13,297.00 | 10% | <i>\$12,057.05</i> |
| EW ResponsePLS 4HR AHR SLX9740-40C-AC-R | 97507- SLX9740-40C- AC-R | \$ 13,297.00 | 10% | <i>\$12,057.05</i> |
| EW ResponsePLS 4HR AHR SLX9740-40C-DC-F | 97507- SLX9740-40C- DC-F | \$ 13,297.00 | 10% | <i>\$12,057.05</i> |
| EW ResponsePLS 4HR AHR SLX9740-80C | 97507- SLX9740-80C | \$ 24,041.00 | 10% | <i>\$21,799.18</i> |
| EW ResponsePLS 4HR AHR SLX9740-80C-AC-F | 97507- SLX9740-80C- AC-F | \$ 24,041.00 | 10% | <i>\$21,799.18</i> |
| EW ResponsePLS 4HR AHR SLX9740-80C-AC-R | 97507- SLX9740-80C- AC-R | \$ 24,041.00 | 10% | <i>\$21,799.18</i> |
| EW ResponsePLS 4HR AHR SLX9740-80C-DC-F | 97507- SLX9740-80C- DC-F | \$ 24,041.00 | 10% | <i>\$21,799.18</i> |

| | | | | |
|---|---|-------------|-----|------------|
| EW ResponsePLS 4HR AHR V300-8P-2X | 97507-V300- 8P-2X | \$ 870.00 | 10% | \$788.87 |
| EW ResponsePLS 4HR AHR V300-8T-2X | 97507-V300- 8T-2X | \$ 821.00 | 10% | \$744.44 |
| EW ResponsePLS 4HR AHR V300HT-8P-2X | 97507-V300HT- 8P-2X | \$ 1,078.00 | 10% | \$977.48 |
| EW ResponsePLS 4HR AHR V300HT-8T-2X | 97507-V300HT- 8T-2X | \$ 929.00 | 10% | \$842.37 |
| EW ResponsePLS 4HR AHR- VIM-SS | 97507-VIM-SS | \$ 612.00 | 10% | \$554.93 |
| EW ResponsePLS 4HR AHRVIMSSV80 | 97507-VIM- SSV80 | \$ 749.00 | 10% | \$679.16 |
| EW ResponsePLS 4HR AHR- VIM2-SS | 97507-VIM2- SS | \$ 611.00 | 10% | \$554.02 |
| EW ResponsePLS 4HR AHRVIM2SS | 97507-VIM2- SS128 | \$ 1,074.00 | 10% | \$973.85 |
| EW ResponsePLS 4HR AHRVIM2V80 | 97507-VIM2- V80 | \$ 1,147.00 | 10% | \$1,040.04 |
| EW ResponsePLS 4HR AHRVIM | 97507- VIM210G4X | \$ 1,629.00 | 10% | \$1,477.10 |
| EW RespPLS 4HR AHR VSP4900-12MXU-12XE | 97507- VSP4900- 12MXU-12XE | \$ 2,331.00 | 10% | \$2,113.63 |
| EW RespPLS 4HR AHR VSP4900-12MXU-12XE-B1 | 97507- VSP4900- 12MXU-12XE- B1 | \$ 2,331.00 | 10% | \$2,113.63 |
| EW ResponsePLS 4HR AHR VSP4900-24S | 97507- VSP4900-24S | \$ 1,694.00 | 10% | \$1,536.03 |
| EW ResponsePLS 4HR AHR VSP4900-24S-B3 | 97507- VSP4900-24S- B3 | \$ 1,694.00 | 10% | \$1,536.03 |
| EW ResponsePLS 4HR AHR VSP4900-24XE | 97507- VSP4900- 24XE | \$ 2,331.00 | 10% | \$2,113.63 |
| EW ResponsePLS 4HR AHR VSP4900-24XE-B3 | 97507- VSP4900- 24XE-B3 | \$ 2,331.00 | 10% | \$2,113.63 |
| EW ResponsePLS 4HR AHR X435-24P-4S | 97507-X435- 24P-4S | \$ 995.00 | 10% | \$902.22 |

| | | | | |
|--|------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR X435-24T-4S | 97507-X435- 24T-4S | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW ResponsePLS 4HR AHR X435-8P-2T-W | 97507-X435- 8P-2T-W | \$ 865.00 | 10% | <i>\$784.34</i> |
| EW ResponsePLS 4HR AHR X435-8P-4S | 97507-X435- 8P-4S | \$ 852.00 | 10% | <i>\$772.55</i> |
| EW ResponsePLS 4HR AHR X435-8T-4S | 97507-X435- 8T-4S | \$ 823.00 | 10% | <i>\$746.26</i> |
| EW ResponsePLS 4HR AHRX46024P | 97507-X460- 24P | \$ 2,473.00 | 10% | <i>\$2,242.39</i> |
| EW ResponsePLS 4HR AHRX46024T | 97507-X460- 24T | \$ 2,107.00 | 10% | <i>\$1,910.52</i> |
| EW ResponsePLS 4HR AHRX46024T | 97507-X460- 24TDC | \$ 2,526.00 | 10% | <i>\$2,290.45</i> |
| EW ResponsePLS 4HR AHRX46024X | 97507-X460- 24X | \$ 2,790.00 | 10% | <i>\$2,529.83</i> |
| EW ResponsePLS 4HR AHRX46024X | 97507-X460- 24XDC | \$ 3,016.00 | 10% | <i>\$2,734.76</i> |
| EW ResponsePLS 4HR AHRX46048P | 97507-X460- 48P | \$ 2,790.00 | 10% | <i>\$2,529.83</i> |
| EW ResponsePLS 4HR AHRX46048T | 97507-X460- 48T | \$ 2,577.00 | 10% | <i>\$2,336.69</i> |
| EW ResponsePLS 4HR AHRX46048T | 97507-X460- 48TDC | \$ 2,957.00 | 10% | <i>\$2,681.26</i> |
| EW ResponsePLS 4HR AHRX46048X | 97507-X460- 48X | \$ 3,275.00 | 10% | <i>\$2,969.61</i> |
| EW ResponsePLS 4HR AHRX46048X | 97507-X460- 48XDC | \$ 3,281.00 | 10% | <i>\$2,975.05</i> |
| EW ResponsePLS 4HR AHR X465-24MU | 97507-X465- 24MU | \$ 2,531.00 | 10% | <i>\$2,294.98</i> |
| EW ResponsePLS 4HR AHR X465-24S | 97507-X465- 24S | \$ 1,694.00 | 10% | <i>\$1,536.03</i> |
| EW ResponsePLS 4HR AHR X465-24S-B3 | 97507-X465- 24S-B3 | \$ 1,694.00 | 10% | <i>\$1,536.03</i> |
| EW ResponsePLS 4HR AHR HX465-24W | 97507-X465- 24W | \$ 1,694.00 | 10% | <i>\$1,536.03</i> |
| EW ResponsePLS 4HR AHR X465-24XE | 97507-X465- 24XE | \$ 2,331.00 | 10% | <i>\$2,113.63</i> |
| EW ResponsePLS 4HR AHR X465-24XE-B3 | 97507-X465- 24XE-B3 | \$ 2,331.00 | 10% | <i>\$2,113.63</i> |
| EW ResponsePLS 4HR AHR X465-48P | 97507-X465- 48P | \$ 1,956.00 | 10% | <i>\$1,773.60</i> |

| | | | | |
|---|---------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HR AHR X465-48T | 97507-X465- 48T | \$ 1,923.00 | 10% | <i>\$1,743.68</i> |
| EW ResponsePLS 4HR AHR X465-48W | 97507-X465- 48W | \$ 2,222.00 | 10% | <i>\$2,014.80</i> |
| EW ResponsePLS 4HR AHR X465i-48W | 97507-X465i- 48W | \$ 2,501.00 | 10% | <i>\$2,267.78</i> |
| EW ResponsePLS 4HR AHR X465i-48W-B1-S1 | 97507-X465i- 48W-B1-S1 | \$ 2,501.00 | 10% | <i>\$2,267.78</i> |
| EW ResponsePLS 4HR AHR X465i-48W-B2-S1 | 97507-X465i- 48W-B2-S1 | \$ 2,501.00 | 10% | <i>\$2,267.78</i> |
| EW ResponsePLS 4HR AHRX48024X | 97507-X480- 24X | \$ 2,960.00 | 10% | <i>\$2,683.98</i> |
| EW ResponsePLUS 4HR AHR- X480T | 97507-X480- 48T | \$ 2,561.00 | 10% | <i>\$2,322.19</i> |
| EW ResponsePLS 4HR AHR- X48048 | 97507-X480- 48X | \$ 3,565.00 | 10% | <i>\$3,232.56</i> |
| EW ResponsePLS 4HR AHR X695-48Y-8C | 97507-X695- 48Y-8C | \$ 4,101.00 | 10% | <i>\$3,718.58</i> |
| EW ResponsePLS 4HR AHR XA1440 | 97507-XA1440 | \$ 1,035.00 | 10% | <i>\$938.49</i> |
| EW ResponsePLS 4HR AHR XA1480 | 97507-XA1480 | \$ 1,152.00 | 10% | <i>\$1,044.58</i> |
| EW ResponsePLS 4HR AHRXGM32SF | 97507-XGM3- 2SF | \$ 749.00 | 10% | <i>\$679.16</i> |
| EW ResponsePLS 4HR AHR XR600 | 97507-XR600 | \$ 1,206.00 | 10% | <i>\$1,093.54</i> |
| EW ResponsPLS 4HROnsite 1130C | 97508-1130C | \$ 3,152.00 | 6% | <i>\$2,985.10</i> |
| EW ResponsPLS 4HROnsite- 16119 | 97508-16119 | \$ 860.00 | 10% | <i>\$779.81</i> |
| EW ResponsPLS 4HROnsite- 16120 | 97508-16120 | \$ 965.00 | 10% | <i>\$875.01</i> |
| EW ResponsPLS 4HROnsite- 16126 | 97508-16126 | \$ 860.00 | 10% | <i>\$779.81</i> |
| EW ResponsPLS 4HROnsite- 16127 | 97508-16127 | \$ 901.00 | 10% | <i>\$816.98</i> |
| EW ResponsPLS 4HROnsite- 16172 | 97508-16172 | \$ 1,766.00 | 10% | <i>\$1,601.32</i> |
| EW ResponsPLS 4HROnsite 16172T | 97508-16172T | \$ 1,877.00 | 10% | <i>\$1,701.97</i> |
| EW ResponsPLS 4HROnsite- 16173 | 97508-16173 | \$ 1,781.00 | 10% | <i>\$1,614.92</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-16173T | 97508-16173T | \$ 1,890.00 | 10% | <i>\$1,713.76</i> |
| EW ResponsPLS 4HROnsite-16174 | 97508-16174 | \$ 1,979.00 | 10% | <i>\$1,794.46</i> |
| EW ResponsPLS 4HROnsite-16175 | 97508-16175 | \$ 2,067.00 | 10% | <i>\$1,874.25</i> |
| EW ResponsPLS 4HROnsite-16176 | 97508-16176 | \$ 1,979.00 | 10% | <i>\$1,794.46</i> |
| EW ResponsPLS 4HROnsite-16177 | 97508-16177 | \$ 1,873.00 | 10% | <i>\$1,698.34</i> |
| EW ResponsPLS 4HROnsite-16177T | 97508-16177T | \$ 2,134.00 | 10% | <i>\$1,935.00</i> |
| EW ResponsPLS 4HROnsite-16178 | 97508-16178 | \$ 2,275.00 | 10% | <i>\$2,062.86</i> |
| EW ResponsPLS 4HROnsite-16179 | 97508-16179 | \$ 2,298.00 | 10% | <i>\$2,083.71</i> |
| EW ResponsPLS 4HROnsite-16179T | 97508-16179T | \$ 2,452.00 | 10% | <i>\$2,223.35</i> |
| EW ResponsPLS 4HROnsite-16301T | 97508-16301T | \$ 3,707.00 | 10% | <i>\$3,361.32</i> |
| EW ResponsPLS 4HROnsite-16303T | 97508-16303T | \$ 3,707.00 | 10% | <i>\$3,361.32</i> |
| EW ResponsPLS 4HROnsite-16304T | 97508-16304T | \$ 4,558.00 | 10% | <i>\$4,132.97</i> |
| EW ResponsPLS 4HROnsite-16401T | 97508-16401T | \$ 2,503.00 | 10% | <i>\$2,269.60</i> |
| EW ResponsPLS 4HROnsite-16402T | 97508-16402T | \$ 3,119.00 | 10% | <i>\$2,828.15</i> |
| EW ResponsPLS 4HROnsite-16403T | 97508-16403T | \$ 2,923.00 | 10% | <i>\$2,650.43</i> |
| EW ResponsPLS 4HROnsite-16404T | 97508-16404T | \$ 2,923.00 | 10% | <i>\$2,650.43</i> |
| EW ResponsPLS 4HROnsite-16405T | 97508-16405T | \$ 3,428.00 | 10% | <i>\$3,108.34</i> |
| EW ResponsPLS 4HROnsite-16406T | 97508-16406T | \$ 4,131.00 | 10% | <i>\$3,745.78</i> |
| EW ResponsPLS 4HROnsite-16431 | 97508-16431 | \$ 3,017.00 | 10% | <i>\$2,735.66</i> |
| EW ResponsPLS 4HROnsite-16432 | 97508-16432 | \$ 3,188.00 | 10% | <i>\$2,890.72</i> |
| EW ResponsPLS 4HROnsite-16440 | 97508-16440 | \$ 2,343.00 | 10% | <i>\$2,124.52</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-16441 | 97508-16441 | \$ 2,233.00 | 10% | <i>\$2,024.77</i> |
| EW ResponsPLS 4HROnsite-16442 | 97508-16442 | \$ 901.00 | 10% | <i>\$816.98</i> |
| EW ResponsPLS 4HROnsite-16444 | 97508-16444 | \$ 674.00 | 10% | <i>\$611.15</i> |
| EW ResponsPLS 4HROnsite-16501 | 97508-16501 | \$ 1,557.00 | 10% | <i>\$1,411.81</i> |
| EW ResponsPLS 4HROnsite-16501T | 97508-16501T | \$ 1,631.00 | 10% | <i>\$1,478.91</i> |
| EW ResponsPLS 4HROnsite-16502 | 97508-16502 | \$ 1,673.00 | 10% | <i>\$1,516.99</i> |
| EW ResponsPLS 4HROnsite-16502T | 97508-16502T | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW ResponsPLS 4HROnsite-16503 | 97508-16503 | \$ 1,608.00 | 10% | <i>\$1,458.05</i> |
| EW ResponsPLS 4HROnsite-16503T | 97508-16503T | \$ 1,703.00 | 10% | <i>\$1,544.20</i> |
| EW ResponsPLS 4HROnsite-16504 | 97508-16504 | \$ 1,792.00 | 10% | <i>\$1,624.90</i> |
| EW ResponsPLS 4HROnsite-16504T | 97508-16504T | \$ 1,894.00 | 10% | <i>\$1,717.38</i> |
| EW ResponsPLS 4HROnsite-16505 | 97508-16505 | \$ 1,823.00 | 10% | <i>\$1,653.01</i> |
| EW ResponsPLS 4HROnsite-16505T | 97508-16505T | \$ 1,968.00 | 10% | <i>\$1,784.48</i> |
| EW ResponsPLS 4HROnsite-16506 | 97508-16506 | \$ 2,110.00 | 10% | <i>\$1,913.24</i> |
| EW ResponsPLS 4HROnsite-16506T | 97508-16506T | \$ 2,312.00 | 10% | <i>\$2,096.41</i> |
| EW ResponsPLS 4HROnsite-16507 | 97508-16507 | \$ 2,055.00 | 10% | <i>\$1,863.37</i> |
| EW ResponsPLS 4HROnsite-16507T | 97508-16507T | \$ 2,209.00 | 10% | <i>\$2,003.01</i> |
| EW ResponsPLS 4HROnsite-16508 | 97508-16508 | \$ 2,247.00 | 10% | <i>\$2,037.47</i> |
| EW ResponsPLS 4HROnsite-16508T | 97508-16508T | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-16509 | 97508-16509 | \$ 2,247.00 | 10% | <i>\$2,037.47</i> |
| EW ResponsPLS 4HROnsite-16509T | 97508-16509T | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-16510 | 97508-16510 | \$ 2,430.00 | 10% | <i>\$2,203.40</i> |
| EW ResponsPLS 4HROnsite-16510T | 97508-16510T | \$ 2,649.00 | 10% | <i>\$2,401.98</i> |
| EW ResponsPLS 4HROnsite-16513 | 97508-16513 | \$ 2,055.00 | 10% | <i>\$1,863.37</i> |
| EW ResponsPLS 4HROnsite-16514 | 97508-16514 | \$ 2,384.00 | 10% | <i>\$2,161.69</i> |
| EW ResponsPLS 4HROnsite-16515 | 97508-16515 | \$ 1,418.00 | 10% | <i>\$1,285.77</i> |
| EW ResponsPLS 4HROnsite-16516 | 97508-16516 | \$ 1,436.00 | 10% | <i>\$1,302.09</i> |
| EW ResponsPLS 4HROnsite-16517 | 97508-16517 | \$ 1,629.00 | 10% | <i>\$1,477.10</i> |
| EW ResponsPLS 4HROnsite-16518 | 97508-16518 | \$ 1,587.00 | 10% | <i>\$1,439.01</i> |
| EW ResponsPLS 4HROnsite-16519 | 97508-16519 | \$ 1,690.00 | 10% | <i>\$1,532.41</i> |
| EW ResponsPLS 4HROnsite-16520 | 97508-16520 | \$ 1,924.00 | 10% | <i>\$1,744.59</i> |
| EW ResponsPLUS 4HROnsite-16530 | 97508-16530 | \$ 1,581.00 | 10% | <i>\$1,433.57</i> |
| EW ResponsPLUS 4HROnsite-16531 | 97508-16531 | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW ResponsPLUS 4HROnsite16531T | 97508-16531T | \$ 1,680.00 | 10% | <i>\$1,523.34</i> |
| EW ResponsPLUS 4HROnsite-16532 | 97508-16532 | \$ 1,663.00 | 10% | <i>\$1,507.93</i> |
| EW ResponsPLUS 4HROnsite16532T | 97508-16532T | \$ 1,680.00 | 10% | <i>\$1,523.34</i> |
| EW ResponsPLUS 4HROnsite-16533 | 97508-16533 | \$ 1,786.00 | 10% | <i>\$1,619.46</i> |
| EW ResponsPLUS 4HROnsite16533T | 97508-16533T | \$ 1,817.00 | 10% | <i>\$1,647.56</i> |
| EW ResponsPLUS 4HROnsite-16534 | 97508-16534 | \$ 1,817.00 | 10% | <i>\$1,647.56</i> |
| EW ResponsPLUS 4HROnsite-16535 | 97508-16535 | \$ 2,036.00 | 10% | <i>\$1,846.14</i> |
| EW ResponsPLUS 4HROnsite-16535A | 97508-16535A | \$ 2,036.00 | 10% | <i>\$1,846.14</i> |
| EW ResponsPLUS 4HROnsite16535T | 97508-16535T | \$ 2,105.00 | 10% | <i>\$1,908.71</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLUS 4HRonsite-16536 | 97508-16536 | \$ 1,555.00 | 10% | <i>\$1,410.00</i> |
| EW ResponsPLUS 4HRonsite-16537 | 97508-16537 | \$ 1,666.00 | 10% | <i>\$1,510.65</i> |
| EW ResponsPLUS 4HRonsite-16538 | 97508-16538 | \$ 1,749.00 | 10% | <i>\$1,585.91</i> |
| EW ResponsPLUS 4HRonsite16538T | 97508-16538T | \$ 1,976.00 | 10% | <i>\$1,791.74</i> |
| EW ResponsPLUS 4HRonsite-16539 | 97508-16539 | \$ 1,899.00 | 10% | <i>\$1,721.92</i> |
| EW ResponsPLUS 4HRonsite-16540 | 97508-16540 | \$ 1,714.00 | 10% | <i>\$1,554.17</i> |
| EW ResponsPLUS 4HRonsite-16541 | 97508-16541 | \$ 1,418.00 | 10% | <i>\$1,285.77</i> |
| EW ResponsPLS 4HRonsite 16560 | 97508-16560 | \$ 1,295.00 | 10% | <i>\$1,174.24</i> |
| EW ResponsPLS 4HRonsite 16561 | 97508-16561 | \$ 1,343.00 | 10% | <i>\$1,217.77</i> |
| EW ResponsPLS 4HRonsite 16562 | 97508-16562 | \$ 1,376.00 | 10% | <i>\$1,247.69</i> |
| EW ResponsPLS 4HRonsite 16563 | 97508-16563 | \$ 1,438.00 | 10% | <i>\$1,303.91</i> |
| EW ResponsPLS 4HRonsite 16564 | 97508-16564 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW ResponsPLS 4HRonsite 16565 | 97508-16565 | \$ 1,647.00 | 10% | <i>\$1,493.42</i> |
| EW ResponsPLS 4HRonsite 16566 | 97508-16566 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW ResponsPLS 4HRonsite 16567 | 97508-16567 | \$ 1,314.00 | 10% | <i>\$1,191.47</i> |
| EW ResponsPLS 4HRonsite 16568 | 97508-16568 | \$ 1,296.00 | 10% | <i>\$1,175.15</i> |
| EW ResponsPLS 4HRonsite 16569 | 97508-16569 | \$ 1,355.00 | 10% | <i>\$1,228.65</i> |
| EW ResponsPLS 4HRonsite 16570 | 97508-16570 | \$ 1,376.00 | 10% | <i>\$1,247.69</i> |
| EW ResponsPLS 4HRonsite 16571 | 97508-16571 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW ResponsPLS 4HRonsite-16701 | 97508-16701 | \$ 1,886.00 | 10% | <i>\$1,710.13</i> |
| EW ResponsPLS 4HRonsite-16702 | 97508-16702 | \$ 2,196.00 | 10% | <i>\$1,991.22</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-16703 | 97508-16703 | \$ 2,123.00 | 10% | <i>\$1,925.03</i> |
| EW ResponsPLS 4HROnsite 16703T | 97508-16703T | \$ 2,276.00 | 10% | <i>\$2,063.76</i> |
| EW ResponsPLUS 4HROnsite-16704 | 97508-16704 | \$ 2,470.00 | 10% | <i>\$2,239.67</i> |
| EW ResponsPLS 4HROnsite 16704T | 97508-16704T | \$ 2,135.00 | 10% | <i>\$1,935.91</i> |
| EW ResponsPLS 4HROnsite-16705 | 97508-16705 | \$ 2,196.00 | 10% | <i>\$1,991.22</i> |
| EW ResponsPLS 4HROnsite 16705T | 97508-16705T | \$ 2,351.00 | 10% | <i>\$2,131.77</i> |
| EW ResponsPLS 4HROnsite-16706 | 97508-16706 | \$ 2,826.00 | 10% | <i>\$2,562.48</i> |
| EW ResponsPLS 4HROnsite 16706T | 97508-16706T | \$ 3,020.00 | 10% | <i>\$2,738.39</i> |
| EW ResponsPLS 4HROnsite-16710 | 97508-16710 | \$ 719.00 | 10% | <i>\$651.95</i> |
| EW ResponsPLS 4HROnsite 16710T | 97508-16710T | \$ 767.00 | 10% | <i>\$695.48</i> |
| EW ResponsPLS 4HROnsite-16711 | 97508-16711 | \$ 543.00 | 10% | <i>\$492.37</i> |
| EW ResponsPLS 4HROnsite 16711T | 97508-16711T | \$ 585.00 | 10% | <i>\$530.45</i> |
| EW ResponsPLS 4HROnsite-16712 | 97508-16712 | \$ 596.00 | 10% | <i>\$540.42</i> |
| EW ResponsPLS 4HROnsite 16712T | 97508-16712T | \$ 622.00 | 10% | <i>\$564.00</i> |
| EW ResponsPLS 4HROnsite-16713 | 97508-16713 | \$ 498.00 | 10% | <i>\$451.56</i> |
| EW ResponsPLS 4HROnsite 16713T | 97508-16713T | \$ 531.00 | 10% | <i>\$481.48</i> |
| EW ResponsPLS 4HROnsite-16715 | 97508-16715 | \$ 530.00 | 10% | <i>\$480.58</i> |
| EW ResponsPLS 4HROnsite 16715T | 97508-16715T | \$ 585.00 | 10% | <i>\$530.45</i> |
| EW ResponsPLS 4HROnsite-16716 | 97508-16716 | \$ 1,869.00 | 10% | <i>\$1,694.72</i> |
| EW ResponsPLS 4HROnsite 16716T | 97508-16716T | \$ 2,015.00 | 10% | <i>\$1,827.10</i> |
| EW ResponsPLS 4HROnsite-16717 | 97508-16717 | \$ 2,010.00 | 10% | <i>\$1,822.57</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-16718 | 97508-16718 | \$ 1,917.00 | 10% | <i>\$1,738.24</i> |
| EW ResponsPLS 4HROnsite-16719 | 97508-16719 | \$ 2,064.00 | 10% | <i>\$1,871.53</i> |
| EW ResponsPLS 4HROnsite 16720 | 97508-16720 | \$ 2,492.00 | 10% | <i>\$2,259.62</i> |
| EW ResponsPLS 4HROnsite 16720T | 97508-16720T | \$ 2,905.00 | 10% | <i>\$2,634.11</i> |
| EW ResponsPLS 4HROnsite 16756 | 97508-16756 | \$ 2,264.00 | 10% | <i>\$2,052.88</i> |
| EW ResponsPLS 4HROnsite 16756T | 97508-16756T | \$ 2,677.00 | 10% | <i>\$2,427.37</i> |
| EW ResponsPLS 4HROnsite 16757 | 97508-16757 | \$ 2,211.00 | 10% | <i>\$2,004.82</i> |
| EW ResponsPLS 4HROnsite 16757T | 97508-16757T | \$ 2,609.00 | 10% | <i>\$2,365.71</i> |
| EW ResponsPLS 4HROnsite 16790 | 97508-16790 | \$ 2,630.00 | 10% | <i>\$2,384.75</i> |
| EW ResponsPLS 4HROnsite 16791 | 97508-16791 | \$ 3,395.00 | 10% | <i>\$3,078.42</i> |
| EW ResponsPLS 4HROnsite-17101 | 97508-17101 | \$ 4,891.00 | 10% | <i>\$4,434.91</i> |
| EW ResponsPLS 4HROnsite-17101T | 97508-17101T | \$ 6,120.00 | 10% | <i>\$5,549.31</i> |
| EW ResponsPLS 4HROnsite-17102 | 97508-17102 | \$ 4,891.00 | 10% | <i>\$4,434.91</i> |
| EW ResponsPLS 4HROnsite-17102T | 97508-17102T | \$ 6,120.00 | 10% | <i>\$5,549.31</i> |
| EW ResponsPLS 4HROnsite-17103 | 97508-17103 | \$ 3,749.00 | 10% | <i>\$3,399.41</i> |
| EW ResponsPLS 4HROnsite-17103C | 97508-17103C | \$ 3,639.00 | 10% | <i>\$3,299.66</i> |
| EW ResponsPLS 4HROnsite-17103T | 97508-17103T | \$ 4,667.00 | 10% | <i>\$4,231.80</i> |
| EW ResponsPLS 4HROnsite-17104 | 97508-17104 | \$ 3,749.00 | 10% | <i>\$3,399.41</i> |
| EW ResponsPLS 4HROnsite-17104T | 97508-17104T | \$ 4,667.00 | 10% | <i>\$4,231.80</i> |
| EW ResponsPLS 4HROnsite-17121 | 97508-17121 | \$ 1,193.00 | 10% | <i>\$1,081.75</i> |
| EW ResponsPLS 4HROnsite-17122 | 97508-17122 | \$ 884.00 | 10% | <i>\$801.57</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-17200 | 97508-17200 | \$ 7,051.00 | 10% | <i>\$6,393.49</i> |
| EW ResponsPLS 4HROnsite-17200T | 97508-17200T | \$ 7,936.00 | 10% | <i>\$7,195.97</i> |
| EW ResponsPLS 4HROnsite-17201 | 97508-17201 | \$ 7,051.00 | 10% | <i>\$6,393.49</i> |
| EW ResponsPLS 4HROnsite-17201T | 97508-17201T | \$ 7,936.00 | 10% | <i>\$7,195.97</i> |
| EW ResponsPLS 4HROnsite-17202 | 97508-17202 | \$ 7,051.00 | 10% | <i>\$6,393.49</i> |
| EW ResponsPLS 4HROnsite-17202T | 97508-17202T | \$ 7,936.00 | 10% | <i>\$7,195.97</i> |
| EW ResponsPLS 4HROnsite-17203 | 97508-17203 | \$ 7,138.00 | 10% | <i>\$6,472.38</i> |
| EW ResponsPLS 4HROnsite-17203T | 97508-17203T | \$ 8,041.00 | 10% | <i>\$7,291.18</i> |
| EW ResponsPLS 4HROnsite-17204 | 97508-17204 | \$ 7,138.00 | 10% | <i>\$6,472.38</i> |
| EW ResponsPLS 4HROnsite-17204T | 97508-17204T | \$ 8,041.00 | 10% | <i>\$7,291.18</i> |
| EW ResponsPLS 4HROnsite-17205 | 97508-17205 | \$ 7,094.00 | 10% | <i>\$6,432.48</i> |
| EW ResponsPLS 4HROnsite-17205T | 97508-17205T | \$ 7,989.00 | 10% | <i>\$7,244.03</i> |
| EW ResponsPLS 4HROnsite-17206 | 97508-17206 | \$ 7,094.00 | 10% | <i>\$6,432.48</i> |
| EW ResponsPLS 4HROnsite-17206T | 97508-17206T | \$ 7,989.00 | 10% | <i>\$7,244.03</i> |
| EW ResponsPLS 4HROnsite-17300 | 97508-17300 | \$ 5,126.00 | 10% | <i>\$4,648.00</i> |
| EW ResponsPLS 4HROnsite-17310 | 97508-17310 | \$ 4,760.00 | 10% | <i>\$4,316.13</i> |
| EW ResponsPLS 4HROnsite-17350 | 97508-17350 | \$ 4,954.00 | 10% | <i>\$4,492.04</i> |
| EW ResponsPLS 4HROnsite-17360 | 97508-17360 | \$ 5,820.00 | 10% | <i>\$5,277.29</i> |
| EW ResponsPLS 4HROnsite-17401 | 97508-17401 | \$ 1,771.00 | 10% | <i>\$1,605.85</i> |
| EW ResponsPLS 4HROnsite-17401G | 97508-17401G | \$ 1,832.00 | 10% | <i>\$1,661.17</i> |
| EW ResponsPLS 4HROnsite-17401T | 97508-17401T | \$ 1,832.00 | 10% | <i>\$1,661.17</i> |

| | | | | |
|--------------------------------------|---------------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite 17402 | 97508-17402 | \$ 1,918.00 | 10% | <i>\$1,739.15</i> |
| EW ResponsPLS 4HROnsite 17402G | 97508-17402G | \$ 1,905.00 | 10% | <i>\$1,727.36</i> |
| EW ResponsPLS 4HROnsite 17402T | 97508-17402T | \$ 1,905.00 | 10% | <i>\$1,727.36</i> |
| EW ResponsPLS 4HROnsite 17403 | 97508-17403 | \$ 1,982.00 | 10% | <i>\$1,797.18</i> |
| EW ResponsPLS 4HROnsite 17404 | 97508-17404 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsPLS 4HROnsite 17405 | 97508-17405 | \$ 1,649.00 | 10% | <i>\$1,495.23</i> |
| EW ResponsPLS 4HROnsite 17700 | 97508-17700 | \$ 8,412.00 | 10% | <i>\$7,627.58</i> |
| EW ResponsPLS 4HROnsite- 17701 | 97508-17701 | \$ 7,190.00 | 10% | <i>\$6,519.53</i> |
| EW ResponsPLS 4HROnsite- 17702 | 97508-17702 | \$ 7,190.00 | 10% | <i>\$6,519.53</i> |
| EW ResponsPLS 4HROnsite- 17703 | 97508-17703 | \$ 7,855.00 | 10% | <i>\$7,122.52</i> |
| EW ResponsPLS 4HROnsite- 17704 | 97508-17704 | \$ 7,855.00 | 10% | <i>\$7,122.52</i> |
| EW ResponsPLS 4HROnsite- 17705 | 97508-17705 | \$ 7,232.00 | 10% | <i>\$6,557.62</i> |
| EW ResponsPLS 4HROnsite- 17706 | 97508-17706 | \$ 7,232.00 | 10% | <i>\$6,557.62</i> |
| EW ResponsPLS 4HROnsite 17800 | 97508-17800 | \$ 8,517.00 | 10% | <i>\$7,722.79</i> |
| EW ResponsPLS 4HROnsite 17810 | 97508-17810 | \$ 7,061.00 | 10% | <i>\$6,402.56</i> |
| EW ResponsPLS 4HROnsite 18101 | 97508-18101 | \$ 738.00 | 10% | <i>\$669.18</i> |
| EW ResponsPLS 4HROnsite 18102 | 97508-18102 | \$ 841.00 | 10% | <i>\$762.58</i> |
| EW ResponsPLS 4HROnsite 18103 | 97508-18103 | \$ 886.00 | 10% | <i>\$803.38</i> |
| EW ResponsPLS 4HROnsite 18104 | 97508-18104 | \$ 1,098.00 | 10% | <i>\$995.61</i> |
| EW ResponsPLS 4HROnsite 18104-6PK | 97508-18104- 6PK | \$ 6,584.00 | 10% | <i>\$5,970.04</i> |
| EW ResponsPLS 4HROnsite- 30135 | 97508-30135 | \$ 3,309.00 | 10% | <i>\$3,000.44</i> |

| | | | | |
|----------------------------------|-------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite 30136 | 97508-30136 | \$ 10,113.00 | 10% | <i>\$9,169.96</i> |
| EW ResponsPLS 4HROnsite 30137 | 97508-30137 | \$ 2,705.00 | 10% | <i>\$2,452.76</i> |
| EW ResponsPLS 4HROnsite 30138 | 97508-30138 | \$ 7,671.00 | 10% | <i>\$6,955.68</i> |
| EW ResponsPLS 4HROnsite 30139 | 97508-30139 | \$ 13,209.00 | 10% | <i>\$11,977.26</i> |
| EW ResponsPLS 4HROnsite 30912 | 97508-30912 | \$ 449.00 | 10% | <i>\$407.13</i> |
| EW ResponsPLS 4HROnsite 30913 | 97508-30913 | \$ 449.00 | 10% | <i>\$407.13</i> |
| EW ResponsPLS 4HROnsite 31012 | 97508-31012 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW ResponsPLS 4HROnsite 31013 | 97508-31013 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW ResponsPLS 4HROnsite 31014 | 97508-31014 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW ResponsPLS 4HROnsite 31015 | 97508-31015 | \$ 470.00 | 10% | <i>\$426.17</i> |
| EW ResponsPLS 4HROnsite 31016 | 97508-31016 | \$ 715.00 | 10% | <i>\$648.33</i> |
| EW ResponsPLS 4HROnsite 31017 | 97508-31017 | \$ 715.00 | 10% | <i>\$648.33</i> |
| EW ResponsPLS 4HROnsite 31018 | 97508-31018 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsPLS 4HROnsite 31019 | 97508-31019 | \$ 765.00 | 10% | <i>\$693.66</i> |
| EW ResponsPLS 4HROnsite 31025 | 97508-31025 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS 4HROnsite 31026 | 97508-31026 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS 4HROnsite 31028 | 97508-31028 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS 4HROnsite 31029 | 97508-31029 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS 4HROnsite 31031 | 97508-31031 | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW ResponsPLS 4HROnsite 31032 | 97508-31032 | \$ 399.00 | 10% | <i>\$361.79</i> |
| EW ResponsPLS 4HROnsite 31034 | 97508-31034 | \$ 475.00 | 10% | <i>\$430.71</i> |

| | | | | |
|---|------------------------|--------------|-----|-------------------|
| EW ResponsPLS 4HROnsite 31035 | 97508-31035 | \$ 475.00 | 10% | <i>\$430.71</i> |
| EW ResponsPLS 4HROnsite 31050 | 97508-31050 | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW ResponsPLS 4HROnsite 31051 | 97508-31051 | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW ResponsPLS 4HROnsite 31055 | 97508-31055 | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW ResponsPLS 4HROnsite 31056 | 97508-31056 | \$ 457.00 | 10% | <i>\$414.38</i> |
| EW ResponsPLS 4HROnsite 39031 | 97508-39031 | \$ 868.00 | 10% | <i>\$787.06</i> |
| EW ResponsPLS 4HROnsite 39032 | 97508-39032 | \$ 922.00 | 10% | <i>\$836.02</i> |
| EW ResponsPLS 4HROnsite 39033 | 97508-39033 | \$ 868.00 | 10% | <i>\$787.06</i> |
| EW ResponsPLS 4HROnsite 39034 | 97508-39034 | \$ 868.00 | 10% | <i>\$787.06</i> |
| EW ResponsPLS 4HROnsite 39035 | 97508-39035 | \$ 1,843.00 | 10% | <i>\$1,671.14</i> |
| EW ResponsPLS 4HROnsite 39036 | 97508-39036 | \$ 774.00 | 10% | <i>\$701.82</i> |
| EW ResponsPLS 4HROnsite 39037 | 97508-39037 | \$ 774.00 | 10% | <i>\$701.82</i> |
| EW ResponsPLS 4HROnsite 39038 | 97508-39038 | \$ 932.00 | 10% | <i>\$845.09</i> |
| EW ResponsPLS 4HROnsite 39039 | 97508-39039 | \$ 932.00 | 10% | <i>\$845.09</i> |
| EW ResponsPLS 4HROnsite 4120-24MW-4Y | 97508-4120- 24MW-4Y | \$ 1,933.00 | 10% | <i>\$1,752.75</i> |
| EW ResponsPLS 4HROnsite 4120-48MW-4Y | 97508-4120- 48MW-4Y | \$ 2,308.00 | 10% | <i>\$2,092.78</i> |
| EW ResponsPLS 4HROnsite 4120C | 97508-4120C | \$ 8,870.00 | 10% | <i>\$8,042.87</i> |
| EW ResponsPLS 4HROnsite 4120C-1 | 97508-4120C-1 | \$ 10,014.00 | 10% | <i>\$9,080.19</i> |
| EW ResponsPLS 4HROnsite 41216 | 97508-41216 | \$ 2,831.00 | 10% | <i>\$2,567.01</i> |
| EW ResponsPLS 4HROnsite 4220-12P-4X | 97508-4220- 12P-4X | \$ 1,135.00 | 10% | <i>\$1,029.16</i> |
| EW ResponsPLS 4HROnsite 4220-12T-4X | 97508-4220- 12T-4X | \$ 1,048.00 | 10% | <i>\$950.27</i> |

| | | | | |
|--|---------------------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite 4220-24P-4X | 97508-4220- 24P-4X | \$ 1,244.00 | 10% | <i>\$1,128.00</i> |
| EW ResponsPLS 4HROnsite 4220-24T-4X | 97508-4220- 24T-4X | \$ 1,146.00 | 10% | <i>\$1,039.14</i> |
| EW ResponsPLS 4HROnsite 4220-48P-4X | 97508-4220- 48P-4X | \$ 1,462.00 | 10% | <i>\$1,325.67</i> |
| EW ResponsPLS 4HROnsite 4220-48T-4X | 97508-4220- 48T-4X | \$ 1,299.00 | 10% | <i>\$1,177.87</i> |
| EW ResponsPLS 4HROnsite 4220-4MW-20P-4X | 97508-4220- 4MW-20P-4X | \$ 1,408.00 | 10% | <i>\$1,276.70</i> |
| EW ResponsPLS 4HROnsite 4220-4MW-8P-4X | 97508-4220- 4MW-8P-4X | \$ 1,233.00 | 10% | <i>\$1,118.02</i> |
| EW ResponsPLS 4HROnsite 4220-8MW-40P-4X | 97508-4220- 8MW-40P-4X | \$ 1,680.00 | 10% | <i>\$1,523.34</i> |
| EW ResponsPLS 4HROnsite 4220-8X | 97508-4220-8X | \$ 1,266.00 | 10% | <i>\$1,147.95</i> |
| EW ResponsPLS 4HROnsite- 48001 | 97508-48001 | \$ 12,374.00 | 10% | <i>\$11,220.12</i> |
| EW ResponsPLS 4HROnsite- 48038 | 97508-48038 | \$ 4,419.00 | 10% | <i>\$4,006.93</i> |
| EW ResponsPLS 4HROnsite- 48039 | 97508-48039 | \$ 4,419.00 | 10% | <i>\$4,006.93</i> |
| EW ResponsPLS 4HROnsite- 48040 | 97508-48040 | \$ 4,204.00 | 10% | <i>\$3,811.98</i> |
| EW ResponsPLS 4HROnsite- 48041 | 97508-48041 | \$ 4,419.00 | 10% | <i>\$4,006.93</i> |
| EW ResponsPLS 4HROnsite- 48046 | 97508-48046 | \$ 5,656.00 | 10% | <i>\$5,128.58</i> |
| EW ResponsPLS 4HROnsite- 48047 | 97508-48047 | \$ 14,324.00 | 10% | <i>\$12,988.29</i> |
| EW ResponsPLS 4HROnsite- 48051 | 97508-48051 | \$ 9,991.00 | 10% | <i>\$9,059.34</i> |
| EW ResponsPLS 4HROnsite- 48061 | 97508-48061 | \$ 11,598.00 | 10% | <i>\$10,516.49</i> |
| EW ResponsPLS 4HROnsite- 48062 | 97508-48062 | \$ 18,290.00 | 10% | <i>\$16,584.46</i> |
| EW ResponsPLS 4HROnsite 5320-16P-4XE | 97508-5320- 16P-4XE | \$ 1,416.00 | 10% | <i>\$1,283.96</i> |
| EW ResponsPLS 4HROnsite 5320-16P-4XE-DC | 97508-5320- 16P-4XE-DC | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW ResponsPLS 4HROnsite 5320-24P-8XE | 97508-5320- 24P-8XE | \$ 1,460.00 | 10% | <i>\$1,323.86</i> |

| | | | | |
|--|---------------------------|-------------|-----|------------|
| EW ResponsPLS 4HROns 5320-24T-24S-4XE-XT | 97508-5320-24T-24S-4XE-XT | \$ 1,517.00 | 10% | \$1,375.54 |
| EW ResponsPLS 4HROnsite 5320-24T-4X-XT | 97508-5320-24T-4X-XT | \$ 1,190.00 | 10% | \$1,079.03 |
| EW ResponsPLS 4HROnsite 5320-24T-8XE | 97508-5320-24T-8XE | \$ 1,323.00 | 10% | \$1,199.63 |
| EW ResponsPLS 4HROnsite 5320-48P-8XE | 97508-5320-48P-8XE | \$ 1,829.00 | 10% | \$1,658.45 |
| EW ResponsPLS 4HROnsite 5320-48T-8XE | 97508-5320-48T-8XE | \$ 1,579.00 | 10% | \$1,431.76 |
| EW ResponsPLS 4HROnsi 5420F-16MW-32P-4XE | 97508-5420F-16MW-32P-4XE | \$ 2,577.00 | 10% | \$2,336.69 |
| EW ResponsPLS 4HROnsit 5420F-16W-32P-4XE | 97508-5420F-16W-32P-4XE | \$ 2,505.00 | 10% | \$2,271.41 |
| EW ResponsPLS 4HROnsite 5420F-24P-4XE | 97508-5420F-24P-4XE | \$ 1,776.00 | 10% | \$1,610.39 |
| EW ResponsPLS 4HROnsite 5420F-24S-4XE | 97508-5420F-24S-4XE | \$ 1,833.00 | 10% | \$1,662.07 |
| EW ResponsPLS 4HROnsite 5420F-24T-4XE | 97508-5420F-24T-4XE | \$ 1,672.00 | 10% | \$1,516.09 |
| EW ResponsPLS 4HROnsite 5420F-48P-4XE | 97508-5420F-48P-4XE | \$ 2,107.00 | 10% | \$1,910.52 |
| EW ResponsPLS 4HROnsite 5420F-48P-4XL | 97508-5420F-48P-4XL | \$ 2,223.00 | 10% | \$2,015.71 |
| EW ResponsPLS 4HROnsite 5420F-48T-4XE | 97508-5420F-48T-4XE | \$ 1,806.00 | 10% | \$1,637.59 |
| EW ResponsPLS 4HROnsite 5420F-8W-16P-4XE | 97508-5420F-8W-16P-4XE | \$ 1,822.00 | 10% | \$1,652.10 |
| EW ResponsPLS 4HROnsi 5420M-16MW-32P-4YE | 97508-5420M-16MW-32P-4YE | \$ 2,715.00 | 10% | \$2,461.83 |
| EW ResponsPLS 4HROnsite 5420M-24T-4YE | 97508-5420M-24T-4YE | \$ 1,797.00 | 10% | \$1,629.43 |
| EW ResponsPLS 4HROnsite 5420M-24W-4YE | 97508-5420M-24W-4YE | \$ 1,649.00 | 10% | \$1,495.23 |
| EW ResponsPLS 4HROnsite 5420M-48T-4YE | 97508-5420M-48T-4YE | \$ 2,035.00 | 10% | \$1,845.24 |
| EW ResponsPLS 4HROnsite 5420M-48W-4YE | 97508-5420M-48W-4YE | \$ 2,238.00 | 10% | \$2,029.31 |

| | | | | |
|---|-----------------------------------|-------------|-----|------------|
| EW RESPONSEPLUS 4HR ONSITE 5520-12MW-36W | 97508-5520- 12MW-36W | \$ 2,848.00 | 10% | \$2,582.42 |
| EW RESPONSEPLUS 4HR ONSITE 5520-24T | 97508-5520- 24T | \$ 1,789.00 | 10% | \$1,622.18 |
| EW RESPONSEPLU 4HR ON 5520-24T-ACDC-BASE | 97508-5520- 24T-ACDC- BASE | \$ 1,789.00 | 10% | \$1,622.18 |
| EW RESPONSEPLUS 4HR ONSITE 5520-24T-BASE | 97508-5520- 24T-BASE | \$ 1,789.00 | 10% | \$1,622.18 |
| EW RESPONSEPLUS 4HR ONSITE 5520-24W | 97508-5520- 24W | \$ 1,934.00 | 10% | \$1,753.65 |
| EW RESPONSEPLUS 4HR ONSITE 5520-24X | 97508-5520- 24X | \$ 2,949.00 | 10% | \$2,674.01 |
| EW RESPONSEPLU 4HR ON 5520-24X-ACDC-BASE | 97508-5520- 24X-ACDC- BASE | \$ 2,949.00 | 10% | \$2,674.01 |
| EW RESPONSEPLUS 4HR ONSITE 5520-24X-BASE | 97508-5520- 24X-BASE | \$ 2,949.00 | 10% | \$2,674.01 |
| EW RESPONSEPLUS 4HR ONSITE 5520-48SE | 97508-5520- 48SE | \$ 2,831.00 | 10% | \$2,567.01 |
| EW RESPONSEPL 4HR ON 5520-48SE-ACDC-BASE | 97508-5520- 48SE-ACDC- BASE | \$ 2,831.00 | 10% | \$2,567.01 |
| EW RESPONSEPLUS 4HR ONSIT 5520-48SE-BASE | 97508-5520- 48SE-BASE | \$ 2,831.00 | 10% | \$2,567.01 |
| EW RESPONSEPLUS 4HR ONSITE 5520-48T | 97508-5520- 48T | \$ 2,232.00 | 10% | \$2,023.87 |
| EW RESPONSEPLU 4HR ON 5520-48T-ACDC-BASE | 97508-5520- 48T-ACDC- BASE | \$ 2,232.00 | 10% | \$2,023.87 |
| EW RESPONSEPLUS 4HR ONSITE 5520-48T-BASE | 97508-5520- 48T-BASE | \$ 2,232.00 | 10% | \$2,023.87 |
| EW RESPONSEPLUS 4HR ONSITE 5520-48W | 97508-5520- 48W | \$ 2,573.00 | 10% | \$2,333.07 |
| EW ResponsPLS 4HROnsite 5720-24MW | 97508-5720- 24MW | \$ 2,597.00 | 10% | \$2,354.83 |
| EW ResponsPLS 4HROnsite 5720-24MXW | 97508-5720- 24MXW | \$ 3,428.00 | 10% | \$3,108.34 |
| EW ResponsPLS 4HROnsite 5720-48MW | 97508-5720- 48MW | \$ 2,949.00 | 10% | \$2,674.01 |
| EW ResponsPLS 4HROnsite 5720-48MXW | 97508-5720- 48MXW | \$ 4,034.00 | 10% | \$3,657.83 |

| | | | | |
|--|----------------------------------|-------------|-----|------------|
| EW ResponsPLS 4HROnsite 7520-48XT-6C | 97508-7520- 48XT-6C | \$ 4,773.00 | 10% | \$4,327.92 |
| EW ResponsPLS 4HROnsit 7520- 48XT-6C-AC-F | 97508-7520- 48XT-6C-AC- F | \$ 4,773.00 | 10% | \$4,327.92 |
| EW ResponsPLS 4HROnsit 7520- 48XT-6C-AC-R | 97508-7520- 48XT-6C-AC- R | \$ 4,773.00 | 10% | \$4,327.92 |
| EW ResponsPLS 4HROnsite 7520-48Y-8C | 97508-7520- 48Y-8C | \$ 4,465.00 | 10% | \$4,048.64 |
| EW ResponsPLS 4HROnsite 7520-48Y-8C-AC-F | 97508-7520- 48Y-8C-AC-F | \$ 4,465.00 | 10% | \$4,048.64 |
| EW ResponsPLS 4HROnsite 7520-48Y-8C-AC-R | 97508-7520- 48Y-8C-AC-R | \$ 4,465.00 | 10% | \$4,048.64 |
| EW RESPONSEPLUS 4HR ONSITE 7520-48YE-8CE | 97508-7520- 48YE-8CE | \$ 5,163.00 | 10% | \$4,681.55 |
| EW RESPONSEPLU 4HRONS 7520-48YE-8CE-AC-F | 97508-7520- 48YE-8CE-AC- F | \$ 5,163.00 | 10% | \$4,681.55 |
| EW RESPONSEPLU 4HRONS 7520-48YE-8CE-AC-R | 97508-7520- 48YE-8CE-AC- R | \$ 5,163.00 | 10% | \$4,681.55 |
| EW ResponsPLS 4HROnsite 7720-32C | 97508-7720- 32C | \$ 5,496.00 | 10% | \$4,983.50 |
| EW ResponsPLS 4HROnsite 7720-32C-AC-F | 97508-7720- 32C-AC-F | \$ 5,496.00 | 10% | \$4,983.50 |
| EW ResponsPLS 4HROnsite 7720-32C-AC-R | 97508-7720- 32C-AC-R | \$ 5,496.00 | 10% | \$4,983.50 |
| EW ResponsPLS 4HROnsite 8520-48XT-6C | 97508-8520- 48XT-6C | \$ 4,519.00 | 10% | \$4,097.60 |
| EW ResponsPLS4HROnsite 8520-48XT-6C-AC-F | 97508-8520- 48XT-6C-AC- F | \$ 4,519.00 | 10% | \$4,097.60 |
| EW ResponsPLS4HROnsite 8520-48XT-6C-AC-R | 97508-8520- 48XT-6C-AC- R | \$ 4,519.00 | 10% | \$4,097.60 |
| EW ResponsPLS4HROnsite 8520-48XT-6C-DC-F | 97508-8520- 48XT-6C-DC- F | \$ 4,519.00 | 10% | \$4,097.60 |
| EW ResponsPLS4HROnsite 8520-48XT-6C-DC-R | 97508-8520- 48XT-6C-DC- R | \$ 4,519.00 | 10% | \$4,097.60 |

| | | | | |
|---|----------------------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite 8520-48Y-8C | 97508-8520- 48Y-8C | \$ 4,650.00 | 10% | <i>\$4,216.39</i> |
| EW ResponsPLS 4HROnsite 8520-48Y-8C-AC-F | 97508-8520- 48Y-8C-AC-F | \$ 4,650.00 | 10% | <i>\$4,216.39</i> |
| EW ResponsPLS 4HROnsite 8520-48Y-8C-AC-R | 97508-8520- 48Y-8C-AC-R | \$ 4,650.00 | 10% | <i>\$4,216.39</i> |
| EW ResponsPLS 4HROnsite 8520-48Y-8C-DC-F | 97508-8520- 48Y-8C-DC-F | \$ 4,650.00 | 10% | <i>\$4,216.39</i> |
| EW ResponsPLS 4HROnsite 8520-48Y-8C-DC-R | 97508-8520- 48Y-8C-DC-R | \$ 4,650.00 | 10% | <i>\$4,216.39</i> |
| EW ResponsPLS 4HROnsite 8720-32C | 97508-8720- 32C | \$ 5,139.00 | 10% | <i>\$4,659.79</i> |
| EW ResponsPLS 4HROnsite 8720-32C-AC-F | 97508-8720- 32C-AC-F | \$ 5,139.00 | 10% | <i>\$4,659.79</i> |
| EW ResponsPLS 4HROnsite 8720-32C-AC-R | 97508-8720- 32C-AC-R | \$ 5,139.00 | 10% | <i>\$4,659.79</i> |
| EW ResponsPLS 4HROnsite 8720-32C-DC-F | 97508-8720- 32C-DC-F | \$ 5,139.00 | 10% | <i>\$4,659.79</i> |
| EW ResponsPLS 4HROnsite 8720-32C-DC-R | 97508-8720- 32C-DC-R | \$ 5,139.00 | 10% | <i>\$4,659.79</i> |
| EW ResponsPLUS 4HROnsite- 8806 | 97508-8806 | \$ 5,106.00 | 10% | <i>\$4,629.87</i> |
| EW ResponsPLS 4HROnsite- 8810 | 97508-8810 | \$ 10,436.00 | 10% | <i>\$9,462.84</i> |
| EW ResponsPLS 4HROnsite 8820-40C | 97508-8820- 40C | \$ 15,017.00 | 10% | <i>\$13,616.66</i> |
| EW ResponsPLS 4HROnsite 8820-40C-AC-F | 97508-8820- 40C-AC-F | \$ 15,017.00 | 10% | <i>\$13,616.66</i> |
| EW ResponsPLS 4HROnsite 8820-40C-AC-R | 97508-8820- 40C-AC-R | \$ 15,017.00 | 10% | <i>\$13,616.66</i> |
| EW ResponsPLS 4HROnsite 8820-40C-DC-F | 97508-8820- 40C-DC-F | \$ 15,017.00 | 10% | <i>\$13,616.66</i> |
| EW ResponsPLS 4HROnsite 8820-40C-DC-R | 97508-8820- 40C-DC-R | \$ 15,017.00 | 10% | <i>\$13,616.66</i> |
| EW ResponsPLS 4HROnsite 8820-80C | 97508-8820- 80C | \$ 26,528.00 | 10% | <i>\$24,054.26</i> |
| EW ResponsPLS 4HROnsite 8820-80C-AC-F | 97508-8820- 80C-AC-F | \$ 26,528.00 | 10% | <i>\$24,054.26</i> |
| EW ResponsPLS 4HROnsite 8820-80C-AC-R | 97508-8820- 80C-AC-R | \$ 26,528.00 | 10% | <i>\$24,054.26</i> |
| EW ResponsPLS 4HROnsite 8820-80C-DC-F | 97508-8820- 80C-DC-F | \$ 26,528.00 | 10% | <i>\$24,054.26</i> |

| | | | | |
|---|---------------------------------|--------------|-----|-------------|
| EW ResponsPLS 4HROnsite 8820-80C-DC-R | 97508-8820- 80C-DC-R | \$ 26,528.00 | 10% | \$24,054.26 |
| EW ResponsPLS 4HROnsite 9920-16C | 97508-9920- 16C | \$ 13,654.00 | 10% | \$12,380.76 |
| EW ResponsPLS 4HROnsite 9920-4D | 97508-9920-4D | \$ 13,654.00 | 10% | \$12,380.76 |
| EW ResponsPLS 4HROnsite 9920-NPB-8 | 97508-9920- NPB-8 | \$ 19,744.00 | 10% | \$17,902.87 |
| EW ResponsePLS 4HROnsite AH-AP-1130-AC-C | 97508-AH-AP- 1130-AC-CE | \$ 437.00 | 10% | \$396.25 |
| EW ResponsePLS 4HROnsite AH-AP-1130-AC-F | 97508-AH-AP- 1130-AC-FCC | \$ 437.00 | 10% | \$396.25 |
| EW ResponsePLS 4HROnsite AH-AP-1130-AC-W | 97508-AH-AP- 1130-AC-W | \$ 437.00 | 10% | \$396.25 |
| EW ResponsePLS 4HROnsite AH-AP-122-AC-CA | 97508-AH-AP- 122-AC-CAN | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-122-AC-CE | 97508-AH-AP- 122-AC-CE | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-122-AC-FC | 97508-AH-AP- 122-AC-FCC | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-122-AC-W | 97508-AH-AP- 122-AC-W | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-130-AC-CE | 97508-AH-AP- 130-AC-CE | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-130-AC-FC | 97508-AH-AP- 130-AC-FCC | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-130-AC-W | 97508-AH-AP- 130-AC-W | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-150W-AC-C | 97508-AH-AP- 150W-AC- CAN | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-150W-AC-C | 97508-AH-AP- 150W-AC-CE | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-150W-AC-F | 97508-AH-AP- 150W-AC-FCC | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-150W-AC-W | 97508-AH-AP- 150W-AC-W | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-230-AC-CE | 97508-AH-AP- 230-AC-CE | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-230-AC-FC | 97508-AH-AP- 230-AC-FCC | \$ 390.00 | 10% | \$353.63 |

| | | | | |
|---|---------------------------------|-----------|-----|----------|
| EW ResponsePLS 4HROnsite AH-AP-230-AC-W | 97508-AH-AP- 230-AC-W | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-250-AC-CA | 97508-AH-AP- 250-AC-CAN | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-250-AC-CE | 97508-AH-AP- 250-AC-CE | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-250-AC-FC | 97508-AH-AP- 250-AC-FCC | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-250-AC-W | 97508-AH-AP- 250-AC-W | \$ 390.00 | 10% | \$353.63 |
| EW ResponsePLS 4HROnsite AH-AP-630-AX-CA | 97508-AH-AP- 630-AX-CAN | \$ 444.00 | 10% | \$402.60 |
| EW ResponsePLS 4HROnsite AH-AP-630-AX-CE | 97508-AH-AP- 630-AX-CE | \$ 444.00 | 10% | \$402.60 |
| EW ResponsePLS 4HROnsite AH-AP-630-AX-FC | 97508-AH-AP- 630-AX-FCC | \$ 444.00 | 10% | \$402.60 |
| EW ResponsePLS 4HROnsite AH-AP-630-AX-W | 97508-AH-AP- 630-AX-W | \$ 444.00 | 10% | \$402.60 |
| EW ResponsePLS 4HROnsite AH-AP-650-AX-CA | 97508-AH-AP- 650-AX-CAN | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-AP-650-AX-CE | 97508-AH-AP- 650-AX-CE | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-AP-650-AX-FC | 97508-AH-AP- 650-AX-FCC | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-AP-650-AX-W | 97508-AH-AP- 650-AX-W | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-AP-650X-AX-C | 97508-AH-AP- 650X-AX- CAN | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-AP-650X-AX-C | 97508-AH-AP- 650X-AX-CE | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-AP-650X-AX-F | 97508-AH-AP- 650X-AX-FCC | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-AP-650X-AX-W | 97508-AH-AP- 650X-AX-W | \$ 397.00 | 10% | \$359.98 |
| EW ResponsePLS 4HROnsite AH-ATOM-CAN | 97508-AH- ATOM-CAN | \$ 410.00 | 10% | \$371.77 |
| EW ResponsePLS 4HROnsite AH-ATOM-CE-EU | 97508-AH- ATOM-CE-EU | \$ 431.00 | 10% | \$390.81 |

| | | | | |
|--|--------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HROnsite AH-ATOM-CE-UK | 97508-AH- ATOM-CE-UK | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW ResponsePLS 4HROnsite AH-ATOM-FCC | 97508-AH- ATOM-FCC | \$ 409.00 | 10% | <i>\$370.86</i> |
| EW ResponsePLS 4HROnsite AH-ATOM-W | 97508-AH- ATOM-W | \$ 410.00 | 10% | <i>\$371.77</i> |
| EW ResponsePLS 4HROnsite AH-ATOM-W-EU | 97508-AH- ATOM-W-EU | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW ResponsePLS 4HROnsite AH-ATOM-W-UK | 97508-AH- ATOM-W-UK | \$ 431.00 | 10% | <i>\$390.81</i> |
| EW ResponsePLS 4HROnsite AH-SR-2208P-AU | 97508-AH-SR- 2208P-AU | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-SR-2208P-EU | 97508-AH-SR- 2208P-EU | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-SR-2208P-NA | 97508-AH-SR- 2208P-NA | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-SR-2208P-UK | 97508-AH-SR- 2208P-UK | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-SR-2224P-AU | 97508-AH-SR- 2224P-AU | \$ 1,194.00 | 10% | <i>\$1,082.66</i> |
| EW ResponsePLS 4HROnsite AH-SR-2224P-EU | 97508-AH-SR- 2224P-EU | \$ 1,194.00 | 10% | <i>\$1,082.66</i> |
| EW ResponsePLS 4HROnsite AH-SR-2224P-NA | 97508-AH-SR- 2224P-NA | \$ 1,194.00 | 10% | <i>\$1,082.66</i> |
| EW ResponsePLS 4HROnsite AH-SR-2224P-UK | 97508-AH-SR- 2224P-UK | \$ 1,194.00 | 10% | <i>\$1,082.66</i> |
| EW ResponsePLS 4HROnsite AH-SR-2324P-AU | 97508-AH-SR- 2324P-AU | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW ResponsePLS 4HROnsite AH-SR-2324P-EU | 97508-AH-SR- 2324P-EU | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW ResponsePLS 4HROnsite AH-SR-2324P-NA | 97508-AH-SR- 2324P-NA | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW ResponsePLS 4HROnsite AH-SR-2324P-UK | 97508-AH-SR- 2324P-UK | \$ 1,253.00 | 10% | <i>\$1,136.16</i> |
| EW ResponsePLS 4HROnsite AH-SR-2348P-AU | 97508-AH-SR- 2348P-AU | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsePLS 4HROnsite AH-SR-2348P-EU | 97508-AH-SR- 2348P-EU | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsePLS 4HROnsite AH-SR-2348P-NA | 97508-AH-SR- 2348P-NA | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |

| | | | | |
|--|---------------------------------|-------------|-----|-------------------|
| EW ResponsePLS 4HROnsite AH-SR-2348P-UK | 97508-AH-SR- 2348P-UK | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsePLS 4HROnsite AH-XR200P-AU | 97508-AH- XR200P-AU | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-XR200P-EU | 97508-AH- XR200P-EU | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-XR200P-UK | 97508-AH- XR200P-UK | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-XR200P-US | 97508-AH- XR200P-US | \$ 1,142.00 | 10% | <i>\$1,035.51</i> |
| EW ResponsePLS 4HROnsite AH-XR600P | 97508-AH- XR600P | \$ 1,151.00 | 10% | <i>\$1,043.67</i> |
| EW ResponsePLS 4HROnsite AH-XR600P-AU | 97508-AH- XR600P-AU | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW ResponsePLS 4HROnsite AH-XR600P-EU | 97508-AH- XR600P-EU | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW ResponsePLS 4HROnsite AH-XR600P-KR | 97508-AH- XR600P-KR | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW ResponsePLS 4HROnsite AH-XR600P-UK | 97508-AH- XR600P-UK | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW ResponsePLS 4HROnsite AH-XR600P-US | 97508-AH- XR600P-US | \$ 1,156.00 | 10% | <i>\$1,048.20</i> |
| EW ResponsPLS 4HROnsite AP- 8533-IL | 97508-AP- 8533-68SB30- IL | \$ 420.00 | 10% | <i>\$380.84</i> |
| EW ResponsPLS 4HROnsite AP3000-IL | 97508-AP3000- IL | \$ 291.24 | 10% | <i>\$264.08</i> |
| EW ResponsPLS 4HROnsite AP3000-TN | 97508-AP3000- TN | \$ 291.24 | 10% | <i>\$264.08</i> |
| EW ResponsPLS 4HROnsite AP3000-WW | 97508-AP3000- WW | \$ 291.24 | 10% | <i>\$264.08</i> |
| EW ResponsPLS 4HROnsite AP3000X-WW | 97508- AP3000X-WW | \$ 316.24 | 10% | <i>\$286.75</i> |
| EW ResponsPLS 4HROnsite AP302W-CAN | 97508- AP302W-CAN | \$ 384.00 | 10% | <i>\$348.19</i> |
| EW ResponsPLS 4HROnsite AP302W-EG | 97508- AP302W-EG | \$ 287.00 | 10% | <i>\$260.24</i> |
| EW ResponsPLS 4HROnsite AP302W-FCC | 97508- AP302W-FCC | \$ 384.00 | 10% | <i>\$348.19</i> |
| EW ResponsPLS 4HROnsite AP302W-WR | 97508- AP302W-WR | \$ 367.00 | 10% | <i>\$332.78</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EW ResponsePLS 4HROnsite AP305C-1-CAN | 97508-AP305C- 1-CAN | \$ 388.00 | 10% | \$351.82 |
| EW ResponsePLS 4HROnsite AP305C-1-EG | 97508-AP305C- 1-EG | \$ 388.00 | 10% | \$351.82 |
| EW ResponsePLS 4HROnsite AP305C-1-FCC | 97508-AP305C- 1-FCC | \$ 388.00 | 10% | \$351.82 |
| EW ResponsePLS 4HROnsite AP305C-1-IL | 97508-AP305C- 1-IL | \$ 388.00 | 10% | \$351.82 |
| EW ResponsePLS 4HROnsite AP305C-1-WR | 97508-AP305C- 1-WR | \$ 388.00 | 10% | \$351.82 |
| EW ResponsePLS 4HROnsite AP305C-CAN | 97508-AP305C- CAN | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305C-EG | 97508-AP305C- EG | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305C-FCC | 97508-AP305C- FCC | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305C-IL | 97508-AP305C- IL | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305C-WR | 97508-AP305C- WR | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305CX-CAN | 97508- AP305CX- CAN | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305CX-FCC | 97508- AP305CX- FCC | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305CX-IL | 97508- AP305CX-IL | \$ 418.00 | 10% | \$379.02 |
| EW ResponsePLS 4HROnsite AP305CX-WR | 97508- AP305CX-WR | \$ 418.00 | 10% | \$379.02 |
| EW ResponsPLS 4HROnsite AP310e-1-WR | 97508-AP310e- 1-WR | \$ 369.00 | 10% | \$334.59 |
| EW ResponsPLS 4HROnsite AP310e-CAN | 97508-AP310e- CAN | \$ 388.00 | 10% | \$351.82 |
| EW ResponsPLS 4HROnsite AP310e-FCC | 97508-AP310e- FCC | \$ 388.00 | 10% | \$351.82 |
| EW ResponsPLS 4HROnsite AP310e-IL | 97508-AP310e- IL | \$ 388.00 | 10% | \$351.82 |
| EW ResponsPLS 4HROnsite AP310e-WR | 97508-AP310e- WR | \$ 388.00 | 10% | \$351.82 |

| | | | | |
|--|------------------------|-----------|-----|-----------------|
| EW ResponsPLS 4HROnsite AP310i-1-WR | 97508-AP310i- 1-WR | \$ 369.00 | 10% | <i>\$334.59</i> |
| EW ResponsPLS 4HROnsite AP310i-CAN | 97508-AP310i- CAN | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW ResponsPLS 4HROnsite AP310i-FCC | 97508-AP310i- FCC | \$ 388.00 | 10% | <i>\$351.82</i> |
| EW ResponsPLS 4HROnsite AP310i-IL | 97508-AP310i- IL | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsPLS 4HROnsite AP310i-WR | 97508-AP310i- WR | \$ 387.00 | 10% | <i>\$350.91</i> |
| EW ResponsPLS 4HROnsite AP360e-CAN | 97508-AP360e- CAN | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS 4HROnsite AP360e-FCC | 97508-AP360e- FCC | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS 4HROnsite AP360e-IL | 97508-AP360e- IL | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS 4HROnsite AP360e-WR | 97508-AP360e- WR | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS 4HROnsite AP360i-CAN | 97508-AP360i- CAN | \$ 418.00 | 10% | <i>\$379.02</i> |
| EW ResponsPLS 4HROnsite AP360i-FCC | 97508-AP360i- FCC | \$ 418.00 | 10% | <i>\$379.02</i> |
| EW ResponsPLS 4HROnsite AP360i-WR | 97508-AP360i- WR | \$ 418.00 | 10% | <i>\$379.02</i> |
| EW ResponsPLS 4HROnsite AP4000-WW | 97508-AP4000- 1-WW | \$ 375.00 | 10% | <i>\$340.03</i> |
| EW ResponsPLS 4HROnsite AP4000-IL | 97508-AP4000- IL | \$ 375.00 | 10% | <i>\$340.03</i> |
| EW ResponsPLS 4HROnsite AP4000-WW | 97508-AP4000- WW | \$ 375.00 | 10% | <i>\$340.03</i> |
| EW ResponsePLS 4HROnsite AP410C-1-CAN | 97508-AP410C- 1-CAN | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS 4HROnsite AP410C-1-EG | 97508-AP410C- 1-EG | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS 4HROnsite AP410C-1-FCC | 97508-AP410C- 1-FCC | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS 4HROnsite AP410C-1-IL | 97508-AP410C- 1-IL | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS 4HROnsite AP410C-1-WR | 97508-AP410C- 1-WR | \$ 385.00 | 10% | <i>\$349.10</i> |

| | | | | |
|---|------------------------|-----------|-----|----------|
| EW ResponsePLS 4HROnsite AP410C-CAN | 97508-AP410C- CAN | \$ 414.00 | 10% | \$375.39 |
| EW ResponsePLS 4HROnsite AP410C-EG | 97508-AP410C- EG | \$ 414.00 | 10% | \$375.39 |
| EW ResponsePLS 4HROnsite AP410C-FCC | 97508-AP410C- FCC | \$ 414.00 | 10% | \$375.39 |
| EW ResponsePLS 4HROnsite AP410C-IL | 97508-AP410C- IL | \$ 414.00 | 10% | \$375.39 |
| EW ResponsePLS 4HROnsite AP410C-WR | 97508-AP410C- WR | \$ 414.00 | 10% | \$375.39 |
| EW ResponsPLS 4HROnsite AP410e-CAN | 97508-AP410e- CAN | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP410e-FCC | 97508-AP410e- FCC | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP410e-WR | 97508-AP410e- WR | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP410i-1-FCC | 97508-AP410i- 1-FCC | \$ 409.00 | 10% | \$370.86 |
| EW ResponsPLS 4HROnsite AP410i-1-WR | 97508-AP410i- 1-WR | \$ 409.00 | 10% | \$370.86 |
| EW ResponsPLS 4HROnsite AP410i-CAN | 97508-AP410i- CAN | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP410i-FCC | 97508-AP410i- FCC | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP410i-IL | 97508-AP410i- IL | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP410i-WR | 97508-AP410i- WR | \$ 428.00 | 10% | \$388.09 |
| EW ResponsePLS 4HROnsite AP460C-CAN | 97508-AP460C- CAN | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460C-EG | 97508-AP460C- EG | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460C-FCC | 97508-AP460C- FCC | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460C-IL | 97508-AP460C- IL | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460C-WR | 97508-AP460C- WR | \$ 451.00 | 10% | \$408.94 |
| EW ResponsPLS 4HROnsite AP460e-CAN | 97508-AP460e- CAN | \$ 450.00 | 10% | \$408.04 |
| EW ResponsPLS 4HROnsite AP460e-FCC | 97508-AP460e- FCC | \$ 450.00 | 10% | \$408.04 |

| | | | | |
|---|-----------------------------|-----------|-----|----------|
| EW ResponsPLS 4HROnsite AP460e-WR | 97508-AP460e- WR | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP460i-CAN | 97508-AP460i- CAN | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP460i-FCC | 97508-AP460i- FCC | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP460i-IL | 97508-AP460i- IL | \$ 428.00 | 10% | \$388.09 |
| EW ResponsPLS 4HROnsite AP460i-WR | 97508-AP460i- WR | \$ 428.00 | 10% | \$388.09 |
| EW ResponsePLS 4HROnsite AP460S12C-CAN | 97508- AP460S12C- CAN | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460S12C-FCC | 97508- AP460S12C- FCC | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460S12C-WR | 97508- AP460S12C- WR | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460S6C-CAN | 97508- AP460S6C- CAN | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460S6C-FCC | 97508- AP460S6C- FCC | \$ 451.00 | 10% | \$408.94 |
| EW ResponsePLS 4HROnsite AP460S6C-WR | 97508- AP460S6C- WR | \$ 451.00 | 10% | \$408.94 |
| EW ResponsPLS 4HROnsite AP5010-IL | 97508-AP5010- IL | \$ 423.00 | 10% | \$383.56 |
| EW ResponsPLS 4HROnsite AP5010-WW | 97508-AP5010- WW | \$ 423.00 | 10% | \$383.56 |
| EW ResponsPLS 4HROnsite AP5020-WW | 97508-AP5020- WW | \$ 441.14 | 6% | \$417.78 |
| EW ResponsPLS 4HROnsite AP5050D-WW | 97508- AP5050D-WW | \$ 651.00 | 10% | \$590.29 |
| EW ResponsPLS 4HROnsite AP5050U-WW | 97508- AP5050U-WW | \$ 552.00 | 10% | \$500.53 |
| EW ResponsPLS 4HROnsite AP505i-FCC | 97508-AP505i- FCC | \$ 433.00 | 10% | \$392.62 |
| EW ResponsPLS 4HROnsite AP505i-FCC-TAA | 97508-AP505i- FCC-TAA | \$ 433.00 | 10% | \$392.62 |

| | | | | |
|---|---------------------------|-----------|-----|-----------------|
| EW ResponsPLS 4HROnsite AP505i-WR | 97508-AP505i- WR | \$ 455.00 | 10% | <i>\$412.57</i> |
| EW ResponsePLS 4HROnsite AP510C-CAN | 97508-AP510C- CAN | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsePLS 4HROnsite AP510C-CE | 97508-AP510C- CE | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsePLS 4HROnsite AP510C-FCC | 97508-AP510C- FCC | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsePLS 4HROnsite AP510C-W | 97508-AP510C- W | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS 4HROnsite AP510C-WW | 97508-AP510C- WW | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW ResponsePLS 4HROnsite AP510CX-CAN | 97508- AP510CX- CAN | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsePLS 4HROnsite AP510CX-CE | 97508- AP510CX-CE | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsePLS 4HROnsite AP510CX-FCC | 97508- AP510CX- FCC | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsePLS 4HROnsite AP510CX-W | 97508- AP510CX-W | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS 4HROnsite AP510CX-WW | 97508- AP510CX-WW | \$ 512.00 | 10% | <i>\$464.26</i> |
| EW ResponsPLS 4HROnsite AP510e-FCC | 97508-AP510e- FCC | \$ 499.00 | 10% | <i>\$452.47</i> |
| EW ResponsPLS 4HROnsite AP510e-FCC-TAA | 97508-AP510e- FCC-TAA | \$ 499.00 | 10% | <i>\$452.47</i> |
| EW ResponsPLS 4HROnsite AP510e-WR | 97508-AP510e- WR | \$ 475.00 | 10% | <i>\$430.71</i> |
| EW ResponsPLS 4HROnsite AP510i-1-FCC | 97508-AP510i- 1-FCC | \$ 451.00 | 10% | <i>\$408.94</i> |
| EW ResponsPLS 4HROnsite AP510i-1-WR | 97508-AP510i- 1-WR | \$ 451.00 | 10% | <i>\$408.94</i> |
| EW ResponsPLS 4HROnsite AP510i-FCC | 97508-AP510i- FCC | \$ 473.00 | 10% | <i>\$428.89</i> |
| EW ResponsPLS 4HROnsite AP510i-FCC-TAA | 97508-AP510i- FCC-TAA | \$ 473.00 | 10% | <i>\$428.89</i> |
| EW ResponsPLS 4HROnsite AP510i-WR | 97508-AP510i- WR | \$ 473.00 | 10% | <i>\$428.89</i> |

| | | | | |
|---------------------------------------|----------------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite AP560h-FCC | 97508-AP560h- FCC | \$ 736.00 | 10% | <i>\$667.37</i> |
| EW ResponsPLS 4HROnsite AP560h-WR | 97508-AP560h- WR | \$ 736.00 | 10% | <i>\$667.37</i> |
| EW ResponsPLS 4HROnsite AP560i-FCC | 97508-AP560i- FCC | \$ 618.00 | 10% | <i>\$560.37</i> |
| EW ResponsPLS 4HROnsite AP560i-WR | 97508-AP560i- WR | \$ 589.00 | 10% | <i>\$534.08</i> |
| EW ResponsPLS 4HROnsite AP560m-FCC | 97508-AP560m- FCC | \$ 618.00 | 10% | <i>\$560.37</i> |
| EW ResponsPLS 4HROnsite AP560t-FCC | 97508-AP560t- FCC | \$ 736.00 | 10% | <i>\$667.37</i> |
| EW ResponsPLS 4HROnsite AP560u-FCC | 97508-AP560u- FCC | \$ 575.00 | 10% | <i>\$521.38</i> |
| EW ResponsPLS 4HROnsite E2122 | 97508-E2122 | \$ 8,516.00 | 10% | <i>\$7,721.88</i> |
| EW ResponsPLS 4HROnsite E2122-1 | 97508-E2122-1 | \$ 8,071.00 | 10% | <i>\$7,318.38</i> |
| EW ResponsPLS 4HROnsite E3120-1 | 97508-E3120-1 | \$ 12,519.00 | 10% | <i>\$11,351.60</i> |
| EW ResponsPLS 4HROnsite E3125 | 97508-E3125 | \$ 13,828.00 | 10% | <i>\$12,538.54</i> |
| EW ResponsPLS 4HROnsite- H30131 | 97508-H30131 | \$ 3,240.00 | 10% | <i>\$2,937.87</i> |
| EW ResponsPLS 4HROnsite- H30132 | 97508-H30132 | \$ 3,178.00 | 10% | <i>\$2,881.65</i> |
| EW ResponsPLS 4HROnsite- H30133 | 97508-H30133 | \$ 6,485.00 | 10% | <i>\$5,880.27</i> |
| EW ResponsPLS 4HROnsite- H30134 | 97508-H30134 | \$ 7,907.00 | 10% | <i>\$7,169.67</i> |
| EW ResponsPLS 4HROnsite- H30135 | 97508-H30135 | \$ 6,611.00 | 10% | <i>\$5,994.52</i> |
| EW ResponsPLS 4HROnsite- H30136 | 97508-H30136 | \$ 7,907.00 | 10% | <i>\$7,169.67</i> |
| EW ResponsPLS 4HROnsite- H30184 | 97508-H30184 | \$ 1,295.00 | 10% | <i>\$1,174.24</i> |
| EW ResponsPLS 4HROnsite- H30185 | 97508-H30185 | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW ResponsPLS 4HROnsite- H30186 | 97508-H30186 | \$ 1,472.00 | 10% | <i>\$1,334.74</i> |
| EW ResponsPLS 4HROnsite- H30187 | 97508-H30187 | \$ 1,410.00 | 10% | <i>\$1,278.52</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-H30188 | 97508-H30188 | \$ 1,472.00 | 10% | <i>\$1,334.74</i> |
| EW ResponsPLS 4HROnsite-H30189 | 97508-H30189 | \$ 1,472.00 | 10% | <i>\$1,334.74</i> |
| EW ResponsPLS 4HROnsite-H30190 | 97508-H30190 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30214 | 97508-H30214 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS 4HROnsite-H30215 | 97508-H30215 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS 4HROnsite-H30216 | 97508-H30216 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30217 | 97508-H30217 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30218 | 97508-H30218 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30219 | 97508-H30219 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30220 | 97508-H30220 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30221 | 97508-H30221 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30222 | 97508-H30222 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30223 | 97508-H30223 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30224 | 97508-H30224 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30225 | 97508-H30225 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30226 | 97508-H30226 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30227 | 97508-H30227 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30228 | 97508-H30228 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30229 | 97508-H30229 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30267 | 97508-H30267 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |
| EW ResponsPLS 4HROnsite-H30268 | 97508-H30268 | \$ 1,827.00 | 10% | <i>\$1,656.63</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite-H30269 | 97508-H30269 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30270 | 97508-H30270 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30271 | 97508-H30271 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30272 | 97508-H30272 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30273 | 97508-H30273 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-H30274 | 97508-H30274 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-H30275 | 97508-H30275 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30276 | 97508-H30276 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30277 | 97508-H30277 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-H30278 | 97508-H30278 | \$ 2,548.00 | 10% | <i>\$2,310.40</i> |
| EW ResponsPLS 4HROnsite-H30279 | 97508-H30279 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-H30280 | 97508-H30280 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-H30281 | 97508-H30281 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-H30282 | 97508-H30282 | \$ 2,437.00 | 10% | <i>\$2,209.75</i> |
| EW ResponsPLS 4HROnsite-H30283 | 97508-H30283 | \$ 1,936.00 | 10% | <i>\$1,755.47</i> |
| EW ResponsPLS 4HROnsite-H30284 | 97508-H30284 | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS 4HROnsite-H30296 | 97508-H30296 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS 4HROnsite-H30297 | 97508-H30297 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS 4HROnsite-H30298 | 97508-H30298 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS 4HROnsite-H30299 | 97508-H30299 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS 4HROnsite-H30381 | 97508-H30381 | \$ 2,874.00 | 10% | <i>\$2,606.00</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|------------|
| EW ResponsPLS 4HROnsite-H30384 | 97508-H30384 | \$ 2,729.00 | 10% | \$2,474.52 |
| EW ResponsPLS 4HROnsite-H30391 | 97508-H30391 | \$ 1,824.00 | 10% | \$1,653.91 |
| EW ResponsPLS 4HROnsite-H30392 | 97508-H30392 | \$ 1,824.00 | 10% | \$1,653.91 |
| EW ResponsPLS 4HROnsite-H30393 | 97508-H30393 | \$ 1,043.00 | 10% | \$945.74 |
| EW ResponsPLS 4HROnsite-H30394 | 97508-H30394 | \$ 3,128.00 | 10% | \$2,836.31 |
| EW ResponsPLS 4HROnsite-H30395 | 97508-H30395 | \$ 3,647.00 | 10% | \$3,306.92 |
| EW ResponsPLS 4HROnsite-H30396 | 97508-H30396 | \$ 3,353.00 | 10% | \$3,040.33 |
| EW ResponsPLS 4HROnsite-H30397 | 97508-H30397 | \$ 3,903.00 | 10% | \$3,539.05 |
| EW ResponsPLS 4HROnsite-H30398 | 97508-H30398 | \$ 1,063.00 | 10% | \$963.88 |
| EW ResponsPLS 4HROnsite-H30400 | 97508-H30400 | \$ 780.00 | 10% | \$707.27 |
| EW ResponsPLS 4HROnsite-H30401 | 97508-H30401 | \$ 918.00 | 10% | \$832.40 |
| EW ResponsPLS 4HROnsite-H30402 | 97508-H30402 | \$ 946.00 | 10% | \$857.79 |
| EW ResponsPLS 4HROnsite-H30403 | 97508-H30403 | \$ 1,203.00 | 10% | \$1,090.82 |
| EW ResponsPLS 4HROnsite-H30480 | 97508-H30480 | \$ 3,018.00 | 10% | \$2,736.57 |
| EW ResponsPLS 4HROnsite-H30495 | 97508-H30495 | \$ 4,212.00 | 10% | \$3,819.23 |
| EW ResponsPLS 4HROnsite-H30496 | 97508-H30496 | \$ 4,131.00 | 10% | \$3,745.78 |
| EW ResponsPLS 4HROnsite-H30497 | 97508-H30497 | \$ 5,129.00 | 10% | \$4,650.72 |
| EW ResponsPLS 4HROnsite-H30498 | 97508-H30498 | \$ 5,032.00 | 10% | \$4,562.77 |
| EW ResponsPLS 4HROnsite-H30499 | 97508-H30499 | \$ 1,431.00 | 10% | \$1,297.56 |
| EW ResponsPLS 4HROnsite-H30501 | 97508-H30501 | \$ 5,032.00 | 10% | \$4,562.77 |
| EW ResponsPLS 4HROnsite-H30502 | 97508-H30502 | \$ 6,607.00 | 10% | \$5,990.90 |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite-H30503 | 97508-H30503 | \$ 1,431.00 | 10% | <i>\$1,297.56</i> |
| EW ResponsPLS 4HROnsite-H30505 | 97508-H30505 | \$ 7,436.00 | 10% | <i>\$6,742.59</i> |
| EW ResponsPLS 4HROnsite-H30506 | 97508-H30506 | \$ 9,348.00 | 10% | <i>\$8,476.30</i> |
| EW ResponsPLS 4HROnsite-H30509 | 97508-H30509 | \$ 6,607.00 | 10% | <i>\$5,990.90</i> |
| EW ResponsPLS 4HROnsite-H30510 | 97508-H30510 | \$ 7,436.00 | 10% | <i>\$6,742.59</i> |
| EW ResponsPLS 4HROnsite-H30511 | 97508-H30511 | \$ 9,348.00 | 10% | <i>\$8,476.30</i> |
| EW ResponsPLS 4HROnsite-H30512 | 97508-H30512 | \$ 1,431.00 | 10% | <i>\$1,297.56</i> |
| EW ResponsPLS 4HROnsite-H30513 | 97508-H30513 | \$ 2,119.00 | 10% | <i>\$1,921.40</i> |
| EW ResponsPLS 4HROnsite-H30525 | 97508-H30525 | \$ 7,676.00 | 10% | <i>\$6,960.21</i> |
| EW ResponsPLS 4HROnsite-H30526 | 97508-H30526 | \$ 5,758.00 | 10% | <i>\$5,221.07</i> |
| EW ResponsPLS 4HROnsite-H30528 | 97508-H30528 | \$ 8,839.00 | 10% | <i>\$8,014.76</i> |
| EW ResponsPLS 4HROnsite-H30531 | 97508-H30531 | \$ 12,404.00 | 10% | <i>\$11,247.33</i> |
| EW ResponsPLS 4HROnsite-H30532 | 97508-H30532 | \$ 12,404.00 | 10% | <i>\$11,247.33</i> |
| EW ResponsPLS 4HROnsite-H30534 | 97508-H30534 | \$ 12,645.00 | 10% | <i>\$11,465.85</i> |
| EW ResponsPLS 4HROnsite-H30535 | 97508-H30535 | \$ 13,446.00 | 10% | <i>\$12,192.16</i> |
| EW ResponsPLS 4HROnsite-H30536 | 97508-H30536 | \$ 12,404.00 | 10% | <i>\$11,247.33</i> |
| EW ResponsPLS 4HROnsite-H30537 | 97508-H30537 | \$ 13,446.00 | 10% | <i>\$12,192.16</i> |
| EW ResponsPLS 4HROnsite-H30538 | 97508-H30538 | \$ 7,676.00 | 10% | <i>\$6,960.21</i> |
| EW ResponsPLS 4HROnsite-H30539 | 97508-H30539 | \$ 14,359.00 | 10% | <i>\$13,020.02</i> |
| EW ResponsPLS 4HROnsite-H30540 | 97508-H30540 | \$ 14,827.00 | 10% | <i>\$13,444.38</i> |
| EW ResponsPLS 4HROnsite-H30543 | 97508-H30543 | \$ 1,404.00 | 10% | <i>\$1,273.08</i> |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite-H30544 | 97508-H30544 | \$ 2,176.00 | 10% | <i>\$1,973.09</i> |
| EW ResponsPLS 4HROnsite-H30548 | 97508-H30548 | \$ 1,404.00 | 10% | <i>\$1,273.08</i> |
| EW ResponsPLS 4HROnsite-H30549 | 97508-H30549 | \$ 2,079.00 | 10% | <i>\$1,885.13</i> |
| EW ResponsPLS 4HROnsite-H30550 | 97508-H30550 | \$ 2,079.00 | 10% | <i>\$1,885.13</i> |
| EW ResponsPLS 4HROnsite-H30552 | 97508-H30552 | \$ 1,404.00 | 10% | <i>\$1,273.08</i> |
| EW ResponsPLS 4HROnsite-H30553 | 97508-H30553 | \$ 1,982.00 | 10% | <i>\$1,797.18</i> |
| EW ResponsPLS 4HROnsite-H30569 | 97508-H30569 | \$ 6,485.00 | 10% | <i>\$5,880.27</i> |
| EW ResponsPLS 4HROnsite-H30570 | 97508-H30570 | \$ 7,568.00 | 10% | <i>\$6,862.28</i> |
| EW ResponsPLS 4HROnsite-H30571 | 97508-H30571 | \$ 7,568.00 | 10% | <i>\$6,862.28</i> |
| EW ResponsPLS 4HROnsite-H30573 | 97508-H30573 | \$ 6,485.00 | 10% | <i>\$5,880.27</i> |
| EW ResponsPLS 4HROnsite-H30574 | 97508-H30574 | \$ 7,070.00 | 10% | <i>\$6,410.72</i> |
| EW ResponsPLS 4HROnsite-H30575 | 97508-H30575 | \$ 4,838.00 | 10% | <i>\$4,386.86</i> |
| EW ResponsPLS 4HROnsite-H30576 | 97508-H30576 | \$ 6,485.00 | 10% | <i>\$5,880.27</i> |
| EW ResponsPLS 4HROnsite-H30577 | 97508-H30577 | \$ 7,425.00 | 10% | <i>\$6,732.62</i> |
| EW ResponsPLS 4HROnsite-H30578 | 97508-H30578 | \$ 7,425.00 | 10% | <i>\$6,732.62</i> |
| EW ResponsPLS 4HROnsite-H30587 | 97508-H30587 | \$ 5,870.00 | 10% | <i>\$5,322.62</i> |
| EW ResponsPLS 4HROnsite-H30588 | 97508-H30588 | \$ 4,191.00 | 10% | <i>\$3,800.19</i> |
| EW ResponsPLS 4HROnsite-H30589 | 97508-H30589 | \$ 6,267.00 | 10% | <i>\$5,682.60</i> |
| EW ResponsPLS 4HROnsite-H30632 | 97508-H30632 | \$ 476.00 | 10% | <i>\$431.61</i> |
| EW ResponsPLS 4HROnsite-H30633 | 97508-H30633 | \$ 476.00 | 10% | <i>\$431.61</i> |
| EW ResponsPLS 4HROnsite-H30643 | 97508-H30643 | \$ 11,680.00 | 10% | <i>\$10,590.84</i> |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite-H30706 | 97508-H30706 | \$ 9,012.00 | 10% | <i>\$8,171.63</i> |
| EW ResponsPLS 4HROnsite-H30707 | 97508-H30707 | \$ 5,758.00 | 10% | <i>\$5,221.07</i> |
| EW ResponsPLS 4HROnsite-H30724 | 97508-H30724 | \$ 906.00 | 10% | <i>\$821.52</i> |
| EW ResponsPLS 4HROnsite-H30725 | 97508-H30725 | \$ 3,178.00 | 10% | <i>\$2,881.65</i> |
| EW ResponsPLS 4HROnsite-H30726 | 97508-H30726 | \$ 13,707.00 | 10% | <i>\$12,428.82</i> |
| EW ResponsPLS 4HROnsite-H30727 | 97508-H30727 | \$ 14,547.00 | 10% | <i>\$13,190.49</i> |
| EW ResponsPLS 4HROnsite-H30730 | 97508-H30730 | \$ 449.00 | 10% | <i>\$407.13</i> |
| EW ResponsPLS 4HROnsite-H30731 | 97508-H30731 | \$ 449.00 | 10% | <i>\$407.13</i> |
| EW ResponsPLS 4HROnsite-H30733 | 97508-H30733 | \$ 12,886.00 | 10% | <i>\$11,684.38</i> |
| EW ResponsPLS 4HROnsite-H30734 | 97508-H30734 | \$ 9,926.00 | 10% | <i>\$9,000.40</i> |
| EW ResponsPLS 4HROnsite-H30735 | 97508-H30735 | \$ 11,510.00 | 10% | <i>\$10,436.69</i> |
| EW ResponsPLS 4HROnsite-H30736 | 97508-H30736 | \$ 2,149.00 | 10% | <i>\$1,948.61</i> |
| EW ResponsPLS 4HROnsite-H30738 | 97508-H30738 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS 4HROnsite H30787 | 97508-H30787 | \$ 340.00 | 10% | <i>\$308.30</i> |
| EW ResponsPLS 4HROnsite H30847 | 97508-H30847 | \$ 345.00 | 10% | <i>\$312.83</i> |
| EW ResponsPLS 4HROnsite H30852 | 97508-H30852 | \$ 345.00 | 10% | <i>\$312.83</i> |
| EW ResponsPLS 4HROnsite H30857 | 97508-H30857 | \$ 415.00 | 10% | <i>\$376.30</i> |
| EW ResponsPLS 4HROnsite H31337 | 97508-H31337 | \$ 14,549.00 | 10% | <i>\$13,192.31</i> |
| EW ResponsPLS 4HROnsite H31338 | 97508-H31338 | \$ 14,549.00 | 10% | <i>\$13,192.31</i> |
| EW ResponsPLS 4HROnsite H31341 | 97508-H31341 | \$ 7,852.00 | 10% | <i>\$7,119.80</i> |
| EW ResponsPLS 4HROnsite H31342 | 97508-H31342 | \$ 2,232.00 | 10% | <i>\$2,023.87</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H31343 | 97508-H31343 | \$ 3,093.00 | 10% | <i>\$2,804.58</i> |
| EW ResponsPLS 4HROnsite H31344 | 97508-H31344 | \$ 3,093.00 | 10% | <i>\$2,804.58</i> |
| EW ResponsPLS 4HROnsite H31345 | 97508-H31345 | \$ 3,093.00 | 10% | <i>\$2,804.58</i> |
| EW ResponsPLS 4HROnsite H31346 | 97508-H31346 | \$ 3,093.00 | 10% | <i>\$2,804.58</i> |
| EW ResponsPLS 4HROnsite H31362 | 97508-H31362 | \$ 38,498.00 | 10% | <i>\$34,908.06</i> |
| EW ResponsPLS 4HROnsite H31363 | 97508-H31363 | \$ 38,498.00 | 10% | <i>\$34,908.06</i> |
| EW ResponsPLS 4HROnsite H31364 | 97508-H31364 | \$ 14,260.00 | 10% | <i>\$12,930.26</i> |
| EW ResponsPLS 4HROnsite H31365 | 97508-H31365 | \$ 14,260.00 | 10% | <i>\$12,930.26</i> |
| EW ResponsPLS 4HROnsite H31366 | 97508-H31366 | \$ 19,749.00 | 10% | <i>\$17,907.41</i> |
| EW ResponsPLS 4HROnsite H31367 | 97508-H31367 | \$ 19,749.00 | 10% | <i>\$17,907.41</i> |
| EW ResponsPLS 4HROnsite H32010 | 97508-H32010 | \$ 1,870.00 | 10% | <i>\$1,695.62</i> |
| EW ResponsPLS 4HROnsite H32011 | 97508-H32011 | \$ 1,870.00 | 10% | <i>\$1,695.62</i> |
| EW ResponsPLS 4HROnsite H32012 | 97508-H32012 | \$ 5,006.00 | 10% | <i>\$4,539.19</i> |
| EW ResponsPLS 4HROnsite H32013 | 97508-H32013 | \$ 5,006.00 | 10% | <i>\$4,539.19</i> |
| EW ResponsPLS 4HROnsite H32014 | 97508-H32014 | \$ 5,006.00 | 10% | <i>\$4,539.19</i> |
| EW ResponsPLS 4HROnsite H32015 | 97508-H32015 | \$ 5,006.00 | 10% | <i>\$4,539.19</i> |
| EW ResponsPLS 4HROnsite H32016 | 97508-H32016 | \$ 4,539.00 | 10% | <i>\$4,115.74</i> |
| EW ResponsPLS 4HROnsite H32017 | 97508-H32017 | \$ 4,539.00 | 10% | <i>\$4,115.74</i> |
| EW ResponsPLS 4HROnsite H32018 | 97508-H32018 | \$ 4,539.00 | 10% | <i>\$4,115.74</i> |
| EW ResponsPLS 4HROnsite H32019 | 97508-H32019 | \$ 4,539.00 | 10% | <i>\$4,115.74</i> |
| EW ResponsPLS 4HROnsite H32020 | 97508-H32020 | \$ 39,509.00 | 10% | <i>\$35,824.79</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|-------------|
| EW ResponsPLS 4HROnsite H32021 | 97508-H32021 | \$ 39,509.00 | 10% | \$35,824.79 |
| EW ResponsPLS 4HROnsite H32022 | 97508-H32022 | \$ 39,509.00 | 10% | \$35,824.79 |
| EW ResponsPLS 4HROnsite H32023 | 97508-H32023 | \$ 39,509.00 | 10% | \$35,824.79 |
| EW ResponsPLS 4HROnsite H32028 | 97508-H32028 | \$ 74,318.00 | 10% | \$67,387.85 |
| EW ResponsPLS 4HROnsite H32029 | 97508-H32029 | \$ 74,318.00 | 10% | \$67,387.85 |
| EW ResponsPLS 4HROnsite H32030 | 97508-H32030 | \$ 77,938.00 | 10% | \$70,670.28 |
| EW ResponsPLS 4HROnsite H32031 | 97508-H32031 | \$ 77,938.00 | 10% | \$70,670.28 |
| EW ResponsPLS 4HROnsite H32032 | 97508-H32032 | \$ 77,938.00 | 10% | \$70,670.28 |
| EW ResponsPLS 4HROnsite H32033 | 97508-H32033 | \$ 77,938.00 | 10% | \$70,670.28 |
| EW ResponsPLS 4HROnsite H32038 | 97508-H32038 | \$ 14,549.00 | 10% | \$13,192.31 |
| EW ResponsPLS 4HROnsite H32039 | 97508-H32039 | \$ 14,549.00 | 10% | \$13,192.31 |
| EW ResponsPLS 4HROnsite H32040 | 97508-H32040 | \$ 14,549.00 | 10% | \$13,192.31 |
| EW ResponsPLS 4HROnsite H32041 | 97508-H32041 | \$ 14,549.00 | 10% | \$13,192.31 |
| EW ResponsPLS 4HROnsite H32046 | 97508-H32046 | \$ 20,148.00 | 10% | \$18,269.20 |
| EW ResponsPLS 4HROnsite H32047 | 97508-H32047 | \$ 20,148.00 | 10% | \$18,269.20 |
| EW ResponsPLS 4HROnsite H32048 | 97508-H32048 | \$ 20,148.00 | 10% | \$18,269.20 |
| EW ResponsPLS 4HROnsite H32049 | 97508-H32049 | \$ 20,148.00 | 10% | \$18,269.20 |
| EW ResponsPLS 4HROnsite H32054 | 97508-H32054 | \$ 14,549.00 | 10% | \$13,192.31 |
| EW ResponsPLS 4HROnsite H32055 | 97508-H32055 | \$ 20,148.00 | 10% | \$18,269.20 |
| EW ResponsPLS 4HROnsite H32056 | 97508-H32056 | \$ 5,761.00 | 10% | \$5,223.79 |
| EW ResponsPLS 4HROnsite H32057 | 97508-H32057 | \$ 5,935.00 | 10% | \$5,381.56 |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H32058 | 97508-H32058 | \$ 5,935.00 | 10% | <i>\$5,381.56</i> |
| EW ResponsPLS 4HROnsite H32059 | 97508-H32059 | \$ 5,935.00 | 10% | <i>\$5,381.56</i> |
| EW ResponsPLS 4HROnsite H32060 | 97508-H32060 | \$ 6,829.00 | 10% | <i>\$6,192.20</i> |
| EW ResponsPLS 4HROnsite H32061 | 97508-H32061 | \$ 7,170.00 | 10% | <i>\$6,501.40</i> |
| EW ResponsPLS 4HROnsite H32062 | 97508-H32062 | \$ 6,894.00 | 10% | <i>\$6,251.13</i> |
| EW ResponsPLS 4HROnsite H32063 | 97508-H32063 | \$ 6,837.00 | 10% | <i>\$6,199.45</i> |
| EW ResponsPLS 4HROnsite H32064 | 97508-H32064 | \$ 6,894.00 | 10% | <i>\$6,251.13</i> |
| EW ResponsPLS 4HROnsite H32065 | 97508-H32065 | \$ 6,354.00 | 10% | <i>\$5,761.49</i> |
| EW ResponsPLS 4HROnsite H32066 | 97508-H32066 | \$ 6,354.00 | 10% | <i>\$5,761.49</i> |
| EW ResponsPLS 4HROnsite H32067 | 97508-H32067 | \$ 6,354.00 | 10% | <i>\$5,761.49</i> |
| EW ResponsPLS 4HROnsite H32068 | 97508-H32068 | \$ 6,354.00 | 10% | <i>\$5,761.49</i> |
| EW ResponsPLS 4HROnsite H32069 | 97508-H32069 | \$ 7,541.00 | 10% | <i>\$6,837.80</i> |
| EW ResponsPLS 4HROnsite H32070 | 97508-H32070 | \$ 7,541.00 | 10% | <i>\$6,837.80</i> |
| EW ResponsPLS 4HROnsite H32071 | 97508-H32071 | \$ 7,541.00 | 10% | <i>\$6,837.80</i> |
| EW ResponsPLS 4HROnsite H32072 | 97508-H32072 | \$ 7,541.00 | 10% | <i>\$6,837.80</i> |
| EW ResponsPLS 4HROnsite H32073 | 97508-H32073 | \$ 47,956.00 | 10% | <i>\$43,484.10</i> |
| EW ResponsPLS 4HROnsite H32074 | 97508-H32074 | \$ 47,956.00 | 10% | <i>\$43,484.10</i> |
| EW ResponsPLS 4HROnsite H32075 | 97508-H32075 | \$ 65,217.00 | 10% | <i>\$59,135.51</i> |
| EW ResponsPLS 4HROnsite H32076 | 97508-H32076 | \$ 65,217.00 | 10% | <i>\$59,135.51</i> |
| EW ResponsPLS 4HROnsite H32101 | 97508-H32101 | \$ 3,511.00 | 10% | <i>\$3,183.60</i> |
| EW ResponsPLS 4HROnsite H32102 | 97508-H32102 | \$ 3,511.00 | 10% | <i>\$3,183.60</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H32103 | 97508-H32103 | \$ 3,511.00 | 10% | <i>\$3,183.60</i> |
| EW ResponsPLS 4HROnsite H32104 | 97508-H32104 | \$ 3,511.00 | 10% | <i>\$3,183.60</i> |
| EW ResponsPLS 4HROnsite H32105 | 97508-H32105 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |
| EW ResponsPLS 4HROnsite H32106 | 97508-H32106 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |
| EW ResponsPLS 4HROnsite H32107 | 97508-H32107 | \$ 12,249.00 | 10% | <i>\$11,106.78</i> |
| EW ResponsPLS 4HROnsite H32108 | 97508-H32108 | \$ 12,249.00 | 10% | <i>\$11,106.78</i> |
| EW ResponsPLS 4HROnsite H32109 | 97508-H32109 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |
| EW ResponsPLS 4HROnsite H32110 | 97508-H32110 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |
| EW ResponsPLS 4HROnsite H32111 | 97508-H32111 | \$ 3,510.00 | 10% | <i>\$3,182.69</i> |
| EW ResponsPLS 4HROnsite H32112 | 97508-H32112 | \$ 3,510.00 | 10% | <i>\$3,182.69</i> |
| EW ResponsPLS 4HROnsite H32113 | 97508-H32113 | \$ 3,511.00 | 10% | <i>\$3,183.60</i> |
| EW ResponsPLS 4HROnsite H32114 | 97508-H32114 | \$ 3,511.00 | 10% | <i>\$3,183.60</i> |
| EW ResponsPLS 4HROnsite H32115 | 97508-H32115 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |
| EW ResponsPLS 4HROnsite H32116 | 97508-H32116 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |
| EW ResponsPLS 4HROnsite H32117 | 97508-H32117 | \$ 3,387.00 | 10% | <i>\$3,071.16</i> |
| EW ResponsPLS 4HROnsite H32118 | 97508-H32118 | \$ 3,388.00 | 10% | <i>\$3,072.07</i> |
| EW ResponsPLS 4HROnsite H32119 | 97508-H32119 | \$ 3,388.00 | 10% | <i>\$3,072.07</i> |
| EW ResponsPLS 4HROnsite H32120 | 97508-H32120 | \$ 3,388.00 | 10% | <i>\$3,072.07</i> |
| EW ResponsPLS 4HROnsite H32121 | 97508-H32121 | \$ 12,249.00 | 10% | <i>\$11,106.78</i> |
| EW ResponsPLS 4HROnsite H32122 | 97508-H32122 | \$ 12,249.00 | 10% | <i>\$11,106.78</i> |
| EW ResponsPLS 4HROnsite H32123 | 97508-H32123 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H32124 | 97508-H32124 | \$ 5,490.00 | 10% | <i>\$4,978.06</i> |
| EW ResponsPLS 4HROnsite H32125 | 97508-H32125 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32126 | 97508-H32126 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32127 | 97508-H32127 | \$ 6,032.00 | 10% | <i>\$5,469.52</i> |
| EW ResponsPLS 4HROnsite H32128 | 97508-H32128 | \$ 6,032.00 | 10% | <i>\$5,469.52</i> |
| EW ResponsPLS 4HROnsite H32129 | 97508-H32129 | \$ 6,032.00 | 10% | <i>\$5,469.52</i> |
| EW ResponsPLS 4HROnsite H32130 | 97508-H32130 | \$ 6,032.00 | 10% | <i>\$5,469.52</i> |
| EW ResponsPLS 4HROnsite H32131 | 97508-H32131 | \$ 6,032.00 | 10% | <i>\$5,469.52</i> |
| EW ResponsPLS 4HROnsite H32132 | 97508-H32132 | \$ 6,032.00 | 10% | <i>\$5,469.52</i> |
| EW ResponsPLS 4HROnsite H32133 | 97508-H32133 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32134 | 97508-H32134 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32135 | 97508-H32135 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32136 | 97508-H32136 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32137 | 97508-H32137 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32138 | 97508-H32138 | \$ 5,338.00 | 10% | <i>\$4,840.23</i> |
| EW ResponsPLS 4HROnsite H32139 | 97508-H32139 | \$ 20,352.00 | 10% | <i>\$18,454.18</i> |
| EW ResponsPLS 4HROnsite H32140 | 97508-H32140 | \$ 20,352.00 | 10% | <i>\$18,454.18</i> |
| EW ResponsPLS 4HROnsite H32141 | 97508-H32141 | \$ 24,124.00 | 10% | <i>\$21,874.44</i> |
| EW ResponsPLS 4HROnsite H32142 | 97508-H32142 | \$ 24,124.00 | 10% | <i>\$21,874.44</i> |
| EW ResponsPLS 4HROnsite H32146 | 97508-H32146 | \$ 3,326.00 | 10% | <i>\$3,015.85</i> |
| EW ResponsPLS 4HROnsite H32147 | 97508-H32147 | \$ 3,326.00 | 10% | <i>\$3,015.85</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H32148 | 97508-H32148 | \$ 5,201.00 | 10% | <i>\$4,716.01</i> |
| EW ResponsPLS 4HROnsite H32149 | 97508-H32149 | \$ 5,201.00 | 10% | <i>\$4,716.01</i> |
| EW ResponsPLS 4HROnsite H32150 | 97508-H32150 | \$ 3,326.00 | 10% | <i>\$3,015.85</i> |
| EW ResponsPLS 4HROnsite H32169 | 97508-H32169 | \$ 3,553.00 | 10% | <i>\$3,221.68</i> |
| EW ResponsPLS 4HROnsite H32170 | 97508-H32170 | \$ 3,553.00 | 10% | <i>\$3,221.68</i> |
| EW ResponsPLS 4HROnsite H32171 | 97508-H32171 | \$ 3,428.00 | 10% | <i>\$3,108.34</i> |
| EW ResponsPLS 4HROnsite H32172 | 97508-H32172 | \$ 3,428.00 | 10% | <i>\$3,108.34</i> |
| EW ResponsPLS 4HROnsite H32173 | 97508-H32173 | \$ 6,560.00 | 10% | <i>\$5,948.28</i> |
| EW ResponsPLS 4HROnsite H32174 | 97508-H32174 | \$ 6,560.00 | 10% | <i>\$5,948.28</i> |
| EW ResponsPLS 4HROnsite H32175 | 97508-H32175 | \$ 5,805.00 | 10% | <i>\$5,263.68</i> |
| EW ResponsPLS 4HROnsite H32176 | 97508-H32176 | \$ 5,805.00 | 10% | <i>\$5,263.68</i> |
| EW ResponsPLS 4HROnsite H32177 | 97508-H32177 | \$ 22,798.00 | 10% | <i>\$20,672.09</i> |
| EW ResponsPLS 4HROnsite H32178 | 97508-H32178 | \$ 27,023.00 | 10% | <i>\$24,503.11</i> |
| EW ResponsPLS 4HROnsite H34008 | 97508-H34008 | \$ 1,271.00 | 10% | <i>\$1,152.48</i> |
| EW ResponsPLS 4HROnsite H34009 | 97508-H34009 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW ResponsPLS 4HROnsite H34010 | 97508-H34010 | \$ 1,209.00 | 10% | <i>\$1,096.26</i> |
| EW ResponsPLS 4HROnsite H34011 | 97508-H34011 | \$ 1,381.00 | 10% | <i>\$1,252.22</i> |
| EW ResponsPLS 4HROnsite H34012 | 97508-H34012 | \$ 1,532.00 | 10% | <i>\$1,389.14</i> |
| EW ResponsPLS 4HROnsite H34013 | 97508-H34013 | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsPLS 4HROnsite H34014 | 97508-H34014 | \$ 1,405.00 | 10% | <i>\$1,273.98</i> |
| EW ResponsPLS 4HROnsite H34015 | 97508-H34015 | \$ 1,227.00 | 10% | <i>\$1,112.58</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite H34016 | 97508-H34016 | \$ 1,428.00 | 10% | <i>\$1,294.84</i> |
| EW ResponsPLS 4HROnsite H34017 | 97508-H34017 | \$ 1,593.00 | 10% | <i>\$1,444.45</i> |
| EW ResponsPLS 4HROnsite H34018 | 97508-H34018 | \$ 1,347.00 | 10% | <i>\$1,221.39</i> |
| EW ResponsPLS 4HROnsite H34019 | 97508-H34019 | \$ 1,347.00 | 10% | <i>\$1,221.39</i> |
| EW ResponsPLS 4HROnsite H34020 | 97508-H34020 | \$ 1,347.00 | 10% | <i>\$1,221.39</i> |
| EW ResponsPLS 4HROnsite H34021 | 97508-H34021 | \$ 1,347.00 | 10% | <i>\$1,221.39</i> |
| EW ResponsPLS 4HROnsite H34048 | 97508-H34048 | \$ 1,851.00 | 10% | <i>\$1,678.39</i> |
| EW ResponsPLS 4HROnsite H34049 | 97508-H34049 | \$ 1,851.00 | 10% | <i>\$1,678.39</i> |
| EW ResponsPLS 4HROnsite H34050 | 97508-H34050 | \$ 1,682.00 | 10% | <i>\$1,525.15</i> |
| EW ResponsPLS 4HROnsite H34051 | 97508-H34051 | \$ 1,682.00 | 10% | <i>\$1,525.15</i> |
| EW ResponsPLS 4HROnsite H34052 | 97508-H34052 | \$ 1,971.00 | 10% | <i>\$1,787.20</i> |
| EW ResponsPLS 4HROnsite H34053 | 97508-H34053 | \$ 1,971.00 | 10% | <i>\$1,787.20</i> |
| EW ResponsPLS 4HROnsite H34054 | 97508-H34054 | \$ 1,773.00 | 10% | <i>\$1,607.67</i> |
| EW ResponsPLS 4HROnsite H34055 | 97508-H34055 | \$ 1,773.00 | 10% | <i>\$1,607.67</i> |
| EW ResponsPLS 4HROnsite H34056 | 97508-H34056 | \$ 2,149.00 | 10% | <i>\$1,948.61</i> |
| EW ResponsPLS 4HROnsite H34057 | 97508-H34057 | \$ 2,149.00 | 10% | <i>\$1,948.61</i> |
| EW ResponsPLS 4HROnsite H34058 | 97508-H34058 | \$ 2,020.00 | 10% | <i>\$1,831.64</i> |
| EW ResponsPLS 4HROnsite H34059 | 97508-H34059 | \$ 2,020.00 | 10% | <i>\$1,831.64</i> |
| EW ResponsPLS 4HROnsite H34062 | 97508-H34062 | \$ 2,149.00 | 10% | <i>\$1,948.61</i> |
| EW ResponsPLS 4HROnsite H34063 | 97508-H34063 | \$ 2,149.00 | 10% | <i>\$1,948.61</i> |
| EW ResponsPLS 4HROnsite H34064 | 97508-H34064 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite H34065 | 97508-H34065 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |
| EW ResponsPLS 4HROnsite H34066 | 97508-H34066 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |
| EW ResponsPLS 4HROnsite H34067 | 97508-H34067 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |
| EW ResponsPLS 4HROnsite H34068 | 97508-H34068 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |
| EW ResponsPLS 4HROnsite H34069 | 97508-H34069 | \$ 1,684.00 | 10% | <i>\$1,526.97</i> |
| EW ResponsPLS 4HROnsite H34070 | 97508-H34070 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |
| EW ResponsPLS 4HROnsite H34071 | 97508-H34071 | \$ 1,733.00 | 10% | <i>\$1,571.40</i> |
| EW ResponsPLS 4HROnsite H34072 | 97508-H34072 | \$ 5,749.00 | 10% | <i>\$5,212.91</i> |
| EW ResponsPLS 4HROnsite H34073 | 97508-H34073 | \$ 5,640.00 | 10% | <i>\$5,114.07</i> |
| EW ResponsPLS 4HROnsite H34074 | 97508-H34074 | \$ 7,088.00 | 10% | <i>\$6,427.04</i> |
| EW ResponsPLS 4HROnsite H34075 | 97508-H34075 | \$ 6,853.00 | 10% | <i>\$6,213.96</i> |
| EW ResponsPLS 4HROnsite H34076 | 97508-H34076 | \$ 5,749.00 | 10% | <i>\$5,212.91</i> |
| EW ResponsPLS 4HROnsite H34077 | 97508-H34077 | \$ 5,640.00 | 10% | <i>\$5,114.07</i> |
| EW ResponsPLS 4HROnsite H34078 | 97508-H34078 | \$ 5,749.00 | 10% | <i>\$5,212.91</i> |
| EW ResponsPLS 4HROnsite H34079 | 97508-H34079 | \$ 5,640.00 | 10% | <i>\$5,114.07</i> |
| EW ResponsPLS 4HROnsite H34080 | 97508-H34080 | \$ 7,088.00 | 10% | <i>\$6,427.04</i> |
| EW ResponsPLS 4HROnsite H34081 | 97508-H34081 | \$ 6,853.00 | 10% | <i>\$6,213.96</i> |
| EW ResponsPLS 4HROnsite H34082 | 97508-H34082 | \$ 6,800.00 | 10% | <i>\$6,165.90</i> |
| EW ResponsPLS 4HROnsite H34083 | 97508-H34083 | \$ 6,573.00 | 10% | <i>\$5,960.07</i> |
| EW ResponsPLS 4HROnsite H34084 | 97508-H34084 | \$ 4,839.00 | 10% | <i>\$4,387.76</i> |
| EW ResponsPLS 4HROnsite H34085 | 97508-H34085 | \$ 4,839.00 | 10% | <i>\$4,387.76</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H34086 | 97508-H34086 | \$ 5,635.00 | 10% | <i>\$5,109.54</i> |
| EW ResponsPLS 4HROnsite H34087 | 97508-H34087 | \$ 5,405.00 | 10% | <i>\$4,900.98</i> |
| EW ResponsPLS 4HROnsite H34088 | 97508-H34088 | \$ 11,384.00 | 10% | <i>\$10,322.44</i> |
| EW ResponsPLS 4HROnsite H34089 | 97508-H34089 | \$ 11,384.00 | 10% | <i>\$10,322.44</i> |
| EW ResponsPLS 4HROnsite H34090 | 97508-H34090 | \$ 13,109.00 | 10% | <i>\$11,886.59</i> |
| EW ResponsPLS 4HROnsite H34091 | 97508-H34091 | \$ 12,710.00 | 10% | <i>\$11,524.79</i> |
| EW ResponsPLS 4HROnsite H34092 | 97508-H34092 | \$ 12,710.00 | 10% | <i>\$11,524.79</i> |
| EW ResponsPLS 4HROnsite H34093 | 97508-H34093 | \$ 12,710.00 | 10% | <i>\$11,524.79</i> |
| EW ResponsPLS 4HROnsite H34094 | 97508-H34094 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34095 | 97508-H34095 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34096 | 97508-H34096 | \$ 1,640.00 | 10% | <i>\$1,487.07</i> |
| EW ResponsPLS 4HROnsite H34097 | 97508-H34097 | \$ 1,640.00 | 10% | <i>\$1,487.07</i> |
| EW ResponsPLS 4HROnsite H34098 | 97508-H34098 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34099 | 97508-H34099 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34100 | 97508-H34100 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34101 | 97508-H34101 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34102 | 97508-H34102 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34103 | 97508-H34103 | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS 4HROnsite H34104 | 97508-H34104 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW ResponsPLS 4HROnsite H34105 | 97508-H34105 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW ResponsPLS 4HROnsite H34106 | 97508-H34106 | \$ 897.00 | 10% | <i>\$813.35</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H34107 | 97508-H34107 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW ResponsPLS 4HROnsite H34108 | 97508-H34108 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW ResponsPLS 4HROnsite H34109 | 97508-H34109 | \$ 897.00 | 10% | <i>\$813.35</i> |
| EW ResponsPLS 4HROnsite H34110 | 97508-H34110 | \$ 12,244.00 | 10% | <i>\$11,102.25</i> |
| EW ResponsPLS 4HROnsite H34111 | 97508-H34111 | \$ 12,244.00 | 10% | <i>\$11,102.25</i> |
| EW ResponsPLS 4HROnsite H34112 | 97508-H34112 | \$ 12,244.00 | 10% | <i>\$11,102.25</i> |
| EW ResponsPLS 4HROnsite H34114 | 97508-H34114 | \$ 17,536.00 | 10% | <i>\$15,900.77</i> |
| EW ResponsPLS 4HROnsite H34115 | 97508-H34115 | \$ 17,120.00 | 10% | <i>\$15,523.56</i> |
| EW ResponsPLS 4HROnsite H34116 | 97508-H34116 | \$ 17,120.00 | 10% | <i>\$15,523.56</i> |
| EW ResponsPLS 4HROnsite H34117 | 97508-H34117 | \$ 17,536.00 | 10% | <i>\$15,900.77</i> |
| EW ResponsPLS 4HROnsite H34118 | 97508-H34118 | \$ 3,377.00 | 10% | <i>\$3,062.09</i> |
| EW ResponsPLS 4HROnsite H34119 | 97508-H34119 | \$ 3,377.00 | 10% | <i>\$3,062.09</i> |
| EW ResponsPLS 4HROnsite H34120 | 97508-H34120 | \$ 2,451.00 | 10% | <i>\$2,222.44</i> |
| EW ResponsPLS 4HROnsite H34121 | 97508-H34121 | \$ 2,451.00 | 10% | <i>\$2,222.44</i> |
| EW ResponsPLS 4HROnsite H34122 | 97508-H34122 | \$ 2,543.00 | 10% | <i>\$2,305.87</i> |
| EW ResponsPLS 4HROnsite H34123 | 97508-H34123 | \$ 2,543.00 | 10% | <i>\$2,305.87</i> |
| EW ResponsPLS 4HROnsite H34124 | 97508-H34124 | \$ 3,584.00 | 10% | <i>\$3,249.79</i> |
| EW ResponsPLS 4HROnsite H34125 | 97508-H34125 | \$ 3,584.00 | 10% | <i>\$3,249.79</i> |
| EW ResponsPLS 4HROnsite H34126 | 97508-H34126 | \$ 3,584.00 | 10% | <i>\$3,249.79</i> |
| EW ResponsPLS 4HROnsite H34127 | 97508-H34127 | \$ 3,584.00 | 10% | <i>\$3,249.79</i> |
| EW ResponsPLS 4HROnsite H34129 | 97508-H34129 | \$ 1,845.00 | 10% | <i>\$1,672.95</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite H34130 | 97508-H34130 | \$ 1,917.00 | 10% | <i>\$1,738.24</i> |
| EW ResponsPLS 4HROnsite H34131 | 97508-H34131 | \$ 1,908.00 | 10% | <i>\$1,730.08</i> |
| EW ResponsPLS 4HROnsite H34132 | 97508-H34132 | \$ 1,917.00 | 10% | <i>\$1,738.24</i> |
| EW ResponsPLS 4HROnsite H34172 | 97508-H34172 | \$ 3,791.00 | 10% | <i>\$3,437.49</i> |
| EW ResponsPLS 4HROnsite H34726 | 97508-H34726 | \$ 6,010.00 | 10% | <i>\$5,449.57</i> |
| EW ResponsPLS 4HROnsite H34727 | 97508-H34727 | \$ 6,010.00 | 10% | <i>\$5,449.57</i> |
| EW ResponsPLS 4HROnsite H34728 | 97508-H34728 | \$ 6,010.00 | 10% | <i>\$5,449.57</i> |
| EW ResponsPLS 4HROnsite H34729 | 97508-H34729 | \$ 6,010.00 | 10% | <i>\$5,449.57</i> |
| EW ResponsPLS 4HROnsite H34730 | 97508-H34730 | \$ 6,357.00 | 10% | <i>\$5,764.21</i> |
| EW ResponsPLS 4HROnsite H34731 | 97508-H34731 | \$ 6,357.00 | 10% | <i>\$5,764.21</i> |
| EW ResponsPLS 4HROnsite H34732 | 97508-H34732 | \$ 6,357.00 | 10% | <i>\$5,764.21</i> |
| EW ResponsPLS 4HROnsite H34733 | 97508-H34733 | \$ 6,357.00 | 10% | <i>\$5,764.21</i> |
| EW ResponsPLS 4HROnsite H34734 | 97508-H34734 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |
| EW ResponsPLS 4HROnsite H34735 | 97508-H34735 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |
| EW ResponsPLS 4HROnsite H34736 | 97508-H34736 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H34737 | 97508-H34737 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H34738 | 97508-H34738 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34739 | 97508-H34739 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34740 | 97508-H34740 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |
| EW ResponsPLS 4HROnsite H34741 | 97508-H34741 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |
| EW ResponsPLS 4HROnsite H34742 | 97508-H34742 | \$ 1,894.00 | 10% | <i>\$1,717.38</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H34743 | 97508-H34743 | \$ 1,894.00 | 10% | <i>\$1,717.38</i> |
| EW ResponsPLS 4HROnsite H34744 | 97508-H34744 | \$ 2,186.00 | 10% | <i>\$1,982.16</i> |
| EW ResponsPLS 4HROnsite H34745 | 97508-H34745 | \$ 2,186.00 | 10% | <i>\$1,982.16</i> |
| EW ResponsPLS 4HROnsite H34746 | 97508-H34746 | \$ 2,310.00 | 10% | <i>\$2,094.59</i> |
| EW ResponsPLS 4HROnsite H34747 | 97508-H34747 | \$ 2,310.00 | 10% | <i>\$2,094.59</i> |
| EW ResponsPLS 4HROnsite H34748 | 97508-H34748 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34749 | 97508-H34749 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34750 | 97508-H34750 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34751 | 97508-H34751 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34752 | 97508-H34752 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34753 | 97508-H34753 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34754 | 97508-H34754 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34755 | 97508-H34755 | \$ 3,042.00 | 10% | <i>\$2,758.33</i> |
| EW ResponsPLS 4HROnsite H34756 | 97508-H34756 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H34757 | 97508-H34757 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H34758 | 97508-H34758 | \$ 2,186.00 | 10% | <i>\$1,982.16</i> |
| EW ResponsPLS 4HROnsite H34759 | 97508-H34759 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H34760 | 97508-H34760 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H34761 | 97508-H34761 | \$ 2,186.00 | 10% | <i>\$1,982.16</i> |
| EW ResponsPLS 4HROnsite H34993 | 97508-H34993 | \$ 23,273.00 | 10% | <i>\$21,102.79</i> |
| EW ResponsPLS 4HROnsite H34994 | 97508-H34994 | \$ 23,273.00 | 10% | <i>\$21,102.79</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H34996 | 97508-H34996 | \$ 23,273.00 | 10% | <i>\$21,102.79</i> |
| EW ResponsPLS 4HROnsite H34997 | 97508-H34997 | \$ 23,273.00 | 10% | <i>\$21,102.79</i> |
| EW ResponsPLS 4HROnsite H35005 | 97508-H35005 | \$ 17,700.00 | 10% | <i>\$16,049.48</i> |
| EW ResponsPLS 4HROnsite H35006 | 97508-H35006 | \$ 17,700.00 | 10% | <i>\$16,049.48</i> |
| EW ResponsPLS 4HROnsite H35012 | 97508-H35012 | \$ 11,631.00 | 10% | <i>\$10,546.41</i> |
| EW ResponsPLS 4HROnsite H35270 | 97508-H35270 | \$ 1,971.00 | 10% | <i>\$1,787.20</i> |
| EW ResponsPLS 4HROnsite H35271 | 97508-H35271 | \$ 1,773.00 | 10% | <i>\$1,607.67</i> |
| EW ResponsPLS 4HROnsite H35272 | 97508-H35272 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsPLS 4HROnsite H35273 | 97508-H35273 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsPLS 4HROnsite H35274 | 97508-H35274 | \$ 2,321.00 | 10% | <i>\$2,104.57</i> |
| EW ResponsPLS 4HROnsite H35275 | 97508-H35275 | \$ 2,149.00 | 10% | <i>\$1,948.61</i> |
| EW ResponsPLS 4HROnsite H35276 | 97508-H35276 | \$ 5,749.00 | 10% | <i>\$5,212.91</i> |
| EW ResponsPLS 4HROnsite H35277 | 97508-H35277 | \$ 6,800.00 | 10% | <i>\$6,165.90</i> |
| EW ResponsPLS 4HROnsite H35278 | 97508-H35278 | \$ 4,839.00 | 10% | <i>\$4,387.76</i> |
| EW ResponsPLS 4HROnsite H35279 | 97508-H35279 | \$ 5,405.00 | 10% | <i>\$4,900.98</i> |
| EW ResponsPLS 4HROnsite H35280 | 97508-H35280 | \$ 12,010.00 | 10% | <i>\$10,890.07</i> |
| EW ResponsPLS 4HROnsite H35292 | 97508-H35292 | \$ 4,839.00 | 10% | <i>\$4,387.76</i> |
| EW ResponsPLS 4HROnsite H35293 | 97508-H35293 | \$ 5,405.00 | 10% | <i>\$4,900.98</i> |
| EW ResponsPLS 4HROnsite H35295 | 97508-H35295 | \$ 1,758.00 | 10% | <i>\$1,594.07</i> |
| EW ResponsPLS 4HROnsite H35302 | 97508-H35302 | \$ 4,753.00 | 10% | <i>\$4,309.78</i> |
| EW ResponsPLS 4HROnsite H35303 | 97508-H35303 | \$ 4,753.00 | 10% | <i>\$4,309.78</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite H35304 | 97508-H35304 | \$ 4,753.00 | 10% | <i>\$4,309.78</i> |
| EW ResponsPLS 4HROnsite H35305 | 97508-H35305 | \$ 4,919.00 | 10% | <i>\$4,460.30</i> |
| EW ResponsPLS 4HROnsite H35306 | 97508-H35306 | \$ 4,919.00 | 10% | <i>\$4,460.30</i> |
| EW ResponsPLS 4HROnsite H35307 | 97508-H35307 | \$ 4,919.00 | 10% | <i>\$4,460.30</i> |
| EW ResponsPLS 4HROnsite H35309 | 97508-H35309 | \$ 5,904.00 | 10% | <i>\$5,353.45</i> |
| EW ResponsPLS 4HROnsite H35310 | 97508-H35310 | \$ 5,904.00 | 10% | <i>\$5,353.45</i> |
| EW ResponsPLS 4HROnsite H35311 | 97508-H35311 | \$ 5,904.00 | 10% | <i>\$5,353.45</i> |
| EW ResponsPLS 4HROnsite H35312 | 97508-H35312 | \$ 4,873.00 | 10% | <i>\$4,418.59</i> |
| EW ResponsPLS 4HROnsite H35313 | 97508-H35313 | \$ 4,873.00 | 10% | <i>\$4,418.59</i> |
| EW ResponsPLS 4HROnsite H35314 | 97508-H35314 | \$ 4,873.00 | 10% | <i>\$4,418.59</i> |
| EW ResponsPLS 4HROnsite H35315 | 97508-H35315 | \$ 2,845.00 | 10% | <i>\$2,579.70</i> |
| EW ResponsPLS 4HROnsite H35318 | 97508-H35318 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsPLS 4HROnsite H35319 | 97508-H35319 | \$ 2,155.00 | 10% | <i>\$1,954.05</i> |
| EW ResponsPLS 4HROnsite H35320 | 97508-H35320 | \$ 2,198.00 | 10% | <i>\$1,993.04</i> |
| EW ResponsPLS 4HROnsite H35321 | 97508-H35321 | \$ 2,499.00 | 10% | <i>\$2,265.97</i> |
| EW ResponsPLS 4HROnsite H35322 | 97508-H35322 | \$ 2,880.00 | 10% | <i>\$2,611.44</i> |
| EW ResponsPLS 4HROnsite H35323 | 97508-H35323 | \$ 2,845.00 | 10% | <i>\$2,579.70</i> |
| EW ResponsPLS 4HROnsite H35328 | 97508-H35328 | \$ 864.00 | 10% | <i>\$783.43</i> |
| EW ResponsPLS 4HROnsite H35330 | 97508-H35330 | \$ 1,194.00 | 10% | <i>\$1,082.66</i> |
| EW ResponsPLS 4HROnsite H35340 | 97508-H35340 | \$ 4,790.00 | 10% | <i>\$4,343.33</i> |
| EW ResponsPLS 4HROnsite H35341 | 97508-H35341 | \$ 4,790.00 | 10% | <i>\$4,343.33</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite H35342 | 97508-H35342 | \$ 4,046.00 | 10% | <i>\$3,668.71</i> |
| EW ResponsPLS 4HROnsite H35343 | 97508-H35343 | \$ 4,790.00 | 10% | <i>\$4,343.33</i> |
| EW ResponsPLS 4HROnsite H35344 | 97508-H35344 | \$ 4,935.00 | 10% | <i>\$4,474.81</i> |
| EW ResponsPLS 4HROnsite H35345 | 97508-H35345 | \$ 4,935.00 | 10% | <i>\$4,474.81</i> |
| EW ResponsPLS 4HROnsite H35346 | 97508-H35346 | \$ 4,155.00 | 10% | <i>\$3,767.55</i> |
| EW ResponsPLS 4HROnsite H35347 | 97508-H35347 | \$ 4,935.00 | 10% | <i>\$4,474.81</i> |
| EW ResponsPLS 4HROnsite H35349 | 97508-H35349 | \$ 5,294.00 | 10% | <i>\$4,800.33</i> |
| EW ResponsPLS 4HROnsite H35350 | 97508-H35350 | \$ 5,294.00 | 10% | <i>\$4,800.33</i> |
| EW ResponsPLS 4HROnsite H35351 | 97508-H35351 | \$ 4,446.00 | 10% | <i>\$4,031.41</i> |
| EW ResponsPLS 4HROnsite H35352 | 97508-H35352 | \$ 5,294.00 | 10% | <i>\$4,800.33</i> |
| EW ResponsPLS 4HROnsite H35359 | 97508-H35359 | \$ 2,500.00 | 10% | <i>\$2,266.88</i> |
| EW ResponsPLS 4HROnsite H35360 | 97508-H35360 | \$ 2,880.00 | 10% | <i>\$2,611.44</i> |
| EW ResponsPLS 4HROnsite H35361 | 97508-H35361 | \$ 2,845.00 | 10% | <i>\$2,579.70</i> |
| EW ResponsPLS 4HROnsite H35362 | 97508-H35362 | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsPLS 4HROnsite H35366 | 97508-H35366 | \$ 2,093.00 | 10% | <i>\$1,897.83</i> |
| EW ResponsPLS 4HROnsite H35367 | 97508-H35367 | \$ 2,436.00 | 10% | <i>\$2,208.84</i> |
| EW ResponsPLS 4HROnsite H35368 | 97508-H35368 | \$ 3,714.00 | 10% | <i>\$3,367.67</i> |
| EW ResponsPLS 4HROnsite H35369 | 97508-H35369 | \$ 1,208.00 | 10% | <i>\$1,095.35</i> |
| EW ResponsPLS 4HROnsite H35370 | 97508-H35370 | \$ 1,699.00 | 10% | <i>\$1,540.57</i> |
| EW ResponsPLS 4HROnsite H35375 | 97508-H35375 | \$ 1,348.00 | 10% | <i>\$1,222.30</i> |
| EW ResponsPLS 4HROnsite H35376 | 97508-H35376 | \$ 2,022.00 | 10% | <i>\$1,833.45</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite H35377 | 97508-H35377 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW ResponsPLS 4HROnsite H35378 | 97508-H35378 | \$ 1,348.00 | 10% | <i>\$1,222.30</i> |
| EW ResponsPLS 4HROnsite H35379 | 97508-H35379 | \$ 845.00 | 10% | <i>\$766.20</i> |
| EW ResponsPLS 4HROnsite H35380 | 97508-H35380 | \$ 1,514.00 | 10% | <i>\$1,372.82</i> |
| EW ResponsPLS 4HROnsite H35381 | 97508-H35381 | \$ 1,850.00 | 10% | <i>\$1,677.49</i> |
| EW ResponsPLS 4HROnsite H35384 | 97508-H35384 | \$ 680.00 | 10% | <i>\$616.59</i> |
| EW ResponsPLS 4HROnsite H35385 | 97508-H35385 | \$ 904.00 | 10% | <i>\$819.70</i> |
| EW ResponsPLS 4HROnsite H35386 | 97508-H35386 | \$ 1,507.00 | 10% | <i>\$1,366.47</i> |
| EW ResponsPLS 4HROnsite H35387 | 97508-H35387 | \$ 1,410.00 | 10% | <i>\$1,278.52</i> |
| EW ResponsPLS 4HROnsite H35388 | 97508-H35388 | \$ 1,037.00 | 10% | <i>\$940.30</i> |
| EW ResponsPLS 4HROnsite H35389 | 97508-H35389 | \$ 583.00 | 10% | <i>\$528.64</i> |
| EW ResponsPLS 4HROnsite H35390 | 97508-H35390 | \$ 506.00 | 10% | <i>\$458.82</i> |
| EW ResponsPLS 4HROnsite H35391 | 97508-H35391 | \$ 1,113.00 | 10% | <i>\$1,009.21</i> |
| EW ResponsPLS 4HROnsite H35392 | 97508-H35392 | \$ 1,698.00 | 10% | <i>\$1,539.66</i> |
| EW ResponsPLS 4HROnsite H35393 | 97508-H35393 | \$ 2,259.00 | 10% | <i>\$2,048.35</i> |
| EW ResponsPLS 4HROnsite H35394 | 97508-H35394 | \$ 406.00 | 10% | <i>\$368.14</i> |
| EW ResponsPLS 4HROnsite H35395 | 97508-H35395 | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsPLS 4HROnsite H35396 | 97508-H35396 | \$ 406.00 | 10% | <i>\$368.14</i> |
| EW ResponsPLS 4HROnsite H35397 | 97508-H35397 | \$ 344.00 | 10% | <i>\$311.92</i> |
| EW ResponsPLS 4HROnsite H35398 | 97508-H35398 | \$ 1,056.00 | 10% | <i>\$957.53</i> |
| EW ResponsPLS 4HROnsite H35399 | 97508-H35399 | \$ 1,285.00 | 10% | <i>\$1,165.17</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite H35400 | 97508-H35400 | \$ 1,412.00 | 10% | <i>\$1,280.33</i> |
| EW ResponsPLS 4HROnsite H35401 | 97508-H35401 | \$ 757.00 | 10% | <i>\$686.41</i> |
| EW ResponsPLS 4HROnsite H35415 | 97508-H35415 | \$ 466.00 | 10% | <i>\$422.55</i> |
| EW ResponsPLS 4HROnsite H35416 | 97508-H35416 | \$ 466.00 | 10% | <i>\$422.55</i> |
| EW ResponsPLS 4HROnsite H35426 | 97508-H35426 | \$ 583.00 | 10% | <i>\$528.64</i> |
| EW ResponsPLS 4HROnsite H35427 | 97508-H35427 | \$ 1,410.00 | 10% | <i>\$1,278.52</i> |
| EW ResponsPLS 4HROnsite H35428 | 97508-H35428 | \$ 506.00 | 10% | <i>\$458.82</i> |
| EW ResponsPLS 4HROnsite H35429 | 97508-H35429 | \$ 1,113.00 | 10% | <i>\$1,009.21</i> |
| EW ResponsPLS 4HROnsite H35430 | 97508-H35430 | \$ 1,930.00 | 10% | <i>\$1,750.03</i> |
| EW ResponsPLS 4HROnsite H35431 | 97508-H35431 | \$ 1,930.00 | 10% | <i>\$1,750.03</i> |
| EW ResponsPLS 4HROnsite H35432 | 97508-H35432 | \$ 1,894.00 | 10% | <i>\$1,717.38</i> |
| EW ResponsPLS 4HROnsite H35433 | 97508-H35433 | \$ 2,133.00 | 10% | <i>\$1,934.10</i> |
| EW ResponsPLS 4HROnsite H35434 | 97508-H35434 | \$ 2,253.00 | 10% | <i>\$2,042.91</i> |
| EW ResponsPLS 4HROnsite H35435 | 97508-H35435 | \$ 2,253.00 | 10% | <i>\$2,042.91</i> |
| EW ResponsPLS 4HROnsite H35436 | 97508-H35436 | \$ 2,954.00 | 10% | <i>\$2,678.54</i> |
| EW ResponsPLS 4HROnsite H35437 | 97508-H35437 | \$ 2,954.00 | 10% | <i>\$2,678.54</i> |
| EW ResponsPLS 4HROnsite H35438 | 97508-H35438 | \$ 2,954.00 | 10% | <i>\$2,678.54</i> |
| EW ResponsPLS 4HROnsite H35439 | 97508-H35439 | \$ 2,954.00 | 10% | <i>\$2,678.54</i> |
| EW ResponsPLS 4HROnsite H35440 | 97508-H35440 | \$ 2,133.00 | 10% | <i>\$1,934.10</i> |
| EW ResponsPLS 4HROnsite H35441 | 97508-H35441 | \$ 2,133.00 | 10% | <i>\$1,934.10</i> |
| EW ResponsPLS 4HROnsite H35442 | 97508-H35442 | \$ 2,133.00 | 10% | <i>\$1,934.10</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H35443 | 97508-H35443 | \$ 6,010.00 | 10% | <i>\$5,449.57</i> |
| EW ResponsPLS 4HROnsite H35444 | 97508-H35444 | \$ 6,357.00 | 10% | <i>\$5,764.21</i> |
| EW ResponsPLS 4HROnsite H35445 | 97508-H35445 | \$ 5,749.00 | 10% | <i>\$5,212.91</i> |
| EW ResponsPLS 4HROnsite H35446 | 97508-H35446 | \$ 5,640.00 | 10% | <i>\$5,114.07</i> |
| EW ResponsPLS 4HROnsite H35447 | 97508-H35447 | \$ 6,444.00 | 10% | <i>\$5,843.10</i> |
| EW ResponsPLS 4HROnsite H35448 | 97508-H35448 | \$ 6,230.00 | 10% | <i>\$5,649.05</i> |
| EW ResponsPLS 4HROnsite H35449 | 97508-H35449 | \$ 4,839.00 | 10% | <i>\$4,387.76</i> |
| EW ResponsPLS 4HROnsite H35450 | 97508-H35450 | \$ 5,123.00 | 10% | <i>\$4,645.28</i> |
| EW ResponsPLS 4HROnsite H35451 | 97508-H35451 | \$ 12,710.00 | 10% | <i>\$11,524.79</i> |
| EW ResponsPLS 4HROnsite H35452 | 97508-H35452 | \$ 12,710.00 | 10% | <i>\$11,524.79</i> |
| EW ResponsPLS 4HROnsite H35453 | 97508-H35453 | \$ 6,357.00 | 10% | <i>\$5,764.21</i> |
| EW ResponsPLS 4HROnsite H35454 | 97508-H35454 | \$ 6,010.00 | 10% | <i>\$5,449.57</i> |
| EW ResponsPLS 4HROnsite H35455 | 97508-H35455 | \$ 2,198.00 | 10% | <i>\$1,993.04</i> |
| EW ResponsPLS 4HROnsite H35456 | 97508-H35456 | \$ 2,461.00 | 10% | <i>\$2,231.51</i> |
| EW ResponsPLS 4HROnsite H35457 | 97508-H35457 | \$ 2,333.00 | 10% | <i>\$2,115.45</i> |
| EW ResponsPLS 4HROnsite H35458 | 97508-H35458 | \$ 2,467.00 | 10% | <i>\$2,236.95</i> |
| EW ResponsPLS 4HROnsite H35471 | 97508-H35471 | \$ 2,198.00 | 10% | <i>\$1,993.04</i> |
| EW ResponsPLS 4HROnsite H35600 | 97508-H35600 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsPLS 4HROnsite H35601 | 97508-H35601 | \$ 1,621.00 | 10% | <i>\$1,469.84</i> |
| EW ResponsPLS 4HROnsite H35602 | 97508-H35602 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |
| EW ResponsPLS 4HROnsite H35603 | 97508-H35603 | \$ 1,988.00 | 10% | <i>\$1,802.62</i> |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EW ResponsPLS 4HROnsite H35604 | 97508-H35604 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H35605 | 97508-H35605 | \$ 2,197.00 | 10% | <i>\$1,992.13</i> |
| EW ResponsPLS 4HROnsite H35606 | 97508-H35606 | \$ 2,321.00 | 10% | <i>\$2,104.57</i> |
| EW ResponsPLS 4HROnsite H35607 | 97508-H35607 | \$ 2,310.00 | 10% | <i>\$2,094.59</i> |
| EW ResponsPLS 4HROnsite ISW-24W-4X | 97508-ISW- 24W-4X | \$ 2,078.00 | 10% | <i>\$1,884.23</i> |
| EW ResponsPLS 4HROnsite ISW-4W-4WS-4X | 97508-ISW-4W- 4WS-4X | \$ 1,615.00 | 10% | <i>\$1,464.40</i> |
| EW ResponsPLUS 4HROnsite- MS128 | 97508- MSM128 | \$ 4,254.00 | 10% | <i>\$3,857.31</i> |
| EW ResponsPLS 4HROnsite- MSM48C | 97508- MSM48C | \$ 2,866.00 | 10% | <i>\$2,598.75</i> |
| EW ResponsPLS 4HROnsit SLX9150-48XT-DC-F | 97508- SLX9150- 48XT-DC-F | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsPLS 4HROnsit SLX9150-48XT-DC-R | 97508- SLX9150- 48XT-DC-R | \$ 4,700.00 | 10% | <i>\$4,261.73</i> |
| EW ResponsPLS 4HROnsite SLX9150-48Y-DC-F | 97508- SLX9150-48Y- DC-F | \$ 4,178.00 | 10% | <i>\$3,788.40</i> |
| EW ResponsPLS 4HROnsite SLX9150-48Y-DC-R | 97508- SLX9150-48Y- DC-R | \$ 4,561.00 | 10% | <i>\$4,135.69</i> |
| EW ResponsPLS 4HROnsite SLX9740-40C | 97508- SLX9740-40C | \$ 14,169.00 | 10% | <i>\$12,847.74</i> |
| EW ResponsPLS 4HROnsite SLX9740-40C-AC-F | 97508- SLX9740-40C- AC-F | \$ 14,169.00 | 10% | <i>\$12,847.74</i> |
| EW ResponsPLS 4HROnsite SLX9740-40C-AC-R | 97508- SLX9740-40C- AC-R | \$ 14,169.00 | 10% | <i>\$12,847.74</i> |
| EW ResponsPLS 4HROnsite SLX9740-40C-DC-F | 97508- SLX9740-40C- DC-F | \$ 14,169.00 | 10% | <i>\$12,847.74</i> |
| EW ResponsPLS 4HROnsite SLX9740-80C | 97508- SLX9740-80C | \$ 25,680.00 | 10% | <i>\$23,285.34</i> |

| | | | | |
|--|---|--------------|-----|-------------|
| EW ResponsPLS 4HROnsite SLX9740-80C-AC-F | 97508- SLX9740-80C- AC-F | \$ 25,680.00 | 10% | \$23,285.34 |
| EW ResponsPLS 4HROnsite SLX9740-80C-AC-R | 97508- SLX9740-80C- AC-R | \$ 25,680.00 | 10% | \$23,285.34 |
| EW ResponsPLS 4HROnsite SLX9740-80C-DC-F | 97508- SLX9740-80C- DC-F | \$ 25,680.00 | 10% | \$23,285.34 |
| EW ResponsPLS 4HROnsite V300-8P-2X | 97508-V300- 8P-2X | \$ 911.00 | 10% | \$826.05 |
| EW ResponsPLS 4HROnsite V300-8T-2X | 97508-V300- 8T-2X | \$ 848.00 | 10% | \$768.92 |
| EW ResponsPLS 4HROnsite V300HT-8P-2X | 97508-V300HT- 8P-2X | \$ 1,171.00 | 10% | \$1,061.80 |
| EW ResponsPLS 4HROnsite V300HT-8T-2X | 97508-V300HT- 8T-2X | \$ 986.00 | 10% | \$894.06 |
| EW ResponsPLS 4HROnsite- VIM-SS | 97508-VIM-SS | \$ 652.00 | 10% | \$591.20 |
| EW ResponsPLS 4HROnsiteVIMSSV8 | 97508-VIM- SSV80 | \$ 832.00 | 10% | \$754.42 |
| EW ResponsPLS 4HROnsiteVIM2SS | 97508-VIM2- SS | \$ 656.00 | 10% | \$594.83 |
| EW ResponsPLS 4HROnsiteVIM2SS | 97508-VIM2- SS128 | \$ 1,241.00 | 10% | \$1,125.28 |
| EW ResponsPLS 4HROnsiteVIM2V80 | 97508-VIM2- V80 | \$ 1,326.00 | 10% | \$1,202.35 |
| EW ResponsPLS 4HROnsiteVIM | 97508- VIM210G4X | \$ 1,937.00 | 10% | \$1,756.37 |
| EW ResPLS 4HROnsit VSP4900- 12MXU-12XE | 97508- VSP4900- 12MXU-12XE | \$ 2,621.00 | 10% | \$2,376.59 |
| EW ResPLS 4HROnsit VSP4900- 12MXU-12XE-B1 | 97508- VSP4900- 12MXU-12XE- B1 | \$ 2,621.00 | 10% | \$2,376.59 |
| EW ResponsPLS 4HROnsite VSP4900-24S | 97508- VSP4900-24S | \$ 1,855.00 | 10% | \$1,682.02 |
| EW ResponsPLS 4HROnsite VSP4900-24S-B3 | 97508- VSP4900-24S- B3 | \$ 1,855.00 | 10% | \$1,682.02 |

| | | | | |
|--|-------------------------------|-------------|-----|------------|
| EW ResponsPLS 4HROnsite VSP4900-24XE | 97508- VSP4900- 24XE | \$ 2,621.00 | 10% | \$2,376.59 |
| EW ResponsPLS 4HROnsite VSP4900-24XE-B3 | 97508- VSP4900- 24XE-B3 | \$ 2,621.00 | 10% | \$2,376.59 |
| EW ResponsPLS 4HROnsite X435-24P-4S | 97508-X435- 24P-4S | \$ 1,070.00 | 10% | \$970.22 |
| EW ResponsPLS 4HROnsite X435-24T-4S | 97508-X435- 24T-4S | \$ 907.00 | 10% | \$822.42 |
| EW ResponsPLS 4HROnsite X435-8P-2T-W | 97508-X435- 8P-2T-W | \$ 907.00 | 10% | \$822.42 |
| EW ResponsPLS 4HROnsite X435-8P-4S | 97508-X435- 8P-4S | \$ 889.00 | 10% | \$806.10 |
| EW ResponsPLS 4HROnsite X435-8T-4S | 97508-X435- 8T-4S | \$ 853.00 | 10% | \$773.46 |
| EW ResponsPLS 4HROnsiteX46024P | 97508-X460- 24P | \$ 2,759.00 | 10% | \$2,501.72 |
| EW ResponsPLS 4HROnsiteX46024T | 97508-X460- 24T | \$ 2,306.00 | 10% | \$2,090.97 |
| EW ResponsPLS 4HROnsiteX46024T | 97508-X460- 24TDC | \$ 2,826.00 | 10% | \$2,562.48 |
| EW ResponsPLS 4HROnsiteX46024X | 97508-X460- 24X | \$ 3,156.00 | 10% | \$2,861.70 |
| EW ResponsPLS 4HROnsiteX46024X | 97508-X460- 24XDC | \$ 3,428.00 | 10% | \$3,108.34 |
| EW ResponsPLS 4HROnsiteX46048P | 97508-X460- 48P | \$ 3,156.00 | 10% | \$2,861.70 |
| EW ResponsPLS 4HROnsiteX46048T | 97508-X460- 48T | \$ 2,884.00 | 10% | \$2,615.07 |
| EW ResponsPLS 4HROnsiteX46048T | 97508-X460- 48TDC | \$ 3,368.00 | 10% | \$3,053.93 |
| EW ResponsPLS 4HROnsiteX46048X | 97508-X460- 48X | \$ 3,764.00 | 10% | \$3,413.01 |
| EW ResponsPLS 4HROnsiteX46048X | 97508-X460- 48XDC | \$ 3,764.00 | 10% | \$3,413.01 |
| EW ResponsPLS 4HROnsite X465-24MU | 97508-X465- 24MU | \$ 2,880.00 | 10% | \$2,611.44 |
| EW ResponsPLS 4HROnsite X465-24S | 97508-X465- 24S | \$ 1,855.00 | 10% | \$1,682.02 |
| EW ResponsPLS 4HROnsite X465-24S-B3 | 97508-X465- 24S-B3 | \$ 1,855.00 | 10% | \$1,682.02 |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW ResponsPLS 4HROnsite X465-24W | 97508-X465- 24W | \$ 1,855.00 | 10% | <i>\$1,682.02</i> |
| EW ResponsPLS 4HROnsite X465-24XE | 97508-X465- 24XE | \$ 2,621.00 | 10% | <i>\$2,376.59</i> |
| EW ResponsPLS 4HROnsite X465-24XE-B3 | 97508-X465- 24XE-B3 | \$ 2,621.00 | 10% | <i>\$2,376.59</i> |
| EW ResponsPLS 4HROnsite X465-48P | 97508-X465- 48P | \$ 2,198.00 | 10% | <i>\$1,993.04</i> |
| EW ResponsPLS 4HROnsite X465-48T | 97508-X465- 48T | \$ 2,155.00 | 10% | <i>\$1,954.05</i> |
| EW ResponsPLS 4HROnsite X465-48W | 97508-X465- 48W | \$ 2,499.00 | 10% | <i>\$2,265.97</i> |
| EW ResponsPLS 4HROnsite X465i-48W | 97508-X465i- 48W | \$ 2,845.00 | 10% | <i>\$2,579.70</i> |
| EW ResponsPLS 4HROnsite X465i-48W-B1-S1 | 97508-X465i- 48W-B1-S1 | \$ 2,845.00 | 10% | <i>\$2,579.70</i> |
| EW ResponsPLS 4HROnsite X465i-48W-B2-S1 | 97508-X465i- 48W-B2-S1 | \$ 2,845.00 | 10% | <i>\$2,579.70</i> |
| EW ResponsPLS 4HROnsiteX48024X | 97508-X480- 24X | \$ 3,411.00 | 10% | <i>\$3,092.92</i> |
| EW ResponsPLUS 4HROnsite- X480T | 97508-X480- 48T | \$ 3,011.00 | 10% | <i>\$2,730.22</i> |
| EW ResponsPLS 4HROnsite- X48048 | 97508-X480- 48X | \$ 4,169.00 | 10% | <i>\$3,780.24</i> |
| EW ResponsPLS 4HROnsite X695-48Y-8C | 97508-X695- 48Y-8C | \$ 4,941.00 | 10% | <i>\$4,480.25</i> |
| EW ResponsPLS 4HROnsite XA1440 | 97508-XA1440 | \$ 1,123.00 | 10% | <i>\$1,018.28</i> |
| EW ResponsPLS 4HROnsite XA1480 | 97508-XA1480 | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW ResponsPLS 4HROnsiteXGM32SF | 97508-XGM3- 2SF | \$ 832.00 | 10% | <i>\$754.42</i> |
| EW ResponsPLS 4HROnsite XR600 | 97508-XR600 | \$ 1,232.00 | 10% | <i>\$1,117.12</i> |
| EW ResponsPLS NBDOnsite 1130C | 97511-1130C | \$ 2,552.00 | 6% | <i>\$2,416.87</i> |
| EW ResponsPLS NBDOnsite- 16119 | 97511-16119 | \$ 722.00 | 10% | <i>\$654.67</i> |
| EW ResponsPLS NBDOnsite- 16120 | 97511-16120 | \$ 801.00 | 10% | <i>\$726.31</i> |
| EW ResponsPLS NBDOnsite- 16126 | 97511-16126 | \$ 722.00 | 10% | <i>\$654.67</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-16127 | 97511-16127 | \$ 757.00 | 10% | <i>\$686.41</i> |
| EW ResponsPLS NBDOnsite-16172 | 97511-16172 | \$ 1,626.00 | 10% | <i>\$1,474.38</i> |
| EW ResponsPLS NBDOnsite 16172T | 97511-16172T | \$ 1,736.00 | 10% | <i>\$1,574.12</i> |
| EW ResponsPLS NBDOnsite-16173 | 97511-16173 | \$ 1,632.00 | 10% | <i>\$1,479.82</i> |
| EW ResponsPLS NBDOnsite 16173T | 97511-16173T | \$ 1,742.00 | 10% | <i>\$1,579.56</i> |
| EW ResponsPLS NBDOnsite-16174 | 97511-16174 | \$ 1,758.00 | 10% | <i>\$1,594.07</i> |
| EW ResponsPLS NBDOnsite-16175 | 97511-16175 | \$ 1,832.00 | 10% | <i>\$1,661.17</i> |
| EW ResponsPLS NBDOnsite-16176 | 97511-16176 | \$ 1,773.00 | 10% | <i>\$1,607.67</i> |
| EW ResponsPLS NBDOnsite-16177 | 97511-16177 | \$ 1,665.00 | 10% | <i>\$1,509.74</i> |
| EW ResponsPLS NBDOnsite 16177T | 97511-16177T | \$ 1,906.00 | 10% | <i>\$1,728.27</i> |
| EW ResponsPLS NBDOnsite-16178 | 97511-16178 | \$ 1,973.00 | 10% | <i>\$1,789.02</i> |
| EW ResponsPLS NBDOnsite-16179 | 97511-16179 | \$ 1,986.00 | 10% | <i>\$1,800.81</i> |
| EW ResponsPLS NBDOnsite 16179T | 97511-16179T | \$ 2,113.00 | 10% | <i>\$1,915.96</i> |
| EW ResponsPLS NBDOnsite-16301T | 97511-16301T | \$ 2,913.00 | 10% | <i>\$2,641.36</i> |
| EW ResponsPLS NBDOnsite-16303T | 97511-16303T | \$ 2,913.00 | 10% | <i>\$2,641.36</i> |
| EW ResponsPLS NBDOnsite-16304T | 97511-16304T | \$ 3,495.00 | 10% | <i>\$3,169.09</i> |
| EW ResponsPLS NBDOnsite-16401T | 97511-16401T | \$ 2,130.00 | 10% | <i>\$1,931.38</i> |
| EW ResponsPLS NBDOnsite-16402T | 97511-16402T | \$ 2,554.00 | 10% | <i>\$2,315.84</i> |
| EW ResponsPLS NBDOnsite-16403T | 97511-16403T | \$ 2,415.00 | 10% | <i>\$2,189.80</i> |
| EW ResponsPLS NBDOnsite-16404T | 97511-16404T | \$ 2,415.00 | 10% | <i>\$2,189.80</i> |
| EW ResponsPLS NBDOnsite-16405T | 97511-16405T | \$ 2,767.00 | 10% | <i>\$2,508.98</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-16406T | 97511-16406T | \$ 3,245.00 | 10% | <i>\$2,942.40</i> |
| EW ResponsPLS NBDOnsite-16431 | 97511-16431 | \$ 2,453.00 | 10% | <i>\$2,224.26</i> |
| EW ResponsPLS NBDOnsite-16432 | 97511-16432 | \$ 2,577.00 | 10% | <i>\$2,336.69</i> |
| EW ResponsPLS NBDOnsite-16440 | 97511-16440 | \$ 1,994.00 | 10% | <i>\$1,808.06</i> |
| EW ResponsPLS NBDOnsite-16441 | 97511-16441 | \$ 1,918.00 | 10% | <i>\$1,739.15</i> |
| EW ResponsPLS NBDOnsite-16442 | 97511-16442 | \$ 757.00 | 10% | <i>\$686.41</i> |
| EW ResponsPLS NBDOnsite-16444 | 97511-16444 | \$ 606.00 | 10% | <i>\$549.49</i> |
| EW ResponsPLS NBDOnsite-16501 | 97511-16501 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsPLS NBDOnsite-16501T | 97511-16501T | \$ 1,533.00 | 10% | <i>\$1,390.05</i> |
| EW ResponsPLS NBDOnsite-16502 | 97511-16502 | \$ 1,557.00 | 10% | <i>\$1,411.81</i> |
| EW ResponsPLS NBDOnsite-16502T | 97511-16502T | \$ 1,601.00 | 10% | <i>\$1,451.71</i> |
| EW ResponsPLS NBDOnsite-16503 | 97511-16503 | \$ 1,514.00 | 10% | <i>\$1,372.82</i> |
| EW ResponsPLS NBDOnsite-16503T | 97511-16503T | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS NBDOnsite-16504 | 97511-16504 | \$ 1,645.00 | 10% | <i>\$1,491.60</i> |
| EW ResponsPLS NBDOnsite-16504T | 97511-16504T | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW ResponsPLS NBDOnsite-16505 | 97511-16505 | \$ 1,658.00 | 10% | <i>\$1,503.39</i> |
| EW ResponsPLS NBDOnsite-16505T | 97511-16505T | \$ 1,761.00 | 10% | <i>\$1,596.79</i> |
| EW ResponsPLS NBDOnsite-16506 | 97511-16506 | \$ 1,859.00 | 10% | <i>\$1,685.65</i> |
| EW ResponsPLS NBDOnsite-16506T | 97511-16506T | \$ 2,004.00 | 10% | <i>\$1,817.13</i> |
| EW ResponsPLS NBDOnsite-16507 | 97511-16507 | \$ 1,822.00 | 10% | <i>\$1,652.10</i> |
| EW ResponsPLS NBDOnsite-16507T | 97511-16507T | \$ 1,924.00 | 10% | <i>\$1,744.59</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-16508 | 97511-16508 | \$ 1,953.00 | 10% | <i>\$1,770.88</i> |
| EW ResponsPLS NBDOnsite-16508T | 97511-16508T | \$ 2,078.00 | 10% | <i>\$1,884.23</i> |
| EW ResponsPLS NBDOnsite-16509 | 97511-16509 | \$ 1,953.00 | 10% | <i>\$1,770.88</i> |
| EW ResponsPLS NBDOnsite-16509T | 97511-16509T | \$ 2,078.00 | 10% | <i>\$1,884.23</i> |
| EW ResponsPLS NBDOnsite-16510 | 97511-16510 | \$ 2,078.00 | 10% | <i>\$1,884.23</i> |
| EW ResponsPLS NBDOnsite-16510T | 97511-16510T | \$ 2,231.00 | 10% | <i>\$2,022.96</i> |
| EW ResponsPLS NBDOnsite-16513 | 97511-16513 | \$ 1,813.00 | 10% | <i>\$1,643.94</i> |
| EW ResponsPLS NBDOnsite-16514 | 97511-16514 | \$ 2,036.00 | 10% | <i>\$1,846.14</i> |
| EW ResponsPLS NBDOnsite-16515 | 97511-16515 | \$ 1,361.00 | 10% | <i>\$1,234.09</i> |
| EW ResponsPLS NBDOnsite-16516 | 97511-16516 | \$ 1,374.00 | 10% | <i>\$1,245.87</i> |
| EW ResponsPLS NBDOnsite-16517 | 97511-16517 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW ResponsPLS NBDOnsite-16518 | 97511-16518 | \$ 1,472.00 | 10% | <i>\$1,334.74</i> |
| EW ResponsPLS NBDOnsite-16519 | 97511-16519 | \$ 1,572.00 | 10% | <i>\$1,425.41</i> |
| EW ResponsPLS NBDOnsite-16520 | 97511-16520 | \$ 1,731.00 | 10% | <i>\$1,569.58</i> |
| EW ResponsPLUS NBDOnsite-16530 | 97511-16530 | \$ 1,513.00 | 10% | <i>\$1,371.91</i> |
| EW ResponsPLUS NBDOnsite-16531 | 97511-16531 | \$ 1,565.00 | 10% | <i>\$1,419.06</i> |
| EW ResponsPLUS NBDOnsite16531T | 97511-16531T | \$ 1,560.00 | 10% | <i>\$1,414.53</i> |
| EW ResponsPLUS NBDOnsite-16532 | 97511-16532 | \$ 1,565.00 | 10% | <i>\$1,419.06</i> |
| EW ResponsPLUS NBDOnsite16532T | 97511-16532T | \$ 1,560.00 | 10% | <i>\$1,414.53</i> |
| EW ResponsPLUS NBDOnsite-16533 | 97511-16533 | \$ 1,651.00 | 10% | <i>\$1,497.04</i> |
| EW ResponsPLUS NBDOnsite16533T | 97511-16533T | \$ 1,657.00 | 10% | <i>\$1,502.48</i> |

| | | | | |
|---------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLUS NBDOnsite-16534 | 97511-16534 | \$ 1,672.00 | 10% | <i>\$1,516.09</i> |
| EW ResponsPLUS NBDOnsite-16535 | 97511-16535 | \$ 1,825.00 | 10% | <i>\$1,654.82</i> |
| EW ResponsPLUS NBDOnsite-16535A | 97511-16535A | \$ 1,825.00 | 10% | <i>\$1,654.82</i> |
| EW ResponsPLUS NBDOnsite16535T | 97511-16535T | \$ 1,862.00 | 10% | <i>\$1,688.37</i> |
| EW ResponsPLUS NBDOnsite-16536 | 97511-16536 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLUS NBDOnsite-16537 | 97511-16537 | \$ 1,527.00 | 10% | <i>\$1,384.61</i> |
| EW ResponsPLUS NBDOnsite-16538 | 97511-16538 | \$ 1,590.00 | 10% | <i>\$1,441.73</i> |
| EW ResponsPLUS NBDOnsite16538T | 97511-16538T | \$ 1,770.00 | 10% | <i>\$1,604.95</i> |
| EW ResponsPLUS NBDOnsite-16539 | 97511-16539 | \$ 1,693.00 | 10% | <i>\$1,535.13</i> |
| EW ResponsPLUS NBDOnsite-16540 | 97511-16540 | \$ 1,568.00 | 10% | <i>\$1,421.78</i> |
| EW ResponsPLUS NBDOnsite-16541 | 97511-16541 | \$ 1,363.00 | 10% | <i>\$1,235.90</i> |
| EW ResponsPLS NBDOnsite 16560 | 97511-16560 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW ResponsPLS NBDOnsite 16561 | 97511-16561 | \$ 1,295.00 | 10% | <i>\$1,174.24</i> |
| EW ResponsPLS NBDOnsite 16562 | 97511-16562 | \$ 1,314.00 | 10% | <i>\$1,191.47</i> |
| EW ResponsPLS NBDOnsite 16563 | 97511-16563 | \$ 1,355.00 | 10% | <i>\$1,228.65</i> |
| EW ResponsPLS NBDOnsite 16564 | 97511-16564 | \$ 1,397.00 | 10% | <i>\$1,266.73</i> |
| EW ResponsPLS NBDOnsite 16565 | 97511-16565 | \$ 1,505.00 | 10% | <i>\$1,364.66</i> |
| EW ResponsPLS NBDOnsite 16566 | 97511-16566 | \$ 1,232.00 | 10% | <i>\$1,117.12</i> |
| EW ResponsPLS NBDOnsite 16567 | 97511-16567 | \$ 1,274.00 | 10% | <i>\$1,155.20</i> |
| EW ResponsPLS NBDOnsite 16568 | 97511-16568 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW ResponsPLS NBDOnsite 16569 | 97511-16569 | \$ 1,303.00 | 10% | <i>\$1,181.50</i> |

| | | | | |
|------------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite 16570 | 97511-16570 | \$ 1,314.00 | 10% | <i>\$1,191.47</i> |
| EW ResponsPLS NBDOnsite 16571 | 97511-16571 | \$ 1,397.00 | 10% | <i>\$1,266.73</i> |
| EW ResponsPLS NBDOnsite- 16701 | 97511-16701 | \$ 1,678.00 | 10% | <i>\$1,521.53</i> |
| EW ResponsPLS NBDOnsite- 16702 | 97511-16702 | \$ 1,892.00 | 10% | <i>\$1,715.57</i> |
| EW ResponsPLS NBDOnsite- 16703 | 97511-16703 | \$ 1,887.00 | 10% | <i>\$1,711.04</i> |
| EW ResponsPLS NBDOnsite 16703T | 97511-16703T | \$ 2,025.00 | 10% | <i>\$1,836.17</i> |
| EW ResponsPLUS NBDOnsite- 16704 | 97511-16704 | \$ 2,088.00 | 10% | <i>\$1,893.29</i> |
| EW ResponsPLS NBDOnsite 16704T | 97511-16704T | \$ 1,761.00 | 10% | <i>\$1,596.79</i> |
| EW ResponsPLS NBDOnsite- 16705 | 97511-16705 | \$ 1,892.00 | 10% | <i>\$1,715.57</i> |
| EW ResponsPLS NBDOnsite 16705T | 97511-16705T | \$ 2,018.00 | 10% | <i>\$1,829.82</i> |
| EW ResponsPLS NBDOnsite- 16706 | 97511-16706 | \$ 2,363.00 | 10% | <i>\$2,142.65</i> |
| EW ResponsPLS NBDOnsite 16706T | 97511-16706T | \$ 2,532.00 | 10% | <i>\$2,295.89</i> |
| EW ResponsPLS NBDOnsite- 16710 | 97511-16710 | \$ 627.00 | 10% | <i>\$568.53</i> |
| EW ResponsPLS NBDOnsite 16710T | 97511-16710T | \$ 668.00 | 10% | <i>\$605.71</i> |
| EW ResponsPLS NBDOnsite- 16711 | 97511-16711 | \$ 505.00 | 10% | <i>\$457.91</i> |
| EW ResponsPLS NBDOnsite 16711T | 97511-16711T | \$ 539.00 | 10% | <i>\$488.74</i> |
| EW ResponsPLS NBDOnsite- 16712 | 97511-16712 | \$ 536.00 | 10% | <i>\$486.02</i> |
| EW ResponsPLS NBDOnsite 16712T | 97511-16712T | \$ 564.00 | 10% | <i>\$511.41</i> |
| EW ResponsPLS NBDOnsite- 16713 | 97511-16713 | \$ 473.00 | 10% | <i>\$428.89</i> |
| EW ResponsPLS NBDOnsite 16713T | 97511-16713T | \$ 508.00 | 10% | <i>\$460.63</i> |
| EW ResponsPLS NBDOnsite- 16715 | 97511-16715 | \$ 493.00 | 10% | <i>\$447.03</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-16715T | 97511-16715T | \$ 539.00 | 10% | <i>\$488.74</i> |
| EW ResponsPLS NBDOnsite-16716 | 97511-16716 | \$ 1,709.00 | 10% | <i>\$1,549.64</i> |
| EW ResponsPLS NBDOnsite-16716T | 97511-16716T | \$ 1,833.00 | 10% | <i>\$1,662.07</i> |
| EW ResponsPLS NBDOnsite-16717 | 97511-16717 | \$ 1,761.00 | 10% | <i>\$1,596.79</i> |
| EW ResponsPLS NBDOnsite-16718 | 97511-16718 | \$ 1,748.00 | 10% | <i>\$1,585.00</i> |
| EW ResponsPLS NBDOnsite-16719 | 97511-16719 | \$ 1,803.00 | 10% | <i>\$1,634.87</i> |
| EW ResponsPLS NBDOnsite-16720 | 97511-16720 | \$ 2,086.00 | 10% | <i>\$1,891.48</i> |
| EW ResponsPLS NBDOnsite-16720T | 97511-16720T | \$ 2,428.00 | 10% | <i>\$2,201.59</i> |
| EW ResponsPLS NBDOnsite-16756 | 97511-16756 | \$ 1,969.00 | 10% | <i>\$1,785.39</i> |
| EW ResponsPLS NBDOnsite-16756T | 97511-16756T | \$ 2,328.00 | 10% | <i>\$2,110.91</i> |
| EW ResponsPLS NBDOnsite-16757 | 97511-16757 | \$ 1,929.00 | 10% | <i>\$1,749.12</i> |
| EW ResponsPLS NBDOnsite-16757T | 97511-16757T | \$ 2,280.00 | 10% | <i>\$2,067.39</i> |
| EW ResponsPLS NBDOnsite-16790 | 97511-16790 | \$ 2,011.00 | 10% | <i>\$1,823.47</i> |
| EW ResponsPLS NBDOnsite-16791 | 97511-16791 | \$ 2,595.00 | 10% | <i>\$2,353.02</i> |
| EW ResponsPLS NBDOnsite-17101 | 97511-17101 | \$ 3,704.00 | 10% | <i>\$3,358.60</i> |
| EW ResponsPLS NBDOnsite-17101T | 97511-17101T | \$ 4,608.00 | 10% | <i>\$4,178.30</i> |
| EW ResponsPLS NBDOnsite-17102 | 97511-17102 | \$ 3,704.00 | 10% | <i>\$3,358.60</i> |
| EW ResponsPLS NBDOnsite-17102T | 97511-17102T | \$ 4,608.00 | 10% | <i>\$4,178.30</i> |
| EW ResponsPLS NBDOnsite-17103 | 97511-17103 | \$ 2,928.00 | 10% | <i>\$2,654.96</i> |
| EW ResponsPLS NBDOnsite-17103C | 97511-17103C | \$ 2,843.00 | 10% | <i>\$2,577.89</i> |
| EW ResponsPLS NBDOnsite-17103T | 97511-17103T | \$ 3,610.00 | 10% | <i>\$3,273.37</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|------------|
| EW ResponsPLS NBDOnsite-17104 | 97511-17104 | \$ 2,928.00 | 10% | \$2,654.96 |
| EW ResponsPLS NBDOnsite-17104T | 97511-17104T | \$ 3,610.00 | 10% | \$3,273.37 |
| EW ResponsPLS NBDOnsite-17121 | 97511-17121 | \$ 956.00 | 10% | \$866.85 |
| EW ResponsPLS NBDOnsite-17122 | 97511-17122 | \$ 732.00 | 10% | \$663.74 |
| EW ResponsPLS NBDOnsite-17200 | 97511-17200 | \$ 5,187.00 | 10% | \$4,703.31 |
| EW ResponsPLS NBDOnsite-17200T | 97511-17200T | \$ 5,812.00 | 10% | \$5,270.03 |
| EW ResponsPLS NBDOnsite-17201 | 97511-17201 | \$ 5,187.00 | 10% | \$4,703.31 |
| EW ResponsPLS NBDOnsite-17201T | 97511-17201T | \$ 5,812.00 | 10% | \$5,270.03 |
| EW ResponsPLS NBDOnsite-17202 | 97511-17202 | \$ 5,187.00 | 10% | \$4,703.31 |
| EW ResponsPLS NBDOnsite-17202T | 97511-17202T | \$ 5,812.00 | 10% | \$5,270.03 |
| EW ResponsPLS NBDOnsite-17203 | 97511-17203 | \$ 5,251.00 | 10% | \$4,761.34 |
| EW ResponsPLS NBDOnsite-17203T | 97511-17203T | \$ 5,883.00 | 10% | \$5,334.41 |
| EW ResponsPLS NBDOnsite-17204 | 97511-17204 | \$ 5,251.00 | 10% | \$4,761.34 |
| EW ResponsPLS NBDOnsite-17204T | 97511-17204T | \$ 5,883.00 | 10% | \$5,334.41 |
| EW ResponsPLS NBDOnsite-17205 | 97511-17205 | \$ 5,220.00 | 10% | \$4,733.24 |
| EW ResponsPLS NBDOnsite-17205T | 97511-17205T | \$ 5,851.00 | 10% | \$5,305.39 |
| EW ResponsPLS NBDOnsite-17206 | 97511-17206 | \$ 5,220.00 | 10% | \$4,733.24 |
| EW ResponsPLS NBDOnsite-17206T | 97511-17206T | \$ 5,851.00 | 10% | \$5,305.39 |
| EW ResponsPLS NBDOnsite-17300 | 97511-17300 | \$ 3,898.00 | 10% | \$3,534.51 |
| EW ResponsPLS NBDOnsite-17310 | 97511-17310 | \$ 3,649.00 | 10% | \$3,308.73 |
| EW ResponsPLS NBDOnsite 17350 | 97511-17350 | \$ 3,770.00 | 10% | \$3,418.45 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite 17360 | 97511-17360 | \$ 4,369.00 | 10% | <i>\$3,961.59</i> |
| EW ResponsPLS NBDOnsite 17401 | 97511-17401 | \$ 1,595.00 | 10% | <i>\$1,446.27</i> |
| EW ResponsPLS NBDOnsite 17401G | 97511-17401G | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW ResponsPLS NBDOnsite 17401T | 97511-17401T | \$ 1,628.00 | 10% | <i>\$1,476.19</i> |
| EW ResponsPLS NBDOnsite 17402 | 97511-17402 | \$ 1,673.00 | 10% | <i>\$1,516.99</i> |
| EW ResponsPLS NBDOnsite 17402G | 97511-17402G | \$ 1,635.00 | 10% | <i>\$1,482.54</i> |
| EW ResponsPLS NBDOnsite 17402T | 97511-17402T | \$ 1,635.00 | 10% | <i>\$1,482.54</i> |
| EW ResponsPLS NBDOnsite 17403 | 97511-17403 | \$ 1,704.00 | 10% | <i>\$1,545.10</i> |
| EW ResponsPLS NBDOnsite 17404 | 97511-17404 | \$ 1,492.00 | 10% | <i>\$1,352.87</i> |
| EW ResponsPLS NBDOnsite 17405 | 97511-17405 | \$ 1,484.00 | 10% | <i>\$1,345.62</i> |
| EW ResponsPLS NBDOnsite 17700 | 97511-17700 | \$ 6,123.00 | 10% | <i>\$5,552.03</i> |
| EW ResponsPLS NBDOnsite- 17701 | 97511-17701 | \$ 5,238.00 | 10% | <i>\$4,749.56</i> |
| EW ResponsPLS NBDOnsite- 17702 | 97511-17702 | \$ 5,238.00 | 10% | <i>\$4,749.56</i> |
| EW ResponsPLS NBDOnsite- 17703 | 97511-17703 | \$ 5,719.00 | 10% | <i>\$5,185.70</i> |
| EW ResponsPLS NBDOnsite- 17704 | 97511-17704 | \$ 5,719.00 | 10% | <i>\$5,185.70</i> |
| EW ResponsPLS NBDOnsite- 17705 | 97511-17705 | \$ 5,268.00 | 10% | <i>\$4,776.76</i> |
| EW ResponsPLS NBDOnsite- 17706 | 97511-17706 | \$ 5,268.00 | 10% | <i>\$4,776.76</i> |
| EW ResponsPLS NBDOnsite 17800 | 97511-17800 | \$ 6,232.00 | 10% | <i>\$5,650.87</i> |
| EW ResponsPLS NBDOnsite 17810 | 97511-17810 | \$ 5,234.00 | 10% | <i>\$4,745.93</i> |
| EW ResponsPLS NBDOnsite 18101 | 97511-18101 | \$ 621.00 | 10% | <i>\$563.09</i> |
| EW ResponsPLS NBDOnsite 18102 | 97511-18102 | \$ 693.00 | 10% | <i>\$628.38</i> |

| | | | | |
|--------------------------------------|---------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite 18103 | 97511-18103 | \$ 726.00 | 10% | <i>\$658.30</i> |
| EW ResponsPLS NBDOnsite 18104 | 97511-18104 | \$ 872.00 | 10% | <i>\$790.69</i> |
| EW ResponsPLS NBDOnsite 18104-6PK | 97511-18104- 6PK | \$ 5,236.00 | 10% | <i>\$4,747.74</i> |
| EW ResponsPLS NBDOnsite- 30135 | 97511-30135 | \$ 2,960.00 | 10% | <i>\$2,683.98</i> |
| EW ResponsPLS NBDOnsite 30136 | 97511-30136 | \$ 7,314.00 | 10% | <i>\$6,631.97</i> |
| EW ResponsPLS NBDOnsite 30137 | 97511-30137 | \$ 2,252.00 | 10% | <i>\$2,042.00</i> |
| EW ResponsPLS NBDOnsite 30138 | 97511-30138 | \$ 5,593.00 | 10% | <i>\$5,071.45</i> |
| EW ResponsPLS NBDOnsite 30139 | 97511-30139 | \$ 9,414.00 | 10% | <i>\$8,536.14</i> |
| EW ResponsPLS NBDOnsite 30912 | 97511-30912 | \$ 427.00 | 10% | <i>\$387.18</i> |
| EW ResponsPLS NBDOnsite 30913 | 97511-30913 | \$ 427.00 | 10% | <i>\$387.18</i> |
| EW ResponsPLS NBDOnsite 31012 | 97511-31012 | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS NBDOnsite 31013 | 97511-31013 | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS NBDOnsite 31014 | 97511-31014 | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS NBDOnsite 31015 | 97511-31015 | \$ 419.00 | 10% | <i>\$379.93</i> |
| EW ResponsPLS NBDOnsite 31016 | 97511-31016 | \$ 592.00 | 10% | <i>\$536.80</i> |
| EW ResponsPLS NBDOnsite 31017 | 97511-31017 | \$ 592.00 | 10% | <i>\$536.80</i> |
| EW ResponsPLS NBDOnsite 31018 | 97511-31018 | \$ 632.00 | 10% | <i>\$573.07</i> |
| EW ResponsPLS NBDOnsite 31019 | 97511-31019 | \$ 632.00 | 10% | <i>\$573.07</i> |
| EW ResponsPLS NBDOnsite 31025 | 97511-31025 | \$ 349.00 | 10% | <i>\$316.46</i> |
| EW ResponsPLS NBDOnsite 31026 | 97511-31026 | \$ 349.00 | 10% | <i>\$316.46</i> |
| EW ResponsPLS NBDOnsite 31028 | 97511-31028 | \$ 348.00 | 10% | <i>\$315.55</i> |

| | | | | |
|---|------------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite 31029 | 97511-31029 | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsPLS NBDOnsite 31031 | 97511-31031 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsPLS NBDOnsite 31032 | 97511-31032 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EW ResponsPLS NBDOnsite 31034 | 97511-31034 | \$ 418.00 | 10% | <i>\$379.02</i> |
| EW ResponsPLS NBDOnsite 31035 | 97511-31035 | \$ 418.00 | 10% | <i>\$379.02</i> |
| EW ResponsPLS NBDOnsite 31050 | 97511-31050 | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsPLS NBDOnsite 31051 | 97511-31051 | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsPLS NBDOnsite 31055 | 97511-31055 | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsPLS NBDOnsite 31056 | 97511-31056 | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW ResponsPLS NBDOnsite 39031 | 97511-39031 | \$ 825.00 | 10% | <i>\$748.07</i> |
| EW ResponsPLS NBDOnsite 39032 | 97511-39032 | \$ 825.00 | 10% | <i>\$748.07</i> |
| EW ResponsPLS NBDOnsite 39033 | 97511-39033 | \$ 825.00 | 10% | <i>\$748.07</i> |
| EW ResponsPLS NBDOnsite 39034 | 97511-39034 | \$ 825.00 | 10% | <i>\$748.07</i> |
| EW ResponsPLS NBDOnsite 39035 | 97511-39035 | \$ 1,430.00 | 10% | <i>\$1,296.65</i> |
| EW ResponsPLS NBDOnsite 39036 | 97511-39036 | \$ 722.00 | 10% | <i>\$654.67</i> |
| EW ResponsPLS NBDOnsite 39037 | 97511-39037 | \$ 722.00 | 10% | <i>\$654.67</i> |
| EW ResponsPLS NBDOnsite 39038 | 97511-39038 | \$ 828.00 | 10% | <i>\$750.79</i> |
| EW ResponsPLS NBDOnsite 39039 | 97511-39039 | \$ 828.00 | 10% | <i>\$750.79</i> |
| EW ResponsPLS NBDOnsite 4120-24MW-4Y | 97511-4120- 24MW-4Y | \$ 1,474.00 | 10% | <i>\$1,336.55</i> |
| EW ResponsPLS NBDOnsite 4120-48MW-4Y | 97511-4120- 48MW-4Y | \$ 1,696.00 | 10% | <i>\$1,537.85</i> |
| EW ResponsPLS NBDOnsite 4120C | 97511-4120C | \$ 6,336.00 | 10% | <i>\$5,745.17</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite 4120C-1 | 97511-4120C-1 | \$ 7,153.00 | 10% | <i>\$6,485.98</i> |
| EW ResponsPLS NBDOnsite 41216 | 97511-41216 | \$ 2,082.00 | 10% | <i>\$1,887.85</i> |
| EW ResponsPLS NBDOnsite 4220-12P-4X | 97511-4220- 12P-4X | \$ 1,011.00 | 10% | <i>\$916.72</i> |
| EW ResponsPLS NBDOnsite 4220-12T-4X | 97511-4220- 12T-4X | \$ 957.00 | 10% | <i>\$867.76</i> |
| EW ResponsPLS NBDOnsite 4220-24P-4X | 97511-4220- 24P-4X | \$ 1,078.00 | 10% | <i>\$977.48</i> |
| EW ResponsPLS NBDOnsite 4220-24T-4X | 97511-4220- 24T-4X | \$ 1,017.00 | 10% | <i>\$922.16</i> |
| EW ResponsPLS NBDOnsite 4220-48P-4X | 97511-4220- 48P-4X | \$ 1,213.00 | 10% | <i>\$1,099.89</i> |
| EW ResponsPLS NBDOnsite 4220-48T-4X | 97511-4220- 48T-4X | \$ 1,112.00 | 10% | <i>\$1,008.31</i> |
| EW ResponsPLS NBDOnsite 4220-4MW-20P-4X | 97511-4220- 4MW-20P-4X | \$ 1,179.00 | 10% | <i>\$1,069.06</i> |
| EW ResponsPLS NBDOnsite 4220-4MW-8P-4X | 97511-4220- 4MW-8P-4X | \$ 1,071.00 | 10% | <i>\$971.13</i> |
| EW ResponsPLS NBDOnsite 4220-8MW-40P-4X | 97511-4220- 8MW-40P-4X | \$ 1,348.00 | 10% | <i>\$1,222.30</i> |
| EW ResponsPLS NBDOnsite 4220-8X | 97511-4220-8X | \$ 1,092.00 | 10% | <i>\$990.17</i> |
| EW ResponsPLS NBDOnsite- 48001 | 97511-48001 | \$ 9,207.00 | 10% | <i>\$8,348.45</i> |
| EW ResponsPLS NBDOnsite- 48038 | 97511-48038 | \$ 3,167.00 | 10% | <i>\$2,871.68</i> |
| EW ResponsPLS NBDOnsite- 48039 | 97511-48039 | \$ 3,167.00 | 10% | <i>\$2,871.68</i> |
| EW ResponsPLS NBDOnsite- 48040 | 97511-48040 | \$ 3,072.00 | 10% | <i>\$2,785.54</i> |
| EW ResponsPLS NBDOnsite- 48041 | 97511-48041 | \$ 3,167.00 | 10% | <i>\$2,871.68</i> |
| EW ResponsPLS NBDOnsite- 48046 | 97511-48046 | \$ 4,019.00 | 10% | <i>\$3,644.23</i> |
| EW ResponsPLS NBDOnsite- 48047 | 97511-48047 | \$ 9,963.00 | 10% | <i>\$9,033.95</i> |
| EW ResponsPLS NBDOnsite- 48051 | 97511-48051 | \$ 6,995.00 | 10% | <i>\$6,342.72</i> |
| EW ResponsPLS NBDOnsite- 48061 | 97511-48061 | \$ 8,095.00 | 10% | <i>\$7,340.14</i> |

| | | | | |
|--|---------------------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite-48062 | 97511-48062 | \$ 12,684.00 | 10% | <i>\$11,501.22</i> |
| EW ResponsPLS NBDOnsite 5320-16P-4XE | 97511-5320-16P-4XE | \$ 1,290.00 | 10% | <i>\$1,169.71</i> |
| EW ResponsPLS NBDOnsite 5320-16P-4XE-DC | 97511-5320-16P-4XE-DC | \$ 1,346.00 | 10% | <i>\$1,220.49</i> |
| EW ResponsPLS NBDOnsite 5320-24P-8XE | 97511-5320-24P-8XE | \$ 1,316.00 | 10% | <i>\$1,193.28</i> |
| EW ResponsPLS NBDOns 5320-24T-24S-4XE-XT | 97511-5320-24T-24S-4XE-XT | \$ 1,247.00 | 10% | <i>\$1,130.72</i> |
| EW ResponsPLS NBDOnsite 5320-24T-4X-XT | 97511-5320-24T-4X-XT | \$ 1,044.00 | 10% | <i>\$946.65</i> |
| EW ResponsPLS NBDOnsite 5320-24T-8XE | 97511-5320-24T-8XE | \$ 1,223.00 | 10% | <i>\$1,108.96</i> |
| EW ResponsPLS NBDOnsite 5320-48P-8XE | 97511-5320-48P-8XE | \$ 1,591.00 | 10% | <i>\$1,442.64</i> |
| EW ResponsPLS NBDOnsite 5320-48T-8XE | 97511-5320-48T-8XE | \$ 1,418.00 | 10% | <i>\$1,285.77</i> |
| EW ResponsPLS NBDOnsi 5420F-16MW-32P-4XE | 97511-5420F-16MW-32P-4XE | \$ 2,142.00 | 10% | <i>\$1,942.26</i> |
| EW ResponsPLS NBDOnsit 5420F-16W-32P-4XE | 97511-5420F-16W-32P-4XE | \$ 1,935.00 | 10% | <i>\$1,754.56</i> |
| EW ResponsPLS NBDOnsite 5420F-24P-4XE | 97511-5420F-24P-4XE | \$ 1,569.00 | 10% | <i>\$1,422.69</i> |
| EW ResponsPLS NBDOnsite 5420F-24S-4XE | 97511-5420F-24S-4XE | \$ 1,625.00 | 10% | <i>\$1,473.47</i> |
| EW ResponsPLS NBDOnsite 5420F-24T-4XE | 97511-5420F-24T-4XE | \$ 1,502.00 | 10% | <i>\$1,361.94</i> |
| EW ResponsPLS NBDOnsite 5420F-48P-4XE | 97511-5420F-48P-4XE | \$ 1,781.00 | 10% | <i>\$1,614.92</i> |
| EW ResponsPLS NBDOnsite 5420F-48P-4XL | 97511-5420F-48P-4XL | \$ 1,893.00 | 10% | <i>\$1,716.48</i> |
| EW ResponsPLS NBDOnsite 5420F-48T-4XE | 97511-5420F-48T-4XE | \$ 1,571.00 | 10% | <i>\$1,424.50</i> |
| EW ResponsPLS NBDOnsite 5420F-8W-16P-4XE | 97511-5420F-8W-16P-4XE | \$ 1,606.00 | 10% | <i>\$1,456.24</i> |
| EW ResponsPLS NBDOnsi 5420M-16MW-32P-4YE | 97511-5420M-16MW-32P-4YE | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite 5420M-24T-4YE | 97511-5420M- 24T-4YE | \$ 1,607.00 | 10% | <i>\$1,457.15</i> |
| EW ResponsPLS NBDOnsite 5420M-24W-4YE | 97511-5420M- 24W-4YE | \$ 1,471.00 | 10% | <i>\$1,333.83</i> |
| EW ResponsPLS NBDOnsite 5420M-48T-4YE | 97511-5420M- 48T-4YE | \$ 1,776.00 | 10% | <i>\$1,610.39</i> |
| EW ResponsPLS NBDOnsite 5420M-48W-4YE | 97511-5420M- 48W-4YE | \$ 1,930.00 | 10% | <i>\$1,750.03</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-12MW-36W | 97511-5520- 12MW-36W | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-24T | 97511-5520- 24T | \$ 1,604.00 | 10% | <i>\$1,454.43</i> |
| EW RESPONSEPLU NBD ON 5520-24T-ACDC-BASE | 97511-5520- 24T-ACDC- BASE | \$ 1,604.00 | 10% | <i>\$1,454.43</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-24T-BASE | 97511-5520- 24T-BASE | \$ 1,604.00 | 10% | <i>\$1,454.43</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-24W | 97511-5520- 24W | \$ 1,656.00 | 10% | <i>\$1,501.58</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-24X | 97511-5520- 24X | \$ 2,422.00 | 10% | <i>\$2,196.15</i> |
| EW RESPONSEPLU NBD ON 5520-24X-ACDC-BASE | 97511-5520- 24X-ACDC- BASE | \$ 2,422.00 | 10% | <i>\$2,196.15</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-24X-BASE | 97511-5520- 24X-BASE | \$ 2,422.00 | 10% | <i>\$2,196.15</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-48SE | 97511-5520- 48SE | \$ 2,291.00 | 10% | <i>\$2,077.36</i> |
| EW RESPONSEPL NBD ON 5520-48SE-ACDC-BASE | 97511-5520- 48SE-ACDC- BASE | \$ 2,291.00 | 10% | <i>\$2,077.36</i> |
| EW RESPONSEPLUS NBD ONSIT 5520-48SE-BASE | 97511-5520- 48SE-BASE | \$ 2,291.00 | 10% | <i>\$2,077.36</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-48T | 97511-5520- 48T | \$ 1,921.00 | 10% | <i>\$1,741.87</i> |
| EW RESPONSEPLU NBD ON 5520-48T-ACDC-BASE | 97511-5520- 48T-ACDC- BASE | \$ 1,921.00 | 10% | <i>\$1,741.87</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-48T-BASE | 97511-5520- 48T-BASE | \$ 1,921.00 | 10% | <i>\$1,741.87</i> |
| EW RESPONSEPLUS NBD ONSITE 5520-48W | 97511-5520- 48W | \$ 2,028.00 | 10% | <i>\$1,838.89</i> |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite 5720-24MW | 97511-5720- 24MW | \$ 1,837.00 | 10% | <i>\$1,665.70</i> |
| EW ResponsPLS NBDOnsite 5720-24MXW | 97511-5720- 24MXW | \$ 2,399.00 | 10% | <i>\$2,175.29</i> |
| EW ResponsPLS NBDOnsite 5720-48MW | 97511-5720- 48MW | \$ 2,053.00 | 10% | <i>\$1,861.56</i> |
| EW ResponsPLS NBDOnsite 5720-48MXW | 97511-5720- 48MXW | \$ 2,735.00 | 10% | <i>\$2,479.96</i> |
| EW ResponsPLS NBDOnsite 7520-48XT-6C | 97511-7520- 48XT-6C | \$ 3,136.00 | 10% | <i>\$2,843.57</i> |
| EW ResponsPLS NBDOnsit 7520-48XT-6C-AC-F | 97511-7520- 48XT-6C-AC- F | \$ 3,136.00 | 10% | <i>\$2,843.57</i> |
| EW ResponsPLS NBDOnsit 7520-48XT-6C-AC-R | 97511-7520- 48XT-6C-AC- R | \$ 3,136.00 | 10% | <i>\$2,843.57</i> |
| EW ResponsPLS NBDOnsite 7520-48Y-8C | 97511-7520- 48Y-8C | \$ 2,926.00 | 10% | <i>\$2,653.15</i> |
| EW ResponsPLS NBDOnsite 7520-48Y-8C-AC-F | 97511-7520- 48Y-8C-AC-F | \$ 2,926.00 | 10% | <i>\$2,653.15</i> |
| EW ResponsPLS NBDOnsite 7520-48Y-8C-AC-R | 97511-7520- 48Y-8C-AC-R | \$ 2,926.00 | 10% | <i>\$2,653.15</i> |
| EW RESPONSEPLUS NBD ONSITE 7520-48YE-8CE | 97511-7520- 48YE-8CE | \$ 3,392.00 | 10% | <i>\$3,075.70</i> |
| EW RESPONSEPLU NBDONS 7520-48YE-8CE-AC-F | 97511-7520- 48YE-8CE-AC- F | \$ 3,392.00 | 10% | <i>\$3,075.70</i> |
| EW RESPONSEPLU NBDONS 7520-48YE-8CE-AC-R | 97511-7520- 48YE-8CE-AC- R | \$ 3,392.00 | 10% | <i>\$3,075.70</i> |
| EW ResponsPLS NBDOnsite 7720-32C | 97511-7720- 32C | \$ 3,628.00 | 10% | <i>\$3,289.69</i> |
| EW ResponsPLS NBDOnsite 7720-32C-AC-F | 97511-7720- 32C-AC-F | \$ 3,628.00 | 10% | <i>\$3,289.69</i> |
| EW ResponsPLS NBDOnsite 7720-32C-AC-R | 97511-7720- 32C-AC-R | \$ 3,628.00 | 10% | <i>\$3,289.69</i> |
| EW ResponsPLS NBDOnsite 8520-48XT-6C | 97511-8520- 48XT-6C | \$ 3,882.00 | 10% | <i>\$3,520.00</i> |
| EW ResponsPLSNBDOnsite 8520-48XT-6C-AC-F | 97511-8520- 48XT-6C-AC- F | \$ 3,882.00 | 10% | <i>\$3,520.00</i> |

| | | | | |
|---|---------------------------------|--------------|-----|-------------|
| EW ResponsPLSNBDOnsite 8520-48XT-6C-AC-R | 97511-8520- 48XT-6C-AC- R | \$ 3,882.00 | 10% | \$3,520.00 |
| EW ResponsPLSNBDOnsite 8520-48XT-6C-DC-F | 97511-8520- 48XT-6C-DC- F | \$ 3,882.00 | 10% | \$3,520.00 |
| EW ResponsPLSNBDOnsite 8520-48XT-6C-DC-R | 97511-8520- 48XT-6C-DC- R | \$ 3,882.00 | 10% | \$3,520.00 |
| EW ResponsPLS NBDOnsite 8520-48Y-8C | 97511-8520- 48Y-8C | \$ 3,999.00 | 10% | \$3,626.09 |
| EW ResponsPLS NBDOnsite 8520-48Y-8C-AC-F | 97511-8520- 48Y-8C-AC-F | \$ 3,999.00 | 10% | \$3,626.09 |
| EW ResponsPLS NBDOnsite 8520-48Y-8C-AC-R | 97511-8520- 48Y-8C-AC-R | \$ 3,999.00 | 10% | \$3,626.09 |
| EW ResponsPLS NBDOnsite 8520-48Y-8C-DC-F | 97511-8520- 48Y-8C-DC-F | \$ 3,999.00 | 10% | \$3,626.09 |
| EW ResponsPLS NBDOnsite 8520-48Y-8C-DC-R | 97511-8520- 48Y-8C-DC-R | \$ 3,999.00 | 10% | \$3,626.09 |
| EW ResponsPLS NBDOnsite 8720-32C | 97511-8720- 32C | \$ 4,395.00 | 10% | \$3,985.17 |
| EW ResponsPLS NBDOnsite 8720-32C-AC-F | 97511-8720- 32C-AC-F | \$ 4,395.00 | 10% | \$3,985.17 |
| EW ResponsPLS NBDOnsite 8720-32C-AC-R | 97511-8720- 32C-AC-R | \$ 4,395.00 | 10% | \$3,985.17 |
| EW ResponsPLS NBDOnsite 8720-32C-DC-F | 97511-8720- 32C-DC-F | \$ 4,395.00 | 10% | \$3,985.17 |
| EW ResponsPLS NBDOnsite 8720-32C-DC-R | 97511-8720- 32C-DC-R | \$ 4,395.00 | 10% | \$3,985.17 |
| EW ResponsPLUS NBDOnsite- 8806 | 97511-8806 | \$ 4,322.00 | 10% | \$3,918.97 |
| EW ResponsPLS NBDOnsite- 8810 | 97511-8810 | \$ 8,416.00 | 10% | \$7,631.21 |
| EW ResponsPLS NBDOnsite 8820-40C | 97511-8820- 40C | \$ 12,401.00 | 10% | \$11,244.61 |
| EW ResponsPLS NBDOnsite 8820-40C-AC-F | 97511-8820- 40C-AC-F | \$ 12,401.00 | 10% | \$11,244.61 |
| EW ResponsPLS NBDOnsite 8820-40C-AC-R | 97511-8820- 40C-AC-R | \$ 12,401.00 | 10% | \$11,244.61 |
| EW ResponsPLS NBDOnsite 8820-40C-DC-F | 97511-8820- 40C-DC-F | \$ 12,401.00 | 10% | \$11,244.61 |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite 8820-40C-DC-R | 97511-8820- 40C-DC-R | \$ 12,401.00 | 10% | <i>\$11,244.61</i> |
| EW ResponsPLS NBDOnsite 8820-80C | 97511-8820- 80C | \$ 21,611.00 | 10% | <i>\$19,595.77</i> |
| EW ResponsPLS NBDOnsite 8820-80C-AC-F | 97511-8820- 80C-AC-F | \$ 21,611.00 | 10% | <i>\$19,595.77</i> |
| EW ResponsPLS NBDOnsite 8820-80C-AC-R | 97511-8820- 80C-AC-R | \$ 21,611.00 | 10% | <i>\$19,595.77</i> |
| EW ResponsPLS NBDOnsite 8820-80C-DC-F | 97511-8820- 80C-DC-F | \$ 21,611.00 | 10% | <i>\$19,595.77</i> |
| EW ResponsPLS NBDOnsite 8820-80C-DC-R | 97511-8820- 80C-DC-R | \$ 21,611.00 | 10% | <i>\$19,595.77</i> |
| EW ResponsPLS NBDOnsite 9920-16C | 97511-9920- 16C | \$ 10,637.00 | 10% | <i>\$9,645.10</i> |
| EW ResponsPLS NBDOnsite 9920-4D | 97511-9920-4D | \$ 10,637.00 | 10% | <i>\$9,645.10</i> |
| EW ResponsPLS NBDOnsite 9920-NPB-8 | 97511-9920- NPB-8 | \$ 16,805.00 | 10% | <i>\$15,237.93</i> |
| EW ResponsePLS NBDOnsite AH-AP-1130-AC-C | 97511-AH-AP- 1130-AC-CE | \$ 390.00 | 10% | <i>\$353.63</i> |
| EW ResponsePLS NBDOnsite AH-AP-1130-AC-F | 97511-AH-AP- 1130-AC-FCC | \$ 390.00 | 10% | <i>\$353.63</i> |
| EW ResponsePLS NBDOnsite AH-AP-1130-AC-W | 97511-AH-AP- 1130-AC-W | \$ 390.00 | 10% | <i>\$353.63</i> |
| EW ResponsePLS NBDOnsite AH-AP-122-AC-CA | 97511-AH-AP- 122-AC-CAN | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW ResponsePLS NBDOnsite AH-AP-122-AC-CE | 97511-AH-AP- 122-AC-CE | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW ResponsePLS NBDOnsite AH-AP-122-AC-FC | 97511-AH-AP- 122-AC-FCC | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW ResponsePLS NBDOnsite AH-AP-122-AC-W | 97511-AH-AP- 122-AC-W | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW ResponsePLS NBDOnsite AH-AP-130-AC-CE | 97511-AH-AP- 130-AC-CE | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW ResponsePLS NBDOnsite AH-AP-130-AC-FC | 97511-AH-AP- 130-AC-FCC | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW ResponsePLS NBDOnsite AH-AP-130-AC-W | 97511-AH-AP- 130-AC-W | \$ 356.00 | 10% | <i>\$322.80</i> |
| EW ResponsePLS NBDOnsite AH-AP-150W-AC-C | 97511-AH-AP- 150W-AC- CAN | \$ 356.00 | 10% | <i>\$322.80</i> |

| | | | | |
|---|---------------------------------|-----------|-----|----------|
| EW ResponsePLS NBDOnsite AH-AP-150W-AC-C | 97511-AH-AP- 150W-AC-CE | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-150W-AC-F | 97511-AH-AP- 150W-AC-FCC | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-150W-AC-W | 97511-AH-AP- 150W-AC-W | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-230-AC-CE | 97511-AH-AP- 230-AC-CE | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-230-AC-FC | 97511-AH-AP- 230-AC-FCC | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-230-AC-W | 97511-AH-AP- 230-AC-W | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-250-AC-CA | 97511-AH-AP- 250-AC-CAN | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-250-AC-CE | 97511-AH-AP- 250-AC-CE | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-250-AC-FC | 97511-AH-AP- 250-AC-FCC | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-250-AC-W | 97511-AH-AP- 250-AC-W | \$ 356.00 | 10% | \$322.80 |
| EW ResponsePLS NBDOnsite AH-AP-630-AX-CA | 97511-AH-AP- 630-AX-CAN | \$ 395.00 | 10% | \$358.17 |
| EW ResponsePLS NBDOnsite AH-AP-630-AX-CE | 97511-AH-AP- 630-AX-CE | \$ 395.00 | 10% | \$358.17 |
| EW ResponsePLS NBDOnsite AH-AP-630-AX-FC | 97511-AH-AP- 630-AX-FCC | \$ 395.00 | 10% | \$358.17 |
| EW ResponsePLS NBDOnsite AH-AP-630-AX-W | 97511-AH-AP- 630-AX-W | \$ 395.00 | 10% | \$358.17 |
| EW ResponsePLS NBDOnsite AH-AP-650-AX-CA | 97511-AH-AP- 650-AX-CAN | \$ 347.00 | 10% | \$314.64 |
| EW ResponsePLS NBDOnsite AH-AP-650-AX-CE | 97511-AH-AP- 650-AX-CE | \$ 347.00 | 10% | \$314.64 |
| EW ResponsePLS NBDOnsite AH-AP-650-AX-FC | 97511-AH-AP- 650-AX-FCC | \$ 347.00 | 10% | \$314.64 |
| EW ResponsePLS NBDOnsite AH-AP-650-AX-W | 97511-AH-AP- 650-AX-W | \$ 347.00 | 10% | \$314.64 |
| EW ResponsePLS NBDOnsite AH-AP-650X-AX-C | 97511-AH-AP- 650X-AX- CAN | \$ 347.00 | 10% | \$314.64 |
| EW ResponsePLS NBDOnsite AH-AP-650X-AX-C | 97511-AH-AP- 650X-AX-CE | \$ 347.00 | 10% | \$314.64 |

| | | | | |
|---|-----------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBDOnsite AH-AP-650X-AX-F | 97511-AH-AP- 650X-AX-FCC | \$ 347.00 | 10% | <i>\$314.64</i> |
| EW ResponsePLS NBDOnsite AH-AP-650X-AX-W | 97511-AH-AP- 650X-AX-W | \$ 347.00 | 10% | <i>\$314.64</i> |
| EW ResponsePLS NBDOnsite AH-ATOM-CAN | 97511-AH- ATOM-CAN | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsePLS NBDOnsite AH-ATOM-CE-EU | 97511-AH- ATOM-CE-EU | \$ 393.00 | 10% | <i>\$356.35</i> |
| EW ResponsePLS NBDOnsite AH-ATOM-CE-UK | 97511-AH- ATOM-CE-UK | \$ 393.00 | 10% | <i>\$356.35</i> |
| EW ResponsePLS NBDOnsite AH-ATOM-FCC | 97511-AH- ATOM-FCC | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsePLS NBDOnsite AH-ATOM-W | 97511-AH- ATOM-W | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsePLS NBDOnsite AH-ATOM-W-EU | 97511-AH- ATOM-W-EU | \$ 393.00 | 10% | <i>\$356.35</i> |
| EW ResponsePLS NBDOnsite AH-ATOM-W-UK | 97511-AH- ATOM-W-UK | \$ 393.00 | 10% | <i>\$356.35</i> |
| EW ResponsePLS NBDOnsite AH-SR-2208P-AU | 97511-AH-SR- 2208P-AU | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-SR-2208P-EU | 97511-AH-SR- 2208P-EU | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-SR-2208P-NA | 97511-AH-SR- 2208P-NA | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-SR-2208P-UK | 97511-AH-SR- 2208P-UK | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-SR-2224P-AU | 97511-AH-SR- 2224P-AU | \$ 1,145.00 | 10% | <i>\$1,038.23</i> |
| EW ResponsePLS NBDOnsite AH-SR-2224P-EU | 97511-AH-SR- 2224P-EU | \$ 1,145.00 | 10% | <i>\$1,038.23</i> |
| EW ResponsePLS NBDOnsite AH-SR-2224P-NA | 97511-AH-SR- 2224P-NA | \$ 1,145.00 | 10% | <i>\$1,038.23</i> |
| EW ResponsePLS NBDOnsite AH-SR-2224P-UK | 97511-AH-SR- 2224P-UK | \$ 1,145.00 | 10% | <i>\$1,038.23</i> |
| EW ResponsePLS NBDOnsite AH-SR-2324P-AU | 97511-AH-SR- 2324P-AU | \$ 1,185.00 | 10% | <i>\$1,074.50</i> |
| EW ResponsePLS NBDOnsite AH-SR-2324P-EU | 97511-AH-SR- 2324P-EU | \$ 1,185.00 | 10% | <i>\$1,074.50</i> |
| EW ResponsePLS NBDOnsite AH-SR-2324P-NA | 97511-AH-SR- 2324P-NA | \$ 1,185.00 | 10% | <i>\$1,074.50</i> |

| | | | | |
|--|---------------------------------|-------------|-----|-------------------|
| EW ResponsePLS NBDOnsite AH-SR-2324P-UK | 97511-AH-SR- 2324P-UK | \$ 1,185.00 | 10% | <i>\$1,074.50</i> |
| EW ResponsePLS NBDOnsite AH-SR-2348P-AU | 97511-AH-SR- 2348P-AU | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBDOnsite AH-SR-2348P-EU | 97511-AH-SR- 2348P-EU | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBDOnsite AH-SR-2348P-NA | 97511-AH-SR- 2348P-NA | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBDOnsite AH-SR-2348P-UK | 97511-AH-SR- 2348P-UK | \$ 1,322.00 | 10% | <i>\$1,198.72</i> |
| EW ResponsePLS NBDOnsite AH-XR200P-AU | 97511-AH- XR200P-AU | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-XR200P-EU | 97511-AH- XR200P-EU | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-XR200P-UK | 97511-AH- XR200P-UK | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-XR200P-US | 97511-AH- XR200P-US | \$ 1,109.00 | 10% | <i>\$1,005.59</i> |
| EW ResponsePLS NBDOnsite AH-XR600P | 97511-AH- XR600P | \$ 1,115.00 | 10% | <i>\$1,011.03</i> |
| EW ResponsePLS NBDOnsite AH-XR600P-AU | 97511-AH- XR600P-AU | \$ 1,119.00 | 10% | <i>\$1,014.65</i> |
| EW ResponsePLS NBDOnsite AH-XR600P-EU | 97511-AH- XR600P-EU | \$ 1,119.00 | 10% | <i>\$1,014.65</i> |
| EW ResponsePLS NBDOnsite AH-XR600P-KR | 97511-AH- XR600P-KR | \$ 1,119.00 | 10% | <i>\$1,014.65</i> |
| EW ResponsePLS NBDOnsite AH-XR600P-UK | 97511-AH- XR600P-UK | \$ 1,119.00 | 10% | <i>\$1,014.65</i> |
| EW ResponsePLS NBDOnsite AH-XR600P-US | 97511-AH- XR600P-US | \$ 1,119.00 | 10% | <i>\$1,014.65</i> |
| EW ResponsPLS NBDOnsite AP- 8533-IL | 97511-AP- 8533-68SB30- IL | \$ 465.00 | 10% | <i>\$421.64</i> |
| EW ResponsPLS NBDOnsite AP3000-IL | 97511-AP3000- IL | \$ 259.74 | 10% | <i>\$235.52</i> |
| EW ResponsPLS NBDOnsite AP3000-TN | 97511-AP3000- TN | \$ 259.74 | 10% | <i>\$235.52</i> |
| EW ResponsPLS NBDOnsite AP3000-WW | 97511-AP3000- WW | \$ 259.74 | 10% | <i>\$235.52</i> |
| EW ResponsPLS NBDOnsite AP3000X-WW | 97511- AP3000X-WW | \$ 275.99 | 10% | <i>\$250.25</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite AP302W-CAN | 97511- AP302W-CAN | \$ 359.00 | 10% | \$325.52 |
| EW ResponsPLS NBDOnsite AP302W-EG | 97511- AP302W-EG | \$ 261.00 | 10% | \$236.66 |
| EW ResponsPLS NBDOnsite AP302W-FCC | 97511- AP302W-FCC | \$ 359.00 | 10% | \$325.52 |
| EW ResponsPLS NBDOnsite AP302W-WR | 97511- AP302W-WR | \$ 342.00 | 10% | \$310.11 |
| EW ResponsePLS NBDOnsite AP305C-1-CAN | 97511-AP305C- 1-CAN | \$ 355.00 | 10% | \$321.90 |
| EW ResponsePLS NBDOnsite AP305C-1-EG | 97511-AP305C- 1-EG | \$ 355.00 | 10% | \$321.90 |
| EW ResponsePLS NBDOnsite AP305C-1-FCC | 97511-AP305C- 1-FCC | \$ 355.00 | 10% | \$321.90 |
| EW ResponsePLS NBDOnsite AP305C-1-IL | 97511-AP305C- 1-IL | \$ 355.00 | 10% | \$321.90 |
| EW ResponsePLS NBDOnsite AP305C-1-WR | 97511-AP305C- 1-WR | \$ 355.00 | 10% | \$321.90 |
| EW ResponsePLS NBDOnsite AP305C-CAN | 97511-AP305C- CAN | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305C-EG | 97511-AP305C- EG | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305C-FCC | 97511-AP305C- FCC | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305C-IL | 97511-AP305C- IL | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305C-WR | 97511-AP305C- WR | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305CX-CAN | 97511- AP305CX- CAN | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305CX-FCC | 97511- AP305CX- FCC | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305CX-IL | 97511- AP305CX-IL | \$ 382.00 | 10% | \$346.38 |
| EW ResponsePLS NBDOnsite AP305CX-WR | 97511- AP305CX-WR | \$ 382.00 | 10% | \$346.38 |
| EW ResponsPLS NBDOnsite AP310e-1-WR | 97511-AP310e- 1-WR | \$ 348.00 | 10% | \$315.55 |

| | | | | |
|--|------------------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite AP310e-CAN | 97511-AP310e- CAN | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP310e-FCC | 97511-AP310e- FCC | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP310e-IL | 97511-AP310e- IL | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP310e-WR | 97511-AP310e- WR | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP310i-1-WR | 97511-AP310i- 1-WR | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsPLS NBDOnsite AP310i-CAN | 97511-AP310i- CAN | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP310i-FCC | 97511-AP310i- FCC | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP310i-IL | 97511-AP310i- IL | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP310i-WR | 97511-AP310i- WR | \$ 365.00 | 10% | <i>\$330.96</i> |
| EW ResponsPLS NBDOnsite AP360e-CAN | 97511-AP360e- CAN | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS NBDOnsite AP360e-FCC | 97511-AP360e- FCC | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS NBDOnsite AP360e-IL | 97511-AP360e- IL | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS NBDOnsite AP360e-WR | 97511-AP360e- WR | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS NBDOnsite AP360i-CAN | 97511-AP360i- CAN | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS NBDOnsite AP360i-FCC | 97511-AP360i- FCC | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS NBDOnsite AP360i-WR | 97511-AP360i- WR | \$ 386.00 | 10% | <i>\$350.01</i> |
| EW ResponsPLS NBDOnsite AP4000-WW | 97511-AP4000- 1-WW | \$ 332.00 | 10% | <i>\$301.04</i> |
| EW ResponsPLS NBDOnsite AP4000-IL | 97511-AP4000- IL | \$ 332.00 | 10% | <i>\$301.04</i> |
| EW ResponsPLS NBDOnsite AP4000-WW | 97511-AP4000- WW | \$ 332.00 | 10% | <i>\$301.04</i> |
| EW ResponsePLS NBDOnsite AP410C-1-CAN | 97511-AP410C- 1-CAN | \$ 348.00 | 10% | <i>\$315.55</i> |

| | | | | |
|--|------------------------|-----------|-----|-----------------|
| EW ResponsePLS NBDOnsite AP410C-1-EG | 97511-AP410C- 1-EG | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBDOnsite AP410C-1-FCC | 97511-AP410C- 1-FCC | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBDOnsite AP410C-1-IL | 97511-AP410C- 1-IL | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBDOnsite AP410C-1-WR | 97511-AP410C- 1-WR | \$ 348.00 | 10% | <i>\$315.55</i> |
| EW ResponsePLS NBDOnsite AP410C-CAN | 97511-AP410C- CAN | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsePLS NBDOnsite AP410C-EG | 97511-AP410C- EG | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsePLS NBDOnsite AP410C-FCC | 97511-AP410C- FCC | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsePLS NBDOnsite AP410C-IL | 97511-AP410C- IL | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsePLS NBDOnsite AP410C-WR | 97511-AP410C- WR | \$ 374.00 | 10% | <i>\$339.12</i> |
| EW ResponsPLS NBDOnsite AP410e-CAN | 97511-AP410e- CAN | \$ 390.00 | 10% | <i>\$353.63</i> |
| EW ResponsPLS NBDOnsite AP410e-FCC | 97511-AP410e- FCC | \$ 390.00 | 10% | <i>\$353.63</i> |
| EW ResponsPLS NBDOnsite AP410e-WR | 97511-AP410e- WR | \$ 390.00 | 10% | <i>\$353.63</i> |
| EW ResponsPLS NBDOnsite AP410i-1-FCC | 97511-AP410i- 1-FCC | \$ 372.00 | 10% | <i>\$337.31</i> |
| EW ResponsPLS NBDOnsite AP410i-1-WR | 97511-AP410i- 1-WR | \$ 372.00 | 10% | <i>\$337.31</i> |
| EW ResponsPLS NBDOnsite AP410i-CAN | 97511-AP410i- CAN | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite AP410i-FCC | 97511-AP410i- FCC | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite AP410i-IL | 97511-AP410i- IL | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite AP410i-WR | 97511-AP410i- WR | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsePLS NBDOnsite AP460C-CAN | 97511-AP460C- CAN | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460C-EG | 97511-AP460C- EG | \$ 402.00 | 10% | <i>\$364.51</i> |

| | | | | |
|---|-----------------------------|-----------|-----|-----------------|
| EW ResponsePLS NBDOnsite AP460C-FCC | 97511-AP460C- FCC | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460C-IL | 97511-AP460C- IL | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460C-WR | 97511-AP460C- WR | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsPLS NBDOnsite AP460e-CAN | 97511-AP460e- CAN | \$ 405.00 | 10% | <i>\$367.23</i> |
| EW ResponsPLS NBDOnsite AP460e-FCC | 97511-AP460e- FCC | \$ 405.00 | 10% | <i>\$367.23</i> |
| EW ResponsPLS NBDOnsite AP460e-WR | 97511-AP460e- WR | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsPLS NBDOnsite AP460i-CAN | 97511-AP460i- CAN | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsPLS NBDOnsite AP460i-FCC | 97511-AP460i- FCC | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsPLS NBDOnsite AP460i-IL | 97511-AP460i- IL | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsPLS NBDOnsite AP460i-WR | 97511-AP460i- WR | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW ResponsePLS NBDOnsite AP460S12C-CAN | 97511- AP460S12C- CAN | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460S12C-FCC | 97511- AP460S12C- FCC | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460S12C-WR | 97511- AP460S12C- WR | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460S6C-CAN | 97511- AP460S6C- CAN | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460S6C-FCC | 97511- AP460S6C- FCC | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsePLS NBDOnsite AP460S6C-WR | 97511- AP460S6C- WR | \$ 402.00 | 10% | <i>\$364.51</i> |
| EW ResponsPLS NBDOnsite AP5010-IL | 97511-AP5010- IL | \$ 353.00 | 10% | <i>\$320.08</i> |
| EW ResponsPLS NBDOnsite AP5010-WW | 97511-AP5010- WW | \$ 353.00 | 10% | <i>\$320.08</i> |

| | | | | |
|---|---------------------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite AP5020-WW | 97511-AP5020- WW | \$ 357.18 | 6% | \$338.27 |
| EW ResponsPLS NBDOnsite AP5050D-WW | 97511- AP5050D-WW | \$ 511.00 | 10% | \$463.35 |
| EW ResponsPLS NBDOnsite AP5050U-WW | 97511- AP5050U-WW | \$ 443.00 | 10% | \$401.69 |
| EW ResponsPLS NBDOnsite AP505i-FCC | 97511-AP505i- FCC | \$ 385.00 | 10% | \$349.10 |
| EW ResponsPLS NBDOnsite AP505i-FCC-TAA | 97511-AP505i- FCC-TAA | \$ 385.00 | 10% | \$349.10 |
| EW ResponsPLS NBDOnsite AP505i-WR | 97511-AP505i- WR | \$ 404.00 | 10% | \$366.33 |
| EW ResponsePLS NBDOnsite AP510C-CAN | 97511-AP510C- CAN | \$ 340.00 | 10% | \$308.30 |
| EW ResponsePLS NBDOnsite AP510C-CE | 97511-AP510C- CE | \$ 340.00 | 10% | \$308.30 |
| EW ResponsePLS NBDOnsite AP510C-FCC | 97511-AP510C- FCC | \$ 340.00 | 10% | \$308.30 |
| EW ResponsePLS NBDOnsite AP510C-W | 97511-AP510C- W | \$ 340.00 | 10% | \$308.30 |
| EW ResponsPLS NBDOnsite AP510C-WW | 97511-AP510C- WW | \$ 450.00 | 10% | \$408.04 |
| EW ResponsePLS NBDOnsite AP510CX-CAN | 97511- AP510CX- CAN | \$ 340.00 | 10% | \$308.30 |
| EW ResponsePLS NBDOnsite AP510CX-CE | 97511- AP510CX- CE | \$ 340.00 | 10% | \$308.30 |
| EW ResponsePLS NBDOnsite AP510CX-FCC | 97511- AP510CX- FCC | \$ 340.00 | 10% | \$308.30 |
| EW ResponsePLS NBDOnsite AP510CX-W | 97511- AP510CX- W | \$ 340.00 | 10% | \$308.30 |
| EW ResponsPLS NBDOnsite AP510CX-WW | 97511- AP510CX- WW | \$ 450.00 | 10% | \$408.04 |
| EW ResponsPLS NBDOnsite AP510e-FCC | 97511-AP510e- FCC | \$ 435.00 | 10% | \$394.44 |
| EW ResponsPLS NBDOnsite AP510e-FCC-TAA | 97511-AP510e- FCC-TAA | \$ 435.00 | 10% | \$394.44 |
| EW ResponsPLS NBDOnsite AP510e-WR | 97511-AP510e- WR | \$ 415.00 | 10% | \$376.30 |

| | | | | |
|---|--------------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite AP510i-1-FCC | 97511-AP510i- 1-FCC | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsPLS NBDOnsite AP510i-1-WR | 97511-AP510i- 1-WR | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW ResponsPLS NBDOnsite AP510i-FCC | 97511-AP510i- FCC | \$ 417.00 | 10% | <i>\$378.11</i> |
| EW ResponsPLS NBDOnsite AP510i-FCC-TAA | 97511-AP510i- FCC-TAA | \$ 417.00 | 10% | <i>\$378.11</i> |
| EW ResponsPLS NBDOnsite AP510i-WR | 97511-AP510i- WR | \$ 417.00 | 10% | <i>\$378.11</i> |
| EW ResponsPLS NBDOnsite AP560h-FCC | 97511-AP560h- FCC | \$ 599.00 | 10% | <i>\$543.14</i> |
| EW ResponsPLS NBDOnsite AP560h-WR | 97511-AP560h- WR | \$ 599.00 | 10% | <i>\$543.14</i> |
| EW ResponsPLS NBDOnsite AP560i-FCC | 97511-AP560i- FCC | \$ 518.00 | 10% | <i>\$469.70</i> |
| EW ResponsPLS NBDOnsite AP560i-WR | 97511-AP560i- WR | \$ 494.00 | 10% | <i>\$447.93</i> |
| EW ResponsPLS NBDOnsite AP560m-FCC | 97511-AP560m- FCC | \$ 518.00 | 10% | <i>\$469.70</i> |
| EW ResponsPLS NBDOnsite AP560t-FCC | 97511-AP560t- FCC | \$ 599.00 | 10% | <i>\$543.14</i> |
| EW ResponsPLS NBDOnsite AP560u-FCC | 97511-AP560u- FCC | \$ 482.00 | 10% | <i>\$437.05</i> |
| EW ResponsPLS NBDOnsite E2122 | 97511-E2122 | \$ 6,196.00 | 10% | <i>\$5,618.22</i> |
| EW ResponsPLS NBDOnsite E2122-1 | 97511-E2122-1 | \$ 5,872.00 | 10% | <i>\$5,324.44</i> |
| EW ResponsPLS NBDOnsite E3120-1 | 97511-E3120-1 | \$ 8,923.00 | 10% | <i>\$8,090.93</i> |
| EW ResponsPLS NBDOnsite E3125 | 97511-E3125 | \$ 9,945.00 | 10% | <i>\$9,017.63</i> |
| EW ResponsPLS NBDOnsite- H30131 | 97511-H30131 | \$ 2,513.00 | 10% | <i>\$2,278.66</i> |
| EW ResponsPLS NBDOnsite- H30132 | 97511-H30132 | \$ 2,463.00 | 10% | <i>\$2,233.33</i> |
| EW ResponsPLS NBDOnsite- H30133 | 97511-H30133 | \$ 4,606.00 | 10% | <i>\$4,176.49</i> |
| EW ResponsPLS NBDOnsite- H30134 | 97511-H30134 | \$ 5,520.00 | 10% | <i>\$5,005.26</i> |
| EW ResponsPLS NBDOnsite- H30135 | 97511-H30135 | \$ 4,696.00 | 10% | <i>\$4,258.10</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-H30136 | 97511-H30136 | \$ 5,520.00 | 10% | <i>\$5,005.26</i> |
| EW ResponsPLS NBDOnsite-H30184 | 97511-H30184 | \$ 1,261.00 | 10% | <i>\$1,143.41</i> |
| EW ResponsPLS NBDOnsite-H30185 | 97511-H30185 | \$ 1,547.00 | 10% | <i>\$1,402.74</i> |
| EW ResponsPLS NBDOnsite-H30186 | 97511-H30186 | \$ 1,390.00 | 10% | <i>\$1,260.38</i> |
| EW ResponsPLS NBDOnsite-H30187 | 97511-H30187 | \$ 1,374.00 | 10% | <i>\$1,245.87</i> |
| EW ResponsPLS NBDOnsite-H30188 | 97511-H30188 | \$ 1,390.00 | 10% | <i>\$1,260.38</i> |
| EW ResponsPLS NBDOnsite-H30189 | 97511-H30189 | \$ 1,390.00 | 10% | <i>\$1,260.38</i> |
| EW ResponsPLS NBDOnsite-H30190 | 97511-H30190 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30214 | 97511-H30214 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsPLS NBDOnsite-H30215 | 97511-H30215 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsPLS NBDOnsite-H30216 | 97511-H30216 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30217 | 97511-H30217 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30218 | 97511-H30218 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30219 | 97511-H30219 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30220 | 97511-H30220 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30221 | 97511-H30221 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30222 | 97511-H30222 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30223 | 97511-H30223 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30224 | 97511-H30224 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30225 | 97511-H30225 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30226 | 97511-H30226 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-H30227 | 97511-H30227 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30228 | 97511-H30228 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30229 | 97511-H30229 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30267 | 97511-H30267 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30268 | 97511-H30268 | \$ 1,652.00 | 10% | <i>\$1,497.95</i> |
| EW ResponsPLS NBDOnsite-H30269 | 97511-H30269 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30270 | 97511-H30270 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30271 | 97511-H30271 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30272 | 97511-H30272 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30273 | 97511-H30273 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsPLS NBDOnsite-H30274 | 97511-H30274 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsPLS NBDOnsite-H30275 | 97511-H30275 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30276 | 97511-H30276 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |
| EW ResponsPLS NBDOnsite-H30277 | 97511-H30277 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsPLS NBDOnsite-H30278 | 97511-H30278 | \$ 2,114.00 | 10% | <i>\$1,916.87</i> |
| EW ResponsPLS NBDOnsite-H30279 | 97511-H30279 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsPLS NBDOnsite-H30280 | 97511-H30280 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsPLS NBDOnsite-H30281 | 97511-H30281 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsPLS NBDOnsite-H30282 | 97511-H30282 | \$ 2,041.00 | 10% | <i>\$1,850.68</i> |
| EW ResponsPLS NBDOnsite-H30283 | 97511-H30283 | \$ 1,674.00 | 10% | <i>\$1,517.90</i> |
| EW ResponsPLS NBDOnsite-H30284 | 97511-H30284 | \$ 1,841.00 | 10% | <i>\$1,669.33</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-H30296 | 97511-H30296 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsPLS NBDOnsite-H30297 | 97511-H30297 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsPLS NBDOnsite-H30298 | 97511-H30298 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsPLS NBDOnsite-H30299 | 97511-H30299 | \$ 1,485.00 | 10% | <i>\$1,346.52</i> |
| EW ResponsPLS NBDOnsite-H30381 | 97511-H30381 | \$ 2,618.00 | 10% | <i>\$2,373.87</i> |
| EW ResponsPLS NBDOnsite-H30384 | 97511-H30384 | \$ 2,519.00 | 10% | <i>\$2,284.10</i> |
| EW ResponsPLS NBDOnsite-H30391 | 97511-H30391 | \$ 1,332.00 | 10% | <i>\$1,207.79</i> |
| EW ResponsPLS NBDOnsite-H30392 | 97511-H30392 | \$ 1,332.00 | 10% | <i>\$1,207.79</i> |
| EW ResponsPLS NBDOnsite-H30393 | 97511-H30393 | \$ 823.00 | 10% | <i>\$746.26</i> |
| EW ResponsPLS NBDOnsite-H30394 | 97511-H30394 | \$ 2,176.00 | 10% | <i>\$1,973.09</i> |
| EW ResponsPLS NBDOnsite-H30395 | 97511-H30395 | \$ 2,513.00 | 10% | <i>\$2,278.66</i> |
| EW ResponsPLS NBDOnsite-H30396 | 97511-H30396 | \$ 2,322.00 | 10% | <i>\$2,105.47</i> |
| EW ResponsPLS NBDOnsite-H30397 | 97511-H30397 | \$ 2,683.00 | 10% | <i>\$2,432.81</i> |
| EW ResponsPLS NBDOnsite-H30398 | 97511-H30398 | \$ 840.00 | 10% | <i>\$761.67</i> |
| EW ResponsPLS NBDOnsite-H30400 | 97511-H30400 | \$ 650.00 | 10% | <i>\$589.39</i> |
| EW ResponsPLS NBDOnsite-H30401 | 97511-H30401 | \$ 749.00 | 10% | <i>\$679.16</i> |
| EW ResponsPLS NBDOnsite-H30402 | 97511-H30402 | \$ 760.00 | 10% | <i>\$689.13</i> |
| EW ResponsPLS NBDOnsite-H30403 | 97511-H30403 | \$ 928.00 | 10% | <i>\$841.46</i> |
| EW ResponsPLS NBDOnsite-H30480 | 97511-H30480 | \$ 2,690.00 | 10% | <i>\$2,439.16</i> |
| EW ResponsPLS NBDOnsite-H30495 | 97511-H30495 | \$ 3,477.00 | 10% | <i>\$3,152.77</i> |
| EW ResponsPLS NBDOnsite-H30496 | 97511-H30496 | \$ 3,411.00 | 10% | <i>\$3,092.92</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|------------|
| EW ResponsPLS NBDOnsite-H30497 | 97511-H30497 | \$ 4,072.00 | 10% | \$3,692.29 |
| EW ResponsPLS NBDOnsite-H30498 | 97511-H30498 | \$ 3,995.00 | 10% | \$3,622.47 |
| EW ResponsPLS NBDOnsite-H30499 | 97511-H30499 | \$ 1,083.00 | 10% | \$982.01 |
| EW ResponsPLS NBDOnsite-H30501 | 97511-H30501 | \$ 3,995.00 | 10% | \$3,622.47 |
| EW ResponsPLS NBDOnsite-H30502 | 97511-H30502 | \$ 5,018.00 | 10% | \$4,550.07 |
| EW ResponsPLS NBDOnsite-H30503 | 97511-H30503 | \$ 1,083.00 | 10% | \$982.01 |
| EW ResponsPLS NBDOnsite-H30505 | 97511-H30505 | \$ 5,552.00 | 10% | \$5,034.28 |
| EW ResponsPLS NBDOnsite-H30506 | 97511-H30506 | \$ 6,792.00 | 10% | \$6,158.65 |
| EW ResponsPLS NBDOnsite-H30509 | 97511-H30509 | \$ 5,018.00 | 10% | \$4,550.07 |
| EW ResponsPLS NBDOnsite-H30510 | 97511-H30510 | \$ 5,552.00 | 10% | \$5,034.28 |
| EW ResponsPLS NBDOnsite-H30511 | 97511-H30511 | \$ 6,792.00 | 10% | \$6,158.65 |
| EW ResponsPLS NBDOnsite-H30512 | 97511-H30512 | \$ 1,083.00 | 10% | \$982.01 |
| EW ResponsPLS NBDOnsite-H30513 | 97511-H30513 | \$ 1,529.00 | 10% | \$1,386.42 |
| EW ResponsPLS NBDOnsite-H30525 | 97511-H30525 | \$ 5,115.00 | 10% | \$4,638.03 |
| EW ResponsPLS NBDOnsite-H30526 | 97511-H30526 | \$ 3,880.00 | 10% | \$3,518.19 |
| EW ResponsPLS NBDOnsite-H30528 | 97511-H30528 | \$ 5,875.00 | 10% | \$5,327.16 |
| EW ResponsPLS NBDOnsite-H30531 | 97511-H30531 | \$ 8,177.00 | 10% | \$7,414.49 |
| EW ResponsPLS NBDOnsite-H30532 | 97511-H30532 | \$ 8,177.00 | 10% | \$7,414.49 |
| EW ResponsPLS NBDOnsite-H30534 | 97511-H30534 | \$ 8,336.00 | 10% | \$7,558.67 |
| EW ResponsPLS NBDOnsite-H30535 | 97511-H30535 | \$ 8,853.00 | 10% | \$8,027.46 |
| EW ResponsPLS NBDOnsite-H30536 | 97511-H30536 | \$ 8,177.00 | 10% | \$7,414.49 |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite-H30537 | 97511-H30537 | \$ 8,853.00 | 10% | <i>\$8,027.46</i> |
| EW ResponsPLS NBDOnsite-H30538 | 97511-H30538 | \$ 5,115.00 | 10% | <i>\$4,638.03</i> |
| EW ResponsPLS NBDOnsite-H30539 | 97511-H30539 | \$ 9,455.00 | 10% | <i>\$8,573.32</i> |
| EW ResponsPLS NBDOnsite-H30540 | 97511-H30540 | \$ 9,746.00 | 10% | <i>\$8,837.19</i> |
| EW ResponsPLS NBDOnsite-H30543 | 97511-H30543 | \$ 1,062.00 | 10% | <i>\$962.97</i> |
| EW ResponsPLS NBDOnsite-H30544 | 97511-H30544 | \$ 1,557.00 | 10% | <i>\$1,411.81</i> |
| EW ResponsPLS NBDOnsite-H30548 | 97511-H30548 | \$ 1,062.00 | 10% | <i>\$962.97</i> |
| EW ResponsPLS NBDOnsite-H30549 | 97511-H30549 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW ResponsPLS NBDOnsite-H30550 | 97511-H30550 | \$ 1,499.00 | 10% | <i>\$1,359.22</i> |
| EW ResponsPLS NBDOnsite-H30552 | 97511-H30552 | \$ 1,062.00 | 10% | <i>\$962.97</i> |
| EW ResponsPLS NBDOnsite-H30553 | 97511-H30553 | \$ 1,429.00 | 10% | <i>\$1,295.75</i> |
| EW ResponsPLS NBDOnsite-H30569 | 97511-H30569 | \$ 4,606.00 | 10% | <i>\$4,176.49</i> |
| EW ResponsPLS NBDOnsite-H30570 | 97511-H30570 | \$ 5,313.00 | 10% | <i>\$4,817.56</i> |
| EW ResponsPLS NBDOnsite-H30571 | 97511-H30571 | \$ 5,313.00 | 10% | <i>\$4,817.56</i> |
| EW ResponsPLS NBDOnsite-H30573 | 97511-H30573 | \$ 4,606.00 | 10% | <i>\$4,176.49</i> |
| EW ResponsPLS NBDOnsite-H30574 | 97511-H30574 | \$ 4,991.00 | 10% | <i>\$4,525.59</i> |
| EW ResponsPLS NBDOnsite-H30575 | 97511-H30575 | \$ 3,540.00 | 10% | <i>\$3,209.90</i> |
| EW ResponsPLS NBDOnsite-H30576 | 97511-H30576 | \$ 4,606.00 | 10% | <i>\$4,176.49</i> |
| EW ResponsPLS NBDOnsite-H30577 | 97511-H30577 | \$ 5,212.00 | 10% | <i>\$4,725.98</i> |
| EW ResponsPLS NBDOnsite-H30578 | 97511-H30578 | \$ 5,212.00 | 10% | <i>\$4,725.98</i> |
| EW ResponsPLS NBDOnsite-H30587 | 97511-H30587 | \$ 3,956.00 | 10% | <i>\$3,587.10</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|------------|
| EW ResponsPLS NBDOnsite-H30588 | 97511-H30588 | \$ 2,867.00 | 10% | \$2,599.65 |
| EW ResponsPLS NBDOnsite-H30589 | 97511-H30589 | \$ 4,221.00 | 10% | \$3,827.39 |
| EW ResponsPLS NBDOnsite-H30632 | 97511-H30632 | \$ 427.00 | 10% | \$387.18 |
| EW ResponsPLS NBDOnsite-H30633 | 97511-H30633 | \$ 427.00 | 10% | \$387.18 |
| EW ResponsPLS NBDOnsite-H30643 | 97511-H30643 | \$ 8,451.00 | 10% | \$7,662.94 |
| EW ResponsPLS NBDOnsite-H30706 | 97511-H30706 | \$ 5,987.00 | 10% | \$5,428.71 |
| EW ResponsPLS NBDOnsite-H30707 | 97511-H30707 | \$ 3,880.00 | 10% | \$3,518.19 |
| EW ResponsPLS NBDOnsite-H30724 | 97511-H30724 | \$ 704.00 | 10% | \$638.35 |
| EW ResponsPLS NBDOnsite-H30725 | 97511-H30725 | \$ 2,463.00 | 10% | \$2,233.33 |
| EW ResponsPLS NBDOnsite-H30726 | 97511-H30726 | \$ 9,025.00 | 10% | \$8,183.42 |
| EW ResponsPLS NBDOnsite-H30727 | 97511-H30727 | \$ 9,560.00 | 10% | \$8,668.53 |
| EW ResponsPLS NBDOnsite-H30730 | 97511-H30730 | \$ 427.00 | 10% | \$387.18 |
| EW ResponsPLS NBDOnsite-H30731 | 97511-H30731 | \$ 427.00 | 10% | \$387.18 |
| EW ResponsPLS NBDOnsite-H30733 | 97511-H30733 | \$ 8,506.00 | 10% | \$7,712.82 |
| EW ResponsPLS NBDOnsite-H30734 | 97511-H30734 | \$ 6,581.00 | 10% | \$5,967.32 |
| EW ResponsPLS NBDOnsite-H30735 | 97511-H30735 | \$ 7,595.00 | 10% | \$6,886.77 |
| EW ResponsPLS NBDOnsite-H30736 | 97511-H30736 | \$ 1,551.00 | 10% | \$1,406.37 |
| EW ResponsPLS NBDOnsite-H30738 | 97511-H30738 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H30787 | 97511-H30787 | \$ 298.00 | 10% | \$270.21 |
| EW ResponsPLS NBDOnsite H30847 | 97511-H30847 | \$ 307.00 | 10% | \$278.37 |
| EW ResponsPLS NBDOnsite H30852 | 97511-H30852 | \$ 307.00 | 10% | \$278.37 |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H30857 | 97511-H30857 | \$ 352.00 | 10% | <i>\$319.18</i> |
| EW ResponsPLS NBDOnsite H31337 | 97511-H31337 | \$ 11,041.00 | 10% | <i>\$10,011.43</i> |
| EW ResponsPLS NBDOnsite H31338 | 97511-H31338 | \$ 11,041.00 | 10% | <i>\$10,011.43</i> |
| EW ResponsPLS NBDOnsite H31341 | 97511-H31341 | \$ 6,048.00 | 10% | <i>\$5,484.02</i> |
| EW ResponsPLS NBDOnsite H31342 | 97511-H31342 | \$ 1,664.00 | 10% | <i>\$1,508.83</i> |
| EW ResponsPLS NBDOnsite H31343 | 97511-H31343 | \$ 2,261.00 | 10% | <i>\$2,050.16</i> |
| EW ResponsPLS NBDOnsite H31344 | 97511-H31344 | \$ 2,261.00 | 10% | <i>\$2,050.16</i> |
| EW ResponsPLS NBDOnsite H31345 | 97511-H31345 | \$ 2,261.00 | 10% | <i>\$2,050.16</i> |
| EW ResponsPLS NBDOnsite H31346 | 97511-H31346 | \$ 2,261.00 | 10% | <i>\$2,050.16</i> |
| EW ResponsPLS NBDOnsite H31362 | 97511-H31362 | \$ 26,589.00 | 10% | <i>\$24,109.58</i> |
| EW ResponsPLS NBDOnsite H31363 | 97511-H31363 | \$ 26,589.00 | 10% | <i>\$24,109.58</i> |
| EW ResponsPLS NBDOnsite H31364 | 97511-H31364 | \$ 10,100.00 | 10% | <i>\$9,158.18</i> |
| EW ResponsPLS NBDOnsite H31365 | 97511-H31365 | \$ 10,100.00 | 10% | <i>\$9,158.18</i> |
| EW ResponsPLS NBDOnsite H31366 | 97511-H31366 | \$ 13,979.00 | 10% | <i>\$12,675.46</i> |
| EW ResponsPLS NBDOnsite H31367 | 97511-H31367 | \$ 13,979.00 | 10% | <i>\$12,675.46</i> |
| EW ResponsPLS NBDOnsite H32010 | 97511-H32010 | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW ResponsPLS NBDOnsite H32011 | 97511-H32011 | \$ 1,711.00 | 10% | <i>\$1,551.45</i> |
| EW ResponsPLS NBDOnsite H32012 | 97511-H32012 | \$ 3,650.00 | 10% | <i>\$3,309.64</i> |
| EW ResponsPLS NBDOnsite H32013 | 97511-H32013 | \$ 3,650.00 | 10% | <i>\$3,309.64</i> |
| EW ResponsPLS NBDOnsite H32014 | 97511-H32014 | \$ 3,650.00 | 10% | <i>\$3,309.64</i> |
| EW ResponsPLS NBDOnsite H32015 | 97511-H32015 | \$ 3,650.00 | 10% | <i>\$3,309.64</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H32016 | 97511-H32016 | \$ 3,358.00 | 10% | <i>\$3,044.87</i> |
| EW ResponsPLS NBDOnsite H32017 | 97511-H32017 | \$ 3,358.00 | 10% | <i>\$3,044.87</i> |
| EW ResponsPLS NBDOnsite H32018 | 97511-H32018 | \$ 3,358.00 | 10% | <i>\$3,044.87</i> |
| EW ResponsPLS NBDOnsite H32019 | 97511-H32019 | \$ 3,358.00 | 10% | <i>\$3,044.87</i> |
| EW ResponsPLS NBDOnsite H32020 | 97511-H32020 | \$ 27,019.00 | 10% | <i>\$24,499.48</i> |
| EW ResponsPLS NBDOnsite H32021 | 97511-H32021 | \$ 27,019.00 | 10% | <i>\$24,499.48</i> |
| EW ResponsPLS NBDOnsite H32022 | 97511-H32022 | \$ 27,019.00 | 10% | <i>\$24,499.48</i> |
| EW ResponsPLS NBDOnsite H32023 | 97511-H32023 | \$ 27,019.00 | 10% | <i>\$24,499.48</i> |
| EW ResponsPLS NBDOnsite H32028 | 97511-H32028 | \$ 50,228.00 | 10% | <i>\$45,544.24</i> |
| EW ResponsPLS NBDOnsite H32029 | 97511-H32029 | \$ 50,228.00 | 10% | <i>\$45,544.24</i> |
| EW ResponsPLS NBDOnsite H32030 | 97511-H32030 | \$ 52,676.00 | 10% | <i>\$47,763.96</i> |
| EW ResponsPLS NBDOnsite H32031 | 97511-H32031 | \$ 52,676.00 | 10% | <i>\$47,763.96</i> |
| EW ResponsPLS NBDOnsite H32032 | 97511-H32032 | \$ 52,676.00 | 10% | <i>\$47,763.96</i> |
| EW ResponsPLS NBDOnsite H32033 | 97511-H32033 | \$ 52,676.00 | 10% | <i>\$47,763.96</i> |
| EW ResponsPLS NBDOnsite H32038 | 97511-H32038 | \$ 10,186.00 | 10% | <i>\$9,236.16</i> |
| EW ResponsPLS NBDOnsite H32039 | 97511-H32039 | \$ 10,186.00 | 10% | <i>\$9,236.16</i> |
| EW ResponsPLS NBDOnsite H32040 | 97511-H32040 | \$ 10,186.00 | 10% | <i>\$9,236.16</i> |
| EW ResponsPLS NBDOnsite H32041 | 97511-H32041 | \$ 10,186.00 | 10% | <i>\$9,236.16</i> |
| EW ResponsPLS NBDOnsite H32046 | 97511-H32046 | \$ 14,095.00 | 10% | <i>\$12,780.64</i> |
| EW ResponsPLS NBDOnsite H32047 | 97511-H32047 | \$ 14,095.00 | 10% | <i>\$12,780.64</i> |
| EW ResponsPLS NBDOnsite H32048 | 97511-H32048 | \$ 14,095.00 | 10% | <i>\$12,780.64</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H32049 | 97511-H32049 | \$ 14,095.00 | 10% | <i>\$12,780.64</i> |
| EW ResponsPLS NBDOnsite H32054 | 97511-H32054 | \$ 10,186.00 | 10% | <i>\$9,236.16</i> |
| EW ResponsPLS NBDOnsite H32055 | 97511-H32055 | \$ 14,095.00 | 10% | <i>\$12,780.64</i> |
| EW ResponsPLS NBDOnsite H32056 | 97511-H32056 | \$ 4,257.00 | 10% | <i>\$3,860.03</i> |
| EW ResponsPLS NBDOnsite H32057 | 97511-H32057 | \$ 4,385.00 | 10% | <i>\$3,976.10</i> |
| EW ResponsPLS NBDOnsite H32058 | 97511-H32058 | \$ 4,385.00 | 10% | <i>\$3,976.10</i> |
| EW ResponsPLS NBDOnsite H32059 | 97511-H32059 | \$ 4,385.00 | 10% | <i>\$3,976.10</i> |
| EW ResponsPLS NBDOnsite H32060 | 97511-H32060 | \$ 4,150.00 | 10% | <i>\$3,763.01</i> |
| EW ResponsPLS NBDOnsite H32061 | 97511-H32061 | \$ 4,358.00 | 10% | <i>\$3,951.62</i> |
| EW ResponsPLS NBDOnsite H32062 | 97511-H32062 | \$ 4,190.00 | 10% | <i>\$3,799.28</i> |
| EW ResponsPLS NBDOnsite H32063 | 97511-H32063 | \$ 4,155.00 | 10% | <i>\$3,767.55</i> |
| EW ResponsPLS NBDOnsite H32064 | 97511-H32064 | \$ 4,190.00 | 10% | <i>\$3,799.28</i> |
| EW ResponsPLS NBDOnsite H32065 | 97511-H32065 | \$ 4,527.00 | 10% | <i>\$4,104.86</i> |
| EW ResponsPLS NBDOnsite H32066 | 97511-H32066 | \$ 4,527.00 | 10% | <i>\$4,104.86</i> |
| EW ResponsPLS NBDOnsite H32067 | 97511-H32067 | \$ 4,527.00 | 10% | <i>\$4,104.86</i> |
| EW ResponsPLS NBDOnsite H32068 | 97511-H32068 | \$ 4,527.00 | 10% | <i>\$4,104.86</i> |
| EW ResponsPLS NBDOnsite H32069 | 97511-H32069 | \$ 5,266.00 | 10% | <i>\$4,774.95</i> |
| EW ResponsPLS NBDOnsite H32070 | 97511-H32070 | \$ 5,266.00 | 10% | <i>\$4,774.95</i> |
| EW ResponsPLS NBDOnsite H32071 | 97511-H32071 | \$ 5,266.00 | 10% | <i>\$4,774.95</i> |
| EW ResponsPLS NBDOnsite H32072 | 97511-H32072 | \$ 5,266.00 | 10% | <i>\$4,774.95</i> |
| EW ResponsPLS NBDOnsite H32073 | 97511-H32073 | \$ 31,098.00 | 10% | <i>\$28,198.11</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H32074 | 97511-H32074 | \$ 31,098.00 | 10% | <i>\$28,198.11</i> |
| EW ResponsPLS NBDOnsite H32075 | 97511-H32075 | \$ 42,310.00 | 10% | <i>\$38,364.59</i> |
| EW ResponsPLS NBDOnsite H32076 | 97511-H32076 | \$ 42,310.00 | 10% | <i>\$38,364.59</i> |
| EW ResponsPLS NBDOnsite H32101 | 97511-H32101 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32102 | 97511-H32102 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32103 | 97511-H32103 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32104 | 97511-H32104 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32105 | 97511-H32105 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32106 | 97511-H32106 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32107 | 97511-H32107 | \$ 8,232.00 | 10% | <i>\$7,464.37</i> |
| EW ResponsPLS NBDOnsite H32108 | 97511-H32108 | \$ 8,232.00 | 10% | <i>\$7,464.37</i> |
| EW ResponsPLS NBDOnsite H32109 | 97511-H32109 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32110 | 97511-H32110 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32111 | 97511-H32111 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32112 | 97511-H32112 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32113 | 97511-H32113 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32114 | 97511-H32114 | \$ 2,771.00 | 10% | <i>\$2,512.60</i> |
| EW ResponsPLS NBDOnsite H32115 | 97511-H32115 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32116 | 97511-H32116 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32117 | 97511-H32117 | \$ 2,692.00 | 10% | <i>\$2,440.97</i> |
| EW ResponsPLS NBDOnsite H32118 | 97511-H32118 | \$ 2,692.00 | 10% | <i>\$2,440.97</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H32119 | 97511-H32119 | \$ 2,692.00 | 10% | <i>\$2,440.97</i> |
| EW ResponsPLS NBDOnsite H32120 | 97511-H32120 | \$ 2,692.00 | 10% | <i>\$2,440.97</i> |
| EW ResponsPLS NBDOnsite H32121 | 97511-H32121 | \$ 8,232.00 | 10% | <i>\$7,464.37</i> |
| EW ResponsPLS NBDOnsite H32122 | 97511-H32122 | \$ 8,232.00 | 10% | <i>\$7,464.37</i> |
| EW ResponsPLS NBDOnsite H32123 | 97511-H32123 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32124 | 97511-H32124 | \$ 4,004.00 | 10% | <i>\$3,630.63</i> |
| EW ResponsPLS NBDOnsite H32125 | 97511-H32125 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32126 | 97511-H32126 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32127 | 97511-H32127 | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsPLS NBDOnsite H32128 | 97511-H32128 | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsPLS NBDOnsite H32129 | 97511-H32129 | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsPLS NBDOnsite H32130 | 97511-H32130 | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsPLS NBDOnsite H32131 | 97511-H32131 | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsPLS NBDOnsite H32132 | 97511-H32132 | \$ 4,304.00 | 10% | <i>\$3,902.65</i> |
| EW ResponsPLS NBDOnsite H32133 | 97511-H32133 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32134 | 97511-H32134 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32135 | 97511-H32135 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32136 | 97511-H32136 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32137 | 97511-H32137 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32138 | 97511-H32138 | \$ 3,872.00 | 10% | <i>\$3,510.94</i> |
| EW ResponsPLS NBDOnsite H32139 | 97511-H32139 | \$ 13,815.00 | 10% | <i>\$12,526.75</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H32140 | 97511-H32140 | \$ 13,815.00 | 10% | <i>\$12,526.75</i> |
| EW ResponsPLS NBDOnsite H32141 | 97511-H32141 | \$ 16,585.00 | 10% | <i>\$15,038.45</i> |
| EW ResponsPLS NBDOnsite H32142 | 97511-H32142 | \$ 16,585.00 | 10% | <i>\$15,038.45</i> |
| EW ResponsPLS NBDOnsite H32146 | 97511-H32146 | \$ 2,627.00 | 10% | <i>\$2,382.03</i> |
| EW ResponsPLS NBDOnsite H32147 | 97511-H32147 | \$ 2,627.00 | 10% | <i>\$2,382.03</i> |
| EW ResponsPLS NBDOnsite H32148 | 97511-H32148 | \$ 3,792.00 | 10% | <i>\$3,438.40</i> |
| EW ResponsPLS NBDOnsite H32149 | 97511-H32149 | \$ 3,792.00 | 10% | <i>\$3,438.40</i> |
| EW ResponsPLS NBDOnsite H32150 | 97511-H32150 | \$ 2,627.00 | 10% | <i>\$2,382.03</i> |
| EW ResponsPLS NBDOnsite H32169 | 97511-H32169 | \$ 2,805.00 | 10% | <i>\$2,543.43</i> |
| EW ResponsPLS NBDOnsite H32170 | 97511-H32170 | \$ 2,805.00 | 10% | <i>\$2,543.43</i> |
| EW ResponsPLS NBDOnsite H32171 | 97511-H32171 | \$ 2,724.00 | 10% | <i>\$2,469.99</i> |
| EW ResponsPLS NBDOnsite H32172 | 97511-H32172 | \$ 2,724.00 | 10% | <i>\$2,469.99</i> |
| EW ResponsPLS NBDOnsite H32173 | 97511-H32173 | \$ 4,683.00 | 10% | <i>\$4,246.31</i> |
| EW ResponsPLS NBDOnsite H32174 | 97511-H32174 | \$ 4,683.00 | 10% | <i>\$4,246.31</i> |
| EW ResponsPLS NBDOnsite H32175 | 97511-H32175 | \$ 4,213.00 | 10% | <i>\$3,820.14</i> |
| EW ResponsPLS NBDOnsite H32176 | 97511-H32176 | \$ 4,213.00 | 10% | <i>\$3,820.14</i> |
| EW ResponsPLS NBDOnsite H32177 | 97511-H32177 | \$ 15,475.00 | 10% | <i>\$14,031.96</i> |
| EW ResponsPLS NBDOnsite H32178 | 97511-H32178 | \$ 18,578.00 | 10% | <i>\$16,845.60</i> |
| EW ResponsPLS NBDOnsite H34008 | 97511-H34008 | \$ 1,238.00 | 10% | <i>\$1,122.56</i> |
| EW ResponsPLS NBDOnsite H34009 | 97511-H34009 | \$ 1,304.00 | 10% | <i>\$1,182.40</i> |
| EW ResponsPLS NBDOnsite H34010 | 97511-H34010 | \$ 1,164.00 | 10% | <i>\$1,055.46</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H34011 | 97511-H34011 | \$ 1,290.00 | 10% | <i>\$1,169.71</i> |
| EW ResponsPLS NBDOnsite H34012 | 97511-H34012 | \$ 1,372.00 | 10% | <i>\$1,244.06</i> |
| EW ResponsPLS NBDOnsite H34013 | 97511-H34013 | \$ 1,263.00 | 10% | <i>\$1,145.23</i> |
| EW ResponsPLS NBDOnsite H34014 | 97511-H34014 | \$ 1,304.00 | 10% | <i>\$1,182.40</i> |
| EW ResponsPLS NBDOnsite H34015 | 97511-H34015 | \$ 1,178.00 | 10% | <i>\$1,068.15</i> |
| EW ResponsPLS NBDOnsite H34016 | 97511-H34016 | \$ 1,317.00 | 10% | <i>\$1,194.19</i> |
| EW ResponsPLS NBDOnsite H34017 | 97511-H34017 | \$ 1,398.00 | 10% | <i>\$1,267.64</i> |
| EW ResponsPLS NBDOnsite H34018 | 97511-H34018 | \$ 1,282.00 | 10% | <i>\$1,162.45</i> |
| EW ResponsPLS NBDOnsite H34019 | 97511-H34019 | \$ 1,282.00 | 10% | <i>\$1,162.45</i> |
| EW ResponsPLS NBDOnsite H34020 | 97511-H34020 | \$ 1,282.00 | 10% | <i>\$1,162.45</i> |
| EW ResponsPLS NBDOnsite H34021 | 97511-H34021 | \$ 1,282.00 | 10% | <i>\$1,162.45</i> |
| EW ResponsPLS NBDOnsite H34048 | 97511-H34048 | \$ 1,532.00 | 10% | <i>\$1,389.14</i> |
| EW ResponsPLS NBDOnsite H34049 | 97511-H34049 | \$ 1,532.00 | 10% | <i>\$1,389.14</i> |
| EW ResponsPLS NBDOnsite H34050 | 97511-H34050 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW ResponsPLS NBDOnsite H34051 | 97511-H34051 | \$ 1,447.00 | 10% | <i>\$1,312.07</i> |
| EW ResponsPLS NBDOnsite H34052 | 97511-H34052 | \$ 1,590.00 | 10% | <i>\$1,441.73</i> |
| EW ResponsPLS NBDOnsite H34053 | 97511-H34053 | \$ 1,590.00 | 10% | <i>\$1,441.73</i> |
| EW ResponsPLS NBDOnsite H34054 | 97511-H34054 | \$ 1,489.00 | 10% | <i>\$1,350.15</i> |
| EW ResponsPLS NBDOnsite H34055 | 97511-H34055 | \$ 1,489.00 | 10% | <i>\$1,350.15</i> |
| EW ResponsPLS NBDOnsite H34056 | 97511-H34056 | \$ 1,734.00 | 10% | <i>\$1,572.30</i> |
| EW ResponsPLS NBDOnsite H34057 | 97511-H34057 | \$ 1,734.00 | 10% | <i>\$1,572.30</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H34058 | 97511-H34058 | \$ 1,670.00 | 10% | <i>\$1,514.27</i> |
| EW ResponsPLS NBDOnsite H34059 | 97511-H34059 | \$ 1,670.00 | 10% | <i>\$1,514.27</i> |
| EW ResponsPLS NBDOnsite H34062 | 97511-H34062 | \$ 1,734.00 | 10% | <i>\$1,572.30</i> |
| EW ResponsPLS NBDOnsite H34063 | 97511-H34063 | \$ 1,734.00 | 10% | <i>\$1,572.30</i> |
| EW ResponsPLS NBDOnsite H34064 | 97511-H34064 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLS NBDOnsite H34065 | 97511-H34065 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLS NBDOnsite H34066 | 97511-H34066 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLS NBDOnsite H34067 | 97511-H34067 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLS NBDOnsite H34068 | 97511-H34068 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLS NBDOnsite H34069 | 97511-H34069 | \$ 1,411.00 | 10% | <i>\$1,279.42</i> |
| EW ResponsPLS NBDOnsite H34070 | 97511-H34070 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLS NBDOnsite H34071 | 97511-H34071 | \$ 1,452.00 | 10% | <i>\$1,316.60</i> |
| EW ResponsPLS NBDOnsite H34072 | 97511-H34072 | \$ 3,484.00 | 10% | <i>\$3,159.12</i> |
| EW ResponsPLS NBDOnsite H34073 | 97511-H34073 | \$ 3,417.00 | 10% | <i>\$3,098.36</i> |
| EW ResponsPLS NBDOnsite H34074 | 97511-H34074 | \$ 4,255.00 | 10% | <i>\$3,858.22</i> |
| EW ResponsPLS NBDOnsite H34075 | 97511-H34075 | \$ 4,134.00 | 10% | <i>\$3,748.50</i> |
| EW ResponsPLS NBDOnsite H34076 | 97511-H34076 | \$ 3,484.00 | 10% | <i>\$3,159.12</i> |
| EW ResponsPLS NBDOnsite H34077 | 97511-H34077 | \$ 3,417.00 | 10% | <i>\$3,098.36</i> |
| EW ResponsPLS NBDOnsite H34078 | 97511-H34078 | \$ 3,484.00 | 10% | <i>\$3,159.12</i> |
| EW ResponsPLS NBDOnsite H34079 | 97511-H34079 | \$ 3,417.00 | 10% | <i>\$3,098.36</i> |
| EW ResponsPLS NBDOnsite H34080 | 97511-H34080 | \$ 4,255.00 | 10% | <i>\$3,858.22</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H34081 | 97511-H34081 | \$ 4,134.00 | 10% | <i>\$3,748.50</i> |
| EW ResponsPLS NBDOnsite H34082 | 97511-H34082 | \$ 4,081.00 | 10% | <i>\$3,700.45</i> |
| EW ResponsPLS NBDOnsite H34083 | 97511-H34083 | \$ 3,965.00 | 10% | <i>\$3,595.26</i> |
| EW ResponsPLS NBDOnsite H34084 | 97511-H34084 | \$ 3,168.00 | 10% | <i>\$2,872.58</i> |
| EW ResponsPLS NBDOnsite H34085 | 97511-H34085 | \$ 3,168.00 | 10% | <i>\$2,872.58</i> |
| EW ResponsPLS NBDOnsite H34086 | 97511-H34086 | \$ 3,689.00 | 10% | <i>\$3,345.00</i> |
| EW ResponsPLS NBDOnsite H34087 | 97511-H34087 | \$ 3,539.00 | 10% | <i>\$3,208.99</i> |
| EW ResponsPLS NBDOnsite H34088 | 97511-H34088 | \$ 6,506.00 | 10% | <i>\$5,899.32</i> |
| EW ResponsPLS NBDOnsite H34089 | 97511-H34089 | \$ 6,506.00 | 10% | <i>\$5,899.32</i> |
| EW ResponsPLS NBDOnsite H34090 | 97511-H34090 | \$ 7,492.00 | 10% | <i>\$6,793.37</i> |
| EW ResponsPLS NBDOnsite H34091 | 97511-H34091 | \$ 6,975.00 | 10% | <i>\$6,324.58</i> |
| EW ResponsPLS NBDOnsite H34092 | 97511-H34092 | \$ 6,975.00 | 10% | <i>\$6,324.58</i> |
| EW ResponsPLS NBDOnsite H34093 | 97511-H34093 | \$ 6,975.00 | 10% | <i>\$6,324.58</i> |
| EW ResponsPLS NBDOnsite H34094 | 97511-H34094 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW ResponsPLS NBDOnsite H34095 | 97511-H34095 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW ResponsPLS NBDOnsite H34096 | 97511-H34096 | \$ 892.00 | 10% | <i>\$808.82</i> |
| EW ResponsPLS NBDOnsite H34097 | 97511-H34097 | \$ 892.00 | 10% | <i>\$808.82</i> |
| EW ResponsPLS NBDOnsite H34098 | 97511-H34098 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW ResponsPLS NBDOnsite H34099 | 97511-H34099 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW ResponsPLS NBDOnsite H34100 | 97511-H34100 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW ResponsPLS NBDOnsite H34101 | 97511-H34101 | \$ 839.00 | 10% | <i>\$760.76</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H34102 | 97511-H34102 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW ResponsPLS NBDOnsite H34103 | 97511-H34103 | \$ 839.00 | 10% | <i>\$760.76</i> |
| EW ResponsPLS NBDOnsite H34104 | 97511-H34104 | \$ 611.00 | 10% | <i>\$554.02</i> |
| EW ResponsPLS NBDOnsite H34105 | 97511-H34105 | \$ 611.00 | 10% | <i>\$554.02</i> |
| EW ResponsPLS NBDOnsite H34106 | 97511-H34106 | \$ 611.00 | 10% | <i>\$554.02</i> |
| EW ResponsPLS NBDOnsite H34107 | 97511-H34107 | \$ 611.00 | 10% | <i>\$554.02</i> |
| EW ResponsPLS NBDOnsite H34108 | 97511-H34108 | \$ 611.00 | 10% | <i>\$554.02</i> |
| EW ResponsPLS NBDOnsite H34109 | 97511-H34109 | \$ 611.00 | 10% | <i>\$554.02</i> |
| EW ResponsPLS NBDOnsite H34110 | 97511-H34110 | \$ 6,718.00 | 10% | <i>\$6,091.55</i> |
| EW ResponsPLS NBDOnsite H34111 | 97511-H34111 | \$ 6,718.00 | 10% | <i>\$6,091.55</i> |
| EW ResponsPLS NBDOnsite H34112 | 97511-H34112 | \$ 6,718.00 | 10% | <i>\$6,091.55</i> |
| EW ResponsPLS NBDOnsite H34114 | 97511-H34114 | \$ 10,277.00 | 10% | <i>\$9,318.67</i> |
| EW ResponsPLS NBDOnsite H34115 | 97511-H34115 | \$ 9,861.00 | 10% | <i>\$8,941.46</i> |
| EW ResponsPLS NBDOnsite H34116 | 97511-H34116 | \$ 9,861.00 | 10% | <i>\$8,941.46</i> |
| EW ResponsPLS NBDOnsite H34117 | 97511-H34117 | \$ 10,277.00 | 10% | <i>\$9,318.67</i> |
| EW ResponsPLS NBDOnsite H34118 | 97511-H34118 | \$ 1,544.00 | 10% | <i>\$1,400.02</i> |
| EW ResponsPLS NBDOnsite H34119 | 97511-H34119 | \$ 1,544.00 | 10% | <i>\$1,400.02</i> |
| EW ResponsPLS NBDOnsite H34120 | 97511-H34120 | \$ 1,191.00 | 10% | <i>\$1,079.94</i> |
| EW ResponsPLS NBDOnsite H34121 | 97511-H34121 | \$ 1,191.00 | 10% | <i>\$1,079.94</i> |
| EW ResponsPLS NBDOnsite H34122 | 97511-H34122 | \$ 1,224.00 | 10% | <i>\$1,109.86</i> |
| EW ResponsPLS NBDOnsite H34123 | 97511-H34123 | \$ 1,224.00 | 10% | <i>\$1,109.86</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H34124 | 97511-H34124 | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW ResponsPLS NBDOnsite H34125 | 97511-H34125 | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW ResponsPLS NBDOnsite H34126 | 97511-H34126 | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW ResponsPLS NBDOnsite H34127 | 97511-H34127 | \$ 1,618.00 | 10% | <i>\$1,467.12</i> |
| EW ResponsPLS NBDOnsite H34129 | 97511-H34129 | \$ 1,488.00 | 10% | <i>\$1,349.24</i> |
| EW ResponsPLS NBDOnsite H34130 | 97511-H34130 | \$ 1,546.00 | 10% | <i>\$1,401.84</i> |
| EW ResponsPLS NBDOnsite H34131 | 97511-H34131 | \$ 1,538.00 | 10% | <i>\$1,394.58</i> |
| EW ResponsPLS NBDOnsite H34132 | 97511-H34132 | \$ 1,546.00 | 10% | <i>\$1,401.84</i> |
| EW ResponsPLS NBDOnsite H34172 | 97511-H34172 | \$ 3,000.00 | 10% | <i>\$2,720.25</i> |
| EW ResponsPLS NBDOnsite H34174 | 97511-H34174 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34175 | 97511-H34175 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34176 | 97511-H34176 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34177 | 97511-H34177 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34178 | 97511-H34178 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34179 | 97511-H34179 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34180 | 97511-H34180 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34181 | 97511-H34181 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34182 | 97511-H34182 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34183 | 97511-H34183 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34184 | 97511-H34184 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34185 | 97511-H34185 | \$ 376.00 | 10% | <i>\$340.94</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34186 | 97511-H34186 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34187 | 97511-H34187 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34188 | 97511-H34188 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34189 | 97511-H34189 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34190 | 97511-H34190 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34191 | 97511-H34191 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34192 | 97511-H34192 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34193 | 97511-H34193 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34194 | 97511-H34194 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34195 | 97511-H34195 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34196 | 97511-H34196 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34197 | 97511-H34197 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34198 | 97511-H34198 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34199 | 97511-H34199 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34200 | 97511-H34200 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34201 | 97511-H34201 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34202 | 97511-H34202 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34203 | 97511-H34203 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34204 | 97511-H34204 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34205 | 97511-H34205 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34206 | 97511-H34206 | \$ 376.00 | 10% | <i>\$340.94</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34207 | 97511-H34207 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34208 | 97511-H34208 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34209 | 97511-H34209 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34210 | 97511-H34210 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34211 | 97511-H34211 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34212 | 97511-H34212 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34213 | 97511-H34213 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34214 | 97511-H34214 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34215 | 97511-H34215 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34216 | 97511-H34216 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34217 | 97511-H34217 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34218 | 97511-H34218 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34219 | 97511-H34219 | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW ResponsPLS NBDOnsite H34220 | 97511-H34220 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34221 | 97511-H34221 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34222 | 97511-H34222 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34223 | 97511-H34223 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34224 | 97511-H34224 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34225 | 97511-H34225 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34226 | 97511-H34226 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34227 | 97511-H34227 | \$ 391.00 | 10% | <i>\$354.54</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34228 | 97511-H34228 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34229 | 97511-H34229 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34230 | 97511-H34230 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34231 | 97511-H34231 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34232 | 97511-H34232 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34233 | 97511-H34233 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34234 | 97511-H34234 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34235 | 97511-H34235 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34236 | 97511-H34236 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34237 | 97511-H34237 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34238 | 97511-H34238 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34239 | 97511-H34239 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34240 | 97511-H34240 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34241 | 97511-H34241 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34242 | 97511-H34242 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34243 | 97511-H34243 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34244 | 97511-H34244 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34245 | 97511-H34245 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34246 | 97511-H34246 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34247 | 97511-H34247 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34248 | 97511-H34248 | \$ 391.00 | 10% | <i>\$354.54</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34249 | 97511-H34249 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34250 | 97511-H34250 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34251 | 97511-H34251 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34252 | 97511-H34252 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34253 | 97511-H34253 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34254 | 97511-H34254 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34255 | 97511-H34255 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34256 | 97511-H34256 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34257 | 97511-H34257 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34258 | 97511-H34258 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34259 | 97511-H34259 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34260 | 97511-H34260 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34261 | 97511-H34261 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34262 | 97511-H34262 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34263 | 97511-H34263 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34264 | 97511-H34264 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34265 | 97511-H34265 | \$ 391.00 | 10% | <i>\$354.54</i> |
| EW ResponsPLS NBDOnsite H34266 | 97511-H34266 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H34267 | 97511-H34267 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H34268 | 97511-H34268 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H34269 | 97511-H34269 | \$ 373.00 | 10% | <i>\$338.22</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34270 | 97511-H34270 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34271 | 97511-H34271 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34272 | 97511-H34272 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34273 | 97511-H34273 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34274 | 97511-H34274 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34275 | 97511-H34275 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34276 | 97511-H34276 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34277 | 97511-H34277 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34278 | 97511-H34278 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34279 | 97511-H34279 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34280 | 97511-H34280 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34281 | 97511-H34281 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34282 | 97511-H34282 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34283 | 97511-H34283 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34284 | 97511-H34284 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34285 | 97511-H34285 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34286 | 97511-H34286 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34287 | 97511-H34287 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34288 | 97511-H34288 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34289 | 97511-H34289 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34290 | 97511-H34290 | \$ 373.00 | 10% | \$338.22 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34291 | 97511-H34291 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34292 | 97511-H34292 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34293 | 97511-H34293 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34294 | 97511-H34294 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34295 | 97511-H34295 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34296 | 97511-H34296 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34297 | 97511-H34297 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34298 | 97511-H34298 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34299 | 97511-H34299 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34300 | 97511-H34300 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34301 | 97511-H34301 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34302 | 97511-H34302 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34303 | 97511-H34303 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34304 | 97511-H34304 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34305 | 97511-H34305 | \$ 373.00 | 10% | \$338.22 |
| EW ResponsPLS NBDOnsite H34306 | 97511-H34306 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34307 | 97511-H34307 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34308 | 97511-H34308 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34309 | 97511-H34309 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34310 | 97511-H34310 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34311 | 97511-H34311 | \$ 400.00 | 10% | \$362.70 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34312 | 97511-H34312 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34313 | 97511-H34313 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34314 | 97511-H34314 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34315 | 97511-H34315 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34316 | 97511-H34316 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34317 | 97511-H34317 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34318 | 97511-H34318 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34319 | 97511-H34319 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34320 | 97511-H34320 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34321 | 97511-H34321 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34322 | 97511-H34322 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34323 | 97511-H34323 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34324 | 97511-H34324 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34325 | 97511-H34325 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34326 | 97511-H34326 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34327 | 97511-H34327 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34328 | 97511-H34328 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34329 | 97511-H34329 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34330 | 97511-H34330 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34331 | 97511-H34331 | \$ 400.00 | 10% | \$362.70 |
| EW ResponsPLS NBDOnsite H34332 | 97511-H34332 | \$ 400.00 | 10% | \$362.70 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34333 | 97511-H34333 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34334 | 97511-H34334 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34335 | 97511-H34335 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34336 | 97511-H34336 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34337 | 97511-H34337 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34338 | 97511-H34338 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34339 | 97511-H34339 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34340 | 97511-H34340 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34341 | 97511-H34341 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34342 | 97511-H34342 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34343 | 97511-H34343 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34344 | 97511-H34344 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34345 | 97511-H34345 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34346 | 97511-H34346 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34347 | 97511-H34347 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34348 | 97511-H34348 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34349 | 97511-H34349 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34350 | 97511-H34350 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34351 | 97511-H34351 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34352 | 97511-H34352 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34353 | 97511-H34353 | \$ 400.00 | 10% | <i>\$362.70</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34354 | 97511-H34354 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34355 | 97511-H34355 | \$ 400.00 | 10% | <i>\$362.70</i> |
| EW ResponsPLS NBDOnsite H34403 | 97511-H34403 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34404 | 97511-H34404 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34405 | 97511-H34405 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34406 | 97511-H34406 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34407 | 97511-H34407 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34408 | 97511-H34408 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34409 | 97511-H34409 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34410 | 97511-H34410 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34411 | 97511-H34411 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34412 | 97511-H34412 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34413 | 97511-H34413 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34414 | 97511-H34414 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34415 | 97511-H34415 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34416 | 97511-H34416 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34417 | 97511-H34417 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34418 | 97511-H34418 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34419 | 97511-H34419 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34420 | 97511-H34420 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34421 | 97511-H34421 | \$ 502.00 | 10% | <i>\$455.19</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34422 | 97511-H34422 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34423 | 97511-H34423 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34424 | 97511-H34424 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34425 | 97511-H34425 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34426 | 97511-H34426 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34427 | 97511-H34427 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34428 | 97511-H34428 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34429 | 97511-H34429 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34430 | 97511-H34430 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34431 | 97511-H34431 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34432 | 97511-H34432 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34433 | 97511-H34433 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34434 | 97511-H34434 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34435 | 97511-H34435 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34436 | 97511-H34436 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34437 | 97511-H34437 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34438 | 97511-H34438 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34439 | 97511-H34439 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34440 | 97511-H34440 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34441 | 97511-H34441 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34442 | 97511-H34442 | \$ 502.00 | 10% | <i>\$455.19</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34443 | 97511-H34443 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34444 | 97511-H34444 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34445 | 97511-H34445 | \$ 502.00 | 10% | <i>\$455.19</i> |
| EW ResponsPLS NBDOnsite H34446 | 97511-H34446 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34447 | 97511-H34447 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34448 | 97511-H34448 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34449 | 97511-H34449 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34450 | 97511-H34450 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34451 | 97511-H34451 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34452 | 97511-H34452 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34453 | 97511-H34453 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34454 | 97511-H34454 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34455 | 97511-H34455 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34456 | 97511-H34456 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34457 | 97511-H34457 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34458 | 97511-H34458 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34459 | 97511-H34459 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34460 | 97511-H34460 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34461 | 97511-H34461 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34462 | 97511-H34462 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34463 | 97511-H34463 | \$ 532.00 | 10% | <i>\$482.39</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34464 | 97511-H34464 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34465 | 97511-H34465 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34466 | 97511-H34466 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34467 | 97511-H34467 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34468 | 97511-H34468 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34469 | 97511-H34469 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34470 | 97511-H34470 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34471 | 97511-H34471 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34472 | 97511-H34472 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34473 | 97511-H34473 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34474 | 97511-H34474 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34475 | 97511-H34475 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34476 | 97511-H34476 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34477 | 97511-H34477 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34478 | 97511-H34478 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34479 | 97511-H34479 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34480 | 97511-H34480 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34481 | 97511-H34481 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34482 | 97511-H34482 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34483 | 97511-H34483 | \$ 532.00 | 10% | \$482.39 |
| EW ResponsPLS NBDOnsite H34484 | 97511-H34484 | \$ 532.00 | 10% | \$482.39 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34485 | 97511-H34485 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34486 | 97511-H34486 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34487 | 97511-H34487 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34488 | 97511-H34488 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34489 | 97511-H34489 | \$ 532.00 | 10% | <i>\$482.39</i> |
| EW ResponsPLS NBDOnsite H34490 | 97511-H34490 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34491 | 97511-H34491 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34492 | 97511-H34492 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34493 | 97511-H34493 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34494 | 97511-H34494 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34495 | 97511-H34495 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34496 | 97511-H34496 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34497 | 97511-H34497 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34498 | 97511-H34498 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34499 | 97511-H34499 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34500 | 97511-H34500 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34501 | 97511-H34501 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34502 | 97511-H34502 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34503 | 97511-H34503 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34504 | 97511-H34504 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34505 | 97511-H34505 | \$ 355.00 | 10% | <i>\$321.90</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34506 | 97511-H34506 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34507 | 97511-H34507 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34508 | 97511-H34508 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34509 | 97511-H34509 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34510 | 97511-H34510 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34511 | 97511-H34511 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34512 | 97511-H34512 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34513 | 97511-H34513 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34514 | 97511-H34514 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34515 | 97511-H34515 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34516 | 97511-H34516 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34517 | 97511-H34517 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34518 | 97511-H34518 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34519 | 97511-H34519 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34520 | 97511-H34520 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34521 | 97511-H34521 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34522 | 97511-H34522 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34523 | 97511-H34523 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34524 | 97511-H34524 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34525 | 97511-H34525 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34526 | 97511-H34526 | \$ 355.00 | 10% | <i>\$321.90</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34527 | 97511-H34527 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34528 | 97511-H34528 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34529 | 97511-H34529 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34530 | 97511-H34530 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34531 | 97511-H34531 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34532 | 97511-H34532 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34533 | 97511-H34533 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34534 | 97511-H34534 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34535 | 97511-H34535 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34536 | 97511-H34536 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34537 | 97511-H34537 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34538 | 97511-H34538 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34539 | 97511-H34539 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34540 | 97511-H34540 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34541 | 97511-H34541 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34542 | 97511-H34542 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34543 | 97511-H34543 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34544 | 97511-H34544 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34545 | 97511-H34545 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34546 | 97511-H34546 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34547 | 97511-H34547 | \$ 355.00 | 10% | <i>\$321.90</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34548 | 97511-H34548 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34549 | 97511-H34549 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34550 | 97511-H34550 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34551 | 97511-H34551 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34552 | 97511-H34552 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34553 | 97511-H34553 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34554 | 97511-H34554 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34555 | 97511-H34555 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34556 | 97511-H34556 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34557 | 97511-H34557 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34558 | 97511-H34558 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34559 | 97511-H34559 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34560 | 97511-H34560 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34561 | 97511-H34561 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34562 | 97511-H34562 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34563 | 97511-H34563 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34564 | 97511-H34564 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34565 | 97511-H34565 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34566 | 97511-H34566 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34567 | 97511-H34567 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34568 | 97511-H34568 | \$ 355.00 | 10% | <i>\$321.90</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|-----------------|
| EW ResponsPLS NBDOnsite H34569 | 97511-H34569 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34570 | 97511-H34570 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34571 | 97511-H34571 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34572 | 97511-H34572 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34573 | 97511-H34573 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34574 | 97511-H34574 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34575 | 97511-H34575 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34576 | 97511-H34576 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34577 | 97511-H34577 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34578 | 97511-H34578 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34579 | 97511-H34579 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34580 | 97511-H34580 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34581 | 97511-H34581 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34582 | 97511-H34582 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34583 | 97511-H34583 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34584 | 97511-H34584 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34585 | 97511-H34585 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34586 | 97511-H34586 | \$ 355.00 | 10% | <i>\$321.90</i> |
| EW ResponsPLS NBDOnsite H34587 | 97511-H34587 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW ResponsPLS NBDOnsite H34588 | 97511-H34588 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW ResponsPLS NBDOnsite H34589 | 97511-H34589 | \$ 407.00 | 10% | <i>\$369.05</i> |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34590 | 97511-H34590 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34591 | 97511-H34591 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34592 | 97511-H34592 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34593 | 97511-H34593 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34594 | 97511-H34594 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34595 | 97511-H34595 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34596 | 97511-H34596 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34597 | 97511-H34597 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34598 | 97511-H34598 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34599 | 97511-H34599 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34600 | 97511-H34600 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34601 | 97511-H34601 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34602 | 97511-H34602 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34603 | 97511-H34603 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34604 | 97511-H34604 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34605 | 97511-H34605 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34606 | 97511-H34606 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34607 | 97511-H34607 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34608 | 97511-H34608 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34609 | 97511-H34609 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34610 | 97511-H34610 | \$ 407.00 | 10% | \$369.05 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34611 | 97511-H34611 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34612 | 97511-H34612 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34613 | 97511-H34613 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34614 | 97511-H34614 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34615 | 97511-H34615 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34616 | 97511-H34616 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34617 | 97511-H34617 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34618 | 97511-H34618 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34619 | 97511-H34619 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34620 | 97511-H34620 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34621 | 97511-H34621 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34622 | 97511-H34622 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34623 | 97511-H34623 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34624 | 97511-H34624 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34625 | 97511-H34625 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34626 | 97511-H34626 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34627 | 97511-H34627 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34628 | 97511-H34628 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34629 | 97511-H34629 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34630 | 97511-H34630 | \$ 407.00 | 10% | \$369.05 |
| EW ResponsPLS NBDOnsite H34631 | 97511-H34631 | \$ 407.00 | 10% | \$369.05 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34632 | 97511-H34632 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34633 | 97511-H34633 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34634 | 97511-H34634 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34635 | 97511-H34635 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34636 | 97511-H34636 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34637 | 97511-H34637 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34638 | 97511-H34638 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34639 | 97511-H34639 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34640 | 97511-H34640 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34641 | 97511-H34641 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34642 | 97511-H34642 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34643 | 97511-H34643 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34644 | 97511-H34644 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34645 | 97511-H34645 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34646 | 97511-H34646 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34647 | 97511-H34647 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34648 | 97511-H34648 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34649 | 97511-H34649 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34650 | 97511-H34650 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34651 | 97511-H34651 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34652 | 97511-H34652 | \$ 410.00 | 10% | \$371.77 |

| | | | | |
|-----------------------------------|--------------|-----------|-----|----------|
| EW ResponsPLS NBDOnsite H34653 | 97511-H34653 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34654 | 97511-H34654 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34655 | 97511-H34655 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34656 | 97511-H34656 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34657 | 97511-H34657 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34658 | 97511-H34658 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34659 | 97511-H34659 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34660 | 97511-H34660 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34661 | 97511-H34661 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34662 | 97511-H34662 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34663 | 97511-H34663 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34664 | 97511-H34664 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34665 | 97511-H34665 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34666 | 97511-H34666 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34667 | 97511-H34667 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34668 | 97511-H34668 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34669 | 97511-H34669 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34670 | 97511-H34670 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34671 | 97511-H34671 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34672 | 97511-H34672 | \$ 410.00 | 10% | \$371.77 |
| EW ResponsPLS NBDOnsite H34673 | 97511-H34673 | \$ 410.00 | 10% | \$371.77 |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H34674 | 97511-H34674 | \$ 410.00 | 10% | <i>\$371.77</i> |
| EW ResponsPLS NBDOnsite H34675 | 97511-H34675 | \$ 410.00 | 10% | <i>\$371.77</i> |
| EW ResponsPLS NBDOnsite H34676 | 97511-H34676 | \$ 410.00 | 10% | <i>\$371.77</i> |
| EW ResponsPLS NBDOnsite H34677 | 97511-H34677 | \$ 410.00 | 10% | <i>\$371.77</i> |
| EW ResponsPLS NBDOnsite H34678 | 97511-H34678 | \$ 410.00 | 10% | <i>\$371.77</i> |
| EW ResponsPLS NBDOnsite H34726 | 97511-H34726 | \$ 3,655.00 | 10% | <i>\$3,314.17</i> |
| EW ResponsPLS NBDOnsite H34727 | 97511-H34727 | \$ 3,655.00 | 10% | <i>\$3,314.17</i> |
| EW ResponsPLS NBDOnsite H34728 | 97511-H34728 | \$ 3,655.00 | 10% | <i>\$3,314.17</i> |
| EW ResponsPLS NBDOnsite H34729 | 97511-H34729 | \$ 3,655.00 | 10% | <i>\$3,314.17</i> |
| EW ResponsPLS NBDOnsite H34730 | 97511-H34730 | \$ 3,832.00 | 10% | <i>\$3,474.67</i> |
| EW ResponsPLS NBDOnsite H34731 | 97511-H34731 | \$ 3,832.00 | 10% | <i>\$3,474.67</i> |
| EW ResponsPLS NBDOnsite H34732 | 97511-H34732 | \$ 3,832.00 | 10% | <i>\$3,474.67</i> |
| EW ResponsPLS NBDOnsite H34733 | 97511-H34733 | \$ 3,832.00 | 10% | <i>\$3,474.67</i> |
| EW ResponsPLS NBDOnsite H34734 | 97511-H34734 | \$ 1,626.00 | 10% | <i>\$1,474.38</i> |
| EW ResponsPLS NBDOnsite H34735 | 97511-H34735 | \$ 1,626.00 | 10% | <i>\$1,474.38</i> |
| EW ResponsPLS NBDOnsite H34736 | 97511-H34736 | \$ 1,728.00 | 10% | <i>\$1,566.86</i> |
| EW ResponsPLS NBDOnsite H34737 | 97511-H34737 | \$ 1,728.00 | 10% | <i>\$1,566.86</i> |
| EW ResponsPLS NBDOnsite H34738 | 97511-H34738 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34739 | 97511-H34739 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34740 | 97511-H34740 | \$ 1,626.00 | 10% | <i>\$1,474.38</i> |
| EW ResponsPLS NBDOnsite H34741 | 97511-H34741 | \$ 1,626.00 | 10% | <i>\$1,474.38</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H34742 | 97511-H34742 | \$ 1,544.00 | 10% | <i>\$1,400.02</i> |
| EW ResponsPLS NBDOnsite H34743 | 97511-H34743 | \$ 1,544.00 | 10% | <i>\$1,400.02</i> |
| EW ResponsPLS NBDOnsite H34744 | 97511-H34744 | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW ResponsPLS NBDOnsite H34745 | 97511-H34745 | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW ResponsPLS NBDOnsite H34746 | 97511-H34746 | \$ 1,784.00 | 10% | <i>\$1,617.64</i> |
| EW ResponsPLS NBDOnsite H34747 | 97511-H34747 | \$ 1,784.00 | 10% | <i>\$1,617.64</i> |
| EW ResponsPLS NBDOnsite H34748 | 97511-H34748 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34749 | 97511-H34749 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34750 | 97511-H34750 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34751 | 97511-H34751 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34752 | 97511-H34752 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34753 | 97511-H34753 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34754 | 97511-H34754 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34755 | 97511-H34755 | \$ 2,160.00 | 10% | <i>\$1,958.58</i> |
| EW ResponsPLS NBDOnsite H34756 | 97511-H34756 | \$ 1,728.00 | 10% | <i>\$1,566.86</i> |
| EW ResponsPLS NBDOnsite H34757 | 97511-H34757 | \$ 1,728.00 | 10% | <i>\$1,566.86</i> |
| EW ResponsPLS NBDOnsite H34758 | 97511-H34758 | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW ResponsPLS NBDOnsite H34759 | 97511-H34759 | \$ 1,728.00 | 10% | <i>\$1,566.86</i> |
| EW ResponsPLS NBDOnsite H34760 | 97511-H34760 | \$ 1,728.00 | 10% | <i>\$1,566.86</i> |
| EW ResponsPLS NBDOnsite H34761 | 97511-H34761 | \$ 1,720.00 | 10% | <i>\$1,559.61</i> |
| EW ResponsPLS NBDOnsite H34993 | 97511-H34993 | \$ 17,124.00 | 10% | <i>\$15,527.19</i> |

| | | | | |
|-----------------------------------|--------------|--------------|-----|--------------------|
| EW ResponsPLS NBDOnsite H34994 | 97511-H34994 | \$ 17,124.00 | 10% | <i>\$15,527.19</i> |
| EW ResponsPLS NBDOnsite H34996 | 97511-H34996 | \$ 17,124.00 | 10% | <i>\$15,527.19</i> |
| EW ResponsPLS NBDOnsite H34997 | 97511-H34997 | \$ 17,124.00 | 10% | <i>\$15,527.19</i> |
| EW ResponsPLS NBDOnsite H35005 | 97511-H35005 | \$ 12,337.00 | 10% | <i>\$11,186.57</i> |
| EW ResponsPLS NBDOnsite H35006 | 97511-H35006 | \$ 12,337.00 | 10% | <i>\$11,186.57</i> |
| EW ResponsPLS NBDOnsite H35012 | 97511-H35012 | \$ 8,433.00 | 10% | <i>\$7,646.62</i> |
| EW ResponsPLS NBDOnsite H35070 | 97511-H35070 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35071 | 97511-H35071 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35072 | 97511-H35072 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35073 | 97511-H35073 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35074 | 97511-H35074 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35075 | 97511-H35075 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35076 | 97511-H35076 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35077 | 97511-H35077 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35078 | 97511-H35078 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35079 | 97511-H35079 | \$ 373.00 | 10% | <i>\$338.22</i> |
| EW ResponsPLS NBDOnsite H35080 | 97511-H35080 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW ResponsPLS NBDOnsite H35081 | 97511-H35081 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW ResponsPLS NBDOnsite H35082 | 97511-H35082 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW ResponsPLS NBDOnsite H35083 | 97511-H35083 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW ResponsPLS NBDOnsite H35270 | 97511-H35270 | \$ 1,590.00 | 10% | <i>\$1,441.73</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H35271 | 97511-H35271 | \$ 1,489.00 | 10% | <i>\$1,350.15</i> |
| EW ResponsPLS NBDOnsite H35272 | 97511-H35272 | \$ 1,359.00 | 10% | <i>\$1,232.27</i> |
| EW ResponsPLS NBDOnsite H35273 | 97511-H35273 | \$ 1,359.00 | 10% | <i>\$1,232.27</i> |
| EW ResponsPLS NBDOnsite H35274 | 97511-H35274 | \$ 1,793.00 | 10% | <i>\$1,625.80</i> |
| EW ResponsPLS NBDOnsite H35275 | 97511-H35275 | \$ 1,734.00 | 10% | <i>\$1,572.30</i> |
| EW ResponsPLS NBDOnsite H35276 | 97511-H35276 | \$ 3,484.00 | 10% | <i>\$3,159.12</i> |
| EW ResponsPLS NBDOnsite H35277 | 97511-H35277 | \$ 4,081.00 | 10% | <i>\$3,700.45</i> |
| EW ResponsPLS NBDOnsite H35278 | 97511-H35278 | \$ 3,168.00 | 10% | <i>\$2,872.58</i> |
| EW ResponsPLS NBDOnsite H35279 | 97511-H35279 | \$ 3,539.00 | 10% | <i>\$3,208.99</i> |
| EW ResponsPLS NBDOnsite H35280 | 97511-H35280 | \$ 6,591.00 | 10% | <i>\$5,976.39</i> |
| EW ResponsPLS NBDOnsite H35292 | 97511-H35292 | \$ 3,168.00 | 10% | <i>\$2,872.58</i> |
| EW ResponsPLS NBDOnsite H35293 | 97511-H35293 | \$ 3,539.00 | 10% | <i>\$3,208.99</i> |
| EW ResponsPLS NBDOnsite H35295 | 97511-H35295 | \$ 1,416.00 | 10% | <i>\$1,283.96</i> |
| EW ResponsPLS NBDOnsite H35302 | 97511-H35302 | \$ 3,652.00 | 10% | <i>\$3,311.45</i> |
| EW ResponsPLS NBDOnsite H35303 | 97511-H35303 | \$ 3,652.00 | 10% | <i>\$3,311.45</i> |
| EW ResponsPLS NBDOnsite H35304 | 97511-H35304 | \$ 3,652.00 | 10% | <i>\$3,311.45</i> |
| EW ResponsPLS NBDOnsite H35305 | 97511-H35305 | \$ 3,765.00 | 10% | <i>\$3,413.91</i> |
| EW ResponsPLS NBDOnsite H35306 | 97511-H35306 | \$ 3,765.00 | 10% | <i>\$3,413.91</i> |
| EW ResponsPLS NBDOnsite H35307 | 97511-H35307 | \$ 3,765.00 | 10% | <i>\$3,413.91</i> |
| EW ResponsPLS NBDOnsite H35309 | 97511-H35309 | \$ 4,036.00 | 10% | <i>\$3,659.64</i> |
| EW ResponsPLS NBDOnsite H35310 | 97511-H35310 | \$ 4,036.00 | 10% | <i>\$3,659.64</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H35311 | 97511-H35311 | \$ 4,036.00 | 10% | <i>\$3,659.64</i> |
| EW ResponsPLS NBDOnsite H35312 | 97511-H35312 | \$ 3,334.00 | 10% | <i>\$3,023.10</i> |
| EW ResponsPLS NBDOnsite H35313 | 97511-H35313 | \$ 3,334.00 | 10% | <i>\$3,023.10</i> |
| EW ResponsPLS NBDOnsite H35314 | 97511-H35314 | \$ 3,334.00 | 10% | <i>\$3,023.10</i> |
| EW ResponsPLS NBDOnsite H35315 | 97511-H35315 | \$ 2,159.00 | 10% | <i>\$1,957.67</i> |
| EW ResponsPLS NBDOnsite H35318 | 97511-H35318 | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsPLS NBDOnsite H35319 | 97511-H35319 | \$ 1,705.00 | 10% | <i>\$1,546.01</i> |
| EW ResponsPLS NBDOnsite H35320 | 97511-H35320 | \$ 1,745.00 | 10% | <i>\$1,582.28</i> |
| EW ResponsPLS NBDOnsite H35321 | 97511-H35321 | \$ 1,932.00 | 10% | <i>\$1,751.84</i> |
| EW ResponsPLS NBDOnsite H35322 | 97511-H35322 | \$ 2,181.00 | 10% | <i>\$1,977.62</i> |
| EW ResponsPLS NBDOnsite H35323 | 97511-H35323 | \$ 2,159.00 | 10% | <i>\$1,957.67</i> |
| EW ResponsPLS NBDOnsite H35328 | 97511-H35328 | \$ 806.00 | 10% | <i>\$730.84</i> |
| EW ResponsPLS NBDOnsite H35330 | 97511-H35330 | \$ 1,138.00 | 10% | <i>\$1,031.88</i> |
| EW ResponsPLS NBDOnsite H35340 | 97511-H35340 | \$ 4,120.00 | 10% | <i>\$3,735.81</i> |
| EW ResponsPLS NBDOnsite H35341 | 97511-H35341 | \$ 4,120.00 | 10% | <i>\$3,735.81</i> |
| EW ResponsPLS NBDOnsite H35342 | 97511-H35342 | \$ 3,458.00 | 10% | <i>\$3,135.54</i> |
| EW ResponsPLS NBDOnsite H35343 | 97511-H35343 | \$ 4,120.00 | 10% | <i>\$3,735.81</i> |
| EW ResponsPLS NBDOnsite H35344 | 97511-H35344 | \$ 4,239.00 | 10% | <i>\$3,843.71</i> |
| EW ResponsPLS NBDOnsite H35345 | 97511-H35345 | \$ 4,239.00 | 10% | <i>\$3,843.71</i> |
| EW ResponsPLS NBDOnsite H35346 | 97511-H35346 | \$ 3,541.00 | 10% | <i>\$3,210.80</i> |
| EW ResponsPLS NBDOnsite H35347 | 97511-H35347 | \$ 4,239.00 | 10% | <i>\$3,843.71</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H35349 | 97511-H35349 | \$ 4,528.00 | 10% | <i>\$4,105.76</i> |
| EW ResponsPLS NBDOnsite H35350 | 97511-H35350 | \$ 4,528.00 | 10% | <i>\$4,105.76</i> |
| EW ResponsPLS NBDOnsite H35351 | 97511-H35351 | \$ 3,775.00 | 10% | <i>\$3,422.98</i> |
| EW ResponsPLS NBDOnsite H35352 | 97511-H35352 | \$ 4,528.00 | 10% | <i>\$4,105.76</i> |
| EW ResponsPLS NBDOnsite H35359 | 97511-H35359 | \$ 1,932.00 | 10% | <i>\$1,751.84</i> |
| EW ResponsPLS NBDOnsite H35360 | 97511-H35360 | \$ 2,182.00 | 10% | <i>\$1,978.53</i> |
| EW ResponsPLS NBDOnsite H35361 | 97511-H35361 | \$ 2,159.00 | 10% | <i>\$1,957.67</i> |
| EW ResponsPLS NBDOnsite H35362 | 97511-H35362 | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsPLS NBDOnsite H35366 | 97511-H35366 | \$ 1,491.00 | 10% | <i>\$1,351.96</i> |
| EW ResponsPLS NBDOnsite H35367 | 97511-H35367 | \$ 1,740.00 | 10% | <i>\$1,577.75</i> |
| EW ResponsPLS NBDOnsite H35368 | 97511-H35368 | \$ 2,644.00 | 10% | <i>\$2,397.45</i> |
| EW ResponsPLS NBDOnsite H35369 | 97511-H35369 | \$ 863.00 | 10% | <i>\$782.53</i> |
| EW ResponsPLS NBDOnsite H35370 | 97511-H35370 | \$ 1,208.00 | 10% | <i>\$1,095.35</i> |
| EW ResponsPLS NBDOnsite H35375 | 97511-H35375 | \$ 1,017.00 | 10% | <i>\$922.16</i> |
| EW ResponsPLS NBDOnsite H35376 | 97511-H35376 | \$ 1,526.00 | 10% | <i>\$1,383.70</i> |
| EW ResponsPLS NBDOnsite H35377 | 97511-H35377 | \$ 636.00 | 10% | <i>\$576.69</i> |
| EW ResponsPLS NBDOnsite H35378 | 97511-H35378 | \$ 1,017.00 | 10% | <i>\$922.16</i> |
| EW ResponsPLS NBDOnsite H35379 | 97511-H35379 | \$ 636.00 | 10% | <i>\$576.69</i> |
| EW ResponsPLS NBDOnsite H35380 | 97511-H35380 | \$ 1,145.00 | 10% | <i>\$1,038.23</i> |
| EW ResponsPLS NBDOnsite H35381 | 97511-H35381 | \$ 1,400.00 | 10% | <i>\$1,269.45</i> |
| EW ResponsPLS NBDOnsite H35384 | 97511-H35384 | \$ 508.00 | 10% | <i>\$460.63</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H35385 | 97511-H35385 | \$ 680.00 | 10% | <i>\$616.59</i> |
| EW ResponsPLS NBDOnsite H35386 | 97511-H35386 | \$ 1,132.00 | 10% | <i>\$1,026.44</i> |
| EW ResponsPLS NBDOnsite H35387 | 97511-H35387 | \$ 1,058.00 | 10% | <i>\$959.34</i> |
| EW ResponsPLS NBDOnsite H35388 | 97511-H35388 | \$ 783.00 | 10% | <i>\$709.99</i> |
| EW ResponsPLS NBDOnsite H35389 | 97511-H35389 | \$ 440.00 | 10% | <i>\$398.97</i> |
| EW ResponsPLS NBDOnsite H35390 | 97511-H35390 | \$ 381.00 | 10% | <i>\$345.47</i> |
| EW ResponsPLS NBDOnsite H35391 | 97511-H35391 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW ResponsPLS NBDOnsite H35392 | 97511-H35392 | \$ 1,272.00 | 10% | <i>\$1,153.39</i> |
| EW ResponsPLS NBDOnsite H35393 | 97511-H35393 | \$ 1,698.00 | 10% | <i>\$1,539.66</i> |
| EW ResponsPLS NBDOnsite H35394 | 97511-H35394 | \$ 305.00 | 10% | <i>\$276.56</i> |
| EW ResponsPLS NBDOnsite H35395 | 97511-H35395 | \$ 254.00 | 10% | <i>\$230.31</i> |
| EW ResponsPLS NBDOnsite H35396 | 97511-H35396 | \$ 305.00 | 10% | <i>\$276.56</i> |
| EW ResponsPLS NBDOnsite H35397 | 97511-H35397 | \$ 254.00 | 10% | <i>\$230.31</i> |
| EW ResponsPLS NBDOnsite H35398 | 97511-H35398 | \$ 795.00 | 10% | <i>\$720.87</i> |
| EW ResponsPLS NBDOnsite H35399 | 97511-H35399 | \$ 961.00 | 10% | <i>\$871.39</i> |
| EW ResponsPLS NBDOnsite H35400 | 97511-H35400 | \$ 1,062.00 | 10% | <i>\$962.97</i> |
| EW ResponsPLS NBDOnsite H35401 | 97511-H35401 | \$ 566.00 | 10% | <i>\$513.22</i> |
| EW ResponsPLS NBDOnsite H35415 | 97511-H35415 | \$ 353.00 | 10% | <i>\$320.08</i> |
| EW ResponsPLS NBDOnsite H35416 | 97511-H35416 | \$ 353.00 | 10% | <i>\$320.08</i> |
| EW ResponsPLS NBDOnsite H35426 | 97511-H35426 | \$ 440.00 | 10% | <i>\$398.97</i> |
| EW ResponsPLS NBDOnsite H35427 | 97511-H35427 | \$ 1,058.00 | 10% | <i>\$959.34</i> |

| | | | | |
|-----------------------------------|--------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite H35428 | 97511-H35428 | \$ 381.00 | 10% | <i>\$345.47</i> |
| EW ResponsPLS NBDOnsite H35429 | 97511-H35429 | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW ResponsPLS NBDOnsite H35430 | 97511-H35430 | \$ 1,579.00 | 10% | <i>\$1,431.76</i> |
| EW ResponsPLS NBDOnsite H35431 | 97511-H35431 | \$ 1,579.00 | 10% | <i>\$1,431.76</i> |
| EW ResponsPLS NBDOnsite H35432 | 97511-H35432 | \$ 1,544.00 | 10% | <i>\$1,400.02</i> |
| EW ResponsPLS NBDOnsite H35433 | 97511-H35433 | \$ 1,678.00 | 10% | <i>\$1,521.53</i> |
| EW ResponsPLS NBDOnsite H35434 | 97511-H35434 | \$ 1,741.00 | 10% | <i>\$1,578.65</i> |
| EW ResponsPLS NBDOnsite H35435 | 97511-H35435 | \$ 1,741.00 | 10% | <i>\$1,578.65</i> |
| EW ResponsPLS NBDOnsite H35436 | 97511-H35436 | \$ 2,097.00 | 10% | <i>\$1,901.45</i> |
| EW ResponsPLS NBDOnsite H35437 | 97511-H35437 | \$ 2,097.00 | 10% | <i>\$1,901.45</i> |
| EW ResponsPLS NBDOnsite H35438 | 97511-H35438 | \$ 2,097.00 | 10% | <i>\$1,901.45</i> |
| EW ResponsPLS NBDOnsite H35439 | 97511-H35439 | \$ 2,097.00 | 10% | <i>\$1,901.45</i> |
| EW ResponsPLS NBDOnsite H35440 | 97511-H35440 | \$ 1,678.00 | 10% | <i>\$1,521.53</i> |
| EW ResponsPLS NBDOnsite H35441 | 97511-H35441 | \$ 1,678.00 | 10% | <i>\$1,521.53</i> |
| EW ResponsPLS NBDOnsite H35442 | 97511-H35442 | \$ 1,678.00 | 10% | <i>\$1,521.53</i> |
| EW ResponsPLS NBDOnsite H35443 | 97511-H35443 | \$ 3,655.00 | 10% | <i>\$3,314.17</i> |
| EW ResponsPLS NBDOnsite H35444 | 97511-H35444 | \$ 3,832.00 | 10% | <i>\$3,474.67</i> |
| EW ResponsPLS NBDOnsite H35445 | 97511-H35445 | \$ 3,484.00 | 10% | <i>\$3,159.12</i> |
| EW ResponsPLS NBDOnsite H35446 | 97511-H35446 | \$ 3,417.00 | 10% | <i>\$3,098.36</i> |
| EW ResponsPLS NBDOnsite H35447 | 97511-H35447 | \$ 3,868.00 | 10% | <i>\$3,507.31</i> |
| EW ResponsPLS NBDOnsite H35448 | 97511-H35448 | \$ 3,758.00 | 10% | <i>\$3,407.57</i> |

| | | | | |
|--|-------------------------|-------------|-----|------------|
| EW ResponsPLS NBDOnsite H35449 | 97511-H35449 | \$ 3,168.00 | 10% | \$2,872.58 |
| EW ResponsPLS NBDOnsite H35450 | 97511-H35450 | \$ 3,354.00 | 10% | \$3,041.24 |
| EW ResponsPLS NBDOnsite H35451 | 97511-H35451 | \$ 6,975.00 | 10% | \$6,324.58 |
| EW ResponsPLS NBDOnsite H35452 | 97511-H35452 | \$ 6,975.00 | 10% | \$6,324.58 |
| EW ResponsPLS NBDOnsite H35453 | 97511-H35453 | \$ 3,832.00 | 10% | \$3,474.67 |
| EW ResponsPLS NBDOnsite H35454 | 97511-H35454 | \$ 3,655.00 | 10% | \$3,314.17 |
| EW ResponsPLS NBDOnsite H35455 | 97511-H35455 | \$ 1,745.00 | 10% | \$1,582.28 |
| EW ResponsPLS NBDOnsite H35456 | 97511-H35456 | \$ 1,913.00 | 10% | \$1,734.61 |
| EW ResponsPLS NBDOnsite H35457 | 97511-H35457 | \$ 1,840.00 | 10% | \$1,668.42 |
| EW ResponsPLS NBDOnsite H35458 | 97511-H35458 | \$ 1,923.00 | 10% | \$1,743.68 |
| EW ResponsPLS NBDOnsite H35471 | 97511-H35471 | \$ 1,746.00 | 10% | \$1,583.19 |
| EW ResponsPLS NBDOnsite H35600 | 97511-H35600 | \$ 1,359.00 | 10% | \$1,232.27 |
| EW ResponsPLS NBDOnsite H35601 | 97511-H35601 | \$ 1,359.00 | 10% | \$1,232.27 |
| EW ResponsPLS NBDOnsite H35602 | 97511-H35602 | \$ 1,626.00 | 10% | \$1,474.38 |
| EW ResponsPLS NBDOnsite H35603 | 97511-H35603 | \$ 1,626.00 | 10% | \$1,474.38 |
| EW ResponsPLS NBDOnsite H35604 | 97511-H35604 | \$ 1,728.00 | 10% | \$1,566.86 |
| EW ResponsPLS NBDOnsite H35605 | 97511-H35605 | \$ 1,728.00 | 10% | \$1,566.86 |
| EW ResponsPLS NBDOnsite H35606 | 97511-H35606 | \$ 1,793.00 | 10% | \$1,625.80 |
| EW ResponsPLS NBDOnsite H35607 | 97511-H35607 | \$ 1,784.00 | 10% | \$1,617.64 |
| EW ResponsPLS NBDOnsite ISW-24W-4X | 97511-ISW- 24W-4X | \$ 1,603.00 | 10% | \$1,453.52 |
| EW ResponsPLS NBDOnsite ISW-4W-4WS-4X | 97511-ISW-4W- 4WS-4X | \$ 1,313.00 | 10% | \$1,190.56 |

| | | | | |
|--|-------------------------|--------------|-----|-------------|
| EW ResponsPLUS NBDOnsite-MS128 | 97511-MSM128 | \$ 3,011.00 | 10% | \$2,730.22 |
| EW ResponsPLS NBDOnsite-MSM48C | 97511-MSM48C | \$ 2,110.00 | 10% | \$1,913.24 |
| EW ResponsPLS NBDOnsit SLX9150-48XT-DC-F | 97511-SLX9150-48XT-DC-F | \$ 3,696.00 | 10% | \$3,351.35 |
| EW ResponsPLS NBDOnsit SLX9150-48XT-DC-R | 97511-SLX9150-48XT-DC-R | \$ 4,036.00 | 10% | \$3,659.64 |
| EW ResponsPLS NBDOnsite SLX9150-48Y-DC-F | 97511-SLX9150-48Y-DC-F | \$ 3,594.00 | 10% | \$3,258.86 |
| EW ResponsPLS NBDOnsite SLX9150-48Y-DC-R | 97511-SLX9150-48Y-DC-R | \$ 3,925.00 | 10% | \$3,558.99 |
| EW ResponsPLS NBDOnsite SLX9740-40C | 97511-SLX9740-40C | \$ 11,553.00 | 10% | \$10,475.68 |
| EW ResponsPLS NBDOnsite SLX9740-40C-AC-F | 97511-SLX9740-40C-AC-F | \$ 11,553.00 | 10% | \$10,475.68 |
| EW ResponsPLS NBDOnsite SLX9740-40C-AC-R | 97511-SLX9740-40C-AC-R | \$ 11,553.00 | 10% | \$10,475.68 |
| EW ResponsPLS NBDOnsite SLX9740-40C-DC-F | 97511-SLX9740-40C-DC-F | \$ 11,553.00 | 10% | \$10,475.68 |
| EW ResponsPLS NBDOnsite SLX9740-80C | 97511-SLX9740-80C | \$ 20,763.00 | 10% | \$18,826.85 |
| EW ResponsPLS NBDOnsite SLX9740-80C-AC-F | 97511-SLX9740-80C-AC-F | \$ 20,763.00 | 10% | \$18,826.85 |
| EW ResponsPLS NBDOnsite SLX9740-80C-AC-R | 97511-SLX9740-80C-AC-R | \$ 20,763.00 | 10% | \$18,826.85 |
| EW ResponsPLS NBDOnsite SLX9740-80C-DC-F | 97511-SLX9740-80C-DC-F | \$ 20,763.00 | 10% | \$18,826.85 |
| EW ResponsPLS NBDOnsite V300-8P-2X | 97511-V300-8P-2X | \$ 835.00 | 10% | \$757.14 |
| EW ResponsPLS NBDOnsite V300-8T-2X | 97511-V300-8T-2X | \$ 795.00 | 10% | \$720.87 |

| | | | | |
|---|---|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite V300HT-8P-2X | 97511-V300HT- 8P-2X | \$ 1,129.00 | 10% | <i>\$1,023.72</i> |
| EW ResponsPLS NBDOnsite V300HT-8T-2X | 97511-V300HT- 8T-2X | \$ 960.00 | 10% | <i>\$870.48</i> |
| EW ResponsPLS NBDOnsite- VIM-SS | 97511-VIM-SS | \$ 584.00 | 10% | <i>\$529.54</i> |
| EW ResponsPLS NBDOnsiteVIMSSV8 | 97511-VIM- SSV80 | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW ResponsPLS NBDOnsiteVIM2SS | 97511-VIM2- SS | \$ 586.00 | 10% | <i>\$531.36</i> |
| EW ResponsPLS NBDOnsiteVIM2SS | 97511-VIM2- SS128 | \$ 979.00 | 10% | <i>\$887.71</i> |
| EW ResponsPLS NBDOnsiteVIM2V80 | 97511-VIM2- V80 | \$ 1,045.00 | 10% | <i>\$947.55</i> |
| EW ResponsPLS NBDOnsiteVIM | 97511- VIM210G4X | \$ 1,462.00 | 10% | <i>\$1,325.67</i> |
| EW ResPLS NBDOnsit VSP4900-12MXU-12XE | 97511- VSP4900- 12MXU-12XE | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |
| EW ResPLS NBDOnsit VSP4900-12MXU-12XE-B1 | 97511- VSP4900- 12MXU-12XE- B1 | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |
| EW ResponsPLS NBDOnsite VSP4900-24S | 97511- VSP4900-24S | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsPLS NBDOnsite VSP4900-24S-B3 | 97511- VSP4900-24S- B3 | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsPLS NBDOnsite VSP4900-24XE | 97511- VSP4900- 24XE | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |
| EW ResponsPLS NBDOnsite VSP4900-24XE-B3 | 97511- VSP4900- 24XE-B3 | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |
| EW ResponsPLS NBDOnsite X435-24P-4S | 97511-X435- 24P-4S | \$ 936.00 | 10% | <i>\$848.72</i> |
| EW ResponsPLS NBDOnsite X435-24T-4S | 97511-X435- 24T-4S | \$ 833.00 | 10% | <i>\$755.32</i> |
| EW ResponsPLS NBDOnsite X435-8P-2T-W | 97511-X435- 8P-2T-W | \$ 833.00 | 10% | <i>\$755.32</i> |

| | | | | |
|---|------------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite X435-8P-4S | 97511-X435- 8P-4S | \$ 822.00 | 10% | <i>\$745.35</i> |
| EW ResponsPLS NBDOnsite X435-8T-4S | 97511-X435- 8T-4S | \$ 800.00 | 10% | <i>\$725.40</i> |
| EW ResponsPLS NBDOnsiteX46024P | 97511-X460- 24P | \$ 2,312.00 | 10% | <i>\$2,096.41</i> |
| EW ResponsPLS NBDOnsiteX46024T | 97511-X460- 24T | \$ 1,997.00 | 10% | <i>\$1,810.78</i> |
| EW ResponsPLS NBDOnsiteX46024T | 97511-X460- 24TDC | \$ 2,356.00 | 10% | <i>\$2,136.30</i> |
| EW ResponsPLS NBDOnsiteX46024X | 97511-X460- 24X | \$ 2,577.00 | 10% | <i>\$2,336.69</i> |
| EW ResponsPLS NBDOnsiteX46024X | 97511-X460- 24XDC | \$ 2,775.00 | 10% | <i>\$2,516.23</i> |
| EW ResponsPLS NBDOnsiteX46048P | 97511-X460- 48P | \$ 2,577.00 | 10% | <i>\$2,336.69</i> |
| EW ResponsPLS NBDOnsiteX46048T | 97511-X460- 48T | \$ 2,399.00 | 10% | <i>\$2,175.29</i> |
| EW ResponsPLS NBDOnsiteX46048T | 97511-X460- 48TDC | \$ 2,730.00 | 10% | <i>\$2,475.43</i> |
| EW ResponsPLS NBDOnsiteX46048X | 97511-X460- 48X | \$ 2,995.00 | 10% | <i>\$2,715.72</i> |
| EW ResponsPLS NBDOnsiteX46048X | 97511-X460- 48XDC | \$ 3,010.00 | 10% | <i>\$2,729.32</i> |
| EW ResponsPLS NBDOnsite X465-24MU | 97511-X465- 24MU | \$ 2,181.00 | 10% | <i>\$1,977.62</i> |
| EW ResponsPLS NBDOnsite X465-24S | 97511-X465- 24S | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsPLS NBDOnsite X465-24S-B3 | 97511-X465- 24S-B3 | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsPLS NBDOnsite X465-24W | 97511-X465- 24W | \$ 1,530.00 | 10% | <i>\$1,387.33</i> |
| EW ResponsPLS NBDOnsite X465-24XE | 97511-X465- 24XE | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |
| EW ResponsPLS NBDOnsite X465-24XE-B3 | 97511-X465- 24XE-B3 | \$ 2,026.00 | 10% | <i>\$1,837.08</i> |
| EW ResponsPLS NBDOnsite X465-48P | 97511-X465- 48P | \$ 1,746.00 | 10% | <i>\$1,583.19</i> |
| EW ResponsPLS NBDOnsite X465-48T | 97511-X465- 48T | \$ 1,705.00 | 10% | <i>\$1,546.01</i> |
| EW ResponsPLS NBDOnsite X465-48W | 97511-X465- 48W | \$ 1,932.00 | 10% | <i>\$1,751.84</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EW ResponsPLS NBDOnsite X465i-48W | 97511-X465i- 48W | \$ 2,159.00 | 10% | <i>\$1,957.67</i> |
| EW ResponsPLS NBDOnsite X465i-48W-B1-S1 | 97511-X465i- 48W-B1-S1 | \$ 2,159.00 | 10% | <i>\$1,957.67</i> |
| EW ResponsPLS NBDOnsite X465i-48W-B2-S1 | 97511-X465i- 48W-B2-S1 | \$ 2,159.00 | 10% | <i>\$1,957.67</i> |
| EW ResponsPLS NBDOnsiteX48024X | 97511-X480- 24X | \$ 2,703.00 | 10% | <i>\$2,450.95</i> |
| EW ResponsPLUS NBDOnsite- X480T | 97511-X480- 48T | \$ 2,297.00 | 10% | <i>\$2,082.80</i> |
| EW ResponsPLS NBDOnsite- X48048 | 97511-X480- 48X | \$ 3,222.00 | 10% | <i>\$2,921.55</i> |
| EW ResponsPLS NBDOnsite X695-48Y-8C | 97511-X695- 48Y-8C | \$ 3,363.00 | 10% | <i>\$3,049.40</i> |
| EW ResponsPLS NBDOnsite XA1440 | 97511-XA1440 | \$ 957.00 | 10% | <i>\$867.76</i> |
| EW ResponsPLS NBDOnsite XA1480 | 97511-XA1480 | \$ 1,050.00 | 10% | <i>\$952.09</i> |
| EW ResponsPLS NBDOnsiteXGM32SF | 97511-XGM3- 2SF | \$ 710.00 | 10% | <i>\$643.79</i> |
| EW ResponsPLS NBDOnsite XR600 | 97511-XR600 | \$ 1,193.00 | 10% | <i>\$1,081.75</i> |
| EWP Premier TAC OS 10200 | 98000-10200 | \$ 1,726.00 | 6% | <i>\$1,634.61</i> |
| EWP Premier TAC OS 10320 | 98000-10320 | \$ 1,893.00 | 6% | <i>\$1,792.77</i> |
| EWP Premier TAC OS 10330 | 98000-10330 | \$ 4,553.00 | 6% | <i>\$4,311.92</i> |
| EWP Premier TAC OS 10331 | 98000-10331 | \$ 2,096.00 | 6% | <i>\$1,985.02</i> |
| EWP Premier TAC OS 10335 | 98000-10335 | \$ 3,268.00 | 6% | <i>\$3,094.96</i> |
| EWP Premier TAC OS 10403 | 98000-10403 | \$ 4,165.00 | 6% | <i>\$3,944.46</i> |
| EWP Premier TAC OS 10404 | 98000-10404 | \$ 1,990.00 | 6% | <i>\$1,884.63</i> |
| EWP Premier TAC OS 10441 | 98000-10441 | \$ 1,341.00 | 6% | <i>\$1,269.99</i> |
| EWP Premier TAC OS 10442 | 98000-10442 | \$ 1,418.00 | 6% | <i>\$1,342.92</i> |
| EWP Premier TAC OS 11011 | 98000-11011 | \$ 201.00 | 6% | <i>\$190.36</i> |
| EWP Premier TAC OS 1130C | 98000-1130C | \$ 768.00 | 6% | <i>\$727.33</i> |
| EWP Premier TAC OS 16119 | 98000-16119 | \$ 239.00 | 6% | <i>\$226.34</i> |
| EWP Premier TAC OS 16120 | 98000-16120 | \$ 292.00 | 6% | <i>\$276.54</i> |
| EWP Premier TAC OS 16126 | 98000-16126 | \$ 239.00 | 6% | <i>\$226.34</i> |
| EWP Premier TAC OS 16127 | 98000-16127 | \$ 251.00 | 6% | <i>\$237.71</i> |
| EWP Premier TAC OS 16169 | 98000-16169 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier TAC OS 16172 | 98000-16172 | \$ 252.00 | 6% | <i>\$238.66</i> |
| EWP Premier TAC OS 16172T | 98000-16172T | \$ 299.00 | 6% | <i>\$283.17</i> |
| EWP Premier TAC OS 16173 | 98000-16173 | \$ 252.00 | 6% | <i>\$238.66</i> |
| EWP Premier TAC OS 16173T | 98000-16173T | \$ 299.00 | 6% | <i>\$283.17</i> |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS 16174 | 98000-16174 | \$ 410.00 | 6% | \$388.29 |
| EWP Premier TAC OS 16175 | 98000-16175 | \$ 420.00 | 6% | \$397.76 |
| EWP Premier TAC OS 16176 | 98000-16176 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS 16177 | 98000-16177 | \$ 364.00 | 6% | \$344.73 |
| EWP Premier TAC OS 16177T | 98000-16177T | \$ 460.00 | 6% | \$435.64 |
| EWP Premier TAC OS 16178 | 98000-16178 | \$ 537.00 | 6% | \$508.57 |
| EWP Premier TAC OS 16179 | 98000-16179 | \$ 551.00 | 6% | \$521.82 |
| EWP Premier TAC OS 16179T | 98000-16179T | \$ 659.00 | 6% | \$624.11 |
| EWP Premier TAC OS 16190 | 98000-16190 | \$ 149.00 | 6% | \$141.11 |
| EWP Premier TAC OS 16191 | 98000-16191 | \$ 296.00 | 6% | \$280.33 |
| EWP Premier TAC OS 16192 | 98000-16192 | \$ 296.00 | 6% | \$280.33 |
| EWP Premier TAC OS 16200 | 98000-16200 | \$ 165.00 | 6% | \$156.26 |
| EWP Premier TAC OS 16301T | 98000-16301T | \$ 1,393.00 | 6% | \$1,319.24 |
| EWP Premier TAC OS 16303T | 98000-16303T | \$ 1,393.00 | 6% | \$1,319.24 |
| EWP Premier TAC OS 16304T | 98000-16304T | \$ 1,850.00 | 6% | \$1,752.04 |
| EWP Premier TAC OS 16323 | 98000-16323 | \$ 165.00 | 6% | \$156.26 |
| EWP Premier TAC OS 16401T | 98000-16401T | \$ 641.00 | 6% | \$607.06 |
| EWP Premier TAC OS 16402T | 98000-16402T | \$ 977.00 | 6% | \$925.27 |
| EWP Premier TAC OS 16403T | 98000-16403T | \$ 867.00 | 6% | \$821.09 |
| EWP Premier TAC OS 16404T | 98000-16404T | \$ 867.00 | 6% | \$821.09 |
| EWP Premier TAC OS 16405T | 98000-16405T | \$ 1,142.00 | 6% | \$1,081.53 |
| EWP Premier TAC OS 16406T | 98000-16406T | \$ 1,529.00 | 6% | \$1,448.04 |
| EWP Premier TAC OS 16423 | 98000-16423 | \$ 307.00 | 6% | \$290.74 |
| EWP Premier TAC OS 16425 | 98000-16425 | \$ 165.00 | 6% | \$156.26 |
| EWP Premier TAC OS 16426 | 98000-16426 | \$ 136.00 | 6% | \$128.80 |
| EWP Premier TAC OS 16431 | 98000-16431 | \$ 988.00 | 6% | \$935.69 |
| EWP Premier TAC OS 16432 | 98000-16432 | \$ 1,043.00 | 6% | \$987.77 |
| EWP Premier TAC OS 16440 | 98000-16440 | \$ 618.00 | 6% | \$585.28 |
| EWP Premier TAC OS 16441 | 98000-16441 | \$ 557.00 | 6% | \$527.51 |
| EWP Premier TAC OS 16442 | 98000-16442 | \$ 251.00 | 6% | \$237.71 |
| EWP Premier TAC OS 16444 | 98000-16444 | \$ 125.00 | 6% | \$118.38 |
| EWP Premier TAC OS 16490 | 98000-16490 | \$ 111.00 | 6% | \$105.12 |
| EWP Premier TAC OS 16491 | 98000-16491 | \$ 237.00 | 6% | \$224.45 |
| EWP Premier TAC OS 16492 | 98000-16492 | \$ 363.00 | 6% | \$343.78 |
| EWP Premier TAC OS 16493 | 98000-16493 | \$ 363.00 | 6% | \$343.78 |
| EWP Premier TAC OS 16495 | 98000-16495 | \$ 111.00 | 6% | \$105.12 |
| EWP Premier TAC OS 16496 | 98000-16496 | \$ 338.00 | 6% | \$320.10 |
| EWP Premier TAC OS 16501 | 98000-16501 | \$ 132.00 | 6% | \$125.01 |
| EWP Premier TAC OS 16501T | 98000-16501T | \$ 197.00 | 6% | \$186.57 |
| EWP Premier TAC OS 16502 | 98000-16502 | \$ 197.00 | 6% | \$186.57 |
| EWP Premier TAC OS 16502T | 98000-16502T | \$ 233.00 | 6% | \$220.66 |
| EWP Premier TAC OS 16503 | 98000-16503 | \$ 162.00 | 6% | \$153.42 |

| | | | | |
|---------------------------|--------------|-----------|----|-----------------|
| EWP Premier TAC OS 16503T | 98000-16503T | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier TAC OS 16504 | 98000-16504 | \$ 263.00 | 6% | <i>\$249.07</i> |
| EWP Premier TAC OS 16504T | 98000-16504T | \$ 314.00 | 6% | <i>\$297.37</i> |
| EWP Premier TAC OS 16505 | 98000-16505 | \$ 286.00 | 6% | <i>\$270.86</i> |
| EWP Premier TAC OS 16505T | 98000-16505T | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWP Premier TAC OS 16506 | 98000-16506 | \$ 443.00 | 6% | <i>\$419.54</i> |
| EWP Premier TAC OS 16506T | 98000-16506T | \$ 540.00 | 6% | <i>\$511.41</i> |
| EWP Premier TAC OS 16507 | 98000-16507 | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWP Premier TAC OS 16507T | 98000-16507T | \$ 473.00 | 6% | <i>\$447.95</i> |
| EWP Premier TAC OS 16508 | 98000-16508 | \$ 503.00 | 6% | <i>\$476.37</i> |
| EWP Premier TAC OS 16508T | 98000-16508T | \$ 605.00 | 6% | <i>\$572.97</i> |
| EWP Premier TAC OS 16509 | 98000-16509 | \$ 503.00 | 6% | <i>\$476.37</i> |
| EWP Premier TAC OS 16509T | 98000-16509T | \$ 605.00 | 6% | <i>\$572.97</i> |
| EWP Premier TAC OS 16510 | 98000-16510 | \$ 605.00 | 6% | <i>\$572.97</i> |
| EWP Premier TAC OS 16510T | 98000-16510T | \$ 722.00 | 6% | <i>\$683.77</i> |
| EWP Premier TAC OS 16513 | 98000-16513 | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWP Premier TAC OS 16514 | 98000-16514 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier TAC OS 16515 | 98000-16515 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier TAC OS 16516 | 98000-16516 | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier TAC OS 16517 | 98000-16517 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier TAC OS 16518 | 98000-16518 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier TAC OS 16519 | 98000-16519 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier TAC OS 16520 | 98000-16520 | \$ 343.00 | 6% | <i>\$324.84</i> |
| EWP Premier TAC OS 16521 | 98000-16521 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier TAC OS 16522 | 98000-16522 | \$ 135.00 | 6% | <i>\$127.85</i> |
| EWP Premier TAC OS 16523 | 98000-16523 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier TAC OS 16524 | 98000-16524 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier TAC OS 16530 | 98000-16530 | \$ 136.00 | 6% | <i>\$128.80</i> |
| EWP Premier TAC OS 16531 | 98000-16531 | \$ 175.00 | 6% | <i>\$165.73</i> |
| EWP Premier TAC OS 16531T | 98000-16531T | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier TAC OS 16532 | 98000-16532 | \$ 175.00 | 6% | <i>\$165.73</i> |
| EWP Premier TAC OS 16532T | 98000-16532T | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier TAC OS 16533 | 98000-16533 | \$ 249.00 | 6% | <i>\$235.82</i> |
| EWP Premier TAC OS 16533T | 98000-16533T | \$ 285.00 | 6% | <i>\$269.91</i> |
| EWP Premier TAC OS 16534 | 98000-16534 | \$ 262.00 | 6% | <i>\$248.13</i> |
| EWP Premier TAC OS 16535 | 98000-16535 | \$ 388.00 | 6% | <i>\$367.46</i> |
| EWP Premier TAC OS 16535A | 98000-16535A | \$ 388.00 | 6% | <i>\$367.46</i> |
| EWP Premier TAC OS 16535T | 98000-16535T | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWP Premier TAC OS 16536 | 98000-16536 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier TAC OS 16537 | 98000-16537 | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier TAC OS 16538 | 98000-16538 | \$ 289.00 | 6% | <i>\$273.70</i> |
| EWP Premier TAC OS 16538T | 98000-16538T | \$ 366.00 | 6% | <i>\$346.62</i> |

| | | | | |
|---------------------------|--------------|-----------|----|----------|
| EWP Premier TAC OS 16539 | 98000-16539 | \$ 376.00 | 6% | \$356.09 |
| EWP Premier TAC OS 16540 | 98000-16540 | \$ 269.00 | 6% | \$254.76 |
| EWP Premier TAC OS 16541 | 98000-16541 | \$ 108.00 | 6% | \$102.28 |
| EWP Premier TAC OS 16560 | 98000-16560 | \$ 65.00 | 6% | \$61.56 |
| EWP Premier TAC OS 16561 | 98000-16561 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier TAC OS 16562 | 98000-16562 | \$ 108.00 | 6% | \$102.28 |
| EWP Premier TAC OS 16563 | 98000-16563 | \$ 146.00 | 6% | \$138.27 |
| EWP Premier TAC OS 16564 | 98000-16564 | \$ 174.00 | 6% | \$164.79 |
| EWP Premier TAC OS 16565 | 98000-16565 | \$ 269.00 | 6% | \$254.76 |
| EWP Premier TAC OS 16566 | 98000-16566 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS 16567 | 98000-16567 | \$ 80.00 | 6% | \$75.76 |
| EWP Premier TAC OS 16568 | 98000-16568 | \$ 65.00 | 6% | \$61.56 |
| EWP Premier TAC OS 16569 | 98000-16569 | \$ 102.00 | 6% | \$96.60 |
| EWP Premier TAC OS 16570 | 98000-16570 | \$ 108.00 | 6% | \$102.28 |
| EWP Premier TAC OS 16571 | 98000-16571 | \$ 174.00 | 6% | \$164.79 |
| EWP Premier TAC OS 16701 | 98000-16701 | \$ 369.00 | 6% | \$349.46 |
| EWP Premier TAC OS 16702 | 98000-16702 | \$ 539.00 | 6% | \$510.46 |
| EWP Premier TAC OS 16703 | 98000-16703 | \$ 429.00 | 6% | \$406.28 |
| EWP Premier TAC OS 16703T | 98000-16703T | \$ 507.00 | 6% | \$480.15 |
| EWP Premier TAC OS 16704 | 98000-16704 | \$ 624.00 | 6% | \$590.96 |
| EWP Premier TAC OS 16704T | 98000-16704T | \$ 739.00 | 6% | \$699.87 |
| EWP Premier TAC OS 16705 | 98000-16705 | \$ 539.00 | 6% | \$510.46 |
| EWP Premier TAC OS 16705T | 98000-16705T | \$ 652.00 | 6% | \$617.48 |
| EWP Premier TAC OS 16706 | 98000-16706 | \$ 810.00 | 6% | \$767.11 |
| EWP Premier TAC OS 16706T | 98000-16706T | \$ 974.00 | 6% | \$922.43 |
| EWP Premier TAC OS 16710 | 98000-16710 | \$ 173.00 | 6% | \$163.84 |
| EWP Premier TAC OS 16710T | 98000-16710T | \$ 208.00 | 6% | \$196.99 |
| EWP Premier TAC OS 16711 | 98000-16711 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier TAC OS 16711T | 98000-16711T | \$ 84.00 | 6% | \$79.55 |
| EWP Premier TAC OS 16712 | 98000-16712 | \$ 103.00 | 6% | \$97.55 |
| EWP Premier TAC OS 16712T | 98000-16712T | \$ 122.00 | 6% | \$115.54 |
| EWP Premier TAC OS 16713 | 98000-16713 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS 16713T | 98000-16713T | \$ 62.00 | 6% | \$58.72 |
| EWP Premier TAC OS 16715 | 98000-16715 | \$ 73.00 | 6% | \$69.13 |
| EWP Premier TAC OS 16715T | 98000-16715T | \$ 84.00 | 6% | \$79.55 |
| EWP Premier TAC OS 16716 | 98000-16716 | \$ 281.00 | 6% | \$266.12 |
| EWP Premier TAC OS 16716T | 98000-16716T | \$ 336.00 | 6% | \$318.21 |
| EWP Premier TAC OS 16717 | 98000-16717 | \$ 432.00 | 6% | \$409.13 |
| EWP Premier TAC OS 16718 | 98000-16718 | \$ 305.00 | 6% | \$288.85 |
| EWP Premier TAC OS 16718T | 98000-16718T | \$ 367.00 | 6% | \$347.57 |
| EWP Premier TAC OS 16719 | 98000-16719 | \$ 461.00 | 6% | \$436.59 |
| EWP Premier TAC OS 16719T | 98000-16719T | \$ 553.00 | 6% | \$523.72 |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS 16720 | 98000-16720 | \$ 708.00 | 6% | \$670.51 |
| EWP Premier TAC OS 16720T | 98000-16720T | \$ 820.00 | 6% | \$776.58 |
| EWP Premier TAC OS 16755 | 98000-16755 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier TAC OS 16756 | 98000-16756 | \$ 523.00 | 6% | \$495.31 |
| EWP Premier TAC OS 16756T | 98000-16756T | \$ 616.00 | 6% | \$583.38 |
| EWP Premier TAC OS 16757 | 98000-16757 | \$ 490.00 | 6% | \$464.05 |
| EWP Premier TAC OS 16757T | 98000-16757T | \$ 569.00 | 6% | \$538.87 |
| EWP Premier TAC OS 16778 | 98000-16778 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS 16779 | 98000-16779 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS 16780 | 98000-16780 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS 16790 | 98000-16790 | \$ 1,097.00 | 6% | \$1,038.91 |
| EWP Premier TAC OS 16791 | 98000-16791 | \$ 1,416.00 | 6% | \$1,341.02 |
| EWP Premier TAC OS 16795 | 98000-16795 | \$ 198.00 | 6% | \$187.52 |
| EWP Premier TAC OS 16801 | 98000-16801 | \$ 146.00 | 6% | \$138.27 |
| EWP Premier TAC OS 16802 | 98000-16802 | \$ 174.00 | 6% | \$164.79 |
| EWP Premier TAC OS 16803 | 98000-16803 | \$ 182.00 | 6% | \$172.36 |
| EWP Premier TAC OS 16804 | 98000-16804 | \$ 226.00 | 6% | \$214.03 |
| EWP Premier TAC OS 16805 | 98000-16805 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS 16806 | 98000-16806 | \$ 42.00 | 6% | \$39.78 |
| EWP Premier TAC OS 17101 | 98000-17101 | \$ 2,159.00 | 6% | \$2,044.68 |
| EWP Premier TAC OS 17101T | 98000-17101T | \$ 2,584.00 | 6% | \$2,447.18 |
| EWP Premier TAC OS 17102 | 98000-17102 | \$ 2,159.00 | 6% | \$2,044.68 |
| EWP Premier TAC OS 17102T | 98000-17102T | \$ 2,584.00 | 6% | \$2,447.18 |
| EWP Premier TAC OS 17103 | 98000-17103 | \$ 1,505.00 | 6% | \$1,425.31 |
| EWP Premier TAC OS 17103C | 98000-17103C | \$ 1,367.00 | 6% | \$1,294.62 |
| EWP Premier TAC OS 17103T | 98000-17103T | \$ 1,805.00 | 6% | \$1,709.43 |
| EWP Premier TAC OS 17104 | 98000-17104 | \$ 1,505.00 | 6% | \$1,425.31 |
| EWP Premier TAC OS 17104T | 98000-17104T | \$ 1,805.00 | 6% | \$1,709.43 |
| EWP Premier TAC OS 17121 | 98000-17121 | \$ 434.00 | 6% | \$411.02 |
| EWP Premier TAC OS 17122 | 98000-17122 | \$ 268.00 | 6% | \$253.81 |
| EWP Premier TAC OS 17131 | 98000-17131 | \$ 516.00 | 6% | \$488.68 |
| EWP Premier TAC OS 17133 | 98000-17133 | \$ 316.00 | 6% | \$299.27 |
| EWP Premier TAC OS 17134 | 98000-17134 | \$ 479.00 | 6% | \$453.64 |
| EWP Premier TAC OS 17135 | 98000-17135 | \$ 395.00 | 6% | \$374.08 |
| EWP Premier TAC OS 17136 | 98000-17136 | \$ 79.00 | 6% | \$74.82 |
| EWP Premier TAC OS 17137 | 98000-17137 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier TAC OS 17138 | 98000-17138 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier TAC OS 17139 | 98000-17139 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier TAC OS 17200 | 98000-17200 | \$ 3,396.00 | 6% | \$3,216.18 |
| EWP Premier TAC OS 17200T | 98000-17200T | \$ 3,711.00 | 6% | \$3,514.50 |
| EWP Premier TAC OS 17201 | 98000-17201 | \$ 3,396.00 | 6% | \$3,216.18 |
| EWP Premier TAC OS 17201T | 98000-17201T | \$ 3,711.00 | 6% | \$3,514.50 |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS 17202 | 98000-17202 | \$ 3,396.00 | 6% | \$3,216.18 |
| EWP Premier TAC OS 17202T | 98000-17202T | \$ 3,711.00 | 6% | \$3,514.50 |
| EWP Premier TAC OS 17203 | 98000-17203 | \$ 3,457.00 | 6% | \$3,273.95 |
| EWP Premier TAC OS 17203T | 98000-17203T | \$ 3,758.00 | 6% | \$3,559.01 |
| EWP Premier TAC OS 17204 | 98000-17204 | \$ 3,457.00 | 6% | \$3,273.95 |
| EWP Premier TAC OS 17204T | 98000-17204T | \$ 3,758.00 | 6% | \$3,559.01 |
| EWP Premier TAC OS 17205 | 98000-17205 | \$ 3,422.00 | 6% | \$3,240.81 |
| EWP Premier TAC OS 17205T | 98000-17205T | \$ 3,731.00 | 6% | \$3,533.44 |
| EWP Premier TAC OS 17206 | 98000-17206 | \$ 3,422.00 | 6% | \$3,240.81 |
| EWP Premier TAC OS 17206T | 98000-17206T | \$ 3,731.00 | 6% | \$3,533.44 |
| EWP Premier TAC OS 17300 | 98000-17300 | \$ 2,259.00 | 6% | \$2,139.39 |
| EWP Premier TAC OS 17310 | 98000-17310 | \$ 2,051.00 | 6% | \$1,942.40 |
| EWP Premier TAC OS 17310T | 98000-17310T | \$ 2,461.00 | 6% | \$2,330.69 |
| EWP Premier TAC OS 17350 | 98000-17350 | \$ 2,101.00 | 6% | \$1,989.75 |
| EWP Premier TAC OS 17360 | 98000-17360 | \$ 2,585.00 | 6% | \$2,448.12 |
| EWP Premier TAC OS 17401 | 98000-17401 | \$ 318.00 | 6% | \$301.16 |
| EWP Premier TAC OS 17401G | 98000-17401G | \$ 391.00 | 6% | \$370.30 |
| EWP Premier TAC OS 17401T | 98000-17401T | \$ 370.00 | 6% | \$350.41 |
| EWP Premier TAC OS 17402 | 98000-17402 | \$ 448.00 | 6% | \$424.28 |
| EWP Premier TAC OS 17402G | 98000-17402G | \$ 519.00 | 6% | \$491.52 |
| EWP Premier TAC OS 17402T | 98000-17402T | \$ 487.00 | 6% | \$461.21 |
| EWP Premier TAC OS 17403 | 98000-17403 | \$ 495.00 | 6% | \$468.79 |
| EWP Premier TAC OS 17404 | 98000-17404 | \$ 238.00 | 6% | \$225.40 |
| EWP Premier TAC OS 17405 | 98000-17405 | \$ 294.00 | 6% | \$278.43 |
| EWP Premier TAC OS 17431 | 98000-17431 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier TAC OS 17433 | 98000-17433 | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS 17434 | 98000-17434 | \$ 75.00 | 6% | \$71.03 |
| EWP Premier TAC OS 17435 | 98000-17435 | \$ 102.00 | 6% | \$96.60 |
| EWP Premier TAC OS 17700 | 98000-17700 | \$ 3,976.00 | 6% | \$3,765.47 |
| EWP Premier TAC OS 17701 | 98000-17701 | \$ 3,527.00 | 6% | \$3,340.25 |
| EWP Premier TAC OS 17702 | 98000-17702 | \$ 3,527.00 | 6% | \$3,340.25 |
| EWP Premier TAC OS 17703 | 98000-17703 | \$ 3,784.00 | 6% | \$3,583.64 |
| EWP Premier TAC OS 17704 | 98000-17704 | \$ 3,784.00 | 6% | \$3,583.64 |
| EWP Premier TAC OS 17705 | 98000-17705 | \$ 3,546.00 | 6% | \$3,358.24 |
| EWP Premier TAC OS 17706 | 98000-17706 | \$ 3,546.00 | 6% | \$3,358.24 |
| EWP Premier TAC OS 17725 | 98000-17725 | \$ 663.00 | 6% | \$627.89 |
| EWP Premier TAC OS 17726 | 98000-17726 | \$ 293.00 | 6% | \$277.49 |
| EWP Premier TAC OS 17727 | 98000-17727 | \$ 585.00 | 6% | \$554.02 |
| EWP Premier TAC OS 17728 | 98000-17728 | \$ 273.00 | 6% | \$258.54 |
| EWP Premier TAC OS 17729 | 98000-17729 | \$ 183.00 | 6% | \$173.31 |
| EWP Premier TAC OS 17800 | 98000-17800 | \$ 4,053.00 | 6% | \$3,838.39 |
| EWP Premier TAC OS 17810 | 98000-17810 | \$ 3,233.00 | 6% | \$3,061.81 |

| | | | | |
|------------------------------|-----------------|-------------|----|-------------------|
| EWP Premier TAC OS 17825 | 98000-17825 | \$ 508.00 | 6% | <i>\$481.10</i> |
| EWP Premier TAC OS 17826 | 98000-17826 | \$ 585.00 | 6% | <i>\$554.02</i> |
| EWP Premier TAC OS 17828 | 98000-17828 | \$ 359.00 | 6% | <i>\$339.99</i> |
| EWP Premier TAC OS 18101 | 98000-18101 | \$ 211.00 | 6% | <i>\$199.83</i> |
| EWP Premier TAC OS 18102 | 98000-18102 | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier TAC OS 18103 | 98000-18103 | \$ 295.00 | 6% | <i>\$279.38</i> |
| EWP Premier TAC OS 18104 | 98000-18104 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWP Premier TAC OS 18104-6PK | 98000-18104-6PK | \$ 2,357.00 | 6% | <i>\$2,232.20</i> |
| EWP Premier TAC OS 18202 | 98000-18202 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier TAC OS 30135 | 98000-30135 | \$ 423.00 | 6% | <i>\$400.60</i> |
| EWP Premier TAC OS 30136 | 98000-30136 | \$ 3,303.00 | 6% | <i>\$3,128.11</i> |
| EWP Premier TAC OS 30137 | 98000-30137 | \$ 604.00 | 6% | <i>\$572.02</i> |
| EWP Premier TAC OS 30138 | 98000-30138 | \$ 2,988.00 | 6% | <i>\$2,829.79</i> |
| EWP Premier TAC OS 30139 | 98000-30139 | \$ 5,843.00 | 6% | <i>\$5,533.61</i> |
| EWP Premier TAC OS 30912 | 98000-30912 | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS 30913 | 98000-30913 | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS 31012 | 98000-31012 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS 31013 | 98000-31013 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS 31014 | 98000-31014 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS 31015 | 98000-31015 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS 31016 | 98000-31016 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier TAC OS 31017 | 98000-31017 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier TAC OS 31018 | 98000-31018 | \$ 103.00 | 6% | <i>\$97.55</i> |
| EWP Premier TAC OS 31019 | 98000-31019 | \$ 103.00 | 6% | <i>\$97.55</i> |
| EWP Premier TAC OS 31025 | 98000-31025 | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS 31026 | 98000-31026 | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS 31028 | 98000-31028 | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS 31029 | 98000-31029 | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS 31031 | 98000-31031 | \$ 48.00 | 6% | <i>\$45.46</i> |
| EWP Premier TAC OS 31032 | 98000-31032 | \$ 48.00 | 6% | <i>\$45.46</i> |
| EWP Premier TAC OS 31034 | 98000-31034 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS 31035 | 98000-31035 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS 31050 | 98000-31050 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 31051 | 98000-31051 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 31055 | 98000-31055 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 31056 | 98000-31056 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37101 | 98000-37101 | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS 37102 | 98000-37102 | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS 37103 | 98000-37103 | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS 37111 | 98000-37111 | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS 37112 | 98000-37112 | \$ 45.00 | 6% | <i>\$42.62</i> |

| | | | | |
|---------------------------------|--------------------|-------------|-----|-------------------|
| EWP Premier TAC OS 37113 | 98000-37113 | \$ 48.00 | 6% | <i>\$45.46</i> |
| EWP Premier TAC OS 37114 | 98000-37114 | \$ 48.00 | 6% | <i>\$45.46</i> |
| EWP Premier TAC OS 37115 | 98000-37115 | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS 37116 | 98000-37116 | \$ 48.00 | 6% | <i>\$45.46</i> |
| EWP Premier TAC OS 37117 | 98000-37117 | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS 37121 | 98000-37121 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37122 | 98000-37122 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37123 | 98000-37123 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37124 | 98000-37124 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37125 | 98000-37125 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37126 | 98000-37126 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37129 | 98000-37129 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 37130 | 98000-37130 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS 39031 | 98000-39031 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier TAC OS 39032 | 98000-39032 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier TAC OS 39033 | 98000-39033 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier TAC OS 39034 | 98000-39034 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier TAC OS 39035 | 98000-39035 | \$ 155.00 | 6% | <i>\$146.79</i> |
| EWP Premier TAC OS 39036 | 98000-39036 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier TAC OS 39037 | 98000-39037 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier TAC OS 39038 | 98000-39038 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier TAC OS 39039 | 98000-39039 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier TAC OS 39505 | 98000-39505 | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS 4120-24MW-4Y | 98000-4120-24MW-4Y | \$ 555.00 | 6% | <i>\$525.61</i> |
| EWP Premier TAC OS 4120-48MW-4Y | 98000-4120-48MW-4Y | \$ 740.00 | 6% | <i>\$700.82</i> |
| EWP Premier TAC OS 4120C | 98000-4120C | \$ 4,075.00 | 10% | <i>\$3,695.01</i> |
| EWP Premier TAC OS 4120C-1 | 98000-4120C-1 | \$ 4,491.00 | 6% | <i>\$4,253.20</i> |
| EWP Premier TAC OS 41216 | 98000-41216 | \$ 1,307.00 | 6% | <i>\$1,237.79</i> |
| EWP Premier TAC OS 41312 | 98000-41312 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWP Premier TAC OS 41314 | 98000-41314 | \$ 2,847.00 | 6% | <i>\$2,696.25</i> |
| EWP Premier TAC OS 4220-12P-4X | 98000-4220-12P-4X | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier TAC OS 4220-12T-4X | 98000-4220-12T-4X | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier TAC OS 4220-24P-4X | 98000-4220-24P-4X | \$ 221.00 | 6% | <i>\$209.30</i> |
| EWP Premier TAC OS 4220-24T-4X | 98000-4220-24T-4X | \$ 171.00 | 6% | <i>\$161.95</i> |

| | | | | |
|--|---------------------------|-------------|----|-------------------|
| EWP Premier TAC OS 4220-48P-4X | 98000-4220-48P-4X | \$ 331.00 | 6% | <i>\$313.47</i> |
| EWP Premier TAC OS 4220-48T-4X | 98000-4220-48T-4X | \$ 248.00 | 6% | <i>\$234.87</i> |
| EWP Premier TAC OS 4220-4MW-20P-4X | 98000-4220-4MW-20P-4X | \$ 303.00 | 6% | <i>\$286.96</i> |
| EWP Premier TAC OS 4220-4MW-8P-4X | 98000-4220-4MW-8P-4X | \$ 215.00 | 6% | <i>\$203.62</i> |
| EWP Premier TAC OS 4220-8MW-40P-4X | 98000-4220-8MW-40P-4X | \$ 441.00 | 6% | <i>\$417.65</i> |
| EWP Premier TAC OS 4220-8X | 98000-4220-8X | \$ 232.00 | 6% | <i>\$219.72</i> |
| EWP Premier TAC OS 48001 | 98000-48001 | \$ 5,415.00 | 6% | <i>\$5,128.28</i> |
| EWP Premier TAC OS 48038 | 98000-48038 | \$ 2,174.00 | 6% | <i>\$2,058.89</i> |
| EWP Premier TAC OS 48039 | 98000-48039 | \$ 2,174.00 | 6% | <i>\$2,058.89</i> |
| EWP Premier TAC OS 48040 | 98000-48040 | \$ 2,028.00 | 6% | <i>\$1,920.62</i> |
| EWP Premier TAC OS 48041 | 98000-48041 | \$ 2,174.00 | 6% | <i>\$2,058.89</i> |
| EWP Premier TAC OS 48046 | 98000-48046 | \$ 2,856.00 | 6% | <i>\$2,704.77</i> |
| EWP Premier TAC OS 48047 | 98000-48047 | \$ 7,597.00 | 6% | <i>\$7,194.74</i> |
| EWP Premier TAC OS 48051 | 98000-48051 | \$ 5,222.00 | 6% | <i>\$4,945.50</i> |
| EWP Premier TAC OS 48061 | 98000-48061 | \$ 6,104.00 | 6% | <i>\$5,780.79</i> |
| EWP Premier TAC OS 48062 | 98000-48062 | \$ 9,763.00 | 6% | <i>\$9,246.05</i> |
| EWP Premier TAC OS 48091 | 98000-48091 | \$ 1,793.00 | 6% | <i>\$1,698.06</i> |
| EWP Premier TAC OS 48093 | 98000-48093 | \$ 1,196.00 | 6% | <i>\$1,132.67</i> |
| EWP Premier TAC OS 48094 | 98000-48094 | \$ 1,793.00 | 6% | <i>\$1,698.06</i> |
| EWP PREMIER TAC OS 5000-MACSEC-LIC | 98000-5000-MACSEC-LIC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP PREMIER TAC OS 5000-PRMR-LIC | 98000-5000-PRMR-LIC | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier TAC OS 5320-16P-4XE | 98000-5320-16P-4XE | \$ 228.00 | 6% | <i>\$215.93</i> |
| EWP Premier TAC OS 5320-16P-4XE-DC | 98000-5320-16P-4XE-DC | \$ 277.00 | 6% | <i>\$262.33</i> |
| EWP Premier TAC OS 5320-24P-8XE | 98000-5320-24P-8XE | \$ 242.00 | 6% | <i>\$229.19</i> |
| EWP Premier TAC OS 5320-24T-24S-4XE-XT | 98000-5320-24T-24S-4XE-XT | \$ 357.00 | 6% | <i>\$338.10</i> |
| EWP Premier TAC OS 5320-24T-4X-XT | 98000-5320-24T-4X-XT | \$ 192.00 | 6% | <i>\$181.83</i> |
| EWP Premier TAC OS 5320-24T-8XE | 98000-5320-24T-8XE | \$ 177.00 | 6% | <i>\$167.63</i> |

| | | | | |
|---------------------------------------|--------------------------|-----------|----|-----------------|
| EWP Premier TAC OS 5320-48P-8XE | 98000-5320-48P-8XE | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWP Premier TAC OS 5320-48T-8XE | 98000-5320-48T-8XE | \$ 292.00 | 6% | <i>\$276.54</i> |
| EWP Premier TAC OS 5420F-16MW-32P-4XE | 98000-5420F-16MW-32P-4XE | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWP Premier TAC OS 5420F-16W-32P-4XE | 98000-5420F-16W-32P-4XE | \$ 688.00 | 6% | <i>\$651.57</i> |
| EWP Premier TAC OS 5420F-24P-4XE | 98000-5420F-24P-4XE | \$ 396.00 | 6% | <i>\$375.03</i> |
| EWP Premier TAC OS 5420F-24S-4XE | 98000-5420F-24S-4XE | \$ 387.00 | 6% | <i>\$366.51</i> |
| EWP Premier TAC OS 5420F-24T-4XE | 98000-5420F-24T-4XE | \$ 336.00 | 6% | <i>\$318.21</i> |
| EWP Premier TAC OS 5420F-48P-4XE | 98000-5420F-48P-4XE | \$ 609.00 | 6% | <i>\$576.75</i> |
| EWP Premier TAC OS 5420F-48P-4XL | 98000-5420F-48P-4XL | \$ 624.00 | 6% | <i>\$590.96</i> |
| EWP Premier TAC OS 5420F-48T-4XE | 98000-5420F-48T-4XE | \$ 451.00 | 6% | <i>\$427.12</i> |
| EWP Premier TAC OS 5420F-8W-16P-4XE | 98000-5420F-8W-16P-4XE | \$ 413.00 | 6% | <i>\$391.13</i> |
| EWP Premier TAC OS 5420M-16MW-32P-4YE | 98000-5420M-16MW-32P-4YE | \$ 955.00 | 6% | <i>\$904.43</i> |
| EWP Premier TAC OS 5420M-24T-4YE | 98000-5420M-24T-4YE | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWP Premier TAC OS 5420M-24W-4YE | 98000-5420M-24W-4YE | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWP Premier TAC OS 5420M-48T-4YE | 98000-5420M-48T-4YE | \$ 553.00 | 6% | <i>\$523.72</i> |
| EWP Premier TAC OS 5420M-48W-4YE | 98000-5420M-48W-4YE | \$ 608.00 | 6% | <i>\$575.81</i> |
| EWP PREMIER TAC OS 5520-12MW-36W | 98000-5520-12MW-36W | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWP PREMIER TAC OS 5520-24T | 98000-5520-24T | \$ 342.00 | 6% | <i>\$323.89</i> |
| EWP PREMIER TAC OS 5520-24T-ACDC-BASE | 98000-5520-24T-ACDC-BASE | \$ 342.00 | 6% | <i>\$323.89</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EWP PREMIER TAC OS 5520-24T-BASE | 98000-5520-24T-BASE | \$ 342.00 | 10% | <i>\$310.11</i> |
| EWP PREMIER TAC OS 5520-24W | 98000-5520-24W | \$ 439.00 | 6% | <i>\$415.75</i> |
| EWP PREMIER TAC OS 5520-24X | 98000-5520-24X | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP PREMIER TAC OS 5520-24X-ACDC-BASE | 98000-5520-24X-ACDC-BASE | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP PREMIER TAC OS 5520-24X-BASE | 98000-5520-24X-BASE | \$ 927.00 | 10% | <i>\$840.56</i> |
| EWP PREMIER TAC OS 5520-48SE | 98000-5520-48SE | \$ 783.00 | 6% | <i>\$741.54</i> |
| EWP PREMIER TAC OS 5520-48SE-ACDC-BASE | 98000-5520-48SE-ACDC-BASE | \$ 783.00 | 6% | <i>\$741.54</i> |
| EWP PREMIER TAC OS 5520-48SE-BASE | 98000-5520-48SE-BASE | \$ 783.00 | 10% | <i>\$709.99</i> |
| EWP PREMIER TAC OS 5520-48T | 98000-5520-48T | \$ 531.00 | 6% | <i>\$502.88</i> |
| EWP PREMIER TAC OS 5520-48T-ACDC-BASE | 98000-5520-48T-ACDC-BASE | \$ 531.00 | 6% | <i>\$502.88</i> |
| EWP PREMIER TAC OS 5520-48T-BASE | 98000-5520-48T-BASE | \$ 531.00 | 10% | <i>\$481.48</i> |
| EWP PREMIER TAC OS 5520-48W | 98000-5520-48W | \$ 620.00 | 6% | <i>\$587.17</i> |
| EWP Premier TAC OS 5720-24MW | 98000-5720-24MW | \$ 1,041.00 | 6% | <i>\$985.88</i> |
| EWP Premier TAC OS 5720-24MXW | 98000-5720-24MXW | \$ 1,379.00 | 6% | <i>\$1,305.98</i> |
| EWP Premier TAC OS 5720-48MW | 98000-5720-48MW | \$ 1,279.00 | 6% | <i>\$1,211.28</i> |
| EWP Premier TAC OS 5720-48MXW | 98000-5720-48MXW | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWP Premier TAC OS 7000-MACSEC-LIC-P | 98000-7000-MACSEC-LIC-P | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier TAC OS 7000-PRMR-LIC-P | 98000-7000-PRMR-LIC-P | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier TAC OS 7520-48XT-6C | 98000-7520-48XT-6C | \$ 1,962.00 | 6% | <i>\$1,858.11</i> |

| | | | | |
|---------------------------------------|--------------------------|-------------|----|-------------------|
| EWP Premier TAC OS 7520-48XT-6C-AC-F | 98000-7520-48XT-6C-AC-F | \$ 1,962.00 | 6% | <i>\$1,858.11</i> |
| EWP Premier TAC OS 7520-48XT-6C-AC-R | 98000-7520-48XT-6C-AC-R | \$ 1,962.00 | 6% | <i>\$1,858.11</i> |
| EWP Premier TAC OS 7520-48Y-8C | 98000-7520-48Y-8C | \$ 1,816.00 | 6% | <i>\$1,719.84</i> |
| EWP Premier TAC OS 7520-48Y-8C-AC-F | 98000-7520-48Y-8C-AC-F | \$ 1,816.00 | 6% | <i>\$1,719.84</i> |
| EWP Premier TAC OS 7520-48Y-8C-AC-R | 98000-7520-48Y-8C-AC-R | \$ 1,816.00 | 6% | <i>\$1,719.84</i> |
| EWP PREMIER TAC OS 7520-48YE-8CE | 98000-7520-48YE-8CE | \$ 2,102.00 | 6% | <i>\$1,990.70</i> |
| EWP PREMIER TAC OS 7520-48YE-8CE-AC-F | 98000-7520-48YE-8CE-AC-F | \$ 2,102.00 | 6% | <i>\$1,990.70</i> |
| EWP PREMIER TAC OS 7520-48YE-8CE-AC-R | 98000-7520-48YE-8CE-AC-R | \$ 2,102.00 | 6% | <i>\$1,990.70</i> |
| EWP Premier TAC OS 7720-32C | 98000-7720-32C | \$ 2,303.00 | 6% | <i>\$2,181.06</i> |
| EWP Premier TAC OS 7720-32C-AC-F | 98000-7720-32C-AC-F | \$ 2,303.00 | 6% | <i>\$2,181.06</i> |
| EWP Premier TAC OS 7720-32C-AC-R | 98000-7720-32C-AC-R | \$ 2,303.00 | 6% | <i>\$2,181.06</i> |
| EWP Premier TAC OS 8000-PRMR-LIC-P | 98000-8000-PRMR-LIC-P | \$ 524.00 | 6% | <i>\$496.25</i> |
| EWP Premier TAC OS 8520-48XT-6C | 98000-8520-48XT-6C | \$ 1,745.00 | 6% | <i>\$1,652.60</i> |
| EWP Premier TAC OS 8520-48XT-6C-AC-F | 98000-8520-48XT-6C-AC-F | \$ 1,745.00 | 6% | <i>\$1,652.60</i> |
| EWP Premier TAC OS 8520-48XT-6C-AC-R | 98000-8520-48XT-6C-AC-R | \$ 1,745.00 | 6% | <i>\$1,652.60</i> |
| EWP Premier TAC OS 8520-48XT-6C-DC-F | 98000-8520-48XT-6C-DC-F | \$ 1,745.00 | 6% | <i>\$1,652.60</i> |
| EWP Premier TAC OS 8520-48XT-6C-DC-R | 98000-8520-48XT-6C-DC-R | \$ 1,745.00 | 6% | <i>\$1,652.60</i> |

| | | | | |
|-------------------------------------|------------------------|--------------|-----|--------------------|
| EWP Premier TAC OS 8520-48Y-8C | 98000-8520-48Y-8C | \$ 1,768.00 | 6% | <i>\$1,674.38</i> |
| EWP Premier TAC OS 8520-48Y-8C-AC-F | 98000-8520-48Y-8C-AC-F | \$ 1,768.00 | 6% | <i>\$1,674.38</i> |
| EWP Premier TAC OS 8520-48Y-8C-AC-R | 98000-8520-48Y-8C-AC-R | \$ 1,768.00 | 6% | <i>\$1,674.38</i> |
| EWP Premier TAC OS 8520-48Y-8C-DC-F | 98000-8520-48Y-8C-DC-F | \$ 1,768.00 | 6% | <i>\$1,674.38</i> |
| EWP Premier TAC OS 8520-48Y-8C-DC-R | 98000-8520-48Y-8C-DC-R | \$ 1,768.00 | 6% | <i>\$1,674.38</i> |
| EWP Premier TAC OS 86100 | 98000-86100 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWP Premier TAC OS 86101 | 98000-86101 | \$ 6,377.00 | 6% | <i>\$6,039.34</i> |
| EWP Premier TAC OS 87100 | 98000-87100 | \$ 2,938.00 | 6% | <i>\$2,782.43</i> |
| EWP Premier TAC OS 87101 | 98000-87101 | \$ 4,668.00 | 6% | <i>\$4,420.83</i> |
| EWP Premier TAC OS 8720-32C | 98000-8720-32C | \$ 2,037.00 | 6% | <i>\$1,929.14</i> |
| EWP Premier TAC OS 8720-32C-AC-F | 98000-8720-32C-AC-F | \$ 2,037.00 | 6% | <i>\$1,929.14</i> |
| EWP Premier TAC OS 8720-32C-AC-R | 98000-8720-32C-AC-R | \$ 2,037.00 | 6% | <i>\$1,929.14</i> |
| EWP Premier TAC OS 8720-32C-DC-F | 98000-8720-32C-DC-F | \$ 2,037.00 | 6% | <i>\$1,929.14</i> |
| EWP Premier TAC OS 8720-32C-DC-R | 98000-8720-32C-DC-R | \$ 2,037.00 | 6% | <i>\$1,929.14</i> |
| EWP Premier TAC OS 8806 | 98000-8806 | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| EWP Premier TAC OS 8810 | 98000-8810 | \$ 3,528.00 | 6% | <i>\$3,341.19</i> |
| EWP Premier TAC OS 88100 | 98000-88100 | \$ 5,246.00 | 6% | <i>\$4,968.22</i> |
| EWP Premier TAC OS 8820-40C | 98000-8820-40C | \$ 10,992.00 | 10% | <i>\$9,967.00</i> |
| EWP Premier TAC OS 8820-40C-AC-F | 98000-8820-40C-AC-F | \$ 10,992.00 | 10% | <i>\$9,967.00</i> |
| EWP Premier TAC OS 8820-40C-AC-R | 98000-8820-40C-AC-R | \$ 10,992.00 | 10% | <i>\$9,967.00</i> |
| EWP Premier TAC OS 8820-40C-DC-F | 98000-8820-40C-DC-F | \$ 10,992.00 | 10% | <i>\$9,967.00</i> |
| EWP Premier TAC OS 8820-40C-DC-R | 98000-8820-40C-DC-R | \$ 10,992.00 | 10% | <i>\$9,967.00</i> |
| EWP Premier TAC OS 8820-80C | 98000-8820-80C | \$ 15,824.00 | 10% | <i>\$14,348.41</i> |
| EWP Premier TAC OS 8820-80C-AC-F | 98000-8820-80C-AC-F | \$ 15,824.00 | 10% | <i>\$14,348.41</i> |

| | | | | |
|--------------------------------------|-------------------------|--------------|-----|--------------------|
| EWP Premier TAC OS 8820-80C-AC-R | 98000-8820-80C-AC-R | \$ 15,824.00 | 10% | <i>\$14,348.41</i> |
| EWP Premier TAC OS 8820-80C-DC-F | 98000-8820-80C-DC-F | \$ 15,824.00 | 10% | <i>\$14,348.41</i> |
| EWP Premier TAC OS 8820-80C-DC-R | 98000-8820-80C-DC-R | \$ 15,824.00 | 10% | <i>\$14,348.41</i> |
| EWP Premier TAC OS 88XOS | 98000-88XOS | \$ 2,847.00 | 6% | <i>\$2,696.25</i> |
| EWP Premier TAC OS 9920-16C | 98000-9920-16C | \$ 8,295.00 | 6% | <i>\$7,855.78</i> |
| EWP Premier TAC OS 9920-4D | 98000-9920-4D | \$ 8,295.00 | 6% | <i>\$7,855.78</i> |
| EWP Premier TAC OS 9920-NPB-8 | 98000-9920-NPB-8 | \$ 15,090.00 | 6% | <i>\$14,290.98</i> |
| EWP Premier TAC OS A10148 | 98000-A10148 | \$ 2,536.00 | 6% | <i>\$2,401.72</i> |
| EWP Premier TAC OS A10149 | 98000-A10149 | \$ 4,985.00 | 6% | <i>\$4,721.04</i> |
| EWP Premier TAC OS AH-AP-1130-AC-CE | 98000-AH-AP-1130-AC-CE | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-1130-AC-FCC | 98000-AH-AP-1130-AC-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-1130-AC-W | 98000-AH-AP-1130-AC-W | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-121-N-CE | 98000-AH-AP-121-N-CE | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-121-N-FCC | 98000-AH-AP-121-N-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-121-N-W | 98000-AH-AP-121-N-W | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-121-N-W-NEC | 98000-AH-AP-121-N-W-NEC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-122-AC-CAN | 98000-AH-AP-122-AC-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-122-AC-CE | 98000-AH-AP-122-AC-CE | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-122-AC-FCC | 98000-AH-AP-122-AC-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-122-AC-W | 98000-AH-AP-122-AC-W | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-122X-AC-CAN | 98000-AH-AP-122X-AC-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AH-AP-122X-AC-CE | 98000-AH-AP-122X-AC-CE | \$ 45.00 | 6% | <i>\$42.62</i> |

| | | | | |
|--------------------------------------|-------------------------|----------|----|---------|
| EWP Premier TAC OS AH-AP-122X-AC-FCC | 98000-AH-AP-122X-AC-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-122X-AC-W | 98000-AH-AP-122X-AC-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-130-AC-CE | 98000-AH-AP-130-AC-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-130-AC-FCC | 98000-AH-AP-130-AC-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-130-AC-W | 98000-AH-AP-130-AC-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-141-N-CE | 98000-AH-AP-141-N-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-141-N-FCC | 98000-AH-AP-141-N-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-141-N-W | 98000-AH-AP-141-N-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-141-N-W-NEC | 98000-AH-AP-141-N-W-NEC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-150W-AC-CAN | 98000-AH-AP-150W-AC-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-150W-AC-CE | 98000-AH-AP-150W-AC-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-150W-AC-FCC | 98000-AH-AP-150W-AC-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-150W-AC-W | 98000-AH-AP-150W-AC-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-230-AC-CE | 98000-AH-AP-230-AC-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-230-AC-FCC | 98000-AH-AP-230-AC-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-230-AC-W | 98000-AH-AP-230-AC-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-245X-AC-CAN | 98000-AH-AP-245X-AC-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-245X-AC-CE | 98000-AH-AP-245X-AC-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-245X-AC-FCC | 98000-AH-AP-245X-AC-FCC | \$ 45.00 | 6% | \$42.62 |

| | | | | |
|-------------------------------------|------------------------|----------|----|---------|
| EWP Premier TAC OS AH-AP-245X-AC-W | 98000-AH-AP-245X-AC-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-250-AC-CAN | 98000-AH-AP-250-AC-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-250-AC-CE | 98000-AH-AP-250-AC-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-250-AC-FCC | 98000-AH-AP-250-AC-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-250-AC-W | 98000-AH-AP-250-AC-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-330-N-FCC | 98000-AH-AP-330-N-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-330-N-W | 98000-AH-AP-330-N-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-350-N-FCC | 98000-AH-AP-350-N-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-350-N-W | 98000-AH-AP-350-N-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-550-AC-CAN | 98000-AH-AP-550-AC-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-550-AC-CE | 98000-AH-AP-550-AC-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-550-AC-FCC | 98000-AH-AP-550-AC-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-550-AC-W | 98000-AH-AP-550-AC-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-630-AX-CAN | 98000-AH-AP-630-AX-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-630-AX-CE | 98000-AH-AP-630-AX-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-630-AX-FCC | 98000-AH-AP-630-AX-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-630-AX-W | 98000-AH-AP-630-AX-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AH-AP-650-AX-CAN | 98000-AH-AP-650-AX-CAN | \$ 40.00 | 6% | \$37.88 |
| EWP Premier TAC OS AH-AP-650-AX-CE | 98000-AH-AP-650-AX-CE | \$ 40.00 | 6% | \$37.88 |
| EWP Premier TAC OS AH-AP-650-AX-FCC | 98000-AH-AP-650-AX-FCC | \$ 40.00 | 6% | \$37.88 |
| EWP Premier TAC OS AH-AP-650-AX-W | 98000-AH-AP-650-AX-W | \$ 40.00 | 6% | \$37.88 |

| | | | | |
|--------------------------------------|-------------------------|----------|-----|---------|
| EWP Premier TAC OS AH-AP-650X-AX-CAN | 98000-AH-AP-650X-AX-CAN | \$ 40.00 | 6% | \$37.88 |
| EWP Premier TAC OS AH-AP-650X-AX-CE | 98000-AH-AP-650X-AX-CE | \$ 40.00 | 6% | \$37.88 |
| EWP Premier TAC OS AH-AP-650X-AX-FCC | 98000-AH-AP-650X-AX-FCC | \$ 40.00 | 6% | \$37.88 |
| EWP Premier TAC OS AH-AP-650X-AX-W | 98000-AH-AP-650X-AX-W | \$ 40.00 | 6% | \$37.88 |
| EWP Premier TAC OS AH-ATOM-CAN | 98000-AH-ATOM-CAN | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AH-ATOM-CE-EU | 98000-AH-ATOM-CE-EU | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AH-ATOM-CE-UK | 98000-AH-ATOM-CE-UK | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AH-ATOM-FCC | 98000-AH-ATOM-FCC | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AH-ATOM-W | 98000-AH-ATOM-W | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AH-ATOM-W-EU | 98000-AH-ATOM-W-EU | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AH-ATOM-W-UK | 98000-AH-ATOM-W-UK | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AH-BR-200WP-N-CE | 98000-AH-BR-200WP-N-CE | \$ 44.00 | 10% | \$39.90 |
| EWP Premier TAC OS AH-BR-200WP-N-FCC | 98000-AH-BR-200WP-N-FCC | \$ 44.00 | 10% | \$39.90 |
| EWP Premier TAC OS AH-BR-200WP-N-W | 98000-AH-BR-200WP-N-W | \$ 44.00 | 10% | \$39.90 |
| EWP Premier TAC OS AH-SR-2024P | 98000-AH-SR-2024P | \$ 42.00 | 10% | \$38.08 |
| EWP Premier TAC OS AH-SR-2124P | 98000-AH-SR-2124P | \$ 42.00 | 10% | \$38.08 |
| EWP Premier TAC OS AH-SR-2208P-AU | 98000-AH-SR-2208P-AU | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS AH-SR-2208P-EU | 98000-AH-SR-2208P-EU | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS AH-SR-2208P-NA | 98000-AH-SR-2208P-NA | \$ 44.00 | 6% | \$41.67 |

| | | | | |
|-----------------------------------|----------------------|----------|----|----------------|
| EWP Premier TAC OS AH-SR-2208P-UK | 98000-AH-SR-2208P-UK | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2224P-AU | 98000-AH-SR-2224P-AU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2224P-EU | 98000-AH-SR-2224P-EU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2224P-NA | 98000-AH-SR-2224P-NA | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2224P-UK | 98000-AH-SR-2224P-UK | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2324P-AU | 98000-AH-SR-2324P-AU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2324P-EU | 98000-AH-SR-2324P-EU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2324P-NA | 98000-AH-SR-2324P-NA | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2324P-UK | 98000-AH-SR-2324P-UK | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2348P-AU | 98000-AH-SR-2348P-AU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2348P-EU | 98000-AH-SR-2348P-EU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2348P-NA | 98000-AH-SR-2348P-NA | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-SR-2348P-UK | 98000-AH-SR-2348P-UK | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR200P-AU | 98000-AH-XR200P-AU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR200P-EU | 98000-AH-XR200P-EU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR200P-UK | 98000-AH-XR200P-UK | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR200P-US | 98000-AH-XR200P-US | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR600P | 98000-AH-XR600P | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR600P-AU | 98000-AH-XR600P-AU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR600P-EU | 98000-AH-XR600P-EU | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR600P-KR | 98000-AH-XR600P-KR | \$ 44.00 | 6% | <i>\$41.67</i> |

| | | | | |
|--------------------------------------|-------------------------|----------|-----|----------------|
| EWP Premier TAC OS AH-XR600P-UK | 98000-AH-XR600P-UK | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AH-XR600P-US | 98000-AH-XR600P-US | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AP-8533-68SB30-IL | 98000-AP-8533-68SB30-IL | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier TAC OS AP3000-IL | 98000-AP3000-IL | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS AP3000-TN | 98000-AP3000-TN | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS AP3000-WW | 98000-AP3000-WW | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS AP3000X-WW | 98000-AP3000X-WW | \$ 45.53 | 6% | <i>\$43.12</i> |
| EWP Premier TAC OS AP302W-CAN | 98000-AP302W-CAN | \$ 41.00 | 6% | <i>\$38.83</i> |
| EWP Premier TAC OS AP302W-EG | 98000-AP302W-EG | \$ 45.00 | 10% | <i>\$40.80</i> |
| EWP Premier TAC OS AP302W-FCC | 98000-AP302W-FCC | \$ 41.00 | 6% | <i>\$38.83</i> |
| EWP Premier TAC OS AP302W-WR | 98000-AP302W-WR | \$ 41.00 | 6% | <i>\$38.83</i> |
| EWP Premier TAC OS AP305C-1-CAN | 98000-AP305C-1-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP305C-1-EG | 98000-AP305C-1-EG | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP305C-1-FCC | 98000-AP305C-1-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP305C-1-IL | 98000-AP305C-1-IL | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP305C-1-WR | 98000-AP305C-1-WR | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP305C-CAN | 98000-AP305C-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP305C-EG | 98000-AP305C-EG | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP305C-FCC | 98000-AP305C-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |

| | | | | |
|--------------------------------|-------------------|----------|-----|---------|
| EWP Premier TAC OS AP305C-IL | 98000-AP305C-IL | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP305C-WR | 98000-AP305C-WR | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP305CX-CAN | 98000-AP305CX-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP305CX-FCC | 98000-AP305CX-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP305CX-IL | 98000-AP305CX-IL | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP305CX-WR | 98000-AP305CX-WR | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP310e-1-WR | 98000-AP310e-1-WR | \$ 39.00 | 10% | \$35.36 |
| EWP Premier TAC OS AP310e-CAN | 98000-AP310e-CAN | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS AP310e-FCC | 98000-AP310e-FCC | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS AP310e-IL | 98000-AP310e-IL | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS AP310e-WR | 98000-AP310e-WR | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS AP310i-1-WR | 98000-AP310i-1-WR | \$ 39.00 | 10% | \$35.36 |
| EWP Premier TAC OS AP310i-CAN | 98000-AP310i-CAN | \$ 34.00 | 6% | \$32.20 |
| EWP Premier TAC OS AP310i-FCC | 98000-AP310i-FCC | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS AP310i-IL | 98000-AP310i-IL | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS AP310i-WR | 98000-AP310i-WR | \$ 39.00 | 6% | \$36.93 |
| EWP Premier TAC OS AP360e-CAN | 98000-AP360e-CAN | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS AP360e-FCC | 98000-AP360e-FCC | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS AP360e-IL | 98000-AP360e-IL | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS AP360e-WR | 98000-AP360e-WR | \$ 43.00 | 6% | \$40.72 |

| | | | | |
|---------------------------------|--------------------|----------|-----|----------------|
| EWP Premier TAC OS AP360i-CAN | 98000-AP360i-CAN | \$ 43.00 | 6% | <i>\$40.72</i> |
| EWP Premier TAC OS AP360i-FCC | 98000-AP360i-FCC | \$ 43.00 | 6% | <i>\$40.72</i> |
| EWP Premier TAC OS AP360i-WR | 98000-AP360i-WR | \$ 43.00 | 6% | <i>\$40.72</i> |
| EWP Premier TAC OS AP4000-WW | 98000-AP4000-1-WW | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AP4000-IL | 98000-AP4000-IL | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AP4000-WW | 98000-AP4000-WW | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS AP410C-1-CAN | 98000-AP410C-1-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-1-EG | 98000-AP410C-1-EG | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-1-FCC | 98000-AP410C-1-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-1-IL | 98000-AP410C-1-IL | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-1-WR | 98000-AP410C-1-WR | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-CAN | 98000-AP410C-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-EG | 98000-AP410C-EG | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-FCC | 98000-AP410C-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-IL | 98000-AP410C-IL | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410C-WR | 98000-AP410C-WR | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP410e-CAN | 98000-AP410e-CAN | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS AP410e-FCC | 98000-AP410e-FCC | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS AP410e-WR | 98000-AP410e-WR | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS AP410i-1-FCC | 98000-AP410i-1-FCC | \$ 46.00 | 10% | <i>\$41.71</i> |

| | | | | |
|----------------------------------|---------------------|----------|-----|----------------|
| EWP Premier TAC OS AP410i-1-WR | 98000-AP410i-1-WR | \$ 46.00 | 10% | <i>\$41.71</i> |
| EWP Premier TAC OS AP410i-CAN | 98000-AP410i-CAN | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS AP410i-FCC | 98000-AP410i-FCC | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS AP410i-IL | 98000-AP410i-IL | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS AP410i-WR | 98000-AP410i-WR | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS AP460C-CAN | 98000-AP460C-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP460C-EG | 98000-AP460C-EG | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP460C-FCC | 98000-AP460C-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP460C-IL | 98000-AP460C-IL | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP460C-WR | 98000-AP460C-WR | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP460e-CAN | 98000-AP460e-CAN | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS AP460e-FCC | 98000-AP460e-FCC | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS AP460e-WR | 98000-AP460e-WR | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS AP460i-CAN | 98000-AP460i-CAN | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS AP460i-FCC | 98000-AP460i-FCC | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS AP460i-IL | 98000-AP460i-IL | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS AP460i-WR | 98000-AP460i-WR | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS AP460S12C-CAN | 98000-AP460S12C-CAN | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS AP460S12C-FCC | 98000-AP460S12C-FCC | \$ 45.00 | 6% | <i>\$42.62</i> |

| | | | | |
|-----------------------------------|----------------------|-----------|-----|---------|
| EWP Premier TAC OS AP460S12C-WR | 98000-AP460S12C-WR | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP460S6C-CAN | 98000-AP460S6C-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP460S6C-FCC | 98000-AP460S6C-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP460S6C-WR | 98000-AP460S6C-WR | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP5010-IL | 98000-AP5010-IL | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS AP5010-WW | 98000-AP5010-WW | \$ 56.00 | 10% | \$50.78 |
| EWP Premier TAC OS AP5020-WW | 98000-AP5020-WW | \$ 62.39 | 6% | \$59.09 |
| EWP Premier TAC OS AP5050D-WW | 98000-AP5050D-WW | \$ 103.00 | 6% | \$97.55 |
| EWP Premier TAC OS AP5050U-WW | 98000-AP5050U-WW | \$ 87.00 | 6% | \$82.39 |
| EWP Premier TAC OS AP505i-FCC | 98000-AP505i-FCC | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS AP505i-FCC-TAA | 98000-AP505i-FCC-TAA | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS AP505i-WR | 98000-AP505i-WR | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS AP510C-CAN | 98000-AP510C-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510C-CE | 98000-AP510C-CE | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510C-FCC | 98000-AP510C-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510C-W | 98000-AP510C-W | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510C-WW | 98000-AP510C-WW | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510CX-CAN | 98000-AP510CX-CAN | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510CX-CE | 98000-AP510CX-CE | \$ 45.00 | 6% | \$42.62 |

| | | | | |
|-----------------------------------|----------------------|-------------|-----|------------|
| EWP Premier TAC OS AP510CX-FCC | 98000-AP510CX-FCC | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510CX-W | 98000-AP510CX-W | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS AP510CX-WW | 98000-AP510CX-WW | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS AP510e-FCC | 98000-AP510e-FCC | \$ 57.00 | 6% | \$53.98 |
| EWP Premier TAC OS AP510e-FCC-TAA | 98000-AP510e-FCC-TAA | \$ 57.00 | 6% | \$53.98 |
| EWP Premier TAC OS AP510e-WR | 98000-AP510e-WR | \$ 57.00 | 6% | \$53.98 |
| EWP Premier TAC OS AP510i-1-FCC | 98000-AP510i-1-FCC | \$ 54.00 | 10% | \$48.96 |
| EWP Premier TAC OS AP510i-1-WR | 98000-AP510i-1-WR | \$ 54.00 | 10% | \$48.96 |
| EWP Premier TAC OS AP510i-FCC | 98000-AP510i-FCC | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS AP510i-FCC-TAA | 98000-AP510i-FCC-TAA | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS AP510i-WR | 98000-AP510i-WR | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS AP560h-FCC | 98000-AP560h-FCC | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS AP560h-WR | 98000-AP560h-WR | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS AP560i-FCC | 98000-AP560i-FCC | \$ 74.00 | 6% | \$70.08 |
| EWP Premier TAC OS AP560i-WR | 98000-AP560i-WR | \$ 74.00 | 6% | \$70.08 |
| EWP Premier TAC OS AP560m-FCC | 98000-AP560m-FCC | \$ 69.00 | 6% | \$65.35 |
| EWP Premier TAC OS AP560t-FCC | 98000-AP560t-FCC | \$ 85.00 | 6% | \$80.50 |
| EWP Premier TAC OS AP560u-FCC | 98000-AP560u-FCC | \$ 69.00 | 6% | \$65.35 |
| EWP Premier TAC OS E2122 | 98000-E2122 | \$ 3,572.00 | 6% | \$3,382.86 |
| EWP Premier TAC OS E2122-1 | 98000-E2122-1 | \$ 3,402.00 | 6% | \$3,221.86 |
| EWP Premier TAC OS E3120-1 | 98000-E3120-1 | \$ 5,565.00 | 6% | \$5,270.33 |
| EWP Premier TAC OS E3125 | 98000-E3125 | \$ 6,093.00 | 6% | \$5,770.38 |

| | | | | |
|--|---------------------------|-------------|----|-------------------|
| EWP Premier TAC OS EXOS-AVB-FP-X435 | 98000-EXOS-AVB-FP-X435 | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier TAC OS EXOS-AVB-FP-X465 | 98000-EXOS-AVB-FP-X465 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier TAC OS EXOS-CORE-FP-X695 | 98000-EXOS-CORE-FP-X695 | \$ 642.00 | 6% | <i>\$608.01</i> |
| EWP Premier TAC OS EXOS-MACSEC-FP-X695 | 98000-EXOS-MACSEC-FP-X695 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier TAC OS H30003 | 98000-H30003 | \$ 41.00 | 6% | <i>\$38.83</i> |
| EWP Premier TAC OS H30004 | 98000-H30004 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier TAC OS H30005 | 98000-H30005 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier TAC OS H30006 | 98000-H30006 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier TAC OS H30007 | 98000-H30007 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier TAC OS H30008 | 98000-H30008 | \$ 155.00 | 6% | <i>\$146.79</i> |
| EWP Premier TAC OS H30009 | 98000-H30009 | \$ 41.00 | 6% | <i>\$38.83</i> |
| EWP Premier TAC OS H30010 | 98000-H30010 | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier TAC OS H30011 | 98000-H30011 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier TAC OS H30012 | 98000-H30012 | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier TAC OS H30078 | 98000-H30078 | \$ 1,763.00 | 6% | <i>\$1,669.65</i> |
| EWP Premier TAC OS H30104 | 98000-H30104 | \$ 1,593.00 | 6% | <i>\$1,508.65</i> |
| EWP Premier TAC OS H30105 | 98000-H30105 | \$ 1,561.00 | 6% | <i>\$1,478.35</i> |
| EWP Premier TAC OS H30131 | 98000-H30131 | \$ 881.00 | 6% | <i>\$834.35</i> |
| EWP Premier TAC OS H30132 | 98000-H30132 | \$ 864.00 | 6% | <i>\$818.25</i> |
| EWP Premier TAC OS H30133 | 98000-H30133 | \$ 2,269.00 | 6% | <i>\$2,148.86</i> |
| EWP Premier TAC OS H30134 | 98000-H30134 | \$ 2,874.00 | 6% | <i>\$2,721.82</i> |
| EWP Premier TAC OS H30135 | 98000-H30135 | \$ 2,313.00 | 6% | <i>\$2,190.53</i> |
| EWP Premier TAC OS H30136 | 98000-H30136 | \$ 2,874.00 | 6% | <i>\$2,721.82</i> |
| EWP Premier TAC OS H30184 | 98000-H30184 | \$ 46.00 | 6% | <i>\$43.56</i> |
| EWP Premier TAC OS H30185 | 98000-H30185 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier TAC OS H30186 | 98000-H30186 | \$ 110.00 | 6% | <i>\$104.18</i> |
| EWP Premier TAC OS H30187 | 98000-H30187 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier TAC OS H30188 | 98000-H30188 | \$ 110.00 | 6% | <i>\$104.18</i> |
| EWP Premier TAC OS H30189 | 98000-H30189 | \$ 110.00 | 6% | <i>\$104.18</i> |
| EWP Premier TAC OS H30190 | 98000-H30190 | \$ 220.00 | 6% | <i>\$208.35</i> |
| EWP Premier TAC OS H30214 | 98000-H30214 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier TAC OS H30215 | 98000-H30215 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier TAC OS H30216 | 98000-H30216 | \$ 220.00 | 6% | <i>\$208.35</i> |
| EWP Premier TAC OS H30217 | 98000-H30217 | \$ 220.00 | 6% | <i>\$208.35</i> |
| EWP Premier TAC OS H30218 | 98000-H30218 | \$ 220.00 | 6% | <i>\$208.35</i> |
| EWP Premier TAC OS H30219 | 98000-H30219 | \$ 220.00 | 6% | <i>\$208.35</i> |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS H30220 | 98000-H30220 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30221 | 98000-H30221 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30222 | 98000-H30222 | \$ 220.00 | 6% | \$208.35 |
| EWP Premier TAC OS H30223 | 98000-H30223 | \$ 220.00 | 6% | \$208.35 |
| EWP Premier TAC OS H30224 | 98000-H30224 | \$ 220.00 | 6% | \$208.35 |
| EWP Premier TAC OS H30225 | 98000-H30225 | \$ 220.00 | 6% | \$208.35 |
| EWP Premier TAC OS H30226 | 98000-H30226 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30227 | 98000-H30227 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30228 | 98000-H30228 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30229 | 98000-H30229 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30267 | 98000-H30267 | \$ 220.00 | 6% | \$208.35 |
| EWP Premier TAC OS H30268 | 98000-H30268 | \$ 220.00 | 6% | \$208.35 |
| EWP Premier TAC OS H30269 | 98000-H30269 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30270 | 98000-H30270 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30271 | 98000-H30271 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30272 | 98000-H30272 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30273 | 98000-H30273 | \$ 473.00 | 6% | \$447.95 |
| EWP Premier TAC OS H30274 | 98000-H30274 | \$ 473.00 | 6% | \$447.95 |
| EWP Premier TAC OS H30275 | 98000-H30275 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30276 | 98000-H30276 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30277 | 98000-H30277 | \$ 473.00 | 6% | \$447.95 |
| EWP Premier TAC OS H30278 | 98000-H30278 | \$ 510.00 | 6% | \$483.00 |
| EWP Premier TAC OS H30279 | 98000-H30279 | \$ 473.00 | 6% | \$447.95 |
| EWP Premier TAC OS H30280 | 98000-H30280 | \$ 473.00 | 6% | \$447.95 |
| EWP Premier TAC OS H30281 | 98000-H30281 | \$ 473.00 | 6% | \$447.95 |
| EWP Premier TAC OS H30282 | 98000-H30282 | \$ 473.00 | 6% | \$447.95 |
| EWP Premier TAC OS H30283 | 98000-H30283 | \$ 318.00 | 6% | \$301.16 |
| EWP Premier TAC OS H30284 | 98000-H30284 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H30293 | 98000-H30293 | \$ 1,672.00 | 6% | \$1,583.47 |
| EWP Premier TAC OS H30296 | 98000-H30296 | \$ 116.00 | 6% | \$109.86 |
| EWP Premier TAC OS H30297 | 98000-H30297 | \$ 116.00 | 6% | \$109.86 |
| EWP Premier TAC OS H30298 | 98000-H30298 | \$ 116.00 | 6% | \$109.86 |
| EWP Premier TAC OS H30299 | 98000-H30299 | \$ 116.00 | 6% | \$109.86 |
| EWP Premier TAC OS H30380 | 98000-H30380 | \$ 3,082.00 | 6% | \$2,918.81 |
| EWP Premier TAC OS H30381 | 98000-H30381 | \$ 318.00 | 6% | \$301.16 |
| EWP Premier TAC OS H30383 | 98000-H30383 | \$ 2,307.00 | 6% | \$2,184.84 |
| EWP Premier TAC OS H30384 | 98000-H30384 | \$ 255.00 | 6% | \$241.50 |
| EWP Premier TAC OS H30391 | 98000-H30391 | \$ 597.00 | 6% | \$565.39 |
| EWP Premier TAC OS H30392 | 98000-H30392 | \$ 597.00 | 6% | \$565.39 |
| EWP Premier TAC OS H30393 | 98000-H30393 | \$ 273.00 | 6% | \$258.54 |
| EWP Premier TAC OS H30394 | 98000-H30394 | \$ 1,145.00 | 6% | \$1,084.37 |
| EWP Premier TAC OS H30395 | 98000-H30395 | \$ 1,366.00 | 6% | \$1,293.67 |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| EWP Premier TAC OS H30396 | 98000-H30396 | \$ 1,250.00 | 6% | <i>\$1,183.81</i> |
| EWP Premier TAC OS H30397 | 98000-H30397 | \$ 1,478.00 | 6% | <i>\$1,399.74</i> |
| EWP Premier TAC OS H30398 | 98000-H30398 | \$ 280.00 | 6% | <i>\$265.17</i> |
| EWP Premier TAC OS H30400 | 98000-H30400 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier TAC OS H30401 | 98000-H30401 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier TAC OS H30402 | 98000-H30402 | \$ 229.00 | 6% | <i>\$216.87</i> |
| EWP Premier TAC OS H30403 | 98000-H30403 | \$ 338.00 | 6% | <i>\$320.10</i> |
| EWP Premier TAC OS H30434 | 98000-H30434 | \$ 100.00 | 6% | <i>\$94.71</i> |
| EWP Premier TAC OS H30480 | 98000-H30480 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWP Premier TAC OS H30495 | 98000-H30495 | \$ 881.00 | 6% | <i>\$834.35</i> |
| EWP Premier TAC OS H30496 | 98000-H30496 | \$ 864.00 | 6% | <i>\$818.25</i> |
| EWP Premier TAC OS H30497 | 98000-H30497 | \$ 1,274.00 | 6% | <i>\$1,206.54</i> |
| EWP Premier TAC OS H30498 | 98000-H30498 | \$ 1,250.00 | 6% | <i>\$1,183.81</i> |
| EWP Premier TAC OS H30499 | 98000-H30499 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWP Premier TAC OS H30501 | 98000-H30501 | \$ 1,250.00 | 6% | <i>\$1,183.81</i> |
| EWP Premier TAC OS H30502 | 98000-H30502 | \$ 1,918.00 | 6% | <i>\$1,816.44</i> |
| EWP Premier TAC OS H30503 | 98000-H30503 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWP Premier TAC OS H30505 | 98000-H30505 | \$ 2,269.00 | 6% | <i>\$2,148.86</i> |
| EWP Premier TAC OS H30506 | 98000-H30506 | \$ 3,088.00 | 6% | <i>\$2,924.49</i> |
| EWP Premier TAC OS H30509 | 98000-H30509 | \$ 1,918.00 | 6% | <i>\$1,816.44</i> |
| EWP Premier TAC OS H30510 | 98000-H30510 | \$ 2,269.00 | 6% | <i>\$2,148.86</i> |
| EWP Premier TAC OS H30511 | 98000-H30511 | \$ 3,088.00 | 6% | <i>\$2,924.49</i> |
| EWP Premier TAC OS H30512 | 98000-H30512 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWP Premier TAC OS H30513 | 98000-H30513 | \$ 723.00 | 6% | <i>\$684.72</i> |
| EWP Premier TAC OS H30525 | 98000-H30525 | \$ 3,088.00 | 6% | <i>\$2,924.49</i> |
| EWP Premier TAC OS H30526 | 98000-H30526 | \$ 2,269.00 | 6% | <i>\$2,148.86</i> |
| EWP Premier TAC OS H30528 | 98000-H30528 | \$ 3,576.00 | 6% | <i>\$3,386.65</i> |
| EWP Premier TAC OS H30531 | 98000-H30531 | \$ 5,090.00 | 6% | <i>\$4,820.48</i> |
| EWP Premier TAC OS H30532 | 98000-H30532 | \$ 5,090.00 | 6% | <i>\$4,820.48</i> |
| EWP Premier TAC OS H30534 | 98000-H30534 | \$ 5,189.00 | 6% | <i>\$4,914.24</i> |
| EWP Premier TAC OS H30535 | 98000-H30535 | \$ 5,532.00 | 6% | <i>\$5,239.08</i> |
| EWP Premier TAC OS H30536 | 98000-H30536 | \$ 5,090.00 | 6% | <i>\$4,820.48</i> |
| EWP Premier TAC OS H30537 | 98000-H30537 | \$ 5,532.00 | 6% | <i>\$5,239.08</i> |
| EWP Premier TAC OS H30538 | 98000-H30538 | \$ 3,088.00 | 6% | <i>\$2,924.49</i> |
| EWP Premier TAC OS H30539 | 98000-H30539 | \$ 5,909.00 | 6% | <i>\$5,596.12</i> |
| EWP Premier TAC OS H30540 | 98000-H30540 | \$ 6,111.00 | 6% | <i>\$5,787.42</i> |
| EWP Premier TAC OS H30543 | 98000-H30543 | \$ 423.00 | 6% | <i>\$400.60</i> |
| EWP Premier TAC OS H30544 | 98000-H30544 | \$ 748.00 | 6% | <i>\$708.39</i> |
| EWP Premier TAC OS H30548 | 98000-H30548 | \$ 423.00 | 6% | <i>\$400.60</i> |
| EWP Premier TAC OS H30549 | 98000-H30549 | \$ 709.00 | 6% | <i>\$671.46</i> |
| EWP Premier TAC OS H30550 | 98000-H30550 | \$ 709.00 | 6% | <i>\$671.46</i> |
| EWP Premier TAC OS H30552 | 98000-H30552 | \$ 423.00 | 6% | <i>\$400.60</i> |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS H30553 | 98000-H30553 | \$ 663.00 | 6% | \$627.89 |
| EWP Premier TAC OS H30569 | 98000-H30569 | \$ 2,269.00 | 6% | \$2,148.86 |
| EWP Premier TAC OS H30570 | 98000-H30570 | \$ 2,717.00 | 6% | \$2,573.13 |
| EWP Premier TAC OS H30571 | 98000-H30571 | \$ 2,717.00 | 6% | \$2,573.13 |
| EWP Premier TAC OS H30573 | 98000-H30573 | \$ 2,269.00 | 6% | \$2,148.86 |
| EWP Premier TAC OS H30574 | 98000-H30574 | \$ 2,513.00 | 6% | \$2,379.94 |
| EWP Premier TAC OS H30575 | 98000-H30575 | \$ 1,561.00 | 6% | \$1,478.35 |
| EWP Premier TAC OS H30576 | 98000-H30576 | \$ 2,269.00 | 6% | \$2,148.86 |
| EWP Premier TAC OS H30577 | 98000-H30577 | \$ 2,666.00 | 6% | \$2,524.84 |
| EWP Premier TAC OS H30578 | 98000-H30578 | \$ 2,666.00 | 6% | \$2,524.84 |
| EWP Premier TAC OS H30587 | 98000-H30587 | \$ 2,313.00 | 6% | \$2,190.53 |
| EWP Premier TAC OS H30588 | 98000-H30588 | \$ 1,591.00 | 6% | \$1,506.76 |
| EWP Premier TAC OS H30589 | 98000-H30589 | \$ 2,423.00 | 6% | \$2,294.70 |
| EWP Premier TAC OS H30622 | 98000-H30622 | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS H30626 | 98000-H30626 | \$ 45.00 | 6% | \$42.62 |
| EWP Premier TAC OS H30632 | 98000-H30632 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30633 | 98000-H30633 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30643 | 98000-H30643 | \$ 3,819.00 | 6% | \$3,616.78 |
| EWP Premier TAC OS H30706 | 98000-H30706 | \$ 3,646.00 | 6% | \$3,452.94 |
| EWP Premier TAC OS H30707 | 98000-H30707 | \$ 2,269.00 | 6% | \$2,148.86 |
| EWP Premier TAC OS H30724 | 98000-H30724 | \$ 101.00 | 6% | \$95.65 |
| EWP Premier TAC OS H30725 | 98000-H30725 | \$ 864.00 | 6% | \$818.25 |
| EWP Premier TAC OS H30726 | 98000-H30726 | \$ 5,641.00 | 6% | \$5,342.31 |
| EWP Premier TAC OS H30727 | 98000-H30727 | \$ 5,994.00 | 6% | \$5,676.62 |
| EWP Premier TAC OS H30730 | 98000-H30730 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30731 | 98000-H30731 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30732 | 98000-H30732 | \$ 1,424.00 | 6% | \$1,348.60 |
| EWP Premier TAC OS H30733 | 98000-H30733 | \$ 5,587.00 | 6% | \$5,291.17 |
| EWP Premier TAC OS H30734 | 98000-H30734 | \$ 4,264.00 | 6% | \$4,038.22 |
| EWP Premier TAC OS H30735 | 98000-H30735 | \$ 4,885.00 | 6% | \$4,626.34 |
| EWP Premier TAC OS H30736 | 98000-H30736 | \$ 774.00 | 6% | \$733.02 |
| EWP Premier TAC OS H30738 | 98000-H30738 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30739 | 98000-H30739 | \$ 790.00 | 6% | \$748.17 |
| EWP Premier TAC OS H30740 | 98000-H30740 | \$ 457.00 | 6% | \$432.80 |
| EWP Premier TAC OS H30741 | 98000-H30741 | \$ 837.00 | 6% | \$792.68 |
| EWP Premier TAC OS H30742 | 98000-H30742 | \$ 749.00 | 6% | \$709.34 |
| EWP Premier TAC OS H30743 | 98000-H30743 | \$ 790.00 | 6% | \$748.17 |
| EWP Premier TAC OS H30744 | 98000-H30744 | \$ 457.00 | 6% | \$432.80 |
| EWP Premier TAC OS H30745 | 98000-H30745 | \$ 465.00 | 6% | \$440.38 |
| EWP Premier TAC OS H30746 | 98000-H30746 | \$ 869.00 | 6% | \$822.99 |
| EWP Premier TAC OS H30747 | 98000-H30747 | \$ 1,638.00 | 6% | \$1,551.27 |
| EWP Premier TAC OS H30748 | 98000-H30748 | \$ 2,427.00 | 6% | \$2,298.49 |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS H30749 | 98000-H30749 | \$ 5,448.00 | 6% | \$5,159.53 |
| EWP Premier TAC OS H30750 | 98000-H30750 | \$ 5,448.00 | 6% | \$5,159.53 |
| EWP Premier TAC OS H30751 | 98000-H30751 | \$ 3,245.00 | 6% | \$3,073.18 |
| EWP Premier TAC OS H30754 | 98000-H30754 | \$ 5,448.00 | 6% | \$5,159.53 |
| EWP Premier TAC OS H30755 | 98000-H30755 | \$ 5,926.00 | 6% | \$5,612.22 |
| EWP Premier TAC OS H30756 | 98000-H30756 | \$ 5,448.00 | 6% | \$5,159.53 |
| EWP Premier TAC OS H30757 | 98000-H30757 | \$ 2,427.00 | 6% | \$2,298.49 |
| EWP Premier TAC OS H30758 | 98000-H30758 | \$ 4,566.00 | 6% | \$4,324.23 |
| EWP Premier TAC OS H30759 | 98000-H30759 | \$ 5,130.00 | 6% | \$4,858.37 |
| EWP Premier TAC OS H30760 | 98000-H30760 | \$ 5,865.00 | 6% | \$5,554.45 |
| EWP Premier TAC OS H30761 | 98000-H30761 | \$ 2,427.00 | 6% | \$2,298.49 |
| EWP Premier TAC OS H30762 | 98000-H30762 | \$ 5,926.00 | 6% | \$5,612.22 |
| EWP Premier TAC OS H30763 | 98000-H30763 | \$ 5,926.00 | 6% | \$5,612.22 |
| EWP Premier TAC OS H30764 | 98000-H30764 | \$ 3,753.00 | 6% | \$3,554.28 |
| EWP Premier TAC OS H30765 | 98000-H30765 | \$ 3,308.00 | 6% | \$3,132.84 |
| EWP Premier TAC OS H30766 | 98000-H30766 | \$ 6,416.00 | 6% | \$6,076.27 |
| EWP Premier TAC OS H30767 | 98000-H30767 | \$ 3,753.00 | 6% | \$3,554.28 |
| EWP Premier TAC OS H30769 | 98000-H30769 | \$ 1,802.00 | 6% | \$1,706.58 |
| EWP Premier TAC OS H30773 | 98000-H30773 | \$ 65.00 | 6% | \$61.56 |
| EWP Premier TAC OS H30774 | 98000-H30774 | \$ 66.00 | 6% | \$62.51 |
| EWP Premier TAC OS H30775 | 98000-H30775 | \$ 66.00 | 6% | \$62.51 |
| EWP Premier TAC OS H30776 | 98000-H30776 | \$ 65.00 | 6% | \$61.56 |
| EWP Premier TAC OS H30777 | 98000-H30777 | \$ 66.00 | 6% | \$62.51 |
| EWP Premier TAC OS H30778 | 98000-H30778 | \$ 66.00 | 6% | \$62.51 |
| EWP Premier TAC OS H30779 | 98000-H30779 | \$ 53.00 | 6% | \$50.19 |
| EWP Premier TAC OS H30780 | 98000-H30780 | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS H30781 | 98000-H30781 | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS H30782 | 98000-H30782 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30783 | 98000-H30783 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30784 | 98000-H30784 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30785 | 98000-H30785 | \$ 53.00 | 6% | \$50.19 |
| EWP Premier TAC OS H30786 | 98000-H30786 | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS H30787 | 98000-H30787 | \$ 53.00 | 6% | \$50.19 |
| EWP Premier TAC OS H30788 | 98000-H30788 | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS H30789 | 98000-H30789 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30790 | 98000-H30790 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30791 | 98000-H30791 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30793 | 98000-H30793 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30794 | 98000-H30794 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30795 | 98000-H30795 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30796 | 98000-H30796 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30797 | 98000-H30797 | \$ 47.00 | 6% | \$44.51 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H30798 | 98000-H30798 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30799 | 98000-H30799 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30800 | 98000-H30800 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS H30801 | 98000-H30801 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30802 | 98000-H30802 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS H30803 | 98000-H30803 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30804 | 98000-H30804 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30805 | 98000-H30805 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30806 | 98000-H30806 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30807 | 98000-H30807 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30808 | 98000-H30808 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30809 | 98000-H30809 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30810 | 98000-H30810 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30811 | 98000-H30811 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30812 | 98000-H30812 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30813 | 98000-H30813 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS H30814 | 98000-H30814 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30815 | 98000-H30815 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30816 | 98000-H30816 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30817 | 98000-H30817 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30818 | 98000-H30818 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30819 | 98000-H30819 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30820 | 98000-H30820 | \$ 43.00 | 6% | \$40.72 |
| EWP Premier TAC OS H30821 | 98000-H30821 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS H30822 | 98000-H30822 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30823 | 98000-H30823 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS H30824 | 98000-H30824 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30825 | 98000-H30825 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS H30826 | 98000-H30826 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30827 | 98000-H30827 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30828 | 98000-H30828 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30829 | 98000-H30829 | \$ 48.00 | 6% | \$45.46 |
| EWP Premier TAC OS H30830 | 98000-H30830 | \$ 56.00 | 6% | \$53.03 |
| EWP Premier TAC OS H30831 | 98000-H30831 | \$ 46.00 | 6% | \$43.56 |
| EWP Premier TAC OS H30838 | 98000-H30838 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30839 | 98000-H30839 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30840 | 98000-H30840 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30841 | 98000-H30841 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30842 | 98000-H30842 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30843 | 98000-H30843 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30844 | 98000-H30844 | \$ 47.00 | 6% | \$44.51 |
| EWP Premier TAC OS H30845 | 98000-H30845 | \$ 47.00 | 6% | \$44.51 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H30846 | 98000-H30846 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30847 | 98000-H30847 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30848 | 98000-H30848 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30849 | 98000-H30849 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30850 | 98000-H30850 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30851 | 98000-H30851 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30852 | 98000-H30852 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier TAC OS H30853 | 98000-H30853 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30854 | 98000-H30854 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30855 | 98000-H30855 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30856 | 98000-H30856 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30857 | 98000-H30857 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30858 | 98000-H30858 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30859 | 98000-H30859 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30860 | 98000-H30860 | \$ 60.00 | 6% | \$56.82 |
| EWP Premier TAC OS H30866 | 98000-H30866 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H30867 | 98000-H30867 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30868 | 98000-H30868 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30869 | 98000-H30869 | \$ 85.00 | 6% | \$80.50 |
| EWP Premier TAC OS H30870 | 98000-H30870 | \$ 85.00 | 6% | \$80.50 |
| EWP Premier TAC OS H30871 | 98000-H30871 | \$ 84.00 | 6% | \$79.55 |
| EWP Premier TAC OS H30872 | 98000-H30872 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier TAC OS H30873 | 98000-H30873 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier TAC OS H30874 | 98000-H30874 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier TAC OS H30875 | 98000-H30875 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30876 | 98000-H30876 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30877 | 98000-H30877 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30878 | 98000-H30878 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30891 | 98000-H30891 | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS H30892 | 98000-H30892 | \$ 54.00 | 6% | \$51.14 |
| EWP Premier TAC OS H30893 | 98000-H30893 | \$ 49.00 | 6% | \$46.41 |
| EWP Premier TAC OS H30894 | 98000-H30894 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30895 | 98000-H30895 | \$ 66.00 | 6% | \$62.51 |
| EWP Premier TAC OS H30913 | 98000-H30913 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30914 | 98000-H30914 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30915 | 98000-H30915 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30916 | 98000-H30916 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30917 | 98000-H30917 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30918 | 98000-H30918 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30944 | 98000-H30944 | \$ 44.00 | 6% | \$41.67 |
| EWP Premier TAC OS H30946 | 98000-H30946 | \$ 53.00 | 6% | \$50.19 |
| EWP Premier TAC OS H30947 | 98000-H30947 | \$ 53.00 | 6% | \$50.19 |

| | | | | |
|---------------------------|--------------|----------|----|----------------|
| EWP Premier TAC OS H30948 | 98000-H30948 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS H30950 | 98000-H30950 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS H30951 | 98000-H30951 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS H30952 | 98000-H30952 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS H30966 | 98000-H30966 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier TAC OS H30967 | 98000-H30967 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier TAC OS H30968 | 98000-H30968 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier TAC OS H30969 | 98000-H30969 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H30970 | 98000-H30970 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier TAC OS H30971 | 98000-H30971 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier TAC OS H30972 | 98000-H30972 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier TAC OS H30973 | 98000-H30973 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier TAC OS H30974 | 98000-H30974 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier TAC OS H30975 | 98000-H30975 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier TAC OS H30976 | 98000-H30976 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier TAC OS H30977 | 98000-H30977 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier TAC OS H30978 | 98000-H30978 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier TAC OS H31040 | 98000-H31040 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier TAC OS H31041 | 98000-H31041 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H31042 | 98000-H31042 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier TAC OS H31047 | 98000-H31047 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier TAC OS H31060 | 98000-H31060 | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS H31062 | 98000-H31062 | \$ 43.00 | 6% | <i>\$40.72</i> |
| EWP Premier TAC OS H31066 | 98000-H31066 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier TAC OS H31068 | 98000-H31068 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier TAC OS H31077 | 98000-H31077 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier TAC OS H31124 | 98000-H31124 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier TAC OS H31127 | 98000-H31127 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier TAC OS H31132 | 98000-H31132 | \$ 63.00 | 6% | <i>\$59.66</i> |
| EWP Premier TAC OS H31134 | 98000-H31134 | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS H31135 | 98000-H31135 | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS H31136 | 98000-H31136 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H31137 | 98000-H31137 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier TAC OS H31185 | 98000-H31185 | \$ 35.00 | 6% | <i>\$33.15</i> |
| EWP Premier TAC OS H31192 | 98000-H31192 | \$ 34.00 | 6% | <i>\$32.20</i> |
| EWP Premier TAC OS H31193 | 98000-H31193 | \$ 34.00 | 6% | <i>\$32.20</i> |
| EWP Premier TAC OS H31194 | 98000-H31194 | \$ 34.00 | 6% | <i>\$32.20</i> |
| EWP Premier TAC OS H31197 | 98000-H31197 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H31198 | 98000-H31198 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H31199 | 98000-H31199 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H31200 | 98000-H31200 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H31201 | 98000-H31201 | \$ 49.00 | 6% | <i>\$46.41</i> |

| | | | | |
|---------------------------|--------------|--------------|----|--------------------|
| EWP Premier TAC OS H31202 | 98000-H31202 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier TAC OS H31203 | 98000-H31203 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS H31204 | 98000-H31204 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS H31205 | 98000-H31205 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS H31206 | 98000-H31206 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS H31207 | 98000-H31207 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier TAC OS H31208 | 98000-H31208 | \$ 54.00 | 6% | <i>\$51.14</i> |
| EWP Premier TAC OS H31335 | 98000-H31335 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier TAC OS H31337 | 98000-H31337 | \$ 6,242.00 | 6% | <i>\$5,911.49</i> |
| EWP Premier TAC OS H31338 | 98000-H31338 | \$ 6,242.00 | 6% | <i>\$5,911.49</i> |
| EWP Premier TAC OS H31339 | 98000-H31339 | \$ 986.00 | 6% | <i>\$933.79</i> |
| EWP Premier TAC OS H31340 | 98000-H31340 | \$ 2,120.00 | 6% | <i>\$2,007.75</i> |
| EWP Premier TAC OS H31341 | 98000-H31341 | \$ 3,214.00 | 6% | <i>\$3,043.82</i> |
| EWP Premier TAC OS H31342 | 98000-H31342 | \$ 1,009.00 | 6% | <i>\$955.57</i> |
| EWP Premier TAC OS H31343 | 98000-H31343 | \$ 1,497.00 | 6% | <i>\$1,417.73</i> |
| EWP Premier TAC OS H31344 | 98000-H31344 | \$ 1,497.00 | 6% | <i>\$1,417.73</i> |
| EWP Premier TAC OS H31345 | 98000-H31345 | \$ 1,497.00 | 6% | <i>\$1,417.73</i> |
| EWP Premier TAC OS H31346 | 98000-H31346 | \$ 1,497.00 | 6% | <i>\$1,417.73</i> |
| EWP Premier TAC OS H31348 | 98000-H31348 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier TAC OS H31349 | 98000-H31349 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier TAC OS H31350 | 98000-H31350 | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier TAC OS H31351 | 98000-H31351 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier TAC OS H31352 | 98000-H31352 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier TAC OS H31353 | 98000-H31353 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier TAC OS H31354 | 98000-H31354 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier TAC OS H31355 | 98000-H31355 | \$ 63.00 | 6% | <i>\$59.66</i> |
| EWP Premier TAC OS H31356 | 98000-H31356 | \$ 63.00 | 6% | <i>\$59.66</i> |
| EWP Premier TAC OS H31357 | 98000-H31357 | \$ 63.00 | 6% | <i>\$59.66</i> |
| EWP Premier TAC OS H31358 | 98000-H31358 | \$ 42.00 | 6% | <i>\$39.78</i> |
| EWP Premier TAC OS H31359 | 98000-H31359 | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier TAC OS H31360 | 98000-H31360 | \$ 41.00 | 6% | <i>\$38.83</i> |
| EWP Premier TAC OS H31362 | 98000-H31362 | \$ 11,429.00 | 6% | <i>\$10,823.83</i> |
| EWP Premier TAC OS H31363 | 98000-H31363 | \$ 11,429.00 | 6% | <i>\$10,823.83</i> |
| EWP Premier TAC OS H31364 | 98000-H31364 | \$ 3,995.00 | 6% | <i>\$3,783.46</i> |
| EWP Premier TAC OS H31365 | 98000-H31365 | \$ 3,995.00 | 6% | <i>\$3,783.46</i> |
| EWP Premier TAC OS H31366 | 98000-H31366 | \$ 7,973.00 | 6% | <i>\$7,550.83</i> |
| EWP Premier TAC OS H31367 | 98000-H31367 | \$ 7,973.00 | 6% | <i>\$7,550.83</i> |
| EWP Premier TAC OS H31368 | 98000-H31368 | \$ 333.00 | 6% | <i>\$315.37</i> |
| EWP Premier TAC OS H31369 | 98000-H31369 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier TAC OS H31370 | 98000-H31370 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier TAC OS H31393 | 98000-H31393 | \$ 41.00 | 6% | <i>\$38.83</i> |
| EWP Premier TAC OS H32010 | 98000-H32010 | \$ 230.00 | 6% | <i>\$217.82</i> |

| | | | | |
|---------------------------|--------------|--------------|----|-------------|
| EWP Premier TAC OS H32011 | 98000-H32011 | \$ 230.00 | 6% | \$217.82 |
| EWP Premier TAC OS H32012 | 98000-H32012 | \$ 1,336.00 | 6% | \$1,265.26 |
| EWP Premier TAC OS H32013 | 98000-H32013 | \$ 1,336.00 | 6% | \$1,265.26 |
| EWP Premier TAC OS H32014 | 98000-H32014 | \$ 1,336.00 | 6% | \$1,265.26 |
| EWP Premier TAC OS H32015 | 98000-H32015 | \$ 1,336.00 | 6% | \$1,265.26 |
| EWP Premier TAC OS H32016 | 98000-H32016 | \$ 1,147.00 | 6% | \$1,086.27 |
| EWP Premier TAC OS H32017 | 98000-H32017 | \$ 1,147.00 | 6% | \$1,086.27 |
| EWP Premier TAC OS H32018 | 98000-H32018 | \$ 1,147.00 | 6% | \$1,086.27 |
| EWP Premier TAC OS H32019 | 98000-H32019 | \$ 1,147.00 | 6% | \$1,086.27 |
| EWP Premier TAC OS H32020 | 98000-H32020 | \$ 11,878.00 | 6% | \$11,249.06 |
| EWP Premier TAC OS H32021 | 98000-H32021 | \$ 11,878.00 | 6% | \$11,249.06 |
| EWP Premier TAC OS H32022 | 98000-H32022 | \$ 11,878.00 | 6% | \$11,249.06 |
| EWP Premier TAC OS H32023 | 98000-H32023 | \$ 11,878.00 | 6% | \$11,249.06 |
| EWP Premier TAC OS H32028 | 98000-H32028 | \$ 21,970.00 | 6% | \$20,806.69 |
| EWP Premier TAC OS H32029 | 98000-H32029 | \$ 21,970.00 | 6% | \$20,806.69 |
| EWP Premier TAC OS H32030 | 98000-H32030 | \$ 24,024.00 | 6% | \$22,751.93 |
| EWP Premier TAC OS H32031 | 98000-H32031 | \$ 24,024.00 | 6% | \$22,751.93 |
| EWP Premier TAC OS H32032 | 98000-H32032 | \$ 24,024.00 | 6% | \$22,751.93 |
| EWP Premier TAC OS H32033 | 98000-H32033 | \$ 24,024.00 | 6% | \$22,751.93 |
| EWP Premier TAC OS H32038 | 98000-H32038 | \$ 4,155.00 | 6% | \$3,934.99 |
| EWP Premier TAC OS H32039 | 98000-H32039 | \$ 4,155.00 | 6% | \$3,934.99 |
| EWP Premier TAC OS H32040 | 98000-H32040 | \$ 4,155.00 | 6% | \$3,934.99 |
| EWP Premier TAC OS H32041 | 98000-H32041 | \$ 4,155.00 | 6% | \$3,934.99 |
| EWP Premier TAC OS H32046 | 98000-H32046 | \$ 5,763.00 | 6% | \$5,457.85 |
| EWP Premier TAC OS H32047 | 98000-H32047 | \$ 5,763.00 | 6% | \$5,457.85 |
| EWP Premier TAC OS H32048 | 98000-H32048 | \$ 5,763.00 | 6% | \$5,457.85 |
| EWP Premier TAC OS H32049 | 98000-H32049 | \$ 5,763.00 | 6% | \$5,457.85 |
| EWP Premier TAC OS H32054 | 98000-H32054 | \$ 4,155.00 | 6% | \$3,934.99 |
| EWP Premier TAC OS H32055 | 98000-H32055 | \$ 5,763.00 | 6% | \$5,457.85 |
| EWP Premier TAC OS H32056 | 98000-H32056 | \$ 1,242.00 | 6% | \$1,176.24 |
| EWP Premier TAC OS H32057 | 98000-H32057 | \$ 1,242.00 | 6% | \$1,176.24 |
| EWP Premier TAC OS H32058 | 98000-H32058 | \$ 1,242.00 | 6% | \$1,176.24 |
| EWP Premier TAC OS H32059 | 98000-H32059 | \$ 1,242.00 | 6% | \$1,176.24 |
| EWP Premier TAC OS H32060 | 98000-H32060 | \$ 1,594.00 | 6% | \$1,509.60 |
| EWP Premier TAC OS H32061 | 98000-H32061 | \$ 1,674.00 | 6% | \$1,585.36 |
| EWP Premier TAC OS H32062 | 98000-H32062 | \$ 1,594.00 | 6% | \$1,509.60 |
| EWP Premier TAC OS H32063 | 98000-H32063 | \$ 1,595.00 | 6% | \$1,510.54 |
| EWP Premier TAC OS H32064 | 98000-H32064 | \$ 1,594.00 | 6% | \$1,509.60 |
| EWP Premier TAC OS H32065 | 98000-H32065 | \$ 2,685.00 | 6% | \$2,542.83 |
| EWP Premier TAC OS H32066 | 98000-H32066 | \$ 2,685.00 | 6% | \$2,542.83 |
| EWP Premier TAC OS H32067 | 98000-H32067 | \$ 2,685.00 | 6% | \$2,542.83 |
| EWP Premier TAC OS H32068 | 98000-H32068 | \$ 2,685.00 | 6% | \$2,542.83 |

| | | | | |
|---------------------------|--------------|--------------|----|-------------|
| EWP Premier TAC OS H32069 | 98000-H32069 | \$ 3,347.00 | 6% | \$3,169.78 |
| EWP Premier TAC OS H32070 | 98000-H32070 | \$ 3,347.00 | 6% | \$3,169.78 |
| EWP Premier TAC OS H32071 | 98000-H32071 | \$ 3,347.00 | 6% | \$3,169.78 |
| EWP Premier TAC OS H32072 | 98000-H32072 | \$ 3,347.00 | 6% | \$3,169.78 |
| EWP Premier TAC OS H32073 | 98000-H32073 | \$ 16,715.00 | 6% | \$15,829.94 |
| EWP Premier TAC OS H32074 | 98000-H32074 | \$ 16,715.00 | 6% | \$15,829.94 |
| EWP Premier TAC OS H32075 | 98000-H32075 | \$ 22,709.00 | 6% | \$21,506.56 |
| EWP Premier TAC OS H32076 | 98000-H32076 | \$ 22,709.00 | 6% | \$21,506.56 |
| EWP Premier TAC OS H32090 | 98000-H32090 | \$ 1,385.00 | 6% | \$1,311.66 |
| EWP Premier TAC OS H32097 | 98000-H32097 | \$ 3,288.00 | 6% | \$3,113.90 |
| EWP Premier TAC OS H32101 | 98000-H32101 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32102 | 98000-H32102 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32103 | 98000-H32103 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32104 | 98000-H32104 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32105 | 98000-H32105 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32106 | 98000-H32106 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32107 | 98000-H32107 | \$ 4,028.00 | 6% | \$3,814.72 |
| EWP Premier TAC OS H32108 | 98000-H32108 | \$ 4,028.00 | 6% | \$3,814.72 |
| EWP Premier TAC OS H32109 | 98000-H32109 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32110 | 98000-H32110 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32111 | 98000-H32111 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32112 | 98000-H32112 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32113 | 98000-H32113 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32114 | 98000-H32114 | \$ 750.00 | 6% | \$710.29 |
| EWP Premier TAC OS H32115 | 98000-H32115 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32116 | 98000-H32116 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32117 | 98000-H32117 | \$ 711.00 | 6% | \$673.35 |
| EWP Premier TAC OS H32118 | 98000-H32118 | \$ 711.00 | 6% | \$673.35 |
| EWP Premier TAC OS H32119 | 98000-H32119 | \$ 711.00 | 6% | \$673.35 |
| EWP Premier TAC OS H32120 | 98000-H32120 | \$ 711.00 | 6% | \$673.35 |
| EWP Premier TAC OS H32121 | 98000-H32121 | \$ 4,028.00 | 6% | \$3,814.72 |
| EWP Premier TAC OS H32122 | 98000-H32122 | \$ 4,028.00 | 6% | \$3,814.72 |
| EWP Premier TAC OS H32123 | 98000-H32123 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32124 | 98000-H32124 | \$ 1,491.00 | 6% | \$1,412.05 |
| EWP Premier TAC OS H32125 | 98000-H32125 | \$ 1,472.00 | 6% | \$1,394.06 |
| EWP Premier TAC OS H32126 | 98000-H32126 | \$ 1,472.00 | 6% | \$1,394.06 |
| EWP Premier TAC OS H32127 | 98000-H32127 | \$ 1,736.00 | 6% | \$1,644.08 |
| EWP Premier TAC OS H32128 | 98000-H32128 | \$ 1,736.00 | 6% | \$1,644.08 |
| EWP Premier TAC OS H32129 | 98000-H32129 | \$ 1,736.00 | 6% | \$1,644.08 |
| EWP Premier TAC OS H32130 | 98000-H32130 | \$ 1,736.00 | 6% | \$1,644.08 |
| EWP Premier TAC OS H32131 | 98000-H32131 | \$ 1,736.00 | 6% | \$1,644.08 |
| EWP Premier TAC OS H32132 | 98000-H32132 | \$ 1,736.00 | 6% | \$1,644.08 |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| EWP Premier TAC OS H32133 | 98000-H32133 | \$ 1,472.00 | 6% | <i>\$1,394.06</i> |
| EWP Premier TAC OS H32134 | 98000-H32134 | \$ 1,472.00 | 6% | <i>\$1,394.06</i> |
| EWP Premier TAC OS H32135 | 98000-H32135 | \$ 1,472.00 | 6% | <i>\$1,394.06</i> |
| EWP Premier TAC OS H32136 | 98000-H32136 | \$ 1,472.00 | 6% | <i>\$1,394.06</i> |
| EWP Premier TAC OS H32137 | 98000-H32137 | \$ 1,472.00 | 6% | <i>\$1,394.06</i> |
| EWP Premier TAC OS H32138 | 98000-H32138 | \$ 1,472.00 | 6% | <i>\$1,394.06</i> |
| EWP Premier TAC OS H32139 | 98000-H32139 | \$ 6,224.00 | 6% | <i>\$5,894.44</i> |
| EWP Premier TAC OS H32140 | 98000-H32140 | \$ 6,224.00 | 6% | <i>\$5,894.44</i> |
| EWP Premier TAC OS H32141 | 98000-H32141 | \$ 7,185.00 | 6% | <i>\$6,804.55</i> |
| EWP Premier TAC OS H32142 | 98000-H32142 | \$ 7,185.00 | 6% | <i>\$6,804.55</i> |
| EWP Premier TAC OS H32143 | 98000-H32143 | \$ 285.00 | 6% | <i>\$269.91</i> |
| EWP Premier TAC OS H32144 | 98000-H32144 | \$ 299.00 | 6% | <i>\$283.17</i> |
| EWP Premier TAC OS H32146 | 98000-H32146 | \$ 683.00 | 6% | <i>\$646.84</i> |
| EWP Premier TAC OS H32147 | 98000-H32147 | \$ 683.00 | 6% | <i>\$646.84</i> |
| EWP Premier TAC OS H32148 | 98000-H32148 | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| EWP Premier TAC OS H32149 | 98000-H32149 | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| EWP Premier TAC OS H32150 | 98000-H32150 | \$ 683.00 | 6% | <i>\$646.84</i> |
| EWP Premier TAC OS H32151 | 98000-H32151 | \$ 285.00 | 6% | <i>\$269.91</i> |
| EWP Premier TAC OS H32152 | 98000-H32152 | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWP Premier TAC OS H32154 | 98000-H32154 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWP Premier TAC OS H32169 | 98000-H32169 | \$ 715.00 | 6% | <i>\$677.14</i> |
| EWP Premier TAC OS H32170 | 98000-H32170 | \$ 715.00 | 6% | <i>\$677.14</i> |
| EWP Premier TAC OS H32171 | 98000-H32171 | \$ 678.00 | 6% | <i>\$642.10</i> |
| EWP Premier TAC OS H32172 | 98000-H32172 | \$ 678.00 | 6% | <i>\$642.10</i> |
| EWP Premier TAC OS H32173 | 98000-H32173 | \$ 1,775.00 | 6% | <i>\$1,681.01</i> |
| EWP Premier TAC OS H32174 | 98000-H32174 | \$ 1,775.00 | 6% | <i>\$1,681.01</i> |
| EWP Premier TAC OS H32175 | 98000-H32175 | \$ 1,507.00 | 6% | <i>\$1,427.20</i> |
| EWP Premier TAC OS H32176 | 98000-H32176 | \$ 1,507.00 | 6% | <i>\$1,427.20</i> |
| EWP Premier TAC OS H32177 | 98000-H32177 | \$ 6,901.00 | 6% | <i>\$6,535.59</i> |
| EWP Premier TAC OS H32178 | 98000-H32178 | \$ 7,965.00 | 6% | <i>\$7,543.25</i> |
| EWP Premier TAC OS H34008 | 98000-H34008 | \$ 36.00 | 6% | <i>\$34.09</i> |
| EWP Premier TAC OS H34009 | 98000-H34009 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier TAC OS H34010 | 98000-H34010 | \$ 44.00 | 6% | <i>\$41.67</i> |
| EWP Premier TAC OS H34011 | 98000-H34011 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier TAC OS H34012 | 98000-H34012 | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier TAC OS H34013 | 98000-H34013 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier TAC OS H34014 | 98000-H34014 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier TAC OS H34015 | 98000-H34015 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier TAC OS H34016 | 98000-H34016 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier TAC OS H34017 | 98000-H34017 | \$ 193.00 | 6% | <i>\$182.78</i> |
| EWP Premier TAC OS H34018 | 98000-H34018 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier TAC OS H34019 | 98000-H34019 | \$ 74.00 | 6% | <i>\$70.08</i> |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| EWP Premier TAC OS H34020 | 98000-H34020 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier TAC OS H34021 | 98000-H34021 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier TAC OS H34048 | 98000-H34048 | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier TAC OS H34049 | 98000-H34049 | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier TAC OS H34050 | 98000-H34050 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier TAC OS H34051 | 98000-H34051 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier TAC OS H34052 | 98000-H34052 | \$ 312.00 | 6% | <i>\$295.48</i> |
| EWP Premier TAC OS H34053 | 98000-H34053 | \$ 312.00 | 6% | <i>\$295.48</i> |
| EWP Premier TAC OS H34054 | 98000-H34054 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34055 | 98000-H34055 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34056 | 98000-H34056 | \$ 350.00 | 6% | <i>\$331.47</i> |
| EWP Premier TAC OS H34057 | 98000-H34057 | \$ 350.00 | 6% | <i>\$331.47</i> |
| EWP Premier TAC OS H34058 | 98000-H34058 | \$ 307.00 | 6% | <i>\$290.74</i> |
| EWP Premier TAC OS H34059 | 98000-H34059 | \$ 307.00 | 6% | <i>\$290.74</i> |
| EWP Premier TAC OS H34062 | 98000-H34062 | \$ 350.00 | 6% | <i>\$331.47</i> |
| EWP Premier TAC OS H34063 | 98000-H34063 | \$ 350.00 | 6% | <i>\$331.47</i> |
| EWP Premier TAC OS H34064 | 98000-H34064 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34065 | 98000-H34065 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34066 | 98000-H34066 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34067 | 98000-H34067 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34068 | 98000-H34068 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34069 | 98000-H34069 | \$ 230.00 | 6% | <i>\$217.82</i> |
| EWP Premier TAC OS H34070 | 98000-H34070 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34071 | 98000-H34071 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier TAC OS H34072 | 98000-H34072 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H34073 | 98000-H34073 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H34074 | 98000-H34074 | \$ 2,928.00 | 6% | <i>\$2,772.96</i> |
| EWP Premier TAC OS H34075 | 98000-H34075 | \$ 2,712.00 | 6% | <i>\$2,568.40</i> |
| EWP Premier TAC OS H34076 | 98000-H34076 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H34077 | 98000-H34077 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H34078 | 98000-H34078 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H34079 | 98000-H34079 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H34080 | 98000-H34080 | \$ 2,928.00 | 6% | <i>\$2,772.96</i> |
| EWP Premier TAC OS H34081 | 98000-H34081 | \$ 2,809.00 | 6% | <i>\$2,660.26</i> |
| EWP Premier TAC OS H34082 | 98000-H34082 | \$ 2,795.00 | 6% | <i>\$2,647.00</i> |
| EWP Premier TAC OS H34083 | 98000-H34083 | \$ 2,682.00 | 6% | <i>\$2,539.99</i> |
| EWP Premier TAC OS H34084 | 98000-H34084 | \$ 1,796.00 | 6% | <i>\$1,700.90</i> |
| EWP Premier TAC OS H34085 | 98000-H34085 | \$ 1,796.00 | 6% | <i>\$1,700.90</i> |
| EWP Premier TAC OS H34086 | 98000-H34086 | \$ 2,192.00 | 6% | <i>\$2,075.93</i> |
| EWP Premier TAC OS H34087 | 98000-H34087 | \$ 2,093.00 | 6% | <i>\$1,982.18</i> |
| EWP Premier TAC OS H34088 | 98000-H34088 | \$ 5,028.00 | 6% | <i>\$4,761.77</i> |
| EWP Premier TAC OS H34089 | 98000-H34089 | \$ 5,028.00 | 6% | <i>\$4,761.77</i> |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS H34090 | 98000-H34090 | \$ 5,526.00 | 6% | \$5,233.40 |
| EWP Premier TAC OS H34091 | 98000-H34091 | \$ 3,222.00 | 6% | \$3,051.40 |
| EWP Premier TAC OS H34092 | 98000-H34092 | \$ 3,222.00 | 6% | \$3,051.40 |
| EWP Premier TAC OS H34093 | 98000-H34093 | \$ 3,222.00 | 6% | \$3,051.40 |
| EWP Premier TAC OS H34094 | 98000-H34094 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34095 | 98000-H34095 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34096 | 98000-H34096 | \$ 418.00 | 6% | \$395.87 |
| EWP Premier TAC OS H34097 | 98000-H34097 | \$ 418.00 | 6% | \$395.87 |
| EWP Premier TAC OS H34098 | 98000-H34098 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34099 | 98000-H34099 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34100 | 98000-H34100 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34101 | 98000-H34101 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34102 | 98000-H34102 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34103 | 98000-H34103 | \$ 374.00 | 6% | \$354.20 |
| EWP Premier TAC OS H34104 | 98000-H34104 | \$ 163.00 | 6% | \$154.37 |
| EWP Premier TAC OS H34105 | 98000-H34105 | \$ 163.00 | 6% | \$154.37 |
| EWP Premier TAC OS H34106 | 98000-H34106 | \$ 163.00 | 6% | \$154.37 |
| EWP Premier TAC OS H34107 | 98000-H34107 | \$ 163.00 | 6% | \$154.37 |
| EWP Premier TAC OS H34108 | 98000-H34108 | \$ 163.00 | 6% | \$154.37 |
| EWP Premier TAC OS H34109 | 98000-H34109 | \$ 163.00 | 6% | \$154.37 |
| EWP Premier TAC OS H34110 | 98000-H34110 | \$ 2,961.00 | 6% | \$2,804.22 |
| EWP Premier TAC OS H34111 | 98000-H34111 | \$ 2,961.00 | 6% | \$2,804.22 |
| EWP Premier TAC OS H34112 | 98000-H34112 | \$ 2,961.00 | 6% | \$2,804.22 |
| EWP Premier TAC OS H34114 | 98000-H34114 | \$ 3,879.00 | 6% | \$3,673.61 |
| EWP Premier TAC OS H34115 | 98000-H34115 | \$ 3,879.00 | 6% | \$3,673.61 |
| EWP Premier TAC OS H34116 | 98000-H34116 | \$ 3,879.00 | 6% | \$3,673.61 |
| EWP Premier TAC OS H34117 | 98000-H34117 | \$ 3,879.00 | 6% | \$3,673.61 |
| EWP Premier TAC OS H34118 | 98000-H34118 | \$ 978.00 | 6% | \$926.21 |
| EWP Premier TAC OS H34119 | 98000-H34119 | \$ 978.00 | 6% | \$926.21 |
| EWP Premier TAC OS H34120 | 98000-H34120 | \$ 677.00 | 6% | \$641.15 |
| EWP Premier TAC OS H34121 | 98000-H34121 | \$ 677.00 | 6% | \$641.15 |
| EWP Premier TAC OS H34122 | 98000-H34122 | \$ 704.00 | 6% | \$666.72 |
| EWP Premier TAC OS H34123 | 98000-H34123 | \$ 704.00 | 6% | \$666.72 |
| EWP Premier TAC OS H34124 | 98000-H34124 | \$ 1,050.00 | 6% | \$994.40 |
| EWP Premier TAC OS H34125 | 98000-H34125 | \$ 1,050.00 | 6% | \$994.40 |
| EWP Premier TAC OS H34126 | 98000-H34126 | \$ 1,050.00 | 6% | \$994.40 |
| EWP Premier TAC OS H34127 | 98000-H34127 | \$ 1,050.00 | 6% | \$994.40 |
| EWP Premier TAC OS H34128 | 98000-H34128 | \$ 161.00 | 6% | \$152.48 |
| EWP Premier TAC OS H34129 | 98000-H34129 | \$ 292.00 | 6% | \$276.54 |
| EWP Premier TAC OS H34130 | 98000-H34130 | \$ 317.00 | 6% | \$300.21 |
| EWP Premier TAC OS H34131 | 98000-H34131 | \$ 317.00 | 6% | \$300.21 |
| EWP Premier TAC OS H34132 | 98000-H34132 | \$ 317.00 | 6% | \$300.21 |

| | | | | |
|---------------------------|--------------|-----------|----|----------|
| EWP Premier TAC OS H34172 | 98000-H34172 | \$ 660.00 | 6% | \$625.05 |
| EWP Premier TAC OS H34174 | 98000-H34174 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34175 | 98000-H34175 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34176 | 98000-H34176 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34177 | 98000-H34177 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34178 | 98000-H34178 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34179 | 98000-H34179 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34180 | 98000-H34180 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34181 | 98000-H34181 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34182 | 98000-H34182 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34183 | 98000-H34183 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34184 | 98000-H34184 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34185 | 98000-H34185 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34186 | 98000-H34186 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34187 | 98000-H34187 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34188 | 98000-H34188 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34189 | 98000-H34189 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34190 | 98000-H34190 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34191 | 98000-H34191 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34192 | 98000-H34192 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34193 | 98000-H34193 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34194 | 98000-H34194 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34195 | 98000-H34195 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34196 | 98000-H34196 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34197 | 98000-H34197 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34198 | 98000-H34198 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34199 | 98000-H34199 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34200 | 98000-H34200 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34201 | 98000-H34201 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34202 | 98000-H34202 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34203 | 98000-H34203 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34204 | 98000-H34204 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34205 | 98000-H34205 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34206 | 98000-H34206 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34207 | 98000-H34207 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34208 | 98000-H34208 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34209 | 98000-H34209 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34210 | 98000-H34210 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34211 | 98000-H34211 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34212 | 98000-H34212 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34213 | 98000-H34213 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34214 | 98000-H34214 | \$ 35.00 | 6% | \$33.15 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34215 | 98000-H34215 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34216 | 98000-H34216 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34217 | 98000-H34217 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34218 | 98000-H34218 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34219 | 98000-H34219 | \$ 35.00 | 6% | \$33.15 |
| EWP Premier TAC OS H34220 | 98000-H34220 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34221 | 98000-H34221 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34222 | 98000-H34222 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34223 | 98000-H34223 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34224 | 98000-H34224 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34225 | 98000-H34225 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34226 | 98000-H34226 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34227 | 98000-H34227 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34228 | 98000-H34228 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34229 | 98000-H34229 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34230 | 98000-H34230 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34231 | 98000-H34231 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34232 | 98000-H34232 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34233 | 98000-H34233 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34234 | 98000-H34234 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34235 | 98000-H34235 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34236 | 98000-H34236 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34237 | 98000-H34237 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34238 | 98000-H34238 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34239 | 98000-H34239 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34240 | 98000-H34240 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34241 | 98000-H34241 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34242 | 98000-H34242 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34243 | 98000-H34243 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34244 | 98000-H34244 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34245 | 98000-H34245 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34246 | 98000-H34246 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34247 | 98000-H34247 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34248 | 98000-H34248 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34249 | 98000-H34249 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34250 | 98000-H34250 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34251 | 98000-H34251 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34252 | 98000-H34252 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34253 | 98000-H34253 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34254 | 98000-H34254 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34255 | 98000-H34255 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34256 | 98000-H34256 | \$ 52.00 | 6% | \$49.25 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34257 | 98000-H34257 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34258 | 98000-H34258 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34259 | 98000-H34259 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34260 | 98000-H34260 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34261 | 98000-H34261 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34262 | 98000-H34262 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34263 | 98000-H34263 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34264 | 98000-H34264 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34265 | 98000-H34265 | \$ 52.00 | 6% | \$49.25 |
| EWP Premier TAC OS H34266 | 98000-H34266 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34267 | 98000-H34267 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34268 | 98000-H34268 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34269 | 98000-H34269 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34270 | 98000-H34270 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34271 | 98000-H34271 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34272 | 98000-H34272 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34273 | 98000-H34273 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34274 | 98000-H34274 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34275 | 98000-H34275 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34276 | 98000-H34276 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34277 | 98000-H34277 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34278 | 98000-H34278 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34279 | 98000-H34279 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34280 | 98000-H34280 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34281 | 98000-H34281 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34282 | 98000-H34282 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34283 | 98000-H34283 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34284 | 98000-H34284 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34285 | 98000-H34285 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34286 | 98000-H34286 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34287 | 98000-H34287 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34288 | 98000-H34288 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34289 | 98000-H34289 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34290 | 98000-H34290 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34291 | 98000-H34291 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34292 | 98000-H34292 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34293 | 98000-H34293 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34294 | 98000-H34294 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34295 | 98000-H34295 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34296 | 98000-H34296 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34297 | 98000-H34297 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34298 | 98000-H34298 | \$ 41.00 | 6% | \$38.83 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34299 | 98000-H34299 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34300 | 98000-H34300 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34301 | 98000-H34301 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34302 | 98000-H34302 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34303 | 98000-H34303 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34304 | 98000-H34304 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34305 | 98000-H34305 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H34306 | 98000-H34306 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34307 | 98000-H34307 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34308 | 98000-H34308 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34309 | 98000-H34309 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34310 | 98000-H34310 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34311 | 98000-H34311 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34312 | 98000-H34312 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34313 | 98000-H34313 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34314 | 98000-H34314 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34315 | 98000-H34315 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34316 | 98000-H34316 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34317 | 98000-H34317 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34318 | 98000-H34318 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34319 | 98000-H34319 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34320 | 98000-H34320 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34321 | 98000-H34321 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34322 | 98000-H34322 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34323 | 98000-H34323 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34324 | 98000-H34324 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34325 | 98000-H34325 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34326 | 98000-H34326 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34327 | 98000-H34327 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34328 | 98000-H34328 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34329 | 98000-H34329 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34330 | 98000-H34330 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34331 | 98000-H34331 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34332 | 98000-H34332 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34333 | 98000-H34333 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34334 | 98000-H34334 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34335 | 98000-H34335 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34336 | 98000-H34336 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34337 | 98000-H34337 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34338 | 98000-H34338 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34339 | 98000-H34339 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34340 | 98000-H34340 | \$ 55.00 | 6% | \$52.09 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34341 | 98000-H34341 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34342 | 98000-H34342 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34343 | 98000-H34343 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34344 | 98000-H34344 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34345 | 98000-H34345 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34346 | 98000-H34346 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34347 | 98000-H34347 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34348 | 98000-H34348 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34349 | 98000-H34349 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34350 | 98000-H34350 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34351 | 98000-H34351 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34352 | 98000-H34352 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34353 | 98000-H34353 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34354 | 98000-H34354 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34355 | 98000-H34355 | \$ 55.00 | 6% | \$52.09 |
| EWP Premier TAC OS H34356 | 98000-H34356 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34357 | 98000-H34357 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34358 | 98000-H34358 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34359 | 98000-H34359 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34360 | 98000-H34360 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34361 | 98000-H34361 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34362 | 98000-H34362 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34363 | 98000-H34363 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34364 | 98000-H34364 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34365 | 98000-H34365 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34366 | 98000-H34366 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34367 | 98000-H34367 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34368 | 98000-H34368 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34369 | 98000-H34369 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34370 | 98000-H34370 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34371 | 98000-H34371 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34372 | 98000-H34372 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34373 | 98000-H34373 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34374 | 98000-H34374 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34375 | 98000-H34375 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34376 | 98000-H34376 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34377 | 98000-H34377 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34378 | 98000-H34378 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34379 | 98000-H34379 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34380 | 98000-H34380 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34381 | 98000-H34381 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34382 | 98000-H34382 | \$ 90.00 | 6% | \$85.23 |

| | | | | |
|---------------------------|--------------|-----------|----|----------|
| EWP Premier TAC OS H34383 | 98000-H34383 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34384 | 98000-H34384 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34385 | 98000-H34385 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34386 | 98000-H34386 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34387 | 98000-H34387 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34388 | 98000-H34388 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34389 | 98000-H34389 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34390 | 98000-H34390 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34391 | 98000-H34391 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34392 | 98000-H34392 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34393 | 98000-H34393 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34394 | 98000-H34394 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34395 | 98000-H34395 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34396 | 98000-H34396 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34397 | 98000-H34397 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34398 | 98000-H34398 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34399 | 98000-H34399 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34400 | 98000-H34400 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34401 | 98000-H34401 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34402 | 98000-H34402 | \$ 90.00 | 6% | \$85.23 |
| EWP Premier TAC OS H34403 | 98000-H34403 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34404 | 98000-H34404 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34405 | 98000-H34405 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34406 | 98000-H34406 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34407 | 98000-H34407 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34408 | 98000-H34408 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34409 | 98000-H34409 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34410 | 98000-H34410 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34411 | 98000-H34411 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34412 | 98000-H34412 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34413 | 98000-H34413 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34414 | 98000-H34414 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34415 | 98000-H34415 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34416 | 98000-H34416 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34417 | 98000-H34417 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34418 | 98000-H34418 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34419 | 98000-H34419 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34420 | 98000-H34420 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34421 | 98000-H34421 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34422 | 98000-H34422 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34423 | 98000-H34423 | \$ 143.00 | 6% | \$135.43 |
| EWP Premier TAC OS H34424 | 98000-H34424 | \$ 143.00 | 6% | \$135.43 |

| | | | | |
|---------------------------|--------------|-----------|----|-----------------|
| EWP Premier TAC OS H34425 | 98000-H34425 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34426 | 98000-H34426 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34427 | 98000-H34427 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34428 | 98000-H34428 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34429 | 98000-H34429 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34430 | 98000-H34430 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34431 | 98000-H34431 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34432 | 98000-H34432 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34433 | 98000-H34433 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34434 | 98000-H34434 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34435 | 98000-H34435 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34436 | 98000-H34436 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34437 | 98000-H34437 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34438 | 98000-H34438 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34439 | 98000-H34439 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34440 | 98000-H34440 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34441 | 98000-H34441 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34442 | 98000-H34442 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34443 | 98000-H34443 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34444 | 98000-H34444 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34445 | 98000-H34445 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier TAC OS H34446 | 98000-H34446 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34447 | 98000-H34447 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34448 | 98000-H34448 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34449 | 98000-H34449 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34450 | 98000-H34450 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34451 | 98000-H34451 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34452 | 98000-H34452 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34453 | 98000-H34453 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34454 | 98000-H34454 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34455 | 98000-H34455 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34456 | 98000-H34456 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34457 | 98000-H34457 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34458 | 98000-H34458 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34459 | 98000-H34459 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34460 | 98000-H34460 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34461 | 98000-H34461 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34462 | 98000-H34462 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34463 | 98000-H34463 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34464 | 98000-H34464 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34465 | 98000-H34465 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34466 | 98000-H34466 | \$ 164.00 | 6% | <i>\$155.32</i> |

| | | | | |
|---------------------------|--------------|-----------|----|-----------------|
| EWP Premier TAC OS H34467 | 98000-H34467 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34468 | 98000-H34468 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34469 | 98000-H34469 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34470 | 98000-H34470 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34471 | 98000-H34471 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34472 | 98000-H34472 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34473 | 98000-H34473 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34474 | 98000-H34474 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34475 | 98000-H34475 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34476 | 98000-H34476 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34477 | 98000-H34477 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34478 | 98000-H34478 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34479 | 98000-H34479 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34480 | 98000-H34480 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34481 | 98000-H34481 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34482 | 98000-H34482 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34483 | 98000-H34483 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34484 | 98000-H34484 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34485 | 98000-H34485 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34486 | 98000-H34486 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34487 | 98000-H34487 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34488 | 98000-H34488 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34489 | 98000-H34489 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier TAC OS H34490 | 98000-H34490 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34491 | 98000-H34491 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34492 | 98000-H34492 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34493 | 98000-H34493 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34494 | 98000-H34494 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34495 | 98000-H34495 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34496 | 98000-H34496 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34497 | 98000-H34497 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34498 | 98000-H34498 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34499 | 98000-H34499 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34500 | 98000-H34500 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34501 | 98000-H34501 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34502 | 98000-H34502 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34503 | 98000-H34503 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34504 | 98000-H34504 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34505 | 98000-H34505 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34506 | 98000-H34506 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34507 | 98000-H34507 | \$ 25.00 | 6% | <i>\$23.68</i> |
| EWP Premier TAC OS H34508 | 98000-H34508 | \$ 25.00 | 6% | <i>\$23.68</i> |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34509 | 98000-H34509 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34510 | 98000-H34510 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34511 | 98000-H34511 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34512 | 98000-H34512 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34513 | 98000-H34513 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34514 | 98000-H34514 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34515 | 98000-H34515 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34516 | 98000-H34516 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34517 | 98000-H34517 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34518 | 98000-H34518 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34519 | 98000-H34519 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34520 | 98000-H34520 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34521 | 98000-H34521 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34522 | 98000-H34522 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34523 | 98000-H34523 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34524 | 98000-H34524 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34525 | 98000-H34525 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34526 | 98000-H34526 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34527 | 98000-H34527 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34528 | 98000-H34528 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34529 | 98000-H34529 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34530 | 98000-H34530 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34531 | 98000-H34531 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34532 | 98000-H34532 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34533 | 98000-H34533 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34534 | 98000-H34534 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34535 | 98000-H34535 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34536 | 98000-H34536 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34537 | 98000-H34537 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34538 | 98000-H34538 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34539 | 98000-H34539 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34540 | 98000-H34540 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34541 | 98000-H34541 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34542 | 98000-H34542 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34543 | 98000-H34543 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34544 | 98000-H34544 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34545 | 98000-H34545 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34546 | 98000-H34546 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34547 | 98000-H34547 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34548 | 98000-H34548 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34549 | 98000-H34549 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34550 | 98000-H34550 | \$ 25.00 | 6% | \$23.68 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34551 | 98000-H34551 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34552 | 98000-H34552 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34553 | 98000-H34553 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34554 | 98000-H34554 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34555 | 98000-H34555 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34556 | 98000-H34556 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34557 | 98000-H34557 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34558 | 98000-H34558 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34559 | 98000-H34559 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34560 | 98000-H34560 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34561 | 98000-H34561 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34562 | 98000-H34562 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34563 | 98000-H34563 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34564 | 98000-H34564 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34565 | 98000-H34565 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34566 | 98000-H34566 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34567 | 98000-H34567 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34568 | 98000-H34568 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34569 | 98000-H34569 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34570 | 98000-H34570 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34571 | 98000-H34571 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34572 | 98000-H34572 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34573 | 98000-H34573 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34574 | 98000-H34574 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34575 | 98000-H34575 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34576 | 98000-H34576 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34577 | 98000-H34577 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34578 | 98000-H34578 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34579 | 98000-H34579 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34580 | 98000-H34580 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34581 | 98000-H34581 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34582 | 98000-H34582 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34583 | 98000-H34583 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34584 | 98000-H34584 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34585 | 98000-H34585 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34586 | 98000-H34586 | \$ 25.00 | 6% | \$23.68 |
| EWP Premier TAC OS H34587 | 98000-H34587 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34588 | 98000-H34588 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34589 | 98000-H34589 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34590 | 98000-H34590 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34591 | 98000-H34591 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34592 | 98000-H34592 | \$ 61.00 | 6% | \$57.77 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34593 | 98000-H34593 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34594 | 98000-H34594 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34595 | 98000-H34595 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34596 | 98000-H34596 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34597 | 98000-H34597 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34598 | 98000-H34598 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34599 | 98000-H34599 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34600 | 98000-H34600 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34601 | 98000-H34601 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34602 | 98000-H34602 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34603 | 98000-H34603 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34604 | 98000-H34604 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34605 | 98000-H34605 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34606 | 98000-H34606 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34607 | 98000-H34607 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34608 | 98000-H34608 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34609 | 98000-H34609 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34610 | 98000-H34610 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34611 | 98000-H34611 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34612 | 98000-H34612 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34613 | 98000-H34613 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34614 | 98000-H34614 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34615 | 98000-H34615 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34616 | 98000-H34616 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34617 | 98000-H34617 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34618 | 98000-H34618 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34619 | 98000-H34619 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34620 | 98000-H34620 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34621 | 98000-H34621 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34622 | 98000-H34622 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34623 | 98000-H34623 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34624 | 98000-H34624 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34625 | 98000-H34625 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34626 | 98000-H34626 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34627 | 98000-H34627 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34628 | 98000-H34628 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34629 | 98000-H34629 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34630 | 98000-H34630 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34631 | 98000-H34631 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H34632 | 98000-H34632 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34633 | 98000-H34633 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34634 | 98000-H34634 | \$ 70.00 | 6% | \$66.29 |

| | | | | |
|---------------------------|--------------|----------|----|---------|
| EWP Premier TAC OS H34635 | 98000-H34635 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34636 | 98000-H34636 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34637 | 98000-H34637 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34638 | 98000-H34638 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34639 | 98000-H34639 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34640 | 98000-H34640 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34641 | 98000-H34641 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34642 | 98000-H34642 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34643 | 98000-H34643 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34644 | 98000-H34644 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34645 | 98000-H34645 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34646 | 98000-H34646 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34647 | 98000-H34647 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34648 | 98000-H34648 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34649 | 98000-H34649 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34650 | 98000-H34650 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34651 | 98000-H34651 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34652 | 98000-H34652 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34653 | 98000-H34653 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34654 | 98000-H34654 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34655 | 98000-H34655 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34656 | 98000-H34656 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34657 | 98000-H34657 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34658 | 98000-H34658 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34659 | 98000-H34659 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34660 | 98000-H34660 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34661 | 98000-H34661 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34662 | 98000-H34662 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34663 | 98000-H34663 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34664 | 98000-H34664 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34665 | 98000-H34665 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34666 | 98000-H34666 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34667 | 98000-H34667 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34668 | 98000-H34668 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34669 | 98000-H34669 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34670 | 98000-H34670 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34671 | 98000-H34671 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34672 | 98000-H34672 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34673 | 98000-H34673 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34674 | 98000-H34674 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34675 | 98000-H34675 | \$ 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34676 | 98000-H34676 | \$ 70.00 | 6% | \$66.29 |

| | | | | | |
|---------------------------|--------------|----|-------|----|---------|
| EWP Premier TAC OS H34677 | 98000-H34677 | \$ | 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34678 | 98000-H34678 | \$ | 70.00 | 6% | \$66.29 |
| EWP Premier TAC OS H34679 | 98000-H34679 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34680 | 98000-H34680 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34681 | 98000-H34681 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34682 | 98000-H34682 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34683 | 98000-H34683 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34684 | 98000-H34684 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34685 | 98000-H34685 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34686 | 98000-H34686 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34687 | 98000-H34687 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34688 | 98000-H34688 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34689 | 98000-H34689 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34690 | 98000-H34690 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34691 | 98000-H34691 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34692 | 98000-H34692 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34693 | 98000-H34693 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34694 | 98000-H34694 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34695 | 98000-H34695 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34696 | 98000-H34696 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34697 | 98000-H34697 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34698 | 98000-H34698 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34699 | 98000-H34699 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34700 | 98000-H34700 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34701 | 98000-H34701 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34702 | 98000-H34702 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34703 | 98000-H34703 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34704 | 98000-H34704 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34705 | 98000-H34705 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34706 | 98000-H34706 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34707 | 98000-H34707 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34708 | 98000-H34708 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34709 | 98000-H34709 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34710 | 98000-H34710 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34711 | 98000-H34711 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34712 | 98000-H34712 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34713 | 98000-H34713 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34714 | 98000-H34714 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34715 | 98000-H34715 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34716 | 98000-H34716 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34717 | 98000-H34717 | \$ | 81.00 | 6% | \$76.71 |
| EWP Premier TAC OS H34718 | 98000-H34718 | \$ | 81.00 | 6% | \$76.71 |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| EWP Premier TAC OS H34719 | 98000-H34719 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier TAC OS H34720 | 98000-H34720 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier TAC OS H34721 | 98000-H34721 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier TAC OS H34722 | 98000-H34722 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier TAC OS H34723 | 98000-H34723 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier TAC OS H34724 | 98000-H34724 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier TAC OS H34725 | 98000-H34725 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier TAC OS H34726 | 98000-H34726 | \$ 2,328.00 | 6% | <i>\$2,204.73</i> |
| EWP Premier TAC OS H34727 | 98000-H34727 | \$ 2,328.00 | 6% | <i>\$2,204.73</i> |
| EWP Premier TAC OS H34728 | 98000-H34728 | \$ 2,328.00 | 6% | <i>\$2,204.73</i> |
| EWP Premier TAC OS H34729 | 98000-H34729 | \$ 2,328.00 | 6% | <i>\$2,204.73</i> |
| EWP Premier TAC OS H34730 | 98000-H34730 | \$ 2,489.00 | 6% | <i>\$2,357.21</i> |
| EWP Premier TAC OS H34731 | 98000-H34731 | \$ 2,489.00 | 6% | <i>\$2,357.21</i> |
| EWP Premier TAC OS H34732 | 98000-H34732 | \$ 2,489.00 | 6% | <i>\$2,357.21</i> |
| EWP Premier TAC OS H34733 | 98000-H34733 | \$ 2,489.00 | 6% | <i>\$2,357.21</i> |
| EWP Premier TAC OS H34734 | 98000-H34734 | \$ 351.00 | 6% | <i>\$332.41</i> |
| EWP Premier TAC OS H34735 | 98000-H34735 | \$ 351.00 | 6% | <i>\$332.41</i> |
| EWP Premier TAC OS H34736 | 98000-H34736 | \$ 446.00 | 6% | <i>\$422.38</i> |
| EWP Premier TAC OS H34737 | 98000-H34737 | \$ 446.00 | 6% | <i>\$422.38</i> |
| EWP Premier TAC OS H34738 | 98000-H34738 | \$ 842.00 | 6% | <i>\$797.42</i> |
| EWP Premier TAC OS H34739 | 98000-H34739 | \$ 842.00 | 6% | <i>\$797.42</i> |
| EWP Premier TAC OS H34740 | 98000-H34740 | \$ 362.00 | 6% | <i>\$342.83</i> |
| EWP Premier TAC OS H34741 | 98000-H34741 | \$ 362.00 | 6% | <i>\$342.83</i> |
| EWP Premier TAC OS H34742 | 98000-H34742 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier TAC OS H34743 | 98000-H34743 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier TAC OS H34744 | 98000-H34744 | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier TAC OS H34745 | 98000-H34745 | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier TAC OS H34746 | 98000-H34746 | \$ 525.00 | 6% | <i>\$497.20</i> |
| EWP Premier TAC OS H34747 | 98000-H34747 | \$ 525.00 | 6% | <i>\$497.20</i> |
| EWP Premier TAC OS H34748 | 98000-H34748 | \$ 873.00 | 6% | <i>\$826.77</i> |
| EWP Premier TAC OS H34749 | 98000-H34749 | \$ 842.00 | 6% | <i>\$797.42</i> |
| EWP Premier TAC OS H34750 | 98000-H34750 | \$ 873.00 | 6% | <i>\$826.77</i> |
| EWP Premier TAC OS H34751 | 98000-H34751 | \$ 873.00 | 6% | <i>\$826.77</i> |
| EWP Premier TAC OS H34752 | 98000-H34752 | \$ 873.00 | 6% | <i>\$826.77</i> |
| EWP Premier TAC OS H34753 | 98000-H34753 | \$ 842.00 | 6% | <i>\$797.42</i> |
| EWP Premier TAC OS H34754 | 98000-H34754 | \$ 873.00 | 6% | <i>\$826.77</i> |
| EWP Premier TAC OS H34755 | 98000-H34755 | \$ 873.00 | 6% | <i>\$826.77</i> |
| EWP Premier TAC OS H34756 | 98000-H34756 | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier TAC OS H34757 | 98000-H34757 | \$ 446.00 | 6% | <i>\$422.38</i> |
| EWP Premier TAC OS H34758 | 98000-H34758 | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier TAC OS H34759 | 98000-H34759 | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier TAC OS H34760 | 98000-H34760 | \$ 463.00 | 6% | <i>\$438.48</i> |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS H34761 | 98000-H34761 | \$ 463.00 | 6% | \$438.48 |
| EWP Premier TAC OS H34993 | 98000-H34993 | \$ 9,830.00 | 6% | \$9,309.50 |
| EWP Premier TAC OS H34994 | 98000-H34994 | \$ 9,830.00 | 6% | \$9,309.50 |
| EWP Premier TAC OS H34996 | 98000-H34996 | \$ 9,830.00 | 6% | \$9,309.50 |
| EWP Premier TAC OS H34997 | 98000-H34997 | \$ 9,830.00 | 6% | \$9,309.50 |
| EWP Premier TAC OS H35005 | 98000-H35005 | \$ 6,313.00 | 6% | \$5,978.73 |
| EWP Premier TAC OS H35006 | 98000-H35006 | \$ 6,313.00 | 6% | \$5,978.73 |
| EWP Premier TAC OS H35012 | 98000-H35012 | \$ 3,785.00 | 6% | \$3,584.58 |
| EWP Premier TAC OS H35070 | 98000-H35070 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35071 | 98000-H35071 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35072 | 98000-H35072 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35073 | 98000-H35073 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35074 | 98000-H35074 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35075 | 98000-H35075 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35076 | 98000-H35076 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35077 | 98000-H35077 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35078 | 98000-H35078 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35079 | 98000-H35079 | \$ 41.00 | 6% | \$38.83 |
| EWP Premier TAC OS H35080 | 98000-H35080 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H35081 | 98000-H35081 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H35082 | 98000-H35082 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H35083 | 98000-H35083 | \$ 61.00 | 6% | \$57.77 |
| EWP Premier TAC OS H35270 | 98000-H35270 | \$ 312.00 | 6% | \$295.48 |
| EWP Premier TAC OS H35271 | 98000-H35271 | \$ 233.00 | 6% | \$220.66 |
| EWP Premier TAC OS H35272 | 98000-H35272 | \$ 213.00 | 6% | \$201.72 |
| EWP Premier TAC OS H35273 | 98000-H35273 | \$ 213.00 | 6% | \$201.72 |
| EWP Premier TAC OS H35274 | 98000-H35274 | \$ 506.00 | 6% | \$479.21 |
| EWP Premier TAC OS H35275 | 98000-H35275 | \$ 350.00 | 6% | \$331.47 |
| EWP Premier TAC OS H35276 | 98000-H35276 | \$ 2,230.00 | 6% | \$2,111.92 |
| EWP Premier TAC OS H35277 | 98000-H35277 | \$ 2,795.00 | 6% | \$2,647.00 |
| EWP Premier TAC OS H35278 | 98000-H35278 | \$ 1,796.00 | 6% | \$1,700.90 |
| EWP Premier TAC OS H35279 | 98000-H35279 | \$ 2,021.00 | 6% | \$1,913.99 |
| EWP Premier TAC OS H35280 | 98000-H35280 | \$ 2,903.00 | 6% | \$2,749.29 |
| EWP Premier TAC OS H35281 | 98000-H35281 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35282 | 98000-H35282 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35283 | 98000-H35283 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35284 | 98000-H35284 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35285 | 98000-H35285 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35286 | 98000-H35286 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35287 | 98000-H35287 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35288 | 98000-H35288 | \$ 1,404.00 | 6% | \$1,329.66 |
| EWP Premier TAC OS H35289 | 98000-H35289 | \$ 3,511.00 | 6% | \$3,325.09 |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| EWP Premier TAC OS H35291 | 98000-H35291 | \$ 2,528.00 | 6% | <i>\$2,394.14</i> |
| EWP Premier TAC OS H35294 | 98000-H35294 | \$ 805.00 | 6% | <i>\$762.38</i> |
| EWP Premier TAC OS H35295 | 98000-H35295 | \$ 272.00 | 6% | <i>\$257.60</i> |
| EWP Premier TAC OS H35296 | 98000-H35296 | \$ 5,709.00 | 6% | <i>\$5,406.71</i> |
| EWP Premier TAC OS H35297 | 98000-H35297 | \$ 5,709.00 | 6% | <i>\$5,406.71</i> |
| EWP Premier TAC OS H35298 | 98000-H35298 | \$ 9,172.00 | 6% | <i>\$8,686.34</i> |
| EWP Premier TAC OS H35299 | 98000-H35299 | \$ 9,172.00 | 6% | <i>\$8,686.34</i> |
| EWP Premier TAC OS H35300 | 98000-H35300 | \$ 1,409.00 | 6% | <i>\$1,334.39</i> |
| EWP Premier TAC OS H35301 | 98000-H35301 | \$ 636.00 | 6% | <i>\$602.32</i> |
| EWP Premier TAC OS H35302 | 98000-H35302 | \$ 2,185.00 | 6% | <i>\$2,069.30</i> |
| EWP Premier TAC OS H35303 | 98000-H35303 | \$ 2,185.00 | 6% | <i>\$2,069.30</i> |
| EWP Premier TAC OS H35304 | 98000-H35304 | \$ 2,185.00 | 6% | <i>\$2,069.30</i> |
| EWP Premier TAC OS H35305 | 98000-H35305 | \$ 2,292.00 | 6% | <i>\$2,170.64</i> |
| EWP Premier TAC OS H35306 | 98000-H35306 | \$ 2,292.00 | 6% | <i>\$2,170.64</i> |
| EWP Premier TAC OS H35307 | 98000-H35307 | \$ 2,292.00 | 6% | <i>\$2,170.64</i> |
| EWP Premier TAC OS H35308 | 98000-H35308 | \$ 531.00 | 6% | <i>\$502.88</i> |
| EWP Premier TAC OS H35309 | 98000-H35309 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier TAC OS H35310 | 98000-H35310 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier TAC OS H35311 | 98000-H35311 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier TAC OS H35312 | 98000-H35312 | \$ 2,345.00 | 6% | <i>\$2,220.83</i> |
| EWP Premier TAC OS H35313 | 98000-H35313 | \$ 2,345.00 | 6% | <i>\$2,220.83</i> |
| EWP Premier TAC OS H35314 | 98000-H35314 | \$ 2,345.00 | 6% | <i>\$2,220.83</i> |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| EWP Premier TAC OS H35315 | 98000-H35315 | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| EWP Premier TAC OS H35316 | 98000-H35316 | \$ 170.00 | 6% | <i>\$161.00</i> |
| EWP Premier TAC OS H35317 | 98000-H35317 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier TAC OS H35318 | 98000-H35318 | \$ 490.00 | 6% | <i>\$464.05</i> |
| EWP Premier TAC OS H35319 | 98000-H35319 | \$ 662.00 | 6% | <i>\$626.95</i> |
| EWP Premier TAC OS H35320 | 98000-H35320 | \$ 686.00 | 6% | <i>\$649.68</i> |
| EWP Premier TAC OS H35321 | 98000-H35321 | \$ 874.00 | 6% | <i>\$827.72</i> |
| EWP Premier TAC OS H35322 | 98000-H35322 | \$ 1,058.00 | 6% | <i>\$1,001.98</i> |
| EWP Premier TAC OS H35323 | 98000-H35323 | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| EWP Premier TAC OS H35328 | 98000-H35328 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier TAC OS H35330 | 98000-H35330 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier TAC OS H35340 | 98000-H35340 | \$ 1,830.00 | 6% | <i>\$1,733.10</i> |
| EWP Premier TAC OS H35341 | 98000-H35341 | \$ 1,830.00 | 6% | <i>\$1,733.10</i> |
| EWP Premier TAC OS H35342 | 98000-H35342 | \$ 1,659.00 | 6% | <i>\$1,571.16</i> |
| EWP Premier TAC OS H35343 | 98000-H35343 | \$ 1,830.00 | 6% | <i>\$1,733.10</i> |
| EWP Premier TAC OS H35344 | 98000-H35344 | \$ 1,914.00 | 6% | <i>\$1,812.65</i> |
| EWP Premier TAC OS H35345 | 98000-H35345 | \$ 1,914.00 | 6% | <i>\$1,812.65</i> |
| EWP Premier TAC OS H35346 | 98000-H35346 | \$ 1,717.00 | 6% | <i>\$1,626.08</i> |
| EWP Premier TAC OS H35347 | 98000-H35347 | \$ 1,914.00 | 6% | <i>\$1,812.65</i> |
| EWP Premier TAC OS H35348 | 98000-H35348 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier TAC OS H35349 | 98000-H35349 | \$ 2,107.00 | 6% | <i>\$1,995.43</i> |
| EWP Premier TAC OS H35350 | 98000-H35350 | \$ 2,107.00 | 6% | <i>\$1,995.43</i> |
| EWP Premier TAC OS H35351 | 98000-H35351 | \$ 1,883.00 | 6% | <i>\$1,783.30</i> |
| EWP Premier TAC OS H35352 | 98000-H35352 | \$ 2,107.00 | 6% | <i>\$1,995.43</i> |
| EWP Premier TAC OS H35353 | 98000-H35353 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier TAC OS H35357 | 98000-H35357 | \$ 231.00 | 6% | <i>\$218.77</i> |
| EWP Premier TAC OS H35358 | 98000-H35358 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier TAC OS H35359 | 98000-H35359 | \$ 874.00 | 6% | <i>\$827.72</i> |
| EWP Premier TAC OS H35360 | 98000-H35360 | \$ 1,058.00 | 6% | <i>\$1,001.98</i> |
| EWP Premier TAC OS H35361 | 98000-H35361 | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| EWP Premier TAC OS H35362 | 98000-H35362 | \$ 490.00 | 6% | <i>\$464.05</i> |

| | | | | |
|---------------------------|--------------|-------------|----|------------|
| EWP Premier TAC OS H35366 | 98000-H35366 | \$ 922.00 | 6% | \$873.18 |
| EWP Premier TAC OS H35367 | 98000-H35367 | \$ 1,075.00 | 6% | \$1,018.08 |
| EWP Premier TAC OS H35368 | 98000-H35368 | \$ 1,637.00 | 6% | \$1,550.32 |
| EWP Premier TAC OS H35369 | 98000-H35369 | \$ 533.00 | 6% | \$504.78 |
| EWP Premier TAC OS H35370 | 98000-H35370 | \$ 749.00 | 6% | \$709.34 |
| EWP Premier TAC OS H35371 | 98000-H35371 | \$ 214.00 | 6% | \$202.67 |
| EWP Premier TAC OS H35374 | 98000-H35374 | \$ 242.00 | 6% | \$229.19 |
| EWP Premier TAC OS H35375 | 98000-H35375 | \$ 458.00 | 6% | \$433.75 |
| EWP Premier TAC OS H35376 | 98000-H35376 | \$ 684.00 | 6% | \$647.78 |
| EWP Premier TAC OS H35377 | 98000-H35377 | \$ 284.00 | 6% | \$268.96 |
| EWP Premier TAC OS H35378 | 98000-H35378 | \$ 458.00 | 6% | \$433.75 |
| EWP Premier TAC OS H35379 | 98000-H35379 | \$ 284.00 | 6% | \$268.96 |
| EWP Premier TAC OS H35380 | 98000-H35380 | \$ 509.00 | 6% | \$482.05 |
| EWP Premier TAC OS H35381 | 98000-H35381 | \$ 625.00 | 6% | \$591.91 |
| EWP Premier TAC OS H35384 | 98000-H35384 | \$ 206.00 | 6% | \$195.09 |
| EWP Premier TAC OS H35385 | 98000-H35385 | \$ 278.00 | 6% | \$263.28 |
| EWP Premier TAC OS H35386 | 98000-H35386 | \$ 458.00 | 6% | \$433.75 |
| EWP Premier TAC OS H35387 | 98000-H35387 | \$ 419.00 | 6% | \$396.81 |
| EWP Premier TAC OS H35388 | 98000-H35388 | \$ 316.00 | 6% | \$299.27 |
| EWP Premier TAC OS H35389 | 98000-H35389 | \$ 171.00 | 6% | \$161.95 |
| EWP Premier TAC OS H35390 | 98000-H35390 | \$ 148.00 | 6% | \$140.16 |
| EWP Premier TAC OS H35391 | 98000-H35391 | \$ 331.00 | 6% | \$313.47 |
| EWP Premier TAC OS H35392 | 98000-H35392 | \$ 509.00 | 6% | \$482.05 |
| EWP Premier TAC OS H35393 | 98000-H35393 | \$ 684.00 | 6% | \$647.78 |
| EWP Premier TAC OS H35394 | 98000-H35394 | \$ 123.00 | 6% | \$116.49 |
| EWP Premier TAC OS H35395 | 98000-H35395 | \$ 104.00 | 6% | \$98.49 |
| EWP Premier TAC OS H35396 | 98000-H35396 | \$ 123.00 | 6% | \$116.49 |
| EWP Premier TAC OS H35397 | 98000-H35397 | \$ 104.00 | 6% | \$98.49 |
| EWP Premier TAC OS H35398 | 98000-H35398 | \$ 323.00 | 6% | \$305.90 |
| EWP Premier TAC OS H35399 | 98000-H35399 | \$ 387.00 | 6% | \$366.51 |
| EWP Premier TAC OS H35400 | 98000-H35400 | \$ 425.00 | 6% | \$402.50 |
| EWP Premier TAC OS H35401 | 98000-H35401 | \$ 233.00 | 6% | \$220.66 |
| EWP Premier TAC OS H35404 | 98000-H35404 | \$ 101.00 | 6% | \$95.65 |
| EWP Premier TAC OS H35405 | 98000-H35405 | \$ 242.00 | 6% | \$229.19 |
| EWP Premier TAC OS H35406 | 98000-H35406 | \$ 29.00 | 6% | \$27.46 |
| EWP Premier TAC OS H35407 | 98000-H35407 | \$ 206.00 | 6% | \$195.09 |
| EWP Premier TAC OS H35408 | 98000-H35408 | \$ 301.00 | 6% | \$285.06 |
| EWP Premier TAC OS H35409 | 98000-H35409 | \$ 29.00 | 6% | \$27.46 |
| EWP Premier TAC OS H35415 | 98000-H35415 | \$ 149.00 | 6% | \$141.11 |
| EWP Premier TAC OS H35416 | 98000-H35416 | \$ 149.00 | 6% | \$141.11 |
| EWP Premier TAC OS H35424 | 98000-H35424 | \$ 548.00 | 6% | \$518.98 |
| EWP Premier TAC OS H35426 | 98000-H35426 | \$ 171.00 | 6% | \$161.95 |

| | | | | |
|---------------------------|--------------|-------------|----|-------------------|
| EWP Premier TAC OS H35427 | 98000-H35427 | \$ 419.00 | 6% | <i>\$396.81</i> |
| EWP Premier TAC OS H35428 | 98000-H35428 | \$ 148.00 | 6% | <i>\$140.16</i> |
| EWP Premier TAC OS H35429 | 98000-H35429 | \$ 331.00 | 6% | <i>\$313.47</i> |
| EWP Premier TAC OS H35430 | 98000-H35430 | \$ 334.00 | 6% | <i>\$316.31</i> |
| EWP Premier TAC OS H35431 | 98000-H35431 | \$ 334.00 | 6% | <i>\$316.31</i> |
| EWP Premier TAC OS H35432 | 98000-H35432 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier TAC OS H35433 | 98000-H35433 | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWP Premier TAC OS H35434 | 98000-H35434 | \$ 482.00 | 6% | <i>\$456.48</i> |
| EWP Premier TAC OS H35435 | 98000-H35435 | \$ 482.00 | 6% | <i>\$456.48</i> |
| EWP Premier TAC OS H35436 | 98000-H35436 | \$ 802.00 | 6% | <i>\$759.53</i> |
| EWP Premier TAC OS H35437 | 98000-H35437 | \$ 802.00 | 6% | <i>\$759.53</i> |
| EWP Premier TAC OS H35438 | 98000-H35438 | \$ 802.00 | 6% | <i>\$759.53</i> |
| EWP Premier TAC OS H35439 | 98000-H35439 | \$ 802.00 | 6% | <i>\$759.53</i> |
| EWP Premier TAC OS H35440 | 98000-H35440 | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWP Premier TAC OS H35441 | 98000-H35441 | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWP Premier TAC OS H35442 | 98000-H35442 | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWP Premier TAC OS H35443 | 98000-H35443 | \$ 2,328.00 | 6% | <i>\$2,204.73</i> |
| EWP Premier TAC OS H35444 | 98000-H35444 | \$ 2,489.00 | 6% | <i>\$2,357.21</i> |
| EWP Premier TAC OS H35445 | 98000-H35445 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H35446 | 98000-H35446 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWP Premier TAC OS H35447 | 98000-H35447 | \$ 2,662.00 | 6% | <i>\$2,521.05</i> |
| EWP Premier TAC OS H35448 | 98000-H35448 | \$ 2,465.00 | 6% | <i>\$2,334.48</i> |
| EWP Premier TAC OS H35449 | 98000-H35449 | \$ 1,796.00 | 6% | <i>\$1,700.90</i> |
| EWP Premier TAC OS H35450 | 98000-H35450 | \$ 1,925.00 | 6% | <i>\$1,823.07</i> |
| EWP Premier TAC OS H35451 | 98000-H35451 | \$ 3,222.00 | 6% | <i>\$3,051.40</i> |
| EWP Premier TAC OS H35452 | 98000-H35452 | \$ 3,222.00 | 6% | <i>\$3,051.40</i> |
| EWP Premier TAC OS H35453 | 98000-H35453 | \$ 2,489.00 | 6% | <i>\$2,357.21</i> |
| EWP Premier TAC OS H35454 | 98000-H35454 | \$ 2,328.00 | 6% | <i>\$2,204.73</i> |
| EWP Premier TAC OS H35455 | 98000-H35455 | \$ 686.00 | 6% | <i>\$649.68</i> |
| EWP Premier TAC OS H35456 | 98000-H35456 | \$ 819.00 | 6% | <i>\$775.63</i> |
| EWP Premier TAC OS H35457 | 98000-H35457 | \$ 759.00 | 6% | <i>\$718.81</i> |
| EWP Premier TAC OS H35458 | 98000-H35458 | \$ 830.00 | 6% | <i>\$786.05</i> |
| EWP Premier TAC OS H35471 | 98000-H35471 | \$ 686.00 | 6% | <i>\$649.68</i> |
| EWP Premier TAC OS H35600 | 98000-H35600 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier TAC OS H35601 | 98000-H35601 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier TAC OS H35602 | 98000-H35602 | \$ 362.00 | 6% | <i>\$342.83</i> |
| EWP Premier TAC OS H35603 | 98000-H35603 | \$ 362.00 | 6% | <i>\$342.83</i> |
| EWP Premier TAC OS H35604 | 98000-H35604 | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier TAC OS H35605 | 98000-H35605 | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier TAC OS H35606 | 98000-H35606 | \$ 506.00 | 6% | <i>\$479.21</i> |
| EWP Premier TAC OS H35607 | 98000-H35607 | \$ 525.00 | 6% | <i>\$497.20</i> |

| | | | | |
|----------------------------------|---------------------|--------------|----|-------------|
| EWP Premier TAC OS ISW-24W-4X | 98000-ISW-24W-4X | \$ 666.00 | 6% | \$630.74 |
| EWP Premier TAC OS ISW-4W-4WS-4X | 98000-ISW-4W-4WS-4X | \$ 424.00 | 6% | \$401.55 |
| EWP Premier TAC OS MSM128 | 98000-MSM128 | \$ 2,174.00 | 6% | \$2,058.89 |
| EWP Premier TAC OS MSM48C | 98000-MSM48C | \$ 1,293.00 | 6% | \$1,224.54 |
| EWP Premier TAC OS S22027 | 98000-S22027 | \$ 952.00 | 6% | \$901.59 |
| EWP Premier TAC OS S22028 | 98000-S22028 | \$ 908.00 | 6% | \$859.92 |
| EWP Premier TAC OS S22030 | 98000-S22030 | \$ 550.00 | 6% | \$520.88 |
| EWP Premier TAC OS S22031 | 98000-S22031 | \$ 1,096.00 | 6% | \$1,037.97 |
| EWP Premier TAC OS S22032 | 98000-S22032 | \$ 550.00 | 6% | \$520.88 |
| EWP Premier TAC OS S22035 | 98000-S22035 | \$ 551.00 | 6% | \$521.82 |
| EWP Premier TAC OS S22036 | 98000-S22036 | \$ 526.00 | 6% | \$498.15 |
| EWP Premier TAC OS S22037 | 98000-S22037 | \$ 803.00 | 6% | \$760.48 |
| EWP Premier TAC OS S22038 | 98000-S22038 | \$ 803.00 | 6% | \$760.48 |
| EWP Premier TAC OS S22039 | 98000-S22039 | \$ 803.00 | 6% | \$760.48 |
| EWP Premier TAC OS S22040 | 98000-S22040 | \$ 769.00 | 6% | \$728.28 |
| EWP Premier TAC OS S22041 | 98000-S22041 | \$ 734.00 | 6% | \$695.13 |
| EWP Premier TAC OS S22042 | 98000-S22042 | \$ 1,191.00 | 6% | \$1,127.94 |
| EWP Premier TAC OS S22044 | 98000-S22044 | \$ 305.00 | 6% | \$288.85 |
| EWP Premier TAC OS S22045 | 98000-S22045 | \$ 283.00 | 6% | \$268.02 |
| EWP Premier TAC OS S22046 | 98000-S22046 | \$ 690.00 | 6% | \$653.46 |
| EWP Premier TAC OS S22047 | 98000-S22047 | \$ 659.00 | 6% | \$624.11 |
| EWP Premier TAC OS S22055 | 98000-S22055 | \$ 1,008.00 | 6% | \$954.63 |
| EWP Premier TAC OS S22057 | 98000-S22057 | \$ 2,779.00 | 6% | \$2,631.85 |
| EWP Premier TAC OS S22072 | 98000-S22072 | \$ 1,201.00 | 6% | \$1,137.41 |
| EWP Premier TAC OS S22073 | 98000-S22073 | \$ 1,201.00 | 6% | \$1,137.41 |
| EWP Premier TAC OS S22074 | 98000-S22074 | \$ 182.00 | 6% | \$172.36 |
| EWP Premier TAC OS S22075 | 98000-S22075 | \$ 1,037.00 | 6% | \$982.09 |
| EWP Premier TAC OS S22117 | 98000-S22117 | \$ 803.00 | 6% | \$760.48 |
| EWP Premier TAC OS S22119 | 98000-S22119 | \$ 2,002.00 | 6% | \$1,895.99 |
| EWP Premier TAC OS S22123 | 98000-S22123 | \$ 112.00 | 6% | \$106.07 |
| EWP Premier TAC OS S22124 | 98000-S22124 | \$ 237.00 | 6% | \$224.45 |
| EWP Premier TAC OS S22144 | 98000-S22144 | \$ 3,471.00 | 6% | \$3,287.21 |
| EWP Premier TAC OS S22145 | 98000-S22145 | \$ 6,937.00 | 6% | \$6,569.69 |
| EWP Premier TAC OS S22146 | 98000-S22146 | \$ 17,327.00 | 6% | \$16,409.54 |
| EWP Premier TAC OS S22147 | 98000-S22147 | \$ 34,687.00 | 6% | \$32,850.32 |
| EWP Premier TAC OS S22148 | 98000-S22148 | \$ 325.00 | 6% | \$307.79 |
| EWP Premier TAC OS S22149 | 98000-S22149 | \$ 1,610.00 | 6% | \$1,524.75 |
| EWP Premier TAC OS S22150 | 98000-S22150 | \$ 18.00 | 6% | \$17.05 |

| | | | | |
|---|---------------------------------|--------------|-----|-------------|
| EW Software and TAC S22179 | 98000-S22179 | \$ 2,807.00 | 6% | \$2,658.37 |
| EW Software and TAC S22180 | 98000-S22180 | \$ 2,844.00 | 6% | \$2,693.41 |
| EWP Premier TAC OS S22181 | 98000-S22181 | \$ 62,400.00 | 6% | \$59,095.92 |
| EWP Premier TAC OS S22182 | 98000-S22182 | \$ 12,480.00 | 6% | \$11,819.18 |
| EWP Premier TAC OS SLX9150-48XT-DC-F | 98000- SLX9150- 48XT-DC-F | \$ 1,662.00 | 6% | \$1,574.00 |
| EWP Premier TAC OS SLX9150-48XT-DC-R | 98000- SLX9150- 48XT-DC-R | \$ 1,832.00 | 6% | \$1,735.00 |
| EWP Premier TAC OS SLX9150-48Y-DC-F | 98000- SLX9150-48Y- DC-F | \$ 1,589.00 | 6% | \$1,504.86 |
| EWP Premier TAC OS SLX9150-48Y-DC-R | 98000- SLX9150-48Y- DC-R | \$ 1,751.00 | 6% | \$1,658.28 |
| EWP Premier TAC OS SLX9740-40C | 98000- SLX9740-40C | \$ 9,763.00 | 6% | \$9,246.05 |
| EWP Premier TAC OS SLX9740-40C-AC-F | 98000- SLX9740-40C- AC-F | \$ 9,763.00 | 6% | \$9,246.05 |
| EWP Premier TAC OS SLX9740-40C-AC-R | 98000- SLX9740-40C- AC-R | \$ 9,763.00 | 10% | \$8,852.60 |
| EWP Premier TAC OS SLX9740-40C-DC-F | 98000- SLX9740-40C- DC-F | \$ 9,763.00 | 6% | \$9,246.05 |
| EWP Premier TAC OS SLX9740-80C | 98000- SLX9740-80C | \$ 14,595.00 | 6% | \$13,822.19 |
| EWP Premier TAC OS SLX9740-80C-AC-F | 98000- SLX9740-80C- AC-F | \$ 14,595.00 | 6% | \$13,822.19 |
| EWP Premier TAC OS SLX9740-80C-AC-R | 98000- SLX9740-80C- AC-R | \$ 14,595.00 | 10% | \$13,234.02 |
| EWP Premier TAC OS SLX9740-80C-DC-F | 98000- SLX9740-80C- DC-F | \$ 14,595.00 | 6% | \$13,822.19 |
| EWP Premier TAC OS SLX9740-ADV-LIC-P | 98000- SLX9740- ADV-LIC-P | \$ 1,753.00 | 6% | \$1,660.18 |
| EWP Premier TAC OS V300-8P- 2X | 98000-V300- 8P-2X | \$ 116.00 | 6% | \$109.86 |

| | | | | |
|---------------------------------------|-----------------------------|-----------|----|-----------------|
| EWP Premier TAC OS V300-8T-2X | 98000-V300-8T-2X | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier TAC OS V300HT-8P-2X | 98000-V300HT-8P-2X | \$ 269.00 | 6% | <i>\$254.76</i> |
| EWP Premier TAC OS V300HT-8T-2X | 98000-V300HT-8T-2X | \$ 162.00 | 6% | <i>\$153.42</i> |
| EWP Premier TAC OS VIM-SS | 98000-VIM-SS | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier TAC OS VIM-SSV80 | 98000-VIM-SSV80 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier TAC OS VIM2-SS | 98000-VIM2-SS | \$ 137.00 | 6% | <i>\$129.75</i> |
| EWPPremier TAC OS VIM2-SS128 | 98000-VIM2-SS128 | \$ 448.00 | 6% | <i>\$424.28</i> |
| EWP Premier TAC OS VIM2-V80 | 98000-VIM2-V80 | \$ 480.00 | 6% | <i>\$454.58</i> |
| EWP Premier TAC OS VIM210G4X | 98000-VIM210G4X | \$ 833.00 | 6% | <i>\$788.89</i> |
| EWP Premier TAC OS VIM5-2Q | 98000-VIM5-2Q | \$ 150.00 | 6% | <i>\$142.06</i> |
| EWP Premier TAC OS VIM5-2Y | 98000-VIM5-2Y | \$ 171.00 | 6% | <i>\$161.95</i> |
| EWP Premier TAC OS VIM5-4X | 98000-VIM5-4X | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier TAC OS VIM5-4XE | 98000-VIM5-4XE | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier TAC OS VIM5-4Y | 98000-VIM5-4Y | \$ 219.00 | 6% | <i>\$207.40</i> |
| EWP Premier TAC OS VIM5-4YE | 98000-VIM5-4YE | \$ 290.00 | 6% | <i>\$274.64</i> |
| EWP Prem TAC OS VSP4900-12MXU-12XE | 98000-VSP4900-12MXU-12XE | \$ 917.00 | 6% | <i>\$868.44</i> |
| EWP Prem TAC OS VSP4900-12MXU-12XE-B1 | 98000-VSP4900-12MXU-12XE-B1 | \$ 917.00 | 6% | <i>\$868.44</i> |
| EWP Premier TAC OS VSP4900-24S | 98000-VSP4900-24S | \$ 490.00 | 6% | <i>\$464.05</i> |

| | | | | |
|---------------------------------------|-------------------------------|-------------|----|------------|
| EWP Premier TAC OS VSP4900-24S-B3 | 98000- VSP4900-24S- B3 | \$ 490.00 | 6% | \$464.05 |
| EWP Premier TAC OS VSP4900-24XE | 98000- VSP4900- 24XE | \$ 917.00 | 6% | \$868.44 |
| EWP Premier TAC OS VSP4900-24XE-B3 | 98000- VSP4900- 24XE-B3 | \$ 917.00 | 6% | \$868.44 |
| EWP Premier TAC OS X435- 24P-4S | 98000-X435- 24P-4S | \$ 202.00 | 6% | \$191.30 |
| EWP Premier TAC OS X435- 24T-4S | 98000-X435- 24T-4S | \$ 109.00 | 6% | \$103.23 |
| EWP Premier TAC OS X435-8P- 2T-W | 98000-X435- 8P-2T-W | \$ 109.00 | 6% | \$103.23 |
| EWP Premier TAC OS X435-8P- 4S | 98000-X435- 8P-4S | \$ 101.00 | 6% | \$95.65 |
| EWP Premier TAC OS X435-8T- 4S | 98000-X435- 8T-4S | \$ 80.00 | 6% | \$75.76 |
| EWP Premier TAC OS X460- 24P | 98000-X460- 24P | \$ 743.00 | 6% | \$703.66 |
| EWP Premier TAC OS X460- 24T | 98000-X460- 24T | \$ 531.00 | 6% | \$502.88 |
| EWPPremier TAC OS X460- 24TDC | 98000-X460- 24TDC | \$ 779.00 | 6% | \$737.75 |
| EWP Premier TAC OS X460- 24X | 98000-X460- 24X | \$ 989.00 | 6% | \$936.63 |
| EWPPremier TAC OS X460- 24XDC | 98000-X460- 24XDC | \$ 1,106.00 | 6% | \$1,047.44 |
| EWP Premier TAC OS X460- 48P | 98000-X460- 48P | \$ 989.00 | 6% | \$936.63 |
| EWP Premier TAC OS X460- 48T | 98000-X460- 48T | \$ 850.00 | 6% | \$804.99 |
| EWPPremier TAC OS X460- 48TDC | 98000-X460- 48TDC | \$ 1,077.00 | 6% | \$1,019.97 |
| EWP Premier TAC OS X460- 48X | 98000-X460- 48X | \$ 1,326.00 | 6% | \$1,255.79 |
| EWPPremier TAC OS X460- 48XDC | 98000-X460- 48XDC | \$ 1,280.00 | 6% | \$1,212.22 |
| EWP Premier TAC OS X460CORE | 98000- X460CORE | \$ 307.00 | 6% | \$290.74 |

| | | | | |
|------------------------------------|-----------------------|-------------|----|-------------------|
| EWP Premier TAC OS X460MPLS | 98000-X460MPLS | \$ 201.00 | 6% | <i>\$190.36</i> |
| EWP Premier TAC OS X460NS | 98000-X460NS | \$ 237.00 | 6% | <i>\$224.45</i> |
| EWP Premier TAC OS X465-24MU | 98000-X465-24MU | \$ 1,058.00 | 6% | <i>\$1,001.98</i> |
| EWP Premier TAC OS X465-24S | 98000-X465-24S | \$ 490.00 | 6% | <i>\$464.05</i> |
| EWP Premier TAC OS X465-24S-B3 | 98000-X465-24S-B3 | \$ 490.00 | 6% | <i>\$464.05</i> |
| EWP Premier TAC OS X465-24W | 98000-X465-24W | \$ 490.00 | 6% | <i>\$464.05</i> |
| EWP Premier TAC OS X465-24XE | 98000-X465-24XE | \$ 917.00 | 6% | <i>\$868.44</i> |
| EWP Premier TAC OS X465-24XE-B3 | 98000-X465-24XE-B3 | \$ 917.00 | 6% | <i>\$868.44</i> |
| EWP Premier TAC OS X465-48P | 98000-X465-48P | \$ 686.00 | 6% | <i>\$649.68</i> |
| EWP Premier TAC OS X465-48T | 98000-X465-48T | \$ 662.00 | 6% | <i>\$626.95</i> |
| EWP Premier TAC OS X465-48W | 98000-X465-48W | \$ 874.00 | 6% | <i>\$827.72</i> |
| EWP Premier TAC OS X465i-48W | 98000-X465i-48W | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| EWP Premier TAC OS X465i-48W-B1-S1 | 98000-X465i-48W-B1-S1 | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| EWP Premier TAC OS X465i-48W-B2-S1 | 98000-X465i-48W-B2-S1 | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| EWP Premier TAC OS X480-24X | 98000-X480-24X | \$ 1,242.00 | 6% | <i>\$1,176.24</i> |
| EWP Premier TAC OS X480-48T | 98000-X480-48T | \$ 1,242.00 | 6% | <i>\$1,176.24</i> |
| EWP Premier TAC OS X480-48X | 98000-X480-48X | \$ 1,652.00 | 6% | <i>\$1,564.53</i> |
| EWP Premier TAC OS X480CORE | 98000-X480CORE | \$ 560.00 | 6% | <i>\$530.35</i> |
| EWP Premier TAC OS X480MPLS | 98000-X480MPLS | \$ 293.00 | 6% | <i>\$277.49</i> |
| EWP Premier TAC OS X695-48Y-8C | 98000-X695-48Y-8C | \$ 2,390.00 | 6% | <i>\$2,263.45</i> |
| EWP Premier TAC OS XGM3-2SF | 98000-XGM3-2SF | \$ 210.00 | 6% | <i>\$198.88</i> |

| | | | | |
|------------------------------------|--------------|---------------|----|---------------------|
| EWP Premier TAC OS XR600 | 98000-XR600 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier TAC OS ZR-XFP | 98000-ZR-XFP | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWP Premier SOFTWARE SUPPORT 30313 | 98003-30313 | \$ 678.00 | 6% | <i>\$642.10</i> |
| EWP Premier SOFTWARE SUPPORT 30314 | 98003-30314 | \$ 697.00 | 6% | <i>\$660.09</i> |
| EWP Premier SOFTWARE SUPPORT 30316 | 98003-30316 | \$ 697.00 | 6% | <i>\$660.09</i> |
| EWP Premier SOFTWARE SUPPORT 30324 | 98003-30324 | \$ 660.00 | 6% | <i>\$625.05</i> |
| EWP Premier SOFTWARE SUPPORT 30326 | 98003-30326 | \$ 660.00 | 6% | <i>\$625.05</i> |
| EWP Premier SOFTWARE SUPPORT 30327 | 98003-30327 | \$ 504.00 | 6% | <i>\$477.31</i> |
| EWP Premier SOFTWARE SUPPORT 30328 | 98003-30328 | \$ 2,511.00 | 6% | <i>\$2,378.04</i> |
| EWP Premier SOFTWARE SUPPORT 30329 | 98003-30329 | \$ 10,035.00 | 6% | <i>\$9,503.65</i> |
| EWP Premier SOFTWARE SUPPORT 30330 | 98003-30330 | \$ 50,177.00 | 6% | <i>\$47,520.13</i> |
| EWP Premier SOFTWARE SUPPORT 30331 | 98003-30331 | \$ 200,704.00 | 6% | <i>\$190,076.72</i> |
| EWP Premier SOFTWARE SUPPORT 39521 | 98003-39521 | \$ 713.00 | 6% | <i>\$675.25</i> |
| EWP Premier SOFTWARE SUPPORT 39522 | 98003-39522 | \$ 7,125.00 | 6% | <i>\$6,747.73</i> |
| EWP Premier SOFTWARE SUPPORT 39523 | 98003-39523 | \$ 71,249.00 | 6% | <i>\$67,476.37</i> |
| EWP Premier SOFTWARE SUPPORT 39524 | 98003-39524 | \$ 356,246.00 | 6% | <i>\$337,382.77</i> |
| EWP Premier SOFTWARE SUPPORT 39525 | 98003-39525 | \$ 712,492.00 | 6% | <i>\$674,765.55</i> |
| EWP Premier SOFTWARE SUPPORT 48101 | 98003-48101 | \$ 7,832.00 | 6% | <i>\$7,417.30</i> |
| EWP Premier SOFTWARE SUPPORT 85108 | 98003-85108 | \$ 310.00 | 6% | <i>\$293.59</i> |
| EWP Premier SOFTWARE SUPPORT 85109 | 98003-85109 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier SOFTWARE SUPPORT 85110 | 98003-85110 | \$ 1,080.00 | 6% | <i>\$1,022.81</i> |

| | | | | |
|-------------------------------------|------------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT 85111 | 98003-85111 | \$ 1,853.00 | 6% | <i>\$1,754.88</i> |
| EWP Premier SOFTWARE SUPPORT 85112 | 98003-85112 | \$ 2,956.00 | 6% | <i>\$2,799.48</i> |
| EWP Premier SOFTWARE SUPPORT 85113 | 98003-85113 | \$ 4,927.00 | 6% | <i>\$4,666.12</i> |
| EWP Premier SOFTWARE SUPPORT 85114 | 98003-85114 | \$ 6,569.00 | 6% | <i>\$6,221.17</i> |
| EWP Premier SOFTWARE SUPPORT 85115 | 98003-85115 | \$ 310.00 | 6% | <i>\$293.59</i> |
| EWP Premier SOFTWARE SUPPORT 85116 | 98003-85116 | \$ 464.00 | 6% | <i>\$439.43</i> |
| EWP Premier SOFTWARE SUPPORT 85117 | 98003-85117 | \$ 770.00 | 6% | <i>\$729.23</i> |
| EWP Premier SOFTWARE SUPPORT 85118 | 98003-85118 | \$ 926.00 | 6% | <i>\$876.97</i> |
| EWP Premier SOFTWARE SUPPORT 85119 | 98003-85119 | \$ 1,851.00 | 6% | <i>\$1,752.99</i> |
| EWP Premier SOFTWARE SUPPORT 85120 | 98003-85120 | \$ 1,541.00 | 6% | <i>\$1,459.40</i> |
| EWP Premier SOFTWARE SUPPORT 88201 | 98003-88201 | \$ 2,766.00 | 6% | <i>\$2,619.54</i> |
| EWP Premier SOFTWARE SUPPORT 88202 | 98003-88202 | \$ 7,775.00 | 6% | <i>\$7,363.31</i> |
| EWP Premier SOFTWARE SUPPORT 88203 | 98003-88203 | \$ 29,379.00 | 6% | <i>\$27,823.38</i> |
| EWP Premier SOFTWARE SUPPORT 88211 | 98003-88211 | \$ 3,441.00 | 6% | <i>\$3,258.80</i> |
| EWP Premier SOFTWARE SUPPORT 88212 | 98003-88212 | \$ 6,569.00 | 6% | <i>\$6,221.17</i> |
| EWP Premier SOFTWARE SUPPORT 88213 | 98003-88213 | \$ 3,037.00 | 6% | <i>\$2,876.19</i> |
| EWP Premier SOFTWARE SUB EXTR-IQ-TC | 98003-EXTR-IQ-TC | \$ 390.00 | 6% | <i>\$369.35</i> |
| EWPPremier SOFTWARE SUPPORT NACVX5 | 98003-NAC-VX-5 | \$ 1,570.00 | 6% | <i>\$1,486.87</i> |
| EWP Premier SOFTWARE SUPPORT S20097 | 98003-S20097 | \$ 26,436.00 | 6% | <i>\$25,036.21</i> |
| EWP Premier SOFTWARE SUPPORT S20098 | 98003-S20098 | \$ 2,520.00 | 6% | <i>\$2,386.57</i> |
| EWP Premier SOFTWARE SUPPORT S20099 | 98003-S20099 | \$ 7,068.00 | 6% | <i>\$6,693.75</i> |

| | | | | |
|-------------------------------------|--------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S20100 | 98003-S20100 | \$ 12,086.00 | 6% | <i>\$11,446.05</i> |
| EWP Premier SOFTWARE SUPPORT S20101 | 98003-S20101 | \$ 3,130.00 | 6% | <i>\$2,964.27</i> |
| EWP Premier SOFTWARE SUPPORT S20112 | 98003-S20112 | \$ 2,520.00 | 6% | <i>\$2,386.57</i> |
| EWP Premier SOFTWARE SUPPORT S20113 | 98003-S20113 | \$ 12,086.00 | 6% | <i>\$11,446.05</i> |
| EWP Premier SOFTWARE SUPPORT S20114 | 98003-S20114 | \$ 4,744.00 | 6% | <i>\$4,492.81</i> |
| EWP Premier SOFTWARE SUPPORT S20116 | 98003-S20116 | \$ 3,888.00 | 6% | <i>\$3,682.13</i> |
| EWP Premier SOFTWARE SUPPORT S20117 | 98003-S20117 | \$ 1,411.00 | 6% | <i>\$1,336.29</i> |
| EWP Premier SOFTWARE SUPPORT S20119 | 98003-S20119 | \$ 964.00 | 6% | <i>\$912.96</i> |
| EWP Premier SOFTWARE SUPPORT S20120 | 98003-S20120 | \$ 5,693.00 | 6% | <i>\$5,391.56</i> |
| EWP Premier SOFTWARE SUPPORT S20121 | 98003-S20121 | \$ 17,215.00 | 6% | <i>\$16,303.47</i> |
| EWP Premier SOFTWARE SUPPORT S20122 | 98003-S20122 | \$ 5,783.00 | 6% | <i>\$5,476.79</i> |
| EWP Premier SOFTWARE SUPPORT S20124 | 98003-S20124 | \$ 5,286.00 | 6% | <i>\$5,006.11</i> |
| EWP Premier SOFTWARE SUPPORT S20125 | 98003-S20125 | \$ 2,367.00 | 6% | <i>\$2,241.67</i> |
| EWP Premier SOFTWARE SUPPORT S20127 | 98003-S20127 | \$ 3,130.00 | 6% | <i>\$2,964.27</i> |
| EWP Premier SOFTWARE SUPPORT S20128 | 98003-S20128 | \$ 1,544.00 | 6% | <i>\$1,462.25</i> |
| EWP Premier SOFTWARE SUPPORT S20129 | 98003-S20129 | \$ 8,310.00 | 6% | <i>\$7,869.99</i> |
| EWP Premier SOFTWARE SUPPORT S20130 | 98003-S20130 | \$ 24,163.00 | 6% | <i>\$22,883.57</i> |
| EWP Premier SOFTWARE SUPPORT S20131 | 98003-S20131 | \$ 7,348.00 | 6% | <i>\$6,958.92</i> |
| EWP Premier SOFTWARE SUPPORT S20133 | 98003-S20133 | \$ 7,068.00 | 6% | <i>\$6,693.75</i> |
| EWP Premier SOFTWARE SUPPORT S20134 | 98003-S20134 | \$ 3,524.00 | 6% | <i>\$3,337.40</i> |
| EWP Premier SOFTWARE SUPPORT S20136 | 98003-S20136 | \$ 2,710.00 | 6% | <i>\$2,566.51</i> |

| | | | | |
|-------------------------------------|--------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S20137 | 98003-S20137 | \$ 1,124.00 | 6% | <i>\$1,064.48</i> |
| EWP Premier SOFTWARE SUPPORT S20139 | 98003-S20139 | \$ 5,012.00 | 6% | <i>\$4,746.61</i> |
| EWP Premier SOFTWARE SUPPORT S20140 | 98003-S20140 | \$ 1,263.00 | 6% | <i>\$1,196.12</i> |
| EWP Premier SOFTWARE SUPPORT S20141 | 98003-S20141 | \$ 6,164.00 | 6% | <i>\$5,837.62</i> |
| EWP Premier SOFTWARE SUPPORT S20142 | 98003-S20142 | \$ 4,133.00 | 6% | <i>\$3,914.16</i> |
| EWP Premier SOFTWARE SUPPORT S20143 | 98003-S20143 | \$ 8,520.00 | 6% | <i>\$8,068.87</i> |
| EWP Premier SOFTWARE SUPPORT S20144 | 98003-S20144 | \$ 3,784.00 | 6% | <i>\$3,583.64</i> |
| EWP Premier SOFTWARE SUPPORT S20145 | 98003-S20145 | \$ 3,924.00 | 6% | <i>\$3,716.22</i> |
| EWP Premier SOFTWARE SUPPORT S20146 | 98003-S20146 | \$ 16,837.00 | 6% | <i>\$15,945.48</i> |
| EWP Premier SOFTWARE SUPPORT S20149 | 98003-S20149 | \$ 8,050.00 | 6% | <i>\$7,623.75</i> |
| EWP Premier SOFTWARE SUPPORT S20150 | 98003-S20150 | \$ 22,992.00 | 6% | <i>\$21,774.57</i> |
| EWP Premier SOFTWARE SUPPORT S20153 | 98003-S20153 | \$ 2,667.00 | 6% | <i>\$2,525.78</i> |
| EWP Premier SOFTWARE SUPPORT S20154 | 98003-S20154 | \$ 11,826.00 | 6% | <i>\$11,199.81</i> |
| EWP Premier SOFTWARE SUPPORT S20155 | 98003-S20155 | \$ 31,512.00 | 6% | <i>\$29,843.44</i> |
| EWP Premier SOFTWARE SUPPORT S20159 | 98003-S20159 | \$ 43,505.00 | 6% | <i>\$41,201.41</i> |
| EWP Premier SOFTWARE SUPPORT S20161 | 98003-S20161 | \$ 12,002.00 | 6% | <i>\$11,366.49</i> |
| EWP Premier SOFTWARE SUPPORT S20162 | 98003-S20162 | \$ 7,665.00 | 6% | <i>\$7,259.14</i> |
| EWP Premier SOFTWARE SUPPORT S20163 | 98003-S20163 | \$ 1,966.00 | 6% | <i>\$1,861.90</i> |
| EWP Premier SOFTWARE SUPPORT S20164 | 98003-S20164 | \$ 1,966.00 | 6% | <i>\$1,861.90</i> |
| EWP Premier SOFTWARE SUPPORT S20165 | 98003-S20165 | \$ 10,416.00 | 6% | <i>\$9,864.47</i> |
| EWP Premier SOFTWARE SUPPORT S20166 | 98003-S20166 | \$ 2,520.00 | 6% | <i>\$2,386.57</i> |

| | | | | |
|-------------------------------------|--------------|--------------|----|-------------|
| EWP Premier SOFTWARE SUPPORT S20167 | 98003-S20167 | \$ 4,212.00 | 6% | \$3,988.97 |
| EWP Premier SOFTWARE SUPPORT S20168 | 98003-S20168 | \$ 830.00 | 6% | \$786.05 |
| EWP Premier SOFTWARE SUPPORT S20169 | 98003-S20169 | \$ 14,261.00 | 6% | \$13,505.88 |
| EWP Premier SOFTWARE SUPPORT S20170 | 98003-S20170 | \$ 3,334.00 | 6% | \$3,157.46 |
| EWP Premier SOFTWARE SUPPORT S20171 | 98003-S20171 | \$ 5,693.00 | 6% | \$5,391.56 |
| EWP Premier SOFTWARE SUPPORT S20172 | 98003-S20172 | \$ 1,124.00 | 6% | \$1,064.48 |
| EWP Premier SOFTWARE SUPPORT S20173 | 98003-S20173 | \$ 563.00 | 6% | \$533.19 |
| EWP Premier SOFTWARE SUPPORT S20174 | 98003-S20174 | \$ 4,534.00 | 6% | \$4,293.92 |
| EWP Premier SOFTWARE SUPPORT S20177 | 98003-S20177 | \$ 1,411.00 | 6% | \$1,336.29 |
| EWP Premier SOFTWARE SUPPORT S20178 | 98003-S20178 | \$ 7,068.00 | 6% | \$6,693.75 |
| EWP Premier SOFTWARE SUPPORT S20181 | 98003-S20181 | \$ 2,520.00 | 6% | \$2,386.57 |
| EWP Premier SOFTWARE SUPPORT S20182 | 98003-S20182 | \$ 10,416.00 | 6% | \$9,864.47 |
| EWP Premier SOFTWARE SUPPORT S20185 | 98003-S20185 | \$ 14,261.00 | 6% | \$13,505.88 |
| EWP Premier SOFTWARE SUPPORT S20187 | 98003-S20187 | \$ 3,888.00 | 6% | \$3,682.13 |
| EWP Premier SOFTWARE SUPPORT S20188 | 98003-S20188 | \$ 20,289.00 | 6% | \$19,214.70 |
| EWP Premier SOFTWARE SUPPORT S20189 | 98003-S20189 | \$ 34,634.00 | 6% | \$32,800.13 |
| EWP Premier SOFTWARE SUPPORT S20190 | 98003-S20190 | \$ 8,871.00 | 6% | \$8,401.28 |
| EWP Premier SOFTWARE SUPPORT S20192 | 98003-S20192 | \$ 10,416.00 | 6% | \$9,864.47 |
| EWP Premier SOFTWARE SUPPORT S20213 | 98003-S20213 | \$ 2,566.00 | 6% | \$2,430.13 |
| EWP Premier SOFTWARE SUPPORT S20245 | 98003-S20245 | \$ 9,004.00 | 6% | \$8,527.24 |
| EWP Premier SOFTWARE SUPPORT S20246 | 98003-S20246 | \$ 54,093.00 | 6% | \$51,228.78 |

| | | | | |
|-------------------------------------|--------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S20247 | 98003-S20247 | \$ 88,314.00 | 6% | <i>\$83,637.77</i> |
| EWP Premier SOFTWARE SUPPORT S20248 | 98003-S20248 | \$ 34,634.00 | 6% | <i>\$32,800.13</i> |
| EWP Premier SOFTWARE SUPPORT S20252 | 98003-S20252 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier SOFTWARE SUPPORT S20253 | 98003-S20253 | \$ 1,377.00 | 6% | <i>\$1,304.09</i> |
| EWP Premier SOFTWARE SUPPORT S20254 | 98003-S20254 | \$ 1,377.00 | 6% | <i>\$1,304.09</i> |
| EWP Premier SOFTWARE SUPPORT S20255 | 98003-S20255 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EWP Premier SOFTWARE SUPPORT S20256 | 98003-S20256 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EWP Premier SOFTWARE SUPPORT S20257 | 98003-S20257 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier SOFTWARE SUPPORT S20258 | 98003-S20258 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWP Premier SOFTWARE SUPPORT S20259 | 98003-S20259 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWP Premier SOFTWARE SUPPORT S20260 | 98003-S20260 | \$ 679.00 | 6% | <i>\$643.05</i> |
| EWP Premier SOFTWARE SUPPORT S20261 | 98003-S20261 | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWP Premier SOFTWARE SUPPORT S20268 | 98003-S20268 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier SOFTWARE SUPPORT S20269 | 98003-S20269 | \$ 1,377.00 | 6% | <i>\$1,304.09</i> |
| EWP Premier SOFTWARE SUPPORT S20270 | 98003-S20270 | \$ 1,377.00 | 6% | <i>\$1,304.09</i> |
| EWP Premier SOFTWARE SUPPORT S20271 | 98003-S20271 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EWP Premier SOFTWARE SUPPORT S20272 | 98003-S20272 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EWP Premier SOFTWARE SUPPORT S20273 | 98003-S20273 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier SOFTWARE SUPPORT S20274 | 98003-S20274 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWP Premier SOFTWARE SUPPORT S20275 | 98003-S20275 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWP Premier SOFTWARE SUPPORT S20281 | 98003-S20281 | \$ 678.00 | 6% | <i>\$642.10</i> |

| | | | | |
|-------------------------------------|--------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S20282 | 98003-S20282 | \$ 678.00 | 6% | <i>\$642.10</i> |
| EWP Premier SOFTWARE SUPPORT S20283 | 98003-S20283 | \$ 697.00 | 6% | <i>\$660.09</i> |
| EWP Premier SOFTWARE SUPPORT S20284 | 98003-S20284 | \$ 678.00 | 6% | <i>\$642.10</i> |
| EWP Premier SOFTWARE SUPPORT S20293 | 98003-S20293 | \$ 1,790.00 | 6% | <i>\$1,695.22</i> |
| EWP Premier SOFTWARE SUPPORT S20296 | 98003-S20296 | \$ 5,390.00 | 6% | <i>\$5,104.60</i> |
| EWP Premier SOFTWARE SUPPORT S20298 | 98003-S20298 | \$ 2,569.00 | 6% | <i>\$2,432.97</i> |
| EWP Premier SOFTWARE SUPPORT S20299 | 98003-S20299 | \$ 5,802.00 | 6% | <i>\$5,494.78</i> |
| EWP Premier SOFTWARE SUPPORT S20300 | 98003-S20300 | \$ 8,471.00 | 6% | <i>\$8,022.46</i> |
| EWP Premier SOFTWARE SUPPORT S20301 | 98003-S20301 | \$ 12,320.00 | 6% | <i>\$11,667.66</i> |
| EWP Premier SOFTWARE SUPPORT S20302 | 98003-S20302 | \$ 17,550.00 | 6% | <i>\$16,620.73</i> |
| EWP Premier SOFTWARE SUPPORT S20303 | 98003-S20303 | \$ 24,632.00 | 6% | <i>\$23,327.74</i> |
| EWP Premier SOFTWARE SUPPORT S20304 | 98003-S20304 | \$ 35,305.00 | 6% | <i>\$33,435.60</i> |
| EWP Premier SOFTWARE SUPPORT S20309 | 98003-S20309 | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier SOFTWARE SUPPORT S20310 | 98003-S20310 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier SOFTWARE SUPPORT S20313 | 98003-S20313 | \$ 3,134.00 | 6% | <i>\$2,968.05</i> |
| EWP Premier SOFTWARE SUPPORT S20314 | 98003-S20314 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier SOFTWARE SUPPORT S20330 | 98003-S20330 | \$ 29.00 | 6% | <i>\$27.46</i> |
| EWP Premier SOFTWARE SUPPORT S20331 | 98003-S20331 | \$ 21.00 | 6% | <i>\$19.89</i> |
| EWP Premier SOFTWARE SUPPORT S20343 | 98003-S20343 | \$ 286.00 | 6% | <i>\$270.86</i> |
| EWP Premier SOFTWARE SUPPORT S20344 | 98003-S20344 | \$ 2,850.00 | 6% | <i>\$2,699.09</i> |
| EWP Premier SOFTWARE SUPPORT S20345 | 98003-S20345 | \$ 31,343.00 | 6% | <i>\$29,683.39</i> |

| | | | | |
|-------------------------------------|--------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S20346 | 98003-S20346 | \$ 62,684.00 | 6% | <i>\$59,364.88</i> |
| EWP Premier SOFTWARE SUPPORT S20353 | 98003-S20353 | \$ 8,135.00 | 6% | <i>\$7,704.25</i> |
| EWP Premier SOFTWARE SUPPORT S20354 | 98003-S20354 | \$ 647.00 | 6% | <i>\$612.74</i> |
| EWP Premier SOFTWARE SUPPORT S20358 | 98003-S20358 | \$ 203.00 | 6% | <i>\$192.25</i> |
| EWP Premier SOFTWARE SUPPORT S20359 | 98003-S20359 | \$ 18.00 | 6% | <i>\$17.05</i> |
| EWP Premier SOFTWARE SUPPORT S20360 | 98003-S20360 | \$ 250.00 | 6% | <i>\$236.76</i> |
| EWP Premier SOFTWARE SUPPORT S20361 | 98003-S20361 | \$ 987.00 | 6% | <i>\$934.74</i> |
| EWP Premier SOFTWARE SUPPORT S20362 | 98003-S20362 | \$ 3,941.00 | 6% | <i>\$3,732.32</i> |
| EWP Premier SOFTWARE SUPPORT S20363 | 98003-S20363 | \$ 15,783.00 | 6% | <i>\$14,947.29</i> |
| EWP Premier SOFTWARE SUPPORT S20364 | 98003-S20364 | \$ 31,560.00 | 6% | <i>\$29,888.90</i> |
| EWP Premier SOFTWARE SUPPORT S20365 | 98003-S20365 | \$ 18.00 | 6% | <i>\$17.05</i> |
| EWP Premier SOFTWARE SUPPORT S20366 | 98003-S20366 | \$ 250.00 | 6% | <i>\$236.76</i> |
| EWP Premier SOFTWARE SUPPORT S20367 | 98003-S20367 | \$ 987.00 | 6% | <i>\$934.74</i> |
| EWP Premier SOFTWARE SUPPORT S20368 | 98003-S20368 | \$ 3,941.00 | 6% | <i>\$3,732.32</i> |
| EWP Premier SOFTWARE SUPPORT S20369 | 98003-S20369 | \$ 15,783.00 | 6% | <i>\$14,947.29</i> |
| EWP Premier SOFTWARE SUPPORT S20370 | 98003-S20370 | \$ 31,560.00 | 6% | <i>\$29,888.90</i> |
| EWP Premier SOFTWARE SUPPORT S20371 | 98003-S20371 | \$ 19.00 | 6% | <i>\$17.99</i> |
| EWP Premier SOFTWARE SUPPORT S20372 | 98003-S20372 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier SOFTWARE SUPPORT S20373 | 98003-S20373 | \$ 166.00 | 6% | <i>\$157.21</i> |
| EWP Premier SOFTWARE SUPPORT S20374 | 98003-S20374 | \$ 831.00 | 6% | <i>\$787.00</i> |
| EWP Premier SOFTWARE SUPPORT S20375 | 98003-S20375 | \$ 1,659.00 | 6% | <i>\$1,571.16</i> |

| | | | | |
|-------------------------------------|--------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S20376 | 98003-S20376 | \$ 8,294.00 | 6% | <i>\$7,854.83</i> |
| EWP Premier SOFTWARE SUPPORT S20377 | 98003-S20377 | \$ 16,587.00 | 6% | <i>\$15,708.72</i> |
| EWP Premier SOFTWARE SUPPORT S20378 | 98003-S20378 | \$ 33,174.00 | 6% | <i>\$31,417.44</i> |
| EWP Premier SOFTWARE SUPPORT S20400 | 98003-S20400 | \$ 3,584.00 | 6% | <i>\$3,394.23</i> |
| EWP Premier SOFTWARE SUPPORT S20401 | 98003-S20401 | \$ 1,381.00 | 6% | <i>\$1,307.88</i> |
| EWP Premier SOFTWARE SUPPORT S20411 | 98003-S20411 | \$ 197.00 | 6% | <i>\$186.57</i> |
| EWP Premier SOFTWARE SUPPORT S20412 | 98003-S20412 | \$ 77,282.00 | 6% | <i>\$73,189.92</i> |
| EWP Premier SOFTWARE SUPPORT S20413 | 98003-S20413 | \$ 659.00 | 6% | <i>\$624.11</i> |
| EWP Premier SOFTWARE SUPPORT S20414 | 98003-S20414 | \$ 77,282.00 | 6% | <i>\$73,189.92</i> |
| EWP Premier SOFTWARE SUPPORT S20415 | 98003-S20415 | \$ 19,326.00 | 6% | <i>\$18,302.69</i> |
| EWP Premier SOFTWARE SUPPORT S20416 | 98003-S20416 | \$ 19,326.00 | 6% | <i>\$18,302.69</i> |
| EWP Premier SOFTWARE SUPPORT S20417 | 98003-S20417 | \$ 19,326.00 | 6% | <i>\$18,302.69</i> |
| EWP Premier SOFTWARE SUPPORT S20418 | 98003-S20418 | \$ 19,326.00 | 6% | <i>\$18,302.69</i> |
| EWP Premier SOFTWARE SUPPORT S20419 | 98003-S20419 | \$ 77,282.00 | 6% | <i>\$73,189.92</i> |
| EWP Premier SOFTWARE SUPPORT S20420 | 98003-S20420 | \$ 28,982.00 | 6% | <i>\$27,447.40</i> |
| EWP Premier SOFTWARE SUPPORT S20421 | 98003-S20421 | \$ 57,964.00 | 6% | <i>\$54,894.81</i> |
| EWP Premier SOFTWARE SUPPORT S20422 | 98003-S20422 | \$ 28,982.00 | 6% | <i>\$27,447.40</i> |
| EWP Premier SOFTWARE SUPPORT S20423 | 98003-S20423 | \$ 7,728.00 | 6% | <i>\$7,318.80</i> |
| EWP Premier SOFTWARE SUPPORT S20424 | 98003-S20424 | \$ 3,870.00 | 6% | <i>\$3,665.08</i> |
| EWP Premier SOFTWARE SUPPORT S20425 | 98003-S20425 | \$ 7,728.00 | 6% | <i>\$7,318.80</i> |
| EWP Premier SOFTWARE SUPPORT S20426 | 98003-S20426 | \$ 3,870.00 | 6% | <i>\$3,665.08</i> |

| | | | | |
|-------------------------------------|--------------|-------------|----|-------------------|
| EWP Premier SOFTWARE SUPPORT S20428 | 98003-S20428 | \$ 2,065.00 | 6% | <i>\$1,955.66</i> |
| EWP Premier SOFTWARE SUPPORT S20429 | 98003-S20429 | \$ 1,066.00 | 6% | <i>\$1,009.56</i> |
| EWP Premier SOFTWARE SUPPORT S20430 | 98003-S20430 | \$ 5,142.00 | 6% | <i>\$4,869.73</i> |
| EWP Premier SOFTWARE SUPPORT S20431 | 98003-S20431 | \$ 2,654.00 | 6% | <i>\$2,513.47</i> |
| EWP Premier SOFTWARE SUPPORT S20434 | 98003-S20434 | \$ 4,393.00 | 6% | <i>\$4,160.39</i> |
| EWP Premier SOFTWARE SUPPORT S20435 | 98003-S20435 | \$ 3,296.00 | 6% | <i>\$3,121.48</i> |
| EWP Premier SOFTWARE SUPPORT S20436 | 98003-S20436 | \$ 236.00 | 6% | <i>\$223.50</i> |
| EWP Premier SOFTWARE SUPPORT S20437 | 98003-S20437 | \$ 1,801.00 | 6% | <i>\$1,705.64</i> |
| EWP Premier SOFTWARE SUPPORT S20438 | 98003-S20438 | \$ 3,296.00 | 6% | <i>\$3,121.48</i> |
| EWP Premier SOFTWARE SUPPORT S20439 | 98003-S20439 | \$ 4,506.00 | 6% | <i>\$4,267.41</i> |
| EWP Premier SOFTWARE SUPPORT S20440 | 98003-S20440 | \$ 3,159.00 | 6% | <i>\$2,991.73</i> |
| EWP Premier SOFTWARE SUPPORT S20441 | 98003-S20441 | \$ 1,263.00 | 6% | <i>\$1,196.12</i> |
| EWP Premier SOFTWARE SUPPORT S20442 | 98003-S20442 | \$ 2,507.00 | 6% | <i>\$2,374.25</i> |
| EWP Premier SOFTWARE SUPPORT S20443 | 98003-S20443 | \$ 1,587.00 | 6% | <i>\$1,502.97</i> |
| EWP Premier SOFTWARE SUPPORT S20453 | 98003-S20453 | \$ 3,768.00 | 6% | <i>\$3,568.48</i> |
| EWP Premier SOFTWARE SUPPORT S20463 | 98003-S20463 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWP Premier SOFTWARE SUPPORT S20465 | 98003-S20465 | \$ 1,407.00 | 6% | <i>\$1,332.50</i> |
| EWP Premier SOFTWARE SUPPORT S20477 | 98003-S20477 | \$ 3,947.00 | 6% | <i>\$3,738.01</i> |
| EWP Premier SOFTWARE SUPPORT S20478 | 98003-S20478 | \$ 2,266.00 | 6% | <i>\$2,146.02</i> |
| EWP Premier SOFTWARE SUPPORT S20479 | 98003-S20479 | \$ 3,947.00 | 6% | <i>\$3,738.01</i> |
| EWP Premier SOFTWARE SUPPORT S20480 | 98003-S20480 | \$ 3,604.00 | 6% | <i>\$3,413.17</i> |

| | | | | |
|-------------------------------------|--------------|-------------|----|-------------------|
| EWP Premier SOFTWARE SUPPORT S20481 | 98003-S20481 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWP Premier SOFTWARE SUPPORT S22011 | 98003-S22011 | \$ 6,664.00 | 6% | <i>\$6,311.14</i> |
| EWP Premier SOFTWARE SUPPORT S22014 | 98003-S22014 | \$ 2,904.00 | 6% | <i>\$2,750.23</i> |
| EWP Premier SOFTWARE SUPPORT S22015 | 98003-S22015 | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP Premier SOFTWARE SUPPORT S22016 | 98003-S22016 | \$ 2,560.00 | 6% | <i>\$2,424.45</i> |
| EWP Premier SOFTWARE SUPPORT S22017 | 98003-S22017 | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP Premier SOFTWARE SUPPORT S22018 | 98003-S22018 | \$ 2,904.00 | 6% | <i>\$2,750.23</i> |
| EWP Premier SOFTWARE SUPPORT S22019 | 98003-S22019 | \$ 2,904.00 | 6% | <i>\$2,750.23</i> |
| EWP Premier SOFTWARE SUPPORT S22020 | 98003-S22020 | \$ 2,904.00 | 6% | <i>\$2,750.23</i> |
| EWP Premier SOFTWARE SUPPORT S22021 | 98003-S22021 | \$ 2,904.00 | 6% | <i>\$2,750.23</i> |
| EWP Premier SOFTWARE SUPPORT S22022 | 98003-S22022 | \$ 2,560.00 | 6% | <i>\$2,424.45</i> |
| EWP Premier SOFTWARE SUPPORT S22027 | 98003-S22027 | \$ 1,654.00 | 6% | <i>\$1,566.42</i> |
| EWP Premier SOFTWARE SUPPORT S22028 | 98003-S22028 | \$ 1,579.00 | 6% | <i>\$1,495.39</i> |
| EWP Premier SOFTWARE SUPPORT S22030 | 98003-S22030 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWP Premier SOFTWARE SUPPORT S22031 | 98003-S22031 | \$ 1,898.00 | 6% | <i>\$1,797.50</i> |
| EWP Premier SOFTWARE SUPPORT S22032 | 98003-S22032 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWP Premier SOFTWARE SUPPORT S22035 | 98003-S22035 | \$ 909.00 | 6% | <i>\$860.87</i> |
| EWP Premier SOFTWARE SUPPORT S22036 | 98003-S22036 | \$ 868.00 | 6% | <i>\$822.04</i> |
| EWP Premier SOFTWARE SUPPORT S22037 | 98003-S22037 | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| EWP Premier SOFTWARE SUPPORT S22038 | 98003-S22038 | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| EWP Premier SOFTWARE SUPPORT S22039 | 98003-S22039 | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |

| | | | | |
|-------------------------------------|--------------|-------------|----|-------------------|
| EWP Premier SOFTWARE SUPPORT S22040 | 98003-S22040 | \$ 1,323.00 | 6% | <i>\$1,252.95</i> |
| EWP Premier SOFTWARE SUPPORT S22041 | 98003-S22041 | \$ 1,264.00 | 6% | <i>\$1,197.07</i> |
| EWP Premier SOFTWARE SUPPORT S22042 | 98003-S22042 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier SOFTWARE SUPPORT S22044 | 98003-S22044 | \$ 532.00 | 6% | <i>\$503.83</i> |
| EWP Premier SOFTWARE SUPPORT S22045 | 98003-S22045 | \$ 486.00 | 6% | <i>\$460.27</i> |
| EWP Premier SOFTWARE SUPPORT S22046 | 98003-S22046 | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWP Premier SOFTWARE SUPPORT S22047 | 98003-S22047 | \$ 1,142.00 | 6% | <i>\$1,081.53</i> |
| EWP Premier SOFTWARE SUPPORT S22051 | 98003-S22051 | \$ 1,662.00 | 6% | <i>\$1,574.00</i> |
| EWP Premier SOFTWARE SUPPORT S22055 | 98003-S22055 | \$ 1,911.00 | 6% | <i>\$1,809.81</i> |
| EWP Premier SOFTWARE SUPPORT S22057 | 98003-S22057 | \$ 5,287.00 | 6% | <i>\$5,007.05</i> |
| EWP Premier SOFTWARE SUPPORT S22063 | 98003-S22063 | \$ 2,864.00 | 6% | <i>\$2,712.35</i> |
| EWP Premier SOFTWARE SUPPORT S22064 | 98003-S22064 | \$ 1,211.00 | 6% | <i>\$1,146.88</i> |
| EWP Premier SOFTWARE SUPPORT S22065 | 98003-S22065 | \$ 4,067.00 | 6% | <i>\$3,851.65</i> |
| EWP Premier SOFTWARE SUPPORT S22066 | 98003-S22066 | \$ 1,509.00 | 6% | <i>\$1,429.10</i> |
| EWP Premier SOFTWARE SUPPORT S22067 | 98003-S22067 | \$ 6,931.00 | 6% | <i>\$6,564.00</i> |
| EWP Premier SOFTWARE SUPPORT S22068 | 98003-S22068 | \$ 966.00 | 6% | <i>\$914.85</i> |
| EWP Premier SOFTWARE SUPPORT S22069 | 98003-S22069 | \$ 2,565.00 | 6% | <i>\$2,429.18</i> |
| EWP Premier SOFTWARE SUPPORT S22070 | 98003-S22070 | \$ 5,720.00 | 6% | <i>\$5,417.13</i> |
| EWP Premier SOFTWARE SUPPORT S22072 | 98003-S22072 | \$ 2,281.00 | 6% | <i>\$2,160.22</i> |
| EWP Premier SOFTWARE SUPPORT S22073 | 98003-S22073 | \$ 2,281.00 | 6% | <i>\$2,160.22</i> |
| EWP Premier SOFTWARE SUPPORT S22074 | 98003-S22074 | \$ 336.00 | 6% | <i>\$318.21</i> |

| | | | | |
|-------------------------------------|--------------|-------------|----|-------------------|
| EWP Premier SOFTWARE SUPPORT S22075 | 98003-S22075 | \$ 1,972.00 | 6% | <i>\$1,867.58</i> |
| EWP Premier SOFTWARE SUPPORT S22076 | 98003-S22076 | \$ 176.00 | 6% | <i>\$166.68</i> |
| EWP Premier SOFTWARE SUPPORT S22077 | 98003-S22077 | \$ 744.00 | 6% | <i>\$704.61</i> |
| EWP Premier SOFTWARE SUPPORT S22078 | 98003-S22078 | \$ 932.00 | 6% | <i>\$882.65</i> |
| EWP Premier SOFTWARE SUPPORT S22079 | 98003-S22079 | \$ 202.00 | 6% | <i>\$191.30</i> |
| EWP Premier SOFTWARE SUPPORT S22080 | 98003-S22080 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier SOFTWARE SUPPORT S22081 | 98003-S22081 | \$ 202.00 | 6% | <i>\$191.30</i> |
| EWP Premier SOFTWARE SUPPORT S22084 | 98003-S22084 | \$ 990.00 | 6% | <i>\$937.58</i> |
| EWP Premier SOFTWARE SUPPORT S22085 | 98003-S22085 | \$ 1,221.00 | 6% | <i>\$1,156.35</i> |
| EWP Premier SOFTWARE SUPPORT S22086 | 98003-S22086 | \$ 188.00 | 6% | <i>\$178.05</i> |
| EWP Premier SOFTWARE SUPPORT S22087 | 98003-S22087 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWP Premier SOFTWARE SUPPORT S22088 | 98003-S22088 | \$ 1,135.00 | 6% | <i>\$1,074.90</i> |
| EWP Premier SOFTWARE SUPPORT S22089 | 98003-S22089 | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier SOFTWARE SUPPORT S22090 | 98003-S22090 | \$ 528.00 | 6% | <i>\$500.04</i> |
| EWP Premier SOFTWARE SUPPORT S22091 | 98003-S22091 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWP Premier SOFTWARE SUPPORT S22092 | 98003-S22092 | \$ 528.00 | 6% | <i>\$500.04</i> |
| EWP Premier SOFTWARE SUPPORT S22093 | 98003-S22093 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWP Premier SOFTWARE SUPPORT S22094 | 98003-S22094 | \$ 789.00 | 6% | <i>\$747.22</i> |
| EWP Premier SOFTWARE SUPPORT S22095 | 98003-S22095 | \$ 789.00 | 6% | <i>\$747.22</i> |
| EWP Premier SOFTWARE SUPPORT S22117 | 98003-S22117 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |
| EWP Premier SOFTWARE SUPPORT S22119 | 98003-S22119 | \$ 3,803.00 | 6% | <i>\$3,601.63</i> |

| | | | | |
|-------------------------------------|--------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S22123 | 98003-S22123 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier SOFTWARE SUPPORT S22124 | 98003-S22124 | \$ 446.00 | 6% | <i>\$422.38</i> |
| EWP Premier SOFTWARE SUPPORT S22139 | 98003-S22139 | \$ 591.00 | 6% | <i>\$559.71</i> |
| EWP Premier SOFTWARE SUPPORT S22140 | 98003-S22140 | \$ 961.00 | 6% | <i>\$910.12</i> |
| EWP Premier SOFTWARE SUPPORT S22141 | 98003-S22141 | \$ 3,597.00 | 6% | <i>\$3,406.54</i> |
| EWP Premier SOFTWARE SUPPORT S22142 | 98003-S22142 | \$ 5,206.00 | 6% | <i>\$4,930.34</i> |
| EWP Premier SOFTWARE SUPPORT S22143 | 98003-S22143 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier SOFTWARE SUPPORT S22152 | 98003-S22152 | \$ 8,598.00 | 6% | <i>\$8,142.74</i> |
| EWP Premier SOFTWARE SUPPORT S22153 | 98003-S22153 | \$ 13,713.00 | 6% | <i>\$12,986.90</i> |
| EWP Premier SOFTWARE SUPPORT S22154 | 98003-S22154 | \$ 23,965.00 | 6% | <i>\$22,696.05</i> |
| EWP Premier SOFTWARE SUPPORT S22155 | 98003-S22155 | \$ 25,389.00 | 6% | <i>\$24,044.65</i> |
| EWP Premier SOFTWARE SUPPORT S22156 | 98003-S22156 | \$ 8,595.00 | 6% | <i>\$8,139.89</i> |
| EWP Premier SOFTWARE SUPPORT S22157 | 98003-S22157 | \$ 13,705.00 | 6% | <i>\$12,979.32</i> |
| EWP Premier SOFTWARE SUPPORT S22158 | 98003-S22158 | \$ 8,190.00 | 6% | <i>\$7,756.34</i> |
| EWP Premier SOFTWARE SUPPORT S22159 | 98003-S22159 | \$ 13,054.00 | 6% | <i>\$12,362.79</i> |
| EWP Premier SOFTWARE SUPPORT S22160 | 98003-S22160 | \$ 10,590.00 | 6% | <i>\$10,029.26</i> |
| EWP Premier SOFTWARE SUPPORT S22161 | 98003-S22161 | \$ 16,884.00 | 6% | <i>\$15,989.99</i> |
| EWP Premier SOFTWARE SUPPORT S22162 | 98003-S22162 | \$ 29,523.00 | 6% | <i>\$27,959.76</i> |
| EWP Premier SOFTWARE SUPPORT S22163 | 98003-S22163 | \$ 2,869.00 | 6% | <i>\$2,717.09</i> |
| EWP Premier SOFTWARE SUPPORT S22164 | 98003-S22164 | \$ 5,738.00 | 6% | <i>\$5,434.17</i> |
| EWP Premier SOFTWARE SUPPORT S22165 | 98003-S22165 | \$ 10,757.00 | 6% | <i>\$10,187.42</i> |

| | | | | |
|---|-------------------------|--------------|----|--------------------|
| EWP Premier SOFTWARE SUPPORT S22166 | 98003-S22166 | \$ 7,894.00 | 6% | <i>\$7,476.01</i> |
| EWP Premier SOFTWARE SUPPORT S22167 | 98003-S22167 | \$ 10,757.00 | 6% | <i>\$10,187.42</i> |
| EWP Premier SOFTWARE SUPPORT S22173 | 98003-S22173 | \$ 906.00 | 6% | <i>\$858.03</i> |
| EWP Premier SOFTWARE SUPPORT S22174 | 98003-S22174 | \$ 1,812.00 | 6% | <i>\$1,716.05</i> |
| EWP Premier SOFTWARE SUPPORT S22175 | 98003-S22175 | \$ 3,625.00 | 6% | <i>\$3,433.06</i> |
| EWP SW SUPPORT S22176 FEDEX LIC BDL | 98003-S22176 | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier SW SUPPORT XCC-ACT-V5-VT | 98003-XCC-ACT-V5-VT | \$ 554.00 | 6% | <i>\$524.67</i> |
| EWP Prem SW SUPPORT XCC-ACT-V5-VT-EGY | 98003-XCC-ACT-V5-VT-EGY | \$ 554.00 | 6% | <i>\$524.67</i> |
| EWP Premier SOFTWARE SUPP XESNPLUSSWPKG | 98003-XESN-PLUS-SW-PKG | \$ 14,929.00 | 6% | <i>\$14,138.51</i> |
| EWP Premier SOFTW SUB XIQ-CACT-APP | 98003-XIQ-CACT-APP | \$ 390.00 | 6% | <i>\$369.35</i> |
| EWP Premier SW SUPPORT XIQ-CACT-VT | 98003-XIQ-CACT-VT | \$ 528.00 | 6% | <i>\$500.04</i> |
| EWP Premier SW SUPPORT XIQ-CACT-VT-EGY | 98003-XIQ-CACT-VT-EGY | \$ 528.00 | 6% | <i>\$500.04</i> |
| EWP Premier SOFTW SUPPORT XIQ-PIL-P-OP | 98003-XIQ-PIL-P-OP | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier SOFTWARE SUPPORT XVM-LIC-1 | 98003-XVM-LIC-1 | \$ 778.00 | 6% | <i>\$736.80</i> |
| EWP Premier NBD AHR 10200 | 98004-10200 | \$ 2,323.00 | 6% | <i>\$2,200.00</i> |
| EWP Premier NBD AHR 10320 | 98004-10320 | \$ 2,552.00 | 6% | <i>\$2,416.87</i> |
| EWP Premier NBD AHR 10330 | 98004-10330 | \$ 6,126.00 | 6% | <i>\$5,801.63</i> |
| EWP Premier NBD AHR 10331 | 98004-10331 | \$ 2,823.00 | 6% | <i>\$2,673.52</i> |
| EWP Premier NBD AHR 10335 | 98004-10335 | \$ 4,400.00 | 6% | <i>\$4,167.02</i> |
| EWP Premier NBD AHR 10403 | 98004-10403 | \$ 5,615.00 | 6% | <i>\$5,317.69</i> |
| EWP Premier NBD AHR 10404 | 98004-10404 | \$ 2,760.00 | 6% | <i>\$2,613.86</i> |
| EWP Premier NBD AHR 10441 | 98004-10441 | \$ 1,853.00 | 6% | <i>\$1,754.88</i> |
| EWP Premier NBD AHR 10442 | 98004-10442 | \$ 1,969.00 | 6% | <i>\$1,864.74</i> |
| EWP Premier NBD AHR 1130C | 98004-1130C | \$ 1,247.00 | 6% | <i>\$1,180.97</i> |
| EWP Premier NBD AHR 16119 | 98004-16119 | \$ 336.00 | 6% | <i>\$318.21</i> |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| EWP Premier NBD AHR 16120 | 98004-16120 | \$ 416.00 | 6% | \$393.97 |
| EWP Premier NBD AHR 16126 | 98004-16126 | \$ 336.00 | 6% | \$318.21 |
| EWP Premier NBD AHR 16127 | 98004-16127 | \$ 352.00 | 6% | \$333.36 |
| EWP Premier NBD AHR 16172 | 98004-16172 | \$ 342.00 | 6% | \$323.89 |
| EWP Premier NBD AHR 16172T | 98004-16172T | \$ 407.00 | 6% | \$385.45 |
| EWP Premier NBD AHR 16173 | 98004-16173 | \$ 348.00 | 6% | \$329.57 |
| EWP Premier NBD AHR 16173T | 98004-16173T | \$ 414.00 | 6% | \$392.08 |
| EWP Premier NBD AHR 16174 | 98004-16174 | \$ 550.00 | 6% | \$520.88 |
| EWP Premier NBD AHR 16175 | 98004-16175 | \$ 569.00 | 6% | \$538.87 |
| EWP Premier NBD AHR 16176 | 98004-16176 | \$ 494.00 | 6% | \$467.84 |
| EWP Premier NBD AHR 16177 | 98004-16177 | \$ 489.00 | 6% | \$463.11 |
| EWP Premier NBD AHR 16177T | 98004-16177T | \$ 622.00 | 6% | \$589.07 |
| EWP Premier NBD AHR 16178 | 98004-16178 | \$ 725.00 | 6% | \$686.61 |
| EWP Premier NBD AHR 16179 | 98004-16179 | \$ 746.00 | 6% | \$706.50 |
| EWP Premier NBD AHR 16179T | 98004-16179T | \$ 887.00 | 6% | \$840.03 |
| EWP Premier NBD AHR 16301T | 98004-16301T | \$ 1,959.00 | 6% | \$1,855.27 |
| EWP Premier NBD AHR 16303T | 98004-16303T | \$ 1,959.00 | 6% | \$1,855.27 |
| EWP Premier NBD AHR 16304T | 98004-16304T | \$ 2,608.00 | 6% | \$2,469.91 |
| EWP Premier NBD AHR 16401T | 98004-16401T | \$ 910.00 | 6% | \$861.82 |
| EWP Premier NBD AHR 16402T | 98004-16402T | \$ 1,381.00 | 6% | \$1,307.88 |
| EWP Premier NBD AHR 16403T | 98004-16403T | \$ 1,220.00 | 6% | \$1,155.40 |
| EWP Premier NBD AHR 16404T | 98004-16404T | \$ 1,220.00 | 6% | \$1,155.40 |
| EWP Premier NBD AHR 16405T | 98004-16405T | \$ 1,608.00 | 6% | \$1,522.86 |
| EWP Premier NBD AHR 16406T | 98004-16406T | \$ 2,143.00 | 6% | \$2,029.53 |
| EWP Premier NBD AHR 16431 | 98004-16431 | \$ 1,381.00 | 6% | \$1,307.88 |
| EWP Premier NBD AHR 16432 | 98004-16432 | \$ 1,473.00 | 6% | \$1,395.00 |
| EWP Premier NBD AHR 16440 | 98004-16440 | \$ 869.00 | 6% | \$822.99 |
| EWP Premier NBD AHR 16441 | 98004-16441 | \$ 779.00 | 6% | \$737.75 |
| EWP Premier NBD AHR 16442 | 98004-16442 | \$ 352.00 | 6% | \$333.36 |

| | | | | |
|----------------------------|--------------|-------------|----|-----------------|
| EWP Premier NBD AHR 16444 | 98004-16444 | \$ 176.00 | 6% | <i>\$166.68</i> |
| EWP Premier NBD AHR 16501 | 98004-16501 | \$ 184.00 | 6% | <i>\$174.26</i> |
| EWP Premier NBD AHR 16501T | 98004-16501T | \$ 237.00 | 6% | <i>\$224.45</i> |
| EWP Premier NBD AHR 16502 | 98004-16502 | \$ 271.00 | 6% | <i>\$256.65</i> |
| EWP Premier NBD AHR 16502T | 98004-16502T | \$ 330.00 | 6% | <i>\$312.53</i> |
| EWP Premier NBD AHR 16503 | 98004-16503 | \$ 221.00 | 6% | <i>\$209.30</i> |
| EWP Premier NBD AHR 16503T | 98004-16503T | \$ 288.00 | 6% | <i>\$272.75</i> |
| EWP Premier NBD AHR 16504 | 98004-16504 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWP Premier NBD AHR 16504T | 98004-16504T | \$ 435.00 | 6% | <i>\$411.97</i> |
| EWP Premier NBD AHR 16505 | 98004-16505 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWP Premier NBD AHR 16505T | 98004-16505T | \$ 493.00 | 6% | <i>\$466.90</i> |
| EWP Premier NBD AHR 16506 | 98004-16506 | \$ 620.00 | 6% | <i>\$587.17</i> |
| EWP Premier NBD AHR 16506T | 98004-16506T | \$ 763.00 | 6% | <i>\$722.60</i> |
| EWP Premier NBD AHR 16507 | 98004-16507 | \$ 567.00 | 6% | <i>\$536.98</i> |
| EWP Premier NBD AHR 16507T | 98004-16507T | \$ 668.00 | 6% | <i>\$632.63</i> |
| EWP Premier NBD AHR 16508 | 98004-16508 | \$ 713.00 | 6% | <i>\$675.25</i> |
| EWP Premier NBD AHR 16508T | 98004-16508T | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier NBD AHR 16509 | 98004-16509 | \$ 713.00 | 6% | <i>\$675.25</i> |
| EWP Premier NBD AHR 16509T | 98004-16509T | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier NBD AHR 16510 | 98004-16510 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier NBD AHR 16510T | 98004-16510T | \$ 1,014.00 | 6% | <i>\$960.31</i> |
| EWP Premier NBD AHR 16513 | 98004-16513 | \$ 507.00 | 6% | <i>\$480.15</i> |
| EWP Premier NBD AHR 16514 | 98004-16514 | \$ 827.00 | 6% | <i>\$783.21</i> |
| EWP Premier NBD AHR 16515 | 98004-16515 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR 16516 | 98004-16516 | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier NBD AHR 16517 | 98004-16517 | \$ 316.00 | 6% | <i>\$299.27</i> |
| EWP Premier NBD AHR 16518 | 98004-16518 | \$ 275.00 | 6% | <i>\$260.44</i> |
| EWP Premier NBD AHR 16519 | 98004-16519 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR 16520 | 98004-16520 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR 16530 | 98004-16530 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR 16531 | 98004-16531 | \$ 231.00 | 6% | <i>\$218.77</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-----------------|
| EWP Premier NBD AHR 16531T | 98004-16531T | \$ 262.00 | 6% | <i>\$248.13</i> |
| EWP Premier NBD AHR 16532 | 98004-16532 | \$ 231.00 | 6% | <i>\$218.77</i> |
| EWP Premier NBD AHR 16532T | 98004-16532T | \$ 262.00 | 6% | <i>\$248.13</i> |
| EWP Premier NBD AHR 16533 | 98004-16533 | \$ 329.00 | 6% | <i>\$311.58</i> |
| EWP Premier NBD AHR 16533T | 98004-16533T | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier NBD AHR 16534 | 98004-16534 | \$ 354.00 | 6% | <i>\$335.26</i> |
| EWP Premier NBD AHR 16535 | 98004-16535 | \$ 514.00 | 6% | <i>\$486.78</i> |
| EWP Premier NBD AHR 16535A | 98004-16535A | \$ 514.00 | 6% | <i>\$486.78</i> |
| EWP Premier NBD AHR 16535T | 98004-16535T | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier NBD AHR 16536 | 98004-16536 | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier NBD AHR 16537 | 98004-16537 | \$ 329.00 | 6% | <i>\$311.58</i> |
| EWP Premier NBD AHR 16538 | 98004-16538 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWP Premier NBD AHR 16538T | 98004-16538T | \$ 492.00 | 6% | <i>\$465.95</i> |
| EWP Premier NBD AHR 16539 | 98004-16539 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD AHR 16540 | 98004-16540 | \$ 364.00 | 6% | <i>\$344.73</i> |
| EWP Premier NBD AHR 16541 | 98004-16541 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR 16560 | 98004-16560 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD AHR 16561 | 98004-16561 | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD AHR 16562 | 98004-16562 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR 16563 | 98004-16563 | \$ 196.00 | 6% | <i>\$185.62</i> |
| EWP Premier NBD AHR 16564 | 98004-16564 | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier NBD AHR 16565 | 98004-16565 | \$ 357.00 | 6% | <i>\$338.10</i> |
| EWP Premier NBD AHR 16566 | 98004-16566 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier NBD AHR 16567 | 98004-16567 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD AHR 16568 | 98004-16568 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD AHR 16569 | 98004-16569 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier NBD AHR 16570 | 98004-16570 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR 16571 | 98004-16571 | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier NBD AHR 16701 | 98004-16701 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD AHR 16702 | 98004-16702 | \$ 750.00 | 6% | <i>\$710.29</i> |
| EWP Premier NBD AHR 16703 | 98004-16703 | \$ 593.00 | 6% | <i>\$561.60</i> |
| EWP Premier NBD AHR 16703T | 98004-16703T | \$ 705.00 | 6% | <i>\$667.67</i> |
| EWP Premier NBD AHR 16704 | 98004-16704 | \$ 865.00 | 6% | <i>\$819.20</i> |
| EWP Premier NBD AHR 16704T | 98004-16704T | \$ 1,040.00 | 6% | <i>\$984.93</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR 16705 | 98004-16705 | \$ 750.00 | 6% | <i>\$710.29</i> |
| EWP Premier NBD AHR 16705T | 98004-16705T | \$ 903.00 | 6% | <i>\$855.19</i> |
| EWP Premier NBD AHR 16706 | 98004-16706 | \$ 1,136.00 | 6% | <i>\$1,075.85</i> |
| EWP Premier NBD AHR 16706T | 98004-16706T | \$ 1,368.00 | 6% | <i>\$1,295.56</i> |
| EWP Premier NBD AHR 16710 | 98004-16710 | \$ 226.00 | 6% | <i>\$214.03</i> |
| EWP Premier NBD AHR 16710T | 98004-16710T | \$ 280.00 | 6% | <i>\$265.17</i> |
| EWP Premier NBD AHR 16711 | 98004-16711 | \$ 100.00 | 6% | <i>\$94.71</i> |
| EWP Premier NBD AHR 16711T | 98004-16711T | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier NBD AHR 16712 | 98004-16712 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier NBD AHR 16712T | 98004-16712T | \$ 156.00 | 6% | <i>\$147.74</i> |
| EWP Premier NBD AHR 16713 | 98004-16713 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR 16713T | 98004-16713T | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR 16715 | 98004-16715 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD AHR 16715T | 98004-16715T | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier NBD AHR 16716 | 98004-16716 | \$ 397.00 | 6% | <i>\$375.98</i> |
| EWP Premier NBD AHR 16716T | 98004-16716T | \$ 469.00 | 6% | <i>\$444.17</i> |
| EWP Premier NBD AHR 16717 | 98004-16717 | \$ 602.00 | 6% | <i>\$570.12</i> |
| EWP Premier NBD AHR 16718 | 98004-16718 | \$ 429.00 | 6% | <i>\$406.28</i> |
| EWP Premier NBD AHR 16718T | 98004-16718T | \$ 509.00 | 6% | <i>\$482.05</i> |
| EWP Premier NBD AHR 16719 | 98004-16719 | \$ 638.00 | 6% | <i>\$604.22</i> |
| EWP Premier NBD AHR 16719T | 98004-16719T | \$ 767.00 | 6% | <i>\$726.39</i> |
| EWP Premier NBD AHR 16720 | 98004-16720 | \$ 991.00 | 6% | <i>\$938.53</i> |
| EWP Premier NBD AHR 16720T | 98004-16720T | \$ 1,152.00 | 6% | <i>\$1,091.00</i> |
| EWP Premier NBD AHR 16756 | 98004-16756 | \$ 723.00 | 6% | <i>\$684.72</i> |
| EWP Premier NBD AHR 16756T | 98004-16756T | \$ 860.00 | 6% | <i>\$814.46</i> |
| EWP Premier NBD AHR 16757 | 98004-16757 | \$ 685.00 | 6% | <i>\$648.73</i> |
| EWP Premier NBD AHR 16757T | 98004-16757T | \$ 804.00 | 6% | <i>\$761.43</i> |
| EWP Premier NBD AHR 16790 | 98004-16790 | \$ 1,536.00 | 6% | <i>\$1,454.67</i> |
| EWP Premier NBD AHR 16791 | 98004-16791 | \$ 1,981.00 | 6% | <i>\$1,876.11</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR 16801 | 98004-16801 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier NBD AHR 16802 | 98004-16802 | \$ 230.00 | 6% | <i>\$217.82</i> |
| EWP Premier NBD AHR 16803 | 98004-16803 | \$ 237.00 | 6% | <i>\$224.45</i> |
| EWP Premier NBD AHR 16804 | 98004-16804 | \$ 292.00 | 6% | <i>\$276.54</i> |
| EWP Premier NBD AHR 16805 | 98004-16805 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier NBD AHR 16806 | 98004-16806 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier NBD AHR 17101 | 98004-17101 | \$ 2,909.00 | 6% | <i>\$2,754.97</i> |
| EWP Premier NBD AHR 17101T | 98004-17101T | \$ 3,641.00 | 6% | <i>\$3,448.21</i> |
| EWP Premier NBD AHR 17102 | 98004-17102 | \$ 2,909.00 | 6% | <i>\$2,754.97</i> |
| EWP Premier NBD AHR 17102T | 98004-17102T | \$ 3,641.00 | 6% | <i>\$3,448.21</i> |
| EWP Premier NBD AHR 17103 | 98004-17103 | \$ 2,027.00 | 6% | <i>\$1,919.67</i> |
| EWP Premier NBD AHR 17103C | 98004-17103C | \$ 1,967.00 | 6% | <i>\$1,862.85</i> |
| EWP Premier NBD AHR 17103T | 98004-17103T | \$ 2,540.00 | 6% | <i>\$2,405.51</i> |
| EWP Premier NBD AHR 17104 | 98004-17104 | \$ 2,027.00 | 6% | <i>\$1,919.67</i> |
| EWP Premier NBD AHR 17104T | 98004-17104T | \$ 2,540.00 | 6% | <i>\$2,405.51</i> |
| EWP Premier NBD AHR 17121 | 98004-17121 | \$ 584.00 | 6% | <i>\$553.08</i> |
| EWP Premier NBD AHR 17122 | 98004-17122 | \$ 360.00 | 6% | <i>\$340.94</i> |
| EWP Premier NBD AHR 17200 | 98004-17200 | \$ 4,569.00 | 6% | <i>\$4,327.07</i> |
| EWP Premier NBD AHR 17200T | 98004-17200T | \$ 5,229.00 | 6% | <i>\$4,952.12</i> |
| EWP Premier NBD AHR 17201 | 98004-17201 | \$ 4,569.00 | 6% | <i>\$4,327.07</i> |
| EWP Premier NBD AHR 17201T | 98004-17201T | \$ 5,229.00 | 6% | <i>\$4,952.12</i> |
| EWP Premier NBD AHR 17202 | 98004-17202 | \$ 4,569.00 | 6% | <i>\$4,327.07</i> |
| EWP Premier NBD AHR 17202T | 98004-17202T | \$ 5,229.00 | 6% | <i>\$4,952.12</i> |
| EWP Premier NBD AHR 17203 | 98004-17203 | \$ 4,639.00 | 6% | <i>\$4,393.36</i> |
| EWP Premier NBD AHR 17203T | 98004-17203T | \$ 5,301.00 | 6% | <i>\$5,020.31</i> |
| EWP Premier NBD AHR 17204 | 98004-17204 | \$ 4,639.00 | 6% | <i>\$4,393.36</i> |
| EWP Premier NBD AHR 17204T | 98004-17204T | \$ 5,301.00 | 6% | <i>\$5,020.31</i> |
| EWP Premier NBD AHR 17205 | 98004-17205 | \$ 4,600.00 | 6% | <i>\$4,356.43</i> |
| EWP Premier NBD AHR 17205T | 98004-17205T | \$ 5,263.00 | 6% | <i>\$4,984.32</i> |
| EWP Premier NBD AHR 17206 | 98004-17206 | \$ 4,600.00 | 6% | <i>\$4,356.43</i> |

| | | | | |
|-----------------------------------|---------------------|-------------|----|------------|
| EWP Premier NBD AHR 17206T | 98004-17206T | \$ 5,263.00 | 6% | \$4,984.32 |
| EWP Premier NBD AHR 17300 | 98004-17300 | \$ 3,037.00 | 6% | \$2,876.19 |
| EWP Premier NBD AHR 17310 | 98004-17310 | \$ 2,758.00 | 6% | \$2,611.96 |
| EWP Premier NBD AHR 17310T | 98004-17310T | \$ 3,314.00 | 6% | \$3,138.52 |
| EWP Premier NBD AHR 17350 | 98004-17350 | \$ 2,820.00 | 6% | \$2,670.68 |
| EWP Premier NBD AHR 17360 | 98004-17360 | \$ 3,473.00 | 6% | \$3,289.10 |
| EWP Premier NBD AHR 17401 | 98004-17401 | \$ 432.00 | 6% | \$409.13 |
| EWP Premier NBD AHR 17401G | 98004-17401G | \$ 524.00 | 6% | \$496.25 |
| EWP Premier NBD AHR 17401T | 98004-17401T | \$ 496.00 | 6% | \$469.74 |
| EWP Premier NBD AHR 17402 | 98004-17402 | \$ 605.00 | 6% | \$572.97 |
| EWP Premier NBD AHR 17402G | 98004-17402G | \$ 693.00 | 6% | \$656.31 |
| EWP Premier NBD AHR 17402T | 98004-17402T | \$ 657.00 | 6% | \$622.21 |
| EWP Premier NBD AHR 17403 | 98004-17403 | \$ 670.00 | 6% | \$634.52 |
| EWP Premier NBD AHR 17404 | 98004-17404 | \$ 320.00 | 6% | \$303.06 |
| EWP Premier NBD AHR 17405 | 98004-17405 | \$ 399.00 | 6% | \$377.87 |
| EWP Premier NBD AHR 17700 | 98004-17700 | \$ 5,353.00 | 6% | \$5,069.56 |
| EWP Premier NBD AHR 17701 | 98004-17701 | \$ 4,708.00 | 6% | \$4,458.71 |
| EWP Premier NBD AHR 17702 | 98004-17702 | \$ 4,708.00 | 6% | \$4,458.71 |
| EWP Premier NBD AHR 17703 | 98004-17703 | \$ 5,156.00 | 6% | \$4,882.99 |
| EWP Premier NBD AHR 17704 | 98004-17704 | \$ 5,156.00 | 6% | \$4,882.99 |
| EWP Premier NBD AHR 17705 | 98004-17705 | \$ 4,745.00 | 6% | \$4,493.75 |
| EWP Premier NBD AHR 17706 | 98004-17706 | \$ 4,745.00 | 6% | \$4,493.75 |
| EWP Premier NBD AHR 17800 | 98004-17800 | \$ 5,470.00 | 6% | \$5,180.36 |
| EWP Premier NBD AHR 17810 | 98004-17810 | \$ 4,370.00 | 6% | \$4,138.61 |
| EWP Premier NBD AHR 18101 | 98004-18101 | \$ 286.00 | 6% | \$270.86 |
| EWP Premier NBD AHR 18102 | 98004-18102 | \$ 366.00 | 6% | \$346.62 |
| EWP Premier NBD AHR 18103 | 98004-18103 | \$ 400.00 | 6% | \$378.82 |
| EWP Premier NBD AHR 18104 | 98004-18104 | \$ 569.00 | 6% | \$538.87 |
| EWP Premier NBD AHR 18104- 6PK | 98004-18104- 6PK | \$ 3,314.00 | 6% | \$3,138.52 |
| EWP Premier NBD AHR 18202 | 98004-18202 | \$ 214.00 | 6% | \$202.67 |
| EWP Premier NBD AHR 30135 | 98004-30135 | \$ 558.00 | 6% | \$528.45 |
| EWP Premier NBD AHR 30136 | 98004-30136 | \$ 4,329.00 | 6% | \$4,099.78 |
| EWP Premier NBD AHR 30137 | 98004-30137 | \$ 1,090.00 | 6% | \$1,032.28 |
| EWP Premier NBD AHR 30138 | 98004-30138 | \$ 5,003.00 | 6% | \$4,738.09 |
| EWP Premier NBD AHR 30139 | 98004-30139 | \$ 9,147.00 | 6% | \$8,662.67 |

| | | | | |
|---------------------------|-------------|-----------|----|----------|
| EWP Premier NBD AHR 30912 | 98004-30912 | \$ 58.00 | 6% | \$54.93 |
| EWP Premier NBD AHR 30913 | 98004-30913 | \$ 58.00 | 6% | \$54.93 |
| EWP Premier NBD AHR 31012 | 98004-31012 | \$ 100.00 | 6% | \$94.71 |
| EWP Premier NBD AHR 31013 | 98004-31013 | \$ 100.00 | 6% | \$94.71 |
| EWP Premier NBD AHR 31014 | 98004-31014 | \$ 100.00 | 6% | \$94.71 |
| EWP Premier NBD AHR 31015 | 98004-31015 | \$ 100.00 | 6% | \$94.71 |
| EWP Premier NBD AHR 31016 | 98004-31016 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD AHR 31017 | 98004-31017 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD AHR 31018 | 98004-31018 | \$ 355.00 | 6% | \$336.20 |
| EWP Premier NBD AHR 31019 | 98004-31019 | \$ 355.00 | 6% | \$336.20 |
| EWP Premier NBD AHR 31025 | 98004-31025 | \$ 65.00 | 6% | \$61.56 |
| EWP Premier NBD AHR 31026 | 98004-31026 | \$ 65.00 | 6% | \$61.56 |
| EWP Premier NBD AHR 31028 | 98004-31028 | \$ 67.00 | 6% | \$63.45 |
| EWP Premier NBD AHR 31029 | 98004-31029 | \$ 76.00 | 6% | \$71.98 |
| EWP Premier NBD AHR 31031 | 98004-31031 | \$ 82.00 | 6% | \$77.66 |
| EWP Premier NBD AHR 31032 | 98004-31032 | \$ 82.00 | 6% | \$77.66 |
| EWP Premier NBD AHR 31034 | 98004-31034 | \$ 98.00 | 6% | \$92.81 |
| EWP Premier NBD AHR 31035 | 98004-31035 | \$ 98.00 | 6% | \$92.81 |
| EWP Premier NBD AHR 31050 | 98004-31050 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 31051 | 98004-31051 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 31055 | 98004-31055 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 31056 | 98004-31056 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37101 | 98004-37101 | \$ 58.00 | 6% | \$54.93 |
| EWP Premier NBD AHR 37102 | 98004-37102 | \$ 58.00 | 6% | \$54.93 |
| EWP Premier NBD AHR 37103 | 98004-37103 | \$ 58.00 | 6% | \$54.93 |
| EWP Premier NBD AHR 37111 | 98004-37111 | \$ 67.00 | 6% | \$63.45 |
| EWP Premier NBD AHR 37112 | 98004-37112 | \$ 67.00 | 6% | \$63.45 |
| EWP Premier NBD AHR 37113 | 98004-37113 | \$ 82.00 | 6% | \$77.66 |
| EWP Premier NBD AHR 37114 | 98004-37114 | \$ 82.00 | 6% | \$77.66 |
| EWP Premier NBD AHR 37115 | 98004-37115 | \$ 67.00 | 6% | \$63.45 |
| EWP Premier NBD AHR 37116 | 98004-37116 | \$ 82.00 | 6% | \$77.66 |
| EWP Premier NBD AHR 37117 | 98004-37117 | \$ 67.00 | 6% | \$63.45 |
| EWP Premier NBD AHR 37121 | 98004-37121 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37122 | 98004-37122 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37123 | 98004-37123 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37124 | 98004-37124 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37125 | 98004-37125 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37126 | 98004-37126 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37129 | 98004-37129 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 37130 | 98004-37130 | \$ 129.00 | 6% | \$122.17 |
| EWP Premier NBD AHR 39031 | 98004-39031 | \$ 113.00 | 6% | \$107.02 |
| EWP Premier NBD AHR 39032 | 98004-39032 | \$ 149.00 | 6% | \$141.11 |

| | | | | |
|-------------------------------------|-----------------------|-------------|-----|-------------------|
| EWP Premier NBD AHR 39033 | 98004-39033 | \$ 113.00 | 6% | <i>\$107.02</i> |
| EWP Premier NBD AHR 39034 | 98004-39034 | \$ 113.00 | 6% | <i>\$107.02</i> |
| EWP Premier NBD AHR 39035 | 98004-39035 | \$ 660.00 | 6% | <i>\$625.05</i> |
| EWP Premier NBD AHR 39036 | 98004-39036 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD AHR 39037 | 98004-39037 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD AHR 39038 | 98004-39038 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR 39039 | 98004-39039 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR 39505 | 98004-39505 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR 4120-24MW-4Y | 98004-4120-24MW-4Y | \$ 690.00 | 6% | <i>\$653.46</i> |
| EWP Premier NBD AHR 4120-48MW-4Y | 98004-4120-48MW-4Y | \$ 920.00 | 6% | <i>\$871.29</i> |
| EWP Premier NBD AHR 4120C | 98004-4120C | \$ 6,164.00 | 10% | <i>\$5,589.21</i> |
| EWP Premier NBD AHR 4120C-1 | 98004-4120C-1 | \$ 6,793.00 | 6% | <i>\$6,433.31</i> |
| EWP Premier NBD AHR 41216 | 98004-41216 | \$ 1,844.00 | 6% | <i>\$1,746.36</i> |
| EWP Premier NBD AHR 4220-12P-4X | 98004-4220-12P-4X | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier NBD AHR 4220-12T-4X | 98004-4220-12T-4X | \$ 154.00 | 6% | <i>\$145.85</i> |
| EWP Premier NBD AHR 4220-24P-4X | 98004-4220-24P-4X | \$ 280.00 | 6% | <i>\$265.17</i> |
| EWP Premier NBD AHR 4220-24T-4X | 98004-4220-24T-4X | \$ 217.00 | 6% | <i>\$205.51</i> |
| EWP Premier NBD AHR 4220-48P-4X | 98004-4220-48P-4X | \$ 421.00 | 6% | <i>\$398.71</i> |
| EWP Premier NBD AHR 4220-48T-4X | 98004-4220-48T-4X | \$ 316.00 | 6% | <i>\$299.27</i> |
| EWP Premier NBD AHR 4220-4MW-20P-4X | 98004-4220-4MW-20P-4X | \$ 386.00 | 6% | <i>\$365.56</i> |
| EWP Premier NBD AHR 4220-4MW-8P-4X | 98004-4220-4MW-8P-4X | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier NBD AHR 4220-8MW-40P-4X | 98004-4220-8MW-40P-4X | \$ 561.00 | 6% | <i>\$531.30</i> |
| EWP Premier NBD AHR 4220-8X | 98004-4220-8X | \$ 294.00 | 6% | <i>\$278.43</i> |
| EWP Premier NBD AHR 48001 | 98004-48001 | \$ 7,643.00 | 6% | <i>\$7,238.30</i> |
| EWP Premier NBD AHR 48038 | 98004-48038 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |
| EWP Premier NBD AHR 48039 | 98004-48039 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |
| EWP Premier NBD AHR 48040 | 98004-48040 | \$ 2,781.00 | 6% | <i>\$2,633.75</i> |
| EWP Premier NBD AHR 48041 | 98004-48041 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |
| EWP Premier NBD AHR 48046 | 98004-48046 | \$ 4,022.00 | 6% | <i>\$3,809.04</i> |

| | | | | |
|---|---------------------------|--------------|----|--------------------|
| EWP Premier NBD AHR 48047 | 98004-48047 | \$ 10,710.00 | 6% | <i>\$10,142.91</i> |
| EWP Premier NBD AHR 48051 | 98004-48051 | \$ 7,369.00 | 6% | <i>\$6,978.81</i> |
| EWP Premier NBD AHR 48061 | 98004-48061 | \$ 8,609.00 | 6% | <i>\$8,153.15</i> |
| EWP Premier NBD AHR 48062 | 98004-48062 | \$ 13,771.00 | 6% | <i>\$13,041.83</i> |
| EWP Premier NBD AHR 5320-16P-4XE | 98004-5320-16P-4XE | \$ 285.00 | 6% | <i>\$269.91</i> |
| EWP Premier NBD AHR 5320-16P-4XE-DC | 98004-5320-16P-4XE-DC | \$ 345.00 | 6% | <i>\$326.73</i> |
| EWP Premier NBD AHR 5320-24P-8XE | 98004-5320-24P-8XE | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWP Premier NBD AHR 5320-24T-24S-4XE-XT | 98004-5320-24T-24S-4XE-XT | \$ 344.00 | 6% | <i>\$325.79</i> |
| EWP Premier NBD AHR 5320-24T-4X-XT | 98004-5320-24T-4X-XT | \$ 185.00 | 6% | <i>\$175.20</i> |
| EWP Premier NBD AHR 5320-24T-8XE | 98004-5320-24T-8XE | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD AHR 5320-48P-8XE | 98004-5320-48P-8XE | \$ 514.00 | 6% | <i>\$486.78</i> |
| EWP Premier NBD AHR 5320-48T-8XE | 98004-5320-48T-8XE | \$ 364.00 | 6% | <i>\$344.73</i> |
| EWP Premier NBD AHR 5420F-16MW-32P-4XE | 98004-5420F-16MW-32P-4XE | \$ 1,057.00 | 6% | <i>\$1,001.03</i> |
| EWP Premier NBD AHR 5420F-16W-32P-4XE | 98004-5420F-16W-32P-4XE | \$ 894.00 | 6% | <i>\$846.66</i> |
| EWP Premier NBD AHR 5420F-24P-4XE | 98004-5420F-24P-4XE | \$ 444.00 | 6% | <i>\$420.49</i> |
| EWP Premier NBD AHR 5420F-24S-4XE | 98004-5420F-24S-4XE | \$ 504.00 | 6% | <i>\$477.31</i> |
| EWP Premier NBD AHR 5420F-24T-4XE | 98004-5420F-24T-4XE | \$ 367.00 | 6% | <i>\$347.57</i> |
| EWP Premier NBD AHR 5420F-48P-4XE | 98004-5420F-48P-4XE | \$ 694.00 | 6% | <i>\$657.25</i> |
| EWP Premier NBD AHR 5420F-48P-4XL | 98004-5420F-48P-4XL | \$ 808.00 | 6% | <i>\$765.22</i> |
| EWP Premier NBD AHR 5420F-48T-4XE | 98004-5420F-48T-4XE | \$ 509.00 | 6% | <i>\$482.05</i> |
| EWP Premier NBD AHR 5420F-8W-16P-4XE | 98004-5420F-8W-16P-4XE | \$ 536.00 | 6% | <i>\$507.62</i> |

| | | | | |
|---|---------------------------|-------------|-----|-------------------|
| EWP Premier NBD AHR 5420M-16MW-32P-4YE | 98004-5420M-16MW-32P-4YE | \$ 1,145.00 | 6% | <i>\$1,084.37</i> |
| EWP Premier NBD AHR 5420M-24T-4YE | 98004-5420M-24T-4YE | \$ 500.00 | 6% | <i>\$473.53</i> |
| EWP Premier NBD AHR 5420M-24W-4YE | 98004-5420M-24W-4YE | \$ 456.00 | 6% | <i>\$431.85</i> |
| EWP Premier NBD AHR 5420M-48T-4YE | 98004-5420M-48T-4YE | \$ 682.00 | 6% | <i>\$645.89</i> |
| EWP Premier NBD AHR 5420M-48W-4YE | 98004-5420M-48W-4YE | \$ 753.00 | 6% | <i>\$713.13</i> |
| EWP PREMIER NBD AHR 5520-12MW-36W | 98004-5520-12MW-36W | \$ 1,067.00 | 6% | <i>\$1,010.50</i> |
| EWP PREMIER NBD AHR 5520-24T | 98004-5520-24T | \$ 431.00 | 6% | <i>\$408.18</i> |
| EWP PREMIER NBD AHR 5520-24T-ACDC-BASE | 98004-5520-24T-ACDC-BASE | \$ 431.00 | 6% | <i>\$408.18</i> |
| EWP PREMIER NBD AHR 5520-24T-BASE | 98004-5520-24T-BASE | \$ 431.00 | 10% | <i>\$390.81</i> |
| EWP PREMIER NBD AHR 5520-24W | 98004-5520-24W | \$ 658.00 | 6% | <i>\$623.16</i> |
| EWP PREMIER NBD AHR 5520-24X | 98004-5520-24X | \$ 1,240.00 | 6% | <i>\$1,174.34</i> |
| EWP PREMIER NBD AHR 5520-24X-ACDC-BASE | 98004-5520-24X-ACDC-BASE | \$ 1,240.00 | 6% | <i>\$1,174.34</i> |
| EWP PREMIER NBD AHR 5520-24X-BASE | 98004-5520-24X-BASE | \$ 1,240.00 | 10% | <i>\$1,124.37</i> |
| EWP PREMIER NBD AHR 5520-48SE | 98004-5520-48SE | \$ 1,277.00 | 6% | <i>\$1,209.38</i> |
| EWP PREMIER NBD AHR 5520-48SE-ACDC-BASE | 98004-5520-48SE-ACDC-BASE | \$ 1,277.00 | 6% | <i>\$1,209.38</i> |
| EWP PREMIER NBD AHR 5520-48SE-BASE | 98004-5520-48SE-BASE | \$ 1,277.00 | 10% | <i>\$1,157.92</i> |
| EWP PREMIER NBD AHR 5520-48T | 98004-5520-48T | \$ 727.00 | 6% | <i>\$688.51</i> |
| EWP PREMIER NBD AHR 5520-48T-ACDC-BASE | 98004-5520-48T-ACDC-BASE | \$ 727.00 | 6% | <i>\$688.51</i> |
| EWP PREMIER NBD AHR 5520-48T-BASE | 98004-5520-48T-BASE | \$ 727.00 | 10% | <i>\$659.21</i> |

| | | | | |
|--|--------------------------|-------------|----|-------------------|
| EWP PREMIER NBD AHR 5520-48W | 98004-5520-48W | \$ 853.00 | 6% | <i>\$807.83</i> |
| EWP Premier NBD AHR 5720-24MW | 98004-5720-24MW | \$ 1,305.00 | 6% | <i>\$1,235.90</i> |
| EWP Premier NBD AHR 5720-24MXW | 98004-5720-24MXW | \$ 1,764.00 | 6% | <i>\$1,670.60</i> |
| EWP Premier NBD AHR 5720-48MW | 98004-5720-48MW | \$ 1,543.00 | 6% | <i>\$1,461.30</i> |
| EWP Premier NBD AHR 5720-48MXW | 98004-5720-48MXW | \$ 2,224.00 | 6% | <i>\$2,106.24</i> |
| EWP Premier NBD AHR 7520-48XT-6C | 98004-7520-48XT-6C | \$ 2,383.00 | 6% | <i>\$2,256.82</i> |
| EWP Premier NBD AHR 7520-48XT-6C-AC-F | 98004-7520-48XT-6C-AC-F | \$ 2,383.00 | 6% | <i>\$2,256.82</i> |
| EWP Premier NBD AHR 7520-48XT-6C-AC-R | 98004-7520-48XT-6C-AC-R | \$ 2,383.00 | 6% | <i>\$2,256.82</i> |
| EWP Premier NBD AHR 7520-48Y-8C | 98004-7520-48Y-8C | \$ 2,212.00 | 6% | <i>\$2,094.87</i> |
| EWP Premier NBD AHR 7520-48Y-8C-AC-F | 98004-7520-48Y-8C-AC-F | \$ 2,212.00 | 6% | <i>\$2,094.87</i> |
| EWP Premier NBD AHR 7520-48Y-8C-AC-R | 98004-7520-48Y-8C-AC-R | \$ 2,212.00 | 6% | <i>\$2,094.87</i> |
| EWP PREMIER NBD AHR 7520-48YE-8CE | 98004-7520-48YE-8CE | \$ 2,591.00 | 6% | <i>\$2,453.81</i> |
| EWP PREMIER NBD AHR 7520-48YE-8CE-AC-F | 98004-7520-48YE-8CE-AC-F | \$ 2,591.00 | 6% | <i>\$2,453.81</i> |
| EWP PREMIER NBD AHR 7520-48YE-8CE-AC-R | 98004-7520-48YE-8CE-AC-R | \$ 2,591.00 | 6% | <i>\$2,453.81</i> |
| EWP Premier NBD AHR 7720-32C | 98004-7720-32C | \$ 2,784.00 | 6% | <i>\$2,636.59</i> |
| EWP Premier NBD AHR 7720-32C-AC-F | 98004-7720-32C-AC-F | \$ 2,784.00 | 6% | <i>\$2,636.59</i> |
| EWP Premier NBD AHR 7720-32C-AC-R | 98004-7720-32C-AC-R | \$ 2,784.00 | 6% | <i>\$2,636.59</i> |
| EWP Premier NBD AHR 8520-48XT-6C | 98004-8520-48XT-6C | \$ 2,973.00 | 6% | <i>\$2,815.58</i> |
| EWP Premier NBD AHR 8520-48XT-6C-AC-F | 98004-8520-48XT-6C-AC-F | \$ 2,973.00 | 6% | <i>\$2,815.58</i> |

| | | | | |
|---------------------------------------|-------------------------|--------------|-----|-------------|
| EWP Premier NBD AHR 8520-48XT-6C-AC-R | 98004-8520-48XT-6C-AC-R | \$ 2,973.00 | 6% | \$2,815.58 |
| EWP Premier NBD AHR 8520-48XT-6C-DC-F | 98004-8520-48XT-6C-DC-F | \$ 2,973.00 | 6% | \$2,815.58 |
| EWP Premier NBD AHR 8520-48XT-6C-DC-R | 98004-8520-48XT-6C-DC-R | \$ 2,973.00 | 6% | \$2,815.58 |
| EWP Premier NBD AHR 8520-48Y-8C | 98004-8520-48Y-8C | \$ 3,058.00 | 6% | \$2,896.08 |
| EWP Premier NBD AHR 8520-48Y-8C-AC-F | 98004-8520-48Y-8C-AC-F | \$ 3,058.00 | 6% | \$2,896.08 |
| EWP Premier NBD AHR 8520-48Y-8C-AC-R | 98004-8520-48Y-8C-AC-R | \$ 3,058.00 | 6% | \$2,896.08 |
| EWP Premier NBD AHR 8520-48Y-8C-DC-F | 98004-8520-48Y-8C-DC-F | \$ 3,058.00 | 6% | \$2,896.08 |
| EWP Premier NBD AHR 8520-48Y-8C-DC-R | 98004-8520-48Y-8C-DC-R | \$ 3,058.00 | 6% | \$2,896.08 |
| EWP Premier NBD AHR 86100 | 98004-86100 | \$ 6,323.00 | 6% | \$5,988.20 |
| EWP Premier NBD AHR 86101 | 98004-86101 | \$ 8,692.00 | 6% | \$8,231.76 |
| EWP Premier NBD AHR 87100 | 98004-87100 | \$ 3,926.00 | 6% | \$3,718.12 |
| EWP Premier NBD AHR 87101 | 98004-87101 | \$ 6,042.00 | 6% | \$5,722.08 |
| EWP Premier NBD AHR 8720-32C | 98004-8720-32C | \$ 3,386.00 | 6% | \$3,206.71 |
| EWP Premier NBD AHR 8720-32C-AC-F | 98004-8720-32C-AC-F | \$ 3,386.00 | 6% | \$3,206.71 |
| EWP Premier NBD AHR 8720-32C-AC-R | 98004-8720-32C-AC-R | \$ 3,386.00 | 6% | \$3,206.71 |
| EWP Premier NBD AHR 8720-32C-DC-F | 98004-8720-32C-DC-F | \$ 3,386.00 | 6% | \$3,206.71 |
| EWP Premier NBD AHR 8720-32C-DC-R | 98004-8720-32C-DC-R | \$ 3,386.00 | 6% | \$3,206.71 |
| EWP Premier NBD AHR 8806 | 98004-8806 | \$ 1,913.00 | 6% | \$1,811.71 |
| EWP Premier NBD AHR 8810 | 98004-8810 | \$ 4,974.00 | 6% | \$4,710.63 |
| EWP Premier NBD AHR 88100 | 98004-88100 | \$ 7,147.00 | 6% | \$6,768.57 |
| EWP Premier NBD AHR 8820-40C | 98004-8820-40C | \$ 13,549.00 | 10% | \$12,285.56 |
| EWP Premier NBD AHR 8820-40C-AC-F | 98004-8820-40C-AC-F | \$ 13,549.00 | 10% | \$12,285.56 |
| EWP Premier NBD AHR 8820-40C-AC-R | 98004-8820-40C-AC-R | \$ 13,549.00 | 10% | \$12,285.56 |

| | | | | |
|---------------------------------------|-------------------------|---------------|-----|---------------------|
| EWP Premier NBD AHR 8820-40C-DC-F | 98004-8820-40C-DC-F | \$ 13,549.00 | 10% | <i>\$12,285.56</i> |
| EWP Premier NBD AHR 8820-40C-DC-R | 98004-8820-40C-DC-R | \$ 13,549.00 | 10% | <i>\$12,285.56</i> |
| EWP Premier NBD AHR 8820-80C | 98004-8820-80C | \$ 24,395.00 | 10% | <i>\$22,120.17</i> |
| EWP Premier NBD AHR 8820-80C-AC-F | 98004-8820-80C-AC-F | \$ 24,395.00 | 10% | <i>\$22,120.17</i> |
| EWP Premier NBD AHR 8820-80C-AC-R | 98004-8820-80C-AC-R | \$ 24,395.00 | 10% | <i>\$22,120.17</i> |
| EWP Premier NBD AHR 8820-80C-DC-F | 98004-8820-80C-DC-F | \$ 24,395.00 | 10% | <i>\$22,120.17</i> |
| EWP Premier NBD AHR 8820-80C-DC-R | 98004-8820-80C-DC-R | \$ 24,395.00 | 10% | <i>\$22,120.17</i> |
| EWP Premier NBD AHR 9920-16C | 98004-9920-16C | \$ 10,558.00 | 6% | <i>\$9,998.95</i> |
| EWP Premier NBD AHR 9920-4D | 98004-9920-4D | \$ 10,558.00 | 6% | <i>\$9,998.95</i> |
| EWP Premier NBD AHR 9920-NPB-8 | 98004-9920-NPB-8 | \$ 19,205.00 | 6% | <i>\$18,188.10</i> |
| EWP Premier NBD AHR A10148 | 98004-A10148 | \$ 3,454.00 | 6% | <i>\$3,271.11</i> |
| EWP Premier NBD AHR A10149 | 98004-A10149 | \$ 6,578.00 | 6% | <i>\$6,229.69</i> |
| EWP Premier NBD AHR A10152 | 98004-A10152 | \$ 6,578.00 | 6% | <i>\$6,229.69</i> |
| EWP Premier NBD AHR A10153 | 98004-A10153 | \$ 191,200.00 | 6% | <i>\$181,075.96</i> |
| EWP Premier NBD AHR A10154 | 98004-A10154 | \$ 19,682.00 | 6% | <i>\$18,639.84</i> |
| EWP Premier NBD AHR A10155 | 98004-A10155 | \$ 7,094.00 | 6% | <i>\$6,718.37</i> |
| EWP Premier NBD AHR A10157 | 98004-A10157 | \$ 12,296.00 | 6% | <i>\$11,644.93</i> |
| EWP Premier NBD AHR A10175 | 98004-A10175 | \$ 7,026.00 | 6% | <i>\$6,653.97</i> |
| EWP Premier NBD AHR A10176 | 98004-A10176 | \$ 10,539.00 | 6% | <i>\$9,980.96</i> |
| EWP Premier NBD AHR AH-AP-1130-AC-CE | 98004-AH-AP-1130-AC-CE | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-1130-AC-FCC | 98004-AH-AP-1130-AC-FCC | \$ 80.00 | 6% | <i>\$75.76</i> |

| | | | | |
|---------------------------------------|-------------------------|----------|----|---------|
| EWP Premier NBD AHR AH-AP-1130-AC-W | 98004-AH-AP-1130-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-121-N-CE | 98004-AH-AP-121-N-CE | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-121-N-FCC | 98004-AH-AP-121-N-FCC | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-121-N-W | 98004-AH-AP-121-N-W | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-121-N-W-NEC | 98004-AH-AP-121-N-W-NEC | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-122-AC-CAN | 98004-AH-AP-122-AC-CAN | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-122-AC-CE | 98004-AH-AP-122-AC-CE | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-122-AC-FCC | 98004-AH-AP-122-AC-FCC | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-122-AC-W | 98004-AH-AP-122-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-122X-AC-CAN | 98004-AH-AP-122X-AC-CAN | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-122X-AC-CE | 98004-AH-AP-122X-AC-CE | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-122X-AC-FCC | 98004-AH-AP-122X-AC-FCC | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-122X-AC-W | 98004-AH-AP-122X-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-130-AC-CE | 98004-AH-AP-130-AC-CE | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-130-AC-FCC | 98004-AH-AP-130-AC-FCC | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-130-AC-W | 98004-AH-AP-130-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-141-N-CE | 98004-AH-AP-141-N-CE | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-141-N-FCC | 98004-AH-AP-141-N-FCC | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-141-N-W | 98004-AH-AP-141-N-W | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-141-N-W-NEC | 98004-AH-AP-141-N-W-NEC | \$ 87.00 | 6% | \$82.39 |

| | | | | |
|---------------------------------------|-------------------------|----------|----|---------|
| EWP Premier NBD AHR AH-AP-150W-AC-CAN | 98004-AH-AP-150W-AC-CAN | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-150W-AC-CE | 98004-AH-AP-150W-AC-CE | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-150W-AC-FCC | 98004-AH-AP-150W-AC-FCC | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-150W-AC-W | 98004-AH-AP-150W-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-170-N-W | 98004-AH-AP-170-N-W | \$ 86.00 | 6% | \$81.45 |
| EWP Premier NBD AHR AH-AP-230-AC-CE | 98004-AH-AP-230-AC-CE | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-230-AC-FCC | 98004-AH-AP-230-AC-FCC | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-230-AC-W | 98004-AH-AP-230-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-245X-AC-CAN | 98004-AH-AP-245X-AC-CAN | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-245X-AC-CE | 98004-AH-AP-245X-AC-CE | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-245X-AC-FCC | 98004-AH-AP-245X-AC-FCC | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-245X-AC-W | 98004-AH-AP-245X-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-250-AC-CAN | 98004-AH-AP-250-AC-CAN | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-250-AC-CE | 98004-AH-AP-250-AC-CE | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-250-AC-FCC | 98004-AH-AP-250-AC-FCC | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-250-AC-W | 98004-AH-AP-250-AC-W | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-AP-330-N-FCC | 98004-AH-AP-330-N-FCC | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-330-N-W | 98004-AH-AP-330-N-W | \$ 87.00 | 6% | \$82.39 |
| EWP Premier NBD AHR AH-AP-350-N-FCC | 98004-AH-AP-350-N-FCC | \$ 87.00 | 6% | \$82.39 |

| | | | | |
|---------------------------------------|-------------------------|----------|----|----------------|
| EWP Premier NBD AHR AH-AP-350-N-W | 98004-AH-AP-350-N-W | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD AHR AH-AP-550-AC-CAN | 98004-AH-AP-550-AC-CAN | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-550-AC-CE | 98004-AH-AP-550-AC-CE | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-550-AC-FCC | 98004-AH-AP-550-AC-FCC | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-550-AC-W | 98004-AH-AP-550-AC-W | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-630-AX-CAN | 98004-AH-AP-630-AX-CAN | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-630-AX-CE | 98004-AH-AP-630-AX-CE | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-630-AX-FCC | 98004-AH-AP-630-AX-FCC | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-630-AX-W | 98004-AH-AP-630-AX-W | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-AP-650-AX-CAN | 98004-AH-AP-650-AX-CAN | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-AP-650-AX-CE | 98004-AH-AP-650-AX-CE | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-AP-650-AX-FCC | 98004-AH-AP-650-AX-FCC | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-AP-650-AX-W | 98004-AH-AP-650-AX-W | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-AP-650X-AX-CAN | 98004-AH-AP-650X-AX-CAN | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-AP-650X-AX-CE | 98004-AH-AP-650X-AX-CE | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-AP-650X-AX-FCC | 98004-AH-AP-650X-AX-FCC | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-AP-650X-AX-W | 98004-AH-AP-650X-AX-W | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD AHR AH-ATOM-CAN | 98004-AH-ATOM-CAN | \$ 79.00 | 6% | <i>\$74.82</i> |
| EWP Premier NBD AHR AH-ATOM-CE-EU | 98004-AH-ATOM-CE-EU | \$ 83.00 | 6% | <i>\$78.61</i> |

| | | | | |
|---------------------------------------|-------------------------|----------|-----|----------------|
| EWP Premier NBD AHR AH-ATOM-CE-UK | 98004-AH-ATOM-CE-UK | \$ 83.00 | 6% | <i>\$78.61</i> |
| EWP Premier NBD AHR AH-ATOM-FCC | 98004-AH-ATOM-FCC | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AH-ATOM-W | 98004-AH-ATOM-W | \$ 79.00 | 6% | <i>\$74.82</i> |
| EWP Premier NBD AHR AH-ATOM-W-EU | 98004-AH-ATOM-W-EU | \$ 83.00 | 6% | <i>\$78.61</i> |
| EWP Premier NBD AHR AH-ATOM-W-UK | 98004-AH-ATOM-W-UK | \$ 83.00 | 6% | <i>\$78.61</i> |
| EWP Premier NBD AHR AH-BR-200WP-N-CE | 98004-AH-BR-200WP-N-CE | \$ 72.00 | 10% | <i>\$65.29</i> |
| EWP Premier NBD AHR AH-BR-200WP-N-FCC | 98004-AH-BR-200WP-N-FCC | \$ 72.00 | 10% | <i>\$65.29</i> |
| EWP Premier NBD AHR AH-BR-200WP-N-W | 98004-AH-BR-200WP-N-W | \$ 72.00 | 10% | <i>\$65.29</i> |
| EWP Premier NBD AHR AH-SR-2024P | 98004-AH-SR-2024P | \$ 68.00 | 10% | <i>\$61.66</i> |
| EWP Premier NBD AHR AH-SR-2124P | 98004-AH-SR-2124P | \$ 68.00 | 10% | <i>\$61.66</i> |
| EWP Premier NBD AHR AH-SR-2208P-AU | 98004-AH-SR-2208P-AU | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2208P-EU | 98004-AH-SR-2208P-EU | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2208P-NA | 98004-AH-SR-2208P-NA | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2208P-UK | 98004-AH-SR-2208P-UK | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2224P-AU | 98004-AH-SR-2224P-AU | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2224P-EU | 98004-AH-SR-2224P-EU | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2224P-NA | 98004-AH-SR-2224P-NA | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2224P-UK | 98004-AH-SR-2224P-UK | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2324P-AU | 98004-AH-SR-2324P-AU | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD AHR AH-SR-2324P-EU | 98004-AH-SR-2324P-EU | \$ 80.00 | 6% | <i>\$75.76</i> |

| | | | | |
|---------------------------------------|-------------------------|-----------|----|----------|
| EWP Premier NBD AHR AH-SR-2324P-NA | 98004-AH-SR-2324P-NA | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-SR-2324P-UK | 98004-AH-SR-2324P-UK | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-SR-2348P-AU | 98004-AH-SR-2348P-AU | \$ 71.00 | 6% | \$67.24 |
| EWP Premier NBD AHR AH-SR-2348P-EU | 98004-AH-SR-2348P-EU | \$ 71.00 | 6% | \$67.24 |
| EWP Premier NBD AHR AH-SR-2348P-NA | 98004-AH-SR-2348P-NA | \$ 71.00 | 6% | \$67.24 |
| EWP Premier NBD AHR AH-SR-2348P-UK | 98004-AH-SR-2348P-UK | \$ 71.00 | 6% | \$67.24 |
| EWP Premier NBD AHR AH-XR200P-AU | 98004-AH-XR200P-AU | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR200P-EU | 98004-AH-XR200P-EU | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR200P-UK | 98004-AH-XR200P-UK | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR200P-US | 98004-AH-XR200P-US | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR600P | 98004-AH-XR600P | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR600P-AU | 98004-AH-XR600P-AU | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR600P-EU | 98004-AH-XR600P-EU | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR600P-KR | 98004-AH-XR600P-KR | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR600P-UK | 98004-AH-XR600P-UK | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AH-XR600P-US | 98004-AH-XR600P-US | \$ 80.00 | 6% | \$75.76 |
| EWP Premier NBD AHR AP-8533-68SB30-IL | 98004-AP-8533-68SB30-IL | \$ 144.00 | 6% | \$136.38 |
| EWP Premier NBD AHR AP3000-IL | 98004-AP3000-IL | \$ 52.65 | 6% | \$49.86 |
| EWP Premier NBD AHR AP3000-TN | 98004-AP3000-TN | \$ 52.65 | 6% | \$49.86 |
| EWP Premier NBD AHR AP3000-WW | 98004-AP3000-WW | \$ 52.65 | 6% | \$49.86 |

| | | | | |
|-------------------------------------|---------------------------|----------|-----|----------------|
| EWP Premier NBD AHR AP3000X-WW | 98004- AP3000X-WW | \$ 67.28 | 6% | <i>\$63.71</i> |
| EWP Premier NBD AHR AP302W-CAN | 98004- AP302W-CAN | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD AHR AP302W-EG | 98004- AP302W-EG | \$ 64.00 | 10% | <i>\$58.03</i> |
| EWP Premier NBD AHR AP302W-FCC | 98004- AP302W-FCC | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD AHR AP302W-WR | 98004- AP302W-WR | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD AHR AP305C-1-CAN | 98004-AP305C- 1-CAN | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR AP305C-1-EG | 98004-AP305C- 1-EG | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR AP305C-1-FCC | 98004-AP305C- 1-FCC | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR AP305C-1-IL | 98004-AP305C- 1-IL | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR AP305C-1-WR | 98004-AP305C- 1-WR | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR AP305C-CAN | 98004-AP305C- CAN | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305C-EG | 98004-AP305C- EG | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305C-FCC | 98004-AP305C- FCC | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305C-IL | 98004-AP305C- IL | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305C-WR | 98004-AP305C- WR | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305CX-CAN | 98004- AP305CX- CAN | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305CX-FCC | 98004- AP305CX- FCC | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305CX-IL | 98004- AP305CX-IL | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD AHR AP305CX-WR | 98004- AP305CX-WR | \$ 84.00 | 6% | <i>\$79.55</i> |

| | | | | |
|---------------------------------|-------------------|----------|-----|----------------|
| EWP Premier NBD AHR AP310e-1-WR | 98004-AP310e-1-WR | \$ 50.00 | 10% | <i>\$45.34</i> |
| EWP Premier NBD AHR AP310e-CAN | 98004-AP310e-CAN | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP310e-FCC | 98004-AP310e-FCC | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP310e-IL | 98004-AP310e-IL | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP310e-WR | 98004-AP310e-WR | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP310i-1-WR | 98004-AP310i-1-WR | \$ 50.00 | 10% | <i>\$45.34</i> |
| EWP Premier NBD AHR AP310i-CAN | 98004-AP310i-CAN | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP310i-FCC | 98004-AP310i-FCC | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP310i-IL | 98004-AP310i-IL | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP310i-WR | 98004-AP310i-WR | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR AP360e-CAN | 98004-AP360e-CAN | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR AP360e-FCC | 98004-AP360e-FCC | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR AP360e-IL | 98004-AP360e-IL | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR AP360e-WR | 98004-AP360e-WR | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR AP360i-CAN | 98004-AP360i-CAN | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR AP360i-FCC | 98004-AP360i-FCC | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR AP360i-WR | 98004-AP360i-WR | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR AP4000-1-WW | 98004-AP4000-1-WW | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR AP4000-IL | 98004-AP4000-IL | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR AP4000-WW | 98004-AP4000-WW | \$ 77.00 | 6% | <i>\$72.92</i> |

| | | | | |
|----------------------------------|--------------------|----------|-----|----------------|
| EWP Premier NBD AHR AP410C-1-CAN | 98004-AP410C-1-CAN | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier NBD AHR AP410C-1-EG | 98004-AP410C-1-EG | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier NBD AHR AP410C-1-FCC | 98004-AP410C-1-FCC | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier NBD AHR AP410C-1-IL | 98004-AP410C-1-IL | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier NBD AHR AP410C-1-WR | 98004-AP410C-1-WR | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier NBD AHR AP410C-CAN | 98004-AP410C-CAN | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AP410C-EG | 98004-AP410C-EG | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AP410C-FCC | 98004-AP410C-FCC | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AP410C-IL | 98004-AP410C-IL | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AP410C-WR | 98004-AP410C-WR | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AP410e-CAN | 98004-AP410e-CAN | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier NBD AHR AP410e-FCC | 98004-AP410e-FCC | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier NBD AHR AP410e-WR | 98004-AP410e-WR | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier NBD AHR AP410i-1-FCC | 98004-AP410i-1-FCC | \$ 88.00 | 10% | <i>\$79.79</i> |
| EWP Premier NBD AHR AP410i-1-WR | 98004-AP410i-1-WR | \$ 88.00 | 10% | <i>\$79.79</i> |
| EWP Premier NBD AHR AP410i-CAN | 98004-AP410i-CAN | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier NBD AHR AP410i-FCC | 98004-AP410i-FCC | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier NBD AHR AP410i-IL | 98004-AP410i-IL | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier NBD AHR AP410i-WR | 98004-AP410i-WR | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier NBD AHR AP460C-CAN | 98004-AP460C-CAN | \$ 82.00 | 6% | <i>\$77.66</i> |

| | | | | |
|-----------------------------------|---------------------|-----------|----|-----------------|
| EWP Premier NBD AHR AP460C-EG | 98004-AP460C-EG | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460C-FCC | 98004-AP460C-FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460C-IL | 98004-AP460C-IL | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460C-WR | 98004-AP460C-WR | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460e-CAN | 98004-AP460e-CAN | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier NBD AHR AP460e-FCC | 98004-AP460e-FCC | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier NBD AHR AP460e-WR | 98004-AP460e-WR | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR AP460i-CAN | 98004-AP460i-CAN | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR AP460i-FCC | 98004-AP460i-FCC | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR AP460i-IL | 98004-AP460i-IL | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR AP460i-WR | 98004-AP460i-WR | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR AP460S12C-CAN | 98004-AP460S12C-CAN | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460S12C-FCC | 98004-AP460S12C-FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460S12C-WR | 98004-AP460S12C-WR | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460S6C-CAN | 98004-AP460S6C-CAN | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460S6C-FCC | 98004-AP460S6C-FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP460S6C-WR | 98004-AP460S6C-WR | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR AP5010-IL | 98004-AP5010-IL | \$ 124.00 | 6% | <i>\$117.43</i> |

| | | | | |
|------------------------------------|----------------------|-----------|-----|-----------------|
| EWP Premier NBD AHR AP5010-WW | 98004-AP5010-WW | \$ 124.00 | 10% | <i>\$112.44</i> |
| EWP Premier NBD AHR AP5020-WW | 98004-AP5020-WW | \$ 140.34 | 6% | <i>\$132.91</i> |
| EWP Premier NBD AHR AP5050D-WW | 98004-AP5050D-WW | \$ 318.00 | 6% | <i>\$301.16</i> |
| EWP Premier NBD AHR AP5050U-WW | 98004-AP5050U-WW | \$ 248.00 | 6% | <i>\$234.87</i> |
| EWP Premier NBD AHR AP505i-FCC | 98004-AP505i-FCC | \$ 113.00 | 6% | <i>\$107.02</i> |
| EWP Premier NBD AHR AP505i-FCC-TAA | 98004-AP505i-FCC-TAA | \$ 113.00 | 6% | <i>\$107.02</i> |
| EWP Premier NBD AHR AP505i-WR | 98004-AP505i-WR | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR AP510C-CAN | 98004-AP510C-CAN | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510C-CE | 98004-AP510C-CE | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510C-FCC | 98004-AP510C-FCC | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510C-W | 98004-AP510C-W | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510C-WW | 98004-AP510C-WW | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AP510CX-CAN | 98004-AP510CX-CAN | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510CX-CE | 98004-AP510CX-CE | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510CX-FCC | 98004-AP510CX-FCC | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510CX-W | 98004-AP510CX-W | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR AP510CX-WW | 98004-AP510CX-WW | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR AP510e-FCC | 98004-AP510e-FCC | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR AP510e-FCC-TAA | 98004-AP510e-FCC-TAA | \$ 147.00 | 6% | <i>\$139.22</i> |

| | | | | |
|------------------------------------|----------------------|-------------|-----|-------------------|
| EWP Premier NBD AHR AP510e-WR | 98004-AP510e-WR | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR AP510i-1-FCC | 98004-AP510i-1-FCC | \$ 124.00 | 10% | <i>\$112.44</i> |
| EWP Premier NBD AHR AP510i-1-WR | 98004-AP510i-1-WR | \$ 124.00 | 10% | <i>\$112.44</i> |
| EWP Premier NBD AHR AP510i-FCC | 98004-AP510i-FCC | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier NBD AHR AP510i-FCC-TAA | 98004-AP510i-FCC-TAA | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier NBD AHR AP510i-WR | 98004-AP510i-WR | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier NBD AHR AP560h-FCC | 98004-AP560h-FCC | \$ 325.00 | 6% | <i>\$307.79</i> |
| EWP Premier NBD AHR AP560h-WR | 98004-AP560h-WR | \$ 325.00 | 6% | <i>\$307.79</i> |
| EWP Premier NBD AHR AP560i-FCC | 98004-AP560i-FCC | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier NBD AHR AP560i-WR | 98004-AP560i-WR | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier NBD AHR AP560m-FCC | 98004-AP560m-FCC | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier NBD AHR AP560t-FCC | 98004-AP560t-FCC | \$ 325.00 | 6% | <i>\$307.79</i> |
| EWP Premier NBD AHR AP560u-FCC | 98004-AP560u-FCC | \$ 221.00 | 6% | <i>\$209.30</i> |
| EWP Premier NBD AHR E2122 | 98004-E2122 | \$ 5,591.00 | 6% | <i>\$5,294.96</i> |
| EWP Premier NBD AHR E2122-1 | 98004-E2122-1 | \$ 5,325.00 | 6% | <i>\$5,043.04</i> |
| EWP Premier NBD AHR E3120-1 | 98004-E3120-1 | \$ 8,711.00 | 6% | <i>\$8,249.75</i> |
| EWP Premier NBD AHR E3125 | 98004-E3125 | \$ 9,184.00 | 6% | <i>\$8,697.71</i> |
| EWP Premier NBD AHR H30003 | 98004-H30003 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30004 | 98004-H30004 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier NBD AHR H30005 | 98004-H30005 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier NBD AHR H30006 | 98004-H30006 | \$ 113.00 | 6% | <i>\$107.02</i> |
| EWP Premier NBD AHR H30007 | 98004-H30007 | \$ 106.00 | 6% | <i>\$100.39</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30008 | 98004-H30008 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier NBD AHR H30009 | 98004-H30009 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30010 | 98004-H30010 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD AHR H30011 | 98004-H30011 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H30012 | 98004-H30012 | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier NBD AHR H30078 | 98004-H30078 | \$ 2,201.00 | 6% | <i>\$2,084.46</i> |
| EWP Premier NBD AHR H30104 | 98004-H30104 | \$ 1,994.00 | 6% | <i>\$1,888.42</i> |
| EWP Premier NBD AHR H30105 | 98004-H30105 | \$ 2,009.00 | 6% | <i>\$1,902.62</i> |
| EWP Premier NBD AHR H30131 | 98004-H30131 | \$ 1,151.00 | 6% | <i>\$1,090.05</i> |
| EWP Premier NBD AHR H30132 | 98004-H30132 | \$ 1,129.00 | 6% | <i>\$1,069.22</i> |
| EWP Premier NBD AHR H30133 | 98004-H30133 | \$ 2,978.00 | 6% | <i>\$2,820.31</i> |
| EWP Premier NBD AHR H30134 | 98004-H30134 | \$ 3,764.00 | 6% | <i>\$3,564.70</i> |
| EWP Premier NBD AHR H30135 | 98004-H30135 | \$ 3,037.00 | 6% | <i>\$2,876.19</i> |
| EWP Premier NBD AHR H30136 | 98004-H30136 | \$ 3,764.00 | 6% | <i>\$3,564.70</i> |
| EWP Premier NBD AHR H30184 | 98004-H30184 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier NBD AHR H30185 | 98004-H30185 | \$ 267.00 | 6% | <i>\$252.86</i> |
| EWP Premier NBD AHR H30186 | 98004-H30186 | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier NBD AHR H30187 | 98004-H30187 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier NBD AHR H30188 | 98004-H30188 | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier NBD AHR H30189 | 98004-H30189 | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier NBD AHR H30190 | 98004-H30190 | \$ 279.00 | 6% | <i>\$264.23</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H30214 | 98004-H30214 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR H30215 | 98004-H30215 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR H30216 | 98004-H30216 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30217 | 98004-H30217 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30218 | 98004-H30218 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30219 | 98004-H30219 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30220 | 98004-H30220 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30221 | 98004-H30221 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30222 | 98004-H30222 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30223 | 98004-H30223 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30224 | 98004-H30224 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30225 | 98004-H30225 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30226 | 98004-H30226 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30227 | 98004-H30227 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30228 | 98004-H30228 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30229 | 98004-H30229 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30267 | 98004-H30267 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30268 | 98004-H30268 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H30269 | 98004-H30269 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30270 | 98004-H30270 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30271 | 98004-H30271 | \$ 457.00 | 6% | <i>\$432.80</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30272 | 98004-H30272 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30273 | 98004-H30273 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier NBD AHR H30274 | 98004-H30274 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier NBD AHR H30275 | 98004-H30275 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30276 | 98004-H30276 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30277 | 98004-H30277 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier NBD AHR H30278 | 98004-H30278 | \$ 668.00 | 6% | <i>\$632.63</i> |
| EWP Premier NBD AHR H30279 | 98004-H30279 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier NBD AHR H30280 | 98004-H30280 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier NBD AHR H30281 | 98004-H30281 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier NBD AHR H30282 | 98004-H30282 | \$ 617.00 | 6% | <i>\$584.33</i> |
| EWP Premier NBD AHR H30283 | 98004-H30283 | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWP Premier NBD AHR H30284 | 98004-H30284 | \$ 457.00 | 6% | <i>\$432.80</i> |
| EWP Premier NBD AHR H30293 | 98004-H30293 | \$ 2,170.00 | 6% | <i>\$2,055.10</i> |
| EWP Premier NBD AHR H30296 | 98004-H30296 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR H30297 | 98004-H30297 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR H30298 | 98004-H30298 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR H30299 | 98004-H30299 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier NBD AHR H30380 | 98004-H30380 | \$ 4,038.00 | 6% | <i>\$3,824.19</i> |
| EWP Premier NBD AHR H30381 | 98004-H30381 | \$ 416.00 | 6% | <i>\$393.97</i> |
| EWP Premier NBD AHR H30383 | 98004-H30383 | \$ 5,737.00 | 6% | <i>\$5,433.23</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30384 | 98004-H30384 | \$ 336.00 | 6% | <i>\$318.21</i> |
| EWP Premier NBD AHR H30391 | 98004-H30391 | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWP Premier NBD AHR H30392 | 98004-H30392 | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWP Premier NBD AHR H30393 | 98004-H30393 | \$ 354.00 | 6% | <i>\$335.26</i> |
| EWP Premier NBD AHR H30394 | 98004-H30394 | \$ 1,502.00 | 6% | <i>\$1,422.47</i> |
| EWP Premier NBD AHR H30395 | 98004-H30395 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWP Premier NBD AHR H30396 | 98004-H30396 | \$ 1,634.00 | 6% | <i>\$1,547.48</i> |
| EWP Premier NBD AHR H30397 | 98004-H30397 | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWP Premier NBD AHR H30398 | 98004-H30398 | \$ 362.00 | 6% | <i>\$342.83</i> |
| EWP Premier NBD AHR H30400 | 98004-H30400 | \$ 197.00 | 6% | <i>\$186.57</i> |
| EWP Premier NBD AHR H30401 | 98004-H30401 | \$ 282.00 | 6% | <i>\$267.07</i> |
| EWP Premier NBD AHR H30402 | 98004-H30402 | \$ 302.00 | 6% | <i>\$286.01</i> |
| EWP Premier NBD AHR H30403 | 98004-H30403 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWP Premier NBD AHR H30434 | 98004-H30434 | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier NBD AHR H30480 | 98004-H30480 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWP Premier NBD AHR H30495 | 98004-H30495 | \$ 1,151.00 | 6% | <i>\$1,090.05</i> |
| EWP Premier NBD AHR H30496 | 98004-H30496 | \$ 1,129.00 | 6% | <i>\$1,069.22</i> |
| EWP Premier NBD AHR H30497 | 98004-H30497 | \$ 1,665.00 | 6% | <i>\$1,576.84</i> |
| EWP Premier NBD AHR H30498 | 98004-H30498 | \$ 1,634.00 | 6% | <i>\$1,547.48</i> |
| EWP Premier NBD AHR H30499 | 98004-H30499 | \$ 563.00 | 6% | <i>\$533.19</i> |
| EWP Premier NBD AHR H30501 | 98004-H30501 | \$ 1,634.00 | 6% | <i>\$1,547.48</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD AHR H30502 | 98004-H30502 | \$ 2,512.00 | 6% | \$2,378.99 |
| EWP Premier NBD AHR H30503 | 98004-H30503 | \$ 563.00 | 6% | \$533.19 |
| EWP Premier NBD AHR H30505 | 98004-H30505 | \$ 2,978.00 | 6% | \$2,820.31 |
| EWP Premier NBD AHR H30506 | 98004-H30506 | \$ 4,048.00 | 6% | \$3,833.66 |
| EWP Premier NBD AHR H30509 | 98004-H30509 | \$ 2,512.00 | 6% | \$2,378.99 |
| EWP Premier NBD AHR H30510 | 98004-H30510 | \$ 2,978.00 | 6% | \$2,820.31 |
| EWP Premier NBD AHR H30511 | 98004-H30511 | \$ 4,048.00 | 6% | \$3,833.66 |
| EWP Premier NBD AHR H30512 | 98004-H30512 | \$ 563.00 | 6% | \$533.19 |
| EWP Premier NBD AHR H30513 | 98004-H30513 | \$ 943.00 | 6% | \$893.07 |
| EWP Premier NBD AHR H30525 | 98004-H30525 | \$ 4,048.00 | 6% | \$3,833.66 |
| EWP Premier NBD AHR H30526 | 98004-H30526 | \$ 2,978.00 | 6% | \$2,820.31 |
| EWP Premier NBD AHR H30528 | 98004-H30528 | \$ 4,682.00 | 6% | \$4,434.09 |
| EWP Premier NBD AHR H30531 | 98004-H30531 | \$ 6,671.00 | 6% | \$6,317.77 |
| EWP Premier NBD AHR H30532 | 98004-H30532 | \$ 6,671.00 | 6% | \$6,317.77 |
| EWP Premier NBD AHR H30534 | 98004-H30534 | \$ 6,799.00 | 6% | \$6,438.99 |
| EWP Premier NBD AHR H30535 | 98004-H30535 | \$ 7,261.00 | 6% | \$6,876.53 |
| EWP Premier NBD AHR H30536 | 98004-H30536 | \$ 6,671.00 | 6% | \$6,317.77 |
| EWP Premier NBD AHR H30537 | 98004-H30537 | \$ 7,261.00 | 6% | \$6,876.53 |
| EWP Premier NBD AHR H30538 | 98004-H30538 | \$ 4,048.00 | 6% | \$3,833.66 |
| EWP Premier NBD AHR H30539 | 98004-H30539 | \$ 7,754.00 | 6% | \$7,343.43 |
| EWP Premier NBD AHR H30540 | 98004-H30540 | \$ 8,017.00 | 6% | \$7,592.50 |

| | | | | |
|-------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD AHR H30543 | 98004-H30543 | \$ 552.00 | 6% | \$522.77 |
| EWP Premier NBD AHR H30544 | 98004-H30544 | \$ 978.00 | 6% | \$926.21 |
| EWP Premier NBD AHR H30548 | 98004-H30548 | \$ 552.00 | 6% | \$522.77 |
| EWP Premier NBD AHR H30549 | 98004-H30549 | \$ 925.00 | 6% | \$876.02 |
| EWP Premier NBD AHR H30550 | 98004-H30550 | \$ 925.00 | 6% | \$876.02 |
| EWP Premier NBD AHR H30552 | 98004-H30552 | \$ 552.00 | 6% | \$522.77 |
| EWP Premier NBD AHR H30553 | 98004-H30553 | \$ 874.00 | 6% | \$827.72 |
| EWP Premier NBD AHR H30567 | 98004-H30567 | \$ 3,306.00 | 6% | \$3,130.95 |
| EWP Premier NBD AHR H30569 | 98004-H30569 | \$ 2,978.00 | 6% | \$2,820.31 |
| EWP Premier NBD AHR H30570 | 98004-H30570 | \$ 3,564.00 | 6% | \$3,375.29 |
| EWP Premier NBD AHR H30571 | 98004-H30571 | \$ 3,564.00 | 6% | \$3,375.29 |
| EWP Premier NBD AHR H30573 | 98004-H30573 | \$ 2,978.00 | 6% | \$2,820.31 |
| EWP Premier NBD AHR H30574 | 98004-H30574 | \$ 3,290.00 | 6% | \$3,115.79 |
| EWP Premier NBD AHR H30575 | 98004-H30575 | \$ 2,048.00 | 6% | \$1,939.56 |
| EWP Premier NBD AHR H30576 | 98004-H30576 | \$ 2,978.00 | 6% | \$2,820.31 |
| EWP Premier NBD AHR H30577 | 98004-H30577 | \$ 3,497.00 | 6% | \$3,311.83 |
| EWP Premier NBD AHR H30578 | 98004-H30578 | \$ 3,497.00 | 6% | \$3,311.83 |
| EWP Premier NBD AHR H30587 | 98004-H30587 | \$ 3,037.00 | 6% | \$2,876.19 |
| EWP Premier NBD AHR H30588 | 98004-H30588 | \$ 2,086.00 | 6% | \$1,975.55 |
| EWP Premier NBD AHR H30589 | 98004-H30589 | \$ 3,181.00 | 6% | \$3,012.57 |
| EWP Premier NBD AHR H30591 | 98004-H30591 | \$ 4,949.00 | 6% | \$4,686.95 |

| | | | | |
|-------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD AHR H30625 | 98004-H30625 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD AHR H30626 | 98004-H30626 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD AHR H30632 | 98004-H30632 | \$ 86.00 | 6% | \$81.45 |
| EWP Premier NBD AHR H30633 | 98004-H30633 | \$ 86.00 | 6% | \$81.45 |
| EWP Premier NBD AHR H30643 | 98004-H30643 | \$ 5,003.00 | 6% | \$4,738.09 |
| EWP Premier NBD AHR H30706 | 98004-H30706 | \$ 4,775.00 | 6% | \$4,522.16 |
| EWP Premier NBD AHR H30707 | 98004-H30707 | \$ 2,978.00 | 6% | \$2,820.31 |
| EWP Premier NBD AHR H30724 | 98004-H30724 | \$ 336.00 | 6% | \$318.21 |
| EWP Premier NBD AHR H30725 | 98004-H30725 | \$ 1,129.00 | 6% | \$1,069.22 |
| EWP Premier NBD AHR H30726 | 98004-H30726 | \$ 7,401.00 | 6% | \$7,009.12 |
| EWP Premier NBD AHR H30727 | 98004-H30727 | \$ 7,863.00 | 6% | \$7,446.65 |
| EWP Premier NBD AHR H30730 | 98004-H30730 | \$ 72.00 | 6% | \$68.19 |
| EWP Premier NBD AHR H30731 | 98004-H30731 | \$ 72.00 | 6% | \$68.19 |
| EWP Premier NBD AHR H30732 | 98004-H30732 | \$ 1,969.00 | 6% | \$1,864.74 |
| EWP Premier NBD AHR H30733 | 98004-H30733 | \$ 8,217.00 | 6% | \$7,781.91 |
| EWP Premier NBD AHR H30734 | 98004-H30734 | \$ 6,270.00 | 6% | \$5,938.00 |
| EWP Premier NBD AHR H30735 | 98004-H30735 | \$ 6,941.00 | 6% | \$6,573.47 |
| EWP Premier NBD AHR H30736 | 98004-H30736 | \$ 1,108.00 | 6% | \$1,049.33 |
| EWP Premier NBD AHR H30738 | 98004-H30738 | \$ 50.00 | 6% | \$47.35 |
| EWP Premier NBD AHR H30739 | 98004-H30739 | \$ 1,037.00 | 6% | \$982.09 |
| EWP Premier NBD AHR H30740 | 98004-H30740 | \$ 597.00 | 6% | \$565.39 |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30741 | 98004-H30741 | \$ 1,098.00 | 6% | <i>\$1,039.86</i> |
| EWP Premier NBD AHR H30742 | 98004-H30742 | \$ 978.00 | 6% | <i>\$926.21</i> |
| EWP Premier NBD AHR H30743 | 98004-H30743 | \$ 1,037.00 | 6% | <i>\$982.09</i> |
| EWP Premier NBD AHR H30744 | 98004-H30744 | \$ 597.00 | 6% | <i>\$565.39</i> |
| EWP Premier NBD AHR H30745 | 98004-H30745 | \$ 609.00 | 6% | <i>\$576.75</i> |
| EWP Premier NBD AHR H30746 | 98004-H30746 | \$ 1,244.00 | 6% | <i>\$1,178.13</i> |
| EWP Premier NBD AHR H30747 | 98004-H30747 | \$ 2,151.00 | 6% | <i>\$2,037.10</i> |
| EWP Premier NBD AHR H30748 | 98004-H30748 | \$ 3,182.00 | 6% | <i>\$3,013.51</i> |
| EWP Premier NBD AHR H30749 | 98004-H30749 | \$ 7,141.00 | 6% | <i>\$6,762.88</i> |
| EWP Premier NBD AHR H30750 | 98004-H30750 | \$ 7,141.00 | 6% | <i>\$6,762.88</i> |
| EWP Premier NBD AHR H30751 | 98004-H30751 | \$ 4,249.00 | 6% | <i>\$4,024.02</i> |
| EWP Premier NBD AHR H30754 | 98004-H30754 | \$ 7,141.00 | 6% | <i>\$6,762.88</i> |
| EWP Premier NBD AHR H30755 | 98004-H30755 | \$ 7,776.00 | 6% | <i>\$7,364.26</i> |
| EWP Premier NBD AHR H30756 | 98004-H30756 | \$ 7,141.00 | 6% | <i>\$6,762.88</i> |
| EWP Premier NBD AHR H30757 | 98004-H30757 | \$ 3,182.00 | 6% | <i>\$3,013.51</i> |
| EWP Premier NBD AHR H30758 | 98004-H30758 | \$ 6,713.00 | 6% | <i>\$6,357.55</i> |
| EWP Premier NBD AHR H30759 | 98004-H30759 | \$ 7,289.00 | 6% | <i>\$6,903.05</i> |
| EWP Premier NBD AHR H30760 | 98004-H30760 | \$ 8,625.00 | 6% | <i>\$8,168.31</i> |
| EWP Premier NBD AHR H30761 | 98004-H30761 | \$ 3,182.00 | 6% | <i>\$3,013.51</i> |
| EWP Premier NBD AHR H30762 | 98004-H30762 | \$ 7,776.00 | 6% | <i>\$7,364.26</i> |
| EWP Premier NBD AHR H30763 | 98004-H30763 | \$ 7,776.00 | 6% | <i>\$7,364.26</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30764 | 98004-H30764 | \$ 4,912.00 | 6% | <i>\$4,651.91</i> |
| EWP Premier NBD AHR H30765 | 98004-H30765 | \$ 4,333.00 | 6% | <i>\$4,103.57</i> |
| EWP Premier NBD AHR H30766 | 98004-H30766 | \$ 8,418.00 | 6% | <i>\$7,972.27</i> |
| EWP Premier NBD AHR H30767 | 98004-H30767 | \$ 4,912.00 | 6% | <i>\$4,651.91</i> |
| EWP Premier NBD AHR H30769 | 98004-H30769 | \$ 2,538.00 | 6% | <i>\$2,403.61</i> |
| EWP Premier NBD AHR H30773 | 98004-H30773 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD AHR H30774 | 98004-H30774 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR H30775 | 98004-H30775 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR H30776 | 98004-H30776 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD AHR H30777 | 98004-H30777 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR H30778 | 98004-H30778 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR H30779 | 98004-H30779 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H30780 | 98004-H30780 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier NBD AHR H30781 | 98004-H30781 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier NBD AHR H30782 | 98004-H30782 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier NBD AHR H30783 | 98004-H30783 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR H30784 | 98004-H30784 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR H30785 | 98004-H30785 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H30786 | 98004-H30786 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier NBD AHR H30787 | 98004-H30787 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H30788 | 98004-H30788 | \$ 98.00 | 6% | <i>\$92.81</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H30789 | 98004-H30789 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR H30790 | 98004-H30790 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier NBD AHR H30791 | 98004-H30791 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier NBD AHR H30793 | 98004-H30793 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30794 | 98004-H30794 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30795 | 98004-H30795 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30796 | 98004-H30796 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30797 | 98004-H30797 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30798 | 98004-H30798 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30799 | 98004-H30799 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30800 | 98004-H30800 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR H30801 | 98004-H30801 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30802 | 98004-H30802 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR H30803 | 98004-H30803 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30804 | 98004-H30804 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30805 | 98004-H30805 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30806 | 98004-H30806 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30807 | 98004-H30807 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30808 | 98004-H30808 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30809 | 98004-H30809 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30810 | 98004-H30810 | \$ 50.00 | 6% | <i>\$47.35</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H30811 | 98004-H30811 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30812 | 98004-H30812 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30813 | 98004-H30813 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR H30814 | 98004-H30814 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30815 | 98004-H30815 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30816 | 98004-H30816 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30817 | 98004-H30817 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30818 | 98004-H30818 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30819 | 98004-H30819 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30820 | 98004-H30820 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H30821 | 98004-H30821 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR H30822 | 98004-H30822 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30823 | 98004-H30823 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR H30824 | 98004-H30824 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30825 | 98004-H30825 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR H30826 | 98004-H30826 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30827 | 98004-H30827 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30828 | 98004-H30828 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD AHR H30829 | 98004-H30829 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD AHR H30830 | 98004-H30830 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD AHR H30831 | 98004-H30831 | \$ 74.00 | 6% | <i>\$70.08</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30833 | 98004-H30833 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWP Premier NBD AHR H30834 | 98004-H30834 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWP Premier NBD AHR H30836 | 98004-H30836 | \$ 1,414.00 | 6% | <i>\$1,339.13</i> |
| EWP Premier NBD AHR H30838 | 98004-H30838 | \$ 53.00 | 6% | <i>\$50.19</i> |
| EWP Premier NBD AHR H30839 | 98004-H30839 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30840 | 98004-H30840 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30841 | 98004-H30841 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30842 | 98004-H30842 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30843 | 98004-H30843 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30844 | 98004-H30844 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30845 | 98004-H30845 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H30846 | 98004-H30846 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30847 | 98004-H30847 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30848 | 98004-H30848 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30849 | 98004-H30849 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30850 | 98004-H30850 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30851 | 98004-H30851 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30852 | 98004-H30852 | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD AHR H30853 | 98004-H30853 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR H30854 | 98004-H30854 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR H30855 | 98004-H30855 | \$ 140.00 | 6% | <i>\$132.59</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H30856 | 98004-H30856 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR H30857 | 98004-H30857 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR H30858 | 98004-H30858 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR H30859 | 98004-H30859 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR H30860 | 98004-H30860 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD AHR H30866 | 98004-H30866 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD AHR H30867 | 98004-H30867 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H30868 | 98004-H30868 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H30869 | 98004-H30869 | \$ 266.00 | 6% | <i>\$251.92</i> |
| EWP Premier NBD AHR H30870 | 98004-H30870 | \$ 266.00 | 6% | <i>\$251.92</i> |
| EWP Premier NBD AHR H30871 | 98004-H30871 | \$ 244.00 | 6% | <i>\$231.08</i> |
| EWP Premier NBD AHR H30872 | 98004-H30872 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier NBD AHR H30873 | 98004-H30873 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier NBD AHR H30874 | 98004-H30874 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier NBD AHR H30875 | 98004-H30875 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H30876 | 98004-H30876 | \$ 48.00 | 6% | <i>\$45.46</i> |
| EWP Premier NBD AHR H30877 | 98004-H30877 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H30878 | 98004-H30878 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H30891 | 98004-H30891 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR H30892 | 98004-H30892 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR H30893 | 98004-H30893 | \$ 86.00 | 6% | <i>\$81.45</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30894 | 98004-H30894 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H30895 | 98004-H30895 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR H30896 | 98004-H30896 | \$ 405.00 | 6% | <i>\$383.56</i> |
| EWP Premier NBD AHR H30897 | 98004-H30897 | \$ 699.00 | 6% | <i>\$661.99</i> |
| EWP Premier NBD AHR H30898 | 98004-H30898 | \$ 790.00 | 6% | <i>\$748.17</i> |
| EWP Premier NBD AHR H30900 | 98004-H30900 | \$ 2,380.00 | 6% | <i>\$2,253.98</i> |
| EWP Premier NBD AHR H30901 | 98004-H30901 | \$ 3,167.00 | 6% | <i>\$2,999.31</i> |
| EWP Premier NBD AHR H30902 | 98004-H30902 | \$ 3,325.00 | 6% | <i>\$3,148.94</i> |
| EWP Premier NBD AHR H30904 | 98004-H30904 | \$ 4,867.00 | 6% | <i>\$4,609.29</i> |
| EWP Premier NBD AHR H30905 | 98004-H30905 | \$ 6,952.00 | 6% | <i>\$6,583.89</i> |
| EWP Premier NBD AHR H30906 | 98004-H30906 | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier NBD AHR H30910 | 98004-H30910 | \$ 560.00 | 6% | <i>\$530.35</i> |
| EWP Premier NBD AHR H30912 | 98004-H30912 | \$ 525.00 | 6% | <i>\$497.20</i> |
| EWP Premier NBD AHR H30913 | 98004-H30913 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier NBD AHR H30914 | 98004-H30914 | \$ 49.00 | 6% | <i>\$46.41</i> |
| EWP Premier NBD AHR H30915 | 98004-H30915 | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR H30916 | 98004-H30916 | \$ 52.00 | 6% | <i>\$49.25</i> |
| EWP Premier NBD AHR H30917 | 98004-H30917 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier NBD AHR H30918 | 98004-H30918 | \$ 55.00 | 6% | <i>\$52.09</i> |
| EWP Premier NBD AHR H30946 | 98004-H30946 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H30948 | 98004-H30948 | \$ 97.00 | 6% | <i>\$91.86</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H30950 | 98004-H30950 | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier NBD AHR H30951 | 98004-H30951 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H30952 | 98004-H30952 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H30966 | 98004-H30966 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR H30967 | 98004-H30967 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD AHR H30968 | 98004-H30968 | \$ 174.00 | 6% | <i>\$164.79</i> |
| EWP Premier NBD AHR H30969 | 98004-H30969 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H30970 | 98004-H30970 | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier NBD AHR H30971 | 98004-H30971 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD AHR H30972 | 98004-H30972 | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier NBD AHR H30973 | 98004-H30973 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H30974 | 98004-H30974 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD AHR H30975 | 98004-H30975 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H30976 | 98004-H30976 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H30977 | 98004-H30977 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD AHR H30978 | 98004-H30978 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H30995 | 98004-H30995 | \$ 1,905.00 | 6% | <i>\$1,804.13</i> |
| EWP Premier NBD AHR H30996 | 98004-H30996 | \$ 4,255.00 | 6% | <i>\$4,029.70</i> |
| EWP Premier NBD AHR H31030 | 98004-H31030 | \$ 6,143.00 | 6% | <i>\$5,817.73</i> |
| EWP Premier NBD AHR H31031 | 98004-H31031 | \$ 488.00 | 6% | <i>\$462.16</i> |
| EWP Premier NBD AHR H31033 | 98004-H31033 | \$ 3,650.00 | 6% | <i>\$3,456.73</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H31034 | 98004-H31034 | \$ 2,028.00 | 6% | <i>\$1,920.62</i> |
| EWP Premier NBD AHR H31035 | 98004-H31035 | \$ 2,127.00 | 6% | <i>\$2,014.38</i> |
| EWP Premier NBD AHR H31036 | 98004-H31036 | \$ 4,250.00 | 6% | <i>\$4,024.96</i> |
| EWP Premier NBD AHR H31040 | 98004-H31040 | \$ 166.00 | 6% | <i>\$157.21</i> |
| EWP Premier NBD AHR H31041 | 98004-H31041 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier NBD AHR H31042 | 98004-H31042 | \$ 247.00 | 6% | <i>\$233.92</i> |
| EWP Premier NBD AHR H31043 | 98004-H31043 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier NBD AHR H31044 | 98004-H31044 | \$ 560.00 | 6% | <i>\$530.35</i> |
| EWP Premier NBD AHR H31047 | 98004-H31047 | \$ 166.00 | 6% | <i>\$157.21</i> |
| EWP Premier NBD AHR H31049 | 98004-H31049 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWP Premier NBD AHR H31060 | 98004-H31060 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H31062 | 98004-H31062 | \$ 50.00 | 6% | <i>\$47.35</i> |
| EWP Premier NBD AHR H31066 | 98004-H31066 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H31068 | 98004-H31068 | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier NBD AHR H31077 | 98004-H31077 | \$ 247.00 | 6% | <i>\$233.92</i> |
| EWP Premier NBD AHR H31103 | 98004-H31103 | \$ 3,895.00 | 6% | <i>\$3,688.76</i> |
| EWP Premier NBD AHR H31124 | 98004-H31124 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD AHR H31127 | 98004-H31127 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD AHR H31132 | 98004-H31132 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier NBD AHR H31134 | 98004-H31134 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H31135 | 98004-H31135 | \$ 59.00 | 6% | <i>\$55.88</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H31136 | 98004-H31136 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD AHR H31137 | 98004-H31137 | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier NBD AHR H31197 | 98004-H31197 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H31198 | 98004-H31198 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H31199 | 98004-H31199 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H31200 | 98004-H31200 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H31201 | 98004-H31201 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H31202 | 98004-H31202 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD AHR H31203 | 98004-H31203 | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier NBD AHR H31204 | 98004-H31204 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H31205 | 98004-H31205 | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier NBD AHR H31206 | 98004-H31206 | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier NBD AHR H31207 | 98004-H31207 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H31208 | 98004-H31208 | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier NBD AHR H31210 | 98004-H31210 | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier NBD AHR H31335 | 98004-H31335 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD AHR H31337 | 98004-H31337 | \$ 8,432.00 | 6% | <i>\$7,985.53</i> |
| EWP Premier NBD AHR H31338 | 98004-H31338 | \$ 8,432.00 | 6% | <i>\$7,985.53</i> |
| EWP Premier NBD AHR H31339 | 98004-H31339 | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| EWP Premier NBD AHR H31340 | 98004-H31340 | \$ 2,927.00 | 6% | <i>\$2,772.02</i> |
| EWP Premier NBD AHR H31341 | 98004-H31341 | \$ 4,341.00 | 6% | <i>\$4,111.14</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD AHR H31342 | 98004-H31342 | \$ 1,363.00 | 6% | <i>\$1,290.83</i> |
| EWP Premier NBD AHR H31343 | 98004-H31343 | \$ 2,019.00 | 6% | <i>\$1,912.09</i> |
| EWP Premier NBD AHR H31344 | 98004-H31344 | \$ 2,019.00 | 6% | <i>\$1,912.09</i> |
| EWP Premier NBD AHR H31345 | 98004-H31345 | \$ 2,019.00 | 6% | <i>\$1,912.09</i> |
| EWP Premier NBD AHR H31346 | 98004-H31346 | \$ 2,019.00 | 6% | <i>\$1,912.09</i> |
| EWP Premier NBD AHR H31348 | 98004-H31348 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD AHR H31349 | 98004-H31349 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD AHR H31350 | 98004-H31350 | \$ 244.00 | 6% | <i>\$231.08</i> |
| EWP Premier NBD AHR H31351 | 98004-H31351 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H31352 | 98004-H31352 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H31353 | 98004-H31353 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier NBD AHR H31354 | 98004-H31354 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier NBD AHR H31355 | 98004-H31355 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD AHR H31356 | 98004-H31356 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD AHR H31357 | 98004-H31357 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD AHR H31358 | 98004-H31358 | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD AHR H31359 | 98004-H31359 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H31360 | 98004-H31360 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier NBD AHR H31361 | 98004-H31361 | \$ 2,681.00 | 6% | <i>\$2,539.04</i> |
| EWP Premier NBD AHR H31362 | 98004-H31362 | \$ 22,661.00 | 6% | <i>\$21,461.10</i> |
| EWP Premier NBD AHR H31363 | 98004-H31363 | \$ 22,661.00 | 6% | <i>\$21,461.10</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD AHR H31364 | 98004-H31364 | \$ 7,920.00 | 6% | <i>\$7,500.64</i> |
| EWP Premier NBD AHR H31365 | 98004-H31365 | \$ 7,920.00 | 6% | <i>\$7,500.64</i> |
| EWP Premier NBD AHR H31366 | 98004-H31366 | \$ 10,984.00 | 6% | <i>\$10,402.40</i> |
| EWP Premier NBD AHR H31367 | 98004-H31367 | \$ 10,984.00 | 6% | <i>\$10,402.40</i> |
| EWP Premier NBD AHR H31369 | 98004-H31369 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H31370 | 98004-H31370 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD AHR H31393 | 98004-H31393 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier NBD AHR H32010 | 98004-H32010 | \$ 308.00 | 6% | <i>\$291.69</i> |
| EWP Premier NBD AHR H32011 | 98004-H32011 | \$ 308.00 | 6% | <i>\$291.69</i> |
| EWP Premier NBD AHR H32012 | 98004-H32012 | \$ 2,536.00 | 6% | <i>\$2,401.72</i> |
| EWP Premier NBD AHR H32013 | 98004-H32013 | \$ 2,536.00 | 6% | <i>\$2,401.72</i> |
| EWP Premier NBD AHR H32014 | 98004-H32014 | \$ 2,536.00 | 6% | <i>\$2,401.72</i> |
| EWP Premier NBD AHR H32015 | 98004-H32015 | \$ 2,536.00 | 6% | <i>\$2,401.72</i> |
| EWP Premier NBD AHR H32016 | 98004-H32016 | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier NBD AHR H32017 | 98004-H32017 | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier NBD AHR H32018 | 98004-H32018 | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier NBD AHR H32019 | 98004-H32019 | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier NBD AHR H32020 | 98004-H32020 | \$ 22,583.00 | 6% | <i>\$21,387.23</i> |
| EWP Premier NBD AHR H32021 | 98004-H32021 | \$ 22,583.00 | 6% | <i>\$21,387.23</i> |
| EWP Premier NBD AHR H32022 | 98004-H32022 | \$ 22,583.00 | 6% | <i>\$21,387.23</i> |
| EWP Premier NBD AHR H32023 | 98004-H32023 | \$ 22,583.00 | 6% | <i>\$21,387.23</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD AHR H32024 | 98004-H32024 | \$ 17,795.00 | 6% | <i>\$16,852.75</i> |
| EWP Premier NBD AHR H32028 | 98004-H32028 | \$ 43,550.00 | 6% | <i>\$41,244.03</i> |
| EWP Premier NBD AHR H32029 | 98004-H32029 | \$ 43,550.00 | 6% | <i>\$41,244.03</i> |
| EWP Premier NBD AHR H32030 | 98004-H32030 | \$ 45,671.00 | 6% | <i>\$43,252.72</i> |
| EWP Premier NBD AHR H32031 | 98004-H32031 | \$ 45,671.00 | 6% | <i>\$43,252.72</i> |
| EWP Premier NBD AHR H32032 | 98004-H32032 | \$ 45,671.00 | 6% | <i>\$43,252.72</i> |
| EWP Premier NBD AHR H32033 | 98004-H32033 | \$ 45,671.00 | 6% | <i>\$43,252.72</i> |
| EWP Premier NBD AHR H32038 | 98004-H32038 | \$ 7,893.00 | 6% | <i>\$7,475.07</i> |
| EWP Premier NBD AHR H32039 | 98004-H32039 | \$ 7,893.00 | 6% | <i>\$7,475.07</i> |
| EWP Premier NBD AHR H32040 | 98004-H32040 | \$ 7,893.00 | 6% | <i>\$7,475.07</i> |
| EWP Premier NBD AHR H32041 | 98004-H32041 | \$ 7,893.00 | 6% | <i>\$7,475.07</i> |
| EWP Premier NBD AHR H32046 | 98004-H32046 | \$ 10,944.00 | 6% | <i>\$10,364.52</i> |
| EWP Premier NBD AHR H32047 | 98004-H32047 | \$ 10,944.00 | 6% | <i>\$10,364.52</i> |
| EWP Premier NBD AHR H32048 | 98004-H32048 | \$ 10,944.00 | 6% | <i>\$10,364.52</i> |
| EWP Premier NBD AHR H32049 | 98004-H32049 | \$ 10,944.00 | 6% | <i>\$10,364.52</i> |
| EWP Premier NBD AHR H32054 | 98004-H32054 | \$ 7,893.00 | 6% | <i>\$7,475.07</i> |
| EWP Premier NBD AHR H32055 | 98004-H32055 | \$ 10,944.00 | 6% | <i>\$10,364.52</i> |
| EWP Premier NBD AHR H32056 | 98004-H32056 | \$ 2,456.00 | 6% | <i>\$2,325.95</i> |
| EWP Premier NBD AHR H32057 | 98004-H32057 | \$ 2,456.00 | 6% | <i>\$2,325.95</i> |
| EWP Premier NBD AHR H32058 | 98004-H32058 | \$ 2,456.00 | 6% | <i>\$2,325.95</i> |
| EWP Premier NBD AHR H32059 | 98004-H32059 | \$ 2,456.00 | 6% | <i>\$2,325.95</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD AHR H32060 | 98004-H32060 | \$ 3,029.00 | 6% | <i>\$2,868.61</i> |
| EWP Premier NBD AHR H32061 | 98004-H32061 | \$ 3,180.00 | 6% | <i>\$3,011.62</i> |
| EWP Premier NBD AHR H32062 | 98004-H32062 | \$ 3,029.00 | 6% | <i>\$2,868.61</i> |
| EWP Premier NBD AHR H32063 | 98004-H32063 | \$ 3,033.00 | 6% | <i>\$2,872.40</i> |
| EWP Premier NBD AHR H32064 | 98004-H32064 | \$ 3,029.00 | 6% | <i>\$2,868.61</i> |
| EWP Premier NBD AHR H32065 | 98004-H32065 | \$ 3,451.00 | 6% | <i>\$3,268.27</i> |
| EWP Premier NBD AHR H32066 | 98004-H32066 | \$ 3,451.00 | 6% | <i>\$3,268.27</i> |
| EWP Premier NBD AHR H32067 | 98004-H32067 | \$ 3,451.00 | 6% | <i>\$3,268.27</i> |
| EWP Premier NBD AHR H32068 | 98004-H32068 | \$ 3,451.00 | 6% | <i>\$3,268.27</i> |
| EWP Premier NBD AHR H32069 | 98004-H32069 | \$ 4,289.00 | 6% | <i>\$4,061.90</i> |
| EWP Premier NBD AHR H32070 | 98004-H32070 | \$ 4,289.00 | 6% | <i>\$4,061.90</i> |
| EWP Premier NBD AHR H32071 | 98004-H32071 | \$ 4,289.00 | 6% | <i>\$4,061.90</i> |
| EWP Premier NBD AHR H32072 | 98004-H32072 | \$ 4,289.00 | 6% | <i>\$4,061.90</i> |
| EWP Premier NBD AHR H32073 | 98004-H32073 | \$ 31,770.00 | 6% | <i>\$30,087.78</i> |
| EWP Premier NBD AHR H32074 | 98004-H32074 | \$ 31,770.00 | 6% | <i>\$30,087.78</i> |
| EWP Premier NBD AHR H32075 | 98004-H32075 | \$ 43,176.00 | 6% | <i>\$40,889.83</i> |
| EWP Premier NBD AHR H32076 | 98004-H32076 | \$ 42,764.00 | 6% | <i>\$40,499.65</i> |
| EWP Premier NBD AHR H32101 | 98004-H32101 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier NBD AHR H32102 | 98004-H32102 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier NBD AHR H32103 | 98004-H32103 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier NBD AHR H32104 | 98004-H32104 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H32105 | 98004-H32105 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32106 | 98004-H32106 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32107 | 98004-H32107 | \$ 7,652.00 | 6% | <i>\$7,246.83</i> |
| EWP Premier NBD AHR H32108 | 98004-H32108 | \$ 7,652.00 | 6% | <i>\$7,246.83</i> |
| EWP Premier NBD AHR H32109 | 98004-H32109 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32110 | 98004-H32110 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32111 | 98004-H32111 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier NBD AHR H32112 | 98004-H32112 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier NBD AHR H32113 | 98004-H32113 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier NBD AHR H32114 | 98004-H32114 | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier NBD AHR H32115 | 98004-H32115 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32116 | 98004-H32116 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32117 | 98004-H32117 | \$ 1,330.00 | 6% | <i>\$1,259.58</i> |
| EWP Premier NBD AHR H32118 | 98004-H32118 | \$ 1,330.00 | 6% | <i>\$1,259.58</i> |
| EWP Premier NBD AHR H32119 | 98004-H32119 | \$ 1,330.00 | 6% | <i>\$1,259.58</i> |
| EWP Premier NBD AHR H32120 | 98004-H32120 | \$ 1,330.00 | 6% | <i>\$1,259.58</i> |
| EWP Premier NBD AHR H32121 | 98004-H32121 | \$ 7,652.00 | 6% | <i>\$7,246.83</i> |
| EWP Premier NBD AHR H32122 | 98004-H32122 | \$ 7,652.00 | 6% | <i>\$7,246.83</i> |
| EWP Premier NBD AHR H32123 | 98004-H32123 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32124 | 98004-H32124 | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR H32125 | 98004-H32125 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD AHR H32126 | 98004-H32126 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H32127 | 98004-H32127 | \$ 3,289.00 | 6% | <i>\$3,114.85</i> |
| EWP Premier NBD AHR H32128 | 98004-H32128 | \$ 3,289.00 | 6% | <i>\$3,114.85</i> |
| EWP Premier NBD AHR H32129 | 98004-H32129 | \$ 3,289.00 | 6% | <i>\$3,114.85</i> |
| EWP Premier NBD AHR H32130 | 98004-H32130 | \$ 3,289.00 | 6% | <i>\$3,114.85</i> |
| EWP Premier NBD AHR H32131 | 98004-H32131 | \$ 3,289.00 | 6% | <i>\$3,114.85</i> |
| EWP Premier NBD AHR H32132 | 98004-H32132 | \$ 3,289.00 | 6% | <i>\$3,114.85</i> |
| EWP Premier NBD AHR H32133 | 98004-H32133 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H32134 | 98004-H32134 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H32135 | 98004-H32135 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H32136 | 98004-H32136 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H32137 | 98004-H32137 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H32138 | 98004-H32138 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H32139 | 98004-H32139 | \$ 11,825.00 | 6% | <i>\$11,198.87</i> |
| EWP Premier NBD AHR H32140 | 98004-H32140 | \$ 11,825.00 | 6% | <i>\$11,198.87</i> |
| EWP Premier NBD AHR H32141 | 98004-H32141 | \$ 13,648.00 | 6% | <i>\$12,925.34</i> |
| EWP Premier NBD AHR H32142 | 98004-H32142 | \$ 13,648.00 | 6% | <i>\$12,925.34</i> |
| EWP Premier NBD AHR H32143 | 98004-H32143 | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWP Premier NBD AHR H32144 | 98004-H32144 | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWP Premier NBD AHR H32146 | 98004-H32146 | \$ 1,345.00 | 6% | <i>\$1,273.78</i> |
| EWP Premier NBD AHR H32147 | 98004-H32147 | \$ 1,345.00 | 6% | <i>\$1,273.78</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD AHR H32148 | 98004-H32148 | \$ 2,683.00 | 6% | <i>\$2,540.94</i> |
| EWP Premier NBD AHR H32149 | 98004-H32149 | \$ 2,683.00 | 6% | <i>\$2,540.94</i> |
| EWP Premier NBD AHR H32150 | 98004-H32150 | \$ 1,345.00 | 6% | <i>\$1,273.78</i> |
| EWP Premier NBD AHR H32151 | 98004-H32151 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWP Premier NBD AHR H32152 | 98004-H32152 | \$ 582.00 | 6% | <i>\$551.18</i> |
| EWP Premier NBD AHR H32169 | 98004-H32169 | \$ 1,410.00 | 6% | <i>\$1,335.34</i> |
| EWP Premier NBD AHR H32170 | 98004-H32170 | \$ 1,410.00 | 6% | <i>\$1,335.34</i> |
| EWP Premier NBD AHR H32171 | 98004-H32171 | \$ 1,321.00 | 6% | <i>\$1,251.05</i> |
| EWP Premier NBD AHR H32172 | 98004-H32172 | \$ 1,321.00 | 6% | <i>\$1,251.05</i> |
| EWP Premier NBD AHR H32173 | 98004-H32173 | \$ 3,509.00 | 6% | <i>\$3,323.20</i> |
| EWP Premier NBD AHR H32174 | 98004-H32174 | \$ 3,509.00 | 6% | <i>\$3,323.20</i> |
| EWP Premier NBD AHR H32175 | 98004-H32175 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWP Premier NBD AHR H32176 | 98004-H32176 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWP Premier NBD AHR H32177 | 98004-H32177 | \$ 13,677.00 | 6% | <i>\$12,952.80</i> |
| EWP Premier NBD AHR H32178 | 98004-H32178 | \$ 15,783.00 | 6% | <i>\$14,947.29</i> |
| EWP Premier NBD AHR H34008 | 98004-H34008 | \$ 40.00 | 6% | <i>\$37.88</i> |
| EWP Premier NBD AHR H34009 | 98004-H34009 | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier NBD AHR H34010 | 98004-H34010 | \$ 45.00 | 6% | <i>\$42.62</i> |
| EWP Premier NBD AHR H34011 | 98004-H34011 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34012 | 98004-H34012 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier NBD AHR H34013 | 98004-H34013 | \$ 72.00 | 6% | <i>\$68.19</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34014 | 98004-H34014 | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier NBD AHR H34015 | 98004-H34015 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier NBD AHR H34016 | 98004-H34016 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD AHR H34017 | 98004-H34017 | \$ 216.00 | 6% | <i>\$204.56</i> |
| EWP Premier NBD AHR H34018 | 98004-H34018 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34019 | 98004-H34019 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34020 | 98004-H34020 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34021 | 98004-H34021 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34028 | 98004-H34028 | \$ 201.00 | 6% | <i>\$190.36</i> |
| EWP Premier NBD AHR H34048 | 98004-H34048 | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWP Premier NBD AHR H34049 | 98004-H34049 | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWP Premier NBD AHR H34050 | 98004-H34050 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34051 | 98004-H34051 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34052 | 98004-H34052 | \$ 350.00 | 6% | <i>\$331.47</i> |
| EWP Premier NBD AHR H34053 | 98004-H34053 | \$ 350.00 | 6% | <i>\$331.47</i> |
| EWP Premier NBD AHR H34054 | 98004-H34054 | \$ 263.00 | 6% | <i>\$249.07</i> |
| EWP Premier NBD AHR H34055 | 98004-H34055 | \$ 263.00 | 6% | <i>\$249.07</i> |
| EWP Premier NBD AHR H34056 | 98004-H34056 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier NBD AHR H34057 | 98004-H34057 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier NBD AHR H34058 | 98004-H34058 | \$ 331.00 | 6% | <i>\$313.47</i> |
| EWP Premier NBD AHR H34059 | 98004-H34059 | \$ 331.00 | 6% | <i>\$313.47</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD AHR H34062 | 98004-H34062 | \$ 381.00 | 6% | \$360.83 |
| EWP Premier NBD AHR H34063 | 98004-H34063 | \$ 381.00 | 6% | \$360.83 |
| EWP Premier NBD AHR H34064 | 98004-H34064 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD AHR H34065 | 98004-H34065 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD AHR H34066 | 98004-H34066 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD AHR H34067 | 98004-H34067 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD AHR H34068 | 98004-H34068 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD AHR H34069 | 98004-H34069 | \$ 243.00 | 6% | \$230.13 |
| EWP Premier NBD AHR H34070 | 98004-H34070 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD AHR H34071 | 98004-H34071 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD AHR H34072 | 98004-H34072 | \$ 2,506.00 | 6% | \$2,373.31 |
| EWP Premier NBD AHR H34073 | 98004-H34073 | \$ 2,459.00 | 6% | \$2,328.80 |
| EWP Premier NBD AHR H34074 | 98004-H34074 | \$ 3,143.00 | 6% | \$2,976.58 |
| EWP Premier NBD AHR H34075 | 98004-H34075 | \$ 3,015.00 | 6% | \$2,855.36 |
| EWP Premier NBD AHR H34076 | 98004-H34076 | \$ 2,506.00 | 6% | \$2,373.31 |
| EWP Premier NBD AHR H34077 | 98004-H34077 | \$ 2,459.00 | 6% | \$2,328.80 |
| EWP Premier NBD AHR H34078 | 98004-H34078 | \$ 2,506.00 | 6% | \$2,373.31 |
| EWP Premier NBD AHR H34079 | 98004-H34079 | \$ 2,459.00 | 6% | \$2,328.80 |
| EWP Premier NBD AHR H34080 | 98004-H34080 | \$ 3,143.00 | 6% | \$2,976.58 |
| EWP Premier NBD AHR H34081 | 98004-H34081 | \$ 3,015.00 | 6% | \$2,855.36 |
| EWP Premier NBD AHR H34082 | 98004-H34082 | \$ 3,000.00 | 6% | \$2,841.15 |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H34083 | 98004-H34083 | \$ 2,878.00 | 6% | <i>\$2,725.61</i> |
| EWP Premier NBD AHR H34084 | 98004-H34084 | \$ 2,010.00 | 6% | <i>\$1,903.57</i> |
| EWP Premier NBD AHR H34085 | 98004-H34085 | \$ 2,010.00 | 6% | <i>\$1,903.57</i> |
| EWP Premier NBD AHR H34086 | 98004-H34086 | \$ 2,352.00 | 6% | <i>\$2,227.46</i> |
| EWP Premier NBD AHR H34087 | 98004-H34087 | \$ 2,245.00 | 6% | <i>\$2,126.13</i> |
| EWP Premier NBD AHR H34088 | 98004-H34088 | \$ 5,382.00 | 6% | <i>\$5,097.02</i> |
| EWP Premier NBD AHR H34089 | 98004-H34089 | \$ 5,382.00 | 6% | <i>\$5,097.02</i> |
| EWP Premier NBD AHR H34090 | 98004-H34090 | \$ 6,197.00 | 6% | <i>\$5,868.87</i> |
| EWP Premier NBD AHR H34091 | 98004-H34091 | \$ 3,523.00 | 6% | <i>\$3,336.46</i> |
| EWP Premier NBD AHR H34092 | 98004-H34092 | \$ 3,523.00 | 6% | <i>\$3,336.46</i> |
| EWP Premier NBD AHR H34093 | 98004-H34093 | \$ 3,523.00 | 6% | <i>\$3,336.46</i> |
| EWP Premier NBD AHR H34094 | 98004-H34094 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD AHR H34095 | 98004-H34095 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD AHR H34096 | 98004-H34096 | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWP Premier NBD AHR H34097 | 98004-H34097 | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWP Premier NBD AHR H34098 | 98004-H34098 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD AHR H34099 | 98004-H34099 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD AHR H34100 | 98004-H34100 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD AHR H34101 | 98004-H34101 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD AHR H34102 | 98004-H34102 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD AHR H34103 | 98004-H34103 | \$ 404.00 | 6% | <i>\$382.61</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H34104 | 98004-H34104 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H34105 | 98004-H34105 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H34106 | 98004-H34106 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H34107 | 98004-H34107 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H34108 | 98004-H34108 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H34109 | 98004-H34109 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD AHR H34110 | 98004-H34110 | \$ 3,376.00 | 6% | <i>\$3,197.24</i> |
| EWP Premier NBD AHR H34111 | 98004-H34111 | \$ 3,376.00 | 6% | <i>\$3,197.24</i> |
| EWP Premier NBD AHR H34112 | 98004-H34112 | \$ 3,376.00 | 6% | <i>\$3,197.24</i> |
| EWP Premier NBD AHR H34114 | 98004-H34114 | \$ 4,434.00 | 6% | <i>\$4,199.22</i> |
| EWP Premier NBD AHR H34115 | 98004-H34115 | \$ 4,434.00 | 6% | <i>\$4,199.22</i> |
| EWP Premier NBD AHR H34116 | 98004-H34116 | \$ 4,434.00 | 6% | <i>\$4,199.22</i> |
| EWP Premier NBD AHR H34117 | 98004-H34117 | \$ 4,434.00 | 6% | <i>\$4,199.22</i> |
| EWP Premier NBD AHR H34118 | 98004-H34118 | \$ 1,117.00 | 6% | <i>\$1,057.85</i> |
| EWP Premier NBD AHR H34119 | 98004-H34119 | \$ 1,117.00 | 6% | <i>\$1,057.85</i> |
| EWP Premier NBD AHR H34120 | 98004-H34120 | \$ 774.00 | 6% | <i>\$733.02</i> |
| EWP Premier NBD AHR H34121 | 98004-H34121 | \$ 774.00 | 6% | <i>\$733.02</i> |
| EWP Premier NBD AHR H34122 | 98004-H34122 | \$ 802.00 | 6% | <i>\$759.53</i> |
| EWP Premier NBD AHR H34123 | 98004-H34123 | \$ 802.00 | 6% | <i>\$759.53</i> |
| EWP Premier NBD AHR H34124 | 98004-H34124 | \$ 1,200.00 | 6% | <i>\$1,136.46</i> |
| EWP Premier NBD AHR H34125 | 98004-H34125 | \$ 1,200.00 | 6% | <i>\$1,136.46</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H34126 | 98004-H34126 | \$ 1,200.00 | 6% | <i>\$1,136.46</i> |
| EWP Premier NBD AHR H34127 | 98004-H34127 | \$ 1,200.00 | 6% | <i>\$1,136.46</i> |
| EWP Premier NBD AHR H34128 | 98004-H34128 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier NBD AHR H34129 | 98004-H34129 | \$ 327.00 | 6% | <i>\$309.69</i> |
| EWP Premier NBD AHR H34130 | 98004-H34130 | \$ 339.00 | 6% | <i>\$321.05</i> |
| EWP Premier NBD AHR H34131 | 98004-H34131 | \$ 339.00 | 6% | <i>\$321.05</i> |
| EWP Premier NBD AHR H34132 | 98004-H34132 | \$ 339.00 | 6% | <i>\$321.05</i> |
| EWP Premier NBD AHR H34156 | 98004-H34156 | \$ 321.00 | 6% | <i>\$304.00</i> |
| EWP Premier NBD AHR H34172 | 98004-H34172 | \$ 744.00 | 6% | <i>\$704.61</i> |
| EWP Premier NBD AHR H34174 | 98004-H34174 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34175 | 98004-H34175 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34176 | 98004-H34176 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34177 | 98004-H34177 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34178 | 98004-H34178 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34179 | 98004-H34179 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34180 | 98004-H34180 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34181 | 98004-H34181 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34182 | 98004-H34182 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34183 | 98004-H34183 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34184 | 98004-H34184 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34185 | 98004-H34185 | \$ 47.00 | 6% | <i>\$44.51</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34186 | 98004-H34186 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34187 | 98004-H34187 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34188 | 98004-H34188 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34189 | 98004-H34189 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34190 | 98004-H34190 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34191 | 98004-H34191 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34192 | 98004-H34192 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34193 | 98004-H34193 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34194 | 98004-H34194 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34195 | 98004-H34195 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34196 | 98004-H34196 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34197 | 98004-H34197 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34198 | 98004-H34198 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34199 | 98004-H34199 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34200 | 98004-H34200 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34201 | 98004-H34201 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34202 | 98004-H34202 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34203 | 98004-H34203 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34204 | 98004-H34204 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34205 | 98004-H34205 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34206 | 98004-H34206 | \$ 47.00 | 6% | <i>\$44.51</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34207 | 98004-H34207 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34208 | 98004-H34208 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34209 | 98004-H34209 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34210 | 98004-H34210 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34211 | 98004-H34211 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34212 | 98004-H34212 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34213 | 98004-H34213 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34214 | 98004-H34214 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34215 | 98004-H34215 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34216 | 98004-H34216 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34217 | 98004-H34217 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34218 | 98004-H34218 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34219 | 98004-H34219 | \$ 47.00 | 6% | <i>\$44.51</i> |
| EWP Premier NBD AHR H34220 | 98004-H34220 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34221 | 98004-H34221 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34222 | 98004-H34222 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34223 | 98004-H34223 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34224 | 98004-H34224 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34225 | 98004-H34225 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34226 | 98004-H34226 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34227 | 98004-H34227 | \$ 68.00 | 6% | <i>\$64.40</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34228 | 98004-H34228 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34229 | 98004-H34229 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34230 | 98004-H34230 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34231 | 98004-H34231 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34232 | 98004-H34232 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34233 | 98004-H34233 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34234 | 98004-H34234 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34235 | 98004-H34235 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34236 | 98004-H34236 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34237 | 98004-H34237 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34238 | 98004-H34238 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34239 | 98004-H34239 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34240 | 98004-H34240 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34241 | 98004-H34241 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34242 | 98004-H34242 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34243 | 98004-H34243 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34244 | 98004-H34244 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34245 | 98004-H34245 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34246 | 98004-H34246 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34247 | 98004-H34247 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34248 | 98004-H34248 | \$ 68.00 | 6% | <i>\$64.40</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34249 | 98004-H34249 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34250 | 98004-H34250 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34251 | 98004-H34251 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34252 | 98004-H34252 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34253 | 98004-H34253 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34254 | 98004-H34254 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34255 | 98004-H34255 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34256 | 98004-H34256 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34257 | 98004-H34257 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34258 | 98004-H34258 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34259 | 98004-H34259 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34260 | 98004-H34260 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34261 | 98004-H34261 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34262 | 98004-H34262 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34263 | 98004-H34263 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34264 | 98004-H34264 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34265 | 98004-H34265 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier NBD AHR H34266 | 98004-H34266 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34267 | 98004-H34267 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34268 | 98004-H34268 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34269 | 98004-H34269 | \$ 51.00 | 6% | <i>\$48.30</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34270 | 98004-H34270 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34271 | 98004-H34271 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34272 | 98004-H34272 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34273 | 98004-H34273 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34274 | 98004-H34274 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34275 | 98004-H34275 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34276 | 98004-H34276 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34277 | 98004-H34277 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34278 | 98004-H34278 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34279 | 98004-H34279 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34280 | 98004-H34280 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34281 | 98004-H34281 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34282 | 98004-H34282 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34283 | 98004-H34283 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34284 | 98004-H34284 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34285 | 98004-H34285 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34286 | 98004-H34286 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34287 | 98004-H34287 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34288 | 98004-H34288 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34289 | 98004-H34289 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34290 | 98004-H34290 | \$ 51.00 | 6% | <i>\$48.30</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34291 | 98004-H34291 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34292 | 98004-H34292 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34293 | 98004-H34293 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34294 | 98004-H34294 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34295 | 98004-H34295 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34296 | 98004-H34296 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34297 | 98004-H34297 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34298 | 98004-H34298 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34299 | 98004-H34299 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34300 | 98004-H34300 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34301 | 98004-H34301 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34302 | 98004-H34302 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34303 | 98004-H34303 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34304 | 98004-H34304 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34305 | 98004-H34305 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H34306 | 98004-H34306 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34307 | 98004-H34307 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34308 | 98004-H34308 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34309 | 98004-H34309 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34310 | 98004-H34310 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34311 | 98004-H34311 | \$ 77.00 | 6% | <i>\$72.92</i> |

| | | | | |
|-------------------------------|--------------|----------|----|---------|
| EWP Premier NBD AHR H34312 | 98004-H34312 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34313 | 98004-H34313 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34314 | 98004-H34314 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34315 | 98004-H34315 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34316 | 98004-H34316 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34317 | 98004-H34317 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34318 | 98004-H34318 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34319 | 98004-H34319 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34320 | 98004-H34320 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34321 | 98004-H34321 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34322 | 98004-H34322 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34323 | 98004-H34323 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34324 | 98004-H34324 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34325 | 98004-H34325 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34326 | 98004-H34326 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34327 | 98004-H34327 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34328 | 98004-H34328 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34329 | 98004-H34329 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34330 | 98004-H34330 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34331 | 98004-H34331 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34332 | 98004-H34332 | \$ 77.00 | 6% | \$72.92 |

| | | | | |
|-------------------------------|--------------|----------|----|---------|
| EWP Premier NBD AHR H34333 | 98004-H34333 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34334 | 98004-H34334 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34335 | 98004-H34335 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34336 | 98004-H34336 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34337 | 98004-H34337 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34338 | 98004-H34338 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34339 | 98004-H34339 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34340 | 98004-H34340 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34341 | 98004-H34341 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34342 | 98004-H34342 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34343 | 98004-H34343 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34344 | 98004-H34344 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34345 | 98004-H34345 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34346 | 98004-H34346 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34347 | 98004-H34347 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34348 | 98004-H34348 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34349 | 98004-H34349 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34350 | 98004-H34350 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34351 | 98004-H34351 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34352 | 98004-H34352 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34353 | 98004-H34353 | \$ 77.00 | 6% | \$72.92 |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34354 | 98004-H34354 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34355 | 98004-H34355 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34356 | 98004-H34356 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34357 | 98004-H34357 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34358 | 98004-H34358 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34359 | 98004-H34359 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34360 | 98004-H34360 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34361 | 98004-H34361 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34362 | 98004-H34362 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34363 | 98004-H34363 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34364 | 98004-H34364 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34365 | 98004-H34365 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34366 | 98004-H34366 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34367 | 98004-H34367 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34368 | 98004-H34368 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34369 | 98004-H34369 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34370 | 98004-H34370 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34371 | 98004-H34371 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34372 | 98004-H34372 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34373 | 98004-H34373 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34374 | 98004-H34374 | \$ 118.00 | 6% | <i>\$111.75</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34375 | 98004-H34375 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34376 | 98004-H34376 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34377 | 98004-H34377 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34378 | 98004-H34378 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34379 | 98004-H34379 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34380 | 98004-H34380 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34381 | 98004-H34381 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34382 | 98004-H34382 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34383 | 98004-H34383 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34384 | 98004-H34384 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34385 | 98004-H34385 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34386 | 98004-H34386 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34387 | 98004-H34387 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34388 | 98004-H34388 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34389 | 98004-H34389 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34390 | 98004-H34390 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34391 | 98004-H34391 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34392 | 98004-H34392 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34393 | 98004-H34393 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34394 | 98004-H34394 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34395 | 98004-H34395 | \$ 118.00 | 6% | <i>\$111.75</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34396 | 98004-H34396 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34397 | 98004-H34397 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34398 | 98004-H34398 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34399 | 98004-H34399 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34400 | 98004-H34400 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34401 | 98004-H34401 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34402 | 98004-H34402 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD AHR H34403 | 98004-H34403 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34404 | 98004-H34404 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34405 | 98004-H34405 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34406 | 98004-H34406 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34407 | 98004-H34407 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34408 | 98004-H34408 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34409 | 98004-H34409 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34410 | 98004-H34410 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34411 | 98004-H34411 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34412 | 98004-H34412 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34413 | 98004-H34413 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34414 | 98004-H34414 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34415 | 98004-H34415 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34416 | 98004-H34416 | \$ 187.00 | 6% | <i>\$177.10</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34417 | 98004-H34417 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34418 | 98004-H34418 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34419 | 98004-H34419 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34420 | 98004-H34420 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34421 | 98004-H34421 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34422 | 98004-H34422 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34423 | 98004-H34423 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34424 | 98004-H34424 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34425 | 98004-H34425 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34426 | 98004-H34426 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34427 | 98004-H34427 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34428 | 98004-H34428 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34429 | 98004-H34429 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34430 | 98004-H34430 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34431 | 98004-H34431 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34432 | 98004-H34432 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34433 | 98004-H34433 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34434 | 98004-H34434 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34435 | 98004-H34435 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34436 | 98004-H34436 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34437 | 98004-H34437 | \$ 187.00 | 6% | <i>\$177.10</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34438 | 98004-H34438 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34439 | 98004-H34439 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34440 | 98004-H34440 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34441 | 98004-H34441 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34442 | 98004-H34442 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34443 | 98004-H34443 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34444 | 98004-H34444 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34445 | 98004-H34445 | \$ 187.00 | 6% | <i>\$177.10</i> |
| EWP Premier NBD AHR H34446 | 98004-H34446 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34447 | 98004-H34447 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34448 | 98004-H34448 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34449 | 98004-H34449 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34450 | 98004-H34450 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34451 | 98004-H34451 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34452 | 98004-H34452 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34453 | 98004-H34453 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34454 | 98004-H34454 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34455 | 98004-H34455 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34456 | 98004-H34456 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34457 | 98004-H34457 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34458 | 98004-H34458 | \$ 218.00 | 6% | <i>\$206.46</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34459 | 98004-H34459 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34460 | 98004-H34460 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34461 | 98004-H34461 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34462 | 98004-H34462 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34463 | 98004-H34463 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34464 | 98004-H34464 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34465 | 98004-H34465 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34466 | 98004-H34466 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34467 | 98004-H34467 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34468 | 98004-H34468 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34469 | 98004-H34469 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34470 | 98004-H34470 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34471 | 98004-H34471 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34472 | 98004-H34472 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34473 | 98004-H34473 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34474 | 98004-H34474 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34475 | 98004-H34475 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34476 | 98004-H34476 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34477 | 98004-H34477 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34478 | 98004-H34478 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34479 | 98004-H34479 | \$ 218.00 | 6% | <i>\$206.46</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD AHR H34480 | 98004-H34480 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34481 | 98004-H34481 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34482 | 98004-H34482 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34483 | 98004-H34483 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34484 | 98004-H34484 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34485 | 98004-H34485 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34486 | 98004-H34486 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34487 | 98004-H34487 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34488 | 98004-H34488 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34489 | 98004-H34489 | \$ 218.00 | 6% | <i>\$206.46</i> |
| EWP Premier NBD AHR H34490 | 98004-H34490 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34491 | 98004-H34491 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34492 | 98004-H34492 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34493 | 98004-H34493 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34494 | 98004-H34494 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34495 | 98004-H34495 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34496 | 98004-H34496 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34497 | 98004-H34497 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34498 | 98004-H34498 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34499 | 98004-H34499 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34500 | 98004-H34500 | \$ 33.00 | 6% | <i>\$31.25</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34501 | 98004-H34501 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34502 | 98004-H34502 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34503 | 98004-H34503 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34504 | 98004-H34504 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34505 | 98004-H34505 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34506 | 98004-H34506 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34507 | 98004-H34507 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34508 | 98004-H34508 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34509 | 98004-H34509 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34510 | 98004-H34510 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34511 | 98004-H34511 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34512 | 98004-H34512 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34513 | 98004-H34513 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34514 | 98004-H34514 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34515 | 98004-H34515 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34516 | 98004-H34516 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34517 | 98004-H34517 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34518 | 98004-H34518 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34519 | 98004-H34519 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34520 | 98004-H34520 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34521 | 98004-H34521 | \$ 33.00 | 6% | <i>\$31.25</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34522 | 98004-H34522 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34523 | 98004-H34523 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34524 | 98004-H34524 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34525 | 98004-H34525 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34526 | 98004-H34526 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34527 | 98004-H34527 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34528 | 98004-H34528 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34529 | 98004-H34529 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34530 | 98004-H34530 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34531 | 98004-H34531 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34532 | 98004-H34532 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34533 | 98004-H34533 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34534 | 98004-H34534 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34535 | 98004-H34535 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34536 | 98004-H34536 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34537 | 98004-H34537 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34538 | 98004-H34538 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34539 | 98004-H34539 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34540 | 98004-H34540 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34541 | 98004-H34541 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34542 | 98004-H34542 | \$ 33.00 | 6% | <i>\$31.25</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34543 | 98004-H34543 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34544 | 98004-H34544 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34545 | 98004-H34545 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34546 | 98004-H34546 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34547 | 98004-H34547 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34548 | 98004-H34548 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34549 | 98004-H34549 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34550 | 98004-H34550 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34551 | 98004-H34551 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34552 | 98004-H34552 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34553 | 98004-H34553 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34554 | 98004-H34554 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34555 | 98004-H34555 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34556 | 98004-H34556 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34557 | 98004-H34557 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34558 | 98004-H34558 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34559 | 98004-H34559 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34560 | 98004-H34560 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34561 | 98004-H34561 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34562 | 98004-H34562 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34563 | 98004-H34563 | \$ 33.00 | 6% | <i>\$31.25</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34564 | 98004-H34564 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34565 | 98004-H34565 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34566 | 98004-H34566 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34567 | 98004-H34567 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34568 | 98004-H34568 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34569 | 98004-H34569 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34570 | 98004-H34570 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34571 | 98004-H34571 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34572 | 98004-H34572 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34573 | 98004-H34573 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34574 | 98004-H34574 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34575 | 98004-H34575 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34576 | 98004-H34576 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34577 | 98004-H34577 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34578 | 98004-H34578 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34579 | 98004-H34579 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34580 | 98004-H34580 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34581 | 98004-H34581 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34582 | 98004-H34582 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34583 | 98004-H34583 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34584 | 98004-H34584 | \$ 33.00 | 6% | <i>\$31.25</i> |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34585 | 98004-H34585 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34586 | 98004-H34586 | \$ 33.00 | 6% | <i>\$31.25</i> |
| EWP Premier NBD AHR H34587 | 98004-H34587 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34588 | 98004-H34588 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34589 | 98004-H34589 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34590 | 98004-H34590 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34591 | 98004-H34591 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34592 | 98004-H34592 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34593 | 98004-H34593 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34594 | 98004-H34594 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34595 | 98004-H34595 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34596 | 98004-H34596 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34597 | 98004-H34597 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34598 | 98004-H34598 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34599 | 98004-H34599 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34600 | 98004-H34600 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34601 | 98004-H34601 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34602 | 98004-H34602 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34603 | 98004-H34603 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34604 | 98004-H34604 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H34605 | 98004-H34605 | \$ 77.00 | 6% | <i>\$72.92</i> |

| | | | | |
|-------------------------------|--------------|----------|----|---------|
| EWP Premier NBD AHR H34606 | 98004-H34606 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34607 | 98004-H34607 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34608 | 98004-H34608 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34609 | 98004-H34609 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34610 | 98004-H34610 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34611 | 98004-H34611 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34612 | 98004-H34612 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34613 | 98004-H34613 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34614 | 98004-H34614 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34615 | 98004-H34615 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34616 | 98004-H34616 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34617 | 98004-H34617 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34618 | 98004-H34618 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34619 | 98004-H34619 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34620 | 98004-H34620 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34621 | 98004-H34621 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34622 | 98004-H34622 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34623 | 98004-H34623 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34624 | 98004-H34624 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34625 | 98004-H34625 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34626 | 98004-H34626 | \$ 77.00 | 6% | \$72.92 |

| | | | | |
|-------------------------------|--------------|----------|----|---------|
| EWP Premier NBD AHR H34627 | 98004-H34627 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34628 | 98004-H34628 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34629 | 98004-H34629 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34630 | 98004-H34630 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34631 | 98004-H34631 | \$ 77.00 | 6% | \$72.92 |
| EWP Premier NBD AHR H34632 | 98004-H34632 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34633 | 98004-H34633 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34634 | 98004-H34634 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34635 | 98004-H34635 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34636 | 98004-H34636 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34637 | 98004-H34637 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34638 | 98004-H34638 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34639 | 98004-H34639 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34640 | 98004-H34640 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34641 | 98004-H34641 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34642 | 98004-H34642 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34643 | 98004-H34643 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34644 | 98004-H34644 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34645 | 98004-H34645 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34646 | 98004-H34646 | \$ 88.00 | 6% | \$83.34 |
| EWP Premier NBD AHR H34647 | 98004-H34647 | \$ 88.00 | 6% | \$83.34 |

| | | | | |
|-------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD AHR H34648 | 98004-H34648 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34649 | 98004-H34649 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34650 | 98004-H34650 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34651 | 98004-H34651 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34652 | 98004-H34652 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34653 | 98004-H34653 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34654 | 98004-H34654 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34655 | 98004-H34655 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34656 | 98004-H34656 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34657 | 98004-H34657 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34658 | 98004-H34658 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34659 | 98004-H34659 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34660 | 98004-H34660 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34661 | 98004-H34661 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34662 | 98004-H34662 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34663 | 98004-H34663 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34664 | 98004-H34664 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34665 | 98004-H34665 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34666 | 98004-H34666 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34667 | 98004-H34667 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34668 | 98004-H34668 | \$ 88.00 | 6% | <i>\$83.34</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|----------------|
| EWP Premier NBD AHR H34669 | 98004-H34669 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34670 | 98004-H34670 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34671 | 98004-H34671 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34672 | 98004-H34672 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34673 | 98004-H34673 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34674 | 98004-H34674 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34675 | 98004-H34675 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34676 | 98004-H34676 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34677 | 98004-H34677 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34678 | 98004-H34678 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD AHR H34679 | 98004-H34679 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34680 | 98004-H34680 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34681 | 98004-H34681 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34682 | 98004-H34682 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34683 | 98004-H34683 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34684 | 98004-H34684 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34685 | 98004-H34685 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34686 | 98004-H34686 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34687 | 98004-H34687 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34688 | 98004-H34688 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34689 | 98004-H34689 | \$ 101.00 | 6% | <i>\$95.65</i> |

| | | | | |
|-------------------------------|--------------|-----------|----|----------------|
| EWP Premier NBD AHR H34690 | 98004-H34690 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34691 | 98004-H34691 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34692 | 98004-H34692 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34693 | 98004-H34693 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34694 | 98004-H34694 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34695 | 98004-H34695 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34696 | 98004-H34696 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34697 | 98004-H34697 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34698 | 98004-H34698 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34699 | 98004-H34699 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34700 | 98004-H34700 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34701 | 98004-H34701 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34702 | 98004-H34702 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34703 | 98004-H34703 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34704 | 98004-H34704 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34705 | 98004-H34705 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34706 | 98004-H34706 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34707 | 98004-H34707 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34708 | 98004-H34708 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34709 | 98004-H34709 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34710 | 98004-H34710 | \$ 101.00 | 6% | <i>\$95.65</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H34711 | 98004-H34711 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34712 | 98004-H34712 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34713 | 98004-H34713 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34714 | 98004-H34714 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34715 | 98004-H34715 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34716 | 98004-H34716 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34717 | 98004-H34717 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34718 | 98004-H34718 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34719 | 98004-H34719 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34720 | 98004-H34720 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34721 | 98004-H34721 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34722 | 98004-H34722 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34723 | 98004-H34723 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34724 | 98004-H34724 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34725 | 98004-H34725 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier NBD AHR H34726 | 98004-H34726 | \$ 2,607.00 | 6% | <i>\$2,468.96</i> |
| EWP Premier NBD AHR H34727 | 98004-H34727 | \$ 2,607.00 | 6% | <i>\$2,468.96</i> |
| EWP Premier NBD AHR H34728 | 98004-H34728 | \$ 2,607.00 | 6% | <i>\$2,468.96</i> |
| EWP Premier NBD AHR H34729 | 98004-H34729 | \$ 2,607.00 | 6% | <i>\$2,468.96</i> |
| EWP Premier NBD AHR H34730 | 98004-H34730 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H34731 | 98004-H34731 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H34732 | 98004-H34732 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H34733 | 98004-H34733 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H34734 | 98004-H34734 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWP Premier NBD AHR H34735 | 98004-H34735 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWP Premier NBD AHR H34736 | 98004-H34736 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWP Premier NBD AHR H34737 | 98004-H34737 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWP Premier NBD AHR H34738 | 98004-H34738 | \$ 977.00 | 6% | <i>\$925.27</i> |
| EWP Premier NBD AHR H34739 | 98004-H34739 | \$ 977.00 | 6% | <i>\$925.27</i> |
| EWP Premier NBD AHR H34740 | 98004-H34740 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWP Premier NBD AHR H34741 | 98004-H34741 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWP Premier NBD AHR H34742 | 98004-H34742 | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier NBD AHR H34743 | 98004-H34743 | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier NBD AHR H34744 | 98004-H34744 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWP Premier NBD AHR H34745 | 98004-H34745 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWP Premier NBD AHR H34746 | 98004-H34746 | \$ 585.00 | 6% | <i>\$554.02</i> |
| EWP Premier NBD AHR H34747 | 98004-H34747 | \$ 585.00 | 6% | <i>\$554.02</i> |
| EWP Premier NBD AHR H34748 | 98004-H34748 | \$ 977.00 | 6% | <i>\$925.27</i> |
| EWP Premier NBD AHR H34749 | 98004-H34749 | \$ 977.00 | 6% | <i>\$925.27</i> |
| EWP Premier NBD AHR H34750 | 98004-H34750 | \$ 977.00 | 6% | <i>\$925.27</i> |
| EWP Premier NBD AHR H34751 | 98004-H34751 | \$ 977.00 | 6% | <i>\$925.27</i> |
| EWP Premier NBD AHR H34752 | 98004-H34752 | \$ 977.00 | 6% | <i>\$925.27</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|-------------|
| EWP Premier NBD AHR H34753 | 98004-H34753 | \$ 977.00 | 6% | \$925.27 |
| EWP Premier NBD AHR H34754 | 98004-H34754 | \$ 977.00 | 6% | \$925.27 |
| EWP Premier NBD AHR H34755 | 98004-H34755 | \$ 977.00 | 6% | \$925.27 |
| EWP Premier NBD AHR H34756 | 98004-H34756 | \$ 512.00 | 6% | \$484.89 |
| EWP Premier NBD AHR H34757 | 98004-H34757 | \$ 512.00 | 6% | \$484.89 |
| EWP Premier NBD AHR H34758 | 98004-H34758 | \$ 512.00 | 6% | \$484.89 |
| EWP Premier NBD AHR H34759 | 98004-H34759 | \$ 512.00 | 6% | \$484.89 |
| EWP Premier NBD AHR H34760 | 98004-H34760 | \$ 512.00 | 6% | \$484.89 |
| EWP Premier NBD AHR H34761 | 98004-H34761 | \$ 512.00 | 6% | \$484.89 |
| EWP Premier NBD AHR H34839 | 98004-H34839 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34840 | 98004-H34840 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34841 | 98004-H34841 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34842 | 98004-H34842 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34843 | 98004-H34843 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34844 | 98004-H34844 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34845 | 98004-H34845 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34846 | 98004-H34846 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD AHR H34993 | 98004-H34993 | \$ 12,982.00 | 6% | \$12,294.60 |
| EWP Premier NBD AHR H34994 | 98004-H34994 | \$ 12,982.00 | 6% | \$12,294.60 |
| EWP Premier NBD AHR H34996 | 98004-H34996 | \$ 12,982.00 | 6% | \$12,294.60 |
| EWP Premier NBD AHR H34997 | 98004-H34997 | \$ 12,982.00 | 6% | \$12,294.60 |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H35005 | 98004-H35005 | \$ 9,478.00 | 6% | <i>\$8,976.14</i> |
| EWP Premier NBD AHR H35006 | 98004-H35006 | \$ 9,478.00 | 6% | <i>\$8,976.14</i> |
| EWP Premier NBD AHR H35012 | 98004-H35012 | \$ 5,688.00 | 6% | <i>\$5,386.82</i> |
| EWP Premier NBD AHR H35070 | 98004-H35070 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35071 | 98004-H35071 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35072 | 98004-H35072 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35073 | 98004-H35073 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35074 | 98004-H35074 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35075 | 98004-H35075 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35076 | 98004-H35076 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35077 | 98004-H35077 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35078 | 98004-H35078 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35079 | 98004-H35079 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD AHR H35080 | 98004-H35080 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H35081 | 98004-H35081 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H35082 | 98004-H35082 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H35083 | 98004-H35083 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD AHR H35090 | 98004-H35090 | \$ 560.00 | 6% | <i>\$530.35</i> |
| EWP Premier NBD AHR H35091 | 98004-H35091 | \$ 2,797.00 | 6% | <i>\$2,648.90</i> |
| EWP Premier NBD AHR H35262 | 98004-H35262 | \$ 2,710.00 | 6% | <i>\$2,566.51</i> |
| EWP Premier NBD AHR H35270 | 98004-H35270 | \$ 350.00 | 6% | <i>\$331.47</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H35271 | 98004-H35271 | \$ 263.00 | 6% | <i>\$249.07</i> |
| EWP Premier NBD AHR H35273 | 98004-H35273 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier NBD AHR H35274 | 98004-H35274 | \$ 585.00 | 6% | <i>\$554.02</i> |
| EWP Premier NBD AHR H35275 | 98004-H35275 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier NBD AHR H35276 | 98004-H35276 | \$ 2,506.00 | 6% | <i>\$2,373.31</i> |
| EWP Premier NBD AHR H35277 | 98004-H35277 | \$ 3,000.00 | 6% | <i>\$2,841.15</i> |
| EWP Premier NBD AHR H35278 | 98004-H35278 | \$ 2,010.00 | 6% | <i>\$1,903.57</i> |
| EWP Premier NBD AHR H35279 | 98004-H35279 | \$ 2,245.00 | 6% | <i>\$2,126.13</i> |
| EWP Premier NBD AHR H35280 | 98004-H35280 | \$ 3,313.00 | 6% | <i>\$3,137.58</i> |
| EWP Premier NBD AHR H35281 | 98004-H35281 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35282 | 98004-H35282 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35283 | 98004-H35283 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35284 | 98004-H35284 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35285 | 98004-H35285 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35286 | 98004-H35286 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35287 | 98004-H35287 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35288 | 98004-H35288 | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWP Premier NBD AHR H35289 | 98004-H35289 | \$ 4,729.00 | 6% | <i>\$4,478.60</i> |
| EWP Premier NBD AHR H35291 | 98004-H35291 | \$ 3,405.00 | 6% | <i>\$3,224.71</i> |
| EWP Premier NBD AHR H35294 | 98004-H35294 | \$ 923.00 | 6% | <i>\$874.13</i> |
| EWP Premier NBD AHR H35295 | 98004-H35295 | \$ 311.00 | 6% | <i>\$294.53</i> |

| | | | | |
|-------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD AHR H35296 | 98004-H35296 | \$ 7,508.00 | 6% | <i>\$7,110.45</i> |
| EWP Premier NBD AHR H35297 | 98004-H35297 | \$ 7,508.00 | 6% | <i>\$7,110.45</i> |
| EWP Premier NBD AHR H35298 | 98004-H35298 | \$ 12,059.00 | 6% | <i>\$11,420.48</i> |
| EWP Premier NBD AHR H35299 | 98004-H35299 | \$ 12,059.00 | 6% | <i>\$11,420.48</i> |
| EWP Premier NBD AHR H35302 | 98004-H35302 | \$ 2,936.00 | 6% | <i>\$2,780.54</i> |
| EWP Premier NBD AHR H35303 | 98004-H35303 | \$ 2,936.00 | 6% | <i>\$2,780.54</i> |
| EWP Premier NBD AHR H35304 | 98004-H35304 | \$ 2,936.00 | 6% | <i>\$2,780.54</i> |
| EWP Premier NBD AHR H35305 | 98004-H35305 | \$ 3,080.00 | 6% | <i>\$2,916.91</i> |
| EWP Premier NBD AHR H35306 | 98004-H35306 | \$ 3,080.00 | 6% | <i>\$2,916.91</i> |
| EWP Premier NBD AHR H35307 | 98004-H35307 | \$ 3,080.00 | 6% | <i>\$2,916.91</i> |
| EWP Premier NBD AHR H35309 | 98004-H35309 | \$ 3,313.00 | 6% | <i>\$3,137.58</i> |
| EWP Premier NBD AHR H35310 | 98004-H35310 | \$ 3,313.00 | 6% | <i>\$3,137.58</i> |
| EWP Premier NBD AHR H35311 | 98004-H35311 | \$ 3,313.00 | 6% | <i>\$3,137.58</i> |
| EWP Premier NBD AHR H35312 | 98004-H35312 | \$ 2,741.00 | 6% | <i>\$2,595.86</i> |
| EWP Premier NBD AHR H35313 | 98004-H35313 | \$ 2,741.00 | 6% | <i>\$2,595.86</i> |
| EWP Premier NBD AHR H35314 | 98004-H35314 | \$ 2,741.00 | 6% | <i>\$2,595.86</i> |
| EWP Premier NBD AHR H35315 | 98004-H35315 | \$ 1,219.00 | 6% | <i>\$1,154.45</i> |
| EWP Premier NBD AHR H35318 | 98004-H35318 | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier NBD AHR H35319 | 98004-H35319 | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWP Premier NBD AHR H35320 | 98004-H35320 | \$ 804.00 | 6% | <i>\$761.43</i> |
| EWP Premier NBD AHR H35321 | 98004-H35321 | \$ 1,026.00 | 6% | <i>\$971.67</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H35322 | 98004-H35322 | \$ 1,243.00 | 6% | <i>\$1,177.18</i> |
| EWP Premier NBD AHR H35323 | 98004-H35323 | \$ 1,219.00 | 6% | <i>\$1,154.45</i> |
| EWP Premier NBD AHR H35328 | 98004-H35328 | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier NBD AHR H35330 | 98004-H35330 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier NBD AHR H35332 | 98004-H35332 | \$ 2,972.00 | 6% | <i>\$2,814.63</i> |
| EWP Premier NBD AHR H35333 | 98004-H35333 | \$ 2,972.00 | 6% | <i>\$2,814.63</i> |
| EWP Premier NBD AHR H35340 | 98004-H35340 | \$ 3,180.00 | 6% | <i>\$3,011.62</i> |
| EWP Premier NBD AHR H35341 | 98004-H35341 | \$ 3,180.00 | 6% | <i>\$3,011.62</i> |
| EWP Premier NBD AHR H35342 | 98004-H35342 | \$ 2,664.00 | 6% | <i>\$2,522.94</i> |
| EWP Premier NBD AHR H35343 | 98004-H35343 | \$ 3,180.00 | 6% | <i>\$3,011.62</i> |
| EWP Premier NBD AHR H35344 | 98004-H35344 | \$ 3,278.00 | 6% | <i>\$3,104.43</i> |
| EWP Premier NBD AHR H35345 | 98004-H35345 | \$ 3,278.00 | 6% | <i>\$3,104.43</i> |
| EWP Premier NBD AHR H35346 | 98004-H35346 | \$ 2,737.00 | 6% | <i>\$2,592.08</i> |
| EWP Premier NBD AHR H35347 | 98004-H35347 | \$ 3,278.00 | 6% | <i>\$3,104.43</i> |
| EWP Premier NBD AHR H35349 | 98004-H35349 | \$ 3,522.00 | 6% | <i>\$3,335.51</i> |
| EWP Premier NBD AHR H35350 | 98004-H35350 | \$ 3,522.00 | 6% | <i>\$3,335.51</i> |
| EWP Premier NBD AHR H35351 | 98004-H35351 | \$ 2,930.00 | 6% | <i>\$2,774.86</i> |
| EWP Premier NBD AHR H35352 | 98004-H35352 | \$ 3,522.00 | 6% | <i>\$3,335.51</i> |
| EWP Premier NBD AHR H35359 | 98004-H35359 | \$ 1,026.00 | 6% | <i>\$971.67</i> |
| EWP Premier NBD AHR H35360 | 98004-H35360 | \$ 1,243.00 | 6% | <i>\$1,177.18</i> |
| EWP Premier NBD AHR H35361 | 98004-H35361 | \$ 1,219.00 | 6% | <i>\$1,154.45</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H35362 | 98004-H35362 | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier NBD AHR H35366 | 98004-H35366 | \$ 1,471.00 | 6% | <i>\$1,393.11</i> |
| EWP Premier NBD AHR H35367 | 98004-H35367 | \$ 1,716.00 | 6% | <i>\$1,625.14</i> |
| EWP Premier NBD AHR H35368 | 98004-H35368 | \$ 2,613.00 | 6% | <i>\$2,474.64</i> |
| EWP Premier NBD AHR H35369 | 98004-H35369 | \$ 852.00 | 6% | <i>\$806.89</i> |
| EWP Premier NBD AHR H35370 | 98004-H35370 | \$ 1,192.00 | 6% | <i>\$1,128.88</i> |
| EWP Premier NBD AHR H35375 | 98004-H35375 | \$ 727.00 | 6% | <i>\$688.51</i> |
| EWP Premier NBD AHR H35376 | 98004-H35376 | \$ 1,083.00 | 6% | <i>\$1,025.66</i> |
| EWP Premier NBD AHR H35377 | 98004-H35377 | \$ 455.00 | 6% | <i>\$430.91</i> |
| EWP Premier NBD AHR H35378 | 98004-H35378 | \$ 727.00 | 6% | <i>\$688.51</i> |
| EWP Premier NBD AHR H35379 | 98004-H35379 | \$ 455.00 | 6% | <i>\$430.91</i> |
| EWP Premier NBD AHR H35380 | 98004-H35380 | \$ 817.00 | 6% | <i>\$773.74</i> |
| EWP Premier NBD AHR H35381 | 98004-H35381 | \$ 999.00 | 6% | <i>\$946.10</i> |
| EWP Premier NBD AHR H35384 | 98004-H35384 | \$ 331.00 | 6% | <i>\$313.47</i> |
| EWP Premier NBD AHR H35385 | 98004-H35385 | \$ 435.00 | 6% | <i>\$411.97</i> |
| EWP Premier NBD AHR H35386 | 98004-H35386 | \$ 727.00 | 6% | <i>\$688.51</i> |
| EWP Premier NBD AHR H35387 | 98004-H35387 | \$ 679.00 | 6% | <i>\$643.05</i> |
| EWP Premier NBD AHR H35388 | 98004-H35388 | \$ 499.00 | 6% | <i>\$472.58</i> |
| EWP Premier NBD AHR H35389 | 98004-H35389 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H35390 | 98004-H35390 | \$ 243.00 | 6% | <i>\$230.13</i> |
| EWP Premier NBD AHR H35391 | 98004-H35391 | \$ 533.00 | 6% | <i>\$504.78</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H35392 | 98004-H35392 | \$ 817.00 | 6% | <i>\$773.74</i> |
| EWP Premier NBD AHR H35393 | 98004-H35393 | \$ 1,083.00 | 6% | <i>\$1,025.66</i> |
| EWP Premier NBD AHR H35394 | 98004-H35394 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier NBD AHR H35395 | 98004-H35395 | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier NBD AHR H35396 | 98004-H35396 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier NBD AHR H35397 | 98004-H35397 | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier NBD AHR H35398 | 98004-H35398 | \$ 506.00 | 6% | <i>\$479.21</i> |
| EWP Premier NBD AHR H35399 | 98004-H35399 | \$ 616.00 | 6% | <i>\$583.38</i> |
| EWP Premier NBD AHR H35400 | 98004-H35400 | \$ 680.00 | 6% | <i>\$643.99</i> |
| EWP Premier NBD AHR H35401 | 98004-H35401 | \$ 362.00 | 6% | <i>\$342.83</i> |
| EWP Premier NBD AHR H35415 | 98004-H35415 | \$ 246.00 | 6% | <i>\$232.97</i> |
| EWP Premier NBD AHR H35416 | 98004-H35416 | \$ 246.00 | 6% | <i>\$232.97</i> |
| EWP Premier NBD AHR H35426 | 98004-H35426 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD AHR H35427 | 98004-H35427 | \$ 679.00 | 6% | <i>\$643.05</i> |
| EWP Premier NBD AHR H35428 | 98004-H35428 | \$ 243.00 | 6% | <i>\$230.13</i> |
| EWP Premier NBD AHR H35429 | 98004-H35429 | \$ 533.00 | 6% | <i>\$504.78</i> |
| EWP Premier NBD AHR H35430 | 98004-H35430 | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWP Premier NBD AHR H35431 | 98004-H35431 | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWP Premier NBD AHR H35432 | 98004-H35432 | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier NBD AHR H35433 | 98004-H35433 | \$ 488.00 | 6% | <i>\$462.16</i> |
| EWP Premier NBD AHR H35434 | 98004-H35434 | \$ 557.00 | 6% | <i>\$527.51</i> |

| | | | | |
|-------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD AHR H35435 | 98004-H35435 | \$ 557.00 | 6% | <i>\$527.51</i> |
| EWP Premier NBD AHR H35436 | 98004-H35436 | \$ 930.00 | 6% | <i>\$880.76</i> |
| EWP Premier NBD AHR H35437 | 98004-H35437 | \$ 930.00 | 6% | <i>\$880.76</i> |
| EWP Premier NBD AHR H35438 | 98004-H35438 | \$ 930.00 | 6% | <i>\$880.76</i> |
| EWP Premier NBD AHR H35439 | 98004-H35439 | \$ 930.00 | 6% | <i>\$880.76</i> |
| EWP Premier NBD AHR H35440 | 98004-H35440 | \$ 488.00 | 6% | <i>\$462.16</i> |
| EWP Premier NBD AHR H35441 | 98004-H35441 | \$ 488.00 | 6% | <i>\$462.16</i> |
| EWP Premier NBD AHR H35442 | 98004-H35442 | \$ 488.00 | 6% | <i>\$462.16</i> |
| EWP Premier NBD AHR H35443 | 98004-H35443 | \$ 2,607.00 | 6% | <i>\$2,468.96</i> |
| EWP Premier NBD AHR H35444 | 98004-H35444 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H35445 | 98004-H35445 | \$ 2,506.00 | 6% | <i>\$2,373.31</i> |
| EWP Premier NBD AHR H35446 | 98004-H35446 | \$ 2,459.00 | 6% | <i>\$2,328.80</i> |
| EWP Premier NBD AHR H35447 | 98004-H35447 | \$ 2,857.00 | 6% | <i>\$2,705.72</i> |
| EWP Premier NBD AHR H35448 | 98004-H35448 | \$ 2,741.00 | 6% | <i>\$2,595.86</i> |
| EWP Premier NBD AHR H35449 | 98004-H35449 | \$ 2,010.00 | 6% | <i>\$1,903.57</i> |
| EWP Premier NBD AHR H35450 | 98004-H35450 | \$ 2,138.00 | 6% | <i>\$2,024.79</i> |
| EWP Premier NBD AHR H35451 | 98004-H35451 | \$ 3,523.00 | 6% | <i>\$3,336.46</i> |
| EWP Premier NBD AHR H35452 | 98004-H35452 | \$ 3,523.00 | 6% | <i>\$3,336.46</i> |
| EWP Premier NBD AHR H35453 | 98004-H35453 | \$ 2,793.00 | 6% | <i>\$2,645.11</i> |
| EWP Premier NBD AHR H35454 | 98004-H35454 | \$ 2,607.00 | 6% | <i>\$2,468.96</i> |
| EWP Premier NBD AHR H35455 | 98004-H35455 | \$ 804.00 | 6% | <i>\$761.43</i> |

| | | | | |
|---------------------------------------|-------------------------|-------------|----|-------------------|
| EWP Premier NBD AHR H35456 | 98004-H35456 | \$ 1,005.00 | 6% | <i>\$951.79</i> |
| EWP Premier NBD AHR H35457 | 98004-H35457 | \$ 906.00 | 6% | <i>\$858.03</i> |
| EWP Premier NBD AHR H35458 | 98004-H35458 | \$ 991.00 | 6% | <i>\$938.53</i> |
| EWP Premier NBD AHR H35471 | 98004-H35471 | \$ 804.00 | 6% | <i>\$761.43</i> |
| EWP Premier NBD AHR H35600 | 98004-H35600 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier NBD AHR H35601 | 98004-H35601 | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier NBD AHR H35602 | 98004-H35602 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWP Premier NBD AHR H35603 | 98004-H35603 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWP Premier NBD AHR H35604 | 98004-H35604 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWP Premier NBD AHR H35605 | 98004-H35605 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWP Premier NBD AHR H35606 | 98004-H35606 | \$ 585.00 | 6% | <i>\$554.02</i> |
| EWP Premier NBD AHR H35607 | 98004-H35607 | \$ 585.00 | 6% | <i>\$554.02</i> |
| EWP Premier NBD AHR ISW-24W-4X | 98004-ISW-24W-4X | \$ 827.00 | 6% | <i>\$783.21</i> |
| EWP Premier NBD AHR ISW-4W-4WS-4X | 98004-ISW-4W-4WS-4X | \$ 524.00 | 6% | <i>\$496.25</i> |
| EWP Premier NBD AHR MSM128 | 98004-MSM128 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |
| EWP Premier NBD AHR MSM48C | 98004-MSM48C | \$ 1,822.00 | 6% | <i>\$1,725.53</i> |
| EWP Premier NBD AHR R100-8T | 98004-R100-8T | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier NBD AHR SLX9150-48XT-DC-F | 98004-SLX9150-48XT-DC-F | \$ 2,832.00 | 6% | <i>\$2,682.05</i> |
| EWP Premier NBD AHR SLX9150-48XT-DC-R | 98004-SLX9150-48XT-DC-R | \$ 3,123.00 | 6% | <i>\$2,957.64</i> |

| | | | | |
|---|--------------------------------|--------------|-----|--------------------|
| EWP Premier NBD AHR SLX9150-48Y-DC-F | 98004- SLX9150-48Y- DC-F | \$ 2,748.00 | 6% | <i>\$2,602.49</i> |
| EWP Premier NBD AHR SLX9150-48Y-DC-R | 98004- SLX9150-48Y- DC-R | \$ 3,029.00 | 6% | <i>\$2,868.61</i> |
| EWP Premier NBD AHR SLX9740-40C | 98004- SLX9740-40C | \$ 12,320.00 | 6% | <i>\$11,667.66</i> |
| EWP Premier NBD AHR SLX9740-40C-AC-F | 98004- SLX9740-40C- AC-F | \$ 12,320.00 | 6% | <i>\$11,667.66</i> |
| EWP Premier NBD AHR SLX9740-40C-AC-R | 98004- SLX9740-40C- AC-R | \$ 12,320.00 | 10% | <i>\$11,171.16</i> |
| EWP Premier NBD AHR SLX9740-40C-DC-F | 98004- SLX9740-40C- DC-F | \$ 12,320.00 | 6% | <i>\$11,667.66</i> |
| EWP Premier NBD AHR SLX9740-80C | 98004- SLX9740-80C | \$ 23,166.00 | 6% | <i>\$21,939.36</i> |
| EWP Premier NBD AHR SLX9740-80C-AC-F | 98004- SLX9740-80C- AC-F | \$ 23,166.00 | 6% | <i>\$21,939.36</i> |
| EWP Premier NBD AHR SLX9740-80C-AC-R | 98004- SLX9740-80C- AC-R | \$ 23,166.00 | 10% | <i>\$21,005.77</i> |
| EWP Premier NBD AHR SLX9740-80C-DC-F | 98004- SLX9740-80C- DC-F | \$ 23,166.00 | 6% | <i>\$21,939.36</i> |
| EWP Premier NBD AHR V300- 8P-2X | 98004-V300- 8P-2X | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier NBD AHR V300- 8T-2X | 98004-V300- 8T-2X | \$ 93.00 | 6% | <i>\$88.08</i> |
| EWP Premier NBD AHR V300HT-8P-2X | 98004-V300HT- 8P-2X | \$ 307.00 | 6% | <i>\$290.74</i> |
| EWP Premier NBD AHR V300HT-8T-2X | 98004-V300HT- 8T-2X | \$ 185.00 | 6% | <i>\$175.20</i> |
| EWP Premier NBD AHR VIM- SS | 98004-VIM-SS | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier NBD AHR VIM- SSV80 | 98004-VIM- SSV80 | \$ 296.00 | 6% | <i>\$280.33</i> |

| | | | | |
|--|-----------------------------|-------------|----|-------------------|
| EWP Premier NBD AHR VIM2-SS | 98004-VIM2-SS | \$ 184.00 | 6% | <i>\$174.26</i> |
| EWP Premier NBD AHR VIM2-SS128 | 98004-VIM2-SS128 | \$ 637.00 | 6% | <i>\$603.27</i> |
| EWP Premier NBD AHR VIM2-V80 | 98004-VIM2-V80 | \$ 680.00 | 6% | <i>\$643.99</i> |
| EWP Premier NBD AHR VIM210G4X | 98004-VIM210G4X | \$ 1,175.00 | 6% | <i>\$1,112.78</i> |
| EWP Premier NBD AHR VIM5-2Q | 98004-VIM5-2Q | \$ 193.00 | 6% | <i>\$182.78</i> |
| EWP Premier NBD AHR VIM5-2Y | 98004-VIM5-2Y | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier NBD AHR VIM5-4X | 98004-VIM5-4X | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD AHR VIM5-4XE | 98004-VIM5-4XE | \$ 188.00 | 6% | <i>\$178.05</i> |
| EWP Premier NBD AHR VIM5-4Y | 98004-VIM5-4Y | \$ 290.00 | 6% | <i>\$274.64</i> |
| EWP Premier NBD AHR VIM5-4YE | 98004-VIM5-4YE | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Prem NBD AHR VSP4900-12MXU-12XE | 98004-VSP4900-12MXU-12XE | \$ 1,075.00 | 6% | <i>\$1,018.08</i> |
| EWP Prem NBD AHR VSP4900-12MXU-12XE-B1 | 98004-VSP4900-12MXU-12XE-B1 | \$ 1,075.00 | 6% | <i>\$1,018.08</i> |
| EWP Premier NBD AHR VSP4900-24S | 98004-VSP4900-24S | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier NBD AHR VSP4900-24S-B3 | 98004-VSP4900-24S-B3 | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier NBD AHR VSP4900-24XE | 98004-VSP4900-24XE | \$ 1,075.00 | 6% | <i>\$1,018.08</i> |
| EWP Premier NBD AHR VSP4900-24XE-B3 | 98004-VSP4900-24XE-B3 | \$ 1,075.00 | 6% | <i>\$1,018.08</i> |
| EWP Premier NBD AHR X435-24P-4S | 98004-X435-24P-4S | \$ 239.00 | 6% | <i>\$226.34</i> |
| EWP Premier NBD AHR X435-24T-4S | 98004-X435-24T-4S | \$ 131.00 | 6% | <i>\$124.06</i> |

| | | | | |
|----------------------------------|--------------------|-------------|----|-------------------|
| EWP Premier NBD AHR X435-8P-2T-W | 98004-X435-8P-2T-W | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD AHR X435-8P-4S | 98004-X435-8P-4S | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD AHR X435-8T-4S | 98004-X435-8T-4S | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD AHR X460-24P | 98004-X460-24P | \$ 1,051.00 | 6% | <i>\$995.35</i> |
| EWP Premier NBD AHR X460-24T | 98004-X460-24T | \$ 758.00 | 6% | <i>\$717.86</i> |
| EWP Premier NBD AHR X460-24TDC | 98004-X460-24TDC | \$ 1,109.00 | 6% | <i>\$1,050.28</i> |
| EWP Premier NBD AHR X460-24X | 98004-X460-24X | \$ 1,395.00 | 6% | <i>\$1,321.13</i> |
| EWP Premier NBD AHR X460-24XDC | 98004-X460-24XDC | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWP Premier NBD AHR X460-48P | 98004-X460-48P | \$ 1,395.00 | 6% | <i>\$1,321.13</i> |
| EWP Premier NBD AHR X460-48T | 98004-X460-48T | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWP Premier NBD AHR X460-48TDC | 98004-X460-48TDC | \$ 1,514.00 | 6% | <i>\$1,433.83</i> |
| EWP Premier NBD AHR X460-48X | 98004-X460-48X | \$ 1,858.00 | 6% | <i>\$1,759.62</i> |
| EWP Premier NBD AHR X460-48XDC | 98004-X460-48XDC | \$ 1,806.00 | 6% | <i>\$1,710.37</i> |
| EWP Premier NBD AHR X465-24MU | 98004-X465-24MU | \$ 1,243.00 | 6% | <i>\$1,177.18</i> |
| EWP Premier NBD AHR X465-24S | 98004-X465-24S | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier NBD AHR X465-24S-B3 | 98004-X465-24S-B3 | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier NBD AHR X465-24W | 98004-X465-24W | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier NBD AHR X465-24XE | 98004-X465-24XE | \$ 1,075.00 | 6% | <i>\$1,018.08</i> |
| EWP Premier NBD AHR X465-24XE-B3 | 98004-X465-24XE-B3 | \$ 1,075.00 | 6% | <i>\$1,018.08</i> |
| EWP Premier NBD AHR X465-48P | 98004-X465-48P | \$ 804.00 | 6% | <i>\$761.43</i> |
| EWP Premier NBD AHR X465-48T | 98004-X465-48T | \$ 776.00 | 6% | <i>\$734.91</i> |

| | | | | |
|--------------------------------------|------------------------|-------------|-----|-------------------|
| EWP Premier NBD AHR X465-48W | 98004-X465-48W | \$ 1,026.00 | 6% | <i>\$971.67</i> |
| EWP Premier NBD AHR X465i-48W | 98004-X465i-48W | \$ 1,219.00 | 6% | <i>\$1,154.45</i> |
| EWP Premier NBD AHR X465i-48W-B1-S1 | 98004-X465i-48W-B1-S1 | \$ 1,219.00 | 6% | <i>\$1,154.45</i> |
| EWP Premier NBD AHR X465i-48W-B2-S1 | 98004-X465i-48W-B2-S1 | \$ 1,219.00 | 6% | <i>\$1,154.45</i> |
| EWP Premier NBD AHR X480-24X | 98004-X480-24X | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWP Premier NBD AHR X480-48T | 98004-X480-48T | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWP Premier NBD AHR X480-48X | 98004-X480-48X | \$ 2,329.00 | 6% | <i>\$2,205.68</i> |
| EWP Premier NBD AHR X695-48Y-8C | 98004-X695-48Y-8C | \$ 2,806.00 | 6% | <i>\$2,657.42</i> |
| EWP Premier NBD AHR XA1440 | 98004-XA1440 | \$ 295.00 | 6% | <i>\$279.38</i> |
| EWP Premier NBD AHR XA1480 | 98004-XA1480 | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWP Premier NBD AHR XGM3-2SF | 98004-XGM3-2SF | \$ 296.00 | 6% | <i>\$280.33</i> |
| EWP Premier NBD AHR XR600 | 98004-XR600 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD AHR XSW-BR-M-A-D | 98004-XSW-BR-M-A-D | \$ 96.00 | 10% | <i>\$87.05</i> |
| EWP Premier NBD AHR XSW-BR-M-A-D-3YR | 98004-XSW-BR-M-A-D-3YR | \$ 287.00 | 10% | <i>\$260.24</i> |
| EWP Premier NBD AHR XSW-BR-M-A-D-5YR | 98004-XSW-BR-M-A-D-5YR | \$ 479.00 | 10% | <i>\$434.33</i> |
| EWP Premier NBD AHR XSW-BR-S-A-D | 98004-XSW-BR-S-A-D | \$ 55.00 | 10% | <i>\$49.87</i> |
| EWP Premier NBD AHR XSW-BR-S-A-D-3YR | 98004-XSW-BR-S-A-D-3YR | \$ 164.00 | 10% | <i>\$148.71</i> |
| EWP Premier NBD AHR XSW-BR-S-A-D-5YR | 98004-XSW-BR-S-A-D-5YR | \$ 273.00 | 10% | <i>\$247.54</i> |
| EWP Premier NBD AHR XSW-BR-XS-A-D | 98004-XSW-BR-XS-A-D | \$ 44.00 | 10% | <i>\$39.90</i> |

| | | | | |
|--|-----------------------------|-------------|-----|-------------------|
| EWP Premier NBD AHR XSW-BR-XS-A-D-3YR | 98004-XSW-BR-XS-A-D-3YR | \$ 133.00 | 10% | <i>\$120.60</i> |
| EWP Premier NBD AHR XSW-BR-XS-A-D-5YR | 98004-XSW-BR-XS-A-D-5YR | \$ 221.00 | 10% | <i>\$200.39</i> |
| EWP Premier NBD AHR XSW-DC-M-A-D | 98004-XSW-DC-M-A-D | \$ 355.00 | 10% | <i>\$321.90</i> |
| EWP Premier NBD AHR XSW-DC-M-A-D-3YR | 98004-XSW-DC-M-A-D-3YR | \$ 1,066.00 | 10% | <i>\$966.60</i> |
| EWP Premier NBD AHR XSW-DC-M-A-D-5YR | 98004-XSW-DC-M-A-D-5YR | \$ 1,777.00 | 10% | <i>\$1,611.29</i> |
| EWP Premier NBD AHR XSW-DC-S-A-D | 98004-XSW-DC-S-A-D | \$ 164.00 | 10% | <i>\$148.71</i> |
| EWP Premier NBD AHR XSW-DC-S-A-D-3YR | 98004-XSW-DC-S-A-D-3YR | \$ 492.00 | 10% | <i>\$446.12</i> |
| EWP Premier NBD AHR XSW-DC-S-A-D-5YR | 98004-XSW-DC-S-A-D-5YR | \$ 820.00 | 10% | <i>\$743.54</i> |
| EWP Premier NBD AHR XSW-DC-SR-L-A-D | 98004-XSW-DC-SR-L-A-D | \$ 410.00 | 10% | <i>\$371.77</i> |
| EWP Premier NBD AHR XSW-DC-SR-L-A-D-3YR | 98004-XSW-DC-SR-L-A-D-3YR | \$ 1,230.00 | 10% | <i>\$1,115.30</i> |
| EWP Premier NBD AHR XSW-DC-SR-L-A-D-5YR | 98004-XSW-DC-SR-L-A-D-5YR | \$ 2,050.00 | 10% | <i>\$1,858.84</i> |
| EWP Premier NBD AHR XSW-DCV2-LR-L-A-D | 98004-XSW-DCV2-LR-L-A-D | \$ 410.00 | 10% | <i>\$371.77</i> |
| EWP Premier NBD AHR XSW-DCV2-LR-L-A-D3YR | 98004-XSW-DCV2-LR-L-A-D-3YR | \$ 1,230.00 | 10% | <i>\$1,115.30</i> |
| EWP Premier NBD AHR XSW-DCV2-LR-L-A-D5YR | 98004-XSW-DCV2-LR-L-A-D-5YR | \$ 2,050.00 | 10% | <i>\$1,858.84</i> |
| EWP Premier NBD AHR XSW-DCV2-M-A-D | 98004-XSW-DCV2-M-A-D | \$ 355.00 | 10% | <i>\$321.90</i> |

| | | | | |
|--|-----------------------------|-------------|-----|------------|
| EWP Premier NBD AHR XSW-DCV2-M-A-D-3YR | 98004-XSW-DCV2-M-A-D-3YR | \$ 1,066.00 | 10% | \$966.60 |
| EWP Premier NBD AHR XSW-DCV2-M-A-D-5YR | 98004-XSW-DCV2-M-A-D-5YR | \$ 1,777.00 | 10% | \$1,611.29 |
| EWP Premier NBD AHR XSW-DCV2-SR-L-A-D | 98004-XSW-DCV2-SR-L-A-D | \$ 410.00 | 10% | \$371.77 |
| EWP Prem NBD AHR XSW-DCV2-SR-L-A-D-3YR | 98004-XSW-DCV2-SR-L-A-D-3YR | \$ 1,230.00 | 10% | \$1,115.30 |
| EWP Prem NBD AHR XSW-DCV2-SR-L-A-D-5YR | 98004-XSW-DCV2-SR-L-A-D-5YR | \$ 2,050.00 | 10% | \$1,858.84 |
| EWP Premier NBD AHR ZR-XFP | 98004-ZR-XFP | \$ 1,766.00 | 6% | \$1,672.49 |
| EWP Premier 4HR AHR 10200 | 98007-10200 | \$ 3,030.00 | 6% | \$2,869.56 |
| EWP Premier 4HR AHR 10320 | 98007-10320 | \$ 3,338.00 | 6% | \$3,161.25 |
| EWP Premier 4HR AHR 10330 | 98007-10330 | \$ 8,009.00 | 6% | \$7,584.92 |
| EWP Premier 4HR AHR 10331 | 98007-10331 | \$ 3,699.00 | 6% | \$3,503.14 |
| EWP Premier 4HR AHR 10335 | 98007-10335 | \$ 5,754.00 | 6% | \$5,449.33 |
| EWP Premier 4HR AHR 10403 | 98007-10403 | \$ 7,349.00 | 6% | \$6,959.87 |
| EWP Premier 4HR AHR 10404 | 98007-10404 | \$ 3,610.00 | 6% | \$3,418.85 |
| EWP Premier 4HR AHR 10441 | 98007-10441 | \$ 2,427.00 | 6% | \$2,298.49 |
| EWP Premier 4HR AHR 10442 | 98007-10442 | \$ 2,580.00 | 6% | \$2,443.39 |
| EWP Premier 4HR AHR 1130C | 98007-1130C | \$ 1,487.00 | 6% | \$1,408.26 |
| EWP Premier 4HR AHR 16119 | 98007-16119 | \$ 436.00 | 6% | \$412.91 |
| EWP Premier 4HR AHR 16120 | 98007-16120 | \$ 543.00 | 6% | \$514.25 |
| EWP Premier 4HR AHR 16126 | 98007-16126 | \$ 436.00 | 6% | \$412.91 |
| EWP Premier 4HR AHR 16127 | 98007-16127 | \$ 457.00 | 6% | \$432.80 |
| EWP Premier 4HR AHR 16172 | 98007-16172 | \$ 438.00 | 6% | \$414.81 |
| EWP Premier 4HR AHR 16172T | 98007-16172T | \$ 525.00 | 6% | \$497.20 |
| EWP Premier 4HR AHR 16173 | 98007-16173 | \$ 450.00 | 6% | \$426.17 |
| EWP Premier 4HR AHR 16173T | 98007-16173T | \$ 547.00 | 6% | \$518.04 |
| EWP Premier 4HR AHR 16174 | 98007-16174 | \$ 718.00 | 6% | \$679.98 |
| EWP Premier 4HR AHR 16175 | 98007-16175 | \$ 746.00 | 6% | \$706.50 |
| EWP Premier 4HR AHR 16176 | 98007-16176 | \$ 650.00 | 6% | \$615.58 |
| EWP Premier 4HR AHR 16177 | 98007-16177 | \$ 641.00 | 6% | \$607.06 |
| EWP Premier 4HR AHR 16177T | 98007-16177T | \$ 814.00 | 6% | \$770.90 |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR AHR 16178 | 98007-16178 | \$ 938.00 | 6% | \$888.33 |
| EWP Premier 4HR AHR 16179 | 98007-16179 | \$ 969.00 | 6% | \$917.69 |
| EWP Premier 4HR AHR 16179T | 98007-16179T | \$ 1,152.00 | 6% | \$1,091.00 |
| EWP Premier 4HR AHR 16301T | 98007-16301T | \$ 2,561.00 | 6% | \$2,425.40 |
| EWP Premier 4HR AHR 16303T | 98007-16303T | \$ 2,561.00 | 6% | \$2,425.40 |
| EWP Premier 4HR AHR 16304T | 98007-16304T | \$ 3,410.00 | 6% | \$3,229.44 |
| EWP Premier 4HR AHR 16401T | 98007-16401T | \$ 1,183.00 | 6% | \$1,120.36 |
| EWP Premier 4HR AHR 16402T | 98007-16402T | \$ 1,806.00 | 6% | \$1,710.37 |
| EWP Premier 4HR AHR 16403T | 98007-16403T | \$ 1,585.00 | 6% | \$1,501.07 |
| EWP Premier 4HR AHR 16404T | 98007-16404T | \$ 1,585.00 | 6% | \$1,501.07 |
| EWP Premier 4HR AHR 16405T | 98007-16405T | \$ 2,101.00 | 6% | \$1,989.75 |
| EWP Premier 4HR AHR 16406T | 98007-16406T | \$ 2,795.00 | 6% | \$2,647.00 |
| EWP Premier 4HR AHR 16431 | 98007-16431 | \$ 1,801.00 | 6% | \$1,705.64 |
| EWP Premier 4HR AHR 16432 | 98007-16432 | \$ 1,920.00 | 6% | \$1,818.34 |
| EWP Premier 4HR AHR 16440 | 98007-16440 | \$ 1,129.00 | 6% | \$1,069.22 |
| EWP Premier 4HR AHR 16441 | 98007-16441 | \$ 1,016.00 | 6% | \$962.20 |
| EWP Premier 4HR AHR 16442 | 98007-16442 | \$ 457.00 | 6% | \$432.80 |
| EWP Premier 4HR AHR 16444 | 98007-16444 | \$ 226.00 | 6% | \$214.03 |
| EWP Premier 4HR AHR 16501 | 98007-16501 | \$ 237.00 | 6% | \$224.45 |
| EWP Premier 4HR AHR 16501T | 98007-16501T | \$ 317.00 | 6% | \$300.21 |
| EWP Premier 4HR AHR 16502 | 98007-16502 | \$ 360.00 | 6% | \$340.94 |
| EWP Premier 4HR AHR 16502T | 98007-16502T | \$ 435.00 | 6% | \$411.97 |
| EWP Premier 4HR AHR 16503 | 98007-16503 | \$ 294.00 | 6% | \$278.43 |
| EWP Premier 4HR AHR 16503T | 98007-16503T | \$ 375.00 | 6% | \$355.14 |
| EWP Premier 4HR AHR 16504 | 98007-16504 | \$ 479.00 | 6% | \$453.64 |
| EWP Premier 4HR AHR 16504T | 98007-16504T | \$ 567.00 | 6% | \$536.98 |
| EWP Premier 4HR AHR 16505 | 98007-16505 | \$ 527.00 | 6% | \$499.10 |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR 16505T | 98007-16505T | \$ 639.00 | 6% | <i>\$605.16</i> |
| EWP Premier 4HR AHR 16506 | 98007-16506 | \$ 807.00 | 6% | <i>\$764.27</i> |
| EWP Premier 4HR AHR 16506T | 98007-16506T | \$ 992.00 | 6% | <i>\$939.47</i> |
| EWP Premier 4HR AHR 16507 | 98007-16507 | \$ 735.00 | 6% | <i>\$696.08</i> |
| EWP Premier 4HR AHR 16507T | 98007-16507T | \$ 881.00 | 6% | <i>\$834.35</i> |
| EWP Premier 4HR AHR 16508 | 98007-16508 | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP Premier 4HR AHR 16508T | 98007-16508T | \$ 1,109.00 | 6% | <i>\$1,050.28</i> |
| EWP Premier 4HR AHR 16509 | 98007-16509 | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP Premier 4HR AHR 16509T | 98007-16509T | \$ 1,109.00 | 6% | <i>\$1,050.28</i> |
| EWP Premier 4HR AHR 16510 | 98007-16510 | \$ 1,109.00 | 6% | <i>\$1,050.28</i> |
| EWP Premier 4HR AHR 16510T | 98007-16510T | \$ 1,329.00 | 6% | <i>\$1,258.63</i> |
| EWP Premier 4HR AHR 16513 | 98007-16513 | \$ 662.00 | 6% | <i>\$626.95</i> |
| EWP Premier 4HR AHR 16514 | 98007-16514 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR AHR 16515 | 98007-16515 | \$ 190.00 | 6% | <i>\$179.94</i> |
| EWP Premier 4HR AHR 16516 | 98007-16516 | \$ 211.00 | 6% | <i>\$199.83</i> |
| EWP Premier 4HR AHR 16517 | 98007-16517 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWP Premier 4HR AHR 16518 | 98007-16518 | \$ 359.00 | 6% | <i>\$339.99</i> |
| EWP Premier 4HR AHR 16519 | 98007-16519 | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier 4HR AHR 16520 | 98007-16520 | \$ 595.00 | 6% | <i>\$563.49</i> |
| EWP Premier 4HR AHR 16530 | 98007-16530 | \$ 222.00 | 6% | <i>\$210.25</i> |
| EWP Premier 4HR AHR 16531 | 98007-16531 | \$ 309.00 | 6% | <i>\$292.64</i> |
| EWP Premier 4HR AHR 16531T | 98007-16531T | \$ 347.00 | 6% | <i>\$328.63</i> |
| EWP Premier 4HR AHR 16532 | 98007-16532 | \$ 309.00 | 6% | <i>\$292.64</i> |
| EWP Premier 4HR AHR 16532T | 98007-16532T | \$ 347.00 | 6% | <i>\$328.63</i> |
| EWP Premier 4HR AHR 16533 | 98007-16533 | \$ 422.00 | 6% | <i>\$399.66</i> |
| EWP Premier 4HR AHR 16533T | 98007-16533T | \$ 492.00 | 6% | <i>\$465.95</i> |
| EWP Premier 4HR AHR 16534 | 98007-16534 | \$ 454.00 | 6% | <i>\$429.96</i> |
| EWP Premier 4HR AHR 16535 | 98007-16535 | \$ 675.00 | 6% | <i>\$639.26</i> |
| EWP Premier 4HR AHR 16535A | 98007-16535A | \$ 675.00 | 6% | <i>\$639.26</i> |
| EWP Premier 4HR AHR 16535T | 98007-16535T | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWP Premier 4HR AHR 16536 | 98007-16536 | \$ 315.00 | 6% | <i>\$298.32</i> |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR AHR 16537 | 98007-16537 | \$ 425.00 | 6% | \$402.50 |
| EWP Premier 4HR AHR 16538 | 98007-16538 | \$ 510.00 | 6% | \$483.00 |
| EWP Premier 4HR AHR 16538T | 98007-16538T | \$ 637.00 | 6% | \$603.27 |
| EWP Premier 4HR AHR 16539 | 98007-16539 | \$ 663.00 | 6% | \$627.89 |
| EWP Premier 4HR AHR 16540 | 98007-16540 | \$ 475.00 | 6% | \$449.85 |
| EWP Premier 4HR AHR 16541 | 98007-16541 | \$ 183.00 | 6% | \$173.31 |
| EWP Premier 4HR AHR 16560 | 98007-16560 | \$ 111.00 | 6% | \$105.12 |
| EWP Premier 4HR AHR 16561 | 98007-16561 | \$ 154.00 | 6% | \$145.85 |
| EWP Premier 4HR AHR 16562 | 98007-16562 | \$ 190.00 | 6% | \$179.94 |
| EWP Premier 4HR AHR 16563 | 98007-16563 | \$ 252.00 | 6% | \$238.66 |
| EWP Premier 4HR AHR 16564 | 98007-16564 | \$ 307.00 | 6% | \$290.74 |
| EWP Premier 4HR AHR 16565 | 98007-16565 | \$ 467.00 | 6% | \$442.27 |
| EWP Premier 4HR AHR 16566 | 98007-16566 | \$ 71.00 | 6% | \$67.24 |
| EWP Premier 4HR AHR 16567 | 98007-16567 | \$ 133.00 | 6% | \$125.96 |
| EWP Premier 4HR AHR 16568 | 98007-16568 | \$ 111.00 | 6% | \$105.12 |
| EWP Premier 4HR AHR 16569 | 98007-16569 | \$ 175.00 | 6% | \$165.73 |
| EWP Premier 4HR AHR 16570 | 98007-16570 | \$ 190.00 | 6% | \$179.94 |
| EWP Premier 4HR AHR 16571 | 98007-16571 | \$ 307.00 | 6% | \$290.74 |
| EWP Premier 4HR AHR 16701 | 98007-16701 | \$ 665.00 | 6% | \$629.79 |
| EWP Premier 4HR AHR 16702 | 98007-16702 | \$ 978.00 | 6% | \$926.21 |
| EWP Premier 4HR AHR 16703 | 98007-16703 | \$ 770.00 | 6% | \$729.23 |
| EWP Premier 4HR AHR 16703T | 98007-16703T | \$ 923.00 | 6% | \$874.13 |
| EWP Premier 4HR AHR 16704 | 98007-16704 | \$ 1,130.00 | 6% | \$1,070.17 |
| EWP Premier 4HR AHR 16704T | 98007-16704T | \$ 1,360.00 | 6% | \$1,287.99 |
| EWP Premier 4HR AHR 16705 | 98007-16705 | \$ 978.00 | 6% | \$926.21 |
| EWP Premier 4HR AHR 16705T | 98007-16705T | \$ 1,187.00 | 6% | \$1,124.15 |
| EWP Premier 4HR AHR 16706 | 98007-16706 | \$ 1,495.00 | 6% | \$1,415.84 |
| EWP Premier 4HR AHR 16706T | 98007-16706T | \$ 1,799.00 | 6% | \$1,703.74 |
| EWP Premier 4HR AHR 16710 | 98007-16710 | \$ 298.00 | 6% | \$282.22 |
| EWP Premier 4HR AHR 16710T | 98007-16710T | \$ 359.00 | 6% | \$339.99 |
| EWP Premier 4HR AHR 16711 | 98007-16711 | \$ 126.00 | 6% | \$119.33 |
| EWP Premier 4HR AHR 16711T | 98007-16711T | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR 16712 | 98007-16712 | \$ 173.00 | 6% | \$163.84 |
| EWP Premier 4HR AHR 16712T | 98007-16712T | \$ 203.00 | 6% | \$192.25 |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR AHR 16713 | 98007-16713 | \$ 80.00 | 6% | \$75.76 |
| EWP Premier 4HR AHR 16713T | 98007-16713T | \$ 93.00 | 6% | \$88.08 |
| EWP Premier 4HR AHR 16715 | 98007-16715 | \$ 120.00 | 6% | \$113.65 |
| EWP Premier 4HR AHR 16715T | 98007-16715T | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR 16716 | 98007-16716 | \$ 523.00 | 6% | \$495.31 |
| EWP Premier 4HR AHR 16716T | 98007-16716T | \$ 618.00 | 6% | \$585.28 |
| EWP Premier 4HR AHR 16717 | 98007-16717 | \$ 786.00 | 6% | \$744.38 |
| EWP Premier 4HR AHR 16718 | 98007-16718 | \$ 561.00 | 6% | \$531.30 |
| EWP Premier 4HR AHR 16718T | 98007-16718T | \$ 664.00 | 6% | \$628.84 |
| EWP Premier 4HR AHR 16719 | 98007-16719 | \$ 835.00 | 6% | \$790.79 |
| EWP Premier 4HR AHR 16719T | 98007-16719T | \$ 1,002.00 | 6% | \$948.94 |
| EWP Premier 4HR AHR 16720 | 98007-16720 | \$ 1,295.00 | 6% | \$1,226.43 |
| EWP Premier 4HR AHR 16720T | 98007-16720T | \$ 1,507.00 | 6% | \$1,427.20 |
| EWP Premier 4HR AHR 16756 | 98007-16756 | \$ 943.00 | 6% | \$893.07 |
| EWP Premier 4HR AHR 16756T | 98007-16756T | \$ 1,109.00 | 6% | \$1,050.28 |
| EWP Premier 4HR AHR 16757 | 98007-16757 | \$ 895.00 | 6% | \$847.61 |
| EWP Premier 4HR AHR 16757T | 98007-16757T | \$ 1,056.00 | 6% | \$1,000.08 |
| EWP Premier 4HR AHR 16790 | 98007-16790 | \$ 2,008.00 | 6% | \$1,901.68 |
| EWP Premier 4HR AHR 16791 | 98007-16791 | \$ 2,591.00 | 6% | \$2,453.81 |
| EWP Premier 4HR AHR 16801 | 98007-16801 | \$ 258.00 | 6% | \$244.34 |
| EWP Premier 4HR AHR 16802 | 98007-16802 | \$ 298.00 | 6% | \$282.22 |
| EWP Premier 4HR AHR 16803 | 98007-16803 | \$ 320.00 | 6% | \$303.06 |
| EWP Premier 4HR AHR 16804 | 98007-16804 | \$ 390.00 | 6% | \$369.35 |
| EWP Premier 4HR AHR 16805 | 98007-16805 | \$ 87.00 | 6% | \$82.39 |
| EWP Premier 4HR AHR 16806 | 98007-16806 | \$ 73.00 | 6% | \$69.13 |
| EWP Premier 4HR AHR 17101 | 98007-17101 | \$ 3,797.00 | 6% | \$3,595.95 |
| EWP Premier 4HR AHR 17101T | 98007-17101T | \$ 4,755.00 | 6% | \$4,503.22 |
| EWP Premier 4HR AHR 17102 | 98007-17102 | \$ 3,797.00 | 6% | \$3,595.95 |
| EWP Premier 4HR AHR 17102T | 98007-17102T | \$ 4,755.00 | 6% | \$4,503.22 |
| EWP Premier 4HR AHR 17103 | 98007-17103 | \$ 2,645.00 | 6% | \$2,504.95 |
| EWP Premier 4HR AHR 17103C | 98007-17103C | \$ 2,567.00 | 6% | \$2,431.08 |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR 17103T | 98007-17103T | \$ 3,317.00 | 6% | <i>\$3,141.36</i> |
| EWP Premier 4HR AHR 17104 | 98007-17104 | \$ 2,645.00 | 6% | <i>\$2,504.95</i> |
| EWP Premier 4HR AHR 17104T | 98007-17104T | \$ 3,317.00 | 6% | <i>\$3,141.36</i> |
| EWP Premier 4HR AHR 17121 | 98007-17121 | \$ 756.00 | 6% | <i>\$715.97</i> |
| EWP Premier 4HR AHR 17122 | 98007-17122 | \$ 470.00 | 6% | <i>\$445.11</i> |
| EWP Premier 4HR AHR 17200 | 98007-17200 | \$ 5,970.00 | 6% | <i>\$5,653.89</i> |
| EWP Premier 4HR AHR 17200T | 98007-17200T | \$ 6,834.00 | 6% | <i>\$6,472.14</i> |
| EWP Premier 4HR AHR 17201 | 98007-17201 | \$ 5,970.00 | 6% | <i>\$5,653.89</i> |
| EWP Premier 4HR AHR 17201T | 98007-17201T | \$ 6,834.00 | 6% | <i>\$6,472.14</i> |
| EWP Premier 4HR AHR 17202 | 98007-17202 | \$ 5,970.00 | 6% | <i>\$5,653.89</i> |
| EWP Premier 4HR AHR 17202T | 98007-17202T | \$ 6,834.00 | 6% | <i>\$6,472.14</i> |
| EWP Premier 4HR AHR 17203 | 98007-17203 | \$ 6,066.00 | 6% | <i>\$5,744.81</i> |
| EWP Premier 4HR AHR 17203T | 98007-17203T | \$ 6,933.00 | 6% | <i>\$6,565.90</i> |
| EWP Premier 4HR AHR 17204 | 98007-17204 | \$ 6,066.00 | 6% | <i>\$5,744.81</i> |
| EWP Premier 4HR AHR 17204T | 98007-17204T | \$ 6,933.00 | 6% | <i>\$6,565.90</i> |
| EWP Premier 4HR AHR 17205 | 98007-17205 | \$ 6,022.00 | 6% | <i>\$5,703.14</i> |
| EWP Premier 4HR AHR 17205T | 98007-17205T | \$ 6,880.00 | 6% | <i>\$6,515.70</i> |
| EWP Premier 4HR AHR 17206 | 98007-17206 | \$ 6,022.00 | 6% | <i>\$5,703.14</i> |
| EWP Premier 4HR AHR 17206T | 98007-17206T | \$ 6,880.00 | 6% | <i>\$6,515.70</i> |
| EWP Premier 4HR AHR 17300 | 98007-17300 | \$ 3,968.00 | 6% | <i>\$3,757.89</i> |
| EWP Premier 4HR AHR 17310 | 98007-17310 | \$ 3,599.00 | 6% | <i>\$3,408.43</i> |
| EWP Premier 4HR AHR 17310T | 98007-17310T | \$ 4,331.00 | 6% | <i>\$4,101.67</i> |
| EWP Premier 4HR AHR 17350 | 98007-17350 | \$ 3,690.00 | 6% | <i>\$3,494.61</i> |
| EWP Premier 4HR AHR 17360 | 98007-17360 | \$ 4,543.00 | 6% | <i>\$4,302.45</i> |
| EWP Premier 4HR AHR 17401 | 98007-17401 | \$ 563.00 | 6% | <i>\$533.19</i> |
| EWP Premier 4HR AHR 17401G | 98007-17401G | \$ 686.00 | 6% | <i>\$649.68</i> |
| EWP Premier 4HR AHR 17401T | 98007-17401T | \$ 650.00 | 6% | <i>\$615.58</i> |
| EWP Premier 4HR AHR 17402 | 98007-17402 | \$ 799.00 | 6% | <i>\$756.69</i> |
| EWP Premier 4HR AHR 17402G | 98007-17402G | \$ 907.00 | 6% | <i>\$858.97</i> |

| | | | | |
|-------------------------------|-----------------|--------------|----|--------------------|
| EWP Premier 4HR AHR 17402T | 98007-17402T | \$ 858.00 | 6% | <i>\$812.57</i> |
| EWP Premier 4HR AHR 17403 | 98007-17403 | \$ 875.00 | 6% | <i>\$828.67</i> |
| EWP Premier 4HR AHR 17404 | 98007-17404 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWP Premier 4HR AHR 17405 | 98007-17405 | \$ 522.00 | 6% | <i>\$494.36</i> |
| EWP Premier 4HR AHR 17700 | 98007-17700 | \$ 6,999.00 | 6% | <i>\$6,628.40</i> |
| EWP Premier 4HR AHR 17701 | 98007-17701 | \$ 6,188.00 | 6% | <i>\$5,860.35</i> |
| EWP Premier 4HR AHR 17702 | 98007-17702 | \$ 6,188.00 | 6% | <i>\$5,860.35</i> |
| EWP Premier 4HR AHR 17703 | 98007-17703 | \$ 6,775.00 | 6% | <i>\$6,416.26</i> |
| EWP Premier 4HR AHR 17704 | 98007-17704 | \$ 6,775.00 | 6% | <i>\$6,416.26</i> |
| EWP Premier 4HR AHR 17705 | 98007-17705 | \$ 6,230.00 | 6% | <i>\$5,900.12</i> |
| EWP Premier 4HR AHR 17706 | 98007-17706 | \$ 6,230.00 | 6% | <i>\$5,900.12</i> |
| EWP Premier 4HR AHR 17800 | 98007-17800 | \$ 7,148.00 | 6% | <i>\$6,769.51</i> |
| EWP Premier 4HR AHR 17810 | 98007-17810 | \$ 5,712.00 | 6% | <i>\$5,409.55</i> |
| EWP Premier 4HR AHR 18101 | 98007-18101 | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWP Premier 4HR AHR 18102 | 98007-18102 | \$ 474.00 | 6% | <i>\$448.90</i> |
| EWP Premier 4HR AHR 18103 | 98007-18103 | \$ 523.00 | 6% | <i>\$495.31</i> |
| EWP Premier 4HR AHR 18104 | 98007-18104 | \$ 747.00 | 6% | <i>\$707.45</i> |
| EWP Premier 4HR AHR 18104-6PK | 98007-18104-6PK | \$ 4,339.00 | 6% | <i>\$4,109.25</i> |
| EWP Premier 4HR AHR 18202 | 98007-18202 | \$ 282.00 | 6% | <i>\$267.07</i> |
| EWP Premier 4HR AHR 30135 | 98007-30135 | \$ 1,043.00 | 6% | <i>\$987.77</i> |
| EWP Premier 4HR AHR 30136 | 98007-30136 | \$ 8,132.00 | 6% | <i>\$7,701.41</i> |
| EWP Premier 4HR AHR 30137 | 98007-30137 | \$ 1,528.00 | 6% | <i>\$1,447.09</i> |
| EWP Premier 4HR AHR 30138 | 98007-30138 | \$ 6,999.00 | 6% | <i>\$6,628.40</i> |
| EWP Premier 4HR AHR 30139 | 98007-30139 | \$ 11,960.00 | 6% | <i>\$11,326.72</i> |
| EWP Premier 4HR AHR 30912 | 98007-30912 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier 4HR AHR 30913 | 98007-30913 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier 4HR AHR 31012 | 98007-31012 | \$ 171.00 | 6% | <i>\$161.95</i> |
| EWP Premier 4HR AHR 31013 | 98007-31013 | \$ 171.00 | 6% | <i>\$161.95</i> |
| EWP Premier 4HR AHR 31014 | 98007-31014 | \$ 171.00 | 6% | <i>\$161.95</i> |
| EWP Premier 4HR AHR 31015 | 98007-31015 | \$ 171.00 | 6% | <i>\$161.95</i> |
| EWP Premier 4HR AHR 31016 | 98007-31016 | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWP Premier 4HR AHR 31017 | 98007-31017 | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWP Premier 4HR AHR 31018 | 98007-31018 | \$ 467.00 | 6% | <i>\$442.27</i> |
| EWP Premier 4HR AHR 31019 | 98007-31019 | \$ 467.00 | 6% | <i>\$442.27</i> |
| EWP Premier 4HR AHR 31025 | 98007-31025 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier 4HR AHR 31026 | 98007-31026 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier 4HR AHR 31028 | 98007-31028 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR AHR 31029 | 98007-31029 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR 31031 | 98007-31031 | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR 31032 | 98007-31032 | \$ 107.00 | 6% | <i>\$101.33</i> |

| | | | | |
|----------------------------------|--------------------|-------------|-----|-------------------|
| EWP Premier 4HR AHR 31034 | 98007-31034 | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier 4HR AHR 31035 | 98007-31035 | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier 4HR AHR 31050 | 98007-31050 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 31051 | 98007-31051 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 31055 | 98007-31055 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 31056 | 98007-31056 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37101 | 98007-37101 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier 4HR AHR 37102 | 98007-37102 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier 4HR AHR 37103 | 98007-37103 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier 4HR AHR 37111 | 98007-37111 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR AHR 37112 | 98007-37112 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR AHR 37113 | 98007-37113 | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR 37114 | 98007-37114 | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR 37115 | 98007-37115 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR AHR 37116 | 98007-37116 | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR 37117 | 98007-37117 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR AHR 37121 | 98007-37121 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37122 | 98007-37122 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37123 | 98007-37123 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37124 | 98007-37124 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37125 | 98007-37125 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37126 | 98007-37126 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37129 | 98007-37129 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 37130 | 98007-37130 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier 4HR AHR 39031 | 98007-39031 | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR 39032 | 98007-39032 | \$ 277.00 | 6% | <i>\$262.33</i> |
| EWP Premier 4HR AHR 39033 | 98007-39033 | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR 39034 | 98007-39034 | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR 39035 | 98007-39035 | \$ 1,224.00 | 6% | <i>\$1,159.19</i> |
| EWP Premier 4HR AHR 39036 | 98007-39036 | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier 4HR AHR 39037 | 98007-39037 | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier 4HR AHR 39038 | 98007-39038 | \$ 322.00 | 6% | <i>\$304.95</i> |
| EWP Premier 4HR AHR 39039 | 98007-39039 | \$ 322.00 | 6% | <i>\$304.95</i> |
| EWP Premier 4HR AHR 39505 | 98007-39505 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier 4HR AHR 4120-24MW-4Y | 98007-4120-24MW-4Y | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| EWP Premier 4HR AHR 4120-48MW-4Y | 98007-4120-48MW-4Y | \$ 1,382.00 | 6% | <i>\$1,308.82</i> |
| EWP Premier 4HR AHR 4120C | 98007-4120C | \$ 8,082.00 | 10% | <i>\$7,328.35</i> |
| EWP Premier 4HR AHR 4120C-1 | 98007-4120C-1 | \$ 8,907.00 | 6% | <i>\$8,435.37</i> |
| EWP Premier 4HR AHR 41216 | 98007-41216 | \$ 2,404.00 | 6% | <i>\$2,276.71</i> |

| | | | | |
|---|---------------------------|--------------|----|-------------|
| EWP Premier 4HR AHR 4220-12P-4X | 98007-4220-12P-4X | \$ 303.00 | 6% | \$286.96 |
| EWP Premier 4HR AHR 4220-12T-4X | 98007-4220-12T-4X | \$ 222.00 | 6% | \$210.25 |
| EWP Premier 4HR AHR 4220-24P-4X | 98007-4220-24P-4X | \$ 404.00 | 6% | \$382.61 |
| EWP Premier 4HR AHR 4220-24T-4X | 98007-4220-24T-4X | \$ 313.00 | 6% | \$296.43 |
| EWP Premier 4HR AHR 4220-48P-4X | 98007-4220-48P-4X | \$ 607.00 | 6% | \$574.86 |
| EWP Premier 4HR AHR 4220-48T-4X | 98007-4220-48T-4X | \$ 455.00 | 6% | \$430.91 |
| EWP Premier 4HR AHR 4220-4MW-20P-4X | 98007-4220-4MW-20P-4X | \$ 556.00 | 6% | \$526.56 |
| EWP Premier 4HR AHR 4220-4MW-8P-4X | 98007-4220-4MW-8P-4X | \$ 394.00 | 6% | \$373.14 |
| EWP Premier 4HR AHR 4220-8MW-40P-4X | 98007-4220-8MW-40P-4X | \$ 809.00 | 6% | \$766.16 |
| EWP Premier 4HR AHR 4220-8X | 98007-4220-8X | \$ 425.00 | 6% | \$402.50 |
| EWP Premier 4HR AHR 48001 | 98007-48001 | \$ 9,996.00 | 6% | \$9,466.71 |
| EWP Premier 4HR AHR 48038 | 98007-48038 | \$ 4,000.00 | 6% | \$3,788.20 |
| EWP Premier 4HR AHR 48039 | 98007-48039 | \$ 4,000.00 | 6% | \$3,788.20 |
| EWP Premier 4HR AHR 48040 | 98007-48040 | \$ 3,810.00 | 6% | \$3,608.26 |
| EWP Premier 4HR AHR 48041 | 98007-48041 | \$ 4,000.00 | 6% | \$3,788.20 |
| EWP Premier 4HR AHR 48046 | 98007-48046 | \$ 5,254.00 | 6% | \$4,975.80 |
| EWP Premier 4HR AHR 48047 | 98007-48047 | \$ 14,001.00 | 6% | \$13,259.65 |
| EWP Premier 4HR AHR 48051 | 98007-48051 | \$ 9,631.00 | 6% | \$9,121.04 |
| EWP Premier 4HR AHR 48061 | 98007-48061 | \$ 11,255.00 | 6% | \$10,659.05 |
| EWP Premier 4HR AHR 48062 | 98007-48062 | \$ 18,007.00 | 6% | \$17,053.53 |
| EWP Premier 4HR AHR 5320-16P-4XE | 98007-5320-16P-4XE | \$ 397.00 | 6% | \$375.98 |
| EWP Premier 4HR AHR 5320-16P-4XE-DC | 98007-5320-16P-4XE-DC | \$ 481.00 | 6% | \$455.53 |
| EWP Premier 4HR AHR 5320-24P-8XE | 98007-5320-24P-8XE | \$ 429.00 | 6% | \$406.28 |
| EWP Premier 4HR AHR 5320-24T-24S-4XE-XT | 98007-5320-24T-24S-4XE-XT | \$ 552.00 | 6% | \$522.77 |
| EWP Premier 4HR AHR 5320-24T-4X-XT | 98007-5320-24T-4X-XT | \$ 297.00 | 6% | \$281.27 |

| | | | | |
|--|--------------------------|-------------|----|------------|
| EWP Premier 4HR AHR 5320-24T-8XE | 98007-5320-24T-8XE | \$ 309.00 | 6% | \$292.64 |
| EWP Premier 4HR AHR 5320-48P-8XE | 98007-5320-48P-8XE | \$ 720.00 | 6% | \$681.88 |
| EWP Premier 4HR AHR 5320-48T-8XE | 98007-5320-48T-8XE | \$ 503.00 | 6% | \$476.37 |
| EWP Premier 4HR AHR 5420F-16MW-32P-4XE | 98007-5420F-16MW-32P-4XE | \$ 1,323.00 | 6% | \$1,252.95 |
| EWP Premier 4HR AHR 5420F-16W-32P-4XE | 98007-5420F-16W-32P-4XE | \$ 1,292.00 | 6% | \$1,223.59 |
| EWP Premier 4HR AHR 5420F-24P-4XE | 98007-5420F-24P-4XE | \$ 557.00 | 6% | \$527.51 |
| EWP Premier 4HR AHR 5420F-24S-4XE | 98007-5420F-24S-4XE | \$ 629.00 | 6% | \$595.69 |
| EWP Premier 4HR AHR 5420F-24T-4XE | 98007-5420F-24T-4XE | \$ 501.00 | 6% | \$474.47 |
| EWP Premier 4HR AHR 5420F-48P-4XE | 98007-5420F-48P-4XE | \$ 841.00 | 6% | \$796.47 |
| EWP Premier 4HR AHR 5420F-48P-4XL | 98007-5420F-48P-4XL | \$ 1,013.00 | 6% | \$959.36 |
| EWP Premier 4HR AHR 5420F-48T-4XE | 98007-5420F-48T-4XE | \$ 638.00 | 6% | \$604.22 |
| EWP Premier 4HR AHR 5420F-8W-16P-4XE | 98007-5420F-8W-16P-4XE | \$ 671.00 | 6% | \$635.47 |
| EWP Premier 4HR AHR 5420M-16MW-32P-4YE | 98007-5420M-16MW-32P-4YE | \$ 1,519.00 | 6% | \$1,438.57 |
| EWP Premier 4HR AHR 5420M-24T-4YE | 98007-5420M-24T-4YE | \$ 656.00 | 6% | \$621.26 |
| EWP Premier 4HR AHR 5420M-24W-4YE | 98007-5420M-24W-4YE | \$ 598.00 | 6% | \$566.34 |
| EWP Premier 4HR AHR 5420M-48T-4YE | 98007-5420M-48T-4YE | \$ 897.00 | 6% | \$849.50 |
| EWP Premier 4HR AHR 5420M-48W-4YE | 98007-5420M-48W-4YE | \$ 1,002.00 | 6% | \$948.94 |
| EWP PREMIER 4HR AHR 5520-12MW-36W | 98007-5520-12MW-36W | \$ 1,603.00 | 6% | \$1,518.12 |
| EWP PREMIER 4HR AHR 5520-24T | 98007-5520-24T | \$ 565.00 | 6% | \$535.08 |

| | | | | |
|---|---------------------------|-------------|-----|------------|
| EWP PREMIER 4HR AHR 5520-24T-ACDC-BASE | 98007-5520-24T-ACDC-BASE | \$ 565.00 | 6% | \$535.08 |
| EWP PREMIER 4HR AHR 5520-24T-BASE | 98007-5520-24T-BASE | \$ 565.00 | 10% | \$512.31 |
| EWP PREMIER 4HR AHR 5520-24W | 98007-5520-24W | \$ 860.00 | 6% | \$814.46 |
| EWP PREMIER 4HR AHR 5520-24X | 98007-5520-24X | \$ 1,622.00 | 6% | \$1,536.12 |
| EWP PREMIER 4HR AHR 5520-24X-ACDC-BASE | 98007-5520-24X-ACDC-BASE | \$ 1,622.00 | 6% | \$1,536.12 |
| EWP PREMIER 4HR AHR 5520-24X-BASE | 98007-5520-24X-BASE | \$ 1,622.00 | 10% | \$1,470.75 |
| EWP PREMIER 4HR AHR 5520-48SE | 98007-5520-48SE | \$ 1,671.00 | 6% | \$1,582.52 |
| EWP PREMIER 4HR AHR 5520-48SE-ACDC-BASE | 98007-5520-48SE-ACDC-BASE | \$ 1,671.00 | 6% | \$1,582.52 |
| EWP PREMIER 4HR AHR 5520-48SE-BASE | 98007-5520-48SE-BASE | \$ 1,671.00 | 10% | \$1,515.18 |
| EWP PREMIER 4HR AHR 5520-48T | 98007-5520-48T | \$ 992.00 | 6% | \$939.47 |
| EWP PREMIER 4HR AHR 5520-48T-ACDC-BASE | 98007-5520-48T-ACDC-BASE | \$ 992.00 | 6% | \$939.47 |
| EWP PREMIER 4HR AHR 5520-48T-BASE | 98007-5520-48T-BASE | \$ 992.00 | 10% | \$899.50 |
| EWP PREMIER 4HR AHR 5520-48W | 98007-5520-48W | \$ 1,258.00 | 6% | \$1,191.39 |
| EWP Premier 4HR AHR 5720-24MW | 98007-5720-24MW | \$ 1,920.00 | 6% | \$1,818.34 |
| EWP Premier 4HR AHR 5720-24MXW | 98007-5720-24MXW | \$ 2,594.00 | 6% | \$2,456.65 |
| EWP Premier 4HR AHR 5720-48MW | 98007-5720-48MW | \$ 2,256.00 | 6% | \$2,136.54 |
| EWP Premier 4HR AHR 5720-48MXW | 98007-5720-48MXW | \$ 3,272.00 | 6% | \$3,098.75 |
| EWP Premier 4HR AHR 7520-48XT-6C | 98007-7520-48XT-6C | \$ 3,697.00 | 6% | \$3,501.24 |
| EWP Premier 4HR AHR 7520-48XT-6C-AC-F | 98007-7520-48XT-6C-AC-F | \$ 3,697.00 | 6% | \$3,501.24 |

| | | | | |
|--|--------------------------|-------------|----|------------|
| EWP Premier 4HR AHR 7520-48XT-6C-AC-R | 98007-7520-48XT-6C-AC-R | \$ 3,697.00 | 6% | \$3,501.24 |
| EWP Premier 4HR AHR 7520-48Y-8C | 98007-7520-48Y-8C | \$ 3,447.00 | 6% | \$3,264.48 |
| EWP Premier 4HR AHR 7520-48Y-8C-AC-F | 98007-7520-48Y-8C-AC-F | \$ 3,447.00 | 6% | \$3,264.48 |
| EWP Premier 4HR AHR 7520-48Y-8C-AC-R | 98007-7520-48Y-8C-AC-R | \$ 3,447.00 | 6% | \$3,264.48 |
| EWP PREMIER 4HR AHR 7520-48YE-8CE | 98007-7520-48YE-8CE | \$ 4,002.00 | 6% | \$3,790.09 |
| EWP PREMIER 4HR AHR 7520-48YE-8CE-AC-F | 98007-7520-48YE-8CE-AC-F | \$ 4,002.00 | 6% | \$3,790.09 |
| EWP PREMIER 4HR AHR 7520-48YE-8CE-AC-R | 98007-7520-48YE-8CE-AC-R | \$ 4,002.00 | 6% | \$3,790.09 |
| EWP Premier 4HR AHR 7720-32C | 98007-7720-32C | \$ 4,283.00 | 6% | \$4,056.22 |
| EWP Premier 4HR AHR 7720-32C-AC-F | 98007-7720-32C-AC-F | \$ 4,283.00 | 6% | \$4,056.22 |
| EWP Premier 4HR AHR 7720-32C-AC-R | 98007-7720-32C-AC-R | \$ 4,283.00 | 6% | \$4,056.22 |
| EWP Premier 4HR AHR 8520-48XT-6C | 98007-8520-48XT-6C | \$ 3,826.00 | 6% | \$3,623.41 |
| EWP Premier 4HR AHR 8520-48XT-6C-AC-F | 98007-8520-48XT-6C-AC-F | \$ 3,826.00 | 6% | \$3,623.41 |
| EWP Premier 4HR AHR 8520-48XT-6C-AC-R | 98007-8520-48XT-6C-AC-R | \$ 3,826.00 | 6% | \$3,623.41 |
| EWP Premier 4HR AHR 8520-48XT-6C-DC-F | 98007-8520-48XT-6C-DC-F | \$ 3,826.00 | 6% | \$3,623.41 |
| EWP Premier 4HR AHR 8520-48XT-6C-DC-R | 98007-8520-48XT-6C-DC-R | \$ 3,826.00 | 6% | \$3,623.41 |
| EWP Premier 4HR AHR 8520-48Y-8C | 98007-8520-48Y-8C | \$ 3,669.00 | 6% | \$3,474.73 |
| EWP Premier 4HR AHR 8520-48Y-8C-AC-F | 98007-8520-48Y-8C-AC-F | \$ 3,670.00 | 6% | \$3,475.67 |
| EWP Premier 4HR AHR 8520-48Y-8C-AC-R | 98007-8520-48Y-8C-AC-R | \$ 3,670.00 | 6% | \$3,475.67 |

| | | | | |
|--------------------------------------|------------------------|--------------|-----|--------------------|
| EWP Premier 4HR AHR 8520-48Y-8C-DC-F | 98007-8520-48Y-8C-DC-F | \$ 3,669.00 | 6% | <i>\$3,474.73</i> |
| EWP Premier 4HR AHR 8520-48Y-8C-DC-R | 98007-8520-48Y-8C-DC-R | \$ 3,669.00 | 6% | <i>\$3,474.73</i> |
| EWP Premier 4HR AHR 86100 | 98007-86100 | \$ 7,193.00 | 6% | <i>\$6,812.13</i> |
| EWP Premier 4HR AHR 86101 | 98007-86101 | \$ 9,882.00 | 6% | <i>\$9,358.75</i> |
| EWP Premier 4HR AHR 87100 | 98007-87100 | \$ 4,466.00 | 6% | <i>\$4,229.53</i> |
| EWP Premier 4HR AHR 87101 | 98007-87101 | \$ 6,871.00 | 6% | <i>\$6,507.18</i> |
| EWP Premier 4HR AHR 8720-32C | 98007-8720-32C | \$ 4,224.00 | 6% | <i>\$4,000.34</i> |
| EWP Premier 4HR AHR 8720-32C-AC-F | 98007-8720-32C-AC-F | \$ 4,224.00 | 6% | <i>\$4,000.34</i> |
| EWP Premier 4HR AHR 8720-32C-AC-R | 98007-8720-32C-AC-R | \$ 4,224.00 | 6% | <i>\$4,000.34</i> |
| EWP Premier 4HR AHR 8720-32C-DC-F | 98007-8720-32C-DC-F | \$ 4,224.00 | 6% | <i>\$4,000.34</i> |
| EWP Premier 4HR AHR 8720-32C-DC-R | 98007-8720-32C-DC-R | \$ 4,224.00 | 6% | <i>\$4,000.34</i> |
| EWP Premier 4HR AHR 8806 | 98007-8806 | \$ 2,500.00 | 6% | <i>\$2,367.63</i> |
| EWP Premier 4HR AHR 8810 | 98007-8810 | \$ 6,500.00 | 6% | <i>\$6,155.83</i> |
| EWP Premier 4HR AHR 88100 | 98007-88100 | \$ 8,118.00 | 6% | <i>\$7,688.15</i> |
| EWP Premier 4HR AHR 8820-40C | 98007-8820-40C | \$ 18,476.00 | 10% | <i>\$16,753.11</i> |
| EWP Premier 4HR AHR 8820-40C-AC-F | 98007-8820-40C-AC-F | \$ 18,476.00 | 10% | <i>\$16,753.11</i> |
| EWP Premier 4HR AHR 8820-40C-AC-R | 98007-8820-40C-AC-R | \$ 18,476.00 | 10% | <i>\$16,753.11</i> |
| EWP Premier 4HR AHR 8820-40C-DC-F | 98007-8820-40C-DC-F | \$ 18,476.00 | 10% | <i>\$16,753.11</i> |
| EWP Premier 4HR AHR 8820-40C-DC-R | 98007-8820-40C-DC-R | \$ 18,476.00 | 10% | <i>\$16,753.11</i> |
| EWP Premier 4HR AHR 8820-80C | 98007-8820-80C | \$ 33,661.00 | 10% | <i>\$30,522.11</i> |
| EWP Premier 4HR AHR 8820-80C-AC-F | 98007-8820-80C-AC-F | \$ 33,661.00 | 10% | <i>\$30,522.11</i> |
| EWP Premier 4HR AHR 8820-80C-AC-R | 98007-8820-80C-AC-R | \$ 33,661.00 | 10% | <i>\$30,522.11</i> |
| EWP Premier 4HR AHR 8820-80C-DC-F | 98007-8820-80C-DC-F | \$ 33,661.00 | 10% | <i>\$30,522.11</i> |
| EWP Premier 4HR AHR 8820-80C-DC-R | 98007-8820-80C-DC-R | \$ 33,661.00 | 10% | <i>\$30,522.11</i> |

| | | | | |
|---------------------------------------|-------------------------|--------------|----|--------------------|
| EWP Premier 4HR AHR 9920-16C | 98007-9920-16C | \$ 13,237.00 | 6% | <i>\$12,536.10</i> |
| EWP Premier 4HR AHR 9920-4D | 98007-9920-4D | \$ 13,237.00 | 6% | <i>\$12,536.10</i> |
| EWP Premier 4HR AHR 9920-NPB-8 | 98007-9920-NPB-8 | \$ 21,817.00 | 6% | <i>\$20,661.79</i> |
| EWP Premier 4HR AHR A10148 | 98007-A10148 | \$ 3,923.00 | 6% | <i>\$3,715.28</i> |
| EWP Premier 4HR AHR A10149 | 98007-A10149 | \$ 7,481.00 | 6% | <i>\$7,084.88</i> |
| EWP Premier 4HR AHR A10152 | 98007-A10152 | \$ 7,481.00 | 6% | <i>\$7,084.88</i> |
| EWP Premier 4HR AHR A10154 | 98007-A10154 | \$ 22,371.00 | 6% | <i>\$21,186.46</i> |
| EWP Premier 4HR AHR A10155 | 98007-A10155 | \$ 8,069.00 | 6% | <i>\$7,641.75</i> |
| EWP Premier 4HR AHR A10157 | 98007-A10157 | \$ 13,973.00 | 6% | <i>\$13,233.13</i> |
| EWP Premier 4HR AHR A10175 | 98007-A10175 | \$ 9,188.00 | 6% | <i>\$8,701.50</i> |
| EWP Premier 4HR AHR A10176 | 98007-A10176 | \$ 13,779.00 | 6% | <i>\$13,049.40</i> |
| EWP Premier 4HR AHR AH-AP-1130-AC-CE | 98007-AH-AP-1130-AC-CE | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR AHR AH-AP-1130-AC-FCC | 98007-AH-AP-1130-AC-FCC | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR AHR AH-AP-1130-AC-W | 98007-AH-AP-1130-AC-W | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR AHR AH-AP-122-AC-CAN | 98007-AH-AP-122-AC-CAN | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-122-AC-CE | 98007-AH-AP-122-AC-CE | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-122-AC-FCC | 98007-AH-AP-122-AC-FCC | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-122-AC-W | 98007-AH-AP-122-AC-W | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-130-AC-CE | 98007-AH-AP-130-AC-CE | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-130-AC-FCC | 98007-AH-AP-130-AC-FCC | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-130-AC-W | 98007-AH-AP-130-AC-W | \$ 104.00 | 6% | <i>\$98.49</i> |

| | | | | |
|---------------------------------------|-------------------------|-----------|----|-----------------|
| EWP Premier 4HR AHR AH-AP-150W-AC-CAN | 98007-AH-AP-150W-AC-CAN | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-150W-AC-CE | 98007-AH-AP-150W-AC-CE | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-150W-AC-FCC | 98007-AH-AP-150W-AC-FCC | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-150W-AC-W | 98007-AH-AP-150W-AC-W | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-230-AC-CE | 98007-AH-AP-230-AC-CE | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-230-AC-FCC | 98007-AH-AP-230-AC-FCC | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-230-AC-W | 98007-AH-AP-230-AC-W | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-250-AC-CAN | 98007-AH-AP-250-AC-CAN | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-250-AC-CE | 98007-AH-AP-250-AC-CE | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-250-AC-FCC | 98007-AH-AP-250-AC-FCC | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-250-AC-W | 98007-AH-AP-250-AC-W | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-AP-630-AX-CAN | 98007-AH-AP-630-AX-CAN | \$ 149.00 | 6% | <i>\$141.11</i> |
| EWP Premier 4HR AHR AH-AP-630-AX-CE | 98007-AH-AP-630-AX-CE | \$ 149.00 | 6% | <i>\$141.11</i> |
| EWP Premier 4HR AHR AH-AP-630-AX-FCC | 98007-AH-AP-630-AX-FCC | \$ 149.00 | 6% | <i>\$141.11</i> |
| EWP Premier 4HR AHR AH-AP-630-AX-W | 98007-AH-AP-630-AX-W | \$ 149.00 | 6% | <i>\$141.11</i> |
| EWP Premier 4HR AHR AH-AP-650-AX-CAN | 98007-AH-AP-650-AX-CAN | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR AH-AP-650-AX-CE | 98007-AH-AP-650-AX-CE | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR AH-AP-650-AX-FCC | 98007-AH-AP-650-AX-FCC | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR AH-AP-650-AX-W | 98007-AH-AP-650-AX-W | \$ 141.00 | 6% | <i>\$133.53</i> |

| | | | | |
|---------------------------------------|-------------------------|-----------|----|-----------------|
| EWP Premier 4HR AHR AH-AP-650X-AX-CAN | 98007-AH-AP-650X-AX-CAN | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR AH-AP-650X-AX-CE | 98007-AH-AP-650X-AX-CE | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR AH-AP-650X-AX-FCC | 98007-AH-AP-650X-AX-FCC | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR AH-AP-650X-AX-W | 98007-AH-AP-650X-AX-W | \$ 141.00 | 6% | <i>\$133.53</i> |
| EWP Premier 4HR AHR AH-ATOM-CAN | 98007-AH-ATOM-CAN | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR AH-ATOM-CE-EU | 98007-AH-ATOM-CE-EU | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR AH-ATOM-CE-UK | 98007-AH-ATOM-CE-UK | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR AH-ATOM-FCC | 98007-AH-ATOM-FCC | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR AH-ATOM-W | 98007-AH-ATOM-W | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR AH-ATOM-W-EU | 98007-AH-ATOM-W-EU | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR AH-ATOM-W-UK | 98007-AH-ATOM-W-UK | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR AH-SR-2208P-AU | 98007-AH-SR-2208P-AU | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-SR-2208P-EU | 98007-AH-SR-2208P-EU | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-SR-2208P-NA | 98007-AH-SR-2208P-NA | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-SR-2208P-UK | 98007-AH-SR-2208P-UK | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-SR-2224P-AU | 98007-AH-SR-2224P-AU | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR AH-SR-2224P-EU | 98007-AH-SR-2224P-EU | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR AH-SR-2224P-NA | 98007-AH-SR-2224P-NA | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR AH-SR-2224P-UK | 98007-AH-SR-2224P-UK | \$ 146.00 | 6% | <i>\$138.27</i> |

| | | | | |
|---------------------------------------|-------------------------|-----------|----|-----------------|
| EWP Premier 4HR AHR AH-SR-2324P-AU | 98007-AH-SR-2324P-AU | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier 4HR AHR AH-SR-2324P-EU | 98007-AH-SR-2324P-EU | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier 4HR AHR AH-SR-2324P-NA | 98007-AH-SR-2324P-NA | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier 4HR AHR AH-SR-2324P-UK | 98007-AH-SR-2324P-UK | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier 4HR AHR AH-SR-2348P-AU | 98007-AH-SR-2348P-AU | \$ 324.00 | 6% | <i>\$306.84</i> |
| EWP Premier 4HR AHR AH-SR-2348P-EU | 98007-AH-SR-2348P-EU | \$ 324.00 | 6% | <i>\$306.84</i> |
| EWP Premier 4HR AHR AH-SR-2348P-NA | 98007-AH-SR-2348P-NA | \$ 324.00 | 6% | <i>\$306.84</i> |
| EWP Premier 4HR AHR AH-SR-2348P-UK | 98007-AH-SR-2348P-UK | \$ 324.00 | 6% | <i>\$306.84</i> |
| EWP Premier 4HR AHR AH-XR200P-AU | 98007-AH-XR200P-AU | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-XR200P-EU | 98007-AH-XR200P-EU | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-XR200P-UK | 98007-AH-XR200P-UK | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-XR200P-US | 98007-AH-XR200P-US | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier 4HR AHR AH-XR600P | 98007-AH-XR600P | \$ 110.00 | 6% | <i>\$104.18</i> |
| EWP Premier 4HR AHR AH-XR600P-AU | 98007-AH-XR600P-AU | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR AH-XR600P-EU | 98007-AH-XR600P-EU | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR AH-XR600P-KR | 98007-AH-XR600P-KR | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR AH-XR600P-UK | 98007-AH-XR600P-UK | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR AH-XR600P-US | 98007-AH-XR600P-US | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR AP-8533-68SB30-IL | 98007-AP-8533-68SB30-IL | \$ 188.00 | 6% | <i>\$178.05</i> |
| EWP Premier 4HR AHR AP3000-IL | 98007-AP3000-IL | \$ 75.15 | 6% | <i>\$71.17</i> |

| | | | | |
|----------------------------------|--------------------|-----------|-----|-----------------|
| EWP Premier 4HR AHR AP3000-TN | 98007-AP3000-TN | \$ 75.15 | 6% | <i>\$71.17</i> |
| EWP Premier 4HR AHR AP3000-WW | 98007-AP3000-WW | \$ 75.15 | 6% | <i>\$71.17</i> |
| EWP Premier 4HR AHR AP3000X-WW | 98007-AP3000X-WW | \$ 96.03 | 6% | <i>\$90.94</i> |
| EWP Premier 4HR AHR AP302W-CAN | 98007-AP302W-CAN | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier 4HR AHR AP302W-EG | 98007-AP302W-EG | \$ 84.00 | 10% | <i>\$76.17</i> |
| EWP Premier 4HR AHR AP302W-FCC | 98007-AP302W-FCC | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier 4HR AHR AP302W-WR | 98007-AP302W-WR | \$ 76.00 | 6% | <i>\$71.98</i> |
| EWP Premier 4HR AHR AP305C-1-CAN | 98007-AP305C-1-CAN | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier 4HR AHR AP305C-1-EG | 98007-AP305C-1-EG | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier 4HR AHR AP305C-1-FCC | 98007-AP305C-1-FCC | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier 4HR AHR AP305C-1-IL | 98007-AP305C-1-IL | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier 4HR AHR AP305C-1-WR | 98007-AP305C-1-WR | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier 4HR AHR AP305C-CAN | 98007-AP305C-CAN | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP305C-EG | 98007-AP305C-EG | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP305C-FCC | 98007-AP305C-FCC | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP305C-IL | 98007-AP305C-IL | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP305C-WR | 98007-AP305C-WR | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP305CX-CAN | 98007-AP305CX-CAN | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP305CX-FCC | 98007-AP305CX-FCC | \$ 108.00 | 6% | <i>\$102.28</i> |

| | | | | |
|---------------------------------|-------------------|-----------|-----|-----------------|
| EWP Premier 4HR AHR AP305CX-IL | 98007-AP305CX-IL | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP305CX-WR | 98007-AP305CX-WR | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR AHR AP310e-1-WR | 98007-AP310e-1-WR | \$ 64.00 | 10% | <i>\$58.03</i> |
| EWP Premier 4HR AHR AP310e-CAN | 98007-AP310e-CAN | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP310e-FCC | 98007-AP310e-FCC | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP310e-IL | 98007-AP310e-IL | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP310e-WR | 98007-AP310e-WR | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP310i-1-WR | 98007-AP310i-1-WR | \$ 64.00 | 10% | <i>\$58.03</i> |
| EWP Premier 4HR AHR AP310i-CAN | 98007-AP310i-CAN | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP310i-FCC | 98007-AP310i-FCC | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP310i-IL | 98007-AP310i-IL | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP310i-WR | 98007-AP310i-WR | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier 4HR AHR AP360e-CAN | 98007-AP360e-CAN | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR AP360e-FCC | 98007-AP360e-FCC | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR AP360e-IL | 98007-AP360e-IL | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR AP360e-WR | 98007-AP360e-WR | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR AP360i-CAN | 98007-AP360i-CAN | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR AP360i-FCC | 98007-AP360i-FCC | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR AP360i-WR | 98007-AP360i-WR | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR AP4000-WW | 98007-AP4000-1-WW | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier 4HR AHR AP4000-IL | 98007-AP4000-IL | \$ 114.00 | 6% | <i>\$107.96</i> |

| | | | | |
|----------------------------------|--------------------|-----------|-----|-----------------|
| EWP Premier 4HR AHR AP4000-WW | 98007-AP4000-WW | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier 4HR AHR AP410C-1-CAN | 98007-AP410C-1-CAN | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR AHR AP410C-1-EG | 98007-AP410C-1-EG | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR AHR AP410C-1-FCC | 98007-AP410C-1-FCC | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR AHR AP410C-1-IL | 98007-AP410C-1-IL | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR AHR AP410C-1-WR | 98007-AP410C-1-WR | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR AHR AP410C-CAN | 98007-AP410C-CAN | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR AHR AP410C-EG | 98007-AP410C-EG | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR AHR AP410C-FCC | 98007-AP410C-FCC | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR AHR AP410C-IL | 98007-AP410C-IL | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR AHR AP410C-WR | 98007-AP410C-WR | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR AHR AP410e-CAN | 98007-AP410e-CAN | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR AHR AP410e-FCC | 98007-AP410e-FCC | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR AHR AP410e-WR | 98007-AP410e-WR | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR AHR AP410i-1-FCC | 98007-AP410i-1-FCC | \$ 117.00 | 10% | <i>\$106.09</i> |
| EWP Premier 4HR AHR AP410i-1-WR | 98007-AP410i-1-WR | \$ 117.00 | 10% | <i>\$106.09</i> |
| EWP Premier 4HR AHR AP410i-CAN | 98007-AP410i-CAN | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR AHR AP410i-FCC | 98007-AP410i-FCC | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR AHR AP410i-IL | 98007-AP410i-IL | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR AHR AP410i-WR | 98007-AP410i-WR | \$ 122.00 | 6% | <i>\$115.54</i> |

| | | | | |
|-----------------------------------|---------------------|-----------|----|----------|
| EWP Premier 4HR AHR AP460C-CAN | 98007-AP460C-CAN | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460C-EG | 98007-AP460C-EG | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460C-FCC | 98007-AP460C-FCC | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460C-IL | 98007-AP460C-IL | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460C-WR | 98007-AP460C-WR | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460e-CAN | 98007-AP460e-CAN | \$ 141.00 | 6% | \$133.53 |
| EWP Premier 4HR AHR AP460e-FCC | 98007-AP460e-FCC | \$ 141.00 | 6% | \$133.53 |
| EWP Premier 4HR AHR AP460e-WR | 98007-AP460e-WR | \$ 134.00 | 6% | \$126.90 |
| EWP Premier 4HR AHR AP460i-CAN | 98007-AP460i-CAN | \$ 134.00 | 6% | \$126.90 |
| EWP Premier 4HR AHR AP460i-FCC | 98007-AP460i-FCC | \$ 134.00 | 6% | \$126.90 |
| EWP Premier 4HR AHR AP460i-IL | 98007-AP460i-IL | \$ 134.00 | 6% | \$126.90 |
| EWP Premier 4HR AHR AP460i-WR | 98007-AP460i-WR | \$ 134.00 | 6% | \$126.90 |
| EWP Premier 4HR AHR AP460S12C-CAN | 98007-AP460S12C-CAN | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460S12C-FCC | 98007-AP460S12C-FCC | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460S12C-WR | 98007-AP460S12C-WR | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460S6C-CAN | 98007-AP460S6C-CAN | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460S6C-FCC | 98007-AP460S6C-FCC | \$ 147.00 | 6% | \$139.22 |
| EWP Premier 4HR AHR AP460S6C-WR | 98007-AP460S6C-WR | \$ 147.00 | 6% | \$139.22 |

| | | | | |
|------------------------------------|----------------------|-----------|-----|-----------------|
| EWP Premier 4HR AHR AP5010-IL | 98007-AP5010-IL | \$ 183.00 | 6% | <i>\$173.31</i> |
| EWP Premier 4HR AHR AP5010-WW | 98007-AP5010-WW | \$ 183.00 | 10% | <i>\$165.94</i> |
| EWP Premier 4HR AHR AP5020-WW | 98007-AP5020-WW | \$ 200.32 | 6% | <i>\$189.71</i> |
| EWP Premier 4HR AHR AP5050D-WW | 98007-AP5050D-WW | \$ 418.00 | 6% | <i>\$395.87</i> |
| EWP Premier 4HR AHR AP5050U-WW | 98007-AP5050U-WW | \$ 326.00 | 6% | <i>\$308.74</i> |
| EWP Premier 4HR AHR AP505i-FCC | 98007-AP505i-FCC | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR AP505i-FCC-TAA | 98007-AP505i-FCC-TAA | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR AP505i-WR | 98007-AP505i-WR | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR AHR AP510C-CAN | 98007-AP510C-CAN | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510C-CE | 98007-AP510C-CE | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510C-FCC | 98007-AP510C-FCC | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510C-W | 98007-AP510C-W | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510C-WW | 98007-AP510C-WW | \$ 160.00 | 6% | <i>\$151.53</i> |
| EWP Premier 4HR AHR AP510CX-CAN | 98007-AP510CX-CAN | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510CX-CE | 98007-AP510CX-CE | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510CX-FCC | 98007-AP510CX-FCC | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510CX-W | 98007-AP510CX-W | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR AP510CX-WW | 98007-AP510CX-WW | \$ 160.00 | 6% | <i>\$151.53</i> |
| EWP Premier 4HR AHR AP510e-FCC | 98007-AP510e-FCC | \$ 190.00 | 6% | <i>\$179.94</i> |

| | | | | |
|------------------------------------|----------------------|--------------|-----|--------------------|
| EWP Premier 4HR AHR AP510e-FCC-TAA | 98007-AP510e-FCC-TAA | \$ 190.00 | 6% | <i>\$179.94</i> |
| EWP Premier 4HR AHR AP510e-WR | 98007-AP510e-WR | \$ 181.00 | 6% | <i>\$171.42</i> |
| EWP Premier 4HR AHR AP510i-1-FCC | 98007-AP510i-1-FCC | \$ 160.00 | 10% | <i>\$145.08</i> |
| EWP Premier 4HR AHR AP510i-1-WR | 98007-AP510i-1-WR | \$ 160.00 | 10% | <i>\$145.08</i> |
| EWP Premier 4HR AHR AP510i-FCC | 98007-AP510i-FCC | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR AHR AP510i-FCC-TAA | 98007-AP510i-FCC-TAA | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR AHR AP510i-WR | 98007-AP510i-WR | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR AHR AP560h-FCC | 98007-AP560h-FCC | \$ 426.00 | 6% | <i>\$403.44</i> |
| EWP Premier 4HR AHR AP560h-WR | 98007-AP560h-WR | \$ 426.00 | 6% | <i>\$403.44</i> |
| EWP Premier 4HR AHR AP560i-FCC | 98007-AP560i-FCC | \$ 312.00 | 6% | <i>\$295.48</i> |
| EWP Premier 4HR AHR AP560i-WR | 98007-AP560i-WR | \$ 297.00 | 6% | <i>\$281.27</i> |
| EWP Premier 4HR AHR AP560m-FCC | 98007-AP560m-FCC | \$ 312.00 | 6% | <i>\$295.48</i> |
| EWP Premier 4HR AHR AP560t-FCC | 98007-AP560t-FCC | \$ 426.00 | 6% | <i>\$403.44</i> |
| EWP Premier 4HR AHR AP560u-FCC | 98007-AP560u-FCC | \$ 290.00 | 6% | <i>\$274.64</i> |
| EWP Premier 4HR AHR E2122 | 98007-E2122 | \$ 7,312.00 | 6% | <i>\$6,924.83</i> |
| EWP Premier 4HR AHR E2122-1 | 98007-E2122-1 | \$ 6,964.00 | 6% | <i>\$6,595.26</i> |
| EWP Premier 4HR AHR E3120-1 | 98007-E3120-1 | \$ 11,390.00 | 6% | <i>\$10,786.90</i> |
| EWP Premier 4HR AHR E3125 | 98007-E3125 | \$ 12,003.00 | 6% | <i>\$11,367.44</i> |
| EWP Premier 4HR AHR H30078 | 98007-H30078 | \$ 4,135.00 | 6% | <i>\$3,916.05</i> |
| EWP Premier 4HR AHR H30104 | 98007-H30104 | \$ 3,750.00 | 6% | <i>\$3,551.44</i> |
| EWP Premier 4HR AHR H30105 | 98007-H30105 | \$ 3,776.00 | 6% | <i>\$3,576.06</i> |
| EWP Premier 4HR AHR H30131 | 98007-H30131 | \$ 2,167.00 | 6% | <i>\$2,052.26</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H30132 | 98007-H30132 | \$ 2,125.00 | 6% | <i>\$2,012.48</i> |
| EWP Premier 4HR AHR H30133 | 98007-H30133 | \$ 5,582.00 | 6% | <i>\$5,286.43</i> |
| EWP Premier 4HR AHR H30134 | 98007-H30134 | \$ 7,064.00 | 6% | <i>\$6,689.96</i> |
| EWP Premier 4HR AHR H30135 | 98007-H30135 | \$ 5,690.00 | 6% | <i>\$5,388.71</i> |
| EWP Premier 4HR AHR H30136 | 98007-H30136 | \$ 7,064.00 | 6% | <i>\$6,689.96</i> |
| EWP Premier 4HR AHR H30184 | 98007-H30184 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30185 | 98007-H30185 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H30186 | 98007-H30186 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR AHR H30187 | 98007-H30187 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier 4HR AHR H30188 | 98007-H30188 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR AHR H30189 | 98007-H30189 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR AHR H30190 | 98007-H30190 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30214 | 98007-H30214 | \$ 271.00 | 6% | <i>\$256.65</i> |
| EWP Premier 4HR AHR H30215 | 98007-H30215 | \$ 271.00 | 6% | <i>\$256.65</i> |
| EWP Premier 4HR AHR H30216 | 98007-H30216 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30217 | 98007-H30217 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30218 | 98007-H30218 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30219 | 98007-H30219 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30220 | 98007-H30220 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30221 | 98007-H30221 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30222 | 98007-H30222 | \$ 529.00 | 6% | <i>\$500.99</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H30223 | 98007-H30223 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30224 | 98007-H30224 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30225 | 98007-H30225 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30226 | 98007-H30226 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30227 | 98007-H30227 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30228 | 98007-H30228 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30229 | 98007-H30229 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30267 | 98007-H30267 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30268 | 98007-H30268 | \$ 529.00 | 6% | <i>\$500.99</i> |
| EWP Premier 4HR AHR H30269 | 98007-H30269 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30270 | 98007-H30270 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30271 | 98007-H30271 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30272 | 98007-H30272 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30273 | 98007-H30273 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| EWP Premier 4HR AHR H30274 | 98007-H30274 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| EWP Premier 4HR AHR H30275 | 98007-H30275 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30276 | 98007-H30276 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30277 | 98007-H30277 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| EWP Premier 4HR AHR H30278 | 98007-H30278 | \$ 1,255.00 | 6% | <i>\$1,188.55</i> |
| EWP Premier 4HR AHR H30279 | 98007-H30279 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| EWP Premier 4HR AHR H30280 | 98007-H30280 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H30281 | 98007-H30281 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| EWP Premier 4HR AHR H30282 | 98007-H30282 | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| EWP Premier 4HR AHR H30283 | 98007-H30283 | \$ 769.00 | 6% | <i>\$728.28</i> |
| EWP Premier 4HR AHR H30284 | 98007-H30284 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR AHR H30293 | 98007-H30293 | \$ 4,073.00 | 6% | <i>\$3,857.33</i> |
| EWP Premier 4HR AHR H30296 | 98007-H30296 | \$ 271.00 | 6% | <i>\$256.65</i> |
| EWP Premier 4HR AHR H30297 | 98007-H30297 | \$ 271.00 | 6% | <i>\$256.65</i> |
| EWP Premier 4HR AHR H30298 | 98007-H30298 | \$ 271.00 | 6% | <i>\$256.65</i> |
| EWP Premier 4HR AHR H30299 | 98007-H30299 | \$ 271.00 | 6% | <i>\$256.65</i> |
| EWP Premier 4HR AHR H30381 | 98007-H30381 | \$ 771.00 | 6% | <i>\$730.18</i> |
| EWP Premier 4HR AHR H30384 | 98007-H30384 | \$ 616.00 | 6% | <i>\$583.38</i> |
| EWP Premier 4HR AHR H30391 | 98007-H30391 | \$ 1,451.00 | 6% | <i>\$1,374.17</i> |
| EWP Premier 4HR AHR H30392 | 98007-H30392 | \$ 1,451.00 | 6% | <i>\$1,374.17</i> |
| EWP Premier 4HR AHR H30393 | 98007-H30393 | \$ 656.00 | 6% | <i>\$621.26</i> |
| EWP Premier 4HR AHR H30394 | 98007-H30394 | \$ 2,827.00 | 6% | <i>\$2,677.31</i> |
| EWP Premier 4HR AHR H30395 | 98007-H30395 | \$ 3,364.00 | 6% | <i>\$3,185.88</i> |
| EWP Premier 4HR AHR H30396 | 98007-H30396 | \$ 3,069.00 | 6% | <i>\$2,906.50</i> |
| EWP Premier 4HR AHR H30397 | 98007-H30397 | \$ 3,631.00 | 6% | <i>\$3,438.74</i> |
| EWP Premier 4HR AHR H30398 | 98007-H30398 | \$ 669.00 | 6% | <i>\$633.58</i> |
| EWP Premier 4HR AHR H30400 | 98007-H30400 | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier 4HR AHR H30401 | 98007-H30401 | \$ 516.00 | 6% | <i>\$488.68</i> |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR AHR H30402 | 98007-H30402 | \$ 558.00 | 6% | \$528.45 |
| EWP Premier 4HR AHR H30403 | 98007-H30403 | \$ 821.00 | 6% | \$777.53 |
| EWP Premier 4HR AHR H30434 | 98007-H30434 | \$ 223.00 | 6% | \$211.19 |
| EWP Premier 4HR AHR H30480 | 98007-H30480 | \$ 952.00 | 6% | \$901.59 |
| EWP Premier 4HR AHR H30495 | 98007-H30495 | \$ 2,167.00 | 6% | \$2,052.26 |
| EWP Premier 4HR AHR H30496 | 98007-H30496 | \$ 2,125.00 | 6% | \$2,012.48 |
| EWP Premier 4HR AHR H30497 | 98007-H30497 | \$ 3,129.00 | 6% | \$2,963.32 |
| EWP Premier 4HR AHR H30498 | 98007-H30498 | \$ 3,069.00 | 6% | \$2,906.50 |
| EWP Premier 4HR AHR H30499 | 98007-H30499 | \$ 1,051.00 | 6% | \$995.35 |
| EWP Premier 4HR AHR H30501 | 98007-H30501 | \$ 3,069.00 | 6% | \$2,906.50 |
| EWP Premier 4HR AHR H30502 | 98007-H30502 | \$ 4,717.00 | 6% | \$4,467.23 |
| EWP Premier 4HR AHR H30503 | 98007-H30503 | \$ 1,051.00 | 6% | \$995.35 |
| EWP Premier 4HR AHR H30505 | 98007-H30505 | \$ 5,582.00 | 6% | \$5,286.43 |
| EWP Premier 4HR AHR H30506 | 98007-H30506 | \$ 7,581.00 | 6% | \$7,179.59 |
| EWP Premier 4HR AHR H30509 | 98007-H30509 | \$ 4,717.00 | 6% | \$4,467.23 |
| EWP Premier 4HR AHR H30510 | 98007-H30510 | \$ 5,582.00 | 6% | \$5,286.43 |
| EWP Premier 4HR AHR H30511 | 98007-H30511 | \$ 7,581.00 | 6% | \$7,179.59 |
| EWP Premier 4HR AHR H30512 | 98007-H30512 | \$ 1,051.00 | 6% | \$995.35 |
| EWP Premier 4HR AHR H30513 | 98007-H30513 | \$ 1,766.00 | 6% | \$1,672.49 |
| EWP Premier 4HR AHR H30525 | 98007-H30525 | \$ 7,581.00 | 6% | \$7,179.59 |
| EWP Premier 4HR AHR H30526 | 98007-H30526 | \$ 5,582.00 | 6% | \$5,286.43 |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H30528 | 98007-H30528 | \$ 8,795.00 | 6% | <i>\$8,329.30</i> |
| EWP Premier 4HR AHR H30531 | 98007-H30531 | \$ 12,527.00 | 6% | <i>\$11,863.70</i> |
| EWP Premier 4HR AHR H30532 | 98007-H30532 | \$ 12,527.00 | 6% | <i>\$11,863.70</i> |
| EWP Premier 4HR AHR H30534 | 98007-H30534 | \$ 12,770.00 | 6% | <i>\$12,093.83</i> |
| EWP Premier 4HR AHR H30535 | 98007-H30535 | \$ 13,622.00 | 6% | <i>\$12,900.72</i> |
| EWP Premier 4HR AHR H30536 | 98007-H30536 | \$ 12,527.00 | 6% | <i>\$11,863.70</i> |
| EWP Premier 4HR AHR H30537 | 98007-H30537 | \$ 13,622.00 | 6% | <i>\$12,900.72</i> |
| EWP Premier 4HR AHR H30538 | 98007-H30538 | \$ 7,581.00 | 6% | <i>\$7,179.59</i> |
| EWP Premier 4HR AHR H30539 | 98007-H30539 | \$ 14,548.00 | 6% | <i>\$13,777.68</i> |
| EWP Premier 4HR AHR H30540 | 98007-H30540 | \$ 15,050.00 | 6% | <i>\$14,253.10</i> |
| EWP Premier 4HR AHR H30543 | 98007-H30543 | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| EWP Premier 4HR AHR H30544 | 98007-H30544 | \$ 1,838.00 | 6% | <i>\$1,740.68</i> |
| EWP Premier 4HR AHR H30548 | 98007-H30548 | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| EWP Premier 4HR AHR H30549 | 98007-H30549 | \$ 1,733.00 | 6% | <i>\$1,641.24</i> |
| EWP Premier 4HR AHR H30550 | 98007-H30550 | \$ 1,733.00 | 6% | <i>\$1,641.24</i> |
| EWP Premier 4HR AHR H30552 | 98007-H30552 | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| EWP Premier 4HR AHR H30553 | 98007-H30553 | \$ 1,634.00 | 6% | <i>\$1,547.48</i> |
| EWP Premier 4HR AHR H30569 | 98007-H30569 | \$ 5,582.00 | 6% | <i>\$5,286.43</i> |
| EWP Premier 4HR AHR H30570 | 98007-H30570 | \$ 6,680.00 | 6% | <i>\$6,326.29</i> |
| EWP Premier 4HR AHR H30571 | 98007-H30571 | \$ 6,680.00 | 6% | <i>\$6,326.29</i> |
| EWP Premier 4HR AHR H30573 | 98007-H30573 | \$ 5,582.00 | 6% | <i>\$5,286.43</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H30574 | 98007-H30574 | \$ 6,172.00 | 6% | <i>\$5,845.19</i> |
| EWP Premier 4HR AHR H30575 | 98007-H30575 | \$ 3,851.00 | 6% | <i>\$3,647.09</i> |
| EWP Premier 4HR AHR H30576 | 98007-H30576 | \$ 5,582.00 | 6% | <i>\$5,286.43</i> |
| EWP Premier 4HR AHR H30577 | 98007-H30577 | \$ 6,552.00 | 6% | <i>\$6,205.07</i> |
| EWP Premier 4HR AHR H30578 | 98007-H30578 | \$ 6,552.00 | 6% | <i>\$6,205.07</i> |
| EWP Premier 4HR AHR H30587 | 98007-H30587 | \$ 5,690.00 | 6% | <i>\$5,388.71</i> |
| EWP Premier 4HR AHR H30588 | 98007-H30588 | \$ 3,926.00 | 6% | <i>\$3,718.12</i> |
| EWP Premier 4HR AHR H30589 | 98007-H30589 | \$ 5,961.00 | 6% | <i>\$5,645.37</i> |
| EWP Premier 4HR AHR H30632 | 98007-H30632 | \$ 151.00 | 6% | <i>\$143.00</i> |
| EWP Premier 4HR AHR H30633 | 98007-H30633 | \$ 151.00 | 6% | <i>\$143.00</i> |
| EWP Premier 4HR AHR H30643 | 98007-H30643 | \$ 9,394.00 | 6% | <i>\$8,896.59</i> |
| EWP Premier 4HR AHR H30706 | 98007-H30706 | \$ 8,965.00 | 6% | <i>\$8,490.30</i> |
| EWP Premier 4HR AHR H30707 | 98007-H30707 | \$ 5,582.00 | 6% | <i>\$5,286.43</i> |
| EWP Premier 4HR AHR H30724 | 98007-H30724 | \$ 616.00 | 6% | <i>\$583.38</i> |
| EWP Premier 4HR AHR H30725 | 98007-H30725 | \$ 2,125.00 | 6% | <i>\$2,012.48</i> |
| EWP Premier 4HR AHR H30726 | 98007-H30726 | \$ 13,886.00 | 6% | <i>\$13,150.74</i> |
| EWP Premier 4HR AHR H30727 | 98007-H30727 | \$ 14,763.00 | 6% | <i>\$13,981.30</i> |
| EWP Premier 4HR AHR H30730 | 98007-H30730 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR AHR H30731 | 98007-H30731 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR AHR H30732 | 98007-H30732 | \$ 2,580.00 | 6% | <i>\$2,443.39</i> |
| EWP Premier 4HR AHR H30733 | 98007-H30733 | \$ 13,298.00 | 6% | <i>\$12,593.87</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H30734 | 98007-H30734 | \$ 10,146.00 | 6% | <i>\$9,608.77</i> |
| EWP Premier 4HR AHR H30735 | 98007-H30735 | \$ 11,739.00 | 6% | <i>\$11,117.42</i> |
| EWP Premier 4HR AHR H30736 | 98007-H30736 | \$ 1,844.00 | 6% | <i>\$1,746.36</i> |
| EWP Premier 4HR AHR H30738 | 98007-H30738 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier 4HR AHR H30739 | 98007-H30739 | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWP Premier 4HR AHR H30740 | 98007-H30740 | \$ 1,124.00 | 6% | <i>\$1,064.48</i> |
| EWP Premier 4HR AHR H30741 | 98007-H30741 | \$ 2,053.00 | 6% | <i>\$1,944.29</i> |
| EWP Premier 4HR AHR H30742 | 98007-H30742 | \$ 1,826.00 | 6% | <i>\$1,729.31</i> |
| EWP Premier 4HR AHR H30743 | 98007-H30743 | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWP Premier 4HR AHR H30744 | 98007-H30744 | \$ 1,124.00 | 6% | <i>\$1,064.48</i> |
| EWP Premier 4HR AHR H30745 | 98007-H30745 | \$ 1,143.00 | 6% | <i>\$1,082.48</i> |
| EWP Premier 4HR AHR H30746 | 98007-H30746 | \$ 2,066.00 | 6% | <i>\$1,956.61</i> |
| EWP Premier 4HR AHR H30747 | 98007-H30747 | \$ 4,048.00 | 6% | <i>\$3,833.66</i> |
| EWP Premier 4HR AHR H30748 | 98007-H30748 | \$ 5,970.00 | 6% | <i>\$5,653.89</i> |
| EWP Premier 4HR AHR H30749 | 98007-H30749 | \$ 13,412.00 | 6% | <i>\$12,701.83</i> |
| EWP Premier 4HR AHR H30750 | 98007-H30750 | \$ 13,412.00 | 6% | <i>\$12,701.83</i> |
| EWP Premier 4HR AHR H30751 | 98007-H30751 | \$ 7,962.00 | 6% | <i>\$7,540.41</i> |
| EWP Premier 4HR AHR H30754 | 98007-H30754 | \$ 13,412.00 | 6% | <i>\$12,701.83</i> |
| EWP Premier 4HR AHR H30755 | 98007-H30755 | \$ 14,580.00 | 6% | <i>\$13,807.99</i> |
| EWP Premier 4HR AHR H30756 | 98007-H30756 | \$ 13,412.00 | 6% | <i>\$12,701.83</i> |
| EWP Premier 4HR AHR H30757 | 98007-H30757 | \$ 5,970.00 | 6% | <i>\$5,653.89</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H30758 | 98007-H30758 | \$ 10,857.00 | 6% | <i>\$10,282.12</i> |
| EWP Premier 4HR AHR H30759 | 98007-H30759 | \$ 12,329.00 | 6% | <i>\$11,676.18</i> |
| EWP Premier 4HR AHR H30760 | 98007-H30760 | \$ 13,960.00 | 6% | <i>\$13,220.82</i> |
| EWP Premier 4HR AHR H30761 | 98007-H30761 | \$ 5,970.00 | 6% | <i>\$5,653.89</i> |
| EWP Premier 4HR AHR H30762 | 98007-H30762 | \$ 14,580.00 | 6% | <i>\$13,807.99</i> |
| EWP Premier 4HR AHR H30763 | 98007-H30763 | \$ 14,580.00 | 6% | <i>\$13,807.99</i> |
| EWP Premier 4HR AHR H30764 | 98007-H30764 | \$ 9,234.00 | 6% | <i>\$8,745.06</i> |
| EWP Premier 4HR AHR H30765 | 98007-H30765 | \$ 8,117.00 | 6% | <i>\$7,687.20</i> |
| EWP Premier 4HR AHR H30766 | 98007-H30766 | \$ 15,805.00 | 6% | <i>\$14,968.13</i> |
| EWP Premier 4HR AHR H30767 | 98007-H30767 | \$ 9,234.00 | 6% | <i>\$8,745.06</i> |
| EWP Premier 4HR AHR H30769 | 98007-H30769 | \$ 3,325.00 | 6% | <i>\$3,148.94</i> |
| EWP Premier 4HR AHR H30773 | 98007-H30773 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier 4HR AHR H30774 | 98007-H30774 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR AHR H30775 | 98007-H30775 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR AHR H30776 | 98007-H30776 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier 4HR AHR H30777 | 98007-H30777 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR AHR H30778 | 98007-H30778 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR AHR H30779 | 98007-H30779 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H30780 | 98007-H30780 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier 4HR AHR H30781 | 98007-H30781 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier 4HR AHR H30782 | 98007-H30782 | \$ 102.00 | 6% | <i>\$96.60</i> |

| | | | | |
|----------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR AHR H30783 | 98007-H30783 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier 4HR AHR H30784 | 98007-H30784 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier 4HR AHR H30785 | 98007-H30785 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H30786 | 98007-H30786 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier 4HR AHR H30787 | 98007-H30787 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H30788 | 98007-H30788 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier 4HR AHR H30789 | 98007-H30789 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier 4HR AHR H30790 | 98007-H30790 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H30791 | 98007-H30791 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier 4HR AHR H30793 | 98007-H30793 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30794 | 98007-H30794 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR AHR H30795 | 98007-H30795 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30796 | 98007-H30796 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier 4HR AHR H30797 | 98007-H30797 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30798 | 98007-H30798 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H30799 | 98007-H30799 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30800 | 98007-H30800 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H30801 | 98007-H30801 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier 4HR AHR H30802 | 98007-H30802 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H30803 | 98007-H30803 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30804 | 98007-H30804 | \$ 96.00 | 6% | <i>\$90.92</i> |

| | | | | |
|----------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR AHR H30805 | 98007-H30805 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H30806 | 98007-H30806 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30807 | 98007-H30807 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30808 | 98007-H30808 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier 4HR AHR H30809 | 98007-H30809 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H30810 | 98007-H30810 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier 4HR AHR H30811 | 98007-H30811 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30812 | 98007-H30812 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H30813 | 98007-H30813 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H30814 | 98007-H30814 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30815 | 98007-H30815 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier 4HR AHR H30816 | 98007-H30816 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier 4HR AHR H30817 | 98007-H30817 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30818 | 98007-H30818 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H30819 | 98007-H30819 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30820 | 98007-H30820 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier 4HR AHR H30821 | 98007-H30821 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H30822 | 98007-H30822 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30823 | 98007-H30823 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H30824 | 98007-H30824 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H30825 | 98007-H30825 | \$ 102.00 | 6% | <i>\$96.60</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H30826 | 98007-H30826 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30827 | 98007-H30827 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30828 | 98007-H30828 | \$ 96.00 | 6% | <i>\$90.92</i> |
| EWP Premier 4HR AHR H30829 | 98007-H30829 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H30830 | 98007-H30830 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR AHR H30831 | 98007-H30831 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H30833 | 98007-H30833 | \$ 497.00 | 6% | <i>\$470.68</i> |
| EWP Premier 4HR AHR H30834 | 98007-H30834 | \$ 497.00 | 6% | <i>\$470.68</i> |
| EWP Premier 4HR AHR H30836 | 98007-H30836 | \$ 1,847.00 | 6% | <i>\$1,749.20</i> |
| EWP Premier 4HR AHR H30838 | 98007-H30838 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier 4HR AHR H30839 | 98007-H30839 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30840 | 98007-H30840 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30841 | 98007-H30841 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30842 | 98007-H30842 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30843 | 98007-H30843 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30844 | 98007-H30844 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30845 | 98007-H30845 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR AHR H30846 | 98007-H30846 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR AHR H30847 | 98007-H30847 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR AHR H30848 | 98007-H30848 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR AHR H30849 | 98007-H30849 | \$ 117.00 | 6% | <i>\$110.80</i> |

| | | | | |
|----------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR AHR H30850 | 98007-H30850 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR AHR H30851 | 98007-H30851 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR AHR H30852 | 98007-H30852 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR AHR H30853 | 98007-H30853 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30854 | 98007-H30854 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30855 | 98007-H30855 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30856 | 98007-H30856 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30857 | 98007-H30857 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30858 | 98007-H30858 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30859 | 98007-H30859 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30860 | 98007-H30860 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR AHR H30866 | 98007-H30866 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier 4HR AHR H30867 | 98007-H30867 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier 4HR AHR H30868 | 98007-H30868 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier 4HR AHR H30869 | 98007-H30869 | \$ 347.00 | 6% | <i>\$328.63</i> |
| EWP Premier 4HR AHR H30870 | 98007-H30870 | \$ 347.00 | 6% | <i>\$328.63</i> |
| EWP Premier 4HR AHR H30871 | 98007-H30871 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EWP Premier 4HR AHR H30872 | 98007-H30872 | \$ 184.00 | 6% | <i>\$174.26</i> |
| EWP Premier 4HR AHR H30873 | 98007-H30873 | \$ 184.00 | 6% | <i>\$174.26</i> |
| EWP Premier 4HR AHR H30874 | 98007-H30874 | \$ 184.00 | 6% | <i>\$174.26</i> |
| EWP Premier 4HR AHR H30875 | 98007-H30875 | \$ 66.00 | 6% | <i>\$62.51</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H30876 | 98007-H30876 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier 4HR AHR H30877 | 98007-H30877 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier 4HR AHR H30878 | 98007-H30878 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier 4HR AHR H30891 | 98007-H30891 | \$ 132.00 | 6% | <i>\$125.01</i> |
| EWP Premier 4HR AHR H30892 | 98007-H30892 | \$ 132.00 | 6% | <i>\$125.01</i> |
| EWP Premier 4HR AHR H30893 | 98007-H30893 | \$ 110.00 | 6% | <i>\$104.18</i> |
| EWP Premier 4HR AHR H30894 | 98007-H30894 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier 4HR AHR H30895 | 98007-H30895 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR AHR H30896 | 98007-H30896 | \$ 526.00 | 6% | <i>\$498.15</i> |
| EWP Premier 4HR AHR H30897 | 98007-H30897 | \$ 914.00 | 6% | <i>\$865.60</i> |
| EWP Premier 4HR AHR H30898 | 98007-H30898 | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| EWP Premier 4HR AHR H30900 | 98007-H30900 | \$ 3,111.00 | 6% | <i>\$2,946.27</i> |
| EWP Premier 4HR AHR H30901 | 98007-H30901 | \$ 4,140.00 | 6% | <i>\$3,920.79</i> |
| EWP Premier 4HR AHR H30902 | 98007-H30902 | \$ 4,347.00 | 6% | <i>\$4,116.83</i> |
| EWP Premier 4HR AHR H30904 | 98007-H30904 | \$ 6,364.00 | 6% | <i>\$6,027.03</i> |
| EWP Premier 4HR AHR H30905 | 98007-H30905 | \$ 9,090.00 | 6% | <i>\$8,608.68</i> |
| EWP Premier 4HR AHR H30906 | 98007-H30906 | \$ 252.00 | 6% | <i>\$238.66</i> |
| EWP Premier 4HR AHR H30912 | 98007-H30912 | \$ 686.00 | 6% | <i>\$649.68</i> |
| EWP Premier 4HR AHR H30913 | 98007-H30913 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier 4HR AHR H30914 | 98007-H30914 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier 4HR AHR H30915 | 98007-H30915 | \$ 68.00 | 6% | <i>\$64.40</i> |

| | | | | |
|----------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR AHR H30916 | 98007-H30916 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier 4HR AHR H30917 | 98007-H30917 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier 4HR AHR H30918 | 98007-H30918 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier 4HR AHR H30946 | 98007-H30946 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR AHR H30948 | 98007-H30948 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR AHR H30950 | 98007-H30950 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR H30951 | 98007-H30951 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR AHR H30952 | 98007-H30952 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR AHR H30966 | 98007-H30966 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR AHR H30967 | 98007-H30967 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier 4HR AHR H30968 | 98007-H30968 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR AHR H30969 | 98007-H30969 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier 4HR AHR H30970 | 98007-H30970 | \$ 157.00 | 6% | <i>\$148.69</i> |
| EWP Premier 4HR AHR H30971 | 98007-H30971 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR H30972 | 98007-H30972 | \$ 157.00 | 6% | <i>\$148.69</i> |
| EWP Premier 4HR AHR H30973 | 98007-H30973 | \$ 230.00 | 6% | <i>\$217.82</i> |
| EWP Premier 4HR AHR H30974 | 98007-H30974 | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier 4HR AHR H30975 | 98007-H30975 | \$ 230.00 | 6% | <i>\$217.82</i> |
| EWP Premier 4HR AHR H30976 | 98007-H30976 | \$ 230.00 | 6% | <i>\$217.82</i> |
| EWP Premier 4HR AHR H30977 | 98007-H30977 | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier 4HR AHR H30978 | 98007-H30978 | \$ 230.00 | 6% | <i>\$217.82</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H30995 | 98007-H30995 | \$ 2,491.00 | 6% | <i>\$2,359.10</i> |
| EWP Premier 4HR AHR H31030 | 98007-H31030 | \$ 8,030.00 | 6% | <i>\$7,604.81</i> |
| EWP Premier 4HR AHR H31031 | 98007-H31031 | \$ 638.00 | 6% | <i>\$604.22</i> |
| EWP Premier 4HR AHR H31033 | 98007-H31033 | \$ 4,770.00 | 6% | <i>\$4,517.43</i> |
| EWP Premier 4HR AHR H31034 | 98007-H31034 | \$ 2,651.00 | 6% | <i>\$2,510.63</i> |
| EWP Premier 4HR AHR H31035 | 98007-H31035 | \$ 2,780.00 | 6% | <i>\$2,632.80</i> |
| EWP Premier 4HR AHR H31036 | 98007-H31036 | \$ 5,558.00 | 6% | <i>\$5,263.70</i> |
| EWP Premier 4HR AHR H31040 | 98007-H31040 | \$ 214.00 | 6% | <i>\$202.67</i> |
| EWP Premier 4HR AHR H31041 | 98007-H31041 | \$ 110.00 | 6% | <i>\$104.18</i> |
| EWP Premier 4HR AHR H31042 | 98007-H31042 | \$ 320.00 | 6% | <i>\$303.06</i> |
| EWP Premier 4HR AHR H31043 | 98007-H31043 | \$ 232.00 | 6% | <i>\$219.72</i> |
| EWP Premier 4HR AHR H31047 | 98007-H31047 | \$ 215.00 | 6% | <i>\$203.62</i> |
| EWP Premier 4HR AHR H31049 | 98007-H31049 | \$ 2,225.00 | 6% | <i>\$2,107.19</i> |
| EWP Premier 4HR AHR H31060 | 98007-H31060 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier 4HR AHR H31062 | 98007-H31062 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier 4HR AHR H31066 | 98007-H31066 | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier 4HR AHR H31068 | 98007-H31068 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier 4HR AHR H31077 | 98007-H31077 | \$ 320.00 | 6% | <i>\$303.06</i> |
| EWP Premier 4HR AHR H31103 | 98007-H31103 | \$ 5,092.00 | 6% | <i>\$4,822.38</i> |
| EWP Premier 4HR AHR H31124 | 98007-H31124 | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR AHR H31127 | 98007-H31127 | \$ 210.00 | 6% | <i>\$198.88</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H31132 | 98007-H31132 | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier 4HR AHR H31134 | 98007-H31134 | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier 4HR AHR H31135 | 98007-H31135 | \$ 70.00 | 6% | <i>\$66.29</i> |
| EWP Premier 4HR AHR H31136 | 98007-H31136 | \$ 107.00 | 6% | <i>\$101.33</i> |
| EWP Premier 4HR AHR H31137 | 98007-H31137 | \$ 100.00 | 6% | <i>\$94.71</i> |
| EWP Premier 4HR AHR H31197 | 98007-H31197 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR H31198 | 98007-H31198 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR H31199 | 98007-H31199 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR H31200 | 98007-H31200 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR H31201 | 98007-H31201 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR H31202 | 98007-H31202 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR AHR H31203 | 98007-H31203 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR H31204 | 98007-H31204 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H31205 | 98007-H31205 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR H31206 | 98007-H31206 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR H31207 | 98007-H31207 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H31208 | 98007-H31208 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR H31210 | 98007-H31210 | \$ 252.00 | 6% | <i>\$238.66</i> |
| EWP Premier 4HR AHR H31335 | 98007-H31335 | \$ 138.00 | 6% | <i>\$130.69</i> |
| EWP Premier 4HR AHR H31337 | 98007-H31337 | \$ 11,033.00 | 6% | <i>\$10,448.80</i> |
| EWP Premier 4HR AHR H31338 | 98007-H31338 | \$ 11,033.00 | 6% | <i>\$10,448.80</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H31339 | 98007-H31339 | \$ 1,798.00 | 6% | <i>\$1,702.80</i> |
| EWP Premier 4HR AHR H31340 | 98007-H31340 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |
| EWP Premier 4HR AHR H31341 | 98007-H31341 | \$ 5,675.00 | 6% | <i>\$5,374.51</i> |
| EWP Premier 4HR AHR H31342 | 98007-H31342 | \$ 1,787.00 | 6% | <i>\$1,692.38</i> |
| EWP Premier 4HR AHR H31343 | 98007-H31343 | \$ 2,639.00 | 6% | <i>\$2,499.26</i> |
| EWP Premier 4HR AHR H31344 | 98007-H31344 | \$ 2,639.00 | 6% | <i>\$2,499.26</i> |
| EWP Premier 4HR AHR H31345 | 98007-H31345 | \$ 2,639.00 | 6% | <i>\$2,499.26</i> |
| EWP Premier 4HR AHR H31346 | 98007-H31346 | \$ 2,639.00 | 6% | <i>\$2,499.26</i> |
| EWP Premier 4HR AHR H31348 | 98007-H31348 | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier 4HR AHR H31349 | 98007-H31349 | \$ 200.00 | 6% | <i>\$189.41</i> |
| EWP Premier 4HR AHR H31350 | 98007-H31350 | \$ 318.00 | 6% | <i>\$301.16</i> |
| EWP Premier 4HR AHR H31351 | 98007-H31351 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H31352 | 98007-H31352 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H31353 | 98007-H31353 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H31354 | 98007-H31354 | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier 4HR AHR H31355 | 98007-H31355 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier 4HR AHR H31356 | 98007-H31356 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier 4HR AHR H31357 | 98007-H31357 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier 4HR AHR H31358 | 98007-H31358 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier 4HR AHR H31359 | 98007-H31359 | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier 4HR AHR H31360 | 98007-H31360 | \$ 69.00 | 6% | <i>\$65.35</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H31361 | 98007-H31361 | \$ 3,505.00 | 6% | <i>\$3,319.41</i> |
| EWP Premier 4HR AHR H31362 | 98007-H31362 | \$ 32,377.00 | 6% | <i>\$30,662.64</i> |
| EWP Premier 4HR AHR H31363 | 98007-H31363 | \$ 32,377.00 | 6% | <i>\$30,662.64</i> |
| EWP Premier 4HR AHR H31364 | 98007-H31364 | \$ 11,315.00 | 6% | <i>\$10,715.87</i> |
| EWP Premier 4HR AHR H31365 | 98007-H31365 | \$ 11,315.00 | 6% | <i>\$10,715.87</i> |
| EWP Premier 4HR AHR H31366 | 98007-H31366 | \$ 15,689.00 | 6% | <i>\$14,858.27</i> |
| EWP Premier 4HR AHR H31367 | 98007-H31367 | \$ 15,689.00 | 6% | <i>\$14,858.27</i> |
| EWP Premier 4HR AHR H31369 | 98007-H31369 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H31370 | 98007-H31370 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR AHR H31393 | 98007-H31393 | \$ 68.00 | 6% | <i>\$64.40</i> |
| EWP Premier 4HR AHR H32010 | 98007-H32010 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWP Premier 4HR AHR H32011 | 98007-H32011 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWP Premier 4HR AHR H32012 | 98007-H32012 | \$ 3,624.00 | 6% | <i>\$3,432.11</i> |
| EWP Premier 4HR AHR H32013 | 98007-H32013 | \$ 3,624.00 | 6% | <i>\$3,432.11</i> |
| EWP Premier 4HR AHR H32014 | 98007-H32014 | \$ 3,624.00 | 6% | <i>\$3,432.11</i> |
| EWP Premier 4HR AHR H32015 | 98007-H32015 | \$ 3,624.00 | 6% | <i>\$3,432.11</i> |
| EWP Premier 4HR AHR H32016 | 98007-H32016 | \$ 3,224.00 | 6% | <i>\$3,053.29</i> |
| EWP Premier 4HR AHR H32017 | 98007-H32017 | \$ 3,224.00 | 6% | <i>\$3,053.29</i> |
| EWP Premier 4HR AHR H32018 | 98007-H32018 | \$ 3,224.00 | 6% | <i>\$3,053.29</i> |
| EWP Premier 4HR AHR H32019 | 98007-H32019 | \$ 3,224.00 | 6% | <i>\$3,053.29</i> |
| EWP Premier 4HR AHR H32020 | 98007-H32020 | \$ 32,258.00 | 6% | <i>\$30,549.94</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H32021 | 98007-H32021 | \$ 32,258.00 | 6% | <i>\$30,549.94</i> |
| EWP Premier 4HR AHR H32022 | 98007-H32022 | \$ 32,258.00 | 6% | <i>\$30,549.94</i> |
| EWP Premier 4HR AHR H32023 | 98007-H32023 | \$ 32,258.00 | 6% | <i>\$30,549.94</i> |
| EWP Premier 4HR AHR H32028 | 98007-H32028 | \$ 62,205.00 | 6% | <i>\$58,911.25</i> |
| EWP Premier 4HR AHR H32029 | 98007-H32029 | \$ 62,205.00 | 6% | <i>\$58,911.25</i> |
| EWP Premier 4HR AHR H32030 | 98007-H32030 | \$ 65,238.00 | 6% | <i>\$61,783.65</i> |
| EWP Premier 4HR AHR H32031 | 98007-H32031 | \$ 65,238.00 | 6% | <i>\$61,783.65</i> |
| EWP Premier 4HR AHR H32032 | 98007-H32032 | \$ 65,238.00 | 6% | <i>\$61,783.65</i> |
| EWP Premier 4HR AHR H32033 | 98007-H32033 | \$ 65,238.00 | 6% | <i>\$61,783.65</i> |
| EWP Premier 4HR AHR H32038 | 98007-H32038 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWP Premier 4HR AHR H32039 | 98007-H32039 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWP Premier 4HR AHR H32040 | 98007-H32040 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWP Premier 4HR AHR H32041 | 98007-H32041 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWP Premier 4HR AHR H32046 | 98007-H32046 | \$ 15,632.00 | 6% | <i>\$14,804.29</i> |
| EWP Premier 4HR AHR H32047 | 98007-H32047 | \$ 15,632.00 | 6% | <i>\$14,804.29</i> |
| EWP Premier 4HR AHR H32048 | 98007-H32048 | \$ 15,632.00 | 6% | <i>\$14,804.29</i> |
| EWP Premier 4HR AHR H32049 | 98007-H32049 | \$ 15,632.00 | 6% | <i>\$14,804.29</i> |
| EWP Premier 4HR AHR H32054 | 98007-H32054 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWP Premier 4HR AHR H32055 | 98007-H32055 | \$ 15,632.00 | 6% | <i>\$14,804.29</i> |
| EWP Premier 4HR AHR H32056 | 98007-H32056 | \$ 4,209.00 | 6% | <i>\$3,986.13</i> |
| EWP Premier 4HR AHR H32057 | 98007-H32057 | \$ 4,209.00 | 6% | <i>\$3,986.13</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H32058 | 98007-H32058 | \$ 4,209.00 | 6% | <i>\$3,986.13</i> |
| EWP Premier 4HR AHR H32059 | 98007-H32059 | \$ 4,209.00 | 6% | <i>\$3,986.13</i> |
| EWP Premier 4HR AHR H32060 | 98007-H32060 | \$ 4,323.00 | 6% | <i>\$4,094.10</i> |
| EWP Premier 4HR AHR H32061 | 98007-H32061 | \$ 4,539.00 | 6% | <i>\$4,298.66</i> |
| EWP Premier 4HR AHR H32062 | 98007-H32062 | \$ 4,323.00 | 6% | <i>\$4,094.10</i> |
| EWP Premier 4HR AHR H32063 | 98007-H32063 | \$ 4,328.00 | 6% | <i>\$4,098.83</i> |
| EWP Premier 4HR AHR H32064 | 98007-H32064 | \$ 4,323.00 | 6% | <i>\$4,094.10</i> |
| EWP Premier 4HR AHR H32065 | 98007-H32065 | \$ 4,931.00 | 6% | <i>\$4,669.90</i> |
| EWP Premier 4HR AHR H32066 | 98007-H32066 | \$ 4,931.00 | 6% | <i>\$4,669.90</i> |
| EWP Premier 4HR AHR H32067 | 98007-H32067 | \$ 4,931.00 | 6% | <i>\$4,669.90</i> |
| EWP Premier 4HR AHR H32068 | 98007-H32068 | \$ 4,931.00 | 6% | <i>\$4,669.90</i> |
| EWP Premier 4HR AHR H32069 | 98007-H32069 | \$ 6,128.00 | 6% | <i>\$5,803.52</i> |
| EWP Premier 4HR AHR H32070 | 98007-H32070 | \$ 6,128.00 | 6% | <i>\$5,803.52</i> |
| EWP Premier 4HR AHR H32071 | 98007-H32071 | \$ 6,128.00 | 6% | <i>\$5,803.52</i> |
| EWP Premier 4HR AHR H32072 | 98007-H32072 | \$ 6,128.00 | 6% | <i>\$5,803.52</i> |
| EWP Premier 4HR AHR H32073 | 98007-H32073 | \$ 45,386.00 | 6% | <i>\$42,982.81</i> |
| EWP Premier 4HR AHR H32074 | 98007-H32074 | \$ 45,386.00 | 6% | <i>\$42,982.81</i> |
| EWP Premier 4HR AHR H32075 | 98007-H32075 | \$ 61,673.00 | 6% | <i>\$58,407.41</i> |
| EWP Premier 4HR AHR H32076 | 98007-H32076 | \$ 61,086.00 | 6% | <i>\$57,851.50</i> |
| EWP Premier 4HR AHR H32101 | 98007-H32101 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWP Premier 4HR AHR H32102 | 98007-H32102 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H32103 | 98007-H32103 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWP Premier 4HR AHR H32104 | 98007-H32104 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWP Premier 4HR AHR H32105 | 98007-H32105 | \$ 4,045.00 | 6% | <i>\$3,830.82</i> |
| EWP Premier 4HR AHR H32106 | 98007-H32106 | \$ 4,045.00 | 6% | <i>\$3,830.82</i> |
| EWP Premier 4HR AHR H32107 | 98007-H32107 | \$ 10,929.00 | 6% | <i>\$10,350.31</i> |
| EWP Premier 4HR AHR H32108 | 98007-H32108 | \$ 10,929.00 | 6% | <i>\$10,350.31</i> |
| EWP Premier 4HR AHR H32109 | 98007-H32109 | \$ 4,045.00 | 6% | <i>\$3,830.82</i> |
| EWP Premier 4HR AHR H32110 | 98007-H32110 | \$ 4,045.00 | 6% | <i>\$3,830.82</i> |
| EWP Premier 4HR AHR H32111 | 98007-H32111 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWP Premier 4HR AHR H32112 | 98007-H32112 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWP Premier 4HR AHR H32113 | 98007-H32113 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWP Premier 4HR AHR H32114 | 98007-H32114 | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWP Premier 4HR AHR H32115 | 98007-H32115 | \$ 4,045.00 | 6% | <i>\$3,830.82</i> |
| EWP Premier 4HR AHR H32116 | 98007-H32116 | \$ 4,045.00 | 6% | <i>\$3,830.82</i> |
| EWP Premier 4HR AHR H32117 | 98007-H32117 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWP Premier 4HR AHR H32118 | 98007-H32118 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWP Premier 4HR AHR H32119 | 98007-H32119 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWP Premier 4HR AHR H32120 | 98007-H32120 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWP Premier 4HR AHR H32121 | 98007-H32121 | \$ 10,929.00 | 6% | <i>\$10,350.31</i> |
| EWP Premier 4HR AHR H32122 | 98007-H32122 | \$ 10,929.00 | 6% | <i>\$10,350.31</i> |
| EWP Premier 4HR AHR H32123 | 98007-H32123 | \$ 4,045.00 | 6% | <i>\$3,830.82</i> |

| | | | | |
|----------------------------|--------------|--------------|----|-------------|
| EWP Premier 4HR AHR H32124 | 98007-H32124 | \$ 4,045.00 | 6% | \$3,830.82 |
| EWP Premier 4HR AHR H32125 | 98007-H32125 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32126 | 98007-H32126 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32127 | 98007-H32127 | \$ 4,697.00 | 6% | \$4,448.29 |
| EWP Premier 4HR AHR H32128 | 98007-H32128 | \$ 4,697.00 | 6% | \$4,448.29 |
| EWP Premier 4HR AHR H32129 | 98007-H32129 | \$ 4,697.00 | 6% | \$4,448.29 |
| EWP Premier 4HR AHR H32130 | 98007-H32130 | \$ 4,697.00 | 6% | \$4,448.29 |
| EWP Premier 4HR AHR H32131 | 98007-H32131 | \$ 4,697.00 | 6% | \$4,448.29 |
| EWP Premier 4HR AHR H32132 | 98007-H32132 | \$ 4,697.00 | 6% | \$4,448.29 |
| EWP Premier 4HR AHR H32133 | 98007-H32133 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32134 | 98007-H32134 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32135 | 98007-H32135 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32136 | 98007-H32136 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32137 | 98007-H32137 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32138 | 98007-H32138 | \$ 3,990.00 | 6% | \$3,778.73 |
| EWP Premier 4HR AHR H32139 | 98007-H32139 | \$ 16,887.00 | 6% | \$15,992.83 |
| EWP Premier 4HR AHR H32140 | 98007-H32140 | \$ 16,887.00 | 6% | \$15,992.83 |
| EWP Premier 4HR AHR H32141 | 98007-H32141 | \$ 19,491.00 | 6% | \$18,458.95 |
| EWP Premier 4HR AHR H32142 | 98007-H32142 | \$ 19,491.00 | 6% | \$18,458.95 |
| EWP Premier 4HR AHR H32146 | 98007-H32146 | \$ 1,913.00 | 6% | \$1,811.71 |
| EWP Premier 4HR AHR H32147 | 98007-H32147 | \$ 1,913.00 | 6% | \$1,811.71 |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H32148 | 98007-H32148 | \$ 3,832.00 | 6% | <i>\$3,629.10</i> |
| EWP Premier 4HR AHR H32149 | 98007-H32149 | \$ 3,832.00 | 6% | <i>\$3,629.10</i> |
| EWP Premier 4HR AHR H32150 | 98007-H32150 | \$ 1,913.00 | 6% | <i>\$1,811.71</i> |
| EWP Premier 4HR AHR H32152 | 98007-H32152 | \$ 827.00 | 6% | <i>\$783.21</i> |
| EWP Premier 4HR AHR H32169 | 98007-H32169 | \$ 2,004.00 | 6% | <i>\$1,897.89</i> |
| EWP Premier 4HR AHR H32170 | 98007-H32170 | \$ 2,004.00 | 6% | <i>\$1,897.89</i> |
| EWP Premier 4HR AHR H32171 | 98007-H32171 | \$ 1,887.00 | 6% | <i>\$1,787.08</i> |
| EWP Premier 4HR AHR H32172 | 98007-H32172 | \$ 1,887.00 | 6% | <i>\$1,787.08</i> |
| EWP Premier 4HR AHR H32173 | 98007-H32173 | \$ 5,013.00 | 6% | <i>\$4,747.56</i> |
| EWP Premier 4HR AHR H32174 | 98007-H32174 | \$ 5,013.00 | 6% | <i>\$4,747.56</i> |
| EWP Premier 4HR AHR H32175 | 98007-H32175 | \$ 4,257.00 | 6% | <i>\$4,031.59</i> |
| EWP Premier 4HR AHR H32176 | 98007-H32176 | \$ 4,257.00 | 6% | <i>\$4,031.59</i> |
| EWP Premier 4HR AHR H32177 | 98007-H32177 | \$ 19,533.00 | 6% | <i>\$18,498.73</i> |
| EWP Premier 4HR AHR H32178 | 98007-H32178 | \$ 22,541.00 | 6% | <i>\$21,347.45</i> |
| EWP Premier 4HR AHR H34008 | 98007-H34008 | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier 4HR AHR H34009 | 98007-H34009 | \$ 199.00 | 6% | <i>\$188.46</i> |
| EWP Premier 4HR AHR H34010 | 98007-H34010 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR AHR H34011 | 98007-H34011 | \$ 178.00 | 6% | <i>\$168.57</i> |
| EWP Premier 4HR AHR H34012 | 98007-H34012 | \$ 319.00 | 6% | <i>\$302.11</i> |
| EWP Premier 4HR AHR H34013 | 98007-H34013 | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier 4HR AHR H34014 | 98007-H34014 | \$ 199.00 | 6% | <i>\$188.46</i> |

| | | | | |
|----------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR AHR H34015 | 98007-H34015 | \$ 101.00 | 6% | <i>\$95.65</i> |
| EWP Premier 4HR AHR H34016 | 98007-H34016 | \$ 226.00 | 6% | <i>\$214.03</i> |
| EWP Premier 4HR AHR H34017 | 98007-H34017 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWP Premier 4HR AHR H34018 | 98007-H34018 | \$ 135.00 | 6% | <i>\$127.85</i> |
| EWP Premier 4HR AHR H34019 | 98007-H34019 | \$ 135.00 | 6% | <i>\$127.85</i> |
| EWP Premier 4HR AHR H34020 | 98007-H34020 | \$ 135.00 | 6% | <i>\$127.85</i> |
| EWP Premier 4HR AHR H34021 | 98007-H34021 | \$ 135.00 | 6% | <i>\$127.85</i> |
| EWP Premier 4HR AHR H34048 | 98007-H34048 | \$ 620.00 | 6% | <i>\$587.17</i> |
| EWP Premier 4HR AHR H34049 | 98007-H34049 | \$ 620.00 | 6% | <i>\$587.17</i> |
| EWP Premier 4HR AHR H34050 | 98007-H34050 | \$ 449.00 | 6% | <i>\$425.23</i> |
| EWP Premier 4HR AHR H34051 | 98007-H34051 | \$ 449.00 | 6% | <i>\$425.23</i> |
| EWP Premier 4HR AHR H34052 | 98007-H34052 | \$ 721.00 | 6% | <i>\$682.82</i> |
| EWP Premier 4HR AHR H34053 | 98007-H34053 | \$ 721.00 | 6% | <i>\$682.82</i> |
| EWP Premier 4HR AHR H34054 | 98007-H34054 | \$ 541.00 | 6% | <i>\$512.35</i> |
| EWP Premier 4HR AHR H34055 | 98007-H34055 | \$ 541.00 | 6% | <i>\$512.35</i> |
| EWP Premier 4HR AHR H34056 | 98007-H34056 | \$ 786.00 | 6% | <i>\$744.38</i> |
| EWP Premier 4HR AHR H34057 | 98007-H34057 | \$ 786.00 | 6% | <i>\$744.38</i> |
| EWP Premier 4HR AHR H34058 | 98007-H34058 | \$ 676.00 | 6% | <i>\$640.21</i> |
| EWP Premier 4HR AHR H34059 | 98007-H34059 | \$ 676.00 | 6% | <i>\$640.21</i> |
| EWP Premier 4HR AHR H34062 | 98007-H34062 | \$ 786.00 | 6% | <i>\$744.38</i> |
| EWP Premier 4HR AHR H34063 | 98007-H34063 | \$ 786.00 | 6% | <i>\$744.38</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H34064 | 98007-H34064 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H34065 | 98007-H34065 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H34066 | 98007-H34066 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H34067 | 98007-H34067 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H34068 | 98007-H34068 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H34069 | 98007-H34069 | \$ 501.00 | 6% | <i>\$474.47</i> |
| EWP Premier 4HR AHR H34070 | 98007-H34070 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H34071 | 98007-H34071 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWP Premier 4HR AHR H34072 | 98007-H34072 | \$ 4,435.00 | 6% | <i>\$4,200.17</i> |
| EWP Premier 4HR AHR H34073 | 98007-H34073 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR AHR H34074 | 98007-H34074 | \$ 5,565.00 | 6% | <i>\$5,270.33</i> |
| EWP Premier 4HR AHR H34075 | 98007-H34075 | \$ 5,332.00 | 6% | <i>\$5,049.67</i> |
| EWP Premier 4HR AHR H34076 | 98007-H34076 | \$ 4,435.00 | 6% | <i>\$4,200.17</i> |
| EWP Premier 4HR AHR H34077 | 98007-H34077 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR AHR H34078 | 98007-H34078 | \$ 4,435.00 | 6% | <i>\$4,200.17</i> |
| EWP Premier 4HR AHR H34079 | 98007-H34079 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR AHR H34080 | 98007-H34080 | \$ 5,565.00 | 6% | <i>\$5,270.33</i> |
| EWP Premier 4HR AHR H34081 | 98007-H34081 | \$ 5,332.00 | 6% | <i>\$5,049.67</i> |
| EWP Premier 4HR AHR H34082 | 98007-H34082 | \$ 5,312.00 | 6% | <i>\$5,030.73</i> |
| EWP Premier 4HR AHR H34083 | 98007-H34083 | \$ 5,089.00 | 6% | <i>\$4,819.54</i> |
| EWP Premier 4HR AHR H34084 | 98007-H34084 | \$ 3,557.00 | 6% | <i>\$3,368.66</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H34085 | 98007-H34085 | \$ 3,557.00 | 6% | <i>\$3,368.66</i> |
| EWP Premier 4HR AHR H34086 | 98007-H34086 | \$ 4,161.00 | 6% | <i>\$3,940.68</i> |
| EWP Premier 4HR AHR H34087 | 98007-H34087 | \$ 3,972.00 | 6% | <i>\$3,761.68</i> |
| EWP Premier 4HR AHR H34088 | 98007-H34088 | \$ 9,522.00 | 6% | <i>\$9,017.81</i> |
| EWP Premier 4HR AHR H34089 | 98007-H34089 | \$ 9,522.00 | 6% | <i>\$9,017.81</i> |
| EWP Premier 4HR AHR H34090 | 98007-H34090 | \$ 10,965.00 | 6% | <i>\$10,384.40</i> |
| EWP Premier 4HR AHR H34091 | 98007-H34091 | \$ 7,588.00 | 6% | <i>\$7,186.22</i> |
| EWP Premier 4HR AHR H34092 | 98007-H34092 | \$ 7,588.00 | 6% | <i>\$7,186.22</i> |
| EWP Premier 4HR AHR H34093 | 98007-H34093 | \$ 7,588.00 | 6% | <i>\$7,186.22</i> |
| EWP Premier 4HR AHR H34094 | 98007-H34094 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34095 | 98007-H34095 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34096 | 98007-H34096 | \$ 989.00 | 6% | <i>\$936.63</i> |
| EWP Premier 4HR AHR H34097 | 98007-H34097 | \$ 989.00 | 6% | <i>\$936.63</i> |
| EWP Premier 4HR AHR H34098 | 98007-H34098 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34099 | 98007-H34099 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34100 | 98007-H34100 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34101 | 98007-H34101 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34102 | 98007-H34102 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34103 | 98007-H34103 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWP Premier 4HR AHR H34104 | 98007-H34104 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier 4HR AHR H34105 | 98007-H34105 | \$ 381.00 | 6% | <i>\$360.83</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H34106 | 98007-H34106 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier 4HR AHR H34107 | 98007-H34107 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier 4HR AHR H34108 | 98007-H34108 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier 4HR AHR H34109 | 98007-H34109 | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier 4HR AHR H34110 | 98007-H34110 | \$ 7,274.00 | 6% | <i>\$6,888.84</i> |
| EWP Premier 4HR AHR H34111 | 98007-H34111 | \$ 7,274.00 | 6% | <i>\$6,888.84</i> |
| EWP Premier 4HR AHR H34112 | 98007-H34112 | \$ 7,274.00 | 6% | <i>\$6,888.84</i> |
| EWP Premier 4HR AHR H34114 | 98007-H34114 | \$ 9,551.00 | 6% | <i>\$9,045.27</i> |
| EWP Premier 4HR AHR H34115 | 98007-H34115 | \$ 9,551.00 | 6% | <i>\$9,045.27</i> |
| EWP Premier 4HR AHR H34116 | 98007-H34116 | \$ 9,551.00 | 6% | <i>\$9,045.27</i> |
| EWP Premier 4HR AHR H34117 | 98007-H34117 | \$ 9,551.00 | 6% | <i>\$9,045.27</i> |
| EWP Premier 4HR AHR H34118 | 98007-H34118 | \$ 2,408.00 | 6% | <i>\$2,280.50</i> |
| EWP Premier 4HR AHR H34119 | 98007-H34119 | \$ 2,408.00 | 6% | <i>\$2,280.50</i> |
| EWP Premier 4HR AHR H34120 | 98007-H34120 | \$ 1,665.00 | 6% | <i>\$1,576.84</i> |
| EWP Premier 4HR AHR H34121 | 98007-H34121 | \$ 1,665.00 | 6% | <i>\$1,576.84</i> |
| EWP Premier 4HR AHR H34122 | 98007-H34122 | \$ 1,736.00 | 6% | <i>\$1,644.08</i> |
| EWP Premier 4HR AHR H34123 | 98007-H34123 | \$ 1,736.00 | 6% | <i>\$1,644.08</i> |
| EWP Premier 4HR AHR H34124 | 98007-H34124 | \$ 2,580.00 | 6% | <i>\$2,443.39</i> |
| EWP Premier 4HR AHR H34125 | 98007-H34125 | \$ 2,580.00 | 6% | <i>\$2,443.39</i> |
| EWP Premier 4HR AHR H34126 | 98007-H34126 | \$ 2,580.00 | 6% | <i>\$2,443.39</i> |
| EWP Premier 4HR AHR H34127 | 98007-H34127 | \$ 2,580.00 | 6% | <i>\$2,443.39</i> |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR AHR H34128 | 98007-H34128 | \$ 316.00 | 6% | \$299.27 |
| EWP Premier 4HR AHR H34129 | 98007-H34129 | \$ 675.00 | 6% | \$639.26 |
| EWP Premier 4HR AHR H34130 | 98007-H34130 | \$ 700.00 | 6% | \$662.94 |
| EWP Premier 4HR AHR H34131 | 98007-H34131 | \$ 700.00 | 6% | \$662.94 |
| EWP Premier 4HR AHR H34132 | 98007-H34132 | \$ 700.00 | 6% | \$662.94 |
| EWP Premier 4HR AHR H34172 | 98007-H34172 | \$ 2,104.00 | 6% | \$1,992.59 |
| EWP Premier 4HR AHR H34726 | 98007-H34726 | \$ 4,610.00 | 6% | \$4,365.90 |
| EWP Premier 4HR AHR H34727 | 98007-H34727 | \$ 4,610.00 | 6% | \$4,365.90 |
| EWP Premier 4HR AHR H34728 | 98007-H34728 | \$ 4,610.00 | 6% | \$4,365.90 |
| EWP Premier 4HR AHR H34729 | 98007-H34729 | \$ 4,610.00 | 6% | \$4,365.90 |
| EWP Premier 4HR AHR H34730 | 98007-H34730 | \$ 4,940.00 | 6% | \$4,678.43 |
| EWP Premier 4HR AHR H34731 | 98007-H34731 | \$ 4,940.00 | 6% | \$4,678.43 |
| EWP Premier 4HR AHR H34732 | 98007-H34732 | \$ 4,940.00 | 6% | \$4,678.43 |
| EWP Premier 4HR AHR H34733 | 98007-H34733 | \$ 4,940.00 | 6% | \$4,678.43 |
| EWP Premier 4HR AHR H34734 | 98007-H34734 | \$ 718.00 | 6% | \$679.98 |
| EWP Premier 4HR AHR H34735 | 98007-H34735 | \$ 718.00 | 6% | \$679.98 |
| EWP Premier 4HR AHR H34736 | 98007-H34736 | \$ 912.00 | 6% | \$863.71 |
| EWP Premier 4HR AHR H34737 | 98007-H34737 | \$ 912.00 | 6% | \$863.71 |
| EWP Premier 4HR AHR H34738 | 98007-H34738 | \$ 1,728.00 | 6% | \$1,636.50 |
| EWP Premier 4HR AHR H34739 | 98007-H34739 | \$ 1,728.00 | 6% | \$1,636.50 |
| EWP Premier 4HR AHR H34740 | 98007-H34740 | \$ 718.00 | 6% | \$679.98 |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H34741 | 98007-H34741 | \$ 718.00 | 6% | <i>\$679.98</i> |
| EWP Premier 4HR AHR H34742 | 98007-H34742 | \$ 556.00 | 6% | <i>\$526.56</i> |
| EWP Premier 4HR AHR H34743 | 98007-H34743 | \$ 556.00 | 6% | <i>\$526.56</i> |
| EWP Premier 4HR AHR H34744 | 98007-H34744 | \$ 912.00 | 6% | <i>\$863.71</i> |
| EWP Premier 4HR AHR H34745 | 98007-H34745 | \$ 912.00 | 6% | <i>\$863.71</i> |
| EWP Premier 4HR AHR H34746 | 98007-H34746 | \$ 1,028.00 | 6% | <i>\$973.57</i> |
| EWP Premier 4HR AHR H34747 | 98007-H34747 | \$ 1,028.00 | 6% | <i>\$973.57</i> |
| EWP Premier 4HR AHR H34748 | 98007-H34748 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34749 | 98007-H34749 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34750 | 98007-H34750 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34751 | 98007-H34751 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34752 | 98007-H34752 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34753 | 98007-H34753 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34754 | 98007-H34754 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34755 | 98007-H34755 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWP Premier 4HR AHR H34756 | 98007-H34756 | \$ 912.00 | 6% | <i>\$863.71</i> |
| EWP Premier 4HR AHR H34757 | 98007-H34757 | \$ 912.00 | 6% | <i>\$863.71</i> |
| EWP Premier 4HR AHR H34758 | 98007-H34758 | \$ 912.00 | 6% | <i>\$863.71</i> |
| EWP Premier 4HR AHR H34759 | 98007-H34759 | \$ 912.00 | 6% | <i>\$863.71</i> |
| EWP Premier 4HR AHR H34760 | 98007-H34760 | \$ 912.00 | 6% | <i>\$863.71</i> |
| EWP Premier 4HR AHR H34761 | 98007-H34761 | \$ 912.00 | 6% | <i>\$863.71</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H34839 | 98007-H34839 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34840 | 98007-H34840 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34841 | 98007-H34841 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34842 | 98007-H34842 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34843 | 98007-H34843 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34844 | 98007-H34844 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34845 | 98007-H34845 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34846 | 98007-H34846 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR AHR H34993 | 98007-H34993 | \$ 18,988.00 | 6% | <i>\$17,982.59</i> |
| EWP Premier 4HR AHR H34994 | 98007-H34994 | \$ 18,988.00 | 6% | <i>\$17,982.59</i> |
| EWP Premier 4HR AHR H34996 | 98007-H34996 | \$ 18,988.00 | 6% | <i>\$17,982.59</i> |
| EWP Premier 4HR AHR H34997 | 98007-H34997 | \$ 18,988.00 | 6% | <i>\$17,982.59</i> |
| EWP Premier 4HR AHR H35005 | 98007-H35005 | \$ 13,858.00 | 6% | <i>\$13,124.22</i> |
| EWP Premier 4HR AHR H35006 | 98007-H35006 | \$ 13,858.00 | 6% | <i>\$13,124.22</i> |
| EWP Premier 4HR AHR H35012 | 98007-H35012 | \$ 8,329.00 | 6% | <i>\$7,887.98</i> |
| EWP Premier 4HR AHR H35262 | 98007-H35262 | \$ 3,128.00 | 6% | <i>\$2,962.37</i> |
| EWP Premier 4HR AHR H35270 | 98007-H35270 | \$ 721.00 | 6% | <i>\$682.82</i> |
| EWP Premier 4HR AHR H35271 | 98007-H35271 | \$ 541.00 | 6% | <i>\$512.35</i> |
| EWP Premier 4HR AHR H35273 | 98007-H35273 | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWP Premier 4HR AHR H35274 | 98007-H35274 | \$ 1,028.00 | 6% | <i>\$973.57</i> |
| EWP Premier 4HR AHR H35275 | 98007-H35275 | \$ 786.00 | 6% | <i>\$744.38</i> |

| | | | | |
|----------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR AHR H35276 | 98007-H35276 | \$ 4,435.00 | 6% | <i>\$4,200.17</i> |
| EWP Premier 4HR AHR H35277 | 98007-H35277 | \$ 5,312.00 | 6% | <i>\$5,030.73</i> |
| EWP Premier 4HR AHR H35278 | 98007-H35278 | \$ 3,557.00 | 6% | <i>\$3,368.66</i> |
| EWP Premier 4HR AHR H35279 | 98007-H35279 | \$ 3,972.00 | 6% | <i>\$3,761.68</i> |
| EWP Premier 4HR AHR H35280 | 98007-H35280 | \$ 7,136.00 | 6% | <i>\$6,758.15</i> |
| EWP Premier 4HR AHR H35281 | 98007-H35281 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35282 | 98007-H35282 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35283 | 98007-H35283 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35284 | 98007-H35284 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35285 | 98007-H35285 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35286 | 98007-H35286 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35287 | 98007-H35287 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35288 | 98007-H35288 | \$ 2,621.00 | 6% | <i>\$2,482.22</i> |
| EWP Premier 4HR AHR H35289 | 98007-H35289 | \$ 6,916.00 | 6% | <i>\$6,549.80</i> |
| EWP Premier 4HR AHR H35291 | 98007-H35291 | \$ 4,978.00 | 6% | <i>\$4,714.41</i> |
| EWP Premier 4HR AHR H35294 | 98007-H35294 | \$ 1,633.00 | 6% | <i>\$1,546.53</i> |
| EWP Premier 4HR AHR H35295 | 98007-H35295 | \$ 642.00 | 6% | <i>\$608.01</i> |
| EWP Premier 4HR AHR H35296 | 98007-H35296 | \$ 9,653.00 | 6% | <i>\$9,141.87</i> |
| EWP Premier 4HR AHR H35297 | 98007-H35297 | \$ 9,653.00 | 6% | <i>\$9,141.87</i> |
| EWP Premier 4HR AHR H35298 | 98007-H35298 | \$ 15,505.00 | 6% | <i>\$14,684.01</i> |
| EWP Premier 4HR AHR H35299 | 98007-H35299 | \$ 15,505.00 | 6% | <i>\$14,684.01</i> |

| | | | | |
|----------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR AHR H35302 | 98007-H35302 | \$ 3,773.00 | 6% | \$3,573.22 |
| EWP Premier 4HR AHR H35303 | 98007-H35303 | \$ 3,773.00 | 6% | \$3,573.22 |
| EWP Premier 4HR AHR H35304 | 98007-H35304 | \$ 3,773.00 | 6% | \$3,573.22 |
| EWP Premier 4HR AHR H35305 | 98007-H35305 | \$ 3,962.00 | 6% | \$3,752.21 |
| EWP Premier 4HR AHR H35306 | 98007-H35306 | \$ 3,962.00 | 6% | \$3,752.21 |
| EWP Premier 4HR AHR H35307 | 98007-H35307 | \$ 3,962.00 | 6% | \$3,752.21 |
| EWP Premier 4HR AHR H35309 | 98007-H35309 | \$ 4,812.00 | 6% | \$4,557.20 |
| EWP Premier 4HR AHR H35310 | 98007-H35310 | \$ 4,812.00 | 6% | \$4,557.20 |
| EWP Premier 4HR AHR H35311 | 98007-H35311 | \$ 4,812.00 | 6% | \$4,557.20 |
| EWP Premier 4HR AHR H35312 | 98007-H35312 | \$ 3,976.00 | 6% | \$3,765.47 |
| EWP Premier 4HR AHR H35313 | 98007-H35313 | \$ 3,976.00 | 6% | \$3,765.47 |
| EWP Premier 4HR AHR H35314 | 98007-H35314 | \$ 3,976.00 | 6% | \$3,765.47 |
| EWP Premier 4HR AHR H35315 | 98007-H35315 | \$ 1,780.00 | 6% | \$1,685.75 |
| EWP Premier 4HR AHR H35318 | 98007-H35318 | \$ 855.00 | 6% | \$809.73 |
| EWP Premier 4HR AHR H35319 | 98007-H35319 | \$ 1,134.00 | 6% | \$1,073.95 |
| EWP Premier 4HR AHR H35320 | 98007-H35320 | \$ 1,174.00 | 6% | \$1,111.84 |
| EWP Premier 4HR AHR H35321 | 98007-H35321 | \$ 1,498.00 | 6% | \$1,418.68 |
| EWP Premier 4HR AHR H35322 | 98007-H35322 | \$ 1,815.00 | 6% | \$1,718.90 |
| EWP Premier 4HR AHR H35323 | 98007-H35323 | \$ 1,780.00 | 6% | \$1,685.75 |
| EWP Premier 4HR AHR H35328 | 98007-H35328 | \$ 151.00 | 6% | \$143.00 |
| EWP Premier 4HR AHR H35330 | 98007-H35330 | \$ 122.00 | 6% | \$115.54 |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H35340 | 98007-H35340 | \$ 3,816.00 | 6% | <i>\$3,613.94</i> |
| EWP Premier 4HR AHR H35341 | 98007-H35341 | \$ 3,817.00 | 6% | <i>\$3,614.89</i> |
| EWP Premier 4HR AHR H35342 | 98007-H35342 | \$ 3,455.00 | 6% | <i>\$3,272.06</i> |
| EWP Premier 4HR AHR H35343 | 98007-H35343 | \$ 3,817.00 | 6% | <i>\$3,614.89</i> |
| EWP Premier 4HR AHR H35344 | 98007-H35344 | \$ 4,218.00 | 6% | <i>\$3,994.66</i> |
| EWP Premier 4HR AHR H35345 | 98007-H35345 | \$ 4,218.00 | 6% | <i>\$3,994.66</i> |
| EWP Premier 4HR AHR H35346 | 98007-H35346 | \$ 3,554.00 | 6% | <i>\$3,365.82</i> |
| EWP Premier 4HR AHR H35347 | 98007-H35347 | \$ 4,218.00 | 6% | <i>\$3,994.66</i> |
| EWP Premier 4HR AHR H35349 | 98007-H35349 | \$ 4,393.00 | 6% | <i>\$4,160.39</i> |
| EWP Premier 4HR AHR H35350 | 98007-H35350 | \$ 4,393.00 | 6% | <i>\$4,160.39</i> |
| EWP Premier 4HR AHR H35351 | 98007-H35351 | \$ 3,824.00 | 6% | <i>\$3,621.52</i> |
| EWP Premier 4HR AHR H35352 | 98007-H35352 | \$ 4,393.00 | 6% | <i>\$4,160.39</i> |
| EWP Premier 4HR AHR H35359 | 98007-H35359 | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| EWP Premier 4HR AHR H35360 | 98007-H35360 | \$ 1,815.00 | 6% | <i>\$1,718.90</i> |
| EWP Premier 4HR AHR H35361 | 98007-H35361 | \$ 1,780.00 | 6% | <i>\$1,685.75</i> |
| EWP Premier 4HR AHR H35362 | 98007-H35362 | \$ 855.00 | 6% | <i>\$809.73</i> |
| EWP Premier 4HR AHR H35366 | 98007-H35366 | \$ 1,297.00 | 6% | <i>\$1,228.32</i> |
| EWP Premier 4HR AHR H35367 | 98007-H35367 | \$ 1,513.00 | 6% | <i>\$1,432.89</i> |
| EWP Premier 4HR AHR H35368 | 98007-H35368 | \$ 3,418.00 | 6% | <i>\$3,237.02</i> |
| EWP Premier 4HR AHR H35369 | 98007-H35369 | \$ 1,117.00 | 6% | <i>\$1,057.85</i> |
| EWP Premier 4HR AHR H35370 | 98007-H35370 | \$ 1,053.00 | 6% | <i>\$997.24</i> |

| | | | | |
|----------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR AHR H35375 | 98007-H35375 | \$ 636.00 | 6% | <i>\$602.32</i> |
| EWP Premier 4HR AHR H35376 | 98007-H35376 | \$ 953.00 | 6% | <i>\$902.54</i> |
| EWP Premier 4HR AHR H35377 | 98007-H35377 | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWP Premier 4HR AHR H35378 | 98007-H35378 | \$ 636.00 | 6% | <i>\$602.32</i> |
| EWP Premier 4HR AHR H35379 | 98007-H35379 | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWP Premier 4HR AHR H35380 | 98007-H35380 | \$ 720.00 | 6% | <i>\$681.88</i> |
| EWP Premier 4HR AHR H35381 | 98007-H35381 | \$ 876.00 | 6% | <i>\$829.62</i> |
| EWP Premier 4HR AHR H35384 | 98007-H35384 | \$ 291.00 | 6% | <i>\$275.59</i> |
| EWP Premier 4HR AHR H35385 | 98007-H35385 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWP Premier 4HR AHR H35386 | 98007-H35386 | \$ 636.00 | 6% | <i>\$602.32</i> |
| EWP Premier 4HR AHR H35387 | 98007-H35387 | \$ 594.00 | 6% | <i>\$562.55</i> |
| EWP Premier 4HR AHR H35388 | 98007-H35388 | \$ 441.00 | 6% | <i>\$417.65</i> |
| EWP Premier 4HR AHR H35389 | 98007-H35389 | \$ 249.00 | 6% | <i>\$235.82</i> |
| EWP Premier 4HR AHR H35390 | 98007-H35390 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier 4HR AHR H35391 | 98007-H35391 | \$ 473.00 | 6% | <i>\$447.95</i> |
| EWP Premier 4HR AHR H35392 | 98007-H35392 | \$ 720.00 | 6% | <i>\$681.88</i> |
| EWP Premier 4HR AHR H35393 | 98007-H35393 | \$ 953.00 | 6% | <i>\$902.54</i> |
| EWP Premier 4HR AHR H35394 | 98007-H35394 | \$ 175.00 | 6% | <i>\$165.73</i> |
| EWP Premier 4HR AHR H35395 | 98007-H35395 | \$ 150.00 | 6% | <i>\$142.06</i> |
| EWP Premier 4HR AHR H35396 | 98007-H35396 | \$ 175.00 | 6% | <i>\$165.73</i> |
| EWP Premier 4HR AHR H35397 | 98007-H35397 | \$ 150.00 | 6% | <i>\$142.06</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H35398 | 98007-H35398 | \$ 446.00 | 6% | <i>\$422.38</i> |
| EWP Premier 4HR AHR H35399 | 98007-H35399 | \$ 545.00 | 6% | <i>\$516.14</i> |
| EWP Premier 4HR AHR H35400 | 98007-H35400 | \$ 596.00 | 6% | <i>\$564.44</i> |
| EWP Premier 4HR AHR H35401 | 98007-H35401 | \$ 317.00 | 6% | <i>\$300.21</i> |
| EWP Premier 4HR AHR H35415 | 98007-H35415 | \$ 220.00 | 6% | <i>\$208.35</i> |
| EWP Premier 4HR AHR H35416 | 98007-H35416 | \$ 220.00 | 6% | <i>\$208.35</i> |
| EWP Premier 4HR AHR H35426 | 98007-H35426 | \$ 249.00 | 6% | <i>\$235.82</i> |
| EWP Premier 4HR AHR H35427 | 98007-H35427 | \$ 594.00 | 6% | <i>\$562.55</i> |
| EWP Premier 4HR AHR H35428 | 98007-H35428 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier 4HR AHR H35429 | 98007-H35429 | \$ 473.00 | 6% | <i>\$447.95</i> |
| EWP Premier 4HR AHR H35430 | 98007-H35430 | \$ 684.00 | 6% | <i>\$647.78</i> |
| EWP Premier 4HR AHR H35431 | 98007-H35431 | \$ 684.00 | 6% | <i>\$647.78</i> |
| EWP Premier 4HR AHR H35432 | 98007-H35432 | \$ 556.00 | 6% | <i>\$526.56</i> |
| EWP Premier 4HR AHR H35433 | 98007-H35433 | \$ 869.00 | 6% | <i>\$822.99</i> |
| EWP Premier 4HR AHR H35434 | 98007-H35434 | \$ 979.00 | 6% | <i>\$927.16</i> |
| EWP Premier 4HR AHR H35435 | 98007-H35435 | \$ 979.00 | 6% | <i>\$927.16</i> |
| EWP Premier 4HR AHR H35436 | 98007-H35436 | \$ 1,646.00 | 6% | <i>\$1,558.84</i> |
| EWP Premier 4HR AHR H35437 | 98007-H35437 | \$ 1,646.00 | 6% | <i>\$1,558.84</i> |
| EWP Premier 4HR AHR H35438 | 98007-H35438 | \$ 1,646.00 | 6% | <i>\$1,558.84</i> |
| EWP Premier 4HR AHR H35439 | 98007-H35439 | \$ 1,646.00 | 6% | <i>\$1,558.84</i> |
| EWP Premier 4HR AHR H35440 | 98007-H35440 | \$ 869.00 | 6% | <i>\$822.99</i> |

| | | | | |
|----------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR AHR H35441 | 98007-H35441 | \$ 869.00 | 6% | <i>\$822.99</i> |
| EWP Premier 4HR AHR H35442 | 98007-H35442 | \$ 869.00 | 6% | <i>\$822.99</i> |
| EWP Premier 4HR AHR H35443 | 98007-H35443 | \$ 4,610.00 | 6% | <i>\$4,365.90</i> |
| EWP Premier 4HR AHR H35444 | 98007-H35444 | \$ 4,940.00 | 6% | <i>\$4,678.43</i> |
| EWP Premier 4HR AHR H35445 | 98007-H35445 | \$ 4,435.00 | 6% | <i>\$4,200.17</i> |
| EWP Premier 4HR AHR H35446 | 98007-H35446 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR AHR H35447 | 98007-H35447 | \$ 5,059.00 | 6% | <i>\$4,791.13</i> |
| EWP Premier 4HR AHR H35448 | 98007-H35448 | \$ 4,847.00 | 6% | <i>\$4,590.35</i> |
| EWP Premier 4HR AHR H35449 | 98007-H35449 | \$ 3,557.00 | 6% | <i>\$3,368.66</i> |
| EWP Premier 4HR AHR H35450 | 98007-H35450 | \$ 3,783.00 | 6% | <i>\$3,582.69</i> |
| EWP Premier 4HR AHR H35451 | 98007-H35451 | \$ 7,588.00 | 6% | <i>\$7,186.22</i> |
| EWP Premier 4HR AHR H35452 | 98007-H35452 | \$ 7,588.00 | 6% | <i>\$7,186.22</i> |
| EWP Premier 4HR AHR H35453 | 98007-H35453 | \$ 4,940.00 | 6% | <i>\$4,678.43</i> |
| EWP Premier 4HR AHR H35454 | 98007-H35454 | \$ 4,610.00 | 6% | <i>\$4,365.90</i> |
| EWP Premier 4HR AHR H35455 | 98007-H35455 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| EWP Premier 4HR AHR H35456 | 98007-H35456 | \$ 1,448.00 | 6% | <i>\$1,371.33</i> |
| EWP Premier 4HR AHR H35457 | 98007-H35457 | \$ 1,309.00 | 6% | <i>\$1,239.69</i> |
| EWP Premier 4HR AHR H35458 | 98007-H35458 | \$ 1,432.00 | 6% | <i>\$1,356.18</i> |
| EWP Premier 4HR AHR H35471 | 98007-H35471 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| EWP Premier 4HR AHR H35600 | 98007-H35600 | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWP Premier 4HR AHR H35601 | 98007-H35601 | \$ 481.00 | 6% | <i>\$455.53</i> |

| | | | | |
|---------------------------------------|-------------------------|--------------|-----|-------------|
| EWP Premier 4HR AHR H35602 | 98007-H35602 | \$ 718.00 | 6% | \$679.98 |
| EWP Premier 4HR AHR H35603 | 98007-H35603 | \$ 718.00 | 6% | \$679.98 |
| EWP Premier 4HR AHR H35604 | 98007-H35604 | \$ 912.00 | 6% | \$863.71 |
| EWP Premier 4HR AHR H35605 | 98007-H35605 | \$ 912.00 | 6% | \$863.71 |
| EWP Premier 4HR AHR H35606 | 98007-H35606 | \$ 1,028.00 | 6% | \$973.57 |
| EWP Premier 4HR AHR H35607 | 98007-H35607 | \$ 1,028.00 | 6% | \$973.57 |
| EWP Premier 4HR AHR ISW-24W-4X | 98007-ISW-24W-4X | \$ 1,208.00 | 6% | \$1,144.04 |
| EWP Premier 4HR AHR ISW-4W-4WS-4X | 98007-ISW-4W-4WS-4X | \$ 766.00 | 6% | \$725.44 |
| EWP Premier 4HR AHR MSM128 | 98007-MSM128 | \$ 4,000.00 | 6% | \$3,788.20 |
| EWP Premier 4HR AHR MSM48C | 98007-MSM48C | \$ 2,375.00 | 6% | \$2,249.24 |
| EWP Premier 4HR AHR SLX9150-48XT-DC-F | 98007-SLX9150-48XT-DC-F | \$ 3,644.00 | 6% | \$3,451.05 |
| EWP Premier 4HR AHR SLX9150-48XT-DC-R | 98007-SLX9150-48XT-DC-R | \$ 4,017.00 | 6% | \$3,804.30 |
| EWP Premier 4HR AHR SLX9150-48Y-DC-F | 98007-SLX9150-48Y-DC-F | \$ 3,297.00 | 6% | \$3,122.42 |
| EWP Premier 4HR AHR SLX9150-48Y-DC-R | 98007-SLX9150-48Y-DC-R | \$ 3,635.00 | 6% | \$3,442.53 |
| EWP Premier 4HR AHR SLX9740-40C | 98007-SLX9740-40C | \$ 17,247.00 | 6% | \$16,333.77 |
| EWP Premier 4HR AHR SLX9740-40C-AC-F | 98007-SLX9740-40C-AC-F | \$ 17,247.00 | 6% | \$16,333.77 |
| EWP Premier 4HR AHR SLX9740-40C-AC-R | 98007-SLX9740-40C-AC-R | \$ 17,247.00 | 10% | \$15,638.72 |
| EWP Premier 4HR AHR SLX9740-40C-DC-F | 98007-SLX9740-40C-DC-F | \$ 17,247.00 | 6% | \$16,333.77 |

| | | | | |
|---|--------------------------------|--------------|-----|--------------------|
| EWP Premier 4HR AHR SLX9740-80C | 98007- SLX9740-80C | \$ 32,432.00 | 6% | <i>\$30,714.73</i> |
| EWP Premier 4HR AHR SLX9740-80C-AC-F | 98007- SLX9740-80C- AC-F | \$ 32,432.00 | 6% | <i>\$30,714.73</i> |
| EWP Premier 4HR AHR SLX9740-80C-AC-R | 98007- SLX9740-80C- AC-R | \$ 32,432.00 | 10% | <i>\$29,407.72</i> |
| EWP Premier 4HR AHR SLX9740-80C-DC-F | 98007- SLX9740-80C- DC-F | \$ 32,432.00 | 6% | <i>\$30,714.73</i> |
| EWP Premier 4HR AHR V300- 8P-2X | 98007-V300- 8P-2X | \$ 197.00 | 6% | <i>\$186.57</i> |
| EWP Premier 4HR AHR V300- 8T-2X | 98007-V300- 8T-2X | \$ 137.00 | 6% | <i>\$129.75</i> |
| EWP Premier 4HR AHR V300HT-8P-2X | 98007-V300HT- 8P-2X | \$ 450.00 | 6% | <i>\$426.17</i> |
| EWP Premier 4HR AHR V300HT-8T-2X | 98007-V300HT- 8T-2X | \$ 270.00 | 6% | <i>\$255.70</i> |
| EWP Premier 4HR AHR VIM- SS | 98007-VIM-SS | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier 4HR AHR VIM- SSV80 | 98007-VIM- SSV80 | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWP Premier 4HR AHR VIM2- SS | 98007-VIM2- SS | \$ 237.00 | 6% | <i>\$224.45</i> |
| EWP Premier 4HR AHR VIM2- SS128 | 98007-VIM2- SS128 | \$ 827.00 | 6% | <i>\$783.21</i> |
| EWP Premier 4HR AHR VIM2- V80 | 98007-VIM2- V80 | \$ 884.00 | 6% | <i>\$837.19</i> |
| EWP Premier 4HR AHR VIM210G4X | 98007- VIM210G4X | \$ 1,528.00 | 6% | <i>\$1,447.09</i> |
| EWP Premier 4HR AHR VIM5- 2Q | 98007-VIM5- 2Q | \$ 265.00 | 6% | <i>\$250.97</i> |
| EWP Premier 4HR AHR VIM5- 2Y | 98007-VIM5- 2Y | \$ 312.00 | 6% | <i>\$295.48</i> |
| EWP Premier 4HR AHR VIM5- 4X | 98007-VIM5- 4X | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier 4HR AHR VIM5- 4XE | 98007-VIM5- 4XE | \$ 258.00 | 6% | <i>\$244.34</i> |
| EWP Premier 4HR AHR VIM5- 4Y | 98007-VIM5- 4Y | \$ 399.00 | 6% | <i>\$377.87</i> |

| | | | | |
|--|-----------------------------|-------------|----|-------------------|
| EWP Premier 4HR AHR VIM5-4YE | 98007-VIM5-4YE | \$ 515.00 | 6% | <i>\$487.73</i> |
| EWP Prem 4HR AHR VSP4900-12MXU-12XE | 98007-VSP4900-12MXU-12XE | \$ 1,571.00 | 6% | <i>\$1,487.82</i> |
| EWP Prem 4HR AHR VSP4900-12MXU-12XE-B1 | 98007-VSP4900-12MXU-12XE-B1 | \$ 1,571.00 | 6% | <i>\$1,487.82</i> |
| EWP Premier 4HR AHR VSP4900-24S | 98007-VSP4900-24S | \$ 855.00 | 6% | <i>\$809.73</i> |
| EWP Premier 4HR AHR VSP4900-24S-B3 | 98007-VSP4900-24S-B3 | \$ 855.00 | 6% | <i>\$809.73</i> |
| EWP Premier 4HR AHR VSP4900-24XE | 98007-VSP4900-24XE | \$ 1,571.00 | 6% | <i>\$1,487.82</i> |
| EWP Premier 4HR AHR VSP4900-24XE-B3 | 98007-VSP4900-24XE-B3 | \$ 1,571.00 | 6% | <i>\$1,487.82</i> |
| EWP Premier 4HR AHR X435-24P-4S | 98007-X435-24P-4S | \$ 349.00 | 6% | <i>\$330.52</i> |
| EWP Premier 4HR AHR X435-24T-4S | 98007-X435-24T-4S | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier 4HR AHR X435-8P-2T-W | 98007-X435-8P-2T-W | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier 4HR AHR X435-8P-4S | 98007-X435-8P-4S | \$ 172.00 | 6% | <i>\$162.89</i> |
| EWP Premier 4HR AHR X435-8T-4S | 98007-X435-8T-4S | \$ 139.00 | 6% | <i>\$131.64</i> |
| EWP Premier 4HR AHR X460-24P | 98007-X460-24P | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| EWP Premier 4HR AHR X460-24T | 98007-X460-24T | \$ 985.00 | 6% | <i>\$932.84</i> |
| EWP Premier 4HR AHR X460-24TDC | 98007-X460-24TDC | \$ 1,447.00 | 6% | <i>\$1,370.38</i> |
| EWP Premier 4HR AHR X460-24X | 98007-X460-24X | \$ 1,827.00 | 6% | <i>\$1,730.26</i> |
| EWP Premier 4HR AHR X460-24XDC | 98007-X460-24XDC | \$ 2,033.00 | 6% | <i>\$1,925.35</i> |
| EWP Premier 4HR AHR X460-48P | 98007-X460-48P | \$ 1,827.00 | 6% | <i>\$1,730.26</i> |

| | | | | |
|-------------------------------------|-----------------------|-------------|----|-------------------|
| EWP Premier 4HR AHR X460-48T | 98007-X460-48T | \$ 1,562.00 | 6% | <i>\$1,479.29</i> |
| EWP Premier 4HR AHR X460-48TDC | 98007-X460-48TDC | \$ 1,973.00 | 6% | <i>\$1,868.53</i> |
| EWP Premier 4HR AHR X460-48X | 98007-X460-48X | \$ 2,430.00 | 6% | <i>\$2,301.33</i> |
| EWP Premier 4HR AHR X460-48XDC | 98007-X460-48XDC | \$ 2,364.00 | 6% | <i>\$2,238.83</i> |
| EWP Premier 4HR AHR X465-24MU | 98007-X465-24MU | \$ 1,815.00 | 6% | <i>\$1,718.90</i> |
| EWP Premier 4HR AHR X465-24S | 98007-X465-24S | \$ 855.00 | 6% | <i>\$809.73</i> |
| EWP Premier 4HR AHR X465-24S-B3 | 98007-X465-24S-B3 | \$ 855.00 | 6% | <i>\$809.73</i> |
| EWP Premier 4HR AHR X465-24W | 98007-X465-24W | \$ 855.00 | 6% | <i>\$809.73</i> |
| EWP Premier 4HR AHR X465-24XE | 98007-X465-24XE | \$ 1,571.00 | 6% | <i>\$1,487.82</i> |
| EWP Premier 4HR AHR X465-24XE-B3 | 98007-X465-24XE-B3 | \$ 1,571.00 | 6% | <i>\$1,487.82</i> |
| EWP Premier 4HR AHR X465-48P | 98007-X465-48P | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| EWP Premier 4HR AHR X465-48T | 98007-X465-48T | \$ 1,134.00 | 6% | <i>\$1,073.95</i> |
| EWP Premier 4HR AHR X465-48W | 98007-X465-48W | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| EWP Premier 4HR AHR X465i-48W | 98007-X465i-48W | \$ 1,780.00 | 6% | <i>\$1,685.75</i> |
| EWP Premier 4HR AHR X465i-48W-B1-S1 | 98007-X465i-48W-B1-S1 | \$ 1,780.00 | 6% | <i>\$1,685.75</i> |
| EWP Premier 4HR AHR X465i-48W-B2-S1 | 98007-X465i-48W-B2-S1 | \$ 1,780.00 | 6% | <i>\$1,685.75</i> |
| EWP Premier 4HR AHR X480-24X | 98007-X480-24X | \$ 2,289.00 | 6% | <i>\$2,167.80</i> |
| EWP Premier 4HR AHR X480-48T | 98007-X480-48T | \$ 2,289.00 | 6% | <i>\$2,167.80</i> |
| EWP Premier 4HR AHR X480-48X | 98007-X480-48X | \$ 3,044.00 | 6% | <i>\$2,882.82</i> |
| EWP Premier 4HR AHR X695-48Y-8C | 98007-X695-48Y-8C | \$ 4,102.00 | 6% | <i>\$3,884.80</i> |
| EWP Premier 4HR AHR XA1440 | 98007-XA1440 | \$ 431.00 | 6% | <i>\$408.18</i> |

| | | | | |
|-------------------------------|----------------|-------------|----|-------------------|
| EWP Premier 4HR AHR XA1480 | 98007-XA1480 | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier 4HR AHR XGM3-2SF | 98007-XGM3-2SF | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWP Premier 4HR AHR XR600 | 98007-XR600 | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR AHR ZR-XFP | 98007-ZR-XFP | \$ 2,305.00 | 6% | <i>\$2,182.95</i> |
| EWP Premier 4HR ONSITE 10200 | 98008-10200 | \$ 3,656.00 | 6% | <i>\$3,462.41</i> |
| EWP Premier 4HR ONSITE 10320 | 98008-10320 | \$ 4,018.00 | 6% | <i>\$3,805.25</i> |
| EWP Premier 4HR ONSITE 10330 | 98008-10330 | \$ 9,658.00 | 6% | <i>\$9,146.61</i> |
| EWP Premier 4HR ONSITE 10331 | 98008-10331 | \$ 4,453.00 | 6% | <i>\$4,217.21</i> |
| EWP Premier 4HR ONSITE 10335 | 98008-10335 | \$ 6,934.00 | 6% | <i>\$6,566.84</i> |
| EWP Premier 4HR ONSITE 10403 | 98008-10403 | \$ 8,849.00 | 6% | <i>\$8,380.45</i> |
| EWP Premier 4HR ONSITE 10404 | 98008-10404 | \$ 4,343.00 | 6% | <i>\$4,113.04</i> |
| EWP Premier 4HR ONSITE 10441 | 98008-10441 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE 10442 | 98008-10442 | \$ 3,102.00 | 6% | <i>\$2,937.75</i> |
| EWP Premier 4HR ONSITE 1130C | 98008-1130C | \$ 1,967.00 | 6% | <i>\$1,862.85</i> |
| EWP Premier 4HR ONSITE 16119 | 98008-16119 | \$ 523.00 | 6% | <i>\$495.31</i> |
| EWP Premier 4HR ONSITE 16120 | 98008-16120 | \$ 656.00 | 6% | <i>\$621.26</i> |
| EWP Premier 4HR ONSITE 16126 | 98008-16126 | \$ 523.00 | 6% | <i>\$495.31</i> |
| EWP Premier 4HR ONSITE 16127 | 98008-16127 | \$ 548.00 | 6% | <i>\$518.98</i> |
| EWP Premier 4HR ONSITE 16172 | 98008-16172 | \$ 532.00 | 6% | <i>\$503.83</i> |
| EWP Premier 4HR ONSITE 16172T | 98008-16172T | \$ 642.00 | 6% | <i>\$608.01</i> |
| EWP Premier 4HR ONSITE 16173 | 98008-16173 | \$ 547.00 | 6% | <i>\$518.04</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 16173T | 98008-16173T | \$ 658.00 | 6% | <i>\$623.16</i> |
| EWP Premier 4HR ONSITE 16174 | 98008-16174 | \$ 864.00 | 6% | <i>\$818.25</i> |
| EWP Premier 4HR ONSITE 16175 | 98008-16175 | \$ 894.00 | 6% | <i>\$846.66</i> |
| EWP Premier 4HR ONSITE 16176 | 98008-16176 | \$ 783.00 | 6% | <i>\$741.54</i> |
| EWP Premier 4HR ONSITE 16177 | 98008-16177 | \$ 772.00 | 6% | <i>\$731.12</i> |
| EWP Premier 4HR ONSITE 16177T | 98008-16177T | \$ 983.00 | 6% | <i>\$930.95</i> |
| EWP Premier 4HR ONSITE 16178 | 98008-16178 | \$ 1,139.00 | 6% | <i>\$1,078.69</i> |
| EWP Premier 4HR ONSITE 16179 | 98008-16179 | \$ 1,168.00 | 6% | <i>\$1,106.15</i> |
| EWP Premier 4HR ONSITE 16179T | 98008-16179T | \$ 1,404.00 | 6% | <i>\$1,329.66</i> |
| EWP Premier 4HR ONSITE 16301T | 98008-16301T | \$ 3,090.00 | 6% | <i>\$2,926.38</i> |
| EWP Premier 4HR ONSITE 16303T | 98008-16303T | \$ 3,090.00 | 6% | <i>\$2,926.38</i> |
| EWP Premier 4HR ONSITE 16304T | 98008-16304T | \$ 4,119.00 | 6% | <i>\$3,900.90</i> |
| EWP Premier 4HR ONSITE 16401T | 98008-16401T | \$ 1,425.00 | 6% | <i>\$1,349.55</i> |
| EWP Premier 4HR ONSITE 16402T | 98008-16402T | \$ 2,166.00 | 6% | <i>\$2,051.31</i> |
| EWP Premier 4HR ONSITE 16403T | 98008-16403T | \$ 1,924.00 | 6% | <i>\$1,822.12</i> |
| EWP Premier 4HR ONSITE 16404T | 98008-16404T | \$ 1,924.00 | 6% | <i>\$1,822.12</i> |
| EWP Premier 4HR ONSITE 16405T | 98008-16405T | \$ 2,526.00 | 6% | <i>\$2,392.25</i> |
| EWP Premier 4HR ONSITE 16406T | 98008-16406T | \$ 3,376.00 | 6% | <i>\$3,197.24</i> |
| EWP Premier 4HR ONSITE 16431 | 98008-16431 | \$ 2,179.00 | 6% | <i>\$2,063.62</i> |
| EWP Premier 4HR ONSITE 16432 | 98008-16432 | \$ 2,312.00 | 6% | <i>\$2,189.58</i> |
| EWP Premier 4HR ONSITE 16440 | 98008-16440 | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 16441 | 98008-16441 | \$ 1,227.00 | 6% | <i>\$1,162.03</i> |
| EWP Premier 4HR ONSITE 16442 | 98008-16442 | \$ 548.00 | 6% | <i>\$518.98</i> |
| EWP Premier 4HR ONSITE 16444 | 98008-16444 | \$ 275.00 | 6% | <i>\$260.44</i> |
| EWP Premier 4HR ONSITE 16501 | 98008-16501 | \$ 294.00 | 6% | <i>\$278.43</i> |
| EWP Premier 4HR ONSITE 16501T | 98008-16501T | \$ 383.00 | 6% | <i>\$362.72</i> |
| EWP Premier 4HR ONSITE 16502 | 98008-16502 | \$ 427.00 | 6% | <i>\$404.39</i> |
| EWP Premier 4HR ONSITE 16502T | 98008-16502T | \$ 516.00 | 6% | <i>\$488.68</i> |
| EWP Premier 4HR ONSITE 16503 | 98008-16503 | \$ 353.00 | 6% | <i>\$334.31</i> |
| EWP Premier 4HR ONSITE 16503T | 98008-16503T | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWP Premier 4HR ONSITE 16504 | 98008-16504 | \$ 573.00 | 6% | <i>\$542.66</i> |
| EWP Premier 4HR ONSITE 16504T | 98008-16504T | \$ 691.00 | 6% | <i>\$654.41</i> |
| EWP Premier 4HR ONSITE 16505 | 98008-16505 | \$ 640.00 | 6% | <i>\$606.11</i> |
| EWP Premier 4HR ONSITE 16505T | 98008-16505T | \$ 779.00 | 6% | <i>\$737.75</i> |
| EWP Premier 4HR ONSITE 16506 | 98008-16506 | \$ 979.00 | 6% | <i>\$927.16</i> |
| EWP Premier 4HR ONSITE 16506T | 98008-16506T | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWP Premier 4HR ONSITE 16507 | 98008-16507 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier 4HR ONSITE 16507T | 98008-16507T | \$ 1,065.00 | 6% | <i>\$1,008.61</i> |
| EWP Premier 4HR ONSITE 16508 | 98008-16508 | \$ 1,115.00 | 6% | <i>\$1,055.96</i> |
| EWP Premier 4HR ONSITE 16508T | 98008-16508T | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| EWP Premier 4HR ONSITE 16509 | 98008-16509 | \$ 1,115.00 | 6% | <i>\$1,055.96</i> |
| EWP Premier 4HR ONSITE 16509T | 98008-16509T | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 16510 | 98008-16510 | \$ 1,329.00 | 6% | <i>\$1,258.63</i> |
| EWP Premier 4HR ONSITE 16510T | 98008-16510T | \$ 1,593.00 | 6% | <i>\$1,508.65</i> |
| EWP Premier 4HR ONSITE 16513 | 98008-16513 | \$ 875.00 | 6% | <i>\$828.67</i> |
| EWP Premier 4HR ONSITE 16514 | 98008-16514 | \$ 1,304.00 | 6% | <i>\$1,234.95</i> |
| EWP Premier 4HR ONSITE 16515 | 98008-16515 | \$ 226.00 | 6% | <i>\$214.03</i> |
| EWP Premier 4HR ONSITE 16516 | 98008-16516 | \$ 253.00 | 6% | <i>\$239.60</i> |
| EWP Premier 4HR ONSITE 16517 | 98008-16517 | \$ 492.00 | 6% | <i>\$465.95</i> |
| EWP Premier 4HR ONSITE 16518 | 98008-16518 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWP Premier 4HR ONSITE 16519 | 98008-16519 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWP Premier 4HR ONSITE 16520 | 98008-16520 | \$ 727.00 | 6% | <i>\$688.51</i> |
| EWP Premier 4HR ONSITE 16530 | 98008-16530 | \$ 268.00 | 6% | <i>\$253.81</i> |
| EWP Premier 4HR ONSITE 16531 | 98008-16531 | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWP Premier 4HR ONSITE 16531T | 98008-16531T | \$ 421.00 | 6% | <i>\$398.71</i> |
| EWP Premier 4HR ONSITE 16532 | 98008-16532 | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWP Premier 4HR ONSITE 16532T | 98008-16532T | \$ 421.00 | 6% | <i>\$398.71</i> |
| EWP Premier 4HR ONSITE 16533 | 98008-16533 | \$ 514.00 | 6% | <i>\$486.78</i> |
| EWP Premier 4HR ONSITE 16533T | 98008-16533T | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE 16534 | 98008-16534 | \$ 553.00 | 6% | <i>\$523.72</i> |
| EWP Premier 4HR ONSITE 16535 | 98008-16535 | \$ 814.00 | 6% | <i>\$770.90</i> |
| EWP Premier 4HR ONSITE 16535A | 98008-16535A | \$ 814.00 | 6% | <i>\$770.90</i> |
| EWP Premier 4HR ONSITE 16535T | 98008-16535T | \$ 928.00 | 6% | <i>\$878.86</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 16536 | 98008-16536 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWP Premier 4HR ONSITE 16537 | 98008-16537 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier 4HR ONSITE 16538 | 98008-16538 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWP Premier 4HR ONSITE 16538T | 98008-16538T | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWP Premier 4HR ONSITE 16539 | 98008-16539 | \$ 801.00 | 6% | <i>\$758.59</i> |
| EWP Premier 4HR ONSITE 16540 | 98008-16540 | \$ 571.00 | 6% | <i>\$540.77</i> |
| EWP Premier 4HR ONSITE 16541 | 98008-16541 | \$ 217.00 | 6% | <i>\$205.51</i> |
| EWP Premier 4HR ONSITE 16560 | 98008-16560 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier 4HR ONSITE 16561 | 98008-16561 | \$ 190.00 | 6% | <i>\$179.94</i> |
| EWP Premier 4HR ONSITE 16562 | 98008-16562 | \$ 231.00 | 6% | <i>\$218.77</i> |
| EWP Premier 4HR ONSITE 16563 | 98008-16563 | \$ 307.00 | 6% | <i>\$290.74</i> |
| EWP Premier 4HR ONSITE 16564 | 98008-16564 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWP Premier 4HR ONSITE 16565 | 98008-16565 | \$ 559.00 | 6% | <i>\$529.40</i> |
| EWP Premier 4HR ONSITE 16566 | 98008-16566 | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier 4HR ONSITE 16567 | 98008-16567 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier 4HR ONSITE 16568 | 98008-16568 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier 4HR ONSITE 16569 | 98008-16569 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier 4HR ONSITE 16570 | 98008-16570 | \$ 231.00 | 6% | <i>\$218.77</i> |
| EWP Premier 4HR ONSITE 16571 | 98008-16571 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWP Premier 4HR ONSITE 16701 | 98008-16701 | \$ 801.00 | 6% | <i>\$758.59</i> |
| EWP Premier 4HR ONSITE 16702 | 98008-16702 | \$ 1,180.00 | 6% | <i>\$1,117.52</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 16703 | 98008-16703 | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP Premier 4HR ONSITE 16703T | 98008-16703T | \$ 1,109.00 | 6% | <i>\$1,050.28</i> |
| EWP Premier 4HR ONSITE 16704 | 98008-16704 | \$ 1,363.00 | 6% | <i>\$1,290.83</i> |
| EWP Premier 4HR ONSITE 16704T | 98008-16704T | \$ 1,643.00 | 6% | <i>\$1,556.00</i> |
| EWP Premier 4HR ONSITE 16705 | 98008-16705 | \$ 1,180.00 | 6% | <i>\$1,117.52</i> |
| EWP Premier 4HR ONSITE 16705T | 98008-16705T | \$ 1,420.00 | 6% | <i>\$1,344.81</i> |
| EWP Premier 4HR ONSITE 16706 | 98008-16706 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWP Premier 4HR ONSITE 16706T | 98008-16706T | \$ 2,157.00 | 6% | <i>\$2,042.79</i> |
| EWP Premier 4HR ONSITE 16710 | 98008-16710 | \$ 358.00 | 6% | <i>\$339.04</i> |
| EWP Premier 4HR ONSITE 16710T | 98008-16710T | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWP Premier 4HR ONSITE 16711 | 98008-16711 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE 16711T | 98008-16711T | \$ 181.00 | 6% | <i>\$171.42</i> |
| EWP Premier 4HR ONSITE 16712 | 98008-16712 | \$ 206.00 | 6% | <i>\$195.09</i> |
| EWP Premier 4HR ONSITE 16712T | 98008-16712T | \$ 247.00 | 6% | <i>\$233.92</i> |
| EWP Premier 4HR ONSITE 16713 | 98008-16713 | \$ 100.00 | 6% | <i>\$94.71</i> |
| EWP Premier 4HR ONSITE 16713T | 98008-16713T | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier 4HR ONSITE 16715 | 98008-16715 | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE 16715T | 98008-16715T | \$ 181.00 | 6% | <i>\$171.42</i> |
| EWP Premier 4HR ONSITE 16716 | 98008-16716 | \$ 624.00 | 6% | <i>\$590.96</i> |
| EWP Premier 4HR ONSITE 16716T | 98008-16716T | \$ 751.00 | 6% | <i>\$711.23</i> |
| EWP Premier 4HR ONSITE 16717 | 98008-16717 | \$ 947.00 | 6% | <i>\$896.86</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 16718 | 98008-16718 | \$ 677.00 | 6% | <i>\$641.15</i> |
| EWP Premier 4HR ONSITE 16718T | 98008-16718T | \$ 804.00 | 6% | <i>\$761.43</i> |
| EWP Premier 4HR ONSITE 16719 | 98008-16719 | \$ 1,012.00 | 6% | <i>\$958.41</i> |
| EWP Premier 4HR ONSITE 16719T | 98008-16719T | \$ 1,216.00 | 6% | <i>\$1,151.61</i> |
| EWP Premier 4HR ONSITE 16720 | 98008-16720 | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWP Premier 4HR ONSITE 16720T | 98008-16720T | \$ 1,811.00 | 6% | <i>\$1,715.11</i> |
| EWP Premier 4HR ONSITE 16756 | 98008-16756 | \$ 1,136.00 | 6% | <i>\$1,075.85</i> |
| EWP Premier 4HR ONSITE 16756T | 98008-16756T | \$ 1,344.00 | 6% | <i>\$1,272.84</i> |
| EWP Premier 4HR ONSITE 16757 | 98008-16757 | \$ 1,076.00 | 6% | <i>\$1,019.03</i> |
| EWP Premier 4HR ONSITE 16757T | 98008-16757T | \$ 1,267.00 | 6% | <i>\$1,199.91</i> |
| EWP Premier 4HR ONSITE 16790 | 98008-16790 | \$ 2,417.00 | 6% | <i>\$2,289.02</i> |
| EWP Premier 4HR ONSITE 16791 | 98008-16791 | \$ 3,119.00 | 6% | <i>\$2,953.85</i> |
| EWP Premier 4HR ONSITE 16801 | 98008-16801 | \$ 313.00 | 6% | <i>\$296.43</i> |
| EWP Premier 4HR ONSITE 16802 | 98008-16802 | \$ 362.00 | 6% | <i>\$342.83</i> |
| EWP Premier 4HR ONSITE 16803 | 98008-16803 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWP Premier 4HR ONSITE 16804 | 98008-16804 | \$ 473.00 | 6% | <i>\$447.95</i> |
| EWP Premier 4HR ONSITE 16805 | 98008-16805 | \$ 100.00 | 6% | <i>\$94.71</i> |
| EWP Premier 4HR ONSITE 16806 | 98008-16806 | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier 4HR ONSITE 17101 | 98008-17101 | \$ 4,582.00 | 6% | <i>\$4,339.38</i> |
| EWP Premier 4HR ONSITE 17101T | 98008-17101T | \$ 5,746.00 | 6% | <i>\$5,441.75</i> |
| EWP Premier 4HR ONSITE 17102 | 98008-17102 | \$ 4,582.00 | 6% | <i>\$4,339.38</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 17102T | 98008-17102T | \$ 5,746.00 | 6% | <i>\$5,441.75</i> |
| EWP Premier 4HR ONSITE 17103 | 98008-17103 | \$ 3,191.00 | 6% | <i>\$3,022.04</i> |
| EWP Premier 4HR ONSITE 17103C | 98008-17103C | \$ 3,096.00 | 6% | <i>\$2,932.07</i> |
| EWP Premier 4HR ONSITE 17103T | 98008-17103T | \$ 4,001.00 | 6% | <i>\$3,789.15</i> |
| EWP Premier 4HR ONSITE 17104 | 98008-17104 | \$ 3,191.00 | 6% | <i>\$3,022.04</i> |
| EWP Premier 4HR ONSITE 17104T | 98008-17104T | \$ 4,001.00 | 6% | <i>\$3,789.15</i> |
| EWP Premier 4HR ONSITE 17121 | 98008-17121 | \$ 918.00 | 6% | <i>\$869.39</i> |
| EWP Premier 4HR ONSITE 17122 | 98008-17122 | \$ 572.00 | 6% | <i>\$541.71</i> |
| EWP Premier 4HR ONSITE 17200 | 98008-17200 | \$ 7,206.00 | 6% | <i>\$6,824.44</i> |
| EWP Premier 4HR ONSITE 17200T | 98008-17200T | \$ 8,237.00 | 6% | <i>\$7,800.85</i> |
| EWP Premier 4HR ONSITE 17201 | 98008-17201 | \$ 7,206.00 | 6% | <i>\$6,824.44</i> |
| EWP Premier 4HR ONSITE 17201T | 98008-17201T | \$ 8,237.00 | 6% | <i>\$7,800.85</i> |
| EWP Premier 4HR ONSITE 17202 | 98008-17202 | \$ 7,206.00 | 6% | <i>\$6,824.44</i> |
| EWP Premier 4HR ONSITE 17202T | 98008-17202T | \$ 8,237.00 | 6% | <i>\$7,800.85</i> |
| EWP Premier 4HR ONSITE 17203 | 98008-17203 | \$ 7,315.00 | 6% | <i>\$6,927.67</i> |
| EWP Premier 4HR ONSITE 17203T | 98008-17203T | \$ 8,358.00 | 6% | <i>\$7,915.44</i> |
| EWP Premier 4HR ONSITE 17204 | 98008-17204 | \$ 7,315.00 | 6% | <i>\$6,927.67</i> |
| EWP Premier 4HR ONSITE 17204T | 98008-17204T | \$ 8,358.00 | 6% | <i>\$7,915.44</i> |
| EWP Premier 4HR ONSITE 17205 | 98008-17205 | \$ 7,257.00 | 6% | <i>\$6,872.74</i> |
| EWP Premier 4HR ONSITE 17205T | 98008-17205T | \$ 8,296.00 | 6% | <i>\$7,856.73</i> |
| EWP Premier 4HR ONSITE 17206 | 98008-17206 | \$ 7,257.00 | 6% | <i>\$6,872.74</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 17206T | 98008-17206T | \$ 8,296.00 | 6% | <i>\$7,856.73</i> |
| EWP Premier 4HR ONSITE 17300 | 98008-17300 | \$ 4,786.00 | 6% | <i>\$4,532.58</i> |
| EWP Premier 4HR ONSITE 17310 | 98008-17310 | \$ 4,343.00 | 6% | <i>\$4,113.04</i> |
| EWP Premier 4HR ONSITE 17310T | 98008-17310T | \$ 5,238.00 | 6% | <i>\$4,960.65</i> |
| EWP Premier 4HR ONSITE 17350 | 98008-17350 | \$ 4,445.00 | 6% | <i>\$4,209.64</i> |
| EWP Premier 4HR ONSITE 17360 | 98008-17360 | \$ 5,474.00 | 6% | <i>\$5,184.15</i> |
| EWP Premier 4HR ONSITE 17401 | 98008-17401 | \$ 681.00 | 6% | <i>\$644.94</i> |
| EWP Premier 4HR ONSITE 17401G | 98008-17401G | \$ 824.00 | 6% | <i>\$780.37</i> |
| EWP Premier 4HR ONSITE 17401T | 98008-17401T | \$ 782.00 | 6% | <i>\$740.59</i> |
| EWP Premier 4HR ONSITE 17402 | 98008-17402 | \$ 960.00 | 6% | <i>\$909.17</i> |
| EWP Premier 4HR ONSITE 17402G | 98008-17402G | \$ 1,089.00 | 6% | <i>\$1,031.34</i> |
| EWP Premier 4HR ONSITE 17402T | 98008-17402T | \$ 1,035.00 | 6% | <i>\$980.20</i> |
| EWP Premier 4HR ONSITE 17403 | 98008-17403 | \$ 1,056.00 | 6% | <i>\$1,000.08</i> |
| EWP Premier 4HR ONSITE 17404 | 98008-17404 | \$ 501.00 | 6% | <i>\$474.47</i> |
| EWP Premier 4HR ONSITE 17405 | 98008-17405 | \$ 632.00 | 6% | <i>\$598.54</i> |
| EWP Premier 4HR ONSITE 17700 | 98008-17700 | \$ 8,441.00 | 6% | <i>\$7,994.05</i> |
| EWP Premier 4HR ONSITE 17701 | 98008-17701 | \$ 7,452.00 | 6% | <i>\$7,057.42</i> |
| EWP Premier 4HR ONSITE 17702 | 98008-17702 | \$ 7,452.00 | 6% | <i>\$7,057.42</i> |
| EWP Premier 4HR ONSITE 17703 | 98008-17703 | \$ 8,160.00 | 6% | <i>\$7,727.93</i> |
| EWP Premier 4HR ONSITE 17704 | 98008-17704 | \$ 8,160.00 | 6% | <i>\$7,727.93</i> |
| EWP Premier 4HR ONSITE 17705 | 98008-17705 | \$ 7,500.00 | 6% | <i>\$7,102.88</i> |

| | | | | |
|-------------------------------------|---------------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE 17706 | 98008-17706 | \$ 7,500.00 | 6% | <i>\$7,102.88</i> |
| EWP Premier 4HR ONSITE 17800 | 98008-17800 | \$ 8,622.00 | 6% | <i>\$8,165.47</i> |
| EWP Premier 4HR ONSITE 17810 | 98008-17810 | \$ 6,892.00 | 6% | <i>\$6,527.07</i> |
| EWP Premier 4HR ONSITE 18101 | 98008-18101 | \$ 447.00 | 6% | <i>\$423.33</i> |
| EWP Premier 4HR ONSITE 18102 | 98008-18102 | \$ 576.00 | 6% | <i>\$545.50</i> |
| EWP Premier 4HR ONSITE 18103 | 98008-18103 | \$ 630.00 | 6% | <i>\$596.64</i> |
| EWP Premier 4HR ONSITE 18104 | 98008-18104 | \$ 894.00 | 6% | <i>\$846.66</i> |
| EWP Premier 4HR ONSITE 18104-6PK | 98008-18104- 6PK | \$ 5,206.00 | 6% | <i>\$4,930.34</i> |
| EWP Premier 4HR ONSITE 18202 | 98008-18202 | \$ 336.00 | 6% | <i>\$318.21</i> |
| EWP Premier 4HR ONSITE 30135 | 98008-30135 | \$ 1,168.00 | 6% | <i>\$1,106.15</i> |
| EWP Premier 4HR ONSITE 30136 | 98008-30136 | \$ 9,086.00 | 6% | <i>\$8,604.90</i> |
| EWP Premier 4HR ONSITE 30137 | 98008-30137 | \$ 1,909.00 | 6% | <i>\$1,807.92</i> |
| EWP Premier 4HR ONSITE 30138 | 98008-30138 | \$ 8,754.00 | 6% | <i>\$8,290.48</i> |
| EWP Premier 4HR ONSITE 30139 | 98008-30139 | \$ 14,423.00 | 6% | <i>\$13,659.30</i> |
| EWP Premier 4HR ONSITE 30912 | 98008-30912 | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier 4HR ONSITE 30913 | 98008-30913 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE 31012 | 98008-31012 | \$ 185.00 | 6% | <i>\$175.20</i> |
| EWP Premier 4HR ONSITE 31013 | 98008-31013 | \$ 185.00 | 6% | <i>\$175.20</i> |
| EWP Premier 4HR ONSITE 31014 | 98008-31014 | \$ 185.00 | 6% | <i>\$175.20</i> |
| EWP Premier 4HR ONSITE 31015 | 98008-31015 | \$ 185.00 | 6% | <i>\$175.20</i> |
| EWP Premier 4HR ONSITE 31016 | 98008-31016 | \$ 487.00 | 6% | <i>\$461.21</i> |

| | | | | |
|---------------------------------|-------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE 31017 | 98008-31017 | \$ 487.00 | 6% | <i>\$461.21</i> |
| EWP Premier 4HR ONSITE 31018 | 98008-31018 | \$ 552.00 | 6% | <i>\$522.77</i> |
| EWP Premier 4HR ONSITE 31019 | 98008-31019 | \$ 552.00 | 6% | <i>\$522.77</i> |
| EWP Premier 4HR ONSITE 31025 | 98008-31025 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR ONSITE 31026 | 98008-31026 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR ONSITE 31028 | 98008-31028 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier 4HR ONSITE 31029 | 98008-31029 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR ONSITE 31031 | 98008-31031 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier 4HR ONSITE 31032 | 98008-31032 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier 4HR ONSITE 31034 | 98008-31034 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR ONSITE 31035 | 98008-31035 | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR ONSITE 31050 | 98008-31050 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 31051 | 98008-31051 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 31055 | 98008-31055 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 31056 | 98008-31056 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37101 | 98008-37101 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE 37102 | 98008-37102 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE 37103 | 98008-37103 | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE 37111 | 98008-37111 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier 4HR ONSITE 37112 | 98008-37112 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier 4HR ONSITE 37113 | 98008-37113 | \$ 133.00 | 6% | <i>\$125.96</i> |

| | | | | |
|---------------------------------|-------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE 37114 | 98008-37114 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier 4HR ONSITE 37115 | 98008-37115 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier 4HR ONSITE 37116 | 98008-37116 | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier 4HR ONSITE 37117 | 98008-37117 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier 4HR ONSITE 37121 | 98008-37121 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37122 | 98008-37122 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37123 | 98008-37123 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37124 | 98008-37124 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37125 | 98008-37125 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37126 | 98008-37126 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37129 | 98008-37129 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 37130 | 98008-37130 | \$ 205.00 | 6% | <i>\$194.15</i> |
| EWP Premier 4HR ONSITE 39031 | 98008-39031 | \$ 183.00 | 6% | <i>\$173.31</i> |
| EWP Premier 4HR ONSITE 39032 | 98008-39032 | \$ 307.00 | 6% | <i>\$290.74</i> |
| EWP Premier 4HR ONSITE 39033 | 98008-39033 | \$ 183.00 | 6% | <i>\$173.31</i> |
| EWP Premier 4HR ONSITE 39034 | 98008-39034 | \$ 239.00 | 6% | <i>\$226.34</i> |
| EWP Premier 4HR ONSITE 39035 | 98008-39035 | \$ 1,371.00 | 6% | <i>\$1,298.41</i> |
| EWP Premier 4HR ONSITE 39036 | 98008-39036 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier 4HR ONSITE 39037 | 98008-39037 | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier 4HR ONSITE 39038 | 98008-39038 | \$ 349.00 | 6% | <i>\$330.52</i> |
| EWP Premier 4HR ONSITE 39039 | 98008-39039 | \$ 349.00 | 6% | <i>\$330.52</i> |

| | | | | |
|---|---------------------------|--------------|-----|--------------------|
| EWP Premier 4HR ONSITE 39505 | 98008-39505 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier 4HR ONSITE 4120-24MW-4Y | 98008-4120- 24MW-4Y | \$ 1,284.00 | 6% | <i>\$1,216.01</i> |
| EWP Premier 4HR ONSITE 4120-48MW-4Y | 98008-4120- 48MW-4Y | \$ 1,712.00 | 6% | <i>\$1,621.35</i> |
| EWP Premier 4HR ONSITE 4120C | 98008-4120C | \$ 9,719.00 | 10% | <i>\$8,812.70</i> |
| EWP Premier 4HR ONSITE 4120C-1 | 98008-4120C-1 | \$ 10,711.00 | 6% | <i>\$10,143.85</i> |
| EWP Premier 4HR ONSITE 41216 | 98008-41216 | \$ 2,901.00 | 6% | <i>\$2,747.39</i> |
| EWP Premier 4HR ONSITE 4220-12P-4X | 98008-4220- 12P-4X | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier 4HR ONSITE 4220-12T-4X | 98008-4220- 12T-4X | \$ 275.00 | 6% | <i>\$260.44</i> |
| EWP Premier 4HR ONSITE 4220-24P-4X | 98008-4220- 24P-4X | \$ 500.00 | 6% | <i>\$473.53</i> |
| EWP Premier 4HR ONSITE 4220-24T-4X | 98008-4220- 24T-4X | \$ 387.00 | 6% | <i>\$366.51</i> |
| EWP Premier 4HR ONSITE 4220-48P-4X | 98008-4220- 48P-4X | \$ 751.00 | 6% | <i>\$711.23</i> |
| EWP Premier 4HR ONSITE 4220-48T-4X | 98008-4220- 48T-4X | \$ 563.00 | 6% | <i>\$533.19</i> |
| EWP Premier 4HR ONSITE 4220-4MW-20P-4X | 98008-4220- 4MW-20P-4X | \$ 688.00 | 6% | <i>\$651.57</i> |
| EWP Premier 4HR ONSITE 4220-4MW-8P-4X | 98008-4220- 4MW-8P-4X | \$ 488.00 | 6% | <i>\$462.16</i> |
| EWP Premier 4HR ONSITE 4220-8MW-40P-4X | 98008-4220- 8MW-40P-4X | \$ 1,001.00 | 6% | <i>\$948.00</i> |
| EWP Premier 4HR ONSITE 4220-8X | 98008-4220-8X | \$ 525.00 | 6% | <i>\$497.20</i> |
| EWP Premier 4HR ONSITE 48001 | 98008-48001 | \$ 12,047.00 | 6% | <i>\$11,409.11</i> |
| EWP Premier 4HR ONSITE 48038 | 98008-48038 | \$ 4,826.00 | 6% | <i>\$4,570.46</i> |
| EWP Premier 4HR ONSITE 48039 | 98008-48039 | \$ 4,826.00 | 6% | <i>\$4,570.46</i> |
| EWP Premier 4HR ONSITE 48040 | 98008-48040 | \$ 4,546.00 | 6% | <i>\$4,305.29</i> |
| EWP Premier 4HR ONSITE 48041 | 98008-48041 | \$ 4,826.00 | 6% | <i>\$4,570.46</i> |

| | | | | |
|--|-----------------------------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE 48046 | 98008-48046 | \$ 6,338.00 | 6% | <i>\$6,002.40</i> |
| EWP Premier 4HR ONSITE 48047 | 98008-48047 | \$ 16,886.00 | 6% | <i>\$15,991.89</i> |
| EWP Premier 4HR ONSITE 48051 | 98008-48051 | \$ 11,614.00 | 6% | <i>\$10,999.04</i> |
| EWP Premier 4HR ONSITE 48061 | 98008-48061 | \$ 13,574.00 | 6% | <i>\$12,855.26</i> |
| EWP Premier 4HR ONSITE 48062 | 98008-48062 | \$ 21,712.00 | 6% | <i>\$20,562.35</i> |
| EWP Premier 4HR ONSITE 5320-16P-4XE | 98008-5320- 16P-4XE | \$ 478.00 | 6% | <i>\$452.69</i> |
| EWP Premier 4HR ONSITE 5320-16P-4XE-DC | 98008-5320- 16P-4XE-DC | \$ 578.00 | 6% | <i>\$547.39</i> |
| EWP Premier 4HR ONSITE 5320-24P-8XE | 98008-5320- 24P-8XE | \$ 518.00 | 6% | <i>\$490.57</i> |
| EWP Premier 4HR Onsi 5320- 24T-24S-4XE-XT | 98008-5320- 24T-24S-4XE- XT | \$ 708.00 | 6% | <i>\$670.51</i> |
| EWP Premier 4HR ONSITE 5320-24T-4X-XT | 98008-5320- 24T-4X-XT | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWP Premier 4HR ONSITE 5320-24T-8XE | 98008-5320- 24T-8XE | \$ 372.00 | 6% | <i>\$352.30</i> |
| EWP Premier 4HR ONSITE 5320-48P-8XE | 98008-5320- 48P-8XE | \$ 870.00 | 6% | <i>\$823.93</i> |
| EWP Premier 4HR ONSITE 5320-48T-8XE | 98008-5320- 48T-8XE | \$ 605.00 | 6% | <i>\$572.97</i> |
| EWP Prem 4HR ONSITE 5420F- 16MW-32P-4XE | 98008-5420F- 16MW-32P- 4XE | \$ 1,599.00 | 6% | <i>\$1,514.33</i> |
| EWP Premier 4HR ONSITE 5420F-16W-32P-4XE | 98008-5420F- 16W-32P-4XE | \$ 1,555.00 | 6% | <i>\$1,472.66</i> |
| EWP Premier 4HR ONSITE 5420F-24P-4XE | 98008-5420F- 24P-4XE | \$ 693.00 | 6% | <i>\$656.31</i> |
| EWP Premier 4HR ONSITE 5420F-24S-4XE | 98008-5420F- 24S-4XE | \$ 762.00 | 6% | <i>\$721.65</i> |
| EWP Premier 4HR ONSITE 5420F-24T-4XE | 98008-5420F- 24T-4XE | \$ 571.00 | 6% | <i>\$540.77</i> |
| EWP Premier 4HR ONSITE 5420F-48P-4XE | 98008-5420F- 48P-4XE | \$ 1,079.00 | 6% | <i>\$1,021.87</i> |
| EWP Premier 4HR ONSITE 5420F-48P-4XL | 98008-5420F- 48P-4XL | \$ 1,222.00 | 6% | <i>\$1,157.30</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EWP Premier 4HR ONSITE 5420F-48T-4XE | 98008-5420F- 48T-4XE | \$ 791.00 | 6% | <i>\$749.12</i> |
| EWP Premier 4HR ONSITE 5420F-8W-16P-4XE | 98008-5420F- 8W-16P-4XE | \$ 812.00 | 6% | <i>\$769.00</i> |
| EWP Prem 4HR ONSITE 5420M- 16MW-32P-4YE | 98008-5420M- 16MW-32P- 4YE | \$ 1,798.00 | 6% | <i>\$1,702.80</i> |
| EWP Premier 4HR ONSITE 5420M-24T-4YE | 98008-5420M- 24T-4YE | \$ 779.00 | 6% | <i>\$737.75</i> |
| EWP Premier 4HR ONSITE 5420M-24W-4YE | 98008-5420M- 24W-4YE | \$ 710.00 | 6% | <i>\$672.41</i> |
| EWP Premier 4HR ONSITE 5420M-48T-4YE | 98008-5420M- 48T-4YE | \$ 1,067.00 | 6% | <i>\$1,010.50</i> |
| EWP Premier 4HR ONSITE 5420M-48W-4YE | 98008-5420M- 48W-4YE | \$ 1,223.00 | 6% | <i>\$1,158.24</i> |
| EWP PREMIER 4HR ONSITE 5520-12MW-36W | 98008-5520- 12MW-36W | \$ 1,934.00 | 6% | <i>\$1,831.59</i> |
| EWP PREMIER 4HR ONSITE 5520-24T | 98008-5520- 24T | \$ 681.00 | 6% | <i>\$644.94</i> |
| EWP PREMIER 4HR ONSIT 5520-24T-ACDC-BASE | 98008-5520- 24T-ACDC- BASE | \$ 681.00 | 6% | <i>\$644.94</i> |
| EWP PREMIER 4HR ONSITE 5520-24T-BASE | 98008-5520- 24T-BASE | \$ 681.00 | 10% | <i>\$617.50</i> |
| EWP PREMIER 4HR ONSITE 5520-24W | 98008-5520- 24W | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| EWP PREMIER 4HR ONSITE 5520-24X | 98008-5520- 24X | \$ 1,956.00 | 6% | <i>\$1,852.43</i> |
| EWP PREMIER 4HR ONSIT 5520-24X-ACDC-BASE | 98008-5520- 24X-ACDC- BASE | \$ 1,956.00 | 6% | <i>\$1,852.43</i> |
| EWP PREMIER 4HR ONSITE 5520-24X-BASE | 98008-5520- 24X-BASE | \$ 1,956.00 | 10% | <i>\$1,773.60</i> |
| EWP PREMIER 4HR ONSITE 5520-48SE | 98008-5520- 48SE | \$ 2,015.00 | 6% | <i>\$1,908.31</i> |
| EWP PREMIER 4HR ONSI 5520-48SE-ACDC-BASE | 98008-5520- 48SE-ACDC- BASE | \$ 2,015.00 | 6% | <i>\$1,908.31</i> |
| EWP PREMIER 4HR ONSITE 5520-48SE-BASE | 98008-5520- 48SE-BASE | \$ 2,015.00 | 10% | <i>\$1,827.10</i> |
| EWP PREMIER 4HR ONSITE 5520-48T | 98008-5520- 48T | \$ 1,196.00 | 6% | <i>\$1,132.67</i> |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EWP PREMIER 4HR ONSIT 5520-48T-ACDC-BASE | 98008-5520- 48T-ACDC- BASE | \$ 1,196.00 | 6% | <i>\$1,132.67</i> |
| EWP PREMIER 4HR ONSITE 5520-48T-BASE | 98008-5520- 48T-BASE | \$ 1,196.00 | 10% | <i>\$1,084.47</i> |
| EWP PREMIER 4HR ONSITE 5520-48W | 98008-5520- 48W | \$ 1,517.00 | 6% | <i>\$1,436.67</i> |
| EWP Premier 4HR ONSITE 5720-24MW | 98008-5720- 24MW | \$ 2,350.00 | 6% | <i>\$2,225.57</i> |
| EWP Premier 4HR ONSITE 5720-24MXW | 98008-5720- 24MXW | \$ 3,178.00 | 6% | <i>\$3,009.72</i> |
| EWP Premier 4HR ONSITE 5720-48MW | 98008-5720- 48MW | \$ 2,764.00 | 6% | <i>\$2,617.65</i> |
| EWP Premier 4HR ONSITE 5720-48MXW | 98008-5720- 48MXW | \$ 4,007.00 | 6% | <i>\$3,794.83</i> |
| EWP Premier 4HR ONSITE 7520-48XT-6C | 98008-7520- 48XT-6C | \$ 4,569.00 | 6% | <i>\$4,327.07</i> |
| EWP Premier 4HR ONSITE 7520-48XT-6C-AC-F | 98008-7520- 48XT-6C-AC- F | \$ 4,569.00 | 6% | <i>\$4,327.07</i> |
| EWP Premier 4HR ONSITE 7520-48XT-6C-AC-R | 98008-7520- 48XT-6C-AC- R | \$ 4,569.00 | 6% | <i>\$4,327.07</i> |
| EWP Premier 4HR ONSITE 7520-48Y-8C | 98008-7520- 48Y-8C | \$ 4,267.00 | 6% | <i>\$4,041.06</i> |
| EWP Premier 4HR ONSITE 7520-48Y-8C-AC-F | 98008-7520- 48Y-8C-AC-F | \$ 4,267.00 | 6% | <i>\$4,041.06</i> |
| EWP Premier 4HR ONSITE 7520-48Y-8C-AC-R | 98008-7520- 48Y-8C-AC-R | \$ 4,267.00 | 6% | <i>\$4,041.06</i> |
| EWP PREMIER 4HR ONSITE 7520-48YE-8CE | 98008-7520- 48YE-8CE | \$ 4,952.00 | 6% | <i>\$4,689.79</i> |
| EWP PREMIER 4HR ONSIT 7520-48YE-8CE-AC-F | 98008-7520- 48YE-8CE-AC- F | \$ 4,952.00 | 6% | <i>\$4,689.79</i> |
| EWP PREMIER 4HR ONSIT 7520-48YE-8CE-AC-R | 98008-7520- 48YE-8CE-AC- R | \$ 4,952.00 | 6% | <i>\$4,689.79</i> |
| EWP Premier 4HR ONSITE 7720-32C | 98008-7720- 32C | \$ 5,278.00 | 6% | <i>\$4,998.53</i> |
| EWP Premier 4HR ONSITE 7720-32C-AC-F | 98008-7720- 32C-AC-F | \$ 5,278.00 | 6% | <i>\$4,998.53</i> |
| EWP Premier 4HR ONSITE 7720-32C-AC-R | 98008-7720- 32C-AC-R | \$ 5,278.00 | 6% | <i>\$4,998.53</i> |

| | | | | |
|---|---------------------------------|--------------|----|------------|
| EWP Premier 4HR ONSITE 8520-48XT-6C | 98008-8520- 48XT-6C | \$ 4,036.00 | 6% | \$3,822.29 |
| EWP Premier 4HR ONSITE 8520-48XT-6C-AC-F | 98008-8520- 48XT-6C-AC- F | \$ 4,036.00 | 6% | \$3,822.29 |
| EWP Premier 4HR ONSITE 8520-48XT-6C-AC-R | 98008-8520- 48XT-6C-AC- R | \$ 4,036.00 | 6% | \$3,822.29 |
| EWP Premier 4HR ONSITE 8520-48XT-6C-DC-F | 98008-8520- 48XT-6C-DC- F | \$ 4,036.00 | 6% | \$3,822.29 |
| EWP Premier 4HR ONSITE 8520-48XT-6C-DC-R | 98008-8520- 48XT-6C-DC- R | \$ 4,036.00 | 6% | \$3,822.29 |
| EWP Premier 4HR ONSITE 8520-48Y-8C | 98008-8520- 48Y-8C | \$ 4,136.00 | 6% | \$3,917.00 |
| EWP Premier 4HR ONSITE 8520-48Y-8C-AC-F | 98008-8520- 48Y-8C-AC-F | \$ 4,136.00 | 6% | \$3,917.00 |
| EWP Premier 4HR ONSITE 8520-48Y-8C-AC-R | 98008-8520- 48Y-8C-AC-R | \$ 4,136.00 | 6% | \$3,917.00 |
| EWP Premier 4HR ONSITE 8520-48Y-8C-DC-F | 98008-8520- 48Y-8C-DC-F | \$ 4,136.00 | 6% | \$3,917.00 |
| EWP Premier 4HR ONSITE 8520-48Y-8C-DC-R | 98008-8520- 48Y-8C-DC-R | \$ 4,136.00 | 6% | \$3,917.00 |
| EWP Premier 4HR ONSITE 86100 | 98008-86100 | \$ 7,406.00 | 6% | \$7,013.85 |
| EWP Premier 4HR ONSITE 86101 | 98008-86101 | \$ 10,178.00 | 6% | \$9,639.07 |
| EWP Premier 4HR ONSITE 87100 | 98008-87100 | \$ 4,600.00 | 6% | \$4,356.43 |
| EWP Premier 4HR ONSITE 87101 | 98008-87101 | \$ 7,071.00 | 6% | \$6,696.59 |
| EWP Premier 4HR ONSITE 8720-32C | 98008-8720- 32C | \$ 4,626.00 | 6% | \$4,381.05 |
| EWP Premier 4HR ONSITE 8720-32C-AC-F | 98008-8720- 32C-AC-F | \$ 4,627.00 | 6% | \$4,382.00 |
| EWP Premier 4HR ONSITE 8720-32C-AC-R | 98008-8720- 32C-AC-R | \$ 4,627.00 | 6% | \$4,382.00 |
| EWP Premier 4HR ONSITE 8720-32C-DC-F | 98008-8720- 32C-DC-F | \$ 4,626.00 | 6% | \$4,381.05 |
| EWP Premier 4HR ONSITE 8720-32C-DC-R | 98008-8720- 32C-DC-R | \$ 4,626.00 | 6% | \$4,381.05 |

| | | | | |
|---|-------------------------|--------------|-----|--------------------|
| EWP Premier 4HR ONSITE 8806 | 98008-8806 | \$ 3,021.00 | 6% | <i>\$2,861.04</i> |
| EWP Premier 4HR ONSITE 8810 | 98008-8810 | \$ 7,844.00 | 6% | <i>\$7,428.66</i> |
| EWP Premier 4HR ONSITE 88100 | 98008-88100 | \$ 8,363.00 | 6% | <i>\$7,920.18</i> |
| EWP Premier 4HR ONSITE 8820-40C | 98008-8820- 40C | \$ 19,708.00 | 10% | <i>\$17,870.23</i> |
| EWP Premier 4HR ONSITE 8820-40C-AC-F | 98008-8820- 40C-AC-F | \$ 19,708.00 | 10% | <i>\$17,870.23</i> |
| EWP Premier 4HR ONSITE 8820-40C-AC-R | 98008-8820- 40C-AC-R | \$ 19,708.00 | 10% | <i>\$17,870.23</i> |
| EWP Premier 4HR ONSITE 8820-40C-DC-F | 98008-8820- 40C-DC-F | \$ 19,708.00 | 10% | <i>\$17,870.23</i> |
| EWP Premier 4HR ONSITE 8820-40C-DC-R | 98008-8820- 40C-DC-R | \$ 19,708.00 | 10% | <i>\$17,870.23</i> |
| EWP Premier 4HR ONSITE 8820-80C | 98008-8820- 80C | \$ 35,978.00 | 10% | <i>\$32,623.05</i> |
| EWP Premier 4HR ONSITE 8820-80C-AC-F | 98008-8820- 80C-AC-F | \$ 35,978.00 | 10% | <i>\$32,623.05</i> |
| EWP Premier 4HR ONSITE 8820-80C-AC-R | 98008-8820- 80C-AC-R | \$ 35,978.00 | 10% | <i>\$32,623.05</i> |
| EWP Premier 4HR ONSITE 8820-80C-DC-F | 98008-8820- 80C-DC-F | \$ 35,978.00 | 10% | <i>\$32,623.05</i> |
| EWP Premier 4HR ONSITE 8820-80C-DC-R | 98008-8820- 80C-DC-R | \$ 35,978.00 | 10% | <i>\$32,623.05</i> |
| EWP Premier 4HR ONSITE 9920-16C | 98008-9920- 16C | \$ 15,248.00 | 6% | <i>\$14,440.62</i> |
| EWP Premier 4HR ONSITE 9920-4D | 98008-9920-4D | \$ 15,248.00 | 6% | <i>\$14,440.62</i> |
| EWP Premier 4HR ONSITE 9920-NPB-8 | 98008-9920- NPB-8 | \$ 23,776.00 | 6% | <i>\$22,517.06</i> |
| EWP Premier 4HR ONSITE A10148 | 98008-A10148 | \$ 4,041.00 | 6% | <i>\$3,827.03</i> |
| EWP Premier 4HR ONSITE A10149 | 98008-A10149 | \$ 7,698.00 | 6% | <i>\$7,290.39</i> |
| EWP Premier 4HR ONSITE A10152 | 98008-A10152 | \$ 7,698.00 | 6% | <i>\$7,290.39</i> |
| EWP Premier 4HR ONSITE A10154 | 98008-A10154 | \$ 23,044.00 | 6% | <i>\$21,823.82</i> |
| EWP Premier 4HR ONSITE A10155 | 98008-A10155 | \$ 8,308.00 | 6% | <i>\$7,868.09</i> |

| | | | | |
|--|-------------------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE A10157 | 98008-A10157 | \$ 14,394.00 | 6% | <i>\$13,631.84</i> |
| EWP Premier 4HR ONSITE A10175 | 98008-A10175 | \$ 11,079.00 | 6% | <i>\$10,492.37</i> |
| EWP Premier 4HR ONSITE A10176 | 98008-A10176 | \$ 16,617.00 | 6% | <i>\$15,737.13</i> |
| EWP Premier 4HR ONSITE AH-AP-1130-AC-CE | 98008-AH-AP-1130-AC-CE | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-1130-AC-FCC | 98008-AH-AP-1130-AC-FCC | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-1130-AC-W | 98008-AH-AP-1130-AC-W | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-122-AC-CAN | 98008-AH-AP-122-AC-CAN | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-122-AC-CE | 98008-AH-AP-122-AC-CE | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-122-AC-FCC | 98008-AH-AP-122-AC-FCC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-122-AC-W | 98008-AH-AP-122-AC-W | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-130-AC-CE | 98008-AH-AP-130-AC-CE | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-130-AC-FCC | 98008-AH-AP-130-AC-FCC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-130-AC-W | 98008-AH-AP-130-AC-W | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-150W-AC-CAN | 98008-AH-AP-150W-AC-CAN | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-150W-AC-CE | 98008-AH-AP-150W-AC-CE | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-150W-AC-FCC | 98008-AH-AP-150W-AC-FCC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-150W-AC-W | 98008-AH-AP-150W-AC-W | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-230-AC-CE | 98008-AH-AP-230-AC-CE | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-230-AC-FCC | 98008-AH-AP-230-AC-FCC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-230-AC-W | 98008-AH-AP-230-AC-W | \$ 125.00 | 6% | <i>\$118.38</i> |

| | | | | |
|--|-------------------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE AH-AP-250-AC-CAN | 98008-AH-AP-250-AC-CAN | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-250-AC-CE | 98008-AH-AP-250-AC-CE | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-250-AC-FCC | 98008-AH-AP-250-AC-FCC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-250-AC-W | 98008-AH-AP-250-AC-W | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-AP-630-AX-CAN | 98008-AH-AP-630-AX-CAN | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR ONSITE AH-AP-630-AX-CE | 98008-AH-AP-630-AX-CE | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR ONSITE AH-AP-630-AX-FCC | 98008-AH-AP-630-AX-FCC | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR ONSITE AH-AP-630-AX-W | 98008-AH-AP-630-AX-W | \$ 182.00 | 6% | <i>\$172.36</i> |
| EWP Premier 4HR ONSITE AH-AP-650-AX-CAN | 98008-AH-AP-650-AX-CAN | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-650-AX-CE | 98008-AH-AP-650-AX-CE | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-650-AX-FCC | 98008-AH-AP-650-AX-FCC | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-650-AX-W | 98008-AH-AP-650-AX-W | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-650X-AX-CAN | 98008-AH-AP-650X-AX-CAN | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-650X-AX-CE | 98008-AH-AP-650X-AX-CE | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-650X-AX-FCC | 98008-AH-AP-650X-AX-FCC | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-AP-650X-AX-W | 98008-AH-AP-650X-AX-W | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier 4HR ONSITE AH-ATOM-CAN | 98008-AH-ATOM-CAN | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR ONSITE AH-ATOM-CE-EU | 98008-AH-ATOM-CE-EU | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier 4HR ONSITE AH-ATOM-CE-UK | 98008-AH-ATOM-CE-UK | \$ 130.00 | 6% | <i>\$123.12</i> |

| | | | | |
|---------------------------------------|----------------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE AH-ATOM-FCC | 98008-AH-ATOM-FCC | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier 4HR ONSITE AH-ATOM-W | 98008-AH-ATOM-W | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier 4HR ONSITE AH-ATOM-W-EU | 98008-AH-ATOM-W-EU | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier 4HR ONSITE AH-ATOM-W-UK | 98008-AH-ATOM-W-UK | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier 4HR ONSITE AH-SR-2208P-AU | 98008-AH-SR-2208P-AU | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-SR-2208P-EU | 98008-AH-SR-2208P-EU | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-SR-2208P-NA | 98008-AH-SR-2208P-NA | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-SR-2208P-UK | 98008-AH-SR-2208P-UK | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH-SR-2224P-AU | 98008-AH-SR-2224P-AU | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AH-SR-2224P-EU | 98008-AH-SR-2224P-EU | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AH-SR-2224P-NA | 98008-AH-SR-2224P-NA | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AH-SR-2224P-UK | 98008-AH-SR-2224P-UK | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AH-SR-2324P-AU | 98008-AH-SR-2324P-AU | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier 4HR ONSITE AH-SR-2324P-EU | 98008-AH-SR-2324P-EU | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier 4HR ONSITE AH-SR-2324P-NA | 98008-AH-SR-2324P-NA | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier 4HR ONSITE AH-SR-2324P-UK | 98008-AH-SR-2324P-UK | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier 4HR ONSITE AH-SR-2348P-AU | 98008-AH-SR-2348P-AU | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWP Premier 4HR ONSITE AH-SR-2348P-EU | 98008-AH-SR-2348P-EU | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWP Premier 4HR ONSITE AH-SR-2348P-NA | 98008-AH-SR-2348P-NA | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWP Premier 4HR ONSITE AH-SR-2348P-UK | 98008-AH-SR-2348P-UK | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWP Premier 4HR ONSITE AH-XR200P-AU | 98008-AH-XR200P-AU | \$ 125.00 | 6% | <i>\$118.38</i> |

| | | | | |
|--|---------------------------------|-----------|-----|-----------------|
| EWP Premier 4HR ONSITE AH- XR200P-EU | 98008-AH- XR200P-EU | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH- XR200P-UK | 98008-AH- XR200P-UK | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH- XR200P-US | 98008-AH- XR200P-US | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier 4HR ONSITE AH- XR600P | 98008-AH- XR600P | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier 4HR ONSITE AH- XR600P-AU | 98008-AH- XR600P-AU | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier 4HR ONSITE AH- XR600P-EU | 98008-AH- XR600P-EU | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier 4HR ONSITE AH- XR600P-KR | 98008-AH- XR600P-KR | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier 4HR ONSITE AH- XR600P-UK | 98008-AH- XR600P-UK | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier 4HR ONSITE AH- XR600P-US | 98008-AH- XR600P-US | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier 4HR ONSITE AP- 8533-68SB30-IL | 98008-AP- 8533-68SB30- IL | \$ 232.00 | 6% | <i>\$219.72</i> |
| EWP Premier 4HR ONSITE AP3000-IL | 98008-AP3000- IL | \$ 102.15 | 6% | <i>\$96.74</i> |
| EWP Premier 4HR ONSITE AP3000-TN | 98008-AP3000- TN | \$ 102.15 | 6% | <i>\$96.74</i> |
| EWP Premier 4HR ONSITE AP3000-WW | 98008-AP3000- WW | \$ 102.15 | 6% | <i>\$96.74</i> |
| EWP Premier 4HR ONSITE AP3000X-WW | 98008- AP3000X-WW | \$ 130.53 | 6% | <i>\$123.61</i> |
| EWP Premier 4HR ONSITE AP302W-CAN | 98008- AP302W-CAN | \$ 93.00 | 6% | <i>\$88.08</i> |
| EWP Premier 4HR ONSITE AP302W-EG | 98008- AP302W-EG | \$ 101.00 | 10% | <i>\$91.58</i> |
| EWP Premier 4HR ONSITE AP302W-FCC | 98008- AP302W-FCC | \$ 93.00 | 6% | <i>\$88.08</i> |
| EWP Premier 4HR ONSITE AP302W-WR | 98008- AP302W-WR | \$ 92.00 | 6% | <i>\$87.13</i> |
| EWP Premier 4HR ONSITE AP305C-1-CAN | 98008-AP305C- 1-CAN | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR ONSITE AP305C-1-EG | 98008-AP305C- 1-EG | \$ 122.00 | 6% | <i>\$115.54</i> |

| | | | | |
|---------------------------------------|---------------------------|-----------|-----|-----------------|
| EWP Premier 4HR ONSITE AP305C-FCC | 98008-AP305C- 1-FCC | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR ONSITE AP305C-1-IL | 98008-AP305C- 1-IL | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR ONSITE AP305C-1-WR | 98008-AP305C- 1-WR | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR ONSITE AP305C-CAN | 98008-AP305C- CAN | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305C-EG | 98008-AP305C- EG | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305C-FCC | 98008-AP305C- FCC | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305C-IL | 98008-AP305C- IL | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305C-WR | 98008-AP305C- WR | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305CX-CAN | 98008- AP305CX- CAN | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305CX-FCC | 98008- AP305CX- FCC | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305CX-IL | 98008- AP305CX-IL | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP305CX-WR | 98008- AP305CX-WR | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier 4HR ONSITE AP310e-1-WR | 98008-AP310e- 1-WR | \$ 78.00 | 10% | <i>\$70.73</i> |
| EWP Premier 4HR ONSITE AP310e-CAN | 98008-AP310e- CAN | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE AP310e-FCC | 98008-AP310e- FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE AP310e-IL | 98008-AP310e- IL | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE AP310e-WR | 98008-AP310e- WR | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE AP310i-1-WR | 98008-AP310i- 1-WR | \$ 78.00 | 10% | <i>\$70.73</i> |
| EWP Premier 4HR ONSITE AP310i-CAN | 98008-AP310i- CAN | \$ 82.00 | 6% | <i>\$77.66</i> |

| | | | | |
|--|------------------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE AP310i-FCC | 98008-AP310i- FCC | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE AP310i-IL | 98008-AP310i- IL | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE AP310i-WR | 98008-AP310i- WR | \$ 82.00 | 6% | <i>\$77.66</i> |
| EWP Premier 4HR ONSITE AP360e-CAN | 98008-AP360e- CAN | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR ONSITE AP360e-FCC | 98008-AP360e- FCC | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR ONSITE AP360e-IL | 98008-AP360e- IL | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR ONSITE AP360e-WR | 98008-AP360e- WR | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR ONSITE AP360i-CAN | 98008-AP360i- CAN | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR ONSITE AP360i-FCC | 98008-AP360i- FCC | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR ONSITE AP360i-WR | 98008-AP360i- WR | \$ 119.00 | 6% | <i>\$112.70</i> |
| EWP Premier 4HR ONSITE AP4000-WW | 98008-AP4000- 1-WW | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE AP4000-IL | 98008-AP4000- IL | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE AP4000-WW | 98008-AP4000- WW | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE AP410C-1-CAN | 98008-AP410C- 1-CAN | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier 4HR ONSITE AP410C-1-EG | 98008-AP410C- 1-EG | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier 4HR ONSITE AP410C-1-FCC | 98008-AP410C- 1-FCC | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier 4HR ONSITE AP410C-1-IL | 98008-AP410C- 1-IL | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier 4HR ONSITE AP410C-1-WR | 98008-AP410C- 1-WR | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier 4HR ONSITE AP410C-CAN | 98008-AP410C- CAN | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE AP410C-EG | 98008-AP410C- EG | \$ 144.00 | 6% | <i>\$136.38</i> |

| | | | | |
|--|------------------------|-----------|-----|-----------------|
| EWP Premier 4HR ONSITE AP410C-FCC | 98008-AP410C- FCC | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE AP410C-IL | 98008-AP410C- IL | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE AP410C-WR | 98008-AP410C- WR | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE AP410e-CAN | 98008-AP410e- CAN | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE AP410e-FCC | 98008-AP410e- FCC | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE AP410e-WR | 98008-AP410e- WR | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE AP410i-1-FCC | 98008-AP410i- 1-FCC | \$ 139.00 | 10% | <i>\$126.04</i> |
| EWP Premier 4HR ONSITE AP410i-1-WR | 98008-AP410i- 1-WR | \$ 139.00 | 10% | <i>\$126.04</i> |
| EWP Premier 4HR ONSITE AP410i-CAN | 98008-AP410i- CAN | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE AP410i-FCC | 98008-AP410i- FCC | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE AP410i-IL | 98008-AP410i- IL | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE AP410i-WR | 98008-AP410i- WR | \$ 146.00 | 6% | <i>\$138.27</i> |
| EWP Premier 4HR ONSITE AP460C-CAN | 98008-AP460C- CAN | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460C-EG | 98008-AP460C- EG | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460C-FCC | 98008-AP460C- FCC | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460C-IL | 98008-AP460C- IL | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460C-WR | 98008-AP460C- WR | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460e-CAN | 98008-AP460e- CAN | \$ 170.00 | 6% | <i>\$161.00</i> |
| EWP Premier 4HR ONSITE AP460e-FCC | 98008-AP460e- FCC | \$ 170.00 | 6% | <i>\$161.00</i> |
| EWP Premier 4HR ONSITE AP460e-WR | 98008-AP460e- WR | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier 4HR ONSITE AP460i-CAN | 98008-AP460i- CAN | \$ 163.00 | 6% | <i>\$154.37</i> |

| | | | | |
|--|-----------------------------|-----------|-----|-----------------|
| EWP Premier 4HR ONSITE AP460i-FCC | 98008-AP460i- FCC | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier 4HR ONSITE AP460i-IL | 98008-AP460i- IL | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier 4HR ONSITE AP460i-WR | 98008-AP460i- WR | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier 4HR ONSITE AP460S12C-CAN | 98008- AP460S12C- CAN | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460S12C-FCC | 98008- AP460S12C- FCC | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460S12C-WR | 98008- AP460S12C- WR | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460S6C-CAN | 98008- AP460S6C- CAN | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460S6C-FCC | 98008- AP460S6C- FCC | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP460S6C-WR | 98008- AP460S6C- WR | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier 4HR ONSITE AP5010-IL | 98008-AP5010- IL | \$ 229.00 | 6% | <i>\$216.87</i> |
| EWP Premier 4HR ONSITE AP5010-WW | 98008-AP5010- WW | \$ 229.00 | 10% | <i>\$207.65</i> |
| EWP Premier 4HR ONSITE AP5020-WW | 98008-AP5020- WW | \$ 272.29 | 6% | <i>\$257.87</i> |
| EWP Premier 4HR ONSITE AP5050D-WW | 98008- AP5050D-WW | \$ 523.00 | 6% | <i>\$495.31</i> |
| EWP Premier 4HR ONSITE AP5050U-WW | 98008- AP5050U-WW | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWP Premier 4HR ONSITE AP505i-FCC | 98008-AP505i- FCC | \$ 175.00 | 6% | <i>\$165.73</i> |
| EWP Premier 4HR ONSITE AP505i-FCC-TAA | 98008-AP505i- FCC-TAA | \$ 175.00 | 6% | <i>\$165.73</i> |
| EWP Premier 4HR ONSITE AP505i-WR | 98008-AP505i- WR | \$ 184.00 | 6% | <i>\$174.26</i> |
| EWP Premier 4HR ONSITE AP510C-CAN | 98008-AP510C- CAN | \$ 168.00 | 6% | <i>\$159.10</i> |

| | | | | |
|--|---------------------------|-----------|-----|-----------------|
| EWP Premier 4HR ONSITE AP510C-CE | 98008-AP510C- CE | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR ONSITE AP510C-FCC | 98008-AP510C- FCC | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR ONSITE AP510C-W | 98008-AP510C- W | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR ONSITE AP510C-WW | 98008-AP510C- WW | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier 4HR ONSITE AP510CX-CAN | 98008- AP510CX- CAN | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR ONSITE AP510CX-CE | 98008- AP510CX-CE | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR ONSITE AP510CX-FCC | 98008- AP510CX- FCC | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR ONSITE AP510CX-W | 98008- AP510CX-W | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier 4HR ONSITE AP510CX-WW | 98008- AP510CX-WW | \$ 195.00 | 6% | <i>\$184.67</i> |
| EWP Premier 4HR ONSITE AP510e-FCC | 98008-AP510e- FCC | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier 4HR ONSITE AP510e-FCC-TAA | 98008-AP510e- FCC-TAA | \$ 233.00 | 6% | <i>\$220.66</i> |
| EWP Premier 4HR ONSITE AP510e-WR | 98008-AP510e- WR | \$ 222.00 | 6% | <i>\$210.25</i> |
| EWP Premier 4HR ONSITE AP510i-1-FCC | 98008-AP510i- 1-FCC | \$ 197.00 | 10% | <i>\$178.63</i> |
| EWP Premier 4HR ONSITE AP510i-1-WR | 98008-AP510i- 1-WR | \$ 197.00 | 10% | <i>\$178.63</i> |
| EWP Premier 4HR ONSITE AP510i-FCC | 98008-AP510i- FCC | \$ 206.00 | 6% | <i>\$195.09</i> |
| EWP Premier 4HR ONSITE AP510i-FCC-TAA | 98008-AP510i- FCC-TAA | \$ 206.00 | 6% | <i>\$195.09</i> |
| EWP Premier 4HR ONSITE AP510i-WR | 98008-AP510i- WR | \$ 206.00 | 6% | <i>\$195.09</i> |
| EWP Premier 4HR ONSITE AP560h-FCC | 98008-AP560h- FCC | \$ 513.00 | 6% | <i>\$485.84</i> |
| EWP Premier 4HR ONSITE AP560h-WR | 98008-AP560h- WR | \$ 513.00 | 6% | <i>\$485.84</i> |

| | | | | |
|--------------------------------------|----------------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE AP560i-FCC | 98008-AP560i- FCC | \$ 374.00 | 6% | <i>\$354.20</i> |
| EWP Premier 4HR ONSITE AP560i-WR | 98008-AP560i- WR | \$ 357.00 | 6% | <i>\$338.10</i> |
| EWP Premier 4HR ONSITE AP560m-FCC | 98008-AP560m- FCC | \$ 374.00 | 6% | <i>\$354.20</i> |
| EWP Premier 4HR ONSITE AP560t-FCC | 98008-AP560t- FCC | \$ 513.00 | 6% | <i>\$485.84</i> |
| EWP Premier 4HR ONSITE AP560u-FCC | 98008-AP560u- FCC | \$ 348.00 | 6% | <i>\$329.57</i> |
| EWP Premier 4HR ONSITE E2122 | 98008-E2122 | \$ 8,817.00 | 6% | <i>\$8,350.14</i> |
| EWP Premier 4HR ONSITE E2122-1 | 98008-E2122-1 | \$ 8,397.00 | 6% | <i>\$7,952.38</i> |
| EWP Premier 4HR ONSITE E3120-1 | 98008-E3120-1 | \$ 13,736.00 | 6% | <i>\$13,008.68</i> |
| EWP Premier 4HR ONSITE E3125 | 98008-E3125 | \$ 14,475.00 | 6% | <i>\$13,708.55</i> |
| EWP Premier 4HR ONSITE H30078 | 98008-H30078 | \$ 4,618.00 | 6% | <i>\$4,373.48</i> |
| EWP Premier 4HR ONSITE H30104 | 98008-H30104 | \$ 4,190.00 | 6% | <i>\$3,968.14</i> |
| EWP Premier 4HR ONSITE H30105 | 98008-H30105 | \$ 4,220.00 | 6% | <i>\$3,996.55</i> |
| EWP Premier 4HR ONSITE H30131 | 98008-H30131 | \$ 2,413.00 | 6% | <i>\$2,285.23</i> |
| EWP Premier 4HR ONSITE H30132 | 98008-H30132 | \$ 2,367.00 | 6% | <i>\$2,241.67</i> |
| EWP Premier 4HR ONSITE H30133 | 98008-H30133 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30134 | 98008-H30134 | \$ 7,890.00 | 6% | <i>\$7,472.22</i> |
| EWP Premier 4HR ONSITE H30135 | 98008-H30135 | \$ 6,353.00 | 6% | <i>\$6,016.61</i> |
| EWP Premier 4HR ONSITE H30136 | 98008-H30136 | \$ 7,890.00 | 6% | <i>\$7,472.22</i> |
| EWP Premier 4HR ONSITE H30184 | 98008-H30184 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier 4HR ONSITE H30185 | 98008-H30185 | \$ 560.00 | 6% | <i>\$530.35</i> |
| EWP Premier 4HR ONSITE H30186 | 98008-H30186 | \$ 287.00 | 6% | <i>\$271.80</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE H30187 | 98008-H30187 | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR ONSITE H30188 | 98008-H30188 | \$ 287.00 | 6% | <i>\$271.80</i> |
| EWP Premier 4HR ONSITE H30189 | 98008-H30189 | \$ 287.00 | 6% | <i>\$271.80</i> |
| EWP Premier 4HR ONSITE H30190 | 98008-H30190 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30214 | 98008-H30214 | \$ 301.00 | 6% | <i>\$285.06</i> |
| EWP Premier 4HR ONSITE H30215 | 98008-H30215 | \$ 301.00 | 6% | <i>\$285.06</i> |
| EWP Premier 4HR ONSITE H30216 | 98008-H30216 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30217 | 98008-H30217 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30218 | 98008-H30218 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30219 | 98008-H30219 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30220 | 98008-H30220 | \$ 941.00 | 6% | <i>\$891.17</i> |
| EWP Premier 4HR ONSITE H30221 | 98008-H30221 | \$ 941.00 | 6% | <i>\$891.17</i> |
| EWP Premier 4HR ONSITE H30222 | 98008-H30222 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30223 | 98008-H30223 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30224 | 98008-H30224 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30225 | 98008-H30225 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H30226 | 98008-H30226 | \$ 941.00 | 6% | <i>\$891.17</i> |
| EWP Premier 4HR ONSITE H30227 | 98008-H30227 | \$ 941.00 | 6% | <i>\$891.17</i> |
| EWP Premier 4HR ONSITE H30228 | 98008-H30228 | \$ 941.00 | 6% | <i>\$891.17</i> |
| EWP Premier 4HR ONSITE H30229 | 98008-H30229 | \$ 941.00 | 6% | <i>\$891.17</i> |
| EWP Premier 4HR ONSITE H30267 | 98008-H30267 | \$ 587.00 | 6% | <i>\$555.92</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR ONSITE H30268 | 98008-H30268 | \$ 587.00 | 6% | \$555.92 |
| EWP Premier 4HR ONSITE H30269 | 98008-H30269 | \$ 941.00 | 6% | \$891.17 |
| EWP Premier 4HR ONSITE H30270 | 98008-H30270 | \$ 941.00 | 6% | \$891.17 |
| EWP Premier 4HR ONSITE H30271 | 98008-H30271 | \$ 941.00 | 6% | \$891.17 |
| EWP Premier 4HR ONSITE H30272 | 98008-H30272 | \$ 941.00 | 6% | \$891.17 |
| EWP Premier 4HR ONSITE H30273 | 98008-H30273 | \$ 1,285.00 | 6% | \$1,216.96 |
| EWP Premier 4HR ONSITE H30274 | 98008-H30274 | \$ 1,285.00 | 6% | \$1,216.96 |
| EWP Premier 4HR ONSITE H30275 | 98008-H30275 | \$ 941.00 | 6% | \$891.17 |
| EWP Premier 4HR ONSITE H30276 | 98008-H30276 | \$ 941.00 | 6% | \$891.17 |
| EWP Premier 4HR ONSITE H30277 | 98008-H30277 | \$ 1,285.00 | 6% | \$1,216.96 |
| EWP Premier 4HR ONSITE H30278 | 98008-H30278 | \$ 1,410.00 | 6% | \$1,335.34 |
| EWP Premier 4HR ONSITE H30279 | 98008-H30279 | \$ 1,285.00 | 6% | \$1,216.96 |
| EWP Premier 4HR ONSITE H30280 | 98008-H30280 | \$ 1,285.00 | 6% | \$1,216.96 |
| EWP Premier 4HR ONSITE H30281 | 98008-H30281 | \$ 1,285.00 | 6% | \$1,216.96 |
| EWP Premier 4HR ONSITE H30282 | 98008-H30282 | \$ 1,285.00 | 6% | \$1,216.96 |
| EWP Premier 4HR ONSITE H30283 | 98008-H30283 | \$ 855.00 | 6% | \$809.73 |
| EWP Premier 4HR ONSITE H30284 | 98008-H30284 | \$ 941.00 | 6% | \$891.17 |
| EWP Premier 4HR ONSITE H30293 | 98008-H30293 | \$ 4,550.00 | 6% | \$4,309.08 |
| EWP Premier 4HR ONSITE H30296 | 98008-H30296 | \$ 301.00 | 6% | \$285.06 |
| EWP Premier 4HR ONSITE H30297 | 98008-H30297 | \$ 301.00 | 6% | \$285.06 |
| EWP Premier 4HR ONSITE H30298 | 98008-H30298 | \$ 301.00 | 6% | \$285.06 |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H30299 | 98008-H30299 | \$ 301.00 | 6% | <i>\$285.06</i> |
| EWP Premier 4HR ONSITE H30381 | 98008-H30381 | \$ 857.00 | 6% | <i>\$811.62</i> |
| EWP Premier 4HR ONSITE H30384 | 98008-H30384 | \$ 690.00 | 6% | <i>\$653.46</i> |
| EWP Premier 4HR ONSITE H30391 | 98008-H30391 | \$ 1,633.00 | 6% | <i>\$1,546.53</i> |
| EWP Premier 4HR ONSITE H30392 | 98008-H30392 | \$ 1,633.00 | 6% | <i>\$1,546.53</i> |
| EWP Premier 4HR ONSITE H30393 | 98008-H30393 | \$ 729.00 | 6% | <i>\$690.40</i> |
| EWP Premier 4HR ONSITE H30394 | 98008-H30394 | \$ 3,154.00 | 6% | <i>\$2,987.00</i> |
| EWP Premier 4HR ONSITE H30395 | 98008-H30395 | \$ 3,758.00 | 6% | <i>\$3,559.01</i> |
| EWP Premier 4HR ONSITE H30396 | 98008-H30396 | \$ 3,423.00 | 6% | <i>\$3,241.75</i> |
| EWP Premier 4HR ONSITE H30397 | 98008-H30397 | \$ 4,065.00 | 6% | <i>\$3,849.76</i> |
| EWP Premier 4HR ONSITE H30398 | 98008-H30398 | \$ 743.00 | 6% | <i>\$703.66</i> |
| EWP Premier 4HR ONSITE H30400 | 98008-H30400 | \$ 414.00 | 6% | <i>\$392.08</i> |
| EWP Premier 4HR ONSITE H30401 | 98008-H30401 | \$ 576.00 | 6% | <i>\$545.50</i> |
| EWP Premier 4HR ONSITE H30402 | 98008-H30402 | \$ 623.00 | 6% | <i>\$590.01</i> |
| EWP Premier 4HR ONSITE H30403 | 98008-H30403 | \$ 920.00 | 6% | <i>\$871.29</i> |
| EWP Premier 4HR ONSITE H30434 | 98008-H30434 | \$ 250.00 | 6% | <i>\$236.76</i> |
| EWP Premier 4HR ONSITE H30480 | 98008-H30480 | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| EWP Premier 4HR ONSITE H30495 | 98008-H30495 | \$ 2,413.00 | 6% | <i>\$2,285.23</i> |
| EWP Premier 4HR ONSITE H30496 | 98008-H30496 | \$ 2,367.00 | 6% | <i>\$2,241.67</i> |
| EWP Premier 4HR ONSITE H30497 | 98008-H30497 | \$ 3,491.00 | 6% | <i>\$3,306.15</i> |
| EWP Premier 4HR ONSITE H30498 | 98008-H30498 | \$ 3,423.00 | 6% | <i>\$3,241.75</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H30499 | 98008-H30499 | \$ 1,171.00 | 6% | <i>\$1,109.00</i> |
| EWP Premier 4HR ONSITE H30501 | 98008-H30501 | \$ 3,423.00 | 6% | <i>\$3,241.75</i> |
| EWP Premier 4HR ONSITE H30502 | 98008-H30502 | \$ 5,266.00 | 6% | <i>\$4,987.17</i> |
| EWP Premier 4HR ONSITE H30503 | 98008-H30503 | \$ 1,171.00 | 6% | <i>\$1,109.00</i> |
| EWP Premier 4HR ONSITE H30505 | 98008-H30505 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30506 | 98008-H30506 | \$ 8,474.00 | 6% | <i>\$8,025.30</i> |
| EWP Premier 4HR ONSITE H30509 | 98008-H30509 | \$ 5,266.00 | 6% | <i>\$4,987.17</i> |
| EWP Premier 4HR ONSITE H30510 | 98008-H30510 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30511 | 98008-H30511 | \$ 8,474.00 | 6% | <i>\$8,025.30</i> |
| EWP Premier 4HR ONSITE H30512 | 98008-H30512 | \$ 1,171.00 | 6% | <i>\$1,109.00</i> |
| EWP Premier 4HR ONSITE H30513 | 98008-H30513 | \$ 1,979.00 | 6% | <i>\$1,874.21</i> |
| EWP Premier 4HR ONSITE H30525 | 98008-H30525 | \$ 8,474.00 | 6% | <i>\$8,025.30</i> |
| EWP Premier 4HR ONSITE H30526 | 98008-H30526 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30528 | 98008-H30528 | \$ 9,831.00 | 6% | <i>\$9,310.45</i> |
| EWP Premier 4HR ONSITE H30531 | 98008-H30531 | \$ 13,989.00 | 6% | <i>\$13,248.28</i> |
| EWP Premier 4HR ONSITE H30532 | 98008-H30532 | \$ 13,989.00 | 6% | <i>\$13,248.28</i> |
| EWP Premier 4HR ONSITE H30534 | 98008-H30534 | \$ 14,260.00 | 6% | <i>\$13,504.93</i> |
| EWP Premier 4HR ONSITE H30535 | 98008-H30535 | \$ 15,216.00 | 6% | <i>\$14,410.31</i> |
| EWP Premier 4HR ONSITE H30536 | 98008-H30536 | \$ 13,989.00 | 6% | <i>\$13,248.28</i> |
| EWP Premier 4HR ONSITE H30537 | 98008-H30537 | \$ 15,216.00 | 6% | <i>\$14,410.31</i> |
| EWP Premier 4HR ONSITE H30538 | 98008-H30538 | \$ 8,474.00 | 6% | <i>\$8,025.30</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H30539 | 98008-H30539 | \$ 16,248.00 | 6% | <i>\$15,387.67</i> |
| EWP Premier 4HR ONSITE H30540 | 98008-H30540 | \$ 16,816.00 | 6% | <i>\$15,925.59</i> |
| EWP Premier 4HR ONSITE H30543 | 98008-H30543 | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWP Premier 4HR ONSITE H30544 | 98008-H30544 | \$ 2,053.00 | 6% | <i>\$1,944.29</i> |
| EWP Premier 4HR ONSITE H30548 | 98008-H30548 | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWP Premier 4HR ONSITE H30549 | 98008-H30549 | \$ 1,941.00 | 6% | <i>\$1,838.22</i> |
| EWP Premier 4HR ONSITE H30550 | 98008-H30550 | \$ 1,941.00 | 6% | <i>\$1,838.22</i> |
| EWP Premier 4HR ONSITE H30552 | 98008-H30552 | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWP Premier 4HR ONSITE H30553 | 98008-H30553 | \$ 1,824.00 | 6% | <i>\$1,727.42</i> |
| EWP Premier 4HR ONSITE H30569 | 98008-H30569 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30570 | 98008-H30570 | \$ 7,460.00 | 6% | <i>\$7,064.99</i> |
| EWP Premier 4HR ONSITE H30571 | 98008-H30571 | \$ 7,460.00 | 6% | <i>\$7,064.99</i> |
| EWP Premier 4HR ONSITE H30573 | 98008-H30573 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30574 | 98008-H30574 | \$ 6,893.00 | 6% | <i>\$6,528.02</i> |
| EWP Premier 4HR ONSITE H30575 | 98008-H30575 | \$ 4,302.00 | 6% | <i>\$4,074.21</i> |
| EWP Premier 4HR ONSITE H30576 | 98008-H30576 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30577 | 98008-H30577 | \$ 7,320.00 | 6% | <i>\$6,932.41</i> |
| EWP Premier 4HR ONSITE H30578 | 98008-H30578 | \$ 7,320.00 | 6% | <i>\$6,932.41</i> |
| EWP Premier 4HR ONSITE H30587 | 98008-H30587 | \$ 6,353.00 | 6% | <i>\$6,016.61</i> |
| EWP Premier 4HR ONSITE H30588 | 98008-H30588 | \$ 4,387.00 | 6% | <i>\$4,154.71</i> |
| EWP Premier 4HR ONSITE H30589 | 98008-H30589 | \$ 6,655.00 | 6% | <i>\$6,302.62</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H30632 | 98008-H30632 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier 4HR ONSITE H30633 | 98008-H30633 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier 4HR ONSITE H30643 | 98008-H30643 | \$ 10,500.00 | 6% | <i>\$9,944.03</i> |
| EWP Premier 4HR ONSITE H30706 | 98008-H30706 | \$ 10,022.00 | 6% | <i>\$9,491.34</i> |
| EWP Premier 4HR ONSITE H30707 | 98008-H30707 | \$ 6,232.00 | 6% | <i>\$5,902.02</i> |
| EWP Premier 4HR ONSITE H30724 | 98008-H30724 | \$ 690.00 | 6% | <i>\$653.46</i> |
| EWP Premier 4HR ONSITE H30725 | 98008-H30725 | \$ 2,367.00 | 6% | <i>\$2,241.67</i> |
| EWP Premier 4HR ONSITE H30726 | 98008-H30726 | \$ 15,510.00 | 6% | <i>\$14,688.75</i> |
| EWP Premier 4HR ONSITE H30727 | 98008-H30727 | \$ 16,493.00 | 6% | <i>\$15,619.70</i> |
| EWP Premier 4HR ONSITE H30730 | 98008-H30730 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier 4HR ONSITE H30731 | 98008-H30731 | \$ 134.00 | 6% | <i>\$126.90</i> |
| EWP Premier 4HR ONSITE H30732 | 98008-H30732 | \$ 3,107.00 | 6% | <i>\$2,942.48</i> |
| EWP Premier 4HR ONSITE H30733 | 98008-H30733 | \$ 14,842.00 | 6% | <i>\$14,056.12</i> |
| EWP Premier 4HR ONSITE H30734 | 98008-H30734 | \$ 11,326.00 | 6% | <i>\$10,726.29</i> |
| EWP Premier 4HR ONSITE H30735 | 98008-H30735 | \$ 13,119.00 | 6% | <i>\$12,424.35</i> |
| EWP Premier 4HR ONSITE H30736 | 98008-H30736 | \$ 2,048.00 | 6% | <i>\$1,939.56</i> |
| EWP Premier 4HR ONSITE H30738 | 98008-H30738 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30739 | 98008-H30739 | \$ 2,174.00 | 6% | <i>\$2,058.89</i> |
| EWP Premier 4HR ONSITE H30740 | 98008-H30740 | \$ 1,260.00 | 6% | <i>\$1,193.28</i> |
| EWP Premier 4HR ONSITE H30741 | 98008-H30741 | \$ 2,301.00 | 6% | <i>\$2,179.16</i> |
| EWP Premier 4HR ONSITE H30742 | 98008-H30742 | \$ 2,048.00 | 6% | <i>\$1,939.56</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H30743 | 98008-H30743 | \$ 2,174.00 | 6% | <i>\$2,058.89</i> |
| EWP Premier 4HR ONSITE H30744 | 98008-H30744 | \$ 1,260.00 | 6% | <i>\$1,193.28</i> |
| EWP Premier 4HR ONSITE H30745 | 98008-H30745 | \$ 1,284.00 | 6% | <i>\$1,216.01</i> |
| EWP Premier 4HR ONSITE H30746 | 98008-H30746 | \$ 2,294.00 | 6% | <i>\$2,172.53</i> |
| EWP Premier 4HR ONSITE H30747 | 98008-H30747 | \$ 4,519.00 | 6% | <i>\$4,279.72</i> |
| EWP Premier 4HR ONSITE H30748 | 98008-H30748 | \$ 6,665.00 | 6% | <i>\$6,312.09</i> |
| EWP Premier 4HR ONSITE H30749 | 98008-H30749 | \$ 14,975.00 | 6% | <i>\$14,182.07</i> |
| EWP Premier 4HR ONSITE H30750 | 98008-H30750 | \$ 14,975.00 | 6% | <i>\$14,182.07</i> |
| EWP Premier 4HR ONSITE H30751 | 98008-H30751 | \$ 8,892.00 | 6% | <i>\$8,421.17</i> |
| EWP Premier 4HR ONSITE H30754 | 98008-H30754 | \$ 14,975.00 | 6% | <i>\$14,182.07</i> |
| EWP Premier 4HR ONSITE H30755 | 98008-H30755 | \$ 16,287.00 | 6% | <i>\$15,424.60</i> |
| EWP Premier 4HR ONSITE H30756 | 98008-H30756 | \$ 14,975.00 | 6% | <i>\$14,182.07</i> |
| EWP Premier 4HR ONSITE H30757 | 98008-H30757 | \$ 6,665.00 | 6% | <i>\$6,312.09</i> |
| EWP Premier 4HR ONSITE H30758 | 98008-H30758 | \$ 12,120.00 | 6% | <i>\$11,478.25</i> |
| EWP Premier 4HR ONSITE H30759 | 98008-H30759 | \$ 13,773.00 | 6% | <i>\$13,043.72</i> |
| EWP Premier 4HR ONSITE H30760 | 98008-H30760 | \$ 15,584.00 | 6% | <i>\$14,758.83</i> |
| EWP Premier 4HR ONSITE H30761 | 98008-H30761 | \$ 6,665.00 | 6% | <i>\$6,312.09</i> |
| EWP Premier 4HR ONSITE H30762 | 98008-H30762 | \$ 16,287.00 | 6% | <i>\$15,424.60</i> |
| EWP Premier 4HR ONSITE H30763 | 98008-H30763 | \$ 16,287.00 | 6% | <i>\$15,424.60</i> |
| EWP Premier 4HR ONSITE H30764 | 98008-H30764 | \$ 10,323.00 | 6% | <i>\$9,776.40</i> |
| EWP Premier 4HR ONSITE H30765 | 98008-H30765 | \$ 9,066.00 | 6% | <i>\$8,585.96</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H30766 | 98008-H30766 | \$ 17,657.00 | 6% | <i>\$16,722.06</i> |
| EWP Premier 4HR ONSITE H30767 | 98008-H30767 | \$ 10,323.00 | 6% | <i>\$9,776.40</i> |
| EWP Premier 4HR ONSITE H30769 | 98008-H30769 | \$ 4,009.00 | 6% | <i>\$3,796.72</i> |
| EWP Premier 4HR ONSITE H30773 | 98008-H30773 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR ONSITE H30774 | 98008-H30774 | \$ 277.00 | 6% | <i>\$262.33</i> |
| EWP Premier 4HR ONSITE H30775 | 98008-H30775 | \$ 277.00 | 6% | <i>\$262.33</i> |
| EWP Premier 4HR ONSITE H30776 | 98008-H30776 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR ONSITE H30777 | 98008-H30777 | \$ 277.00 | 6% | <i>\$262.33</i> |
| EWP Premier 4HR ONSITE H30778 | 98008-H30778 | \$ 277.00 | 6% | <i>\$262.33</i> |
| EWP Premier 4HR ONSITE H30779 | 98008-H30779 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H30780 | 98008-H30780 | \$ 156.00 | 6% | <i>\$147.74</i> |
| EWP Premier 4HR ONSITE H30781 | 98008-H30781 | \$ 156.00 | 6% | <i>\$147.74</i> |
| EWP Premier 4HR ONSITE H30782 | 98008-H30782 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier 4HR ONSITE H30783 | 98008-H30783 | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier 4HR ONSITE H30784 | 98008-H30784 | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier 4HR ONSITE H30785 | 98008-H30785 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H30786 | 98008-H30786 | \$ 156.00 | 6% | <i>\$147.74</i> |
| EWP Premier 4HR ONSITE H30787 | 98008-H30787 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H30788 | 98008-H30788 | \$ 156.00 | 6% | <i>\$147.74</i> |
| EWP Premier 4HR ONSITE H30789 | 98008-H30789 | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier 4HR ONSITE H30790 | 98008-H30790 | \$ 126.00 | 6% | <i>\$119.33</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE H30791 | 98008-H30791 | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier 4HR ONSITE H30793 | 98008-H30793 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30794 | 98008-H30794 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30795 | 98008-H30795 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30796 | 98008-H30796 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30797 | 98008-H30797 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30798 | 98008-H30798 | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR ONSITE H30799 | 98008-H30799 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30800 | 98008-H30800 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR ONSITE H30801 | 98008-H30801 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30802 | 98008-H30802 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR ONSITE H30803 | 98008-H30803 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30804 | 98008-H30804 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30805 | 98008-H30805 | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR ONSITE H30806 | 98008-H30806 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30807 | 98008-H30807 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30808 | 98008-H30808 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30809 | 98008-H30809 | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR ONSITE H30810 | 98008-H30810 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30811 | 98008-H30811 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30812 | 98008-H30812 | \$ 111.00 | 6% | <i>\$105.12</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE H30813 | 98008-H30813 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR ONSITE H30814 | 98008-H30814 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30815 | 98008-H30815 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30816 | 98008-H30816 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30817 | 98008-H30817 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30818 | 98008-H30818 | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR ONSITE H30819 | 98008-H30819 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30820 | 98008-H30820 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H30821 | 98008-H30821 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR ONSITE H30822 | 98008-H30822 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30823 | 98008-H30823 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR ONSITE H30824 | 98008-H30824 | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR ONSITE H30825 | 98008-H30825 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR ONSITE H30826 | 98008-H30826 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30827 | 98008-H30827 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30828 | 98008-H30828 | \$ 117.00 | 6% | <i>\$110.80</i> |
| EWP Premier 4HR ONSITE H30829 | 98008-H30829 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier 4HR ONSITE H30830 | 98008-H30830 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier 4HR ONSITE H30831 | 98008-H30831 | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier 4HR ONSITE H30833 | 98008-H30833 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier 4HR ONSITE H30834 | 98008-H30834 | \$ 614.00 | 6% | <i>\$581.49</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H30836 | 98008-H30836 | \$ 2,291.00 | 6% | <i>\$2,169.69</i> |
| EWP Premier 4HR ONSITE H30838 | 98008-H30838 | \$ 83.00 | 6% | <i>\$78.61</i> |
| EWP Premier 4HR ONSITE H30839 | 98008-H30839 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30840 | 98008-H30840 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30841 | 98008-H30841 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30842 | 98008-H30842 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30843 | 98008-H30843 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30844 | 98008-H30844 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30845 | 98008-H30845 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier 4HR ONSITE H30846 | 98008-H30846 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30847 | 98008-H30847 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30848 | 98008-H30848 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30849 | 98008-H30849 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30850 | 98008-H30850 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30851 | 98008-H30851 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30852 | 98008-H30852 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30853 | 98008-H30853 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR ONSITE H30854 | 98008-H30854 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR ONSITE H30855 | 98008-H30855 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR ONSITE H30856 | 98008-H30856 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR ONSITE H30857 | 98008-H30857 | \$ 224.00 | 6% | <i>\$212.14</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier 4HR ONSITE H30858 | 98008-H30858 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR ONSITE H30859 | 98008-H30859 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR ONSITE H30860 | 98008-H30860 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier 4HR ONSITE H30866 | 98008-H30866 | \$ 242.00 | 6% | <i>\$229.19</i> |
| EWP Premier 4HR ONSITE H30867 | 98008-H30867 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30868 | 98008-H30868 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H30869 | 98008-H30869 | \$ 431.00 | 6% | <i>\$408.18</i> |
| EWP Premier 4HR ONSITE H30870 | 98008-H30870 | \$ 431.00 | 6% | <i>\$408.18</i> |
| EWP Premier 4HR ONSITE H30871 | 98008-H30871 | \$ 396.00 | 6% | <i>\$375.03</i> |
| EWP Premier 4HR ONSITE H30872 | 98008-H30872 | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier 4HR ONSITE H30873 | 98008-H30873 | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier 4HR ONSITE H30874 | 98008-H30874 | \$ 227.00 | 6% | <i>\$214.98</i> |
| EWP Premier 4HR ONSITE H30875 | 98008-H30875 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier 4HR ONSITE H30876 | 98008-H30876 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier 4HR ONSITE H30877 | 98008-H30877 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier 4HR ONSITE H30878 | 98008-H30878 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier 4HR ONSITE H30891 | 98008-H30891 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier 4HR ONSITE H30892 | 98008-H30892 | \$ 164.00 | 6% | <i>\$155.32</i> |
| EWP Premier 4HR ONSITE H30893 | 98008-H30893 | \$ 136.00 | 6% | <i>\$128.80</i> |
| EWP Premier 4HR ONSITE H30894 | 98008-H30894 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier 4HR ONSITE H30895 | 98008-H30895 | \$ 277.00 | 6% | <i>\$262.33</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H30896 | 98008-H30896 | \$ 651.00 | 6% | <i>\$616.53</i> |
| EWP Premier 4HR ONSITE H30897 | 98008-H30897 | \$ 1,133.00 | 6% | <i>\$1,073.01</i> |
| EWP Premier 4HR ONSITE H30898 | 98008-H30898 | \$ 1,279.00 | 6% | <i>\$1,211.28</i> |
| EWP Premier 4HR ONSITE H30900 | 98008-H30900 | \$ 3,862.00 | 6% | <i>\$3,657.51</i> |
| EWP Premier 4HR ONSITE H30901 | 98008-H30901 | \$ 5,139.00 | 6% | <i>\$4,866.89</i> |
| EWP Premier 4HR ONSITE H30902 | 98008-H30902 | \$ 5,394.00 | 6% | <i>\$5,108.39</i> |
| EWP Premier 4HR ONSITE H30904 | 98008-H30904 | \$ 7,897.00 | 6% | <i>\$7,478.85</i> |
| EWP Premier 4HR ONSITE H30905 | 98008-H30905 | \$ 11,281.00 | 6% | <i>\$10,683.67</i> |
| EWP Premier 4HR ONSITE H30906 | 98008-H30906 | \$ 314.00 | 6% | <i>\$297.37</i> |
| EWP Premier 4HR ONSITE H30912 | 98008-H30912 | \$ 852.00 | 6% | <i>\$806.89</i> |
| EWP Premier 4HR ONSITE H30913 | 98008-H30913 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier 4HR ONSITE H30914 | 98008-H30914 | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier 4HR ONSITE H30915 | 98008-H30915 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier 4HR ONSITE H30916 | 98008-H30916 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier 4HR ONSITE H30917 | 98008-H30917 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier 4HR ONSITE H30918 | 98008-H30918 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier 4HR ONSITE H30946 | 98008-H30946 | \$ 157.00 | 6% | <i>\$148.69</i> |
| EWP Premier 4HR ONSITE H30948 | 98008-H30948 | \$ 157.00 | 6% | <i>\$148.69</i> |
| EWP Premier 4HR ONSITE H30950 | 98008-H30950 | \$ 172.00 | 6% | <i>\$162.89</i> |
| EWP Premier 4HR ONSITE H30951 | 98008-H30951 | \$ 157.00 | 6% | <i>\$148.69</i> |
| EWP Premier 4HR ONSITE H30952 | 98008-H30952 | \$ 157.00 | 6% | <i>\$148.69</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|------------|
| EWP Premier 4HR ONSITE H30966 | 98008-H30966 | \$ 277.00 | 6% | \$262.33 |
| EWP Premier 4HR ONSITE H30967 | 98008-H30967 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier 4HR ONSITE H30968 | 98008-H30968 | \$ 277.00 | 6% | \$262.33 |
| EWP Premier 4HR ONSITE H30969 | 98008-H30969 | \$ 144.00 | 6% | \$136.38 |
| EWP Premier 4HR ONSITE H30970 | 98008-H30970 | \$ 195.00 | 6% | \$184.67 |
| EWP Premier 4HR ONSITE H30971 | 98008-H30971 | \$ 171.00 | 6% | \$161.95 |
| EWP Premier 4HR ONSITE H30972 | 98008-H30972 | \$ 195.00 | 6% | \$184.67 |
| EWP Premier 4HR ONSITE H30973 | 98008-H30973 | \$ 284.00 | 6% | \$268.96 |
| EWP Premier 4HR ONSITE H30974 | 98008-H30974 | \$ 248.00 | 6% | \$234.87 |
| EWP Premier 4HR ONSITE H30975 | 98008-H30975 | \$ 284.00 | 6% | \$268.96 |
| EWP Premier 4HR ONSITE H30976 | 98008-H30976 | \$ 284.00 | 6% | \$268.96 |
| EWP Premier 4HR ONSITE H30977 | 98008-H30977 | \$ 248.00 | 6% | \$234.87 |
| EWP Premier 4HR ONSITE H30978 | 98008-H30978 | \$ 284.00 | 6% | \$268.96 |
| EWP Premier 4HR ONSITE H30995 | 98008-H30995 | \$ 3,089.00 | 6% | \$2,925.44 |
| EWP Premier 4HR ONSITE H31030 | 98008-H31030 | \$ 9,967.00 | 6% | \$9,439.25 |
| EWP Premier 4HR ONSITE H31031 | 98008-H31031 | \$ 792.00 | 6% | \$750.06 |
| EWP Premier 4HR ONSITE H31033 | 98008-H31033 | \$ 5,920.00 | 6% | \$5,606.54 |
| EWP Premier 4HR ONSITE H31034 | 98008-H31034 | \$ 3,290.00 | 6% | \$3,115.79 |
| EWP Premier 4HR ONSITE H31035 | 98008-H31035 | \$ 3,449.00 | 6% | \$3,266.38 |
| EWP Premier 4HR ONSITE H31036 | 98008-H31036 | \$ 6,897.00 | 6% | \$6,531.80 |
| EWP Premier 4HR ONSITE H31040 | 98008-H31040 | \$ 265.00 | 6% | \$250.97 |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H31041 | 98008-H31041 | \$ 136.00 | 6% | <i>\$128.80</i> |
| EWP Premier 4HR ONSITE H31042 | 98008-H31042 | \$ 396.00 | 6% | <i>\$375.03</i> |
| EWP Premier 4HR ONSITE H31043 | 98008-H31043 | \$ 287.00 | 6% | <i>\$271.80</i> |
| EWP Premier 4HR ONSITE H31047 | 98008-H31047 | \$ 267.00 | 6% | <i>\$252.86</i> |
| EWP Premier 4HR ONSITE H31049 | 98008-H31049 | \$ 2,762.00 | 6% | <i>\$2,615.75</i> |
| EWP Premier 4HR ONSITE H31060 | 98008-H31060 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier 4HR ONSITE H31062 | 98008-H31062 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier 4HR ONSITE H31066 | 98008-H31066 | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR ONSITE H31068 | 98008-H31068 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier 4HR ONSITE H31077 | 98008-H31077 | \$ 396.00 | 6% | <i>\$375.03</i> |
| EWP Premier 4HR ONSITE H31103 | 98008-H31103 | \$ 6,316.00 | 6% | <i>\$5,981.57</i> |
| EWP Premier 4HR ONSITE H31124 | 98008-H31124 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier 4HR ONSITE H31127 | 98008-H31127 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR ONSITE H31132 | 98008-H31132 | \$ 245.00 | 6% | <i>\$232.03</i> |
| EWP Premier 4HR ONSITE H31134 | 98008-H31134 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier 4HR ONSITE H31135 | 98008-H31135 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier 4HR ONSITE H31136 | 98008-H31136 | \$ 132.00 | 6% | <i>\$125.01</i> |
| EWP Premier 4HR ONSITE H31137 | 98008-H31137 | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR ONSITE H31197 | 98008-H31197 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE H31198 | 98008-H31198 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE H31199 | 98008-H31199 | \$ 143.00 | 6% | <i>\$135.43</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H31200 | 98008-H31200 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE H31201 | 98008-H31201 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE H31202 | 98008-H31202 | \$ 143.00 | 6% | <i>\$135.43</i> |
| EWP Premier 4HR ONSITE H31203 | 98008-H31203 | \$ 172.00 | 6% | <i>\$162.89</i> |
| EWP Premier 4HR ONSITE H31204 | 98008-H31204 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H31205 | 98008-H31205 | \$ 172.00 | 6% | <i>\$162.89</i> |
| EWP Premier 4HR ONSITE H31206 | 98008-H31206 | \$ 172.00 | 6% | <i>\$162.89</i> |
| EWP Premier 4HR ONSITE H31207 | 98008-H31207 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H31208 | 98008-H31208 | \$ 172.00 | 6% | <i>\$162.89</i> |
| EWP Premier 4HR ONSITE H31210 | 98008-H31210 | \$ 314.00 | 6% | <i>\$297.37</i> |
| EWP Premier 4HR ONSITE H31335 | 98008-H31335 | \$ 171.00 | 6% | <i>\$161.95</i> |
| EWP Premier 4HR ONSITE H31337 | 98008-H31337 | \$ 13,309.00 | 6% | <i>\$12,604.29</i> |
| EWP Premier 4HR ONSITE H31338 | 98008-H31338 | \$ 13,309.00 | 6% | <i>\$12,604.29</i> |
| EWP Premier 4HR ONSITE H31339 | 98008-H31339 | \$ 2,164.00 | 6% | <i>\$2,049.42</i> |
| EWP Premier 4HR ONSITE H31340 | 98008-H31340 | \$ 4,620.00 | 6% | <i>\$4,375.37</i> |
| EWP Premier 4HR ONSITE H31341 | 98008-H31341 | \$ 6,847.00 | 6% | <i>\$6,484.45</i> |
| EWP Premier 4HR ONSITE H31342 | 98008-H31342 | \$ 2,154.00 | 6% | <i>\$2,039.95</i> |
| EWP Premier 4HR ONSITE H31343 | 98008-H31343 | \$ 3,184.00 | 6% | <i>\$3,015.41</i> |
| EWP Premier 4HR ONSITE H31344 | 98008-H31344 | \$ 3,184.00 | 6% | <i>\$3,015.41</i> |
| EWP Premier 4HR ONSITE H31345 | 98008-H31345 | \$ 3,184.00 | 6% | <i>\$3,015.41</i> |
| EWP Premier 4HR ONSITE H31346 | 98008-H31346 | \$ 3,184.00 | 6% | <i>\$3,015.41</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H31348 | 98008-H31348 | \$ 248.00 | 6% | <i>\$234.87</i> |
| EWP Premier 4HR ONSITE H31349 | 98008-H31349 | \$ 248.00 | 6% | <i>\$234.87</i> |
| EWP Premier 4HR ONSITE H31350 | 98008-H31350 | \$ 396.00 | 6% | <i>\$375.03</i> |
| EWP Premier 4HR ONSITE H31351 | 98008-H31351 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H31352 | 98008-H31352 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H31353 | 98008-H31353 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier 4HR ONSITE H31354 | 98008-H31354 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier 4HR ONSITE H31355 | 98008-H31355 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR ONSITE H31356 | 98008-H31356 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR ONSITE H31357 | 98008-H31357 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier 4HR ONSITE H31358 | 98008-H31358 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier 4HR ONSITE H31359 | 98008-H31359 | \$ 108.00 | 6% | <i>\$102.28</i> |
| EWP Premier 4HR ONSITE H31360 | 98008-H31360 | \$ 83.00 | 6% | <i>\$78.61</i> |
| EWP Premier 4HR ONSITE H31361 | 98008-H31361 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR ONSITE H31362 | 98008-H31362 | \$ 38,852.00 | 6% | <i>\$36,794.79</i> |
| EWP Premier 4HR ONSITE H31363 | 98008-H31363 | \$ 38,852.00 | 6% | <i>\$36,794.79</i> |
| EWP Premier 4HR ONSITE H31364 | 98008-H31364 | \$ 13,574.00 | 6% | <i>\$12,855.26</i> |
| EWP Premier 4HR ONSITE H31365 | 98008-H31365 | \$ 13,574.00 | 6% | <i>\$12,855.26</i> |
| EWP Premier 4HR ONSITE H31366 | 98008-H31366 | \$ 18,829.00 | 6% | <i>\$17,832.00</i> |
| EWP Premier 4HR ONSITE H31367 | 98008-H31367 | \$ 18,829.00 | 6% | <i>\$17,832.00</i> |
| EWP Premier 4HR ONSITE H31369 | 98008-H31369 | \$ 153.00 | 6% | <i>\$144.90</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H31370 | 98008-H31370 | \$ 153.00 | 6% | <i>\$144.90</i> |
| EWP Premier 4HR ONSITE H31393 | 98008-H31393 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier 4HR ONSITE H32010 | 98008-H32010 | \$ 520.00 | 6% | <i>\$492.47</i> |
| EWP Premier 4HR ONSITE H32011 | 98008-H32011 | \$ 520.00 | 6% | <i>\$492.47</i> |
| EWP Premier 4HR ONSITE H32012 | 98008-H32012 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR ONSITE H32013 | 98008-H32013 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR ONSITE H32014 | 98008-H32014 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR ONSITE H32015 | 98008-H32015 | \$ 4,350.00 | 6% | <i>\$4,119.67</i> |
| EWP Premier 4HR ONSITE H32016 | 98008-H32016 | \$ 3,865.00 | 6% | <i>\$3,660.35</i> |
| EWP Premier 4HR ONSITE H32017 | 98008-H32017 | \$ 3,865.00 | 6% | <i>\$3,660.35</i> |
| EWP Premier 4HR ONSITE H32018 | 98008-H32018 | \$ 3,865.00 | 6% | <i>\$3,660.35</i> |
| EWP Premier 4HR ONSITE H32019 | 98008-H32019 | \$ 3,865.00 | 6% | <i>\$3,660.35</i> |
| EWP Premier 4HR ONSITE H32020 | 98008-H32020 | \$ 38,709.00 | 6% | <i>\$36,659.36</i> |
| EWP Premier 4HR ONSITE H32021 | 98008-H32021 | \$ 38,709.00 | 6% | <i>\$36,659.36</i> |
| EWP Premier 4HR ONSITE H32022 | 98008-H32022 | \$ 38,709.00 | 6% | <i>\$36,659.36</i> |
| EWP Premier 4HR ONSITE H32023 | 98008-H32023 | \$ 38,709.00 | 6% | <i>\$36,659.36</i> |
| EWP Premier 4HR ONSITE H32028 | 98008-H32028 | \$ 74,646.00 | 6% | <i>\$70,693.49</i> |
| EWP Premier 4HR ONSITE H32029 | 98008-H32029 | \$ 74,646.00 | 6% | <i>\$70,693.49</i> |
| EWP Premier 4HR ONSITE H32030 | 98008-H32030 | \$ 78,284.00 | 6% | <i>\$74,138.86</i> |
| EWP Premier 4HR ONSITE H32031 | 98008-H32031 | \$ 78,284.00 | 6% | <i>\$74,138.86</i> |
| EWP Premier 4HR ONSITE H32032 | 98008-H32032 | \$ 78,284.00 | 6% | <i>\$74,138.86</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H32033 | 98008-H32033 | \$ 78,284.00 | 6% | <i>\$74,138.86</i> |
| EWP Premier 4HR ONSITE H32038 | 98008-H32038 | \$ 13,529.00 | 6% | <i>\$12,812.64</i> |
| EWP Premier 4HR ONSITE H32039 | 98008-H32039 | \$ 13,529.00 | 6% | <i>\$12,812.64</i> |
| EWP Premier 4HR ONSITE H32040 | 98008-H32040 | \$ 13,529.00 | 6% | <i>\$12,812.64</i> |
| EWP Premier 4HR ONSITE H32041 | 98008-H32041 | \$ 13,529.00 | 6% | <i>\$12,812.64</i> |
| EWP Premier 4HR ONSITE H32046 | 98008-H32046 | \$ 18,765.00 | 6% | <i>\$17,771.39</i> |
| EWP Premier 4HR ONSITE H32047 | 98008-H32047 | \$ 18,765.00 | 6% | <i>\$17,771.39</i> |
| EWP Premier 4HR ONSITE H32048 | 98008-H32048 | \$ 18,765.00 | 6% | <i>\$17,771.39</i> |
| EWP Premier 4HR ONSITE H32049 | 98008-H32049 | \$ 18,765.00 | 6% | <i>\$17,771.39</i> |
| EWP Premier 4HR ONSITE H32054 | 98008-H32054 | \$ 13,529.00 | 6% | <i>\$12,812.64</i> |
| EWP Premier 4HR ONSITE H32055 | 98008-H32055 | \$ 18,765.00 | 6% | <i>\$17,771.39</i> |
| EWP Premier 4HR ONSITE H32056 | 98008-H32056 | \$ 5,086.00 | 6% | <i>\$4,816.70</i> |
| EWP Premier 4HR ONSITE H32057 | 98008-H32057 | \$ 5,086.00 | 6% | <i>\$4,816.70</i> |
| EWP Premier 4HR ONSITE H32058 | 98008-H32058 | \$ 5,086.00 | 6% | <i>\$4,816.70</i> |
| EWP Premier 4HR ONSITE H32059 | 98008-H32059 | \$ 5,086.00 | 6% | <i>\$4,816.70</i> |
| EWP Premier 4HR ONSITE H32060 | 98008-H32060 | \$ 6,275.00 | 6% | <i>\$5,942.74</i> |
| EWP Premier 4HR ONSITE H32061 | 98008-H32061 | \$ 6,589.00 | 6% | <i>\$6,240.11</i> |
| EWP Premier 4HR ONSITE H32062 | 98008-H32062 | \$ 6,275.00 | 6% | <i>\$5,942.74</i> |
| EWP Premier 4HR ONSITE H32063 | 98008-H32063 | \$ 6,282.00 | 6% | <i>\$5,949.37</i> |
| EWP Premier 4HR ONSITE H32064 | 98008-H32064 | \$ 6,275.00 | 6% | <i>\$5,942.74</i> |
| EWP Premier 4HR ONSITE H32065 | 98008-H32065 | \$ 5,915.00 | 6% | <i>\$5,601.80</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H32066 | 98008-H32066 | \$ 5,915.00 | 6% | <i>\$5,601.80</i> |
| EWP Premier 4HR ONSITE H32067 | 98008-H32067 | \$ 5,915.00 | 6% | <i>\$5,601.80</i> |
| EWP Premier 4HR ONSITE H32068 | 98008-H32068 | \$ 5,915.00 | 6% | <i>\$5,601.80</i> |
| EWP Premier 4HR ONSITE H32069 | 98008-H32069 | \$ 7,353.00 | 6% | <i>\$6,963.66</i> |
| EWP Premier 4HR ONSITE H32070 | 98008-H32070 | \$ 7,353.00 | 6% | <i>\$6,963.66</i> |
| EWP Premier 4HR ONSITE H32071 | 98008-H32071 | \$ 7,353.00 | 6% | <i>\$6,963.66</i> |
| EWP Premier 4HR ONSITE H32072 | 98008-H32072 | \$ 7,353.00 | 6% | <i>\$6,963.66</i> |
| EWP Premier 4HR ONSITE H32073 | 98008-H32073 | \$ 54,453.00 | 6% | <i>\$51,569.71</i> |
| EWP Premier 4HR ONSITE H32074 | 98008-H32074 | \$ 54,453.00 | 6% | <i>\$51,569.71</i> |
| EWP Premier 4HR ONSITE H32075 | 98008-H32075 | \$ 74,005.00 | 6% | <i>\$70,086.44</i> |
| EWP Premier 4HR ONSITE H32076 | 98008-H32076 | \$ 73,302.00 | 6% | <i>\$69,420.66</i> |
| EWP Premier 4HR ONSITE H32101 | 98008-H32101 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32102 | 98008-H32102 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32103 | 98008-H32103 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32104 | 98008-H32104 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32105 | 98008-H32105 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |
| EWP Premier 4HR ONSITE H32106 | 98008-H32106 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |
| EWP Premier 4HR ONSITE H32107 | 98008-H32107 | \$ 13,118.00 | 6% | <i>\$12,423.40</i> |
| EWP Premier 4HR ONSITE H32108 | 98008-H32108 | \$ 13,118.00 | 6% | <i>\$12,423.40</i> |
| EWP Premier 4HR ONSITE H32109 | 98008-H32109 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |
| EWP Premier 4HR ONSITE H32110 | 98008-H32110 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H32111 | 98008-H32111 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32112 | 98008-H32112 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32113 | 98008-H32113 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32114 | 98008-H32114 | \$ 2,424.00 | 6% | <i>\$2,295.65</i> |
| EWP Premier 4HR ONSITE H32115 | 98008-H32115 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |
| EWP Premier 4HR ONSITE H32116 | 98008-H32116 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |
| EWP Premier 4HR ONSITE H32117 | 98008-H32117 | \$ 2,277.00 | 6% | <i>\$2,156.43</i> |
| EWP Premier 4HR ONSITE H32118 | 98008-H32118 | \$ 2,277.00 | 6% | <i>\$2,156.43</i> |
| EWP Premier 4HR ONSITE H32119 | 98008-H32119 | \$ 2,277.00 | 6% | <i>\$2,156.43</i> |
| EWP Premier 4HR ONSITE H32120 | 98008-H32120 | \$ 2,277.00 | 6% | <i>\$2,156.43</i> |
| EWP Premier 4HR ONSITE H32121 | 98008-H32121 | \$ 13,118.00 | 6% | <i>\$12,423.40</i> |
| EWP Premier 4HR ONSITE H32122 | 98008-H32122 | \$ 13,118.00 | 6% | <i>\$12,423.40</i> |
| EWP Premier 4HR ONSITE H32123 | 98008-H32123 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |
| EWP Premier 4HR ONSITE H32124 | 98008-H32124 | \$ 4,850.00 | 6% | <i>\$4,593.19</i> |
| EWP Premier 4HR ONSITE H32125 | 98008-H32125 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32126 | 98008-H32126 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32127 | 98008-H32127 | \$ 5,641.00 | 6% | <i>\$5,342.31</i> |
| EWP Premier 4HR ONSITE H32128 | 98008-H32128 | \$ 5,641.00 | 6% | <i>\$5,342.31</i> |
| EWP Premier 4HR ONSITE H32129 | 98008-H32129 | \$ 5,641.00 | 6% | <i>\$5,342.31</i> |
| EWP Premier 4HR ONSITE H32130 | 98008-H32130 | \$ 5,641.00 | 6% | <i>\$5,342.31</i> |
| EWP Premier 4HR ONSITE H32131 | 98008-H32131 | \$ 5,641.00 | 6% | <i>\$5,342.31</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H32132 | 98008-H32132 | \$ 5,641.00 | 6% | <i>\$5,342.31</i> |
| EWP Premier 4HR ONSITE H32133 | 98008-H32133 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32134 | 98008-H32134 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32135 | 98008-H32135 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32136 | 98008-H32136 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32137 | 98008-H32137 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32138 | 98008-H32138 | \$ 4,787.00 | 6% | <i>\$4,533.53</i> |
| EWP Premier 4HR ONSITE H32139 | 98008-H32139 | \$ 20,272.00 | 6% | <i>\$19,198.60</i> |
| EWP Premier 4HR ONSITE H32140 | 98008-H32140 | \$ 20,272.00 | 6% | <i>\$19,198.60</i> |
| EWP Premier 4HR ONSITE H32141 | 98008-H32141 | \$ 23,386.00 | 6% | <i>\$22,147.71</i> |
| EWP Premier 4HR ONSITE H32142 | 98008-H32142 | \$ 23,386.00 | 6% | <i>\$22,147.71</i> |
| EWP Premier 4HR ONSITE H32146 | 98008-H32146 | \$ 2,299.00 | 6% | <i>\$2,177.27</i> |
| EWP Premier 4HR ONSITE H32147 | 98008-H32147 | \$ 2,299.00 | 6% | <i>\$2,177.27</i> |
| EWP Premier 4HR ONSITE H32148 | 98008-H32148 | \$ 4,596.00 | 6% | <i>\$4,352.64</i> |
| EWP Premier 4HR ONSITE H32149 | 98008-H32149 | \$ 4,596.00 | 6% | <i>\$4,352.64</i> |
| EWP Premier 4HR ONSITE H32150 | 98008-H32150 | \$ 2,299.00 | 6% | <i>\$2,177.27</i> |
| EWP Premier 4HR ONSITE H32169 | 98008-H32169 | \$ 2,408.00 | 6% | <i>\$2,280.50</i> |
| EWP Premier 4HR ONSITE H32170 | 98008-H32170 | \$ 2,408.00 | 6% | <i>\$2,280.50</i> |
| EWP Premier 4HR ONSITE H32171 | 98008-H32171 | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier 4HR ONSITE H32172 | 98008-H32172 | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier 4HR ONSITE H32173 | 98008-H32173 | \$ 6,017.00 | 6% | <i>\$5,698.40</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H32174 | 98008-H32174 | \$ 6,017.00 | 6% | <i>\$5,698.40</i> |
| EWP Premier 4HR ONSITE H32175 | 98008-H32175 | \$ 5,107.00 | 6% | <i>\$4,836.58</i> |
| EWP Premier 4HR ONSITE H32176 | 98008-H32176 | \$ 5,107.00 | 6% | <i>\$4,836.58</i> |
| EWP Premier 4HR ONSITE H32177 | 98008-H32177 | \$ 23,442.00 | 6% | <i>\$22,200.75</i> |
| EWP Premier 4HR ONSITE H32178 | 98008-H32178 | \$ 27,046.00 | 6% | <i>\$25,613.91</i> |
| EWP Premier 4HR ONSITE H34008 | 98008-H34008 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier 4HR ONSITE H34009 | 98008-H34009 | \$ 239.00 | 6% | <i>\$226.34</i> |
| EWP Premier 4HR ONSITE H34010 | 98008-H34010 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier 4HR ONSITE H34011 | 98008-H34011 | \$ 211.00 | 6% | <i>\$199.83</i> |
| EWP Premier 4HR ONSITE H34012 | 98008-H34012 | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWP Premier 4HR ONSITE H34013 | 98008-H34013 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE H34014 | 98008-H34014 | \$ 239.00 | 6% | <i>\$226.34</i> |
| EWP Premier 4HR ONSITE H34015 | 98008-H34015 | \$ 122.00 | 6% | <i>\$115.54</i> |
| EWP Premier 4HR ONSITE H34016 | 98008-H34016 | \$ 263.00 | 6% | <i>\$249.07</i> |
| EWP Premier 4HR ONSITE H34017 | 98008-H34017 | \$ 454.00 | 6% | <i>\$429.96</i> |
| EWP Premier 4HR ONSITE H34018 | 98008-H34018 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier 4HR ONSITE H34019 | 98008-H34019 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier 4HR ONSITE H34020 | 98008-H34020 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier 4HR ONSITE H34021 | 98008-H34021 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier 4HR ONSITE H34048 | 98008-H34048 | \$ 737.00 | 6% | <i>\$697.98</i> |
| EWP Premier 4HR ONSITE H34049 | 98008-H34049 | \$ 737.00 | 6% | <i>\$697.98</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H34050 | 98008-H34050 | \$ 545.00 | 6% | <i>\$516.14</i> |
| EWP Premier 4HR ONSITE H34051 | 98008-H34051 | \$ 545.00 | 6% | <i>\$516.14</i> |
| EWP Premier 4HR ONSITE H34052 | 98008-H34052 | \$ 871.00 | 6% | <i>\$824.88</i> |
| EWP Premier 4HR ONSITE H34053 | 98008-H34053 | \$ 871.00 | 6% | <i>\$824.88</i> |
| EWP Premier 4HR ONSITE H34054 | 98008-H34054 | \$ 649.00 | 6% | <i>\$614.64</i> |
| EWP Premier 4HR ONSITE H34055 | 98008-H34055 | \$ 649.00 | 6% | <i>\$614.64</i> |
| EWP Premier 4HR ONSITE H34056 | 98008-H34056 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWP Premier 4HR ONSITE H34057 | 98008-H34057 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWP Premier 4HR ONSITE H34058 | 98008-H34058 | \$ 805.00 | 6% | <i>\$762.38</i> |
| EWP Premier 4HR ONSITE H34059 | 98008-H34059 | \$ 805.00 | 6% | <i>\$762.38</i> |
| EWP Premier 4HR ONSITE H34062 | 98008-H34062 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWP Premier 4HR ONSITE H34063 | 98008-H34063 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWP Premier 4HR ONSITE H34064 | 98008-H34064 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE H34065 | 98008-H34065 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE H34066 | 98008-H34066 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE H34067 | 98008-H34067 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE H34068 | 98008-H34068 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE H34069 | 98008-H34069 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier 4HR ONSITE H34070 | 98008-H34070 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE H34071 | 98008-H34071 | \$ 592.00 | 6% | <i>\$560.65</i> |
| EWP Premier 4HR ONSITE H34072 | 98008-H34072 | \$ 5,296.00 | 6% | <i>\$5,015.58</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H34073 | 98008-H34073 | \$ 5,195.00 | 6% | <i>\$4,919.92</i> |
| EWP Premier 4HR ONSITE H34074 | 98008-H34074 | \$ 6,650.00 | 6% | <i>\$6,297.88</i> |
| EWP Premier 4HR ONSITE H34075 | 98008-H34075 | \$ 6,380.00 | 6% | <i>\$6,042.18</i> |
| EWP Premier 4HR ONSITE H34076 | 98008-H34076 | \$ 5,296.00 | 6% | <i>\$5,015.58</i> |
| EWP Premier 4HR ONSITE H34077 | 98008-H34077 | \$ 5,195.00 | 6% | <i>\$4,919.92</i> |
| EWP Premier 4HR ONSITE H34078 | 98008-H34078 | \$ 5,296.00 | 6% | <i>\$5,015.58</i> |
| EWP Premier 4HR ONSITE H34079 | 98008-H34079 | \$ 5,195.00 | 6% | <i>\$4,919.92</i> |
| EWP Premier 4HR ONSITE H34080 | 98008-H34080 | \$ 6,650.00 | 6% | <i>\$6,297.88</i> |
| EWP Premier 4HR ONSITE H34081 | 98008-H34081 | \$ 6,380.00 | 6% | <i>\$6,042.18</i> |
| EWP Premier 4HR ONSITE H34082 | 98008-H34082 | \$ 6,347.00 | 6% | <i>\$6,010.93</i> |
| EWP Premier 4HR ONSITE H34083 | 98008-H34083 | \$ 6,090.00 | 6% | <i>\$5,767.53</i> |
| EWP Premier 4HR ONSITE H34084 | 98008-H34084 | \$ 4,256.00 | 6% | <i>\$4,030.64</i> |
| EWP Premier 4HR ONSITE H34085 | 98008-H34085 | \$ 4,256.00 | 6% | <i>\$4,030.64</i> |
| EWP Premier 4HR ONSITE H34086 | 98008-H34086 | \$ 4,980.00 | 6% | <i>\$4,716.31</i> |
| EWP Premier 4HR ONSITE H34087 | 98008-H34087 | \$ 4,753.00 | 6% | <i>\$4,501.33</i> |
| EWP Premier 4HR ONSITE H34088 | 98008-H34088 | \$ 11,387.00 | 6% | <i>\$10,784.06</i> |
| EWP Premier 4HR ONSITE H34089 | 98008-H34089 | \$ 11,387.00 | 6% | <i>\$10,784.06</i> |
| EWP Premier 4HR ONSITE H34090 | 98008-H34090 | \$ 13,113.00 | 6% | <i>\$12,418.67</i> |
| EWP Premier 4HR ONSITE H34091 | 98008-H34091 | \$ 10,294.00 | 6% | <i>\$9,748.93</i> |
| EWP Premier 4HR ONSITE H34092 | 98008-H34092 | \$ 10,294.00 | 6% | <i>\$9,748.93</i> |
| EWP Premier 4HR ONSITE H34093 | 98008-H34093 | \$ 10,294.00 | 6% | <i>\$9,748.93</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H34094 | 98008-H34094 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34095 | 98008-H34095 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34096 | 98008-H34096 | \$ 1,342.00 | 6% | <i>\$1,270.94</i> |
| EWP Premier 4HR ONSITE H34097 | 98008-H34097 | \$ 1,342.00 | 6% | <i>\$1,270.94</i> |
| EWP Premier 4HR ONSITE H34098 | 98008-H34098 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34099 | 98008-H34099 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34100 | 98008-H34100 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34101 | 98008-H34101 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34102 | 98008-H34102 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34103 | 98008-H34103 | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWP Premier 4HR ONSITE H34104 | 98008-H34104 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier 4HR ONSITE H34105 | 98008-H34105 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier 4HR ONSITE H34106 | 98008-H34106 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier 4HR ONSITE H34107 | 98008-H34107 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier 4HR ONSITE H34108 | 98008-H34108 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier 4HR ONSITE H34109 | 98008-H34109 | \$ 517.00 | 6% | <i>\$489.62</i> |
| EWP Premier 4HR ONSITE H34110 | 98008-H34110 | \$ 9,869.00 | 6% | <i>\$9,346.44</i> |
| EWP Premier 4HR ONSITE H34111 | 98008-H34111 | \$ 9,869.00 | 6% | <i>\$9,346.44</i> |
| EWP Premier 4HR ONSITE H34112 | 98008-H34112 | \$ 9,869.00 | 6% | <i>\$9,346.44</i> |
| EWP Premier 4HR ONSITE H34114 | 98008-H34114 | \$ 12,961.00 | 6% | <i>\$12,274.72</i> |
| EWP Premier 4HR ONSITE H34115 | 98008-H34115 | \$ 12,961.00 | 6% | <i>\$12,274.72</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H34116 | 98008-H34116 | \$ 12,961.00 | 6% | <i>\$12,274.72</i> |
| EWP Premier 4HR ONSITE H34117 | 98008-H34117 | \$ 12,961.00 | 6% | <i>\$12,274.72</i> |
| EWP Premier 4HR ONSITE H34118 | 98008-H34118 | \$ 3,273.00 | 6% | <i>\$3,099.69</i> |
| EWP Premier 4HR ONSITE H34119 | 98008-H34119 | \$ 3,273.00 | 6% | <i>\$3,099.69</i> |
| EWP Premier 4HR ONSITE H34120 | 98008-H34120 | \$ 2,252.00 | 6% | <i>\$2,132.76</i> |
| EWP Premier 4HR ONSITE H34121 | 98008-H34121 | \$ 2,252.00 | 6% | <i>\$2,132.76</i> |
| EWP Premier 4HR ONSITE H34122 | 98008-H34122 | \$ 2,353.00 | 6% | <i>\$2,228.41</i> |
| EWP Premier 4HR ONSITE H34123 | 98008-H34123 | \$ 2,353.00 | 6% | <i>\$2,228.41</i> |
| EWP Premier 4HR ONSITE H34124 | 98008-H34124 | \$ 3,505.00 | 6% | <i>\$3,319.41</i> |
| EWP Premier 4HR ONSITE H34125 | 98008-H34125 | \$ 3,505.00 | 6% | <i>\$3,319.41</i> |
| EWP Premier 4HR ONSITE H34126 | 98008-H34126 | \$ 3,505.00 | 6% | <i>\$3,319.41</i> |
| EWP Premier 4HR ONSITE H34127 | 98008-H34127 | \$ 3,505.00 | 6% | <i>\$3,319.41</i> |
| EWP Premier 4HR ONSITE H34128 | 98008-H34128 | \$ 378.00 | 6% | <i>\$357.98</i> |
| EWP Premier 4HR ONSITE H34129 | 98008-H34129 | \$ 815.00 | 6% | <i>\$771.85</i> |
| EWP Premier 4HR ONSITE H34130 | 98008-H34130 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR ONSITE H34131 | 98008-H34131 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR ONSITE H34132 | 98008-H34132 | \$ 846.00 | 6% | <i>\$801.20</i> |
| EWP Premier 4HR ONSITE H34172 | 98008-H34172 | \$ 2,818.00 | 6% | <i>\$2,668.79</i> |
| EWP Premier 4HR ONSITE H34726 | 98008-H34726 | \$ 5,511.00 | 6% | <i>\$5,219.19</i> |
| EWP Premier 4HR ONSITE H34727 | 98008-H34727 | \$ 5,511.00 | 6% | <i>\$5,219.19</i> |
| EWP Premier 4HR ONSITE H34728 | 98008-H34728 | \$ 5,511.00 | 6% | <i>\$5,219.19</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H34729 | 98008-H34729 | \$ 5,511.00 | 6% | <i>\$5,219.19</i> |
| EWP Premier 4HR ONSITE H34730 | 98008-H34730 | \$ 5,907.00 | 6% | <i>\$5,594.22</i> |
| EWP Premier 4HR ONSITE H34731 | 98008-H34731 | \$ 5,907.00 | 6% | <i>\$5,594.22</i> |
| EWP Premier 4HR ONSITE H34732 | 98008-H34732 | \$ 5,907.00 | 6% | <i>\$5,594.22</i> |
| EWP Premier 4HR ONSITE H34733 | 98008-H34733 | \$ 5,907.00 | 6% | <i>\$5,594.22</i> |
| EWP Premier 4HR ONSITE H34734 | 98008-H34734 | \$ 854.00 | 6% | <i>\$808.78</i> |
| EWP Premier 4HR ONSITE H34735 | 98008-H34735 | \$ 854.00 | 6% | <i>\$808.78</i> |
| EWP Premier 4HR ONSITE H34736 | 98008-H34736 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34737 | 98008-H34737 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34738 | 98008-H34738 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34739 | 98008-H34739 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34740 | 98008-H34740 | \$ 854.00 | 6% | <i>\$808.78</i> |
| EWP Premier 4HR ONSITE H34741 | 98008-H34741 | \$ 854.00 | 6% | <i>\$808.78</i> |
| EWP Premier 4HR ONSITE H34742 | 98008-H34742 | \$ 706.00 | 6% | <i>\$668.62</i> |
| EWP Premier 4HR ONSITE H34743 | 98008-H34743 | \$ 706.00 | 6% | <i>\$668.62</i> |
| EWP Premier 4HR ONSITE H34744 | 98008-H34744 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34745 | 98008-H34745 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34746 | 98008-H34746 | \$ 1,233.00 | 6% | <i>\$1,167.71</i> |
| EWP Premier 4HR ONSITE H34747 | 98008-H34747 | \$ 1,233.00 | 6% | <i>\$1,167.71</i> |
| EWP Premier 4HR ONSITE H34748 | 98008-H34748 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34749 | 98008-H34749 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H34750 | 98008-H34750 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34751 | 98008-H34751 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34752 | 98008-H34752 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34753 | 98008-H34753 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34754 | 98008-H34754 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34755 | 98008-H34755 | \$ 2,058.00 | 6% | <i>\$1,949.03</i> |
| EWP Premier 4HR ONSITE H34756 | 98008-H34756 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34757 | 98008-H34757 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34758 | 98008-H34758 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34759 | 98008-H34759 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34760 | 98008-H34760 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34761 | 98008-H34761 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H34839 | 98008-H34839 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34840 | 98008-H34840 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34841 | 98008-H34841 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34842 | 98008-H34842 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34843 | 98008-H34843 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34844 | 98008-H34844 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34845 | 98008-H34845 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34846 | 98008-H34846 | \$ 867.00 | 6% | <i>\$821.09</i> |
| EWP Premier 4HR ONSITE H34993 | 98008-H34993 | \$ 21,483.00 | 6% | <i>\$20,345.48</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H34994 | 98008-H34994 | \$ 21,483.00 | 6% | <i>\$20,345.48</i> |
| EWP Premier 4HR ONSITE H34996 | 98008-H34996 | \$ 21,483.00 | 6% | <i>\$20,345.48</i> |
| EWP Premier 4HR ONSITE H34997 | 98008-H34997 | \$ 21,483.00 | 6% | <i>\$20,345.48</i> |
| EWP Premier 4HR ONSITE H35005 | 98008-H35005 | \$ 16,772.00 | 6% | <i>\$15,883.92</i> |
| EWP Premier 4HR ONSITE H35006 | 98008-H35006 | \$ 16,772.00 | 6% | <i>\$15,883.92</i> |
| EWP Premier 4HR ONSITE H35012 | 98008-H35012 | \$ 10,063.00 | 6% | <i>\$9,530.16</i> |
| EWP Premier 4HR ONSITE H35262 | 98008-H35262 | \$ 4,067.00 | 6% | <i>\$3,851.65</i> |
| EWP Premier 4HR ONSITE H35270 | 98008-H35270 | \$ 871.00 | 6% | <i>\$824.88</i> |
| EWP Premier 4HR ONSITE H35271 | 98008-H35271 | \$ 649.00 | 6% | <i>\$614.64</i> |
| EWP Premier 4HR ONSITE H35273 | 98008-H35273 | \$ 566.00 | 6% | <i>\$536.03</i> |
| EWP Premier 4HR ONSITE H35274 | 98008-H35274 | \$ 1,233.00 | 6% | <i>\$1,167.71</i> |
| EWP Premier 4HR ONSITE H35275 | 98008-H35275 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWP Premier 4HR ONSITE H35276 | 98008-H35276 | \$ 5,296.00 | 6% | <i>\$5,015.58</i> |
| EWP Premier 4HR ONSITE H35277 | 98008-H35277 | \$ 6,347.00 | 6% | <i>\$6,010.93</i> |
| EWP Premier 4HR ONSITE H35278 | 98008-H35278 | \$ 4,256.00 | 6% | <i>\$4,030.64</i> |
| EWP Premier 4HR ONSITE H35279 | 98008-H35279 | \$ 4,753.00 | 6% | <i>\$4,501.33</i> |
| EWP Premier 4HR ONSITE H35280 | 98008-H35280 | \$ 9,680.00 | 6% | <i>\$9,167.44</i> |
| EWP Premier 4HR ONSITE H35281 | 98008-H35281 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE H35282 | 98008-H35282 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE H35283 | 98008-H35283 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE H35284 | 98008-H35284 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier 4HR ONSITE H35285 | 98008-H35285 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE H35286 | 98008-H35286 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE H35287 | 98008-H35287 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE H35288 | 98008-H35288 | \$ 2,914.00 | 6% | <i>\$2,759.70</i> |
| EWP Premier 4HR ONSITE H35289 | 98008-H35289 | \$ 7,642.00 | 6% | <i>\$7,237.36</i> |
| EWP Premier 4HR ONSITE H35291 | 98008-H35291 | \$ 5,500.00 | 6% | <i>\$5,208.78</i> |
| EWP Premier 4HR ONSITE H35294 | 98008-H35294 | \$ 1,944.00 | 6% | <i>\$1,841.07</i> |
| EWP Premier 4HR ONSITE H35295 | 98008-H35295 | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWP Premier 4HR ONSITE H35296 | 98008-H35296 | \$ 11,526.00 | 6% | <i>\$10,915.70</i> |
| EWP Premier 4HR ONSITE H35297 | 98008-H35297 | \$ 11,526.00 | 6% | <i>\$10,915.70</i> |
| EWP Premier 4HR ONSITE H35298 | 98008-H35298 | \$ 18,521.00 | 6% | <i>\$17,540.31</i> |
| EWP Premier 4HR ONSITE H35299 | 98008-H35299 | \$ 18,521.00 | 6% | <i>\$17,540.31</i> |
| EWP Premier 4HR ONSITE H35302 | 98008-H35302 | \$ 4,511.00 | 6% | <i>\$4,272.14</i> |
| EWP Premier 4HR ONSITE H35303 | 98008-H35303 | \$ 4,511.00 | 6% | <i>\$4,272.14</i> |
| EWP Premier 4HR ONSITE H35304 | 98008-H35304 | \$ 4,511.00 | 6% | <i>\$4,272.14</i> |
| EWP Premier 4HR ONSITE H35305 | 98008-H35305 | \$ 4,728.00 | 6% | <i>\$4,477.65</i> |
| EWP Premier 4HR ONSITE H35306 | 98008-H35306 | \$ 4,728.00 | 6% | <i>\$4,477.65</i> |
| EWP Premier 4HR ONSITE H35307 | 98008-H35307 | \$ 4,728.00 | 6% | <i>\$4,477.65</i> |
| EWP Premier 4HR ONSITE H35309 | 98008-H35309 | \$ 5,807.00 | 6% | <i>\$5,499.52</i> |
| EWP Premier 4HR ONSITE H35310 | 98008-H35310 | \$ 5,807.00 | 6% | <i>\$5,499.52</i> |
| EWP Premier 4HR ONSITE H35311 | 98008-H35311 | \$ 5,807.00 | 6% | <i>\$5,499.52</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H35312 | 98008-H35312 | \$ 4,796.00 | 6% | <i>\$4,542.05</i> |
| EWP Premier 4HR ONSITE H35313 | 98008-H35313 | \$ 4,796.00 | 6% | <i>\$4,542.05</i> |
| EWP Premier 4HR ONSITE H35314 | 98008-H35314 | \$ 4,796.00 | 6% | <i>\$4,542.05</i> |
| EWP Premier 4HR ONSITE H35315 | 98008-H35315 | \$ 2,132.00 | 6% | <i>\$2,019.11</i> |
| EWP Premier 4HR ONSITE H35318 | 98008-H35318 | \$ 1,021.00 | 6% | <i>\$966.94</i> |
| EWP Premier 4HR ONSITE H35319 | 98008-H35319 | \$ 1,373.00 | 6% | <i>\$1,300.30</i> |
| EWP Premier 4HR ONSITE H35320 | 98008-H35320 | \$ 1,423.00 | 6% | <i>\$1,347.65</i> |
| EWP Premier 4HR ONSITE H35321 | 98008-H35321 | \$ 1,782.00 | 6% | <i>\$1,687.64</i> |
| EWP Premier 4HR ONSITE H35322 | 98008-H35322 | \$ 2,172.00 | 6% | <i>\$2,056.99</i> |
| EWP Premier 4HR ONSITE H35323 | 98008-H35323 | \$ 2,132.00 | 6% | <i>\$2,019.11</i> |
| EWP Premier 4HR ONSITE H35328 | 98008-H35328 | \$ 183.00 | 6% | <i>\$173.31</i> |
| EWP Premier 4HR ONSITE H35330 | 98008-H35330 | \$ 147.00 | 6% | <i>\$139.22</i> |
| EWP Premier 4HR ONSITE H35340 | 98008-H35340 | \$ 4,302.00 | 6% | <i>\$4,074.21</i> |
| EWP Premier 4HR ONSITE H35341 | 98008-H35341 | \$ 4,302.00 | 6% | <i>\$4,074.21</i> |
| EWP Premier 4HR ONSITE H35342 | 98008-H35342 | \$ 3,647.00 | 6% | <i>\$3,453.89</i> |
| EWP Premier 4HR ONSITE H35343 | 98008-H35343 | \$ 4,302.00 | 6% | <i>\$4,074.21</i> |
| EWP Premier 4HR ONSITE H35344 | 98008-H35344 | \$ 4,450.00 | 6% | <i>\$4,214.37</i> |
| EWP Premier 4HR ONSITE H35345 | 98008-H35345 | \$ 4,450.00 | 6% | <i>\$4,214.37</i> |
| EWP Premier 4HR ONSITE H35346 | 98008-H35346 | \$ 3,756.00 | 6% | <i>\$3,557.12</i> |
| EWP Premier 4HR ONSITE H35347 | 98008-H35347 | \$ 4,450.00 | 6% | <i>\$4,214.37</i> |
| EWP Premier 4HR ONSITE H35349 | 98008-H35349 | \$ 4,811.00 | 6% | <i>\$4,556.26</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H35350 | 98008-H35350 | \$ 4,812.00 | 6% | <i>\$4,557.20</i> |
| EWP Premier 4HR ONSITE H35351 | 98008-H35351 | \$ 4,048.00 | 6% | <i>\$3,833.66</i> |
| EWP Premier 4HR ONSITE H35352 | 98008-H35352 | \$ 4,812.00 | 6% | <i>\$4,557.20</i> |
| EWP Premier 4HR ONSITE H35359 | 98008-H35359 | \$ 1,782.00 | 6% | <i>\$1,687.64</i> |
| EWP Premier 4HR ONSITE H35360 | 98008-H35360 | \$ 2,172.00 | 6% | <i>\$2,056.99</i> |
| EWP Premier 4HR ONSITE H35361 | 98008-H35361 | \$ 2,132.00 | 6% | <i>\$2,019.11</i> |
| EWP Premier 4HR ONSITE H35362 | 98008-H35362 | \$ 1,021.00 | 6% | <i>\$966.94</i> |
| EWP Premier 4HR ONSITE H35366 | 98008-H35366 | \$ 2,056.00 | 6% | <i>\$1,947.13</i> |
| EWP Premier 4HR ONSITE H35367 | 98008-H35367 | \$ 2,398.00 | 6% | <i>\$2,271.03</i> |
| EWP Premier 4HR ONSITE H35368 | 98008-H35368 | \$ 3,659.00 | 6% | <i>\$3,465.26</i> |
| EWP Premier 4HR ONSITE H35369 | 98008-H35369 | \$ 1,192.00 | 6% | <i>\$1,128.88</i> |
| EWP Premier 4HR ONSITE H35370 | 98008-H35370 | \$ 1,673.00 | 6% | <i>\$1,584.41</i> |
| EWP Premier 4HR ONSITE H35375 | 98008-H35375 | \$ 1,011.00 | 6% | <i>\$957.47</i> |
| EWP Premier 4HR ONSITE H35376 | 98008-H35376 | \$ 1,517.00 | 6% | <i>\$1,436.67</i> |
| EWP Premier 4HR ONSITE H35377 | 98008-H35377 | \$ 636.00 | 6% | <i>\$602.32</i> |
| EWP Premier 4HR ONSITE H35378 | 98008-H35378 | \$ 1,011.00 | 6% | <i>\$957.47</i> |
| EWP Premier 4HR ONSITE H35379 | 98008-H35379 | \$ 636.00 | 6% | <i>\$602.32</i> |
| EWP Premier 4HR ONSITE H35380 | 98008-H35380 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| EWP Premier 4HR ONSITE H35381 | 98008-H35381 | \$ 1,393.00 | 6% | <i>\$1,319.24</i> |
| EWP Premier 4HR ONSITE H35384 | 98008-H35384 | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWP Premier 4HR ONSITE H35385 | 98008-H35385 | \$ 610.00 | 6% | <i>\$577.70</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H35386 | 98008-H35386 | \$ 1,011.00 | 6% | <i>\$957.47</i> |
| EWP Premier 4HR ONSITE H35387 | 98008-H35387 | \$ 946.00 | 6% | <i>\$895.91</i> |
| EWP Premier 4HR ONSITE H35388 | 98008-H35388 | \$ 700.00 | 6% | <i>\$662.94</i> |
| EWP Premier 4HR ONSITE H35389 | 98008-H35389 | \$ 395.00 | 6% | <i>\$374.08</i> |
| EWP Premier 4HR ONSITE H35390 | 98008-H35390 | \$ 339.00 | 6% | <i>\$321.05</i> |
| EWP Premier 4HR ONSITE H35391 | 98008-H35391 | \$ 747.00 | 6% | <i>\$707.45</i> |
| EWP Premier 4HR ONSITE H35392 | 98008-H35392 | \$ 1,141.00 | 6% | <i>\$1,080.58</i> |
| EWP Premier 4HR ONSITE H35393 | 98008-H35393 | \$ 1,517.00 | 6% | <i>\$1,436.67</i> |
| EWP Premier 4HR ONSITE H35394 | 98008-H35394 | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier 4HR ONSITE H35395 | 98008-H35395 | \$ 234.00 | 6% | <i>\$221.61</i> |
| EWP Premier 4HR ONSITE H35396 | 98008-H35396 | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier 4HR ONSITE H35397 | 98008-H35397 | \$ 234.00 | 6% | <i>\$221.61</i> |
| EWP Premier 4HR ONSITE H35398 | 98008-H35398 | \$ 713.00 | 6% | <i>\$675.25</i> |
| EWP Premier 4HR ONSITE H35399 | 98008-H35399 | \$ 862.00 | 6% | <i>\$816.36</i> |
| EWP Premier 4HR ONSITE H35400 | 98008-H35400 | \$ 953.00 | 6% | <i>\$902.54</i> |
| EWP Premier 4HR ONSITE H35401 | 98008-H35401 | \$ 506.00 | 6% | <i>\$479.21</i> |
| EWP Premier 4HR ONSITE H35415 | 98008-H35415 | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWP Premier 4HR ONSITE H35416 | 98008-H35416 | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWP Premier 4HR ONSITE H35426 | 98008-H35426 | \$ 395.00 | 6% | <i>\$374.08</i> |
| EWP Premier 4HR ONSITE H35427 | 98008-H35427 | \$ 946.00 | 6% | <i>\$895.91</i> |
| EWP Premier 4HR ONSITE H35428 | 98008-H35428 | \$ 339.00 | 6% | <i>\$321.05</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE H35429 | 98008-H35429 | \$ 747.00 | 6% | <i>\$707.45</i> |
| EWP Premier 4HR ONSITE H35430 | 98008-H35430 | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWP Premier 4HR ONSITE H35431 | 98008-H35431 | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWP Premier 4HR ONSITE H35432 | 98008-H35432 | \$ 706.00 | 6% | <i>\$668.62</i> |
| EWP Premier 4HR ONSITE H35433 | 98008-H35433 | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| EWP Premier 4HR ONSITE H35434 | 98008-H35434 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| EWP Premier 4HR ONSITE H35435 | 98008-H35435 | \$ 1,174.00 | 6% | <i>\$1,111.84</i> |
| EWP Premier 4HR ONSITE H35436 | 98008-H35436 | \$ 1,960.00 | 6% | <i>\$1,856.22</i> |
| EWP Premier 4HR ONSITE H35437 | 98008-H35437 | \$ 1,960.00 | 6% | <i>\$1,856.22</i> |
| EWP Premier 4HR ONSITE H35438 | 98008-H35438 | \$ 1,960.00 | 6% | <i>\$1,856.22</i> |
| EWP Premier 4HR ONSITE H35439 | 98008-H35439 | \$ 1,960.00 | 6% | <i>\$1,856.22</i> |
| EWP Premier 4HR ONSITE H35440 | 98008-H35440 | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| EWP Premier 4HR ONSITE H35441 | 98008-H35441 | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| EWP Premier 4HR ONSITE H35442 | 98008-H35442 | \$ 1,036.00 | 6% | <i>\$981.14</i> |
| EWP Premier 4HR ONSITE H35443 | 98008-H35443 | \$ 5,511.00 | 6% | <i>\$5,219.19</i> |
| EWP Premier 4HR ONSITE H35444 | 98008-H35444 | \$ 5,907.00 | 6% | <i>\$5,594.22</i> |
| EWP Premier 4HR ONSITE H35445 | 98008-H35445 | \$ 5,296.00 | 6% | <i>\$5,015.58</i> |
| EWP Premier 4HR ONSITE H35446 | 98008-H35446 | \$ 5,195.00 | 6% | <i>\$4,919.92</i> |
| EWP Premier 4HR ONSITE H35447 | 98008-H35447 | \$ 6,045.00 | 6% | <i>\$5,724.92</i> |
| EWP Premier 4HR ONSITE H35448 | 98008-H35448 | \$ 5,800.00 | 6% | <i>\$5,492.89</i> |
| EWP Premier 4HR ONSITE H35449 | 98008-H35449 | \$ 4,256.00 | 6% | <i>\$4,030.64</i> |

| | | | | |
|--|-------------------------|--------------|----|-------------------|
| EWP Premier 4HR ONSITE H35450 | 98008-H35450 | \$ 4,527.00 | 6% | <i>\$4,287.30</i> |
| EWP Premier 4HR ONSITE H35451 | 98008-H35451 | \$ 10,294.00 | 6% | <i>\$9,748.93</i> |
| EWP Premier 4HR ONSITE H35452 | 98008-H35452 | \$ 10,294.00 | 6% | <i>\$9,748.93</i> |
| EWP Premier 4HR ONSITE H35453 | 98008-H35453 | \$ 5,907.00 | 6% | <i>\$5,594.22</i> |
| EWP Premier 4HR ONSITE H35454 | 98008-H35454 | \$ 5,511.00 | 6% | <i>\$5,219.19</i> |
| EWP Premier 4HR ONSITE H35455 | 98008-H35455 | \$ 1,423.00 | 6% | <i>\$1,347.65</i> |
| EWP Premier 4HR ONSITE H35456 | 98008-H35456 | \$ 1,760.00 | 6% | <i>\$1,666.81</i> |
| EWP Premier 4HR ONSITE H35457 | 98008-H35457 | \$ 1,586.00 | 6% | <i>\$1,502.02</i> |
| EWP Premier 4HR ONSITE H35458 | 98008-H35458 | \$ 1,740.00 | 6% | <i>\$1,647.87</i> |
| EWP Premier 4HR ONSITE H35471 | 98008-H35471 | \$ 1,423.00 | 6% | <i>\$1,347.65</i> |
| EWP Premier 4HR ONSITE H35600 | 98008-H35600 | \$ 566.00 | 6% | <i>\$536.03</i> |
| EWP Premier 4HR ONSITE H35601 | 98008-H35601 | \$ 566.00 | 6% | <i>\$536.03</i> |
| EWP Premier 4HR ONSITE H35602 | 98008-H35602 | \$ 854.00 | 6% | <i>\$808.78</i> |
| EWP Premier 4HR ONSITE H35603 | 98008-H35603 | \$ 854.00 | 6% | <i>\$808.78</i> |
| EWP Premier 4HR ONSITE H35604 | 98008-H35604 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H35605 | 98008-H35605 | \$ 1,088.00 | 6% | <i>\$1,030.39</i> |
| EWP Premier 4HR ONSITE H35606 | 98008-H35606 | \$ 1,233.00 | 6% | <i>\$1,167.71</i> |
| EWP Premier 4HR ONSITE H35607 | 98008-H35607 | \$ 1,233.00 | 6% | <i>\$1,167.71</i> |
| EWP Premier 4HR ONSITE ISW- 24W-4X | 98008-ISW- 24W-4X | \$ 1,460.00 | 6% | <i>\$1,382.69</i> |
| EWP Premier 4HR ONSITE ISW- 4W-4WS-4X | 98008-ISW-4W- 4WS-4X | \$ 927.00 | 6% | <i>\$877.92</i> |
| EWP Premier 4HR ONSITE MSM128 | 98008- MSM128 | \$ 4,826.00 | 6% | <i>\$4,570.46</i> |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EWP Premier 4HR ONSITE MSM48C | 98008- MSM48C | \$ 2,872.00 | 6% | <i>\$2,719.93</i> |
| EWP Premier 4HR ONSITE SLX9150-48XT-DC-F | 98008- SLX9150- 48XT-DC-F | \$ 3,843.00 | 6% | <i>\$3,639.51</i> |
| EWP Premier 4HR ONSITE SLX9150-48XT-DC-R | 98008- SLX9150- 48XT-DC-R | \$ 4,237.00 | 6% | <i>\$4,012.65</i> |
| EWP Premier 4HR ONSITE SLX9150-48Y-DC-F | 98008- SLX9150-48Y- DC-F | \$ 3,716.00 | 6% | <i>\$3,519.24</i> |
| EWP Premier 4HR ONSITE SLX9150-48Y-DC-R | 98008- SLX9150-48Y- DC-R | \$ 4,097.00 | 6% | <i>\$3,880.06</i> |
| EWP Premier 4HR ONSITE SLX9740-40C | 98008- SLX9740-40C | \$ 18,479.00 | 6% | <i>\$17,500.54</i> |
| EWP Premier 4HR ONSITE SLX9740-40C-AC-F | 98008- SLX9740-40C- AC-F | \$ 18,479.00 | 6% | <i>\$17,500.54</i> |
| EWP Premier 4HR ONSITE SLX9740-40C-AC-R | 98008- SLX9740-40C- AC-R | \$ 18,479.00 | 10% | <i>\$16,755.83</i> |
| EWP Premier 4HR ONSITE SLX9740-40C-DC-F | 98008- SLX9740-40C- DC-F | \$ 18,479.00 | 6% | <i>\$17,500.54</i> |
| EWP Premier 4HR ONSITE SLX9740-80C | 98008- SLX9740-80C | \$ 34,749.00 | 6% | <i>\$32,909.04</i> |
| EWP Premier 4HR ONSITE SLX9740-80C-AC-F | 98008- SLX9740-80C- AC-F | \$ 34,749.00 | 6% | <i>\$32,909.04</i> |
| EWP Premier 4HR ONSITE SLX9740-80C-AC-R | 98008- SLX9740-80C- AC-R | \$ 34,749.00 | 10% | <i>\$31,508.66</i> |
| EWP Premier 4HR ONSITE SLX9740-80C-DC-F | 98008- SLX9740-80C- DC-F | \$ 34,749.00 | 6% | <i>\$32,909.04</i> |
| EWP Premier 4HR ONSITE V300-8P-2X | 98008-V300- 8P-2X | \$ 238.00 | 6% | <i>\$225.40</i> |
| EWP Premier 4HR ONSITE V300-8T-2X | 98008-V300- 8T-2X | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier 4HR ONSITE V300HT-8P-2X | 98008-V300HT- 8P-2X | \$ 545.00 | 6% | <i>\$516.14</i> |

| | | | | |
|---|---|-------------|----|------------|
| EWP Premier 4HR ONSITE V300HT-8T-2X | 98008-V300HT- 8T-2X | \$ 327.00 | 6% | \$309.69 |
| EWP Premier 4HR ONSITE VIM-SS | 98008-VIM-SS | \$ 246.00 | 6% | \$232.97 |
| EWPPremier 4HR ONSITE VIM- SSV8 | 98008-VIM- SSV80 | \$ 464.00 | 6% | \$439.43 |
| EWP Premier 4HR ONSITE VIM2-SS | 98008-VIM2- SS | \$ 290.00 | 6% | \$274.64 |
| EWPPremier 4HR ONSITE VIM2-SS1 | 98008-VIM2- SS128 | \$ 998.00 | 6% | \$945.16 |
| EWPPremier 4HR ONSITE VIM2-V80 | 98008-VIM2- V80 | \$ 1,065.00 | 6% | \$1,008.61 |
| EWPPremier 4HR ONSITE VIM210G4 | 98008- VIM210G4X | \$ 1,844.00 | 6% | \$1,746.36 |
| EWP Premier 4HR ONSITE VIM5-2Q | 98008-VIM5- 2Q | \$ 329.00 | 6% | \$311.58 |
| EWP Premier 4HR ONSITE VIM5-2Y | 98008-VIM5- 2Y | \$ 383.00 | 6% | \$362.72 |
| EWP Premier 4HR ONSITE VIM5-4X | 98008-VIM5- 4X | \$ 162.00 | 6% | \$153.42 |
| EWP Premier 4HR ONSITE VIM5-4XE | 98008-VIM5- 4XE | \$ 318.00 | 6% | \$301.16 |
| EWP Premier 4HR ONSITE VIM5-4Y | 98008-VIM5- 4Y | \$ 491.00 | 6% | \$465.00 |
| EWP Premier 4HR ONSITE VIM5-4YE | 98008-VIM5- 4YE | \$ 634.00 | 6% | \$600.43 |
| EWP Prem 4HR ONSIT VSP4900-12MXU-12XE | 98008- VSP4900- 12MXU-12XE | \$ 1,869.00 | 6% | \$1,770.04 |
| EWP Prem 4HR ONSIT VSP4900-12MXU-12XE-B1 | 98008- VSP4900- 12MXU-12XE- B1 | \$ 1,869.00 | 6% | \$1,770.04 |
| EWP Premier 4HR ONSITE VSP4900-24S | 98008- VSP4900-24S | \$ 1,021.00 | 6% | \$966.94 |
| EWP Premier 4HR ONSITE VSP4900-24S-B3 | 98008- VSP4900-24S- B3 | \$ 1,021.00 | 6% | \$966.94 |
| EWP Premier 4HR ONSITE VSP4900-24XE | 98008- VSP4900- 24XE | \$ 1,869.00 | 6% | \$1,770.04 |

| | | | | |
|---|-------------------------------|-------------|----|-------------------|
| EWP Premier 4HR ONSITE VSP4900-24XE-B3 | 98008- VSP4900- 24XE-B3 | \$ 1,869.00 | 6% | <i>\$1,770.04</i> |
| EWP Premier 4HR ONSITE X435-24P-4S | 98008-X435- 24P-4S | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWP Premier 4HR ONSITE X435-24T-4S | 98008-X435- 24T-4S | \$ 234.00 | 6% | <i>\$221.61</i> |
| EWP Premier 4HR ONSITE X435-8P-2T-W | 98008-X435- 8P-2T-W | \$ 234.00 | 6% | <i>\$221.61</i> |
| EWP Premier 4HR ONSITE X435-8P-4S | 98008-X435- 8P-4S | \$ 211.00 | 6% | <i>\$199.83</i> |
| EWP Premier 4HR ONSITE X435-8T-4S | 98008-X435- 8T-4S | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWPPremier 4HR ONSITE X460-24P | 98008-X460- 24P | \$ 1,660.00 | 6% | <i>\$1,572.10</i> |
| EWPPremier 4HR ONSITE X460-24T | 98008-X460- 24T | \$ 1,189.00 | 6% | <i>\$1,126.04</i> |
| EWPPremier 4HR ONSITE X460-24T | 98008-X460- 24TDC | \$ 1,747.00 | 6% | <i>\$1,654.50</i> |
| EWPPremier 4HR ONSITE X460-24X | 98008-X460- 24X | \$ 2,195.00 | 6% | <i>\$2,078.77</i> |
| EWPPremier 4HR ONSITE X460-24X | 98008-X460- 24XDC | \$ 2,452.00 | 6% | <i>\$2,322.17</i> |
| EWPPremier 4HR ONSITE X460-48P | 98008-X460- 48P | \$ 2,195.00 | 6% | <i>\$2,078.77</i> |
| EWPPremier 4HR ONSITE X460-48T | 98008-X460- 48T | \$ 1,879.00 | 6% | <i>\$1,779.51</i> |
| EWPPremier 4HR ONSITE X460-48T | 98008-X460- 48TDC | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |
| EWPPremier 4HR ONSITE X460-48X | 98008-X460- 48X | \$ 2,928.00 | 6% | <i>\$2,772.96</i> |
| EWPPremier 4HR ONSITE X460-48X | 98008-X460- 48XDC | \$ 2,847.00 | 6% | <i>\$2,696.25</i> |
| EWP Premier 4HR ONSITE X465-24MU | 98008-X465- 24MU | \$ 2,172.00 | 6% | <i>\$2,056.99</i> |
| EWP Premier 4HR ONSITE X465-24S | 98008-X465- 24S | \$ 1,021.00 | 6% | <i>\$966.94</i> |
| EWP Premier 4HR ONSITE X465-24S-B3 | 98008-X465- 24S-B3 | \$ 1,021.00 | 6% | <i>\$966.94</i> |
| EWP Premier 4HR ONSITE X465-24W | 98008-X465- 24W | \$ 1,021.00 | 6% | <i>\$966.94</i> |

| | | | | |
|--|--------------------------------|-------------|-----|-------------------|
| EWP Premier 4HR ONSITE X465-24XE | 98008-X465- 24XE | \$ 1,869.00 | 6% | <i>\$1,770.04</i> |
| EWP Premier 4HR ONSITE X465-24XE-B3 | 98008-X465- 24XE-B3 | \$ 1,869.00 | 6% | <i>\$1,770.04</i> |
| EWP Premier 4HR ONSITE X465-48P | 98008-X465- 48P | \$ 1,423.00 | 6% | <i>\$1,347.65</i> |
| EWP Premier 4HR ONSITE X465-48T | 98008-X465- 48T | \$ 1,373.00 | 6% | <i>\$1,300.30</i> |
| EWP Premier 4HR ONSITE X465-48W | 98008-X465- 48W | \$ 1,782.00 | 6% | <i>\$1,687.64</i> |
| EWP Premier 4HR ONSITE X465i-48W | 98008-X465i- 48W | \$ 2,132.00 | 6% | <i>\$2,019.11</i> |
| EWP Premier 4HR ONSITE X465i-48W-B1-S1 | 98008-X465i- 48W-B1-S1 | \$ 2,132.00 | 6% | <i>\$2,019.11</i> |
| EWP Premier 4HR ONSITE X465i-48W-B2-S1 | 98008-X465i- 48W-B2-S1 | \$ 2,132.00 | 6% | <i>\$2,019.11</i> |
| EWPPremier 4HR ONSITE X480-24X | 98008-X480- 24X | \$ 2,755.00 | 6% | <i>\$2,609.12</i> |
| EWPPremier 4HR ONSITE X480-48T | 98008-X480- 48T | \$ 2,755.00 | 6% | <i>\$2,609.12</i> |
| EWPPremier 4HR ONSITE X480-48X | 98008-X480- 48X | \$ 3,674.00 | 6% | <i>\$3,479.46</i> |
| EWP Premier 4HR ONSITE X695-48Y-8C | 98008-X695- 48Y-8C | \$ 4,963.00 | 6% | <i>\$4,700.21</i> |
| EWP Premier 4HR ONSITE XA1440 | 98008-XA1440 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWP Premier 4HR ONSITE XA1480 | 98008-XA1480 | \$ 695.00 | 6% | <i>\$658.20</i> |
| EWPPremier 4HR ONSITE XGM3-2SF | 98008-XGM3- 2SF | \$ 464.00 | 6% | <i>\$439.43</i> |
| EWP Premier 4HR ONSITE XR600 | 98008-XR600 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier 4HR ONSITE XSW-BR-M-A-D | 98008-XSW- BR-M-A-D | \$ 447.00 | 10% | <i>\$405.32</i> |
| EWP Premier 4HR ONSITE XSW-BR-M-A-D-3YR | 98008-XSW- BR-M-A-D- 3YR | \$ 1,340.00 | 10% | <i>\$1,215.05</i> |
| EWP Premier 4HR ONSITE XSW-BR-M-A-D-5YR | 98008-XSW- BR-M-A-D- 5YR | \$ 2,233.00 | 10% | <i>\$2,024.77</i> |
| EWP Premier 4HR ONSITE XSW-BR-S-A-D | 98008-XSW- BR-S-A-D | \$ 255.00 | 10% | <i>\$231.22</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EWP Premier 4HR ONSITE XSW-BR-S-A-D-3YR | 98008-XSW- BR-S-A-D- 3YR | \$ 766.00 | 10% | <i>\$694.57</i> |
| EWP Premier 4HR ONSITE XSW-BR-S-A-D-5YR | 98008-XSW- BR-S-A-D- 5YR | \$ 1,276.00 | 10% | <i>\$1,157.01</i> |
| EWP Premier 4HR ONSITE XSW-BR-XS-A-D | 98008-XSW- BR-XS-A-D | \$ 207.00 | 10% | <i>\$187.70</i> |
| EWP Premier 4HR ONSITE XSW-BR-XS-A-D-3YR | 98008-XSW- BR-XS-A-D- 3YR | \$ 620.00 | 10% | <i>\$562.19</i> |
| EWP Premier 4HR ONSITE XSW-BR-XS-A-D-5YR | 98008-XSW- BR-XS-A-D- 5YR | \$ 1,033.00 | 10% | <i>\$936.67</i> |
| EWP Premier 4HR ONSITE XSW-DC-M-A-D | 98008-XSW- DC-M-A-D | \$ 1,658.00 | 10% | <i>\$1,503.39</i> |
| EWP Premier 4HR ONSITE XSW-DC-M-A-D-3YR | 98008-XSW- DC-M-A-D- 3YR | \$ 4,975.00 | 10% | <i>\$4,511.08</i> |
| EWP Premier 4HR ONSITE XSW-DC-M-A-D-5YR | 98008-XSW- DC-M-A-D- 5YR | \$ 8,292.00 | 10% | <i>\$7,518.77</i> |
| EWP Premier 4HR ONSITE XSW-DC-S-A-D | 98008-XSW- DC-S-A-D | \$ 766.00 | 10% | <i>\$694.57</i> |
| EWP Premier 4HR ONSITE XSW-DC-S-A-D-3YR | 98008-XSW- DC-S-A-D- 3YR | \$ 2,297.00 | 10% | <i>\$2,082.80</i> |
| EWP Premier 4HR ONSITE XSW-DC-S-A-D-5YR | 98008-XSW- DC-S-A-D- 5YR | \$ 3,828.00 | 10% | <i>\$3,471.04</i> |
| EWP Premier 4HR ONSITE XSW-DC-SR-L-A-D | 98008-XSW- DC-SR-L-A-D | \$ 1,914.00 | 10% | <i>\$1,735.52</i> |
| EWP Premier 4HR OS XSW-DC- SR-L-A-D-3YR | 98008-XSW- DC-SR-L-A-D- 3YR | \$ 5,741.00 | 10% | <i>\$5,205.65</i> |
| EWP Premier 4HR OS XSW-DC- SR-L-A-D-5YR | 98008-XSW- DC-SR-L-A-D- 5YR | \$ 9,568.00 | 10% | <i>\$8,675.78</i> |
| EWP Premier 4HR ONSITE XSW-DCV2-LR-L-A-D | 98008-XSW- DCV2-LR-L-A- D | \$ 1,914.00 | 10% | <i>\$1,735.52</i> |

| | | | | |
|--|-----------------------------|-------------|-----|------------|
| EWP Premier 4HR OS XSW-DCV2-LR-L-A-D-3YR | 98008-XSW-DCV2-LR-L-A-D-3YR | \$ 5,741.00 | 10% | \$5,205.65 |
| EWP Premier 4HR OS XSW-DCV2-LR-L-A-D-5YR | 98008-XSW-DCV2-LR-L-A-D-5YR | \$ 9,568.00 | 10% | \$8,675.78 |
| EWP Premier 4HR ONSITE XSW-DCV2-M-A-D | 98008-XSW-DCV2-M-A-D | \$ 1,658.00 | 10% | \$1,503.39 |
| EWP Prem 4HR ONSITE XSW-DCV2-M-A-D-3YR | 98008-XSW-DCV2-M-A-D-3YR | \$ 4,975.00 | 10% | \$4,511.08 |
| EWP Prem 4HR ONSITE XSW-DCV2-M-A-D-5YR | 98008-XSW-DCV2-M-A-D-5YR | \$ 8,292.00 | 10% | \$7,518.77 |
| EWP Premier 4HR ONSITE XSW-DCV2-SR-L-A-D | 98008-XSW-DCV2-SR-L-A-D | \$ 1,914.00 | 10% | \$1,735.52 |
| EWP Premier 4HR OS XSW-DCV2-SR-L-A-D-3YR | 98008-XSW-DCV2-SR-L-A-D-3YR | \$ 5,741.00 | 10% | \$5,205.65 |
| EWP Premier 4HR OS XSW-DCV2-SR-L-A-D-5YR | 98008-XSW-DCV2-SR-L-A-D-5YR | \$ 9,568.00 | 10% | \$8,675.78 |
| EWP Premier 4HR ONSITE ZR-XFP | 98008-ZR-XFP | \$ 2,778.00 | 6% | \$2,630.90 |
| EWP Premier NBD ONSITE 10200 | 98011-10200 | \$ 2,673.00 | 6% | \$2,531.46 |
| EWP Premier NBD ONSITE 10320 | 98011-10320 | \$ 2,944.00 | 6% | \$2,788.12 |
| EWP Premier NBD ONSITE 10330 | 98011-10330 | \$ 7,064.00 | 6% | \$6,689.96 |
| EWP Premier NBD ONSITE 10331 | 98011-10331 | \$ 3,258.00 | 6% | \$3,085.49 |
| EWP Premier NBD ONSITE 10335 | 98011-10335 | \$ 5,077.00 | 6% | \$4,808.17 |
| EWP Premier NBD ONSITE 10403 | 98011-10403 | \$ 6,485.00 | 6% | \$6,141.62 |
| EWP Premier NBD ONSITE 10404 | 98011-10404 | \$ 3,185.00 | 6% | \$3,016.35 |
| EWP Premier NBD ONSITE 10441 | 98011-10441 | \$ 2,143.00 | 6% | \$2,029.53 |
| EWP Premier NBD ONSITE 10442 | 98011-10442 | \$ 2,271.00 | 6% | \$2,150.75 |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE 1130C | 98011-1130C | \$ 1,367.00 | 6% | <i>\$1,294.62</i> |
| EWP Premier NBD ONSITE 16119 | 98011-16119 | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWP Premier NBD ONSITE 16120 | 98011-16120 | \$ 482.00 | 6% | <i>\$456.48</i> |
| EWP Premier NBD ONSITE 16126 | 98011-16126 | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWP Premier NBD ONSITE 16127 | 98011-16127 | \$ 398.00 | 6% | <i>\$376.93</i> |
| EWP Premier NBD ONSITE 16172 | 98011-16172 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWP Premier NBD ONSITE 16172T | 98011-16172T | \$ 465.00 | 6% | <i>\$440.38</i> |
| EWP Premier NBD ONSITE 16173 | 98011-16173 | \$ 399.00 | 6% | <i>\$377.87</i> |
| EWP Premier NBD ONSITE 16173T | 98011-16173T | \$ 473.00 | 6% | <i>\$447.95</i> |
| EWP Premier NBD ONSITE 16174 | 98011-16174 | \$ 629.00 | 6% | <i>\$595.69</i> |
| EWP Premier NBD ONSITE 16175 | 98011-16175 | \$ 650.00 | 6% | <i>\$615.58</i> |
| EWP Premier NBD ONSITE 16176 | 98011-16176 | \$ 579.00 | 6% | <i>\$548.34</i> |
| EWP Premier NBD ONSITE 16177 | 98011-16177 | \$ 558.00 | 6% | <i>\$528.45</i> |
| EWP Premier NBD ONSITE 16177T | 98011-16177T | \$ 717.00 | 6% | <i>\$679.03</i> |
| EWP Premier NBD ONSITE 16178 | 98011-16178 | \$ 828.00 | 6% | <i>\$784.16</i> |
| EWP Premier NBD ONSITE 16179 | 98011-16179 | \$ 849.00 | 6% | <i>\$804.05</i> |
| EWP Premier NBD ONSITE 16179T | 98011-16179T | \$ 1,013.00 | 6% | <i>\$959.36</i> |
| EWP Premier NBD ONSITE 16301T | 98011-16301T | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier NBD ONSITE 16303T | 98011-16303T | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWP Premier NBD ONSITE 16304T | 98011-16304T | \$ 3,010.00 | 6% | <i>\$2,850.62</i> |
| EWP Premier NBD ONSITE 16401T | 98011-16401T | \$ 1,043.00 | 6% | <i>\$987.77</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE 16402T | 98011-16402T | \$ 1,585.00 | 6% | <i>\$1,501.07</i> |
| EWP Premier NBD ONSITE 16403T | 98011-16403T | \$ 1,403.00 | 6% | <i>\$1,328.71</i> |
| EWP Premier NBD ONSITE 16404T | 98011-16404T | \$ 1,403.00 | 6% | <i>\$1,328.71</i> |
| EWP Premier NBD ONSITE 16405T | 98011-16405T | \$ 1,858.00 | 6% | <i>\$1,759.62</i> |
| EWP Premier NBD ONSITE 16406T | 98011-16406T | \$ 2,466.00 | 6% | <i>\$2,335.43</i> |
| EWP Premier NBD ONSITE 16431 | 98011-16431 | \$ 1,597.00 | 6% | <i>\$1,512.44</i> |
| EWP Premier NBD ONSITE 16432 | 98011-16432 | \$ 1,689.00 | 6% | <i>\$1,599.57</i> |
| EWP Premier NBD ONSITE 16440 | 98011-16440 | \$ 996.00 | 6% | <i>\$943.26</i> |
| EWP Premier NBD ONSITE 16441 | 98011-16441 | \$ 898.00 | 6% | <i>\$850.45</i> |
| EWP Premier NBD ONSITE 16442 | 98011-16442 | \$ 398.00 | 6% | <i>\$376.93</i> |
| EWP Premier NBD ONSITE 16444 | 98011-16444 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier NBD ONSITE 16501 | 98011-16501 | \$ 213.00 | 6% | <i>\$201.72</i> |
| EWP Premier NBD ONSITE 16501T | 98011-16501T | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD ONSITE 16502 | 98011-16502 | \$ 317.00 | 6% | <i>\$300.21</i> |
| EWP Premier NBD ONSITE 16502T | 98011-16502T | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier NBD ONSITE 16503 | 98011-16503 | \$ 251.00 | 6% | <i>\$237.71</i> |
| EWP Premier NBD ONSITE 16503T | 98011-16503T | \$ 330.00 | 6% | <i>\$312.53</i> |
| EWP Premier NBD ONSITE 16504 | 98011-16504 | \$ 418.00 | 6% | <i>\$395.87</i> |
| EWP Premier NBD ONSITE 16504T | 98011-16504T | \$ 507.00 | 6% | <i>\$480.15</i> |
| EWP Premier NBD ONSITE 16505 | 98011-16505 | \$ 462.00 | 6% | <i>\$437.54</i> |
| EWP Premier NBD ONSITE 16505T | 98011-16505T | \$ 573.00 | 6% | <i>\$542.66</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD ONSITE 16506 | 98011-16506 | \$ 721.00 | 6% | \$682.82 |
| EWP Premier NBD ONSITE 16506T | 98011-16506T | \$ 881.00 | 6% | \$834.35 |
| EWP Premier NBD ONSITE 16507 | 98011-16507 | \$ 648.00 | 6% | \$613.69 |
| EWP Premier NBD ONSITE 16507T | 98011-16507T | \$ 771.00 | 6% | \$730.18 |
| EWP Premier NBD ONSITE 16508 | 98011-16508 | \$ 815.00 | 6% | \$771.85 |
| EWP Premier NBD ONSITE 16508T | 98011-16508T | \$ 976.00 | 6% | \$924.32 |
| EWP Premier NBD ONSITE 16509 | 98011-16509 | \$ 815.00 | 6% | \$771.85 |
| EWP Premier NBD ONSITE 16509T | 98011-16509T | \$ 976.00 | 6% | \$924.32 |
| EWP Premier NBD ONSITE 16510 | 98011-16510 | \$ 976.00 | 6% | \$924.32 |
| EWP Premier NBD ONSITE 16510T | 98011-16510T | \$ 1,168.00 | 6% | \$1,106.15 |
| EWP Premier NBD ONSITE 16513 | 98011-16513 | \$ 625.00 | 6% | \$591.91 |
| EWP Premier NBD ONSITE 16514 | 98011-16514 | \$ 958.00 | 6% | \$907.27 |
| EWP Premier NBD ONSITE 16515 | 98011-16515 | \$ 168.00 | 6% | \$159.10 |
| EWP Premier NBD ONSITE 16516 | 98011-16516 | \$ 190.00 | 6% | \$179.94 |
| EWP Premier NBD ONSITE 16517 | 98011-16517 | \$ 359.00 | 6% | \$339.99 |
| EWP Premier NBD ONSITE 16518 | 98011-16518 | \$ 316.00 | 6% | \$299.27 |
| EWP Premier NBD ONSITE 16519 | 98011-16519 | \$ 330.00 | 6% | \$312.53 |
| EWP Premier NBD ONSITE 16520 | 98011-16520 | \$ 536.00 | 6% | \$507.62 |
| EWP Premier NBD ONSITE 16530 | 98011-16530 | \$ 201.00 | 6% | \$190.36 |
| EWP Premier NBD ONSITE 16531 | 98011-16531 | \$ 262.00 | 6% | \$248.13 |
| EWP Premier NBD ONSITE 16531T | 98011-16531T | \$ 300.00 | 6% | \$284.12 |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE 16532 | 98011-16532 | \$ 262.00 | 6% | <i>\$248.13</i> |
| EWP Premier NBD ONSITE 16532T | 98011-16532T | \$ 300.00 | 6% | <i>\$284.12</i> |
| EWP Premier NBD ONSITE 16533 | 98011-16533 | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier NBD ONSITE 16533T | 98011-16533T | \$ 430.00 | 6% | <i>\$407.23</i> |
| EWP Premier NBD ONSITE 16534 | 98011-16534 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWP Premier NBD ONSITE 16535 | 98011-16535 | \$ 601.00 | 6% | <i>\$569.18</i> |
| EWP Premier NBD ONSITE 16535A | 98011-16535A | \$ 601.00 | 6% | <i>\$569.18</i> |
| EWP Premier NBD ONSITE 16535T | 98011-16535T | \$ 683.00 | 6% | <i>\$646.84</i> |
| EWP Premier NBD ONSITE 16536 | 98011-16536 | \$ 281.00 | 6% | <i>\$266.12</i> |
| EWP Premier NBD ONSITE 16537 | 98011-16537 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWP Premier NBD ONSITE 16538 | 98011-16538 | \$ 447.00 | 6% | <i>\$423.33</i> |
| EWP Premier NBD ONSITE 16538T | 98011-16538T | \$ 569.00 | 6% | <i>\$538.87</i> |
| EWP Premier NBD ONSITE 16539 | 98011-16539 | \$ 587.00 | 6% | <i>\$555.92</i> |
| EWP Premier NBD ONSITE 16540 | 98011-16540 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWP Premier NBD ONSITE 16541 | 98011-16541 | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD ONSITE 16560 | 98011-16560 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE 16561 | 98011-16561 | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD ONSITE 16562 | 98011-16562 | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier NBD ONSITE 16563 | 98011-16563 | \$ 224.00 | 6% | <i>\$212.14</i> |
| EWP Premier NBD ONSITE 16564 | 98011-16564 | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier NBD ONSITE 16565 | 98011-16565 | \$ 413.00 | 6% | <i>\$391.13</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE 16566 | 98011-16566 | \$ 63.00 | 6% | <i>\$59.66</i> |
| EWP Premier NBD ONSITE 16567 | 98011-16567 | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD ONSITE 16568 | 98011-16568 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE 16569 | 98011-16569 | \$ 154.00 | 6% | <i>\$145.85</i> |
| EWP Premier NBD ONSITE 16570 | 98011-16570 | \$ 168.00 | 6% | <i>\$159.10</i> |
| EWP Premier NBD ONSITE 16571 | 98011-16571 | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier NBD ONSITE 16701 | 98011-16701 | \$ 580.00 | 6% | <i>\$549.29</i> |
| EWP Premier NBD ONSITE 16702 | 98011-16702 | \$ 863.00 | 6% | <i>\$817.30</i> |
| EWP Premier NBD ONSITE 16703 | 98011-16703 | \$ 677.00 | 6% | <i>\$641.15</i> |
| EWP Premier NBD ONSITE 16703T | 98011-16703T | \$ 814.00 | 6% | <i>\$770.90</i> |
| EWP Premier NBD ONSITE 16704 | 98011-16704 | \$ 996.00 | 6% | <i>\$943.26</i> |
| EWP Premier NBD ONSITE 16704T | 98011-16704T | \$ 1,196.00 | 6% | <i>\$1,132.67</i> |
| EWP Premier NBD ONSITE 16705 | 98011-16705 | \$ 863.00 | 6% | <i>\$817.30</i> |
| EWP Premier NBD ONSITE 16705T | 98011-16705T | \$ 1,037.00 | 6% | <i>\$982.09</i> |
| EWP Premier NBD ONSITE 16706 | 98011-16706 | \$ 1,308.00 | 6% | <i>\$1,238.74</i> |
| EWP Premier NBD ONSITE 16706T | 98011-16706T | \$ 1,586.00 | 6% | <i>\$1,502.02</i> |
| EWP Premier NBD ONSITE 16710 | 98011-16710 | \$ 266.00 | 6% | <i>\$251.92</i> |
| EWP Premier NBD ONSITE 16710T | 98011-16710T | \$ 319.00 | 6% | <i>\$302.11</i> |
| EWP Premier NBD ONSITE 16711 | 98011-16711 | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWP Premier NBD ONSITE 16711T | 98011-16711T | \$ 127.00 | 6% | <i>\$120.28</i> |
| EWP Premier NBD ONSITE 16712 | 98011-16712 | \$ 153.00 | 6% | <i>\$144.90</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE 16712T | 98011-16712T | \$ 176.00 | 6% | <i>\$166.68</i> |
| EWP Premier NBD ONSITE 16713 | 98011-16713 | \$ 74.00 | 6% | <i>\$70.08</i> |
| EWP Premier NBD ONSITE 16713T | 98011-16713T | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier NBD ONSITE 16715 | 98011-16715 | \$ 109.00 | 6% | <i>\$103.23</i> |
| EWP Premier NBD ONSITE 16715T | 98011-16715T | \$ 127.00 | 6% | <i>\$120.28</i> |
| EWP Premier NBD ONSITE 16716 | 98011-16716 | \$ 453.00 | 6% | <i>\$429.01</i> |
| EWP Premier NBD ONSITE 16716T | 98011-16716T | \$ 550.00 | 6% | <i>\$520.88</i> |
| EWP Premier NBD ONSITE 16717 | 98011-16717 | \$ 694.00 | 6% | <i>\$657.25</i> |
| EWP Premier NBD ONSITE 16718 | 98011-16718 | \$ 490.00 | 6% | <i>\$464.05</i> |
| EWP Premier NBD ONSITE 16718T | 98011-16718T | \$ 595.00 | 6% | <i>\$563.49</i> |
| EWP Premier NBD ONSITE 16719 | 98011-16719 | \$ 736.00 | 6% | <i>\$697.03</i> |
| EWP Premier NBD ONSITE 16719T | 98011-16719T | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier NBD ONSITE 16720 | 98011-16720 | \$ 1,138.00 | 6% | <i>\$1,077.74</i> |
| EWP Premier NBD ONSITE 16720T | 98011-16720T | \$ 1,322.00 | 6% | <i>\$1,252.00</i> |
| EWP Premier NBD ONSITE 16756 | 98011-16756 | \$ 834.00 | 6% | <i>\$789.84</i> |
| EWP Premier NBD ONSITE 16756T | 98011-16756T | \$ 986.00 | 6% | <i>\$933.79</i> |
| EWP Premier NBD ONSITE 16757 | 98011-16757 | \$ 787.00 | 6% | <i>\$745.33</i> |
| EWP Premier NBD ONSITE 16757T | 98011-16757T | \$ 923.00 | 6% | <i>\$874.13</i> |
| EWP Premier NBD ONSITE 16790 | 98011-16790 | \$ 1,771.00 | 6% | <i>\$1,677.23</i> |
| EWP Premier NBD ONSITE 16791 | 98011-16791 | \$ 2,286.00 | 6% | <i>\$2,164.96</i> |
| EWP Premier NBD ONSITE 16801 | 98011-16801 | \$ 223.00 | 6% | <i>\$211.19</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE 16802 | 98011-16802 | \$ 265.00 | 6% | <i>\$250.97</i> |
| EWP Premier NBD ONSITE 16803 | 98011-16803 | \$ 279.00 | 6% | <i>\$264.23</i> |
| EWP Premier NBD ONSITE 16804 | 98011-16804 | \$ 349.00 | 6% | <i>\$330.52</i> |
| EWP Premier NBD ONSITE 16805 | 98011-16805 | \$ 73.00 | 6% | <i>\$69.13</i> |
| EWP Premier NBD ONSITE 16806 | 98011-16806 | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE 17101 | 98011-17101 | \$ 3,352.00 | 6% | <i>\$3,174.51</i> |
| EWP Premier NBD ONSITE 17101T | 98011-17101T | \$ 4,205.00 | 6% | <i>\$3,982.35</i> |
| EWP Premier NBD ONSITE 17102 | 98011-17102 | \$ 3,352.00 | 6% | <i>\$3,174.51</i> |
| EWP Premier NBD ONSITE 17102T | 98011-17102T | \$ 4,205.00 | 6% | <i>\$3,982.35</i> |
| EWP Premier NBD ONSITE 17103 | 98011-17103 | \$ 2,336.00 | 6% | <i>\$2,212.31</i> |
| EWP Premier NBD ONSITE 17103C | 98011-17103C | \$ 2,267.00 | 6% | <i>\$2,146.96</i> |
| EWP Premier NBD ONSITE 17103T | 98011-17103T | \$ 2,928.00 | 6% | <i>\$2,772.96</i> |
| EWP Premier NBD ONSITE 17104 | 98011-17104 | \$ 2,336.00 | 6% | <i>\$2,212.31</i> |
| EWP Premier NBD ONSITE 17104T | 98011-17104T | \$ 2,928.00 | 6% | <i>\$2,772.96</i> |
| EWP Premier NBD ONSITE 17121 | 98011-17121 | \$ 674.00 | 6% | <i>\$638.31</i> |
| EWP Premier NBD ONSITE 17122 | 98011-17122 | \$ 413.00 | 6% | <i>\$391.13</i> |
| EWP Premier NBD ONSITE 17200 | 98011-17200 | \$ 5,270.00 | 6% | <i>\$4,990.95</i> |
| EWP Premier NBD ONSITE 17200T | 98011-17200T | \$ 6,024.00 | 6% | <i>\$5,705.03</i> |
| EWP Premier NBD ONSITE 17201 | 98011-17201 | \$ 5,270.00 | 6% | <i>\$4,990.95</i> |
| EWP Premier NBD ONSITE 17201T | 98011-17201T | \$ 6,024.00 | 6% | <i>\$5,705.03</i> |
| EWP Premier NBD ONSITE 17202 | 98011-17202 | \$ 5,270.00 | 6% | <i>\$4,990.95</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE 17202T | 98011-17202T | \$ 6,024.00 | 6% | <i>\$5,705.03</i> |
| EWP Premier NBD ONSITE 17203 | 98011-17203 | \$ 5,359.00 | 6% | <i>\$5,075.24</i> |
| EWP Premier NBD ONSITE 17203T | 98011-17203T | \$ 6,119.00 | 6% | <i>\$5,795.00</i> |
| EWP Premier NBD ONSITE 17204 | 98011-17204 | \$ 5,359.00 | 6% | <i>\$5,075.24</i> |
| EWP Premier NBD ONSITE 17204T | 98011-17204T | \$ 6,119.00 | 6% | <i>\$5,795.00</i> |
| EWP Premier NBD ONSITE 17205 | 98011-17205 | \$ 5,309.00 | 6% | <i>\$5,027.89</i> |
| EWP Premier NBD ONSITE 17205T | 98011-17205T | \$ 6,077.00 | 6% | <i>\$5,755.22</i> |
| EWP Premier NBD ONSITE 17206 | 98011-17206 | \$ 5,309.00 | 6% | <i>\$5,027.89</i> |
| EWP Premier NBD ONSITE 17206T | 98011-17206T | \$ 6,077.00 | 6% | <i>\$5,755.22</i> |
| EWP Premier NBD ONSITE 17300 | 98011-17300 | \$ 3,502.00 | 6% | <i>\$3,316.57</i> |
| EWP Premier NBD ONSITE 17310 | 98011-17310 | \$ 3,175.00 | 6% | <i>\$3,006.88</i> |
| EWP Premier NBD ONSITE 17310T | 98011-17310T | \$ 3,827.00 | 6% | <i>\$3,624.36</i> |
| EWP Premier NBD ONSITE 17350 | 98011-17350 | \$ 3,251.00 | 6% | <i>\$3,078.86</i> |
| EWP Premier NBD ONSITE 17360 | 98011-17360 | \$ 4,009.00 | 6% | <i>\$3,796.72</i> |
| EWP Premier NBD ONSITE 17401 | 98011-17401 | \$ 501.00 | 6% | <i>\$474.47</i> |
| EWP Premier NBD ONSITE 17401G | 98011-17401G | \$ 601.00 | 6% | <i>\$569.18</i> |
| EWP Premier NBD ONSITE 17401T | 98011-17401T | \$ 571.00 | 6% | <i>\$540.77</i> |
| EWP Premier NBD ONSITE 17402 | 98011-17402 | \$ 701.00 | 6% | <i>\$663.88</i> |
| EWP Premier NBD ONSITE 17402G | 98011-17402G | \$ 803.00 | 6% | <i>\$760.48</i> |
| EWP Premier NBD ONSITE 17402T | 98011-17402T | \$ 762.00 | 6% | <i>\$721.65</i> |
| EWP Premier NBD ONSITE 17403 | 98011-17403 | \$ 773.00 | 6% | <i>\$732.07</i> |

| | | | | |
|-------------------------------------|---------------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE 17404 | 98011-17404 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWP Premier NBD ONSITE 17405 | 98011-17405 | \$ 464.00 | 6% | <i>\$439.43</i> |
| EWP Premier NBD ONSITE 17700 | 98011-17700 | \$ 6,176.00 | 6% | <i>\$5,848.98</i> |
| EWP Premier NBD ONSITE 17701 | 98011-17701 | \$ 5,420.00 | 6% | <i>\$5,133.01</i> |
| EWP Premier NBD ONSITE 17702 | 98011-17702 | \$ 5,420.00 | 6% | <i>\$5,133.01</i> |
| EWP Premier NBD ONSITE 17703 | 98011-17703 | \$ 5,937.00 | 6% | <i>\$5,622.64</i> |
| EWP Premier NBD ONSITE 17704 | 98011-17704 | \$ 5,937.00 | 6% | <i>\$5,622.64</i> |
| EWP Premier NBD ONSITE 17705 | 98011-17705 | \$ 5,456.00 | 6% | <i>\$5,167.10</i> |
| EWP Premier NBD ONSITE 17706 | 98011-17706 | \$ 5,456.00 | 6% | <i>\$5,167.10</i> |
| EWP Premier NBD ONSITE 17800 | 98011-17800 | \$ 6,312.00 | 6% | <i>\$5,977.78</i> |
| EWP Premier NBD ONSITE 17810 | 98011-17810 | \$ 5,049.00 | 6% | <i>\$4,781.66</i> |
| EWP Premier NBD ONSITE 18101 | 98011-18101 | \$ 327.00 | 6% | <i>\$309.69</i> |
| EWP Premier NBD ONSITE 18102 | 98011-18102 | \$ 421.00 | 6% | <i>\$398.71</i> |
| EWP Premier NBD ONSITE 18103 | 98011-18103 | \$ 462.00 | 6% | <i>\$437.54</i> |
| EWP Premier NBD ONSITE 18104 | 98011-18104 | \$ 657.00 | 6% | <i>\$622.21</i> |
| EWP Premier NBD ONSITE 18104-6PK | 98011-18104- 6PK | \$ 3,825.00 | 6% | <i>\$3,622.47</i> |
| EWP Premier NBD ONSITE 18202 | 98011-18202 | \$ 250.00 | 6% | <i>\$236.76</i> |
| EWP Premier NBD ONSITE 30135 | 98011-30135 | \$ 809.00 | 6% | <i>\$766.16</i> |
| EWP Premier NBD ONSITE 30136 | 98011-30136 | \$ 6,234.00 | 6% | <i>\$5,903.91</i> |
| EWP Premier NBD ONSITE 30137 | 98011-30137 | \$ 1,305.00 | 6% | <i>\$1,235.90</i> |
| EWP Premier NBD ONSITE 30138 | 98011-30138 | \$ 6,002.00 | 6% | <i>\$5,684.19</i> |

| | | | | |
|---------------------------------|-------------|--------------|----|-------------------|
| EWP Premier NBD ONSITE 30139 | 98011-30139 | \$ 10,554.00 | 6% | <i>\$9,995.17</i> |
| EWP Premier NBD ONSITE 30912 | 98011-30912 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE 30913 | 98011-30913 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE 31012 | 98011-31012 | \$ 132.00 | 6% | <i>\$125.01</i> |
| EWP Premier NBD ONSITE 31013 | 98011-31013 | \$ 132.00 | 6% | <i>\$125.01</i> |
| EWP Premier NBD ONSITE 31014 | 98011-31014 | \$ 132.00 | 6% | <i>\$125.01</i> |
| EWP Premier NBD ONSITE 31015 | 98011-31015 | \$ 132.00 | 6% | <i>\$125.01</i> |
| EWP Premier NBD ONSITE 31016 | 98011-31016 | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWP Premier NBD ONSITE 31017 | 98011-31017 | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWP Premier NBD ONSITE 31018 | 98011-31018 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWP Premier NBD ONSITE 31019 | 98011-31019 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWP Premier NBD ONSITE 31025 | 98011-31025 | \$ 71.00 | 6% | <i>\$67.24</i> |
| EWP Premier NBD ONSITE 31026 | 98011-31026 | \$ 71.00 | 6% | <i>\$67.24</i> |
| EWP Premier NBD ONSITE 31028 | 98011-31028 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD ONSITE 31029 | 98011-31029 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE 31031 | 98011-31031 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE 31032 | 98011-31032 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE 31034 | 98011-31034 | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier NBD ONSITE 31035 | 98011-31035 | \$ 130.00 | 6% | <i>\$123.12</i> |
| EWP Premier NBD ONSITE 31050 | 98011-31050 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 31051 | 98011-31051 | \$ 152.00 | 6% | <i>\$143.95</i> |

| | | | | |
|---------------------------------|-------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE 31055 | 98011-31055 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 31056 | 98011-31056 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37101 | 98011-37101 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier NBD ONSITE 37102 | 98011-37102 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier NBD ONSITE 37103 | 98011-37103 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier NBD ONSITE 37111 | 98011-37111 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD ONSITE 37112 | 98011-37112 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD ONSITE 37113 | 98011-37113 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE 37114 | 98011-37114 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE 37115 | 98011-37115 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD ONSITE 37116 | 98011-37116 | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE 37117 | 98011-37117 | \$ 78.00 | 6% | <i>\$73.87</i> |
| EWP Premier NBD ONSITE 37121 | 98011-37121 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37122 | 98011-37122 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37123 | 98011-37123 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37124 | 98011-37124 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37125 | 98011-37125 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37126 | 98011-37126 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37129 | 98011-37129 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 37130 | 98011-37130 | \$ 152.00 | 6% | <i>\$143.95</i> |
| EWP Premier NBD ONSITE 39031 | 98011-39031 | \$ 198.00 | 6% | <i>\$187.52</i> |

| | | | | |
|---|---------------------------|-------------|-----|-------------------|
| EWP Premier NBD ONSITE 39032 | 98011-39032 | \$ 212.00 | 6% | <i>\$200.77</i> |
| EWP Premier NBD ONSITE 39033 | 98011-39033 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier NBD ONSITE 39034 | 98011-39034 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier NBD ONSITE 39035 | 98011-39035 | \$ 943.00 | 6% | <i>\$893.07</i> |
| EWP Premier NBD ONSITE 39036 | 98011-39036 | \$ 142.00 | 6% | <i>\$134.48</i> |
| EWP Premier NBD ONSITE 39037 | 98011-39037 | \$ 142.00 | 6% | <i>\$134.48</i> |
| EWP Premier NBD ONSITE 39038 | 98011-39038 | \$ 242.00 | 6% | <i>\$229.19</i> |
| EWP Premier NBD ONSITE 39039 | 98011-39039 | \$ 242.00 | 6% | <i>\$229.19</i> |
| EWP Premier NBD ONSITE 39505 | 98011-39505 | \$ 72.00 | 6% | <i>\$68.19</i> |
| EWP Premier NBD ONSITE 4120-24MW-4Y | 98011-4120- 24MW-4Y | \$ 825.00 | 6% | <i>\$781.32</i> |
| EWP Premier NBD ONSITE 4120-48MW-4Y | 98011-4120- 48MW-4Y | \$ 1,100.00 | 6% | <i>\$1,041.76</i> |
| EWP Premier NBD ONSITE 4120C | 98011-4120C | \$ 7,122.00 | 10% | <i>\$6,457.87</i> |
| EWP Premier NBD ONSITE 4120C-1 | 98011-4120C-1 | \$ 7,850.00 | 6% | <i>\$7,434.34</i> |
| EWP Premier NBD ONSITE 41216 | 98011-41216 | \$ 2,123.00 | 6% | <i>\$2,010.59</i> |
| EWP Premier NBD ONSITE 4220-12P-4X | 98011-4220- 12P-4X | \$ 251.00 | 6% | <i>\$237.71</i> |
| EWP Premier NBD ONSITE 4220-12T-4X | 98011-4220- 12T-4X | \$ 184.00 | 6% | <i>\$174.26</i> |
| EWP Premier NBD ONSITE 4220-24P-4X | 98011-4220- 24P-4X | \$ 334.00 | 6% | <i>\$316.31</i> |
| EWP Premier NBD ONSITE 4220-24T-4X | 98011-4220- 24T-4X | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier NBD ONSITE 4220-48P-4X | 98011-4220- 48P-4X | \$ 502.00 | 6% | <i>\$475.42</i> |
| EWP Premier NBD ONSITE 4220-48T-4X | 98011-4220- 48T-4X | \$ 376.00 | 6% | <i>\$356.09</i> |
| EWP Premier NBD ONSITE 4220-4MW-20P-4X | 98011-4220- 4MW-20P-4X | \$ 460.00 | 6% | <i>\$435.64</i> |

| | | | | |
|--|-----------------------------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE 4220-4MW-8P-4X | 98011-4220- 4MW-8P-4X | \$ 326.00 | 6% | <i>\$308.74</i> |
| EWP Premier NBD ONSITE 4220-8MW-40P-4X | 98011-4220- 8MW-40P-4X | \$ 669.00 | 6% | <i>\$633.58</i> |
| EWP Premier NBD ONSITE 4220-8X | 98011-4220-8X | \$ 351.00 | 6% | <i>\$332.41</i> |
| EWP Premier NBD ONSITE 48001 | 98011-48001 | \$ 8,819.00 | 6% | <i>\$8,352.03</i> |
| EWP Premier NBD ONSITE 48038 | 98011-48038 | \$ 3,531.00 | 6% | <i>\$3,344.03</i> |
| EWP Premier NBD ONSITE 48039 | 98011-48039 | \$ 3,531.00 | 6% | <i>\$3,344.03</i> |
| EWP Premier NBD ONSITE 48040 | 98011-48040 | \$ 3,369.00 | 6% | <i>\$3,190.61</i> |
| EWP Premier NBD ONSITE 48041 | 98011-48041 | \$ 3,531.00 | 6% | <i>\$3,344.03</i> |
| EWP Premier NBD ONSITE 48046 | 98011-48046 | \$ 4,638.00 | 6% | <i>\$4,392.42</i> |
| EWP Premier NBD ONSITE 48047 | 98011-48047 | \$ 12,356.00 | 6% | <i>\$11,701.75</i> |
| EWP Premier NBD ONSITE 48051 | 98011-48051 | \$ 8,496.00 | 6% | <i>\$8,046.14</i> |
| EWP Premier NBD ONSITE 48061 | 98011-48061 | \$ 9,933.00 | 6% | <i>\$9,407.05</i> |
| EWP Premier NBD ONSITE 48062 | 98011-48062 | \$ 15,885.00 | 6% | <i>\$15,043.89</i> |
| EWP Premier NBD ONSITE 5320-16P-4XE | 98011-5320- 16P-4XE | \$ 350.00 | 6% | <i>\$331.47</i> |
| EWP Premier NBD ONSITE 5320-16P-4XE-DC | 98011-5320- 16P-4XE-DC | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWP Premier NBD ONSITE 5320-24P-8XE | 98011-5320- 24P-8XE | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWP Premier NBD Onsi 5320- 24T-24S-4XE-XT | 98011-5320- 24T-24S-4XE- XT | \$ 438.00 | 6% | <i>\$414.81</i> |
| EWP Premier NBD Onsite 5320- 24T-4X-XT | 98011-5320- 24T-4X-XT | \$ 236.00 | 6% | <i>\$223.50</i> |
| EWP Premier NBD ONSITE 5320-24T-8XE | 98011-5320- 24T-8XE | \$ 272.00 | 6% | <i>\$257.60</i> |
| EWP Premier NBD ONSITE 5320-48P-8XE | 98011-5320- 48P-8XE | \$ 632.00 | 6% | <i>\$598.54</i> |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EWP Premier NBD ONSITE 5320-48T-8XE | 98011-5320- 48T-8XE | \$ 445.00 | 6% | <i>\$421.44</i> |
| EWP Prem NBD ONSITE 5420F- 16MW-32P-4XE | 98011-5420F- 16MW-32P- 4XE | \$ 1,167.00 | 6% | <i>\$1,105.21</i> |
| EWP Premier NBD ONSITE 5420F-16W-32P-4XE | 98011-5420F- 16W-32P-4XE | \$ 1,054.00 | 6% | <i>\$998.19</i> |
| EWP Premier NBD ONSITE 5420F-24P-4XE | 98011-5420F- 24P-4XE | \$ 483.00 | 6% | <i>\$457.43</i> |
| EWP Premier NBD ONSITE 5420F-24S-4XE | 98011-5420F- 24S-4XE | \$ 554.00 | 6% | <i>\$524.67</i> |
| EWP Premier NBD ONSITE 5420F-24T-4XE | 98011-5420F- 24T-4XE | \$ 399.00 | 6% | <i>\$377.87</i> |
| EWP Premier NBD ONSITE 5420F-48P-4XE | 98011-5420F- 48P-4XE | \$ 753.00 | 6% | <i>\$713.13</i> |
| EWP Premier NBD ONSITE 5420F-48P-4XL | 98011-5420F- 48P-4XL | \$ 892.00 | 6% | <i>\$844.77</i> |
| EWP Premier NBD ONSITE 5420F-48T-4XE | 98011-5420F- 48T-4XE | \$ 550.00 | 6% | <i>\$520.88</i> |
| EWP Premier NBD ONSITE 5420F-8W-16P-4XE | 98011-5420F- 8W-16P-4XE | \$ 593.00 | 6% | <i>\$561.60</i> |
| EWP Prem NBD ONSITE 5420M-16MW-32P-4YE | 98011-5420M- 16MW-32P- 4YE | \$ 1,228.00 | 6% | <i>\$1,162.98</i> |
| EWP Premier NBD ONSITE 5420M-24T-4YE | 98011-5420M- 24T-4YE | \$ 586.00 | 6% | <i>\$554.97</i> |
| EWP Premier NBD ONSITE 5420M-24W-4YE | 98011-5420M- 24W-4YE | \$ 535.00 | 6% | <i>\$506.67</i> |
| EWP Premier NBD ONSITE 5420M-48T-4YE | 98011-5420M- 48T-4YE | \$ 800.00 | 6% | <i>\$757.64</i> |
| EWP Premier NBD ONSITE 5420M-48W-4YE | 98011-5420M- 48W-4YE | \$ 915.00 | 6% | <i>\$866.55</i> |
| EWP PREMIER NBD ONSITE 5520-12MW-36W | 98011-5520- 12MW-36W | \$ 1,306.00 | 6% | <i>\$1,236.85</i> |
| EWP PREMIER NBD ONSITE 5520-24T | 98011-5520- 24T | \$ 498.00 | 6% | <i>\$471.63</i> |
| EWP PREMIER NBD ONSIT 5520-24T-ACDC-BASE | 98011-5520- 24T-ACDC- BASE | \$ 498.00 | 6% | <i>\$471.63</i> |
| EWP PREMIER NBD ONSITE 5520-24T-BASE | 98011-5520- 24T-BASE | \$ 498.00 | 10% | <i>\$451.56</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EWP PREMIER NBD ONSITE 5520-24W | 98011-5520- 24W | \$ 759.00 | 6% | <i>\$718.81</i> |
| EWP PREMIER NBD ONSITE 5520-24X | 98011-5520- 24X | \$ 1,430.00 | 6% | <i>\$1,354.28</i> |
| EWP PREMIER NBD ONSIT 5520-24X-ACDC-BASE | 98011-5520- 24X-ACDC- BASE | \$ 1,430.00 | 6% | <i>\$1,354.28</i> |
| EWP PREMIER NBD ONSITE 5520-24X-BASE | 98011-5520- 24X-BASE | \$ 1,430.00 | 10% | <i>\$1,296.65</i> |
| EWP PREMIER NBD ONSITE 5520-48SE | 98011-5520- 48SE | \$ 1,474.00 | 6% | <i>\$1,395.95</i> |
| EWP PREMIER NBD ONSI 5520-48SE-ACDC-BASE | 98011-5520- 48SE-ACDC- BASE | \$ 1,474.00 | 6% | <i>\$1,395.95</i> |
| EWP PREMIER NBD ONSITE 5520-48SE-BASE | 98011-5520- 48SE-BASE | \$ 1,474.00 | 10% | <i>\$1,336.55</i> |
| EWP PREMIER NBD ONSITE 5520-48T | 98011-5520- 48T | \$ 875.00 | 6% | <i>\$828.67</i> |
| EWP PREMIER NBD ONSIT 5520-48T-ACDC-BASE | 98011-5520- 48T-ACDC- BASE | \$ 875.00 | 6% | <i>\$828.67</i> |
| EWP PREMIER NBD ONSITE 5520-48T-BASE | 98011-5520- 48T-BASE | \$ 875.00 | 10% | <i>\$793.41</i> |
| EWP PREMIER NBD ONSITE 5520-48W | 98011-5520- 48W | \$ 1,039.00 | 6% | <i>\$983.98</i> |
| EWP Premier NBD ONSITE 5720-24MW | 98011-5720- 24MW | \$ 1,588.00 | 6% | <i>\$1,503.92</i> |
| EWP Premier NBD ONSITE 5720-24MXW | 98011-5720- 24MXW | \$ 2,147.00 | 6% | <i>\$2,033.32</i> |
| EWP Premier NBD ONSITE 5720-48MW | 98011-5720- 48MW | \$ 1,867.00 | 6% | <i>\$1,768.14</i> |
| EWP Premier NBD ONSITE 5720-48MXW | 98011-5720- 48MXW | \$ 2,707.00 | 6% | <i>\$2,563.66</i> |
| EWP Premier NBD ONSITE 7520-48XT-6C | 98011-7520- 48XT-6C | \$ 2,931.00 | 6% | <i>\$2,775.80</i> |
| EWP Premier NBD ONSITE 7520-48XT-6C-AC-F | 98011-7520- 48XT-6C-AC- F | \$ 2,931.00 | 6% | <i>\$2,775.80</i> |
| EWP Premier NBD ONSITE 7520-48XT-6C-AC-R | 98011-7520- 48XT-6C-AC- R | \$ 2,931.00 | 6% | <i>\$2,775.80</i> |
| EWP Premier NBD ONSITE 7520-48Y-8C | 98011-7520- 48Y-8C | \$ 2,727.00 | 6% | <i>\$2,582.61</i> |

| | | | | |
|---|----------------------------------|-------------|----|------------|
| EWP Premier NBD ONSITE 7520-48Y-8C-AC-F | 98011-7520- 48Y-8C-AC-F | \$ 2,727.00 | 6% | \$2,582.61 |
| EWP Premier NBD ONSITE 7520-48Y-8C-AC-R | 98011-7520- 48Y-8C-AC-R | \$ 2,727.00 | 6% | \$2,582.61 |
| EWP PREMIER NBD ONSITE 7520-48YE-8CE | 98011-7520- 48YE-8CE | \$ 3,181.00 | 6% | \$3,012.57 |
| EWP PREMIER NBD ONSIT 7520-48YE-8CE-AC-F | 98011-7520- 48YE-8CE-AC- F | \$ 3,181.00 | 6% | \$3,012.57 |
| EWP PREMIER NBD ONSIT 7520-48YE-8CE-AC-R | 98011-7520- 48YE-8CE-AC- R | \$ 3,181.00 | 6% | \$3,012.57 |
| EWP Premier NBD ONSITE 7720-32C | 98011-7720- 32C | \$ 3,409.00 | 6% | \$3,228.49 |
| EWP Premier NBD ONSITE 7720-32C-AC-F | 98011-7720- 32C-AC-F | \$ 3,409.00 | 6% | \$3,228.49 |
| EWP Premier NBD ONSITE 7720-32C-AC-R | 98011-7720- 32C-AC-R | \$ 3,409.00 | 6% | \$3,228.49 |
| EWP Premier NBD ONSITE 8520-48XT-6C | 98011-8520- 48XT-6C | \$ 3,403.00 | 6% | \$3,222.81 |
| EWP Premier NBD ONSITE 8520-48XT-6C-AC-F | 98011-8520- 48XT-6C-AC- F | \$ 3,403.00 | 6% | \$3,222.81 |
| EWP Premier NBD ONSITE 8520-48XT-6C-AC-R | 98011-8520- 48XT-6C-AC- R | \$ 3,403.00 | 6% | \$3,222.81 |
| EWP Premier NBD ONSITE 8520-48XT-6C-DC-F | 98011-8520- 48XT-6C-DC- F | \$ 3,403.00 | 6% | \$3,222.81 |
| EWP Premier NBD ONSITE 8520-48XT-6C-DC-R | 98011-8520- 48XT-6C-DC- R | \$ 3,403.00 | 6% | \$3,222.81 |
| EWP Premier NBD ONSITE 8520-48Y-8C | 98011-8520- 48Y-8C | \$ 3,493.00 | 6% | \$3,308.05 |
| EWP Premier NBD ONSITE 8520-48Y-8C-AC-F | 98011-8520- 48Y-8C-AC-F | \$ 3,493.00 | 6% | \$3,308.05 |
| EWP Premier NBD ONSITE 8520-48Y-8C-AC-R | 98011-8520- 48Y-8C-AC-R | \$ 3,493.00 | 6% | \$3,308.05 |
| EWP Premier NBD ONSITE 8520-48Y-8C-DC-F | 98011-8520- 48Y-8C-DC-F | \$ 3,493.00 | 6% | \$3,308.05 |
| EWP Premier NBD ONSITE 8520-48Y-8C-DC-R | 98011-8520- 48Y-8C-DC-R | \$ 3,493.00 | 6% | \$3,308.05 |

| | | | | |
|---|-------------------------|--------------|-----|--------------------|
| EWP Premier NBD ONSITE 86100 | 98011-86100 | \$ 6,763.00 | 6% | <i>\$6,404.90</i> |
| EWP Premier NBD ONSITE 86101 | 98011-86101 | \$ 9,290.00 | 6% | <i>\$8,798.09</i> |
| EWP Premier NBD ONSITE 87100 | 98011-87100 | \$ 4,195.00 | 6% | <i>\$3,972.87</i> |
| EWP Premier NBD ONSITE 87101 | 98011-87101 | \$ 6,452.00 | 6% | <i>\$6,110.37</i> |
| EWP Premier NBD ONSITE 8720-32C | 98011-8720- 32C | \$ 3,882.00 | 6% | <i>\$3,676.45</i> |
| EWP Premier NBD ONSITE 8720-32C-AC-F | 98011-8720- 32C-AC-F | \$ 3,883.00 | 6% | <i>\$3,677.40</i> |
| EWP Premier NBD ONSITE 8720-32C-AC-R | 98011-8720- 32C-AC-R | \$ 3,883.00 | 6% | <i>\$3,677.40</i> |
| EWP Premier NBD ONSITE 8720-32C-DC-F | 98011-8720- 32C-DC-F | \$ 3,883.00 | 6% | <i>\$3,677.40</i> |
| EWP Premier NBD ONSITE 8720-32C-DC-R | 98011-8720- 32C-DC-R | \$ 3,883.00 | 6% | <i>\$3,677.40</i> |
| EWP Premier NBD ONSITE 8806 | 98011-8806 | \$ 2,208.00 | 6% | <i>\$2,091.09</i> |
| EWP Premier NBD ONSITE 8810 | 98011-8810 | \$ 5,737.00 | 6% | <i>\$5,433.23</i> |
| EWP Premier NBD ONSITE 88100 | 98011-88100 | \$ 7,630.00 | 6% | <i>\$7,225.99</i> |
| EWP Premier NBD ONSITE 8820-40C | 98011-8820- 40C | \$ 16,012.00 | 10% | <i>\$14,518.88</i> |
| EWP Premier NBD ONSITE 8820-40C-AC-F | 98011-8820- 40C-AC-F | \$ 16,012.00 | 10% | <i>\$14,518.88</i> |
| EWP Premier NBD ONSITE 8820-40C-AC-R | 98011-8820- 40C-AC-R | \$ 16,012.00 | 10% | <i>\$14,518.88</i> |
| EWP Premier NBD ONSITE 8820-40C-DC-F | 98011-8820- 40C-DC-F | \$ 16,012.00 | 10% | <i>\$14,518.88</i> |
| EWP Premier NBD ONSITE 8820-40C-DC-R | 98011-8820- 40C-DC-R | \$ 16,012.00 | 10% | <i>\$14,518.88</i> |
| EWP Premier NBD ONSITE 8820-80C | 98011-8820- 80C | \$ 29,028.00 | 10% | <i>\$26,321.14</i> |
| EWP Premier NBD ONSITE 8820-80C-AC-F | 98011-8820- 80C-AC-F | \$ 29,028.00 | 10% | <i>\$26,321.14</i> |
| EWP Premier NBD ONSITE 8820-80C-AC-R | 98011-8820- 80C-AC-R | \$ 29,028.00 | 10% | <i>\$26,321.14</i> |
| EWP Premier NBD ONSITE 8820-80C-DC-F | 98011-8820- 80C-DC-F | \$ 29,028.00 | 10% | <i>\$26,321.14</i> |

| | | | | |
|--|-----------------------------|--------------|-----|--------------------|
| EWP Premier NBD ONSITE 8820-80C-DC-R | 98011-8820- 80C-DC-R | \$ 29,028.00 | 10% | <i>\$26,321.14</i> |
| EWP Premier NBD ONSITE 9920-16C | 98011-9920- 16C | \$ 12,232.00 | 6% | <i>\$11,584.32</i> |
| EWP Premier NBD ONSITE 9920-4D | 98011-9920-4D | \$ 12,232.00 | 6% | <i>\$11,584.32</i> |
| EWP Premier NBD ONSITE 9920-NPB-8 | 98011-9920- NPB-8 | \$ 20,837.00 | 6% | <i>\$19,733.68</i> |
| EWP Premier NBD ONSITE A10148 | 98011-A10148 | \$ 3,693.00 | 6% | <i>\$3,497.46</i> |
| EWP Premier NBD ONSITE A10149 | 98011-A10149 | \$ 7,026.00 | 6% | <i>\$6,653.97</i> |
| EWP Premier NBD ONSITE A10152 | 98011-A10152 | \$ 7,026.00 | 6% | <i>\$6,653.97</i> |
| EWP Premier NBD ONSITE A10154 | 98011-A10154 | \$ 21,026.00 | 6% | <i>\$19,912.67</i> |
| EWP Premier NBD ONSITE A10155 | 98011-A10155 | \$ 7,586.00 | 6% | <i>\$7,184.32</i> |
| EWP Premier NBD ONSITE A10157 | 98011-A10157 | \$ 13,131.00 | 6% | <i>\$12,435.71</i> |
| EWP Premier NBD ONSITE A10175 | 98011-A10175 | \$ 8,106.00 | 6% | <i>\$7,676.79</i> |
| EWP Premier NBD ONSITE A10176 | 98011-A10176 | \$ 12,161.00 | 6% | <i>\$11,517.08</i> |
| EWP Premier NBD ONSITE AH- AP-1130-AC-CE | 98011-AH-AP- 1130-AC-CE | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier NBD ONSITE AH- AP-1130-AC-FCC | 98011-AH-AP- 1130-AC-FCC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier NBD ONSITE AH- AP-1130-AC-W | 98011-AH-AP- 1130-AC-W | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier NBD ONSITE AH- AP-122-AC-CAN | 98011-AH-AP- 122-AC-CAN | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH- AP-122-AC-CE | 98011-AH-AP- 122-AC-CE | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH- AP-122-AC-FCC | 98011-AH-AP- 122-AC-FCC | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH- AP-122-AC-W | 98011-AH-AP- 122-AC-W | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH- AP-130-AC-CE | 98011-AH-AP- 130-AC-CE | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH- AP-130-AC-FCC | 98011-AH-AP- 130-AC-FCC | \$ 91.00 | 6% | <i>\$86.18</i> |

| | | | | |
|--|-------------------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE AH-AP-130-AC-W | 98011-AH-AP-130-AC-W | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-150W-AC-CAN | 98011-AH-AP-150W-AC-CAN | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-150W-AC-CE | 98011-AH-AP-150W-AC-CE | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-150W-AC-FCC | 98011-AH-AP-150W-AC-FCC | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-150W-AC-W | 98011-AH-AP-150W-AC-W | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-230-AC-CE | 98011-AH-AP-230-AC-CE | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-230-AC-FCC | 98011-AH-AP-230-AC-FCC | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-230-AC-W | 98011-AH-AP-230-AC-W | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-250-AC-CAN | 98011-AH-AP-250-AC-CAN | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-250-AC-CE | 98011-AH-AP-250-AC-CE | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-250-AC-FCC | 98011-AH-AP-250-AC-FCC | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-250-AC-W | 98011-AH-AP-250-AC-W | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-AP-630-AX-CAN | 98011-AH-AP-630-AX-CAN | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE AH-AP-630-AX-CE | 98011-AH-AP-630-AX-CE | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE AH-AP-630-AX-FCC | 98011-AH-AP-630-AX-FCC | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE AH-AP-630-AX-W | 98011-AH-AP-630-AX-W | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE AH-AP-650-AX-CAN | 98011-AH-AP-650-AX-CAN | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier NBD ONSITE AH-AP-650-AX-CE | 98011-AH-AP-650-AX-CE | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier NBD ONSITE AH-AP-650-AX-FCC | 98011-AH-AP-650-AX-FCC | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier NBD ONSITE AH-AP-650-AX-W | 98011-AH-AP-650-AX-W | \$ 123.00 | 6% | <i>\$116.49</i> |

| | | | | |
|--|-------------------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE AH-AP-650X-AX-CAN | 98011-AH-AP-650X-AX-CAN | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier NBD ONSITE AH-AP-650X-AX-CE | 98011-AH-AP-650X-AX-CE | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier NBD ONSITE AH-AP-650X-AX-FCC | 98011-AH-AP-650X-AX-FCC | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier NBD ONSITE AH-AP-650X-AX-W | 98011-AH-AP-650X-AX-W | \$ 123.00 | 6% | <i>\$116.49</i> |
| EWP Premier NBD ONSITE AH-ATOM-CAN | 98011-AH-ATOM-CAN | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD ONSITE AH-ATOM-CE-EU | 98011-AH-ATOM-CE-EU | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AH-ATOM-CE-UK | 98011-AH-ATOM-CE-UK | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AH-ATOM-FCC | 98011-AH-ATOM-FCC | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD ONSITE AH-ATOM-W | 98011-AH-ATOM-W | \$ 90.00 | 6% | <i>\$85.23</i> |
| EWP Premier NBD ONSITE AH-ATOM-W-EU | 98011-AH-ATOM-W-EU | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AH-ATOM-W-UK | 98011-AH-ATOM-W-UK | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AH-SR-2208P-AU | 98011-AH-SR-2208P-AU | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-SR-2208P-EU | 98011-AH-SR-2208P-EU | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-SR-2208P-NA | 98011-AH-SR-2208P-NA | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-SR-2208P-UK | 98011-AH-SR-2208P-UK | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-SR-2224P-AU | 98011-AH-SR-2224P-AU | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD ONSITE AH-SR-2224P-EU | 98011-AH-SR-2224P-EU | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD ONSITE AH-SR-2224P-NA | 98011-AH-SR-2224P-NA | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD ONSITE AH-SR-2224P-UK | 98011-AH-SR-2224P-UK | \$ 128.00 | 6% | <i>\$121.22</i> |

| | | | | |
|--|-------------------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE AH-SR-2324P-AU | 98011-AH-SR-2324P-AU | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier NBD ONSITE AH-SR-2324P-EU | 98011-AH-SR-2324P-EU | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier NBD ONSITE AH-SR-2324P-NA | 98011-AH-SR-2324P-NA | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier NBD ONSITE AH-SR-2324P-UK | 98011-AH-SR-2324P-UK | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier NBD ONSITE AH-SR-2348P-AU | 98011-AH-SR-2348P-AU | \$ 280.00 | 6% | <i>\$265.17</i> |
| EWP Premier NBD ONSITE AH-SR-2348P-EU | 98011-AH-SR-2348P-EU | \$ 280.00 | 6% | <i>\$265.17</i> |
| EWP Premier NBD ONSITE AH-SR-2348P-NA | 98011-AH-SR-2348P-NA | \$ 280.00 | 6% | <i>\$265.17</i> |
| EWP Premier NBD ONSITE AH-SR-2348P-UK | 98011-AH-SR-2348P-UK | \$ 280.00 | 6% | <i>\$265.17</i> |
| EWP Premier NBD ONSITE AH-XR200P-AU | 98011-AH-XR200P-AU | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-XR200P-EU | 98011-AH-XR200P-EU | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-XR200P-UK | 98011-AH-XR200P-UK | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-XR200P-US | 98011-AH-XR200P-US | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE AH-XR600P | 98011-AH-XR600P | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE AH-XR600P-AU | 98011-AH-XR600P-AU | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD ONSITE AH-XR600P-EU | 98011-AH-XR600P-EU | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD ONSITE AH-XR600P-KR | 98011-AH-XR600P-KR | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD ONSITE AH-XR600P-UK | 98011-AH-XR600P-UK | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD ONSITE AH-XR600P-US | 98011-AH-XR600P-US | \$ 102.00 | 6% | <i>\$96.60</i> |
| EWP Premier NBD ONSITE AP-8533-68SB30-IL | 98011-AP-8533-68SB30-IL | \$ 169.00 | 6% | <i>\$160.05</i> |
| EWP Premier NBD ONSITE AP3000-IL | 98011-AP3000-IL | \$ 70.65 | 6% | <i>\$66.91</i> |

| | | | | |
|--|---------------------------|----------|-----|----------------|
| EWP Premier NBD ONSITE AP3000-TN | 98011-AP3000- TN | \$ 70.65 | 6% | <i>\$66.91</i> |
| EWP Premier NBD ONSITE AP3000-WW | 98011-AP3000- WW | \$ 70.65 | 6% | <i>\$66.91</i> |
| EWP Premier NBD ONSITE AP3000X-WW | 98011- AP3000X-WW | \$ 90.28 | 6% | <i>\$85.49</i> |
| EWP Premier NBD ONSITE AP302W-CAN | 98011- AP302W-CAN | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier NBD ONSITE AP302W-EG | 98011- AP302W-EG | \$ 74.00 | 10% | <i>\$67.10</i> |
| EWP Premier NBD ONSITE AP302W-FCC | 98011- AP302W-FCC | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier NBD ONSITE AP302W-WR | 98011- AP302W-WR | \$ 66.00 | 6% | <i>\$62.51</i> |
| EWP Premier NBD ONSITE AP305C-1-CAN | 98011-AP305C- 1-CAN | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE AP305C-1-EG | 98011-AP305C- 1-EG | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE AP305C-FCC | 98011-AP305C- 1-FCC | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE AP305C-1-IL | 98011-AP305C- 1-IL | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE AP305C-1-WR | 98011-AP305C- 1-WR | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE AP305C-CAN | 98011-AP305C- CAN | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP305C-EG | 98011-AP305C- EG | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP305C-FCC | 98011-AP305C- FCC | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP305C-IL | 98011-AP305C- IL | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP305C-WR | 98011-AP305C- WR | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP305CX-CAN | 98011- AP305CX- CAN | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP305CX-FCC | 98011- AP305CX- FCC | \$ 95.00 | 6% | <i>\$89.97</i> |

| | | | | |
|---------------------------------------|-----------------------|----------|-----|----------------|
| EWP Premier NBD ONSITE AP305CX-IL | 98011- AP305CX-IL | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP305CX-WR | 98011- AP305CX-WR | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE AP310e-1-WR | 98011-AP310e- 1-WR | \$ 57.00 | 10% | <i>\$51.68</i> |
| EWP Premier NBD ONSITE AP310e-CAN | 98011-AP310e- CAN | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP310e-FCC | 98011-AP310e- FCC | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP310e-IL | 98011-AP310e- IL | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP310e-WR | 98011-AP310e- WR | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP310i-1-WR | 98011-AP310i- 1-WR | \$ 57.00 | 10% | <i>\$51.68</i> |
| EWP Premier NBD ONSITE AP310i-CAN | 98011-AP310i- CAN | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP310i-FCC | 98011-AP310i- FCC | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP310i-IL | 98011-AP310i- IL | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP310i-WR | 98011-AP310i- WR | \$ 60.00 | 6% | <i>\$56.82</i> |
| EWP Premier NBD ONSITE AP360e-CAN | 98011-AP360e- CAN | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE AP360e-FCC | 98011-AP360e- FCC | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE AP360e-IL | 98011-AP360e- IL | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE AP360e-WR | 98011-AP360e- WR | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE AP360i-CAN | 98011-AP360i- CAN | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE AP360i-FCC | 98011-AP360i- FCC | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE AP360i-WR | 98011-AP360i- WR | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE AP4000-WW | 98011-AP4000- 1-WW | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier NBD ONSITE AP4000-IL | 98011-AP4000- IL | \$ 98.00 | 6% | <i>\$92.81</i> |

| | | | | |
|--|------------------------|-----------|-----|-----------------|
| EWP Premier NBD ONSITE AP4000-WW | 98011-AP4000- WW | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier NBD ONSITE AP410C-1-CAN | 98011-AP410C- 1-CAN | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE AP410C-1-EG | 98011-AP410C- 1-EG | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE AP410C-1-FCC | 98011-AP410C- 1-FCC | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE AP410C-1-IL | 98011-AP410C- 1-IL | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE AP410C-1-WR | 98011-AP410C- 1-WR | \$ 97.00 | 6% | <i>\$91.86</i> |
| EWP Premier NBD ONSITE AP410C-CAN | 98011-AP410C- CAN | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier NBD ONSITE AP410C-EG | 98011-AP410C- EG | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier NBD ONSITE AP410C-FCC | 98011-AP410C- FCC | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier NBD ONSITE AP410C-IL | 98011-AP410C- IL | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier NBD ONSITE AP410C-WR | 98011-AP410C- WR | \$ 104.00 | 6% | <i>\$98.49</i> |
| EWP Premier NBD ONSITE AP410e-CAN | 98011-AP410e- CAN | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE AP410e-FCC | 98011-AP410e- FCC | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE AP410e-WR | 98011-AP410e- WR | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE AP410i-1-FCC | 98011-AP410i- 1-FCC | \$ 101.00 | 10% | <i>\$91.58</i> |
| EWP Premier NBD ONSITE AP410i-1-WR | 98011-AP410i- 1-WR | \$ 101.00 | 10% | <i>\$91.58</i> |
| EWP Premier NBD ONSITE AP410i-CAN | 98011-AP410i- CAN | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE AP410i-FCC | 98011-AP410i- FCC | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE AP410i-IL | 98011-AP410i- IL | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE AP410i-WR | 98011-AP410i- WR | \$ 106.00 | 6% | <i>\$100.39</i> |

| | | | | |
|---|-----------------------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE AP460C-CAN | 98011-AP460C- CAN | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460C-EG | 98011-AP460C- EG | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460C-FCC | 98011-AP460C- FCC | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460C-IL | 98011-AP460C- IL | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460C-WR | 98011-AP460C- WR | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460e-CAN | 98011-AP460e- CAN | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier NBD ONSITE AP460e-FCC | 98011-AP460e- FCC | \$ 125.00 | 6% | <i>\$118.38</i> |
| EWP Premier NBD ONSITE AP460e-WR | 98011-AP460e- WR | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD ONSITE AP460i-CAN | 98011-AP460i- CAN | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD ONSITE AP460i-FCC | 98011-AP460i- FCC | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD ONSITE AP460i-IL | 98011-AP460i- IL | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD ONSITE AP460i-WR | 98011-AP460i- WR | \$ 120.00 | 6% | <i>\$113.65</i> |
| EWP Premier NBD ONSITE AP460S12C-CAN | 98011- AP460S12C- CAN | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460S12C-FCC | 98011- AP460S12C- FCC | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460S12C-WR | 98011- AP460S12C- WR | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460S6C-CAN | 98011- AP460S6C- CAN | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460S6C-FCC | 98011- AP460S6C- FCC | \$ 129.00 | 6% | <i>\$122.17</i> |
| EWP Premier NBD ONSITE AP460S6C-WR | 98011- AP460S6C- WR | \$ 129.00 | 6% | <i>\$122.17</i> |

| | | | | |
|--|---------------------------|-----------|-----|-----------------|
| EWP Premier NBD ONSITE AP5010-IL | 98011-AP5010- IL | \$ 159.00 | 6% | <i>\$150.58</i> |
| EWP Premier NBD ONSITE AP5010-WW | 98011-AP5010- WW | \$ 159.00 | 10% | <i>\$144.17</i> |
| EWP Premier NBD ONSITE AP5020-WW | 98011-AP5020- WW | \$ 188.32 | 6% | <i>\$178.35</i> |
| EWP Premier NBD ONSITE AP5050D-WW | 98011- AP5050D-WW | \$ 383.00 | 6% | <i>\$362.72</i> |
| EWP Premier NBD ONSITE AP5050U-WW | 98011- AP5050U-WW | \$ 299.00 | 6% | <i>\$283.17</i> |
| EWP Premier NBD ONSITE AP505i-FCC | 98011-AP505i- FCC | \$ 127.00 | 6% | <i>\$120.28</i> |
| EWP Premier NBD ONSITE AP505i-FCC-TAA | 98011-AP505i- FCC-TAA | \$ 127.00 | 6% | <i>\$120.28</i> |
| EWP Premier NBD ONSITE AP505i-WR | 98011-AP505i- WR | \$ 133.00 | 6% | <i>\$125.96</i> |
| EWP Premier NBD ONSITE AP510C-CAN | 98011-AP510C- CAN | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510C-CE | 98011-AP510C- CE | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510C-FCC | 98011-AP510C- FCC | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510C-W | 98011-AP510C- W | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510C-WW | 98011-AP510C- WW | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD ONSITE AP510CX-CAN | 98011- AP510CX- CAN | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510CX-CE | 98011- AP510CX- CE | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510CX-FCC | 98011- AP510CX- FCC | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510CX-W | 98011- AP510CX- W | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE AP510CX-WW | 98011- AP510CX- WW | \$ 140.00 | 6% | <i>\$132.59</i> |
| EWP Premier NBD ONSITE AP510e-FCC | 98011-AP510e- FCC | \$ 171.00 | 6% | <i>\$161.95</i> |

| | | | | |
|--|--------------------------|--------------|-----|--------------------|
| EWP Premier NBD ONSITE AP510e-FCC-TAA | 98011-AP510e- FCC-TAA | \$ 171.00 | 6% | <i>\$161.95</i> |
| EWP Premier NBD ONSITE AP510e-WR | 98011-AP510e- WR | \$ 163.00 | 6% | <i>\$154.37</i> |
| EWP Premier NBD ONSITE AP510i-1-FCC | 98011-AP510i- 1-FCC | \$ 142.00 | 10% | <i>\$128.76</i> |
| EWP Premier NBD ONSITE AP510i-1-WR | 98011-AP510i- 1-WR | \$ 142.00 | 10% | <i>\$128.76</i> |
| EWP Premier NBD ONSITE AP510i-FCC | 98011-AP510i- FCC | \$ 149.00 | 6% | <i>\$141.11</i> |
| EWP Premier NBD ONSITE AP510i-FCC-TAA | 98011-AP510i- FCC-TAA | \$ 149.00 | 6% | <i>\$141.11</i> |
| EWP Premier NBD ONSITE AP510i-WR | 98011-AP510i- WR | \$ 149.00 | 6% | <i>\$141.11</i> |
| EWP Premier NBD ONSITE AP560h-FCC | 98011-AP560h- FCC | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier NBD ONSITE AP560h-WR | 98011-AP560h- WR | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier NBD ONSITE AP560i-FCC | 98011-AP560i- FCC | \$ 274.00 | 6% | <i>\$259.49</i> |
| EWP Premier NBD ONSITE AP560i-WR | 98011-AP560i- WR | \$ 261.00 | 6% | <i>\$247.18</i> |
| EWP Premier NBD ONSITE AP560m-FCC | 98011-AP560m- FCC | \$ 274.00 | 6% | <i>\$259.49</i> |
| EWP Premier NBD ONSITE AP560t-FCC | 98011-AP560t- FCC | \$ 375.00 | 6% | <i>\$355.14</i> |
| EWP Premier NBD ONSITE AP560u-FCC | 98011-AP560u- FCC | \$ 255.00 | 6% | <i>\$241.50</i> |
| EWP Premier NBD ONSITE E2122 | 98011-E2122 | \$ 6,451.00 | 6% | <i>\$6,109.42</i> |
| EWP Premier NBD ONSITE E2122-1 | 98011-E2122-1 | \$ 6,144.00 | 6% | <i>\$5,818.68</i> |
| EWP Premier NBD ONSITE E3120-1 | 98011-E3120-1 | \$ 10,051.00 | 6% | <i>\$9,518.80</i> |
| EWP Premier NBD ONSITE E3125 | 98011-E3125 | \$ 10,592.00 | 6% | <i>\$10,031.15</i> |
| EWP Premier NBD ONSITE H30078 | 98011-H30078 | \$ 3,171.00 | 6% | <i>\$3,003.10</i> |
| EWP Premier NBD ONSITE H30104 | 98011-H30104 | \$ 2,876.00 | 6% | <i>\$2,723.72</i> |
| EWP Premier NBD ONSITE H30105 | 98011-H30105 | \$ 2,896.00 | 6% | <i>\$2,742.66</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H30131 | 98011-H30131 | \$ 1,659.00 | 6% | <i>\$1,571.16</i> |
| EWP Premier NBD ONSITE H30132 | 98011-H30132 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWP Premier NBD ONSITE H30133 | 98011-H30133 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30134 | 98011-H30134 | \$ 5,411.00 | 6% | <i>\$5,124.49</i> |
| EWP Premier NBD ONSITE H30135 | 98011-H30135 | \$ 4,361.00 | 6% | <i>\$4,130.09</i> |
| EWP Premier NBD ONSITE H30136 | 98011-H30136 | \$ 5,411.00 | 6% | <i>\$5,124.49</i> |
| EWP Premier NBD ONSITE H30184 | 98011-H30184 | \$ 75.00 | 6% | <i>\$71.03</i> |
| EWP Premier NBD ONSITE H30185 | 98011-H30185 | \$ 386.00 | 6% | <i>\$365.56</i> |
| EWP Premier NBD ONSITE H30186 | 98011-H30186 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier NBD ONSITE H30187 | 98011-H30187 | \$ 80.00 | 6% | <i>\$75.76</i> |
| EWP Premier NBD ONSITE H30188 | 98011-H30188 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier NBD ONSITE H30189 | 98011-H30189 | \$ 198.00 | 6% | <i>\$187.52</i> |
| EWP Premier NBD ONSITE H30190 | 98011-H30190 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30214 | 98011-H30214 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30215 | 98011-H30215 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30216 | 98011-H30216 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30217 | 98011-H30217 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30218 | 98011-H30218 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30219 | 98011-H30219 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30220 | 98011-H30220 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30221 | 98011-H30221 | \$ 653.00 | 6% | <i>\$618.42</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H30222 | 98011-H30222 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30223 | 98011-H30223 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30224 | 98011-H30224 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30225 | 98011-H30225 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30226 | 98011-H30226 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30227 | 98011-H30227 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30228 | 98011-H30228 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30229 | 98011-H30229 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30267 | 98011-H30267 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30268 | 98011-H30268 | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWP Premier NBD ONSITE H30269 | 98011-H30269 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30270 | 98011-H30270 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30271 | 98011-H30271 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30272 | 98011-H30272 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30273 | 98011-H30273 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier NBD ONSITE H30274 | 98011-H30274 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier NBD ONSITE H30275 | 98011-H30275 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30276 | 98011-H30276 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30277 | 98011-H30277 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier NBD ONSITE H30278 | 98011-H30278 | \$ 969.00 | 6% | <i>\$917.69</i> |
| EWP Premier NBD ONSITE H30279 | 98011-H30279 | \$ 888.00 | 6% | <i>\$840.98</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H30280 | 98011-H30280 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier NBD ONSITE H30281 | 98011-H30281 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier NBD ONSITE H30282 | 98011-H30282 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWP Premier NBD ONSITE H30283 | 98011-H30283 | \$ 594.00 | 6% | <i>\$562.55</i> |
| EWP Premier NBD ONSITE H30284 | 98011-H30284 | \$ 653.00 | 6% | <i>\$618.42</i> |
| EWP Premier NBD ONSITE H30293 | 98011-H30293 | \$ 3,122.00 | 6% | <i>\$2,956.69</i> |
| EWP Premier NBD ONSITE H30296 | 98011-H30296 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30297 | 98011-H30297 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30298 | 98011-H30298 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30299 | 98011-H30299 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30381 | 98011-H30381 | \$ 595.00 | 6% | <i>\$563.49</i> |
| EWP Premier NBD ONSITE H30384 | 98011-H30384 | \$ 476.00 | 6% | <i>\$450.80</i> |
| EWP Premier NBD ONSITE H30391 | 98011-H30391 | \$ 1,117.00 | 6% | <i>\$1,057.85</i> |
| EWP Premier NBD ONSITE H30392 | 98011-H30392 | \$ 1,117.00 | 6% | <i>\$1,057.85</i> |
| EWP Premier NBD ONSITE H30393 | 98011-H30393 | \$ 506.00 | 6% | <i>\$479.21</i> |
| EWP Premier NBD ONSITE H30394 | 98011-H30394 | \$ 2,165.00 | 6% | <i>\$2,050.36</i> |
| EWP Premier NBD ONSITE H30395 | 98011-H30395 | \$ 2,575.00 | 6% | <i>\$2,438.65</i> |
| EWP Premier NBD ONSITE H30396 | 98011-H30396 | \$ 2,350.00 | 6% | <i>\$2,225.57</i> |
| EWP Premier NBD ONSITE H30397 | 98011-H30397 | \$ 2,788.00 | 6% | <i>\$2,640.38</i> |
| EWP Premier NBD ONSITE H30398 | 98011-H30398 | \$ 516.00 | 6% | <i>\$488.68</i> |
| EWP Premier NBD ONSITE H30400 | 98011-H30400 | \$ 282.00 | 6% | <i>\$267.07</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H30401 | 98011-H30401 | \$ 396.00 | 6% | <i>\$375.03</i> |
| EWP Premier NBD ONSITE H30402 | 98011-H30402 | \$ 426.00 | 6% | <i>\$403.44</i> |
| EWP Premier NBD ONSITE H30403 | 98011-H30403 | \$ 630.00 | 6% | <i>\$596.64</i> |
| EWP Premier NBD ONSITE H30434 | 98011-H30434 | \$ 173.00 | 6% | <i>\$163.84</i> |
| EWP Premier NBD ONSITE H30480 | 98011-H30480 | \$ 735.00 | 6% | <i>\$696.08</i> |
| EWP Premier NBD ONSITE H30495 | 98011-H30495 | \$ 1,659.00 | 6% | <i>\$1,571.16</i> |
| EWP Premier NBD ONSITE H30496 | 98011-H30496 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWP Premier NBD ONSITE H30497 | 98011-H30497 | \$ 2,394.00 | 6% | <i>\$2,267.24</i> |
| EWP Premier NBD ONSITE H30498 | 98011-H30498 | \$ 2,350.00 | 6% | <i>\$2,225.57</i> |
| EWP Premier NBD ONSITE H30499 | 98011-H30499 | \$ 810.00 | 6% | <i>\$767.11</i> |
| EWP Premier NBD ONSITE H30501 | 98011-H30501 | \$ 2,350.00 | 6% | <i>\$2,225.57</i> |
| EWP Premier NBD ONSITE H30502 | 98011-H30502 | \$ 3,614.00 | 6% | <i>\$3,422.64</i> |
| EWP Premier NBD ONSITE H30503 | 98011-H30503 | \$ 810.00 | 6% | <i>\$767.11</i> |
| EWP Premier NBD ONSITE H30505 | 98011-H30505 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30506 | 98011-H30506 | \$ 5,812.00 | 6% | <i>\$5,504.25</i> |
| EWP Premier NBD ONSITE H30509 | 98011-H30509 | \$ 3,614.00 | 6% | <i>\$3,422.64</i> |
| EWP Premier NBD ONSITE H30510 | 98011-H30510 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30511 | 98011-H30511 | \$ 5,812.00 | 6% | <i>\$5,504.25</i> |
| EWP Premier NBD ONSITE H30512 | 98011-H30512 | \$ 810.00 | 6% | <i>\$767.11</i> |
| EWP Premier NBD ONSITE H30513 | 98011-H30513 | \$ 1,359.00 | 6% | <i>\$1,287.04</i> |
| EWP Premier NBD ONSITE H30525 | 98011-H30525 | \$ 5,812.00 | 6% | <i>\$5,504.25</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H30526 | 98011-H30526 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30528 | 98011-H30528 | \$ 6,742.00 | 6% | <i>\$6,385.01</i> |
| EWP Premier NBD ONSITE H30531 | 98011-H30531 | \$ 9,601.00 | 6% | <i>\$9,092.63</i> |
| EWP Premier NBD ONSITE H30532 | 98011-H30532 | \$ 9,601.00 | 6% | <i>\$9,092.63</i> |
| EWP Premier NBD ONSITE H30534 | 98011-H30534 | \$ 9,788.00 | 6% | <i>\$9,269.73</i> |
| EWP Premier NBD ONSITE H30535 | 98011-H30535 | \$ 10,441.00 | 6% | <i>\$9,888.15</i> |
| EWP Premier NBD ONSITE H30536 | 98011-H30536 | \$ 9,601.00 | 6% | <i>\$9,092.63</i> |
| EWP Premier NBD ONSITE H30537 | 98011-H30537 | \$ 10,441.00 | 6% | <i>\$9,888.15</i> |
| EWP Premier NBD ONSITE H30538 | 98011-H30538 | \$ 5,812.00 | 6% | <i>\$5,504.25</i> |
| EWP Premier NBD ONSITE H30539 | 98011-H30539 | \$ 11,151.00 | 6% | <i>\$10,560.55</i> |
| EWP Premier NBD ONSITE H30540 | 98011-H30540 | \$ 11,532.00 | 6% | <i>\$10,921.38</i> |
| EWP Premier NBD ONSITE H30543 | 98011-H30543 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWP Premier NBD ONSITE H30544 | 98011-H30544 | \$ 1,410.00 | 6% | <i>\$1,335.34</i> |
| EWP Premier NBD ONSITE H30548 | 98011-H30548 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWP Premier NBD ONSITE H30549 | 98011-H30549 | \$ 1,331.00 | 6% | <i>\$1,260.52</i> |
| EWP Premier NBD ONSITE H30550 | 98011-H30550 | \$ 1,331.00 | 6% | <i>\$1,260.52</i> |
| EWP Premier NBD ONSITE H30552 | 98011-H30552 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWP Premier NBD ONSITE H30553 | 98011-H30553 | \$ 1,254.00 | 6% | <i>\$1,187.60</i> |
| EWP Premier NBD ONSITE H30569 | 98011-H30569 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30570 | 98011-H30570 | \$ 5,122.00 | 6% | <i>\$4,850.79</i> |
| EWP Premier NBD ONSITE H30571 | 98011-H30571 | \$ 5,122.00 | 6% | <i>\$4,850.79</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H30573 | 98011-H30573 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30574 | 98011-H30574 | \$ 4,727.00 | 6% | <i>\$4,476.71</i> |
| EWP Premier NBD ONSITE H30575 | 98011-H30575 | \$ 2,952.00 | 6% | <i>\$2,795.69</i> |
| EWP Premier NBD ONSITE H30576 | 98011-H30576 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30577 | 98011-H30577 | \$ 5,024.00 | 6% | <i>\$4,757.98</i> |
| EWP Premier NBD ONSITE H30578 | 98011-H30578 | \$ 5,024.00 | 6% | <i>\$4,757.98</i> |
| EWP Premier NBD ONSITE H30587 | 98011-H30587 | \$ 4,361.00 | 6% | <i>\$4,130.09</i> |
| EWP Premier NBD ONSITE H30588 | 98011-H30588 | \$ 3,010.00 | 6% | <i>\$2,850.62</i> |
| EWP Premier NBD ONSITE H30589 | 98011-H30589 | \$ 4,568.00 | 6% | <i>\$4,326.12</i> |
| EWP Premier NBD ONSITE H30632 | 98011-H30632 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD ONSITE H30633 | 98011-H30633 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD ONSITE H30643 | 98011-H30643 | \$ 7,201.00 | 6% | <i>\$6,819.71</i> |
| EWP Premier NBD ONSITE H30706 | 98011-H30706 | \$ 6,873.00 | 6% | <i>\$6,509.07</i> |
| EWP Premier NBD ONSITE H30707 | 98011-H30707 | \$ 4,277.00 | 6% | <i>\$4,050.53</i> |
| EWP Premier NBD ONSITE H30724 | 98011-H30724 | \$ 476.00 | 6% | <i>\$450.80</i> |
| EWP Premier NBD ONSITE H30725 | 98011-H30725 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWP Premier NBD ONSITE H30726 | 98011-H30726 | \$ 10,644.00 | 6% | <i>\$10,080.40</i> |
| EWP Premier NBD ONSITE H30727 | 98011-H30727 | \$ 11,314.00 | 6% | <i>\$10,714.92</i> |
| EWP Premier NBD ONSITE H30730 | 98011-H30730 | \$ 113.00 | 6% | <i>\$107.02</i> |
| EWP Premier NBD ONSITE H30731 | 98011-H30731 | \$ 113.00 | 6% | <i>\$107.02</i> |
| EWP Premier NBD ONSITE H30732 | 98011-H30732 | \$ 2,271.00 | 6% | <i>\$2,150.75</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H30733 | 98011-H30733 | \$ 10,289.00 | 6% | <i>\$9,744.20</i> |
| EWP Premier NBD ONSITE H30734 | 98011-H30734 | \$ 7,844.00 | 6% | <i>\$7,428.66</i> |
| EWP Premier NBD ONSITE H30735 | 98011-H30735 | \$ 9,046.00 | 6% | <i>\$8,567.01</i> |
| EWP Premier NBD ONSITE H30736 | 98011-H30736 | \$ 1,431.00 | 6% | <i>\$1,355.23</i> |
| EWP Premier NBD ONSITE H30738 | 98011-H30738 | \$ 77.00 | 6% | <i>\$72.92</i> |
| EWP Premier NBD ONSITE H30739 | 98011-H30739 | \$ 1,492.00 | 6% | <i>\$1,413.00</i> |
| EWP Premier NBD ONSITE H30740 | 98011-H30740 | \$ 865.00 | 6% | <i>\$819.20</i> |
| EWP Premier NBD ONSITE H30741 | 98011-H30741 | \$ 1,578.00 | 6% | <i>\$1,494.44</i> |
| EWP Premier NBD ONSITE H30742 | 98011-H30742 | \$ 1,406.00 | 6% | <i>\$1,331.55</i> |
| EWP Premier NBD ONSITE H30743 | 98011-H30743 | \$ 1,492.00 | 6% | <i>\$1,413.00</i> |
| EWP Premier NBD ONSITE H30744 | 98011-H30744 | \$ 865.00 | 6% | <i>\$819.20</i> |
| EWP Premier NBD ONSITE H30745 | 98011-H30745 | \$ 883.00 | 6% | <i>\$836.25</i> |
| EWP Premier NBD ONSITE H30746 | 98011-H30746 | \$ 1,599.00 | 6% | <i>\$1,514.33</i> |
| EWP Premier NBD ONSITE H30747 | 98011-H30747 | \$ 3,103.00 | 6% | <i>\$2,938.70</i> |
| EWP Premier NBD ONSITE H30748 | 98011-H30748 | \$ 4,573.00 | 6% | <i>\$4,330.86</i> |
| EWP Premier NBD ONSITE H30749 | 98011-H30749 | \$ 10,275.00 | 6% | <i>\$9,730.94</i> |
| EWP Premier NBD ONSITE H30750 | 98011-H30750 | \$ 10,275.00 | 6% | <i>\$9,730.94</i> |
| EWP Premier NBD ONSITE H30751 | 98011-H30751 | \$ 6,101.00 | 6% | <i>\$5,777.95</i> |
| EWP Premier NBD ONSITE H30754 | 98011-H30754 | \$ 10,275.00 | 6% | <i>\$9,730.94</i> |
| EWP Premier NBD ONSITE H30755 | 98011-H30755 | \$ 11,178.00 | 6% | <i>\$10,586.12</i> |
| EWP Premier NBD ONSITE H30756 | 98011-H30756 | \$ 10,275.00 | 6% | <i>\$9,730.94</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H30757 | 98011-H30757 | \$ 4,573.00 | 6% | <i>\$4,330.86</i> |
| EWP Premier NBD ONSITE H30758 | 98011-H30758 | \$ 8,397.00 | 6% | <i>\$7,952.38</i> |
| EWP Premier NBD ONSITE H30759 | 98011-H30759 | \$ 9,499.00 | 6% | <i>\$8,996.03</i> |
| EWP Premier NBD ONSITE H30760 | 98011-H30760 | \$ 10,805.00 | 6% | <i>\$10,232.88</i> |
| EWP Premier NBD ONSITE H30761 | 98011-H30761 | \$ 4,573.00 | 6% | <i>\$4,330.86</i> |
| EWP Premier NBD ONSITE H30762 | 98011-H30762 | \$ 11,178.00 | 6% | <i>\$10,586.12</i> |
| EWP Premier NBD ONSITE H30763 | 98011-H30763 | \$ 11,178.00 | 6% | <i>\$10,586.12</i> |
| EWP Premier NBD ONSITE H30764 | 98011-H30764 | \$ 7,077.00 | 6% | <i>\$6,702.27</i> |
| EWP Premier NBD ONSITE H30765 | 98011-H30765 | \$ 6,219.00 | 6% | <i>\$5,889.70</i> |
| EWP Premier NBD ONSITE H30766 | 98011-H30766 | \$ 12,108.00 | 6% | <i>\$11,466.88</i> |
| EWP Premier NBD ONSITE H30767 | 98011-H30767 | \$ 7,077.00 | 6% | <i>\$6,702.27</i> |
| EWP Premier NBD ONSITE H30769 | 98011-H30769 | \$ 2,933.00 | 6% | <i>\$2,777.70</i> |
| EWP Premier NBD ONSITE H30773 | 98011-H30773 | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier NBD ONSITE H30774 | 98011-H30774 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier NBD ONSITE H30775 | 98011-H30775 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier NBD ONSITE H30776 | 98011-H30776 | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier NBD ONSITE H30777 | 98011-H30777 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier NBD ONSITE H30778 | 98011-H30778 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier NBD ONSITE H30779 | 98011-H30779 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H30780 | 98011-H30780 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier NBD ONSITE H30781 | 98011-H30781 | \$ 116.00 | 6% | <i>\$109.86</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H30782 | 98011-H30782 | \$ 93.00 | 6% | <i>\$88.08</i> |
| EWP Premier NBD ONSITE H30783 | 98011-H30783 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE H30784 | 98011-H30784 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE H30785 | 98011-H30785 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H30786 | 98011-H30786 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier NBD ONSITE H30787 | 98011-H30787 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H30788 | 98011-H30788 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier NBD ONSITE H30789 | 98011-H30789 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE H30790 | 98011-H30790 | \$ 93.00 | 6% | <i>\$88.08</i> |
| EWP Premier NBD ONSITE H30791 | 98011-H30791 | \$ 95.00 | 6% | <i>\$89.97</i> |
| EWP Premier NBD ONSITE H30793 | 98011-H30793 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30794 | 98011-H30794 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H30795 | 98011-H30795 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30796 | 98011-H30796 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier NBD ONSITE H30797 | 98011-H30797 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30798 | 98011-H30798 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD ONSITE H30799 | 98011-H30799 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30800 | 98011-H30800 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier NBD ONSITE H30801 | 98011-H30801 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier NBD ONSITE H30802 | 98011-H30802 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier NBD ONSITE H30803 | 98011-H30803 | \$ 131.00 | 6% | <i>\$124.06</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H30804 | 98011-H30804 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30805 | 98011-H30805 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD ONSITE H30806 | 98011-H30806 | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE H30807 | 98011-H30807 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30808 | 98011-H30808 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier NBD ONSITE H30809 | 98011-H30809 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD ONSITE H30810 | 98011-H30810 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier NBD ONSITE H30811 | 98011-H30811 | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE H30812 | 98011-H30812 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD ONSITE H30813 | 98011-H30813 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier NBD ONSITE H30814 | 98011-H30814 | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE H30815 | 98011-H30815 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier NBD ONSITE H30816 | 98011-H30816 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier NBD ONSITE H30817 | 98011-H30817 | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE H30818 | 98011-H30818 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD ONSITE H30819 | 98011-H30819 | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE H30820 | 98011-H30820 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier NBD ONSITE H30821 | 98011-H30821 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier NBD ONSITE H30822 | 98011-H30822 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30823 | 98011-H30823 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier NBD ONSITE H30824 | 98011-H30824 | \$ 84.00 | 6% | <i>\$79.55</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H30825 | 98011-H30825 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier NBD ONSITE H30826 | 98011-H30826 | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE H30827 | 98011-H30827 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30828 | 98011-H30828 | \$ 88.00 | 6% | <i>\$83.34</i> |
| EWP Premier NBD ONSITE H30829 | 98011-H30829 | \$ 94.00 | 6% | <i>\$89.02</i> |
| EWP Premier NBD ONSITE H30830 | 98011-H30830 | \$ 131.00 | 6% | <i>\$124.06</i> |
| EWP Premier NBD ONSITE H30831 | 98011-H30831 | \$ 84.00 | 6% | <i>\$79.55</i> |
| EWP Premier NBD ONSITE H30833 | 98011-H30833 | \$ 448.00 | 6% | <i>\$424.28</i> |
| EWP Premier NBD ONSITE H30834 | 98011-H30834 | \$ 448.00 | 6% | <i>\$424.28</i> |
| EWP Premier NBD ONSITE H30836 | 98011-H30836 | \$ 1,669.00 | 6% | <i>\$1,580.63</i> |
| EWP Premier NBD ONSITE H30838 | 98011-H30838 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier NBD ONSITE H30839 | 98011-H30839 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30840 | 98011-H30840 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30841 | 98011-H30841 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30842 | 98011-H30842 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30843 | 98011-H30843 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30844 | 98011-H30844 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30845 | 98011-H30845 | \$ 89.00 | 6% | <i>\$84.29</i> |
| EWP Premier NBD ONSITE H30846 | 98011-H30846 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H30847 | 98011-H30847 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H30848 | 98011-H30848 | \$ 105.00 | 6% | <i>\$99.44</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H30849 | 98011-H30849 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H30850 | 98011-H30850 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H30851 | 98011-H30851 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H30852 | 98011-H30852 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H30853 | 98011-H30853 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30854 | 98011-H30854 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30855 | 98011-H30855 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30856 | 98011-H30856 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30857 | 98011-H30857 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30858 | 98011-H30858 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30859 | 98011-H30859 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30860 | 98011-H30860 | \$ 165.00 | 6% | <i>\$156.26</i> |
| EWP Premier NBD ONSITE H30866 | 98011-H30866 | \$ 177.00 | 6% | <i>\$167.63</i> |
| EWP Premier NBD ONSITE H30867 | 98011-H30867 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H30868 | 98011-H30868 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H30869 | 98011-H30869 | \$ 315.00 | 6% | <i>\$298.32</i> |
| EWP Premier NBD ONSITE H30870 | 98011-H30870 | \$ 315.00 | 6% | <i>\$298.32</i> |
| EWP Premier NBD ONSITE H30871 | 98011-H30871 | \$ 288.00 | 6% | <i>\$272.75</i> |
| EWP Premier NBD ONSITE H30872 | 98011-H30872 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier NBD ONSITE H30873 | 98011-H30873 | \$ 167.00 | 6% | <i>\$158.16</i> |
| EWP Premier NBD ONSITE H30874 | 98011-H30874 | \$ 167.00 | 6% | <i>\$158.16</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H30875 | 98011-H30875 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H30876 | 98011-H30876 | \$ 58.00 | 6% | <i>\$54.93</i> |
| EWP Premier NBD ONSITE H30877 | 98011-H30877 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H30878 | 98011-H30878 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H30891 | 98011-H30891 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE H30892 | 98011-H30892 | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE H30893 | 98011-H30893 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H30894 | 98011-H30894 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H30895 | 98011-H30895 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier NBD ONSITE H30896 | 98011-H30896 | \$ 475.00 | 6% | <i>\$449.85</i> |
| EWP Premier NBD ONSITE H30897 | 98011-H30897 | \$ 825.00 | 6% | <i>\$781.32</i> |
| EWP Premier NBD ONSITE H30898 | 98011-H30898 | \$ 930.00 | 6% | <i>\$880.76</i> |
| EWP Premier NBD ONSITE H30900 | 98011-H30900 | \$ 2,810.00 | 6% | <i>\$2,661.21</i> |
| EWP Premier NBD ONSITE H30901 | 98011-H30901 | \$ 3,739.00 | 6% | <i>\$3,541.02</i> |
| EWP Premier NBD ONSITE H30902 | 98011-H30902 | \$ 3,925.00 | 6% | <i>\$3,717.17</i> |
| EWP Premier NBD ONSITE H30904 | 98011-H30904 | \$ 5,747.00 | 6% | <i>\$5,442.70</i> |
| EWP Premier NBD ONSITE H30905 | 98011-H30905 | \$ 8,209.00 | 6% | <i>\$7,774.33</i> |
| EWP Premier NBD ONSITE H30906 | 98011-H30906 | \$ 229.00 | 6% | <i>\$216.87</i> |
| EWP Premier NBD ONSITE H30912 | 98011-H30912 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWP Premier NBD ONSITE H30913 | 98011-H30913 | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier NBD ONSITE H30914 | 98011-H30914 | \$ 60.00 | 6% | <i>\$56.82</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H30915 | 98011-H30915 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier NBD ONSITE H30916 | 98011-H30916 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier NBD ONSITE H30917 | 98011-H30917 | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier NBD ONSITE H30918 | 98011-H30918 | \$ 67.00 | 6% | <i>\$63.45</i> |
| EWP Premier NBD ONSITE H30946 | 98011-H30946 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier NBD ONSITE H30948 | 98011-H30948 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier NBD ONSITE H30950 | 98011-H30950 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier NBD ONSITE H30951 | 98011-H30951 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier NBD ONSITE H30952 | 98011-H30952 | \$ 116.00 | 6% | <i>\$109.86</i> |
| EWP Premier NBD ONSITE H30966 | 98011-H30966 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier NBD ONSITE H30967 | 98011-H30967 | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier NBD ONSITE H30968 | 98011-H30968 | \$ 204.00 | 6% | <i>\$193.20</i> |
| EWP Premier NBD ONSITE H30969 | 98011-H30969 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H30970 | 98011-H30970 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier NBD ONSITE H30971 | 98011-H30971 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier NBD ONSITE H30972 | 98011-H30972 | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier NBD ONSITE H30973 | 98011-H30973 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30974 | 98011-H30974 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier NBD ONSITE H30975 | 98011-H30975 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30976 | 98011-H30976 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30977 | 98011-H30977 | \$ 180.00 | 6% | <i>\$170.47</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H30978 | 98011-H30978 | \$ 207.00 | 6% | <i>\$196.04</i> |
| EWP Premier NBD ONSITE H30995 | 98011-H30995 | \$ 2,248.00 | 6% | <i>\$2,128.97</i> |
| EWP Premier NBD ONSITE H31030 | 98011-H31030 | \$ 7,251.00 | 6% | <i>\$6,867.06</i> |
| EWP Premier NBD ONSITE H31031 | 98011-H31031 | \$ 578.00 | 6% | <i>\$547.39</i> |
| EWP Premier NBD ONSITE H31033 | 98011-H31033 | \$ 4,309.00 | 6% | <i>\$4,080.84</i> |
| EWP Premier NBD ONSITE H31034 | 98011-H31034 | \$ 2,395.00 | 6% | <i>\$2,268.18</i> |
| EWP Premier NBD ONSITE H31035 | 98011-H31035 | \$ 2,509.00 | 6% | <i>\$2,376.15</i> |
| EWP Premier NBD ONSITE H31036 | 98011-H31036 | \$ 5,019.00 | 6% | <i>\$4,753.24</i> |
| EWP Premier NBD ONSITE H31040 | 98011-H31040 | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier NBD ONSITE H31041 | 98011-H31041 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H31042 | 98011-H31042 | \$ 290.00 | 6% | <i>\$274.64</i> |
| EWP Premier NBD ONSITE H31043 | 98011-H31043 | \$ 210.00 | 6% | <i>\$198.88</i> |
| EWP Premier NBD ONSITE H31047 | 98011-H31047 | \$ 194.00 | 6% | <i>\$183.73</i> |
| EWP Premier NBD ONSITE H31049 | 98011-H31049 | \$ 2,010.00 | 6% | <i>\$1,903.57</i> |
| EWP Premier NBD ONSITE H31060 | 98011-H31060 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier NBD ONSITE H31062 | 98011-H31062 | \$ 61.00 | 6% | <i>\$57.77</i> |
| EWP Premier NBD ONSITE H31066 | 98011-H31066 | \$ 81.00 | 6% | <i>\$76.71</i> |
| EWP Premier NBD ONSITE H31068 | 98011-H31068 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier NBD ONSITE H31077 | 98011-H31077 | \$ 290.00 | 6% | <i>\$274.64</i> |
| EWP Premier NBD ONSITE H31103 | 98011-H31103 | \$ 4,597.00 | 6% | <i>\$4,353.59</i> |
| EWP Premier NBD ONSITE H31124 | 98011-H31124 | \$ 109.00 | 6% | <i>\$103.23</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H31127 | 98011-H31127 | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier NBD ONSITE H31132 | 98011-H31132 | \$ 179.00 | 6% | <i>\$169.52</i> |
| EWP Premier NBD ONSITE H31134 | 98011-H31134 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H31135 | 98011-H31135 | \$ 65.00 | 6% | <i>\$61.56</i> |
| EWP Premier NBD ONSITE H31136 | 98011-H31136 | \$ 98.00 | 6% | <i>\$92.81</i> |
| EWP Premier NBD ONSITE H31137 | 98011-H31137 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H31197 | 98011-H31197 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H31198 | 98011-H31198 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H31199 | 98011-H31199 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H31200 | 98011-H31200 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H31201 | 98011-H31201 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H31202 | 98011-H31202 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE H31203 | 98011-H31203 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD ONSITE H31204 | 98011-H31204 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H31205 | 98011-H31205 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD ONSITE H31206 | 98011-H31206 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD ONSITE H31207 | 98011-H31207 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H31208 | 98011-H31208 | \$ 128.00 | 6% | <i>\$121.22</i> |
| EWP Premier NBD ONSITE H31210 | 98011-H31210 | \$ 229.00 | 6% | <i>\$216.87</i> |
| EWP Premier NBD ONSITE H31335 | 98011-H31335 | \$ 126.00 | 6% | <i>\$119.33</i> |
| EWP Premier NBD ONSITE H31337 | 98011-H31337 | \$ 9,731.00 | 6% | <i>\$9,215.74</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H31338 | 98011-H31338 | \$ 9,731.00 | 6% | <i>\$9,215.74</i> |
| EWP Premier NBD ONSITE H31339 | 98011-H31339 | \$ 1,584.00 | 6% | <i>\$1,500.13</i> |
| EWP Premier NBD ONSITE H31340 | 98011-H31340 | \$ 3,379.00 | 6% | <i>\$3,200.08</i> |
| EWP Premier NBD ONSITE H31341 | 98011-H31341 | \$ 5,007.00 | 6% | <i>\$4,741.88</i> |
| EWP Premier NBD ONSITE H31342 | 98011-H31342 | \$ 1,575.00 | 6% | <i>\$1,491.60</i> |
| EWP Premier NBD ONSITE H31343 | 98011-H31343 | \$ 2,333.00 | 6% | <i>\$2,209.47</i> |
| EWP Premier NBD ONSITE H31344 | 98011-H31344 | \$ 2,333.00 | 6% | <i>\$2,209.47</i> |
| EWP Premier NBD ONSITE H31345 | 98011-H31345 | \$ 2,333.00 | 6% | <i>\$2,209.47</i> |
| EWP Premier NBD ONSITE H31346 | 98011-H31346 | \$ 2,333.00 | 6% | <i>\$2,209.47</i> |
| EWP Premier NBD ONSITE H31348 | 98011-H31348 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier NBD ONSITE H31349 | 98011-H31349 | \$ 180.00 | 6% | <i>\$170.47</i> |
| EWP Premier NBD ONSITE H31350 | 98011-H31350 | \$ 288.00 | 6% | <i>\$272.75</i> |
| EWP Premier NBD ONSITE H31351 | 98011-H31351 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H31352 | 98011-H31352 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H31353 | 98011-H31353 | \$ 93.00 | 6% | <i>\$88.08</i> |
| EWP Premier NBD ONSITE H31354 | 98011-H31354 | \$ 93.00 | 6% | <i>\$88.08</i> |
| EWP Premier NBD ONSITE H31355 | 98011-H31355 | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier NBD ONSITE H31356 | 98011-H31356 | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier NBD ONSITE H31357 | 98011-H31357 | \$ 191.00 | 6% | <i>\$180.89</i> |
| EWP Premier NBD ONSITE H31358 | 98011-H31358 | \$ 69.00 | 6% | <i>\$65.35</i> |
| EWP Premier NBD ONSITE H31359 | 98011-H31359 | \$ 81.00 | 6% | <i>\$76.71</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H31360 | 98011-H31360 | \$ 64.00 | 6% | <i>\$60.61</i> |
| EWP Premier NBD ONSITE H31361 | 98011-H31361 | \$ 3,165.00 | 6% | <i>\$2,997.41</i> |
| EWP Premier NBD ONSITE H31362 | 98011-H31362 | \$ 26,709.00 | 6% | <i>\$25,294.76</i> |
| EWP Premier NBD ONSITE H31363 | 98011-H31363 | \$ 26,709.00 | 6% | <i>\$25,294.76</i> |
| EWP Premier NBD ONSITE H31364 | 98011-H31364 | \$ 9,335.00 | 6% | <i>\$8,840.71</i> |
| EWP Premier NBD ONSITE H31365 | 98011-H31365 | \$ 9,335.00 | 6% | <i>\$8,840.71</i> |
| EWP Premier NBD ONSITE H31366 | 98011-H31366 | \$ 12,944.00 | 6% | <i>\$12,258.62</i> |
| EWP Premier NBD ONSITE H31367 | 98011-H31367 | \$ 12,944.00 | 6% | <i>\$12,258.62</i> |
| EWP Premier NBD ONSITE H31369 | 98011-H31369 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H31370 | 98011-H31370 | \$ 112.00 | 6% | <i>\$106.07</i> |
| EWP Premier NBD ONSITE H31393 | 98011-H31393 | \$ 63.00 | 6% | <i>\$59.66</i> |
| EWP Premier NBD ONSITE H32010 | 98011-H32010 | \$ 359.00 | 6% | <i>\$339.99</i> |
| EWP Premier NBD ONSITE H32011 | 98011-H32011 | \$ 359.00 | 6% | <i>\$339.99</i> |
| EWP Premier NBD ONSITE H32012 | 98011-H32012 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWP Premier NBD ONSITE H32013 | 98011-H32013 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWP Premier NBD ONSITE H32014 | 98011-H32014 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWP Premier NBD ONSITE H32015 | 98011-H32015 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWP Premier NBD ONSITE H32016 | 98011-H32016 | \$ 2,663.00 | 6% | <i>\$2,521.99</i> |
| EWP Premier NBD ONSITE H32017 | 98011-H32017 | \$ 2,663.00 | 6% | <i>\$2,521.99</i> |
| EWP Premier NBD ONSITE H32018 | 98011-H32018 | \$ 2,663.00 | 6% | <i>\$2,521.99</i> |
| EWP Premier NBD ONSITE H32019 | 98011-H32019 | \$ 2,663.00 | 6% | <i>\$2,521.99</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H32020 | 98011-H32020 | \$ 26,614.00 | 6% | <i>\$25,204.79</i> |
| EWP Premier NBD ONSITE H32021 | 98011-H32021 | \$ 26,614.00 | 6% | <i>\$25,204.79</i> |
| EWP Premier NBD ONSITE H32022 | 98011-H32022 | \$ 26,614.00 | 6% | <i>\$25,204.79</i> |
| EWP Premier NBD ONSITE H32023 | 98011-H32023 | \$ 26,614.00 | 6% | <i>\$25,204.79</i> |
| EWP Premier NBD ONSITE H32028 | 98011-H32028 | \$ 51,318.00 | 6% | <i>\$48,600.71</i> |
| EWP Premier NBD ONSITE H32029 | 98011-H32029 | \$ 51,318.00 | 6% | <i>\$48,600.71</i> |
| EWP Premier NBD ONSITE H32030 | 98011-H32030 | \$ 53,818.00 | 6% | <i>\$50,968.34</i> |
| EWP Premier NBD ONSITE H32031 | 98011-H32031 | \$ 53,818.00 | 6% | <i>\$50,968.34</i> |
| EWP Premier NBD ONSITE H32032 | 98011-H32032 | \$ 53,818.00 | 6% | <i>\$50,968.34</i> |
| EWP Premier NBD ONSITE H32033 | 98011-H32033 | \$ 53,818.00 | 6% | <i>\$50,968.34</i> |
| EWP Premier NBD ONSITE H32038 | 98011-H32038 | \$ 9,302.00 | 6% | <i>\$8,809.46</i> |
| EWP Premier NBD ONSITE H32039 | 98011-H32039 | \$ 9,302.00 | 6% | <i>\$8,809.46</i> |
| EWP Premier NBD ONSITE H32040 | 98011-H32040 | \$ 9,302.00 | 6% | <i>\$8,809.46</i> |
| EWP Premier NBD ONSITE H32041 | 98011-H32041 | \$ 9,302.00 | 6% | <i>\$8,809.46</i> |
| EWP Premier NBD ONSITE H32046 | 98011-H32046 | \$ 12,901.00 | 6% | <i>\$12,217.89</i> |
| EWP Premier NBD ONSITE H32047 | 98011-H32047 | \$ 12,901.00 | 6% | <i>\$12,217.89</i> |
| EWP Premier NBD ONSITE H32048 | 98011-H32048 | \$ 12,901.00 | 6% | <i>\$12,217.89</i> |
| EWP Premier NBD ONSITE H32049 | 98011-H32049 | \$ 12,901.00 | 6% | <i>\$12,217.89</i> |
| EWP Premier NBD ONSITE H32054 | 98011-H32054 | \$ 9,302.00 | 6% | <i>\$8,809.46</i> |
| EWP Premier NBD ONSITE H32055 | 98011-H32055 | \$ 12,901.00 | 6% | <i>\$12,217.89</i> |
| EWP Premier NBD ONSITE H32056 | 98011-H32056 | \$ 3,507.00 | 6% | <i>\$3,321.30</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H32057 | 98011-H32057 | \$ 3,507.00 | 6% | <i>\$3,321.30</i> |
| EWP Premier NBD ONSITE H32058 | 98011-H32058 | \$ 3,507.00 | 6% | <i>\$3,321.30</i> |
| EWP Premier NBD ONSITE H32059 | 98011-H32059 | \$ 3,507.00 | 6% | <i>\$3,321.30</i> |
| EWP Premier NBD ONSITE H32060 | 98011-H32060 | \$ 3,571.00 | 6% | <i>\$3,381.92</i> |
| EWP Premier NBD ONSITE H32061 | 98011-H32061 | \$ 3,750.00 | 6% | <i>\$3,551.44</i> |
| EWP Premier NBD ONSITE H32062 | 98011-H32062 | \$ 3,571.00 | 6% | <i>\$3,381.92</i> |
| EWP Premier NBD ONSITE H32063 | 98011-H32063 | \$ 3,575.00 | 6% | <i>\$3,385.70</i> |
| EWP Premier NBD ONSITE H32064 | 98011-H32064 | \$ 3,571.00 | 6% | <i>\$3,381.92</i> |
| EWP Premier NBD ONSITE H32065 | 98011-H32065 | \$ 4,070.00 | 6% | <i>\$3,854.49</i> |
| EWP Premier NBD ONSITE H32066 | 98011-H32066 | \$ 4,070.00 | 6% | <i>\$3,854.49</i> |
| EWP Premier NBD ONSITE H32067 | 98011-H32067 | \$ 4,070.00 | 6% | <i>\$3,854.49</i> |
| EWP Premier NBD ONSITE H32068 | 98011-H32068 | \$ 4,070.00 | 6% | <i>\$3,854.49</i> |
| EWP Premier NBD ONSITE H32069 | 98011-H32069 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWP Premier NBD ONSITE H32070 | 98011-H32070 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWP Premier NBD ONSITE H32071 | 98011-H32071 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWP Premier NBD ONSITE H32072 | 98011-H32072 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWP Premier NBD ONSITE H32073 | 98011-H32073 | \$ 37,441.00 | 6% | <i>\$35,458.50</i> |
| EWP Premier NBD ONSITE H32074 | 98011-H32074 | \$ 37,441.00 | 6% | <i>\$35,458.50</i> |
| EWP Premier NBD ONSITE H32075 | 98011-H32075 | \$ 50,878.00 | 6% | <i>\$48,184.01</i> |
| EWP Premier NBD ONSITE H32076 | 98011-H32076 | \$ 50,394.00 | 6% | <i>\$47,725.64</i> |
| EWP Premier NBD ONSITE H32101 | 98011-H32101 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H32102 | 98011-H32102 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWP Premier NBD ONSITE H32103 | 98011-H32103 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWP Premier NBD ONSITE H32104 | 98011-H32104 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWP Premier NBD ONSITE H32105 | 98011-H32105 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32106 | 98011-H32106 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32107 | 98011-H32107 | \$ 9,022.00 | 6% | <i>\$8,544.29</i> |
| EWP Premier NBD ONSITE H32108 | 98011-H32108 | \$ 9,022.00 | 6% | <i>\$8,544.29</i> |
| EWP Premier NBD ONSITE H32109 | 98011-H32109 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32110 | 98011-H32110 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32111 | 98011-H32111 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWP Premier NBD ONSITE H32112 | 98011-H32112 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWP Premier NBD ONSITE H32113 | 98011-H32113 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWP Premier NBD ONSITE H32114 | 98011-H32114 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWP Premier NBD ONSITE H32115 | 98011-H32115 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32116 | 98011-H32116 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32117 | 98011-H32117 | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| EWP Premier NBD ONSITE H32118 | 98011-H32118 | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| EWP Premier NBD ONSITE H32119 | 98011-H32119 | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| EWP Premier NBD ONSITE H32120 | 98011-H32120 | \$ 1,568.00 | 6% | <i>\$1,484.97</i> |
| EWP Premier NBD ONSITE H32121 | 98011-H32121 | \$ 9,022.00 | 6% | <i>\$8,544.29</i> |
| EWP Premier NBD ONSITE H32122 | 98011-H32122 | \$ 9,022.00 | 6% | <i>\$8,544.29</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H32123 | 98011-H32123 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32124 | 98011-H32124 | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWP Premier NBD ONSITE H32125 | 98011-H32125 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32126 | 98011-H32126 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32127 | 98011-H32127 | \$ 3,881.00 | 6% | <i>\$3,675.50</i> |
| EWP Premier NBD ONSITE H32128 | 98011-H32128 | \$ 3,881.00 | 6% | <i>\$3,675.50</i> |
| EWP Premier NBD ONSITE H32129 | 98011-H32129 | \$ 3,881.00 | 6% | <i>\$3,675.50</i> |
| EWP Premier NBD ONSITE H32130 | 98011-H32130 | \$ 3,881.00 | 6% | <i>\$3,675.50</i> |
| EWP Premier NBD ONSITE H32131 | 98011-H32131 | \$ 3,881.00 | 6% | <i>\$3,675.50</i> |
| EWP Premier NBD ONSITE H32132 | 98011-H32132 | \$ 3,881.00 | 6% | <i>\$3,675.50</i> |
| EWP Premier NBD ONSITE H32133 | 98011-H32133 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32134 | 98011-H32134 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32135 | 98011-H32135 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32136 | 98011-H32136 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32137 | 98011-H32137 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32138 | 98011-H32138 | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWP Premier NBD ONSITE H32139 | 98011-H32139 | \$ 13,943.00 | 6% | <i>\$13,204.72</i> |
| EWP Premier NBD ONSITE H32140 | 98011-H32140 | \$ 13,943.00 | 6% | <i>\$13,204.72</i> |
| EWP Premier NBD ONSITE H32141 | 98011-H32141 | \$ 16,086.00 | 6% | <i>\$15,234.25</i> |
| EWP Premier NBD ONSITE H32142 | 98011-H32142 | \$ 16,086.00 | 6% | <i>\$15,234.25</i> |
| EWP Premier NBD ONSITE H32146 | 98011-H32146 | \$ 1,585.00 | 6% | <i>\$1,501.07</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H32147 | 98011-H32147 | \$ 1,585.00 | 6% | <i>\$1,501.07</i> |
| EWP Premier NBD ONSITE H32148 | 98011-H32148 | \$ 3,160.00 | 6% | <i>\$2,992.68</i> |
| EWP Premier NBD ONSITE H32149 | 98011-H32149 | \$ 3,160.00 | 6% | <i>\$2,992.68</i> |
| EWP Premier NBD ONSITE H32150 | 98011-H32150 | \$ 1,585.00 | 6% | <i>\$1,501.07</i> |
| EWP Premier NBD ONSITE H32169 | 98011-H32169 | \$ 1,660.00 | 6% | <i>\$1,572.10</i> |
| EWP Premier NBD ONSITE H32170 | 98011-H32170 | \$ 1,660.00 | 6% | <i>\$1,572.10</i> |
| EWP Premier NBD ONSITE H32171 | 98011-H32171 | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWP Premier NBD ONSITE H32172 | 98011-H32172 | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWP Premier NBD ONSITE H32173 | 98011-H32173 | \$ 4,139.00 | 6% | <i>\$3,919.84</i> |
| EWP Premier NBD ONSITE H32174 | 98011-H32174 | \$ 4,139.00 | 6% | <i>\$3,919.84</i> |
| EWP Premier NBD ONSITE H32175 | 98011-H32175 | \$ 3,516.00 | 6% | <i>\$3,329.83</i> |
| EWP Premier NBD ONSITE H32176 | 98011-H32176 | \$ 3,516.00 | 6% | <i>\$3,329.83</i> |
| EWP Premier NBD ONSITE H32177 | 98011-H32177 | \$ 16,119.00 | 6% | <i>\$15,265.50</i> |
| EWP Premier NBD ONSITE H32178 | 98011-H32178 | \$ 18,601.00 | 6% | <i>\$17,616.08</i> |
| EWP Premier NBD ONSITE H34008 | 98011-H34008 | \$ 51.00 | 6% | <i>\$48.30</i> |
| EWP Premier NBD ONSITE H34009 | 98011-H34009 | \$ 136.00 | 6% | <i>\$128.80</i> |
| EWP Premier NBD ONSITE H34010 | 98011-H34010 | \$ 57.00 | 6% | <i>\$53.98</i> |
| EWP Premier NBD ONSITE H34011 | 98011-H34011 | \$ 118.00 | 6% | <i>\$111.75</i> |
| EWP Premier NBD ONSITE H34012 | 98011-H34012 | \$ 221.00 | 6% | <i>\$209.30</i> |
| EWP Premier NBD ONSITE H34013 | 98011-H34013 | \$ 86.00 | 6% | <i>\$81.45</i> |
| EWP Premier NBD ONSITE H34014 | 98011-H34014 | \$ 136.00 | 6% | <i>\$128.80</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34015 | 98011-H34015 | \$ 71.00 | 6% | <i>\$67.24</i> |
| EWP Premier NBD ONSITE H34016 | 98011-H34016 | \$ 151.00 | 6% | <i>\$143.00</i> |
| EWP Premier NBD ONSITE H34017 | 98011-H34017 | \$ 255.00 | 6% | <i>\$241.50</i> |
| EWP Premier NBD ONSITE H34018 | 98011-H34018 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34019 | 98011-H34019 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34020 | 98011-H34020 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34021 | 98011-H34021 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34048 | 98011-H34048 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWP Premier NBD ONSITE H34049 | 98011-H34049 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWP Premier NBD ONSITE H34050 | 98011-H34050 | \$ 305.00 | 6% | <i>\$288.85</i> |
| EWP Premier NBD ONSITE H34051 | 98011-H34051 | \$ 305.00 | 6% | <i>\$288.85</i> |
| EWP Premier NBD ONSITE H34052 | 98011-H34052 | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWP Premier NBD ONSITE H34053 | 98011-H34053 | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWP Premier NBD ONSITE H34054 | 98011-H34054 | \$ 361.00 | 6% | <i>\$341.89</i> |
| EWP Premier NBD ONSITE H34055 | 98011-H34055 | \$ 361.00 | 6% | <i>\$341.89</i> |
| EWP Premier NBD ONSITE H34056 | 98011-H34056 | \$ 524.00 | 6% | <i>\$496.25</i> |
| EWP Premier NBD ONSITE H34057 | 98011-H34057 | \$ 524.00 | 6% | <i>\$496.25</i> |
| EWP Premier NBD ONSITE H34058 | 98011-H34058 | \$ 448.00 | 6% | <i>\$424.28</i> |
| EWP Premier NBD ONSITE H34059 | 98011-H34059 | \$ 448.00 | 6% | <i>\$424.28</i> |
| EWP Premier NBD ONSITE H34062 | 98011-H34062 | \$ 524.00 | 6% | <i>\$496.25</i> |
| EWP Premier NBD ONSITE H34063 | 98011-H34063 | \$ 524.00 | 6% | <i>\$496.25</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD ONSITE H34064 | 98011-H34064 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD ONSITE H34065 | 98011-H34065 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD ONSITE H34066 | 98011-H34066 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD ONSITE H34067 | 98011-H34067 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD ONSITE H34068 | 98011-H34068 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD ONSITE H34069 | 98011-H34069 | \$ 308.00 | 6% | \$291.69 |
| EWP Premier NBD ONSITE H34070 | 98011-H34070 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD ONSITE H34071 | 98011-H34071 | \$ 311.00 | 6% | \$294.53 |
| EWP Premier NBD ONSITE H34072 | 98011-H34072 | \$ 2,986.00 | 6% | \$2,827.89 |
| EWP Premier NBD ONSITE H34073 | 98011-H34073 | \$ 2,931.00 | 6% | \$2,775.80 |
| EWP Premier NBD ONSITE H34074 | 98011-H34074 | \$ 3,749.00 | 6% | \$3,550.49 |
| EWP Premier NBD ONSITE H34075 | 98011-H34075 | \$ 3,594.00 | 6% | \$3,403.70 |
| EWP Premier NBD ONSITE H34076 | 98011-H34076 | \$ 2,986.00 | 6% | \$2,827.89 |
| EWP Premier NBD ONSITE H34077 | 98011-H34077 | \$ 2,931.00 | 6% | \$2,775.80 |
| EWP Premier NBD ONSITE H34078 | 98011-H34078 | \$ 2,986.00 | 6% | \$2,827.89 |
| EWP Premier NBD ONSITE H34079 | 98011-H34079 | \$ 2,931.00 | 6% | \$2,775.80 |
| EWP Premier NBD ONSITE H34080 | 98011-H34080 | \$ 3,749.00 | 6% | \$3,550.49 |
| EWP Premier NBD ONSITE H34081 | 98011-H34081 | \$ 3,594.00 | 6% | \$3,403.70 |
| EWP Premier NBD ONSITE H34082 | 98011-H34082 | \$ 3,578.00 | 6% | \$3,388.54 |
| EWP Premier NBD ONSITE H34083 | 98011-H34083 | \$ 3,430.00 | 6% | \$3,248.38 |
| EWP Premier NBD ONSITE H34084 | 98011-H34084 | \$ 2,552.00 | 6% | \$2,416.87 |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H34085 | 98011-H34085 | \$ 2,552.00 | 6% | <i>\$2,416.87</i> |
| EWP Premier NBD ONSITE H34086 | 98011-H34086 | \$ 2,985.00 | 6% | <i>\$2,826.94</i> |
| EWP Premier NBD ONSITE H34087 | 98011-H34087 | \$ 2,850.00 | 6% | <i>\$2,699.09</i> |
| EWP Premier NBD ONSITE H34088 | 98011-H34088 | \$ 6,414.00 | 6% | <i>\$6,074.38</i> |
| EWP Premier NBD ONSITE H34089 | 98011-H34089 | \$ 6,414.00 | 6% | <i>\$6,074.38</i> |
| EWP Premier NBD ONSITE H34090 | 98011-H34090 | \$ 7,387.00 | 6% | <i>\$6,995.86</i> |
| EWP Premier NBD ONSITE H34091 | 98011-H34091 | \$ 4,418.00 | 6% | <i>\$4,184.07</i> |
| EWP Premier NBD ONSITE H34092 | 98011-H34092 | \$ 4,418.00 | 6% | <i>\$4,184.07</i> |
| EWP Premier NBD ONSITE H34093 | 98011-H34093 | \$ 4,418.00 | 6% | <i>\$4,184.07</i> |
| EWP Premier NBD ONSITE H34094 | 98011-H34094 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34095 | 98011-H34095 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34096 | 98011-H34096 | \$ 572.00 | 6% | <i>\$541.71</i> |
| EWP Premier NBD ONSITE H34097 | 98011-H34097 | \$ 572.00 | 6% | <i>\$541.71</i> |
| EWP Premier NBD ONSITE H34098 | 98011-H34098 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34099 | 98011-H34099 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34100 | 98011-H34100 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34101 | 98011-H34101 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34102 | 98011-H34102 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34103 | 98011-H34103 | \$ 510.00 | 6% | <i>\$483.00</i> |
| EWP Premier NBD ONSITE H34104 | 98011-H34104 | \$ 225.00 | 6% | <i>\$213.09</i> |
| EWP Premier NBD ONSITE H34105 | 98011-H34105 | \$ 225.00 | 6% | <i>\$213.09</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H34106 | 98011-H34106 | \$ 225.00 | 6% | <i>\$213.09</i> |
| EWP Premier NBD ONSITE H34107 | 98011-H34107 | \$ 225.00 | 6% | <i>\$213.09</i> |
| EWP Premier NBD ONSITE H34108 | 98011-H34108 | \$ 225.00 | 6% | <i>\$213.09</i> |
| EWP Premier NBD ONSITE H34109 | 98011-H34109 | \$ 225.00 | 6% | <i>\$213.09</i> |
| EWP Premier NBD ONSITE H34110 | 98011-H34110 | \$ 4,236.00 | 6% | <i>\$4,011.70</i> |
| EWP Premier NBD ONSITE H34111 | 98011-H34111 | \$ 4,236.00 | 6% | <i>\$4,011.70</i> |
| EWP Premier NBD ONSITE H34112 | 98011-H34112 | \$ 4,236.00 | 6% | <i>\$4,011.70</i> |
| EWP Premier NBD ONSITE H34114 | 98011-H34114 | \$ 5,561.00 | 6% | <i>\$5,266.55</i> |
| EWP Premier NBD ONSITE H34115 | 98011-H34115 | \$ 5,561.00 | 6% | <i>\$5,266.55</i> |
| EWP Premier NBD ONSITE H34116 | 98011-H34116 | \$ 5,561.00 | 6% | <i>\$5,266.55</i> |
| EWP Premier NBD ONSITE H34117 | 98011-H34117 | \$ 5,561.00 | 6% | <i>\$5,266.55</i> |
| EWP Premier NBD ONSITE H34118 | 98011-H34118 | \$ 1,407.00 | 6% | <i>\$1,332.50</i> |
| EWP Premier NBD ONSITE H34119 | 98011-H34119 | \$ 1,407.00 | 6% | <i>\$1,332.50</i> |
| EWP Premier NBD ONSITE H34120 | 98011-H34120 | \$ 968.00 | 6% | <i>\$916.74</i> |
| EWP Premier NBD ONSITE H34121 | 98011-H34121 | \$ 968.00 | 6% | <i>\$916.74</i> |
| EWP Premier NBD ONSITE H34122 | 98011-H34122 | \$ 1,009.00 | 6% | <i>\$955.57</i> |
| EWP Premier NBD ONSITE H34123 | 98011-H34123 | \$ 1,009.00 | 6% | <i>\$955.57</i> |
| EWP Premier NBD ONSITE H34124 | 98011-H34124 | \$ 1,500.00 | 6% | <i>\$1,420.58</i> |
| EWP Premier NBD ONSITE H34125 | 98011-H34125 | \$ 1,500.00 | 6% | <i>\$1,420.58</i> |
| EWP Premier NBD ONSITE H34126 | 98011-H34126 | \$ 1,500.00 | 6% | <i>\$1,420.58</i> |
| EWP Premier NBD ONSITE H34127 | 98011-H34127 | \$ 1,500.00 | 6% | <i>\$1,420.58</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD ONSITE H34128 | 98011-H34128 | \$ 245.00 | 6% | \$232.03 |
| EWP Premier NBD ONSITE H34129 | 98011-H34129 | \$ 449.00 | 6% | \$425.23 |
| EWP Premier NBD ONSITE H34130 | 98011-H34130 | \$ 467.00 | 6% | \$442.27 |
| EWP Premier NBD ONSITE H34131 | 98011-H34131 | \$ 467.00 | 6% | \$442.27 |
| EWP Premier NBD ONSITE H34132 | 98011-H34132 | \$ 467.00 | 6% | \$442.27 |
| EWP Premier NBD ONSITE H34172 | 98011-H34172 | \$ 2,011.00 | 6% | \$1,904.52 |
| EWP Premier NBD ONSITE H34174 | 98011-H34174 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34175 | 98011-H34175 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34176 | 98011-H34176 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34177 | 98011-H34177 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34178 | 98011-H34178 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34179 | 98011-H34179 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34180 | 98011-H34180 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34181 | 98011-H34181 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34182 | 98011-H34182 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34183 | 98011-H34183 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34184 | 98011-H34184 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34185 | 98011-H34185 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34186 | 98011-H34186 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34187 | 98011-H34187 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34188 | 98011-H34188 | \$ 62.00 | 6% | \$58.72 |

| | | | | |
|----------------------------------|--------------|----------|----|---------|
| EWP Premier NBD ONSITE H34189 | 98011-H34189 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34190 | 98011-H34190 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34191 | 98011-H34191 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34192 | 98011-H34192 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34193 | 98011-H34193 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34194 | 98011-H34194 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34195 | 98011-H34195 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34196 | 98011-H34196 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34197 | 98011-H34197 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34198 | 98011-H34198 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34199 | 98011-H34199 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34200 | 98011-H34200 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34201 | 98011-H34201 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34202 | 98011-H34202 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34203 | 98011-H34203 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34204 | 98011-H34204 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34205 | 98011-H34205 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34206 | 98011-H34206 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34207 | 98011-H34207 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34208 | 98011-H34208 | \$ 62.00 | 6% | \$58.72 |
| EWP Premier NBD ONSITE H34209 | 98011-H34209 | \$ 62.00 | 6% | \$58.72 |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34210 | 98011-H34210 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34211 | 98011-H34211 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34212 | 98011-H34212 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34213 | 98011-H34213 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34214 | 98011-H34214 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34215 | 98011-H34215 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34216 | 98011-H34216 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34217 | 98011-H34217 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34218 | 98011-H34218 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34219 | 98011-H34219 | \$ 62.00 | 6% | <i>\$58.72</i> |
| EWP Premier NBD ONSITE H34220 | 98011-H34220 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34221 | 98011-H34221 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34222 | 98011-H34222 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34223 | 98011-H34223 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34224 | 98011-H34224 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34225 | 98011-H34225 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34226 | 98011-H34226 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34227 | 98011-H34227 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34228 | 98011-H34228 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34229 | 98011-H34229 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34230 | 98011-H34230 | \$ 85.00 | 6% | <i>\$80.50</i> |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34231 | 98011-H34231 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34232 | 98011-H34232 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34233 | 98011-H34233 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34234 | 98011-H34234 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34235 | 98011-H34235 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34236 | 98011-H34236 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34237 | 98011-H34237 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34238 | 98011-H34238 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34239 | 98011-H34239 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34240 | 98011-H34240 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34241 | 98011-H34241 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34242 | 98011-H34242 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34243 | 98011-H34243 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34244 | 98011-H34244 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34245 | 98011-H34245 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34246 | 98011-H34246 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34247 | 98011-H34247 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34248 | 98011-H34248 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34249 | 98011-H34249 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34250 | 98011-H34250 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34251 | 98011-H34251 | \$ 85.00 | 6% | <i>\$80.50</i> |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34252 | 98011-H34252 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34253 | 98011-H34253 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34254 | 98011-H34254 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34255 | 98011-H34255 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34256 | 98011-H34256 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34257 | 98011-H34257 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34258 | 98011-H34258 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34259 | 98011-H34259 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34260 | 98011-H34260 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34261 | 98011-H34261 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34262 | 98011-H34262 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34263 | 98011-H34263 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34264 | 98011-H34264 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34265 | 98011-H34265 | \$ 85.00 | 6% | <i>\$80.50</i> |
| EWP Premier NBD ONSITE H34266 | 98011-H34266 | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD ONSITE H34267 | 98011-H34267 | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD ONSITE H34268 | 98011-H34268 | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD ONSITE H34269 | 98011-H34269 | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD ONSITE H34270 | 98011-H34270 | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD ONSITE H34271 | 98011-H34271 | \$ 59.00 | 6% | <i>\$55.88</i> |
| EWP Premier NBD ONSITE H34272 | 98011-H34272 | \$ 59.00 | 6% | <i>\$55.88</i> |

| | | | | |
|----------------------------------|--------------|----------|----|---------|
| EWP Premier NBD ONSITE H34273 | 98011-H34273 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34274 | 98011-H34274 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34275 | 98011-H34275 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34276 | 98011-H34276 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34277 | 98011-H34277 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34278 | 98011-H34278 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34279 | 98011-H34279 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34280 | 98011-H34280 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34281 | 98011-H34281 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34282 | 98011-H34282 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34283 | 98011-H34283 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34284 | 98011-H34284 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34285 | 98011-H34285 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34286 | 98011-H34286 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34287 | 98011-H34287 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34288 | 98011-H34288 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34289 | 98011-H34289 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34290 | 98011-H34290 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34291 | 98011-H34291 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34292 | 98011-H34292 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34293 | 98011-H34293 | \$ 59.00 | 6% | \$55.88 |

| | | | | |
|----------------------------------|--------------|----------|----|---------|
| EWP Premier NBD ONSITE H34294 | 98011-H34294 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34295 | 98011-H34295 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34296 | 98011-H34296 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34297 | 98011-H34297 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34298 | 98011-H34298 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34299 | 98011-H34299 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34300 | 98011-H34300 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34301 | 98011-H34301 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34302 | 98011-H34302 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34303 | 98011-H34303 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34304 | 98011-H34304 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34305 | 98011-H34305 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H34306 | 98011-H34306 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34307 | 98011-H34307 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34308 | 98011-H34308 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34309 | 98011-H34309 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34310 | 98011-H34310 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34311 | 98011-H34311 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34312 | 98011-H34312 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34313 | 98011-H34313 | \$ 91.00 | 6% | \$86.18 |
| EWP Premier NBD ONSITE H34314 | 98011-H34314 | \$ 91.00 | 6% | \$86.18 |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34315 | 98011-H34315 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34316 | 98011-H34316 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34317 | 98011-H34317 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34318 | 98011-H34318 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34319 | 98011-H34319 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34320 | 98011-H34320 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34321 | 98011-H34321 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34322 | 98011-H34322 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34323 | 98011-H34323 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34324 | 98011-H34324 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34325 | 98011-H34325 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34326 | 98011-H34326 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34327 | 98011-H34327 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34328 | 98011-H34328 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34329 | 98011-H34329 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34330 | 98011-H34330 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34331 | 98011-H34331 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34332 | 98011-H34332 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34333 | 98011-H34333 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34334 | 98011-H34334 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34335 | 98011-H34335 | \$ 91.00 | 6% | <i>\$86.18</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34336 | 98011-H34336 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34337 | 98011-H34337 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34338 | 98011-H34338 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34339 | 98011-H34339 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34340 | 98011-H34340 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34341 | 98011-H34341 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34342 | 98011-H34342 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34343 | 98011-H34343 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34344 | 98011-H34344 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34345 | 98011-H34345 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34346 | 98011-H34346 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34347 | 98011-H34347 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34348 | 98011-H34348 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34349 | 98011-H34349 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34350 | 98011-H34350 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34351 | 98011-H34351 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34352 | 98011-H34352 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34353 | 98011-H34353 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34354 | 98011-H34354 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34355 | 98011-H34355 | \$ 91.00 | 6% | <i>\$86.18</i> |
| EWP Premier NBD ONSITE H34403 | 98011-H34403 | \$ 223.00 | 6% | <i>\$211.19</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34404 | 98011-H34404 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34405 | 98011-H34405 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34406 | 98011-H34406 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34407 | 98011-H34407 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34408 | 98011-H34408 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34409 | 98011-H34409 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34410 | 98011-H34410 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34411 | 98011-H34411 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34412 | 98011-H34412 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34413 | 98011-H34413 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34414 | 98011-H34414 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34415 | 98011-H34415 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34416 | 98011-H34416 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34417 | 98011-H34417 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34418 | 98011-H34418 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34419 | 98011-H34419 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34420 | 98011-H34420 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34421 | 98011-H34421 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34422 | 98011-H34422 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34423 | 98011-H34423 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34424 | 98011-H34424 | \$ 223.00 | 6% | <i>\$211.19</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34425 | 98011-H34425 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34426 | 98011-H34426 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34427 | 98011-H34427 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34428 | 98011-H34428 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34429 | 98011-H34429 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34430 | 98011-H34430 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34431 | 98011-H34431 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34432 | 98011-H34432 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34433 | 98011-H34433 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34434 | 98011-H34434 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34435 | 98011-H34435 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34436 | 98011-H34436 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34437 | 98011-H34437 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34438 | 98011-H34438 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34439 | 98011-H34439 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34440 | 98011-H34440 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34441 | 98011-H34441 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34442 | 98011-H34442 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34443 | 98011-H34443 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34444 | 98011-H34444 | \$ 223.00 | 6% | <i>\$211.19</i> |
| EWP Premier NBD ONSITE H34445 | 98011-H34445 | \$ 223.00 | 6% | <i>\$211.19</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|----------|
| EWP Premier NBD ONSITE H34446 | 98011-H34446 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34447 | 98011-H34447 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34448 | 98011-H34448 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34449 | 98011-H34449 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34450 | 98011-H34450 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34451 | 98011-H34451 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34452 | 98011-H34452 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34453 | 98011-H34453 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34454 | 98011-H34454 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34455 | 98011-H34455 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34456 | 98011-H34456 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34457 | 98011-H34457 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34458 | 98011-H34458 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34459 | 98011-H34459 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34460 | 98011-H34460 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34461 | 98011-H34461 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34462 | 98011-H34462 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34463 | 98011-H34463 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34464 | 98011-H34464 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34465 | 98011-H34465 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34466 | 98011-H34466 | \$ 259.00 | 6% | \$245.29 |

| | | | | |
|----------------------------------|--------------|-----------|----|----------|
| EWP Premier NBD ONSITE H34467 | 98011-H34467 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34468 | 98011-H34468 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34469 | 98011-H34469 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34470 | 98011-H34470 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34471 | 98011-H34471 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34472 | 98011-H34472 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34473 | 98011-H34473 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34474 | 98011-H34474 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34475 | 98011-H34475 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34476 | 98011-H34476 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34477 | 98011-H34477 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34478 | 98011-H34478 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34479 | 98011-H34479 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34480 | 98011-H34480 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34481 | 98011-H34481 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34482 | 98011-H34482 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34483 | 98011-H34483 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34484 | 98011-H34484 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34485 | 98011-H34485 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34486 | 98011-H34486 | \$ 259.00 | 6% | \$245.29 |
| EWP Premier NBD ONSITE H34487 | 98011-H34487 | \$ 259.00 | 6% | \$245.29 |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34488 | 98011-H34488 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier NBD ONSITE H34489 | 98011-H34489 | \$ 259.00 | 6% | <i>\$245.29</i> |
| EWP Premier NBD ONSITE H34490 | 98011-H34490 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34491 | 98011-H34491 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34492 | 98011-H34492 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34493 | 98011-H34493 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34494 | 98011-H34494 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34495 | 98011-H34495 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34496 | 98011-H34496 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34497 | 98011-H34497 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34498 | 98011-H34498 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34499 | 98011-H34499 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34500 | 98011-H34500 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34501 | 98011-H34501 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34502 | 98011-H34502 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34503 | 98011-H34503 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34504 | 98011-H34504 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34505 | 98011-H34505 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34506 | 98011-H34506 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34507 | 98011-H34507 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34508 | 98011-H34508 | \$ 37.00 | 6% | <i>\$35.04</i> |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34509 | 98011-H34509 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34510 | 98011-H34510 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34511 | 98011-H34511 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34512 | 98011-H34512 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34513 | 98011-H34513 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34514 | 98011-H34514 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34515 | 98011-H34515 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34516 | 98011-H34516 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34517 | 98011-H34517 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34518 | 98011-H34518 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34519 | 98011-H34519 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34520 | 98011-H34520 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34521 | 98011-H34521 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34522 | 98011-H34522 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34523 | 98011-H34523 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34524 | 98011-H34524 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34525 | 98011-H34525 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34526 | 98011-H34526 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34527 | 98011-H34527 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34528 | 98011-H34528 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34529 | 98011-H34529 | \$ 37.00 | 6% | <i>\$35.04</i> |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34530 | 98011-H34530 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34531 | 98011-H34531 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34532 | 98011-H34532 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34533 | 98011-H34533 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34534 | 98011-H34534 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34535 | 98011-H34535 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34536 | 98011-H34536 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34537 | 98011-H34537 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34538 | 98011-H34538 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34539 | 98011-H34539 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34540 | 98011-H34540 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34541 | 98011-H34541 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34542 | 98011-H34542 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34543 | 98011-H34543 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34544 | 98011-H34544 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34545 | 98011-H34545 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34546 | 98011-H34546 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34547 | 98011-H34547 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34548 | 98011-H34548 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34549 | 98011-H34549 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34550 | 98011-H34550 | \$ 37.00 | 6% | <i>\$35.04</i> |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34551 | 98011-H34551 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34552 | 98011-H34552 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34553 | 98011-H34553 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34554 | 98011-H34554 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34555 | 98011-H34555 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34556 | 98011-H34556 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34557 | 98011-H34557 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34558 | 98011-H34558 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34559 | 98011-H34559 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34560 | 98011-H34560 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34561 | 98011-H34561 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34562 | 98011-H34562 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34563 | 98011-H34563 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34564 | 98011-H34564 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34565 | 98011-H34565 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34566 | 98011-H34566 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34567 | 98011-H34567 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34568 | 98011-H34568 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34569 | 98011-H34569 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34570 | 98011-H34570 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34571 | 98011-H34571 | \$ 37.00 | 6% | <i>\$35.04</i> |

| | | | | |
|----------------------------------|--------------|----------|----|----------------|
| EWP Premier NBD ONSITE H34572 | 98011-H34572 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34573 | 98011-H34573 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34574 | 98011-H34574 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34575 | 98011-H34575 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34576 | 98011-H34576 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34577 | 98011-H34577 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34578 | 98011-H34578 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34579 | 98011-H34579 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34580 | 98011-H34580 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34581 | 98011-H34581 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34582 | 98011-H34582 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34583 | 98011-H34583 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34584 | 98011-H34584 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34585 | 98011-H34585 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34586 | 98011-H34586 | \$ 37.00 | 6% | <i>\$35.04</i> |
| EWP Premier NBD ONSITE H34587 | 98011-H34587 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34588 | 98011-H34588 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34589 | 98011-H34589 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34590 | 98011-H34590 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34591 | 98011-H34591 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34592 | 98011-H34592 | \$ 99.00 | 6% | <i>\$93.76</i> |

| | | | | |
|----------------------------------|--------------|----------|----|---------|
| EWP Premier NBD ONSITE H34593 | 98011-H34593 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34594 | 98011-H34594 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34595 | 98011-H34595 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34596 | 98011-H34596 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34597 | 98011-H34597 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34598 | 98011-H34598 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34599 | 98011-H34599 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34600 | 98011-H34600 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34601 | 98011-H34601 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34602 | 98011-H34602 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34603 | 98011-H34603 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34604 | 98011-H34604 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34605 | 98011-H34605 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34606 | 98011-H34606 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34607 | 98011-H34607 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34608 | 98011-H34608 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34609 | 98011-H34609 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34610 | 98011-H34610 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34611 | 98011-H34611 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34612 | 98011-H34612 | \$ 99.00 | 6% | \$93.76 |
| EWP Premier NBD ONSITE H34613 | 98011-H34613 | \$ 99.00 | 6% | \$93.76 |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34614 | 98011-H34614 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34615 | 98011-H34615 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34616 | 98011-H34616 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34617 | 98011-H34617 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34618 | 98011-H34618 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34619 | 98011-H34619 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34620 | 98011-H34620 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34621 | 98011-H34621 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34622 | 98011-H34622 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34623 | 98011-H34623 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34624 | 98011-H34624 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34625 | 98011-H34625 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34626 | 98011-H34626 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34627 | 98011-H34627 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34628 | 98011-H34628 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34629 | 98011-H34629 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34630 | 98011-H34630 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34631 | 98011-H34631 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H34632 | 98011-H34632 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34633 | 98011-H34633 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34634 | 98011-H34634 | \$ 106.00 | 6% | <i>\$100.39</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34635 | 98011-H34635 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34636 | 98011-H34636 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34637 | 98011-H34637 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34638 | 98011-H34638 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34639 | 98011-H34639 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34640 | 98011-H34640 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34641 | 98011-H34641 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34642 | 98011-H34642 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34643 | 98011-H34643 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34644 | 98011-H34644 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34645 | 98011-H34645 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34646 | 98011-H34646 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34647 | 98011-H34647 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34648 | 98011-H34648 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34649 | 98011-H34649 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34650 | 98011-H34650 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34651 | 98011-H34651 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34652 | 98011-H34652 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34653 | 98011-H34653 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34654 | 98011-H34654 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34655 | 98011-H34655 | \$ 106.00 | 6% | <i>\$100.39</i> |

| | | | | |
|----------------------------------|--------------|-----------|----|-----------------|
| EWP Premier NBD ONSITE H34656 | 98011-H34656 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34657 | 98011-H34657 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34658 | 98011-H34658 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34659 | 98011-H34659 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34660 | 98011-H34660 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34661 | 98011-H34661 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34662 | 98011-H34662 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34663 | 98011-H34663 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34664 | 98011-H34664 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34665 | 98011-H34665 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34666 | 98011-H34666 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34667 | 98011-H34667 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34668 | 98011-H34668 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34669 | 98011-H34669 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34670 | 98011-H34670 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34671 | 98011-H34671 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34672 | 98011-H34672 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34673 | 98011-H34673 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34674 | 98011-H34674 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34675 | 98011-H34675 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34676 | 98011-H34676 | \$ 106.00 | 6% | <i>\$100.39</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H34677 | 98011-H34677 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34678 | 98011-H34678 | \$ 106.00 | 6% | <i>\$100.39</i> |
| EWP Premier NBD ONSITE H34726 | 98011-H34726 | \$ 3,110.00 | 6% | <i>\$2,945.33</i> |
| EWP Premier NBD ONSITE H34727 | 98011-H34727 | \$ 3,110.00 | 6% | <i>\$2,945.33</i> |
| EWP Premier NBD ONSITE H34728 | 98011-H34728 | \$ 3,110.00 | 6% | <i>\$2,945.33</i> |
| EWP Premier NBD ONSITE H34729 | 98011-H34729 | \$ 3,110.00 | 6% | <i>\$2,945.33</i> |
| EWP Premier NBD ONSITE H34730 | 98011-H34730 | \$ 3,331.00 | 6% | <i>\$3,154.62</i> |
| EWP Premier NBD ONSITE H34731 | 98011-H34731 | \$ 3,331.00 | 6% | <i>\$3,154.62</i> |
| EWP Premier NBD ONSITE H34732 | 98011-H34732 | \$ 3,331.00 | 6% | <i>\$3,154.62</i> |
| EWP Premier NBD ONSITE H34733 | 98011-H34733 | \$ 3,331.00 | 6% | <i>\$3,154.62</i> |
| EWP Premier NBD ONSITE H34734 | 98011-H34734 | \$ 484.00 | 6% | <i>\$458.37</i> |
| EWP Premier NBD ONSITE H34735 | 98011-H34735 | \$ 484.00 | 6% | <i>\$458.37</i> |
| EWP Premier NBD ONSITE H34736 | 98011-H34736 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34737 | 98011-H34737 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34738 | 98011-H34738 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34739 | 98011-H34739 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34740 | 98011-H34740 | \$ 484.00 | 6% | <i>\$458.37</i> |
| EWP Premier NBD ONSITE H34741 | 98011-H34741 | \$ 484.00 | 6% | <i>\$458.37</i> |
| EWP Premier NBD ONSITE H34742 | 98011-H34742 | \$ 348.00 | 6% | <i>\$329.57</i> |
| EWP Premier NBD ONSITE H34743 | 98011-H34743 | \$ 348.00 | 6% | <i>\$329.57</i> |
| EWP Premier NBD ONSITE H34744 | 98011-H34744 | \$ 614.00 | 6% | <i>\$581.49</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H34745 | 98011-H34745 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34746 | 98011-H34746 | \$ 696.00 | 6% | <i>\$659.15</i> |
| EWP Premier NBD ONSITE H34747 | 98011-H34747 | \$ 696.00 | 6% | <i>\$659.15</i> |
| EWP Premier NBD ONSITE H34748 | 98011-H34748 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34749 | 98011-H34749 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34750 | 98011-H34750 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34751 | 98011-H34751 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34752 | 98011-H34752 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34753 | 98011-H34753 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34754 | 98011-H34754 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34755 | 98011-H34755 | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWP Premier NBD ONSITE H34756 | 98011-H34756 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34757 | 98011-H34757 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34758 | 98011-H34758 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34759 | 98011-H34759 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34760 | 98011-H34760 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34761 | 98011-H34761 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H34839 | 98011-H34839 | \$ 343.00 | 6% | <i>\$324.84</i> |
| EWP Premier NBD ONSITE H34840 | 98011-H34840 | \$ 343.00 | 6% | <i>\$324.84</i> |
| EWP Premier NBD ONSITE H34841 | 98011-H34841 | \$ 343.00 | 6% | <i>\$324.84</i> |
| EWP Premier NBD ONSITE H34842 | 98011-H34842 | \$ 343.00 | 6% | <i>\$324.84</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|-------------|
| EWP Premier NBD ONSITE H34843 | 98011-H34843 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD ONSITE H34844 | 98011-H34844 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD ONSITE H34845 | 98011-H34845 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD ONSITE H34846 | 98011-H34846 | \$ 343.00 | 6% | \$324.84 |
| EWP Premier NBD ONSITE H34993 | 98011-H34993 | \$ 15,215.00 | 6% | \$14,409.37 |
| EWP Premier NBD ONSITE H34994 | 98011-H34994 | \$ 15,215.00 | 6% | \$14,409.37 |
| EWP Premier NBD ONSITE H34996 | 98011-H34996 | \$ 15,215.00 | 6% | \$14,409.37 |
| EWP Premier NBD ONSITE H34997 | 98011-H34997 | \$ 15,215.00 | 6% | \$14,409.37 |
| EWP Premier NBD ONSITE H35005 | 98011-H35005 | \$ 11,303.00 | 6% | \$10,704.51 |
| EWP Premier NBD ONSITE H35006 | 98011-H35006 | \$ 11,303.00 | 6% | \$10,704.51 |
| EWP Premier NBD ONSITE H35012 | 98011-H35012 | \$ 6,799.00 | 6% | \$6,438.99 |
| EWP Premier NBD ONSITE H35070 | 98011-H35070 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35071 | 98011-H35071 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35072 | 98011-H35072 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35073 | 98011-H35073 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35074 | 98011-H35074 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35075 | 98011-H35075 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35076 | 98011-H35076 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35077 | 98011-H35077 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35078 | 98011-H35078 | \$ 59.00 | 6% | \$55.88 |
| EWP Premier NBD ONSITE H35079 | 98011-H35079 | \$ 59.00 | 6% | \$55.88 |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H35080 | 98011-H35080 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H35081 | 98011-H35081 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H35082 | 98011-H35082 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H35083 | 98011-H35083 | \$ 99.00 | 6% | <i>\$93.76</i> |
| EWP Premier NBD ONSITE H35270 | 98011-H35270 | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWP Premier NBD ONSITE H35271 | 98011-H35271 | \$ 361.00 | 6% | <i>\$341.89</i> |
| EWP Premier NBD ONSITE H35273 | 98011-H35273 | \$ 295.00 | 6% | <i>\$279.38</i> |
| EWP Premier NBD ONSITE H35274 | 98011-H35274 | \$ 696.00 | 6% | <i>\$659.15</i> |
| EWP Premier NBD ONSITE H35275 | 98011-H35275 | \$ 524.00 | 6% | <i>\$496.25</i> |
| EWP Premier NBD ONSITE H35276 | 98011-H35276 | \$ 2,986.00 | 6% | <i>\$2,827.89</i> |
| EWP Premier NBD ONSITE H35277 | 98011-H35277 | \$ 3,578.00 | 6% | <i>\$3,388.54</i> |
| EWP Premier NBD ONSITE H35278 | 98011-H35278 | \$ 2,552.00 | 6% | <i>\$2,416.87</i> |
| EWP Premier NBD ONSITE H35279 | 98011-H35279 | \$ 2,850.00 | 6% | <i>\$2,699.09</i> |
| EWP Premier NBD ONSITE H35280 | 98011-H35280 | \$ 4,157.00 | 6% | <i>\$3,936.89</i> |
| EWP Premier NBD ONSITE H35281 | 98011-H35281 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |
| EWP Premier NBD ONSITE H35282 | 98011-H35282 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |
| EWP Premier NBD ONSITE H35283 | 98011-H35283 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |
| EWP Premier NBD ONSITE H35284 | 98011-H35284 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |
| EWP Premier NBD ONSITE H35285 | 98011-H35285 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |
| EWP Premier NBD ONSITE H35286 | 98011-H35286 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |
| EWP Premier NBD ONSITE H35287 | 98011-H35287 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |

| | | | | |
|----------------------------------|--------------|--------------|----|--------------------|
| EWP Premier NBD ONSITE H35288 | 98011-H35288 | \$ 2,186.00 | 6% | <i>\$2,070.25</i> |
| EWP Premier NBD ONSITE H35289 | 98011-H35289 | \$ 5,457.00 | 6% | <i>\$5,168.05</i> |
| EWP Premier NBD ONSITE H35291 | 98011-H35291 | \$ 3,931.00 | 6% | <i>\$3,722.85</i> |
| EWP Premier NBD ONSITE H35294 | 98011-H35294 | \$ 1,096.00 | 6% | <i>\$1,037.97</i> |
| EWP Premier NBD ONSITE H35295 | 98011-H35295 | \$ 427.00 | 6% | <i>\$404.39</i> |
| EWP Premier NBD ONSITE H35296 | 98011-H35296 | \$ 8,580.00 | 6% | <i>\$8,125.69</i> |
| EWP Premier NBD ONSITE H35297 | 98011-H35297 | \$ 8,580.00 | 6% | <i>\$8,125.69</i> |
| EWP Premier NBD ONSITE H35298 | 98011-H35298 | \$ 13,782.00 | 6% | <i>\$13,052.24</i> |
| EWP Premier NBD ONSITE H35299 | 98011-H35299 | \$ 13,782.00 | 6% | <i>\$13,052.24</i> |
| EWP Premier NBD ONSITE H35302 | 98011-H35302 | \$ 3,355.00 | 6% | <i>\$3,177.35</i> |
| EWP Premier NBD ONSITE H35303 | 98011-H35303 | \$ 3,355.00 | 6% | <i>\$3,177.35</i> |
| EWP Premier NBD ONSITE H35304 | 98011-H35304 | \$ 3,355.00 | 6% | <i>\$3,177.35</i> |
| EWP Premier NBD ONSITE H35305 | 98011-H35305 | \$ 3,518.00 | 6% | <i>\$3,331.72</i> |
| EWP Premier NBD ONSITE H35306 | 98011-H35306 | \$ 3,518.00 | 6% | <i>\$3,331.72</i> |
| EWP Premier NBD ONSITE H35307 | 98011-H35307 | \$ 3,518.00 | 6% | <i>\$3,331.72</i> |
| EWP Premier NBD ONSITE H35309 | 98011-H35309 | \$ 3,938.00 | 6% | <i>\$3,729.48</i> |
| EWP Premier NBD ONSITE H35310 | 98011-H35310 | \$ 3,938.00 | 6% | <i>\$3,729.48</i> |
| EWP Premier NBD ONSITE H35311 | 98011-H35311 | \$ 3,938.00 | 6% | <i>\$3,729.48</i> |
| EWP Premier NBD ONSITE H35312 | 98011-H35312 | \$ 3,256.00 | 6% | <i>\$3,083.59</i> |
| EWP Premier NBD ONSITE H35313 | 98011-H35313 | \$ 3,256.00 | 6% | <i>\$3,083.59</i> |
| EWP Premier NBD ONSITE H35314 | 98011-H35314 | \$ 3,256.00 | 6% | <i>\$3,083.59</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H35315 | 98011-H35315 | \$ 1,429.00 | 6% | <i>\$1,353.33</i> |
| EWP Premier NBD ONSITE H35318 | 98011-H35318 | \$ 687.00 | 6% | <i>\$650.62</i> |
| EWP Premier NBD ONSITE H35319 | 98011-H35319 | \$ 910.00 | 6% | <i>\$861.82</i> |
| EWP Premier NBD ONSITE H35320 | 98011-H35320 | \$ 960.00 | 6% | <i>\$909.17</i> |
| EWP Premier NBD ONSITE H35321 | 98011-H35321 | \$ 1,202.00 | 6% | <i>\$1,138.35</i> |
| EWP Premier NBD ONSITE H35322 | 98011-H35322 | \$ 1,457.00 | 6% | <i>\$1,379.85</i> |
| EWP Premier NBD ONSITE H35323 | 98011-H35323 | \$ 1,429.00 | 6% | <i>\$1,353.33</i> |
| EWP Premier NBD ONSITE H35328 | 98011-H35328 | \$ 124.00 | 6% | <i>\$117.43</i> |
| EWP Premier NBD ONSITE H35330 | 98011-H35330 | \$ 87.00 | 6% | <i>\$82.39</i> |
| EWP Premier NBD ONSITE H35340 | 98011-H35340 | \$ 3,633.00 | 6% | <i>\$3,440.63</i> |
| EWP Premier NBD ONSITE H35341 | 98011-H35341 | \$ 3,633.00 | 6% | <i>\$3,440.63</i> |
| EWP Premier NBD ONSITE H35342 | 98011-H35342 | \$ 3,060.00 | 6% | <i>\$2,897.97</i> |
| EWP Premier NBD ONSITE H35343 | 98011-H35343 | \$ 3,633.00 | 6% | <i>\$3,440.63</i> |
| EWP Premier NBD ONSITE H35344 | 98011-H35344 | \$ 3,752.00 | 6% | <i>\$3,553.33</i> |
| EWP Premier NBD ONSITE H35345 | 98011-H35345 | \$ 3,752.00 | 6% | <i>\$3,553.33</i> |
| EWP Premier NBD ONSITE H35346 | 98011-H35346 | \$ 3,148.00 | 6% | <i>\$2,981.31</i> |
| EWP Premier NBD ONSITE H35347 | 98011-H35347 | \$ 3,752.00 | 6% | <i>\$3,553.33</i> |
| EWP Premier NBD ONSITE H35349 | 98011-H35349 | \$ 4,037.00 | 6% | <i>\$3,823.24</i> |
| EWP Premier NBD ONSITE H35350 | 98011-H35350 | \$ 4,038.00 | 6% | <i>\$3,824.19</i> |
| EWP Premier NBD ONSITE H35351 | 98011-H35351 | \$ 3,377.00 | 6% | <i>\$3,198.19</i> |
| EWP Premier NBD ONSITE H35352 | 98011-H35352 | \$ 4,038.00 | 6% | <i>\$3,824.19</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H35359 | 98011-H35359 | \$ 1,202.00 | 6% | <i>\$1,138.35</i> |
| EWP Premier NBD ONSITE H35360 | 98011-H35360 | \$ 1,457.00 | 6% | <i>\$1,379.85</i> |
| EWP Premier NBD ONSITE H35361 | 98011-H35361 | \$ 1,429.00 | 6% | <i>\$1,353.33</i> |
| EWP Premier NBD ONSITE H35362 | 98011-H35362 | \$ 687.00 | 6% | <i>\$650.62</i> |
| EWP Premier NBD ONSITE H35366 | 98011-H35366 | \$ 2,571.00 | 6% | <i>\$2,434.87</i> |
| EWP Premier NBD ONSITE H35367 | 98011-H35367 | \$ 2,998.00 | 6% | <i>\$2,839.26</i> |
| EWP Premier NBD ONSITE H35368 | 98011-H35368 | \$ 4,571.00 | 6% | <i>\$4,328.97</i> |
| EWP Premier NBD ONSITE H35369 | 98011-H35369 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| EWP Premier NBD ONSITE H35370 | 98011-H35370 | \$ 2,084.00 | 6% | <i>\$1,973.65</i> |
| EWP Premier NBD ONSITE H35375 | 98011-H35375 | \$ 1,264.00 | 6% | <i>\$1,197.07</i> |
| EWP Premier NBD ONSITE H35376 | 98011-H35376 | \$ 1,899.00 | 6% | <i>\$1,798.45</i> |
| EWP Premier NBD ONSITE H35377 | 98011-H35377 | \$ 792.00 | 6% | <i>\$750.06</i> |
| EWP Premier NBD ONSITE H35378 | 98011-H35378 | \$ 1,264.00 | 6% | <i>\$1,197.07</i> |
| EWP Premier NBD ONSITE H35379 | 98011-H35379 | \$ 792.00 | 6% | <i>\$750.06</i> |
| EWP Premier NBD ONSITE H35380 | 98011-H35380 | \$ 1,427.00 | 6% | <i>\$1,351.44</i> |
| EWP Premier NBD ONSITE H35381 | 98011-H35381 | \$ 1,738.00 | 6% | <i>\$1,645.97</i> |
| EWP Premier NBD ONSITE H35384 | 98011-H35384 | \$ 570.00 | 6% | <i>\$539.82</i> |
| EWP Premier NBD ONSITE H35385 | 98011-H35385 | \$ 758.00 | 6% | <i>\$717.86</i> |
| EWP Premier NBD ONSITE H35386 | 98011-H35386 | \$ 1,264.00 | 6% | <i>\$1,197.07</i> |
| EWP Premier NBD ONSITE H35387 | 98011-H35387 | \$ 1,183.00 | 6% | <i>\$1,120.36</i> |
| EWP Premier NBD ONSITE H35388 | 98011-H35388 | \$ 868.00 | 6% | <i>\$822.04</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H35389 | 98011-H35389 | \$ 491.00 | 6% | <i>\$465.00</i> |
| EWP Premier NBD ONSITE H35390 | 98011-H35390 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWP Premier NBD ONSITE H35391 | 98011-H35391 | \$ 933.00 | 6% | <i>\$883.60</i> |
| EWP Premier NBD ONSITE H35392 | 98011-H35392 | \$ 1,427.00 | 6% | <i>\$1,351.44</i> |
| EWP Premier NBD ONSITE H35393 | 98011-H35393 | \$ 1,899.00 | 6% | <i>\$1,798.45</i> |
| EWP Premier NBD ONSITE H35394 | 98011-H35394 | \$ 343.00 | 6% | <i>\$324.84</i> |
| EWP Premier NBD ONSITE H35395 | 98011-H35395 | \$ 286.00 | 6% | <i>\$270.86</i> |
| EWP Premier NBD ONSITE H35396 | 98011-H35396 | \$ 343.00 | 6% | <i>\$324.84</i> |
| EWP Premier NBD ONSITE H35397 | 98011-H35397 | \$ 286.00 | 6% | <i>\$270.86</i> |
| EWP Premier NBD ONSITE H35398 | 98011-H35398 | \$ 887.00 | 6% | <i>\$840.03</i> |
| EWP Premier NBD ONSITE H35399 | 98011-H35399 | \$ 1,077.00 | 6% | <i>\$1,019.97</i> |
| EWP Premier NBD ONSITE H35400 | 98011-H35400 | \$ 1,187.00 | 6% | <i>\$1,124.15</i> |
| EWP Premier NBD ONSITE H35401 | 98011-H35401 | \$ 636.00 | 6% | <i>\$602.32</i> |
| EWP Premier NBD ONSITE H35415 | 98011-H35415 | \$ 426.00 | 6% | <i>\$403.44</i> |
| EWP Premier NBD ONSITE H35416 | 98011-H35416 | \$ 426.00 | 6% | <i>\$403.44</i> |
| EWP Premier NBD ONSITE H35426 | 98011-H35426 | \$ 491.00 | 6% | <i>\$465.00</i> |
| EWP Premier NBD ONSITE H35427 | 98011-H35427 | \$ 1,183.00 | 6% | <i>\$1,120.36</i> |
| EWP Premier NBD ONSITE H35428 | 98011-H35428 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWP Premier NBD ONSITE H35429 | 98011-H35429 | \$ 933.00 | 6% | <i>\$883.60</i> |
| EWP Premier NBD ONSITE H35430 | 98011-H35430 | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWP Premier NBD ONSITE H35431 | 98011-H35431 | \$ 461.00 | 6% | <i>\$436.59</i> |

| | | | | |
|----------------------------------|--------------|-------------|----|------------|
| EWP Premier NBD ONSITE H35432 | 98011-H35432 | \$ 348.00 | 6% | \$329.57 |
| EWP Premier NBD ONSITE H35433 | 98011-H35433 | \$ 585.00 | 6% | \$554.02 |
| EWP Premier NBD ONSITE H35434 | 98011-H35434 | \$ 663.00 | 6% | \$627.89 |
| EWP Premier NBD ONSITE H35435 | 98011-H35435 | \$ 663.00 | 6% | \$627.89 |
| EWP Premier NBD ONSITE H35436 | 98011-H35436 | \$ 1,106.00 | 6% | \$1,047.44 |
| EWP Premier NBD ONSITE H35437 | 98011-H35437 | \$ 1,106.00 | 6% | \$1,047.44 |
| EWP Premier NBD ONSITE H35438 | 98011-H35438 | \$ 1,106.00 | 6% | \$1,047.44 |
| EWP Premier NBD ONSITE H35439 | 98011-H35439 | \$ 1,106.00 | 6% | \$1,047.44 |
| EWP Premier NBD ONSITE H35440 | 98011-H35440 | \$ 585.00 | 6% | \$554.02 |
| EWP Premier NBD ONSITE H35441 | 98011-H35441 | \$ 585.00 | 6% | \$554.02 |
| EWP Premier NBD ONSITE H35442 | 98011-H35442 | \$ 585.00 | 6% | \$554.02 |
| EWP Premier NBD ONSITE H35443 | 98011-H35443 | \$ 3,110.00 | 6% | \$2,945.33 |
| EWP Premier NBD ONSITE H35444 | 98011-H35444 | \$ 3,331.00 | 6% | \$3,154.62 |
| EWP Premier NBD ONSITE H35445 | 98011-H35445 | \$ 2,986.00 | 6% | \$2,827.89 |
| EWP Premier NBD ONSITE H35446 | 98011-H35446 | \$ 2,931.00 | 6% | \$2,775.80 |
| EWP Premier NBD ONSITE H35447 | 98011-H35447 | \$ 3,408.00 | 6% | \$3,227.55 |
| EWP Premier NBD ONSITE H35448 | 98011-H35448 | \$ 3,267.00 | 6% | \$3,094.01 |
| EWP Premier NBD ONSITE H35449 | 98011-H35449 | \$ 2,552.00 | 6% | \$2,416.87 |
| EWP Premier NBD ONSITE H35450 | 98011-H35450 | \$ 2,714.00 | 6% | \$2,570.29 |
| EWP Premier NBD ONSITE H35451 | 98011-H35451 | \$ 4,418.00 | 6% | \$4,184.07 |
| EWP Premier NBD ONSITE H35452 | 98011-H35452 | \$ 4,418.00 | 6% | \$4,184.07 |

| | | | | |
|---|---------------------------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE H35453 | 98011-H35453 | \$ 3,331.00 | 6% | <i>\$3,154.62</i> |
| EWP Premier NBD ONSITE H35454 | 98011-H35454 | \$ 3,110.00 | 6% | <i>\$2,945.33</i> |
| EWP Premier NBD ONSITE H35455 | 98011-H35455 | \$ 960.00 | 6% | <i>\$909.17</i> |
| EWP Premier NBD ONSITE H35456 | 98011-H35456 | \$ 1,200.00 | 6% | <i>\$1,136.46</i> |
| EWP Premier NBD ONSITE H35457 | 98011-H35457 | \$ 1,077.00 | 6% | <i>\$1,019.97</i> |
| EWP Premier NBD ONSITE H35458 | 98011-H35458 | \$ 1,184.00 | 6% | <i>\$1,121.31</i> |
| EWP Premier NBD ONSITE H35471 | 98011-H35471 | \$ 960.00 | 6% | <i>\$909.17</i> |
| EWP Premier NBD ONSITE H35600 | 98011-H35600 | \$ 295.00 | 6% | <i>\$279.38</i> |
| EWP Premier NBD ONSITE H35601 | 98011-H35601 | \$ 295.00 | 6% | <i>\$279.38</i> |
| EWP Premier NBD ONSITE H35602 | 98011-H35602 | \$ 484.00 | 6% | <i>\$458.37</i> |
| EWP Premier NBD ONSITE H35603 | 98011-H35603 | \$ 484.00 | 6% | <i>\$458.37</i> |
| EWP Premier NBD ONSITE H35604 | 98011-H35604 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H35605 | 98011-H35605 | \$ 614.00 | 6% | <i>\$581.49</i> |
| EWP Premier NBD ONSITE H35606 | 98011-H35606 | \$ 696.00 | 6% | <i>\$659.15</i> |
| EWP Premier NBD ONSITE H35607 | 98011-H35607 | \$ 696.00 | 6% | <i>\$659.15</i> |
| EWP Premier NBD ONSITE ISW-24W-4X | 98011-ISW- 24W-4X | \$ 985.00 | 6% | <i>\$932.84</i> |
| EWP Premier NBD ONSITE ISW-4W-4WS-4X | 98011-ISW-4W- 4WS-4X | \$ 625.00 | 6% | <i>\$591.91</i> |
| EWP Premier NBD ONSITE MSM128 | 98011- MSM128 | \$ 3,531.00 | 6% | <i>\$3,344.03</i> |
| EWP Premier NBD ONSITE MSM48C | 98011- MSM48C | \$ 2,096.00 | 6% | <i>\$1,985.02</i> |
| EWP Premier NBD ONSITE SLX9150-48XT-DC-F | 98011- SLX9150- 48XT-DC-F | \$ 3,241.00 | 6% | <i>\$3,069.39</i> |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EWP Premier NBD ONSITE SLX9150-48XT-DC-R | 98011- SLX9150- 48XT-DC-R | \$ 3,573.00 | 6% | <i>\$3,383.81</i> |
| EWP Premier NBD ONSITE SLX9150-48Y-DC-F | 98011- SLX9150-48Y- DC-F | \$ 3,139.00 | 6% | <i>\$2,972.79</i> |
| EWP Premier NBD ONSITE SLX9150-48Y-DC-R | 98011- SLX9150-48Y- DC-R | \$ 3,461.00 | 6% | <i>\$3,277.74</i> |
| EWP Premier NBD ONSITE SLX9740-40C | 98011- SLX9740-40C | \$ 14,783.00 | 6% | <i>\$14,000.24</i> |
| EWP Premier NBD ONSITE SLX9740-40C-AC-F | 98011- SLX9740-40C- AC-F | \$ 14,783.00 | 6% | <i>\$14,000.24</i> |
| EWP Premier NBD ONSITE SLX9740-40C-AC-R | 98011- SLX9740-40C- AC-R | \$ 14,783.00 | 10% | <i>\$13,404.49</i> |
| EWP Premier NBD ONSITE SLX9740-40C-DC-F | 98011- SLX9740-40C- DC-F | \$ 14,783.00 | 6% | <i>\$14,000.24</i> |
| EWP Premier NBD ONSITE SLX9740-80C | 98011- SLX9740-80C | \$ 27,799.00 | 6% | <i>\$26,327.04</i> |
| EWP Premier NBD ONSITE SLX9740-80C-AC-F | 98011- SLX9740-80C- AC-F | \$ 27,799.00 | 6% | <i>\$26,327.04</i> |
| EWP Premier NBD ONSITE SLX9740-80C-AC-R | 98011- SLX9740-80C- AC-R | \$ 27,799.00 | 10% | <i>\$25,206.74</i> |
| EWP Premier NBD ONSITE SLX9740-80C-DC-F | 98011- SLX9740-80C- DC-F | \$ 27,799.00 | 6% | <i>\$26,327.04</i> |
| EWP Premier NBD ONSITE V300-8P-2X | 98011-V300- 8P-2X | \$ 161.00 | 6% | <i>\$152.48</i> |
| EWP Premier NBD ONSITE V300-8T-2X | 98011-V300- 8T-2X | \$ 111.00 | 6% | <i>\$105.12</i> |
| EWP Premier NBD ONSITE V300HT-8P-2X | 98011-V300HT- 8P-2X | \$ 501.00 | 6% | <i>\$474.47</i> |
| EWP Premier NBD ONSITE V300HT-8T-2X | 98011-V300HT- 8T-2X | \$ 299.00 | 6% | <i>\$283.17</i> |
| EWP Premier NBD ONSITE VIM-SS | 98011-VIM-SS | \$ 183.00 | 6% | <i>\$173.31</i> |

| | | | | |
|---|---|-------------|----|-------------------|
| EWPPremier NBD ONSITE VIM-SSV8 | 98011-VIM- SSV80 | \$ 338.00 | 6% | <i>\$320.10</i> |
| EWP Premier NBD ONSITE VIM2-SS | 98011-VIM2- SS | \$ 211.00 | 6% | <i>\$199.83</i> |
| EWPPremier NBD ONSITE VIM2-SS1 | 98011-VIM2- SS128 | \$ 729.00 | 6% | <i>\$690.40</i> |
| EWPPremier NBD ONSITE VIM2-V80 | 98011-VIM2- V80 | \$ 779.00 | 6% | <i>\$737.75</i> |
| EWPPremier NBD ONSITE VIM210G4 | 98011- VIM210G4X | \$ 1,352.00 | 6% | <i>\$1,280.41</i> |
| EWP Premier NBD ONSITE VIM5-2Q | 98011-VIM5- 2Q | \$ 231.00 | 6% | <i>\$218.77</i> |
| EWP Premier NBD ONSITE VIM5-2Y | 98011-VIM5- 2Y | \$ 273.00 | 6% | <i>\$258.54</i> |
| EWP Premier NBD ONSITE VIM5-4X | 98011-VIM5- 4X | \$ 121.00 | 6% | <i>\$114.59</i> |
| EWP Premier NBD ONSITE VIM5-4XE | 98011-VIM5- 4XE | \$ 225.00 | 6% | <i>\$213.09</i> |
| EWP Premier NBD ONSITE VIM5-4Y | 98011-VIM5- 4Y | \$ 349.00 | 6% | <i>\$330.52</i> |
| EWP Premier NBD ONSITE VIM5-4YE | 98011-VIM5- 4YE | \$ 450.00 | 6% | <i>\$426.17</i> |
| EWP Prem NBD ONSIT VSP4900-12MXU-12XE | 98011- VSP4900- 12MXU-12XE | \$ 1,261.00 | 6% | <i>\$1,194.23</i> |
| EWP Prem NBD ONSIT VSP4900-12MXU-12XE-B1 | 98011- VSP4900- 12MXU-12XE- B1 | \$ 1,261.00 | 6% | <i>\$1,194.23</i> |
| EWP Premier NBD ONSITE VSP4900-24S | 98011- VSP4900-24S | \$ 687.00 | 6% | <i>\$650.62</i> |
| EWP Premier NBD ONSITE VSP4900-24S-B3 | 98011- VSP4900-24S- B3 | \$ 687.00 | 6% | <i>\$650.62</i> |
| EWP Premier NBD ONSITE VSP4900-24XE | 98011- VSP4900- 24XE | \$ 1,261.00 | 6% | <i>\$1,194.23</i> |
| EWP Premier NBD ONSITE VSP4900-24XE-B3 | 98011- VSP4900- 24XE-B3 | \$ 1,261.00 | 6% | <i>\$1,194.23</i> |
| EWP Premier NBD ONSITE X435-24P-4S | 98011-X435- 24P-4S | \$ 288.00 | 6% | <i>\$272.75</i> |

| | | | | |
|--|------------------------|-------------|----|-------------------|
| EWP Premier NBD ONSITE X435-24T-4S | 98011-X435- 24T-4S | \$ 159.00 | 6% | <i>\$150.58</i> |
| EWP Premier NBD ONSITE X435-8P-2T-W | 98011-X435- 8P-2T-W | \$ 159.00 | 6% | <i>\$150.58</i> |
| EWP Premier NBD ONSITE X435-8P-4S | 98011-X435- 8P-4S | \$ 144.00 | 6% | <i>\$136.38</i> |
| EWP Premier NBD ONSITE X435-8T-4S | 98011-X435- 8T-4S | \$ 114.00 | 6% | <i>\$107.96</i> |
| EWPPremier NBD ONSITE X460-24P | 98011-X460- 24P | \$ 1,211.00 | 6% | <i>\$1,146.88</i> |
| EWPPremier NBD ONSITE X460-24T | 98011-X460- 24T | \$ 875.00 | 6% | <i>\$828.67</i> |
| EWPPremier NBD ONSITE X460-24T | 98011-X460- 24TDC | \$ 1,278.00 | 6% | <i>\$1,210.33</i> |
| EWPPremier NBD ONSITE X460-24X | 98011-X460- 24X | \$ 1,608.00 | 6% | <i>\$1,522.86</i> |
| EWPPremier NBD ONSITE X460-24X | 98011-X460- 24XDC | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWPPremier NBD ONSITE X460-48P | 98011-X460- 48P | \$ 1,608.00 | 6% | <i>\$1,522.86</i> |
| EWPPremier NBD ONSITE X460-48T | 98011-X460- 48T | \$ 1,381.00 | 6% | <i>\$1,307.88</i> |
| EWPPremier NBD ONSITE X460-48T | 98011-X460- 48TDC | \$ 1,740.00 | 6% | <i>\$1,647.87</i> |
| EWPPremier NBD ONSITE X460-48X | 98011-X460- 48X | \$ 2,143.00 | 6% | <i>\$2,029.53</i> |
| EWPPremier NBD ONSITE X460-48X | 98011-X460- 48XDC | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWP Premier NBD ONSITE X465-24MU | 98011-X465- 24MU | \$ 1,457.00 | 6% | <i>\$1,379.85</i> |
| EWP Premier NBD ONSITE X465-24S | 98011-X465- 24S | \$ 687.00 | 6% | <i>\$650.62</i> |
| EWP Premier NBD ONSITE X465-24S-B3 | 98011-X465- 24S-B3 | \$ 687.00 | 6% | <i>\$650.62</i> |
| EWP Premier NBD ONSITE X465-24W | 98011-X465- 24W | \$ 687.00 | 6% | <i>\$650.62</i> |
| EWP Premier NBD ONSITE X465-24XE | 98011-X465- 24XE | \$ 1,261.00 | 6% | <i>\$1,194.23</i> |
| EWP Premier NBD ONSITE X465-24XE-B3 | 98011-X465- 24XE-B3 | \$ 1,261.00 | 6% | <i>\$1,194.23</i> |
| EWP Premier NBD ONSITE X465-48P | 98011-X465- 48P | \$ 960.00 | 6% | <i>\$909.17</i> |

| | | | | |
|--|--------------------------------|-------------|-----|-------------------|
| EWP Premier NBD ONSITE X465-48T | 98011-X465- 48T | \$ 910.00 | 6% | <i>\$861.82</i> |
| EWP Premier NBD ONSITE X465-48W | 98011-X465- 48W | \$ 1,202.00 | 6% | <i>\$1,138.35</i> |
| EWP Premier NBD ONSITE X465i-48W | 98011-X465i- 48W | \$ 1,429.00 | 6% | <i>\$1,353.33</i> |
| EWP Premier NBD ONSITE X465i-48W-B1-S1 | 98011-X465i- 48W-B1-S1 | \$ 1,429.00 | 6% | <i>\$1,353.33</i> |
| EWP Premier NBD ONSITE X465i-48W-B2-S1 | 98011-X465i- 48W-B2-S1 | \$ 1,429.00 | 6% | <i>\$1,353.33</i> |
| EWPPremier NBD ONSITE X480-24X | 98011-X480- 24X | \$ 2,021.00 | 6% | <i>\$1,913.99</i> |
| EWPPremier NBD ONSITE X480-48T | 98011-X480- 48T | \$ 2,021.00 | 6% | <i>\$1,913.99</i> |
| EWPPremier NBD ONSITE X480-48X | 98011-X480- 48X | \$ 2,690.00 | 6% | <i>\$2,547.56</i> |
| EWP Premier NBD ONSITE X695-48Y-8C | 98011-X695- 48Y-8C | \$ 3,346.00 | 6% | <i>\$3,168.83</i> |
| EWP Premier NBD ONSITE XA1440 | 98011-XA1440 | \$ 351.00 | 6% | <i>\$332.41</i> |
| EWP Premier NBD ONSITE XA1480 | 98011-XA1480 | \$ 469.00 | 6% | <i>\$444.17</i> |
| EWPPremier NBD ONSITE XGM3-2SF | 98011-XGM3- 2SF | \$ 338.00 | 6% | <i>\$320.10</i> |
| EWP Premier NBD ONSITE XR600 | 98011-XR600 | \$ 105.00 | 6% | <i>\$99.44</i> |
| EWP Premier NBD ONSITE XSW-BR-M-A-D | 98011-XSW- BR-M-A-D | \$ 191.00 | 10% | <i>\$173.19</i> |
| EWP Premier NBD ONSITE XSW-BR-M-A-D-3YR | 98011-XSW- BR-M-A-D- 3YR | \$ 574.00 | 10% | <i>\$520.47</i> |
| EWP Premier NBD ONSITE XSW-BR-M-A-D-5YR | 98011-XSW- BR-M-A-D- 5YR | \$ 957.00 | 10% | <i>\$867.76</i> |
| EWP Premier NBD ONSITE XSW-BR-S-A-D | 98011-XSW- BR-S-A-D | \$ 109.00 | 10% | <i>\$98.84</i> |
| EWP Premier NBD ONSITE XSW-BR-S-A-D-3YR | 98011-XSW- BR-S-A-D- 3YR | \$ 328.00 | 10% | <i>\$297.41</i> |
| EWP Premier NBD ONSITE XSW-BR-S-A-D-5YR | 98011-XSW- BR-S-A-D- 5YR | \$ 547.00 | 10% | <i>\$495.99</i> |

| | | | | |
|--|-------------------------------------|-------------|-----|-------------------|
| EWP Premier NBD ONSITE XSW-BR-XS-A-D | 98011-XSW- BR-XS-A-D | \$ 89.00 | 10% | <i>\$80.70</i> |
| EWP Premier NBD ONSITE XSW-BR-XS-A-D-3YR | 98011-XSW- BR-XS-A-D- 3YR | \$ 266.00 | 10% | <i>\$241.20</i> |
| EWP Premier NBD ONSITE XSW-BR-XS-A-D-5YR | 98011-XSW- BR-XS-A-D- 5YR | \$ 443.00 | 10% | <i>\$401.69</i> |
| EWP Premier NBD ONSITE XSW-DC-M-A-D | 98011-XSW- DC-M-A-D | \$ 711.00 | 10% | <i>\$644.70</i> |
| EWP Premier NBD ONSITE XSW-DC-M-A-D-3YR | 98011-XSW- DC-M-A-D- 3YR | \$ 2,132.00 | 10% | <i>\$1,933.19</i> |
| EWP Premier NBD ONSITE XSW-DC-M-A-D-5YR | 98011-XSW- DC-M-A-D- 5YR | \$ 3,554.00 | 10% | <i>\$3,222.59</i> |
| EWP Premier NBD ONSITE XSW-DC-S-A-D | 98011-XSW- DC-S-A-D | \$ 328.00 | 10% | <i>\$297.41</i> |
| EWP Premier NBD ONSITE XSW-DC-S-A-D-3YR | 98011-XSW- DC-S-A-D- 3YR | \$ 984.00 | 10% | <i>\$892.24</i> |
| EWP Premier NBD ONSITE XSW-DC-S-A-D-5YR | 98011-XSW- DC-S-A-D- 5YR | \$ 1,640.00 | 10% | <i>\$1,487.07</i> |
| EWP Premier NBD ONSITE XSW-DC-SR-L-A-D | 98011-XSW- DC-SR-L-A-D | \$ 820.00 | 10% | <i>\$743.54</i> |
| EWP Premier NBD OS XSW- DC-SR-L-A-D-3YR | 98011-XSW- DC-SR-L-A-D- 3YR | \$ 2,460.00 | 10% | <i>\$2,230.61</i> |
| EWP Premier NBD OS XSW- DC-SR-L-A-D-5YR | 98011-XSW- DC-SR-L-A-D- 5YR | \$ 4,101.00 | 10% | <i>\$3,718.58</i> |
| EWP Premier NBD ONSITE XSW-DCV2-LR-L-A-D | 98011-XSW- DCV2-LR-L-A- D | \$ 820.00 | 10% | <i>\$743.54</i> |
| EWP Premier NBD OS XSW- DCV2-LR-L-A-D-3YR | 98011-XSW- DCV2-LR-L-A- D-3YR | \$ 2,460.00 | 10% | <i>\$2,230.61</i> |
| EWP Premier NBD OS XSW- DCV2-LR-L-A-D-5YR | 98011-XSW- DCV2-LR-L-A- D-5YR | \$ 4,101.00 | 10% | <i>\$3,718.58</i> |
| EWP Premier NBD ONSITE XSW-DCV2-M-A-D | 98011-XSW- DCV2-M-A-D | \$ 711.00 | 10% | <i>\$644.70</i> |

| | | | | |
|--|-----------------------------|-------------|-----|------------|
| EWP Prem NBD ONSITE XSW-DCV2-M-A-D-3YR | 98011-XSW-DCV2-M-A-D-3YR | \$ 2,132.00 | 10% | \$1,933.19 |
| EWP Prem NBD ONSITE XSW-DCV2-M-A-D-5YR | 98011-XSW-DCV2-M-A-D-5YR | \$ 3,554.00 | 10% | \$3,222.59 |
| EWP Premier NBD ONSITE XSW-DCV2-SR-L-A-D | 98011-XSW-DCV2-SR-L-A-D | \$ 820.00 | 10% | \$743.54 |
| EWP Premier NBD OS XSW-DCV2-SR-L-A-D-3YR | 98011-XSW-DCV2-SR-L-A-D-3YR | \$ 2,460.00 | 10% | \$2,230.61 |
| EWP Premier NBD OS XSW-DCV2-SR-L-A-D-5YR | 98011-XSW-DCV2-SR-L-A-D-5YR | \$ 4,101.00 | 10% | \$3,718.58 |
| EWP Premier NBD ONSITE ZR-XFP | 98011-ZR-XFP | \$ 2,035.00 | 6% | \$1,927.25 |
| EWPP PremierPLS NBD AHR 1130C | 98504-1130C | \$ 2,720.00 | 6% | \$2,575.98 |
| EWPP PremierPLS NBD AHR 16119 | 98504-16119 | \$ 750.00 | 6% | \$710.29 |
| EWPP PremierPLS NBD AHR 16120 | 98504-16120 | \$ 830.00 | 6% | \$786.05 |
| EWPP PremierPLS NBD AHR 16126 | 98504-16126 | \$ 750.00 | 6% | \$710.29 |
| EWPP PremierPLS NBD AHR 16127 | 98504-16127 | \$ 785.00 | 6% | \$743.43 |
| EWPP PremierPLS NBD AHR 16172 | 98504-16172 | \$ 1,610.00 | 6% | \$1,524.75 |
| EWPP PremierPLS NBD AHR 16172T | 98504-16172T | \$ 1,720.00 | 6% | \$1,628.93 |
| EWPP PremierPLS NBD AHR 16173 | 98504-16173 | \$ 1,617.00 | 6% | \$1,531.38 |
| EWPP PremierPLS NBD AHR 16173T | 98504-16173T | \$ 1,736.00 | 6% | \$1,644.08 |
| EWPP PremierPLS NBD AHR 16174 | 98504-16174 | \$ 1,801.00 | 6% | \$1,705.64 |
| EWPP PremierPLS NBD AHR 16175 | 98504-16175 | \$ 1,832.00 | 6% | \$1,735.00 |
| EWPP PremierPLS NBD AHR 16176 | 98504-16176 | \$ 1,766.00 | 6% | \$1,672.49 |
| EWPP PremierPLS NBD AHR 16177 | 98504-16177 | \$ 1,665.00 | 6% | \$1,576.84 |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR 16177T | 98504-16177T | \$ 1,921.00 | 6% | <i>\$1,819.28</i> |
| EWPP PremierPLS NBD AHR 16178 | 98504-16178 | \$ 1,979.00 | 6% | <i>\$1,874.21</i> |
| EWPP PremierPLS NBD AHR 16179 | 98504-16179 | \$ 2,003.00 | 6% | <i>\$1,896.94</i> |
| EWPP PremierPLS NBD AHR 16179T | 98504-16179T | \$ 2,151.00 | 6% | <i>\$2,037.10</i> |
| EWPP PremierPLS NBD AHR 16301T | 98504-16301T | \$ 3,048.00 | 6% | <i>\$2,886.61</i> |
| EWPP PremierPLS NBD AHR 16303T | 98504-16303T | \$ 3,048.00 | 6% | <i>\$2,886.61</i> |
| EWPP PremierPLS NBD AHR 16304T | 98504-16304T | \$ 3,678.00 | 6% | <i>\$3,483.25</i> |
| EWPP PremierPLS NBD AHR 16401T | 98504-16401T | \$ 2,151.00 | 6% | <i>\$2,037.10</i> |
| EWPP PremierPLS NBD AHR 16402T | 98504-16402T | \$ 2,606.00 | 6% | <i>\$2,468.01</i> |
| EWPP PremierPLS NBD AHR 16403T | 98504-16403T | \$ 2,452.00 | 6% | <i>\$2,322.17</i> |
| EWPP PremierPLS NBD AHR 16404T | 98504-16404T | \$ 2,452.00 | 6% | <i>\$2,322.17</i> |
| EWPP PremierPLS NBD AHR 16405T | 98504-16405T | \$ 2,826.00 | 6% | <i>\$2,676.36</i> |
| EWPP PremierPLS NBD AHR 16406T | 98504-16406T | \$ 3,340.00 | 6% | <i>\$3,163.15</i> |
| EWPP PremierPLS NBD AHR 16431 | 98504-16431 | \$ 2,550.00 | 6% | <i>\$2,414.98</i> |
| EWPP PremierPLS NBD AHR 16432 | 98504-16432 | \$ 2,633.00 | 6% | <i>\$2,493.58</i> |
| EWPP PremierPLS NBD AHR 16440 | 98504-16440 | \$ 2,053.00 | 6% | <i>\$1,944.29</i> |
| EWPP PremierPLS NBD AHR 16441 | 98504-16441 | \$ 1,968.00 | 6% | <i>\$1,863.79</i> |
| EWPP PremierPLS NBD AHR 16442 | 98504-16442 | \$ 785.00 | 6% | <i>\$743.43</i> |
| EWPP PremierPLS NBD AHR 16444 | 98504-16444 | \$ 618.00 | 6% | <i>\$585.28</i> |
| EWPP PremierPLS NBD AHR 16501 | 98504-16501 | \$ 1,453.00 | 6% | <i>\$1,376.06</i> |
| EWPP PremierPLS NBD AHR 16501T | 98504-16501T | \$ 1,504.00 | 6% | <i>\$1,424.36</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR 16502 | 98504-16502 | \$ 1,543.00 | 6% | <i>\$1,461.30</i> |
| EWPP PremierPLS NBD AHR 16502T | 98504-16502T | \$ 1,593.00 | 6% | <i>\$1,508.65</i> |
| EWPP PremierPLS NBD AHR 16503 | 98504-16503 | \$ 1,491.00 | 6% | <i>\$1,412.05</i> |
| EWPP PremierPLS NBD AHR 16503T | 98504-16503T | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWPP PremierPLS NBD AHR 16504 | 98504-16504 | \$ 1,631.00 | 6% | <i>\$1,544.64</i> |
| EWPP PremierPLS NBD AHR 16504T | 98504-16504T | \$ 1,695.00 | 6% | <i>\$1,605.25</i> |
| EWPP PremierPLS NBD AHR 16505 | 98504-16505 | \$ 1,641.00 | 6% | <i>\$1,554.11</i> |
| EWPP PremierPLS NBD AHR 16505T | 98504-16505T | \$ 1,755.00 | 6% | <i>\$1,662.07</i> |
| EWPP PremierPLS NBD AHR 16506 | 98504-16506 | \$ 1,851.00 | 6% | <i>\$1,752.99</i> |
| EWPP PremierPLS NBD AHR 16506T | 98504-16506T | \$ 2,011.00 | 6% | <i>\$1,904.52</i> |
| EWPP PremierPLS NBD AHR 16507 | 98504-16507 | \$ 1,822.00 | 6% | <i>\$1,725.53</i> |
| EWPP PremierPLS NBD AHR 16507T | 98504-16507T | \$ 1,924.00 | 6% | <i>\$1,822.12</i> |
| EWPP PremierPLS NBD AHR 16508 | 98504-16508 | \$ 1,960.00 | 6% | <i>\$1,856.22</i> |
| EWPP PremierPLS NBD AHR 16508T | 98504-16508T | \$ 2,091.00 | 6% | <i>\$1,980.28</i> |
| EWPP PremierPLS NBD AHR 16509 | 98504-16509 | \$ 1,960.00 | 6% | <i>\$1,856.22</i> |
| EWPP PremierPLS NBD AHR 16509T | 98504-16509T | \$ 2,091.00 | 6% | <i>\$1,980.28</i> |
| EWPP PremierPLS NBD AHR 16510 | 98504-16510 | \$ 2,091.00 | 6% | <i>\$1,980.28</i> |
| EWPP PremierPLS NBD AHR 16510T | 98504-16510T | \$ 2,253.00 | 6% | <i>\$2,133.70</i> |
| EWPP PremierPLS NBD AHR 16513 | 98504-16513 | \$ 1,761.00 | 6% | <i>\$1,667.76</i> |
| EWPP PremierPLS NBD AHR 16514 | 98504-16514 | \$ 2,053.00 | 6% | <i>\$1,944.29</i> |
| EWPP PremierPLS NBD AHR 16515 | 98504-16515 | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR 16516 | 98504-16516 | \$ 1,373.00 | 6% | <i>\$1,300.30</i> |
| EWPP PremierPLS NBD AHR 16517 | 98504-16517 | \$ 1,520.00 | 6% | <i>\$1,439.52</i> |
| EWPP PremierPLS NBD AHR 16518 | 98504-16518 | \$ 1,485.00 | 6% | <i>\$1,406.37</i> |
| EWPP PremierPLS NBD AHR 16519 | 98504-16519 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR 16520 | 98504-16520 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR 16530 | 98504-16530 | \$ 1,505.00 | 6% | <i>\$1,425.31</i> |
| EWPP PremierPLS NBD AHR 16531 | 98504-16531 | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWPP PremierPLS NBD AHR 16531T | 98504-16531T | \$ 1,596.00 | 6% | <i>\$1,511.49</i> |
| EWPP PremierPLS NBD AHR 16532 | 98504-16532 | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWPP PremierPLS NBD AHR 16532T | 98504-16532T | \$ 1,596.00 | 6% | <i>\$1,511.49</i> |
| EWPP PremierPLS NBD AHR 16533 | 98504-16533 | \$ 1,650.00 | 6% | <i>\$1,562.63</i> |
| EWPP PremierPLS NBD AHR 16533T | 98504-16533T | \$ 1,711.00 | 6% | <i>\$1,620.40</i> |
| EWPP PremierPLS NBD AHR 16534 | 98504-16534 | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWPP PremierPLS NBD AHR 16535 | 98504-16535 | \$ 1,834.00 | 6% | <i>\$1,736.89</i> |
| EWPP PremierPLS NBD AHR 16535A | 98504-16535A | \$ 1,834.00 | 6% | <i>\$1,736.89</i> |
| EWPP PremierPLS NBD AHR 16535T | 98504-16535T | \$ 1,925.00 | 6% | <i>\$1,823.07</i> |
| EWPP PremierPLS NBD AHR 16536 | 98504-16536 | \$ 1,444.00 | 6% | <i>\$1,367.54</i> |
| EWPP PremierPLS NBD AHR 16537 | 98504-16537 | \$ 1,527.00 | 6% | <i>\$1,446.15</i> |
| EWPP PremierPLS NBD AHR 16538 | 98504-16538 | \$ 1,591.00 | 6% | <i>\$1,506.76</i> |
| EWPP PremierPLS NBD AHR 16538T | 98504-16538T | \$ 1,827.00 | 6% | <i>\$1,730.26</i> |
| EWPP PremierPLS NBD AHR 16539 | 98504-16539 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR 16540 | 98504-16540 | \$ 1,563.00 | 6% | <i>\$1,480.24</i> |
| EWPP PremierPLS NBD AHR 16541 | 98504-16541 | \$ 1,347.00 | 6% | <i>\$1,275.68</i> |
| EWPP PremierPLS NBD AHR 16560 | 98504-16560 | \$ 1,297.00 | 6% | <i>\$1,228.32</i> |
| EWPP PremierPLS NBD AHR 16561 | 98504-16561 | \$ 1,334.00 | 6% | <i>\$1,263.36</i> |
| EWPP PremierPLS NBD AHR 16562 | 98504-16562 | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |
| EWPP PremierPLS NBD AHR 16563 | 98504-16563 | \$ 1,410.00 | 6% | <i>\$1,335.34</i> |
| EWPP PremierPLS NBD AHR 16564 | 98504-16564 | \$ 1,452.00 | 6% | <i>\$1,375.12</i> |
| EWPP PremierPLS NBD AHR 16565 | 98504-16565 | \$ 1,570.00 | 6% | <i>\$1,486.87</i> |
| EWPP PremierPLS NBD AHR 16566 | 98504-16566 | \$ 1,272.00 | 6% | <i>\$1,204.65</i> |
| EWPP PremierPLS NBD AHR 16567 | 98504-16567 | \$ 1,318.00 | 6% | <i>\$1,248.21</i> |
| EWPP PremierPLS NBD AHR 16568 | 98504-16568 | \$ 1,298.00 | 6% | <i>\$1,229.27</i> |
| EWPP PremierPLS NBD AHR 16569 | 98504-16569 | \$ 1,347.00 | 6% | <i>\$1,275.68</i> |
| EWPP PremierPLS NBD AHR 16570 | 98504-16570 | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |
| EWPP PremierPLS NBD AHR 16571 | 98504-16571 | \$ 1,451.00 | 6% | <i>\$1,374.17</i> |
| EWPP PremierPLS NBD AHR 16701 | 98504-16701 | \$ 1,719.00 | 6% | <i>\$1,627.98</i> |
| EWPP PremierPLS NBD AHR 16702 | 98504-16702 | \$ 1,952.00 | 6% | <i>\$1,848.64</i> |
| EWPP PremierPLS NBD AHR 16703 | 98504-16703 | \$ 1,923.00 | 6% | <i>\$1,821.18</i> |
| EWPP PremierPLS NBD AHR 16703T | 98504-16703T | \$ 2,071.00 | 6% | <i>\$1,961.34</i> |
| EWPP PremierPLS NBD AHR 16704 | 98504-16704 | \$ 2,187.00 | 6% | <i>\$2,071.20</i> |
| EWPP PremierPLS NBD AHR 16704T | 98504-16704T | \$ 1,860.00 | 6% | <i>\$1,761.51</i> |
| EWPP PremierPLS NBD AHR 16705 | 98504-16705 | \$ 1,952.00 | 6% | <i>\$1,848.64</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR 16705T | 98504-16705T | \$ 2,109.00 | 6% | <i>\$1,997.33</i> |
| EWPP PremierPLS NBD AHR 16706 | 98504-16706 | \$ 2,452.00 | 6% | <i>\$2,322.17</i> |
| EWPP PremierPLS NBD AHR 16706T | 98504-16706T | \$ 2,657.00 | 6% | <i>\$2,516.31</i> |
| EWPP PremierPLS NBD AHR 16710 | 98504-16710 | \$ 643.00 | 6% | <i>\$608.95</i> |
| EWPP PremierPLS NBD AHR 16710T | 98504-16710T | \$ 699.00 | 6% | <i>\$661.99</i> |
| EWPP PremierPLS NBD AHR 16711 | 98504-16711 | \$ 518.00 | 6% | <i>\$490.57</i> |
| EWPP PremierPLS NBD AHR 16711T | 98504-16711T | \$ 552.00 | 6% | <i>\$522.77</i> |
| EWPP PremierPLS NBD AHR 16712 | 98504-16712 | \$ 549.00 | 6% | <i>\$519.93</i> |
| EWPP PremierPLS NBD AHR 16712T | 98504-16712T | \$ 578.00 | 6% | <i>\$547.39</i> |
| EWPP PremierPLS NBD AHR 16713 | 98504-16713 | \$ 484.00 | 6% | <i>\$458.37</i> |
| EWPP PremierPLS NBD AHR 16713T | 98504-16713T | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR 16715 | 98504-16715 | \$ 493.00 | 6% | <i>\$466.90</i> |
| EWPP PremierPLS NBD AHR 16715T | 98504-16715T | \$ 552.00 | 6% | <i>\$522.77</i> |
| EWPP PremierPLS NBD AHR 16716 | 98504-16716 | \$ 1,735.00 | 6% | <i>\$1,643.13</i> |
| EWPP PremierPLS NBD AHR 16716T | 98504-16716T | \$ 1,868.00 | 6% | <i>\$1,769.09</i> |
| EWPP PremierPLS NBD AHR 16717 | 98504-16717 | \$ 1,810.00 | 6% | <i>\$1,714.16</i> |
| EWPP PremierPLS NBD AHR 16718 | 98504-16718 | \$ 1,766.00 | 6% | <i>\$1,672.49</i> |
| EWPP PremierPLS NBD AHR 16719 | 98504-16719 | \$ 1,847.00 | 6% | <i>\$1,749.20</i> |
| EWPP PremierPLS NBD AHR 16720 | 98504-16720 | \$ 2,222.00 | 6% | <i>\$2,104.35</i> |
| EWPP PremierPLS NBD AHR 16720T | 98504-16720T | \$ 2,587.00 | 6% | <i>\$2,450.02</i> |
| EWPP PremierPLS NBD AHR 16756 | 98504-16756 | \$ 2,078.00 | 6% | <i>\$1,967.97</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR 16756T | 98504-16756T | \$ 2,453.00 | 6% | <i>\$2,323.11</i> |
| EWPP PremierPLS NBD AHR 16757 | 98504-16757 | \$ 2,037.00 | 6% | <i>\$1,929.14</i> |
| EWPP PremierPLS NBD AHR 16757T | 98504-16757T | \$ 2,407.00 | 6% | <i>\$2,279.55</i> |
| EWPP PremierPLS NBD AHR 16790 | 98504-16790 | \$ 2,128.00 | 6% | <i>\$2,015.32</i> |
| EWPP PremierPLS NBD AHR 16791 | 98504-16791 | \$ 2,747.00 | 6% | <i>\$2,601.55</i> |
| EWPP PremierPLS NBD AHR 17101 | 98504-17101 | \$ 3,919.00 | 6% | <i>\$3,711.49</i> |
| EWPP PremierPLS NBD AHR 17101T | 98504-17101T | \$ 4,786.00 | 6% | <i>\$4,532.58</i> |
| EWPP PremierPLS NBD AHR 17102 | 98504-17102 | \$ 3,919.00 | 6% | <i>\$3,711.49</i> |
| EWPP PremierPLS NBD AHR 17102T | 98504-17102T | \$ 4,786.00 | 6% | <i>\$4,532.58</i> |
| EWPP PremierPLS NBD AHR 17103 | 98504-17103 | \$ 3,069.00 | 6% | <i>\$2,906.50</i> |
| EWPP PremierPLS NBD AHR 17103C | 98504-17103C | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR 17103T | 98504-17103T | \$ 3,722.00 | 6% | <i>\$3,524.92</i> |
| EWPP PremierPLS NBD AHR 17104 | 98504-17104 | \$ 3,069.00 | 6% | <i>\$2,906.50</i> |
| EWPP PremierPLS NBD AHR 17104T | 98504-17104T | \$ 3,722.00 | 6% | <i>\$3,524.92</i> |
| EWPP PremierPLS NBD AHR 17121 | 98504-17121 | \$ 1,008.00 | 6% | <i>\$954.63</i> |
| EWPP PremierPLS NBD AHR 17122 | 98504-17122 | \$ 761.00 | 6% | <i>\$720.71</i> |
| EWPP PremierPLS NBD AHR 17200 | 98504-17200 | \$ 5,520.00 | 6% | <i>\$5,227.72</i> |
| EWPP PremierPLS NBD AHR 17200T | 98504-17200T | \$ 6,198.00 | 6% | <i>\$5,869.82</i> |
| EWPP PremierPLS NBD AHR 17201 | 98504-17201 | \$ 5,520.00 | 6% | <i>\$5,227.72</i> |
| EWPP PremierPLS NBD AHR 17201T | 98504-17201T | \$ 6,198.00 | 6% | <i>\$5,869.82</i> |
| EWPP PremierPLS NBD AHR 17202 | 98504-17202 | \$ 5,520.00 | 6% | <i>\$5,227.72</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS NBD AHR 17202T | 98504-17202T | \$ 6,198.00 | 6% | \$5,869.82 |
| EWPP PremierPLS NBD AHR 17203 | 98504-17203 | \$ 5,591.00 | 6% | \$5,294.96 |
| EWPP PremierPLS NBD AHR 17203T | 98504-17203T | \$ 6,272.00 | 6% | \$5,939.90 |
| EWPP PremierPLS NBD AHR 17204 | 98504-17204 | \$ 5,591.00 | 6% | \$5,294.96 |
| EWPP PremierPLS NBD AHR 17204T | 98504-17204T | \$ 6,272.00 | 6% | \$5,939.90 |
| EWPP PremierPLS NBD AHR 17205 | 98504-17205 | \$ 5,552.00 | 6% | \$5,258.02 |
| EWPP PremierPLS NBD AHR 17205T | 98504-17205T | \$ 6,232.00 | 6% | \$5,902.02 |
| EWPP PremierPLS NBD AHR 17206 | 98504-17206 | \$ 5,552.00 | 6% | \$5,258.02 |
| EWPP PremierPLS NBD AHR 17206T | 98504-17206T | \$ 6,232.00 | 6% | \$5,902.02 |
| EWPP PremierPLS NBD AHR 17300 | 98504-17300 | \$ 4,133.00 | 6% | \$3,914.16 |
| EWPP PremierPLS NBD AHR 17310 | 98504-17310 | \$ 3,862.00 | 6% | \$3,657.51 |
| EWPP PremierPLS NBD AHR 17350 | 98504-17350 | \$ 4,029.00 | 6% | \$3,815.66 |
| EWPP PremierPLS NBD AHR 17360 | 98504-17360 | \$ 4,682.00 | 6% | \$4,434.09 |
| EWPP PremierPLS NBD AHR 17401 | 98504-17401 | \$ 1,626.00 | 6% | \$1,539.90 |
| EWPP PremierPLS NBD AHR 17401G | 98504-17401G | \$ 1,717.00 | 6% | \$1,626.08 |
| EWPP PremierPLS NBD AHR 17401T | 98504-17401T | \$ 1,709.00 | 6% | \$1,618.51 |
| EWPP PremierPLS NBD AHR 17402 | 98504-17402 | \$ 1,705.00 | 6% | \$1,614.72 |
| EWPP PremierPLS NBD AHR 17402G | 98504-17402G | \$ 1,727.00 | 6% | \$1,635.56 |
| EWPP PremierPLS NBD AHR 17402T | 98504-17402T | \$ 1,716.00 | 6% | \$1,625.14 |
| EWPP PremierPLS NBD AHR 17403 | 98504-17403 | \$ 1,789.00 | 6% | \$1,694.27 |
| EWPP PremierPLS NBD AHR 17404 | 98504-17404 | \$ 1,515.00 | 6% | \$1,434.78 |

| | | | | |
|-----------------------------------|-----------------|--------------|----|-------------------|
| EWPP PremierPLS NBD AHR 17405 | 98504-17405 | \$ 1,506.00 | 6% | <i>\$1,426.26</i> |
| EWPP PremierPLS NBD AHR 17700 | 98504-17700 | \$ 6,473.00 | 6% | <i>\$6,130.25</i> |
| EWPP PremierPLS NBD AHR 17701 | 98504-17701 | \$ 5,597.00 | 6% | <i>\$5,300.64</i> |
| EWPP PremierPLS NBD AHR 17702 | 98504-17702 | \$ 5,597.00 | 6% | <i>\$5,300.64</i> |
| EWPP PremierPLS NBD AHR 17703 | 98504-17703 | \$ 6,107.00 | 6% | <i>\$5,783.63</i> |
| EWPP PremierPLS NBD AHR 17704 | 98504-17704 | \$ 6,107.00 | 6% | <i>\$5,783.63</i> |
| EWPP PremierPLS NBD AHR 17705 | 98504-17705 | \$ 5,626.00 | 6% | <i>\$5,328.10</i> |
| EWPP PremierPLS NBD AHR 17706 | 98504-17706 | \$ 5,626.00 | 6% | <i>\$5,328.10</i> |
| EWPP PremierPLS NBD AHR 17800 | 98504-17800 | \$ 6,714.00 | 6% | <i>\$6,358.49</i> |
| EWPP PremierPLS NBD AHR 17810 | 98504-17810 | \$ 5,614.00 | 6% | <i>\$5,316.74</i> |
| EWPP PremierPLS NBD AHR 18101 | 98504-18101 | \$ 664.00 | 6% | <i>\$628.84</i> |
| EWPP PremierPLS NBD AHR 18102 | 98504-18102 | \$ 743.00 | 6% | <i>\$703.66</i> |
| EWPP PremierPLS NBD AHR 18103 | 98504-18103 | \$ 777.00 | 6% | <i>\$735.86</i> |
| EWPP PremierPLS NBD AHR 18104 | 98504-18104 | \$ 941.00 | 6% | <i>\$891.17</i> |
| EWPP PremierPLS NBD AHR 18104-6PK | 98504-18104-6PK | \$ 5,641.00 | 6% | <i>\$5,342.31</i> |
| EWPP PremierPLS NBD AHR 30135 | 98504-30135 | \$ 2,827.00 | 6% | <i>\$2,677.31</i> |
| EWPP PremierPLS NBD AHR 30136 | 98504-30136 | \$ 6,552.00 | 6% | <i>\$6,205.07</i> |
| EWPP PremierPLS NBD AHR 30137 | 98504-30137 | \$ 2,784.00 | 6% | <i>\$2,636.59</i> |
| EWPP PremierPLS NBD AHR 30138 | 98504-30138 | \$ 6,416.00 | 6% | <i>\$6,076.27</i> |
| EWPP PremierPLS NBD AHR 30139 | 98504-30139 | \$ 10,301.00 | 6% | <i>\$9,755.56</i> |
| EWPP PremierPLS NBD AHR 30912 | 98504-30912 | \$ 393.00 | 6% | <i>\$372.19</i> |

| | | | | |
|----------------------------------|-------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR 30913 | 98504-30913 | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS NBD AHR 31012 | 98504-31012 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremierPLS NBD AHR 31013 | 98504-31013 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremierPLS NBD AHR 31014 | 98504-31014 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremierPLS NBD AHR 31015 | 98504-31015 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremierPLS NBD AHR 31016 | 98504-31016 | \$ 610.00 | 6% | <i>\$577.70</i> |
| EWPP PremierPLS NBD AHR 31017 | 98504-31017 | \$ 610.00 | 6% | <i>\$577.70</i> |
| EWPP PremierPLS NBD AHR 31018 | 98504-31018 | \$ 656.00 | 6% | <i>\$621.26</i> |
| EWPP PremierPLS NBD AHR 31019 | 98504-31019 | \$ 656.00 | 6% | <i>\$621.26</i> |
| EWPP PremierPLS NBD AHR 31025 | 98504-31025 | \$ 368.00 | 6% | <i>\$348.51</i> |
| EWPP PremierPLS NBD AHR 31026 | 98504-31026 | \$ 368.00 | 6% | <i>\$348.51</i> |
| EWPP PremierPLS NBD AHR 31028 | 98504-31028 | \$ 361.00 | 6% | <i>\$341.89</i> |
| EWPP PremierPLS NBD AHR 31029 | 98504-31029 | \$ 361.00 | 6% | <i>\$341.89</i> |
| EWPP PremierPLS NBD AHR 31031 | 98504-31031 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWPP PremierPLS NBD AHR 31032 | 98504-31032 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWPP PremierPLS NBD AHR 31034 | 98504-31034 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR 31035 | 98504-31035 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR 31050 | 98504-31050 | \$ 422.00 | 6% | <i>\$399.66</i> |
| EWPP PremierPLS NBD AHR 31051 | 98504-31051 | \$ 422.00 | 6% | <i>\$399.66</i> |
| EWPP PremierPLS NBD AHR 31055 | 98504-31055 | \$ 422.00 | 6% | <i>\$399.66</i> |
| EWPP PremierPLS NBD AHR 31056 | 98504-31056 | \$ 422.00 | 6% | <i>\$399.66</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EWPP PremierPLS NBD AHR 39031 | 98504-39031 | \$ 785.00 | 6% | <i>\$743.43</i> |
| EWPP PremierPLS NBD AHR 39032 | 98504-39032 | \$ 822.00 | 6% | <i>\$778.48</i> |
| EWPP PremierPLS NBD AHR 39033 | 98504-39033 | \$ 785.00 | 6% | <i>\$743.43</i> |
| EWPP PremierPLS NBD AHR 39034 | 98504-39034 | \$ 785.00 | 6% | <i>\$743.43</i> |
| EWPP PremierPLS NBD AHR 39035 | 98504-39035 | \$ 1,332.00 | 6% | <i>\$1,261.47</i> |
| EWPP PremierPLS NBD AHR 39036 | 98504-39036 | \$ 756.00 | 6% | <i>\$715.97</i> |
| EWPP PremierPLS NBD AHR 39037 | 98504-39037 | \$ 756.00 | 6% | <i>\$715.97</i> |
| EWPP PremierPLS NBD AHR 39038 | 98504-39038 | \$ 817.00 | 6% | <i>\$773.74</i> |
| EWPP PremierPLS NBD AHR 39039 | 98504-39039 | \$ 817.00 | 6% | <i>\$773.74</i> |
| EWPP PremierPLS NBD AHR 4120-24MW-4Y | 98504-4120- 24MW-4Y | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| EWPP PremierPLS NBD AHR 4120-48MW-4Y | 98504-4120- 48MW-4Y | \$ 1,729.00 | 6% | <i>\$1,637.45</i> |
| EWPP PremierPLS NBD AHR 4120C | 98504-4120C | \$ 7,190.00 | 10% | <i>\$6,519.53</i> |
| EWPP PremierPLS NBD AHR 4120C-1 | 98504-4120C-1 | \$ 6,787.00 | 6% | <i>\$6,427.63</i> |
| EWPP PremierPLS NBD AHR 41216 | 98504-41216 | \$ 2,221.00 | 6% | <i>\$2,103.40</i> |
| EWPP PremierPLS NBD AHR 4220-12P-4X | 98504-4220- 12P-4X | \$ 1,019.00 | 6% | <i>\$965.04</i> |
| EWPP PremierPLS NBD AHR 4220-12T-4X | 98504-4220- 12T-4X | \$ 963.00 | 6% | <i>\$912.01</i> |
| EWPP PremierPLS NBD AHR 4220-24P-4X | 98504-4220- 24P-4X | \$ 1,089.00 | 6% | <i>\$1,031.34</i> |
| EWPP PremierPLS NBD AHR 4220-24T-4X | 98504-4220- 24T-4X | \$ 1,026.00 | 6% | <i>\$971.67</i> |
| EWPP PremierPLS NBD AHR 4220-48P-4X | 98504-4220- 48P-4X | \$ 1,229.00 | 6% | <i>\$1,163.92</i> |
| EWPP PremierPLS NBD AHR 4220-48T-4X | 98504-4220- 48T-4X | \$ 1,124.00 | 6% | <i>\$1,064.48</i> |
| EWPP PremierPLS NBD AHR 4220-4MW-20P-4X | 98504-4220- 4MW-20P-4X | \$ 1,194.00 | 6% | <i>\$1,130.78</i> |

| | | | | |
|---|-----------------------------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR 4220-4MW-8P-4X | 98504-4220- 4MW-8P-4X | \$ 1,082.00 | 6% | <i>\$1,024.71</i> |
| EWPP PremierPLS NBD AHR 4220-8MW-40P-4X | 98504-4220- 8MW-40P-4X | \$ 1,370.00 | 6% | <i>\$1,297.46</i> |
| EWPP PremierPLS NBD AHR 4220-8X | 98504-4220-8X | \$ 1,103.00 | 6% | <i>\$1,044.60</i> |
| EWPP PremierPLS NBD AHR 48001 | 98504-48001 | \$ 9,582.00 | 6% | <i>\$9,074.63</i> |
| EWPP PremierPLS NBD AHR 48038 | 98504-48038 | \$ 3,397.00 | 6% | <i>\$3,217.13</i> |
| EWPP PremierPLS NBD AHR 48039 | 98504-48039 | \$ 3,397.00 | 6% | <i>\$3,217.13</i> |
| EWPP PremierPLS NBD AHR 48040 | 98504-48040 | \$ 3,125.00 | 6% | <i>\$2,959.53</i> |
| EWPP PremierPLS NBD AHR 48041 | 98504-48041 | \$ 3,397.00 | 6% | <i>\$3,217.13</i> |
| EWPP PremierPLS NBD AHR 48046 | 98504-48046 | \$ 4,321.00 | 6% | <i>\$4,092.20</i> |
| EWPP PremierPLS NBD AHR 48047 | 98504-48047 | \$ 10,765.00 | 6% | <i>\$10,194.99</i> |
| EWPP PremierPLS NBD AHR 48051 | 98504-48051 | \$ 7,544.00 | 6% | <i>\$7,144.55</i> |
| EWPP PremierPLS NBD AHR 48061 | 98504-48061 | \$ 8,741.00 | 6% | <i>\$8,278.16</i> |
| EWPP PremierPLS NBD AHR 48062 | 98504-48062 | \$ 13,714.00 | 6% | <i>\$12,987.84</i> |
| EWPP PremierPLS NBD AHR 5320-16P-4XE | 98504-5320- 16P-4XE | \$ 1,224.00 | 6% | <i>\$1,159.19</i> |
| EWPP PremierPLS NBD AHR 5320-16P-4XE-DC | 98504-5320- 16P-4XE-DC | \$ 1,284.00 | 6% | <i>\$1,216.01</i> |
| EWPP PremierPLS NBD AHR 5320-24P-8XE | 98504-5320- 24P-8XE | \$ 1,205.00 | 6% | <i>\$1,141.20</i> |
| EWPP PremierPLS NBD 5320- 24T-24S-4XE-XT | 98504-5320- 24T-24S-4XE- XT | \$ 1,153.00 | 6% | <i>\$1,091.95</i> |
| EWPP PremierPLS NBD AHR 5320-24T-4X-XT | 98504-5320- 24T-4X-XT | \$ 994.00 | 6% | <i>\$941.37</i> |
| EWPP PremierPLS NBD AHR 5320-24T-8XE | 98504-5320- 24T-8XE | \$ 1,166.00 | 6% | <i>\$1,104.26</i> |
| EWPP PremierPLS NBD AHR 5320-48P-8XE | 98504-5320- 48P-8XE | \$ 1,509.00 | 6% | <i>\$1,429.10</i> |

| | | | | |
|---|----------------------------------|-------------|-----|-------------------|
| EWPP PremierPLS NBD AHR 5320-48T-8XE | 98504-5320- 48T-8XE | \$ 1,359.00 | 6% | <i>\$1,287.04</i> |
| EWPP PremiPLS NBD AHR 5420F-16MW-32P-4XE | 98504-5420F- 16MW-32P- 4XE | \$ 2,279.00 | 6% | <i>\$2,158.33</i> |
| EWPP PremPLS NBD AHR 5420F-16W-32P-4XE | 98504-5420F- 16W-32P-4XE | \$ 1,927.00 | 6% | <i>\$1,824.97</i> |
| EWPP PremierPLS NBD AHR 5420F-24P-4XE | 98504-5420F- 24P-4XE | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPP PremierPLS NBD AHR 5420F-24S-4XE | 98504-5420F- 24S-4XE | \$ 1,692.00 | 6% | <i>\$1,602.41</i> |
| EWPP PremierPLS NBD AHR 5420F-24T-4XE | 98504-5420F- 24T-4XE | \$ 1,556.00 | 6% | <i>\$1,473.61</i> |
| EWPP PremierPLS NBD AHR 5420F-48P-4XE | 98504-5420F- 48P-4XE | \$ 1,884.00 | 6% | <i>\$1,784.24</i> |
| EWPP PremierPLS NBD AHR 5420F-48P-4XL | 98504-5420F- 48P-4XL | \$ 1,994.00 | 6% | <i>\$1,888.42</i> |
| EWPP PremierPLS NBD AHR 5420F-48T-4XE | 98504-5420F- 48T-4XE | \$ 1,686.00 | 6% | <i>\$1,596.73</i> |
| EWPP PremierPLS NBD AHR 5420F-8W-16P-4XE | 98504-5420F- 8W-16P-4XE | \$ 1,714.00 | 6% | <i>\$1,623.24</i> |
| EWPP PremiPLS NBD AHR 5420M-16MW-32P-4YE | 98504-5420M- 16MW-32P- 4YE | \$ 2,206.00 | 6% | <i>\$2,089.19</i> |
| EWPP PremierPLS NBD AHR 5420M-24T-4YE | 98504-5420M- 24T-4YE | \$ 1,676.00 | 6% | <i>\$1,587.26</i> |
| EWPP PremierPLS NBD AHR 5420M-24W-4YE | 98504-5420M- 24W-4YE | \$ 1,500.00 | 6% | <i>\$1,420.58</i> |
| EWPP PremierPLS NBD AHR 5420M-48T-4YE | 98504-5420M- 48T-4YE | \$ 1,859.00 | 6% | <i>\$1,760.57</i> |
| EWPP PremierPLS NBD AHR 5420M-48W-4YE | 98504-5420M- 48W-4YE | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWPP PREMIERPLUS NBD AHR 5520-12MW-36W | 98504-5520- 12MW-36W | \$ 2,168.00 | 6% | <i>\$2,053.20</i> |
| EWPP PREMIERPLUS NBD AHR 5520-24T | 98504-5520- 24T | \$ 1,636.00 | 6% | <i>\$1,549.37</i> |
| EWPP PREMIERPL NBD AH 5520-24T-ACDC-BASE | 98504-5520- 24T-ACDC- BASE | \$ 1,636.00 | 6% | <i>\$1,549.37</i> |
| EWPP PREMIERPLUS NBD AHR 5520-24T-BASE | 98504-5520- 24T-BASE | \$ 1,636.00 | 10% | <i>\$1,483.44</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EWPP PREMIERPLUS NBD AHR 5520-24W | 98504-5520- 24W | \$ 1,706.00 | 6% | <i>\$1,615.67</i> |
| EWPP PREMIERPLUS NBD AHR 5520-24X | 98504-5520- 24X | \$ 2,520.00 | 6% | <i>\$2,386.57</i> |
| EWPP PREMIERPL NBD AH 5520-24X-ACDC-BASE | 98504-5520- 24X-ACDC- BASE | \$ 2,520.00 | 6% | <i>\$2,386.57</i> |
| EWPP PREMIERPLUS NBD AHR 5520-24X-BASE | 98504-5520- 24X-BASE | \$ 2,520.00 | 10% | <i>\$2,285.01</i> |
| EWPP PREMIERPLUS NBD AHR 5520-48SE | 98504-5520- 48SE | \$ 2,389.00 | 6% | <i>\$2,262.50</i> |
| EWPP PREMIERPL NBD A 5520-48SE-ACDC-BASE | 98504-5520- 48SE-ACDC- BASE | \$ 2,389.00 | 6% | <i>\$2,262.50</i> |
| EWPP PREMIERPLUS NBD AHR 5520-48SE-BASE | 98504-5520- 48SE-BASE | \$ 2,389.00 | 10% | <i>\$2,166.23</i> |
| EWPP PREMIERPLUS NBD AHR 5520-48T | 98504-5520- 48T | \$ 1,942.00 | 6% | <i>\$1,839.17</i> |
| EWPP PREMIERPL NBD AH 5520-48T-ACDC-BASE | 98504-5520- 48T-ACDC- BASE | \$ 1,942.00 | 6% | <i>\$1,839.17</i> |
| EWPP PREMIERPLUS NBD AHR 5520-48T-BASE | 98504-5520- 48T-BASE | \$ 1,942.00 | 10% | <i>\$1,760.91</i> |
| EWPP PREMIERPLUS NBD AHR 5520-48W | 98504-5520- 48W | \$ 1,987.00 | 6% | <i>\$1,881.79</i> |
| EWPP PremierPLS NBD AHR 5720-24MW | 98504-5720- 24MW | \$ 1,845.00 | 6% | <i>\$1,747.31</i> |
| EWPP PremierPLS NBD AHR 5720-24MXW | 98504-5720- 24MXW | \$ 1,764.00 | 6% | <i>\$1,670.60</i> |
| EWPP PremierPLS NBD AHR 5720-48MW | 98504-5720- 48MW | \$ 1,543.00 | 6% | <i>\$1,461.30</i> |
| EWPP PremierPLS NBD AHR 5720-48MXW | 98504-5720- 48MXW | \$ 2,224.00 | 6% | <i>\$2,106.24</i> |
| EWPP PremierPLS NBD AHR 7520-48XT-6C | 98504-7520- 48XT-6C | \$ 3,137.00 | 6% | <i>\$2,970.90</i> |
| EWPP PremierPLS NBD AH 7520-48XT-6C-AC-F | 98504-7520- 48XT-6C-AC- F | \$ 3,137.00 | 6% | <i>\$2,970.90</i> |
| EWPP PremierPLS NBD AH 7520-48XT-6C-AC-R | 98504-7520- 48XT-6C-AC- R | \$ 3,137.00 | 6% | <i>\$2,970.90</i> |
| EWPP PremierPLS NBD AHR 7520-48Y-8C | 98504-7520- 48Y-8C | \$ 2,921.00 | 6% | <i>\$2,766.33</i> |

| | | | | |
|--|----------------------------------|-------------|----|------------|
| EWPP PremierPLS NBD AHR 7520-48Y-8C-AC-F | 98504-7520- 48Y-8C-AC-F | \$ 2,921.00 | 6% | \$2,766.33 |
| EWPP PremierPLS NBD AHR 7520-48Y-8C-AC-R | 98504-7520- 48Y-8C-AC-R | \$ 2,921.00 | 6% | \$2,766.33 |
| EWPP PREMIERPLUS NBD AHR 7520-48YE-8CE | 98504-7520- 48YE-8CE | \$ 3,400.00 | 6% | \$3,219.97 |
| EWPP PREMIERPL NBD AHR 7520-48YE-8CE-AC-F | 98504-7520- 48YE-8CE-AC- F | \$ 3,400.00 | 6% | \$3,219.97 |
| EWPP PREMIERPL NBD AHR 7520-48YE-8CE-AC-R | 98504-7520- 48YE-8CE-AC- R | \$ 3,400.00 | 6% | \$3,219.97 |
| EWPP PremierPLS NBD AHR 7720-32C | 98504-7720- 32C | \$ 3,644.00 | 6% | \$3,451.05 |
| EWPP PremierPLS NBD AHR 7720-32C-AC-F | 98504-7720- 32C-AC-F | \$ 3,644.00 | 6% | \$3,451.05 |
| EWPP PremierPLS NBD AHR 7720-32C-AC-R | 98504-7720- 32C-AC-R | \$ 3,644.00 | 6% | \$3,451.05 |
| EWPP PremierPLS NBD AHR 8520-48XT-6C | 98504-8520- 48XT-6C | \$ 4,306.00 | 6% | \$4,078.00 |
| EWPP PremPLS NBD AHR 8520-48XT-6C-AC-F | 98504-8520- 48XT-6C-AC- F | \$ 4,306.00 | 6% | \$4,078.00 |
| EWPP PremPLS NBD AHR 8520-48XT-6C-AC-R | 98504-8520- 48XT-6C-AC- R | \$ 4,306.00 | 6% | \$4,078.00 |
| EWPP PremPLS NBD AHR 8520-48XT-6C-DC-F | 98504-8520- 48XT-6C-DC- F | \$ 4,306.00 | 6% | \$4,078.00 |
| EWPP PremPLS NBD AHR 8520-48XT-6C-DC-R | 98504-8520- 48XT-6C-DC- R | \$ 4,306.00 | 6% | \$4,078.00 |
| EWPP PremierPLS NBD AHR 8520-48Y-8C | 98504-8520- 48Y-8C | \$ 4,471.00 | 6% | \$4,234.26 |
| EWPP PremierPLS NBD AHR 8520-48Y-8C-AC-F | 98504-8520- 48Y-8C-AC-F | \$ 4,471.00 | 6% | \$4,234.26 |
| EWPP PremierPLS NBD AHR 8520-48Y-8C-AC-R | 98504-8520- 48Y-8C-AC-R | \$ 4,471.00 | 6% | \$4,234.26 |
| EWPP PremierPLS NBD AHR 8520-48Y-8C-DC-F | 98504-8520- 48Y-8C-DC-F | \$ 4,471.00 | 6% | \$4,234.26 |
| EWPP PremierPLS NBD AHR 8520-48Y-8C-DC-R | 98504-8520- 48Y-8C-DC-R | \$ 4,471.00 | 6% | \$4,234.26 |

| | | | | |
|---|----------------------------|--------------|-----|--------------------|
| EWPP PremierPLS NBD AHR 8720-32C | 98504-8720- 32C | \$ 4,800.00 | 6% | <i>\$4,545.84</i> |
| EWPP PremierPLS NBD AHR 8720-32C-AC-F | 98504-8720- 32C-AC-F | \$ 4,800.00 | 6% | <i>\$4,545.84</i> |
| EWPP PremierPLS NBD AHR 8720-32C-AC-R | 98504-8720- 32C-AC-R | \$ 4,800.00 | 6% | <i>\$4,545.84</i> |
| EWPP PremierPLS NBD AHR 8720-32C-DC-F | 98504-8720- 32C-DC-F | \$ 4,800.00 | 6% | <i>\$4,545.84</i> |
| EWPP PremierPLS NBD AHR 8720-32C-DC-R | 98504-8720- 32C-DC-R | \$ 4,800.00 | 6% | <i>\$4,545.84</i> |
| EWPP PremierPLS NBD AHR 8806 | 98504-8806 | \$ 4,442.00 | 6% | <i>\$4,206.80</i> |
| EWPP PremierPLS NBD AHR 8810 | 98504-8810 | \$ 8,748.00 | 6% | <i>\$8,284.79</i> |
| EWPP PremierPLS NBD AHR 8820-40C | 98504-8820- 40C | \$ 14,654.00 | 10% | <i>\$13,287.51</i> |
| EWPP PremierPLS NBD AHR 8820-40C-AC-F | 98504-8820- 40C-AC-F | \$ 14,654.00 | 10% | <i>\$13,287.51</i> |
| EWPP PremierPLS NBD AHR 8820-40C-AC-R | 98504-8820- 40C-AC-R | \$ 14,654.00 | 10% | <i>\$13,287.51</i> |
| EWPP PremierPLS NBD AHR 8820-40C-DC-F | 98504-8820- 40C-DC-F | \$ 14,654.00 | 10% | <i>\$13,287.51</i> |
| EWPP PremierPLS NBD AHR 8820-40C-DC-R | 98504-8820- 40C-DC-R | \$ 14,654.00 | 10% | <i>\$13,287.51</i> |
| EWPP PremierPLS NBD AHR 8820-80C | 98504-8820- 80C | \$ 25,501.00 | 10% | <i>\$23,123.03</i> |
| EWPP PremierPLS NBD AHR 8820-80C-AC-F | 98504-8820- 80C-AC-F | \$ 25,501.00 | 10% | <i>\$23,123.03</i> |
| EWPP PremierPLS NBD AHR 8820-80C-AC-R | 98504-8820- 80C-AC-R | \$ 25,501.00 | 10% | <i>\$23,123.03</i> |
| EWPP PremierPLS NBD AHR 8820-80C-DC-F | 98504-8820- 80C-DC-F | \$ 25,501.00 | 10% | <i>\$23,123.03</i> |
| EWPP PremierPLS NBD AHR 8820-80C-DC-R | 98504-8820- 80C-DC-R | \$ 25,501.00 | 10% | <i>\$23,123.03</i> |
| EWPP PremierPLS NBD AHR 9920-16C | 98504-9920- 16C | \$ 11,978.00 | 6% | <i>\$11,343.76</i> |
| EWPP PremierPLS NBD AHR 9920-4D | 98504-9920-4D | \$ 11,978.00 | 6% | <i>\$11,343.76</i> |
| EWPP PremierPLS NBD AHR 9920-NPB-8 | 98504-9920- NPB-8 | \$ 20,659.00 | 6% | <i>\$19,565.11</i> |
| EWPP PremierPLS NBD AHR AH-AP-1130-AC-CE | 98504-AH-AP- 1130-AC-CE | \$ 369.00 | 6% | <i>\$349.46</i> |

| | | | | |
|---|---------------------------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR AH-AP-1130-AC-FC | 98504-AH-AP- 1130-AC-FCC | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-1130-AC-W | 98504-AH-AP- 1130-AC-W | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-121-N-CE | 98504-AH-AP- 121-N-CE | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWPP PremierPLS NBD AHR AH-AP-121-N-FCC | 98504-AH-AP- 121-N-FCC | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWPP PremierPLS NBD AHR AH-AP-121-N-W | 98504-AH-AP- 121-N-W | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWPP PremierPLS NBD AHR AH-AP-121-N-W-NE | 98504-AH-AP- 121-N-W-NEC | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWPP PremierPLS NBD AHR AH-AP-122-AC-CAN | 98504-AH-AP- 122-AC-CAN | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-122-AC-CE | 98504-AH-AP- 122-AC-CE | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-122-AC-FCC | 98504-AH-AP- 122-AC-FCC | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-122-AC-W | 98504-AH-AP- 122-AC-W | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-122X-AC-CA | 98504-AH-AP- 122X-AC- CAN | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-122X-AC-CE | 98504-AH-AP- 122X-AC-CE | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-122X-AC-FC | 98504-AH-AP- 122X-AC-FCC | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-122X-AC-W | 98504-AH-AP- 122X-AC-W | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-130-AC-CE | 98504-AH-AP- 130-AC-CE | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-130-AC-FCC | 98504-AH-AP- 130-AC-FCC | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-130-AC-W | 98504-AH-AP- 130-AC-W | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-141-N-CE | 98504-AH-AP- 141-N-CE | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWPP PremierPLS NBD AHR AH-AP-141-N-FCC | 98504-AH-AP- 141-N-FCC | \$ 404.00 | 6% | <i>\$382.61</i> |
| EWPP PremierPLS NBD AHR AH-AP-141-N-W | 98504-AH-AP- 141-N-W | \$ 404.00 | 6% | <i>\$382.61</i> |

| | | | | |
|---|---------------------------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR AH-AP-150W-AC-CA | 98504-AH-AP- 150W-AC- CAN | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-150W-AC-CE | 98504-AH-AP- 150W-AC-CE | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-150W-AC-FC | 98504-AH-AP- 150W-AC-FCC | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-150W-AC-W | 98504-AH-AP- 150W-AC-W | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-230-AC-CE | 98504-AH-AP- 230-AC-CE | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-230-AC-FCC | 98504-AH-AP- 230-AC-FCC | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-230-AC-W | 98504-AH-AP- 230-AC-W | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-245X-AC-CA | 98504-AH-AP- 245X-AC- CAN | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-245X-AC-CE | 98504-AH-AP- 245X-AC-CE | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-245X-AC-FC | 98504-AH-AP- 245X-AC-FCC | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-245X-AC-W | 98504-AH-AP- 245X-AC-W | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-250-AC-CAN | 98504-AH-AP- 250-AC-CAN | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-250-AC-CE | 98504-AH-AP- 250-AC-CE | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-250-AC-FCC | 98504-AH-AP- 250-AC-FCC | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-250-AC-W | 98504-AH-AP- 250-AC-W | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AH-AP-330-N-FCC | 98504-AH-AP- 330-N-FCC | \$ 404.00 | 6% | \$382.61 |
| EWPP PremierPLS NBD AHR AH-AP-330-N-W | 98504-AH-AP- 330-N-W | \$ 404.00 | 6% | \$382.61 |
| EWPP PremierPLS NBD AHR AH-AP-350-N-FCC | 98504-AH-AP- 350-N-FCC | \$ 404.00 | 6% | \$382.61 |
| EWPP PremierPLS NBD AHR AH-AP-350-N-W | 98504-AH-AP- 350-N-W | \$ 404.00 | 6% | \$382.61 |

| | | | | |
|---|---------------------------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR AH-AP-550-AC-CAN | 98504-AH-AP- 550-AC-CAN | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-550-AC-CE | 98504-AH-AP- 550-AC-CE | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-550-AC-FCC | 98504-AH-AP- 550-AC-FCC | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-550-AC-W | 98504-AH-AP- 550-AC-W | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-630-AX-CAN | 98504-AH-AP- 630-AX-CAN | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-630-AX-CE | 98504-AH-AP- 630-AX-CE | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-630-AX-FCC | 98504-AH-AP- 630-AX-FCC | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-630-AX-W | 98504-AH-AP- 630-AX-W | \$ 369.00 | 6% | <i>\$349.46</i> |
| EWPP PremierPLS NBD AHR AH-AP-650-AX-CAN | 98504-AH-AP- 650-AX-CAN | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-AP-650-AX-CE | 98504-AH-AP- 650-AX-CE | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-AP-650-AX-FCC | 98504-AH-AP- 650-AX-FCC | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-AP-650-AX-W | 98504-AH-AP- 650-AX-W | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-AP-650X-AX-CA | 98504-AH-AP- 650X-AX- CAN | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-AP-650X-AX-CE | 98504-AH-AP- 650X-AX-CE | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-AP-650X-AX-FC | 98504-AH-AP- 650X-AX-FCC | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-AP-650X-AX-W | 98504-AH-AP- 650X-AX-W | \$ 304.00 | 6% | <i>\$287.90</i> |
| EWPP PremierPLS NBD AHR AH-ATOM-CAN | 98504-AH- ATOM-CAN | \$ 381.00 | 6% | <i>\$360.83</i> |
| EWPP PremierPLS NBD AHR AH-ATOM-CE-EU | 98504-AH- ATOM-CE-EU | \$ 400.00 | 6% | <i>\$378.82</i> |
| EWPP PremierPLS NBD AHR AH-ATOM-CE-UK | 98504-AH- ATOM-CE-UK | \$ 400.00 | 6% | <i>\$378.82</i> |

| | | | | |
|--|-------------------------|-------------|----|------------|
| EWPP PremierPLS NBD AHR AH-ATOM-FCC | 98504-AH-ATOM-FCC | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBD AHR AH-ATOM-W | 98504-AH-ATOM-W | \$ 381.00 | 6% | \$360.83 |
| EWPP PremierPLS NBD AHR AH-ATOM-W-EU | 98504-AH-ATOM-W-EU | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS NBD AHR AH-ATOM-W-UK | 98504-AH-ATOM-W-UK | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS NBD AHR AH-BR-100-N-FCC | 98504-AH-BR-100-N-FCC | \$ 1,247.00 | 6% | \$1,180.97 |
| EWPP PremierPLS NBD AHR AH-BR-100-N-W | 98504-AH-BR-100-N-W | \$ 1,247.00 | 6% | \$1,180.97 |
| EWPP PremierPLS NBD AHR AH-BR-100-N-W-AU | 98504-AH-BR-100-N-W-AU | \$ 1,247.00 | 6% | \$1,180.97 |
| EWPP PremierPLS NBD AHR AH-BR-100-N-W-EU | 98504-AH-BR-100-N-W-EU | \$ 1,247.00 | 6% | \$1,180.97 |
| EWPP PremierPLS NBD AHR AH-BR-100-N-W-UK | 98504-AH-BR-100-N-W-UK | \$ 1,247.00 | 6% | \$1,180.97 |
| EWPP PremierPLS NBD AHR AH-BR-100-N-W-US | 98504-AH-BR-100-N-W-US | \$ 1,247.00 | 6% | \$1,180.97 |
| EWPP PremierPLS NBD AHR AH-BR-200 | 98504-AH-BR-200 | \$ 1,134.00 | 6% | \$1,073.95 |
| EWPP PremierPLS NBD AHR AH-BR-200WP-N-CE | 98504-AH-BR-200WP-N-CE | \$ 1,191.00 | 6% | \$1,127.94 |
| EWPP PremierPLS NBD AHR AH-BR-200WP-N-EU | 98504-AH-BR-200WP-N-EU | \$ 1,191.00 | 6% | \$1,127.94 |
| EWPP PremierPLS NBD AHR AH-BR-200WP-N-FC | 98504-AH-BR-200WP-N-FCC | \$ 1,134.00 | 6% | \$1,073.95 |
| EWPP PremierPLS NBD AHR AH-BR-200WP-N-W | 98504-AH-BR-200WP-N-W | \$ 1,191.00 | 6% | \$1,127.94 |
| EWPP PremierPLS NBD AHR AH-SR-2024P | 98504-AH-SR-2024P | \$ 1,137.00 | 6% | \$1,076.80 |
| EWPP PremierPLS NBD AHR AH-SR-2124P | 98504-AH-SR-2124P | \$ 1,137.00 | 6% | \$1,076.80 |
| EWPP PremierPLS NBD AHR AH-SR-2148P | 98504-AH-SR-2148P | \$ 1,137.00 | 6% | \$1,076.80 |
| EWPP PremierPLS NBD AHR AH-SR-2208P-AU | 98504-AH-SR-2208P-AU | \$ 1,137.00 | 6% | \$1,076.80 |
| EWPP PremierPLS NBD AHR AH-SR-2208P-EU | 98504-AH-SR-2208P-EU | \$ 1,137.00 | 6% | \$1,076.80 |

| | | | | |
|--|----------------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR AH-SR-2208P-NA | 98504-AH-SR-2208P-NA | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2208P-UK | 98504-AH-SR-2208P-UK | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2224P-AU | 98504-AH-SR-2224P-AU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2224P-EU | 98504-AH-SR-2224P-EU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2224P-NA | 98504-AH-SR-2224P-NA | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2224P-UK | 98504-AH-SR-2224P-UK | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2324P-AU | 98504-AH-SR-2324P-AU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2324P-EU | 98504-AH-SR-2324P-EU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2324P-NA | 98504-AH-SR-2324P-NA | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2324P-UK | 98504-AH-SR-2324P-UK | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2348P-AU | 98504-AH-SR-2348P-AU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2348P-EU | 98504-AH-SR-2348P-EU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2348P-NA | 98504-AH-SR-2348P-NA | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-SR-2348P-UK | 98504-AH-SR-2348P-UK | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR200P-AU | 98504-AH-XR200P-AU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR200P-EU | 98504-AH-XR200P-EU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR200P-UK | 98504-AH-XR200P-UK | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR200P-US | 98504-AH-XR200P-US | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR600P | 98504-AH-XR600P | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR600P-AU | 98504-AH-XR600P-AU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR600P-EU | 98504-AH-XR600P-EU | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |

| | | | | |
|---|---------------------------------|-------------|-----|-------------------|
| EWPP PremierPLS NBD AHR AH-XR600P-KR | 98504-AH- XR600P-KR | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR600P-UK | 98504-AH- XR600P-UK | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AH-XR600P-US | 98504-AH- XR600P-US | \$ 1,137.00 | 6% | <i>\$1,076.80</i> |
| EWPP PremierPLS NBD AHR AP-8533-IL | 98504-AP- 8533-68SB30- IL | \$ 390.00 | 6% | <i>\$369.35</i> |
| EWPP PremierPLS NBD AHR AP3000-IL | 98504-AP3000- IL | \$ 253.89 | 6% | <i>\$240.45</i> |
| EWPP PremierPLS NBD AHR AP3000-TN | 98504-AP3000- TN | \$ 253.89 | 6% | <i>\$240.45</i> |
| EWPP PremierPLS NBD AHR AP3000-WW | 98504-AP3000- WW | \$ 253.89 | 6% | <i>\$240.45</i> |
| EWPP PremierPLS NBD AHR AP3000X-WW | 98504- AP3000X-WW | \$ 268.52 | 6% | <i>\$254.30</i> |
| EWPP PremierPLS NBD AHR AP302W-CAN | 98504- AP302W-CAN | \$ 364.00 | 6% | <i>\$344.73</i> |
| EWPP PremierPLS NBD AHR AP302W-EG | 98504- AP302W-EG | \$ 266.00 | 10% | <i>\$241.20</i> |
| EWPP PremierPLS NBD AHR AP302W-FCC | 98504- AP302W-FCC | \$ 364.00 | 6% | <i>\$344.73</i> |
| EWPP PremierPLS NBD AHR AP302W-WR | 98504- AP302W-WR | \$ 360.00 | 6% | <i>\$340.94</i> |
| EWPP PremierPLS NBD AHR AP305C-1-CAN | 98504-AP305C- 1-CAN | \$ 360.00 | 6% | <i>\$340.94</i> |
| EWPP PremierPLS NBD AHR AP305C-1-EG | 98504-AP305C- 1-EG | \$ 360.00 | 6% | <i>\$340.94</i> |
| EWPP PremierPLS NBD AHR AP305C-FCC | 98504-AP305C- 1-FCC | \$ 360.00 | 6% | <i>\$340.94</i> |
| EWPP PremierPLS NBD AHR AP305C-1-IL | 98504-AP305C- 1-IL | \$ 360.00 | 6% | <i>\$340.94</i> |
| EWPP PremierPLS NBD AHR AP305C-1-WR | 98504-AP305C- 1-WR | \$ 360.00 | 6% | <i>\$340.94</i> |
| EWPP PremierPLS NBD AHR AP305C-CAN | 98504-AP305C- CAN | \$ 388.00 | 6% | <i>\$367.46</i> |
| EWPP PremierPLS NBD AHR AP305C-EG | 98504-AP305C- EG | \$ 388.00 | 6% | <i>\$367.46</i> |

| | | | | |
|-------------------------------------|-------------------|-----------|-----|----------|
| EWPP PremierPLS NBD AHR AP305C-FCC | 98504-AP305C-FCC | \$ 388.00 | 6% | \$367.46 |
| EWPP PremierPLS NBD AHR AP305C-IL | 98504-AP305C-IL | \$ 388.00 | 6% | \$367.46 |
| EWPP PremierPLS NBD AHR AP305C-WR | 98504-AP305C-WR | \$ 388.00 | 6% | \$367.46 |
| EWPP PremierPLS NBD AHR AP305CX-CAN | 98504-AP305CX-CAN | \$ 388.00 | 6% | \$367.46 |
| EWPP PremierPLS NBD AHR AP305CX-FCC | 98504-AP305CX-FCC | \$ 388.00 | 6% | \$367.46 |
| EWPP PremierPLS NBD AHR AP305CX-IL | 98504-AP305CX-IL | \$ 388.00 | 6% | \$367.46 |
| EWPP PremierPLS NBD AHR AP305CX-WR | 98504-AP305CX-WR | \$ 388.00 | 6% | \$367.46 |
| EWPP PremierPLS NBD AHR AP310e-1-WR | 98504-AP310e-1-WR | \$ 352.00 | 10% | \$319.18 |
| EWPP PremierPLS NBD AHR AP310e-CAN | 98504-AP310e-CAN | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP310e-FCC | 98504-AP310e-FCC | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP310e-IL | 98504-AP310e-IL | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP310e-WR | 98504-AP310e-WR | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP310i-1-WR | 98504-AP310i-1-WR | \$ 352.00 | 10% | \$319.18 |
| EWPP PremierPLS NBD AHR AP310i-CAN | 98504-AP310i-CAN | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP310i-FCC | 98504-AP310i-FCC | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP310i-IL | 98504-AP310i-IL | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP310i-WR | 98504-AP310i-WR | \$ 369.00 | 6% | \$349.46 |
| EWPP PremierPLS NBD AHR AP360e-CAN | 98504-AP360e-CAN | \$ 392.00 | 6% | \$371.24 |
| EWPP PremierPLS NBD AHR AP360e-FCC | 98504-AP360e-FCC | \$ 392.00 | 6% | \$371.24 |
| EWPP PremierPLS NBD AHR AP360e-IL | 98504-AP360e-IL | \$ 392.00 | 6% | \$371.24 |

| | | | | |
|--------------------------------------|--------------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR AP360e-WR | 98504-AP360e-WR | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPP PremierPLS NBD AHR AP360i-CAN | 98504-AP360i-CAN | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPP PremierPLS NBD AHR AP360i-FCC | 98504-AP360i-FCC | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPP PremierPLS NBD AHR AP360i-WR | 98504-AP360i-WR | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPP PremierPLS NBD AHR AP4000-WW | 98504-AP4000-1-WW | \$ 327.00 | 6% | <i>\$309.69</i> |
| EWPP PremierPLS NBD AHR AP4000-IL | 98504-AP4000-IL | \$ 327.00 | 6% | <i>\$309.69</i> |
| EWPP PremierPLS NBD AHR AP4000-WW | 98504-AP4000-WW | \$ 327.00 | 6% | <i>\$309.69</i> |
| EWPP PremierPLS NBD AHR AP410C-1-CAN | 98504-AP410C-1-CAN | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWPP PremierPLS NBD AHR AP410C-1-EG | 98504-AP410C-1-EG | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWPP PremierPLS NBD AHR AP410C-1-FCC | 98504-AP410C-1-FCC | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWPP PremierPLS NBD AHR AP410C-1-IL | 98504-AP410C-1-IL | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWPP PremierPLS NBD AHR AP410C-1-WR | 98504-AP410C-1-WR | \$ 340.00 | 6% | <i>\$322.00</i> |
| EWPP PremierPLS NBD AHR AP410C-CAN | 98504-AP410C-CAN | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR AP410C-EG | 98504-AP410C-EG | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR AP410C-FCC | 98504-AP410C-FCC | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR AP410C-IL | 98504-AP410C-IL | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR AP410C-WR | 98504-AP410C-WR | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR AP410e-CAN | 98504-AP410e-CAN | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS NBD AHR AP410e-FCC | 98504-AP410e-FCC | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS NBD AHR AP410e-WR | 98504-AP410e-WR | \$ 406.00 | 6% | <i>\$384.50</i> |

| | | | | |
|---------------------------------------|---------------------|-----------|-----|-----------------|
| EWPP PremierPLS NBD AHR AP410i-1-FCC | 98504-AP410i-1-FCC | \$ 387.00 | 10% | <i>\$350.91</i> |
| EWPP PremierPLS NBD AHR AP410i-1-WR | 98504-AP410i-1-WR | \$ 387.00 | 10% | <i>\$350.91</i> |
| EWPP PremierPLS NBD AHR AP410i-CAN | 98504-AP410i-CAN | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS NBD AHR AP410i-FCC | 98504-AP410i-FCC | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS NBD AHR AP410i-IL | 98504-AP410i-IL | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS NBD AHR AP410i-WR | 98504-AP410i-WR | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS NBD AHR AP460C-CAN | 98504-AP460C-CAN | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWPP PremierPLS NBD AHR AP460C-EG | 98504-AP460C-EG | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWPP PremierPLS NBD AHR AP460C-FCC | 98504-AP460C-FCC | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWPP PremierPLS NBD AHR AP460C-IL | 98504-AP460C-IL | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWPP PremierPLS NBD AHR AP460C-WR | 98504-AP460C-WR | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWPP PremierPLS NBD AHR AP460e-CAN | 98504-AP460e-CAN | \$ 422.00 | 6% | <i>\$399.66</i> |
| EWPP PremierPLS NBD AHR AP460e-FCC | 98504-AP460e-FCC | \$ 422.00 | 6% | <i>\$399.66</i> |
| EWPP PremierPLS NBD AHR AP460e-WR | 98504-AP460e-WR | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS NBD AHR AP460i-CAN | 98504-AP460i-CAN | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS NBD AHR AP460i-FCC | 98504-AP460i-FCC | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS NBD AHR AP460i-IL | 98504-AP460i-IL | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS NBD AHR AP460i-WR | 98504-AP460i-WR | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS NBD AHR AP460S12C-CAN | 98504-AP460S12C-CAN | \$ 384.00 | 6% | <i>\$363.67</i> |
| EWPP PremierPLS NBD AHR AP460S12C-FCC | 98504-AP460S12C-FCC | \$ 384.00 | 6% | <i>\$363.67</i> |

| | | | | |
|---|----------------------------|-----------|-----|----------|
| EWPP PremierPLS NBD AHR AP460S12C-WR | 98504- AP460S12C- WR | \$ 384.00 | 6% | \$363.67 |
| EWPP PremierPLS NBD AHR AP460S6C-CAN | 98504- AP460S6C- CAN | \$ 384.00 | 6% | \$363.67 |
| EWPP PremierPLS NBD AHR AP460S6C-FCC | 98504- AP460S6C- FCC | \$ 384.00 | 6% | \$363.67 |
| EWPP PremierPLS NBD AHR AP460S6C-WR | 98504- AP460S6C- WR | \$ 384.00 | 6% | \$363.67 |
| EWPP PremierPLS NBD AHR AP5010-IL | 98504-AP5010- IL | \$ 349.00 | 6% | \$330.52 |
| EWPP PremierPLS NBD AHR AP5010-WW | 98504-AP5010- WW | \$ 349.00 | 10% | \$316.46 |
| EWPP PremierPLS NBD AHR AP5020-WW | 98504-AP5020- WW | \$ 341.58 | 6% | \$323.49 |
| EWPP PremierPLS NBD AHR AP5050D-WW | 98504- AP5050D-WW | \$ 520.00 | 6% | \$492.47 |
| EWPP PremierPLS NBD AHR AP5050U-WW | 98504- AP5050U-WW | \$ 450.00 | 6% | \$426.17 |
| EWPP PremierPLS NBD AHR AP505i-FCC | 98504-AP505i- FCC | \$ 396.00 | 6% | \$375.03 |
| EWPP PremierPLS NBD AHR AP505i-FCC-TAA | 98504-AP505i- FCC-TAA | \$ 396.00 | 6% | \$375.03 |
| EWPP PremierPLS NBD AHR AP505i-WR | 98504-AP505i- WR | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS NBD AHR AP510C-CAN | 98504-AP510C- CAN | \$ 304.00 | 6% | \$287.90 |
| EWPP PremierPLS NBD AHR AP510C-CE | 98504-AP510C- CE | \$ 304.00 | 6% | \$287.90 |
| EWPP PremierPLS NBD AHR AP510C-FCC | 98504-AP510C- FCC | \$ 304.00 | 6% | \$287.90 |
| EWPP PremierPLS NBD AHR AP510C-W | 98504-AP510C- W | \$ 304.00 | 6% | \$287.90 |
| EWPP PremierPLS NBD AHR AP510C-WW | 98504-AP510C- WW | \$ 403.00 | 6% | \$381.66 |
| EWPP PremierPLS NBD AHR AP510CX-CAN | 98504- AP510CX- CAN | \$ 304.00 | 6% | \$287.90 |
| EWPP PremierPLS NBD AHR AP510CX-CE | 98504- AP510CX- CE | \$ 304.00 | 6% | \$287.90 |

| | | | | |
|---|---------------------------|-------------|-----|------------|
| EWPP PremierPLS NBD AHR AP510CX-FCC | 98504- AP510CX- FCC | \$ 304.00 | 6% | \$287.90 |
| EWPP PremierPLS NBD AHR AP510CX-W | 98504- AP510CX-W | \$ 304.00 | 6% | \$287.90 |
| EWPP PremierPLS NBD AHR AP510CX-WW | 98504- AP510CX-WW | \$ 403.00 | 6% | \$381.66 |
| EWPP PremierPLS NBD AHR AP510e-FCC | 98504-AP510e- FCC | \$ 444.00 | 6% | \$420.49 |
| EWPP PremierPLS NBD AHR AP510e-FCC-TAA | 98504-AP510e- FCC-TAA | \$ 444.00 | 6% | \$420.49 |
| EWPP PremierPLS NBD AHR AP510e-WR | 98504-AP510e- WR | \$ 423.00 | 6% | \$400.60 |
| EWPP PremierPLS NBD AHR AP510i-1-FCC | 98504-AP510i- 1-FCC | \$ 409.00 | 10% | \$370.86 |
| EWPP PremierPLS NBD AHR AP510i-1-WR | 98504-AP510i- 1-WR | \$ 409.00 | 10% | \$370.86 |
| EWPP PremierPLS NBD AHR AP510i-FCC | 98504-AP510i- FCC | \$ 429.00 | 6% | \$406.28 |
| EWPP PremierPLS NBD AHR AP510i-FCC-TAA | 98504-AP510i- FCC-TAA | \$ 429.00 | 6% | \$406.28 |
| EWPP PremierPLS NBD AHR AP510i-WR | 98504-AP510i- WR | \$ 429.00 | 6% | \$406.28 |
| EWPP PremierPLS NBD AHR AP560h-FCC | 98504-AP560h- FCC | \$ 624.00 | 6% | \$590.96 |
| EWPP PremierPLS NBD AHR AP560h-WR | 98504-AP560h- WR | \$ 624.00 | 6% | \$590.96 |
| EWPP PremierPLS NBD AHR AP560i-FCC | 98504-AP560i- FCC | \$ 534.00 | 6% | \$505.72 |
| EWPP PremierPLS NBD AHR AP560i-WR | 98504-AP560i- WR | \$ 509.00 | 6% | \$482.05 |
| EWPP PremierPLS NBD AHR AP560m-FCC | 98504-AP560m- FCC | \$ 534.00 | 6% | \$505.72 |
| EWPP PremierPLS NBD AHR AP560t-FCC | 98504-AP560t- FCC | \$ 624.00 | 6% | \$590.96 |
| EWPP PremierPLS NBD AHR AP560u-FCC | 98504-AP560u- FCC | \$ 497.00 | 6% | \$470.68 |
| EWPP PremierPLS NBD AHR E2122 | 98504-E2122 | \$ 7,312.00 | 6% | \$6,924.83 |
| EWPP PremierPLS NBD AHR E2122-1 | 98504-E2122-1 | \$ 6,964.00 | 6% | \$6,595.26 |

| | | | | |
|---------------------------------|---------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR E3120-1 | 98504-E3120-1 | \$ 9,810.00 | 6% | <i>\$9,290.56</i> |
| EWPP PremierPLS NBD AHR E3125 | 98504-E3125 | \$ 10,656.00 | 6% | <i>\$10,091.76</i> |
| EWPP PremierPLS NBD AHR H30003 | 98504-H30003 | \$ 876.00 | 6% | <i>\$829.62</i> |
| EWPP PremierPLS NBD AHR H30004 | 98504-H30004 | \$ 898.00 | 6% | <i>\$850.45</i> |
| EWPP PremierPLS NBD AHR H30005 | 98504-H30005 | \$ 1,268.00 | 6% | <i>\$1,200.86</i> |
| EWPP PremierPLS NBD AHR H30006 | 98504-H30006 | \$ 1,323.00 | 6% | <i>\$1,252.95</i> |
| EWPP PremierPLS NBD AHR H30007 | 98504-H30007 | \$ 1,318.00 | 6% | <i>\$1,248.21</i> |
| EWPP PremierPLS NBD AHR H30008 | 98504-H30008 | \$ 1,408.00 | 6% | <i>\$1,333.45</i> |
| EWPP PremierPLS NBD AHR H30009 | 98504-H30009 | \$ 1,262.00 | 6% | <i>\$1,195.18</i> |
| EWPP PremierPLS NBD AHR H30010 | 98504-H30010 | \$ 1,304.00 | 6% | <i>\$1,234.95</i> |
| EWPP PremierPLS NBD AHR H30011 | 98504-H30011 | \$ 1,290.00 | 6% | <i>\$1,221.69</i> |
| EWPP PremierPLS NBD AHR H30012 | 98504-H30012 | \$ 1,345.00 | 6% | <i>\$1,273.78</i> |
| EWPP PremierPLS NBD AHR H30131 | 98504-H30131 | \$ 2,274.00 | 6% | <i>\$2,153.59</i> |
| EWPP PremierPLS NBD AHR H30132 | 98504-H30132 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWPP PremierPLS NBD AHR H30133 | 98504-H30133 | \$ 4,009.00 | 6% | <i>\$3,796.72</i> |
| EWPP PremierPLS NBD AHR H30134 | 98504-H30134 | \$ 4,768.00 | 6% | <i>\$4,515.53</i> |
| EWPP PremierPLS NBD AHR H30135 | 98504-H30135 | \$ 4,086.00 | 6% | <i>\$3,869.65</i> |
| EWPP PremierPLS NBD AHR H30136 | 98504-H30136 | \$ 4,768.00 | 6% | <i>\$4,515.53</i> |
| EWPP PremierPLS NBD AHR H30184 | 98504-H30184 | \$ 1,244.00 | 6% | <i>\$1,178.13</i> |
| EWPP PremierPLS NBD AHR H30185 | 98504-H30185 | \$ 1,478.00 | 6% | <i>\$1,399.74</i> |
| EWPP PremierPLS NBD AHR H30186 | 98504-H30186 | \$ 1,352.00 | 6% | <i>\$1,280.41</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H30187 | 98504-H30187 | \$ 1,329.00 | 6% | <i>\$1,258.63</i> |
| EWPP PremierPLS NBD AHR H30188 | 98504-H30188 | \$ 1,352.00 | 6% | <i>\$1,280.41</i> |
| EWPP PremierPLS NBD AHR H30189 | 98504-H30189 | \$ 1,352.00 | 6% | <i>\$1,280.41</i> |
| EWPP PremierPLS NBD AHR H30190 | 98504-H30190 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30214 | 98504-H30214 | \$ 1,416.00 | 6% | <i>\$1,341.02</i> |
| EWPP PremierPLS NBD AHR H30215 | 98504-H30215 | \$ 1,416.00 | 6% | <i>\$1,341.02</i> |
| EWPP PremierPLS NBD AHR H30216 | 98504-H30216 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30217 | 98504-H30217 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30218 | 98504-H30218 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30219 | 98504-H30219 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30220 | 98504-H30220 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30221 | 98504-H30221 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30222 | 98504-H30222 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30223 | 98504-H30223 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30224 | 98504-H30224 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30225 | 98504-H30225 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30226 | 98504-H30226 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30227 | 98504-H30227 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30228 | 98504-H30228 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30229 | 98504-H30229 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30267 | 98504-H30267 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H30268 | 98504-H30268 | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLS NBD AHR H30269 | 98504-H30269 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30270 | 98504-H30270 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30271 | 98504-H30271 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30272 | 98504-H30272 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30273 | 98504-H30273 | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| EWPP PremierPLS NBD AHR H30274 | 98504-H30274 | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| EWPP PremierPLS NBD AHR H30275 | 98504-H30275 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30276 | 98504-H30276 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30277 | 98504-H30277 | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| EWPP PremierPLS NBD AHR H30278 | 98504-H30278 | \$ 1,924.00 | 6% | <i>\$1,822.12</i> |
| EWPP PremierPLS NBD AHR H30279 | 98504-H30279 | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| EWPP PremierPLS NBD AHR H30280 | 98504-H30280 | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| EWPP PremierPLS NBD AHR H30281 | 98504-H30281 | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| EWPP PremierPLS NBD AHR H30282 | 98504-H30282 | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| EWPP PremierPLS NBD AHR H30283 | 98504-H30283 | \$ 1,562.00 | 6% | <i>\$1,479.29</i> |
| EWPP PremierPLS NBD AHR H30284 | 98504-H30284 | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS NBD AHR H30296 | 98504-H30296 | \$ 1,416.00 | 6% | <i>\$1,341.02</i> |
| EWPP PremierPLS NBD AHR H30297 | 98504-H30297 | \$ 1,416.00 | 6% | <i>\$1,341.02</i> |
| EWPP PremierPLS NBD AHR H30298 | 98504-H30298 | \$ 1,416.00 | 6% | <i>\$1,341.02</i> |
| EWPP PremierPLS NBD AHR H30299 | 98504-H30299 | \$ 1,416.00 | 6% | <i>\$1,341.02</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS NBD AHR H30381 | 98504-H30381 | \$ 2,520.00 | 6% | \$2,386.57 |
| EWPP PremierPLS NBD AHR H30384 | 98504-H30384 | \$ 2,440.00 | 6% | \$2,310.80 |
| EWPP PremierPLS NBD AHR H30391 | 98504-H30391 | \$ 1,177.00 | 6% | \$1,114.68 |
| EWPP PremierPLS NBD AHR H30392 | 98504-H30392 | \$ 1,177.00 | 6% | \$1,114.68 |
| EWPP PremierPLS NBD AHR H30393 | 98504-H30393 | \$ 761.00 | 6% | \$720.71 |
| EWPP PremierPLS NBD AHR H30394 | 98504-H30394 | \$ 1,870.00 | 6% | \$1,770.98 |
| EWPP PremierPLS NBD AHR H30395 | 98504-H30395 | \$ 2,155.00 | 6% | \$2,040.89 |
| EWPP PremierPLS NBD AHR H30396 | 98504-H30396 | \$ 1,996.00 | 6% | \$1,890.31 |
| EWPP PremierPLS NBD AHR H30397 | 98504-H30397 | \$ 2,294.00 | 6% | \$2,172.53 |
| EWPP PremierPLS NBD AHR H30398 | 98504-H30398 | \$ 776.00 | 6% | \$734.91 |
| EWPP PremierPLS NBD AHR H30400 | 98504-H30400 | \$ 610.00 | 6% | \$577.70 |
| EWPP PremierPLS NBD AHR H30401 | 98504-H30401 | \$ 696.00 | 6% | \$659.15 |
| EWPP PremierPLS NBD AHR H30402 | 98504-H30402 | \$ 708.00 | 6% | \$670.51 |
| EWPP PremierPLS NBD AHR H30403 | 98504-H30403 | \$ 846.00 | 6% | \$801.20 |
| EWPP PremierPLS NBD AHR H30480 | 98504-H30480 | \$ 2,571.00 | 6% | \$2,434.87 |
| EWPP PremierPLS NBD AHR H30495 | 98504-H30495 | \$ 3,229.00 | 6% | \$3,058.02 |
| EWPP PremierPLS NBD AHR H30496 | 98504-H30496 | \$ 3,168.00 | 6% | \$3,000.25 |
| EWPP PremierPLS NBD AHR H30497 | 98504-H30497 | \$ 3,724.00 | 6% | \$3,526.81 |
| EWPP PremierPLS NBD AHR H30498 | 98504-H30498 | \$ 3,654.00 | 6% | \$3,460.52 |
| EWPP PremierPLS NBD AHR H30499 | 98504-H30499 | \$ 970.00 | 6% | \$918.64 |
| EWPP PremierPLS NBD AHR H30501 | 98504-H30501 | \$ 3,654.00 | 6% | \$3,460.52 |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H30502 | 98504-H30502 | \$ 4,499.00 | 6% | <i>\$4,260.78</i> |
| EWPP PremierPLS NBD AHR H30503 | 98504-H30503 | \$ 970.00 | 6% | <i>\$918.64</i> |
| EWPP PremierPLS NBD AHR H30505 | 98504-H30505 | \$ 4,946.00 | 6% | <i>\$4,684.11</i> |
| EWPP PremierPLS NBD AHR H30506 | 98504-H30506 | \$ 5,976.00 | 6% | <i>\$5,659.57</i> |
| EWPP PremierPLS NBD AHR H30509 | 98504-H30509 | \$ 4,499.00 | 6% | <i>\$4,260.78</i> |
| EWPP PremierPLS NBD AHR H30510 | 98504-H30510 | \$ 4,946.00 | 6% | <i>\$4,684.11</i> |
| EWPP PremierPLS NBD AHR H30511 | 98504-H30511 | \$ 5,976.00 | 6% | <i>\$5,659.57</i> |
| EWPP PremierPLS NBD AHR H30512 | 98504-H30512 | \$ 970.00 | 6% | <i>\$918.64</i> |
| EWPP PremierPLS NBD AHR H30513 | 98504-H30513 | \$ 1,338.00 | 6% | <i>\$1,267.15</i> |
| EWPP PremierPLS NBD AHR H30525 | 98504-H30525 | \$ 4,317.00 | 6% | <i>\$4,088.41</i> |
| EWPP PremierPLS NBD AHR H30526 | 98504-H30526 | \$ 3,285.00 | 6% | <i>\$3,111.06</i> |
| EWPP PremierPLS NBD AHR H30528 | 98504-H30528 | \$ 4,933.00 | 6% | <i>\$4,671.80</i> |
| EWPP PremierPLS NBD AHR H30531 | 98504-H30531 | \$ 6,848.00 | 6% | <i>\$6,485.40</i> |
| EWPP PremierPLS NBD AHR H30532 | 98504-H30532 | \$ 6,848.00 | 6% | <i>\$6,485.40</i> |
| EWPP PremierPLS NBD AHR H30534 | 98504-H30534 | \$ 6,981.00 | 6% | <i>\$6,611.36</i> |
| EWPP PremierPLS NBD AHR H30535 | 98504-H30535 | \$ 7,411.00 | 6% | <i>\$7,018.59</i> |
| EWPP PremierPLS NBD AHR H30536 | 98504-H30536 | \$ 6,848.00 | 6% | <i>\$6,485.40</i> |
| EWPP PremierPLS NBD AHR H30537 | 98504-H30537 | \$ 7,411.00 | 6% | <i>\$7,018.59</i> |
| EWPP PremierPLS NBD AHR H30538 | 98504-H30538 | \$ 4,317.00 | 6% | <i>\$4,088.41</i> |
| EWPP PremierPLS NBD AHR H30539 | 98504-H30539 | \$ 7,916.00 | 6% | <i>\$7,496.85</i> |
| EWPP PremierPLS NBD AHR H30540 | 98504-H30540 | \$ 8,150.00 | 6% | <i>\$7,718.46</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H30543 | 98504-H30543 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPP PremierPLS NBD AHR H30544 | 98504-H30544 | \$ 1,365.00 | 6% | <i>\$1,292.72</i> |
| EWPP PremierPLS NBD AHR H30548 | 98504-H30548 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPP PremierPLS NBD AHR H30549 | 98504-H30549 | \$ 1,313.00 | 6% | <i>\$1,243.48</i> |
| EWPP PremierPLS NBD AHR H30550 | 98504-H30550 | \$ 1,313.00 | 6% | <i>\$1,243.48</i> |
| EWPP PremierPLS NBD AHR H30552 | 98504-H30552 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPP PremierPLS NBD AHR H30553 | 98504-H30553 | \$ 1,260.00 | 6% | <i>\$1,193.28</i> |
| EWPP PremierPLS NBD AHR H30569 | 98504-H30569 | \$ 4,009.00 | 6% | <i>\$3,796.72</i> |
| EWPP PremierPLS NBD AHR H30570 | 98504-H30570 | \$ 4,594.00 | 6% | <i>\$4,350.75</i> |
| EWPP PremierPLS NBD AHR H30571 | 98504-H30571 | \$ 4,594.00 | 6% | <i>\$4,350.75</i> |
| EWPP PremierPLS NBD AHR H30573 | 98504-H30573 | \$ 4,009.00 | 6% | <i>\$3,796.72</i> |
| EWPP PremierPLS NBD AHR H30574 | 98504-H30574 | \$ 4,333.00 | 6% | <i>\$4,103.57</i> |
| EWPP PremierPLS NBD AHR H30575 | 98504-H30575 | \$ 3,115.00 | 6% | <i>\$2,950.06</i> |
| EWPP PremierPLS NBD AHR H30576 | 98504-H30576 | \$ 4,009.00 | 6% | <i>\$3,796.72</i> |
| EWPP PremierPLS NBD AHR H30577 | 98504-H30577 | \$ 4,506.00 | 6% | <i>\$4,267.41</i> |
| EWPP PremierPLS NBD AHR H30578 | 98504-H30578 | \$ 4,506.00 | 6% | <i>\$4,267.41</i> |
| EWPP PremierPLS NBD AHR H30587 | 98504-H30587 | \$ 3,350.00 | 6% | <i>\$3,172.62</i> |
| EWPP PremierPLS NBD AHR H30588 | 98504-H30588 | \$ 2,440.00 | 6% | <i>\$2,310.80</i> |
| EWPP PremierPLS NBD AHR H30589 | 98504-H30589 | \$ 3,509.00 | 6% | <i>\$3,323.20</i> |
| EWPP PremierPLS NBD AHR H30632 | 98504-H30632 | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS NBD AHR H30633 | 98504-H30633 | \$ 415.00 | 6% | <i>\$393.03</i> |

| | | | | |
|--------------------------------|--------------|-------------|-----|-------------------|
| EWPP PremierPLS NBD AHR H30643 | 98504-H30643 | \$ 7,266.00 | 6% | <i>\$6,881.27</i> |
| EWPP PremierPLS NBD AHR H30706 | 98504-H30706 | \$ 5,028.00 | 6% | <i>\$4,761.77</i> |
| EWPP PremierPLS NBD AHR H30707 | 98504-H30707 | \$ 3,285.00 | 6% | <i>\$3,111.06</i> |
| EWPP PremierPLS NBD AHR H30724 | 98504-H30724 | \$ 643.00 | 6% | <i>\$608.95</i> |
| EWPP PremierPLS NBD AHR H30725 | 98504-H30725 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWPP PremierPLS NBD AHR H30726 | 98504-H30726 | \$ 7,556.00 | 6% | <i>\$7,155.91</i> |
| EWPP PremierPLS NBD AHR H30727 | 98504-H30727 | \$ 7,995.00 | 6% | <i>\$7,571.66</i> |
| EWPP PremierPLS NBD AHR H30730 | 98504-H30730 | \$ 400.00 | 6% | <i>\$378.82</i> |
| EWPP PremierPLS NBD AHR H30731 | 98504-H30731 | \$ 400.00 | 6% | <i>\$378.82</i> |
| EWPP PremierPLS NBD AHR H30733 | 98504-H30733 | \$ 8,343.00 | 6% | <i>\$7,901.24</i> |
| EWPP PremierPLS NBD AHR H30734 | 98504-H30734 | \$ 6,461.00 | 6% | <i>\$6,118.89</i> |
| EWPP PremierPLS NBD AHR H30735 | 98504-H30735 | \$ 7,115.00 | 6% | <i>\$6,738.26</i> |
| EWPP PremierPLS NBD AHR H30736 | 98504-H30736 | \$ 1,490.00 | 6% | <i>\$1,411.10</i> |
| EWPP PremierPLS NBD AHR H30738 | 98504-H30738 | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS NBD AHR H30787 | 98504-H30787 | \$ 305.00 | 10% | <i>\$276.56</i> |
| EWPP PremierPLS NBD AHR H30788 | 98504-H30788 | \$ 306.00 | 10% | <i>\$277.47</i> |
| EWPP PremierPLS NBD AHR H30791 | 98504-H30791 | \$ 292.00 | 10% | <i>\$264.77</i> |
| EWPP PremierPLS NBD AHR H30847 | 98504-H30847 | \$ 311.00 | 10% | <i>\$282.00</i> |
| EWPP PremierPLS NBD AHR H30848 | 98504-H30848 | \$ 311.00 | 10% | <i>\$282.00</i> |
| EWPP PremierPLS NBD AHR H30852 | 98504-H30852 | \$ 311.00 | 10% | <i>\$282.00</i> |
| EWPP PremierPLS NBD AHR H30857 | 98504-H30857 | \$ 358.00 | 10% | <i>\$324.62</i> |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EWPP PremierPLS NBD AHR H30869 | 98504-H30869 | \$ 491.00 | 10% | <i>\$445.21</i> |
| EWPP PremierPLS NBD AHR H30900 | 98504-H30900 | \$ 3,936.00 | 10% | <i>\$3,568.97</i> |
| EWPP PremierPLS NBD AHR H31337 | 98504-H31337 | \$ 11,899.00 | 6% | <i>\$11,268.95</i> |
| EWPP PremierPLS NBD AHR H31338 | 98504-H31338 | \$ 11,899.00 | 6% | <i>\$11,268.95</i> |
| EWPP PremierPLS NBD AHR H31341 | 98504-H31341 | \$ 6,500.00 | 6% | <i>\$6,155.83</i> |
| EWPP PremierPLS NBD AHR H31342 | 98504-H31342 | \$ 1,801.00 | 6% | <i>\$1,705.64</i> |
| EWPP PremierPLS NBD AHR H31343 | 98504-H31343 | \$ 2,455.00 | 6% | <i>\$2,325.01</i> |
| EWPP PremierPLS NBD AHR H31344 | 98504-H31344 | \$ 2,455.00 | 6% | <i>\$2,325.01</i> |
| EWPP PremierPLS NBD AHR H31345 | 98504-H31345 | \$ 2,455.00 | 6% | <i>\$2,325.01</i> |
| EWPP PremierPLS NBD AHR H31346 | 98504-H31346 | \$ 2,455.00 | 6% | <i>\$2,325.01</i> |
| EWPP PremierPLS NBD AHR H31362 | 98504-H31362 | \$ 29,530.00 | 6% | <i>\$27,966.39</i> |
| EWPP PremierPLS NBD AHR H31363 | 98504-H31363 | \$ 29,530.00 | 6% | <i>\$27,966.39</i> |
| EWPP PremierPLS NBD AHR H31364 | 98504-H31364 | \$ 11,149.00 | 6% | <i>\$10,558.66</i> |
| EWPP PremierPLS NBD AHR H31365 | 98504-H31365 | \$ 11,149.00 | 6% | <i>\$10,558.66</i> |
| EWPP PremierPLS NBD AHR H31366 | 98504-H31366 | \$ 15,428.00 | 6% | <i>\$14,611.09</i> |
| EWPP PremierPLS NBD AHR H31367 | 98504-H31367 | \$ 15,428.00 | 6% | <i>\$14,611.09</i> |
| EWPP PremierPLS NBD AHR H32010 | 98504-H32010 | \$ 1,786.00 | 6% | <i>\$1,691.43</i> |
| EWPP PremierPLS NBD AHR H32011 | 98504-H32011 | \$ 1,786.00 | 6% | <i>\$1,691.43</i> |
| EWPP PremierPLS NBD AHR H32012 | 98504-H32012 | \$ 3,803.00 | 6% | <i>\$3,601.63</i> |
| EWPP PremierPLS NBD AHR H32013 | 98504-H32013 | \$ 3,919.00 | 6% | <i>\$3,711.49</i> |
| EWPP PremierPLS NBD AHR H32014 | 98504-H32014 | \$ 3,919.00 | 6% | <i>\$3,711.49</i> |

| | | | | |
|--------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR H32015 | 98504-H32015 | \$ 3,919.00 | 6% | <i>\$3,711.49</i> |
| EWPP PremierPLS NBD AHR H32016 | 98504-H32016 | \$ 3,672.00 | 6% | <i>\$3,477.57</i> |
| EWPP PremierPLS NBD AHR H32017 | 98504-H32017 | \$ 3,672.00 | 6% | <i>\$3,477.57</i> |
| EWPP PremierPLS NBD AHR H32018 | 98504-H32018 | \$ 3,672.00 | 6% | <i>\$3,477.57</i> |
| EWPP PremierPLS NBD AHR H32019 | 98504-H32019 | \$ 3,672.00 | 6% | <i>\$3,477.57</i> |
| EWPP PremierPLS NBD AHR H32020 | 98504-H32020 | \$ 30,088.00 | 6% | <i>\$28,494.84</i> |
| EWPP PremierPLS NBD AHR H32021 | 98504-H32021 | \$ 30,088.00 | 6% | <i>\$28,494.84</i> |
| EWPP PremierPLS NBD AHR H32022 | 98504-H32022 | \$ 30,088.00 | 6% | <i>\$28,494.84</i> |
| EWPP PremierPLS NBD AHR H32023 | 98504-H32023 | \$ 30,088.00 | 6% | <i>\$28,494.84</i> |
| EWPP PremierPLS NBD AHR H32028 | 98504-H32028 | \$ 56,118.00 | 6% | <i>\$53,146.55</i> |
| EWPP PremierPLS NBD AHR H32029 | 98504-H32029 | \$ 56,118.00 | 6% | <i>\$53,146.55</i> |
| EWPP PremierPLS NBD AHR H32030 | 98504-H32030 | \$ 58,855.00 | 6% | <i>\$55,738.63</i> |
| EWPP PremierPLS NBD AHR H32031 | 98504-H32031 | \$ 58,855.00 | 6% | <i>\$55,738.63</i> |
| EWPP PremierPLS NBD AHR H32032 | 98504-H32032 | \$ 58,855.00 | 6% | <i>\$55,738.63</i> |
| EWPP PremierPLS NBD AHR H32033 | 98504-H32033 | \$ 58,855.00 | 6% | <i>\$55,738.63</i> |
| EWPP PremierPLS NBD AHR H32038 | 98504-H32038 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWPP PremierPLS NBD AHR H32039 | 98504-H32039 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWPP PremierPLS NBD AHR H32040 | 98504-H32040 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWPP PremierPLS NBD AHR H32041 | 98504-H32041 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWPP PremierPLS NBD AHR H32046 | 98504-H32046 | \$ 15,606.00 | 6% | <i>\$14,779.66</i> |
| EWPP PremierPLS NBD AHR H32047 | 98504-H32047 | \$ 15,606.00 | 6% | <i>\$14,779.66</i> |

| | | | | |
|--------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR H32048 | 98504-H32048 | \$ 15,606.00 | 6% | <i>\$14,779.66</i> |
| EWPP PremierPLS NBD AHR H32049 | 98504-H32049 | \$ 15,606.00 | 6% | <i>\$14,779.66</i> |
| EWPP PremierPLS NBD AHR H32054 | 98504-H32054 | \$ 11,279.00 | 6% | <i>\$10,681.78</i> |
| EWPP PremierPLS NBD AHR H32055 | 98504-H32055 | \$ 15,606.00 | 6% | <i>\$14,779.66</i> |
| EWPP PremierPLS NBD AHR H32056 | 98504-H32056 | \$ 4,122.00 | 6% | <i>\$3,903.74</i> |
| EWPP PremierPLS NBD AHR H32057 | 98504-H32057 | \$ 4,122.00 | 6% | <i>\$3,903.74</i> |
| EWPP PremierPLS NBD AHR H32058 | 98504-H32058 | \$ 4,122.00 | 6% | <i>\$3,903.74</i> |
| EWPP PremierPLS NBD AHR H32059 | 98504-H32059 | \$ 4,122.00 | 6% | <i>\$3,903.74</i> |
| EWPP PremierPLS NBD AHR H32060 | 98504-H32060 | \$ 4,515.00 | 6% | <i>\$4,275.93</i> |
| EWPP PremierPLS NBD AHR H32061 | 98504-H32061 | \$ 4,741.00 | 6% | <i>\$4,489.96</i> |
| EWPP PremierPLS NBD AHR H32062 | 98504-H32062 | \$ 4,515.00 | 6% | <i>\$4,275.93</i> |
| EWPP PremierPLS NBD AHR H32063 | 98504-H32063 | \$ 4,520.00 | 6% | <i>\$4,280.67</i> |
| EWPP PremierPLS NBD AHR H32064 | 98504-H32064 | \$ 4,515.00 | 6% | <i>\$4,275.93</i> |
| EWPP PremierPLS NBD AHR H32065 | 98504-H32065 | \$ 4,937.00 | 6% | <i>\$4,675.59</i> |
| EWPP PremierPLS NBD AHR H32066 | 98504-H32066 | \$ 4,937.00 | 6% | <i>\$4,675.59</i> |
| EWPP PremierPLS NBD AHR H32067 | 98504-H32067 | \$ 4,937.00 | 6% | <i>\$4,675.59</i> |
| EWPP PremierPLS NBD AHR H32068 | 98504-H32068 | \$ 4,937.00 | 6% | <i>\$4,675.59</i> |
| EWPP PremierPLS NBD AHR H32069 | 98504-H32069 | \$ 5,775.00 | 6% | <i>\$5,469.21</i> |
| EWPP PremierPLS NBD AHR H32070 | 98504-H32070 | \$ 5,775.00 | 6% | <i>\$5,469.21</i> |
| EWPP PremierPLS NBD AHR H32071 | 98504-H32071 | \$ 5,775.00 | 6% | <i>\$5,469.21</i> |
| EWPP PremierPLS NBD AHR H32072 | 98504-H32072 | \$ 5,775.00 | 6% | <i>\$5,469.21</i> |

| | | | | |
|--------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR H32073 | 98504-H32073 | \$ 36,629.00 | 6% | <i>\$34,689.49</i> |
| EWPP PremierPLS NBD AHR H32074 | 98504-H32074 | \$ 36,629.00 | 6% | <i>\$34,689.49</i> |
| EWPP PremierPLS NBD AHR H32075 | 98504-H32075 | \$ 49,837.00 | 6% | <i>\$47,198.13</i> |
| EWPP PremierPLS NBD AHR H32076 | 98504-H32076 | \$ 49,363.00 | 6% | <i>\$46,749.23</i> |
| EWPP PremierPLS NBD AHR H32101 | 98504-H32101 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32102 | 98504-H32102 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32103 | 98504-H32103 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32104 | 98504-H32104 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32105 | 98504-H32105 | \$ 4,392.00 | 6% | <i>\$4,159.44</i> |
| EWPP PremierPLS NBD AHR H32106 | 98504-H32106 | \$ 4,392.00 | 6% | <i>\$4,159.44</i> |
| EWPP PremierPLS NBD AHR H32107 | 98504-H32107 | \$ 9,214.00 | 6% | <i>\$8,726.12</i> |
| EWPP PremierPLS NBD AHR H32108 | 98504-H32108 | \$ 9,214.00 | 6% | <i>\$8,726.12</i> |
| EWPP PremierPLS NBD AHR H32109 | 98504-H32109 | \$ 4,392.00 | 6% | <i>\$4,159.44</i> |
| EWPP PremierPLS NBD AHR H32110 | 98504-H32110 | \$ 4,392.00 | 6% | <i>\$4,159.44</i> |
| EWPP PremierPLS NBD AHR H32111 | 98504-H32111 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32112 | 98504-H32112 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32113 | 98504-H32113 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32114 | 98504-H32114 | \$ 2,980.00 | 6% | <i>\$2,822.21</i> |
| EWPP PremierPLS NBD AHR H32115 | 98504-H32115 | \$ 4,392.00 | 6% | <i>\$4,159.44</i> |
| EWPP PremierPLS NBD AHR H32116 | 98504-H32116 | \$ 4,392.00 | 6% | <i>\$4,159.44</i> |
| EWPP PremierPLS NBD AHR H32117 | 98504-H32117 | \$ 2,892.00 | 6% | <i>\$2,738.87</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS NBD AHR H32118 | 98504-H32118 | \$ 2,892.00 | 6% | \$2,738.87 |
| EWPP PremierPLS NBD AHR H32119 | 98504-H32119 | \$ 2,892.00 | 6% | \$2,738.87 |
| EWPP PremierPLS NBD AHR H32120 | 98504-H32120 | \$ 2,892.00 | 6% | \$2,738.87 |
| EWPP PremierPLS NBD AHR H32121 | 98504-H32121 | \$ 9,214.00 | 6% | \$8,726.12 |
| EWPP PremierPLS NBD AHR H32122 | 98504-H32122 | \$ 9,214.00 | 6% | \$8,726.12 |
| EWPP PremierPLS NBD AHR H32123 | 98504-H32123 | \$ 4,392.00 | 6% | \$4,159.44 |
| EWPP PremierPLS NBD AHR H32124 | 98504-H32124 | \$ 4,392.00 | 6% | \$4,159.44 |
| EWPP PremierPLS NBD AHR H32125 | 98504-H32125 | \$ 4,246.00 | 6% | \$4,021.17 |
| EWPP PremierPLS NBD AHR H32126 | 98504-H32126 | \$ 4,246.00 | 6% | \$4,021.17 |
| EWPP PremierPLS NBD AHR H32127 | 98504-H32127 | \$ 4,740.00 | 6% | \$4,489.02 |
| EWPP PremierPLS NBD AHR H32128 | 98504-H32128 | \$ 4,740.00 | 6% | \$4,489.02 |
| EWPP PremierPLS NBD AHR H32129 | 98504-H32129 | \$ 4,740.00 | 6% | \$4,489.02 |
| EWPP PremierPLS NBD AHR H32130 | 98504-H32130 | \$ 4,740.00 | 6% | \$4,489.02 |
| EWPP PremierPLS NBD AHR H32131 | 98504-H32131 | \$ 4,740.00 | 6% | \$4,489.02 |
| EWPP PremierPLS NBD AHR H32132 | 98504-H32132 | \$ 4,740.00 | 6% | \$4,489.02 |
| EWPP PremierPLS NBD AHR H32133 | 98504-H32133 | \$ 4,246.00 | 6% | \$4,021.17 |
| EWPP PremierPLS NBD AHR H32134 | 98504-H32134 | \$ 4,246.00 | 6% | \$4,021.17 |
| EWPP PremierPLS NBD AHR H32135 | 98504-H32135 | \$ 4,246.00 | 6% | \$4,021.17 |
| EWPP PremierPLS NBD AHR H32136 | 98504-H32136 | \$ 4,246.00 | 6% | \$4,021.17 |
| EWPP PremierPLS NBD AHR H32137 | 98504-H32137 | \$ 4,246.00 | 6% | \$4,021.17 |
| EWPP PremierPLS NBD AHR H32138 | 98504-H32138 | \$ 4,246.00 | 6% | \$4,021.17 |

| | | | | |
|--------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR H32139 | 98504-H32139 | \$ 15,418.00 | 6% | <i>\$14,601.62</i> |
| EWPP PremierPLS NBD AHR H32140 | 98504-H32140 | \$ 15,418.00 | 6% | <i>\$14,601.62</i> |
| EWPP PremierPLS NBD AHR H32141 | 98504-H32141 | \$ 18,451.00 | 6% | <i>\$17,474.02</i> |
| EWPP PremierPLS NBD AHR H32142 | 98504-H32142 | \$ 18,451.00 | 6% | <i>\$17,474.02</i> |
| EWPP PremierPLS NBD AHR H32146 | 98504-H32146 | \$ 2,823.00 | 6% | <i>\$2,673.52</i> |
| EWPP PremierPLS NBD AHR H32147 | 98504-H32147 | \$ 2,823.00 | 6% | <i>\$2,673.52</i> |
| EWPP PremierPLS NBD AHR H32148 | 98504-H32148 | \$ 4,161.00 | 6% | <i>\$3,940.68</i> |
| EWPP PremierPLS NBD AHR H32149 | 98504-H32149 | \$ 4,161.00 | 6% | <i>\$3,940.68</i> |
| EWPP PremierPLS NBD AHR H32150 | 98504-H32150 | \$ 2,823.00 | 6% | <i>\$2,673.52</i> |
| EWPP PremierPLS NBD AHR H32152 | 98504-H32152 | \$ 1,961.00 | 6% | <i>\$1,857.17</i> |
| EWPP PremierPLS NBD AHR H32169 | 98504-H32169 | \$ 2,957.00 | 6% | <i>\$2,800.43</i> |
| EWPP PremierPLS NBD AHR H32170 | 98504-H32170 | \$ 2,957.00 | 6% | <i>\$2,800.43</i> |
| EWPP PremierPLS NBD AHR H32171 | 98504-H32171 | \$ 2,870.00 | 6% | <i>\$2,718.03</i> |
| EWPP PremierPLS NBD AHR H32172 | 98504-H32172 | \$ 2,870.00 | 6% | <i>\$2,718.03</i> |
| EWPP PremierPLS NBD AHR H32173 | 98504-H32173 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWPP PremierPLS NBD AHR H32174 | 98504-H32174 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWPP PremierPLS NBD AHR H32175 | 98504-H32175 | \$ 4,527.00 | 6% | <i>\$4,287.30</i> |
| EWPP PremierPLS NBD AHR H32176 | 98504-H32176 | \$ 4,527.00 | 6% | <i>\$4,287.30</i> |
| EWPP PremierPLS NBD AHR H32177 | 98504-H32177 | \$ 16,942.00 | 6% | <i>\$16,044.92</i> |
| EWPP PremierPLS NBD AHR H32178 | 98504-H32178 | \$ 20,274.00 | 6% | <i>\$19,200.49</i> |
| EWPP PremierPLS NBD AHR H34008 | 98504-H34008 | \$ 1,261.00 | 6% | <i>\$1,194.23</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H34009 | 98504-H34009 | \$ 1,334.00 | 6% | <i>\$1,263.36</i> |
| EWPP PremierPLS NBD AHR H34010 | 98504-H34010 | \$ 1,188.00 | 6% | <i>\$1,125.10</i> |
| EWPP PremierPLS NBD AHR H34011 | 98504-H34011 | \$ 1,321.00 | 6% | <i>\$1,251.05</i> |
| EWPP PremierPLS NBD AHR H34012 | 98504-H34012 | \$ 1,401.00 | 6% | <i>\$1,326.82</i> |
| EWPP PremierPLS NBD AHR H34013 | 98504-H34013 | \$ 1,291.00 | 6% | <i>\$1,222.64</i> |
| EWPP PremierPLS NBD AHR H34014 | 98504-H34014 | \$ 1,334.00 | 6% | <i>\$1,263.36</i> |
| EWPP PremierPLS NBD AHR H34015 | 98504-H34015 | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWPP PremierPLS NBD AHR H34016 | 98504-H34016 | \$ 1,346.00 | 6% | <i>\$1,274.73</i> |
| EWPP PremierPLS NBD AHR H34017 | 98504-H34017 | \$ 1,434.00 | 6% | <i>\$1,358.07</i> |
| EWPP PremierPLS NBD AHR H34018 | 98504-H34018 | \$ 1,293.00 | 6% | <i>\$1,224.54</i> |
| EWPP PremierPLS NBD AHR H34019 | 98504-H34019 | \$ 1,293.00 | 6% | <i>\$1,224.54</i> |
| EWPP PremierPLS NBD AHR H34020 | 98504-H34020 | \$ 1,293.00 | 6% | <i>\$1,224.54</i> |
| EWPP PremierPLS NBD AHR H34021 | 98504-H34021 | \$ 1,293.00 | 6% | <i>\$1,224.54</i> |
| EWPP PremierPLS NBD AHR H34048 | 98504-H34048 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |
| EWPP PremierPLS NBD AHR H34049 | 98504-H34049 | \$ 1,524.00 | 6% | <i>\$1,443.30</i> |
| EWPP PremierPLS NBD AHR H34050 | 98504-H34050 | \$ 1,437.00 | 6% | <i>\$1,360.91</i> |
| EWPP PremierPLS NBD AHR H34051 | 98504-H34051 | \$ 1,437.00 | 6% | <i>\$1,360.91</i> |
| EWPP PremierPLS NBD AHR H34052 | 98504-H34052 | \$ 1,570.00 | 6% | <i>\$1,486.87</i> |
| EWPP PremierPLS NBD AHR H34053 | 98504-H34053 | \$ 1,570.00 | 6% | <i>\$1,486.87</i> |
| EWPP PremierPLS NBD AHR H34054 | 98504-H34054 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| EWPP PremierPLS NBD AHR H34055 | 98504-H34055 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H34056 | 98504-H34056 | \$ 1,713.00 | 6% | <i>\$1,622.30</i> |
| EWPP PremierPLS NBD AHR H34057 | 98504-H34057 | \$ 1,713.00 | 6% | <i>\$1,622.30</i> |
| EWPP PremierPLS NBD AHR H34058 | 98504-H34058 | \$ 1,661.00 | 6% | <i>\$1,573.05</i> |
| EWPP PremierPLS NBD AHR H34059 | 98504-H34059 | \$ 1,661.00 | 6% | <i>\$1,573.05</i> |
| EWPP PremierPLS NBD AHR H34062 | 98504-H34062 | \$ 1,713.00 | 6% | <i>\$1,622.30</i> |
| EWPP PremierPLS NBD AHR H34063 | 98504-H34063 | \$ 1,713.00 | 6% | <i>\$1,622.30</i> |
| EWPP PremierPLS NBD AHR H34064 | 98504-H34064 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWPP PremierPLS NBD AHR H34065 | 98504-H34065 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWPP PremierPLS NBD AHR H34066 | 98504-H34066 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWPP PremierPLS NBD AHR H34067 | 98504-H34067 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWPP PremierPLS NBD AHR H34068 | 98504-H34068 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWPP PremierPLS NBD AHR H34069 | 98504-H34069 | \$ 1,428.00 | 6% | <i>\$1,352.39</i> |
| EWPP PremierPLS NBD AHR H34070 | 98504-H34070 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWPP PremierPLS NBD AHR H34071 | 98504-H34071 | \$ 1,442.00 | 6% | <i>\$1,365.65</i> |
| EWPP PremierPLS NBD AHR H34072 | 98504-H34072 | \$ 3,648.00 | 6% | <i>\$3,454.84</i> |
| EWPP PremierPLS NBD AHR H34073 | 98504-H34073 | \$ 3,577.00 | 6% | <i>\$3,387.60</i> |
| EWPP PremierPLS NBD AHR H34074 | 98504-H34074 | \$ 4,481.00 | 6% | <i>\$4,243.73</i> |
| EWPP PremierPLS NBD AHR H34075 | 98504-H34075 | \$ 4,351.00 | 6% | <i>\$4,120.61</i> |
| EWPP PremierPLS NBD AHR H34076 | 98504-H34076 | \$ 3,648.00 | 6% | <i>\$3,454.84</i> |
| EWPP PremierPLS NBD AHR H34077 | 98504-H34077 | \$ 3,577.00 | 6% | <i>\$3,387.60</i> |
| EWPP PremierPLS NBD AHR H34078 | 98504-H34078 | \$ 3,648.00 | 6% | <i>\$3,454.84</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H34079 | 98504-H34079 | \$ 3,577.00 | 6% | <i>\$3,387.60</i> |
| EWPP PremierPLS NBD AHR H34080 | 98504-H34080 | \$ 4,481.00 | 6% | <i>\$4,243.73</i> |
| EWPP PremierPLS NBD AHR H34081 | 98504-H34081 | \$ 4,351.00 | 6% | <i>\$4,120.61</i> |
| EWPP PremierPLS NBD AHR H34082 | 98504-H34082 | \$ 4,278.00 | 6% | <i>\$4,051.48</i> |
| EWPP PremierPLS NBD AHR H34083 | 98504-H34083 | \$ 4,153.00 | 6% | <i>\$3,933.10</i> |
| EWPP PremierPLS NBD AHR H34084 | 98504-H34084 | \$ 3,152.00 | 6% | <i>\$2,985.10</i> |
| EWPP PremierPLS NBD AHR H34085 | 98504-H34085 | \$ 3,152.00 | 6% | <i>\$2,985.10</i> |
| EWPP PremierPLS NBD AHR H34086 | 98504-H34086 | \$ 3,688.00 | 6% | <i>\$3,492.72</i> |
| EWPP PremierPLS NBD AHR H34087 | 98504-H34087 | \$ 3,521.00 | 6% | <i>\$3,334.56</i> |
| EWPP PremierPLS NBD AHR H34088 | 98504-H34088 | \$ 6,842.00 | 6% | <i>\$6,479.72</i> |
| EWPP PremierPLS NBD AHR H34089 | 98504-H34089 | \$ 6,842.00 | 6% | <i>\$6,479.72</i> |
| EWPP PremierPLS NBD AHR H34090 | 98504-H34090 | \$ 7,878.00 | 6% | <i>\$7,460.86</i> |
| EWPP PremierPLS NBD AHR H34091 | 98504-H34091 | \$ 7,061.00 | 6% | <i>\$6,687.12</i> |
| EWPP PremierPLS NBD AHR H34092 | 98504-H34092 | \$ 7,061.00 | 6% | <i>\$6,687.12</i> |
| EWPP PremierPLS NBD AHR H34093 | 98504-H34093 | \$ 7,061.00 | 6% | <i>\$6,687.12</i> |
| EWPP PremierPLS NBD AHR H34094 | 98504-H34094 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS NBD AHR H34095 | 98504-H34095 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS NBD AHR H34096 | 98504-H34096 | \$ 902.00 | 6% | <i>\$854.24</i> |
| EWPP PremierPLS NBD AHR H34097 | 98504-H34097 | \$ 902.00 | 6% | <i>\$854.24</i> |
| EWPP PremierPLS NBD AHR H34098 | 98504-H34098 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS NBD AHR H34099 | 98504-H34099 | \$ 848.00 | 6% | <i>\$803.10</i> |

| | | | | |
|--------------------------------|--------------|--------------|----|-------------------|
| EWPP PremierPLS NBD AHR H34100 | 98504-H34100 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS NBD AHR H34101 | 98504-H34101 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS NBD AHR H34102 | 98504-H34102 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS NBD AHR H34103 | 98504-H34103 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS NBD AHR H34104 | 98504-H34104 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWPP PremierPLS NBD AHR H34105 | 98504-H34105 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWPP PremierPLS NBD AHR H34106 | 98504-H34106 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWPP PremierPLS NBD AHR H34107 | 98504-H34107 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWPP PremierPLS NBD AHR H34108 | 98504-H34108 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWPP PremierPLS NBD AHR H34109 | 98504-H34109 | \$ 621.00 | 6% | <i>\$588.12</i> |
| EWPP PremierPLS NBD AHR H34110 | 98504-H34110 | \$ 6,768.00 | 6% | <i>\$6,409.63</i> |
| EWPP PremierPLS NBD AHR H34111 | 98504-H34111 | \$ 6,768.00 | 6% | <i>\$6,409.63</i> |
| EWPP PremierPLS NBD AHR H34112 | 98504-H34112 | \$ 6,768.00 | 6% | <i>\$6,409.63</i> |
| EWPP PremierPLS NBD AHR H34114 | 98504-H34114 | \$ 10,372.00 | 6% | <i>\$9,822.80</i> |
| EWPP PremierPLS NBD AHR H34115 | 98504-H34115 | \$ 9,947.00 | 6% | <i>\$9,420.31</i> |
| EWPP PremierPLS NBD AHR H34116 | 98504-H34116 | \$ 9,947.00 | 6% | <i>\$9,420.31</i> |
| EWPP PremierPLS NBD AHR H34117 | 98504-H34117 | \$ 10,372.00 | 6% | <i>\$9,822.80</i> |
| EWPP PremierPLS NBD AHR H34118 | 98504-H34118 | \$ 1,542.00 | 6% | <i>\$1,460.35</i> |
| EWPP PremierPLS NBD AHR H34119 | 98504-H34119 | \$ 1,542.00 | 6% | <i>\$1,460.35</i> |
| EWPP PremierPLS NBD AHR H34120 | 98504-H34120 | \$ 1,199.00 | 6% | <i>\$1,135.51</i> |
| EWPP PremierPLS NBD AHR H34121 | 98504-H34121 | \$ 1,199.00 | 6% | <i>\$1,135.51</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H34122 | 98504-H34122 | \$ 1,229.00 | 6% | <i>\$1,163.92</i> |
| EWPP PremierPLS NBD AHR H34123 | 98504-H34123 | \$ 1,229.00 | 6% | <i>\$1,163.92</i> |
| EWPP PremierPLS NBD AHR H34124 | 98504-H34124 | \$ 1,625.00 | 6% | <i>\$1,538.96</i> |
| EWPP PremierPLS NBD AHR H34125 | 98504-H34125 | \$ 1,625.00 | 6% | <i>\$1,538.96</i> |
| EWPP PremierPLS NBD AHR H34126 | 98504-H34126 | \$ 1,625.00 | 6% | <i>\$1,538.96</i> |
| EWPP PremierPLS NBD AHR H34127 | 98504-H34127 | \$ 1,625.00 | 6% | <i>\$1,538.96</i> |
| EWPP PremierPLS NBD AHR H34129 | 98504-H34129 | \$ 1,470.00 | 6% | <i>\$1,392.16</i> |
| EWPP PremierPLS NBD AHR H34130 | 98504-H34130 | \$ 1,527.00 | 6% | <i>\$1,446.15</i> |
| EWPP PremierPLS NBD AHR H34131 | 98504-H34131 | \$ 1,527.00 | 6% | <i>\$1,446.15</i> |
| EWPP PremierPLS NBD AHR H34132 | 98504-H34132 | \$ 1,527.00 | 6% | <i>\$1,446.15</i> |
| EWPP PremierPLS NBD AHR H34172 | 98504-H34172 | \$ 1,964.00 | 6% | <i>\$1,860.01</i> |
| EWPP PremierPLS NBD AHR H34174 | 98504-H34174 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34175 | 98504-H34175 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34176 | 98504-H34176 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34177 | 98504-H34177 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34178 | 98504-H34178 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34179 | 98504-H34179 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34180 | 98504-H34180 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34181 | 98504-H34181 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34182 | 98504-H34182 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34183 | 98504-H34183 | \$ 382.00 | 6% | <i>\$361.77</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34184 | 98504-H34184 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34185 | 98504-H34185 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34186 | 98504-H34186 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34187 | 98504-H34187 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34188 | 98504-H34188 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34189 | 98504-H34189 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34190 | 98504-H34190 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34191 | 98504-H34191 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34192 | 98504-H34192 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34193 | 98504-H34193 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34194 | 98504-H34194 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34195 | 98504-H34195 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34196 | 98504-H34196 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34197 | 98504-H34197 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34198 | 98504-H34198 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34199 | 98504-H34199 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34200 | 98504-H34200 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34201 | 98504-H34201 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34202 | 98504-H34202 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34203 | 98504-H34203 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34204 | 98504-H34204 | \$ 382.00 | 6% | <i>\$361.77</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34205 | 98504-H34205 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34206 | 98504-H34206 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34207 | 98504-H34207 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34208 | 98504-H34208 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34209 | 98504-H34209 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34210 | 98504-H34210 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34211 | 98504-H34211 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34212 | 98504-H34212 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34213 | 98504-H34213 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34214 | 98504-H34214 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34215 | 98504-H34215 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34216 | 98504-H34216 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34217 | 98504-H34217 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34218 | 98504-H34218 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34219 | 98504-H34219 | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS NBD AHR H34220 | 98504-H34220 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34221 | 98504-H34221 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34222 | 98504-H34222 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34223 | 98504-H34223 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34224 | 98504-H34224 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34225 | 98504-H34225 | \$ 403.00 | 6% | <i>\$381.66</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34226 | 98504-H34226 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34227 | 98504-H34227 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34228 | 98504-H34228 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34229 | 98504-H34229 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34230 | 98504-H34230 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34231 | 98504-H34231 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34232 | 98504-H34232 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34233 | 98504-H34233 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34234 | 98504-H34234 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34235 | 98504-H34235 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34236 | 98504-H34236 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34237 | 98504-H34237 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34238 | 98504-H34238 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34239 | 98504-H34239 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34240 | 98504-H34240 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34241 | 98504-H34241 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34242 | 98504-H34242 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34243 | 98504-H34243 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34244 | 98504-H34244 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34245 | 98504-H34245 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34246 | 98504-H34246 | \$ 403.00 | 6% | <i>\$381.66</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34247 | 98504-H34247 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34248 | 98504-H34248 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34249 | 98504-H34249 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34250 | 98504-H34250 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34251 | 98504-H34251 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34252 | 98504-H34252 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34253 | 98504-H34253 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34254 | 98504-H34254 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34255 | 98504-H34255 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34256 | 98504-H34256 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34257 | 98504-H34257 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34258 | 98504-H34258 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34259 | 98504-H34259 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34260 | 98504-H34260 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34261 | 98504-H34261 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34262 | 98504-H34262 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34263 | 98504-H34263 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34264 | 98504-H34264 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34265 | 98504-H34265 | \$ 403.00 | 6% | <i>\$381.66</i> |
| EWPP PremierPLS NBD AHR H34266 | 98504-H34266 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34267 | 98504-H34267 | \$ 385.00 | 6% | <i>\$364.61</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34268 | 98504-H34268 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34269 | 98504-H34269 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34270 | 98504-H34270 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34271 | 98504-H34271 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34272 | 98504-H34272 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34273 | 98504-H34273 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34274 | 98504-H34274 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34275 | 98504-H34275 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34276 | 98504-H34276 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34277 | 98504-H34277 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34278 | 98504-H34278 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34279 | 98504-H34279 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34280 | 98504-H34280 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34281 | 98504-H34281 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34282 | 98504-H34282 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34283 | 98504-H34283 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34284 | 98504-H34284 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34285 | 98504-H34285 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34286 | 98504-H34286 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34287 | 98504-H34287 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34288 | 98504-H34288 | \$ 385.00 | 6% | <i>\$364.61</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34289 | 98504-H34289 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34290 | 98504-H34290 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34291 | 98504-H34291 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34292 | 98504-H34292 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34293 | 98504-H34293 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34294 | 98504-H34294 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34295 | 98504-H34295 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34296 | 98504-H34296 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34297 | 98504-H34297 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34298 | 98504-H34298 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34299 | 98504-H34299 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34300 | 98504-H34300 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34301 | 98504-H34301 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34302 | 98504-H34302 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34303 | 98504-H34303 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34304 | 98504-H34304 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34305 | 98504-H34305 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H34306 | 98504-H34306 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34307 | 98504-H34307 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34308 | 98504-H34308 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34309 | 98504-H34309 | \$ 411.00 | 6% | <i>\$389.24</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34310 | 98504-H34310 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34311 | 98504-H34311 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34312 | 98504-H34312 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34313 | 98504-H34313 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34314 | 98504-H34314 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34315 | 98504-H34315 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34316 | 98504-H34316 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34317 | 98504-H34317 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34318 | 98504-H34318 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34319 | 98504-H34319 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34320 | 98504-H34320 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34321 | 98504-H34321 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34322 | 98504-H34322 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34323 | 98504-H34323 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34324 | 98504-H34324 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34325 | 98504-H34325 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34326 | 98504-H34326 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34327 | 98504-H34327 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34328 | 98504-H34328 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34329 | 98504-H34329 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34330 | 98504-H34330 | \$ 411.00 | 6% | \$389.24 |

| | | | | |
|-----------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34331 | 98504-H34331 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34332 | 98504-H34332 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34333 | 98504-H34333 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34334 | 98504-H34334 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34335 | 98504-H34335 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34336 | 98504-H34336 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34337 | 98504-H34337 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34338 | 98504-H34338 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34339 | 98504-H34339 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34340 | 98504-H34340 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34341 | 98504-H34341 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34342 | 98504-H34342 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34343 | 98504-H34343 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34344 | 98504-H34344 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34345 | 98504-H34345 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34346 | 98504-H34346 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34347 | 98504-H34347 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34348 | 98504-H34348 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34349 | 98504-H34349 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34350 | 98504-H34350 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34351 | 98504-H34351 | \$ 411.00 | 6% | \$389.24 |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34352 | 98504-H34352 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34353 | 98504-H34353 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34354 | 98504-H34354 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34355 | 98504-H34355 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34356 | 98504-H34356 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34357 | 98504-H34357 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34358 | 98504-H34358 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34359 | 98504-H34359 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34360 | 98504-H34360 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34361 | 98504-H34361 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34362 | 98504-H34362 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34363 | 98504-H34363 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34364 | 98504-H34364 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34365 | 98504-H34365 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34366 | 98504-H34366 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34367 | 98504-H34367 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34368 | 98504-H34368 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34369 | 98504-H34369 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34370 | 98504-H34370 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34371 | 98504-H34371 | \$ 452.00 | 6% | \$428.07 |
| EWPP PremierPLS NBD AHR H34372 | 98504-H34372 | \$ 452.00 | 6% | \$428.07 |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34373 | 98504-H34373 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34374 | 98504-H34374 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34375 | 98504-H34375 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34376 | 98504-H34376 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34377 | 98504-H34377 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34378 | 98504-H34378 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34379 | 98504-H34379 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34380 | 98504-H34380 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34381 | 98504-H34381 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34382 | 98504-H34382 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34383 | 98504-H34383 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34384 | 98504-H34384 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34385 | 98504-H34385 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34386 | 98504-H34386 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34387 | 98504-H34387 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34388 | 98504-H34388 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34389 | 98504-H34389 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34390 | 98504-H34390 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34391 | 98504-H34391 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34392 | 98504-H34392 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34393 | 98504-H34393 | \$ 452.00 | 6% | <i>\$428.07</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34394 | 98504-H34394 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34395 | 98504-H34395 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34396 | 98504-H34396 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34397 | 98504-H34397 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34398 | 98504-H34398 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34399 | 98504-H34399 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34400 | 98504-H34400 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34401 | 98504-H34401 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34402 | 98504-H34402 | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS NBD AHR H34403 | 98504-H34403 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34404 | 98504-H34404 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34405 | 98504-H34405 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34406 | 98504-H34406 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34407 | 98504-H34407 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34408 | 98504-H34408 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34409 | 98504-H34409 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34410 | 98504-H34410 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34411 | 98504-H34411 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34412 | 98504-H34412 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34413 | 98504-H34413 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34414 | 98504-H34414 | \$ 521.00 | 6% | <i>\$493.41</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34415 | 98504-H34415 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34416 | 98504-H34416 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34417 | 98504-H34417 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34418 | 98504-H34418 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34419 | 98504-H34419 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34420 | 98504-H34420 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34421 | 98504-H34421 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34422 | 98504-H34422 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34423 | 98504-H34423 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34424 | 98504-H34424 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34425 | 98504-H34425 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34426 | 98504-H34426 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34427 | 98504-H34427 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34428 | 98504-H34428 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34429 | 98504-H34429 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34430 | 98504-H34430 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34431 | 98504-H34431 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34432 | 98504-H34432 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34433 | 98504-H34433 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34434 | 98504-H34434 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34435 | 98504-H34435 | \$ 521.00 | 6% | <i>\$493.41</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34436 | 98504-H34436 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34437 | 98504-H34437 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34438 | 98504-H34438 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34439 | 98504-H34439 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34440 | 98504-H34440 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34441 | 98504-H34441 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34442 | 98504-H34442 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34443 | 98504-H34443 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34444 | 98504-H34444 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34445 | 98504-H34445 | \$ 521.00 | 6% | <i>\$493.41</i> |
| EWPP PremierPLS NBD AHR H34446 | 98504-H34446 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34447 | 98504-H34447 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34448 | 98504-H34448 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34449 | 98504-H34449 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34450 | 98504-H34450 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34451 | 98504-H34451 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34452 | 98504-H34452 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34453 | 98504-H34453 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34454 | 98504-H34454 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34455 | 98504-H34455 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34456 | 98504-H34456 | \$ 551.00 | 6% | <i>\$521.82</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34457 | 98504-H34457 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34458 | 98504-H34458 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34459 | 98504-H34459 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34460 | 98504-H34460 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34461 | 98504-H34461 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34462 | 98504-H34462 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34463 | 98504-H34463 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34464 | 98504-H34464 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34465 | 98504-H34465 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34466 | 98504-H34466 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34467 | 98504-H34467 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34468 | 98504-H34468 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34469 | 98504-H34469 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34470 | 98504-H34470 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34471 | 98504-H34471 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34472 | 98504-H34472 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34473 | 98504-H34473 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34474 | 98504-H34474 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34475 | 98504-H34475 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34476 | 98504-H34476 | \$ 551.00 | 6% | <i>\$521.82</i> |
| EWPP PremierPLS NBD AHR H34477 | 98504-H34477 | \$ 551.00 | 6% | <i>\$521.82</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34478 | 98504-H34478 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34479 | 98504-H34479 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34480 | 98504-H34480 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34481 | 98504-H34481 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34482 | 98504-H34482 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34483 | 98504-H34483 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34484 | 98504-H34484 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34485 | 98504-H34485 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34486 | 98504-H34486 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34487 | 98504-H34487 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34488 | 98504-H34488 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34489 | 98504-H34489 | \$ 551.00 | 6% | \$521.82 |
| EWPP PremierPLS NBD AHR H34490 | 98504-H34490 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34491 | 98504-H34491 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34492 | 98504-H34492 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34493 | 98504-H34493 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34494 | 98504-H34494 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34495 | 98504-H34495 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34496 | 98504-H34496 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34497 | 98504-H34497 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34498 | 98504-H34498 | \$ 366.00 | 6% | \$346.62 |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34499 | 98504-H34499 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34500 | 98504-H34500 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34501 | 98504-H34501 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34502 | 98504-H34502 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34503 | 98504-H34503 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34504 | 98504-H34504 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34505 | 98504-H34505 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34506 | 98504-H34506 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34507 | 98504-H34507 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34508 | 98504-H34508 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34509 | 98504-H34509 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34510 | 98504-H34510 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34511 | 98504-H34511 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34512 | 98504-H34512 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34513 | 98504-H34513 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34514 | 98504-H34514 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34515 | 98504-H34515 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34516 | 98504-H34516 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34517 | 98504-H34517 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34518 | 98504-H34518 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34519 | 98504-H34519 | \$ 366.00 | 6% | \$346.62 |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34520 | 98504-H34520 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34521 | 98504-H34521 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34522 | 98504-H34522 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34523 | 98504-H34523 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34524 | 98504-H34524 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34525 | 98504-H34525 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34526 | 98504-H34526 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34527 | 98504-H34527 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34528 | 98504-H34528 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34529 | 98504-H34529 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34530 | 98504-H34530 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34531 | 98504-H34531 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34532 | 98504-H34532 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34533 | 98504-H34533 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34534 | 98504-H34534 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34535 | 98504-H34535 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34536 | 98504-H34536 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34537 | 98504-H34537 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34538 | 98504-H34538 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34539 | 98504-H34539 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34540 | 98504-H34540 | \$ 366.00 | 6% | \$346.62 |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34541 | 98504-H34541 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34542 | 98504-H34542 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34543 | 98504-H34543 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34544 | 98504-H34544 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34545 | 98504-H34545 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34546 | 98504-H34546 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34547 | 98504-H34547 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34548 | 98504-H34548 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34549 | 98504-H34549 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34550 | 98504-H34550 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34551 | 98504-H34551 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34552 | 98504-H34552 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34553 | 98504-H34553 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34554 | 98504-H34554 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34555 | 98504-H34555 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34556 | 98504-H34556 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34557 | 98504-H34557 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34558 | 98504-H34558 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34559 | 98504-H34559 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34560 | 98504-H34560 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34561 | 98504-H34561 | \$ 366.00 | 6% | \$346.62 |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34562 | 98504-H34562 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34563 | 98504-H34563 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34564 | 98504-H34564 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34565 | 98504-H34565 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34566 | 98504-H34566 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34567 | 98504-H34567 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34568 | 98504-H34568 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34569 | 98504-H34569 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34570 | 98504-H34570 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34571 | 98504-H34571 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34572 | 98504-H34572 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34573 | 98504-H34573 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34574 | 98504-H34574 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34575 | 98504-H34575 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34576 | 98504-H34576 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34577 | 98504-H34577 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34578 | 98504-H34578 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34579 | 98504-H34579 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34580 | 98504-H34580 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34581 | 98504-H34581 | \$ 366.00 | 6% | \$346.62 |
| EWPP PremierPLS NBD AHR H34582 | 98504-H34582 | \$ 366.00 | 6% | \$346.62 |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34583 | 98504-H34583 | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR H34584 | 98504-H34584 | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR H34585 | 98504-H34585 | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR H34586 | 98504-H34586 | \$ 366.00 | 6% | <i>\$346.62</i> |
| EWPP PremierPLS NBD AHR H34587 | 98504-H34587 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34588 | 98504-H34588 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34589 | 98504-H34589 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34590 | 98504-H34590 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34591 | 98504-H34591 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34592 | 98504-H34592 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34593 | 98504-H34593 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34594 | 98504-H34594 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34595 | 98504-H34595 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34596 | 98504-H34596 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34597 | 98504-H34597 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34598 | 98504-H34598 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34599 | 98504-H34599 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34600 | 98504-H34600 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34601 | 98504-H34601 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34602 | 98504-H34602 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H34603 | 98504-H34603 | \$ 411.00 | 6% | <i>\$389.24</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34604 | 98504-H34604 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34605 | 98504-H34605 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34606 | 98504-H34606 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34607 | 98504-H34607 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34608 | 98504-H34608 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34609 | 98504-H34609 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34610 | 98504-H34610 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34611 | 98504-H34611 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34612 | 98504-H34612 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34613 | 98504-H34613 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34614 | 98504-H34614 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34615 | 98504-H34615 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34616 | 98504-H34616 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34617 | 98504-H34617 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34618 | 98504-H34618 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34619 | 98504-H34619 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34620 | 98504-H34620 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34621 | 98504-H34621 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34622 | 98504-H34622 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34623 | 98504-H34623 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34624 | 98504-H34624 | \$ 411.00 | 6% | \$389.24 |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34625 | 98504-H34625 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34626 | 98504-H34626 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34627 | 98504-H34627 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34628 | 98504-H34628 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34629 | 98504-H34629 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34630 | 98504-H34630 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34631 | 98504-H34631 | \$ 411.00 | 6% | \$389.24 |
| EWPP PremierPLS NBD AHR H34632 | 98504-H34632 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34633 | 98504-H34633 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34634 | 98504-H34634 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34635 | 98504-H34635 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34636 | 98504-H34636 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34637 | 98504-H34637 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34638 | 98504-H34638 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34639 | 98504-H34639 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34640 | 98504-H34640 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34641 | 98504-H34641 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34642 | 98504-H34642 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34643 | 98504-H34643 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34644 | 98504-H34644 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34645 | 98504-H34645 | \$ 420.00 | 6% | \$397.76 |

| | | | | |
|--------------------------------|--------------|-----------|----|----------|
| EWPP PremierPLS NBD AHR H34646 | 98504-H34646 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34647 | 98504-H34647 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34648 | 98504-H34648 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34649 | 98504-H34649 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34650 | 98504-H34650 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34651 | 98504-H34651 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34652 | 98504-H34652 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34653 | 98504-H34653 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34654 | 98504-H34654 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34655 | 98504-H34655 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34656 | 98504-H34656 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34657 | 98504-H34657 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34658 | 98504-H34658 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34659 | 98504-H34659 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34660 | 98504-H34660 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34661 | 98504-H34661 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34662 | 98504-H34662 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34663 | 98504-H34663 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34664 | 98504-H34664 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34665 | 98504-H34665 | \$ 420.00 | 6% | \$397.76 |
| EWPP PremierPLS NBD AHR H34666 | 98504-H34666 | \$ 420.00 | 6% | \$397.76 |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34667 | 98504-H34667 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34668 | 98504-H34668 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34669 | 98504-H34669 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34670 | 98504-H34670 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34671 | 98504-H34671 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34672 | 98504-H34672 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34673 | 98504-H34673 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34674 | 98504-H34674 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34675 | 98504-H34675 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34676 | 98504-H34676 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34677 | 98504-H34677 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34678 | 98504-H34678 | \$ 420.00 | 6% | <i>\$397.76</i> |
| EWPP PremierPLS NBD AHR H34679 | 98504-H34679 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34680 | 98504-H34680 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34681 | 98504-H34681 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34682 | 98504-H34682 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34683 | 98504-H34683 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34684 | 98504-H34684 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34685 | 98504-H34685 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34686 | 98504-H34686 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34687 | 98504-H34687 | \$ 436.00 | 6% | <i>\$412.91</i> |

| | | | | |
|--------------------------------|--------------|-----------|----|-----------------|
| EWPP PremierPLS NBD AHR H34688 | 98504-H34688 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34689 | 98504-H34689 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34690 | 98504-H34690 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34691 | 98504-H34691 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34692 | 98504-H34692 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34693 | 98504-H34693 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34694 | 98504-H34694 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34695 | 98504-H34695 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34696 | 98504-H34696 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34697 | 98504-H34697 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34698 | 98504-H34698 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34699 | 98504-H34699 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34700 | 98504-H34700 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34701 | 98504-H34701 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34702 | 98504-H34702 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34703 | 98504-H34703 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34704 | 98504-H34704 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34705 | 98504-H34705 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34706 | 98504-H34706 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34707 | 98504-H34707 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34708 | 98504-H34708 | \$ 436.00 | 6% | <i>\$412.91</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H34709 | 98504-H34709 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34710 | 98504-H34710 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34711 | 98504-H34711 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34712 | 98504-H34712 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34713 | 98504-H34713 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34714 | 98504-H34714 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34715 | 98504-H34715 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34716 | 98504-H34716 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34717 | 98504-H34717 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34718 | 98504-H34718 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34719 | 98504-H34719 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34720 | 98504-H34720 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34721 | 98504-H34721 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34722 | 98504-H34722 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34723 | 98504-H34723 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34724 | 98504-H34724 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34725 | 98504-H34725 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLS NBD AHR H34726 | 98504-H34726 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |
| EWPP PremierPLS NBD AHR H34727 | 98504-H34727 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |
| EWPP PremierPLS NBD AHR H34728 | 98504-H34728 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |
| EWPP PremierPLS NBD AHR H34729 | 98504-H34729 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H34730 | 98504-H34730 | \$ 4,013.00 | 6% | <i>\$3,800.51</i> |
| EWPP PremierPLS NBD AHR H34731 | 98504-H34731 | \$ 4,013.00 | 6% | <i>\$3,800.51</i> |
| EWPP PremierPLS NBD AHR H34732 | 98504-H34732 | \$ 4,013.00 | 6% | <i>\$3,800.51</i> |
| EWPP PremierPLS NBD AHR H34733 | 98504-H34733 | \$ 4,013.00 | 6% | <i>\$3,800.51</i> |
| EWPP PremierPLS NBD AHR H34734 | 98504-H34734 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS NBD AHR H34735 | 98504-H34735 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS NBD AHR H34736 | 98504-H34736 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34737 | 98504-H34737 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34738 | 98504-H34738 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34739 | 98504-H34739 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34740 | 98504-H34740 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS NBD AHR H34741 | 98504-H34741 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS NBD AHR H34742 | 98504-H34742 | \$ 1,503.00 | 6% | <i>\$1,423.42</i> |
| EWPP PremierPLS NBD AHR H34743 | 98504-H34743 | \$ 1,503.00 | 6% | <i>\$1,423.42</i> |
| EWPP PremierPLS NBD AHR H34744 | 98504-H34744 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34745 | 98504-H34745 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34746 | 98504-H34746 | \$ 1,851.00 | 6% | <i>\$1,752.99</i> |
| EWPP PremierPLS NBD AHR H34747 | 98504-H34747 | \$ 1,851.00 | 6% | <i>\$1,752.99</i> |
| EWPP PremierPLS NBD AHR H34748 | 98504-H34748 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34749 | 98504-H34749 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34750 | 98504-H34750 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR H34751 | 98504-H34751 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34752 | 98504-H34752 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34753 | 98504-H34753 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34754 | 98504-H34754 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34755 | 98504-H34755 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS NBD AHR H34756 | 98504-H34756 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34757 | 98504-H34757 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34758 | 98504-H34758 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34759 | 98504-H34759 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34760 | 98504-H34760 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34761 | 98504-H34761 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H34993 | 98504-H34993 | \$ 18,220.00 | 6% | <i>\$17,255.25</i> |
| EWPP PremierPLS NBD AHR H34994 | 98504-H34994 | \$ 18,220.00 | 6% | <i>\$17,255.25</i> |
| EWPP PremierPLS NBD AHR H34996 | 98504-H34996 | \$ 18,220.00 | 6% | <i>\$17,255.25</i> |
| EWPP PremierPLS NBD AHR H34997 | 98504-H34997 | \$ 18,220.00 | 6% | <i>\$17,255.25</i> |
| EWPP PremierPLS NBD AHR H35005 | 98504-H35005 | \$ 12,937.00 | 6% | <i>\$12,251.99</i> |
| EWPP PremierPLS NBD AHR H35006 | 98504-H35006 | \$ 12,937.00 | 6% | <i>\$12,251.99</i> |
| EWPP PremierPLS NBD AHR H35012 | 98504-H35012 | \$ 8,796.00 | 6% | <i>\$8,330.25</i> |
| EWPP PremierPLS NBD AHR H35070 | 98504-H35070 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35071 | 98504-H35071 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35072 | 98504-H35072 | \$ 385.00 | 6% | <i>\$364.61</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H35073 | 98504-H35073 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35074 | 98504-H35074 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35075 | 98504-H35075 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35076 | 98504-H35076 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35077 | 98504-H35077 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35078 | 98504-H35078 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35079 | 98504-H35079 | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS NBD AHR H35080 | 98504-H35080 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H35081 | 98504-H35081 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H35082 | 98504-H35082 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H35083 | 98504-H35083 | \$ 411.00 | 6% | <i>\$389.24</i> |
| EWPP PremierPLS NBD AHR H35270 | 98504-H35270 | \$ 1,570.00 | 6% | <i>\$1,486.87</i> |
| EWPP PremierPLS NBD AHR H35271 | 98504-H35271 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| EWPP PremierPLS NBD AHR H35272 | 98504-H35272 | \$ 1,373.00 | 6% | <i>\$1,300.30</i> |
| EWPP PremierPLS NBD AHR H35273 | 98504-H35273 | \$ 1,373.00 | 6% | <i>\$1,300.30</i> |
| EWPP PremierPLS NBD AHR H35274 | 98504-H35274 | \$ 1,851.00 | 6% | <i>\$1,752.99</i> |
| EWPP PremierPLS NBD AHR H35275 | 98504-H35275 | \$ 1,713.00 | 6% | <i>\$1,622.30</i> |
| EWPP PremierPLS NBD AHR H35276 | 98504-H35276 | \$ 3,648.00 | 6% | <i>\$3,454.84</i> |
| EWPP PremierPLS NBD AHR H35277 | 98504-H35277 | \$ 4,278.00 | 6% | <i>\$4,051.48</i> |
| EWPP PremierPLS NBD AHR H35278 | 98504-H35278 | \$ 3,152.00 | 6% | <i>\$2,985.10</i> |
| EWPP PremierPLS NBD AHR H35279 | 98504-H35279 | \$ 3,521.00 | 6% | <i>\$3,334.56</i> |

| | | | | |
|------------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS NBD AHR H35280 | 98504-H35280 | \$ 6,640.00 | 6% | <i>\$6,288.41</i> |
| EWPP PremierPLS NBD AHR H35294 | 98504-H35294 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPP PremierPLS NBD AHR H35295 | 98504-H35295 | \$ 1,399.00 | 6% | <i>\$1,324.92</i> |
| EWPP PremierPLUS NBD AHR H35296 | 98504-H35296 | \$ 10,202.00 | 6% | <i>\$9,661.80</i> |
| EWPP PremierPLUS NBD AHR H35297 | 98504-H35297 | \$ 10,202.00 | 6% | <i>\$9,661.80</i> |
| EWPP PremierPLUS NBD AHR H35298 | 98504-H35298 | \$ 16,391.00 | 6% | <i>\$15,523.10</i> |
| EWPP PremierPLUS NBD AHR H35299 | 98504-H35299 | \$ 16,391.00 | 6% | <i>\$15,523.10</i> |
| EWPP PremierPLS NBD AHR H35302 | 98504-H35302 | \$ 4,130.00 | 6% | <i>\$3,911.32</i> |
| EWPP PremierPLS NBD AHR H35303 | 98504-H35303 | \$ 4,130.00 | 6% | <i>\$3,911.32</i> |
| EWPP PremierPLS NBD AHR H35304 | 98504-H35304 | \$ 4,130.00 | 6% | <i>\$3,911.32</i> |
| EWPP PremierPLS NBD AHR H35305 | 98504-H35305 | \$ 4,269.00 | 6% | <i>\$4,042.96</i> |
| EWPP PremierPLS NBD AHR H35306 | 98504-H35306 | \$ 4,269.00 | 6% | <i>\$4,042.96</i> |
| EWPP PremierPLS NBD AHR H35307 | 98504-H35307 | \$ 4,269.00 | 6% | <i>\$4,042.96</i> |
| EWPP PremierPLS NBD AHR H35309 | 98504-H35309 | \$ 4,173.00 | 6% | <i>\$3,952.04</i> |
| EWPP PremierPLS NBD AHR H35310 | 98504-H35310 | \$ 4,173.00 | 6% | <i>\$3,952.04</i> |
| EWPP PremierPLS NBD AHR H35311 | 98504-H35311 | \$ 4,173.00 | 6% | <i>\$3,952.04</i> |
| EWPP PremierPLS NBD AHR H35312 | 98504-H35312 | \$ 3,450.00 | 6% | <i>\$3,267.32</i> |
| EWPP PremierPLS NBD AHR H35313 | 98504-H35313 | \$ 3,450.00 | 6% | <i>\$3,267.32</i> |
| EWPP PremierPLS NBD AHR H35314 | 98504-H35314 | \$ 3,450.00 | 6% | <i>\$3,267.32</i> |
| EWPP PremierPLS NBD AHR H35315 | 98504-H35315 | \$ 2,190.00 | 6% | <i>\$2,074.04</i> |
| EWPP PremierPLS NBD AHR H35318 | 98504-H35318 | \$ 1,635.00 | 6% | <i>\$1,548.43</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H35319 | 98504-H35319 | \$ 1,790.00 | 6% | <i>\$1,695.22</i> |
| EWPP PremierPLS NBD AHR H35320 | 98504-H35320 | \$ 1,818.00 | 6% | <i>\$1,721.74</i> |
| EWPP PremierPLS NBD AHR H35321 | 98504-H35321 | \$ 1,981.00 | 6% | <i>\$1,876.11</i> |
| EWPP PremierPLS NBD AHR H35322 | 98504-H35322 | \$ 2,208.00 | 6% | <i>\$2,091.09</i> |
| EWPP PremierPLS NBD AHR H35323 | 98504-H35323 | \$ 2,189.00 | 6% | <i>\$2,073.09</i> |
| EWPP PremierPLS NBD AHR H35328 | 98504-H35328 | \$ 830.00 | 6% | <i>\$786.05</i> |
| EWPP PremierPLS NBD AHR H35330 | 98504-H35330 | \$ 1,156.00 | 6% | <i>\$1,094.79</i> |
| EWPP PremierPLS NBD AHR H35340 | 98504-H35340 | \$ 4,650.00 | 6% | <i>\$4,403.78</i> |
| EWPP PremierPLS NBD AHR H35341 | 98504-H35341 | \$ 4,650.00 | 6% | <i>\$4,403.78</i> |
| EWPP PremierPLS NBD AHR H35342 | 98504-H35342 | \$ 3,762.00 | 6% | <i>\$3,562.80</i> |
| EWPP PremierPLS NBD AHR H35343 | 98504-H35343 | \$ 4,650.00 | 6% | <i>\$4,403.78</i> |
| EWPP PremierPLS NBD AHR H35344 | 98504-H35344 | \$ 4,747.00 | 6% | <i>\$4,495.65</i> |
| EWPP PremierPLS NBD AHR H35345 | 98504-H35345 | \$ 4,747.00 | 6% | <i>\$4,495.65</i> |
| EWPP PremierPLS NBD AHR H35346 | 98504-H35346 | \$ 3,834.00 | 6% | <i>\$3,630.99</i> |
| EWPP PremierPLS NBD AHR H35347 | 98504-H35347 | \$ 4,747.00 | 6% | <i>\$4,495.65</i> |
| EWPP PremierPLS NBD AHR H35349 | 98504-H35349 | \$ 4,992.00 | 6% | <i>\$4,727.67</i> |
| EWPP PremierPLS NBD AHR H35350 | 98504-H35350 | \$ 4,992.00 | 6% | <i>\$4,727.67</i> |
| EWPP PremierPLS NBD AHR H35351 | 98504-H35351 | \$ 4,027.00 | 6% | <i>\$3,813.77</i> |
| EWPP PremierPLS NBD AHR H35352 | 98504-H35352 | \$ 4,992.00 | 6% | <i>\$4,727.67</i> |
| EWPP PremierPLS NBD AHR H35359 | 98504-H35359 | \$ 1,981.00 | 6% | <i>\$1,876.11</i> |
| EWPP PremierPLS NBD AHR H35360 | 98504-H35360 | \$ 2,208.00 | 6% | <i>\$2,091.09</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H35361 | 98504-H35361 | \$ 2,190.00 | 6% | <i>\$2,074.04</i> |
| EWPP PremierPLS NBD AHR H35362 | 98504-H35362 | \$ 1,635.00 | 6% | <i>\$1,548.43</i> |
| EWPP PremierPLS NBD AHR H35366 | 98504-H35366 | \$ 1,930.00 | 6% | <i>\$1,827.81</i> |
| EWPP PremierPLS NBD AHR H35367 | 98504-H35367 | \$ 2,251.00 | 6% | <i>\$2,131.81</i> |
| EWPP PremierPLS NBD AHR H35368 | 98504-H35368 | \$ 3,422.00 | 6% | <i>\$3,240.81</i> |
| EWPP PremierPLS NBD AHR H35369 | 98504-H35369 | \$ 1,116.00 | 6% | <i>\$1,056.91</i> |
| EWPP PremierPLS NBD AHR H35370 | 98504-H35370 | \$ 1,561.00 | 6% | <i>\$1,478.35</i> |
| EWPP PremierPLS NBD AHR H35375 | 98504-H35375 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWPP PremierPLS NBD AHR H35376 | 98504-H35376 | \$ 772.00 | 6% | <i>\$731.12</i> |
| EWPP PremierPLS NBD AHR H35377 | 98504-H35377 | \$ 326.00 | 6% | <i>\$308.74</i> |
| EWPP PremierPLS NBD AHR H35378 | 98504-H35378 | \$ 512.00 | 6% | <i>\$484.89</i> |
| EWPP PremierPLS NBD AHR H35379 | 98504-H35379 | \$ 326.00 | 6% | <i>\$308.74</i> |
| EWPP PremierPLS NBD AHR H35380 | 98504-H35380 | \$ 576.00 | 6% | <i>\$545.50</i> |
| EWPP PremierPLS NBD AHR H35381 | 98504-H35381 | \$ 707.00 | 6% | <i>\$669.56</i> |
| EWPP PremierPLS NBD AHR H35384 | 98504-H35384 | \$ 570.00 | 6% | <i>\$539.82</i> |
| EWPP PremierPLS NBD AHR H35385 | 98504-H35385 | \$ 758.00 | 6% | <i>\$717.86</i> |
| EWPP PremierPLS NBD AHR H35386 | 98504-H35386 | \$ 1,258.00 | 6% | <i>\$1,191.39</i> |
| EWPP PremierPLS NBD AHR H35387 | 98504-H35387 | \$ 1,176.00 | 6% | <i>\$1,113.73</i> |
| EWPP PremierPLS NBD AHR H35388 | 98504-H35388 | \$ 868.00 | 6% | <i>\$822.04</i> |
| EWPP PremierPLS NBD AHR H35389 | 98504-H35389 | \$ 485.00 | 6% | <i>\$459.32</i> |
| EWPP PremierPLS NBD AHR H35390 | 98504-H35390 | \$ 424.00 | 6% | <i>\$401.55</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS NBD AHR H35391 | 98504-H35391 | \$ 928.00 | 6% | \$878.86 |
| EWPP PremierPLS NBD AHR H35392 | 98504-H35392 | \$ 1,420.00 | 6% | \$1,344.81 |
| EWPP PremierPLS NBD AHR H35393 | 98504-H35393 | \$ 1,887.00 | 6% | \$1,787.08 |
| EWPP PremierPLS NBD AHR H35394 | 98504-H35394 | \$ 343.00 | 6% | \$324.84 |
| EWPP PremierPLS NBD AHR H35395 | 98504-H35395 | \$ 286.00 | 6% | \$270.86 |
| EWPP PremierPLS NBD AHR H35396 | 98504-H35396 | \$ 343.00 | 6% | \$324.84 |
| EWPP PremierPLS NBD AHR H35397 | 98504-H35397 | \$ 286.00 | 6% | \$270.86 |
| EWPP PremierPLS NBD AHR H35398 | 98504-H35398 | \$ 882.00 | 6% | \$835.30 |
| EWPP PremierPLS NBD AHR H35399 | 98504-H35399 | \$ 1,070.00 | 6% | \$1,013.34 |
| EWPP PremierPLS NBD AHR H35400 | 98504-H35400 | \$ 1,181.00 | 6% | \$1,118.47 |
| EWPP PremierPLS NBD AHR H35401 | 98504-H35401 | \$ 629.00 | 6% | \$595.69 |
| EWPP PremierPLS NBD AHR H35415 | 98504-H35415 | \$ 173.00 | 6% | \$163.84 |
| EWPP PremierPLS NBD AHR H35416 | 98504-H35416 | \$ 173.00 | 6% | \$163.84 |
| EWPP PremierPLS NBD AHR H35426 | 98504-H35426 | \$ 485.00 | 6% | \$459.32 |
| EWPP PremierPLS NBD AHR H35427 | 98504-H35427 | \$ 1,176.00 | 6% | \$1,113.73 |
| EWPP PremierPLS NBD AHR H35428 | 98504-H35428 | \$ 424.00 | 6% | \$401.55 |
| EWPP PremierPLS NBD AHR H35429 | 98504-H35429 | \$ 928.00 | 6% | \$878.86 |
| EWPP PremierPLS NBD AHR H35430 | 98504-H35430 | \$ 1,591.00 | 6% | \$1,506.76 |
| EWPP PremierPLS NBD AHR H35431 | 98504-H35431 | \$ 1,591.00 | 6% | \$1,506.76 |
| EWPP PremierPLS NBD AHR H35432 | 98504-H35432 | \$ 1,503.00 | 6% | \$1,423.42 |
| EWPP PremierPLS NBD AHR H35433 | 98504-H35433 | \$ 1,694.00 | 6% | \$1,604.30 |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H35434 | 98504-H35434 | \$ 1,763.00 | 6% | <i>\$1,669.65</i> |
| EWPP PremierPLS NBD AHR H35435 | 98504-H35435 | \$ 1,763.00 | 6% | <i>\$1,669.65</i> |
| EWPP PremierPLS NBD AHR H35436 | 98504-H35436 | \$ 2,137.00 | 6% | <i>\$2,023.85</i> |
| EWPP PremierPLS NBD AHR H35437 | 98504-H35437 | \$ 2,137.00 | 6% | <i>\$2,023.85</i> |
| EWPP PremierPLS NBD AHR H35438 | 98504-H35438 | \$ 2,137.00 | 6% | <i>\$2,023.85</i> |
| EWPP PremierPLS NBD AHR H35439 | 98504-H35439 | \$ 2,137.00 | 6% | <i>\$2,023.85</i> |
| EWPP PremierPLS NBD AHR H35440 | 98504-H35440 | \$ 1,694.00 | 6% | <i>\$1,604.30</i> |
| EWPP PremierPLS NBD AHR H35441 | 98504-H35441 | \$ 1,694.00 | 6% | <i>\$1,604.30</i> |
| EWPP PremierPLS NBD AHR H35442 | 98504-H35442 | \$ 1,694.00 | 6% | <i>\$1,604.30</i> |
| EWPP PremierPLS NBD AHR H35443 | 98504-H35443 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |
| EWPP PremierPLS NBD AHR H35444 | 98504-H35444 | \$ 4,013.00 | 6% | <i>\$3,800.51</i> |
| EWPP PremierPLS NBD AHR H35445 | 98504-H35445 | \$ 3,648.00 | 6% | <i>\$3,454.84</i> |
| EWPP PremierPLS NBD AHR H35446 | 98504-H35446 | \$ 3,577.00 | 6% | <i>\$3,387.60</i> |
| EWPP PremierPLS NBD AHR H35447 | 98504-H35447 | \$ 4,074.00 | 6% | <i>\$3,858.28</i> |
| EWPP PremierPLS NBD AHR H35448 | 98504-H35448 | \$ 3,955.00 | 6% | <i>\$3,745.58</i> |
| EWPP PremierPLS NBD AHR H35449 | 98504-H35449 | \$ 3,152.00 | 6% | <i>\$2,985.10</i> |
| EWPP PremierPLS NBD AHR H35450 | 98504-H35450 | \$ 3,353.00 | 6% | <i>\$3,175.46</i> |
| EWPP PremierPLS NBD AHR H35451 | 98504-H35451 | \$ 7,061.00 | 6% | <i>\$6,687.12</i> |
| EWPP PremierPLS NBD AHR H35452 | 98504-H35452 | \$ 7,061.00 | 6% | <i>\$6,687.12</i> |
| EWPP PremierPLS NBD AHR H35453 | 98504-H35453 | \$ 4,013.00 | 6% | <i>\$3,800.51</i> |
| EWPP PremierPLS NBD AHR H35454 | 98504-H35454 | \$ 3,828.00 | 6% | <i>\$3,625.31</i> |

| | | | | |
|---|---------------------------------|-------------|----|-------------------|
| EWPP PremierPLS NBD AHR H35455 | 98504-H35455 | \$ 1,818.00 | 6% | <i>\$1,721.74</i> |
| EWPP PremierPLS NBD AHR H35456 | 98504-H35456 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPP PremierPLS NBD AHR H35457 | 98504-H35457 | \$ 1,920.00 | 6% | <i>\$1,818.34</i> |
| EWPP PremierPLS NBD AHR H35458 | 98504-H35458 | \$ 2,007.00 | 6% | <i>\$1,900.73</i> |
| EWPP PremierPLS NBD AHR H35471 | 98504-H35471 | \$ 1,818.00 | 6% | <i>\$1,721.74</i> |
| EWPP PremierPLS NBD AHR H35600 | 98504-H35600 | \$ 1,373.00 | 6% | <i>\$1,300.30</i> |
| EWPP PremierPLS NBD AHR H35601 | 98504-H35601 | \$ 1,373.00 | 6% | <i>\$1,300.30</i> |
| EWPP PremierPLS NBD AHR H35602 | 98504-H35602 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS NBD AHR H35603 | 98504-H35603 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS NBD AHR H35604 | 98504-H35604 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H35605 | 98504-H35605 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLS NBD AHR H35606 | 98504-H35606 | \$ 1,851.00 | 6% | <i>\$1,752.99</i> |
| EWPP PremierPLS NBD AHR H35607 | 98504-H35607 | \$ 1,851.00 | 6% | <i>\$1,752.99</i> |
| EWPP PremierPLS NBD AHR ISW-24W-4X | 98504-ISW- 24W-4X | \$ 827.00 | 6% | <i>\$783.21</i> |
| EWPP PremierPLS NBD AHR ISW-4W-4WS-4X | 98504-ISW-4W- 4WS-4X | \$ 1,333.00 | 6% | <i>\$1,262.42</i> |
| EWPP PremierPLS NBD AHR MSM128 | 98504- MSM128 | \$ 3,237.00 | 6% | <i>\$3,065.60</i> |
| EWPP PremierPLS NBD AHR MSM48C | 98504- MSM48C | \$ 2,200.00 | 6% | <i>\$2,083.51</i> |
| EWPPPremierPLS NBD AHR R100-8T | 98504-R100-8T | \$ 1,214.00 | 6% | <i>\$1,149.72</i> |
| EWPP PremierPLS NBDAHR SLX9150-48XT-DC-F | 98504- SLX9150- 48XT-DC-F | \$ 4,102.00 | 6% | <i>\$3,884.80</i> |
| EWPP PremierPLS NBDAHR SLX9150-48XT-DC-R | 98504- SLX9150- 48XT-DC-R | \$ 4,522.00 | 6% | <i>\$4,282.56</i> |

| | | | | |
|---|--------------------------------|--------------|-----|--------------------|
| EWPP PremierPLS NBD AHR SLX9150-48Y-DC-F | 98504- SLX9150-48Y- DC-F | \$ 4,017.00 | 6% | <i>\$3,804.30</i> |
| EWPP PremierPLS NBD AHR SLX9150-48Y-DC-R | 98504- SLX9150-48Y- DC-R | \$ 4,429.00 | 6% | <i>\$4,194.48</i> |
| EWPP PremierPLS NBD AHR SLX9740-40C | 98504- SLX9740-40C | \$ 13,425.00 | 6% | <i>\$12,714.15</i> |
| EWPP PremierPLS NBD AHR SLX9740-40C-AC-F | 98504- SLX9740-40C- AC-F | \$ 13,425.00 | 6% | <i>\$12,714.15</i> |
| EWPP PremierPLS NBD AHR SLX9740-40C-AC-R | 98504- SLX9740-40C- AC-R | \$ 13,425.00 | 10% | <i>\$12,173.12</i> |
| EWPP PremierPLS NBD AHR SLX9740-40C-DC-F | 98504- SLX9740-40C- DC-F | \$ 13,425.00 | 6% | <i>\$12,714.15</i> |
| EWPP PremierPLS NBD AHR SLX9740-80C | 98504- SLX9740-80C | \$ 24,272.00 | 6% | <i>\$22,986.80</i> |
| EWPP PremierPLS NBD AHR SLX9740-80C-AC-F | 98504- SLX9740-80C- AC-F | \$ 24,272.00 | 6% | <i>\$22,986.80</i> |
| EWPP PremierPLS NBD AHR SLX9740-80C-AC-R | 98504- SLX9740-80C- AC-R | \$ 24,272.00 | 10% | <i>\$22,008.64</i> |
| EWPP PremierPLS NBD AHR SLX9740-80C-DC-F | 98504- SLX9740-80C- DC-F | \$ 24,272.00 | 6% | <i>\$22,986.80</i> |
| EWPP PremierPLS NBD AHR V300-8P-2X | 98504-V300- 8P-2X | \$ 860.00 | 6% | <i>\$814.46</i> |
| EWPP PremierPLS NBD AHR V300-8T-2X | 98504-V300- 8T-2X | \$ 819.00 | 6% | <i>\$775.63</i> |
| EWPP PremierPLS NBD AHR V300HT-8P-2X | 98504-V300HT- 8P-2X | \$ 1,033.00 | 6% | <i>\$978.30</i> |
| EWPP PremierPLS NBD AHR V300HT-8T-2X | 98504-V300HT- 8T-2X | \$ 910.00 | 6% | <i>\$861.82</i> |
| EWPP PremierPLS NBD AHR VIM-SS | 98504-VIM-SS | \$ 604.00 | 6% | <i>\$572.02</i> |
| EWPPPremierPLS NBD AHR VIM-SSV | 98504-VIM- SSV80 | \$ 729.00 | 6% | <i>\$690.40</i> |

| | | | | |
|--|---|-------------|----|------------|
| EWPPPremierPLS NBD AHR VIM2-SS | 98504-VIM2- SS | \$ 597.00 | 6% | \$565.39 |
| EWPPPremierPLS NBD AHR VIM2-SS | 98504-VIM2- SS128 | \$ 1,031.00 | 6% | \$976.41 |
| EWPPPremierPLS NBD AHR VIM2-V8 | 98504-VIM2- V80 | \$ 1,101.00 | 6% | \$1,042.70 |
| EWPPPremierPLS NBD AHR VIM210G | 98504- VIM210G4X | \$ 1,548.00 | 6% | \$1,466.03 |
| EWPP PremPL NBD AHR VSP4900-12MXU-12XE | 98504- VSP4900- 12MXU-12XE | \$ 2,078.00 | 6% | \$1,967.97 |
| EWPP PremPL NBD AHR VSP4900-12MXU-12XE-B1 | 98504- VSP4900- 12MXU-12XE- B1 | \$ 2,078.00 | 6% | \$1,967.97 |
| EWPP PremierPLS NBD AHR VSP4900-24S | 98504- VSP4900-24S | \$ 1,635.00 | 6% | \$1,548.43 |
| EWPP PremierPLS NBD AHR VSP4900-24S-B3 | 98504- VSP4900-24S- B3 | \$ 1,635.00 | 6% | \$1,548.43 |
| EWPP PremierPLS NBD AHR VSP4900-24XE | 98504- VSP4900- 24XE | \$ 2,078.00 | 6% | \$1,967.97 |
| EWPP PremierPLS NBD AHR VSP4900-24XE-B3 | 98504- VSP4900- 24XE-B3 | \$ 2,078.00 | 6% | \$1,967.97 |
| EWPP PremierPLS NBD AHR X435-24P-4S | 98504-X435- 24P-4S | \$ 965.00 | 6% | \$913.90 |
| EWPP PremierPLS NBD AHR X435-24T-4S | 98504-X435- 24T-4S | \$ 857.00 | 6% | \$811.62 |
| EWPP PremierPLS NBD AHR X435-8P-2T-W | 98504-X435- 8P-2T-W | \$ 857.00 | 6% | \$811.62 |
| EWPP PremierPLS NBD AHR X435-8P-4S | 98504-X435- 8P-4S | \$ 845.00 | 6% | \$800.26 |
| EWPP PremierPLS NBD AHR X435-8T-4S | 98504-X435- 8T-4S | \$ 820.00 | 6% | \$776.58 |
| EWPPPremierPLS NBD AHR X460-24 | 98504-X460- 24P | \$ 2,289.00 | 6% | \$2,167.80 |
| EWPPPremierPLS NBD AHR X460-24 | 98504-X460- 24T | \$ 2,004.00 | 6% | \$1,897.89 |
| EWPPPremierPLS NBD AHR X460-24 | 98504-X460- 24TDC | \$ 2,342.00 | 6% | \$2,217.99 |

| | | | | |
|---|-----------------------|-------------|----|------------|
| EWPPPremierPLS NBD AHR X460-24 | 98504-X460-24X | \$ 2,620.00 | 6% | \$2,481.27 |
| EWPPPremierPLS NBD AHR X460-24 | 98504-X460-24XDC | \$ 2,775.00 | 6% | \$2,628.06 |
| EWPPPremierPLS NBD AHR X460-48 | 98504-X460-48P | \$ 2,620.00 | 6% | \$2,481.27 |
| EWPPPremierPLS NBD AHR X460-48 | 98504-X460-48T | \$ 2,430.00 | 6% | \$2,301.33 |
| EWPPPremierPLS NBD AHR X460-48 | 98504-X460-48TDC | \$ 2,730.00 | 6% | \$2,585.45 |
| EWPPPremierPLS NBD AHR X460-48 | 98504-X460-48X | \$ 3,069.00 | 6% | \$2,906.50 |
| EWPPPremierPLS NBD AHR X460-48 | 98504-X460-48XDC | \$ 3,016.00 | 6% | \$2,856.30 |
| EWPP PremierPLS NBD AHR X465-24MU | 98504-X465-24MU | \$ 2,208.00 | 6% | \$2,091.09 |
| EWPP PremierPLS NBD AHR X465-24S | 98504-X465-24S | \$ 1,635.00 | 6% | \$1,548.43 |
| EWPP PremierPLS NBD AHR X465-24S-B3 | 98504-X465-24S-B3 | \$ 1,635.00 | 6% | \$1,548.43 |
| EWPP PremierPLS NBD AHR X465-24W | 98504-X465-24W | \$ 1,635.00 | 6% | \$1,548.43 |
| EWPP PremierPLS NBD AHR X465-24XE | 98504-X465-24XE | \$ 2,078.00 | 6% | \$1,967.97 |
| EWPP PremierPLS NBD AHR X465-24XE-B3 | 98504-X465-24XE-B3 | \$ 2,078.00 | 6% | \$1,967.97 |
| EWPP PremierPLS NBD AHR X465-48P | 98504-X465-48P | \$ 1,818.00 | 6% | \$1,721.74 |
| EWPP PremierPLS NBD AHR X465-48T | 98504-X465-48T | \$ 1,790.00 | 6% | \$1,695.22 |
| EWPP PremierPLS NBD AHR X465-48W | 98504-X465-48W | \$ 1,981.00 | 6% | \$1,876.11 |
| EWPP PremierPLS NBD AHR X465i-48W | 98504-X465i-48W | \$ 2,189.00 | 6% | \$2,073.09 |
| EWPP PremierPLS NBD AHR X465i-48W-B1-S1 | 98504-X465i-48W-B1-S1 | \$ 2,189.00 | 6% | \$2,073.09 |
| EWPP PremierPLS NBD AHR X465i-48W-B2-S1 | 98504-X465i-48W-B2-S1 | \$ 2,190.00 | 6% | \$2,074.04 |
| EWPPPremierPLS NBD AHR X480-24 | 98504-X480-24X | \$ 2,827.00 | 6% | \$2,677.31 |
| EWPPPremierPLS NBD AHR X480-48 | 98504-X480-48T | \$ 2,428.00 | 6% | \$2,299.44 |

| | | | | |
|--|-----------------------|-------------|----|-------------------|
| EWPPremierPLS NBD AHR X480-48 | 98504-X480- 48X | \$ 3,383.00 | 6% | <i>\$3,203.87</i> |
| EWPP PremierPLS NBD AHR X695-48Y-8C | 98504-X695- 48Y-8C | \$ 3,550.00 | 6% | <i>\$3,362.03</i> |
| EWPP PremierPLS NBD AHR XA1440 | 98504-XA1440 | \$ 992.00 | 6% | <i>\$939.47</i> |
| EWPP PremierPLS NBD AHR XA1480 | 98504-XA1480 | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| EWPPPremierPLS NBD AHR XGM3-2S | 98504-XGM3- 2SF | \$ 729.00 | 6% | <i>\$690.40</i> |
| EWPP PremierPLS NBD AHR XR600 | 98504-XR600 | \$ 1,221.00 | 6% | <i>\$1,156.35</i> |
| EWPP PremierPLS 4HR AHR 1130C | 98507-1130C | \$ 2,960.00 | 6% | <i>\$2,803.27</i> |
| EWPP PremierPLS 4HR AHR 16119 | 98507-16119 | \$ 844.00 | 6% | <i>\$799.31</i> |
| EWPP PremierPLS 4HR AHR 16120 | 98507-16120 | \$ 950.00 | 6% | <i>\$899.70</i> |
| EWPP PremierPLS 4HR AHR 16126 | 98507-16126 | \$ 844.00 | 6% | <i>\$799.31</i> |
| EWPP PremierPLS 4HR AHR 16127 | 98507-16127 | \$ 884.00 | 6% | <i>\$837.19</i> |
| EWPP PremierPLS 4HR AHR 16172 | 98507-16172 | \$ 1,707.00 | 6% | <i>\$1,616.61</i> |
| EWPP PremierPLS 4HR AHR 16172T | 98507-16172T | \$ 1,825.00 | 6% | <i>\$1,728.37</i> |
| EWPP PremierPLS 4HR AHR 16173 | 98507-16173 | \$ 1,720.00 | 6% | <i>\$1,628.93</i> |
| EWPP PremierPLS 4HR AHR 16173T | 98507-16173T | \$ 1,839.00 | 6% | <i>\$1,741.62</i> |
| EWPP PremierPLS 4HR AHR 16174 | 98507-16174 | \$ 1,960.00 | 6% | <i>\$1,856.22</i> |
| EWPP PremierPLS 4HR AHR 16175 | 98507-16175 | \$ 2,003.00 | 6% | <i>\$1,896.94</i> |
| EWPP PremierPLS 4HR AHR 16176 | 98507-16176 | \$ 1,915.00 | 6% | <i>\$1,813.60</i> |
| EWPP PremierPLS 4HR AHR 16177 | 98507-16177 | \$ 1,810.00 | 6% | <i>\$1,714.16</i> |
| EWPP PremierPLS 4HR AHR 16177T | 98507-16177T | \$ 2,083.00 | 6% | <i>\$1,972.71</i> |
| EWPP PremierPLS 4HR AHR 16178 | 98507-16178 | \$ 2,187.00 | 6% | <i>\$2,071.20</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR 16179 | 98507-16179 | \$ 2,217.00 | 6% | <i>\$2,099.61</i> |
| EWPP PremierPLS 4HR AHR 16179T | 98507-16179T | \$ 2,377.00 | 6% | <i>\$2,251.14</i> |
| EWPP PremierPLS 4HR AHR 16301T | 98507-16301T | \$ 3,625.00 | 6% | <i>\$3,433.06</i> |
| EWPP PremierPLS 4HR AHR 16303T | 98507-16303T | \$ 3,625.00 | 6% | <i>\$3,433.06</i> |
| EWPP PremierPLS 4HR AHR 16304T | 98507-16304T | \$ 4,439.00 | 6% | <i>\$4,203.95</i> |
| EWPP PremierPLS 4HR AHR 16401T | 98507-16401T | \$ 2,415.00 | 6% | <i>\$2,287.13</i> |
| EWPP PremierPLS 4HR AHR 16402T | 98507-16402T | \$ 3,010.00 | 6% | <i>\$2,850.62</i> |
| EWPP PremierPLS 4HR AHR 16403T | 98507-16403T | \$ 2,805.00 | 6% | <i>\$2,656.48</i> |
| EWPP PremierPLS 4HR AHR 16404T | 98507-16404T | \$ 2,805.00 | 6% | <i>\$2,656.48</i> |
| EWPP PremierPLS 4HR AHR 16405T | 98507-16405T | \$ 3,295.00 | 6% | <i>\$3,120.53</i> |
| EWPP PremierPLS 4HR AHR 16406T | 98507-16406T | \$ 3,963.00 | 6% | <i>\$3,753.16</i> |
| EWPP PremierPLS 4HR AHR 16431 | 98507-16431 | \$ 2,949.00 | 6% | <i>\$2,792.85</i> |
| EWPP PremierPLS 4HR AHR 16432 | 98507-16432 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |
| EWPP PremierPLS 4HR AHR 16440 | 98507-16440 | \$ 2,305.00 | 6% | <i>\$2,182.95</i> |
| EWPP PremierPLS 4HR AHR 16441 | 98507-16441 | \$ 2,193.00 | 6% | <i>\$2,076.88</i> |
| EWPP PremierPLS 4HR AHR 16442 | 98507-16442 | \$ 884.00 | 6% | <i>\$837.19</i> |
| EWPP PremierPLS 4HR AHR 16444 | 98507-16444 | \$ 666.00 | 6% | <i>\$630.74</i> |
| EWPP PremierPLS 4HR AHR 16501 | 98507-16501 | \$ 1,504.00 | 6% | <i>\$1,424.36</i> |
| EWPP PremierPLS 4HR AHR 16501T | 98507-16501T | \$ 1,580.00 | 6% | <i>\$1,496.34</i> |
| EWPP PremierPLS 4HR AHR 16502 | 98507-16502 | \$ 1,621.00 | 6% | <i>\$1,535.17</i> |
| EWPP PremierPLS 4HR AHR 16502T | 98507-16502T | \$ 1,695.00 | 6% | <i>\$1,605.25</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR 16503 | 98507-16503 | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWPP PremierPLS 4HR AHR 16503T | 98507-16503T | \$ 1,637.00 | 6% | <i>\$1,550.32</i> |
| EWPP PremierPLS 4HR AHR 16504 | 98507-16504 | \$ 1,731.00 | 6% | <i>\$1,639.34</i> |
| EWPP PremierPLS 4HR AHR 16504T | 98507-16504T | \$ 1,822.00 | 6% | <i>\$1,725.53</i> |
| EWPP PremierPLS 4HR AHR 16505 | 98507-16505 | \$ 1,757.00 | 6% | <i>\$1,663.97</i> |
| EWPP PremierPLS 4HR AHR 16505T | 98507-16505T | \$ 1,894.00 | 6% | <i>\$1,793.71</i> |
| EWPP PremierPLS 4HR AHR 16506 | 98507-16506 | \$ 2,031.00 | 6% | <i>\$1,923.46</i> |
| EWPP PremierPLS 4HR AHR 16506T | 98507-16506T | \$ 2,231.00 | 6% | <i>\$2,112.87</i> |
| EWPP PremierPLS 4HR AHR 16507 | 98507-16507 | \$ 1,982.00 | 6% | <i>\$1,877.05</i> |
| EWPP PremierPLS 4HR AHR 16507T | 98507-16507T | \$ 2,120.00 | 6% | <i>\$2,007.75</i> |
| EWPP PremierPLS 4HR AHR 16508 | 98507-16508 | \$ 2,166.00 | 6% | <i>\$2,051.31</i> |
| EWPP PremierPLS 4HR AHR 16508T | 98507-16508T | \$ 2,342.00 | 6% | <i>\$2,217.99</i> |
| EWPP PremierPLS 4HR AHR 16509 | 98507-16509 | \$ 2,166.00 | 6% | <i>\$2,051.31</i> |
| EWPP PremierPLS 4HR AHR 16509T | 98507-16509T | \$ 2,342.00 | 6% | <i>\$2,217.99</i> |
| EWPP PremierPLS 4HR AHR 16510 | 98507-16510 | \$ 2,342.00 | 6% | <i>\$2,217.99</i> |
| EWPP PremierPLS 4HR AHR 16510T | 98507-16510T | \$ 2,554.00 | 6% | <i>\$2,418.77</i> |
| EWPP PremierPLS 4HR AHR 16513 | 98507-16513 | \$ 1,909.00 | 6% | <i>\$1,807.92</i> |
| EWPP PremierPLS 4HR AHR 16514 | 98507-16514 | \$ 2,298.00 | 6% | <i>\$2,176.32</i> |
| EWPP PremierPLS 4HR AHR 16515 | 98507-16515 | \$ 1,401.00 | 6% | <i>\$1,326.82</i> |
| EWPP PremierPLS 4HR AHR 16516 | 98507-16516 | \$ 1,423.00 | 6% | <i>\$1,347.65</i> |
| EWPP PremierPLS 4HR AHR 16517 | 98507-16517 | \$ 1,613.00 | 6% | <i>\$1,527.59</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR 16518 | 98507-16518 | \$ 1,563.00 | 6% | <i>\$1,480.24</i> |
| EWPP PremierPLS 4HR AHR 16519 | 98507-16519 | \$ 1,637.00 | 6% | <i>\$1,550.32</i> |
| EWPP PremierPLS 4HR AHR 16520 | 98507-16520 | \$ 1,850.00 | 6% | <i>\$1,752.04</i> |
| EWPP PremierPLS 4HR AHR 16530 | 98507-16530 | \$ 1,551.00 | 6% | <i>\$1,468.87</i> |
| EWPP PremierPLS 4HR AHR 16531 | 98507-16531 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWPP PremierPLS 4HR AHR 16531T | 98507-16531T | \$ 1,680.00 | 6% | <i>\$1,591.04</i> |
| EWPP PremierPLS 4HR AHR 16532 | 98507-16532 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWPP PremierPLS 4HR AHR 16532T | 98507-16532T | \$ 1,680.00 | 6% | <i>\$1,591.04</i> |
| EWPP PremierPLS 4HR AHR 16533 | 98507-16533 | \$ 1,741.00 | 6% | <i>\$1,648.81</i> |
| EWPP PremierPLS 4HR AHR 16533T | 98507-16533T | \$ 1,827.00 | 6% | <i>\$1,730.26</i> |
| EWPP PremierPLS 4HR AHR 16534 | 98507-16534 | \$ 1,773.00 | 6% | <i>\$1,679.12</i> |
| EWPP PremierPLS 4HR AHR 16535 | 98507-16535 | \$ 1,989.00 | 6% | <i>\$1,883.68</i> |
| EWPP PremierPLS 4HR AHR 16535A | 98507-16535A | \$ 1,989.00 | 6% | <i>\$1,883.68</i> |
| EWPP PremierPLS 4HR AHR 16535T | 98507-16535T | \$ 2,110.00 | 6% | <i>\$1,998.28</i> |
| EWPP PremierPLS 4HR AHR 16536 | 98507-16536 | \$ 1,515.00 | 6% | <i>\$1,434.78</i> |
| EWPP PremierPLS 4HR AHR 16537 | 98507-16537 | \$ 1,624.00 | 6% | <i>\$1,538.01</i> |
| EWPP PremierPLS 4HR AHR 16538 | 98507-16538 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR 16538T | 98507-16538T | \$ 1,972.00 | 6% | <i>\$1,867.58</i> |
| EWPP PremierPLS 4HR AHR 16539 | 98507-16539 | \$ 1,848.00 | 6% | <i>\$1,750.15</i> |
| EWPP PremierPLS 4HR AHR 16540 | 98507-16540 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPP PremierPLS 4HR AHR 16541 | 98507-16541 | \$ 1,388.00 | 6% | <i>\$1,314.51</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR 16560 | 98507-16560 | \$ 1,326.00 | 6% | <i>\$1,255.79</i> |
| EWPP PremierPLS 4HR AHR 16561 | 98507-16561 | \$ 1,368.00 | 6% | <i>\$1,295.56</i> |
| EWPP PremierPLS 4HR AHR 16562 | 98507-16562 | \$ 1,403.00 | 6% | <i>\$1,328.71</i> |
| EWPP PremierPLS 4HR AHR 16563 | 98507-16563 | \$ 1,466.00 | 6% | <i>\$1,388.38</i> |
| EWPP PremierPLS 4HR AHR 16564 | 98507-16564 | \$ 1,520.00 | 6% | <i>\$1,439.52</i> |
| EWPP PremierPLS 4HR AHR 16565 | 98507-16565 | \$ 1,682.00 | 6% | <i>\$1,592.94</i> |
| EWPP PremierPLS 4HR AHR 16566 | 98507-16566 | \$ 1,285.00 | 6% | <i>\$1,216.96</i> |
| EWPP PremierPLS 4HR AHR 16567 | 98507-16567 | \$ 1,346.00 | 6% | <i>\$1,274.73</i> |
| EWPP PremierPLS 4HR AHR 16568 | 98507-16568 | \$ 1,327.00 | 6% | <i>\$1,256.74</i> |
| EWPP PremierPLS 4HR AHR 16569 | 98507-16569 | \$ 1,388.00 | 6% | <i>\$1,314.51</i> |
| EWPP PremierPLS 4HR AHR 16570 | 98507-16570 | \$ 1,403.00 | 6% | <i>\$1,328.71</i> |
| EWPP PremierPLS 4HR AHR 16571 | 98507-16571 | \$ 1,520.00 | 6% | <i>\$1,439.52</i> |
| EWPP PremierPLS 4HR AHR 16701 | 98507-16701 | \$ 1,867.00 | 6% | <i>\$1,768.14</i> |
| EWPP PremierPLS 4HR AHR 16702 | 98507-16702 | \$ 2,172.00 | 6% | <i>\$2,056.99</i> |
| EWPP PremierPLS 4HR AHR 16703 | 98507-16703 | \$ 2,093.00 | 6% | <i>\$1,982.18</i> |
| EWPP PremierPLS 4HR AHR 16703T | 98507-16703T | \$ 2,250.00 | 6% | <i>\$2,130.86</i> |
| EWPP PremierPLS 4HR AHR 16704 | 98507-16704 | \$ 2,435.00 | 6% | <i>\$2,306.07</i> |
| EWPP PremierPLS 4HR AHR 16704T | 98507-16704T | \$ 2,126.00 | 6% | <i>\$2,013.43</i> |
| EWPP PremierPLS 4HR AHR 16705 | 98507-16705 | \$ 2,172.00 | 6% | <i>\$2,056.99</i> |
| EWPP PremierPLS 4HR AHR 16705T | 98507-16705T | \$ 2,344.00 | 6% | <i>\$2,219.89</i> |
| EWPP PremierPLS 4HR AHR 16706 | 98507-16706 | \$ 2,787.00 | 6% | <i>\$2,639.43</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS 4HR AHR 16706T | 98507-16706T | \$ 3,016.00 | 6% | \$2,856.30 |
| EWPP PremierPLS 4HR AHR 16710 | 98507-16710 | \$ 710.00 | 6% | \$672.41 |
| EWPP PremierPLS 4HR AHR 16710T | 98507-16710T | \$ 764.00 | 6% | \$723.55 |
| EWPP PremierPLS 4HR AHR 16711 | 98507-16711 | \$ 543.00 | 6% | \$514.25 |
| EWPP PremierPLS 4HR AHR 16711T | 98507-16711T | \$ 579.00 | 6% | \$548.34 |
| EWPP PremierPLS 4HR AHR 16712 | 98507-16712 | \$ 590.00 | 6% | \$558.76 |
| EWPP PremierPLS 4HR AHR 16712T | 98507-16712T | \$ 616.00 | 6% | \$583.38 |
| EWPP PremierPLS 4HR AHR 16713 | 98507-16713 | \$ 497.00 | 6% | \$470.68 |
| EWPP PremierPLS 4HR AHR 16713T | 98507-16713T | \$ 532.00 | 6% | \$503.83 |
| EWPP PremierPLS 4HR AHR 16715 | 98507-16715 | \$ 517.00 | 6% | \$489.62 |
| EWPP PremierPLS 4HR AHR 16715T | 98507-16715T | \$ 579.00 | 6% | \$548.34 |
| EWPP PremierPLS 4HR AHR 16716 | 98507-16716 | \$ 1,852.00 | 6% | \$1,753.94 |
| EWPP PremierPLS 4HR AHR 16716T | 98507-16716T | \$ 1,992.00 | 6% | \$1,886.52 |
| EWPP PremierPLS 4HR AHR 16717 | 98507-16717 | \$ 1,988.00 | 6% | \$1,882.74 |
| EWPP PremierPLS 4HR AHR 16718 | 98507-16718 | \$ 1,891.00 | 6% | \$1,790.87 |
| EWPP PremierPLS 4HR AHR 16719 | 98507-16719 | \$ 2,030.00 | 6% | \$1,922.51 |
| EWPP PremierPLS 4HR AHR 16720 | 98507-16720 | \$ 2,526.00 | 6% | \$2,392.25 |
| EWPP PremierPLS 4HR AHR 16720T | 98507-16720T | \$ 2,941.00 | 6% | \$2,785.27 |
| EWPP PremierPLS 4HR AHR 16756 | 98507-16756 | \$ 2,295.00 | 6% | \$2,173.48 |
| EWPP PremierPLS 4HR AHR 16756T | 98507-16756T | \$ 2,710.00 | 6% | \$2,566.51 |
| EWPP PremierPLS 4HR AHR 16757 | 98507-16757 | \$ 2,248.00 | 6% | \$2,128.97 |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR 16757T | 98507-16757T | \$ 2,650.00 | 6% | <i>\$2,509.68</i> |
| EWPP PremierPLS 4HR AHR 16790 | 98507-16790 | \$ 2,578.00 | 6% | <i>\$2,441.49</i> |
| EWPP PremierPLS 4HR AHR 16791 | 98507-16791 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPP PremierPLS 4HR AHR 17101 | 98507-17101 | \$ 4,767.00 | 6% | <i>\$4,514.59</i> |
| EWPP PremierPLS 4HR AHR 17101T | 98507-17101T | \$ 5,848.00 | 6% | <i>\$5,538.35</i> |
| EWPP PremierPLS 4HR AHR 17102 | 98507-17102 | \$ 4,767.00 | 6% | <i>\$4,514.59</i> |
| EWPP PremierPLS 4HR AHR 17102T | 98507-17102T | \$ 5,848.00 | 6% | <i>\$5,538.35</i> |
| EWPP PremierPLS 4HR AHR 17103 | 98507-17103 | \$ 3,660.00 | 6% | <i>\$3,466.20</i> |
| EWPP PremierPLS 4HR AHR 17103C | 98507-17103C | \$ 3,553.00 | 6% | <i>\$3,364.87</i> |
| EWPP PremierPLS 4HR AHR 17103T | 98507-17103T | \$ 4,462.00 | 6% | <i>\$4,225.74</i> |
| EWPP PremierPLS 4HR AHR 17104 | 98507-17104 | \$ 3,660.00 | 6% | <i>\$3,466.20</i> |
| EWPP PremierPLS 4HR AHR 17104T | 98507-17104T | \$ 4,462.00 | 6% | <i>\$4,225.74</i> |
| EWPP PremierPLS 4HR AHR 17121 | 98507-17121 | \$ 1,175.00 | 6% | <i>\$1,112.78</i> |
| EWPP PremierPLS 4HR AHR 17122 | 98507-17122 | \$ 862.00 | 6% | <i>\$816.36</i> |
| EWPP PremierPLS 4HR AHR 17200 | 98507-17200 | \$ 6,859.00 | 6% | <i>\$6,495.82</i> |
| EWPP PremierPLS 4HR AHR 17200T | 98507-17200T | \$ 7,729.00 | 6% | <i>\$7,319.75</i> |
| EWPP PremierPLS 4HR AHR 17201 | 98507-17201 | \$ 6,859.00 | 6% | <i>\$6,495.82</i> |
| EWPP PremierPLS 4HR AHR 17201T | 98507-17201T | \$ 7,729.00 | 6% | <i>\$7,319.75</i> |
| EWPP PremierPLS 4HR AHR 17202 | 98507-17202 | \$ 6,859.00 | 6% | <i>\$6,495.82</i> |
| EWPP PremierPLS 4HR AHR 17202T | 98507-17202T | \$ 7,729.00 | 6% | <i>\$7,319.75</i> |
| EWPP PremierPLS 4HR AHR 17203 | 98507-17203 | \$ 6,948.00 | 6% | <i>\$6,580.10</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR 17203T | 98507-17203T | \$ 7,824.00 | 6% | <i>\$7,409.72</i> |
| EWPP PremierPLS 4HR AHR 17204 | 98507-17204 | \$ 6,948.00 | 6% | <i>\$6,580.10</i> |
| EWPP PremierPLS 4HR AHR 17204T | 98507-17204T | \$ 7,824.00 | 6% | <i>\$7,409.72</i> |
| EWPP PremierPLS 4HR AHR 17205 | 98507-17205 | \$ 6,903.00 | 6% | <i>\$6,537.49</i> |
| EWPP PremierPLS 4HR AHR 17205T | 98507-17205T | \$ 7,776.00 | 6% | <i>\$7,364.26</i> |
| EWPP PremierPLS 4HR AHR 17206 | 98507-17206 | \$ 6,903.00 | 6% | <i>\$6,537.49</i> |
| EWPP PremierPLS 4HR AHR 17206T | 98507-17206T | \$ 7,776.00 | 6% | <i>\$7,364.26</i> |
| EWPP PremierPLS 4HR AHR 17300 | 98507-17300 | \$ 5,022.00 | 6% | <i>\$4,756.09</i> |
| EWPP PremierPLS 4HR AHR 17310 | 98507-17310 | \$ 4,667.00 | 6% | <i>\$4,419.88</i> |
| EWPP PremierPLS 4HR AHR 17350 | 98507-17350 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPP PremierPLS 4HR AHR 17360 | 98507-17360 | \$ 5,751.00 | 6% | <i>\$5,446.48</i> |
| EWPP PremierPLS 4HR AHR 17401 | 98507-17401 | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWPP PremierPLS 4HR AHR 17401G | 98507-17401G | \$ 1,869.00 | 6% | <i>\$1,770.04</i> |
| EWPP PremierPLS 4HR AHR 17401T | 98507-17401T | \$ 1,864.00 | 6% | <i>\$1,765.30</i> |
| EWPP PremierPLS 4HR AHR 17402 | 98507-17402 | \$ 1,887.00 | 6% | <i>\$1,787.08</i> |
| EWPP PremierPLS 4HR AHR 17402G | 98507-17402G | \$ 1,928.00 | 6% | <i>\$1,825.91</i> |
| EWPP PremierPLS 4HR AHR 17402T | 98507-17402T | \$ 1,916.00 | 6% | <i>\$1,814.55</i> |
| EWPP PremierPLS 4HR AHR 17403 | 98507-17403 | \$ 1,996.00 | 6% | <i>\$1,890.31</i> |
| EWPP PremierPLS 4HR AHR 17404 | 98507-17404 | \$ 1,605.00 | 6% | <i>\$1,520.02</i> |
| EWPP PremierPLS 4HR AHR 17405 | 98507-17405 | \$ 1,622.00 | 6% | <i>\$1,536.12</i> |
| EWPP PremierPLS 4HR AHR 17700 | 98507-17700 | \$ 8,118.00 | 6% | <i>\$7,688.15</i> |

| | | | | |
|--------------------------------------|---------------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR 17701 | 98507-17701 | \$ 7,001.00 | 6% | <i>\$6,630.30</i> |
| EWPP PremierPLS 4HR AHR 17702 | 98507-17702 | \$ 7,001.00 | 6% | <i>\$6,630.30</i> |
| EWPP PremierPLS 4HR AHR 17703 | 98507-17703 | \$ 7,648.00 | 6% | <i>\$7,243.04</i> |
| EWPP PremierPLS 4HR AHR 17704 | 98507-17704 | \$ 7,648.00 | 6% | <i>\$7,243.04</i> |
| EWPP PremierPLS 4HR AHR 17705 | 98507-17705 | \$ 7,043.00 | 6% | <i>\$6,670.07</i> |
| EWPP PremierPLS 4HR AHR 17706 | 98507-17706 | \$ 7,043.00 | 6% | <i>\$6,670.07</i> |
| EWPP PremierPLS 4HR AHR 17800 | 98507-17800 | \$ 8,393.00 | 6% | <i>\$7,948.59</i> |
| EWPP PremierPLS 4HR AHR 17810 | 98507-17810 | \$ 6,956.00 | 6% | <i>\$6,587.68</i> |
| EWPP PremierPLS 4HR AHR 18101 | 98507-18101 | \$ 750.00 | 6% | <i>\$710.29</i> |
| EWPP PremierPLS 4HR AHR 18102 | 98507-18102 | \$ 848.00 | 6% | <i>\$803.10</i> |
| EWPP PremierPLS 4HR AHR 18103 | 98507-18103 | \$ 894.00 | 6% | <i>\$846.66</i> |
| EWPP PremierPLS 4HR AHR 18104 | 98507-18104 | \$ 1,111.00 | 6% | <i>\$1,052.17</i> |
| EWPP PremierPLS 4HR AHR 18104-6PK | 98507-18104- 6PK | \$ 6,666.00 | 6% | <i>\$6,313.04</i> |
| EWPP PremierPLS 4HR AHR 30135 | 98507-30135 | \$ 3,288.00 | 6% | <i>\$3,113.90</i> |
| EWPP PremierPLS 4HR AHR 30136 | 98507-30136 | \$ 10,354.00 | 6% | <i>\$9,805.76</i> |
| EWPP PremierPLS 4HR AHR 30137 | 98507-30137 | \$ 3,222.00 | 6% | <i>\$3,051.40</i> |
| EWPP PremierPLS 4HR AHR 30138 | 98507-30138 | \$ 8,414.00 | 6% | <i>\$7,968.48</i> |
| EWPP PremierPLS 4HR AHR 30139 | 98507-30139 | \$ 13,116.00 | 6% | <i>\$12,421.51</i> |
| EWPP PremierPLS 4HR AHR 30912 | 98507-30912 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremierPLS 4HR AHR 30913 | 98507-30913 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremierPLS 4HR AHR 31012 | 98507-31012 | \$ 480.00 | 6% | <i>\$454.58</i> |

| | | | | |
|----------------------------------|-------------|-----------|----|-----------------|
| EWPP PremierPLS 4HR AHR 31013 | 98507-31013 | \$ 480.00 | 6% | <i>\$454.58</i> |
| EWPP PremierPLS 4HR AHR 31014 | 98507-31014 | \$ 480.00 | 6% | <i>\$454.58</i> |
| EWPP PremierPLS 4HR AHR 31015 | 98507-31015 | \$ 480.00 | 6% | <i>\$454.58</i> |
| EWPP PremierPLS 4HR AHR 31016 | 98507-31016 | \$ 704.00 | 6% | <i>\$666.72</i> |
| EWPP PremierPLS 4HR AHR 31017 | 98507-31017 | \$ 704.00 | 6% | <i>\$666.72</i> |
| EWPP PremierPLS 4HR AHR 31018 | 98507-31018 | \$ 762.00 | 6% | <i>\$721.65</i> |
| EWPP PremierPLS 4HR AHR 31019 | 98507-31019 | \$ 762.00 | 6% | <i>\$721.65</i> |
| EWPP PremierPLS 4HR AHR 31025 | 98507-31025 | \$ 387.00 | 6% | <i>\$366.51</i> |
| EWPP PremierPLS 4HR AHR 31026 | 98507-31026 | \$ 387.00 | 6% | <i>\$366.51</i> |
| EWPP PremierPLS 4HR AHR 31028 | 98507-31028 | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR 31029 | 98507-31029 | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR 31031 | 98507-31031 | \$ 400.00 | 6% | <i>\$378.82</i> |
| EWPP PremierPLS 4HR AHR 31032 | 98507-31032 | \$ 400.00 | 6% | <i>\$378.82</i> |
| EWPP PremierPLS 4HR AHR 31034 | 98507-31034 | \$ 489.00 | 6% | <i>\$463.11</i> |
| EWPP PremierPLS 4HR AHR 31035 | 98507-31035 | \$ 489.00 | 6% | <i>\$463.11</i> |
| EWPP PremierPLS 4HR AHR 31050 | 98507-31050 | \$ 460.00 | 6% | <i>\$435.64</i> |
| EWPP PremierPLS 4HR AHR 31051 | 98507-31051 | \$ 460.00 | 6% | <i>\$435.64</i> |
| EWPP PremierPLS 4HR AHR 31055 | 98507-31055 | \$ 460.00 | 6% | <i>\$435.64</i> |
| EWPP PremierPLS 4HR AHR 31056 | 98507-31056 | \$ 460.00 | 6% | <i>\$435.64</i> |
| EWPP PremierPLS 4HR AHR 39031 | 98507-39031 | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWPP PremierPLS 4HR AHR 39032 | 98507-39032 | \$ 947.00 | 6% | <i>\$896.86</i> |

| | | | | |
|--|---------------------------|-------------|-----|-------------------|
| EWPP PremierPLS 4HR AHR 39033 | 98507-39033 | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWPP PremierPLS 4HR AHR 39034 | 98507-39034 | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWPP PremierPLS 4HR AHR 39035 | 98507-39035 | \$ 1,892.00 | 6% | <i>\$1,791.82</i> |
| EWPP PremierPLS 4HR AHR 39036 | 98507-39036 | \$ 797.00 | 6% | <i>\$754.80</i> |
| EWPP PremierPLS 4HR AHR 39037 | 98507-39037 | \$ 797.00 | 6% | <i>\$754.80</i> |
| EWPP PremierPLS 4HR AHR 39038 | 98507-39038 | \$ 963.00 | 6% | <i>\$912.01</i> |
| EWPP PremierPLS 4HR AHR 39039 | 98507-39039 | \$ 963.00 | 6% | <i>\$912.01</i> |
| EWPP PremierPLS 4HR AHR 4120-24MW-4Y | 98507-4120- 24MW-4Y | \$ 1,845.00 | 6% | <i>\$1,747.31</i> |
| EWPP PremierPLS 4HR AHR 4120-48MW-4Y | 98507-4120- 48MW-4Y | \$ 2,190.00 | 6% | <i>\$2,074.04</i> |
| EWPP PremierPLS 4HR AHR 4120C | 98507-4120C | \$ 9,053.00 | 10% | <i>\$8,208.81</i> |
| EWPP PremierPLS 4HR AHR 4120C-1 | 98507-4120C-1 | \$ 8,839.00 | 6% | <i>\$8,370.97</i> |
| EWPP PremierPLS 4HR AHR 41216 | 98507-41216 | \$ 2,761.00 | 6% | <i>\$2,614.81</i> |
| EWPP PremierPLS 4HR AHR 4220-12P-4X | 98507-4220- 12P-4X | \$ 1,112.00 | 6% | <i>\$1,053.12</i> |
| EWPP PremierPLS 4HR AHR 4220-12T-4X | 98507-4220- 12T-4X | \$ 1,031.00 | 6% | <i>\$976.41</i> |
| EWPP PremierPLS 4HR AHR 4220-24P-4X | 98507-4220- 24P-4X | \$ 1,213.00 | 6% | <i>\$1,148.77</i> |
| EWPP PremierPLS 4HR AHR 4220-24T-4X | 98507-4220- 24T-4X | \$ 1,122.00 | 6% | <i>\$1,062.59</i> |
| EWPP PremierPLS 4HR AHR 4220-48P-4X | 98507-4220- 48P-4X | \$ 1,415.00 | 6% | <i>\$1,340.08</i> |
| EWPP PremierPLS 4HR AHR 4220-48T-4X | 98507-4220- 48T-4X | \$ 1,263.00 | 6% | <i>\$1,196.12</i> |
| EWPP PremierPLS 4HR AHR 4220-4MW-20P-4X | 98507-4220- 4MW-20P-4X | \$ 1,365.00 | 6% | <i>\$1,292.72</i> |
| EWPP PremierPLS 4HR AHR 4220-4MW-8P-4X | 98507-4220- 4MW-8P-4X | \$ 1,203.00 | 6% | <i>\$1,139.30</i> |
| EWPP PremierPLS 4HR AHR 4220-8MW-40P-4X | 98507-4220- 8MW-40P-4X | \$ 1,618.00 | 6% | <i>\$1,532.33</i> |

| | | | | |
|---|-----------------------------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR 4220-8X | 98507-4220-8X | \$ 1,233.00 | 6% | <i>\$1,167.71</i> |
| EWPP PremierPLS 4HR AHR 48001 | 98507-48001 | \$ 11,824.00 | 6% | <i>\$11,197.92</i> |
| EWPP PremierPLS 4HR AHR 48038 | 98507-48038 | \$ 4,293.00 | 6% | <i>\$4,065.69</i> |
| EWPP PremierPLS 4HR AHR 48039 | 98507-48039 | \$ 4,293.00 | 6% | <i>\$4,065.69</i> |
| EWPP PremierPLS 4HR AHR 48040 | 98507-48040 | \$ 4,105.00 | 6% | <i>\$3,887.64</i> |
| EWPP PremierPLS 4HR AHR 48041 | 98507-48041 | \$ 4,293.00 | 6% | <i>\$4,065.69</i> |
| EWPP PremierPLS 4HR AHR 48046 | 98507-48046 | \$ 5,499.00 | 6% | <i>\$5,207.83</i> |
| EWPP PremierPLS 4HR AHR 48047 | 98507-48047 | \$ 13,903.00 | 6% | <i>\$13,166.84</i> |
| EWPP PremierPLS 4HR AHR 48051 | 98507-48051 | \$ 9,701.00 | 6% | <i>\$9,187.33</i> |
| EWPP PremierPLS 4HR AHR 48061 | 98507-48061 | \$ 11,264.00 | 6% | <i>\$10,667.57</i> |
| EWPP PremierPLS 4HR AHR 48062 | 98507-48062 | \$ 17,749.00 | 6% | <i>\$16,809.19</i> |
| EWPP PremierPLS 4HR AHR 5320-16P-4XE | 98507-5320- 16P-4XE | \$ 1,399.00 | 6% | <i>\$1,324.92</i> |
| EWPP PremierPLS 4HR AHR 5320-16P-4XE-DC | 98507-5320- 16P-4XE-DC | \$ 1,482.00 | 6% | <i>\$1,403.53</i> |
| EWPP PremierPLS 4HR AHR 5320-24P-8XE | 98507-5320- 24P-8XE | \$ 1,428.00 | 6% | <i>\$1,352.39</i> |
| EWPP PremierPLS 4HR 5320- 24T-24S-4XE-XT | 98507-5320- 24T-24S-4XE- XT | \$ 1,361.00 | 6% | <i>\$1,288.94</i> |
| EWPP PremierPLS 4HR AHR 5320-24T-4X-XT | 98507-5320- 24T-4X-XT | \$ 1,106.00 | 6% | <i>\$1,047.44</i> |
| EWPP PremierPLS 4HR AHR 5320-24T-8XE | 98507-5320- 24T-8XE | \$ 1,307.00 | 6% | <i>\$1,237.79</i> |
| EWPP PremierPLS 4HR AHR 5320-48P-8XE | 98507-5320- 48P-8XE | \$ 1,781.00 | 6% | <i>\$1,686.70</i> |
| EWPP PremierPLS 4HR AHR 5320-48T-8XE | 98507-5320- 48T-8XE | \$ 1,561.00 | 6% | <i>\$1,478.35</i> |
| EWPP PremiPLS 4HR AHR 5420F-16MW-32P-4XE | 98507-5420F- 16MW-32P- 4XE | \$ 2,545.00 | 6% | <i>\$2,410.24</i> |

| | | | | |
|---|----------------------------------|-------------|-----|------------|
| EWPP PremPLS 4HR AHR 5420F-16W-32P-4XE | 98507-5420F- 16W-32P-4XE | \$ 2,485.00 | 6% | \$2,353.42 |
| EWPP PremierPLS 4HR AHR 5420F-24P-4XE | 98507-5420F- 24P-4XE | \$ 1,745.00 | 6% | \$1,652.60 |
| EWPP PremierPLS 4HR AHR 5420F-24S-4XE | 98507-5420F- 24S-4XE | \$ 1,817.00 | 6% | \$1,720.79 |
| EWPP PremierPLS 4HR AHR 5420F-24T-4XE | 98507-5420F- 24T-4XE | \$ 1,688.00 | 6% | \$1,598.62 |
| EWPP PremierPLS 4HR AHR 5420F-48P-4XE | 98507-5420F- 48P-4XE | \$ 2,029.00 | 6% | \$1,921.56 |
| EWPP PremierPLS 4HR AHR 5420F-48P-4XL | 98507-5420F- 48P-4XL | \$ 2,200.00 | 6% | \$2,083.51 |
| EWPP PremierPLS 4HR AHR 5420F-48T-4XE | 98507-5420F- 48T-4XE | \$ 1,813.00 | 6% | \$1,717.00 |
| EWPP PremierPLS 4HR AHR 5420F-8W-16P-4XE | 98507-5420F- 8W-16P-4XE | \$ 1,851.00 | 6% | \$1,752.99 |
| EWPP PremPLS 4HR AHR 5420M-16MW-32P-4YE | 98507-5420M- 16MW-32P- 4YE | \$ 2,719.00 | 6% | \$2,575.03 |
| EWPP PremierPLS 4HR AHR 5420M-24T-4YE | 98507-5420M- 24T-4YE | \$ 1,832.00 | 6% | \$1,735.00 |
| EWPP PremierPLS 4HR AHR 5420M-24W-4YE | 98507-5420M- 24W-4YE | \$ 1,639.00 | 6% | \$1,552.21 |
| EWPP PremierPLS 4HR AHR 5420M-48T-4YE | 98507-5420M- 48T-4YE | \$ 2,073.00 | 6% | \$1,963.23 |
| EWPP PremierPLS 4HR AHR 5420M-48W-4YE | 98507-5420M- 48W-4YE | \$ 2,192.00 | 6% | \$2,075.93 |
| EWPP PREMIERPLUS 4HR AHR 5520-12MW-36W | 98507-5520- 12MW-36W | \$ 2,871.00 | 6% | \$2,718.98 |
| EWPP PREMIERPLUS 4HR AHR 5520-24T | 98507-5520- 24T | \$ 1,773.00 | 6% | \$1,679.12 |
| EWPP PREMIERPL 4HR AH 5520-24T-ACDC-BASE | 98507-5520- 24T-ACDC- BASE | \$ 1,773.00 | 6% | \$1,679.12 |
| EWPP PREMIERPLUS 4HR AHR 5520-24T-BASE | 98507-5520- 24T-BASE | \$ 1,773.00 | 10% | \$1,607.67 |
| EWPP PREMIERPLUS 4HR AHR 5520-24W | 98507-5520- 24W | \$ 1,908.00 | 6% | \$1,806.97 |
| EWPP PREMIERPLUS 4HR AHR 5520-24X | 98507-5520- 24X | \$ 2,900.00 | 6% | \$2,746.45 |

| | | | | |
|---|-----------------------------------|-------------|-----|------------|
| EWPP PREMIERPL 4HR AH 5520-24X-ACDC-BASE | 98507-5520- 24X-ACDC- BASE | \$ 2,900.00 | 6% | \$2,746.45 |
| EWPP PREMIERPLUS 4HR AHR 5520-24X-BASE | 98507-5520- 24X-BASE | \$ 2,900.00 | 10% | \$2,629.58 |
| EWPP PREMIERPLUS 4HR AHR 5520-48SE | 98507-5520- 48SE | \$ 2,783.00 | 6% | \$2,635.64 |
| EWPP PREMIERPL 4HR A 5520-48SE-ACDC-BASE | 98507-5520- 48SE-ACDC- BASE | \$ 2,783.00 | 6% | \$2,635.64 |
| EWPP PREMIERPLUS 4HR AHR 5520-48SE-BASE | 98507-5520- 48SE-BASE | \$ 2,783.00 | 10% | \$2,523.49 |
| EWPP PREMIERPLUS 4HR AHR 5520-48T | 98507-5520- 48T | \$ 2,259.00 | 6% | \$2,139.39 |
| EWPP PREMIERPL 4HR AH 5520-48T-ACDC-BASE | 98507-5520- 48T-ACDC- BASE | \$ 2,259.00 | 6% | \$2,139.39 |
| EWPP PREMIERPLUS 4HR AHR 5520-48T-BASE | 98507-5520- 48T-BASE | \$ 2,259.00 | 10% | \$2,048.35 |
| EWPP PREMIERPLUS 4HR AHR 5520-48W | 98507-5520- 48W | \$ 2,535.00 | 6% | \$2,400.77 |
| EWPP PremierPLS 4HR AHR 5720-24MW | 98507-5720- 24MW | \$ 2,463.00 | 6% | \$2,332.58 |
| EWPP PremierPLS 4HR AHR 5720-24MXW | 98507-5720- 24MXW | \$ 2,594.00 | 6% | \$2,456.65 |
| EWPP PremierPLS 4HR AHR 5720-48MW | 98507-5720- 48MW | \$ 2,256.00 | 6% | \$2,136.54 |
| EWPP PremierPLS 4HR AHR 5720-48MXW | 98507-5720- 48MXW | \$ 3,272.00 | 6% | \$3,098.75 |
| EWPP PremierPLS 4HR AHR 7520-48XT-6C | 98507-7520- 48XT-6C | \$ 4,449.00 | 6% | \$4,213.43 |
| EWPP PremierPLS 4HR AH 7520-48XT-6C-AC-F | 98507-7520- 48XT-6C-AC- F | \$ 4,449.00 | 6% | \$4,213.43 |
| EWPP PremierPLS 4HR AH 7520-48XT-6C-AC-R | 98507-7520- 48XT-6C-AC- R | \$ 4,449.00 | 6% | \$4,213.43 |
| EWPP PremierPLS 4HR AHR 7520-48Y-8C | 98507-7520- 48Y-8C | \$ 4,154.00 | 6% | \$3,934.05 |
| EWPP PremierPLS 4HR AHR 7520-48Y-8C-AC-F | 98507-7520- 48Y-8C-AC-F | \$ 4,154.00 | 6% | \$3,934.05 |
| EWPP PremierPLS 4HR AHR 7520-48Y-8C-AC-R | 98507-7520- 48Y-8C-AC-R | \$ 4,154.00 | 6% | \$3,934.05 |

| | | | | |
|---|----------------------------------|-------------|----|-------------------|
| EWPP PREMIERPLUS 4HR AHR 7520-48YE-8CE | 98507-7520- 48YE-8CE | \$ 4,810.00 | 6% | <i>\$4,555.31</i> |
| EWPP PREMIERPL 4HRAHR 7520-48YE-8CE-AC-F | 98507-7520- 48YE-8CE-AC- F | \$ 4,810.00 | 6% | <i>\$4,555.31</i> |
| EWPP PREMIERPL 4HRAHR 7520-48YE-8CE-AC-R | 98507-7520- 48YE-8CE-AC- R | \$ 4,810.00 | 6% | <i>\$4,555.31</i> |
| EWPP PremierPLS 4HR AHR 7720-32C | 98507-7720- 32C | \$ 5,141.00 | 6% | <i>\$4,868.78</i> |
| EWPP PremierPLS 4HR AHR 7720-32C-AC-F | 98507-7720- 32C-AC-F | \$ 5,141.00 | 6% | <i>\$4,868.78</i> |
| EWPP PremierPLS 4HR AHR 7720-32C-AC-R | 98507-7720- 32C-AC-R | \$ 5,141.00 | 6% | <i>\$4,868.78</i> |
| EWPP PremierPLS 4HR AHR 8520-48XT-6C | 98507-8520- 48XT-6C | \$ 5,155.00 | 6% | <i>\$4,882.04</i> |
| EWPP PremPLS 4HR AHR 8520- 48XT-6C-AC-F | 98507-8520- 48XT-6C-AC- F | \$ 5,155.00 | 6% | <i>\$4,882.04</i> |
| EWPP PremPLS 4HR AHR 8520- 48XT-6C-AC-R | 98507-8520- 48XT-6C-AC- R | \$ 5,155.00 | 6% | <i>\$4,882.04</i> |
| EWPP PremPLS 4HR AHR 8520- 48XT-6C-DC-F | 98507-8520- 48XT-6C-DC- F | \$ 5,155.00 | 6% | <i>\$4,882.04</i> |
| EWPP PremPLS 4HR AHR 8520- 48XT-6C-DC-R | 98507-8520- 48XT-6C-DC- R | \$ 5,155.00 | 6% | <i>\$4,882.04</i> |
| EWPP PremierPLS 4HR AHR 8520-48Y-8C | 98507-8520- 48Y-8C | \$ 5,336.00 | 6% | <i>\$5,053.46</i> |
| EWPP PremierPLS 4HR AHR 8520-48Y-8C-AC-F | 98507-8520- 48Y-8C-AC-F | \$ 5,336.00 | 6% | <i>\$5,053.46</i> |
| EWPP PremierPLS 4HR AHR 8520-48Y-8C-AC-R | 98507-8520- 48Y-8C-AC-R | \$ 5,336.00 | 6% | <i>\$5,053.46</i> |
| EWPP PremierPLS 4HR AHR 8520-48Y-8C-DC-F | 98507-8520- 48Y-8C-DC-F | \$ 5,336.00 | 6% | <i>\$5,053.46</i> |
| EWPP PremierPLS 4HR AHR 8520-48Y-8C-DC-R | 98507-8520- 48Y-8C-DC-R | \$ 5,336.00 | 6% | <i>\$5,053.46</i> |
| EWPP PremierPLS 4HR AHR 8720-32C | 98507-8720- 32C | \$ 5,792.00 | 6% | <i>\$5,485.31</i> |
| EWPP PremierPLS 4HR AHR 8720-32C-AC-F | 98507-8720- 32C-AC-F | \$ 5,792.00 | 6% | <i>\$5,485.31</i> |

| | | | | |
|---|-----------------------------|--------------|-----|--------------------|
| EWPP PremierPLS 4HR AHR 8720-32C-AC-R | 98507-8720- 32C-AC-R | \$ 5,792.00 | 6% | <i>\$5,485.31</i> |
| EWPP PremierPLS 4HR AHR 8720-32C-DC-F | 98507-8720- 32C-DC-F | \$ 5,792.00 | 6% | <i>\$5,485.31</i> |
| EWPP PremierPLS 4HR AHR 8720-32C-DC-R | 98507-8720- 32C-DC-R | \$ 5,792.00 | 6% | <i>\$5,485.31</i> |
| EWPP PremierPLS 4HR AHR 8806 | 98507-8806 | \$ 5,003.00 | 6% | <i>\$4,738.09</i> |
| EWPP PremierPLS 4HR AHR 8810 | 98507-8810 | \$ 10,205.00 | 6% | <i>\$9,664.65</i> |
| EWPP PremierPLS 4HR AHR 8820-40C | 98507-8820- 40C | \$ 19,582.00 | 10% | <i>\$17,755.98</i> |
| EWPP PremierPLS 4HR AHR 8820-40C-AC-F | 98507-8820- 40C-AC-F | \$ 19,582.00 | 10% | <i>\$17,755.98</i> |
| EWPP PremierPLS 4HR AHR 8820-40C-AC-R | 98507-8820- 40C-AC-R | \$ 19,582.00 | 10% | <i>\$17,755.98</i> |
| EWPP PremierPLS 4HR AHR 8820-40C-DC-F | 98507-8820- 40C-DC-F | \$ 19,582.00 | 10% | <i>\$17,755.98</i> |
| EWPP PremierPLS 4HR AHR 8820-40C-DC-R | 98507-8820- 40C-DC-R | \$ 19,582.00 | 10% | <i>\$17,755.98</i> |
| EWPP PremierPLS 4HR AHR 8820-80C | 98507-8820- 80C | \$ 34,767.00 | 10% | <i>\$31,524.98</i> |
| EWPP PremierPLS 4HR AHR 8820-80C-AC-F | 98507-8820- 80C-AC-F | \$ 34,767.00 | 10% | <i>\$31,524.98</i> |
| EWPP PremierPLS 4HR AHR 8820-80C-AC-R | 98507-8820- 80C-AC-R | \$ 34,767.00 | 10% | <i>\$31,524.98</i> |
| EWPP PremierPLS 4HR AHR 8820-80C-DC-F | 98507-8820- 80C-DC-F | \$ 34,767.00 | 10% | <i>\$31,524.98</i> |
| EWPP PremierPLS 4HR AHR 8820-80C-DC-R | 98507-8820- 80C-DC-R | \$ 34,767.00 | 10% | <i>\$31,524.98</i> |
| EWPP PremierPLS 4HR AHR 9920-16C | 98507-9920- 16C | \$ 14,659.00 | 6% | <i>\$13,882.81</i> |
| EWPP PremierPLS 4HR AHR 9920-4D | 98507-9920-4D | \$ 14,659.00 | 6% | <i>\$13,882.81</i> |
| EWPP PremierPLS 4HR AHR 9920-NPB-8 | 98507-9920- NPB-8 | \$ 23,271.00 | 6% | <i>\$22,038.80</i> |
| EWPP PremierPLS 4HR AHR AH-AP-1130-AC-CE | 98507-AH-AP- 1130-AC-CE | \$ 434.00 | 6% | <i>\$411.02</i> |
| EWPP PremierPLS 4HR AHR AH-AP-1130-AC-FC | 98507-AH-AP- 1130-AC-FCC | \$ 434.00 | 6% | <i>\$411.02</i> |
| EWPP PremierPLS 4HR AHR AH-AP-1130-AC-W | 98507-AH-AP- 1130-AC-W | \$ 434.00 | 6% | <i>\$411.02</i> |

| | | | | |
|---|---------------------------------|-----------|----|-----------------|
| EWPP PremierPLS 4HR AHR AH-AP-122-AC-CAN | 98507-AH-AP- 122-AC-CAN | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-122-AC-CE | 98507-AH-AP- 122-AC-CE | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-122-AC-FCC | 98507-AH-AP- 122-AC-FCC | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-122-AC-W | 98507-AH-AP- 122-AC-W | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-130-AC-CE | 98507-AH-AP- 130-AC-CE | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-130-AC-FCC | 98507-AH-AP- 130-AC-FCC | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-130-AC-W | 98507-AH-AP- 130-AC-W | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-150W-AC-CA | 98507-AH-AP- 150W-AC- CAN | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-150W-AC-CE | 98507-AH-AP- 150W-AC-CE | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-150W-AC-FC | 98507-AH-AP- 150W-AC-FCC | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-150W-AC-W | 98507-AH-AP- 150W-AC-W | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-230-AC-CE | 98507-AH-AP- 230-AC-CE | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-230-AC-FCC | 98507-AH-AP- 230-AC-FCC | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-230-AC-W | 98507-AH-AP- 230-AC-W | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-250-AC-CAN | 98507-AH-AP- 250-AC-CAN | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-250-AC-CE | 98507-AH-AP- 250-AC-CE | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-250-AC-FCC | 98507-AH-AP- 250-AC-FCC | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-250-AC-W | 98507-AH-AP- 250-AC-W | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR AH-AP-630-AX-CAN | 98507-AH-AP- 630-AX-CAN | \$ 439.00 | 6% | <i>\$415.75</i> |
| EWPP PremierPLS 4HR AHR AH-AP-630-AX-CE | 98507-AH-AP- 630-AX-CE | \$ 439.00 | 6% | <i>\$415.75</i> |

| | | | | |
|---|---------------------------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR AH-AP-630-AX-FCC | 98507-AH-AP- 630-AX-FCC | \$ 439.00 | 6% | <i>\$415.75</i> |
| EWPP PremierPLS 4HR AHR AH-AP-630-AX-W | 98507-AH-AP- 630-AX-W | \$ 439.00 | 6% | <i>\$415.75</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650-AX-CAN | 98507-AH-AP- 650-AX-CAN | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650-AX-CE | 98507-AH-AP- 650-AX-CE | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650-AX-FCC | 98507-AH-AP- 650-AX-FCC | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650-AX-W | 98507-AH-AP- 650-AX-W | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650X-AX-CA | 98507-AH-AP- 650X-AX- CAN | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650X-AX-CE | 98507-AH-AP- 650X-AX-CE | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650X-AX-FC | 98507-AH-AP- 650X-AX-FCC | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-AP-650X-AX-W | 98507-AH-AP- 650X-AX-W | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HR AHR AH-ATOM-CAN | 98507-AH- ATOM-CAN | \$ 405.00 | 6% | <i>\$383.56</i> |
| EWPP PremierPLS 4HR AHR AH-ATOM-CE-EU | 98507-AH- ATOM-CE-EU | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWPP PremierPLS 4HR AHR AH-ATOM-CE-UK | 98507-AH- ATOM-CE-UK | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWPP PremierPLS 4HR AHR AH-ATOM-FCC | 98507-AH- ATOM-FCC | \$ 405.00 | 6% | <i>\$383.56</i> |
| EWPP PremierPLS 4HR AHR AH-ATOM-W | 98507-AH- ATOM-W | \$ 405.00 | 6% | <i>\$383.56</i> |
| EWPP PremierPLS 4HR AHR AH-ATOM-W-EU | 98507-AH- ATOM-W-EU | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWPP PremierPLS 4HR AHR AH-ATOM-W-UK | 98507-AH- ATOM-W-UK | \$ 425.00 | 6% | <i>\$402.50</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2208P-AU | 98507-AH-SR- 2208P-AU | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2208P-EU | 98507-AH-SR- 2208P-EU | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |

| | | | | |
|---|--------------------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR AH-SR-2208P-NA | 98507-AH-SR- 2208P-NA | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2208P-UK | 98507-AH-SR- 2208P-UK | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2224P-AU | 98507-AH-SR- 2224P-AU | \$ 1,203.00 | 6% | <i>\$1,139.30</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2224P-EU | 98507-AH-SR- 2224P-EU | \$ 1,203.00 | 6% | <i>\$1,139.30</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2224P-NA | 98507-AH-SR- 2224P-NA | \$ 1,203.00 | 6% | <i>\$1,139.30</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2224P-UK | 98507-AH-SR- 2224P-UK | \$ 1,203.00 | 6% | <i>\$1,139.30</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2324P-AU | 98507-AH-SR- 2324P-AU | \$ 1,252.00 | 6% | <i>\$1,185.71</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2324P-EU | 98507-AH-SR- 2324P-EU | \$ 1,252.00 | 6% | <i>\$1,185.71</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2324P-NA | 98507-AH-SR- 2324P-NA | \$ 1,252.00 | 6% | <i>\$1,185.71</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2324P-UK | 98507-AH-SR- 2324P-UK | \$ 1,252.00 | 6% | <i>\$1,185.71</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2348P-AU | 98507-AH-SR- 2348P-AU | \$ 1,414.00 | 6% | <i>\$1,339.13</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2348P-EU | 98507-AH-SR- 2348P-EU | \$ 1,414.00 | 6% | <i>\$1,339.13</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2348P-NA | 98507-AH-SR- 2348P-NA | \$ 1,414.00 | 6% | <i>\$1,339.13</i> |
| EWPP PremierPLS 4HR AHR AH-SR-2348P-UK | 98507-AH-SR- 2348P-UK | \$ 1,414.00 | 6% | <i>\$1,339.13</i> |
| EWPP PremierPLS 4HR AHR AH-XR200P-AU | 98507-AH- XR200P-AU | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWPP PremierPLS 4HR AHR AH-XR200P-EU | 98507-AH- XR200P-EU | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWPP PremierPLS 4HR AHR AH-XR200P-UK | 98507-AH- XR200P-UK | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWPP PremierPLS 4HR AHR AH-XR200P-US | 98507-AH- XR200P-US | \$ 1,161.00 | 6% | <i>\$1,099.53</i> |
| EWPP PremierPLS 4HR AHR AH-XR600P | 98507-AH- XR600P | \$ 1,168.00 | 6% | <i>\$1,106.15</i> |
| EWPP PremierPLS 4HR AHR AH-XR600P-AU | 98507-AH- XR600P-AU | \$ 1,173.00 | 6% | <i>\$1,110.89</i> |
| EWPP PremierPLS 4HR AHR AH-XR600P-EU | 98507-AH- XR600P-EU | \$ 1,173.00 | 6% | <i>\$1,110.89</i> |

| | | | | |
|---|---------------------------------|-------------|-----|-------------------|
| EWPP PremierPLS 4HR AHR AH-XR600P-KR | 98507-AH- XR600P-KR | \$ 1,173.00 | 6% | <i>\$1,110.89</i> |
| EWPP PremierPLS 4HR AHR AH-XR600P-UK | 98507-AH- XR600P-UK | \$ 1,173.00 | 6% | <i>\$1,110.89</i> |
| EWPP PremierPLS 4HR AHR AH-XR600P-US | 98507-AH- XR600P-US | \$ 1,173.00 | 6% | <i>\$1,110.89</i> |
| EWPP PremierPLS 4HR AHR AP-8533-IL | 98507-AP- 8533-68SB30- IL | \$ 419.00 | 6% | <i>\$396.81</i> |
| EWPP PremierPLS 4HR AHR AP3000-IL | 98507-AP3000- IL | \$ 276.39 | 6% | <i>\$261.76</i> |
| EWPP PremierPLS 4HR AHR AP3000-TN | 98507-AP3000- TN | \$ 276.39 | 6% | <i>\$261.76</i> |
| EWPP PremierPLS 4HR AHR AP3000-WW | 98507-AP3000- WW | \$ 276.39 | 6% | <i>\$261.76</i> |
| EWPP PremierPLS 4HR AHR AP3000X-WW | 98507- AP3000X-WW | \$ 297.27 | 6% | <i>\$281.52</i> |
| EWPP PremierPLS 4HR AHR AP302W-CAN | 98507- AP302W-CAN | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS 4HR AHR AP302W-EG | 98507- AP302W-EG | \$ 285.00 | 10% | <i>\$258.42</i> |
| EWPP PremierPLS 4HR AHR AP302W-FCC | 98507- AP302W-FCC | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremierPLS 4HR AHR AP302W-WR | 98507- AP302W-WR | \$ 378.00 | 6% | <i>\$357.98</i> |
| EWPP PremierPLS 4HR AHR AP305C-1-CAN | 98507-AP305C- 1-CAN | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS 4HR AHR AP305C-1-EG | 98507-AP305C- 1-EG | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS 4HR AHR AP305C-FCC | 98507-AP305C- 1-FCC | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS 4HR AHR AP305C-1-IL | 98507-AP305C- 1-IL | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS 4HR AHR AP305C-1-WR | 98507-AP305C- 1-WR | \$ 385.00 | 6% | <i>\$364.61</i> |
| EWPP PremierPLS 4HR AHR AP305C-CAN | 98507-AP305C- CAN | \$ 413.00 | 6% | <i>\$391.13</i> |
| EWPP PremierPLS 4HR AHR AP305C-EG | 98507-AP305C- EG | \$ 413.00 | 6% | <i>\$391.13</i> |

| | | | | |
|-------------------------------------|-------------------|-----------|-----|----------|
| EWPP PremierPLS 4HR AHR AP305C-FCC | 98507-AP305C-FCC | \$ 413.00 | 6% | \$391.13 |
| EWPP PremierPLS 4HR AHR AP305C-IL | 98507-AP305C-IL | \$ 413.00 | 6% | \$391.13 |
| EWPP PremierPLS 4HR AHR AP305C-WR | 98507-AP305C-WR | \$ 413.00 | 6% | \$391.13 |
| EWPP PremierPLS 4HR AHR AP305CX-CAN | 98507-AP305CX-CAN | \$ 413.00 | 6% | \$391.13 |
| EWPP PremierPLS 4HR AHR AP305CX-FCC | 98507-AP305CX-FCC | \$ 413.00 | 6% | \$391.13 |
| EWPP PremierPLS 4HR AHR AP305CX-IL | 98507-AP305CX-IL | \$ 413.00 | 6% | \$391.13 |
| EWPP PremierPLS 4HR AHR AP305CX-WR | 98507-AP305CX-WR | \$ 413.00 | 6% | \$391.13 |
| EWPP PremierPLS 4HR AHR AP310e-1-WR | 98507-AP310e-1-WR | \$ 367.00 | 10% | \$332.78 |
| EWPP PremierPLS 4HR AHR AP310e-CAN | 98507-AP310e-CAN | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP310e-FCC | 98507-AP310e-FCC | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP310e-IL | 98507-AP310e-IL | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP310e-WR | 98507-AP310e-WR | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP310i-1-WR | 98507-AP310i-1-WR | \$ 367.00 | 10% | \$332.78 |
| EWPP PremierPLS 4HR AHR AP310i-CAN | 98507-AP310i-CAN | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP310i-FCC | 98507-AP310i-FCC | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP310i-IL | 98507-AP310i-IL | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP310i-WR | 98507-AP310i-WR | \$ 385.00 | 6% | \$364.61 |
| EWPP PremierPLS 4HR AHR AP360e-CAN | 98507-AP360e-CAN | \$ 416.00 | 6% | \$393.97 |
| EWPP PremierPLS 4HR AHR AP360e-FCC | 98507-AP360e-FCC | \$ 416.00 | 6% | \$393.97 |
| EWPP PremierPLS 4HR AHR AP360e-IL | 98507-AP360e-IL | \$ 416.00 | 6% | \$393.97 |

| | | | | |
|--------------------------------------|--------------------|-----------|----|----------|
| EWPP PremierPLS 4HR AHR AP360e-WR | 98507-AP360e-WR | \$ 416.00 | 6% | \$393.97 |
| EWPP PremierPLS 4HR AHR AP360i-CAN | 98507-AP360i-CAN | \$ 416.00 | 6% | \$393.97 |
| EWPP PremierPLS 4HR AHR AP360i-FCC | 98507-AP360i-FCC | \$ 416.00 | 6% | \$393.97 |
| EWPP PremierPLS 4HR AHR AP360i-WR | 98507-AP360i-WR | \$ 416.00 | 6% | \$393.97 |
| EWPP PremierPLS 4HR AHR AP4000-WW | 98507-AP4000-1-WW | \$ 364.00 | 6% | \$344.73 |
| EWPP PremierPLS 4HR AHR AP4000-IL | 98507-AP4000-IL | \$ 364.00 | 6% | \$344.73 |
| EWPP PremierPLS 4HR AHR AP4000-WW | 98507-AP4000-WW | \$ 364.00 | 6% | \$344.73 |
| EWPP PremierPLS 4HR AHR AP410C-1-CAN | 98507-AP410C-1-CAN | \$ 379.00 | 6% | \$358.93 |
| EWPP PremierPLS 4HR AHR AP410C-1-EG | 98507-AP410C-1-EG | \$ 379.00 | 6% | \$358.93 |
| EWPP PremierPLS 4HR AHR AP410C-1-FCC | 98507-AP410C-1-FCC | \$ 379.00 | 6% | \$358.93 |
| EWPP PremierPLS 4HR AHR AP410C-1-IL | 98507-AP410C-1-IL | \$ 379.00 | 6% | \$358.93 |
| EWPP PremierPLS 4HR AHR AP410C-1-WR | 98507-AP410C-1-WR | \$ 379.00 | 6% | \$358.93 |
| EWPP PremierPLS 4HR AHR AP410C-CAN | 98507-AP410C-CAN | \$ 407.00 | 6% | \$385.45 |
| EWPP PremierPLS 4HR AHR AP410C-EG | 98507-AP410C-EG | \$ 407.00 | 6% | \$385.45 |
| EWPP PremierPLS 4HR AHR AP410C-FCC | 98507-AP410C-FCC | \$ 407.00 | 6% | \$385.45 |
| EWPP PremierPLS 4HR AHR AP410C-IL | 98507-AP410C-IL | \$ 407.00 | 6% | \$385.45 |
| EWPP PremierPLS 4HR AHR AP410C-WR | 98507-AP410C-WR | \$ 407.00 | 6% | \$385.45 |
| EWPP PremierPLS 4HR AHR AP410e-CAN | 98507-AP410e-CAN | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP410e-FCC | 98507-AP410e-FCC | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP410e-WR | 98507-AP410e-WR | \$ 435.00 | 6% | \$411.97 |

| | | | | |
|---------------------------------------|---------------------|-----------|-----|----------|
| EWPP PremierPLS 4HR AHR AP410i-1-FCC | 98507-AP410i-1-FCC | \$ 414.00 | 10% | \$375.39 |
| EWPP PremierPLS 4HR AHR AP410i-1-WR | 98507-AP410i-1-WR | \$ 414.00 | 10% | \$375.39 |
| EWPP PremierPLS 4HR AHR AP410i-CAN | 98507-AP410i-CAN | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP410i-FCC | 98507-AP410i-FCC | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP410i-IL | 98507-AP410i-IL | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP410i-WR | 98507-AP410i-WR | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP460C-CAN | 98507-AP460C-CAN | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460C-EG | 98507-AP460C-EG | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460C-FCC | 98507-AP460C-FCC | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460C-IL | 98507-AP460C-IL | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460C-WR | 98507-AP460C-WR | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460e-CAN | 98507-AP460e-CAN | \$ 456.00 | 6% | \$431.85 |
| EWPP PremierPLS 4HR AHR AP460e-FCC | 98507-AP460e-FCC | \$ 456.00 | 6% | \$431.85 |
| EWPP PremierPLS 4HR AHR AP460e-WR | 98507-AP460e-WR | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP460i-CAN | 98507-AP460i-CAN | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP460i-FCC | 98507-AP460i-FCC | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP460i-IL | 98507-AP460i-IL | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP460i-WR | 98507-AP460i-WR | \$ 435.00 | 6% | \$411.97 |
| EWPP PremierPLS 4HR AHR AP460S12C-CAN | 98507-AP460S12C-CAN | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460S12C-FCC | 98507-AP460S12C-FCC | \$ 449.00 | 6% | \$425.23 |

| | | | | |
|---|----------------------------|-----------|-----|----------|
| EWPP PremierPLS 4HR AHR AP460S12C-WR | 98507- AP460S12C- WR | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460S6C-CAN | 98507- AP460S6C- CAN | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460S6C-FCC | 98507- AP460S6C- FCC | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP460S6C-WR | 98507- AP460S6C- WR | \$ 449.00 | 6% | \$425.23 |
| EWPP PremierPLS 4HR AHR AP5010-IL | 98507-AP5010- IL | \$ 407.00 | 6% | \$385.45 |
| EWPP PremierPLS 4HR AHR AP5010-WW | 98507-AP5010- WW | \$ 407.00 | 10% | \$369.05 |
| EWPP PremierPLS 4HR AHR AP5020-WW | 98507-AP5020- WW | \$ 401.56 | 6% | \$380.30 |
| EWPP PremierPLS 4HR AHR AP5050D-WW | 98507- AP5050D-WW | \$ 620.00 | 6% | \$587.17 |
| EWPP PremierPLS 4HR AHR AP5050U-WW | 98507- AP5050U-WW | \$ 528.00 | 6% | \$500.04 |
| EWPP PremierPLS 4HR AHR AP505i-FCC | 98507-AP505i- FCC | \$ 429.00 | 6% | \$406.28 |
| EWPP PremierPLS 4HR AHR AP505i-FCC-TAA | 98507-AP505i- FCC-TAA | \$ 429.00 | 6% | \$406.28 |
| EWPP PremierPLS 4HR AHR AP505i-WR | 98507-AP505i- WR | \$ 451.00 | 6% | \$427.12 |
| EWPP PremierPLS 4HR AHR AP510C-CAN | 98507-AP510C- CAN | \$ 372.00 | 6% | \$352.30 |
| EWPP PremierPLS 4HR AHR AP510C-CE | 98507-AP510C- CE | \$ 372.00 | 6% | \$352.30 |
| EWPP PremierPLS 4HR AHR AP510C-FCC | 98507-AP510C- FCC | \$ 372.00 | 6% | \$352.30 |
| EWPP PremierPLS 4HR AHR AP510C-W | 98507-AP510C- W | \$ 372.00 | 6% | \$352.30 |
| EWPP PremierPLS 4HR AHR AP510C-WW | 98507-AP510C- WW | \$ 493.00 | 6% | \$466.90 |
| EWPP PremierPLS 4HR AHR AP510CX-CAN | 98507- AP510CX- CAN | \$ 372.00 | 6% | \$352.30 |
| EWPP PremierPLS 4HR AHR AP510CX-CE | 98507- AP510CX- CE | \$ 372.00 | 6% | \$352.30 |

| | | | | |
|---|---------------------------|-------------|-----|------------|
| EWPP PremierPLS 4HR AHR AP510CX-FCC | 98507- AP510CX- FCC | \$ 372.00 | 6% | \$352.30 |
| EWPP PremierPLS 4HR AHR AP510CX-W | 98507- AP510CX-W | \$ 372.00 | 6% | \$352.30 |
| EWPP PremierPLS 4HR AHR AP510CX-WW | 98507- AP510CX-WW | \$ 493.00 | 6% | \$466.90 |
| EWPP PremierPLS 4HR AHR AP510e-FCC | 98507-AP510e- FCC | \$ 489.00 | 6% | \$463.11 |
| EWPP PremierPLS 4HR AHR AP510e-FCC-TAA | 98507-AP510e- FCC-TAA | \$ 489.00 | 6% | \$463.11 |
| EWPP PremierPLS 4HR AHR AP510e-WR | 98507-AP510e- WR | \$ 466.00 | 6% | \$441.33 |
| EWPP PremierPLS 4HR AHR AP510i-1-FCC | 98507-AP510i- 1-FCC | \$ 444.00 | 10% | \$402.60 |
| EWPP PremierPLS 4HR AHR AP510i-1-WR | 98507-AP510i- 1-WR | \$ 444.00 | 10% | \$402.60 |
| EWPP PremierPLS 4HR AHR AP510i-FCC | 98507-AP510i- FCC | \$ 466.00 | 6% | \$441.33 |
| EWPP PremierPLS 4HR AHR AP510i-FCC-TAA | 98507-AP510i- FCC-TAA | \$ 466.00 | 6% | \$441.33 |
| EWPP PremierPLS 4HR AHR AP510i-WR | 98507-AP510i- WR | \$ 466.00 | 6% | \$441.33 |
| EWPP PremierPLS 4HR AHR AP560h-FCC | 98507-AP560h- FCC | \$ 723.00 | 6% | \$684.72 |
| EWPP PremierPLS 4HR AHR AP560h-WR | 98507-AP560h- WR | \$ 723.00 | 6% | \$684.72 |
| EWPP PremierPLS 4HR AHR AP560i-FCC | 98507-AP560i- FCC | \$ 610.00 | 6% | \$577.70 |
| EWPP PremierPLS 4HR AHR AP560i-WR | 98507-AP560i- WR | \$ 581.00 | 6% | \$550.24 |
| EWPP PremierPLS 4HR AHR AP560m-FCC | 98507-AP560m- FCC | \$ 609.00 | 6% | \$576.75 |
| EWPP PremierPLS 4HR AHR AP560t-FCC | 98507-AP560t- FCC | \$ 723.00 | 6% | \$684.72 |
| EWPP PremierPLS 4HR AHR AP560u-FCC | 98507-AP560u- FCC | \$ 567.00 | 6% | \$536.98 |
| EWPP PremierPLS 4HR AHR E2122 | 98507-E2122 | \$ 9,032.00 | 6% | \$8,553.76 |
| EWPP PremierPLS 4HR AHR E2122-1 | 98507-E2122-1 | \$ 8,602.00 | 6% | \$8,146.52 |

| | | | | |
|---------------------------------|---------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR E3120-1 | 98507-E3120-1 | \$ 12,491.00 | 6% | <i>\$11,829.60</i> |
| EWPP PremierPLS 4HR AHR E3125 | 98507-E3125 | \$ 13,476.00 | 6% | <i>\$12,762.45</i> |
| EWPP PremierPLS 4HR AHR H30131 | 98507-H30131 | \$ 3,237.00 | 6% | <i>\$3,065.60</i> |
| EWPP PremierPLS 4HR AHR H30132 | 98507-H30132 | \$ 3,175.00 | 6% | <i>\$3,006.88</i> |
| EWPP PremierPLS 4HR AHR H30133 | 98507-H30133 | \$ 6,486.00 | 6% | <i>\$6,142.57</i> |
| EWPP PremierPLS 4HR AHR H30134 | 98507-H30134 | \$ 7,910.00 | 6% | <i>\$7,491.17</i> |
| EWPP PremierPLS 4HR AHR H30135 | 98507-H30135 | \$ 6,612.00 | 6% | <i>\$6,261.89</i> |
| EWPP PremierPLS 4HR AHR H30136 | 98507-H30136 | \$ 7,910.00 | 6% | <i>\$7,491.17</i> |
| EWPP PremierPLS 4HR AHR H30184 | 98507-H30184 | \$ 1,286.00 | 6% | <i>\$1,217.91</i> |
| EWPP PremierPLS 4HR AHR H30185 | 98507-H30185 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR H30186 | 98507-H30186 | \$ 1,463.00 | 6% | <i>\$1,385.53</i> |
| EWPP PremierPLS 4HR AHR H30187 | 98507-H30187 | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| EWPP PremierPLS 4HR AHR H30188 | 98507-H30188 | \$ 1,463.00 | 6% | <i>\$1,385.53</i> |
| EWPP PremierPLS 4HR AHR H30189 | 98507-H30189 | \$ 1,463.00 | 6% | <i>\$1,385.53</i> |
| EWPP PremierPLS 4HR AHR H30190 | 98507-H30190 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30214 | 98507-H30214 | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| EWPP PremierPLS 4HR AHR H30215 | 98507-H30215 | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| EWPP PremierPLS 4HR AHR H30216 | 98507-H30216 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30217 | 98507-H30217 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30218 | 98507-H30218 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30219 | 98507-H30219 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H30220 | 98507-H30220 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30221 | 98507-H30221 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30222 | 98507-H30222 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30223 | 98507-H30223 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30224 | 98507-H30224 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30225 | 98507-H30225 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30226 | 98507-H30226 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30227 | 98507-H30227 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30228 | 98507-H30228 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30229 | 98507-H30229 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30267 | 98507-H30267 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30268 | 98507-H30268 | \$ 1,783.00 | 6% | <i>\$1,688.59</i> |
| EWPP PremierPLS 4HR AHR H30269 | 98507-H30269 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30270 | 98507-H30270 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30271 | 98507-H30271 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30272 | 98507-H30272 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30273 | 98507-H30273 | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |
| EWPP PremierPLS 4HR AHR H30274 | 98507-H30274 | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |
| EWPP PremierPLS 4HR AHR H30275 | 98507-H30275 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30276 | 98507-H30276 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30277 | 98507-H30277 | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H30278 | 98507-H30278 | \$ 2,481.00 | 6% | <i>\$2,349.63</i> |
| EWPP PremierPLS 4HR AHR H30279 | 98507-H30279 | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |
| EWPP PremierPLS 4HR AHR H30280 | 98507-H30280 | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |
| EWPP PremierPLS 4HR AHR H30281 | 98507-H30281 | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |
| EWPP PremierPLS 4HR AHR H30282 | 98507-H30282 | \$ 2,379.00 | 6% | <i>\$2,253.03</i> |
| EWPP PremierPLS 4HR AHR H30283 | 98507-H30283 | \$ 1,895.00 | 6% | <i>\$1,794.66</i> |
| EWPP PremierPLS 4HR AHR H30284 | 98507-H30284 | \$ 2,085.00 | 6% | <i>\$1,974.60</i> |
| EWPP PremierPLS 4HR AHR H30296 | 98507-H30296 | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| EWPP PremierPLS 4HR AHR H30297 | 98507-H30297 | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| EWPP PremierPLS 4HR AHR H30298 | 98507-H30298 | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| EWPP PremierPLS 4HR AHR H30299 | 98507-H30299 | \$ 1,533.00 | 6% | <i>\$1,451.83</i> |
| EWPP PremierPLS 4HR AHR H30381 | 98507-H30381 | \$ 2,857.00 | 6% | <i>\$2,705.72</i> |
| EWPP PremierPLS 4HR AHR H30384 | 98507-H30384 | \$ 2,708.00 | 6% | <i>\$2,564.61</i> |
| EWPP PremierPLS 4HR AHR H30391 | 98507-H30391 | \$ 1,820.00 | 6% | <i>\$1,723.63</i> |
| EWPP PremierPLS 4HR AHR H30392 | 98507-H30392 | \$ 1,820.00 | 6% | <i>\$1,723.63</i> |
| EWPP PremierPLS 4HR AHR H30393 | 98507-H30393 | \$ 1,043.00 | 6% | <i>\$987.77</i> |
| EWPP PremierPLS 4HR AHR H30394 | 98507-H30394 | \$ 3,129.00 | 6% | <i>\$2,963.32</i> |
| EWPP PremierPLS 4HR AHR H30395 | 98507-H30395 | \$ 3,645.00 | 6% | <i>\$3,452.00</i> |
| EWPP PremierPLS 4HR AHR H30396 | 98507-H30396 | \$ 3,358.00 | 6% | <i>\$3,180.19</i> |
| EWPP PremierPLS 4HR AHR H30397 | 98507-H30397 | \$ 3,905.00 | 6% | <i>\$3,698.23</i> |
| EWPP PremierPLS 4HR AHR H30398 | 98507-H30398 | \$ 1,064.00 | 6% | <i>\$1,007.66</i> |

| | | | | |
|--------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H30400 | 98507-H30400 | \$ 775.00 | 6% | <i>\$733.96</i> |
| EWPP PremierPLS 4HR AHR H30401 | 98507-H30401 | \$ 924.00 | 6% | <i>\$875.07</i> |
| EWPP PremierPLS 4HR AHR H30402 | 98507-H30402 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPP PremierPLS 4HR AHR H30403 | 98507-H30403 | \$ 1,200.00 | 6% | <i>\$1,136.46</i> |
| EWPP PremierPLS 4HR AHR H30480 | 98507-H30480 | \$ 2,991.00 | 6% | <i>\$2,832.63</i> |
| EWPP PremierPLS 4HR AHR H30495 | 98507-H30495 | \$ 4,193.00 | 6% | <i>\$3,970.98</i> |
| EWPP PremierPLS 4HR AHR H30496 | 98507-H30496 | \$ 4,113.00 | 6% | <i>\$3,895.22</i> |
| EWPP PremierPLS 4HR AHR H30497 | 98507-H30497 | \$ 5,115.00 | 6% | <i>\$4,844.16</i> |
| EWPP PremierPLS 4HR AHR H30498 | 98507-H30498 | \$ 5,018.00 | 6% | <i>\$4,752.30</i> |
| EWPP PremierPLS 4HR AHR H30499 | 98507-H30499 | \$ 1,432.00 | 6% | <i>\$1,356.18</i> |
| EWPP PremierPLS 4HR AHR H30501 | 98507-H30501 | \$ 5,018.00 | 6% | <i>\$4,752.30</i> |
| EWPP PremierPLS 4HR AHR H30502 | 98507-H30502 | \$ 6,598.00 | 6% | <i>\$6,248.64</i> |
| EWPP PremierPLS 4HR AHR H30503 | 98507-H30503 | \$ 1,432.00 | 6% | <i>\$1,356.18</i> |
| EWPP PremierPLS 4HR AHR H30505 | 98507-H30505 | \$ 7,425.00 | 6% | <i>\$7,031.85</i> |
| EWPP PremierPLS 4HR AHR H30506 | 98507-H30506 | \$ 9,346.00 | 6% | <i>\$8,851.13</i> |
| EWPP PremierPLS 4HR AHR H30509 | 98507-H30509 | \$ 6,598.00 | 6% | <i>\$6,248.64</i> |
| EWPP PremierPLS 4HR AHR H30510 | 98507-H30510 | \$ 7,425.00 | 6% | <i>\$7,031.85</i> |
| EWPP PremierPLS 4HR AHR H30511 | 98507-H30511 | \$ 9,346.00 | 6% | <i>\$8,851.13</i> |
| EWPP PremierPLS 4HR AHR H30512 | 98507-H30512 | \$ 1,432.00 | 6% | <i>\$1,356.18</i> |
| EWPP PremierPLS 4HR AHR H30513 | 98507-H30513 | \$ 2,120.00 | 6% | <i>\$2,007.75</i> |
| EWPP PremierPLS 4HR AHR H30525 | 98507-H30525 | \$ 7,687.00 | 6% | <i>\$7,279.97</i> |

| | | | | |
|--------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H30526 | 98507-H30526 | \$ 5,765.00 | 6% | <i>\$5,459.74</i> |
| EWPP PremierPLS 4HR AHR H30528 | 98507-H30528 | \$ 8,847.00 | 6% | <i>\$8,378.55</i> |
| EWPP PremierPLS 4HR AHR H30531 | 98507-H30531 | \$ 12,420.00 | 6% | <i>\$11,762.36</i> |
| EWPP PremierPLS 4HR AHR H30532 | 98507-H30532 | \$ 12,420.00 | 6% | <i>\$11,762.36</i> |
| EWPP PremierPLS 4HR AHR H30534 | 98507-H30534 | \$ 12,663.00 | 6% | <i>\$11,992.49</i> |
| EWPP PremierPLS 4HR AHR H30535 | 98507-H30535 | \$ 13,470.00 | 6% | <i>\$12,756.76</i> |
| EWPP PremierPLS 4HR AHR H30536 | 98507-H30536 | \$ 12,420.00 | 6% | <i>\$11,762.36</i> |
| EWPP PremierPLS 4HR AHR H30537 | 98507-H30537 | \$ 13,470.00 | 6% | <i>\$12,756.76</i> |
| EWPP PremierPLS 4HR AHR H30538 | 98507-H30538 | \$ 7,687.00 | 6% | <i>\$7,279.97</i> |
| EWPP PremierPLS 4HR AHR H30539 | 98507-H30539 | \$ 14,387.00 | 6% | <i>\$13,625.21</i> |
| EWPP PremierPLS 4HR AHR H30540 | 98507-H30540 | \$ 14,847.00 | 6% | <i>\$14,060.85</i> |
| EWPP PremierPLS 4HR AHR H30543 | 98507-H30543 | \$ 1,405.00 | 6% | <i>\$1,330.61</i> |
| EWPP PremierPLS 4HR AHR H30544 | 98507-H30544 | \$ 2,179.00 | 6% | <i>\$2,063.62</i> |
| EWPP PremierPLS 4HR AHR H30548 | 98507-H30548 | \$ 1,405.00 | 6% | <i>\$1,330.61</i> |
| EWPP PremierPLS 4HR AHR H30549 | 98507-H30549 | \$ 2,080.00 | 6% | <i>\$1,969.86</i> |
| EWPP PremierPLS 4HR AHR H30550 | 98507-H30550 | \$ 2,080.00 | 6% | <i>\$1,969.86</i> |
| EWPP PremierPLS 4HR AHR H30552 | 98507-H30552 | \$ 1,405.00 | 6% | <i>\$1,330.61</i> |
| EWPP PremierPLS 4HR AHR H30553 | 98507-H30553 | \$ 1,980.00 | 6% | <i>\$1,875.16</i> |
| EWPP PremierPLS 4HR AHR H30569 | 98507-H30569 | \$ 6,486.00 | 6% | <i>\$6,142.57</i> |
| EWPP PremierPLS 4HR AHR H30570 | 98507-H30570 | \$ 7,562.00 | 6% | <i>\$7,161.59</i> |
| EWPP PremierPLS 4HR AHR H30571 | 98507-H30571 | \$ 7,562.00 | 6% | <i>\$7,161.59</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H30573 | 98507-H30573 | \$ 6,486.00 | 6% | <i>\$6,142.57</i> |
| EWPP PremierPLS 4HR AHR H30574 | 98507-H30574 | \$ 7,074.00 | 6% | <i>\$6,699.43</i> |
| EWPP PremierPLS 4HR AHR H30575 | 98507-H30575 | \$ 4,827.00 | 6% | <i>\$4,571.41</i> |
| EWPP PremierPLS 4HR AHR H30576 | 98507-H30576 | \$ 6,486.00 | 6% | <i>\$6,142.57</i> |
| EWPP PremierPLS 4HR AHR H30577 | 98507-H30577 | \$ 7,418.00 | 6% | <i>\$7,025.22</i> |
| EWPP PremierPLS 4HR AHR H30578 | 98507-H30578 | \$ 7,418.00 | 6% | <i>\$7,025.22</i> |
| EWPP PremierPLS 4HR AHR H30587 | 98507-H30587 | \$ 5,878.00 | 6% | <i>\$5,566.76</i> |
| EWPP PremierPLS 4HR AHR H30588 | 98507-H30588 | \$ 4,186.00 | 6% | <i>\$3,964.35</i> |
| EWPP PremierPLS 4HR AHR H30589 | 98507-H30589 | \$ 6,158.00 | 6% | <i>\$5,831.93</i> |
| EWPP PremierPLS 4HR AHR H30632 | 98507-H30632 | \$ 477.00 | 6% | <i>\$451.74</i> |
| EWPP PremierPLS 4HR AHR H30633 | 98507-H30633 | \$ 477.00 | 6% | <i>\$451.74</i> |
| EWPP PremierPLS 4HR AHR H30643 | 98507-H30643 | \$ 11,444.00 | 6% | <i>\$10,838.04</i> |
| EWPP PremierPLS 4HR AHR H30706 | 98507-H30706 | \$ 9,020.00 | 6% | <i>\$8,542.39</i> |
| EWPP PremierPLS 4HR AHR H30707 | 98507-H30707 | \$ 5,765.00 | 6% | <i>\$5,459.74</i> |
| EWPP PremierPLS 4HR AHR H30724 | 98507-H30724 | \$ 909.00 | 6% | <i>\$860.87</i> |
| EWPP PremierPLS 4HR AHR H30725 | 98507-H30725 | \$ 3,175.00 | 6% | <i>\$3,006.88</i> |
| EWPP PremierPLS 4HR AHR H30726 | 98507-H30726 | \$ 13,733.00 | 6% | <i>\$13,005.84</i> |
| EWPP PremierPLS 4HR AHR H30727 | 98507-H30727 | \$ 14,566.00 | 6% | <i>\$13,794.73</i> |
| EWPP PremierPLS 4HR AHR H30730 | 98507-H30730 | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HR AHR H30731 | 98507-H30731 | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HR AHR H30733 | 98507-H30733 | \$ 13,184.00 | 6% | <i>\$12,485.91</i> |

| | | | | |
|--------------------------------|--------------|--------------|-----|--------------------|
| EWPP PremierPLS 4HR AHR H30734 | 98507-H30734 | \$ 10,151.00 | 6% | <i>\$9,613.50</i> |
| EWPP PremierPLS 4HR AHR H30735 | 98507-H30735 | \$ 11,687.00 | 6% | <i>\$11,068.17</i> |
| EWPP PremierPLS 4HR AHR H30736 | 98507-H30736 | \$ 2,184.00 | 6% | <i>\$2,068.36</i> |
| EWPP PremierPLS 4HR AHR H30738 | 98507-H30738 | \$ 393.00 | 6% | <i>\$372.19</i> |
| EWPP PremierPLS 4HR AHR H30787 | 98507-H30787 | \$ 332.00 | 10% | <i>\$301.04</i> |
| EWPP PremierPLS 4HR AHR H30788 | 98507-H30788 | \$ 333.00 | 10% | <i>\$301.95</i> |
| EWPP PremierPLS 4HR AHR H30791 | 98507-H30791 | \$ 315.00 | 10% | <i>\$285.63</i> |
| EWPP PremierPLS 4HR AHR H30847 | 98507-H30847 | \$ 339.00 | 10% | <i>\$307.39</i> |
| EWPP PremierPLS 4HR AHR H30848 | 98507-H30848 | \$ 339.00 | 10% | <i>\$307.39</i> |
| EWPP PremierPLS 4HR AHR H30852 | 98507-H30852 | \$ 339.00 | 10% | <i>\$307.39</i> |
| EWPP PremierPLS 4HR AHR H30857 | 98507-H30857 | \$ 399.00 | 10% | <i>\$361.79</i> |
| EWPP PremierPLS 4HR AHR H30869 | 98507-H30869 | \$ 574.00 | 10% | <i>\$520.47</i> |
| EWPP PremierPLS 4HR AHR H30900 | 98507-H30900 | \$ 4,671.00 | 10% | <i>\$4,235.43</i> |
| EWPP PremierPLS 4HR AHR H31337 | 98507-H31337 | \$ 14,501.00 | 6% | <i>\$13,733.17</i> |
| EWPP PremierPLS 4HR AHR H31338 | 98507-H31338 | \$ 14,501.00 | 6% | <i>\$13,733.17</i> |
| EWPP PremierPLS 4HR AHR H31341 | 98507-H31341 | \$ 7,834.00 | 6% | <i>\$7,419.19</i> |
| EWPP PremierPLS 4HR AHR H31342 | 98507-H31342 | \$ 2,223.00 | 6% | <i>\$2,105.29</i> |
| EWPP PremierPLS 4HR AHR H31343 | 98507-H31343 | \$ 3,077.00 | 6% | <i>\$2,914.07</i> |
| EWPP PremierPLS 4HR AHR H31344 | 98507-H31344 | \$ 3,077.00 | 6% | <i>\$2,914.07</i> |
| EWPP PremierPLS 4HR AHR H31345 | 98507-H31345 | \$ 3,077.00 | 6% | <i>\$2,914.07</i> |
| EWPP PremierPLS 4HR AHR H31346 | 98507-H31346 | \$ 3,077.00 | 6% | <i>\$2,914.07</i> |

| | | | | |
|--------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H31362 | 98507-H31362 | \$ 39,246.00 | 6% | <i>\$37,167.92</i> |
| EWPP PremierPLS 4HR AHR H31363 | 98507-H31363 | \$ 39,246.00 | 6% | <i>\$37,167.92</i> |
| EWPP PremierPLS 4HR AHR H31364 | 98507-H31364 | \$ 14,543.00 | 6% | <i>\$13,772.95</i> |
| EWPP PremierPLS 4HR AHR H31365 | 98507-H31365 | \$ 14,543.00 | 6% | <i>\$13,772.95</i> |
| EWPP PremierPLS 4HR AHR H31366 | 98507-H31366 | \$ 20,133.00 | 6% | <i>\$19,066.96</i> |
| EWPP PremierPLS 4HR AHR H31367 | 98507-H31367 | \$ 20,133.00 | 6% | <i>\$19,066.96</i> |
| EWPP PremierPLS 4HR AHR H32010 | 98507-H32010 | \$ 1,913.00 | 6% | <i>\$1,811.71</i> |
| EWPP PremierPLS 4HR AHR H32011 | 98507-H32011 | \$ 1,913.00 | 6% | <i>\$1,811.71</i> |
| EWPP PremierPLS 4HR AHR H32012 | 98507-H32012 | \$ 5,006.00 | 6% | <i>\$4,740.93</i> |
| EWPP PremierPLS 4HR AHR H32013 | 98507-H32013 | \$ 5,006.00 | 6% | <i>\$4,740.93</i> |
| EWPP PremierPLS 4HR AHR H32014 | 98507-H32014 | \$ 5,006.00 | 6% | <i>\$4,740.93</i> |
| EWPP PremierPLS 4HR AHR H32015 | 98507-H32015 | \$ 5,006.00 | 6% | <i>\$4,740.93</i> |
| EWPP PremierPLS 4HR AHR H32016 | 98507-H32016 | \$ 4,633.00 | 6% | <i>\$4,387.68</i> |
| EWPP PremierPLS 4HR AHR H32017 | 98507-H32017 | \$ 4,633.00 | 6% | <i>\$4,387.68</i> |
| EWPP PremierPLS 4HR AHR H32018 | 98507-H32018 | \$ 4,633.00 | 6% | <i>\$4,387.68</i> |
| EWPP PremierPLS 4HR AHR H32019 | 98507-H32019 | \$ 4,633.00 | 6% | <i>\$4,387.68</i> |
| EWPP PremierPLS 4HR AHR H32020 | 98507-H32020 | \$ 40,277.00 | 6% | <i>\$38,144.33</i> |
| EWPP PremierPLS 4HR AHR H32021 | 98507-H32021 | \$ 40,277.00 | 6% | <i>\$38,144.33</i> |
| EWPP PremierPLS 4HR AHR H32022 | 98507-H32022 | \$ 40,277.00 | 6% | <i>\$38,144.33</i> |
| EWPP PremierPLS 4HR AHR H32023 | 98507-H32023 | \$ 40,277.00 | 6% | <i>\$38,144.33</i> |
| EWPP PremierPLS 4HR AHR H32028 | 98507-H32028 | \$ 75,761.00 | 6% | <i>\$71,749.46</i> |

| | | | | |
|--------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H32029 | 98507-H32029 | \$ 75,761.00 | 6% | <i>\$71,749.46</i> |
| EWPP PremierPLS 4HR AHR H32030 | 98507-H32030 | \$ 79,451.00 | 6% | <i>\$75,244.07</i> |
| EWPP PremierPLS 4HR AHR H32031 | 98507-H32031 | \$ 79,451.00 | 6% | <i>\$75,244.07</i> |
| EWPP PremierPLS 4HR AHR H32032 | 98507-H32032 | \$ 79,451.00 | 6% | <i>\$75,244.07</i> |
| EWPP PremierPLS 4HR AHR H32033 | 98507-H32033 | \$ 79,451.00 | 6% | <i>\$75,244.07</i> |
| EWPP PremierPLS 4HR AHR H32038 | 98507-H32038 | \$ 14,838.00 | 6% | <i>\$14,052.33</i> |
| EWPP PremierPLS 4HR AHR H32039 | 98507-H32039 | \$ 14,838.00 | 6% | <i>\$14,052.33</i> |
| EWPP PremierPLS 4HR AHR H32040 | 98507-H32040 | \$ 14,838.00 | 6% | <i>\$14,052.33</i> |
| EWPP PremierPLS 4HR AHR H32041 | 98507-H32041 | \$ 14,838.00 | 6% | <i>\$14,052.33</i> |
| EWPP PremierPLS 4HR AHR H32046 | 98507-H32046 | \$ 20,540.00 | 6% | <i>\$19,452.41</i> |
| EWPP PremierPLS 4HR AHR H32047 | 98507-H32047 | \$ 20,540.00 | 6% | <i>\$19,452.41</i> |
| EWPP PremierPLS 4HR AHR H32048 | 98507-H32048 | \$ 20,540.00 | 6% | <i>\$19,452.41</i> |
| EWPP PremierPLS 4HR AHR H32049 | 98507-H32049 | \$ 20,540.00 | 6% | <i>\$19,452.41</i> |
| EWPP PremierPLS 4HR AHR H32054 | 98507-H32054 | \$ 14,838.00 | 6% | <i>\$14,052.33</i> |
| EWPP PremierPLS 4HR AHR H32055 | 98507-H32055 | \$ 20,540.00 | 6% | <i>\$19,452.41</i> |
| EWPP PremierPLS 4HR AHR H32056 | 98507-H32056 | \$ 5,705.00 | 6% | <i>\$5,402.92</i> |
| EWPP PremierPLS 4HR AHR H32057 | 98507-H32057 | \$ 5,877.00 | 6% | <i>\$5,565.81</i> |
| EWPP PremierPLS 4HR AHR H32058 | 98507-H32058 | \$ 5,877.00 | 6% | <i>\$5,565.81</i> |
| EWPP PremierPLS 4HR AHR H32059 | 98507-H32059 | \$ 5,877.00 | 6% | <i>\$5,565.81</i> |
| EWPP PremierPLS 4HR AHR H32060 | 98507-H32060 | \$ 5,811.00 | 6% | <i>\$5,503.31</i> |
| EWPP PremierPLS 4HR AHR H32061 | 98507-H32061 | \$ 6,102.00 | 6% | <i>\$5,778.90</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H32062 | 98507-H32062 | \$ 5,811.00 | 6% | <i>\$5,503.31</i> |
| EWPP PremierPLS 4HR AHR H32063 | 98507-H32063 | \$ 5,818.00 | 6% | <i>\$5,509.94</i> |
| EWPP PremierPLS 4HR AHR H32064 | 98507-H32064 | \$ 5,811.00 | 6% | <i>\$5,503.31</i> |
| EWPP PremierPLS 4HR AHR H32065 | 98507-H32065 | \$ 6,416.00 | 6% | <i>\$6,076.27</i> |
| EWPP PremierPLS 4HR AHR H32066 | 98507-H32066 | \$ 6,416.00 | 6% | <i>\$6,076.27</i> |
| EWPP PremierPLS 4HR AHR H32067 | 98507-H32067 | \$ 6,416.00 | 6% | <i>\$6,076.27</i> |
| EWPP PremierPLS 4HR AHR H32068 | 98507-H32068 | \$ 6,416.00 | 6% | <i>\$6,076.27</i> |
| EWPP PremierPLS 4HR AHR H32069 | 98507-H32069 | \$ 7,614.00 | 6% | <i>\$7,210.84</i> |
| EWPP PremierPLS 4HR AHR H32070 | 98507-H32070 | \$ 7,614.00 | 6% | <i>\$7,210.84</i> |
| EWPP PremierPLS 4HR AHR H32071 | 98507-H32071 | \$ 7,614.00 | 6% | <i>\$7,210.84</i> |
| EWPP PremierPLS 4HR AHR H32072 | 98507-H32072 | \$ 7,614.00 | 6% | <i>\$7,210.84</i> |
| EWPP PremierPLS 4HR AHR H32073 | 98507-H32073 | \$ 50,963.00 | 6% | <i>\$48,264.51</i> |
| EWPP PremierPLS 4HR AHR H32074 | 98507-H32074 | \$ 50,963.00 | 6% | <i>\$48,264.51</i> |
| EWPP PremierPLS 4HR AHR H32075 | 98507-H32075 | \$ 69,311.00 | 6% | <i>\$65,640.98</i> |
| EWPP PremierPLS 4HR AHR H32076 | 98507-H32076 | \$ 68,650.00 | 6% | <i>\$65,014.98</i> |
| EWPP PremierPLS 4HR AHR H32101 | 98507-H32101 | \$ 3,579.00 | 6% | <i>\$3,389.49</i> |
| EWPP PremierPLS 4HR AHR H32102 | 98507-H32102 | \$ 3,579.00 | 6% | <i>\$3,389.49</i> |
| EWPP PremierPLS 4HR AHR H32103 | 98507-H32103 | \$ 3,579.00 | 6% | <i>\$3,389.49</i> |
| EWPP PremierPLS 4HR AHR H32104 | 98507-H32104 | \$ 3,579.00 | 6% | <i>\$3,389.49</i> |
| EWPP PremierPLS 4HR AHR H32105 | 98507-H32105 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |
| EWPP PremierPLS 4HR AHR H32106 | 98507-H32106 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H32107 | 98507-H32107 | \$ 12,487.00 | 6% | <i>\$11,825.81</i> |
| EWPP PremierPLS 4HR AHR H32108 | 98507-H32108 | \$ 12,487.00 | 6% | <i>\$11,825.81</i> |
| EWPP PremierPLS 4HR AHR H32109 | 98507-H32109 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |
| EWPP PremierPLS 4HR AHR H32110 | 98507-H32110 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |
| EWPP PremierPLS 4HR AHR H32111 | 98507-H32111 | \$ 3,578.00 | 6% | <i>\$3,388.54</i> |
| EWPP PremierPLS 4HR AHR H32112 | 98507-H32112 | \$ 3,578.00 | 6% | <i>\$3,388.54</i> |
| EWPP PremierPLS 4HR AHR H32113 | 98507-H32113 | \$ 3,579.00 | 6% | <i>\$3,389.49</i> |
| EWPP PremierPLS 4HR AHR H32114 | 98507-H32114 | \$ 3,579.00 | 6% | <i>\$3,389.49</i> |
| EWPP PremierPLS 4HR AHR H32115 | 98507-H32115 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |
| EWPP PremierPLS 4HR AHR H32116 | 98507-H32116 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |
| EWPP PremierPLS 4HR AHR H32117 | 98507-H32117 | \$ 3,461.00 | 6% | <i>\$3,277.74</i> |
| EWPP PremierPLS 4HR AHR H32118 | 98507-H32118 | \$ 3,461.00 | 6% | <i>\$3,277.74</i> |
| EWPP PremierPLS 4HR AHR H32119 | 98507-H32119 | \$ 3,461.00 | 6% | <i>\$3,277.74</i> |
| EWPP PremierPLS 4HR AHR H32120 | 98507-H32120 | \$ 3,461.00 | 6% | <i>\$3,277.74</i> |
| EWPP PremierPLS 4HR AHR H32121 | 98507-H32121 | \$ 12,487.00 | 6% | <i>\$11,825.81</i> |
| EWPP PremierPLS 4HR AHR H32122 | 98507-H32122 | \$ 12,487.00 | 6% | <i>\$11,825.81</i> |
| EWPP PremierPLS 4HR AHR H32123 | 98507-H32123 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |
| EWPP PremierPLS 4HR AHR H32124 | 98507-H32124 | \$ 5,606.00 | 6% | <i>\$5,309.16</i> |
| EWPP PremierPLS 4HR AHR H32125 | 98507-H32125 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32126 | 98507-H32126 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32127 | 98507-H32127 | \$ 6,150.00 | 6% | <i>\$5,824.36</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H32128 | 98507-H32128 | \$ 6,150.00 | 6% | <i>\$5,824.36</i> |
| EWPP PremierPLS 4HR AHR H32129 | 98507-H32129 | \$ 6,150.00 | 6% | <i>\$5,824.36</i> |
| EWPP PremierPLS 4HR AHR H32130 | 98507-H32130 | \$ 6,150.00 | 6% | <i>\$5,824.36</i> |
| EWPP PremierPLS 4HR AHR H32131 | 98507-H32131 | \$ 6,150.00 | 6% | <i>\$5,824.36</i> |
| EWPP PremierPLS 4HR AHR H32132 | 98507-H32132 | \$ 6,150.00 | 6% | <i>\$5,824.36</i> |
| EWPP PremierPLS 4HR AHR H32133 | 98507-H32133 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32134 | 98507-H32134 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32135 | 98507-H32135 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32136 | 98507-H32136 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32137 | 98507-H32137 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32138 | 98507-H32138 | \$ 5,442.00 | 6% | <i>\$5,153.85</i> |
| EWPP PremierPLS 4HR AHR H32139 | 98507-H32139 | \$ 20,747.00 | 6% | <i>\$19,648.45</i> |
| EWPP PremierPLS 4HR AHR H32140 | 98507-H32140 | \$ 20,747.00 | 6% | <i>\$19,648.45</i> |
| EWPP PremierPLS 4HR AHR H32141 | 98507-H32141 | \$ 24,600.00 | 6% | <i>\$23,297.43</i> |
| EWPP PremierPLS 4HR AHR H32142 | 98507-H32142 | \$ 24,600.00 | 6% | <i>\$23,297.43</i> |
| EWPP PremierPLS 4HR AHR H32146 | 98507-H32146 | \$ 3,391.00 | 6% | <i>\$3,211.45</i> |
| EWPP PremierPLS 4HR AHR H32147 | 98507-H32147 | \$ 3,391.00 | 6% | <i>\$3,211.45</i> |
| EWPP PremierPLS 4HR AHR H32148 | 98507-H32148 | \$ 5,310.00 | 6% | <i>\$5,028.84</i> |
| EWPP PremierPLS 4HR AHR H32149 | 98507-H32149 | \$ 5,310.00 | 6% | <i>\$5,028.84</i> |
| EWPP PremierPLS 4HR AHR H32150 | 98507-H32150 | \$ 3,391.00 | 6% | <i>\$3,211.45</i> |
| EWPP PremierPLS 4HR AHR H32152 | 98507-H32152 | \$ 2,305.00 | 6% | <i>\$2,182.95</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H32169 | 98507-H32169 | \$ 3,553.00 | 6% | <i>\$3,364.87</i> |
| EWPP PremierPLS 4HR AHR H32170 | 98507-H32170 | \$ 3,553.00 | 6% | <i>\$3,364.87</i> |
| EWPP PremierPLS 4HR AHR H32171 | 98507-H32171 | \$ 3,434.00 | 6% | <i>\$3,252.17</i> |
| EWPP PremierPLS 4HR AHR H32172 | 98507-H32172 | \$ 3,434.00 | 6% | <i>\$3,252.17</i> |
| EWPP PremierPLS 4HR AHR H32173 | 98507-H32173 | \$ 6,560.00 | 6% | <i>\$6,212.65</i> |
| EWPP PremierPLS 4HR AHR H32174 | 98507-H32174 | \$ 6,560.00 | 6% | <i>\$6,212.65</i> |
| EWPP PremierPLS 4HR AHR H32175 | 98507-H32175 | \$ 5,805.00 | 6% | <i>\$5,497.63</i> |
| EWPP PremierPLS 4HR AHR H32176 | 98507-H32176 | \$ 5,805.00 | 6% | <i>\$5,497.63</i> |
| EWPP PremierPLS 4HR AHR H32177 | 98507-H32177 | \$ 22,798.00 | 6% | <i>\$21,590.85</i> |
| EWPP PremierPLS 4HR AHR H32178 | 98507-H32178 | \$ 27,031.00 | 6% | <i>\$25,599.71</i> |
| EWPP PremierPLS 4HR AHR H34008 | 98507-H34008 | \$ 1,293.00 | 6% | <i>\$1,224.54</i> |
| EWPP PremierPLS 4HR AHR H34009 | 98507-H34009 | \$ 1,419.00 | 6% | <i>\$1,343.86</i> |
| EWPP PremierPLS 4HR AHR H34010 | 98507-H34010 | \$ 1,222.00 | 6% | <i>\$1,157.30</i> |
| EWPP PremierPLS 4HR AHR H34011 | 98507-H34011 | \$ 1,399.00 | 6% | <i>\$1,324.92</i> |
| EWPP PremierPLS 4HR AHR H34012 | 98507-H34012 | \$ 1,540.00 | 6% | <i>\$1,458.46</i> |
| EWPP PremierPLS 4HR AHR H34013 | 98507-H34013 | \$ 1,344.00 | 6% | <i>\$1,272.84</i> |
| EWPP PremierPLS 4HR AHR H34014 | 98507-H34014 | \$ 1,419.00 | 6% | <i>\$1,343.86</i> |
| EWPP PremierPLS 4HR AHR H34015 | 98507-H34015 | \$ 1,243.00 | 6% | <i>\$1,177.18</i> |
| EWPP PremierPLS 4HR AHR H34016 | 98507-H34016 | \$ 1,447.00 | 6% | <i>\$1,370.38</i> |
| EWPP PremierPLS 4HR AHR H34017 | 98507-H34017 | \$ 1,597.00 | 6% | <i>\$1,512.44</i> |
| EWPP PremierPLS 4HR AHR H34018 | 98507-H34018 | \$ 1,350.00 | 6% | <i>\$1,278.52</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H34019 | 98507-H34019 | \$ 1,350.00 | 6% | <i>\$1,278.52</i> |
| EWPP PremierPLS 4HR AHR H34020 | 98507-H34020 | \$ 1,350.00 | 6% | <i>\$1,278.52</i> |
| EWPP PremierPLS 4HR AHR H34021 | 98507-H34021 | \$ 1,350.00 | 6% | <i>\$1,278.52</i> |
| EWPP PremierPLS 4HR AHR H34048 | 98507-H34048 | \$ 1,840.00 | 6% | <i>\$1,742.57</i> |
| EWPP PremierPLS 4HR AHR H34049 | 98507-H34049 | \$ 1,840.00 | 6% | <i>\$1,742.57</i> |
| EWPP PremierPLS 4HR AHR H34050 | 98507-H34050 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS 4HR AHR H34051 | 98507-H34051 | \$ 1,671.00 | 6% | <i>\$1,582.52</i> |
| EWPP PremierPLS 4HR AHR H34052 | 98507-H34052 | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWPP PremierPLS 4HR AHR H34053 | 98507-H34053 | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWPP PremierPLS 4HR AHR H34054 | 98507-H34054 | \$ 1,761.00 | 6% | <i>\$1,667.76</i> |
| EWPP PremierPLS 4HR AHR H34055 | 98507-H34055 | \$ 1,761.00 | 6% | <i>\$1,667.76</i> |
| EWPP PremierPLS 4HR AHR H34056 | 98507-H34056 | \$ 2,118.00 | 6% | <i>\$2,005.85</i> |
| EWPP PremierPLS 4HR AHR H34057 | 98507-H34057 | \$ 2,118.00 | 6% | <i>\$2,005.85</i> |
| EWPP PremierPLS 4HR AHR H34058 | 98507-H34058 | \$ 2,007.00 | 6% | <i>\$1,900.73</i> |
| EWPP PremierPLS 4HR AHR H34059 | 98507-H34059 | \$ 2,007.00 | 6% | <i>\$1,900.73</i> |
| EWPP PremierPLS 4HR AHR H34062 | 98507-H34062 | \$ 2,118.00 | 6% | <i>\$2,005.85</i> |
| EWPP PremierPLS 4HR AHR H34063 | 98507-H34063 | \$ 2,118.00 | 6% | <i>\$2,005.85</i> |
| EWPP PremierPLS 4HR AHR H34064 | 98507-H34064 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR H34065 | 98507-H34065 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR H34066 | 98507-H34066 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR H34067 | 98507-H34067 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H34068 | 98507-H34068 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR H34069 | 98507-H34069 | \$ 1,687.00 | 6% | <i>\$1,597.67</i> |
| EWPP PremierPLS 4HR AHR H34070 | 98507-H34070 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR H34071 | 98507-H34071 | \$ 1,703.00 | 6% | <i>\$1,612.83</i> |
| EWPP PremierPLS 4HR AHR H34072 | 98507-H34072 | \$ 5,578.00 | 6% | <i>\$5,282.64</i> |
| EWPP PremierPLS 4HR AHR H34073 | 98507-H34073 | \$ 5,472.00 | 6% | <i>\$5,182.26</i> |
| EWPP PremierPLS 4HR AHR H34074 | 98507-H34074 | \$ 6,900.00 | 6% | <i>\$6,534.65</i> |
| EWPP PremierPLS 4HR AHR H34075 | 98507-H34075 | \$ 6,668.00 | 6% | <i>\$6,314.93</i> |
| EWPP PremierPLS 4HR AHR H34076 | 98507-H34076 | \$ 5,578.00 | 6% | <i>\$5,282.64</i> |
| EWPP PremierPLS 4HR AHR H34077 | 98507-H34077 | \$ 5,472.00 | 6% | <i>\$5,182.26</i> |
| EWPP PremierPLS 4HR AHR H34078 | 98507-H34078 | \$ 5,578.00 | 6% | <i>\$5,282.64</i> |
| EWPP PremierPLS 4HR AHR H34079 | 98507-H34079 | \$ 5,472.00 | 6% | <i>\$5,182.26</i> |
| EWPP PremierPLS 4HR AHR H34080 | 98507-H34080 | \$ 6,900.00 | 6% | <i>\$6,534.65</i> |
| EWPP PremierPLS 4HR AHR H34081 | 98507-H34081 | \$ 6,668.00 | 6% | <i>\$6,314.93</i> |
| EWPP PremierPLS 4HR AHR H34082 | 98507-H34082 | \$ 6,587.00 | 6% | <i>\$6,238.22</i> |
| EWPP PremierPLS 4HR AHR H34083 | 98507-H34083 | \$ 6,365.00 | 6% | <i>\$6,027.97</i> |
| EWPP PremierPLS 4HR AHR H34084 | 98507-H34084 | \$ 4,702.00 | 6% | <i>\$4,453.03</i> |
| EWPP PremierPLS 4HR AHR H34085 | 98507-H34085 | \$ 4,702.00 | 6% | <i>\$4,453.03</i> |
| EWPP PremierPLS 4HR AHR H34086 | 98507-H34086 | \$ 5,500.00 | 6% | <i>\$5,208.78</i> |
| EWPP PremierPLS 4HR AHR H34087 | 98507-H34087 | \$ 5,250.00 | 6% | <i>\$4,972.01</i> |
| EWPP PremierPLS 4HR AHR H34088 | 98507-H34088 | \$ 10,982.00 | 6% | <i>\$10,400.50</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H34089 | 98507-H34089 | \$ 10,982.00 | 6% | <i>\$10,400.50</i> |
| EWPP PremierPLS 4HR AHR H34090 | 98507-H34090 | \$ 12,645.00 | 6% | <i>\$11,975.45</i> |
| EWPP PremierPLS 4HR AHR H34091 | 98507-H34091 | \$ 11,127.00 | 6% | <i>\$10,537.83</i> |
| EWPP PremierPLS 4HR AHR H34092 | 98507-H34092 | \$ 11,127.00 | 6% | <i>\$10,537.83</i> |
| EWPP PremierPLS 4HR AHR H34093 | 98507-H34093 | \$ 11,127.00 | 6% | <i>\$10,537.83</i> |
| EWPP PremierPLS 4HR AHR H34094 | 98507-H34094 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34095 | 98507-H34095 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34096 | 98507-H34096 | \$ 1,433.00 | 6% | <i>\$1,357.12</i> |
| EWPP PremierPLS 4HR AHR H34097 | 98507-H34097 | \$ 1,433.00 | 6% | <i>\$1,357.12</i> |
| EWPP PremierPLS 4HR AHR H34098 | 98507-H34098 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34099 | 98507-H34099 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34100 | 98507-H34100 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34101 | 98507-H34101 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34102 | 98507-H34102 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34103 | 98507-H34103 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| EWPP PremierPLS 4HR AHR H34104 | 98507-H34104 | \$ 825.00 | 6% | <i>\$781.32</i> |
| EWPP PremierPLS 4HR AHR H34105 | 98507-H34105 | \$ 825.00 | 6% | <i>\$781.32</i> |
| EWPP PremierPLS 4HR AHR H34106 | 98507-H34106 | \$ 825.00 | 6% | <i>\$781.32</i> |
| EWPP PremierPLS 4HR AHR H34107 | 98507-H34107 | \$ 825.00 | 6% | <i>\$781.32</i> |
| EWPP PremierPLS 4HR AHR H34108 | 98507-H34108 | \$ 825.00 | 6% | <i>\$781.32</i> |
| EWPP PremierPLS 4HR AHR H34109 | 98507-H34109 | \$ 825.00 | 6% | <i>\$781.32</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H34110 | 98507-H34110 | \$ 10,667.00 | 6% | <i>\$10,102.18</i> |
| EWPP PremierPLS 4HR AHR H34111 | 98507-H34111 | \$ 10,667.00 | 6% | <i>\$10,102.18</i> |
| EWPP PremierPLS 4HR AHR H34112 | 98507-H34112 | \$ 10,667.00 | 6% | <i>\$10,102.18</i> |
| EWPP PremierPLS 4HR AHR H34114 | 98507-H34114 | \$ 15,491.00 | 6% | <i>\$14,670.75</i> |
| EWPP PremierPLS 4HR AHR H34115 | 98507-H34115 | \$ 15,064.00 | 6% | <i>\$14,266.36</i> |
| EWPP PremierPLS 4HR AHR H34116 | 98507-H34116 | \$ 15,064.00 | 6% | <i>\$14,266.36</i> |
| EWPP PremierPLS 4HR AHR H34117 | 98507-H34117 | \$ 15,491.00 | 6% | <i>\$14,670.75</i> |
| EWPP PremierPLS 4HR AHR H34118 | 98507-H34118 | \$ 2,834.00 | 6% | <i>\$2,683.94</i> |
| EWPP PremierPLS 4HR AHR H34119 | 98507-H34119 | \$ 2,834.00 | 6% | <i>\$2,683.94</i> |
| EWPP PremierPLS 4HR AHR H34120 | 98507-H34120 | \$ 2,091.00 | 6% | <i>\$1,980.28</i> |
| EWPP PremierPLS 4HR AHR H34121 | 98507-H34121 | \$ 2,091.00 | 6% | <i>\$1,980.28</i> |
| EWPP PremierPLS 4HR AHR H34122 | 98507-H34122 | \$ 2,160.00 | 6% | <i>\$2,045.63</i> |
| EWPP PremierPLS 4HR AHR H34123 | 98507-H34123 | \$ 2,160.00 | 6% | <i>\$2,045.63</i> |
| EWPP PremierPLS 4HR AHR H34124 | 98507-H34124 | \$ 3,004.00 | 6% | <i>\$2,844.94</i> |
| EWPP PremierPLS 4HR AHR H34125 | 98507-H34125 | \$ 3,004.00 | 6% | <i>\$2,844.94</i> |
| EWPP PremierPLS 4HR AHR H34126 | 98507-H34126 | \$ 3,004.00 | 6% | <i>\$2,844.94</i> |
| EWPP PremierPLS 4HR AHR H34127 | 98507-H34127 | \$ 3,004.00 | 6% | <i>\$2,844.94</i> |
| EWPP PremierPLS 4HR AHR H34129 | 98507-H34129 | \$ 1,818.00 | 6% | <i>\$1,721.74</i> |
| EWPP PremierPLS 4HR AHR H34130 | 98507-H34130 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |
| EWPP PremierPLS 4HR AHR H34131 | 98507-H34131 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |
| EWPP PremierPLS 4HR AHR H34132 | 98507-H34132 | \$ 1,888.00 | 6% | <i>\$1,788.03</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H34172 | 98507-H34172 | \$ 3,325.00 | 6% | <i>\$3,148.94</i> |
| EWPP PremierPLS 4HR AHR H34726 | 98507-H34726 | \$ 5,829.00 | 6% | <i>\$5,520.35</i> |
| EWPP PremierPLS 4HR AHR H34727 | 98507-H34727 | \$ 5,829.00 | 6% | <i>\$5,520.35</i> |
| EWPP PremierPLS 4HR AHR H34728 | 98507-H34728 | \$ 5,829.00 | 6% | <i>\$5,520.35</i> |
| EWPP PremierPLS 4HR AHR H34729 | 98507-H34729 | \$ 5,829.00 | 6% | <i>\$5,520.35</i> |
| EWPP PremierPLS 4HR AHR H34730 | 98507-H34730 | \$ 6,160.00 | 6% | <i>\$5,833.83</i> |
| EWPP PremierPLS 4HR AHR H34731 | 98507-H34731 | \$ 6,160.00 | 6% | <i>\$5,833.83</i> |
| EWPP PremierPLS 4HR AHR H34732 | 98507-H34732 | \$ 6,160.00 | 6% | <i>\$5,833.83</i> |
| EWPP PremierPLS 4HR AHR H34733 | 98507-H34733 | \$ 6,160.00 | 6% | <i>\$5,833.83</i> |
| EWPP PremierPLS 4HR AHR H34734 | 98507-H34734 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPP PremierPLS 4HR AHR H34735 | 98507-H34735 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPP PremierPLS 4HR AHR H34736 | 98507-H34736 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34737 | 98507-H34737 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34738 | 98507-H34738 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34739 | 98507-H34739 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34740 | 98507-H34740 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPP PremierPLS 4HR AHR H34741 | 98507-H34741 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPP PremierPLS 4HR AHR H34742 | 98507-H34742 | \$ 1,833.00 | 6% | <i>\$1,735.94</i> |
| EWPP PremierPLS 4HR AHR H34743 | 98507-H34743 | \$ 1,833.00 | 6% | <i>\$1,735.94</i> |
| EWPP PremierPLS 4HR AHR H34744 | 98507-H34744 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34745 | 98507-H34745 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H34746 | 98507-H34746 | \$ 2,294.00 | 6% | <i>\$2,172.53</i> |
| EWPP PremierPLS 4HR AHR H34747 | 98507-H34747 | \$ 2,294.00 | 6% | <i>\$2,172.53</i> |
| EWPP PremierPLS 4HR AHR H34748 | 98507-H34748 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34749 | 98507-H34749 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34750 | 98507-H34750 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34751 | 98507-H34751 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34752 | 98507-H34752 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34753 | 98507-H34753 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34754 | 98507-H34754 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34755 | 98507-H34755 | \$ 2,995.00 | 6% | <i>\$2,836.41</i> |
| EWPP PremierPLS 4HR AHR H34756 | 98507-H34756 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34757 | 98507-H34757 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34758 | 98507-H34758 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34759 | 98507-H34759 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34760 | 98507-H34760 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34761 | 98507-H34761 | \$ 2,181.00 | 6% | <i>\$2,065.52</i> |
| EWPP PremierPLS 4HR AHR H34993 | 98507-H34993 | \$ 24,226.00 | 6% | <i>\$22,943.23</i> |
| EWPP PremierPLS 4HR AHR H34994 | 98507-H34994 | \$ 24,226.00 | 6% | <i>\$22,943.23</i> |
| EWPP PremierPLS 4HR AHR H34996 | 98507-H34996 | \$ 24,226.00 | 6% | <i>\$22,943.23</i> |
| EWPP PremierPLS 4HR AHR H34997 | 98507-H34997 | \$ 24,226.00 | 6% | <i>\$22,943.23</i> |
| EWPP PremierPLS 4HR AHR H35005 | 98507-H35005 | \$ 17,316.00 | 6% | <i>\$16,399.12</i> |

| | | | | |
|------------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H35006 | 98507-H35006 | \$ 17,316.00 | 6% | <i>\$16,399.12</i> |
| EWPP PremierPLS 4HR AHR H35012 | 98507-H35012 | \$ 11,436.00 | 6% | <i>\$10,830.46</i> |
| EWPP PremierPLS 4HR AHR H35270 | 98507-H35270 | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWPP PremierPLS 4HR AHR H35271 | 98507-H35271 | \$ 1,761.00 | 6% | <i>\$1,667.76</i> |
| EWPP PremierPLS 4HR AHR H35272 | 98507-H35272 | \$ 1,623.00 | 6% | <i>\$1,537.06</i> |
| EWPP PremierPLS 4HR AHR H35273 | 98507-H35273 | \$ 1,623.00 | 6% | <i>\$1,537.06</i> |
| EWPP PremierPLS 4HR AHR H35274 | 98507-H35274 | \$ 2,294.00 | 6% | <i>\$2,172.53</i> |
| EWPP PremierPLS 4HR AHR H35275 | 98507-H35275 | \$ 2,118.00 | 6% | <i>\$2,005.85</i> |
| EWPP PremierPLS 4HR AHR H35276 | 98507-H35276 | \$ 5,578.00 | 6% | <i>\$5,282.64</i> |
| EWPP PremierPLS 4HR AHR H35277 | 98507-H35277 | \$ 6,587.00 | 6% | <i>\$6,238.22</i> |
| EWPP PremierPLS 4HR AHR H35278 | 98507-H35278 | \$ 4,702.00 | 6% | <i>\$4,453.03</i> |
| EWPP PremierPLS 4HR AHR H35279 | 98507-H35279 | \$ 5,250.00 | 6% | <i>\$4,972.01</i> |
| EWPP PremierPLS 4HR AHR H35280 | 98507-H35280 | \$ 10,463.00 | 6% | <i>\$9,908.98</i> |
| EWPP PremierPLS 4HR AHR H35294 | 98507-H35294 | \$ 2,828.00 | 6% | <i>\$2,678.26</i> |
| EWPP PremierPLS 4HR AHR H35295 | 98507-H35295 | \$ 1,731.00 | 6% | <i>\$1,639.34</i> |
| EWPP PremierPLUS 4HR AHR H35296 | 98507-H35296 | \$ 13,120.00 | 6% | <i>\$12,425.30</i> |
| EWPP PremierPLUS 4HR AHR H35297 | 98507-H35297 | \$ 13,120.00 | 6% | <i>\$12,425.30</i> |
| EWPP PremierPLUS 4HR AHR H35298 | 98507-H35298 | \$ 21,074.00 | 6% | <i>\$19,958.13</i> |
| EWPP PremierPLUS 4HR AHR H35299 | 98507-H35299 | \$ 21,074.00 | 6% | <i>\$19,958.13</i> |
| EWPP PremierPLS 4HR AHR H35302 | 98507-H35302 | \$ 4,942.00 | 6% | <i>\$4,680.32</i> |
| EWPP PremierPLS 4HR AHR H35303 | 98507-H35303 | \$ 4,942.00 | 6% | <i>\$4,680.32</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS 4HR AHR H35304 | 98507-H35304 | \$ 4,942.00 | 6% | \$4,680.32 |
| EWPP PremierPLS 4HR AHR H35305 | 98507-H35305 | \$ 5,124.00 | 6% | \$4,852.68 |
| EWPP PremierPLS 4HR AHR H35306 | 98507-H35306 | \$ 5,124.00 | 6% | \$4,852.68 |
| EWPP PremierPLS 4HR AHR H35307 | 98507-H35307 | \$ 5,124.00 | 6% | \$4,852.68 |
| EWPP PremierPLS 4HR AHR H35309 | 98507-H35309 | \$ 5,670.00 | 6% | \$5,369.77 |
| EWPP PremierPLS 4HR AHR H35310 | 98507-H35310 | \$ 5,670.00 | 6% | \$5,369.77 |
| EWPP PremierPLS 4HR AHR H35311 | 98507-H35311 | \$ 5,670.00 | 6% | \$5,369.77 |
| EWPP PremierPLS 4HR AHR H35312 | 98507-H35312 | \$ 4,683.00 | 6% | \$4,435.04 |
| EWPP PremierPLS 4HR AHR H35313 | 98507-H35313 | \$ 4,683.00 | 6% | \$4,435.04 |
| EWPP PremierPLS 4HR AHR H35314 | 98507-H35314 | \$ 4,683.00 | 6% | \$4,435.04 |
| EWPP PremierPLS 4HR AHR H35315 | 98507-H35315 | \$ 2,751.00 | 6% | \$2,605.33 |
| EWPP PremierPLS 4HR AHR H35318 | 98507-H35318 | \$ 1,915.00 | 6% | \$1,813.60 |
| EWPP PremierPLS 4HR AHR H35319 | 98507-H35319 | \$ 2,149.00 | 6% | \$2,035.21 |
| EWPP PremierPLS 4HR AHR H35320 | 98507-H35320 | \$ 2,189.00 | 6% | \$2,073.09 |
| EWPP PremierPLS 4HR AHR H35321 | 98507-H35321 | \$ 2,454.00 | 6% | \$2,324.06 |
| EWPP PremierPLS 4HR AHR H35322 | 98507-H35322 | \$ 2,781.00 | 6% | \$2,633.75 |
| EWPP PremierPLS 4HR AHR H35323 | 98507-H35323 | \$ 2,751.00 | 6% | \$2,605.33 |
| EWPP PremierPLS 4HR AHR H35328 | 98507-H35328 | \$ 877.00 | 6% | \$830.56 |
| EWPP PremierPLS 4HR AHR H35330 | 98507-H35330 | \$ 1,210.00 | 6% | \$1,145.93 |
| EWPP PremierPLS 4HR AHR H35340 | 98507-H35340 | \$ 5,550.00 | 6% | \$5,256.13 |
| EWPP PremierPLS 4HR AHR H35341 | 98507-H35341 | \$ 5,550.00 | 6% | \$5,256.13 |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H35342 | 98507-H35342 | \$ 4,547.00 | 6% | <i>\$4,306.24</i> |
| EWPP PremierPLS 4HR AHR H35343 | 98507-H35343 | \$ 5,550.00 | 6% | <i>\$5,256.13</i> |
| EWPP PremierPLS 4HR AHR H35344 | 98507-H35344 | \$ 5,684.00 | 6% | <i>\$5,383.03</i> |
| EWPP PremierPLS 4HR AHR H35345 | 98507-H35345 | \$ 5,684.00 | 6% | <i>\$5,383.03</i> |
| EWPP PremierPLS 4HR AHR H35346 | 98507-H35346 | \$ 4,651.00 | 6% | <i>\$4,404.73</i> |
| EWPP PremierPLS 4HR AHR H35347 | 98507-H35347 | \$ 5,684.00 | 6% | <i>\$5,383.03</i> |
| EWPP PremierPLS 4HR AHR H35349 | 98507-H35349 | \$ 6,024.00 | 6% | <i>\$5,705.03</i> |
| EWPP PremierPLS 4HR AHR H35350 | 98507-H35350 | \$ 6,024.00 | 6% | <i>\$5,705.03</i> |
| EWPP PremierPLS 4HR AHR H35351 | 98507-H35351 | \$ 4,921.00 | 6% | <i>\$4,660.43</i> |
| EWPP PremierPLS 4HR AHR H35352 | 98507-H35352 | \$ 6,024.00 | 6% | <i>\$5,705.03</i> |
| EWPP PremierPLS 4HR AHR H35359 | 98507-H35359 | \$ 2,454.00 | 6% | <i>\$2,324.06</i> |
| EWPP PremierPLS 4HR AHR H35360 | 98507-H35360 | \$ 2,781.00 | 6% | <i>\$2,633.75</i> |
| EWPP PremierPLS 4HR AHR H35361 | 98507-H35361 | \$ 2,751.00 | 6% | <i>\$2,605.33</i> |
| EWPP PremierPLS 4HR AHR H35362 | 98507-H35362 | \$ 1,916.00 | 6% | <i>\$1,814.55</i> |
| EWPP PremierPLS 4HR AHR H35366 | 98507-H35366 | \$ 2,349.00 | 6% | <i>\$2,224.62</i> |
| EWPP PremierPLS 4HR AHR H35367 | 98507-H35367 | \$ 2,738.00 | 6% | <i>\$2,593.02</i> |
| EWPP PremierPLS 4HR AHR H35368 | 98507-H35368 | \$ 4,169.00 | 6% | <i>\$3,948.25</i> |
| EWPP PremierPLS 4HR AHR H35369 | 98507-H35369 | \$ 1,360.00 | 6% | <i>\$1,287.99</i> |
| EWPP PremierPLS 4HR AHR H35370 | 98507-H35370 | \$ 1,902.00 | 6% | <i>\$1,801.29</i> |
| EWPP PremierPLS 4HR AHR H35375 | 98507-H35375 | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| EWPP PremierPLS 4HR AHR H35376 | 98507-H35376 | \$ 2,062.00 | 6% | <i>\$1,952.82</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H35377 | 98507-H35377 | \$ 862.00 | 6% | <i>\$816.36</i> |
| EWPP PremierPLS 4HR AHR H35378 | 98507-H35378 | \$ 1,374.00 | 6% | <i>\$1,301.25</i> |
| EWPP PremierPLS 4HR AHR H35379 | 98507-H35379 | \$ 862.00 | 6% | <i>\$816.36</i> |
| EWPP PremierPLS 4HR AHR H35380 | 98507-H35380 | \$ 1,544.00 | 6% | <i>\$1,462.25</i> |
| EWPP PremierPLS 4HR AHR H35381 | 98507-H35381 | \$ 1,887.00 | 6% | <i>\$1,787.08</i> |
| EWPP PremierPLS 4HR AHR H35384 | 98507-H35384 | \$ 675.00 | 6% | <i>\$639.26</i> |
| EWPP PremierPLS 4HR AHR H35385 | 98507-H35385 | \$ 896.00 | 6% | <i>\$848.56</i> |
| EWPP PremierPLS 4HR AHR H35386 | 98507-H35386 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| EWPP PremierPLS 4HR AHR H35387 | 98507-H35387 | \$ 1,389.00 | 6% | <i>\$1,315.45</i> |
| EWPP PremierPLS 4HR AHR H35388 | 98507-H35388 | \$ 1,026.00 | 6% | <i>\$971.67</i> |
| EWPP PremierPLS 4HR AHR H35389 | 98507-H35389 | \$ 576.00 | 6% | <i>\$545.50</i> |
| EWPP PremierPLS 4HR AHR H35390 | 98507-H35390 | \$ 498.00 | 6% | <i>\$471.63</i> |
| EWPP PremierPLS 4HR AHR H35391 | 98507-H35391 | \$ 1,098.00 | 6% | <i>\$1,039.86</i> |
| EWPP PremierPLS 4HR AHR H35392 | 98507-H35392 | \$ 1,674.00 | 6% | <i>\$1,585.36</i> |
| EWPP PremierPLS 4HR AHR H35393 | 98507-H35393 | \$ 2,230.00 | 6% | <i>\$2,111.92</i> |
| EWPP PremierPLS 4HR AHR H35394 | 98507-H35394 | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS 4HR AHR H35395 | 98507-H35395 | \$ 337.00 | 6% | <i>\$319.16</i> |
| EWPP PremierPLS 4HR AHR H35396 | 98507-H35396 | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS 4HR AHR H35397 | 98507-H35397 | \$ 337.00 | 6% | <i>\$319.16</i> |
| EWPP PremierPLS 4HR AHR H35398 | 98507-H35398 | \$ 1,043.00 | 6% | <i>\$987.77</i> |
| EWPP PremierPLS 4HR AHR H35399 | 98507-H35399 | \$ 1,264.00 | 6% | <i>\$1,197.07</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR H35400 | 98507-H35400 | \$ 1,393.00 | 6% | <i>\$1,319.24</i> |
| EWPP PremierPLS 4HR AHR H35401 | 98507-H35401 | \$ 746.00 | 6% | <i>\$706.50</i> |
| EWPP PremierPLS 4HR AHR H35415 | 98507-H35415 | \$ 466.00 | 6% | <i>\$441.33</i> |
| EWPP PremierPLS 4HR AHR H35416 | 98507-H35416 | \$ 466.00 | 6% | <i>\$441.33</i> |
| EWPP PremierPLS 4HR AHR H35426 | 98507-H35426 | \$ 576.00 | 6% | <i>\$545.50</i> |
| EWPP PremierPLS 4HR AHR H35427 | 98507-H35427 | \$ 1,389.00 | 6% | <i>\$1,315.45</i> |
| EWPP PremierPLS 4HR AHR H35428 | 98507-H35428 | \$ 498.00 | 6% | <i>\$471.63</i> |
| EWPP PremierPLS 4HR AHR H35429 | 98507-H35429 | \$ 1,098.00 | 6% | <i>\$1,039.86</i> |
| EWPP PremierPLS 4HR AHR H35430 | 98507-H35430 | \$ 1,891.00 | 6% | <i>\$1,790.87</i> |
| EWPP PremierPLS 4HR AHR H35431 | 98507-H35431 | \$ 1,891.00 | 6% | <i>\$1,790.87</i> |
| EWPP PremierPLS 4HR AHR H35432 | 98507-H35432 | \$ 1,833.00 | 6% | <i>\$1,735.94</i> |
| EWPP PremierPLS 4HR AHR H35433 | 98507-H35433 | \$ 2,077.00 | 6% | <i>\$1,967.02</i> |
| EWPP PremierPLS 4HR AHR H35434 | 98507-H35434 | \$ 2,185.00 | 6% | <i>\$2,069.30</i> |
| EWPP PremierPLS 4HR AHR H35435 | 98507-H35435 | \$ 2,185.00 | 6% | <i>\$2,069.30</i> |
| EWPP PremierPLS 4HR AHR H35436 | 98507-H35436 | \$ 2,852.00 | 6% | <i>\$2,700.99</i> |
| EWPP PremierPLS 4HR AHR H35437 | 98507-H35437 | \$ 2,852.00 | 6% | <i>\$2,700.99</i> |
| EWPP PremierPLS 4HR AHR H35438 | 98507-H35438 | \$ 2,852.00 | 6% | <i>\$2,700.99</i> |
| EWPP PremierPLS 4HR AHR H35439 | 98507-H35439 | \$ 2,852.00 | 6% | <i>\$2,700.99</i> |
| EWPP PremierPLS 4HR AHR H35440 | 98507-H35440 | \$ 2,077.00 | 6% | <i>\$1,967.02</i> |
| EWPP PremierPLS 4HR AHR H35441 | 98507-H35441 | \$ 2,077.00 | 6% | <i>\$1,967.02</i> |
| EWPP PremierPLS 4HR AHR H35442 | 98507-H35442 | \$ 2,077.00 | 6% | <i>\$1,967.02</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPP PremierPLS 4HR AHR H35443 | 98507-H35443 | \$ 5,829.00 | 6% | <i>\$5,520.35</i> |
| EWPP PremierPLS 4HR AHR H35444 | 98507-H35444 | \$ 6,160.00 | 6% | <i>\$5,833.83</i> |
| EWPP PremierPLS 4HR AHR H35445 | 98507-H35445 | \$ 5,578.00 | 6% | <i>\$5,282.64</i> |
| EWPP PremierPLS 4HR AHR H35446 | 98507-H35446 | \$ 5,472.00 | 6% | <i>\$5,182.26</i> |
| EWPP PremierPLS 4HR AHR H35447 | 98507-H35447 | \$ 6,273.00 | 6% | <i>\$5,940.84</i> |
| EWPP PremierPLS 4HR AHR H35448 | 98507-H35448 | \$ 6,062.00 | 6% | <i>\$5,741.02</i> |
| EWPP PremierPLS 4HR AHR H35449 | 98507-H35449 | \$ 4,702.00 | 6% | <i>\$4,453.03</i> |
| EWPP PremierPLS 4HR AHR H35450 | 98507-H35450 | \$ 5,000.00 | 6% | <i>\$4,735.25</i> |
| EWPP PremierPLS 4HR AHR H35451 | 98507-H35451 | \$ 11,127.00 | 6% | <i>\$10,537.83</i> |
| EWPP PremierPLS 4HR AHR H35452 | 98507-H35452 | \$ 11,127.00 | 6% | <i>\$10,537.83</i> |
| EWPP PremierPLS 4HR AHR H35453 | 98507-H35453 | \$ 6,160.00 | 6% | <i>\$5,833.83</i> |
| EWPP PremierPLS 4HR AHR H35454 | 98507-H35454 | \$ 5,829.00 | 6% | <i>\$5,520.35</i> |
| EWPP PremierPLS 4HR AHR H35455 | 98507-H35455 | \$ 2,189.00 | 6% | <i>\$2,073.09</i> |
| EWPP PremierPLS 4HR AHR H35456 | 98507-H35456 | \$ 2,429.00 | 6% | <i>\$2,300.38</i> |
| EWPP PremierPLS 4HR AHR H35457 | 98507-H35457 | \$ 2,324.00 | 6% | <i>\$2,200.94</i> |
| EWPP PremierPLS 4HR AHR H35458 | 98507-H35458 | \$ 2,445.00 | 6% | <i>\$2,315.54</i> |
| EWPP PremierPLS 4HR AHR H35471 | 98507-H35471 | \$ 2,189.00 | 6% | <i>\$2,073.09</i> |
| EWPP PremierPLS 4HR AHR H35600 | 98507-H35600 | \$ 1,623.00 | 6% | <i>\$1,537.06</i> |
| EWPP PremierPLS 4HR AHR H35601 | 98507-H35601 | \$ 1,623.00 | 6% | <i>\$1,537.06</i> |
| EWPP PremierPLS 4HR AHR H35602 | 98507-H35602 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPP PremierPLS 4HR AHR H35603 | 98507-H35603 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |

| | | | | |
|---|---------------------------------|--------------|-----|-------------|
| EWPP PremierPLS 4HR AHR H35604 | 98507-H35604 | \$ 2,181.00 | 6% | \$2,065.52 |
| EWPP PremierPLS 4HR AHR H35605 | 98507-H35605 | \$ 2,181.00 | 6% | \$2,065.52 |
| EWPP PremierPLS 4HR AHR H35606 | 98507-H35606 | \$ 2,294.00 | 6% | \$2,172.53 |
| EWPP PremierPLS 4HR AHR H35607 | 98507-H35607 | \$ 2,294.00 | 6% | \$2,172.53 |
| EWPP PremierPLS 4HR AHR ISW-24W-4X | 98507-ISW- 24W-4X | \$ 1,208.00 | 6% | \$1,144.04 |
| EWPP PremierPLS 4HR AHR ISW-4W-4WS-4X | 98507-ISW-4W- 4WS-4X | \$ 1,575.00 | 6% | \$1,491.60 |
| EWPP PremierPLS 4HR AHR MSM128 | 98507- MSM128 | \$ 4,133.00 | 6% | \$3,914.16 |
| EWPP PremierPLS 4HR AHR MSM48C | 98507- MSM48C | \$ 2,732.00 | 6% | \$2,587.34 |
| EWPP PremierPL 4HR AHR SLX9150-48XT-DC-F | 98507- SLX9150- 48XT-DC-F | \$ 4,909.00 | 6% | \$4,649.07 |
| EWPP PremierPLS 4HRAHR SLX9150-48XT-DC-R | 98507- SLX9150- 48XT-DC-R | \$ 5,412.00 | 6% | \$5,125.43 |
| EWPP PremierPLS 4HR AHR SLX9150-48Y-DC-F | 98507- SLX9150-48Y- DC-F | \$ 4,795.00 | 6% | \$4,541.10 |
| EWPP PremierPLS 4HR AHR SLX9150-48Y-DC-R | 98507- SLX9150-48Y- DC-R | \$ 5,286.00 | 6% | \$5,006.11 |
| EWPP PremierPLS 4HR AHR SLX9740-40C | 98507- SLX9740-40C | \$ 18,353.00 | 6% | \$17,381.21 |
| EWPP PremierPLS 4HR AHR SLX9740-40C-AC-F | 98507- SLX9740-40C- AC-F | \$ 18,353.00 | 6% | \$17,381.21 |
| EWPP PremierPLS 4HR AHR SLX9740-40C-AC-R | 98507- SLX9740-40C- AC-R | \$ 18,353.00 | 10% | \$16,641.58 |
| EWPP PremierPLS 4HR AHR SLX9740-40C-DC-F | 98507- SLX9740-40C- DC-F | \$ 18,353.00 | 6% | \$17,381.21 |
| EWPP PremierPLS 4HR AHR SLX9740-80C | 98507- SLX9740-80C | \$ 33,538.00 | 6% | \$31,762.16 |

| | | | | |
|---|---|--------------|-----|--------------------|
| EWPP PremierPLS 4HR AHR SLX9740-80C-AC-F | 98507- SLX9740-80C- AC-F | \$ 33,538.00 | 6% | <i>\$31,762.16</i> |
| EWPP PremierPLS 4HR AHR SLX9740-80C-AC-R | 98507- SLX9740-80C- AC-R | \$ 33,538.00 | 10% | <i>\$30,410.58</i> |
| EWPP PremierPLS 4HR AHR SLX9740-80C-DC-F | 98507- SLX9740-80C- DC-F | \$ 33,538.00 | 6% | <i>\$31,762.16</i> |
| EWPP PremierPLS 4HR AHR V300-8P-2X | 98507-V300- 8P-2X | \$ 923.00 | 6% | <i>\$874.13</i> |
| EWPP PremierPLS 4HR AHR V300-8T-2X | 98507-V300- 8T-2X | \$ 862.00 | 6% | <i>\$816.36</i> |
| EWPP PremierPLS 4HR AHR V300HT-8P-2X | 98507-V300HT- 8P-2X | \$ 1,176.00 | 6% | <i>\$1,113.73</i> |
| EWPP PremierPLS 4HR AHR V300HT-8T-2X | 98507-V300HT- 8T-2X | \$ 994.00 | 6% | <i>\$941.37</i> |
| EWPP PremierPLS 4HR AHR VIM-SS | 98507-VIM-SS | \$ 646.00 | 6% | <i>\$611.79</i> |
| EWPPPremierPLS 4HR AHR VIM-SSV | 98507-VIM- SSV80 | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWPPPremierPLS 4HR AHR VIM2-SS | 98507-VIM2- SS | \$ 651.00 | 6% | <i>\$616.53</i> |
| EWPPPremierPLS 4HR AHR VIM2-SS | 98507-VIM2- SS128 | \$ 1,214.00 | 6% | <i>\$1,149.72</i> |
| EWPPPremierPLS 4HR AHR VIM2-V8 | 98507-VIM2- V80 | \$ 1,296.00 | 6% | <i>\$1,227.38</i> |
| EWPPPremierPLS 4HR AHR VIM210G | 98507- VIM210G4X | \$ 1,890.00 | 6% | <i>\$1,789.92</i> |
| EWPP PremPL 4HRAHR VSP4900-12MXU-12XE | 98507- VSP4900- 12MXU-12XE | \$ 2,574.00 | 6% | <i>\$2,437.71</i> |
| EWPP PremPL 4HRAHR VSP4900-12MXU-12XE-B1 | 98507- VSP4900- 12MXU-12XE- B1 | \$ 2,574.00 | 6% | <i>\$2,437.71</i> |
| EWPP PremierPLS 4HR AHR VSP4900-24S | 98507- VSP4900-24S | \$ 1,916.00 | 6% | <i>\$1,814.55</i> |
| EWPP PremierPLS 4HR AHR VSP4900-24S-B3 | 98507- VSP4900-24S- B3 | \$ 1,915.00 | 6% | <i>\$1,813.60</i> |

| | | | | |
|--|-------------------------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR VSP4900-24XE | 98507- VSP4900- 24XE | \$ 2,574.00 | 6% | <i>\$2,437.71</i> |
| EWPP PremierPLS 4HR AHR VSP4900-24XE-B3 | 98507- VSP4900- 24XE-B3 | \$ 2,574.00 | 6% | <i>\$2,437.71</i> |
| EWPP PremierPLS 4HR AHR X435-24P-4S | 98507-X435- 24P-4S | \$ 1,074.00 | 6% | <i>\$1,017.13</i> |
| EWPP PremierPLS 4HR AHR X435-24T-4S | 98507-X435- 24T-4S | \$ 917.00 | 6% | <i>\$868.44</i> |
| EWPP PremierPLS 4HR AHR X435-8P-2T-W | 98507-X435- 8P-2T-W | \$ 917.00 | 6% | <i>\$868.44</i> |
| EWPP PremierPLS 4HR AHR X435-8P-4S | 98507-X435- 8P-4S | \$ 899.00 | 6% | <i>\$851.40</i> |
| EWPP PremierPLS 4HR AHR X435-8T-4S | 98507-X435- 8T-4S | \$ 864.00 | 6% | <i>\$818.25</i> |
| EWPPPremierPLS 4HR AHR X460-24 | 98507-X460- 24P | \$ 2,598.00 | 6% | <i>\$2,460.44</i> |
| EWPPPremierPLS 4HR AHR X460-24 | 98507-X460- 24T | \$ 2,224.00 | 6% | <i>\$2,106.24</i> |
| EWPPPremierPLS 4HR AHR X460-24 | 98507-X460- 24TDC | \$ 2,664.00 | 6% | <i>\$2,522.94</i> |
| EWPPPremierPLS 4HR AHR X460-24 | 98507-X460- 24X | \$ 3,032.00 | 6% | <i>\$2,871.46</i> |
| EWPPPremierPLS 4HR AHR X460-24 | 98507-X460- 24XDC | \$ 3,230.00 | 6% | <i>\$3,058.97</i> |
| EWPPPremierPLS 4HR AHR X460-48 | 98507-X460- 48P | \$ 3,032.00 | 6% | <i>\$2,871.46</i> |
| EWPPPremierPLS 4HR AHR X460-48 | 98507-X460- 48T | \$ 2,782.00 | 6% | <i>\$2,634.69</i> |
| EWPPPremierPLS 4HR AHR X460-48 | 98507-X460- 48TDC | \$ 3,170.00 | 6% | <i>\$3,002.15</i> |
| EWPPPremierPLS 4HR AHR X460-48 | 98507-X460- 48X | \$ 3,610.00 | 6% | <i>\$3,418.85</i> |
| EWPPPremierPLS 4HR AHR X460-48 | 98507-X460- 48XDC | \$ 3,544.00 | 6% | <i>\$3,356.35</i> |
| EWPP PremierPLS 4HR AHR X465-24MU | 98507-X465- 24MU | \$ 2,781.00 | 6% | <i>\$2,633.75</i> |
| EWPP PremierPLS 4HR AHR X465-24S | 98507-X465- 24S | \$ 1,916.00 | 6% | <i>\$1,814.55</i> |
| EWPP PremierPLS 4HR AHR X465-24S-B3 | 98507-X465- 24S-B3 | \$ 1,915.00 | 6% | <i>\$1,813.60</i> |

| | | | | |
|---|-----------------------|-------------|----|-------------------|
| EWPP PremierPLS 4HR AHR X465-24W | 98507-X465-24W | \$ 1,915.00 | 6% | <i>\$1,813.60</i> |
| EWPP PremierPLS 4HR AHR X465-24XE | 98507-X465-24XE | \$ 2,574.00 | 6% | <i>\$2,437.71</i> |
| EWPP PremierPLS 4HR AHR X465-24XE-B3 | 98507-X465-24XE-B3 | \$ 2,574.00 | 6% | <i>\$2,437.71</i> |
| EWPP PremierPLS 4HR AHR X465-48P | 98507-X465-48P | \$ 2,189.00 | 6% | <i>\$2,073.09</i> |
| EWPP PremierPLS 4HR AHR X465-48T | 98507-X465-48T | \$ 2,149.00 | 6% | <i>\$2,035.21</i> |
| EWPP PremierPLS 4HR AHR X465-48W | 98507-X465-48W | \$ 2,454.00 | 6% | <i>\$2,324.06</i> |
| EWPP PremierPLS 4HR AHR X465i-48W | 98507-X465i-48W | \$ 2,751.00 | 6% | <i>\$2,605.33</i> |
| EWPP PremierPLS 4HR AHR X465i-48W-B1-S1 | 98507-X465i-48W-B1-S1 | \$ 2,751.00 | 6% | <i>\$2,605.33</i> |
| EWPP PremierPLS 4HR AHR X465i-48W-B2-S1 | 98507-X465i-48W-B2-S1 | \$ 2,751.00 | 6% | <i>\$2,605.33</i> |
| EWPPPremierPLS 4HR AHR X480-24 | 98507-X480-24X | \$ 3,338.00 | 6% | <i>\$3,161.25</i> |
| EWPPPremierPLS 4HR AHR X480-48 | 98507-X480-48T | \$ 2,938.00 | 6% | <i>\$2,782.43</i> |
| EWPPPremierPLS 4HR AHR X480-48 | 98507-X480-48X | \$ 4,066.00 | 6% | <i>\$3,850.71</i> |
| EWPP PremierPLS 4HR AHR X695-48Y-8C | 98507-X695-48Y-8C | \$ 4,845.00 | 6% | <i>\$4,588.46</i> |
| EWPP PremierPLS 4HR AHR XA1440 | 98507-XA1440 | \$ 1,128.00 | 6% | <i>\$1,068.27</i> |
| EWPP PremierPLS 4HR AHR XA1480 | 98507-XA1480 | \$ 1,250.00 | 6% | <i>\$1,183.81</i> |
| EWPPPremierPLS 4HR AHR XGM3-2S | 98507-XGM3-2SF | \$ 813.00 | 6% | <i>\$769.95</i> |
| EWPP PremierPLS 4HR AHR XR600 | 98507-XR600 | \$ 1,256.00 | 6% | <i>\$1,189.49</i> |
| EWPP PremierPLS4HROnsite 1130C | 98508-1130C | \$ 3,440.00 | 6% | <i>\$3,257.85</i> |
| EWPP PremierPLS4HROnsite 16119 | 98508-16119 | \$ 930.00 | 6% | <i>\$880.76</i> |
| EWPP PremierPLS4HROnsite 16120 | 98508-16120 | \$ 1,057.00 | 6% | <i>\$1,001.03</i> |
| EWPP PremierPLS4HROnsite 16126 | 98508-16126 | \$ 930.00 | 6% | <i>\$880.76</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS4HROnsite 16127 | 98508-16127 | \$ 975.00 | 6% | \$923.37 |
| EWPP PremierPLS4HROnsite 16172 | 98508-16172 | \$ 1,794.00 | 6% | \$1,699.01 |
| EWPPPremierPLS4HROnsite 16172T | 98508-16172T | \$ 1,921.00 | 6% | \$1,819.28 |
| EWPP PremierPLS4HROnsite 16173 | 98508-16173 | \$ 1,810.00 | 6% | \$1,714.16 |
| EWPPPremierPLS4HROnsite 16173T | 98508-16173T | \$ 1,936.00 | 6% | \$1,833.49 |
| EWPP PremierPLS4HROnsite 16174 | 98508-16174 | \$ 2,100.00 | 6% | \$1,988.81 |
| EWPP PremierPLS4HROnsite 16175 | 98508-16175 | \$ 2,143.00 | 6% | \$2,029.53 |
| EWPP PremierPLS4HROnsite 16176 | 98508-16176 | \$ 2,039.00 | 6% | \$1,931.03 |
| EWPP PremierPLS4HROnsite 16177 | 98508-16177 | \$ 1,934.00 | 6% | \$1,831.59 |
| EWPPPremierPLS4HROnsite 16177T | 98508-16177T | \$ 2,223.00 | 6% | \$2,105.29 |
| EWPP PremierPLS4HROnsite 16178 | 98508-16178 | \$ 2,377.00 | 6% | \$2,251.14 |
| EWPP PremierPLS4HROnsite 16179 | 98508-16179 | \$ 2,408.00 | 6% | \$2,280.50 |
| EWPPPremierPLS4HROnsite 16179T | 98508-16179T | \$ 2,586.00 | 6% | \$2,449.07 |
| EWPPPremierPLS4HROnsite 16301T | 98508-16301T | \$ 4,124.00 | 6% | \$3,905.63 |
| EWPPPremierPLS4HROnsite 16303T | 98508-16303T | \$ 4,124.00 | 6% | \$3,905.63 |
| EWPPPremierPLS4HROnsite 16304T | 98508-16304T | \$ 5,115.00 | 6% | \$4,844.16 |
| EWPPPremierPLS4HROnsite 16401T | 98508-16401T | \$ 2,642.00 | 6% | \$2,502.11 |
| EWPPPremierPLS4HROnsite 16402T | 98508-16402T | \$ 3,353.00 | 6% | \$3,175.46 |
| EWPPPremierPLS4HROnsite 16403T | 98508-16403T | \$ 3,119.00 | 6% | \$2,953.85 |
| EWPPPremierPLS4HROnsite 16404T | 98508-16404T | \$ 3,119.00 | 6% | \$2,953.85 |
| EWPPPremierPLS4HROnsite 16405T | 98508-16405T | \$ 3,699.00 | 6% | \$3,503.14 |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLS4HROnsite 16406T | 98508-16406T | \$ 4,513.00 | 6% | <i>\$4,274.04</i> |
| EWPP PremierPLS4HROnsite 16431 | 98508-16431 | \$ 3,306.00 | 6% | <i>\$3,130.95</i> |
| EWPP PremierPLS4HROnsite 16432 | 98508-16432 | \$ 3,440.00 | 6% | <i>\$3,257.85</i> |
| EWPP PremierPLS4HROnsite 16440 | 98508-16440 | \$ 2,522.00 | 6% | <i>\$2,388.46</i> |
| EWPP PremierPLS4HROnsite 16441 | 98508-16441 | \$ 2,397.00 | 6% | <i>\$2,270.08</i> |
| EWPP PremierPLS4HROnsite 16442 | 98508-16442 | \$ 975.00 | 6% | <i>\$923.37</i> |
| EWPP PremierPLS4HROnsite 16444 | 98508-16444 | \$ 708.00 | 6% | <i>\$670.51</i> |
| EWPP PremierPLS4HROnsite 16501 | 98508-16501 | \$ 1,557.00 | 6% | <i>\$1,474.56</i> |
| EWPPPremierPLS4HROnsite 16501T | 98508-16501T | \$ 1,645.00 | 6% | <i>\$1,557.90</i> |
| EWPP PremierPLS4HROnsite 16502 | 98508-16502 | \$ 1,690.00 | 6% | <i>\$1,600.51</i> |
| EWPPPremierPLS4HROnsite 16502T | 98508-16502T | \$ 1,769.00 | 6% | <i>\$1,675.33</i> |
| EWPP PremierPLS4HROnsite 16503 | 98508-16503 | \$ 1,614.00 | 6% | <i>\$1,528.54</i> |
| EWPPPremierPLS4HROnsite 16503T | 98508-16503T | \$ 1,718.00 | 6% | <i>\$1,627.03</i> |
| EWPP PremierPLS4HROnsite 16504 | 98508-16504 | \$ 1,827.00 | 6% | <i>\$1,730.26</i> |
| EWPPPremierPLS4HROnsite 16504T | 98508-16504T | \$ 1,938.00 | 6% | <i>\$1,835.38</i> |
| EWPP PremierPLS4HROnsite 16505 | 98508-16505 | \$ 1,865.00 | 6% | <i>\$1,766.25</i> |
| EWPPPremierPLS4HROnsite 16505T | 98508-16505T | \$ 2,025.00 | 6% | <i>\$1,917.78</i> |
| EWPP PremierPLS4HROnsite 16506 | 98508-16506 | \$ 2,190.00 | 6% | <i>\$2,074.04</i> |
| EWPPPremierPLS4HROnsite 16506T | 98508-16506T | \$ 2,422.00 | 6% | <i>\$2,293.76</i> |
| EWPP PremierPLS4HROnsite 16507 | 98508-16507 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| EWPPPremierPLS4HROnsite 16507T | 98508-16507T | \$ 2,298.00 | 6% | <i>\$2,176.32</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS4HROnsite 16508 | 98508-16508 | \$ 2,347.00 | 6% | \$2,222.73 |
| EWPPPremierPLS4HROnsite 16508T | 98508-16508T | \$ 2,561.00 | 6% | \$2,425.40 |
| EWPP PremierPLS4HROnsite 16509 | 98508-16509 | \$ 2,347.00 | 6% | \$2,222.73 |
| EWPPPremierPLS4HROnsite 16509T | 98508-16509T | \$ 2,561.00 | 6% | \$2,425.40 |
| EWPP PremierPLS4HROnsite 16510 | 98508-16510 | \$ 2,554.00 | 6% | \$2,418.77 |
| EWPPPremierPLS4HROnsite 16510T | 98508-16510T | \$ 2,805.00 | 6% | \$2,656.48 |
| EWPP PremierPLS4HROnsite 16513 | 98508-16513 | \$ 2,114.00 | 6% | \$2,002.06 |
| EWPP PremierPLS4HROnsite 16514 | 98508-16514 | \$ 2,505.00 | 6% | \$2,372.36 |
| EWPP PremierPLS4HROnsite 16515 | 98508-16515 | \$ 1,436.00 | 6% | \$1,359.96 |
| EWPP PremierPLS4HROnsite 16516 | 98508-16516 | \$ 1,463.00 | 6% | \$1,385.53 |
| EWPP PremierPLS4HROnsite 16517 | 98508-16517 | \$ 1,689.00 | 6% | \$1,599.57 |
| EWPP PremierPLS4HROnsite 16518 | 98508-16518 | \$ 1,634.00 | 6% | \$1,547.48 |
| EWPP PremierPLS4HROnsite 16519 | 98508-16519 | \$ 1,703.00 | 6% | \$1,612.83 |
| EWPP PremierPLS4HROnsite 16520 | 98508-16520 | \$ 1,973.00 | 6% | \$1,868.53 |
| EWPP PremierPLS4HROnsite 16530 | 98508-16530 | \$ 1,596.00 | 6% | \$1,511.49 |
| EWPP PremierPLS4HROnsite 16531 | 98508-16531 | \$ 1,689.00 | 6% | \$1,599.57 |
| EWPPPremierPLS4HROnsite 16531T | 98508-16531T | \$ 1,758.00 | 6% | \$1,664.91 |
| EWPP PremierPLS4HROnsite 16532 | 98508-16532 | \$ 1,689.00 | 6% | \$1,599.57 |
| EWPPPremierPLS4HROnsite 16532T | 98508-16532T | \$ 1,758.00 | 6% | \$1,664.91 |
| EWPP PremierPLS4HROnsite 16533 | 98508-16533 | \$ 1,827.00 | 6% | \$1,730.26 |
| EWPPPremierPLS4HROnsite 16533T | 98508-16533T | \$ 1,925.00 | 6% | \$1,823.07 |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS4HROnsite 16534 | 98508-16534 | \$ 1,866.00 | 6% | <i>\$1,767.20</i> |
| EWPP PremierPLS4HROnsite 16535 | 98508-16535 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPP PremierPLS4HROnsite 16535A | 98508-16535A | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPPPremierPLS4HROnsite 16535T | 98508-16535T | \$ 2,264.00 | 6% | <i>\$2,144.12</i> |
| EWPP PremierPLS4HROnsite 16536 | 98508-16536 | \$ 1,577.00 | 6% | <i>\$1,493.50</i> |
| EWPP PremierPLS4HROnsite 16537 | 98508-16537 | \$ 1,709.00 | 6% | <i>\$1,618.51</i> |
| EWPP PremierPLS4HROnsite 16538 | 98508-16538 | \$ 1,808.00 | 6% | <i>\$1,712.27</i> |
| EWPPPremierPLS4HROnsite 16538T | 98508-16538T | \$ 2,109.00 | 6% | <i>\$1,997.33</i> |
| EWPP PremierPLS4HROnsite 16539 | 98508-16539 | \$ 1,981.00 | 6% | <i>\$1,876.11</i> |
| EWPP PremierPLS4HROnsite 16540 | 98508-16540 | \$ 1,766.00 | 6% | <i>\$1,672.49</i> |
| EWPP PremierPLS4HROnsite 16541 | 98508-16541 | \$ 1,424.00 | 6% | <i>\$1,348.60</i> |
| EWPP PremierPLS4HROnsite 16560 | 98508-16560 | \$ 1,346.00 | 6% | <i>\$1,274.73</i> |
| EWPP PremierPLS4HROnsite 16561 | 98508-16561 | \$ 1,403.00 | 6% | <i>\$1,328.71</i> |
| EWPP PremierPLS4HROnsite 16562 | 98508-16562 | \$ 1,444.00 | 6% | <i>\$1,367.54</i> |
| EWPP PremierPLS4HROnsite 16563 | 98508-16563 | \$ 1,520.00 | 6% | <i>\$1,439.52</i> |
| EWPP PremierPLS4HROnsite 16564 | 98508-16564 | \$ 1,591.00 | 6% | <i>\$1,506.76</i> |
| EWPP PremierPLS4HROnsite 16565 | 98508-16565 | \$ 1,772.00 | 6% | <i>\$1,678.17</i> |
| EWPP PremierPLS4HROnsite 16566 | 98508-16566 | \$ 1,305.00 | 6% | <i>\$1,235.90</i> |
| EWPP PremierPLS4HROnsite 16567 | 98508-16567 | \$ 1,376.00 | 6% | <i>\$1,303.14</i> |
| EWPP PremierPLS4HROnsite 16568 | 98508-16568 | \$ 1,347.00 | 6% | <i>\$1,275.68</i> |
| EWPP PremierPLS4HROnsite 16569 | 98508-16569 | \$ 1,424.00 | 6% | <i>\$1,348.60</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS4HROnsite 16570 | 98508-16570 | \$ 1,444.00 | 6% | <i>\$1,367.54</i> |
| EWPP PremierPLS4HROnsite 16571 | 98508-16571 | \$ 1,591.00 | 6% | <i>\$1,506.76</i> |
| EWPP PremierPLS4HROnsite 16701 | 98508-16701 | \$ 1,995.00 | 6% | <i>\$1,889.36</i> |
| EWPP PremierPLS4HROnsite 16702 | 98508-16702 | \$ 2,363.00 | 6% | <i>\$2,237.88</i> |
| EWPP PremierPLS4HROnsite 16703 | 98508-16703 | \$ 2,241.00 | 6% | <i>\$2,122.34</i> |
| EWPPPremierPLS4HROnsite 16703T | 98508-16703T | \$ 2,416.00 | 6% | <i>\$2,288.07</i> |
| EWPP PremierPLS4HROnsite 16704 | 98508-16704 | \$ 2,661.00 | 6% | <i>\$2,520.10</i> |
| EWPPPremierPLS4HROnsite 16704T | 98508-16704T | \$ 2,366.00 | 6% | <i>\$2,240.72</i> |
| EWPP PremierPLS4HROnsite 16705 | 98508-16705 | \$ 2,363.00 | 6% | <i>\$2,237.88</i> |
| EWPPPremierPLS4HROnsite 16705T | 98508-16705T | \$ 2,549.00 | 6% | <i>\$2,414.03</i> |
| EWPP PremierPLS4HROnsite 16706 | 98508-16706 | \$ 3,073.00 | 6% | <i>\$2,910.28</i> |
| EWPPPremierPLS4HROnsite 16706T | 98508-16706T | \$ 3,320.00 | 6% | <i>\$3,144.21</i> |
| EWPP PremierPLS4HROnsite 16710 | 98508-16710 | \$ 768.00 | 6% | <i>\$727.33</i> |
| EWPPPremierPLS4HROnsite 16710T | 98508-16710T | \$ 833.00 | 6% | <i>\$788.89</i> |
| EWPP PremierPLS4HROnsite 16711 | 98508-16711 | \$ 570.00 | 6% | <i>\$539.82</i> |
| EWPPPremierPLS4HROnsite 16711T | 98508-16711T | \$ 606.00 | 6% | <i>\$573.91</i> |
| EWPP PremierPLS4HROnsite 16712 | 98508-16712 | \$ 624.00 | 6% | <i>\$590.96</i> |
| EWPPPremierPLS4HROnsite 16712T | 98508-16712T | \$ 655.00 | 6% | <i>\$620.32</i> |
| EWPP PremierPLS4HROnsite 16713 | 98508-16713 | \$ 518.00 | 6% | <i>\$490.57</i> |
| EWPPPremierPLS4HROnsite 16713T | 98508-16713T | \$ 552.00 | 6% | <i>\$522.77</i> |
| EWPP PremierPLS4HROnsite 16715 | 98508-16715 | \$ 543.00 | 6% | <i>\$514.25</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLS4HROnsite 16715T | 98508-16715T | \$ 606.00 | 6% | <i>\$573.91</i> |
| EWPP PremierPLS4HROnsite 16716 | 98508-16716 | \$ 1,955.00 | 6% | <i>\$1,851.48</i> |
| EWPPPremierPLS4HROnsite 16716T | 98508-16716T | \$ 2,101.00 | 6% | <i>\$1,989.75</i> |
| EWPP PremierPLS4HROnsite 16717 | 98508-16717 | \$ 2,143.00 | 6% | <i>\$2,029.53</i> |
| EWPP PremierPLS4HROnsite 16718 | 98508-16718 | \$ 2,001.00 | 6% | <i>\$1,895.05</i> |
| EWPP PremierPLS4HROnsite 16719 | 98508-16719 | \$ 2,201.00 | 6% | <i>\$2,084.46</i> |
| EWPP PremierPLS4HROnsite 16720 | 98508-16720 | \$ 2,787.00 | 6% | <i>\$2,639.43</i> |
| EWPPPremierPLS4HROnsite 16720T | 98508-16720T | \$ 3,247.00 | 6% | <i>\$3,075.07</i> |
| EWPP PremierPLS4HROnsite 16756 | 98508-16756 | \$ 2,490.00 | 6% | <i>\$2,358.15</i> |
| EWPPPremierPLS4HROnsite 16756T | 98508-16756T | \$ 2,947.00 | 6% | <i>\$2,790.96</i> |
| EWPP PremierPLS4HROnsite 16757 | 98508-16757 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLS4HROnsite 16757T | 98508-16757T | \$ 2,860.00 | 6% | <i>\$2,708.56</i> |
| EWPP PremierPLS4HROnsite 16790 | 98508-16790 | \$ 2,970.00 | 6% | <i>\$2,812.74</i> |
| EWPP PremierPLS4HROnsite 16791 | 98508-16791 | \$ 3,833.00 | 6% | <i>\$3,630.04</i> |
| EWPP PremierPLS4HROnsite 17101 | 98508-17101 | \$ 5,515.00 | 6% | <i>\$5,222.98</i> |
| EWPPPremierPLS4HROnsite 17101T | 98508-17101T | \$ 6,787.00 | 6% | <i>\$6,427.63</i> |
| EWPP PremierPLS4HROnsite 17102 | 98508-17102 | \$ 5,515.00 | 6% | <i>\$5,222.98</i> |
| EWPPPremierPLS4HROnsite 17102T | 98508-17102T | \$ 6,787.00 | 6% | <i>\$6,427.63</i> |
| EWPP PremierPLS4HROnsite 17103 | 98508-17103 | \$ 4,183.00 | 6% | <i>\$3,961.51</i> |
| EWPP PremierPLS4HROnsite 17103C | 98508-17103C | \$ 4,060.00 | 6% | <i>\$3,845.02</i> |
| EWPPPremierPLS4HROnsite 17103T | 98508-17103T | \$ 5,114.00 | 6% | <i>\$4,843.21</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS4HROnsite 17104 | 98508-17104 | \$ 4,183.00 | 6% | <i>\$3,961.51</i> |
| EWPPPremierPLS4HROnsite 17104T | 98508-17104T | \$ 5,114.00 | 6% | <i>\$4,843.21</i> |
| EWPP PremierPLS4HROnsite 17121 | 98508-17121 | \$ 1,327.00 | 6% | <i>\$1,256.74</i> |
| EWPP PremierPLS4HROnsite 17122 | 98508-17122 | \$ 960.00 | 6% | <i>\$909.17</i> |
| EWPP PremierPLS4HROnsite 17200 | 98508-17200 | \$ 8,028.00 | 6% | <i>\$7,602.92</i> |
| EWPPPremierPLS4HROnsite 17200T | 98508-17200T | \$ 9,066.00 | 6% | <i>\$8,585.96</i> |
| EWPP PremierPLS4HROnsite 17201 | 98508-17201 | \$ 8,028.00 | 6% | <i>\$7,602.92</i> |
| EWPPPremierPLS4HROnsite 17201T | 98508-17201T | \$ 9,066.00 | 6% | <i>\$8,585.96</i> |
| EWPP PremierPLS4HROnsite 17202 | 98508-17202 | \$ 8,028.00 | 6% | <i>\$7,602.92</i> |
| EWPPPremierPLS4HROnsite 17202T | 98508-17202T | \$ 9,066.00 | 6% | <i>\$8,585.96</i> |
| EWPP PremierPLS4HROnsite 17203 | 98508-17203 | \$ 8,139.00 | 6% | <i>\$7,708.04</i> |
| EWPPPremierPLS4HROnsite 17203T | 98508-17203T | \$ 9,179.00 | 6% | <i>\$8,692.97</i> |
| EWPP PremierPLS4HROnsite 17204 | 98508-17204 | \$ 8,139.00 | 6% | <i>\$7,708.04</i> |
| EWPPPremierPLS4HROnsite 17204T | 98508-17204T | \$ 9,179.00 | 6% | <i>\$8,692.97</i> |
| EWPP PremierPLS4HROnsite 17205 | 98508-17205 | \$ 8,080.00 | 6% | <i>\$7,652.16</i> |
| EWPPPremierPLS4HROnsite 17205T | 98508-17205T | \$ 9,127.00 | 6% | <i>\$8,643.73</i> |
| EWPP PremierPLS4HROnsite 17206 | 98508-17206 | \$ 8,080.00 | 6% | <i>\$7,652.16</i> |
| EWPPPremierPLS4HROnsite 17206T | 98508-17206T | \$ 9,127.00 | 6% | <i>\$8,643.73</i> |
| EWPP PremierPLS4HROnsite 17300 | 98508-17300 | \$ 5,799.00 | 6% | <i>\$5,491.94</i> |
| EWPP PremierPLS4HROnsite 17310 | 98508-17310 | \$ 5,376.00 | 6% | <i>\$5,091.34</i> |
| EWPP PremierPLS4HROnsite 17350 | 98508-17350 | \$ 5,654.00 | 6% | <i>\$5,354.62</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS4HROnsite 17360 | 98508-17360 | \$ 6,681.00 | 6% | <i>\$6,327.24</i> |
| EWPP PremierPLS4HROnsite 17401 | 98508-17401 | \$ 1,863.00 | 6% | <i>\$1,764.35</i> |
| EWPPPremierPLS4HROnsite 17401G | 98508-17401G | \$ 2,002.00 | 6% | <i>\$1,895.99</i> |
| EWPPPremierPLS4HROnsite 17401T | 98508-17401T | \$ 1,996.00 | 6% | <i>\$1,890.31</i> |
| EWPP PremierPLS4HROnsite 17402 | 98508-17402 | \$ 2,040.00 | 6% | <i>\$1,931.98</i> |
| EWPPPremierPLS4HROnsite 17402G | 98508-17402G | \$ 2,104.00 | 6% | <i>\$1,992.59</i> |
| EWPPPremierPLS4HROnsite 17402T | 98508-17402T | \$ 2,094.00 | 6% | <i>\$1,983.12</i> |
| EWPP PremierPLS4HROnsite 17403 | 98508-17403 | \$ 2,176.00 | 6% | <i>\$2,060.78</i> |
| EWPP PremierPLS4HROnsite 17404 | 98508-17404 | \$ 1,687.00 | 6% | <i>\$1,597.67</i> |
| EWPP PremierPLS4HROnsite 17405 | 98508-17405 | \$ 1,724.00 | 6% | <i>\$1,632.71</i> |
| EWPP PremierPLS4HROnsite 17700 | 98508-17700 | \$ 9,560.00 | 6% | <i>\$9,053.80</i> |
| EWPP PremierPLS4HROnsite 17701 | 98508-17701 | \$ 8,205.00 | 6% | <i>\$7,770.55</i> |
| EWPP PremierPLS4HROnsite 17702 | 98508-17702 | \$ 8,205.00 | 6% | <i>\$7,770.55</i> |
| EWPP PremierPLS4HROnsite 17703 | 98508-17703 | \$ 8,965.00 | 6% | <i>\$8,490.30</i> |
| EWPP PremierPLS4HROnsite 17704 | 98508-17704 | \$ 8,965.00 | 6% | <i>\$8,490.30</i> |
| EWPP PremierPLS4HROnsite 17705 | 98508-17705 | \$ 8,254.00 | 6% | <i>\$7,816.95</i> |
| EWPP PremierPLS4HROnsite 17706 | 98508-17706 | \$ 8,254.00 | 6% | <i>\$7,816.95</i> |
| EWPP PremierPLS4HROnsite 17800 | 98508-17800 | \$ 9,867.00 | 6% | <i>\$9,344.54</i> |
| EWPP PremierPLS4HROnsite 17810 | 98508-17810 | \$ 8,134.00 | 6% | <i>\$7,703.30</i> |
| EWPP PremierPLS4HROnsite 18101 | 98508-18101 | \$ 822.00 | 6% | <i>\$778.48</i> |
| EWPP PremierPLS4HROnsite 18102 | 98508-18102 | \$ 947.00 | 6% | <i>\$896.86</i> |

| | | | | |
|---------------------------------------|---------------------|--------------|----|--------------------|
| EWPP PremierPLS4HROnsite 18103 | 98508-18103 | \$ 999.00 | 6% | <i>\$946.10</i> |
| EWPP PremierPLS4HROnsite 18104 | 98508-18104 | \$ 1,255.00 | 6% | <i>\$1,188.55</i> |
| EWPP PremierPLS4HROnsite 18104-6PK | 98508-18104- 6PK | \$ 7,534.00 | 6% | <i>\$7,135.07</i> |
| EWPP PremierPLS4HROnsite 30135 | 98508-30135 | \$ 3,404.00 | 6% | <i>\$3,223.76</i> |
| EWPP PremierPLS4HROnsite 30136 | 98508-30136 | \$ 11,307.00 | 6% | <i>\$10,708.29</i> |
| EWPP PremierPLS4HROnsite 30137 | 98508-30137 | \$ 3,602.00 | 6% | <i>\$3,411.27</i> |
| EWPP PremierPLS4HROnsite 30138 | 98508-30138 | \$ 10,166.00 | 6% | <i>\$9,627.71</i> |
| EWPP PremierPLS4HROnsite 30139 | 98508-30139 | \$ 15,577.00 | 6% | <i>\$14,752.20</i> |
| EWPP PremierPLS4HROnsite 30912 | 98508-30912 | \$ 458.00 | 6% | <i>\$433.75</i> |
| EWPP PremierPLS4HROnsite 30913 | 98508-30913 | \$ 458.00 | 6% | <i>\$433.75</i> |
| EWPP PremierPLS4HROnsite 31012 | 98508-31012 | \$ 494.00 | 6% | <i>\$467.84</i> |
| EWPP PremierPLS4HROnsite 31013 | 98508-31013 | \$ 494.00 | 6% | <i>\$467.84</i> |
| EWPP PremierPLS4HROnsite 31014 | 98508-31014 | \$ 494.00 | 6% | <i>\$467.84</i> |
| EWPP PremierPLS4HROnsite 31015 | 98508-31015 | \$ 494.00 | 6% | <i>\$467.84</i> |
| EWPP PremierPLS4HROnsite 31016 | 98508-31016 | \$ 780.00 | 6% | <i>\$738.70</i> |
| EWPP PremierPLS4HROnsite 31017 | 98508-31017 | \$ 780.00 | 6% | <i>\$738.70</i> |
| EWPP PremierPLS4HROnsite 31018 | 98508-31018 | \$ 847.00 | 6% | <i>\$802.15</i> |
| EWPP PremierPLS4HROnsite 31019 | 98508-31019 | \$ 847.00 | 6% | <i>\$802.15</i> |
| EWPP PremierPLS4HROnsite 31025 | 98508-31025 | \$ 400.00 | 6% | <i>\$378.82</i> |
| EWPP PremierPLS4HROnsite 31026 | 98508-31026 | \$ 400.00 | 6% | <i>\$378.82</i> |
| EWPP PremierPLS4HROnsite 31028 | 98508-31028 | \$ 399.00 | 6% | <i>\$377.87</i> |

| | | | | |
|--|------------------------|--------------|-----|------------|
| EWPP PremierPLS4HROnsite 31029 | 98508-31029 | \$ 399.00 | 6% | \$377.87 |
| EWPP PremierPLS4HROnsite 31031 | 98508-31031 | \$ 425.00 | 6% | \$402.50 |
| EWPP PremierPLS4HROnsite 31032 | 98508-31032 | \$ 425.00 | 6% | \$402.50 |
| EWPP PremierPLS4HROnsite 31034 | 98508-31034 | \$ 509.00 | 6% | \$482.05 |
| EWPP PremierPLS4HROnsite 31035 | 98508-31035 | \$ 509.00 | 6% | \$482.05 |
| EWPP PremierPLS4HROnsite 31050 | 98508-31050 | \$ 497.00 | 6% | \$470.68 |
| EWPP PremierPLS4HROnsite 31051 | 98508-31051 | \$ 497.00 | 6% | \$470.68 |
| EWPP PremierPLS4HROnsite 31055 | 98508-31055 | \$ 497.00 | 6% | \$470.68 |
| EWPP PremierPLS4HROnsite 31056 | 98508-31056 | \$ 497.00 | 6% | \$470.68 |
| EWPP PremierPLS4HROnsite 39031 | 98508-39031 | \$ 913.00 | 6% | \$864.66 |
| EWPP PremierPLS4HROnsite 39032 | 98508-39032 | \$ 975.00 | 6% | \$923.37 |
| EWPP PremierPLS4HROnsite 39033 | 98508-39033 | \$ 913.00 | 6% | \$864.66 |
| EWPP PremierPLS4HROnsite 39034 | 98508-39034 | \$ 913.00 | 6% | \$864.66 |
| EWPP PremierPLS4HROnsite 39035 | 98508-39035 | \$ 2,033.00 | 6% | \$1,925.35 |
| EWPP PremierPLS4HROnsite 39036 | 98508-39036 | \$ 823.00 | 6% | \$779.42 |
| EWPP PremierPLS4HROnsite 39037 | 98508-39037 | \$ 823.00 | 6% | \$779.42 |
| EWPP PremierPLS4HROnsite 39038 | 98508-39038 | \$ 990.00 | 6% | \$937.58 |
| EWPP PremierPLS4HROnsite 39039 | 98508-39039 | \$ 990.00 | 6% | \$937.58 |
| EWPP PremierPLS4HROnsite 4120-24MW-4Y | 98508-4120- 24MW-4Y | \$ 2,092.00 | 6% | \$1,981.23 |
| EWPP PremierPLS4HROnsite 4120-48MW-4Y | 98508-4120- 48MW-4Y | \$ 2,520.00 | 6% | \$2,386.57 |
| EWPP PremierPLS4HROnsite 4120C | 98508-4120C | \$ 10,746.00 | 10% | \$9,743.94 |

| | | | | |
|---|---------------------------|--------------|----|--------------------|
| EWPP PremierPLS4HROnsite 4120C-1 | 98508-4120C-1 | \$ 10,705.00 | 6% | <i>\$10,138.17</i> |
| EWPP PremierPLS4HROnsite 41216 | 98508-41216 | \$ 3,229.00 | 6% | <i>\$3,058.02</i> |
| EWPP PremierPLS4HROnsite 4220-12P-4X | 98508-4220- 12P-4X | \$ 1,184.00 | 6% | <i>\$1,121.31</i> |
| EWPP PremierPLS4HROnsite 4220-12T-4X | 98508-4220- 12T-4X | \$ 1,083.00 | 6% | <i>\$1,025.66</i> |
| EWPP PremierPLS4HROnsite 4220-24P-4X | 98508-4220- 24P-4X | \$ 1,309.00 | 6% | <i>\$1,239.69</i> |
| EWPP PremierPLS4HROnsite 4220-24T-4X | 98508-4220- 24T-4X | \$ 1,196.00 | 6% | <i>\$1,132.67</i> |
| EWPP PremierPLS4HROnsite 4220-48P-4X | 98508-4220- 48P-4X | \$ 1,559.00 | 6% | <i>\$1,476.45</i> |
| EWPP PremierPLS4HROnsite 4220-48T-4X | 98508-4220- 48T-4X | \$ 1,371.00 | 6% | <i>\$1,298.41</i> |
| EWPP PremierPLS4HROnsite 4220-4MW-20P-4X | 98508-4220- 4MW-20P-4X | \$ 1,497.00 | 6% | <i>\$1,417.73</i> |
| EWPP PremierPLS4HROnsite 4220-4MW-8P-4X | 98508-4220- 4MW-8P-4X | \$ 1,296.00 | 6% | <i>\$1,227.38</i> |
| EWPP PremierPLS4HROnsite 4220-8MW-40P-4X | 98508-4220- 8MW-40P-4X | \$ 1,810.00 | 6% | <i>\$1,714.16</i> |
| EWPP PremierPLS4HROnsite 4220-8X | 98508-4220-8X | \$ 1,334.00 | 6% | <i>\$1,263.36</i> |
| EWPP PremierPLS4HROnsite 48001 | 98508-48001 | \$ 13,776.00 | 6% | <i>\$13,046.56</i> |
| EWPP PremierPLS4HROnsite 48038 | 98508-48038 | \$ 5,079.00 | 6% | <i>\$4,810.07</i> |
| EWPP PremierPLS4HROnsite 48039 | 98508-48039 | \$ 5,079.00 | 6% | <i>\$4,810.07</i> |
| EWPP PremierPLS4HROnsite 48040 | 98508-48040 | \$ 4,806.00 | 6% | <i>\$4,551.52</i> |
| EWPP PremierPLS4HROnsite 48041 | 98508-48041 | \$ 5,079.00 | 6% | <i>\$4,810.07</i> |
| EWPP PremierPLS4HROnsite 48046 | 98508-48046 | \$ 6,529.00 | 6% | <i>\$6,183.29</i> |
| EWPP PremierPLS4HROnsite 48047 | 98508-48047 | \$ 16,647.00 | 6% | <i>\$15,765.54</i> |
| EWPP PremierPLS4HROnsite 48051 | 98508-48051 | \$ 11,592.00 | 6% | <i>\$10,978.20</i> |
| EWPP PremierPLS4HROnsite 48061 | 98508-48061 | \$ 13,468.00 | 6% | <i>\$12,754.87</i> |

| | | | | |
|--|-----------------------------------|--------------|----|--------------------|
| EWPP PremierPLS4HROnsite 48062 | 98508-48062 | \$ 21,278.00 | 6% | <i>\$20,151.33</i> |
| EWPP PremierPLS4HROnsite 5320-16P-4XE | 98508-5320- 16P-4XE | \$ 1,478.00 | 6% | <i>\$1,399.74</i> |
| EWPP PremierPLS4HROnsite 5320-16P-4XE-DC | 98508-5320- 16P-4XE-DC | \$ 1,577.00 | 6% | <i>\$1,493.50</i> |
| EWPP PremierPLS4HROnsite 5320-24P-8XE | 98508-5320- 24P-8XE | \$ 1,518.00 | 6% | <i>\$1,437.62</i> |
| EWPP PremierPLS4HROn 5320- 24T-24S-4XE-XT | 98508-5320- 24T-24S-4XE- XT | \$ 1,517.00 | 6% | <i>\$1,436.67</i> |
| EWPP PremierPLS4HROnsite 5320-24T-4X-XT | 98508-5320- 24T-4X-XT | \$ 1,190.00 | 6% | <i>\$1,126.99</i> |
| EWPP PremierPLS4HROnsite 5320-24T-8XE | 98508-5320- 24T-8XE | \$ 1,370.00 | 6% | <i>\$1,297.46</i> |
| EWPP PremierPLS4HROnsite 5320-48P-8XE | 98508-5320- 48P-8XE | \$ 1,929.00 | 6% | <i>\$1,826.86</i> |
| EWPP PremierPLS4HROnsite 5320-48T-8XE | 98508-5320- 48T-8XE | \$ 1,665.00 | 6% | <i>\$1,576.84</i> |
| EWPP PremPLS4HROnsite 5420F-16MW-32P-4XE | 98508-5420F- 16MW-32P- 4XE | \$ 2,819.00 | 6% | <i>\$2,669.73</i> |
| EWPP PremPLS4HROnsite 5420F-16W-32P-4XE | 98508-5420F- 16W-32P-4XE | \$ 2,742.00 | 6% | <i>\$2,596.81</i> |
| EWPP PremierPLS4HROnsite 5420F-24P-4XE | 98508-5420F- 24P-4XE | \$ 1,881.00 | 6% | <i>\$1,781.40</i> |
| EWPP PremierPLS4HROnsite 5420F-24S-4XE | 98508-5420F- 24S-4XE | \$ 1,949.00 | 6% | <i>\$1,845.80</i> |
| EWPP PremierPLS4HROnsite 5420F-24T-4XE | 98508-5420F- 24T-4XE | \$ 1,758.00 | 6% | <i>\$1,664.91</i> |
| EWPP PremierPLS4HROnsite 5420F-48P-4XE | 98508-5420F- 48P-4XE | \$ 2,267.00 | 6% | <i>\$2,146.96</i> |
| EWPP PremierPLS4HROnsite 5420F-48P-4XL | 98508-5420F- 48P-4XL | \$ 2,410.00 | 6% | <i>\$2,282.39</i> |
| EWPP PremierPLS4HROnsite 5420F-48T-4XE | 98508-5420F- 48T-4XE | \$ 1,967.00 | 6% | <i>\$1,862.85</i> |
| EWPP PremierPLS4HROnsit 5420F-8W-16P-4XE | 98508-5420F- 8W-16P-4XE | \$ 1,988.00 | 6% | <i>\$1,882.74</i> |
| EWPP PremPLS4HROnsite 5420M-16MW-32P-4YE | 98508-5420M- 16MW-32P- 4YE | \$ 3,020.00 | 6% | <i>\$2,860.09</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EWPP PremierPLS4HROnsite 5420M-24T-4YE | 98508-5420M- 24T-4YE | \$ 1,959.00 | 6% | <i>\$1,855.27</i> |
| EWPP PremierPLS4HROnsite 5420M-24W-4YE | 98508-5420M- 24W-4YE | \$ 1,753.00 | 6% | <i>\$1,660.18</i> |
| EWPP PremierPLS4HROnsite 5420M-48T-4YE | 98508-5420M- 48T-4YE | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPP PremierPLS4HROnsite 5420M-48W-4YE | 98508-5420M- 48W-4YE | \$ 2,411.00 | 6% | <i>\$2,283.34</i> |
| EWPP PREMIERPLUS 4HRONSITE 5520-12MW-36W | 98508-5520- 12MW-36W | \$ 3,201.00 | 6% | <i>\$3,031.51</i> |
| EWPP PREMIERPLUS 4HR ONSITE 5520-24T | 98508-5520- 24T | \$ 1,889.00 | 6% | <i>\$1,788.98</i> |
| EWPP PREMIERPL 4HR ON 5520-24T-ACDC-BASE | 98508-5520- 24T-ACDC- BASE | \$ 1,889.00 | 6% | <i>\$1,788.98</i> |
| EWPP PREMIERPLUS 4HR ONSIT 5520-24T-BASE | 98508-5520- 24T-BASE | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EWPP PREMIERPLUS 4HR ONSITE 5520-24W | 98508-5520- 24W | \$ 2,086.00 | 6% | <i>\$1,975.55</i> |
| EWPP PREMIERPLUS 4HR ONSITE 5520-24X | 98508-5520- 24X | \$ 3,234.00 | 6% | <i>\$3,062.76</i> |
| EWPP PREMIERPL 4HR ON 5520-24X-ACDC-BASE | 98508-5520- 24X-ACDC- BASE | \$ 3,234.00 | 6% | <i>\$3,062.76</i> |
| EWPP PREMIERPLUS 4HR ONSIT 5520-24X-BASE | 98508-5520- 24X-BASE | \$ 3,234.00 | 10% | <i>\$2,932.43</i> |
| EWPP PREMIERPLUS 4HR ONSITE 5520-48SE | 98508-5520- 48SE | \$ 3,127.00 | 6% | <i>\$2,961.43</i> |
| EWPP PREMIERPL 4H ON 5520-48SE-ACDC-BASE | 98508-5520- 48SE-ACDC- BASE | \$ 3,127.00 | 6% | <i>\$2,961.43</i> |
| EWPP PREMIERPLUS 4HR ONSI 5520-48SE-BASE | 98508-5520- 48SE-BASE | \$ 3,127.00 | 10% | <i>\$2,835.41</i> |
| EWPP PREMIERPLUS 4HR ONSITE 5520-48T | 98508-5520- 48T | \$ 2,461.00 | 6% | <i>\$2,330.69</i> |
| EWPP PREMIERPL 4HR ON 5520-48T-ACDC-BASE | 98508-5520- 48T-ACDC- BASE | \$ 2,461.00 | 6% | <i>\$2,330.69</i> |
| EWPP PREMIERPLUS 4HR ONSIT 5520-48T-BASE | 98508-5520- 48T-BASE | \$ 2,461.00 | 10% | <i>\$2,231.51</i> |
| EWPP PREMIERPLUS 4HR ONSITE 5520-48W | 98508-5520- 48W | \$ 2,797.00 | 6% | <i>\$2,648.90</i> |

| | | | | |
|---|----------------------------------|-------------|----|------------|
| EWPP PremierPLS4HROnsite 5720-24MW | 98508-5720- 24MW | \$ 2,906.00 | 6% | \$2,752.13 |
| EWPP PremierPLS4HROnsite 5720-24MXW | 98508-5720- 24MXW | \$ 3,178.00 | 6% | \$3,009.72 |
| EWPP PremierPLS4HROnsite 5720-48MW | 98508-5720- 48MW | \$ 2,764.00 | 6% | \$2,617.65 |
| EWPP PremierPLS4HROnsite 5720-48MXW | 98508-5720- 48MXW | \$ 4,007.00 | 6% | \$3,794.83 |
| EWPP PremierPLS4HROnsite 7520-48XT-6C | 98508-7520- 48XT-6C | \$ 5,329.00 | 6% | \$5,046.83 |
| EWPP PremierPLS4HROnsi 7520-48XT-6C-AC-F | 98508-7520- 48XT-6C-AC- F | \$ 5,329.00 | 6% | \$5,046.83 |
| EWPP PremierPLS4HROnsi 7520-48XT-6C-AC-R | 98508-7520- 48XT-6C-AC- R | \$ 5,329.00 | 6% | \$5,046.83 |
| EWPP PremierPLS4HROnsite 7520-48Y-8C | 98508-7520- 48Y-8C | \$ 4,981.00 | 6% | \$4,717.26 |
| EWPP PremierPLS4HROnsit 7520-48Y-8C-AC-F | 98508-7520- 48Y-8C-AC-F | \$ 4,981.00 | 6% | \$4,717.26 |
| EWPP PremierPLS4HROnsit 7520-48Y-8C-AC-R | 98508-7520- 48Y-8C-AC-R | \$ 4,981.00 | 6% | \$4,717.26 |
| EWPP PREMIERPLUS 4HR ONSIT 7520-48YE-8CE | 98508-7520- 48YE-8CE | \$ 5,761.00 | 6% | \$5,455.96 |
| EWPP PREMIERPL 4HRONS 7520-48YE-8CE-AC-F | 98508-7520- 48YE-8CE-AC- F | \$ 5,761.00 | 6% | \$5,455.96 |
| EWPP PREMIERPL 4HRONS 7520-48YE-8CE-AC-R | 98508-7520- 48YE-8CE-AC- R | \$ 5,761.00 | 6% | \$5,455.96 |
| EWPP PremierPLS4HROnsite 7720-32C | 98508-7720- 32C | \$ 6,145.00 | 6% | \$5,819.62 |
| EWPP PremierPLS4HROnsite 7720-32C-AC-F | 98508-7720- 32C-AC-F | \$ 6,145.00 | 6% | \$5,819.62 |
| EWPP PremierPLS4HROnsite 7720-32C-AC-R | 98508-7720- 32C-AC-R | \$ 6,145.00 | 6% | \$5,819.62 |
| EWPP PremierPLS4HROnsite 8520-48XT-6C | 98508-8520- 48XT-6C | \$ 5,368.00 | 6% | \$5,083.76 |
| EWPP PremPLS4HROnsite 8520- 48XT-6C-AC-F | 98508-8520- 48XT-6C-AC- F | \$ 5,369.00 | 6% | \$5,084.71 |

| | | | | |
|---|-------------------------|--------------|-----|-------------|
| EWPP PremPLS4HROnsite 8520-48XT-6C-AC-R | 98508-8520-48XT-6C-AC-R | \$ 5,369.00 | 6% | \$5,084.71 |
| EWPP PremPLS4HROnsite 8520-48XT-6C-DC-F | 98508-8520-48XT-6C-DC-F | \$ 5,368.00 | 6% | \$5,083.76 |
| EWPP PremPLS4HROnsite 8520-48XT-6C-DC-R | 98508-8520-48XT-6C-DC-R | \$ 5,368.00 | 6% | \$5,083.76 |
| EWPP PremierPLS4HROnsite 8520-48Y-8C | 98508-8520-48Y-8C | \$ 5,550.00 | 6% | \$5,256.13 |
| EWPP PremPLS4HROnsite 8520-48Y-8C-AC-F | 98508-8520-48Y-8C-AC-F | \$ 5,550.00 | 6% | \$5,256.13 |
| EWPP PremPLS4HROnsite 8520-48Y-8C-AC-R | 98508-8520-48Y-8C-AC-R | \$ 5,550.00 | 6% | \$5,256.13 |
| EWPP PremPLS4HROnsite 8520-48Y-8C-DC-F | 98508-8520-48Y-8C-DC-F | \$ 5,550.00 | 6% | \$5,256.13 |
| EWPP PremPLS4HROnsite 8520-48Y-8C-DC-R | 98508-8520-48Y-8C-DC-R | \$ 5,550.00 | 6% | \$5,256.13 |
| EWPP PremierPLS4HROnsite 8720-32C | 98508-8720-32C | \$ 6,039.00 | 6% | \$5,719.23 |
| EWPP PremierPLS4HROnsite 8720-32C-AC-F | 98508-8720-32C-AC-F | \$ 6,040.00 | 6% | \$5,720.18 |
| EWPP PremierPLS4HROnsite 8720-32C-AC-R | 98508-8720-32C-AC-R | \$ 6,040.00 | 6% | \$5,720.18 |
| EWPP PremierPLS4HROnsite 8720-32C-DC-F | 98508-8720-32C-DC-F | \$ 6,039.00 | 6% | \$5,719.23 |
| EWPP PremierPLS4HROnsite 8720-32C-DC-R | 98508-8720-32C-DC-R | \$ 6,039.00 | 6% | \$5,719.23 |
| EWPP PremierPLS4HROnsite 8806 | 98508-8806 | \$ 5,491.00 | 6% | \$5,200.25 |
| EWPP PremierPLS4HROnsite 8810 | 98508-8810 | \$ 11,481.00 | 6% | \$10,873.08 |
| EWPP PremierPLS4HROnsite 8820-40C | 98508-8820-40C | \$ 20,814.00 | 10% | \$18,873.09 |
| EWPP PremierPLS4HROnsite 8820-40C-AC-F | 98508-8820-40C-AC-F | \$ 20,814.00 | 10% | \$18,873.09 |
| EWPP PremierPLS4HROnsite 8820-40C-AC-R | 98508-8820-40C-AC-R | \$ 20,814.00 | 10% | \$18,873.09 |
| EWPP PremierPLS4HROnsite 8820-40C-DC-F | 98508-8820-40C-DC-F | \$ 20,814.00 | 10% | \$18,873.09 |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EWPP PremierPLS4HROnsite 8820-40C-DC-R | 98508-8820- 40C-DC-R | \$ 20,814.00 | 10% | <i>\$18,873.09</i> |
| EWPP PremierPLS4HROnsite 8820-80C | 98508-8820- 80C | \$ 37,083.00 | 10% | <i>\$33,625.01</i> |
| EWPP PremierPLS4HROnsite 8820-80C-AC-F | 98508-8820- 80C-AC-F | \$ 37,083.00 | 10% | <i>\$33,625.01</i> |
| EWPP PremierPLS4HROnsite 8820-80C-AC-R | 98508-8820- 80C-AC-R | \$ 37,083.00 | 10% | <i>\$33,625.01</i> |
| EWPP PremierPLS4HROnsite 8820-80C-DC-F | 98508-8820- 80C-DC-F | \$ 37,083.00 | 10% | <i>\$33,625.01</i> |
| EWPP PremierPLS4HROnsite 8820-80C-DC-R | 98508-8820- 80C-DC-R | \$ 37,083.00 | 10% | <i>\$33,625.01</i> |
| EWPP PremierPLS4HROnsite 9920-16C | 98508-9920- 16C | \$ 16,669.00 | 6% | <i>\$15,786.38</i> |
| EWPP PremierPLS4HROnsite 9920-4D | 98508-9920-4D | \$ 16,669.00 | 6% | <i>\$15,786.38</i> |
| EWPP PremierPLS4HROnsite 9920-NPB-8 | 98508-9920- NPB-8 | \$ 25,230.00 | 6% | <i>\$23,894.07</i> |
| EWPP PremierPLS 4HROnsite AH-AP-1130-AC- | 98508-AH-AP- 1130-AC-CE | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWPP PremierPLS 4HROnsite AH-AP-1130-AC- | 98508-AH-AP- 1130-AC-FCC | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWPP PremierPLS 4HROnsite AH-AP-1130-AC- | 98508-AH-AP- 1130-AC-W | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWPP PremierPLS 4HROnsite AH-AP-122-AC-C | 98508-AH-AP- 122-AC-CAN | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HROnsite AH-AP-122-AC-C | 98508-AH-AP- 122-AC-CE | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HROnsite AH-AP-122-AC-F | 98508-AH-AP- 122-AC-FCC | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HROnsite AH-AP-122-AC-W | 98508-AH-AP- 122-AC-W | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HROnsite AH-AP-130-AC-C | 98508-AH-AP- 130-AC-CE | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HROnsite AH-AP-130-AC-F | 98508-AH-AP- 130-AC-FCC | \$ 380.00 | 6% | <i>\$359.88</i> |
| EWPP PremierPLS 4HROnsite AH-AP-130-AC-W | 98508-AH-AP- 130-AC-W | \$ 415.00 | 6% | <i>\$393.03</i> |
| EWPP PremierPLS 4HROnsite AH-AP-150W-AC- | 98508-AH-AP- 150W-AC- CAN | \$ 415.00 | 6% | <i>\$393.03</i> |

| | | | | |
|---|---------------------------------|-----------|----|----------|
| EWPP PremierPLS 4HROnsite AH-AP-150W-AC- | 98508-AH-AP- 150W-AC-CE | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-150W-AC- | 98508-AH-AP- 150W-AC-FCC | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-150W-AC- | 98508-AH-AP- 150W-AC-W | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-230-AC-C | 98508-AH-AP- 230-AC-CE | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-230-AC-F | 98508-AH-AP- 230-AC-FCC | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-230-AC-W | 98508-AH-AP- 230-AC-W | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-250-AC-C | 98508-AH-AP- 250-AC-CAN | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-250-AC-C | 98508-AH-AP- 250-AC-CE | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-250-AC-F | 98508-AH-AP- 250-AC-FCC | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-250-AC-W | 98508-AH-AP- 250-AC-W | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS 4HROnsite AH-AP-630-AX-C | 98508-AH-AP- 630-AX-CAN | \$ 471.00 | 6% | \$446.06 |
| EWPP PremierPLS 4HROnsite AH-AP-630-AX-C | 98508-AH-AP- 630-AX-CE | \$ 471.00 | 6% | \$446.06 |
| EWPP PremierPLS 4HROnsite AH-AP-630-AX-F | 98508-AH-AP- 630-AX-FCC | \$ 471.00 | 6% | \$446.06 |
| EWPP PremierPLS 4HROnsite AH-AP-630-AX-W | 98508-AH-AP- 630-AX-W | \$ 471.00 | 6% | \$446.06 |
| EWPP PremierPLS 4HROnsite AH-AP-650-AX-C | 98508-AH-AP- 650-AX-CAN | \$ 412.00 | 6% | \$390.18 |
| EWPP PremierPLS 4HROnsite AH-AP-650-AX-C | 98508-AH-AP- 650-AX-CE | \$ 412.00 | 6% | \$390.18 |
| EWPP PremierPLS 4HROnsite AH-AP-650-AX-F | 98508-AH-AP- 650-AX-FCC | \$ 412.00 | 6% | \$390.18 |
| EWPP PremierPLS 4HROnsite AH-AP-650-AX-W | 98508-AH-AP- 650-AX-W | \$ 412.00 | 6% | \$390.18 |
| EWPP PremierPLS 4HROnsite AH-AP-650X-AX- | 98508-AH-AP- 650X-AX- CAN | \$ 412.00 | 6% | \$390.18 |
| EWPP PremierPLS 4HROnsite AH-AP-650X-AX- | 98508-AH-AP- 650X-AX-CE | \$ 412.00 | 6% | \$390.18 |

| | | | | |
|---|-----------------------------|-------------|----|------------|
| EWPP PremierPLS 4HROnsite AH-AP-650X-AX- | 98508-AH-AP- 650X-AX-FCC | \$ 412.00 | 6% | \$390.18 |
| EWPP PremierPLS 4HROnsite AH-AP-650X-AX- | 98508-AH-AP- 650X-AX-W | \$ 412.00 | 6% | \$390.18 |
| EWPP PremierPLS 4HROnsite AH-ATOM-CAN | 98508-AH- ATOM-CAN | \$ 429.00 | 6% | \$406.28 |
| EWPP PremierPLS 4HROnsite AH-ATOM-CE-EU | 98508-AH- ATOM-CE-EU | \$ 450.00 | 6% | \$426.17 |
| EWPP PremierPLS 4HROnsite AH-ATOM-CE-UK | 98508-AH- ATOM-CE-UK | \$ 450.00 | 6% | \$426.17 |
| EWPP PremierPLS 4HROnsite AH-ATOM-FCC | 98508-AH- ATOM-FCC | \$ 428.00 | 6% | \$405.34 |
| EWPP PremierPLS 4HROnsite AH-ATOM-W | 98508-AH- ATOM-W | \$ 429.00 | 6% | \$406.28 |
| EWPP PremierPLS 4HROnsite AH-ATOM-W-EU | 98508-AH- ATOM-W-EU | \$ 450.00 | 6% | \$426.17 |
| EWPP PremierPLS 4HROnsite AH-ATOM-W-UK | 98508-AH- ATOM-W-UK | \$ 450.00 | 6% | \$426.17 |
| EWPP PremierPLS 4HROnsite AH-SR-2208P-AU | 98508-AH-SR- 2208P-AU | \$ 1,183.00 | 6% | \$1,120.36 |
| EWPP PremierPLS 4HROnsite AH-SR-2208P-EU | 98508-AH-SR- 2208P-EU | \$ 1,183.00 | 6% | \$1,120.36 |
| EWPP PremierPLS 4HROnsite AH-SR-2208P-NA | 98508-AH-SR- 2208P-NA | \$ 1,183.00 | 6% | \$1,120.36 |
| EWPP PremierPLS 4HROnsite AH-SR-2208P-UK | 98508-AH-SR- 2208P-UK | \$ 1,183.00 | 6% | \$1,120.36 |
| EWPP PremierPLS 4HROnsite AH-SR-2224P-AU | 98508-AH-SR- 2224P-AU | \$ 1,236.00 | 6% | \$1,170.55 |
| EWPP PremierPLS 4HROnsite AH-SR-2224P-EU | 98508-AH-SR- 2224P-EU | \$ 1,236.00 | 6% | \$1,170.55 |
| EWPP PremierPLS 4HROnsite AH-SR-2224P-NA | 98508-AH-SR- 2224P-NA | \$ 1,236.00 | 6% | \$1,170.55 |
| EWPP PremierPLS 4HROnsite AH-SR-2224P-UK | 98508-AH-SR- 2224P-UK | \$ 1,236.00 | 6% | \$1,170.55 |
| EWPP PremierPLS 4HROnsite AH-SR-2324P-AU | 98508-AH-SR- 2324P-AU | \$ 1,296.00 | 6% | \$1,227.38 |
| EWPP PremierPLS 4HROnsite AH-SR-2324P-EU | 98508-AH-SR- 2324P-EU | \$ 1,296.00 | 6% | \$1,227.38 |
| EWPP PremierPLS 4HROnsite AH-SR-2324P-NA | 98508-AH-SR- 2324P-NA | \$ 1,296.00 | 6% | \$1,227.38 |

| | | | | |
|---|---------------------------------|-------------|----|-------------------|
| EWPP PremierPLS 4HROnsite AH-SR-2324P-UK | 98508-AH-SR- 2324P-UK | \$ 1,296.00 | 6% | <i>\$1,227.38</i> |
| EWPP PremierPLS 4HROnsite AH-SR-2348P-AU | 98508-AH-SR- 2348P-AU | \$ 1,499.00 | 6% | <i>\$1,419.63</i> |
| EWPP PremierPLS 4HROnsite AH-SR-2348P-EU | 98508-AH-SR- 2348P-EU | \$ 1,499.00 | 6% | <i>\$1,419.63</i> |
| EWPP PremierPLS 4HROnsite AH-SR-2348P-NA | 98508-AH-SR- 2348P-NA | \$ 1,499.00 | 6% | <i>\$1,419.63</i> |
| EWPP PremierPLS 4HROnsite AH-SR-2348P-UK | 98508-AH-SR- 2348P-UK | \$ 1,499.00 | 6% | <i>\$1,419.63</i> |
| EWPP PremierPLS 4HROnsite AH-XR200P-AU | 98508-AH- XR200P-AU | \$ 1,183.00 | 6% | <i>\$1,120.36</i> |
| EWPP PremierPLS 4HROnsite AH-XR200P-EU | 98508-AH- XR200P-EU | \$ 1,183.00 | 6% | <i>\$1,120.36</i> |
| EWPP PremierPLS 4HROnsite AH-XR200P-UK | 98508-AH- XR200P-UK | \$ 1,183.00 | 6% | <i>\$1,120.36</i> |
| EWPP PremierPLS 4HROnsite AH-XR200P-US | 98508-AH- XR200P-US | \$ 1,183.00 | 6% | <i>\$1,120.36</i> |
| EWPP PremierPLS 4HROnsite AH-XR600P | 98508-AH- XR600P | \$ 1,191.00 | 6% | <i>\$1,127.94</i> |
| EWPP PremierPLS 4HROnsite AH-XR600P-AU | 98508-AH- XR600P-AU | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWPP PremierPLS 4HROnsite AH-XR600P-EU | 98508-AH- XR600P-EU | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWPP PremierPLS 4HROnsite AH-XR600P-KR | 98508-AH- XR600P-KR | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWPP PremierPLS 4HROnsite AH-XR600P-UK | 98508-AH- XR600P-UK | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWPP PremierPLS 4HROnsite AH-XR600P-US | 98508-AH- XR600P-US | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWPP PremierPLS4HROnsite AP-8533-IL | 98508-AP- 8533-68SB30- IL | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWPP PremierPLS4HROnsite AP3000-IL | 98508-AP3000- IL | \$ 303.39 | 6% | <i>\$287.33</i> |
| EWPP PremierPLS4HROnsite AP3000-TN | 98508-AP3000- TN | \$ 303.39 | 6% | <i>\$287.33</i> |
| EWPP PremierPLS4HROnsite AP3000-WW | 98508-AP3000- WW | \$ 303.39 | 6% | <i>\$287.33</i> |
| EWPP PremierPLS4HROnsite AP3000X-WW | 98508- AP3000X-WW | \$ 331.77 | 6% | <i>\$314.20</i> |

| | | | | |
|---|---------------------------|-----------|-----|-----------------|
| EWPP PremierPLS4HROnsite AP302W-CAN | 98508- AP302W-CAN | \$ 398.00 | 6% | <i>\$376.93</i> |
| EWPP PremierPLS4HROnsite AP302W-EG | 98508- AP302W-EG | \$ 302.00 | 10% | <i>\$273.84</i> |
| EWPP PremierPLS4HROnsite AP302W-FCC | 98508- AP302W-FCC | \$ 398.00 | 6% | <i>\$376.93</i> |
| EWPP PremierPLS4HROnsite AP302W-WR | 98508- AP302W-WR | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPP PremierPLS 4HROnsite AP305C-1-CAN | 98508-AP305C- 1-CAN | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS 4HROnsite AP305C-1-EG | 98508-AP305C- 1-EG | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS 4HROnsite AP305C-FCC | 98508-AP305C- 1-FCC | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS 4HROnsite AP305C-1-IL | 98508-AP305C- 1-IL | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS 4HROnsite AP305C-1-WR | 98508-AP305C- 1-WR | \$ 406.00 | 6% | <i>\$384.50</i> |
| EWPP PremierPLS 4HROnsite AP305C-CAN | 98508-AP305C- CAN | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305C-EG | 98508-AP305C- EG | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305C-FCC | 98508-AP305C- FCC | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305C-IL | 98508-AP305C- IL | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305C-WR | 98508-AP305C- WR | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305CX-CAN | 98508- AP305CX- CAN | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305CX-FCC | 98508- AP305CX- FCC | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305CX-IL | 98508- AP305CX-IL | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS 4HROnsite AP305CX-WR | 98508- AP305CX-WR | \$ 437.00 | 6% | <i>\$413.86</i> |
| EWPP PremierPLS4HROnsite AP310e-1-WR | 98508-AP310e- 1-WR | \$ 382.00 | 10% | <i>\$346.38</i> |

| | | | | |
|---|------------------------|-----------|-----|----------|
| EWPP PremierPLS4HROnsite AP310e-CAN | 98508-AP310e- CAN | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP310e-FCC | 98508-AP310e- FCC | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP310e-IL | 98508-AP310e- IL | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP310e-WR | 98508-AP310e- WR | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP310i-1-WR | 98508-AP310i- 1-WR | \$ 382.00 | 10% | \$346.38 |
| EWPP PremierPLS4HROnsite AP310i-CAN | 98508-AP310i- CAN | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP310i-FCC | 98508-AP310i- FCC | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP310i-IL | 98508-AP310i- IL | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP310i-WR | 98508-AP310i- WR | \$ 400.00 | 6% | \$378.82 |
| EWPP PremierPLS4HROnsite AP360e-CAN | 98508-AP360e- CAN | \$ 436.00 | 6% | \$412.91 |
| EWPP PremierPLS4HROnsite AP360e-FCC | 98508-AP360e- FCC | \$ 436.00 | 6% | \$412.91 |
| EWPP PremierPLS4HROnsite AP360e-IL | 98508-AP360e- IL | \$ 436.00 | 6% | \$412.91 |
| EWPP PremierPLS4HROnsite AP360e-WR | 98508-AP360e- WR | \$ 436.00 | 6% | \$412.91 |
| EWPP PremierPLS4HROnsite AP360i-CAN | 98508-AP360i- CAN | \$ 436.00 | 6% | \$412.91 |
| EWPP PremierPLS4HROnsite AP360i-FCC | 98508-AP360i- FCC | \$ 436.00 | 6% | \$412.91 |
| EWPP PremierPLS4HROnsite AP360i-WR | 98508-AP360i- WR | \$ 436.00 | 6% | \$412.91 |
| EWPP PremierPLS4HROnsite AP4000-WW | 98508-AP4000- 1-WW | \$ 393.00 | 6% | \$372.19 |
| EWPP PremierPLS4HROnsite AP4000-IL | 98508-AP4000- IL | \$ 393.00 | 6% | \$372.19 |
| EWPP PremierPLS4HROnsite AP4000-WW | 98508-AP4000- WW | \$ 393.00 | 6% | \$372.19 |
| EWPP PremierPLS 4HROnsite AP410C-1-CAN | 98508-AP410C- 1-CAN | \$ 402.00 | 6% | \$380.71 |

| | | | | |
|---|------------------------|-----------|-----|-----------------|
| EWPP PremierPLS 4HROnsite AP410C-1-EG | 98508-AP410C- 1-EG | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS 4HROnsite AP410C-1-FCC | 98508-AP410C- 1-FCC | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS 4HROnsite AP410C-1-IL | 98508-AP410C- 1-IL | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS 4HROnsite AP410C-1-WR | 98508-AP410C- 1-WR | \$ 402.00 | 6% | <i>\$380.71</i> |
| EWPP PremierPLS 4HROnsite AP410C-CAN | 98508-AP410C- CAN | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS 4HROnsite AP410C-EG | 98508-AP410C- EG | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS 4HROnsite AP410C-FCC | 98508-AP410C- FCC | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS 4HROnsite AP410C-IL | 98508-AP410C- IL | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS 4HROnsite AP410C-WR | 98508-AP410C- WR | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS4HROnsite AP410e-CAN | 98508-AP410e- CAN | \$ 460.00 | 6% | <i>\$435.64</i> |
| EWPP PremierPLS4HROnsite AP410e-FCC | 98508-AP410e- FCC | \$ 460.00 | 6% | <i>\$435.64</i> |
| EWPP PremierPLS4HROnsite AP410e-WR | 98508-AP410e- WR | \$ 460.00 | 6% | <i>\$435.64</i> |
| EWPP PremierPLS4HROnsite AP410i-1-FCC | 98508-AP410i- 1-FCC | \$ 439.00 | 10% | <i>\$398.06</i> |
| EWPP PremierPLS4HROnsite AP410i-1-WR | 98508-AP410i- 1-WR | \$ 439.00 | 10% | <i>\$398.06</i> |
| EWPP PremierPLS4HROnsite AP410i-CAN | 98508-AP410i- CAN | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWPP PremierPLS4HROnsite AP410i-FCC | 98508-AP410i- FCC | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWPP PremierPLS4HROnsite AP410i-IL | 98508-AP410i- IL | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWPP PremierPLS4HROnsite AP410i-WR | 98508-AP410i- WR | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWPP PremierPLS 4HROnsite AP460C-CAN | 98508-AP460C- CAN | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460C-EG | 98508-AP460C- EG | \$ 481.00 | 6% | <i>\$455.53</i> |

| | | | | |
|--|-----------------------------|-----------|-----|-----------------|
| EWPP PremierPLS 4HROnsite AP460C-FCC | 98508-AP460C- FCC | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460C-IL | 98508-AP460C- IL | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460C-WR | 98508-AP460C- WR | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS4HROnsite AP460e-CAN | 98508-AP460e- CAN | \$ 485.00 | 6% | <i>\$459.32</i> |
| EWPP PremierPLS4HROnsite AP460e-FCC | 98508-AP460e- FCC | \$ 485.00 | 6% | <i>\$459.32</i> |
| EWPP PremierPLS4HROnsite AP460e-WR | 98508-AP460e- WR | \$ 462.00 | 6% | <i>\$437.54</i> |
| EWPP PremierPLS4HROnsite AP460i-CAN | 98508-AP460i- CAN | \$ 462.00 | 6% | <i>\$437.54</i> |
| EWPP PremierPLS4HROnsite AP460i-FCC | 98508-AP460i- FCC | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWPP PremierPLS4HROnsite AP460i-IL | 98508-AP460i- IL | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWPP PremierPLS4HROnsite AP460i-WR | 98508-AP460i- WR | \$ 463.00 | 6% | <i>\$438.48</i> |
| EWPP PremierPLS 4HROnsite AP460S12C-CAN | 98508- AP460S12C- CAN | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460S12C-FCC | 98508- AP460S12C- FCC | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460S12C-WR | 98508- AP460S12C- WR | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460S6C-CAN | 98508- AP460S6C- CAN | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460S6C-FCC | 98508- AP460S6C- FCC | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS 4HROnsite AP460S6C-WR | 98508- AP460S6C- WR | \$ 481.00 | 6% | <i>\$455.53</i> |
| EWPP PremierPLS4HROnsite AP5010-IL | 98508-AP5010- IL | \$ 452.00 | 6% | <i>\$428.07</i> |
| EWPP PremierPLS4HROnsite AP5010-WW | 98508-AP5010- WW | \$ 452.00 | 10% | <i>\$409.85</i> |

| | | | | |
|--|---------------------------|-----------|----|-----------------|
| EWPP PremierPLS4HROnsite AP5020-WW | 98508-AP5020- WW | \$ 473.53 | 6% | <i>\$448.46</i> |
| EWPP PremierPLS4HROnsite AP5050D-WW | 98508- AP5050D-WW | \$ 725.00 | 6% | <i>\$686.61</i> |
| EWPP PremierPLS4HROnsite AP5050U-WW | 98508- AP5050U-WW | \$ 609.00 | 6% | <i>\$576.75</i> |
| EWPP PremierPLS4HROnsite AP505i-FCC | 98508-AP505i- FCC | \$ 459.00 | 6% | <i>\$434.70</i> |
| EWPP PremierPLS4HROnsite AP505i-FCC-TAA | 98508-AP505i- FCC-TAA | \$ 459.00 | 6% | <i>\$434.70</i> |
| EWPP PremierPLS4HROnsite AP505i-WR | 98508-AP505i- WR | \$ 482.00 | 6% | <i>\$456.48</i> |
| EWPP PremierPLS 4HROnsite AP510C-CAN | 98508-AP510C- CAN | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS 4HROnsite AP510C-CE | 98508-AP510C- CE | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS 4HROnsite AP510C-FCC | 98508-AP510C- FCC | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS 4HROnsite AP510C-W | 98508-AP510C- W | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS4HROnsite AP510C-WW | 98508-AP510C- WW | \$ 532.00 | 6% | <i>\$503.83</i> |
| EWPP PremierPLS 4HROnsite AP510CX-CAN | 98508- AP510CX- CAN | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS 4HROnsite AP510CX-CE | 98508- AP510CX- CE | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS 4HROnsite AP510CX-FCC | 98508- AP510CX- FCC | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS 4HROnsite AP510CX-W | 98508- AP510CX- W | \$ 401.00 | 6% | <i>\$379.77</i> |
| EWPP PremierPLS4HROnsite AP510CX-WW | 98508- AP510CX- WW | \$ 532.00 | 6% | <i>\$503.83</i> |
| EWPP PremierPLS4HROnsite AP510e-FCC | 98508-AP510e- FCC | \$ 532.00 | 6% | <i>\$503.83</i> |
| EWPP PremierPLS4HROnsite AP510e-FCC-TAA | 98508-AP510e- FCC-TAA | \$ 532.00 | 6% | <i>\$503.83</i> |
| EWPP PremierPLS4HROnsite AP510e-WR | 98508-AP510e- WR | \$ 507.00 | 6% | <i>\$480.15</i> |

| | | | | |
|--|--------------------------|--------------|-----|--------------------|
| EWPP PremierPLS4HROnsite AP510i-1-FCC | 98508-AP510i- 1-FCC | \$ 480.00 | 10% | <i>\$435.24</i> |
| EWPP PremierPLS4HROnsite AP510i-1-WR | 98508-AP510i- 1-WR | \$ 480.00 | 10% | <i>\$435.24</i> |
| EWPP PremierPLS4HROnsite AP510i-FCC | 98508-AP510i- FCC | \$ 503.00 | 6% | <i>\$476.37</i> |
| EWPP PremierPLS4HROnsite AP510i-FCC-TAA | 98508-AP510i- FCC-TAA | \$ 503.00 | 6% | <i>\$476.37</i> |
| EWPP PremierPLS4HROnsite AP510i-WR | 98508-AP510i- WR | \$ 503.00 | 6% | <i>\$476.37</i> |
| EWPP PremierPLS4HROnsite AP560h-FCC | 98508-AP560h- FCC | \$ 812.00 | 6% | <i>\$769.00</i> |
| EWPP PremierPLS4HROnsite AP560h-WR | 98508-AP560h- WR | \$ 812.00 | 6% | <i>\$769.00</i> |
| EWPP PremierPLS4HROnsite AP560i-FCC | 98508-AP560i- FCC | \$ 672.00 | 6% | <i>\$636.42</i> |
| EWPP PremierPLS4HROnsite AP560i-WR | 98508-AP560i- WR | \$ 641.00 | 6% | <i>\$607.06</i> |
| EWPP PremierPLS4HROnsite AP560m-FCC | 98508-AP560m- FCC | \$ 672.00 | 6% | <i>\$636.42</i> |
| EWPP PremierPLS4HROnsite AP560t-FCC | 98508-AP560t- FCC | \$ 812.00 | 6% | <i>\$769.00</i> |
| EWPP PremierPLS4HROnsite AP560u-FCC | 98508-AP560u- FCC | \$ 625.00 | 6% | <i>\$591.91</i> |
| EWPP PremierPLS4HROnsite E2122 | 98508-E2122 | \$ 10,538.00 | 6% | <i>\$9,980.01</i> |
| EWPP PremierPLS4HROnsite E2122-1 | 98508-E2122-1 | \$ 10,036.00 | 6% | <i>\$9,504.59</i> |
| EWPP PremierPLS4HROnsite E3120-1 | 98508-E3120-1 | \$ 14,835.00 | 6% | <i>\$14,049.49</i> |
| EWPP PremierPLS4HROnsite E3125 | 98508-E3125 | \$ 15,948.00 | 6% | <i>\$15,103.55</i> |
| EWPPPremierPLS4HROnsite H30131 | 98508-H30131 | \$ 3,478.00 | 6% | <i>\$3,293.84</i> |
| EWPPPremierPLS4HROnsite H30132 | 98508-H30132 | \$ 3,410.00 | 6% | <i>\$3,229.44</i> |
| EWPPPremierPLS4HROnsite H30133 | 98508-H30133 | \$ 7,110.00 | 6% | <i>\$6,733.53</i> |
| EWPPPremierPLS4HROnsite H30134 | 98508-H30134 | \$ 8,696.00 | 6% | <i>\$8,235.55</i> |
| EWPPPremierPLS4HROnsite H30135 | 98508-H30135 | \$ 7,248.00 | 6% | <i>\$6,864.22</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| EWPPPremierPLS4HROnsite H30136 | 98508-H30136 | \$ 8,696.00 | 6% | \$8,235.55 |
| EWPPPremierPLS4HROnsite H30184 | 98508-H30184 | \$ 1,293.00 | 6% | \$1,224.54 |
| EWPPPremierPLS4HROnsite H30185 | 98508-H30185 | \$ 1,758.00 | 6% | \$1,664.91 |
| EWPPPremierPLS4HROnsite H30186 | 98508-H30186 | \$ 1,492.00 | 6% | \$1,413.00 |
| EWPPPremierPLS4HROnsite H30187 | 98508-H30187 | \$ 1,381.00 | 6% | \$1,307.88 |
| EWPPPremierPLS4HROnsite H30188 | 98508-H30188 | \$ 1,492.00 | 6% | \$1,413.00 |
| EWPPPremierPLS4HROnsite H30189 | 98508-H30189 | \$ 1,492.00 | 6% | \$1,413.00 |
| EWPPPremierPLS4HROnsite H30190 | 98508-H30190 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30214 | 98508-H30214 | \$ 1,562.00 | 6% | \$1,479.29 |
| EWPPPremierPLS4HROnsite H30215 | 98508-H30215 | \$ 1,562.00 | 6% | \$1,479.29 |
| EWPPPremierPLS4HROnsite H30216 | 98508-H30216 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30217 | 98508-H30217 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30218 | 98508-H30218 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30219 | 98508-H30219 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30220 | 98508-H30220 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30221 | 98508-H30221 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30222 | 98508-H30222 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30223 | 98508-H30223 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30224 | 98508-H30224 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30225 | 98508-H30225 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30226 | 98508-H30226 | \$ 2,179.00 | 6% | \$2,063.62 |

| | | | | |
|-----------------------------------|--------------|-------------|----|------------|
| EWPPPremierPLS4HROnsite H30227 | 98508-H30227 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30228 | 98508-H30228 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30229 | 98508-H30229 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30267 | 98508-H30267 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30268 | 98508-H30268 | \$ 1,841.00 | 6% | \$1,743.52 |
| EWPPPremierPLS4HROnsite H30269 | 98508-H30269 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30270 | 98508-H30270 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30271 | 98508-H30271 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30272 | 98508-H30272 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30273 | 98508-H30273 | \$ 2,511.00 | 6% | \$2,378.04 |
| EWPPPremierPLS4HROnsite H30274 | 98508-H30274 | \$ 2,511.00 | 6% | \$2,378.04 |
| EWPPPremierPLS4HROnsite H30275 | 98508-H30275 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30276 | 98508-H30276 | \$ 2,179.00 | 6% | \$2,063.62 |
| EWPPPremierPLS4HROnsite H30277 | 98508-H30277 | \$ 2,511.00 | 6% | \$2,378.04 |
| EWPPPremierPLS4HROnsite H30278 | 98508-H30278 | \$ 2,627.00 | 6% | \$2,487.90 |
| EWPPPremierPLS4HROnsite H30279 | 98508-H30279 | \$ 2,511.00 | 6% | \$2,378.04 |
| EWPPPremierPLS4HROnsite H30280 | 98508-H30280 | \$ 2,511.00 | 6% | \$2,378.04 |
| EWPPPremierPLS4HROnsite H30281 | 98508-H30281 | \$ 2,511.00 | 6% | \$2,378.04 |
| EWPPPremierPLS4HROnsite H30282 | 98508-H30282 | \$ 2,511.00 | 6% | \$2,378.04 |
| EWPPPremierPLS4HROnsite H30283 | 98508-H30283 | \$ 1,981.00 | 6% | \$1,876.11 |
| EWPPPremierPLS4HROnsite H30284 | 98508-H30284 | \$ 2,179.00 | 6% | \$2,063.62 |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLS4HROnsite H30296 | 98508-H30296 | \$ 1,562.00 | 6% | <i>\$1,479.29</i> |
| EWPPPremierPLS4HROnsite H30297 | 98508-H30297 | \$ 1,562.00 | 6% | <i>\$1,479.29</i> |
| EWPPPremierPLS4HROnsite H30298 | 98508-H30298 | \$ 1,562.00 | 6% | <i>\$1,479.29</i> |
| EWPPPremierPLS4HROnsite H30299 | 98508-H30299 | \$ 1,562.00 | 6% | <i>\$1,479.29</i> |
| EWPPPremierPLS4HROnsite H30381 | 98508-H30381 | \$ 2,942.00 | 6% | <i>\$2,786.22</i> |
| EWPPPremierPLS4HROnsite H30384 | 98508-H30384 | \$ 2,781.00 | 6% | <i>\$2,633.75</i> |
| EWPPPremierPLS4HROnsite H30391 | 98508-H30391 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPPPremierPLS4HROnsite H30392 | 98508-H30392 | \$ 1,986.00 | 6% | <i>\$1,880.84</i> |
| EWPPPremierPLS4HROnsite H30393 | 98508-H30393 | \$ 1,116.00 | 6% | <i>\$1,056.91</i> |
| EWPPPremierPLS4HROnsite H30394 | 98508-H30394 | \$ 3,444.00 | 6% | <i>\$3,261.64</i> |
| EWPPPremierPLS4HROnsite H30395 | 98508-H30395 | \$ 4,027.00 | 6% | <i>\$3,813.77</i> |
| EWPPPremierPLS4HROnsite H30396 | 98508-H30396 | \$ 3,700.00 | 6% | <i>\$3,504.09</i> |
| EWPPPremierPLS4HROnsite H30397 | 98508-H30397 | \$ 4,313.00 | 6% | <i>\$4,084.63</i> |
| EWPPPremierPLS4HROnsite H30398 | 98508-H30398 | \$ 1,138.00 | 6% | <i>\$1,077.74</i> |
| EWPPPremierPLS4HROnsite H30400 | 98508-H30400 | \$ 814.00 | 6% | <i>\$770.90</i> |
| EWPPPremierPLS4HROnsite H30401 | 98508-H30401 | \$ 978.00 | 6% | <i>\$926.21</i> |
| EWPPPremierPLS4HROnsite H30402 | 98508-H30402 | \$ 1,010.00 | 6% | <i>\$956.52</i> |
| EWPPPremierPLS4HROnsite H30403 | 98508-H30403 | \$ 1,299.00 | 6% | <i>\$1,230.22</i> |
| EWPPPremierPLS4HROnsite H30480 | 98508-H30480 | \$ 3,103.00 | 6% | <i>\$2,938.70</i> |
| EWPPPremierPLS4HROnsite H30495 | 98508-H30495 | \$ 4,434.00 | 6% | <i>\$4,199.22</i> |
| EWPPPremierPLS4HROnsite H30496 | 98508-H30496 | \$ 4,348.00 | 6% | <i>\$4,117.77</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H30497 | 98508-H30497 | \$ 5,462.00 | 6% | <i>\$5,172.79</i> |
| EWPPPremierPLS4HROnsite H30498 | 98508-H30498 | \$ 5,359.00 | 6% | <i>\$5,075.24</i> |
| EWPPPremierPLS4HROnsite H30499 | 98508-H30499 | \$ 1,551.00 | 6% | <i>\$1,468.87</i> |
| EWPPPremierPLS4HROnsite H30501 | 98508-H30501 | \$ 5,359.00 | 6% | <i>\$5,075.24</i> |
| EWPPPremierPLS4HROnsite H30502 | 98508-H30502 | \$ 7,122.00 | 6% | <i>\$6,744.89</i> |
| EWPPPremierPLS4HROnsite H30503 | 98508-H30503 | \$ 1,551.00 | 6% | <i>\$1,468.87</i> |
| EWPPPremierPLS4HROnsite H30505 | 98508-H30505 | \$ 8,047.00 | 6% | <i>\$7,620.91</i> |
| EWPPPremierPLS4HROnsite H30506 | 98508-H30506 | \$ 10,191.00 | 6% | <i>\$9,651.39</i> |
| EWPPPremierPLS4HROnsite H30509 | 98508-H30509 | \$ 7,122.00 | 6% | <i>\$6,744.89</i> |
| EWPPPremierPLS4HROnsite H30510 | 98508-H30510 | \$ 8,047.00 | 6% | <i>\$7,620.91</i> |
| EWPPPremierPLS4HROnsite H30511 | 98508-H30511 | \$ 10,191.00 | 6% | <i>\$9,651.39</i> |
| EWPPPremierPLS4HROnsite H30512 | 98508-H30512 | \$ 1,551.00 | 6% | <i>\$1,468.87</i> |
| EWPPPremierPLS4HROnsite H30513 | 98508-H30513 | \$ 2,321.00 | 6% | <i>\$2,198.10</i> |
| EWPPPremierPLS4HROnsite H30525 | 98508-H30525 | \$ 8,532.00 | 6% | <i>\$8,080.23</i> |
| EWPPPremierPLS4HROnsite H30526 | 98508-H30526 | \$ 6,388.00 | 6% | <i>\$6,049.76</i> |
| EWPPPremierPLS4HROnsite H30528 | 98508-H30528 | \$ 9,831.00 | 6% | <i>\$9,310.45</i> |
| EWPPPremierPLS4HROnsite H30531 | 98508-H30531 | \$ 13,818.00 | 6% | <i>\$13,086.34</i> |
| EWPPPremierPLS4HROnsite H30532 | 98508-H30532 | \$ 13,818.00 | 6% | <i>\$13,086.34</i> |
| EWPPPremierPLS4HROnsite H30534 | 98508-H30534 | \$ 14,088.00 | 6% | <i>\$13,342.04</i> |
| EWPPPremierPLS4HROnsite H30535 | 98508-H30535 | \$ 14,987.00 | 6% | <i>\$14,193.44</i> |
| EWPPPremierPLS4HROnsite H30536 | 98508-H30536 | \$ 13,818.00 | 6% | <i>\$13,086.34</i> |

| | | | | |
|------------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROn-site H30537 | 98508-H30537 | \$ 14,987.00 | 6% | <i>\$14,193.44</i> |
| EWPPPremierPLS4HROn-site H30538 | 98508-H30538 | \$ 8,532.00 | 6% | <i>\$8,080.23</i> |
| EWPPPremierPLS4HROn-site H30539 | 98508-H30539 | \$ 16,004.00 | 6% | <i>\$15,156.59</i> |
| EWPPPremierPLS4HROn-site H30540 | 98508-H30540 | \$ 16,527.00 | 6% | <i>\$15,651.90</i> |
| EWPPPremierPLS4HROn-site H30543 | 98508-H30543 | \$ 1,523.00 | 6% | <i>\$1,442.36</i> |
| EWPPPremierPLS4HROn-site H30544 | 98508-H30544 | \$ 2,380.00 | 6% | <i>\$2,253.98</i> |
| EWPPPremierPLS4HROn-site H30548 | 98508-H30548 | \$ 1,523.00 | 6% | <i>\$1,442.36</i> |
| EWPPPremierPLS4HROn-site H30549 | 98508-H30549 | \$ 2,276.00 | 6% | <i>\$2,155.49</i> |
| EWPPPremierPLS4HROn-site H30550 | 98508-H30550 | \$ 2,276.00 | 6% | <i>\$2,155.49</i> |
| EWPPPremierPLS4HROn-site H30552 | 98508-H30552 | \$ 1,523.00 | 6% | <i>\$1,442.36</i> |
| EWPPPremierPLS4HROn-site H30553 | 98508-H30553 | \$ 2,165.00 | 6% | <i>\$2,050.36</i> |
| EWPPPremierPLS4HROn-site H30569 | 98508-H30569 | \$ 7,110.00 | 6% | <i>\$6,733.53</i> |
| EWPPPremierPLS4HROn-site H30570 | 98508-H30570 | \$ 8,311.00 | 6% | <i>\$7,870.93</i> |
| EWPPPremierPLS4HROn-site H30571 | 98508-H30571 | \$ 8,311.00 | 6% | <i>\$7,870.93</i> |
| EWPPPremierPLS4HROn-site H30573 | 98508-H30573 | \$ 7,110.00 | 6% | <i>\$6,733.53</i> |
| EWPPPremierPLS4HROn-site H30574 | 98508-H30574 | \$ 7,762.00 | 6% | <i>\$7,351.00</i> |
| EWPPPremierPLS4HROn-site H30575 | 98508-H30575 | \$ 5,261.00 | 6% | <i>\$4,982.43</i> |
| EWPPPremierPLS4HROn-site H30576 | 98508-H30576 | \$ 7,110.00 | 6% | <i>\$6,733.53</i> |
| EWPPPremierPLS4HROn-site H30577 | 98508-H30577 | \$ 8,152.00 | 6% | <i>\$7,720.35</i> |
| EWPPPremierPLS4HROn-site H30578 | 98508-H30578 | \$ 8,152.00 | 6% | <i>\$7,720.35</i> |
| EWPPPremierPLS4HROn-site H30587 | 98508-H30587 | \$ 6,512.00 | 6% | <i>\$6,167.19</i> |

| | | | | |
|-------------------------------------|--------------|--------------|-----|--------------------|
| EWPPPremierPLS4HROn-site H30588 | 98508-H30588 | \$ 4,627.00 | 6% | <i>\$4,382.00</i> |
| EWPPPremierPLS4HROn-site H30589 | 98508-H30589 | \$ 6,822.00 | 6% | <i>\$6,460.78</i> |
| EWPPPremierPLS4HROn-site H30632 | 98508-H30632 | \$ 492.00 | 6% | <i>\$465.95</i> |
| EWPPPremierPLS4HROn-site H30633 | 98508-H30633 | \$ 492.00 | 6% | <i>\$465.95</i> |
| EWPPPremierPLS4HROn-site H30643 | 98508-H30643 | \$ 12,496.00 | 6% | <i>\$11,834.34</i> |
| EWPPPremierPLS4HROn-site H30706 | 98508-H30706 | \$ 10,022.00 | 6% | <i>\$9,491.34</i> |
| EWPPPremierPLS4HROn-site H30707 | 98508-H30707 | \$ 6,388.00 | 6% | <i>\$6,049.76</i> |
| EWPPPremierPLS4HROn-site H30724 | 98508-H30724 | \$ 978.00 | 6% | <i>\$926.21</i> |
| EWPPPremierPLS4HROn-site H30725 | 98508-H30725 | \$ 3,410.00 | 6% | <i>\$3,229.44</i> |
| EWPPPremierPLS4HROn-site H30726 | 98508-H30726 | \$ 15,276.00 | 6% | <i>\$14,467.14</i> |
| EWPPPremierPLS4HROn-site H30727 | 98508-H30727 | \$ 16,212.00 | 6% | <i>\$15,353.57</i> |
| EWPPPremierPLS4HROn-site H30730 | 98508-H30730 | \$ 464.00 | 6% | <i>\$439.43</i> |
| EWPPPremierPLS4HROn-site H30731 | 98508-H30731 | \$ 464.00 | 6% | <i>\$439.43</i> |
| EWPPPremierPLS4HROn-site H30733 | 98508-H30733 | \$ 14,655.00 | 6% | <i>\$13,879.02</i> |
| EWPPPremierPLS4HROn-site H30734 | 98508-H30734 | \$ 11,274.00 | 6% | <i>\$10,677.04</i> |
| EWPPPremierPLS4HROn-site H30735 | 98508-H30735 | \$ 12,997.00 | 6% | <i>\$12,308.81</i> |
| EWPPPremierPLS4HROn-site H30736 | 98508-H30736 | \$ 2,380.00 | 6% | <i>\$2,253.98</i> |
| EWPPPremierPLS4HROn-site H30738 | 98508-H30738 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremierPLS4HROn-site H30787 | 98508-H30787 | \$ 362.00 | 10% | <i>\$328.24</i> |
| EWPP PremierPLS4HROn-site H30788 | 98508-H30788 | \$ 364.00 | 10% | <i>\$330.06</i> |
| EWPP PremierPLS4HROn-site H30791 | 98508-H30791 | \$ 340.00 | 10% | <i>\$308.30</i> |

| | | | | |
|------------------------------------|--------------|--------------|-----|--------------------|
| EWPP PremierPLS4HROnsite H30847 | 98508-H30847 | \$ 366.00 | 10% | <i>\$331.87</i> |
| EWPP PremierPLS4HROnsite H30848 | 98508-H30848 | \$ 366.00 | 10% | <i>\$331.87</i> |
| EWPP PremierPLS4HROnsite H30852 | 98508-H30852 | \$ 366.00 | 10% | <i>\$331.87</i> |
| EWPP PremierPLS4HROnsite H30857 | 98508-H30857 | \$ 447.00 | 10% | <i>\$405.32</i> |
| EWPP PremierPLS4HROnsite H30869 | 98508-H30869 | \$ 657.00 | 10% | <i>\$595.73</i> |
| EWPP PremierPLS4HROnsite H30900 | 98508-H30900 | \$ 5,430.00 | 10% | <i>\$4,923.65</i> |
| EWPPPremierPLS4HROnsite H31337 | 98508-H31337 | \$ 16,776.00 | 6% | <i>\$15,887.71</i> |
| EWPPPremierPLS4HROnsite H31338 | 98508-H31338 | \$ 16,776.00 | 6% | <i>\$15,887.71</i> |
| EWPPPremierPLS4HROnsite H31341 | 98508-H31341 | \$ 9,006.00 | 6% | <i>\$8,529.13</i> |
| EWPPPremierPLS4HROnsite H31342 | 98508-H31342 | \$ 2,591.00 | 6% | <i>\$2,453.81</i> |
| EWPPPremierPLS4HROnsite H31343 | 98508-H31343 | \$ 3,621.00 | 6% | <i>\$3,429.27</i> |
| EWPPPremierPLS4HROnsite H31344 | 98508-H31344 | \$ 3,621.00 | 6% | <i>\$3,429.27</i> |
| EWPPPremierPLS4HROnsite H31345 | 98508-H31345 | \$ 3,621.00 | 6% | <i>\$3,429.27</i> |
| EWPPPremierPLS4HROnsite H31346 | 98508-H31346 | \$ 3,621.00 | 6% | <i>\$3,429.27</i> |
| EWPPPremierPLS4HROnsite H31362 | 98508-H31362 | \$ 45,722.00 | 6% | <i>\$43,301.02</i> |
| EWPPPremierPLS4HROnsite H31363 | 98508-H31363 | \$ 45,722.00 | 6% | <i>\$43,301.02</i> |
| EWPPPremierPLS4HROnsite H31364 | 98508-H31364 | \$ 16,803.00 | 6% | <i>\$15,913.28</i> |
| EWPPPremierPLS4HROnsite H31365 | 98508-H31365 | \$ 16,803.00 | 6% | <i>\$15,913.28</i> |
| EWPPPremierPLS4HROnsite H31366 | 98508-H31366 | \$ 23,271.00 | 6% | <i>\$22,038.80</i> |
| EWPPPremierPLS4HROnsite H31367 | 98508-H31367 | \$ 23,271.00 | 6% | <i>\$22,038.80</i> |
| EWPPPremierPLS4HROnsite H32010 | 98508-H32010 | \$ 1,995.00 | 6% | <i>\$1,889.36</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H32011 | 98508-H32011 | \$ 1,995.00 | 6% | <i>\$1,889.36</i> |
| EWPPPremierPLS4HROnsite H32012 | 98508-H32012 | \$ 5,732.00 | 6% | <i>\$5,428.49</i> |
| EWPPPremierPLS4HROnsite H32013 | 98508-H32013 | \$ 5,732.00 | 6% | <i>\$5,428.49</i> |
| EWPPPremierPLS4HROnsite H32014 | 98508-H32014 | \$ 5,732.00 | 6% | <i>\$5,428.49</i> |
| EWPPPremierPLS4HROnsite H32015 | 98508-H32015 | \$ 5,732.00 | 6% | <i>\$5,428.49</i> |
| EWPPPremierPLS4HROnsite H32016 | 98508-H32016 | \$ 5,275.00 | 6% | <i>\$4,995.69</i> |
| EWPPPremierPLS4HROnsite H32017 | 98508-H32017 | \$ 5,275.00 | 6% | <i>\$4,995.69</i> |
| EWPPPremierPLS4HROnsite H32018 | 98508-H32018 | \$ 5,275.00 | 6% | <i>\$4,995.69</i> |
| EWPPPremierPLS4HROnsite H32019 | 98508-H32019 | \$ 5,275.00 | 6% | <i>\$4,995.69</i> |
| EWPPPremierPLS4HROnsite H32020 | 98508-H32020 | \$ 47,068.00 | 6% | <i>\$44,575.75</i> |
| EWPPPremierPLS4HROnsite H32021 | 98508-H32021 | \$ 47,068.00 | 6% | <i>\$44,575.75</i> |
| EWPPPremierPLS4HROnsite H32022 | 98508-H32022 | \$ 47,068.00 | 6% | <i>\$44,575.75</i> |
| EWPPPremierPLS4HROnsite H32023 | 98508-H32023 | \$ 47,068.00 | 6% | <i>\$44,575.75</i> |
| EWPPPremierPLS4HROnsite H32028 | 98508-H32028 | \$ 88,857.00 | 6% | <i>\$84,152.02</i> |
| EWPPPremierPLS4HROnsite H32029 | 98508-H32029 | \$ 88,857.00 | 6% | <i>\$84,152.02</i> |
| EWPPPremierPLS4HROnsite H32030 | 98508-H32030 | \$ 93,188.00 | 6% | <i>\$88,253.70</i> |
| EWPPPremierPLS4HROnsite H32031 | 98508-H32031 | \$ 93,188.00 | 6% | <i>\$88,253.70</i> |
| EWPPPremierPLS4HROnsite H32032 | 98508-H32032 | \$ 93,188.00 | 6% | <i>\$88,253.70</i> |
| EWPPPremierPLS4HROnsite H32033 | 98508-H32033 | \$ 93,188.00 | 6% | <i>\$88,253.70</i> |
| EWPPPremierPLS4HROnsite H32038 | 98508-H32038 | \$ 17,207.00 | 6% | <i>\$16,295.89</i> |
| EWPPPremierPLS4HROnsite H32039 | 98508-H32039 | \$ 17,207.00 | 6% | <i>\$16,295.89</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H32040 | 98508-H32040 | \$ 17,207.00 | 6% | <i>\$16,295.89</i> |
| EWPPPremierPLS4HROnsite H32041 | 98508-H32041 | \$ 17,207.00 | 6% | <i>\$16,295.89</i> |
| EWPPPremierPLS4HROnsite H32046 | 98508-H32046 | \$ 23,832.00 | 6% | <i>\$22,570.10</i> |
| EWPPPremierPLS4HROnsite H32047 | 98508-H32047 | \$ 23,832.00 | 6% | <i>\$22,570.10</i> |
| EWPPPremierPLS4HROnsite H32048 | 98508-H32048 | \$ 23,832.00 | 6% | <i>\$22,570.10</i> |
| EWPPPremierPLS4HROnsite H32049 | 98508-H32049 | \$ 23,832.00 | 6% | <i>\$22,570.10</i> |
| EWPPPremierPLS4HROnsite H32054 | 98508-H32054 | \$ 17,207.00 | 6% | <i>\$16,295.89</i> |
| EWPPPremierPLS4HROnsite H32055 | 98508-H32055 | \$ 23,832.00 | 6% | <i>\$22,570.10</i> |
| EWPPPremierPLS4HROnsite H32056 | 98508-H32056 | \$ 6,555.00 | 6% | <i>\$6,207.91</i> |
| EWPPPremierPLS4HROnsite H32057 | 98508-H32057 | \$ 6,750.00 | 6% | <i>\$6,392.59</i> |
| EWPPPremierPLS4HROnsite H32058 | 98508-H32058 | \$ 6,750.00 | 6% | <i>\$6,392.59</i> |
| EWPPPremierPLS4HROnsite H32059 | 98508-H32059 | \$ 6,750.00 | 6% | <i>\$6,392.59</i> |
| EWPPPremierPLS4HROnsite H32060 | 98508-H32060 | \$ 7,761.00 | 6% | <i>\$7,350.06</i> |
| EWPPPremierPLS4HROnsite H32061 | 98508-H32061 | \$ 8,149.00 | 6% | <i>\$7,717.51</i> |
| EWPPPremierPLS4HROnsite H32062 | 98508-H32062 | \$ 7,761.00 | 6% | <i>\$7,350.06</i> |
| EWPPPremierPLS4HROnsite H32063 | 98508-H32063 | \$ 7,769.00 | 6% | <i>\$7,357.63</i> |
| EWPPPremierPLS4HROnsite H32064 | 98508-H32064 | \$ 7,761.00 | 6% | <i>\$7,350.06</i> |
| EWPPPremierPLS4HROnsite H32065 | 98508-H32065 | \$ 7,403.00 | 6% | <i>\$7,011.01</i> |
| EWPPPremierPLS4HROnsite H32066 | 98508-H32066 | \$ 7,403.00 | 6% | <i>\$7,011.01</i> |
| EWPPPremierPLS4HROnsite H32067 | 98508-H32067 | \$ 7,403.00 | 6% | <i>\$7,011.01</i> |
| EWPPPremierPLS4HROnsite H32068 | 98508-H32068 | \$ 7,403.00 | 6% | <i>\$7,011.01</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H32069 | 98508-H32069 | \$ 8,837.00 | 6% | <i>\$8,369.08</i> |
| EWPPPremierPLS4HROnsite H32070 | 98508-H32070 | \$ 8,837.00 | 6% | <i>\$8,369.08</i> |
| EWPPPremierPLS4HROnsite H32071 | 98508-H32071 | \$ 8,837.00 | 6% | <i>\$8,369.08</i> |
| EWPPPremierPLS4HROnsite H32072 | 98508-H32072 | \$ 8,837.00 | 6% | <i>\$8,369.08</i> |
| EWPPPremierPLS4HROnsite H32073 | 98508-H32073 | \$ 60,510.00 | 6% | <i>\$57,306.00</i> |
| EWPPPremierPLS4HROnsite H32074 | 98508-H32074 | \$ 60,510.00 | 6% | <i>\$57,306.00</i> |
| EWPPPremierPLS4HROnsite H32075 | 98508-H32075 | \$ 82,289.00 | 6% | <i>\$77,931.80</i> |
| EWPPPremierPLS4HROnsite H32076 | 98508-H32076 | \$ 81,505.00 | 6% | <i>\$77,189.31</i> |
| EWPPPremierPLS4HROnsite H32101 | 98508-H32101 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |
| EWPPPremierPLS4HROnsite H32102 | 98508-H32102 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |
| EWPPPremierPLS4HROnsite H32103 | 98508-H32103 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |
| EWPPPremierPLS4HROnsite H32104 | 98508-H32104 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |
| EWPPPremierPLS4HROnsite H32105 | 98508-H32105 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32106 | 98508-H32106 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32107 | 98508-H32107 | \$ 14,678.00 | 6% | <i>\$13,900.80</i> |
| EWPPPremierPLS4HROnsite H32108 | 98508-H32108 | \$ 14,678.00 | 6% | <i>\$13,900.80</i> |
| EWPPPremierPLS4HROnsite H32109 | 98508-H32109 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32110 | 98508-H32110 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32111 | 98508-H32111 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |
| EWPPPremierPLS4HROnsite H32112 | 98508-H32112 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |
| EWPPPremierPLS4HROnsite H32113 | 98508-H32113 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H32114 | 98508-H32114 | \$ 3,986.00 | 6% | <i>\$3,774.94</i> |
| EWPPPremierPLS4HROnsite H32115 | 98508-H32115 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32116 | 98508-H32116 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32117 | 98508-H32117 | \$ 3,839.00 | 6% | <i>\$3,635.72</i> |
| EWPPPremierPLS4HROnsite H32118 | 98508-H32118 | \$ 3,839.00 | 6% | <i>\$3,635.72</i> |
| EWPPPremierPLS4HROnsite H32119 | 98508-H32119 | \$ 3,839.00 | 6% | <i>\$3,635.72</i> |
| EWPPPremierPLS4HROnsite H32120 | 98508-H32120 | \$ 3,839.00 | 6% | <i>\$3,635.72</i> |
| EWPPPremierPLS4HROnsite H32121 | 98508-H32121 | \$ 14,678.00 | 6% | <i>\$13,900.80</i> |
| EWPPPremierPLS4HROnsite H32122 | 98508-H32122 | \$ 14,678.00 | 6% | <i>\$13,900.80</i> |
| EWPPPremierPLS4HROnsite H32123 | 98508-H32123 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32124 | 98508-H32124 | \$ 6,410.00 | 6% | <i>\$6,070.59</i> |
| EWPPPremierPLS4HROnsite H32125 | 98508-H32125 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| EWPPPremierPLS4HROnsite H32126 | 98508-H32126 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| EWPPPremierPLS4HROnsite H32127 | 98508-H32127 | \$ 7,093.00 | 6% | <i>\$6,717.43</i> |
| EWPPPremierPLS4HROnsite H32128 | 98508-H32128 | \$ 7,093.00 | 6% | <i>\$6,717.43</i> |
| EWPPPremierPLS4HROnsite H32129 | 98508-H32129 | \$ 7,093.00 | 6% | <i>\$6,717.43</i> |
| EWPPPremierPLS4HROnsite H32130 | 98508-H32130 | \$ 7,093.00 | 6% | <i>\$6,717.43</i> |
| EWPPPremierPLS4HROnsite H32131 | 98508-H32131 | \$ 7,093.00 | 6% | <i>\$6,717.43</i> |
| EWPPPremierPLS4HROnsite H32132 | 98508-H32132 | \$ 7,093.00 | 6% | <i>\$6,717.43</i> |
| EWPPPremierPLS4HROnsite H32133 | 98508-H32133 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| EWPPPremierPLS4HROnsite H32134 | 98508-H32134 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H32135 | 98508-H32135 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| EWPPPremierPLS4HROnsite H32136 | 98508-H32136 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| EWPPPremierPLS4HROnsite H32137 | 98508-H32137 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| EWPPPremierPLS4HROnsite H32138 | 98508-H32138 | \$ 6,239.00 | 6% | <i>\$5,908.64</i> |
| EWPPPremierPLS4HROnsite H32139 | 98508-H32139 | \$ 24,304.00 | 6% | <i>\$23,017.10</i> |
| EWPPPremierPLS4HROnsite H32140 | 98508-H32140 | \$ 24,304.00 | 6% | <i>\$23,017.10</i> |
| EWPPPremierPLS4HROnsite H32141 | 98508-H32141 | \$ 28,700.00 | 6% | <i>\$27,180.34</i> |
| EWPPPremierPLS4HROnsite H32142 | 98508-H32142 | \$ 28,700.00 | 6% | <i>\$27,180.34</i> |
| EWPPPremierPLS4HROnsite H32146 | 98508-H32146 | \$ 3,775.00 | 6% | <i>\$3,575.11</i> |
| EWPPPremierPLS4HROnsite H32147 | 98508-H32147 | \$ 3,775.00 | 6% | <i>\$3,575.11</i> |
| EWPPPremierPLS4HROnsite H32148 | 98508-H32148 | \$ 6,073.00 | 6% | <i>\$5,751.43</i> |
| EWPPPremierPLS4HROnsite H32149 | 98508-H32149 | \$ 6,073.00 | 6% | <i>\$5,751.43</i> |
| EWPPPremierPLS4HROnsite H32150 | 98508-H32150 | \$ 3,775.00 | 6% | <i>\$3,575.11</i> |
| EWPPPremierPLS4HROnsite H32169 | 98508-H32169 | \$ 3,956.00 | 6% | <i>\$3,746.53</i> |
| EWPPPremierPLS4HROnsite H32170 | 98508-H32170 | \$ 3,956.00 | 6% | <i>\$3,746.53</i> |
| EWPPPremierPLS4HROnsite H32171 | 98508-H32171 | \$ 3,809.00 | 6% | <i>\$3,607.31</i> |
| EWPPPremierPLS4HROnsite H32172 | 98508-H32172 | \$ 3,809.00 | 6% | <i>\$3,607.31</i> |
| EWPPPremierPLS4HROnsite H32173 | 98508-H32173 | \$ 7,565.00 | 6% | <i>\$7,164.43</i> |
| EWPPPremierPLS4HROnsite H32174 | 98508-H32174 | \$ 7,565.00 | 6% | <i>\$7,164.43</i> |
| EWPPPremierPLS4HROnsite H32175 | 98508-H32175 | \$ 6,656.00 | 6% | <i>\$6,303.56</i> |
| EWPPPremierPLS4HROnsite H32176 | 98508-H32176 | \$ 6,656.00 | 6% | <i>\$6,303.56</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H32177 | 98508-H32177 | \$ 26,708.00 | 6% | <i>\$25,293.81</i> |
| EWPPPremierPLS4HROnsite H32178 | 98508-H32178 | \$ 31,536.00 | 6% | <i>\$29,866.17</i> |
| EWPPPremierPLS4HROnsite H34008 | 98508-H34008 | \$ 1,306.00 | 6% | <i>\$1,236.85</i> |
| EWPPPremierPLS4HROnsite H34009 | 98508-H34009 | \$ 1,459.00 | 6% | <i>\$1,381.75</i> |
| EWPPPremierPLS4HROnsite H34010 | 98508-H34010 | \$ 1,240.00 | 6% | <i>\$1,174.34</i> |
| EWPPPremierPLS4HROnsite H34011 | 98508-H34011 | \$ 1,431.00 | 6% | <i>\$1,355.23</i> |
| EWPPPremierPLS4HROnsite H34012 | 98508-H34012 | \$ 1,603.00 | 6% | <i>\$1,518.12</i> |
| EWPPPremierPLS4HROnsite H34013 | 98508-H34013 | \$ 1,366.00 | 6% | <i>\$1,293.67</i> |
| EWPPPremierPLS4HROnsite H34014 | 98508-H34014 | \$ 1,459.00 | 6% | <i>\$1,381.75</i> |
| EWPPPremierPLS4HROnsite H34015 | 98508-H34015 | \$ 1,263.00 | 6% | <i>\$1,196.12</i> |
| EWPPPremierPLS4HROnsite H34016 | 98508-H34016 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| EWPPPremierPLS4HROnsite H34017 | 98508-H34017 | \$ 1,675.00 | 6% | <i>\$1,586.31</i> |
| EWPPPremierPLS4HROnsite H34018 | 98508-H34018 | \$ 1,380.00 | 6% | <i>\$1,306.93</i> |
| EWPPPremierPLS4HROnsite H34019 | 98508-H34019 | \$ 1,380.00 | 6% | <i>\$1,306.93</i> |
| EWPPPremierPLS4HROnsite H34020 | 98508-H34020 | \$ 1,380.00 | 6% | <i>\$1,306.93</i> |
| EWPPPremierPLS4HROnsite H34021 | 98508-H34021 | \$ 1,380.00 | 6% | <i>\$1,306.93</i> |
| EWPPPremierPLS4HROnsite H34048 | 98508-H34048 | \$ 1,958.00 | 6% | <i>\$1,854.32</i> |
| EWPPPremierPLS4HROnsite H34049 | 98508-H34049 | \$ 1,958.00 | 6% | <i>\$1,854.32</i> |
| EWPPPremierPLS4HROnsite H34050 | 98508-H34050 | \$ 1,764.00 | 6% | <i>\$1,670.60</i> |
| EWPPPremierPLS4HROnsite H34051 | 98508-H34051 | \$ 1,764.00 | 6% | <i>\$1,670.60</i> |
| EWPPPremierPLS4HROnsite H34052 | 98508-H34052 | \$ 2,092.00 | 6% | <i>\$1,981.23</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLS4HROnsite H34053 | 98508-H34053 | \$ 2,092.00 | 6% | <i>\$1,981.23</i> |
| EWPPPremierPLS4HROnsite H34054 | 98508-H34054 | \$ 1,870.00 | 6% | <i>\$1,770.98</i> |
| EWPPPremierPLS4HROnsite H34055 | 98508-H34055 | \$ 1,870.00 | 6% | <i>\$1,770.98</i> |
| EWPPPremierPLS4HROnsite H34056 | 98508-H34056 | \$ 2,281.00 | 6% | <i>\$2,160.22</i> |
| EWPPPremierPLS4HROnsite H34057 | 98508-H34057 | \$ 2,281.00 | 6% | <i>\$2,160.22</i> |
| EWPPPremierPLS4HROnsite H34058 | 98508-H34058 | \$ 2,136.00 | 6% | <i>\$2,022.90</i> |
| EWPPPremierPLS4HROnsite H34059 | 98508-H34059 | \$ 2,136.00 | 6% | <i>\$2,022.90</i> |
| EWPPPremierPLS4HROnsite H34062 | 98508-H34062 | \$ 2,281.00 | 6% | <i>\$2,160.22</i> |
| EWPPPremierPLS4HROnsite H34063 | 98508-H34063 | \$ 2,281.00 | 6% | <i>\$2,160.22</i> |
| EWPPPremierPLS4HROnsite H34064 | 98508-H34064 | \$ 1,789.00 | 6% | <i>\$1,694.27</i> |
| EWPPPremierPLS4HROnsite H34065 | 98508-H34065 | \$ 1,789.00 | 6% | <i>\$1,694.27</i> |
| EWPPPremierPLS4HROnsite H34066 | 98508-H34066 | \$ 1,789.00 | 6% | <i>\$1,694.27</i> |
| EWPPPremierPLS4HROnsite H34067 | 98508-H34067 | \$ 1,789.00 | 6% | <i>\$1,694.27</i> |
| EWPPPremierPLS4HROnsite H34068 | 98508-H34068 | \$ 1,789.00 | 6% | <i>\$1,694.27</i> |
| EWPPPremierPLS4HROnsite H34069 | 98508-H34069 | \$ 1,772.00 | 6% | <i>\$1,678.17</i> |
| EWPPPremierPLS4HROnsite H34070 | 98508-H34070 | \$ 1,789.00 | 6% | <i>\$1,694.27</i> |
| EWPPPremierPLS4HROnsite H34071 | 98508-H34071 | \$ 1,789.00 | 6% | <i>\$1,694.27</i> |
| EWPPPremierPLS4HROnsite H34072 | 98508-H34072 | \$ 6,439.00 | 6% | <i>\$6,098.05</i> |
| EWPPPremierPLS4HROnsite H34073 | 98508-H34073 | \$ 6,316.00 | 6% | <i>\$5,981.57</i> |
| EWPPPremierPLS4HROnsite H34074 | 98508-H34074 | \$ 7,985.00 | 6% | <i>\$7,562.19</i> |
| EWPPPremierPLS4HROnsite H34075 | 98508-H34075 | \$ 7,717.00 | 6% | <i>\$7,308.38</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H34076 | 98508-H34076 | \$ 6,439.00 | 6% | <i>\$6,098.05</i> |
| EWPPPremierPLS4HROnsite H34077 | 98508-H34077 | \$ 6,316.00 | 6% | <i>\$5,981.57</i> |
| EWPPPremierPLS4HROnsite H34078 | 98508-H34078 | \$ 6,439.00 | 6% | <i>\$6,098.05</i> |
| EWPPPremierPLS4HROnsite H34079 | 98508-H34079 | \$ 6,316.00 | 6% | <i>\$5,981.57</i> |
| EWPPPremierPLS4HROnsite H34080 | 98508-H34080 | \$ 7,985.00 | 6% | <i>\$7,562.19</i> |
| EWPPPremierPLS4HROnsite H34081 | 98508-H34081 | \$ 7,717.00 | 6% | <i>\$7,308.38</i> |
| EWPPPremierPLS4HROnsite H34082 | 98508-H34082 | \$ 7,622.00 | 6% | <i>\$7,218.42</i> |
| EWPPPremierPLS4HROnsite H34083 | 98508-H34083 | \$ 7,366.00 | 6% | <i>\$6,975.97</i> |
| EWPPPremierPLS4HROnsite H34084 | 98508-H34084 | \$ 5,397.00 | 6% | <i>\$5,111.23</i> |
| EWPPPremierPLS4HROnsite H34085 | 98508-H34085 | \$ 5,397.00 | 6% | <i>\$5,111.23</i> |
| EWPPPremierPLS4HROnsite H34086 | 98508-H34086 | \$ 6,314.00 | 6% | <i>\$5,979.67</i> |
| EWPPPremierPLS4HROnsite H34087 | 98508-H34087 | \$ 6,027.00 | 6% | <i>\$5,707.87</i> |
| EWPPPremierPLS4HROnsite H34088 | 98508-H34088 | \$ 12,848.00 | 6% | <i>\$12,167.70</i> |
| EWPPPremierPLS4HROnsite H34089 | 98508-H34089 | \$ 12,848.00 | 6% | <i>\$12,167.70</i> |
| EWPPPremierPLS4HROnsite H34090 | 98508-H34090 | \$ 14,793.00 | 6% | <i>\$14,009.71</i> |
| EWPPPremierPLS4HROnsite H34091 | 98508-H34091 | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| EWPPPremierPLS4HROnsite H34092 | 98508-H34092 | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| EWPPPremierPLS4HROnsite H34093 | 98508-H34093 | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| EWPPPremierPLS4HROnsite H34094 | 98508-H34094 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34095 | 98508-H34095 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34096 | 98508-H34096 | \$ 1,785.00 | 6% | <i>\$1,690.48</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H34097 | 98508-H34097 | \$ 1,785.00 | 6% | <i>\$1,690.48</i> |
| EWPPPremierPLS4HROnsite H34098 | 98508-H34098 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34099 | 98508-H34099 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34100 | 98508-H34100 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34101 | 98508-H34101 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34102 | 98508-H34102 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34103 | 98508-H34103 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPPPremierPLS4HROnsite H34104 | 98508-H34104 | \$ 961.00 | 6% | <i>\$910.12</i> |
| EWPPPremierPLS4HROnsite H34105 | 98508-H34105 | \$ 961.00 | 6% | <i>\$910.12</i> |
| EWPPPremierPLS4HROnsite H34106 | 98508-H34106 | \$ 961.00 | 6% | <i>\$910.12</i> |
| EWPPPremierPLS4HROnsite H34107 | 98508-H34107 | \$ 961.00 | 6% | <i>\$910.12</i> |
| EWPPPremierPLS4HROnsite H34108 | 98508-H34108 | \$ 961.00 | 6% | <i>\$910.12</i> |
| EWPPPremierPLS4HROnsite H34109 | 98508-H34109 | \$ 961.00 | 6% | <i>\$910.12</i> |
| EWPPPremierPLS4HROnsite H34110 | 98508-H34110 | \$ 13,259.00 | 6% | <i>\$12,556.94</i> |
| EWPPPremierPLS4HROnsite H34111 | 98508-H34111 | \$ 13,259.00 | 6% | <i>\$12,556.94</i> |
| EWPPPremierPLS4HROnsite H34112 | 98508-H34112 | \$ 13,259.00 | 6% | <i>\$12,556.94</i> |
| EWPPPremierPLS4HROnsite H34114 | 98508-H34114 | \$ 18,901.00 | 6% | <i>\$17,900.19</i> |
| EWPPPremierPLS4HROnsite H34115 | 98508-H34115 | \$ 18,475.00 | 6% | <i>\$17,496.75</i> |
| EWPPPremierPLS4HROnsite H34116 | 98508-H34116 | \$ 18,475.00 | 6% | <i>\$17,496.75</i> |
| EWPPPremierPLS4HROnsite H34117 | 98508-H34117 | \$ 18,901.00 | 6% | <i>\$17,900.19</i> |
| EWPPPremierPLS4HROnsite H34118 | 98508-H34118 | \$ 3,699.00 | 6% | <i>\$3,503.14</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLS4HROnsite H34119 | 98508-H34119 | \$ 3,699.00 | 6% | <i>\$3,503.14</i> |
| EWPPPremierPLS4HROnsite H34120 | 98508-H34120 | \$ 2,678.00 | 6% | <i>\$2,536.20</i> |
| EWPPPremierPLS4HROnsite H34121 | 98508-H34121 | \$ 2,678.00 | 6% | <i>\$2,536.20</i> |
| EWPPPremierPLS4HROnsite H34122 | 98508-H34122 | \$ 2,778.00 | 6% | <i>\$2,630.90</i> |
| EWPPPremierPLS4HROnsite H34123 | 98508-H34123 | \$ 2,778.00 | 6% | <i>\$2,630.90</i> |
| EWPPPremierPLS4HROnsite H34124 | 98508-H34124 | \$ 3,930.00 | 6% | <i>\$3,721.91</i> |
| EWPPPremierPLS4HROnsite H34125 | 98508-H34125 | \$ 3,930.00 | 6% | <i>\$3,721.91</i> |
| EWPPPremierPLS4HROnsite H34126 | 98508-H34126 | \$ 3,930.00 | 6% | <i>\$3,721.91</i> |
| EWPPPremierPLS4HROnsite H34127 | 98508-H34127 | \$ 3,930.00 | 6% | <i>\$3,721.91</i> |
| EWPPPremierPLS4HROnsite H34129 | 98508-H34129 | \$ 1,957.00 | 6% | <i>\$1,853.38</i> |
| EWPPPremierPLS4HROnsite H34130 | 98508-H34130 | \$ 2,034.00 | 6% | <i>\$1,926.30</i> |
| EWPPPremierPLS4HROnsite H34131 | 98508-H34131 | \$ 2,034.00 | 6% | <i>\$1,926.30</i> |
| EWPPPremierPLS4HROnsite H34132 | 98508-H34132 | \$ 2,034.00 | 6% | <i>\$1,926.30</i> |
| EWPPPremierPLS4HROnsite H34172 | 98508-H34172 | \$ 4,038.00 | 6% | <i>\$3,824.19</i> |
| EWPPPremierPLS4HROnsite H34726 | 98508-H34726 | \$ 6,730.00 | 6% | <i>\$6,373.65</i> |
| EWPPPremierPLS4HROnsite H34727 | 98508-H34727 | \$ 6,730.00 | 6% | <i>\$6,373.65</i> |
| EWPPPremierPLS4HROnsite H34728 | 98508-H34728 | \$ 6,730.00 | 6% | <i>\$6,373.65</i> |
| EWPPPremierPLS4HROnsite H34729 | 98508-H34729 | \$ 6,730.00 | 6% | <i>\$6,373.65</i> |
| EWPPPremierPLS4HROnsite H34730 | 98508-H34730 | \$ 7,127.00 | 6% | <i>\$6,749.63</i> |
| EWPPPremierPLS4HROnsite H34731 | 98508-H34731 | \$ 7,127.00 | 6% | <i>\$6,749.63</i> |
| EWPPPremierPLS4HROnsite H34732 | 98508-H34732 | \$ 7,127.00 | 6% | <i>\$6,749.63</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLS4HROnsite H34733 | 98508-H34733 | \$ 7,127.00 | 6% | <i>\$6,749.63</i> |
| EWPPPremierPLS4HROnsite H34734 | 98508-H34734 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPPPremierPLS4HROnsite H34735 | 98508-H34735 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPPPremierPLS4HROnsite H34736 | 98508-H34736 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34737 | 98508-H34737 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34738 | 98508-H34738 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34739 | 98508-H34739 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34740 | 98508-H34740 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPPPremierPLS4HROnsite H34741 | 98508-H34741 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPPPremierPLS4HROnsite H34742 | 98508-H34742 | \$ 1,983.00 | 6% | <i>\$1,878.00</i> |
| EWPPPremierPLS4HROnsite H34743 | 98508-H34743 | \$ 1,983.00 | 6% | <i>\$1,878.00</i> |
| EWPPPremierPLS4HROnsite H34744 | 98508-H34744 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34745 | 98508-H34745 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34746 | 98508-H34746 | \$ 2,500.00 | 6% | <i>\$2,367.63</i> |
| EWPPPremierPLS4HROnsite H34747 | 98508-H34747 | \$ 2,500.00 | 6% | <i>\$2,367.63</i> |
| EWPPPremierPLS4HROnsite H34748 | 98508-H34748 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34749 | 98508-H34749 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34750 | 98508-H34750 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34751 | 98508-H34751 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34752 | 98508-H34752 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34753 | 98508-H34753 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H34754 | 98508-H34754 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34755 | 98508-H34755 | \$ 3,327.00 | 6% | <i>\$3,150.84</i> |
| EWPPPremierPLS4HROnsite H34756 | 98508-H34756 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34757 | 98508-H34757 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34758 | 98508-H34758 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34759 | 98508-H34759 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34760 | 98508-H34760 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34761 | 98508-H34761 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H34993 | 98508-H34993 | \$ 26,721.00 | 6% | <i>\$25,306.12</i> |
| EWPPPremierPLS4HROnsite H34994 | 98508-H34994 | \$ 26,721.00 | 6% | <i>\$25,306.12</i> |
| EWPPPremierPLS4HROnsite H34996 | 98508-H34996 | \$ 26,721.00 | 6% | <i>\$25,306.12</i> |
| EWPPPremierPLS4HROnsite H34997 | 98508-H34997 | \$ 26,721.00 | 6% | <i>\$25,306.12</i> |
| EWPPPremierPLS4HROnsite H35005 | 98508-H35005 | \$ 20,231.00 | 6% | <i>\$19,159.77</i> |
| EWPPPremierPLS4HROnsite H35006 | 98508-H35006 | \$ 20,231.00 | 6% | <i>\$19,159.77</i> |
| EWPPPremierPLS4HROnsite H35012 | 98508-H35012 | \$ 13,170.00 | 6% | <i>\$12,472.65</i> |
| EWPPPremierPLS4HROnsite H35270 | 98508-H35270 | \$ 2,092.00 | 6% | <i>\$1,981.23</i> |
| EWPPPremierPLS4HROnsite H35271 | 98508-H35271 | \$ 1,870.00 | 6% | <i>\$1,770.98</i> |
| EWPPPremierPLS4HROnsite H35272 | 98508-H35272 | \$ 1,706.00 | 6% | <i>\$1,615.67</i> |
| EWPPPremierPLS4HROnsite H35273 | 98508-H35273 | \$ 1,706.00 | 6% | <i>\$1,615.67</i> |
| EWPPPremierPLS4HROnsite H35274 | 98508-H35274 | \$ 2,500.00 | 6% | <i>\$2,367.63</i> |
| EWPPPremierPLS4HROnsite H35275 | 98508-H35275 | \$ 2,281.00 | 6% | <i>\$2,160.22</i> |

| | | | | |
|---------------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H35276 | 98508-H35276 | \$ 6,439.00 | 6% | <i>\$6,098.05</i> |
| EWPPPremierPLS4HROnsite H35277 | 98508-H35277 | \$ 7,622.00 | 6% | <i>\$7,218.42</i> |
| EWPPPremierPLS4HROnsite H35278 | 98508-H35278 | \$ 5,397.00 | 6% | <i>\$5,111.23</i> |
| EWPPPremierPLS4HROnsite H35279 | 98508-H35279 | \$ 6,028.00 | 6% | <i>\$5,708.82</i> |
| EWPPPremierPLS4HROnsite H35280 | 98508-H35280 | \$ 13,008.00 | 6% | <i>\$12,319.23</i> |
| EWPP PremierPLS4HROnsite H35294 | 98508-H35294 | \$ 3,143.00 | 6% | <i>\$2,976.58</i> |
| EWPPPremierPLS4HROnsite H35295 | 98508-H35295 | \$ 1,865.00 | 6% | <i>\$1,766.25</i> |
| EWPP PremierPLUS 4HR ONSITE H35296 | 98508-H35296 | \$ 15,666.00 | 6% | <i>\$14,836.49</i> |
| EWPP PremierPLUS 4HR ONSITE H35297 | 98508-H35297 | \$ 15,666.00 | 6% | <i>\$14,836.49</i> |
| EWPP PremierPLUS 4HR ONSITE H35298 | 98508-H35298 | \$ 25,172.00 | 6% | <i>\$23,839.14</i> |
| EWPP PremierPLUS 4HR ONSITE H35299 | 98508-H35299 | \$ 25,172.00 | 6% | <i>\$23,839.14</i> |
| EWPP PremierPLS4HROnsite H35302 | 98508-H35302 | \$ 5,658.00 | 6% | <i>\$5,358.41</i> |
| EWPP PremierPLS4HROnsite H35303 | 98508-H35303 | \$ 5,658.00 | 6% | <i>\$5,358.41</i> |
| EWPP PremierPLS4HROnsite H35304 | 98508-H35304 | \$ 5,658.00 | 6% | <i>\$5,358.41</i> |
| EWPP PremierPLS4HROnsite H35305 | 98508-H35305 | \$ 5,870.00 | 6% | <i>\$5,559.18</i> |
| EWPP PremierPLS4HROnsite H35306 | 98508-H35306 | \$ 5,870.00 | 6% | <i>\$5,559.18</i> |
| EWPP PremierPLS4HROnsite H35307 | 98508-H35307 | \$ 5,870.00 | 6% | <i>\$5,559.18</i> |
| EWPP PremierPLS4HROnsite H35309 | 98508-H35309 | \$ 6,674.00 | 6% | <i>\$6,320.61</i> |
| EWPP PremierPLS4HROnsite H35310 | 98508-H35310 | \$ 6,674.00 | 6% | <i>\$6,320.61</i> |
| EWPP PremierPLS4HROnsite H35311 | 98508-H35311 | \$ 6,674.00 | 6% | <i>\$6,320.61</i> |
| EWPP PremierPLS4HROnsite H35312 | 98508-H35312 | \$ 5,510.00 | 6% | <i>\$5,218.25</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLS4HROnsite H35313 | 98508-H35313 | \$ 5,510.00 | 6% | \$5,218.25 |
| EWPP PremierPLS4HROnsite H35314 | 98508-H35314 | \$ 5,510.00 | 6% | \$5,218.25 |
| EWPP PremierPLS4HROnsite H35315 | 98508-H35315 | \$ 3,101.00 | 6% | \$2,936.80 |
| EWPP PremierPLS4HROnsite H35318 | 98508-H35318 | \$ 2,079.00 | 6% | \$1,968.92 |
| EWPP PremierPLS4HROnsite H35319 | 98508-H35319 | \$ 2,387.00 | 6% | \$2,260.61 |
| EWPP PremierPLS4HROnsite H35320 | 98508-H35320 | \$ 2,438.00 | 6% | \$2,308.91 |
| EWPP PremierPLS4HROnsite H35321 | 98508-H35321 | \$ 2,739.00 | 6% | \$2,593.97 |
| EWPP PremierPLS4HROnsite H35322 | 98508-H35322 | \$ 3,137.00 | 6% | \$2,970.90 |
| EWPP PremierPLS4HROnsite H35323 | 98508-H35323 | \$ 3,101.00 | 6% | \$2,936.80 |
| EWPP PremierPLS4HROnsite H35328 | 98508-H35328 | \$ 909.00 | 6% | \$860.87 |
| EWPPPremierPLS4HROnsite H35330 | 98508-H35330 | \$ 1,235.00 | 6% | \$1,169.61 |
| EWPP PremierPLS4HROnsite H35340 | 98508-H35340 | \$ 5,773.00 | 6% | \$5,467.32 |
| EWPP PremierPLS4HROnsite H35341 | 98508-H35341 | \$ 5,773.00 | 6% | \$5,467.32 |
| EWPP PremierPLS4HROnsite H35342 | 98508-H35342 | \$ 4,744.00 | 6% | \$4,492.81 |
| EWPP PremierPLS4HROnsite H35343 | 98508-H35343 | \$ 5,773.00 | 6% | \$5,467.32 |
| EWPP PremierPLS4HROnsite H35344 | 98508-H35344 | \$ 5,918.00 | 6% | \$5,604.64 |
| EWPP PremierPLS4HROnsite H35345 | 98508-H35345 | \$ 5,919.00 | 6% | \$5,605.59 |
| EWPP PremierPLS4HROnsite H35346 | 98508-H35346 | \$ 4,854.00 | 6% | \$4,596.98 |
| EWPP PremierPLS4HROnsite H35347 | 98508-H35347 | \$ 5,919.00 | 6% | \$5,605.59 |
| EWPP PremierPLS4HROnsite H35349 | 98508-H35349 | \$ 6,281.00 | 6% | \$5,948.42 |
| EWPP PremierPLS4HROnsite H35350 | 98508-H35350 | \$ 6,282.00 | 6% | \$5,949.37 |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS4HROnsite H35351 | 98508-H35351 | \$ 5,145.00 | 6% | <i>\$4,872.57</i> |
| EWPP PremierPLS4HROnsite H35352 | 98508-H35352 | \$ 6,282.00 | 6% | <i>\$5,949.37</i> |
| EWPP PremierPLS4HROnsite H35359 | 98508-H35359 | \$ 2,739.00 | 6% | <i>\$2,593.97</i> |
| EWPP PremierPLS4HROnsite H35360 | 98508-H35360 | \$ 3,138.00 | 6% | <i>\$2,971.84</i> |
| EWPP PremierPLS4HROnsite H35361 | 98508-H35361 | \$ 3,101.00 | 6% | <i>\$2,936.80</i> |
| EWPP PremierPLS4HROnsite H35362 | 98508-H35362 | \$ 2,079.00 | 6% | <i>\$1,968.92</i> |
| EWPP PremierPLS4HROnsite H35366 | 98508-H35366 | \$ 2,787.00 | 6% | <i>\$2,639.43</i> |
| EWPP PremierPLS4HROnsite H35367 | 98508-H35367 | \$ 3,249.00 | 6% | <i>\$3,076.97</i> |
| EWPP PremierPLS4HROnsite H35368 | 98508-H35368 | \$ 4,948.00 | 6% | <i>\$4,686.00</i> |
| EWPP PremierPLS4HROnsite H35369 | 98508-H35369 | \$ 1,611.00 | 6% | <i>\$1,525.70</i> |
| EWPP PremierPLS4HROnsite H35370 | 98508-H35370 | \$ 2,258.00 | 6% | <i>\$2,138.44</i> |
| EWPP PremierPLS4HROnsite H35375 | 98508-H35375 | \$ 1,602.00 | 6% | <i>\$1,517.17</i> |
| EWPP PremierPLS4HROnsite H35376 | 98508-H35376 | \$ 2,399.00 | 6% | <i>\$2,271.97</i> |
| EWPP PremierPLS4HROnsite H35377 | 98508-H35377 | \$ 1,006.00 | 6% | <i>\$952.73</i> |
| EWPP PremierPLS4HROnsite H35378 | 98508-H35378 | \$ 1,602.00 | 6% | <i>\$1,517.17</i> |
| EWPP PremierPLS4HROnsite H35379 | 98508-H35379 | \$ 1,006.00 | 6% | <i>\$952.73</i> |
| EWPP PremierPLS4HROnsite H35380 | 98508-H35380 | \$ 1,803.00 | 6% | <i>\$1,707.53</i> |
| EWPP PremierPLS4HROnsite H35381 | 98508-H35381 | \$ 2,204.00 | 6% | <i>\$2,087.30</i> |
| EWPP PremierPLS4HROnsite H35384 | 98508-H35384 | \$ 784.00 | 6% | <i>\$742.49</i> |
| EWPP PremierPLS4HROnsite H35385 | 98508-H35385 | \$ 1,051.00 | 6% | <i>\$995.35</i> |
| EWPP PremierPLS4HROnsite H35386 | 98508-H35386 | \$ 1,743.00 | 6% | <i>\$1,650.71</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLS4HROnsite H35387 | 98508-H35387 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPP PremierPLS4HROnsite H35388 | 98508-H35388 | \$ 1,199.00 | 6% | <i>\$1,135.51</i> |
| EWPP PremierPLS4HROnsite H35389 | 98508-H35389 | \$ 674.00 | 6% | <i>\$638.31</i> |
| EWPP PremierPLS4HROnsite H35390 | 98508-H35390 | \$ 582.00 | 6% | <i>\$551.18</i> |
| EWPP PremierPLS4HROnsite H35391 | 98508-H35391 | \$ 1,285.00 | 6% | <i>\$1,216.96</i> |
| EWPP PremierPLS4HROnsite H35392 | 98508-H35392 | \$ 1,965.00 | 6% | <i>\$1,860.95</i> |
| EWPP PremierPLS4HROnsite H35393 | 98508-H35393 | \$ 2,613.00 | 6% | <i>\$2,474.64</i> |
| EWPP PremierPLS4HROnsite H35394 | 98508-H35394 | \$ 473.00 | 6% | <i>\$447.95</i> |
| EWPP PremierPLS4HROnsite H35395 | 98508-H35395 | \$ 395.00 | 6% | <i>\$374.08</i> |
| EWPP PremierPLS4HROnsite H35396 | 98508-H35396 | \$ 473.00 | 6% | <i>\$447.95</i> |
| EWPP PremierPLS4HROnsite H35397 | 98508-H35397 | \$ 395.00 | 6% | <i>\$374.08</i> |
| EWPP PremierPLS4HROnsite H35398 | 98508-H35398 | \$ 1,218.00 | 6% | <i>\$1,153.51</i> |
| EWPP PremierPLS4HROnsite H35399 | 98508-H35399 | \$ 1,484.00 | 6% | <i>\$1,405.42</i> |
| EWPP PremierPLS4HROnsite H35400 | 98508-H35400 | \$ 1,634.00 | 6% | <i>\$1,547.48</i> |
| EWPP PremierPLS4HROnsite H35401 | 98508-H35401 | \$ 876.00 | 6% | <i>\$829.62</i> |
| EWPP PremierPLS4HROnsite H35415 | 98508-H35415 | \$ 540.00 | 6% | <i>\$511.41</i> |
| EWPP PremierPLS4HROnsite H35416 | 98508-H35416 | \$ 540.00 | 6% | <i>\$511.41</i> |
| EWPP PremierPLS4HROnsite H35426 | 98508-H35426 | \$ 674.00 | 6% | <i>\$638.31</i> |
| EWPP PremierPLS4HROnsite H35427 | 98508-H35427 | \$ 1,632.00 | 6% | <i>\$1,545.59</i> |
| EWPP PremierPLS4HROnsite H35428 | 98508-H35428 | \$ 582.00 | 6% | <i>\$551.18</i> |
| EWPP PremierPLS4HROnsite H35429 | 98508-H35429 | \$ 1,285.00 | 6% | <i>\$1,216.96</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLS4HROn-site H35430 | 98508-H35430 | \$ 2,018.00 | 6% | <i>\$1,911.15</i> |
| EWPPPremierPLS4HROn-site H35431 | 98508-H35431 | \$ 2,018.00 | 6% | <i>\$1,911.15</i> |
| EWPPPremierPLS4HROn-site H35432 | 98508-H35432 | \$ 1,983.00 | 6% | <i>\$1,878.00</i> |
| EWPPPremierPLS4HROn-site H35433 | 98508-H35433 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPPPremierPLS4HROn-site H35434 | 98508-H35434 | \$ 2,381.00 | 6% | <i>\$2,254.93</i> |
| EWPPPremierPLS4HROn-site H35435 | 98508-H35435 | \$ 2,381.00 | 6% | <i>\$2,254.93</i> |
| EWPPPremierPLS4HROn-site H35436 | 98508-H35436 | \$ 3,169.00 | 6% | <i>\$3,001.20</i> |
| EWPPPremierPLS4HROn-site H35437 | 98508-H35437 | \$ 3,169.00 | 6% | <i>\$3,001.20</i> |
| EWPPPremierPLS4HROn-site H35438 | 98508-H35438 | \$ 3,169.00 | 6% | <i>\$3,001.20</i> |
| EWPPPremierPLS4HROn-site H35439 | 98508-H35439 | \$ 3,169.00 | 6% | <i>\$3,001.20</i> |
| EWPPPremierPLS4HROn-site H35440 | 98508-H35440 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPPPremierPLS4HROn-site H35441 | 98508-H35441 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPPPremierPLS4HROn-site H35442 | 98508-H35442 | \$ 2,244.00 | 6% | <i>\$2,125.18</i> |
| EWPPPremierPLS4HROn-site H35443 | 98508-H35443 | \$ 6,730.00 | 6% | <i>\$6,373.65</i> |
| EWPPPremierPLS4HROn-site H35444 | 98508-H35444 | \$ 7,127.00 | 6% | <i>\$6,749.63</i> |
| EWPPPremierPLS4HROn-site H35445 | 98508-H35445 | \$ 6,439.00 | 6% | <i>\$6,098.05</i> |
| EWPPPremierPLS4HROn-site H35446 | 98508-H35446 | \$ 6,316.00 | 6% | <i>\$5,981.57</i> |
| EWPPPremierPLS4HROn-site H35447 | 98508-H35447 | \$ 7,259.00 | 6% | <i>\$6,874.64</i> |
| EWPPPremierPLS4HROn-site H35448 | 98508-H35448 | \$ 7,015.00 | 6% | <i>\$6,643.56</i> |
| EWPPPremierPLS4HROn-site H35449 | 98508-H35449 | \$ 5,397.00 | 6% | <i>\$5,111.23</i> |
| EWPPPremierPLS4HROn-site H35450 | 98508-H35450 | \$ 5,741.00 | 6% | <i>\$5,437.01</i> |

| | | | | |
|---|-------------------------|--------------|----|--------------------|
| EWPPPremierPLS4HROnsite H35451 | 98508-H35451 | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| EWPPPremierPLS4HROnsite H35452 | 98508-H35452 | \$ 13,834.00 | 6% | <i>\$13,101.49</i> |
| EWPPPremierPLS4HROnsite H35453 | 98508-H35453 | \$ 7,127.00 | 6% | <i>\$6,749.63</i> |
| EWPPPremierPLS4HROnsite H35454 | 98508-H35454 | \$ 6,730.00 | 6% | <i>\$6,373.65</i> |
| EWPP PremierPLS4HROnsite H35455 | 98508-H35455 | \$ 2,438.00 | 6% | <i>\$2,308.91</i> |
| EWPP PremierPLS4HROnsite H35456 | 98508-H35456 | \$ 2,741.00 | 6% | <i>\$2,595.86</i> |
| EWPP PremierPLS4HROnsite H35457 | 98508-H35457 | \$ 2,599.00 | 6% | <i>\$2,461.38</i> |
| EWPP PremierPLS4HROnsite H35458 | 98508-H35458 | \$ 2,754.00 | 6% | <i>\$2,608.18</i> |
| EWPP PremierPLS4HROnsite H35471 | 98508-H35471 | \$ 2,438.00 | 6% | <i>\$2,308.91</i> |
| EWPPPremierPLS4HROnsite H35600 | 98508-H35600 | \$ 1,706.00 | 6% | <i>\$1,615.67</i> |
| EWPPPremierPLS4HROnsite H35601 | 98508-H35601 | \$ 1,706.00 | 6% | <i>\$1,615.67</i> |
| EWPPPremierPLS4HROnsite H35602 | 98508-H35602 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPPPremierPLS4HROnsite H35603 | 98508-H35603 | \$ 2,119.00 | 6% | <i>\$2,006.80</i> |
| EWPPPremierPLS4HROnsite H35604 | 98508-H35604 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H35605 | 98508-H35605 | \$ 2,356.00 | 6% | <i>\$2,231.25</i> |
| EWPPPremierPLS4HROnsite H35606 | 98508-H35606 | \$ 2,500.00 | 6% | <i>\$2,367.63</i> |
| EWPPPremierPLS4HROnsite H35607 | 98508-H35607 | \$ 2,500.00 | 6% | <i>\$2,367.63</i> |
| EWPP PremierPLS4HROnsite ISW-24W-4X | 98508-ISW- 24W-4X | \$ 1,460.00 | 6% | <i>\$1,382.69</i> |
| EWPP PremierPLS4HROnsite ISW-4W-4WS-4X | 98508-ISW-4W- 4WS-4X | \$ 1,736.00 | 6% | <i>\$1,644.08</i> |
| EWPPPremierPLS4HROnsite MSM128 | 98508- MSM128 | \$ 4,918.00 | 6% | <i>\$4,657.59</i> |
| EWPPPremierPLS4HROnsite MSM48C | 98508- MSM48C | \$ 3,201.00 | 6% | <i>\$3,031.51</i> |

| | | | | |
|---|---------------------------------|--------------|-----|--------------------|
| EWPP PremierPLS4HROnsi SLX9150-48XT-DC-F | 98508- SLX9150- 48XT-DC-F | \$ 5,114.00 | 6% | <i>\$4,843.21</i> |
| EWPP PremierPLS4HROnsi SLX9150-48XT-DC-R | 98508- SLX9150- 48XT-DC-R | \$ 5,639.00 | 6% | <i>\$5,340.41</i> |
| EWPP PremierPLS4HROnsit SLX9150-48Y-DC-F | 98508- SLX9150-48Y- DC-F | \$ 4,987.00 | 6% | <i>\$4,722.94</i> |
| EWPP PremierPLS4HROnsit SLX9150-48Y-DC-R | 98508- SLX9150-48Y- DC-R | \$ 5,498.00 | 6% | <i>\$5,206.88</i> |
| EWPP PremierPLS4HROnsite SLX9740-40C | 98508- SLX9740-40C | \$ 19,585.00 | 6% | <i>\$18,547.97</i> |
| EWPP PremierPLS4HROnsiteSLX9740- 40C-AC-F | 98508- SLX9740-40C- AC-F | \$ 19,585.00 | 6% | <i>\$18,547.97</i> |
| EWPP PremierPLS4HROnsiteSLX9740- 40C-AC-R | 98508- SLX9740-40C- AC-R | \$ 19,585.00 | 10% | <i>\$17,758.70</i> |
| EWPP PremierPLS4HROnsiteSLX9740- 40C-DC-F | 98508- SLX9740-40C- DC-F | \$ 19,585.00 | 6% | <i>\$18,547.97</i> |
| EWPP PremierPLS4HROnsite SLX9740-80C | 98508- SLX9740-80C | \$ 35,854.00 | 6% | <i>\$33,955.53</i> |
| EWPP PremierPLS4HROnsiteSLX9740- 80C-AC-F | 98508- SLX9740-80C- AC-F | \$ 35,854.00 | 6% | <i>\$33,955.53</i> |
| EWPP PremierPLS4HROnsiteSLX9740- 80C-AC-R | 98508- SLX9740-80C- AC-R | \$ 35,854.00 | 10% | <i>\$32,510.61</i> |
| EWPP PremierPLS4HROnsiteSLX9740- 80C-DC-F | 98508- SLX9740-80C- DC-F | \$ 35,854.00 | 6% | <i>\$33,955.53</i> |
| EWPP PremierPLS4HROnsite V300-8P-2X | 98508-V300- 8P-2X | \$ 963.00 | 6% | <i>\$912.01</i> |
| EWPP PremierPLS4HROnsite V300-8T-2X | 98508-V300- 8T-2X | \$ 889.00 | 6% | <i>\$841.93</i> |
| EWPP PremierPLS4HROnsite V300HT-8P-2X | 98508-V300HT- 8P-2X | \$ 1,271.00 | 6% | <i>\$1,203.70</i> |

| | | | | |
|---|---|-------------|----|------------|
| EWPP PremierPLS4HROnsite V300HT-8T-2X | 98508-V300HT- 8T-2X | \$ 1,052.00 | 6% | \$996.30 |
| EWPPPremierPLS4HROnsite VIM-SS | 98508-VIM-SS | \$ 688.00 | 6% | \$651.57 |
| EWPPPremierPLS4HROnsite VIM-SS | 98508-VIM- SSV80 | \$ 891.00 | 6% | \$843.82 |
| EWPPPremierPLS4HROnsite VIM2-S | 98508-VIM2- SS | \$ 696.00 | 6% | \$659.15 |
| EWPPPremierPLS4HROnsite VIM2-S | 98508-VIM2- SS128 | \$ 1,380.00 | 6% | \$1,306.93 |
| EWPPPremierPLS4HROnsite VIM2-V | 98508-VIM2- V80 | \$ 1,473.00 | 6% | \$1,395.00 |
| EWPPPremierPLS4HROnsite VIM210 | 98508- VIM210G4X | \$ 2,190.00 | 6% | \$2,074.04 |
| EWPP PremPLS4HROns VSP4900-12MXU-12XE | 98508- VSP4900- 12MXU-12XE | \$ 2,873.00 | 6% | \$2,720.87 |
| EWPP PremPLS4HROns VSP4900-12MXU-12XE-B1 | 98508- VSP4900- 12MXU-12XE- B1 | \$ 2,873.00 | 6% | \$2,720.87 |
| EWPP PremierPLS4HROnsite VSP4900-24S | 98508- VSP4900-24S | \$ 2,079.00 | 6% | \$1,968.92 |
| EWPP PremierPLS4HROnsite VSP4900-24S-B3 | 98508- VSP4900-24S- B3 | \$ 2,079.00 | 6% | \$1,968.92 |
| EWPP PremierPLS4HROnsite VSP4900-24XE | 98508- VSP4900- 24XE | \$ 2,873.00 | 6% | \$2,720.87 |
| EWPP PremierPLS4HROnsite VSP4900-24XE-B3 | 98508- VSP4900- 24XE-B3 | \$ 2,873.00 | 6% | \$2,720.87 |
| EWPP PremierPLS4HROnsite X435-24P-4S | 98508-X435- 24P-4S | \$ 1,151.00 | 6% | \$1,090.05 |
| EWPP PremierPLS4HROnsite X435-24T-4S | 98508-X435- 24T-4S | \$ 960.00 | 6% | \$909.17 |
| EWPP PremierPLS4HROnsite X435-8P-2T-W | 98508-X435- 8P-2T-W | \$ 960.00 | 6% | \$909.17 |
| EWPP PremierPLS4HROnsite X435-8P-4S | 98508-X435- 8P-4S | \$ 938.00 | 6% | \$888.33 |
| EWPP PremierPLS4HROnsite X435-8T-4S | 98508-X435- 8T-4S | \$ 895.00 | 6% | \$847.61 |

| | | | | |
|---|---------------------------|-------------|----|------------|
| EWPPPremierPLS4HROnsite X460-2 | 98508-X460- 24P | \$ 2,870.00 | 6% | \$2,718.03 |
| EWPPPremierPLS4HROnsite X460-2 | 98508-X460- 24T | \$ 2,415.00 | 6% | \$2,287.13 |
| EWPPPremierPLS4HROnsite X460-2 | 98508-X460- 24TDC | \$ 2,951.00 | 6% | \$2,794.74 |
| EWPPPremierPLS4HROnsite X460-2 | 98508-X460- 24X | \$ 3,383.00 | 6% | \$3,203.87 |
| EWPPPremierPLS4HROnsite X460-2 | 98508-X460- 24XDC | \$ 3,626.00 | 6% | \$3,434.00 |
| EWPPPremierPLS4HROnsite X460-4 | 98508-X460- 48P | \$ 3,383.00 | 6% | \$3,203.87 |
| EWPPPremierPLS4HROnsite X460-4 | 98508-X460- 48T | \$ 3,083.00 | 6% | \$2,919.76 |
| EWPPPremierPLS4HROnsite X460-4 | 98508-X460- 48TDC | \$ 3,559.00 | 6% | \$3,370.55 |
| EWPPPremierPLS4HROnsite X460-4 | 98508-X460- 48X | \$ 4,088.00 | 6% | \$3,871.54 |
| EWPPPremierPLS4HROnsite X460-4 | 98508-X460- 48XDC | \$ 4,007.00 | 6% | \$3,794.83 |
| EWPP PremierPLS4HROnsite X465-24MU | 98508-X465- 24MU | \$ 3,137.00 | 6% | \$2,970.90 |
| EWPP PremierPLS4HROnsite X465-24S | 98508-X465- 24S | \$ 2,079.00 | 6% | \$1,968.92 |
| EWPP PremierPLS4HROnsite X465-24S-B3 | 98508-X465- 24S-B3 | \$ 2,079.00 | 6% | \$1,968.92 |
| EWPP PremierPLS4HROnsite X465-24W | 98508-X465- 24W | \$ 2,079.00 | 6% | \$1,968.92 |
| EWPP PremierPLS4HROnsite X465-24XE | 98508-X465- 24XE | \$ 2,873.00 | 6% | \$2,720.87 |
| EWPP PremierPLS4HROnsite X465-24XE-B3 | 98508-X465- 24XE-B3 | \$ 2,873.00 | 6% | \$2,720.87 |
| EWPP PremierPLS4HROnsite X465-48P | 98508-X465- 48P | \$ 2,438.00 | 6% | \$2,308.91 |
| EWPP PremierPLS4HROnsite X465-48T | 98508-X465- 48T | \$ 2,387.00 | 6% | \$2,260.61 |
| EWPP PremierPLS4HROnsite X465-48W | 98508-X465- 48W | \$ 2,739.00 | 6% | \$2,593.97 |
| EWPP PremierPLS4HROnsite X465i-48W | 98508-X465i- 48W | \$ 3,101.00 | 6% | \$2,936.80 |
| EWPP PremierPLS4HROnsite X465i-48W-B1-S1 | 98508-X465i- 48W-B1-S1 | \$ 3,101.00 | 6% | \$2,936.80 |

| | | | | |
|---|---------------------------|-------------|----|-------------------|
| EWPP PremierPLS4HROnsite X465i-48W-B2-S1 | 98508-X465i- 48W-B2-S1 | \$ 3,101.00 | 6% | <i>\$2,936.80</i> |
| EWPPPremierPLS4HROnsite X480-2 | 98508-X480- 24X | \$ 3,785.00 | 6% | <i>\$3,584.58</i> |
| EWPPPremierPLS4HROnsite X480-4 | 98508-X480- 48T | \$ 3,383.00 | 6% | <i>\$3,203.87</i> |
| EWPPPremierPLS4HROnsite X480-4 | 98508-X480- 48X | \$ 4,665.00 | 6% | <i>\$4,417.99</i> |
| EWPP PremierPLS4HROnsite X695-48Y-8C | 98508-X695- 48Y-8C | \$ 5,713.00 | 6% | <i>\$5,410.50</i> |
| EWPP PremierPLS4HROnsite XA1440 | 98508-XA1440 | \$ 1,219.00 | 6% | <i>\$1,154.45</i> |
| EWPP PremierPLS4HROnsite XA1480 | 98508-XA1480 | \$ 1,370.00 | 6% | <i>\$1,297.46</i> |
| EWPPPremierPLS4HROnsite XGM3-2 | 98508-XGM3- 2SF | \$ 891.00 | 6% | <i>\$843.82</i> |
| EWPP PremierPLS4HROnsite XR600 | 98508-XR600 | \$ 1,280.00 | 6% | <i>\$1,212.22</i> |
| EWPP PremeirPLSNBDOnsite 1130C | 98511-1130C | \$ 2,840.00 | 6% | <i>\$2,689.62</i> |
| EWPP PremierPLSNBDOnsite 16119 | 98511-16119 | \$ 797.00 | 6% | <i>\$754.80</i> |
| EWPP PremierPLSNBDOnsite 16120 | 98511-16120 | \$ 888.00 | 6% | <i>\$840.98</i> |
| EWPP PremierPLSNBDOnsite 16126 | 98511-16126 | \$ 797.00 | 6% | <i>\$754.80</i> |
| EWPP PremierPLSNBDOnsite 16127 | 98511-16127 | \$ 835.00 | 6% | <i>\$790.79</i> |
| EWPP PremierPLSNBDOnsite 16172 | 98511-16172 | \$ 1,663.00 | 6% | <i>\$1,574.94</i> |
| EWPPPremierPLSNBDOnsite 16172T | 98511-16172T | \$ 1,781.00 | 6% | <i>\$1,686.70</i> |
| EWPP PremierPLSNBDOnsite 16173 | 98511-16173 | \$ 1,670.00 | 6% | <i>\$1,581.57</i> |
| EWPPPremierPLSNBDOnsite 16173T | 98511-16173T | \$ 1,786.00 | 6% | <i>\$1,691.43</i> |
| EWPP PremierPLSNBDOnsite 16174 | 98511-16174 | \$ 1,881.00 | 6% | <i>\$1,781.40</i> |
| EWPP PremierPLSNBDOnsite 16175 | 98511-16175 | \$ 1,915.00 | 6% | <i>\$1,813.60</i> |
| EWPP PremierPLSNBDOnsite 16176 | 98511-16176 | \$ 1,840.00 | 6% | <i>\$1,742.57</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLSNBDOnsite 16177 | 98511-16177 | \$ 1,734.00 | 6% | <i>\$1,642.18</i> |
| EWPPPremierPLSNBDOnsite 16177T | 98511-16177T | \$ 1,995.00 | 6% | <i>\$1,889.36</i> |
| EWPP PremierPLSNBDOnsite 16178 | 98511-16178 | \$ 2,083.00 | 6% | <i>\$1,972.71</i> |
| EWPP PremierPLSNBDOnsite 16179 | 98511-16179 | \$ 2,107.00 | 6% | <i>\$1,995.43</i> |
| EWPPPremierPLSNBDOnsite 16179T | 98511-16179T | \$ 2,261.00 | 6% | <i>\$2,141.28</i> |
| EWPPPremierPLSNBDOnsite 16301T | 98511-16301T | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWPPPremierPLSNBDOnsite 16303T | 98511-16303T | \$ 3,336.00 | 6% | <i>\$3,159.36</i> |
| EWPPPremierPLSNBDOnsite 16304T | 98511-16304T | \$ 4,059.00 | 6% | <i>\$3,844.08</i> |
| EWPPPremierPLSNBDOnsite 16401T | 98511-16401T | \$ 2,284.00 | 6% | <i>\$2,163.06</i> |
| EWPPPremierPLSNBDOnsite 16402T | 98511-16402T | \$ 2,805.00 | 6% | <i>\$2,656.48</i> |
| EWPPPremierPLSNBDOnsite 16403T | 98511-16403T | \$ 2,627.00 | 6% | <i>\$2,487.90</i> |
| EWPPPremierPLSNBDOnsite 16404T | 98511-16404T | \$ 2,627.00 | 6% | <i>\$2,487.90</i> |
| EWPPPremierPLSNBDOnsite 16405T | 98511-16405T | \$ 3,060.00 | 6% | <i>\$2,897.97</i> |
| EWPPPremierPLSNBDOnsite 16406T | 98511-16406T | \$ 3,647.00 | 6% | <i>\$3,453.89</i> |
| EWPP PremierPLSNBDOnsite 16431 | 98511-16431 | \$ 2,753.00 | 6% | <i>\$2,607.23</i> |
| EWPP PremierPLSNBDOnsite 16432 | 98511-16432 | \$ 2,845.00 | 6% | <i>\$2,694.36</i> |
| EWPP PremierPLSNBDOnsite 16440 | 98511-16440 | \$ 2,179.00 | 6% | <i>\$2,063.62</i> |
| EWPP PremierPLSNBDOnsite 16441 | 98511-16441 | \$ 2,080.00 | 6% | <i>\$1,969.86</i> |
| EWPP PremierPLSNBDOnsite 16442 | 98511-16442 | \$ 835.00 | 6% | <i>\$790.79</i> |
| EWPP PremierPLSNBDOnsite 16444 | 98511-16444 | \$ 638.00 | 6% | <i>\$604.22</i> |
| EWPP PremierPLSNBDOnsite 16501 | 98511-16501 | \$ 1,485.00 | 6% | <i>\$1,406.37</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite 16501T | 98511-16501T | \$ 1,549.00 | 6% | <i>\$1,466.98</i> |
| EWPP PremierPLSNBDOnsite 16502 | 98511-16502 | \$ 1,580.00 | 6% | <i>\$1,496.34</i> |
| EWPPPremierPLSNBDOnsite 16502T | 98511-16502T | \$ 1,637.00 | 6% | <i>\$1,550.32</i> |
| EWPP PremierPLSNBDOnsite 16503 | 98511-16503 | \$ 1,520.00 | 6% | <i>\$1,439.52</i> |
| EWPPPremierPLSNBDOnsite 16503T | 98511-16503T | \$ 1,593.00 | 6% | <i>\$1,508.65</i> |
| EWPP PremierPLSNBDOnsite 16504 | 98511-16504 | \$ 1,681.00 | 6% | <i>\$1,591.99</i> |
| EWPPPremierPLSNBDOnsite 16504T | 98511-16504T | \$ 1,761.00 | 6% | <i>\$1,667.76</i> |
| EWPP PremierPLSNBDOnsite 16505 | 98511-16505 | \$ 1,698.00 | 6% | <i>\$1,608.09</i> |
| EWPPPremierPLSNBDOnsite 16505T | 98511-16505T | \$ 1,827.00 | 6% | <i>\$1,730.26</i> |
| EWPP PremierPLSNBDOnsite 16506 | 98511-16506 | \$ 1,945.00 | 6% | <i>\$1,842.01</i> |
| EWPPPremierPLSNBDOnsite 16506T | 98511-16506T | \$ 2,120.00 | 6% | <i>\$2,007.75</i> |
| EWPP PremierPLSNBDOnsite 16507 | 98511-16507 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite 16507T | 98511-16507T | \$ 2,020.00 | 6% | <i>\$1,913.04</i> |
| EWPP PremierPLSNBDOnsite 16508 | 98511-16508 | \$ 2,061.00 | 6% | <i>\$1,951.87</i> |
| EWPPPremierPLSNBDOnsite 16508T | 98511-16508T | \$ 2,218.00 | 6% | <i>\$2,100.56</i> |
| EWPP PremierPLSNBDOnsite 16509 | 98511-16509 | \$ 2,061.00 | 6% | <i>\$1,951.87</i> |
| EWPPPremierPLSNBDOnsite 16509T | 98511-16509T | \$ 2,218.00 | 6% | <i>\$2,100.56</i> |
| EWPP PremierPLSNBDOnsite 16510 | 98511-16510 | \$ 2,218.00 | 6% | <i>\$2,100.56</i> |
| EWPPPremierPLSNBDOnsite 16510T | 98511-16510T | \$ 2,399.00 | 6% | <i>\$2,271.97</i> |
| EWPP PremierPLSNBDOnsite 16513 | 98511-16513 | \$ 1,879.00 | 6% | <i>\$1,779.51</i> |
| EWPP PremierPLSNBDOnsite 16514 | 98511-16514 | \$ 2,174.00 | 6% | <i>\$2,058.89</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLSNBDOnsite 16515 | 98511-16515 | \$ 1,381.00 | 6% | <i>\$1,307.88</i> |
| EWPP PremierPLSNBDOnsite 16516 | 98511-16516 | \$ 1,401.00 | 6% | <i>\$1,326.82</i> |
| EWPP PremierPLSNBDOnsite 16517 | 98511-16517 | \$ 1,563.00 | 6% | <i>\$1,480.24</i> |
| EWPP PremierPLSNBDOnsite 16518 | 98511-16518 | \$ 1,520.00 | 6% | <i>\$1,439.52</i> |
| EWPP PremierPLSNBDOnsite 16519 | 98511-16519 | \$ 1,593.00 | 6% | <i>\$1,508.65</i> |
| EWPP PremierPLSNBDOnsite 16520 | 98511-16520 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWPP PremierPLSNBDOnsite 16530 | 98511-16530 | \$ 1,527.00 | 6% | <i>\$1,446.15</i> |
| EWPP PremierPLSNBDOnsite 16531 | 98511-16531 | \$ 1,588.00 | 6% | <i>\$1,503.92</i> |
| EWPPPremierPLSNBDOnsite 16531T | 98511-16531T | \$ 1,635.00 | 6% | <i>\$1,548.43</i> |
| EWPP PremierPLSNBDOnsite 16532 | 98511-16532 | \$ 1,588.00 | 6% | <i>\$1,503.92</i> |
| EWPPPremierPLSNBDOnsite 16532T | 98511-16532T | \$ 1,635.00 | 6% | <i>\$1,548.43</i> |
| EWPP PremierPLSNBDOnsite 16533 | 98511-16533 | \$ 1,695.00 | 6% | <i>\$1,605.25</i> |
| EWPPPremierPLSNBDOnsite 16533T | 98511-16533T | \$ 1,766.00 | 6% | <i>\$1,672.49</i> |
| EWPP PremierPLSNBDOnsite 16534 | 98511-16534 | \$ 1,727.00 | 6% | <i>\$1,635.56</i> |
| EWPP PremierPLSNBDOnsite 16535 | 98511-16535 | \$ 1,911.00 | 6% | <i>\$1,809.81</i> |
| EWPP PremierPLSNBDOnsite 16535A | 98511-16535A | \$ 1,911.00 | 6% | <i>\$1,809.81</i> |
| EWPPPremierPLSNBDOnsite 16535T | 98511-16535T | \$ 2,017.00 | 6% | <i>\$1,910.20</i> |
| EWPP PremierPLSNBDOnsite 16536 | 98511-16536 | \$ 1,478.00 | 6% | <i>\$1,399.74</i> |
| EWPP PremierPLSNBDOnsite 16537 | 98511-16537 | \$ 1,577.00 | 6% | <i>\$1,493.50</i> |
| EWPP PremierPLSNBDOnsite 16538 | 98511-16538 | \$ 1,645.00 | 6% | <i>\$1,557.90</i> |
| EWPPPremierPLSNBDOnsite 16538T | 98511-16538T | \$ 1,903.00 | 6% | <i>\$1,802.24</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLSNBDOnsite 16539 | 98511-16539 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPP PremierPLSNBDOnsite 16540 | 98511-16540 | \$ 1,619.00 | 6% | <i>\$1,533.27</i> |
| EWPP PremierPLSNBDOnsite 16541 | 98511-16541 | \$ 1,368.00 | 6% | <i>\$1,295.56</i> |
| EWPP PremierPLSNBDOnsite 16560 | 98511-16560 | \$ 1,313.00 | 6% | <i>\$1,243.48</i> |
| EWPP PremierPLSNBDOnsite 16561 | 98511-16561 | \$ 1,352.00 | 6% | <i>\$1,280.41</i> |
| EWPP PremierPLSNBDOnsite 16562 | 98511-16562 | \$ 1,382.00 | 6% | <i>\$1,308.82</i> |
| EWPP PremierPLSNBDOnsite 16563 | 98511-16563 | \$ 1,437.00 | 6% | <i>\$1,360.91</i> |
| EWPP PremierPLSNBDOnsite 16564 | 98511-16564 | \$ 1,486.00 | 6% | <i>\$1,407.32</i> |
| EWPP PremierPLSNBDOnsite 16565 | 98511-16565 | \$ 1,624.00 | 6% | <i>\$1,538.01</i> |
| EWPP PremierPLSNBDOnsite 16566 | 98511-16566 | \$ 1,277.00 | 6% | <i>\$1,209.38</i> |
| EWPP PremierPLSNBDOnsite 16567 | 98511-16567 | \$ 1,335.00 | 6% | <i>\$1,264.31</i> |
| EWPP PremierPLSNBDOnsite 16568 | 98511-16568 | \$ 1,314.00 | 6% | <i>\$1,244.42</i> |
| EWPP PremierPLSNBDOnsite 16569 | 98511-16569 | \$ 1,368.00 | 6% | <i>\$1,295.56</i> |
| EWPP PremierPLSNBDOnsite 16570 | 98511-16570 | \$ 1,381.00 | 6% | <i>\$1,307.88</i> |
| EWPP PremierPLSNBDOnsite 16571 | 98511-16571 | \$ 1,486.00 | 6% | <i>\$1,407.32</i> |
| EWPP PremierPLSNBDOnsite 16701 | 98511-16701 | \$ 1,790.00 | 6% | <i>\$1,695.22</i> |
| EWPP PremierPLSNBDOnsite 16702 | 98511-16702 | \$ 2,059.00 | 6% | <i>\$1,949.98</i> |
| EWPP PremierPLSNBDOnsite 16703 | 98511-16703 | \$ 2,009.00 | 6% | <i>\$1,902.62</i> |
| EWPPPremierPLSNBDOnsite 16703T | 98511-16703T | \$ 2,166.00 | 6% | <i>\$2,051.31</i> |
| EWPP PremierPLSNBDOnsite 16704 | 98511-16704 | \$ 2,280.00 | 6% | <i>\$2,159.27</i> |
| EWPPPremierPLSNBDOnsite 16704T | 98511-16704T | \$ 1,992.00 | 6% | <i>\$1,886.52</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLSNBDOnsite 16705 | 98511-16705 | \$ 2,059.00 | 6% | <i>\$1,949.98</i> |
| EWPPPremierPLSNBDOnsite 16705T | 98511-16705T | \$ 2,224.00 | 6% | <i>\$2,106.24</i> |
| EWPP PremierPLSNBDOnsite 16706 | 98511-16706 | \$ 2,613.00 | 6% | <i>\$2,474.64</i> |
| EWPPPremierPLSNBDOnsite 16706T | 98511-16706T | \$ 2,836.00 | 6% | <i>\$2,685.83</i> |
| EWPP PremierPLSNBDOnsite 16710 | 98511-16710 | \$ 676.00 | 6% | <i>\$640.21</i> |
| EWPPPremierPLSNBDOnsite 16710T | 98511-16710T | \$ 733.00 | 6% | <i>\$694.19</i> |
| EWPP PremierPLSNBDOnsite 16711 | 98511-16711 | \$ 530.00 | 6% | <i>\$501.94</i> |
| EWPPPremierPLSNBDOnsite 16711T | 98511-16711T | \$ 566.00 | 6% | <i>\$536.03</i> |
| EWPP PremierPLSNBDOnsite 16712 | 98511-16712 | \$ 570.00 | 6% | <i>\$539.82</i> |
| EWPPPremierPLSNBDOnsite 16712T | 98511-16712T | \$ 599.00 | 6% | <i>\$567.28</i> |
| EWPP PremierPLSNBDOnsite 16713 | 98511-16713 | \$ 490.00 | 6% | <i>\$464.05</i> |
| EWPPPremierPLSNBDOnsite 16713T | 98511-16713T | \$ 526.00 | 6% | <i>\$498.15</i> |
| EWPP PremierPLSNBDOnsite 16715 | 98511-16715 | \$ 505.00 | 6% | <i>\$478.26</i> |
| EWPPPremierPLSNBDOnsite 16715T | 98511-16715T | \$ 566.00 | 6% | <i>\$536.03</i> |
| EWPP PremierPLSNBDOnsite 16716 | 98511-16716 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWPPPremierPLSNBDOnsite 16716T | 98511-16716T | \$ 1,923.00 | 6% | <i>\$1,821.18</i> |
| EWPP PremierPLSNBDOnsite 16717 | 98511-16717 | \$ 1,895.00 | 6% | <i>\$1,794.66</i> |
| EWPP PremierPLSNBDOnsite 16718 | 98511-16718 | \$ 1,827.00 | 6% | <i>\$1,730.26</i> |
| EWPP PremierPLSNBDOnsite 16719 | 98511-16719 | \$ 1,938.00 | 6% | <i>\$1,835.38</i> |
| EWPP PremierPLSNBDOnsite 16720 | 98511-16720 | \$ 2,370.00 | 6% | <i>\$2,244.51</i> |
| EWPPPremierPLSNBDOnsite 16720T | 98511-16720T | \$ 2,755.00 | 6% | <i>\$2,609.12</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|------------|
| EWPP PremierPLSNBDOnsite 16756 | 98511-16756 | \$ 2,187.00 | 6% | \$2,071.20 |
| EWPPPremierPLSNBDOnsite 16756T | 98511-16756T | \$ 2,587.00 | 6% | \$2,450.02 |
| EWPP PremierPLSNBDOnsite 16757 | 98511-16757 | \$ 2,140.00 | 6% | \$2,026.69 |
| EWPPPremierPLSNBDOnsite 16757T | 98511-16757T | \$ 2,522.00 | 6% | \$2,388.46 |
| EWPP PremeirPLSNBDOnsite 16790 | 98511-16790 | \$ 2,354.00 | 6% | \$2,229.36 |
| EWPP PremierPLSNBDOnsite 16791 | 98511-16791 | \$ 3,038.00 | 6% | \$2,877.14 |
| EWPP PremierPLSNBDOnsite 17101 | 98511-17101 | \$ 4,343.00 | 6% | \$4,113.04 |
| EWPPPremierPLSNBDOnsite 17101T | 98511-17101T | \$ 5,321.00 | 6% | \$5,039.25 |
| EWPP PremierPLSNBDOnsite 17102 | 98511-17102 | \$ 4,343.00 | 6% | \$4,113.04 |
| EWPPPremierPLSNBDOnsite 17102T | 98511-17102T | \$ 5,321.00 | 6% | \$5,039.25 |
| EWPP PremierPLSNBDOnsite 17103 | 98511-17103 | \$ 3,364.00 | 6% | \$3,185.88 |
| EWPP PremierPLSNBDOnsite 17103C | 98511-17103C | \$ 3,266.00 | 6% | \$3,093.07 |
| EWPPPremierPLSNBDOnsite 17103T | 98511-17103T | \$ 4,096.00 | 6% | \$3,879.12 |
| EWPP PremierPLSNBDOnsite 17104 | 98511-17104 | \$ 3,364.00 | 6% | \$3,185.88 |
| EWPPPremierPLSNBDOnsite 17104T | 98511-17104T | \$ 4,096.00 | 6% | \$3,879.12 |
| EWPP PremierPLSNBDOnsite 17121 | 98511-17121 | \$ 1,091.00 | 6% | \$1,033.23 |
| EWPP PremierPLSNBDOnsite 17122 | 98511-17122 | \$ 812.00 | 6% | \$769.00 |
| EWPP PremierPLSNBDOnsite 17200 | 98511-17200 | \$ 6,189.00 | 6% | \$5,861.29 |
| EWPPPremierPLSNBDOnsite 17200T | 98511-17200T | \$ 6,960.00 | 6% | \$6,591.47 |
| EWPP PremierPLSNBDOnsite 17201 | 98511-17201 | \$ 6,189.00 | 6% | \$5,861.29 |
| EWPPPremierPLSNBDOnsite 17201T | 98511-17201T | \$ 6,960.00 | 6% | \$6,591.47 |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLSNBDOnsite 17202 | 98511-17202 | \$ 6,189.00 | 6% | <i>\$5,861.29</i> |
| EWPPPremierPLSNBDOnsite 17202T | 98511-17202T | \$ 6,960.00 | 6% | <i>\$6,591.47</i> |
| EWPP PremierPLSNBDOnsite 17203 | 98511-17203 | \$ 6,272.00 | 6% | <i>\$5,939.90</i> |
| EWPPPremierPLSNBDOnsite 17203T | 98511-17203T | \$ 7,048.00 | 6% | <i>\$6,674.81</i> |
| EWPP PremierPLSNBDOnsite 17204 | 98511-17204 | \$ 6,272.00 | 6% | <i>\$5,939.90</i> |
| EWPPPremierPLSNBDOnsite 17204T | 98511-17204T | \$ 7,048.00 | 6% | <i>\$6,674.81</i> |
| EWPP PremierPLSNBDOnsite 17205 | 98511-17205 | \$ 6,228.00 | 6% | <i>\$5,898.23</i> |
| EWPPPremierPLSNBDOnsite 17205T | 98511-17205T | \$ 7,008.00 | 6% | <i>\$6,636.93</i> |
| EWPP PremierPLSNBDOnsite 17206 | 98511-17206 | \$ 6,228.00 | 6% | <i>\$5,898.23</i> |
| EWPPPremierPLSNBDOnsite 17206T | 98511-17206T | \$ 7,008.00 | 6% | <i>\$6,636.93</i> |
| EWPP PremierPLSNBDOnsite 17300 | 98511-17300 | \$ 4,577.00 | 6% | <i>\$4,334.65</i> |
| EWPP PremierPLSNBDOnsite 17310 | 98511-17310 | \$ 4,264.00 | 6% | <i>\$4,038.22</i> |
| EWPP PremierPLSNBDOnsite 17350 | 98511-17350 | \$ 4,459.00 | 6% | <i>\$4,222.90</i> |
| EWPP PremierPLSNBDOnsite 17360 | 98511-17360 | \$ 5,219.00 | 6% | <i>\$4,942.65</i> |
| EWPP PremierPLSNBDOnsite 17401 | 98511-17401 | \$ 1,687.00 | 6% | <i>\$1,597.67</i> |
| EWPPPremierPLSNBDOnsite 17401G | 98511-17401G | \$ 1,793.00 | 6% | <i>\$1,698.06</i> |
| EWPPPremierPLSNBDOnsite 17401T | 98511-17401T | \$ 1,785.00 | 6% | <i>\$1,690.48</i> |
| EWPP PremierPLSNBDOnsite 17402 | 98511-17402 | \$ 1,796.00 | 6% | <i>\$1,700.90</i> |
| EWPPPremierPLSNBDOnsite 17402G | 98511-17402G | \$ 1,831.00 | 6% | <i>\$1,734.05</i> |
| EWPPPremierPLSNBDOnsite 17402T | 98511-17402T | \$ 1,820.00 | 6% | <i>\$1,723.63</i> |
| EWPP PremierPLSNBDOnsite 17403 | 98511-17403 | \$ 1,892.00 | 6% | <i>\$1,791.82</i> |

| | | | | |
|---------------------------------------|---------------------|--------------|----|--------------------|
| EWPP PremierPLSNBDOnsite 17404 | 98511-17404 | \$ 1,563.00 | 6% | <i>\$1,480.24</i> |
| EWPP PremierPLSNBDOnsite 17405 | 98511-17405 | \$ 1,563.00 | 6% | <i>\$1,480.24</i> |
| EWPP PremierPLSNBDOnsite 17700 | 98511-17700 | \$ 7,296.00 | 6% | <i>\$6,909.68</i> |
| EWPP PremierPLSNBDOnsite 17701 | 98511-17701 | \$ 6,272.00 | 6% | <i>\$5,939.90</i> |
| EWPP PremierPLSNBDOnsite 17702 | 98511-17702 | \$ 6,272.00 | 6% | <i>\$5,939.90</i> |
| EWPP PremierPLSNBDOnsite 17703 | 98511-17703 | \$ 6,854.00 | 6% | <i>\$6,491.08</i> |
| EWPP PremierPLSNBDOnsite 17704 | 98511-17704 | \$ 6,854.00 | 6% | <i>\$6,491.08</i> |
| EWPP PremierPLSNBDOnsite 17705 | 98511-17705 | \$ 6,308.00 | 6% | <i>\$5,973.99</i> |
| EWPP PremierPLSNBDOnsite 17706 | 98511-17706 | \$ 6,308.00 | 6% | <i>\$5,973.99</i> |
| EWPP PremierPLSNBDOnsite 17800 | 98511-17800 | \$ 7,557.00 | 6% | <i>\$7,156.86</i> |
| EWPP PremierPLSNBDOnsite 17810 | 98511-17810 | \$ 6,291.00 | 6% | <i>\$5,957.89</i> |
| EWPP PremeirPLSNBDOnsite 18101 | 98511-18101 | \$ 704.00 | 6% | <i>\$666.72</i> |
| EWPP PremeirPLSNBDOnsite 18102 | 98511-18102 | \$ 795.00 | 6% | <i>\$752.90</i> |
| EWPP PremeirPLSNBDOnsite 18103 | 98511-18103 | \$ 834.00 | 6% | <i>\$789.84</i> |
| EWPP PremierPLSNBDOnsite 18104 | 98511-18104 | \$ 1,025.00 | 6% | <i>\$970.73</i> |
| EWPP PremierPLSNBDOnsite 18104-6PK | 98511-18104- 6PK | \$ 6,153.00 | 6% | <i>\$5,827.20</i> |
| EWPP PremierPLSNBDOnsite 30135 | 98511-30135 | \$ 3,065.00 | 6% | <i>\$2,902.71</i> |
| EWPP PremierPLSNBDOnsite 30136 | 98511-30136 | \$ 8,455.00 | 6% | <i>\$8,007.31</i> |
| EWPP PremeirPLSNBDOnsite 30137 | 98511-30137 | \$ 2,999.00 | 6% | <i>\$2,840.20</i> |
| EWPP PremeirPLSNBDOnsite 30138 | 98511-30138 | \$ 7,414.00 | 6% | <i>\$7,021.43</i> |
| EWPP PremeirPLSNBDOnsite 30139 | 98511-30139 | \$ 11,708.00 | 6% | <i>\$11,088.06</i> |

| | | | | |
|-----------------------------------|-------------|-----------|----|-----------------|
| EWPP PremierPLSNBDOnsite 30912 | 98511-30912 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLSNBDOnsite 30913 | 98511-30913 | \$ 436.00 | 6% | <i>\$412.91</i> |
| EWPP PremierPLSNBDOnsite 31012 | 98511-31012 | \$ 441.00 | 6% | <i>\$417.65</i> |
| EWPP PremierPLSNBDOnsite 31013 | 98511-31013 | \$ 441.00 | 6% | <i>\$417.65</i> |
| EWPP PremierPLSNBDOnsite 31014 | 98511-31014 | \$ 441.00 | 6% | <i>\$417.65</i> |
| EWPP PremierPLSNBDOnsite 31015 | 98511-31015 | \$ 441.00 | 6% | <i>\$417.65</i> |
| EWPP PremierPLSNBDOnsite 31016 | 98511-31016 | \$ 656.00 | 6% | <i>\$621.26</i> |
| EWPP PremierPLSNBDOnsite 31017 | 98511-31017 | \$ 656.00 | 6% | <i>\$621.26</i> |
| EWPP PremierPLSNBDOnsite 31018 | 98511-31018 | \$ 710.00 | 6% | <i>\$672.41</i> |
| EWPP PremierPLSNBDOnsite 31019 | 98511-31019 | \$ 710.00 | 6% | <i>\$672.41</i> |
| EWPP PremierPLSNBDOnsite 31025 | 98511-31025 | \$ 374.00 | 6% | <i>\$354.20</i> |
| EWPP PremierPLSNBDOnsite 31026 | 98511-31026 | \$ 374.00 | 6% | <i>\$354.20</i> |
| EWPP PremierPLSNBDOnsite 31028 | 98511-31028 | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWPP PremierPLSNBDOnsite 31029 | 98511-31029 | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWPP PremierPLSNBDOnsite 31031 | 98511-31031 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWPP PremierPLSNBDOnsite 31032 | 98511-31032 | \$ 391.00 | 6% | <i>\$370.30</i> |
| EWPP PremierPLSNBDOnsite 31034 | 98511-31034 | \$ 450.00 | 6% | <i>\$426.17</i> |
| EWPP PremierPLSNBDOnsite 31035 | 98511-31035 | \$ 450.00 | 6% | <i>\$426.17</i> |
| EWPP PremierPLSNBDOnsite 31050 | 98511-31050 | \$ 444.00 | 6% | <i>\$420.49</i> |
| EWPP PremierPLSNBDOnsite 31051 | 98511-31051 | \$ 444.00 | 6% | <i>\$420.49</i> |
| EWPP PremierPLSNBDOnsite 31055 | 98511-31055 | \$ 444.00 | 6% | <i>\$420.49</i> |

| | | | | |
|--|------------------------|-------------|-----|-------------------|
| EWPP PremierPLSNBDOnsite 31056 | 98511-31056 | \$ 444.00 | 6% | <i>\$420.49</i> |
| EWPP PremierPLSNBDOnsite 39031 | 98511-39031 | \$ 869.00 | 6% | <i>\$822.99</i> |
| EWPP PremierPLSNBDOnsite 39032 | 98511-39032 | \$ 877.00 | 6% | <i>\$830.56</i> |
| EWPP PremierPLSNBDOnsite 39033 | 98511-39033 | \$ 869.00 | 6% | <i>\$822.99</i> |
| EWPP PremierPLSNBDOnsite 39034 | 98511-39034 | \$ 869.00 | 6% | <i>\$822.99</i> |
| EWPP PremierPLSNBDOnsite 39035 | 98511-39035 | \$ 1,613.00 | 6% | <i>\$1,527.59</i> |
| EWPP PremierPLSNBDOnsite 39036 | 98511-39036 | \$ 771.00 | 6% | <i>\$730.18</i> |
| EWPP PremierPLSNBDOnsite 39037 | 98511-39037 | \$ 771.00 | 6% | <i>\$730.18</i> |
| EWPP PremierPLSNBDOnsite 39038 | 98511-39038 | \$ 883.00 | 6% | <i>\$836.25</i> |
| EWPP PremierPLSNBDOnsite 39039 | 98511-39039 | \$ 883.00 | 6% | <i>\$836.25</i> |
| EWPP PremeirPLSNBDOnsite 4120-24MW-4Y | 98511-4120- 24MW-4Y | \$ 1,633.00 | 6% | <i>\$1,546.53</i> |
| EWPP PremeirPLSNBDOnsite 4120-48MW-4Y | 98511-4120- 48MW-4Y | \$ 1,909.00 | 6% | <i>\$1,807.92</i> |
| EWPP PremeirPLSNBDOnsite 4120C | 98511-4120C | \$ 8,150.00 | 10% | <i>\$7,390.01</i> |
| EWPP PremeirPLSNBDOnsite 4120C-1 | 98511-4120C-1 | \$ 7,844.00 | 6% | <i>\$7,428.66</i> |
| EWPP PremierPLSNBDOnsite 41216 | 98511-41216 | \$ 2,488.00 | 6% | <i>\$2,356.26</i> |
| EWPP PremeirPLSNBDOnsite 4220-12P-4X | 98511-4220- 12P-4X | \$ 1,059.00 | 6% | <i>\$1,002.93</i> |
| EWPP PremeirPLSNBDOnsite 4220-12T-4X | 98511-4220- 12T-4X | \$ 992.00 | 6% | <i>\$939.47</i> |
| EWPP PremeirPLSNBDOnsite 4220-24P-4X | 98511-4220- 24P-4X | \$ 1,143.00 | 6% | <i>\$1,082.48</i> |
| EWPP PremeirPLSNBDOnsite 4220-24T-4X | 98511-4220- 24T-4X | \$ 1,068.00 | 6% | <i>\$1,011.45</i> |
| EWPP PremeirPLSNBDOnsite 4220-48P-4X | 98511-4220- 48P-4X | \$ 1,310.00 | 6% | <i>\$1,240.64</i> |
| EWPP PremeirPLSNBDOnsite 4220-48T-4X | 98511-4220- 48T-4X | \$ 1,185.00 | 6% | <i>\$1,122.25</i> |

| | | | | |
|--|-----------------------------------|--------------|----|--------------------|
| EWPP PremerPLSNBDOnsite 4220-4MW-20P-4X | 98511-4220- 4MW-20P-4X | \$ 1,269.00 | 6% | <i>\$1,201.81</i> |
| EWPP PremerPLSNBDOnsite 4220-4MW-8P-4X | 98511-4220- 4MW-8P-4X | \$ 1,135.00 | 6% | <i>\$1,074.90</i> |
| EWPP PremerPLSNBDOnsite 4220-8MW-40P-4X | 98511-4220- 8MW-40P-4X | \$ 1,478.00 | 6% | <i>\$1,399.74</i> |
| EWPP PremerPLSNBDOnsite 4220-8X | 98511-4220-8X | \$ 1,160.00 | 6% | <i>\$1,098.58</i> |
| EWPP PremierPLSNBDOnsite 48001 | 98511-48001 | \$ 10,702.00 | 6% | <i>\$10,135.33</i> |
| EWPP PremierPLSNBDOnsite 48038 | 98511-48038 | \$ 3,847.00 | 6% | <i>\$3,643.30</i> |
| EWPP PremierPLSNBDOnsite 48039 | 98511-48039 | \$ 3,847.00 | 6% | <i>\$3,643.30</i> |
| EWPP PremierPLSNBDOnsite 48040 | 98511-48040 | \$ 3,686.00 | 6% | <i>\$3,490.83</i> |
| EWPP PremierPLSNBDOnsite 48041 | 98511-48041 | \$ 3,847.00 | 6% | <i>\$3,643.30</i> |
| EWPP PremierPLSNBDOnsite 48046 | 98511-48046 | \$ 4,909.00 | 6% | <i>\$4,649.07</i> |
| EWPP PremierPLSNBDOnsite 48047 | 98511-48047 | \$ 12,334.00 | 6% | <i>\$11,680.91</i> |
| EWPP PremierPLSNBDOnsite 48051 | 98511-48051 | \$ 8,623.00 | 6% | <i>\$8,166.41</i> |
| EWPP PremierPLSNBDOnsite 48061 | 98511-48061 | \$ 10,001.00 | 6% | <i>\$9,471.45</i> |
| EWPP PremierPLSNBDOnsite 48062 | 98511-48062 | \$ 15,731.00 | 6% | <i>\$14,898.04</i> |
| EWPP PremerPLSNBDOnsite 5320-16P-4XE | 98511-5320- 16P-4XE | \$ 1,352.00 | 6% | <i>\$1,280.41</i> |
| EWPP PremerPLSNBDOnsite 5320-16P-4XE-DC | 98511-5320- 16P-4XE-DC | \$ 1,423.00 | 6% | <i>\$1,347.65</i> |
| EWPP PremerPLSNBDOnsite 5320-24P-8XE | 98511-5320- 24P-8XE | \$ 1,376.00 | 6% | <i>\$1,303.14</i> |
| EWPP PremierPLSNBDOn 5320- 24T-24S-4XE-XT | 98511-5320- 24T-24S-4XE- XT | \$ 1,247.00 | 6% | <i>\$1,180.97</i> |
| EWPP PremerPLSNBDOnsite 5320-24T-4X-XT | 98511-5320- 24T-4X-XT | \$ 1,044.00 | 6% | <i>\$988.72</i> |
| EWPP PremerPLSNBDOnsite 5320-24T-8XE | 98511-5320- 24T-8XE | \$ 1,270.00 | 6% | <i>\$1,202.75</i> |

| | | | | |
|---|----------------------------------|-------------|----|-------------------|
| EWPP PremeirPLSNBDOnsite 5320-48P-8XE | 98511-5320- 48P-8XE | \$ 1,692.00 | 6% | <i>\$1,602.41</i> |
| EWPP PremeirPLSNBDOnsite 5320-48T-8XE | 98511-5320- 48T-8XE | \$ 1,504.00 | 6% | <i>\$1,424.36</i> |
| EWPP PremPLSNBDOnsite 5420F-16MW-32P-4XE | 98511-5420F- 16MW-32P- 4XE | \$ 2,387.00 | 6% | <i>\$2,260.61</i> |
| EWPP PremeirPLSNBDOnsi 5420F-16W-32P-4XE | 98511-5420F- 16W-32P-4XE | \$ 2,156.00 | 6% | <i>\$2,041.84</i> |
| EWPP PremeirPLSNBDOnsite 5420F-24P-4XE | 98511-5420F- 24P-4XE | \$ 1,672.00 | 6% | <i>\$1,583.47</i> |
| EWPP PremeirPLSNBDOnsite 5420F-24S-4XE | 98511-5420F- 24S-4XE | \$ 1,741.00 | 6% | <i>\$1,648.81</i> |
| EWPP PremeirPLSNBDOnsite 5420F-24T-4XE | 98511-5420F- 24T-4XE | \$ 1,587.00 | 6% | <i>\$1,502.97</i> |
| EWPP PremeirPLSNBDOnsite 5420F-48P-4XE | 98511-5420F- 48P-4XE | \$ 1,940.00 | 6% | <i>\$1,837.28</i> |
| EWPP PremeirPLSNBDOnsite 5420F-48P-4XL | 98511-5420F- 48P-4XL | \$ 2,079.00 | 6% | <i>\$1,968.92</i> |
| EWPP PremeirPLSNBDOnsite 5420F-48T-4XE | 98511-5420F- 48T-4XE | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWPP PremeirPLSNBDOnsit 5420F-8W-16P-4XE | 98511-5420F- 8W-16P-4XE | \$ 1,769.00 | 6% | <i>\$1,675.33</i> |
| EWPP PremPLSNBDOnsite 5420M-16MW-32P-4YE | 98511-5420M- 16MW-32P- 4YE | \$ 2,292.00 | 6% | <i>\$2,170.64</i> |
| EWPP PremeirPLSNBDOnsite 5420M-24T-4YE | 98511-5420M- 24T-4YE | \$ 1,762.00 | 6% | <i>\$1,668.70</i> |
| EWPP PremeirPLSNBDOnsite 5420M-24W-4YE | 98511-5420M- 24W-4YE | \$ 1,577.00 | 6% | <i>\$1,493.50</i> |
| EWPP PremeirPLSNBDOnsite 5420M-48T-4YE | 98511-5420M- 48T-4YE | \$ 1,978.00 | 6% | <i>\$1,873.26</i> |
| EWPP PremeirPLSNBDOnsite 5420M-48W-4YE | 98511-5420M- 48W-4YE | \$ 2,104.00 | 6% | <i>\$1,992.59</i> |
| EWPP PREMIERPLUS NBDONSITE 5520-12MW-36W | 98511-5520- 12MW-36W | \$ 2,473.00 | 6% | <i>\$2,342.05</i> |
| EWPP PREMIERPLUS NBD ONSITE 5520-24T | 98511-5520- 24T | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |
| EWPP PREMIERPL NBD ON 5520-24T-ACDC-BASE | 98511-5520- 24T-ACDC- BASE | \$ 1,705.00 | 6% | <i>\$1,614.72</i> |

| | | | | |
|---|-----------------------------------|-------------|-----|-------------------|
| EWPP PREMIERPLUS NBD ONSIT 5520-24T-BASE | 98511-5520- 24T-BASE | \$ 1,705.00 | 10% | <i>\$1,546.01</i> |
| EWPP PREMIERPLUS NBD ONSITE 5520-24W | 98511-5520- 24W | \$ 1,807.00 | 6% | <i>\$1,711.32</i> |
| EWPP PREMIERPLUS NBD ONSITE 5520-24X | 98511-5520- 24X | \$ 2,708.00 | 6% | <i>\$2,564.61</i> |
| EWPP PREMIERPL NBD ON 5520-24X-ACDC-BASE | 98511-5520- 24X-ACDC- BASE | \$ 2,708.00 | 6% | <i>\$2,564.61</i> |
| EWPP PREMIERPLUS NBD ONSIT 5520-24X-BASE | 98511-5520- 24X-BASE | \$ 2,708.00 | 10% | <i>\$2,455.48</i> |
| EWPP PREMIERPLUS NBD ONSITE 5520-48SE | 98511-5520- 48SE | \$ 2,585.00 | 6% | <i>\$2,448.12</i> |
| EWPP PREMIERP NBD ON 5520-48SE-ACDC-BASE | 98511-5520- 48SE-ACDC- BASE | \$ 2,585.00 | 6% | <i>\$2,448.12</i> |
| EWPP PREMIERPLUS NBD ONSI 5520-48SE-BASE | 98511-5520- 48SE-BASE | \$ 2,585.00 | 10% | <i>\$2,343.95</i> |
| EWPP PREMIERPLUS NBD ONSITE 5520-48T | 98511-5520- 48T | \$ 2,143.00 | 6% | <i>\$2,029.53</i> |
| EWPP PREMIERPL NBD ON 5520-48T-ACDC-BASE | 98511-5520- 48T-ACDC- BASE | \$ 2,143.00 | 6% | <i>\$2,029.53</i> |
| EWPP PREMIERPLUS NBD ONSIT 5520-48T-BASE | 98511-5520- 48T-BASE | \$ 2,143.00 | 10% | <i>\$1,943.17</i> |
| EWPP PREMIERPLUS NBD ONSITE 5520-48W | 98511-5520- 48W | \$ 2,236.00 | 6% | <i>\$2,117.60</i> |
| EWPP PremeirPLSNBDOnsite 5720-24MW | 98511-5720- 24MW | \$ 2,148.00 | 6% | <i>\$2,034.26</i> |
| EWPP PremeirPLSNBDOnsite 5720-24MXW | 98511-5720- 24MXW | \$ 2,147.00 | 6% | <i>\$2,033.32</i> |
| EWPP PremeirPLSNBDOnsite 5720-48MW | 98511-5720- 48MW | \$ 1,867.00 | 6% | <i>\$1,768.14</i> |
| EWPP PremeirPLSNBDOnsite 5720-48MXW | 98511-5720- 48MXW | \$ 2,707.00 | 6% | <i>\$2,563.66</i> |
| EWPP PremierPLSNBDOnsite 7520-48XT-6C | 98511-7520- 48XT-6C | \$ 3,683.00 | 6% | <i>\$3,487.99</i> |
| EWPP PremierPLSNBDOnsi 7520-48XT-6C-AC-F | 98511-7520- 48XT-6C-AC- F | \$ 3,683.00 | 6% | <i>\$3,487.99</i> |
| EWPP PremierPLSNBDOnsi 7520-48XT-6C-AC-R | 98511-7520- 48XT-6C-AC- R | \$ 3,683.00 | 6% | <i>\$3,487.99</i> |

| | | | | |
|---|----------------------------------|-------------|----|-------------------|
| EWPP PremierPLSNBDOnsite 7520-48Y-8C | 98511-7520- 48Y-8C | \$ 3,434.00 | 6% | <i>\$3,252.17</i> |
| EWPP PremierPLSNBDOnsit 7520-48Y-8C-AC-F | 98511-7520- 48Y-8C-AC-F | \$ 3,434.00 | 6% | <i>\$3,252.17</i> |
| EWPP PremierPLSNBDOnsit 7520-48Y-8C-AC-R | 98511-7520- 48Y-8C-AC-R | \$ 3,434.00 | 6% | <i>\$3,252.17</i> |
| EWPP PREMIERPLUS NBD ONSIT 7520-48YE-8CE | 98511-7520- 48YE-8CE | \$ 3,990.00 | 6% | <i>\$3,778.73</i> |
| EWPP PREMIERPL NBDONS 7520-48YE-8CE-AC-F | 98511-7520- 48YE-8CE-AC- F | \$ 3,990.00 | 6% | <i>\$3,778.73</i> |
| EWPP PREMIERPL NBDONS 7520-48YE-8CE-AC-R | 98511-7520- 48YE-8CE-AC- R | \$ 3,990.00 | 6% | <i>\$3,778.73</i> |
| EWPP PremierPLSNBDOnsite 7720-32C | 98511-7720- 32C | \$ 4,267.00 | 6% | <i>\$4,041.06</i> |
| EWPP PremierPLSNBDOnsite 7720-32C-AC-F | 98511-7720- 32C-AC-F | \$ 4,267.00 | 6% | <i>\$4,041.06</i> |
| EWPP PremierPLSNBDOnsite 7720-32C-AC-R | 98511-7720- 32C-AC-R | \$ 4,267.00 | 6% | <i>\$4,041.06</i> |
| EWPP PremeirPLSNBDOnsite 8520-48XT-6C | 98511-8520- 48XT-6C | \$ 4,730.00 | 6% | <i>\$4,479.55</i> |
| EWPP PremPLSNBDOnsite 8520-48XT-6C-AC-F | 98511-8520- 48XT-6C-AC- F | \$ 4,730.00 | 6% | <i>\$4,479.55</i> |
| EWPP PremPLSNBDOnsite 8520-48XT-6C-AC-R | 98511-8520- 48XT-6C-AC- R | \$ 4,730.00 | 6% | <i>\$4,479.55</i> |
| EWPP PremPLSNBDOnsite 8520-48XT-6C-DC-F | 98511-8520- 48XT-6C-DC- F | \$ 4,730.00 | 6% | <i>\$4,479.55</i> |
| EWPP PremPLSNBDOnsite 8520-48XT-6C-DC-R | 98511-8520- 48XT-6C-DC- R | \$ 4,730.00 | 6% | <i>\$4,479.55</i> |
| EWPP PremeirPLSNBDOnsite 8520-48Y-8C | 98511-8520- 48Y-8C | \$ 4,901.00 | 6% | <i>\$4,641.49</i> |
| EWPP PremPLSNBDOnsite 8520-48Y-8C-AC-F | 98511-8520- 48Y-8C-AC-F | \$ 4,901.00 | 6% | <i>\$4,641.49</i> |
| EWPP PremPLSNBDOnsite 8520-48Y-8C-AC-R | 98511-8520- 48Y-8C-AC-R | \$ 4,901.00 | 6% | <i>\$4,641.49</i> |
| EWPP PremPLSNBDOnsite 8520-48Y-8C-DC-F | 98511-8520- 48Y-8C-DC-F | \$ 4,901.00 | 6% | <i>\$4,641.49</i> |

| | | | | |
|---|----------------------------|--------------|-----|--------------------|
| EWPP PremPLSNBDOnsite 8520-48Y-8C-DC-R | 98511-8520- 48Y-8C-DC-R | \$ 4,901.00 | 6% | <i>\$4,641.49</i> |
| EWPP PremeirPLSNBDOnsite 8720-32C | 98511-8720- 32C | \$ 5,297.00 | 6% | <i>\$5,016.52</i> |
| EWPP PremeirPLSNBDOnsite 8720-32C-AC-F | 98511-8720- 32C-AC-F | \$ 5,297.00 | 6% | <i>\$5,016.52</i> |
| EWPP PremeirPLSNBDOnsite 8720-32C-AC-R | 98511-8720- 32C-AC-R | \$ 5,297.00 | 6% | <i>\$5,016.52</i> |
| EWPP PremeirPLSNBDOnsite 8720-32C-DC-F | 98511-8720- 32C-DC-F | \$ 5,297.00 | 6% | <i>\$5,016.52</i> |
| EWPP PremeirPLSNBDOnsite 8720-32C-DC-R | 98511-8720- 32C-DC-R | \$ 5,297.00 | 6% | <i>\$5,016.52</i> |
| EWPP PremierPLSNBDOnsite 8806 | 98511-8806 | \$ 4,721.00 | 6% | <i>\$4,471.02</i> |
| EWPP PremierPLSNBDOnsite 8810 | 98511-8810 | \$ 9,477.00 | 6% | <i>\$8,975.19</i> |
| EWPP PremeirPLSNBDOnsite 8820-40C | 98511-8820- 40C | \$ 17,118.00 | 10% | <i>\$15,521.75</i> |
| EWPP PremeirPLSNBDOnsite 8820-40C-AC-F | 98511-8820- 40C-AC-F | \$ 17,118.00 | 10% | <i>\$15,521.75</i> |
| EWPP PremeirPLSNBDOnsite 8820-40C-AC-R | 98511-8820- 40C-AC-R | \$ 17,118.00 | 10% | <i>\$15,521.75</i> |
| EWPP PremeirPLSNBDOnsite 8820-40C-DC-F | 98511-8820- 40C-DC-F | \$ 17,118.00 | 10% | <i>\$15,521.75</i> |
| EWPP PremeirPLSNBDOnsite 8820-40C-DC-R | 98511-8820- 40C-DC-R | \$ 17,118.00 | 10% | <i>\$15,521.75</i> |
| EWPP PremeirPLSNBDOnsite 8820-80C | 98511-8820- 80C | \$ 30,133.00 | 10% | <i>\$27,323.10</i> |
| EWPP PremeirPLSNBDOnsite 8820-80C-AC-F | 98511-8820- 80C-AC-F | \$ 30,133.00 | 10% | <i>\$27,323.10</i> |
| EWPP PremeirPLSNBDOnsite 8820-80C-AC-R | 98511-8820- 80C-AC-R | \$ 30,133.00 | 10% | <i>\$27,323.10</i> |
| EWPP PremeirPLSNBDOnsite 8820-80C-DC-F | 98511-8820- 80C-DC-F | \$ 30,133.00 | 10% | <i>\$27,323.10</i> |
| EWPP PremeirPLSNBDOnsite 8820-80C-DC-R | 98511-8820- 80C-DC-R | \$ 30,133.00 | 10% | <i>\$27,323.10</i> |
| EWPP PremeirPLSNBDOnsite 9920-16C | 98511-9920- 16C | \$ 13,655.00 | 6% | <i>\$12,931.97</i> |
| EWPP PremeirPLSNBDOnsite 9920-4D | 98511-9920-4D | \$ 13,655.00 | 6% | <i>\$12,931.97</i> |
| EWPP PremeirPLSNBDOnsite 9920-NPB-8 | 98511-9920- NPB-8 | \$ 22,292.00 | 6% | <i>\$21,111.64</i> |

| | | | | |
|---|---------------------------------|-----------|----|----------|
| EWPP PremierPLS NBDOnsite AH-AP-1130-AC- | 98511-AH-AP- 1130-AC-CE | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS NBDOnsite AH-AP-1130-AC- | 98511-AH-AP- 1130-AC-FCC | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS NBDOnsite AH-AP-1130-AC- | 98511-AH-AP- 1130-AC-W | \$ 415.00 | 6% | \$393.03 |
| EWPP PremierPLS NBDOnsite AH-AP-122-AC-C | 98511-AH-AP- 122-AC-CAN | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-122-AC-C | 98511-AH-AP- 122-AC-CE | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-122-AC-F | 98511-AH-AP- 122-AC-FCC | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-122-AC-W | 98511-AH-AP- 122-AC-W | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-130-AC-C | 98511-AH-AP- 130-AC-CE | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-130-AC-F | 98511-AH-AP- 130-AC-FCC | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-130-AC-W | 98511-AH-AP- 130-AC-W | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-150W-AC- | 98511-AH-AP- 150W-AC- CAN | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-150W-AC- | 98511-AH-AP- 150W-AC-CE | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-150W-AC- | 98511-AH-AP- 150W-AC-FCC | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-150W-AC- | 98511-AH-AP- 150W-AC-W | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-230-AC-C | 98511-AH-AP- 230-AC-CE | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-230-AC-F | 98511-AH-AP- 230-AC-FCC | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-230-AC-W | 98511-AH-AP- 230-AC-W | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-250-AC-C | 98511-AH-AP- 250-AC-CAN | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-250-AC-C | 98511-AH-AP- 250-AC-CE | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-250-AC-F | 98511-AH-AP- 250-AC-FCC | \$ 380.00 | 6% | \$359.88 |

| | | | | |
|---|---------------------------------|-----------|----|----------|
| EWPP PremierPLS NBDOnsite AH-AP-250-AC-W | 98511-AH-AP- 250-AC-W | \$ 380.00 | 6% | \$359.88 |
| EWPP PremierPLS NBDOnsite AH-AP-630-AX-C | 98511-AH-AP- 630-AX-CAN | \$ 421.00 | 6% | \$398.71 |
| EWPP PremierPLS NBDOnsite AH-AP-630-AX-C | 98511-AH-AP- 630-AX-CE | \$ 421.00 | 6% | \$398.71 |
| EWPP PremierPLS NBDOnsite AH-AP-630-AX-F | 98511-AH-AP- 630-AX-FCC | \$ 421.00 | 6% | \$398.71 |
| EWPP PremierPLS NBDOnsite AH-AP-630-AX-W | 98511-AH-AP- 630-AX-W | \$ 421.00 | 6% | \$398.71 |
| EWPP PremierPLS NBDOnsite AH-AP-650-AX-C | 98511-AH-AP- 650-AX-CAN | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-AP-650-AX-C | 98511-AH-AP- 650-AX-CE | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-AP-650-AX-F | 98511-AH-AP- 650-AX-FCC | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-AP-650-AX-W | 98511-AH-AP- 650-AX-W | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-AP-650X-AX- | 98511-AH-AP- 650X-AX- CAN | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-AP-650X-AX- | 98511-AH-AP- 650X-AX-CE | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-AP-650X-AX- | 98511-AH-AP- 650X-AX-FCC | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-AP-650X-AX- | 98511-AH-AP- 650X-AX-W | \$ 362.00 | 6% | \$342.83 |
| EWPP PremierPLS NBDOnsite AH-ATOM-CAN | 98511-AH- ATOM-CAN | \$ 394.00 | 6% | \$373.14 |
| EWPP PremierPLS NBDOnsite AH-ATOM-CE-EU | 98511-AH- ATOM-CE-EU | \$ 414.00 | 6% | \$392.08 |
| EWPP PremierPLS NBDOnsite AH-ATOM-CE-UK | 98511-AH- ATOM-CE-UK | \$ 414.00 | 6% | \$392.08 |
| EWPP PremierPLS NBDOnsite AH-ATOM-FCC | 98511-AH- ATOM-FCC | \$ 393.00 | 6% | \$372.19 |
| EWPP PremierPLS NBDOnsite AH-ATOM-W | 98511-AH- ATOM-W | \$ 394.00 | 6% | \$373.14 |
| EWPP PremierPLS NBDOnsite AH-ATOM-W-EU | 98511-AH- ATOM-W-EU | \$ 414.00 | 6% | \$392.08 |

| | | | | |
|---|--------------------------|-------------|----|-------------------|
| EWPP PremierPLS NBDOnsite AH-ATOM-W-UK | 98511-AH- ATOM-W-UK | \$ 414.00 | 6% | <i>\$392.08</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2208P-AU | 98511-AH-SR- 2208P-AU | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2208P-EU | 98511-AH-SR- 2208P-EU | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2208P-NA | 98511-AH-SR- 2208P-NA | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2208P-UK | 98511-AH-SR- 2208P-UK | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2224P-AU | 98511-AH-SR- 2224P-AU | \$ 1,185.00 | 6% | <i>\$1,122.25</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2224P-EU | 98511-AH-SR- 2224P-EU | \$ 1,185.00 | 6% | <i>\$1,122.25</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2224P-NA | 98511-AH-SR- 2224P-NA | \$ 1,185.00 | 6% | <i>\$1,122.25</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2224P-UK | 98511-AH-SR- 2224P-UK | \$ 1,185.00 | 6% | <i>\$1,122.25</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2324P-AU | 98511-AH-SR- 2324P-AU | \$ 1,226.00 | 6% | <i>\$1,161.08</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2324P-EU | 98511-AH-SR- 2324P-EU | \$ 1,226.00 | 6% | <i>\$1,161.08</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2324P-NA | 98511-AH-SR- 2324P-NA | \$ 1,226.00 | 6% | <i>\$1,161.08</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2324P-UK | 98511-AH-SR- 2324P-UK | \$ 1,226.00 | 6% | <i>\$1,161.08</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2348P-AU | 98511-AH-SR- 2348P-AU | \$ 1,366.00 | 6% | <i>\$1,293.67</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2348P-EU | 98511-AH-SR- 2348P-EU | \$ 1,366.00 | 6% | <i>\$1,293.67</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2348P-NA | 98511-AH-SR- 2348P-NA | \$ 1,366.00 | 6% | <i>\$1,293.67</i> |
| EWPP PremierPLS NBDOnsite AH-SR-2348P-UK | 98511-AH-SR- 2348P-UK | \$ 1,366.00 | 6% | <i>\$1,293.67</i> |
| EWPP PremierPLS NBDOnsite AH-XR200P-AU | 98511-AH- XR200P-AU | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWPP PremierPLS NBDOnsite AH-XR200P-EU | 98511-AH- XR200P-EU | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWPP PremierPLS NBDOnsite AH-XR200P-UK | 98511-AH- XR200P-UK | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |
| EWPP PremierPLS NBDOnsite AH-XR200P-US | 98511-AH- XR200P-US | \$ 1,149.00 | 6% | <i>\$1,088.16</i> |

| | | | | |
|---|---------------------------------|-------------|-----|-------------------|
| EWPP PremierPLS NBDOnsite AH-XR600P | 98511-AH- XR600P | \$ 1,154.00 | 6% | <i>\$1,092.90</i> |
| EWPP PremierPLS NBDOnsite AH-XR600P-AU | 98511-AH- XR600P-AU | \$ 1,160.00 | 6% | <i>\$1,098.58</i> |
| EWPP PremierPLS NBDOnsite AH-XR600P-EU | 98511-AH- XR600P-EU | \$ 1,160.00 | 6% | <i>\$1,098.58</i> |
| EWPP PremierPLS NBDOnsite AH-XR600P-KR | 98511-AH- XR600P-KR | \$ 1,160.00 | 6% | <i>\$1,098.58</i> |
| EWPP PremierPLS NBDOnsite AH-XR600P-UK | 98511-AH- XR600P-UK | \$ 1,160.00 | 6% | <i>\$1,098.58</i> |
| EWPP PremierPLS NBDOnsite AH-XR600P-US | 98511-AH- XR600P-US | \$ 1,160.00 | 6% | <i>\$1,098.58</i> |
| EWPP PremeirPLSNBDOnsite AP-8533-IL | 98511-AP- 8533-68SB30- IL | \$ 507.00 | 6% | <i>\$480.15</i> |
| EWPP PremeirPLSNBDOnsite AP3000-IL | 98511-AP3000- IL | \$ 271.89 | 6% | <i>\$257.49</i> |
| EWPP PremeirPLSNBDOnsite AP3000-TN | 98511-AP3000- TN | \$ 271.89 | 6% | <i>\$257.49</i> |
| EWPP PremeirPLSNBDOnsite AP3000-WW | 98511-AP3000- WW | \$ 271.89 | 6% | <i>\$257.49</i> |
| EWPP PremeirPLSNBDOnsite AP3000X-WW | 98511- AP3000X-WW | \$ 291.52 | 6% | <i>\$276.08</i> |
| EWPP PremeirPLSNBDOnsite AP302W-CAN | 98511- AP302W-CAN | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWPP PremeirPLSNBDOnsite AP302W-EG | 98511- AP302W-EG | \$ 275.00 | 10% | <i>\$249.36</i> |
| EWPP PremeirPLSNBDOnsite AP302W-FCC | 98511- AP302W-FCC | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWPP PremeirPLSNBDOnsite AP302W-WR | 98511- AP302W-WR | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPP PremierPLS NBDOnsite AP305C-1-CAN | 98511-AP305C- 1-CAN | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWPP PremierPLS NBDOnsite AP305C-1-EG | 98511-AP305C- 1-EG | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWPP PremierPLS NBDOnsite AP305C-FCC | 98511-AP305C- 1-FCC | \$ 373.00 | 6% | <i>\$353.25</i> |
| EWPP PremierPLS NBDOnsite AP305C-1-IL | 98511-AP305C- 1-IL | \$ 373.00 | 6% | <i>\$353.25</i> |

| | | | | |
|--|---------------------------|-----------|-----|----------|
| EWPP PremierPLS NBDOnsite AP305C-1-WR | 98511-AP305C- 1-WR | \$ 373.00 | 6% | \$353.25 |
| EWPP PremierPLS NBDOnsite AP305C-CAN | 98511-AP305C- CAN | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305C-EG | 98511-AP305C- EG | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305C-FCC | 98511-AP305C- FCC | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305C-IL | 98511-AP305C- IL | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305C-WR | 98511-AP305C- WR | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305CX-CAN | 98511- AP305CX- CAN | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305CX-FCC | 98511- AP305CX- FCC | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305CX-IL | 98511- AP305CX-IL | \$ 402.00 | 6% | \$380.71 |
| EWPP PremierPLS NBDOnsite AP305CX-WR | 98511- AP305CX-WR | \$ 402.00 | 6% | \$380.71 |
| EWPP PremeirPLSNBDOnsite AP310e-1-WR | 98511-AP310e- 1-WR | \$ 358.00 | 10% | \$324.62 |
| EWPP PremeirPLSNBDOnsite AP310e-CAN | 98511-AP310e- CAN | \$ 376.00 | 6% | \$356.09 |
| EWPP PremeirPLSNBDOnsite AP310e-FCC | 98511-AP310e- FCC | \$ 376.00 | 6% | \$356.09 |
| EWPP PremeirPLSNBDOnsite AP310e-IL | 98511-AP310e- IL | \$ 376.00 | 6% | \$356.09 |
| EWPP PremeirPLSNBDOnsite AP310e-WR | 98511-AP310e- WR | \$ 376.00 | 6% | \$356.09 |
| EWPP PremeirPLSNBDOnsite AP310i-1-WR | 98511-AP310i- 1-WR | \$ 358.00 | 10% | \$324.62 |
| EWPP PremeirPLSNBDOnsite AP310i-CAN | 98511-AP310i- CAN | \$ 376.00 | 6% | \$356.09 |
| EWPP PremeirPLSNBDOnsite AP310i-FCC | 98511-AP310i- FCC | \$ 376.00 | 6% | \$356.09 |
| EWPP PremeirPLSNBDOnsite AP310i-IL | 98511-AP310i- IL | \$ 376.00 | 6% | \$356.09 |
| EWPP PremeirPLSNBDOnsite AP310i-WR | 98511-AP310i- WR | \$ 376.00 | 6% | \$356.09 |

| | | | | |
|---|------------------------|-----------|----|----------|
| EWPP PremerPLSNBDOnsite AP360e-CAN | 98511-AP360e- CAN | \$ 404.00 | 6% | \$382.61 |
| EWPP PremerPLSNBDOnsite AP360e-FCC | 98511-AP360e- FCC | \$ 404.00 | 6% | \$382.61 |
| EWPP PremerPLSNBDOnsite AP360e-IL | 98511-AP360e- IL | \$ 404.00 | 6% | \$382.61 |
| EWPP PremerPLSNBDOnsite AP360e-WR | 98511-AP360e- WR | \$ 404.00 | 6% | \$382.61 |
| EWPP PremerPLSNBDOnsite AP360i-CAN | 98511-AP360i- CAN | \$ 403.00 | 6% | \$381.66 |
| EWPP PremerPLSNBDOnsite AP360i-FCC | 98511-AP360i- FCC | \$ 403.00 | 6% | \$381.66 |
| EWPP PremerPLSNBDOnsite AP360i-WR | 98511-AP360i- WR | \$ 403.00 | 6% | \$381.66 |
| EWPP PremerPLSNBDOnsite AP4000-WW | 98511-AP4000- 1-WW | \$ 348.00 | 6% | \$329.57 |
| EWPP PremerPLSNBDOnsite AP4000-IL | 98511-AP4000- IL | \$ 348.00 | 6% | \$329.57 |
| EWPP PremerPLSNBDOnsite AP4000-WW | 98511-AP4000- WW | \$ 348.00 | 6% | \$329.57 |
| EWPP PremierPLS NBDOnsite AP410C-1-CAN | 98511-AP410C- 1-CAN | \$ 365.00 | 6% | \$345.67 |
| EWPP PremierPLS NBDOnsite AP410C-1-EG | 98511-AP410C- 1-EG | \$ 365.00 | 6% | \$345.67 |
| EWPP PremierPLS NBDOnsite AP410C-1-FCC | 98511-AP410C- 1-FCC | \$ 365.00 | 6% | \$345.67 |
| EWPP PremierPLS NBDOnsite AP410C-1-IL | 98511-AP410C- 1-IL | \$ 365.00 | 6% | \$345.67 |
| EWPP PremierPLS NBDOnsite AP410C-1-WR | 98511-AP410C- 1-WR | \$ 365.00 | 6% | \$345.67 |
| EWPP PremierPLS NBDOnsite AP410C-CAN | 98511-AP410C- CAN | \$ 392.00 | 6% | \$371.24 |
| EWPP PremierPLS NBDOnsite AP410C-EG | 98511-AP410C- EG | \$ 392.00 | 6% | \$371.24 |
| EWPP PremierPLS NBDOnsite AP410C-FCC | 98511-AP410C- FCC | \$ 392.00 | 6% | \$371.24 |
| EWPP PremierPLS NBDOnsite AP410C-IL | 98511-AP410C- IL | \$ 392.00 | 6% | \$371.24 |
| EWPP PremierPLS NBDOnsite AP410C-WR | 98511-AP410C- WR | \$ 392.00 | 6% | \$371.24 |

| | | | | |
|---|------------------------|-----------|-----|----------|
| EWPP PremerPLSNBDOnsite AP410e-CAN | 98511-AP410e- CAN | \$ 421.00 | 6% | \$398.71 |
| EWPP PremerPLSNBDOnsite AP410e-FCC | 98511-AP410e- FCC | \$ 421.00 | 6% | \$398.71 |
| EWPP PremerPLSNBDOnsite AP410e-WR | 98511-AP410e- WR | \$ 421.00 | 6% | \$398.71 |
| EWPP PremerPLSNBDOnsite AP410i-1-FCC | 98511-AP410i- 1-FCC | \$ 401.00 | 10% | \$363.61 |
| EWPP PremerPLSNBDOnsite AP410i-1-WR | 98511-AP410i- 1-WR | \$ 401.00 | 10% | \$363.61 |
| EWPP PremerPLSNBDOnsite AP410i-CAN | 98511-AP410i- CAN | \$ 421.00 | 6% | \$398.71 |
| EWPP PremerPLSNBDOnsite AP410i-FCC | 98511-AP410i- FCC | \$ 421.00 | 6% | \$398.71 |
| EWPP PremerPLSNBDOnsite AP410i-IL | 98511-AP410i- IL | \$ 421.00 | 6% | \$398.71 |
| EWPP PremerPLSNBDOnsite AP410i-WR | 98511-AP410i- WR | \$ 421.00 | 6% | \$398.71 |
| EWPP PremierPLS NBDOnsite AP460C-CAN | 98511-AP460C- CAN | \$ 432.00 | 6% | \$409.13 |
| EWPP PremierPLS NBDOnsite AP460C-EG | 98511-AP460C- EG | \$ 432.00 | 6% | \$409.13 |
| EWPP PremierPLS NBDOnsite AP460C-FCC | 98511-AP460C- FCC | \$ 432.00 | 6% | \$409.13 |
| EWPP PremierPLS NBDOnsite AP460C-IL | 98511-AP460C- IL | \$ 432.00 | 6% | \$409.13 |
| EWPP PremierPLS NBDOnsite AP460C-WR | 98511-AP460C- WR | \$ 432.00 | 6% | \$409.13 |
| EWPP PremerPLSNBDOnsite AP460e-CAN | 98511-AP460e- CAN | \$ 439.00 | 6% | \$415.75 |
| EWPP PremerPLSNBDOnsite AP460e-FCC | 98511-AP460e- FCC | \$ 439.00 | 6% | \$415.75 |
| EWPP PremerPLSNBDOnsite AP460e-WR | 98511-AP460e- WR | \$ 418.00 | 6% | \$395.87 |
| EWPP PremerPLSNBDOnsite AP460i-CAN | 98511-AP460i- CAN | \$ 418.00 | 6% | \$395.87 |
| EWPP PremerPLSNBDOnsite AP460i-FCC | 98511-AP460i- FCC | \$ 419.00 | 6% | \$396.81 |
| EWPP PremerPLSNBDOnsite AP460i-IL | 98511-AP460i- IL | \$ 419.00 | 6% | \$396.81 |
| EWPP PremerPLSNBDOnsite AP460i-WR | 98511-AP460i- WR | \$ 419.00 | 6% | \$396.81 |

| | | | | |
|--|-----------------------------|-----------|-----|-----------------|
| EWPP PremierPLS NBDOnsite AP460S12C-CAN | 98511- AP460S12C- CAN | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS NBDOnsite AP460S12C-FCC | 98511- AP460S12C- FCC | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS NBDOnsite AP460S12C-WR | 98511- AP460S12C- WR | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS NBDOnsite AP460S6C-CAN | 98511- AP460S6C- CAN | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS NBDOnsite AP460S6C-FCC | 98511- AP460S6C- FCC | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS NBDOnsite AP460S6C-WR | 98511- AP460S6C- WR | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremeirPLSNBDOnsite AP5010-IL | 98511-AP5010- IL | \$ 382.00 | 6% | <i>\$361.77</i> |
| EWPP PremeirPLSNBDOnsite AP5010-WW | 98511-AP5010- WW | \$ 382.00 | 10% | <i>\$346.38</i> |
| EWPP PremeirPLSNBDOnsite AP5020 | 98511-AP5020- WW | \$ 389.56 | 6% | <i>\$368.93</i> |
| EWPP PremeirPLSNBDOnsite AP5050D-WW | 98511- AP5050D-WW | \$ 585.00 | 6% | <i>\$554.02</i> |
| EWPP PremeirPLSNBDOnsite AP5050U-WW | 98511- AP5050U-WW | \$ 500.00 | 6% | <i>\$473.53</i> |
| EWPP PremeirPLSNBDOnsite AP505i-FCC | 98511-AP505i- FCC | \$ 412.00 | 6% | <i>\$390.18</i> |
| EWPP PremeirPLSNBDOnsite AP505i-FCC-TAA | 98511-AP505i- FCC-TAA | \$ 412.00 | 6% | <i>\$390.18</i> |
| EWPP PremeirPLSNBDOnsite AP505i-WR | 98511-AP505i- WR | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPP PremierPLS NBDOnsite AP510C-CAN | 98511-AP510C- CAN | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWPP PremierPLS NBDOnsite AP510C-CE | 98511-AP510C- CE | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWPP PremierPLS NBDOnsite AP510C-FCC | 98511-AP510C- FCC | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWPP PremierPLS NBDOnsite AP510C-W | 98511-AP510C- W | \$ 355.00 | 6% | <i>\$336.20</i> |

| | | | | |
|--|---------------------------|-----------|-----|-----------------|
| EWPP PremierPLSNBDOnsite AP510C-WW | 98511-AP510C- WW | \$ 471.00 | 6% | <i>\$446.06</i> |
| EWPP PremierPLS NBDOnsite AP510CX-CAN | 98511- AP510CX- CAN | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWPP PremierPLS NBDOnsite AP510CX-CE | 98511- AP510CX-CE | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWPP PremierPLS NBDOnsite AP510CX-FCC | 98511- AP510CX- FCC | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWPP PremierPLS NBDOnsite AP510CX-W | 98511- AP510CX-W | \$ 355.00 | 6% | <i>\$336.20</i> |
| EWPP PremierPLSNBDOnsite AP510CX-WW | 98511- AP510CX-WW | \$ 471.00 | 6% | <i>\$446.06</i> |
| EWPP PremierPLSNBDOnsite AP510e-FCC | 98511-AP510e- FCC | \$ 470.00 | 6% | <i>\$445.11</i> |
| EWPP PremierPLSNBDOnsite AP510e-FCC-TAA | 98511-AP510e- FCC-TAA | \$ 470.00 | 6% | <i>\$445.11</i> |
| EWPP PremierPLSNBDOnsite AP510e-WR | 98511-AP510e- WR | \$ 448.00 | 6% | <i>\$424.28</i> |
| EWPP PremierPLSNBDOnsite AP510i-1-FCC | 98511-AP510i- 1-FCC | \$ 426.00 | 10% | <i>\$386.28</i> |
| EWPP PremierPLSNBDOnsite AP510i-1-WR | 98511-AP510i- 1-WR | \$ 426.00 | 10% | <i>\$386.28</i> |
| EWPP PremierPLSNBDOnsite AP510i-FCC | 98511-AP510i- FCC | \$ 447.00 | 6% | <i>\$423.33</i> |
| EWPP PremierPLSNBDOnsite AP510i-FCC-TAA | 98511-AP510i- FCC-TAA | \$ 447.00 | 6% | <i>\$423.33</i> |
| EWPP PremierPLSNBDOnsite AP510i-WR | 98511-AP510i- WR | \$ 447.00 | 6% | <i>\$423.33</i> |
| EWPP PremierPLSNBDOnsite AP560h-FCC | 98511-AP560h- FCC | \$ 674.00 | 6% | <i>\$638.31</i> |
| EWPP PremierPLSNBDOnsite AP560h-WR | 98511-AP560h- WR | \$ 674.00 | 6% | <i>\$638.31</i> |
| EWPP PremierPLSNBDOnsite AP560i-FCC | 98511-AP560i- FCC | \$ 572.00 | 6% | <i>\$541.71</i> |
| EWPP PremierPLSNBDOnsite AP560i-WR | 98511-AP560i- WR | \$ 545.00 | 6% | <i>\$516.14</i> |
| EWPP PremierPLSNBDOnsite AP560m-FCC | 98511-AP560m- FCC | \$ 572.00 | 6% | <i>\$541.71</i> |

| | | | | |
|------------------------------------|------------------|--------------|----|--------------------|
| EWPP PremerPLSNBDOnsite AP560t-FCC | 98511-AP560t-FCC | \$ 674.00 | 6% | <i>\$638.31</i> |
| EWPP PremerPLSNBDOnsite AP560u-FCC | 98511-AP560u-FCC | \$ 532.00 | 6% | <i>\$503.83</i> |
| EWPP PremerPLSNBDOnsite E2122 | 98511-E2122 | \$ 8,172.00 | 6% | <i>\$7,739.29</i> |
| EWPP PremerPLSNBDOnsite E2122-1 | 98511-E2122-1 | \$ 7,783.00 | 6% | <i>\$7,370.89</i> |
| EWPP PremerPLSNBDOnsite E3120-1 | 98511-E3120-1 | \$ 11,150.00 | 6% | <i>\$10,559.61</i> |
| EWPP PremerPLSNBDOnsite E3125 | 98511-E3125 | \$ 12,064.00 | 6% | <i>\$11,425.21</i> |
| EWPPPremierPLSNBDOnsite H30131 | 98511-H30131 | \$ 2,755.00 | 6% | <i>\$2,609.12</i> |
| EWPPPremierPLSNBDOnsite H30132 | 98511-H30132 | \$ 2,704.00 | 6% | <i>\$2,560.82</i> |
| EWPPPremierPLSNBDOnsite H30133 | 98511-H30133 | \$ 5,247.00 | 6% | <i>\$4,969.17</i> |
| EWPPPremierPLSNBDOnsite H30134 | 98511-H30134 | \$ 6,335.00 | 6% | <i>\$5,999.56</i> |
| EWPPPremierPLSNBDOnsite H30135 | 98511-H30135 | \$ 5,349.00 | 6% | <i>\$5,065.77</i> |
| EWPPPremierPLSNBDOnsite H30136 | 98511-H30136 | \$ 6,335.00 | 6% | <i>\$5,999.56</i> |
| EWPPPremierPLSNBDOnsite H30184 | 98511-H30184 | \$ 1,266.00 | 6% | <i>\$1,198.97</i> |
| EWPPPremierPLSNBDOnsite H30185 | 98511-H30185 | \$ 1,591.00 | 6% | <i>\$1,506.76</i> |
| EWPPPremierPLSNBDOnsite H30186 | 98511-H30186 | \$ 1,408.00 | 6% | <i>\$1,333.45</i> |
| EWPPPremierPLSNBDOnsite H30187 | 98511-H30187 | \$ 1,352.00 | 6% | <i>\$1,280.41</i> |
| EWPPPremierPLSNBDOnsite H30188 | 98511-H30188 | \$ 1,408.00 | 6% | <i>\$1,333.45</i> |
| EWPPPremierPLSNBDOnsite H30189 | 98511-H30189 | \$ 1,408.00 | 6% | <i>\$1,333.45</i> |
| EWPPPremierPLSNBDOnsite H30190 | 98511-H30190 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30214 | 98511-H30214 | \$ 1,475.00 | 6% | <i>\$1,396.90</i> |
| EWPPPremierPLSNBDOnsite H30215 | 98511-H30215 | \$ 1,475.00 | 6% | <i>\$1,396.90</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H30216 | 98511-H30216 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30217 | 98511-H30217 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30218 | 98511-H30218 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30219 | 98511-H30219 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30220 | 98511-H30220 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30221 | 98511-H30221 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30222 | 98511-H30222 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30223 | 98511-H30223 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30224 | 98511-H30224 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30225 | 98511-H30225 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30226 | 98511-H30226 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30227 | 98511-H30227 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30228 | 98511-H30228 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30229 | 98511-H30229 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30267 | 98511-H30267 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30268 | 98511-H30268 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H30269 | 98511-H30269 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30270 | 98511-H30270 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30271 | 98511-H30271 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30272 | 98511-H30272 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30273 | 98511-H30273 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H30274 | 98511-H30274 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| EWPPPremierPLSNBDOnsite H30275 | 98511-H30275 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30276 | 98511-H30276 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30277 | 98511-H30277 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| EWPPPremierPLSNBDOnsite H30278 | 98511-H30278 | \$ 2,209.00 | 6% | <i>\$2,092.03</i> |
| EWPPPremierPLSNBDOnsite H30279 | 98511-H30279 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| EWPPPremierPLSNBDOnsite H30280 | 98511-H30280 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| EWPPPremierPLSNBDOnsite H30281 | 98511-H30281 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| EWPPPremierPLSNBDOnsite H30282 | 98511-H30282 | \$ 2,130.00 | 6% | <i>\$2,017.22</i> |
| EWPPPremierPLSNBDOnsite H30283 | 98511-H30283 | \$ 1,728.00 | 6% | <i>\$1,636.50</i> |
| EWPPPremierPLSNBDOnsite H30284 | 98511-H30284 | \$ 1,901.00 | 6% | <i>\$1,800.34</i> |
| EWPPPremierPLSNBDOnsite H30296 | 98511-H30296 | \$ 1,475.00 | 6% | <i>\$1,396.90</i> |
| EWPPPremierPLSNBDOnsite H30297 | 98511-H30297 | \$ 1,475.00 | 6% | <i>\$1,396.90</i> |
| EWPPPremierPLSNBDOnsite H30298 | 98511-H30298 | \$ 1,475.00 | 6% | <i>\$1,396.90</i> |
| EWPPPremierPLSNBDOnsite H30299 | 98511-H30299 | \$ 1,475.00 | 6% | <i>\$1,396.90</i> |
| EWPPPremierPLSNBDOnsite H30381 | 98511-H30381 | \$ 2,689.00 | 6% | <i>\$2,546.62</i> |
| EWPPPremierPLSNBDOnsite H30384 | 98511-H30384 | \$ 2,575.00 | 6% | <i>\$2,438.65</i> |
| EWPPPremierPLSNBDOnsite H30391 | 98511-H30391 | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| EWPPPremierPLSNBDOnsite H30392 | 98511-H30392 | \$ 1,498.00 | 6% | <i>\$1,418.68</i> |
| EWPPPremierPLSNBDOnsite H30393 | 98511-H30393 | \$ 900.00 | 6% | <i>\$852.35</i> |
| EWPPPremierPLSNBDOnsite H30394 | 98511-H30394 | \$ 2,499.00 | 6% | <i>\$2,366.68</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H30395 | 98511-H30395 | \$ 2,902.00 | 6% | <i>\$2,748.34</i> |
| EWPPPremierPLSNBDOnsite H30396 | 98511-H30396 | \$ 2,676.00 | 6% | <i>\$2,534.31</i> |
| EWPPPremierPLSNBDOnsite H30397 | 98511-H30397 | \$ 3,103.00 | 6% | <i>\$2,938.70</i> |
| EWPPPremierPLSNBDOnsite H30398 | 98511-H30398 | \$ 917.00 | 6% | <i>\$868.44</i> |
| EWPPPremierPLSNBDOnsite H30400 | 98511-H30400 | \$ 690.00 | 6% | <i>\$653.46</i> |
| EWPPPremierPLSNBDOnsite H30401 | 98511-H30401 | \$ 810.00 | 6% | <i>\$767.11</i> |
| EWPPPremierPLSNBDOnsite H30402 | 98511-H30402 | \$ 827.00 | 6% | <i>\$783.21</i> |
| EWPPPremierPLSNBDOnsite H30403 | 98511-H30403 | \$ 1,023.00 | 6% | <i>\$968.83</i> |
| EWPPPremierPLSNBDOnsite H30480 | 98511-H30480 | \$ 2,781.00 | 6% | <i>\$2,633.75</i> |
| EWPPPremierPLSNBDOnsite H30495 | 98511-H30495 | \$ 3,711.00 | 6% | <i>\$3,514.50</i> |
| EWPPPremierPLSNBDOnsite H30496 | 98511-H30496 | \$ 3,639.00 | 6% | <i>\$3,446.31</i> |
| EWPPPremierPLSNBDOnsite H30497 | 98511-H30497 | \$ 4,418.00 | 6% | <i>\$4,184.07</i> |
| EWPPPremierPLSNBDOnsite H30498 | 98511-H30498 | \$ 4,337.00 | 6% | <i>\$4,107.36</i> |
| EWPPPremierPLSNBDOnsite H30499 | 98511-H30499 | \$ 1,204.00 | 6% | <i>\$1,140.25</i> |
| EWPPPremierPLSNBDOnsite H30501 | 98511-H30501 | \$ 4,337.00 | 6% | <i>\$4,107.36</i> |
| EWPPPremierPLSNBDOnsite H30502 | 98511-H30502 | \$ 5,549.00 | 6% | <i>\$5,255.18</i> |
| EWPPPremierPLSNBDOnsite H30503 | 98511-H30503 | \$ 1,204.00 | 6% | <i>\$1,140.25</i> |
| EWPPPremierPLSNBDOnsite H30505 | 98511-H30505 | \$ 6,183.00 | 6% | <i>\$5,855.61</i> |
| EWPPPremierPLSNBDOnsite H30506 | 98511-H30506 | \$ 7,660.00 | 6% | <i>\$7,254.40</i> |
| EWPPPremierPLSNBDOnsite H30509 | 98511-H30509 | \$ 5,549.00 | 6% | <i>\$5,255.18</i> |
| EWPPPremierPLSNBDOnsite H30510 | 98511-H30510 | \$ 6,183.00 | 6% | <i>\$5,855.61</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H30511 | 98511-H30511 | \$ 7,660.00 | 6% | <i>\$7,254.40</i> |
| EWPPPremierPLSNBDOnsite H30512 | 98511-H30512 | \$ 1,204.00 | 6% | <i>\$1,140.25</i> |
| EWPPPremierPLSNBDOnsite H30513 | 98511-H30513 | \$ 1,733.00 | 6% | <i>\$1,641.24</i> |
| EWPPPremierPLSNBDOnsite H30525 | 98511-H30525 | \$ 6,001.00 | 6% | <i>\$5,683.25</i> |
| EWPPPremierPLSNBDOnsite H30526 | 98511-H30526 | \$ 4,526.00 | 6% | <i>\$4,286.35</i> |
| EWPPPremierPLSNBDOnsite H30528 | 98511-H30528 | \$ 6,893.00 | 6% | <i>\$6,528.02</i> |
| EWPPPremierPLSNBDOnsite H30531 | 98511-H30531 | \$ 9,634.00 | 6% | <i>\$9,123.88</i> |
| EWPPPremierPLSNBDOnsite H30532 | 98511-H30532 | \$ 9,634.00 | 6% | <i>\$9,123.88</i> |
| EWPPPremierPLSNBDOnsite H30534 | 98511-H30534 | \$ 9,821.00 | 6% | <i>\$9,300.98</i> |
| EWPPPremierPLSNBDOnsite H30535 | 98511-H30535 | \$ 10,441.00 | 6% | <i>\$9,888.15</i> |
| EWPPPremierPLSNBDOnsite H30536 | 98511-H30536 | \$ 9,634.00 | 6% | <i>\$9,123.88</i> |
| EWPPPremierPLSNBDOnsite H30537 | 98511-H30537 | \$ 10,441.00 | 6% | <i>\$9,888.15</i> |
| EWPPPremierPLSNBDOnsite H30538 | 98511-H30538 | \$ 6,001.00 | 6% | <i>\$5,683.25</i> |
| EWPPPremierPLSNBDOnsite H30539 | 98511-H30539 | \$ 11,151.00 | 6% | <i>\$10,560.55</i> |
| EWPPPremierPLSNBDOnsite H30540 | 98511-H30540 | \$ 11,500.00 | 6% | <i>\$10,891.08</i> |
| EWPPPremierPLSNBDOnsite H30543 | 98511-H30543 | \$ 1,181.00 | 6% | <i>\$1,118.47</i> |
| EWPPPremierPLSNBDOnsite H30544 | 98511-H30544 | \$ 1,771.00 | 6% | <i>\$1,677.23</i> |
| EWPPPremierPLSNBDOnsite H30548 | 98511-H30548 | \$ 1,181.00 | 6% | <i>\$1,118.47</i> |
| EWPPPremierPLSNBDOnsite H30549 | 98511-H30549 | \$ 1,699.00 | 6% | <i>\$1,609.04</i> |
| EWPPPremierPLSNBDOnsite H30550 | 98511-H30550 | \$ 1,699.00 | 6% | <i>\$1,609.04</i> |
| EWPPPremierPLSNBDOnsite H30552 | 98511-H30552 | \$ 1,181.00 | 6% | <i>\$1,118.47</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H30553 | 98511-H30553 | \$ 1,621.00 | 6% | <i>\$1,535.17</i> |
| EWPPPremierPLSNBDOnsite H30569 | 98511-H30569 | \$ 5,247.00 | 6% | <i>\$4,969.17</i> |
| EWPPPremierPLSNBDOnsite H30570 | 98511-H30570 | \$ 6,077.00 | 6% | <i>\$5,755.22</i> |
| EWPPPremierPLSNBDOnsite H30571 | 98511-H30571 | \$ 6,077.00 | 6% | <i>\$5,755.22</i> |
| EWPPPremierPLSNBDOnsite H30573 | 98511-H30573 | \$ 5,247.00 | 6% | <i>\$4,969.17</i> |
| EWPPPremierPLSNBDOnsite H30574 | 98511-H30574 | \$ 5,703.00 | 6% | <i>\$5,401.03</i> |
| EWPPPremierPLSNBDOnsite H30575 | 98511-H30575 | \$ 3,975.00 | 6% | <i>\$3,764.52</i> |
| EWPPPremierPLSNBDOnsite H30576 | 98511-H30576 | \$ 5,247.00 | 6% | <i>\$4,969.17</i> |
| EWPPPremierPLSNBDOnsite H30577 | 98511-H30577 | \$ 5,962.00 | 6% | <i>\$5,646.31</i> |
| EWPPPremierPLSNBDOnsite H30578 | 98511-H30578 | \$ 5,962.00 | 6% | <i>\$5,646.31</i> |
| EWPPPremierPLSNBDOnsite H30587 | 98511-H30587 | \$ 4,615.00 | 6% | <i>\$4,370.64</i> |
| EWPPPremierPLSNBDOnsite H30588 | 98511-H30588 | \$ 3,317.00 | 6% | <i>\$3,141.36</i> |
| EWPPPremierPLSNBDOnsite H30589 | 98511-H30589 | \$ 4,835.00 | 6% | <i>\$4,578.99</i> |
| EWPPPremierPLSNBDOnsite H30632 | 98511-H30632 | \$ 442.00 | 6% | <i>\$418.60</i> |
| EWPPPremierPLSNBDOnsite H30633 | 98511-H30633 | \$ 442.00 | 6% | <i>\$418.60</i> |
| EWPPPremierPLSNBDOnsite H30643 | 98511-H30643 | \$ 9,358.00 | 6% | <i>\$8,862.49</i> |
| EWPPPremierPLSNBDOnsite H30706 | 98511-H30706 | \$ 7,027.00 | 6% | <i>\$6,654.92</i> |
| EWPPPremierPLSNBDOnsite H30707 | 98511-H30707 | \$ 4,526.00 | 6% | <i>\$4,286.35</i> |
| EWPPPremierPLSNBDOnsite H30724 | 98511-H30724 | \$ 776.00 | 6% | <i>\$734.91</i> |
| EWPPPremierPLSNBDOnsite H30725 | 98511-H30725 | \$ 2,704.00 | 6% | <i>\$2,560.82</i> |
| EWPPPremierPLSNBDOnsite H30726 | 98511-H30726 | \$ 10,644.00 | 6% | <i>\$10,080.40</i> |

| | | | | |
|------------------------------------|--------------|--------------|-----|--------------------|
| EWPPPremierPLSNBDOnsite H30727 | 98511-H30727 | \$ 11,280.00 | 6% | <i>\$10,682.72</i> |
| EWPPPremierPLSNBDOnsite H30730 | 98511-H30730 | \$ 442.00 | 6% | <i>\$418.60</i> |
| EWPPPremierPLSNBDOnsite H30731 | 98511-H30731 | \$ 442.00 | 6% | <i>\$418.60</i> |
| EWPPPremierPLSNBDOnsite H30733 | 98511-H30733 | \$ 10,317.00 | 6% | <i>\$9,770.71</i> |
| EWPPPremierPLSNBDOnsite H30734 | 98511-H30734 | \$ 7,962.00 | 6% | <i>\$7,540.41</i> |
| EWPPPremierPLSNBDOnsite H30735 | 98511-H30735 | \$ 9,120.00 | 6% | <i>\$8,637.10</i> |
| EWPPPremierPLSNBDOnsite H30736 | 98511-H30736 | \$ 1,791.00 | 6% | <i>\$1,696.17</i> |
| EWPPPremierPLSNBDOnsite H30738 | 98511-H30738 | \$ 408.00 | 6% | <i>\$386.40</i> |
| EWPP PremeirPLSNBDOnsite H30787 | 98511-H30787 | \$ 320.00 | 10% | <i>\$290.16</i> |
| EWPP PremeirPLSNBDOnsite H30788 | 98511-H30788 | \$ 322.00 | 10% | <i>\$291.97</i> |
| EWPP PremeirPLSNBDOnsite H30791 | 98511-H30791 | \$ 305.00 | 10% | <i>\$276.56</i> |
| EWPP PremeirPLSNBDOnsite H30847 | 98511-H30847 | \$ 328.00 | 10% | <i>\$297.41</i> |
| EWPP PremeirPLSNBDOnsite H30848 | 98511-H30848 | \$ 328.00 | 10% | <i>\$297.41</i> |
| EWPP PremeirPLSNBDOnsite H30852 | 98511-H30852 | \$ 328.00 | 10% | <i>\$297.41</i> |
| EWPP PremeirPLSNBDOnsite H30857 | 98511-H30857 | \$ 384.00 | 10% | <i>\$348.19</i> |
| EWPP PremeirPLSNBDOnsite H30869 | 98511-H30869 | \$ 540.00 | 10% | <i>\$489.65</i> |
| EWPP PremeirPLSNBDOnsite H30900 | 98511-H30900 | \$ 4,374.00 | 10% | <i>\$3,966.12</i> |
| EWPPPremierPLSNBDOnsite H31337 | 98511-H31337 | \$ 13,201.00 | 6% | <i>\$12,502.01</i> |
| EWPPPremierPLSNBDOnsite H31338 | 98511-H31338 | \$ 13,201.00 | 6% | <i>\$12,502.01</i> |
| EWPPPremierPLSNBDOnsite H31341 | 98511-H31341 | \$ 7,166.00 | 6% | <i>\$6,786.56</i> |
| EWPPPremierPLSNBDOnsite H31342 | 98511-H31342 | \$ 2,011.00 | 6% | <i>\$1,904.52</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|-------------|
| EWPPPremierPLSNBDOnsite H31343 | 98511-H31343 | \$ 2,769.00 | 6% | \$2,622.38 |
| EWPPPremierPLSNBDOnsite H31344 | 98511-H31344 | \$ 2,769.00 | 6% | \$2,622.38 |
| EWPPPremierPLSNBDOnsite H31345 | 98511-H31345 | \$ 2,769.00 | 6% | \$2,622.38 |
| EWPPPremierPLSNBDOnsite H31346 | 98511-H31346 | \$ 2,769.00 | 6% | \$2,622.38 |
| EWPPPremierPLSNBDOnsite H31362 | 98511-H31362 | \$ 33,580.00 | 6% | \$31,801.94 |
| EWPPPremierPLSNBDOnsite H31363 | 98511-H31363 | \$ 33,580.00 | 6% | \$31,801.94 |
| EWPPPremierPLSNBDOnsite H31364 | 98511-H31364 | \$ 12,563.00 | 6% | \$11,897.79 |
| EWPPPremierPLSNBDOnsite H31365 | 98511-H31365 | \$ 12,563.00 | 6% | \$11,897.79 |
| EWPPPremierPLSNBDOnsite H31366 | 98511-H31366 | \$ 17,389.00 | 6% | \$16,468.25 |
| EWPPPremierPLSNBDOnsite H31367 | 98511-H31367 | \$ 17,389.00 | 6% | \$16,468.25 |
| EWPPPremierPLSNBDOnsite H32010 | 98511-H32010 | \$ 1,837.00 | 6% | \$1,739.73 |
| EWPPPremierPLSNBDOnsite H32011 | 98511-H32011 | \$ 1,837.00 | 6% | \$1,739.73 |
| EWPPPremierPLSNBDOnsite H32012 | 98511-H32012 | \$ 4,376.00 | 6% | \$4,144.29 |
| EWPPPremierPLSNBDOnsite H32013 | 98511-H32013 | \$ 4,376.00 | 6% | \$4,144.29 |
| EWPPPremierPLSNBDOnsite H32014 | 98511-H32014 | \$ 4,376.00 | 6% | \$4,144.29 |
| EWPPPremierPLSNBDOnsite H32015 | 98511-H32015 | \$ 4,376.00 | 6% | \$4,144.29 |
| EWPPPremierPLSNBDOnsite H32016 | 98511-H32016 | \$ 4,072.00 | 6% | \$3,856.39 |
| EWPPPremierPLSNBDOnsite H32017 | 98511-H32017 | \$ 4,072.00 | 6% | \$3,856.39 |
| EWPPPremierPLSNBDOnsite H32018 | 98511-H32018 | \$ 4,072.00 | 6% | \$3,856.39 |
| EWPPPremierPLSNBDOnsite H32019 | 98511-H32019 | \$ 4,072.00 | 6% | \$3,856.39 |
| EWPPPremierPLSNBDOnsite H32020 | 98511-H32020 | \$ 34,335.00 | 6% | \$32,516.96 |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H32021 | 98511-H32021 | \$ 34,335.00 | 6% | <i>\$32,516.96</i> |
| EWPPPremierPLSNBDOnsite H32022 | 98511-H32022 | \$ 34,335.00 | 6% | <i>\$32,516.96</i> |
| EWPPPremierPLSNBDOnsite H32023 | 98511-H32023 | \$ 34,335.00 | 6% | <i>\$32,516.96</i> |
| EWPPPremierPLSNBDOnsite H32028 | 98511-H32028 | \$ 64,300.00 | 6% | <i>\$60,895.32</i> |
| EWPPPremierPLSNBDOnsite H32029 | 98511-H32029 | \$ 64,300.00 | 6% | <i>\$60,895.32</i> |
| EWPPPremierPLSNBDOnsite H32030 | 98511-H32030 | \$ 67,433.00 | 6% | <i>\$63,862.42</i> |
| EWPPPremierPLSNBDOnsite H32031 | 98511-H32031 | \$ 67,433.00 | 6% | <i>\$63,862.42</i> |
| EWPPPremierPLSNBDOnsite H32032 | 98511-H32032 | \$ 67,433.00 | 6% | <i>\$63,862.42</i> |
| EWPPPremierPLSNBDOnsite H32033 | 98511-H32033 | \$ 67,433.00 | 6% | <i>\$63,862.42</i> |
| EWPPPremierPLSNBDOnsite H32038 | 98511-H32038 | \$ 12,761.00 | 6% | <i>\$12,085.31</i> |
| EWPPPremierPLSNBDOnsite H32039 | 98511-H32039 | \$ 12,761.00 | 6% | <i>\$12,085.31</i> |
| EWPPPremierPLSNBDOnsite H32040 | 98511-H32040 | \$ 12,761.00 | 6% | <i>\$12,085.31</i> |
| EWPPPremierPLSNBDOnsite H32041 | 98511-H32041 | \$ 12,761.00 | 6% | <i>\$12,085.31</i> |
| EWPPPremierPLSNBDOnsite H32046 | 98511-H32046 | \$ 17,661.00 | 6% | <i>\$16,725.85</i> |
| EWPPPremierPLSNBDOnsite H32047 | 98511-H32047 | \$ 17,661.00 | 6% | <i>\$16,725.85</i> |
| EWPPPremierPLSNBDOnsite H32048 | 98511-H32048 | \$ 17,661.00 | 6% | <i>\$16,725.85</i> |
| EWPPPremierPLSNBDOnsite H32049 | 98511-H32049 | \$ 17,661.00 | 6% | <i>\$16,725.85</i> |
| EWPPPremierPLSNBDOnsite H32054 | 98511-H32054 | \$ 12,761.00 | 6% | <i>\$12,085.31</i> |
| EWPPPremierPLSNBDOnsite H32055 | 98511-H32055 | \$ 17,661.00 | 6% | <i>\$16,725.85</i> |
| EWPPPremierPLSNBDOnsite H32056 | 98511-H32056 | \$ 5,022.00 | 6% | <i>\$4,756.09</i> |
| EWPPPremierPLSNBDOnsite H32057 | 98511-H32057 | \$ 5,173.00 | 6% | <i>\$4,899.09</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H32058 | 98511-H32058 | \$ 5,173.00 | 6% | <i>\$4,899.09</i> |
| EWPPPremierPLSNBDOnsite H32059 | 98511-H32059 | \$ 5,173.00 | 6% | <i>\$4,899.09</i> |
| EWPPPremierPLSNBDOnsite H32060 | 98511-H32060 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWPPPremierPLSNBDOnsite H32061 | 98511-H32061 | \$ 5,309.00 | 6% | <i>\$5,027.89</i> |
| EWPPPremierPLSNBDOnsite H32062 | 98511-H32062 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWPPPremierPLSNBDOnsite H32063 | 98511-H32063 | \$ 5,062.00 | 6% | <i>\$4,793.97</i> |
| EWPPPremierPLSNBDOnsite H32064 | 98511-H32064 | \$ 5,056.00 | 6% | <i>\$4,788.28</i> |
| EWPPPremierPLSNBDOnsite H32065 | 98511-H32065 | \$ 5,555.00 | 6% | <i>\$5,260.86</i> |
| EWPPPremierPLSNBDOnsite H32066 | 98511-H32066 | \$ 5,555.00 | 6% | <i>\$5,260.86</i> |
| EWPPPremierPLSNBDOnsite H32067 | 98511-H32067 | \$ 5,555.00 | 6% | <i>\$5,260.86</i> |
| EWPPPremierPLSNBDOnsite H32068 | 98511-H32068 | \$ 5,555.00 | 6% | <i>\$5,260.86</i> |
| EWPPPremierPLSNBDOnsite H32069 | 98511-H32069 | \$ 6,542.00 | 6% | <i>\$6,195.60</i> |
| EWPPPremierPLSNBDOnsite H32070 | 98511-H32070 | \$ 6,542.00 | 6% | <i>\$6,195.60</i> |
| EWPPPremierPLSNBDOnsite H32071 | 98511-H32071 | \$ 6,542.00 | 6% | <i>\$6,195.60</i> |
| EWPPPremierPLSNBDOnsite H32072 | 98511-H32072 | \$ 6,542.00 | 6% | <i>\$6,195.60</i> |
| EWPPPremierPLSNBDOnsite H32073 | 98511-H32073 | \$ 42,602.00 | 6% | <i>\$40,346.22</i> |
| EWPPPremierPLSNBDOnsite H32074 | 98511-H32074 | \$ 42,602.00 | 6% | <i>\$40,346.22</i> |
| EWPPPremierPLSNBDOnsite H32075 | 98511-H32075 | \$ 57,948.00 | 6% | <i>\$54,879.65</i> |
| EWPPPremierPLSNBDOnsite H32076 | 98511-H32076 | \$ 57,396.00 | 6% | <i>\$54,356.88</i> |
| EWPPPremierPLSNBDOnsite H32101 | 98511-H32101 | \$ 3,233.00 | 6% | <i>\$3,061.81</i> |
| EWPPPremierPLSNBDOnsite H32102 | 98511-H32102 | \$ 3,233.00 | 6% | <i>\$3,061.81</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H32103 | 98511-H32103 | \$ 3,233.00 | 6% | <i>\$3,061.81</i> |
| EWPPPremierPLSNBDOnsite H32104 | 98511-H32104 | \$ 3,233.00 | 6% | <i>\$3,061.81</i> |
| EWPPPremierPLSNBDOnsite H32105 | 98511-H32105 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPPPremierPLSNBDOnsite H32106 | 98511-H32106 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPPPremierPLSNBDOnsite H32107 | 98511-H32107 | \$ 10,583.00 | 6% | <i>\$10,022.63</i> |
| EWPPPremierPLSNBDOnsite H32108 | 98511-H32108 | \$ 10,583.00 | 6% | <i>\$10,022.63</i> |
| EWPPPremierPLSNBDOnsite H32109 | 98511-H32109 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPPPremierPLSNBDOnsite H32110 | 98511-H32110 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPPPremierPLSNBDOnsite H32111 | 98511-H32111 | \$ 3,232.00 | 6% | <i>\$3,060.87</i> |
| EWPPPremierPLSNBDOnsite H32112 | 98511-H32112 | \$ 3,232.00 | 6% | <i>\$3,060.87</i> |
| EWPPPremierPLSNBDOnsite H32113 | 98511-H32113 | \$ 3,233.00 | 6% | <i>\$3,061.81</i> |
| EWPPPremierPLSNBDOnsite H32114 | 98511-H32114 | \$ 3,233.00 | 6% | <i>\$3,061.81</i> |
| EWPPPremierPLSNBDOnsite H32115 | 98511-H32115 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPPPremierPLSNBDOnsite H32116 | 98511-H32116 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPPPremierPLSNBDOnsite H32117 | 98511-H32117 | \$ 3,128.00 | 6% | <i>\$2,962.37</i> |
| EWPPPremierPLSNBDOnsite H32118 | 98511-H32118 | \$ 3,128.00 | 6% | <i>\$2,962.37</i> |
| EWPPPremierPLSNBDOnsite H32119 | 98511-H32119 | \$ 3,128.00 | 6% | <i>\$2,962.37</i> |
| EWPPPremierPLSNBDOnsite H32120 | 98511-H32120 | \$ 3,128.00 | 6% | <i>\$2,962.37</i> |
| EWPPPremierPLSNBDOnsite H32121 | 98511-H32121 | \$ 10,583.00 | 6% | <i>\$10,022.63</i> |
| EWPPPremierPLSNBDOnsite H32122 | 98511-H32122 | \$ 10,583.00 | 6% | <i>\$10,022.63</i> |
| EWPPPremierPLSNBDOnsite H32123 | 98511-H32123 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H32124 | 98511-H32124 | \$ 4,896.00 | 6% | <i>\$4,636.76</i> |
| EWPPPremierPLSNBDOnsite H32125 | 98511-H32125 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32126 | 98511-H32126 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32127 | 98511-H32127 | \$ 5,331.00 | 6% | <i>\$5,048.72</i> |
| EWPPPremierPLSNBDOnsite H32128 | 98511-H32128 | \$ 5,331.00 | 6% | <i>\$5,048.72</i> |
| EWPPPremierPLSNBDOnsite H32129 | 98511-H32129 | \$ 5,331.00 | 6% | <i>\$5,048.72</i> |
| EWPPPremierPLSNBDOnsite H32130 | 98511-H32130 | \$ 5,331.00 | 6% | <i>\$5,048.72</i> |
| EWPPPremierPLSNBDOnsite H32131 | 98511-H32131 | \$ 5,331.00 | 6% | <i>\$5,048.72</i> |
| EWPPPremierPLSNBDOnsite H32132 | 98511-H32132 | \$ 5,331.00 | 6% | <i>\$5,048.72</i> |
| EWPPPremierPLSNBDOnsite H32133 | 98511-H32133 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32134 | 98511-H32134 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32135 | 98511-H32135 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32136 | 98511-H32136 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32137 | 98511-H32137 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32138 | 98511-H32138 | \$ 4,746.00 | 6% | <i>\$4,494.70</i> |
| EWPPPremierPLSNBDOnsite H32139 | 98511-H32139 | \$ 17,641.00 | 6% | <i>\$16,706.91</i> |
| EWPPPremierPLSNBDOnsite H32140 | 98511-H32140 | \$ 17,641.00 | 6% | <i>\$16,706.91</i> |
| EWPPPremierPLSNBDOnsite H32141 | 98511-H32141 | \$ 21,014.00 | 6% | <i>\$19,901.31</i> |
| EWPPPremierPLSNBDOnsite H32142 | 98511-H32142 | \$ 21,014.00 | 6% | <i>\$19,901.31</i> |
| EWPPPremierPLSNBDOnsite H32146 | 98511-H32146 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |
| EWPPPremierPLSNBDOnsite H32147 | 98511-H32147 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H32148 | 98511-H32148 | \$ 4,638.00 | 6% | <i>\$4,392.42</i> |
| EWPPPremierPLSNBDOnsite H32149 | 98511-H32149 | \$ 4,638.00 | 6% | <i>\$4,392.42</i> |
| EWPPPremierPLSNBDOnsite H32150 | 98511-H32150 | \$ 3,061.00 | 6% | <i>\$2,898.92</i> |
| EWPPPremierPLSNBDOnsite H32169 | 98511-H32169 | \$ 3,207.00 | 6% | <i>\$3,037.19</i> |
| EWPPPremierPLSNBDOnsite H32170 | 98511-H32170 | \$ 3,207.00 | 6% | <i>\$3,037.19</i> |
| EWPPPremierPLSNBDOnsite H32171 | 98511-H32171 | \$ 3,105.00 | 6% | <i>\$2,940.59</i> |
| EWPPPremierPLSNBDOnsite H32172 | 98511-H32172 | \$ 3,105.00 | 6% | <i>\$2,940.59</i> |
| EWPPPremierPLSNBDOnsite H32173 | 98511-H32173 | \$ 5,687.00 | 6% | <i>\$5,385.87</i> |
| EWPPPremierPLSNBDOnsite H32174 | 98511-H32174 | \$ 5,687.00 | 6% | <i>\$5,385.87</i> |
| EWPPPremierPLSNBDOnsite H32175 | 98511-H32175 | \$ 5,066.00 | 6% | <i>\$4,797.76</i> |
| EWPPPremierPLSNBDOnsite H32176 | 98511-H32176 | \$ 5,066.00 | 6% | <i>\$4,797.76</i> |
| EWPPPremierPLSNBDOnsite H32177 | 98511-H32177 | \$ 19,386.00 | 6% | <i>\$18,359.51</i> |
| EWPPPremierPLSNBDOnsite H32178 | 98511-H32178 | \$ 23,091.00 | 6% | <i>\$21,868.33</i> |
| EWPPPremierPLSNBDOnsite H34008 | 98511-H34008 | \$ 1,271.00 | 6% | <i>\$1,203.70</i> |
| EWPPPremierPLSNBDOnsite H34009 | 98511-H34009 | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| EWPPPremierPLSNBDOnsite H34010 | 98511-H34010 | \$ 1,197.00 | 6% | <i>\$1,133.62</i> |
| EWPPPremierPLSNBDOnsite H34011 | 98511-H34011 | \$ 1,339.00 | 6% | <i>\$1,268.10</i> |
| EWPPPremierPLSNBDOnsite H34012 | 98511-H34012 | \$ 1,439.00 | 6% | <i>\$1,362.80</i> |
| EWPPPremierPLSNBDOnsite H34013 | 98511-H34013 | \$ 1,306.00 | 6% | <i>\$1,236.85</i> |
| EWPPPremierPLSNBDOnsite H34014 | 98511-H34014 | \$ 1,355.00 | 6% | <i>\$1,283.25</i> |
| EWPPPremierPLSNBDOnsite H34015 | 98511-H34015 | \$ 1,214.00 | 6% | <i>\$1,149.72</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H34016 | 98511-H34016 | \$ 1,371.00 | 6% | <i>\$1,298.41</i> |
| EWPPPremierPLSNBDOnsite H34017 | 98511-H34017 | \$ 1,476.00 | 6% | <i>\$1,397.85</i> |
| EWPPPremierPLSNBDOnsite H34018 | 98511-H34018 | \$ 1,314.00 | 6% | <i>\$1,244.42</i> |
| EWPPPremierPLSNBDOnsite H34019 | 98511-H34019 | \$ 1,314.00 | 6% | <i>\$1,244.42</i> |
| EWPPPremierPLSNBDOnsite H34020 | 98511-H34020 | \$ 1,314.00 | 6% | <i>\$1,244.42</i> |
| EWPPPremierPLSNBDOnsite H34021 | 98511-H34021 | \$ 1,314.00 | 6% | <i>\$1,244.42</i> |
| EWPPPremierPLSNBDOnsite H34048 | 98511-H34048 | \$ 1,631.00 | 6% | <i>\$1,544.64</i> |
| EWPPPremierPLSNBDOnsite H34049 | 98511-H34049 | \$ 1,631.00 | 6% | <i>\$1,544.64</i> |
| EWPPPremierPLSNBDOnsite H34050 | 98511-H34050 | \$ 1,525.00 | 6% | <i>\$1,444.25</i> |
| EWPPPremierPLSNBDOnsite H34051 | 98511-H34051 | \$ 1,525.00 | 6% | <i>\$1,444.25</i> |
| EWPPPremierPLSNBDOnsite H34052 | 98511-H34052 | \$ 1,702.00 | 6% | <i>\$1,611.88</i> |
| EWPPPremierPLSNBDOnsite H34053 | 98511-H34053 | \$ 1,702.00 | 6% | <i>\$1,611.88</i> |
| EWPPPremierPLSNBDOnsite H34054 | 98511-H34054 | \$ 1,580.00 | 6% | <i>\$1,496.34</i> |
| EWPPPremierPLSNBDOnsite H34055 | 98511-H34055 | \$ 1,580.00 | 6% | <i>\$1,496.34</i> |
| EWPPPremierPLSNBDOnsite H34056 | 98511-H34056 | \$ 1,854.00 | 6% | <i>\$1,755.83</i> |
| EWPPPremierPLSNBDOnsite H34057 | 98511-H34057 | \$ 1,854.00 | 6% | <i>\$1,755.83</i> |
| EWPPPremierPLSNBDOnsite H34058 | 98511-H34058 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPPPremierPLSNBDOnsite H34059 | 98511-H34059 | \$ 1,779.00 | 6% | <i>\$1,684.80</i> |
| EWPPPremierPLSNBDOnsite H34062 | 98511-H34062 | \$ 1,854.00 | 6% | <i>\$1,755.83</i> |
| EWPPPremierPLSNBDOnsite H34063 | 98511-H34063 | \$ 1,854.00 | 6% | <i>\$1,755.83</i> |
| EWPPPremierPLSNBDOnsite H34064 | 98511-H34064 | \$ 1,508.00 | 6% | <i>\$1,428.15</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H34065 | 98511-H34065 | \$ 1,508.00 | 6% | <i>\$1,428.15</i> |
| EWPPPremierPLSNBDOnsite H34066 | 98511-H34066 | \$ 1,508.00 | 6% | <i>\$1,428.15</i> |
| EWPPPremierPLSNBDOnsite H34067 | 98511-H34067 | \$ 1,508.00 | 6% | <i>\$1,428.15</i> |
| EWPPPremierPLSNBDOnsite H34068 | 98511-H34068 | \$ 1,508.00 | 6% | <i>\$1,428.15</i> |
| EWPPPremierPLSNBDOnsite H34069 | 98511-H34069 | \$ 1,494.00 | 6% | <i>\$1,414.89</i> |
| EWPPPremierPLSNBDOnsite H34070 | 98511-H34070 | \$ 1,508.00 | 6% | <i>\$1,428.15</i> |
| EWPPPremierPLSNBDOnsite H34071 | 98511-H34071 | \$ 1,508.00 | 6% | <i>\$1,428.15</i> |
| EWPPPremierPLSNBDOnsite H34072 | 98511-H34072 | \$ 4,130.00 | 6% | <i>\$3,911.32</i> |
| EWPPPremierPLSNBDOnsite H34073 | 98511-H34073 | \$ 4,051.00 | 6% | <i>\$3,836.50</i> |
| EWPPPremierPLSNBDOnsite H34074 | 98511-H34074 | \$ 5,085.00 | 6% | <i>\$4,815.75</i> |
| EWPPPremierPLSNBDOnsite H34075 | 98511-H34075 | \$ 4,929.00 | 6% | <i>\$4,668.01</i> |
| EWPPPremierPLSNBDOnsite H34076 | 98511-H34076 | \$ 4,130.00 | 6% | <i>\$3,911.32</i> |
| EWPPPremierPLSNBDOnsite H34077 | 98511-H34077 | \$ 4,051.00 | 6% | <i>\$3,836.50</i> |
| EWPPPremierPLSNBDOnsite H34078 | 98511-H34078 | \$ 4,130.00 | 6% | <i>\$3,911.32</i> |
| EWPPPremierPLSNBDOnsite H34079 | 98511-H34079 | \$ 4,051.00 | 6% | <i>\$3,836.50</i> |
| EWPPPremierPLSNBDOnsite H34080 | 98511-H34080 | \$ 5,085.00 | 6% | <i>\$4,815.75</i> |
| EWPPPremierPLSNBDOnsite H34081 | 98511-H34081 | \$ 4,929.00 | 6% | <i>\$4,668.01</i> |
| EWPPPremierPLSNBDOnsite H34082 | 98511-H34082 | \$ 4,854.00 | 6% | <i>\$4,596.98</i> |
| EWPPPremierPLSNBDOnsite H34083 | 98511-H34083 | \$ 4,705.00 | 6% | <i>\$4,455.87</i> |
| EWPPPremierPLSNBDOnsite H34084 | 98511-H34084 | \$ 3,694.00 | 6% | <i>\$3,498.40</i> |
| EWPPPremierPLSNBDOnsite H34085 | 98511-H34085 | \$ 3,694.00 | 6% | <i>\$3,498.40</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H34086 | 98511-H34086 | \$ 4,320.00 | 6% | <i>\$4,091.26</i> |
| EWPPPremierPLSNBDOnsite H34087 | 98511-H34087 | \$ 4,123.00 | 6% | <i>\$3,904.69</i> |
| EWPPPremierPLSNBDOnsite H34088 | 98511-H34088 | \$ 7,875.00 | 6% | <i>\$7,458.02</i> |
| EWPPPremierPLSNBDOnsite H34089 | 98511-H34089 | \$ 7,875.00 | 6% | <i>\$7,458.02</i> |
| EWPPPremierPLSNBDOnsite H34090 | 98511-H34090 | \$ 9,068.00 | 6% | <i>\$8,587.85</i> |
| EWPPPremierPLSNBDOnsite H34091 | 98511-H34091 | \$ 7,958.00 | 6% | <i>\$7,536.62</i> |
| EWPPPremierPLSNBDOnsite H34092 | 98511-H34092 | \$ 7,958.00 | 6% | <i>\$7,536.62</i> |
| EWPPPremierPLSNBDOnsite H34093 | 98511-H34093 | \$ 7,958.00 | 6% | <i>\$7,536.62</i> |
| EWPPPremierPLSNBDOnsite H34094 | 98511-H34094 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34095 | 98511-H34095 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34096 | 98511-H34096 | \$ 1,019.00 | 6% | <i>\$965.04</i> |
| EWPPPremierPLSNBDOnsite H34097 | 98511-H34097 | \$ 1,019.00 | 6% | <i>\$965.04</i> |
| EWPPPremierPLSNBDOnsite H34098 | 98511-H34098 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34099 | 98511-H34099 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34100 | 98511-H34100 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34101 | 98511-H34101 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34102 | 98511-H34102 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34103 | 98511-H34103 | \$ 952.00 | 6% | <i>\$901.59</i> |
| EWPPPremierPLSNBDOnsite H34104 | 98511-H34104 | \$ 667.00 | 6% | <i>\$631.68</i> |
| EWPPPremierPLSNBDOnsite H34105 | 98511-H34105 | \$ 667.00 | 6% | <i>\$631.68</i> |
| EWPPPremierPLSNBDOnsite H34106 | 98511-H34106 | \$ 667.00 | 6% | <i>\$631.68</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H34107 | 98511-H34107 | \$ 667.00 | 6% | <i>\$631.68</i> |
| EWPPPremierPLSNBDOnsite H34108 | 98511-H34108 | \$ 667.00 | 6% | <i>\$631.68</i> |
| EWPPPremierPLSNBDOnsite H34109 | 98511-H34109 | \$ 667.00 | 6% | <i>\$631.68</i> |
| EWPPPremierPLSNBDOnsite H34110 | 98511-H34110 | \$ 7,628.00 | 6% | <i>\$7,224.10</i> |
| EWPPPremierPLSNBDOnsite H34111 | 98511-H34111 | \$ 7,628.00 | 6% | <i>\$7,224.10</i> |
| EWPPPremierPLSNBDOnsite H34112 | 98511-H34112 | \$ 7,628.00 | 6% | <i>\$7,224.10</i> |
| EWPPPremierPLSNBDOnsite H34114 | 98511-H34114 | \$ 11,500.00 | 6% | <i>\$10,891.08</i> |
| EWPPPremierPLSNBDOnsite H34115 | 98511-H34115 | \$ 11,073.00 | 6% | <i>\$10,486.68</i> |
| EWPPPremierPLSNBDOnsite H34116 | 98511-H34116 | \$ 11,073.00 | 6% | <i>\$10,486.68</i> |
| EWPPPremierPLSNBDOnsite H34117 | 98511-H34117 | \$ 11,500.00 | 6% | <i>\$10,891.08</i> |
| EWPPPremierPLSNBDOnsite H34118 | 98511-H34118 | \$ 1,830.00 | 6% | <i>\$1,733.10</i> |
| EWPPPremierPLSNBDOnsite H34119 | 98511-H34119 | \$ 1,830.00 | 6% | <i>\$1,733.10</i> |
| EWPPPremierPLSNBDOnsite H34120 | 98511-H34120 | \$ 1,393.00 | 6% | <i>\$1,319.24</i> |
| EWPPPremierPLSNBDOnsite H34121 | 98511-H34121 | \$ 1,393.00 | 6% | <i>\$1,319.24</i> |
| EWPPPremierPLSNBDOnsite H34122 | 98511-H34122 | \$ 1,434.00 | 6% | <i>\$1,358.07</i> |
| EWPPPremierPLSNBDOnsite H34123 | 98511-H34123 | \$ 1,434.00 | 6% | <i>\$1,358.07</i> |
| EWPPPremierPLSNBDOnsite H34124 | 98511-H34124 | \$ 1,926.00 | 6% | <i>\$1,824.02</i> |
| EWPPPremierPLSNBDOnsite H34125 | 98511-H34125 | \$ 1,926.00 | 6% | <i>\$1,824.02</i> |
| EWPPPremierPLSNBDOnsite H34126 | 98511-H34126 | \$ 1,926.00 | 6% | <i>\$1,824.02</i> |
| EWPPPremierPLSNBDOnsite H34127 | 98511-H34127 | \$ 1,926.00 | 6% | <i>\$1,824.02</i> |
| EWPPPremierPLSNBDOnsite H34129 | 98511-H34129 | \$ 1,592.00 | 6% | <i>\$1,507.70</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H34130 | 98511-H34130 | \$ 1,655.00 | 6% | <i>\$1,567.37</i> |
| EWPPPremierPLSNBDOnsite H34131 | 98511-H34131 | \$ 1,655.00 | 6% | <i>\$1,567.37</i> |
| EWPPPremierPLSNBDOnsite H34132 | 98511-H34132 | \$ 1,655.00 | 6% | <i>\$1,567.37</i> |
| EWPPPremierPLSNBDOnsite H34172 | 98511-H34172 | \$ 3,231.00 | 6% | <i>\$3,059.92</i> |
| EWPPPremierPLSNBDOnsite H34174 | 98511-H34174 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34175 | 98511-H34175 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34176 | 98511-H34176 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34177 | 98511-H34177 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34178 | 98511-H34178 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34179 | 98511-H34179 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34180 | 98511-H34180 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34181 | 98511-H34181 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34182 | 98511-H34182 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34183 | 98511-H34183 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34184 | 98511-H34184 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34185 | 98511-H34185 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34186 | 98511-H34186 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34187 | 98511-H34187 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34188 | 98511-H34188 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34189 | 98511-H34189 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34190 | 98511-H34190 | \$ 394.00 | 6% | <i>\$373.14</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34191 | 98511-H34191 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34192 | 98511-H34192 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34193 | 98511-H34193 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34194 | 98511-H34194 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34195 | 98511-H34195 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34196 | 98511-H34196 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34197 | 98511-H34197 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34198 | 98511-H34198 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34199 | 98511-H34199 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34200 | 98511-H34200 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34201 | 98511-H34201 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34202 | 98511-H34202 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34203 | 98511-H34203 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34204 | 98511-H34204 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34205 | 98511-H34205 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34206 | 98511-H34206 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34207 | 98511-H34207 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34208 | 98511-H34208 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34209 | 98511-H34209 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34210 | 98511-H34210 | \$ 394.00 | 6% | <i>\$373.14</i> |
| EWPPPremierPLSNBDOnsite H34211 | 98511-H34211 | \$ 394.00 | 6% | <i>\$373.14</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|----------|
| EWPPPremierPLSNBDOnsite H34212 | 98511-H34212 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34213 | 98511-H34213 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34214 | 98511-H34214 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34215 | 98511-H34215 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34216 | 98511-H34216 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34217 | 98511-H34217 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34218 | 98511-H34218 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34219 | 98511-H34219 | \$ 394.00 | 6% | \$373.14 |
| EWPPPremierPLSNBDOnsite H34220 | 98511-H34220 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34221 | 98511-H34221 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34222 | 98511-H34222 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34223 | 98511-H34223 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34224 | 98511-H34224 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34225 | 98511-H34225 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34226 | 98511-H34226 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34227 | 98511-H34227 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34228 | 98511-H34228 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34229 | 98511-H34229 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34230 | 98511-H34230 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34231 | 98511-H34231 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34232 | 98511-H34232 | \$ 417.00 | 6% | \$394.92 |

| | | | | |
|-----------------------------------|--------------|-----------|----|----------|
| EWPPPremierPLSNBDOnsite H34233 | 98511-H34233 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34234 | 98511-H34234 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34235 | 98511-H34235 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34236 | 98511-H34236 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34237 | 98511-H34237 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34238 | 98511-H34238 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34239 | 98511-H34239 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34240 | 98511-H34240 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34241 | 98511-H34241 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34242 | 98511-H34242 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34243 | 98511-H34243 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34244 | 98511-H34244 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34245 | 98511-H34245 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34246 | 98511-H34246 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34247 | 98511-H34247 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34248 | 98511-H34248 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34249 | 98511-H34249 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34250 | 98511-H34250 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34251 | 98511-H34251 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34252 | 98511-H34252 | \$ 417.00 | 6% | \$394.92 |
| EWPPPremierPLSNBDOnsite H34253 | 98511-H34253 | \$ 417.00 | 6% | \$394.92 |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34254 | 98511-H34254 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34255 | 98511-H34255 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34256 | 98511-H34256 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34257 | 98511-H34257 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34258 | 98511-H34258 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34259 | 98511-H34259 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34260 | 98511-H34260 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34261 | 98511-H34261 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34262 | 98511-H34262 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34263 | 98511-H34263 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34264 | 98511-H34264 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34265 | 98511-H34265 | \$ 417.00 | 6% | <i>\$394.92</i> |
| EWPPPremierPLSNBDOnsite H34266 | 98511-H34266 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34267 | 98511-H34267 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34268 | 98511-H34268 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34269 | 98511-H34269 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34270 | 98511-H34270 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34271 | 98511-H34271 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34272 | 98511-H34272 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34273 | 98511-H34273 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34274 | 98511-H34274 | \$ 392.00 | 6% | <i>\$371.24</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34275 | 98511-H34275 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34276 | 98511-H34276 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34277 | 98511-H34277 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34278 | 98511-H34278 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34279 | 98511-H34279 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34280 | 98511-H34280 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34281 | 98511-H34281 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34282 | 98511-H34282 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34283 | 98511-H34283 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34284 | 98511-H34284 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34285 | 98511-H34285 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34286 | 98511-H34286 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34287 | 98511-H34287 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34288 | 98511-H34288 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34289 | 98511-H34289 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34290 | 98511-H34290 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34291 | 98511-H34291 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34292 | 98511-H34292 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34293 | 98511-H34293 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34294 | 98511-H34294 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34295 | 98511-H34295 | \$ 392.00 | 6% | <i>\$371.24</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34296 | 98511-H34296 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34297 | 98511-H34297 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34298 | 98511-H34298 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34299 | 98511-H34299 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34300 | 98511-H34300 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34301 | 98511-H34301 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34302 | 98511-H34302 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34303 | 98511-H34303 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34304 | 98511-H34304 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34305 | 98511-H34305 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H34306 | 98511-H34306 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34307 | 98511-H34307 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34308 | 98511-H34308 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34309 | 98511-H34309 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34310 | 98511-H34310 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34311 | 98511-H34311 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34312 | 98511-H34312 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34313 | 98511-H34313 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34314 | 98511-H34314 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34315 | 98511-H34315 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34316 | 98511-H34316 | \$ 424.00 | 6% | <i>\$401.55</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34317 | 98511-H34317 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34318 | 98511-H34318 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34319 | 98511-H34319 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34320 | 98511-H34320 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34321 | 98511-H34321 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34322 | 98511-H34322 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34323 | 98511-H34323 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34324 | 98511-H34324 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34325 | 98511-H34325 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34326 | 98511-H34326 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34327 | 98511-H34327 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34328 | 98511-H34328 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34329 | 98511-H34329 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34330 | 98511-H34330 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34331 | 98511-H34331 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34332 | 98511-H34332 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34333 | 98511-H34333 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34334 | 98511-H34334 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34335 | 98511-H34335 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34336 | 98511-H34336 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34337 | 98511-H34337 | \$ 424.00 | 6% | <i>\$401.55</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34338 | 98511-H34338 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34339 | 98511-H34339 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34340 | 98511-H34340 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34341 | 98511-H34341 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34342 | 98511-H34342 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34343 | 98511-H34343 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34344 | 98511-H34344 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34345 | 98511-H34345 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34346 | 98511-H34346 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34347 | 98511-H34347 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34348 | 98511-H34348 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34349 | 98511-H34349 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34350 | 98511-H34350 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34351 | 98511-H34351 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34352 | 98511-H34352 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34353 | 98511-H34353 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34354 | 98511-H34354 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34355 | 98511-H34355 | \$ 424.00 | 6% | <i>\$401.55</i> |
| EWPPPremierPLSNBDOnsite H34403 | 98511-H34403 | \$ 556.00 | 6% | <i>\$526.56</i> |
| EWPPPremierPLSNBDOnsite H34404 | 98511-H34404 | \$ 556.00 | 6% | <i>\$526.56</i> |
| EWPPPremierPLSNBDOnsite H34405 | 98511-H34405 | \$ 556.00 | 6% | <i>\$526.56</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|----------|
| EWPPPremierPLSNBDOnsite H34406 | 98511-H34406 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34407 | 98511-H34407 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34408 | 98511-H34408 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34409 | 98511-H34409 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34410 | 98511-H34410 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34411 | 98511-H34411 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34412 | 98511-H34412 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34413 | 98511-H34413 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34414 | 98511-H34414 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34415 | 98511-H34415 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34416 | 98511-H34416 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34417 | 98511-H34417 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34418 | 98511-H34418 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34419 | 98511-H34419 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34420 | 98511-H34420 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34421 | 98511-H34421 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34422 | 98511-H34422 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34423 | 98511-H34423 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34424 | 98511-H34424 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34425 | 98511-H34425 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34426 | 98511-H34426 | \$ 556.00 | 6% | \$526.56 |

| | | | | |
|-----------------------------------|--------------|-----------|----|----------|
| EWPPPremierPLSNBDOnsite H34427 | 98511-H34427 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34428 | 98511-H34428 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34429 | 98511-H34429 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34430 | 98511-H34430 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34431 | 98511-H34431 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34432 | 98511-H34432 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34433 | 98511-H34433 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34434 | 98511-H34434 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34435 | 98511-H34435 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34436 | 98511-H34436 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34437 | 98511-H34437 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34438 | 98511-H34438 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34439 | 98511-H34439 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34440 | 98511-H34440 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34441 | 98511-H34441 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34442 | 98511-H34442 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34443 | 98511-H34443 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34444 | 98511-H34444 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34445 | 98511-H34445 | \$ 556.00 | 6% | \$526.56 |
| EWPPPremierPLSNBDOnsite H34446 | 98511-H34446 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34447 | 98511-H34447 | \$ 594.00 | 6% | \$562.55 |

| | | | | |
|-----------------------------------|--------------|-----------|----|----------|
| EWPPPremierPLSNBDOnsite H34448 | 98511-H34448 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34449 | 98511-H34449 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34450 | 98511-H34450 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34451 | 98511-H34451 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34452 | 98511-H34452 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34453 | 98511-H34453 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34454 | 98511-H34454 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34455 | 98511-H34455 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34456 | 98511-H34456 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34457 | 98511-H34457 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34458 | 98511-H34458 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34459 | 98511-H34459 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34460 | 98511-H34460 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34461 | 98511-H34461 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34462 | 98511-H34462 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34463 | 98511-H34463 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34464 | 98511-H34464 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34465 | 98511-H34465 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34466 | 98511-H34466 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34467 | 98511-H34467 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34468 | 98511-H34468 | \$ 594.00 | 6% | \$562.55 |

| | | | | |
|-----------------------------------|--------------|-----------|----|----------|
| EWPPPremierPLSNBDOnsite H34469 | 98511-H34469 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34470 | 98511-H34470 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34471 | 98511-H34471 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34472 | 98511-H34472 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34473 | 98511-H34473 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34474 | 98511-H34474 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34475 | 98511-H34475 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34476 | 98511-H34476 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34477 | 98511-H34477 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34478 | 98511-H34478 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34479 | 98511-H34479 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34480 | 98511-H34480 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34481 | 98511-H34481 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34482 | 98511-H34482 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34483 | 98511-H34483 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34484 | 98511-H34484 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34485 | 98511-H34485 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34486 | 98511-H34486 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34487 | 98511-H34487 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34488 | 98511-H34488 | \$ 594.00 | 6% | \$562.55 |
| EWPPPremierPLSNBDOnsite H34489 | 98511-H34489 | \$ 594.00 | 6% | \$562.55 |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34490 | 98511-H34490 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34491 | 98511-H34491 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34492 | 98511-H34492 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34493 | 98511-H34493 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34494 | 98511-H34494 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34495 | 98511-H34495 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34496 | 98511-H34496 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34497 | 98511-H34497 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34498 | 98511-H34498 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34499 | 98511-H34499 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34500 | 98511-H34500 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34501 | 98511-H34501 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34502 | 98511-H34502 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34503 | 98511-H34503 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34504 | 98511-H34504 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34505 | 98511-H34505 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34506 | 98511-H34506 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34507 | 98511-H34507 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34508 | 98511-H34508 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34509 | 98511-H34509 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34510 | 98511-H34510 | \$ 370.00 | 6% | <i>\$350.41</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34511 | 98511-H34511 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34512 | 98511-H34512 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34513 | 98511-H34513 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34514 | 98511-H34514 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34515 | 98511-H34515 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34516 | 98511-H34516 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34517 | 98511-H34517 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34518 | 98511-H34518 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34519 | 98511-H34519 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34520 | 98511-H34520 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34521 | 98511-H34521 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34522 | 98511-H34522 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34523 | 98511-H34523 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34524 | 98511-H34524 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34525 | 98511-H34525 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34526 | 98511-H34526 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34527 | 98511-H34527 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34528 | 98511-H34528 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34529 | 98511-H34529 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34530 | 98511-H34530 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34531 | 98511-H34531 | \$ 370.00 | 6% | <i>\$350.41</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34532 | 98511-H34532 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34533 | 98511-H34533 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34534 | 98511-H34534 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34535 | 98511-H34535 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34536 | 98511-H34536 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34537 | 98511-H34537 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34538 | 98511-H34538 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34539 | 98511-H34539 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34540 | 98511-H34540 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34541 | 98511-H34541 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34542 | 98511-H34542 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34543 | 98511-H34543 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34544 | 98511-H34544 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34545 | 98511-H34545 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34546 | 98511-H34546 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34547 | 98511-H34547 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34548 | 98511-H34548 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34549 | 98511-H34549 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34550 | 98511-H34550 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34551 | 98511-H34551 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34552 | 98511-H34552 | \$ 370.00 | 6% | <i>\$350.41</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34553 | 98511-H34553 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34554 | 98511-H34554 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34555 | 98511-H34555 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34556 | 98511-H34556 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34557 | 98511-H34557 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34558 | 98511-H34558 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34559 | 98511-H34559 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34560 | 98511-H34560 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34561 | 98511-H34561 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34562 | 98511-H34562 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34563 | 98511-H34563 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34564 | 98511-H34564 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34565 | 98511-H34565 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34566 | 98511-H34566 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34567 | 98511-H34567 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34568 | 98511-H34568 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34569 | 98511-H34569 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34570 | 98511-H34570 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34571 | 98511-H34571 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34572 | 98511-H34572 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34573 | 98511-H34573 | \$ 370.00 | 6% | <i>\$350.41</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34574 | 98511-H34574 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34575 | 98511-H34575 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34576 | 98511-H34576 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34577 | 98511-H34577 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34578 | 98511-H34578 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34579 | 98511-H34579 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34580 | 98511-H34580 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34581 | 98511-H34581 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34582 | 98511-H34582 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34583 | 98511-H34583 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34584 | 98511-H34584 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34585 | 98511-H34585 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34586 | 98511-H34586 | \$ 370.00 | 6% | <i>\$350.41</i> |
| EWPPPremierPLSNBDOnsite H34587 | 98511-H34587 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34588 | 98511-H34588 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34589 | 98511-H34589 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34590 | 98511-H34590 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34591 | 98511-H34591 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34592 | 98511-H34592 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34593 | 98511-H34593 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34594 | 98511-H34594 | \$ 432.00 | 6% | <i>\$409.13</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34595 | 98511-H34595 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34596 | 98511-H34596 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34597 | 98511-H34597 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34598 | 98511-H34598 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34599 | 98511-H34599 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34600 | 98511-H34600 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34601 | 98511-H34601 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34602 | 98511-H34602 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34603 | 98511-H34603 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34604 | 98511-H34604 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34605 | 98511-H34605 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34606 | 98511-H34606 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34607 | 98511-H34607 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34608 | 98511-H34608 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34609 | 98511-H34609 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34610 | 98511-H34610 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34611 | 98511-H34611 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34612 | 98511-H34612 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34613 | 98511-H34613 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34614 | 98511-H34614 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34615 | 98511-H34615 | \$ 432.00 | 6% | <i>\$409.13</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34616 | 98511-H34616 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34617 | 98511-H34617 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34618 | 98511-H34618 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34619 | 98511-H34619 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34620 | 98511-H34620 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34621 | 98511-H34621 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34622 | 98511-H34622 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34623 | 98511-H34623 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34624 | 98511-H34624 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34625 | 98511-H34625 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34626 | 98511-H34626 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34627 | 98511-H34627 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34628 | 98511-H34628 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34629 | 98511-H34629 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34630 | 98511-H34630 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34631 | 98511-H34631 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H34632 | 98511-H34632 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34633 | 98511-H34633 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34634 | 98511-H34634 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34635 | 98511-H34635 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34636 | 98511-H34636 | \$ 440.00 | 6% | <i>\$416.70</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34637 | 98511-H34637 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34638 | 98511-H34638 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34639 | 98511-H34639 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34640 | 98511-H34640 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34641 | 98511-H34641 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34642 | 98511-H34642 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34643 | 98511-H34643 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34644 | 98511-H34644 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34645 | 98511-H34645 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34646 | 98511-H34646 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34647 | 98511-H34647 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34648 | 98511-H34648 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34649 | 98511-H34649 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34650 | 98511-H34650 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34651 | 98511-H34651 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34652 | 98511-H34652 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34653 | 98511-H34653 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34654 | 98511-H34654 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34655 | 98511-H34655 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34656 | 98511-H34656 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34657 | 98511-H34657 | \$ 440.00 | 6% | <i>\$416.70</i> |

| | | | | |
|-----------------------------------|--------------|-----------|----|-----------------|
| EWPPPremierPLSNBDOnsite H34658 | 98511-H34658 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34659 | 98511-H34659 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34660 | 98511-H34660 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34661 | 98511-H34661 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34662 | 98511-H34662 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34663 | 98511-H34663 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34664 | 98511-H34664 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34665 | 98511-H34665 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34666 | 98511-H34666 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34667 | 98511-H34667 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34668 | 98511-H34668 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34669 | 98511-H34669 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34670 | 98511-H34670 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34671 | 98511-H34671 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34672 | 98511-H34672 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34673 | 98511-H34673 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34674 | 98511-H34674 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34675 | 98511-H34675 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34676 | 98511-H34676 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34677 | 98511-H34677 | \$ 440.00 | 6% | <i>\$416.70</i> |
| EWPPPremierPLSNBDOnsite H34678 | 98511-H34678 | \$ 440.00 | 6% | <i>\$416.70</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H34726 | 98511-H34726 | \$ 4,330.00 | 6% | <i>\$4,100.73</i> |
| EWPPPremierPLSNBDOnsite H34727 | 98511-H34727 | \$ 4,330.00 | 6% | <i>\$4,100.73</i> |
| EWPPPremierPLSNBDOnsite H34728 | 98511-H34728 | \$ 4,330.00 | 6% | <i>\$4,100.73</i> |
| EWPPPremierPLSNBDOnsite H34729 | 98511-H34729 | \$ 4,330.00 | 6% | <i>\$4,100.73</i> |
| EWPPPremierPLSNBDOnsite H34730 | 98511-H34730 | \$ 4,551.00 | 6% | <i>\$4,310.02</i> |
| EWPPPremierPLSNBDOnsite H34731 | 98511-H34731 | \$ 4,551.00 | 6% | <i>\$4,310.02</i> |
| EWPPPremierPLSNBDOnsite H34732 | 98511-H34732 | \$ 4,551.00 | 6% | <i>\$4,310.02</i> |
| EWPPPremierPLSNBDOnsite H34733 | 98511-H34733 | \$ 4,551.00 | 6% | <i>\$4,310.02</i> |
| EWPPPremierPLSNBDOnsite H34734 | 98511-H34734 | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWPPPremierPLSNBDOnsite H34735 | 98511-H34735 | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWPPPremierPLSNBDOnsite H34736 | 98511-H34736 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34737 | 98511-H34737 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34738 | 98511-H34738 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34739 | 98511-H34739 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34740 | 98511-H34740 | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWPPPremierPLSNBDOnsite H34741 | 98511-H34741 | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWPPPremierPLSNBDOnsite H34742 | 98511-H34742 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWPPPremierPLSNBDOnsite H34743 | 98511-H34743 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWPPPremierPLSNBDOnsite H34744 | 98511-H34744 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34745 | 98511-H34745 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34746 | 98511-H34746 | \$ 1,961.00 | 6% | <i>\$1,857.17</i> |

| | | | | |
|-----------------------------------|--------------|--------------|----|--------------------|
| EWPPPremierPLSNBDOnsite H34747 | 98511-H34747 | \$ 1,961.00 | 6% | <i>\$1,857.17</i> |
| EWPPPremierPLSNBDOnsite H34748 | 98511-H34748 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34749 | 98511-H34749 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34750 | 98511-H34750 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34751 | 98511-H34751 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34752 | 98511-H34752 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34753 | 98511-H34753 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34754 | 98511-H34754 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34755 | 98511-H34755 | \$ 2,428.00 | 6% | <i>\$2,299.44</i> |
| EWPPPremierPLSNBDOnsite H34756 | 98511-H34756 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34757 | 98511-H34757 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34758 | 98511-H34758 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34759 | 98511-H34759 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34760 | 98511-H34760 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34761 | 98511-H34761 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H34993 | 98511-H34993 | \$ 20,452.00 | 6% | <i>\$19,369.07</i> |
| EWPPPremierPLSNBDOnsite H34994 | 98511-H34994 | \$ 20,452.00 | 6% | <i>\$19,369.07</i> |
| EWPPPremierPLSNBDOnsite H34996 | 98511-H34996 | \$ 20,452.00 | 6% | <i>\$19,369.07</i> |
| EWPPPremierPLSNBDOnsite H34997 | 98511-H34997 | \$ 20,452.00 | 6% | <i>\$19,369.07</i> |
| EWPPPremierPLSNBDOnsite H35005 | 98511-H35005 | \$ 14,763.00 | 6% | <i>\$13,981.30</i> |
| EWPPPremierPLSNBDOnsite H35006 | 98511-H35006 | \$ 14,763.00 | 6% | <i>\$13,981.30</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H35012 | 98511-H35012 | \$ 9,909.00 | 6% | <i>\$9,384.32</i> |
| EWPPPremierPLSNBDOnsite H35070 | 98511-H35070 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35071 | 98511-H35071 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35072 | 98511-H35072 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35073 | 98511-H35073 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35074 | 98511-H35074 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35075 | 98511-H35075 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35076 | 98511-H35076 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35077 | 98511-H35077 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35078 | 98511-H35078 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35079 | 98511-H35079 | \$ 392.00 | 6% | <i>\$371.24</i> |
| EWPPPremierPLSNBDOnsite H35080 | 98511-H35080 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H35081 | 98511-H35081 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H35082 | 98511-H35082 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H35083 | 98511-H35083 | \$ 432.00 | 6% | <i>\$409.13</i> |
| EWPPPremierPLSNBDOnsite H35270 | 98511-H35270 | \$ 1,702.00 | 6% | <i>\$1,611.88</i> |
| EWPPPremierPLSNBDOnsite H35271 | 98511-H35271 | \$ 1,580.00 | 6% | <i>\$1,496.34</i> |
| EWPPPremierPLSNBDOnsite H35272 | 98511-H35272 | \$ 1,439.00 | 6% | <i>\$1,362.80</i> |
| EWPPPremierPLSNBDOnsite H35273 | 98511-H35273 | \$ 1,439.00 | 6% | <i>\$1,362.80</i> |
| EWPPPremierPLSNBDOnsite H35274 | 98511-H35274 | \$ 1,961.00 | 6% | <i>\$1,857.17</i> |
| EWPPPremierPLSNBDOnsite H35275 | 98511-H35275 | \$ 1,854.00 | 6% | <i>\$1,755.83</i> |

| | | | | |
|---------------------------------------|--------------|--------------|----|-------------|
| EWPPPremierPLSNBDOnsite H35276 | 98511-H35276 | \$ 4,130.00 | 6% | \$3,911.32 |
| EWPPPremierPLSNBDOnsite H35277 | 98511-H35277 | \$ 4,854.00 | 6% | \$4,596.98 |
| EWPPPremierPLSNBDOnsite H35278 | 98511-H35278 | \$ 3,694.00 | 6% | \$3,498.40 |
| EWPPPremierPLSNBDOnsite H35279 | 98511-H35279 | \$ 4,123.00 | 6% | \$3,904.69 |
| EWPPPremierPLSNBDOnsite H35280 | 98511-H35280 | \$ 7,482.00 | 6% | \$7,085.83 |
| EWPP PremierPLSNBDOnsite H35294 | 98511-H35294 | \$ 2,292.00 | 6% | \$2,170.64 |
| EWPPPremierPLSNBDOnsite H35295 | 98511-H35295 | \$ 1,516.00 | 6% | \$1,435.73 |
| EWPP PremierPLUS NBD ONSITE H35296 | 98511-H35296 | \$ 11,661.00 | 6% | \$11,043.55 |
| EWPP PremierPLUS NBD ONSITE H35297 | 98511-H35297 | \$ 11,661.00 | 6% | \$11,043.55 |
| EWPP PremierPLUS NBD ONSITE H35298 | 98511-H35298 | \$ 18,733.00 | 6% | \$17,741.09 |
| EWPP PremierPLUS NBD ONSITE H35299 | 98511-H35299 | \$ 18,733.00 | 6% | \$17,741.09 |
| EWPP PremeirPLSNBDOnsite H35302 | 98511-H35302 | \$ 4,536.00 | 6% | \$4,295.82 |
| EWPP PremeirPLSNBDOnsite H35303 | 98511-H35303 | \$ 4,536.00 | 6% | \$4,295.82 |
| EWPP PremeirPLSNBDOnsite H35304 | 98511-H35304 | \$ 4,536.00 | 6% | \$4,295.82 |
| EWPP PremeirPLSNBDOnsite H35305 | 98511-H35305 | \$ 4,694.00 | 6% | \$4,445.45 |
| EWPP PremeirPLSNBDOnsite H35306 | 98511-H35306 | \$ 4,694.00 | 6% | \$4,445.45 |
| EWPP PremeirPLSNBDOnsite H35307 | 98511-H35307 | \$ 4,694.00 | 6% | \$4,445.45 |
| EWPP PremierPLSNBDOnsite H35309 | 98511-H35309 | \$ 4,796.00 | 6% | \$4,542.05 |
| EWPP PremeirPLSNBDOnsite H35310 | 98511-H35310 | \$ 4,796.00 | 6% | \$4,542.05 |
| EWPP PremierPLSNBDOnsite H35311 | 98511-H35311 | \$ 4,796.00 | 6% | \$4,542.05 |
| EWPP PremierPLSNBDOnsite H35312 | 98511-H35312 | \$ 3,963.00 | 6% | \$3,753.16 |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPP PremierPLSNBDOnsite H35313 | 98511-H35313 | \$ 3,963.00 | 6% | <i>\$3,753.16</i> |
| EWPP PremierPLSNBDOnsite H35314 | 98511-H35314 | \$ 3,963.00 | 6% | <i>\$3,753.16</i> |
| EWPP PremeirPLSNBDOnsite H35315 | 98511-H35315 | \$ 2,399.00 | 6% | <i>\$2,271.97</i> |
| EWPP PremierPLSNBDOnsite H35318 | 98511-H35318 | \$ 1,748.00 | 6% | <i>\$1,655.44</i> |
| EWPP PremierPLSNBDOnsite H35319 | 98511-H35319 | \$ 1,925.00 | 6% | <i>\$1,823.07</i> |
| EWPP PremierPLSNBDOnsite H35320 | 98511-H35320 | \$ 1,973.00 | 6% | <i>\$1,868.53</i> |
| EWPP PremierPLSNBDOnsite H35321 | 98511-H35321 | \$ 2,159.00 | 6% | <i>\$2,044.68</i> |
| EWPP PremierPLSNBDOnsite H35322 | 98511-H35322 | \$ 2,423.00 | 6% | <i>\$2,294.70</i> |
| EWPP PremierPLSNBDOnsite H35323 | 98511-H35323 | \$ 2,399.00 | 6% | <i>\$2,271.97</i> |
| EWPP PremierPLSNBDOnsite H35328 | 98511-H35328 | \$ 851.00 | 6% | <i>\$805.94</i> |
| EWPPPremierPLSNBDOnsite H35330 | 98511-H35330 | \$ 1,175.00 | 6% | <i>\$1,112.78</i> |
| EWPP PremeirPLSNBDOnsite H35340 | 98511-H35340 | \$ 5,098.00 | 6% | <i>\$4,828.06</i> |
| EWPP PremeirPLSNBDOnsite H35341 | 98511-H35341 | \$ 5,098.00 | 6% | <i>\$4,828.06</i> |
| EWPP PremeirPLSNBDOnsite H35342 | 98511-H35342 | \$ 4,157.00 | 6% | <i>\$3,936.89</i> |
| EWPP PremeirPLSNBDOnsite H35343 | 98511-H35343 | \$ 5,098.00 | 6% | <i>\$4,828.06</i> |
| EWPP PremeirPLSNBDOnsite H35344 | 98511-H35344 | \$ 5,215.00 | 6% | <i>\$4,938.87</i> |
| EWPP PremeirPLSNBDOnsite H35345 | 98511-H35345 | \$ 5,215.00 | 6% | <i>\$4,938.87</i> |
| EWPP PremeirPLSNBDOnsite H35346 | 98511-H35346 | \$ 4,240.00 | 6% | <i>\$4,015.49</i> |
| EWPP PremeirPLSNBDOnsite H35347 | 98511-H35347 | \$ 5,215.00 | 6% | <i>\$4,938.87</i> |
| EWPP PremeirPLSNBDOnsite H35349 | 98511-H35349 | \$ 5,509.00 | 6% | <i>\$5,217.30</i> |
| EWPP PremeirPLSNBDOnsite H35350 | 98511-H35350 | \$ 5,509.00 | 6% | <i>\$5,217.30</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPP PremeirPLSNBDOnsite H35351 | 98511-H35351 | \$ 4,474.00 | 6% | <i>\$4,237.10</i> |
| EWPP PremeirPLSNBDOnsite H35352 | 98511-H35352 | \$ 5,509.00 | 6% | <i>\$5,217.30</i> |
| EWPP PremeirPLSNBDOnsite H35359 | 98511-H35359 | \$ 2,159.00 | 6% | <i>\$2,044.68</i> |
| EWPP PremeirPLSNBDOnsite H35360 | 98511-H35360 | \$ 2,423.00 | 6% | <i>\$2,294.70</i> |
| EWPP PremeirPLSNBDOnsite H35361 | 98511-H35361 | \$ 2,399.00 | 6% | <i>\$2,271.97</i> |
| EWPP PremeirPLSNBDOnsite H35362 | 98511-H35362 | \$ 1,748.00 | 6% | <i>\$1,655.44</i> |
| EWPP PremeirPLSNBDOnsite H35366 | 98511-H35366 | \$ 2,154.00 | 6% | <i>\$2,039.95</i> |
| EWPP PremeirPLSNBDOnsite H35367 | 98511-H35367 | \$ 2,510.00 | 6% | <i>\$2,377.10</i> |
| EWPP PremeirPLSNBDOnsite H35368 | 98511-H35368 | \$ 3,819.00 | 6% | <i>\$3,616.78</i> |
| EWPP PremeirPLSNBDOnsite H35369 | 98511-H35369 | \$ 1,248.00 | 6% | <i>\$1,181.92</i> |
| EWPP PremeirPLSNBDOnsite H35370 | 98511-H35370 | \$ 1,743.00 | 6% | <i>\$1,650.71</i> |
| EWPP PremeirPLSNBDOnsite H35375 | 98511-H35375 | \$ 1,290.00 | 6% | <i>\$1,221.69</i> |
| EWPP PremeirPLSNBDOnsite H35376 | 98511-H35376 | \$ 1,933.00 | 6% | <i>\$1,830.65</i> |
| EWPP PremeirPLSNBDOnsite H35377 | 98511-H35377 | \$ 803.00 | 6% | <i>\$760.48</i> |
| EWPP PremeirPLSNBDOnsite H35378 | 98511-H35378 | \$ 1,290.00 | 6% | <i>\$1,221.69</i> |
| EWPP PremeirPLSNBDOnsite H35379 | 98511-H35379 | \$ 803.00 | 6% | <i>\$760.48</i> |
| EWPP PremeirPLSNBDOnsite H35380 | 98511-H35380 | \$ 1,447.00 | 6% | <i>\$1,370.38</i> |
| EWPP PremeirPLSNBDOnsite H35381 | 98511-H35381 | \$ 1,769.00 | 6% | <i>\$1,675.33</i> |
| EWPP PremeirPLSNBDOnsite H35384 | 98511-H35384 | \$ 622.00 | 6% | <i>\$589.07</i> |
| EWPP PremeirPLSNBDOnsite H35385 | 98511-H35385 | \$ 831.00 | 6% | <i>\$787.00</i> |
| EWPP PremeirPLSNBDOnsite H35386 | 98511-H35386 | \$ 1,388.00 | 6% | <i>\$1,314.51</i> |

| | | | | |
|------------------------------------|--------------|-------------|----|-------------------|
| EWPP PremeirPLSNBDOnsite H35387 | 98511-H35387 | \$ 1,298.00 | 6% | <i>\$1,229.27</i> |
| EWPP PremeirPLSNBDOnsite H35388 | 98511-H35388 | \$ 953.00 | 6% | <i>\$902.54</i> |
| EWPP PremeirPLSNBDOnsite H35389 | 98511-H35389 | \$ 533.00 | 6% | <i>\$504.78</i> |
| EWPP PremeirPLSNBDOnsite H35390 | 98511-H35390 | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWPP PremeirPLSNBDOnsite H35391 | 98511-H35391 | \$ 1,019.00 | 6% | <i>\$965.04</i> |
| EWPP PremeirPLSNBDOnsite H35392 | 98511-H35392 | \$ 1,556.00 | 6% | <i>\$1,473.61</i> |
| EWPP PremeirPLSNBDOnsite H35393 | 98511-H35393 | \$ 2,075.00 | 6% | <i>\$1,965.13</i> |
| EWPP PremeirPLSNBDOnsite H35394 | 98511-H35394 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWPP PremeirPLSNBDOnsite H35395 | 98511-H35395 | \$ 311.00 | 6% | <i>\$294.53</i> |
| EWPP PremeirPLSNBDOnsite H35396 | 98511-H35396 | \$ 377.00 | 6% | <i>\$357.04</i> |
| EWPP PremeirPLSNBDOnsite H35397 | 98511-H35397 | \$ 311.00 | 6% | <i>\$294.53</i> |
| EWPP PremeirPLSNBDOnsite H35398 | 98511-H35398 | \$ 973.00 | 6% | <i>\$921.48</i> |
| EWPP PremeirPLSNBDOnsite H35399 | 98511-H35399 | \$ 1,181.00 | 6% | <i>\$1,118.47</i> |
| EWPP PremeirPLSNBDOnsite H35400 | 98511-H35400 | \$ 1,297.00 | 6% | <i>\$1,228.32</i> |
| EWPP PremeirPLSNBDOnsite H35401 | 98511-H35401 | \$ 693.00 | 6% | <i>\$656.31</i> |
| EWPP PremeirPLSNBDOnsite H35415 | 98511-H35415 | \$ 433.00 | 6% | <i>\$410.07</i> |
| EWPP PremeirPLSNBDOnsite H35416 | 98511-H35416 | \$ 433.00 | 6% | <i>\$410.07</i> |
| EWPP PremeirPLSNBDOnsite H35426 | 98511-H35426 | \$ 533.00 | 6% | <i>\$504.78</i> |
| EWPP PremeirPLSNBDOnsite H35427 | 98511-H35427 | \$ 1,298.00 | 6% | <i>\$1,229.27</i> |
| EWPP PremeirPLSNBDOnsite H35428 | 98511-H35428 | \$ 461.00 | 6% | <i>\$436.59</i> |
| EWPP PremeirPLSNBDOnsite H35429 | 98511-H35429 | \$ 1,019.00 | 6% | <i>\$965.04</i> |

| | | | | |
|-----------------------------------|--------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H35430 | 98511-H35430 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H35431 | 98511-H35431 | \$ 1,667.00 | 6% | <i>\$1,578.73</i> |
| EWPPPremierPLSNBDOnsite H35432 | 98511-H35432 | \$ 1,626.00 | 6% | <i>\$1,539.90</i> |
| EWPPPremierPLSNBDOnsite H35433 | 98511-H35433 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWPPPremierPLSNBDOnsite H35434 | 98511-H35434 | \$ 1,868.00 | 6% | <i>\$1,769.09</i> |
| EWPPPremierPLSNBDOnsite H35435 | 98511-H35435 | \$ 1,868.00 | 6% | <i>\$1,769.09</i> |
| EWPPPremierPLSNBDOnsite H35436 | 98511-H35436 | \$ 2,312.00 | 6% | <i>\$2,189.58</i> |
| EWPPPremierPLSNBDOnsite H35437 | 98511-H35437 | \$ 2,312.00 | 6% | <i>\$2,189.58</i> |
| EWPPPremierPLSNBDOnsite H35438 | 98511-H35438 | \$ 2,312.00 | 6% | <i>\$2,189.58</i> |
| EWPPPremierPLSNBDOnsite H35439 | 98511-H35439 | \$ 2,312.00 | 6% | <i>\$2,189.58</i> |
| EWPPPremierPLSNBDOnsite H35440 | 98511-H35440 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWPPPremierPLSNBDOnsite H35441 | 98511-H35441 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWPPPremierPLSNBDOnsite H35442 | 98511-H35442 | \$ 1,792.00 | 6% | <i>\$1,697.11</i> |
| EWPPPremierPLSNBDOnsite H35443 | 98511-H35443 | \$ 4,330.00 | 6% | <i>\$4,100.73</i> |
| EWPPPremierPLSNBDOnsite H35444 | 98511-H35444 | \$ 4,551.00 | 6% | <i>\$4,310.02</i> |
| EWPPPremierPLSNBDOnsite H35445 | 98511-H35445 | \$ 4,130.00 | 6% | <i>\$3,911.32</i> |
| EWPPPremierPLSNBDOnsite H35446 | 98511-H35446 | \$ 4,051.00 | 6% | <i>\$3,836.50</i> |
| EWPPPremierPLSNBDOnsite H35447 | 98511-H35447 | \$ 4,623.00 | 6% | <i>\$4,378.21</i> |
| EWPPPremierPLSNBDOnsite H35448 | 98511-H35448 | \$ 4,481.00 | 6% | <i>\$4,243.73</i> |
| EWPPPremierPLSNBDOnsite H35449 | 98511-H35449 | \$ 3,694.00 | 6% | <i>\$3,498.40</i> |
| EWPPPremierPLSNBDOnsite H35450 | 98511-H35450 | \$ 3,927.00 | 6% | <i>\$3,719.07</i> |

| | | | | |
|---|-------------------------|-------------|----|-------------------|
| EWPPPremierPLSNBDOnsite H35451 | 98511-H35451 | \$ 7,958.00 | 6% | <i>\$7,536.62</i> |
| EWPPPremierPLSNBDOnsite H35452 | 98511-H35452 | \$ 7,958.00 | 6% | <i>\$7,536.62</i> |
| EWPPPremierPLSNBDOnsite H35453 | 98511-H35453 | \$ 4,551.00 | 6% | <i>\$4,310.02</i> |
| EWPPPremierPLSNBDOnsite H35454 | 98511-H35454 | \$ 4,330.00 | 6% | <i>\$4,100.73</i> |
| EWPP PremeirPLSNBDOnsite H35455 | 98511-H35455 | \$ 1,973.00 | 6% | <i>\$1,868.53</i> |
| EWPP PremierPLSNBDOnsite H35456 | 98511-H35456 | \$ 2,182.00 | 6% | <i>\$2,066.46</i> |
| EWPP PremierPLSNBDOnsite H35457 | 98511-H35457 | \$ 2,094.00 | 6% | <i>\$1,983.12</i> |
| EWPP PremierPLSNBDOnsite H35458 | 98511-H35458 | \$ 2,198.00 | 6% | <i>\$2,081.62</i> |
| EWPP PremierPLSNBDOnsite H35471 | 98511-H35471 | \$ 1,973.00 | 6% | <i>\$1,868.53</i> |
| EWPPPremierPLSNBDOnsite H35600 | 98511-H35600 | \$ 1,439.00 | 6% | <i>\$1,362.80</i> |
| EWPPPremierPLSNBDOnsite H35601 | 98511-H35601 | \$ 1,439.00 | 6% | <i>\$1,362.80</i> |
| EWPPPremierPLSNBDOnsite H35602 | 98511-H35602 | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWPPPremierPLSNBDOnsite H35603 | 98511-H35603 | \$ 1,750.00 | 6% | <i>\$1,657.34</i> |
| EWPPPremierPLSNBDOnsite H35604 | 98511-H35604 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H35605 | 98511-H35605 | \$ 1,882.00 | 6% | <i>\$1,782.35</i> |
| EWPPPremierPLSNBDOnsite H35606 | 98511-H35606 | \$ 1,961.00 | 6% | <i>\$1,857.17</i> |
| EWPPPremierPLSNBDOnsite H35607 | 98511-H35607 | \$ 1,961.00 | 6% | <i>\$1,857.17</i> |
| EWPP PremeirPLSNBDOnsite ISW-24W-4X | 98511-ISW- 24W-4X | \$ 985.00 | 6% | <i>\$932.84</i> |
| EWPP PremeirPLSNBDOnsite ISW-4W-4WS-4X | 98511-ISW-4W- 4WS-4X | \$ 1,434.00 | 6% | <i>\$1,358.07</i> |
| EWPPPremierPLSNBDOnsite MSM128 | 98511- MSM128 | \$ 3,686.00 | 6% | <i>\$3,490.83</i> |
| EWPPPremierPLSNBDOnsite MSM48C | 98511- MSM48C | \$ 2,466.00 | 6% | <i>\$2,335.43</i> |

| | | | | |
|--|---------------------------------|--------------|-----|-------------|
| EWPP PremerPLSNBDOnsi SLX9150-48XT-DC-F | 98511- SLX9150- 48XT-DC-F | \$ 4,505.00 | 6% | \$4,266.46 |
| EWPP PremerPLSNBDOnsi SLX9150-48XT-DC-R | 98511- SLX9150- 48XT-DC-R | \$ 4,967.00 | 6% | \$4,704.00 |
| EWPP PremierPLSNBDOnsit SLX9150-48Y-DC-F | 98511- SLX9150-48Y- DC-F | \$ 4,403.00 | 6% | \$4,169.86 |
| EWPP PremierPLSNBDOnsit SLX9150-48Y-DC-R | 98511- SLX9150-48Y- DC-R | \$ 4,854.00 | 6% | \$4,596.98 |
| EWPP PremerPLSNBDOnsite SLX9740-40C | 98511- SLX9740-40C | \$ 15,889.00 | 6% | \$15,047.68 |
| EWPP PremerPLSNBDOnsiteSLX9740- 40C-AC-F | 98511- SLX9740-40C- AC-F | \$ 15,889.00 | 6% | \$15,047.68 |
| EWPP PremerPLSNBDOnsiteSLX9740- 40C-AC-R | 98511- SLX9740-40C- AC-R | \$ 15,889.00 | 10% | \$14,407.35 |
| EWPP PremerPLSNBDOnsiteSLX9740- 40C-DC-F | 98511- SLX9740-40C- DC-F | \$ 15,889.00 | 6% | \$15,047.68 |
| EWPP PremerPLSNBDOnsite SLX9740-80C | 98511- SLX9740-80C | \$ 28,904.00 | 6% | \$27,373.53 |
| EWPP PremerPLSNBDOnsiteSLX9740- 80C-AC-F | 98511- SLX9740-80C- AC-F | \$ 28,904.00 | 6% | \$27,373.53 |
| EWPP PremerPLSNBDOnsiteSLX9740- 80C-AC-R | 98511- SLX9740-80C- AC-R | \$ 28,904.00 | 10% | \$26,208.70 |
| EWPP PremerPLSNBDOnsiteSLX9740- 80C-DC-F | 98511- SLX9740-80C- DC-F | \$ 28,904.00 | 6% | \$27,373.53 |
| EWPP PremierPLSNBDOnsite V300-8P-2X | 98511-V300- 8P-2X | \$ 886.00 | 6% | \$839.09 |
| EWPP PremierPLSNBDOnsite V300-8T-2X | 98511-V300- 8T-2X | \$ 836.00 | 6% | \$791.73 |
| EWPP PremierPLSNBDOnsite V300HT-8P-2X | 98511-V300HT- 8P-2X | \$ 1,225.00 | 6% | \$1,160.14 |

| | | | | |
|---|---|-------------|----|------------|
| EWPP PremierPLSNBDOnsite V300HT-8T-2X | 98511-V300HT- 8T-2X | \$ 1,025.00 | 6% | \$970.73 |
| EWPPPremierPLSNBDOnsite VIM-SS | 98511-VIM-SS | \$ 624.00 | 6% | \$590.96 |
| EWPPPremierPLSNBDOnsite VIM-SS | 98511-VIM- SSV80 | \$ 771.00 | 6% | \$730.18 |
| EWPPPremierPLSNBDOnsite VIM2-S | 98511-VIM2- SS | \$ 623.00 | 6% | \$590.01 |
| EWPPPremierPLSNBDOnsite VIM2-S | 98511-VIM2- SS128 | \$ 1,124.00 | 6% | \$1,064.48 |
| EWPPPremierPLSNBDOnsite VIM2-V | 98511-VIM2- V80 | \$ 1,198.00 | 6% | \$1,134.57 |
| EWPPPremierPLSNBDOnsite VIM210 | 98511- VIM210G4X | \$ 1,719.00 | 6% | \$1,627.98 |
| EWPP PremPLNBD Ons VSP4900-12MXU-12XE | 98511- VSP4900- 12MXU-12XE | \$ 2,264.00 | 6% | \$2,144.12 |
| EWPP PremPLNBD Ons VSP4900-12MXU-12XE-B1 | 98511- VSP4900- 12MXU-12XE- B1 | \$ 2,264.00 | 6% | \$2,144.12 |
| EWPP PremierPLSNBDOnsite VSP4900-24S | 98511- VSP4900-24S | \$ 1,748.00 | 6% | \$1,655.44 |
| EWPP PremierPLSNBDOnsite VSP4900-24S-B3 | 98511- VSP4900-24S- B3 | \$ 1,748.00 | 6% | \$1,655.44 |
| EWPP PremierPLSNBDOnsite VSP4900-24XE | 98511- VSP4900- 24XE | \$ 2,264.00 | 6% | \$2,144.12 |
| EWPP PremierPLSNBDOnsite VSP4900-24XE-B3 | 98511- VSP4900- 24XE-B3 | \$ 2,264.00 | 6% | \$2,144.12 |
| EWPP PremierPLSNBDOnsite X435-24P-4S | 98511-X435- 24P-4S | \$ 1,013.00 | 6% | \$959.36 |
| EWPP PremierPLSNBDOnsite X435-24T-4S | 98511-X435- 24T-4S | \$ 884.00 | 6% | \$837.19 |
| EWPP PremierPLSNBDOnsite X435-8P-2T-W | 98511-X435- 8P-2T-W | \$ 884.00 | 6% | \$837.19 |
| EWPP PremierPLSNBDOnsite X435-8P-4S | 98511-X435- 8P-4S | \$ 868.00 | 6% | \$822.04 |
| EWPP PremierPLSNBDOnsite X435-8T-4S | 98511-X435- 8T-4S | \$ 841.00 | 6% | \$796.47 |

| | | | | |
|---|---------------------------|-------------|----|------------|
| EWPPPremierPLSNBDOnsite X460-2 | 98511-X460- 24P | \$ 2,444.00 | 6% | \$2,314.59 |
| EWPPPremierPLSNBDOnsite X460-2 | 98511-X460- 24T | \$ 2,114.00 | 6% | \$2,002.06 |
| EWPPPremierPLSNBDOnsite X460-2 | 98511-X460- 24TDC | \$ 2,503.00 | 6% | \$2,370.47 |
| EWPPPremierPLSNBDOnsite X460-2 | 98511-X460- 24X | \$ 2,826.00 | 6% | \$2,676.36 |
| EWPPPremierPLSNBDOnsite X460-2 | 98511-X460- 24XDC | \$ 3,002.00 | 6% | \$2,843.04 |
| EWPPPremierPLSNBDOnsite X460-4 | 98511-X460- 48P | \$ 2,826.00 | 6% | \$2,676.36 |
| EWPPPremierPLSNBDOnsite X460-4 | 98511-X460- 48T | \$ 2,606.00 | 6% | \$2,468.01 |
| EWPPPremierPLSNBDOnsite X460-4 | 98511-X460- 48TDC | \$ 2,951.00 | 6% | \$2,794.74 |
| EWPPPremierPLSNBDOnsite X460-4 | 98511-X460- 48X | \$ 3,340.00 | 6% | \$3,163.15 |
| EWPPPremierPLSNBDOnsite X460-4 | 98511-X460- 48XDC | \$ 3,281.00 | 6% | \$3,107.27 |
| EWPP PremeirPLSNBDOnsite X465-24MU | 98511-X465- 24MU | \$ 2,423.00 | 6% | \$2,294.70 |
| EWPP PremierPLSNBDOnsite X465-24S | 98511-X465- 24S | \$ 1,748.00 | 6% | \$1,655.44 |
| EWPP PremierPLSNBDOnsite X465-24S-B3 | 98511-X465- 24S-B3 | \$ 1,748.00 | 6% | \$1,655.44 |
| EWPP PremeirPLSNBDOnsite X465-24W | 98511-X465- 24W | \$ 1,748.00 | 6% | \$1,655.44 |
| EWPP PremierPLSNBDOnsite X465-24XE | 98511-X465- 24XE | \$ 2,264.00 | 6% | \$2,144.12 |
| EWPP PremierPLSNBDOnsite X465-24XE-B3 | 98511-X465- 24XE-B3 | \$ 2,264.00 | 6% | \$2,144.12 |
| EWPP PremeirPLSNBDOnsite X465-48P | 98511-X465- 48P | \$ 1,973.00 | 6% | \$1,868.53 |
| EWPP PremeirPLSNBDOnsite X465-48T | 98511-X465- 48T | \$ 1,925.00 | 6% | \$1,823.07 |
| EWPP PremeirPLSNBDOnsite X465-48W | 98511-X465- 48W | \$ 2,159.00 | 6% | \$2,044.68 |
| EWPP PremierPLSNBDOnsite X465i-48W | 98511-X465i- 48W | \$ 2,399.00 | 6% | \$2,271.97 |
| EWPP PremierPLSNBDOnsite X465i-48W-B1-S1 | 98511-X465i- 48W-B1-S1 | \$ 2,399.00 | 6% | \$2,271.97 |

| | | | | |
|---|---------------------------|--------------|-----|-------------|
| EWPP PremierPLSNBDOnsite X465i-48W-B2-S1 | 98511-X465i- 48W-B2-S1 | \$ 2,399.00 | 6% | \$2,271.97 |
| EWPPPremierPLSNBDOnsite X480-2 | 98511-X480- 24X | \$ 3,084.00 | 6% | \$2,920.70 |
| EWPPPremierPLSNBDOnsite X480-4 | 98511-X480- 48T | \$ 2,683.00 | 6% | \$2,540.94 |
| EWPPPremierPLSNBDOnsite X480-4 | 98511-X480- 48X | \$ 3,725.00 | 6% | \$3,527.76 |
| EWPP PremierPLSNBDOnsite X695-48Y-8C | 98511-X695- 48Y-8C | \$ 4,089.00 | 6% | \$3,872.49 |
| EWPP PremierPLSNBDOnsite XA1440 | 98511-XA1440 | \$ 1,050.00 | 6% | \$994.40 |
| EWPP PremierPLSNBDOnsite XA1480 | 98511-XA1480 | \$ 1,145.00 | 6% | \$1,084.37 |
| EWPPPremierPLSNBDOnsite XGM3-2 | 98511-XGM3- 2SF | \$ 771.00 | 6% | \$730.18 |
| EWPP PremeirPLSNBDOnsite XR600 | 98511-XR600 | \$ 1,241.00 | 6% | \$1,175.29 |
| Extreme 9920 16x100/40G line card | 9920-16C | \$140,705.00 | 48% | \$73,715.35 |
| Extreme 9920 4x400G line card | 9920-4D | \$140,700.00 | 48% | \$73,712.73 |
| Extreme 9920 AC Power Supply 1600W Front-Back | 9920-ACPWR- 1600W-F | \$6,381.00 | 48% | \$3,343.01 |
| Extreme 9920 DC Power Supply 1600W Front-Back | 9920-DCPWR- 1600W-F | \$8,934.00 | 48% | \$4,680.52 |
| Extreme 9920 Fan Front-Back | 9920-FAN-F | \$2,468.00 | 48% | \$1,292.99 |
| Extreme 9920 8-slot with four empty power supply slots and five empty fan slots | 9920-NPB-8 | \$130,592.00 | 48% | \$68,417.15 |
| PWR CRD 16A/250V CEE7/7 EURO | AA0020051-E6 | \$90.00 | 48% | \$47.15 |
| POWER CORD 15A/250V AS 3112 AUSTRALIA | AA0020057-E6 | \$90.00 | 48% | \$47.15 |
| POWER CORD 2.5M 10A IEC C13 TO NEMA 5-15 USA | AA0020062E6 | \$28.00 | 48% | \$14.67 |
| POWER CORD 2.5M 10A IEC C13 TO BS1363 UK | AA0020063E6 | \$30.00 | 48% | \$15.72 |
| POWER CORD 2.5M 10A IEC C13 TO CEE 7/17 EU | AA0020064E6 | \$26.00 | 48% | \$13.62 |
| POWER CORD 2.0M 10A IEC C15 TO NEMA 5-15 USA | AA0020074-E6 | \$37.00 | 48% | \$19.38 |

| | | | | |
|---|------------------|------------|-----|------------|
| PWR CRD 16A/250V CEE7/7 EURO | AA0020078-E6 | \$73.00 | 48% | \$38.24 |
| POWER CORD 2.5M IEC C15 TO CNS-10917 TAIWAN | AA0020094-E6 | \$58.00 | 48% | \$30.39 |
| POWER CORD 2.5M IEC C15 TO NBR 14136 BRAZIL | AA0020100-E6 | \$58.00 | 48% | \$30.39 |
| POWER CORD C15 TO L6-15P 250V/15A 2.5 METER TWIST AND LOCK | AA0020108-E6 | \$115.00 | 48% | \$60.25 |
| SFP+ ER SM 40KM | AA1403013-E6 | \$8,234.00 | 48% | \$4,313.79 |
| SFP+ LRM MMF 220M/300M | AA1403017-E6 | \$1,527.00 | 48% | \$800.00 |
| 10G-BX 10km SFP+ TX/RX pair AA1403170 | AA1403169-E6 | \$3,565.00 | 48% | \$1,867.70 |
| 10G-BX 10km SFP+ RX/TX pair AA1403169 | AA1403170-E6 | \$3,565.00 | 48% | \$1,867.70 |
| 40G LM4 QSFP+ UP TO 80m ON MMF | AA1404002-E6 | \$6,600.00 | 48% | \$3,457.74 |
| SFP 1000BASE-BX (LC) - 1310NM | AA1419069-E6 | \$1,312.00 | 48% | \$687.36 |
| SFP 1000BASE-BX (LC) - 1490NM | AA1419070-E6 | \$1,312.00 | 48% | \$687.36 |
| Cable cover for AP3000 or AP3000X to hide Ethernet Port and Ethernet cable. Includes a 7 Flat Cat5e RJ45 Cable and inline coupler. (5 Pack Kit) | ACC-3000-ETH-CAP | \$75.00 | 48% | \$39.29 |
| Cable cover for AP305C or AP305CX to hide Ethernet Port and Ethernet cable. Includes a 5 Flat Cat5e RJ45 Cable and inline coupler. (5 Pack Kit) | ACC-305C-ETH-CAP | \$64.00 | 48% | \$33.53 |
| Cable cover for AP4000 to hide Ethernet Port and Ethernet cable. Includes a 7 Flat Cat6 RJ45 Cable (5 Pack Kit) | ACC-4000-ETH-CAP | \$59.00 | 48% | \$30.91 |
| Cable cover for AP410C to hide Ethernet Port and Ethernet cable. Includes a 7 Flat Cat6 RJ45 Cable and inline coupler. (5 Pack Kit) | ACC-410C-ETH-CAP | \$89.00 | 48% | \$46.63 |

| | | | | |
|--|----------------------|------------|-----|-------------------|
| Adaptor Bracket for 3rd Party AIR-AP-BRACKET 1 and AIR-AP-BRACKET 2. | ACC-BKT-AX-ADAPT-012 | \$59.00 | 48% | <i>\$30.91</i> |
| Beam Mounting for Indoor Access Points | ACC-BKT-AX-BEAM | \$36.00 | 48% | <i>\$18.86</i> |
| Junction Box Mounting for Indoor Access Points | ACC-BKT-AX-JB | \$36.00 | 48% | <i>\$18.86</i> |
| Cloud AP Bracket for 1.5 inch wide T-bars varying in thickness from 3.175mm to 6.35mm | ACC-BKT-AX-TBW | \$27.00 | 48% | <i>\$14.15</i> |
| Adaptor bracket for Cloud AP to WiNG Mounting Plate (37201) 10 in pack | ACC-BKT-AX-WNGADAPT | \$308.00 | 48% | <i>\$161.36</i> |
| Desk Mount stand for the AP302W. Includes screws. | ACC-BKT-AX-WP-DSKSTD | \$31.00 | 48% | <i>\$16.24</i> |
| Surface Mounted Wallplate Housing Extension | ACC-BKT-AX-WP-EXT | \$21.00 | 48% | <i>\$11.00</i> |
| AP302W Wallplate in-box accessory (sold as a spare) | ACC-BKT-AX-WP-SPARE | \$21.00 | 48% | <i>\$11.00</i> |
| Adaptor bracket AH-ACC-BKT-TB for 15/16 Wide T-Bars Non-Flat/Protruded ceiling tiles | ACC-BKT-TB-NF | \$15.00 | 48% | <i>\$7.86</i> |
| Outdoor AP CAT6 Gasket enables cable diameter range from 6mm to 9.2mm (Pack of 10 Gaskets) | ACC-CAT6-LAN-GSKT | \$50.00 | 48% | <i>\$26.20</i> |
| Adaptor bracket for Outdoor AP460xxxC for tilting brackets (KT-147407-02 KT-150173-01 or MBO-ART02). | ACC-MBO-KT-AX | \$113.00 | 48% | <i>\$59.20</i> |
| Micro-USB to USB Console Adapter Cable for Extreme Wireless Access Points | ACC-WIFI-MICRO-USB | \$44.00 | 48% | <i>\$23.05</i> |
| LICENSERADIOSHARE ADV FORENSICS 1 AP | AD-FERS-P-1 | \$65.00 | 48% | <i>\$34.05</i> |
| LICENSE ADV FORENSICS FOR ONE SENSOR-AD | AD-FESN-P-1 | \$195.00 | 48% | <i>\$102.16</i> |
| LICENSERS WIPS FOR 1 SENSOR-ADSP | AD-FLRS-P-1 | \$99.00 | 48% | <i>\$51.87</i> |
| LICENSERS WIPS FOR 100 SENSOR-ADSP | AD-FLRS-P-100 | \$8,995.00 | 48% | <i>\$4,712.48</i> |
| LICENSE WIPS FOR ONE SENSOR-AIRDEFENSE | AD-SNFL-P-1 | \$695.00 | 48% | <i>\$364.11</i> |

| | | | | |
|---|------------------------|--------------|-----|--------------------|
| LICENSEVULNERABILITY ASSESMNT 1 SENSOR | AD-VASN-P-1 | \$295.00 | 48% | <i>\$154.55</i> |
| Ipe30so/ax Series switched AC/DC power supply (cordless) | ADP-06-00 | \$11.00 | 48% | <i>\$5.76</i> |
| TR Travel Reimbursement | AGTR_0_TRV L | \$ 1.00 | 1% | <i>\$1.00</i> |
| TR Attendee ASU Course | AGTR-ASU-pa | \$ 3,645.00 | 1% | <i>\$3,635.61</i> |
| TR Session ASU Course | AGTR-ASU-ps | \$ 14,580.00 | 1% | <i>\$14,542.46</i> |
| TR Certification Attendee | AGTR-exam-pa | \$ 1,215.00 | 1% | <i>\$1,211.87</i> |
| TR 1 Unit Attendee | AGTR-MOD- pa | \$ 1,215.00 | 1% | <i>\$1,211.87</i> |
| TR 1 Unit Session | AGTR-MOD- ps | \$ 4,860.00 | 1% | <i>\$4,847.49</i> |
| TR Attendee OHN Course | AGTR-OHN- pa | \$ 6,075.00 | 1% | <i>\$6,059.36</i> |
| TR Session OHN Course | AGTR-OHN- ps | \$ 24,300.00 | 1% | <i>\$24,237.43</i> |
| TR Attendee SDW Course | AGTR-SDW- pa | \$ 4,860.00 | 1% | <i>\$4,847.49</i> |
| TR Session SDW Course | AGTR-SDW- ps | \$ 19,440.00 | 1% | <i>\$19,389.94</i> |
| AP650X articulated indoor antenna kit (8 x Dual Band 5dBi antennas) | AH-ACC-ANT- AX-KT | \$155.00 | 48% | <i>\$81.20</i> |
| 9/16 ceiling mount brackets for Non-Flat/Protruded ceiling tiles - use with AH-ACC-BKT-AX-TB | AH-ACC-BKT- 916-KIT | \$24.00 | 48% | <i>\$12.57</i> |
| 15/16 ceiling mount brackets for Non-Flat/Protruded ceiling tiles - use with AH-ACC-BKT-AX-TB | AH-ACC-BKT- AC-KIT | \$24.00 | 48% | <i>\$12.57</i> |
| Outdoor AP stainless steel wall bracket assembly | AH-ACC-BKT- ASM | \$60.00 | 48% | <i>\$31.43</i> |
| Mounting bracket for Interlude ceilings. | AH-ACC-BKT- AX-IL | \$32.00 | 48% | <i>\$16.76</i> |
| Mounting bracket for Silhouette 1/8 and Silhouette 1/4 ceilings. | AH-ACC-BKT- AX-SL | \$32.00 | 48% | <i>\$16.76</i> |

| | | | | |
|---|-------------------|----------|-----|----------------|
| Mounting bracket for Prelude 15/16 and Suprafine 9/16 ceilings supported on AP630 AP650 AP650X AP305C AP305CX AP410C AP510C AP510CX | AH-ACC-BKT-AX-TB | \$32.00 | 48% | <i>\$16.76</i> |
| Mounting bracket for direct-to-wall installations. | AH-ACC-BKT-AX-WL | \$32.00 | 48% | <i>\$16.76</i> |
| AP1130 Marine grade accessory kit. All items are marine grade. Includes screw pack mounting brackets locking screw for mounting bracket 1-2.75 metal hose strap | AH-ACC-MRN-KIT | \$110.00 | 48% | <i>\$57.63</i> |
| AP100 series AP200 series AP300 series AP500 series Plenum Bracket Kit | AH-ACC-PLENUM-KIT | \$110.00 | 48% | <i>\$57.63</i> |
| 30W power adapter (12VDC 2.5A) for AP650 AP650X. | AH-ACC-PW-30W | \$89.00 | 48% | <i>\$46.63</i> |
| 6ft universal power cord with EU plug. Compatible with XR600P AP650/AP650X power supply or any switch. | AH-ACC-PW-CBL-EU | \$16.00 | 48% | <i>\$8.38</i> |
| 6ft universal power cord with Japan plug. Compatible with XR600P AP650/AP650X power supply or any switch. | AH-ACC-PW-CBL-JP | \$16.00 | 48% | <i>\$8.38</i> |
| 6ft universal power cord with Korea plug. Compatible with XR600P AP650/AP650X power supply or any switch. | AH-ACC-PW-CBL-KR | \$16.00 | 48% | <i>\$8.38</i> |
| 6ft 18 AWG universal power cord with US plug. Compatible with XR600P AP650/AP650X power supply or any switch. | AH-ACC-PW-CBL-US | \$16.00 | 48% | <i>\$8.38</i> |
| 36W power supply for AP550. Includes adaptor for US. Applicable for Canada | AH-ACC-PWR-36W-US | \$110.00 | 48% | <i>\$57.63</i> |
| Rubber feet for AP130/AP200 series/AP550 | AH-ACC-RBR-FT | \$10.00 | 48% | <i>\$5.24</i> |
| Outdoor Access Point stainless steel strap for 3 inches to 7 inches diameter pole | AH-ACC-STRP-MRN | \$22.00 | 48% | <i>\$11.53</i> |

| | | | | |
|---|----------------------|-------------|-----|------------|
| XR600 Mounting Brackets. Includes two brackets and screws. | AH-ACC- XR600-BKT | \$54.00 | 48% | \$28.29 |
| XR600 USB Protector. Includes screws. | AH-ACC- XR600-USB | \$10.00 | 48% | \$5.24 |
| AH-HM-S-PT-1Y | AH-HM-S-PT- 1Y | \$ 25.00 | 6% | \$23.68 |
| AH-HM-S-SL-1Y | AH-HM-S-SL- 1Y | \$ 80.00 | 10% | \$72.54 |
| AH-HM-S-VG-PT-1Y | AH-HM-S-VG- PT-1Y | \$ 99.00 | 6% | \$93.76 |
| AH-HM-S-VG-SL-1Y | AH-HM-S-VG- SL-1Y | \$ 300.00 | 10% | \$272.03 |
| Aerohive ID Manager directory integration add-on to enable employee sponsorship of guest accounts for 1 year. Requires devices to interface with user directory. Incl. phone support, sw subscription & customer portal access. Renewal only. | AH-IDM-DIR- 1YR | \$ 1,364.00 | 6% | \$1,291.78 |
| Aerohive ID Manager for 1 year for 1 active key without text messaging support. Includes phone support, software subscription and customer portal access. Renewal only. | AH-IDM- NOSMS-1YR | \$ 2.75 | 6% | \$2.60 |
| Aerohive ID Manager for 1 year for 1 active key with text messaging support. Includes phone support, software subscription and customer portal access. Renewal only. | AH-IDM-SMS- 1YR | \$ 11.00 | 6% | \$10.42 |
| VG-VA VPN Gateway Virtual Appliance | AH-VG-VA | \$3,599.00 | 48% | \$1,885.52 |
| Indoor Omni Directional external antenna with 5 ports RPSMA for indoor installations | AI-DP04360S | \$355.00 | 48% | \$185.98 |
| AI-DQ04360S Dipole Omni Array 5.5dBi/6dBi dual band outdoor with quad feed 36 leads and RPSMA connectors | AI-DQ04360S | \$915.00 | 48% | \$479.37 |

| | | | | |
|---|--------------------|------------|-----|-------------------|
| Dipole 3.2 dBi (2.4 GHz) and 5.2 dBi (5 GHz) dual band with RP-SMA connector (2 pack) | AI-DS0305360-RPSMA | \$30.00 | 48% | <i>\$15.72</i> |
| Panel 120 deg sector 5dBi/5dBi dual band outdoor 36 lead with 2 RP-SMA connectors | AIO-DD05120-RPSMA | \$740.00 | 48% | <i>\$387.69</i> |
| Panel 60 deg sector 7.5dBi (2.4 GHz) and 7.5dBi (2.4GHz) dual band 36 lead with 2 RP-SMA connectors outdoor rated | AIO-DD75060-RPSMA | \$720.00 | 48% | <i>\$377.21</i> |
| 15 dBi Indoor/Outdoor Sector 21 Deg 36 inch cable N type | AIO-DQ15021-N | \$1,329.00 | 48% | <i>\$696.26</i> |
| 15 dBi Indoor/Outdoor Sector 21 Deg 36 inch cable RPSMA | AIO-DQ15021-RPSMA | \$1,329.00 | 48% | <i>\$696.26</i> |
| UNIVERSAL RACK MOUNT KIT D ERS48XX ERS55XX ERS56XX VSP4000 VSP7000 | AL1011001-E6 | \$38.00 | 48% | <i>\$19.91</i> |
| DB-9 FEM TO RJ-45 CONS CON RED - CONV DB-9 M TO RJ45 SERIAL | AL2011020-E6 | \$14.00 | 48% | <i>\$7.33</i> |
| AVAYA RJ-45/DB-9 INTEGRATED CONSOLE CABLE. Note 1.5m cable with DB-9 Female for PC and RJ-45 for device console port. | AL2011022-E6 | \$24.00 | 48% | <i>\$12.57</i> |
| ERS3626GTS NO POWER CORD | AL3600A05-E6 | \$2,830.00 | 48% | <i>\$1,482.64</i> |
| ERS3650GTS NO POWER CORD | AL3600A06-E6 | \$4,919.00 | 48% | <i>\$2,577.06</i> |
| ERS3626GTS-PWR+ NO POWER CORD | AL3600A15-E6 | \$3,578.00 | 48% | <i>\$1,874.51</i> |
| ERS3650GTS-PWR+ NO POWER CORD | AL3600A16-E6 | \$5,819.00 | 48% | <i>\$3,048.57</i> |
| PT to PT 5.15-5.875 GHZ 19.5 dBi Dual Polarized Directional Antenna 2x2 5.15-5.875GHz 19.5dBi Az/EI 17/17deg | AO-DD19017N | \$1,234.00 | 48% | <i>\$646.49</i> |
| Indoor Dual Radio WiFi 6E AP 2.4 GHz and 6 GHz or 5GHz and 6GHz or 2.4 GHz and 5 GHz Multirate Port Internal antennas. Inc Mt (AH-ACC-BKT-AX-TB). Domain Israel | AP3000-IL | \$900.00 | 48% | <i>\$471.51</i> |

| | | | | |
|---|------------|------------|-----|-----------------|
| Indoor Dual Radio WiFi 6E AP 2.4 GHz and 6 GHz or 5GHz and 6GHz or 2.4 GHz and 5 GHz Multirate Port Internal antennas. Inc Mt (AH-ACC-BKT-AX-TB). Domain Tunisia | AP3000-TN | \$900.00 | 48% | <i>\$471.51</i> |
| Indoor Dual Radio WiFi 6E AP 2.4 GHz and 5 GHz or 5GHz and 6GHz Multirate Port Internal antennas. BLE/Zigbee. Inc Mt (AH-ACC-BKT-AX-TB). Domain World SKU | AP3000-WW | \$900.00 | 48% | <i>\$471.51</i> |
| Indoor Dual Radio WiFi 6E AP 2.4 GHz and 5 GHz or 5GHz and 6GHz Multirate Port External antennas. BLE/Zigbee. Inc Mt (AH-ACC-BKT-AX-TB). Domain World SKU | AP3000X-WW | \$1,150.00 | 48% | <i>\$602.49</i> |
| ExtremeCloud IQ Indoor WiFi6 Wallplate 2x2 radios with Dual 5GHz and 4 GE Ethernet ports with POE Out. Integrated light/power sensors BLE. AI/ML green mode. Internal antennas. Domain Canada | AP302W-CAN | \$574.00 | 48% | <i>\$300.72</i> |
| ExtremeCloud IQ Indoor WiFi6 Wallplate 2x2 radios with Dual 5GHz and 4 GE Ethernet ports with POE Out. Integrated light/power sensors BLE. AI/ML green mode. Internal antennas. Domain Egypt | AP302W-EG | \$631.00 | 48% | <i>\$330.58</i> |
| ExtremeCloud IQ Indoor WiFi6 Wallplate 2x2 radios with Dual 5GHz and 4 GE Ethernet ports with POE Out. Integrated light/power sensors BLE. AI/ML green mode. Internal antennas. Domain US | AP302W-FCC | \$574.00 | 48% | <i>\$300.72</i> |

| | | | | |
|---|--------------|----------|-----|----------|
| ExtremeCloud IQ Indoor WiFi6 Wallplate 2x2 radios with Dual 5GHz and 4 GE Ethernet ports with POE Out. Integrated light/power sensors BLE. AI/ML green mode. Internal antennas. Domain EMEA and Rest Of World | AP302W-WR | \$574.00 | 48% | \$300.72 |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GE port. Integrated light/power sensors . AI/ML green mode. Internal antennas. Includes Connect. Domain Canada | AP305C-1-CAN | \$656.00 | 48% | \$343.68 |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors. AI/ML green mode. Internal antennas. Includes Connect. Domain Egypt | AP305C-1-EG | \$656.00 | 48% | \$343.68 |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors. AI/ML green mode. Internal antennas. Includes Connect. Domain US | AP305C-1-FCC | \$656.00 | 48% | \$343.68 |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors. AI/ML green mode. Internal antennas. Includes Connect. Domain Israel | AP305C-1-IL | \$656.00 | 48% | \$343.68 |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors. AI/ML green mode. Internal antennas. Includes Connect. Domain Rest of World | AP305C-1-WR | \$656.00 | 48% | \$343.68 |

| | | | | |
|--|------------|----------|-----|-----------------|
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal antennas. Includes Connect. Domain Canada | AP305C-CAN | \$709.00 | 48% | <i>\$371.45</i> |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal antennas. Includes Connect. Domain Egypt | AP305C-EG | \$709.00 | 48% | <i>\$371.45</i> |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal antennas. Includes Connect. Domain US | AP305C-FCC | \$709.00 | 48% | <i>\$371.45</i> |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal antennas. Includes Connect. Domain Israel | AP305C-IL | \$709.00 | 48% | <i>\$371.45</i> |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GbE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal antennas. Includes Connect. Domain Rest of World | AP305C-WR | \$709.00 | 48% | <i>\$371.45</i> |

| | | | | |
|--|-------------|----------|-----|-----------------|
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. External antenna support. Antennas sold separately. Includes Connect. Domain Canada | AP305CX-CAN | \$709.00 | 48% | <i>\$371.45</i> |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. External antenna support. Antennas sold separately. Includes Connect. Domain US | AP305CX-FCC | \$709.00 | 48% | <i>\$371.45</i> |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. External antenna support. Antennas sold separately. Includes Connect. Domain Israel | AP305CX-IL | \$709.00 | 48% | <i>\$371.45</i> |
| ExtremeCloud IQ Indoor WiFi 6 AP 2x2 radios with Dual 5GHz and 1x1GE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. External antenna support. Antennas sold separately. Includes Connect. Domain Rest of World | AP305CX-WR | \$709.00 | 48% | <i>\$371.45</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor External Antenna Access Point. Wi-Fi 6 - Domain EMEA Rest of World | AP310e-1-WR | \$759.00 | 48% | <i>\$397.64</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor External Antenna Access Point. Domain Canada | AP310e-CAN | \$863.00 | 48% | <i>\$452.13</i> |

| | | | | |
|--|-------------|------------|-----|-----------------|
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor External Antenna Access Point. Domain US and Puerto Rico | AP310e-FCC | \$863.00 | 48% | <i>\$452.13</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor External Antenna Access Point. Domain Israel | AP310e-IL | \$863.00 | 48% | <i>\$452.13</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor External Antenna Access Point. Domain EMEA Rest of World | AP310e-WR | \$863.00 | 48% | <i>\$452.13</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor Internal Antenna Access Point. Wi-Fi 6 - Domain EMEA Rest of World | AP310i-1-WR | \$759.00 | 48% | <i>\$397.64</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor Internal Antenna Access Point. Domain Canada | AP310i-CAN | \$863.00 | 48% | <i>\$452.13</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor Internal Antenna Access Point. Domain US and Puerto Rico | AP310i-FCC | \$863.00 | 48% | <i>\$452.13</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor Internal Antenna Access Point. Domain Israel | AP310i-IL | \$863.00 | 48% | <i>\$452.13</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Indoor Internal Antenna Access Point. Domain EMEA Rest of World | AP310i-WR | \$863.00 | 48% | <i>\$452.13</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Outdoor External Antenna Access Point. Domain Canada | AP360e-CAN | \$1,261.00 | 48% | <i>\$660.64</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Outdoor External Antenna Access Point. Domain US and Puerto Rico | AP360e-FCC | \$1,261.00 | 48% | <i>\$660.64</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Outdoor External Antenna Access Point. Domain Israel | AP360e-IL | \$1,261.00 | 48% | <i>\$660.64</i> |

| | | | | |
|---|--------------|------------|-----|-----------------|
| Dual Radio 802.11ax - 2x22 Dual 5G Outdoor External Antenna Access Point. Domain EMEA Rest of World | AP360e-WR | \$1,261.00 | 48% | <i>\$660.64</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Outdoor Internal Antenna Access Point. Domain Canada | AP360i-CAN | \$1,261.00 | 48% | <i>\$660.64</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Outdoor Internal Antenna Access Point. Domain US and Puerto Rico | AP360i-FCC | \$1,261.00 | 48% | <i>\$660.64</i> |
| Dual Radio 802.11ax - 2x22 Dual 5G Outdoor Internal Antenna Access Point. Domain EMEA Rest of World | AP360i-WR | \$1,261.00 | 48% | <i>\$660.64</i> |
| Indoor Tri Radio WiFi 6E AP 2.4 GHz 5GHz 6GHz Multirate Port. Integrated Light power sensors BLE/Zigbee. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Israel | AP4000-IL | \$1,249.00 | 48% | <i>\$654.35</i> |
| Indoor Tri Radio WiFi 6E AP 2.4 GHz 5GHz 6GHz Multirate Port. Integrated Light power sensors BLE/Zigbee. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain World Sku | AP4000-WW | \$1,249.00 | 48% | <i>\$654.35</i> |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Canada | AP410C-1-CAN | \$1,099.00 | 48% | <i>\$575.77</i> |

| | | | | |
|--|--------------|------------|-----|----------|
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Egypt | AP410C-1-EG | \$1,099.00 | 48% | \$575.77 |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain US | AP410C-1-FCC | \$1,099.00 | 48% | \$575.77 |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Israel | AP410C-1-IL | \$1,099.00 | 48% | \$575.77 |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Rest of World | AP410C-1-WR | \$1,099.00 | 48% | \$575.77 |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors BLE/Zigbee. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Canada | AP410C-CAN | \$1,203.00 | 48% | \$630.25 |

| | | | | |
|---|------------|------------|-----|-----------------|
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors BLE/Zigbee. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Egypt | AP410C-EG | \$1,203.00 | 48% | <i>\$630.25</i> |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors BLE/Zigbee. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain US | AP410C-FCC | \$1,203.00 | 48% | <i>\$630.25</i> |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors BLE/Zigbee. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Israel | AP410C-IL | \$1,203.00 | 48% | <i>\$630.25</i> |
| ExtremeCloud IQ Indoor Tri Radio WiFi 6 AP 2.4 GHz 5GHz Sensor w/ Dual 5GHz Multirate Port. Integrated Light power sensors BLE/Zigbee. AI/ML green mode. INT antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Rest of World | AP410C-WR | \$1,203.00 | 48% | <i>\$630.25</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor External Antenna Access Point. Domain Canada | AP410e-CAN | \$1,533.00 | 48% | <i>\$803.14</i> |

| | | | | |
|---|--------------|------------|-----|-----------------|
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor External Antenna Access Point. Domain US and Puerto Rico | AP410e-FCC | \$1,533.00 | 48% | <i>\$803.14</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor External Antenna Access Point. Domain EMEA Rest of World | AP410e-WR | \$1,533.00 | 48% | <i>\$803.14</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor Internal Antenna Access Point. Wi-Fi 6 - Domain US and Puerto Rico | AP410i-1-FCC | \$1,364.00 | 48% | <i>\$714.60</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor Internal Antenna Access Point. Wi-Fi 6 - Domain EMEA Rest of World | AP410i-1-WR | \$1,364.00 | 48% | <i>\$714.60</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor Internal Antenna Access Point. Domain Canada | AP410i-CAN | \$1,533.00 | 48% | <i>\$803.14</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor Internal Antenna Access Point. Domain US and Puerto Rico | AP410i-FCC | \$1,533.00 | 48% | <i>\$803.14</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor Internal Antenna Access Point. Domain Israel | AP410i-IL | \$1,533.00 | 48% | <i>\$803.14</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Indoor Internal Antenna Access Point. Domain EMEA Rest of World | AP410i-WR | \$1,533.00 | 48% | <i>\$803.14</i> |

| | | | | |
|---|------------|------------|-----|-----------------|
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal OMNI antenna. Domain Canada</p> | AP460C-CAN | \$1,481.00 | 48% | <i>\$775.90</i> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal OMNI antenna. Domain Egypt</p> | AP460C-EG | \$1,481.00 | 48% | <i>\$775.90</i> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal OMNI antenna.Domain US</p> | AP460C-FCC | \$1,481.00 | 48% | <i>\$775.90</i> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal OMNI antenna. Domain Israel</p> | AP460C-IL | \$1,481.00 | 48% | <i>\$775.90</i> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal OMNI antenna. Domain Rest of World</p> | AP460C-WR | \$1,481.00 | 48% | <i>\$775.90</i> |

| | | | | |
|---|-------------------|------------|-----|-----------------|
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Outdoor External Antenna Access Point. Domain Canada | AP460e-CAN | \$1,791.00 | 48% | <i>\$938.30</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Outdoor External Antenna Access Point. Domain US and Puerto Rico | AP460e-FCC | \$1,791.00 | 48% | <i>\$938.30</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Outdoor External Antenna Access Point. Domain EMEA Rest of World | AP460e-WR | \$1,791.00 | 48% | <i>\$938.30</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Outdoor Internal Antenna Access Point. Domain Canada | AP460i-CAN | \$1,791.00 | 48% | <i>\$938.30</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Outdoor Internal Antenna Access Point. Domain US and Puerto Rico | AP460i-FCC | \$1,791.00 | 48% | <i>\$938.30</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Outdoor Internal Antenna Access Point. Domain Israel | AP460i-IL | \$1,791.00 | 48% | <i>\$938.30</i> |
| Tri Radio 802.11ax - 4x44 + 2x22 Full time 2x22 Sensor Outdoor Internal Antenna Access Point. Domain EMEA Rest of World | AP460i-WR | \$1,791.00 | 48% | <i>\$938.30</i> |
| ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal sector antenna (120). Domain Canada | AP460S12C- CAN | \$1,481.00 | 48% | <i>\$775.90</i> |

| | | | | |
|---|----------------------------|-------------------|------------|------------------------|
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal sector antenna (120). Domain US</p> | <p>AP460S12C- FCC</p> | <p>\$1,481.00</p> | <p>48%</p> | <p><i>\$775.90</i></p> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal sector antenna (120). Domain Rest of World</p> | <p>AP460S12C- WR</p> | <p>\$1,481.00</p> | <p>48%</p> | <p><i>\$775.90</i></p> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal sector antenna (60). Domain Canada</p> | <p>AP460S6C- CAN</p> | <p>\$1,481.00</p> | <p>48%</p> | <p><i>\$775.90</i></p> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port . Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal sector antenna (60). Domain US</p> | <p>AP460S6C- FCC</p> | <p>\$1,481.00</p> | <p>48%</p> | <p><i>\$775.90</i></p> |
| <p>ExtremeCloud IQ Tri-radio Outdoor WiFi 6 AP (4x4 5 GHz 2x2 dual band 1x1 sensor). Dual 5GHz 2.5 GE 1 GE port. Integrated light/power sensors BLE/Zigbee. AI/ML green mode. Internal sector antenna (60). Domain Rest of World</p> | <p>AP460S6C- WR</p> | <p>\$1,481.00</p> | <p>48%</p> | <p><i>\$775.90</i></p> |

| | | | | |
|---|----------------|------------|-----|-------------------|
| Indoor Tri Radio WiFi 6E AP (4x44) 2.4 GHz 5GHz 6GHz Multirate Port Internal antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain Israel | AP5010-IL | \$1,999.00 | 48% | <i>\$1,047.28</i> |
| Indoor Tri Radio WiFi 6E AP (4x44) 2.4 GHz 5GHz 6GHz Multirate Port Internal antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain World SKU | AP5010-WW | \$1,999.00 | 48% | <i>\$1,047.28</i> |
| Indoor Tri Radio WiFi 7 AP 2.4 GHz 5GHz 6GHz Multirate Port Internal antennas. T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Domain World Sku | AP5020-WW | \$2,399.00 | 48% | <i>\$1,256.84</i> |
| Outdoor Internal Directional Antenna Tri Radio WiFi 6E AP (4x44) 2.4 GHz 5GHz 6GHz Multirate Port Directional Antennas software selectable 30 degrees or 70 degrees. Mounting sold separately. Domain World Sku | AP5050D-WW | \$4,999.00 | 48% | <i>\$2,618.98</i> |
| Outdoor Tri Radio WiFi 6E AP (4x44) 2.4 GHz 5GHz 6GHz Multirate Port Internal Omni antennas. Mounting sold separately Domain World Sku | AP5050U-WW | \$3,899.00 | 48% | <i>\$2,042.69</i> |
| Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Domain US Puerto Rico and Colombia | AP505i-FCC | \$1,483.00 | 48% | <i>\$776.94</i> |
| Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Domain US Puerto Rico and Colombia. TAA Compliant | AP505i-FCC-TAA | \$1,556.00 | 48% | <i>\$815.19</i> |
| Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Domain EMEA and Rest Of World | AP505i-WR | \$1,556.00 | 48% | <i>\$815.19</i> |

| | | | | |
|---|----------------|------------|-----|-------------------|
| ExtremeCloud IQ Indoor WiFi6 AP 4x4 radios 2.5 GbE 1 GbE port. Integrated light/power sensors BLE. AI/ML green mode. Internal antennas T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Includes Connect. All regulatory domains World Sku | AP510C-WW | \$1,822.00 | 48% | <i>\$954.55</i> |
| ExtremeCloud IQ Indoor WiFi6 AP 4x4 radios 2.5 GbE 1 GbE port. Integrated light/power sensors BLE. AI/ML green mode. External antennas T-Bar Incl Mt (AH-ACC-BKT-AX-TB). Includes Connect. All regulatory domains World Sku | AP510CX-WW | \$1,822.00 | 48% | <i>\$954.55</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point with external antenna ports. Domain US Puerto Rico and Colombia. | AP510e-FCC | \$2,076.00 | 48% | <i>\$1,087.62</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point with external antenna ports. Domain US Puerto Rico and Colombia. TAA Compliant. | AP510e-FCC-TAA | \$2,076.00 | 48% | <i>\$1,087.62</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point with external antenna ports. Domain EMEA and Rest Of World. | AP510e-WR | \$1,979.00 | 48% | <i>\$1,036.80</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Wi-Fi 6 - Domain US Puerto Rico and Colombia | AP510i-1-FCC | \$1,741.00 | 48% | <i>\$912.11</i> |

| | | | | |
|--|-----------------------|-------------|-----|--------------------|
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Wi-Fi 6 - Domain EMEA and Rest Of World | AP510i-1-WR | \$1,741.00 | 48% | <i>\$912.11</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Domain US Puerto Rico and Colombia | AP510i-FCC | \$1,946.00 | 48% | <i>\$1,019.51</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Domain US Puerto Rico and Colombia. TAA Compliant | AP510i-FCC-TAA | \$1,946.00 | 48% | <i>\$1,019.51</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Indoor 11ax access point. Internal Antenna. Domain EMEA and Rest Of World | AP510i-WR | \$1,946.00 | 48% | <i>\$1,019.51</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Outdoor 11ax access point. Internal Antenna. Domain US and Colombia | AP560i-FCC | \$3,379.00 | 48% | <i>\$1,770.26</i> |
| Dual 5GHz Dual band Sensor radio Dual Radio 802.11ax/ac/abgn 4x44 MIMO Outdoor 11ax access point. Internal Antenna. Domain Canada EMEA and Singapore | AP560i-WR | \$3,384.00 | 48% | <i>\$1,772.88</i> |
| SLX 9240-32C Switch. No Fans/Power supplies included. 32x100GE/40GE. | BR-SLX-9240-32C | \$56,159.00 | 48% | <i>\$29,421.70</i> |
| Advanced Feature License | BR-SLX-9240-ADV-LIC-P | \$7,259.00 | 48% | <i>\$3,802.99</i> |

| | | | | |
|--|-----------------------|-------------|-----|-------------|
| SLX 9540-24S Switch AC with Front to Back airflow (Port-side to non-port side airflow). Supports 24x10GE/1GE + 24x1GE ports. | BR-SLX-9540-24S-AC-F | \$51,060.00 | 48% | \$26,750.33 |
| SLX 9540-24S Switch AC with Back to Front airflow (Non-port Side to port side airflow). Supports 24x10GE/1GE + 24x1GE ports. | BR-SLX-9540-24S-AC-R | \$51,060.00 | 48% | \$26,750.33 |
| Upgrade 24x1GE to 24x10GE/1GE | BR-SLX-9540-24S-COD-P | \$5,495.00 | 48% | \$2,878.83 |
| SLX 9540-24S Switch DC with Front to Back airflow (Port-side to non-port side airflow). Supports 24x10GE/1GE + 24x1GE ports. | BR-SLX-9540-24S-DC-F | \$55,702.00 | 48% | \$29,182.28 |
| SLX 9540-24S Switch DC with Back to Front airflow (Non-port Side to port side airflow). Supports 24x10GE/1GE + 24x1GE ports. | BR-SLX-9540-24S-DC-R | \$55,702.00 | 48% | \$29,182.28 |
| Ports on Demand for 2x100GE/40GE Uplinks | BR-SLX-9540-2C-POD-P | \$5,995.00 | 48% | \$3,140.78 |
| SLX 9540-48S Switch AC with Front to Back airflow (Port-side to non-port side airflow). Supports 48x10GE/1GE + 6x100GE/40GE. (1+1) redundant power supplies and (4+1) redundant fans included. | BR-SLX-9540-48S-AC-F | \$71,178.00 | 48% | \$37,290.15 |
| SLX 9540-48S Switch AC with Back to Front airflow (Non-port Side to port side airflow). Supports 48x10GE/1GE + 6x100GE/40GE. (1+1) redundant power supplies and (4+1) redundant fans included. | BR-SLX-9540-48S-AC-R | \$71,178.00 | 48% | \$37,290.15 |

| | | | | |
|--|---------------------------|-------------|-----|-------------|
| SLX 9540-48S Switch DC with Front to Back airflow (Port-side to non-port side airflow). Supports 48x10GE/1GE + 6x100GE/40GE. (1+1) redundant power supplies and (4+1) redundant fans included. | BR-SLX-9540-48S-DC-F | \$77,367.00 | 48% | \$40,532.57 |
| SLX 9540-48S Switch DC with Back to Front airflow (Non-port Side to port side airflow). Supports 48x10GE/1GE + 6x100GE/40GE. (1+1) redundant power supplies and (4+1) redundant fans included. | BR-SLX-9540-48S-DC-R | \$77,367.00 | 48% | \$40,532.57 |
| Advanced Feature License | BR-SLX-9540-ADV-LIC-P | \$9,000.00 | 48% | \$4,715.10 |
| 6x100G POD SW license to be used with SLX9850-100Gx12CQ-M 100G blade only | BR-SLX9850-100GX6CQ-M-UPG | \$26,995.00 | 48% | \$14,142.68 |
| 2-PORT 40G Ports on Demand(POD) LICENSE FOR VDX6740 AND VDX6740T | BR-VDX6740-2X40G-POD | \$4,977.00 | 48% | \$2,607.45 |
| 8-PORT 10G SFP+ Ports on Demand(POD)LICENSE FOR VDX6740 and VDX6740T | BR-VDX6740-8X10G-POD | \$4,562.00 | 48% | \$2,390.03 |
| VCS S/W LICENSE FOR VDX6740 AND VDX6740T | BR-VDX6740-VCS | \$7,000.00 | 48% | \$3,667.30 |
| SW16-PORT 10G Capacity on Demand LIC FOR VDX6740T-1G | BR-VDX6740T-1G-16X10G-COD | \$6,844.00 | 48% | \$3,585.57 |
| BEAM CLIP for Mounting Plate | BRKT-000147A-01 | \$27.00 | 48% | \$14.15 |
| Router cable ipe30so/ax ipe40so/ax V2 ipe420ax Series | CBL-01-RO | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Argentina standard power cable | COS-01-AR | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Australian standard power cable | COS-01-AU | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Brazilian standard power cable | COS-01-BR | \$11.00 | 48% | \$5.76 |

| | | | | |
|---|-----------|---------|-----|---------|
| ipe30(ax)/ipe40(ax)/420ax Series Swiss standard power cable | COS-01-CH | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Chinese standard power cable | COS-01-CN | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Danish standard power cable | COS-01-DK | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series European standard power cable | COS-01-EU | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Isralian standard power cable | COS-01-IL | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series India/S. Africa standard power cable | COS-01-IN | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Italian standard power cable | COS-01-IT | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series Japanese standard power cable | COS-01-JP | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series United Kingdom standard power cable | COS-01-UK | \$11.00 | 48% | \$5.76 |
| ipe30(ax)/ipe40(ax)/420ax Series USA/Canada standard power cable | COS-01-US | \$11.00 | 48% | \$5.76 |
| ipe2000ax/4000ax Series Argentina standard power cables | COS-02-AR | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series Australian standard power cables | COS-02-AU | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series Brazilian standard power cables | COS-02-BR | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series Swiss standard power cables | COS-02-CH | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series Chinese standard power cables | COS-02-CN | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series Denmark standard power cables | COS-02-DK | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series European standard power cables | COS-02-EU | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series Isralian standard power cables | COS-02-IL | \$24.00 | 48% | \$12.57 |
| ipe2000ax/4000ax Series India/S. Africa standard power cables | COS-02-IN | \$24.00 | 48% | \$12.57 |

| | | | | |
|---|--------------------|--------------|-----|--------------------|
| ipe2000ax/4000ax Series Italian standard power cables | COS-02-IT | \$24.00 | 48% | <i>\$12.57</i> |
| ipe2000ax/4000ax Series Japanese standard power cables | COS-02-JP | \$24.00 | 48% | <i>\$12.57</i> |
| ipe2000ax/4000ax Series United Kingdom standard power cables | COS-02-UK | \$24.00 | 48% | <i>\$12.57</i> |
| ipe2000ax/4000ax Series USA/Canada standard power cables | COS-02-US | \$24.00 | 48% | <i>\$12.57</i> |
| CLOUD WLAN MGMT- FCC REG DOMAIN | CS-WLANNAM9 | \$99.00 | 48% | <i>\$51.87</i> |
| 1024X ADAPTIVE AP - WiNG AP Adoption Capacity for Universal Compute Platform HW | CX-WiNG-ADP-1024 | \$119,994.00 | 48% | <i>\$62,864.86</i> |
| 128X ADAPTIVE AP - WiNG AP Adoption Capacity for Universal Compute Platform HW | CX-WiNG-ADP-128 | \$15,234.00 | 48% | <i>\$7,981.09</i> |
| 16X ADAPTIVE AP - WiNG AP Adoption Capacity for Universal Compute Platform HW | CX-WiNG-ADP-16 | \$1,902.00 | 48% | <i>\$996.46</i> |
| 256X ADAPTIVE AP - WiNG AP Adoption Capacity for Universal Compute Platform HW | CX-WiNG-ADP-256 | \$30,414.00 | 48% | <i>\$15,933.89</i> |
| 64X ADAPTIVE AP - WiNG AP Adoption Capacity for Universal Compute Platform HW | CX-WiNG-ADP-64 | \$7,603.00 | 48% | <i>\$3,983.21</i> |
| 8X ADAPTIVE AP - WiNG AP Adoption Capacity for Universal Compute Platform HW | CX-WiNG-ADP-8 | \$954.00 | 48% | <i>\$499.80</i> |
| WiNG Controller Activation Key for Universal Compute Platform HW | CX-WiNG-APPLNC-LIC | \$1.00 | 48% | <i>\$0.52</i> |

| | | | | |
|--|----------------------|---------------|-----|--------------|
| ExtremeCloud IQ Controller E2122-1 (1300W Edition)-expandable to 2000 APs/Defenders and 800 Switches (Requires Separate Activation Key) | E2122-1 | \$46,199.00 | 38% | \$28,858.21 |
| ExtremeCloud IQ Controller E3120-1 (1300W Edition) - expandable to 5000 APs/Defenders and 1000 Switches (Requires Separate Activation Key) | E3120-1 | \$77,817.00 | 38% | \$48,608.39 |
| ExtremeCloud IQ Controller E3125 - expandable to 5000 APs/Defenders and 1000 Switches (Requires Separate Activation Key) | E3125 | \$84,000.00 | 38% | \$52,470.60 |
| ExtremeCloud Customer Success - 1Yr | EC-CS-1Y | \$ 89,995.00 | 1% | \$89,763.26 |
| Onsite Resident Engineer - 1 Month | EC-OPA-1M | \$ 60,000.00 | 1% | \$59,845.50 |
| Remote Resident Engineer - 1 Month | EC-OPA-1M-REMOTE | \$ 46,800.00 | 1% | \$46,679.49 |
| Onsite Resident Engineer - 12 Months | EC-OPA-1Y | \$ 384,000.00 | 1% | \$383,011.20 |
| Remote Engineer - 12 Months | EC-OPA-1Y-REMOTE | \$ 300,000.00 | 1% | \$299,227.50 |
| Onsite Resident Engineer - 3 Months | EC-OPA-3M | \$ 150,000.00 | 1% | \$149,613.75 |
| Remote Resident Engineer - 3 Months | EC-OPA-3M-REMOTE | \$ 117,000.00 | 1% | \$116,698.73 |
| Onsite Resident Engineer - 6 Months | EC-OPA-6M | \$ 240,000.00 | 1% | \$239,382.00 |
| Remote Resident Engineer - 6 Months | EC-OPA-6M-REMOTE | \$ 187,200.00 | 1% | \$186,717.96 |
| Remote Network Management - 1 Month | EC-OPA-EDU-1M-REMOTE | \$ 46,800.00 | 1% | \$46,679.49 |
| Remote Network Management - 12 Months | EC-OPA-EDU-1Y-REMOTE | \$ 300,000.00 | 1% | \$299,227.50 |
| Remote Network Management - 3 Months | EC-OPA-EDU-3M-REMOTE | \$ 117,000.00 | 1% | \$116,698.73 |

| | | | | |
|--|----------------------|---------------|-----|---------------------|
| Remote Network Management - 6 Months | EC-OPA-EDU-6M-REMOTE | \$ 187,200.00 | 1% | <i>\$186,717.96</i> |
| VSP 7200 8000 800W DC POWER SUPPLY FTB COOLING | EC8005001-E6 | \$2,342.00 | 48% | <i>\$1,226.97</i> |
| VSP 8000 100-240V 800W AC Power Supply (No power cord) | EC8005A01-E6 | \$1,246.00 | 48% | <i>\$652.78</i> |
| VSP 8000 Chassis Universal Slide Rack Mount Kit (300mm - 900mm) | EC8011002-E6 | \$969.00 | 48% | <i>\$507.66</i> |
| VSP 8400 CHASSIS SPARE FAN MODULE (QUANTITY - 1) | EC8011005-E6 | \$229.00 | 48% | <i>\$119.97</i> |
| VSP 8400 24 port 1/10G SFP+ IO Module | EC8404001-E6 | \$23,491.00 | 48% | <i>\$12,306.93</i> |
| 8424XS ESM 24 PORT 1/10G SFP+ GSA VERSION | EC8404001-E6GS | \$23,491.00 | 48% | <i>\$12,306.93</i> |
| VSP 8400 24 port 1/10G Copper IO Module | EC8404002-E6 | \$25,840.00 | 48% | <i>\$13,537.58</i> |
| 8424XT ESM 24 PORT 100M/1G/10G BASE-T GSA VERSION | EC8404002-E6GS | \$24,919.00 | 48% | <i>\$13,055.06</i> |
| VSP 8400 8 port 40G QSFP+ IO Module | EC8404003-E6 | \$23,491.00 | 48% | <i>\$12,306.93</i> |
| 8408QQ ESM 8 PORT 40G QSFP+ GSA VERSION | EC8404003-E6GS | \$22,654.00 | 48% | <i>\$11,868.43</i> |
| VSP 8400 16 port 1/10G SFP+ and 2 port 40G QSFP+ combination IO Module | EC8404005-E6 | \$23,491.00 | 48% | <i>\$12,306.93</i> |
| 8418XSQ ESM 16 PORT 1/10G SFP+2 PORT 40G QSFP+ COMBO GSA VERSION | EC8404005-E6GS | \$23,491.00 | 48% | <i>\$12,306.93</i> |
| VSP 8400 16 port 1/10G Copper and 2 port 40G QSFP+ combination IO Module | EC8404006-E6 | \$19,573.00 | 48% | <i>\$10,254.29</i> |
| 8418XTQ ESM 16 PORT 1/10G BASE-T () 2 PORT 40G QSFP+ GSA | EC8404006-E6GS | \$18,875.00 | 48% | <i>\$9,888.61</i> |
| VSP 8400 24 port 100/1000 Mbps SFP IO Module | EC8404007-E6 | \$8,608.00 | 48% | <i>\$4,509.73</i> |
| 8424GS ESM 24 PORT 100M/1G SFP GSA | EC8404007-E6GS | \$8,301.00 | 48% | <i>\$4,348.89</i> |

| | | | | |
|---|--------------------------|--------------|-----|--------------------|
| VSP 8400 24 port 10/100/1000 Mbps Copper IO Module | EC8404008-E6 | \$8,608.00 | 48% | <i>\$4,509.73</i> |
| 8424GT ES2M 24 PORT 10M/100M/1G BASE-T GSA | EC8404008-E6GS | \$8,301.00 | 48% | <i>\$4,348.89</i> |
| VSP 8400 2 port 100G IO Module | EC8404009-E6 | \$10,959.00 | 48% | <i>\$5,741.42</i> |
| 8402CQ ES2M 2 PORT 100G QSFP28 - GSA. TRANSCEIVERS NOT INCL. | EC8404009-E6GS | \$10,568.00 | 48% | <i>\$5,536.58</i> |
| VSP 8400 ETHERNET SWITCH MODULE FILLER PANEL | EC8411002-E6 | \$38.00 | 48% | <i>\$19.91</i> |
| Service Panel for AP560i/AP560h | EIO-03-SP | \$105.00 | 48% | <i>\$55.01</i> |
| Underseat Mounting Solution for AP5050U or AP560i w/ Pass-Through | EIO-04 | \$669.00 | 48% | <i>\$350.49</i> |
| EIO-GASKET Silicone Rubber Kit | EIO-GASKET | \$96.00 | 48% | <i>\$50.29</i> |
| Extreme SLX 9640-24S Router. Supports 24x10GE/1GE + 4x100GE/40GE. (24S+4C sku no Power supplies or Fans) | EN-SLX-9640-24S | \$86,652.00 | 48% | <i>\$45,396.98</i> |
| Extreme SLX 9640-24S Router. Supports 24x10GE/1GE + 12x100GE/40GE. (All ports 24S+12C sku with no Power supplies or Fans) | EN-SLX-9640-24S-12C | \$139,267.00 | 48% | <i>\$72,961.98</i> |
| Extreme SLX 9640-24S Router AC with Front to Back airflow. Supports 24x10GE/1GE + 12x100GE/40GE.(1 Power supply 6 Fans) | EN-SLX-9640-24S-12C-AC-F | \$147,005.00 | 48% | <i>\$77,015.92</i> |
| Extreme SLX 9640-24S Router AC with Front to Back airflow. Supports 24x10GE/1GE + 4x100GE/40GE.(1 Power supply 6 Fans) | EN-SLX-9640-24S-AC-F | \$92,843.00 | 48% | <i>\$48,640.45</i> |
| Extreme SLX 9640 Ports on Demand License for 4 ports of 100GE/40GE Uplinks | EN-SLX-9640-4C-POD-P | \$20,000.00 | 48% | <i>\$10,478.00</i> |
| Extreme SLX 9640 Advanced Feature License | EN-SLX-9640-ADV-LIC-P | \$9,000.00 | 48% | <i>\$4,715.10</i> |

| | | | | |
|---|---------------------|-------------|-----|------------|
| SERVICE REINSTATEMENT FEE | ES-REINSTATE | \$ - | 6% | \$0.00 |
| 2 meters cat5E UTP straight Ethernet cable | ETH-05-02 | \$11.00 | 48% | \$5.76 |
| ExtremeXOS Audio Video Bridging Feature Pack for X435 Series | EXOS-AVB-FP-X435 | \$495.00 | 48% | \$259.33 |
| ExtremeXOS Audio Video Bridging Feature Pack for Summit X465 series switches | EXOS-AVB-FP-X465 | \$1,095.00 | 48% | \$573.67 |
| Core Feature Pack for ExtremeSwitching X465 | EXOS-CORE-FP-X465 | \$1,995.00 | 48% | \$1,045.18 |
| X695 Core Feature License for GuestVM BGP-EVPN etc | EXOS-CORE-FP-X695 | \$5,995.00 | 48% | \$3,140.78 |
| MACsec Feature Pack for ExtremeSwitching X465 | EXOS-MACSEC-FP-X465 | \$1,595.00 | 48% | \$835.62 |
| MACsec Feature Pack for X695 series switches. Enables MACsec when used with LRM/ MACsec Adapter (10965) | EXOS-MACSEC-FP-X695 | \$1,595.00 | 48% | \$835.62 |
| MPLS Feature Pack for ExtremeSwitching X465 | EXOS-MPLS-FP-X465 | \$1,995.00 | 48% | \$1,045.18 |
| MPLS Feature Pack for ExtremeSwitching X590 | EXOS-MPLS-FP-X590 | \$2,995.00 | 48% | \$1,569.08 |
| Tunnel Concentrator for Cloud Wireless Applications | EXTR-IQ-TC | \$1,495.00 | 48% | \$783.23 |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) | FCVPN100-EW-1YR | \$ 600.00 | 6% | \$568.23 |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) | FCVPN100-EW-3YR | \$ 1,440.00 | 6% | \$1,363.75 |

| | | | | |
|---|------------------|-------------|----|-------------------|
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) | FCVPN100-EW-5YR | \$ 2,160.00 | 6% | <i>\$2,045.63</i> |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes ExtremeWorks Premier Support (24x7x365 TAC and eSupport) | FCVPN100-EWP-1YR | \$ 780.00 | 6% | <i>\$738.70</i> |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes ExtremeWorks Premier Support (24x7x365 TAC and eSupport) | FCVPN100-EWP-3YR | \$ 1,872.00 | 6% | <i>\$1,772.88</i> |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes ExtremeWorks Premier Support (24x7x365 TAC and eSupport) | FCVPN100-EWP-5YR | \$ 2,808.00 | 6% | <i>\$2,659.32</i> |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes PartnerWorks Plus Support (24x7x365 TAC and eSupport) | FCVPN100-PW-1YR | \$ 600.00 | 6% | <i>\$568.23</i> |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes PartnerWorks Plus Support (24x7x365 TAC and eSupport) | FCVPN100-PW-3YR | \$ 1,440.00 | 6% | <i>\$1,363.75</i> |
| Fabric Connect VPN App at 100Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes PartnerWorks Plus Support (24x7x365 TAC and eSupport) | FCVPN100-PW-5YR | \$ 2,160.00 | 6% | <i>\$2,045.63</i> |

| | | | | |
|---|------------------|-------------|----|-------------------|
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) | FCVPN500-EW-1YR | \$ 800.00 | 6% | <i>\$757.64</i> |
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) | FCVPN500-EW-3YR | \$ 1,920.00 | 6% | <i>\$1,818.34</i> |
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) | FCVPN500-EW-5YR | \$ 2,880.00 | 6% | <i>\$2,727.50</i> |
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes ExtremeWorks Premier Support (24x7x365 TAC and eSupport) | FCVPN500-EWP-1YR | \$ 1,040.00 | 6% | <i>\$984.93</i> |
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes ExtremeWorks Premier Support (24x7x365 TAC and eSupport) | FCVPN500-EWP-3YR | \$ 2,496.00 | 6% | <i>\$2,363.84</i> |
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes ExtremeWorks Premier Support (24x7x365 TAC and eSupport) | FCVPN500-EWP-5YR | \$ 3,744.00 | 6% | <i>\$3,545.76</i> |
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes PartnerWorks Plus Support (24x7x365 TAC and eSupport) | FCVPN500-PW-1YR | \$ 800.00 | 6% | <i>\$757.64</i> |

| | | | | |
|--|-----------------|-------------|----|-------------------|
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes PartnerWorks Plus Support (24x7x365 TAC and eSupport) | FCVPN500-PW-3YR | \$ 1,920.00 | 6% | <i>\$1,818.34</i> |
| Fabric Connect VPN App at 500Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes PartnerWorks Plus Support (24x7x365 TAC and eSupport) | FCVPN500-PW-5YR | \$ 2,880.00 | 6% | <i>\$2,727.50</i> |
| Fabric Services Routing App at 100Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) (US K-12) | FSR100-EW-1YR | \$ 600.00 | 6% | <i>\$568.23</i> |
| Fabric Services Routing App at 100Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) (US K-12) | FSR100-EW-3YR | \$ 1,440.00 | 6% | <i>\$1,363.75</i> |
| Fabric Services Routing App at 100Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) (US K-12) | FSR100-EW-5YR | \$ 2,160.00 | 6% | <i>\$2,045.63</i> |
| Fabric Services Routing App at 500Mbps Bandwidth Tier, 1YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) (US K-12) | FSR500-EW-1YR | \$ 800.00 | 6% | <i>\$757.64</i> |
| Fabric Services Routing App at 500Mbps Bandwidth Tier, 3YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) (US K-12) | FSR500-EW-3YR | \$ 1,920.00 | 6% | <i>\$1,818.34</i> |

| | | | | |
|--|---------------|--------------|-----|-------------|
| Fabric Services Routing App at 500Mbps Bandwidth Tier, 5YR Right-to-Use (RTU) term license - includes ExtremeWorks Support (24x7x365 TAC and eSupport) (US K-12) | FSR500-EW-5YR | \$ 2,880.00 | 6% | \$2,727.50 |
| KM 1000BASE-LX MM | I-MGBIC-LC03 | \$1,278.00 | 48% | \$669.54 |
| Ipanema SD-WAN Edge Subscription for 1 Site - Large - up to 500Mbps | ISD-EDG-L | \$ 4,925.00 | 6% | \$4,664.22 |
| Ipanema SD-WAN Edge High Availability Subscription for 1 Site - Large - up to 500Mbps | ISD-EDG-L-HA | \$ 1,231.00 | 6% | \$1,165.82 |
| Ipanema SD-WAN Edge Subscription for 1 Site - Medium - up to 250Mbps | ISD-EDG-M | \$ 2,462.00 | 6% | \$2,331.64 |
| Ipanema SD-WAN Edge High Availability Subscription for 1 Site - Medium - up to 250Mbps | ISD-EDG-M-HA | \$ 616.00 | 6% | \$583.38 |
| Ipanema SD-WAN Edge Subscription for 1 Site - Small up to 100Mbps | ISD-EDG-S | \$ 1,642.00 | 6% | \$1,555.06 |
| Ipanema SD-WAN Edge High Availability Subscription for 1 Site - Small up to 100Mbps | ISD-EDG-S-HA | \$ 410.00 | 6% | \$388.29 |
| Ipanema SD-WAN Edge Subscription for 1 Site - X Large - up to 2000Mbps | ISD-EDG-XL | \$ 9,850.00 | 6% | \$9,328.44 |
| Ipanema SD-WAN Edge High Availability Subscription for 1 Site - X Large - up to 2000Mbps | ISD-EDG-XL-HA | \$ 2,462.00 | 6% | \$2,331.64 |
| Ipanema SD-WAN Edge Subscription for 1 Site - X Small up to 50Mbps | ISD-EDG-XS | \$ 1,231.00 | 6% | \$1,165.82 |
| Ipanema SD-WAN Edge High Availability Subscription for 1 Site - X Small up to 50Mbps | ISD-EDG-XS-HA | \$ 308.00 | 6% | \$291.69 |
| Ipanema SD-WAN Edge Subscription for 1 Site - XX Large - up to 4000Mbps | ISD-EDG-XXL | \$ 17,237.00 | 6% | \$16,324.30 |

| | | | | |
|---|----------------|---------------|----|--------------|
| Ipanema SD-WAN Edge High Availability Subscription for 1 Site - XX Large - up to 4000Mbps | ISD-EDG-XXL-HA | \$ 4,309.00 | 6% | \$4,080.84 |
| Ipanema SD-WAN Enhanced Reporting L - up to 500 sites | ISD-ENHR-L | \$ 27,360.00 | 6% | \$25,911.29 |
| Ipanema SD-WAN Enhanced Reporting M - up to 200 sites | ISD-ENHR-M | \$ 13,680.00 | 6% | \$12,955.64 |
| Ipanema SD-WAN Enhanced Reporting S - up to 50 sites | ISD-ENHR-S | \$ 6,840.00 | 6% | \$6,477.82 |
| Ipanema SD-WAN Enhanced Reporting XL - unlimited sites | ISD-ENHR-XL | \$ 34,200.00 | 6% | \$32,389.11 |
| Ipanema SD-WAN Foundation Subscription for 1 Site - Large - up to 500Mbps | ISD-FND-L | \$ 3,557.00 | 6% | \$3,368.66 |
| Ipanema SD-WAN Foundation Subscription for 1 Site - Medium - up to 250Mbps | ISD-FND-M | \$ 1,915.00 | 6% | \$1,813.60 |
| Ipanema SD-WAN Foundation Subscription for 1 Site - Small - up to 100Mbps | ISD-FND-S | \$ 1,094.00 | 6% | \$1,036.07 |
| Ipanema SD-WAN Foundation Subscription for 1 Site - X Large - up to 2000Mbps | ISD-FND-XL | \$ 7,661.00 | 6% | \$7,255.35 |
| Ipanema SD-WAN Foundation Subscription for 1 Site - XX Large - up to 4000Mbps | ISD-FND-XXL | \$ 9,850.00 | 6% | \$9,328.44 |
| Ipanema SD-WAN Dedicated Instance Hosting Fee - L | ISD-HOST-L | \$ 273,600.00 | 6% | \$259,112.88 |
| Ipanema SD-WAN Dedicated Instance Hosting Fee - M | ISD-HOST-M | \$ 342,000.00 | 6% | \$323,891.10 |
| Ipanema SD-WAN Dedicated Instance Hosting Fee - S | ISD-HOST-S | \$ 376,200.00 | 6% | \$356,280.21 |
| Ipanema SD-WAN Dedicated Instance Hosting Fee - XL | ISD-HOST-XL | \$ 171,000.00 | 6% | \$161,945.55 |
| Ipanema SD-WAN Dedicated Instance Hosting Fee - XXL | ISD-HOST-XXL | \$ 54,720.00 | 6% | \$51,822.58 |
| Ipanema SD-WAN Remote Visibility & Control Subscription - Large - up to 100 destinations | ISD-RVC-L | \$ 64,980.00 | 6% | \$61,539.31 |
| Ipanema SD-WAN Remote Visibility & Control Subscription - Medium - up to 20 destinations | ISD-RVC-M | \$ 13,680.00 | 6% | \$12,955.64 |

| | | | | |
|--|-------------|---------------|-----|--------------|
| Ipanema SD-WAN Remote Visibility & Control Subscription - Small - up to 5 destinations | ISD-RVC-S | \$ 4,104.00 | 6% | \$3,886.69 |
| Ipanema SD-WAN Remote Visibility & Control Subscription - X Large - up to 500 destinations | ISD-RVC-XL | \$ 307,800.00 | 6% | \$291,501.99 |
| Ipanema SD-WAN EdgeSentry Subscription - Large - 250 Users | ISD-SENT-L | \$ 68,400.00 | 6% | \$64,778.22 |
| Ipanema SD-WAN EdgeSentry Subscription - Medium - 50 Users | ISD-SENT-M | \$ 14,364.00 | 6% | \$13,603.43 |
| Ipanema SD-WAN EdgeSentry Subscription - Small - 10 Users - (requires min 50 Users per Domain) | ISD-SENT-S | \$ 3,010.00 | 6% | \$2,850.62 |
| Ipanema SD-WAN EdgeSentry Subscription - X Large - 1000 Users | ISD-SENT-XL | \$ 259,920.00 | 6% | \$246,157.24 |
| WAN Optimization Subscription for 1 Site - Large - up to 150Mbps | ISD-WO-L | \$ 2,394.00 | 6% | \$2,267.24 |
| WAN Optimization Subscription for 1 Site - Medium - up to 80Mbps | ISD-WO-M | \$ 1,368.00 | 6% | \$1,295.56 |
| WAN Optimization Subscription for 1 Site - Small - up to 40Mbps | ISD-WO-S | \$ 684.00 | 6% | \$647.78 |
| WAN Optimization Subscription for 1 Site - X Large - up to 500Mbps | ISD-WO-XL | \$ 5,130.00 | 6% | \$4,858.37 |
| 28-Port ISW Industrial Ethernet Switch 24 10/100/1000BASE-T 90W PoE ports plus 4 10GBASE-X SFP+ ports 720W PoE Operating Temp -40C - +75C dual DC power inputs fanless 1RU | ISW-24W-4X | \$11,995.00 | 48% | \$6,284.18 |

| | | | | |
|---|-------------------|------------|-----|------------|
| 12-Port ISW Industrial Ethernet Switch 4 10/100/1000BASE-T 90W PoE ports 4 combo ports supporting either 4 10/100/1000BASE-T 90W PoE OR 4 1000BASE-X (SFP) plus 4 10GBASE-X SFP+ ports Oper Temp -40C - +75C dual DC power inputs fanless | ISW-4W-4WS-4X | \$6,495.00 | 48% | \$3,402.73 |
| ISW AC-DC Power Supply 960W Output DIN Rail -30 - 70C | ISW-AC-DC-PS-960W | \$2,495.00 | 48% | \$1,307.13 |
| UNIVERSAL MOUNTING KIT FOR EWLAN APS | KT-135628-01 | \$49.00 | 48% | \$25.67 |
| OUTDOOR MOUNTING HARDWARE KIT FOR OUTDOOR ACCESS POINTS-STAINLESS STEEL FOR HARSH ENVIRONMENTS | KT-147407-02 | \$326.00 | 48% | \$170.79 |
| OUTDOOR AP 12 IN EXT ARM FOR MNTG KIT | KT-150173-01 | \$197.00 | 48% | \$103.21 |
| OUTDOOR RJ45 CONNECTOR PLUG KIT | KT-153676-01 | \$40.00 | 48% | \$20.96 |
| KIT AP7161 VEHICLE MOUNT | KT-158767-01 | \$326.00 | 48% | \$170.79 |
| MBO-ART03 2-Axis Rotational Variable Extension Mtg Brkt for Outdoor Access Points | MBO-ART03 | \$300.00 | 48% | \$157.17 |
| 1U rail kit mount (19 to 26 inch) for ipe2000ax/4000ax Series | MEC-04-1U | \$117.00 | 48% | \$61.30 |
| 1000BASE-T RJ45 MINI GBIC | MGBIC-02 | \$363.00 | 48% | \$190.18 |
| 1000BASE-BX40-D SFP | MGBIC-BX40-D | \$4,351.00 | 48% | \$2,279.49 |
| 1000BASE-BX40-U BIDIRECTIONAL SFP | MGBIC-BX40-U | \$4,351.00 | 48% | \$2,279.49 |
| MINI GBIC 1000BASE-FX W/ 1 LC MM PT -2KM | MGBIC-LC03 | \$1,050.00 | 48% | \$550.10 |
| 10 ft Low-Loss coaxial cable jumper N Male to N Male | ML-1499-10JK-01R | \$296.00 | 48% | \$155.07 |
| 25 ft Low-Loss coaxial cable jumper N Male to N Male with 2 connector seal kits | ML-1499-25JK-01R | \$290.00 | 48% | \$151.93 |

| | | | | |
|--|--------------------|----------|-----|----------|
| Dipole 3.2dBi (2.4 GHz) and 4.9dBi (5 GHz) dual band with RP-SMA connector color black | ML-2452-APA2-01 | \$37.00 | 48% | \$19.38 |
| Dipole 3.2dBi (2.4 GHz) and 4.9dBi (5 GHz) dual band with RP-SMA connector color white | ML-2452-APA2-02 | \$37.00 | 48% | \$19.38 |
| ANTDIPOLEGN2DBI-2.4GHZ1DBI-5GHZBLK | ML-2452-APAG2A1-01 | \$12.00 | 48% | \$6.29 |
| Antenna 2G and 5G 3dB Omni for indoor White Color | ML-2452-APAG2A1-02 | \$12.00 | 48% | \$6.29 |
| Dipole 3.9dBi (2.4 GHz) and 5.7dBi (5 GHz) dual band with RP-SMA connector outdoor rated color white | ML-2452-HPA5-036 | \$373.00 | 48% | \$195.41 |
| ANTDUAL BAND 6 DBI ANTENNA | ML-2452-HPA6-01 | \$60.00 | 48% | \$31.43 |
| ANT 6 DUAL ELEMENT OMN ANTENNA | ML-2452-HPA6M6-072 | \$884.00 | 48% | \$463.13 |
| ANT 6 PORT OMNI ANTENNA | ML-2452-HPA6X6-036 | \$588.00 | 48% | \$308.05 |
| Dipole 4dBi (2.4 GHz) and 7.3dBi (5 GHz) dual band with standard N-type connector outdoor rated color white | ML-2452-HPAG4A6-01 | \$187.00 | 48% | \$97.97 |
| Dipole 4.7dBi (2.4 GHz) and 8dBi (5 GHz) dual band with N type connector | ML-2452-HPAG5A8-01 | \$374.00 | 48% | \$195.94 |
| 2.4/5 GHz Lightning Arrestor (N Female to N Female) with N Male to RP-SMA Male adapter | ML-2452-LAK1-01R | \$329.00 | 48% | \$172.36 |
| DUAL BAND LIGHTNING ARRESTOR | ML-2452-LAK1-02R | \$244.00 | 48% | \$127.83 |
| Panel 120 deg sector 4.5dBi/ 5dBi dual band outdoor 4 lead with standard N-type connector | ML-2452-PNA5-01R | \$392.00 | 48% | \$205.37 |
| Antenna 2.4/5 GHz Outdoor Panel 7 dBi Beam Width E-Plane 66 degrees H-Plane 68 degrees Connector Type N-Male | ML-2452-PNA7-01R | \$518.00 | 48% | \$271.38 |
| ANT3 PORT DUAL BAND PANEL ANTENNA WITH 36 INCH CABLE AND N-MALE CONNECTOR | ML-2452-PNL6M3-N36 | \$370.00 | 48% | \$193.84 |

| | | | | |
|---|--------------------|----------|-----|----------|
| ANT MIMO DUAL BAND SECTOR | ML-2452-PNL9M3-036 | \$708.00 | 48% | \$370.92 |
| ANT3 PORT DUAL BAND PANEL ANTENNA | ML-2452-PNL9M3-N36 | \$488.00 | 48% | \$255.66 |
| Patch 4dBi (2.4 GHz) and 5dBi (5 GHz) dual band with 2 RP-SMA connectors | ML-2452-PTA2M2-036 | \$231.00 | 48% | \$121.02 |
| AP-7131 3 PORT MIMO ANTENNA 36IN PIGTAIL | ML-2452-PTA3M3-036 | \$294.00 | 48% | \$154.03 |
| ANTENNA PATCH4 DUAL ELEMENT INDOOR | ML-2452-PTA4M4-036 | \$314.00 | 48% | \$164.50 |
| ANT 6 PORT PATCH ANTENNA | ML-2452-PTA6M6-036 | \$589.00 | 48% | \$308.58 |
| ANT 6 PORT PATCH ANTENNA | ML-2452-PTA6X6-036 | \$354.00 | 48% | \$185.46 |
| Polarized Panel Azimuth 100 Elevation Beamwidth 80 deg 6.92dBi/ 7.3dBi dual band indoor with quad feed 32 leads and standard RP-SMA plug connectors | ML-2452-SEC6M4-036 | \$712.00 | 48% | \$373.02 |
| DUAL BAND SECTOR WITH 30 INCH CABLE AND N CONNECTORS | ML-2452-SEC6M4-N30 | \$684.00 | 48% | \$358.35 |
| DUAL POLARIZED DUAL BAND WIDE BEAM DIRECTIONAL ANTENNA WITH 36 INCH CABLE AND N-MALE CONNECTOR | ML-2452-SEC6M4-N36 | \$683.00 | 48% | \$357.82 |
| ANT 3 DUAL BAND ELEMENTS VMM ANTENNA | ML-2452-VMM3M3-036 | \$393.00 | 48% | \$205.89 |
| ANT 2.4GHZ 3.3DBI DIPOLE ANTENNA | ML-2499-HPA3-02R | \$141.00 | 48% | \$73.87 |
| Outdoor Rated Type Dipole Gain 4dBi 2.4GHz Connector N-Male | ML-2499-HPA4-01 | \$214.00 | 48% | \$112.11 |
| Environment Outdoor Rated Type Dipole Gain 8 dBi 2.4GHz Connector N-Male | ML-2499-HPA8-01 | \$313.00 | 48% | \$163.98 |

| | | | | |
|---|-------------------|--------------|-----|-------------|
| Antenna 5 GHz Outdoor Type Dipole Array (Pipe) Omnidirectional 6 dBi Beam Width E-Plane 16 degrees H-Plane 360 degrees N-Male connector type | ML-5299-FHPA6-01R | \$313.00 | 48% | \$163.98 |
| Environment Outdoor Rated Type Dipole Gain 10 dBi 5.0GHz4.9GHz Connector N-Male | ML-5299-HPA10-01 | \$393.00 | 48% | \$205.89 |
| Outdoor Rated Type Dipole Gain 5dBi 5.0GHz Connector N-Male | ML-5299-HPA5-01 | \$214.00 | 48% | \$112.11 |
| NIaaS Per Port-Local/State/Fed Gov Only | NIAAS-PER-PORT | \$ 850.00 | 6% | \$804.99 |
| NX-5500 SERVICES PLATFORM | NX-5500-100R0-WR | \$7,848.00 | 48% | \$4,111.57 |
| LICENSE128X AP LICENSE PACK FOR NX-5500 | NX-5500-ADP-128 | \$15,206.00 | 48% | \$7,966.42 |
| LICENSE16X AP LICENSE PACK FOR NX-5500 | NX-5500-ADP-16 | \$1,901.00 | 48% | \$995.93 |
| LICENSE64X AP LICENSE PACK FOR NX-5500 | NX-5500-ADP-64 | \$7,603.00 | 48% | \$3,983.21 |
| NX 7500 - 2-PORT 10G SFP+ NMC MODULE | NX-7500-10G-NMC | \$5,498.00 | 48% | \$2,880.40 |
| NX 7500 - 4-PORT 1G SFP NMC MODULE | NX-7500-1G-NMC | \$4,713.00 | 48% | \$2,469.14 |
| NX 7500 AC POWER SUPPLY | NX-7500-AC-PSU | \$1,180.00 | 48% | \$618.20 |
| LICENSENX 7500 - 1024 PACK ADAPTIVE AP | NX-7500-ADP-1024 | \$119,994.00 | 48% | \$62,864.86 |
| LICENSENX 7500 - 256 PACK ADAPTIVE AP | NX-7500-ADP-256 | \$30,414.00 | 48% | \$15,933.89 |
| LICENSENX 7500 - 64 PACK ADAPTIVE AP | NX-7500-ADP-64 | \$7,602.00 | 48% | \$3,982.69 |
| LICENSENX 7500 - 8 PACK ADAPTIVE AP | NX-7500-ADP-8 | \$954.00 | 48% | \$499.80 |
| LICENSENX 7500 ADVANCED SECURITY | NX-7500-ADSEC-LIC | \$6,000.00 | 48% | \$3,143.40 |
| NX 7530 500GB SPARE HARD DRIVE | NX-7500-HD-500GB | \$1,728.00 | 48% | \$905.30 |
| NX 7500 MOUNTING KIT - SLIDING RAILS | NX-7500-RAIL | \$473.00 | 48% | \$247.80 |

| | | | | |
|--|--------------------|---------------|-----|---------------------|
| NX 7500 1GBPS LONG RANGE SFP XCVR | NX-7500-SFP-LX | \$1,180.00 | 48% | <i>\$618.20</i> |
| NX 7500 1GBPS SHORT RANGE SFP XCVR | NX-7500-SFP-SX | \$628.00 | 48% | <i>\$329.01</i> |
| NX 7500 10GBPS LONG RANGE SFP+ XCVR | NX-7500-SFPPL-LX | \$3,262.00 | 48% | <i>\$1,708.96</i> |
| NX 7500 10GBPS SHORT RANGE SFP+ XCVR | NX-7500-SFPPL-SX | \$1,631.00 | 48% | <i>\$854.48</i> |
| NX 7510 INTEGRATED SVC PLATFORM | NX-7510-100R0-WR | \$23,560.00 | 48% | <i>\$12,343.08</i> |
| NX 7520 INTEGRATED SVC PLATFORM | NX-7520-100R0-WR | \$31,414.00 | 48% | <i>\$16,457.79</i> |
| NX 7530 INTEGRATED SVC PLATFORM | NX-7530-100R0-WR | \$32,985.00 | 48% | <i>\$17,280.84</i> |
| LICENSE1024 ADP AP FOR NX 9000 | NX-9000-1024LIC-WR | \$119,994.00 | 48% | <i>\$62,864.86</i> |
| LICENSE128 ADP AP FOR NX 9000 | NX-9000-128LIC-WR | \$15,234.00 | 48% | <i>\$7,981.09</i> |
| LICENSE8 PACK FOR NX 95XX | NX-9000-8LIC-WR | \$954.00 | 48% | <i>\$499.80</i> |
| LICENSEADVANCED SECURITY FOR NX 9000 | NX-9000-ADVSEC-LIC | \$1,799.00 | 48% | <i>\$942.50</i> |
| SINGLE PORT 802.3AF MIDSPAN DEVICE | PD-3501G-ENT | \$100.00 | 48% | <i>\$52.39</i> |
| OUTDOOR 802.3AT POE SINGLE PORT MIDSPAN | PD-9001GO-ENT | \$613.00 | 48% | <i>\$321.15</i> |
| SINGLE PORT 802.3AT COMPLIANT MIDSPAN | PD-9001GR-ENT | \$138.00 | 48% | <i>\$72.30</i> |
| SINGLE PORT 802.3AT PLUS OUTDOOR MIDSPAN | PD-9501GO-ENT | \$980.00 | 48% | <i>\$513.42</i> |
| MOUNTING BRACKET FOR OUTDOOR MIDSPANS | PD-MBKOUT | \$140.00 | 48% | <i>\$73.35</i> |
| PREMIER PLUS OSE FULL TIME RENEW | PP-ROSE-FT | \$ 320,000.00 | 1% | <i>\$319,176.00</i> |
| Premier Delivery Engineer 25 PCT Time | Prem-DE-25 | \$ 126,000.00 | 6% | <i>\$119,328.30</i> |
| Premier Delivery Engineer 50 PCT Time | Prem-DE-50 | \$ 230,400.00 | 6% | <i>\$218,200.32</i> |
| Premier Delivery Engineer 75 PCT Time | Prem-DE-75 | \$ 307,200.00 | 6% | <i>\$290,933.76</i> |
| Premier Delivery Engineer Full Time | Prem-DE-FT | \$ 384,000.00 | 6% | <i>\$363,667.20</i> |

| | | | | |
|--|-----------------------|---------------|----|--------------|
| 3-day on-site consulting | PREM-ONSITECONSULT-3 | \$ 9,450.00 | 6% | \$8,949.62 |
| Premier Resident Engineer Fed Full Time | Prem-RE-FED-FT | \$ 540,000.00 | 6% | \$511,407.00 |
| Premier Resident Engineer Full Time | Prem-RE-FT | \$ 384,000.00 | 6% | \$363,667.20 |
| 1-day Remote Consulting | PREM-REMOTECONSULT-1 | \$ 2,160.00 | 6% | \$2,045.63 |
| ERATE PROF SERVICE FOR K12 | PS-ERATE-ESU | \$ 3,150.00 | 1% | \$3,141.89 |
| EXTREME SERVICE UNITS SINGLE | PS-ESU-1 | \$ 3,150.00 | 1% | \$3,141.89 |
| EXTREME SERVICE UNITS FEDERAL SINGLE | PS-ESU-1-FEDERAL | \$ 4,200.00 | 1% | \$4,189.19 |
| Professional Services Project Management | PS-ESU-PM | \$ 3,150.00 | 1% | \$3,141.89 |
| Remote (ESU) Extreme Service Unit | PS-ESU-REMOTE | \$ 2,160.00 | 1% | \$2,154.44 |
| HOURLY RATE FOR KY PROFESSIONAL SERVICES | PS-KY2004-001 | \$ 156.00 | 1% | \$155.60 |
| Hr Rate - Onsite PS - NY ONLY | PS-NY2017-001 | \$ 375.00 | 1% | \$374.03 |
| Hr Rate - Remote PS - NY ONLY | PS-NY2017-002 | \$ 187.50 | 1% | \$187.02 |
| Basic EMC/NAC Setup - NY ONLY | PS-NY2017-EMC | \$ 9,000.00 | 1% | \$8,976.83 |
| Basic EXT WiFi Setup - NY ONLY | PS-NY2017-WIFI | \$ 9,000.00 | 1% | \$8,976.83 |
| OnSite Engineer Federal | PS-OSE-FEDERAL | \$ 540,000.00 | 1% | \$538,609.50 |
| PS for WiNG to XIQ Migration | PS-WING-MIGRATION-XIQ | \$ 1,800.00 | 6% | \$1,704.69 |
| XMC to XIQ-SE Large Network Upgrade | PS-XIQ-SE-LG | \$ 6,480.00 | 1% | \$6,463.31 |
| XMC to XIQ-SE Medium Network Upgrade | PS-XIQ-SE-MD | \$ 4,320.00 | 1% | \$4,308.88 |
| XMC to XIQ-SE Small Network Upgrade | PS-XIQ-SE-SM | \$ 2,160.00 | 1% | \$2,154.44 |

| | | | | |
|---|------------------|------------|-----|------------|
| 1300W Redundant Power Supply for appliances E3120/E2122/4120C | PSI-1300W-APL | \$825.00 | 48% | \$432.22 |
| 10GB QSFP+-SFP+ ADAPTOR | QSFP-SFPP-ADPT | \$290.00 | 48% | \$151.93 |
| 150W external redundant power supply extended temperature | RPS-150W-XT | \$1,095.00 | 48% | \$573.67 |
| 550W (370W PoE) external redundant power supply | RPS-550W | \$1,695.00 | 48% | \$888.01 |
| 950W (740W PoE) external redundant power supply | RPS-950W | \$2,095.00 | 48% | \$1,097.57 |
| 1 meter RPS cable for use with 550W 950W external RPS used with 4220 switches | RPS-CBL-1M | \$245.00 | 48% | \$128.36 |
| External RPS Cable 1 meter 14 conductor 2x7 connector 12V/150W applications | RPS-CBL-1M-2x7 | \$195.00 | 48% | \$102.16 |
| EW SECUPLIFT 10200 | SECUPLIFT-10200 | \$ 371.00 | 10% | \$336.40 |
| EW SECUPLIFT 10320 | SECUPLIFT-10320 | \$ 177.00 | 10% | \$160.49 |
| EW SECUPLIFT 10330 | SECUPLIFT-10330 | \$ 588.00 | 10% | \$533.17 |
| EW SECUPLIFT 10331 | SECUPLIFT-10331 | \$ 353.00 | 10% | \$320.08 |
| EW SECUPLIFT 10335 | SECUPLIFT-10335 | \$ 353.00 | 10% | \$320.08 |
| EW SECUPLIFT 10403 | SECUPLIFT-10403 | \$ 371.00 | 10% | \$336.40 |
| EW SECUPLIFT 10404 | SECUPLIFT-10404 | \$ 407.00 | 10% | \$369.05 |
| EW SECUPLIFT 10441 | SECUPLIFT-10441 | \$ 205.00 | 10% | \$185.88 |
| EW SECUPLIFT 10442 | SECUPLIFT-10442 | \$ 205.00 | 10% | \$185.88 |
| SECUPLIFT 16126 | SECUPLIFT-16126 | \$ 97.00 | 10% | \$87.95 |
| EW SECUPLIFT 16172 | SECUPLIFT-16172 | \$ 73.00 | 10% | \$66.19 |
| EW SECUPLIFT 16172T | SECUPLIFT-16172T | \$ 108.00 | 10% | \$97.93 |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT 16173 | SECUPLIFT-16173 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW SECUPLIFT 16173T | SECUPLIFT-16173T | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW SECUPLIFT 16174 | SECUPLIFT-16174 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT 16175 | SECUPLIFT-16175 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW SECUPLIFT 16176 | SECUPLIFT-16176 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW SECUPLIFT 16177 | SECUPLIFT-16177 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW SECUPLIFT 16177T | SECUPLIFT-16177T | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW SECUPLIFT 16178 | SECUPLIFT-16178 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW SECUPLIFT 16179 | SECUPLIFT-16179 | \$ 108.00 | 10% | <i>\$97.93</i> |
| EW SECUPLIFT 16179T | SECUPLIFT-16179T | \$ 215.00 | 10% | <i>\$194.95</i> |
| EW SECUPLIFT 16530 | SECUPLIFT-16530 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16531 | SECUPLIFT-16531 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16531T | SECUPLIFT-16531T | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16532 | SECUPLIFT-16532 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16532T | SECUPLIFT-16532T | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16533 | SECUPLIFT-16533 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16533T | SECUPLIFT-16533T | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16534 | SECUPLIFT-16534 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16535 | SECUPLIFT-16535 | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW SECUPLIFT 16535A | SECUPLIFT-16535A | \$ 106.00 | 10% | <i>\$96.12</i> |
| EW SECUPLIFT 16535T | SECUPLIFT-16535T | \$ 106.00 | 10% | <i>\$96.12</i> |

| | | | | |
|---------------------|------------------|----------|-----|----------------|
| EW SECUPLIFT 16536 | SECUPLIFT-16536 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16537 | SECUPLIFT-16537 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16538 | SECUPLIFT-16538 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16538T | SECUPLIFT-16538T | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW SECUPLIFT 16539 | SECUPLIFT-16539 | \$ 96.00 | 10% | <i>\$87.05</i> |
| EW SECUPLIFT 16540 | SECUPLIFT-16540 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16541 | SECUPLIFT-16541 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16560 | SECUPLIFT-16560 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16561 | SECUPLIFT-16561 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16562 | SECUPLIFT-16562 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16563 | SECUPLIFT-16563 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16564 | SECUPLIFT-16564 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16565 | SECUPLIFT-16565 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16566 | SECUPLIFT-16566 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16567 | SECUPLIFT-16567 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16568 | SECUPLIFT-16568 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16569 | SECUPLIFT-16569 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16570 | SECUPLIFT-16570 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16571 | SECUPLIFT-16571 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 16701 | SECUPLIFT-16701 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW SECUPLIFT 16702 | SECUPLIFT-16702 | \$ 99.00 | 10% | <i>\$89.77</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT 16703 | SECUPLIFT-16703 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW SECUPLIFT 16703T | SECUPLIFT-16703T | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW SECUPLIFT 16704 | SECUPLIFT-16704 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW SECUPLIFT 16704T | SECUPLIFT-16704T | \$ 208.00 | 10% | <i>\$188.60</i> |
| EW SECUPLIFT 16705 | SECUPLIFT-16705 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW SECUPLIFT 16705T | SECUPLIFT-16705T | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT 16706 | SECUPLIFT-16706 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW SECUPLIFT 16706T | SECUPLIFT-16706T | \$ 208.00 | 10% | <i>\$188.60</i> |
| EW SECUPLIFT 16710 | SECUPLIFT-16710 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW SECUPLIFT 16710T | SECUPLIFT-16710T | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16711 | SECUPLIFT-16711 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW SECUPLIFT 16711T | SECUPLIFT-16711T | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16712 | SECUPLIFT-16712 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW SECUPLIFT 16712T | SECUPLIFT-16712T | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16713 | SECUPLIFT-16713 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW SECUPLIFT 16713T | SECUPLIFT-16713T | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT 16715 | SECUPLIFT-16715 | \$ 32.00 | 10% | <i>\$29.02</i> |
| EW SECUPLIFT 16715T | SECUPLIFT-16715T | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 16716 | SECUPLIFT-16716 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW SECUPLIFT 16716T | SECUPLIFT-16716T | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW SECUPLIFT 16717 | SECUPLIFT-16717 | \$ 99.00 | 10% | <i>\$89.77</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT 16718 | SECUPLIFT-16718 | \$ 110.00 | 10% | <i>\$99.74</i> |
| EW SECUPLIFT 16718T | SECUPLIFT-16718T | \$ 209.00 | 10% | <i>\$189.51</i> |
| EW SECUPLIFT 16719 | SECUPLIFT-16719 | \$ 99.00 | 10% | <i>\$89.77</i> |
| EW SECUPLIFT 16719T | SECUPLIFT-16719T | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT 16720 | SECUPLIFT-16720 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT 16720T | SECUPLIFT-16720T | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT 16756 | SECUPLIFT-16756 | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW SECUPLIFT 16756T | SECUPLIFT-16756T | \$ 208.00 | 10% | <i>\$188.60</i> |
| EW SECUPLIFT 16757 | SECUPLIFT-16757 | \$ 220.00 | 10% | <i>\$199.49</i> |
| EW SECUPLIFT 16757T | SECUPLIFT-16757T | \$ 208.00 | 10% | <i>\$188.60</i> |
| EW SECUPLIFT 16790 | SECUPLIFT-16790 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT 16791 | SECUPLIFT-16791 | \$ 200.00 | 10% | <i>\$181.35</i> |
| SECUPLIFT SER 16801 | SECUPLIFT-16801 | \$ 35.00 | 10% | <i>\$31.74</i> |
| SECUPLIFT SER 16802 | SECUPLIFT-16802 | \$ 40.00 | 10% | <i>\$36.27</i> |
| SECUPLIFT SER 16803 | SECUPLIFT-16803 | \$ 40.00 | 10% | <i>\$36.27</i> |
| SECUPLIFT SER 16804 | SECUPLIFT-16804 | \$ 40.00 | 10% | <i>\$36.27</i> |
| EW SECUPLIFT 17101 | SECUPLIFT-17101 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17102 | SECUPLIFT-17102 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17103 | SECUPLIFT-17103 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17104 | SECUPLIFT-17104 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17121 | SECUPLIFT-17121 | \$ 200.00 | 10% | <i>\$181.35</i> |

| | | | | |
|---------------------|------------------|-------------|-----|-----------------|
| EW SECUPLIFT 17122 | SECUPLIFT-17122 | \$ 68.00 | 10% | <i>\$61.66</i> |
| SECUPLIFT SER 17200 | SECUPLIFT-17200 | \$ 1,020.00 | 10% | <i>\$924.89</i> |
| EW SECUPLIFT 17201 | SECUPLIFT-17201 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17202 | SECUPLIFT-17202 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17203 | SECUPLIFT-17203 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17204 | SECUPLIFT-17204 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17205 | SECUPLIFT-17205 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17206 | SECUPLIFT-17206 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT 17300 | SECUPLIFT-17300 | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW SECUPLIFT 17310 | SECUPLIFT-17310 | \$ 398.00 | 10% | <i>\$360.89</i> |
| EW SECUPLIFT 17310T | SECUPLIFT-17310T | \$ 376.00 | 10% | <i>\$340.94</i> |
| EW SECUPLIFT 17350 | SECUPLIFT-17350 | \$ 404.00 | 10% | <i>\$366.33</i> |
| EW SECUPLIFT 17360 | SECUPLIFT-17360 | \$ 673.00 | 10% | <i>\$610.24</i> |
| EW SECUPLIFT 17401 | SECUPLIFT-17401 | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW SECUPLIFT 17401G | SECUPLIFT-17401G | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT 17401T | SECUPLIFT-17401T | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT 17402 | SECUPLIFT-17402 | \$ 102.00 | 10% | <i>\$92.49</i> |
| EW SECUPLIFT 17402G | SECUPLIFT-17402G | \$ 193.00 | 10% | <i>\$175.00</i> |
| EW SECUPLIFT 17402T | SECUPLIFT-17402T | \$ 193.00 | 10% | <i>\$175.00</i> |
| EW SECUPLIFT 17403 | SECUPLIFT-17403 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT 17404 | SECUPLIFT-17404 | \$ 67.00 | 10% | <i>\$60.75</i> |

| | | | | |
|------------------------|-----------------|-----------|-----|-----------------|
| EW SECUPLIFT 17405 | SECUPLIFT-17405 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW SECUPLIFT 17701 | SECUPLIFT-17701 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT 17702 | SECUPLIFT-17702 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT 17703 | SECUPLIFT-17703 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT 17704 | SECUPLIFT-17704 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT 17705 | SECUPLIFT-17705 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT 17706 | SECUPLIFT-17706 | \$ 643.00 | 10% | <i>\$583.04</i> |
| EW SECUPLIFT 17800 | SECUPLIFT-17800 | \$ 392.00 | 10% | <i>\$355.45</i> |
| EW SECUPLIFT 17810 | SECUPLIFT-17810 | \$ 392.00 | 10% | <i>\$355.45</i> |
| EW SECUPLIFT 18101 | SECUPLIFT-18101 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 18102 | SECUPLIFT-18102 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 18103 | SECUPLIFT-18103 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT 18104 | SECUPLIFT-18104 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT 18202 | SECUPLIFT-18202 | \$ 60.00 | 10% | <i>\$54.41</i> |
| EW Secure Uplift 30135 | SECUPLIFT-30135 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW Secure Uplift 30136 | SECUPLIFT-30136 | \$ 647.00 | 10% | <i>\$586.67</i> |
| EW SECUPLIFT 30137 | SECUPLIFT-30137 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW SECUPLIFT 30138 | SECUPLIFT-30138 | \$ 647.00 | 10% | <i>\$586.67</i> |
| EW Secure Uplift 30139 | SECUPLIFT-30139 | \$ 908.00 | 10% | <i>\$823.33</i> |
| EW Secure Uplift 31012 | SECUPLIFT-31012 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift 31013 | SECUPLIFT-31013 | \$ 35.00 | 10% | <i>\$31.74</i> |

| | | | | |
|------------------------|-----------------|----------|-----|----------------|
| EW Secure Uplift 31014 | SECUPLIFT-31014 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift 31015 | SECUPLIFT-31015 | \$ 21.00 | 10% | <i>\$19.04</i> |
| EW Secure Uplift 31016 | SECUPLIFT-31016 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Secure Uplift 31017 | SECUPLIFT-31017 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Secure Uplift 31018 | SECUPLIFT-31018 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Secure Uplift 31019 | SECUPLIFT-31019 | \$ 68.00 | 10% | <i>\$61.66</i> |
| EW Secure Uplift 31025 | SECUPLIFT-31025 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift 31026 | SECUPLIFT-31026 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift 31028 | SECUPLIFT-31028 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 31029 | SECUPLIFT-31029 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 31031 | SECUPLIFT-31031 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 31032 | SECUPLIFT-31032 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 31034 | SECUPLIFT-31034 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift 31035 | SECUPLIFT-31035 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift 31050 | SECUPLIFT-31050 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 31051 | SECUPLIFT-31051 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 31055 | SECUPLIFT-31055 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 31056 | SECUPLIFT-31056 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 37101 | SECUPLIFT-37101 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37102 | SECUPLIFT-37102 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37103 | SECUPLIFT-37103 | \$ 13.00 | 10% | <i>\$11.79</i> |

| | | | | |
|----------------------------|------------------------|-----------|-----|-----------------|
| EW Secure Uplift 37111 | SECUPLIFT-37111 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37112 | SECUPLIFT-37112 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37113 | SECUPLIFT-37113 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37114 | SECUPLIFT-37114 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37115 | SECUPLIFT-37115 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37116 | SECUPLIFT-37116 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37117 | SECUPLIFT-37117 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift 37121 | SECUPLIFT-37121 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 37122 | SECUPLIFT-37122 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 37123 | SECUPLIFT-37123 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 37124 | SECUPLIFT-37124 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 37129 | SECUPLIFT-37129 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 37130 | SECUPLIFT-37130 | \$ 19.00 | 10% | <i>\$17.23</i> |
| EW Secure Uplift 39505 | SECUPLIFT-39505 | \$ 12.00 | 10% | <i>\$10.88</i> |
| SECUPLIFT SER 4120-24MW-4Y | SECUPLIFT-4120-24MW-4Y | \$ 175.00 | 10% | <i>\$158.68</i> |
| SECUPLIFT SER 4120-48MW-4Y | SECUPLIFT-4120-48MW-4Y | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 4220-12P-4X | SECUPLIFT-4220-12P-4X | \$ 45.00 | 10% | <i>\$40.80</i> |
| SECUPLIFT SER 4220-12T-4X | SECUPLIFT-4220-12T-4X | \$ 45.00 | 10% | <i>\$40.80</i> |
| SECUPLIFT SER 4220-24P-4X | SECUPLIFT-4220-24P-4X | \$ 50.00 | 10% | <i>\$45.34</i> |
| SECUPLIFT SER 4220-24T-4X | SECUPLIFT-4220-24T-4X | \$ 50.00 | 10% | <i>\$45.34</i> |

| | | | | |
|-----------------------------------|------------------------------|-----------|-----|-----------------|
| SECUPLIFT SER 4220-48P-4X | SECUPLIFT-4220-48P-4X | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 4220-48T-4X | SECUPLIFT-4220-48T-4X | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 4220-4MW-20P-4X | SECUPLIFT-4220-4MW-20P-4X | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 4220-4MW-8P-4X | SECUPLIFT-4220-4MW-8P-4X | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 4220-8MW-40P-4X | SECUPLIFT-4220-8MW-40P-4X | \$ 119.00 | 10% | <i>\$107.90</i> |
| SECUPLIFT SER 4220-8X | SECUPLIFT-4220-8X | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 5320-16P-4XE | SECUPLIFT-5320-16P-4XE | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 5320-16P-4XE-DC | SECUPLIFT-5320-16P-4XE-DC | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 5320-24P-8XE | SECUPLIFT-5320-24P-8XE | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 5320-24T-4X-XT | SECUPLIFT-5320-24T-4X-XT | \$ 84.00 | 6% | <i>\$79.55</i> |
| SECUPLIFT SER 5320-24T-8XE | SECUPLIFT-5320-24T-8XE | \$ 84.00 | 10% | <i>\$76.17</i> |
| SECUPLIFT SER 5320-24T-24S-4XE-XT | SECUPLIFT-5320-24T24S-4XE-XT | \$ 84.00 | 6% | <i>\$79.55</i> |
| SECUPLIFT SER 5320-48P-8XE | SECUPLIFT-5320-48P-8XE | \$ 119.00 | 10% | <i>\$107.90</i> |
| SECUPLIFT SER 5320-48T-8XE | SECUPLIFT-5320-48T-8XE | \$ 90.00 | 10% | <i>\$81.61</i> |
| SECUPLIFT SER 5420F-16MW-32P-4XE | SECUPLIFT-5420F-16MW-32P-4XE | \$ 205.00 | 10% | <i>\$185.88</i> |
| SECUPLIFT SER 5420F-16W-32P-4XE | SECUPLIFT-5420F-16W-32P-4XE | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5420F-24P-4XE | SECUPLIFT-5420F-24P-4XE | \$ 100.00 | 10% | <i>\$90.68</i> |

| | | | | |
|----------------------------------|------------------------------|-----------|-----|-----------------|
| SECUPLIFT SER 5420F-24S-4XE | SECUPLIFT-5420F-24S-4XE | \$ 100.00 | 10% | <i>\$90.68</i> |
| SECUPLIFT SER 5420F-24T-4XE | SECUPLIFT-5420F-24T-4XE | \$ 100.00 | 10% | <i>\$90.68</i> |
| SECUPLIFT SER 5420F-48P-4XE | SECUPLIFT-5420F-48P-4XE | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5420F-48P-4XL | SECUPLIFT-5420F-48P-4XL | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5420F-48T-4XE | SECUPLIFT-5420F-48T-4XE | \$ 96.00 | 10% | <i>\$87.05</i> |
| SECUPLIFT SER 5420F-8W-16P-4XE | SECUPLIFT-5420F-8W-16P-4XE | \$ 96.00 | 10% | <i>\$87.05</i> |
| SECUPLIFT SER 5420M-16MW-32P-4YE | SECUPLIFT-5420M-16MW-32P-4YE | \$ 205.00 | 10% | <i>\$185.88</i> |
| SECUPLIFT SER 5420M-24T-4YE | SECUPLIFT-5420M-24T-4YE | \$ 96.00 | 10% | <i>\$87.05</i> |
| SECUPLIFT SER 5420M-24W-4YE | SECUPLIFT-5420M-24W-4YE | \$ 94.00 | 10% | <i>\$85.23</i> |
| SECUPLIFT SER 5420M-48T-4YE | SECUPLIFT-5420M-48T-4YE | \$ 96.00 | 10% | <i>\$87.05</i> |
| SECUPLIFT SER 5420M-48W-4YE | SECUPLIFT-5420M-48W-4YE | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5520-12MW-36W | SECUPLIFT-5520-12MW-36W | \$ 193.00 | 10% | <i>\$175.00</i> |
| SECUPLIFT SER 5520-24T | SECUPLIFT-5520-24T | \$ 188.00 | 10% | <i>\$170.47</i> |
| SECUPLIFT SER 5520-24T-ACDC-BASE | SECUPLIFT-5520-24T-ACDC-BASE | \$ 188.00 | 10% | <i>\$170.47</i> |

| | | | | |
|-----------------------------------|------------------------------|-----------|-----|-----------------|
| SECUPLIFT SER 5520-24T-BASE | SECUPLIFT-5520-24T-BASE | \$ 188.00 | 10% | <i>\$170.47</i> |
| SECUPLIFT SER 5520-24W | SECUPLIFT-5520-24W | \$ 188.00 | 10% | <i>\$170.47</i> |
| SECUPLIFT SER 5520-24X | SECUPLIFT-5520-24X | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5520-24X-ACDC-BASE | SECUPLIFT-5520-24X-ACDC-BASE | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5520-24X-BASE | SECUPLIFT-5520-24X-BASE | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5520-48SE | SECUPLIFT-5520-48SE | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5520-48SE-ACDC-BASE | SECUPLIFT-5520-48SE-ACDC-BAS | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5520-48SE-BASE | SECUPLIFT-5520-48SE-BASE | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5520-48T | SECUPLIFT-5520-48T | \$ 193.00 | 10% | <i>\$175.00</i> |
| SECUPLIFT SER 5520-48T-ACDC-BASE | SECUPLIFT-5520-48T-ACDC-BASE | \$ 193.00 | 10% | <i>\$175.00</i> |
| SECUPLIFT SER 5520-48T-BASE | SECUPLIFT-5520-48T-BASE | \$ 193.00 | 10% | <i>\$175.00</i> |
| SECUPLIFT SER 5520-48W | SECUPLIFT-5520-48W | \$ 199.00 | 10% | <i>\$180.44</i> |
| SECUPLIFT SER 5720-24MW | SECUPLIFT-5720-24MW | \$ 224.00 | 10% | <i>\$203.11</i> |
| SECUPLIFT SER 5720-24MXW | SECUPLIFT-5720-24MXW | \$ 224.00 | 10% | <i>\$203.11</i> |
| SECUPLIFT SER 5720-48MW | SECUPLIFT-5720-48MW | \$ 224.00 | 10% | <i>\$203.11</i> |
| SECUPLIFT SER 5720-48MXW | SECUPLIFT-5720-48MXW | \$ 336.00 | 10% | <i>\$304.67</i> |
| SECUPLIFT SER 7520-48XT-6C | SECUPLIFT-7520-48XT-6C | \$ 372.00 | 10% | <i>\$337.31</i> |

| | | | | |
|----------------------------------|------------------------------|-----------|-----|-----------------|
| SECUPLIFT SER 7520-48XT-6C-AC-F | SECUPLIFT-7520-48XT-6C-AC-F | \$ 372.00 | 10% | <i>\$337.31</i> |
| SECUPLIFT SER 7520-48XT-6C-AC-R | SECUPLIFT-7520-48XT-6C-AC-R | \$ 372.00 | 10% | <i>\$337.31</i> |
| SECUPLIFT SER 7520-48Y-8C | SECUPLIFT-7520-48Y-8C | \$ 349.00 | 10% | <i>\$316.46</i> |
| SECUPLIFT SER 7520-48Y-8C-AC-F | SECUPLIFT-7520-48Y-8C-AC-F | \$ 349.00 | 10% | <i>\$316.46</i> |
| SECUPLIFT SER 7520-48Y-8C-AC-R | SECUPLIFT-7520-48Y-8C-AC-R | \$ 349.00 | 10% | <i>\$316.46</i> |
| SECUPLIFT SER 7520-48YE-8CE | SECUPLIFT-7520-48YE-8CE | \$ 349.00 | 10% | <i>\$316.46</i> |
| SECUPLIFT SER 7520-48YE-8CE-AC-F | SECUPLIFT-7520-48YE-8CE-AC-F | \$ 349.00 | 10% | <i>\$316.46</i> |
| SECUPLIFT SER 7520-48YE-8CE-AC-R | SECUPLIFT-7520-48YE-8CE-AC-R | \$ 349.00 | 10% | <i>\$316.46</i> |
| SECUPLIFT SER 7720-32C | SECUPLIFT-7720-32C | \$ 582.00 | 10% | <i>\$527.73</i> |
| SECUPLIFT SER 7720-32C-AC-F | SECUPLIFT-7720-32C-AC-F | \$ 582.00 | 10% | <i>\$527.73</i> |
| SECUPLIFT SER 7720-32C-AC-R | SECUPLIFT-7720-32C-AC-R | \$ 582.00 | 10% | <i>\$527.73</i> |
| SECUPLIFT SER 8520-48XT-6C | SECUPLIFT-8520-48XT-6C | \$ 560.00 | 10% | <i>\$507.78</i> |
| SECUPLIFT SER 8520-48XT-6C-AC-F | SECUPLIFT-8520-48XT-6C-AC-F | \$ 560.00 | 10% | <i>\$507.78</i> |
| SECUPLIFT SER 8520-48XT-6C-AC-R | SECUPLIFT-8520-48XT-6C-AC-R | \$ 560.00 | 10% | <i>\$507.78</i> |
| SECUPLIFT SER 8520-48XT-6C-DC-F | SECUPLIFT-8520-48XT-6C-DC-F | \$ 560.00 | 10% | <i>\$507.78</i> |

| | | | | |
|---------------------------------|-----------------------------|-------------|-----|------------|
| SECUPLIFT SER 8520-48XT-6C-DC-R | SECUPLIFT-8520-48XT-6C-DC-R | \$ 560.00 | 10% | \$507.78 |
| SECUPLIFT SER 8520-48Y-8C | SECUPLIFT-8520-48Y-8C | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8520-48Y-8C-AC-F | SECUPLIFT-8520-48Y-8C-AC-F | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8520-48Y-8C-AC-R | SECUPLIFT-8520-48Y-8C-AC-R | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8520-48Y-8C-DC-F | SECUPLIFT-8520-48Y-8C-DC-F | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8520-48Y-8C-DC-R | SECUPLIFT-8520-48Y-8C-DC-R | \$ 594.00 | 10% | \$538.61 |
| EW SECUPLIFT 86100 | SECUPLIFT-86100 | \$ 679.00 | 10% | \$615.68 |
| EW SECUPLIFT 86101 | SECUPLIFT-86101 | \$ 1,020.00 | 10% | \$924.89 |
| EW SECUPLIFT 87100 | SECUPLIFT-87100 | \$ 407.00 | 10% | \$369.05 |
| EW SECUPLIFT 87101 | SECUPLIFT-87101 | \$ 679.00 | 10% | \$615.68 |
| SECUPLIFT SER 8720-32C | SECUPLIFT-8720-32C | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8720-32C-AC-F | SECUPLIFT-8720-32C-AC-F | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8720-32C-AC-R | SECUPLIFT-8720-32C-AC-R | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8720-32C-DC-F | SECUPLIFT-8720-32C-DC-F | \$ 594.00 | 10% | \$538.61 |
| SECUPLIFT SER 8720-32C-DC-R | SECUPLIFT-8720-32C-DC-R | \$ 594.00 | 10% | \$538.61 |
| EW SECUPLIFT 88100 | SECUPLIFT-88100 | \$ 679.00 | 10% | \$615.68 |
| SECUPLIFT 8820-40C | Secuplift-8820-40C | \$ 1,310.00 | 10% | \$1,187.84 |

| | | | | |
|------------------------------------|-----------------------------|-------------|-----|-------------------|
| SECUPLIFT 8820-40C-AC-F | Secuplift-8820-40C-AC-F | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |
| SECUPLIFT 8820-40C-AC-R | Secuplift-8820-40C-AC-R | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |
| SECUPLIFT 8820-40C-DC-F | Secuplift-8820-40C-DC-F | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |
| SECUPLIFT 8820-40C-DC-R | Secuplift-8820-40C-DC-R | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |
| SECUPLIFT 8820-80C | Secuplift-8820-80C | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT 8820-80C-AC-F | Secuplift-8820-80C-AC-F | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT 8820-80C-AC-R | Secuplift-8820-80C-AC-R | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT 8820-80C-DC-F | Secuplift-8820-80C-DC-F | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT 8820-80C-DC-R | Secuplift-8820-80C-DC-R | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT SER 9920-16C | SECUPLIFT-9920-16C | \$ 890.00 | 10% | <i>\$807.01</i> |
| SECUPLIFT SER 9920-4D | SECUPLIFT-9920-4D | \$ 890.00 | 10% | <i>\$807.01</i> |
| SECUPLIFT SER 9920-NPB-8 | SECUPLIFT-9920-NPB-8 | \$ 2,671.00 | 10% | <i>\$2,421.93</i> |
| EW Secure Uplift-AH-AP-1130-AC-CE | SECUPLIFT-AH-AP-1130-AC-CE | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-1130-AC-FCC | SECUPLIFT-AH-AP-1130-AC-FCC | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-1130-AC-W | SECUPLIFT-AH-AP-1130-AC-W | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-122-AC-CAN | SECUPLIFT-AH-AP-122-AC-CAN | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-122-AC-CE | SECUPLIFT-AH-AP-122-AC-CE | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-122-AC-FCC | SECUPLIFT-AH-AP-122-AC-FCC | \$ 13.00 | 10% | <i>\$11.79</i> |

| | | | | |
|------------------------------------|-----------------------------|----------|-----|----------------|
| EW Secure Uplift-AH-AP-122-AC-W | SECUPLIFT-AH-AP-122-AC-W | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-130-AC-CE | SECUPLIFT-AH-AP-130-AC-CE | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-130-AC-FCC | SECUPLIFT-AH-AP-130-AC-FCC | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-130-AC-W | SECUPLIFT-AH-AP-130-AC-W | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-150W-AC-CAN | SECUPLIFT-AH-AP-150W-AC-CAN | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-150W-AC-CE | SECUPLIFT-AH-AP-150W-AC-CE | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-150W-AC-FCC | SECUPLIFT-AH-AP-150W-AC-FCC | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-150W-AC-W | SECUPLIFT-AH-AP-150W-AC-W | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-230-AC-CE | SECUPLIFT-AH-AP-230-AC-CE | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-230-AC-FCC | SECUPLIFT-AH-AP-230-AC-FCC | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-230-AC-W | SECUPLIFT-AH-AP-230-AC-W | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-250-AC-CAN | SECUPLIFT-AH-AP-250-AC-CAN | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-250-AC-CE | SECUPLIFT-AH-AP-250-AC-CE | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-250-AC-FCC | SECUPLIFT-AH-AP-250-AC-FCC | \$ 13.00 | 10% | <i>\$11.79</i> |

| | | | | |
|------------------------------------|-----------------------------|----------|-----|----------------|
| EW Secure Uplift-AH-AP-250-AC-W | SECUPLIFT-AH-AP-250-AC-W | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-630-AX-CAN | SECUPLIFT-AH-AP-630-AX-CAN | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-630-AX-CE | SECUPLIFT-AH-AP-630-AX-CE | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-630-AX-FCC | SECUPLIFT-AH-AP-630-AX-FCC | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-630-AX-W | SECUPLIFT-AH-AP-630-AX-W | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-AP-650-AX-CAN | SECUPLIFT-AH-AP-650-AX-CAN | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-AP-650-AX-CE | SECUPLIFT-AH-AP-650-AX-CE | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-AP-650-AX-FCC | SECUPLIFT-AH-AP-650-AX-FCC | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-AP-650-AX-W | SECUPLIFT-AH-AP-650-AX-W | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-AP-650X-AX-CAN | SECUPLIFT-AH-AP-650X-AX-CAN | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-AP-650X-AX-CE | SECUPLIFT-AH-AP-650X-AX-CE | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-AP-650X-AX-FCC | SECUPLIFT-AH-AP-650X-AX-FCC | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-AP-650X-AX-W | SECUPLIFT-AH-AP-650X-AX-W | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-ATOM-CAN | SECUPLIFT-AH-ATOM-CAN | \$ 11.00 | 10% | <i>\$9.97</i> |

| | | | | |
|---------------------------------|--------------------------|----------|-----|----------------|
| EW Secure Uplift-AH-ATOM-CE-EU | SECUPLIFT-AH-ATOM-CE-EU | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-ATOM-CE-UK | SECUPLIFT-AH-ATOM-CE-UK | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-ATOM-FCC | SECUPLIFT-AH-ATOM-FCC | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-ATOM-W | SECUPLIFT-AH-ATOM-W | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AH-ATOM-W-EU | SECUPLIFT-AH-ATOM-W-EU | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-ATOM-W-UK | SECUPLIFT-AH-ATOM-W-UK | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-SR-2208P-AU | SECUPLIFT-AH-SR-2208P-AU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2208P-EU | SECUPLIFT-AH-SR-2208P-EU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2208P-NA | SECUPLIFT-AH-SR-2208P-NA | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2208P-UK | SECUPLIFT-AH-SR-2208P-UK | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2224P-AU | SECUPLIFT-AH-SR-2224P-AU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2224P-EU | SECUPLIFT-AH-SR-2224P-EU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2224P-NA | SECUPLIFT-AH-SR-2224P-NA | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2224P-UK | SECUPLIFT-AH-SR-2224P-UK | \$ 13.00 | 10% | <i>\$11.79</i> |

| | | | | |
|---------------------------------|--------------------------|----------|-----|----------------|
| EW Secure Uplift-AH-SR-2324P-AU | SECUPLIFT-AH-SR-2324P-AU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2324P-EU | SECUPLIFT-AH-SR-2324P-EU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2324P-NA | SECUPLIFT-AH-SR-2324P-NA | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2324P-UK | SECUPLIFT-AH-SR-2324P-UK | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-SR-2348P-AU | SECUPLIFT-AH-SR-2348P-AU | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-SR-2348P-EU | SECUPLIFT-AH-SR-2348P-EU | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-SR-2348P-NA | SECUPLIFT-AH-SR-2348P-NA | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-SR-2348P-UK | SECUPLIFT-AH-SR-2348P-UK | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AH-XR200P-AU | SECUPLIFT-AH-XR200P-AU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR200P-EU | SECUPLIFT-AH-XR200P-EU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR200P-UK | SECUPLIFT-AH-XR200P-UK | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR200P-US | SECUPLIFT-AH-XR200P-US | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR600P | SECUPLIFT-AH-XR600P | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR600P-AU | SECUPLIFT-AH-XR600P-AU | \$ 13.00 | 10% | <i>\$11.79</i> |

| | | | | |
|------------------------------------|-----------------------------|----------|-----|----------------|
| EW Secure Uplift-AH-XR600P-EU | SECUPLIFT-AH-XR600P-EU | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR600P-KR | SECUPLIFT-AH-XR600P-KR | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR600P-UK | SECUPLIFT-AH-XR600P-UK | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift-AH-XR600P-US | SECUPLIFT-AH-XR600P-US | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift AP-8533-68SB30-IL | SECUPLIFT-AP-8533-68SB30-IL | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER AP3000-WW | SECUPLIFT-AP3000-WW | \$ 10.00 | 6% | <i>\$9.47</i> |
| SECUPLIFT SER AP3000X-WW | SECUPLIFT-AP3000X-WW | \$ 18.00 | 6% | <i>\$17.05</i> |
| SECUPLIFT SER AP302W-WR | SECUPLIFT-AP302W-WR | \$ 11.00 | 6% | <i>\$10.42</i> |
| EW Secure Uplift-AP305C-CAN | SECUPLIFT-AP305C-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP305C-FCC | SECUPLIFT-AP305C-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP305C-WR | SECUPLIFT-AP305C-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP305CX-CAN | SECUPLIFT-AP305CX-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP305CX-FCC | SECUPLIFT-AP305CX-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP305CX-WR | SECUPLIFT-AP305CX-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| SECUPLIFT SER AP310e-WR | SECUPLIFT-AP310e-WR | \$ 10.00 | 6% | <i>\$9.47</i> |
| SECUPLIFT SER AP310i-WR | SECUPLIFT-AP310i-WR | \$ 10.00 | 6% | <i>\$9.47</i> |
| SECUPLIFT SER AP360e-WR | SECUPLIFT-AP360e-WR | \$ 20.00 | 6% | <i>\$18.94</i> |
| SECUPLIFT SER AP360i-WR | SECUPLIFT-AP360i-WR | \$ 20.00 | 6% | <i>\$18.94</i> |

| | | | | |
|--------------------------------|-------------------------|----------|-----|----------------|
| SECUPLIFT SER AP4000-WW | SECUPLIFT-AP4000-WW | \$ 21.00 | 6% | <i>\$19.89</i> |
| EW Secure Uplift-AP410C-CAN | SECUPLIFT-AP410C-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP410C-FCC | SECUPLIFT-AP410C-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP410C-WR | SECUPLIFT-AP410C-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| SECUPLIFT SER AP410e-WR | SECUPLIFT-AP410e-WR | \$ 25.00 | 6% | <i>\$23.68</i> |
| SECUPLIFT SER AP410i-WR | SECUPLIFT-AP410i-WR | \$ 25.00 | 6% | <i>\$23.68</i> |
| EW Secure Uplift-AP460C-CAN | SECUPLIFT-AP460C-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP460C-FCC | SECUPLIFT-AP460C-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP460C-WR | SECUPLIFT-AP460C-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| SECUPLIFT SER AP460e-WR | SECUPLIFT-AP460e-WR | \$ 27.00 | 6% | <i>\$25.57</i> |
| SECUPLIFT SER AP460i-WR | SECUPLIFT-AP460i-WR | \$ 27.00 | 6% | <i>\$25.57</i> |
| EW Secure Uplift-AP460S12C-CAN | SECUPLIFT-AP460S12C-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP460S12C-FCC | SECUPLIFT-AP460S12C-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP460S12C-WR | SECUPLIFT-AP460S12C-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP460S6C-CAN | SECUPLIFT-AP460S6C-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP460S6C-FCC | SECUPLIFT-AP460S6C-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP460S6C-WR | SECUPLIFT-AP460S6C-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| SECUPLIFT SER AP5010-WW | SECUPLIFT-AP5010-WW | \$ 34.00 | 6% | <i>\$32.20</i> |

| | | | | |
|---------------------------------|--------------------------|----------|-----|----------------|
| SECUPLIFT SER AP5020-WW | SECUPLIFT-AP5020-WW | \$ 38.00 | 6% | <i>\$35.99</i> |
| SECUPLIFT SER AP5050D-WW | SECUPLIFT-AP5050D-WW | \$ 86.00 | 6% | <i>\$81.45</i> |
| SECUPLIFT SER AP5050U-WW | SECUPLIFT-AP5050U-WW | \$ 67.00 | 6% | <i>\$63.45</i> |
| EW Secure Uplift AP505i-FCC | SECUPLIFT-AP505i-FCC | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift AP505i-FCC-TAA | SECUPLIFT-AP505i-FCC-TAA | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift AP505i-WR | SECUPLIFT-AP505i-WR | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift-AP510C-CAN | SECUPLIFT-AP510C-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510C-CE | SECUPLIFT-AP510C-CE | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510C-FCC | SECUPLIFT-AP510C-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510C-W | SECUPLIFT-AP510C-W | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510C-WR | SECUPLIFT-AP510C-WR | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510CX-W | SECUPLIFT-AP510C-WW | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AP510CX-CAN | SECUPLIFT-AP510CX-CAN | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510CX-CE | SECUPLIFT-AP510CX-CE | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510CX-FCC | SECUPLIFT-AP510CX-FCC | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510CX-W | SECUPLIFT-AP510CX-W | \$ 12.00 | 10% | <i>\$10.88</i> |
| EW Secure Uplift-AP510CX-WR | SECUPLIFT-AP510CX-WR | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift-AP510CX-WR | SECUPLIFT-AP510CX-WW | \$ 11.00 | 10% | <i>\$9.97</i> |
| EW Secure Uplift AP510e-FCC | SECUPLIFT-AP510e-FCC | \$ 17.00 | 10% | <i>\$15.41</i> |

| | | | | |
|---------------------------------|--------------------------|-------------|-----|-------------------|
| EW Secure Uplift AP510e-FCC-TAA | SECUPLIFT-AP510e-FCC-TAA | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift AP510e-WR | SECUPLIFT-AP510e-WR | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift AP510i-FCC | SECUPLIFT-AP510i-FCC | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift AP510i-FCC-TAA | SECUPLIFT-AP510i-FCC-TAA | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift AP510i-WR | SECUPLIFT-AP510i-WR | \$ 17.00 | 10% | <i>\$15.41</i> |
| EW Secure Uplift AP560h-FCC | SECUPLIFT-AP560h-FCC | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Secure Uplift AP560h-WR | SECUPLIFT-AP560h-WR | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Secure Uplift AP560i-FCC | SECUPLIFT-AP560i-FCC | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Secure Uplift AP560i-WR | SECUPLIFT-AP560i-WR | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Secure Uplift AP560m-FCC | SECUPLIFT-AP560m-FCC | \$ 29.00 | 10% | <i>\$26.30</i> |
| EW Secure Uplift AP560t-FCC | SECUPLIFT-AP560t-FCC | \$ 58.00 | 10% | <i>\$52.59</i> |
| EW Secure Uplift AP560u-FCC | SECUPLIFT-AP560u-FCC | \$ 29.00 | 10% | <i>\$26.30</i> |
| SECUPLIFT SER E2122-1 | SECUPLIFT-E2122-1 | \$ 1,400.00 | 6% | <i>\$1,325.87</i> |
| SECUPLIFT SER E3120-1 | SECUPLIFT-E3120-1 | \$ 2,289.00 | 6% | <i>\$2,167.80</i> |
| EW SECUPLIFT H30078 | SECUPLIFT-H30078 | \$ 186.00 | 10% | <i>\$168.66</i> |
| EW SECUPLIFT H30104 | SECUPLIFT-H30104 | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW SECUPLIFT H30105 | SECUPLIFT-H30105 | \$ 205.00 | 10% | <i>\$185.88</i> |
| SECUPLIFT H30133 | SECUPLIFT-H30133 | \$ 647.00 | 10% | <i>\$586.67</i> |
| SECUPLIFT H30134 | SECUPLIFT-H30134 | \$ 647.00 | 10% | <i>\$586.67</i> |
| SECUPLIFT H30381 | SECUPLIFT-H30381 | \$ 97.00 | 10% | <i>\$87.95</i> |

| | | | | |
|-------------------------|------------------|-----------|-----|-----------------|
| SECUPLIFT H30384 | SECUPLIFT-H30384 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT H30394 | SECUPLIFT-H30394 | \$ 194.00 | 10% | <i>\$175.91</i> |
| SECUPLIFT H30396 | SECUPLIFT-H30396 | \$ 194.00 | 10% | <i>\$175.91</i> |
| SECUPLIFT H30501 | SECUPLIFT-H30501 | \$ 194.00 | 10% | <i>\$175.91</i> |
| EW SECUPLIFT H30569 | SECUPLIFT-H30569 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT H30573 | SECUPLIFT-H30573 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT H30575 | SECUPLIFT-H30575 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT H30576 | SECUPLIFT-H30576 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW Secure Uplift H30773 | SECUPLIFT-H30773 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Secure Uplift H30776 | SECUPLIFT-H30776 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Secure Uplift H30779 | SECUPLIFT-H30779 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H30782 | SECUPLIFT-H30782 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H30785 | SECUPLIFT-H30785 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H30787 | SECUPLIFT-H30787 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H30790 | SECUPLIFT-H30790 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H30871 | SECUPLIFT-H30871 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Secure Uplift H30876 | SECUPLIFT-H30876 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW SECUPLIFT H30898 | SECUPLIFT-H30898 | \$ 67.00 | 10% | <i>\$60.75</i> |
| EW SECUPLIFT H30900 | SECUPLIFT-H30900 | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW SECUPLIFT H30901 | SECUPLIFT-H30901 | \$ 395.00 | 10% | <i>\$358.17</i> |
| EW SECUPLIFT H30902 | SECUPLIFT-H30902 | \$ 658.00 | 10% | <i>\$596.64</i> |

| | | | | |
|-------------------------|------------------|-------------|-----|-------------------|
| EW SECUPLIFT H30904 | SECUPLIFT-H30904 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT H30905 | SECUPLIFT-H30905 | \$ 1,529.00 | 10% | <i>\$1,386.42</i> |
| EW Secure Uplift H30912 | SECUPLIFT-H30912 | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW Secure Uplift H30914 | SECUPLIFT-H30914 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H30967 | SECUPLIFT-H30967 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Secure Uplift H30971 | SECUPLIFT-H30971 | \$ 20.00 | 10% | <i>\$18.14</i> |
| EW Secure Uplift H30974 | SECUPLIFT-H30974 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Secure Uplift H30977 | SECUPLIFT-H30977 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Secure Uplift H31042 | SECUPLIFT-H31042 | \$ 36.00 | 10% | <i>\$32.64</i> |
| EW SECUPLIFT H31043 | SECUPLIFT-H31043 | \$ 70.00 | 10% | <i>\$63.47</i> |
| EW Secure Uplift H31060 | SECUPLIFT-H31060 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H31066 | SECUPLIFT-H31066 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H31077 | SECUPLIFT-H31077 | \$ 36.00 | 10% | <i>\$32.64</i> |
| EW Secure Uplift H31127 | SECUPLIFT-H31127 | \$ 35.00 | 10% | <i>\$31.74</i> |
| EW Secure Uplift H31135 | SECUPLIFT-H31135 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31204 | SECUPLIFT-H31204 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H31207 | SECUPLIFT-H31207 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H31335 | SECUPLIFT-H31335 | \$ 18.00 | 10% | <i>\$16.32</i> |
| EW SECUPLIFT H31337 | SECUPLIFT-H31337 | \$ 1,985.00 | 10% | <i>\$1,799.90</i> |
| EW SECUPLIFT H31338 | SECUPLIFT-H31338 | \$ 1,985.00 | 10% | <i>\$1,799.90</i> |
| EW SECUPLIFT H31339 | SECUPLIFT-H31339 | \$ 193.00 | 10% | <i>\$175.00</i> |

| | | | | |
|-------------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT H31340 | SECUPLIFT-H31340 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT H31341 | SECUPLIFT-H31341 | \$ 662.00 | 10% | <i>\$600.27</i> |
| EW SECUPLIFT H31342 | SECUPLIFT-H31342 | \$ 397.00 | 10% | <i>\$359.98</i> |
| EW SECUPLIFT H31343 | SECUPLIFT-H31343 | \$ 397.00 | 10% | <i>\$359.98</i> |
| EW SECUPLIFT H31344 | SECUPLIFT-H31344 | \$ 397.00 | 10% | <i>\$359.98</i> |
| EW SECUPLIFT H31345 | SECUPLIFT-H31345 | \$ 397.00 | 10% | <i>\$359.98</i> |
| EW SECUPLIFT H31346 | SECUPLIFT-H31346 | \$ 397.00 | 10% | <i>\$359.98</i> |
| EW Secure Uplift H31348 | SECUPLIFT-H31348 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Secure Uplift H31349 | SECUPLIFT-H31349 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW Secure Uplift H31350 | SECUPLIFT-H31350 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Secure Uplift H31351 | SECUPLIFT-H31351 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31352 | SECUPLIFT-H31352 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31353 | SECUPLIFT-H31353 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31354 | SECUPLIFT-H31354 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31355 | SECUPLIFT-H31355 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Secure Uplift H31356 | SECUPLIFT-H31356 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Secure Uplift H31357 | SECUPLIFT-H31357 | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW Secure Uplift H31358 | SECUPLIFT-H31358 | \$ 15.00 | 10% | <i>\$13.60</i> |
| EW Secure Uplift H31359 | SECUPLIFT-H31359 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31360 | SECUPLIFT-H31360 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31361 | SECUPLIFT-H31361 | \$ 647.00 | 10% | <i>\$586.67</i> |

| | | | | |
|-------------------------|------------------|-------------|-----|-------------------|
| EW SECUPLIFT H31362 | SECUPLIFT-H31362 | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW SECUPLIFT H31363 | SECUPLIFT-H31363 | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW SECUPLIFT H31364 | SECUPLIFT-H31364 | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW SECUPLIFT H31365 | SECUPLIFT-H31365 | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW SECUPLIFT H31366 | SECUPLIFT-H31366 | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW SECUPLIFT H31367 | SECUPLIFT-H31367 | \$ 1,940.00 | 10% | <i>\$1,759.10</i> |
| EW SECUPLIFT H31368 | SECUPLIFT-H31368 | \$ 150.00 | 10% | <i>\$136.01</i> |
| EW Secure Uplift H31369 | SECUPLIFT-H31369 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW Secure Uplift H31370 | SECUPLIFT-H31370 | \$ 13.00 | 10% | <i>\$11.79</i> |
| EW SECUPLIFT H32010 | SECUPLIFT-H32010 | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW SECUPLIFT H32011 | SECUPLIFT-H32011 | \$ 177.00 | 10% | <i>\$160.49</i> |
| EW SECUPLIFT H32012 | SECUPLIFT-H32012 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32013 | SECUPLIFT-H32013 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32014 | SECUPLIFT-H32014 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32015 | SECUPLIFT-H32015 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32016 | SECUPLIFT-H32016 | \$ 169.00 | 10% | <i>\$153.24</i> |
| EW SECUPLIFT H32017 | SECUPLIFT-H32017 | \$ 169.00 | 10% | <i>\$153.24</i> |
| EW SECUPLIFT H32018 | SECUPLIFT-H32018 | \$ 169.00 | 10% | <i>\$153.24</i> |
| EW SECUPLIFT H32019 | SECUPLIFT-H32019 | \$ 169.00 | 10% | <i>\$153.24</i> |
| EW SECUPLIFT H32020 | SECUPLIFT-H32020 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32021 | SECUPLIFT-H32021 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |

| | | | | |
|---------------------|------------------|-------------|-----|-------------------|
| EW SECUPLIFT H32022 | SECUPLIFT-H32022 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32023 | SECUPLIFT-H32023 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32028 | SECUPLIFT-H32028 | \$ 3,881.00 | 10% | <i>\$3,519.10</i> |
| EW SECUPLIFT H32029 | SECUPLIFT-H32029 | \$ 181.00 | 10% | <i>\$164.12</i> |
| EW SECUPLIFT H32030 | SECUPLIFT-H32030 | \$ 3,779.00 | 10% | <i>\$3,426.61</i> |
| EW SECUPLIFT H32031 | SECUPLIFT-H32031 | \$ 3,779.00 | 10% | <i>\$3,426.61</i> |
| EW SECUPLIFT H32032 | SECUPLIFT-H32032 | \$ 3,779.00 | 10% | <i>\$3,426.61</i> |
| EW SECUPLIFT H32033 | SECUPLIFT-H32033 | \$ 3,779.00 | 10% | <i>\$3,426.61</i> |
| EW SECUPLIFT H32038 | SECUPLIFT-H32038 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32039 | SECUPLIFT-H32039 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32040 | SECUPLIFT-H32040 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32041 | SECUPLIFT-H32041 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32046 | SECUPLIFT-H32046 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32047 | SECUPLIFT-H32047 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32048 | SECUPLIFT-H32048 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32049 | SECUPLIFT-H32049 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32054 | SECUPLIFT-H32054 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32055 | SECUPLIFT-H32055 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32056 | SECUPLIFT-H32056 | \$ 163.00 | 10% | <i>\$147.80</i> |
| EW SECUPLIFT H32059 | SECUPLIFT-H32059 | \$ 163.00 | 10% | <i>\$147.80</i> |
| EW SECUPLIFT H32060 | SECUPLIFT-H32060 | \$ 156.00 | 10% | <i>\$141.45</i> |

| | | | | |
|---------------------|------------------|-------------|-----|-------------------|
| EW SECUPLIFT H32062 | SECUPLIFT-H32062 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32064 | SECUPLIFT-H32064 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32065 | SECUPLIFT-H32065 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW SECUPLIFT H32066 | SECUPLIFT-H32066 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW SECUPLIFT H32067 | SECUPLIFT-H32067 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW SECUPLIFT H32068 | SECUPLIFT-H32068 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW SECUPLIFT H32069 | SECUPLIFT-H32069 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW SECUPLIFT H32070 | SECUPLIFT-H32070 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW SECUPLIFT H32071 | SECUPLIFT-H32071 | \$ 156.00 | 10% | <i>\$141.45</i> |
| EW SECUPLIFT H32072 | SECUPLIFT-H32072 | \$ 152.00 | 10% | <i>\$137.83</i> |
| EW SECUPLIFT H32073 | SECUPLIFT-H32073 | \$ 2,862.00 | 10% | <i>\$2,595.12</i> |
| EW SECUPLIFT H32074 | SECUPLIFT-H32074 | \$ 2,683.00 | 10% | <i>\$2,432.81</i> |
| EW SECUPLIFT H32075 | SECUPLIFT-H32075 | \$ 3,816.00 | 10% | <i>\$3,460.16</i> |
| EW SECUPLIFT H32076 | SECUPLIFT-H32076 | \$ 3,816.00 | 10% | <i>\$3,460.16</i> |
| EW SECUPLIFT H32101 | SECUPLIFT-H32101 | \$ 3,669.00 | 10% | <i>\$3,326.87</i> |
| EW SECUPLIFT H32102 | SECUPLIFT-H32102 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32103 | SECUPLIFT-H32103 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32104 | SECUPLIFT-H32104 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32105 | SECUPLIFT-H32105 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32106 | SECUPLIFT-H32106 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32107 | SECUPLIFT-H32107 | \$ 536.00 | 10% | <i>\$486.02</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT H32108 | SECUPLIFT-H32108 | \$ 536.00 | 10% | <i>\$486.02</i> |
| EW SECUPLIFT H32109 | SECUPLIFT-H32109 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32110 | SECUPLIFT-H32110 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32111 | SECUPLIFT-H32111 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32112 | SECUPLIFT-H32112 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32113 | SECUPLIFT-H32113 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32114 | SECUPLIFT-H32114 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32115 | SECUPLIFT-H32115 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32116 | SECUPLIFT-H32116 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32117 | SECUPLIFT-H32117 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32118 | SECUPLIFT-H32118 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32119 | SECUPLIFT-H32119 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32120 | SECUPLIFT-H32120 | \$ 148.00 | 10% | <i>\$134.20</i> |
| EW SECUPLIFT H32121 | SECUPLIFT-H32121 | \$ 536.00 | 10% | <i>\$486.02</i> |
| EW SECUPLIFT H32122 | SECUPLIFT-H32122 | \$ 536.00 | 10% | <i>\$486.02</i> |
| EW SECUPLIFT H32123 | SECUPLIFT-H32123 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32124 | SECUPLIFT-H32124 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32125 | SECUPLIFT-H32125 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32126 | SECUPLIFT-H32126 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32127 | SECUPLIFT-H32127 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32128 | SECUPLIFT-H32128 | \$ 158.00 | 10% | <i>\$143.27</i> |

| | | | | |
|---------------------|------------------|-------------|-----|-------------------|
| EW SECUPLIFT H32129 | SECUPLIFT-H32129 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32130 | SECUPLIFT-H32130 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32131 | SECUPLIFT-H32131 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32132 | SECUPLIFT-H32132 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32133 | SECUPLIFT-H32133 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32134 | SECUPLIFT-H32134 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32135 | SECUPLIFT-H32135 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32136 | SECUPLIFT-H32136 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32137 | SECUPLIFT-H32137 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32138 | SECUPLIFT-H32138 | \$ 158.00 | 10% | <i>\$143.27</i> |
| EW SECUPLIFT H32142 | SECUPLIFT-H32142 | \$ 1,889.00 | 10% | <i>\$1,712.85</i> |
| EW SECUPLIFT H32146 | SECUPLIFT-H32146 | \$ 153.00 | 10% | <i>\$138.73</i> |
| EW SECUPLIFT H34010 | SECUPLIFT-H34010 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW SECUPLIFT H34015 | SECUPLIFT-H34015 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW SECUPLIFT H34018 | SECUPLIFT-H34018 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT H34019 | SECUPLIFT-H34019 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT H34020 | SECUPLIFT-H34020 | \$ 31.00 | 10% | <i>\$28.11</i> |
| EW SECUPLIFT H34021 | SECUPLIFT-H34021 | \$ 64.00 | 10% | <i>\$58.03</i> |
| EW SECUPLIFT H34048 | SECUPLIFT-H34048 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW SECUPLIFT H34056 | SECUPLIFT-H34056 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW SECUPLIFT H34057 | SECUPLIFT-H34057 | \$ 223.00 | 10% | <i>\$202.21</i> |

| | | | | |
|---------------------|------------------|-------------|-----|-----------------|
| EW SECUPLIFT H34058 | SECUPLIFT-H34058 | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW SECUPLIFT H34059 | SECUPLIFT-H34059 | \$ 111.00 | 10% | <i>\$100.65</i> |
| EW SECUPLIFT H34062 | SECUPLIFT-H34062 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW SECUPLIFT H34063 | SECUPLIFT-H34063 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW SECUPLIFT H34064 | SECUPLIFT-H34064 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT H34065 | SECUPLIFT-H34065 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT H34066 | SECUPLIFT-H34066 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT H34067 | SECUPLIFT-H34067 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT H34068 | SECUPLIFT-H34068 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT H34069 | SECUPLIFT-H34069 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW SECUPLIFT H34070 | SECUPLIFT-H34070 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT H34071 | SECUPLIFT-H34071 | \$ 103.00 | 10% | <i>\$93.40</i> |
| EW SECUPLIFT H34072 | SECUPLIFT-H34072 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT H34073 | SECUPLIFT-H34073 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT H34074 | SECUPLIFT-H34074 | \$ 690.00 | 10% | <i>\$625.66</i> |
| EW SECUPLIFT H34075 | SECUPLIFT-H34075 | \$ 1,035.00 | 10% | <i>\$938.49</i> |
| EW SECUPLIFT H34076 | SECUPLIFT-H34076 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW SECUPLIFT H34077 | SECUPLIFT-H34077 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW SECUPLIFT H34078 | SECUPLIFT-H34078 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW SECUPLIFT H34079 | SECUPLIFT-H34079 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW SECUPLIFT H34080 | SECUPLIFT-H34080 | \$ 690.00 | 10% | <i>\$625.66</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT H34081 | SECUPLIFT-H34081 | \$ 690.00 | 10% | <i>\$625.66</i> |
| EW SECUPLIFT H34082 | SECUPLIFT-H34082 | \$ 662.00 | 10% | <i>\$600.27</i> |
| EW SECUPLIFT H34083 | SECUPLIFT-H34083 | \$ 662.00 | 10% | <i>\$600.27</i> |
| EW SECUPLIFT H34084 | SECUPLIFT-H34084 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW SECUPLIFT H34085 | SECUPLIFT-H34085 | \$ 385.00 | 10% | <i>\$349.10</i> |
| EW SECUPLIFT H34086 | SECUPLIFT-H34086 | \$ 414.00 | 10% | <i>\$375.39</i> |
| EW SECUPLIFT H34087 | SECUPLIFT-H34087 | \$ 397.00 | 10% | <i>\$359.98</i> |
| EW SECUPLIFT H34088 | SECUPLIFT-H34088 | \$ 643.00 | 10% | <i>\$583.04</i> |
| EW SECUPLIFT H34089 | SECUPLIFT-H34089 | \$ 643.00 | 10% | <i>\$583.04</i> |
| EW SECUPLIFT H34091 | SECUPLIFT-H34091 | \$ 627.00 | 10% | <i>\$568.53</i> |
| EW SECUPLIFT H34092 | SECUPLIFT-H34092 | \$ 627.00 | 10% | <i>\$568.53</i> |
| EW SECUPLIFT H34093 | SECUPLIFT-H34093 | \$ 627.00 | 10% | <i>\$568.53</i> |
| EW SECUPLIFT H34094 | SECUPLIFT-H34094 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34095 | SECUPLIFT-H34095 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34096 | SECUPLIFT-H34096 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34097 | SECUPLIFT-H34097 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34098 | SECUPLIFT-H34098 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34099 | SECUPLIFT-H34099 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34100 | SECUPLIFT-H34100 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34101 | SECUPLIFT-H34101 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34102 | SECUPLIFT-H34102 | \$ 189.00 | 10% | <i>\$171.38</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT H34103 | SECUPLIFT-H34103 | \$ 189.00 | 10% | <i>\$171.38</i> |
| EW SECUPLIFT H34104 | SECUPLIFT-H34104 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT H34105 | SECUPLIFT-H34105 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT H34106 | SECUPLIFT-H34106 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT H34107 | SECUPLIFT-H34107 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT H34108 | SECUPLIFT-H34108 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT H34109 | SECUPLIFT-H34109 | \$ 94.00 | 10% | <i>\$85.23</i> |
| EW SECUPLIFT H34128 | SECUPLIFT-H34128 | \$ 34.00 | 10% | <i>\$30.83</i> |
| EW SECUPLIFT H34129 | SECUPLIFT-H34129 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H34130 | SECUPLIFT-H34130 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34131 | SECUPLIFT-H34131 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW SECUPLIFT H34132 | SECUPLIFT-H34132 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34734 | SECUPLIFT-H34734 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW SECUPLIFT H34735 | SECUPLIFT-H34735 | \$ 97.00 | 10% | <i>\$87.95</i> |
| EW SECUPLIFT H34736 | SECUPLIFT-H34736 | \$ 100.00 | 10% | <i>\$90.68</i> |
| EW SECUPLIFT H34737 | SECUPLIFT-H34737 | \$ 102.00 | 10% | <i>\$92.49</i> |
| EW SECUPLIFT H34738 | SECUPLIFT-H34738 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34739 | SECUPLIFT-H34739 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H34740 | SECUPLIFT-H34740 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34741 | SECUPLIFT-H34741 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34744 | SECUPLIFT-H34744 | \$ 198.00 | 10% | <i>\$179.54</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT H34745 | SECUPLIFT-H34745 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW SECUPLIFT H34746 | SECUPLIFT-H34746 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW SECUPLIFT H34747 | SECUPLIFT-H34747 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW SECUPLIFT H34748 | SECUPLIFT-H34748 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34749 | SECUPLIFT-H34749 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H34750 | SECUPLIFT-H34750 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34751 | SECUPLIFT-H34751 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34752 | SECUPLIFT-H34752 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34753 | SECUPLIFT-H34753 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H34754 | SECUPLIFT-H34754 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34755 | SECUPLIFT-H34755 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34756 | SECUPLIFT-H34756 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34757 | SECUPLIFT-H34757 | \$ 193.00 | 10% | <i>\$175.00</i> |
| EW SECUPLIFT H34758 | SECUPLIFT-H34758 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW SECUPLIFT H34759 | SECUPLIFT-H34759 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34760 | SECUPLIFT-H34760 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H34761 | SECUPLIFT-H34761 | \$ 198.00 | 10% | <i>\$179.54</i> |
| EW SECUPLIFT H35273 | SECUPLIFT-H35273 | \$ 102.00 | 10% | <i>\$92.49</i> |
| EW SECUPLIFT H35274 | SECUPLIFT-H35274 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H35275 | SECUPLIFT-H35275 | \$ 223.00 | 10% | <i>\$202.21</i> |
| EW SECUPLIFT H35276 | SECUPLIFT-H35276 | \$ 407.00 | 10% | <i>\$369.05</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT H35277 | SECUPLIFT-H35277 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT H35278 | SECUPLIFT-H35278 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT H35279 | SECUPLIFT-H35279 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT H35280 | SECUPLIFT-H35280 | \$ 679.00 | 10% | <i>\$615.68</i> |
| EW SECUPLIFT H35292 | SECUPLIFT-H35292 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT H35293 | SECUPLIFT-H35293 | \$ 407.00 | 10% | <i>\$369.05</i> |
| EW SECUPLIFT H35294 | SECUPLIFT-H35294 | \$ 198.00 | 10% | <i>\$179.54</i> |
| SECUPLIFT H35296 | SECUPLIFT-H35296 | \$ 363.00 | 10% | <i>\$329.15</i> |
| SECUPLIFT H35297 | SECUPLIFT-H35297 | \$ 363.00 | 10% | <i>\$329.15</i> |
| SECUPLIFT H35298 | SECUPLIFT-H35298 | \$ 605.00 | 10% | <i>\$548.58</i> |
| SECUPLIFT H35299 | SECUPLIFT-H35299 | \$ 605.00 | 10% | <i>\$548.58</i> |
| SECUPLIFT H35302 | SECUPLIFT-H35302 | \$ 194.00 | 10% | <i>\$175.91</i> |
| SECUPLIFT H35303 | SECUPLIFT-H35303 | \$ 194.00 | 10% | <i>\$175.91</i> |
| SECUPLIFT H35304 | SECUPLIFT-H35304 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT H35305 | SECUPLIFT-H35305 | \$ 194.00 | 10% | <i>\$175.91</i> |
| SECUPLIFT H35306 | SECUPLIFT-H35306 | \$ 194.00 | 10% | <i>\$175.91</i> |
| SECUPLIFT H35307 | SECUPLIFT-H35307 | \$ 194.00 | 10% | <i>\$175.91</i> |
| EW SECUPLIFT H35309 | SECUPLIFT-H35309 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW SECUPLIFT H35310 | SECUPLIFT-H35310 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW SECUPLIFT H35311 | SECUPLIFT-H35311 | \$ 582.00 | 10% | <i>\$527.73</i> |
| EW SECUPLIFT H35312 | SECUPLIFT-H35312 | \$ 349.00 | 10% | <i>\$316.46</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| EW SECUPLIFT H35313 | SECUPLIFT-H35313 | \$ 349.00 | 10% | <i>\$316.46</i> |
| EW SECUPLIFT H35314 | SECUPLIFT-H35314 | \$ 349.00 | 10% | <i>\$316.46</i> |
| EW SECUPLIFT H35318 | SECUPLIFT-H35318 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35319 | SECUPLIFT-H35319 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35320 | SECUPLIFT-H35320 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35321 | SECUPLIFT-H35321 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35322 | SECUPLIFT-H35322 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35323 | SECUPLIFT-H35323 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35328 | SECUPLIFT-H35328 | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW SECUPLIFT H35330 | SECUPLIFT-H35330 | \$ 68.00 | 10% | <i>\$61.66</i> |
| SECUPLIFT H35340 | SECUPLIFT-H35340 | \$ 635.00 | 10% | <i>\$575.79</i> |
| SECUPLIFT H35341 | SECUPLIFT-H35341 | \$ 635.00 | 10% | <i>\$575.79</i> |
| SECUPLIFT H35342 | SECUPLIFT-H35342 | \$ 582.00 | 10% | <i>\$527.73</i> |
| SECUPLIFT H35343 | SECUPLIFT-H35343 | \$ 635.00 | 10% | <i>\$575.79</i> |
| SECUPLIFT H35344 | SECUPLIFT-H35344 | \$ 635.00 | 10% | <i>\$575.79</i> |
| SECUPLIFT H35345 | SECUPLIFT-H35345 | \$ 635.00 | 10% | <i>\$575.79</i> |
| SECUPLIFT H35346 | SECUPLIFT-H35346 | \$ 582.00 | 10% | <i>\$527.73</i> |
| SECUPLIFT H35347 | SECUPLIFT-H35347 | \$ 635.00 | 10% | <i>\$575.79</i> |
| SECUPLIFT H35349 | SECUPLIFT-H35349 | \$ 954.00 | 10% | <i>\$865.04</i> |
| SECUPLIFT H35350 | SECUPLIFT-H35350 | \$ 954.00 | 10% | <i>\$865.04</i> |
| SECUPLIFT H35351 | SECUPLIFT-H35351 | \$ 874.00 | 10% | <i>\$792.50</i> |

| | | | | |
|---------------------|------------------|-----------|-----|-----------------|
| SECUPLIFT H35352 | SECUPLIFT-H35352 | \$ 954.00 | 10% | <i>\$865.04</i> |
| EW SECUPLIFT H35359 | SECUPLIFT-H35359 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35360 | SECUPLIFT-H35360 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35361 | SECUPLIFT-H35361 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT H35362 | SECUPLIFT-H35362 | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT H35366 | SECUPLIFT-H35366 | \$ 191.00 | 10% | <i>\$173.19</i> |
| SECUPLIFT H35367 | SECUPLIFT-H35367 | \$ 191.00 | 10% | <i>\$173.19</i> |
| SECUPLIFT H35368 | SECUPLIFT-H35368 | \$ 191.00 | 10% | <i>\$173.19</i> |
| SECUPLIFT H35369 | SECUPLIFT-H35369 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35370 | SECUPLIFT-H35370 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35375 | SECUPLIFT-H35375 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35376 | SECUPLIFT-H35376 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35377 | SECUPLIFT-H35377 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35378 | SECUPLIFT-H35378 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35379 | SECUPLIFT-H35379 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35380 | SECUPLIFT-H35380 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35381 | SECUPLIFT-H35381 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35384 | SECUPLIFT-H35384 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35385 | SECUPLIFT-H35385 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35386 | SECUPLIFT-H35386 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35387 | SECUPLIFT-H35387 | \$ 97.00 | 10% | <i>\$87.95</i> |

| | | | | |
|----------------------|------------------|-----------|-----|-----------------|
| SECUPLIFT H35388 | SECUPLIFT-H35388 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35389 | SECUPLIFT-H35389 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT H35390 | SECUPLIFT-H35390 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT H35391 | SECUPLIFT-H35391 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT H35392 | SECUPLIFT-H35392 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35393 | SECUPLIFT-H35393 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35394 | SECUPLIFT-H35394 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35395 | SECUPLIFT-H35395 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35396 | SECUPLIFT-H35396 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35397 | SECUPLIFT-H35397 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35398 | SECUPLIFT-H35398 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35399 | SECUPLIFT-H35399 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35400 | SECUPLIFT-H35400 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35401 | SECUPLIFT-H35401 | \$ 95.00 | 10% | <i>\$86.14</i> |
| SECUPLIFT H35426 | SECUPLIFT-H35426 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT H35427 | SECUPLIFT-H35427 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT H35428 | SECUPLIFT-H35428 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT H35429 | SECUPLIFT-H35429 | \$ 97.00 | 10% | <i>\$87.95</i> |
| SECUPLIFT SER H35430 | SECUPLIFT-H35430 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35431 | SECUPLIFT-H35431 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35432 | SECUPLIFT-H35432 | \$ 193.00 | 10% | <i>\$175.00</i> |

| | | | | |
|---------------------------------|------------------|-----------|-----|-----------------|
| SECUPLIFT SER H35433 | SECUPLIFT-H35433 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35434 | SECUPLIFT-H35434 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35435 | SECUPLIFT-H35435 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35436 | SECUPLIFT-H35436 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35437 | SECUPLIFT-H35437 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35438 | SECUPLIFT-H35438 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35439 | SECUPLIFT-H35439 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35440 | SECUPLIFT-H35440 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35441 | SECUPLIFT-H35441 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35442 | SECUPLIFT-H35442 | \$ 184.00 | 10% | <i>\$166.84</i> |
| SECUPLIFT SER H35445 | SECUPLIFT-H35445 | \$ 389.00 | 10% | <i>\$352.73</i> |
| SECUPLIFT SER H35446 | SECUPLIFT-H35446 | \$ 389.00 | 10% | <i>\$352.73</i> |
| SECUPLIFT SER H35447 | SECUPLIFT-H35447 | \$ 597.00 | 10% | <i>\$541.33</i> |
| SECUPLIFT SER H35448 | SECUPLIFT-H35448 | \$ 597.00 | 10% | <i>\$541.33</i> |
| SECUPLIFT SER H35449 | SECUPLIFT-H35449 | \$ 389.00 | 10% | <i>\$352.73</i> |
| SECUPLIFT SER H35450 | SECUPLIFT-H35450 | \$ 358.00 | 10% | <i>\$324.62</i> |
| SECUPLIFT SER H35451 | SECUPLIFT-H35451 | \$ 597.00 | 10% | <i>\$541.33</i> |
| SECUPLIFT SER H35452 | SECUPLIFT-H35452 | \$ 597.00 | 10% | <i>\$541.33</i> |
| SECUPLIFT SER H35455 | SECUPLIFT-H35455 | \$ 185.00 | 10% | <i>\$167.75</i> |
| SECUPLIFT SER VSP4900-48P-B1-2Y | SECUPLIFT-H35456 | \$ 194.00 | 10% | <i>\$175.91</i> |
| SECUPLIFT SER VSP4900-48P-B1-4X | SECUPLIFT-H35457 | \$ 179.00 | 10% | <i>\$162.31</i> |

| | | | | |
|----------------------------------|-----------------------------|-------------|-----|-------------------|
| SECUPLIFT SER VSP4900-48P-B1-4XE | SECUPLIFT-H35458 | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER H35471 | SECUPLIFT-H35471 | \$ 185.00 | 10% | <i>\$167.75</i> |
| EW SECUPLIFT H35600 | SECUPLIFT-H35600 | \$ 102.00 | 10% | <i>\$92.49</i> |
| EW SECUPLIFT H35601 | SECUPLIFT-H35601 | \$ 102.00 | 10% | <i>\$92.49</i> |
| EW SECUPLIFT H35602 | SECUPLIFT-H35602 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H35603 | SECUPLIFT-H35603 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H35604 | SECUPLIFT-H35604 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H35605 | SECUPLIFT-H35605 | \$ 200.00 | 10% | <i>\$181.35</i> |
| EW SECUPLIFT H35606 | SECUPLIFT-H35606 | \$ 205.00 | 10% | <i>\$185.88</i> |
| EW SECUPLIFT H35607 | SECUPLIFT-H35607 | \$ 198.00 | 10% | <i>\$179.54</i> |
| SECUPLIFT SER ISW-24W-4X | SECUPLIFT-ISW-24W-4X | \$ 150.00 | 10% | <i>\$136.01</i> |
| SECUPLIFT SER ISW-4W-4WS-4X | SECUPLIFT-ISW-4W-4WS-4X | \$ 75.00 | 10% | <i>\$68.01</i> |
| EW SECUPLIFT R100-8T | SECUPLIFT-R100-8T | \$ 34.00 | 10% | <i>\$30.83</i> |
| SECUPLIFT SER SLX9150-48XT-DC-F | SECUPLIFT-SLX9150-48XT-DC-F | \$ 560.00 | 10% | <i>\$507.78</i> |
| SECUPLIFT SER SLX9150-48XT-DC-R | SECUPLIFT-SLX9150-48XT-DC-R | \$ 611.00 | 10% | <i>\$554.02</i> |
| SECUPLIFT SER SLX9150-48Y-DC-F | SECUPLIFT-SLX9150-48Y-DC-F | \$ 560.00 | 10% | <i>\$507.78</i> |
| SECUPLIFT SER SLX9150-48Y-DC-R | SECUPLIFT-SLX9150-48Y-DC-R | \$ 611.00 | 10% | <i>\$554.02</i> |
| SECUPLIFT SLX9740-40C | Secuplift-SLX9740-40C | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |

| | | | | |
|--------------------------------|----------------------------|-------------|-----|-------------------|
| SECUPLIFT SLX9740-40C-AC-F | Secuplift-SLX9740-40C-AC-F | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |
| SECUPLIFT SER SLX9740-40C-AC-R | SECUPLIFT-SLX9740-40C-AC-R | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |
| SECUPLIFT SER SLX9740-40C-DC-F | SECUPLIFT-SLX9740-40C-DC-F | \$ 1,310.00 | 10% | <i>\$1,187.84</i> |
| SECUPLIFT SLX9740-80C | Secuplift-SLX9740-80C | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT SLX9740-80C-AC-F | Secuplift-SLX9740-80C-AC-F | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT SER SLX9740-80C-AC-R | SECUPLIFT-SLX9740-80C-AC-R | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT SER SLX9740-80C-DC-F | SECUPLIFT-SLX9740-80C-DC-F | \$ 2,646.00 | 10% | <i>\$2,399.26</i> |
| SECUPLIFT SER V300-8P-2X | SECUPLIFT-V300-8P-2X | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER V300-8T-2X | SECUPLIFT-V300-8T-2X | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER V300HT-8P-2X | SECUPLIFT-V300HT-8P-2X | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER V300HT-8T-2X | SECUPLIFT-V300HT-8T-2X | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW SECUPLIFT VIM2-SS | SECUPLIFT-VIM2-SS | \$ 36.00 | 10% | <i>\$32.64</i> |
| EW SECUPLIFT VIM2-SS128 | SECUPLIFT-VIM2-SS128 | \$ 71.00 | 10% | <i>\$64.38</i> |
| EW SECUPLIFT VIM210G4X | SECUPLIFT-VIM210G4X | \$ 213.00 | 10% | <i>\$193.14</i> |
| EW SECUPLIFT VIM5-2Q | SECUPLIFT-VIM5-2Q | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW SECUPLIFT VIM5-2Y | SECUPLIFT-VIM5-2Y | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW SECUPLIFT VIM5-4X | SECUPLIFT-VIM5-4X | \$ 30.00 | 10% | <i>\$27.20</i> |

| | | | | |
|-------------------------------------|------------------------------|-----------|-----|-----------------|
| EW SECUPLIFT VIM5-4XE | SECUPLIFT-VIM5-4XE | \$ 30.00 | 10% | <i>\$27.20</i> |
| EW SECUPLIFT VIM5-4Y | SECUPLIFT-VIM5-4Y | \$ 33.00 | 10% | <i>\$29.92</i> |
| EW SECUPLIFT VIM5-4YE | SECUPLIFT-VIM5-4YE | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER VSP4900-12MXU-12XE | SECUPLIFT-VSP49-12MXU-12XE | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER VSP4900-12MXU-12XE-B1 | SECUPLIFT-VSP49-12MXU-12XE-B | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER VSP4900-24S | SECUPLIFT-VSP4900-24S | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER VSP4900-24S-B3 | SECUPLIFT-VSP4900-24S-B3 | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER VSP4900-24XE | SECUPLIFT-VSP4900-24XE | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER VSP4900-24XE-B3 | SECUPLIFT-VSP4900-24XE-B3 | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X435-24P-4S | SECUPLIFT-X435-24P-4S | \$ 29.00 | 10% | <i>\$26.30</i> |
| SECUPLIFT SER X435-24T-4S | SECUPLIFT-X435-24T-4S | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER X435-8P-2T-W | SECUPLIFT-X435-8P-2T-W | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER X435-8P-4S | SECUPLIFT-X435-8P-4S | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER X435-8T-4S | SECUPLIFT-X435-8T-4S | \$ 30.00 | 10% | <i>\$27.20</i> |
| SECUPLIFT SER X465-24MU | SECUPLIFT-X465-24MU | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465-24MU-24W | SECUPLIFT-X465-24MU-24W | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465-24S | SECUPLIFT-X465-24S | \$ 179.00 | 10% | <i>\$162.31</i> |

| | | | | |
|-------------------------------|---------------------------|-----------|-----|-----------------|
| SECUPLIFT SER X465-24S-B3 | SECUPLIFT-X465-24S-B3 | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465-24W | SECUPLIFT-X465-24W | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465-24XE | SECUPLIFT-X465-24XE | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465-24XE-B3 | SECUPLIFT-X465-24XE-B3 | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465-48P | SECUPLIFT-X465-48P | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT X465-48T | SECUPLIFT-X465-48T | \$ 175.00 | 10% | <i>\$158.68</i> |
| SECUPLIFT SER X465i-48W | SECUPLIFT-X465i-48W | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465i-48W-B1-S1 | SECUPLIFT-X465i-48W-B1-S1 | \$ 179.00 | 10% | <i>\$162.31</i> |
| SECUPLIFT SER X465i-48W-B2-S1 | SECUPLIFT-X465i-48W-B2-S1 | \$ 179.00 | 10% | <i>\$162.31</i> |
| EW SECUPLIFT X480-24X | SECUPLIFT-X480-24X | \$ 427.00 | 10% | <i>\$387.18</i> |
| EW SECUPLIFT X480-48T | SECUPLIFT-X480-48T | \$ 427.00 | 10% | <i>\$387.18</i> |
| EW SECUPLIFT X480-48X | SECUPLIFT-X480-48X | \$ 427.00 | 10% | <i>\$387.18</i> |
| SECUPLIFT SER X695-48Y-8C | SECUPLIFT-X695-48Y-8C | \$ 358.00 | 10% | <i>\$324.62</i> |
| EW SECUPLIFT XA1440 | SECUPLIFT-XA1440 | \$ 86.00 | 10% | <i>\$77.98</i> |
| EW SECUPLIFT XA1480 | SECUPLIFT-XA1480 | \$ 86.00 | 10% | <i>\$77.98</i> |
| SECUPLIFT SER XSW-BR-M-A-D | SECUPLIFT-XSW-BR-M-A-D | \$ 89.00 | 6% | <i>\$84.29</i> |
| SECUPLIFT SER XSW-BR-S-A-D | SECUPLIFT-XSW-BR-S-A-D | \$ 50.00 | 6% | <i>\$47.35</i> |
| SECUPLIFT SER XSW-BR-XS-A-D | SECUPLIFT-XSW-BR-XS-A-D | \$ 55.00 | 6% | <i>\$52.09</i> |

| | | | | |
|--|-----------------------------|--------------|-----|---------------------|
| SECUPLIFT SER XSW-DC-S-A-D | SECUPLIFT-XSW-DC-S-A-D | \$ 195.00 | 6% | <i>\$184.67</i> |
| SECUPLIFT SER XSW-DCV2-LR-L-A-D | SECUPLIFT-XSW-DCV2-LR-L-A-D | \$ 675.00 | 6% | <i>\$639.26</i> |
| SECUPLIFT SER XSW-DCV2-M-A-D | SECUPLIFT-XSW-DCV2-M-A-D | \$ 600.00 | 6% | <i>\$568.23</i> |
| SECUPLIFT SER XSW-DCV2-SR-L-A-D | SECUPLIFT-XSW-DCV2-SR-L-A-D | \$ 650.00 | 6% | <i>\$615.58</i> |
| EW SECUPLIFT ZR-XFP | SECUPLIFT-ZR-XFP | \$ 186.00 | 10% | <i>\$168.66</i> |
| Extreme SLX 9740-40C Router. Base unit with 40x100GE/40GE capable QSFP28 ports 2 unpopulated power supply slots 6 unpopulated fan slots | SLX9740-40C | \$110,433.00 | 48% | <i>\$57,855.85</i> |
| Extreme SLX 9740-40C-AC-F Router. Base unit with 40x100GE/40GE capable QSFP28 ports 2 AC power supplies 6 fan modules | SLX9740-40C-AC-F | \$120,952.00 | 48% | <i>\$63,366.75</i> |
| Extreme SLX 9740 with Back to Front air flow. Supports 40x100/40G with two AC power supplies six fan modules and a 4-post rack mount kit | SLX9740-40C-AC-R | \$120,952.00 | 48% | <i>\$63,366.75</i> |
| Extreme SLX 9740-80C Router. Base unit with 80x100GE/40GE capable QSFP28 ports 4 unpopulated power supply slots 4 unpopulated fan slots | SLX9740-80C | \$209,041.00 | 48% | <i>\$109,516.58</i> |
| Extreme SLX 9740-80C-AC-F Router. Base unit with 80x100GE/40GE capable QSFP28 ports 4 AC power supplies 4 fan modules | SLX9740-80C-AC-F | \$227,448.00 | 48% | <i>\$119,160.01</i> |

| | | | | |
|--|-------------------|--------------|-----|---------------------|
| Extreme SLX 9740 with Back to Front air flow. Supports 80x100/40G with four AC power supplies four fan modules and a 4-post rack mount kit | SLX9740-80C-AC-R | \$227,448.00 | 48% | <i>\$119,160.01</i> |
| Advanced Feature License for SLX 9740 | SLX9740-ADV-LIC-P | \$12,995.00 | 48% | <i>\$6,808.08</i> |
| AIRDEFENSE ADSP SERVER SW LICENSE | SP-SWSV-P-1 | \$995.00 | 48% | <i>\$521.28</i> |
| ssd Mass Storage for ipe-420ax | SSD-03-xx | \$467.00 | 48% | <i>\$244.66</i> |
| ssd Boot Storage for ipe-420ax | SSD-04-xx | \$58.00 | 48% | <i>\$30.39</i> |
| 2M STACKING CABLE - LIMITED SUPPORT | STK-CAB-2M | \$605.00 | 48% | <i>\$316.96</i> |
| 3-SLOT MODULAR SHELF FOR 1005W PS | STK-RPS-1005CH3 | \$300.00 | 48% | <i>\$157.17</i> |
| 1005W 802.3AT POE REDUNDANT POWER SUPPLY | STK-RPS-1005PS | \$2,824.00 | 48% | <i>\$1,479.49</i> |
| 2-SLOT MODULAR SHELF FOR 150W RPS | STK-RPS-150CH2 | \$275.00 | 48% | <i>\$144.07</i> |
| 8-SLOT MODULAR SHELF FOR 150W PS | STK-RPS-150CH8 | \$674.00 | 48% | <i>\$353.11</i> |
| 150W NON-POE REDUNDANT POWER SUPPLY | STK-RPS-150PS | \$990.00 | 48% | <i>\$518.66</i> |
| EW TAC HM Classic-XIQ Migration 25 AP | TMGTAC-MIG-ETR | \$ 1,800.00 | 6% | <i>\$1,704.69</i> |
| Training Lab Hire per Day/Student | TR-LAB-1 | \$ 35.00 | 1% | <i>\$34.91</i> |
| Training Student Mat. per Day/Student | TR-MAT-1 | \$ 50.00 | 1% | <i>\$49.87</i> |
| V300-8P-2T-W 8 port 10/100/1000BASE-T POE+ ports half/full duplex 2x1000BASE-T ports POE powered 802.3bt type 4 fanless | V300-8P-2T-W | \$1,406.00 | 48% | <i>\$736.60</i> |
| V300-8P-2X 8 10/100/1000BASE-T POE+ ports half/full duplex 2xSFP+ ports fanless comes with 280W power supply and protective front cover | V300-8P-2X | \$1,663.00 | 48% | <i>\$871.25</i> |

| | | | | |
|--|-----------------------|------------|-----|-------------------|
| V300-8T-2X 8 10/100/1000BASE-T ports half/full duplex 2xSFP+ ports fanless comes with 40W power supply and protective front cover | V300-8T-2X | \$1,149.00 | 48% | <i>\$601.96</i> |
| V300HT-8P-2X 8 10/100/1000BASE-T POE+ ports half/full duplex 2xSFP+ ports fanless high temperature model power supply sold separately comes with protective front cover | V300HT-8P- 2X | \$3,202.00 | 48% | <i>\$1,677.53</i> |
| V300HT-8T-2X 8 10/100/1000BASE-T ports half/full duplex 2xSFP+ ports fanless high temperature model power supply sold separately comes with protective front cover | V300HT-8T- 2X | \$1,920.00 | 48% | <i>\$1,005.89</i> |
| Versatile Interface Module 5 with two 40GbE (QSFP) ports supported on ExtremeSwitching X465 and VSP4900 | VIM5-2Q | \$2,693.00 | 48% | <i>\$1,410.86</i> |
| Versatile Interface Module 5 with four 10GbE (SFP+) ports supported on ExtremeSwitching X465 and VSP4900 | VIM5-4X | \$1,683.00 | 48% | <i>\$881.72</i> |
| Versatile Interface Module 5 with four 10GbE (SFP+) ports LRM MACsec capable supported on ExtremeSwitching X465 and VSP4900 | VIM5-4XE | \$2,693.00 | 48% | <i>\$1,410.86</i> |
| Versatile Interface Module 5 with four 25GbE (SFP28) ports MACsec capable supported on ExtremeSwitching X465 and VSP4900 | VIM5-4YE | \$5,384.00 | 48% | <i>\$2,820.68</i> |
| VSP 4900 Premier Feature License for 1 Chassis | VSP-PRMR-L- LIC-P | \$5,640.00 | 48% | <i>\$2,954.80</i> |
| VSP 4900 Premier Feature License with MACsec for 1 Chassis | VSP-PRMR- LE-LIC-P | \$5,640.00 | 48% | <i>\$2,954.80</i> |
| VSP 7400 Premier Feature License Includes Insight license | VSP-PRMR- LIC-P | \$8,500.00 | 48% | <i>\$4,453.15</i> |

| | | | | |
|--|-----------------------|-------------|-----|--------------------|
| VSP4900 with 12 100Mb/1/2.5/5/10Gb ports with 802.1bt Type3 PoE(60W) and 12 1G/10Gb SFP+ LRM and MACSEC capable ports includes fan modules 1 unpopulated VIM5 slot 2 unpopulated PSU slots rack mount kit | VSP4900-12MXU-12XE | \$19,515.00 | 48% | <i>\$10,223.91</i> |
| VSP4900-12MXU-12XE Bundle includes VSP4900-12MXU-12XE and one 1100W AC PSU FB (10941) | VSP4900-12MXU-12XE-B1 | \$21,171.00 | 48% | <i>\$11,091.49</i> |
| VSP4900 with 24 100/1000Mb SFP ports includes fan modules 1 unpopulated VIM5 slot 2 unpopulated PSU slots rack mount kit | VSP4900-24S | \$10,499.00 | 48% | <i>\$5,500.43</i> |
| VSP4900-24S Bundle includes VSP4900-24S and one 350W AC PSU FB (10953) | VSP4900-24S-B3 | \$11,436.00 | 48% | <i>\$5,991.32</i> |
| VSP4900 with 24 1/10Gb SFP+ LRM and MACSEC capable ports includes fan modules 1 unpopulated VIM5 slot 2 unpopulated PSU slots rack mount kit | VSP4900-24XE | \$20,187.00 | 48% | <i>\$10,575.97</i> |
| VSP4900-24XE Bundle includes VSP4900-24XE and one 350W AC PSU FB (10953) | VSP4900-24XE-B3 | \$21,171.00 | 48% | <i>\$11,091.49</i> |
| ExtremeSwitching VSP 4900 with 48 10/100/1000Mb FDX/HDX ports MACSEC capable with 802.3at PoE (30W) includes fan modules VOSS operating system 1 unpopulated VIM slot 2 unpopulated PSU slots rack mount kit | VSP4900-48P | \$13,897.00 | 48% | <i>\$7,280.64</i> |
| VSP4900-48P Bundle includes VSP4900-48P and one 1100W AC PSU FB (10941) | VSP4900-48P-B1 | \$15,474.00 | 48% | <i>\$8,106.83</i> |

| | | | | |
|--|---------------------|-------------|-----|-------------|
| VSP4900-48P Bundle includes one VSP4900-48P one 1100W AC PSU FB (10941) and one VIM5-4X | VSP4900-48P-B1-4X | \$16,300.00 | 48% | \$8,539.57 |
| VSP4900-48P Bundle includes one VSP4900-48P one 1100W AC PSU FB (10941) and one VIM5-4XE | VSP4900-48P-B1-4XE | \$17,259.00 | 48% | \$9,041.99 |
| VSP 7400 32 x 100Gbps QSFP28 ports 8-core CPU 16GB RAM 128GB SSD 4-post rack mount kit No PSU No Fans | VSP7400-32C | \$36,572.00 | 48% | \$19,160.07 |
| VSP 7400 32 x 100Gbps QSFP28 ports 8-core CPU 16GB RAM 128GB SSD Single 750W AC PSU six fans 4-post rack mount kit Front to Back Airflow | VSP7400-32C-AC-F | \$38,497.00 | 48% | \$20,168.58 |
| VSP 7400 32 x 100Gbps QSFP28 ports 8-core CPU 16GB RAM 128GB SSD Single 750W AC PSU six fans 4-post rack mount kit Back to Front Airflow | VSP7400-32C-AC-R | \$38,497.00 | 48% | \$20,168.58 |
| VSP 7400 48 x 10/25Gbps SFP28 ports 8 x 100Gbps QSFP28 ports 8-core CPU 16GB RAM 128GB SSD 4-post rack mount kit No PSU No Fans | VSP7400-48Y-8C | \$31,298.00 | 48% | \$16,397.02 |
| VSP 7400 48 x 10/25Gbps SFP28 ports 8 x 100Gbps QSFP28 ports 8-core CPU 16GB RAM 128GB SSD Single 750W AC PSU six fans 4-post rack mount kit Front to Back Airflow | VSP7400-48Y-8C-AC-F | \$32,550.00 | 48% | \$17,052.95 |
| VSP 7400 48 x 10/25Gbps SFP28 ports 8 x 100Gbps QSFP28 ports 8-core CPU 16GB RAM 128GB SSD Single 750W AC PSU six fans 4-post rack mount kit Back to Front Airflow | VSP7400-48Y-8C-AC-R | \$32,550.00 | 48% | \$17,052.95 |

| | | | | |
|---|--------------------|--------------|-----|--------------------|
| LICENSEVX-9000 - 1024X ADAPTIVE AP | VX-9000-ADP-1024 | \$119,994.00 | 48% | <i>\$62,864.86</i> |
| LICENSEVX-9000 - 16X ADAPTIVE AP | VX-9000-ADP-16 | \$1,902.00 | 48% | <i>\$996.46</i> |
| LICENSEVX-9000 - 256X ADAPTIVE AP | VX-9000-ADP-256 | \$30,414.00 | 48% | <i>\$15,933.89</i> |
| LICENSEVX-9000 - 512X ADAPTIVE AP | VX-9000-ADP-512 | \$60,822.00 | 48% | <i>\$31,864.65</i> |
| LICENSEVX-9000 - 64X ADAPTIVE AP | VX-9000-ADP-64 | \$7,602.00 | 48% | <i>\$3,982.69</i> |
| LICENSEVX-9000 APPLIANCE | VX-9000-APPLNC-LIC | \$2,394.00 | 48% | <i>\$1,254.22</i> |
| X435-24P-4S 24 port 10/100/1000BASE-T PoE+ half/full duplex 4x1/2.5G unpopulated SFP 1 AC PSU | X435-24P-4S | \$2,560.00 | 48% | <i>\$1,341.18</i> |
| X435-24T-4S 24 port 10/100/1000BASE-T half/full duplex 4x1/2.5G unpopulated SFP 1 AC PSU fanless | X435-24T-4S | \$1,406.00 | 48% | <i>\$736.60</i> |
| X435-8P-2T-W 8 port 10/100/1000BASE-T PoE+ half/full duplex 2x1000BASE-T uplinks POE powered 802.3bt type 4 fanless | X435-8P-2T-W | \$1,406.00 | 48% | <i>\$736.60</i> |
| X435-8P-4S 8 port 10/100/1000BASE-T PoE+ half/full duplex 4x1/2.5G unpopulated SFP 1 AC PSU fanless | X435-8P-4S | \$1,277.00 | 48% | <i>\$669.02</i> |
| X435-8T-4S 8 port 10/100/1000BASE-T half/full duplex 4x1G/2.5G unpopulated SFP 1 AC PSU fanless | X435-8T-4S | \$1,020.00 | 48% | <i>\$534.38</i> |
| ExtremeSwitching X465 with 24 100Mb/1/2.5/5Gb ports with 802.3bt Type3 PoE (60W) includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-24MU | \$18,134.00 | 48% | <i>\$9,500.40</i> |

| | | | | |
|--|------------------|-------------|-----|--------------------|
| ExtremeSwitching X465 with 24 100Mb/1/2.5/5Gb 802.3bt Type3 PoE (60W) capable ports and 24 10/100/1000Mb FDX/HDX MACSEC 802.3bt Type4 PoE (90W) capable ports includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-24MU-24W | \$20,959.00 | 48% | <i>\$10,980.42</i> |
| ExtremeSwitching X465-24MU-24W Bundle includes X465-24MU-24W and one 1100W AC PSU FB (10941) | X465-24MU-24W-B1 | \$22,577.00 | 48% | <i>\$11,828.09</i> |
| ExtremeSwitching X465-24MU-24W Bundle includes X465-24MU-24W and one 2000W AC PSU FB (XN-ACPWR-2000W-F) | X465-24MU-24W-B2 | \$23,994.00 | 48% | <i>\$12,570.46</i> |
| ExtremeSwitching X465-24MU Bundle includes X465-24MU and one 1100W AC PSU FB (10941) | X465-24MU-B1 | \$19,754.00 | 48% | <i>\$10,349.12</i> |
| ExtremeSwitching X465-24MU Bundle includes X465-24MU and one 2000W AC PSU FB (XN-ACPWR-2000W-F) | X465-24MU-B2 | \$21,171.00 | 48% | <i>\$11,091.49</i> |
| ExtremeSwitching X465 with 24 100/1000Mb SFP ports includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-24S | \$10,499.00 | 48% | <i>\$5,500.43</i> |
| ExtremeSwitching X465-24S Bundle includes X465-24S and one 350W AC PSU FB (10953) | X465-24S-B3 | \$11,436.00 | 48% | <i>\$5,991.32</i> |
| ExtremeSwitching X465 with 24 10/100/1000Mb FDX/HDX ports MACSEC capable with 802.3bt Type4 PoE (90W) includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-24W | \$10,561.00 | 48% | <i>\$5,532.91</i> |

| | | | | |
|--|--------------|-------------|-----|--------------------|
| ExtremeSwitching X465-24W Bundle includes X465-24W and one 1100W AC PSU FB (10941) | X465-24W-B1 | \$12,103.00 | 48% | <i>\$6,340.76</i> |
| ExtremeSwitching X465-24W Bundle includes X465-24W and one 2000W AC PSU FB (XN- ACPWR-2000W-F) | X465-24W-B2 | \$13,455.00 | 48% | <i>\$7,049.07</i> |
| ExtremeSwitching X465 with 24 100Mb/1Gb/10GBASE-X SFP+ LRM and MACSEC capable ports includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-24XE | \$20,187.00 | 48% | <i>\$10,575.97</i> |
| ExtremeSwitching X465-24XE Bundle includes X465-24XE and one 350W AC PSU FB (10953) | X465-24XE-B3 | \$21,171.00 | 48% | <i>\$11,091.49</i> |
| ExtremeSwitching X465 with 48 10/100/1000Mb FDX/HDX MACSEC capable ports with 802.3at PoE (30W) includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-48P | \$13,897.00 | 48% | <i>\$7,280.64</i> |
| ExtremeSwitching X465-48P Bundle includes X465-48P and one 1100W AC PSU FB (10941) | X465-48P-B1 | \$15,474.00 | 48% | <i>\$8,106.83</i> |
| ExtremeSwitching X465 with 48 10/100/1000Mb FDX/HDX MACSEC capable ports includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-48T | \$12,518.00 | 48% | <i>\$6,558.18</i> |
| ExtremeSwitching X465-48T Bundle includes X465-48T and one 350W AC PSU FB (10953) | X465-48T-B3 | \$13,455.00 | 48% | <i>\$7,049.07</i> |

| | | | | |
|---|-----------------|-------------|-----|--------------------|
| ExtremeSwitching X465 with 48 10/100/1000Mb FDX/HDX MACSEC capable ports 802.3bt Type4 PoE (90W) includes fan modules EXOS Advanced Edge 1 VIM5 slot 2 PSU slots rack mount kit | X465-48W | \$16,618.00 | 48% | <i>\$8,706.17</i> |
| ExtremeSwitching X465-48W Bundle includes X465-48W and one 1100W AC PSU FB (10941) | X465-48W-B1 | \$18,222.00 | 48% | <i>\$9,546.51</i> |
| ExtremeSwitching X465-48W Bundle includes X465-48W and one 2000W AC PSU FB (XN-ACPWR-2000W-F) | X465-48W-B2 | \$19,513.00 | 48% | <i>\$10,222.86</i> |
| ExtremeSwitching X465 Insight model with 48 10/100/1000Mb FDX/HDX MACSEC capable ports 802.3bt Type 4 PoE includes fans EXOS Advanced Edge 1 VIM5 SLOT 2 PSU slots rack mount kit | X465i-48W | \$18,134.00 | 48% | <i>\$9,500.40</i> |
| ExtremeSwitching X465i-48W Bundle includes X465i-48W 120GB SSD and one 1100W AC PSU FB (10941) | X465i-48W-B1-S1 | \$22,998.00 | 48% | <i>\$12,048.65</i> |
| ExtremeSwitching X465i-48W Bundle includes X465i-48W 120GB SSD and one 2000W AC PSU FB (XN-ACPWR-2000W-F) | X465i-48W-B2-S1 | \$24,383.00 | 48% | <i>\$12,774.25</i> |
| X695-48Y Switch with two empty power supply slots six empty fan slots Supports 48x25GE/10GE/1GE + 8x100GE/40GE | X695-48Y-8C | \$32,080.00 | 48% | <i>\$16,806.71</i> |
| Spare 12V/60W External Power Adapter for XA1440 and XA1480 hardware appliance | XA1400-PWR-ADPT | \$224.00 | 48% | <i>\$117.35</i> |

| | | | | |
|---|-------------------|--------------|-----|-------------|
| ExtremeAccess Platform 1440 hardware appliance with 6 10/100/1000Mbps Base-T ports and 2 1/10Gb SFP+ ports includes Fan and 1 12V external power adapter. Power Cord to be ordered separately | XA1440 | \$3,845.00 | 48% | \$2,014.40 |
| ExtremeAccess Platform 1480 hardware appliance with 6 10/100/1000Mbps Base-T ports and 2 1/10Gb SFP+ ports includes Fan and 1 12V external power adapter. Power Cord to be ordered separately | XA1480 | \$5,128.00 | 48% | \$2,686.56 |
| ExtremeCloud Business Insight SaaS Subscription and ExtremeWorks Support, 10K EndSystems per Year | XBI-S-10K-EW | \$ 50,000.00 | 6% | \$47,352.50 |
| ExtremeCloud Business Insights SaaS Subscription and ExtremeWorks Support 1K End-Systems per Year | XBI-S-1K-EW | \$ 7,500.00 | 6% | \$7,102.88 |
| SLX Fixed FAN Front to Back airflow | XBR-3250CFM-FAN-F | \$1,215.00 | 48% | \$636.54 |
| SLX Fixed AC 650W Power Supply Front to Back airflow. Power cords not included. | XBR-ACPWR-650-F | \$2,314.00 | 48% | \$1,212.30 |
| SLX Fixed AC 650W Power Supply Back to Front airflow. Power cords not included. | XBR-ACPWR-650-R | \$2,314.00 | 48% | \$1,212.30 |
| SLX Fixed DC 650W Power Supply Front to BDCh airflow. Power cords not included. | XBR-DCPWR-650-F | \$4,112.00 | 48% | \$2,154.28 |
| SLX 9140/9240/9540/9640 Fixed Rackmount kit 4-post mid/flush mount compatible | XBR-R000297 | \$1,215.00 | 48% | \$636.54 |
| ExtremeCloud Secure Tier, includes Network Access Control and RADIUS as a Service, SaaS Subscription and EW SaaS Support per device identity (IOT device), per year | XC-SIOT-S-C-EW | \$ 12.00 | 6% | \$11.36 |

| | | | | |
|--|------------------|----------|----|----------------|
| ExtremeCloud Secure Tier, includes Network Access Control and RADIUS as a Service, SaaS Subscription and PW SaaS Support per device identity (IOT device), per year | XC-SIOT-S-C-PWP | \$ 12.00 | 6% | <i>\$11.36</i> |
| ExtremeCloud Secure Plus Tier, includes Universal ZTNA, SaaS Subscription and EW SaaS Support per device identity (IOT device), per year | XC-SPIOT-S-C-EW | \$ 24.00 | 6% | <i>\$22.73</i> |
| ExtremeCloud Secure Plus Tier, includes Universal ZTNA, SaaS Subscription and PWP SaaS Support per device identity (IOT device), per year | XC-SPIOT-S-C-PWP | \$ 24.00 | 6% | <i>\$22.73</i> |
| ExtremeCloud Secure Plus Tier, includes Universal ZTNA, minimum of 50 qty required for initial order, SaaS Subscription and EW SaaS Support per user identity, per year | XC-SPUI-S-C-EW | \$ 60.00 | 6% | <i>\$56.82</i> |
| ExtremeCloud Secure Plus Tier, includes Universal ZTNA, minimum of 50 qty required for initial order, SaaS Subscription and PWP SaaS Support per user identity, per year | XC-SPUI-S-C-PWP | \$ 60.00 | 6% | <i>\$56.82</i> |
| ExtremeCloud Secure Tier, includes Network Access Control and RADIUS as a Service, minimum of 50 qty required for initial order, SaaS Subscription and EW SaaS Support per user identity, per year | XC-SUI-S-C-EW | \$ 12.00 | 6% | <i>\$11.36</i> |

| | | | | |
|--|------------------------|-------------|----|-------------------|
| ExtremeCloud Secure Tier, includes Network Access Control and RADIUS as a Service, minimum of 50 qty required for initial order, SaaS Subscription and PW SaaS Support per user identity, per year | XC-SUI-S-C-PWP | \$ 12.00 | 6% | <i>\$11.36</i> |
| ExtremeCloud IQ Pilot Cloud APs, SR, XR Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT0-C-EW-10YR-K12 | \$ 1,225.00 | 6% | <i>\$1,160.14</i> |
| ExtremeCloud IQ Pilot Tier 0 CLOUD RTU License and EW TAC 1Yr (US K-12) | XCIQ-PT0-C-EW-1YR-K12 | \$ 175.00 | 6% | <i>\$165.73</i> |
| ExtremeCloud IQ Pilot Tier 0 CLOUD RTU License and EW TAC 3Yr (US K-12) | XCIQ-PT0-C-EW-3YR-K12 | \$ 350.00 | 6% | <i>\$331.47</i> |
| ExtremeCloud IQ Pilot Tier 0 CLOUD RTU License and EW TAC 5Yr (US K-12) | XCIQ-PT0-C-EW-5YR-K12 | \$ 525.00 | 6% | <i>\$497.20</i> |
| ExtremeCloud IQ Pilot Cloud APs, SR, XR Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT0-C-EW-7YR-K12 | \$ 875.00 | 6% | <i>\$828.67</i> |
| ExtremeCloud IQ Pilot Cloud APs, SR, XR Tier 0 for 10YR Local Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT0-L-EW-10YR-K12 | \$ 1,225.00 | 6% | <i>\$1,160.14</i> |
| ExtremeCloud IQ Pilot Tier 0 LOCAL RTU License and EW TAC 1Yr (US K-12) | XCIQ-PT0-L-EW-1YR-K12 | \$ 175.00 | 6% | <i>\$165.73</i> |
| ExtremeCloud IQ Pilot Tier 0 LOCAL RTU License and EW TAC 3Yr (US K-12) | XCIQ-PT0-L-EW-3YR-K12 | \$ 350.00 | 6% | <i>\$331.47</i> |
| ExtremeCloud IQ Pilot Tier 0 LOCAL RTU License and EW TAC 5Yr (US K-12) | XCIQ-PT0-L-EW-5YR-K12 | \$ 525.00 | 6% | <i>\$497.20</i> |

| | | | | |
|--|------------------------|-------------|----|------------|
| ExtremeCloud IQ Pilot Cloud APs, SR, XR Tier 0 for 7YR Local Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT0-L-EW-7YR-K12 | \$ 875.00 | 6% | \$828.67 |
| ExtremeCloud IQ Pilot 4100 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT041-C-EW-10YK12 | \$ 5,550.00 | 6% | \$5,256.13 |
| ExtremeCloud IQ Pilot 4100 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT041-C-EW-1YK12 | \$ 600.00 | 6% | \$568.23 |
| ExtremeCloud IQ Pilot 4100 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT041-C-EW-3YK12 | \$ 1,650.00 | 6% | \$1,562.63 |
| ExtremeCloud IQ Pilot 4100 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT041-C-EW-5YK12 | \$ 2,700.00 | 6% | \$2,557.04 |
| ExtremeCloud IQ Pilot 4100 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT041-C-EW-7YK12 | \$ 3,900.00 | 6% | \$3,693.50 |
| ExtremeCloud IQ Pilot 4200 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT042-C-EW-10YK12 | \$ 2,791.00 | 6% | \$2,643.22 |
| ExtremeCloud IQ Pilot 4200 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT042-C-EW-1YK12 | \$ 324.00 | 6% | \$306.84 |
| ExtremeCloud IQ Pilot 4200 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT042-C-EW-3YK12 | \$ 822.00 | 6% | \$778.48 |
| ExtremeCloud IQ Pilot 4200 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT042-C-EW-5YK12 | \$ 1,320.00 | 6% | \$1,250.11 |

| | | | | |
|---|------------------------|-------------|----|-------------------|
| ExtremeCloud IQ Pilot 4200 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT042-C-EW-7YK12 | \$ 1,969.00 | 6% | <i>\$1,864.74</i> |
| ExtremeCloud IQ Pilot 440-G2 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT0440-C-EW-1YK12 | \$ 284.00 | 6% | <i>\$268.96</i> |
| ExtremeCloud IQ Pilot 440-G2 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT0440-C-EW-3YK12 | \$ 701.00 | 6% | <i>\$663.88</i> |
| ExtremeCloud IQ Pilot 440-G2 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT0440-C-EW-5YK12 | \$ 1,118.00 | 6% | <i>\$1,058.80</i> |
| ExtremeCloud IQ Pilot 5300 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT053-C-EW-10YK12 | \$ 2,791.00 | 6% | <i>\$2,643.22</i> |
| ExtremeCloud IQ Pilot 5300 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT053-C-EW-1YK12 | \$ 324.00 | 6% | <i>\$306.84</i> |
| ExtremeCloud IQ Pilot 5300 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT053-C-EW-3YK12 | \$ 822.00 | 6% | <i>\$778.48</i> |
| ExtremeCloud IQ Pilot 5300 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT053-C-EW-5YK12 | \$ 1,320.00 | 6% | <i>\$1,250.11</i> |
| ExtremeCloud IQ Pilot 5300 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT053-C-EW-7YK12 | \$ 1,969.00 | 6% | <i>\$1,864.74</i> |
| ExtremeCloud IQ Pilot 5400 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT054-C-EW-10YK12 | \$ 3,490.00 | 6% | <i>\$3,305.20</i> |

| | | | | |
|--|------------------------|-------------|----|------------|
| ExtremeCloud IQ Pilot 5400 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT054-C-EW-1YK12 | \$ 394.00 | 6% | \$373.14 |
| ExtremeCloud IQ Pilot 5400 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT054-C-EW-3YK12 | \$ 1,032.00 | 6% | \$977.36 |
| ExtremeCloud IQ Pilot 5400 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT054-C-EW-5YK12 | \$ 1,670.00 | 6% | \$1,581.57 |
| ExtremeCloud IQ Pilot 5400 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT054-C-EW-7YK12 | \$ 2,458.00 | 6% | \$2,327.85 |
| ExtremeCloud IQ Pilot 5500 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT055-C-EW-10YK12 | \$ 4,610.00 | 6% | \$4,365.90 |
| ExtremeCloud IQ Pilot 5500 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT055-C-EW-1YK12 | \$ 506.00 | 6% | \$479.21 |
| ExtremeCloud IQ Pilot 5500 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT055-C-EW-3YK12 | \$ 1,368.00 | 6% | \$1,295.56 |
| ExtremeCloud IQ Pilot 5500 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT055-C-EW-5YK12 | \$ 2,230.00 | 6% | \$2,111.92 |
| ExtremeCloud IQ Pilot 5500 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT055-C-EW-7YK12 | \$ 3,242.00 | 6% | \$3,070.34 |
| ExtremeCloud IQ Pilot 5700 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT057-C-EW-10YK12 | \$ 8,653.00 | 6% | \$8,194.82 |

| | | | | |
|--|------------------------|--------------|----|--------------------|
| ExtremeCloud IQ Pilot 5700 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT057-C-EW-1YK12 | \$ 910.00 | 6% | <i>\$861.82</i> |
| ExtremeCloud IQ Pilot 5700 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT057-C-EW-3YK12 | \$ 2,581.00 | 6% | <i>\$2,444.34</i> |
| ExtremeCloud IQ Pilot 5700 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT057-C-EW-5YK12 | \$ 4,251.00 | 6% | <i>\$4,025.91</i> |
| ExtremeCloud IQ Pilot 5700 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT057-C-EW-7YK12 | \$ 6,072.00 | 6% | <i>\$5,750.49</i> |
| ExtremeCloud IQ Pilot 7500 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT075-C-EW-10YK12 | \$ 14,225.00 | 6% | <i>\$13,471.79</i> |
| ExtremeCloud IQ Pilot 7500 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT075-C-EW-1YK12 | \$ 1,468.00 | 6% | <i>\$1,390.27</i> |
| ExtremeCloud IQ Pilot 7500 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT075-C-EW-3YK12 | \$ 4,253.00 | 6% | <i>\$4,027.80</i> |
| ExtremeCloud IQ Pilot 7500 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT075-C-EW-5YK12 | \$ 7,038.00 | 6% | <i>\$6,665.34</i> |
| ExtremeCloud IQ Pilot 7500 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT075-C-EW-7YK12 | \$ 9,973.00 | 6% | <i>\$9,444.93</i> |
| ExtremeCloud IQ Pilot 7700 Tier 0 for 10YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT077-C-EW-10YK12 | \$ 17,450.00 | 6% | <i>\$16,526.02</i> |

| | | | | |
|---|-----------------------|----------------|----|-----------------------|
| ExtremeCloud IQ Pilot 7700 Tier 0 for 1YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT077-C-EW-1YK12 | \$ 1,790.00 | 6% | <i>\$1,695.22</i> |
| ExtremeCloud IQ Pilot 7700 Tier 0 for 3YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT077-C-EW-3YK12 | \$ 5,220.00 | 6% | <i>\$4,943.60</i> |
| ExtremeCloud IQ Pilot 7700 Tier 0 for 5YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT077-C-EW-5YK12 | \$ 8,650.00 | 6% | <i>\$8,191.98</i> |
| ExtremeCloud IQ Pilot 7700 Tier 0 for 7YR Cloud Subscription with ExtremeWorks TAC OS (US K-12) | XCIQ-PT077-C-EW-7YK12 | \$ 12,230.00 | 6% | <i>\$11,582.42</i> |
| ExtremeCloud IQ Pilot Tier 1 CLOUD RTU License and EW TAC 1Yr (US K-12) | XCIQ-PT1-C-EW-1YR-K12 | \$ 175.00 | 6% | <i>\$165.73</i> |
| ExtremeCloud IQ Pilot Tier 1 CLOUD RTU License and EW TAC 3Yr (US K-12) | XCIQ-PT1-C-EW-3YR-K12 | \$ 350.00 | 6% | <i>\$331.47</i> |
| ExtremeCloud IQ Pilot Tier 1 CLOUD RTU License and EW TAC 5Yr (US K-12) | XCIQ-PT1-C-EW-5YR-K12 | \$ 525.00 | 6% | <i>\$497.20</i> |
| Fabric Skill per managed device | XCO-EFA-D-EW-1Y | \$ 1,250.00 | 6% | <i>\$1,183.81</i> |
| Fabric Skill per managed device | XCO-EFA-D-EWP-1Y | \$ 1,625.00 | 6% | <i>\$1,538.96</i> |
| Fabric Skill per managed device | XCO-EFA-D-PWP-1Y | \$ 1,250.00 | 6% | <i>\$1,183.81</i> |
| Fabric Skill unlimited managed devices | XCO-EFA-U-EW-1Y | \$7,291,700.00 | 6% | <i>\$6,905,604.49</i> |
| Fabric Skill unlimited managed devices | XCO-EFA-U-EWP-1Y | \$9,479,210.00 | 6% | <i>\$8,977,285.83</i> |
| Fabric Skill unlimited managed devices | XCO-EFA-U-PWP-1Y | \$7,291,700.00 | 6% | <i>\$6,905,604.49</i> |
| Visibility Skill per managed device | XCO-VIS-D-EW-1Y | \$ 900.00 | 6% | <i>\$852.35</i> |
| Visibility Skill per managed device | XCO-VIS-D-EWP-1Y | \$ 1,170.00 | 6% | <i>\$1,108.05</i> |
| Visibility Skill per managed device | XCO-VIS-D-PWP-1Y | \$ 900.00 | 6% | <i>\$852.35</i> |

| | | | | |
|--|---------------------------|--------------|-----|--------------------|
| Workspace per cluster | XCO-WS-X- EW-1Y | \$ 31,250.00 | 6% | <i>\$29,595.31</i> |
| Workspace per cluster | XCO-WS-X- EWP-1Y | \$ 40,625.00 | 6% | <i>\$38,473.91</i> |
| Workspace per cluster | XCO-WS-X- PWP-1Y | \$ 31,250.00 | 6% | <i>\$29,595.31</i> |
| SLX9540/SLX9640/VDX6940/ DX6740T MID-MOUNT RACK KIT for 2 post racks | XEN-R000294 | \$483.00 | 48% | <i>\$253.04</i> |
| SLX 9640 FAN Front to Back airflow | XEN-SLX9640- FAN-F | \$1,366.00 | 48% | <i>\$715.65</i> |
| SLX 9640 FAN Back to Front airflow | XEN-SLX9640- FAN-R | \$1,366.00 | 48% | <i>\$715.65</i> |
| Extreme Intuitive Insights for 10 IoT devices for 1 Year - ExtremeWorks | XII-IOT-S-10- EW | \$ 100.00 | 6% | <i>\$94.71</i> |
| XIQ CTL Activation Key for CloudEdge | XIQ-CACT- APP | \$ 1,495.00 | 6% | <i>\$1,415.84</i> |
| ExtremeCloud IQ Controller Activation License for Hardware Appliances | XIQ-CACT- HW | \$1.00 | 38% | <i>\$0.62</i> |
| ExtremeCloud IQ Controller Activation License for Hardware Appliances (Egypt Only) | XIQ-CACT- HW-EGY | \$1.00 | 38% | <i>\$0.62</i> |
| ExtremeCloud IQ Controller Activation License for Virtual Appliances | XIQ-CACT- VT | \$1,995.00 | 38% | <i>\$1,246.18</i> |
| ExtremeCloud IQ Controller Activation License for Virtual Appliances (Egypt Only) | XIQ-CACT- VT-EGY | \$1,995.00 | 38% | <i>\$1,246.18</i> |
| Extreme CloudOps Subscription - EW | XIQ- CLOUDOPS-S- EW | \$ 20,000.00 | 6% | <i>\$18,941.00</i> |
| ExtremeCloud IQ Co-Pilot SaaS Subscription and EW SaaS Support for one (1) device per year (Requires active XIQ Pilot SaaS Subscription) | XIQ-COPILOT- S-C-EW | \$ 99.00 | 6% | <i>\$93.76</i> |

| | | | | |
|---|------------------------|---------------|----|--------------|
| ExtremeCloud IQ Co-Pilot SaaS Subscription and PWP SaaS Support for one (1) device per year (Requires active XIQ Pilot SaaS Subscription) | XIQ-COPILOT-S-C-PWP | \$ 99.00 | 6% | \$93.76 |
| Extreme CloudOPS subscription for Edge Cloud - ExtremeWorks | XIQ-EDGEOPS-S-EW | \$ 70,000.00 | 6% | \$66,293.50 |
| ExtremeNAC SW subscription for 100,000 end-systems for 1 Year ExtremeWorks | XIQ-NAC-S-100K-EW | \$ 250,000.00 | 6% | \$236,762.50 |
| ExtremeNAC SW subscription for 100,000 end-systems for 1 Year PartnerWorks Plus | XIQ-NAC-S-100K-PWP | \$ 250,000.00 | 6% | \$236,762.50 |
| ExtremeNAC SW subscription for 10,000 end-systems for 1 Year ExtremeWorks | XIQ-NAC-S-10K-EW | \$ 32,500.00 | 6% | \$30,779.13 |
| ExtremeNAC SW subscription for 10,000 end-systems for 1 Year PartnerWorks Plus | XIQ-NAC-S-10K-PWP | \$ 32,500.00 | 6% | \$30,779.13 |
| ExtremeNAC SW subscription for 1,000 end-systems for 1 Year ExtremeWorks | XIQ-NAC-S-1K-EW | \$ 3,500.00 | 6% | \$3,314.68 |
| ExtremeNAC SW subscription for 1,000 end-systems for 1 Year PartnerWorks Plus | XIQ-NAC-S-1K-PWP | \$ 3,500.00 | 6% | \$3,314.68 |
| ExtremeCloud IQ Navigator SaaS Subscription EW SaaS Support for one (1) device (1 year) | XIQ-NAV-S-C-EW | \$ 50.00 | 6% | \$47.35 |
| ExtremeCloud IQ Navigator SaaS Subscription PWP SaaS Support for one (1) device (1 year) | XIQ-NAV-S-C-PWP | \$ 50.00 | 6% | \$47.35 |
| ExtremeCloud IQ Pilot and CoPilot Bundle SaaS Subscription and EW SaaS Support for one (1) device (1 year) | XIQ-PIL-COPILOT-S-C-EW | \$ 249.00 | 6% | \$235.82 |

| | | | | |
|--|----------------------------------|----------------------|-----|----------|
| ExtremeCloud IQ Pilot and CoPilot Bundle SaaS Subscription and PWP SaaS Support for one (1) device (1 year) | XIQ-PIL-COPII-S-C-PWP | \$ 249.00 | 6% | \$235.82 |
| ExtremeCloud IQ Pilot SaaS Subscription and EW SaaS Support for one (1) device (1 year) | XIQ-PIL-S-C-EW | \$ 150.00 | 6% | \$142.06 |
| ExtremeCloud IQ Pilot SaaS Subscription and EW SaaS Support for one (1) device (1 year), 1 year delayed term start | XIQ-PIL-S-C-EW-DELAY | \$ 150.00 | 6% | \$142.06 |
| ExtremeCloud IQ Pilot SaaS Subscription and PWP SaaS Support for one (1) device (1 year) | XIQ-PIL-S-C-PWP | \$ 150.00 | 6% | \$142.06 |
| ExtremeCloud IQ Pilot SaaS Subscription and PWP SaaS Support for one (1) device (1 year), 1 year delayed term start | XIQ-PIL-S-C-PWP-DELAY | \$ 150.00 | 6% | \$142.06 |
| XMC2XIQ NAV USK12 SaaS, EW SaaS Sup | XMC2XIQ-NAV-USK12-S-C-EW | \$ 9.00 | 6% | \$8.52 |
| XMC2XIQ NAV USK12 SaaS, PWP SaaS Sup | XMC2XIQ-NAV-USK12-S-C-PWP | \$ 9.00 | 6% | \$8.52 |
| XMC2XIQ PIL USK12 SaaS, EW SaaS Sup | XMC2XIQ-PIL-USK12-S-C-EW | \$ 25.00 | 6% | \$23.68 |
| XMC2XIQ PIL USK12 SaaS, PWP SaaS Sup | XMC2XIQ-PIL-USK12-S-C-PWP | \$ 25.00 | 6% | \$23.68 |
| 2-Post mounting ear NEBS earthquake kit for SLX9150 SLX9250 SLX 9740-40C VSP7400 X695 7520 7720 8520 8720 8820-40C | XN-2P-RKMT299 | \$279.00 | 48% | \$146.17 |
| 2-Post Rail Kit for SLX 9740-80C/8820-80C | XN-2P-RKMT300 | \$227.00 | 48% | \$118.93 |

| | | | | |
|--|-----------------|---------|-----|----------------|
| Optional two post rack mount kit for ExtremeSwitching X465 and VSP4900 models. Includes brackets for front or mid-mount of chassis in a two post rack. | XN-2P-RMKIT-001 | \$85.00 | 48% | <i>\$44.53</i> |
| Rack Mounting Kit to mount a X435 8T-4S or 8P-4S switch in 1RU space. Can also be used to mount RPS-550W and RPS-950W | XN-2P-RMKIT-002 | \$64.00 | 48% | <i>\$33.53</i> |
| Rack Mount Kit to mount single compact form factor device in 1RU space. For use with X435-8P-2T-W RPS-150W-XT | XN-2P-RMKIT-003 | \$64.00 | 48% | <i>\$33.53</i> |
| Rack Mount Kit Spare for 24 and 48 port models of 200 series X430 X435 X440-G2 | XN-2P-RMKIT-004 | \$64.00 | 48% | <i>\$33.53</i> |
| Optional two post rack mount kit 5520 | XN-2P-RMKIT-005 | \$90.00 | 48% | <i>\$47.15</i> |
| Spare two post rack mount kit for ExtremeSwitching 5320 - 24 and 48 ports switches. Includes brackets for front or mid-mount of chassis in a two post rack. | XN-2P-RMKIT-006 | \$49.00 | 48% | <i>\$25.67</i> |
| Spare two post rack mount kit for ExtremeSwitching 5320 - 16 ports switch. Includes brackets for front or mid-mount of chassis in a two post rack. | XN-2P-RMKIT-007 | \$35.00 | 48% | <i>\$18.34</i> |
| Spare two post rack mount kit for ExtremeSwitching 5420 4220 and 4120 24 48 port switches. Includes brackets for front or mid-mount of chassis in a two post rack. | XN-2P-RMKIT-008 | \$39.00 | 48% | <i>\$20.43</i> |
| Spare two post rack mount kit for ExtremeSwitching 4220 and X440-G2 12port switches. Includes brackets for front or mid-mount of chassis in a two post rack. | XN-2P-RMKIT-009 | \$45.00 | 48% | <i>\$23.58</i> |

| | | | | |
|--|----------------------|------------|-----|-------------------|
| Spare 1U height two post rack mount kit for ExtremeSwitching 5320 - 16 ports switch. Includes brackets for front or mid-mount of chassis in a two post rack. | XN-2P-RMKIT-011 | \$86.00 | 48% | <i>\$45.06</i> |
| Optional two post rack mount kit for ExtremeAccess Platform 1400 models. Includes brackets for front mount of chassis in a two post rack. | XN-2P-RMKIT-XA | \$384.00 | 48% | <i>\$201.18</i> |
| Optional Two Post Rack Mount Kit for One Compact Switch - 19 Rack - V300 | XN-2P-RMTKIT-1CS-001 | \$90.00 | 48% | <i>\$47.15</i> |
| Optional Two Post Rack Mount Kit for Two Compact Switches - side by side for a 19 Rack - V300 | XN-2P-RMTKIT-2CS-001 | \$76.00 | 48% | <i>\$39.82</i> |
| Spare four post rack mount kit for use with ExtremeSwitching X465 and VSP4900 | XN-4P-RKMT-001 | \$134.00 | 48% | <i>\$70.20</i> |
| 4-Post rack mount rail kit for SLX9150 SLX9250 VSP7400 X695 7520 7720 8520 and 8720 | XN-4P-RKMT298 | \$893.00 | 48% | <i>\$467.84</i> |
| 4-Post Rail Kit for SLX 9740-80C/8820-80C/7830 | XN-4P-RKMT301 | \$1,199.00 | 48% | <i>\$628.16</i> |
| 4-Post Rail Kit for SLX 9740-40C/8820-40C/7520-48YE/8730 | XN-4P-RKMT302 | \$1,199.00 | 48% | <i>\$628.16</i> |
| Extreme 9920 4-Post Rack Mount Kit | XN-4P-RKMT303 | \$1,481.00 | 48% | <i>\$775.90</i> |
| Optional four post rack mount kit 5520 | XN-4P-RMKIT-005 | \$182.00 | 48% | <i>\$95.35</i> |
| 1100 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-1100W-FB | \$1,695.00 | 48% | <i>\$888.01</i> |
| 1200W AC PoE PSU supported on PoE models of 5420 switches | XN-ACPWR-1200W | \$2,095.00 | 48% | <i>\$1,097.57</i> |
| 1200 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-1200W-FB | \$1,595.00 | 48% | <i>\$835.62</i> |
| 1200 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-1200W-FB-U | \$2,095.00 | 48% | <i>\$1,097.57</i> |

| | | | | |
|--|---------------------|------------|-----|-------------------|
| 150W AC PSU supported on Non-PoE 5420 switches | XN-ACPWR-150W | \$745.00 | 48% | <i>\$390.31</i> |
| 150 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-150W-FB | \$745.00 | 48% | <i>\$390.31</i> |
| 150 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-150W-FB-U | \$745.00 | 48% | <i>\$390.31</i> |
| SLX 9740 8820 Fixed AC 1600W Power Supply Front to Back. Power cords not included. | XN-ACPWR-1600W-F | \$3,017.00 | 48% | <i>\$1,580.61</i> |
| SLX 9740 8820 Fixed AC 1600W Power Supply Back to Front. Power cords not included. | XN-ACPWR-1600W-R | \$3,017.00 | 48% | <i>\$1,580.61</i> |
| 2000W AC PoE PSU supported on PoE models of 5420 switches | XN-ACPWR-2000W | \$3,244.00 | 48% | <i>\$1,699.53</i> |
| Modular Power Supply 2000W AC Front to BackSupported on X465 VSP4900 5520 | XN-ACPWR-2000W-F | \$2,962.00 | 48% | <i>\$1,551.79</i> |
| 2000 Watt AC PoE Power Supply Module - Front to Back airflow. Supported on ExtremeSwitching 5520 5720 X465 and VSP4900 | XN-ACPWR-2000W-FB | \$2,595.00 | 48% | <i>\$1,359.52</i> |
| 2000 Watt AC PoE Power Supply Module - Front to Back airflow. Supported on ExtremeSwitching 5420 | XN-ACPWR-2000W-FB-A | \$2,495.00 | 48% | <i>\$1,307.13</i> |
| 2000 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-2000W-FB-U | \$3,244.00 | 48% | <i>\$1,699.53</i> |
| V300-8P-2X 280W AC Power Supply - Field Replaceable Unit | XN-ACPWR-280W | \$641.00 | 48% | <i>\$335.82</i> |
| V300HT-8P-2X 320W AC Power Supply High Temperature | XN-ACPWR-320W-HT | \$893.00 | 48% | <i>\$467.84</i> |
| 350 Watt AC Power Supply Module - Back to Front airflow | XN-ACPWR-350W-BF | \$995.00 | 48% | <i>\$521.28</i> |
| 350 Watt AC Power Supply Module - Front to Back airflow for Summit X465 VSP4900 5520 | XN-ACPWR-350W-FB | \$995.00 | 48% | <i>\$521.28</i> |
| V300-8T-2X 40W AC Power Supply - Field Replaceable Unit | XN-ACPWR-40W | \$180.00 | 48% | <i>\$94.30</i> |
| V300HT-8T-2X 40W AC Power Supply High Temperature | XN-ACPWR-40W-HT | \$250.00 | 48% | <i>\$130.98</i> |

| | | | | |
|---|---------------------|------------|-----|------------|
| 550 Watt AC Power Supply Module - Back to Front airflow | XN-ACPWR-550W-BF | \$1,495.00 | 48% | \$783.23 |
| 550 Watt AC Power Supply Module - Front to Back airflow | XN-ACPWR-550W-FB | \$1,495.00 | 48% | \$783.23 |
| 600W AC PoE PSU supported on PoE models of 5420 switches | XN-ACPWR-600W | \$1,198.00 | 48% | \$627.63 |
| 600 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-600W-FB | \$1,198.00 | 48% | \$627.63 |
| 600 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-600W-FB-U | \$1,198.00 | 48% | \$627.63 |
| V300HT-8T-2X 60W AC Power Supply High Temperature for DIN Rail Mounting | XN-ACPWR-60W-HT-DIN | \$340.00 | 48% | \$178.13 |
| 715 Watt AC PoE Power Supply Module - Front to Back airflow for Summit X465 VSP4900 5520 5720 | XN-ACPWR-715W-FB | \$1,345.00 | 48% | \$704.65 |
| 750W AC PSU Front to Back Airflow for VSP7400 SLX9150 SLX9250 X695 8520 and 8720 | XN-ACPWR-750W-F | \$1,873.00 | 48% | \$981.26 |
| 750W AC PSU Back to Front Airflow for VSP7400 SLX9150 SLX9250 X695 8520 and 8720 | XN-ACPWR-750W-R | \$1,873.00 | 48% | \$981.26 |
| AC 800W PSU Front to Back Airflow for use in 7520 7720 | XN-ACPWR-800W-F | \$1,999.00 | 48% | \$1,047.28 |
| AC 800W PSU Back to Front Airflow for use in 7520 7720 | XN-ACPWR-800W-R | \$1,999.00 | 48% | \$1,047.28 |
| 920W AC PoE PSU supported on PoE models of 5420 switches | XN-ACPWR-920W | \$1,595.00 | 48% | \$835.62 |
| 920 Watt AC PoE Power Supply Module - Front to Back airflow | XN-ACPWR-920W-FB-U | \$1,595.00 | 48% | \$835.62 |
| SLX 9740 8820 Fixed DC 1600W Power Supply Front to Back. Power cords not included. | XN-DCPWR-1600W-F | \$6,568.00 | 48% | \$3,440.98 |
| SLX 9740 8820 Fixed DC 1600W Power Supply Back to Front. Power cords not included. | XN-DCPWR-1600W-R | \$6,568.00 | 48% | \$3,440.98 |
| 550 Watt DC Power Supply Module - Back to Front airflow | XN-DCPWR-550W-BF | \$2,495.00 | 48% | \$1,307.13 |
| 550 Watt DC Power Supply Module - Front to Back airflow | XN-DCPWR-550W-FB | \$2,495.00 | 48% | \$1,307.13 |

| | | | | |
|--|-------------------|------------|-----|-------------------|
| 750W DC PSU Front to Back Airflow for VSP7400 SLX9150 SLX9250 X695 8520 and 8720 | XN-DCPWR-750W-F | \$2,999.00 | 48% | <i>\$1,571.18</i> |
| 750W DC PSU Back to Front Airflow for VSP7400 SLX9150 SLX9250 X695 8520 and 8720 | XN-DCPWR-750W-R | \$2,999.00 | 48% | <i>\$1,571.18</i> |
| DC 800W PSU Front to Back Airflow for use in 7520 7720 | XN-DCPWR-800W-F | \$2,999.00 | 48% | <i>\$1,571.18</i> |
| DC 800W PSU Back to Front Airflow for use in 7520 7720 | XN-DCPWR-800W-R | \$2,999.00 | 48% | <i>\$1,571.18</i> |
| Optional DIN Rail Mounting Bracket for V300 | XN-DIN-MT-001 | \$39.00 | 48% | <i>\$20.43</i> |
| Spare Fan Module for 5420M switches | XN-FAN-000 | \$166.00 | 48% | <i>\$86.97</i> |
| Single Fan module Front to Back Airflow for VSP7400 SLX9150 SLX9250 X695 7520 7720 8520 and 8720 | XN-FAN-001-F | \$289.00 | 48% | <i>\$151.41</i> |
| Single Fan module Back to Front Airflow for VSP7400 SLX9150 SLX9250 X695 7520 7720 8520 and 8720 | XN-FAN-001-R | \$289.00 | 48% | <i>\$151.41</i> |
| Spare fan module front to back airflow supported on ExtremeSwitching X465 and VSP4900 | XN-FAN-002-F | \$319.00 | 48% | <i>\$167.12</i> |
| FAN Front to Back airflow for SLX9740-40C 8820-40C | XN-FAN-003-F | \$382.00 | 48% | <i>\$200.13</i> |
| FAN Back to Front airflow for SLX9740-40C 8820-40C | XN-FAN-003-R | \$382.00 | 48% | <i>\$200.13</i> |
| FAN Front to Back airflow for SLX9740-80C 8820-80C | XN-FAN-004-F | \$642.00 | 48% | <i>\$336.34</i> |
| FAN Back to Front airflow for SLX9740-80C 8820-80C | XN-FAN-004-R | \$642.00 | 48% | <i>\$336.34</i> |
| Spare Fan Module for 5720 switches Front to Back airflow | XN-FAN-005-F | \$165.00 | 48% | <i>\$86.44</i> |
| Micro-USB 2.0 to USB 2.0 Type A male console cable | XN-MICRO-USB-USBA | \$12.00 | 10% | <i>\$10.88</i> |
| Extreme Mini-USB to RJ45 console cable for VDX/SLX | XN-MiniUSB-RJ45 | \$128.00 | 48% | <i>\$67.06</i> |
| Optional Field Replacement Unit - Mounting Bracket Kit for V300 - Horizontal or Vertical Surface | XN-MTKIT-CS-001 | \$39.00 | 48% | <i>\$20.43</i> |

| | | | | |
|--|--------------------------|------------|-----|------------|
| V300 Protective Cover | XN-PRTC-CVR-V300 | \$52.00 | 48% | \$27.24 |
| Protective Cover for V300 16 Pack | XN-PRTC-CVR-V300-16PK | \$822.00 | 48% | \$430.65 |
| V300 PS Mounting Kit for Non-DIN PSs. Supports V300 320W-HT 280W 40W-HT 40W Power Supplys | XN-PS-MT-001 | \$39.00 | 48% | \$20.43 |
| RJ45 to DB9 console cable 6ft | XN-RJ45-DB9-CONSOLE-CBL | \$25.00 | 10% | \$22.67 |
| RJ45 to USB 2.0 Type A male console cable 6ft | XN-RJ45-USBA-CONSOLE-CBL | \$58.00 | 10% | \$52.59 |
| RJ45 to USB-C console cable 6ft | XN-RJ45-USBC-CONSOLE-CBL | \$58.00 | 10% | \$52.59 |
| Modular SSD 120GB supported on ExtremeSwitching X465 and VSP4900 | XN-SSD-001-120 | \$1,830.00 | 48% | \$958.74 |
| Modular SSD 120GB supported on ExtremeSwitching 5720 | XN-SSD-002-120 | \$917.00 | 48% | \$480.42 |
| Bluetooth 5.0 USB adapter | XN-USB-BT500-ADAPTER | \$112.00 | 48% | \$58.68 |
| XR600 Branch Router 6x GE Ethernet Ports 2x USB Console Port with included power supply (power cord sold separately) | XR600 | \$1,064.00 | 48% | \$557.43 |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps Appl ipe-40axV2 Deploy Special Purchase | XSW-BR-M-A-D-NR | \$2,701.00 | 48% | \$1,415.05 |

| | | | | |
|---|-------------------------------|-------------|----|-------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) High- Availability Included - NBD AHR ExtremeWorks 1 Year | XSW-BR-M- HA-S-EW | \$ 1,980.00 | 6% | <i>\$1,875.16</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) High- Availability Included - NBD AHR ExtremeWorks 3 Year | XSW-BR-M- HA-S-EW-3Y | \$ 5,940.00 | 6% | <i>\$5,625.48</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) High- Availability Included - NBD AHR ExtremeWorks 5 Year | XSW-BR-M- HA-S-EW-5Y | \$ 9,900.00 | 6% | <i>\$9,375.80</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) High- Availability - NBD AHR ExtremeWorks (Renewal Only) | XSW-BR-M- HA-S-EW-R | \$ 1,980.00 | 6% | <i>\$1,875.16</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch 750Mbps (for version 23.2 and above only 250Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 3 Year | XSW-BR-M- HA-S-EW-R- 3Y | \$ 5,940.00 | 6% | <i>\$5,625.48</i> |

| | | | | |
|---|-------------------------------|--------------|----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch 750Mbps (for version 23.2 and above only 250Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 5 Year | XSW-BR-M- HA-S-EW-R- 5Y | \$ 9,900.00 | 6% | <i>\$9,375.80</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) - NBD AHR ExtremeWorks 1 Year | XSW-BR-M-S- EW | \$ 3,190.00 | 6% | <i>\$3,021.09</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) - NBD AHR ExtremeWorks 3 Year | XSW-BR-M-S- EW-3Y | \$ 9,570.00 | 6% | <i>\$9,063.27</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) - NBD AHR ExtremeWorks 5 Year | XSW-BR-M-S- EW-5Y | \$ 15,950.00 | 6% | <i>\$15,105.45</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch up to 750Mbps (for version 23.2 and above only, 250Mbps for prior versions) - NBD AHR ExtremeWorks (Renewal Only) | XSW-BR-M-S- EW-R | \$ 3,190.00 | 6% | <i>\$3,021.09</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch 750Mbps (for version 23.2 and above only 250Mbps for prior versions) - ExtremeWorks (Renewal Only) 3 Year | XSW-BR-M-S- EW-R-3Y | \$ 9,570.00 | 6% | <i>\$9,063.27</i> |

| | | | | |
|---|-------------------------|--------------|-----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Medium Branch 750Mbps (for version 23.2 and above only 250Mbps for prior versions) - ExtremeWorks (Renewal Only) 5 Year | XSW-BR-M-S- EW-R-5Y | \$ 15,950.00 | 6% | <i>\$15,105.45</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps Appl ipe-30ax Deploy Special Purchase | XSW-BR-S-A- D-NR | \$1,220.00 | 48% | <i>\$639.16</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) High-Availability HW Included- NBD AHR ExtremeWorks 1 Year | XSW-BR-S- HA-S-EW | \$ 1,131.00 | 6% | <i>\$1,071.11</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) High-Availability HW Included- NBD AHR ExtremeWorks 3 Year | XSW-BR-S- HA-S-EW-3Y | \$ 3,393.00 | 6% | <i>\$3,213.34</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) High-Availability HW Included- NBD AHR ExtremeWorks 5 Year | XSW-BR-S- HA-S-EW-5Y | \$ 5,655.00 | 6% | <i>\$5,355.57</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) High-Availability - NBD AHR ExtremeWorks (Renewal Only) | XSW-BR-S- HA-S-EW-R | \$ 1,131.00 | 6% | <i>\$1,071.11</i> |

| | | | | |
|--|-------------------------------|-------------|----|-------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch 500Mbps (for version 23.2 and above only 100Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 3 Year | XSW-BR-S- HA-S-EW-R- 3Y | \$ 3,393.00 | 6% | <i>\$3,213.34</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch 500Mbps (for version 23.2 and above only 100Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 5 Year | XSW-BR-S- HA-S-EW-R- 5Y | \$ 5,655.00 | 6% | <i>\$5,355.57</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) - NBD AHR ExtremeWorks 1 Year | XSW-BR-S-S- EW | \$ 1,823.00 | 6% | <i>\$1,726.47</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) - NBD AHR ExtremeWorks 3 Year | XSW-BR-S-S- EW-3Y | \$ 5,469.00 | 6% | <i>\$5,179.42</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) - NBD AHR ExtremeWorks 5 Year | XSW-BR-S-S- EW-5Y | \$ 9,115.00 | 6% | <i>\$8,632.36</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch up to 500Mbps (for version 23.2 and above only, 100Mbps for prior versions) - NBD AHR ExtremeWorks (Renewal Only) | XSW-BR-S-S- EW-R | \$ 1,823.00 | 6% | <i>\$1,726.47</i> |

| | | | | |
|---|--------------------------|-------------|-----|------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch 500Mbps (for version 23.2 and above only 100Mbps for prior versions) - ExtremeWorks (Renewal Only) 3 Year | XSW-BR-S-S- EW-R-3Y | \$ 5,469.00 | 6% | \$5,179.42 |
| ExtremeCloud SD-WAN Enterprise XaaS for Small Branch 500Mbps (for version 23.2 and above only 100Mbps for prior versions) - ExtremeWorks (Renewal Only) 5 Year | XSW-BR-S-S- EW-R-5Y | \$ 9,115.00 | 6% | \$8,632.36 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps Appl ipe- 30so Deploy Special Purchase | XSW-BR-XS- A-D-NR | \$975.00 | 48% | \$510.80 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) High- Availability - NBD AHR ExtremeWorks 1 Year | XSW-BR-XS- HA-S-EW | \$ 916.00 | 6% | \$867.50 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) High- Availability - NBD AHR ExtremeWorks 3 Year | XSW-BR-XS- HA-S-EW-3Y | \$ 2,748.00 | 6% | \$2,602.49 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) High- Availability - NBD AHR ExtremeWorks 5 Year | XSW-BR-XS- HA-S-EW-5Y | \$ 4,580.00 | 6% | \$4,337.49 |

| | | | | |
|---|--------------------------------|-------------|----|------------|
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) High- Availability - NBD AHR ExtremeWorks (Renewal Only) | XSW-BR-XS- HA-S-EW-R | \$ 916.00 | 6% | \$867.50 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch 250Mbps (for version 23.2 and above only 50Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 3 Year | XSW-BR-XS- HA-S-EW-R- 3Y | \$ 2,748.00 | 6% | \$2,602.49 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch 250Mbps (for version 23.2 and above only 50Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 5 Year | XSW-BR-XS- HA-S-EW-R- 5Y | \$ 4,580.00 | 6% | \$4,337.49 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) - NBD AHR ExtremeWorks 1 Year | XSW-BR-XS- S-EW | \$ 1,476.00 | 6% | \$1,397.85 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) - NBD AHR ExtremeWorks 3 Year | XSW-BR-XS- S-EW-3Y | \$ 4,428.00 | 6% | \$4,193.54 |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) - NBD AHR ExtremeWorks 5 Year | XSW-BR-XS- S-EW-5Y | \$ 7,380.00 | 6% | \$6,989.23 |

| | | | | |
|---|--------------------------------|--------------|----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch up to 250Mbps (for version 23.2 and above only, 50Mbps for prior versions) - NBD AHR ExtremeWorks (Renewal Only) | XSW-BR-XS- S-EW-R | \$ 1,476.00 | 6% | <i>\$1,397.85</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch 250Mbps (for version 23.2 and above only 50Mbps for prior versions) - ExtremeWorks (Renewal Only) 3 Year | XSW-BR-XS- S-EW-R-3Y | \$ 4,428.00 | 6% | <i>\$4,193.54</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for XSmall Branch 250Mbps (for version 23.2 and above only 50Mbps for prior versions) - ExtremeWorks (Renewal Only) 5 Year | XSW-BR-XS- S-EW-R-5Y | \$ 7,380.00 | 6% | <i>\$6,989.23</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 1 Year | XSW-DC-LR- HA-L-S-EW | \$ 11,312.00 | 6% | <i>\$10,713.03</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 3 Year | XSW-DC-LR- HA-L-S-EW- 3Y | \$ 33,936.00 | 6% | <i>\$32,139.09</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 5 Year | XSW-DC-LR- HA-L-S-EW- 5Y | \$ 56,560.00 | 6% | <i>\$53,565.15</i> |

| | | | | |
|---|----------------------------------|--------------|----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-LR- HA-L-S-EW-R | \$ 11,312.00 | 6% | <i>\$10,713.03</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-LR- HA-L-S-EW-R- 3Y | \$ 33,936.00 | 6% | <i>\$32,139.09</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-LR- HA-L-S-EW-R- 5Y | \$ 56,560.00 | 6% | <i>\$53,565.15</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks 1 Year | XSW-DC-LR- L-S-EW | \$ 13,669.00 | 6% | <i>\$12,945.23</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks 3 Year | XSW-DC-LR- L-S-EW-3Y | \$ 41,007.00 | 6% | <i>\$38,835.68</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks 5 Year | XSW-DC-LR- L-S-EW-5Y | \$ 68,345.00 | 6% | <i>\$64,726.13</i> |

| | | | | |
|---|---------------------------|--------------|----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-LR- L-S-EW-R | \$ 13,669.00 | 6% | <i>\$12,945.23</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-LR- L-S-EW-R-3Y | \$ 41,007.00 | 6% | <i>\$38,835.68</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC LR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-LR- L-S-EW-R-5Y | \$ 68,345.00 | 6% | <i>\$64,726.13</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 1 Year | XSW-DC-M- HA-S-EW | \$ 9,804.00 | 6% | <i>\$9,284.88</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 3 Year | XSW-DC-M- HA-S-EW-3Y | \$ 29,412.00 | 6% | <i>\$27,854.63</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 5 Year | XSW-DC-M- HA-S-EW-5Y | \$ 49,020.00 | 6% | <i>\$46,424.39</i> |

| | | | | |
|---|-------------------------------|--------------|----|-------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-M- HA-S-EW-R | \$ 9,804.00 | 6% | \$9,284.88 |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC 2Gbps (for version 23.2 and above only 1Gbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-M- HA-S-EW-R- 3Y | \$ 29,412.00 | 6% | \$27,854.63 |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC 2Gbps (for version 23.2 and above only 1Gbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-M- HA-S-EW-R- 5Y | \$ 49,020.00 | 6% | \$46,424.39 |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) - NBD AHR ExtremeWorks 1 Year | XSW-DC-M-S- EW | \$ 11,846.00 | 6% | \$11,218.75 |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) - NBD AHR ExtremeWorks 3 Year | XSW-DC-M-S- EW-3Y | \$ 35,538.00 | 6% | \$33,656.26 |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) - NBD AHR ExtremeWorks 5 Year | XSW-DC-M-S- EW-5Y | \$ 59,230.00 | 6% | \$56,093.77 |

| | | | | |
|--|-------------------------|--------------|-----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC up to 2Gbps (for version 23.2 and above only, 1Gbps for prior versions) - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-M-S- EW-R | \$ 11,846.00 | 6% | <i>\$11,218.75</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC 2Gbps (for version 23.2 and above only 1Gbps for prior versions) - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-M-S- EW-R-3Y | \$ 35,538.00 | 6% | <i>\$33,656.26</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC 2Gbps (for version 23.2 and above only 1Gbps for prior versions) - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-M-S- EW-R-5Y | \$ 59,230.00 | 6% | <i>\$56,093.77</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps Appli e-420ax Deploy Special Purchase | XSW-DC-S-A- D-NR | \$6,192.00 | 48% | <i>\$3,243.99</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) High-Availability - NBD AHR ExtremeWorks 1 Year | XSW-DC-S- HA-S-EW | \$ 4,242.00 | 6% | <i>\$4,017.39</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) High-Availability - NBD AHR ExtremeWorks 3 Year | XSW-DC-S- HA-S-EW-3Y | \$ 12,726.00 | 6% | <i>\$12,052.16</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) High-Availability - NBD AHR ExtremeWorks 5 Year | XSW-DC-S- HA-S-EW-5Y | \$ 21,210.00 | 6% | <i>\$20,086.93</i> |

| | | | | |
|---|-----------------------|--------------|----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) High-Availability - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-S-HA-S-EW-R | \$ 4,242.00 | 6% | <i>\$4,017.39</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC 1Gbps (for version 23.2 and above only 500Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-S-HA-S-EW-R-3Y | \$ 12,726.00 | 6% | <i>\$12,052.16</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC 1Gbps (for version 23.2 and above only 500Mbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-S-HA-S-EW-R-5Y | \$ 21,210.00 | 6% | <i>\$20,086.93</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) - NBD AHR ExtremeWorks 1 Year | XSW-DC-S-S-EW | \$ 5,468.00 | 6% | <i>\$5,178.47</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) - NBD AHR ExtremeWorks 3 Year | XSW-DC-S-S-EW-3Y | \$ 16,404.00 | 6% | <i>\$15,535.41</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) - NBD AHR ExtremeWorks 5 Year | XSW-DC-S-S-EW-5Y | \$ 27,340.00 | 6% | <i>\$25,892.35</i> |

| | | | | |
|---|--------------------------------|--------------|----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC up to 1Gbps (for version 23.2 and above only, 500Mbps for prior versions) - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-S-S- EW-R | \$ 5,468.00 | 6% | <i>\$5,178.47</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC 1Gbps (for version 23.2 and above only 500Mbps for prior versions) - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-S-S- EW-R-3Y | \$ 16,404.00 | 6% | <i>\$15,535.41</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Small DC 1Gbps (for version 23.2 and above only 500Mbps for prior versions) - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-S-S- EW-R-5Y | \$ 27,340.00 | 6% | <i>\$25,892.35</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 1 Year | XSW-DC-SR- HA-L-S-EW | \$ 11,312.00 | 6% | <i>\$10,713.03</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 3 Year | XSW-DC-SR- HA-L-S-EW- 3Y | \$ 33,936.00 | 6% | <i>\$32,139.09</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks 5 Year | XSW-DC-SR- HA-L-S-EW- 5Y | \$ 56,560.00 | 6% | <i>\$53,565.15</i> |

| | | | | |
|---|----------------------------------|--------------|----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) High-Availability - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-SR- HA-L-S-EW-R | \$ 11,312.00 | 6% | <i>\$10,713.03</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-SR- HA-L-S-EW-R- 3Y | \$ 33,936.00 | 6% | <i>\$32,139.09</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) High-Availability - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-SR- HA-L-S-EW-R- 5Y | \$ 56,560.00 | 6% | <i>\$53,565.15</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks 1 Year | XSW-DC-SR- L-S-EW | \$ 13,669.00 | 6% | <i>\$12,945.23</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks 3 Year | XSW-DC-SR- L-S-EW-3Y | \$ 41,007.00 | 6% | <i>\$38,835.68</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks 5 Year | XSW-DC-SR- L-S-EW-5Y | \$ 68,345.00 | 6% | <i>\$64,726.13</i> |

| | | | | |
|--|---------------------------|--------------|-----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE up to 10Gbps (for version 23.2 and above only, 2Gbps for prior versions) - NBD AHR ExtremeWorks (Renewal Only) | XSW-DC-SR- L-S-EW-R | \$ 13,669.00 | 6% | <i>\$12,945.23</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) - ExtremeWorks (Renewal Only) 3 Year | XSW-DC-SR- L-S-EW-R-3Y | \$ 41,007.00 | 6% | <i>\$38,835.68</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC SR 10GE 10Gbps (for version 23.2 and above only 2Gbps for prior versions) - ExtremeWorks (Renewal Only) 5 Year | XSW-DC-SR- L-S-EW-R-5Y | \$ 68,345.00 | 6% | <i>\$64,726.13</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC V2 up to 10Gbps LR Appl IPE- 2200AX-F Deploy Special Purchase | XSW-DCV2- LR-L-A-D-NR | \$25,690.00 | 48% | <i>\$13,458.99</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Medium DC V2 up to 2Gbps Appl IPE- 2200AX-T Deploy Special Purchase | XSW-DCV2- M-A-D-NR | \$18,839.00 | 48% | <i>\$9,869.75</i> |
| ExtremeCloud SD-WAN Enterprise XaaS for Large DC V2 up to 10Gbps SR Appl IPE- 2200AX-F Deploy Special Purchase | XSW-DCV2- SR-L-A-D-NR | \$25,690.00 | 48% | <i>\$13,458.99</i> |
| MSP ExtremeCloud SDWAN Medium Branch up to 750Mbps Appl ipe-40axV2 | XSW-MSP-BR- M-A | \$2,701.00 | 48% | <i>\$1,415.05</i> |
| MSP ExtremeCloud SDWAN Small Branch up to 500Mbps Appl ipe-30ax | XSW-MSP-BR- S-A | \$1,220.00 | 48% | <i>\$639.16</i> |
| MSP ExtremeCloud SDWAN XSmall Branch up to 250Mbps Appl ipe-30so | XSW-MSP-BR- XS-A | \$975.00 | 48% | <i>\$510.80</i> |

| | | | | |
|---|---------------------|--------------|-----|-------------|
| MSP ExtremeCloud SDWAN Small DC up to 1Gbps Appl ipe-420ax | XSW-MSP-DC-S-A | \$6,192.00 | 48% | \$3,243.99 |
| MSP ExtremeCloud SDWAN Large DC V2 up to 10Gbps LR Appl IPE-2200AX-F | XSW-MSP-DCV2-LR-L-A | \$25,690.00 | 48% | \$13,458.99 |
| MSP ExtremeCloud SDWAN Medium DC V2 up to 2Gbps Appl IPE-2200AX-T | XSW-MSP-DCV2-M-A | \$18,839.00 | 48% | \$9,869.75 |
| MSP ExtremeCloud SDWAN Large DC V2 up to 10Gbps SR Appl IPE-2200AX-F | XSW-MSP-DCV2-SR-L-A | \$25,690.00 | 48% | \$13,458.99 |
| ExtremeCloud SD-WAN Enterprise XaaS V+C, 5 Destinations, Additive, Per Domain ExtremeWorks 1 Year | XSW-RVC-S-EW | \$ 3,078.00 | 6% | \$2,915.02 |
| ExtremeCloud SD-WAN Enterprise XaaS V+C, 5 Destinations, Additive, Per Domain ExtremeWorks 1 Year | XSW-RVC-S-EW | \$ 3,078.00 | 6% | \$2,915.02 |
| ExtremeCloud SD-WAN Enterprise XaaS V+C, 5 Destinations, Additive, Per Domain 3 Year | XSW-RVC-S-EW-3Y | \$ 9,234.00 | 6% | \$8,745.06 |
| ExtremeCloud SD-WAN Enterprise XaaS V+C, 5 Destinations, Additive, Per Domain 3 Year | XSW-RVC-S-EW-3Y | \$ 9,234.00 | 6% | \$8,745.06 |
| ExtremeCloud SD-WAN Enterprise XaaS V+C, 5 Destinations, Additive, Per Domain 5 Year | XSW-RVC-S-EW-5Y | \$ 15,390.00 | 6% | \$14,575.10 |
| ExtremeCloud SD-WAN Enterprise XaaS V+C, 5 Destinations, Additive, Per Domain 5 Year | XSW-RVC-S-EW-5Y | \$ 15,390.00 | 6% | \$14,575.10 |
| ExtremeCloud SD-WAN Enterprise XaaS EdgeSentry, Per 10 Users, Additive, Per Domain (requires min 50 users per Domain) ExtremeWorks 1 Year | XSW-SENT-S-EW | \$ 3,078.00 | 6% | \$2,915.02 |

| | | | | |
|---|----------------------|--------------|-----|--------------------|
| ExtremeCloud SD-WAN Enterprise XaaS EdgeSentry, Per 10 Users, Additive, Per Domain (requires min 50 users per Domain) ExtremeWorks 3 Year | XSW-SENT-S- EW-3Y | \$ 9,234.00 | 6% | <i>\$8,745.06</i> |
| ExtremeCloud SD-WAN Enterprise XaaS EdgeSentry, Per 10 Users, Additive, Per Domain (requires min 50 users per Domain) ExtremeWorks 5 Year | XSW-SENT-S- EW-5Y | \$ 15,390.00 | 6% | <i>\$14,575.10</i> |
| Extreme Visibility Manager Perpetual License for One Device | XVM-LIC-1 | \$2,982.00 | 48% | <i>\$1,562.27</i> |